

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	B	1	Fuel Pump Room to the North	No	W1	CMU	N/A	None	0	N/A	N/A	
1410	1	B	1	Fuel Pump Room to the North	No	W2	CMU	N/A	None	0	N/A	N/A	
1410	1	B	1	Fuel Pump Room to the North	No	W3	Concrete	White	Flaking	240	0.5	Negative	
1410	1	B	1	Fuel Pump Room to the North	No	W4	Concrete	White	None	0	N/A	N/A	
1410	1	B	1	Fuel Pump Room to the North	No	Ceiling	Concrete	White	Flaking	250	0.4	Negative	
1410	1	B	1	Fuel Pump Room to the North	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	W2	Concrete	Grey	None	0	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	W3	Concrete	Grey	None	0	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	W4	Concrete	Grey	None	0	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	2	Storage area next to Fuel Pump Room to the South	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	3	Mechanical Room in front of Elevator	No	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	B	3	Mechanical Room in front of Elevator	No	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	B	3	Mechanical Room in front of Elevator	No	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	B	3	Mechanical Room in front of Elevator	No	Duct	Metal	White	Flaking	10	0	Negative	
1410	1	B	3	Mechanical Room in front of Elevator	No	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	B	3	Mechanical Room in front of Elevator	No	Ceiling	Concrete	White	Flaking	250	0.3	Negative	
1410	1	B	3	Mechanical Room in front of Elevator	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	4	Boiler Room	No	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	B	4	Boiler Room	No	Pipe	Metal	Red	Flaking	12	0.3	Negative	
1410	1	B	4	Boiler Room	No	Pipe	Metal	Grey	Flaking	80	0.4	Negative	
1410	1	B	4	Boiler Room	No	Conduit	Metal	White	Flaking	150	0	Negative	
1410	1	B	4	Boiler Room	No	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	B	4	Boiler Room	No	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	B	4	Boiler Room	No	Pipe	Metal	White	Flaking	70	0.2	Negative	
1410	1	B	4	Boiler Room	No	W4	Concrete	Grey	Flaking	280	0.1	Negative	
1410	1	B	4	Boiler Room	No	Duct	Metal	Grey	Flaking	260	0.3	Negative	
1410	1	B	4	Boiler Room	No	Ceiling	Concrete	White	Flaking	300	0.2	Negative	
1410	1	B	4	Boiler Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	W3	Concrete	Grey	None	0	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	5	High Voltage Room Entrance	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	7	High Voltage Room	No	W1	Concrete	N/A	None	0	N/A	N/A	
1410	1	B	7	High Voltage Room	No	Doorframe	Metal	Red	Flaking	16	0.2	Negative	
1410	1	B	7	High Voltage Room	No	Door	Metal	Red	Flaking	24	0	Negative	
1410	1	B	7	High Voltage Room	No	W2	Concrete	N/A	None	0	N/A	N/A	
1410	1	B	7	High Voltage Room	No	W3	Concrete	N/A	None	0	N/A	N/A	
1410	1	B	7	High Voltage Room	No	W4	Concrete	N/A	None	0	N/A	N/A	
1410	1	B	7	High Voltage Room	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	7	High Voltage Room	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	100	Classroom 100	Yes	W1	CMU	Grey	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report						
				Inspection Company: BATT		James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	1	100	Classroom 100	Yes	Door Frame	Metal	Blue	Chipping	8	0.4	Negative
1410	1	1	100	Classroom 100	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	1	100	Classroom 100	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	1	100	Classroom 100	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	1	100	Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	100	Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	Door Frame	Metal	Grey	Chipping	10	0.5	Negative
1410	1	1	102	Classroom 102 Kindergarten	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	Door Frame	Metal	Grey	Chipping	3	0.6	Negative
1410	1	1	102	Classroom 102 Kindergarten	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	102	Classroom 102 Kindergarten	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	103	IMC (Library)	Yes	W1	CMU	Blue	Chipping	6	0.4	Negative
1410	1	1	103	IMC (Library)	Yes	Door Frame	Metal	Blue	Chipping	20	0.5	Negative
1410	1	1	103	IMC (Library)	Yes	W2	CMU	Blue	Chipping	8	0.2	Negative
1410	1	1	103	IMC (Library)	Yes	W3	CMU	Blue	Flaking	3	0.6	Negative
1410	1	1	103	IMC (Library)	Yes	Door Frame	Metal	Blue	Chipping	5	0.1	Negative
1410	1	1	103	IMC (Library)	Yes	W4	CMU	Blue	Chipping	5	0.4	Negative
1410	1	1	103	IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	103	IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	Door Frame	Metal	Grey	Chipping	10	0.5	Negative
1410	1	1	104	Classroom 104 Kindergarten	Yes	Pipe	Metal	Grey	Flaking	4	0.3	Negative
1410	1	1	104	Classroom 104 Kindergarten	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	Door Frame	Metal	Grey	Chipping	2	0.4	Negative
1410	1	1	104	Classroom 104 Kindergarten	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	104	Classroom 104 Kindergarten	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	Door Frame	Metal	Blue	Chipping	10	0.5	Negative
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	W2	CMU	Tan	Flaking	4	0.3	Negative
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	W4	CMU	Tan	Flaking	10	0.3	Negative
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	Door Frame	Metal	Blue	Chipping	8	0.4	Negative
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	105	Teacher's Leader Room attached to Main Office to the East	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report					
				Inspection Company: BATT			James Rhoads Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	1	106	School Police Office	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	106	School Police Office	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	106	School Police Office	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	106	School Police Office	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	106	School Police Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	106	School Police Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	107	Main Office	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	107	Main Office	Yes	Door Frame	Metal	Grey	Chipping	16	0.1	Negative
1410	1	1	107	Main Office	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	107	Main Office	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	107	Main Office	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	107	Main Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	107	Main Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	108	Principal's Office	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	108	Principal's Office	Yes	Bath Wall	CMU	Tan	Chipping	4	0.5	Negative
1410	1	1	108	Principal's Office	Yes	W2	CMU	Tan	Chipping	5	0.3	Negative
1410	1	1	108	Principal's Office	Yes	Door Frame	Metal	Tan	Chipping	5	0.3	Negative
1410	1	1	108	Principal's Office	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	108	Principal's Office	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	108	Principal's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	108	Principal's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	109	Auditorium	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	109	Auditorium	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	109	Auditorium	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	109	Auditorium	Yes	W4	CMU	Tan	Chipping	10	0.3	Negative
1410	1	1	109	Auditorium	Yes	Door Frame	Metal	Tan	Chipping	10	0.4	Negative
1410	1	1	109	Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	109	Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	111	Cafeteria Girl's Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	111	Cafeteria Girl's Restroom	Yes	Door Frame	Metal	Grey	Chipping	9	0.5	Negative
1410	1	1	111	Cafeteria Girl's Restroom	Yes	W2	CMU	Tan	Flaking	11	0.4	Negative
1410	1	1	111	Cafeteria Girl's Restroom	Yes	W3	CMU	Tan	Flaking	16	0.5	Negative
1410	1	1	111	Cafeteria Girl's Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	111	Cafeteria Girl's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	111	Cafeteria Girl's Restroom	Yes	Floor	Concrete	Grey	Flaking	23	0.3	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	W1	CMU	Tan	Flaking	6	0.2	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	Door Frame	Metal	Black	Chipping	8	0.4	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	W2	CMU	Tan	Flaking	6	0.4	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	W3	CMU	Tan	Flaking	10	0.3	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	W4	CMU	Tan	Flaking	9	0.3	Negative
1410	1	1	112	Cafeteria Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	112	Cafeteria Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	W1	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	113	Storage Closet in Hallway across from the Boy's and Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	115	Kitchen/Kitchen Office	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	Door Frame	Metal	Tan	Chipping	14	0.5	Negative	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	116	Kitchen Storage Area next to Boy's Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	117	Gym/Cafeteria	Yes	W1	CMU	Tan	Flaking	20	0.2	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	Door Frame	Metal	Tan	Chipping	8	0.5	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	W2	CMU	Tan	Chipping	22	0.4	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	Door Frame	Metal	Blue	Chipping	9	0.5	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	W3	CMU	Tan	Flaking	120	0.3	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	W4	CMU	Tan	Chipping	16	0.4	Negative	
1410	1	1	117	Gym/Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	117	Gym/Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	118	Fan Room in Hallway next to Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	Door Frame	Metal	Blue	Chipping	8	0.5	Negative	
1410	1	1	119	Men's Restroom behind Elevator	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	Partition	Metal	Blue	Chipping	21	0.2	Negative	
1410	1	1	119	Men's Restroom behind Elevator	Yes	Baseboard	Concrete	Blue	Flaking	30	0.3	Negative	
1410	1	1	119	Men's Restroom behind Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	119	Men's Restroom behind Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report					
				Inspection Company: BATT			James Rhoads Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	120	Storage Closet in Hallway across from Classroom 100	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	121	Gym Teacher's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	122	Women's Restroom next to the Auditorium	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	200	Classroom 200	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	200	Classroom 200	Yes	Door Frame	Metal	Green	Chipping	6	0.2	Negative
1410	1	2	200	Classroom 200	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	200	Classroom 200	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	200	Classroom 200	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	2	200	Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	200	Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201	Classroom 201	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	201	Classroom 201	Yes	Door Frame	Metal	Grey	Chipping	5	0.1	Negative
1410	1	2	201	Classroom 201	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	201	Classroom 201	Yes	Door Frame	Metal	Grey	Chipping	8	2.1	Positive
1410	1	2	201	Classroom 201	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	201	Classroom 201	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	2	201	Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201	Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202	Classroom 202	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	202	Classroom 202	Yes	Door Frame	Metal	Grey	Chipping	5	0.5	Negative
1410	1	2	202	Classroom 202	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	202	Classroom 202	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	202	Classroom 202	Yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	2	202	Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202	Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	203	Classroom 203	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	203	Classroom 203	Yes	Door Frame	Metal	Grey	Chipping	8	0.2	Negative
1410	1	2	203	Classroom 203	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	203	Classroom 203	Yes	Door Frame	Metal	Grey	Chipping	2	3	Positive
1410	1	2	203	Classroom 203	Yes	W3	CMU	Grey	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	203	Classroom 203	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	203	Classroom 203	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	203	Classroom 203	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	Door Frame	Metal	Grey	Chipping	2	0.3	Negative	
1410	1	2	204	Classroom 204	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204	Classroom 204	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	Door Frame	Metal	Grey	Chipping	4	0.4	Negative	
1410	1	2	205	Classroom 205	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205	Classroom 205	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	Door Frame	Metal	Grey	Chipping	6	0.5	Negative	
1410	1	2	206	Classroom 206	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206	Classroom 206	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	207	Classroom 207	Yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207	Classroom 207	Yes	Door Frame	Metal	Blue	Chipping	6	0.4	Negative	
1410	1	2	207	Classroom 207	Yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207	Classroom 207	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	207	Classroom 207	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207	Classroom 207	Yes	Ceiling	Concrete	Tan	Cracking	17	0.2	Negative	
1410	1	2	207	Classroom 207	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	Door Frame	Metal	Grey	Chipping	8	0.2	Negative	
1410	1	2	208	Classroom 208	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208	Classroom 208	Yes	Closet Frame	CMU	White	None	6	3.1	Positive	
1410	1	2	209	Classroom 209	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209	Classroom 209	Yes	Door Frame	Metal	Grey	Chipping	9	0.2	Negative	
1410	1	2	209	Classroom 209	Yes	W2	CMU	Grey	Chipping	2	0.5	Negative	
1410	1	2	209	Classroom 209	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209	Classroom 209	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	209	Classroom 209	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report						
				Inspection Company: BATTA		James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	2	209	Classroom 209	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	210	Classroom 210	Yes	W1	CMU	White	None	0	N/A	N/A
1410	1	2	210	Classroom 210	Yes	Door Frame	Metal	Green	Chipping	12	0.4	Negative
1410	1	2	210	Classroom 210	Yes	W2	CMU	White	None	0	N/A	N/A
1410	1	2	210	Classroom 210	Yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	210	Classroom 210	Yes	W4	Metal	Green	Chipping	8	0.2	Negative
1410	1	2	210	Classroom 210	Yes	Ceiling	Concrete	Tan	Flaking	25	0.4	Negative
1410	1	2	210	Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	211	Room 200A across from Classroom 200	Yes	W1	CMU	White / Blue	None	0	N/A	N/A
1410	1	2	211	Room 200A across from Classroom 200	Yes	Door Frame	Metal	Blue	Chipping	7	0.5	Negative
1410	1	2	211	Room 200A across from Classroom 200	Yes	W2	CMU	Blue	Chipping	8	0.5	Negative
1410	1	2	211	Room 200A across from Classroom 200	Yes	W3	CMU	White / Blue	None	0	N/A	N/A
1410	1	2	211	Room 200A across from Classroom 200	Yes	W4	CMU	White / Blue	None	0	N/A	N/A
1410	1	2	211	Room 200A across from Classroom 200	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	211	Room 200A across from Classroom 200	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	Door Frame	Metal	Purple	Chipping	7	0.2	Negative
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	W4	CMU	Tan	Chipping	25	0.3	Negative
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	212	Women's Restroom across from Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	W1	CMU	Blue	None	0	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	Door Frame	Metal	Green	Chipping	11	0.4	Negative
1410	1	2	213	Custodial Closet across from Classroom 202	No	W2	CMU	Blue	None	0	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	W3	CMU	Blue	None	0	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	W4	CMU	Blue	None	0	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	213	Custodial Closet across from Classroom 202	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	Door Frame	Metal	Green	Chipping	8	0.5	Negative
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	W4	CMU	Tan	Flaking	4	0.3	Negative
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	214	Boy's Restroom across from Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	Door Frame	Metal	Green	Chipping	6	0.4	Negative
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	W4	CMU	Tan	Chipping	1	0.5	Negative
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	215	Girl's Restroom across from Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	216	Fan Room next to Classroom 202	No	W1	CMU	Tan	None	0	N/A	N/A
1410	1	2	216	Fan Room next to Classroom 202	No	W2	CMU	Tan	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	216	Fan Room next to Classroom 202	No	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	2	216	Fan Room next to Classroom 202	No	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	2	216	Fan Room next to Classroom 202	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	216	Fan Room next to Classroom 202	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	217	Book Closet next to Fan Room next to Classroom 202	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300	Classroom 300	Yes	W1	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300	Classroom 300	Yes	Door Frame	Metal	Yellow	Chipping	9	0	Negative	
1410	1	3	300	Classroom 300	Yes	W2	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300	Classroom 300	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	300	Classroom 300	Yes	W4	Concrete	Yellow	Chipping	4	0.2	Negative	
1410	1	3	300	Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300	Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	301	Classroom 301	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301	Classroom 301	Yes	Door Frame	Metal	Brown	Chipping	11	0.5	Negative	
1410	1	3	301	Classroom 301	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301	Classroom 301	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	301	Classroom 301	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301	Classroom 301	Yes	Ceiling	Concrete	White	Flaking	20	0.2	Negative	
1410	1	3	301	Classroom 301	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	W1	CMU	Blue	N/A	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	W1	Concrete	White	Chipping	16	0.2	Negative	
1410	1	3	302	Classroom 302	Yes	Door Frame	Metal	Blue	Chipping	10	0.6	Negative	
1410	1	3	302	Classroom 302	Yes	W2	CMU	Blue	Chipping	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	W3	CMU	Grey	N/A	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	W4	CMU	Blue	N/A	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	W4	Concrete	White	Chipping	27	0.3	Negative	
1410	1	3	302	Classroom 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302	Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	303	Classroom 303	Yes	W1	CMU	Tan	Chipping	4	0.2	Negative	
1410	1	3	303	Classroom 303	Yes	Door Frame	Metal	Blue	Chipping	7	0.5	Negative	
1410	1	3	303	Classroom 303	Yes	W2	CMU	Blue	Chipping	6	0.3	Negative	
1410	1	3	303	Classroom 303	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	303	Classroom 303	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	303	Classroom 303	Yes	Ceiling	Concrete	White	Chipping	16	0.3	Negative	
1410	1	3	303	Classroom 303	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	304	Classroom 304	Yes	W1	CMU	White	Chipping	5	0.4	Negative	
1410	1	3	304	Classroom 304	Yes	Door Frame	Metal	Tan	Chipping	13	0.5	Negative	
1410	1	3	304	Classroom 304	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	304	Classroom 304	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	304	Classroom 304	Yes	W4	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	304	Classroom 304	Yes	Ceiling	Concrete	White	Flaking	11	0.3	Negative	
1410	1	3	304	Classroom 304	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	305	Classroom 305	Yes	W1	CMU	Green	Chipping	2	0.1	Negative	
1410	1	3	305	Classroom 305	Yes	Door Frame	Metal	Green / Blue	Chipping	14	0.5	Negative	
1410	1	3	305	Classroom 305	Yes	W2	CMU	Green	None	0	N/A	N/A	
1410	1	3	305	Classroom 305	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	305	Classroom 305	Yes	W4	CMU	Green	None	0	N/A	N/A	
1410	1	3	305	Classroom 305	Yes	Ceiling	Concrete	White	Flaking	15	0.4	Negative	
1410	1	3	305	Classroom 305	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	306	Classroom 306	Yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	3	306	Classroom 306	Yes	Door Frame	Metal	Blue	Chipping	9	0.1	Negative	
1410	1	3	306	Classroom 306	Yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	3	306	Classroom 306	Yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	3	306	Classroom 306	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	3	306	Classroom 306	Yes	Ceiling	Concrete	White	Flaking	16	0.2	Negative	
1410	1	3	306	Classroom 306	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	307	Classroom 307	Yes	W1	CMU	Green Blue	None	0	N/A	N/A	
1410	1	3	307	Classroom 307	Yes	W2	CMU	Green Blue	Chipping	3	0.4	Negative	
1410	1	3	307	Classroom 307	Yes	W3	CMU	Green Blue	None	0	N/A	N/A	
1410	1	3	307	Classroom 307	Yes	W4	CMU	Green Blue	None	0	N/A	N/A	
1410	1	3	307	Classroom 307	Yes	Ceiling	Concrete	White	Flaking	16	0.2	Negative	
1410	1	3	307	Classroom 307	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	308	Classroom 308	Yes	W1	CMU	Grey	Chipping	2	0.4	Negative	
1410	1	3	308	Classroom 308	Yes	Door Frame	Metal	Grey	Chipping	12	0.5	Negative	
1410	1	3	308	Classroom 308	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	3	308	Classroom 308	Yes	Door Frame	Metal	Grey	Chipping	11	7.4	Positive	
1410	1	3	308	Classroom 308	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	308	Classroom 308	Yes	W4	CMU	Orange	None	0	N/A	N/A	
1410	1	3	308	Classroom 308	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	308	Classroom 308	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	W1	Concrete	Grey	Chipping	2	0.1	Negative	
1410	1	3	309	Classroom 309	Yes	Door Frame	Metal	Grey	Chipping	10	0.5	Negative	
1410	1	3	309	Classroom 309	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	W4	CMU	Orange	None	0	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	309	Classroom 309	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	W1	CMU	Grey / Orange	None	0	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	Door Frame	Metal	Grey	Chipping	6	0.6	Negative	
1410	1	3	310	Classroom 310	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310	Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	W2	CMU	Tan	Chipping	19	0.1	Negative	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	W4	CMU	Tan	Chipping	8	0.2	Negative	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	Ceiling	Concrete	White	Flaking	2	0.2	Negative	
1410	1	3	311	Women's Restroom across from Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	Door Frame	Metal	Blue	Chipping	9	0.3	Negative	
1410	1	3	312	Fan Room near Classroom 302	No	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	312	Fan Room near Classroom 302	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	W1	CMU	White / Grey	None	0	N/A	N/A	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	Door Frame	Metal	Blue / Brown	Chipping	7	0.2	Negative	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	W2	CMU	White / Grey	None	0	N/A	N/A	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	W3	CMU	White / Grey	Flaking	2	0.3	Negative	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	W4	CMU	White / Grey	None	0	N/A	N/A	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	Ceiling	Concrete	White	Flaking	12	0.2	Negative	
1410	1	3	313	Boy's Restroom across from Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	Door Frame	Metal	Brown	Chipping	7	0.5	Negative	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	W2	CMU	Tan	Chipping	2	0.3	Negative	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	314	Girl's Restroom across Classroom 302	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Nurse's Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	Door Frame	Metal	Blue	Chipping	5	0.2	Negative	
1410	1	3	316	Custodial Closet near Classroom 302	No	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	316	Custodial Closet near Classroom 302	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	Door Frame	Metal	Blue	Chipping	9	0.5	Negative	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	W4	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	317	Book Closet across from the Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400	Classroom 400	Yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	400	Classroom 400	Yes	Door Frame	Metal	Green / Brown	Chipping	13	0.5	Negative	
1410	1	4	400	Classroom 400	Yes	W2	CMU	Green	None	0	N/A	N/A	
1410	1	4	400	Classroom 400	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	400	Classroom 400	Yes	W4	CMU	Blue	Chipping	4	0.3	Negative	
1410	1	4	400	Classroom 400	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400	Classroom 400	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	401	Classroom 401	Yes	W1	CMU	Blue	Chipping	20	0.3	Negative	
1410	1	4	401	Classroom 401	Yes	Door Frame	Metal	Blue / Brown	Chipping	10	0.6	Negative	
1410	1	4	401	Classroom 401	Yes	W2	CMU	Blue	None	N/A	N/A	N/A	
1410	1	4	401	Classroom 401	Yes	W3	CMU	Grey	None	N/A	N/A	N/A	
1410	1	4	401	Classroom 401	Yes	W4	CMU	Blue	None	N/A	N/A	N/A	
1410	1	4	401	Classroom 401	Yes	Ceiling	Concrete	White	Flaking	10	0.3	Negative	
1410	1	4	401	Classroom 401	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	402	Classroom 402	Yes	W1	CMU	Green / Yellow	Chipping	6	0.2	Negative	
1410	1	4	402	Classroom 402	Yes	Door Frame	Metal	Blue / Brown	Chipping	5	0.1	Negative	
1410	1	4	402	Classroom 402	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	402	Classroom 402	Yes	Pipe	Metal	White	Flaking	5	0.5	Negative	
1410	1	4	402	Classroom 402	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	402	Classroom 402	Yes	Floor Edge	Concrete	Grey	Flaking	9	0.2	Negative	
1410	1	4	402	Classroom 402	Yes	W4	CMU	Green	None	0	N/A	N/A	
1410	1	4	402	Classroom 402	Yes	Ceiling	Concrete	White	Flaking	30	0.3	Negative	
1410	1	4	402	Classroom 402	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	403	Classroom 403	Yes	W1	CMU	White / Green	Chipping	29	0.3	Negative	
1410	1	4	403	Classroom 403	Yes	Door Frame	Metal	Blue	Chipping	16	0.5	Negative	
1410	1	4	403	Classroom 403	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	403	Classroom 403	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	403	Classroom 403	Yes	W4	CMU	Green	Chipping	9	0.1	Negative	
1410	1	4	403	Classroom 403	Yes	Ceiling	Concrete	White	Flaking	10	0.3	Negative	
1410	1	4	403	Classroom 403	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	404	Classroom 404	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404	Classroom 404	Yes	Door Frame	Metal	Blue Green / Brown	Chipping	7	0.6	Negative	
1410	1	4	404	Classroom 404	Yes	W2	CMU	Grey	Efflorescence	50	0.5	Negative	
1410	1	4	404	Classroom 404	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404	Classroom 404	Yes	W4	CMU	Blue Green	None	0	N/A	N/A	
1410	1	4	404	Classroom 404	Yes	Ceiling	Concrete	White	Flaking	13	0.1	Negative	
1410	1	4	404	Classroom 404	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	405	Classroom 405	Yes	W1	CMU	Grey	Chipping	9	0.1	Negative	
1410	1	4	405	Classroom 405	Yes	Door Frame	Metal	Green	Chipping	14	0.5	Negative	
1410	1	4	405	Classroom 405	Yes	W2	CMU	Grey	Chipping	9	0.4	Negative	
1410	1	4	405	Classroom 405	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	405	Classroom 405	Yes	W4	CMU	Grey	Chipping	20	0.3	Negative	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	405	Classroom 405	Yes	Ceiling	Concrete	White	Flaking	14	0.2	Negative	
1410	1	4	405	Classroom 405	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	406	Classroom 406	Yes	W1	CMU	Blue	Chipping	11	0.6	Negative	
1410	1	4	406	Classroom 406	Yes	Door Frame	Metal	Blue	Chipping	16	0.5	Negative	
1410	1	4	406	Classroom 406	Yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	406	Classroom 406	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	406	Classroom 406	Yes	W4	CMU	Blue	Chipping	20	0.5	Negative	
1410	1	4	406	Classroom 406	Yes	Ceiling	Concrete	White	Flaking	12	0.2	Negative	
1410	1	4	406	Classroom 406	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	407	Classroom 407	Yes	W1	CMU	Blue	Chipping	6	0.3	Negative	
1410	1	4	407	Classroom 407	Yes	Door Frame	Metal	Blue / Brown	Chipping	16	0.5	Negative	
1410	1	4	407	Classroom 407	Yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	407	Classroom 407	Yes	Pipe	Metal	White	Chipping	4	0.4	Negative	
1410	1	4	407	Classroom 407	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	407	Classroom 407	Yes	W4	CMU	Blue	Chipping	11	0.1	Negative	
1410	1	4	407	Classroom 407	Yes	Ceiling	Concrete	White	Flaking	33	0.3	Negative	
1410	1	4	407	Classroom 407	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	408	Classroom 408	Yes	W1	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408	Classroom 408	Yes	Door Frame	Metal	Blue / Brown	Chipping	11	0.6	Negative	
1410	1	4	408	Classroom 408	Yes	W2	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408	Classroom 408	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	408	Classroom 408	Yes	W4	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408	Classroom 408	Yes	Ceiling	Concrete	White	Flaking	14	0.2	Negative	
1410	1	4	408	Classroom 408	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	409	Classroom 409	Yes	W1	CMU	Blue	Chipping	33	0.4	Negative	
1410	1	4	409	Classroom 409	Yes	Door Frame	Metal	Blue / Brown	Chipping	15	0.3	Negative	
1410	1	4	409	Classroom 409	Yes	W2	CMU	Blue	Chipping	9	0.3	Negative	
1410	1	4	409	Classroom 409	Yes	Wall Panels	Transite	Blue	Chipping	9	0.2	Negative	
1410	1	4	409	Classroom 409	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	409	Classroom 409	Yes	W4	CMU	Blue	Chipping	8	0.2	Negative	
1410	1	4	409	Classroom 409	Yes	Ceiling	Concrete	White	Flaking	35	0.2	Negative	
1410	1	4	409	Classroom 409	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	Door Frame	Metal	Blue / Brown	Chipping	8	0.5	Negative	
1410	1	4	410	Classroom 410	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410	Classroom 410	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	Door Frame	Metal	Brown	Chipping	4	0.3	Negative	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATTA			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	411	Women's Restroom across from Classroom 400	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	Door Frame	Metal	Brown	Chipping	6	0.2	Negative	
1410	1	4	412	Custodial Closet across from Classroom 400	No	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	412	Custodial Closet across from Classroom 400	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	Door Frame	Metal	Blue / Brown	Chipping	8	0.5	Negative	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	W4	CMU	White	Efflorescence	6	0.5	Negative	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	413	Boy's Restroom across from Classroom 402	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	Door Frame	Metal	Brown	Chipping	9	0.4	Negative	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	W2	CMU	White	Flaking	8	0.5	Negative	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	414	Girl's Restroom across from Classroom 402	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	415	Men's Restroom across from Classroom 402	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	416	Fan Room next to Classroom 402	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	Door Frame	Metal	Brown	Chipping	7	0.5	Negative	
1410	1	4	417	Book Closet next to Fan Room	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	417	Book Closet next to Fan Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	W4	CMU	Grey	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	B	003A	Restroom in the Basement Mechanical Area	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	100A	Girl's Restroom next to Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	100B	Boy's Restroom between Girl's Restroom and Fan Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102A	Classroom 102 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102C	Classroom 102 Supply Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	102D	Classroom 102 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	103A	IMC (Library) Office	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104A	Classroom 104 Restroom	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	104A	Classroom 104 Restroom	Yes	W2	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes, 003542									
				Inspection Company: BATTa			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	1	104A	Classroom 104 Restroom	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	104A	Classroom 104 Restroom	Yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	104A	Classroom 104 Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104A	Classroom 104 Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	W1	CMU	Tan	Chipping	1	0.5	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	Door Frame	Metal	Grey	Chipping	13	0.4	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	W2	CMU	Blue	Chipping	5	0.4	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	Baseboard	CMU	Grey	Chipping	19	0.1	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	W3	CMU	Grey	Chipping	2	0.3	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	W4	CMU	Tan	Chipping	3	0.4	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	Baseboard	CMU	Grey	Chipping	17	0.2	Negative	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104B	Teacher's Lounge across from the IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104C	Classroom 104 Supply Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	104D	Classroom 104 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	105A	Teacher's Leader Room attached to Main Office to the East Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	1	105B	Teacher's Leader Room attached to Main Office to the East - Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	107A	Main Office Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	108A	Principal's Office Restroom	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	108B	Principal's Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	109A	Stage	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	109A	Stage	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	109A	Stage	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	109A	Stage	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	109A	Stage	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	109A	Stage	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	113A	Custodial Closet in Hallway across from the Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	11A	Closet next to Main entrance Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	200A	Classroom 200 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	200A	Classroom 200 Closet	yes	W2	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report					
				Inspection Company: BATT			James Rhoads Elementary School					
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	2	200A	Classroom 200 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	2	200A	Classroom 200 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	2	200A	Classroom 200 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	200A	Classroom 200 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	200B	Classroom 200 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201A	Classroom 201 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	201B	Classroom 201 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202A	Classroom 202 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	Door Frame	Metal	Grey	Chipping	2	2.2	Positive
1410	1	2	202B	Classroom 202 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	202B	Classroom 202 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	203A	Classroom 203 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	203B	Classroom 203 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	2	203B	Classroom 203 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	2	203B	Classroom 203 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	2	203B	Classroom 203 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	203B	Classroom 203 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	203B	Classroom 203 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204A	Classroom 204 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	Door Frame	Metal	Grey	Chipping	2	5	Positive	
1410	1	2	204B	Classroom 204 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	204B	Classroom 204 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205A	Classroom 205 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	Door Frame	Metal	Grey	Chipping	3	3.6	Positive	
1410	1	2	205B	Classroom 205 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	205B	Classroom 205 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	Closet Frame	CMU	White	None	2	6.7	Positive	
1410	1	2	206A	Classroom 206 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206A	Classroom 206 Closet	yes	Floor	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	206B	Classroom 206 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	207A	Classroom 207 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	207A	Classroom 207 Closet	yes	Door Frame	Metal	Green	Chipping	2	0.5	Negative	
1410	1	2	207A	Classroom 207 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	207A	Classroom 207 Closet	yes	W3	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	207A	Classroom 207 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	207A	Classroom 207 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	207A	Classroom 207 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	10	3.4	Positive	
1410	1	2	207B	Classroom 207 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	2	3.5	Positive	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	5	0.9	Positive	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Shelf	Wood	Blue	Chipping	4	0.1	Negative	
1410	1	2	207B	Classroom 207 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	207B	Classroom 207 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208A	Classroom 208 Closet	yes	Floor	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	208B	Classroom 208 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	Door Frame	Metal	Brown	Chipping	10	4.6	Positive	
1410	1	2	209A	Classroom 209 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	209A	Classroom 209 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	209B	Classroom 209 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	Door Frame	Metal	Green	Chipping	25	6.1	Positive	
1410	1	2	210A	Classroom 210 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	210A	Classroom 210 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	210B	Classroom 210 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Door Frame	Metal	Green	Chipping	25	6.1	Positive	
1410	1	2	210B	Classroom 210 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Shelf	Metal	Blue	Chipping	16	0	Negative	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	6	5.5	Positive	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	20	1.4	Positive	
1410	1	2	210B	Classroom 210 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	2	210B	Classroom 210 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	210B	Classroom 210 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	W1	CMU	White / Green	None	0	N/A	N/A	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	Door Frame	Metal	Blue	Chipping	5	0.5	Negative	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	W2	CMU	White / Green	None	0	N/A	N/A	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	W3	CMU	White / Green	None	0	N/A	N/A	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	W4	CMU	White / Green	None	0	N/A	N/A	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	Ceiling	Concrete	White	Chipping	8	0.2	Negative	
1410	1	2	215A	Men's Restroom across from Classroom 202	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300A	Classroom 300 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	Door Frame	Metal	Blue	Chipping	8	0.6	Negative	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300A	Room 300A across from Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	yes	W1	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	Yes	Door Frame	Metal	Yellow	Chipping	12	4.2	Positive	
1410	1	3	300B	Classroom 300 Coat Closet	yes	W2	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	Yes	Shelf	Metal	Yellow	Chipping	5	0.1	Negative	
1410	1	3	300B	Classroom 300 Coat Closet	Yes	Shelf Support	Metal	Yellow	Chipping	1	5	Positive	
1410	1	3	300B	Classroom 300 Coat Closet	Yes	Coat Rack	Wood	Yellow	Chipping	25	1.3	Positive	
1410	1	3	300B	Classroom 300 Coat Closet	yes	W3	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	yes	W4	CMU	Yellow	None	0	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	300B	Classroom 300 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	301A	Classroom 301 Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301A	Classroom 301 Closet	yes	Door Frame	Metal	Brown	Chipping	2	0.3	Negative	
1410	1	3	301A	Classroom 301 Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301A	Classroom 301 Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301A	Classroom 301 Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	301A	Classroom 301 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	301A	Classroom 301 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Door Frame	Metal	Brown	Chipping	9	5.6	Positive	
1410	1	3	301B	Classroom 301 Coat Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Shelf	Metal	Tan	Chipping	1	0.2	Negative	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Shelf Support	Metal	Tan	Chipping	2	4.3	Positive	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Coat Rack	Wood	Tan	Chipping	3	1	Positive	
1410	1	3	301B	Classroom 301 Coat Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	301B	Classroom 301 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	Door Frame	Metal	Blue	Chipping	6	0.1	Negative	
1410	1	3	302A	Classroom 302 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302A	Classroom 302 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	9	4.6	Positive	
1410	1	3	302B	Classroom 302 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Shelf	Metal	Blue	Chipping	10	0.2	Negative	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	1	6.7	Positive	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	38	1.2	Positive	
1410	1	3	302B	Classroom 302 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	302B	Classroom 302 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	303A	Classroom 303 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	10	4.1	Positive	
1410	1	3	303B	Classroom 303 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Shelf	Metal	White	Chipping	4	0.2	Negative	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Shelf Support	Metal	White	Chipping	4	3.4	Positive	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Coat Rack	Wood	White	Chipping	6	1.6	Positive	
1410	1	3	303B	Classroom 303 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	303B	Classroom 303 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	304A	Classroom 304 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	304A	Classroom 304 Closet	yes	Door Frame	Metal	Tan	Chipping	5	0.5	Negative	
1410	1	3	304A	Classroom 304 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	304A	Classroom 304 Closet	yes	Pipe Cover	Metal	White	Chipping	4	0.6	Negative	
1410	1	3	304A	Classroom 304 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	304A	Classroom 304 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	304A	Classroom 304 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	304A	Classroom 304 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Door Frame	Metal	Tan	Chipping	16	4.4	Positive	
1410	1	3	304B	Classroom 304 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Shelf	Metal	tan	Chipping	2	0.1	Negative	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Shelf Support	Metal	White	Chipping	3	3.2	Positive	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Shelf Support	Wood	White	Chipping	5	1.1	Positive	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Coat Rack	Wood	tan	Chipping	4	0.9	Positive	
1410	1	3	304B	Classroom 304 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	304B	Classroom 304 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	Door Frame	Metal	Blue	Chipping	3	0.5	Negative	
1410	1	3	305A	Classroom 305 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	305A	Classroom 305 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	W1	CMU	Green	None	0	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	16	4.6	Positive	
1410	1	3	305B	Classroom 305 Coat Closet	yes	W2	CMU	Green	None	0	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Shelf	Metal	Blue	Chipping	5	0.1	Negative	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	3	6.5	Positive	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Coat Rack	Wood	Blue	Flaking	22	0.9	Positive	
1410	1	3	305B	Classroom 305 Coat Closet	yes	W3	CMU	Green	None	0	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	W4	CMU	Green	None	0	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	305B	Classroom 305 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	306A	Classroom 306 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	306B	Classroom 306 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	3	306B	Classroom 306 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	15	2.5	Positive	
1410	1	3	306B	Classroom 306 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report						
				Inspection Company: BATT A		James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	3	306B	Classroom 306 Coat Closet	yes	Shelf	Metal	Blue	Chipping	7	0.2	Negative
1410	1	3	306B	Classroom 306 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	2	4.7	Positive
1410	1	3	306B	Classroom 306 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	2	1	Positive
1410	1	3	306B	Classroom 306 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A
1410	1	3	306B	Classroom 306 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A
1410	1	3	306B	Classroom 306 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	306B	Classroom 306 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	Door Frame	Metal	Blue	Chipping	2	0.5	Negative
1410	1	3	307A	Classroom 307 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	307A	Classroom 307 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	307B	Classroom 307 Coat Closet	yes	W1	CMU	Green Blue	None	0	N/A	N/A
1410	1	3	307B	Classroom 307 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	5	4.8	Positive
1410	1	3	307B	Classroom 307 Coat Closet	yes	W2	CMU	Green Blue	None	0	N/A	N/A
1410	1	3	307B	Classroom 307 Coat Closet	yes	Shelf	Metal	Blue	Chipping	2	0.2	Negative
1410	1	3	307B	Classroom 307 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	1	3.9	Positive
1410	1	3	307B	Classroom 307 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	6	0.9	Positive
1410	1	3	307B	Classroom 307 Coat Closet	yes	W3	CMU	Green Blue	Chipping	3	0.4	Negative
1410	1	3	307B	Classroom 307 Coat Closet	yes	W4	CMU	Green Blue	None	0	N/A	N/A
1410	1	3	307B	Classroom 307 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	307B	Classroom 307 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	308A	Classroom 308 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	308B	Classroom 308 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	W1	CMU	White	None	0	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	W2	CMU	White	None	0	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	W3	CMU	White	None	0	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	W4	CMU	White	None	0	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	309A	Classroom 309 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	309B	Classroom 309 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	3	309B	Classroom 309 Coat Closet	yes	Door Frame	Metal	Grey	Chipping	15	4.2	Positive
1410	1	3	309B	Classroom 309 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	309B	Classroom 309 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	309B	Classroom 309 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	3	309B	Classroom 309 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	309B	Classroom 309 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310A	Classroom 310 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	Door Frame	Metal	Grey	Chipping	9	11.1	Positive	
1410	1	3	310B	Classroom 310 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	310B	Classroom 310 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	Door Frame	Metal	Brown	Chipping	7	0.4	Negative	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400A	Room 400A across from Classroom 400	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	W1	CMU	Green	None	0	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	15	3.1	Positive	
1410	1	4	400B	Classroom 400 Coat Closet	yes	W2	CMU	Green	None	0	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Shelf	Metal	Blue	Chipping	7	0.1	Negative	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	3	4.2	Positive	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	12	0.9	Positive	
1410	1	4	400B	Classroom 400 Coat Closet	yes	W3	CMU	Green	None	0	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	W4	CMU	Green	None	0	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400B	Classroom 400 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	Door Frame	Metal	Blue	Chipping	8	0.2	Negative	
1410	1	4	400C	Classroom 400 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	400C	Classroom 400 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	401A	Classroom 401 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	401A	Classroom 401 Closet	yes	Door Frame	Metal	Blue	Chipping	7	0.4	Negative	
1410	1	4	401A	Classroom 401 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	401A	Classroom 401 Closet	yes	W3	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes, 003542									
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	401A	Classroom 401 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	401A	Classroom 401 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	401A	Classroom 401 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	26	1.8	Positive	
1410	1	4	401B	Classroom 401 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Shelf	Metal	Blue	Chipping	17	0.2	Negative	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	1	3.4	Positive	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	19	1.1	Positive	
1410	1	4	401B	Classroom 401 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	401B	Classroom 401 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	Door Frame	Metal	Blue	Chipping	3	0.2	Negative	
1410	1	4	402A	Classroom 402 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	402A	Classroom 402 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Door Frame	Metal	Blue / Yellow	Chipping	15	2.6	Positive	
1410	1	4	402B	Classroom 402 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Shelf	Metal	Blue	Chipping	3	0.1	Negative	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Shelf Support	Metal	Yellow	Chipping	1	6.2	Positive	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	7	0.9	Positive	
1410	1	4	402B	Classroom 402 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	402B	Classroom 402 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	Door Frame	Metal	Blue	Chipping	10	0.5	Negative	
1410	1	4	403A	Classroom 403 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	403A	Classroom 403 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	403B	Classroom 403 Coat Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	19	0.5	Negative	
1410	1	4	403B	Classroom 403 Coat Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Shelf	Metal	Blue	Chipping	6	0.1	Negative	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	1	6.8	Positive	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	16	1.1	Positive	
1410	1	4	403B	Classroom 403 Coat Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	403B	Classroom 403 Coat Closet	yes	W4	CMU	White	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	403B	Classroom 403 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	Door Frame	Metal	Blue Green	Chipping	3	0.6	Negative	
1410	1	4	404A	Classroom 404 Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	Pipe	Metal	Grey	Chipping	1	0.5	Negative	
1410	1	4	404A	Classroom 404 Closet	yes	W3	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	404A	Classroom 404 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	404B	Classroom 404 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404B	Classroom 404 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Door Frame	Metal	Blue Green	Chipping	6	2.2	Positive	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Shelf	Metal	Grey	Chipping	6	0.1	Negative	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Shelf Support	Metal	Grey	Chipping	3	4	Positive	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Shelf Support	Wood	Grey	Efflorescence	10	1.6	Positive	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Coat Rack	Wood	Grey	Chipping	2	0.8	Positive	
1410	1	4	404B	Classroom 404 Coat Closet	yes	W3	CMU	Grey	Efflorescence	50	0.5	Negative	
1410	1	4	404B	Classroom 404 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	404B	Classroom 404 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	Door Frame	Metal	Green	Chipping	3	0.5	Negative	
1410	1	4	405A	Classroom 405 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	405A	Classroom 405 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	405B	Classroom 405 Coat Closet	yes	W1	CMU	Grey	None	0	N/A	N/A	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Door Frame	Metal	Green	Chipping	23	2	Positive	
1410	1	4	405B	Classroom 405 Coat Closet	yes	W2	CMU	Grey	None	0	N/A	N/A	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Shelf	Metal	Green	Chipping	4	0.2	Negative	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Shelf Support	Metal	Green	Chipping	1	2.7	Positive	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Coat Rack	Wood	Green	Chipping	22	0.8	Positive	
1410	1	4	405B	Classroom 405 Coat Closet	yes	W3	CMU	Grey	Chipping	9	0.4	Negative	
1410	1	4	405B	Classroom 405 Coat Closet	yes	W4	CMU	Grey	None	0	N/A	N/A	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	405B	Classroom 405 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	Door Frame	Metal	Blue	Chipping	4	0.5	Negative	
1410	1	4	406A	Classroom 406 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	406A	Classroom 406 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	406B	Classroom 406 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	20	1.7	Positive	
1410	1	4	406B	Classroom 406 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Shelf	Metal	White	Chipping	8	0.2	Negative	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Shelf Support	Metal	White	Chipping	2	0.2	Negative	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Coat Rack	Wood	White	Chipping	18	0.2	Negative	
1410	1	4	406B	Classroom 406 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	4	406B	Classroom 406 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	406B	Classroom 406 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	Door Frame	Metal	Tan	Chipping	3	0.1	Negative	
1410	1	4	407A	Classroom 407 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	Pipe	Metal	White	Chipping	6	0.4	Negative	
1410	1	4	407A	Classroom 407 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	407A	Classroom 407 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Door Frame	Metal	White	Chipping	30	1.9	Positive	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Shelf	Metal	White	Chipping	5	0.2	Negative	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Shelf Support	Metal	White	Chipping	4	5.8	Positive	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Coat Rack	Wood	White	Chipping	13	1.5	Positive	
1410	1	4	407B	Classroom 407 Coat Closet	yes	W3	CMU	Blue	None	0	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	407B	Classroom 407 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	Door Frame	Metal	Blue	Chipping	1	0.5	Negative	
1410	1	4	408A	Classroom 408 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	408A	Classroom 408 Closet	yes	Floor	N/A	N/A	None	N/A	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	W1	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	18	2.5	Positive	
1410	1	4	408B	Classroom 408 Coat Closet	yes	W2	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Shelf	Metal	Blue	Chipping	2	0.1	Negative	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	2	7.9	Positive	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	10	1.2	Positive	
1410	1	4	408B	Classroom 408 Coat Closet	yes	W3	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	W4	CMU	Yellow	None	0	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	408B	Classroom 408 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	4	409A	Classroom 409 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	409A	Classroom 409 Closet	yes	Door Frame	Metal	Blue	Chipping	2	0.4	Negative	
1410	1	4	409A	Classroom 409 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	409A	Classroom 409 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	409A	Classroom 409 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	409A	Classroom 409 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	409A	Classroom 409 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	409B	Classroom 409 Coat Closet	yes	W1	CMU	Blue	None	0	N/A	N/A	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Door Frame	Metal	Blue	Chipping	28	2.4	Positive	
1410	1	4	409B	Classroom 409 Coat Closet	yes	W2	CMU	Blue	None	0	N/A	N/A	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Shelf	Metal	Blue	Chipping	9	0.1	Negative	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Shelf Support	Metal	Blue	Chipping	1	5.8	Positive	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Coat Rack	Wood	Blue	Chipping	26	0.8	Positive	
1410	1	4	409B	Classroom 409 Coat Closet	yes	W3	CMU	Blue	Chipping	9	0.3	Negative	
1410	1	4	409B	Classroom 409 Coat Closet	yes	W4	CMU	Blue	None	0	N/A	N/A	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	409B	Classroom 409 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410A	Classroom 410 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	410B	Classroom 410 Coat Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	E1	Elevator	Yes	W1	Metal	N/A	None	0	N/A	N/A	
1410	1	4	E1	Elevator	Yes	W2	Metal	N/A	None	0	N/A	N/A	
1410	1	4	E1	Elevator	Yes	W3	Metal	N/A	None	0	N/A	N/A	
1410	1	4	E1	Elevator	Yes	W4	Metal	N/A	None	0	N/A	N/A	
1410	1	4	E1	Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	E1	Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	Door Frame	Metal	Blue	Chipping	9	0.1	Negative	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11/H14	Hallway from the Elevator to Classroom 100	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11A	Main Entrance Foyer	Yes	W1	Marble	N/A	None	0	N/A	N/A	
1410	1	1	H11A	Main Entrance Foyer	Yes	W2	Marble	N/A	None	0	N/A	N/A	
1410	1	1	H11A	Main Entrance Foyer	Yes	W3	Marble	N/A	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	1	H11A	Main Entrance Foyer	Yes	W4	Marble	N/A	None	0	N/A	N/A	
1410	1	1	H11A	Main Entrance Foyer	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11A	Main Entrance Foyer	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H11B	Hallway leading into the Cafeteria	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H12	Hallway from the Auditorium to the IMC (Library)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	W1	CMU	White	None	0	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	W2	CMU	White	None	0	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	W3	CMU	White	None	0	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	W4	CMU	White	None	0	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	H12A	East Entrance Foyer by IMC (Library) and Teacher's Lounge	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	H25	Hallway from Classroom 200 to Classroom 201	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	W2	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	H26	Hallway from Elevator to Classroom 210	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	W2	CMU	Tan	Flaking	14	0.3	Negative	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	W3	CMU	Tan	None	0	N/A	N/A	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	W4	CMU	Tan	None	0	N/A	N/A	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	H37	Hallway from Elevator to Classroom 310	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	W1	CMU	Tan	None	0	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22		Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes, 003542								
				Inspection Company: BATTA				James Rhoads Elementary School				
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	W3	CMU	Tan	Flaking	9	0.2	Negative
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	H38	Hallway from Classroom 301 to Classroom 300	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	W2	CMU	Tan	Flaking	27	0.3	Negative
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	W4	CMU	Tan	Flaking	19	0.4	Negative
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	H410	Hallway from Elevator to Classroom 410	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	H49	Hallway from Classroom 400 to Classroom 401	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	PC215A	215A Men's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	W3	Concrete	Grey	None	0	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	W4	Concrete	Grey	None	0	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S01	Stairs leading to the outside at the North of the Boiler Room	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S02	Stairs behind Elevator	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	W1	CMU	Grey	None	0	N/A	N/A
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	W2	CMU	Grey	None	0	N/A	N/A
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	W3	Concrete	Grey	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report						
				Inspection Company: BATT		James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	W4	Concrete	Grey	None	0	N/A	N/A
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	B	S03	Small Stairs leading into the Boiler Room from the South	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	W1	CMU	Tan	Chipping	11	0.5	Negative
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	W2	CMU	Tan	Chipping	20	0.4	Negative
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	Railing Post	Metal	Blue	Chipping	9	2.8	Positive
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	W4	CMU	Tan	Chipping	35	0	Negative
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	Railing	Metal	Blue	Chipping	45	3.6	Positive
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	Stair Tread	Metal	Blue	Chipping	70	0.3	Negative
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	Ceiling	Metal	Tan	Flaking	20	1.4	Positive
1410	1	1	S11	Stairwell A (1st and 2nd)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	W2	CMU	Tan	None	0	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	S11A	Hallway from Stairwell A to School Yard	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	S12	Stairwell C (1st Floor)	Yes	W1	CMU	Tan	None	0	N/A	N/A
1410	1	1	S12	Stairwell C (1st Floor)	Yes	W2	CMU	Tan	Chipping	11	0.4	Negative
1410	1	1	S12	Stairwell C (1st Floor)	Yes	W3	CMU	Tan	None	0	N/A	N/A
1410	1	1	S12	Stairwell C (1st Floor)	Yes	W4	CMU	Tan	None	0	N/A	N/A
1410	1	1	S12	Stairwell C (1st Floor)	Yes	Stair Tread	Metal	Blue	Chipping	60	0.3	Negative
1410	1	1	S12	Stairwell C (1st Floor)	Yes	Railing	Metal	Blue	Chipping	20	0	Negative
1410	1	1	S12	Stairwell C (1st Floor)	Yes	Railing Post	Metal	Blue	Chipping	6	2.5	Positive
1410	1	1	S12	Stairwell C (1st Floor)	Yes	Ceiling	Concrete	White	Flaking	9	0.4	Negative
1410	1	1	S12	Stairwell C (1st Floor)	Yes	Floor	Concrete	Blue	Chipping	100	0.2	Negative
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	W1	CMU	White	None	0	N/A	N/A
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	W2	CMU	White	None	0	N/A	N/A
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Railing	Metal	Blue	Chipping	30	0.1	Negative
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	W3	CMU	White	None	0	N/A	N/A
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	W4	CMU	White	None	0	N/A	N/A
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Conduit	Metal	White	Chipping	3	0.1	Negative
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Railing	Metal	Blue	Chipping	20	0.1	Negative
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Railing Post	Metal	Blue	Chipping	6	1.6	Positive
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	2	S12	Stairwell C (2nd Floor)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	W1	CMU	White	None	0	N/A	N/A
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Door	Metal	Blue	Chipping	1	0	Negative
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Door Frame	Metal	Blue	Chipping	7	0.5	Negative
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	W2	CMU	White	Flaking	15	0.3	Negative
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Railing	Metal	Blue	Chipping	15	1.6	Positive
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	W3	CMU	White	None	0	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	W4	CMU	White	Flaking	7	0.4	Negative	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Railing Post	Metal	Blue	Chipping	2	3.6	Positive	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Baseboard	Metal	Blue	Chipping	2	5.6	Positive	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Stair Tread	Metal	Blue	Chipping	45	0.3	Negative	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Stair Riser	Metal	Blue	Chipping	2	2.6	Positive	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	S12	Stairwell C (3rd Floor)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	W1	CMU	White	Chipping	8	0.4	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Door	Metal	Blue	Chipping	17	0.2	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Door Frame	Metal	Blue	Chipping	7	0.3	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	W2	CMU	White	Chipping	12	0.3	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Railing	Metal	Blue	Flaking	5	2.5	Positive	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	W3	CMU	White	Chipping	12	0.5	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	W4	CMU	White	Chipping	8	0.4	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Railing Post	Metal	Blue	Flaking	3	3.5	Positive	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Baseboard	Metal	Blue	Chipping	2	2.5	Positive	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Stair Tread	Metal	Blue	Chipping	20	0.4	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Stair Riser	Metal	Blue	Chipping	1	2	Positive	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Ceiling	Concrete	White	Flaking	2	0.2	Negative	
1410	1	4	S12	Stairwell C (4th Floor)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Door	Metal	Blue	Chipping	8	0.1	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	W2	CMU	Tan	Chipping	21	0.5	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Stair Tread	Metal	Blue	Chipping	55	0.3	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	W3	CMU	Tan	Chipping	11	0.4	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	W4	CMU	Tan	Chipping	23	0.4	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Railing	Metal	Blue	Chipping	30	0.1	Negative	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Railing Post	Metal	Blue	Chipping	6	1.9	Positive	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Ceiling	Metal	Tan	Flaking	5	6	Positive	
1410	1	1	S13	Stairwell B(1st and 2nd)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	W1	CMU	Tan	None	0	N/A	N/A	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Door	Metal	Brown / Blue	Chipping	30	0.2	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	W2	CMU	Tan	Chipping	21	0.5	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Stair Tread	Metal	Blue	Chipping	30	0.1	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	W3	CMU	Tan	Chipping	19	0.5	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	W4	CMU	Tan	Chipping	16	0.5	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Railing	Metal	Blue	Chipping	21	0.1	Negative	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Railing Post	Metal	Blue	Chipping	5	1.5	Positive	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Ceiling	Metal	Tan	Flaking	10	2.6	Positive	
1410	1	1	S13	Stairwell B (3rd and 4th)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	W1	CMU	Tan	Chipping	12	0	Negative	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	W2	CMU	Tan	Chipping	17	0.5	Negative	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	Railing Post	Metal	Blue	Chipping	9	1.6	Positive	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	W3	CMU	Tan	Chipping	1	0.5	Negative	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	W4	CMU	Tan	Chipping	15	0.5	Negative	

				Inspection Dates: 12/28/21 - 1/4/22			Lead Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Charles Rhodes, 003542									
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	Railing	Metal	Blue	Chipping	45	1.5	Positive	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	Stair Tread	Metal	Blue	Chipping	60	0.4	Negative	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	122PC	122 Women's Restroom Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	AT	9	Attic/Penthouse in Stairwell	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	S21	Stairwell A (3rd and 4th)	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	8	Crawl Space - Basement by Shower	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	CS	9	Crawl Space - Basement Storage	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315PC	Nurse's Office Pipe Chase	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	2	PC213	Pipe Chase in Custodial Closet across from Classroom 202	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	

				Inspection Dates: 12/28/21 - 1/4/22								
				Inspector Name and Certificate Number: Charles Rhodes, 003542		Lead Safe Certification Assessment Report						
				Inspection Company: BATT A		James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	3	PC316	Pipe Chase in Custodial Closet across from Classroom 302	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	4	PC412	Pipe Chase in Custodial Closet across from Classroom 400	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC113A	Pipe Chase in Custodial Closet in Hallway across from the Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC118A	Pipe Chase in Fan Room in Hallway next to Boy's Restroom	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	W1	N/A	N/A	N/A	N/A	N/A	N/A

				Inspection Dates: 12/28/21 - 1/4/22									
				Inspector Name and Certificate Number: Charles Rhodes, 003542			Lead Safe Certification Assessment Report						
				Inspection Company: BATT A			James Rhoads Elementary School						
ULCS#	E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC100A	Pipe Chase in Girl's Restroom next to Classroom 100	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC117	Pipe Chase in Gym (near Boy's Restroom)	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	1	PC103	Pipe Chase in IMC	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	4	PC415	Pipe Chase in Men's Restroom across from Classroom 402	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	R	R1	Rooftop	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1410	1	3	315	Sampled HID 2602 from wall 2. AM Viva-EHS June 2021	Yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A	