

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	4	S44	Stairway to Roof Access on West Side	W2	Plaster	White	Efflorescence	6	Prior sampling data used	Positive
5560	1	4	S44	Stairway to Roof Access on West Side	Stringer/Baseboard	Concrete	Grey	Chipping	4	Prior sampling data used	Positive
5560	1	4	H410	Hallway Next to Rooftop Courtyard	Ceiling	Plaster	White	Flaking	50	Prior sampling data used	Positive
5560	1	4	Restroom	Boy's Rooftop Restroom	Ceiling	Plaster	White	Flaking	20	Prior sampling data used	Positive
5560	1	4	Restroom	Girl's Rooftop Restroom	Ceiling	Plaster	White	Flaking	20	Prior sampling data used	Positive
5560	1	4	S43	East Roof Access Stair	Ceiling	Plaster	White	Flaking	30	Prior sampling data used	Positive
5560	1	3	H39	Main 3rd Floor Hallway	Radiator	Metal	White	Chipping	2	Prior sampling data used	Positive
5560	1	3	301C	Computer Server Room in Classroom 301	W1	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	3	301C	Computer Server Room in Classroom 301	W2	Plaster	White	Flaking	6	Prior sampling data used	Positive
5560	1	3	301C	Computer Server Room in Classroom 301	W3	Plaster	White	Flaking	32	Prior sampling data used	Positive
5560	1	3	301C	Computer Server Room in Classroom 301	Ceiling	Plaster	White	Flaking	32	Prior sampling data used	Positive
5560	1	3	301A	Custodial Closet Next to Classroom 301	W2	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	3	301A	Custodial Closet Next to Classroom 301	W3	Plaster	White	Partially Inaccessible	N/A	N/A	Positive
5560	1	3	301A	Custodial Closet Next to Classroom 301	W4	Plaster	White	Partially Inaccessible	N/A	N/A	Positive
5560	1	3	303	Classroom 303	W2	Plaster	White	Chipping	1	Prior sampling data used	Positive
5560	1	3	303	Classroom 303	Radiator	Metal	White	Flaking	1	Prior sampling data used	Positive
5560	1	3	304	Classroom 304	W2	Plaster	White	Flaking	8	Prior sampling data used	Positive
5560	1	3	304	Classroom 304	W3	Plaster	White	Flaking	44	Prior sampling data used	Positive
5560	1	3	304A	Men's Staff Lounge next to Classroom 304	W2	Plaster	White	Flaking	2	Prior sampling data used	Positive
5560	1	3	S34	Stairwell Next to Classroom 305	Radiator	Metal	White	Flaking	1	Prior sampling data used	Positive
5560	1	3	306A	Girl's Restroom next to West Stair	Radiator	Metal	White	Chipping	3	Prior sampling data used	Positive
5560	1	3	306A	Girl's Restroom next to West Stair	Floor	Concrete	Grey	Chipping	4	0	Negative

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	3	306	Classroom 306	W3	Plaster	White	Efflorescence	4	Prior sampling data used	Positive
5560	1	3	307	Classroom 307	W1	Plaster	White	Chipping	2	N/A	Negative
5560	1	3	307	Classroom 307	W2	Plaster	White	Chipping	1	N/A	Negative
5560	1	2	H27	Main 2nd Floor Hallway	Ceiling	Plaster	White	Efflorescence	2	Prior sampling data used	Positive
5560	1	2	204A	Nurse's Office	W3	Plaster	White	Efflorescence	2	Prior sampling data used	Positive
5560	1	2	204	Classroom 204	W1	Plaster	White	Flaking	2	Prior sampling data used	Positive
5560	1	2	204	Classroom 204	W3	Plaster	White	Efflorescence	2	Prior sampling data used	Positive
5560	1	2	204	Classroom 204	Ceiling	Plaster	White	Moisture Damage	1	Prior sampling data used	Positive
5560	1	2	203	Classroom 203	W1	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	203	Classroom 203	W3	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	202	Classroom 202	W1	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	202	Classroom 202	W3	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	201	Classroom 201	W1	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	201	Classroom 201	Radiator	Metal	White	Chipping	1	Prior sampling data used	Positive
5560	1	2	201	Classroom 201	W4	Plaster	White	Chipping	1	Prior sampling data used	Positive
5560	1	2	201A	Book Closet Next to Staff Lounge	W2	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	2	201A	Book Closet Next to Staff Lounge	W3	Plaster	White	Flaking	8	Prior sampling data used	Positive
5560	1	2	201A	Book Closet Next to Staff Lounge	W4	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	2	201B	Book Closet next to Stairs	W2	Plaster	White	Flaking	10	Prior sampling data used	Positive
5560	1	2	201B	Book Closet next to Stairs	W3	Plaster	White	Flaking	20	Prior sampling data used	Positive
5560	1	2	201B	Book Closet next to Stairs	W4	Plaster	White	Flaking	16	Prior sampling data used	Positive
5560	1	2	201B	Book Closet next to Stairs	Ceiling	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	2	205C	2nd Floor Girls' Restroom	W2	Plaster	White	Efflorescence	3	Prior sampling data used	Positive

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	2	205	Classroom 205	W3	Plaster	White	Efflorescence	4	Prior sampling data used	Positive
5560	1	2	205	Classroom 205	Window Sill	Wood	N/A	Moisture Damage	12	Prior sampling data used	Positive
5560	1	2	205	Classroom 205	Window Frame	Wood	N/A	Moisture Damage	16	Prior sampling data used	Positive
5560	1	2	207	Classroom 207	W1	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	2	207	Classroom 207	W4	Plaster	Blue	Chipping	1	Prior sampling data used	Positive
5560	1	2	201C	2nd Floor Boys' Restroom	W3	Plaster	White	Alligatoring	3	Prior sampling data used	Positive
5560	1	2	201C	2nd Floor Boys' Restroom	Pipe Chase Door	Wood	Brown	Chipping	4	N/A	N/A
5560	1	1	100A	Gym Office	W3	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	1	100B	Gym Storage Closet	W2	Plaster	White	Flaking	18	Prior sampling data used	Positive
5560	1	1	S12	Right Side Gym Stairwell to Basement	W2	Plaster	White	Flaking	2	Prior sampling data used	Positive
5560	1	1	S12	Right Side Gym Stairwell to Basement	Ceiling	Plaster	White	Flaking	4	Prior sampling data used	Positive
5560	1	1	S12	Right Side Gym Stairwell to Basement	Handrail	Metal	Black	Chipping	1	Prior sampling data used	Positive
5560	1	1	S12	Right Side Gym Stairwell to Basement	Stair Risers	Concrete	Grey	Chipping	6	Prior sampling data used	Positive
5560	1	1	S11	Left Side Gym Stairwell to Basement	Stair Risers	Concrete	Grey	Chipping	6	Prior sampling data used	Positive
5560	1	1	S13	Stairwell across from Stairwell S18	Stair Risers	Concrete	Grey	Chipping	20	Prior sampling data used	Positive
5560	1	1	S13	Stairwell across from Stairwell S18	Newel Post	Metal	Grey	Friction	1	Prior sampling data used	Positive
5560	1	1	S13	Stairwell across from Stairwell S18	Door Frame	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	S13	Stairwell across from Stairwell S18	Door	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	S13	Stairwell across from Stairwell S18	Push bar	Metal	Grey	Friction	2	N/A	N/A
5560	1	1	S13	Stairwell across from Stairwell S18	Handrail	Metal	Grey	Friction	2	N/A	N/A
5560	1	1	S18	Stairs adjacent Classroom 101	W1	Plaster	White	Chipping	3	Prior sampling data used	Positive
5560	1	1	S18	Stairs adjacent Classroom 101	Door Frame	Metal	Brown	Chipping	4	N/A	N/A
5560	1	1	S18	Stairs adjacent Classroom 101	Door	Metal	Brown	Chipping	4	N/A	N/A
5560	1	1	S18	Stairs adjacent Classroom 101	Push bar	Metal	Grey	Friction	4	N/A	N/A
5560	1	1	101	Classroom 101	W1	Plaster	White	Chipping	1	Prior sampling data used	Positive

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	1	102	Classroom 102	W1	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	1	103	Classroom 103	W1	Plaster	White	Flaking	3	Prior sampling data used	Positive
5560	1	1	103	Classroom 103	Coat Rack	Wood	White	Chipping	3	N/A	N/A
5560	1	1	103	Classroom 103	W3	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	1	H14	1st Floor Main Hallway	Door Frame	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	H14	1st Floor Main Hallway	Door	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	H14	1st Floor Main Hallway	Push bar	Metal	Grey	Chipping	2	N/A	N/A
5560	1	1	H14	1st Floor Main Hallway	Ceiling	Plaster	White	Flaking	2	Prior sampling data used	Positive
5560	1	1	S19	Visitor Entrance Stairwell	Door Frame	Metal	Blue	Chipping	3	N/A	N/A
5560	1	1	S19	Visitor Entrance Stairwell	Door	Metal	Blue	Chipping	4	N/A	N/A
5560	1	1	S19	Visitor Entrance Stairwell	Door Frame	Metal	Blue	Chipping	1	N/A	N/A
5560	1	1	S19	Visitor Entrance Stairwell	Door	Metal	Blue	Chipping	1	N/A	N/A
5560	1	1	S14	West Stairwell across from Main Office	Stair Soffit	Plaster	White	Alligating	4	Prior sampling data used	Positive
5560	1	1	S14	West Stairwell across from Main Office	Newel Post	Metal	Grey	Friction	1	Prior sampling data used	Positive
5560	1	1	S14	West Stairwell across from Main Office	Stair Risers	Concrete	Grey	Chipping	10	Prior sampling data used	Positive
5560	1	1	S14	West Stairwell across from Main Office	Handrail	Metal	Grey	Friction	10	Prior sampling data used	Positive
5560	1	1	104	Counselor's Suite Lobby	W2	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	1	100	Gymnasium	Door Frame	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	100	Gymnasium	Door	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	100	Gymnasium	Door Frame	Metal	Grey	Chipping	2	N/A	N/A
5560	1	1	100	Gymnasium	Door Frame	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	100	Gymnasium	Door	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	100	Gymnasium	Baseboard	Concrete	Brown	Chipping	5	N/A	N/A
5560	1	1	107	Auditorium	W1	Plaster	White	Chipping	4	Prior sampling data used	Positive
5560	1	1	107	Auditorium	W3	Plaster	White	Flaking	72	Prior sampling data used	Positive
5560	1	1	107	Auditorium	W4	Plaster	White	Flaking	24	Prior sampling data used	Positive
5560	1	1	107	Auditorium	Ceiling	Plaster	White	Flaking	24	Prior sampling data used	Positive
		1	107	Auditorium	Curtains	Fabric	N/A	Debris	N/A	Prior sampling data used	N/A

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	1	107	Auditorium	Door Frame	Metal	Brown	Chipping	3	N/A	N/A
5560	1	1	107	Auditorium	Door	Metal	Brown	Chipping	2	N/A	N/A
5560	1	1	107	Auditorium	Push Bar	Metal	Grey	Friction	2	N/A	N/A
5560	1	1	108	Stage	Ceiling	Plaster	White	Flaking	20	Prior sampling data used	Positive
5560	1	B	1	Cafeteria	W4	Concrete	White	Flaking	24	N/A	N/A
5560	1	B	1	Cafeteria	Ceiling	Concrete	White	Flaking	30	Prior sampling data used	Positive
5560	1	B	5	Kitchen	Ceiling	Concrete	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	S3	Stairs next to Cafeteria	Stair Risers	Concrete	Grey	Chipping	30	Prior sampling data used	Positive
5560	1	B	S2	Stairwell next to Cafeteria	Stair Risers	Concrete	Grey	Chipping	30	Prior sampling data used	Positive
5560	1	B	S1	Stairwell near Cafeteria next to East side Windows	Stair Risers	Concrete	Grey	Chipping	30	Prior sampling data used	Positive
5560	1	B	1C	Staff Restrooms next to Cafeteria in Hallway	Ceiling	Plaster	Brown	Flaking	8	Prior sampling data used	Positive
5560	1	B	2A	Boy's Restroom next to Cafeteria	Ceiling	Plaster	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	2A	Boy's Restroom next to Cafeteria	Floor	Concrete	Grey	Chipping	2	N/A	N/A
5560	1	B	4	Basement Girls' Restroom	W3	Plaster	Tan	Flaking	3	Prior sampling data used	Positive
5560	1	B	4	Basement Girls' Restroom	W4	Plaster	Tan	Flaking	12	Prior sampling data used	Positive
5560	1	B	4	Basement Girls' Restroom	Floor	Concrete	Grey	Chipping	4	N/A	N/A
5560	1	B	10	Basement Storage to Left of Building Engineer's Office	W1	Concrete	Green	Efflorescence	10	Prior sampling data used	Positive
5560	1	B	10	Basement Storage to Left of Building Engineer's Office	W2	Concrete	Green	Efflorescence	10	Prior sampling data used	Positive
5560	1	B	10	Basement Storage to Left of Building Engineer's Office	W3	Concrete	Green	Efflorescence	10	Prior sampling data used	Positive
5560	1	B	10	Basement Storage to Left of Building Engineer's Office	W4	Concrete	Green	Efflorescence	20	Prior sampling data used	Positive
5560	1	B	1A	Storage next to Cafeteria east Stairwell	Ceiling	Plaster	Brown	Flaking	8	Prior sampling data used	Positive
5560	1	2	209	Laundry Room to Left of Men's Restroom above Gym	W2	Plaster	White	Flaking	18	Prior sampling data used	Positive
5560	1	2	210	Gym Office	W3	Plaster	White	Chipping	2	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W1	Brick	White	Flaking	200	Prior sampling data used	Positive

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	B	3	Boiler Room	W1	Brick	Blue	Flaking	200	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W1	Concrete	Blue	Flaking	100	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W2	Brick	White	Flaking	200	N/A	N/A
5560	1	B	3	Boiler Room	W2	Brick	Blue	Flaking	200	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W2	Concrete	Blue	Flaking	100	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W3	Brick	White	Flaking	200	N/A	N/A
5560	1	B	3	Boiler Room	W3	Brick	Blue	Flaking	200	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W3	Concrete	Blue	Flaking	100	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W4	Brick	White	Flaking	200	N/A	N/A
5560	1	B	3	Boiler Room	W4	Brick	Blue	Flaking	200	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	W4	Concrete	Blue	Flaking	100	Prior sampling data used	Positive
5560	1	B	3	Boiler Room	Ceiling	Concrete	White	Flaking	100	N/A	N/A
5560	1	B	3	Boiler Room	Floor	Concrete	Red	Friction	20	N/A	N/A
5560	1	B	3	Boiler Room	Hand rails	Metal	Gray	Friction	10	N/A	Negative
5560	1	B	3	Boiler Room	Columns	Concrete	White	Friction	5	N/A	Negative
5560	1	B	3	Boiler Room	Columns	Concrete	Blue	Friction	5	N/A	Negative
5560	1	B	003A	Staff Restroom next to Boiler Room	W1	Brick	Blue	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W1	Brick	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W2	Brick	Blue	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W2	Brick	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W3	Brick	Blue	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W3	Concrete	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W4	Brick	Blue	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	W4	Brick	White	Flaking	5	Prior sampling data used	Positive
5560	1	B	003A	Staff Restroom next to Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
5560	1	B	003A	Staff Restroom next to Boiler Room	Floor	Concrete	Gray	Friction	10	N/A	Negative

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	W1	Brick	Blue	Chipping	5	Prior sampling data used	Positive
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	W2	Brick	Blue	Chipping	5	Prior sampling data used	Positive
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	W3	Brick	Blue	Flaking	5	Prior sampling data used	Positive
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	W4	Brick	Blue	Chipping	5	Prior sampling data used	Positive
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	Ceiling	Concrete	White	None	0	N/A	N/A
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	Floor	Concrete	Red	Friction	10	N/A	Negative
5560	1	B	S7	Stairwell at Basement Restroom in Boiler Room	Hand rails	Metal	Gray	Friction	10	N/A	Negative
5560	1	B	6	Water Pump Room	W1	Brick	White	Chipping	20	Prior sampling data used	Positive
5560	1	B	6	Water Pump Room	W1	Brick	Gray	Chipping	20	N/A	Negative
5560	1	B	6	Water Pump Room	W2	Brick	White	Chipping	20	Prior sampling data used	Positive
5560	1	B	6	Water Pump Room	W2	Brick	Gray	Chipping	20	N/A	Negative
5560	1	B	6	Water Pump Room	W3	Brick	White	Chipping	20	Prior sampling data used	Positive
5560	1	B	6	Water Pump Room	W3	Brick	Gray	Chipping	20	N/A	Negative
5560	1	B	6	Water Pump Room	W4	Brick	White	Chipping	20	Prior sampling data used	Positive
5560	1	B	6	Water Pump Room	W4	Brick	Gray	Chipping	20	N/A	Negative
5560	1	B	6	Water Pump Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
5560	1	B	6	Water Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
5560	1	B	008A	Fan Room next to Sewage Pump Room	W1	Brick	White	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W1	Brick	Blue	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W2	Brick	White	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W2	Brick	Blue	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W3	Brick	White	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5560	1	B	008A	Fan Room next to Sewage Pump Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
5560	1	B	008A	Fan Room next to Sewage Pump Room	W3	Brick	Blue	Flaking	20	Prior sampling data used	Positive

ULCS #	Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
5560	1	B	008A	Fan Room next to Sewage Pump Room	W4	Brick	White	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	W4	Brick	Blue	Flaking	20	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	Ceiling	Concrete	White	Flaking	30	Prior sampling data used	Positive
5560	1	B	008A	Fan Room next to Sewage Pump Room	Floor	Concrete	Red	None	0	N/A	N/A
5560	1	B	008A	Fan Room next to Sewage Pump Room	Hand rails	Metal	Silver	Friction	10	N/A	Negative
5560	1	B	008A	Fan Room next to Sewage Pump Room	Fan Unit Interior	Metal	Grey	Flaking	150	N/A	N/A
5560	1	B	008B	Sewage Injector Pump Room	W1	Brick	White	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W1	Brick	Blue	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W2	Brick	White	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W2	Brick	Blue	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W3	Brick	White	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W3	Brick	Blue	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W4	Concrete	White	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	W4	Concrete	Blue	Flaking	10	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	Ceiling	Concrete	White	Flaking	30	Prior sampling data used	Positive
5560	1	B	008B	Sewage Injector Pump Room	Floor	Concrete	Gray	None	0	N/A	N/A
5560	1	B	9A	Staff Restroom in Building Engineer's Office	W1	Plaster	Blue	Chipping	10	Prior sampling data used	Positive
5560	1	B	9A	Staff Restroom in Building Engineer's Office	W2	Plaster	Blue	Chipping	10	Prior sampling data used	Positive
5560	1	B	9A	Staff Restroom in Building Engineer's Office	W3	Plaster	Blue	Chipping	10	Prior sampling data used	Positive
5560	1	B	9A	Staff Restroom in Building Engineer's Office	W4	Plaster	Blue	Chipping	10	Prior sampling data used	Positive
									3868		
5560	1	B	9A	Staff Restroom in Building Engineer's Office	Ceiling	Concrete	White	Friction	10	N/A	Negative
5560	1	B	9A	Staff Restroom in Building Engineer's Office	Floor	Concrete	Gray	None	0	N/A	N/A

7746