

			School District of Philadelphia								
			Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
			Inspection Company: Vertex			Sullivan Elementary School					
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	300	300 : Classroom 300	yes	W1	Plaster	Green	Chipping/Staple Holes	10	31.1	Positive
1	3	300	300 : Classroom 300	yes	Door Frame	Wood	Varnish	Friction	10	0.11	Negative
1	3	300	300 : Classroom 300	yes	W2	Plaster	Green	Chipping/Staple Holes	20	17.1	Positive
1	3	300	300 : Classroom 300	yes	Pipe	Metal	Green	Chipping	1	25	Positive
1	3	300	300 : Classroom 300	yes	Chalkboard Frame/Trough	Wood	Varnish	Friction	10	0.06	Negative
1	3	300	300 : Classroom 300	yes	W3	Plaster	Green	Chipping/Flaking/Damage	14	21.8	Positive
1	3	300	300 : Classroom 300	yes	Window Sill & Frame	Wood	Varnish	Friction	10	0.1	Negative
1	3	300	300 : Classroom 300	yes	W4	Plaster	Green	Chipping/Flaking/Staple Holes	10	16.9	Positive
1	3	300	300 : Classroom 300	yes	Door	Wood	Varnish	Friction	4	0.08	Negative
1	3	300	300 : Classroom 300	yes	Floor	Wood	Varnish	Chipping	50	0	Negative
1	3	300	300 : Classroom 300	yes	Baseboard	Wood	Varnish	Friction	10	0.1	Negative
1	3	300	300 : Classroom 300	yes	Ceiling	Plaster	White	Flaking	3	32.1	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	W1	Plaster	Green	Partially Inaccessible		13	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	W2	Plaster	Green	Flaking	1	16.1	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	Window Sill & Frame	Wood	Varnish	Friction	2	0.15	Negative
1	3	300AA	300AA : Classroom 300 Coat Room	yes	Pipe	Metal	Green	Chipping	1	15	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	W3	Plaster	Green	Partially Inaccessible		13.1	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	W4	Plaster	Green	Partially Inaccessible		13.1	Positive
1	3	300AA	300AA : Classroom 300 Coat Room	yes	Floor	Wood	Varnish	Partially Inaccessible	N/A	0	Negative
1	3	300AA	300AA : Classroom 300 Coat Room	yes	Baseboard	Wood	Varnish	Partially Inaccessible	N/A	0.13	Negative
1	3	300AA	300AA : Classroom 300 Coat Room	yes	Ceiling	Plaster	White	Flaking	1	13.5	Positive
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300PS	300PS : Classroom 300 Coat Room Pipe Shaft	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	300C	300C : Classroom 300 Storage Closet	yes	W1	Plaster	Tan	Partially Inaccessible	N/A	0	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	W2	Plaster	Tan	Partially Inaccessible	N/A	0.03	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	W3	Plaster	Tan	Partially Inaccessible	N/A	0.03	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.09	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	W4	Plaster	Tan	Partially Inaccessible	N/A	0.03	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	Floor	Wood	Varnish	Partially Inaccessible	N/A	0	Negative
1	3	300C	300C : Classroom 300 Storage Closet	yes	Ceiling	Plaster	Tan	Partially Inaccessible	N/A	0.07	Negative
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	W1	Plaster	Tan/Greem/White	Flaking	1	19.3	Positive
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	Door and Frame	Wood	Varnish	Friction	4	0.08	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	W2	Plaster	Tan/Greem/White	Holes/Flaking	1	19.3	Positive
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	W3	Plaster	Tan/Greem/White	None	0	N/A	N/A
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	W4	Plaster	Tan/Greem/White	None	0	N/A	N/A
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300A	300A : Staff Lounge adjacent to Classroom 301	yes	Ceiling	Plaster	White	Hole	1	24	Positive
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	W3	Plaster	Green	Chipping	2	14.7	Positive
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	Radiator	Metal	Grey	Chipping	4	0.6	Negative
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	300B	300B : Staff Lounge adjacent to Classroom 301 Restroom	yes	Ceiling	Plaster	Green	None	0	N/A	N/A
1	3	301	301 : Classroom 301	yes	W1	Plaster	Green	Chipping/Cracking	10	22.4	Positive
1	3	301	301 : Classroom 301	yes	Door and Frame	Wood	Varnish	Friction	10	0.17	Negative
1	3	301	301 : Classroom 301	yes	W2	Plaster	Green	Chipping	30	12.3	Positive
1	3	301	301 : Classroom 301	yes	Chalkboard and Frame	Wood	Varnish	Friction	10	0.09	Negative
1	3	301	301 : Classroom 301	yes	W3	Plaster	Green	Efflorescence/Flaking/Chipping	15	22.4	Positive
1	3	301	301 : Classroom 301	yes	Radiator Cover	Metal	Green	Chipping	4	0	Negative
1	3	301	301 : Classroom 301	yes	Window Sill and Frame	Wood	Varnish	Friction	10	0.11	Negative
1	3	301	301 : Classroom 301	yes	W4	Plaster	Green	Chipping	10	24.3	Positive
1	3	301	301 : Classroom 301	yes	Floor	Wood	Varnish	Chipping	50	0	Negative
1	3	301	301 : Classroom 301	yes	Baseboard	Wood	Varnish	Friction	20	0.08	Negative
1	3	301	301 : Classroom 301	yes	Ceiling	Plaster	White	Flaking/Water Damage	2	26.3	Positive
1	3	301A	301A : Classroom 301 Coat Room	yes	W1	Plaster	Green	Chipping/Broken Plaster	20	12.3	Positive
1	3	301A	301A : Classroom 301 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	301A	301A : Classroom 301 Coat Room	yes	W3	Plaster	Green	Chipping/Broken Plaster	20	9.9	Positive
1	3	301A	301A : Classroom 301 Coat Room	yes	W4	Plaster	Green	Partially Inaccessible		11.4	Positive
1	3	301A	301A : Classroom 301 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	301A	301A : Classroom 301 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	300B	300B : Classroom 301 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access

			School District of Philadelphia									
			Name of Inspector: Paul Davis				Lead Safe Certification Assessment Report					
			Inspection Company: Vertex				Sullivan Elementary School					
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	3	300B	300B : Classroom 301 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	300B	300B : Classroom 301 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	300B	300B : Classroom 301 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	300B	300B : Classroom 301 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	300B	300B : Classroom 301 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	3	302	302 : Classroom 302	yes	W1	Plaster	Green	Cracking/Chipping	6	22.9	Positive	
1	3	302	302 : Classroom 302	yes	W2	Plaster	Green	Chipping/Flaking	20	17.7	Positive	
1	3	302	302 : Classroom 302	yes	W3	Plaster	Green	Chipping	5	19.4	Positive	
1	3	302	302 : Classroom 302	yes	W4	Plaster	Green	Chipping/Flaking	15	17.2	Positive	
1	3	302	302 : Classroom 302	yes	Floor	Wood	Varnish	Scrapes/Friction	40	0.01	Negative	
1	3	302	302 : Classroom 302	yes	Ceiling	Plaster	White	None	0	N/A	N/A	
1	3	302A	302A : Classroom 302 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A	
1	3	302A	302A : Classroom 302 Coat Room	yes	W2	Plaster	Green	Chipping	6	11.6	Positive	
1	3	302A	302A : Classroom 302 Coat Room	yes	Pipe	Metal	Green	Chipping	2	0.22	Negative	
1	3	302A	302A : Classroom 302 Coat Room	yes	W3	Plaster	Green	Partially Inaccessible		13	Positive	
1	3	302A	302A : Classroom 302 Coat Room	yes	W4	Plaster	Green	Chipping/Flaking/Hole	12	12.8	Positive	
1	3	302A	302A : Classroom 302 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A	
1	3	302A	302A : Classroom 302 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A	
1	3	302B	302B : Classroom 302 Storage Closet	yes	W1	Plaster	Tan	Partially Inaccessible		6.1	Positive	
1	3	302B	302B : Classroom 302 Storage Closet	yes	W2	Plaster	Tan	Partially Inaccessible		7.2	Positive	
1	3	302B	302B : Classroom 302 Storage Closet	yes	W3	Plaster	Tan	Partially Inaccessible		9.1	Positive	
1	3	302B	302B : Classroom 302 Storage Closet	yes	W4	Plaster	Tan	Partially Inaccessible		6.7	Positive	
1	3	302B	302B : Classroom 302 Storage Closet	yes	Floor	Wood	Varnish	Partially Inaccessible	N/A	0.01	Negative	
1	3	302B	302B : Classroom 302 Storage Closet	yes	Ceiling	Plaster	Tan	Partially Inaccessible		5.2	Positive	
1	3	303	303 : Classroom 303	yes	W1	Plaster	Green/White	Chipping/Flaking/Efflorescence	5	29.6	Positive	
1	3	303	303 : Classroom 303	yes	Door and Frame	Wood	Varnish	Chipping	10	0.04	Negative	
1	3	303	303 : Classroom 303	yes	W2	Plaster	Green/White	Chipping/Flaking/Efflorescence	7	18.2	Positive	
1	3	303	303 : Classroom 303	yes	Chalkboard Trough and Frame	Wood	Varnish	Chipping	20	0.08	Negative	
1	3	303	303 : Classroom 303	yes	W3	Plaster	Green	Cracking/Chipping	4	32.1	Positive	
1	3	303	303 : Classroom 303	yes	Window Sill and Frame	Wood	Varnish	Chipping	10	0.23	Negative	
1	3	303	303 : Classroom 303	yes	W4	Plaster	Green	Chipping/Flaking	2	33.4	Positive	
1	3	303	303 : Classroom 303	yes	Floor	Wood	Varnish	Friction	40	0	Negative	
1	3	303	303 : Classroom 303	yes	Baseboard	Wood	Varnish	Chipping	15	0.22	Negative	
1	3	303	303 : Classroom 303	yes	Ceiling	Plaster	White	Efflorescence/Cracking/Flaking	3	32.3	Positive	
1	3	303A	303A : Classroom 303 Coat Closet	yes	W1	Plaster	Green	Spalling/Flaking/Chipping	6	11	Positive	
1	3	303A	303A : Classroom 303 Coat Closet	yes	W2	Plaster	Green	Partially Inaccessible		15	Positive	

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	303A	303A : Classroom 303 Coat Closet	yes	W3	Plaster	Green	Partially Inaccessible		9.1	Positive
1	3	303A	303A : Classroom 303 Coat Closet	yes	W4	Plaster	Green	Partially Inaccessible		17.6	Positive
1	3	303A	303A : Classroom 303 Coat Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	303A	303A : Classroom 303 Coat Closet	yes	Ceiling	Plaster	Green	None	0	N/A	N/A
1	3	303C	303C : Classroom 303 Storage Closet	yes	W1	Plaster	Tan	Partially Inaccessible		3.7	Positive
1	3	303C	303C : Classroom 303 Storage Closet	yes	W2	Plaster	Tan	Partially Inaccessible		4.4	Positive
1	3	303C	303C : Classroom 303 Storage Closet	yes	W3	Plaster	Tan	Partially Inaccessible		7.2	Positive
1	3	303C	303C : Classroom 303 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.05	Negative
1	3	303C	303C : Classroom 303 Storage Closet	yes	W4	Plaster	Tan	Partially Inaccessible		5.8	Positive
1	3	303C	303C : Classroom 303 Storage Closet	yes	Floor	Wood	Varnish	Partially Inaccessible	N/A	0	Negative
1	3	303C	303C : Classroom 303 Storage Closet	yes	Ceiling	Plaster	Tan	Partially Inaccessible		11.4	Positive
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	W2	Plaster	Purple	Chipping/Flaking/Cracking	5	0.02	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	W4	Plaster	Purple	Chipping/Flaking	6	0.31	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Covebase	Concrete	Brown	Chipping	2	0.09	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Tread	Concrete	Grey	Chipping	40	0.34	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Riser	Concrete	Grey	Chipping	20	0.39	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Stringer	Concrete	Grey	Chipping	12	0.33	Negative
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Spindles	Metal	Grey	Chipping	6	7.24	Positive
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Newel Posts	Metal	Grey	Chipping	8	5.85	Positive
1	3	S-2	S-2 : Stairwell adjacent to Classroom 303	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	Doors	Metal	Brown	Chipping	20	0	Negative
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	Door Frames	Metal	Brown	Chipping	6	0	Negative
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	W2	Plaster	Blue	Chipping	5	25.6	Positive
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	W4	Plaster	Blue	Chipping/Flaking	2	26.9	Positive
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	Covebase	Concrete	Brown	Chipping	6	0.05	Negative
1	3	H33	H33 : Hallway from Classrooms 301 to 303	yes	Ceiling	Plaster	White	Chipping/Flaking	10	25.4	Positive
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	W1	Plaster	Yellow	Partially Inaccessible	N/A	0.18	Negative
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	W2	Plaster	Yellow	Partially Inaccessible	N/A	0.16	Negative
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	W3	Plaster	Yellow	Partially Inaccessible	N/A	0.13	Negative
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.09	Negative
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	W4	Plaster	Yellow	Partially Inaccessible	N/A	0.25	Negative

			<p style="text-align: center;">School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School</p>								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3		Storage Closet between Classroom 303 and Girl's Restroom	yes	Ceiling	Plaster	Yellow	Partially Inaccessible	N/A	0.2	Negative
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	W1	Plaster	Tan	Cracking/Flaking	3	11.1	Positive
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303V	Vestibule for Girl's Restroom adjacent to Classroom 304	yes	Ceiling	Plaster	Tan	Chipping/Flaking	2	19.4	Positive
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	W2	Plaster	Tan	Cracking	5	14.3	Positive
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	Pipe	Metal	Tan	Chipping	3	0.5	Negative
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	W3	Plaster	Tan	Flaking	1	10.8	Positive
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	W4	Plaster	Tan	Flaking/Chipping	2	17.1	Positive
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	Floor	Ceramic Tiles	N/A	N/A	N/A	N/A	N/A
1	3	303B	303B : Girl's Restroom adjacent to Classroom 304	yes	Ceiling	Plaster	Tan	Chipping/Flaking	35	17.8	Positive
1	3	304	304 : Classroom 304	yes	W1	Plaster	Green	Chipping/Staple Holes	3	27.5	Positive
1	3	304	304 : Classroom 304	yes	W2	Plaster	Green	Chipping/Staple Holes	4	28.2	Positive
1	3	304	304 : Classroom 304	yes	Divider Wall	Wood	Varnish	Friction	2	0.05	Negative
1	3	304	304 : Classroom 304	yes	W3	Plaster	Green	Hole	1	18.7	Positive
1	3	304	304 : Classroom 304	yes	Radiator Cover	Metal	Tan	Chipping	5	0	Negative
1	3	304	304 : Classroom 304	yes	W3	Metal Pipe	Green	Flaking/Chipping	5	23.6	Positive
1	3	304	304 : Classroom 304	yes	W4	Plaster	Green	Chipping/Flaking	4	15.9	Positive
1	3	304	304 : Classroom 304	yes	Floor	Wood	Varnish	Friction	40	0.01	Negative
1	3	304	304 : Classroom 304	yes	Ceiling	Plaster	White	Flaking	1	26.5	Positive
1	3	304A	304A : Classroom 304 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	304A	304A : Classroom 304 Coat Room	yes	W2	Plaster	Green	Chipping/Flaking	4	14.5	Positive
1	3	304A	304A : Classroom 304 Coat Room	yes	W3	Plaster	Green	Partially Inaccessible		13.2	Positive
1	3	304A	304A : Classroom 304 Coat Room	yes	W4	Plaster	Green	Partially Inaccessible		15	Positive
1	3	304A	304A : Classroom 304 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	304A	304A : Classroom 304 Coat Room	yes	Ceiling	Plaster	White	Flaking	1	15.7	Positive
1	3	304B	304B : Classroom 304 Storage Closet	yes	W1	Plaster	White	Cracking	20	0	Negative
1	3	304B	304B : Classroom 304 Storage Closet	yes	W2	Plaster	White	Cracking	50	0	Negative
1	3	304B	304B : Classroom 304 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible/Cracking	20	0	Negative
1	3	304B	304B : Classroom 304 Storage Closet	yes	Shelving	Wood	Varnish	Friction	20	0.05	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	304B	304B : Classroom 304 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible/Cracking	20	0	Negative
1	3	304B	304B : Classroom 304 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	304B	304B : Classroom 304 Storage Closet	yes	Ceiling	Plaster	White	Cracking	25	0	Negative
1	3	305	305 : Classroom 305	yes	W1	Plaster	Green	Chipping/Flaking	4	28.4	Positive
1	3	305	305 : Classroom 305	yes	W2	Plaster	Green	Chipping/Flaking	1	27.3	Positive
1	3	305	305 : Classroom 305	yes	W3	Plaster	Green	Chipping/Flaking/Damage	3	15.4	Positive
1	3	305	305 : Classroom 305	yes	Pipe	Metal	Green	Chipping/Flaking	3	24.1	Positive
1	3	305	305 : Classroom 305	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	305	305 : Classroom 305	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	305	305 : Classroom 305	yes	Ceiling	Plaster	White	Cracking	10	25.1	Positive
1	3	305A	305A : Classroom 305 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	305A	305A : Classroom 305 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	305A	305A : Classroom 305 Coat Room	yes	W3	Plaster	Green	None	0	N/A	N/A
1	3	305A	305A : Classroom 305 Coat Room	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	305A	305A : Classroom 305 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	305A	305A : Classroom 305 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	305B	305B : Classroom 305 Storage Closet	yes	W1	Plaster	Tan	Cracking	2	5.4	Positive
1	3	305B	305B : Classroom 305 Storage Closet	yes	W2	Plaster	Tan	Cracking	20	4.7	Positive
1	3	305B	305B : Classroom 305 Storage Closet	yes	W3	Plaster	Tan	Partially Inaccessible/Cracking	20	3.5	Positive
1	3	305B	305B : Classroom 305 Storage Closet	yes	W4	Plaster	Tan	Partially Inaccessible/Cracking	20	4.4	Positive
1	3	305B	305B : Classroom 305 Storage Closet	yes	Shelving	Wood	Varnish	Friction	20	0.09	Negative
1	3	305B	305B : Classroom 305 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	305B	305B : Classroom 305 Storage Closet	yes	Ceiling	Plaster	Tan	Cracking/Damage	2	3.4	Positive
1	3	306	306 : Classroom 306	yes	W1	Plaster	Green	Chipping/Flaking/Staple Holes	20	25.7	Positive
1	3	306	306 : Classroom 306	yes	Chalkboard Troughs and Frames	Wood	Varnish	Friction	10	0.1	Negative
1	3	306	306 : Classroom 306	yes	Doors and Frames	Wood	Varnish	Friction	10	0.11	Negative
1	3	306	306 : Classroom 306	yes	W2	Plaster	Green	Chipping/Flaking	4	21.9	Positive
1	3	306	306 : Classroom 306	yes	W3	Plaster	Green	Staple Holes	12	21.4	Positive
1	3	306	306 : Classroom 306	yes	Window Sills and Frames	Wood	Varnish	Friction	10	0.1	Negative
1	3	306	306 : Classroom 306	yes	Radiator	Metal	Grey	Chipping	6	5.2	Positive
1	3	306	306 : Classroom 306	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	Divider Wall	Wood	Varnish	Staples	20	0.04	Negative
1	3	306	306 : Classroom 306	yes	Floor	Wood	Varnish	Friction	40	0.01	Negative
1	3	306	306 : Classroom 306	yes	Baseboard	Wood	Varnish	Friction	10	0.2	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	306	306 : Classroom 306	yes	Ceiling	Plaster	White	Efflorescence/Water Damage	6	25.9	Positive
1	3	306A	306A : Classroom 306 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	306A	306A : Classroom 306 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	306A	306A : Classroom 306 Coat Room	yes	W3	Plaster	Green	None	0	N/A	N/A
1	3	306A	306A : Classroom 306 Coat Room	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	306A	306A : Classroom 306 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	306A	306A : Classroom 306 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	306B	306B : Classroom 306 Storage Closet	yes	W1	Plaster	Tan	Partially Inaccessible/Flaking	2	7.8	Positive
1	3	306B	306B : Classroom 306 Storage Closet	yes	W2	Plaster	Tan	Partially Inaccessible/Flaking	4	6.7	Positive
1	3	306B	306B : Classroom 306 Storage Closet	yes	W3	Plaster	Tan	Partially Inaccessible		6.8	Positive
1	3	306B	306B : Classroom 306 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.07	Negative
1	3	306B	306B : Classroom 306 Storage Closet	yes	W4	Plaster	Tan	Partially Inaccessible		5	Positive
1	3	306B	306B : Classroom 306 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	306B	306B : Classroom 306 Storage Closet	yes	Ceiling	Plaster	Tan	Flaking	2	5.1	Positive
1	3	307	307 : Classroom 307	yes	W1	Plaster	Green	Staples/Chipping	14	29.4	Positive
1	3	307	307 : Classroom 307	yes	W2	Plaster	Green	Staples/Chipping	15	24.3	Positive
1	3	307	307 : Classroom 307	yes	W3	Plaster	Green	Staples/Chipping/Flaking	15	24.1	Positive
1	3	307	307 : Classroom 307	yes	Pipe	Metal	Green	Chipping	4	34.8	Positive
1	3	307	307 : Classroom 307	yes	W4	Plaster	Green	Staples/Chipping	4	19.5	Positive
1	3	307	307 : Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307	307 : Classroom 307	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	W3	Plaster	Green	None	0	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307A	307A : Classroom 307 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	Floor	N/A	N/A	None	0	N/A	N/A
1	3	307V	307V : Vestibule for Boy's Restroom adjacent to Classroom 307	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	W1	Plaster	White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	W2	Plaster	White	Chipping/Flaking	30	8.8	Positive
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	W3	Plaster	White	Chipping/Flaking	3	11.2	Positive
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	Radiator	Metal	Grey	Chipping/Flaking	6	4.1	Positive
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	W4	Plaster	White	Chipping/Flaking/Cracking	8	16.3	Positive
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	Access Door	Metal	Grey	Flaking	2	0	Negative
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	307B	307B : Boy's Restroom adjacent to Classroom 307	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	W1	Plaster	Tan	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	W2	Plaster	Tan	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	W3	Plaster	Tan	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	W4	Plaster	Tan	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	Floor	N/A	N/A	None	0	N/A	N/A
1	3	307C	307C : Boy's Restroom adjacent to Classroom 307 Service Closet	no	Ceiling	Plaster	Tan	Chipping/Hole	2	15.5	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	W1	Plaster	Green	Chipping/Flaking	10	4.51	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	W2	Plaster	Green	Chipping/Flaking	5	6.76	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	Radiator	Metal	Tan	Chipping	2	5.11	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	W3	Plaster	White	Partially Inaccessible		7.7	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.07	Negative
1	3	312	312 : Speech Room across from Classroom 307	yes	W4	Plaster	White	Partially Inaccessible		3.8	Positive
1	3	312	312 : Speech Room across from Classroom 307	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	312	312 : Speech Room across from Classroom 307	yes	Ceiling	Plaster	White	Efflorescence/Flaking	6	5.58	Positive
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	W1	Plaster	Tan	Flaking	2	2	Positive
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	W2	Plaster	Tan	N/A	N/A	N/A	N/A
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	W3	Plaster	Tan	Efflorescence/Flaking	12	21.5	Positive
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	Radiator	Metal	Tan	Chipping/Flaking	20	4.5	Positive
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	W4	Plaster	Tan	N/A	N/A	N/A	N/A
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	Cove base	Concrete	Brown	Chipping	5	0.08	Negative
1	3	H32	H32 : Hallway from Classrooms 304 to 307	yes	Ceiling	Plaster	White	Efflorescence/Flaking/Cracking	20	25	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	W1	Brick	White	Flaking	15	2.5	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Doors and Frames	Metal	Brown	Chipping	5	0	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	W2	Brick	White	Flaking	50	3.3	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	W3	Brick	White	Flaking	100	3.5	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	W4	Brick	White	Flaking	20	4.9	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Grate	Metal	Grey	Flaking	50	27.7	Positive

			<p style="text-align: center;">School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School</p>								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o r	S p a c e #	O n - S i t e R o o m N a m e	S t u d e n t / T e a c h e r O c c u p i e d (y e s / n o)	C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f D a m a g e	D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g / c m 2)	X R F (p o s i t i v e / n e g a t i v e)
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Covebase	Concrete	Brown	Chipping/Flaking	10	0.19	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Ceiling	Concrete	White	Flaking	25	0.02	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Riser	Metal	Brown	Friction	10	0.3	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Tread	Metal	Brown	Friction	10	0.27	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Stringer	Metal	Brown	Friction	10	0.4	Negative
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Window Frame	Metal	Brown	Chipping/Flaking	4	4.9	Positive
1	3	S-1	S-1 : Fire Tower across from Classroom 307	yes	Hand Rail	Metal	Brown	Friction	12	0.09	Negative
1	3	308	308 : Classroom 308	yes	W1	Plaster	Green	Chipping/Flaking	3	17.4	Positive
1	3	308	308 : Classroom 308	yes	W2	Plaster	Green	Chipping/Flaking	5	19.4	Positive
1	3	308	308 : Classroom 308	yes	W3	Plaster	Green	Chipping/Flaking	5	34.2	Positive
1	3	308	308 : Classroom 308	yes	Radiator	Metal	Grey	Chipping/Flaking	8	4.9	Positive
1	3	308	308 : Classroom 308	yes	W4	Plaster	Green	Chipping/Flaking	2	15.6	Positive
1	3	308	308 : Classroom 308	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	308A	308A : Classroom 308 Coat Room	yes	W1	Plaster	Green	Chipping/Flaking	12	10.1	Positive
1	3	308A	308A : Classroom 308 Coat Room	yes	W2	Plaster	Green	Partially Inaccessible		18.2	Positive
1	3	308A	308A : Classroom 308 Coat Room	yes	W3	Plaster	Green	Partially Inaccessible/Chipping/Flaking	5	13.7	Positive
1	3	308A	308A : Classroom 308 Coat Room	yes	W4	Plaster	Green	Partially Inaccessible		5.1	Positive
1	3	308A	308A : Classroom 308 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	308A	308A : Classroom 308 Coat Room	yes	Ceiling	Plaster	Green	None	0	N/A	N/A
1	3	308B	308B : Classroom 308 Storage Closet	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	308B	308B : Classroom 308 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible		3.3	Positive
1	3	308B	308B : Classroom 308 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible		3.9	Positive
1	3	308B	308B : Classroom 308 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible		3.6	Positive
1	3	308B	308B : Classroom 308 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	308B	308B : Classroom 308 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Door and Frames	Wood	Varnish	Friction	5	0.07	Negative
1	3	309	309 : Classroom 309	yes	W2	Plaster	Green	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	W3	Plaster	Green	Holes	1	33.3	Positive
1	3	309	309 : Classroom 309	yes	Window Sills and Frames	Wood	Varnish	Friction	5	0.08	Negative
1	3	309	309 : Classroom 309	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Chalkboard Troughs and Frames	Wood	Varnish	Friction	8	0.06	Negative
1	3	309	309 : Classroom 309	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Baseboard	Wood	Varnish	Friction	12	0.08	Negative
1	3	309	309 : Classroom 309	yes	Ceiling	Plaster	White	None	0	N/A	N/A

			School District of Philadelphia								
			Name of Inspector: Paul Davis						Lead Safe Certification Assessment Report		
			Inspection Company: Vertex						Sullivan Elementary School		
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	309A	309A : Classroom 309 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	309A	309A : Classroom 309 Coat Room	yes	W2	Plaster	Green	Partially Inaccessible		12.07	Positive
1	3	309A	309A : Classroom 309 Coat Room	yes	W3	Plaster	Green	Partially Inaccessible		10.54	Positive
1	3	309A	309A : Classroom 309 Coat Room	yes	W4	Plaster	Green	Partially Inaccessible		10.2	Positive
1	3	309A	309A : Classroom 309 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	309A	309A : Classroom 309 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	309B	309B : Classroom 309 Storage Closet	yes	W1	Plaster	Tan	Cracking	20	0.13	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	W2	Plaster	Tan	Cracking	40	0.15	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	W3	Plaster	Tan	Cracking	50	0.2	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	Shelving	Wood	Varnish	Friction	10	0.05	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	W4	Plaster	Tan	Cracking	40	0.13	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	Floor	Wood	Varnish	Friction	5	0.01	Negative
1	3	309B	309B : Classroom 309 Storage Closet	yes	Ceiling	Plaster	Tan	Flaking/Hole	1	0.19	Negative
1	3	310	310 : Classroom 310	yes	W1	Plaster	Green	Partially Inaccessible/Flaking	3	3.8	Positive
1	3	310	310 : Classroom 310	yes	W2	Plaster	Green	Chipping	2	15.8	Positive
1	3	310	310 : Classroom 310	yes	W3	Plaster	Green	Chipping/Flaking	4	22.5	Positive
1	3	310	310 : Classroom 310	yes	Radiator	Metal	Grey	Chipping/Flaking	8	6.3	Positive
1	3	310	310 : Classroom 310	yes	W4	Plaster	Green	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	Ceiling	Plaster	White	Efflorescence/Flaking/Hole	1	33.7	Positive
1	3	310A	310A : Classroom 310 Coat Room	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	310A	310A : Classroom 310 Coat Room	yes	W2	Plaster	Green	Partially Inaccessible		11.8	Positive
1	3	310A	310A : Classroom 310 Coat Room	yes	W3	Plaster	Green	None	0	N/A	N/A
1	3	310A	310A : Classroom 310 Coat Room	yes	W4	Plaster	Green	Cracking	1	11.1	Positive
1	3	310A	310A : Classroom 310 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	310A	310A : Classroom 310 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	310B	310B : Classroom 310 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310B	310B : Classroom 310 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310B	310B : Classroom 310 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310B	310B : Classroom 310 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310B	310B : Classroom 310 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310B	310B : Classroom 310 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	311	311 : Office 311	yes	W1	Plaster	Green	None	0	N/A	N/A
1	3	311	311 : Office 311	yes	W2	Plaster	Grey	Partially Inaccessible/Flaking	20	12.5	Positive
1	3	311	311 : Office 311	yes	Shelving	Wood	Varnish	Friction	20	0.06	Negative
1	3	311	311 : Office 311	yes	Pipe	Metal	Green	Chipping	1	16.3	Positive
1	3	311	311 : Office 311	yes	W3	Plaster	Green	Chipping/Flaking	2	11.3	Positive
1	3	311	311 : Office 311	yes	W4	Plaster	Green	Partially Inaccessible		10.3	Positive
1	3	311	311 : Office 311	yes	Floor	Wood	Varnish	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	311	311 : Office 311	yes	Ceiling	Plaster	White	Chipping/Flaking/Hole	3	14.3	Positive
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	W1	Metal Doors and Frame	Brown	Chipping	8	0	Negative
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	W2	Plaster	Blue and White	Cracking	1	28.3	Positive
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	W4	Plaster	Blue	Chipping/Flaking	1	26.5	Positive
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	Covebase	Concrete	Brown	Chipping	6	0.04	Negative
1	3	H31	H31 : Hallway from Classrooms 308 to 310	yes	Ceiling	Plaster	White	Flaking	1	27.5	Positive
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W1	Plaster	White	Partially Inaccessible	N/A	0.01	Negative
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W2	Plaster	White	Partially Inaccessible	N/A	0.01	Negative
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W3	Plaster	White	Partially Inaccessible	N/A	0.01	Negative
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W4	Plaster	White	Partially Inaccessible	N/A	0.01	Negative
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Ceiling	Plaster	White	Partially Inaccessible	N/A	0.01	Negative
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	W1	Plaster	Blue	Flaking	1	15.76	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	Pipe Outer Cover	Metal	Blue	Flaking	1	7.08	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	W2	Plaster	Blue	Chipping	4	14	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	W4	Plaster	Blue	Spalling	10	13.37	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	Spindles	Metal	Grey	Chipping	6	2.78	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	Newel Posts	Metal	Grey	Chipping	6	7.81	Positive
1	3	S-3	S-3 : Stairwell adjacent to Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	W2	Plaster	Yellow	Chipping/Flaking	3	23.7	Positive
1	2	214	214 : Classroom 214	yes	W3	Plaster	Yellow	Chipping	3	34.2	Positive
1	2	214	214 : Classroom 214	yes	W4	Plaster	Yellow	Chipping/Flaking	3	40.9	Positive
1	2	214	214 : Classroom 214	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	214 : Classroom 214	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	214A	214A : Classroom 214 Closet	yes	W1	Plaster	Yellow	Flaking	1	14.4	Positive
1	2	214A	214A : Classroom 214 Closet	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	214A : Classroom 214 Closet	yes	Radiator	Metal	Grey	Chipping/Flaking	4	4.8	Positive
1	2	214A	214A : Classroom 214 Closet	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	214A : Classroom 214 Closet	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	214A	214A : Classroom 214 Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	214A	214A : Classroom 214 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	214B	214B : Classroom 214 Closet Pipe Shaft	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	215B	215B : Office 215 Foyer	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Office 215 Foyer	yes	W2	Plaster	White	Alligatoring	6	14.78	Positive
1	2	215B	215B : Office 215 Foyer	yes	W3	Sheetrock	White	Chipping/Flaking	3	0.01	Negative
1	2	215B	215B : Office 215 Foyer	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Office 215 Foyer	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215B	215B : Office 215 Foyer	yes	Ceiling	Plaster	White	Alligatoring	40	14.53	Positive
1	2	215	215 : Office 215	yes	W1	Plaster	White	Chipping/Flaking	1	16.31	Positive
1	2	215	215 : Office 215	yes	W2	Plaster	White	Flaking/Chipping	4	12.54	Positive
1	2	215	215 : Office 215	yes	W3	Plaster	White	Efflorescence/Flaking	4	13.48	Positive
1	2	215	215 : Office 215	yes	W4	Plaster	White	Partially Inaccessible		13.55	Positive
1	2	215	215 : Office 215	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	215 : Office 215	yes	Duct Work	Metal	Grey & Blue	Chipping/Flaking	3	0.02	Negative
1	2	215	215 : Office 215	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	215A	215A : Staff Restroom	yes	W1	Plaster	Tan	Flaking	15	12.84	Positive
1	2	215A	215A : Staff Restroom	yes	W2	Plaster	Tan	Flaking Cracking	10	1.48	Positive
1	2	215A	215A : Staff Restroom	yes	W3	Plaster	Tan	Flaking	5	1.83	Positive
1	2	215A	215A : Staff Restroom	yes	Pipe	Metal	Tan	Flaking	1	0.04	Negative
1	2	215A	215A : Staff Restroom	yes	W4	Plaster	Tan	Flaking	15	3.04	Positive
1	2	215A	215A : Staff Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	215A : Staff Restroom	yes	Ceiling	Plaster	Tan	Flaking	4	10.91	Positive
1	2	216	216 : Nurse's Office	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Nurse's Office	yes	Door and Window Frame	Wood	White	Chipping	8	0.09	Negative
1	2	216	216 : Nurse's Office	yes	Door	Wood	White	Cracking	8	0.28	Negative
1	2	216	216 : Nurse's Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Nurse's Office	yes	Built-in Cabinet	Wood	White	Cracking	8	0.37	Negative
1	2	216	216 : Nurse's Office	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Nurse's Office	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Nurse's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	216	216 : Nurse's Office	yes	Baseboard	Wood	White	Chipping	20	0.13	Negative
1	2	216	216 : Nurse's Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	216A	216A : Nurse's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	216A	216A : Nurse's Restroom	yes	Door	Wood	White	Cracking	6	0.36	Negative
1	2	216A	216A : Nurse's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	2	216A	216A : Nurse's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	216A	216A : Nurse's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	2	216A	216A : Nurse's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	216A	216A : Nurse's Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	W1	Plaster	Yellow	Hole/Flaking/Chipping	2	14.27	Positive
1	2	201	201 : Classroom 201	yes	W2	Plaster	Yellow	Partially Inaccessible/Chipping	1	11.65	Positive
1	2	201	201 : Classroom 201	yes	W3	Plaster	Yellow	Efflorescence	3	16.05	Positive
1	2	201	201 : Classroom 201	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	Ceiling	Plaster	White	Efflorescence/Flaking	4	13.52	Positive
1	2	201A	201A : Classroom 201 Coat Room	yes	W1	Plaster	Yellow	Partially Inaccessible		7.68	Positive
1	2	201A	201A : Classroom 201 Coat Room	yes	W2	Plaster	Yellow	Partially Inaccessible		9.8	Positive
1	2	201A	201A : Classroom 201 Coat Room	yes	W3	Plaster	Yellow	Holes	1	11.57	Positive
1	2	201A	201A : Classroom 201 Coat Room	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	201A	201A : Classroom 201 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	201A	201A : Classroom 201 Coat Room	yes	Ceiling	Plaster	White	Alligatoring	90	10.5	Positive
1	2	201B	201B : Classroom 201 Storage Closet	yes	W1	Plaster	White & Tan	Flaking/Cracking	25	0.01	Negative
1	2	201B	201B : Classroom 201 Storage Closet	yes	W2	Plaster	White & Tan	Flaking/Cracking	40	0.01	Negative
1	2	201B	201B : Classroom 201 Storage Closet	yes	W3	Plaster	White & Tan	Flaking/Cracking	50	0.01	Negative
1	2	201B	201B : Classroom 201 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.09	Negative
1	2	201B	201B : Classroom 201 Storage Closet	yes	W4	Plaster	White & Tan	Flaking/Cracking/Hole	40	0.01	Negative
1	2	201B	201B : Classroom 201 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	201B	201B : Classroom 201 Storage Closet	yes	Ceiling	Plaster	White & Tan	Hole	1	0.01	Negative
1	2	203	203 : Classroom 203	yes	W1	Plaster	Yellow	Partially Inaccessible/Chipping/Flaking/Hole	3	13.24	Positive
1	2	203	203 : Classroom 203	yes	W2	Plaster	Yellow	Flaking/Staples	8	13.22	Positive
1	2	203	203 : Classroom 203	yes	W3	Plaster	Yellow	Efflorescence/Flaking	15	11.12	Positive
1	2	203	203 : Classroom 203	yes	W4	Plaster	Yellow	Flaking/Chipping/Staples	5	20.33	Positive
1	2	203	203 : Classroom 203	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	Ceiling	Plaster	White	Flaking	1	16.95	Positive
1	2	203A	203A : Classroom 203 Coat Room	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	203A	203A : Classroom 203 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	203A	203A : Classroom 203 Coat Room	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	203A	203A : Classroom 203 Coat Room	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	203A	203A : Classroom 203 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	203A	203A : Classroom 203 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	203C	203C : Classroom 203 Storage Closet	yes	W1	Plaster	White	Cracking	20	0.01	Negative
1	2	203C	203C : Classroom 203 Storage Closet	yes	W2	Plaster	White	Cracking	40	0.01	Negative
1	2	203C	203C : Classroom 203 Storage Closet	yes	W3	Plaster	White	Cracking	50	0.01	Negative
1	2	203C	203C : Classroom 203 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.05	Negative
1	2	203C	203C : Classroom 203 Storage Closet	yes	W4	Plaster	White	Cracking	40	0.01	Negative

			School District of Philadelphia								
			Name of Inspector: Paul Davis			Lead Safe Certification Assessment Report					
			Inspection Company: Vertex			Sullivan Elementary School					
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	203C	203C : Classroom 203 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	203C	203C : Classroom 203 Storage Closet	yes	Ceiling	Plaster	White	Cracking	4	0.01	Negative
1	2	202	202 : Classroom 202	yes	W1	Plaster	Yellow	Chipping/Flaking	2	14.97	Positive
1	2	202	202 : Classroom 202	yes	Door Frame	Wood	Varnish	Chipping	6	0.07	Negative
1	2	202	202 : Classroom 202	yes	W2	Plaster	Yellow	Staples	4	13.59	Positive
1	2	202	202 : Classroom 202	yes	Chalkboard Trough and Frame	Wood	Varnish	Chipping	10	0.11	Negative
1	2	202	202 : Classroom 202	yes	W3	Plaster	Yellow	Flaking/Chipping	4	14.69	Positive
1	2	202	202 : Classroom 202	yes	Window Sills & frames	Wood	Varnish	Chipping	10	0.11	Negative
1	2	202	202 : Classroom 202	yes	W4	Plaster	Yellow	Flaking/Staples	3	16.43	Positive
1	2	202	202 : Classroom 202	yes	Floor	Wood	Varnish	Chipping	20	0.01	Negative
1	2	202	202 : Classroom 202	yes	Baseboard	Wood	Varnish	Chipping	20	0.06	Negative
1	2	202	202 : Classroom 202	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	202A	202A : Classroom 202 Coat Room	yes	W1	Plaster	Yellow	Partially InaccessibleHole	1	6.14	Positive
1	2	202A	202A : Classroom 202 Coat Room	yes	W2	Plaster	Yellow	Partially Inaccessible		13.4	Positive
1	2	202A	202A : Classroom 202 Coat Room	yes	Pipe	Metal	Yellow	Chipping	3	0.03	Negative
1	2	202A	202A : Classroom 202 Coat Room	yes	W3	Plaster	Yellow	Partially Inaccessible		12.32	Positive
1	2	202A	202A : Classroom 202 Coat Room	yes	W4	Plaster	Yellow	Partially Inaccessible		11.87	Positive
1	2	202A	202A : Classroom 202 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	202A	202A : Classroom 202 Coat Room	yes	Ceiling	Plaster	White	AlligatoringFlaking/Efflorescence	75	10.14	Positive
1	2	202B	202B : Classroom 202 Storage Closet	yes	W1	Plaster	White	Cracking	20	0.01	Negative
1	2	202B	202B : Classroom 202 Storage Closet	yes	W2	Plaster	White	Cracking	50	0.01	Negative
1	2	202B	202B : Classroom 202 Storage Closet	yes	W3	Plaster	White	Cracking	40	0.01	Negative
1	2	202B	202B : Classroom 202 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.11	Negative
1	2	202B	202B : Classroom 202 Storage Closet	yes	W4	Plaster	White	Cracking	50	0.02	Negative
1	2	202B	202B : Classroom 202 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	202B	202B : Classroom 202 Storage Closet	yes	Ceiling	Plaster	White	Cracking	8	0.01	Negative
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	W2	Plaster	Purple	Chipping	5	13.69	Positive
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	W4	Plaster	Purple	Chipping	5	14.45	Positive
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Covebase	Concrete	Brown	Chipping	2	0.03	Negative
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Tread	Concrete	Grey	Chipping	3	0.41	Negative
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Riser	Concrete	Grey	Chipping	6	0.06	Negative
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Spindles	Metal	Grey	Chipping	12	6.67	Positive
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Newel Posts	Metal	Grey	Chipping	8	4.57	Positive
1	2	S-2	S-2 : Stairwell adjacent to Classroom 203	yes	Ceiling	Plaster & Concrete	White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	W1	Plaster	Tan	Partially Inaccessible	N/A	0.02	Negative
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	W2	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	W3	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.07	Negative
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	W4	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2		Storage Closet in Hallway between Girl's Restroom and Stairwell	yes	Ceiling	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	Doors and Frame	Metal	Brown	Chipping	20	0.01	Negative
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	W2	Plaster	Tan	Holes/Flaking/Chipping	5	13.2	Positive
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	W4	Plaster	Tan	Gouged	1	13.13	Positive
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	Covebase	Concrete	Brown	Chipping	8	0.03	Negative
1	2	H23	H23 : Hallway from Classrooms 201 to 203	yes	Ceiling	Plaster	White	Alligatoring	200	19.12	Positive
1	2		Vestibule in Girl's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2		Vestibule in Girl's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	2		Vestibule in Girl's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2		Vestibule in Girl's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	2		Vestibule in Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2		Vestibule in Girl's Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	2	203B	203B : Girl's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	203B	203B : Girl's Restroom	yes	W2	Plaster	Tan	Efflorescence/Spalling	20	15.46	Positive
1	2	203B	203B : Girl's Restroom	yes	Pipe	Metal	Tan	Chipping	4	0.07	Negative
1	2	203B	203B : Girl's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2	203B	203B : Girl's Restroom	yes	W4	Plaster	Tan	Spalling/Flaking	6	1.38	Positive
1	2	203B	203B : Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203B	203B : Girl's Restroom	yes	Ceiling	Plaster	Tan	Flaking/Spalling	20	11.57	Positive
1	2	204	204 : Classroom 204	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	204 : Classroom 204	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	204 : Classroom 204	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	204 : Classroom 204	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	204 : Classroom 204	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204	204 : Classroom 204	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	204A : Classroom 204 Coat Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	204A : Classroom 204 Coat Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E	F	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	204A	204A : Classroom 204 Coat Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	204A : Classroom 204 Coat Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	204A : Classroom 204 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204A	204A : Classroom 204 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	204B	204B : Classroom 204 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205	205 : Classroom 205	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205A	205A : Classroom 205 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	205B	205B : Classroom 205 Storage Closet	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	206 : Classroom 206	yes	W1	Plaster	Yellow	Hole/Flaking	1	18.69	Positive
1	2	206	206 : Classroom 206	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	206	206 : Classroom 206	yes	Divider Wall	Wood	Varnish	Friction	6	0.05	Negative
1	2	206	206 : Classroom 206	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	206	206 : Classroom 206	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	206	206 : Classroom 206	yes	Divider Wall	Wood	Varnish	Friction	6	0.06	Negative
1	2	206	206 : Classroom 206	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	206	206 : Classroom 206	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	206A	206A : Classroom 206 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	206B	206B : Classroom 206 Storage Closet	yes	W1	Plaster	White	Cracking	20	0.01	Negative
1	2	206B	206B : Classroom 206 Storage Closet	yes	W2	Plaster	White	Cracking	40	0.01	Negative
1	2	206B	206B : Classroom 206 Storage Closet	yes	W3	Plaster	White	Cracking	50	0.01	Negative
1	2	206B	206B : Classroom 206 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.17	Negative
1	2	206B	206B : Classroom 206 Storage Closet	yes	W4	Plaster	White	Cracking	40	0.01	Negative
1	2	206B	206B : Classroom 206 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	206B	206B : Classroom 206 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207	207 : Classroom 207	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	207 : Classroom 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	207 : Classroom 207	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	207 : Classroom 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	207 : Classroom 207	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	207 : Classroom 207	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	207A : Classroom 207 Coat Room	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207V	207V : Vestibule to Boy's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	207V	207V : Vestibule to Boy's Restroom	yes	W2	Plaster	Tan	Holes	2	9.45	Positive
1	2	207V	207V : Vestibule to Boy's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2	207V	207V : Vestibule to Boy's Restroom	yes	W4	Plaster	Tan	Spalling	10	8.15	Positive
1	2	207V	207V : Vestibule to Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207V	207V : Vestibule to Boy's Restroom	yes	Ceiling	Plaster	Tan	Spalling	1	7.35	Positive
1	2	207B	207B : Boy's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	207B	207B : Boy's Restroom	yes	W2	Plaster	Tan	Efflorescence/Flaking	10	14.5	Positive
1	2	207B	207B : Boy's Restroom	yes	W3	Plaster	Tan	Spalling	2	7.57	Positive
1	2	207B	207B : Boy's Restroom	yes	Radiator	Metal	Grey	Flaking	6	0.05	Negative
1	2	207B	207B : Boy's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	2	207B	207B : Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207B	207B : Boy's Restroom	yes	Ceiling	Plaster	Tan	Spalling	1	8.91	Positive
1	2	207C	207C : Boy's Restroom Service Closet	no	W1	Plaster	Tan	Efflorescence/Spalling/ Flaking	6	0.02	Negative
1	2	207C	207C : Boy's Restroom Service Closet	no	W2	Plaster	Tan	Efflorescence/Spalling	2	0.01	Negative
1	2	207C	207C : Boy's Restroom Service Closet	no	W3	Plaster	Tan	None	0	N/A	N/A
1	2	207C	207C : Boy's Restroom Service Closet	no	W4	Plaster	Tan	None	0	N/A	N/A
1	2	207C	207C : Boy's Restroom Service Closet	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207C	207C : Boy's Restroom Service Closet	no	Ceiling	Plaster	Tan	Efflorescence/Spalling/ Flaking	10	7.65	Positive
1	2	212	212 : Server Room 212	yes	W1	Plaster	White	Efflorescence/Chipping /Flaking	7	6.67	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	212	212 : Server Room 212	yes	W2	Plaster	White	Efflorescence/Chipping /Flaking	8	8.21	Positive
1	2	212	212 : Server Room 212	yes	W3	Plaster	White	Partially Inaccessible		4.77	Positive
1	2	212	212 : Server Room 212	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Server Room 212	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.09	Negative
1	2	212	212 : Server Room 212	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	212	212 : Server Room 212	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	213	213 : Storage/Copy Room 213	yes	W1	Plaster	White	Partially Inaccessible/Cracking/ Holes	10	0.44	Negative
1	2	213	213 : Storage/Copy Room 213	yes	W2	Plaster	White	Cracking	5	0.54	Negative
1	2	213	213 : Storage/Copy Room 213	yes	W3	Plaster	White	Partially Inaccessible	N/A	0.5	Negative
1	2	213	213 : Storage/Copy Room 213	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.05	Negative
1	2	213	213 : Storage/Copy Room 213	yes	W4	Plaster	White	Partially Inaccessible	N/A	0.46	Negative
1	2	213	213 : Storage/Copy Room 213	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	213	213 : Storage/Copy Room 213	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	W1	Plaster	White	Cracking	15	0.01	Negative
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	W2	Plaster	White	Cracking	20	0.01	Negative
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	W3	Plaster	White	Cracking	40	0.01	Negative
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	W4	Plaster	White	Cracking	20	0.01	Negative
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	213A	213A : Storage/Copy Room 213 Closet	yes	Ceiling	Plaster	White	Divots/Scratches	4	0.01	Negative
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	W1	Plaster	Tan	Holes/Flaking	6	13.53	Positive
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	W3	Plaster	Tan	Spalling/Flaking/Holes	7	14.91	Positive
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	Radiator	Metal	Tan	Chipping/Flaking	12	1.95	Positive
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	Pipe Outer Sleeves	Metal	White & Tan	Chipping/Flaking	12	14.47	Positive
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	Covebase	Concrete	Brown	Chipping	15	0.03	Negative
1	2	H22	H22 : Hallway from Classrooms 201 to 207	yes	Ceiling	Plaster	White	Alligatoring	500	20.55	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	W1	Brick	White	Flaking	100	2.85	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Door and Frames	Metal	Brown	Friction	10	0.08	Negative
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	W2	Brick	White	None	0	N/A	N/A
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	W3	Brick	White	Flaking	100	1.97	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	W4	Brick	White	Flaking	15	2.6	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Grate	Metal	Grey	Flaking	25	11.2	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Tread	Concrete	Brown	Chipping	20	0.08	Negative
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Riser	Concrete	Brown	Chipping	20	0.1	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Stair Window Frame	Metal	Brown	Chipping/Flaking	10	6.45	Positive
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Hand Rail	Metal	Brown	Friction	10	0.1	Negative
1	2	S-1	S-1 : Fire Tower accross from Classroom 207	yes	Ceiling	Concrete	White	Flaking	25	0.1	Negative
1	2	208	208 : Classroom 208	yes	W1	Plaster	Yellow	Chipping/Flaking/Hole	3	15.21	Positive
1	2	208	208 : Classroom 208	yes	W2	Plaster	Yellow	Chipping/Flaking	1	13.54	Positive
1	2	208	208 : Classroom 208	yes	W3	Plaster	Yellow	Chipping/Flaking	2	2.52	Positive
1	2	208	208 : Classroom 208	yes	W4	Plaster	Yellow	Efflorescence	1	10	Positive
1	2	208	208 : Classroom 208	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	208	208 : Classroom 208	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208A	208A : Classroom 208 Coat Room	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	2	208A	208A : Classroom 208 Coat Room	yes	W2	Plaster	Yellow	Partially Inaccessible/Spalling/Efflorescence	7	13.37	Positive
1	2	208A	208A : Classroom 208 Coat Room	yes	W3	Plaster	Yellow	Partially Inaccessible		12.15	Positive
1	2	208A	208A : Classroom 208 Coat Room	yes	W4	Plaster	Yellow	Partially Inaccessible		11.85	Positive
1	2	208A	208A : Classroom 208 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	208A	208A : Classroom 208 Coat Room	yes	Ceiling	Plaster	White	Alligatoring	85	12.15	Positive
1	2	208B	208B : Classroom 208 Storage Closet	yes	W1	Plaster	White	Hole	1	0.01	Negative
1	2	208B	208B : Classroom 208 Storage Closet	yes	W2	Plaster	White	Cracking	40	0.01	Negative
1	2	208B	208B : Classroom 208 Storage Closet	yes	W3	Plaster	White	Cracking	50	0.01	Negative
1	2	208B	208B : Classroom 208 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.05	Negative
1	2	208B	208B : Classroom 208 Storage Closet	yes	W4	Plaster	White	Cracking	40	0.01	Negative
1	2	208B	208B : Classroom 208 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	208B	208B : Classroom 208 Storage Closet	yes	Ceiling	Plaster	White	Cracking	2	0.01	Negative
1	2	209	209 : Classroom 209	yes	W1	Plaster	White	Chipping/Hole	2	9.09	Positive
1	2	209	209 : Classroom 209	yes	Door Frame	Wood	Varnish	Friction	6	0.11	Negative
1	2	209	209 : Classroom 209	yes	Chalkboard Trough and Frame	Wood	Varnish	Chipping	10	0.15	Negative
1	2	209	209 : Classroom 209	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	209	209 : Classroom 209	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	209	209 : Classroom 209	yes	Window Sills and Frame	Wood	Varnish	Friction	10	0.19	Negative
1	2	209	209 : Classroom 209	yes	W4	Plaster	White	Gouges	2	14.44	Positive
1	2	209	209 : Classroom 209	yes	Door	Wood	Varnish	Friction	2	0.08	Negative
1	2	209	209 : Classroom 209	yes	Floor	Wood	Varnish	Friction	40	0.05	Negative
1	2	209	209 : Classroom 209	yes	Baseboard	Wood	Varnish	Friction	20	0.12	Negative
1	2	209	209 : Classroom 209	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Coat Room	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Coat Room	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Coat Room	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Coat Room	yes	W4	Plaster	White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	209A	209A : Classroom 209 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Coat Room	yes	Ceiling	Plaster	White	Flaking	1	11.3	Positive
1	2	209B	209B : Classroom 209 Storage Closet	yes	W1	Plaster	White	Cracking	15	0.01	Negative
1	2	209B	209B : Classroom 209 Storage Closet	yes	W2	Plaster	White	Cracking	30	0.01	Negative
1	2	209B	209B : Classroom 209 Storage Closet	yes	W3	Plaster	White	Cracking	50	0.01	Negative
1	2	209B	209B : Classroom 209 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.06	Negative
1	2	209B	209B : Classroom 209 Storage Closet	yes	W4	Plaster	White	Cracking	50	0.01	Negative
1	2	209B	209B : Classroom 209 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	209B	209B : Classroom 209 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	210	210 : Classroom 210	yes	W1	Plaster	White	Partially Inaccessible/Flaking	10	12.76	Positive
1	2	210	210 : Classroom 210	yes	W2	Plaster	White	Partially Inaccessible/Flaking	40	8.56	Positive
1	2	210	210 : Classroom 210	yes	W3	Plaster	White	Partially Inaccessible/Flaking	12	14.64	Positive
1	2	210	210 : Classroom 210	yes	Pipe	Metal	White	Chipping	2	13.94	Positive
1	2	210	210 : Classroom 210	yes	W4	Plaster	White	Partially Inaccessible/Flaking	5	10.25	Positive
1	2	210	210 : Classroom 210	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	210	210 : Classroom 210	yes	Ceiling	Plaster	White	Flaking	6	0.2	Negative
1	2	210A	210A : Classroom 210 Coat Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210A	210A : Classroom 210 Coat Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210A	210A : Classroom 210 Coat Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210A	210A : Classroom 210 Coat Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210A	210A : Classroom 210 Coat Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210A	210A : Classroom 210 Coat Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	210B	210B : Classroom 210 Storage Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	211 : Office 211	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	211	211 : Office 211	yes	W2	Plaster	White	Partially Inaccessible		7.44	Positive
1	2	211	211 : Office 211	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.04	Negative
1	2	211	211 : Office 211	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	211	211 : Office 211	yes	W4	Plaster	White	Partially Inaccessible/Holes		7.98	Positive
1	2	211	211 : Office 211	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	211	211 : Office 211	yes	Ceiling	Plaster	White	Flaking	12	9.3	Positive
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	W1	Plaster	Blue	Flaking	2	17.35	Positive
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	W2	Plaster	Blue	Chipping	12	1.27	Positive
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	W3	Plaster	Blue	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Covebase	Concrete	Brown	Chipping	6	0.05	Negative
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Tread	Concrete	Brown	Chipping	2	0.1	Negative
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Riser	Concrete	Brown	Chipping	4	0.07	Negative
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Stringer	Concrete	Brown	Chipping	4	0.16	Negative
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Spindles	Metal	Grey	Chipping	10	4.8	Positive
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Newel Posts	Metal	Grey	Chipping	6	3.82	Positive
1	2	S-3	S-3 : Stairwell adjacent to Classroom 208	yes	Ceiling	Plaster	White	Efflorescence	2	14.74	Positive
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	Doors & Frame	Metal	Brown	Chipping	6	0.01	Negative
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	W2	Plaster	Tan	Chipping/Flaking	5	15.44	Positive
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	Pipe outer Covers	Metal	White	Chipping/Flaking	6	12.86	Positive
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	W4	Plaster	Tan	Holes	2	14.41	Positive
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	Covebase	Concrete	Brown	Chipping	10	0.1	Negative
1	2	H21	H21 : Hallway from Classrooms 208 to 210	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W1	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W2	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W3	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W4	Plaster	Tan	Partially Inaccessible	N/A	0.01	Negative
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	114	114 : Main Office	yes	W1	Plaster	Grey and White	None	0	N/A	N/A
1	1	114	114 : Main Office	yes	W2	Plaster	Grey and White	None	0	N/A	N/A
1	1	114	114 : Main Office	yes	W3	Plaster	Grey and White	Flaking	1	34.3	Positive
1	1	114	114 : Main Office	yes	Radiator	Metal	Grey	Chipping	3	0.8	Positive
1	1	114	114 : Main Office	yes	W4	Plaster	Grey and White	None	0	N/A	N/A
1	1	114	114 : Main Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	114 : Main Office	yes	Ceiling	Plaster	White	Flaking	2	16.35	Positive
1	1	114A	114A : Main Office Closet	yes	W1	Plaster	White	Partially Inaccessible/Cracking	5	6.5	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	114A	114A : Main Office Closet	yes	W2	Plaster	White	Partially Inaccessible/Efflorescence/Flaking	30	10.9	Positive
1	1	114A	114A : Main Office Closet	yes	W3	Plaster	White	Partially Inaccessible/Efflorescence/Flaking	10	8.5	Positive
1	1	114A	114A : Main Office Closet	yes	Pipe	Metal	White	Chipping	2	4.9	Positive
1	1	114A	114A : Main Office Closet	yes	W4	Plaster	White	Cracking	10	10.1	Positive
1	1	114A	114A : Main Office Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	114A : Main Office Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.15	Negative
1	1	114A	114A : Main Office Closet	yes	Ceiling	Plaster	White	Flaking	20	15.3	Positive
1	1	114B	114B : Main Office Closet Pipe Shaft	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114B	114B : Main Office Closet Pipe Shaft	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114B	114B : Main Office Closet Pipe Shaft	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114B	114B : Main Office Closet Pipe Shaft	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114B	114B : Main Office Closet Pipe Shaft	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114B	114B : Main Office Closet Pipe Shaft	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	115	115 : Principal's Office	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	115	115 : Principal's Office	yes	W2	Plaster	Tan	Chipping	1	28.7	Positive
1	1	115	115 : Principal's Office	yes	W3	Plaster	Tan	Flaking	2	29.5	Positive
1	1	115	115 : Principal's Office	yes	W4	Plaster	Tan	Flaking	1	32	Positive
1	1	115	115 : Principal's Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115	115 : Principal's Office	yes	Ceiling	Plaster	White	Flaking	3	16.13	Positive
1	1	115A	115A : Principal's Restroom	yes	W1	Plaster	Peach	None	0	N/A	N/A
1	1	115A	115A : Principal's Restroom	yes	W2	Plaster	Peach	Hole	1	11.7	Positive
1	1	115A	115A : Principal's Restroom	yes	W3	Plaster	Peach	Efflorescence	1	12	Positive
1	1	115A	115A : Principal's Restroom	yes	W4	Plaster	Peach	None	0	N/A	N/A
1	1	115A	115A : Principal's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115A	115A : Principal's Restroom	yes	Ceiling	Plaster	Peach	Efflorescence/Peeling	4	8.79	Positive
1	1	115B	115B : Principal's Closet	yes	W1	Plaster	Tan	Hole	1	15.4	Positive
1	1	115B	115B : Principal's Closet	yes	W2	Plaster	Tan	Partially Inaccessible		11.7	Positive
1	1	115B	115B : Principal's Closet	yes	W3	Plaster	Tan	Partially Inaccessible/Chipping/Hole	3	17.4	Positive
1	1	115B	115B : Principal's Closet	yes	W4	Plaster	Tan	Partially Inaccessible		11.6	Positive
1	1	115B	115B : Principal's Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115B	115B : Principal's Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.06	Negative
1	1	115B	115B : Principal's Closet	yes	Ceiling	Plaster	Tan	Flaking	4	9.79	Positive
1	1	H13A	H13A : Women's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	H13A	H13A : Women's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	H13A	H13A : Women's Restroom	yes	W3	Plaster	Tan	Flaking	2	0.04	Negative
1	1	H13A	H13A : Women's Restroom	yes	Radiator	Metal	Grey	Chipping	2	1.59	Positive
1	1	H13A	H13A : Women's Restroom	yes	W4	CMU	Tan	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	S p a c e #	O n - S i t e R o o m N a m e	S t u d e n t / T e a c h e r O c c u p i e d (y e s / n o)	C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f D a m a g e	D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g / c m 2)	X R F (p o s i t i v e / n e g a t i v e)
1	1	H13A	H13A : Women's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13A	H13A : Women's Restroom	yes	Ceiling	Plaster	Tan	Efflorescence	1	5.72	Positive
1	1	101	101 : Classroom 101	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	101	101 : Classroom 101	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	101	101 : Classroom 101	yes	W3	Plaster	Tan	Spalling	15	21	Positive
1	1	101	101 : Classroom 101	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	101	101 : Classroom 101	yes	Bench	Wood	Varnish	Friction	N/A	0.09	Negative
1	1	101	101 : Classroom 101	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	101 : Classroom 101	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	W1	Plaster	Grey	None	0	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	W2	Plaster	Grey	None	0	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	Radiator	Metal	Grey	Chipping/Flaking	3	0.02	Negative
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	W3	Plaster	Grey	None	0	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	W4	Plaster	Grey	None	0	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101A	101A : Classroom 101 Restroom One (left side)	yes	Ceiling	Plaster	Grey	None	0	N/A	N/A
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	W1	Plaster	Grey	Chipping/Flaking/Hole	1	12.7	Positive
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	W2	Plaster	Grey	None	0	N/A	N/A
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	W3	Plaster	Grey	None	0	N/A	N/A
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	W4	Plaster	Grey	None	0	N/A	N/A
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101B	101B : Classroom 101 Restroom Two (right side)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101C	101C : Classroom 101 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	Shelving	Wood	Varnish	Friction	20	0.07	Negative
1	1	101D	101D : Classroom 101 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101D	101D : Classroom 101 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	102	102 : Classroom 102	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	102	102 : Classroom 102	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	102	102 : Classroom 102	yes	W3	Plaster	Tan	Spalling	35	16.7	Positive
1	1	102	102 : Classroom 102	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	102	102 : Classroom 102	yes	Floor	Wood	Varnish	None	0	0.01	Negative
1	1	102	102 : Classroom 102	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102B	102B : Classroom 102 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	102B	102B : Classroom 102 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	1	102B	102B : Classroom 102 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	102B	102B : Classroom 102 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	102B	102B : Classroom 102 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102B	102B : Classroom 102 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	102C	102C : Classroom 102 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	103	103 : Classroom 103	yes	W1	Plaster	Tan	Hole	1	20.3	Positive
1	1	103	103 : Classroom 103	yes	Chalkboard Troughs and Frames	Wood	Varnish	Chipping	20	0.09	Negative
1	1	103	103 : Classroom 103	yes	W2	Plaster	Tan	Spalling	3	24.4	Positive
1	1	103	103 : Classroom 103	yes	W3	Plaster	Tan	Spalling	1	23.2	Positive
1	1	103	103 : Classroom 103	yes	Radiator	Metal	Grey	Flaking/Chipping	10	6.1	Positive
1	1	103	103 : Classroom 103	yes	Window Sills and Frames	Wood	Varnish	Chipping	10	0.22	Negative
1	1	103	103 : Classroom 103	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	103	103 : Classroom 103	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	103 : Classroom 103	yes	Baseboard	Wood	Varnish	Chipping	10	0.12	Negative
1	1	103	103 : Classroom 103	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103A	103A : Classroom 103 Coat Room	yes	Ceiling	Plaster	White	Flaking	15	11.81	Positive
1	1	103C	103C : Classroom 103 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	103C	103C : Classroom 103 Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	103C	103C : Classroom 103 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	103C	103C : Classroom 103 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	103C	103C : Classroom 103 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103C	103C : Classroom 103 Restroom	yes	Ceiling	Plaster	White	Spalling	2	8.82	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	W1	Plaster	Purple	Chipping	1	0.36	Negative
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Door and Frame	Metal	Brown	Chipping	4	0.01	Negative
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	W2	Plaster	Purple	None	0	N/A	N/A
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	W3	Plaster	Purple	Chipping	2	9.41	Positive
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Covebase	Concrete	Brown & White	Chipping	5	0.04	Negative
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Spindles	Metal	Grey	Chipping	15	4.7	Positive
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Newel Posts	Metal	Grey	Chipping	6	2.21	Positive
1	1	S-2	S-2 : Stairwell adjacent to Classroom 103	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	W4	Plaster	White	Spalling/Flaking	20	15.45	Positive
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Covebase	Concrete	Grey	Chipping	6	0.04	Negative
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Tread	Concrete	Grey	Chipping	50	0.35	Negative
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Riser	Concrete	Grey	Chipping	25	0.31	Negative
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Stringer	Concrete	Grey	Chipping	12	1.32	Positive
1	1	S18	S18 : Stairwell adjacent Classroom 101	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	W1	Metal	Brown	Chipping	4	0	Negative
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	W2	Plaster	Tan	Holes/Chipping	10	23.6	Positive
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Bench	Wood	Varnish	Friction	2	0.05	Negative
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	W4	Plaster	Tan	Chipping/Flaking	3	19.1	Positive
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Covebase	Concrete	Brown	Chipping	7	0.06	Negative
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Spindles	Metal	Grey	Chipping	10	5.8	Positive
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Newel Post	Metal	Grey	Chipping	2	4	Positive
1	1	H13	H13 : Hallway from Classrooms 101 to 103	yes	Ceiling	Plaster	White	Flaking	1	14.31	Positive
1	1		Vestibule for Girl's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Girl's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Girl's Restroom	yes	W3	Plaster	Tan	Peeling	4	0.01	Negative
1	1		Vestibule for Girl's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Vestibule for Girl's Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	103B	103B : Girl's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	103B	103B : Girl's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	103B	103B : Girl's Restroom	yes	Pipe	Metal	Tan	Chipping	2	0.07	Negative
1	1	103B	103B : Girl's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	103B	103B : Girl's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	103B	103B : Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	S p a c e #	O n - S i t e R o o m N a m e	S t u d e n t / T e a c h e r O c c u p i e d (y e s / n o)	C o m p o n e n t	S u b s t r a t e M a t e r i a l	C o l o r	D e s c r i p t i o n o f D a m a g e	D a m a g e Q u a n t i t y (s f)	X R F R e a d i n g (m g / c m 2)	X R F (p o s i t i v e / n e g a t i v e)
1	1	103B	103B : Girl's Restroom	yes	Ceiling	Plaster	Tan	Flaking	2	7.64	Positive
1	1	103B	103B : Girl's Restroom	yes	Duct Work	Metal	Tan	Chipping	10	0.01	Negative
1	1	104	104 : Classroom 104	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	104	104 : Classroom 104	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	1	104	104 : Classroom 104	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	104	104 : Classroom 104	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	104	104 : Classroom 104	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	104	104 : Classroom 104	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	104B : Classroom 104 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	104A	104A : Classroom 104 Coat Room	yes	W1	Plaster	Tan	Broken	1	10.8	Positive
1	1	104A	104A : Classroom 104 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	104A	104A : Classroom 104 Coat Room	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1	1	104A	104A : Classroom 104 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	104A	104A : Classroom 104 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	104A	104A : Classroom 104 Coat Room	yes	Ceiling	Plaster	White	Flaking	1	10.7	Positive
1	1	104C	104C : Classroom 104 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	104C	104C : Classroom 104 Storage Closet	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	104C	104C : Classroom 104 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	104C	104C : Classroom 104 Storage Closet	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	104C	104C : Classroom 104 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	104C	104C : Classroom 104 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	105	105 : Classroom 105	yes	W1	Plaster	White	Chipping/Flaking	1	16.7	Positive
1	1	105	105 : Classroom 105	yes	W2	Plaster	White	Chipping/Flaking	1	16.74	Positive
1	1	105	105 : Classroom 105	yes	W3	Plaster	White	Chipping/Flaking/Small Hole	4	11.04	Positive
1	1	105	105 : Classroom 105	yes	Pipe	Metal	White	Flaking	5	13.65	Positive
1	1	105	105 : Classroom 105	yes	Radiator	Metal	Grey	Chipping/Flaking	4	3.65	Positive
1	1	105	105 : Classroom 105	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	105	105 : Classroom 105	yes	Floor	Wood	Varnish	Friction	20	0.05	Negative
1	1	105	105 : Classroom 105	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105B	105B : Classroom 105 Restroom	yes	W1	Plaster	Peach	None	0	N/A	N/A
1	1	105B	105B : Classroom 105 Restroom	yes	W2	Sheetrock	Peach	Flaking	1	0.01	Negative
1	1	105B	105B : Classroom 105 Restroom	yes	W3	Plaster	Peach	Flaking	1	4.95	Positive
1	1	105B	105B : Classroom 105 Restroom	yes	W4	Plaster	Peach	None	0	N/A	N/A
1	1	105B	105B : Classroom 105 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	105B : Classroom 105 Restroom	yes	Ceiling	Plaster	Peach	None	0	N/A	N/A
1	1	105A	105A : Classroom 105 Coat Room	yes	W1	Plaster	White	Hole	1	13.2	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	105A	105A : Classroom 105 Coat Room	yes	W2	Plaster	White	Flaking/Hole	1	9.44	Positive
1	1	105A	105A : Classroom 105 Coat Room	yes	W3	Sheetrock	White	Flaking/Hole	1	0.01	Negative
1	1	105A	105A : Classroom 105 Coat Room	yes	W4	Plaster	White	Partially Inaccessible/Chipping	10	8.24	Positive
1	1	105A	105A : Classroom 105 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	105A	105A : Classroom 105 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105C	105C : Classroom 105 Storage Closet	yes	W1	Plaster	White	Cracking	20	0.01	Negative
1	1	105C	105C : Classroom 105 Storage Closet	yes	W2	Plaster	White	Cracking	40	0.01	Negative
1	1	105C	105C : Classroom 105 Storage Closet	yes	W3	Plaster	White	Cracking	50	0.01	Negative
1	1	105C	105C : Classroom 105 Storage Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.04	Negative
1	1	105C	105C : Classroom 105 Storage Closet	yes	W4	Plaster	White	Cracking	40	0.02	Negative
1	1	105C	105C : Classroom 105 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	105C	105C : Classroom 105 Storage Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	W4	Sheetrock	Blue	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	106	106 : Classroom 106	yes	Ceiling	Plaster	White	Flaking	3	14.29	Positive
1	1	106B	106B : Classroom 106 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	106B	106B : Classroom 106 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	1	106B	106B : Classroom 106 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	106B	106B : Classroom 106 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	106B	106B : Classroom 106 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	106B : Classroom 106 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	106C	106C : Classroom 106 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	106C	106C : Classroom 106 Storage Closet	yes	W2	Plaster	Tan	Hole	1	0.01	Negative
1	1	106C	106C : Classroom 106 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	106C	106C : Classroom 106 Storage Closet	yes	W4	Plaster	Tan	Hole	1	0.02	Negative
1	1	106C	106C : Classroom 106 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	106C	106C : Classroom 106 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	107	107 : Office Suite 107 Common Area	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	107	107 : Office Suite 107 Common Area	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	107	107 : Office Suite 107 Common Area	yes	W3	Sheetrock	White	Chipping/Flaking	3	0.01	Negative
1	1	107	107 : Office Suite 107 Common Area	yes	Door Frames	Metal	Tan	Chipping	8	0.06	Negative
1	1	107	107 : Office Suite 107 Common Area	yes	W4	Plaster	White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	107	107 : Office Suite 107 Common Area	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107	107 : Office Suite 107 Common Area	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	107A : Office 107A	yes	W1	Sheetrock	White	Partially Inaccessible	N/A	0.03	Negative
1	1	107A	107A : Office 107A	yes	W2	Sheetrock	White	Partially Inaccessible	N/A	0.04	Negative
1	1	107A	107A : Office 107A	yes	W3	Plaster	White	Flaking	1	15.41	Positive
1	1	107A	107A : Office 107A	yes	W4	Plaster	White	Flaking/Holes	1	0.05	Negative
1	1	107A	107A : Office 107A	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107A	107A : Office 107A	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	107B : Assistant Principal 107B	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	1	107B	107B : Assistant Principal 107B	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	1	107B	107B : Assistant Principal 107B	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	107B	107B : Assistant Principal 107B	yes	W4	Sheetrock	White	Chipping	1	0.02	Negative
1	1	107B	107B : Assistant Principal 107B	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	107B : Assistant Principal 107B	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107C	107C : Office 107C	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	1	107C	107C : Office 107C	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	107C	107C : Office 107C	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	107C	107C : Office 107C	yes	W4	Sheetrock	White	Flaking	2	0.01	Negative
1	1	107C	107C : Office 107C	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107C	107C : Office 107C	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107E	107E : Office 107 Closet	yes	W1	Plaster	Tan	Flaking	1	9.91	Positive
1	1	107E	107E : Office 107 Closet	yes	W2	Plaster	Tan	Partially Inaccessible/Flaking/Holes	2	11.95	Positive
1	1	107E	107E : Office 107 Closet	yes	W3	Plaster	Tan	Partially Inaccessible/Flaking	2	12.19	Positive
1	1	107E	107E : Office 107 Closet	yes	W4	Plaster	Tan	Partially Inaccessible		12.43	Positive
1	1	107E	107E : Office 107 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	107E	107E : Office 107 Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Vestibule for Boy's Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107D	107D : Boy's Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1		Custodial Closet in Boy's Restroom	no	W1	Plaster	Tan	Efflorescence	2	0.02	Negative

			<p style="text-align: center;">School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School</p>								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1		Custodial Closet in Boy's Restroom	no	W2	Plaster	Tan	Efflorescence	2	0.01	Negative
1	1		Custodial Closet in Boy's Restroom	no	W3	Plaster	Tan	Efflorescence	2	0.01	Negative
1	1		Custodial Closet in Boy's Restroom	no	W4	Plaster	Tan	None	0	N/A	N/A
1	1		Custodial Closet in Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1		Custodial Closet in Boy's Restroom	no	Ceiling	Plaster	Tan	Efflorescence	10	0.01	Negative
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	W1	Plaster	Tan	Flaking/Holes	2	0.04	Negative
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	Door	Metal	Brown	Chipping/Flaking	12	4.55	Positive
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	Floor	Concrete	Grey	Chipping	40	1.92	Positive
1	1	H12A	H12A : School Psychologist Office (Former Projection Room)	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	W1	Marble	N/A	N/A	N/A	N/A	N/A
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	W2	Plaster	White	Chipping	2	13.71	Positive
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	W3	Plaster	White	Staple Holes	40	14.26	Positive
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	Pipe Outer cover	Metal	Tan and White	Chipping/Flaking	5	9.45	Positive
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S16	S16 : Auditorium Entrance Stairs (Right)	yes	Ceiling	Plaster	White	Efflorescence	20	14.47	Positive
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	W1	Marble	N/A	N/A	N/A	N/A	N/A
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	W3	Plaster	White	Chipping	2	24.6	Positive
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	W4	Plaster	White	Chipping	2	22.3	Positive
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S17	S17 : Auditorium Entrance Stairs (Left)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	W1	Brick	White	Flaking	12	2.18	Positive
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Doors	Metal	Brown	Chipping	8	0.01	Negative
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	W2	Brick	White	Flaking	30	4.54	Positive
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	W3	Brick	White	Flaking	100	4.76	Positive
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	W4	Brick	White	Flaking	10	2.03	Positive
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Grate	Metal	Grey	Flaking	40	11.09	Positive
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Tread	Concrete	Brown	Chipping/Flaking	15	0.04	Negative
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Riser	Concrete	Brown	Chipping/Flaking	25	0.1	Negative
	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Stairs Window Frame	Metal	Brown	Chipping	10	10.39	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S-1	S-1 : Fire Tower adjacent to Auditorium	yes	Ceiling	Concrete	White	Flaking	20	0.01	Negative
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	W1	Plaster	Tan	Chipping/Flaking/Holes	3	15.08	Positive
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	W3	Plaster	Tan	Flaking	3	12.82	Positive
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Pipe outer Covers	Metal	Tan and White	Chipping	15	13.32	Positive
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Radiators	Metal	Tan	Chipping/Flaking	10	0.08	Negative
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Spindles and Newel Posts	Metal	Grey	Chipping	50	11.57	Positive
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Covebase	Concrete	Brown	Chipping	5	0.06	Negative
1	1	H12	H12 : Hallway from Classrooms 104 to 107	yes	Ceiling	Plaster	White	Flaking	1	13.52	Positive
1	1	111	111 : Auditorium	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	111	111 : Auditorium	yes	W2	Plaster	Tan	Efflorescence/Flaking/Chipping	20	12.9	Positive
1	1	111	111 : Auditorium	yes	Doors	Metal	Brown	Chipping	5	0	Negative
1	1	111	111 : Auditorium	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	111	111 : Auditorium	yes	W4	Plaster	Tan	Chipping/Flaking	20	5.3	Positive
1	1	111	111 : Auditorium	yes	Doors	Metal	Brown	Chipping	5	0	Negative
1	1	111	111 : Auditorium	yes	Floor	Wood	Varnish	Friction	10	0.01	Negative
1	1	111	111 : Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	111A	111A : Stage	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	111A	111A : Stage	yes	W2	Plaster	Tan	Holes/Cracking	3	4.3	Positive
1	1	111A	111A : Stage	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	111A	111A : Stage	yes	W4	Plaster	Tan	Holes	2	6	Positive
1	1	111A	111A : Stage	yes	Floor	Wood	Varnish	Friction	5	0.01	Negative
1	1	111A	111A : Stage	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	112	112 : Stage Storage (Left)	yes	W1	Plaster	White	Partially Inaccessible		9.5	Positive
1	1	112	112 : Stage Storage (Left)	yes	W2	Plaster	White	Partially Inaccessible		10	Positive
1	1	112	112 : Stage Storage (Left)	yes	W3	Plaster	Blue	Partially Inaccessible		13.5	Positive
1	1	112	112 : Stage Storage (Left)	yes	Pipes	Metal	White	Chipping/Flaking	15	13.7	Positive
1	1	112	112 : Stage Storage (Left)	yes	Radiator	Metal	Grey	Chipping/Flaking	6	4.6	Positive
1	1	112	112 : Stage Storage (Left)	yes	W4	Plaster	White	Partially Inaccessible		13.2	Positive
1	1	112	112 : Stage Storage (Left)	yes	Floor	Wood	Varnish	Partially Inaccessible	N/A	0.02	Negative
1	1	112	112 : Stage Storage (Left)	yes	Ceiling	Plaster	White	Flaking	5	15.9	Positive
1	1	112	112 : Stage Storage (Left)	yes	Duct Work	Metal	White	Flaking	2	4.9	Positive
1	1	112A	112A : Stage Left Restroom	yes	W1	Plaster	Tan	Cracking/Flaking	15	8.5	Positive
1	1	112A	112A : Stage Left Restroom	yes	W2	Plaster	Tan	Cracking/Flaking	12	10.8	Positive
1	1	112A	112A : Stage Left Restroom	yes	W3	Plaster	Tan	Cracking/Flaking	12	11.5	Positive
1	1	112A	112A : Stage Left Restroom	yes	W4	Plaster	Tan	Cracking/Flaking	12	13	Positive
1	1	112A	112A : Stage Left Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	112A	112A : Stage Left Restroom	yes	Ceiling	Plaster	Tan	Cracking/Flaking	2	12.8	Positive
1	1	113	113 : Stage Storage (Right)	yes	W1	Plaster	White	Flaking	12	7.66	Positive
1	1	113	113 : Stage Storage (Right)	yes	W2	Plaster	White	Flaking	75	11.2	Positive
1	1	113	113 : Stage Storage (Right)	yes	W3	Plaster	White	Flaking	100	10.9	Positive
1	1	113	113 : Stage Storage (Right)	yes	Pipes	Metal	White	Flaking	10	0.11	Negative
1	1	113	113 : Stage Storage (Right)	yes	Radiator	Metal	Grey	Flaking	6	7.05	Positive
1	1	113	113 : Stage Storage (Right)	yes	W4	Plaster	White	Flaking	25	11.43	Positive
1	1	113	113 : Stage Storage (Right)	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	113	113 : Stage Storage (Right)	yes	Ceiling	Plaster	White	Flaking	60	10.5	Positive
1	1	113	113 : Stage Storage (Right)	yes	Duct Work	Metal	White	Flaking	8	8.92	Positive
1	1	113A	113A : Stage Right Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	113A	113A : Stage Right Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	113A	113A : Stage Right Restroom	yes	W3	Plaster	White	Spalling	5	0.15	Negative
1	1	113A	113A : Stage Right Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	113A	113A : Stage Right Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113A	113A : Stage Right Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	108	108 : Classroom 108	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	Pipe	Metal	Tan	Flaking	2	0.1	Negative
1	1	108B	108B : Classroom 108 Restroom	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	108B : Classroom 108 Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108A	108A : Classroom 108 Coat Room	yes	W1	Plaster	Tan	Flaking	2	12.6	Positive
1	1	108A	108A : Classroom 108 Coat Room	yes	W2	Plaster	Tan	Flaking	2	15	Positive
1	1	108A	108A : Classroom 108 Coat Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	108A	108A : Classroom 108 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	108A	108A : Classroom 108 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	108A	108A : Classroom 108 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	108C	108C : Classroom 108 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	109	109 : Classroom 109	yes	W1	Plaster	Tan	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	109	109 : Classroom 109	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	109	109 : Classroom 109	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	109	109 : Classroom 109	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	109	109 : Classroom 109	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	109	109 : Classroom 109	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	109A	109A : Classroom 109 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	109B	109B : Classroom 109 Storage Closet	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	110	110 : Classroom 110	yes	W1	Plaster	White	Flaking/Chipping	3	24	Positive
1	1	110	110 : Classroom 110	yes	Door Frame	Wood	Varnish	Chipping	2	0.12	Negative
1	1	110	110 : Classroom 110	yes	W2	Plaster	White	Spalling/Flaking	4	30.8	Positive
1	1	110	110 : Classroom 110	yes	Shelving	Wood	Blue	Chipping	15	0.02	Negative
1	1	110	110 : Classroom 110	yes	Pipe	Metal	White	Alligatoring	8	30.4	Positive
1	1	110	110 : Classroom 110	yes	W3	Plaster	White	Spalling/Flaking	5	24.5	Positive
1	1	110	110 : Classroom 110	yes	Window Sills and Frame	Wood	Varnish	Chipping	4	0.17	Negative
1	1	110	110 : Classroom 110	yes	W4	Plaster	White	Hole/Staples/Flaking	3	32.8	Positive
1	1	110	110 : Classroom 110	yes	Chalkboard and Frame	Wood	Varnish	Chipping	20	0.07	Negative
1	1	110	110 : Classroom 110	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110	110 : Classroom 110	yes	Baseboard	Wood	Varnish	Chipping	30	0.14	Negative
1	1	110	110 : Classroom 110	yes	Ceiling	Plaster	White	Flaking	40	15.17	Positive
1	1	110B	110B : Classroom 110 Restroom	yes	W1	Plaster	Tan	Flaking	1	11.9	Positive
1	1	110B	110B : Classroom 110 Restroom	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	1	110B	110B : Classroom 110 Restroom	yes	W3	Plaster	Tan	Flaking/Hole	1	13	Positive
1	1	110B	110B : Classroom 110 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	110B	110B : Classroom 110 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110B	110B : Classroom 110 Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	110A	110A : Classroom 110 Coat Room	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	110A	110A : Classroom 110 Coat Room	yes	W2	Plaster	Tan	Chipping/Flaking	5	10.8	Positive
1	1	110A	110A : Classroom 110 Coat Room	yes	W3	Sheetrock	Tan	Partially Inaccessible	N/A	0	Negative
1	1	110A	110A : Classroom 110 Coat Room	yes	Shelving	Wood	Brown	Partially Inaccessible	N/A	0	Negative
1	1	110A	110A : Classroom 110 Coat Room	yes	W4	Plaster	Tan	Partially Inaccessible		13.7	Positive

			<p style="text-align: center;">School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School</p>								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	110A	110A : Classroom 110 Coat Room	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110A	110A : Classroom 110 Coat Room	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	110C	110C : Men's Restroom	yes	W1	Plaster	Peach	None	0	N/A	N/A
1	1	110C	110C : Men's Restroom	yes	W2	CMU	Peach	None	0	N/A	N/A
1	1	110C	110C : Men's Restroom	yes	W3	Plaster	Peach	Efflorescence	4	3.83	Positive
1	1	110C	110C : Men's Restroom	yes	Radiator	Metal	Grey	Chipping/Flaking	4	0.09	Negative
1	1	110C	110C : Men's Restroom	yes	W4	Plaster	Peach	None	0	N/A	N/A
1	1	110C	110C : Men's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110C	110C : Men's Restroom	yes	Ceiling	Plaster	Peach	Flaking	50	5.32	Positive
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	W4	Plaster	Blue	Chipping	1	14.8	Positive
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	Spindles	Metal	Grey	Chipping	8	3.7	N/A
1	1	S-3	S-3 : Stairwell adjacent to Classroom 108	yes	Newel Posts	Metal	Grey	Chipping	4	4.98	N/A
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W1	Plaster	White	Cracking	2	0.01	Negative
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W2	Plaster	White	Cracking	2	0.02	Negative
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W3	Plaster	White	Cracking	25	0.01	Negative
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.07	Negative
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	W4	Plaster	White	Cracking	2	0.01	Negative
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1		Storage Closet in Hallway between Boy's Restroom and Stairwell	yes	Ceiling	Plaster	White	Cracking	2	0.01	Negative
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	W1	Metal	Brown	Chipping	6	0.09	Negative
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Pipe Outer Cover	Metal	Tan and White	Chipping	5	10.1	Positive
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Wall	Metal	Brown	Chipping	2	0.02	Negative
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Door	Metal	Brown	Chipping	10	0.01	Negative
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Covebase	Concrete	Brown	Chipping	2	0.04	Negative
1	1	H11	H11 : Hallway from Classrooms 108 to 110	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia								
			Lead Safe Certification Assessment Report								
			Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S14	S14 : Stairwell adjacent to Men's Restroom	yes	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	W2	Brick	White	None	0	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	Floor	Concrete	Brown	None	0	N/A	N/A
1	B	H03C	H03C : Entrance Vestibule near Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	W1	Brick	White	Chipping	2	0.1	Negative
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	W2	Brick	White	Chipping	4	0.43	Negative
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	W3	Brick	White	Partially Inaccessible	N/A	0.56	Negative
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	Shelving	Wood	White	Partially Inaccessible	N/A	0.01	Negative
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	001D	001D : Custodial Storage Room near Girl's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	W1	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	W2	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	W3	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	W4	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001E	001E : Custodial Storage Room near Girl's Restroom Storage Hatch below Stairs	no	Ceiling	Wood	N/A	N/A	N/A	N/A	N/A
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	W1	Brick	White	None	0	N/A	N/A
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	W2	Brick	White	Chipping	5	0.02	Negative
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	W3	Brick	White	Chipping/Flaking	2	0.05	Negative
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	W4	Brick	White	Chipping/Flaking	3	0.03	Negative
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	001C	001C : Service Closet adjacent to Girl's Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03B	H03B : Pipe Chase adjacent to Girl's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001	001 : Girl's Restroom	yes	W1	Brick	Tan	Chipping/Flaking	1	0.06	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	001	001 : Girl's Restroom	yes	W2	Brick	Tan	Chipping/Flaking	2	0.05	Negative
1	B	001	001 : Girl's Restroom	yes	W3	Brick	Tan	Chipping/Flaking	30	0.05	Negative
1	B	001	001 : Girl's Restroom	yes	W4	Brick	Tan	Flaking	75	0.09	Negative
1	B	001	001 : Girl's Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001	001 : Girl's Restroom	yes	Ceiling	Concrete	Tan	Flaking	12	0.06	Negative
1	B	001	001 : Girl's Restroom	yes	Pipes	Metal	Grey	Flaking	10	0.03	Negative
1	B	001	001 : Girl's Restroom	yes	Radiator	Metal	Grey	Flaking	12	0.01	Negative
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001A	001A : Girl's Restroom Sink Pipe Chase	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	001B	001B : Girl's Restroom Toilet Pipe Chase	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H03A	H03A : Closet between Classroom B2 and Girl's Restroom		Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	002	002 : Classroom B2	yes	W1	Plaster	White	Flaking/Broken	3	13.47	Positive
1	B	002	002 : Classroom B2	yes	W2	Plaster	White	Cracking/Flaking	5	15.61	Positive
1	B	002	002 : Classroom B2	yes	W3	Plaster	White	Spalling/Flaking	25	16.41	Positive
1	B	002	002 : Classroom B2	yes	Pipes	Metal	White	Chipping	10	0.03	Negative
1	B	002	002 : Classroom B2	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	002	002 : Classroom B2	yes	Floor	Wood	Varnish	Chipping	25	0.02	Negative
1	B	002	002 : Classroom B2	yes	Floor	Concrete	Brown	Chipping	20	0.03	Negative
1	B	002	002 : Classroom B2	yes	Plate	Metal	Brown	Chipping	20	0.03	Negative
1	B	002	002 : Classroom B2	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	002	002 : Classroom B2	yes	Radiator	Metal	Grey	Chipping	4	6.03	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	002A	002A : Classroom B2 Closet	yes	W1	Plaster	Tan	Partially Inaccessible/Cracking/Efflorescence	75	5.3	Positive
1	B	002A	002A : Classroom B2 Closet	yes	W2	Plaster	Tan	Efflorescence	25	6.83	Positive
1	B	002A	002A : Classroom B2 Closet	yes	W3	Plaster	Tan	Partially Inaccessible/Cracking	50	4.18	Positive
1	B	002A	002A : Classroom B2 Closet	yes	W4	Plaster	Tan	Partially Inaccessible/Cracking	20	4.82	Positive
1	B	002A	002A : Classroom B2 Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	002A	002A : Classroom B2 Closet	yes	Shelving	Wood	Varnish	Partially Inaccessible/Cracking	N/A	0.06	Negative
1	B	002A	002A : Classroom B2 Closet	yes	Ceiling	Plaster	Tan	Cracking	40	5.3	Positive
1	B	002A	002A : Classroom B2 Closet	yes	Radiator	Metal	White	Chipping	4	0.12	Negative
1	B	002B	002B : Classroom B2 Coat Room	yes	W1	Plaster	White	Flaking	3	12.9	Positive
1	B	002B	002B : Classroom B2 Coat Room	yes	W2	Plaster	White	Partially Inaccessible/Flaking	1	11.6	Positive
1	B	002B	002B : Classroom B2 Coat Room	yes	W3	Plaster	White	Flaking	3	14.4	Positive
1	B	002B	002B : Classroom B2 Coat Room	yes	W4	Plaster	White	Partially Inaccessible/Flaking	1	9.97	Positive
1	B	002B	002B : Classroom B2 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	002B	002B : Classroom B2 Coat Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	003	003 : Classroom B7	yes	Radiator	Metal	Grey	Chipping/Flaking	24	8.22	Positive
1	B	003	003 : Classroom B7	yes	Pipes	Metal	White	Flaking	4	0.01	Negative
1	B	003A	003A : Classroom B7 Coat Room	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	003A	003A : Classroom B7 Coat Room	yes	W2	Plaster	White	Flaking	4	12.93	Positive
1	B	003A	003A : Classroom B7 Coat Room	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	003A	003A : Classroom B7 Coat Room	yes	Pipe	Metal	White	Chipping/Flaking	3	2.89	Positive
1	B	003A	003A : Classroom B7 Coat Room	yes	W4	Plaster	White	Partially Inaccessible/Cracking	2	11.47	Positive
1	B	003A	003A : Classroom B7 Coat Room	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	003A	003A : Classroom B7 Coat Room	yes	Ceiling	Plaster	White	Alligatoring	50	5.47	Positive
1	B	003B	003B : Classroom B7 Storage Closet	yes	W1	Plaster	White	Flaking	40	5.25	Positive
1	B	003B	003B : Classroom B7 Storage Closet	yes	W2	Plaster	White	Partially Inaccessible/Flaking	10	5.07	Positive
1	B	003B	003B : Classroom B7 Storage Closet	yes	W3	Plaster	White	Partially Inaccessible/Flaking/Efflorescence	30	4.65	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	003B	003B : Classroom B7 Storage Closet	yes	W4	Plaster	White	Partially Inaccessible/Flaking/Ef floreescence	25	5.33	Positive
1	B	003B	003B : Classroom B7 Storage Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	003B	003B : Classroom B7 Storage Closet	yes	Ceiling	Plaster	White	Flaking	25	5.73	Positive
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	W1	Brick	White	None	0	N/A	N/A
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Doors and Frame	Metal	Brown	Chipping	8	0.01	Negative
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	W2	Brick	White	Chipping/Flaking	3	4.23	Positive
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Pipe outer Cover	Metal	Tan and White	Chipping/Flaking	4	3.55	Positive
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Tread	Concrete	Grey	Chipping	4	0.05	Negative
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Riser	Concrete	Grey	Chipping	2	0.12	Negative
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Hand Rail	Metal	Grey	Friction	12	0.08	Negative
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	W4	Brick	White	Chipping/Flaking	3	2.07	Positive
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Floor	Concrete	Brown	None	0	N/A	N/A
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H03	H03 : Hallway from Girl's Restroom to Classroom B7	yes	Radiator	Metal	White	Flaking	4	6.36	Positive
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	W2	Plaster	Purple	Chipping	2	12.45	Positive
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	W4	Plaster	Purple	Chipping/Flaking	2	14.61	Positive
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S02	S02 : Stairwell adjacent Classroom B7	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	W1	Brick	White	Chipping	1	8.24	Positive
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	W3	Brick	White	None	0	N/A	N/A
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	W4	Brick	White	Hole	1	3.08	Positive
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	Floor	Concrete	Brown	Chipping	3	0.08	Negative
1	B	H02	H02 : Hallway adjacent Boiler Room	yes	Ceiling	Plaster	White	Spalling/Flaking	25	4.39	Positive
1	B	004	004 : Library	yes	W1	Brick	White	None	0	N/A	N/A
1	B	004	004 : Library	yes	W2	Brick	White	None	0	N/A	N/A
1	B	004	004 : Library	yes	W3	Brick	White	None	0	N/A	N/A
1	B	004	004 : Library	yes	Pipe outer Cover	Metal	White	Chipping/Flaking	3	2.24	Positive
1	B	004	004 : Library	yes	W4	Brick	White	None	0	N/A	N/A
1	B	004	004 : Library	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	004	004 : Library	yes	Ceiling	Plaster	White	Flaking	6	0.12	Negative
1	B	004	004 : Library	yes	Radiator	Metal	White	Flaking	15	0.03	Negative
1	B	004A	004A : Library Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004A	004A : Library Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004A	004A : Library Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	004A	004A : Library Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004A	004A : Library Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004A	004A : Library Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004B	004B : Library Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	004C	004C : Former Library Gas Meter Room	no	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	B	004C	004C : Former Library Gas Meter Room	no	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004C	004C : Former Library Gas Meter Room	no	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	B	004C	004C : Former Library Gas Meter Room	no	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004C	004C : Former Library Gas Meter Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004C	004C : Former Library Gas Meter Room	no	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	W1	Brick	Tan	Partially Inaccessible		2.42	Positive
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	W2	Brick	Tan	Partially Inaccessible		2.43	Positive
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	W3	Brick	Tan	Partially Inaccessible		3.02	Positive
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	W4	Brick	Tan	Partially Inaccessible		2.42	Positive
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	Shelving	Wood	Varnish	Partially Inaccessible	N/A	0.06	Negative
1	B	004D	004D : Former Library Closet adjacent to Stairwell	yes	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	012	012 : Boiler Room	no	W1	Brick & Concrete	White/Grey/Green	Flaking	500	0.1	Negative
1	B	012	012 : Boiler Room	no	Pipes	Metal	White	Friction	20	0.03	Negative
1	B	012	012 : Boiler Room	no	W2	Brick & Concrete	White/Grey	Flaking	150	0.03	Negative
1	B	012	012 : Boiler Room	no	W3	Brick & Concrete	White/Grey	Flaking	100	0.08	Negative
1	B	012	012 : Boiler Room	no	W4	Concrete	White/Grey	Flaking	100	0.05	Negative
1	B	012	012 : Boiler Room	no	Floor	Concrete	Black/Grey/Yellow	Chipping	25	0.01	Negative
1	B	012	012 : Boiler Room	no	Stringer	Metal	Grey	Chipping	2	8.55	Positive
1	B	012	012 : Boiler Room	no	Treads	Metal	Grey	Friction	20	4.18	Positive
1	B	012	012 : Boiler Room	no	Hand Rail	Metal	Grey	Friction	12	9.34	Positive
1	B	012	012 : Boiler Room	no	Ceiling	Concrete	Grey	Flaking	150	0.01	Negative
1	B	012	012 : Boiler Room	no	Duct Work	Metal	Grey	Flaking	4	0.01	Negative
1	B	013	013 : Fan Room	no	W1	Concrete	Blue & White	Flaking	200	9.31	Positive
1	B	013	013 : Fan Room	no	Door	Wood	Blue	Chipping	6	0.06	Negative
1	B	013	013 : Fan Room	no	Door Frame	Wood	Blue	Chipping	6	0.04	Negative
1	B	013	013 : Fan Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	013	013 : Fan Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	013	013 : Fan Room	no	W4	Concrete	White & Green	Flaking	225	8.17	Positive
1	B	013	013 : Fan Room	no	Floor	Concrete	Grey	Chipping	25	0.23	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	013	013 : Fan Room	no	Fan Housing	Metal	Blue & grey	Flaking	100	0.09	Negative
1	B	013	013 : Fan Room	no	Ceiling	Concrete	White	Flaking	750	6.31	Positive
1	B	013	013 : Fan Room	no	Duct Work	Metal	White	Flaking	100	7.21	Positive
1	B	H04	H04 : Boiler Room Hallway/Passage	no	W1	Concrete	Blue	Flaking	6	0.02	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	W2	Brick & Concrete	White & Grey	Flaking	100	0.04	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	W3	Concrete	White & Grey	Flaking	20	0.03	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	Door	Wood	Grey	Chipping	2	0.02	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	W4	Concrete	White & Grey	Flaking	2	0.05	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	Door	Wood	Grey	Chipping	2	0.03	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	Floor	Concrete	Grey	Friction	10	0.01	Negative
1	B	H04	H04 : Boiler Room Hallway/Passage	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	H04	H04 : Boiler Room Hallway/Passage	no	Duct Work	Metal	White	Flaking	2	0.03	Negative
1	B	014	014 : Boiler Room Storage	no	W1	Concrete	White	Flaking	3	0.04	Negative
1	B	014	014 : Boiler Room Storage	no	Door and Frame	Wood	Green	Chipping	4	0.01	Negative
1	B	014	014 : Boiler Room Storage	no	W2	Concrete & Brick	White	Flaking	400	0.08	Negative
1	B	014	014 : Boiler Room Storage	no	W3	Concrete & Brick	White	Flaking	100	0.05	Negative
1	B	014	014 : Boiler Room Storage	no	W4	Concrete	White	Partially Inaccessible	N/A	0.03	Negative
1	B	014	014 : Boiler Room Storage	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	014	014 : Boiler Room Storage	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	014	014 : Boiler Room Storage	no	Duct Work	Metal	White	Chipping	1	0.03	Negative
1	B	016	016 : Oil Tank Room	no	W1	Concrete	White & Green	Chipping	4	0.04	Negative
1	B	016	016 : Oil Tank Room	no	Door and Frame	Wood	Green	Chipping	4	0.03	Negative
1	B	016	016 : Oil Tank Room	no	W2	Concrete & Brick	White & Green	Efflorescence	100	0.03	Negative
1	B	016	016 : Oil Tank Room	no	W3	Concrete & Brick	White & Green	Flaking	100	0.09	Negative
1	B	016	016 : Oil Tank Room	no	W4	Concrete & Brick	White & Green	Partially Inaccessible	N/A	0.03	Negative
1	B	016	016 : Oil Tank Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	016	016 : Oil Tank Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	016	016 : Oil Tank Room	no	Duct Work	Metal	White	Chipping	2	0.03	Negative
1	B	S05	S05 : Cafeteria Entrance Steps	yes	W1	Brick	Green and White	None	0	N/A	N/A
1	B	S05	S05 : Cafeteria Entrance Steps	yes	W2	Brick	Green and White	Hole	1	0.01	Negative
1	B	S05	S05 : Cafeteria Entrance Steps	yes	W3	Brick	Green and White	None	0	N/A	N/A
1	B	S05	S05 : Cafeteria Entrance Steps	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S05	S05 : Cafeteria Entrance Steps	yes	Floor	Concrete	Grey	Chipping	2	0.01	Negative
1	B	S05	S05 : Cafeteria Entrance Steps	yes	Tread	Concrete	Grey	Chipping	25	0.05	Negative
1	B	S05	S05 : Cafeteria Entrance Steps	yes	Riser	Concrete	Grey	Chipping	15	0.05	Negative
1	B	S05	S05 : Cafeteria Entrance Steps	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	W1	Brick	Green and White	None	0	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	W2	Brick	Green and White	None	0	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	006	006 : Cafeteria/Gym	yes	W3	Brick	Green and White	None	0	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	W4	Brick	Green and White	None	0	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	Plates	Metal	Blue	Friction	50	0.46	Negative
1	B	006	006 : Cafeteria/Gym	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	006	006 : Cafeteria/Gym	yes	Radiators	Metal	White	Flaking	100	4.12	Positive
1	B	006A	006A : Physical Education Office	yes	W1	Brick	White & Tan	Flaking	5	0.04	Negative
1	B	006A	006A : Physical Education Office	yes	W2	Brick	White & Tan	Partially Inaccessible	N/A	0.08	Negative
1	B	006A	006A : Physical Education Office	yes	W3	Brick	White & Tan	Partially Inaccessible	N/A	0.06	Negative
1	B	006A	006A : Physical Education Office	yes	Pipe	Metal	White & Tan	Flaking	N/A	0.1	Negative
1	B	006A	006A : Physical Education Office	yes	W4	Brick	White & Tan	Partially Inaccessible	N/A	0.09	Negative
1	B	006A	006A : Physical Education Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006A	006A : Physical Education Office	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	006A	006A : Physical Education Office	yes	Duct Work	Metal	White	Flaking	10	0.05	Negative
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	W1	Brick	White	Chipping	4	0.03	Negative
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	W2	Brick	White	Chipping/Flaking	15	0.04	Negative
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	W3	Brick	White	Chipping/Flaking	35	0.03	Negative
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	W4	Brick	White	Chipping/Flaking	30	0.03	Negative
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	Floor	Concrete	Grey	Chipping	10	2.39	Positive
1	B	H05	H05 : Cafeteria Exit Hallway to Outdoors	yes	Ceiling	Concrete	White	Flaking	12	15.1	Positive
1	B	006B	006B :Boy's and Girl's Club Office	yes	W1	Brick	White	Chipping/Flaking	8	0.04	Negative
1	B	006B	006B :Boy's and Girl's Club Office	yes	W2	Brick	Blue	None	0	N/A	N/A
1	B	006B	006B :Boy's and Girl's Club Office	yes	W3	Brick	Blue and White	Efflorescence/Flaking	125	0.04	Negative
1	B	006B	006B :Boy's and Girl's Club Office	yes	W4	Brick	White	Chipping/Flaking	10	0.03	Negative
1	B	006B	006B :Boy's and Girl's Club Office	yes	Pipe	Metal	Blue	Chipping/Flaking	4	0.04	Negative
1	B	006B	006B :Boy's and Girl's Club Office	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006B	006B :Boy's and Girl's Club Office	yes	Ceiling	Plaster	White	Efflorescence/Flaking	100	15.4	Positive
1	B	006B	006B :Boy's and Girl's Club Office	yes	Duct Work	Metal	White	Flaking	75	0.64	Negative
1	B	006C	006C : Cafeteria Storage	yes	W1	Brick	White	Partially Inaccessible	N/A	0.08	Negative
1	B	006C	006C : Cafeteria Storage	yes	W2	Brick	White	Partially Inaccessible	N/A	0.05	Negative
1	B	006C	006C : Cafeteria Storage	yes	W3	Brick	White	Partially Inaccessible	N/A	0.04	Negative
1	B	006C	006C : Cafeteria Storage	yes	W4	Brick	White	Partially Inaccessible	N/A	0.07	Negative
1	B	006C	006C : Cafeteria Storage	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006C	006C : Cafeteria Storage	yes	Ceiling	Plaster	White	Hole	1	0.1	Negative
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006D	006D : Cafeteria/Gym Electrical Room	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
Element	Floor	Space #	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	006E	006E : Cafeteria/Gym Pipe Chase	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	W3	Plaster	Blue	None	0	N/A	N/A
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	W4	Plaster	Blue	Chipping	2	13.31	Positive
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S03	S03 : Stairwell adjacent Kitchen	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	008	008 : Kitchen	yes	W1	Plaster	White	Chipping/Flaking	2	13.29	Positive
1	B	008	008 : Kitchen	yes	W2	Plaster	White	Chipping/Flaking	3	9.36	Positive
1	B	008	008 : Kitchen	yes	W3	Plaster	White	Chipping/Flaking	1	12.14	Positive
1	B	008	008 : Kitchen	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	008	008 : Kitchen	yes	Floor	Wood	Varnish	Friction	20	0.04	Negative
1	B	008	008 : Kitchen	yes	Plate	Metal	Grey	Friction	10	0.12	Negative
1	B	008	008 : Kitchen	yes	Ceiling	Plaster	White	Flaking	2	15.39	Positive
1	B	008	008 : Kitchen	yes	Radiators	Metal	White	Flaking	25	9.68	Positive
1	B	008A	008A : Kitchen Office	yes	W1	Plaster	White	Alligatoring	50	11.52	Positive
1	B	008A	008A : Kitchen Office	yes	W2	Plaster	White	Flaking	20	9.02	Positive
1	B	008A	008A : Kitchen Office	yes	W3	Plaster	White	Partially Inaccessible/Flaking	25	7.63	Positive
1	B	008A	008A : Kitchen Office	yes	W4	Plaster	White	Partially Inaccessible		9.52	Positive
1	B	008A	008A : Kitchen Office	yes	Floor	Wood	Varnish	Friction		0.06	Negative
1	B	008A	008A : Kitchen Office	yes	Plate	Metal	Grey	Friction		0.03	Negative
1	B	008A	008A : Kitchen Office	yes	Ceiling	Plaster	Blue	Flaking	5	5.3	Positive
1	B	008B	008B : Kitchen Storage	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	008B	008B : Kitchen Storage	yes	W2	Plaster	White	Partially Inaccessible/Flaking	6	11.71	Positive
1	B	008B	008B : Kitchen Storage	yes	W3	Plaster	White	Partially Inaccessible		4.75	Positive
1	B	008B	008B : Kitchen Storage	yes	W4	Plaster	White	Partially Inaccessible		8.44	Positive
1	B	008B	008B : Kitchen Storage	yes	Pipe	Metal	White	Chipping	3	12.37	Positive
1	B	008B	008B : Kitchen Storage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	008B	008B : Kitchen Storage	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	009	009 : Classroom B9	yes	W1	Plaster	White	Flaking	6	14.35	Positive
1	B	009	009 : Classroom B9	yes	W2	Plaster	White	Chipping/Flaking	15	13.24	Positive
1	B	009	009 : Classroom B9	yes	Pipe Outer Cover	Metal	Tan	Flaking	5	12.02	Positive
1	B	009	009 : Classroom B9	yes	W3	Plaster	White	Chipping/Flaking	4	11.92	Positive
1	B	009	009 : Classroom B9	yes	Pipe Outer Cover	Metal	White	Flaking	8	9.48	Positive

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	009	009 : Classroom B9	yes	Window Frames	Wood	Varnish	Chipping	4	0.1	Negative
1	B	009	009 : Classroom B9	yes	W4	Plaster	White	Chipping/Flaking	15	19.95	Positive
1	B	009	009 : Classroom B9	yes	Floor	Wood	Varnish	Friction	20	0.08	Negative
1	B	009	009 : Classroom B9	yes	Plate	Metal	Grey	Friction	20	3.62	Positive
1	B	009	009 : Classroom B9	yes	Ceiling	Plaster	White	Flaking	5	17.56	Positive
1	B	009	009 : Classroom B9	yes	Radiator	Metal	White	Flaking	20	9.76	Positive
1	B	009A	009A : Classroom B9 Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	B	009A	009A : Classroom B9 Restroom	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	B	009A	009A : Classroom B9 Restroom	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	B	009A	009A : Classroom B9 Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	B	009A	009A : Classroom B9 Restroom	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	009A	009A : Classroom B9 Restroom	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	W1	Wood	Varnish	None	0	N/A	N/A
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	W2	Brick	White	Flaking	4	0.02	Negative
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	W3	Brick	White	Flaking	4	0.05	Negative
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	Access Door	Metal	Grey	Flaking	4	0.14	Negative
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	W4	Brick	White	Flaking	4	0.02	Negative
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	H01A	H01A : Closet between Classroom B9 and Boy's Restroom	no	Ceiling	Concrete	White	Flaking	2	0.06	Negative
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	H01B	H01B : Pipe Chase outside Boy's Restroom	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	W1	Brick	Tan	None	0	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	Pipe	Metal	White	Flaking	4	0.09	Negative
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	W2	Brick	Tan	None	0	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	W3	Brick	Tan	None	0	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	W4	Brick	Tan	None	0	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010	010 : Boy's Restroom adjacent to Classroom B9	yes	Ceiling	Concrete	Tan	Flaking	10	0.12	Negative
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	W4	N/A	N/A	N/A	N/A	N/A	N/A

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010A	010A : Boy's Restroom Center Pipe Chase	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	010B	010B : Boy's Restroom Pipe Chase along Hallway Wall	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011B	011B : Storage Room Under Stairs	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	011B	011B : Storage Room Under Stairs	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	011B	011B : Storage Room Under Stairs	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	011B	011B : Storage Room Under Stairs	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	011B	011B : Storage Room Under Stairs	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	011B	011B : Storage Room Under Stairs	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	W1	Brick	White	Chipping	5	2.94	Positive
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Door and Frame	Metal	Brown	Chipping	5	0.01	Negative
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	W2	Brick	White	None	0	N/A	N/A
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Pipe Outer Cover	Metal	Grey	Chipping/Flaking	10	5.57	Positive
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	W3	Brick	White	Chipping	3	4.05	Positive
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Door and Frame	Metal	Brown	Chipping	5	0.08	Negative
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	W4	Brick	White	Flaking	3	1.21	Positive
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Floor	Concrete	Grey	Chipping	20	0.04	Negative
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Plate	Metal	Grey	Chipping	20	0.14	Negative
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Ceiling	Plaster	White	Efflorescence	50	6.08	Positive
1	B	H01	H01 : Hallway from Kitchen to Boy's Restroom	yes	Duct Work	Metal	White	Flaking	10	6.52	Positive
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Door & Frame	Metal	Brown	Chipping	3	0.01	Negative
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	W2	Plaster	Green	Cracking/Flaking	20	15.45	Positive
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Pipe Outer Cover	Metal	Brown & Green	Chipping	3	12.53	Positive
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	W4	Plaster	Green	None	0	N/A	N/A
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Floor	Concrete	Brown	Chipping	1	0.53	Negative
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Stringer	Concrete	Brown	Chipping	10	0.49	Negative
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Tread	Concrete	Brown	Chipping	30	0.58	Negative
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Riser	Concrete	Brown	Chipping	50	0.56	Negative
1	B	S04	S04 : Stairwell adjacent Boy's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	011	011 : Exit Foyer	yes	W1	Brick	Green & White	Flaking	1	2.12	Positive
1	B	011	011 : Exit Foyer	yes	W2	Brick	Green & White	Spalling/Flaking	8	3.24	Positive
1	B	011	011 : Exit Foyer	yes	Pipe	Metal	Brown	Chipping	3	0.07	Negative
1	B	011	011 : Exit Foyer	yes	W3	Brick	Green & White	Flaking	5	3.3	Positive
1	B	011	011 : Exit Foyer	yes	Door and Frame	Metal	Brown	Chipping	20	0.02	Negative

			School District of Philadelphia Lead Safe Certification Assessment Report Sullivan Elementary School								
			Name of Inspector: Paul Davis								
			Inspection Company: Vertex								
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	011	011 : Exit Foyer	yes	W4	Brick	Green & White	None	0	N/A	N/A
1	B	011	011 : Exit Foyer	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	011	011 : Exit Foyer	yes	Ceiling	Concrete	White	Flaking	20	4.57	Positive
1	B	011A	011A : Staff Restroom	yes	W1	Brick	Blue & White	Flaking	20	0.05	Negative
1	B	011A	011A : Staff Restroom	yes	W2	Brick	Blue & White	Flaking	20	0.08	Negative
1	B	011A	011A : Staff Restroom	yes	W3	Brick	Blue & White	Flaking	20	0.04	Negative
1	B	011A	011A : Staff Restroom	yes	Door	Wood	Blue	Cracking	4	0.15	Negative
1	B	011A	011A : Staff Restroom	yes	W4	Brick	Blue & White	Flaking	2	0.07	Negative
1	B	011A	011A : Staff Restroom	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	011A	011A : Staff Restroom	yes	Ceiling	Concrete	White	Flaking	25	0.04	Negative
1	B	011A	011A : Staff Restroom	yes	Radiator	Metal	White	Flaking	4	0.14	Negative
1	B	011C	011C : Staff Restroom Pipe Chase	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011C	011C : Staff Restroom Pipe Chase	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011C	011C : Staff Restroom Pipe Chase	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011C	011C : Staff Restroom Pipe Chase	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011C	011C : Staff Restroom Pipe Chase	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	011C	011C : Staff Restroom Pipe Chase	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT1	AT1 : Main Attic above 3rd Floor	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	AT	AT2	AT2 : Auditorium Attic	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	CS	CS1	CS1 : Crawl Space - None	no	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A