

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W1	CMU	Yellow	None	0	0	Negative
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W2	CMU	White	None	0	0.1	Negative
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W3	CMU	White	None	0	0.3	Negative
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	W4	CMU	White	None	0	0.2	Negative
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	100 A-1	Hallway outside of Cafeteria 113 and Auditorium 114	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	100A	Women's Staff Restroom across from Cafetorium	W1	CMU	White	None	0	0	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	Doorframe	Metal	Blue	Friction	1	0.5	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	W2	CMU	White	None	0	0.2	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	W3	CMU	White	None	0	0.1	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	100A	Women's Staff Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	100B	Men's Staff Restroom across from Cafetorium	W1	CMU	White	None	0	0.3	Negative
2	1	100B	Men's Staff Restroom across from Cafetorium	Doorframe	Metal	Blue	None	0	0.4	Negative
2	1	100B	Men's Staff Restroom across from Cafetorium	W2	CMU	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	100B	Men's Staff Restroom across from Cafetorium	W3	CMU	White	None	0	0.2	Negative
2	1	100B	Men's Staff Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
2	1	100B	Men's Staff Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.3	Negative
2	1	100B	Men's Staff Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.3	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	None	0	0.5	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Conduit	Metal	White	None	0	0.2	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Ceiling	Drywall	White	None	0	0.2	Negative
2	1	100C	Elevator Machine Room next to Front Entrance Reception/Waiting Area	Floor	Concrete	Grey	None	0	0	Negative
2	1	101	Front Entrance Vestibule	W1	CMU	White	None	0	0.1	Negative
2	1	101	Front Entrance Vestibule	W2	CMU	White	None	0	0.1	Negative
2	1	101	Front Entrance Vestibule	W3	Drywall	White	None	0	0	Negative
2	1	101	Front Entrance Vestibule	Door	Metal	Purple	None	0	0.1	Negative
2	1	101	Front Entrance Vestibule	W4	CMU	White	None	0	0	Negative
2	1	101	Front Entrance Vestibule	Ceiling	Drywall	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	101	Front Entrance Vestibule	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	102	Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.3	Negative
2	1	102	Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
2	1	102	Front Entrance Reception/Waiting Area	Conduit	Metal	Yellow	None	0	0.2	Negative
2	1	102	Front Entrance Reception/Waiting Area	W3	CMU	Yellow	None	0	0.2	Negative
2	1	102	Front Entrance Reception/Waiting Area	Column	Metal	Multi	None	0	0.3	Negative
2	1	102	Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.2	Negative
2	1	102	Front Entrance Reception/Waiting Area	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	102	Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	103	Main Office	W1	CMU	White	None	0	0.1	Negative
2	1	103	Main Office	W1	CMU	Brown	None	0	0.1	Negative
2	1	103	Main Office	W2	CMU	White	None	0	0.1	Negative
2	1	103	Main Office	W3	CMU	White	None	0	0.1	Negative
2	1	103	Main Office	W4	CMU	White	None	0	0.1	Negative
2	1	103	Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103	Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103A	Telecomm Room inside Main Office	W1	Wood	White	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	Doorframe	Metal	Blue	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	W2	Wood	White	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	W3	CMU	White	None	0	0.3	Negative
2	1	103A	Telecomm Room inside Main Office	Metal Panel	Metal	White	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	W4	CMU	White	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	Conduit	Metal	White	None	0	0.2	Negative
2	1	103A	Telecomm Room inside Main Office	Ceiling	Metal	White	None	0	0.1	Negative
2	1	103A	Telecomm Room inside Main Office	Insulation	Fiberglass	White	None	0	0.2	Negative
2	1	103A	Telecomm Room inside Main Office	Support Beam	Metal	White	None	0	0.5	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	103A	Telecomm Room inside Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	103B	Conference Room 103B inside Main Office	W1	CMU	White	None	0	0.1	Negative
2	1	103B	Conference Room 103B inside Main Office	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
2	1	103B	Conference Room 103B inside Main Office	Windowframe	Metal	Blue	None	0	0.1	Negative
2	1	103B	Conference Room 103B inside Main Office	W2	CMU	White	None	0	0.2	Negative
2	1	103B	Conference Room 103B inside Main Office	W3	CMU	White	None	0	0.2	Negative
2	1	103B	Conference Room 103B inside Main Office	W4	CMU	White	None	0	0	Negative
2	1	103B	Conference Room 103B inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103B	Conference Room 103B inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103C	Work Room 103C inside Main Office	W1	CMU	Brown	None	0	0.2	Negative
2	1	103C	Work Room 103C inside Main Office	W2	CMU	White	None	0	0.2	Negative
2	1	103C	Work Room 103C inside Main Office	W3	CMU	White	None	0	0.1	Negative
2	1	103C	Work Room 103C inside Main Office	Doorframe	Metal	Blue	Chipping	1	0.2	Negative
2	1	103C	Work Room 103C inside Main Office	W4	CMU	White	None	0	0.2	Negative
2	1	103C	Work Room 103C inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103C	Work Room 103C inside Main Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	103D	Counselor's Office 103D inside Main Office	W1	CMU	White	None	0	0.1	Negative
2	1	103D	Counselor's Office 103D inside Main Office	Doorframe	Metal	Blue	Chipping	2	0.1	Negative
2	1	103D	Counselor's Office 103D inside Main Office	W2	CMU	White	None	0	0.1	Negative
2	1	103D	Counselor's Office 103D inside Main Office	W3	CMU	White	None	0	0.2	Negative
2	1	103D	Counselor's Office 103D inside Main Office	W4	CMU	White	None	0	0	Negative
2	1	103D	Counselor's Office 103D inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103D	Counselor's Office 103D inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103E	Counselor's Office 103E inside Main Office	W1	CMU	White	None	0	0.1	Negative
2	1	103E	Counselor's Office 103E inside Main Office	Doorframe	Metal	Blue	None	0	0.3	Negative
2	1	103E	Counselor's Office 103E inside Main Office	W2	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	103E	Counselor's Office 103E inside Main Office	W3	CMU	White	None	0	0.2	Negative
2	1	103E	Counselor's Office 103E inside Main Office	W4	CMU	White	None	0	0	Negative
2	1	103E	Counselor's Office 103E inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103E	Counselor's Office 103E inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103F	Principal's Office 103F inside Main Office	W1	CMU	White	None	0	0.1	Negative
2	1	103F	Principal's Office 103F inside Main Office	Conduit	Metal	White	None	0	0.2	Negative
2	1	103F	Principal's Office 103F inside Main Office	Doorframe	Metal	Blue	Friction	3	0.2	Negative
2	1	103F	Principal's Office 103F inside Main Office	W2	CMU	White	None	0	0.1	Negative
2	1	103F	Principal's Office 103F inside Main Office	W3	CMU	White	None	0	0.2	Negative
2	1	103F	Principal's Office 103F inside Main Office	W4	CMU	White	None	0	0.2	Negative
2	1	103F	Principal's Office 103F inside Main Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103F	Principal's Office 103F inside Main Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103G	Principal's Office Closet	W1	CMU	White	None	0	0.2	Negative
2	1	103G	Principal's Office Closet	Doorframe	Metal	White	None	0	0.4	Negative
2	1	103G	Principal's Office Closet	W2	CMU	White	None	0	0.2	Negative
2	1	103G	Principal's Office Closet	Insulation	Fiberglass	White	None	0	0.1	Negative
2	1	103G	Principal's Office Closet	W3	CMU	White	None	0	0.1	Negative
2	1	103G	Principal's Office Closet	Shelf	Wood	White	None	0	0.3	Negative
2	1	103G	Principal's Office Closet	W4	CMU	White	None	0	0.3	Negative
2	1	103G	Principal's Office Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	103G	Principal's Office Closet	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	1	103H	Principal's Office Bathroom	W1	CMU	White	None	0	0.4	Negative
2	1	103H	Principal's Office Bathroom	Doorframe	Metal	Blue	None	0	0.1	Negative
2	1	103H	Principal's Office Bathroom	W2	CMU	White	None	0	0.1	Negative
2	1	103H	Principal's Office Bathroom	Insulation	Fiberglass	White	None	0	0.2	Negative
2	1	103H	Principal's Office Bathroom	W3	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	103H	Principal's Office Bathroom	W4	CMU	White	None	0	0	Negative
2	1	103H	Principal's Office Bathroom	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	103H	Principal's Office Bathroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	104	Girl's Student Restroom across from Cafetorium	W1	CMU	Yellow	None	0	0.1	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	W2	CMU	Yellow	None	0	0.2	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	W3	CMU	Yellow	None	0	0.2	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	W4	CMU	Yellow	None	0	0.1	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	Pipe	Metal	White	None	0	0.2	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	104	Girl's Student Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	105	Boy's Student Restroom across from Cafetorium	W1	CMU	White	None	0	0.2	Negative
2	1	105	Boy's Student Restroom across from Cafetorium	W2	CMU	White	None	0	0.2	Negative
2	1	105	Boy's Student Restroom across from Cafetorium	W3	CMU	White	None	0	0.3	Negative
2	1	105	Boy's Student Restroom across from Cafetorium	W4	CMU	White	None	0	0.1	Negative
2	1	105	Boy's Student Restroom across from Cafetorium	Ceiling	Drywall	White	None	0	0.2	Negative
2	1	105	Boy's Student Restroom across from Cafetorium	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	106	Family Student Resource Center across from Cafetorium	W1	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	106	Family Student Resource Center across from Cafetorium	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
2	1	106	Family Student Resource Center across from Cafetorium	W2	CMU	White	None	0	0.1	Negative
2	1	106	Family Student Resource Center across from Cafetorium	W3	CMU	White	None	0	0	Negative
2	1	106	Family Student Resource Center across from Cafetorium	W4	CMU	White	None	0	0	Negative
2	1	106	Family Student Resource Center across from Cafetorium	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	106	Family Student Resource Center across from Cafetorium	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	106A	Family Student Resource Center Restroom	W1	CMU	White	None	0	0.3	Negative
2	1	106A	Family Student Resource Center Restroom	Doorframe	Metal	Blue	None	0	0	Negative
2	1	106A	Family Student Resource Center Restroom	W2	CMU	White	None	0	0.2	Negative
2	1	106A	Family Student Resource Center Restroom	W3	CMU	White	None	0	0.1	Negative
2	1	106A	Family Student Resource Center Restroom	Pipe	Metal	White	None	0	0.3	Negative
2	1	106A	Family Student Resource Center Restroom	W4	CMU	White	None	0	0.2	Negative
2	1	106A	Family Student Resource Center Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
2	1	106A	Family Student Resource Center Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	107	Nurse's Office	W1	CMU	White	None	0	0.1	Negative
2	1	107	Nurse's Office	Doorframe	Metal	Blue	None	0	0.2	Negative
2	1	107	Nurse's Office	W2	CMU	White	None	0	0.2	Negative
2	1	107	Nurse's Office	W3	CMU	White	None	0	0.1	Negative
2	1	107	Nurse's Office	W4	CMU	White	None	0	0	Negative
2	1	107	Nurse's Office	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	107	Nurse's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	107A	Nurse's Office Restroom	W1	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	107A	Nurse's Office Restroom	Doorframe	Metal	Blue	Friction	4	0.2	Negative
2	1	107A	Nurse's Office Restroom	W2	CMU	White	None	0	0.2	Negative
2	1	107A	Nurse's Office Restroom	W3	CMU	White	None	0	0.2	Negative
2	1	107A	Nurse's Office Restroom	Pipe	Metal	White	None	0	0.3	Negative
2	1	107A	Nurse's Office Restroom	W4	CMU	White	None	0	0.2	Negative
2	1	107A	Nurse's Office Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	107A	Nurse's Office Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	108	Gym Teacher's Office	W1	CMU	White	None	0	0.1	Negative
2	1	108	Gym Teacher's Office	Doorframe	Metal	Blue	None	0	0	Negative
2	1	108	Gym Teacher's Office	W2	CMU	White	None	0	0.1	Negative
2	1	108	Gym Teacher's Office	W3	CMU	White	None	0	0.1	Negative
2	1	108	Gym Teacher's Office	Metal Panel	Metal	White	None	0	0.2	Negative
2	1	108	Gym Teacher's Office	W4	CMU	White	None	0	0.1	Negative
2	1	108	Gym Teacher's Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	108	Gym Teacher's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	108A	Gym Teacher's Office Restroom	W1	CMU	White	None	0	0.1	Negative
2	1	108A	Gym Teacher's Office Restroom	Doorframe	Metal	Blue	None	0	0.5	Negative
2	1	108A	Gym Teacher's Office Restroom	W2	CMU	White	None	0	0.2	Negative
2	1	108A	Gym Teacher's Office Restroom	W3	CMU	White	None	0	0.1	Negative
2	1	108A	Gym Teacher's Office Restroom	W4	CMU	White	None	0	0.3	Negative
2	1	108A	Gym Teacher's Office Restroom	Insulation	Fiberglass	White	None	0	0.2	Negative
2	1	108A	Gym Teacher's Office Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
2	1	108A	Gym Teacher's Office Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	109	Gymnasium	W1	CMU	White	Efflorescence	70	0.1	Negative
2	1	109	Gymnasium	Doorframe	Metal	Blue	Chipping	4	0.1	Negative
2	1	109	Gymnasium	Duct	Metal	White	Cracking	10	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	109	Gymnasium	W2	CMU	White	Flaking	4	0.1	Negative
2	1	109	Gymnasium	Pipe	Metal	White	None	0	0.3	Negative
2	1	109	Gymnasium	W3	CMU	White	None	0	0.2	Negative
2	1	109	Gymnasium	W4	CMU	White	None	0	0	Negative
2	1	109	Gymnasium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109	Gymnasium	Floor	Rubber	N/A	N/A	N/A	N/A	N/A
2	1	109A	Gymnasium Girl's Restroom	W1	CMU	White	None	0	0.2	Negative
2	1	109A	Gymnasium Girl's Restroom	Conduit	Metal	White	None	0	0.1	Negative
2	1	109A	Gymnasium Girl's Restroom	Doorframe	Metal	Blue	None	0	0	Negative
2	1	109A	Gymnasium Girl's Restroom	W2	CMU	White	None	0	0.1	Negative
2	1	109A	Gymnasium Girl's Restroom	W3	CMU	White	None	0	0.3	Negative
2	1	109A	Gymnasium Girl's Restroom	W4	CMU	White	None	0	0.1	Negative
2	1	109A	Gymnasium Girl's Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	109A	Gymnasium Girl's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	109B	Gymnasium Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
2	1	109B	Gymnasium Boy's Restroom	Conduit	Metal	White	None	0	0.1	Negative
2	1	109B	Gymnasium Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
2	1	109B	Gymnasium Boy's Restroom	W2	CMU	White	None	0	0.2	Negative
2	1	109B	Gymnasium Boy's Restroom	W3	CMU	White	None	0	0	Negative
2	1	109B	Gymnasium Boy's Restroom	W4	CMU	White	None	0	0.1	Negative
2	1	109B	Gymnasium Boy's Restroom	Ceiling	Drywall	White	None	0	0	Negative
2	1	109B	Gymnasium Boy's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
2	1	109C	Gym Equipment Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109C	Gym Equipment Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109C	Gym Equipment Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109C	Gym Equipment Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	109C	Gym Equipment Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109C	Gym Equipment Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	110	Shipping/Receiving Room next to Kitchen	W1	CMU	White	None	0	0.1	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	Conduit	Metal	White	None	0	0.1	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	Doorframe	Metal	Blue	Friction	5	0.1	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	W2	CMU	White	None	0	0.2	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	Insulation	Fiberglass	White	None	0	0.2	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	W3	CMU	White	None	0	0.1	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	W4	CMU	White	None	0	0.4	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	Ceiling	Metal	White	None	0	0.2	Negative
2	1	110	Shipping/Receiving Room next to Kitchen	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	110A	Shipping/Receiving Room Restroom	W1	CMU	White	None	0	0.2	Negative
2	1	110A	Shipping/Receiving Room Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative
2	1	110A	Shipping/Receiving Room Restroom	W2	CMU	White	None	0	0	Negative
2	1	110A	Shipping/Receiving Room Restroom	W3	CMU	White	None	0	0	Negative
2	1	110A	Shipping/Receiving Room Restroom	W4	CMU	White	None	0	0.2	Negative
2	1	110A	Shipping/Receiving Room Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	110A	Shipping/Receiving Room Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	110B	Building Engineer's Office	W1	CMU	White	None	0	0.1	Negative
2	1	110B	Building Engineer's Office	Doorframe	Metal	Blue	Friction	2	0.4	Negative
2	1	110B	Building Engineer's Office	W2	CMU	White	None	0	0	Negative
2	1	110B	Building Engineer's Office	W3	CMU	White	None	0	0.1	Negative
2	1	110B	Building Engineer's Office	W4	CMU	White	None	0	0.1	Negative
2	1	110B	Building Engineer's Office	Insulation	Fiberglass	White	None	0	0.2	Negative
2	1	110B	Building Engineer's Office	Ceiling	Metal	White	None	0	0.2	Negative
2	1	110B	Building Engineer's Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	111	Kitchen 111	W1	CMU	White	None	0	0.1	Negative
2	1	111	Kitchen 111	Doorframe	Metal	Blue	None	0	0.2	Negative
2	1	111	Kitchen 111	W2	CMU	White	None	0	0	Negative
2	1	111	Kitchen 111	pipe	Metal	White	Chipping	4	0.2	Negative
2	1	111	Kitchen 111	W3	CMU	White	None	0	0.1	Negative
2	1	111	Kitchen 111	W4	CMU	White	None	0	0.1	Negative
2	1	111	Kitchen 111	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	111	Kitchen 111	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	111A	Kitchen Storage Closet	W1	CMU	White	None	0	0.1	Negative
2	1	111A	Kitchen Storage Closet	Doorframe	Metal	Blue	None	0	0.2	Negative
2	1	111A	Kitchen Storage Closet	W2	CMU	White	None	0	0	Negative
2	1	111A	Kitchen Storage Closet	W3	CMU	White	None	0	0.1	Negative
2	1	111A	Kitchen Storage Closet	W4	CMU	White	None	0	0	Negative
2	1	111A	Kitchen Storage Closet	Conduit	Plastic	White	None	0	0.1	Negative
2	1	111A	Kitchen Storage Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	111A	Kitchen Storage Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	111B	Kitchen Office	W1	CMU	White	None	0	0.1	Negative
2	1	111B	Kitchen Office	Doorframe	Metal	Blue	None	0	0.2	Negative
2	1	111B	Kitchen Office	door	Metal	Blue	None	0	0.2	Negative
2	1	111B	Kitchen Office	W2	CMU	White	None	0	0	Negative
2	1	111B	Kitchen Office	W3	CMU	White	None	0	0	Negative
2	1	111B	Kitchen Office	W4	CMU	White	None	0	0.1	Negative
2	1	111B	Kitchen Office	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	111B	Kitchen Office	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	111C	Kitchen Office Restroom	W1	CMU	White	None	0	0.1	Negative
2	1	111C	Kitchen Office Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	111C	Kitchen Office Restroom	W2	CMU	White	None	0	0.2	Negative
2	1	111C	Kitchen Office Restroom	W3	CMU	White	None	0	0.2	Negative
2	1	111C	Kitchen Office Restroom	W4	CMU	White	None	0	0.1	Negative
2	1	111C	Kitchen Office Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	111C	Kitchen Office Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	112	Cafeteria Serving Line	W1	Drywall	White	None	0	0.2	Negative
2	1	112	Cafeteria Serving Line	door	Metal	Blue	Friction	1	0.3	Negative
2	1	112	Cafeteria Serving Line	Doorframe	Metal	Blue	Friction	3	0	Negative
2	1	112	Cafeteria Serving Line	W2	CMU	Green	None	0	0	Negative
2	1	112	Cafeteria Serving Line	W3	CMU	Green	None	0	0.2	Negative
2	1	112	Cafeteria Serving Line	W4	CMU	Green	None	0	0	Negative
2	1	112	Cafeteria Serving Line	Ceiling	Drywall	Green	None	0	0.2	Negative
2	1	112	Cafeteria Serving Line	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	113	Cafeteria	W1	CMU	White	None	0	0.1	Negative
2	1	113	Cafeteria	Doorframe	Metal	Blue	Friction	4	0	Negative
2	1	113	Cafeteria	W2	CMU	Green	None	0	0.1	Negative
2	1	113	Cafeteria	W3	CMU	White	None	0	0.1	Negative
2	1	113	Cafeteria	W4	CMU	White	None	0	0.1	Negative
2	1	113	Cafeteria	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	113	Cafeteria	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	113A	Cafeteria Storage Room	W1	CMU	White	None	0	0.1	Negative
2	1	113A	Cafeteria Storage Room	Doorframe	Metal	Blue	None	0	0.3	Negative
2	1	113A	Cafeteria Storage Room	W2	CMU	White	None	0	0.1	Negative
2	1	113A	Cafeteria Storage Room	W3	CMU	White	None	0	0.2	Negative
2	1	113A	Cafeteria Storage Room	pipe	Metal	White	None	0	0.2	Negative
2	1	113A	Cafeteria Storage Room	W4	CMU	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	113A	Cafeteria Storage Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	1	113A	Cafeteria Storage Room	Floor	Concrete	Blue	Friction	10	0.5	Negative
2	1	114	Auditorium	W1	CMU	White	None	0	0.1	Negative
2	1	114	Auditorium	W2	CMU	White	None	0	0.1	Negative
2	1	114	Auditorium	W3	CMU	White	None	0	0.1	Negative
2	1	114	Auditorium	Conduit	Plaster	White	None	0	0.1	Negative
2	1	114	Auditorium	W4	CMU	White	None	0	0.1	Negative
2	1	114	Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	114	Auditorium	Floor	Concrete	Blue	None	0	0.1	Negative
2	1	115	Auditorium Stage	W1	CMU	White	None	0	0.1	Negative
2	1	115	Auditorium Stage	Conduit	Metal	White	None	0	0	Negative
2	1	115	Auditorium Stage	W2	CMU	Black	None	0	0.2	Negative
2	1	115	Auditorium Stage	W3	CMU	Black	None	0	0	Negative
2	1	115	Auditorium Stage	pipe	Metal	Black	None	0	0.2	Negative
2	1	115	Auditorium Stage	W4	CMU	Black	None	0	0.2	Negative
2	1	115	Auditorium Stage	Ceiling	Drywall	White	None	0	0.1	Negative
2	1	115	Auditorium Stage	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W2	N/A	N/A	N/A	N/A	N/A	N/A
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	CAB1	Elevator 1 next to Front Entrance Reception/Waiting Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	Friction	3	0.2	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	pipe	Metal	Red	None	0	0.2	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Pan	Metal	White	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Post	Metal	Blue	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Railing	Metal	Blue	None	0	0.2	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Stringer	Metal	White	None	0	1.1	Positive
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Ceiling	Metal	White	None	0	0.4	Negative
2	1	Stair A-1	Stairwell A-1 next to Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W1	CMU	White	None	0	0	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Doorframe	Metal	Blue	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W2	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W3	CMU	White	None	0	0.3	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	pipe	Metal	Red	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	W4	CMU	White	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Post	Metal	Blue	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Railing	Metal	Blue	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Stringer	Metal	White	None	0	0.3	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Ceiling	Metal	White	None	0	0.1	Negative
2	1	Stair B-1	Stairwell B-1 next to Front Entrance Reception/Waiting Area	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	200 A-1	Hallway outside of Library 202	W1	CMU	White	None	0	0.1	Negative
2	2	200 A-1	Hallway outside of Library 202	Doorframe	Metal	Blue	None	0	0.1	Negative
2	2	200 A-1	Hallway outside of Library 202	W2	CMU	Blue	None	0	0.1	Negative
2	2	200 A-1	Hallway outside of Library 202	Windowframe	Metal	Blue	None	0	0.1	Negative
2	2	200 A-1	Hallway outside of Library 202	W3	CMU	Blue	None	0	0	Negative
2	2	200 A-1	Hallway outside of Library 202	W4	CMU	White	None	0	0	Negative
2	2	200 A-1	Hallway outside of Library 202	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	200 A-1	Hallway outside of Library 202	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	201	Conference Room 201	W1	CMU	White	None	0	0.4	Negative
2	2	201	Conference Room 202	Doorframe	Metal	Blue	None	0	0.1	Negative
2	2	201	Conference Room 201	W2	CMU	White	None	0	0	Negative
2	2	201	Conference Room 201	W3	CMU	White	None	0	0	Negative
2	2	201	Conference Room 201	W4	CMU	White	None	0	0.4	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	2	201	Conference Room 202	Column	CMU	White	None	0	0	Negative
2	2	201	Conference Room 201	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	201	Conference Room 201	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	202	Library	W1	CMU	Yellow	None	0	0.1	Negative
2	2	202	Library	Doorframe	Metal	Blue	Chipping	4	0.4	Negative
2	2	202	Library	W2	CMU	Yellow	None	0	0.2	Negative
2	2	202	Library	Conduit	Metal	Yellow	None	0	0.1	Negative
2	2	202	Library	Windowframe	Metal	Blue	None	0	0.1	Negative
2	2	202	Library	W3	CMU	White	None	0	0.1	Negative
2	2	202	Library	W4	CMU	Yellow	None	0	0.2	Negative
2	2	202	Library	Column	CMU	Blue	None	0	0.1	Negative
2	2	202	Library	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	202	Library	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
2	2	202A	Library Storage Room	W1	CMU	White	None	0	0	Negative
2	2	202A	Library Storage Room	Doorframe	Metal	Blue	None	0	0.5	Negative
2	2	202A	Library Storage Room	Windowframe	Metal	Blue	None	0	0	Negative
2	2	202A	Library Storage Room	W2	CMU	White	None	0	0	Negative
2	2	202A	Library Storage Room	W3	CMU	White	None	0	0.1	Negative
2	2	202A	Library Storage Room	W4	CMU	White	None	0	0.1	Negative
2	2	202A	Library Storage Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	202A	Library Storage Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	203	Computer Classroom 203	W1	CMU	White	None	0	0.1	Negative
2	2	203	Computer Classroom 203	Doorframe	Metal	Blue	Chipping	3	0.4	Negative
2	2	203	Computer Classroom 203	Conduit	Metal	White	None	0	0.2	Negative
2	2	203	Computer Classroom 203	W2	CMU	Green	None	0	0	Negative
2	2	203	Computer Classroom 203	W3	CMU	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	2	203	Computer Classroom 203	W4	CMU	White	None	0	0	Negative
2	2	203	Computer Classroom 203	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	203	Computer Classroom 203	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	203B	Electrical Room 203B	W1	CMU	White	None	0	0.1	Negative
2	2	203B	Electrical Room 203B	Doorframe	Metal	Blue	None	0	0.1	Negative
2	2	203B	Electrical Room 203B	W2	CMU	White	None	0	0.1	Negative
2	2	203B	Electrical Room 203B	W3	CMU	White	None	0	0.1	Negative
2	2	203B	Electrical Room 203B	Conduit	Metal	White	None	0	0.2	Negative
2	2	203B	Electrical Room 203B	W4	CMU	White	None	0	0.1	Negative
2	2	203B	Electrical Room 203B	Stairs	Wood	Grey	Chipping	2	0.3	Negative
2	2	203B	Electrical Room 203B	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	203B	Electrical Room 203B	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	2	Stair A-2	Stairwell A-2 next to Library 202	W1	CMU	White	None	0	0.1	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	W2	CMU	White	None	0	0	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	Railing	Metal	Blue	None	0	0	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	Post	Metal	Blue	None	0	0	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	Stringer	Metal	White	None	0	0.3	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	W3	CMU	White	None	0	0.1	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	W4	CMU	White	None	0	0.1	Negative
2	2	Stair A-2	Stairwell A-2 next to Library 202	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	Stair A-2	Stairwell A-2 next to Library 202	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W1	CMU	White	None	0	0.2	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Doorframe	Metal	Blue	None	0	0	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Railing	Metal	Blue	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Post	Metal	Blue	None	0	0.1	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Stringer	Metal	White	None	0	0.3	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W2	CMU	White	None	0	0.1	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W3	CMU	White	None	0	0.1	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	W4	CMU	White	None	0	0.1	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Pipe	Metal	Red	None	0	0.2	Negative
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
2	2	Stair B-2	Stairwell B-2 next to Computer Classroom 203	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W2	CMU	White	None	0	0.1	Negative
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W3	CMU	Yellow	None	0	0.4	Negative
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	W4	CMU	Yellow	None	0	0.2	Negative
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	100 B-1	Hallway outside of Music Classroom 116 to Stairwell D-1	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Doorframe	Metal	Blue	Friction	2	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W2	CMU	White	None	0	0.4	Negative
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	W4	CMU	White	None	0	0.1	Negative
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	100 B-2	Hallway between Classroom 123 and Exterior Courtyard	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	100 B-3	Hallway from Classrooms 124 - 126	W1	CMU	White	None	0	0	Negative
3	1	100 B-3	Hallway from Classrooms 124 - 126	W2	CMU	Yellow	None	0	0	Negative
3	1	100 B-3	Hallway from Classrooms 124 - 126	W3	CMU	White	None	0	0	Negative
3	1	100 B-3	Hallway from Classrooms 124 - 126	W4	CMU	Yellow	None	0	0	Negative
3	1	100 B-3	Hallway from Classrooms 124 - 126	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	100 B-3	Hallway from Classrooms 124 - 126	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W1	CMU	White	None	0	0.1	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	door	Metal	Blue	None	0	0	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Doorframe	Metal	Blue	None	0	0.1	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W2	CMU	White	None	0	0	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W3	CMU	White	None	0	0.3	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Railing	Metal	Blue	Flaking	10	0.1	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Post	Metal	Blue	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Stringer	Metal	White	None	0	0	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	W4	CMU	White	None	0	0.1	Negative
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	100 B-4	Hallway with Ramp between Gymnasium and Kindergarten Wing	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	100D	Elevator Machine Room next to Elevator 2	W1	CMU	White	None	0	0.3	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	Doorframe	Metal	Blue	None	0	0.1	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	W2	CMU	White	None	0	0.1	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	W3	CMU	White	None	0	0.2	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	Conduit	Metal	White	None	0	0.1	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	W4	CMU	White	None	0	0.2	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	Ceiling	Metal	White	None	0	0.1	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	Duct	Metal	White	None	0	0.1	Negative
3	1	100D	Elevator Machine Room next to Elevator 2	Floor	Concrete	Grey	None	0	0.4	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	W1	CMU	White	None	0	0.1	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	Doorframe	Metal	Blue	None	0	0.3	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	W2	CMU	White	None	0	0.2	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	W3	CMU	White	None	0	0	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	W4	CMU	White	None	0	0.1	Negative
3	1	100E	Women's Restroom between Classrooms 125 and 126	Ceiling	Drywall	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	100E	Women's Restroom between Classrooms 125 and 126	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	100F	Men's Restroom next to Classroom 124	W1	CMU	White	None	0	0.1	Negative
3	1	100F	Men's Restroom next to Classroom 124	Doorframe	Metal	Blue	None	0	0.3	Negative
3	1	100F	Men's Restroom next to Classroom 124	W2	CMU	White	None	0	0.2	Negative
3	1	100F	Men's Restroom next to Classroom 124	W3	CMU	White	None	0	0	Negative
3	1	100F	Men's Restroom next to Classroom 124	W4	CMU	White	None	0	0.1	Negative
3	1	100F	Men's Restroom next to Classroom 124	Ceiling	Drywall	White	None	0	0	Negative
3	1	100F	Men's Restroom next to Classroom 124	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	116	Special Ed Classroom 116	W1	CMU	White	None	0	0.3	Negative
3	1	116	Special Ed Classroom 116	Doorframe	Metal	Blue	None	0	0.3	Negative
3	1	116	Special Ed Classroom 116	W2	CMU	White	None	0	0	Negative
3	1	116	Special Ed Classroom 116	W3	CMU	Yellow	None	0	0.1	Negative
3	1	116	Special Ed Classroom 116	W4	CMU	White	None	0	0	Negative
3	1	116	Special Ed Classroom 116	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	116	Special Ed Classroom 116	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	117	Office 117 between Classroom 116 and Music Room	W1	CMU	White	None	0	0.1	Negative
3	1	117	Office 117 between Classroom 116 and Music Room	Doorframe	Metal	Blue	Chipping	2	0.2	Negative
3	1	117	Office 117 between Classroom 116 and Music Room	W2	CMU	White	None	0	0	Negative
3	1	117	Office 117 between Classroom 116 and Music Room	W3	CMU	White	None	0	0.1	Negative
3	1	117	Office 117 between Classroom 116 and Music Room	W4	CMU	Blue	None	0	0	Negative
3	1	117	Office 117 between Classroom 116 and Music Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	117	Office 117 between Classroom 116 and Music Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	118	Exit Vestibule between Classrooms 116 and 118	W1	CMU	White	None	0	0.1	Negative
3	1	118	Exit Vestibule between Classrooms 116 and 118	Doorframe	Metal	Blue	None	0	0.6	Negative
3	1	118	Exit Vestibule between Classrooms 116 and 118	W2	CMU	White	None	0	0.2	Negative
3	1	118	Exit Vestibule between Classrooms 116 and 118	W3	CMU	White	None	0	0.1	Negative
3	1	118	Exit Vestibule between Classrooms 116 and 118	W4	CMU	White	None	0	0.2	Negative
3	1	118	Exit Vestibule between Classrooms 116 and 118	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	118	Exit Vestibule between Classrooms 116 and 118	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	119	Music Room next to Boiler Room	W1	CMU	White	None	0	0.1	Negative
3	1	119	Music Room next to Boiler Room	Doorframe	Metal	Blue	Friction	5	0.5	Negative
3	1	119	Music Room next to Boiler Room	W2	CMU	White	None	0	0	Negative
3	1	119	Music Room next to Boiler Room	W3	CMU	Yellow	None	0	0	Negative
3	1	119	Music Room next to Boiler Room	W4	CMU	White	None	0	0	Negative
3	1	119	Music Room next to Boiler Room	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	119	Music Room next to Boiler Room	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	119A	Music Room Closet	W1	CMU	White	None	0	0.1	Negative
3	1	119A	Music Room Closet	Doorframe	Metal	Blue	None	0	0.3	Negative
3	1	119A	Music Room Closet	W2	CMU	White	None	0	0.2	Negative
3	1	119A	Music Room Closet	W3	CMU	White	None	0	0.1	Negative
3	1	119A	Music Room Closet	W4	CMU	White	None	0	0	Negative
3	1	119A	Music Room Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	119A	Music Room Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	120	Boiler Room 120	W1	CMU	White	None	0	0	Negative
3	1	120	Boiler Room 120	Doorframe	Metal	Blue	Friction	1	0.5	Negative
3	1	120	Boiler Room 120	W2	CMU	White	None	0	0.1	Negative
3	1	120	Boiler Room 120	W3	CMU	White	None	0	0.1	Negative
3	1	120	Boiler Room 120	W4	CMU	White	None	0	0.1	Negative
3	1	120	Boiler Room 120	Conduit	Metal	White	Chipping	4	0.3	Negative
3	1	120	Boiler Room 120	Ceiling	Metal	White	None	0	0.1	Negative
3	1	120	Boiler Room 120	Floor	Concrete	Grey	Friction	75	0.2	Negative
3	1	121	Electrical Room 121	W1	CMU	White	None	0	0.2	Negative
3	1	121	Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
3	1	121	Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
3	1	121	Electrical Room 121	W2	CMU	White	None	0	0	Negative
3	1	121	Electrical Room 121	W3	CMU	White	None	0	0	Negative
3	1	121	Electrical Room 121	W4	CMU	White	None	0	0	Negative
3	1	121	Electrical Room 121	Ceiling	Metal	White	None	0	0.1	Negative
3	1	121	Electrical Room 121	pipe	Metal	Red	None	0	0.1	Negative
3	1	121	Electrical Room 121	Conduit	Metal	White	None	0	0.1	Negative
3	1	121	Electrical Room 121	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	122	Fire Pump Room 122	W1	CMU	White	None	0	0	Negative
3	1	122	Fire Pump Room 122	Doorframe	Metal	Blue	None	0	0.1	Negative
3	1	122	Fire Pump Room 122	door	Metal	Blue	None	0	0.2	Negative
3	1	122	Fire Pump Room 122	W2	CMU	White	None	0	0.2	Negative
3	1	122	Fire Pump Room 122	W3	CMU	White	None	0	0.2	Negative
3	1	122	Fire Pump Room 122	pipe	Metal	White	None	0	0.1	Negative
3	1	122	Fire Pump Room 122	W4	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	122	Fire Pump Room 122	Ceiling	Metal	White	Flaking	2	0.2	Negative
3	1	122	Fire Pump Room 122	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	123	Classroom 123	W1	CMU	White	None	0	0.1	Negative
3	1	123	Classroom 123	Doorframe	Metal	Blue	Friction	1	0.2	Negative
3	1	123	Classroom 123	W2	CMU	White	None	0	0.1	Negative
3	1	123	Classroom 123	W3	CMU	White	None	0	0	Negative
3	1	123	Classroom 123	W4	CMU	White	None	0	0.1	Negative
3	1	123	Classroom 123	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	123	Classroom 123	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	123A	Classroom 123 Restroom	W1	CMU	White	None	0	0.2	Negative
3	1	123A	Classroom 123 Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
3	1	123A	Classroom 123 Restroom	W2	CMU	White	None	0	0.1	Negative
3	1	123A	Classroom 123 Restroom	W3	CMU	White	None	0	0.1	Negative
3	1	123A	Classroom 123 Restroom	W4	CMU	White	None	0	0.1	Negative
3	1	123A	Classroom 123 Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
3	1	123A	Classroom 123 Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	124	Classroom 124	W1	CMU	White	None	0	0.1	Negative
3	1	124	Classroom 124	Doorframe	Metal	Blue	Friction	2	0.4	Negative
3	1	124	Classroom 124	W2	CMU	White	None	0	0.1	Negative
3	1	124	Classroom 124	W3	CMU	White	None	0	0.2	Negative
3	1	124	Classroom 124	W4	CMU	White	None	0	0.1	Negative
3	1	124	Classroom 124	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	124	Classroom 124	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	124A	Classroom 124 Restroom	W1	CMU	White	None	0	0.1	Negative
3	1	124A	Classroom 124 Restroom	Doorframe	Metal	Blue	None	0	0.1	Negative
3	1	124A	Classroom 124 Restroom	W2	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	124A	Classroom 124 Restroom	W3	CMU	White	None	0	0.2	Negative
3	1	124A	Classroom 124 Restroom	W4	CMU	White	None	0	0	Negative
3	1	124A	Classroom 124 Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
3	1	124A	Classroom 124 Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	125	Classroom 125	W1	CMU	White	None	0	0	Negative
3	1	125	Classroom 125	Doorframe	Metal	Blue	Friction	4	0.2	Negative
3	1	125	Classroom 125	W2	CMU	White	None	0	0.1	Negative
3	1	125	Classroom 125	W3	CMU	White	None	0	0	Negative
3	1	125	Classroom 125	W4	CMU	White	None	0	0.1	Negative
3	1	125	Classroom 125	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	125	Classroom 125	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	125A	Classroom 125 Restroom	W1	CMU	White	None	0	0.1	Negative
3	1	125A	Classroom 125 Restroom	Doorframe	Metal	Blue	Friction	1	0.4	Negative
3	1	125A	Classroom 125 Restroom	W2	CMU	White	None	0	0.1	Negative
3	1	125A	Classroom 125 Restroom	W3	CMU	White	None	0	0.3	Negative
3	1	125A	Classroom 125 Restroom	W4	CMU	White	None	0	0.1	Negative
3	1	125A	Classroom 125 Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
3	1	125A	Classroom 125 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	126	Classroom 126	W1	CMU	White	None	0	0.2	Negative
3	1	126	Classroom 126	Doorframe	Metal	Blue	Friction	3	0.1	Negative
3	1	126	Classroom 126	W2	CMU	White	None	0	0.2	Negative
3	1	126	Classroom 126	W3	CMU	White	None	0	0.3	Negative
3	1	126	Classroom 126	W4	CMU	White	None	0	0.1	Negative
3	1	126	Classroom 126	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	126	Classroom 126	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	126A	Classroom 126 Restroom	W1	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	126A	Classroom 126 Restroom	Doorframe	Metal	Blue	Friction	3	0.1	Negative
3	1	126A	Classroom 126 Restroom	W2	CMU	White	None	0	0.1	Negative
3	1	126A	Classroom 126 Restroom	W3	CMU	White	None	0	0.1	Negative
3	1	126A	Classroom 126 Restroom	W4	CMU	White	None	0	0	Negative
3	1	126A	Classroom 126 Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
3	1	126A	Classroom 126 Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W2	CMU	White	None	0	0.1	Negative
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	W4	CMU	White	None	0	0.1	Negative
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	127	Entrance Vestibule between Stairwell C-1 and Kindergarten Wing	Floor	Carpet	N/A	N/A	N/A	N/A	N/A
3	1	129	Classroom 127	W1	CMU	White	None	0	0.1	Negative
3	1	129	Classroom 127	Doorframe	Metal	Blue	Friction	2	0.1	Negative
3	1	129	Classroom 127	W2	CMU	White	None	0	0.1	Negative
3	1	129	Classroom 127	W3	CMU	White	None	0	0	Negative
3	1	129	Classroom 127	W4	CMU	Yellow	None	0	0.2	Negative
3	1	129	Classroom 127	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	129	Classroom 127	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	130	Office next to Classroom 127	W1	CMU	White	None	0	0	Negative
3	1	130	Office next to Classroom 127	Doorframe	Metal	Blue	None	0	0.1	Negative
3	1	130	Office next to Classroom 127	W2	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	130	Office next to Classroom 127	W3	CMU	White	None	0	0	Negative
3	1	130	Office next to Classroom 127	W4	CMU	White	None	0	0.2	Negative
3	1	130	Office next to Classroom 127	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	130	Office next to Classroom 127	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	W1	CMU	White	None	0	0	Negative
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	Doorframe	Metal	Blue	Friction	1	0.3	Negative
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	W2	CMU	White	None	0	0	Negative
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	W3	CMU	White	None	0	0	Negative
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	W4	CMU	White	None	0	0.2	Negative
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	1	131	Faculty Lounge next to Kindergarten Wing double doors	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	1	CAB2	Elevator 2 across from Classroom 116	Floor	N/A	N/A	N/A	N/A	N/A	N/A
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W1	CMU	White	None	0	0	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Doorframe	Metal	Blue	None	0	0.5	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W2	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Railing	Metal	Blue	None	0	0.1	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Post	Metal	Blue	None	0	0.1	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Stringer	Metal	White	None	0	0.3	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Stair Pan	Metal	White	None	0	0.6	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	pipe	Metal	Red	None	0	0	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W3	CMU	White	None	0	0.2	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	W4	CMU	White	None	0	0	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Ceiling	Metal	White	None	0	0.2	Negative
3	1	Stair C-1	Stairwell C-1 between Gymnasium and Kindergarten Wing	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W1	CMU	White	None	0	0.1	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Doorframe	Metal	Blue	None	0	0.2	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W2	CMU	White	None	0	0.1	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Railing	Metal	Blue	Flaking	40	0.1	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Post	Metal	Blue	None	0	0.1	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Stringer	Metal	White	None	0	0.3	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Stair Pan	Metal	White	None	0	0.2	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	pipe	Metal	Red	None	0	0.1	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W3	CMU	White	None	0	0.4	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	W4	CMU	White	None	0	0.2	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Ceiling	Metal	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Duct Insulation	Fiberglass	White	None	0	0	Negative
3	1	Stair D-1	Stairwell D-1 next to Electrical Room 121	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200 B-1	Hallway outside of Classrooms 204 -207	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	2	200 B-1	Hallway outside of Classrooms 204 -207	W2	CMU	White	None	0	0.2	Negative
3	2	200 B-1	Hallway outside of Classrooms 204 -207	W3	CMU	Blue	None	0	0	Negative
3	2	200 B-1	Hallway outside of Classrooms 204 -207	W4	CMU	Blue	None	0	0.2	Negative
3	2	200 B-1	Hallway outside of Classrooms 204 -207	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200 B-1	Hallway outside of Classrooms 204 -207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200 B-2	Hallway outside of Classrooms 208 -209	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	2	200 B-2	Hallway outside of Classrooms 208 -209	W2	CMU	White	None	0	0.1	Negative
3	2	200 B-2	Hallway outside of Classrooms 208 -209	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	2	200 B-2	Hallway outside of Classrooms 208 -209	W4	CMU	White	None	0	0.1	Negative
3	2	200 B-2	Hallway outside of Classrooms 208 -209	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200 B-2	Hallway outside of Classrooms 208 -209	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200 B-3	Hallway outside of Classrooms 211 -215	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	2	200 B-3	Hallway outside of Classrooms 211 -215	W2	CMU	Blue	None	0	0.2	Negative
3	2	200 B-3	Hallway outside of Classrooms 211 -215	W3	CMU	Blue	None	0	0	Negative
3	2	200 B-3	Hallway outside of Classrooms 211 -215	W4	CMU	White	None	0	0.1	Negative
3	2	200 B-3	Hallway outside of Classrooms 211 -215	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200 B-3	Hallway outside of Classrooms 211 -215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200 B-4	Hallway outside of Restrooms	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	2	200 B-4	Hallway outside of Restrooms	W2	CMU	Blue	None	0	0.1	Negative
3	2	200 B-4	Hallway outside of Restrooms	W3	CMU	White	None	0	0	Negative
3	2	200 B-4	Hallway outside of Restrooms	W4	CMU	White	None	0	0.2	Negative
3	2	200 B-4	Hallway outside of Restrooms	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200 B-4	Hallway outside of Restrooms	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	200A	Hall Closet next to Women's Restroom	W1	CMU	White	None	0	0.2	Negative
3	2	200A	Hall Closet next to Women's Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	200A	Hall Closet next to Women's Restroom	W2	CMU	White	None	0	0.1	Negative
3	2	200A	Hall Closet next to Women's Restroom	W3	no access	White	None	0	0.1	Negative
3	2	200A	Hall Closet next to Women's Restroom	W4	CMU	White	None	0	0.1	Negative
3	2	200A	Hall Closet next to Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200A	Hall Closet next to Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200B	Women's Restroom	W1	CMU	White	None	0	0.1	Negative
3	2	200B	Women's Restroom	Doorframe	Metal	Blue	None	0	0.7	Positive
3	2	200B	Women's Restroom	W2	CMU	White	None	0	0.1	Negative
3	2	200B	Women's Restroom	W3	CMU	White	None	0	0.2	Negative
3	2	200B	Women's Restroom	W4	CMU	White	None	0	0.1	Negative
3	2	200B	Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200B	Women's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	2	200C	Custodial Closet	W1	CMU	White	None	0	0.1	Negative
3	2	200C	Custodial Closet	Doorframe	Metal	Blue	Friction	4	0.3	Negative
3	2	200C	Custodial Closet	W2	CMU	White	None	0	0.1	Negative
3	2	200C	Custodial Closet	W3	CMU	White	None	0	0.4	Negative
3	2	200C	Custodial Closet	Step	Concrete	Grey	None	0	0.1	Negative
3	2	200C	Custodial Closet	W4	CMU	White	None	0	0.1	Negative
3	2	200C	Custodial Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200C	Custodial Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	200D	Men's Restroom	W1	CMU	White	None	0	0.1	Negative
3	2	200D	Men's Restroom	Doorframe	Metal	Blue	None	0	0.7	Positive
3	2	200D	Men's Restroom	W2	CMU	White	None	0	0.1	Negative
3	2	200D	Men's Restroom	W3	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	200D	Men's Restroom	W4	CMU	White	None	0	0.1	Negative
3	2	200D	Men's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	200D	Men's Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	2	200E	Electrical Room next to Boy's Restroom	W1	CMU	White	None	0	0.1	Negative
3	2	200E	Electrical Room next to Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
3	2	200E	Electrical Room next to Boy's Restroom	W2	CMU	White	None	0	0.1	Negative
3	2	200E	Electrical Room next to Boy's Restroom	W3	CMU	White	None	0	0.3	Negative
3	2	200E	Electrical Room next to Boy's Restroom	Duct	Metal	White	None	0	0.2	Negative
3	2	200E	Electrical Room next to Boy's Restroom	W4	CMU	White	None	0	0	Negative
3	2	200E	Electrical Room next to Boy's Restroom	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
3	2	200E	Electrical Room next to Boy's Restroom	Floor	Concrete	Grey	Friction	6	0.3	Negative
3	2	200F	Telecomm Room across from Classroom 204	W1	CMU	White	None	0	0.1	Negative
3	2	200F	Telecomm Room across from Classroom 204	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	200F	Telecomm Room across from Classroom 204	W2	CMU	White	None	0	0.1	Negative
3	2	200F	Telecomm Room across from Classroom 204	W3	CMU	White	None	0	0.2	Negative
3	2	200F	Telecomm Room across from Classroom 204	W4	CMU	White	None	0	0.5	Negative
3	2	200F	Telecomm Room across from Classroom 204	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
3	2	200F	Telecomm Room across from Classroom 204	Floor	Concrete	Grey	Friction	6	0.3	Negative
3	2	204	Classroom 204	W1	CMU	White	None	0	0.1	Negative
3	2	204	Classroom 204	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	204	Classroom 204	W2	CMU	White	None	0	0.1	Negative
3	2	204	Classroom 204	W3	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	204	Classroom 204	W4	CMU	White	None	0	0.5	Negative
3	2	204	Classroom 204	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	204	Classroom 204	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	205	Classroom 205	W1	CMU	White	None	0	0.1	Negative
3	2	205	Classroom 205	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	205	Classroom 205	W2	CMU	White	None	0	0	Negative
3	2	205	Classroom 205	W3	CMU	White	None	0	0.1	Negative
3	2	205	Classroom 205	W4	CMU	White	None	0	0	Negative
3	2	205	Classroom 205	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	205	Classroom 205	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	206	Classroom 206	W1	CMU	White	None	0	0.2	Negative
3	2	206	Classroom 206	Doorframe	Metal	Blue	None	0	0.5	Negative
3	2	206	Classroom 206	W2	CMU	White	None	0	0	Negative
3	2	206	Classroom 206	W3	CMU	White	None	0	0.1	Negative
3	2	206	Classroom 206	W4	CMU	White	None	0	0.1	Negative
3	2	206	Classroom 206	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	206	Classroom 206	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	207	Classroom 207	W1	CMU	White	None	0	0.1	Negative
3	2	207	Classroom 207	Doorframe	Metal	Blue	None	0	0.1	Negative
3	2	207	Classroom 207	W2	CMU	White	None	0	0.1	Negative
3	2	207	Classroom 207	W3	CMU	White	None	0	0.1	Negative
3	2	207	Classroom 207	W4	CMU	White	None	0	0.2	Negative
3	2	207	Classroom 207	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	207	Classroom 207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	208	Classroom 208	W1	CMU	White	None	0	0.3	Negative
3	2	208	Classroom 208	Doorframe	Metal	Blue	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	208	Classroom 208	W2	CMU	White	None	0	0	Negative
3	2	208	Classroom 208	W3	CMU	White	None	0	0.2	Negative
3	2	208	Classroom 208	W4	CMU	Blue	None	0	0.1	Negative
3	2	208	Classroom 208	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	208	Classroom 208	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	209	Classroom 209	W1	CMU	White	None	0	0.1	Negative
3	2	209	Classroom 209	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	209	Classroom 209	W2	CMU	White	None	0	0.1	Negative
3	2	209	Classroom 209	W3	CMU	Blue	None	0	0.1	Negative
3	2	209	Classroom 209	W4	CMU	White	None	0	0.3	Negative
3	2	209	Classroom 209	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	209	Classroom 209	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	210	Office 210	W1	CMU	White	None	0	0.1	Negative
3	2	210	Office 210	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	210	Office 210	W2	CMU	White	None	0	0	Negative
3	2	210	Office 210	W3	CMU	Blue	None	0	0.1	Negative
3	2	210	Office 210	W4	CMU	White	None	0	0.2	Negative
3	2	210	Office 210	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	210	Office 210	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	211	Classroom 211	W1	CMU	White	None	0	0.2	Negative
3	2	211	Classroom 211	Doorframe	Metal	Blue	Friction	4	0.3	Negative
3	2	211	Classroom 211	W2	CMU	White	None	0	0.1	Negative
3	2	211	Classroom 211	W3	CMU	White	None	0	0.1	Negative
3	2	211	Classroom 211	W4	CMU	White	None	0	0	Negative
3	2	211	Classroom 211	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	211	Classroom 211	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	212	Classroom 212	W1	CMU	White	None	0	0.1	Negative
3	2	212	Classroom 212	Doorframe	Metal	Blue	Friction	1	0.3	Negative
3	2	212	Classroom 212	W2	CMU	White	None	0	0.1	Negative
3	2	212	Classroom 212	W3	CMU	White	None	0	0	Negative
3	2	212	Classroom 212	W4	CMU	White	None	0	0.1	Negative
3	2	212	Classroom 212	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	212	Classroom 212	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	213	Classroom 213	W1	CMU	White	None	0	0.1	Negative
3	2	213	Classroom 213	Doorframe	Metal	Blue	Friction	3	0.1	Negative
3	2	213	Classroom 213	W2	CMU	White	None	0	0.2	Negative
3	2	213	Classroom 213	W3	CMU	White	None	0	0.2	Negative
3	2	213	Classroom 213	W4	CMU	White	None	0	0.2	Negative
3	2	213	Classroom 213	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	213	Classroom 213	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	214	Classroom 214	W1	CMU	White	None	0	0	Negative
3	2	214	Classroom 214	Doorframe	Metal	Blue	Friction	6	0.2	Negative
3	2	214	Classroom 214	W2	CMU	White	None	0	0	Negative
3	2	214	Classroom 214	W3	CMU	White	None	0	0	Negative
3	2	214	Classroom 214	W4	CMU	White	None	0	0.2	Negative
3	2	214	Classroom 214	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	214	Classroom 214	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	215	Classroom 215	W1	CMU	White	None	0	0	Negative
3	2	215	Classroom 215	Doorframe	Metal	Blue	Friction	4	0.5	Negative
3	2	215	Classroom 215	W2	CMU	White	None	0	0.2	Negative
3	2	215	Classroom 215	W3	CMU	White	None	0	0.1	Negative
3	2	215	Classroom 215	W4	CMU	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	215	Classroom 215	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	215	Classroom 215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	216	Classroom 216	W1	CMU	White	None	0	0.1	Negative
3	2	216	Classroom 216	Doorframe	Metal	Blue	None	0	0.2	Negative
3	2	216	Classroom 216	W2	CMU	White	None	0	0	Negative
3	2	216	Classroom 216	W3	CMU	White	None	0	0.2	Negative
3	2	216	Classroom 216	W4	CMU	White	None	0	0.1	Negative
3	2	216	Classroom 216	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	2	216	Classroom 216	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	217	Girl's Student Restroom	W1	CMU	Yellow	None	0	0.3	Negative
3	2	217	Girl's Student Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
3	2	217	Girl's Student Restroom	W2	CMU	Yellow	None	0	0	Negative
3	2	217	Girl's Student Restroom	W3	CMU	Yellow	None	0	0.1	Negative
3	2	217	Girl's Student Restroom	W4	CMU	Yellow	None	0	0.2	Negative
3	2	217	Girl's Student Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
3	2	217	Girl's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	2	218	Boy's Student Restroom	W1	CMU	White	None	0	0.1	Negative
3	2	218	Boy's Student Restroom	Doorframe	Metal	Blue	Friction	1	0.4	Negative
3	2	218	Boy's Student Restroom	W2	CMU	White	None	0	0.1	Negative
3	2	218	Boy's Student Restroom	W3	Drywall	White	None	0	0	Negative
3	2	218	Boy's Student Restroom	W4	CMU	White	None	0	0.3	Negative
3	2	218	Boy's Student Restroom	Ceiling	Drywall	White	None	0	0	Negative
3	2	218	Boy's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Doorframe	Metal	Blue	Friction	1	0.5	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W2	CMU	White	None	0	0.2	Negative
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W3	CMU	White	None	0	0.2	Negative
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Duct	Metal	White	None	0	0	Negative
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	W4	CMU	White	None	0	0	Negative
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Ceiling	Metal	No Access	No Access	No Access	No Access	No Access
3	2	218A	Pipe Chase between Girl's Restroom and Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	W1	CMU	White	None	0	0	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Doorframe	Metal	Blue	None	0	0.4	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	W2	CMU	White	None	0	0.1	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Post	Metal	Blue	None	0	0	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	pan	Metal	White	None	0	0.7	Positive
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Railing	Metal	Blue	Flaking	10	0.2	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Stringer	Metal	White	Friction	14	0.2	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	W3	CMU	White	None	0	0	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	W4	CMU	White	None	0	0.1	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	pipe	Metal	Red	None	0	0.3	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Ceiling	Metal	White	None	0	0.1	Negative
3	2	Stair C-2	Stairwell C-2 next to Classroom 215	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	W1	CMU	White	None	0	0.2	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Doorframe	Metal	Blue	None	0	0.5	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	W2	CMU	White	None	0	0.1	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Railing	Metal	Blue	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Post	Metal	Blue	None	0	0.2	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Stringer	Metal	White	None	0	0.3	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	pan	Metal	White	None	0	0	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	pipe	Metal	Red	Chipping	2	0.1	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	W3	CMU	White	None	0	0	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	W4	CMU	White	None	0	0	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Ceiling	Metal	White	None	0	0	Negative
3	2	Stair D-2	Stairwell D-2 next to Classroom 207	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	W2	CMU	White	None	0	0.1	Negative
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	Mural	CMU	multi	None	0	0.1	Negative
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	W3	CMU	Green	None	0	0.1	Negative
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	W4	CMU	Green	None	0	0	Negative
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	300 B-1	Hallway outside of Classrooms 301 - 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300 B-2	Hallway outside of Science Classroom 305	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	3	300 B-2	Hallway outside of Science Classroom 305	W2	CMU	White	None	0	0.1	Negative
3	3	300 B-2	Hallway outside of Science Classroom 305	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	3	300 B-2	Hallway outside of Science Classroom 305	W4	CMU	White	None	0	0.1	Negative
3	3	300 B-2	Hallway outside of Science Classroom 305	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	300 B-2	Hallway outside of Science Classroom 305	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	W1	CMU	Green	None	0	0.2	Negative
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	W2	CMU	Green	None	0	0.1	Negative
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	W3	CMU	White	None	0	0.3	Negative
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	300 B-3	Hallway outside of Classrooms 307 - 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300 B-4	Hallway outside of Restrooms	W1	CMU	Green	None	0	0.1	Negative
3	3	300 B-4	Hallway outside of Restrooms	W2	CMU	White	None	0	0.1	Negative
3	3	300 B-4	Hallway outside of Restrooms	W3	CMU	White	None	0	0.1	Negative
3	3	300 B-4	Hallway outside of Restrooms	W4	CMU	White	None	0	0.2	Negative
3	3	300 B-4	Hallway outside of Restrooms	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	300 B-4	Hallway outside of Restrooms	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300A	Hall Closet next to Women's Restroom	W1	CMU	White	None	0	0.1	Negative
3	3	300A	Hall Closet next to Women's Restroom	Doorframe	Metal	Blue	None	0	0.2	Negative
3	3	300A	Hall Closet next to Women's Restroom	W2	CMU	White	None	0	0.1	Negative
3	3	300A	Hall Closet next to Women's Restroom	W3	CMU	White	No Access	No Access	No Access	No Access
3	3	300A	Hall Closet next to Women's Restroom	W4	CMU	White	None	0	0	Negative
3	3	300A	Hall Closet next to Women's Restroom	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	300A	Hall Closet next to Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300B	Women's Restroom	W1	CMU	White	None	0	0	Negative
3	3	300B	Women's Restroom	Doorframe	Metal	Blue	Chipping	1	0.5	Negative
3	3	300B	Women's Restroom	W2	CMU	White	None	0	0.1	Negative
3	3	300B	Women's Restroom	W3	CMU	White	None	0	0.1	Negative
3	3	300B	Women's Restroom	W4	CMU	White	None	0	0.1	Negative
3	3	300B	Women's Restroom	Ceiling	Drywall	White	None	0	0.1	Negative
3	3	300B	Women's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300C	Custodial Closet	W1	CMU	White	None	0	0.1	Negative
3	3	300C	Custodial Closet	Doorframe	Metal	Blue	Chipping	2	0.4	Negative
3	3	300C	Custodial Closet	W2	CMU	White	None	0	0	Negative
3	3	300C	Custodial Closet	W3	CMU	White	None	0	0.2	Negative
3	3	300C	Custodial Closet	W4	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	300C	Custodial Closet	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	300C	Custodial Closet	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300D	Men's Restroom	W1	CMU	White	None	0	0	Negative
3	3	300D	Men's Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative
3	3	300D	Men's Restroom	W2	CMU	White	None	0	0	Negative
3	3	300D	Men's Restroom	W3	CMU	White	None	0	0	Negative
3	3	300D	Men's Restroom	W4	CMU	White	None	0	0.2	Negative
3	3	300D	Men's Restroom	Ceiling	Drywall	White	None	0	0.3	Negative
3	3	300D	Men's Restroom	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	300E	Electrical Room next to Boy's Restroom	W1	CMU	White	None	0	0.2	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
3	3	300E	Electrical Room next to Boy's Restroom	W2	CMU	White	None	0	0.1	Negative
3	3	300E	Electrical Room next to Boy's Restroom	W3	CMU	White	None	0	0	Negative
3	3	300E	Electrical Room next to Boy's Restroom	W4	CMU	White	None	0	0.4	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Conduit	Plastic	White	None	0	0.4	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Ceiling	Metal	White	None	0	0.1	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Conduit	Metal	White	None	0	0.3	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Duct	Metal	White	None	0	0.3	Negative
3	3	300E	Electrical Room next to Boy's Restroom	Floor	Floor Tile	Grey	none	0	0.2	Negative
3	3	300F	Telecomm Room across from Classroom 301	W1	Wood	White	None	0	0.1	Negative
3	3	300F	Telecomm Room across from Classroom 301	Doorframe	Metal	Blue	None	0	0.3	Negative
3	3	300F	Telecomm Room across from Classroom 301	Conduit	Metal	White	None	0	0.2	Negative
3	3	300F	Telecomm Room across from Classroom 301	W2	Wood	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	300F	Telecomm Room across from Classroom 301	W3	Wood	White	None	0	0	Negative
3	3	300F	Telecomm Room across from Classroom 301	Duct	Metal	White	None	0	0.2	Negative
3	3	300F	Telecomm Room across from Classroom 301	W4	Wood	White	None	0	0.1	Negative
3	3	300F	Telecomm Room across from Classroom 301	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	3	300F	Telecomm Room across from Classroom 301	Floor	Concrete	Grey	None	0	0.2	Negative
3	3	301	Classroom 301	W1	CMU	White	None	0	0.1	Negative
3	3	301	Classroom 301	Doorframe	Metal	Blue	Friction	3	0.2	Negative
3	3	301	Classroom 301	W2	CMU	White	None	0	0.1	Negative
3	3	301	Classroom 301	W3	CMU	White	None	0	0	Negative
3	3	301	Classroom 301	W4	CMU	White	None	0	0.1	Negative
3	3	301	Classroom 301	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	301	Classroom 301	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	302	Classroom 302	W1	CMU	White	None	0	0.1	Negative
3	3	302	Classroom 302	Doorframe	Metal	Blue	Friction	5	0.1	Negative
3	3	302	Classroom 302	W2	CMU	White	None	0	0.1	Negative
3	3	302	Classroom 302	W3	CMU	White	None	0	0.5	Negative
3	3	302	Classroom 302	W4	CMU	White	None	0	0.4	Negative
3	3	302	Classroom 302	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	302	Classroom 302	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	303	Classroom 303	W1	CMU	White	None	0	0	Negative
3	3	303	Classroom 303	Doorframe	Metal	Blue	Friction	4	0.2	Negative
3	3	303	Classroom 303	W2	CMU	White	None	0	0.2	Negative
3	3	303	Classroom 303	W3	CMU	White	None	0	0.2	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	303	Classroom 303	W4	CMU	White	None	0	0	Negative
3	3	303	Classroom 303	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	303	Classroom 303	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	304	Classroom 304	W1	CMU	White	None	0	0	Negative
3	3	304	Classroom 304	Doorframe	Metal	Blue	Friction	3	0.5	Negative
3	3	304	Classroom 304	W2	CMU	White	None	0	0.2	Negative
3	3	304	Classroom 304	W3	CMU	White	None	0	0	Negative
3	3	304	Classroom 304	W4	CMU	White	None	0	0.1	Negative
3	3	304	Classroom 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	304	Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	305	Science Classroom 305	W1	CMU	White	None	0	0.2	Negative
3	3	305	Science Classroom 305	Doorframe	Metal	Blue	Friction	3	0.1	Negative
3	3	305	Science Classroom 305	W2	CMU	White	None	0	0	Negative
3	3	305	Science Classroom 305	W3	CMU	White	None	0	0.1	Negative
3	3	305	Science Classroom 305	W4	CMU	White	None	0	0.2	Negative
3	3	305	Science Classroom 305	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	305	Science Classroom 305	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	306	Office 306	W1	CMU	White	None	0	0.1	Negative
3	3	306	Office 306	Doorframe	Metal	Blue	Friction	2	0.5	Negative
3	3	306	Office 306	W2	CMU	White	None	0	0.1	Negative
3	3	306	Office 306	W3	CMU	Green	None	0	0	Negative
3	3	306	Office 306	W4	CMU	White	None	0	0	Negative
3	3	306	Office 306	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	306	Office 306	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	307	Classroom 307	W1	CMU	White	None	0	0.1	Negative
3	3	307	Classroom 307	Doorframe	Metal	Blue	Friction	4	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	307	Classroom 307	W2	CMU	White	None	0	0.1	Negative
3	3	307	Classroom 307	W3	CMU	White	None	0	0.1	Negative
3	3	307	Classroom 307	W4	CMU	White	None	0	0.1	Negative
3	3	307	Classroom 307	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	307	Classroom 307	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	308	Classroom 308	W1	CMU	White	None	0	0.1	Negative
3	3	308	Classroom 308	Doorframe	Metal	Blue	Friction	2	0.1	Negative
3	3	308	Classroom 308	W2	CMU	White	None	0	0.2	Negative
3	3	308	Classroom 308	W3	CMU	White	None	0	0	Negative
3	3	308	Classroom 308	W4	CMU	White	None	0	0.1	Negative
3	3	308	Classroom 308	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	308	Classroom 308	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	309	Classroom 309	W1	CMU	White	None	0	0.1	Negative
3	3	309	Classroom 309	Doorframe	Metal	Blue	Friction	2	0.2	Negative
3	3	309	Classroom 309	W2	CMU	White	None	0	0.1	Negative
3	3	309	Classroom 309	W3	CMU	White	None	0	0.2	Negative
3	3	309	Classroom 309	W4	CMU	White	None	0	0.1	Negative
3	3	309	Classroom 309	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	309	Classroom 309	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	310	Classroom 310	W1	CMU	White	None	0	0.1	Negative
3	3	310	Classroom 310	Doorframe	Metal	Blue	Friction	2	0.1	Negative
3	3	310	Classroom 310	W2	CMU	White	None	0	0.2	Negative
3	3	310	Classroom 310	W3	CMU	White	None	0	0.1	Negative
3	3	310	Classroom 310	W4	CMU	White	None	0	0.2	Negative
3	3	310	Classroom 310	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	310	Classroom 310	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	311	Classroom 311	W1	CMU	White	None	0	0.2	Negative
3	3	311	Classroom 311	Doorframe	Metal	Blue	None	0	0.1	Negative
3	3	311	Classroom 311	W2	CMU	White	None	0	0.2	Negative
3	3	311	Classroom 311	W3	CMU	White	None	0	0.2	Negative
3	3	311	Classroom 311	W4	CMU	White	None	0	0.2	Negative
3	3	311	Classroom 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	311	Classroom 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	312	Classroom 312	W1	CMU	White	None	0	0.1	Negative
3	3	312	Classroom 312	Doorframe	Metal	Blue	None	0	0.2	Negative
3	3	312	Classroom 312	W2	CMU	White	None	0	0.1	Negative
3	3	312	Classroom 312	W3	CMU	White	None	0	0.1	Negative
3	3	312	Classroom 312	W4	CMU	Green	None	0	0.2	Negative
3	3	312	Classroom 312	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	312	Classroom 312	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	313	Girl's Student Restroom	W1	CMU	Yellow	None	0	0.2	Negative
3	3	313	Girl's Student Restroom	Doorframe	Metal	Blue	None	0	0.3	Negative
3	3	313	Girl's Student Restroom	W2	CMU	Yellow	None	0	0	Negative
3	3	313	Girl's Student Restroom	W3	CMU	Yellow	None	0	0	Negative
3	3	313	Girl's Student Restroom	W4	CMU	Yellow	None	0	0.1	Negative
3	3	313	Girl's Student Restroom	Ceiling	Drywall	White	None	0	0.2	Negative
3	3	313	Girl's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	3	314	Boy's Student Restroom	W1	CMU	White	None	0	0	Negative
3	3	314	Boy's Student Restroom	Doorframe	Metal	Blue	None	0	0.4	Negative
3	3	314	Boy's Student Restroom	W2	CMU	White	None	0	0	Negative
3	3	314	Boy's Student Restroom	W3	Drywall	White	None	0	0	Negative
3	3	314	Boy's Student Restroom	W4	CMU	White	None	0	0.1	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	314	Boy's Student Restroom	Ceiling	Drywall	White	None	0	0	Negative
3	3	314	Boy's Student Restroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W1	CMU	White	None	0	0.1	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Doorframe	Metal	Blue	None	0	0.1	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W2	CMU	White	None	0	0	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W3	CMU	White	None	0	0	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Ladder	Metal	Blue	None	0	0.2	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Duct	Metal	White	None	0	0	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	W4	CMU	White	None	0	0.2	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Ceiling	Metal	White	None	0	0.1	Negative
3	3	314A	Pipe Chase between Girl's Student Restroom and Boy's Student Restroom	Floor	Concrete	Grey	None	0	0	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	W1	CMU	White	None	0	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Doorframe	Metal	Blue	None	0	0.6	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	W2	CMU	White	None	0	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	pipe	Metal	Red	None	0	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Railing	Metal	Blue	Chipping	8	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Post	Metal	Blue	None	0	0.2	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Stringer	Metal	White	Friction	3	0.3	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	pan	Metal	White	None	0	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	W3	CMU	White	None	0	0	Negative

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	W4	CMU	White	None	0	0.1	Negative
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	Stair C-3	Stairwell C-3 next to Classroom 311	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	W1	CMU	White	None	0	0	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Doorframe	Metal	Blue	None	0	0.5	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	W2	CMU	White	None	0	0	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Railing	Metal	Blue	Chipping	1	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Post	Metal	Blue	None	0	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Stringer	Metal	White	None	0	0.3	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	pan	Metal	White	None	0	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	pipe	Metal	Red	None	0	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	W3	CMU	White	None	0	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	W4	CMU	White	None	0	0.1	Negative
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Ceiling	Metal	N/A	N/A	N/A	N/A	N/A
3	3	Stair D-3	Stairwell D-3 next to Classroom 304	Floor	Floor Tile	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	AT	AT	Attic - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A
3	CS	CS	Crawl Space - None	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	CS	CS	Crawl Space - None	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	CS	CS	Crawl Space - None	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	CS	CS	Crawl Space - None	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	CS	CS	Crawl Space - None	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 3/13/2023-3/22/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Universal Institute Charter School @ Bluford						
			Inspection Company: BATTA Environmental	5720 Media St, Philadelphia PA 19131						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	CS	CS	Crawl Space - None	Floor	N/A	N/A	N/A	N/A	N/A	N/A

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.