

Appendix A - Scope of Work
John Welsh Elementary School

ULCS#	On-Site Room Name	Primary Component (see terms)	Substrate Material	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Quantity (sf)	Comments
5420	S11 : Stairwell 3 near Gym	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S11 : Stairwell 3 near Gym	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S11 : Stairwell 3 near Gym	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S11 : Stairwell 3 near Gym	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	108 : Stairwell 3 Former Home and School Office	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Mechanical Room	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100 : Classroom 100	W1	Concrete		Concrete	0	Negative			
5420	100 : Classroom 100	W2	Concrete	Flaking	Concrete	0.1	Negative		20SF	
5420	100 : Classroom 100	W3	Concrete	Flaking	Concrete	0.2	Negative		20SF	
5420	100 : Classroom 100	W4	Concrete	Flaking	Concrete	-0.1	Negative		10SF	
5420	100 : Classroom 100	W3	Concrete	Flaking	Concrete	-0.1	Negative	Columns	20SF	
5420	100 : Classroom 100	W1	Metal	Chipping	Metal	0.2	Negative	Door Frame	8SF	
5420	100 : Classroom 100	W2,W3	Wood	Chipping	Wood	0.1	Negative	Shelf Support	3SF	
5420	100 : Classroom 100	W3	Metal	Chipping	Metal	0.1	Negative	Radiator cover	15SF	
5420	100 : Classroom 100	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
5420	100A : Classroom 100 Restroom	W2	Metal	Chipping	Metal	0.4	Negative	Door Frame	4SF	
5420	100A : Classroom 100 Restroom	W1	Concrete	Crack	Concrete	0.1	Negative		6SF	
5420	100A : Classroom 100 Restroom	W2	Concrete	Crack	Concrete	-0.1	Negative		6SF	
5420	100A : Classroom 100 Restroom	W3	Concrete	Crack	Concrete	0	Negative		6SF	
5420	100A : Classroom 100 Restroom	W4	Concrete	Crack	Concrete	-0.2	Negative		6SF	
5420	100B : Classroom 100 Closet	W1	Wood	Chipping	Wood	0.1	Negative	Coat Rack	2SF	
5420	100B : Classroom 100 Closet	W1,W2,W3,W4	Concrete	Crack	Concrete	0	Negative			
5420	100B : Classroom 100 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100B : Classroom 100 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100D : Classroom 100 Closet Pipe Chase	W4	Pipe	Flaking	Pipe	-0.2	Negative			
5420	100D : Classroom 100 Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100D : Classroom 100 Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100D : Classroom 100 Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100D : Classroom 100 Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	100C : Classroom 100 Coat Closet	W2	Metal	Chipping	Metal	0.3	Negative	Door Frame		
5420	100C : Classroom 100 Coat Closet	W1,W2,W3,W4	Concrete		Concrete	0	Negative			
5420	100C : Classroom 100 Coat Closet	W3	Metal	Chipping	Metal	0.2	Negative	Shelf		
5420	100C : Classroom 100 Coat Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	102 : Classroom 102	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	10 SF	
5420	102 : Classroom 102	W3	Metal	Chipping	Metal	-0.1	Negative	Radiator cover	40SF	
5420	102 : Classroom 102	W3	Concrete	Flaking	Concrete	0.2	Negative	Columns	15SF	
5420	102 : Classroom 102	W1	Concrete	Flaking	Concrete	-0.1	Negative		10SF	
5420	102 : Classroom 102	W3	Concrete	Flaking	Concrete	-0.2	Negative		10SF	
5420	102 : Classroom 102	W2	Concrete	Chipping	Concrete	0	Negative		3SF	
5420	102 : Classroom 102	Ceiling	Concrete	Peeling	Concrete	0.1	Negative		60SF	
5420	102 : Classroom 102	W4	Concrete	Chipping	Concrete	-0.1	Negative		3SF	
5420	102A : Classroom 102 Restroom	W4	Metal	Chipping	Metal	0.3	Negative	Door Frame	10SF	
5420	102A : Classroom 102 Restroom	W1	Concrete	Crack	Concrete	-0.3	Negative		5SF	
5420	102A : Classroom 102 Restroom	W3	Concrete	Crack	Concrete	-0.1	Negative		5SF	

Appendix A - Scope of Work

John Welsh Elementary School

[illegible]

Appendix A - Scope of Work

John Welsh Elementary School

[illegible]

Appendix A - Scope of Work

John Welsh Elementary School

[illegible]

Appendix A - Scope of Work

John Welsh Elementary School

[illegible]

ULCS#	On-Site Room Name	Primary Component (see terms)	Substrate Material	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Quantity (sf)	Comments
5420	200 : Classroom 200	W3	Concrete	Chipping	Concrete	0.1	Negative	Columns		
5420	200 : Classroom 200	Ceiling	Concrete	Intact	Concrete	0	Negative			
5420	200 : Classroom 200	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	2SF	
5420	200 : Classroom 200	W1	Wood	Chipping	Wood	0	Negative	Door	1SF	
5420	200 : Classroom 200	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	200 : Classroom 200	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	200 : Classroom 200	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	201 : Classroom 201	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	202 : Classroom 202	W1	Metal	Chipping	Metal	0.2	Negative	Door Frame	10SF	
5420	202 : Classroom 202	W1	Wood	Chipping	Wood	-0.1	Negative	Door	8SF	
5420	202 : Classroom 202	W1	Concrete	Chipping	Concrete	0	Negative		2SF	
5420	202 : Classroom 202	W2	Concrete	Chipping	Concrete	0	Negative		2SF	
5420	202 : Classroom 202	W3	Concrete	Chipping	Concrete	0.1	Negative		2SF	
5420	202 : Classroom 202	W4	Concrete	Chipping	Concrete	-0.1	Negative		2SF	
5420	202 : Classroom 202	Ceiling	Concrete	Intact	Concrete	0.1	Negative			
5420	202 : Classroom 202	W2	Concrete	Intact	Concrete	0.2	Negative			
5420	202 : Classroom 202	W2	Metal	Intact	Metal	-0.5	Negative			
5420	202 : Classroom 202	W2	Metal	Chipping	Metal	0.1	Negative			
5420	202 : Classroom 202	W2	Metal	Chipping	Metal	0.1	Negative	Locker/Frame	1SF	
5420	202 : Classroom 202	W2	Metal	Chipping	Metal	0.1	Negative	Shelf	4SF	
5420	202 : Classroom 202	W2	Wood	Chipping	Wood	0	Negative	Coat Rack	7SF	
5420	202 : Classroom 202	W3	Concrete	Flaking	Concrete	0.3	Negative	Columns	1SF	
5420	203 : Classroom 203	W1	Concrete	Intact	Concrete	0.1	Negative			
5420	203 : Classroom 203	W2	Concrete	Intact	Concrete	0	Negative			
5420	203 : Classroom 203	W3	Concrete	Intact	Concrete	0.1	Negative			
5420	203 : Classroom 203	W4	Concrete	Intact	Concrete	-0.1	Negative			
5420	203 : Classroom 203	W3	Concrete	Intact	Concrete	0.1	Negative			
5420	203 : Classroom 203	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	3SF	
5420	203 : Classroom 203	W1	Wood	Flaking	Wood	0	Negative	Door	10SF	
5420	203 : Classroom 203	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	204 : Classroom 204	W1	Concrete	Chipping	Concrete	0.1	Negative	2SF		
5420	204 : Classroom 204	W2	Concrete	Chipping	Concrete	-0.1	Negative	2SF		
5420	204 : Classroom 204	W3	Concrete	Chipping	Concrete	0	Negative	2SF		
5420	204 : Classroom 204	W4	Concrete	Chipping	Concrete	-0.1	Negative	2SF		
5420	204 : Classroom 204	W2	Concrete	Intact	Concrete	0	Negative			
5420	204 : Classroom 204	W1	Concrete	Intact	Concrete	0.1	Negative			
5420	204 : Classroom 204	W3	Concrete	Intact	Concrete	0	Negative			
5420	204 : Classroom 204	W4	Concrete	Intact	Concrete	0	Negative			
5420	204 : Classroom 204	W2	Metal	Intact	Metal	0.2	Negative			
5420	204 : Classroom 204	W2	Metal	Chipping	Metal	0.1	Negative	Columns	6SF	
5420	204 : Classroom 204	Ceiling	Concrete	Intact	Concrete	0.1	Negative			
5420	204 : Classroom 204	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	12SF	
5420	205 : Classroom 205	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	8SF	
5420	205 : Classroom 205	W1	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	205 : Classroom 205	W2	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	205 : Classroom 205	W3	Concrete	Chipping	Concrete	-0.1	Negative		1SF	
5420	205 : Classroom 205	W4	Concrete	Chipping	Concrete	-0.1	Negative		1SF	
5420	205 : Classroom 205	W1	Concrete	Peeling	Concrete	0	Negative		1SF	
5420	205 : Classroom 205	W2	Concrete	Peeling	Concrete	0	Negative		1SF	

Appendix A - Scope of Work
John Welsh Elementary School

ULCS#	On-Site Room Name	Primary Component (see terms)	Substrate Material	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Quantity (sf)	Comments
5420	209A : Classroom 209 Storage Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209A : Classroom 209 Storage Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209A : Classroom 209 Storage Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209A : Classroom 209 Storage Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209A : Classroom 209 Storage Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209B : Classroom 209 Storage Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209B : Classroom 209 Storage Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209B : Classroom 209 Storage Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209B : Classroom 209 Storage Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	209B : Classroom 209 Storage Closet Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	211 : Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	212 : Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	214 : Storage Room adjacent to Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	214 : Storage Room adjacent to Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	214 : Storage Room adjacent to Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	214 : Storage Room adjacent to Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	214 : Storage Room adjacent to Classroom 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S21 : Stairwell 3 adjacent to Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S21 : Stairwell 3 adjacent to Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S21 : Stairwell 3 adjacent to Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S21 : Stairwell 3 adjacent to Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S21 : Stairwell 3 adjacent to Classroom 211	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H27 : Hallway outside Classrooms 200 to 212	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	S33 : Stairwell 1 adjacent to Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	ST-C : Storage Closet adjacent to Classroom 300	W1	Concrete	Cracking	Concrete	0	Negative		555	

Appendix A - Scope of Work
John Welsh Elementary School

ULCS#	On-Site Room Name	Primary Component (see terms)	Substrate Material	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Quantity (sf)	Comments
5420	300 : Classroom 300	W2	Metal	Peeling	Metal	0.1	Negative		3SF	
5420	300 : Classroom 300	W2	Metal	Chipping	Metal	0	Negative			
5420	300 : Classroom 300	W3	Metal	Chipping	Metal	-0.1	Negative			
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301A : Classroom 301A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	301B : Office 301B	W1	Concrete	Intact	Concrete	0.1	Negative			
5420	301B : Office 301B	W4	Concrete	Intact	Concrete	-0.2	Negative			
5420	301B : Office 301B	W2	Wood	Chipping	Wood	0.1	Negative		3SF	
5420	301B : Office 301B	W2	Wood	Intact	Wood	0	Negative	Chair rail		
5420	301B : Office 301B	W2	Concrete	Intact	Concrete	0.2	Negative	Columns		
5420	301B : Office 301B	W3	Concrete	Intact	Concrete	0.2	Negative	Columns		
5420	301B : Office 301B	W4	Concrete	Intact	Concrete	0.1	Negative	Columns		
5420	301B : Office 301B	W1	Metal	Chipping	Metal	0.3	Negative	Door Frame	1SF	
5420	301B : Office 301B	W1	Wood	Chipping	Wood	0	Negative	Door	1SF	
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	302 : Classroom 302	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	303 : Classroom 303	W1	Concrete	Chipping	Concrete	0	Negative		2SF	
5420	303 : Classroom 303	W2	Concrete	Chipping	Concrete	0.1	Negative		2SF	
5420	303 : Classroom 303	W3	Concrete	Chipping	Concrete	0.1	Negative		2SF	
5420	303 : Classroom 303	W4	Concrete	Chipping	Concrete	0	Negative		2SF	
5420	303 : Classroom 303	W1	Metal	Chipping	Metal	0.4	Negative	Door Frame	8SF	
5420	303 : Classroom 303	W1	Wood	Chipping	Wood	0.1	Negative	Door	4SF	
5420	303 : Classroom 303	W2	Metal	Chipping	Metal	0.1	Negative	Columns	4SF	
5420	303 : Classroom 303	Ceiling	Concrete	Chipping	Concrete	0.2	Negative		1SF	
5420	303 : Classroom 303	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	304 : Classroom 304	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	305 : Classroom 305	W1	Metal	Chipping	Metal	0.3	Negative	Door Frame	10SF	
5420	305 : Classroom 305	W1	Wood	Chipping	Wood	0	Negative	Door	10SF	
5420	305 : Classroom 305	W1	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	305 : Classroom 305	W2	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	305 : Classroom 305	W3	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	305 : Classroom 305	W4	Concrete	Chipping	Concrete	0	Negative		1SF	
5420	305 : Classroom 305	W3	Concrete	Chipping	Concrete	0.2	Negative	Columns	2SF	

Appendix A - Scope of Work

John Welsh Elementary School

ULCS#	On-Site Room Name	Primary Component (see terms)	Substrate Material	Description of Primary Damage (see terms)	Primary Component Damage Quantity (sf)	XRF Reading (mg/cm2)	Primary Component XRF (positive/negative)	Additional Component (see terms)	Quantity (sf)	Comments
5420	306 : Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306 : Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306 : Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306 : Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306 : Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306A : Classroom 306 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306A : Classroom 306 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306A : Classroom 306 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306A : Classroom 306 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	306A : Classroom 306 Closet	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	BT3 : Boy's Restroom across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38A : Storage Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38A : Storage Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38A : Storage Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38B : Custodial Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38B : Custodial Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	H38B : Custodial Closet across from Classroom 306	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	GT3 : Girl's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	GT3 : Girl's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	GT3 : Girl's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	GT3 : Girl's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	GT3 : Girl's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	MT3 : Women's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	MT3 : Women's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	MT3 : Women's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	MT3 : Women's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	MT3 : Women's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	WT3 : Men's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	WT3 : Men's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	WT3 : Men's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	WT3 : Men's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	WT3 : Men's Restroom across from Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	Pipe Chase	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
5420	308 : Classroom 308	N/A	N/A	N/A	N/A	N/A	N/A	N/A		

Appendix A - Scope of Work

John Welsh Elementary School

[illegible]

