

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H11	Lobby	Main Entrance Lobby	yes	W1	Metal	Brown	None	0	N/A	N/A
1	1	H11	Lobby	Main Entrance Lobby	yes	W2	marble	Brown	None	0	N/A	N/A
1	1	H11	Lobby	Main Entrance Lobby	yes	W3	marble	Tan	None	0	N/A	N/A
1	1	H11	Lobby	Main Entrance Lobby	yes	W4	marble	Brown	None	0	N/A	N/A
1	1	H11	Lobby	Main Entrance Lobby	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H11	Lobby	Main Entrance Lobby	yes	Floor	marble	Green	None	0	N/A	N/A
1	1	ADM1	General Administrative Space	Main Office	yes	W1	Plaster	Blue	None	0	0.04	Negative
1	1	ADM1	Doorframe	Main Office	yes	door frame	metal	tan	Chipping	6	0.2	Negative
1	1	ADM1	General Administrative Space	Main Office	yes	W2	Plaster	Blue	None	0	0.11	Negative
1	1	ADM1	General Administrative Space	Main Office	yes	W3	Plaster	Blue	None	0	0.05	Negative
1	1	ADM1	General Administrative Space	Main Office	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	ADM1	General Administrative Space	Main Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM1	General Administrative Space	Main Office	yes	Floor	Concrete	No Access	N/A	N/A	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	W1	Wood	varnish	None	0	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	W2	Wood	varnish	None	0	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	W3	Wood	varnish	None	0	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	W4	Wood	varnish	None	0	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	Ceiling	Wood	varnish	None	0	N/A	N/A
1	1	ADM1A	Storage	Left Storage Closet in Main Office	yes	Floor	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	W1	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	W2	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	W3	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	W4	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	Ceiling	Wood	varnish	None	0	N/A	N/A
1	1	ADM1B	Storage	Right Storage Closet in Main Office	yes	Floor	Wood	varnish	None	0	N/A	N/A
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	W1	Plaster	Blue	Flaking	3	0.02	Negative
1	1	ADM2	Central Reproduction and Copy	Doorframe Data/Copier Room next to Main Office	yes	Door Frame	Metal	Beige	Chipping	6	0.05	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	W2	Plaster	Blue	Flaking	3	0.01	Negative
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	W3	Plaster	White	None	0	0.15	Negative
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	W4	Plaster	Blue	Flaking	12	0.02	Negative
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	Ceiling	Concrete	No Access	N/A	N/A	N/A	N/A
1	1	ADM2	Central Reproduction and Copy	Data/Copier Room next to Main Office	yes	Floor	Plaster	White	None	0	N/A	N/A
1	1	ADM3	Administrative Office	Counselor Office #1	yes	W1	Plaster	Blue	Cracking	6	0.02	Negative
1	1	ADM3	Administrative Office	Counselor Office #1	yes	W2	Plaster	Blue	None	0	0.1	Negative
1	1	ADM3	Administrative Office	Counselor Office #1	yes	W3	Plaster	Blue	None	0	0.07	Negative
1	1	ADM3	Administrative Office	Counselor Office #1	yes	W4	Plaster	Blue	None	0	0.04	Negative
1	1	ADM3	Administrative Office	Counselor Office #1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM3	Administrative Office	Counselor Office #1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	ADM4	Administrative Office	Counselor Office #2	yes	W1	Plaster	Blue	Cracking	4	0.02	Negative
1	1	ADM4	Administrative Office	Counselor Office #2	yes	Doorframe	Metal	Beige	Chipping	3	0.06	Negative
1	1	ADM4	Administrative Office	Counselor Office #2	yes	W2	Plaster	Blue	None	0	0.01	Negative
1	1	ADM4	Administrative Office	Counselor Office #2	yes	W3	Plaster	Blue	None	0	0.01	Negative
1	1	ADM4	Administrative Office	Counselor Office #2	yes	W4	Plaster	Blue	Cracking	8	0.04	Negative
1	1	ADM4	Administrative Office	Counselor Office #2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM4	Administrative Office	Counselor Office #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	W1	Plaster	Green	None	0	0.04	Negative
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	W2	Plaster	Blue	None	0	0.06	Negative
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	W3	Plaster	Green	Chipping	3	0.01	Negative
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	W4	Plaster	Green	None	0	0.13	Negative
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM5	Principal/Directors Office	Principal's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	W1	Plaster	Green	None	0	0.21	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	W2	Plaster	Green	None	0	0.15	Negative
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	W3	N/A	N/A	None	0	N/A	N/A
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	W4	Plaster	Green	None	0	0.16	Negative
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	ADM5RR	Restrooms, Staff - Female	Principal's Office Restroom	yes	Floor	Marble	N/A	None	0	N/A	N/A
1	1	ADM5S	Storage	Principal's Office Storage	yes	W1	Plaster	Green	None	0	0.1	Negative
1	1	ADM5S	Storage	Principal's Office Storage	yes	W2	Plaster	Green	None	0	0.12	Negative
1	1	ADM5S	Storage	Principal's Office Storage	yes	W3	Plaster	Green	None	0	0.13	Negative
1	1	ADM5S	Storage	Principal's Office Storage	yes	W4	Plaster	Green	None	0	0.08	Negative
1	1	ADM5S	Storage	Principal's Office Storage	yes	Ceiling	Plaster	White	None	0	0.14	Negative
1	1	ADM5S	Storage	Principal's Office Storage	yes	Floor	Concrete	No Access	None	0	N/A	N/A
1	1	ADM6	Kitchen	Office Area Kitchen	yes	W1	Plaster	Beige	None	0	0.02	Negative
1	1	ADM6	Kitchen	Office Area Kitchen	yes	W2	Plaster	Beige	None	0	0.02	Negative
1	1	ADM6	Kitchen	Office Area Kitchen	yes	W3	Plaster	Beige	Flaking	8	0.06	Negative
1	1	ADM6	Kitchen	Office Area Kitchen	yes	W4	Plaster	Beige	None	0	0.01	Negative
1	1	ADM6	Kitchen	Office Area Kitchen	yes	Ceiling	Plaster	Beige	None	0	0.05	Negative
1	1	ADM6	Kitchen	Office Area Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	W1	Plaster	Beige	None	0	0.17	Negative
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	W2	Plaster	Beige	None	0	0.01	Negative
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	W3	Plaster	Beige	Cracking	15	0.04	Negative
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	W4	Plaster	Beige	None	0	0.21	Negative
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	Ceiling	Plaster	Beige	None	0	0.32	Negative
1	1	ADM7	Circulation (Hallway)	Walkway at Counselors Offices	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	W1	Plaster	Beige	None	0	0.03	Negative
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	Doorframe	Metal	Tan	Chipping	6	0.01	Negative
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	W2	Plaster	Beige	None	0	0.09	Negative
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	W4	Plaster	Beige	None	0	0.08	Negative
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM8	Conference Room	WIDENER ROOM (Conference Room)	yes	Floor	Concrete	No Access	None	0	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	W1	Concrete Block	Blue	None	0	N/A	N/A
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	Doorframe	Metal	Blue	Chipping	5	0.12	Negative
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	W2	Concrete Block	Blue	None	0	N/A	N/A
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	W3	Concrete Block	Blue	None	0	N/A	N/A
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	W4	Concrete Block	Blue	None	0	N/A	N/A
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	ADM9	Storage	Administration Office Wing Storage #1 next to WIDENER ROOM	yes	Floor	Concrete	No Access	None	0	N/A	N/A
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	ADM10	Storage	Administration Office Wing Storage #2 at the end of the Corridor	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H12	Circulation (Hallway)	Hallway at Main Office	yes	W1	Plaster	Beige	Flaking	6	0.04	Negative
1	1	H12	Circulation (Hallway)	Hallway at Main Office	N/A	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway at Main Office	yes	W3	Plaster	Beige	Bubbling	3	0.07	Negative
1	1	H12	Circulation (Hallway)	Hallway at Main Office	N/A	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H12	Circulation (Hallway)	Hallway at Main Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H12	Circulation (Hallway)	Hallway at Main Office	yes	Floor	Concrete	No Access	N/A	N/A	N/A	N/A
1	1	AUD	Auditorium	Auditorium	yes	W1	Wood	varnish	N/A	N/A	N/A	N/A
1	1	AUD	Auditorium	Auditorium	yes	W2	Wood	varnish	N/A	N/A	N/A	N/A
1	1	AUD	Auditorium	Auditorium	yes	W3	Wood	varnish	N/A	N/A	N/A	N/A
1	1	AUD	Auditorium	Auditorium	yes	W4	Wood	varnish	N/A	N/A	N/A	N/A
1	1	AUD	Auditorium	Auditorium	yes	Ceiling	Plaster	No Access	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	AUD	Auditorium	Auditorium	yes	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	STAGE	Stage	Stage	N/A	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	STAGE	Stage	Stage	yes	W2	Sheetrock	Beige	None	0	0.1	Negative
1	1	STAGE	Stage	Stage	yes	Door	Wood	White	Chipping	4	0.13	Negative
1	1	STAGE	Stage	Stage	yes	Doorframe	Metal	White	Chipping	3	0.15	Negative
1	1	STAGE	Stage	Stage	yes	W3	Sheetrock	Beige	None	0	0.12	Negative
1	1	STAGE	Stage	Stage	yes	W4	Sheetrock	Beige	Chipping	5	0.09	Negative
1	1	STAGE	Stage	Stage	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	STAGE	Stage	Stage	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	yes	W1	Plaster	Beige	Flaking	8	0.04	Negative
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	N/A	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	yes	W3	Plaster	Beige	Flaking	3	0.06	Negative
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	N/A	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H10	Circulation (Hallway)	Hallway at Auditorium Entrance (Corridor F)	yes	Floor	Concrete	No Access	N/A			
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	W1	Plaster	Green	None	0	0.14	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	Doorframe	Metal	Brown	Chipping	6	0.01	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	W2	Plaster	Green	None	0	0.04	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	W3	Plaster	Green	None	0	0.09	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	W4	Plaster	Green	None	0	0.14	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	Ceiling	Plaster	White	None	0	0.1	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #7 in the Hallway outside IMC Library	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	W1	Plaster	Blue	None	0	0.16	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	W2	Plaster	Blue	None	0	0.16	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	W3	Plaster	Blue	None	0	0.16	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	W4	Plaster	Blue	None	0	0.22	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	T7	Student Restrooms - Male/Female (Classroom)	Restroom #8 in the Hallway outside IMC Library	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	1	IMC (Library)	IMC (Library)	yes	W1	Concrete Block	Green	None	0	0.09	Negative
1	1	1	IMC (Library)	IMC (Library)	yes	Door frame	Metal	green	Chipping	3	0.05	Negative
1	1	1	IMC (Library)	IMC (Library)	yes	W2	Concrete Block	Green	None	0	0.11	Negative
1	1	1	IMC (Library)	IMC (Library)	yes	W3	Concrete Block	Green	None	0	0.05	Negative
1	1	1	IMC (Library)	IMC (Library)	yes	W4	Concrete Block	Green	None	0	0.16	Negative
1	1	1	IMC (Library)	IMC (Library)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	IMC (Library)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	1	IMC (Library)	Library Audio Visual Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	Library Audio Visual Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	Library Audio Visual Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	Library Audio Visual Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	Library Audio Visual Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	1	IMC (Library)	Library Audio Visual Room	yes	Flooring	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	W1	Plaster	Blue	None	0	0.32	Negative
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	Doorframe	Metal	Tan	Chipping	3	0.12	Negative
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	W2	Plaster	Blue	None	0	0.22	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	W3	Plaster	Blue	None	0	0.23	Negative
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	W4	Plaster	Blue	None	0	0.21	Negative
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	Ceiling	Plaster	White	None	0	0.02	Negative
1	1	WRR	Restrooms, Staff - Female	Women's Restroom in Hallway next to IMC	yes	Floor	marble	N/A	N/A	N/A	N/A	N/A
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	W1	Plaster	Green	None	0	0.21	Negative
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	W2	Plaster	Green	None	0	0.2	Negative
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	W3	Plaster	Green	None	0	0.16	Negative
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	W4	Plaster	Green	None	0	0.12	Negative
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	Ceiling	Plaster	White	None	0	0.16	Negative
1	1	MRR	Restrooms, Staff - Male	Men's Restroom in Hallway next to IMC	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	W1	Concrete Block	White	Flaking	4	0.01	Negative
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	W2	Concrete Block	White	None	0	0.06	Negative
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	W3	Concrete Block	White	None	0	0.11	Negative
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	W4	Concrete Block	White	None	0	0.13	Negative
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	JC	Service Closets	Custodial Closet in Hallway outside IMC	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	3	Senior High	Classroom 3	yes	W1	Concrete Block	White	None	0	0.14	Negative
1	1	3	Senior High	Classroom 3	yes	Door Frame	Metal	White	Chipping	6	0.05	Negative
1	1	3	Senior High	Classroom 3	yes	W2	Concrete Block	White	None	0	0.04	Negative
1	1	3	Senior High	Classroom 3	yes	Baseboard	Concrete	White	Chipping	8	0.03	Negative
1	1	3	Senior High	Classroom 3	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
1	1	3	Senior High	Classroom 3	yes	W4	Concrete Block	White	None	0	0.01	Negative
1	1	3	Senior High	Classroom 3	yes	Door	Metal	White	Flaking	4	0.01	Negative
1	1	3	Senior High	Classroom 3	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	3	Senior High	Classroom 3	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	4	Senior High	Classroom 4	yes	W1	Concrete Block	White	Chipping/Cracking	5	0.06	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	4	Senior High	Classroom 4	yes	Door Frame	Metal	White	Chipping	8	0.21	
1	1	4	Senior High	Classroom 4	yes	W2	Concrete Block	White	Chipping	1	0.57	Negative
1	1	4	Senior High	Classroom 4	yes	Baseboard	Metal	White	Friction	6	0.11	
1	1	4	Senior High	Classroom 4	yes	W3	Concrete Block	White	None	0	0.01	Negative
1	1	4	Senior High	Classroom 4	yes	W4	Concrete Block	White	None	0	0.03	Negative
1	1	4	Senior High	Classroom 4	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4	Senior High	Classroom 4	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	4	Senior High	Classroom 4 Closet #1	yes	W1	Concrete Block	Beige	None	0	0.03	Negative
1	1	4	Senior High	Classroom 4 Closet #1	yes	W2	Concrete Block	Beige	None	0	0.06	Negative
1	1	4	Senior High	Classroom 4 Closet #1	yes	W3	Concrete Block	Beige	None	0	0.08	Negative
1	1	4	Senior High	Classroom 4 Closet #1	yes	W4	Concrete Block	Beige	None	0	0.12	Negative
1	1	4	Senior High	Classroom 4 Closet #1	yes	Ceiling	Concrete	White	N/A	N/A		
1	1	4	Senior High	Classroom 4 Closet #2	yes	Flooring	Concrete	N/A	N/A	N/A		
1	1	4	Senior High	Classroom 4 Closet #2	Yes	Door Frame W1	Metal	Tan	Chipping	10	0.2	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	W1	Concrete Block	Beige	None	0	0.08	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	W2	Concrete Block	Beige	None	0	0.09	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	W3	Concrete Block	Beige	Cracking	12	0.03	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	W4	Concrete Block	Beige	None	0	0.01	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	Ceiling	Concrete	White	Moisture Damage	20	0.1	Negative
1	1	4	Senior High	Classroom 4 Closet #2	yes	Flooring	Concrete	N/A	N/A	N/A	N/A	
1	1	5	Senior High	Classroom 5	yes	W1	Concrete block	Yellow	Cracking	15	0.01	Negative
1	1	5	Senior High	Classroom 5	yes	Baseboard	Concrete	Yellow	Friction	2	0.03	Negative
1	1	5	Senior High	Classroom 5	yes	Door Frame	Metal	Yello	Chipping	4	0.18	Negative
1	1	5	Senior High	Classroom 5	yes	W2	Concrete block	Yellow	Flaking	4	0.02	Negative
1	1	5	Senior High	Classroom 5	yes	W3	Concrete block	Yellow	Chipping	2	0.08	Negative
1	1	5	Senior High	Classroom 5	yes	W4	Concrete block	Yellow	None	0	0.08	Negative
1	1	5	Senior High	Classroom 5	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5	Senior High	Classroom 5	yes	Floor	Concrete	N/A	N/A	n/a	N/A	N/A
1	1	5A	Storage	Classroom 5 Storge	yes	W1	Concrete block	Green	None	0	N/A	N/A
1	1	5A	Storage	Classroom 5 Storge	yes	Door Frame	Metal	Green	Chipping	6	0.16	Negative
1	1	5A	Storage	Classroom 5 Storge	yes	W2	Concrete block	Green	None	0	N/A	N/A
1	1	5A	Storage	Classroom 5 Storge	yes	W3	Concrete block	Green	None	0	N/A	N/A
1	1	5A	Storage	Classroom 5 Storge	yes	W4	Concrete block	Green	None	0	N/A	N/A
1	1	5A	Storage	Classroom 5 Storge	yes	Ceiling	Plaster	White	None	0	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	5A	Storage	Classroom 5 Storge	yes	Floor	Concrete	N/A	N/A	n/a	n/a	N/A
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	W1	Plaster	Green	Cracking	7	0.02	Negative
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	W2	Plaster	Green	None	0	0.06	Negative
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	W3	Plaster	Green	None	0	0.07	Negative
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	W4	Plaster	Green	None	0	0.15	Negative
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	Ceiling	Plaster	White	Spalling	4	0.01	Negative
1	1	5B	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Classroom 5	Yes	Floor	Marble	N/A	N/A	n/a	N/A	N/A
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	W1	Plaster	Blue	Cracking	1	0.03	Negative
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	W2	Plaster	Blue	Cracking	8	0.13	Negative
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	W3	Plaster	Blue	Cracking	2	0.25	Negative
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	W4	Plaster	Blue	None	0	0.17	Negative
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	Ceiling	Plaster	White	Spalling	4	0.01	Negative
1	1	5C	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 5	Yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	6	Senior High	Classroom 6	Yes	W1	Plaster	Beige	None	0	0.04	Negative
1	1	6	Senior High	Classroom 6	Yes	W2	Plaster	Beige	None	0	0.24	Negative
1	1	6	Senior High	Classroom 6	Yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	6	Senior High	Classroom 6	Yes	W4	Plaster	Beige	None	0	0.02	Negative
1	1	6	Senior High	Classroom 6	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	6	Senior High	Classroom 6	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	7	Senior High	Classroom 7	Yes	W1	Sheetrock	Beige	None	0	0.02	Negative
1	1	7	Senior High	Classroom 7	Yes	W2	Sheetrock	Beige	None	0	0.03	Negative
1	1	7	Senior High	Classroom 7	Yes	W3	Sheetrock	Beige	None	0	0.01	Negative
1	1	7	Senior High	Classroom 7	Yes	W4	Sheetrock	Beige	None	0	0.08	Negative
1	1	7	Senior High	Classroom 7	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	7	Senior High	Classroom 7- Bathroom	Yes	Floor	Concrete	N/A	None	0	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	7	Senior High	Classroom 7- Bathroom	Yes	W1	Plaster	Beige	None	0	0.01	Negative
1	1	7	Senior High	Classroom 7- Bathroom	Yes	W2	Plaster	Beige	None	0	0.01	Negative
1	1	7	Senior High	Classroom 7- Bathroom	Yes	W3	Plaster	Beige	None	0	0.04	Negative
1	1	7	Senior High	Classroom 7- Bathroom	Yes	W4	Plaster	Beige	None	0	0.06	Negative
1	1	7	Senior High	Classroom 7- Bathroom	Yes	Ceiling	No Access	N/A	N/A	N/A	N/A	N/A
1	1	7	Senior High	Classroom 7- Bathroom	Yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	8	Senior High	Classroom 8	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	8	Senior High	Classroom 8	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	8	Senior High	Classroom 8	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	8	Senior High	Classroom 8	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	8	Senior High	Classroom 8	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	8	Senior High	Classroom 8	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	9	Senior High	Classroom 9	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	10	Senior High	Classroom 10	yes	W1	Plaster	Blue	None	0	0.13	Negative
1	1	10	Senior High	Classroom 10	yes	W2	Plaster	Blue	None	0	0.04	Negative
1	1	10	Senior High	Classroom 10	yes	W3	Plaster	Beige	None	0	0.11	Negative
1	1	10	Senior High	Classroom 10	yes	W4	Plaster	Blue	Flaking	3	0.01	Negative
1	1	10	Senior High	Classroom 10	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	10	Senior High	Classroom 10	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	11	Senior High	Classroom 11	yes	W1	Plaster	Beige	Flaking, Cracking	5	0.03	Negative
1	1	11	Senior High	Classroom 11	yes	W2	Plaster	Beige	None	0	0.15	Negative
1	1	11	Senior High	Classroom 11	yes	Baseboard	Cement	Tan	Flaking	3	0.01	Negative
1	1	11	Senior High	Classroom 11	yes	W3	Plaster	Beige	Flaking	4	0.01	Negative
1	1	11	Senior High	Classroom 11	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	11	Senior High	Classroom 11	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	11	Senior High	Classroom 11	yes	Floor	Plaster	N/A	N/A	N/A	N/A	N/A
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	W1	Plaster	Beige	Cracking	4	0.02	Negative
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	W2	Plaster	Beige	None	0	0.16	Negative
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	W3	Plaster	Beige	Cracking/holes	4	0.02	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H03	Circulation (Hallway)	Hallway at IMC (Corridor D)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	W1	Plaster	Beige	Flaking	1	0.03	Negative
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	W2	Plaster	Beige	None	0	0.01	Negative
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	W3	Plaster	Beige	None	0	0.23	Negative
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	W4	Plaster	Beige	None	0	0.18	Negative
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H04	Circulation (Hallway)	Hallway at Gym (East Lobby)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	G1	Gymnasium - Senior High	Gym	yes	W1	Concrete Block	Yellow	Cracking	70	0.03	Negative
1	1	G1	Gymnasium - Senior High	Gym	yes	W2	Concrete Block	Yellow	Cracking/Flaking	75	0.02	Negative
1	1	G1	Gymnasium - Senior High	Gym	yes	W3	Concrete Block	Yellow	Cracking/Flaking	20	0.02	Negative
1	1	G1	Gymnasium - Senior High	Gym	yes	W4	Concrete Block	Yellow	Cracking/Flaking	60	0.03	Negative
1	1	G1	Gymnasium - Senior High	Gym	yes	Ceiling	Metal	Beige	Flaking	15	N/A	No Access
1	1	G1	Gymnasium - Senior High	Gym	yes	Floor	Wood	N/A	N/A			
1	1	G1A	Administrative Office	Gym Office G1A	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	G1A	Administrative Office	Gym Office G1A	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	G1A	Administrative Office	Gym Office G1A	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	G1A	Administrative Office	Gym Office G1A	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	G1A	Administrative Office	Gym Office G1A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	G1A	Administrative Office	Gym Office G1A	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	W1	Plaster	Green	Flaking/Cracking/Chipping	5	0.18	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	Door Frame W2	Metal	Green	None	0	0.36	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	W2	Plaster	Green	Flaking	2	0.29	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	W3	Plaster	Green	None	0	0.19	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	W4	Plaster	Green	None	0	0.26	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	Ceiling	Plaster	White	Hole	1	0.25	Negative
1	1	H14	Circulation (Hallway)	Hallway at Gym Office	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GRR	Restrooms, Staff - Male/Female	Faculty Restroom next to Gym Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	W1	Metal	Green	None	0	3.68	Positive
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	Window Sill	Metal	Green	Chipping	2	0.24	Negative
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	Door Frame	Metal	Green	Chipping	3	6.53	Positive
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	W2	Plaster	Yellow	None	0	0.13	Negative
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	W3	Plaster	Yellow	Chipping	2	0.15	Negative
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	W4	Plaster	Yellow	None	0	0.12	Negative
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	Ceiling	Plaster	White	Holes	2	0.16	Negative
1	1	GS	Storage	Storage (Old Boys Restroom) in Gym Office Area	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WR	Weight Room	Weight Room next to Gym Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	W1	Plaster	Blue	None	0	0.15	Negative
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	Door Frame	Metal	Green	Chipping	6	0.33	Negative
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	W2	Plaster	Blue	None	0	0.16	Negative
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	W3	Plaster	Blue	None	0	0.14	Negative
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	W4	Plaster	Blue	None	0	0.16	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	Ceiling	Plaster	White	Efflorescence	40	0.06	Negative
1	1		Student Restrooms - Female (4-12)	Girl's Bathroom/locker room across from Gym Office	yes	Flooring	Marble	N/A	N/A	N/A	N/A	N/A
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	W1	Plaster	Green	None	0	0.16	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	Door Frame	Metal	Green	Chipping	6	0.32	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	W2	Plaster	Green	None	0	0.19	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	W3	Plaster	Green	None	0	0.18	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	W4	Plaster	Green	None	0	0.2	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	Ceiling	Plaster	White	Efflorescence	12	0.12	Negative
1	1		Student Restrooms - Male (4-12)	Boys Restroom	yes	Flooring	Marble	N/A	N/A	N/A	N/A	N/A
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	Flooring	No Access	No Access	No Access	No Access	No Access	No Access
1	1		Student Restrooms - Male (4-12)	Boys Locker Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Tech Room	Computer - Senior High	Technology Room across from Main Office	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12	Senior High	Classroom 12	yes	W1	Plaster	Beige	None	0	0.25	Negative
1	1	12	Senior High	Classroom 12	yes	Door Frame	Metal	Tan	Chipping	5	0.06	Negative
1	1	12	Senior High	Classroom 12	yes	W2	Plaster	Beige	Efflorescence	30	0.13	Negative
1	1	12	Senior High	Classroom 12	yes	W3	Plaster	Beige	None	0	0.06	Negative
1	1	12	Senior High	Classroom 12	yes	W4	Plaster	Beige	None	0	0.14	Negative
1	1	12	Senior High	Classroom 12	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12	Senior High	Classroom 12	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	12A	Storage	Classroom 12 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12A	Storage	Classroom 12 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12A	Storage	Classroom 12 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12A	Storage	Classroom 12 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12A	Storage	Classroom 12 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12A	Storage	Classroom 12 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	12B	Storage	Classroom 12 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	13	Senior High	Classroom 13	yes	W1	Plaster	Beige	Flaking	1	0.2	Negative
1	1	13	Senior High	Classroom 13	yes	Door Frame	Metal	Tan	Chipping	4	0.19	Negative
1	1	13	Senior High	Classroom 13	yes	W2	Plaster	Beige	None	0	0.18	Negative
1	1	13	Senior High	Classroom 13	yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	13	Senior High	Classroom 13	yes	W4	Plaster	Beige	None	0	0.17	Negative
1	1	13	Senior High	Classroom 13	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	13	Senior High	Classroom 13	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	13A	Storage	Classroom 13 Storage 1	yes	W1	Plaster	Yellow	None	0	0.18	Negative
1	1	13A	Storage	Classroom 13 Storage 1	yes	W2	Plaster	Yellow	None	0	0.12	Negative
1	1	13A	Storage	Classroom 13 Storage 1	yes	W3	Plaster	Yellow	None	0	0.17	Negative
1	1	13A	Storage	Classroom 13 Storage 1	yes	W4	Plaster	Yellow	None	0	0.16	Negative
1	1	13A	Storage	Classroom 13 Storage 1	yes	Ceiling	Plaster	White	None	0	0.18	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	13A	Storage	Classroom 13 Storage 1	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	13B	Storage	Classroom 13 Storage 2	yes	W1	Plaster	N/A	None	0	0.24	Negative
1	1	13B	Storage	Classroom 13 Storage 2	yes	W2	Plaster	Yellow	None	0	0.21	Negative
1	1	13B	Storage	Classroom 13 Storage 2	yes	W3	Plaster	Yellow	None	0	0.2	Negative
1	1	13B	Storage	Classroom 13 Storage 2	yes	W4	Plaster	Yellow	None	0	0.12	Negative
1	1	13B	Storage	Classroom 13 Storage 2	yes	Ceiling	Plaster	Yellow	None	0	0.2	Negative
1	1	13B	Storage	Classroom 13 Storage 2	yes	Floor	Concrete	White	None	0	N/A	N/A
1	1	14	Senior High	Classroom 14	yes	W1	Plaster	Beige	Flaking	2	0.16	Negative
1	1	14	Senior High	Classroom 14	yes	Door Frame	Metal	Tan	Chipping	4	0.2	Negative
1	1	14	Senior High	Classroom 14	yes	W2	Plaster	Beige	None	0	0.15	Negative
1	1	14	Senior High	Classroom 14	yes	W3	Plaster	Beige	None	0	0.13	Negative
1	1	14	Senior High	Classroom 14	yes	W4	Plaster	Beige	None	0	0.14	Negative
1	1	14	Senior High	Classroom 14	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14	Senior High	Classroom 14	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	14A	Storage	Classroom 14 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14A	Storage	Classroom 14 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14A	Storage	Classroom 14 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14A	Storage	Classroom 14 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14A	Storage	Classroom 14 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14A	Storage	Classroom 14 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	14B	Storage	Classroom 14 Storage 2	yes	W1	Plaster	Beige	None	0	0.12	Negative
1	1	14B	Storage	Classroom 14 Storage 2	yes	W2	Plaster	Beige	None	0	0.28	Negative
1	1	14B	Storage	Classroom 14 Storage 2	yes	W3	Plaster	Beige	None	0	0.13	Negative
1	1	14B	Storage	Classroom 14 Storage 2	yes	W4	Plaster	Beige	None	0	0.18	Negative
1	1	14B	Storage	Classroom 14 Storage 2	yes	Ceiling	Plaster	White	None	0	0.2	Negative
1	1	14B	Storage	Classroom 14 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	15	Senior High	Classroom 15	yes	W1	Plaster	Beige	Flaking	2	0.16	Negative
1	1	15	Senior High	Classroom 15	yes	Door Frame	Metal	Tan	Chipping	4	0.13	Negative
1	1	15	Senior High	Classroom 15	yes	W2	Plaster	Beige	Flaking/Chipping	5	0.01	Negative
1	1	15	Senior High	Classroom 15	yes	W3	Plaster	Beige	None	0	0.09	Negative
1	1	15	Senior High	Classroom 15	yes	W4	Plaster	Beige	Flaking/Chipping	15	0.02	Negative
1	1	15	Senior High	Classroom 15	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15	Senior High	Classroom 15	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	15A	Storage	Classroom 15 Storage 1	yes	W1	Plaster	Beige	None	0	0.16	Negative

Element						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	15A	Storage	Classroom 15 Storage 1	yes	W2	Plaster	Beige	None	0	0.25	Negative
1	1	15A	Storage	Classroom 15 Storage 1	yes	W3	Plaster	Beige	None	0	0.19	Negative
1	1	15A	Storage	Classroom 15 Storage 1	yes	W4	Plaster	Beige	None	0	0.23	Negative
1	1	15A	Storage	Classroom 15 Storage 1	yes	Ceiling	Plaster	Beige	None	0	0.18	Negative
1	1	15A	Storage	Classroom 15 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	15B	Storage	Classroom 15 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15B	Storage	Classroom 15 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15B	Storage	Classroom 15 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15B	Storage	Classroom 15 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15B	Storage	Classroom 15 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	15B	Storage	Classroom 15 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16	Senior High	Classroom 16	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16A	Storage	Classroom 16 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	16B	Storage	Classroom 16 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17	Senior High	Classroom 17	yes	W1	Plaster	Beige	Chipping/Cracking	4	0.18	Negative
1	1	17	Senior High	Classroom 17	yes	Door Frame	Metal	Tan	Chipping	4	0.12	Negative
1	1	17	Senior High	Classroom 17	yes	W2	Plaster	Beige	None	0	0.16	Negative
1	1	17	Senior High	Classroom 17	yes	W3	Plaster	Beige	Chipping	3	0.01	Negative
1	1	17	Senior High	Classroom 17	yes	W4	Plaster	Beige	None	0	0.07	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	17	Senior High	Classroom 17	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17	Senior High	Classroom 17	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	17A	Storage	Classroom 17 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17A	Storage	Classroom 17 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17A	Storage	Classroom 17 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17A	Storage	Classroom 17 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17A	Storage	Classroom 17 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17A	Storage	Classroom 17 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	17B	Storage	Classroom 17 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18	Senior High	Classroom 18	yes	W1	Plaster	Beige	Chipping	3	0.19	Negative
1	1	18	Senior High	Classroom 18	yes	Door Frame	Metal	Tan	Chipping	6	0.17	Negative
1	1	18	Senior High	Classroom 18	yes	W2	Plaster	Beige	None	0	0.2	Negative
1	1	18	Senior High	Classroom 18	yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	18	Senior High	Classroom 18	yes	W4	Plaster	Beige	None	0	0.15	Negative
1	1	18	Senior High	Classroom 18	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18	Senior High	Classroom 18	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	18A	Storage	Classroom 18 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18A	Storage	Classroom 18 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18A	Storage	Classroom 18 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18A	Storage	Classroom 18 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18A	Storage	Classroom 18 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18A	Storage	Classroom 18 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	18B	Storage	Classroom 18 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19	Senior High	Classroom 19	yes	W1	Plaster	Yellow	None	0	0.24	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	19	Senior High	Classroom 19	yes	Door Frame	Metal	Yellow	Chipping	6	0.26	Negative
1	1	19	Senior High	Classroom 19	yes	W2	Plaster	Yellow	Chipping	1	0.07	Negative
1	1	19	Senior High	Classroom 19	yes	W3	Plaster	Blue	Cracking	1	0.15	Negative
1	1	19	Senior High	Classroom 19	yes	W4	Plaster	Yellow	None	0	0.1	Negative
1	1	19	Senior High	Classroom 19	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19	Senior High	Classroom 19	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	W1	Plaster	Blue	None	0	0.05	Negative
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	W2	Plaster	Blue	Flaking	2	0.1	Negative
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	W3	Plaster	Blue	None	0	0.05	Negative
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	W4	Plaster	Blue	None	0	0.12	Negative
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	19A	Restrooms, Staff - Male/Female	Faculty Restroom at the end of Classroom 19	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	19B	Storage	Classroom 19 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19B	Storage	Classroom 19 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19B	Storage	Classroom 19 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19B	Storage	Classroom 19 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19B	Storage	Classroom 19 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19B	Storage	Classroom 19 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	W1	Plaster	Green	None	0	0.09	Negative
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	W2	Plaster	Green	None	0	0.15	Negative
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	W3	Plaster	Green	Cracking	4	0.12	Negative
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	W4	Plaster	Green	Cracking	3	0.09	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	Ceiling	Plaster	White	Flaking	4	0.13	Negative
1	1	T1	Student Restrooms - Male/Female (Classroom)	Restroom # 1 - between Classrooms 19 & 20	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	20	Senior High	Classroom 20	yes	W1	Plaster	Yellow	None	0	0.33	Negative
1	1	20	Senior High	Classroom 20	yes	Door Frame	Metal	Blue	Chipping	4	0.18	Negative
1	1	20	Senior High	Classroom 20	yes	W2	Plaster	Yellow	Flaking	3	0.09	Negative
1	1	20	Senior High	Classroom 20	yes	W3	Plaster	Gold	None	0	0.01	Negative
1	1	20	Senior High	Classroom 20	yes	W4	Plaster	Yellow	None	0	0.06	Negative
1	1	20	Senior High	Classroom 20	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20	Senior High	Classroom 20	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	20A	Storage	Classroom 20 Storage 1		W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20A	Storage	Classroom 20 Storage 1		W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20A	Storage	Classroom 20 Storage 1		W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20A	Storage	Classroom 20 Storage 1		W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20A	Storage	Classroom 20 Storage 1		Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20A	Storage	Classroom 20 Storage 1		Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20B	Storage	Classroom 20 Storage 2	yes	W1	Plaster	Green	None	0	0.11	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	Door Frame	Metal	Blue	Chipping	6	0.37	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	W2	Plaster	Green	None	0	0.08	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	W3	Plaster	Green	None	0	0.02	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	W4	Plaster	Green	None	0	0.12	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	20B	Storage	Classroom 20 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	W1	Plaster	Blue	Cracking	2	0.08	Negative
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	W2	Plaster	Blue	None	0	0.06	Negative
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	W3	Plaster	Blue	None	0	0.14	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	W4	Plaster	Blue	None	0	0.09	Negative
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	Ceiling	Plaster	White	Cracking	4	0.02	Negative
1	1	T2	Student Restrooms - Male/Female (Classroom)	Restroom # 2 - between Classrooms 20 & 21	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	20C	Storage	Storage outside Classroom 20	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20C	Storage	Storage outside Classroom 20	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20C	Storage	Storage outside Classroom 20	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20C	Storage	Storage outside Classroom 20	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20C	Storage	Storage outside Classroom 20	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	20C	Storage	Storage outside Classroom 20	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	21	Senior High	Classroom 21	yes	W1	Plaster	Beige	Flaking	1	0.26	Negative
1	1	21	Senior High	Classroom 21	yes	Door Frame	Metal	Tan	Chipping	8	0.27	Negative
1	1	21	Senior High	Classroom 21	yes	W2	Plaster	Beige	Flaking	2	0.01	Negative
1	1	21	Senior High	Classroom 21	yes	W3	Plaster	Beige	Flaking	6	0.14	Negative
1	1	21	Senior High	Classroom 21	yes	W4	Plaster	Beige	Flaking	6	0.05	Negative
1	1	21	Senior High	Classroom 21	yes	Blackboard	Metal	White	Chipping	15	0.23	Negative
1	1	21	Senior High	Classroom 21	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	21	Senior High	Classroom 21	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	21A	Storage	Classroom 21 Storage 1	yes	W1	Plaster	Green	None	0	0.11	Negative
1	1	21A	Storage	Classroom 21 Storage 1	yes	W2	Plaster	Green	None	0	0.05	Negative
1	1	21A	Storage	Classroom 21 Storage 1	yes	W3	Plaster	Green	None	0	0.08	Negative
1	1	21A	Storage	Classroom 21 Storage 1	yes	W4	Plaster	Green	None	0	0.08	Negative
1	1	21A	Storage	Classroom 21 Storage 1	yes	Ceiling	Plaster	Green	None	0	0.21	Negative
1	1	21A	Storage	Classroom 21 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	21B	Storage	Classroom 21 Storage 2	yes	W1	Plaster	Green	None	0	0.08	Negative
1	1	21B	Storage	Classroom 21 Storage 2	yes	W2	Plaster	Green	None	0	0.1	Negative
1	1	21B	Storage	Classroom 21 Storage 2	yes	W3	Plaster	Green	None	0	0.08	Negative
1	1	21B	Storage	Classroom 21 Storage 2	yes	W4	Plaster	Green	None	0	0.13	Negative
1	1	21B	Storage	Classroom 21 Storage 2	yes	Ceiling	Plaster	Green	None	0	0.11	Negative
1	1	21B	Storage	Classroom 21 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	W1	Plaster	Green	None	0	0.11	Negative
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	W2	Plaster	Green	None	0	0.16	Negative
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	W3	Plaster	Green	None	0	0.17	Negative
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	W4	Plaster	Green	None	0	0.14	Negative
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	T3	Student Restrooms - Male/Female (Classroom)	Restroom # 3 - between Classrooms 21 & 22	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	22	Senior High	Classroom 22	yes	W1	Plaster	Beige	Chipping	1	0.32	Negative
1	1	22	Senior High	Classroom 22	yes	Door Frame	Metal	Tan	Chipping	8	0.19	Negative
1	1	22	Senior High	Classroom 22	yes	W2	Plaster	Beige	None	0	0.16	Negative
1	1	22	Senior High	Classroom 22	yes	W3	Plaster	Beige	Chipping	1	0.01	Negative
1	1	22	Senior High	Classroom 22	yes	W4	Plaster	Beige	None	0	0.12	Negative
1	1	22	Senior High	Classroom 22	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	22	Senior High	Classroom 22	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	22A	Storage	Classroom 22 Storage 1	yes	W1	Plaster	Green	None	0	0.13	Negative
1	1	22A	Storage	Classroom 22 Storage 1	yes	W2	Plaster	Green	None	0	0.08	Negative
1	1	22A	Storage	Classroom 22 Storage 1	yes	W3	Plaster	Green	None	0	0.05	Negative
1	1	22A	Storage	Classroom 22 Storage 1	yes	W4	Plaster	Green	None	0	0.09	Negative
1	1	22A	Storage	Classroom 22 Storage 1	yes	Ceiling	Plaster	Green	Flaking	9	0.1	Negative
1	1	22A	Storage	Classroom 22 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	22B	Storage	Classroom 22 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	22B	Storage	Classroom 22 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	22B	Storage	Classroom 22 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	22B	Storage	Classroom 22 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	22B	Storage	Classroom 22 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	22B	Storage	Classroom 22 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	W1	Plaster	Blue	None	0	0.11	Negative
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	W2	Plaster	Blue	None	0	0.01	Negative
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	W3	Plaster	Blue	None	0	0.06	Negative
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	W4	Plaster	Blue	None	0	0.1	Negative
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	Ceiling	Plaster	White	Flaking	10	0.07	Negative
1	1	T4	Student Restrooms - Male/Female (Classroom)	Restroom # 4 - between Classrooms 22 & 23	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	22C	Storage	Storage outside Classroom 22	no	W1	Plaster	Grey	None	0	0.03	Negative
1	1	22C	Storage	Storage outside Classroom 22	no	W2	Plaster	Grey	Flaking/Chipping	14	0.11	Negative
1	1	22C	Storage	Storage outside Classroom 22	no	W3	Plaster	Grey	Flaking/Chipping	8	0.07	Negative
1	1	22C	Storage	Storage outside Classroom 22	no	W4	Plaster	Grey	Flaking	8	0.11	Negative
1	1	22C	Storage	Storage outside Classroom 22	no	Ceiling	Plaster	Grey	Flaking	20	0.11	Negative
1	1	22C	Storage	Storage outside Classroom 22	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	23	Senior High	Classroom 23	yes	W1	Plaster	Blue	Chipping	2	0.26	Negative
1	1	23	Senior High	Classroom 23	yes	Door Frame	Metal	Tan	Chipping	6	0.3	Negative
1	1	23	Senior High	Classroom 23	yes	W2	Plaster	Blue	None	0	0.13	Negative
1	1	23	Senior High	Classroom 23	yes	W3	Plaster	Blue	Flaking	2	0.06	Negative
1	1	23	Senior High	Classroom 23	yes	W4	Plaster	Blue	None	0	0.06	Negative
1	1	23	Senior High	Classroom 23	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	23	Senior High	Classroom 23	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	23A	Storage	Classroom 23 Storage 1	yes	W1	Plaster	Green	None	0	0.22	Negative
1	1	23A	Storage	Classroom 23 Storage 1	yes	W2	Plaster	Green	None	0	0.11	Negative
1	1	23A	Storage	Classroom 23 Storage 1	yes	W3	Plaster	Green	None	0	0.06	Negative
1	1	23A	Storage	Classroom 23 Storage 1	yes	W4	Plaster	Green	None	0	0.11	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	23A	Storage	Classroom 23 Storage 1	yes	Ceiling	Plaster	Green	Flaking	3	0.13	Negative
1	1	23A	Storage	Classroom 23 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	23B	Storage	Classroom 23 Storage 2	yes	W1	Plaster	Green	None	0	0.07	Negative
1	1	23B	Storage	Classroom 23 Storage 2	yes	W2	Plaster	Green	None	0	0.04	Negative
1	1	23B	Storage	Classroom 23 Storage 2	yes	W3	Plaster	Green	None	0	0.11	Negative
1	1	23B	Storage	Classroom 23 Storage 2	yes	W4	Plaster	Green	None	0	0.1	Negative
1	1	23B	Storage	Classroom 23 Storage 2	yes	Ceiling	Plaster	Green	None	0	0.07	Negative
1	1	23B	Storage	Classroom 23 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	W1	Plaster	Green	None	0	0.17	Negative
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	W2	Plaster	Green	None	0	0.14	Negative
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	W3	Plaster	Green	None	0	0.12	Negative
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	W4	Plaster	Green	None	0	0.17	Negative
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	Ceiling	Plaster	White	Flaking	20	0.13	Negative
1	1	T5	Student Restrooms - Male/Female (Classroom)	Restroom # 5 - between Classrooms 23 & 24	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	24	Senior High	Classroom 24	yes	W1	Plaster	Beige	None	0	0.22	Negative
1	1	24	Senior High	Classroom 24	yes	Door Frame	Metal	Tan	Chipping	6	0.23	
1	1	24	Senior High	Classroom 24	yes	W2	Plaster	Beige	None	0	0.12	Negative
1	1	24	Senior High	Classroom 24	yes	W3	Plaster	Beige	None	0	0.08	Negative
1	1	24	Senior High	Classroom 24	yes	W4	Plaster	Beige	None	0	0.07	Negative
1	1	24	Senior High	Classroom 24	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24	Senior High	Classroom 24	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	24A	Storage	Classroom 24 Storage 1	yes	W1	Plaster	Green	None	0	0.08	Negative
1	1	24A	Storage	Classroom 24 Storage 1	yes	W2	Plaster	Green	Cracking	2	0.16	Negative
1	1	24A	Storage	Classroom 24 Storage 1	yes	W3	Plaster	Green	Cracking	4	0.07	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	24A	Storage	Classroom 24 Storage 1	yes	W4	Plaster	Green	None	0	0.01	Negative
1	1	24A	Storage	Classroom 24 Storage 1	yes	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	24A	Storage	Classroom 24 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	24B	Storage	Classroom 24 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24B	Storage	Classroom 24 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24B	Storage	Classroom 24 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24B	Storage	Classroom 24 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24B	Storage	Classroom 24 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24B	Storage	Classroom 24 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24C	Storage	Storage outside Classroom 24	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	W1	Plaster	Blue	None	0	0.08	Negative
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	W2	Plaster	Blue	None	0	0.16	Negative
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	W3	Plaster	Blue	None	0	0.06	Negative
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	W4	Plaster	Blue	None	0	0.03	Negative
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	T6	Student Restrooms - Male/Female (Classroom)	Restroom # 6 - Next to Classroom 24	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	24D	Storage	Storage Room in the Hallway next to Restroom #6 across from Classroom 12	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	W1	Plaster	Blue	None	0	0.04	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	Door Frame	Metal	Tan	Chipping	6	0.22	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	W2	Plaster	Blue	None	0	0.11	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	W3	Plaster	Blue	None	0	0.14	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	W4	Plaster	Blue	Efflorescence	6	0.07	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	Ceiling	Plaster	White	Efflorescence	6	0.01	Negative
1	1	WFR	Restrooms, Staff - Female	Women's Faculty Restroom across from Classroom 12	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	W1	Concrete Block	Beige	Flaking	16	0.08	Negative
1	1	JC	Service Closets	Custodial Closet across from Classroom 12		Door Frame	Metal	Tan	Chipping	10	0.3	
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	W2	Concrete Block	Beige	Flaking	18	0.07	Negative
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	W3	Concrete Block	Beige	Flaking	10	0.04	Negative
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	W4	Concrete Block	Beige	Flaking	10	0.08	Negative
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	Ceiling	Concrete	Beige	Flaking	12	0.05	Negative
1	1	JC	Service Closets	Custodial Closet across from Classroom 12	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	SC	Storage	Storage Closet across from Classroom 12	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	N/A	W1	N/A	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	yes	W2	Plaster	Beige	Flaking	5	0.14	Negative
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	yes	W3	Plaster	Beige	None	0	0.09	Negative
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	yes	W4	Plaster	Beige	Chipping/Flaking	6	0.1	Negative
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H05	Circulation (Hallway)	Hallway at Classroom 12 to 24 (Corridor A)	yes	Floor	Concrete	N/A	N/A	N/a	N/A	N/A
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25B	Storage	Storage Room to the far left of Classroom 25	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25C	Storage	Math Resource Room - Storage Room to the left of Classroom 25	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25	Senior High	Classroom 25	yes	W1	Plaster	Beige	Chipping/Cracking	6	0.13	Negative
1	1	25	Senior High	Classroom 25	yes	Door Frame	Metal	Beige	Chipping	4	0.22	Negative
1	1	25	Senior High	Classroom 25	yes	W2	Plaster	Beige	Chipping/Holes	5	0.16	Negative
1	1	25	Senior High	Classroom 25	yes	W3	Plaster	Beige	Chipping	8	0.08	Negative
1	1	25	Senior High	Classroom 25	yes	W4	Plaster	Beige	Chipping/Cracking	4	0.14	Negative
1	1	25	Senior High	Classroom 25	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	25	Senior High	Classroom 25	yes	Floor	Concrete	N/A	N/A	n/a	N/A	N/A
1	1	26	Senior High	Classroom 26	yes	W1	Plaster	Beige	None	0	0.02	Negative
1	1	26	Senior High	Classroom 26	yes	W2	Plaster	Beige	Cracking	2	0.01	Negative
1	1	26	Senior High	Classroom 26	yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	26	Senior High	Classroom 26	yes	W4	Plaster	Blue	Flaking	2	0.04	Negative
1	1	26	Senior High	Classroom 26	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	26	Senior High	Classroom 26	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	26A	Storage	Classroom 26 Storage	yes	W1	Plaster	Beige	Flaking	2	0.12	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	Door Frame	Metal	Tan	Chipping	12	0.36	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	W2	Plaster	Beige	None	0	0.16	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	W3	Plaster	Beige	None	0	0.13	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	W4	Plaster	Beige	Flaking	8	0.19	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	Ceiling	Plaster	White	None	0	0.17	Negative
1	1	26A	Storage	Classroom 26 Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	W1	Plaster	Green	Cracking	2	0.2	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	Door Frame	Metal	Tan	Chipping	6	0.34	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	W2	Plaster	Green	None	0	0.18	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	W3	Plaster	Green	None	0	0.12	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	W4	Plaster	Green	None	0	0.08	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	Ceiling	Plaster	White	None	0	0.1	Negative
1	1	26B	Student Restrooms - Male/Female (Classroom)	Classroom 26 Restroom	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	26C	Storage	Classroom 26 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	26C	Storage	Classroom 26 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	26C	Storage	Classroom 26 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	26C	Storage	Classroom 26 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	26C	Storage	Classroom 26 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	26C	Storage	Classroom 26 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	W1	Plaster	Beige	Flaking/Chipping/Cracking	10	0.16	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	W3	Plaster	Beige	Cracking/Flaking	5	0.17	Negative
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H06	Circulation (Hallway)	Hallway at Classroom 25 & 26 (Corridor B)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	27	Senior High	Classroom 27	yes	W1	Plaster	Beige	Flaking	5	0.01	Negative
1	1	27	Senior High	Classroom 27	yes	Door Frame	Metal	Tan	Chipping	8	0.26	
1	1	27	Senior High	Classroom 27	yes	W2	Plaster	Beige	Flaking	10	0.04	Negative
1	1	27	Senior High	Classroom 27	yes	W3	Plaster	Beige	None	0	0.09	Negative
1	1	27	Senior High	Classroom 27	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	1	27	Senior High	Classroom 27	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	27	Senior High	Classroom 27	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	27A	Storage	Classroom 27 Storage	yes	W1	Plaster	Beige	Cracking	1	0.19	Negative
1	1	27A	Storage	Classroom 27 Storage	yes	W2	Plaster	Beige	None	0	0.15	Negative
1	1	27A	Storage	Classroom 27 Storage	yes	W3	Plaster	Beige	None	0	0.09	Negative
1	1	27A	Storage	Classroom 27 Storage	yes	W4	Plaster	Beige	Cracking	3	0.08	Negative
1	1	27A	Storage	Classroom 27 Storage	yes	Ceiling	Plaster	Beige	None	0	0.1	Negative
1	1	27A	Storage	Classroom 27 Storage	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	28	Senior High	Classroom 28	yes	W1	Plaster	Beige	None	0	0.09	Negative
1	1	28	Senior High	Classroom 28	yes	Door Frame	Metal	Tan	Chipping	8	0.12	
1	1	28	Senior High	Classroom 28	yes	W2	Plaster	Beige	None	0	0.12	Negative
1	1	28	Senior High	Classroom 28	yes	W3	Plaster	Beige	None	0	0.3	Negative
1	1	28	Senior High	Classroom 28	yes	W4	Plaster	Beige	None	0	0.01	Negative
1	1	28	Senior High	Classroom 28	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28	Senior High	Classroom 28	yes	Floor	No Access	No Access	None	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28A	Storage	Classroom 28 Closet	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	W1	Plaster	Green	Cracking	3	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	Door Frame	Metal	Tan	Chipping	3	0.27	Negative
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	W2	Plaster	Green	None	0	0.09	Negative
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	W3	Plaster	Green	None	0	0.05	Negative
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	W4	Plaster	Green	None	0	0.11	Negative
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	Ceiling	Plaster	White	None	0	0.13	Negative
1	1	28B	Student Restrooms - Male/Female (Classroom)	Classroom 28 Restroom	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	W1	Plaster	Beige	Cracking	4	0.12	Negative
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	W2	Plaster	Beige	Cracking	3	0.09	Negative
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	W3	Plaster	Beige	Cracking/Chipping	6	0.11	Negative
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	W4	Plaster	Beige	None	0	0.15	Negative
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	Ceiling	Plaster	Beige	Cracking	6	0.2	Negative
1	1	28C	Lockers - Female	Locker Area in Classroom 28	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	W1	Plaster	Green	Chipping/Cracking	4	0.17	Negative
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	W2	Plaster	Green	None	0	0.12	Negative
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	W3	Plaster	Green	None	0	0.19	Negative
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	W4	Plaster	Green	Cracking	2	0.01	Negative
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	Ceiling	Plaster	White	Flaking	8	0.07	Negative
1	1	28D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway outside Classroom 28	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	W1	Plaster	Blue	Cracking	3	0.12	Negative
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	W2	Plaster	Blue	None	0	0.13	Negative
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	W3	Plaster	Blue	None	0	0.08	Negative
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	W4	Plaster	Blue	None	0	0.12	Negative
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	Ceiling	Plaster	White	None	0	0.06	Negative
1	1	28E	Restrooms, Staff - Male/Female	Faculty Restroom in the Hallway outside Classroom 28	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	29	School Store	School Store next to Classroom 28	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29	School Store	School Store next to Classroom 28	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29	School Store	School Store next to Classroom 28	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29	School Store	School Store next to Classroom 28	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29	School Store	School Store next to Classroom 28	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29	School Store	School Store next to Classroom 28	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	29A	Storage	School Store - Storage Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	W1	Plaster	Beige	None	0	0.15	Negative
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	W3	Plaster	Beige	Flaking	8	0.22	Negative
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H07	Circulation (Hallway)	Hallway at Classroom 28 & School Store (Corridor E)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	W1	Concrete block	White	None	0	0.1	Negative
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	W2	Concrete block	White	None	0	0.1	Negative
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	W3	Concrete block	White	None	0	0.09	Negative
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	W4	Concrete block	White	None	0	0.11	Negative
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	Ceiling	Concrete	White	None	0	0.09	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	29B	Storage	Storage in the Hallway by Nurse's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	W1	Plaster	Blue	None	0	0.14	Negative
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	W2	Plaster	Blue	None	0	0.12	Negative
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	W3	Plaster	Blue	None	0	0.2	Negative
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	W4	Plaster	Blue	None	0	0.22	Negative
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	30	Health Service Room	Infirmary next to Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	W1	Plaster	Yellow	None	0	0.24	Negative
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	W2	Plaster	Yellow	None	0	0.17	Negative
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	W3	Plaster	Yellow	None	0	0.05	Negative
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	W4	Plaster	Yellow	None	0	0.18	Negative
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	Ceiling	Plaster	White	None	0	0.2	Negative
1	1	30A	Health Service Room	Closet in Infirmary next to Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	W1	Plaster	Blue	None	0	0.01	Negative
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	Door Frame	Metal	Tan	Chipping	4	0.32	Negative
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	W2	Plaster	Blue	None	0	0.07	Negative
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	W3	Plaster	Blue	Chipping	2	0.14	Negative
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	W4	Plaster	Blue	None	0	0.09	Negative
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31	Health Service Room	Room 31 - Waiting Area in Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	31A	Health Service Room	Nurse's Office	yes	W1	Plaster	Blue	None	0	0.11	Negative
1	1	31A	Health Service Room	Nurse's Office	yes	Doorframe	Metal	Brown	Chipping	6	0.16	Negative
1	1	31A	Health Service Room	Nurse's Office	yes	W2	Plaster	Blue	None	0	0.15	Negative
1	1	31A	Health Service Room	Nurse's Office	yes	W3	Plaster	Blue	None	0	0.18	Negative
1	1	31A	Health Service Room	Nurse's Office	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	1	31A	Health Service Room	Nurse's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31A	Health Service Room	Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W1	Plaster	Blue	None	0	0.09	Negative
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W2	Plaster	Blue	None	0	0.1	Negative
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W3	Plaster	Blue	None	0	0.14	Negative
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	W4	Plaster	Blue	None	0	0.05	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	Ceiling	Plaster	White	Flaking	2	0.01	Negative
1	1	31B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	31C	Storage	Nurse's Office Closet	yes	W1	Plaster	Yellow	None	0	0.22	Negative
1	1	31C	Storage	Nurse's Office Closet	yes	W2	Plaster	Yellow	Cracking	2	0.11	Negative
1	1	31C	Storage	Nurse's Office Closet	yes	W3	Plaster	Yellow	Cracking	4	0.17	Negative
1	1	31C	Storage	Nurse's Office Closet	yes	W4	Plaster	Yellow	Cracking	2	0.22	Negative
1	1	31C	Storage	Nurse's Office Closet	yes	Ceiling	Plaster	Yellow	None	0	0.24	Negative
1	1	31C	Storage	Nurse's Office Closet	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	W1	Plaster	Blue	None	0	0.19	Negative
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	W2	Plaster	Blue	None	0	0.12	Negative
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	W3	Plaster	Blue	None	0	0.19	Negative
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	W4	Plaster	Blue	None	0	0.27	Negative
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31D	Health Service Room	Medical Exam Room next to Nurse's Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	31E	Storage	Medical Exam Room Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31E	Storage	Medical Exam Room Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31E	Storage	Medical Exam Room Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31E	Storage	Medical Exam Room Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31E	Storage	Medical Exam Room Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	31E	Storage	Medical Exam Room Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	32	Health Service Room	Physical Therapy Office	yes	W1	Plaster	Blue	None	0	0.13	Negative
1	1	32	Health Service Room	Physical Therapy Office	yes	W2	Plaster	Blue	None	0	0.04	Negative
1	1	32	Health Service Room	Physical Therapy Office	yes	W3	Plaster	Blue	None	0	0.01	Negative
1	1	32	Health Service Room	Physical Therapy Office	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	32	Health Service Room	Physical Therapy Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	32	Health Service Room	Physical Therapy Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	W1	Plaster	Blue	None	0	0.06	Negative
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	W2	Plaster	Blue	None	0	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	W3	Plaster	Blue	None	0	0.02	Negative
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	W4	Plaster	Blue	None	0	0.35	Negative
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	32A	Student Restrooms - Male/Female (Classroom)	Physical Therapy Office Restroom	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	W1	Plaster	Blue	Chipping/Flaking	20	0.09	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	Cubicle Divider	Metal	Pink	Chipped	10	0.04	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	Door Frame	Metal	Tan	Chipping	8	0.27	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	W2	Plaster	Blue	Flaking	2	0.06	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	W3	Plaster	Blue	None	0	0.08	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	W4	Plaster	Blue	None	0	0.1	Negative
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33	Health Service Room	Room 33 - Physical Therapy Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33A	Storage	Room 33 - Physical Therapy Room Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	W1	Plaster	Blue	None	0	0.07	Negative
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	W2	Plaster	Blue	Efflorescence/Chipping	12	0.12	Negative
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	W3	Plaster	Blue	None	0	0.12	Negative
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	W4	Plaster	Blue	Cracking/Flaking	4	0.06	Negative
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	33B	Health Service Room	Hydro Therapy Room in Physical Therapy Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	W1	Plaster	Blue	None	0	0.06	Negative
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	W2	Plaster	Blue	None	0	0.06	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	W3	Plaster	Blue	None	0	0.09	Negative
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	34	Student Restrooms - Female (Classroom)	Girls Restroom next to Classroom 34	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	W1	Plaster	Green	Flaking	1	0.07	Negative
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	W2	Plaster	Green	None	0	0.09	Negative
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	W3	Plaster	Green	None	0	0.14	Negative
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	W4	Plaster	Green	None	0	0.13	Negative
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	Ceiling	Plaster	White	None	0	0.08	Negative
1	1	34	Student Restrooms - Male (Classroom)	Boys Restroom next to Classroom 34	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	34	Senior High	Classroom 34	yes	W1	Plaster	White	None	0	0.04	Negative
1	1	34	Senior High	Classroom 34	yes	W2	Plaster	White	Chipping	2	0.1	Negative
1	1	34	Senior High	Classroom 34	yes	W3	Plaster	White	Chipping	1	0.14	Negative
1	1	34	Senior High	Classroom 34	yes	W4	Sheetrock	White	None	0	0.06	Negative
1	1	34	Senior High	Classroom 34	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	34	Senior High	Classroom 34	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	W1	Plaster	Blue	None	0	0.08	Negative
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	W2	Plaster	Blue	None	0	0.12	Negative
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	W3	Plaster	Blue	None	0	0.01	Negative
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35	Health Service Room	Room 35 - Occupational Therapy Room	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	34A	Senior High	Classroom 34A	yes	W1	Sheetrock	White	None	0	0.01	Negative
1	1	34A	Senior High	Classroom 34A	yes	W2	Plaster	White	None	0	0.01	Negative
1	1	34A	Senior High	Classroom 34A	yes	W3	Plaster	White	None	0	0.01	Negative
1	1	34A	Senior High	Classroom 34A	yes	W4	Plaster	White	None	0	0.4	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	34A	Senior High	Classroom 34A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	34A	Senior High	Classroom 34A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	W1	Plaster	Green	None	0	0.1	Negative
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	W2	Plaster	Green	None	0	0.09	Negative
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	W3	Plaster	Green	None	0	0.13	Negative
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	W4	Plaster	Green	Flaking	1	0.1	Negative
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35A	Health Service Room	Occupational Therapy Room Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	35B	Storage	Occupational Therapy Room Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35B	Storage	Occupational Therapy Room Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35B	Storage	Occupational Therapy Room Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35B	Storage	Occupational Therapy Room Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35B	Storage	Occupational Therapy Room Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	35B	Storage	Occupational Therapy Room Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	W1	Concrete Block	Beige	Cracking/Flaking	5	0.01	Negative
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	W2	Concrete Block	Beige	Chipping	1	0.07	Negative
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	W3	Concrete Block	Beige	None	0	0.5	Negative
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	W4	Concrete Block	Beige	None	0	0.07	Negative
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	36	Administrative Office	Room 36 - Brace Shop	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	36A	Storage	Brace Shop Storage	yes	W1	Concrete Block	Beige	None	0	0.09	Negative
1	1	36A	Storage	Brace Shop Storage	yes	W2	Concrete Block	Beige	Cracking	2	0.09	Negative
1	1	36A	Storage	Brace Shop Storage	yes	W3	Concrete Block	Beige	None	0	0.11	Negative
1	1	36A	Storage	Brace Shop Storage	yes	W4	Concrete Block	Beige	None	0	0.06	Negative
1	1	36A	Storage	Brace Shop Storage	yes	Ceiling	Concrete	White	Flaking	5	0.12	Negative
1	1	36A	Storage	Brace Shop Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	37	Senior High	Classroom 37	yes	W1	Plaster	Beige	Chipping	10	0.11	Negative
1	1	37	Senior High	Classroom 37	yes	Doorfram	Metal	Tan	Flaking	3	0.12	Negative
1	1	37	Senior High	Classroom 37	yes	W2	Plaster	Beige	None	0	0.07	Negative
1	1	37	Senior High	Classroom 37	yes	W3	Plaster	Beige	None	0	0.15	Negative
1	1	37	Senior High	Classroom 37	yes	W4	Plaster	Beige	None	0	0.09	Negative
1	1	37	Senior High	Classroom 37	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	37	Senior High	Classroom 37	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	W1	Plaster	Green	None	0	0.15	Negative
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	W2	Plaster	Green	None	0	0.19	Negative
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	W3	Plaster	Green	None	0	0.21	Negative
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	W4	Plaster	Green	None	0	0.1	Negative
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	Ceiling	Plaster	White	None	0	0.16	Negative
1	1	37A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 37	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	W1	Plaster	Beige	Cracking	2	0.17	Negative
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	W2	Plaster	Beige	None	0	0.11	Negative
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	W3	Plaster	Beige	None	0	0.11	Negative
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	W4	Plaster	Beige	None	0	0.16	Negative
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	Ceiling	Plaster	Beige	Flaking	2	0.07	Negative
1	1	37B	Storage	Storage Room between Classroom 37 and 38	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	37B	Storage	Classroom 37 Storage 1	yes	W1	Plaster	Green	None	0	0.11	Negative
1	1	37B	Storage	Classroom 37 Storage 1	yes	W2	Plaster	Green	None	0	0.17	Negative
1	1	37B	Storage	Classroom 37 Storage 1	yes	W3	Plaster	Green	Cracking/Chipping	10	0.13	Negative
1	1	37B	Storage	Classroom 37 Storage 1	yes	W4	Plaster	Green	None	0	0.11	Negative
1	1	37B	Storage	Classroom 37 Storage 1	yes	Ceiling	Plaster	Green	None	0	0.12	Negative
1	1	37B	Storage	Classroom 37 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	37C	Storage	Classroom 37 Storage 2	yes	W1	Plaster	Green	None	0	0.15	Negative
1	1	37C	Storage	Classroom 37 Storage 2	yes	W2	Plaster	Green	None	0	0.12	Negative
1	1	37C	Storage	Classroom 37 Storage 2	yes	W3	Plaster	Green	None	0	0.11	Negative
1	1	37C	Storage	Classroom 37 Storage 2	yes	W4	Plaster	Green	None	0	0.15	Negative
1	1	37C	Storage	Classroom 37 Storage 2	yes	Ceiling	Plaster	Green	None	0	0.17	Negative
1	1	37C	Storage	Classroom 37 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	W2	Plaster	Beige	Flaking	5	0.1	Negative
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	W3	Plaster	Beige	None	0	0.13	Negative
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	W4	Plaster	Beige	Flaking	2	0.11	Negative
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	37D	Circulation (Hallway)	Hallway at Classroom 37	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	W1	Plaster	Beige	None	0	0.16	Negative
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	W2	Plaster	Beige	Efflorescence	3	0.18	Negative
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	W4	Plaster	Beige	Chipping	1	0.14	Negative
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	37D	Circulation (Hallway)	Hallway at Therapy, Nurse's Office, Kitchen and Cafeteria (Corridor G)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	38	Senior High	Classroom 38	yes	W1	Plaster	Blue	None	0	0.14	Negative
1	1	38	Senior High	Classroom 38	yes	Door frame	Metal	Beige	Chipping	4	0.27	Negative
1	1	38	Senior High	Classroom 38	yes	W2	Plaster	Beige	None	0	0.17	Negative
1	1	38	Senior High	Classroom 38	yes	W3	Plaster	Beige	Chipping	1	0.14	Negative
1	1	38	Senior High	Classroom 38	yes	W4	Plaster	Beige	None	0	0.15	Negative
1	1	38	Senior High	Classroom 38	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	38	Senior High	Classroom 38	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	W1	Plaster	Blue	None	0	0.08	Negative
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	W2	Plaster	Blue	None	0	0.04	Negative
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	W3	Plaster	Blue	None	0	0.11	Negative
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	W4	Plaster	Blue	None	0	0.07	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	38A	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 38	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	38B	Storage	Classroom 38 Storage 1	yes	W1	Plaster	Blue	None	0	0.16	Negative
1	1	38B	Storage	Classroom 38 Storage 1	yes	W2	Plaster	Blue	Chipping	1	0.08	Negative
1	1	38B	Storage	Classroom 38 Storage 1	yes	W3	Plaster	Blue	Chipping	3	0.07	Negative
1	1	38B	Storage	Classroom 38 Storage 1	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	38B	Storage	Classroom 38 Storage 1	yes	Ceiling	Plaster	Blue	None	0	0.1	Negative
1	1	38B	Storage	Classroom 38 Storage 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	38C	Storage	Classroom 38 Storage 2	yes	W1	Plaster	Green	None	0	0.18	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	Door Fram	Metal	Blue	Chipping	3	0.38	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	W2	Plaster	Green	None	0	0.17	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	W3	Plaster	Green	None	0	0.14	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	W4	Plaster	Green	None	0	0.14	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	38C	Storage	Classroom 38 Storage 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	39	Senior High	Classroom 39	yes	W1	Plaster	Yellow	Chipping/Cracking	17	0.13	Negative
1	1	39	Senior High	Classroom 39	yes	Door Frame	Metal	Yellow	Chipping	5	0.22	Negative
1	1	39	Senior High	Classroom 39	yes	W2	Plaster	Yellow	None	0	0.11	Negative
1	1	39	Senior High	Classroom 39	yes	W3	Plaster	Yellow	Cracking	2	0.2	Negative
1	1	39	Senior High	Classroom 39	yes	W4	Plaster	Yellow	Chipping/Cracking	4	0.12	Negative
1	1	39	Senior High	Classroom 39	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39	Senior High	Classroom 39	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	39A	Storage	Classroom 39 Audio Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39A	Storage	Classroom 39 Audio Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39A	Storage	Classroom 39 Audio Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39A	Storage	Classroom 39 Audio Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39A	Storage	Classroom 39 Audio Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39A	Storage	Classroom 39 Audio Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	W1	Plaster	Blue	None	0	0.05	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	W2	Plaster	Blue	None	0	0.09	Negative
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	W3	Plaster	Blue	None	0	0.09	Negative
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	39B	Student Restrooms - Male/Female (Classroom)	Restroom next to Classroom 39	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	40	Senior High	Classroom 40 - Speech Room	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40	Senior High	Classroom 40 - Speech Room	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40	Senior High	Classroom 40 - Speech Room	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40	Senior High	Classroom 40 - Speech Room	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40	Senior High	Classroom 40 - Speech Room	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40	Senior High	Classroom 40 - Speech Room	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40A	Storage	Classroom 40 Storage 1	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	40B	Storage	Classroom 40 Storage 2	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	W1	Plaster	Beige	Cracking	8	0.26	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	Door Frame	Metal	Tan	Chipping	4	0.28	Negative
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	W2	Plaster	Beige	Cracking	6	0.04	Negative
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	W3	Plaster	Beige	None	0	0.05	Negative
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	W4	Plaster	Beige	Cracking	4	0.05	Negative
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	41	Teacher Lounge/Dining	Staff Dining Room next to Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	42	Kitchen	Kitchen	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	42	Kitchen	Kitchen	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	42	Kitchen	Kitchen	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	42	Kitchen	Kitchen	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
1	1	42	Kitchen	Kitchen	yes	Ceiling	Plaster	White	Flaking/Moisture Damage	75	0.01	Negative
1	1	42	Kitchen	Kitchen	yes	Floor	Concrete	N/A	N/A	N/A	N/A	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	Floor	Concrete	N/A	N/A	N/A	N/A	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	W1	Metal	Blue	N/A	N/A	0.06	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	W2	Metal	Blue	N/A	N/A	0.02	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	Baseboard	Wood	Blue	Chipping	6	0.08	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	Negative
1	1	42	Kitchen	Kitchen Manager Office	yes	Ceiling	Plaster	White	Flaking	10	0.02	Negative
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	W1	Plaster	Beige	Flaking/Chipping	20	0.06	Negative
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	W2	Plaster	Beige	Cracking	4	0.12	Negative
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	W3	Plaster	Beige	None	0	0.02	Negative
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	W4	Plaster	Beige	Flaking	6	0.21	Negative
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	43	Cafeteria (Dining Area)	Cafeteria	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	49	Storage	Room 49 - Custodial Storage	yes	W1	Plaster	Green	None	0	0.1	Negative
1	1	49	Storage	Room 49 - Custodial Storage	yes	Door Frame	Metal	Green	Chipping	6	0.29	Negative
1	1	49	Storage	Room 49 - Custodial Storage	yes	W2	Plaster	Green	None	0	0.17	Negative
1	1	49	Storage	Room 49 - Custodial Storage	yes	W3	Plaster	Green	Chipping	10	0.06	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	49	Storage	Room 49 - Custodial Storage	yes	W4	Plaster	Green	Chipping	2	0.05	Negative
1	1	49	Storage	Room 49 - Custodial Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49	Storage	Room 49 - Custodial Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	W1	Plaster	Blue	None	0	0.17	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	Door Frame	Metal	Brown	Chipping	4	0.31	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	W2	Plaster	Blue	None	0	0.26	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	W3	Plaster	Blue	None	0	0.16	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	W4	Plaster	Blue	Flaking	1	0.2	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	49A	Restrooms, Staff - Male/Female	Restroom outside Room 49	yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	49B	Service Closets	Custodial Closet in Hallway across from Kitchen	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50B	Storage	Storage Closet in Hallway outside Room 50	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50	Storage	Room 50 - Custodial Storage	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50A	Restrooms, Staff - Male/Female	Restroom in Room 50	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	W1	Plaster	Blue	None	0	0.1	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	Doorframe	Metal	Brown	chipping	1	0.08	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	W2	Plaster	Blue	None	0	0.05	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	W3	Plaster	Blue	None	0	0.04	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	W4	Plaster	Blue	None	0	0.06	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	50C	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway next to Room 50	Yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	W1	Plaster	Green	None	0	0.23	Negative
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	Door Frame	Metal	Tan	Chipping	2	0.01	Negative
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	W2	Plaster	Green	None	0	0.18	Negative
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	W3	Plaster	Green	None	0	0.18	Negative
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	W4	Plaster	Green	None	0	0.17	Negative
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	Ceiling	Plaster	White	None	0	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	50D	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Room 50	Yes	Floor	Marble	N/A	N/A	N/A	N/A	N/A
1	1	44	Music	Classroom 44 - Music Room	Yes	W1	Plaster	Beige	Flaking	1	0.14	Negative
1	1	44	Music	Classroom 44 - Music Room	Yes	W2	Plaster	Beige	None	0	0.02	Negative
1	1	44	Music	Classroom 44 - Music Room	Yes	W3	Plaster	Beige	Flaking	6	0.12	Negative
1	1	44	Music	Classroom 44 - Music Room	Yes	W4	Plaster	Beige	None	0	0.07	Negative
1	1	44	Music	Classroom 44 - Music Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44	Music	Classroom 44 - Music Room	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	44A	Storage	Music Room Storage by doorway	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44A	Storage	Music Room Storage by doorway	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44A	Storage	Music Room Storage by doorway	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44A	Storage	Music Room Storage by doorway	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44A	Storage	Music Room Storage by doorway	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44A	Storage	Music Room Storage by doorway	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44B	Storage	Music Room Closet	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44C	Music	Music Practice Rooms	Yes	W1	Plaster	Beige	None	0	0.11	Negative
1	1	44C	Music	Music Practice Rooms	Yes	Door Frame	Metal	Beige	Chipping	2	0.32	Negative
1	1	44C	Music	Music Practice Rooms	Yes	W2	Plaster	Beige	None	0	0.08	Negative
1	1	44C	Music	Music Practice Rooms	Yes	W3	Plaster	Beige	None	0	0.01	Negative
1	1	44C	Music	Music Practice Rooms	Yes	W4	Plaster	Beige	None	0	0.12	Negative
1	1	44C	Music	Music Practice Rooms	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	44C	Music	Music Practice Rooms	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	W1	Plaster	Beige	Cracking	6	0.01	Negative
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	Doorframe	Metal	Tan	Chipping	4	0.31	
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	W2	Plaster	Beige	None	0	0.03	Negative
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	W3	Plaster	Beige	Flacking/Cracking/Cjipping	13	0.01	Negative
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	W4	Plaster	Grey	None	0	0.14	Negative
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	45/46	Space (Cafeteria)	Room 45 & 46 - Dining Area	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	47	Principal/Directors Office	Room 47 front office	Yes	W1	Plaster	Blue	None	0	0.18	Negative
1	1	47	Principal/Directors Office	Room 47 front office	Yes	W2	Plaster	Blue	None	0	0.15	Negative
1	1	47	Principal/Directors Office	Room 47 front office	Yes	W3	Plaster	Blue	Chipping/Cracking	3	0.14	Negative
1	1	47	Principal/Directors Office	Room 47 front office	Yes	W4	Plaster	Blue	None	0	0.26	Negative
1	1	47	Principal/Directors Office	Room 47 front office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	47	Principal/Directors Office	Room 47 front office	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	W1	Plaster	Blue	None	0	0.13	Negative
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	W2	Plaster	Blue	None	0	0.15	Negative
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	W3	Plaster	Blue	None	0	0.08	Negative
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	W4	Plaster	Blue	None	0	0.11	Negative
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	47	Principal/Directors Office	Vice Principals Office 47	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	48	Storage	Room 48 - Storage Room	Yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	48	Storage	Room 48 - Storage Room	Yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	48	Storage	Room 48 - Storage Room	Yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	48	Storage	Room 48 - Storage Room	Yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	48	Storage	Room 48 - Storage Room	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	48	Storage	Room 48 - Storage Room	Yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	W1	Plaster	Beige	Chipping	8	0.1	Negative
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	W3	Plaster	Beige	Chipping	2	0.22	Negative
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	H13	Circulation (Hallway)	Hallway at Music Room and Vice Principals Office	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	W1	Concrete Block	Gray	Chipping	3	0.04	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Railing	Metal	Green	Friction	30	0.29	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Newl Post	Metal	Green	Chipping	3	0.41	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Riser	Metal	Green	Chipping	15	0.3	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	W2	Concrete Block	Gray	None	0	0.01	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	yes	Door	Metal	Green	Chipping	20	0.25	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Door Frame	Metal	Green	Chipping	10	0.32	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	W3	Concrete Block	Gray	Cracking	3	0.04	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	W4	Concrete Block	Gray	Chipping	3	0.07	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Ceiling	Concrete	White	Chipping	5	0.03	Negative
1	1	S1	Stairs	Stairwell #1 - In Gym Office Area	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	W1	Concrete Block	Tan	Cracking	6	0.06	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	W2	Concrete Block	Tan	None	0	0.01	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	W3	Concrete Block	Tan	None	0	0.06	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	Railing	Metal	Tan	Chipping	10	0.08	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	W4	Concrete Block	Tan	None	0	0.09	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	Ceiling	Concrete	White	Chipping/Cracking	4	0.08	Negative
1	1	S2	Stairs	Stairwell #2 - Next to Nurse's Suite	Yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	W1	Concrete Block	Tan	None	0	0.01	Negative
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	W2	Concrete Block	Tan	Cracking	2	0.01	Negative
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	W3	Concrete Block	Tan	None	0	0.29	Negative
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	W4	Concrete Block	Tan	Cracking	2	0.01	Negative
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	Ceiling	Concrete	White	None	0	0.05	Negative
1	1	S3	Stairs	Stairwell #3 - Near Cafeteria	Yes	Floor	Concrete	Tan	None	0	0.06	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	W1	Concrete Block	White	Holes	10	0.01	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	Door	Metal	Blue	Chipping	20	0.32	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	Door Frame	Metal	Blue	Chipping	10	0.34	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	W2	Concrete Block	White	None	0	0.01	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	W3	Brick	White	Flaking	150	0.01	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	W4	Concrete Block	White	None	0	0.03	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	Ceiling	Concrete	White	Flaking/Chipping	25	0.02	Negative
1	2	PH01	Mechanical Room	Penthouse Mechanical Rooms	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B02	Electrical Room	Electrical Room in Basement	No	W1	Concrete Block	Grey	Cracking	8	0.01	Negative
1	B	B02	Electrical Room	Electrical Room in Basement	No	W2	Concrete	Grey	Holes	20	0.05	Negative
1	B	B02	Electrical Room	Electrical Room in Basement	No	W3	Concrete Block	Beige	Cracking	15	0.06	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	B02	Electrical Room	Electrical Room in Basement	No	W4	Concrete Block	Grey	Cracking	20	0.04	Negative
1	B	B02	Electrical Room	Electrical Room in Basement	No	Ceiling	Concrete	White	Flaking	20	0.03	Negative
1	B	B02	Electrical Room	Electrical Room in Basement	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	W1	Concrete Block	Grey	Holes/Flaking	40	0.07	Negative
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	W2	Concrete Block	Grey	None	0	0.04	Negative
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	W3	Concrete Block	Grey	Chipping/Flaking	20	0.07	Negative
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	W4	Brick	Grey	Flaking	10	0.15	Negative
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	Ceiling	Concrete	White	Chipping	20	0.08	Negative
1	B	B03A	Mechanical Room	Tank Room next to Electrical Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	W1	Concrete Block	N/A	N/A	N/A	N/A	N/A
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	W2	Concrete Block	N/A	N/A	N/A	N/A	N/A
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	W3	Concrete Block	N/A	N/A	N/A	N/A	N/A
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	W4	Concrete Block	N/A	N/A	N/A	N/A	N/A
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	Ceiling	Concrete	Black	Cracking/Flacking	10	0.09	Negative
1	B	B03B	Mechanical Room	Light and Bulb Room next to Tank Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04	Boiler Room	Boiler Room	No	W1	Concrete	Grey	Flaking	100	0.08	Negative
1	B	B04	Boiler Room	Boiler Room	No	Railing	Metal	Blue	CHipping	15	0.17	Negative
1	B	B04	Boiler Room	Boiler Room	No	W2	Concrete	Grey	Flaking	150	0.08	Negative
1	B	B04	Boiler Room	Boiler Room	No	W3	Concrete	Grey	Flaking	150	0.04	Negative
1	B	B04	Boiler Room	Boiler Room	No	W4	Concrete	Grey	Flaking	75	0.06	Negative
1	B	B04	Boiler Room	Boiler Room	No	Ceiling	Concrete	White	Flaking/Chipping	100	0.06	Negative
1	B	B04	Boiler Room	Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B04A	Mechanical Room	Pump Room next to Boiler Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05	Electrical Room	2nd Electrical Room next To Pump Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05A	Storage	Storage at 2nd Electrical Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B05B	Storage	Storage next to Tank Room	No	W1	Concrete Block	Beige	Cracking/Chipping	2	0.06	Negative
1	B	B05B	Storage	Storage next to Tank Room	No	W2	Plaster	Beige	Flaking	3	0.01	Negative
1	B	B05B	Storage	Storage next to Tank Room	No	W3	Plaster	Beige	None	0	0.08	Negative
1	B	B05B	Storage	Storage next to Tank Room	No	W4	Concrete Block	Beige	None	0	0.01	Negative
1	B	B05B	Storage	Storage next to Tank Room	No	Ceiling	Concrete	Beige	Chipping	3	0.03	Negative
1	B	B05B	Storage	Storage next to Tank Room	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B06	Administrative Office	Building Engineer's Office	no	W1	Concrete Block	Whie	None	0	0.16	Negative
1	B	B06	Administrative Office	Building Engineer's Office	no	W2	Concrete Block	White	None	0	0.14	Negative
1	B	B06	Administrative Office	Building Engineer's Office	no	W3	Brick	Blue	None	0	0.09	Negative
1	B	B06	Administrative Office	Building Engineer's Office	no	W4	Concrete Block	White	None	0	0.1	Negative
1	B	B06	Administrative Office	Building Engineer's Office	no	Ceiling	Concrete	White	Flaking	30	0.06	Negative
1	B	B06	Administrative Office	Building Engineer's Office	no	Floor	Concrete	Grey	Chipping	30	0.04	Negative
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	W1	Concrete Block	Green	Flaking	1	0.06	Negative
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	W2	Concrete Block	Green	None	0	0.07	Negative
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	W3	Concrete Block	Green	Cracking	6	0.06	Negative
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	W4	Concrete Block	Green	Cracking	4	0.08	Negative
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B07	Teacher Lounge/Dining	NW Regional Store Room next to Loading Dock	No	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	W3	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B08	Kitchen and Dry Storage Area	Equipement Paint Room	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	W1	Concrete Block	White	Cracking	4	0.02	Negative
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	W2	Concrete Block	White	None	0	0.12	Negative
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	W3	Concrete Block	White	None	0	0.07	Negative
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	W4	Concrete Block	White	Cracking	4	0.08	Negative
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	Ceiling	Concrete	White	Cracking	3	0.06	Negative
1	B	B08A	Lockers - Male	Men's Locker Room next to Stairwell	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	W1	Concrete Block	White	None	0	0.01	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	Door Frame	Metal	Tan	Chipping	4	0.16	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	W2	Concrete Block	White	Cracking	8	0.06	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	W3	Concrete Block	White	Cracking	5	0.08	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	W4	Concrete Block	White	Cracking	5	0.08	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	Ceiling	Concrete	White	Cracking	12	0.12	Negative
1	B	B808C	Restrooms, Staff - Male	Men's Restroom in Men's Locker Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	W1	Concrete Block	White	Cracking	7	0.11	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	W2	Concrete Block	White	Flaking	20	0.04	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	W3	Concrete Block	White	None	0	0.01	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	W4	Concrete Block	White	Cracking	6	0.09	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	Ceiling	Concrete	White	Flaking	10	0.08	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	B808D	Restrooms, Staff - Female	Women's Locker Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	W1	Concrete Block	White	Cracking	4	0.03	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	W2	Concrete Block	White	None	0	0.01	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	W3	Concrete Block	White	Cracking	10	0.14	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	W4	Concrete Block	White	None	0	0.11	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	Ceiling	Concrete	White	Flaking	12	0.08	Negative
1	B	B808D	Restrooms, Staff - Female	Women's Restroom next to Men's Locker Room	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	BS1	Storage	Storage next to Water Fountain	no	W1	No Access	No Access	No Access	No Access		
1	B	BS1	Storage	Storage next to Water Fountain	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	BS1	Storage	Storage next to Water Fountain	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	BS1	Storage	Storage next to Water Fountain	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	BS1	Storage	Storage next to Water Fountain	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	BS1	Storage	Storage next to Water Fountain	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	W1	Concrete Block	White	Cracking	10	0.02	Negative
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	W2	Concrete Block	White	None	0	0.01	Negative
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	W3	Concrete Block	White	None	0	0.05	Negative
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	W4	Concrete Block	White	None	0	0.22	Negative
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	Ceiling	Concrete	White	Efflorescence/Flaking	12	0.1	Negative
1	B	HB1	Circulation (Hallway)	Basement Hallway at Loading Dock	no	Floor	Concrete	Brown	Chipping	10	0.01	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	W1	Concrete Block	Beige	None	0	0.07	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	W2	Concrete Block	Beige	None	0	0.08	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	W3	Concrete Block	Beige	None	0	0.04	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	W4	Concrete Block	Beige	None	0	0.13	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	Ceiling	Concrete	Beige	None	0	0.1	Negative
1	B	B09	Mechanical Room	Elevator Room at Loading Dock	no	Floor	Concrete	Grey	None	0	0.05	Negative
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	W1	Concrete Block	Beige	None	0	0.06	Negative
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	W2	Concrete Block	Beige	Cracking	12	0.01	Negative
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	W3	Plaster	Beige	None	0	0.1	Negative
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	W4	Concrete Block	Beige	None	0	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	Ceiling	Concrete	Beige	None	0	0.05	Negative
1	B	B09	Mechanical Room	Gas Meter Room at Loading Dock	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	W1	Concrete Block	Tan	None	0	0.01	Negative
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	W2	Concrete Block	Blue	None	0	0.04	Negative
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	W3	Concrete Block	Blue	None	0	0.11	Negative
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	W4	Concrete Block	Tan	None	0	0.05	Negative
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	Ceiling	Concrete	Beige	Chipped	3	0.07	Negative
1	B	B09	Mechanical Room	Water Meter Room at Loading Dock	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	W1	Concrete Block	Beige	None	0	0.04	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	W2	Plaster	Beige	None	0	0.01	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	Railing	Metal	Tan	Chipped	2	0.23	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	W3	Plaster	Beige	None	0	0.07	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	W4	Concrete	Beige	None	0	0.12	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	Ceiling	Concrete	White	None	0	0.13	Negative
1	B	S1	Stairs	Stairwell #1 - Mechanical Area	no	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	W1	Concrete Block	Beige	None	0	0.06	Negative
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	W2	Concrete Block	Beige	None	0	0.08	Negative
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	W3	Concrete Block	Beige	None	0	0.21	Negative
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	W4	Concrete Block	Beige	None	0	0.08	Negative
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	Ceiling	Concrete	White	None	0	0.07	Negative
1	B	S2	Stairs	Stairwell #2 - Next to Men's Locker Area	no	Floor	Concrete	Grey	None	0	0.01	Negative
2	1	101	Senior High	Classroom 101	yes	W1	Sheetrock	Beige	Flaking	4	0.07	Negative
2	1	101	Senior High	Classroom 101	yes	Door Frame	Metal	Tan	Chipping	4	0.13	
2	1	101	Senior High	Classroom 101	yes	W2	Sheetrock	Beige	None	0	0.08	Negative
2	1	101	Senior High	Classroom 101	yes	W3	Sheetrock	Beige	None	0	0.11	Negative
2	1	101	Senior High	Classroom 101	yes	W4	Sheetrock	Beige	None	0	0.06	Negative
2	1	101	Senior High	Classroom 101	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	101	Senior High	Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	0.12	Negative
2	1	101A	Storage	Classroom 101 Storage #1	yes	W1	Sheetrock	Pink	None	0	0.12	Negative
2	1	101A	Storage	Classroom 101 Storage #1	yes	W2	Sheetrock	Pink	None	0	0.08	Negative
2	1	101A	Storage	Classroom 101 Storage #1	yes	W3	Sheetrock	Pink	None	0	0.07	Negative
2	1	101A	Storage	Classroom 101 Storage #1	yes	W4	Sheetrock	Pink	None	0	0.07	Negative
2	1	101A	Storage	Classroom 101 Storage #1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	101A	Storage	Classroom 101 Storage #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	101A	Storage	Classroom 101 Storage #2	yes	W1	Sheetrock	Beige	None	0	0.17	Negative
2	1	101A	Storage	Classroom 101 Storage #2	yes	W2	Sheetrock	Beige	None	0	0.14	Negative
2	1	101A	Storage	Classroom 101 Storage #2	yes	W3	Sheetrock	Beige	None	0	0.06	Negative
2	1	101A	Storage	Classroom 101 Storage #2	yes	W4	Sheetrock	Beige	None	0	0.14	Negative
2	1	101A	Storage	Classroom 101 Storage #2	yes	Ceiling	Plaster	Beige	Chipped	2	0.12	Negative
2	1	101A	Storage	Classroom 101 Storage #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Doorframe	Metal	tan	Chipping	4	0.01	
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Ceiling	Sheetrock	White	None	0	0.04	Negative
2	1	101B	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	W1	Sheetrock	Beige	None	0	0.09	Negative
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	Door Frame	Metal	Tan	Chipping	6	0.1	
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	W2	Sheetrock	Beige	None	0	0.07	Negative
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	W3	Sheetrock	Beige	None	0	0.04	Negative
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	W4	Sheetrock	Beige	NOne	0	0.06	Negative
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102A	Administrative Office	Women Staff Office next to Classroom 101	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	Ceiling	Sheetrock	White	None	0	0.05	Negative
2	1	102AR	Student Restrooms - Male/Female (Classroom)	Women Staff Office Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102B	Administrative Office	Office next to Classroom 103	yes	W1	Sheetrock	Beige	None	0	0.05	Negative
2	1	102B	Administrative Office	Office next to Classroom 103	yes	Door Frame	Metal	Tan	Chipping	3	0.08	
2	1	102B	Administrative Office	Office next to Classroom 103	yes	W2	Sheetrock	Beige	None	0	0.01	Negative
2	1	102B	Administrative Office	Office next to Classroom 103	yes	W3	Sheetrock	Beige	None	0	0.08	Negative
2	1	102B	Administrative Office	Office next to Classroom 103	yes	W4	Sheetrock	Beige	None	0	0.06	Negative
2	1	102B	Administrative Office	Office next to Classroom 103	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102B	Administrative Office	Office next to Classroom 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102C	Storage	Storage outside Women Staff Room 102A	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	Door Frame	Metal	Tan	Chipping	2	0.01	Negative
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	Ceiling	Sheetrock	White	None	0	0.12	Negative
2	1	102	Student Restrooms - Female (4-12)	Girl's Restroom in the Hallway by Classroom 103	yes	Floor	Ceramic tile	N/A	N/A	N/A	N/A	N/A
2	1	103	Senior High	Classroom 103	yes	W1	Sheetrock	beige	None	0	0.07	Negative
2	1	103	Senior High	Classroom 103	yes	Door Frame	Metal	Tan	Chipping	8	0.14	Negative
2	1	103	Senior High	Classroom 103	yes	W2	Sheetrock	beige	None	0	0.04	Negative
2	1	103	Senior High	Classroom 103	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	103	Senior High	Classroom 103	yes	W4	Sheetrock	beige	None	0	0.01	Negative
2	1	103	Senior High	Classroom 103	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	103	Senior High	Classroom 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	103A	Storage	Storage by Classroom 103	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	103A	Storage	Storage by Classroom 103	yes	W2	Sheetrock	Beige	None	0	0.07	Negative
2	1	103A	Storage	Storage by Classroom 103	yes	W3	Sheetrock	Beige	None	0	0.11	Negative
2	1	103A	Storage	Storage by Classroom 103	yes	W4	Sheetrock	Beige	None	0	0.04	Negative
2	1	103A	Storage	Storage by Classroom 103	yes	Ceiling	Sheetrock	Beige	None	0	0.11	Negative
2	1	103A	Storage	Storage by Classroom 103	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	104	Senior High	Classroom 104	yes	W1	Sheetrock	Beige	None	0	0.03	Negative
2	1	104	Senior High	Classroom 104	yes	Door Frame	Metal	Tan	Chipping	3	0.05	Negative
2	1	104	Senior High	Classroom 104	yes	W2	Sheetrock	Beige	None	0	0.06	Negative
2	1	104	Senior High	Classroom 104	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	104	Senior High	Classroom 104	yes	W4	Sheetrock	Beige	None	0	0.1	Negative
2	1	104	Senior High	Classroom 104	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104	Senior High	Classroom 104	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	104A	Storage	Classroom 104 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104A	Storage	Classroom 104 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104A	Storage	Classroom 104 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104A	Storage	Classroom 104 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104A	Storage	Classroom 104 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	104A	Storage	Classroom 104 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105	Senior High	Classroom 105	yes	W1	Sheetrock	Beige	Chipping	3	0.03	Negative
2	1	105	Senior High	Classroom 105	yes	Door Frame	Metal	Tan	Chipping	4	0.01	Negative
2	1	105	Senior High	Classroom 105	yes	W2	Sheetrock	Beige	None	0	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	105	Senior High	Classroom 105	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	105	Senior High	Classroom 105	yes	W4	Sheetrock	Beige	Chipping	1	0.04	Negative
2	1	105	Senior High	Classroom 105	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105	Senior High	Classroom 105	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	105A	Storage	Classroom 105 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105A	Storage	Classroom 105 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105A	Storage	Classroom 105 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105A	Storage	Classroom 105 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105A	Storage	Classroom 105 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	105A	Storage	Classroom 105 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	106	Senior High	Classroom 106	yes	W1	Sheetrock	Beige	chipping	2	0.06	Negative
2	1	106	Senior High	Classroom 106	yes	Door Frame	Metal	Tan	Chipping	4	0.12	Negative
2	1	106	Senior High	Classroom 106	yes	W2	Sheetrock	Beige	None	0	0.01	Negative
2	1	106	Senior High	Classroom 106	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	106	Senior High	Classroom 106	yes	W4	Sheetrock	Beige	None	0	0.06	Negative
2	1	106	Senior High	Classroom 106	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	106	Senior High	Classroom 106	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	106A	Storage	Classroom 106 Storage	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	106A	Storage	Classroom 106 Storage	yes	W2	Sheetrock	Beige	None	0	0.05	Negative
2	1	106A	Storage	Classroom 106 Storage	yes	W3	Sheetrock	Beige	None	0	0.04	Negative
2	1	106A	Storage	Classroom 106 Storage	yes	W4	Sheetrock	Beige	None	0	0.09	Negative
2	1	106A	Storage	Classroom 106 Storage	yes	Ceiling	Sheetrock	Beige	None	0	0.08	Negative
2	1	106A	Storage	Classroom 106 Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	W1	Metal	Brown	None	0	0.01	Negative
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	W2	Sheetrock	Beige	Flaking	1	0.01	Negative
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	W3	Metal	Brown	None	0	0.01	Negative
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	W4	Sheetrock	Beige	Chipping	2	0.04	Negative
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	RF	Circulation (Hallway)	Rear Foyer between Classrooms 106 & 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	107	Senior High	Classroom 107	yes	W1	Sheetrock	Beige	Chipping	6	0.07	Negative
2	1	107	Senior High	Classroom 107	yes	Door Frame	Metal	Tan	Chipping	4	0.08	Negative
2	1	107	Senior High	Classroom 107	yes	W2	Sheetrock	Beige	None	0	0.13	Negative
2	1	107	Senior High	Classroom 107	yes	W3	Sheetrock	Beige	Hole	1	0.01	Negative
2	1	107	Senior High	Classroom 107	yes	W4	Sheetrock	Beige	Cracking	1	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	107	Senior High	Classroom 107	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	107	Senior High	Classroom 107	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	107A	Storage	Classroom 107 Storage	yes	W1	Sheetrock	White	Hole	1	0.06	Negative
2	1	107A	Storage	Classroom 107 Storage	yes	W2	Sheetrock	White	None	0	0.08	Negative
2	1	107A	Storage	Classroom 107 Storage	yes	W3	Sheetrock	White	None	0	0.05	Negative
2	1	107A	Storage	Classroom 107 Storage	yes	W4	N/A	N/A	N/A	N/A	N/A	N/A
2	1	107A	Storage	Classroom 107 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	107A	Storage	Classroom 107 Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	W1	N/A	N/a	N/A	N/A	N/A	N/A
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	W2	Sheetrock	Blue	None	0	0.03	Negative
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	W3	Sheetrock	Blue	None	0	0.11	Negative
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	W4	Sheetrock	Blue	None	0	0.19	Negative
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	Ceiling	Sheetrock	Blue	None	0	0.07	Negative
2	1	107B	Storage	Classroom 107 Storage Closet by doorway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	108	Senior High	Classroom 108	yes	W1	Sheetrock	Yellow	Chipping/Cracking	4	0.14	Negative
2	1	108	Senior High	Classroom 108	yes	Door Frame	Sheetrock	Yellow	Chipping	6	0.08	Negative
2	1	108	Senior High	Classroom 108	yes	W2	Sheetrock	Yellow	None	0	0.09	Negative
2	1	108	Senior High	Classroom 108	yes	W3	Sheetrock	N/A	N/A	N/A	N/A	N/A
2	1	108	Senior High	Classroom 108	yes	W4	Sheetrock	Yellow	None	0	0.12	Negative
2	1	108	Senior High	Classroom 108	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	108	Senior High	Classroom 108	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	W2	Sheetrock	Beige	None	0	0.05	Negative
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	W3	Sheetrock	Beige	None	0	0.16	Negative
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	W4	Sheetrock	Beige	None	0	0.08	Negative
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	Ceiling	Sheetrock	Beige	None	0	0.12	Negative
2	1	108A	Storage	Classroom 108 Storage Closet by doorway	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	109	Senior High	Classroom 109	yes	W1	Sheetrock	Yellow	chipping	6	0.1	Negative
2	1	109	Senior High	Classroom 109	yes	Door Frame	metal	yellow	chipping	10	0.06	N/A
2	1	109	Senior High	Classroom 109	yes	W2	Sheetrock	Yellow	None	0	0.15	Negative
2	1	109	Senior High	Classroom 109	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	109	Senior High	Classroom 109	yes	W4	Sheetrock	Yellow	None	0	0.07	Negative
2	1	109	Senior High	Classroom 109	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109	Senior High	Classroom 109	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	109A	Storage	Classroom 109 Storage	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109A	Storage	Classroom 109 Storage	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109A	Storage	Classroom 109 Storage	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109A	Storage	Classroom 109 Storage	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109A	Storage	Classroom 109 Storage	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	109A	Storage	Classroom 109 Storage	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	110	Senior High	Classroom 110	yes	W1	Sheetrock	beige	Chipping	4	0.09	Negative
2	1	110	Senior High	Classroom 110	yes	Door Frame	Metaql	beige	Chipping	7	0.1	Negative
2	1	110	Senior High	Classroom 110	yes	Cabinet Door	Metal	Green	Flaking	4	0.25	Negative
2	1	110	Senior High	Classroom 110	yes	W2	Sheetrock	beige	None	0	0.06	Negative
2	1	110	Senior High	Classroom 110	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	110	Senior High	Classroom 110	yes	W4	Sheetrock	beige	None	0	0.14	Negative
2	1	110	Senior High	Classroom 110	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	110	Senior High	Classroom 110	yes	Floor	Concrete	N/A	N/A	N/a	N/A	N/A
2	1	110A	Storage	Classroom 110 Storage	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	110A	Storage	Classroom 110 Storage	yes	W2	Sheetrock	beige	None	0	0.07	Negative
2	1	110A	Storage	Classroom 110 Storage	yes	W3	Sheetrock	beige	None	0	0.09	Negative
2	1	110A	Storage	Classroom 110 Storage	yes	W4	Sheetrock	beige	None	0	0.09	Negative
2	1	110A	Storage	Classroom 110 Storage	yes	Ceiling	Sheetrock	beige	None	0	0.08	Negative
2	1	110A	Storage	Classroom 110 Storage	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	W1	Sheetrock	Green	None	0	0.06	Negative
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	W2	Sheetrock	Green	None	0	0.05	Negative
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	W3	Sheetrock	Green	None	0	0.02	Negative
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	W4	Sheetrock	Green	None	0	0.06	Negative
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111A	Administrative Office	Office 111A next to Classroom 110	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	Door Frame	Metal	Brown	Chipping	3	0.04	Negative
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	Ceiling	Sheetrock	White	None	0	0.11	Negative
2	1	111	Student Restrooms - Male (4-12)	Boy's Restroom in the Hallway next to Classroom 110	yes	Floor	Ceramic tile	N/A	N/A	N/A	N/A	N/A
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	W1	Sheetrock	Beige	Cracking	7	0.07	Negative
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	W2	Sheetrock	Beige	Chipping	2	0.07	Negative
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	W3	Sheetrock	Beige	None	0	0.08	Negative
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	W4	Sheetrock	Beige	None	0	0.1	Negative
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111B	Administrative Office	Office 111B next to Office 111A	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	Ceiling	Sheetrock	White	None	0	0.08	Negative
2	1	111C	Restrooms, Staff - Male/Female	Staff Restroom next to Office 111B	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	W1	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	W2	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	W3	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	W4	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	111D	Service Closets	Custodial Closet by Classroom 110	yes	Floor	No Access	No Access	No Access	No Access	No Access	No Access
2	1	112	Senior High	Classroom 112	yes	W1	Sheetrock	Gold	Chipping	10	0.08	Negative
2	1	112	Senior High	Classroom 112	yes	Door Frame	Metal	Yellow	Chipping	7	0.11	Negative
2	1	112	Senior High	Classroom 112	yes	W2	Sheetrock	Yellow	None	0	0.11	Negative
2	1	112	Senior High	Classroom 112	yes	W3	Sheetrock	Gold	None	0	0.07	Negative
2	1	112	Senior High	Classroom 112	yes	W4	Sheetrock	White	Chipping	1	0.01	Negative
2	1	112	Senior High	Classroom 112	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	112	Senior High	Classroom 112	yes	Floor	Concrete	N/A	N/A	N/A	0.14	Negative
2	1	112A	Storage	Classroom 112 Storage #1	yes	W1	Sheetrock	Yellow	None	0	0.11	Negative
2	1	112A	Storage	Classroom 112 Storage #1	yes	W2	Sheetrock	Yellow	None	0	0.12	Negative
2	1	112A	Storage	Classroom 112 Storage #1	yes	W3	Sheetrock	Yellow	None	0	0.11	Negative
2	1	112A	Storage	Classroom 112 Storage #1	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
2	1	112A	Storage	Classroom 112 Storage #1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	112A	Storage	Classroom 112 Storage #1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	112A	Storage	Classroom 112 Storage #2	yes	W1	Sheetrock	Beige	None	0	0.06	Negative
2	1	112A	Storage	Classroom 112 Storage #2	yes	W2	Sheetrock	Beige	None	0	0.01	Negative
2	1	112A	Storage	Classroom 112 Storage #2	yes	W3	Sheetrock	Beige	None	0	0.11	Negative
2	1	112A	Storage	Classroom 112 Storage #2	yes	W4	Sheetrock	Beige	None	0	0.11	Negative
2	1	112A	Storage	Classroom 112 Storage #2	yes	Ceiling	Sheetrock	White	None	0	0.08	Negative
2	1	112A	Storage	Classroom 112 Storage #2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	W1	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
						Door Frame	Metal	Brown	Chipping	3	0.01	Negative
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	W2	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	W3	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	W4	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	Ceiling	Sheetrock	White	None	0	0.12	Negative
2	1	112B	Student Restrooms - Male/Female (Classroom)	Classroom 112 Restroom	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	W1	Sheetrock	Beige	Chipping	10	0.06	Negative
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	W2	Sheetrock	Beige	Chipping	12	0.01	Negative
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	W3	Sheetrock	Blue	None	0	0.01	Negative
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	W4	Sheetrock	Beige	Chipping	18	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	H08	Circulation (Hallway)	Hallway in High School Wing (Corridor H)	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	W1	N/A	N/A	N/A	N/A	N/A	N/A
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	W2	Plaster	Beige	None	0	0.01	Negative
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	W3	N/A	N/A	N/A	N/A	N/A	N/A
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	W4	Plaster	Beige	None	0	0.17	Negative
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
2	1	H09	Circulation (Hallway)	Hallway at High School Exit	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	W1	Sheetrock	White	None	None	0.33	Negative
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	Door Frame	Metal	Green	Chipping	8	0.05	Negative
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	W2	Sheetrock	White	None	0	0.01	Negative
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	W3	Sheetrock	White	Spalling	2	0.01	Negative
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	W4	Sheetrock	White	Chipped	2	0.15	Negative
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P001	Mechanical Room	Room 001 - Mechanical Room to the left of entrance to Pool Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	W1	Sheetrock	Beige	None	0	0.01	Negative
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	W2	Sheetrock	Beige	None	0	0.01	Negative
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	W3	Sheetrock	Beige	None	0	0.01	Negative
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	W4	Sheetrock	Beige	None	0	0.02	Negative
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P104	Restrooms, Staff - Male	Room 104 - Men's Restroom at Pool Area	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	W1	Sheetrock	Beige	None	N/A	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	W2	Sheetrock	Beige	None	N/A	0.01	Negative
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	W3	Sheetrock	Beige	None	N/A	0.02	Negative
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	W4	Sheetrock	Beige	None	N/A	0.02	Negative
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P105	Restrooms, Staff - Female	Room 105 - Women's Restroom at Pool Area	yes	Floor	Ceramic Tile	N/A	N/A	N/a	N/A	N/A
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	W1	Sheetrock	Beige	None	0	0.08	Negative
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	W2	Sheetrock	Beige	Hole	1	0.01	Negative
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	W3	Sheetrock	Beige	None	0	0.01	Negative
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	W4	Sheetrock	Beige	None	0	0.01	Negative
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P106	Student Restrooms - Male (4-12)	Room 106 - Changing Room 1	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	Ceiling	Sheetrock	White	None	0	0.01	Negative
3	1	P106A	Student Restrooms - Male (4-12)	Shower Room inside Changing Room 1	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	W1	Sheetrock	Beige	None	0	0.08	Negative
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	W2	Sheetrock	Beige	None	0	0.05	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	W3	Sheetrock	Beige	None	0	0.03	Negative
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	W4	Sheetrock	Beige	None	0	0.01	Negative
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P107	Student Restrooms - Female (4-12)	Room 107 - Changing Room 2	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	W1	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	W2	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	W3	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	W4	Ceramic	N/A	N/A	N/A	N/A	N/A
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	Ceiling	Sheetrock	White	None	0	0.01	Negative
3	1	P107A	Student Restrooms - Female (4-12)	Shower Room inside Changing Room 2	yes	Floor	Ceramic Tile	N/A	N/A	N/A	N/A	N/A
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	W1	Sheetrock	White	None	0	0.01	Negative
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	W2	Sheetrock	White	None	0	0.01	Negative
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	W3	Sheetrock	White	None	0	0.01	Negative
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	W4	Sheetrock	Grey	None	0	0.01	Negative
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P108	Administrative Office	Room 108 - Mr. Scanlon's Office in Pool Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P109	Storage	Room 109 - Storage at Pool	yes	W1	Sheetrock	White	None	0	0.03	Negative
3	1	P109	Storage	Room 109 - Storage at Pool	yes	W2	Sheetrock	White	None	0	0.01	Negative
3	1	P109	Storage	Room 109 - Storage at Pool	yes	W3	Sheetrock	White	None	0	0.01	Negative
3	1	P109	Storage	Room 109 - Storage at Pool	yes	W4	Sheetrock	White	None	0	0.08	Negative
3	1	P109	Storage	Room 109 - Storage at Pool	yes	Ceiling	No Access	No Access	None	No Access	No Access	No Access
3	1	P109	Storage	Room 109 - Storage at Pool	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	W1	Sheetrock	Beige	None	0	0.01	Negative
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	W2	Sheetrock	Beige	None	0	0.01	Negative

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	W3	Sheetrock	Beige	None	0	0.07	Negative
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	W4	Sheetrock	Beige	None	0	0.01	Negative
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	P110	Laundry/Towel Distribution	Room 110 - Laundry Room at Pool Area	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	W1	Sheetrock	Beige	Chipping	3	0.01	Negative
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	Door Frame	Metal	Green	Chipping	3	0.11	Negative
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	W2	Sheetrock	Beige	Chipping	10	0.01	Negative
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	W3	Sheetrock	Beige	Chipping	8	0.08	Negative
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	W4	Sheetrock	Beige	Chipping	2	0.08	Negative
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	Ceiling	Sheetrock	Beige	None	0	N/A	N/A
3	1	P112	Lockers - Male	Room 112 - Boy's Locker Room at Pool	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	W1	Sheetrock	Beige	chipping	4	0.08	Negative
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	W2	Sheetrock	Beige	chipping	3	0.03	Negative
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	W3	Sheetrock	Beige	chipping	5	0.01	Negative
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	W4	Sheetrock	Beige	chipping	5	0.01	Negative
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	Ceiling	Sheetrock	Beige	chipping	2	0.07	Negative
3	1	P113	Lockers - Female	Room 113 - Girl's Locker Room at Pool	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	W1	Sheetrock	Beige	None	0	0.04	Negative
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	W2	Sheetrock	Beige	Chipping	4	0.07	Negative
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	W3	Concrete Block	Beige	Spalling	5	0.11	Negative
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	W4	Sheetrock	Beige	None	0	0.01	Negative
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	Ceiling	Sheetrock	Beige	Cracking/Flaking	10	0.01	Negative
3	1	H01	Circulation (Hallway)	Hallway/Lounge at Pool Entrance	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	W1	Sheetrock	Beige	None	0	0.01	Negative
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	W2	Sheetrock	Beige	None	0	0.01	Negative
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	W3	Sheetrock	Beige	None	0	0.31	Negative
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	W4	Sheetrock	Beige	Spalling/Chipping	16	0.03	Negative
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	Ceiling	Sheetrock	White	Chipping	2	0.01	Negative
3	1	H02	Circulation (Hallway)	Hallway at Pool Office/Restrooms/Laundry	yes	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	Railing	N/A	Red	Chipping	30	0.34	

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
3	B	PBMR	Mechanical Room	Mechanical Room under Pool	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Room #7	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Attic adjacent to Penthouse	No	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space Entrance Door adjacent to Boiler Rm	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SW Wing	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

						School District of Philadelphia						
			Name of Inspector: Jim Mongan			Lead Safe Certification Assessment Report						
			Inspection Company: VERTEX			Widener School						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	C	CS	Crawl Space	Crawl Space adjacent to Basement SE Wing	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Central Basement	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space in Basement	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	CS	Crawl Space	Crawl Space adjacent to Basement Storage Closet	No	Floor	No Access	No Access	No Access	No Access	No Access	No Access