

PAINT AND PLASTER STABILIZATION
GEORGE SHARSWOOD ELEMENTARY SCHOOL

2300 South 2nd Street
Philadelphia, Pennsylvania 19148
ULCS# 2630

prepared for:

THE SCHOOL DISTRICT OF PHILADELPHIA
OFFICE OF ENVIRONMENTAL MANAGEMENT

440 North Broad Street
3rd Floor
Philadelphia, Pennsylvania 19130

prepared by:

SYNERTECH INCORPORATED

228 Moore Street
Philadelphia, Pennsylvania 19148
Project # 010-4467

November 3rd, 2019

Prepared by:

A handwritten signature in black ink, appearing to read 'Ryan Hutsell', with a stylized flourish extending to the right.

Ryan Hutsell
Project Manager

TABLE OF CONTENTS

I. Introduction

II. Methods Executive Summary

A. Preliminary Steps

- i. Parent and Staff Notifications
- ii. Decluttering
- iii. Wall Hangings
- iv. Swing Space
- v. Facilities Building Cleaning Staff Training

B. Pre-Cleaning

C. Paint and Plaster Stabilization Procedures

- i. Work Practices
- ii. Oversight

D. Cleanup and Completion

- i. Cleanup
- ii. Testing

III. Oversight

- A. Scope of Work
- B. EPA Checklist
- C. Oversight
- D. Sample Results

Appendix A. Scope of Work Table

Appendix B. EPA Checklist Table

Appendix C. Oversight Table

Appendix D. Sample Results Table

Appendix E. Photographs

Appendix F. Environmental Firm Certifications

Appendix G. Paint Contractor Certifications

Appendix H. Documentation of Parent and Staff Notifications

Summary of Paint and Plaster Stabilization Activities
George Sharswood Elementary School
2300 South 2nd Street
Philadelphia, PA 19148
UCLS #: 2630

I. Introduction

This report outlines the paint and plaster stabilization work performed by *Delta, BJDS*, in various areas of the Sharswood School located at 2300 South 2nd Street, Philadelphia, Pennsylvania 19148 as specified in the April 2018 Memo “Paint and Plaster Stabilization Project Plan and Procedures,” provided by the School District of Philadelphia. *Synertech Incorporated* provided environmental oversight and documentation of work areas, and verified they were done correctly in accordance with the School District of Philadelphia’s prescribed work practices, as well as the EPA Renovation, Repair, and Painting Rule (RRP) EPA-740-R-09-002.

II. Methods Executive Summary

A. Preliminary Steps

i. Detailed Work Scope Determination

Synertech generated a school-specific scope determination report which detailed the location and quantity of paint and plaster to be stabilized. This report was made available to the school’s main office.

ii. Parent and Staff Notifications

A letter was sent home with students to announce the project, and a second letter was sent home to notify families that the project would commence within 10 days, giving a date for a kick-off meeting. A questions-and-answers sheet was provided in addition. The EPA Lead RRP pamphlet was sent home with students in grades Pre-K to 1 via backpack. The pamphlet was also made available to the Main Office, and an electronic version was provided to the School Advisory Council and/or Home and School. Documentation of the date that the EPA pamphlet was sent home with students and is attached in *Appendix H*.

An email to the principal was sent by the Operations Division two weeks in advance of the start of work to announce the commencement of the project. This email was to determine logistical issues such as the school calendar, work schedule, storage and/or swing space, etc.

Finally, all teachers were notified directly by the Operations Division through an email and a postcard was placed in each teacher’s mailbox 10 days in advance of the project start.

iii. Decluttering

Classrooms, closets, and other storage areas were decluttered prior to commencing stabilization work.

iv. Wall Hangings

Posters, bulletin boards, framed art, and other wall hangings were removed in order for the paint stabilization project to commence.

v. Swing Space

The identification of swing space was required to ensure that classrooms were available during the school year. A plan was created on a school-specific basis to relocate students and teachers from classrooms during the course of this work. All work areas were scheduled for cleaning by facilities staff after the paint stabilization work by Maintenance.

vi. Facilities Building Cleaning Staff Training

Cleaning staff was provided with information about this project and expectations for post-cleaning.

B. Pre-Cleaning

On an as-needed basis for areas such as cluttered storage closets that required extensive movement of materials as well as HEPA vacuuming and wet wiping prior to paint and plaster stabilization, the Maintenance Environmental staff performed a pre-cleaning. This process provided a clean work area prior to decluttering and stabilization.

C. Paint and Plaster Stabilization Procedures

i. Work Practices

Paint and plaster stabilization work complied with the EPA's Lead RRP Rule. All staff conducting this work was trained and/or certified as Lead RRP Workers. The following procedures were followed:

- Work areas were isolated to restrict dust from impacting adjacent areas.
- Signs/notifications were posted as per EPA Lead RRP.
- "Walk-off" pads were placed at all access points into/out of work area.
- All openings (windows, doors, HVAC system registers/grilles) inside work areas were sealed as per direction from on-site environmental monitors and consisted with the EPA Lead RRP Rules & Guidelines.
- Workers wore disposable clothing and foot coverings while inside work areas.
- All remaining objects in work areas were moved to the center and covered with plastic.
- Portable dust containment barrier systems were erected to limit the size of work areas requiring post-cleaning and limit testing and exposure.
- Plastic floor coverings were extended at least 6 feet out from vertical surfaces being stabilized unless utilizing vertical barriers/containment systems.
- All paint stabilization work was performed in compliance with the EPA Lead RRP Rules & Guidelines, and as per the directions of on-site environmental monitors to minimize dust contamination.

- The contractor took all steps necessary to ensure that no dust or debris left the work area while the work was being performed.
- The contractor took all precautions to ensure that all employees, tools, and other items, including the exteriors of waste containers, were free of dust and debris before leaving the work area.
- The contractor collected all paint chips and debris, folded up plastic floor coverings and any other plastic sheeting used on horizontal surfaces, without dispersing dust or debris and disposed of the material in heavy duty plastic waste bags.
- No power tools were used.
- No dry sweeping with brooms was allowed.
- Water and misting were used to minimize dust.
- HEPA vacuums and wet-wiping/cleaning techniques were employed

ii. Oversight

An environmental technician was on-site to oversee paint and plaster stabilization work to ensure compliance with lead safe work practices. An EPA RRP compliance checklist (*Appendix B*) and an oversight checklist (*Appendix C*) were completed at the end of every shift to record the work areas that were stabilized. The following tasks were verified and recorded:

- Pre-cleaning
- Contents moved
- Work area prepped
- Surfaces stabilized
- Contents put back in place
- Final inspection approval and photos

D. Cleanup & Completion

i. Cleanup

- Upon completion of stabilization, there were no signs of loose, peeling, flaking, bubbling, or crumbling paint or plaster visible on walls or ceilings or on any other painted surfaces.
- There were no visible signs of paint chips, debris or dust of any kind on surfaces with “contained” and isolated work areas NOR outside of the contained and isolated work areas.
- Window sills, floors, baseboards, shelving units, tops of cabinets, desks, chairs, tables, and all other horizontal surfaces were observed to be free of any visible signs of paint and plaster dust and/or debris.
- There were no visible signs of paint chips, and/or paint/plaster dust or debris on academic/educational materials, including books, bins, toys, desks, chairs, carpets, papers, etc., after each work shift and to allow for re-occupancy the next day.
- Any remaining paint and plaster were observed to be tightly adhered to wall and ceiling surfaces such that it could not be further damaged, pried off, or disturbed by “simple fingernail pressure.”
- Newly painted surfaces matched the aesthetics of the area in total and were to never cover the entirety of the wall or ceiling area that was addressed through this work. No visible “patches” of paint were observed.

ii. Testing

- Qualitative and quantitative testing was conducted to verify that stabilization work was performed in accordance with lead safe work practices, and that classrooms were safe for re-occupancy by children and staff.
- Qualitative testing methods, i.e. EPA RRP verification wipe testing and colorimetric wipe testing were compared with the quantitative testing method of Atomic Absorption Spectrophotometry (AAS) as indicated in the below testing protocol.

E. Testing Protocol

i. EPA RRP Verification Wipes and Colorimetric Wipes

Synertech, Incorporated, an environmental consulting firm, and the painter foreman coordinated the EPA RRP Verification Test Wipe in rooms/areas that had been stabilized and cleaned, and where plastic work area coverings were removed and visually inspected. After EPA RRP Verification Wipes passed the cleanliness standard for any surface and/or 40 square feet (SF) section, the colorimetric testing was conducted by the environmental technician on-site.

The colorimetric wipe tests were conducted in “child-occupied area” on approximately 10% of surfaces considered “clean” following the use of the verification wipes. These surfaces included floors, window sills, or the tops of any other immovable objects that were covered and cleaned in each work area. Additional colorimetric wipes were taken outside of work areas as determined by the environmental technician on-site.

“Child-occupied areas” were determined as classrooms, restrooms, cafeterias, gymnasiums, and auditoriums that are routinely used by children in PK-1st Grade children. Common areas that children in PK-1st Grade only pass through, such as hallways, stairways, and garages were not included.

ii. Response to Failed Tests

If colorimetric testing “fails,” then the 40 SF area will be re-wiped by EPA RRP Wipes. The process will continue until both testing methods confirm a “pass.”

iii. Flame Atomic Absorption Spectrophotometry (FAAS)

Flame Atomic Absorption Spectrophotometry (FAAS) was used to verify and confirm the results of the colorimetric testing. FAAS was used as a quality assurance/quality control measure for the colorimetric samples. Approximately 10% of the colorimetric samples taken in each work area were submitted for laboratory FAAS analysis. Results can be viewed in *Appendix D*.

iv. Release of Spaces Back to School/Operations

Once it was determined that EPA RRP wipes and colorimetric wipes were both acceptable as determined on-site by the environmental technician, and if work was completed in accordance with this procedure, the room was turned over to the District’s Operations team for “deep cleaning” and then for re-occupancy.

III. Oversight

A. Scope of Work

A comprehensive Paint and Plaster Scope of Work (*Appendix A*) was determined on February 13th, 2018. This working scope identified room-by-room locations and quantities of paint and plaster stabilization needed throughout the Sharswood School, and was made available to the school's main office.

B. EPA Checklist

The on-site environmental technician updated an on-going checklist provided by the EPA (*Appendix B*) in an effort to contain and minimize dust within a work area. In addition to work area cleanliness, the EPA checklist accounts for visual inspections of the work area as well as qualitative and quantitative testing records.

C. Oversight

Synertech Incorporated was dispatched to the Sharswood School at 7am on Monday June 10th, 2019 to provide renovation oversight. An on-site environmental technician was present through the entirety of the project to oversee paint and plaster stabilization work to ensure compliance with lead safe work practices. Each shift, an oversight report was updated, in which the following tasks were verified and recorded:

- Pre-cleaning
- Contents Moved
- Work Area Prepped
- Surfaces Stabilized
- Contents Back in Place
- Final Inspection Approval

D. Sample Results

Synertech, Incorporated used a combination of qualitative and quantitative testing techniques to ensure that each work area was safe to turn back over to the school for re-occupancy, as detailed in Section II. E. A total of 84 Colorimetric and 35 FAAS Wipes were used to determine safe environments in child-occupied areas before turning them back over to the school. Please refer to the Sample Results Table in *Appendix D* for details of areas tested and their corresponding results.

Thank you for allowing *Synertech Incorporated* to continue to provide The School District of Philadelphia with our professional environmental services. If you have any questions please do not hesitate to contact *Synertech Incorporated* at 215-755-2305.

Sincerely,

Synertech Incorporated
Ryan P. Hutsell
Ryan Hutsell
Project Manager

Appendix A

Scope of Work Table

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2630	1	3	329	Primary	Classroom 329	Ceiling	Flaking	16	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence
2	2630	1	3	329	Primary	Classroom 329	Floor	Chipping	5	N	Y	8	N	0	
3	2630	1	3	329	Primary	Classroom 329	W1	Flaking	36	N	N	0	Y - 192 SF Posters	N	3 Locations; Damage Including Door; Additional Cracking, Chipping
4	2630	1	3	329	Primary	Classroom 329	W2	Flaking	4	N	N	0	Y - 240 Whiteboard, Bulletin Boards, Posters	N	2 Locations
5	2630	1	3	329	Primary	Classroom 329	W3	Flaking	42	N	N	0	Y - 16 SF Posters	N	4 Locations
6	2630	1	3	329	Primary	Classroom 329	W4	Flaking	28	Y	N	0	Y - 50 SF Whiteboard, Posters	Y - 4 SF	3 Locations; Additional Efflorescence, Cracking
7	2630	1	3	330	Primary	Classroom 330	Floor	Chipping	3	N	N	0	None	N	Chipping Around Perimeter
8	2630	1	3	330	Primary	Classroom 330	W1	Flaking	38	N	N	0	Y - 42 SF Posters	N	3 Locations; Additional Cracking
9	2630	1	3	330	Primary	Classroom 330	W2	Cracking	2	N	N	0	Y - 168 SF Bookcases, Posters	N	
10	2630	1	3	330	Primary	Classroom 330	W3	Flaking	17	N	N	0	Y - 168 SF Desks, Contents	N	3 Locations; Additional Cracking
11	2630	1	3	330	Primary	Classroom 330	W4	Partially Inaccessible	0	N	N	0	Y - 192 SF Whiteboard, Posters, Contents	N	
12	2630	1	3	331	Primary	Classroom 331	Ceiling	Flaking	16	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence, Cracking
13	2630	1	3	331	Primary	Classroom 331	Floor	Chipping	10	N	N	0	N	N	Chipping Around Perimeter
14	2630	1	3	331	Primary	Classroom 331	W1	Flaking	18	N	N	0	Y - 30 SF Posters	N	9 Locations; Additional Cracking, Chipping
15	2630	1	3	331	Primary	Classroom 331	W2	Flaking	15	N	N	0	Y - 192 SF Whiteboard, Posters	N	4 Locations; Additional Cracking, Chipping; Chipping Around White Board Trim
16	2630	1	3	331	Primary	Classroom 331	W3	Flaking	14	Y	N	0	Y - 114 Bookcases, Desks, Posters	Y - 2 SF	3 Locations; Additional Efflorescence, Cracking; Substantial Damage Likely Behind Obstructions
17	2630	1	3	331	Primary	Classroom 331	W4	Chipping	3	N	N	0	Y - 84 SF Whiteboard, Posters	N	3 Locations
18	2630	1	3	332	Primary	Classroom 332	Ceiling	Flaking	20	Y	N	0	N	Y - 4 SF	Additional Efflorescence
19	2630	1	3	332	Primary	Classroom 332	Floor	Chipping	6	N	Y	6	N	N	Debris on Floor
20	2630	1	3	332	Primary	Classroom 332	W1	Flaking	24	N	N	0	N	N	5 Locations
21	2630	1	3	332	Primary	Classroom 332	W2	Flaking	26	N	N	0	Y - 96 SF Bulletin Board	Y - 1 SF	3 Locations; Additional Cracking; Flaking Includes Blackboard Trim
22	2630	1	3	332	Primary	Classroom 332	W3	Flaking	192	N	N	0	N	N	Whole Wall; Additional Cracking
23	2630	1	3	332	Primary	Classroom 332	W4	Cracking	14	N	N	0	Y - 128 SF Whiteboard	N	Flaking Includes White Board Trim; Additional Chipping
24	2630	1	3	333	Primary	Classroom 333	Ceiling	Flaking	4	N	N	0	N	N	3 Locations
25	2630	1	3	333	Primary	Classroom 333	W1	Cracking	5	N	N	0	Y - 120 SF Posters, Whiteboards, Desks	N	
26	2630	1	3	333	Primary	Classroom 333	W2	Flaking	3	N	N	0	Y - 64 SF Desks, Bookcases	N	2 Locations; Additional Cracking
27	2630	1	3	333	Primary	Classroom 333	W3	Flaking	20	N	N	0	Y - 90 SF Bookcases, Contents	N	5 Locations; Flaking on Window Sills 1-5
28	2630	1	3	333	Primary	Classroom 333	W4	Cracking	12	N	N	0	N	N	Additional Chipping
29	2630	1	3	334	Primary	Classroom 334	W1	Flaking	28	N	N	0	Y - 88 SF Whiteboard, Posters	N	3 Locations; Additional Cracking; Flaking on Wall & Black Board Trim
30	2630	1	3	334	Primary	Classroom 334	W2	Gouges	2	N	N	0	Y - 216 SF Bulletin Boards, Posters	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
31	2630	1	3	334	Primary	Classroom 334	W3	Cracking	10	N	N	0	N	N	4 Locations; Additional Cracking; Damage on Window Sills & Frames
32	2630	1	3	334	Primary	Classroom 334	W4	Flaking	13	N	N	0	Y - 132 SF Whiteboard, Bulletin Boards, Desks	N	2 Locations
33	2630	1	3	335	Primary	Classroom 335	Floor	Chipping	3	N	N	0	N	N	
34	2630	1	3	335	Primary	Classroom 335	W1	Flaking	10	N	N	0	Y - 100 SF Whiteboard, Posters	N	2 Locations; Flaking on Door & White Board Trim; Additional Cracking
35	2630	1	3	335	Primary	Classroom 335	W2	Partially Inaccessible	0	N	N	0	Y - 216 SF Bulletin Boards, Posters	N	
36	2630	1	3	335	Primary	Classroom 335	W3	Flaking	5	N	Y	2	Y - 196 SF Contents	N	3 Locations; Debris on Window Sill 5; Additional Chipping
37	2630	1	3	335	Primary	Classroom 335	W4	Flaking	32	N	N	0	Y - 240 SF Whiteboard, Posters	N	2 Locations; Additional Cracking
38	2630	1	3	336	Primary	Classroom 336	Floor	Chipping	4	N	N	0	N	N	
39	2630	1	3	336	Primary	Classroom 336	W1	Flaking	25	N	N	0	Y - 144 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking, Chipping
40	2630	1	3	336	Primary	Classroom 336	W2	Flaking	10	N	N	0	Y - 84 SF Bulletin Boards, Posters	N	2 Locations; Additional Cracking
41	2630	1	3	336	Primary	Classroom 336	W3	Flaking	18	Y	N	0	Y - 30 SF Bookcases, Posters	Y - 4 SF	4 Locations; Additional Efflorescence, Cracking; Plaster @ Window 2
42	2630	1	3	336	Primary	Classroom 336	W4	Cracking	12	N	N	0	Y - 240 SF Whiteboards, Contents	N	
43	2630	1	3	337	Primary	Classroom 337	Ceiling	Efflorescence	8	Y	N	0	Y - 36 SF Ductwork	Y - 4 SF	
44	2630	1	3	337	Primary	Classroom 337	Floor	Chipping	6	N	N	0	N	N	
45	2630	1	3	337	Primary	Classroom 337	W1	Cracking	10	N	N	0	Y - 64 SF White Boards, Bulletin Boards	N	3 Locations; Additional Chipping
46	2630	1	3	337	Primary	Classroom 337	W2	Efflorescence	18	Y	N	0	Y - 136 SF Cabinets	Y - 6 SF	3 Locations; Additional Cracking
47	2630	1	3	337	Primary	Classroom 337	W3	Flaking	14	N	N	0	Y - 16 SF Desks, Posters	N	7 Locations; Additional Cracking, Chipping; Windows & Radiator
48	2630	1	3	337	Primary	Classroom 337	W4	Flaking	13	N	N	0	Y - 126 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
49	2630	1	3	338	Primary	Classroom 338	Floor	Chipping	5	N	N	0	N	N	Around Perimeter
50	2630	1	3	338	Primary	Classroom 338	W1	Flaking	14	N	N	0	Y - 32 SF Bookcases, Posters	N	4 Locations; Additional Cracking, Chipping
51	2630	1	3	338	Primary	Classroom 338	W2	Cracking	22	N	N	0	Y - 210 SF Bulletin Boards	N	2 Locations
52	2630	1	3	338	Primary	Classroom 338	W3	Flaking	24	N	N	0	Y - 40 SF Bookcases	N	4 Locations
53	2630	1	3	338	Primary	Classroom 338	W4	Flaking	105	N	N	0	Y - 228 SF Bulletin Boards, White Board	N	4 Locations; Additional Cracking, Chipping, Holes
54	2630	1	3	339	Primary	Classroom 339	W1	Cracking	28	N	N	0	Y - 36 SF Posters	N	2 Locations
55	2630	1	3	339	Primary	Classroom 339	W2	Chipping	3	N	N	0	Y - 50 SF Posters	N	3 Locations
56	2630	1	3	339	Primary	Classroom 339	W3	Flaking	8	N	N	0	N	N	
57	2630	1	3	339	Primary	Classroom 339	W4	Cracking	2	N	N	0	Y - 160 SF Posters	N	
58	2630	1	3	340	Primary	Classroom 340	W1	Flaking	8	N	N	0	Y - 20 SF Posters	N	3 Locations; Additional Cracking, Chipping; Including Door Frame
59	2630	1	3	340	Primary	Classroom 340	W2	Chipping	6	N	N	0	Y - 12 SF Bulletin Boards	N	3 Locations
60	2630	1	3	340	Primary	Classroom 340	W3	Cracking	8	N	N	0	N	N	2 Locations
61	2630	1	3	340	Primary	Classroom 340	W4	Partially Inaccessible	0	N	N	0	Y - 200 SF Whiteboards	N	
62	2630	1	3	341	Primary	Classroom 341	W1	Flaking	16	N	N	0	N	N	5 Locations; Additional Cracking, Chipping, Holes

Sharswood - Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
63	2630	1	3	341	Primary	Classroom 341	W2	Flaking	10	N	N	0	Y - 144 SF Whiteboard, Posters	N	Flaking around Whiteboard; Additional Cracking
64	2630	1	3	341	Primary	Classroom 341	W3	Flaking	26	N	Y	8	N	N	4 Locations; Flaking Around Window Frames; Debris on Window Sills; Additional Cracking
65	2630	1	3	341	Primary	Classroom 341	W4	Flaking	3	N	N	0	N	N	Additional Cracking
66	2630	1	3	342	Primary	Classroom 342-A	Ceiling	Flaking	6	N	N	0	N	N	3 Locations; Additional Chipping
67	2630	1	3	342	Primary	Classroom 342-A	Floor	Chipping	5	N	N	0	N	N	
68	2630	1	3	342	Primary	Classroom 342-A	W1	Flaking	36	N	N	0	Y - 72 SF Whiteboards, Posters	N	4 Locations; Flaking on Door & Wall; Additional Cracking, Chipping
69	2630	1	3	342	Primary	Classroom 342-A	W2	Cracking	64	N	N	0	Y - 40 SF Posters	N	
70	2630	1	3	342	Primary	Classroom 342-A	W3	Flaking	2	N	N	0	Y - 8 SF Posters	N	2 Locations; Additional Cracking
71	2630	1	3	342	Primary	Classroom 342-A	W4	Flaking	2	N	N	0	Y - 40 SF Shelves	N	2 Locations; Additional Chipping
72	2630	1	3	329A	Storage	Storage Room next to Classroom 329	Ceiling	Cracking	2	N	N	0	N	N	
73	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W1	Flaking	1	N	N	0	N	Y - 1 SF	
74	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W2	Flaking	2	N	N	0	N	N	Flaking on Pipe
75	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W3	Flaking	14	N	N	0	N	Y - 2 SF	2 Locations
76	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W4	Flaking	6	N	N	0	N	N	Additional Cracking
77	2630	1	3	333A	Storage	Classroom 333 Coat Closet	Ceiling	Flaking	6	N	N	0	N	N	
78	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W1	Cracking	4	N	N	0	N	N	
79	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W2	Flaking	6	N	N	0	N	N	2 Locations; Additional Cracking
80	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W3	Flaking	16	N	N	0	N	Y - 1 SF	3 Locations; Additional Cracking
81	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W4	Cracking	9	N	N	0	N	N	
82	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W1	Flaking	1	N	N	0	Y - 80 SF Contents	N	
83	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W3	Flaking	16	N	N	0	N	N	4 Locations; Additional Cracking
84	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W4	Cracking	2	N	N	0	N	N	
85	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W1	Flaking	36	N	N	0	Y - 60 SF Contents	N	Additional Cracking
86	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W2	Flaking	3	N	N	0	N	N	
87	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W3	Flaking	4	N	N	0	N	Y - 1 SF	2 Locations; Additional Chipping
88	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Ceiling	Cracking	4	N	N	0	N	N	
89	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Floor	Chipping	2	N	N	0	N	N	
90	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W1	Flaking	24	N	N	0	Y - 72 SF Contents	N	3 Locations; Additional Cracking
91	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W3	Flaking	96	N	N	0	N	N	Additional Cracking

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
92	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W4	Cracking	4	N	N	0	N	N	Additional Chipping on Doors
93	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W2	Cracking	61	N	N	0	N	N	
94	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W3	Flaking	8	N	N	0	N	N	Flaking @ Radiator
95	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking	1	N	N	0	N	N	
96	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	3	N	N	0	N	N	
97	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	Ceiling	Flaking	45	N	N	0	N	N	Whole Ceiling; Additional Cracking
98	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W1	Flaking	12	N	N	0	Y - 72 SF Contents	N	Additional Cracking
99	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
100	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W3	Flaking	40	N	N	0	N	N	
101	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W4	Flaking	8	N	N	0	Y - 20 SF Contents	N	Additional Cracking
102	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	Ceiling	Cracking	3	N	N	0	N	N	2 Locations
103	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W1	Cracking	12	N	N	0	Y - 12 SF File Cabinets	N	
104	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W2	Flaking	12	N	N	0	12 SF Whiteboard	N	2 Locations; Whiteboard Trim & Wall
105	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W3	Flaking	30	N	N	0	N	N	2 Locations; Behind Radiator
106	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	Floor	Chipping	14	N	N	0	N	N	
107	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W2	Flaking	6	N	N	0	Y - 42 SF Papers	N	10 Locations; Additional Cracking, Chipping
108	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W3	Flaking	35	N	Y	3	N	N	Debris on Window Sills 1-4; Additional Cracking
109	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W1	Cracking	8	N	N	0	N	N	2 Locations
110	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W2	Cracking	2	N	N	0	N	N	
111	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	Floor	Chipping	3	N	N	0	N	N	3 Locations
112	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W1	Flaking	24	N	N	0	Y - 64 SF Bulletin Board	N	4 Locations; Additional Cracking, Chipping
113	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W3	Flaking	46	N	N	0	N	N	7 Locations; Additional Cracking; Flaking on Doors
114	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Ceiling	Flaking	12	N	N	N	N	Y- 12 SF	2 Locations; Additional Holes
115	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Floor	Chipping	1	N	N	N	N	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
116	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W2	Flaking	58	N	N	N	Y - 50 SF Posters	N	8 Locations; Additional Cracking
117	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W3	Cracking	5	N	N	N	N	N	2 Locations
118	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W4	Flaking	17	N	N	N	Y - 35 SF Posters	N	5 Locations
119	2630	1	3	S31	Stairs	Fire Tower across from Classroom 341	Ceiling	Flaking	2	N	N	0	N	N	
120	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	Ceiling	Flaking	30	N	N	0	N	N	3 Locations; Additional Cracking; Including Roof Access Landing
121	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W1	Flaking	120	N	N	0	N	N	Including Roof Access Landing
122	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W2	Flaking	18	N	N	0	N	N	Flaking on Wall & Pipe; 3 Locations; Additional Cracking; Including Roof Access Landing
123	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W3	Flaking	120	Y	N	0	N	Y - 30 SF	Additional Efflorescence, Spalling; Including Roof Access Landing
124	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W4	Flaking	96	Y	N	0	N	Y - 60 SF	4 Locations; Additional Efflorescence, Spalling, Cracking; Including Roof Access Landing
125	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
126	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
127	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
128	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
129	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
130	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
131	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
132	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
133	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
134	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
135	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
136	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
137	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	Ceiling	Flaking	28	Y	N	0	Y - 12 SF	N	3 Locations; Including Roof Access Landing
138	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W1	Flaking	32	Y	N	0	Y - 10 SF	N	3 Locations; Flaking on Walls and Behind Radiator; Additional Cracking; Including Roof Access Landing
139	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W2	Flaking	50	Y	N	0	Y - 20 SF	N	3 Locations; Including Roof Access Landing
140	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W3	Flaking	46	Y	N	0	Y - 12 SF	N	3 Locations; Including Roof Access Landing
141	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W4	Flaking	200	Y	N	0	Y - 18 SF	N	3 Locations; Including Roof Access Landing

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
142	2630	1	3	S37	Stairs	Fire Tower across from Classroom 329	Ceiling	Flaking	36	Y	N	0	N	Y - 12 SF	Additional Efflorescence
143	2630	1	2	216	IMC (Library)	IMC/Library	Floor	Chipping	18	N	N	0	N	N	Chipping Around Perimeter
144	2630	1	2	216	IMC (Library)	IMC/Library	W1	Flaking	6	N	N	0	Y - 72 SF Bookcases, Posters	Y - 2 SF	4 Locations; Additional Cracking, Chipping
145	2630	1	2	216	IMC (Library)	IMC/Library	W2	Holes	3	N	N	0	N	N	3 Locations
146	2630	1	2	216	IMC (Library)	IMC/Library	W3	Flaking	7	N	N	0	Y - 86 SF Contents	N	3 Locations; Additional Chipping
147	2630	1	2	216	IMC (Library)	IMC/Library	W4	Chipping	2	N	N	0	Y - 96 SF Desks	N	2 Locations
148	2630	1	2	217	Primary	Classroom 217	Floor	Chipping	6	N	N	0	N	N	Chipping Around Perimeter
149	2630	1	2	217	Primary	Classroom 217	W1	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	Including Door & Wall
150	2630	1	2	217	Primary	Classroom 217	W3	Flaking	4	N	N	0	Y - 32 SF Posters	N	2 Locations; Additional Holes; Damage Includes Radiator
151	2630	1	2	217	Primary	Classroom 217	W4	Partially Inaccessible	0	N	N	0	Y - 140 SF Posters, Bulletin Boards	N	
152	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W1	Cracking	8	N	N	0	Y - 18 SF Contents	N	2 Locations; Additional Cracking
153	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W2	Flaking	5	N	N	0	Y - 24 SF Shelves	N	
154	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W3	Cracking	12	N	N	0	Y - 20 SF Cabinets	N	
155	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W4	Partially Inaccessible	0	N	N	0	Y - 6 SF Contents	N	
156	2630	1	2	219	Primary	Classroom 219	Ceiling	Flaking	24	N	N	0	N	N	Additional Cracking
157	2630	1	2	219	Primary	Classroom 219	Floor	Chipping	9	N	N	0	N	N	
158	2630	1	2	219	Primary	Classroom 219	W1	Flaking	1	N	N	0	N	N	
159	2630	1	2	219	Primary	Classroom 219	W2	Cracking	2	N	N	0	Y - 90 SF Bookcases	N	
160	2630	1	2	219	Primary	Classroom 219	W3	Flaking	12	N	N	0	Y - 16 SF Posters	N	3 Locations; Additional Cracking; Including Pipe, Wall, Radiator
161	2630	1	2	219	Primary	Classroom 219	W4	Holes	4	N	N	0	N	N	
162	2630	1	2	220	Auditorium	Auditorium	Ceiling	Cracking	4	N	N	0	N	N	
163	2630	1	2	220	Auditorium	Auditorium	Floor	Chipping	30	N	N	0	N	N	
164	2630	1	2	220	Auditorium	Auditorium	W1	Flaking	18	N	N	0	Y - 72 SF Bulletin Boards	Y - 1 SF	6 Locations; Additional Cracking, Chipping
165	2630	1	2	220	Auditorium	Auditorium	W3	Flaking	74	N	N	0	Y - 96 SF Contents, Posters	N	10 Locations; Additional Cracking, Chipping
166	2630	1	2	220	Auditorium	Auditorium	W4	Flaking	18	N	N	0	Y - 240 SF Bulletin Board	N	
167	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W3	Flaking	12	N	N	0	N	Y - 1 SF	2 Locations; Additional Cracking; Flaking @ Radiator
168	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF File Cabinets, Bookcases	N	
169	2630	1	2	223	Primary	Classroom 223	Floor	Chipping	33	N	N	0	N	N	Chipping Around Perimeter
170	2630	1	2	223	Primary	Classroom 223	W1	Flaking	8	N	N	0	Y - 42 SF Posters	N	3 Locations; Additional Chipping
171	2630	1	2	223	Primary	Classroom 223	W2	Partially Inaccessible	0	N	N	0	Y - 168 SF Bulletin Boards, Posters	N	
172	2630	1	2	223	Primary	Classroom 223	W3	Flaking	10	N	N	0	Y - 16 SF Posters	N	7 Locations; Additional Cracking
173	2630	1	2	223	Primary	Classroom 223	W4	Flaking	4	N	N	0	Y - 144 SF Whiteboard, Posters	N	2 Locations
174	2630	1	2	224	Primary	Classroom 224	Ceiling	Flaking	40	N	N	0	N	N	2 Locations
175	2630	1	2	224	Primary	Classroom 224	Floor	Chipping	4	N	N	0	N	N	
176	2630	1	2	224	Primary	Classroom 224	W1	Cracking	8	N	N	0	N	N	
177	2630	1	2	224	Primary	Classroom 224	W2	Partially Inaccessible	0	N	Y	25	Y - 48 SF Desks, Posters	N	
178	2630	1	2	224	Primary	Classroom 224	W3	Flaking	16	N	N	0	Y - 35 SF Desks Tables	N	2 Locations; Flaking @ Radiators

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
179	2630	1	2	224	Primary	Classroom 224	W4	Flaking	1	N	Y	1	Y - 18 SF File Cabinets, Desks	Y - 1 SF	
180	2630	1	2	225	Primary	Classroom 225	Ceiling	Cracking	2	N	N	0	N	N	2 Locations; Additional Cracking
181	2630	1	2	225	Primary	Classroom 225	Floor	Chipping	7	N	N	0	N	N	Chipping Around Perimeter
182	2630	1	2	225	Primary	Classroom 225	W1	Flaking	86	N	N	0	Y - 52 SF Contents, Posters	N	3 Locations; Additional Chipping
183	2630	1	2	225	Primary	Classroom 225	W2	Partially Inaccessible	0	N	N	0	Y - 147 SF Bulletin Boards, Posters	N	
184	2630	1	2	225	Primary	Classroom 225	W3	Flaking	22	N	N	0	Y - 54 SF Desks, Bookcases	N	3 Locations; Additional Cracking
185	2630	1	2	225	Primary	Classroom 225	W4	Flaking	12	N	N	0	Y - 48 SF Desks, Posters	N	Additional Cracking
186	2630	1	2	226	Primary	Classroom 226	W1	Flaking	24	Y	N	0	Y - 130 SF Posters, Bookcases, Desks	Y - 24 SF	Additional Efflorescence
187	2630	1	2	226	Primary	Classroom 226	W2	Flaking	8	N	N	0	Y - 52 SF Bookcases, Posters	N	2 Locations; Additional Cracking
188	2630	1	2	226	Primary	Classroom 226	W3	Flaking	26	N	N	0	Y - 100 SF Desks, File Cabinets, Posters	N	3 Locations; Additional Cracking; Flaking Including Radiator
189	2630	1	2	226	Primary	Classroom 226	W4	Partially Inaccessible	0	N	N	0	Y - 45 SF Desks, Posters	N	
190	2630	1	2	227	Primary	Classroom 227	Ceiling	Flaking	10	N	N	0	N	N	2 Locations
191	2630	1	2	227	Primary	Classroom 227	Floor	Chipping	4	N	N	0	N	N	
192	2630	1	2	227	Primary	Classroom 227	W1	Flaking	6	N	N	0	Y - 192 SF Contents, Bookcases	N	3 Locations; Additional Chipping
193	2630	1	2	227	Primary	Classroom 227	W2	Flaking	6	N	N	0	N	N	2 Locations
194	2630	1	2	227	Primary	Classroom 227	W3	Flaking	4	N	N	0	Y - 48 SF Desks, Posters, Contents	Y - 4 SF	
195	2630	1	2	227	Primary	Classroom 227	W4	Cracking	48	N	N	0	Y - 80 SF Whiteboard, Bulletin Boards, Posters	N	
196	2630	1	2	228	Primary	Classroom 228	Ceiling	Flaking	4	N	N	0	N	N	2 Locations
197	2630	1	2	228	Primary	Classroom 228	Floor	Chipping	6	N	Y	3	N	N	
198	2630	1	2	228	Primary	Classroom 228	W1	Flaking	3	N	N	0	Y - 132 SF Posters, File Cabinets	N	2 Locations
199	2630	1	2	228	Primary	Classroom 228	W2	Cracking	14	N	N	0	Y - 30 SF Bookcases	N	
200	2630	1	2	228	Primary	Classroom 228	W3	Flaking	28	N	Y	4	N	N	5 Locations; Flaking on Entire Wall; Debris on Window Sills 4 & 5
201	2630	1	2	228	Primary	Classroom 228	W4	Partially Inaccessible	0	N	N	0	Y - 50 SF File Cabinets, Bulletin Boards, White Board	N	
202	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W1	Partially Inaccessible	0	N	N	0	Y - 12 SF Contents	N	
203	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W2	Partially Inaccessible	0	N	N	0	Y - 100 SF Bookcases	N	
204	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
205	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Bookcase	N	
206	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
207	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
208	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
209	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
210	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
211	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
212	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W3	Flaking	8	N	N	0	N	N	Additional Cracking
213	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W4	Flaking	6	N	N	0	N	N	
214	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W1	Flaking	15	N	N	0	Y - 18 SF Contents	N	2 Locations; Additional Cracking
215	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves	N	
216	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W3	Cracking	12	N	N	0	Y - 20 SF Cabinets	N	
217	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W4	Cracking	6	N	N	0	Y - 6 SF Contents	N	
218	2630	1	2	220A	Auditorium	Auditorium Stage	W3	Flaking	192	N	N	0	Y - 192 SF Posters	N	Whole Wall; Flaking Behind Posters
219	2630	1	2	220A	Auditorium	Auditorium Stage	W4	Flaking	2	N	N	0	N	N	
220	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
221	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
222	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
223	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
224	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
225	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
226	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
227	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
228	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
229	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
230	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
231	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
232	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
233	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
234	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
235	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
236	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
237	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
238	2630	1	2	223A	Storage	Classroom 223 Coat Closet	Ceiling	Holes	2	N	N	0	None	Y - 2 SF	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
239	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W1	Flaking	10	N	N	0	Y - 42 SF Bookcases	N	2 Locations; Additional Cracking, Holes
240	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W2	Flaking	4	N	N	0	Y - 24 SF Contents	N	
241	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W3	Flaking	6	N	N	0	Y - 30 SF Contents	Y - 4 SF	2 Locations; Additional Cracking, Holes
242	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W4	Flaking	3	N	N	0	Y - 24 SF Contents, Boxes	N	2 Locations
243	2630	1	2	224B	Student Restrooms - Male/Female (Classroom)	Classroom 224 Restroom	W2	Flaking	16	N	N	0	N	N	Additional Cracking
244	2630	1	2	226B	Student Restrooms - Male/Female (Classroom)	Classroom 226 Restroom	W3	Flaking	5	N	N	0	N	N	3 Locations; Additional Cracking
245	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W2	Chipping	1	N	N	0	N	N	
246	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W3	Chipping	3	N	N	0	N	N	3 Locations
247	2630	1	2	228A	Storage	Classroom 228 Storage Closet	Ceiling	Flaking	75	N	N	0	N	N	
248	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W1	Flaking	42	N	N	0	N	N	Damage on Entire Wall
249	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W2	Cracking	12	N	N	0	Y - 30 SF Bookcases	N	
250	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W3	Flaking	120	N	N	0	N	N	Damage on Entire Wall
251	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W4	Flaking	50	N	N	0	Y - 12 SF Ductwork	N	
252	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	Floor	Chipping	376	N	N	0	N	N	Hallway Perimeter
253	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W2	Flaking	170	N	N	0	Y - 36 SF Bookcase	N	13 Locations; Additional Cracking
254	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W3	Cracking	6	N	N	0	N	N	
255	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W4	Flaking	117	N	N	0	Y - 54 SF Bookcase	N	4 Locations; Additional Chipping
256	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	Floor	Chipping	2	N	N	0	N	N	
257	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Posters	N	
258	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Bulletin Board, Posters	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
259	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W1	Cracking	65	N	N	0	Y - 36 SF Posters	N	
260	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Ceiling	Flaking	8	N	N	0	N		
261	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Floor	Chipping	3	N	N	0	N		2 Locations
262	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W1	Flaking	38	N	N	0	Y - 88 SF Bulletin Boards, Posters	N	8 Locations; Walls, Windows Frames, Doors; Additional Cracking
263	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W2	Cracking	4	N	N	0	N		
264	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W3	Cracking	188	N	N	0	Y - 72 SF Bulletin Boards, Posters		8 Locations
265	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	Floor	Flaking	2	N	N	0	N	N	2 Locations; Additional Cracking
266	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W2	Flaking	82	N	N	0	Y - 90 SF Bulletin Boards, Posters	N	7 Locations; Walls & Window Frames, Additional Cracking
267	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W3	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
268	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W4	Flaking	34	N	N	0	Y - 110 SF Bulletin Boards, Posters	N	7 Locations; Walls & Window Frames; Additional Cracking
269	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W1	Holes	2	N	N	0	N	N	
270	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W2	Cracking	4	N	N	0	N	N	
271	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W3	Cracking	4	N	N	0	N	N	
272	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
273	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
274	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
275	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
276	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
277	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
278	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
279	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
280	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
281	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
282	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
283	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
284	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	Ceiling	Cracking	3	N	N	0	N	N	
285	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W1	Flaking	2	N	N	0	N	N	
286	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W2	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking
287	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Posters	N	
288	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W4	Flaking	6	N	N	0	N	N	2 Locations
289	2630	1	2	S27	Stairs	Fire Tower Stairwell across from IMC/Library	Ceiling	Flaking	8	N	N	0	N	N	3 Locations
290	2630	1	1	101	Primary	Classroom 101	Floor	Chipping	4	N	N	0	N	N	Chipping Around Perimeter
291	2630	1	1	101	Primary	Classroom 101	W1	Flaking	90	N	N	0	Y - 144 SF Contents, Posters	N	5 Locations; Additional Cracking, Chipping
292	2630	1	1	101	Primary	Classroom 101	W2	Flaking	2	N	N	0	N	N	2 Locations
293	2630	1	1	101	Primary	Classroom 101	W3	Chipping	1	N	N	0	Y - 60 SF Bookcases, Contents	N	
294	2630	1	1	101	Primary	Classroom 101	W4	Flaking	8	N	N	0	Y - 56 SF File Cabinets, Whiteboard, Desks	N	3 Locations; Additional Cracking
295	2630	1	1	102	Primary	Classroom 102	Floor	Chipping	11	N	N	0	N	N	Chipping Around Perimeter
296	2630	1	1	102	Primary	Classroom 102	W1	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	Additional Cracking
297	2630	1	1	102	Primary	Classroom 102	W2	Flaking	6	N	N	0	Y - 84 SF Bookcases, Posters	N	3 Locations; Additional Cracking
298	2630	1	1	102	Primary	Classroom 102	W3	Flaking	6	N	N	0	Y - 64 Bookcases, Desks	N	3 Locations; Including Radiator
299	2630	1	1	102	Primary	Classroom 102	W4	Chipping	4	N	N	0	Y - 60 SF Posters	N	
300	2630	1	1	103	Primary	Classroom 103	Floor	Chipping	7	N	N	0	N	N	4 Locations
301	2630	1	1	103	Primary	Classroom 103	W2	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	3 Locations; Including Chalkboard Trim; Additional Chipping
302	2630	1	1	103	Primary	Classroom 103	W3	Flaking	40	N	N	0	Y - 72 SF Desks, Posters	N	4 Locations; Additional Cracking
303	2630	1	1	103	Primary	Classroom 103	W4	Flaking	30	N	N	0	Y - 160 SF Whiteboard, Posters	N	2 Locations; Additional Cracking
304	2630	1	1	104	Administrative Office	Nurse's Office	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking; Including Pipe Paint
305	2630	1	1	104	Administrative Office	Nurse's Office	W1	Flaking	74	N	N	0	N	N	Additional Cracking
306	2630	1	1	104	Administrative Office	Nurse's Office	W2	Flaking	8	N	N	0	Y - 45 SF Chairs	N	2 Locations; Additional Cracking & Gouges
307	2630	1	1	104	Administrative Office	Nurse's Office	W3	Flaking	18	N	N	0	Y - 96 SF Desks, Contents	N	Additional Cracking

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
308	2630	1	1	104	Administrative Office	Nurse's Office	W4	Partially Inaccessible	0	N	N	0	Y - 144 SF Bulletin Boards, File Cabinets, Posters	N	
309	2630	1	1	105	Primary	Classroom 105	Floor	Chipping	5	N	N	0	N	N	
310	2630	1	1	105	Primary	Classroom 105	W1	Partially Inaccessible	0	N	N	0	Y - 240 SF Posters	N	
311	2630	1	1	105	Primary	Classroom 105	W2	Cracking	2	N	N	0	N	N	
312	2630	1	1	105	Primary	Classroom 105	W3	Flaking	15	N	N	0	Y - 168 SF Posters	N	4 Locations; Including Pipe & Radiator
313	2630	1	1	105	Primary	Classroom 105	W4	Chipping	2	N	N	0	Y - 120 SF Bookcases	N	
314	2630	1	1	106	Primary	Classroom 106	Ceiling	Flaking	8	N	N	0	N	N	
315	2630	1	1	106	Primary	Classroom 106	Floor	Chipping	6	N	N	0	N	N	Chipping Around Perimeter
316	2630	1	1	106	Primary	Classroom 106	W1	Flaking	5	N	N	0	Y - 160 SF Posters, Contents	N	2 Locations
317	2630	1	1	106	Primary	Classroom 106	W2	Cracking	20	N	N	0	Y - 120 SF Posters	N	
318	2630	1	1	106	Primary	Classroom 106	W3	Flaking	4	N	N	0	Y - 144 SF Posters, Contents	N	
319	2630	1	1	106	Primary	Classroom 106	W4	Chipping	2	N	N	0	Y - 72 SF Desks, Bookcases	N	
320	2630	1	1	107	Primary	Classroom 107	W1	Flaking	1	N	N	0	Y - 147 Bookcases, Posters	N	
321	2630	1	1	107	Primary	Classroom 107	W2	Flaking	16	N	N	0	Y - 144 Bookcases, Posters	N	Additional Cracking
322	2630	1	1	107	Primary	Classroom 107	W3	Flaking	20	N	N	0	Y - 84 SF Bookcases, Desks	N	4 Locations; Additional Cracking
323	2630	1	1	107	Primary	Classroom 107	W4	Cracking	28	N	N	0	Y - 150 SF Bookcases, Posters	N	Additional Chipping
324	2630	1	1	108	Primary	Classroom 108	Floor	Chipping	10	N	N	0	N	N	3 Locations
325	2630	1	1	108	Primary	Classroom 108	W1	Flaking	16	N	N	0	Y - 126 SF Bookcases, Posters	N	2 Locations; Additional Cracking
326	2630	1	1	108	Primary	Classroom 108	W2	Flaking	2	N	N	0	Y - 140 SF Bulletin Boards, Posters, Bookcases	N	
327	2630	1	1	108	Primary	Classroom 108	W3	Flaking	9	N	N	0	Y - 24 SF Desks, Bookcases	N	3 Locations; Additional Cracking, Chipping
328	2630	1	1	108	Primary	Classroom 108	W4	Flaking	96	N	N	0	Y - 144 SF Desks, Tables, Contents	N	Additional Cracking
329	2630	1	1	109	Primary	Room 109 Head Start Program	Ceiling	Flaking	75	N	N	0	N	N	5 Locations; Additional Cracking
330	2630	1	1	109	Primary	Room 109 Head Start Program	Floor	Chipping	20	N	N	0	N	N	4 Locations; Additional Cracking
331	2630	1	1	109	Primary	Room 109 Head Start Program	W1	Cracking	6	N	N	0	Y - 160 SF Bulletin Boards, Posters	N	
332	2630	1	1	109	Primary	Room 109 Head Start Program	W2	Partially Inaccessible	0	N	N	0	Y - 140 SF Contents	N	
333	2630	1	1	109	Primary	Room 109 Head Start Program	W3	Flaking	24	N	N	0	Y - 72 SF Contents	N	6 Locations
334	2630	1	1	109	Primary	Room 109 Head Start Program	W4	Flaking	4	N	N	0	Y - 76 SF Posters, Bookcases, Contents	N	2 Locations
335	2630	1	1	110	Administrative Office	Principal's Office	W1	Partially Inaccessible	0	N	N	0	Y - 70 SF Bulletin Boards, Desks	N	2 Locations; Additional Cracking
336	2630	1	1	110	Administrative Office	Principal's Office	W2	Flaking	5	N	N	0	Y - 30 SF Shelves	N	2 Locations
337	2630	1	1	110	Administrative Office	Principal's Office	W3	Flaking	5	N	N	0	N	N	
338	2630	1	1	110	Administrative Office	Principal's Office	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Desks, Bookcases, Contents	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
339	2630	1	1	111	Administrative Office	Main Office	W1	Cracking	12	N	N	0	Y - 26 SF Posters, Desks	N	4 Locations; Additional Chipping
340	2630	1	1	111	Administrative Office	Main Office	W2	Cracking	4	N	N	0	Y - 168 SF Bulletin Boards, Posters, Desks	N	4 Locations
341	2630	1	1	111	Administrative Office	Main Office	W3	Flaking	32	N	N	0	Y - 48 SF Tables, Chairs	N	2 Locations; Additional Cracking; Including Radiator
342	2630	1	1	111	Administrative Office	Main Office	W4	Flaking	20	N	N	0	Y - 60 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
343	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Flaking	110	N	N	0	N	N	Including Pipe Paint; Additional Cracking, Holes
344	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Floor	Chipping	400	N	N	0	N	N	Chipping Around Perimeter
345	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W1	Flaking	230	N	N	0	N	N	Entire Wall; Additional Cracking
346	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W2	Flaking	96	N	N	0	N	N	Entire Wall; Additional Cracking
347	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W3	Flaking	120	N	N	0	N	N	Entire Wall; Additional Cracking, Chipping
348	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking	106	N	N	0	N	N	Entire Wall; Additional Cracking
349	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
350	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
351	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
352	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
353	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
354	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
355	2630	1	1	114	Primary	Room 114 Head Start Program	W1	Flaking	24	N	N	0	Y - 192 SF Cabinet, Bulletin Boards	N	2 Locations; Additional Cracking
356	2630	1	1	114	Primary	Room 114 Head Start Program	W2	Partially Inaccessible	0	N	N	0	Y - 168 SF Bulletin Boards, Posters	N	
357	2630	1	1	114	Primary	Room 114 Head Start Program	W3	Flaking	20	N	N	0	Y - 36 SF Desks, Bookcases	Y - 2	4 Locations; Additional Cracking; Plaster @ Window 3
358	2630	1	1	114	Primary	Room 114 Head Start Program	W4	Flaking	3	N	N	0	Y - 140 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
359	2630	1	1	101A	Storage	Storage Room next to Classroom 101	Ceiling	Flaking	12	N	N	0	N	N	
360	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W1	Partially Inaccessible	0	N	N	0	Y - 160 SF Shelves	N	Flaking @ Radiator

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
361	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W3	Flaking	2	N	N	0	Y - 160 SF Shelves	N	
362	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	Ceiling	Efflorescence	3	Y	N	0	N	Y - 5 SF	
363	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W1	Flaking	8	N	N	0	Y - 32 SF Desks, Fridge	N	3 Locations; Additional Cracking
364	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W2	Flaking	4	N	N	0	Y - 72 SF Tables, Contents	N	2 Locations; Additional Cracking
365	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W3	Flaking	13	N	N	0	N	N	2 Locations; Additional Cracking
366	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W4	Efflorescence	8	Y	N	0	N	Y - 5 SF	3 Locations; Additional Cracking, Chipping
367	2630	1	1	104B	Restrooms, Staff - Male	Men's Restroom in the Maintenance Staff Lounge	W2	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
368	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Ceiling	Cracking	3	N	N	0	N	N	
369	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W1	Flaking	20	N	N	0	N	N	3 Locations; Additional Cracking
370	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
371	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W3	Flaking	24	N	N	0	N	N	Additional Cracking
372	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W1	Cracking	27	N	N	0	N	N	
373	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W3	Flaking	45	N	N	0	N	N	Additional Cracking
374	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W1	Cracking	6	N	N	0	Y - 80 SF Contents	N	3 Locations
375	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
376	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents	N	
377	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W1	Partially Inaccessible	0	N	N	0	Y - 72 SF Contents	N	
378	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
379	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W3	Cracking	4	N	N	0	Y - 60 SF Contents	N	
380	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W4	Cracking	2	N	N	0	N	N	
381	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W1	Cracking	3	N	N	0	N	N	
382	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
383	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
384	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking	2	N	N	0	N	N	2 Locations; Additional Cracking
385	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Cracking	2	N	N	0	N	N	
386	2630	1	1	109A	Storage	Room 109 Storage Room	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking
387	2630	1	1	109A	Storage	Room 109 Storage Room	W1	Flaking	18	N	N	0	Y - 24 SF Contents	N	2 Locations; Additional Cracking
388	2630	1	1	109A	Storage	Room 109 Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
389	2630	1	1	109A	Storage	Room 109 Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Boxes	N	
390	2630	1	1	109A	Storage	Room 109 Storage Room	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves	N	
391	2630	1	1	110T	Restrooms, Staff - Female	Principal's Office Restroom	W1	Flaking	2	N	N	0	N	N	
392	2630	1	1	114A	Storage	Room 114 Storage Closet	W1	Partially Inaccessible	0	N	N	0	Y - 8 SF Contents	N	
393	2630	1	1	114A	Storage	Room 114 Storage Closet	W2	Cracking	16	N	N	0	Y - 8 SF Contents	N	
394	2630	1	1	114A	Storage	Room 114 Storage Closet	W3	Cracking	8	N	N	0	Y - 50 SF File Cabinets, Contents	N	
395	2630	1	1	114A	Storage	Room 114 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
396	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	Ceiling	Flaking	16	N	N	0	N	N	3 Locations
397	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W2	Flaking	176	N	N	0	Y - 160 SF Bookcases	N	5 Locations; Additional Cracking
398	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W3	Cracking	64	N	N	0	N	N	
399	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W4	Flaking	248	N	N	0	Y - 30 SF Bookcase, Posters	N	10 Locations; Additional Cracking
400	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W2	Cracking	6	N	N	0	N	N	
401	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W3	Flaking	2	N	N	0	Y - 16 SF Bulletin Board	N	
402	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Ceiling	Flaking	50	Y	N	0	N	Y - 20 SF	2 Locations; Additional Efflorescence
403	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Floor	Chipping	62	N	N	0	N	N	Hall Perimeter
404	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W1	Flaking	34	N	N	0	Y - 110 SF Bulletin Boards, Posters	N	4 Locations; Additional Cracking
405	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W3	Flaking	14	N	N	0	Y - 90 SF Bulletin Boards, Posters	N	5 Locations; Flaking Includes Doors; Additional Cracking
406	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W2	Flaking	10	N	N	0	Y - 84 SF Bookcases, Posters	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
407	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W3	Cracking	12	N	N	0	N	N	Additional Cracking
408	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W4	Flaking	11	N	N	0	Y - 120 SF File Cabinets, Posters	N	
409	2630	1	1	S11	Stairs	Fire Tower Stairwell near end of Gymnasium	Ceiling	Flaking	3	N	N	0	N	N	2 Locations
410	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	Floor	Chipping	1	N	N	0	N	N	
411	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Posters	N	
412	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W4	Flaking	18	N	N	0	N	N	
413	2630	1	1	S15	Stairs	Fire Tower Stairwell across from Classroom 106	Ceiling	Flaking	24	N	N	0	N	N	
414	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W2	Cracking	6	N	N	0	N	N	
415	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W3	Flaking	6	N	N	0	N	N	Door Frame
416	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W4	Flaking	2	N	N	0	N	N	
417	2630	1	1	S17	Stairs	Fire Tower Stairwell across from Classroom 101	Ceiling	Flaking	4	N	N	0	N	N	
418	2630	1	0	001	Art - Elementary	Art Room	Ceiling	Cracking	15	N	N	0	N	N	4 Locations; Additional Holes
419	2630	1	0	001	Art - Elementary	Art Room	W1	Flaking	2	N	N	0	Y - 368 SF Cabinets	N	
420	2630	1	0	001	Art - Elementary	Art Room	W2	Chipping	1	N	N	0	Y - 224 SF Posters	N	
421	2630	1	0	001	Art - Elementary	Art Room	W3	Flaking	10	N	N	0	Y - 216 SF Shelves, Contents	N	3 Locations; Including Radiators; Additional Chipping
422	2630	1	0	001	Art - Elementary	Art Room	W4	Flaking	4	N	N	0	Y - 180 SF Bookcases, Posters, Contents	N	4 Locations; Additional Cracking
423	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
424	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
425	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
426	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
427	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
428	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
429	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W2	Flaking	26	N	N	0	N	N	
430	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W3	Flaking	16	N	N	0	N	N	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
431	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W4	Partially Inaccessible	0	N	N	0	Y - 180 SF Cabinets	N	
432	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Ceiling	Flaking	30	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
433	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Floor	Flaking	24	N	N	0	N	N	Additional Chipping; Damage Around Perimeter
434	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W2	Flaking	60	N	N	0	N	N	Entire Wall; Including Pipe Paint; Additional Cracking
435	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W3	Flaking	14	N	N	0	N	N	Additional Cracking
436	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W4	Flaking	168	N	N	0	N	N	Additional Cracking
437	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	Ceiling	Cracking	1125	N	N	0	N	N	Entire Ceiling
438	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W2	Chipping	8	N	N	0	N	N	Chipping on Door Frame
439	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W3	Flaking	30	N	N	0	N	N	5 Locations; Window Sills 1-5
440	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W4	Cracking	6	N	N	0	N	N	2 Locations
441	2630	1	0	015	Kitchen	Kitchen	W2	Partially Inaccessible	0	N	N	0	Y - 96 SF Freezer	N	
442	2630	1	0	015	Kitchen	Kitchen	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Freezer	N	
443	2630	1	0	015	Kitchen	Kitchen	W4	Cracking	8	N	N	0	Y - 60 SF Contents	N	2 Locations
444	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	Ceiling	Chipping	8	N	N	0	N	N	2 Locations
445	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W1	Cracking	12	N	N	0	Y - 12 SF Posters	N	3 Locations
446	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W3	Flaking	28	N	N	0	N	N	4 Locations
447	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Posters	N	
448	2630	1	0	021	Resource Room	Room B-10 After School Program	W1	Chipping	3	N	N	0	Y - 110 SF Desks, Posters	N	
449	2630	1	0	021	Resource Room	Room B-10 After School Program	W2	Flaking	7	N	N	0	Y - 120 SF Desks, Posters	N	3 Locations
450	2630	1	0	021	Resource Room	Room B-10 After School Program	W3	Chipping	2	N	N	0	Y - 160 SF Desks, Posters	N	
451	2630	1	0	021	Resource Room	Room B-10 After School Program	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Desks, Posters	N	
452	2630	1	0	001A	Storage	Storage Closet next to Art Room	Ceiling	Flaking	8	N	N	0	Y - 36 SF Ductwork	N	
453	2630	1	0	001A	Storage	Storage Closet next to Art Room	W1	Flaking	3	N	N	0	N	N	
454	2630	1	0	001A	Storage	Storage Closet next to Art Room	W2	Flaking	14	N	N	0	Y - 112 SF Shelves	N	
455	2630	1	0	001A	Storage	Storage Closet next to Art Room	W3	Flaking	3	N	N	0	N	N	
456	2630	1	0	001A	Storage	Storage Closet next to Art Room	W4	Partially Inaccessible	0	N	N	0	Y - 112 SF Shelves	N	
457	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	

Sharswood - Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
458	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
459	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
460	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
461	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
462	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
463	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W1	Flaking	10	N	N	0		N	
464	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W2	Flaking	50	N	N	0	Y - 112 SF Shelves	N	
465	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W3	Flaking	30	N	N	0	Y - 60 SF Shelves	N	
466	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W4	Flaking	20	N	N	0	Y - 112 SF Shelves	N	
467	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W1	Chipping	10	N	N	0	N	N	Door Frame/Door
468	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W3	Chipping	3	N	N	0	N	N	3 Locations
469	2630	1	0	021C	Storage	Room B-10 Storage Closet	Ceiling	Holes	2	N	N	0	N	N	
470	2630	1	0	021C	Storage	Room B-10 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 16 SF Contents	N	
471	2630	1	0	021C	Storage	Room B-10 Storage Closet	W3	Flaking	72	N	N	0	Y - 36 SF Contents	N	Entire Wall
472	2630	1	0	021C	Storage	Room B-10 Storage Closet	W4	Flaking	48	N	N	0	Y - 16 SF Contents	N	Entire Wall
473	2630	1	0	021D	Primary	Classroom B-9	Ceiling	Flaking	30	N	N	0	N	N	Including Pipe Paint
474	2630	1	0	021D	Primary	Classroom B-9	Floor	Chipping	20	N	N	0	N	N	5 Locations; Chipping Around Perimeter
475	2630	1	0	021D	Primary	Classroom B-9	W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks	N	
476	2630	1	0	021D	Primary	Classroom B-9	W2	Flaking	30	N	N	0	Y - 60 SF Tables, Posters	N	
477	2630	1	0	021D	Primary	Classroom B-9	W3	Chipping	2	N	N	0	Y - 168 SF Tables, Posters	N	2 Locations
478	2630	1	0	021D	Primary	Classroom B-9	W4	Partially Inaccessible	0	N	N	0	Y - 84 SF Posters	N	
479	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
480	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	

Sharswood - Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
481	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
482	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
483	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
484	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
485	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	Ceiling	Partially Inaccessible	0	N	N	0	Y - 150 SF Ductwork	N	
486	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W2	Flaking	40	N	N	0	N	N	Additional Cracking
487	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W3	Flaking	20	N	N	0	N	N	Additional Cracking
488	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W4	Flaking	68	N	N	0	N	N	Additional Cracking
489	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Ceiling	Cracking	7	N	N	0	N	N	
490	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Floor	Chipping	10	N	N	0	N	N	Chipping Around Perimeter
491	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W1	Flaking	4	N	N	0	N	N	
492	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W3	Flaking	8	N	N	0	N	N	
493	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W4	Cracking	8	N	N	0	N	N	
494	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Ceiling	Partially Inaccessible	0	N	N	0	Y - 330 SF Ductwork	N	
495	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Floor	Flaking	210	N	N	0	N	N	Additional Chipping; Damage Around Perimeter
496	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W2	Flaking	8	N	N	0	N	N	4 Locations

Sharswood - Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
497	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W3	Flaking	6	N	N	0	N	N	3 Locations; Including Pipe Paint; Additional Cracking
498	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W4	Flaking	37	N	N	0	N	N	6 Locations; Additional Cracking
499	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Ceiling	Flaking	12	N	N	0	Y - 280 SF Ductwork	N	Including Pipe Paint
500	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Floor	Flaking	10	N	N	0	N	N	Additional Chipping
501	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W3	Flaking	30	Y	N	0	N	Y - 12 SF	2 Locations; Additional Efflorescence
502	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W4	Flaking	6	N	N	0	N	N	
503	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W1	Flaking	6	N	N	0	N	N	
504	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W2	Flaking	24	N	N	0	N	N	
505	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W4	Cracking	10	N	N	0	N	N	
506	2630	1	0	S07	Stairs	Fire Tower Stairwell near Art Room	Ceiling	Flaking	8	N	N	0	N	N	

Appendix B
EPA Checklist Table

Sharswood - EPA Checklist

Task ID	ULCS#	E I e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information provided is true and complete (name and title)	Date signed
1	2630	1	3	329	Primary	Classroom 329	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	17 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
2	2630	1	3	329	Primary	Classroom 329	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	17 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
3	2630	1	3	329	Primary	Classroom 329	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
4	2630	1	3	329	Primary	Classroom 329	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
5	2630	1	3	329	Primary	Classroom 329	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
6	2630	1	3	329	Primary	Classroom 329	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
7	2630	1	3	330	Primary	Classroom 330	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	18 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
8	2630	1	3	330	Primary	Classroom 330	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
9	2630	1	3	330	Primary	Classroom 330	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
10	2630	1	3	330	Primary	Classroom 330	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
11	2630	1	3	330	Primary	Classroom 330	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
12	2630	1	3	331	Primary	Classroom 331	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	18 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
13	2630	1	3	331	Primary	Classroom 331	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	18 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
14	2630	1	3	331	Primary	Classroom 331	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
15	2630	1	3	331	Primary	Classroom 331	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
16	2630	1	3	331	Primary	Classroom 331	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
17	2630	1	3	331	Primary	Classroom 331	W4	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
18	2630	1	3	332	Primary	Classroom 332	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	14 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
19	2630	1	3	332	Primary	Classroom 332	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	14 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
20	2630	1	3	332	Primary	Classroom 332	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
21	2630	1	3	332	Primary	Classroom 332	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
22	2630	1	3	332	Primary	Classroom 332	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
23	2630	1	3	332	Primary	Classroom 332	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/17/19
24	2630	1	3	333	Primary	Classroom 333	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
25	2630	1	3	333	Primary	Classroom 333	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
26	2630	1	3	333	Primary	Classroom 333	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
27	2630	1	3	333	Primary	Classroom 333	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
28	2630	1	3	333	Primary	Classroom 333	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
29	2630	1	3	334	Primary	Classroom 334	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
30	2630	1	3	334	Primary	Classroom 334	W2	Gouges	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
31	2630	1	3	334	Primary	Classroom 334	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
32	2630	1	3	334	Primary	Classroom 334	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
33	2630	1	3	335	Primary	Classroom 335	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
34	2630	1	3	335	Primary	Classroom 335	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
35	2630	1	3	335	Primary	Classroom 335	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
36	2630	1	3	335	Primary	Classroom 335	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
37	2630	1	3	335	Primary	Classroom 335	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
38	2630	1	3	336	Primary	Classroom 336	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	16 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
39	2630	1	3	336	Primary	Classroom 336	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
40	2630	1	3	336	Primary	Classroom 336	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
41	2630	1	3	336	Primary	Classroom 336	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
42	2630	1	3	336	Primary	Classroom 336	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
43	2630	1	3	337	Primary	Classroom 337	Ceiling	Efflorescence	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
44	2630	1	3	337	Primary	Classroom 337	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
45	2630	1	3	337	Primary	Classroom 337	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
46	2630	1	3	337	Primary	Classroom 337	W2	Efflorescence	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
47	2630	1	3	337	Primary	Classroom 337	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
48	2630	1	3	337	Primary	Classroom 337	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
49	2630	1	3	338	Primary	Classroom 338	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
50	2630	1	3	338	Primary	Classroom 338	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
51	2630	1	3	338	Primary	Classroom 338	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
52	2630	1	3	338	Primary	Classroom 338	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
53	2630	1	3	338	Primary	Classroom 338	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
54	2630	1	3	339	Primary	Classroom 339	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
55	2630	1	3	339	Primary	Classroom 339	W2	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
56	2630	1	3	339	Primary	Classroom 339	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
57	2630	1	3	339	Primary	Classroom 339	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/19/19
58	2630	1	3	340	Primary	Classroom 340	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/20/19
59	2630	1	3	340	Primary	Classroom 340	W2	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/20/19
60																											

Sharswood - EPA Checklist

Task ID	ULCS#	E I e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
64	2630	1	3	341	Primary	Classroom 341	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/12/19
65	2630	1	3	341	Primary	Classroom 341	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/12/19
66	2630	1	3	342	Primary	Classroom 342-A	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	12 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
67	2630	1	3	342	Primary	Classroom 342-A	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	12 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
68	2630	1	3	342	Primary	Classroom 342-A	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
69	2630	1	3	342	Primary	Classroom 342-A	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
70	2630	1	3	342	Primary	Classroom 342-A	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
71	2630	1	3	342	Primary	Classroom 342-A	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
72	2630	1	3	329A	Storage	Storage Room next to Classroom 329	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
73	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
74	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
75	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP / 4 colorimetric / 4 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
76	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
77	2630	1	3	333A	Storage	Classroom 333 Coat Closet	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
78	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
79	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
80	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
81	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/10/19
82	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
83	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
84	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
85	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
86	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
87	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
88	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
89	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
90	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
91	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
92	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
93	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
94	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/11/19
95	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP/1 colorimetric/1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	6/24/29
96	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/29
97	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
98	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
99	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
100	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
101	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/9/19
102	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
103	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
104	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
105	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/13/19
106	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
107	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
108	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
109	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
110	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
111	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	32 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
112	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
113	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
114	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
115	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
116	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
117	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
118	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
119	2630	1	3	S31	Stairs	Fire Tower across from Classroom 341	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/30/19
120	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
121																											

Sharswood - EPA Checklist

Task ID	ULCS#	E I e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
122	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
123	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
124	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
125	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
126	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
127	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
128	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
129	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
130	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
131	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
132	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
133	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
134	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
135	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
136	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
137	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
138	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
139	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
140	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
141	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
142	2630	1	3	S37	Stairs	Fire Tower across from Classroom 329	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
143	2630	1	2	216	IMC (Library)	IMC/Library	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	40 RRP / 4 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/8/19
144	2630	1	2	216	IMC (Library)	IMC/Library	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/8/19
145	2630	1	2	216	IMC (Library)	IMC/Library	W2	Holes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/8/19
146	2630	1	2	216	IMC (Library)	IMC/Library	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/8/19
147	2630	1	2	216	IMC (Library)	IMC/Library	W4	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/8/19
148	2630	1	2	217	Primary	Classroom 217	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
149	2630	1	2	217	Primary	Classroom 217	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
150	2630	1	2	217	Primary	Classroom 217	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
151	2630	1	2	217	Primary	Classroom 217	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
152	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/18/19
153	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/18/19
154	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/18/19
155	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/18/19
156	2630	1	2	219	Primary	Classroom 219	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
157	2630	1	2	219	Primary	Classroom 219	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
158	2630	1	2	219	Primary	Classroom 219	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
159	2630	1	2	219	Primary	Classroom 219	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
160	2630	1	2	219	Primary	Classroom 219	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
161	2630	1	2	219	Primary	Classroom 219	W4	Holes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
162	2630	1	2	220	Auditorium	Auditorium	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	56 RRP / 2 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
163	2630	1	2	220	Auditorium	Auditorium	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	56 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
164	2630	1	2	220	Auditorium	Auditorium	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	13 RRP / 2 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
165	2630	1	2	220	Auditorium	Auditorium	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	13 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
166	2630	1	2	220	Auditorium	Auditorium	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
167	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
168	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
169	2630	1	2	223	Primary	Classroom 223	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
170	2630	1	2	223	Primary	Classroom 223	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
171	2630	1	2	223	Primary	Classroom 223	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
172	2630	1	2	223	Primary	Classroom 223	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
173	2630	1	2	223	Primary	Classroom 223	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
174	2630	1	2	224	Primary	Classroom 224	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	16 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
175	2630	1	2	224	Primary	Classroom 224	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	16 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
176	2630	1	2	224	Primary	Classroom 224	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
177	2630	1	2	224	Primary	Classroom 224	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
178	2630	1	2	224	Primary	Classroom 224	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
179	2630	1	2	224	Primary	Classroom 224	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
180	2630	1	2	225	Primary</																						

Sharswood - EPA Checklist

Task ID	ULCS#	E I m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
185	2630	1	2	225	Primary	Classroom 225	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/25/19
186	2630	1	2	226	Primary	Classroom 226	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
187	2630	1	2	226	Primary	Classroom 226	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
188	2630	1	2	226	Primary	Classroom 226	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
189	2630	1	2	226	Primary	Classroom 226	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/19/19
190	2630	1	2	227	Primary	Classroom 227	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
191	2630	1	2	227	Primary	Classroom 227	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
192	2630	1	2	227	Primary	Classroom 227	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
193	2630	1	2	227	Primary	Classroom 227	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 2 Colorimetric / 2 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
194	2630	1	2	227	Primary	Classroom 227	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 2 Colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
195	2630	1	2	227	Primary	Classroom 227	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
196	2630	1	2	228	Primary	Classroom 228	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
197	2630	1	2	228	Primary	Classroom 228	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
198	2630	1	2	228	Primary	Classroom 228	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
199	2630	1	2	228	Primary	Classroom 228	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
200	2630	1	2	228	Primary	Classroom 228	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
201	2630	1	2	228	Primary	Classroom 228	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
202	2630	1	2	216B	Computer Area	Computer Server Room next to IMCLibrary	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/6/19
203	2630	1	2	216B	Computer Area	Computer Server Room next to IMCLibrary	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/6/19
204	2630	1	2	216B	Computer Area	Computer Server Room next to IMCLibrary	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/6/19
205	2630	1	2	216B	Computer Area	Computer Server Room next to IMCLibrary	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/6/19
206	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
207	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
208	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
209	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
210	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
211	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/17/19
212	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
213	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/2/19
214	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
215	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
216	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
217	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/17/19
218	2630	1	2	220A	Auditorium	Auditorium Stage	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 color	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
219	2630	1	2	220A	Auditorium	Auditorium Stage	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
220	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP / 1 color	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
221	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
222	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
223	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
224	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
225	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
226	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP / 1 color	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
227	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
228	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
229	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
230	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
231	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
232	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP / 1 color	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
233	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
234	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
235	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
236	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
237	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/15/19
238	2630	1	2	223A	Storage	Classroom 223 Coat Closet	Ceiling	Holes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
239	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
240	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
241	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
242	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/24/19
243	2630	1	2	224B																							

Sharswood - EPA Checklist

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
245	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W2	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
246	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W3	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
247	2630	1	2	228A	Storage	Classroom 228 Storage Closet	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
248	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
249	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
250	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
251	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	6/26/19
252	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
253	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
254	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
255	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
256	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	14 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
257	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
258	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
259	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
260	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	32 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
261	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	32 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
262	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
263	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
264	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
265	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	Floor	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
266	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
267	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
268	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
269	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W1	Holes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
270	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
271	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
272	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
273	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
274	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
275	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
276	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
277	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
278	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
279	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
280	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
281	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
282	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
283	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
284	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
285	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
286	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
287	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
288	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
289	2630	1	2	S27	Stairs	Fire Tower Stairwell across from IMC/Library	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
290	2630	1	1	101	Primary	Classroom 101	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
291	2630	1	1	101	Primary	Classroom 101	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
292	2630	1	1	101	Primary	Classroom 101	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19

Sharswood - EPA Checklist

Task ID	ULCS#	E I e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
293	2630	1	1	101	Primary	Classroom 101	W3	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
294	2630	1	1	101	Primary	Classroom 101	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
295	2630	1	1	102	Primary	Classroom 102	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	18 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
296	2630	1	1	102	Primary	Classroom 102	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
297	2630	1	1	102	Primary	Classroom 102	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
298	2630	1	1	102	Primary	Classroom 102	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
299	2630	1	1	102	Primary	Classroom 102	W4	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/9/19
300	2630	1	1	103	Primary	Classroom 103	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
301	2630	1	1	103	Primary	Classroom 103	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
302	2630	1	1	103	Primary	Classroom 103	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
303	2630	1	1	103	Primary	Classroom 103	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/24/19
304	2630	1	1	104	Administrative Office	Nurse's Office	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	17 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/30/19
305	2630	1	1	104	Administrative Office	Nurse's Office	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/30/19
306	2630	1	1	104	Administrative Office	Nurse's Office	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 2 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/30/19
307	2630	1	1	104	Administrative Office	Nurse's Office	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/30/19
308	2630	1	1	104	Administrative Office	Nurse's Office	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/30/19
309	2630	1	1	105	Primary	Classroom 105	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
310	2630	1	1	105	Primary	Classroom 105	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
311	2630	1	1	105	Primary	Classroom 105	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
312	2630	1	1	105	Primary	Classroom 105	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
313	2630	1	1	105	Primary	Classroom 105	W4	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
314	2630	1	1	106	Primary	Classroom 106	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	21 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
315	2630	1	1	106	Primary	Classroom 106	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	21 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
316	2630	1	1	106	Primary	Classroom 106	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
317	2630	1	1	106	Primary	Classroom 106	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
318	2630	1	1	106	Primary	Classroom 106	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
319	2630	1	1	106	Primary	Classroom 106	W4	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
320	2630	1	1	107	Primary	Classroom 107	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/20/19
321	2630	1	1	107	Primary	Classroom 107	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/20/19
322	2630	1	1	107	Primary	Classroom 107	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/20/19
323	2630	1	1	107	Primary	Classroom 107	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/20/19
324	2630	1	1	108	Primary	Classroom 108	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	21 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
325	2630	1	1	108	Primary	Classroom 108	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
326	2630	1	1	108	Primary	Classroom 108	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
327	2630	1	1	108	Primary	Classroom 108	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
328	2630	1	1	108	Primary	Classroom 108	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
329	2630	1	1	109	Primary	Room 109 Head Start Program	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
330	2630	1	1	109	Primary	Room 109 Head Start Program	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
331	2630	1	1	109	Primary	Room 109 Head Start Program	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
332	2630	1	1	109	Primary	Room 109 Head Start Program	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
333	2630	1	1	109	Primary	Room 109 Head Start Program	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
334	2630	1	1	109	Primary	Room 109 Head Start Program	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
335	2630	1	1	110	Administrative Office	Principal's Office	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
336	2630	1	1	110	Administrative Office	Principal's Office	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
337	2630	1	1	110	Administrative Office	Principal's Office	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
338	2630	1	1	110	Administrative Office	Principal's Office	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
339	2630	1	1	111	Administrative Office	Main Office	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
340	2630	1	1	111	Administrative Office	Main Office	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
341	2630	1	1	111	Administrative Office	Main Office	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
342	2630	1	1	111	Administrative Office	Main Office	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
343	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	54 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
344	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	54 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
345	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	14 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
346	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 2 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
347	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	14 RRP / 4 colorimetric / 2 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
348	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	9/3/19
349	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
350	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
351	2630																										

Sharswood - EPA Checklist

Task ID	ULCS#	E I e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
352	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
353	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
354	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
355	2630	1	1	114	Primary	Room 114 Head Start Program	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
356	2630	1	1	114	Primary	Room 114 Head Start Program	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
357	2630	1	1	114	Primary	Room 114 Head Start Program	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
358	2630	1	1	114	Primary	Room 114 Head Start Program	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
359	2630	1	1	101A	Storage	Storage Room next to Classroom 101	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/29/19
360	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/29/19
361	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/29/19
362	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	Ceiling	Efflorescence	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
363	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
364	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
365	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
366	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W4	Efflorescence	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
367	2630	1	1	104B	Restrooms, Staff - Male	Men's Restroom in the Maintenance Staff Lounge	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
368	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
369	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
370	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
371	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/16/19
372	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
373	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/7/19
374	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
375	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
376	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
377	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
378	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
379	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
380	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/23/19
381	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
382	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
383	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
384	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
385	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
386	2630	1	1	109A	Storage	Room 109 Storage Room	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
387	2630	1	1	109A	Storage	Room 109 Storage Room	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
388	2630	1	1	109A	Storage	Room 109 Storage Room	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
389	2630	1	1	109A	Storage	Room 109 Storage Room	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
390	2630	1	1	109A	Storage	Room 109 Storage Room	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/27/19
391	2630	1	1	110T	Restrooms, Staff - Female	Principal's Office Restroom	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/1/19
392	2630	1	1	114A	Storage	Room 114 Storage Closet	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
393	2630	1	1	114A	Storage	Room 114 Storage Closet	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
394	2630	1	1	114A	Storage	Room 114 Storage Closet	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
395	2630	1	1	114A	Storage	Room 114 Storage Closet	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/13/19
396	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
397	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
398	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
399	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
400	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
401	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
402	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	32 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19

Sharswood - EPA Checklist

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
403	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principa's Office to Classroom 105	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	32 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
404	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principa's Office to Classroom 105	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
405	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principa's Office to Classroom 105	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
406	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
407	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W3	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
408	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
409	2630	1	1	S11	Stairs	Fire Tower Stairwell near end of Gymnasium	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/31/19
410	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principa's Office	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	10 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/31/19
411	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principa's Office	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/31/19
412	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principa's Office	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	7/31/19
413	2630	1	1	S15	Stairs	Fire Tower Stairwell across from Classroom 105	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	9 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
414	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W2	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
415	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
416	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
417	2630	1	1	S17	Stairs	Fire Tower Stairwell across from Classroom 101	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19
418	2630	1	0	001	Art - Elementary	Art Room	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	29 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
419	2630	1	0	001	Art - Elementary	Art Room	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
420	2630	1	0	001	Art - Elementary	Art Room	W2	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
421	2630	1	0	001	Art - Elementary	Art Room	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
422	2630	1	0	001	Art - Elementary	Art Room	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/15/19
423	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	8 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
424	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Floor	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	8 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
425	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W1	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
426	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W2	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
427	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W3	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
428	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W4	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/5/19
429	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
430	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
431	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
432	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	27 RRP / 4 colorimetric / 2 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
433	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Floor	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	27 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
434	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP / 3 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
435	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
436	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
437	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	26 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
438	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W2	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 2 colorimetric / 2 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
439	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP / 2 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
440	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 1 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
441	2630	1	0	015	Kitchen	Kitchen	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP / 1 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
442	2630	1	0	015	Kitchen	Kitchen	W3	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
443	2630	1	0	015	Kitchen	Kitchen	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/21/19
444	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	Ceiling	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	27 RRP / 2 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
445	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W1	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
446	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP / 2 colorimetric	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
447	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP / 2 colorimetric / 1 FAAS	N/A	Austin Gwiazdowski / Environmental Technician	8/23/19
448	2630	1	0	021	Resource Room	Room B-10 After School Program	W1	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
449	2630	1	0	021	Resource Room	Room B-10 After School Program	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
450	2630	1	0	021	Resource Room	Room B-10 After School Program	W3	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
451	2630	1	0	021	Resource Room	Room B-10 After School Program	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
452	2630	1	0	001A	Storage	Storage Closet next to Art Room	Ceiling	Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	4 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
453	2630	1	0	001A	Storage	Storage Closet next to Art Room	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
454	2630	1	0	001A	Storage	Storage Closet next to Art Room	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
455	2630	1	0	001A	Storage	Storage Closet next to Art Room	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
456	2630	1	0	001A	Storage	Storage Closet next to Art Room	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/20/19
457	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Sharswood - EPA Checklist

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
458	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
459	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
460	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
461	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
462	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
463	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
464	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
465	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
466	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/19/19
467	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W1	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
468	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W3	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
469	2630	1	0	021C	Storage	Room B-10 Storage Closet	Ceiling	Holes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
470	2630	1	0	021C	Storage	Room B-10 Storage Closet	W2	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
471	2630	1	0	021C	Storage	Room B-10 Storage Closet	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
472	2630	1	0	021C	Storage	Room B-10 Storage Closet	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	1 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
473	2630	1	0	021D	Primary	Classroom B-9	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
474	2630	1	0	021D	Primary	Classroom B-9	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	19 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
475	2630	1	0	021D	Primary	Classroom B-9	W1	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
476	2630	1	0	021D	Primary	Classroom B-9	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
477	2630	1	0	021D	Primary	Classroom B-9	W3	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
478	2630	1	0	021D	Primary	Classroom B-9	W4	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/12/19
479	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
480	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
481	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
482	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
483	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
484	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
485	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	Ceiling	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
486	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
487	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
488	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
489	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Ceiling	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	12 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
490	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Floor	Chipping	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	12 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
491	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
492	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
493	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/22/19
494	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Ceiling	Partially Inaccessible	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/27/19
495	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Floor	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/27/19
496	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/27/19
497	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/27/19
498	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	15 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/27/19
499	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/26/19

Sharswood - EPA Checklist

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Warning signs posted at entrance to work area	Work area contained to prevent spread of dust and debris	All objects in the work area removed or covered (interiors)	HVAC ducts in the work area closed and covered (interiors)	Windows in the work area closed (interiors)	Doors in the work area closed and sealed (interiors)	Doors that must be used in the work area covered to allow passage but prevent spread of dust	Floors in the work area covered with taped-down plastic (interiors)	Waste contained on-site and while being transported off-site	Work site properly cleaned after renovation	All chips and debris picked up, protective sheeting misted, folded dirty side inward, and taped for removal	Light lenses inspected (Y/N)	Surfaces above light fixtures inspected (Y/N)	Work area surfaces and objects cleaned using HEPA vacuum and/or wet cloths or mops (interior)	Certified renovator performed post-renovation cleaning verification	Describe the results of post-renovation cleaning verification, including the number of wet and dry cloths used	If dust clearance testing was performed instead, attach a copy of the report	I certify under penalty of law that the previous information is true and complete (name and title)	Date signed
500	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Floor	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	20 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/26/19
501	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W3	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	7 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/26/19
502	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W4	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	3 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/26/19
503	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W1	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	2 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
504	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W2	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
505	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W4	Cracking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	5 RRP	N/A	Austin Gwiazdowski / Environmental Technician	8/14/19
506	2630	1	0	S07	Stairs	Fire Tower Stairwell near Art Room	Ceiling	Flaking	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	6 RRP	N/A	Austin Gwiazdowski / Environmental Technician	9/4/19

Appendix C

Oversight Table

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, effloescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
1	2630	1	3	329	Primary	Classroom 329	Ceiling	Flaking				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	672	17	N/A	N/A	N/A	
2	2630	1	3	329	Primary	Classroom 329	Floor	Chipping				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	672	17	N/A	N/A	N/A	
3	2630	1	3	329	Primary	Classroom 329	W1	Flaking				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	168	4	N/A	N/A	N/A	
4	2630	1	3	329	Primary	Classroom 329	W2	Flaking				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
5	2630	1	3	329	Primary	Classroom 329	W3	Flaking				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	168	4	N/A	N/A	N/A	
6	2630	1	3	329	Primary	Classroom 329	W4	Flaking				N/A	N/A	N/A	6/13/19	6/18/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
7	2630	1	3	330	Primary	Classroom 330	Floor	Chipping				N/A	N/A	N/A	6/12/19	6/17/19	7/5/19	6/24/19	696	18	N/A	N/A	N/A	
8	2630	1	3	330	Primary	Classroom 330	W1	Flaking				N/A	N/A	N/A	6/12/19	6/17/19	7/5/19	6/24/19	174	5	N/A	N/A	N/A	
9	2630	1	3	330	Primary	Classroom 330	W2	Cracking				N/A	N/A	N/A	6/12/19	6/17/19	7/5/19	6/24/19	144	4	N/A	N/A	N/A	
10	2630	1	3	330	Primary	Classroom 330	W3	Flaking				N/A	N/A	N/A	6/12/19	6/17/19	7/5/19	6/24/19	174	5	N/A	N/A	N/A	
11	2630	1	3	330	Primary	Classroom 330	W4	Partially Inaccessible				N/A	N/A	N/A	6/12/19	6/17/19	7/5/19	6/24/19	144	4	N/A	N/A	N/A	
12	2630	1	3	331	Primary	Classroom 331	Ceiling		Flaking			N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	696	18	N/A	N/A	N/A	
13	2630	1	3	331	Primary	Classroom 331	Floor	Chipping				N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	696	18	N/A	N/A	N/A	
14	2630	1	3	331	Primary	Classroom 331	W1	Flaking				N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	174	5	N/A	N/A	N/A	
15	2630	1	3	331	Primary	Classroom 331	W2	Flaking				N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
16	2630	1	3	331	Primary	Classroom 331	W3	Flaking				N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	174	5	N/A	N/A	N/A	
17	2630	1	3	331	Primary	Classroom 331	W4	Chipping				N/A	N/A	N/A	6/12/19	6/17/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
18	2630	1	3	332	Primary	Classroom 332	Ceiling	Flaking				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	552	14	N/A	N/A	N/A	
19	2630	1	3	332	Primary	Classroom 332	Floor	Chipping				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	552	14	N/A	N/A	N/A	
20	2630	1	3	332	Primary	Classroom 332	W1	Flaking				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	138	4	N/A	N/A	N/A	
21	2630	1	3	332	Primary	Classroom 332	W2	Flaking				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
22	2630	1	3	332	Primary	Classroom 332	W3	Flaking				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	138	4	N/A	N/A	N/A	
23	2630	1	3	332	Primary	Classroom 332	W4	Cracking				N/A	N/A	N/A	6/11/19	6/17/19	7/8/19	6/24/19	144	4	N/A	N/A	N/A	
24	2630	1	3	333	Primary	Classroom 333	Ceiling	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	775	20	N/A	N/A	N/A	
25	2630	1	3	333	Primary	Classroom 333	W1	Cracking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	186	5	N/A	N/A	N/A	
26	2630	1	3	333	Primary	Classroom 333	W2	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	150	4	N/A	N/A	N/A	
27	2630	1	3	333	Primary	Classroom 333	W3	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	186	5	N/A	N/A	N/A	
28	2630	1	3	333	Primary	Classroom 333	W4	Cracking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	150	4	N/A	N/A	N/A	
29	2630	1	3	334	Primary	Classroom 334	W1	Flaking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	174	4	N/A	N/A	N/A	
30	2630	1	3	334	Primary	Classroom 334	W2	Gouges				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	144	4	N/A	N/A	N/A	
31	2630	1	3	334	Primary	Classroom 334	W3	Cracking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	174	4	N/A	N/A	N/A	
32	2630	1	3	334	Primary	Classroom 334	W4	Flaking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	144	4	N/A	N/A	N/A	
33	2630	1	3	335	Primary	Classroom 335	Floor	Chipping				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	780	20	N/A	N/A	N/A	
34	2630	1	3	335	Primary	Classroom 335	W1	Flaking				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	180	5	N/A	N/A	N/A	
35	2630	1	3	335	Primary	Classroom 335	W2	Partially Inaccessible				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	156	4	N/A	N/A	N/A	
36	2630	1	3	335	Primary	Classroom 335	W3		Flaking			6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	180	5	N/A	N/A	N/A	
37	2630	1	3	335	Primary	Classroom 335	W4	Flaking				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	156	4	N/A	N/A	N/A	
38	2630	1	3	336	Primary	Classroom 336	Floor	Chipping				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	638	16	N/A	N/A	N/A	
39	2630	1	3	336	Primary	Classroom 336	W1	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	154	4	N/A	N/A	N/A	
40	2630	1	3	336	Primary	Classroom 336	W2	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	132	3	N/A	N/A	N/A	
41	2630	1	3	336	Primary	Classroom 336	W3	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	154	4	N/A	N/A	N/A	
42	2630	1	3	336	Primary	Classroom 336	W4	Cracking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	132	3	N/A	N/A	N/A	
43	2630	1	3	337	Primary	Classroom 337	Ceiling	Effloescence				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	768	20	N/A	N/A	N/A	
44	2630	1	3	337	Primary	Classroom 337	Floor	Chipping				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	768	20	N/A	N/A	N/A	
45	2630	1	3	337	Primary	Classroom 337	W1	Cracking				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	192	5	N/A	N/A	N/A	
46	2630	1	3	337	Primary	Classroom 337	W2	Effloescence				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	144	4	N/A	N/A	N/A	
47	2630	1	3	337	Primary	Classroom 337	W3		Flaking			6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	192	5	N/A	N/A	N/A	
48	2630	1	3	337	Primary	Classroom 337	W4	Flaking				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	144	4	N/A	N/A	N/A	
49	2630	1	3	338	Primary	Classroom 338	Floor	Chipping				N/A	N/A	N/A	6/13/19	6/19/19	7/1/19	6/25/19	576	15	N/A	N/A	N/A	
50	2630	1	3	338	Primary	Classroom 338	W1	Flaking				N/A	N/A	N/A	6/13/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
51	2630	1	3	338	Primary	Classroom 338	W2	Cracking				N/A	N/A	N/A	6/13/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
52	2630	1	3	338	Primary	Classroom 338	W3	Flaking				N/A	N/A	N/A	6/13/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
53	2630	1	3	338	Primary	Classroom 338	W4	Flaking				N/A	N/A	N/A	6/13/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
54	2630	1	3	339	Primary	Classroom 339	W1	Cracking				N/A	N/A	N/A	6/14/19	6/19/19	7/1/19	6/25/19	174	5	N/A	N/A	N/A	
55	2630	1	3	339	Primary	Classroom 339	W2	Chipping				N/A	N/A	N/A	6/14/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
56	2630	1	3	339	Primary	Classroom 339	W3	Flaking				N/A	N/A	N/A	6/14/19	6/19/19	7/1/19	6/25/19	174	5	N/A	N/A	N/A	
57	2630	1	3	339	Primary	Classroom 339	W4	Cracking				N/A	N/A	N/A	6/14/19	6/19/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
58	2630	1	3	340	Primary	Classroom 340	W1	Flaking				N/A	N/A	N/A	6/14/19	6/20/19	7/1/19	6/25/19	174	5	N/A	N/A	N/A	
59	2630	1	3	340	Primary	Classroom 340	W2	Chipping				N/A	N/A	N/A	6/14/19	6/20/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
60	2630	1	3	340	Primary	Classroom 340	W3	Cracking				N/A	N/A	N/A	6/14/19	6/20/19	7/1/19	6/25/19	174	5	N/A	N/A	N/A	
61	2630	1	3	340	Primary	Classroom 340	W4	Partially Inaccessible				N/A	N/A	N/A	6/14/19	6/20/19	7/1/19	6/25/19	144	4	N/A	N/A	N/A	
62	2630	1	3	341	Primary	Classroom 341	W1		Flaking			6/24/19	7/1/19	7/1/19	7/3/19	7/12/19	7/20/19	7/16/19	186	5	0	N/A	N/A	2 colorimetric, 1 taken for FAAS on 7/12/19. Passed with <10, 7/15/19.
63	2630	1	3	341	Primary	Classroom 341	W2	Flaking				6/24/19	7/1/19	7/1/19	7/3/19	7/12/19	7/20/19	7/16/19</						

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
72	2630	1	3	329A	Storage	Storage Room next to Classroom 329	Ceiling	Cracking				6/24/19	7/1/19	7/1/19	7/2/19	7/11/19	7/18/19	7/16/19	120	4	N/A	N/A	N/A	
73	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W1	Flaking				6/24/19	7/1/19	7/1/19	7/2/19	7/11/19	7/18/19	7/16/19	48	2	N/A	N/A	N/A	
74	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W2	Flaking				6/24/19	7/1/19	7/1/19	7/2/19	7/11/19	7/18/19	7/16/19	90	3	N/A	N/A	N/A	
75	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W3	Flaking				N/A	N/A	N/A	6/17/19	7/10/19	N/A	7/10/19	84	2	4	yes	<10 µg/ft^2	4 colorimetrics. 4 FAAS. Failed FAAS 3 times, 44 then 66, then 24. Passed 4th FAAS with <10.
76	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W4	Flaking				N/A	N/A	N/A	6/17/19	7/10/19	N/A	7/10/19	144	4	0	N/A	N/A	
77	2630	1	3	333A	Storage	Classroom 333 Coat Closet	Ceiling	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	125	3	N/A	N/A	N/A	
78	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W1	Cracking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	125	3	N/A	N/A	N/A	
79	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W2	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	30	1	N/A	N/A	N/A	
80	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W3	Flaking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	125	3	N/A	N/A	N/A	
81	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W4	Cracking				6/24/19	6/26/19	6/26/19	6/27/19	7/10/19	7/18/19	7/15/19	125	1	N/A	N/A	N/A	
82	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W1	Flaking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	108	3	N/A	N/A	N/A	
83	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W3	Flaking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	108	3	N/A	N/A	N/A	
84	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W4	Cracking				N/A	N/A	N/A	6/11/19	6/13/19	6/26/19	6/21/19	24	1	N/A	N/A	N/A	
85	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W1	Flaking				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	104	3	N/A	N/A	N/A	
86	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W2	Flaking				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	24	1	N/A	N/A	N/A	
87	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W3	Flaking				6/24/19	6/25/19	6/25/19	6/26/19	7/9/19	7/18/19	7/11/19	104	3	N/A	N/A	N/A	
88	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Ceiling	Cracking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	108	3	N/A	N/A	N/A	
89	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Floor	Chipping				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	108	3	N/A	N/A	N/A	
90	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W1	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	24	1	N/A	N/A	N/A	
91	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W3	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	24	1	N/A	N/A	N/A	
92	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W4	Cracking				N/A	N/A	N/A	6/10/19	6/13/19	6/26/19	6/21/19	108	3	N/A	N/A	N/A	
93	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W2	Cracking				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	30	1	N/A	N/A	N/A	
94	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W3	Flaking				6/24/19	6/26/19	6/26/19	7/2/19	7/11/19	7/20/19	7/15/19	130	4	N/A	N/A	N/A	
95	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking				N/A	N/A	N/A	6/17/19	6/20/19	N/A	6/26/19	144	4	0	N/A	N/A	
96	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking				N/A	N/A	N/A	6/17/19	6/20/19	N/A	6/26/19	84	2	1	yes	17 µg/ft^2	1 Colorimetric. 1 FAAS. Passed.
97	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	Ceiling	Flaking				6/24/19	6/26/19	6/26/19	6/28/19	7/9/19	7/18/19	7/11/19	75	2	N/A	N/A	N/A	
98	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W1	Flaking				6/24/19	6/26/19	6/26/19	6/28/19	7/9/19	7/18/19	7/11/19	75	2	N/A	N/A	N/A	
99	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W2	Partially Inaccessible				6/24/19	6/26/19	6/26/19	6/28/19	7/9/19	7/18/19	7/11/19	30	1	N/A	N/A	N/A	
100	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W3	Flaking				6/24/19	6/26/19	6/26/19	6/28/19	7/9/19	7/18/19	7/11/19	75	2	N/A	N/A	N/A	
101	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W4	Flaking				6/24/19	6/26/19	6/26/19	6/28/19	7/9/19	7/18/19	7/11/19	30	1	N/A	N/A	N/A	
102	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	Ceiling	Cracking				N/A	N/A	N/A	6/10/19	6/13/19	7/8/19	6/21/19	252	6	0	N/A	N/A	Classroom marked 342A
103	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W1	Cracking				N/A	N/A	N/A	6/10/19	6/13/19	7/8/19	6/21/19	126	3	0	N/A	N/A	Classroom marked 342A
104	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W2	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	7/8/19	6/21/19	72	2	0	N/A	N/A	Classroom marked 342A
105	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W3	Flaking				N/A	N/A	N/A	6/10/19	6/13/19	7/8/19	6/21/19	126	3	0	N/A	N/A	Classroom marked 342A
106	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	Floor	Chipping				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	800	20	N/A	N/A	N/A	
107	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W2	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
108	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W3	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	48	2	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
109	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W1	Cracking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	150	4	N/A	N/A	N/A	
110	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W2	Cracking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	126	4	N/A	N/A	N/A	
111	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	Floor	Chipping				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	1250	32	N/A	N/A	N/A	
112	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W1	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	750	19	N/A	N/A	N/A	
113	2630	1	3	H311	Circulation (Hallway)	Hallway from Classroom 333 to Fire Tower near Classroom 336	W3	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	750	19	N/A	N/A	N/A	
114	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Ceiling	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	800	20	N/A	N/A	N/A	
115	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	Floor	Chipping				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	800	20	N/A	N/A	N/A	
116	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W2	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
117	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W3	Cracking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	48	2	N/A	N/A	N/A	
118	2630	1	3	H312	Circulation (Hallway)	Hallway from Classrooms 329 to 332	W4	Flaking				7/17/19	7/20/19	7/20/19	7/23/19	8/13/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
119	2630	1	3	S31	Stairs	Fire Tower across from Classroom 341	Ceiling	Flaking				7/17/19	7/20/19	7/20/19	8/12/19	8/30/19	N/A	8/23/19	240	6	N/A	N/A	N/A	
120	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	Ceiling	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	372	10	N/A	N/A	N/A	
121	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W1	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
122	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W2	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
123	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W3	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
124	2630	1	3	S33	Stairs	Stairwell next to Classroom 337	W4	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
125	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Ceiling	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
126	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	Floor	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
127	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W1	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
128	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W2	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
129	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W3	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
130	2630	1	3	S34	Stairs	Fire Tower near Classroom 336	W4	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
131	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Ceiling	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
132	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Floor	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
133	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W1	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
134	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W2	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
135	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W3	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
136	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W4	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
137	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	Ceiling	Flaking				7/29/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	372	10	N/A	N/A	N/A	
138	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W1	Flaking				7/29/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
139	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W2	Flaking				7/29/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
140	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W3	Flaking				7/29/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
141	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W4	Flaking				7/29/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
142	2630	1	3	S37	Stairs	Fire Tower across from Classroom 329	Ceiling	Flaking				7/17/19	7/20/19	7/20/19	8/12/19	9/4/19	N/A	8/30/19	240	6	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
143	2630	1	2	216	IMC (Library)	IMC/Library	Floor	Chipping	7/8/19			6/18/19	6/25/19	6/25/19	6/27/19	7/8/19	7/26/19	7/9/19	1586	40	5	yes/1	< 10 µg/ft²	4 colorimetric 1 FAAS Passed with <10 on 7/8/19. Preexisting hanging ceiling edge. Ceiling (next to windows and drop ceiling) needs to be done. Will retest afterwards. Done and tested W3 with colorimetric 7/19/19.
144	2630	1	2	216	IMC (Library)	IMC/Library	W1	Flaking				6/18/19	6/25/19	6/25/19	6/27/19	7/8/19	7/26/19	7/9/19	366	9	0	no	N/A	
145	2630	1	2	216	IMC (Library)	IMC/Library	W2	Holes				6/18/19	6/25/19	6/25/19	6/27/19	7/8/19	7/26/19	7/9/19	156	4	0	no	N/A	
146	2630	1	2	216	IMC (Library)	IMC/Library	W3	Flaking				6/18/19	6/25/19	6/25/19	6/27/19	7/8/19	7/26/19	7/9/19	366	9	0	no	N/A	
147	2630	1	2	216	IMC (Library)	IMC/Library	W4	Chipping				6/18/19	6/25/19	6/25/19	6/27/19	7/8/19	7/26/19	7/9/19	156	4	0	no	N/A	
148	2630	1	2	217	Primary	Classroom 217	Floor	Chipping				6/18/19	6/20/19	6/20/19	6/21/19	7/2/19	7/9/19	7/5/19	754	19	N/A	N/A	N/A	W3 has preexisting missing ceiling tile.
149	2630	1	2	217	Primary	Classroom 217	W1	Flaking				6/18/19	6/20/19	6/20/19	6/21/19	7/2/19	7/9/19	7/5/19	174	5	N/A	N/A	N/A	
150	2630	1	2	217	Primary	Classroom 217	W3	Flaking				6/18/19	6/20/19	6/20/19	6/21/19	7/2/19	7/9/19	7/5/19	174	5	N/A	N/A	N/A	
151	2630	1	2	217	Primary	Classroom 217	W4	Partially Inaccessible				6/18/19	6/20/19	6/20/19	6/21/19	7/2/19	7/9/19	7/5/19	156	4	N/A	N/A	N/A	
152	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W1	Cracking				7/9/19	7/10/19	7/10/19	7/10/19	7/18/19	7/24/19	7/22/19	138	4	N/A	N/A	N/A	
153	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W2	Flaking				7/9/19	7/10/19	7/10/19	7/10/19	7/18/19	7/24/19	7/22/19	126	4	N/A	N/A	N/A	
154	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W3	Cracking				7/9/19	7/10/19	7/10/19	7/10/19	7/18/19	7/24/19	7/22/19	138	4	N/A	N/A	N/A	
155	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W4	Partially Inaccessible				7/9/19	7/10/19	7/10/19	7/10/19	7/18/19	7/24/19	7/22/19	126	4	N/A	N/A	N/A	
156	2630	1	2	219	Primary	Classroom 219	Ceiling	Flaking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	792	20	N/A	N/A	N/A	
157	2630	1	2	219	Primary	Classroom 219	Floor	Chipping				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	792	20	N/A	N/A	N/A	
158	2630	1	2	219	Primary	Classroom 219	W1	Flaking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	198	5	N/A	N/A	N/A	
159	2630	1	2	219	Primary	Classroom 219	W2	Cracking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	144	4	N/A	N/A	N/A	
160	2630	1	2	219	Primary	Classroom 219	W3	Flaking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	198	5	N/A	N/A	N/A	
161	2630	1	2	219	Primary	Classroom 219	W4	Holes				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	144	4	N/A	N/A	N/A	
162	2630	1	2	220	Auditorium	Auditorium	Ceiling	Cracking				6/18/19	6/18/19	6/18/19	6/21/19	7/15/19	8/12/19	8/6/19	2210	56	2	no	N/A	Tested with 6 colorimetrics, 1 FAAS. being brought to lab at end of the day, 7/12/19.
163	2630	1	2	220	Auditorium	Auditorium	Floor	Chipping				6/18/19	6/18/19	6/18/19	6/21/19	7/15/19	8/12/19	8/6/19	2210	56	0	N/A	N/A	
164	2630	1	2	220	Auditorium	Auditorium	W1	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	7/15/19	8/12/19	8/6/19	510	13	2	no	N/A	Wall has missing corkboard by the stage that was removed prior to this project. Gino (School District Paint Inspector) instructed painters to leave the space as is and not paint the concrete (which the corkboard would cover).
165	2630	1	2	220	Auditorium	Auditorium	W3	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	7/15/19	8/12/19	8/6/19	510	13	1	yes	< 10 µg/ft²	
166	2630	1	2	220	Auditorium	Auditorium	W4	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	7/15/19	8/12/19	8/6/19	156	4	1	no	N/A	
167	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W3	Flaking				7/2/19	7/3/19	7/3/19	7/5/19	7/19/19	8/12/19	7/23/19	60	2	0	N/A	N/A	
168	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W4	Partially Inaccessible				7/2/19	7/3/19	7/3/19	7/5/19	7/19/19	8/12/19	7/23/19	138	4	1	yes	< 10 µg/ft²	1 colorimetric / 1 FAAS on W4, will take to lab 7/18/19, paseed with <10, 7/19/19.
169	2630	1	2	223	Primary	Classroom 223	Floor	Chipping				6/14/19	6/17/19	6/17/19	6/18/19	6/21/19	7/3/19	6/28/19	736	19	N/A	N/A	N/A	
170	2630	1	2	223	Primary	Classroom 223	W1	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/21/19	7/3/19	6/28/19	192	5	N/A	N/A	N/A	
171	2630	1	2	223	Primary	Classroom 223	W2	Partially Inaccessible				6/14/19	6/17/19	6/17/19	6/18/19	6/21/19	7/3/19	6/28/19	144	4	N/A	N/A	N/A	
172	2630	1	2	223	Primary	Classroom 223	W3	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/21/19	7/3/19	6/28/19	192	5	N/A	N/A	N/A	
173	2630	1	2	223	Primary	Classroom 223	W4	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/21/19	7/3/19	6/28/19	144	4	N/A	N/A	N/A	
174	2630	1	2	224	Primary	Classroom 224	Ceiling	Flaking				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	624	16	0	N/A	N/A	2 colorimetrics. 1 FAAS. needs to be retested because ceiling is being redone. Retested on 7/15/19. Passed 2 colorimetrics. Passed FAAS 7/17/19.
175	2630	1	2	224	Primary	Classroom 224	Floor	Chipping				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	624	16	0	N/A	N/A	
176	2630	1	2	224	Primary	Classroom 224	W1	Cracking				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	144	4	0	N/A	N/A	
177	2630	1	2	224	Primary	Classroom 224	W2	Partially Inaccessible				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	156	4	1	yes	< 10 µg/ft²	
178	2630	1	2	224	Primary	Classroom 224	W3	Flaking				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	144	4	1	no	N/A	
179	2630	1	2	224	Primary	Classroom 224	W4	Flaking				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	156	4	0	N/A	N/A	
180	2630	1	2	225	Primary	Classroom 225	Ceiling	Cracking				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	696	18	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
181	2630	1	2	225	Primary	Classroom 225	Floor	Chipping				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	696	18	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
182	2630	1	2	225	Primary	Classroom 225	W1	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	174	5	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
183	2630	1	2	225	Primary	Classroom 225	W2	Partially Inaccessible				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	144	4	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
184	2630	1	2	225	Primary	Classroom 225	W3	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	174	5	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
185	2630	1	2	225	Primary	Classroom 225	W4	Flaking				6/18/19	6/18/19	6/18/19	6/21/19	6/25/19	7/3/19	7/1/19	144	4	N/A	N/A	N/A	Recleaned and Stabilized 7/1/19
186	2630	1	2	226	Primary	Classroom 226	W1	Flaking				6/18/19	7/1/19	7/1/19	7/2/19	7/19/19	7/24/19	7/19/19	174	5	0	N/A	N/A	1 color/1FAAS on W2, 1color on W3. Sending FAAS to lab 7/16/19. Passed with < 10, 7/18/19.
187	2630	1	2	226	Primary	Classroom 226	W2	Flaking				6/18/19	7/1/19	7/1/19	7/2/19	7/19/19	7/24/19	7/19/19	150	4	1	yes	< 10 µg/ft²	
188	2630	1	2	226	Primary	Classroom 226	W3	Flaking				6/18/19	7/1/19	7/1/19	7/2/19	7/19/19	7/24/19	7/19/19	174	5	1	no	N/A	
189	2630	1	2	226	Primary	Classroom 226	W4	Partially Inaccessible				6/18/19	7/1/19	7/1/19	7/2/19	7/19/19	7/24/19	7/19/19	150	4	0	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
190	2630	1	2	227	Primary	Classroom 227	Ceiling	Flaking				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	750	19	0	N/A	N/A	Tested 1 color on W2, 1 color in bathroom, 1 color / FAAS on W3 on 8/6/19. FAAS failed with 46 on 8/6/19. Recleaned and retested, 1 color / 1 FAAS w3, 1 color w2 on 8/8/19. Passed with <10 on 8/9/19.
191	2630	1	2	227	Primary	Classroom 227	Floor	Chipping				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	750	19	0	N/A	N/A	
192	2630	1	2	227	Primary	Classroom 227	W1	Flaking				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	180	5	0	N/A	N/A	
193	2630	1	2	227	Primary	Classroom 227	W2	Flaking				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	150	4	2	no	N/A	
194	2630	1	2	227	Primary	Classroom 227	W3	Flaking				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	180	5	2	yes	< 10 µg/ft²	
195	2630	1	2	227	Primary	Classroom 227	W4	Cracking				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	150	4	0	N/A	N/A	
196	2630	1	2	228	Primary	Classroom 228	Ceiling	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	792	20	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
197	2630	1	2	228	Primary	Classroom 228	Floor	Chipping				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	792	20	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
198	2630	1	2	228	Primary	Classroom 228	W1	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	198	5	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
199	2630	1	2	228	Primary	Classroom 228	W2	Cracking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	144	4	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
200	2630	1	2	228	Primary	Classroom 228	W3	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	198	5	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
201	2630	1	2	228	Primary	Classroom 228	W4	Partially Inaccessible				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	144	4	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
202	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W1	Partially Inaccessible				6/18/19	7/26/19	7/26/19	7/29/19	8/6/19	8/12/19	8/7/19	48	2	N/A	N/A	N/A	
203	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W2	Partially Inaccessible				6/18/19	7/26/19	7/26/19	7/29/19	8/6/19	8/12/19	8/7/19	90	3	N/A	N/A	N/A	
204	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W3	Partially Inaccessible				6/18/19	7/26/19	7/26/19	7/29/19	8/6/19	8/12/19	8/7/19	48	2	N/A	N/A	N/A	
205	2630	1	2	216B	Computer Area	Computer Server Room next to IMC/Library	W4	Partially Inaccessible				6/18/19	7/26/19	7/26/19	7/29/19	8/6/19	8/12/19	8/7/19	90	3	N/A	N/A	N/A	
206	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Ceiling	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	60	2	N/A	N/A	N/A	Air conditioner filter has mold on it, Ryan Hutsell inspected on 8/7/19.
207	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	Floor	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	60	2	N/A	N/A	N/A	
208	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W1	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	60	2	N/A	N/A	N/A	
209	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W2	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	30	1	N/A	N/A	N/A	
210	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W3	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	60	2	N/A	N/A	N/A	
211	2630	1	2	218A	Computer Area	Faculty Lounge Computer Server Room	W4	Inaccessible				8/5/19	8/7/19	8/7/19	8/15/19	8/17/19	8/19/19	8/19/19	30	1	N/A	N/A	N/A	
212	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W3	Flaking				N/A	6/13/19	N/A	6/19/19	7/2/19	N/A	7/5/19	90	3	N/A	N/A	N/A	W1 has preexisting large hole in wall, near ceiling.
213	2630	1	2	219A	Restrooms, Staff - Female	Women's Restroom next to Classroom 219	W4	Flaking				N/A	6/13/19	N/A	6/19/19	7/2/19	N/A	7/5/19	144	4	N/A	N/A	N/A	
214	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W1	Flaking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	125	4	N/A	N/A	N/A	
215	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W2	Partially Inaccessible				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	30	1	N/A	N/A	N/A	
216	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W3	Cracking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	125	4	N/A	N/A	N/A	
217	2630	1	2	219B	Storage	Classroom 219 Coat Closet	W4	Cracking				7/2/19	7/5/19	7/5/19	7/5/19	7/17/19	7/24/19	7/22/19	30	1	N/A	N/A	N/A	
218	2630	1	2	220A	Auditorium	Auditorium Stage	W3	Flaking				6/14/19	6/20/19	6/20/19	6/21/19	7/15/19	8/6/19	8/3/19	126	4	1	no	N/A	tested with 1 colorimetric 7/12/2019
219	2630	1	2	220A	Auditorium	Auditorium Stage	W4	Flaking				6/14/19	6/20/19	6/20/19	6/21/19	7/15/19	8/6/19	8/3/19	72	2	0	N/A	N/A	
220	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Ceiling	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	84	3	1	no	N/A	tested with 1 colorimetric 7/12/2019
221	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Floor	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	84	3	0	N/A	N/A	
222	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W1	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
223	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W2	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	84	3	0	N/A	N/A	
224	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W3	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
225	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W4	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	84	3	0	N/A	N/A	
226	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Ceiling	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	1	no	N/A	tested with 1 colorimetric 7/12/2019
227	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Floor	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
228	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W1	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
229	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W2	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
230	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W3	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
231	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W4	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
232	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Ceiling	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	1	no	N/A	tested with 1 colorimetric 7/12/2019

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
233	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Floor	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
234	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W1	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
235	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W2	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
236	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W3	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	24	1	0	N/A	N/A	
237	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W4	Inaccessible				6/14/19	6/18/19	6/18/19	6/21/19	7/15/19	8/6/19	8/3/19	76	2	0	N/A	N/A	
238	2630	1	2	223A	Storage	Classroom 223 Coat Closet	Ceiling	Holes				6/14/19	6/17/19	6/17/19	6/21/19	6/24/19	7/3/19	6/28/19	104	3	N/A	N/A	N/A	
239	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W1	Flaking				6/14/19	6/17/19	6/17/19	6/21/19	6/24/19	7/3/19	6/28/19	104	3	N/A	N/A	N/A	
240	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W2	Flaking				6/14/19	6/17/19	6/17/19	6/21/19	6/24/19	7/3/19	6/28/19	24	1	N/A	N/A	N/A	
241	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W3	Flaking				6/14/19	6/17/19	6/17/19	6/21/19	6/24/19	7/3/19	6/28/19	104	3	N/A	N/A	N/A	
242	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W4	Flaking				6/14/19	6/17/19	6/17/19	6/21/19	6/24/19	7/3/19	6/28/19	24	1	N/A	N/A	N/A	
243	2630	1	2	224B	Student Restrooms - Male/Female (Classroom)	Classroom 224 Restroom	W2	Flaking				6/14/19	6/17/19	6/17/19	6/17/19	7/17/19	7/24/19	7/18/19	35	1	0	N/A	N/A	
244	2630	1	2	226B	Student Restrooms - Male/Female (Classroom)	Classroom 226 Restroom	W3	Flaking				6/14/19	7/1/19	7/1/19	7/2/19	7/19/19	7/24/19	7/19/19	35	1	1	no	N/A	Ceiling peeling and efflorescence. Needs to be scraped, plastered, and painted again as of 7/18/19
245	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W2	Chipping				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	24	1	0	N/A	N/A	
246	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W3	Chipping				7/22/19	7/24/19	7/24/19	7/24/19	8/9/19	8/12/19	8/7/19	28	1	1	no	N/A	
247	2630	1	2	228A	Storage	Classroom 228 Storage Closet	Ceiling	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	75	2	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
248	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W1	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	75	2	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
249	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W2	Cracking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	30	1	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
250	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W3	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	75	2	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
251	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W4	Flaking				6/14/19	6/17/19	6/17/19	6/18/19	6/26/19	7/3/19	7/2/19	30	1	N/A	N/A	N/A	Recleaned and Stabilized 7/2/19
252	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	Floor	Chipping				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	800	20	N/A	N/A	N/A	
253	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W2	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
254	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W3	Cracking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	48	2	N/A	N/A	N/A	
255	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W4	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
256	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	Floor	Chipping				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	525	14	N/A	N/A	N/A	
257	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W2	Partially Inaccessible				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	126	4	N/A	N/A	N/A	
258	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W3	Partially Inaccessible				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	150	4	N/A	N/A	N/A	
259	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W1	Cracking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	150	4	N/A	N/A	N/A	
260	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	1250	32	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
261	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Floor	Chipping				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	1250	32	N/A	N/A	N/A	
262	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W1	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	750	19	N/A	N/A	N/A	
263	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W2	Cracking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	60	2	N/A	N/A	N/A	
264	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	W3	Cracking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	750	19	N/A	N/A	N/A	
265	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	Floor	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	800	20	N/A	N/A	N/A	
266	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W2	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
267	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W3	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	48	2	N/A	N/A	N/A	
268	2630	1	2	H29	Circulation (Hallway)	Hallway from Faculty Lounge to IMC/Library	W4	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/19/19	8/22/19	8/22/19	600	15	N/A	N/A	N/A	
269	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W1	Holes				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
270	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W2	Cracking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
271	2630	1	2	S23	Stairs	Stairwell next to Classroom 223	W3	Cracking				7/24/19	7/25/19	7/25/19	7/25/19	8/15/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
272	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Ceiling	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
273	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	Floor	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
274	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W1	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
275	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W2	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
276	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W3	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
277	2630	1	2	S24	Stairs	Fire Tower Stairs next to Maintenance Storage Room	W4	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
278	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Ceiling	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
279	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Floor	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
280	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W1	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
281	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W2	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
282	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W3	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	90	3	N/A	N/A	N/A	
283	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W4	Inaccessible				7/17/19	7/20/19	7/20/19	8/9/19	9/4/19	N/A	8/23/19	138	4	N/A	N/A	N/A	
284	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	Ceiling	Cracking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	372	10	N/A	N/A	N/A	
285	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W1	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
286	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W2	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
287	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W3	Partially Inaccessible				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
288	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W4	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
289	2630	1	2	S27	Stairs	Fire Tower Stairwell across from IMC/Library	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	9/4/19	N/A	8/30/19	240	6	N/A	N/A	N/A	
290	2630	1	1	101	Primary	Classroom 101	Floor	Chipping				7/2/19	7/8/19	7/8/19	7/9/19	7/24/19	8/2/19	7/30/19	754	19	N/A	N/A	N/A	
291	2630	1	1	101	Primary	Classroom 101	W1	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/24/19	8/2/19	7/30/19	174	5	N/A	N/A	N/A	
292	2630	1	1	101	Primary	Classroom 101	W2	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/24/19	8/2/19	7/30/19	156	4	N/A	N/A	N/A	
293	2630	1	1	101	Primary	Classroom 101	W3	Chipping				7/2/19	7/8/19	7/8/19	7/9/19	7/24/19	8/2/19	7/30/19	174	5	N/A	N/A	N/A	
294	2630	1	1	101	Primary	Classroom 101	W4	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/24/19	8/2/19	7/30/19	156	4	N/A	N/A	N/A	
295	2630	1	1	102	Primary	Classroom 102	Floor	Chipping				7/31/19	8/2/19	8/2/19	8/2/19	8/9/19	8/14/19	8/12/19	720	18	0	N/A	N/A	Tested 1 color / 1 FAAS on w1, 1 color on w2 on 8/8/19. Passed with < 10 on 8/9/19

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
296	2630	1	1	102	Primary	Classroom 102	W1	Flaking				7/31/19	8/2/19	8/2/19	8/2/19	8/9/19	8/14/19	8/12/19	180	5	1	yes	< 10 µg/ft²	
297	2630	1	1	102	Primary	Classroom 102	W2	Flaking				7/31/19	8/2/19	8/2/19	8/2/19	8/9/19	8/14/19	8/12/19	144	4	1	no	N/A	
298	2630	1	1	102	Primary	Classroom 102	W3	Flaking				7/31/19	8/2/19	8/2/19	8/2/19	8/9/19	8/14/19	8/12/19	180	5	0	N/A	N/A	
299	2630	1	1	102	Primary	Classroom 102	W4	Chipping				7/31/19	8/2/19	8/2/19	8/2/19	8/9/19	8/14/19	8/12/19	144	4	0	N/A	N/A	
300	2630	1	1	103	Primary	Classroom 103	Floor	Chipping				7/10/19	7/11/19	7/11/19	7/15/19	7/24/19	8/2/19	7/30/19	750	19	N/A	N/A	N/A	
301	2630	1	1	103	Primary	Classroom 103	W2	Flaking				7/10/19	7/11/19	7/11/19	7/15/19	7/24/19	8/2/19	7/30/19	150	4	N/A	N/A	N/A	Corkboard on wall has 2 preexisting holes, about 4 inches in diameter.
302	2630	1	1	103	Primary	Classroom 103	W3	Flaking				7/10/19	7/11/19	7/11/19	7/15/19	7/24/19	8/2/19	7/30/19	180	5	N/A	N/A	N/A	
303	2630	1	1	103	Primary	Classroom 103	W4	Flaking				7/10/19	7/11/19	7/11/19	7/15/19	7/24/19	8/2/19	7/30/19	150	4	N/A	N/A	N/A	
304	2630	1	1	104	Administrative Office	Nurse's Office	Ceiling	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/30/19	8/2/19	7/29/19	648	17	0	N/A	N/A	1 color / 1 FAAS on W2, 1 color on W4, passed. Will take FAAS to lab today 7/24/19. Failed with 29, 7/25/19. 1 color / 1 FAAS on W2, 1 color W3, will take FAAS to lab today 7/27/19. Passed FAAS with <10, 7/30/19.
305	2630	1	1	104	Administrative Office	Nurse's Office	W1	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/30/19	8/2/19	7/29/19	144	4	0	N/A	N/A	
306	2630	1	1	104	Administrative Office	Nurse's Office	W2	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/30/19	8/2/19	7/29/19	162	4	2	yes	< 10 µg/ft²	
307	2630	1	1	104	Administrative Office	Nurse's Office	W3	Flaking				7/2/19	7/8/19	7/8/19	7/9/19	7/30/19	8/2/19	7/29/19	144	4	1	no	N/A	
308	2630	1	1	104	Administrative Office	Nurse's Office	W4	Partially Inaccessible				7/2/19	7/8/19	7/8/19	7/9/19	7/30/19	8/2/19	7/29/19	162	4	1	no	N/A	
309	2630	1	1	105	Primary	Classroom 105	Floor	Chipping				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	768	20	0	N/A	N/A	Tested, 1 color / 1 FAAS on w2 carpet, 1 color on w4, 1 color in bathroom on 8/15/19. Passed with < 10 on 8/16/19.
310	2630	1	1	105	Primary	Classroom 105	W1	Partially Inaccessible				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	192	5	0	N/A	N/A	
311	2630	1	1	105	Primary	Classroom 105	W2	Cracking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	144	4	1	yes	< 10 µg/ft²	
312	2630	1	1	105	Primary	Classroom 105	W3	Flaking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	192	5	0	N/A	N/A	
313	2630	1	1	105	Primary	Classroom 105	W4	Chipping				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	144	4	1	no	N/A	
314	2630	1	1	106	Primary	Classroom 106	Ceiling	Flaking				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	806	21	0	N/A	N/A	1 colorimetric / FAAS on W2, 1 color on W3. Will take FAAS to lab 7/20/19. Passed FAAS 7/23/19.
315	2630	1	1	106	Primary	Classroom 106	Floor	Chipping				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	806	21	0	N/A	N/A	
316	2630	1	1	106	Primary	Classroom 106	W1	Flaking				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	186	5	0	N/A	N/A	Leak which made plaster bubble up on W1. Leak is likley from ventilation shaft that goes up to 2nd or 3rd floor. Bubbling is on both sides of the wall. Noticed in the morning of 7/23/19.
317	2630	1	1	106	Primary	Classroom 106	W2	Cracking				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	156	4	1	yes	< 10 µg/ft²	
318	2630	1	1	106	Primary	Classroom 106	W3	Flaking				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	186	5	1	no	N/A	
319	2630	1	1	106	Primary	Classroom 106	W4	Chipping				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	156	4	0	N/A	N/A	
320	2630	1	1	107	Primary	Classroom 107	W1	Flaking				7/10/19	7/11/19	7/11/19	7/12/19	7/20/19	7/31/19	7/29/19	192	5	N/A	N/A	N/A	
321	2630	1	1	107	Primary	Classroom 107	W2	Flaking				7/10/19	7/11/19	7/11/19	7/12/19	7/20/19	7/31/19	7/29/19	156	4	N/A	N/A	N/A	
322	2630	1	1	107	Primary	Classroom 107	W3	Flaking				7/10/19	7/11/19	7/11/19	7/12/19	7/20/19	7/31/19	7/29/19	172	5	N/A	N/A	N/A	
323	2630	1	1	107	Primary	Classroom 107	W4	Cracking				7/10/19	7/11/19	7/11/19	7/12/19	7/20/19	7/31/19	7/29/19	156	4	N/A	N/A	N/A	
324	2630	1	1	108	Primary	Classroom 108	Floor	Chipping				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	832	21	0	N/A	N/A	tested, 1 color / 1 faas on corner w2 w3, 1 color on w1, and samples dropped off at office, 8/8/19. Lab marked received at 9 AM 8/12/19. Passed with < 10 on 8/13/19.
325	2630	1	1	108	Primary	Classroom 108	W1	Flaking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	192	5	1	no	N/A	
326	2630	1	1	108	Primary	Classroom 108	W2	Flaking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	152	4	1	yes	< 10 µg/ft²	
327	2630	1	1	108	Primary	Classroom 108	W3	Flaking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	192	5	0	N/A	N/A	
328	2630	1	1	108	Primary	Classroom 108	W4	Flaking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	152	4	0	N/A	N/A	
329	2630	1	1	109	Primary	Room 109 Head Start Program	Ceiling	Flaking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	768	20	0	N/A	N/A	1 color / FAAS on W2, 1 color in closet, 1 color on W3, will take FAAS to lab 7/25/19. passed with < 10 7/27/19.
330	2630	1	1	109	Primary	Room 109 Head Start Program	Floor	Chipping				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	768	20	0	N/A	N/A	
331	2630	1	1	109	Primary	Room 109 Head Start Program	W1	Cracking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	192	5	0	N/A	N/A	
332	2630	1	1	109	Primary	Room 109 Head Start Program	W2	Partially Inaccessible				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	144	4	1	yes	< 10 µg/ft²	
333	2630	1	1	109	Primary	Room 109 Head Start Program	W3	Flaking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	192	5	1	no	N/A	
334	2630	1	1	109	Primary	Room 109 Head Start Program	W4	Flaking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	144	4	0	N/A	N/A	
335	2630	1	1	110	Administrative Office	Principal's Office	W1	Partially Inaccessible				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	84	3	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
336	2630	1	1	110	Administrative Office	Principal's Office	W2	Flaking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	138	4	N/A	N/A	N/A	
337	2630	1	1	110	Administrative Office	Principal's Office	W3	Flaking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	84	3	N/A	N/A	N/A	
338	2630	1	1	110	Administrative Office	Principal's Office	W4	Partially Inaccessible				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	138	4	N/A	N/A	N/A	
339	2630	1	1	111	Administrative Office	Main Office	W1	Cracking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	144	4	N/A	N/A	N/A	
340	2630	1	1	111	Administrative Office	Main Office	W2	Cracking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	150	4	N/A	N/A	N/A	
341	2630	1	1	111	Administrative Office	Main Office	W3	Flaking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	144	4	N/A	N/A	N/A	
342	2630	1	1	111	Administrative Office	Main Office	W4	Flaking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	150	4	N/A	N/A	N/A	
343	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Flaking				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	2160	54	0	N/A	N/A	Left 2/3 partition of gym (includes W2) tested with 1 color / 1 FAAS on w3, 2 color on w2, 2 color on w3, 1 color in center, will take FAAS sample to lab today, 7/29/19. Passed with < 10 on 7/30/19. 1/3 partition cleaned and tested 1 color / 1 FAAS w3, 1 color w4 on 8/31/19. 1/3 partition FAAS passed with < 10 on 9/3/19.
344	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	Floor	Chipping				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	2160	54	0	N/A	N/A	
345	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W1	Flaking				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	540	14	0	N/A	N/A	
346	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W2	Flaking				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	144	4	2	no	N/A	
347	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W3	Flaking				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	540	14	4	yes	< 10 µg/ft²	
348	2630	1	1	112	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking				7/18/19	7/20/19	7/20/19	7/22/19	9/3/19	9/3/19	8/26/19	144	4	1	no	N/A	
349	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Ceiling	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	128	4	N/A	N/A	N/A	
350	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	Floor	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	128	4	N/A	N/A	N/A	
351	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W1	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	48	2	N/A	N/A	N/A	
352	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W2	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	96	3	N/A	N/A	N/A	
353	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W3	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	48	2	N/A	N/A	N/A	
354	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W4	Inaccessible				8/5/19	8/6/19	8/6/19	8/6/19	8/16/19	8/23/19	8/22/19	96	3	N/A	N/A	N/A	
355	2630	1	1	114	Primary	Room 114 Head Start Program	W1	Flaking				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	192	5	0	N/A	N/A	Tested, 1 color / 1 FAAS w2, 1 color w4, 1 color bathroom, and samples dropped off at office on 8/8/19. Passed with <10 on 9/13/19.
356	2630	1	1	114	Primary	Room 114 Head Start Program	W2	Partially Inaccessible				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	144	4	1	yes	< 10 µg/ft²	
357	2630	1	1	114	Primary	Room 114 Head Start Program	W3	Flaking				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	192	5	0	N/A	N/A	
358	2630	1	1	114	Primary	Room 114 Head Start Program	W4	Flaking				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	144	4	1	no	N/A	
359	2630	1	1	101A	Storage	Storage Room next to Classroom 101	Ceiling	Flaking				7/2/19	7/8/19	7/8/19	7/10/19	7/29/19	8/12/19	7/30/19	120	3	N/A	N/A	N/A	
360	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W1	Partially Inaccessible				7/2/19	7/8/19	7/8/19	7/10/19	7/29/19	8/12/19	7/30/19	48	2	N/A	N/A	N/A	
361	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W3	Flaking				7/2/19	7/8/19	7/8/19	7/10/19	7/29/19	8/12/19	7/30/19	48	2	N/A	N/A	N/A	
362	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	Ceiling	Efflorescence				7/25/19	7/26/19	7/26/19	7/27/19	8/7/19	8/12/19	8/8/19	325	9	N/A	N/A	N/A	
363	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W1	Flaking				7/25/19	7/26/19	7/26/19	7/27/19	8/7/19	8/12/19	8/8/19	78	2	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
364	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W2	Flaking				7/25/19	7/26/19	7/26/19	7/27/19	8/7/19	8/12/19	8/8/19	150	4	N/A	N/A	N/A	
365	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W3	Flaking				7/25/19	7/26/19	7/26/19	7/27/19	8/7/19	8/12/19	8/8/19	78	2	N/A	N/A	N/A	
366	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W4	Efflorescence				7/25/19	7/26/19	7/26/19	7/27/19	8/7/19	8/12/19	8/8/19	150	4	N/A	N/A	N/A	
367	2630	1	1	104B	Restrooms, Staff - Male	Men's Restroom in the Maintenance Staff Lounge	W2	Flaking				7/25/19	7/26/19	7/26/19	7/29/19	8/7/19	8/12/19	8/8/19	25	1	N/A	N/A	N/A	
368	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Ceiling	Cracking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	45	2	1	no	N/A	
369	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W1	Flaking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	45	2	0	N/A	N/A	
370	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	30	1	0	N/A	N/A	
371	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W3	Flaking				8/9/19	8/10/19	8/10/19	8/13/19	8/16/19	8/20/19	8/19/19	45	2	0	N/A	N/A	
372	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W1	Cracking				8/1/19	8/2/19	8/2/19	8/2/19	8/7/19	8/12/19	8/8/19	75	2	0	N/A	N/A	
373	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W3	Flaking				8/1/19	8/2/19	8/2/19	8/2/19	8/7/19	8/12/19	8/8/19	75	2	0	N/A	N/A	
374	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W1	Cracking				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	100	3	1	no	N/A	1 colorimetric 7/20/19.
375	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W2	Partially Inaccessible				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	30	1	0	N/A	N/A	
376	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W3	Partially Inaccessible				6/19/19	6/20/19	6/20/19	6/24/19	7/23/19	7/31/19	7/29/19	100	3	0	N/A	N/A	
377	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W1	Partially Inaccessible				7/10/19	7/11/19	7/11/19	7/12/19	7/23/19	7/31/19	7/29/19	100	3	N/A	N/A	N/A	
378	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W2	Partially Inaccessible				7/10/19	7/11/19	7/11/19	7/12/19	7/23/19	7/31/19	7/29/19	30	1	N/A	N/A	N/A	
379	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W3	Cracking				7/10/19	7/11/19	7/11/19	7/12/19	7/23/19	7/31/19	7/29/19	100	3	N/A	N/A	N/A	
380	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W4	Cracking				7/10/19	7/11/19	7/11/19	7/12/19	7/23/19	7/31/19	7/29/19	30	1	N/A	N/A	N/A	
381	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W1	Cracking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	24	1	0	N/A	N/A	
382	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W2	Partially Inaccessible				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	48	2	0	N/A	N/A	
383	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W4	Partially Inaccessible				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	48	2	0	N/A	N/A	
384	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	48	2	0	N/A	N/A	
385	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Cracking				N/A	7/31/19	7/31/19	7/31/19	8/13/19	8/14/19	8/12/19	42	2	0	N/A	N/A	
386	2630	1	1	109A	Storage	Room 109 Storage Room	Ceiling	Flaking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	75	2	1	no	N/A	Tested with 1 color 7/25/19
387	2630	1	1	109A	Storage	Room 109 Storage Room	W1	Flaking				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	75	2	0	N/A	N/A	
388	2630	1	1	109A	Storage	Room 109 Storage Room	W2	Partially Inaccessible				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	30	1	0	N/A	N/A	
389	2630	1	1	109A	Storage	Room 109 Storage Room	W3	Partially Inaccessible				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	75	2	0	N/A	N/A	
390	2630	1	1	109A	Storage	Room 109 Storage Room	W4	Partially Inaccessible				7/9/19	7/10/19	7/10/19	7/15/19	7/27/19	7/30/19	7/27/19	30	1	0	N/A	N/A	
391	2630	1	1	110T	Restrooms, Staff - Female	Principal's Office Restroom	W1	Flaking				7/27/19	7/30/19	7/30/19	7/30/19	8/1/19	8/8/19	8/5/19	25	1	N/A	N/A	N/A	
392	2630	1	1	114A	Storage	Room 114 Storage Closet	W1	Partially Inaccessible				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	35	1	1	no	N/A	
393	2630	1	1	114A	Storage	Room 114 Storage Closet	W2	Cracking				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	30	1	0	N/A	N/A	
394	2630	1	1	114A	Storage	Room 114 Storage Closet	W3	Cracking				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	35	1	0	N/A	N/A	
395	2630	1	1	114A	Storage	Room 114 Storage Closet	W4	Partially Inaccessible				7/29/19	7/31/19	7/31/19	7/31/19	8/13/19	8/16/19	8/12/19	30	1	0	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
396	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	Ceiling	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/21/19	8/24/19	8/23/19	800	20	N/A	N/A	N/A	
397	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W2	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/21/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
398	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W3	Cracking				8/15/19	8/16/19	8/16/19	8/17/19	8/21/19	8/24/19	8/23/19	48	2	N/A	N/A	N/A	
399	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W4	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/21/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
400	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W2	Cracking				7/31/19	8/1/19	8/1/19	8/1/19	8/5/19	8/10/19	8/6/19	286	7	N/A	N/A	N/A	
401	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W3	Flaking				7/31/19	8/1/19	8/1/19	8/1/19	8/5/19	8/10/19	8/6/19	126	4	N/A	N/A	N/A	
402	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Ceiling	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/20/19	8/24/19	8/23/19	1250	32	N/A	N/A	N/A	
403	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Floor	Chipping				8/15/19	8/16/19	8/16/19	8/17/19	8/20/19	8/24/19	8/23/19	1250	32	N/A	N/A	N/A	
404	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W1	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/20/19	8/24/19	8/23/19	750	19	N/A	N/A	N/A	
405	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W3	Flaking				8/15/19	8/16/19	8/16/19	8/17/19	8/20/19	8/24/19	8/23/19	750	19	N/A	N/A	N/A	
406	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W2	Flaking				8/15/19	8/16/19	8/16/19	8/16/19	8/20/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
407	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W3	Cracking				8/15/19	8/16/19	8/16/19	8/16/19	8/20/19	8/24/19	8/23/19	48	2	N/A	N/A	N/A	
408	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W4	Flaking				8/15/19	8/16/19	8/16/19	8/16/19	8/20/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
409	2630	1	1	S11	Stairs	Fire Tower Stairwell near end of Gymnasium	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	8/31/19	N/A	8/30/19	240	6	N/A	N/A	N/A	
410	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	Floor	Chipping				7/24/19	7/25/19	7/25/19	7/25/19	7/31/19	8/10/19	8/5/19	372	10	N/A	N/A	N/A	
411	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W3	Partially Inaccessible				7/24/19	7/25/19	7/25/19	7/25/19	7/31/19	8/10/19	8/5/19	72	2	N/A	N/A	N/A	
412	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W4	Flaking				7/24/19	7/25/19	7/25/19	7/25/19	7/31/19	8/10/19	8/5/19	186	5	N/A	N/A	N/A	
413	2630	1	1	S15	Stairs	Fire Tower Stairwell across from Classroom 106	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	9/4/19	N/A	8/23/19	345	9	N/A	N/A	N/A	
414	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W2	Cracking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
415	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W3	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
416	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W4	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
417	2630	1	1	S17	Stairs	Fire Tower Stairwell across from Classroom 101	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	9/4/19	N/A	8/30/19	240	6	N/A	N/A	N/A	
418	2630	1	0	001	Art - Elementary	Art Room	Ceiling	Cracking				7/10/19	7/11/19	7/11/19	7/18/19	8/15/19	8/20/19	8/15/19	1161	29	0	N/A	N/A	Tested 1 color / 1 FAAS on w3, 1 color on w2, 1 color on w4, 8/13/19. Passed with <10 on 8/15/19.
419	2630	1	0	001	Art - Elementary	Art Room	W1	Flaking				7/10/19	7/11/19	7/11/19	7/18/19	8/15/19	8/20/19	8/15/19	258	7	0	N/A	N/A	
420	2630	1	0	001	Art - Elementary	Art Room	W2	Chipping				7/10/19	7/11/19	7/11/19	7/18/19	8/15/19	8/20/19	8/15/19	162	4	1	yes	< 10 µg/ft²	
421	2630	1	0	001	Art - Elementary	Art Room	W3	Flaking				7/10/19	7/11/19	7/11/19	7/18/19	8/15/19	8/20/19	8/15/19	258	7	1	no	N/A	
422	2630	1	0	001	Art - Elementary	Art Room	W4	Flaking				7/10/19	7/11/19	7/11/19	7/18/19	8/15/19	8/20/19	8/15/19	162	4	1	no	N/A	
423	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Ceiling	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	312	8	N/A	N/A	N/A	
424	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Floor	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	312	8	N/A	N/A	N/A	
425	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W1	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	72	2	N/A	N/A	N/A	
426	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W2	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	156	4	N/A	N/A	N/A	
427	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W3	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	72	2	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
428	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W4	Inaccessible				7/18/19	7/22/19	7/22/19	7/23/19	8/5/19	8/14/19	8/13/19	156	4	N/A	N/A	N/A	
429	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W2	Flaking				7/18/19	7/22/19	7/22/19	7/26/19	8/14/19	8/15/19	8/15/19	102	3	N/A	N/A	N/A	
430	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W3	Flaking				7/18/19	7/22/19	7/22/19	7/26/19	8/14/19	8/15/19	8/15/19	78	2	N/A	N/A	N/A	
431	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W4	Partially Inaccessible				7/18/19	7/22/19	7/22/19	7/26/19	8/14/19	8/15/19	8/15/19	102	3	N/A	N/A	N/A	
432	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Ceiling	Flaking				8/13/19	8/16/19	8/16/19	8/16/19	8/23/19	9/3/19	8/31/19	1050	27	4	yes	13 µg/ft^2	Tested 1 color on w1, 1 color on w2 failed, needs reclean 8/22/19. Tested 1 color / 1 FAAS near w1 under ceiling, 1 color on w2, 1 color in center under ceiling 8/22/19. Passed with 10 on 8/23/29. Recleaned and tested with 1 color / 1 FAAS on w1, 1 color on w2, 1 color on w3, on 8/31/19. Passed with 13 micrograms/sf on 9/3/19.
433	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Floor	Flaking				8/13/19	8/16/19	8/16/19	8/16/19	8/23/19	9/3/19	8/31/19	1050	27	0	N/A	N/A	
434	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W2	Flaking				8/13/19	8/16/19	8/16/19	8/16/19	8/23/19	9/3/19	8/31/19	210	6	3	no	N/A	
435	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W3	Flaking				8/13/19	8/16/19	8/16/19	8/16/19	8/23/19	9/3/19	8/31/19	180	5	1	no	N/A	
436	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W4	Flaking				8/13/19	8/16/19	8/16/19	8/16/19	8/23/19	9/3/19	8/31/19	210	6	0	N/A	N/A	
437	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	Ceiling	Cracking				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	1025	26	1	no	N/A	Tested 1 color / 1 FAAS w2, 1 color w3, 1 color ceiling on 8/13/19. Failed with 55, will reclean and retest 8/15/19. Tested 1 color / 1 FAAS w2, 1 color w3, 1 color w4 on 8/21/19. Passed with 14 on 8/23/19.
438	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W2	Chipping				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	150	4	2	yes	14 µg/ft^2	
439	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W3	Flaking				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	246	7	2	no	N/A	
440	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W4	Cracking				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	150	4	1	no	N/A	
441	2630	1	0	015	Kitchen	Kitchen	W2	Partially Inaccessible				8/14/19	8/15/19	8/15/19	8/15/19	8/21/19	8/24/19	8/23/19	120	3	1	yes	< 10 µg/ft^2	Tested 1 color / 1 FAAS in center of room on 8/20/19. FAAS pass with < 10 on 8/21/19.
442	2630	1	0	015	Kitchen	Kitchen	W3	Partially Inaccessible				8/14/19	8/15/19	8/15/19	8/15/19	8/21/19	8/24/19	8/23/19	66	2	0	N/A	N/A	
443	2630	1	0	015	Kitchen	Kitchen	W4	Cracking				8/14/19	8/15/19	8/15/19	8/15/19	8/21/19	8/24/19	8/23/19	120	3	0	N/A	N/A	
444	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	Ceiling	Chipping				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	1075	27	2	no	N/A	Tested 1 color / 1 FAAS ceiling, 1 color w3, 1 color w4 on 8/13/19. Failed with 28, will reclean and retest 8/15/19. Tested, 1 color / 1 FAAS on w4, 1 color w3, 1 color ceiling, 8/21/19. Passed with 10 on 8/23/19.
445	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W1	Cracking				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	258	7	0	N/A	N/A	
446	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W3	Flaking				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	258	7	2	no	N/A	
447	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W4	Partially Inaccessible				N/A	N/A	N/A	6/27/19	8/23/19	8/24/19	8/16/19	150	4	2	yes	10 µg/ft^2	
448	2630	1	0	021	Resource Room	Room B-10 After School Program	W1	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	114	3	N/A	N/A	N/A	
449	2630	1	0	021	Resource Room	Room B-10 After School Program	W2	Flaking				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	162	5	N/A	N/A	N/A	
450	2630	1	0	021	Resource Room	Room B-10 After School Program	W3	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	114	3	N/A	N/A	N/A	
451	2630	1	0	021	Resource Room	Room B-10 After School Program	W4	Partially Inaccessible				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	162	5	N/A	N/A	N/A	
452	2630	1	0	001A	Storage	Storage Closet next to Art Room	Ceiling	Flaking				8/16/19	8/19/19	8/19/19	8/19/19	8/20/19	8/20/19	8/20/19	128	4	N/A	N/A	N/A	
453	2630	1	0	001A	Storage	Storage Closet next to Art Room	W1	Flaking				8/16/19	8/19/19	8/19/19	8/19/19	8/20/19	8/20/19	8/20/19	48	2	N/A	N/A	N/A	
454	2630	1	0	001A	Storage	Storage Closet next to Art Room	W2	Flaking				8/16/19	8/19/19	8/19/19	8/19/19	8/20/19	8/20/19	8/20/19	96	3	N/A	N/A	N/A	
455	2630	1	0	001A	Storage	Storage Closet next to Art Room	W3	Flaking				8/16/19	8/19/19	8/19/19	8/19/19	8/20/19	8/20/19	8/20/19	48	2	N/A	N/A	N/A	
456	2630	1	0	001A	Storage	Storage Closet next to Art Room	W4	Partially Inaccessible				8/16/19	8/19/19	8/19/19	8/19/19	8/20/19	8/20/19	8/20/19	96	3	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
457	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Ceiling	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Moldy. Told Ryan Hutseell who inspected it. A team is going to come and remove the mold and moldy furniture. Mold has not been removed as of 9/5/19.
458	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Floor	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Area removed from scope of work
459	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W1	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
460	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W2	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
461	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W3	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
462	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W4	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
463	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W1	Flaking				8/15/19	8/17/19	8/17/19	8/19/19	8/19/19	8/21/19	8/20/19	48	2	N/A	N/A	N/A	
464	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W2	Flaking				8/15/19	8/17/19	8/17/19	8/19/19	8/19/19	8/21/19	8/20/19	90	3	N/A	N/A	N/A	
465	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W3	Flaking				8/15/19	8/17/19	8/17/19	8/19/19	8/19/19	8/21/19	8/20/19	48	2	N/A	N/A	N/A	
466	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W4	Flaking				8/15/19	8/17/19	8/17/19	8/19/19	8/19/19	8/21/19	8/20/19	90	3	N/A	N/A	N/A	
467	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W1	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	48	2	N/A	N/A	N/A	
468	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W3	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	48	2	N/A	N/A	N/A	
469	2630	1	0	021C	Storage	Room B-10 Storage Closet	Ceiling	Holes				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	24	1	N/A	N/A	N/A	
470	2630	1	0	021C	Storage	Room B-10 Storage Closet	W2	Partially Inaccessible				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	24	1	N/A	N/A	N/A	
471	2630	1	0	021C	Storage	Room B-10 Storage Closet	W3	Flaking				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	24	1	N/A	N/A	N/A	
472	2630	1	0	021C	Storage	Room B-10 Storage Closet	W4	Flaking				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/16/19	8/13/19	24	1	N/A	N/A	N/A	
473	2630	1	0	021D	Primary	Classroom B-9	Ceiling	Flaking				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	756	19	N/A	N/A	N/A	
474	2630	1	0	021D	Primary	Classroom B-9	Floor	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	756	19	N/A	N/A	N/A	
475	2630	1	0	021D	Primary	Classroom B-9	W1	Partially Inaccessible				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	168	5	N/A	N/A	N/A	
476	2630	1	0	021D	Primary	Classroom B-9	W2	Flaking				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	162	5	N/A	N/A	N/A	
477	2630	1	0	021D	Primary	Classroom B-9	W3	Chipping				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	168	5	N/A	N/A	N/A	
478	2630	1	0	021D	Primary	Classroom B-9	W4	Partially Inaccessible				7/16/19	7/17/19	7/17/19	7/17/19	8/12/19	8/17/19	8/13/19	162	5	N/A	N/A	N/A	
479	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Ceiling	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Moldy. Told Ryan Hutseell who inspected it. A team is going to come and remove the mold and moldy furniture. Mold has not been removed as of 9/5/19.
480	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Floor	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Area removed from scope of work
481	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W1	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
482	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W2	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
483	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W3	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
484	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W4	Inaccessible				N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
485	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	Ceiling	Partially Inaccessible				N/A	N/A	N/A	8/21/19	8/22/19	8/24/19	8/23/19	800	20	N/A	N/A	N/A	

Sharswood - Oversight

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Date Mold DDC Issued	Date Asbestos DDC Issued	Miscellaneous Items (e.g. missing/stained ceiling tiles, steam leaks, missing lens covers, buckled floors etc.)	Date Notified Tom Sharer (FAC)	Pre-Cleaning Completed (date)	Contents Moved (date)	Work Area Prepped (date)	Surfaces Stabilized (date)	Contents Back in Place (date)	Final Inspection Approval and Photos (date)	Square Footage of Work Area	Number of Required RRP Wipes	Number of Colorimetric Wipes Used to Pass	Final Colorimetric Wipe Submitted for AAS Analysis (yes/no)	AAS Analysis Results	Other Notes or Comments
486	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W2	Flaking				N/A	N/A	N/A	8/21/19	8/22/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
487	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W3	Flaking				N/A	N/A	N/A	8/21/19	8/22/19	8/24/19	8/23/19	48	2	N/A	N/A	N/A	
488	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W4	Flaking				N/A	N/A	N/A	8/21/19	8/22/19	8/24/19	8/23/19	600	15	N/A	N/A	N/A	
489	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Ceiling	Cracking				N/A	N/A	N/A	8/20/19	8/22/19	8/24/19	8/23/19	464	12	N/A	N/A	N/A	
490	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Floor	Chipping				N/A	N/A	N/A	8/20/19	8/22/19	8/24/19	8/23/19	464	12	N/A	N/A	N/A	
491	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W1	Flaking				N/A	N/A	N/A	8/20/19	8/22/19	8/24/19	8/23/19	174	5	N/A	N/A	N/A	
492	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W3	Flaking				N/A	N/A	N/A	8/20/19	8/22/19	8/24/19	8/23/19	174	5	N/A	N/A	N/A	
493	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W4	Cracking				N/A	N/A	N/A	8/20/19	8/22/19	8/24/19	8/23/19	96	3	N/A	N/A	N/A	
494	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Ceiling	Partially Inaccessible				N/A	N/A	N/A	8/21/19	8/27/19	8/28/19	8/27/19	800	20	N/A	N/A	N/A	
495	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Floor	Flaking				N/A	N/A	N/A	8/21/19	8/27/19	8/28/19	8/27/19	800	20	N/A	N/A	N/A	
496	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W2	Flaking				N/A	N/A	N/A	8/21/19	8/27/19	8/28/19	8/27/19	600	15	N/A	N/A	N/A	
497	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W3	Flaking				N/A	N/A	N/A	8/21/19	8/27/19	8/28/19	8/27/19	48	2	N/A	N/A	N/A	
498	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W4	Flaking				N/A	N/A	N/A	8/21/19	8/27/19	8/28/19	8/27/19	600	15	N/A	N/A	N/A	
499	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Ceiling	Flaking				N/A	N/A	N/A	8/21/19	8/26/19	8/28/19	8/27/19	782	20	N/A	N/A	N/A	
500	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Floor	Flaking				N/A	N/A	N/A	8/21/19	8/26/19	8/28/19	8/27/19	782	20	N/A	N/A	N/A	
501	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W3	Flaking				N/A	N/A	N/A	8/21/19	8/26/19	8/28/19	8/27/19	276	7	N/A	N/A	N/A	
502	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W4	Flaking				N/A	N/A	N/A	8/21/19	8/26/19	8/28/19	8/27/19	102	3	N/A	N/A	N/A	
503	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W1	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	72	2	N/A	N/A	N/A	
504	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W2	Flaking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
505	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W4	Cracking				7/19/19	7/30/19	7/30/19	8/2/19	8/14/19	N/A	8/23/19	186	5	N/A	N/A	N/A	
506	2630	1	0	S07	Stairs	Fire Tower Stairwell near Art Room	Ceiling	Flaking				8/9/19	8/12/19	8/12/19	8/12/19	9/4/19	N/A	8/30/19	240	6	N/A	N/A	N/A	

Appendix D
Sample Results Table

Analytical Dust Wipe Results

On Site Room Name	Sample Date				AAS Analysis Results			
3 rd Floor Boys' Restroom	06/20/2019				17 µg/ft²			
3 rd Floor Girls' Restroom	06/20/2019	06/26/2019	07/01/2019	07/08/2019	46 µg/ft²	66 µg/ft²	28 µg/ft²	<10 µg/ft²
Room 224	06/27/2019				<10 µg/ft²			
IMC	07/03/2019				<10 µg/ft²			
Computer Lab	07/12/2019				<10 µg/ft²			
Auditorium	07/12/2019				<10 µg/ft²			
Room 224	07/15/2019				<10 µg/ft²			
Room 226	07/16/2019				<10 µg/ft²			
Room 223A	07/18/2019				<10 µg/ft²			
Room 106	07/20/2019				<10 µg/ft²			
Nurse's Office	07/24/2019		07/27/2019		29 µg/ft²		<10 µg/ft²	
Room 109	07/25/2019				<10 µg/ft²			
Gym	07/29/2019		08/31/2019		<10 µg/ft²		<10 µg/ft²	
Room 227	08/05/2019				46 µg/ft²			
Room 108	08/07/2019				<10 µg/ft²			
Room 114	08/07/2019				<10 µg/ft²			
Room 102	08/08/2019				<10 µg/ft²			
Room 227	08/08/2019				<10 µg/ft²			
Art Room 001	08/14/2019				<10 µg/ft²			
Girls' Cafeteria	08/14/2019		08/21/2019		55 µg/ft²		14 µg/ft²	
Boys' Cafeteria	08/14/2019		10 µg/ft²		28 µg/ft²		10 µg/ft²	
Room 105	08/15/2019				<10 µg/ft²			
Kitchen	08/20/2019				<10 µg/ft²			
Kindergarten Cafeteria	08/22/2019				<10 µg/ft²			

Analytical Dust Wipe Results

On Site Room Name	Sample Date		AAS Analysis Results	
Basement Boys' Restroom 004	08/27/2019		13 µg/ft ²	
Basement Boys' Restroom 018	08/28/2019	08/31/2019	31 µg/ft ²	11 µg/ft ²
Kindergarten Lunch Room	08/31/2019		13 µg/ft ²	

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906132

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Accounts Payable**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 06/20/19 4:00 PM
Collected: 6/20/2019

Project: 010-4467 / Paint & Plaster Stabilization Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201906132-0001	6/20/2019	6/21/2019	144 in ²	17 µg/ft ²
Site: Boys Bathroom, 337B, Back					
2	201906132-0002	6/20/2019	6/21/2019	144 in ²	<10 µg/ft ²
Site: Blank					
3	201906132-0003	6/20/2019	6/21/2019	144 in ²	46 µg/ft ²
Site: Girls Bathroom, 332A, Back					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/21/2019 16:18:04

201906132

Chain of Custody Transmittal

Paint & Plaster
Stabilization

Lead Wipe Samples

Project Name: Sharswood

Project No. 010 - 4467

Laboratory: EMSL

Analysis:	FAAS
-----------	------

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 8/20/19, 1:30 PM

Transmitted to Lab By: _____

Date/Time

Received in Lab By:

Date/Time 6-20-19

Samples Analyzed By: _____

Date/Time

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906388

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Andrew McMahon**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 06/27/19 9:00 AM
Collected: 6/26/2019

Project: **Paint & Plaster Stabilization / Sharswood / Project No. 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201906388-0001	6/26/2019	6/27/2019	144 in ²	66 µg/ft ²
Site: Girls Bathroom, 332A, W3					
2	201906388-0002	6/26/2019	6/27/2019	144 in ²	<10 µg/ft ²
Site: Blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory


*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/28/2019 13:50:50

Date/Time

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906441

CustomerID: SYNE50

CustomerPO: 010-4467

ProjectID:

Attn: **Accounts Payable**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 06/27/19 2:40 PM
Collected: 6/27/2019

Project: **Paint & plaster stabilization - Sharswood / 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201906441-0001	6/27/2019	6/27/2019	144 in ²	<10 µg/ft ²
Site: 224, wall 3					
2	201906441-0002	6/27/2019	6/27/2019	N/A	<10 µg/wipe
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 06/28/2019 15:19:01

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 6/27/19 1:50 PM

Date/Time _____

Date/Time 8/27/17 d 1 5 p

Date/Time _____

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906610

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Accounts Payable**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/01/19 5:10 PM
Collected: 7/1/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201906610-0001	7/1/2019	7/2/2019	144 in ²	28 µg/ft ²
Site: 332A W2 (girls bathroom)					
2	201906610-0002	7/1/2019	7/2/2019	144 in ²	<10 µg/ft ²
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/02/2019 15:00:34

201906610

Chain of Custody Transmittal

Paint & Plaster Stabilization; Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 7/1/19 1 PM


Date/Time _____

Date/Time 7/11/75/9

Date/Time _____

2R14

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201906713

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/05/19 9:00 AM
Collected: 7/3/2019

Project: **Sharswood - Paint & Plaster Stabilization / Project No. 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201906713-0001	7/3/2019	7/5/2019	144 in ²	<10 µg/ft ²
	Site: 216 (IMC) W4				
2	201906713-0002	7/3/2019	7/5/2019	144 in ²	<10 µg/ft ²
	Site: Blank				

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/05/2019 14:39:46

201906713

Chain of Custody Transmittal

Paint & Plaster Stabilization Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 7/3/19 10:30 AM

Date/Time _____

Date/Time 7/3/19 7:40

Date/Time _____

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201906795

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/08/19 5:50 PM
Collected: 7/8/2019

Project: Sharswood / Paint & Plaster Stabilization / Project No. 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201906795-0001	7/8/2019	7/9/2019	144 in ²	<10 µg/ft ²
Site: 332 A (Girls Bathroom) W3					
2	201906795-0002	7/8/2019	7/9/2019	144 in ²	<10 µg/ft ²
Site: Blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/09/2019 16:11:52



201906795

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Chain of Custody Transmittal

Paint & Plaster Stabilizations

Project Name: Sharswood

Project No. 010-4467

Laboratory: EMSL

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 7/8/19 7AM

Transmitted to Lab By: Ally M

Date/Time _____


Received in Lab By: CP WE

Date/Time 7/8/19 5:50p

Samples Analyzed By: _____

Date/Time _____ (1)

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907064

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/12/19 5:55 PM
Collected: 7/12/2019

Project: Sharswood / Paint & Plaster Stabilization / Project No. 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201907064-0001	7/12/2019	7/13/2019	144 in ²	<10 µg/ft ²
Site: 341 (Computer Lab) W2					
2	201907064-0002	7/12/2019	7/13/2019	144 in ²	<10 µg/ft ²
Site: Blank					
3	201907064-0003	7/12/2019	7/13/2019	144 in ²	<10 µg/ft ²
Site: Auditorium W3 (Middle)					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/13/2019 15:12:46

201907064

Chain of Custody Transmittal

Paint and Plaster, Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 7/12/19 8AM

Transmitted to Lab By: [Signature]

Date/Time 7-12-19

Received in Lab By: [Signature]

Date/Time 7/12/19 SSS

Samples Analyzed By: _____

Date/Time _____

32

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201907108

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/15/19 2:50 PM
Collected: 7/15/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
#1	201907108-0001	7/15/2019	7/16/2019	144 in ²	<10 µg/ft ²
	Site: 224 W2				
#2	201907108-0002	7/15/2019	7/16/2019	144 in ²	<10 µg/ft ²
	Site: Blank				

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10972, PA 69-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/16/2019 16:05:04

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Lead Wipe Samples

Paint & Plaster Stabilization: **Lead**

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 7/15/19 1:20 PM

Transmitted to Lab By: [Signature]

Date/Time _____

Received in Lab By: [Signature]

Date/Time 7/15/19 250n

Samples Analyzed By: _____

Date/Time	
------------------	--

2911

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907168

CustomerID: SYNE50

CustomerPO: 010-4467

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/16/19 2:45 PM
Collected: 7/16/2019

Project: **Paint Plaster Stabilization: Sharswood / 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201907168-0001	7/16/2019	7/17/2019	144 in ²	<10 µg/ft ²
Site: 226 W2					
2	201907168-0002	7/16/2019	7/17/2019	144 in ²	<10 µg/ft ²
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/17/2019 16:40:10

201907168

Chain of Custody Transmittal

Paint & Plaster Stabilization: **Lead Wipe Samples**

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED


Date/Time 7/16/19 8:30 AM

Date/Time _____

Date/Time 7/16/19 245r

Date/Time _____

2

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907302

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/18/19 3:25 PM
Collected: 7/18/2019

Project: **Paint & Plaster Stabilization / 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201907302-0001	7/18/2019	7/19/2019	144 in ²	<10 µg/ft ²
Site: 223A (222) W4					
2	201907302-0002	7/18/2019	7/19/2019	144 in ²	<10 µg/ft ²
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/19/2019 15:52:26

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Paint and Plasters ^{stabilization} **Lead Wipe Samples**

Date/Time _____

1
2

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201907409
CustomerID: SYNE50
CustomerPO:
ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/20/19 12:30 PM
Collected: 7/20/2019

Project: Sharswood / 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201907409-0001	7/20/2019	7/22/2019	144 in ²	<10 µg/ft ²
	Site: 106 W2				
2	201907409-0002	7/20/2019	7/22/2019	144 in ²	<10 µg/ft ²
	Site: blank				

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/22/2019 16:08:11

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Paint & Plaster Stabilization

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 7/20/19 10AM

Transmitted to Lab By: _____

Date/Time _____

Received in Lab By: W. H. I.

Date/Time 5/20/19 12:30

Samples Analyzed By: _____

Date/Time _____

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907639

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/24/19 3:35 PM
Collected: 7/24/2019

Project: Paint & Plaster Stabilization / Sharswood / 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201907639-0001	7/24/2019	7/25/2019	144 in ²	29 µg/ft ²
Site: Nurses office (104) W2					
2	201907639-0002	7/24/2019	7/25/2019	144 in ²	<10 µg/ft ²
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 69-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/25/2019 14:36:53

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Lead Wipe Samples

Paint & Plaster Stabilization

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 7/24/19 8:30 AM

Date/Time _____

Date/Time 7-24-19 3:55 a

Date/Time _____

②

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907716

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Synertech, Inc.**
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/25/19 5:20 PM
Collected: 7/25/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201907716-0001	7/25/2019	7/26/2019	144 in ²	<10 µg/ft ²
	Site: 109 W2				
2	201907716-0002	7/25/2019	7/26/2019	144 in ²	<10 µg/ft ²
	Site: Blank				

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/26/2019 15:56:03

201907716

Chain of Custody Transmittal

Paint & Plaster Stabilization: Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski^{gn}

Date/Time 7/25/19 3 PM

Transmitted to Lab By: _____

Date/Time

Received in Lab By: [Signature]

Date/Time 7/25/14

Samples Analyzed By: _____

Date/Time

284

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907792

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/27/19 1:55 PM
Collected: 7/27/2019

Project: Paint & Plaster Stabilization / Sharswood / 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201907792-0001	7/27/2019	7/29/2019	144 in ²	<10 µg/ft ²
Site: 104 W2 (nurses office)					
2	201907792-0002	7/27/2019	7/29/2019	144 in ²	<10 µg/ft ²
Site: blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe =µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/29/2019 15:16:56

201907792

Chain of Custody Transmittal

Paint & Plaster Stabilization **Lead Wipe Samples**

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other _____

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 7/27/19 7:45AM

Date/Time 7/27/19 1:55

Date/Time 7/27/19 1:55

Date/Time _____

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201907871

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 07/29/19 5:05 PM
Collected: 7/29/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
#1	201907871-0001	7/29/2019	7/30/2019	144 in ²	<10 µg/ft ²
Site: Gym (112) W3					
#2	201907871-0002	7/29/2019	7/30/2019	144 in ²	<10 µg/ft ²
Site: Blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 07/30/2019 15:07:30

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201908127

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Synertech, Inc.**
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/05/19 4:30 PM
Collected: 8/5/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201908127-0001	8/5/2019	8/6/2019	144 in ²	46 µg/ft ²
Site: 227 W3 Floor					
2	201908127-0002	8/5/2019	8/6/2019	144 in ²	<10 µg/ft ²
Site: Blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/06/2019 13:49:57



201908127

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Chain of Custody Transmittal

Lead Wipe Samples

Paint & Plaster Stabilization Lead Wip
Project Name: Sharswood

Project No. 010-4467

Laboratory: EMSL

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 8/5/19 1:30 PM

Transmitted to Lab By: Austin Gwiazdowski

Date/Time 8/5/19

Received in Lab By:

Date/Time 8-5-19

Samples Analyzed By:

Date/Time

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201908341

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/12/19 9:00 AM
Collected: 8/7/2019

Project: **Paint & Plaster Stabilization - Sharswood / 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201908341-0001	8/7/2019	8/12/2019	144 in ²	<10 µg/ft ²
Site: blank					
2	201908341-0002	8/7/2019	8/12/2019	144 in ²	<10 µg/ft ²
Site: W2 corner (floor) 108					
3	201908341-0003	8/7/2019	8/12/2019	144 in ²	<10 µg/ft ²
Site: W2 114 (floor)					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/13/2019 09:19:38

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Pain + Plaster Stabilization: Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 8/7/19 3 PM

Transmitted to Lab By: _____

Date/Time _____

Received in Lab By: A. Pottichen

Date/Time 8/12/19 9am

Samples Analyzed By: _____

Date/Time _____

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201908259

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/08/19 5:40 PM
Collected: 8/8/2019

Project: Sharswood - Paint & Plaster Stabilization / Project No. 010-4467

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201908259-0001	8/8/2019	8/9/2019	144 in ²	<10 µg/ft ²
Site: Blank					
2	201908259-0002	8/8/2019	8/9/2019	144 in ²	<10 µg/ft ²
Site: 102 - W1 Floor					
3	201908259-0003	8/8/2019	8/9/2019	144 in ²	<10 µg/ft ²
Site: 227 - W3 Floor					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. $\mu\text{g}/\text{ft}^2 = \mu\text{g}/\text{wipe} \times \text{area sampled in ft}^2$. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/09/2019 15:16:31

321

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201908474

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Synertech, Inc.**
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/13/19 4:50 PM
Collected: 8/13/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
#1	201908474-0001	8/13/2019	8/14/2019	144 in ²	<10 µg/ft ²
	Site: Blank				
#2	201908474-0002	8/13/2019	8/14/2019	144 in ²	<10 µg/ft ²
	Site: 001 W3 Floor (Art Room)				
#3	201908474-0003	8/13/2019	8/14/2019	144 in ²	55 µg/ft ²
	Site: 014 W2 Floor (Girls' Cafeteria)				
#4	201908474-0004	8/13/2019	8/14/2019	144 in ²	28 µg/ft ²
	Site: 016 Ceiling Floor (Boys' Cafeteria)				

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. µg/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845,01

Initial report from 08/14/2019 16:51:51

4814

6

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201908578

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/15/19 4:50 PM
Collected: 8/15/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
#1	201908578-0001	8/15/2019	8/16/2019	144 in ²	<10 µg/ft ²
Site: 105 W2 Carpet Floor					
#2	201908578-0002	8/15/2019	8/16/2019	144 in ²	<10 µg/ft ²
Site: Blank					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/16/2019 14:41:18

Date/Time: _____

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com> cinnaminsonleadlab@emsl.com

EMSL Order: 201908750

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/20/19 4:45 PM
Collected: 8/20/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

Client Sample Description	Lab ID	Collected	Analyzed	Area Sampled	Lead Concentration
1	201908750-0001	8/20/2019	8/21/2019	144 in ²	<10 µg/ft ²
Site: Blank					
2	201908750-0002	8/20/2019	8/21/2019	144 in ²	<10 µg/ft ²
Site: Kitchen (015) Floor W4					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10972, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/21/2019 16:14:31

201908750

Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

X ASTM/EPA APPROVED GHOST WIPES USED

Please mail copy to:
gwiazdowski.austin@gmail.com

Date/Time 8/20/19 11AM

Date/Time Authy 12:00

Date/Time 5/20/17 445

Date/Time _____

[illegible]

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201908865

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/22/19 5:15 PM
Collected: 8/21/2019

Project: **Paint & Plaster Stabilization: Sharswood / Project No. 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201908865-0001	8/21/2019	8/23/2019	144 in ²	<10 µg/ft ²
Site: Blank					
2	201908865-0002	8/21/2019	8/23/2019	144 in ²	14 µg/ft ²
Site: Girl's Cafeteria (014) Floor					
3	201908865-0003	8/21/2019	8/23/2019	144 in ²	10 µg/ft ²
Site: Boy's Cafeteria (016) Floor					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/23/2019 14:52:23

201908863

Chain of Custody Transmittal

Paint & Plaster Stabilization: **Lead Wipe Samples**

Project No. 010-4467

Analysis: FAAS

Please email copy to: gwiazdowski^{us}ustin@gmail.com

Date/Time 8/21/19 10:30 AM

Date/Time 8-22-19

Date/Time 8/12/19 5:55

Date/Time

384

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201908864

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/22/19 5:15 PM
Collected: 8/22/2019

Project: **Paint & Plaster Stabilization: Sharswood / Project No. 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***


<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201908864-0001	8/22/2019	8/23/2019	144 in ²	<10 µg/ft ²
Site: Blank					
2	201908864-0002	8/22/2019	8/23/2019	144 in ²	10 µg/ft ²
Site: Kindergarten Cafeteria (006) Floor					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAP unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/23/2019 14:25:49



201908864

228 Moore Street • Philadelphia, Pennsylvania 19148 • Phone 215-755-2305 • Fax 215-755-2405

Chain of Custody Transmittal

Lead Wipe Samples

Paint & Plaster Stabilization: **Lead Wipe Sa**

Project Name: Sharswood

Project No. 010-4467

Laboratory: EMSL

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

Ⓐ Please email copy to: gwiazdowski.austin@gmail.com

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 8/22/19 3:30 PM

Transmitted to Lab By: [Signature]

Date/Time 8-22-19

Received in Lab By: 

Date/Time 8/22/19 STB

Samples Analyzed By: _____

Date/Time _____

[illegible]

2R11

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201909030

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/27/19 3:25 PM
Collected: 8/27/2019

Project: **Sharswood / Paint & Plaster Stabilization / Project No. 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201909030-0001	8/27/2019	8/28/2019	144 in ²	<10 µg/ft ²
Site: Blank					
2	201909030-0002	8/27/2019	8/28/2019	144 in ²	13 µg/ft ²
Site: 004, Boy's Basement Bathroom, W4 Floor					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/28/2019 14:39:25

201909030

Chain of Custody Transmittal

Paint & Plaster Stabilization: **Lead Wipe Samples**

Project No. 010-4467

Analysis: FAAS

Please email copy to: gwiazdowski.austin@gmail.com

Date/Time 8/27/19 6:30 AM

Date/Time 8/27/18

Date/Time 8/27/14 15:25P

Date/Time _____

Page 1 Of 1

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201909069

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/28/19 4:20 PM
Collected: 8/28/2019

Project: 010-4467 / Paint & Plaster Stabilization: Sharswood

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
#1	201909069-0001	8/28/2019	8/29/2019	144 in ²	<10 µg/ft ²
Site: Blank					
#2	201909069-0002	8/28/2019	8/29/2019	144 in ²	31 µg/ft ²
Site: 018, Basement Boys Bathroom, W3 Floor					

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 08/29/2019 14:59:32

201909069

Chain of Custody Transmittal

Paint & Plaster Stabilization: Lead Wipe Samples

Project No. 010-4467

Analysis: FAAS

Please email copy to: gwiazdowski.austin@gmail.com

X ASTM/EPA APPROVED GHOST WIPES USED

Date/Time 8/28/19 10:30AM

Date/Time 8/28/19 4:20 PM

Date/Time 8/28/19 4:20

Date/Time

2R#

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 786-5974

<http://www.EMSL.com>cinnaminsonleadlab@emsl.com

EMSL Order: 201909193

CustomerID: SYNE50

CustomerPO:

ProjectID:

Attn: **Austin Gwiazdowski**
Synertech, Inc.
228 Moore Street
Philadelphia, PA 19148

Phone: (215) 755-2305
Fax: (215) 755-2405
Received: 08/31/19 1:45 PM
Collected: 8/31/2019

Project: **Paint & Plaster Stabilization / Sharswood / 010-4467****Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)***

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
1	201909193-0001 Site: blank	8/31/2019	9/3/2019	144 in ²	<10 µg/ft ²
2	201909193-0002 Site: 018, right basement bathroom (boys), W3 floor	8/31/2019	9/3/2019	144 in ²	11 µg/ft ²
3	201909193-0003 Site: 006, kindergarden lunch room, W1 floor	8/31/2019	9/3/2019	144 in ²	13 µg/ft ²
4	201909193-0004 Site: 112, gym, W3 floor	8/31/2019	9/3/2019	144 in ²	<10 µg/ft ²

Phillip Worby, Lead Laboratory Manager
or other approved signatory

*Analysis following Lead in Dust by EMSL SOP/ Determination of Environmental Lead by FLAA. Reporting limit is 10 µg/wipe. ug/wipe = µg/ft² x area sampled in ft². Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities (such as volume sampled) or analytical method limitations. Samples received in good condition unless otherwise noted. The lab is not responsible for data reported in µg/ft² which is dependent on the area provided by non-lab personnel. The test results contained within this report meet the requirements of NELAC unless otherwise noted. "<" (less than) results signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, AIHA-LAP, LLC ELLAP 100194, A2LA 2845.01

Initial report from 09/03/2019 14:18:25

201909193

Chain of Custody Transmittal

Lead Wipe Samples

Paint & Plaster Stabilization: ~~Shower~~ **Lead Wipe**

Project Name: Sharswood

Project No. 010-4467

Laboratory: EMSL

Analysis: FAAS

Turnaround Time: ☒ 24 hours ☐ 48 hours ☐ 72 hours ☐ Other

Please email copy to: gwiozdowski.austin@gmail.com

X ASTM/EPA APPROVED GHOST WIPES USED

Samples Collected By: Austin Gwiazdowski

Date/Time 8/31/19 8:30 AM

Transmitted to Lab By: Austin Gwinzdowski

Date/Time 8/31/19 1:45 PM

Received in Lab By:

Date/Time 8/31/19 1:45 p

Samples Analyzed By:

Date/Time

Page 1 Of 1

Appendix E

Photographs



Photos 1 & 2
Typical Contained Classroom Prior to Renovation



Photos 3 & 4
Typical Contained Classroom During Renovation

Appendix F

Environmental Firm Certifications

United States Environmental Protection Agency

This is to certify that



Synertech, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires April 11, 2024

NAT-F199601-1

Certification #

March 28, 2019

Issued On



A handwritten signature in black ink, appearing to read "Michelle Price".

Michelle Price, Chief


Lead, Heavy Metals, and Inorganics Branch

Appendix G

Paint Contractor Certifications

United States Environmental Protection Agency

This is to certify that



Delta/BJDS, Inc.

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint renovation, repair, and painting activities pursuant to 40 CFR Part 745.89

In the Jurisdiction of:

All EPA Administered States, Tribes, and Territories

This certification is valid from the date of issuance and expires August 07, 2023

NAT-F-186289-1

Certification #

July 24, 2018

Issued On

Michelle Price, Chief

Lead, Heavy Metals, and Inorganics Branch



Appendix H

Documentation of Parent and Staff Notification



**George Sharswood School
2300 S. 2nd Street
Philadelphia, PA 19148**

**Leigh McLinden
Principal**

Telephone: 215-400-8270

Paint and Plaster Stabilization: Project Start

Dear School Families,

The School District of Philadelphia works daily to ensure that our students and staff have a safe, healthy environment in which to learn and work. On behalf of the School District, I am writing to share information with you about plans for renovation to remove loose and peeling paint in our school building. The goal of the work is to enhance classroom environments and remove the risk of lead exposure to children in our school community.

The School District has begun paint and plaster stabilization work in school buildings constructed prior to 1978 that are likely to contain lead-based paint. Paint stabilization involves removing loose, peeling, flaking and crumbling paint and plaster under controlled conditions. Our school has been selected for this work because paint damage was documented in occupied spaces such as classrooms and classroom closets, administrative offices, cafeteria, auditorium, bathrooms, kitchen, hallways, and emergency exit stairways.

The work is being completed by individuals who are trained and certified in United States Environmental Protection Agency (EPA) lead-based paint renovation, repair and painting work practices. These work practices ensure that classrooms and other areas are free of paint chips, dust and debris. Each space will be assessed after the work is completed in each area to ensure that the spaces are ready for students and staff to safely occupy. Building staff will also look for signs of paint and plaster damage and clean paint and plaster dust and debris using a HEPA vacuum before, during, and after the project.

Details about the project including the environmental consultant's assessment report, project schedule and frequently asked questions are available in the school's main office or by visiting www.philasd.org/facilities. Copies will also be provided to the School Advisory Council and Home and School Association in the near future.

We understand that you likely will have additional questions, and we will work to address those promptly. The School District will host a meeting for families to share an overview of the repairs and to answer questions on **Wednesday, May 15, 2019 at 8:30 AM** in our school.

Sincerely,

Leigh McLinden
Principal