

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Room 101 Counselor's Suite Entrance Area	W1	Plaster	Blue	None	0	0.25	Negative
1	1	Room 101 Counselor's Suite Entrance Area	W1	Plaster	White	None	0	0.1	Negative
1	1	Room 101 Counselor's Suite Entrance Area	W2	Plaster	Purple	None	0	1.4	Positive
1	1	Room 101 Counselor's Suite Entrance Area	W2	Plaster	White	None	0	0.16	Negative
1	1	Room 101 Counselor's Suite Entrance Area	W3	CMU	Blue	None	0	2.6	Positive
1	1	Room 101 Counselor's Suite Entrance Area	W3	CMU	White	None	0	4.12	Positive
1	1	Room 101 Counselor's Suite Entrance Area	W4	Plaster	Purple	None	0	3.07	Positive
1	1	Room 101 Counselor's Suite Entrance Area	W4	CMU	Purple	None	0	4.71	Positive
1	1	Room 101 Counselor's Suite Entrance Area	W4	CMU	White	None	0	3.89	Positive
1	1	Room 101 Counselor's Suite Entrance Area	Window Frame	Wood	Purple	None	0	5.66	Positive
1	1	Room 101 Counselor's Suite Entrance Area	Window Sill	Wood	Blue	None	0	4.92	Positive
1	1	Room 101 Counselor's Suite Entrance Area	Window Frame	Wood	White	None	0	6.01	Positive
1	1	Room 101 Counselor's Suite Entrance Area	Pipe	Metal	White	None	0	0	Negative
1	1	Room 101 Counselor's Suite Entrance Area	Pipe	Metal	Purple	None	0	0	Negative
1	1	Room 101 Counselor's Suite Entrance Area	Ceiling	Plaster	White	None	0	0.13	Negative
1	1	Room 101 Counselor's Suite Entrance Area	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 101 Counselor's Suite Entrance Area	Baseboard	Wood	Brown	None	0	0.28	Negative
1	1	Room 101 Counselor's Suite Entrance Area	Trim	Wood	Blue	None	0	0.04	Negative
1	1	Room 101 Counselor's Suite Entrance Area	Trim	Wood	Purple	None	0	0.04	Negative
1	1	Counselor Suite Waiting Area	W1	CMU	Purple	None	0	3.3	Positive
1	1	Counselor Suite Waiting Area	W2	CMU	Purple	None	0	4.91	Positive
1	1	Counselor Suite Waiting Area	W3	Plaster	Purple	None	0	0.22	Negative
1	1	Counselor Suite Waiting Area	W3	Plaster	White	None	0	0.09	Negative
1	1	Counselor Suite Waiting Area	W4	Plaster	Purple	None	0	1.33	Positive
1	1	Counselor Suite Waiting Area	W4	Plaster	White	None	0	0.17	Negative
1	1	Counselor Suite Waiting Area	Ceiling	Plaster	White	None	0	0.18	Negative
1	1	Counselor Suite Waiting Area	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Counselor Suite Waiting Area	Pipe	Metal	White	None	0	0	Negative
1	1	Counselor Suite Waiting Area	Window Frame	Wood	Purple	None	0	5.24	Positive
1	1	Counselor Suite Waiting Area	Window Sill	Wood	Purple	None	0	5.58	Positive
1	1	Counselor Suite Waiting Area	Window Frame	Wood	White	None	0	6.08	Positive
1	1	Counselor Suite Waiting Area	Door Frame	Wood	Purple	None	0	5.22	Positive
1	1	Counselor Suite Waiting Area	Baseboard	Wood	Brown	None	0	0.22	Negative
1	1	Counselor Suite Waiting Area	Whiteboard Frame	Wood	Brown	None	0	0.07	Negative
1	1	Counselor Suite Waiting Area	Trim	Wood	Purple	None	0	0.04	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W1	CMU	Purple	None	0	4.3	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	W1	Plaster	Purple	None	0	0.26	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W1	Plaster	White	None	0	0.39	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W2	CMU	Purple	None	0	4.03	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	W2	CMU	White	None	0	4.61	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	W3	Plaster	Purple	None	0	0.07	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W3	Plaster	White	None	0	0.03	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W4	Plaster	Purple	None	0	0.03	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	W4	Plaster	Purple	None	0	0.01	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Ceiling	Plaster	White	None	0	0.3	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor's Suite - Office furthest from Suite entrance	Door Frame	Wood	Purple	None	0	6.31	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	Window Frame	Wood	Purple	None	0	7.15	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	Window Sill	Wood	Purple	None	0	4.52	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	Window Frame	Wood	White	None	0	7.06	Positive
1	1	Counselor's Suite - Office furthest from Suite entrance	Window Frame	Wood	Brown	None	0	0.14	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Window Sill	Wood	Brown	None	0	0.11	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Baseboard	Wood	Brown	None	0	0.15	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Radiator	Metal	Grey	Chipping	1	6.29	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Counselor's Suite - Office furthest from Suite entrance	Whiteboard Frame	Wood	Brown	None	0	0.03	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Pipe	Metal	White	None	0	0	Negative
1	1	Counselor's Suite - Office furthest from Suite entrance	Trim	Wood	Purple	None	0	0.08	Negative
1	1	Counselor's Suite - Center Office off Waiting Area	W1	CMU	Purple	None	0	2.28	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	W2	CMU	Purple	None	0	4.32	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	W2	CMU	White	None	0	7.3	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	W3	Plaster	Purple	None	0	0.04	Negative
1	1	Counselor's Suite - Center Office off Waiting Area	W4	CMU	Purple	None	0	4.47	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	W4	CMU	White	None	0	5.07	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	Ceiling	Plaster	White	None	0	0.31	Negative
1	1	Counselor's Suite - Center Office off Waiting Area	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor's Suite - Center Office off Waiting Area	Door Frame	Wood	White	None	0	5.65	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	Window Frame	Wood	Purple	None	0	5.14	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	Window Sill	Wood	Purple	None	0	5.03	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	Window Frame	Wood	White	None	0	6.23	Positive
1	1	Counselor's Suite - Center Office off Waiting Area	Radiator	Metal	Grey	Chipping	1	0	Negative
1	1	Counselor's Suite - Center Office off Waiting Area	Pipe	Metal	White	None	0	0	Negative
1	1	Counselor's Suite - Center Office off Waiting Area	Baseboard	Wood	Brown	None	0	0.23	Negative
1	1	Counselor's Suite - Office closest to Waiting Area	W1	CMU	Purple	None	0	5.44	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W1	CMU	White	None	0	5.79	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W2	CMU	Purple	None	0	4.99	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W2	CMU	White	None	0	6.92	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W3	Plaster	Purple	None	0	5.24	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W3	Plaster	White	None	0	3.14	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W4	CMU	Purple	None	0	5.38	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	W4	CMU	White	None	0	5.19	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Ceiling	Plaster	White	None	0	3.68	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Counselor's Suite - Office closest to Waiting Area	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor's Suite - Office closest to Waiting Area	Window Frame	Wood	Purple	None	0	5.86	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Window Sill	Wood	Purple	None	0	3.81	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Window Frame	Wood	White	None	0	2.52	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Door Frame	Wood	White	None	0	3.64	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Baseboard	Wood	Brown	None	0	0.18	Negative
1	1	Counselor's Suite - Office closest to Waiting Area	Radiator	Metal	Grey	None	0	3.7	Positive
1	1	Counselor's Suite - Office closest to Waiting Area	Pipe	Metal	White	None	0	0	Negative
1	1	Counselor's Suite - Office across from Suite entrance	W1	CMU	Purple	None	0	4.83	Positive
1	1	Counselor's Suite - Office across from Suite entrance	W2	Plaster	Blue	None	0	2.82	Positive
1	1	Counselor's Suite - Office across from Suite entrance	W2	Plaster	White	None	0	0.22	Negative
1	1	Counselor's Suite - Office across from Suite entrance	W3	Plaster	Purple	None	0	2.72	Positive
1	1	Counselor's Suite - Office across from Suite entrance	W3	Plaster	White	None	0	0.19	Negative
1	1	Counselor's Suite - Office across from Suite entrance	W4	CMU	Blue	None	0	5.72	Positive
1	1	Counselor's Suite - Office across from Suite entrance	W4	CMU	White	None	0	4.69	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Ceiling	Plaster	White	None	0	0.18	Negative
1	1	Counselor's Suite - Office across from Suite entrance	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor's Suite - Office across from Suite entrance	Window Frame	Wood	White	None	0	6.84	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Window Sill	Wood	White	None	0	5.04	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Window Frame	Wood	White	None	0	4.73	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Door Frame	Wood	Purple	None	0	4.66	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Door Frame	Wood	Blue	None	0	6.19	Positive
1	1	Counselor's Suite - Office across from Suite entrance	Radiator	Metal	Grey	Chipping	1	0.02	Negative
1	1	Counselor's Suite - Office across from Suite entrance	Baseboard	Wood	Brown	None	0	0.26	Negative
1	1	Counselor's Suite - Office across from Suite entrance	Pipe	Metal	White	None	0	0	Negative
1	1	Classroom 102	W1	Plaster	White	None	0	0	Negative
1	1	Classroom 102	W1	Ceramic Tile	Unpainted	N/A	N/A	6.38	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 102	W2	Plaster	White	None	0	0.11	Negative
1	1	Classroom 102	W2	Ceramic Tile	Unpainted	N/A	N/A	6.48	Positive
1	1	Classroom 102	W3	Plaster	White	None	0	0.14	Negative
1	1	Classroom 102	W3	Ceramic Tile	Unpainted	N/A	N/A	6.07	Positive
1	1	Classroom 102	W4	Plaster	White	None	0	0.21	Negative
1	1	Classroom 102	W4	Ceramic Tile	Unpainted	N/A	N/A	5.48	Positive
1	1	Classroom 102	Ceiling	Plaster	White	Chipping	3	0.07	Negative
1	1	Classroom 102	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 102	Radiator	Metal	Grey	Chipping	1	0.07	Negative
1	1	Classroom 102	Pipe	Metal	White	None	0	0	Negative
1	1	Classroom 102	Whiteboard Frame	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 102 Closet on hall wall	W1	Plaster	White	None	0	0.09	Negative
1	1	Classroom 102 Closet on hall wall	W2	Plaster	White	None	0	0.1	Negative
1	1	Classroom 102 Closet on hall wall	W3	Plaster	White	None	0	0.09	Negative
1	1	Classroom 102 Closet on hall wall	W4	Plaster	White	Cracking	1	0.06	Negative
1	1	Classroom 102 Closet on hall wall	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	Classroom 102 Closet on hall wall	Floor	9"x9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 102 Closet on hall wall	Pipe	Metal	White	None	0	0	Negative
1	1	Classroom 102 Closet on windows side	W1	Plaster	White	Cracking	1	0.07	Negative
1	1	Classroom 102 Closet on windows side	W2	Plaster	White	Cracking	1	0.05	Negative
1	1	Classroom 102 Closet on windows side	W3	Plaster	White	Cracking	1	0.06	Negative
1	1	Classroom 102 Closet on windows side	W4	Plaster	White	None	0	0.14	Negative
1	1	Classroom 102 Closet on windows side	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	Classroom 102 Closet on windows side	Floor	9"x9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 102 Closet on windows side	Pipe	Metal	White	None	0	0	Negative
1	1	Graphic Arts Room 103	W1	Plaster	White	None	0	0.2	Negative
1	1	Graphic Arts Room 103	W1	Ceramic Tile	Unpainted	N/A	N/A	6.09	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Graphic Arts Room 103	W2	Plaster	White	None	0	0.15	Negative
1	1	Graphic Arts Room 103	W2	Ceramic Tile	Unpainted	N/A	N/A	4.89	Positive
1	1	Graphic Arts Room 103	W3	Plaster	White	None	0	0.11	Negative
1	1	Graphic Arts Room 103	W3	Ceramic Tile	Unpainted	N/A	N/A	6.21	Positive
1	1	Graphic Arts Room 103	W4	Plaster	White	None	0	0.1	Negative
1	1	Graphic Arts Room 103	W4	Ceramic Tile	Unpainted	N/A	N/A	6.59	Positive
1	1	Graphic Arts Room 103	Ceiling	Plaster	White	None	0	0.04	Negative
1	1	Graphic Arts Room 103	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Graphic Arts Room 103	Radiator	Metal	White	None	0	0	Negative
1	1	Graphic Arts Room 103	Pipe	Metal	White	None	0	0.14	Negative
1	1	Graphic Arts Room 103	Whiteboard Frame	Wood	Brown	None	0	0.04	Negative
1	1	Graphic Arts Room Closet on hall wall	W1	Plaster	White	Cracking	1	0.13	Negative
1	1	Graphic Arts Room Closet on hall wall	W2	Plaster	White	None	0	0.1	Negative
1	1	Graphic Arts Room Closet on hall wall	W3	Plaster	White	Chipping	1	0.15	Negative
1	1	Graphic Arts Room Closet on hall wall	W4	Plaster	White	None	0	0.07	Negative
1	1	Graphic Arts Room Closet on hall wall	Ceiling	Plaster	White	None	0	0.1	Negative
1	1	Graphic Arts Room Closet on hall wall	Floor	9"x9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Graphic Arts Room Closet on hall wall	Pipe	Metal	White	None	0	0.01	Negative
1	1	Graphic Arts Room Closet on windows side	W1	Plaster	White	None	0	0.08	Negative
1	1	Graphic Arts Room Closet on windows side	W2	Plaster	White	None	0	0.11	Negative
1	1	Graphic Arts Room Closet on windows side	W3	Plaster	White	Cracking	1	0.09	Negative
1	1	Graphic Arts Room Closet on windows side	W4	Plaster	White	Cracking	1	0.08	Negative
1	1	Graphic Arts Room Closet on windows side	Ceiling	Plaster	White	None	0	0.1	Negative
1	1	Graphic Arts Room Closet on windows side	Floor	Concrete	Black	None	0	0.02	Negative
1	1	Graphic Arts Room Closet on windows side	Pipe	Metal	White	None	0	0	Negative
1	1	Fine Arts Room 104	W1	Plaster	White	None	0	0.15	Negative
1	1	Fine Arts Room 104	W1	Ceramic Tile	Unpainted	N/A	N/A	6.54	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Fine Arts Room 104	W2	Plaster	White	None	0	0.02	Negative
1	1	Fine Arts Room 104	W2	Ceramic Tile	Unpainted	N/A	N/A	6.05	Positive
1	1	Fine Arts Room 104	W3	Plaster	White	None	0	0.17	Negative
1	1	Fine Arts Room 104	W3	Ceramic Tile	Unpainted	N/A	N/A	6.21	Positive
1	1	Fine Arts Room 104	W4	Plaster	White	None	0	0.12	Negative
1	1	Fine Arts Room 104	W4	Ceramic Tile	Unpainted	N/A	N/A	6.1	Positive
1	1	Fine Arts Room 104	Ceiling	Plaster	White	None	0	0.05	Negative
1	1	Fine Arts Room 104	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fine Arts Room 104	Radiator	Metal	Grey	None	0	0.01	Negative
1	1	Fine Arts Room 104	Whiteboard Frame	Wood	Brown	None	0	0.03	Negative
1	1	Fine Arts Room Closet next to Office	W1	Plaster	White	None	0	0.11	Negative
1	1	Fine Arts Room Closet next to Office	W2	Plaster	White	None	0	0.17	Negative
1	1	Fine Arts Room Closet next to Office	W3	Plaster	White	None	0	0.1	Negative
1	1	Fine Arts Room Closet next to Office	W4	Plaster	White	None	0	0.09	Negative
1	1	Fine Arts Room Closet next to Office	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	Fine Arts Room Closet next to Office	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fine Arts Room Closet next to Office	Pipe	Metal	White	None	0	0	Negative
1	1	Fine Arts Room Closet at entrance to room	W1	Plaster	White	Chipping	1	0.13	Negative
1	1	Fine Arts Room Closet at entrance to room	W2	Plaster	White	None	0	0.08	Negative
1	1	Fine Arts Room Closet at entrance to room	W3	Plaster	White	None	0	0.14	Negative
1	1	Fine Arts Room Closet at entrance to room	W4	Plaster	White	None	0	0.11	Negative
1	1	Fine Arts Room Closet at entrance to room	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	Fine Arts Room Closet at entrance to room	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fine Arts Room Closet at entrance to room	Pipe	Metal	White	None	0	0	Negative
1	1	Art Workroom 106	W1	Plaster	White	None	0	0.16	Negative
1	1	Art Workroom 106	W2	Plaster	White	None	0	0.012	Negative
1	1	Art Workroom 106	W3	Plaster	White	None	0	0.17	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Art Workroom 106	W4	Plaster	White	None	0	0.12	Negative
1	1	Art Workroom 106	Ceiling	Plaster	White	None	0	0.16	Negative
1	1	Art Workroom 106	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Fine Arts Room Office	W1	Plaster	White	None	0	0.06	Negative
1	1	Fine Arts Room Office	W1	Ceramic Tile	Unpainted	N/A	N/A	6.33	Positive
1	1	Fine Arts Room Office	W2	Plaster	White	None	0	0.12	Negative
1	1	Fine Arts Room Office	W2	Ceramic Tile	Unpainted	N/A	N/A	6.9	Positive
1	1	Fine Arts Room Office	W3	Plaster	White	None	0	0.1	Negative
1	1	Fine Arts Room Office	W3	Ceramic Tile	Unpainted	N/A	N/A	6.77	Positive
1	1	Fine Arts Room Office	W4	Plaster	White	None	0	0.19	Negative
1	1	Fine Arts Room Office	W4	Tile	White	None	0	6.61	Positive
1	1	Fine Arts Room Office	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Fine Arts Room Office	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fine Arts Room Office	Radiator	Metal	Grey	None	0	0.03	Negative
1	1	Fine Arts Room Office	Door Frame	Metal	Grey	None	0	0.08	Negative
1	1	Kiln Room 107	W1	Plaster	White	None	0	0.08	Negative
1	1	Kiln Room 107	W2	Plaster	White	None	0	0.06	Negative
1	1	Kiln Room 107	W3	Plaster	White	None	0	0.11	Negative
1	1	Kiln Room 107	W4	Plaster	White	None	0	0.09	Negative
1	1	Kiln Room 107	Ceiling	Plaster	White	Chipping	2	0.06	Negative
1	1	Kiln Room 107	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Storeroom 108 across from Elevator No. 2	W1	Plaster	White	None	0	0	Negative
1	1	Storeroom 108 across from Elevator No. 2	W2	Plaster	White	None	0	0.04	Negative
1	1	Storeroom 108 across from Elevator No. 2	W3	Plaster	White	None	0	0	Negative
1	1	Storeroom 108 across from Elevator No. 2	W4	Plaster	White	Cracking	1	0.01	Negative
1	1	Storeroom 108 across from Elevator No. 2	Ceiling	Plaster	White	None	0	0.07	Negative
1	1	Storeroom 108 across from Elevator No. 2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Storeroom 108 across from Elevator No. 2	Pipe	Metal	White	None	0	0	Negative
1	1	Lower Level Gymnasium	W1	Brick	White	None	0	0	Negative
1	1	Lower Level Gymnasium	W2	Brick	White	Flaking	20	0.01	Negative
1	1	Lower Level Gymnasium	W3	Brick	White	Flaking	30	0.01	Negative
1	1	Lower Level Gymnasium	W4	Brick	white	None	0	0	Negative
1	1	Lower Level Gymnasium	Ceiling	Concrete	White	Flaking	100	0	Negative
1	1	Lower Level Gymnasium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Lower Level Gymnasium	Radiator	Metal	Grey	Chipping	100	0.07	Negative
1	1	Lower Level Gymnasium	Radiator Cover	Metal	Grey	Chipping	60	0.09	Negative
1	1	Lower Level Gym Storage Room	W1	Plaster	White	Chipping	10	0.05	Negative
1	1	Lower Level Gym Storage Room	W2	Plaster	White	Efflorescence	20	0.12	Negative
1	1	Lower Level Gym Storage Room	W3	Plaster	White	Flaking	10	0.11	Negative
1	1	Lower Level Gym Storage Room	W4	Plaster	White	None	0	0.1	Negative
1	1	Lower Level Gym Storage Room	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Lower Level Gym Storage Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Lower Level Gym Storage Room	Radiator Cover	Metal	Grey	Chipping	5	0.08	Negative
1	1	Lower Level Gym Storage Room	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Lower Level Gym Storage Room	Radiator	Metal	Grey	Chipping	10	0	Negative
1	1	Lower Level Gym Storage Room	Pipe	Metal	White	Chipping	10	0.05	Negative
1	1	Lower Level Gym Storage Room	Ductwork	Metal	White	Chipping	10	0.15	Negative
1	1	Lower Level Gym Storage Room Restroom	W1	Plaster	White	Chipping	5	0.05	Negative
1	1	Lower Level Gym Storage Room Restroom	W2	Plaster	White	Chipping	1	0.08	Negative
1	1	Lower Level Gym Storage Room Restroom	W3	Plaster	White	Cracking	3	0.1	Negative
1	1	Lower Level Gym Storage Room Restroom	W4	Plaster	White	None	0	0.07	Negative
1	1	Lower Level Gym Storage Room Restroom	Ceiling	Sheet Rock	White	Flaking	2	0.04	Negative
1	1	Lower Level Gym Storage Room Restroom	Floor	Concrete	Grey	Friction	30	2.11	Positive
1	1	Lower Level Gym Storage Room Restroom	Baseboard	Concrete	Grey	None	0	2.19	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Storeroom 136	W1	Plaster	White	None	0	0.14	Negative
1	1	Storeroom 136	W2	Plaster	White	None	0	0.12	Negative
1	1	Storeroom 136	W3	Plaster	White	None	0	0.19	Negative
1	1	Storeroom 136	W4	Plaster	White	None	0	0.13	Negative
1	1	Storeroom 136	Moulding	Wood	White	None	0	0.12	Negative
1	1	Storeroom 136	Baseboard	Wood	White	None	0	0.1	Negative
1	1	Storeroom 136	Pipe	Metal	White	None	0	0	Negative
1	1	Storeroom 136	Window Frame	Wood	Brown	None	0	0.12	Negative
1	1	Storeroom 136	Window Sill	Wood	Brown	None	0	0.9	Positive
1	1	Storeroom 136	Ceiling	Plaster	White	Chipping	15	0.05	Negative
1	1	Storeroom 136	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Storeroom 136 Restroom	W1	Plaster	White	None	0	0.05	Negative
1	1	Storeroom 136 Restroom	W2	Plaster	White	None	0	0	Negative
1	1	Storeroom 136 Restroom	W3	Plaster	White	None	0	0.02	Negative
1	1	Storeroom 136 Restroom	W4	Plaster	White	None	0	0.08	Negative
1	1	Storeroom 136 Restroom	Ceiling	Plaster	White	None	0	0.04	Negative
1	1	Storeroom 136 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Hall Closet next to Storeroom 136	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hall Closet next to Storeroom 136	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hall Closet next to Storeroom 136	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hall Closet next to Storeroom 136	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hall Closet next to Storeroom 136	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hall Closet next to Storeroom 136	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 135	W1	Sheet Rock	Purple	None	0	0	Negative
1	1	Classroom 135	W2	Brick	White	None	0	0	Negative
1	1	Classroom 135	W3	Brick	Purple	None	0	0.07	Negative
1	1	Classroom 135	W4	Brick	Purple	None	0	0.06	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 135	Ceiling	Plaster	White	Chipping	70	0.01	Negative
1	1	Classroom 135	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 135	Window Frame	Wood	Purple	None	0	0.36	Negative
1	1	Classroom 135	Radiator	Metal	Grey	Chipping	10	No Access	No Access
1	1	Classroom 135	Radiator Cover	Metal	Grey	Chipping	5	0	Negative
1	1	Classroom 135	Door Frame	Wood	Purple	Chipping	2	0	Negative
1	1	Classroom 135 Restroom	W1	Sheet Rock	White	None	0	0	Negative
1	1	Classroom 135 Restroom	W2	Brick	White	None	0	0.07	Negative
1	1	Classroom 135 Restroom	W3	Sheet Rock	White	None	0	0	Negative
1	1	Classroom 135 Restroom	W4	Sheet Rock	White	None	0	0	Negative
1	1	Classroom 135 Restroom	Ceiling	Plaster	White	None	0	0	Negative
1	1	Classroom 135 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 135 Restroom	Door Frame	Wood	Brown	None	0	0	Negative
1	1	Classroom 135 Restroom	Window Frame	Metal	Brown	None	0	0.07	Negative
1	1	Classroom 134	W1	Sheet Rock	Black	Friction	1	0	Negative
1	1	Classroom 134	W2	Brick	Black	Chipping	5	0.06	Negative
1	1	Classroom 134	W3	Sheet Rock	Black	Friction	1	0	Negative
1	1	Classroom 134	W4	Brick	Black	Chipping	1	0.11	Negative
1	1	Classroom 134	Window Frame	Wood	brown	None	0	0.08	Negative
1	1	Classroom 134	Radiator	Metal	Grey	Chipping	5	No Access	No Access
1	1	Classroom 134	Radiator Cover	Metal	Grey	Chipping	5	0	Negative
1	1	Classroom 134	Door Frame	Metal	Brown	None	0	0.13	Negative
1	1	Classroom 134	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Classroom 134	Ceiling	Plaster	White	Chipping	10	0.09	Negative
1	1	Classroom 134	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 134 Restroom	W1	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 134 Restroom	W2	Brick	White	None	0	0.14	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 134 Restroom	W3	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 134 Restroom	W4	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 134 Restroom	Ceiling	Plaster	White	Chipping	15	0.08	Negative
1	1	Classroom 134 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 134 Restroom	Window Frame	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 134 Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Classroom 134 Restroom	Pipe	Metal	White	None	0	0	Negative
1	1	Classroom 133	W1	Sheet Rock	Blue	Friction	1	0	Negative
1	1	Classroom 133	W2	Brick	Blue	Chipping	5	0.07	Negative
1	1	Classroom 133	W3	Sheet Rock	Blue	Friction	1	0	Negative
1	1	Classroom 133	W4	Brick	Blue	Chipping	1	0.15	Negative
1	1	Classroom 133	Ceiling	Plaster	White	Flaking	80	0.06	Negative
1	1	Classroom 133	Window Frame	Wood	Brown	None	0	0.09	Negative
1	1	Classroom 133	Radiator	Metal	Grey	Chipping	5	0	No Access
1	1	Classroom 133	Radiator Cover	Metal	Grey	Chipping	5	0	Negative
1	1	Classroom 133	Door Frame	Metal	Brown	None	0	0.13	Negative
1	1	Classroom 133	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Classroom 133	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 133 Restroom	W1	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 133 Restroom	W2	Brick	White	None	0	0.14	Negative
1	1	Classroom 133 Restroom	W3	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 133 Restroom	W4	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 133 Restroom	Ceiling	Plaster	White	None	0	0.02	Negative
1	1	Classroom 133 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 133 Restroom	Window Frame	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 133 Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Classroom 132	W1	Sheet Rock	Purple	Friction	1	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 132	W2	Brick	Yellow	Chipping	5	0.07	Negative
1	1	Classroom 132	W3	Brick	Purple	Friction	1	0	Negative
1	1	Classroom 132	W4	Brick	Yellow	Chipping	1	0.15	Negative
1	1	Classroom 132	Ceiling	Plaster	White	Alligating	20	0.07	Negative
1	1	Classroom 132	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 132	Radiator Cover	Metal	Yellow	None	0	0	Negative
1	1	Classroom 132	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Classroom 132	Window Frame	Wood	Brown	None	0	0.47	Negative
1	1	Classroom 132	Pipe Cover	Metal	Yellow	None	0	0.2	Negative
1	1	Classroom 132	Radiator	Metal	Grey	Chipping	14	No Access	No Access
1	1	Classroom 132 Restroom	W1	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 132 Restroom	W2	Brick	White	Efflorescence	5	0.14	Negative
1	1	Classroom 132 Restroom	W3	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 132 Restroom	W4	Sheet Rock	White	Cracking	1	0	Negative
1	1	Classroom 132 Restroom	Ceiling	Plaster	White	None	0	0.05	Negative
1	1	Classroom 132 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 132 Restroom	Window Frame	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 132 Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	1	Nurse's Office 123	W1	Plaster	White	Cracking	2	0.15	Negative
1	1	Nurse's Office 123	W1	Plaster	Blue	None	0	0.27	Negative
1	1	Nurse's Office 123	W2	Plaster	White	None	0	0.15	Negative
1	1	Nurse's Office 123	W2	Plaster	Blue	None	0	0.23	Negative
1	1	Nurse's Office 123	W3	Plaster	White	None	0	0.2	Negative
1	1	Nurse's Office 123	W3	Plaster	Blue	None	0	0.37	Negative
1	1	Nurse's Office 123	W4	Plaster	White	Cracking	1	0.16	Negative
1	1	Nurse's Office 123	W4	Plaster	Blue	None	0	0.28	Negative
1	1	Nurse's Office 123	Ceiling	Plaster	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Nurse's Office 123	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Office 123	Door Frame	Wood	Brown	Chipping	5	4.72	Positive
1	1	Nurse's Office 123	Door	Wood	Brown	Chipping	5	0	Negative
1	1	Nurse's Office 123	Window Frame	Wood	Brown	None	0	6.56	Positive
1	1	Nurse's Office 123	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	1	Nurse's Office 123	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Nurse's Office 123	Baseboard	Wood	Brown	Friction	5	6.7	Positive
1	1	Nurse's Office 123	Moulding	Wood	Brown	None	0	7.7	Positive
1	1	Nurse's Office 123	Window Sill	Wood	Brown	Friction	1	6.53	Positive
1	1	Nurse's Office 123	Cabinet	Wood	Blue	None	0	5.47	Positive
1	1	Nurse's Office 123	Cabinet	Wood	Black	Chipping	2	8.35	Positive
1	1	Auditorium	W1	Plaster	Grey	Chipping	1	0.09	Negative
1	1	Auditorium	W1	Plaster	White	None	0	0.9	Positive
1	1	Auditorium	W2	Plaster	Grey	Cracking	10	0.02	Negative
1	1	Auditorium	W3	Plaster	Grey	Flaking	70	0.07	Negative
1	1	Auditorium	W3	Plaster	White	Flaking	5	0.12	Negative
1	1	Auditorium	W4	Plaster	Grey	Chipping	2	0.07	Negative
1	1	Auditorium	W4	Plaster	White	None	0	0.06	Negative
1	1	Auditorium	Ceiling	Plaster	White	Flaking	80	0.12	Negative
1	1	Auditorium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Auditorium	Window Sill	Wood	Brown	Friction	4	0.13	Negative
1	1	Auditorium Stage	W1	Plaster	Black	Flaking	20	2.5	Positive
1	1	Auditorium Stage	W2	Plaster	Black	Flaking	15	2.17	Positive
1	1	Auditorium Stage	W3	Plaster	Black	None	0	2.29	Positive
1	1	Auditorium Stage	W4	Plaster	Black	Flaking	20	2.33	Positive
1	1	Auditorium Stage	Ceiling	Plaster	White	Flaking	20	No Access	No Access
1	1	Auditorium Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Auditorium Stage	Door	Wood	Black	Friction	10	0.32	Negative
1	1	Auditorium Stage	Door Frame	Wood	Black	Chipping	10	0.33	Negative
1	1	Auditorium Stage	Radiator	Metal	Black	Chipping	15	0.06	Negative
1	1	Auditorium Stage	Baseboard	Wood	Brown	Friction	5	0.24	Negative
1	1	Auditorium Stage	Radiator Cover	Metal	Black	Chipping	10	0.1	Negative
1	1	Auditorium Stage	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Stage Right Entrance from Stairs	W1	Plaster	White	Flaking	4	0.04	Negative
1	1	Stage Right Entrance from Stairs	W2	Plaster	White	Efflorescence	8	0.06	Negative
1	1	Stage Right Entrance from Stairs	W3	Plaster	White	Efflorescence	20	0.08	Negative
1	1	Stage Right Entrance from Stairs	W4	Plaster	White	Chipping	5	0.05	Negative
1	1	Stage Right Entrance from Stairs	Ceiling	Plaster	White	None	0	0.02	Negative
1	1	Stage Right Entrance from Stairs	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Stage Right Entrance from Stairs	Window Frame	Wood	Brown	None	0	1.33	Positive
1	1	Stage Right Entrance from Stairs	Window Sill	Wood	Brown	Friction	2	0.03	Negative
1	1	Stage Right Entrance from Stairs	Radiator	Metal	Grey	Chipping	5	0.1	Negative
1	1	Stage Right Entrance from Stairs	Radiator Cover	Metal	Grey	Chipping	2	0.1	Negative
1	1	Stage Right Entrance from Stairs	Pipe	Metal	White	None	0	0.1	Negative
1	1	Stage Right Entrance from Stairs	Baseboard	Wood	Grey	None	0	0.34	Negative
1	1	Stage Right Stairs and Storage	W1	Plaster	White	None	0	0.09	Negative
1	1	Stage Right Stairs and Storage	W2	Plaster	White	Cracking	5	0.06	Negative
1	1	Stage Right Stairs and Storage	W3	Plaster	White	None	0	0.1	Negative
1	1	Stage Right Stairs and Storage	W4	Plaster	White	Chipping	4	0.01	Negative
1	1	Stage Right Stairs and Storage	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Stage Right Stairs and Storage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage	W2	Plaster	White	Flaking	40	0.15	Negative
1	1	Hallway behind Stage	W4	Plaster	White	Chipping	15	0.09	Negative
1	1	Hallway behind Stage	Ceiling	Plaster	White	None	0	0.02	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway behind Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway behind Stage	Baseboard	Wood	White	Friction	2	0.08	Negative
1	1	Hallway behind Stage	Window Sill	Wood	Brown	Friction	10	0.02	Negative
1	1	Hallway behind Stage	Window Frame	Wood	Brown	None	0	1.23	Positive
1	1	Hallway behind Stage	Pipe Cover	Metal	White	Chipping	10	0.15	Negative
1	1	Stage Left Storage Area	W1	Plaster	White	Chipping	5	0.2	Negative
1	1	Stage Left Storage Area	W2	Plaster	White	Efflorescence	10	0.12	Negative
1	1	Stage Left Storage Area	W3	Plaster	White	Chipping	1	0.18	Negative
1	1	Stage Left Storage Area	W4	Plaster	White	Chipping	25	0.06	Negative
1	1	Stage Left Storage Area	Ceiling	Plaster	White	None	0	0.05	Negative
1	1	Stage Left Storage Area	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Stage Left Storage Area	Radiator	Metal	Grey	Chipping	2	0	Negative
1	1	Stage Left Storage Area	Radiator Cover	Metal	Grey	Chipping	1	0.07	Negative
1	1	Stage Left Storage Area	Door Frame	Metal	Brown	None	0	0.06	Negative
1	1	Stage Left Storage Area	Door	Metal	Brown	Friction	1	0	Negative
1	1	Stage Left Storage Area	Electric Panel cover	Metal	Brown	Chipping	3	2.38	Positive
1	1	Stage Left Storage Area	Window Sill	Wood	Brown	Friction	6	0.48	Negative
1	1	Stage Left Storage Area	Window Frame	Wood	Brown	None	0	1.65	Positive
1	1	Stage Left Storage Area	Pipe Cover	Metal	White	None	0	0.29	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	W1	Plaster	Green	Cracking	10	0.03	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	W2	Plaster	Green	Efflorescence	5	0.03	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	W3	Plaster	Green	Efflorescence	5	0.06	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	W4	Plaster	Green	Cracking	6	0.04	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	Ceiling	Plaster	Green	Efflorescence	5	0.01	Negative
1	1	Lighting Equipment Room in Stage Left Storage Area	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 121	W1	Plaster	White	None	0	0.09	Negative
1	1	Office 121	W2	Plaster	Yellow	Efflorescence	10	0.15	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Office 121	W2	Plaster	Blue	Chipping	10	0.17	Negative
1	1	Office 121	W3	Plaster	Yellow	None	0	0.16	Negative
1	1	Office 121	W3	Plaster	Blue	None	0	0.14	Negative
1	1	Office 121	W4	Plaster	Yellow	None	0	0.17	Negative
1	1	Office 121	W4	Plaster	Blue	None	0	0.17	Negative
1	1	Office 121	Ceiling	Plaster	White	Flaking	10	0.12	Negative
1	1	Office 121	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 121	Radiator	Metal	Grey	Friction	10	0.01	Negative
1	1	Office 121	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Office 121	Moulding	Wood	Blue	None	0	0.09	Negative
1	1	Main Office 129	W1	Plaster	Blue	None	0	0.27	Negative
1	1	Main Office 129	W1	Plaster	Green	Chipping	1	0.18	Negative
1	1	Main Office 129	W2	Plaster	Blue	None	0	0.16	Negative
1	1	Main Office 129	W2	Plaster	Green	None	0	0.36	Negative
1	1	Main Office 129	W3	Plaster	Blue	None	0	0.11	Negative
1	1	Main Office 129	W3	Plaster	Green	None	0	0.17	Negative
1	1	Main Office 129	W4	Plaster	Blue	Flaking	1	0.27	Negative
1	1	Main Office 129	W4	Plaster	Green	None	0	0.29	Negative
1	1	Main Office 129	Ceiling	Plaster	White	Chipping	10	0.15	Negative
1	1	Main Office 129	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office 129	Radiator	Metal	Red	Chipping	20	0.01	Negative
1	1	Main Office 129	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Main Office 129	Baseboard	Wood	Brown	Friction	10	0.05	Negative
1	1	Main Office Supply Closet	W1	Plaster	White	None	0	0.09	Negative
1	1	Main Office Supply Closet	W2	Plaster	White	None	0	0.1	Negative
1	1	Main Office Supply Closet	W3	Plaster	White	None	0	0.27	Negative
1	1	Main Office Supply Closet	W4	Plaster	White	None	0	0.02	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Main Office Supply Closet	Ceiling	Plaster	White	None	0	0.15	Negative
1	1	Main Office Supply Closet	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 128 Former Principal's Office next to Main	W1	Plaster	Green	None	0	0.3	Negative
1	1	Room 128 Former Principal's Office next to Main	W2	Plaster	Green	None	0	0.43	Negative
1	1	Room 128 Former Principal's Office next to Main	W3	Plaster	Green	None	0	0.23	Negative
1	1	Room 128 Former Principal's Office next to Main	W4	Plaster	Green	None	0	0.24	Negative
1	1	Room 128 Former Principal's Office next to Main	Ceiling	Plaster	Green	Chipping	20	0.15	Negative
1	1	Room 128 Former Principal's Office next to Main	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 128 Former Principal's Office next to Main	Pipe	Metal	Green	None	0	0	Negative
1	1	Room 128 Former Principal's Office next to Main	Baseboard	Wood	Brown	Friction	10	0.13	Negative
1	1	Room 128 Former Principal's Office next to Main	Radiator	Metal	Brown	None	0	0	Negative
1	1	Room 128 Former Principal's Office next to Main	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Restroom in Former Principal's Office next to Mai	W1	Plaster	White	None	0	0.27	Negative
1	1	Restroom in Former Principal's Office next to Mai	W2	Plaster	White	Chipping	1	0.14	Negative
1	1	Restroom in Former Principal's Office next to Mai	W3	Plaster	White	None	0	0.09	Negative
1	1	Restroom in Former Principal's Office next to Mai	W4	Plaster	White	None	0	0.13	Negative
1	1	Restroom in Former Principal's Office next to Mai	Ceiling	Plaster	White	None	0	0.025	Negative
1	1	Restroom in Former Principal's Office next to Mai	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Conference Room 118	W1	Plaster	White	None	0	0.21	Negative
1	1	Conference Room 118	W2	Plaster	White	Cracking	4	0.06	Negative
1	1	Conference Room 118	W3	Plaster	White	None	0	0.02	Negative
1	1	Conference Room 118	W4	Plaster	White	Chipping	2	0.03	Negative
1	1	Conference Room 118	Ceiling	Plaster	White	Chipping	80	0.01	Negative
1	1	Conference Room 118	Baseboard	Concrete	Brown	Chipping	15	2.55	Positive
1	1	Conference Room 118	Radiator	Metal	Grey	None	0	No Access	No Access
1	1	Conference Room 118	Pipe	Metal	White	None	0	0.33	Negative
1	1	Conference Room 118	Window Sill	Wood	Brown	None	0	0.13	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Conference Room 118	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 126 Women's Restroom	W1	Plaster	White	Efflorescence	20	0.23	Negative
1	1	Room 126 Women's Restroom	W2	Plaster	White	Efflorescence	5	0.11	Negative
1	1	Room 126 Women's Restroom	W3	Plaster	White	None	0	0.08	Negative
1	1	Room 126 Women's Restroom	W4	Plaster	White	Chipping	5	0.09	Negative
1	1	Room 126 Women's Restroom	Ceiling	Plaster	White	Flaking	175	0.02	Negative
1	1	Room 126 Women's Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 126 Women's Restroom	Radiator	Metal	Brown	Chipping	1	0	Negative
1	1	Room 126 Women's Restroom	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Room 126 Women's Restroom	Window Frame	Wood	Brown	None	0	0	Negative
1	1	Room 126 Women's Restroom	Door Frame	Wood	Brown	None	0	0.13	Negative
1	1	Storage Room next to Room 125	W1	Plaster	White	Cracking	10	0.02	Negative
1	1	Storage Room next to Room 125	W2	Plaster	White	None	0	0.01	Negative
1	1	Storage Room next to Room 125	W3	Plaster	White	Cracking	10	0	Negative
1	1	Storage Room next to Room 125	W4	Plaster	White	Cracking	10	0.04	Negative
1	1	Storage Room next to Room 125	Ceiling	Plaster	White	None	0	0.03	Negative
1	1	Storage Room next to Room 125	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Office Exam Area	W1	Plaster	White	Flaking	1	0.25	Negative
1	1	Nurse's Office Exam Area	W1	Plaster	Red	None	0	0.42	Negative
1	1	Nurse's Office Exam Area	W2	Plaster	White	None	0	0.31	Negative
1	1	Nurse's Office Exam Area	W3	Plaster	White	Friction	3	0.25	Negative
1	1	Nurse's Office Exam Area	W4	Plaster	White	None	0	0	Negative
1	1	Nurse's Office Exam Area	Ceiling	Plaster	White	Cracking	3	0.12	Negative
1	1	Nurse's Office Exam Area	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Office Exam Area	Window Sill	Wood	Brown	Flaking	1	4.25	Positive
1	1	Nurse's Office Exam Area	Window Frame	Wood	Brown	None	0	5.25	Positive
1	1	Nurse's Office Exam Area	Radiator	Metal	Grey	Chipping	5	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Nurse's Office Exam Area	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Nurse's Office Exam Area	Pipe	Metal	White	None	0	0.15	Negative
1	1	Nurse's Office Exam Area	Pipe Cover	Metal	White	Chipping	1	0.06	Negative
1	1	Nurse's Office Exam Area	Moulding	Wood	White	None	0	5.97	Positive
1	1	Nurse's Office Exam Area	Baseboard	Wood	Brown	Chipping	15	6.21	Positive
1	1	Nurse's Office Exam Area	Door Frame	Wood	brown	Chipping	3	6.1	Positive
1	1	Nurse's Office Exam Area Restroom	W1	Plaster	White	None	0	0.18	Negative
1	1	Nurse's Office Exam Area Restroom	W2	Plaster	White	None	0	0.29	Negative
1	1	Nurse's Office Exam Area Restroom	W3	Plaster	White	None	0	0.22	Negative
1	1	Nurse's Office Exam Area Restroom	W4	Plaster	White	None	0	0.27	Negative
1	1	Nurse's Office Exam Area Restroom	Ceiling	Plaster	White	Flaking	10	0.12	Negative
1	1	Nurse's Office Exam Area Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Office Exam Area Restroom	Pipe Cover	Metal	White	Flaking	2	0.05	Negative
1	1	Nurse's Office Exam Area Restroom	Door Frame	Wood	Brown	Chipping	4	7.22	Positive
1	1	Nurse's Office Exam Area Restroom	Ductwork	Metal	White	None	0	0.24	Negative
1	1	Nurse's Office Exam Area Restroom	Baseboard	Wood	Brown	Friction	5	5.15	Positive
1	1	Nurse's Office Restroom	W1	Plaster	White	None	0	0.17	Negative
1	1	Nurse's Office Restroom	W2	Plaster	White	None	0	0.16	Negative
1	1	Nurse's Office Restroom	W3	Plaster	White	None	0	0.22	Negative
1	1	Nurse's Office Restroom	W4	Plaster	White	None	0	0.2	Negative
1	1	Nurse's Office Restroom	Ceiling	Plaster	White	None	0	0.05	Negative
1	1	Nurse's Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Office Restroom	Door Frame	Wood	Brown	Chipping	1	8.51	Positive
1	1	Nurse's Office Restroom	Baseboard	Wood	Brown	Friction	5	3.93	Positive
1	1	Nurse's Office Restroom	Pipe Cover	Metal	Brown	None	0	0.07	Negative
1	1	Boy's Restroom across from Room 104	W1	Plaster	White	None	0	0.13	Negative
1	1	Boy's Restroom across from Room 104	W2	Plaster	White	Chipping	2	0.11	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Restroom across from Room 104	W3	Plaster	White	None	0	0.17	Negative
1	1	Boy's Restroom across from Room 104	W4	Plaster	White	Chipping	1	0.19	Negative
1	1	Boy's Restroom across from Room 104	Ceiling	Plaster	White	Chipping	150	0.02	Negative
1	1	Boy's Restroom across from Room 104	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom across from Room 104	Window Frame	Wood	Brown	None	0	0.13	Negative
1	1	Boy's Restroom across from Room 104	Door Frame	Wood	Brown	None	0	0.14	Negative
1	1	Electrical Room 111	W1	Plaster	White	None	0	0.12	Negative
1	1	Electrical Room 111	W2	Plaster	White	None	0	0.17	Negative
1	1	Electrical Room 111	W3	Plaster	White	None	0	0.16	Negative
1	1	Electrical Room 111	W4	Plaster	White	Cracking	5	0.15	Negative
1	1	Electrical Room 111	Ceiling	Plaster	White	None	0	0.25	Negative
1	1	Electrical Room 111	Floor	Concrete	White	None	0	0.01	Negative
1	1	Electrical Room 111	Door Frame	Wood	Brown	None	0	0.07	Negative
1	1	Electrical Room 111	Baseboard	Wood	Grey	None	0	0.01	Negative
1	1	Custodial Closet across from Room 106	W1	Plaster	White	Alligatoring	15	0.12	Negative
1	1	Custodial Closet across from Room 106	W2	Plaster	White	Chipping	5	0.03	Negative
1	1	Custodial Closet across from Room 106	W3	Plaster	White	Chipping	10	0	Negative
1	1	Custodial Closet across from Room 106	W4	Plaster	White	Chipping	4	0.16	Negative
1	1	Custodial Closet across from Room 106	Ceiling	Plaster	White	None	0	0.31	Negative
1	1	Custodial Closet across from Room 106	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Custodial Closet across from Room 106	Radiator	Metal	Grey	Chipping	15	0	Negative
1	1	Custodial Closet across from Room 106	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Custodial Closet across from Room 106	Window Frame	Wood	White	Flaking	15	1.32	Positive
1	1	Custodial Closet across from Room 106	Pipe	Metal	White	None	0	0.03	Negative
1	1	Custodial Closet across from Room 106	Window Sill	Wood	White	Alligatoring	5	0.33	Negative
1	1	Elevator No. 1 near Main Office	Elevator door	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator No. 1 near Main Office	W2	Metal	Grey	None	0	0.3	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Elevator No. 1 near Main Office	W3	Metal	Black	None	0	0.01	Negative
1	1	Elevator No. 1 near Main Office	W4	Metal	Grey	None	0	0.5	Negative
1	1	Elevator No. 1 near Main Office	Ceiling	Metal	White	None	0	0.01	Negative
1	1	Elevator No. 1 near Main Office	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator No. 2 near Room 108	W1	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator No. 2 near Room 108	W2	Metal	Grey	None	0	0.3	Negative
1	1	Elevator No. 2 near Room 108	W3	Metal	Black	None	0	0.01	Negative
1	1	Elevator No. 2 near Room 108	W4	Metal	Grey	None	0	0.5	Negative
1	1	Elevator No. 2 near Room 108	Ceiling	Metal	White	None	0	0.01	Negative
1	1	Elevator No. 2 near Room 108	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway between Main Office and Auditorium	W1	Plaster	White	None	0	0.21	Negative
1	1	Hallway between Main Office and Auditorium	W2	Plaster	White	Chipping	1	0.27	Negative
1	1	Hallway between Main Office and Auditorium	W3	Plaster	White	None	0	0.22	Negative
1	1	Hallway between Main Office and Auditorium	W4	Plaster	White	Chipping	10	0.36	Negative
1	1	Hallway between Main Office and Auditorium	Ceiling	Plaster	White	None	0	0.15	Negative
1	1	Hallway between Main Office and Auditorium	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Hallway between Main Office and Auditorium	Radiator	Metal	Grey	Chipping	5	0.1	Negative
1	1	Hallway between Main Office and Auditorium	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Hallway between Main Office and Auditorium	Door Frame	Metal	Brown	Chipping	2	0.22	Negative
1	1	Hallway between Main Office and Auditorium	trim	Concrete	Grey	Friction	10	0.18	Negative
1	1	Hallway along Lower Level Gym and Room 111	W1	Plaster	white	None	0	0.26	Negative
1	1	Hallway along Lower Level Gym and Room 111	W2	Plaster	White	None	0	0.32	Negative
1	1	Hallway along Lower Level Gym and Room 111	W2	Plaster	White	Flaking	5	0.21	Negative
1	1	Hallway along Lower Level Gym and Room 111	W3	Plaster	White	Chipping	2	0.24	Negative
1	1	Hallway along Lower Level Gym and Room 111	W4	Plaster	White	None	0	0.39	Negative
1	1	Hallway along Lower Level Gym and Room 111	W4	Plaster	White	None	0	0.25	Negative
1	1	Hallway along Lower Level Gym and Room 111	Ceiling	Plaster	White	Flaking	20	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway along Lower Level Gym and Room 111	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Hallway along Lower Level Gym and Room 111	Door Frame	Metal	Brown	Chipping	5	0.15	Negative
1	1	Hallway along Lower Level Gym and Room 111	Door Frame	Metal	Brown	Chipping	5	0.16	Negative
1	1	Hallway along Lower Level Gym and Room 111	Pipe Cover	Metal	White	None	0	0.13	Negative
1	1	Hallway along Lower Level Gym and Room 111	Radiator	Metal	Grey	None	0	0	Negative
1	1	Hallway to Room 123 Nurse's Office	W1	Plaster	White	None	0	0.16	Negative
1	1	Hallway to Room 123 Nurse's Office	W2	Plaster	White	Chipping	1	0.19	Negative
1	1	Hallway to Room 123 Nurse's Office	W3	Plaster	White	None	0	0.17	Negative
1	1	Hallway to Room 123 Nurse's Office	W4	Plaster	White	Flaking	3	0.2	Negative
1	1	Hallway to Room 123 Nurse's Office	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	Hallway to Room 123 Nurse's Office	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Hallway from Room 101 Counselor's Suite to Room 102	W1	Plaster	White	None	0	0.22	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	W2	Plaster	White	Chipping	20	0.19	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	W3	Plaster	White	Chipping	2	0.17	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	W4	Plaster	White	Chipping	2	0.2	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Ceiling	Plaster	White	None	0	0.11	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Floor	Concrete	Glazed	None	0	N/A	N/A
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Door Frame	Metal	Blue	Chipping	2	0.23	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Door	Metal	Blue	None	0	0.07	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Radiator	Metal	No Access	No Access	No Access	No Access	No Access
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Door Frame	Metal	Blue	Chipping	2	0.03	Negative
1	1	Hallway from Room 101 Counselor's Suite to Room 102	Door	Metal	Blue	Chipping	5	0.02	Negative
1	1	Hallway between Classrooms 132 and 136	W1	Plaster	White	None	0	0.16	Negative
1	1	Hallway between Classrooms 132 and 136	W2	Plaster	White	Chipping	1	0.19	Negative
1	1	Hallway between Classrooms 132 and 136	W3	Plaster	White	None	0	0.17	Negative
1	1	Hallway between Classrooms 132 and 136	W4	Plaster	White	Flaking	3	0.2	Negative
1	1	Hallway between Classrooms 132 and 136	Ceiling	Plaster	White	Efflorescence	20	0.11	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway between Classrooms 132 and 136	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Hallway between Classrooms 132 and 136	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Hallway between Classrooms 132 and 136	Trim	Concrete	Brown	None	0	0.16	Negative
1	1	Pipe Shaft between Boy's Restroom and Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Shaft between Boy's Restroom and Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Shaft between Boy's Restroom and Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Shaft between Boy's Restroom and Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Shaft between Boy's Restroom and Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Pipe Shaft between Boy's Restroom and Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Stairs from Lower Level Gym to Basement	W1	Brick	Glazed	None	0	N/A	N/A
1	1	Stairs from Lower Level Gym to Basement	W2	Brick	Glazed	None	0	N/A	N/A
1	1	Stairs from Lower Level Gym to Basement	W3	Brick	Glazed	None	0	N/A	N/A
1	1	Stairs from Lower Level Gym to Basement	W4	Brick	Glazed	None	0	N/A	N/A
1	1	Stairs from Lower Level Gym to Basement	Ceiling	Plaster	White	Flaking	70	0.12	Negative
1	1	Stairs from Lower Level Gym to Basement	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Stairs from Lower Level Gym to Basement	Stair Riser	Concrete	Grey	Chipping	20	0.64	Negative
1	1	Stairs from Lower Level Gym to Basement	Radiator Cover	Metal	White	None	0	0	Negative
1	1	Middle Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Middle Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Middle Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Middle Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Middle Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Middle Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Stairwell near Auditorium Rear	W1	Plaster	White	None	0	0.1	Negative
1	1	Stairwell near Auditorium Rear	W2	Plaster	White	Cracking	3	0.17	Negative
1	1	Stairwell near Auditorium Rear	W3	Plaster	White	None	0	0.18	Negative
1	1	Stairwell near Auditorium Rear	W4	Plaster	White	None	0	0.15	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Stairwell near Auditorium Rear	Ceiling	Plaster	White	Chipping	2	0	Negative
1	1	Stairwell near Auditorium Rear	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Stairwell near Auditorium Rear	Newel Post	Metal	Grey	Friction	1	3.52	Positive
1	1	Stairwell near Auditorium Rear	Spindle	Metal	Grey	None	0	3.09	Positive
1	1	Stairwell near Auditorium Rear	Stringer	Concrete	Grey	Chipping	1	0.15	Negative
1	1	Stairwell near Auditorium Rear	Stair Riser	Concrete	Grey	None	0	0.46	Negative
1	1	Stairwell near Auditorium Rear	Stair Tread	Concrete	Grey	None	0	0.01	Negative
1	1	Stairwell near Auditorium Rear	trim	Concrete	Grey	Friction	19	0.51	Negative
1	1	Stairwell near Auditorium Rear	Door	Metal	Black	None	0	0	Negative
1	1	Stairwell near Auditorium Rear	Door Frame	Metal	Black	None	0	0.03	Negative
1	1	Stairwell near Stage and Main Entrance to School	W1	Plaster	White	None	0	0.24	Negative
1	1	Stairwell near Stage and Main Entrance to School	W2	Plaster	White	Cracking	5	0.26	Negative
1	1	Stairwell near Stage and Main Entrance to School	W3	Plaster	White	None	0	0.27	Negative
1	1	Stairwell near Stage and Main Entrance to School	W4	Plaster	White	None	0	0.23	Negative
1	1	Stairwell near Stage and Main Entrance to School	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	Stairwell near Stage and Main Entrance to School	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Stairwell near Stage and Main Entrance to School	Newel Post	Metal	Grey	Chipping	1	4.13	Positive
1	1	Stairwell near Stage and Main Entrance to School	Spindle	Metal	Grey	None	0	3.34	Positive
1	1	Stairwell near Stage and Main Entrance to School	Stringer	Concrete	Grey	None	0	0.39	Negative
1	1	Stairwell near Stage and Main Entrance to School	Door	Metal	Black	None	0	0	Negative
1	1	Stairwell near Stage and Main Entrance to School	Door Frame	Metal	Black	None	0	0.33	Negative
1	1	Stairwell near Stage and Main Entrance to School	Pipe	Metal	White	Chipping	3	0	Negative
1	1	Stairwell near Stage and Main Entrance to School	trim	Concrete	Grey	None	0	0.15	Negative
1	1	Stairwell near Stage and Main Entrance to School	Stair Riser	Concrete	Grey	None	0	0.41	Negative
1	1	Stairwell near Stage and Main Entrance to School	Stair Tread	Concrete	Grey	None	0	0.03	Negative
1	1	Stairwell near Lower Level Gym and Room 108	W1	Plaster	White	None	0	0.27	Negative
1	1	Stairwell near Lower Level Gym and Room 108	W2	Plaster	White	Chipping	5	0.25	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Stairwell near Lower Level Gym and Room 108	W3	Plaster	White	None	0	0.21	Negative
1	1	Stairwell near Lower Level Gym and Room 108	W4	Plaster	White	None	0	0.23	Negative
1	1	Stairwell near Lower Level Gym and Room 108	Ceiling	Plaster	White	Cracking	1	0.05	Negative
1	1	Stairwell near Lower Level Gym and Room 108	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Stairwell near Lower Level Gym and Room 108	Stair Riser	Concrete	Grey	None	0	0.18	Negative
1	1	Stairwell near Lower Level Gym and Room 108	Newel Post	Metal	Grey	Friction	2	4.65	Positive
1	1	Stairwell near Lower Level Gym and Room 108	Spindle	Metal	Grey	None	0	1.81	Positive
1	1	Stairwell near Lower Level Gym and Room 108	Stringer	Concrete	Grey	None	0	0.43	Negative
1	1	Stairwell near Lower Level Gym and Room 108	Door	Metal	Black	None	0	0	Negative
1	1	Stairwell near Lower Level Gym and Room 108	Door Frame	Metal	Black	Friction	2	0.01	Negative
1	1	Stairwell near Lower Level Gym and Room 108	trim	Concrete	Grey	None	0	0.52	Negative
1	1	Stairwell near Lower Level Gym and Room 136	W1	Plaster	White	None	0	0.21	Negative
1	1	Stairwell near Lower Level Gym and Room 136	W2	Plaster	White	None	0	0.22	Negative
1	1	Stairwell near Lower Level Gym and Room 136	W3	Plaster	White	None	0	0.3	Negative
1	1	Stairwell near Lower Level Gym and Room 136	W4	Plaster	White	Flaking	5	0.34	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Ceiling	Plaster	White	None	0	0.18	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	1	Stairwell near Lower Level Gym and Room 136	Stair Riser	Concrete	Grey	None	0	0.09	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Newel Post	Metal	Grey	Friction	2	5.18	Positive
1	1	Stairwell near Lower Level Gym and Room 136	Spindle	Metal	Grey	None	0	3.2	Positive
1	1	Stairwell near Lower Level Gym and Room 136	Stringer	Concrete	Grey	None	0	0.54	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Door	Metal	Black	None	0	0	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Door Frame	Metal	Black	Friction	2	0.55	Negative
1	1	Stairwell near Lower Level Gym and Room 136	Pipe	Metal	White	None	0	0	Negative
1	1	Stairwell near Lower Level Gym and Room 136	trim	Concrete	Grey	None	0	0.74	Positive
1	2	General Office Area over Stage Right Stairs	W1	Plaster	White	None	0	0.12	Negative
1	2	General Office Area over Stage Right Stairs	W2	Plaster	White	Efflorescence	5	0.07	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	General Office Area over Stage Right Stairs	W3	Plaster	White	Efflorescence	10	0.06	Negative
1	2	General Office Area over Stage Right Stairs	W4	Plaster	White	None	0	0.14	Negative
1	2	General Office Area over Stage Right Stairs	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	General Office Area over Stage Right Stairs	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Conference Room 231	W1	Plaster	Orange	None	0	0.11	Negative
1	2	Principal's Conference Room 231	W2	Sheet Rock	Orange	None	0	0	Negative
1	2	Principal's Conference Room 231	W3	Plaster	Orange	None	0	0.09	Negative
1	2	Principal's Conference Room 231	W4	Sheet Rock	Orange	None	0	0	Negative
1	2	Principal's Conference Room 231	Ceiling	Plaster	White	Chipping	5	0.04	Negative
1	2	Principal's Conference Room 231	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Conference Room 231	Radiator Cover	Metal	Orange	None	0	0.14	Negative
1	2	Principal's Conference Room 231	Baseboard	Concrete	Brown	None	0	0.3	Negative
1	2	School Operations Office 231A	W1	Sheet Rock	Tan	None	0	0	Negative
1	2	School Operations Office 231A	W2	Sheet Rock	Tan	None	0	0	Negative
1	2	School Operations Office 231A	W3	Sheet Rock	Tan	None	0	0	Negative
1	2	School Operations Office 231A	W4	Plaster	Tan	Efflorescence	1	0.06	Negative
1	2	School Operations Office 231A	Ceiling	Plaster	White	Chipping	10	0.06	Negative
1	2	School Operations Office 231A	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	School Operations Office 231A	Radiator Cover	Metal	Tan	None	0	0.06	Negative
1	2	School Operations Office 231A	Pipe	Metal	Tan	None	0	0	Negative
1	2	School Operations Office 231A	Baseboard	Concrete	Brown	None	0	0.41	Negative
1	2	School Operations Office 231A	Door	Metal	Brown	None	0	0	Negative
1	2	School Operations Office 231A	Door Frame	Metal	Brown	None	0	0.04	Negative
1	2	MDF Server Room 231B	W1	Sheet Rock	Tan	None	0	0.03	Negative
1	2	MDF Server Room 231B	W2	Plaster	Tan	None	0	0.09	Negative
1	2	MDF Server Room 231B	W3	Plaster	Tan	Chipping	1	0.09	Negative
1	2	MDF Server Room 231B	W4	Plaster	Tan	Chipping	1	0.13	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	MDF Server Room 231B	Ceiling	Plaster	Tan	Chipping	10	0.04	Negative
1	2	MDF Server Room 231B	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	MDF Server Room 231B	Radiator Cover	Metal	Tan	None	0	0.23	Negative
1	2	MDF Server Room 231B	Door Frame	Metal	Brown	None	0	0.06	Negative
1	2	MDF Server Room 231B	Baseboard	Concrete	Brown	None	0	0.89	Positive
1	2	MDF Server Room 231B	Pipe	Metal	White	None	0	0.01	Negative
1	2	Principal's Office 230	W1	Plaster	Blue	None	0	0.09	Negative
1	2	Principal's Office 230	W2	Sheet Rock	Blue	None	0	0	Negative
1	2	Principal's Office 230	W3	Plaster	Blue	None	0	0.15	Negative
1	2	Principal's Office 230	W4	Sheet Rock	Blue	None	0	0	Negative
1	2	Principal's Office 230	Ceiling	Plaster	White	Chipping	20	0.05	Negative
1	2	Principal's Office 230	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office 230	Radiator Cover	Metal	Blue	None	0	0.11	Negative
1	2	Principal's Office 230	Baseboard	Concrete	Brown	None	0	0.34	Negative
1	2	Principal's Office 230	Pipe	Metal	Blue	None	0	0.02	Negative
1	2	Principal's Office 230	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Principal's Office Restroom	W1	Sheet Rock	Green	None	0	0	Negative
1	2	Principal's Office Restroom	W2	Sheet Rock	Green	None	0	0	Negative
1	2	Principal's Office Restroom	W3	Plaster	Green	None	0	0.08	Negative
1	2	Principal's Office Restroom	W4	Sheet Rock	Green	None	0	0	Negative
1	2	Principal's Office Restroom	Ceiling	Plaster	White	Chipping	3	0.05	Negative
1	2	Principal's Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	Baseboard	Concrete	Brown	None	0	0.33	Negative
1	2	Principal's Office Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Principal's Office Closet	W1	Sheet Rock	White	None	0	0	Negative
1	2	Principal's Office Closet	W2	Sheet Rock	White	None	0	0	Negative
1	2	Principal's Office Closet	W3	Plaster	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Principal's Office Closet	W4	Sheet Rock	White	None	0	0	Negative
1	2	Principal's Office Closet	Ceiling	Plaster	White	Chipping	2	0.01	Negative
1	2	Principal's Office Closet	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Closet	Baseboard	Concrete	Brown	None	0	0.23	Negative
1	2	Principal's Office Closet	Door Frame	Metal	Brown	None	0	0	Negative
1	2	General Office Area over Stage Right Stairs Rest	W1	Plaster	White	None	0	0.14	Negative
1	2	General Office Area over Stage Right Stairs Rest	W1	Plaster	Tan	None	0	0.08	Negative
1	2	General Office Area over Stage Right Stairs Rest	W2	Plaster	White	None	0	0.02	Negative
1	2	General Office Area over Stage Right Stairs Rest	W2	Plaster	Tan	Efflorescence	2	0.16	Negative
1	2	General Office Area over Stage Right Stairs Rest	W3	Plaster	White	None	0	0.15	Negative
1	2	General Office Area over Stage Right Stairs Rest	W3	Plaster	Tan	None	0	0.16	Negative
1	2	General Office Area over Stage Right Stairs Rest	W4	Plaster	White	None	0	0.11	Negative
1	2	General Office Area over Stage Right Stairs Rest	W4	Plaster	Tan	None	0	0.11	Negative
1	2	General Office Area over Stage Right Stairs Rest	Ceiling	Plaster	White	Cracking	1	0.07	Negative
1	2	General Office Area over Stage Right Stairs Rest	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	General Office Area over Stage Right Stairs Rest	Pipe	Metal	White	None	0	0	Negative
1	2	General Office Area over Stage Right Stairs Rest	Pipe	Metal	Tan	None	0	0	Negative
1	2	Classroom 204	W1	Plaster	Purple	None	0	0.04	Negative
1	2	Classroom 204	W2	Sheet Rock	Orange	None	0	0.01	Negative
1	2	Classroom 204	W2	Plaster	Orange	Chipping	1	0.01	Negative
1	2	Classroom 204	W3	Plaster	Purple	Efflorescence	2	0.19	Negative
1	2	Classroom 204	W4	Sheet Rock	Orange	None	0	0.01	Negative
1	2	Classroom 204	Ceiling	Plaster	White	Chipping	75	0.01	Negative
1	2	Classroom 204	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 204	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	2	Classroom 204	Pipe	Metal	Grey	Chipping	1	0.02	Negative
1	2	Classroom 204	Baseboard	Concrete	Brown	None	0	0.02	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Exercise Room 201	W1	Plaster	White	None	0	0.2	Negative
1	2	Exercise Room 201	W2	Sheet Rock	White	None	0	0	Negative
1	2	Exercise Room 201	W3	Plaster	White	None	0	0	Negative
1	2	Exercise Room 201	W4	Plaster	White	None	0	0.18	Negative
1	2	Exercise Room 201	Ceiling	Plaster	White	Chipping	10	0.07	Negative
1	2	Exercise Room 201	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Exercise Room 201	Baseboard	Concrete	Brown	None	0	0.02	Negative
1	2	Exercise Room 201	Radiator	Metal	Grey	Chipping	1	0.01	Negative
1	2	Exercise Room 201	Radiator	Metal	Grey	Chipping	1	5.71	Positive
1	2	Classroom 205	W1	Plaster	White	Chipping	1	0	Negative
1	2	Classroom 205	W2	Plaster	White	None	0	0	Negative
1	2	Classroom 205	W3	Plaster	White	Flaking	2	0.06	Negative
1	2	Classroom 205	W4	Plaster	White	None	0	0	Negative
1	2	Classroom 205	W4	Sheet Rock	White	None	0	0	Negative
1	2	Classroom 205	Pipe	Metal	White	Chipping	1	0.2	Negative
1	2	Classroom 205	Baseboard	Wood	Brown	None	0	0.03	Negative
1	2	Classroom 205	Ceiling	Plaster	White	Chipping	15	0.09	Negative
1	2	Classroom 205	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	W1	Plaster	White	None	0	0.01	Negative
1	2	Classroom 206	W2	Plaster	White	None	0	0.03	Negative
1	2	Classroom 206	W3	Plaster	White	Efflorescence	2	0.07	Negative
1	2	Classroom 206	W4	Plaster	White	Chipping	1	0.06	Negative
1	2	Classroom 206	Ceiling	Plaster	White	Chipping	4	0.02	Negative
1	2	Classroom 206	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Classroom 206	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	2	Classroom 206	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 206	Pipe	Metal	White	None	0	0	Negative
1	2	Classroom 207	W1	Plaster	White	None	0	0.09	Negative
1	2	Classroom 207	W2	Plaster	White	None	0	0.06	Negative
1	2	Classroom 207	W3	Plaster	White	Efflorescence	3	0.08	Negative
1	2	Classroom 207	W4	Plaster	White	Chipping	1	0.06	Negative
1	2	Classroom 207	Ceiling	Plaster	White	Chipping	3	0.06	Negative
1	2	Classroom 207	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207	Whiteboard frame	Wood	Brown	None	0	0.01	Negative
1	2	Classroom 207	Radiator	Metal	Grey	Chipping	2	1.02	Positive
1	2	Classroom 207	Pipe	Metal	White	None	0	0	Negative
1	2	Boy's New Locker Room	W1	Plaster	White	None	0	0.02	Negative
1	2	Boy's New Locker Room	W2	Sheet Rock	White	Chipping	1	0	Negative
1	2	Boy's New Locker Room	W3	Plaster	White	Cracking	1	0.12	Negative
1	2	Boy's New Locker Room	W4	Plaster	White	None	0	0.16	Negative
1	2	Boy's New Locker Room	W4	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room	Partition	CMU	White	None	0	0	Negative
1	2	Boy's New Locker Room	Ceiling	Plaster	White	Flaking	2	0.1	Negative
1	2	Boy's New Locker Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's New Locker Room	Baseboard	Concrete	Brown	None	0	0.55	Negative
1	2	Boy's New Locker Room	Radiator	Metal	Grey	Chipping	2	0.02	Negative
1	2	Boy's New Locker Room	Pipe	Metal	White	None	0	0	Negative
1	2	Visitor's Locker Room 212	W1	Plaster	White	None	0	1.04	Positive
1	2	Visitor's Locker Room 212	W2	Plaster	White	None	0	0.02	Negative
1	2	Visitor's Locker Room 212	W3	Plaster	White	None	0	0.07	Negative
1	2	Visitor's Locker Room 212	W4	Sheet Rock	White	None	0	0	Negative
1	2	Visitor's Locker Room 212	Ceiling	Plaster	White	Chipping	2	0.05	Negative
1	2	Visitor's Locker Room 212	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Visitor's Locker Room 212	Baseboard	Concrete	Brown	Chipping	50	0.41	Negative
1	2	Visitor's Locker Room 212	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Visitor's Locker Room 212	Pipe	Metal	White	None	0	0	Negative
1	2	Boy's New Locker Room Restroom	W1	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Restroom	W2	Plaster	White	None	0	0.11	Negative
1	2	Boy's New Locker Room Restroom	W3	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Restroom	W4	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Restroom	Ceiling	Plaster	White	None	0	0.06	Negative
1	2	Boy's New Locker Room Restroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's New Locker Room Restroom	Baseboard	Metal	Brown	None	0	0.76	Positive
1	2	Boy's New Locker Room Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Boy's New Locker Room Showers	W1	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Showers	W2	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Showers	W3	Plaster	White	None	0	0.16	Negative
1	2	Boy's New Locker Room Showers	W4	Sheet Rock	White	None	0	0	Negative
1	2	Boy's New Locker Room Showers	Ceiling	Plaster	White	None	0	0.05	Negative
1	2	Boy's New Locker Room Showers	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's New Locker Room Showers	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Boy's New Locker Room Showers	Baseboard	Concrete	Brown	None	0	0.34	Negative
1	2	Boy's New Locker Room Showers	Pipe	Metal	White	None	0	0	Negative
1	2	Upper Level Gymnasium	W1	Brick	Tan	None	0	0.01	Negative
1	2	Upper Level Gymnasium	W1	Brick	White	None	0	0	Negative
1	2	Upper Level Gymnasium	W2	Brick	Tan	None	0	0.01	Negative
1	2	Upper Level Gymnasium	W2	Brick	White	None	0	0.01	Negative
1	2	Upper Level Gymnasium	W3	Brick	Tan	None	0	0.01	Negative
1	2	Upper Level Gymnasium	W3	Brick	White	None	0	0	Negative
1	2	Upper Level Gymnasium	W4	Brick	Tan	None	0	0.02	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Upper Level Gymnasium	W4	Brick	White	None	0	0	Negative
1	2	Upper Level Gymnasium	Ceiling	Plaster	White	None	0	N/A	No Access
1	2	Upper Level Gymnasium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Upper Level Gymnasium	Radiator	Metal	Grey	None	0	0.04	Negative
1	2	Upper Level Gymnasium	Radiator	Metal	Grey	None	0	0.02	Negative
1	2	Upper Level Gymnasium	Radiator	Metal	Grey	None	0	0.03	Negative
1	2	Girl's Locker Room 210	W1	Sheet Rock	White	None	0	0	Negative
1	2	Girl's Locker Room 210	W1	Plaster	White	None	0	0.02	Negative
1	2	Girl's Locker Room 210	W2	Sheet Rock	White	None	0	0	Negative
1	2	Girl's Locker Room 210	W2	Plaster	White	None	0	0.09	Negative
1	2	Girl's Locker Room 210	W3	Plaster	White	None	0	0.04	Negative
1	2	Girl's Locker Room 210	W4	Plaster	White	None	0	0.04	Negative
1	2	Girl's Locker Room 210	Ceiling	Plaster	White	None	0	0.08	Negative
1	2	Girl's Locker Room 210	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Locker Room 210	Column	Plaster	White	None	0	0	Negative
1	2	Girl's Locker Room 210	Radiator	Metal	Grey	Chipping	3	4.15	Positive
1	2	Girl's Locker Room 210	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	2	Girl's Locker Room 210	Pipe	Metal	White	None	0	0	Negative
1	2	Girl's Locker Room 210	Baseboard	Concrete	Blue	None	0	4.77	Positive
1	2	Girl's Locker Room 210	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Gymnasium Office 209A	W1	Plaster	White	None	0	0.06	Negative
1	2	Gymnasium Office 209A	W2	Plaster	White	None	0	0.05	Negative
1	2	Gymnasium Office 209A	W3	Plaster	White	None	0	0.08	Negative
1	2	Gymnasium Office 209A	W4	Plaster	White	None	0	0.07	Negative
1	2	Gymnasium Office 209A	Ceiling	Plaster	White	Chipping	1	0.1	Negative
1	2	Gymnasium Office 209A	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium Office 209A	Pipe	Metal	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Gymnasium Office 209A	Window Frame	Metal	Tan	None	0	0.02	Negative
1	2	Girl's Locker Room Restroom and Showers	W1	Sheet Rock	White	None	0	0	Negative
1	2	Girl's Locker Room Restroom and Showers	W2	Sheet Rock	White	None	0	0	Negative
1	2	Girl's Locker Room Restroom and Showers	W3	Plaster	White	Efflorescence	2	0	Negative
1	2	Girl's Locker Room Restroom and Showers	W4	Plaster	White	Efflorescence	1	0	Negative
1	2	Girl's Locker Room Restroom and Showers	Ceiling	Plaster	White	None	0	0	Negative
1	2	Girl's Locker Room Restroom and Showers	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Locker Room Restroom and Showers	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Girl's Locker Room Restroom and Showers	Ductwork	Metal	White	None	0	0.07	Negative
1	2	Girl's Locker Room Restroom and Showers	Pipe	Metal	White	Chipping	5	0.17	Negative
1	2	Girl's Locker Room Restroom and Showers	Baseboard	Concrete	Brown	None	0	1.93	Positive
1	2	Girl's Locker Room Restroom and Showers	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Gym Storeroom 209B	W1	Brick	Tan	None	0	0.01	Negative
1	2	Gym Storeroom 209B	W1	Brick	Tan	None	0	0	Negative
1	2	Gym Storeroom 209B	W2	Brick	Tan	None	0	0.03	Negative
1	2	Gym Storeroom 209B	W2	Brick	Tan	None	0	0	Negative
1	2	Gym Storeroom 209B	W3	Brick	Tan	None	0	0	Negative
1	2	Gym Storeroom 209B	W3	Brick	Tan	None	0	0.03	Negative
1	2	Gym Storeroom 209B	W4	Brick	Tan	None	0	0.1	Negative
1	2	Gym Storeroom 209B	W4	Brick	Tan	None	0	0	Negative
1	2	Gym Storeroom 209B	Ceiling	Plaster	White	Chipping	1	0.04	Negative
1	2	Gym Storeroom 209B	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gym Storeroom 209B	Ductwork	Metal	White	Chipping	1	8.18	Positive
1	2	Gym Storage Area	W1	Brick	Tan	None	0	0.03	Negative
1	2	Gym Storage Area	W1	Brick	Tan	None	0	0.01	Negative
1	2	Gym Storage Area	W2	Brick	Tan	None	0	0.01	Negative
1	2	Gym Storage Area	W2	Brick	Tan	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Gym Storage Area	W3	Brick	Tan	None	0	0.03	Negative
1	2	Gym Storage Area	W3	Brick	Tan	None	0	0	Negative
1	2	Gym Storage Area	W4	Brick	Tan	None	0	0.01	Negative
1	2	Gym Storage Area	W4	Brick	Tan	None	0	0	Negative
1	2	Gym Storage Area	Ceiling	Plaster	White	Chipping	2	0.03	Negative
1	2	Gym Storage Area	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gym Storage Area	Ductwork	Metal	White	Chipping	1	0.97	Positive
1	2	Gymnasium Office Restroom	W1	Plaster	White	None	0	0.15	Negative
1	2	Gymnasium Office Restroom	W2	Plaster	White	None	0	0.08	Negative
1	2	Gymnasium Office Restroom	W3	Plaster	White	Efflorescence	2	0.01	Negative
1	2	Gymnasium Office Restroom	W4	Plaster	White	None	0	0.07	Negative
1	2	Gymnasium Office Restroom	Ceiling	Plaster	White	None	0	0.06	Negative
1	2	Gymnasium Office Restroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium Office Restroom	Baseboard	Wood	Brown	None	0	0.03	Negative
1	2	Gymnasium Office Restroom	Radiator Cover	Metal	Grey	None	0	0	Negative
1	2	Gymnasium Office Restroom	Window Sill	Wood	Brown	None	0	0.19	Negative
1	2	Hallway from Gym Office to Women's Locker Room	W1	Sheet Rock	Tan	None	0	0	Negative
1	2	Hallway from Gym Office to Women's Locker Room	W2	Sheet Rock	White	None	0	0	Negative
1	2	Hallway from Gym Office to Women's Locker Room	W3	Plaster	White	None	0	0.07	Negative
1	2	Hallway from Gym Office to Women's Locker Room	W4	Plaster	White	None	0	0.07	Negative
1	2	Hallway from Gym Office to Women's Locker Room	W4	Concrete	White	None	0	0.5	Negative
1	2	Hallway from Gym Office to Women's Locker Room	Ceiling	Plaster	White	None	0	0.09	Negative
1	2	Hallway from Gym Office to Women's Locker Room	Floor	Concrete	Glazed	None	0	N/A	N/A
1	2	Hallway from Gym Office to Women's Locker Room	Pipe	Metal	White	None	0	0	Negative
1	2	Hallway from Gym Office to Women's Locker Room	Door Frame	Metal	Brown	None	0	0	Negative
1	2	Classroom 221	W1	Plaster	White	None	0	0.05	Negative
1	2	Classroom 221	W2	Plaster	White	None	0	0.05	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 221	W3	Plaster	White	None	0	0.11	Negative
1	2	Classroom 221	W4	Plaster	White	None	0	0.05	Negative
1	2	Classroom 221	Ceiling	Plaster	White	Chipping	2	0.05	Negative
1	2	Classroom 221	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 221	Pipe	Metal	White	None	0	0	Negative
1	2	Classroom 221	Radiator	Metal	Grey	Chipping	1	0.02	Negative
1	2	Classroom 221	Whiteboard Frame	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 223	W1	Plaster	White	None	0	0.04	Negative
1	2	Classroom 223	W2	Plaster	White	None	0	0.09	Negative
1	2	Classroom 223	W3	Plaster	White	None	0	0.06	Negative
1	2	Classroom 223	W4	Plaster	White	None	0	0.04	Negative
1	2	Classroom 223	Ceiling	Plaster	White	Chipping	3	0.02	Negative
1	2	Classroom 223	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative
1	2	Classroom 223	Radiator	Metal	Grey	Chipping	1	0.02	Negative
1	2	Classroom 223	Pipe	Metal	White	None	0	0	Negative
1	2	Classroom 223 Closet on 221 side	W1	Plaster	Green	None	0	0.05	Negative
1	2	Classroom 223 Closet on 221 side	W2	Plaster	Green	None	0	0.05	Negative
1	2	Classroom 223 Closet on 221 side	W3	Plaster	Green	None	0	0.05	Negative
1	2	Classroom 223 Closet on 221 side	W3	Concrete	Green	None	0	0.03	Negative
1	2	Classroom 223 Closet on 221 side	W4	Plaster	Green	None	0	0.05	Negative
1	2	Classroom 223 Closet on 221 side	Ceiling	Plaster	Green	None	0	0.06	Negative
1	2	Classroom 223 Closet on 221 side	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223 Closet on 221 side	Pipe	Metal	White	None	0	0	Negative
1	2	Classroom 223 Closet on 221 side	Radiator	Metal	White	Chipping	1	0.04	Negative
1	2	Classroom 223 Closet on windows side	W1	Plaster	Green	Chipping	3	0.08	Negative
1	2	Classroom 223 Closet on windows side	W2	Plaster	Green	Flaking	1	0.08	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 223 Closet on windows side	W3	Plaster	Green	Flaking	1	0.06	Negative
1	2	Classroom 223 Closet on windows side	W4	Plaster	Green	None	0	0.07	Negative
1	2	Classroom 223 Closet on windows side	Ceiling	Plaster	Green	Flaking	1	0.06	Negative
1	2	Classroom 223 Closet on windows side	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223 Closet on windows side	Radiator	Metal	White	Chipping	1	0.01	Negative
1	2	Classroom 223 Closet on windows side	Pipe	Metal	White	None	0	0	Negative
1	2	Classroom 224	W1	Plaster	Blue	None	0	0.01	Negative
1	2	Classroom 224	W1	Plaster	Green	None	0	0.03	Negative
1	2	Classroom 224	W2	Plaster	Blue	None	0	0.03	Negative
1	2	Classroom 224	W3	Plaster	Green	None	0	0.05	Negative
1	2	Classroom 224	W4	Plaster	Blue	None	0	0.1	Negative
1	2	Classroom 224	Ceiling	Plaster	White	Chipping	2	0.08	Negative
1	2	Classroom 224	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative
1	2	Classroom 224	Baseboard	Concrete	Brown	None	0	0.04	Negative
1	2	Classroom 224	Pipe	Metal	White	None	0	0	Negative
1	2	Girl's Restroom across from Classroom 206	W1	Plaster	White	None	0	0	Negative
1	2	Girl's Restroom across from Classroom 206	W2	Plaster	White	None	0	0	Negative
1	2	Girl's Restroom across from Classroom 206	W3	Plaster	White	None	0	0.14	Negative
1	2	Girl's Restroom across from Classroom 206	W4	Plaster	White	None	0	0.1	Negative
1	2	Girl's Restroom across from Classroom 206	Ceiling	Plaster	White	Chipping	2	0.04	Negative
1	2	Girl's Restroom across from Classroom 206	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom across from Classroom 206	Pipe	Metal	White	Chipping	1	0.09	Negative
1	2	Girl's Restroom across from Classroom 206	Radiator Cover	Metal	Brown	None	0	0.06	Negative
1	2	Women's Lounge 218	W1	Plaster	White	None	0	0.21	Negative
1	2	Women's Lounge 218	W2	Plaster	White	None	0	0.1	Negative
1	2	Women's Lounge 218	W2	Sheet Rock	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Women's Lounge 218	W3	Plaster	White	None	0	0.16	Negative
1	2	Women's Lounge 218	W4	Plaster	White	None	0	0.17	Negative
1	2	Women's Lounge 218	Ceiling	Plaster	White	Chipping	1	0.06	Negative
1	2	Women's Lounge 218	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Lounge 218	Ductwork	Metal	White	None	0	0	Negative
1	2	Women's Lounge 218	Radiator	Metal	Grey	None	0	0	Negative
1	2	Women's Lounge 218	Pipe	Metal	White	None	0	0	Negative
1	2	Women's Lounge 218	Baseboard	Wood	Brown	None	0	0.08	Negative
1	2	Women's Lounge Restroom	W1	Plaster	White	None	0	0.17	Negative
1	2	Women's Lounge Restroom	W2	Plaster	White	Efflorescence	2	0.09	Negative
1	2	Women's Lounge Restroom	W3	Plaster	White	None	0	0	Negative
1	2	Women's Lounge Restroom	W4	Plaster	White	None	0	0.16	Negative
1	2	Women's Lounge Restroom	Ceiling	Plaster	White	Chipping	3	0.2	Negative
1	2	Women's Lounge Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Lounge Restroom	Pipe	Metal	White	None	0	0.24	Negative
1	2	Electrical Room 219	W1	Plaster	Green	None	0	0.09	Negative
1	2	Electrical Room 219	W2	Plaster	Green	Cracking	3	0.09	Negative
1	2	Electrical Room 219	W3	Plaster	Green	Chipping	3	0.1	Negative
1	2	Electrical Room 219	W4	Plaster	Green	Cracking	1	0.06	Negative
1	2	Electrical Room 219	Ceiling	Plaster	Green	None	0	0.13	Negative
1	2	Electrical Room 219	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	IDF-3 Server Closet 220	W1	Plaster	Green	None	0	0.03	Negative
1	2	IDF-3 Server Closet 220	W2	Plaster	Green	None	0	0.1	Negative
1	2	IDF-3 Server Closet 220	W2	Wood	White	None	0	0	Negative
1	2	IDF-3 Server Closet 220	W3	Plaster	Green	None	0	0.12	Negative
1	2	IDF-3 Server Closet 220	W3	Wood	White	None	0	0	Negative
1	2	IDF-3 Server Closet 220	W4	Plaster	Green	None	0	0.09	Negative

		Dates: 05/22/2023-06/22/2023	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Zak Khalil #007233	<b>Academy at Palumbo</b>							
		Inspection Company: Viva EHS	<b>1100 Catharine St, Philadelphia PA 19147</b>							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	2	IDF-3 Server Closet 220	W4	Wood	White	None	0	0	Negative	
1	2	IDF-3 Server Closet 220	Ceiling	Plaster	Green	Cracking	1	0.11	Negative	
1	2	IDF-3 Server Closet 220	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom across from Classroom 201	W1	Plaster	White	Efflorescence	5	0.15	Negative	
1	2	Boy's Restroom across from Classroom 201	W2	Plaster	White	None	0	0	Negative	
1	2	Boy's Restroom across from Classroom 201	W3	Plaster	White	None	0	0.17	Negative	
1	2	Boy's Restroom across from Classroom 201	W4	Plaster	White	Efflorescence	1	0	Negative	
1	2	Boy's Restroom across from Classroom 201	Ceiling	Plaster	White	Chipping	5	0	Negative	
1	2	Boy's Restroom across from Classroom 201	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Boy's Restroom across from Classroom 201	Radiator	Metal	Grey	Chipping	1	0.02	Negative	
1	2	Boy's Restroom across from Classroom 201	Pipe	Metal	White	None	0	0	Negative	
1	2	Room 227 Custodial Closet across from Classroom 227	W1	Plaster	White	None	0	2.24	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	W2	Plaster	White	None	0	2.36	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	W3	Plaster	White	None	0	1.91	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	W4	Plaster	White	None	0	2.91	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	Ceiling	Plaster	White	None	0	0.12	Negative	
1	2	Room 227 Custodial Closet across from Classroom 227	Floor	Concrete	Brown	None	0	>10	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	Pipe	Metal	White	None	0	0.06	Negative	
1	2	Room 227 Custodial Closet across from Classroom 227	Floor	Concrete	Grey	None	0	0.79	Positive	
1	2	Room 227 Custodial Closet across from Classroom 227	Radiator	Metal	Grey	Chipping	1	0.08	Negative	
1	2	Room 227 Custodial Closet across from Classroom 227	Baseboard	Concrete	Grey	None	0	2.43	Positive	
1	2	Room 228 Electrical	W1	Plaster	Green	Chipping	1	0.06	Negative	
1	2	Room 228 Electrical	W2	Plaster	Green	Chipping	1	0.05	Negative	
1	2	Room 228 Electrical	W3	Plaster	Green	None	0	0.05	Negative	
1	2	Room 228 Electrical	W4	Plaster	Green	Chipping	2	0.09	Negative	
1	2	Room 228 Electrical	Ceiling	Plaster	Green	Chipping	2	0.07	Negative	
1	2	Room 228 Electrical	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Auditorium Balcony- Room 232	W1	Plaster	Grey	Cracking	1	0.06	Negative
1	2	Auditorium Balcony- Room 232	W2	Balcony Overhang	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium Balcony- Room 232	W3	Plaster	Grey	None	0	0.17	Negative
1	2	Auditorium Balcony- Room 232	W4	Plaster	Grey	Chipping	5	0.02	Negative
1	2	Auditorium Balcony- Room 232	Ceiling	Plaster	White	Chipping	5	0.06	Negative
1	2	Auditorium Balcony- Room 232	Trim	Decorative Plaster	White	Chipping	3	0.09	Negative
1	2	Auditorium Balcony- Room 232	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium Balcony- Room 232	Pipe	Metal	White	None	0	0	Negative
1	2	Hallway from Elevator No. 1 to Room 207	W1	Plaster	White	Cracking	5	0.22	Negative
1	2	Hallway from Elevator No. 1 to Room 207	W2	Plaster	White	None	0	0.3	Negative
1	2	Hallway from Elevator No. 1 to Room 207	W3	Sheet Rock	White	Chipping	1	0.28	Negative
1	2	Hallway from Elevator No. 1 to Room 207	W4	Plaster	White	Alligatoring	10	0.18	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Ceiling	Plaster	White	Chipping	10	0.03	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Hallway from Elevator No. 1 to Room 207	Radiator	Metal	Grey	Chipping	2	0.21	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Pipe Cover	Metal	White	Chipping	5	0.31	Negative
1	2	Hallway from Elevator No. 1 to Room 207	trim	Concrete	Grey	None	0	0	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Door	Metal	Brown	None	0	0.07	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Door Frame	Metal	Brown	None	0	0.07	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Door	Metal	Brown	Chipping	5	0.04	Negative
1	2	Hallway from Elevator No. 1 to Room 207	Door Frame	Metal	Brown	Chipping	5	0.02	Negative
1	2	Hallway along Classrooms 221 to 223	W1	Plaster	White	None	0	0.23	Negative
1	2	Hallway along Classrooms 221 to 223	W2	Plaster	White	None	0	0.19	Negative
1	2	Hallway along Classrooms 221 to 223	W3	Plaster	White	Flaking	1	0.34	Negative
1	2	Hallway along Classrooms 221 to 223	W4	Plaster	White	None	0	0.28	Negative
1	2	Hallway along Classrooms 221 to 223	Ceiling	Plaster	White	None	0	0.02	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Hallway along Classrooms 221 to 223	trim	Concrete	Grey	Chipping	5	0	Negative
1	2	Hallway along Classrooms 221 to 223	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Hallway along Rooms 229 to 231	W1	Plaster	White	None	0	0.17	Negative
1	2	Hallway along Rooms 229 to 231	W2	Plaster	White	None	0	0.14	Negative
1	2	Hallway along Rooms 229 to 231	W3	Plaster	White	Cracking	2	0.15	Negative
1	2	Hallway along Rooms 229 to 231	W4	Plaster	White	None	0	0.16	Negative
1	2	Hallway along Rooms 229 to 231	Ceiling	Plaster	White	None	0	0.01	Negative
1	2	Hallway along Rooms 229 to 231	Radiator	Metal	No Access	None	0	N/A	N/A
1	2	Hallway along Rooms 229 to 231	Pipe Cover	Metal	White	Cracking	1	0.25	Negative
1	2	Hallway along Rooms 229 to 231	trim	Concrete	Grey	None	0	0.01	Negative
1	2	Hallway along Rooms 229 to 231	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Hallway along Gymnasium and Room 212	W1	Plaster	White	Cracking	10	0.16	Negative
1	2	Hallway along Gymnasium and Room 212	W2	Plaster	White	None	0	0.19	Negative
1	2	Hallway along Gymnasium and Room 212	W3	Plaster	White	Flaking	40	0.21	Negative
1	2	Hallway along Gymnasium and Room 212	W4	Plaster	White	None	0	0.17	Negative
1	2	Hallway along Gymnasium and Room 212	Ceiling	Plaster	White	Alligatoring	20	0.04	Negative
1	2	Hallway along Gymnasium and Room 212	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Hallway along Gymnasium and Room 212	Radiator	Metal	Grey	Chipping	10	0.06	Negative
1	2	Hallway along Gymnasium and Room 212	Radiator Cover	Metal	White	None	0	0	Negative
1	2	Hallway along Gymnasium and Room 212	Pipe Cover	Metal	White	Chipping	5	0.32	Negative
1	2	Pipe Shaft between Girl's Restroom and Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Pipe Shaft between Girl's Restroom and Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Pipe Shaft between Girl's Restroom and Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Pipe Shaft between Girl's Restroom and Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Pipe Shaft between Girl's Restroom and Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Pipe Shaft between Girl's Restroom and Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairwell next to Balcony and Room 231	W1	Plaster	White	None	0	0.19	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairwell next to Balcony and Room 231	W2	Plaster	White	None	0	0.05	Negative
1	2	Stairwell next to Balcony and Room 231	W3	Plaster	White	Chipping	1	0.19	Negative
1	2	Stairwell next to Balcony and Room 231	W4	Plaster	White	Cracking	5	0.06	Negative
1	2	Stairwell next to Balcony and Room 231	Ceiling	Plaster	White	None	0	0.03	Negative
1	2	Stairwell next to Balcony and Room 231	Stair Riser	Concrete	Grey	None	0	0.42	Negative
1	2	Stairwell next to Balcony and Room 231	Spindle	Concrete	Grey	None	0	5.15	Positive
1	2	Stairwell next to Balcony and Room 231	Stringer	Metal	Grey	None	0	0.59	Negative
1	2	Stairwell next to Balcony and Room 231	Newel Post	Concrete	Grey	Friction	5	3.26	Positive
1	2	Stairwell next to Balcony and Room 231	trim	Concrete	Grey	None	0	0.42	Negative
1	2	Stairwell next to Balcony and Room 231	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Stairwell near Locker Room	W1	Plaster	White	None	0	0.38	Negative
1	2	Stairwell near Locker Room	W2	Plaster	White	None	0	0.24	Negative
1	2	Stairwell near Locker Room	W3	Plaster	White	Efflorescence	1	0.33	Negative
1	2	Stairwell near Locker Room	W4	Plaster	White	Moisture Dama	4	0.22	Negative
1	2	Stairwell near Locker Room	Ceiling	Plaster	White	Chipping	2	0.03	Negative
1	2	Stairwell near Locker Room	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	2	Stairwell near Locker Room	Spindle	Metal	Grey	Chipping	2	3.52	Positive
1	2	Stairwell near Locker Room	Stringer	Concrete	Grey	None	0	0.45	Negative
1	2	Stairwell near Locker Room	Newel Post	Concrete	Grey	Friction	10	5.48	Positive
1	2	Stairwell near Locker Room	trim	Concrete	Grey	None	0	0.24	Negative
1	2	Stairwell near Locker Room	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Middle Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Middle Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Middle Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Middle Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Middle Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Middle Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairs to Storeroom (former Girl's Locker Room)	W1	Plaster	White	None	0	0.04	Negative
1	2	Stairs to Storeroom (former Girl's Locker Room)	W2	Concrete	White	None	0	0.05	Negative
1	2	Stairs to Storeroom (former Girl's Locker Room)	W4	Brick	Tan	None	0	0	Negative
1	2	Stairs to Storeroom (former Girl's Locker Room)	W4	Concrete	White	None	0	4.14	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	Ceiling	Plaster	White	None	0	0.1	Negative
1	2	Stairs to Storeroom (former Girl's Locker Room)	Floor	Metal	Tan	None	0	6.14	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	Stair Riser	Concrete	Tan	None	0	0.59	Negative
1	2	Stairs to Storeroom (former Girl's Locker Room)	Stringer	Concrete	Tan	None	0	0.79	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	Newel Post	Metal	Tan	Chipping	1	3.64	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	Spindle	Metal	Tan	Chipping	1	2.47	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	Handrail	Metal	Tan	Chipping	1	2.17	Positive
1	2	Stairs to Storeroom (former Girl's Locker Room)	I-Beam	Metal	White	None	0	2.24	Positive
1	2	Stairs from Hall to Girl's Locker Room Area	W1	Plaster	White	Cracking	5	0.15	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	W2	Plaster	White	None	0	0.26	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	W3	Plaster	White	None	0	0.23	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	W4	Plaster	White	None	0	0.2	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	Ceiling	Plaster	White	Chipping	5	0.06	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Stairs from Hall to Girl's Locker Room Area	Door Frame	Metal	Brown	None	0	0.04	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	Stair Riser	Concrete	Grey	None	0	0.48	Negative
1	2	Stairs from Hall to Girl's Locker Room Area	trim	Concrete	Grey	Chipping	10	0.53	Negative
1	2	Stairs from Hallway up to Gymnasium	W1	Plaster	White	Chipping	4	0.24	Negative
1	2	Stairs from Hallway up to Gymnasium	W2	Plaster	White	None	0	0.14	Negative
1	2	Stairs from Hallway up to Gymnasium	W3	Plaster	White	Chipping	1	0.12	Negative
1	2	Stairs from Hallway up to Gymnasium	W4	Plaster	White	Chipping	4	0.16	Negative
1	2	Stairs from Hallway up to Gymnasium	Ceiling	Plaster	White	None	0	0.07	Negative
1	2	Stairs from Hallway up to Gymnasium	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairs from Hallway up to Gymnasium	trim	Concrete	Grey	None	0	0.37	Negative
1	2	Stairs from Hallway up to Gymnasium	Stair Riser	Concrete	Grey	None	0	0.55	Negative
1	2	Stairs from General Office over Stage Right to St	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairs from General Office over Stage Right to St	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairs from General Office over Stage Right to St	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairs from General Office over Stage Right to St	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairs from General Office over Stage Right to St	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairs from General Office over Stage Right to St	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Stairwell near Elevator No. 1	W1	Plaster	White	None	0	0.18	Negative
1	2	Stairwell near Elevator No. 1	W2	Plaster	White	None	0	0.21	Negative
1	2	Stairwell near Elevator No. 1	W3	Plaster	White	Cracking	3	19	Positive
1	2	Stairwell near Elevator No. 1	W4	Plaster	White	None	0	0.22	Negative
1	2	Stairwell near Elevator No. 1	Ceiling	Plaster	White	Moisture Damage	10	0.05	Negative
1	2	Stairwell near Elevator No. 1	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Stairwell near Elevator No. 1	Newel Post	Concrete	Grey	Friction	5	1.82	Positive
1	2	Stairwell near Elevator No. 1	Stringer	Concrete	Grey	None	0	0.55	Negative
1	2	Stairwell near Elevator No. 1	Stair Riser	Concrete	Grey	None	0	0.19	Negative
1	2	Stairwell near Elevator No. 1	trim	Concrete	Grey	None	0	0.02	Negative
1	2	Stairwell near Elevator No. 1	Spindle	Concrete	Grey	None	0	2.33	Positive
1	2	Stairwell near Elevator No. 1	Pipe	Metal	Grey	None	0	0	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	W1	Metal	White	None	0	0.09	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	W2	Plaster	White	None	0	0.2	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	W3	Plaster	White	None	0	0.21	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	W4	Plaster	White	None	0	0.08	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	Ceiling	Plaster	White	None	0	0.15	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	Floor	Concrete	Glazed/Unpainted	None	0	N/A	N/A
1	2	Stairwell near Gymnasium and Elevator No. 2	Newel Post	Concrete	Grey	Friction	10	4.84	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairwell near Gymnasium and Elevator No. 2	Stringer	Concrete	Grey	None	0	0.41	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	Stair Riser	Concrete	Grey	None	0	0.23	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	trim	Concrete	Grey	None	0	0.47	Negative
1	2	Stairwell near Gymnasium and Elevator No. 2	Spindle	Metal	Grey	None	0	2.12	Positive
1	2	Stairwell near Gymnasium and Elevator No. 2	Pipe	Metal	White	None	0	0	Negative
1	3	Room 301 School Store	W1	Plaster	White	None	0	0.09	Negative
1	3	Room 301 School Store	W2	Plaster	White	None	0	0.18	Negative
1	3	Room 301 School Store	W3	Plaster	White	None	0	0.11	Negative
1	3	Room 301 School Store	W4	Plaster	White	None	0	0.14	Negative
1	3	Room 301 School Store	Radiator	Metal	Grey	Chipping	1	0.03	Negative
1	3	Room 301 School Store	Ceiling	Plaster	White	None	0	0.09	Negative
1	3	Room 301 School Store	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Dean's Office 302	W1	Plaster	White	Flaking	3	0.1	Negative
1	3	Dean's Office 302	W2	Sheet Rock	White	None	0	0	Negative
1	3	Dean's Office 302	W3	Plaster	White	None	0	0.11	Negative
1	3	Dean's Office 302	W4	Plaster	White	Flaking	2	0.06	Negative
1	3	Dean's Office 302	Radiator	Metal	Grey	Chipping	2	0.1	Negative
1	3	Dean's Office 302	Ceiling	Plaster	White	Alligatoring	5	0.06	Negative
1	3	Dean's Office 302	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Counselor's Office 303	W1	Plaster	White	None	0	0.05	Negative
1	3	Counselor's Office 303	W2	Plaster	White	None	0	0.17	Negative
1	3	Counselor's Office 303	W3	Plaster	White	None	0	0.16	Negative
1	3	Counselor's Office 303	W4	Sheet Rock	White	None	0	0	Negative
1	3	Counselor's Office 303	Radiator	Metal	Grey	Chipping	1	0.09	Negative
1	3	Counselor's Office 303	Ceiling	Plaster	White	Chipping	2	0.05	Negative
1	3	Counselor's Office 303	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	W1	Plaster	White	None	0	0.18	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 304	W2	Plaster	White	None	0	0.14	Negative
1	3	Classroom 304	W3	Plaster	White	Efflorescence	15	0.09	Negative
1	3	Classroom 304	W4	CMU	White	None	0	0.02	Negative
1	3	Classroom 304	Pipe	Metal	White	None	0	0	Negative
1	3	Classroom 304	Ceiling	Plaster	White	Chipping	4	0.04	Negative
1	3	Classroom 304	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Computer Support Office off Classroom 304	W1	CMU	Yellow	None	0	0.07	Negative
1	3	Computer Support Office off Classroom 304	W1	Plaster	Yellow	None	0	0.13	Negative
1	3	Computer Support Office off Classroom 304	W2	CMU	Yellow	None	0	0.05	Negative
1	3	Computer Support Office off Classroom 304	W3	Plaster	White	None	0	0	Negative
1	3	Computer Support Office off Classroom 304	W3	Plaster	Yellow	None	0	0.02	Negative
1	3	Computer Support Office off Classroom 304	W4	Plaster	Yellow	Flaking	2	0.06	Negative
1	3	Computer Support Office off Classroom 304	Door Frame	Metal	Yellow	Chipping	1	0.06	Negative
1	3	Computer Support Office off Classroom 304	Ceiling	Plaster	White	Chipping	3	0.05	Negative
1	3	Computer Support Office off Classroom 304	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305	W1	Plaster	White	Chipping	1	0.03	Negative
1	3	Classroom 305	W2	Plaster	White	None	0	0.09	Negative
1	3	Classroom 305	W3	Plaster	White	Efflorescence	3	0.05	Negative
1	3	Classroom 305	W4	Plaster	White	None	0	0.08	Negative
1	3	Classroom 305	Radiator Cover	Metal	White	None	0	0	Negative
1	3	Classroom 305	Radiator	Metal	Grey	None	0	0.02	Negative
1	3	Classroom 305	Pipe	Metal	White	Chipping	1	0.14	Negative
1	3	Classroom 305	Whiteboard Frame	Wood	Brown	Chipping	1	0.03	Negative
1	3	Classroom 305	Phonebox	Metal	Brown	None	0	0.02	Negative
1	3	Classroom 305	Ceiling	Plaster	White	Chipping	5	0	Negative
1	3	Classroom 305	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 306	W1	Plaster	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 306	W2	Plaster	White	None	0	0.11	Negative
1	3	Classroom 306	W3	Plaster	White	Efflorescence	2	0.07	Negative
1	3	Classroom 306	W4	Plaster	White	None	0	0	Negative
1	3	Classroom 306	Whiteboard Frame	Wood	Brown	Chipping	1	0.04	Negative
1	3	Classroom 306	Radiator	Metal	Grey	Chipping	1	0.01	Negative
1	3	Classroom 306	Pipe	Metal	White	None	0	0	Negative
1	3	Classroom 306	Phonebox	Metal	Brown	None	0	0.01	Negative
1	3	Classroom 306	Ceiling	Plaster	White	None	0	0.01	Negative
1	3	Classroom 306	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307	W1	Plaster	Orange	None	0	0.05	Negative
1	3	Classroom 307	W2	Plaster	Orange	None	0	0.13	Negative
1	3	Classroom 307	W2	Plaster	White	None	0	0.18	Negative
1	3	Classroom 307	W3	Plaster	Grey	Efflorescence	5	0.09	Negative
1	3	Classroom 307	W4	Plaster	Grey	None	0	0.19	Negative
1	3	Classroom 307	Whiteboard Frame	Wood	Brown	Chipping	1	0.13	Negative
1	3	Classroom 307	Radiator	Metal	Grey	Chipping	1	0.1	Negative
1	3	Classroom 307	Phonebox	Metal	Brown	None	0	0.03	Negative
1	3	Classroom 307	Ceiling	Plaster	White	Alligatoring	3	0.05	Negative
1	3	Classroom 307	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Storeroom (former Girl's Locker Room)	W1	Plaster	White	None	0	0.05	Negative
1	3	Storeroom (former Girl's Locker Room)	W1	Brick	Tan	None	0	0	Negative
1	3	Storeroom (former Girl's Locker Room)	W2	Plaster	White	Chipping	2	0.07	Negative
1	3	Storeroom (former Girl's Locker Room)	W2	Brick	Tan	None	0	0.02	Negative
1	3	Storeroom (former Girl's Locker Room)	W3	Plaster	White	Chipping	3	0.08	Negative
1	3	Storeroom (former Girl's Locker Room)	W3	Brick	Tan	None	0	0.01	Negative
1	3	Storeroom (former Girl's Locker Room)	W4	Concrete	White	None	0	2.95	Positive
1	3	Storeroom (former Girl's Locker Room)	W4	Brick	Tan	None	0	0.03	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Storeroom (former Girl's Locker Room)	Ceiling	Plaster	White	Chipping	2	0.12	Negative
1	3	Storeroom (former Girl's Locker Room)	Floor	Concrete	Grey	Chipping	10	0.05	Negative
1	3	Storeroom (former Girl's Locker Room)	Radiator	Metal	White	None	0	0.03	Negative
1	3	Storeroom (former Girl's Locker Room)	Pipe	Metal	White	None	0	0.19	Negative
1	3	Storeroom (former Girl's Locker Room)	Baseboard	Concrete	Tan	None	0	3.94	Positive
1	3	Storeroom (former Girl's Locker Room)	Divider	Sheet Rock	White	None	0	0	Negative
1	3	Storeroom (former Girl's Locker Room)	Divider	Sheet Rock	Tan	None	0	0	Negative
1	3	Storeroom (former Girl's Locker Room)	Ceiling	Concrete	White	None	0	4.01	Positive
1	3	Storeroom (former Girl's Locker Room)	Trench cover	Metal	Grey	None	0	4.32	Positive
1	3	Storeroom (former Girl's Locker Room)	Window Rail	Metal	Tan	Chipping	5	6.7	Positive
1	3	Storeroom (former Girl's Locker Room)	I-Beam	Metal	White	None	0	2.18	Positive
1	3	Gymnasium Balcony	W1	Brick	White	None	0	0	Negative
1	3	Gymnasium Balcony	W2	Brick	White	None	0	0	Negative
1	3	Gymnasium Balcony	W3	Brick	White	None	0	0	Negative
1	3	Gymnasium Balcony	W3	Plaster	Brown	None	0	0.03	Negative
1	3	Gymnasium Balcony	W4	Brick	White	None	0	0	Negative
1	3	Gymnasium Balcony	Ceiling	Plaster	White	None	0	0.09	Negative
1	3	Gymnasium Balcony	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Gymnasium Balcony	Handrail	Metal	Black	None	0	1.21	Positive
1	3	Gymnasium Balcony	Bench Base	Plaster	Brown	None	0	0.04	Negative
1	3	Gymnasium Balcony	Handrail	Metal	Black	None	0	2.05	Positive
1	3	Gymnasium Balcony	Pipe	Metal	White	None	0	0	Negative
1	3	Cardio Room 312	W1	Plaster	White	None	0	0.11	Negative
1	3	Cardio Room 312	W2	Plaster	White	None	0	0.14	Negative
1	3	Cardio Room 312	W2	Plaster	White	Chipping	3	0.19	Negative
1	3	Cardio Room 312	W4	Sheet Rock	White	None	0	0	Negative
1	3	Cardio Room 312	Pipe	Metal	White	Chipping	1	0	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Cardio Room 312	Baseboard	Concrete	Grey	Chipping	1	0.36	Negative
1	3	Cardio Room 312	Door Frame	Wood	Brown	None	0	0.06	Negative
1	3	Cardio Room 312	Ceiling	Plaster	White	Chipping	3	0.09	Negative
1	3	Cardio Room 312	Floor	Concrete	Grey	Chipping	10	0	Negative
1	3	Boy's Restroom across from Classroom 306	W1	Plaster	White	Efflorescence	5	0.03	Negative
1	3	Boy's Restroom across from Classroom 306	W2	Plaster	White	Efflorescence	1	0.03	Negative
1	3	Boy's Restroom across from Classroom 306	W3	Plaster	White	Chipping	2	0.07	Negative
1	3	Boy's Restroom across from Classroom 306	W4	Plaster	White	None	0	0.19	Negative
1	3	Boy's Restroom across from Classroom 306	Radiator	Metal	Grey	None	0	0.09	Negative
1	3	Boy's Restroom across from Classroom 306	Pipe	Metal	White	None	0	0	Negative
1	3	Boy's Restroom across from Classroom 306	Window Sill	Wood	Brown	Chipping	1	0.01	Negative
1	3	Boy's Restroom across from Classroom 306	Ceiling	Plaster	White	Chipping	5	0	Negative
1	3	Boy's Restroom across from Classroom 306	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Custodial Closet 315	W1	Plaster	White	Chipping	2	0.17	Negative
1	3	Custodial Closet 315	W1	Plaster	Green	Chipping	2	0.09	Negative
1	3	Custodial Closet 315	W2	Plaster	White	Chipping	1	0.17	Negative
1	3	Custodial Closet 315	W3	Plaster	White	Chipping	10	0.12	Negative
1	3	Custodial Closet 315	W3	Plaster	Green	Chipping	1	0.11	Negative
1	3	Custodial Closet 315	W4	Plaster	White	Chipping	3	0.1	Negative
1	3	Custodial Closet 315	Pipe	Metal	White	None	0	0	Negative
1	3	Custodial Closet 315	Radiator	Metal	Grey	Chipping	1	0	Negative
1	3	Custodial Closet 315	Baseboard	Concrete	Black	None	0	6.57	Positive
1	3	Custodial Closet 315	Ceiling	Plaster	White	Chipping	5	0.13	Negative
1	3	Custodial Closet 315	Floor	Concrete	Black	Chipping	10	0.04	Negative
1	3	Weight Lifting Room 311	W1	Plaster	White	Chipping	2	0.18	Negative
1	3	Weight Lifting Room 311	W2	Plaster	White	Chipping	1	0.16	Negative
1	3	Weight Lifting Room 311	W2	Sheet Rock	White	None	0	0.01	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Weight Lifting Room 311	W3	Plaster	White	Efflorescence	3	0.11	Negative
1	3	Weight Lifting Room 311	W4	Plaster	White	Chipping	1	0.32	Negative
1	3	Weight Lifting Room 311	Pipe	Metal	White	None	0	0	Negative
1	3	Weight Lifting Room 311	Pipe	Metal	White	None	0	0	Negative
1	3	Weight Lifting Room 311	Radiator Cover	Metal	White	None	0	5.8	Positive
1	3	Weight Lifting Room 311	Baseboard	Concrete	Grey	None	0	0.43	Negative
1	3	Weight Lifting Room 311	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	Weight Lifting Room 311	Ceiling	Plaster	White	Flaking	10	0.01	Negative
1	3	Weight Lifting Room 311	Floor	Concrete	Glazed	None	0	N/A	N/A
1	3	Classroom 321	W1	Plaster	Blue	None	0	0.05	Negative
1	3	Classroom 321	W2	Plaster	Blue	None	0	0.11	Negative
1	3	Classroom 321	W3	Plaster	Blue	None	0	0.012	Negative
1	3	Classroom 321	W4	Plaster	Blue	None	0	0.1	Negative
1	3	Classroom 321	Ceiling	Plaster	White	Chipping	2	0.02	Negative
1	3	Classroom 321	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 321	Radiator	Metal	No Access	No Access	No Access	No Access	No Access
1	3	Classroom 321	Radiator Cover	Metal	Brown	None	0	0.06	Negative
1	3	Classroom 321	Pipe	Metal	Silver	Chipping	1	0.03	Negative
1	3	Men's Lounge 318	W1	Plaster	White	None	0	0.04	Negative
1	3	Men's Lounge 318	W2	Plaster	White	None	0	0.18	Negative
1	3	Men's Lounge 318	W3	Sheet Rock	White	None	0	0	Negative
1	3	Men's Lounge 318	W3	Plaster	White	None	0	0.22	Negative
1	3	Men's Lounge 318	W4	Plaster	White	Cracking	2	0.22	Negative
1	3	Men's Lounge 318	Baseboard	Wood	Brown	None	0	0.06	Negative
1	3	Men's Lounge 318	Radiator	Metal	Grey	Chipping	1	0	Negative
1	3	Men's Lounge 318	Ductwork	Metal	White	None	0	0	Negative
1	3	Men's Lounge 318	Pipe	Metal	White	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Men's Lounge 318	Ceiling	Plaster	White	Chipping	2	0.06	Negative
1	3	Men's Lounge 318	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Book Closet across from Classroom 305	W1	Plaster	Green	None	0	0.07	Negative
1	3	Book Closet across from Classroom 305	W2	Plaster	Green	None	0	0.13	Negative
1	3	Book Closet across from Classroom 305	W3	Plaster	Green	None	0	0.06	Negative
1	3	Book Closet across from Classroom 305	W4	Plaster	Green	None	0	0.05	Negative
1	3	Book Closet across from Classroom 305	Ceiling	Plaster	Green	None	0	0	Negative
1	3	Book Closet across from Classroom 305	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Book Closet across from Classroom 305	Baseboard	Concrete	Grey	None	0	0.01	Negative
1	3	Men's Lounge Restroom	W1	Plaster	White	None	0	0.17	Negative
1	3	Men's Lounge Restroom	W2	Plaster	White	None	0	0.1	Negative
1	3	Men's Lounge Restroom	W3	Plaster	White	None	0	0.08	Negative
1	3	Men's Lounge Restroom	W4	Plaster	White	None	0	0.13	Negative
1	3	Men's Lounge Restroom	Pipe	Metal	White	None	0	0	Negative
1	3	Men's Lounge Restroom	Ceiling	Plaster	White	Chipping	1	0.08	Negative
1	3	Men's Lounge Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 319	W1	Plaster	Green	Chipping	10	0.06	Negative
1	3	Electrical Room 319	W2	Plaster	Green	Chipping	5	0.05	Negative
1	3	Electrical Room 319	W3	Plaster	Green	Chipping	5	0.07	Negative
1	3	Electrical Room 319	W4	Plaster	Green	Chipping	3	0.1	Negative
1	3	Electrical Room 319	Ceiling	Plaster	White	Chipping	3	0.03	Negative
1	3	Electrical Room 319	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 319	Baseboard	Concrete	Grey	None	0	0	Negative
1	3	Classroom 322	W1	Plaster	White	None	0	0.06	Negative
1	3	Classroom 322	W2	Plaster	White	None	0	0.15	Negative
1	3	Classroom 322	W3	Plaster	White	None	0	0.07	Negative
1	3	Classroom 322	W4	Plaster	White	Efflorescence	1	0.15	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 322	Ceiling	Plaster	White	None	0	0.05	Negative
1	3	Classroom 322	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 322	Radiator	Metal	Grey	Chipping	1	0.04	Negative
1	3	Classroom 322	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative
1	3	Classroom 322	Pipe	Metal	White	None	0	0	Negative
1	3	Classroom 323	W1	Plaster	White	None	0	0.05	Negative
1	3	Classroom 323	W2	Plaster	White	None	0	0.06	Negative
1	3	Classroom 323	W3	Plaster	White	None	0	0.08	Negative
1	3	Classroom 323	W4	Plaster	White	None	0	0.13	Negative
1	3	Classroom 323	Ceiling	Plaster	White	None	0	0.02	Negative
1	3	Classroom 323	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 323	Radiator	Metal	Grey	Chipping	1	0.02	Negative
1	3	Classroom 323	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative
1	3	Classroom 323	Pipe	Metal	White	None	0	0.01	Negative
1	3	Classroom 324	W1	Plaster	White	None	0	0.09	Negative
1	3	Classroom 324	W2	Plaster	White	None	0	0.18	Negative
1	3	Classroom 324	W3	Plaster	White	Chipping	3	0.23	Negative
1	3	Classroom 324	W4	Plaster	White	None	0	0.07	Negative
1	3	Classroom 324	Ceiling	Plaster	White	None	0	0.01	Negative
1	3	Classroom 324	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 324	Radiator	Metal	Grey	Chipping	1	0.04	Negative
1	3	Classroom 324	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative
1	3	Classroom 324	Pipe	Metal	Silver	Chipping	1	0.08	Negative
1	3	Girl's Restroom across from Classroom 302	W1	Plaster	White	Efflorescence	3	0.24	Negative
1	3	Girl's Restroom across from Classroom 302	W2	Plaster	White	None	0	0.23	Negative
1	3	Girl's Restroom across from Classroom 302	W3	Plaster	White	Chipping	1	0.2	Negative
1	3	Girl's Restroom across from Classroom 302	W4	Plaster	White	Efflorescence	2	0.12	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Girl's Restroom across from Classroom 302	Ceiling	Plaster	White	Chipping	25	0.05	Negative
1	3	Girl's Restroom across from Classroom 302	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 302	Radiator	Metal	Grey	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 302	Pipe	Metal	White	None	0	0.01	Negative
1	3	Girl's Restroom across from Classroom 302	Pipe	Metal	Brown	None	0	0	Negative
1	3	Electrical Room 328	W1	Plaster	Green	Efflorescence	1	0.13	Negative
1	3	Electrical Room 328	W2	Plaster	Green	Efflorescence	2	0.11	Negative
1	3	Electrical Room 328	W3	Plaster	Green	Efflorescence	3	0.06	Negative
1	3	Electrical Room 328	W4	Plaster	Green	None	0	0.03	Negative
1	3	Electrical Room 328	Ceiling	Plaster	White	Chipping	3	0.02	Negative
1	3	Electrical Room 328	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 328	Baseboard	Concrete	Grey	None	0	0.01	Negative
1	3	Classroom 332	W1	Plaster	White	None	0	0.06	Negative
1	3	Classroom 332	W2	Plaster	White	None	0	0.08	Negative
1	3	Classroom 332	W3	Plaster	White	Efflorescence	2	0	Negative
1	3	Classroom 332	W4	Plaster	White	None	0	0.09	Negative
1	3	Classroom 332	Ceiling	Plaster	White	Flaking	100	0.04	Negative
1	3	Classroom 332	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 332	Radiator Cover	Metal	White	Chipping	1	0	Negative
1	3	Classroom 332	Whiteboard Frame	Wood	Brown	None	0	0.03	Negative
1	3	Classroom 332	Pipe	Metal	Grey	None	0	0.01	Negative
1	3	Classroom 333	W1	Plaster	White	Chipping	3	0.27	Negative
1	3	Classroom 333	W2	Plaster	White	None	0	0.05	Negative
1	3	Classroom 333	W3	Plaster	White	Efflorescence	2	0.1	Negative
1	3	Classroom 333	W4	Plaster	White	None	0	0.11	Negative
1	3	Classroom 333	Ceiling	Plaster	White	Chipping	5	0.03	Negative
1	3	Classroom 333	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 333	Radiator	Metal	Grey	Chipping	1	0.03	Negative
1	3	Classroom 333	Whiteboard Frame	Wood	Brown	None	0	0.02	Negative
1	3	Classroom 333	Pipe	Metal	Grey	None	0	0.01	Negative
1	3	Classroom 333	Ductwork	Metal	White	Chipping	1	0.04	Negative
1	3	Classroom 333 Closet	W1	Plaster	Green	Chipping	1	0.09	Negative
1	3	Classroom 333 Closet	W2	Plaster	Green	None	0	0.08	Negative
1	3	Classroom 333 Closet	W3	Plaster	Green	Cracking	3	0.07	Negative
1	3	Classroom 333 Closet	W4	Plaster	Green	Efflorescence	10	0.05	Negative
1	3	Classroom 333 Closet	Ceiling	Plaster	White	Cracking	5	0.25	Negative
1	3	Classroom 333 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 333 Closet	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	3	Classroom 333 Closet	Pipe	Metal	Grey	None	0	0	Negative
1	3	Classroom 334	W1	Plaster	White	None	0	0.01	Negative
1	3	Classroom 334	W2	Sheet Rock	White	None	0	0	Negative
1	3	Classroom 334	W3	Plaster	White	Efflorescence	5	0.15	Negative
1	3	Classroom 334	W4	Plaster	White	None	0	0.07	Negative
1	3	Classroom 334	Ceiling	Plaster	White	Flaking	35	0.03	Negative
1	3	Classroom 334	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334	Radiator	Metal	Grey	Chipping	1	5.1	Positive
1	3	Classroom 334	Pipe Cover	Metal	White	Chipping	1	0.24	Negative
1	3	Classroom 335	W1	Plaster	Green	None	0	0.17	Negative
1	3	Classroom 335	W2	Plaster	Green	None	0	0.12	Negative
1	3	Classroom 335	W3	Plaster	Green	None	0	0.1	Negative
1	3	Classroom 335	W4	Sheet Rock	Green	None	0	0	Negative
1	3	Classroom 335	Ceiling	Plaster	White	Chipping	65	0.16	Negative
1	3	Classroom 335	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335	Radiator	Metal	Grey	None	0	2.97	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 335	Pipe	Metal	White	None	0	0.05	Negative
1	3	Classroom 335 Storage Room	W1	Plaster	White	None	0	0.07	Negative
1	3	Classroom 335 Storage Room	W2	Plaster	White	None	0	0.1	Negative
1	3	Classroom 335 Storage Room	W3	Plaster	White	None	0	0.12	Negative
1	3	Classroom 335 Storage Room	W4	Plaster	White	None	0	0.09	Negative
1	3	Classroom 335 Storage Room	Ceiling	Plaster	White	None	0	0.03	Negative
1	3	Classroom 335 Storage Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335 Storage Room	Baseboard	Concrete	Brown	None	0	0.06	Negative
1	3	Classroom 336	W1	Plaster	White	Chipping	2	0.06	Negative
1	3	Classroom 336	W2	Plaster	White	None	0	0.18	Negative
1	3	Classroom 336	W3	Plaster	White	Efflorescence	3	0	Negative
1	3	Classroom 336	W3	Plaster	Pink	Efflorescence	5	0.02	Negative
1	3	Classroom 336	W4	Plaster	Blue	None	0	0	Negative
1	3	Classroom 336	Ceiling	Plaster	White	Chipping	45	0.25	Negative
1	3	Classroom 336	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 336	Radiator	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 336	Pipe	Metal	White	None	0	0.14	Negative
1	3	Classroom 336 Storage Room	W1	Plaster	White	None	0	0.13	Negative
1	3	Classroom 336 Storage Room	W2	Plaster	White	Efflorescence	4	0.06	Negative
1	3	Classroom 336 Storage Room	W3	Plaster	White	None	0	0.11	Negative
1	3	Classroom 336 Storage Room	W4	Plaster	White	None	0	0.08	Negative
1	3	Classroom 336 Storage Room	Ceiling	Plaster	White	None	0	0.01	Negative
1	3	Classroom 336 Storage Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 336 Storage Room	Radiator	Metal	Grey	None	0	0.04	Negative
1	3	Classroom 337	W1	Plaster	White	None	0	0.12	Negative
1	3	Classroom 337	W2	Plaster	White	None	0	0.13	Negative
1	3	Classroom 337	W3	Plaster	White	None	0	0.2	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo							
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	3	Classroom 337	W4	Plaster	White	None	0	0.22	Negative	
1	3	Classroom 337	Ceiling	Plaster	White	Chipping	2	0.02	Negative	
1	3	Classroom 337	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 337	Radiator	Metal	Grey	Chipping	1	0.01	Negative	
1	3	Classroom 337	Whiteboard Frame	Wood	Brown	None	0	0.01	Negative	
1	3	Classroom 337	Pipe	Metal	White	None	0	0.16	Negative	
1	3	Classroom 329	W1	Plaster	White	Chipping	1	0.14	Negative	
1	3	Classroom 329	W2	Plaster	White	None	0	0.13	Negative	
1	3	Classroom 329	W3	Plaster	White	Cracking	2	0.09	Negative	
1	3	Classroom 329	W4	Plaster	White	None	0	0.11	Negative	
1	3	Classroom 329	Ceiling	Plaster	White	Flaking	30	0.36	Negative	
1	3	Classroom 329	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 329	Radiator Cover	Metal	White	None	0	0.06	Negative	
1	3	Classroom 329	Window Sill	Wood	White	None	0	0.05	Negative	
1	3	Classroom 329	Baseboard	Concrete	Brown	None	0	0.38	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	W1	Sheet Rock	White	None	0	0	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	W2	Plaster	White	None	0	0.18	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	W3	Plaster	White	None	0	0.21	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	W4	Plaster	White	None	0	0.16	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Ceiling	Plaster	White	Efflorescence	3	0.04	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Baseboard	Concrete	Brown	None	0	0.11	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Door	Metal	Brown	None	0	0	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Door Frame	Metal	Brown	None	0	0	Negative	
1	3	Storeroom off Hallway from Classroom 332 to Classroom 329	Door Frame	Metal	Brown	None	0	0	Negative	
1	3	Hallway from near Elevator No. 2 to Room 312	W1	Plaster	White	Moisture Damage	3	0.09	Negative	
1	3	Hallway from near Elevator No. 2 to Room 312	W2	Plaster	White	None	0	0.13	Negative	



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Hallway from near Elevator No. 2 to Room 312	W3	Plaster	White	Moisture Damage	20	0.38	Negative
1	3	Hallway from near Elevator No. 2 to Room 312	W4	Plaster	White	None	0	0.28	Negative
1	3	Hallway from near Elevator No. 2 to Room 312	Door Frame	Wood	Brown	None	0	0.42	Negative
1	3	Hallway from near Elevator No. 2 to Room 312	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Hallway from near Elevator No. 2 to Room 312	Pipe Cover	Metal	White	None	0	0.3	Negative
1	3	Hallway from near Elevator No. 2 to Room 312	Ceiling	Plaster	White	None	0	0.3	Negative
1	3	Hallway from near Elevator No. 2 to Room 312	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from near Classroom 307 to Room 301	W1	Plaster	White	None	0	0.23	Negative
1	3	Hallway from near Classroom 307 to Room 301	W2	Plaster	White	Chipping	5	0.27	Negative
1	3	Hallway from near Classroom 307 to Room 301	W3	Plaster	White	None	0	0.17	Negative
1	3	Hallway from near Classroom 307 to Room 301	W4	Plaster	White	Efflorescence	20	0.21	Negative
1	3	Hallway from near Classroom 307 to Room 301	Ceiling	Plaster	White	Efflorescence	20	0.02	Negative
1	3	Hallway from near Classroom 307 to Room 301	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from near Classroom 307 to Room 301	Radiator	Metal	Grey	No Access	0	No Access	No Access
1	3	Hallway from near Classroom 307 to Room 301	Pipe Cover	Metal	White	Chipping	2	0.2	Negative
1	3	Hallway from near Classroom 307 to Room 301	Door	Metal	Grey	None	0	0.21	Negative
1	3	Hallway from near Classroom 307 to Room 301	Door Frame	Metal	Grey	Friction	2	0.03	Negative
1	3	Hallway from near Classroom 307 to Room 301	Door	Metal	Grey	Chipping	1	0.18	Negative
1	3	Hallway from near Classroom 307 to Room 301	Door Frame	Metal	Grey	Friction	2	0.05	Negative
1	3	Hallway between Classrooms 332 and 334	W1	Plaster	White	None	0	0.28	Negative
1	3	Hallway between Classrooms 332 and 334	W2	Plaster	White	Chipping	5	0.19	Negative
1	3	Hallway between Classrooms 332 and 334	W3	Plaster	White	None	0	0.21	Negative
1	3	Hallway between Classrooms 332 and 334	W4	Plaster	White	Chipping	4	0.16	Negative
1	3	Hallway between Classrooms 332 and 334	Ceiling	Plaster	White	None	0	0.03	Negative
1	3	Hallway between Classrooms 332 and 334	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 332 to Classroom 337	W1	Plaster	White	None	0	0.23	Negative
1	3	Hallway from Classroom 332 to Classroom 337	W2	Plaster	White	Flaking	3	0.3	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo							
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	3	Hallway from Classroom 332 to Classroom 337	W3	Plaster	White	None	0	0.27	Negative	
1	3	Hallway from Classroom 332 to Classroom 337	W4	Sheet Rock	White	Chipping	2	0	Negative	
1	3	Hallway from Classroom 332 to Classroom 337	W4	Plaster	White	None	0	0.12	Negative	
1	3	Hallway from Classroom 332 to Classroom 337	Ceiling	Plaster	White	None	0	0.05	Negative	
1	3	Hallway from Classroom 332 to Classroom 337	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Hallway from Classroom 332 to Classroom 337	Radiator	Metal	No Access	No Access	0	No Access	No Access	
1	3	Hallway from Classroom 321 to 322	W1	Plaster	White	Chipping	1	0.2	Negative	
1	3	Hallway from Classroom 321 to 322	W2	Plaster	White	Chipping	10	0.17	Negative	
1	3	Hallway from Classroom 321 to 322	W3	Plaster	White	None	0	0.19	Negative	
1	3	Hallway from Classroom 321 to 322	W4	Plaster	White	Cracking	20	0.11	Negative	
1	3	Hallway from Classroom 321 to 322	Ceiling	Plaster	White	None	0	0.02	Negative	
1	3	Hallway from Classroom 321 to 322	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Hallway along Classroom 329	W1	Plaster	White	None	0	0.17	Negative	
1	3	Hallway along Classroom 329	W2	Plaster	White	Chipping	5	0.29	Negative	
1	3	Hallway along Classroom 329	W3	Plaster	White	None	0	0.26	Negative	
1	3	Hallway along Classroom 329	W4	Plaster	White	Efflorescence	10	0.27	Negative	
1	3	Hallway along Classroom 329	Ceiling	Plaster	White	Cracking	5	0.04	Negative	
1	3	Hallway along Classroom 329	Radiator	Metal	Brown	No Access	0	No Access	No Access	
1	3	Hallway along Classroom 329	Pipe Cover	Metal	Brown	Chipping	5	0.22	Negative	
1	3	Hallway along Classroom 329	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	Hallway along Classroom 329	Panel	Metal	White	None	0	0	Negative	
1	3	Hallway between Classrooms 335 and 337	W1	Plaster	White	None	0	0.2	Negative	
1	3	Hallway between Classrooms 335 and 337	W2	Plaster	White	Moisture Damage	2	0.18	Negative	
1	3	Hallway between Classrooms 335 and 337	W3	Plaster	White	None	0	0.19	Negative	
1	3	Hallway between Classrooms 335 and 337	W4	Plaster	White	Chipping	1	0.2	Negative	
1	3	Hallway between Classrooms 335 and 337	Ceiling	Plaster	White	Flaking	3	0.01	Negative	
1	3	Hallway between Classrooms 335 and 337	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Hallway between Classrooms 335 and 337	Radiator	Metal	White	None	0	N/A	No Access
1	3	Hallway between Classrooms 335 and 337	Pipe Cover	Metal	White	Chipping	1	0.28	Negative
1	3	Hallway between Classrooms 335 and 337	Door	Metal	Brown	None	0	0	Negative
1	3	Pipe Shaft between Restroom and Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Pipe Shaft between Restroom and Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Pipe Shaft between Restroom and Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Pipe Shaft between Restroom and Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Pipe Shaft between Restroom and Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Pipe Shaft between Restroom and Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Stairwell next to Classroom 329	W1	Plaster	White	None	0	0.15	Negative
1	3	Stairwell next to Classroom 329	W2	Plaster	White	None	0	0.16	Negative
1	3	Stairwell next to Classroom 329	W3	Plaster	White	None	0	0.21	Negative
1	3	Stairwell next to Classroom 329	W4	Plaster	White	None	0	0.18	Negative
1	3	Stairwell next to Classroom 329	Ceiling	Plaster	White	Chipping	10	0.04	Negative
1	3	Stairwell next to Classroom 329	Radiator	Metal	No Access	No Access	No Access	No Access	No Access
1	3	Stairwell next to Classroom 329	Spindle	Metal	Grey	None	0	2.39	Positive
1	3	Stairwell next to Classroom 329	Newel Post	Metal	Grey	Chipping	5	4.45	Positive
1	3	Stairwell next to Classroom 329	Stair Riser	Concrete	Grey	None	0	0.44	Negative
1	3	Stairwell next to Classroom 329	Stringer	Concrete	Grey	None	0	0.39	Negative
1	3	Stairwell next to Classroom 329	trim	Concrete	Grey	None	0	0.02	Negative
1	3	Stairwell next to Classroom 329	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell next to Weight Room 311	W1	Plaster	White	None	0	0.26	Negative
1	3	Stairwell next to Weight Room 311	W2	Plaster	White	None	0	0.24	Negative
1	3	Stairwell next to Weight Room 311	W3	Plaster	White	None	0	0.12	Negative
1	3	Stairwell next to Weight Room 311	W4	Plaster	White	None	0	0.46	Negative
1	3	Stairwell next to Weight Room 311	Stair Riser	Concrete	Grey	None	0	0.24	Negative
1	3	Stairwell next to Weight Room 311	Newel Post	Concrete	Grey	Friction	10	3.45	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Stairwell next to Weight Room 311	Stringer	Concrete	Grey	None	0	1.2	Positive
1	3	Stairwell next to Weight Room 311	Spindle	Metal	Grey	None	0	6.6	Positive
1	3	Stairwell next to Weight Room 311	Trim	Concrete	Grey	None	0	0.2	Negative
1	3	Stairwell next to Weight Room 311	Pipe	Metal	Black	None	0	0.48	Negative
1	3	Stairwell next to Weight Room 311	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Stairwell next to Weight Room 311	Ceiling	Plaster	White	None	0	0.35	Negative
1	3	Stairwell next to Weight Room 311	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Middle Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Middle Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Middle Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Middle Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Middle Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Middle Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Stairwell near Room 301 and Elevator No. 1	W1	Plaster	White	None	0	0.27	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	W2	Plaster	White	Chipping	10	0.22	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	W3	Plaster	White	None	0	0.21	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	W4	Plaster	White	None	0	0.2	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	Ceiling	Plaster	White	Moisture Damage	10	0.12	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell near Room 301 and Elevator No. 1	Stair Riser	Concrete	Grey	None	0	0.49	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	Newel Post	Concrete	Grey	Friction	10	2.81	Positive
1	3	Stairwell near Room 301 and Elevator No. 1	Stringer	Concrete	Grey	None	0	2.13	Positive
1	3	Stairwell near Room 301 and Elevator No. 1	Spindle	Metal	Grey	None	0	2.46	Positive
1	3	Stairwell near Room 301 and Elevator No. 1	Trim	Concrete	Grey	None	0	0.4	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	Pipe	Metal	White	None	0	0	Negative
1	3	Stairwell near Room 301 and Elevator No. 1	Radiator	Metal	No Access	None	0	N/A	N/A
1	3	Stairwell near Classroom 307	W1	Plaster	White	None	0	0.19	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Stairwell near Classroom 307	W2	Plaster	White	Flaking	2	0.25	Negative
1	3	Stairwell near Classroom 307	W3	Plaster	White	Chipping	15	0.32	Negative
1	3	Stairwell near Classroom 307	W4	Plaster	White	None	0	0.28	Negative
1	3	Stairwell near Classroom 307	Ceiling	Plaster	White	Chipping	2	0.04	Negative
1	3	Stairwell near Classroom 307	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell near Classroom 307	Stair Riser	Concrete	Grey	None	0	0.25	Negative
1	3	Stairwell near Classroom 307	Newel Post	Concrete	Grey	Friction	10	3.36	Positive
1	3	Stairwell near Classroom 307	Stringer	Concrete	Grey	None	0	0.83	Positive
1	3	Stairwell near Classroom 307	Spindle	Metal	Grey	None	0	2.19	Positive
1	3	Stairwell near Classroom 307	Trim	Concrete	Grey	None	0	0.34	Negative
1	3	Stairwell near Classroom 307	Pipe	Metal	Grey	Flaking	5	0	Negative
1	3	Stairwell near Classroom 307	Radiator	Metal	No Access	None	0	N/A	N/A
1	3	Stairwell near Classroom 307	Pipe	Metal	White	None	0	0.35	Negative
1	4	Classroom 401	W1	Plaster	White	Chipping	5	0.4	Negative
1	4	Classroom 401	W2	Plaster	White	None	0	0.4	Negative
1	4	Classroom 401	W3	Plaster	White	Efflorescence	20	0.29	Negative
1	4	Classroom 401	W4	Plaster	White	Chipping	5	0.11	Negative
1	4	Classroom 401	Ceiling	Plaster	White	Efflorescence	10	0.49	Negative
1	4	Classroom 401	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 401	Window Sill	Wood	Brown	Friction	5	0.38	Negative
1	4	Classroom 401	Door Frame	Metal	Black	None	0	0.26	Negative
1	4	Classroom 401	Radiator	Metal	Brown	Chipping	5	0.44	Negative
1	4	Classroom 401	Radiator Cover	Metal	White	Chipping	2	0.31	Negative
1	4	Prep Room 403 between Classrooms 401/404	W1	Plaster	White	None	0	0.49	Negative
1	4	Prep Room 403 between Classrooms 401/404	W2	Plaster	White	Chipping	5	0.28	Negative
1	4	Prep Room 403 between Classrooms 401/404	W3	Plaster	White	None	0	0.35	Negative
1	4	Prep Room 403 between Classrooms 401/404	W4	Plaster	White	None	0	0.16	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Prep Room 403 between Classrooms 401/404	Ceiling	Plaster	White	Chipping	30	0.24	Negative
1	4	Prep Room 403 between Classrooms 401/404	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Prep Room 403 between Classrooms 401/404	Door Frame	Metal	Black	None	0	0.25	Negative
1	4	Prep Room 403 between Classrooms 401/404	Window Sill	Wood	Brown	None	0	0.29	Negative
1	4	Prep Room 403 between Classrooms 401/404	Radiator Cover	Metal	White	None	0	0.27	Negative
1	4	Prep Room 403 Closet	W1	Plaster	White	None	0	0.25	Negative
1	4	Prep Room 403 Closet	W2	Plaster	White	None	0	0.1	Negative
1	4	Prep Room 403 Closet	W3	Plaster	White	Efflorescence	15	0.12	Negative
1	4	Prep Room 403 Closet	W4	Plaster	White	None	0	0.2	Negative
1	4	Prep Room 403 Closet	Door Frame	Metal	Black	None	0	0.25	Negative
1	4	Prep Room 403 Closet	Ceiling	Plaster	White	Chipping	15	0.36	Negative
1	4	Prep Room 403 Closet	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway between Classrooms 401 and 404	W1	Plaster	White	None	0	0.15	Negative
1	4	Hallway between Classrooms 401 and 404	W2	Plaster	White	Chipping	5	0.33	Negative
1	4	Hallway between Classrooms 401 and 404	W3	Plaster	White	Chipping	1	0.16	Negative
1	4	Hallway between Classrooms 401 and 404	W4	Plaster	White	None	0	0.16	Negative
1	4	Hallway between Classrooms 401 and 404	Ceiling	Plaster	White	None	0	0.48	Negative
1	4	Hallway between Classrooms 401 and 404	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway between Classrooms 401 and 404	Door Frame	Metal	Black	None	0	0.14	Negative
1	4	Hallway between Classrooms 401 and 404	Ductwork	Metal	White	None	0	0.37	Negative
1	4	Hallway between Classrooms 401 and 404	Pipe	Metal	White	None	0	0.27	Negative
1	4	Classroom 404	Door Frame	Metal	Black	None	0	0.4	Negative
1	4	Classroom 404	Ductwork	Metal	White	None	0	0.42	Negative
1	4	Classroom 404	Pipe	Metal	White	None	0	0.33	Negative
1	4	Classroom 404	Radiator	Metal	Brown	Chipping	2	0.1	Negative
1	4	Classroom 404	Radiator Cover	Metal	White	None	0	0.22	Negative
1	4	Classroom 404	Window Sill	Wood	Brown	Friction	2	0.19	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 404	W1	Plaster	White	Chipping	10	0.14	Negative
1	4	Classroom 404	W2	Plaster	White	Cracking	10	0.28	Negative
1	4	Classroom 404	W3	Plaster	White	Efflorescence	15	0.46	Negative
1	4	Classroom 404	W4	Sheet Rock	White	Flaking	2	0.4	Negative
1	4	Classroom 404	Ceiling	Plaster	White	Chipping	10	0.09	Negative
1	4	Classroom 404	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 407	W1	Plaster	White	Chipping	10	0.22	Negative
1	4	Classroom 407	W2	Plaster	White	Chipping	2	0.01	Negative
1	4	Classroom 407	W3	Plaster	White	Efflorescence	15	0.05	Negative
1	4	Classroom 407	W4	Sheet Rock	White	Cracking	2	0.36	Negative
1	4	Classroom 407	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	Classroom 407	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 407	Door Frame	Metal	Black	None	0	0.22	Negative
1	4	Classroom 407	Ductwork	Metal	White	None	0	0.35	Negative
1	4	Classroom 407	Pipe	Metal	White	None	0	0.34	Negative
1	4	Classroom 407	Radiator	Metal	White	Chipping	2	1	Positive
1	4	Classroom 407	Radiator Cover	Metal	White	None	0	0.27	Negative
1	4	Classroom 407	Window Sill	Wood	Brown	Friction	2	0.02	Negative
1	4	Hallway between Classrooms 404 & 407	W1	Plaster	White	Chipping	2	0.22	Negative
1	4	Hallway between Classrooms 404 & 407	W2	Plaster	White	Chipping	2	0.19	Negative
1	4	Hallway between Classrooms 404 & 407	W3	Sheet Rock	White	Chipping	2	0.25	Negative
1	4	Hallway between Classrooms 404 & 407	W4	Sheet Rock	White	Chipping	2	0.26	Negative
1	4	Hallway between Classrooms 404 & 407	Ceiling	Plaster	White	None	0	0.41	Negative
1	4	Hallway between Classrooms 404 & 407	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway between Classrooms 404 & 407	Pipe	Metal	White	None	0	0.13	Negative
1	4	Hallway between Classrooms 404 & 407	Ductwork	Metal	White	None	0	0.03	Negative
1	4	Hallway between Classrooms 404 & 407	Door Frame	Metal	Black	None	0	0.2	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Prep Room 406 between Classrooms 404/407	W1	Plaster	White	None	0	0.25	Negative
1	4	Prep Room 406 between Classrooms 404/407	W2	Plaster	White	None	0	0.28	Negative
1	4	Prep Room 406 between Classrooms 404/407	W3	Plaster	White	Efflorescence	10	0.13	Negative
1	4	Prep Room 406 between Classrooms 404/407	W4	Plaster	White	None	0	0.15	Negative
1	4	Prep Room 406 between Classrooms 404/407	Ceiling	Plaster	White	None	0	0.01	Negative
1	4	Prep Room 406 between Classrooms 404/407	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Prep Room 406 between Classrooms 404/407	Door Frame	Metal	Black	None	0	0.38	Negative
1	4	Prep Room 406 Closet	Door Frame	Metal	Black	None	0	0.38	Negative
1	4	Prep Room 406 Closet	W1	Plaster	White	None	0	0.18	Negative
1	4	Prep Room 406 Closet	W2	Plaster	White	None	0	0.34	Negative
1	4	Prep Room 406 Closet	W3	Plaster	White	None	0	0.08	Negative
1	4	Prep Room 406 Closet	W4	Plaster	White	None	0	0.08	Negative
1	4	Prep Room 406 Closet	Ceiling	Plaster	White	Cracking	20	0.29	Negative
1	4	Prep Room 406 Closet	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Library/IMC	Column	Brick	White	None	0	0.14	Negative
1	4	Library/IMC	Column	Brick	Green	None	0	0.3	Negative
1	4	Library/IMC	Radiator	Metal	No Access	No Access	No Access	No Access	No Access
1	4	Library/IMC	W1	Sheet Rock	White	None	0	0.34	Negative
1	4	Library/IMC	W1	Brick	Grey	None	0	0.17	Negative
1	4	Library/IMC	W2	CMU	White	None	0	0.36	Negative
1	4	Library/IMC	W2	CMU	Green	None	0	0.48	Negative
1	4	Library/IMC	W2	Sheet Rock	White	None	0	0.41	Negative
1	4	Library/IMC	W2	Brick	White	None	0	0.23	Negative
1	4	Library/IMC	W3	Sheet Rock	White	None	0	0.43	Negative
1	4	Library/IMC	W3	Brick	White	None	0	0.36	Negative
1	4	Library/IMC	W4	Brick	White	None	0	0.22	Negative
1	4	Library/IMC	W2	CMU/Architectural Tile	Black	Friction	10	2.5	Positive



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Library/IMC	Ceiling	Spline Ceiling Tiles	Unpainted	N/A	N/A	N/A	N/A
1	4	Library/IMC	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical/Fan Room with New HVAC System	Radiator	Metal	Grey	Chipping	20	0.08	Negative
1	4	Mechanical/Fan Room with New HVAC System	Radiator Cover	Metal	White	None	0	0.03	Negative
1	4	Mechanical/Fan Room with New HVAC System	Ductwork	Metal	White	None	0	0.14	Negative
1	4	Mechanical/Fan Room with New HVAC System	W1	CMU	Yellow	None	0	0.48	Negative
1	4	Mechanical/Fan Room with New HVAC System	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical/Fan Room with New HVAC System	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical/Fan Room with New HVAC System	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical/Fan Room with New HVAC System	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical/Fan Room with New HVAC System	W4	CMU	Yellow	None	0	0.02	Negative
1	4	Mechanical/Fan Room with New HVAC System	W4	Architectural Tile	Unpainted	Friction	5	3.6	Positive
1	4	Mechanical/Fan Room with New HVAC System	Ceiling	Plaster	White	Chipping	100	0.23	Negative
1	4	Mechanical/Fan Room with New HVAC System	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	Radiator	Metal	Brown	Chipping	10	0.12	Negative
1	4	Mechanical Room Unused Restroom	Radiator Cover	Metal	White	None	0	0.16	Negative
1	4	Mechanical Room Unused Restroom	Pipe	Metal	White	Chipping	50	0.48	Negative
1	4	Mechanical Room Unused Restroom	W1	Plaster	White	Chipping	50	0.04	Negative
1	4	Mechanical Room Unused Restroom	W2	Plaster	White	Chipping	50	0.08	Negative
1	4	Mechanical Room Unused Restroom	W3	Plaster	White	Chipping	50	0.49	Negative
1	4	Mechanical Room Unused Restroom	W4	Plaster	White	Chipping	50	0.21	Negative
1	4	Mechanical Room Unused Restroom	Ceiling	Plaster	White	Chipping	50	0.43	Negative
1	4	Mechanical Room Unused Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	Ductwork	Metal	White	None	0	0.16	Negative
1	4	Mechanical Room Unused Restroom	Door Frame	Metal	Yellow	None	0	0.49	Negative
1	4	Mechanical Room Unused Restroom	W1	CMU	Yellow	None	0	0.24	Negative
1	4	Mechanical Room Unused Restroom	W2	CMU	Yellow	None	0	0.32	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Mechanical Room Unused Restroom	W2	Architectural Tile	Unpainted	Friction	10	2.6	Positive
1	4	Mechanical Room Unused Restroom	W3	CMU	Yellow	None	0	0.49	Negative
1	4	Mechanical Room Unused Restroom	W4	CMU	Yellow	None	0	0.44	Negative
1	4	Mechanical Room Unused Restroom	W4	Architectural Tile	N/A	Friction	6	2	Positive
1	4	Mechanical Room Unused Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	4	Mechanical Room Unused Restroom	Ceiling	Plaster	White	Chipping	20	0.32	Negative
1	4	Mechanical Room Unused Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Room 410 Storage Room	W1	Brick	White	None	0	0.2	Negative
1	4	Room 410 Storage Room	W2	CMU	White	None	0	0.01	Negative
1	4	Room 410 Storage Room	W3	CMU	White	None	0	0.14	Negative
1	4	Room 410 Storage Room	W3	Brick	White	Efflorescence	15	0.5	Negative
1	4	Room 410 Storage Room	W4	Sheet Rock	White	None	0	0.16	Negative
1	4	Room 410 Storage Room	W4	Brick	White	None	0	0.22	Negative
1	4	Room 410 Storage Room	Ceiling	Spline	Unpainted	None	0	N/A	N/A
1	4	Room 410 Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Library/IMC Office 409B	Radiator	Metal	Grey	No Access	No Access	No Access	No Access
1	4	Library/IMC Office 409B	W1	Sheet Rock	White	None	0	0.37	Negative
1	4	Library/IMC Office 409B	W2	Sheet Rock	White	None	0	0.22	Negative
1	4	Library/IMC Office 409B	W3	Brick	White	None	0	0.32	Negative
1	4	Library/IMC Office 409B	W4	Sheet Rock	White	None	0	0.19	Negative
1	4	Library/IMC Office 409B	Ceiling	Plaster	White	Chipping	20	0.03	Negative
1	4	Library/IMC Office 409B	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Library/IMC Men's Restroom	Door	Metal	Black	None	0	0.02	Negative
1	4	Library/IMC Men's Restroom	Door Frame	Metal	Black	None	0	0.49	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Library/IMC Men's Restroom	Door	Metal	Brown	None	0	0.17	Negative
1	4	Library/IMC Men's Restroom	Radiator Cover	Metal	Brown	None	0	0.32	Negative
1	4	Library/IMC Men's Restroom	W1	CMU	White	None	0	0.31	Negative
1	4	Library/IMC Men's Restroom	W2	CMU	White	None	0	0.34	Negative
1	4	Library/IMC Men's Restroom	W3	CMU	White	None	0	0.13	Negative
1	4	Library/IMC Men's Restroom	W4	CMU	White	None	0	0.19	Negative
1	4	Library/IMC Men's Restroom	Ceiling	Spline	Unpainted	None	0	N/a	N/A
1	4	Library/IMC Men's Restroom	Floor	Concrete	Grey	None	0	0.47	Negative
1	4	Library/IMC Women's Restroom	Door	Metal	Black	None	0	0.5	Negative
1	4	Library/IMC Women's Restroom	Door Frame	Metal	Black	None	0	0.16	Negative
1	4	Library/IMC Women's Restroom	Door	Metal	Brown	None	0	0.15	Negative
1	4	Library/IMC Women's Restroom	Radiator Cover	Metal	Brown	None	0	0.25	Negative
1	4	Library/IMC Women's Restroom	W1	CMU	White	None	0	0.39	Negative
1	4	Library/IMC Women's Restroom	W2	CMU	White	None	0	0.2	Negative
1	4	Library/IMC Women's Restroom	W3	CMU	White	None	0	0.3	Negative
1	4	Library/IMC Women's Restroom	W4	CMU	White	None	0	0.12	Negative
1	4	Library/IMC Women's Restroom	Ceiling	Plaster	White	Flaking	25	0.02	Negative
1	4	Library/IMC Women's Restroom	Floor	Concrete	Grey	None	0	0.23	Negative
1	4	Library/IMC Office 409A	Radiator	Metal	Grey	No Access	No Access	No Access	No Access
1	4	Library/IMC Office 409A	W1	Sheet Rock	White	None	0	0.45	Negative
1	4	Library/IMC Office 409A	W2	CMU	White	None	0	0.43	Negative
1	4	Library/IMC Office 409A	W3	Brick	White	None	0	0.09	Negative
1	4	Library/IMC Office 409A	W4	Sheet Rock	White	None	0	0.07	Negative
1	4	Library/IMC Office 409A	Ceiling	Plaster	White	Chipping	20	0.03	Negative
1	4	Library/IMC Office 409A	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Girl's Restroom	Pipe	Metal	Brown	None	0	0.42	Negative
1	4	Girl's Restroom	Pipe	Metal	White	None	0	0.04	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Girl's Restroom	Radiator Cover	Metal	White	Chipping	5	0.36	Negative
1	4	Girl's Restroom	Radiator	Metal	Brown	Chipping	20	0.08	Negative
1	4	Girl's Restroom	Window Frame	Wood	Brown	Friction	3	0.17	Negative
1	4	Girl's Restroom	W1	Plaster	White	None	0	0.07	Negative
1	4	Girl's Restroom	W2	Plaster	White	Cracking	10	0.16	Negative
1	4	Girl's Restroom	W3	Plaster	White	Efflorescence	20	0.41	Negative
1	4	Girl's Restroom	W4	Plaster	White	Efflorescence	20	0.19	Negative
1	4	Girl's Restroom	Ceiling	Plaster	White	Chipping	90	0.08	Negative
1	4	Girl's Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Custodial Closet 417	Radiator	Metal	Grey	Chipping	5	0.37	Negative
1	4	Custodial Closet 417	Window Sill	Wood	Green	Chipping	5	0.06	Negative
1	4	Custodial Closet 417	Window Frame	Wood	Green	Chipping	5	0.15	Negative
1	4	Custodial Closet 417	Coat Rack	Wood	Green	Chipping	5	0.15	Negative
1	4	Custodial Closet 417	Pipe	Metal	White	Chipping	1	0.21	Negative
1	4	Custodial Closet 417	Pipe Cover	Metal	White	Chipping	1	0.04	Negative
1	4	Custodial Closet 417	W1	Plaster	White	None	0	0.03	Negative
1	4	Custodial Closet 417	W2	Plaster	White	None	0	0.35	Negative
1	4	Custodial Closet 417	W3	Plaster	White	Chipping	2	0.34	Negative
1	4	Custodial Closet 417	W4	Plaster	White	Chipping	2	0.22	Negative
1	4	Custodial Closet 417	Ceiling	Plaster	White	Efflorescence	15	0.14	Negative
1	4	Custodial Closet 417	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 412	Radiator Cover	Metal	White	None	0	0.35	Negative
1	4	Classroom 412	Radiator Cover	Metal	Brown	None	0	0.37	Negative
1	4	Classroom 412	Radiator	Metal	Brown	None	0	0.28	Negative
1	4	Classroom 412	Pipe Cover	Metal	White	None	0	0.09	Negative
1	4	Classroom 412	Baseboard	Concrete	Grey	None	0	0.18	Negative
1	4	Classroom 412	Window Frame	Wood	Brown	None	0	0.15	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 412	Window Sill	Wood	Brown	None	0	0.04	Negative
1	4	Classroom 412	Door Frame	Wood	Brown	None	0	0.1	Negative
1	4	Classroom 412	W1	Plaster	White	Cracking	2	0.1	Negative
1	4	Classroom 412	W2	Plaster	White	None	0	0.03	Negative
1	4	Classroom 412	W3	Plaster	White	Efflorescence	15	0.05	Negative
1	4	Classroom 412	W4	Sheet Rock	White	None	0	0.31	Negative
1	4	Classroom 412	Ceiling	Plaster	White	None	0	0.46	Negative
1	4	Classroom 412	Floor	Concrete	Grey	None	0	0.38	Negative
1	4	Classroom 411	Radiator Cover	Metal	White	None	0	0.01	Negative
1	4	Classroom 411	Radiator Cover	Metal	Brown	None	0	0.01	Negative
1	4	Classroom 411	Radiator	Metal	Brown	None	0	0.47	Negative
1	4	Classroom 411	Pipe Cover	Metal	White	None	0	0.42	Negative
1	4	Classroom 411	Baseboard	Concrete	Grey	None	0	0.14	Negative
1	4	Classroom 411	Pipe	Metal	White	None	0	0.34	Negative
1	4	Classroom 411	Window Sill	Wood	Brown	None	0	0.2	Negative
1	4	Classroom 411	Door Frame	Wood	Brown	None	0	0.36	Negative
1	4	Classroom 411	W1	Plaster	White	Chipping	1	0.49	Negative
1	4	Classroom 411	W2	Plaster	White	None	0	0.15	Negative
1	4	Classroom 411	W3	Plaster	White	None	0	0.47	Negative
1	4	Classroom 411	W4	Sheet Rock	White	None	0	0.01	Negative
1	4	Classroom 411	Ceiling	Plaster	White	None	0	0.14	Negative
1	4	Classroom 411	Floor	Concrete	Grey	None	0	0.36	Negative
1	4	Classroom 421	Radiator	Metal	Brown	None	0	0.06	Negative
1	4	Classroom 421	Radiator Cover	Metal	White	None	0	0.35	Negative
1	4	Classroom 421	Window Sill	Wood	Brown	None	0	0.42	Negative
1	4	Classroom 421	W1	Plaster	White	Chipping	1	0.43	Negative
1	4	Classroom 421	W2	Plaster	White	None	0	0.28	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 421	W3	Plaster	White	Chipping	10	0.21	Negative
1	4	Classroom 421	W4	Plaster	White	None	0	0.28	Negative
1	4	Classroom 421	Ceiling	Plaster	White	Efflorescence	5	0.25	Negative
1	4	Classroom 421	Baseboard	Wood	Brown	None	0	0.49	Negative
1	4	Classroom 421	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Staff Lounge 418	Radiator	Metal	Grey	Chipping	5	0.43	Negative
1	4	Staff Lounge 418	Radiator Cover	Metal	White	None	0	0.14	Negative
1	4	Staff Lounge 418	Pipe Cover	Metal	White	None	0	0.33	Negative
1	4	Staff Lounge 418	Baseboard	Wood	Brown	None	0	0.22	Negative
1	4	Staff Lounge 418	Window Sill	Wood	Brown	None	0	0.02	Negative
1	4	Staff Lounge 418	W1	Plaster	White	Chipping	2	0.18	Negative
1	4	Staff Lounge 418	W2	Plaster	White	None	0	0.19	Negative
1	4	Staff Lounge 418	W3	Plaster	White	Cracking	5	0.44	Negative
1	4	Staff Lounge 418	W4	Plaster	White	None	0	0.37	Negative
1	4	Staff Lounge 418	Ceiling	Plaster	White	Alligatoring	15	0.49	Negative
1	4	Staff Lounge 418	Ductwork	Metal	White	None	0	0.13	Negative
1	4	Staff Lounge 418	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Staff Lounge Restroom	W1	Plaster	White	None	0	0.46	Negative
1	4	Staff Lounge Restroom	W2	Plaster	White	None	0	0.32	Negative
1	4	Staff Lounge Restroom	W3	Plaster	White	Chipping	5	0.13	Negative
1	4	Staff Lounge Restroom	W4	Plaster	White	None	0	0.32	Negative
1	4	Staff Lounge Restroom	Ceiling	Plaster	White	Chipping	10	0.23	Negative
1	4	Staff Lounge Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Book Closet next to Electrical Room 419	W1	Plaster	Green	Flaking	5	0.33	Negative
1	4	Book Closet next to Electrical Room 419	W2	Plaster	Green	Chipping	10	0.32	Negative
1	4	Book Closet next to Electrical Room 419	W3	Plaster	Green	Flaking	5	0.06	Negative
1	4	Book Closet next to Electrical Room 419	W4	Plaster	Green	Flaking	5	0.35	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Book Closet next to Electrical Room 419	Ceiling	Plaster	White	None	0	0.27	Negative
1	4	Book Closet next to Electrical Room 419	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Electrical Closet 419	W1	Plaster	Green	Cracking	10	0.32	Negative
1	4	Electrical Closet 419	W2	Plaster	Green	Cracking	10	0.16	Negative
1	4	Electrical Closet 419	W3	Plaster	Green	Cracking	10	0.29	Negative
1	4	Electrical Closet 419	W4	Plaster	Green	Cracking	10	0.09	Negative
1	4	Electrical Closet 419	Ceiling	Plaster	White	None	0	0.37	Negative
1	4	Electrical Closet 419	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 422	Radiator	Metal	Brown	None	0	0.1	Negative
1	4	Classroom 422	Radiator Cover	Metal	White	None	0	0.25	Negative
1	4	Classroom 422	Baseboard	Wood	Brown	None	0	0.49	Negative
1	4	Classroom 422	Window Sill	Wood	Brown	None	0	0.4	Negative
1	4	Classroom 422	W1	Plaster	White	None	0	0.01	Negative
1	4	Classroom 422	W2	Plaster	White	None	0	0.44	Negative
1	4	Classroom 422	W3	Plaster	White	Cracking	25	0.46	Negative
1	4	Classroom 422	W4	Plaster	White	Cracking	5	0.45	Negative
1	4	Classroom 422	Ceiling	Plaster	White	Flaking	10	0.04	Negative
1	4	Classroom 422	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 423	W1	Plaster	White	Flaking	10	0.09	Negative
1	4	Classroom 423	W2	Plaster	White	None	0	0.17	Negative
1	4	Classroom 423	W3	Plaster	White	None	0	0.43	Negative
1	4	Classroom 423	W4	Plaster	White	None	0	0.1	Negative
1	4	Classroom 423	W1	Plaster	Red	Flaking	5	0.16	Negative
1	4	Classroom 423	W2	Plaster	Red	None	0	0.17	Negative
1	4	Classroom 423	W3	Plaster	Red	Chipping	10	0.26	Negative
1	4	Classroom 423	W4	Plaster	Red	None	0	0.24	Negative
1	4	Classroom 423	Baseboard	Wood	Brown	None	0	0.22	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 423	Radiator Cover	Metal	White	None	0	0.27	Negative
1	4	Classroom 423	Radiator	Metal	Brown	None	0	0.11	Negative
1	4	Classroom 423	Window Sill	Wood	Brown	None	0	0.27	Negative
1	4	Classroom 423	Whiteboard Frame	Wood	Brown	None	0	0.49	Negative
1	4	Classroom 423	Ceiling	Plaster	White	Flaking	10	0.44	Negative
1	4	Classroom 423	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 423	Baseboard	Wood	Brown	None	0	0.27	Negative
1	4	Classroom 423	Radiator Cover	Metal	White	Chipping	1	0.33	Negative
1	4	Classroom 423	Radiator	Metal	Brown	None	0	0.25	Negative
1	4	Classroom 423	Window Sill	Wood	Brown	None	0	0.28	Negative
1	4	Classroom 423	Whiteboard Frame	Wood	Brown	Chipping	1	0.42	Negative
1	4	Classroom 423	Pipe Cover	Metal	White	Chipping	1	0.04	Negative
1	4	Classroom 424	W1	Plaster	White	Chipping	5	0.31	Negative
1	4	Classroom 424	W2	Plaster	White	Flaking	5	0.14	Negative
1	4	Classroom 424	W3	Plaster	White	Efflorescence	25	0.47	Negative
1	4	Classroom 424	W4	Plaster	White	None	0	0.13	Negative
1	4	Classroom 424	Ceiling	Plaster	White	None	0	0.09	Negative
1	4	Classroom 424	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Physics/Robotics Lab 429	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab 429	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab 429	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab 429	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab 429	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab 429	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Boy's Restroom	W1	Plaster	White	Efflorescence	3	0.06	Negative
1	4	Boy's Restroom	W2	Plaster	White	None	0	0.28	Negative
1	4	Boy's Restroom	W3	Plaster	White	None	0	0.07	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Boy's Restroom	W4	Plaster	White	None	0	0	Negative
1	4	Boy's Restroom	Ceiling	Plaster	white	Chipping	5	0.05	Negative
1	4	Boy's Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Boy's Restroom	Pipe	Metal	white	None	0	0	Negative
1	4	Boy's Restroom	Pipe	Metal	brown	None	0	0.01	Negative
1	4	Boy's Restroom	Radiator	Metal	Grey	None	0	0.07	Negative
1	4	Electrical Room 428	W1	Plaster	Green	Chipping	1	0.07	Negative
1	4	Electrical Room 428	W2	Plaster	Green	Chipping	5	0.05	Negative
1	4	Electrical Room 428	W3	Plaster	Green	Chipping	3	0.05	Negative
1	4	Electrical Room 428	W4	Plaster	Green	None	0	0.04	Negative
1	4	Electrical Room 428	Ceiling	Plaster	Green	Chipping	4	0.07	Negative
1	4	Electrical Room 428	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Electrical Room 428	Pipe	Metal	Green	Chipping	1	0.36	Negative
1	4	Physics/Robotics Lab Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Physics/Robotics Lab Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Classroom 434	W1	Plaster	Tan	None	0	0.15	Negative
1	4	Classroom 434	W1	Plaster	White	None	0	0.14	Negative
1	4	Classroom 434	W2	Plaster	Tan	None	0	0.05	Negative
1	4	Classroom 434	W2	Plaster	White	None	0	0.07	Negative
1	4	Classroom 434	W3	Plaster	Tan	None	0	0	Negative
1	4	Classroom 434	W3	Plaster	White	None	0	0	Negative
1	4	Classroom 434	W4	Plaster	Tan	None	0	0.13	Negative
1	4	Classroom 434	W4	Plaster	White	None	0	0.06	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 434	Ceiling	Plaster	White	None	0	0.06	Negative
1	4	Classroom 434	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 434	Baseboard	Wood	Brown	None	0	0.08	Negative
1	4	Classroom 434	Pipe	Metal	White	None	0	0	Negative
1	4	Classroom 434	Radiator Cover	Metal	Brown	None	0	0.29	Negative
1	4	Classroom 434	Radiator	Metal	Silver	Chipping	1	4.86	Positive
1	4	Classroom 434	Window Frame	Wood	Brown	None	0	0.2	Negative
1	4	Classroom 434	Window Sill	Wood	Brown	None	0	0.15	Negative
1	4	Classroom 434	Whiteboard Frame	Wood	Brown	None	0	0.06	Negative
1	4	Classroom 434	Trim	Wood	Tan	None	0	0.08	Negative
1	4	Classroom 433	W1	Plaster	White	None	0	0.05	Negative
1	4	Classroom 433	W1	Plaster	Blue	None	0	0.07	Negative
1	4	Classroom 433	W2	Plaster	White	None	0	0	Negative
1	4	Classroom 433	W2	Plaster	Blue	None	0	0	Negative
1	4	Classroom 433	W3	Plaster	White	None	0	0.03	Negative
1	4	Classroom 433	W3	Plaster	Tan	None	0	0.05	Negative
1	4	Classroom 433	W4	Plaster	White	None	0	0.05	Negative
1	4	Classroom 433	W4	Plaster	Blue	None	0	0.11	Negative
1	4	Classroom 433	Ceiling	Plaster	White	Flaking	4	0.07	Negative
1	4	Classroom 433	Baseboard	Wood	Brown	None	0	0.08	Negative
1	4	Classroom 433	Radiator Cover	Metal	Brown	None	0	3.3	Positive
1	4	Classroom 433	Whiteboard Frame	Wood	Brown	None	0	0.06	Negative
1	4	Classroom 433	Window Sill	Wood	Brown	None	0	0.09	Negative
1	4	Classroom 433	Pipe	Metal	White	None	0	0	Negative
1	4	Classroom 433	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 432	W1	Plaster	White	None	0	0.13	Negative
1	4	Classroom 432	W1	Plaster	Tan	None	0	0.1	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 432	W2	Plaster	White	None	0	0.04	Negative
1	4	Classroom 432	W2	Plaster	Tan	None	0	0.08	Negative
1	4	Classroom 432	W3	Plaster	White	None	0	0.07	Negative
1	4	Classroom 432	W3	Plaster	Tan	None	0	0.09	Negative
1	4	Classroom 432	W4	Plaster	White	None	0	0.11	Negative
1	4	Classroom 432	W4	Plaster	Tan	None	0	0.14	Negative
1	4	Classroom 432	Ceiling	Plaster	White	Chipping	2	0.14	Negative
1	4	Classroom 432	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 432	Radiator Cover	Metal	Brown	None	0	0	Negative
1	4	Classroom 432	Radiator	Metal	Brown	None	0	0	Negative
1	4	Classroom 432	Window Frame	Wood	Brown	None	0	0.07	Negative
1	4	Classroom 432	Window Sill	Wood	Brown	None	0	0.16	Negative
1	4	Classroom 432	Baseboard	Wood	Brown	None	0	0.04	Negative
1	4	Classroom 432	Whiteboard Frame	Wood	Brown	None	0	0.04	Negative
1	4	Classroom 432	Pipe	Metal	White	None	0	0	Negative
1	4	Classroom 436	W1	Plaster	White	None	0	0.13	Negative
1	4	Classroom 436	W2	Plaster	White	None	0	0.22	Negative
1	4	Classroom 436	W3	Plaster	White	None	0	0.14	Negative
1	4	Classroom 436	W4	Plaster	White	None	0	0	Negative
1	4	Classroom 436	Ceiling	Plaster	White	Chipping	25	0.07	Negative
1	4	Classroom 436	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 436	Baseboard	Wood	Brown	None	0	0.02	Negative
1	4	Classroom 436	Window Sill	Wood	Brown	None	0	0.11	Negative
1	4	Classroom 436	Radiator	Metal	Silver	None	0	0.07	Negative
1	4	Classroom 436	Radiator	Metal	Silver	None	0	0.02	Negative
1	4	Classroom 437	W1	Plaster	White	None	0	0.01	Negative
1	4	Classroom 437	W1	Plaster	Tan	None	0	0.03	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Classroom 437	W2	Plaster	White	None	0	0.17	Negative
1	4	Classroom 437	W2	Plaster	Tan	None	0	0.1	Negative
1	4	Classroom 437	W3	Plaster	White	None	0	0.12	Negative
1	4	Classroom 437	W3	Plaster	Tan	None	0	0.08	Negative
1	4	Classroom 437	W4	Plaster	White	None	0	0.14	Negative
1	4	Classroom 437	W4	Plaster	Tan	None	0	0.11	Negative
1	4	Classroom 437	Ceiling	Plaster	White	Chipping	1	0.05	Negative
1	4	Classroom 437	Floor	9"x9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Classroom 437	Radiator	Metal	Silver	Chipping	1	2.97	Positive
1	4	Classroom 437	Radiator	Metal	Silver	Chipping	1	1.88	Positive
1	4	Classroom 437	Baseboard	Wood	Brown	None	0	0.04	Negative
1	4	Classroom 437	Window Frame	Wood	Brown	None	0	0.5	Negative
1	4	Classroom 437	Window Sill	Wood	Brown	None	0	0.14	Negative
1	4	Classroom 437	Whiteboard Frame	Wood	Brown	None	0	0.05	Negative
1	4	Classroom 437	Pipe	Metal	White	None	0	0	Negative
1	4	Classroom 437	Trim	Wood	White	None	0	0.03	Negative
1	4	Classroom 437	Trim	Wood	Brown	None	0	0.04	Negative
1	4	Storage Room in Small Hallway	W1	Sheet Rock	White	None	0	0	Negative
1	4	Storage Room in Small Hallway	W2	Plaster	White	None	0	0.11	Negative
1	4	Storage Room in Small Hallway	W3	Plaster	White	Efflorescence	5	0.13	Negative
1	4	Storage Room in Small Hallway	W4	Plaster	White	None	0	0.14	Negative
1	4	Storage Room in Small Hallway	Ceiling	Plaster	White	Chipping	3	0.29	Negative
1	4	Storage Room in Small Hallway	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Storage Room in Small Hallway	Pipe	Metal	White	Chipping	2	3.1	Positive
1	4	Hallway from IMC/Library to Room 411	W1	Plaster	White	Flaking	15	0.08	Negative
1	4	Hallway from IMC/Library to Room 411	W2	Plaster	White	None	0	0.45	Negative
1	4	Hallway from IMC/Library to Room 411	W3	Plaster	White	None	0	0.44	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Hallway from IMC/Library to Room 411	W4	Plaster	White	None	0	0.01	Negative
1	4	Hallway from IMC/Library to Room 411	Ceiling	Plaster	White	Chipping	10	0.06	Negative
1	4	Hallway from IMC/Library to Room 411	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway from IMC/Library to Room 411	Pipe 1	Metal	White	None	0	0.27	Negative
1	4	Hallway from IMC/Library to Room 411	Pipe 2	Metal	White	None	0	0.16	Negative
1	4	Hallway from IMC/Library to Room 411	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Hallway from IMC/Library to Room 411	Door Frame	Metal	Brown	Chipping	1	0.17	Negative
1	4	Hallway from IMC/Library to Room 411	Cork Board	Wood	Brown	Flaking	1	0.41	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	W1	Plaster	White	Flaking	6	0	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	W2	Plaster	White	None	0	0.16	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	W3	Plaster	White	None	0	0.24	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	W4	Plaster	White	None	0	0.22	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Ceiling	Plaster	White	Flaking	5	0.33	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Pipe 1	Metal	White	None	0	0.1	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Pipe 2	Metal	White	None	0	0.05	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Door Frame	Metal	Brown	None	0	0.19	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Pipe Cover	Metal	Brown	Chipping	1	0.1	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Pipe Cover	Metal	White	Chipping	3	0.2	Negative
1	4	Hallway from Elevator No. 2 near IMC to Classroom	Cork Board	Wood	Brown	Flaking	1	0.31	Negative
1	4	Hallway from Classroom 421 to Classroom 423	W1	Plaster	White	None	0	0.02	Negative
1	4	Hallway from Classroom 421 to Classroom 423	W2	Plaster	White	Flaking	5	0.16	Negative
1	4	Hallway from Classroom 421 to Classroom 423	W3	Plaster	White	None	0	0.26	Negative
1	4	Hallway from Classroom 421 to Classroom 423	W4	Plaster	White	Flaking	20	0.09	Negative
1	4	Hallway from Classroom 421 to Classroom 423	Ceiling	Plaster	White	Chipping	5	0.21	Negative
1	4	Hallway from Classroom 421 to Classroom 423	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	W1	Plaster	White	Flaking	10	0.42	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	W2	Plaster	White	None	0	0.15	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	W3	Plaster	White	Cracking	20	0.26	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	W4	Plaster	White	None	0	0.26	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	Ceiling	Plaster	White	Flaking	10	0.07	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	Stair Riser	Concrete	Black	Chipping	8	0.33	Negative
1	4	Hallway from Stairwell next to Lab 429 to Stairwe	Stringer	Concrete	Black	Chipping	5	0.31	Negative
1	4	Hallway from Classroom 432 to Classroom 434	W1	Plaster	White	Efflorescence	5	0.16	Negative
1	4	Hallway from Classroom 432 to Classroom 434	W2	Plaster	White	Efflorescence	40	0.08	Negative
1	4	Hallway from Classroom 432 to Classroom 434	W3	Plaster	White	None	0	0.23	Negative
1	4	Hallway from Classroom 432 to Classroom 434	W4	Plaster	White	Moisture Dama	10	0.28	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Ceiling	Plaster	White	Flaking	20	0.24	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway from Classroom 432 to Classroom 434	Univent	Metal	Brown	None	0	0.32	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Pipe Cover	Metal	White	Chipping	5	0.01	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Pipe Cover	Metal	Brown	Chipping	1	0.42	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Radiator Cover	Metal	White	None	0	0.16	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Window Frame	Wood	Brown	Moisture Dama	20	0.45	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Stair Riser	Concrete	Black	Chipping	5	0.12	Negative
1	4	Hallway from Classroom 432 to Classroom 434	Stringer	Concrete	Black	Chipping	10	0.36	Negative
1	4	Hallway from Classroom 434 to Classroom 437	W1	Plaster	White	Efflorescence	10	0.35	Negative
1	4	Hallway from Classroom 434 to Classroom 437	W2	Plaster	White	Moisture Dama	10	0.11	Negative
1	4	Hallway from Classroom 434 to Classroom 437	W3	Plaster	White	Chipping	1	0.19	Negative
1	4	Hallway from Classroom 434 to Classroom 437	W4	Plaster	White	Chipping	5	0.07	Negative
1	4	Hallway from Classroom 434 to Classroom 437	Ceiling	Plaster	White	Efflorescence	10	0.18	Negative
1	4	Hallway from Classroom 434 to Classroom 437	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Hallway from Classroom 434 to Classroom 437	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Hallway near Classroom 432 across to Classroom	W1	Plaster	White	None	0	0.26	Negative
1	4	Hallway near Classroom 432 across to Classroom	W2	Plaster	White	None	0	0.11	Negative
1	4	Hallway near Classroom 432 across to Classroom	W3	Plaster	White	None	0	0.43	Negative
1	4	Hallway near Classroom 432 across to Classroom	W4	Plaster	White	Efflorescence	5	0.26	Negative
1	4	Hallway near Classroom 432 across to Classroom	Ceiling	Plaster	White	Efflorescence	6	0.32	Negative
1	4	Hallway near Classroom 432 across to Classroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Hallway near Classroom 432 across to Classroom	Baseboard	Wood	Brown	Moisture Damage	10	0.26	Negative
1	4	Pipe Shaft between Restroom and Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Pipe Shaft between Restroom and Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Pipe Shaft between Restroom and Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Pipe Shaft between Restroom and Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Pipe Shaft between Restroom and Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Pipe Shaft between Restroom and Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Stairwell near Classroom 429	W1	Plaster	White	None	0	0.5	Negative
1	4	Stairwell near Classroom 429	W2	Plaster	White	None	0	0.13	Negative
1	4	Stairwell near Classroom 429	W3	Plaster	White	None	0	0.02	Negative
1	4	Stairwell near Classroom 429	W4	Plaster	White	None	0	0.24	Negative
1	4	Stairwell near Classroom 429	Ceiling	Plaster	White	None	0	0.24	Negative
1	4	Stairwell near Classroom 429	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Stairwell near Classroom 429	Stair Riser	Concrete	Grey	Friction	5	0.23	Negative
1	4	Stairwell near Classroom 429	Newel Post	Concrete	Grey	None	0	0.36	Negative
1	4	Stairwell near Classroom 429	Stringer	Concrete	Grey	None	0	0.3	Negative
1	4	Stairwell near Classroom 429	Spindle	Metal	Grey	None	0	0.02	Negative
1	4	Stairwell near Classroom 429	Trim	Concrete	Grey	None	0	0.36	Negative
1	4	Stairwell near Classroom 429	Pipe Cover	Metal	White	None	0	0.15	Negative
1	4	Stairwell near Classroom 429	Pipe Cover	Metal	Grey	None	0	0.31	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Stairwell next to Room 411	W1	Plaster	White	None	0	0.24	Negative
1	4	Stairwell next to Room 411	W2	Plaster	White	Flaking	5	0.01	Negative
1	4	Stairwell next to Room 411	W3	Plaster	White	Chipping	1	0.36	Negative
1	4	Stairwell next to Room 411	W4	Plaster	White	Moisture Damage	4	0.37	Negative
1	4	Stairwell next to Room 411	Ceiling	Plaster	White	None	0	0.41	Negative
1	4	Stairwell next to Room 411	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Stairwell next to Room 411	Stair Riser	Concrete	Grey	Friction	5	0.33	Negative
1	4	Stairwell next to Room 411	Newel Post	Concrete	Grey	None	0	4.73	Positive
1	4	Stairwell next to Room 411	Stringer	Concrete	Grey	None	0	1	Positive
1	4	Stairwell next to Room 411	Spindle	Metal	Grey	None	0	2.12	Positive
1	4	Stairwell next to Room 411	Trim	Concrete	Grey	None	0	0.31	Negative
1	4	Stairwell next to Room 411	Pipe Cover	Metal	White	None	0	0.39	Negative
1	4	Stairwell next to Room 411	Pipe Cover	Metal	Grey	None	0	0.36	Negative
1	4	Stairwell next to Room 411	Radiator	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Middle Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Stairwell near Classroom 401	W1	Plaster	White	None	0	0.29	Negative
1	4	Stairwell near Classroom 401	W2	Plaster	White	None	0	0.12	Negative
1	4	Stairwell near Classroom 401	W3	Plaster	White	None	0	0.2	Negative
1	4	Stairwell near Classroom 401	W4	Plaster	White	None	0	0.49	Negative
1	4	Stairwell near Classroom 401	Ceiling	Plaster	White	None	0	0.09	Negative
1	4	Stairwell near Classroom 401	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Stairwell near Classroom 401	Stair Riser	Concrete	Grey	None	0	0.5	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Stairwell near Classroom 401	Newel Post	Concrete	Grey	Friction	10	4.35	Positive
1	4	Stairwell near Classroom 401	Stringer	Concrete	Grey	None	0	0.34	Negative
1	4	Stairwell near Classroom 401	Spindle	Metal	Grey	None	0	1.46	Positive
1	4	Stairwell near Classroom 401	Trim	Concrete	Grey	None	0	0.3	Negative
1	4	Stairwell near Classroom 401	Pipe 1	Metal	White	None	0	0.16	Negative
1	4	Stairwell near Classroom 401	Pipe 2	Metal	Grey	None	0	0.2	Negative
1	4	Stairwell next to IMC/Library	W1	Plaster	White	None	0	0.18	Negative
1	4	Stairwell next to IMC/Library	W2	Plaster	White	None	0	0.49	Negative
1	4	Stairwell next to IMC/Library	W3	Plaster	White	None	0	0.05	Negative
1	4	Stairwell next to IMC/Library	W4	Plaster	White	None	0	0.26	Negative
1	4	Stairwell next to IMC/Library	Ceiling	Plaster	White	None	0	0.34	Negative
1	4	Stairwell next to IMC/Library	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Stairwell next to IMC/Library	Stair Riser	Concrete	Grey	Friction	5	0.02	Negative
1	4	Stairwell next to IMC/Library	Newel Post	Concrete	Grey	None	0	5.02	Positive
1	4	Stairwell next to IMC/Library	Stringer	Concrete	Grey	None	0	0.08	Negative
1	4	Stairwell next to IMC/Library	Spindle	Metal	Grey	None	0	1.9	Positive
1	4	Stairwell next to IMC/Library	Trim	Concrete	Grey	None	0	0.19	Negative
1	4	Stairwell next to IMC/Library	Pipe Cover	Metal	White	None	0	0.1	Negative
1	4	Stairwell next to IMC/Library	Pipe Cover	Metal	Grey	None	0	0.49	Negative
1	5	School Psychologist's Office 501	W1	Plaster	White	None	0	0.19	Negative
1	5	School Psychologist's Office 501	W2	Plaster	White	None	0	0.12	Negative
1	5	School Psychologist's Office 501	W3	Plaster	White	Efflorescence	3	0.18	Negative
1	5	School Psychologist's Office 501	W4	Plaster	White	None	0	0.32	Negative
1	5	School Psychologist's Office 501	W4	Sheet Rock	White	None	0	0.44	Negative
1	5	School Psychologist's Office 501	Window Sill	Wood	Brown	None	0	0.01	Negative
1	5	School Psychologist's Office 501	Ceiling	Plaster	White	Alligatoring	50	0.01	Negative
1	5	School Psychologist's Office 501	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Office 501 Restroom	W1	Plaster	White	None	0	0.37	Negative
1	5	Office 501 Restroom	W2	Plaster	White	Efflorescence	2	0.04	Negative
1	5	Office 501 Restroom	W3	Plaster	White	None	0	0.3	Negative
1	5	Office 501 Restroom	W4	Plaster	White	None	0	0.42	Negative
1	5	Office 501 Restroom	Pipe	Metal	White	None	0	0.04	Negative
1	5	Office 501 Restroom	Ceiling	Plaster	White	Efflorescence	1	0.11	Negative
1	5	Office 501 Restroom	Floor	9"x9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Office 501 IDF-1 Server Room; 501A	W1	Sheet Rock	Unpainted	N/A	N/A	N/A	N/A
1	5	Office 501 IDF-1 Server Room; 501A	W2	Plaster	White	None	0	0.25	Negative
1	5	Office 501 IDF-1 Server Room; 501A	W3	Plaster	White	Efflorescence	3	0.11	Negative
1	5	Office 501 IDF-1 Server Room; 501A	W4	Plaster	White	None	0	0.1	Negative
1	5	Office 501 IDF-1 Server Room; 501A	Mount	Wood	White	None	0	0.31	Negative
1	5	Office 501 IDF-1 Server Room; 501A	Pipe	Metal	White	None	0	0.17	Negative
1	5	Office 501 IDF-1 Server Room; 501A	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Office 501 IDF-1 Server Room; 501A	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 501A	W1	Plaster	White	Efflorescence	5	0.09	Negative
1	5	Classroom 501A	W2	Plaster	White	None	0	0.08	Negative
1	5	Classroom 501A	W3	Plaster	White	Efflorescence	15	0.42	Negative
1	5	Classroom 501A	W4	Plaster	White	Cracking	5	0.49	Negative
1	5	Classroom 501A	Ceiling	Plaster	White	Flaking	100	0.05	Negative
1	5	Classroom 501A	Whiteboard Frame	Wood	Brown	None	0	0.21	Negative
1	5	Classroom 501A	Window Sill	Wood	Brown	None	0	0.25	Negative
1	5	Classroom 501A	Window Frame	Wood	Brown	None	0	0.46	Negative
1	5	Classroom 501A	Radiator	Metal	Grey	Chipping	15	5.6	Positive
1	5	Classroom 501A	Baseboard	Concrete	Brown	None	0	0	Negative
1	5	Classroom 501A	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 502	W1	Plaster	White	None	0	0.32	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Classroom 502	W2	Plaster	White	None	0	0.11	Negative
1	5	Classroom 502	W3	Plaster	White	Efflorescence	20	0	Negative
1	5	Classroom 502	W4	Plaster	White	None	0	0.48	Negative
1	5	Classroom 502	Ceiling	Plaster	White	Alligatoring	10	0.01	Negative
1	5	Classroom 502	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 502	Radiator	Metal	Grey	Chipping	15	4.65	Positive
1	5	Classroom 502	Baseboard	Concrete	Brown	None	0	0.34	Negative
1	5	Classroom 502	Whiteboard Frame	Wood	Brown	Chipping	2	0.06	Negative
1	5	Classroom 503	Baseboard	Concrete	Brown	None	0	0.01	Negative
1	5	Classroom 503	Pipe	Metal	White	None	0	0.02	Negative
1	5	Classroom 503	Pipe	Metal	White	None	0	0.15	Negative
1	5	Classroom 503	Window Frame	Wood	Brown	None	0	0.05	Negative
1	5	Classroom 503	Window Sill	Wood	Brown	None	0	0.45	Negative
1	5	Classroom 503	W1	Plaster	White	Chipping	2	0.21	Negative
1	5	Classroom 503	W2	Plaster	White	Cracking	5	0.47	Negative
1	5	Classroom 503	W3	Plaster	White	Efflorescence	20	0.01	Negative
1	5	Classroom 503	W4	Plaster	White	Cracking	5	0.29	Negative
1	5	Classroom 503	Ceiling	Plaster	White	Chipping	75	0.02	Negative
1	5	Classroom 503	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 504	Baseboard	Concrete	Brown	None	0	0.25	Negative
1	5	Classroom 504	Radiator	Metal	Grey	Chipping	15	4.62	Positive
1	5	Classroom 504	Window Sill	Wood	Brown	None	0	0.3	Negative
1	5	Classroom 504	Pipe	Metal	White	None	0	0.24	Negative
1	5	Classroom 504	Pipe	Metal	White	None	0	0.07	Negative
1	5	Classroom 504	W1	Plaster	White	Chipping	5	0.16	Negative
1	5	Classroom 504	W2	Plaster	White	Cracking	5	0.27	Negative
1	5	Classroom 504	W3	Plaster	White	Efflorescence	20	0.21	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Classroom 504	W4	Plaster	White	Cracking	5	0.41	Negative
1	5	Classroom 504	Ceiling	Plaster	White	Alligatoring	50	0.03	Negative
1	5	Classroom 504	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 506	Window Sill	Wood	Brown	None	0	0	Negative
1	5	Classroom 506	Whiteboard Frame	Wood	Brown	None	0	0.49	Negative
1	5	Classroom 506	Baseboard	Concrete	Brown	None	0	0.06	Negative
1	5	Classroom 506	Radiator	Metal	Grey	Chipping	15	3.63	Positive
1	5	Classroom 506	Pipe	Metal	White	None	0	0.35	Negative
1	5	Classroom 506	W1	Plaster	White	None	0	0.21	Negative
1	5	Classroom 506	W2	Plaster	White	None	0	0.39	Negative
1	5	Classroom 506	W3	Plaster	White	Efflorescence	15	0.16	Negative
1	5	Classroom 506	W4	Plaster	White	None	0	0.03	Negative
1	5	Classroom 506	Ceiling	Plaster	White	Chipping	30	0.05	Negative
1	5	Classroom 506	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 507	Whiteboard Frame	Wood	Brown	None	0	0.4	Negative
1	5	Classroom 507	Baseboard	Concrete	Brown	None	0	0.47	Negative
1	5	Classroom 507	W1	Plaster	White	Efflorescence	20	0.08	Negative
1	5	Classroom 507	W2	Plaster	White	None	0	0.16	Negative
1	5	Classroom 507	W3	Plaster	White	Efflorescence	20	0.5	Negative
1	5	Classroom 507	W4	Plaster	White	None	0	0.17	Negative
1	5	Classroom 507	Ceiling	Plaster	White	Chipping	100	0.06	Negative
1	5	Classroom 507	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Cafeteria 509	W1	Brick	White	None	0	0.11	Negative
1	5	Cafeteria 509	W2	Brick	White	None	0	0.04	Negative
1	5	Cafeteria 509	W3	Brick	White	None	0	0.09	Negative
1	5	Cafeteria 509	W4	Brick	White	None	0	0.41	Negative
1	5	Cafeteria 509	Radiator	Metal	Grey	Chipping	50	0.19	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Cafeteria 509	Column	Brick	White	None	0	0.35	Negative
1	5	Cafeteria 509	Ceiling	spline	Unpainted	N/A	n/a	n/a	N/A
1	5	Cafeteria 509	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Kitchen 510	W1	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen 510	W2	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen 510	W3	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen 510	W4	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen 510	Ceiling	Plaster	White	Efflorescence	5	0.2	Negative
1	5	Kitchen 510	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Kitchen 510	Electric Panel cover	Metal	Grey	None	0	0.21	Negative
1	5	Kitchen 510	Door Frame	Metal	Grey	None	0	0.31	Negative
1	5	Kitchen 510	Fume Hood	Metal	Grey	None	0	0.13	Negative
1	5	Kitchen Dry Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Dry Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Dry Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Dry Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Dry Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Dry Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Kitchen Office	W1	Metal	Brown	None	0	0.11	Negative
1	5	Kitchen Office	W2	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen Office	W3	Sheet Rock	White	None	0	0.11	Negative
1	5	Kitchen Office	W4	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Kitchen Office	Ceiling	Plaster	White	Efflorescence	10	0.49	Negative
1	5	Kitchen Office	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Kitchen Office	Door Frame	Metal	Brown	Chipping	2	0.01	Negative
1	5	Kitchen Office	Door	Metal	Brown	Chipping	2	0.01	Negative
1	5	Kitchen Office	Pipe	Metal	Brown	None	0	0.06	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Area containing the Walk-in Refrigerator/Freezer	W1	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Area containing the Walk-in Refrigerator/Freezer	W2	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Area containing the Walk-in Refrigerator/Freezer	W3	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Area containing the Walk-in Refrigerator/Freezer	W4	Tile	Unpainted	N/A	N/A	n/a	N/A
1	5	Area containing the Walk-in Refrigerator/Freezer	Ceiling	Plaster	White	Efflorescence	10	0.26	Negative
1	5	Area containing the Walk-in Refrigerator/Freezer	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Faculty Lounge 512	W1	Plaster	White	None	0	0.08	Negative
1	5	Faculty Lounge 512	W2	Plaster	White	None	0	0.09	Negative
1	5	Faculty Lounge 512	W3	Plaster	White	None	0	0.17	Negative
1	5	Faculty Lounge 512	W4	Sheet Rock	White	None	0	0.14	Negative
1	5	Faculty Lounge 512	Ceiling	spline	Unpainted	N/A	n/a	n/a	N/A
1	5	Faculty Lounge 512	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Faculty Lounge 512	Moulding	Wood	White	None	0	0.01	Negative
1	5	Faculty Lounge 512	Baseboard	Concrete	Brown	None	0	0.36	Negative
1	5	Faculty Lounge 512	Radiator	Metal	Grey	Chipping	15	0.07	Negative
1	5	Cafeteria Staff Restroom 514	W1	Plaster	White	None	0	0.23	Negative
1	5	Cafeteria Staff Restroom 514	W2	Plaster	White	None	0	0.42	Negative
1	5	Cafeteria Staff Restroom 514	W3	Plaster	White	None	0	0.31	Negative
1	5	Cafeteria Staff Restroom 514	W4	Plaster	White	None	0	0.12	Negative
1	5	Cafeteria Staff Restroom 514	Ceiling	Plaster	White	None	0	0.37	Negative
1	5	Cafeteria Staff Restroom 514	Moulding	Wood	Brown	None	0	0.49	Negative
1	5	Cafeteria Staff Restroom 514	Baseboard	Wood	Brown	None	0	0.27	Negative
1	5	Cafeteria Staff Restroom 514	Radiator	Metal	Brown	Flaking	25	0.47	Negative
1	5	Cafeteria Staff Restroom 514	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Storeroom 513	W1	Plaster	White	None	0	0.21	Negative
1	5	Storeroom 513	W2	Plaster	White	None	0	0.02	Negative
1	5	Storeroom 513	W3	Plaster	White	Flaking	15	0.45	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Storeroom 513	W4	Plaster	White	Flaking	15	0.47	Negative
1	5	Storeroom 513	Ceiling	Plaster	White	None	0	0.38	Negative
1	5	Storeroom 513	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Storeroom 513	Ductwork	Metal	White	None	0	4.69	Positive
1	5	Storeroom 513	Baseboard	Concrete	Grey	None	0	0.08	Negative
1	5	Storeroom 513	Pipe	Metal	White	None	0	0.13	Negative
1	5	Boy's Restroom across from Classroom 507	W1	Plaster	White	Moisture Damage	50	0.14	Negative
1	5	Boy's Restroom across from Classroom 507	W2	Plaster	White	Flaking	15	0.28	Negative
1	5	Boy's Restroom across from Classroom 507	W3	Plaster	White	Moisture Damage	50	0.21	Negative
1	5	Boy's Restroom across from Classroom 507	W4	Plaster	White	Moisture Damage	50	0.06	Negative
1	5	Boy's Restroom across from Classroom 507	Ceiling	Plaster	White	Moisture Damage	150	0.25	Negative
1	5	Boy's Restroom across from Classroom 507	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Staff Restroom Vestibule/Storeroom	W1	Plaster	White	None	0	0.29	Negative
1	5	Staff Restroom Vestibule/Storeroom	W2	Plaster	White	None	0	0.02	Negative
1	5	Staff Restroom Vestibule/Storeroom	W3	Plaster	White	Cracking	10	0.32	Negative
1	5	Staff Restroom Vestibule/Storeroom	W4	Plaster	White	None	0	0.28	Negative
1	5	Staff Restroom Vestibule/Storeroom	Ceiling	Plaster	White	Chipping	50	0.46	Negative
1	5	Staff Restroom Vestibule/Storeroom	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Staff Restroom Vestibule/Storeroom	Pipe Cover	Metal	White	Chipping	5	0.26	Negative
1	5	Staff Restroom Vestibule/Storeroom	Baseboard	Wood	Brown	None	0	0.42	Negative
1	5	Staff Restroom Vestibule/Storeroom	Moulding	Wood	White	None	0	0.01	Negative
1	5	Staff Restroom Vestibule/Storeroom	Radiator	Metal	Grey	Chipping	5	0.46	Negative
1	5	Staff Restroom next to Electrical Room 519	W1	Plaster	White	None	0	0.22	Negative
1	5	Staff Restroom next to Electrical Room 519	W2	Plaster	White	None	0	0.31	Negative
1	5	Staff Restroom next to Electrical Room 519	W3	Plaster	White	None	0	0.17	Negative
1	5	Staff Restroom next to Electrical Room 519	W4	Plaster	White	None	0	0.38	Negative
1	5	Staff Restroom next to Electrical Room 519	Ceiling	Plaster	White	Chipping	2	0.12	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Staff Restroom next to Electrical Room 519	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Faculty Lounge IDF-2 Server Room	W1	Plaster	White	Chipping	5	0.01	Negative
1	5	Faculty Lounge IDF-2 Server Room	W2	Plaster	White	Efflorescence	20	0.03	Negative
1	5	Faculty Lounge IDF-2 Server Room	W3	Sheet Rock	White	None	0	0.15	Negative
1	5	Faculty Lounge IDF-2 Server Room	W4	Plaster	White	None	0	0.3	Negative
1	5	Faculty Lounge IDF-2 Server Room	Radiator	Metal	Grey	None	0	0.4	Negative
1	5	Faculty Lounge IDF-2 Server Room	Radiator Cover	Metal	Grey	None	0	0.29	Negative
1	5	Faculty Lounge IDF-2 Server Room	Board	Wood	White	None	0	0.12	Negative
1	5	Faculty Lounge IDF-2 Server Room	Ceiling	Plaster	White	Chipping	5	0.14	Negative
1	5	Faculty Lounge IDF-2 Server Room	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 521	W1	Plaster	White	None	0	0.07	Negative
1	5	Classroom 521	W2	Plaster	White	None	0	0.37	Negative
1	5	Classroom 521	W3	Plaster	White	Efflorescence	15	0.15	Negative
1	5	Classroom 521	W4	Plaster	White	None	0	0.17	Negative
1	5	Classroom 521	Ceiling	Plaster	White	Flaking	50	0.16	Negative
1	5	Classroom 521	Radiator	Metal	Brown	None	0	0.32	Negative
1	5	Classroom 521	Window Sill	Wood	Brown	None	0	0.41	Negative
1	5	Classroom 521	Whiteboard Frame	Wood	Brown	None	0	0.09	Negative
1	5	Classroom 521	Ductwork	Metal	White	None	0	0.31	Negative
1	5	Classroom 521	Whiteboard frame	Wood	Brown	None	0	0.25	Negative
1	5	Classroom 521	Baseboard	Wood	Brown	None	0	0.01	Negative
1	5	Classroom 521	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Storeroom 520	W1	Plaster	Green	Cracking	20	0.29	Negative
1	5	Storeroom 520	W2	Plaster	Green	Cracking	20	0	Negative
1	5	Storeroom 520	W3	Plaster	Green	Cracking	20	0.5	Negative
1	5	Storeroom 520	W4	Plaster	Green	Cracking	20	0.38	Negative
1	5	Storeroom 520	Ceiling	Plaster	White	None	0	0.18	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Storeroom 520	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Electrical Room 519	W1	Plaster	Green	Cracking	20	0.05	Negative
1	5	Electrical Room 519	W2	Plaster	Green	Cracking	20	0.12	Negative
1	5	Electrical Room 519	W3	Plaster	Green	Cracking	20	0.3	Negative
1	5	Electrical Room 519	W4	Plaster	Green	Cracking	20	0.26	Negative
1	5	Electrical Room 519	Ceiling	Plaster	White	None	0	0.23	Negative
1	5	Electrical Room 519	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Classroom 522	W1	Plaster	White	Chipping	15	0.22	Negative
1	5	Classroom 522	W2	Plaster	White	None	0	0.13	Negative
1	5	Classroom 522	W3	Plaster	White	Efflorescence	5	0.29	Negative
1	5	Classroom 522	W4	Plaster	White	Efflorescence	20	0.09	Negative
1	5	Classroom 522	Ceiling	Plaster	White	None	0	0.22	Negative
1	5	Classroom 522	Door	Wood	Brown	None	0	0.45	Negative
1	5	Classroom 522	Door Frame	Wood	Brown	None	0	0.31	Negative
1	5	Classroom 522	Radiator	Metal	Grey	None	0	0.29	Negative
1	5	Classroom 522	Baseboard	Wood	Grey	None	0	0.48	Negative
1	5	Classroom 522	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Prep Room 523	Window Frame	Wood	Brown	None	0	0.27	Negative
1	5	Prep Room 523	Window Sill	Wood	Brown	None	0	0.25	Negative
1	5	Prep Room 523	Baseboard	Wood	Brown	None	0	0.08	Negative
1	5	Prep Room 523	Radiator	Metal	Grey	None	0	0.37	Negative
1	5	Prep Room 523	Pipe	Metal	White	Chipping	1	0.47	Negative
1	5	Prep Room 523	Pipe Cover	Metal	White	Chipping	1	0.08	Negative
1	5	Prep Room 523	W1	Plaster	White	None	0	0.39	Negative
1	5	Prep Room 523	W2	Plaster	White	None	0	0.17	Negative
1	5	Prep Room 523	W3	Plaster	White	Efflorescence	30	0.4	Negative
1	5	Prep Room 523	W4	Plaster	White	Efflorescence	10	0.04	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Prep Room 523	Ceiling	Plaster	White	None	0	0.04	Negative
1	5	Prep Room 523	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Prep Room 523	Pipe Cover	Metal	White	Chipping	1	0.08	Negative
1	5	Prep Room 523	Radiator	Metal	Grey	Chipping	5	0.08	Negative
1	5	Prep Room 523	Baseboard	Wood	Brown	Friction	1	0.28	Negative
1	5	Prep Room 523	Whiteboard Frame	Wood	Brown	Chipping	2	0.3	Negative
1	5	Classroom 524	W1	Plaster	Red	Chipping	5	0.48	Negative
1	5	Classroom 524	W2	Plaster	Blue	None	0	0.32	Negative
1	5	Classroom 524	W3	Plaster	Orange	Efflorescence	15	0.28	Negative
1	5	Classroom 524	W4	Plaster	Green	Efflorescence	1	0.28	Negative
1	5	Classroom 524	Ceiling	Plaster	White	None	0	0.04	Negative
1	5	Classroom 524	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	TechNology Storeroom next to Girl's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	TechNology Storeroom next to Girl's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	TechNology Storeroom next to Girl's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	TechNology Storeroom next to Girl's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	TechNology Storeroom next to Girl's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	TechNology Storeroom next to Girl's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Custodial Closet next to Elevator No. 1	W1	Plaster	White	None	0	0.21	Negative
1	5	Custodial Closet next to Elevator No. 1	W2	Plaster	White	None	0	0.47	Negative
1	5	Custodial Closet next to Elevator No. 1	W3	Plaster	White	Cracking	5	0.44	Negative
1	5	Custodial Closet next to Elevator No. 1	W4	Plaster	White	Chipping	5	0.1	Negative
1	5	Custodial Closet next to Elevator No. 1	Ceiling	Plaster	White	None	0	0.17	Negative
1	5	Custodial Closet next to Elevator No. 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Custodial Closet next to Elevator No. 1	Shelf	Wood	White	Friction	5	0.48	Negative
1	5	Girl's Restroom across from Room 501A	W1	Plaster	White	None	0	0.38	Negative
1	5	Girl's Restroom across from Room 501A	W2	Plaster	White	None	0	0.29	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Girl's Restroom across from Room 501A	W3	Plaster	White	Efflorescence	5	0.06	Negative
1	5	Girl's Restroom across from Room 501A	W4	Plaster	White	Efflorescence	1	0.12	Negative
1	5	Girl's Restroom across from Room 501A	Ceiling	Plaster	White	None	0	0.25	Negative
1	5	Girl's Restroom across from Room 501A	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	5	Girl's Restroom across from Room 501A	Radiator	Metal	Grey	Chipping	25	0.48	Negative
1	5	Girl's Restroom across from Room 501A	Pipe	Metal	White	None	0	0.34	Negative
1	5	Theater Room 529	Ductwork	Metal	Blue	None	0	0.21	Negative
1	5	Theater Room 529	Radiator	Metal	Blue	None	0	0.49	Negative
1	5	Theater Room 529	Pipe Cover	Metal	Blue	None	0	0.2	Negative
1	5	Theater Room 529	Univent	Metal	Blue	Friction	20	0.02	Negative
1	5	Theater Room 529	Baseboard	Concrete	Grey	None	0	0.09	Negative
1	5	Theater Room 529	W1	Plaster	Blue	Chipping	5	0.15	Negative
1	5	Theater Room 529	W2	Plaster	Blue	Chipping	5	0.03	Negative
1	5	Theater Room 529	W3	Plaster	Blue	Efflorescence	10	0.44	Negative
1	5	Theater Room 529	W4	Plaster	Blue	Chipping	5	0.18	Negative
1	5	Theater Room 529	Ceiling	Plaster	White	None	0	0.18	Negative
1	5	Theater Room 529	Floor	carpet	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Cafeteria to Teacher's Lounge	W1	Plaster	White	Flaking	20	0.21	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	W2 Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Cafeteria to Teacher's Lounge	W3	Plaster	White	Efflorescence	20	0.34	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	W4 Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Cafeteria to Teacher's Lounge	Ceiling	Plaster	White	Flaking	100	0.09	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator	Metal	Grey	Chipping	10	0.46	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator Cover	Metal	Grey	None	0	0.21	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator Cover	Metal	White	None	0	0.14	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator	Metal	Grey	Chipping	10	0.25	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator Cover	Metal	Grey	Chipping	2	0.17	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Radiator Cover	Metal	White	None	0	0.15	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Door Frame	Metal	Brown	Friction	10	0.19	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Door	Wood	Brown	None	0	0.49	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Door Frame	Wood	Brown	None	0	0.28	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Pipe Cover	Metal	White	Chipping	1	0.3	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Panel	Metal	White	None	0	0.18	Negative
1	5	Hallway from Cafeteria to Teacher's Lounge	Trim	Concrete	Brown	None	0	0.47	Negative
1	5	Hallway from Room 501 to Classroom 507	W1	Plaster	White	None	0	0.04	Negative
1	5	Hallway from Room 501 to Classroom 507	W2	Plaster	White	Moisture Damage	15	0.3	Negative
1	5	Hallway from Room 501 to Classroom 507	W3	Plaster	White	Moisture Damage	15	0.25	Negative
1	5	Hallway from Room 501 to Classroom 507	W4	Plaster	White	Moisture Damage	10	0.2	Negative
1	5	Hallway from Room 501 to Classroom 507	Ceiling	Plaster	White	Chipping	500	0.02	Negative
1	5	Hallway from Room 501 to Classroom 507	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Room 501 to Classroom 507	Trim	Concrete	Brown	None	0	0.47	Negative
1	5	Hallway from Classroom 521 to Classroom 522	W1	Plaster	White	None	0	0.31	Negative
1	5	Hallway from Classroom 521 to Classroom 522	W2	Plaster	White	None	0	0.19	Negative
1	5	Hallway from Classroom 521 to Classroom 522	W3	Plaster	White	None	0	0.28	Negative
1	5	Hallway from Classroom 521 to Classroom 522	W4	Plaster	White	None	0	0.49	Negative
1	5	Hallway from Classroom 521 to Classroom 522	Ceiling	Plaster	White	Flaking	75	0.01	Negative
1	5	Hallway from Classroom 521 to Classroom 522	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Stairwell next to Theater Room 529	W1	Plaster	White	Efflorescence	20	0.37	Negative
1	5	Hallway from Stairwell next to Theater Room 529 to Stairwell next to Office 501	W2 Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Stairwell next to Theater Room 529	W3	Plaster	White	Efflorescence	20	0.16	Negative
1	5	Hallway from Stairwell next to Theater Room 529 to Stairwell next to Office 501	W4 Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	5	Hallway from Stairwell next to Theater Room 529	Ceiling	Plaster	White	Chipping	100	0.16	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Hallway from Stairwell next to Theater Room 529	Radiator	Metal	Grey	Chipping	10	0.18	Negative
1	5	Hallway from Stairwell next to Theater Room 529	Radiator Cover	Metal	Grey	None	0	0.46	Negative
1	5	Hallway from Stairwell next to Theater Room 529	Radiator Cover	Metal	White	None	0	0.38	Negative
1	5	Hallway from Stairwell next to Theater Room 529	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Pipe Shaft between Boy's Restroom and Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Pipe Shaft between Boy's Restroom and Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Pipe Shaft between Boy's Restroom and Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Pipe Shaft between Boy's Restroom and Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Pipe Shaft between Boy's Restroom and Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Pipe Shaft between Boy's Restroom and Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell near Room 529	W1	Plaster	White	None	0	0.18	Negative
1	5	Stairwell near Room 529	W2	Plaster	White	Efflorescence	25	0.25	Negative
1	5	Stairwell near Room 529	W3	Plaster	White	None	0	0.27	Negative
1	5	Stairwell near Room 529	W4	Plaster	White	None	0	0.05	Negative
1	5	Stairwell near Room 529	Ceiling	Plaster	White	None	0	0.41	Negative
1	5	Stairwell near Room 529	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Stairwell near Room 529	Stair Riser	Concrete	Grey	None	0	0.3	Negative
1	5	Stairwell near Room 529	Newel Post	Concrete	Grey	Friction	1	5.2	Positive
1	5	Stairwell near Room 529	Stringer	Concrete	Grey	None	0	0.41	Negative
1	5	Stairwell near Room 529	Spindle	Metal	Grey	None	0	2	Positive
1	5	Stairwell near Room 529	Trim	Concrete	Grey	None	0	0.08	Negative
1	5	Stairwell near Room 529	Radiator	Metal	Grey	Chipping	20	0.15	Negative
1	5	Stairwell near Room 529	Radiator Cover	Metal	White	None	0	0.49	Negative
1	5	Stairwell near Room 529	Pipe Cover	Plastic	White	None	0	0.18	Negative
1	5	Stairwell next to Faculty Lounge	Stair Riser	Concrete	Grey	None	0	0.06	Negative
1	5	Stairwell next to Faculty Lounge	Newel Post	Concrete	Grey	Friction	1	6.3	Positive
1	5	Stairwell next to Faculty Lounge	Stringer	Concrete	Grey	None	0	0.19	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Stairwell next to Faculty Lounge	Spindle	Metal	Grey	None	0	1.89	Positive
1	5	Stairwell next to Faculty Lounge	Trim	Concrete	Grey	None	0	0.32	Negative
1	5	Stairwell next to Faculty Lounge	Radiator	Metal	Grey	Chipping	25	0.29	Negative
1	5	Stairwell next to Faculty Lounge	Radiator Cover	Metal	White	None	0	0.35	Negative
1	5	Stairwell next to Faculty Lounge	Pipe Cover	Plastic	White	None	0	0.2	Negative
1	5	Stairwell next to Faculty Lounge	W1	Plaster	White	None	0	0.09	Negative
1	5	Stairwell next to Faculty Lounge	W2	Plaster	White	None	0	0.25	Negative
1	5	Stairwell next to Faculty Lounge	W3	Plaster	White	None	0	0.43	Negative
1	5	Stairwell next to Faculty Lounge	W4	Plaster	White	None	0	0.39	Negative
1	5	Stairwell next to Faculty Lounge	Ceiling	Plaster	White	Moisture Damage	10	0.07	Negative
1	5	Stairwell next to Faculty Lounge	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Stairwell next to Classroom 524	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Classroom 524	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Classroom 524	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Classroom 524	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Classroom 524	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Classroom 524	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	Stairwell next to Office 501	W1	Plaster	White	None	0	0.16	Negative
1	5	Stairwell next to Office 501	W2	Plaster	White	Moisture Damage	5	0.47	Negative
1	5	Stairwell next to Office 501	W3	Plaster	White	Efflorescence	10	0.42	Negative
1	5	Stairwell next to Office 501	W4	Plaster	White	Efflorescence	3	0.45	Negative
1	5	Stairwell next to Office 501	Ceiling	Plaster	White	None	0	0.16	Negative
1	5	Stairwell next to Office 501	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Stairwell next to Office 501	Stair Riser	Concrete	Grey	None	0	0.13	Negative
1	5	Stairwell next to Office 501	Newel Post	Concrete	Grey	Friction	4	3.8	Positive
1	5	Stairwell next to Office 501	Stringer	Concrete	Grey	None	0	0.19	Negative
1	5	Stairwell next to Office 501	Spindle	Metal	Grey	None	0	2.1	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	Stairwell next to Office 501	Trim	Concrete	Grey	None	0	0.44	Negative
1	5	Stairwell next to Office 501	Radiator	Metal	Grey	Chipping	25	0.02	Negative
1	5	Stairwell next to Office 501	Radiator Cover	Metal	White	None	0	0.18	Negative
1	5	Stairwell next to Office 501	Pipe	Metal	White	None	0	0.4	Negative
1	5	Stairwell next to Cafeteria	Stair Riser	Concrete	Grey	None	0	0.29	Negative
1	5	Stairwell next to Cafeteria	Newel Post	Concrete	Grey	Friction	4	4.6	Positive
1	5	Stairwell next to Cafeteria	Stringer	Concrete	Grey	None	0	0.47	Negative
1	5	Stairwell next to Cafeteria	Spindle	Metal	Grey	None	0	2.5	Positive
1	5	Stairwell next to Cafeteria	Trim	Concrete	Grey	None	0	0.23	Negative
1	5	Stairwell next to Cafeteria	Radiator	Metal	Grey	Chipping	20	0.04	Negative
1	5	Stairwell next to Cafeteria	Radiator Cover	Metal	White	None	0	0.26	Negative
1	5	Stairwell next to Cafeteria	Pipe	Metal	White	None	0	0.31	Negative
1	5	Stairwell next to Cafeteria	W1	Plaster	White	None	0	0.13	Negative
1	5	Stairwell next to Cafeteria	W2	Plaster	White	Cracking	10	0.35	Negative
1	5	Stairwell next to Cafeteria	W3	Plaster	White	None	0	0.36	Negative
1	5	Stairwell next to Cafeteria	W4	Plaster	White	None	0	0.11	Negative
1	5	Stairwell next to Cafeteria	Ceiling	Plaster	White	None	0	0.09	Negative
1	5	Stairwell next to Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Wrestling Practice Room	W1	Brick	White	Chipping	1	0.14	Negative
1	6	Wrestling Practice Room	W2	Brick	White	None	0	0.39	Negative
1	6	Wrestling Practice Room	W3	Brick	White	Efflorescence	5	0.28	Negative
1	6	Wrestling Practice Room	W4	Brick	White	None	0	0.01	Negative
1	6	Wrestling Practice Room	Pipe	Metal	White	Flaking	15	0.27	Negative
1	6	Wrestling Practice Room	Pipe	Metal	White	None	0	0.21	Negative
1	6	Wrestling Practice Room	Pipe	Metal	White	Flaking	2	0.41	Negative
1	6	Wrestling Practice Room	Window Frame	Wood	White	Cracking	5	0.35	Negative
1	6	Wrestling Practice Room	Column	Brick	White	Moisture Damage	4	0.44	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Wrestling Practice Room	Ceiling	Concrete	White	Flaking	40	0.44	Negative
1	6	Wrestling Practice Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	6	Wrestling Practice Room Storage Area	W1	Brick	White	None	0	0.45	Negative
1	6	Wrestling Practice Room Storage Area	W2	Brick	White	Efflorescence	15	0.42	Negative
1	6	Wrestling Practice Room Storage Area	W3	Brick	White	Efflorescence	20	0.18	Negative
1	6	Wrestling Practice Room Storage Area	W4	Partition wall	Unpainted	N/A	N/A	N/A	N/A
1	6	Wrestling Practice Room Storage Area	Radiator	Metal	Grey	Flaking	15	No Access	No Access
1	6	Wrestling Practice Room Storage Area	Ceiling	Concrete	White	Flaking	15	0.33	Negative
1	6	Wrestling Practice Room Storage Area	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 604 Girl's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 604 Girl's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 604 Girl's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 604 Girl's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 604 Girl's Restroom	Pipe	Metal	White	None	0	0.45	Negative
1	6	Room 604 Girl's Restroom	Pipe	Metal	Brown	None	0	0.49	Negative
1	6	Room 604 Girl's Restroom	Pipe	Metal	White	None	0	0.49	Negative
1	6	Room 604 Girl's Restroom	Pipe	Metal	Brown	None	0	0.02	Negative
1	6	Room 604 Girl's Restroom	Pipe	Metal	Brown	Chipping	1	0.32	Negative
1	6	Room 604 Girl's Restroom	Radiator	Metal	Grey	Flaking	15	No Access	No Access
1	6	Room 604 Girl's Restroom	Radiator	Metal	Grey	Flaking	15	No Access	No Access
1	6	Room 604 Girl's Restroom	Ceiling	Concrete	White	Flaking	15	0.15	Negative
1	6	Room 604 Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Room 603 Storage	W1	Brick	White	None	0	0.33	Negative
1	6	Room 603 Storage	W2	Brick	White	None	0	0.46	Negative
1	6	Room 603 Storage	W3	Brick	White	None	0	0.1	Negative
1	6	Room 603 Storage	W4	Brick	White	Efflorescence	10	0.12	Negative
1	6	Room 603 Storage	Shelf	Wood	White	None	0	0.04	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Room 603 Storage	Pipe	Metal	White	Chipping	5	0.21	Negative
1	6	Room 603 Storage	Ceiling	Plaster	White	Flaking	10	0.42	Negative
1	6	Room 603 Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Elevator No. 1 Penthouse	W1	Brick	White	Flaking	100	0.2	Negative
1	6	Elevator No. 1 Penthouse	W2	Brick	White	Flaking	100	0.05	Negative
1	6	Elevator No. 1 Penthouse	W3	Brick	White	Flaking	100	0.14	Negative
1	6	Elevator No. 1 Penthouse	W4	Brick	White	Flaking	100	0.08	Negative
1	6	Elevator No. 1 Penthouse	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Elevator No. 1 Penthouse	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	602 Storage Room in Hallway near Elevator 1 an	W1	Brick	White	Efflorescence	5	0.02	Negative
1	6	602 Storage Room in Hallway near Elevator 1 an	W2	Brick	White	Efflorescence	20	0.43	Negative
1	6	602 Storage Room in Hallway near Elevator 1 an	W3	Plaster	White	Cracking	50	0.13	Negative
1	6	602 Storage Room in Hallway near Elevator 1 an	W4	Brick	White	None	0	0.33	Negative
1	6	602 Storage Room in Hallway near Elevator 1 an	Ceiling	Plaster	White	Moisture Dama	10	0.24	Negative
1	6	602 Storage Room in Hallway near Elevator 1 an	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Boy's Restroom	W1	Brick	White	None	0	0.1	Negative
1	6	Boy's Restroom	W1	Plaster	White	Chipping	5	0.45	Negative
1	6	Boy's Restroom	W2	Brick	White	None	0	0.19	Negative
1	6	Boy's Restroom	W3	Brick	White	None	0	0.24	Negative
1	6	Boy's Restroom	W4	Brick	White	None	0	0.32	Negative
1	6	Boy's Restroom	Radiator	Metal	Unpainted	N/A	N/A	N/A	N/A
1	6	Boy's Restroom	Radiator	Metal	Unpainted	N/A	N/A	N/A	N/A
1	6	Boy's Restroom	Pipe	Metal	White	None	0	0.44	Negative
1	6	Boy's Restroom	Pipe	Metal	Brown	None	0	0.2	Negative
1	6	Boy's Restroom	Pipe	Metal	White	None	0	0.32	Negative
1	6	Boy's Restroom	Pipe	Metal	Brown	None	0	0.25	Negative
1	6	Boy's Restroom	Ceiling	Concrete	White	Flaking	15	0.32	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Elevator No. 2 Penthouse	W1	Brick	White	Flaking	100	0.01	Negative
1	6	Elevator No. 2 Penthouse	W2	Brick	White	Flaking	100	0.07	Negative
1	6	Elevator No. 2 Penthouse	W3	Brick	White	Flaking	100	0.46	Negative
1	6	Elevator No. 2 Penthouse	W4	Brick	White	Flaking	100	0.42	Negative
1	6	Elevator No. 2 Penthouse	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Elevator No. 2 Penthouse	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Large Storage Area near Elevator No. 2	W1	Brick	White	None	0	0.09	Negative
1	6	Large Storage Area near Elevator No. 2	W2	Brick	White	Moisture Dama	10	0.39	Negative
1	6	Large Storage Area near Elevator No. 2	W3	Brick	White	Moisture Dama	40	0.48	Negative
1	6	Large Storage Area near Elevator No. 2	W4	Brick	White	Moisture Dama	40	0.44	Negative
1	6	Large Storage Area near Elevator No. 2	Radiator	Metal	Grey	Flaking	15	0.33	Negative
1	6	Large Storage Area near Elevator No. 2	Radiator	Metal	Grey	Flaking	15	0.27	Negative
1	6	Large Storage Area near Elevator No. 2	Radiator	Metal	Grey	Flaking	15	0.42	Negative
1	6	Large Storage Area near Elevator No. 2	Radiator	Metal	Grey	Flaking	15	0.44	Negative
1	6	Large Storage Area near Elevator No. 2	Column	Brick	White	Chipping	5	0.18	Negative
1	6	Large Storage Area near Elevator No. 2	Pipe	Metal	White	Chipping	10	0.45	Negative
1	6	Large Storage Area near Elevator No. 2	Ceiling	Concrete	White	Moisture Dama	40	0.05	Negative
1	6	Large Storage Area near Elevator No. 2	Floor	Wood	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	W1	N/A	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	W2	N/A	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	W3	N/A	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	W4	N/A	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	Ceiling	N/A	Unpainted	No access	No access	No access	No access
1	6	Fan Room next to Stairwell	Floor	N/A	Unpainted	No access	No access	No access	No access
1	6	Room 607 Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	6	Room 607 Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Room 607 Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	6	Room 607 Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	6	Room 607 Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	6	Room 607 Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	W1	Brick	White	None	0	0.42	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	W2	Brick	White	Cracking	5	0.31	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	W3	Brick	White	None	0	0.11	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	W4	Brick	White	None	0	0.01	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	Radiator	Metal	Grey	Flaking	15	0.3	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	Door	Metal	Brown	Flaking	5	0.22	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	Door Frame	Metal	Brown	Flaking	1	0.46	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	Ceiling	Concrete	White	Cracking	20	0.42	Negative
1	6	Hallway from near Elevator No. 2 to Roof Top Pla	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	W1	Brick	White	None	0	0.09	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	W2	Brick	White	None	0	0.1	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	W3	Brick	White	None	0	0.4	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	W4	Brick	White	None	0	0.07	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Radiator	Metal	Grey	Flaking	15	No Access	No Access
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Door	Metal	Brown	Chipping	2	0.49	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Door Frame	Metal	Brown	Chipping	2	0.14	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Door	Metal	Brown	Chipping	1	0.34	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Door Frame	Metal	Brown	Chipping	1	0.16	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Ceiling	Concrete	White	Flaking	15	0.08	Negative
1	6	Hallway from near Elevator No. 1 to Roof Top Pla	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Stairwell in Wrestling Practice Room	W1	Plaster	White	Efflorescence	5	0.3	Negative
1	6	Stairwell in Wrestling Practice Room	W2	Plaster	White	Efflorescence	5	0.24	Negative
1	6	Stairwell in Wrestling Practice Room	W3	Plaster	White	Efflorescence	70	0.36	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Stairwell in Wrestling Practice Room	W4	Plaster	White	Efflorescence	5	0.44	Negative
1	6	Stairwell in Wrestling Practice Room	Radiator	Metal	Grey	Flaking	5	0.07	Negative
1	6	Stairwell in Wrestling Practice Room	Trim	Concrete	Grey	Flaking	10	1	Positive
1	6	Stairwell in Wrestling Practice Room	Spindle	Metal	Grey	None	0	4.1	Positive
1	6	Stairwell in Wrestling Practice Room	Stringer	Concrete	Grey	None	0	1	Positive
1	6	Stairwell in Wrestling Practice Room	Stair Riser	Concrete	Grey	None	0	0.45	Negative
1	6	Stairwell in Wrestling Practice Room	Newel Post	Metal	Grey	None	0	10	Positive
1	6	Stairwell in Wrestling Practice Room	Ceiling	Plaster	White	Efflorescence	15	0.23	Negative
1	6	Stairwell in Wrestling Practice Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Stairwell next to Large Storage Area	W1	Plaster	White	Efflorescence	10	0.08	Negative
1	6	Stairwell next to Large Storage Area	W2	Plaster	White	None	0	0.19	Negative
1	6	Stairwell next to Large Storage Area	W3	Plaster	White	Efflorescence	50	0.09	Negative
1	6	Stairwell next to Large Storage Area	W4	Plaster	White	Efflorescence	20	0.22	Negative
1	6	Stairwell next to Large Storage Area	Trim	Concrete	Grey	Flaking	1	0.17	Negative
1	6	Stairwell next to Large Storage Area	Spindle	Metal	Grey	None	0	3.7	Positive
1	6	Stairwell next to Large Storage Area	Stringer	Concrete	Grey	None	0	0.36	Negative
1	6	Stairwell next to Large Storage Area	Stair Riser	Concrete	Grey	Chipping	10	0.8	Positive
1	6	Stairwell next to Large Storage Area	Newel Post	Metal	Grey	None	0	3.3	Positive
1	6	Stairwell next to Large Storage Area	Window Rail	Metal	Grey	Flaking	5	0.29	Negative
1	6	Stairwell next to Large Storage Area	Ceiling	Plaster	White	Efflorescence	30	0.1	Negative
1	6	Stairwell next to Large Storage Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Stairwell near Elevator No. 1	W1	Plaster	White	Efflorescence	15	0.07	Negative
1	6	Stairwell near Elevator No. 1	W2	Plaster	White	Efflorescence	50	0.42	Negative
1	6	Stairwell near Elevator No. 1	W3	Plaster	White	Efflorescence	50	0.09	Negative
1	6	Stairwell near Elevator No. 1	W4	Plaster	White	None	0	0.38	Negative
1	6	Stairwell near Elevator No. 1	Pipe	Metal	White	None	0	0.16	Negative
1	6	Stairwell near Elevator No. 1	Pipe	Metal	Grey	Chipping	1	0.43	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	6	Stairwell near Elevator No. 1	Pipe	Metal	White	None	0	0.23	Negative
1	6	Stairwell near Elevator No. 1	Radiator	Metal	Grey	Flaking	5	0.41	Negative
1	6	Stairwell near Elevator No. 1	Trim	Concrete	Grey	Flaking	5	0.26	Negative
1	6	Stairwell near Elevator No. 1	Spindle	Metal	Grey	Flaking	1	3.2	Positive
1	6	Stairwell near Elevator No. 1	Stringer	Concrete	Grey	None	0	0.35	Negative
1	6	Stairwell near Elevator No. 1	Stair Riser	Concrete	Grey	None	0	0.2	Negative
1	6	Stairwell near Elevator No. 1	Newel Post	Metal	Grey	None	0	7.8	Positive
1	6	Stairwell near Elevator No. 1	Ceiling	Plaster	White	Efflorescence	10	0.01	Negative
1	6	Stairwell near Elevator No. 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	6	Stairwell near Elevator No. 2	W1	Plaster	White	Efflorescence	20	0.07	Negative
1	6	Stairwell near Elevator No. 2	W2	Plaster	White	None	0	0.02	Negative
1	6	Stairwell near Elevator No. 2	W3	Plaster	White	Efflorescence	10	0.34	Negative
1	6	Stairwell near Elevator No. 2	W4	Plaster	White	Efflorescence	10	0.1	Negative
1	6	Stairwell near Elevator No. 2	Pipe	Metal	White	None	0	0.41	Negative
1	6	Stairwell near Elevator No. 2	Pipe	Metal	Grey	Chipping	2	0.11	Negative
1	6	Stairwell near Elevator No. 2	Pipe	Metal	White	None	0	0.07	Negative
1	6	Stairwell near Elevator No. 2	Radiator	Metal	Grey	None	0	0.3	Negative
1	6	Stairwell near Elevator No. 2	Trim	Concrete	Grey	None	0	1	Positive
1	6	Stairwell near Elevator No. 2	Spindle	Metal	Grey	None	0	2	Positive
1	6	Stairwell near Elevator No. 2	Stringer	Concrete	Grey	None	0	1	Positive
1	6	Stairwell near Elevator No. 2	Stair Riser	Concrete	Grey	None	0	1	Positive
1	6	Stairwell near Elevator No. 2	Newel Post	Metal	Grey	None	0	7.7	Positive
1	6	Stairwell near Elevator No. 2	Ceiling	Plaster	White	Efflorescence	5	0.32	Negative
1	6	Stairwell near Elevator No. 2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic above Auditorium on 3rd Floor adjacent to R	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic above Auditorium on 3rd Floor adjacent to R	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic above Auditorium on 3rd Floor adjacent to R	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	A	Attic above Auditorium on 3rd Floor adjacent to R	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic above Auditorium on 3rd Floor adjacent to R	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic above Auditorium on 3rd Floor adjacent to R	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic between 5th and 6th floor (STAIRWELL)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Construction Office Room B24 Storage #9	W1	Brick	White	None	0	0.15	Negative
1	B	Construction Office Room B24 Storage #9	W1	Brick	Tan	None	0	0.02	Negative
1	B	Construction Office Room B24 Storage #9	W1	Wood	White	None	0	7.64	Positive
1	B	Construction Office Room B24 Storage #9	W2	Brick	White	None	0	0.17	Negative
1	B	Construction Office Room B24 Storage #9	W2	Brick	Tan	None	0	0.01	Negative
1	B	Construction Office Room B24 Storage #9	W3	Brick	White	None	0	0.22	Negative
1	B	Construction Office Room B24 Storage #9	W3	Brick	Tan	None	0	0.01	Negative
1	B	Construction Office Room B24 Storage #9	W4	Brick	White	Chipping	3	0.1	Negative
1	B	Construction Office Room B24 Storage #9	W4	Brick	Tan	None	0	0.01	Negative
1	B	Construction Office Room B24 Storage #9	Ceiling	Concrete	White	Chipping	5	0.16	Negative
1	B	Construction Office Room B24 Storage #9	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Construction Office Room B24 Storage #9	Radiator Cover	Metal	Blue	Chipping	2	0.05	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Construction Office Room B24 Storage #9	Radiator Cover	Metal	White	None	0	0.14	Negative
1	B	Construction Office Room B24 Storage #9	Ductwork	Metal	White	Chipping	5	8.61	Positive
1	B	Construction Office Room B24 Storage #9	Pipe	Metal	White	Chipping	2	5.58	Positive
1	B	Construction Office Room B24 Storage #9	Wall Divider	Wood	Tan	None	0	0.06	Negative
1	B	Construction Office Room B24 Storage #9	Door	Wood	Tan	None	0	0.12	Negative
1	B	Construction Office Room B24 Storage #9	Door Frame	Wood	Tan	None	0	0.06	Negative
1	B	Room 7 Custodial Staff Breakroom	W1	Brick	White	None	0	1.11	Positive
1	B	Room 7 Custodial Staff Breakroom	W1	Brick	Unpainted	None	0	0.06	Negative
1	B	Room 7 Custodial Staff Breakroom	W2	Brick	White	None	0	1.85	Positive
1	B	Room 7 Custodial Staff Breakroom	W2	Brick	Unpainted	None	0	0.01	Negative
1	B	Room 7 Custodial Staff Breakroom	W3	Brick	White	None	0	2.87	Positive
1	B	Room 7 Custodial Staff Breakroom	W3	Brick	Unpainted	None	0	0.02	Negative
1	B	Room 7 Custodial Staff Breakroom	W4	Brick	White	None	0	1.28	Positive
1	B	Room 7 Custodial Staff Breakroom	W4	Brick	Unpainted	None	0	0.02	Negative
1	B	Room 7 Custodial Staff Breakroom	Door	Metal	Grey	None	0	0	Negative
1	B	Room 7 Custodial Staff Breakroom	Ductwork	Metal	White	None	0	0.13	Negative
1	B	Room 7 Custodial Staff Breakroom	Pipe	Metal	White	None	0	1.28	Positive
1	B	Room 7 Custodial Staff Breakroom	Radiator	Metal	Grey	Chipping	1	0.13	Negative
1	B	Room 7 Custodial Staff Breakroom	Ceiling	Plaster	White	Flaking	5	0.05	Negative
1	B	Room 7 Custodial Staff Breakroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B23 Fan Room #3	W1	Brick	White	Chipping	8	0.11	Negative
1	B	Room B23 Fan Room #3	W2	Brick	White	Chipping	5	0.12	Negative
1	B	Room B23 Fan Room #3	W3	Brick	White	Chipping	10	0.39	Negative
1	B	Room B23 Fan Room #3	W4	Brick	White	Chipping	2	0.41	Negative
1	B	Room B23 Fan Room #3	Ductwork	Metal	White	Chipping	3	3.43	Positive
1	B	Room B23 Fan Room #3	Column	Concrete	White	Chipping	8	0.3	Negative
1	B	Room B23 Fan Room #3	Door	Metal	Brown	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Room B23 Fan Room #3	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B23 Fan Room #3	Ceiling	Concrete	White	Chipping	50	0.25	Negative
1	B	Room B23 Fan Room #3	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B21 Storage #11	W1	Brick	White	None	0	0.15	Negative
1	B	Room B21 Storage #11	W2	Brick	White	Chipping	1	0.12	Negative
1	B	Room B21 Storage #11	W2	Concrete	White	None	0	0.16	Negative
1	B	Room B21 Storage #11	W3	Concrete	White	Flaking	4	0.14	Negative
1	B	Room B21 Storage #11	W4	Brick	White	None	0	0.14	Negative
1	B	Room B21 Storage #11	W4	Concrete	White	Chipping	1	0.11	Negative
1	B	Room B21 Storage #11	Door	Metal	Brown	None	0	0	Negative
1	B	Room B21 Storage #11	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B21 Storage #11	Ductwork	Metal	White	Chipping	1	5.58	Positive
1	B	Room B21 Storage #11	Pipe	Metal	White	Chipping	1	5.54	Positive
1	B	Room B21 Storage #11	Ceiling	Concrete	White	None	0	0.15	Negative
1	B	Room B21 Storage #11	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B22 Storage #12	W1	Brick	Grey	Chipping	8	2.31	Positive
1	B	Room B22 Storage #12	W2	Brick	Grey	Chipping	5	2.51	Positive
1	B	Room B22 Storage #12	W3	Brick	Grey	Chipping	4	2.99	Positive
1	B	Room B22 Storage #12	W4	Brick	Grey	Chipping	1	2.61	Positive
1	B	Room B22 Storage #12	Ductwork	Metal	Grey	Chipping	5	0.09	Negative
1	B	Room B22 Storage #12	Column	Concrete	Grey	Chipping	2	2.74	Positive
1	B	Room B22 Storage #12	Door	Metal	Brown	None	0	0	Negative
1	B	Room B22 Storage #12	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B22 Storage #12	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B22 Storage #12	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B15 Storage #3	W1	Brick	White	Chipping	1	1.53	Positive
1	B	Room B15 Storage #3	W1	Brick	Unpainted	None	0	0.01	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Room B15 Storage #3	W2	Brick	White	Chipping	2	1.96	Positive
1	B	Room B15 Storage #3	W2	Brick	Unpainted	None	0	0.02	Negative
1	B	Room B15 Storage #3	W3	Brick	White	None	0	0.83	Positive
1	B	Room B15 Storage #3	W3	Brick	Unpainted	None	0	0.01	Negative
1	B	Room B15 Storage #3	W4	Brick	White	None	0	1.74	Positive
1	B	Room B15 Storage #3	W4	Brick	Unpainted	None	0	0.03	Negative
1	B	Room B15 Storage #3	Radiator	Metal	Grey	Chipping	1	0.15	Negative
1	B	Room B15 Storage #3	Pipe	Metal	White	Chipping	1	1.69	Positive
1	B	Room B15 Storage #3	Ductwork	Metal	White	Chipping	1	6.13	Positive
1	B	Room B15 Storage #3	Ceiling	Plaster	White	Chipping	5	0.07	Negative
1	B	Room B15 Storage #3	Floor	12"x12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B17 Storage #5	W1	Brick	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	W2	Brick	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	W3	Brick	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	W4	Brick	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	Ceiling	Concrete	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	Floor	Concrete	No access	No access	No access	No access	No Access
1	B	Room B17 Storage #5	Pipe	Metal	No access	No access	No access	No access	No Access
1	B	Storage Room across from Room B02 Fan Room	W1	Brick	White	None	0	1.84	Positive
1	B	Storage Room across from Room B02 Fan Room	W2	Brick	White	None	0	2.25	Positive
1	B	Storage Room across from Room B02 Fan Room	W3	Brick	White	None	0	1.4	Positive
1	B	Storage Room across from Room B02 Fan Room	W4	Brick	White	None	0	3.16	Positive
1	B	Storage Room across from Room B02 Fan Room	Ceiling	Concrete	White	None	0	3.31	Positive
1	B	Storage Room across from Room B02 Fan Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Storage Room across from Room B02 Fan Room	Ductwork	Metal	White	Chipping	1	8.77	Positive
1	B	Storage Room across from Room B02 Fan Room	Column	Concrete	White	None	0	2.6	Positive
1	B	Storage Room next to Room B17	W1	Brick	White	None	0	0.71	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Storage Room next to Room B17	W2	Brick	White	None	0	0.73	Positive
1	B	Storage Room next to Room B17	W3	Brick	White	None	0	0.07	Negative
1	B	Storage Room next to Room B17	W4	Brick	White	None	0	0.07	Negative
1	B	Storage Room next to Room B17	Ductwork	Metal	White	Chipping	3	6.85	Positive
1	B	Storage Room next to Room B17	Ceiling	Concrete	White	None	0	0.16	Negative
1	B	Storage Room next to Room B17	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B13 Storage #1	W1	Brick	White	None	0	2.07	Positive
1	B	Room B13 Storage #1	W2	Brick	White	None	0	0.06	Negative
1	B	Room B13 Storage #1	W3	Brick	White	None	0	2.35	Positive
1	B	Room B13 Storage #1	W4	Brick	White	None	0	1.62	Positive
1	B	Room B13 Storage #1	Pipe	Metal	White	None	0	5.29	Positive
1	B	Room B13 Storage #1	Ceiling	Concrete	White	Chipping	5	0.08	Negative
1	B	Room B13 Storage #1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B14 Storage #2	W1	Brick	White	None	0	0.19	Negative
1	B	Room B14 Storage #2	W1	Brick	Unpainted	None	0	0.01	Negative
1	B	Room B14 Storage #2	W2	Brick	White	None	0	0.08	Negative
1	B	Room B14 Storage #2	W2	Brick	Unpainted	None	0	0.01	Negative
1	B	Room B14 Storage #2	W3	Brick	White	None	0	0.07	Negative
1	B	Room B14 Storage #2	W3	Brick	Unpainted	None	0	0.01	Negative
1	B	Room B14 Storage #2	W4	Brick	White	None	0	0.3	Negative
1	B	Room B14 Storage #2	W4	Brick	Unpainted	None	0	0.02	Negative
1	B	Room B14 Storage #2	Pipe	Metal	White	Flaking	5	0.15	Negative
1	B	Room B14 Storage #2	Ductwork	Metal	White	Chipping	1	6.83	Positive
1	B	Room B14 Storage #2	Radiator	Metal	Grey	Chipping	1	0.07	Negative
1	B	Room B14 Storage #2	Ceiling	Plaster	White	Flaking	50	0.08	Negative
1	B	Room B14 Storage #2	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B25 Storage #10	Radiator	Metal	Grey	Chipping	1	0.02	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Room B25 Storage #10	Pipe	Metal	White	Chipping	2	0.18	Negative
1	B	Room B25 Storage #10	Ductwork	Metal	White	Chipping	2	6.15	Positive
1	B	Room B25 Storage #10	W1	Brick	White	None	0	0.09	Negative
1	B	Room B25 Storage #10	W1	Brick	Unpainted	None	0	0.02	Negative
1	B	Room B25 Storage #10	W2	Wood	White	None	0	8.44	Positive
1	B	Room B25 Storage #10	W2	Wood	Tan	None	0	8.96	Positive
1	B	Room B25 Storage #10	W3	Brick	White	None	0	0.29	Negative
1	B	Room B25 Storage #10	W3	Brick	Unpainted	None	0	0.1	Negative
1	B	Room B25 Storage #10	W4	Brick	White	None	0	0.14	Negative
1	B	Room B25 Storage #10	W4	Brick	Unpainted	None	0	0.01	Negative
1	B	Room B25 Storage #10	Ceiling	Concrete	White	Chipping	3	0.12	Negative
1	B	Room B25 Storage #10	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B26 Fan Room #4	W1	Brick	White	Chipping	10	0.12	Negative
1	B	Room B26 Fan Room #4	W2	Brick	White	None	0	0.12	Negative
1	B	Room B26 Fan Room #4	W3	Brick	White	Chipping	20	0.16	Negative
1	B	Room B26 Fan Room #4	W4	Brick	White	Chipping	10	0.19	Negative
1	B	Room B26 Fan Room #4	Pipe	Metal	White	Chipping	6	0.25	Negative
1	B	Room B26 Fan Room #4	Pipe	Metal	White	Chipping	3	3.43	Positive
1	B	Room B26 Fan Room #4	Column	Concrete	White	Chipping	2	0.1	Negative
1	B	Room B26 Fan Room #4	Door	Metal	Brown	None	0	0	Negative
1	B	Room B26 Fan Room #4	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B26 Fan Room #4	Ceiling	Concrete	White	Flaking	500	0.13	Negative
1	B	Room B26 Fan Room #4	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Emergency Generator Room	W1	CMU	White	None	0	0	Negative
1	B	Emergency Generator Room	W1	Brick	Unpainted	None	0	0.02	Negative
1	B	Emergency Generator Room	W2	Brick	Unpainted	None	0	0.02	Negative
1	B	Emergency Generator Room	W3	Brick	Unpainted	None	0	0.02	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Emergency Generator Room	W4	CMU	White	None	0	0	Negative
1	B	Emergency Generator Room	Pipe	Metal	White	Chipping	10	0.16	Negative
1	B	Emergency Generator Room	Ductwork	Metal	White	Chipping	3	5.97	Positive
1	B	Emergency Generator Room	Radiator	Metal	Grey	Chipping	2	0.06	Negative
1	B	Emergency Generator Room	Door	Metal	Brown	None	0	0	Negative
1	B	Emergency Generator Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Emergency Generator Room	Ceiling	Plaster	White	Efflorescence	20	0.11	Negative
1	B	Emergency Generator Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B12 Building Engineer's Office	Pipe	Metal	White	Chipping	1	6.27	Positive
1	B	Room B12 Building Engineer's Office	Column	Concrete	White	Chipping	1	0.13	Negative
1	B	Room B12 Building Engineer's Office	Radiator	Metal	White	Chipping	1	0.05	Negative
1	B	Room B12 Building Engineer's Office	Baseboard	Concrete	Grey	None	0	0.29	Negative
1	B	Room B12 Building Engineer's Office	W1	Brick	White	Chipping	1	1.2	Positive
1	B	Room B12 Building Engineer's Office	W2	Brick	White	Chipping	1	0.1	Negative
1	B	Room B12 Building Engineer's Office	W3	Brick	White	Chipping	2	0.19	Negative
1	B	Room B12 Building Engineer's Office	W4	Brick	White	Chipping	1	0.09	Negative
1	B	Room B12 Building Engineer's Office	Ceiling	Concrete	White	Chipping	4	0.14	Negative
1	B	Room B12 Building Engineer's Office	Floor	Concrete	Grey	None	0	0.07	Negative
1	B	Former Locker Room	W1	Brick	Unpainted	None	0	0.02	Negative
1	B	Former Locker Room	W1	CMU	White	None	0	0	Negative
1	B	Former Locker Room	W2	Brick	Unpainted	None	0	0.01	Negative
1	B	Former Locker Room	W2	CMU	White	None	0	0	Negative
1	B	Former Locker Room	W3	Brick	Unpainted	None	0	0.03	Negative
1	B	Former Locker Room	W3	Brick	White	None	0	0.05	Negative
1	B	Former Locker Room	W4	Brick	Unpainted	None	0	0.02	Negative
1	B	Former Locker Room	Ceiling	Plaster	White	Chipping	200	0.08	Negative
1	B	Former Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Former Locker Room	Ductwork	Metal	White	Chipping	50	5.51	Positive
1	B	Former Locker Room	Pipe	Metal	White	Chipping	20	0.09	Negative
1	B	Former Locker Room	Radiator	Metal	Grey	Chipping	2	0	Negative
1	B	Former Locker Room	Door	Metal	Brown	None	0	0	Negative
1	B	Former Locker Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Former Showers in Former Locker Room	W1	Marble	Unpainted	N/A	N/A	0	N/A
1	B	Former Showers in Former Locker Room	W1	Concrete	White	Chipping	3	0.12	Negative
1	B	Former Showers in Former Locker Room	W2	Marble	Unpainted	N/A	N/A	0	N/A
1	B	Former Showers in Former Locker Room	W2	Concrete	White	Chipping	2	0.09	Negative
1	B	Former Showers in Former Locker Room	W3	Marble	Unpainted	N/A	N/A	0	N/A
1	B	Former Showers in Former Locker Room	W3	Concrete	White	Chipping	4	0.08	Negative
1	B	Former Showers in Former Locker Room	W4	Marble	Unpainted	N/A	N/A	0	N/A
1	B	Former Showers in Former Locker Room	W4	Concrete	White	Chipping	3	0.16	Negative
1	B	Former Showers in Former Locker Room	Ceiling	Concrete	White	Chipping	5	0.1	Negative
1	B	Former Showers in Former Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Former Restroom in Former Locker Room	W1	Brick	Unpainted	None	0	0.02	Negative
1	B	Former Restroom in Former Locker Room	W1	Brick	White	Chipping	25	0.12	Negative
1	B	Former Restroom in Former Locker Room	W2	Brick	Unpainted	None	0	0.02	Negative
1	B	Former Restroom in Former Locker Room	W2	Brick	White	Chipping	50	0.09	Negative
1	B	Former Restroom in Former Locker Room	W3	Brick	Unpainted	None	0	0.01	Negative
1	B	Former Restroom in Former Locker Room	W3	Brick	White	Chipping	50	0.07	Negative
1	B	Former Restroom in Former Locker Room	W4	Brick	Unpainted	None	0	0.03	Negative
1	B	Former Restroom in Former Locker Room	W4	Brick	White	Chipping	25	0.1	Negative
1	B	Former Restroom in Former Locker Room	Ceiling	Concrete	White	Chipping	20	0.08	Negative
1	B	Former Restroom in Former Locker Room	Floor	Concrete	Grey	Chipping	20	0.06	Negative
1	B	Former Restroom in Former Locker Room	Radiator	Metal	Grey	Chipping	1	0.08	Negative
1	B	Former Restroom in Former Locker Room	Stall Door	Marble	Grey	None	0	0	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Former Restroom in Former Locker Room	Pipe	Metal	White	Chipping	6	0.2	Negative
1	B	Former Restroom in Former Locker Room	Pipe	Metal	Brown	Chipping	3	1.35	Positive
1	B	Former Restroom in Former Locker Room	Door	Metal	Brown	None	0	0	Negative
1	B	Former Restroom in Former Locker Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B-11 Custodial Staff Check-in Room	W1	Brick	White	None	0	0.29	Negative
1	B	Room B-11 Custodial Staff Check-in Room	W1	Brick	Grey	None	0	0.19	Negative
1	B	Room B-11 Custodial Staff Check-in Room	W2	Brick	White	None	0	0.26	Negative
1	B	Room B-11 Custodial Staff Check-in Room	W3	Brick	White	None	0	0.11	Negative
1	B	Room B-11 Custodial Staff Check-in Room	W4	Brick	White	None	0	0.12	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Ceiling	Concrete	White	Chipping	3	0.18	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Floor	Concrete	Grey	None	0	0.11	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Column	Concrete	White	None	0	0.19	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Ductwork	Metal	White	Chipping	1	2.46	Positive
1	B	Room B-11 Custodial Staff Check-in Room	Door	Metal	Brown	None	0	0	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Pipe	Metal	White	None	0	0.02	Negative
1	B	Room B-11 Custodial Staff Check-in Room	Radiator Cover	Metal	Brown	None	0	0	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W1	Brick	White	Chipping	1	0.18	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W1	Brick	Grey	None	0	0.14	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W2	Brick	White	Chipping	3	0.15	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W2	Brick	Grey	Chipping	1	0.11	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W3	Brick	White	Chipping	2	0.16	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W3	Brick	Grey	None	0	0.09	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W4	Brick	White	Chipping	1	0.23	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	W4	Brick	Grey	None	0	0.22	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Ceiling	Concrete	White	Chipping	3	0.27	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Floor	Concrete	Grey	None	0	0.16	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Floor	Concrete	Red	None	0	0.58	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Pipe	Metal	White	Chipping	6	2.17	Positive
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Radiator	Metal	Grey	Chipping	1	0	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Door	Metal	Brown	None	0	0	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Restroom/Shower in Custodial Staff Check-in Ro	Door	Wood	Red	None	0	0.12	Negative
1	B	Restroom next to Custodial Check-in Room	Door	Metal	Brown	None	0	0	Negative
1	B	Restroom next to Custodial Check-in Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Restroom next to Custodial Check-in Room	Radiator	Metal	Blue	Chipping	1	0.01	Negative
1	B	Restroom next to Custodial Check-in Room	Column	Concrete	Blue	Chipping	1	0.2	Negative
1	B	Restroom next to Custodial Check-in Room	I-Beam	Metal	Blue	None	0	0	Negative
1	B	Restroom next to Custodial Check-in Room	Window Frame	Wood	Brown	None	0	0.16	Negative
1	B	Restroom next to Custodial Check-in Room	Pipe	Metal	Blue	None	0	0	Negative
1	B	Restroom next to Custodial Check-in Room	W1	Brick	Blue	None	0	0.22	Negative
1	B	Restroom next to Custodial Check-in Room	W2	Brick	Blue	Chipping	1	0.26	Negative
1	B	Restroom next to Custodial Check-in Room	W3	Brick	Blue	None	0	0.19	Negative
1	B	Restroom next to Custodial Check-in Room	W4	Brick	Blue	None	0	0.33	Negative
1	B	Restroom next to Custodial Check-in Room	Ceiling	Concrete	Blue	Chipping	2	0.15	Negative
1	B	Restroom next to Custodial Check-in Room	Floor	Concrete	Grey	Chipping	1	0.05	Negative
1	B	Former Compactor Room (unused) - SW Corner	W1	Concrete	White	Chipping	1	0.01	Negative
1	B	Former Compactor Room (unused) - SW Corner	W1	Concrete	Grey	None	0	0.03	Negative
1	B	Former Compactor Room (unused) - SW Corner	W1	Brick	White	None	0	0.01	Negative
1	B	Former Compactor Room (unused) - SW Corner	W1	Brick	Grey	None	0	0.01	Negative
1	B	Former Compactor Room (unused) - SW Corner	W2	Concrete	White	None	0	0.02	Negative
1	B	Former Compactor Room (unused) - SW Corner	W2	Concrete	Grey	None	0	0.05	Negative
1	B	Former Compactor Room (unused) - SW Corner	W2	Brick	White	Chipping	1	0.04	Negative
1	B	Former Compactor Room (unused) - SW Corner	W3	Concrete	White	Flaking	1	0.04	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Former Compactor Room (unused) - SW Corner	W3	Concrete	Grey	Flaking	3	0.05	Negative
1	B	Former Compactor Room (unused) - SW Corner	W3	Brick	White	Flaking	1	0.03	Negative
1	B	Former Compactor Room (unused) - SW Corner	W4	Concrete	White	Chipping	2	0.03	Negative
1	B	Former Compactor Room (unused) - SW Corner	W4	Concrete	Grey	None	0	0.04	Negative
1	B	Former Compactor Room (unused) - SW Corner	Stair Tread	Concrete	Grey	Chipping	1	0.75	Positive
1	B	Former Compactor Room (unused) - SW Corner	Stair Riser	Concrete	Grey	Chipping	1	2.37	Positive
1	B	Former Compactor Room (unused) - SW Corner	Stringer	Concrete	Grey	None	0	5.37	Positive
1	B	Former Compactor Room (unused) - SW Corner	Handrail	Metal	Grey	Chipping	1	6.11	Positive
1	B	Former Compactor Room (unused) - SW Corner	Pipe	Metal	White	Chipping	10	0.3	Negative
1	B	Former Compactor Room (unused) - SW Corner	Door	Metal	Brown	None	0	2.02	Positive
1	B	Former Compactor Room (unused) - SW Corner	Door Frame	Metal	Brown	None	0	0.95	Positive
1	B	Former Compactor Room (unused) - SW Corner	Window Frame	Metal	Grey	Chipping	1	1	Positive
1	B	Former Compactor Room (unused) - SW Corner	Ceiling	Concrete	White	None	0	N/A	No Access
1	B	Former Compactor Room (unused) - SW Corner	Floor	Concrete	Grey	None	0	0.04	Negative
1	B	Storage Area adjacent to Boiler Room	W1	Concrete	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W1	Concrete	Green	None	0	0.01	Negative
1	B	Storage Area adjacent to Boiler Room	W2	Concrete	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W2	Concrete	Green	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W2	Brick	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W3	Concrete	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W3	Concrete	Green	None	0	0.01	Negative
1	B	Storage Area adjacent to Boiler Room	W3	CMU	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W4	Concrete	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	W4	Concrete	Green	None	0	0.03	Negative
1	B	Storage Area adjacent to Boiler Room	Column	Concrete	White	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	Column	Concrete	Green	None	0	0.03	Negative
1	B	Storage Area adjacent to Boiler Room	Pipe	Metal	White	None	0	0	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Storage Area adjacent to Boiler Room	Post	Wood	Green	None	0	0.15	Negative
1	B	Storage Area adjacent to Boiler Room	Door	Metal	Brown	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Storage Area adjacent to Boiler Room	Ceiling	Concrete	White	Cracking	2	No Access	No Access
1	B	Storage Area adjacent to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Heating Oil Tank Area (tank covered with sand)	W1	CMU	White	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W1	Concrete	White	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W1	Concrete	Green	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W2	Concrete	White	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W2	Concrete	Green	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W3	Brick	White	Chipping	50	0.01	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W3	Concrete	White	Chipping	5	0.01	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W3	Concrete	Green	None	0	0.02	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W4	Concrete	White	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	W4	Concrete	Green	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	Pipe	Metal	White	None	0	1.67	Positive
1	B	Heating Oil Tank Area (tank covered with sand)	Column	Concrete	White	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	Column	Concrete	Green	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	Door	Metal	Brown	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Heating Oil Tank Area (tank covered with sand)	Ceiling	Concrete	White	Cracking	10	No Access	No Access
1	B	Heating Oil Tank Area (tank covered with sand)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Boiler Room Area	W1	Brick	White	Chipping	10	0.1	Negative
1	B	Boiler Room Area	W1	Brick	Grey	Chipping	100	1.89	Positive
1	B	Boiler Room Area	W1	Concrete	White	None	0	0	Negative
1	B	Boiler Room Area	W1	Concrete	Grey	Chipping	10	3.86	Positive
1	B	Boiler Room Area	W2	Brick	White	Chipping	20	0.03	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Boiler Room Area	W2	Brick	Grey	Chipping	15	4.01	Positive
1	B	Boiler Room Area	W2	Concrete	White	Chipping	15	0.02	Negative
1	B	Boiler Room Area	W2	Concrete	Grey	Chipping	20	7.26	Positive
1	B	Boiler Room Area	W3	Concrete	White	Chipping	10	0.03	Negative
1	B	Boiler Room Area	W3	Concrete	Grey	Flaking	50	4.65	Positive
1	B	Boiler Room Area	W3	CMU	White	None	0	0.06	Negative
1	B	Boiler Room Area	W3	CMU	Grey	None	0	0.17	Negative
1	B	Boiler Room Area	W4	Brick	White	Chipping	20	0.03	Negative
1	B	Boiler Room Area	W4	Concrete	White	Chipping	20	0.07	Negative
1	B	Boiler Room Area	W4	Concrete	Grey	Flaking	50	0.84	Positive
1	B	Boiler Room Area	Column	Concrete	White	Chipping	15	0.1	Negative
1	B	Boiler Room Area	Column	Concrete	Grey	Chipping	10	1.91	Positive
1	B	Boiler Room Area	Pipe	Metal	Red	None	0	0	Negative
1	B	Boiler Room Area	Pipe	Metal	Yellow	None	0	0	Negative
1	B	Boiler Room Area	Pipe	Metal	Orange	None	0	0	Negative
1	B	Boiler Room Area	Pipe	Metal	White	None	0	0	Negative
1	B	Boiler Room Area	Ductwork	Metal	White	Flaking	150	5.51	Positive
1	B	Boiler Room Area	Ductwork	Metal	Grey	None	0	0.05	Negative
1	B	Boiler Room Area	Column	Concrete	White	Chipping	20	0.1	Negative
1	B	Boiler Room Area	Column	Concrete	Grey	Chipping	10	1.91	Positive
1	B	Boiler Room Area	Ceiling	Concrete	White	Flaking	4000	No Access	No Access
1	B	Boiler Room Area	Floor	Concrete	Grey	Chipping	4000	6.81	Positive
1	B	Sump Pump Room in Boiler Room	W1	Brick	White	Chipping	250	2.85	Positive
1	B	Sump Pump Room in Boiler Room	W1	Concrete	White	Chipping	2	4.4	Positive
1	B	Sump Pump Room in Boiler Room	W2	Brick	White	Chipping	10	1.79	Positive
1	B	Sump Pump Room in Boiler Room	W2	Concrete	White	Chipping	5	2.93	Positive
1	B	Sump Pump Room in Boiler Room	W3	Brick	White	Chipping	200	3.16	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Sump Pump Room in Boiler Room	W3	Concrete	White	Chipping	5	4.68	Positive
1	B	Sump Pump Room in Boiler Room	W4	Brick	White	Chipping	100	0.04	Negative
1	B	Sump Pump Room in Boiler Room	W4	Concrete	White	Chipping	2	5.48	Positive
1	B	Sump Pump Room in Boiler Room	Pipe	Metal	Grey	Chipping	1	No Access	No Access
1	B	Sump Pump Room in Boiler Room	Door	Metal	Brown	None	0	0	Negative
1	B	Sump Pump Room in Boiler Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Sump Pump Room in Boiler Room	Ceiling	Concrete	White	None	0	N/A	No Access
1	B	Sump Pump Room in Boiler Room	Floor	Concrete	Grey	Chipping	20	0.1	Negative
1	B	Room B06 Engine Room - Fan Room #1	W1	Brick	White	None	0	0.12	Negative
1	B	Room B06 Engine Room - Fan Room #1	W1	Concrete	Grey	Chipping	5	0.06	Negative
1	B	Room B06 Engine Room - Fan Room #1	W2	Brick	White	Chipping	2	0.15	Negative
1	B	Room B06 Engine Room - Fan Room #1	W2	Brick	Grey	Chipping	1	0.1	Negative
1	B	Room B06 Engine Room - Fan Room #1	W3	Brick	White	Chipping	6	0.13	Negative
1	B	Room B06 Engine Room - Fan Room #1	W3	Concrete	Grey	Chipping	10	0.16	Negative
1	B	Room B06 Engine Room - Fan Room #1	W4	CMu	White	None	0	0.04	Negative
1	B	Room B06 Engine Room - Fan Room #1	W4	CMU	Grey	None	0	0.04	Negative
1	B	Room B06 Engine Room - Fan Room #1	Column	Concrete	White	None	0	0.16	Negative
1	B	Room B06 Engine Room - Fan Room #1	Column	Concrete	Grey	Chipping	3	0.16	Negative
1	B	Room B06 Engine Room - Fan Room #1	Ductwork	Metal	White	Chipping	2	5.26	Positive
1	B	Room B06 Engine Room - Fan Room #1	Pipe	Metal	White	None	0	0.19	Negative
1	B	Room B06 Engine Room - Fan Room #1	Ceiling	Concrete	White	Chipping	6	0.08	Negative
1	B	Room B06 Engine Room - Fan Room #1	Floor	Concrete	Grey	Chipping	50	0.09	Negative
1	B	Room B06 Engine Room - Fan Room #1	Door	Metal	Brown	None	0	0	Negative
1	B	Room B06 Engine Room - Fan Room #1	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Room B06 Engine Room - Fan Room #1	Handrail	Metal	Grey	Chipping	1	0.084	Negative
1	B	Room B06 Engine Room - Fan Room #1	Stair Tread	Concrete	Grey	Chipping	1	0.79	Positive
1	B	Room B06 Engine Room - Fan Room #1	Stair Riser	Concrete	Grey	Chipping	1	0.76	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Room B06 Engine Room - Fan Room #1	Stringer	Concrete	Grey	Chipping	1	0.2	Negative
1	B	Electrical Room next to Room B06	W1	CMU	White	None	0	0.06	Negative
1	B	Electrical Room next to Room B06	W1	CMU	Grey	None	0	0.04	Negative
1	B	Electrical Room next to Room B06	W2	Brick	White	None	0	0.17	Negative
1	B	Electrical Room next to Room B06	W2	Concrete	Grey	Chipping	4	0.02	Negative
1	B	Electrical Room next to Room B06	W3	Brick	White	None	0	0.1	Negative
1	B	Electrical Room next to Room B06	W3	Concrete	Grey	Chipping	1	0.08	Negative
1	B	Electrical Room next to Room B06	W4	Brick	White	Chipping	1	0.12	Negative
1	B	Electrical Room next to Room B06	W4	Concrete	Grey	Chipping	5	0.16	Negative
1	B	Electrical Room next to Room B06	Column	Concrete	White	Chipping	1	0.15	Negative
1	B	Electrical Room next to Room B06	Column	Concrete	Grey	Chipping	1	0.17	Negative
1	B	Electrical Room next to Room B06	Door	Metal	Brown	None	0	0	Negative
1	B	Electrical Room next to Room B06	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Electrical Room next to Room B06	Ceiling	Concrete	White	None	0	0.07	Negative
1	B	Electrical Room next to Room B06	Floor	Concrete	Grey	Chipping	25	0.21	Negative
1	B	Fan Room between Electrical Room next to Room B06	Door	Metal	Brown	None	0	0	Negative
1	B	Fan Room between Electrical Room next to Room B06	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Fan Room between Electrical Room next to Room B06	W1	Brick	White	None	0	0.09	Negative
1	B	Fan Room between Electrical Room next to Room B06	W1	Brick	Grey	None	0	0.07	Negative
1	B	Fan Room between Electrical Room next to Room B06	W2	Brick	White	Chipping	3	0.16	Negative
1	B	Fan Room between Electrical Room next to Room B06	W2	Concrete	Grey	Chipping	20	0.13	Negative
1	B	Fan Room between Electrical Room next to Room B06	W3	Brick	White	None	0	0.1	Negative
1	B	Fan Room between Electrical Room next to Room B06	W3	Brick	Grey	None	0	0.12	Negative
1	B	Fan Room between Electrical Room next to Room B06	W4	Brick	White	None	0	0.14	Negative
1	B	Fan Room between Electrical Room next to Room B06	W4	Concrete	Grey	Chipping	30	0.24	Negative
1	B	Fan Room between Electrical Room next to Room B06	Column	Concrete	White	None	0	0.11	Negative
1	B	Fan Room between Electrical Room next to Room B06	Column	Concrete	Grey	Chipping	3	0.21	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Fan Room between Electrical Room next to Room	Pipe	Metal	White	No Access	No Access	No Access	No Access
1	B	Fan Room between Electrical Room next to Room	Ceiling	Concrete	White	No Access	No Access	No Access	No Access
1	B	Fan Room between Electrical Room next to Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Air Intake Room between Fan Rooms	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B02 Fan Room #2	W1	Brick	White	None	0	0.18	Negative
1	B	Room B02 Fan Room #2	W1	Concrete	White	Chipping	2	0.06	Negative
1	B	Room B02 Fan Room #2	W2	Brick	White	Chipping	2	0.1	Negative
1	B	Room B02 Fan Room #2	W3	Brick	White	Chipping	4	0.1	Negative
1	B	Room B02 Fan Room #2	W3	Concrete	White	Chipping	5	0.14	Negative
1	B	Room B02 Fan Room #2	W4	Brick	White	Chipping	1	0.19	Negative
1	B	Room B02 Fan Room #2	W4	Concrete	White	Chipping	5	0.05	Negative
1	B	Room B02 Fan Room #2	Ceiling	Concrete	White	Chipping	3	No Access	No Access
1	B	Room B02 Fan Room #2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B02 Fan Room #2	Column	Concrete	White	Chipping	5	0.29	Negative
1	B	Room B02 Fan Room #2	Ductwork	Metal	White	Chipping	1	No Access	No Access
1	B	Room B02 Fan Room #2	Pipe	Metal	White	Chipping	6	No Access	No Access
1	B	Room B01 Custodial Office	W1	Brick	White	None	0	0.17	Negative
1	B	Room B01 Custodial Office	W1	Brick	Grey	None	0	0.15	Negative
1	B	Room B01 Custodial Office	W2	Brick	White	None	0	0.2	Negative
1	B	Room B01 Custodial Office	W2	Brick	Grey	None	0	0.15	Negative
1	B	Room B01 Custodial Office	W3	Brick	White	None	0	0.17	Negative
1	B	Room B01 Custodial Office	W3	Brick	Grey	Chipping	5	0.11	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Room B01 Custodial Office	W4	Brick	White	Chipping	1	0.11	Negative
1	B	Room B01 Custodial Office	W4	Brick	Grey	Chipping	1	0.16	Negative
1	B	Room B01 Custodial Office	Ceiling	Concrete	White	Chipping	1	0.24	Negative
1	B	Room B01 Custodial Office	Pipe	Metal	White	Chipping	10	0.13	Negative
1	B	Room B01 Custodial Office	Ductwork	Metal	White	Chipping	5	5.2	Positive
1	B	Room B01 Custodial Office	Floor	Concrete	Black	Cracking	20	0.04	Negative
1	B	Room B01 Custodial Office	Column	Concrete	White	None	0	0.11	Negative
1	B	Room B01 Custodial Office	Column	Concrete	Grey	None	0	0.17	Negative
1	1	Room B01 Custodial Office	Radiator	Metal	Grey	Chipping	10	0.05	Negative
1	1	Room B01 Custodial Office	Door	Metal	Unpainted	N/A	N/A	0	Negative
1	1	Room B01 Custodial Office	Door Frame	Metal	Unpainted	N/A	N/A	0	Negative
1	B	Room B01 Custodial Office Restroom	W1	Brick	White	Chipping	1	0.07	Negative
1	B	Room B01 Custodial Office Restroom	W1	Brick	Grey	None	0	0.14	Negative
1	B	Room B01 Custodial Office Restroom	W2	Brick	White	Chipping	1	0.17	Negative
1	B	Room B01 Custodial Office Restroom	W2	Brick	Grey	Chipping	4	0.12	Negative
1	B	Room B01 Custodial Office Restroom	W3	Brick	White	Alligating	3	0.12	Negative
1	B	Room B01 Custodial Office Restroom	W3	Brick	Grey	Chipping	2	0.12	Negative
1	B	Room B01 Custodial Office Restroom	W4	Brick	White	None	0	0.19	Negative
1	B	Room B01 Custodial Office Restroom	W4	Brick	Grey	None	0	0.31	Negative
1	B	Room B01 Custodial Office Restroom	Ceiling	Concrete	White	Chipping	2	0.09	Negative
1	B	Room B01 Custodial Office Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B01 Custodial Office Restroom	Pipe	Metal	White	Chipping	5	0.1	Negative
1	B	Room B01 Custodial Office Restroom	Radiator	Metal	Grey	Chipping	5	0	Negative
1	B	Room B01 Custodial Office Restroom	Column	Concrete	White	Chipping	1	0.16	Negative
1	B	Room B01 Custodial Office Restroom	Column	Concrete	Grey	Chipping	2	0.14	Negative
1	B	Middle Storage Closet in Room B01 Custodial Of	W1	Brick	White	None	0	3.25	Positive
1	B	Middle Storage Closet in Room B01 Custodial Of	W2	Brick	White	None	0	2.37	Positive

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Middle Storage Closet in Room B01 Custodial Office	W3	Brick	White	None	0	2.08	Positive
1	B	Middle Storage Closet in Room B01 Custodial Office	W4	Brick	White	None	0	2.81	Positive
1	B	Middle Storage Closet in Room B01 Custodial Office	Ceiling	Concrete	White	None	0	0.09	Negative
1	B	Middle Storage Closet in Room B01 Custodial Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Middle Storage Closet in Room B01 Custodial Office	Column	Concrete	White	None	0	2.96	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	W1	Brick	White	None	0	2.25	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	W2	Brick	White	None	0	2.21	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	W3	Brick	White	None	0	1.9	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	W4	Brick	White	None	0	3.29	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	Ceiling	Concrete	White	None	0	3.44	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Front Storage Closet in Room B01 Custodial Office	Pipe	Metal	White	Chipping	5	5.91	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	Ductwork	Metal	White	Chipping	5	6.4	Positive
1	B	Front Storage Closet in Room B01 Custodial Office	Column	Concrete	White	None	0	1.95	Positive
1	B	Room B20 Meter Room	Ductwork	Metal	White	Chipping	2	6.02	Positive
1	B	Room B20 Meter Room	Pipe	Metal	White	Chipping	10	0.19	Negative
1	B	Room B20 Meter Room	W1	Brick	White	None	0	0.06	Negative
1	B	Room B20 Meter Room	W2	Brick	White	None	0	0.06	Negative
1	B	Room B20 Meter Room	W2	Concrete	White	None	0	0.12	Negative
1	B	Room B20 Meter Room	W3	Concrete	White	None	0	0.06	Negative
1	B	Room B20 Meter Room	W4	Brick	White	None	0	0.07	Negative
1	B	Room B20 Meter Room	W4	Concrete	White	None	0	0.07	Negative
1	B	Room B20 Meter Room	Ceiling	Concrete	White	None	0	0.05	Negative
1	B	Room B20 Meter Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Room B20 Meter Room	Door	Metal	Brown	None	0	0	Negative
1	B	Room B20 Meter Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Auditorium Plenum	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Auditorium Plenum	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Auditorium Plenum	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Auditorium Plenum	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Auditorium Plenum	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Auditorium Plenum	Ductwork	Metal	White	Chipping	5	7.87	Positive
1	B	Auditorium Plenum	Pipe	Metal	White	Chipping	1	2.84	Positive
1	B	Auditorium Plenum	Door	Wood	White	None	0	0.1	Negative
1	B	Auditorium Plenum	Door Frame	Wood	White	None	0	4.34	Positive
1	B	Auditorium Plenum	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Auditorium Plenum	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway from Room B24 to end of Former Locker	W1	Brick	White	Chipping	2	0.08	Negative
1	B	Hallway from Room B24 to end of Former Locker	W1	Brick	Grey	Chipping	1	0.07	Negative
1	B	Hallway from Room B24 to end of Former Locker	W2	Brick	White	None	0	0.66	Negative
1	B	Hallway from Room B24 to end of Former Locker	W2	Brick	Grey	None	0	0.65	Negative
1	B	Hallway from Room B24 to end of Former Locker	W3	Brick	White	Chipping	10	0.05	Negative
1	B	Hallway from Room B24 to end of Former Locker	W3	Brick	Grey	Chipping	5	0.07	Negative
1	B	Hallway from Room B24 to end of Former Locker	W4	Brick	White	None	0	0.09	Negative
1	B	Hallway from Room B24 to end of Former Locker	W4	Brick	Grey	None	0	0.1	Negative
1	B	Hallway from Room B24 to end of Former Locker	Ductwork	Metal	White	Chipping	50	3.37	Positive
1	B	Hallway from Room B24 to end of Former Locker	Pipe	Metal	White	None	0	0	Negative
1	B	Hallway from Room B24 to end of Former Locker	Ceiling	Concrete	White	Chipping	10	1.92	Positive
1	B	Hallway from Room B24 to end of Former Locker	Floor	Concrete	Grey	None	0	0.04	Negative
1	B	Hallway from Boiler Room Area to Room B01 Cust	W1	Brick	White	Chipping	20	0.14	Negative
1	B	Hallway from Boiler Room Area to Room B01 Cust	W1	Brick	Grey	Chipping	20	0.18	Negative
1	B	Hallway from Boiler Room Area to Room B01 Cust	W1	Concrete	Grey	Chipping	10	0.24	Negative
1	B	Hallway from Boiler Room Area to Room B01 Cust	W2	Brick	White	None	0	0.14	Negative
1	B	Hallway from Boiler Room Area to Room B01 Cust	W2	Brick	Grey	Chipping	4	0.1	Negative



		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Hallway from Boiler Room Area to Room B01	W3	Brick	White	Chipping	15	0.11	Negative
1	B	Hallway from Boiler Room Area to Room B01	W3	Brick	Grey	Chipping	15	0.07	Negative
1	B	Hallway from Boiler Room Area to Room B01	W3	Concrete	Grey	Chipping	1	0.14	Negative
1	B	Hallway from Boiler Room Area to Room B01	W4	Brick	White	Chipping	3	0.15	Negative
1	B	Hallway from Boiler Room Area to Room B01	W4	Brick	Grey	None	0	0.06	Negative
1	B	Hallway from Boiler Room Area to Room B01	W4	Concrete	Grey	Chipping	1	0.21	Negative
1	B	Hallway from Boiler Room Area to Room B01	Cus	Ductwork	Metal	White	250	6.29	Positive
1	B	Hallway from Boiler Room Area to Room B01	Cus	Pipe	Metal	White	0	0	Negative
1	B	Hallway from Boiler Room Area to Room B01	Cus	Stair Tread	Concrete	Brown	5	4.73	Positive
1	B	Hallway from Boiler Room Area to Room B01	Cus	Stair Riser	Concrete	Brown	5	5.41	Positive
1	B	Hallway from Boiler Room Area to Room B01	Cus	Handrail	Metal	Brown	3	5.07	Positive
1	B	Hallway from Boiler Room Area to Room B01	Cus	Ceiling	Concrete	White	500	0.32	Negative
1	B	Hallway from Boiler Room Area to Room B01	Cus	Floor	Concrete	Grey	0	0.03	Negative
1	B	Hallway along Room B15	W2	Brick	White	Chipping	5	1.98	Positive
1	B	Hallway along Room B15	W2	Brick	Grey	Chipping	2	1.77	Positive
1	B	Hallway along Room B15	W4	Brick	White	Chipping	3	1.66	Positive
1	B	Hallway along Room B15	W4	Brick	Grey	Chipping	1	1.66	Positive
1	B	Hallway along Room B15		Ductwork	Metal	White	20	1.93	Positive
1	B	Hallway along Room B15		Pipe	Metal	White	0	0	Negative
1	B	Hallway along Room B15		Ceiling	Concrete	White	20	1.86	Positive
1	B	Hallway along Room B15		Floor	Concrete	Grey	0	0.04	Negative
1	B	Hallway from Room B20 to Room B21	W1	Brick	White	Alligatoring	1	0.5	Negative
1	B	Hallway from Room B20 to Room B21	W1	Brick	Grey	Alligatoring	1	0.18	Negative
1	B	Hallway from Room B20 to Room B21	W2	Brick	White	Alligatoring	6	0.26	Negative
1	B	Hallway from Room B20 to Room B21	W2	Brick	Grey	Chipping	10	0.1	Negative
1	B	Hallway from Room B20 to Room B21	W3	Brick	White	None	0	0.21	Negative
1	B	Hallway from Room B20 to Room B21	W3	Brick	Grey	None	0	0.31	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Hallway from Room B20 to Room B21	W4	Brick	White	None	0	0.27	Negative
1	B	Hallway from Room B20 to Room B21	W4	Brick	Grey	Chipping	1	0.29	Negative
1	B	Hallway from Room B20 to Room B21	Ductwork	Metal	White	Chipping	100	5.03	Positive
1	B	Hallway from Room B20 to Room B21	Pipe	Metal	White	Chipping	6	2.2	Positive
1	B	Hallway from Room B20 to Room B21	Pipe	Metal	White	None	0	0	Negative
1	B	Hallway from Room B20 to Room B21	Ceiling	Concrete	White	Chipping	20	0.71	Positive
1	B	Hallway from Room B20 to Room B21	Floor	Concrete	Grey	Chipping	1	0.04	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W1	Brick	White	Chipping	10	0.42	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W1	Brick	Grey	Chipping	4	0.7	Positive
1	B	Hallway from Stairs next to Rooms B21 and B22	W2	Brick	White	Chipping	2	0.37	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W2	Brick	Grey	Chipping	1	0.12	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W3	Brick	White	Chipping	10	0.17	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W3	Brick	Grey	None	0	0.25	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W4	Brick	White	Chipping	1	0.51	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	W4	Brick	Grey	None	0	0.41	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	Ductwork	Metal	White	Chipping	100	3.63	Positive
1	B	Hallway from Stairs next to Rooms B21 and B22	Pipe	Metal	White	None	0	0	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	Ceiling	Concrete	White	Chipping	75	0.34	Negative
1	B	Hallway from Stairs next to Rooms B21 and B22	Floor	Concrete	Grey	None	0	0.03	Negative
1	B	Stairwell near the rear side of the Auditorium to th	W1	Plaster	White	None	0	0.17	Negative
1	B	Stairwell near the rear side of the Auditorium to th	W2	Plaster	White	None	0	0.19	Negative
1	B	Stairwell near the rear side of the Auditorium to th	W3	Plaster	White	None	0	0	Negative
1	B	Stairwell near the rear side of the Auditorium to th	W4	Plaster	White	None	0	0.17	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Stringer	Concrete	Grey	None	0	0.24	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Stair Riser	Concrete	Grey	None	0	0.33	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Stair Tread	Concrete	Grey	None	0	0.04	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Baseboard	Concrete	Grey	None	0	0.52	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Stairwell near the rear side of the Auditorium to th	Door	Metal	Brown	None	0	0	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Ceiling	Plaster	White	Efflorescence	2	0.04	Negative
1	B	Stairwell near the rear side of the Auditorium to th	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairs from Former Locker Room to Lower Gym	W1	Brick	Unpainted	None	0	0.02	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W1	Brick	Tan	None	0	0	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W2	Brick	Unpainted	None	0	0.02	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W2	Brick	Tan	None	0	0	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W3	Brick	Unpainted	None	0	0.02	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W3	Brick	Tan	None	0	0	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W4	Brick	Unpainted	None	0	0.02	Negative
1	B	Stairs from Former Locker Room to Lower Gym	W4	Brick	Tan	None	0	0	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Radiator	Metal	Grey	Chipping	3	0.99	Positive
1	B	Stairs from Former Locker Room to Lower Gym	Stringer	Concrete	Grey	Chipping	10	0.11	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Stair Riser	Concrete	Grey	Chipping	6	0.18	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Handrail	Metal	Grey	Chipping	2	0.15	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Pipe	Metal	White	Chipping	4	0.06	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Ceiling	Plaster	White	Chipping	20	0.06	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Baseboard	Concrete	Grey	Chipping	3	0.45	Negative
1	B	Stairs from Former Locker Room to Lower Gym	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell near Room B20 Meter Room	W1	Plaster	White	None	0	0.27	Negative
1	B	Stairwell near Room B20 Meter Room	W2	Plaster	White	None	0	0.26	Negative
1	B	Stairwell near Room B20 Meter Room	W3	Plaster	White	None	0	0.24	Negative
1	B	Stairwell near Room B20 Meter Room	W4	Plaster	White	None	0	0.28	Negative
1	B	Stairwell near Room B20 Meter Room	Stringer	Concrete	Grey	None	0	0.15	Negative
1	B	Stairwell near Room B20 Meter Room	Stair Riser	Concrete	Grey	None	0	0.39	Negative
1	B	Stairwell near Room B20 Meter Room	Stair Tread	Concrete	Grey	None	0	0.04	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Stairwell near Room B20 Meter Room	Door	Metal	Brown	None	0	0	Negative
1	B	Stairwell near Room B20 Meter Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Stairwell near Room B20 Meter Room	Baseboard	Concrete	Grey	None	0	0.07	Negative
1	B	Stairwell near Room B20 Meter Room	Ceiling	Plaster	White	None	0	0.04	Negative
1	B	Stairwell near Room B20 Meter Room	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell near Boiler Room Stairs	W1	Brick	White	Chipping	5	0.1	Negative
1	B	Stairwell near Boiler Room Stairs	W1	Brick	Grey	Chipping	1	6.3	Positive
1	B	Stairwell near Boiler Room Stairs	W1	Concrete	White	None	0	0.08	Negative
1	B	Stairwell near Boiler Room Stairs	W1	Concrete	Grey	None	0	0.09	Negative
1	B	Stairwell near Boiler Room Stairs	W2	Brick	White	Chipping	1	0.04	Negative
1	B	Stairwell near Boiler Room Stairs	W2	Brick	Grey	None	0	0.07	Negative
1	B	Stairwell near Boiler Room Stairs	W3	Brick	White	Chipping	5	0.11	Negative
1	B	Stairwell near Boiler Room Stairs	W3	Brick	Grey	None	0	0.09	Negative
1	B	Stairwell near Boiler Room Stairs	W3	Concrete	White	Chipping	2	0.08	Negative
1	B	Stairwell near Boiler Room Stairs	W3	Concrete	Grey	Chipping	3	4.95	Positive
1	B	Stairwell near Boiler Room Stairs	Stair Tread	Concrete	Grey	Chipping	2	3.03	Positive
1	B	Stairwell near Boiler Room Stairs	Stair Riser	Concrete	Grey	None	0	2.81	Positive
1	B	Stairwell near Boiler Room Stairs	Handrail	Metal	Grey	Chipping	2	2.57	Positive
1	B	Stairwell near Boiler Room Stairs	Ceiling	Concrete	White	None	0	0.13	Negative
1	B	Stairwell near Boiler Room Stairs	Floor	Concrete	Grey	Chipping	5	0.06	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lower	W1	Brick	White	Chipping	4	0.09	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lower	W1	Brick	Grey	None	0	2.87	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lower	W2	Brick	White	Chipping	4	0.06	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lower	W2	Brick	Grey	Chipping	3	4.12	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lower	W4	Brick	White	Chipping	15	0.05	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lower	W4	Brick	Grey	Chipping	3	1.01	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lower	W4	Concrete	White	Chipping	2	0.01	Negative

		Dates: 05/22/2023-06/22/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil #007233	Academy at Palumbo						
		Inspection Company: Viva EHS	1100 Catharine St, Philadelphia PA 19147						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	Stairs from Boiler Room to Exit Doors near Lowe	W4	Concrete	Grey	Chipping	5	4.96	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Stringer	Concrete	Grey	None	0	0.02	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Stair Riser	Concrete	Grey	None	0	4.15	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Stair Tread	Concrete	Grey	Chipping	2	0.77	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Handrail	Metal	Grey	Chipping	1	2.7	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Ductwork	Metal	White	Chipping	6	5.49	Positive
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Door	Metal	Brown	None	0	0	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Door Frame	Metal	Brown	None	0	0	Negative
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Ceiling	Concrete	White	Chipping	100	No Access	No Access
1	B	Stairs from Boiler Room to Exit Doors near Lowe	Floor	Concrete	Grey	None	0	0.06	Negative
1	C	Crawl Space next to Fan Room #1	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space next to Fan Room #1	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space next to Fan Room #1	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space next to Fan Room #1	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space next to Fan Room #1	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	C	Crawl Space next to Fan Room #1	Floor	No Access	No Access	No Access	No Access	No Access	No Access

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the paint color column. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.