

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATTA Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	1-1	Boiler Room	Ceiling	Concrete	Green	None	0	0.1	Negative
1	1	1-1	Boiler Room	Ductwork, Exterior	Metal	Silver	Flaking	45	0.1	Negative
1	1	1-1	Boiler Room	Wall	CMU	Green	None	0	0.2	Negative
1	1	1-1	Boiler Room	Floor	Concrete	Grey	Chipping	24	0	Negative
1	1	1-1	Boiler Room	W1	CMU	Green	None	0	0.2	Negative
1	1	1-1	Boiler Room	Door	Metal	Brown	None	0	0.2	Negative
1	1	1-1	Boiler Room	Pipe	Metal	Silver	Chipping	6	0.3	Negative
1	1	1-1	Boiler Room	Door Frame	Metal	Brown	None	0	0.4	Negative
1	1	1-1	Boiler Room	Pipe insulation	Fiberglass	White	Alligatoring	21	0.4	Negative
1	1	1-1	Boiler Room	Flue	Metal	Silver	Flaking	45	0.1	Negative
1	1	1-1	Boiler Room	W2	CMU	Green	None	0	0	Negative
1	1	1-1	Boiler Room	W3	CMU	Green	None	0	0.1	Negative
1	1	1-1	Boiler Room	Conduit	Metal	Green	None	0	0.2	Negative
1	1	1-1	Boiler Room	W4	CMU	Green	None	0	0.2	Negative
1	1	1-1	Boiler Room	Ceiling	concrete	Green	None	0	0.1	Negative
1	1	1-1	Boiler Room	Floor	concrete	Grey	Chipping	24	0	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	Wall	CMU	Yellow	None	0	0	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	W1	CMU	Yellow	None	0	0	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	Door Frame	Metal	White	Chipping	6	0.2	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	W2	CMU	Yellow	None	0	0.1	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	Pipe Insulation	fiberglass	Yellow	None	0	0.1	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	W3	CMU	Yellow	None	0	0	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	W4	CMU	Yellow	None	0	0	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	Ceiling	concrete	White	None	0	0	Negative
1	1	10-1	Coaches Dressing Room next to Men's Lacrosse Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	Wall	CMU	White	None	0	0.5	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	W1	CMU	White	None	0	0.5	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	W2	CMU	White	None	0	0	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	W3	CMU	White	None	0	0	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	W4	CMU	White	None	0	0	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	Duct	Metal	White	Flaking	32	0.1	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	conduit	Metal	White	None	0	0.5	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	Ceiling	concrete	White	None	0	0	Negative
1	1	11-1	Storage Room next to Coaches Dressing Room and Men's Lacrosse Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Wall	CMU	White	None	0	0	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	W1	CMU	White	None	0	0	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Cove Base	Ceramic	Grey	None	0	0.1	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	W2	CMU	White	None	0	0	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	W3	CMU	White	None	0	0.1	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Radiator	Metal	Tan	None	0	0.1	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	W4	CMU	White	None	0	0.1	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Ceiling	concrete	White	None	0	0.5	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Duct	Metal	White	None	0	0.1	Negative
1	1	12-1	Storage Room next to Coaches Dressing Room and Women's Lacrosse Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Wall	CMU	Yellow	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	W1	CMU	Yellow	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Door Frame	Metal	Blue	Chipping	2	0.3	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	W2	CMU	Yellow	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	W3	CMU	Yellow	None	0	0.1	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	W4	CMU	Yellow	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Pipe insulation	fiberglass	Yellow	None	0	0.1	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Shelf	Wood	Blue	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Ceiling	concrete	White	None	0	0	Negative
1	1	13-1	Coaches Dressing Room next to Women's Lacrosse Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	Wall	CMU	Yellow	None	0	0.1	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	W1	CMU	Yellow	None	0	0.1	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	Door Frame	Metal	Tan	Friction	1	0.3	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	W2	CMU	Yellow	None	0	0.1	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	W3	CMU	Yellow	None	0	0	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	W4	CMU	Yellow	None	0	0.1	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	Ceiling	Plaster	White	Flaking	4	0.5	Negative
1	1	14-1	Coaches Shower Area next to Women's Lacrosse Locker Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	15-1	Women's Lacrosse Locker Room Restroom	Ductwork, Exterior	Metal	Green	None	0	0.2	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	Wall	CMU	Green	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	W1	CMU	Green	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	W2	CMU	Green	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	W3	CMU	Green	None	0	0.1	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	W4	CMU	Green	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	Pipe insulation	fiberglass	Green	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	Ceiling	concrete	White	None	0	0	Negative
1	1	15-1	Women's Lacrosse Locker Room Restroom	Floor	concrete	Grey	Flaking	3	0	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	Wall	CMU	Green	Efflorescence	50	0.1	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	W1	CMU	Green	None	0	0.1	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	W2	CMU	Green	Efflorescence	50	0	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	W3	CMU	Green	None	0	0.1	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	W4	CMU	Green	None	0	0.1	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	1	16-1	Women's Lacrosse Locker Room Shower Area	Ceiling	Concrete	White	Flaking	18	0	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	Conduit	Metal	White	None	0	0.3	Negative
1	1	16-1	Women's Lacrosse Locker Room Shower Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Wall	CMU	Green	None	0	0	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Floor	Concrete	Grey	Flaking	3	0	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	W1	CMU	Green	None	0	0.1	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Cove Base	Ceramic	Grey	None	0	0	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	W2	CMU	Green	None	0	0.1	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	W3	CMU	Green	None	0	0	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	W4	CMU	Green	None	0	0.1	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Ceiling	concrete	White	None	0	0	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Conduit	Metal	White	None	0	0.2	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Pipe insulation	fiberglass	Green	None	0	0.2	Negative
1	1	17-1	Storage Room next to Women's Lacrosse Locker Room and Restroom	Floor	concrete	Grey	Flaking	3	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	Wall	CMU	Blue/Green	None	0	0.1	Negative
1	1	18-1	Women's Lacrosse Locker Room	Floor	Concrete	Grey	None	0	0.2	Negative
1	1	18-1	Women's Lacrosse Locker Room	W1	CMU	Blue/Green	None	0	0.1	Negative
1	1	18-1	Women's Lacrosse Locker Room	Door Frame	Metal	Multicolor	Chipping	16	0.4	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	1	18-1	Women's Lacrosse Locker Room	Door	Metal	Multicolor	Flaking	8	0.1	Negative
1	1	18-1	Women's Lacrosse Locker Room	W2	CMU	Blue/Green	None	0	0.1	Negative
1	1	18-1	Women's Lacrosse Locker Room	Pipe	Metal	Green	None	0	0.2	Negative
1	1	18-1	Women's Lacrosse Locker Room	W3	CMU	Blue/Green	None	0	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	Shelf	Metal	Blue/Red	Chipping	30	0.6	Negative
1	1	18-1	Women's Lacrosse Locker Room	W4	CMU	Blue/Green	None	0	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	Ceiling	concrete	White	None	0	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	Pipe insulation	fiberglass	White	None	0	0	Negative
1	1	18-1	Women's Lacrosse Locker Room	duct	Metal	White	Flaking	3	0.2	Negative
1	1	18-1	Women's Lacrosse Locker Room	Floor	concrete	Grey	None	0	0.2	Negative
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	19-1	Custodial Closet inside Women's Lacrosse Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Wall	CMU	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	W1	CMU	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Door Frame	Metal	Tan	Chipping	9	0.1	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	W2	CMU	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	W3	CMU	Green	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Pipe	Metal	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	W4	CMU	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Conduit	Metal	Green	None	0	0.2	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Ceiling	concrete	Green	None	0	0.1	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Pipe insulation	fiberglass	Green	None	0	0	Negative
1	1	2-1	Water Main/Storage Room next to Building Engineer's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	3-1	Building Engineer's Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	3-1	Building Engineer's Office	Wall	CMU	White	None	0	0	Negative
1	1	3-1	Building Engineer's Office	W1	CMU	White	None	0	0	Negative
1	1	3-1	Building Engineer's Office	Door	Metal	Grey	Chipping	1	0.5	Negative
1	1	3-1	Building Engineer's Office	Door Frame	Metal	Grey	Chipping	3	0.4	Negative
1	1	3-1	Building Engineer's Office	Radiator	Metal	Tan	None	0	0	Negative
1	1	3-1	Building Engineer's Office	W2	CMU	White	None	0	0.1	Negative
1	1	3-1	Building Engineer's Office	Door Frame	Metal	Tan	None	0	0.2	Negative
1	1	3-1	Building Engineer's Office	Door	Metal	Tan	None	0	0.1	Negative
1	1	3-1	Building Engineer's Office	W3	CMU	White	None	0	0.1	Negative
1	1	3-1	Building Engineer's Office	W4	CMU	White	None	0	0	Negative
1	1	3-1	Building Engineer's Office	Pipe insulation	fiberglass	Green	None	0	0.2	Negative
1	1	3-1	Building Engineer's Office	Duct	Metal	Tan	None	0	0.3	Negative
1	1	3-1	Building Engineer's Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	3-1	Building Engineer's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	4-1	Men's Lacrosse Locker Room	Ductwork, Exterior	Metal	White	Flaking	10	0.2	Negative
1	1	4-1	Men's Lacrosse Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	4-1	Men's Lacrosse Locker Room	Wall	CMU	Blue/Green	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	4-1	Men's Lacrosse Locker Room	Wall	CMU	Blue/Green	None	0	0.2	Negative
1	1	4-1	Men's Lacrosse Locker Room	Floor	Concrete	Grey	Chipping	700	0.3	Negative
1	1	4-1	Men's Lacrosse Locker Room	W1	CMU	Blue/Green	None	0	0	Negative
1	1	4-1	Men's Lacrosse Locker Room	Door Frame	Metal	Multicolor	Flaking	14	0.8	Positive
1	1	4-1	Men's Lacrosse Locker Room	Door	Metal	Multicolor	Flaking	2	0	Negative
1	1	4-1	Men's Lacrosse Locker Room	Coat Rack	Wood	Red	None	0	0.1	Negative
1	1	4-1	Men's Lacrosse Locker Room	Shelf	Metal	Blue	None	0	0.4	Negative
1	1	4-1	Men's Lacrosse Locker Room	W2	CMU	Blue/Green	None	0	0	Negative
1	1	4-1	Men's Lacrosse Locker Room	W3	CMU	Blue/Green	None	0	0.2	Negative
1	1	4-1	Men's Lacrosse Locker Room	Cove Base	Ceramic	Grey	Flaking	40	0.1	Negative
1	1	4-1	Men's Lacrosse Locker Room	W4	CMU	Blue/Green	None	0	0.1	Negative
1	1	4-1	Men's Lacrosse Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	4-1	Men's Lacrosse Locker Room	Conduit	Metal	White	None	0	0.5	Negative
1	1	4-1	Men's Lacrosse Locker Room	Floor	Concrete	Grey	Chipping	700	0.3	Negative
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	5-1	Custodial Closet inside Men's Lacrosse Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	Wall	CMU	Green	None	0	0.1	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A



			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	W1	CMU	Green	None	0	0.1	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	Cove Base	Ceramic	Grey	Flaking	10	0.1	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	W2	CMU	Green	None	0	0	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	W3	CMU	Green	None	0	0	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	W4	CMU	Green	None	0	0	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	Ceiling	Concrete	White	None	0	0.6	Negative
1	1	6-1	Storage Room next to Men's Lacrosse Locker Room and Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Wall	CMU	Green	None	0	0.1	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	W1	CMU	Green	None	0	0.1	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Cove Base	Ceramic	Grey	None	0	0.1	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	W2	CMU	Green	None	0	0	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	W3	CMU	Green	None	0	0	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Radiator	Metal	Tan	None	0	0.1	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	W4	CMU	Green	None	0	0.1	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Pipe insulation	fiberglass	Green	None	0	0	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Ceiling	Concrete	White	None	0	0	Negative
1	1	7-1	Men's Lacrosse Locker Room Shower Area	Floor	Concrete	Grey	Flaking	40	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Wall	CMU	Green	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	W1	CMU	Green	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	W2	CMU	Green	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Cove Base	Ceramic	Grey	Flaking	20	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	W3	CMU	Green	None	0	0.5	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	W4	CMU	Green	None	0	0.1	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATTA Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	1	8-1	Men's Lacrosse Locker Room Restroom	Radiator	Metal	Tan	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Partitions	Metal	Tan	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Duct	Metal	Green	None	0	0.1	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Pipe insulation	fiberglass	Green	None	0	0.1	Negative
1	1	8-1	Men's Lacrosse Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	Wall	CMU	Yellow	None	0	0	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	W1	CMU	Yellow	None	0	0.1	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	Door Frame	Metal	Tan	Chipping	1	0.1	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	W2	CMU	Yellow	None	0	0.1	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	W3	CMU	Yellow	None	0	0	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	W4	CMU	Yellow	None	0	0	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	pipe	Metal	Yellow	Chipping	8	0.2	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	Ceiling	Plaster	White	None	0	0.5	Negative
1	1	9-1	Coaches Shower Area next to Men's Lacrosse Locker Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	S01	Stairs to 2nd Floor	W1	Plaster	White	None	0	0.4	Negative
1	1	S01	Stairs to 2nd Floor	Door	Metal	Brown	None	0	0.2	Negative
1	1	S01	Stairs to 2nd Floor	Door Frame	Wood	Brown	None	0	0.2	Negative
1	1	S01	Stairs to 2nd Floor	W2	Plaster	White	None	0	0.2	Negative
1	1	S01	Stairs to 2nd Floor	Radiator Cover	Metal	White	None	0	0.2	Negative
1	1	S01	Stairs to 2nd Floor	W3	Plaster	White	Flaking	24	0.3	Negative
1	1	S01	Stairs to 2nd Floor	Stringer	Wood	White	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	S01	Stairs to 2nd Floor	Riser	Wood	White	None	0	0	Negative
1	1	S01	Stairs to 2nd Floor	W4	Plaster	White	None	0	0.3	Negative
1	1	S01	Stairs to 2nd Floor	Ceiling	Concrete	White	None	0	0.1	Negative
1	1	S01	Stairs to 2nd Floor	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	026T	Restroom next to Large Office at Top of Stairs	W1	Plaster	Blue	None	0	0.4	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	Door Frame	Metal	Blue	None	0	0.2	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	026T	Restroom next to Large Office at Top of Stairs	W3	Plaster	Blue	None	0	0.2	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	Window Sill	Wood	White	Chipping	1	0.2	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	W4	Plaster	Blue	None	0	0.4	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	Ceiling	concrete	White	None	0	0.3	Negative
1	2	026T	Restroom next to Large Office at Top of Stairs	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	20-1	Restroom along Dyre Street	W1	Plaster	Blue	None	0	0.1	Negative
1	2	20-1	Restroom along Dyre Street	Door Frame	Metal	Brown	None	0	0.2	Negative
1	2	20-1	Restroom along Dyre Street	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	20-1	Restroom along Dyre Street	W3	Plaster	Blue	None	0	0	Negative
1	2	20-1	Restroom along Dyre Street	Window Sill	Wood	White	None	0	0.1	Negative
1	2	20-1	Restroom along Dyre Street	W4	Plaster	Blue	None	0	0	Negative
1	2	20-1	Restroom along Dyre Street	Ceiling	concrete	White	None	0	0	Negative
1	2	20-1	Restroom along Dyre Street	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	21	Office next to Hallway to Restroom along Dyre Street	Ceiling	Concrete	White	None	0	0	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	W1	Plaster	Tan	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	21	Office next to Hallway to Restroom along Dyre Street	Closet Door Frame	Metal	Brown	None	0	0.2	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	W2	Plaster	Tan	None	0	0	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	Window Sill	Wood	Tan	None	0	0	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	W3	Plaster	Tan	None	0	0.4	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	W4	Plaster	Tan	None	0	0.4	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	Cove Base	Wood	brown	None	0	0.3	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	Ceiling	concrete	White	None	0	0	Negative
1	2	21	Office next to Hallway to Restroom along Dyre Street	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	22	Kitchen	Ceiling	Concrete	White	None	0	0.2	Negative
1	2	22	Kitchen	W1	Plaster	Tan	None	0	0	Negative
1	2	22	Kitchen	Door Frame	Metal	Brown	None	0	0.2	Negative
1	2	22	Kitchen	W2	Plaster	Blue	None	0	0.4	Negative
1	2	22	Kitchen	Cove Base	Wood	White	None	0	0.2	Negative
1	2	22	Kitchen	W3	Plaster	Blue	None	0	0	Negative
1	2	22	Kitchen	Window Sill	Wood	White	None	0	0.1	Negative
1	2	22	Kitchen	W4	Plaster	blue	None	0	0.2	Negative
1	2	22	Kitchen	Ceiling	concrete	White	None	0	0.2	Negative
1	2	22	Kitchen	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	23	Large Office at Top of Stairs	W1	Plaster	Blue	None	0	0	Negative
1	2	23	Large Office at Top of Stairs	Conduit	Plastic	Blue	None	0	0.3	Negative
1	2	23	Large Office at Top of Stairs	Door Frame	Metal	Blue	Friction	1	0.1	Negative
1	2	23	Large Office at Top of Stairs	W2	Plaster	Blue	None	0	0	Negative
1	2	23	Large Office at Top of Stairs	W3	Plaster	brown	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	23	Large Office at Top of Stairs	Shelf	Wood	Blue	None	0	0.1	Negative
1	2	23	Large Office at Top of Stairs	Cove Base	Metal	Blue	None	0	0	Negative
1	2	23	Large Office at Top of Stairs	W4	Plaster	Blue	None	0	0	Negative
1	2	23	Large Office at Top of Stairs	Window Sill	Wood	Blue	Cracking	3	0	Negative
1	2	23	Large Office at Top of Stairs	Ceiling	concrete	White	None	0	0	Negative
1	2	23	Large Office at Top of Stairs	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	26	Office next to Restroom at Top of Stairs	Ceiling	Concrete	White	None	0	0	Negative
1	2	26	Office next to Restroom at Top of Stairs	W1	Plaster	Tan	None	0	0.3	Negative
1	2	26	Office next to Restroom at Top of Stairs	Door Frame	Metal	Blue	Chipping	1	0.2	Negative
1	2	26	Office next to Restroom at Top of Stairs	W2	Plaster	Tan	None	0	0	Negative
1	2	26	Office next to Restroom at Top of Stairs	Window Sill	Wood	White	Cracking	3	0.2	Negative
1	2	26	Office next to Restroom at Top of Stairs	W3	Plaster	Tan	None	0	0	Negative
1	2	26	Office next to Restroom at Top of Stairs	W4	Plaster	Tan	None	0	0.3	Negative
1	2	26	Office next to Restroom at Top of Stairs	Cove Base	Metal	Brown	None	0	0.2	Negative
1	2	26	Office next to Restroom at Top of Stairs	Closet Door Frame	Metal	Brown	Chipping	2	0.2	Negative
1	2	26	Office next to Restroom at Top of Stairs	Ceiling	concrete	White	None	0	0	Negative
1	2	26	Office next to Restroom at Top of Stairs	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	27	Office on the Corner of Large and Dyre Streets	Ceiling	Concrete	White	None	0	0	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	W1	Plaster	Tan	Flaking	2	0.1	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Conduit	plastic	tan	None	0	0.2	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Door Frame	Metal	Brown	None	0	0.1	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Cove Base	Wood	Brown	None	0	0.2	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	W2	Plaster	Tan	None	0	0.4	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	2	27	Office on the Corner of Large and Dyre Streets	Window Sill	Wood	Tan	None	0	0.1	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	W3	Plaster	Tan	Efflorescence	2	0.5	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	W4	Plaster	tan	None	0	0.5	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Closet Door Frame	Metal	Brown	None	0	0.2	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Ceiling	concrete	White	None	0	0	Negative
1	2	27	Office on the Corner of Large and Dyre Streets	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	H21	Hallway to Restroom along Dyre Street	W1	Plaster	Blue	None	0	0.1	Negative
1	2	H21	Hallway to Restroom along Dyre Street	Door Frame	Metal	Brown	None	0	0.2	Negative
1	2	H21	Hallway to Restroom along Dyre Street	Cove Base	Wood	Brown	None	0	0	Negative
1	2	H21	Hallway to Restroom along Dyre Street	W2	Plaster	Blue	None	0	0.2	Negative
1	2	H21	Hallway to Restroom along Dyre Street	W4	Plaster	Blue	None	0	0	Negative
1	2	H21	Hallway to Restroom along Dyre Street	Ceiling	concrete	White	None	0	0.1	Negative
1	2	H21	Hallway to Restroom along Dyre Street	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Floor	Concrete	Grey	Friction	20	0.3	Negative
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	W1	Plaster	Green	Flaking	20	1.3	Positive
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Conduit	Metal	Green	Flaking	1	0.5	Negative
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Door	Metal	Grey/Brown	Flaking	14	0.3	Negative
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Door Frame	Metal	Grey/Green	Flaking	10	0.5	Negative
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Window Frame	Wood	Green	Flaking	5	6	Positive
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	W2	Plaster	Green	Flaking	16	9.2	Positive

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	W3	Plaster	Green	Flaking	24	15.2	Positive
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	W4	Plaster	Green	Flaking	24	12.4	Positive
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Ceiling	Plaster	Green	Flaking	3	1.9	Positive
2	1	1-2	Utility Closet in Building on Corner of Large and Wakeling Streets	Floor	concrete	Grey	Friction	20	0.3	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Wall	CMU	White	None	0	0.5	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Floor	Concrete	Grey	Friction	180	0.1	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	W1	Plaster	White	Cracking	22	0.3	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Conduit	Metal	White	Cracking	2	0.4	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Door	Metal	Grey	Flaking	2	0.1	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Door Frame	Metal	Grey	Flaking	8	0.4	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	W2	cmu	White	None	0	0.5	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	W3	Plaster	White	Efflorescence	8	0.6	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Stalls	Metal	Tan	Flaking	6	0.1	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Cove Base	concrete	Brown	None	0	0.3	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	W4	Plaster	White	Spalling	14	0.2	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Ceiling	Plaster	White	None	0	0.4	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Duct	Metal	White	Cracking	4	0.2	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Pipe insulation	fiberglass	White	None	0	0.1	Negative
2	1	2-2	Men's Restroom in Building on Corner of Large and Wakeling Streets	Floor	concrete	Grey	Friction	180	0.1	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Wall	CMU	White	None	0	0.6	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Floor	Concrete	Brown	Friction	80	0.2	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	W1	Plaster	White	Spalling	32	1.2	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Conduit	Metal	White	Flaking	1	0.2	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Window Frame	Wood	White	Flaking	4	4	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Door	Metal	Grey	Flaking	12	0.4	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Door Frame	Metal	Grey	Flaking	8	0.6	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	W2	CMU	White	None	0	0.6	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	W2	Plaster	White	Flaking	30	22	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Pipe insulation	fiberglass	White	None	0	0.1	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Stalls	Metal	Tan	Flaking	12	0	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Door	Wood	Tan	Cracking	2	2.8	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Door Frame	Metal	tan	None	0	2	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	W3	Plaster	White	Flaking	34	1	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	W4	Plaster	White	Flaking	80	0.4	Negative



			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Pipe	Metal	White	Flaking	1	0.1	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Cove Base	concrete	Brown	Flaking	12	0.3	Negative
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Ceiling	Plaster	White	Flaking	10	5	Positive
2	1	3-2	Women's Restroom in Building on Corner of Large and Wakeling Streets	Floor	concrete	Brown	Friction	80	0.2	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Wall	CMU	White	None	0	0.5	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Floor	Concrete	Grey	Friction	400	0.1	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W1	Plaster	White	None	0	7.1	Positive
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Door	Metal	Grey	Flaking	26	0.1	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Door Frame	Metal	Grey	Flaking	8	0.3	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Coat Rack	Wood	White	None	0	0.6	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Pipe insulation	fiberglass	Green	None	0	0	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	pipe	Metal	Green	Chipping	6	0.2	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Window Frame	Wood	White	Flaking	4	17	Positive
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Window Sash	Wood	Green	Flaking	12	3.8	Positive
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W2	Plaster	White	None	0	10.1	Positive
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W3	Plaster	White	None	0	0.6	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W3	Brick	White	None	0	5.9	Positive

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W4	Brick	White	None	0	10.3	Positive
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Duct	Metal	Green	Chipping	3	0.1	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	W4	Cmu	White	None	0	0.5	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Ceiling	Plaster	Green	Flaking	90	0.3	Negative
2	1	4-2	Weight Room in Building on Corner of Large and Wakeling Streets	Floor	concrete	Grey	Friction	400	0.1	Negative
3	1	1-3	Garage	Ceiling	Concrete	Tan	None	0	0.1	Negative
3	1	1-3	Garage	Wall	CMU	Tan	None	0	0	Negative
3	1	1-3	Garage	W1	CMU	Tan	None	0	0	Negative
3	1	1-3	Garage	W2	CMU	Tan	None	0	0	Negative
3	1	1-3	Garage	W3	CMU	Tan	None	0	0.1	Negative
3	1	1-3	Garage	W4	CMU	Tan	None	0	0.1	Negative
3	1	1-3	Garage	Pipe insulation	Fiberglass	Tan	Cracking	3	0.1	Negative
3	1	1-3	Garage	Ceiling	concrete	Tan	None	0	0.1	Negative
3	1	1-3	Garage	Conduit	Metal	Tan	None	0	0.4	Negative
3	1	1-3	Garage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	Wall	CMU	Green	None	0	0	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	W1	CMU	Green	None	0	0.1	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	Door Frame	Metal	White	Chipping	4	0.2	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	W2	CMU	Green	None	0	0.1	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	W3	CMU	Green	None	0	0.1	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	W4	CMU	Green	None	0	0	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	Ceiling	Plaster	White	None	0	0	Negative
3	1	10-3	Coaches Shower Area next to Men's Varsity Football Locker Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Wall	CMU	White	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	W1	CMU	White	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Door Frame	Metal	White	Chipping	1	0.4	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	W2	CMU	White	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Electrical Cabinet	Metal	Green	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Cove Base	Ceramic	Red	Chipping	3	0.1	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Pipe insulation	Fiberglass	Green	None	0	0.1	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	W3	CMU	White	None	0	0.1	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	W4	CMU	White	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Radiator	Metal	Tan	None	0	0	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Ceiling	Concrete	White	None	0	0.5	Negative
3	1	11-3	Coaches Dressing Room next to Men's Varsity Football Locker Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
3	1	12-3	Storage Room next to Football Coaches Dressing Room	W1	CMU	Green	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	W2	CMU	Green	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	W3	CMU	Green	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	12-3	Storage Room next to Football Coaches Dressing Room	W4	CMU	Green	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	Radiator	Metal	Tan	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	Pipe insulation	Fiberglass	Green	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	duct	Metal	Green	Chipping	16	0.1	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	Ceiling	Concrete	White	None	0	0	Negative
3	1	12-3	Storage Room next to Football Coaches Dressing Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	W1	CMU	Green	None	0	0.4	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	W2	CMU	Green	None	0	0.1	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	Radiator	Metal	Tan	None	0	0	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	W3	CMU	Green	None	0	0	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	W4	CMU	Green	None	0	0	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	Duct	Metal	White	None	0	0.1	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	Ceiling	Concrete	White	None	0	0	Negative
3	1	13-3	Storage Room next to Baseball Coaches Dressing Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	W1	CMU	Blue	None	0	0	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Door Frame	Metal	Tan	Chipping	12	0.4	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Conduit	Plastic	Blue	None	0	0.5	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	W2	CMU	Blue	None	0	0	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Radiator	Metal	Tan	Chipping	1	0.1	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Pipe insulation	Fiberglass	Green	None	0	0.1	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	W3	CMU	Blue	None	0	0	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	W4	CMU	Blue	None	0	0	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Ceiling	Concrete	White	None	0	0	Negative
3	1	14-3	Coaches Dressing Room next to Men's Varsity Baseball Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	W1	CMU	White	None	0	0	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	Door Frame	Metal	Tan	Chipping	8	0.3	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	W2	CMU	White	None	0	0.1	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	W3	CMU	White	None	0	0	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	W4	CMU	White	None	0	0	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	Ceiling	Plaster	White	None	0	0	Negative
3	1	15-3	Coaches Shower Area next to Men's Varsity Baseball Locker Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	W1	CMU	Green	None	0	0.1	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	W2	CMU	Green	None	0	0	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	W3	CMU	Green	None	0	0	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	W4	CMU	Green	None	0	0.1	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	Duct	Metal	Green	None	0	0.2	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	Pipe Insulation	Fiberglass	White	None	0	0.2	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	Ceiling	Concrete	White	None	0	0.2	Negative
3	1	16-3	Men's Varsity Baseball Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	W1	CMU	Green	None	0	0	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	Cove Base	Ceramic	Brown	Flaking	14	0.3	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	W2	CMU	Green	None	0	0	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	W3	CMU	Green	None	0	0	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	W4	CMU	Green	None	0	0.2	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	Ceiling	Concrete	White	Flaking	10	0.3	Negative
3	1	17-3	Men's Varsity Baseball Locker Room Shower Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	W1	CMU	Green	None	0	0.1	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	W2	CMU	Green	None	0	0	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	W3	CMU	Green	None	0	0.1	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	Radiator	Metal	Tan	None	0	0.1	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	Pipe insulation	Fiberglass	Green	None	0	0.4	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	W4	CMU	Green	None	0	0.1	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	Cove Base	Ceramic	Grey	Flaking	6	0.1	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	Ceiling	concrete	White	None	0	0.2	Negative
3	1	18-3	Storage Room next to Men's Varsity Baseball Locker Room	Floor	concrete	Grey	Cracking	100	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Ductwork, Exterior	Metal	Green	Flaking	22	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Floor	Concrete	Grey	Chipping	800	0.1	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	W1	CMU	Green	None	0	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	W2	CMU	Green	None	0	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	W3	CMU	Green	None	0	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Coat Rack	Wood	Blue	None	0	0.3	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Shelf	Metal	Red/Blue	Chipping	72	0.9	Positive
3	1	19-3	Men's Varsity Baseball Locker Room	W4	CMU	Green	None	0	0	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Ceiling	Concrete	White	None	0	0.2	Negative
3	1	19-3	Men's Varsity Baseball Locker Room	Floor	Concrete	Grey	Chipping	800	0.1	Negative
3	1	2-3	Play Room behind Garage	Wall	CMU	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	Door Frame	Metal	White	Cracking	16	0.4	Negative
3	1	2-3	Play Room behind Garage	W1	CMU	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	W2	CMU	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	W3	CMU	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	W4	CMU	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	Radiator	Metal	Tan	None	0	0.1	Negative
3	1	2-3	Play Room behind Garage	Pipe insulation	fiberglass	Tan	None	0	0.2	Negative
3	1	2-3	Play Room behind Garage	Pipe	Metal	Tan	None	0	0.3	Negative
3	1	2-3	Play Room behind Garage	Ceiling	concrete	White	None	0	0	Negative
3	1	2-3	Play Room behind Garage	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	20-3	Custodial Closet inside Men's Varsity Baseball Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
3	1	3-3	Kitchen/Concession Stand	Ductwork, Exterior	Metal	Blue	Flaking	4	0.2	Negative
3	1	3-3	Kitchen/Concession Stand	Ceiling	Concrete	White	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	Wall	CMU	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	W1	CMU	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	Door	Metal	Red/Blue	Flaking	10	0.2	Negative
3	1	3-3	Kitchen/Concession Stand	Door Frame	Metal	Yellow	Flaking	6	0.4	Negative
3	1	3-3	Kitchen/Concession Stand	W2	CMU	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	W3	CMU	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	W4	CMU	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	Door Frame	Metal	Grey	None	0	0.4	Negative
3	1	3-3	Kitchen/Concession Stand	Conduit	Metal	Blue	None	0	0.3	Negative
3	1	3-3	Kitchen/Concession Stand	Radiator	Metal	Blue	None	0	0.1	Negative
3	1	3-3	Kitchen/Concession Stand	Pipe	Metal	Blue	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	Ceiling	Concrete	White	None	0	0	Negative
3	1	3-3	Kitchen/Concession Stand	Floor	Floor Tile/Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	5-3	Men's Varsity Football Locker Room	Ceiling	Concrete	White	None	0	0	Negative
3	1	5-3	Men's Varsity Football Locker Room	Ductwork, Exterior	Metal	White	None	0	0.1	Negative
3	1	5-3	Men's Varsity Football Locker Room	Wall	CMU	Multicolor	None	0	0.1	Negative



			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATTA Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
3	1	5-3	Men's Varsity Football Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
3	1	5-3	Men's Varsity Football Locker Room	W1	CMU	Multicolor	None	0	0.1	Negative
3	1	5-3	Men's Varsity Football Locker Room	Door Frame	Metal	Yellow	Flaking	4	0.8	Positive
3	1	5-3	Men's Varsity Football Locker Room	Door	Metal	Red/Blue	Flaking	10	0.5	Negative
3	1	5-3	Men's Varsity Football Locker Room	W2	CMU	Multicolor	None	0	0.1	Negative
3	1	5-3	Men's Varsity Football Locker Room	W3	CMU	White	None	0	0.1	Negative
3	1	5-3	Men's Varsity Football Locker Room	Coat Rack	Wood	Red	None	0	0.1	Negative
3	1	5-3	Men's Varsity Football Locker Room	Shelf	Metal	White	Flaking	5	0.5	Negative
3	1	5-3	Men's Varsity Football Locker Room	W4	CMU	White	None	0	0.3	Negative
3	1	5-3	Men's Varsity Football Locker Room	Cove Base	Terracotta	Red/Blue	None	0	0	Negative
3	1	5-3	Men's Varsity Football Locker Room	Pipe insulation	Fiberglass	White	None	0	0	Negative
3	1	5-3	Men's Varsity Football Locker Room	Ceiling	Concrete	White	None	0	0.2	Negative
3	1	5-3	Men's Varsity Football Locker Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	Door Frame	Metal	White	None	0	0.3	Negative
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	1	6-3	Custodial Closet inside Men's Varsity Football Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	Wall	CMU	Multicolor	None	0	0	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	W1	CMU	Multicolor	None	0	0	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	W2	CMU	Multicolor	None	0	0	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	W3	CMU	Multicolor	None	0	0.1	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	Radiator	Metal	Tan	None	0	0	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	W4	CMU	Multicolor	None	0	0	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	Ceiling	concrete	White	None	0	0.2	Negative
3	1	7-3	Storage Room next to Men's Varsity Football Locker Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
3	1	8-3	Men's Varsity Football Locker Room Shower Area	Wall	CMU	Multicolor	None	0	0	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	W1	CMU	Multicolor	None	0	0	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	W2	CMU	Multicolor	Flaking	20	0	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	W3	CMU	Multicolor	Flaking	60	0	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	W4	CMU	Multicolor	Flaking	12	0.1	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	Ceiling	concrete	White	None	0	0.2	Negative
3	1	8-3	Men's Varsity Football Locker Room Shower Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	1	9-3	Men's Varsity Football Locker Room Restroom	W1	CMU	White	None	0	0	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	Cove Base	Ceramic	Blue	None	0	0	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	W2	CMU	White	None	0	0	Negative

			<b>Dates: 05/09/2023-05/15/2023</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Tim Smith 057622</b>	<b>Frankford High School Field House</b>						
			<b>Inspection Company: BATT Environmental</b>	<b>1098 Dyre Street, Philadelphia PA 19124</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Paint Damage</b>	<b>Paint Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
3	1	9-3	Men's Varsity Football Locker Room Restroom	Radiator	Metal	Tan	None	0	0.2	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	Pipe Insulation	Fiberglass	Green	None	0	0.1	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	W3	CMU	White	None	0	0	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	Duct	Metal	Green	None	0	0.1	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	W4	CMU	White	None	0	0.1	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	Ceiling	concrete	White	None	0	0.1	Negative
3	1	9-3	Men's Varsity Football Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Ceiling	Concrete	Green	None	0	10.6	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Floor	Concrete	Grey	Flaking	26	0.5	Negative
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	W1	Plaster	Green	Flaking	18	0.8	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Conduit	Metal	Green	None	0	0.3	Negative
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Window Frame	Wood	Green	Flaking	18	5.8	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Door	Metal	Green	Flaking	20	0.3	Negative
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Door Frame	Metal	Green	Flaking	6	0.2	Negative
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	W2	Plaster	Green	Flaking	3	10.8	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	W3	Plaster	Green	Chipping	18	11.8	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Door	Metal	Green	Flaking	3	1.6	Positive

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Door Frame	Metal	Green	Flaking	8	0.5	Negative
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	W4	Plaster	Green	Flaking	2	5.7	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Ceiling	concrete	Green	None	0	10.6	Positive
4	1	1-4	Utility Closet in Building on Corner of Rutland and Wakeling Streets	Floor	concrete	Grey	Flaking	26	0.5	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Ductwork, Exterior	Metal	Tan	Flaking	26	0.3	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Ceiling	Concrete	White	Flaking	6	0.5	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Wall	CMU	White	None	0	0.2	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Floor	Concrete	Brown	Friction	120	0.6	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	W1	Plaster	White	Flaking	5	0.4	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Conduit	Metal	White	None	0	0.6	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Door	Metal	Grey	Flaking	2	0.1	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Door Frame	Metal	Brown	Flaking	8	0.3	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	W2	Plaster	White	Efflorescence	5	6.5	Positive
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	W3	Plaster	White	Flaking	40	0.8	Positive
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	W4	CMU	White	None	0	0.2	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Stall Door	Metal	Tan	Chipping	3	0.1	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Cove Base	Ceramic	Brown	None	0	0.3	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Ceiling	concrete	White	Flaking	6	0.5	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Pipe Insulation	fiberglass	White	None	0	0.2	Negative
4	1	2-4	Men's Restroom in Building on Corner of Rutland and Wakeling Streets	Floor	concrete	Brown	Friction	120	0.6	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Ceiling	Concrete	White	Flaking	5	6.5	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Wall	Concrete	White	Flaking	30	7.3	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Wall	CMU	White	None	0	0.1	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Floor	Concrete	Brown	Friction	120	0.8	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	W1	Plaster	White	Flaking	2	3.8	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Window Frame	Wood	Green	Flaking	1	5.3	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Door	Metal	Brown	Flaking	24	0.4	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Door Frame	Metal	Brown	Flaking	12	0.5	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	W2	concrete	White	Flaking	200	0.5	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	W3	Plaster	White	Flaking	20	5.3	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Conduit	Metal	White	None	0	0.4	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Cove Base	Ceramic	Brown	Flaking	26	0.3	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	W4	Plaster	White	Flaking	30	7.3	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	W4	CMU	White	None	0	0.1	Negative

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Stall Door	Metal	Tan	Chipping	3	0.1	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Pipe Insulation	fiberglass	White	None	0	0	Negative
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Ceiling	Concrete	White	Flaking	5	6.5	Positive
4	1	3-4	Women's Restroom in Building on Corner of Rutland and Wakeling Streets	Floor	concrete	Brown	Friction	120	0.8	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Ceiling	Concrete	White	None	0	0.3	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Wall	CMU	White	None	0	0	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Floor	Concrete	Grey	Friction	200	0.1	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W1	Plaster	White	Flaking	20	4.5	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Door	Metal	Brown	Flaking	4	0.1	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Door Frame	Metal	Brown	Flaking	12	0.6	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W2	CMU	White	None	0	0	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W2	Brick	Green	Flaking	160	13.3	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W3	Plaster	White	None	0	0.3	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W3	Brick	Green	Flaking	100	19.6	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Window Frame	Wood	Green	Alligatoring	2	15.8	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Window Frame	Wood	Green	Flaking	4	18.7	Positive
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	W4	Plaster	White	None	0	9.2	Positive

			Dates: 05/09/2023-05/15/2023	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Tim Smith 057622	Frankford High School Field House						
			Inspection Company: BATT Environmental	1098 Dyre Street, Philadelphia PA 19124						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Cove Base	concrete	Grey	Flaking	280	0.5	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Duct	Metal	White	None	0	0.1	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Ceiling	concrete	White	None	0	0.3	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Pipe Insulation	fiberglass	Green	None	0	0	Negative
4	1	4-4	Equipment Storage Room in Building on Corner of Rutland and Wakeling Streets	Floor	concrete	Grey	Friction	200	0.1	Negative

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.