

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
1	4	S421	Former Fan Room	W1	Plaster	White	Chipping	200	5.6	Positive
1	4	S421	Former Fan Room	W2	Brick	White	Chipping	100	1.9	Positive
1	4	S421	Former Fan Room	W3	Brick	White	Chipping	100	2.1	Positive
1	4	S421	Former Fan Room	W4	Brick	White	Chipping	100	1.4	Positive
1	4	S421	Former Fan Room	Ceiling	Concrete	White	Flaking	100	0.07	Negative
1	4	S421	Former Fan Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	S421	Former Fan Room	Fan	Metal	Grey	Flaking	300	1.1	Positive
1	4	S421	Former Fan Room	Pipe	Metal	White	Chipping	20	0.17	Negative
1	4	S421	Former Fan Room	Radiator	Metal	Grey	Chipping	20	3.1	Positive
1	4	S421	Former Fan Room	Stair Tread	Metal	Grey	Chipping	20	0.9	Positive
1	4	S421	Former Fan Room	Stringer	Metal	White	Chipping	50	9.4	Positive
1	4	S421	Former Fan Room	Hand Rail	Metal	Grey	Chipping	15	0.19	Negative
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	W1	Plaster	White	Cracking	100	23.6	Positive
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	W2	Plaster	White	Cracking	200	26.4	Positive
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	W3	Plaster	White	Cracking	50	22.3	Positive
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	W4	Plaster	White	Cracking	50	6.8	Positive
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	Ceiling	Plaster	White	Cracking	200	12.3	Positive
1	4	H414A	Fresh Air Damper Room/Hallway on 17th Street Side	Radiator	Metal	Grey	Chipping	10	2.3	Positive
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	W1	Plaster	White	Cracking	50	19.7	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	W2	Plaster	White	Cracking	100	22.5	Positive
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	W3	Plaster	White	Cracking	20	23.7	Positive
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	W4	Plaster	White	Cracking	100	23.3	Positive
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	Ceiling	Plaster	White	Cracking	50	16.2	Positive
1	4	H414B	Fresh Air Damper Room/Hallway on 18th Street Side	Radiator	Metal	Grey	Chipping	10	7.4	Positive
1	4	402	4th Floor Roof Girl's Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	402	4th Floor Roof Girl's Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	402	4th Floor Roof Girl's Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	402	4th Floor Roof Girl's Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	402	4th Floor Roof Girl's Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	402	4th Floor Roof Girl's Restroom	Ceiling	Plaster	White	None	0	23.2	Positive
1	4	402	4th Floor Roof Girl's Restroom	Door Frame	Metal	Brown	Chipping	5	0	Negative
1	4	401	4th Floor Roof Boy's Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	401	4th Floor Roof Boy's Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	401	4th Floor Roof Boy's Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	401	4th Floor Roof Boy's Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	401	4th Floor Roof Boy's Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	401	4th Floor Roof Boy's Restroom	Ceiling	Plaster	White	Cracking	20	11.2	Positive
1	4	401	4th Floor Roof Boy's Restroom	Door Frame	Metal	Brown	Chipping	5	0	Negative
1	3	309A	Closet next to Classroom 309	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	309A	Closet next to Classroom 309	W1	Plaster	Blue	None	0	22.9	Positive
1	3	309A	Closet next to Classroom 309	W2	Plaster	Blue	Efflorescence	10	22.4	Positive
1	3	309A	Closet next to Classroom 309	W3	Plaster	Blue	Flaking	5	27.3	Positive
1	3	309A	Closet next to Classroom 309	W4	Plaster	Blue	Chipping	10	23.3	Positive
1	3	309A	Closet next to Classroom 309	Ceiling	Plaster	White	Efflorescence	50	23.1	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	M	P	D	P	X
l	l	o	n	o	o	a	a	e	a	R
e	o	o	e	o	o	o	o	o	o	o
n	r	o	o	o	o	o	o	o	o	o
t		#	N	C	M	C	D	Q	R	(
			o	o	S	S	D	a	e	+
			n	C	M	C	D	a	e	-
			e	C	S	C	D	a	e)
			r	C	S	C	D	a	e)
			n	C	S	C	D	a	e)
			e	C	S	C	D	a	e)
			r	C	S	C	D	a	e)
1	3	308B	Closet across from Classroom 309	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	308B	Closet across from Classroom 309	W1	Plaster	Blue	Flaking	50	3.8	Positive
1	3	308B	Closet across from Classroom 309	W2	Plaster	Blue	Efflorescence	50	15.3	Positive
1	3	308B	Closet across from Classroom 309	W3	Plaster	Blue	Efflorescence	100	14.5	Positive
1	3	308B	Closet across from Classroom 309	W4	Plaster	Blue	Efflorescence	150	15.9	Positive
1	3	308B	Closet across from Classroom 309	Ceiling	Plaster	Blue	Flaking	200	14.6	Positive
1	3	308B	Closet across from Classroom 309	Radiator	Metal	Grey	Chipping	10	0.02	Negative
1	3	308C	Book Closet across from Classroom 308	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	308C	Book Closet across from Classroom 308	W1	Plaster	Tan	Cracking	3	5.2	Positive
1	3	308C	Book Closet across from Classroom 308	W2	Plaster	Tan	Cracking	4	6.3	Positive
1	3	308C	Book Closet across from Classroom 308	W3	Plaster	Tan	Cracking	5	4.2	Positive
1	3	308C	Book Closet across from Classroom 308	W4	Plaster	Tan	Cracking	2	3.1	Positive
1	3	308C	Book Closet across from Classroom 308	Ceiling	Plaster	Tan	Cracking	2	4	Positive
1	3	308D	Book Storage under 4th Floor Access Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	308D	Book Storage under 4th Floor Access Stairwell	W1	Plaster	Tan	Cracking	2	5	Positive
1	3	308D	Book Storage under 4th Floor Access Stairwell	W2	Plaster	Tan	Cracking	3	6.2	Positive
1	3	308D	Book Storage under 4th Floor Access Stairwell	W3	Plaster	Tan	Cracking	4	3.2	Positive
1	3	308D	Book Storage under 4th Floor Access Stairwell	W4	Plaster	Tan	Cracking	2	3.5	Positive
1	3	308D	Book Storage under 4th Floor Access Stairwell	Ceiling	Plaster	Tan	None	0	4.5	Positive
1	3	307B	Closet across from Classroom 307	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	307B	Closet across from Classroom 307	W1	Plaster	Tan	Cracking	25	11.1	Positive
1	3	307B	Closet across from Classroom 307	W2	Plaster	Tan	Cracking	25	13.1	Positive
1	3	307B	Closet across from Classroom 307	W3	Plaster	Tan	Flaking	15	16.3	Positive
1	3	307B	Closet across from Classroom 307	W4	Plaster	Tan	Flaking	15	13.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	307B	Closet across from Classroom 307	Ceiling	Plaster	Tan	Chipping	50	14.3	Positive
1	3	S36	Stairwell across from Classroom 304	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	S36	Stairwell across from Classroom 304	Hand Rail	Metal	Brown	Chipping	5	0.04	Negative
1	3	S36	Stairwell across from Classroom 304	W1	Plaster	White	None	0	15.2	Positive
1	3	S36	Stairwell across from Classroom 304	W2	Plaster	White	Flaking	15	22.7	Positive
1	3	S36	Stairwell across from Classroom 304	W3	Plaster	White	None	0	8.2	Positive
1	3	S36	Stairwell across from Classroom 304	W4	Plaster	White	None	0	13.1	Positive
1	3	S36	Stairwell across from Classroom 304	Ceiling	Concrete	White	None	0	0.02	Negative
1	3	S36	Stairwell across from Classroom 304	Radiator	Metal	Grey	Chipping	5	1.3	Positive
1	3	S36	Stairwell across from Classroom 304	Stringer	Concrete	Brown	Chipping	5	2.9	Positive
1	3	S36	Stairwell across from Classroom 304	Stair Tread	Concrete	Grey	Chipping	5	2.9	Positive
1	3	S36	Stairwell across from Classroom 304	Stair Riser	Concrete	Grey	Chipping	5	9.5	Positive
1	3	S36	Stairwell across from Classroom 301	Door	Metal	Brown	Chipping	1	8.3	Positive
1	3	S36	Stairwell across from Classroom 304	Door Frame	Metal	Brown	Chipping	1	9.5	Positive
1	3	S36	Stairwell across from Classroom 304	Newel Post	Metal	Brown	Chipping	5	7.1	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	H312	Hallway from Classrooms 311 to 304	W1	Plaster	White	Chipping	30	18.9	Positive
1	3	H312	Hallway from Classrooms 311 to 304	W2	Plaster	White	None	0	21.7	Positive
1	3	H312	Hallway from Classrooms 311 to 304	W3	Plaster	White	Chipping	50	27.1	Positive
1	3	H312	Hallway from Classrooms 311 to 304	W4	Plaster	White	None	0	22.4	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Ceiling	Plaster	White	Alligating	500	27.6	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Radiator	Metal	Brown	Chipping	25	8.9	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Stair Tread	Concrete	Grey	Chipping	5	3	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Stair Riser	Concrete	Grey	Chipping	5	4.3	Positive
1	3	H312	Hallway from Classrooms 311 to 304	Newel Post	Metal	Brown	Chipping	5	7.7	Positive
1	3	325	Classroom 325	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	325	Classroom 325	W1	Plaster	White	None	0	22.5	Positive
1	3	325	Classroom 325	W2	Plaster	White	None	0	23.1	Positive
1	3	325	Classroom 325	W3	Plaster	White	None	0	21.2	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	325	Classroom 325	W4	CMU	White	None	0	0.01	Negative
1	3	325	Classroom 325	Pipe	Metal	White	Chipping	2	3.4	Positive
1	3	325	Classroom 325	Ceiling	Plaster	White	Alligating	100	23.2	Positive
1	3	325	Classroom 325	Radiator	Metal	Grey	Chipping	1	0.4	Negative
1	3	300	Boy's Restroom across from Classroom 302	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Boy's Restroom across from Classroom 302	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Boy's Restroom across from Classroom 302	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Boy's Restroom across from Classroom 302	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Boy's Restroom across from Classroom 302	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Boy's Restroom across from Classroom 302	Ceiling	Plaster	White	Chipping	5	17.5	Positive
1	3	300	Boy's Restroom across from Classroom 302	Radiator	Metal	Grey	Chipping	2	0.3	Negative
1	3	S35	Stairwell across from Classroom 301	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S35	Stairwell across from Classroom 301	Hand Rail	Metal	Brown	Chipping	5	0.02	Negative
1	3	S35	Stairwell across from Classroom 301	W1	Plaster	White	None	0	18.2	Positive
1	3	S35	Stairwell across from Classroom 301	W2	Plaster	White	None	0	13.5	Positive
1	3	S35	Stairwell across from Classroom 301	W3	Plaster	White	Cracking	50	29.2	Positive
1	3	S35	Stairwell across from Classroom 301	W4	Plaster	White	None	0	16.9	Positive
1	3	S35	Stairwell across from Classroom 301	Ceiling	Concrete	White	None	0	0	Negative
1	3	S35	Stairwell across from Classroom 301	Radiator	Metal	Grey	Chipping	10	0.8	Positive
1	3	S35	Stairwell across from Classroom 301	Stair Tread	Concrete	Grey	Chipping	15	7.7	Positive
1	3	S35	Stairwell across from Classroom 301	Stair Riser	Concrete	Grey	Chipping	15	7.8	Positive
1	3	S35	Stairwell across from Classroom 301	Newel Post	Metal	Brown	Chipping	5	5.1	Positive
1	3	S35	Stairwell across from Classroom 304	Stringer	Concrete	Brown	Chipping	5	2.9	Positive
1	3	S35	Stairwell across from Classroom 301	Door	Metal	Brown	Chipping	1	8.3	Positive
1	3	S35	Stairwell across from Classroom 301	Door Frame	Metal	Brown	Chipping	1	8.3	Positive
1	3	H313	Hallway from Classrooms 301 to 303	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	H313	Hallway from Classrooms 301 to 303	W1	Plaster	White	Flaking	15	19.8	Positive
1	3	H313	Hallway from Classrooms 301 to 303	W3	Plaster	White	Chipping	10	27.7	Positive
1	3	H313	Hallway from Classrooms 301 to 303	Ceiling	Plaster	White	Alligating	500	24.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	S318	Fire Stairwell next to Classroom 321	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S318	Fire Stairwell next to Classroom 321	W1	Brick	White	Chipping	5	25.3	Positive
1	3	S318	Fire Stairwell next to Classroom 321	W2	Brick	White	Chipping	3	33.5	Positive
1	3	S318	Fire Stairwell next to Classroom 321	W3	Brick	White	Chipping	2	18.8	Positive
1	3	S318	Fire Stairwell next to Classroom 321	W4	Brick	White	Chipping	2	24.7	Positive
1	3	S318	Fire Stairwell next to Classroom 321	Ceiling	Plaster	White	Efflorescence	15	7.4	Positive
1	3	S318	Fire Stairwell next to Classroom 321	Ceiling	Concrete	White	Efflorescence	6	9.3	Positive
1	3	S318	Fire Stairwell next to Classroom 321	Door	Metal	Brown	None	0	0	Negative
1	3	S318	Fire Stairwell next to Classroom 321	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	3	319A	Storage across from Classroom 319	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	319A	Storage across from Classroom 319	W1	Plaster	White	Cracking	5	11.4	Positive
1	3	319A	Storage across from Classroom 319	W2	Plaster	White	Cracking	3	16.6	Positive
1	3	319A	Storage across from Classroom 319	W3	CMU	White	Chipping	2	0	Negative
1	3	319A	Storage across from Classroom 319	W3	Plaster	White	Efflorescence	5	11.6	Positive
1	3	319A	Storage across from Classroom 319	W4	Plaster	White	Cracking	1	10.5	Positive
1	3	319A	Storage across from Classroom 319	Duct Work	Metal	White	Chipping	1	4.7	Positive
1	3	318	Classroom 318	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	318	Classroom 318	W1	Plaster	Tan	Chipping	2	22.8	Positive
1	3	318	Classroom 318	W2	Plaster	Tan	Chipping	3	23.7	Positive
1	3	318	Classroom 318	W3	Plaster	Tan	Efflorescence	5	26.2	Positive
1	3	318	Classroom 318	W4	Plaster	Tan	Chipping	1	29.5	Positive
1	3	318	Classroom 318	Ceiling	Plaster	White	Alligating	400	30.7	Positive
1	3	318	Classroom 318	Pipe	Metal	White	Chipping	2	3.4	Positive
1	3	318	Classroom 318	Radiator	Metal	Grey	Chipping	5	0.3	Negative
1	3	314A	Women's Restroom next to Classroom 315	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	314A	Women's Restroom next to Classroom 315	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	314A	Women's Restroom next to Classroom 315	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	314A	Women's Restroom next to Classroom 315	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	314A	Women's Restroom next to Classroom 315	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	314A	Women's Restroom next to Classroom 315	Ceiling	Plaster	White	Efflorescence	1	3.2	Positive
1	3	314A	Women's Restroom next to Classroom 315	Duct Work	Metal	White	None	0	0	Negative
1	3	H311	Hallway from Classrooms 316 to 321	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	H311	Hallway from Classrooms 316 to 321	W1	Plaster	White	Flaking	40	21.9	Positive
1	3	H311	Hallway from Classrooms 316 to 321	W2	Plaster	White	None	0	24.9	Positive
1	3	H311	Hallway from Classrooms 316 to 321	W3	Plaster	White	Flaking	50	25.3	Positive
1	3	H311	Hallway from Classrooms 316 to 321	W4	Plaster	White	None	0	30.2	Positive
1	3	H311	Hallway from Classrooms 316 to 321	Ceiling	Plaster	White	Alligatoring	500	31.2	Positive
1	3	H311	Hallway from Classrooms 316 to 321	Radiator	Metal	Brown	Chipping	25	7.8	Positive
1	3	S38	Stairwell across from Classroom 314	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	S38	Stairwell across from Classroom 314	Hand Rail	Metal	Brown	Chipping	5	0.01	Negative
1	3	S38	Stairwell across from Classroom 314	W1	Plaster	White	None	0	18.2	Positive
1	3	S38	Stairwell across from Classroom 314	W2	Plaster	White	None	0	11.4	Positive
1	3	S38	Stairwell across from Classroom 314	W3	Plaster	White	None	0	15.7	Positive
1	3	S38	Stairwell across from Classroom 314	W4	Plaster	White	None	0	20.2	Positive
1	3	S38	Stairwell across from Classroom 314	Ceiling	Concrete	White	None	0	0.02	Negative
1	3	S38	Stairwell across from Classroom 314	Door Frame	Metal	Brown	Chipping	5	5.5	Positive
1	3	S38	Stairwell across from Classroom 314	Newel Post	Metal	Brown	Chipping	2	4.8	Positive
1	3	S38	Stairwell across from Classroom 314	Stair Tread	Concrete	Grey	Chipping	15	2.6	Positive
1	3	S38	Stairwell across from Classroom 314	Stair Riser	Concrete	Grey	Chipping	15	9	Positive
1	3	S38	Stairwell across from Classroom 314	Radiator	Metal	Grey	Chipping	10	3.2	Positive
1	3	324B	Custodial Closet across from Classroom 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	324B	Custodial Closet across from Classroom 314	W1	Plaster	White	None	0	14.2	Positive
1	3	324B	Custodial Closet across from Classroom 314	W2	Plaster	White	None	0	17.8	Positive
1	3	324B	Custodial Closet across from Classroom 314	W3	Plaster	White	None	0	21.1	Positive
1	3	324B	Custodial Closet across from Classroom 314	W4	Plaster	White	None	0	15.5	Positive
1	3	324B	Custodial Closet across from Classroom 314	Ceiling	Plaster	White	None	0	13.4	Positive
1	3	324B	Custodial Closet across from Classroom 314	Duct Work	Metal	White	Friction	1	0	Negative
1	3	324B	Custodial Closet across from Classroom 314	Pipe	Metal	White	Chipping	2	3.4	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
1	3	324B	Custodial Closet across from Classroom 314	Door	Metal	Red	Chipping	1	0	Negative
1	3	324A	Girl's Restroom across from Classroom 314	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324A	Girl's Restroom across from Classroom 314	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324A	Girl's Restroom across from Classroom 314	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324A	Girl's Restroom across from Classroom 314	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324A	Girl's Restroom across from Classroom 314	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324A	Girl's Restroom across from Classroom 314	Ceiling	Plaster	White	Chipping	5	17.5	Positive
1	3	324A	Girl's Restroom across from Classroom 314	Radiator	Metal	Grey	Chipping	2	0.3	Negative
1	3	323	Classroom 323	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323	Classroom 323	W1	Plaster	White	Cracking	2	2.2	Positive
1	3	323	Classroom 323	W2	Plaster	White	None	0	17.5	Positive
1	3	323	Classroom 323	W3	Plaster	White	None	0	18.7	Positive
1	3	323	Classroom 323	W4	CMU	White	None	0	0	Negative
1	3	323	Classroom 323	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	S37	Stairwell across from Classroom 312	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	S37	Stairwell across from Classroom 312	Hand Rail	Metal	Brown	Chipping	2	1.8	Positive
1	3	S37	Stairwell across from Classroom 312	W1	Plaster	White	None	0	19.2	Positive
1	3	S37	Stairwell across from Classroom 312	W2	Plaster	White	None	0	20.4	Positive
1	3	S37	Stairwell across from Classroom 312	W3	Plaster	White	None	0	13.4	Positive
1	3	S37	Stairwell across from Classroom 312	W4	Plaster	White	None	0	12.4	Positive
1	3	S37	Stairwell across from Classroom 312	Ceiling	Concrete	White	None	0	0.01	Negative
1	3	S37	Stairwell across from Classroom 312	Door Frame	Metal	Brown	Chipping	1	6.2	Positive
1	3	S37	Stairwell across from Classroom 312	Newel Post	Metal	Brown	Chipping	2	8.8	Positive
1	3	S37	Stairwell across from Classroom 312	Stair Tread	Concrete	Grey	Chipping	10	1.8	Positive
1	3	S37	Stairwell across from Classroom 304	Stringer	Concrete	Brown	Chipping	5	2.9	Positive
1	3	S37	Stairwell across from Classroom 312	Stair Riser	Concrete	Grey	Chipping	10	5.7	Positive
1	3	S37	Stairwell across from Classroom 312	Radiator	Metal	Grey	Chipping	10	19.8	Positive
1	3	H310	Hallway from Classrooms 314 to 312	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	H310	Hallway from Classrooms 314 to 312	W1	Plaster	White	Flaking	10	26	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23							
			Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)							
			General Louis Wagner Middle School (6-8)							
			Inspection Company: Viva EHS							
			1701 West Cheltenham Avenue, Philadelphia, PA 19126							
E	F	S	O	C	S	P	D	P	X	X
l	l	h	n	o	u	o	e	a	R	R
e	o	o	o	m	o	n	s	m	e	e
n	r	#	n	e	n	e	d	q	n	n
t			a	n	a	n	e	a	g	t
			m	e	n	e	s	m	m	(
			e	n	n	n	e	n	n	+
			n	e	n	n	s	n	n	-
			a	n	a	n	e	n	n)
			m	e	n	n	s	m	m	
			e	n	n	n	e	n	n	
1	3	H310	Hallway from Classrooms 314 to 312	W3	Plaster	White	Flaking	10	21.7	Positive
1	3	H310	Hallway from Classrooms 314 to 312	Ceiling	Plaster	White	Alligating	500	29.4	Positive
1	2	218A	Storage across from Classroom 218	Floor	Concrete	White	Friction	5	0.01	Negative
1	2	218A	Storage across from Classroom 218	W1	Plaster	White	None	0	0.04	Negative
1	2	218A	Storage across from Classroom 218	W2	Plaster	White	None	0	0.07	Negative
1	2	218A	Storage across from Classroom 218	W3	Plaster	White	None	0	0.12	Negative
1	2	218A	Storage across from Classroom 218	W3	CMU	White	Efflorescence	1	0.06	Negative
1	2	218A	Storage across from Classroom 218	W4	Plaster	White	None	0	0.05	Negative
1	2	218A	Storage across from Classroom 218	Ceiling	Plaster	White	Efflorescence	2	0.04	Negative
1	2	218A	Storage across from Classroom 218	Radiator	Metal	Silver	Chipping	1	0.09	Negative
1	2	220A	Book Closet across from Classroom 219	Floor	Concrete	White	Friction	10	0	Negative
1	2	220A	Book Closet across from Classroom 219	W1	Plaster	White	Chipping	1	0.09	Negative
1	2	220A	Book Closet across from Classroom 219	W2	Plaster	White	Cracking	1	0.16	Negative
1	2	220A	Book Closet across from Classroom 219	W3	Plaster	White	Efflorescence	1	0	Negative
1	2	220A	Book Closet across from Classroom 219	W3	CMU	White	None	0	0.02	Negative
1	2	220A	Book Closet across from Classroom 219	W4	Plaster	White	None	0	0.18	Negative
1	2	220A	Book Closet across from Classroom 219	Ceiling	Plaster	White	Efflorescence	80	0.1	Negative
1	2	220A	Book Closet across from Classroom 219	Radiator	Metal	Grey	Chipping	1	0.07	Negative
1	2	S218	Fire Stairwell next to Classroom 221	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S218	Fire Stairwell next to Classroom 221	W1	Brick	White	Chipping	1	6	Positive
1	2	S218	Fire Stairwell next to Classroom 221	W2	Brick	White	Chipping	35	6.2	Positive
1	2	S218	Fire Stairwell next to Classroom 221	W3	Brick	White	Chipping	10	6.5	Positive
1	2	S218	Fire Stairwell next to Classroom 221	W4	Brick	White	Chipping	9	3.4	Positive
1	2	S218	Fire Stairwell next to Classroom 221	Ceiling	Plaster	White	Efflorescence	8	9.1	Positive
1	2	S218	Fire Stairwell next to Classroom 221	Ceiling	Concrete	White	Efflorescence	15	5.8	Positive
1	2	S218	Fire Stairwell next to Classroom 221	Door	Metal	Brown	Chipping	2	0.02	Negative
1	2	S218	Fire Stairwell next to Classroom 221	Door Frame	Metal	Brown	Chipping	2	0	Negative
1	2	202	Classroom 202	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W1	Plaster	White	Chipping	1	21.8	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	202	Classroom 202	W2	Sheetrock	White	None	0	0.03	Negative
1	2	202	Classroom 202	W3	Plaster	White	Chipping	3	21.9	Positive
1	2	202	Classroom 202	W4	Plaster	White	Chipping	1	26.9	Positive
1	2	202	Classroom 202	Ceiling	Plaster	White	Alligating	100	28.8	Positive
1	2	202	Classroom 202	Radiator	Metal	Grey	Chipping	10	0	Negative
1	2	226	Classroom 226	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	226	Classroom 226	W4	Plaster	White	None	0	25.2	Positive
1	2	226	Classroom 226	Ceiling	Plaster	White	Alligating	400	21.6	Positive
1	2	226	Classroom 226	Radiator	Metal	Grey	Chipping	5	0.4	Negative
1	2	226	Classroom 226	W1	Plaster	White	Chipping	1	22.4	Positive
1	2	226	Classroom 226	W2	CMU	White	Friction	3	0.08	Negative
1	2	226	Classroom 226	W3	Plaster	White	Chipping	2	26	Positive
1	2	203A	Nurse's Office	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office	Window Sill	Wood	White	Chipping	2	2.3	Positive
1	2	203A	Nurse's Office	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office	Ceiling	Plaster	White	Alligating	50	21.1	Positive
1	2	203A	Nurse's Office	Door Frame	Metal	White	Friction	2	2.3	Positive
1	2	203A	Nurse's Office	Door	Wood	White	Chipping	2	6	Positive
1	2	203C	Nurse's Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203C	Nurse's Office Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203C	Nurse's Office Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203C	Nurse's Office Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203C	Nurse's Office Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	203C	Nurse's Office Restroom	Ceiling	Plaster	White	None	0	24.2	Positive
1	2	203C	Nurse's Office Restroom	Window Sill	Wood	White	Chipping	1	2.1	Positive
1	2	205	Special Education/Counselor's Offices	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	205	Special Education/Counselor's Offices	W1	Plaster	Pink	Alligating	20	19.8	Positive
1	2	205	Special Education/Counselor's Offices	W2	Plaster	White	None	0	20.2	Positive
1	2	205	Special Education/Counselor's Offices	W3	Plaster	White	Cracking	10	19.7	Positive
1	2	205	Special Education/Counselor's Offices	W4	Plaster	White	Cracking	20	20.4	Positive
1	2	205	Special Education/Counselor's Offices	Ceiling	Plaster	White	Alligating	100	24.4	Positive
1	2	205	Special Education/Counselor's Offices	Radiator	Metal	Grey	Chipping	5	0.2	Negative
1	2	208B	Conference Room near Main Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	208B	Conference Room near Main Office	W1	Plaster	White	None	0	18.2	Positive
1	2	208B	Conference Room near Main Office	W2	Plaster	White	None	0	21.3	Positive
1	2	208B	Conference Room near Main Office	W3	Plaster	White	None	0	15.8	Positive
1	2	208B	Conference Room near Main Office	W4	Plaster	White	None	0	14.2	Positive
1	2	208B	Conference Room near Main Office	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	208B	Conference Room near Main Office	Radiator	Metal	Grey	Chipping	5	0.01	Negative
1	2	208E	Mechanical Closet in Main Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	208E	Mechanical Closet in Main Office	W1	Plaster	Green	Chipping	3	4.5	Positive
1	2	208E	Mechanical Closet in Main Office	W2	Plaster	Green	Chipping	2	6	Positive
1	2	208E	Mechanical Closet in Main Office	W3	Plaster	Green	Cracking	2	5.3	Positive
1	2	208E	Mechanical Closet in Main Office	W4	Plaster	Green	Chipping	3	3.8	Positive
1	2	208E	Mechanical Closet in Main Office	Ceiling	Plaster	Green	None	0	20.2	Positive
1	2	229	Principal's Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	229	Principal's Office	W1	Plaster	Blue	None	0	22.3	Positive
1	2	229	Principal's Office	W2	Plaster	Blue	None	0	24.1	Positive
1	2	229	Principal's Office	W3	Plaster	Blue	None	0	19.6	Positive
1	2	229	Principal's Office	W4	Plaster	Blue	Chipping	3	22.6	Positive
1	2	229	Principal's Office	Ceiling	Plaster	White	Cracking	50	29.2	Positive
1	2	229	Principal's Office	Radiator	Metal	Grey	Chipping	1	5.9	Positive
1	2	229A	Principal's Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	229A	Principal's Office Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	229A	Principal's Office Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	229A	Principal's Office Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	229A	Principal's Office Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	229A	Principal's Office Restroom	Ceiling	Plaster	White	Chipping	1	20.2	Positive	
1	2	229A	Principal's Office Restroom	Pipe	Metal	White	Chipping	2	0.28	Negative	
1	2	S217	Principal's Office Closet	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	S217	Principal's Office Closet	W1	Plaster	Tan	None	0	22.1	Positive	
1	2	S217	Principal's Office Closet	W2	Plaster	Tan	Cracking	2	16.7	Positive	
1	2	S217	Principal's Office Closet	W3	Plaster	Tan	Cracking	3	14.3	Positive	
1	2	S217	Principal's Office Closet	W4	Plaster	Tan	Cracking	2	12.8	Positive	
1	2	S217	Principal's Office Closet	Ceiling	Plaster	Tan	Cracking	1	10.1	Positive	
1	2	209	Classroom 209	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	209	Classroom 209	W1	Plaster	Purple	None	0	23.1	Positive	
1	2	209	Classroom 209	W1	Plaster	Grey	None	0	22.2	Positive	
1	2	209	Classroom 209	W1	Plaster	Green	None	0	30.8	Positive	
1	2	209	Classroom 209	W2	Plaster	Green	None	0	25.5	Positive	
1	2	209	Classroom 209	W3	Plaster	White	None	0	20.4	Positive	
1	2	209	Classroom 209	W4	Plaster	Purple	None	0	0.02	Negative	
1	2	209	Classroom 209	Ceiling	Plaster	White	None	0	27.1	Positive	
1	2	BAL	Auditorium Balcony	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	2	BAL	Auditorium Balcony	W1	Plaster	White	Chipping	1	0	Negative	
1	2	BAL	Auditorium Balcony	W1	Plaster	White	Chipping	2	0	Negative	
1	2	BAL	Auditorium Balcony	W2	Plaster	White	Chipping	1	0.2	Negative	
1	2	BAL	Auditorium Balcony	W3	Plaster	White	Chipping	1	0.1	Negative	
1	2	BAL	Auditorium Balcony	W4	Plaster	White	Chipping	1	0	Negative	
1	2	BAL	Auditorium Balcony	Ceiling	Plaster	White	None	0	2.1	Positive	
1	2	211C	Back Office in Vice Principal's Suite	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	211C	Back Office in Vice Principal's Suite	W1	Plaster	White	None	0	14.2	Positive	
1	2	211C	Back Office in Vice Principal's Suite	W2	Plaster	White	None	0	15.6	Positive	
1	2	211C	Back Office in Vice Principal's Suite	W3	Plaster	White	None	0	20.6	Positive	

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	211C	Back Office in Vice Principal's Suite	W4	Plaster	White	None	0	18.2	Positive
1	2	211C	Back Office in Vice Principal's Suite	Ceiling	Plaster	White	Alligatoring	50	28.2	Positive
1	2	211C	Back Office in Vice Principal's Suite	Radiator	Metal	White	Chipping	2	0.2	Negative
1	2	211D	Back Office in Vice Principal's Office Restroom	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211D	Back Office in Vice Principal's Office Restroom	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211D	Back Office in Vice Principal's Office Restroom	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211D	Back Office in Vice Principal's Office Restroom	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211D	Back Office in Vice Principal's Office Restroom	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211D	Back Office in Vice Principal's Office Restroom	Ceiling	Plaster	White	Alligatoring	50	24.3	Positive
1	2	211B	Middle Office in Vice Principal Suite	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211B	Middle Office in Vice Principal Suite	W1	Plaster	White	None	0	25.2	Positive
1	2	211B	Middle Office in Vice Principal Suite	W2	Plaster	White	None	0	24.3	Positive
1	2	211B	Middle Office in Vice Principal Suite	W3	Plaster	White	Alligatoring	40	25.9	Positive
1	2	211B	Middle Office in Vice Principal Suite	W4	Plaster	White	None	0	18.2	Positive
1	2	211B	Middle Office in Vice Principal Suite	Ceiling	Plaster	White	None	0	25.8	Positive
1	2	S27	Stairwell across from Classroom 212	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S27	Stairwell across from Classroom 212	Hand Rail	Metal	Brown	Friction	3	0.3	Negative
1	2	S27	Stairwell across from Classroom 212	W1	Plaster	White	None	0	8.2	Positive
1	2	S27	Stairwell across from Classroom 212	W2	Plaster	White	Cracking	2	28.4	Positive
1	2	S27	Stairwell across from Classroom 212	W3	Plaster	White	None	0	5.6	Positive
1	2	S27	Stairwell across from Classroom 212	W4	Plaster	White	None	0	8.2	Positive
1	2	S27	Stairwell across from Classroom 212	Ceiling	Concrete	White	None	0	0.01	Negative
1	2	S27	Stairwell across from Classroom 212	Newel Post	Metal	Brown	Friction	2	3.2	Positive
1	2	S27	Stairwell across from Classroom 212	Stair Tread	Concrete	Grey	Chipping	2	0.02	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S27	Stairwell across from Classroom 212	Stair Riser	Concrete	Grey	Chipping	4	6.1	Positive
1	2	S27	Stairwell across from Classroom 212	Door Frame	Metal	Brown	Friction	3	4.5	Positive
1	2	S27	Stairwell across from Classroom 212	Door	Metal	Blue	Friction	1	0	Negative
1	2	S27	Stairwell across from Classroom 212	Radiator	Metal	Brown	Chipping	5	1.2	Positive
1	2	227	Girl's Restroom across from Classroom 214	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	227	Girl's Restroom across from Classroom 214	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	227	Girl's Restroom across from Classroom 214	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	227	Girl's Restroom across from Classroom 214	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	227	Girl's Restroom across from Classroom 214	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	227	Girl's Restroom across from Classroom 214	Ceiling	Plaster	White	Chipping	5	12.1	Positive
1	2	227	Girl's Restroom across from Classroom 214	Radiator	Metal	Grey	Chipping	2	0.3	Negative
1	2	227B	Custodial Closet across from Classroom 214	Duct Work	Metal	White	None	0	0.02	Negative
1	2	227B	Custodial Closet across from Classroom 214	Floor	Ceramic Tile 1x1	Unpainted	N/A	N/A	N/A	N/A
1	2	227B	Custodial Closet across from Classroom 214	W1	Plaster	White	Chipping	1	17.3	Positive
1	2	227B	Custodial Closet across from Classroom 214	W2	Plaster	White	Efflorescence	5	18.4	Positive
1	2	227B	Custodial Closet across from Classroom 214	W3	Plaster	White	None	0	20.1	Positive
1	2	227B	Custodial Closet across from Classroom 214	W4	Plaster	White	None	0	18.9	Positive
1	2	227B	Custodial Closet across from Classroom 214	Ceiling	Plaster	White	Efflorescence	5	16.1	Positive
1	2	227B	Custodial Closet across from Classroom 214	Pipe	Metal	White	None	0	0.04	Negative
1	1	102	Classroom 102	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	102	Classroom 102	W1	Brick	Blue	None	0	2.2	Positive
1	1	102	Classroom 102	W2	Brick	Blue	None	0	3.4	Positive
1	1	102	Classroom 102	W3	Brick	Blue	Chipping	5	1.4	Positive
1	1	102	Classroom 102	W4	Brick	Blue	None	0	5	Positive
1	1	102	Classroom 102	Ceiling	Plaster	White	Alligatoring	100	18.9	Positive
1	1	103	Classroom 103/Storage 103	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	103	Classroom 103/Storage 103	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	103	Classroom 103/Storage 103	W1	Brick	White	Chipping	2	1.7	Positive
1	1	103	Classroom 103/Storage 103	W1	Brick	Yellow	Chipping	1	1.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)	General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS	1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F									
l	l	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
e	o									
m	o									
n	r									
t										
1	1	103	Classroom 103/Storage 103	W2	CMU	White	None	0	0	Negative
1	1	103	Classroom 103/Storage 103	W3	Concrete	White	Chipping	1	1	Positive
1	1	103	Classroom 103/Storage 103	W4	Brick	White	Chipping	1	1.2	Positive
1	1	103	Classroom 103/Storage 103	Pipe	metal	Yellow	Chipping	1	0.9	Positive
1	1	103	Classroom 103/Storage 103	Radiator	metal	Silver	Chipping	1	0.02	Negative
1	1	103	Classroom 103/Storage 103	Ceiling	Plaster	White	None	0	20.3	Positive
1	1	103	Classroom 103/Storage 103	Ceiling	Concrete	White	None	0	0.05	Negative
1	1	104	Classroom 104	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W1	Brick	Blue	None	0	1.2	Positive
1	1	104	Classroom 104	W2	Brick	Green	None	0	2.1	Positive
1	1	104	Classroom 104	W2	CMU	Green	None	0	0	Negative
1	1	104	Classroom 104	W3	Brick	Blue	None	0	1.2	Positive
1	1	104	Classroom 104	W4	CMU	Green	None	0	0	Negative
1	1	104	Classroom 104	Ceiling	Plaster	White	Alligating	100	15.6	Positive
1	1	104	Classroom 104	Radiator	Metal	Blue	None	0	0	Negative
1	1	104	Classroom 104	Pipe	Metal	Blue	None	0	0.01	Negative
1	1	104	Classroom 104	Door	Wood	Blue	Chipping	1	0	Negative
1	1	104	Classroom 104	Door Frame	Metal	Blue	None	0	0	Negative
1	1	105	Classroom 105	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	W1	Plaster	White	Flaking	20	22.7	Positive
1	1	105	Classroom 105	W2	Plaster	White	Flaking	15	21.8	Positive
1	1	105	Classroom 105	W3	Plaster	White	Flaking	10	23	Positive
1	1	105	Classroom 105	W4	Plaster	White	Flaking	10	29.5	Positive
1	1	105	Classroom 105	Ceiling	Plaster	White	Alligating	200	10.1	Positive
1	1	106	Storage Room 106 (Former Kitchen)	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	106	Storage Room 106 (Former Kitchen)	W1	Plaster	White	Alligating	100	15.2	Positive
1	1	106	Storage Room 106 (Former Kitchen)	W2	Plaster	White	Cracking	30	15.1	Positive
1	1	106	Storage Room 106 (Former Kitchen)	W3	Plaster	White	Cracking	50	17.7	Positive
1	1	106	Storage Room 106 (Former Kitchen)	W4	Plaster	White	Alligating	50	18.1	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	R	R
e	o	o	o	o	o	o	s	o	e	e
n	r	o	o	o	o	o	s	o	e	e
t	r	o	o	o	o	o	s	o	e	e
1	1	106	Storage Room 106 (Former Kitchen)	Ceiling	Plaster	White	None	0	18.3	Positive
1	1	107	Classroom 107	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	W1	Plaster	Grey	None	0	15.4	Positive
1	1	107	Classroom 107	W2	Plaster	Grey	Cracking	2	20.8	Positive
1	1	107	Classroom 107	W3	Plaster	Grey	Chipping	1	24.3	Positive
1	1	107	Classroom 107	W4	Plaster	Grey	Friction	1	11.8	Positive
1	1	107	Classroom 107	Ceiling	Plaster	White	Flaking	400	1.9	Positive
1	1	107	Classroom 107	Radiator	Metal	Grey	Chipping	1	0.08	Negative
1	1	108	Classroom 108	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W1	Plaster	White	None	0	21.2	Positive
1	1	108	Classroom 108	W2	Plaster	White	None	0	22.8	Positive
1	1	108	Classroom 108	W3	Plaster	White	None	0	30.1	Positive
1	1	108	Classroom 108	W4	Plaster	White	None	0	25.1	Positive
1	1	108	Classroom 108	Ceiling	Plaster	White	Alligatoring	100	28.8	Positive
1	1	108	Classroom 108	Radiator	Metal	Grey	Chipping	5	4.7	Positive
1	1	109	Teacher's Lounge next to Classroom 108	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	109	Teacher's Lounge next to Classroom 108	Trench Cover	Metal	Silver	Friction	2	2.5	Positive
1	1	109	Teacher's Lounge next to Classroom 108	W1	Brick	Blue	Chipping	1	0.4	Negative
1	1	109	Teacher's Lounge next to Classroom 108	W2	Brick	Blue	None	0	0.08	Negative
1	1	109	Teacher's Lounge next to Classroom 108	W3	Brick	Blue	None	0	0.21	Negative
1	1	109	Teacher's Lounge next to Classroom 108	W4	Brick	Blue	None	0	0.27	Negative
1	1	109	Teacher's Lounge next to Classroom 108	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	109	Teacher's Lounge next to Classroom 108	Radiator	Metal	Silver	None	0	0.05	Negative
1	1	109	Teacher's Lounge next to Classroom 108	Pipe	Metal	Silver	None	0	0.1	Negative
1	1	110	Weight Room 110	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Weight Room 110	W1	1x1 Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Weight Room 110	W1	Plaster	Green	Chipping	3	24.5	Positive
1	1	110	Weight Room 110	W2	1x1 Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Weight Room 110	W3	1x1 Spline Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
1	1	110	Weight Room 110	W3	Plaster	Green	Chipping	3	1.4	Positive
1	1	110	Weight Room 110	W4	1x1 Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Weight Room 110	Ceiling	1x1 Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Weight Room 110	Radiator	Metal	Grey	Friction	1	0.22	Negative
1	1	111	Custodial Closet across from Offices 101A and B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	111	Custodial Closet across from Offices 101A and B	W1	Plaster	White	Cracking	10	4.1	Positive
1	1	111	Custodial Closet across from Offices 101A and B	W2	Plaster	White	Cracking	10	1.8	Positive
1	1	111	Custodial Closet across from Offices 101A and B	W3	Plaster	White	Cracking	10	4	Positive
1	1	111	Custodial Closet across from Offices 101A and B	W4	Plaster	White	Cracking	10	7.4	Positive
1	1	111	Custodial Closet across from Offices 101A and B	Ceiling	Plaster	White	Cracking	5	4.8	Positive
1	1	112	Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	112	Building Engineer's Office	W1	Plaster	White	None	0	18.8	Positive
1	1	112	Building Engineer's Office	W2	Plaster	White	Chipping	50	22	Positive
1	1	112	Building Engineer's Office	W3	Plaster	White	Chipping	50	25.6	Positive
1	1	112	Building Engineer's Office	W4	CMU	White	Chipping	20	0.19	Negative
1	1	112	Building Engineer's Office	Ceiling	Plaster	Tan	None	0	23.6	Positive
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	W1	Plaster	White	None	0	13.4	Positive
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	W2	Plaster	White	Cracking	15	4.5	Positive
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	W3	Plaster	White	Cracking	20	4.6	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	a	R	R
e	o	o	s	o	o	o	s	u	e	e
n	r	o	o	o	o	o	s	q	r	(
t		#	N	C	M	C	D	a	e	+
			a	o	a	o	e	m	m	-
			m	n	t	l	s	e	e)
			e	e	r	e	s	n	n	e
			n	n	e	n	e	t	e	
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	W4	Plaster	White	Cracking	20	5.9	Positive
1	1	113	Storage Room next to Custodial Closet across from Offices 101A and 101B	Ceiling	Plaster	White	None	0	2.2	Positive
1	1	118	Boys' Cafeteria	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	118	Boys' Cafeteria	W1	Brick	White	None	0	1.7	Positive
1	1	118	Boys' Cafeteria	W2	Brick	White	Chipping	1	1.6	Positive
1	1	118	Boys' Cafeteria	W3	Brick	White	Chipping	1	2.7	Positive
1	1	118	Boys' Cafeteria	W4	Brick	White	None	0	5	Positive
1	1	118	Boys' Cafeteria	Ceiling	Plaster	White	Cracking	200	10.1	Positive
1	1	119	Kitchen	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119	Kitchen	Duct Work	Metal	Tan	Chipping	1	0.04	Negative
1	1	119	Kitchen	W1	Brick	White	None	0	0	Negative
1	1	119	Kitchen	W2	Brick	White	Chipping	1	2.4	Positive
1	1	119	Kitchen	W3	Brick	White	None	0	0	Negative
1	1	119	Kitchen	W4	Brick	White	None	0	0	Negative
1	1	119	Kitchen	Ceiling	Plaster	White	None	0	10.2	Positive
1	1	120	Girls' Cafeteria	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	120	Girls' Cafeteria	W1	Brick	White	None	0	1.5	Positive
1	1	120	Girls' Cafeteria	W2	CMU	White	Chipping	1	4.2	Positive
1	1	120	Girls' Cafeteria	W3	Brick	White	None	0	4.6	Positive
1	1	120	Girls' Cafeteria	W4	Brick	White	Chipping	1	1.1	Positive
1	1	120	Girls' Cafeteria	Ceiling	Plaster	White	Cracking	200	11.7	Positive
1	1	121	Fan Room near Teacher's Lounge Room 109	Floor	Concrete	Grey	Cracking	150	1.6	Positive
1	1	121	Fan Room near Teacher's Lounge Room 109	W1	Brick	White	None	0	1.2	Positive
1	1	121	Fan Room near Teacher's Lounge Room 109	W2	Brick	White	None	0	2.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)	General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS	1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F	S	O	C	S	P	D	P	X	X
l	l	p	n	o	u	o	e	a	R	R
e	o	a	e	m	b	l	s	m	e	e
m	r	c	r	e	e	e	d	q	r	(
e	o	e	o	n	o	o	s	u	e	p
n	r	s	n	s	m	l	e	n	n	s
t	e	p	a	i	a	t	d	t	e)
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	(positive/negative)
1	1	121	Fan Room near Teacher's Lounge Room 109	W3	Concrete	White	None	0	2.1	Positive
1	1	121	Fan Room near Teacher's Lounge Room 109	W4	Brick	White	None	0	1.3	Positive
1	1	121	Fan Room near Teacher's Lounge Room 109	Ceiling	Concrete	White	None	0	0	Negative
1	1	126	Girl's Restroom next to Weight Room 110	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126	Girl's Restroom next to Weight Room 110	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126	Girl's Restroom next to Weight Room 110	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126	Girl's Restroom next to Weight Room 110	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Staff Restroom in Balcony of Fan Room	Ceiling	Plaster	White	Efflorescence	1	5	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	6	Office near Boiler Room/Electrical Room Entrance	W1	Plaster	Blue	Cracking	4	18.4	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	W2	Plaster	Blue	Alligatoring	5	17.1	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	W3	Plaster	Blue	Alligatoring	5	15.9	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	W4	Plaster	Blue	Alligatoring	5	21.4	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	Ceiling	Concrete	Blue	Chipping	12	19	Positive
1	B	6	Office near Boiler Room/Electrical Room Entrance	Radiator	Metal	Silver	Chipping	2	1.9	Positive
1	B	7	Storage of Office at Electrical Entrance	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F									
l	l	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm²)	XRF (positive/negative)
e	o									
n	r									
t										
1	B	7	Storage of Office at Electrical Entrance	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	7	Storage of Office at Electrical Entrance	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	7	Storage of Office at Electrical Entrance	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	7	Storage of Office at Electrical Entrance	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	7	Storage of Office at Electrical Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	5	Storage in Basement Office near stair to Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	5	Storage in Basement Office near stair to Auditorium	W1	Concrete	Tan	Chipping	33	0.06	Negative
1	B	5	Storage in Basement Office near stair to Auditorium	W2	Concrete	Tan	Chipping	5	0.02	Negative
1	B	5	Storage in Basement Office near stair to Auditorium	W3	Concrete	Tan	Chipping	65	0.04	Negative
1	B	5	Storage in Basement Office near stair to Auditorium	W4	Concrete	Tan	Chipping	10	0.05	Negative
1	B	5	Storage in Basement Office near stair to Auditorium	Ceiling	Concrete	White	None	0	0.02	Negative
1	B	9	Girl's Gymnasium	Floor	Rubber	Unpainted	N/A	N/A	N/A	N/A
1	B	9	Girl's Gymnasium	W1	Brick	White	Chipping	3	0.4	Negative
1	B	9	Girl's Gymnasium	W2	Brick	White	Chipping	2	0.1	Negative
1	B	9	Girl's Gymnasium	W3	Brick	White	Chipping	1	0	Negative
1	B	9	Girl's Gymnasium	W4	Brick	White	Chipping	3	0.2	Negative
1	B	9	Girl's Gymnasium	Ceiling	Plaster	White	Efflorescence	35	15.8	Positive
1	B	9	Girl's Gymnasium	Door Frame	Metal	Orange	Friction	2	0.1	Negative
1	B	9	Girl's Gymnasium	Door	Metal	Orange	Friction	2	0	Negative
1	B	9	Girl's Gymnasium	Radiator	Metal	Grey	Chipping	30	0.05	Negative
1	B	10	Storage Closet in Far Corner of Girl's Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	10	Storage Closet in Far Corner of Girl's Gym	W1	Brick	White	Chipping	30	5.4	Positive
1	B	10	Storage Closet in Far Corner of Girl's Gym	W2	Concrete	White	Chipping	3	2.8	Positive
1	B	10	Storage Closet in Far Corner of Girl's Gym	W3	Concrete	White	Chipping	2	2.9	Positive

			Lead-Safe Certification Assessment Report							
			General Louis Wagner Middle School (6-8)							
			1701 West Cheltenham Avenue, Philadelphia, PA 19126							
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)							
			Inspection Company: Viva EHS							
E	F									
l	l	S	O	C	S	C	D	P	X	X
e	o	p	n	o	m	o	e	a	R	R
n	r	a	e	n	e	n	d	m	e	e
t		#	N	C	M	C	D	Q	R	(
			o	o	a	o	e	a	e	p
			n	n	m	n	s	m	m	s
			m	m	n	n	t	t	t	e
			e	e	n	n	r	r	r	n
			n	n	n	n	e	e	e	e
			a	a	n	n	s	s	s	s
			m	m	n	n	t	t	t	t
			e	e	n	n	r	r	r	r
			n	n	n	n	e	e	e	e
			a	a	n	n	t	t	t	t
			m	m	n	n	t	t	t	t
			e	e	n	n	r	r	r	r
			n	n	n	n	e	e	e	e
			a	a	n	n	t	t	t	t
			m	m	n	n	t	t	t	t
			e	e	n	n	r	r	r	r
			n	n	n	n	e	e	e	e
			a	a	n	n	t	t	t	t
			m	m	n	n	t	t	t	t
			e	e	n	n	r	r	r	r
			n	n	n	n	e	e	e	e
1	B	10	Storage Closet in Far Corner of Girl's Gym	W4	Brick	White	Chipping	2	4.3	Positive
1	B	10	Storage Closet in Far Corner of Girl's Gym	W4	Concrete	White	Chipping	2	3.7	Positive
1	B	10	Storage Closet in Far Corner of Girl's Gym	Ceiling	Concrete	White	Chipping	2	1.6	Positive
1	B	10	Storage Closet in Far Corner of Girl's Gym	Pipe	Metal	White	Chipping	2	2.3	Positive
1	B	10A	Girl's Gymnasium Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10A	Girl's Gymnasium Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10A	Girl's Gymnasium Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10A	Girl's Gymnasium Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10A	Girl's Gymnasium Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10A	Girl's Gymnasium Restroom	Ceiling	Plaster	White	Efflorescence	2	0	Negative
1	B	10B	Girls' Gym Teacher's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	10B	Girls' Gym Teacher's Office	W1	Plaster	White	Chipping	25	18.5	Positive
1	B	10B	Girls' Gym Teacher's Office	W2	Plaster	White	Chipping	50	19.9	Positive
1	B	10B	Girls' Gym Teacher's Office	W3	Plaster	White	Chipping	45	20.9	Positive
1	B	10B	Girls' Gym Teacher's Office	W4	Plaster	White	Chipping	20	20.6	Positive
1	B	10B	Girls' Gym Teacher's Office	Ceiling	Plaster	White	Chipping	2	0	Negative
1	B	10B	Girls' Gym Teacher's Office	Radiator	Metal	Silver	Chipping	5	0.1	Negative
1	B	10B	Girls' Gym Teacher's Office	pipe	Metal	White	Chipping	3	8.9	Positive
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	W1	Brick	White	Chipping	2	0	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	W2	Brick	White	Chipping	3	0.1	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	W3	Brick	White	Chipping	2	0.2	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	W4	Brick	White	Chipping	2	0	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Ceiling	Plaster	White	Efflorescence	20	17.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)	General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS	1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm ²)	XRF (positive/negative)
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Door	Metal	Orange	Chipping	2	0	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Door Frame	Metal	Orange	Chipping	2	0.1	Negative
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Stair Tread	Concrete	Grey	Chipping	5	1.7	Positive
1	B	S01	Stairwell to Gymnasium next to Girl's Restroom	Stair Riser	Concrete	Grey	Chipping	4	5.9	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	W1	Brick	White	None	0	1.2	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	W2	Brick	White	None	0	1.8	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	W3	Brick	White	None	0	2.1	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	W4	Brick	White	None	0	2.9	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	Ceiling	Plaster	White	None	0	10.1	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	Newel Post	Wood	White	None	0	0.02	Negative
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	Stair tread	Concrete	Grey	Friction	2	3.9	Positive
1	B	S02	Stairwell to Gymnasium next to Upper Gil's Locker Room	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	W1	Plaster	Tan	Chipping	20	20.2	Positive
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	W2	Plaster	Tan	Chipping	15	17.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)	General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS	1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	W3	Plaster	Tan	Chipping	25	18.5	Positive
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	W4	Plaster	Tan	Chipping	20	25.2	Positive
1	B	11	Storage Closet next to Girl's Gym Stairwell near Locker Room	Ceiling	Plaster	Tan	Chipping	15	10.7	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Floor	Concrete	Grey	Friction	3	1.3	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Duct Work	Metal	White	None	0	0.01	Negative
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	W1	Brick	White	None	0	2.4	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	W2	Brick	White	None	0	3.1	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	W3	Brick	White	None	0	1.5	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	W4	Brick	White	None	0	1.9	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Lockers	Metal	White	None	0	0.02	Negative
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Radiator	Metal	White	Chipping	1	1.2	Positive
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Pipe	Metal	White	Chipping	1	0	Negative
1	B	14	Girl's Gymnasium Locker Rooms/Restroom	Ceiling	Plaster	White	Flaking	7	No Access	No Access
1	B	9B	Girl's Gymnasium Center Storage Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	9B	Girl's Gymnasium Center Storage Closet	W1	Concrete	White	Chipping	11	1.8	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	W1	Brick	White	Chipping	7	1.6	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	W2	Concrete	White	Chipping	1	5.7	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	W2	Brick	White	Chipping	5	2.2	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	W3	Concrete	White	Chipping	4	1.2	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	W4	Brick	White	Flaking	7	2.3	Positive
1	B	9B	Girl's Gymnasium Center Storage Closet	Ceiling	Concrete	White	Chipping	7	2.2	Positive
1	CS	C	Crawlspace	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	C	Crawlspace	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	C	Crawlspace	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	C	Crawlspace	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	CS	C	Crawlspace	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	C	Crawlspace	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	C	Crawlspace	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	W1	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	W2	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	W3	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	W4	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	3	324BA	Pipe Chase in Custodial Closet across from Classroom 314	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	311	Classroom 311	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	311	Classroom 311	W1	Plaster	White	None	0	23.5	Positive
1	3	311	Classroom 311	W2	Plaster	White	None	0	22.1	Positive
1	3	311	Classroom 311	W3	Plaster	White	Flaking	10	26.9	Positive
1	3	311	Classroom 311	W4	Plaster	White	None	0	26.1	Positive
1	3	311	Classroom 311	Ceiling	Plaster	White	Alligatoring	400	30.8	Positive
1	3	311	Classroom 311	Radiator	Metal	Grey	Chipping	10	0	Negative
1	3	310	Classroom 310	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	310	Classroom 310	W1	Plaster	White	Cracking	50	20.3	Positive
1	3	310	Classroom 310	W2	Plaster	White	Flaking	10	26.5	Positive
1	3	310	Classroom 310	W3	Plaster	White	Cracking	50	24.2	Positive
1	3	310	Classroom 310	W4	Plaster	White	Alligatoring	15	0	Negative
1	3	310	Classroom 310	Ceiling	Plaster	White	Alligatoring	400	27.4	Positive
1	3	310	Classroom 310	Radiator	Metal	Grey	Chipping	10	0.1	Negative
1	3	309	Classroom 309	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	M	P	D	P	X
l	l	o	n	o	u	u	o	e	o	R
e	o	o	e	o	o	o	o	s	s	e
n	r	o	r	o	o	o	o	s	s	e
t		#	N	C	S	C	D	Q	R	(
			o	o	o	o	e	a	e	+
			n	o	o	o	o	s	s	-
			s	o	o	o	o	s	s)
			i	o	o	o	o	s	s)
			n	o	o	o	o	s	s)
1	3	309	Classroom 309	W1	Plaster	White	None	0	24.1	Positive
1	3	309	Classroom 309	W1	Plaster	White	Chipping	20	16	Positive
1	3	309	Classroom 309	W2	Plaster	White	None	0	22.7	Positive
1	3	309	Classroom 309	W3	Plaster	White	None	0	30.2	Positive
1	3	309	Classroom 309	W4	Plaster	White	None	0	27.7	Positive
1	3	309	Classroom 309	Ceiling	Plaster	White	Flaking	400	30.1	Positive
1	3	309	Classroom 309	Radiator	Metal	Grey	Chipping	10	0.11	Negative
1	3	308	Classroom 308 (Now Storage)	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	308	Classroom 308 (Now Storage)	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308	Classroom 308 (Now Storage)	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308	Classroom 308 (Now Storage)	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308	Classroom 308 (Now Storage)	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308	Classroom 308 (Now Storage)	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W1	Plaster	Blue	None	0	25.4	Positive
1	3	307	Classroom 307	W2	Plaster	Blue	None	0	24.2	Positive
1	3	307	Classroom 307	W3	Plaster	Blue	None	0	31.6	Positive
1	3	307	Classroom 307	W4	Plaster	Blue	None	0	17.6	Positive
1	3	307	Classroom 307	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	Radiator	Metal	Grey	Chipping	10	0.01	Negative
1	3	306	Classroom 306	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W1	Plaster	White	Flaking	50	21.3	Positive
1	3	306	Classroom 306	W2	Plaster	White	Chipping	30	18.8	Positive
1	3	306	Classroom 306	W3	Plaster	White	Cracking	10	21.4	Positive
1	3	306	Classroom 306	W4	Plaster	White	Chipping	10	21.6	Positive
1	3	306	Classroom 306	Ceiling	Plaster	White	Alligating	200	33.6	Positive
1	3	306	Classroom 306	Radiator	Metal	Grey	Chipping	10	0.01	Negative
1	3	305	Classroom 305	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W1	Plaster	White	Flaking	200	19.5	Positive

Dates: 10/24/22-11/15/22 1/4/23-1/5/23

Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

General Louis Wagner Middle School (6-8)

1701 West Cheltenham Avenue, Philadelphia, PA 19126

E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	305	Classroom 305	W2	Plaster	White	None	0	24.3	Positive
1	3	305	Classroom 305	W3	Plaster	White	Cracking	50	22.4	Positive
1	3	305	Classroom 305	W4	Plaster	White	Flaking	100	0.1	Negative
1	3	305	Classroom 305	Ceiling	Plaster	White	Alligatoring	400	26.3	Positive
1	3	305	Classroom 305	Radiator	Metal	Grey	Chipping	10	0.18	Negative
1	3	304	Classroom 304	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	W1	Plaster	White	Cracking	15	0.08	Negative
1	3	304	Classroom 304	W2	Plaster	White	None	0	17.2	Positive
1	3	304	Classroom 304	W3	Plaster	White	None	0	19.3	Positive
1	3	304	Classroom 304	W4	Plaster	White	None	0	24.1	Positive
1	3	304	Classroom 304	Ceiling	Plaster	White	Alligatoring	200	26.2	Positive
1	3	304	Classroom 304	Radiator	Metal	Grey	Chipping	10	0.04	Negative
1	3	303	Classroom 303	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W1	Plaster	White	None	0	22.1	Positive
1	3	303	Classroom 303	W2	Plaster	White	None	0	24.7	Positive
1	3	303	Classroom 303	W3	Plaster	White	None	0	31.1	Positive
1	3	303	Classroom 303	W4	Plaster	White	None	0	28.6	Positive
1	3	303	Classroom 303	Ceiling	Plaster	White	Alligatoring	400	24.4	Positive
1	3	303	Classroom 303	Radiator	Metal	Grey	Chipping	10	0.5	Negative
1	3	326	Classroom 326	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	326	Classroom 326	W1	Plaster	Blue	None	0	18.9	Positive
1	3	326	Classroom 326	W2	CMU	Blue	None	0	0	Negative
1	3	326	Classroom 326	W3	Plaster	Blue	None	0	21.2	Positive
1	3	326	Classroom 326	W4	Plaster	Blue	None	0	23.6	Positive
1	3	326	Classroom 326	Ceiling	Plaster	White	Alligatoring	200	24.7	Positive
1	3	326	Classroom 326	Radiator	Metal	Grey	Chipping	10	0.02	Negative
1	3	302	Classroom 302	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W1	Plaster	White	Flaking	100	24	Positive
1	3	302	Classroom 302	W2	Sheetrock	White	Flaking	100	0.01	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	302	Classroom 302	W3	Plaster	White	Cracking	50	23.9	Positive
1	3	302	Classroom 302	W4	Sheetrock	White	Flaking	25	0.01	Negative
1	3	302	Classroom 302	Ceiling	Plaster	White	Alligatoring	100	34	Positive
1	3	302	Classroom 302	Radiator	Metal	Grey	Chipping	10	0.14	Negative
1	3	301	Classroom 301	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	W1	Plaster	White	None	0	20.4	Positive
1	3	301	Classroom 301	W2	Plaster	White	None	0	31.2	Positive
1	3	301	Classroom 301	W3	Plaster	White	None	0	28.7	Positive
1	3	301	Classroom 301	W4	Plaster	White	None	0	23.1	Positive
1	3	301	Classroom 301	Ceiling	Plaster	White	Alligatoring	200	25.3	Positive
1	3	301	Classroom 301	Radiator	Metal	Grey	Chipping	10	0.24	Negative
1	3	322A	Men's Restroom adjacent to Classroom 322	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	322A	Men's Restroom adjacent to Classroom 322	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	322A	Men's Restroom adjacent to Classroom 322	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	322A	Men's Restroom adjacent to Classroom 322	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	322A	Men's Restroom adjacent to Classroom 322	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	322A	Men's Restroom adjacent to Classroom 322	Ceiling	Plaster	White	Alligatoring	50	24.3	Positive
1	3	322A	Men's Restroom adjacent to Classroom 322	Radiator	Metal	Grey	Chipping	5	0.11	Negative
1	3	322	Classroom 322	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	322	Classroom 322	W1	Plaster	White	Cracking	15	20.4	Positive
1	3	322	Classroom 322	W2	Plaster	White	Cracking	20	26.9	Positive
1	3	322	Classroom 322	W3	Plaster	White	Cracking	100	23	Positive
1	3	322	Classroom 322	W4	Plaster	White	Cracking	50	25.2	Positive
1	3	322	Classroom 322	Ceiling	Plaster	White	Alligatoring	400	27.1	Positive
1	3	322	Classroom 322	Radiator	Metal	Grey	Chipping	10	0.01	Negative
1	3	321	Classroom 321	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	321	Classroom 321	W1	Plaster	White	Cracking	5	22.4	Positive
1	3	321	Classroom 321	W2	Plaster	White	Cracking	10	21	Positive
1	3	321	Classroom 321	W3	Plaster	White	Efflorescence	100	21.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	M	P	P	X	X
l	l	p	n	o	u	u	o	o	R	R
e	o	a	e	o	o	o	o	o	e	e
m	r	c	r	n	n	n	n	n	d	d
e	e	e	e	e	e	e	e	e	a	a
n	n	n	n	n	n	n	n	n	m	m
t	t	t	t	t	t	t	t	t	g	g
1	3	321	Classroom 321	W4	Plaster	White	None	0	24.3	Positive
1	3	321	Classroom 321	Ceiling	Plaster	White	Alligatoring	400	26.3	Positive
1	3	321	Classroom 321	Radiator	Metal	Grey	Chipping	10	0.4	Negative
1	3	320	Classroom 320	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	320	Classroom 320	W1	Plaster	White	None	0	26.3	Positive
1	3	320	Classroom 320	W2	Plaster	White	Flaking	5	29.5	Positive
1	3	320	Classroom 320	W3	Plaster	White	Cracking	200	3.5	Positive
1	3	320	Classroom 320	W4	Plaster	White	Cracking	50	28.9	Positive
1	3	320	Classroom 320	Ceiling	Plaster	White	Alligatoring	300	29.1	Positive
1	3	320	Classroom 320	Radiator	Metal	Grey	Chipping	10	0.3	Negative
1	3	319	Classroom 319	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	319	Classroom 319	W1	Plaster	White	Cracking	5	20	Positive
1	3	319	Classroom 319	W2	Plaster	White	None	0	21.3	Positive
1	3	319	Classroom 319	W3	Plaster	White	Chipping	200	22.4	Positive
1	3	319	Classroom 319	W4	Plaster	White	None	0	29.1	Positive
1	3	319	Classroom 319	Ceiling	Plaster	White	Alligatoring	400	31.6	Positive
1	3	319	Classroom 319	Radiator	Metal	Grey	Chipping	10	0.28	Negative
1	3	318A	Storage across from Classroom 318	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	318A	Storage across from Classroom 318	W1	Plaster	White	Flaking	15	21.2	Positive
1	3	318A	Storage across from Classroom 318	W2	Plaster	White	Chipping	10	25.2	Positive
1	3	318A	Storage across from Classroom 318	W3	Plaster	White	Cracking	10	21.7	Positive
1	3	318A	Storage across from Classroom 318	W4	Plaster	White	None	0	23.5	Positive
1	3	318A	Storage across from Classroom 318	Ceiling	Plaster	White	Alligatoring	50	24.3	Positive
1	3	318A	Storage across from Classroom 318	Radiator	Metal	Grey	Chipping	10	0.29	Negative
1	3	317	Classroom 317	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	317	Classroom 317	W1	Plaster	White	Chipping	20	22.7	Positive
1	3	317	Classroom 317	W2	Plaster	White	Flaking	5	13.7	Positive
1	3	317	Classroom 317	W3	Plaster	White	Chipping	20	19.6	Positive
1	3	317	Classroom 317	W4	Plaster	White	Chipping	5	18.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	M	P	D	P	X
l	l	p	n	e	u	a	a	e	o	R
e	o	a	r	r	o	o	o	r	u	e
m	r	c	e	o	m	n	n	d	q	r
e	e	s	s	n	e	e	e	a	a	e
n	n	o	o	n	n	n	n	m	m	n
t	t	o	n	e	e	e	n	en	en	t
o	o	o	o	n	n	n	n	t	t	o
r	r	o	o	n	n	n	n	o	o	o
o	o	o	o	n	n	n	n	n	n	n
u	u	u	u	n	n	n	n	n	n	n
n	n	n	n	n	n	n	n	n	n	n
t	t	t	t	n	n	n	n	n	n	n
o	o	o	o	n	n	n	n	n	n	n
u	u	u	u	n	n	n	n	n	n	n
1	3	317	Classroom 317	Ceiling	Plaster	White	Alligating	400	35.9	Positive
1	3	317	Classroom 317	Radiator	Metal	Grey	Chipping	10	0.3	Negative
1	3	316	Classroom 316	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	316	Classroom 316	W1	Plaster	White	Chipping	10	22.2	Positive
1	3	316	Classroom 316	W2	Plaster	White	Flaking	30	16.3	Positive
1	3	316	Classroom 316	W3	Plaster	White	Flaking	5	2.3	Positive
1	3	316	Classroom 316	W4	Plaster	White	None	0	18.7	Positive
1	3	316	Classroom 316	Ceiling	Plaster	White	Alligating	400	25.9	Positive
1	3	316	Classroom 316	Radiator	Metal	Grey	Chipping	10	0.02	Negative
1	3	315	Classroom 315	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	315	Classroom 315	W1	Plaster	White	None	0	31.2	Positive
1	3	315	Classroom 315	W2	Plaster	White	Cracking	5	25.2	Positive
1	3	315	Classroom 315	W3	Plaster	White	None	0	26.1	Positive
1	3	315	Classroom 315	W4	Plaster	White	Chipping	15	16.8	Positive
1	3	315	Classroom 315	Ceiling	Plaster	White	Alligating	400	35.5	Positive
1	3	315	Classroom 315	Radiator	Metal	Grey	Chipping	10	0.01	Negative
1	3	314	Classroom 314	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	314	Classroom 314	W1	Plaster	White	None	0	18.6	Positive
1	3	314	Classroom 314	W2	Plaster	White	None	0	21.2	Positive
1	3	314	Classroom 314	W3	Plaster	White	None	0	24.1	Positive
1	3	314	Classroom 314	W4	Plaster	White	None	0	22.9	Positive
1	3	314	Classroom 314	Ceiling	Plaster	White	Alligating	200	28.9	Positive
1	3	314	Classroom 314	Radiator	Metal	Grey	Chipping	5	0.01	Negative
1	3	324	Classroom 324	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324	Classroom 324	W1	Plaster	Tan	Cracking	100	21.4	Positive
1	3	324	Classroom 324	W1	CMU	White	None	0	0	Negative
1	3	324	Classroom 324	W2	CMU	White	None	0	0.02	Negative
1	3	324	Classroom 324	W3	Plaster	White	Flaking	150	20.1	Positive
1	3	324	Classroom 324	W4	Plaster	White	Cracking	20	25.7	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	3	324	Classroom 324	Radiator	Metal	Grey	Chipping	30	0.16	Negative	
1	3	324	Classroom 324	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A	
1	3	313	Classroom 313	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	3	313	Classroom 313	W1	Plaster	White	Cracking	50	19.4	Positive	
1	3	313	Classroom 313	W2	Sheetrock	White	Cracking	15	0.03	Negative	
1	3	313	Classroom 313	W3	Plaster	White	Chipping	50	16.9	Positive	
1	3	313	Classroom 313	W4	Sheetrock	White	Chipping	50	0.01	Negative	
1	3	313	Classroom 313	Ceiling	Plaster	White	Alligating	400	25.5	Positive	
1	3	313	Classroom 313	Radiator	Metal	Grey	Chipping	10	0.13	Negative	
1	3	312	Classroom 312	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	3	312	Classroom 312	W1	Plaster	White	None	0	21.1	Positive	
1	3	312	Classroom 312	W2	Plaster	White	None	0	24.3	Positive	
1	3	312	Classroom 312	W3	Plaster	White	None	0	25.1	Positive	
1	3	312	Classroom 312	W4	Plaster	White	None	0	22.3	Positive	
1	3	312	Classroom 312	Ceiling	Plaster	White	Alligating	400	29.4	Positive	
1	3	312	Classroom 312	Radiator	Metal	Grey	Chipping	10	0.4	Negative	
1	2	219	Classroom 219	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	2	219	Classroom 219	W1	Plaster	White	None	0	15.2	Positive	
1	2	219	Classroom 219	W2	Plaster	White	None	0	16.2	Positive	
1	2	219	Classroom 219	W3	Plaster	White	Chipping	5	29	Positive	
1	2	219	Classroom 219	W4	Plaster	White	Chipping	5	25.5	Positive	
1	2	219	Classroom 219	Ceiling	Plaster	White	Cracking	50	25.6	Positive	
1	2	219	Classroom 219	Radiator	Metal	Grey	Chipping	5	0.27	Negative	
1	2	220	Classroom 220	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	2	220	Classroom 220	W1	Plaster	White	Chipping	15	21.1	Positive	
1	2	220	Classroom 220	W2	Plaster	White	Cracking	5	25.6	Positive	
1	2	220	Classroom 220	W3	Plaster	White	Efflorescence	150	19.1	Positive	
1	2	220	Classroom 220	W4	Plaster	White	Cracking	10	19.1	Positive	

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	R	R
e	o	o	o	o	o	o	s	o	e	e
n	r	o	o	o	o	o	s	o	e	e
t	r	o	o	o	o	o	s	o	e	e
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	220	Classroom 220	Ceiling	Plaster	White	Flaking	200	22.3	Positive
1	2	220	Classroom 220	Radiator	Metal	Green	Chipping	10	0.3	Negative
1	2	222	Classroom 222	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	222	Classroom 222	W1	Plaster	White	Chipping	5	19.9	Positive
1	2	222	Classroom 222	W2	Plaster	White	None	0	22.1	Positive
1	2	222	Classroom 222	W3	Plaster	White	None	0	24.6	Positive
1	2	222	Classroom 222	W4	Plaster	White	None	0	21.2	Positive
1	2	222	Classroom 222	Ceiling	Plaster	White	Alligatoring	400	29.4	Positive
1	2	222	Classroom 222	Radiator	Metal	Grey	Chipping	10	0.03	Negative
1	2	201	Classroom 201	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W1	Plaster	Blue	Chipping	5	25.1	Positive
1	2	201	Classroom 201	W2	Plaster	Blue	None	0	24.2	Positive
1	2	201	Classroom 201	W3	Plaster	Blue	Cracking	50	19.5	Positive
1	2	201	Classroom 201	W4	Plaster	Blue	Chipping	15	15.6	Positive
1	2	201	Classroom 201	Ceiling	Plaster	White	None	0	25.4	Positive
1	2	201	Classroom 201	Radiator	Metal	Grey	Chipping	10	0.01	Negative
1	2	S26	Stairwell next to Classroom 226	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	S26	Stairwell next to Classroom 226	Hand Rail	Metal	Brown	Chipping	10	0	Negative
1	2	S26	Stairwell next to Classroom 226	W1	Plaster	White	None	0	8.2	Positive
1	2	S26	Stairwell next to Classroom 226	W2	Plaster	White	None	0	5.3	Positive
1	2	S26	Stairwell next to Classroom 226	W3	Plaster	White	None	0	10.2	Positive
1	2	S26	Stairwell next to Classroom 226	W4	Plaster	White	None	0	11.2	Positive
1	2	S26	Stairwell next to Classroom 226	Ceiling	Concrete	White	None	0	0.01	Negative
1	2	S26	Stairwell next to Classroom 226	Stair Tread	Concrete	Grey	Chipping	15	2.1	Positive
1	2	S26	Stairwell next to Classroom 226	Stair Riser	Concrete	Grey	Chipping	15	8.1	Positive
1	2	S26	Stairwell next to Classroom 226	Newel Post	Metal	Brown	Chipping	5	4	Positive
1	2	S26	Stairwell next to Classroom 226	Stringer	Concrete	Brown	Cracking	1	5.6	Positive
1	2	S26	Stairwell next to Classroom 226	Radiator	Metal	Brown	Chipping	15	3.3	Positive
1	2	H28	Hallway from Classrooms 201 to 203	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	R
l	l	o	n	o	u	o	e	o	R	F
e	o	o	o	o	o	o	s	o	o	o
n	r	o	o	o	o	o	s	o	o	o
t	o	o	o	o	o	o	s	o	o	o
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	H28	Hallway from Classrooms 201 to 203	W2	Plaster	White	Chipping	5	22.3	Positive
1	2	H28	Hallway from Classrooms 201 to 203	W4	Plaster	White	Chipping	5	21.8	Positive
1	2	H28	Hallway from Classrooms 201 to 203	Ceiling	Plaster	White	Alligatoring	400	14.2	Positive
1	2	224	Computer Classroom 224	Radiator	Metal	Grey	Flaking	15	1.2	Positive
1	2	225	Classroom 225	Radiator	Metal	Grey	Chipping	1	0.02	Negative
1	2	H27	Hallway from Classroom 204 to Classroom 209	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	H27	Hallway from Classroom 204 to Classroom 209	W1	Plaster	White	None	0	20.4	Positive
1	2	H27	Hallway from Classroom 204 to Classroom 209	W2	Plaster	White	None	0	12.5	Positive
1	2	H27	Hallway from Classroom 204 to Classroom 209	W3	Plaster	White	None	0	26.1	Positive
1	2	H27	Hallway from Classroom 204 to Classroom 209	W4	Plaster	White	Cracking	50	22.8	Positive
1	2	H27	Hallway from Classroom 204 to Classroom 209	Ceiling	Plaster	Tan	Chipping	500	20.7	Positive
1	2	H27	Hallway from Classroom 204 to Classroom 209	Radiator	Metal	Brown	Flaking	20	3.4	Positive
1	2	211A	1st Office to Right in Vice Principal's Suites	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	211A	1st Office to Right in Vice Principal's Suites	W1	Metal	Green	None	0	0.02	Negative
1	2	211A	1st Office to Right in Vice Principal's Suites	W2	Plaster	Green	Flaking	50	22.6	Positive
1	2	211A	1st Office to Right in Vice Principal's Suites	W3	Plaster	Green	Cracking	25	25.7	Positive
1	2	211A	1st Office to Right in Vice Principal's Suites	W4	Sheetrock	Green	Cracking	10	0.01	Negative
1	2	211A	1st Office to Right in Vice Principal's Suites	Ceiling	Plaster	White	Alligatoring	50	22.4	Positive
1	2	211A	1st Office to Right in Vice Principal's Suites	Radiator	Metal	Grey	Chipping	5	0.22	Negative
1	2	S28	Stairwell across from Classroom 214	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	S28	Stairwell across from Classroom 214	Hand Rail	Metal	Brown	Chipping	5	0.02	Negative
1	2	S28	Stairwell across from Classroom 214	W1	Plaster	White	None	0	12.1	Positive
1	2	S28	Stairwell across from Classroom 214	W2	Plaster	White	None	0	8.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S28	Stairwell across from Classroom 214	W3	Plaster	White	None	0	5.2	Positive
1	2	S28	Stairwell across from Classroom 214	W4	Plaster	White	None	0	23.1	Positive
1	2	S28	Stairwell across from Classroom 214	Ceiling	Concrete	White	None	0	0	Negative
1	2	S28	Stairwell across from Classroom 214	Stair Tread	Concrete	Grey	Chipping	15	4.6	Positive
1	2	S28	Stairwell across from Classroom 214	Stair Riser	Concrete	Grey	Chipping	15	7.7	Positive
1	2	S28	Stairwell across from Classroom 214	Newel Post	Metal	Brown	Chipping	5	5.3	Positive
1	2	S28	Stairwell across from Classroom 214	Door Frame	Metal	Brown	Chipping	5	3.7	Positive
1	2	H26	Hallway from Classrooms 214 to 212	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	H26	Hallway from Classrooms 214 to 212	W1	Plaster	White	None	0	27.3	Positive
1	2	H26	Hallway from Classrooms 214 to 212	W2	Plaster	White	Chipping	50	23.7	Positive
1	2	H26	Hallway from Classrooms 214 to 212	W3	Plaster	White	None	0	19.3	Positive
1	2	H26	Hallway from Classrooms 214 to 212	W4	Plaster	White	Chipping	50	20.7	Positive
1	2	H26	Hallway from Classrooms 214 to 212	Ceiling	Plaster	White	None	0	20.4	Positive
1	2	H26	Hallway from Classrooms 214 to 212	Radiator	Metal	Brown	Chipping	30	4	Positive
1	2	214A	Women's Restroom next to Classroom 215	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	214A	Women's Restroom next to Classroom 215	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	214A	Women's Restroom next to Classroom 215	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	214A	Women's Restroom next to Classroom 215	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	214A	Women's Restroom next to Classroom 215	W4	Plaster	White	Chipping	1	19.5	Positive
1	2	214A	Women's Restroom next to Classroom 215	Ceiling	Plaster	White	Chipping	100	30.1	Positive
1	2	215	Classroom 215	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	215	Classroom 215	W1	Plaster	White	Friction	1	31.2	Positive
1	2	215	Classroom 215	W2	Plaster	White	Friction	2	34.2	Positive
1	2	208D	Main Office	Vent	Metal	Grey	Chipping	5	27.1	Positive
1	2	208D	Main Office	Radiator	Metal	Grey	Chipping	1	3.2	Positive
1	2	215	Classroom 215	W3	Plaster	White	Flaking	4	20.2	Positive
1	2	215	Classroom 215	W4	Plaster	White	Flaking	5	24.1	Positive
1	2	215	Classroom 215	Ceiling	Plaster	White	Alligatoring	200	35.8	Positive
1	2	215	Classroom 215	Radiator	Metal	Grey	Flaking	5	0.02	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F									
l	l	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
e	o									
n	o									
t	r									
1	2	216	Classroom 216	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	216	Classroom 216	W1	Plaster	White	Friction	3	23.7	Positive
1	2	216	Classroom 216	W2	Plaster	White	None	0	19.3	Positive
1	2	216	Classroom 216	W3	Plaster	White	Efflorescence	20	20.8	Positive
1	2	216	Classroom 216	W4	Plaster	White	None	0	20.5	Positive
1	2	216	Classroom 216	Ceiling	Plaster	White	Alligatoring	400	29.3	Positive
1	2	216	Classroom 216	Radiator	Metal	Grey	Flaking	4	0.01	Negative
1	2	217	Classroom 217	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	217	Classroom 217	W1	Plaster	White	Chipping	7	13.5	Positive
1	2	217	Classroom 217	W2	Plaster	White	Chipping	2	28.3	Positive
1	2	217	Classroom 217	W3	Plaster	White	Chipping	20	19.6	Positive
1	2	217	Classroom 217	W4	Plaster	White	Chipping	2	25.5	Positive
1	2	217	Classroom 217	Ceiling	Plaster	White	Alligatoring	200	27.6	Positive
1	2	217	Classroom 217	Radiator	Metal	Grey	Flaking	10	0.03	Negative
1	2	218	Classroom 218	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	218	Classroom 218	W1	Plaster	White	Chipping	1	24.8	Positive
1	2	218	Classroom 218	W2	Plaster	White	Friction	1	27	Positive
1	2	218	Classroom 218	W3	Plaster	White	Efflorescence	7	18.5	Positive
1	2	218	Classroom 218	W4	Plaster	White	None	0	24.8	Positive
1	2	218	Classroom 218	Ceiling	Plaster	White	Alligatoring	200	24.7	Positive
1	2	218	Classroom 218	Radiator	Metal	Grey	Flaking	3	0.26	Negative
1	2	221	Classroom 221	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	221	Classroom 221	W1	Plaster	Blue	Cracking	100	26.3	Positive
1	2	221	Classroom 221	W2	Plaster	Blue	Cracking	10	24.1	Positive
1	2	221	Classroom 221	W3	Plaster	Blue	Efflorescence	100	16.2	Positive
1	2	221	Classroom 221	W4	Plaster	Blue	Cracking	10	19.6	Positive
1	2	221	Classroom 221	Ceiling	Plaster	White	Chipping	50	25.6	Positive
1	2	221	Classroom 221	Radiator	Metal	Grey	Chipping	10	0.29	Negative
1	2	222A	Men's Restroom next to Classroom 222	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E	F	S	O	C	S	P	D	P	X	X	
l	l	p	n	o	u	o	e	o	R	R	
e	o	a	e	m	o	u	s	u	e	e	
m	r	c	r	e	u	s	e	q	d	(
e		#	N	C	S	C	D	Q	R	p	
n			a	o	u	o	e	a	e	s	
t			m	m	m	m	s	m	m	i	
1	2	222A	Men's Restroom next to Classroom 222	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	222A	Men's Restroom next to Classroom 222	W1	Plaster	White	None	0	18.2	Positive	
1	2	222A	Men's Restroom next to Classroom 222	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	222A	Men's Restroom next to Classroom 222	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	222A	Men's Restroom next to Classroom 222	Ceiling	Plaster	White	Flaking	50	24.2	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	H25	Hallway from Classrooms 215 to 221	W1	Plaster	White	None	0	24.5	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	W2	Plaster	White	Flaking	50	19.9	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	W3	Plaster	White	None	0	18.3	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	W4	Plaster	White	Flaking	50	25.7	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	Ceiling	Plaster	White	Cracking	300	21.9	Positive	
1	2	H25	Hallway from Classrooms 215 to 221	Radiator	Metal	Brown	Chipping	20	6.3	Positive	
1	2	S25	Stairwell across from Classroom 201	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	S25	Stairwell across from Classroom 201	Hand Rail	Metal	Brown	Chipping	5	0.05	Negative	
1	2	S25	Stairwell across from Classroom 201	W1	Plaster	White	None	0	12.3	Positive	
1	2	S25	Stairwell across from Classroom 201	W2	Plaster	White	None	0	14.5	Positive	
1	2	S25	Stairwell across from Classroom 201	W3	Plaster	White	None	0	10.1	Positive	
1	2	S25	Stairwell across from Classroom 201	W4	Plaster	White	Chipping	1	26.9	Positive	
1	2	S25	Stairwell across from Classroom 201	Ceiling	Concrete	White	None	0	0.02	Negative	
1	2	224	Computer Classroom 224	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	224	Computer Classroom 224	W1	Plaster	White	None	0	28	Positive	
1	2	224	Computer Classroom 224	W2	CMU	White	None	0	0.09	Negative	
1	2	224	Computer Classroom 224	W3	Plaster	White	None	0	24	Positive	
1	2	224	Computer Classroom 224	W4	Plaster	White	None	0	28.9	Positive	
1	2	224	Computer Classroom 224	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	224A	Boy's Restroom next to Classroom 225	Floor	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	224A	Boy's Restroom next to Classroom 225	W1	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	224A	Boy's Restroom next to Classroom 225	W2	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	224A	Boy's Restroom next to Classroom 225	W3	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A	

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	a	R	R
e	o	o	e	o	o	o	s	m	e	e
n	r	o	r	n	n	n	e	e	n	n
t		#	N	C	M	C	D	Q	R	(
			a	O	S	P	e	a	e	+
			m	n	u	o	s	m	n	-
			e	n	o	n	e	n	e)
			r	e	n	e	n	e	n	e
			n	n	e	n	e	n	e	n
			e	n	e	n	e	n	e	n
1	2	224A	Boy's Restroom next to Classroom 225	W4	Ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224A	Boy's Restroom next to Classroom 225	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	225	Classroom 225	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225	Classroom 225	W1	Plaster	White	None	0	18.3	Positive
1	2	225	Classroom 225	W2	Plaster	White	None	0	19.2	Positive
1	2	225	Classroom 225	W3	Plaster	White	None	0	20.5	Positive
1	2	225	Classroom 225	W4	CMU	White	None	0	0.02	Negative
1	2	225	Classroom 225	Ceiling	Plaster	White	Alligatoring	200	23.4	Positive
1	2	S25	Stairwell across from Classroom 201	Stair Tread	Concrete	Grey	Flaking	15	9.4	Positive
1	2	S25	Stairwell across from Classroom 201	Riser	Concrete	Grey	Flaking	15	7.7	Positive
1	2	S25	Stairwell across from Classroom 201	Newel Post	Metal	Brown	Chipping	2	4.4	Positive
1	2	S25	Stairwell across from Classroom 201	Stringer	Concrete	Brown	Cracking	1	5.1	Positive
1	2	S25	Stairwell across from Classroom 201	Door Frame	Metal	Brown	Chipping	5	6.9	Positive
1	2	S25	Stairwell across from Classroom 201	Radiator	Metal	Grey	Chipping	10	10.1	Positive
1	2	203	Classroom 203	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	Plaster	White	Chipping	5	21.5	Positive
1	2	203	Classroom 203	W2	Plaster	White	None	0	14.3	Positive
1	2	203	Classroom 203	W3	Plaster	White	None	0	12.6	Positive
1	2	203	Classroom 203	W4	Plaster	White	None	0	18	Positive
1	2	203	Classroom 203	Ceiling	Plaster	White	Alligatoring	200	23.4	Positive
1	2	203	Classroom 203	Radiator	Metal	Grey	Chipping	10	0.3	Negative
1	2	204	Classroom 204	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	W1	Plaster	White	None	0	24.2	Positive
1	2	204	Classroom 204	W2	Plaster	White	None	0	20.3	Positive
1	2	204	Classroom 204	W3	Plaster	White	None	0	18.4	Positive
1	2	204	Classroom 204	W4	Plaster	White	None	0	19.2	Positive
1	2	204	Classroom 204	Ceiling	Plaster	White	Cracking	50	18.7	Positive
1	2	204	Classroom 204	Radiator	Metal	Grey	Chipping	10	0.21	Negative
1	2	208D	Main Office	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	h	n	o	u	o	e	o	r	r
e	o	o	o	o	o	o	o	o	o	o
n	r	o	o	o	o	o	o	o	o	o
t		#	N	C	M	C	D	Q	R	(
			a	o	a	o	e	a	e	+
			m	o	m	o	n	m	m	-
			e	o	a	o	n	a	a)
			n	o	m	o	n	a	a)
			e	o	m	o	n	a	a)
1	2	208D	Main Office	W1	Plaster	Green	Cracking	2	27.6	Positive
1	2	212	Classroom 212	Radiator	Metal	Grey	Chipping	5	0.11	Negative
1	2	208D	Main Office	W2	Plaster	Blue	None	0	22.5	Positive
1	2	208D	Main Office	W3	Plaster	Blue	None	0	24.5	Positive
1	2	208D	Main Office	W4	Plaster	Blue	None	0	26.1	Positive
1	2	208D	Main Office	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	Floor	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	W1	Plaster	White	None	0	18.2	Positive
1	2	S215	Stairwell to Main Lobby next to Main Office	W1	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	W2	Plaster	White	None	0	22.4	Positive
1	2	S215	Stairwell to Main Lobby next to Main Office	W2	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	W3	Plaster	White	None	0	21.6	Positive
1	2	S215	Stairwell to Main Lobby next to Main Office	W3	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S215	Stairwell to Main Lobby next to Main Office	W4	Plaster	White	None	0	17.9	Positive
1	2	S215	Stairwell to Main Lobby next to Main Office	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	S214	Stairwell to Main Lobby next to Classroom 209	Floor	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W1	Plaster	White	None	0	20.5	Positive
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W1	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W2	Plaster	White	None	0	29.1	Positive
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W2	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W3	Plaster	White	None	0	10.5	Positive
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W3	Marble	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W4	Plaster	White	None	0	18.5	Positive
1	2	S214	Stairwell to Main Lobby next to Classroom 209	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	2	S214	Stairwell to Main Lobby next to Classroom 209	Ceiling	Plaster	White	None	0	18.2	Positive
1	2	212	Classroom 212	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	212	Classroom 212	W1	Plaster	White	None	0	22.8	Positive
1	2	212	Classroom 212	W2	Plaster	White	Chipping	3	27.1	Positive
1	2	214	Classroom 214	Radiator	Metal	Grey	Chipping	5	0.3	Negative
1	2	212	Classroom 212	W3	Plaster	White	Chipping	3	14.7	Positive
1	2	212	Classroom 212	W4	Plaster	White	Chipping	3	0	Negative
1	2	212	Classroom 212	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	223	Dean's Office 223	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	223	Dean's Office 223	W1	Plaster	White	None	0	20.6	Positive
1	2	223	Dean's Office 223	W2	Plaster	White	None	0	23.2	Positive
1	2	223	Dean's Office 223	W3	Plaster	White	None	0	8	Positive
1	2	223	Dean's Office 223	W4	CMU	White	None	0	0.14	Negative
1	2	223	Dean's Office 223	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	223	Dean's Office 223	Radiator	Metal	Grey	Flaking	5	0.8	Positive
1	2	213	Classroom 213	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	213	Classroom 213	W1	Plaster	White	None	0	20.6	Positive
1	2	213	Classroom 213	W2	Plaster	White	None	0	12.5	Positive
1	2	213	Classroom 213	W3	Plaster	White	Cracking	5	10.8	Positive
1	2	213	Classroom 213	W4	Plaster	White	None	0	18.4	Positive
1	2	213	Classroom 213	Ceiling	Plaster	White	None	0	19.8	Positive
1	2	213	Classroom 213	Radiator	Metal	Grey	Flaking	2	0.07	Negative
1	2	213	Classroom 213	Pipe	Metal	White	Chipping	2	0.01	Negative
1	2	214	Classroom 214	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	r	r
e	o	o	o	o	o	o	s	o	o	o
m	r	o	o	o	o	o	s	o	o	o
n	r	o	o	o	o	o	s	o	o	o
t	r	o	o	o	o	o	s	o	o	o
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	214	Classroom 214	W1	Plaster	White	Chipping	1	25.4	Positive
1	2	214	Classroom 214	W2	Plaster	White	Chipping	2	27.7	Positive
1	2	214	Classroom 214	W3	Plaster	Blue	Chipping	2	22.4	Positive
1	2	214	Classroom 214	W4	Plaster	Blue	Flaking	10	0.02	Negative
1	2	214	Classroom 214	Ceiling	Plaster	White	Alligatoring	50	36	Positive
1	1	106AA	Teacher's' Lounge Break Room	Radiator	Metal	Grey	Chipping	5	1	Positive
1	1	106AA	Teacher's' Lounge Break Room Window Storage	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	106AA	Teacher's' Lounge Break Room Window Storage	W1	Plaster	Green	Cracking	50	12.9	Positive
1	1	106AA	Teacher's' Lounge Break Room Window Storage	W2	Plaster	Green	Flaking	5	12.7	Positive
1	1	106AA	Teacher's' Lounge Break Room Window Storage	W3	Plaster	Green	Cracking	25	10.1	Positive
1	1	106AA	Teacher's' Lounge Break Room Window Storage	W4	Plaster	Green	Cracking	15	10.1	Positive
1	1	106AA	Teacher's' Lounge Break Room Window Storage	Ceiling	Plaster	White	None	0	13.3	Positive
1	1	106AB	Teacher's' Lounge Break Room Storage Room	W1	Plaster	Green	None	0	12.2	Positive
1	1	106AB	Teacher's' Lounge Break Room Storage Room	W2	Plaster	Green	Cracking	5	10.1	Positive
1	1	106AB	Teacher's' Lounge Break Room Storage Room	W3	Plaster	Green	Cracking	25	8	Positive
1	1	106AB	Teacher's' Lounge Break Room Storage Room	W4	Plaster	Green	Cracking	10	10.1	Positive
1	1	106AB	Teacher's' Lounge Break Room Storage Room	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	106AB	Teacher's' Lounge Break Room Storage Room	Ceiling	Plaster	White	None	0	10.2	Positive
1	1	106	Storage Room 106 (Former Kitchen)	Radiator	Metal	Grey	Chipping	10	16.9	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	105	Classroom 105	Radiator	Metal	Grey	Chipping	15	0.8	Positive
1	1	126	Girl's Restroom next to Weight Room 110	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126	Girl's Restroom next to Weight Room 110	Ceiling	Plaster	White	Chipping	7	13.5	Positive
1	1	126	Girl's Restroom next to Weight Room 110	Radiator	Metal	Grey	Chipping	5	0.1	Negative
1	1	127	Women's Restroom across from Auditorium	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	127	Women's Restroom across from Auditorium	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	127	Women's Restroom across from Auditorium	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	127	Women's Restroom across from Auditorium	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	128	Storage Closet next to Main Lobby near Classroom 104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	128	Storage Closet next to Main Lobby near Classroom 104	W1	Plaster	White	Cracking	2	5.5	Positive
1	1	128	Storage Closet next to Main Lobby near Classroom 104	W2	Plaster	White	Cracking	5	9	Positive
1	1	128	Storage Closet next to Main Lobby near Classroom 104	W4	Plaster	White	Cracking	5	8.2	Positive
1	1	128	Storage Closet next to Main Lobby near Classroom 104	Ceiling	Plaster	White	None	0	22.4	Positive
1	1	127	Women's Restroom across from Auditorium	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	127	Women's Restroom across from Auditorium	Ceiling	Plaster	White	None	0	25.6	Positive
1	1	127	Women's Restroom across from Auditorium	Pipe	Metal	White	Chipping	1	12.7	Positive
1	1	129	Men's Restroom across from Auditorium	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	129	Men's Restroom across from Auditorium	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	129	Men's Restroom across from Auditorium	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	129	Men's Restroom across from Auditorium	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	129	Men's Restroom across from Auditorium	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	129	Men's Restroom across from Auditorium	Ceiling	Plaster	White	None	0	28.2	Positive
1	1	100A	Auditorium	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	100A	Auditorium	W1	Plaster	Yellow	Chipping	13	0	Negative
1	1	100A	Auditorium	W2	Plaster	Yellow	Friction	3	0	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	100A	Auditorium	W3	Plaster	Yellow	Chipping	2	0	Negative
1	1	100A	Auditorium	W4	Plaster	Yellow	Chipping	1	0	Negative
1	1	100A	Auditorium	Ceiling	Plaster	White	No Access	No Access	No Access	No Access
1	1	100A(Stage)	Auditorium Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	100A(Stage)	Auditorium Stage	W2	Plaster	Yellow	Friction	1	10.1	Positive
1	1	100A(Stage)	Auditorium Stage	W3	Plaster	Yellow	Friction	3	12.1	Positive
1	1	100A(Stage)	Auditorium Stage	W4	Plaster	Yellow	None	0	18.3	Positive
1	1	100A(Stage)	Auditorium Stage	Ceiling	Plaster	Yellow	None	0	20.8	Positive
1	1	101A	Office 101A	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101A	Office 101A	W1	Sheetrock	Tan	Friction	2	0	Negative
1	1	101A	Office 101A	W2	Brick	White	None	0	1.2	Positive
1	1	101A	Office 101A	W3	Brick	White	Chipping	1	1.6	Positive
1	1	101A	Office 101A	W4	Brick	White	Chipping	2	1	Positive
1	1	101A	Office 101A	Ceiling	Plaster	White	Alligating	50	18.9	Positive
1	1	101A	Office 101A	Radiator	Metal	Grey	Chipping	2	0.18	Negative
1	1	101B	Office 101B	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101B	Office 101B	W1	Sheetrock	Tan	Friction	1	0	Negative
1	1	101B	Office 101B	W2	Brick	White	Chipping	2	2	Positive
1	1	101B	Office 101B	W3	Brick	White	Chipping	1	1.5	Positive
1	1	101B	Office 101B	W4	Brick	White	Friction	1	1.5	Positive
1	1	101B	Office 101B	Ceiling	Plaster	White	Alligating	50	14.4	Positive
1	1	101B-1	Office 101B Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	101B-1	Office 101B Closet	W1	Brick	Grey	None	0	1.3	Positive
1	1	101B-1	Office 101B Closet	W2	Brick	Tan	None	0	1.1	Positive
1	1	101B-1	Office 101B Closet	W3	Brick	White	None	0	1.6	Positive
1	1	101B-1	Office 101B Closet	W4	Brick	White	None	0	1.4	Positive
1	1	101B-1	Office 101B Closet	Ceiling	Plaster	White	None	0	11.9	Positive
1	1	102A	Classroom 102 Closet	Floor	Wood	Unpainted	Chipping	15	0.04	Negative
1	1	102A	Classroom 102 Closet	W1	Brick	White	None	0	1.5	Positive

			<p>Dates: 10/24/22-11/15/22 1/4/23-1/5/23</p> <p>Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)</p> <p>Inspection Company: Viva EHS</p>								<p>Lead-Safe Certification Assessment Report</p> <p>General Louis Wagner Middle School (6-8)</p> <p>1701 West Cheltenham Avenue, Philadelphia, PA 19126</p>									
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)										
1	1	102A	Classroom 102 Closet	W2	Brick	Tan	Flaking	15	2.8	Positive										
1	1	102A	Classroom 102 Closet	W3	Brick	White	None	0	1.3	Positive										
1	1	102A	Classroom 102 Closet	W4	Brick	White	None	0	1.2	Positive										
1	1	102A	Classroom 102 Closet	Ceiling	Concrete	White	None	0	0.02	Negative										
1	1	102A	Classroom 102 Closet	Radiator	Metal	Grey	Chipping	10	0.02	Negative										
1	1	104A	Storage Closet Connected to Main Hallway	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A										
1	1	104A	Storage Closet Connected to Main Hallway	W1	Plaster	White	Cracking	3	11.6	Positive										
1	1	104A	Storage Closet Connected to Main Hallway	W2	Plaster	White	Cracking	5	9.3	Positive										
1	1	104A	Storage Closet Connected to Main Hallway	W3	Plaster	White	Chipping	1	8.7	Positive										
1	1	104A	Storage Closet Connected to Main Hallway	W4	Plaster	White	Cracking	5	7.1	Positive										
1	1	104A	Storage Closet Connected to Main Hallway	Ceiling	Plaster	White	Chipping	2	4.7	Positive										
1	1	104B	Storage Closet across from Classroom/Storage 103	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A										
1	1	104B	Storage Closet across from Classroom/Storage 103	W1	Plaster	White	None	0	11.7	Positive										
1	1	104B	Storage Closet across from Classroom/Storage 103	W2	CMU	White	None	0	0	Negative										
1	1	104B	Storage Closet across from Classroom/Storage 103	W3	Plaster	White	None	0	19.2	Positive										
1	1	104B	Storage Closet across from Classroom/Storage 103	W4	Plaster	White	None	0	13.6	Positive										
1	1	104B	Storage Closet across from Classroom/Storage 103	Ceiling	Spline Tile	Unpainted	N/A	N/A	N/A	N/A										
1	1	104C	Classroom 104 Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A										
1	1	104C	Classroom 104 Closet	W1	Brick	Yellow	Chipping	1	1.3	Positive										
1	1	104C	Classroom 104 Closet	W1	Brick	White	Chipping	1	1.6	Positive										
1	1	104C	Classroom 104 Closet	W1	CMU	Black	None	0	0	Negative										
1	1	104C	Classroom 104 Closet	W1	Brick	Black	None	0	0.3	Negative										
1	1	104C	Classroom 104 Closet	W2	Brick	Yellow	None	0	0.19	Negative										
1	1	104C	Classroom 104 Closet	W2	Brick	White	None	0	0.6	Negative										

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	S	D	P	X	X
l	l	o	o	o	o	o	e	a	R	R
e	o	o	o	o	o	o	s	q	e	e
n	r	#	n	m	m	m	d	a	r	(
t			a	e	e	e	s	m	e	+
			m	n	n	n	c	n	n	-
			e	e	e	e	d	n	n)
			n	n	n	n	s	n	n	
1	1	104C	Classroom 104 Closet	W3	CMU	Yellow	None	0	0	Negative
1	1	104C	Classroom 104 Closet	W3	CMU	White	None	0	0	Negative
1	1	104C	Classroom 104 Closet	W3	Brick	Black	Chipping	2	0.29	Negative
1	1	104C	Classroom 104 Closet	W4	CMU	Black	None	0	0	Negative
1	1	104C	Classroom 104 Closet	W4	CMU	Yellow	None	0	0	Negative
1	1	104C	Classroom 104 Closet	W4	CMU	White	None	0	0	Negative
1	1	104C	Classroom 104 Closet	Ceiling	Plaster	White	None	0	24.3	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	104D	Classroom 104 Storage Closet with Windows	W1	Brick	White	Chipping	2	0.4	Negative
1	1	104D	Classroom 104 Storage Closet with Windows	W1	Brick	Yellow	Chipping	1	0.2	Negative
1	1	104D	Classroom 104 Storage Closet with Windows	W2	CMU	White	None	0	0.02	Negative
1	1	104D	Classroom 104 Storage Closet with Windows	W2	CMU	Yellow	None	0	0.04	Negative
1	1	104D	Classroom 104 Storage Closet with Windows	W3	Brick	White	Chipping	3	2	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	W3	Brick	Yellow	Chipping	1	1.7	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	W4	Brick	White	Chipping	3	1.5	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	W4	Brick	Yellow	Chipping	3	1.2	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	Ceiling	Plaster	White	None	0	26.6	Positive
1	1	104D	Classroom 104 Storage Closet with Windows	Radiator	Metal	Grey	Chipping	2	0.2	Negative
1	1	105A	Classroom 105 Window Storage Closet	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	105A	Classroom 105 Window Storage Closet	W1	Plaster	Green	Efflorescence	30	10.1	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	R	R
e	o	o	s	o	o	o	s	o	e	e
m	r	#	n	m	m	m	d	q	r	(
e			a	c	s	c	a	a	e	p
n			s	o	u	o	m	m	n	s
t			e	m	l	l	e	n	t)
1	1	105A	Classroom 105 Window Storage Closet	W2	Plaster	Green	Cracking	15	10.1	Positive
1	1	105A	Classroom 105 Window Storage Closet	W3	Plaster	Green	Cracking	15	7.7	Positive
1	1	105A	Classroom 105 Window Storage Closet	W4	Plaster	Green	None	0	21.1	Positive
1	1	105A	Classroom 105 Window Storage Closet	Ceiling	Plaster	White	Cracking	5	9.6	Positive
1	1	105B	Classroom 105 Window Storage Closet	Floor	9x9 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	105B	Classroom 105 Storage Closet	W1	Plaster	Green	Cracking	25	10.1	Positive
1	1	105B	Classroom 105 Storage Closet	W2	Plaster	Green	Cracking	5	10.1	Positive
1	1	105B	Classroom 105 Storage Closet	W3	Plaster	Green	Cracking	40	8.7	Positive
1	1	105B	Classroom 105 Storage Closet	W4	Plaster	Green	Cracking	25	8	Positive
1	1	105B	Classroom 105 Storage Closet	Ceiling	Plaster	White	Cracking	5	10.1	Positive
1	1	106A	Teacher's' Lounge Break Room	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	106A	Teacher's' Lounge Break Room	W1	Plaster	White	Cracking	100	21.6	Positive
1	1	106A	Teacher's' Lounge Break Room	W2	Plaster	White	Cracking	50	23.9	Positive
1	1	106A	Teacher's' Lounge Break Room	W3	Plaster	White	Cracking	40	25.8	Positive
1	1	106A	Teacher's' Lounge Break Room	W4	Plaster	White	Cracking	50	26.8	Positive
1	1	106A	Teacher's' Lounge Break Room	Ceiling	Plaster	White	Flaking	50	25.9	Positive
1	1	106B	Classroom 106B Music Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	106B	Classroom 106B Music Room	Radiator	Metal	Grey	Chipping	5	17.5	Positive
1	1	106B	Classroom 106B Music Room	W1	Plaster	White	Cracking	50	27.6	Positive
1	1	106B	Classroom 106B Music Room	W2	Plaster	White	Chipping	50	32	Positive
1	1	106B	Classroom 106B Music Room	W3	Plaster	White	Cracking	50	26.5	Positive
1	1	106B	Classroom 106B Music Room	W4	Plaster	White	Cracking	50	15.9	Positive
1	1	106B	Classroom 106B Music Room	Ceiling	Plaster	White	None	0	15.6	Positive
1	1	106B-1	Classroom 106B Music Room Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	106B-1	Classroom 106B Music Room Closet	W1	Plaster	White	Cracking	15	24.6	Positive
1	1	106B-1	Classroom 106B Music Room Closet	W2	Plaster	White	Flaking	5	26	Positive
1	1	106B-1	Classroom 106B Music Room Closet	W3	Plaster	White	Alligatoring	50	25.2	Positive
1	1	106B-1	Classroom 106B Music Room Closet	W4	Plaster	White	Cracking	15	20.2	Positive
1	1	106B-1	Classroom 106B Music Room Closet	Ceiling	Plaster	White	None	0	19.9	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	o	o	u	o	e	o	R	R
e	o	o	o	o	o	o	s	o	o	o
n	o	o	o	o	o	o	s	o	o	o
t	o	o	o	o	o	o	s	o	o	o
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	106B-1	Classroom 106B Music Room Closet	Radiator	Metal	Grey	Chipping	5	7.9	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	Stair Rail	Metal	Grey	Chipping	4	2.6	Positive
1	1	101B	Office 101B	Radiator	Metal	Grey	Chipping	3	0.8	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	1	106C	Storage Room above Gym across from Classroom 106	Stair Tread	Concrete	Grey	None	0	0	Negative
1	1	101B	Office 101B Closet	W1	Brick	Yellow	None	0	1.3	Positive
1	1	101B	Office 101B Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	101B	Office 101B Closet	W2	Brick	Yellow	None	0	1.1	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W1	Plaster	Yellow	Cracking	2	11.6	Positive
1	1	101B	Office 101B Closet	W3	Brick	Yellow	None	0	1	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W1	Concrete	Yellow	Chipping	3	5.1	Positive
1	1	101B	Office 101B Closet	W4	Brick	Yellow	None	0	1.2	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W2	Plaster	Yellow	Efflorescence	20	15.2	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W2	Brick	Yellow	Chipping	30	9.9	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W3	Plaster	Yellow	Chipping	10	9.6	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W3	Brick	Yellow	Chipping	10	5.1	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	W4	Concrete	Tan	Cracking	1	3.3	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	Ceiling	Concrete	Yellow	Cracking	1	3.5	Positive
1	1	106C	Storage Room above Gym across from Classroom 106	Ceiling	Plaster	Yellow	Peeling	5	9.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	106D	Classroom 106 Storage Closet	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	106D	Classroom 106 Storage Closet	W1	Plaster	Blue	Chipping	2	9	Positive
1	1	106D	Classroom 106 Storage Closet	W2	Plaster	Blue	Cracking	2	10.1	Positive
1	1	106D	Classroom 106 Storage Closet	W3	Plaster	Blue	Cracking	4	9.9	Positive
1	1	106D	Classroom 106 Storage Closet	W4	Plaster	Blue	Cracking	3	6.1	Positive
1	1	106D	Classroom 106 Storage Closet	Ceiling	Plaster	White	None	0	20.6	Positive
1	1	107A	Classroom 107 Closet	Floor	12x12 Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107A	Classroom 107 Closet	W1	Plaster	Tan	Cracking	3	10.3	Positive
1	1	107A	Classroom 107 Closet	W2	Plaster	Tan	Cracking	4	11.7	Positive
1	1	107A	Classroom 107 Closet	W3	Plaster	Tan	Cracking	4	11.9	Positive
1	1	107A	Classroom 107 Closet	W4	Plaster	Tan	Cracking	4	14.3	Positive
1	1	107A	Classroom 107 Closet	Ceiling	Plaster	Tan	Efflorescence	1	12.1	Positive
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	W1	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	W2	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	W3	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	W4	CMU Block	Unpainted	N/A	N/A	N/A	N/A
1	1	107BA	Pipe Chase in Custodial Closet across from Classroom 107/108	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	Floor	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	W1	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	W2	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	W3	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	109A	Lobby Entrance next to Teacher's Lounge	Ceiling	Plaster	White	None	0	6.7	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	R	R
e	o	o	e	o	o	o	s	o	e	e
n	r	o	o	o	o	o	o	o	o	o
t	o	o	o	o	o	o	o	o	o	o
		Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	109A	Lobby Entrance next to Teacher's Lounge	Vents	Metal	White	Chipping	3	6.3	Positive
1	1	111A	Boy's Restroom next to Building Engineer's Office	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	111A	Boy's Restroom next to Building Engineer's Office	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	111A	Boy's Restroom next to Building Engineer's Office	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	111A	Boy's Restroom next to Building Engineer's Office	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	111A	Boy's Restroom next to Building Engineer's Office	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	111A	Boy's Restroom next to Building Engineer's Office	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	117A	Hallway above Fan Room	W1	Brick	White	Friction	1	6.7	Positive
1	1	118	Boys' Cafeteria	Radiator	Metal	Grey	Chipping	10	0.7	Positive
1	1	117A	Hallway above Fan Room	W2	Brick	White	Chipping	3	4.5	Positive
1	1	117A	Hallway above Fan Room	W3	Brick	White	Chipping	2	5.1	Positive
1	1	117A	Hallway above Fan Room	W4	Brick	White	Chipping	1	3.3	Positive
1	1	117A	Hallway above Fan Room	Column	Concrete	White	None	0	0	Negative
1	1	117A	Hallway above Fan Room	Ceiling	Plaster	White	None	0	5.5	Positive
1	1	117A	Hallway above Fan Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	118A	Serving Area (Boys' Side)	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	118A	Serving Area (Boys' Side)	W1	CMU	White	None	0	0	Negative
1	1	118A	Serving Area (Boys' Side)	W2	Brick	White	Chipping	1	2.9	Positive
1	1	118A	Serving Area (Boys' Side)	W3	Brick	White	None	0	1.7	Positive
1	1	118A	Serving Area (Boys' Side)	W4	Brick	White	None	0	2.1	Positive
1	1	118A	Serving Area (Boys' Side)	Ceiling	Plaster	White	None	0	12.3	Positive
1	1	118B	Closet next to Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	118B	Closet next to Cafeteria	W1	Plaster	White	Cracking	1	3.4	Positive
1	1	118A	Serving Area (Boys' Side)	Duct	Metal	Tan	Chipping	2	0.5	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	o	R	R
e	o	o	e	o	o	o	s	u	e	e
n	r	o	r	o	o	o	e	q	o	o
t		#	N	C	M	C	D	(o	(
			a	o	a	o	e)	o)
			m	n	t	n	s	o	o	n
			e	e	e	t	d	o	o	e
			r	r	r	r	e	o	o	n
			n	n	n	n	o	o	o	e
			e	e	e	e	o	o	o	e
			s	s	s	s	o	o	o	e
			e	e	e	e	o	o	o	e
			r	r	r	r	o	o	o	e
			n	n	n	n	o	o	o	e
			e	e	e	e	o	o	o	e
			s	s	s	s	o	o	o	e
			e	e	e	e	o	o	o	e
			r	r	r	r	o	o	o	e
			n	n	n	n	o	o	o	e
			e	e	e	e	o	o	o	e
			s	s	s	s	o	o	o	e
			e	e	e	e	o	o	o	e
			r	r	r	r	o	o	o	e
			n	n	n	n	o	o	o	e
1	1	118B	Closet next to Cafeteria	W2	Plaster	White	Chipping	3	8.1	Positive
1	1	118B	Closet next to Cafeteria	W3	Plaster	White	Chipping	11	10.1	Positive
1	1	118B	Closet next to Cafeteria	W4	Plaster	White	Cracking	5	14.8	Positive
1	1	118B	Closet next to Cafeteria	Ceiling	Plaster	White	Chipping	1	16	Positive
1	1	119A	Kitchen Office	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119A	Kitchen Office	W1	Brick	White	None	0	20.2	Positive
1	1	119	Kitchen	Door	Metal	White	Friction	1	0.26	Negative
1	1	119A	Kitchen Office	W2	Brick	White	Chipping	2	11.6	Positive
1	1	119A	Kitchen Office	W3	Brick	White	Chipping	3	10.7	Positive
1	1	119A	Kitchen Office	W4	Brick	White	Chipping	1	11.5	Positive
1	1	119A	Kitchen Office	Ceiling	Plaster	Grey	Chipping	10	12.6	Positive
1	1	119B	Kitchen Locker Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119B	Kitchen Locker Room	W2	Plaster	White	Alligating	1	9.7	Positive
1	1	119B	Kitchen Locker Room	W3	CMU	White	None	0	0.01	Negative
1	1	119B	Kitchen Locker Room	W4	Plaster	Tan	Chipping	7	7.4	Positive
1	1	119B	Kitchen Locker Room	Ceiling	Plaster	Tan	Chipping	2	12.2	Positive
1	1	119B	Kitchen Locker Room	Stringer	Concrete	Red	Chipping	10	2	Positive
1	1	119B	Kitchen Locker Room	Stair Tread	Concrete	Red	Chipping	2	0.2	Negative
1	1	119B	Kitchen Locker Room	Stair Tread	Concrete	Red	Friction	2	0.4	Negative
1	1	119B	Kitchen Locker Room	Stair Railing	Concrete	Red	Chipping	2	1	Positive
1	1	119B	Kitchen Locker Room	Stair Riser	Concrete	Red	Chipping	1	2.4	Positive
1	1	119C	Kitchen Locker Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119C	Kitchen Locker Room	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119C	Kitchen Locker Room	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119C	Kitchen Locker Room	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119C	Kitchen Locker Room	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119C	Kitchen Locker Room	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	119D	Storage Above Kitchen	Floor	Concrete	Grey	Chipping	100	0.4	Negative
1	1	119D	Storage Above Kitchen	W1	Plaster	White	None	0	12.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	119D	Storage Above Kitchen	W2	Brick	White	Chipping	1	14.3	Positive
1	1	119D	Storage Above Kitchen	W3	Brick	White	Chipping	1	4.4	Positive
1	1	119D	Storage Above Kitchen	W4	Brick	White	Chipping	2	0.5	Negative
1	1	119D	Storage Above Kitchen	Ceiling	Concrete	White	Chipping	1	12.9	Positive
1	1	119D	Storage Above Kitchen	Pipe	Metal	White	Chipping	5	8.1	Positive
1	1	119D	Storage Above Kitchen	Radiator	Metal	Grey	Chipping	2	0.01	Negative
1	1	120A	Serving Area (Girls' Side)	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	120A	Serving Area (Girls' Side)	W1	CMU	White	None	0	0.01	Negative
1	1	120A	Serving Area (Girls' Side)	W2	Brick	White	Chipping	1	2.5	Positive
1	1	120A	Serving Area (Girls' Side)	W3	Brick	White	None	0	1.8	Positive
1	1	120A	Serving Area (Girls' Side)	W4	Brick	White	None	0	2.2	Positive
1	1	120A	Serving Area (Girls' Side)	Ceiling	Plaster	White	Flaking	50	20.5	Positive
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	121A	Staff Restroom in Fan Room Balcony near Classroom 109	Ceiling	Plaster	White	Efflorescence	1	5	Positive
1	1	126A	Closet next to Girl's Restroom next to Weight Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Closet next to Girl's Restroom next to Weight Room	W1	Plaster	Tan	Chipping	3	15.5	Positive
1	1	120	Girls' Cafeteria	Radiator	Metal	Grey	Chipping	10	0.9	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	p	n	o	u	o	e	o	r	r
e	o	a	e	m	o	l	s	u	e	e
n	r	c	r	e	n	o	d	q	r	n
t		#	N	C	M	C	D	Q	R	(
			o	o	a	o	e	a	e	p
			n	n	m	l	s	m	m	s
			e	e	a	o	d	g	g)
			r	r	t	l	e	n	n	e
			o	o	n	o	n	t	t	e
			m	m	e	l	e	g	g	n
			e	e	n	o	n	n	n	e
			r	r	a	l	e	t	t	e
1	1	126A	Closet next to Girl's Restroom next to Weight Room	W2	Plaster	Tan	Chipping	2	16.6	Positive
1	1	126A	Closet next to Girl's Restroom next to Weight Room	W3	Plaster	Tan	Cracking	1	13	Positive
1	1	126A	Closet next to Girl's Restroom next to Weight Room	W4	Plaster	Tan	Chipping	5	14.4	Positive
1	1	126A	Closet next to Girl's Restroom next to Weight Room	Ceiling	Plaster	Tan	Chipping	1	13.5	Positive
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	W1	Plaster	White	Cracking	3	12	Positive
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	W2	Plaster	White	Cracking	5	10.1	Positive
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	W3	Plaster	White	Chipping	2	11.7	Positive
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	W4	Plaster	White	Cracking	4	10.1	Positive
1	1	131A	Storage Closet next to Main Lobby near Classroom 105	Ceiling	Plaster	White	Chipping	25	14.7	Positive
1	1	H11	Hallway near Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	H11	Hallway near Building Engineer's Office	W2	Plaster	Blue	Flaking	10	22.4	Positive
1	1	H11	Hallway near Building Engineer's Office	W4	Plaster	Blue	Chipping	5	21.8	Positive
1	1	H11	Hallway near Building Engineer's Office	Ceiling	Plaster	White	None	0	21.1	Positive
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H119	Hallway to adjacent Kitchen Office to 1st Floor Restroom/Locker Room Area	Ceiling	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H12	Hallway at Cafeterias	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H12	Hallway at Cafeterias	W1	Plaster	Blue	None	0	23	Positive
1	1	H12	Hallway at Cafeterias	W2	Plaster	Blue	None	0	25.2	Positive
1	1	H12	Hallway at Cafeterias	W3	Plaster	Blue	None	0	25.4	Positive
1	1	H12	Hallway at Cafeterias	W4	Plaster	Blue	Flaking	50	23.1	Positive
1	1	H12	Hallway at Cafeterias	Ceiling	Plaster	White	None	0	24	Positive
1	1	H12	Hallway at Cafeterias	Radiator	Metal	Grey	Chipping	15	4.2	Positive
1	1	H13	Hallway between Classrooms 109 and 107	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H13	Hallway between Classrooms 109 and 107	W1	Plaster	Blue	None	0	14.5	Positive
1	1	H13	Hallway between Classrooms 109 and 107	W2	Plaster	Blue	None	0	16.3	Positive
1	1	H13	Hallway between Classrooms 109 and 107	W3	Plaster	Blue	None	0	12.2	Positive
1	1	H13	Hallway between Classrooms 109 and 107	W4	Plaster	Blue	None	0	13.9	Positive
1	1	H13	Hallway between Classrooms 109 and 107	Ceiling	Plaster	White	None	0	21.2	Positive
1	1	H14	Hallway from Classrooms 106 to 103	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	H14	Hallway from Classrooms 106 to 103	W1	Plaster	Blue	None	0	18.9	Positive
1	1	H14	Hallway from Classrooms 106 to 103	W2	Plaster	Blue	Chipping	30	24	Positive
1	1	H14	Hallway from Classrooms 106 to 103	W3	Plaster	Blue	None	0	19.5	Positive
1	1	H14	Hallway from Classrooms 106 to 103	W4	Plaster	Blue	Chipping	15	26.6	Positive
1	1	H14	Hallway from Classrooms 106 to 103	Ceiling	Plaster	White	None	0	29.9	Positive
1	1	MEV	Main Entrance Vestibule	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	MEV	Main Entrance Vestibule	Radiator Cover	Metal	White	Chipping	10	2.2	Positive
1	1	MEV	Main Entrance Vestibule	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	MEV	Main Entrance Vestibule	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	M	P	P	X	X
l	l	h	n	o	u	u	o	o	R	R
e	o	o	o	o	o	o	o	o	e	e
m	r	o	n	n	n	n	n	n	d	d
e	o	o	n	n	n	n	n	n	g	g
n	r	o	n	n	n	n	n	n	m	m
t	o	o	n	n	n	n	n	n	g	g
o	r	o	n	n	n	n	n	n	g	g
o	r	o	n	n	n	n	n	n	g	g
r	r	o	n	n	n	n	n	n	m	m
t	r	o	n	n	n	n	n	n	g	g
o	r	o	n	n	n	n	n	n	m	m
r	r	o	n	n	n	n	n	n	g	g
t	r	o	n	n	n	n	n	n	m	m
o	r	o	n	n	n	n	n	n	g	g
r	r	o	n	n	n	n	n	n	m	m
t	r	o	n	n	n	n	n	n	g	g
1	1	MEV	Main Entrance Vestibule	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	MEV	Main Entrance Vestibule	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	MEV	Main Entrance Vestibule	Ceiling	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	S110	Stairwell Left of Auditorium Stage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S110	Stairwell Left of Auditorium Stage	W1	Plaster	Yellow	Friction	1	0	Negative
1	1	S110	Stairwell Left of Auditorium Stage	W2	Plaster	Yellow	Friction	1	0	Negative
1	1	S110	Stairwell Left of Auditorium Stage	W3	Plaster	Yellow	Friction	1	0	Negative
1	1	S110	Stairwell Left of Auditorium Stage	W4	Plaster	Yellow	Friction	1	0	Negative
1	1	S110	Stairwell Left of Auditorium Stage	Ceiling	Plaster	White	Friction	1	0	Negative
1	1	S112	Stairwell Right of Auditorium Stage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S112	Stairwell Right of Auditorium Stage	W1	Plaster	Yellow	Friction	1	0	Negative
1	1	S112	Stairwell Right of Auditorium Stage	W2	Plaster	Yellow	Friction	1	0	Negative
1	1	S112	Stairwell Right of Auditorium Stage	W3	Plaster	Yellow	Friction	1	0	Negative
1	1	S112	Stairwell Right of Auditorium Stage	W4	Plaster	Yellow	Friction	1	0	Negative
1	1	S112	Stairwell Right of Auditorium Stage	Ceiling	Plaster	White	None	0	18.2	Positive
1	1	S15	Stairwell across from Classroom 101	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	S15	Stairwell across from Classroom 101	Hand Rail	Metal	Brown	Chipping	10	0.01	Negative
1	B	1B	Rectangular Boiler Storage Room	Pipe	Metal	Orange	Flaking	20	0	Negative
1	1	S15	Stairwell across from Classroom 101	W1	Plaster	White	None	0	14.5	Positive
1	1	S15	Stairwell across from Classroom 101	W2	Plaster	White	Chipping	10	26.8	Positive
1	1	S15	Stairwell across from Classroom 101	W3	Plaster	White	None	0	19.2	Positive
1	1	S15	Stairwell across from Classroom 101	W4	Plaster	White	None	0	18.2	Positive
1	1	S15	Stairwell across from Classroom 101	Ceiling	Plaster	White	None	0	14.4	Positive
1	1	S15	Stairwell across from Classroom 101	Door Frame	Metal	Brown	Flaking	5	7.3	Positive
1	1	S15	Stairwell across from Classroom 101	Door	Metal	Blue	Chipping	2	0	Negative
1	1	S15	Stairwell across from Classroom 101	Stair Tread	Concrete	Grey	Chipping	10	8.7	Positive
1	1	S15	Stairwell across from Classroom 101	Stair Riser	Concrete	Grey	Chipping	10	9	Positive
1	1	S15	Stairwell across from Classroom 101	Newel Post	Metal	Brown	Chipping	5	6.6	Positive
1	1	S15	Stairwell across from Classroom 101	Stringer	Concrete	Brown	Chipping	5	5.5	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	N	C	S	M	P	X	R
l	l	o	n	e	o	o	o	o	o	o
m	o	o	e	r	n	n	n	n	n	n
e	r	o	r	n	a	a	a	a	a	a
n	o	o	n	a	a	a	a	a	a	a
t	r	o	e	n	n	n	n	n	n	n
Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)		
1	1	S16	Stairwell across from Classroom 102	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	S16	Stairwell across from Classroom 102	Hand Rail	Metal	Brown	Chipping	5	0.1	Negative
1	1	S16	Stairwell across from Classroom 102	W1	Plaster	White	None	0	21.4	Positive
1	1	S16	Stairwell across from Classroom 102	W2	Plaster	White	None	0	21.5	Positive
1	1	S16	Stairwell across from Classroom 102	W3	Plaster	White	None	0	15.4	Positive
1	1	S16	Stairwell across from Classroom 102	W4	Plaster	White	None	0	18	Positive
1	1	S16	Stairwell across from Classroom 102	Ceiling	Plaster	White	None	0	22.1	Positive
1	1	S16	Stairwell across from Classroom 102	Stair Tread	Concrete	Grey	Chipping	15	1.8	Positive
1	1	S16	Stairwell across from Classroom 102	Stair Riser	Concrete	Grey	Chipping	15	10.4	Positive
1	1	S16	Stairwell across from Classroom 102	Stringer	Concrete	Grey	Chipping	2	6.1	Positive
1	1	S16	Stairwell across from Classroom 102	Newel Post	Metal	Brown	Chipping	5	0.2	Negative
1	1	S16	Stairwell across from Classroom 102	Door Frame	Metal	Brown	Chipping	5	6.3	Positive
1	1	S16	Stairwell across from Classroom 102	Door	Metal	Blue	Chipping	1	0	Negative
1	1	S17	Stairwell across from Classroom 107	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	S17	Stairwell across from Classroom 107	Hand Rail	Metal	Brown	Chipping	3	0.2	Negative
1	1	S17	Stairwell across from Classroom 107	W1	Plaster	White	None	0	18.9	Positive
1	1	S17	Stairwell across from Classroom 107	W2	Plaster	White	None	0	20.1	Positive
1	1	S17	Stairwell across from Classroom 107	W3	Plaster	White	None	0	17.7	Positive
1	1	S17	Stairwell across from Classroom 107	W4	Plaster	White	None	0	16.4	Positive
1	1	S17	Stairwell across from Classroom 107	Ceiling	Plaster	White	None	0	17.1	Positive
1	1	S17	Stairwell across from Classroom 107	Stair Tread	Concrete	Grey	Chipping	20	0.05	Negative
1	1	S17	Stairwell across from Classroom 107	Stair Riser	Concrete	Grey	Chipping	20	6.8	Positive
1	1	S17	Stairwell across from Classroom 107	Newel Post	Metal	Brown	Chipping	3	0.2	Negative
1	1	S17	Stairwell across from Classroom 107	Door	Metal	Blue	Chipping	5	0	Negative
1	1	S17	Stairwell across from Classroom 107	Door Frame	Metal	Brown	Chipping	5	6.7	Positive
1	1	S18	Stairwell across from Classroom 109	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	S18	Stairwell across from Classroom 109	W1	Plaster	White	None	0	10.2	Positive
1	1	S18	Stairwell across from Classroom 109	W2	Plaster	White	None	0	20.3	Positive
1	1	S18	Stairwell across from Classroom 109	W3	Plaster	White	None	0	15.3	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S18	Stairwell across from Classroom 109	W4	Plaster	White	None	0	14.4	Positive
1	B	1	Boiler Room	Stair Riser	Concrete	Grey	Chipping	15	20.2	Positive
1	B	1	Boiler Room	Floor	Concrete	Grey	None	0	0	Negative
1	B	1	Boiler Room	Hand Rail	Metal	Grey	Chipping	10	12.9	Positive
1	B	1	Boiler Room	Hand Rail	Metal	Grey	Flaking	10	7.5	Positive
1	B	1	Boiler Room	Stringer	Concrete	White	Cracking	5	0.4	Negative
1	B	1	Boiler Room	Stair Tread	Concrete	Grey	Flaking	30	8.7	Positive
1	B	1	Boiler Room	W1	Brick	Tan	Flaking	100	0	Negative
1	B	1	Boiler Room	W1	Brick	White	Flaking	100	0.02	Negative
1	B	1	Boiler Room	W2	Brick	White	Flaking	20	0.04	Negative
1	B	1	Boiler Room	W2	Concrete	White	Flaking	200	0.05	Negative
1	B	1	Boiler Room	W2	Brick	Tan	Flaking	5	0.03	Negative
1	B	1	Boiler Room	W2	Concrete	Tan	Flaking	500	0.04	Negative
1	B	1	Boiler Room	W3	Concrete	White	None	0	0.01	Negative
1	B	1	Boiler Room	W3	Concrete	Tan	Flaking	200	0	Negative
1	B	1	Boiler Room	W4	Concrete	Tan	Flaking	500	0	Negative
1	B	1	Boiler Room	W4	Concrete	White	None	0	0.1	Negative
1	B	1	Boiler Room	Stair Tread	Metal	Grey	Chipping	10	12	Positive
1	B	1	Boiler Room	Stringer	Metal	Grey	Flaking	5	14.6	Positive
1	B	1	Boiler Room	Column 1	Concrete	White	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 1	Concrete	Tan	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 2	Concrete	White	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 2	Concrete	Tan	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 3	Concrete	White	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 3	Concrete	Tan	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 4	Concrete	White	Flaking	10	0	Negative
1	B	1	Boiler Room	Column 4	Concrete	Tan	Flaking	10	0	Negative
1	B	1	Boiler Room	Ceiling	Concrete	White	Flaking	500	1.2	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	S	D	P	X	X
l	l	p	n	o	u	u	e	a	r	r
e	o	a	e	m	o	o	s	m	e	e
n	r	c	r	e	n	n	e	e	n	n
t	o	e	o	n	e	e	d	q	r	e
o	r	s	n	o	n	n	e	u	e	n
m	e	p	a	n	e	e	s	a	n	n
e	n	a	n	e	n	e	e	m	t	e
n	t	c	e	n	e	e	s	e	n	n
t	o	e	n	e	n	e	e	n	t	e
o	r	s	a	n	e	e	s	a	n	n
n	o	c	a	n	e	e	s	a	n	n
t	o	e	n	e	n	e	s	a	n	n
1	B	1A	Emergency Generator Room (Former Ash Room)	Hand Rail	Metal	Red	Chipping	5	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	1A	Emergency Generator Room (Former Ash Room)	W1	Concrete	White	None	0	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W1	Concrete	Tan	None	0	0.01	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W2	Concrete	White	Flaking	100	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W2	Concrete	Tan	Flaking	100	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W3	Concrete	White	Flaking	25	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W3	Concrete	Tan	Flaking	25	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W4	Concrete	White	None	0	0.03	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	W4	Concrete	Tan	Cracking	100	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	Ceiling	Concrete	White	Cracking	100	1.4	Positive
1	B	1A	Emergency Generator Room (Former Ash Room)	Column	Concrete	Tan	Flaking	10	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	Column	Concrete	White	Flaking	10	0	Negative
1	B	1A	Emergency Generator Room (Former Ash Room)	Stringer	Metal	Red	Flaking	5	0	Negative
1	B	1B	Rectangular Boiler Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	1B	Rectangular Boiler Storage Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	1B	Rectangular Boiler Storage Room	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	1B	Rectangular Boiler Storage Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	1B	Rectangular Boiler Storage Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	1B	Rectangular Boiler Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	16	Electrical Room adjacent to Boiler Room	Floor	Concrete	Grey	Spalling	500	0.02	Negative
1	B	16	Electrical Room adjacent to Boiler Room	Stair Riser	Concrete	Grey	Chipping	15	19.7	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W1	Brick	Tan	Chipping	15	1.2	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W1	Brick	White	Cracking	5	1.4	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W2	Concrete	Tan	Cracking	100	19.5	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W2	Concrete	White	Chipping	5	1.4	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W3	Brick	Tan	None	0	3.3	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W3	Brick	White	None	0	2.2	Positive
1	B	16	Electrical Room adjacent to Boiler Room	W4	Brick	Tan	Chipping	50	0.09	Negative
1	B	16	Electrical Room adjacent to Boiler Room	W4	Brick	White	Chipping	200	0.02	Negative
1	B	16	Electrical Room adjacent to Boiler Room	Column	Concrete	White	Cracking	10	8.7	Positive
1	B	16	Electrical Room adjacent to Boiler Room	Column	Concrete	Tan	Flaking	15	9	Positive
1	B	16	Electrical Room adjacent to Boiler Room	Stair Tread	Concrete	Grey	Chipping	15	25.8	Positive
1	B	16	Electrical Room adjacent to Boiler Room	Ceiling	Concrete	White	Cracking	200	1.1	Positive
1	B	16A	Electrical Room Staff Restroom	Floor	Concrete	Grey	Chipping	20	0.06	Negative
1	B	16A	Electrical Room Staff Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	16A	Electrical Room Staff Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	16A	Electrical Room Staff Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	16A	Electrical Room Staff Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	16A	Electrical Room Staff Restroom	Ceiling	Concrete	Tan	None	0	0.03	Negative
1	B	16A	Electrical Room Staff Restroom	Pipe	Metal	Tan	Cracking	2	0.28	Negative
1	B	003A	Fan Room near Girl's Gym	Floor	Concrete	Grey	Cracking	150	1.6	Positive
1	B	003A	Fan Room near Girl's Gym	W1	Brick	White	None	0	1.9	Positive
1	B	003A	Fan Room near Girl's Gym	W2	Brick	White	None	0	3.4	Positive
1	B	003A	Fan Room near Girl's Gym	W3	Concrete	White	None	0	0.01	Negative
1	B	003A	Fan Room near Girl's Gym	W4	Brick	White	None	0	3.8	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F									
l	l	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
e	o									
n	o									
t	r									
1	B	003A	Fan Room near Girl's Gym	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	003A	Fan Room near Girl's Gym	Stringer	Concrete	White	Cracking	15	15.2	Positive
1	B	003A	Fan Room near Girl's Gym	Stair Tread	Concrete	Grey	Chipping	5	2.5	Positive
1	B	003A	Fan Room near Girl's Gym	Stair Riser	Concrete	Grey	Cracking	5	13.3	Positive
1	B	003A	Fan Room near Girl's Gym	Hand Rail	Metal	Grey	Chipping	5	6.2	Positive
1	1	S18	Stairwell across from Classroom 109	Ceiling	Plaster	White	None	0	12.1	Positive
1	B	15	Fan Room near Boiler Room	Floor	Concrete	Grey	Flaking	500	0.09	Negative
1	B	15	Fan Room near Boiler Room	W1	Brick	White	Cracking	60	0.4	Negative
1	B	15	Fan Room near Boiler Room	W2	Brick	White	Spalling	40	2.8	Positive
1	B	15	Fan Room near Boiler Room	W3	Brick	White	Flaking	25	3.1	Positive
1	B	15	Fan Room near Boiler Room	W3	Concrete	Grey	Flaking	100	1.5	Positive
1	B	15	Fan Room near Boiler Room	W3	Concrete	White	Flaking	300	1.7	Positive
1	B	15	Fan Room near Boiler Room	W4	Concrete	White	Flaking	150	1.8	Positive
1	B	15	Fan Room near Boiler Room	Fan Unit	Metal	Grey	None	0	0	Negative
1	B	15	Fan Room near Boiler Room	Column	Concrete	White	None	0	0.01	Negative
1	B	15	Fan Room near Boiler Room	Ceiling	Concrete	White	Flaking	50	1.2	Positive
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	W1	Concrete	White	Chipping	15	0.05	Negative
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	W1	Brick	White	Chipping	150	0.04	Negative
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	W2	Brick	White	None	0	2.1	Positive
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	W3	Concrete	White	Flaking	300	0	Negative
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	W4	Brick	White	None	0	1.7	Positive
1	B	001B	Stair Ramp to Fan Room adjacent to Boiler Room	Ceiling	Concrete	White	Flaking	50	0.03	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F									
l	l	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
e	o									
m	o									
e	r									
n										
t										
1	B	3	Boy's Gymnasium	Floor	Rubber	Unpainted	N/A	N/A	N/A	N/A
1	B	3	Boy's Gymnasium	W1	Brick	White	None	0	1.3	Positive
1	B	3	Boy's Gymnasium	W2	Brick	White	None	0	2.4	Positive
1	B	3	Boy's Gymnasium	W3	Brick	White	None	0	1.8	Positive
1	B	3	Boy's Gymnasium	W4	Brick	White	None	0	1.9	Positive
1	B	3	Boy's Gymnasium	Ceiling	Concrete	White	None	0	0.03	Negative
1	B	3	Boy's Gymnasium	Radiator	Metal	Grey	Chipping	60	0.06	Negative
1	B	3	Boy's Gymnasium	Door	Metal	Orange	Flaking	5	0.03	Negative
1	B	8	Storage Closet in Far Corner of Boy's Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	8	Storage Closet in Far Corner of Boy's Gym	W1	Brick	Tan	Chipping	100	3.4	Positive
1	B	8	Storage Closet in Far Corner of Boy's Gym	W2	Brick	White	Chipping	20	2.2	Positive
1	B	8	Storage Closet in Far Corner of Boy's Gym	W3	Concrete	White	Flaking	150	4	Positive
1	B	8	Storage Closet in Far Corner of Boy's Gym	W4	Brick	White	Chipping	20	2.4	Positive
1	B	8	Storage Closet in Far Corner of Boy's Gym	Ceiling	Concrete	White	Flaking	75	4.3	Positive
1	B	8A	Boy's Gymnasium Restroom	Floor	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8A	Boy's Gymnasium Restroom	W1	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8A	Boy's Gymnasium Restroom	W2	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8A	Boy's Gymnasium Restroom	W3	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8A	Boy's Gymnasium Restroom	W4	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8A	Boy's Gymnasium Restroom	Ceiling	Plaster	White	Efflorescence	50	20.6	Positive
1	B	8A	Boy's Gymnasium Restroom	Radiator	Metal	Grey	Chipping	5	0.08	Negative
1	B	8B	Boy's Gym Teacher's Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	8B	Boy's Gym Teacher's Office	W1	Plaster	White	Cracking	100	15.2	Positive
1	B	8B	Boy's Gym Teacher's Office	W2	Plaster	White	Efflorescence	50	17.6	Positive
1	B	8B	Boy's Gym Teacher's Office	W3	Plaster	White	Flaking	50	17	Positive
1	B	8B	Boy's Gym Teacher's Office	W4	Plaster	White	Chipping	100	15.2	Positive
1	B	8B	Boy's Gym Teacher's Office	Ceiling	Concrete	White	None	0	0.02	Negative
1	B	8B	Boy's Gym Teacher's Office	Radiator	Metal	Grey	Chipping	5	0.1	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	S	O	C	S	P	D	P	X	X
l	l	o	n	o	u	o	e	a	R	R
e	o	o	e	o	o	o	s	m	e	e
n	r	o	r	o	o	o	e	e	n	n
t		#	N	C	M	C	D	Q	R	(
			o	o	a	o	e	a	e	+
			n	o	n	o	s	m	n	-
			e	o	n	o	e	n	e)
			r	o	n	o	s	m	n)
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	Ceiling	Concrete	White	None	0	0.02	Negative
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	Stair Tread	Concrete	Grey	Flaking	20	4.5	Positive
1	B	S03	Stairwell to Gymnasium next to Boy's Restroom	Stair Riser	Concrete	Grey	Flaking	20	9.3	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	W1	Brick	White	None	0	1.2	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	W2	Brick	White	None	0	2.2	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	W3	Brick	White	None	0	1.9	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	W4	Brick	White	None	0	2.8	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Stair Riser	Concrete	Grey	Flaking	100	4.1	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Stair Tread	Concrete	Grey	Flaking	100	4.4	Positive

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23		Lead-Safe Certification Assessment Report					
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)		General Louis Wagner Middle School (6-8)					
			Inspection Company: Viva EHS		1701 West Cheltenham Avenue, Philadelphia, PA 19126					
E	F	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Stringer	Concrete	Brown	Flaking	50	4.9	Positive
1	B	S04	Stairwell to Gymnasium next to Upper Boy's Locker Room	Pipe	Metal	Tan	Flaking	5	0.21	Negative
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	12	Storage Closet next to Boy's Gym Stairwell near Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	W1	Brick	White	None	0	1.2	Positive
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	W2	Brick	White	None	0	2.1	Positive
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	W3	Brick	White	None	0	1.1	Positive
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	W4	Brick	White	None	0	1.8	Positive
1	B	13	Boy's Gymnasium Locker Rooms/Restroom	Ceiling	Concrete	White	None	0	0.02	Negative
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	W1	Brick	White	None	0	1.2	Positive
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	W2	Brick	White	None	0	1.8	Positive
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	W3	Concrete	White	None	0	0.03	Negative

			Dates: 10/24/22-11/15/22 1/4/23-1/5/23	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erik Swanson (006917), Eli Tillman (007035)	General Louis Wagner Middle School (6-8)						
			Inspection Company: Viva EHS	1701 West Cheltenham Avenue, Philadelphia, PA 19126						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Paint Damage	Paint Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	W4	Concrete	White	None	0	0	Negative
1	B	3A	Boy's Gymnasium Center Right Storage Closet (Rear)	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	3B	Boy's Gymnasium Center Storage Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	3B	Boy's Gymnasium Center Storage Closet	W1	Plaster	White	Flaking	150	17.5	Positive
1	B	3B	Boy's Gymnasium Center Storage Closet	W2	Plaster	White	Chipping	20	21.5	Positive
1	B	3B	Boy's Gymnasium Center Storage Closet	W3	Plaster	White	Cracking	10	21.3	Positive
1	B	3B	Boy's Gymnasium Center Storage Closet	W4	Plaster	White	Cracking	10	21.9	Positive
1	B	3B	Boy's Gymnasium Center Storage Closet	Ceiling	Plaster	White	Efflorescence	100	No Access	No Access