

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	100	Storage Room 100	W1	Brick	Green	None	0	10.7	Positive
1	1	100	Storage Room 100	W2	Brick	Green	None	0	12.8	Positive
1	1	100	Storage Room 100	W3	Brick	Green	None	0	5.9	Positive
1	1	100	Storage Room 100	W4	Sheetrock	Green	None	0	0	Negative
1	1	100	Storage Room 100	Ceiling	Plaster	White	Flaking	75	18.9	Positive
1	1	101	Classroom 101	Floor	Concrete	Brown	None	0	0.05	Negative
1	1	101	Classroom 101	W1	Brick	Green	Chipping	2	13	Positive
1	1	101	Classroom 101	W2	Sheetrock	Green	None	0	0	Negative
1	1	101	Classroom 101	W3	Brick	Green	None	0	8.4	Positive
1	1	101	Classroom 101	W4	Brick	Green	None	0	12	Positive
1	1	101	Classroom 101	Ceiling	Plaster	White	Chipping	50	18.7	Positive
1	1	101R	Classroom 101 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101R	Classroom 101 Closet	W1	Brick	Tan	None	0	0.02	Negative
1	1	101R	Classroom 101 Closet	W2	Brick	Tan	None	0	0.05	Negative
1	1	101R	Classroom 101 Closet	W3	Brick	Tan	None	0	0.21	Negative
1	1	101R	Classroom 101 Closet	W4	Brick	Tan	None	0	0.09	Negative
1	1	101R	Classroom 101 Closet	Ceiling	Plaster	White	None	0	20.9	Positive
1	1	102	Classroom 102	Floor	Concrete	Black	None	0	0.04	Negative
1	1	102	Classroom 102	W1	Brick	Black	None	0	7	Positive
1	1	102	Classroom 102	W2	Brick	Black	None	0	2.6	Positive
1	1	102	Classroom 102	W3	Brick	Black	None	0	4	Positive
1	1	102	Classroom 102	W4	Brick	Black	None	0	3.1	Positive
1	1	102	Classroom 102	Ceiling	Plaster	White	Flaking	60	17	Positive
1	1	102C	Classroom 102 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102C	Classroom 102 Closet	W1	Brick	Tan	Chipping	2	0.7	Positive
1	1	102C	Classroom 102 Closet	W2	Brick	Tan	Cracking	1	0.01	Negative
1	1	102C	Classroom 102 Closet	W3	Brick	Tan	Cracking	4	0.08	Negative
1	1	102C	Classroom 102 Closet	W4	Brick	Tan	Flaking	1	0.04	Negative
1	1	102C	Classroom 102 Closet	Ceiling	Plaster	White	Moisture Damage	5	16.7	Positive
1	1	100Q	Building Engineer Closet across Room 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100Q	Building Engineer Closet across Room 100	W1	Plaster	Tan	None	0	8.5	Positive
1	1	100Q	Building Engineer Closet across Room 100	W2	Plaster	Tan	None	0	8.2	Positive
1	1	100Q	Building Engineer Closet across Room 100	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100Q	Building Engineer Closet across Room 100	W4	Plaster	Tan	None	0	4.7	Positive
1	1	100Q	Building Engineer Closet across Room 100	Ceiling	Plaster	White	None	0	0	Negative
1	1	101Q	Custodial Closet across Room 100	Floor	Concrete	N/A	N/A	0	0	N/A
1	1	101Q	Custodial Closet across Room 100	W1	Plaster	Tan	Alligating	15	14.8	Positive
1	1	101Q	Custodial Closet across Room 100	W2	Plaster	Tan	Chipping	10	14.3	Positive
1	1	101Q	Custodial Closet across Room 100	W3	Plaster	Tan	Alligating	7	18.1	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	101Q	Custodial Closet across Room 100	W4	Plaster	Tan	Chipping	12	14.2	Positive
1	1	101Q	Custodial Closet across Room 100	Ceiling	Plaster	White	None	0	14.5	Positive
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC101Q	Pipe Chase in Custodial Closet across Room 100	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102B	Boy's Restroom	Floor	Concrete	Grey	Friction	20	0.06	Negative
1	1	102B	Boy's Restroom	W1	Plaster	Green	Chipping	2	14.6	Positive
1	1	102B	Boy's Restroom	W2	Plaster	Green	Cracking	5	13.7	Positive
1	1	102B	Boy's Restroom	W3	Plaster	Green	Cracking	10	4.3	Positive
1	1	102B	Boy's Restroom	W4	Plaster	Green	Chipping	3	11.7	Positive
1	1	102B	Boy's Restroom	Ceiling	Plaster	White	Flaking	100	18.1	Positive
1	1	101B	Girl's Locker Room 101B	Floor	Metal	Brown	Cracking	10	0	Negative
1	1	101B	Girl's Locker Room 101B	W1	Brick	Green	None	0	4.2	Positive
1	1	101B	Girl's Locker Room 101B	W2	Sheetrock	Green	None	0	0	Negative
1	1	101B	Girl's Locker Room 101B	W3	Brick	Green	None	0	4.8	Positive
1	1	101B	Girl's Locker Room 101B	W4	Brick	Green	None	0	0.17	Negative
1	1	101B	Girl's Locker Room 101B	Ceiling	Plaster	White	None	0	16.6	Positive
1	1	101A	Classroom 101A	Floor	Metal	Brown	Friction	10	0	Negative
1	1	101A	Classroom 101A	W1	Brick	Green	Flaking	25	3.5	Positive
1	1	101A	Classroom 101A	W2	Brick	Green	None	0	0.4	Negative
1	1	101A	Classroom 101A	W3	Brick	Green	None	0	3.4	Positive
1	1	101A	Classroom 101A	W4	Sheetrock	Green	None	0	0	Negative
1	1	101A	Classroom 101A	Ceiling	Plaster	White	None	0	12.1	Positive
1	1	102Q	Closet across Classroom 102	Floor	Concrete	N/A	N/A	0	0	N/A
1	1	102Q	Closet across Classroom 102	W1	Sheetrock	Tan	None	0	0	Negative
1	1	102Q	Closet across Classroom 102	W2	Brick	Tan	None	0	3.9	Positive
1	1	102Q	Closet across Classroom 102	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	102Q	Closet across Classroom 102	W4	Brick	Tan	None	0	4	Positive
1	1	102Q	Closet across Classroom 102	Ceiling	Plaster	White	None	0	17	Positive
1	1	104B	Storage Room 104B	Floor	Wood	Brown	Friction	60	0	Negative
1	1	104B	Storage Room 104B	W1	Brick	Yellow	None	0	2.5	Positive
1	1	104B	Storage Room 104B	W2	Brick	Yellow	None	0	2.8	Positive
1	1	104B	Storage Room 104B	W3	Sheetrock	Yellow	None	0	0	Negative
1	1	104B	Storage Room 104B	W4	Brick	Yellow	None	0	2.2	Positive
1	1	104B	Storage Room 104B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104A	Storage Room 104A	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	104A	Storage Room 104A	W1	Brick	Yellow	None	0	0.4	Negative
1	1	104A	Storage Room 104A	W2	Brick	Yellow	None	0	3.4	Positive
1	1	104A	Storage Room 104A	W3	Sheetrock	Yellow	None	0	0	Negative
1	1	104A	Storage Room 104A	W4	Brick	Yellow	None	0	0.11	Negative
1	1	104A	Storage Room 104A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	104D	Storage closet in Storage Room 104A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104D	Storage closet in Storage Room 104A	W1	Brick	Yellow	None	0	0.09	Negative
1	1	104D	Storage closet in Storage Room 104A	W2	Brick	Yellow	None	0	0.11	Negative
1	1	104D	Storage closet in Storage Room 104A	W3	Brick	Yellow	None	0	0.12	Negative
1	1	104D	Storage closet in Storage Room 104A	W4	Brick	Yellow	None	0	0.05	Negative
1	1	104D	Storage closet in Storage Room 104A	Ceiling	Concrete	Yellow	None	0	0	Negative
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	W1	Sheetrock	Green/White	None	0	0	Negative
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	W2	Sheetrock	Green/White	None	0	0	Negative
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	W3	Sheetrock	Green/White	None	0	0	Negative
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	W4	Sheetrock	Green/White	None	0	0	Negative
1	1	103Q	Hallway between the entrances Storage Rooms 104A and 104B	Ceiling	Plaster	Yellow	Chipping	25	25.8	Positive
1	1	105C	Building Engineer Storage across from 104B	Floor	Concrete	N/A	N/A	0	0	N/A
1	1	105C	Building Engineer Storage across from 104B	W1	Brick	Yellow	None	0	0.09	Negative
1	1	105C	Building Engineer Storage across from 104B	W2	Brick	Yellow	None	0	0.06	Negative
1	1	105C	Building Engineer Storage across from 104B	W3	Brick	Yellow	None	0	0.03	Negative
1	1	105C	Building Engineer Storage across from 104B	W4	Brick	Yellow	None	0	0.04	Negative
1	1	105C	Building Engineer Storage across from 104B	Ceiling	Concrete	Yellow	None	0	0.04	Negative
1	1	105D	Storage closet next Building Engineer Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105D	Storage closet next Building Engineer Storage	W1	Concrete	Yellow	N/A	N/A	N/A	N/A
1	1	105D	Storage closet next Building Engineer Storage	W2	Brick	Yellow	None	0	0.14	Negative
1	1	105D	Storage closet next Building Engineer Storage	W3	Brick	Yellow	None	0	0.18	Negative
1	1	105D	Storage closet next Building Engineer Storage	W4	Brick	Yellow	None	0	0.14	Negative
1	1	105D	Storage closet next Building Engineer Storage	Ceiling	Concrete	Yellow	None	0	0.12	Negative
1	1	105	MYA Main Office Room 105	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	MYA Main Office Room 105	W1	Brick	Green	None	0	0.09	Negative
1	1	105	MYA Main Office Room 105	W2	Sheetrock	Blue	None	0	0	Negative
1	1	105	MYA Main Office Room 105	W3	Brick	Green	None	0	0.13	Negative
1	1	105	MYA Main Office Room 105	W4	Brick	Green	None	0	0	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	105	MYA Main Office Room 105	Ceiling	Plaster	White	Flaking	30	24.6	Positive
1	1	105Q	Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105Q	Principal's Office	W1	Brick	Tan	None	0	2.7	Positive
1	1	105Q	Principal's Office	W2	Brick	Tan	None	0	0.7	Positive
1	1	105Q	Principal's Office	W3	Sheetrock	Tan	None	0	0	Negative
1	1	105Q	Principal's Office	W4	Brick	Tan	None	0	0	Negative
1	1	105Q	Principal's Office	Ceiling	Plaster	White	Flaking	50	21.9	Positive
1	1	105S	Principal's Office Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105S	Principal's Office Closet	W1	Brick	Green	None	0	0.08	Negative
1	1	105S	Principal's Office Closet	W2	Brick	Green	None	0	0.12	Negative
1	1	105S	Principal's Office Closet	W3	Brick	Green	None	0	0.1	Negative
1	1	105S	Principal's Office Closet	W4	Brick	Green	None	0	0.04	Negative
1	1	105S	Principal's Office Closet	Ceiling	Concrete	Green	Cracking	25	11.7	Positive
1	1	105R	Principal's Office Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105R	Principal's Office Restroom	W1	Plaster	Green	Cracking	10	11.7	Positive
1	1	105R	Principal's Office Restroom	W2	Plaster	Green	None	0	16.3	Positive
1	1	105R	Principal's Office Restroom	W3	Plaster	Green	None	0	11	Positive
1	1	105R	Principal's Office Restroom	W4	Plaster	Green	None	0	9.3	Positive
1	1	105R	Principal's Office Restroom	Ceiling	Plaster	Tan	Cracking	10	18.9	Positive
1	1	104C	Men's Restroom near Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104C	Men's Restroom near Main Office	W1	Plaster	Green	Moisture Damage	25	21.7	Positive
1	1	104C	Men's Restroom near Main Office	W2	Plaster	Green	Cracking	5	17.7	Positive
1	1	104C	Men's Restroom near Main Office	W3	Plaster	Green	Cracking	8	10.1	Positive
1	1	104C	Men's Restroom near Main Office	W4	Plaster	Green	Cracking	20	15.5	Positive
1	1	104C	Men's Restroom near Main Office	Ceiling	Plaster	Green	Cracking	15	16	Positive
1	1	104Q	Hallway leading to 104B Men's Restroom	Floor	Concrete	N/A	N/A	0	0	Negative
1	1	104Q	Hallway leading to 104B Men's Restroom	W1	Plaster	Green	None	0	17.4	Positive
1	1	104Q	Hallway leading to 104B Men's Restroom	W2	Plaster	Green	None	0	11.7	Positive
1	1	104Q	Hallway leading to 104B Men's Restroom	W3	Plaster	Green	None	0	16	Positive
1	1	104Q	Hallway leading to 104B Men's Restroom	W4	Plaster	Green	None	0	12.4	Positive
1	1	104Q	Hallway leading to 104B Men's Restroom	Ceiling	Plaster	White	None	0	21.6	Positive
1	1	S19	Main Stairwell (Men's Restroom Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S19	Main Stairwell (Men's Restroom Side)	W1	Plaster	Green	None	0	18.1	Positive
1	1	S19	Main Stairwell (Men's Restroom Side)	W2	Plaster	Green	None	0	18.5	Positive
1	1	S19	Main Stairwell (Men's Restroom Side)	W3	Plaster	Green	None	0	20.9	Positive
1	1	S19	Main Stairwell (Men's Restroom Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S19	Main Stairwell (Men's Restroom Side)	Ceiling	Plaster	White	None	0	21	Positive
1	1	S18	Main Stairwell (Women's Restroom Side)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S18	Main Stairwell (Women's Restroom Side)	W1	Plaster	Green	None	0	15.9	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	S18	Main Stairwell (Women's Restroom Side)	W2	Plaster	Green	None	0	21.7	Positive
1	1	S18	Main Stairwell (Women's Restroom Side)	W3	Plaster	Green	None	0	18.2	Positive
1	1	S18	Main Stairwell (Women's Restroom Side)	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S18	Main Stairwell (Women's Restroom Side)	Ceiling	Plaster	White	None	0	19.4	Positive
1	1	H000	Main Entrance (Vestibule)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H000	Main Entrance (Vestibule)	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H000	Main Entrance (Vestibule)	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H000	Main Entrance (Vestibule)	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H000	Main Entrance (Vestibule)	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H000	Main Entrance (Vestibule)	Ceiling	Plaster	White	None	0	22.1	Positive
1	1	H001	Main Entrance Foyer	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H001	Main Entrance Foyer	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H001	Main Entrance Foyer	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H001	Main Entrance Foyer	W3	Plaster	Green	None	0	16.7	Positive
1	1	H001	Main Entrance Foyer	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H001	Main Entrance Foyer	Ceiling	Plaster	White	None	0	9.5	Positive
1	1	105A	Women's Restroom adjacent to Main Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105A	Women's Restroom adjacent to Main Lobby	W1	Plaster	Green	Cracking	5	21.6	Positive
1	1	105A	Women's Restroom adjacent to Main Lobby	W2	Plaster	Green	Chipping	25	12.3	Positive
1	1	105A	Women's Restroom adjacent to Main Lobby	W3	Plaster	Green	Chipping	3	18.8	Positive
1	1	105A	Women's Restroom adjacent to Main Lobby	W4	Plaster	Green	Cracking	30	9.2	Positive
1	1	105A	Women's Restroom adjacent to Main Lobby	Ceiling	Plaster	Tan	Cracking	50	17.9	Positive
1	1	105B	Men's Restroom adjacent to Main Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Men's Restroom adjacent to Main Lobby	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Men's Restroom adjacent to Main Lobby	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Men's Restroom adjacent to Main Lobby	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Men's Restroom adjacent to Main Lobby	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Men's Restroom adjacent to Main Lobby	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106	Classroom 106	Floor	Concrete	Brown	Friction	3	12	Positive
1	1	106	Classroom 106	W1	Plaster	Green	Flaking	7	23.3	Positive
1	1	106	Classroom 106	W2	Plaster	Green	Flaking	1	18.5	Positive
1	1	106	Classroom 106	W3	Plaster	Green	Flaking	3	24.6	Positive
1	1	106	Classroom 106	W4	Plaster	Green	None	0	19.2	Positive
1	1	106	Classroom 106	Ceiling	Plaster	White	Flaking	20	21.1	Positive
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	W1	Plaster	Green	Chipping	7	16.3	Positive
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	W2	Plaster	Green	None	0	10.1	Positive
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	W3	Plaster	Green	None	0	12.4	Positive
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	W4	Plaster	Green	None	0	8.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	106RC	Classroom 106 Closet (No. 2 Right Side Closet)	Ceiling	Plaster	Green	Moisture Damage	15	17.4	Positive
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	W1	Plaster	Green	None	0	13.2	Positive
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	W2	Plaster	Green	None	0	12.6	Positive
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	W3	Plaster	Green	None	0	11.7	Positive
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	W4	Plaster	Green	None	0	12.9	Positive
1	1	106LC	Classroom 106 Closet (No. 1 Left Side Closet)	Ceiling	Plaster	Green	None	0	18	Positive
1	1	107	Classroom 107	Floor	Concrete	Brown	Chipping	10	2.9	Positive
1	1	107	Classroom 107	W1	Plaster	Green	Flaking	3	22.6	Positive
1	1	107	Classroom 107	W2	Plaster	Green	None	0	15.7	Positive
1	1	107	Classroom 107	W3	Plaster	Green	None	0	24.2	Positive
1	1	107	Classroom 107	W4	Plaster	Green	None	0	0.01	Negative
1	1	107	Classroom 107	Ceiling	Plaster	White	Flaking	20	17.9	Positive
1	1	107Q	Classroom 107 - Left Side Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107Q	Classroom 107 - Left Side Closet	W1	Plaster	Green	Flaking	35	14.9	Positive
1	1	107Q	Classroom 107 - Left Side Closet	W2	Plaster	Green	Flaking	20	13.5	Positive
1	1	107Q	Classroom 107 - Left Side Closet	W3	Plaster	Green	Flaking	25	10.4	Positive
1	1	107Q	Classroom 107 - Left Side Closet	W4	Plaster	Green	None	0	13.2	Positive
1	1	107Q	Classroom 107 - Left Side Closet	Ceiling	Plaster	Green	None	0	18.6	Positive
1	1	107R	Classroom 107 Closet (Right Side Closet)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107R	Classroom 107 Closet (Right Side Closet)	W1	Plaster	Green	Flaking	7	10.3	Positive
1	1	107R	Classroom 107 Closet (Right Side Closet)	W2	Plaster	Green	Flaking	5	12.3	Positive
1	1	107R	Classroom 107 Closet (Right Side Closet)	W3	Plaster	Green	Flaking	5	12	Positive
1	1	107R	Classroom 107 Closet (Right Side Closet)	W4	Plaster	Green	None	0	9.7	Positive
1	1	107R	Classroom 107 Closet (Right Side Closet)	Ceiling	Plaster	Green	None	0	23.5	Positive
1	1	107K	Classroom 107 - Kitchen	Floor	Metal	Brown	None	0	0	Negative
1	1	107K	Classroom 107 - Kitchen	W1	Plaster	Green	Alligating	15	17.8	Positive
1	1	107K	Classroom 107 - Kitchen	W2	Plaster	Green	Cracking	10	18.5	Positive
1	1	107K	Classroom 107 - Kitchen	W3	Plaster	Green	None	0	20.8	Positive
1	1	107K	Classroom 107 - Kitchen	W4	Plaster	Green	Cracking	12	18.2	Positive
1	1	107K	Classroom 107 - Kitchen	Ceiling	Plaster	Tan	Cracking	35	20.9	Positive
1	1	107A	Teacher's Lounge 107A	Floor	Metal	Brown	None	0	0.5	Negative
1	1	107A	Teacher's Lounge 107A	W1	Plaster	Green	None	0	24.6	Positive
1	1	107A	Teacher's Lounge 107A	W2	Plaster	Green	Chipping	8	4	Positive
1	1	107A	Teacher's Lounge 107A	W3	Plaster	Green	None	0	28.1	Positive
1	1	107A	Teacher's Lounge 107A	W4	Plaster	Green	Cracking	12	31.3	Positive
1	1	107A	Teacher's Lounge 107A	Ceiling	Plaster	White	Flaking	6	26.9	Positive
1	1	108	Classroom 108	Floor	Concrete	Brown	None	0	0.16	Negative
1	1	108	Classroom 108	W1	Plaster	Tan	None	0	68.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	108	Classroom 108	W2	Plaster	Tan	None	0	58.7	Positive
1	1	108	Classroom 108	W3	Plaster	Tan	None	0	62	Positive
1	1	108	Classroom 108	W4	Plaster	Green	None	0	12.7	Positive
1	1	108	Classroom 108	Ceiling	Plaster	White	Flaking	20	18.1	Positive
1	1	108Q	Classroom 108 Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108Q	Classroom 108 Closet	W1	Plaster	Green	None	0	0	Negative
1	1	108Q	Classroom 108 Closet	W2	Plaster	Green	None	0	30.8	Positive
1	1	108Q	Classroom 108 Closet	W3	Plaster	Green	None	0	31.1	Positive
1	1	108Q	Classroom 108 Closet	W4	Plaster	Green	None	0	0	Negative
1	1	108Q	Classroom 108 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108A	Storage 108A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108A	Storage 108A	W1	Brick	Green	None	0	0.09	Negative
1	1	108A	Storage 108A	W2	Sheetrock	Green	None	0	0	Negative
1	1	108A	Storage 108A	W3	Brick	Green	None	0	0.09	Negative
1	1	108A	Storage 108A	W4	Brick	Green	None	0	0.12	Negative
1	1	108A	Storage 108A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Storage Closet in Storage 108A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108C	Storage Closet in Storage 108A	W1	Brick	Tan	None	0	0.07	Negative
1	1	108C	Storage Closet in Storage 108A	W2	Brick	Tan	None	0	0.21	Negative
1	1	108C	Storage Closet in Storage 108A	W3	Brick	Tan	None	0	0.1	Negative
1	1	108C	Storage Closet in Storage 108A	W4	Brick	Tan	None	0	0.04	Negative
1	1	108C	Storage Closet in Storage 108A	Ceiling	Plaster	White	None	0	14.8	Positive
1	1	108B	Storage/Faculty 108B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	108B	Storage/Faculty 108B	W1	Brick	Tan	None	0	12.8	Positive
1	1	108B	Storage/Faculty 108B	W2	Brick	Tan	None	0	0	Negative
1	1	108B	Storage/Faculty 108B	W3	Brick	Tan	None	0	5.8	Positive
1	1	108B	Storage/Faculty 108B	W4	Sheetrock	Tan	None	0	0.03	Negative
1	1	108B	Storage/Faculty 108B	Ceiling	Plaster	White	Flaking	5	14.8	Positive
1	1	109	Classroom 109	Floor	Concrete	Grey	None	0	0.03	Negative
1	1	109	Classroom 109	W1	Plaster	Green	Flaking	7	37.6	Positive
1	1	109	Classroom 109	W2	Plaster	Green	None	0	26.6	Positive
1	1	109	Classroom 109	W3	Plaster	Green	None	0	29.4	Positive
1	1	109	Classroom 109	W4	Plaster	Green	None	0	30.8	Positive
1	1	109	Classroom 109	Ceiling	Plaster	White	Flaking	20	28.4	Positive
1	1	110	School Store Room 110	Floor	Concrete	Brown	Chipping	5	0.02	Negative
1	1	110	School Store Room 110	W1	Brick	Green	Cracking	20	6.1	Positive
1	1	110	School Store Room 110	W2	Brick	Green	Cracking	3	1.6	Positive
1	1	110	School Store Room 110	W3	Brick	Green	Cracking	8	2.4	Positive
1	1	110	School Store Room 110	W4	Brick	Green	Cracking	12	1.7	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	110	School Store Room 110	Ceiling	Plaster	White	Flaking	10	16	Positive
1	1	110B	Girl's Restroom across from Classroom 109	Floor	Concrete	Grey	None	0	0.01	Negative
1	1	110B	Girl's Restroom across from Classroom 109	W1	Plaster	Green	Cracking	5	13.8	Positive
1	1	110B	Girl's Restroom across from Classroom 109	W2	Plaster	Green	Cracking	20	15.9	Positive
1	1	110B	Girl's Restroom across from Classroom 109	W3	Plaster	Green	Chipping	7	19.5	Positive
1	1	110B	Girl's Restroom across from Classroom 109	W4	Plaster	Green	Cracking	15	15.4	Positive
1	1	110B	Girl's Restroom across from Classroom 109	Ceiling	Plaster	White	Flaking	25	23.9	Positive
1	1	110C	Custodial Closet next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110C	Custodial Closet next to Girl's Restroom	W1	Plaster	Tan	Chipping	3	23.4	Positive
1	1	110C	Custodial Closet next to Girl's Restroom	W2	Plaster	Tan	Chipping	2	19.2	Positive
1	1	110C	Custodial Closet next to Girl's Restroom	W3	Plaster	Tan	Chipping	2	20.4	Positive
1	1	110C	Custodial Closet next to Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110C	Custodial Closet next to Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	PC110C	Pipe Chase in Custodial Closet next to Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	110D	Building Engineer's Closet next to Girl's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Building Engineer's Closet next to Girl's Restroom	W1	Plaster	Tan	Moisture Damage	20	13.5	Positive
1	1	110D	Building Engineer's Closet next to Girl's Restroom	W2	Plaster	Tan	Moisture Damage	25	11.7	Positive
1	1	110D	Building Engineer's Closet next to Girl's Restroom	W3	Plaster	Tan	Moisture Damage	25	16.5	Positive
1	1	110D	Building Engineer's Closet next to Girl's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110D	Building Engineer's Closet next to Girl's Restroom	Ceiling	Plaster	White	Chipping	2	7.4	Positive
1	1	4B	South Fan Room 4B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4B	South Fan Room 4B	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4B	South Fan Room 4B	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4B	South Fan Room 4B	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4B	South Fan Room 4B	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	4B	South Fan Room 4B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	116A	Storage Closet across from School Store	Floor	Concrete	N/A	N/A	0	N/a	N/A
1	1	116A	Storage Closet across from School Store	W1	Brick	White	None	0	17.9	Positive
1	1	116A	Storage Closet across from School Store	W2	Brick	White	None	0	5.3	Positive
1	1	116A	Storage Closet across from School Store	W3	Brick	White	None	0	14.4	Positive
1	1	116A	Storage Closet across from School Store	W4	Brick	White	None	0	8.6	Positive
1	1	116A	Storage Closet across from School Store	Ceiling	Plaster	White	Cracking	3	24.5	Positive
1	1	S13	South East Stairwell leading to the South Gym	Floor	Concrete	Brown	None	0	0.06	Negative
1	1	S13	South East Stairwell leading to the South Gym	W1	Plaster	White	Flaking	5	10.9	Positive



			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	S13	South East Stairwell leading to the South Gym	W2	Plaster	White	Flaking	3	9.9	Positive
1	1	S13	South East Stairwell leading to the South Gym	W3	Plaster	White	Flaking	1	16.7	Positive
1	1	S13	South East Stairwell leading to the South Gym	W4	Plaster	White	Flaking	1	12.7	Positive
1	1	S13	South East Stairwell leading to the South Gym	Ceiling	Plaster	White	Flaking	5	16.4	Positive
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	W1	Brick	White	None	0	11.4	Positive
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	W2	Brick	White	None	0	9.6	Positive
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	W3	Brick	White	None	0	13.2	Positive
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	W4	Brick	White	None	0	9.2	Positive
1	1	S16	Stairwell leading to South East Stairwell leading to the South Girl's Gym	Ceiling	Plaster	White	None	0	16.6	Positive
1	1	110E	BE Storage in South East Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	110E	BE Storage in South East Stairwell	W1	Plaster	Green	Moisture Damage	30	12.1	Positive
1	1	110E	BE Storage in South East Stairwell	W2	Plaster	Green	Moisture Damage	10	10.6	Positive
1	1	110E	BE Storage in South East Stairwell	W3	Plaster	Green	Moisture Damage	5	11.1	Positive
1	1	110E	BE Storage in South East Stairwell	W4	Plaster	Green	Moisture Damage	10	9.7	Positive
1	1	110E	BE Storage in South East Stairwell	Ceiling	Plaster	Green	Cracking	10	13.7	Positive
1	1	110F	Storage Closet under South East Stairwall	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	110F	Storage Closet under South East Stairwall	W1	Brick	Tan	None	0	0.11	Negative
1	1	110F	Storage Closet under South East Stairwall	W2	Brick	Tan	None	0	0.09	Negative
1	1	110F	Storage Closet under South East Stairwall	W3	Brick	Tan	None	0	0.13	Negative
1	1	110F	Storage Closet under South East Stairwall	W4	Brick	Tan	None	0	0.04	Negative
1	1	110F	Storage Closet under South East Stairwall	Ceiling	Concrete	No Access	No Access	No access	No access	No Access
1	1	110G	Storage Closet across from 110F	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	110G	Storage Closet across from 110F	W1	Brick	Tan	None	0	0.03	Negative
1	1	110G	Storage Closet across from 110F	W2	Brick	Tan	None	0	0.07	Negative
1	1	110G	Storage Closet across from 110F	W3	Brick	Tan	None	0	0.09	Negative
1	1	110G	Storage Closet across from 110F	W4	Brick	Tan	None	0	0.04	Negative
1	1	110G	Storage Closet across from 110F	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	1	H17	Hallway leading to the South Gym	Floor	Concrete	Brown	None	0	0	Negative
1	1	H17	Hallway leading to the South Gym	W1	Brick	White	None	0	20.9	Positive
1	1	H17	Hallway leading to the South Gym	W2	Brick	White	None	0	25.5	Positive
1	1	H17	Hallway leading to the South Gym	W3	Brick	White	None	0	22.8	Positive
1	1	H17	Hallway leading to the South Gym	W4	Brick	White	None	0	21.6	Positive
1	1	H17	Hallway leading to the South Gym	Ceiling	Concrete	White	Flaking	5	11	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	B	111A	Gym Storage Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111A	Gym Storage Room	W1	Brick	Yellow	None	0	0.19	Negative
1	B	111A	Gym Storage Room	W2	Brick	Yellow	None	0	0.8	Positive
1	B	111A	Gym Storage Room	W3	Brick	Yellow	None	0	0.3	Negative
1	B	111A	Gym Storage Room	W4	Brick	Yellow	None	0	0.5	Negative
1	B	111A	Gym Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	111	Girl's Gym/South Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111	Girl's Gym/South Gym	W1	Brick	White	None	0	24.3	Positive
1	B	111	Girl's Gym/South Gym	W2	Brick	White	None	0	16.4	Positive
1	B	111	Girl's Gym/South Gym	W3	Brick	White	None	0	26.3	Positive
1	B	111	Girl's Gym/South Gym	W4	Brick	White	None	0	19.9	Positive
1	B	111	Girl's Gym/South Gym	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	B	111B	Long Pipe Run Closet in Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111B	Long Pipe Run Closet in Gym	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111B	Long Pipe Run Closet in Gym	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111B	Long Pipe Run Closet in Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111B	Long Pipe Run Closet in Gym	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	111B	Long Pipe Run Closet in Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S117	Stairwell leading to the South Girl's Gym	Floor	Concrete	Brown	None	0	0	Negative
1	1	S117	Stairwell leading to the South Girl's Gym	W1	Brick	White	None	0	17.1	Positive
1	1	S117	Stairwell leading to the South Girl's Gym	W2	Brick	White	None	0	17.9	Positive
1	1	S117	Stairwell leading to the South Girl's Gym	W3	Brick	White	None	0	18.5	Positive
1	1	S117	Stairwell leading to the South Girl's Gym	W4	Brick	White	None	0	13	Positive
1	1	S117	Stairwell leading to the South Girl's Gym	Ceiling	Concrete	White	None	0	13.2	Positive
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	Floor	Concrete	Brown	None	0	0.03	Negative
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	W1	Plaster	White	None	0	11.5	Positive
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	W2	Plaster	White	None	0	11.7	Positive
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	W3	Plaster	White	None	0	13.3	Positive
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	W4	Plaster	White	None	0	10.6	Positive
1	1	S118	South East stairwell leading to Stairwell to South Boy's Gym	Ceiling	Plaster	White	Flaking	2	15.9	Positive
1	B	111S	South Gym Closet	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	111S	South Gym Closet	W1	Brick	Tan	None	0	0.07	Negative
1	B	111S	South Gym Closet	W2	Brick	Tan	None	0	0.01	Negative
1	B	111S	South Gym Closet	W3	Brick	Tan	None	0	0.04	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	B	111S	South Gym Closet	W4	Brick	Tan	None	0	0.03	Negative
1	B	111S	South Gym Closet	Ceiling	Concrete	Tan	None	0	0	Negative
1	B	111S	South Gym Office	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	111S	South Gym Office	W1	Brick	Tan	None	0	0.11	Negative
1	B	111S	South Gym Office	W2	Brick	Tan	None	0	0.05	Negative
1	B	111S	South Gym Office	W3	Brick	Tan	None	0	0.13	Negative
1	B	111S	South Gym Office	W4	Brick	Tan	None	0	0.04	Negative
1	B	111S	South Gym Office	Ceiling	Concrete	White	None	0	0.12	Negative
1	1	111R	Former Boy's South Locker Room	Floor	Concrete	Grey	None	0	0.02	Negative
1	1	111R	Former Boy's South Locker Room	W1	Brick	White	None	0	17.2	Positive
1	1	111R	Former Boy's South Locker Room	W2	Brick	White	None	0	16.1	Positive
1	1	111R	Former Boy's South Locker Room	W3	Brick	White	None	0	0	Negative
1	1	111R	Former Boy's South Locker Room	W4	Brick	White	None	0	0	Negative
1	1	111R	Former Boy's South Locker Room	Ceiling	Concrete	White	None	0	5.4	Positive
1	1	111C	Rest Room in Former Boy's South Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	111C	Rest Room in Former Boy's South Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	111C	Rest Room in Former Boy's South Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	111C	Rest Room in Former Boy's South Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	111C	Rest Room in Former Boy's South Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	111C	Rest Room in Former Boy's South Locker Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	Auditorium	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	112	Auditorium	W1	Plaster	White	Flaking	15	9.2	Positive
1	1	112	Auditorium	W2	Plaster	White	Flaking	20	8.3	Positive
1	1	112	Auditorium	W3	Plaster	White	Flaking	7	9.3	Positive
1	1	112	Auditorium	W4	Plaster	White	Flaking	20	10.1	Positive
1	1	112	Auditorium	Ceiling	Plaster	White	Flaking	25	No Access	No Access
1	1	112 A	Stage	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	112 A	Stage	W1	Plaster	Black	None	0	4.3	Positive
1	1	112 A	Stage	W2	Plaster	Black	None	0	4.7	Positive
1	1	112 A	Stage	W3	Plaster	Black	None	0	4.1	Positive
1	1	112 A	Stage	W4	Plaster	Black	None	0	5.6	Positive
1	1	112 A	Stage	Ceiling	Plaster	Black	None	0	No Access	No Access
1	1	112C	South Hallway alongside Auditorium	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	112C	South Hallway alongside Auditorium	W1	Plaster	White	None	0	15.9	Positive
1	1	112C	South Hallway alongside Auditorium	W2	Plaster	White	None	0	13.7	Positive
1	1	112C	South Hallway alongside Auditorium	W3	Plaster	White	Flaking	100	0	Negative
1	1	112C	South Hallway alongside Auditorium	W4	Plaster	White	None	0	15.6	Positive
1	1	112C	South Hallway alongside Auditorium	Ceiling	Plaster	White	Flaking	12	19.7	Positive
1	1	112B	Side Room from Stage Left (South)	Floor	Wood	N/A	N/A	0	N/A	N/A

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	112B	Side Room from Stage Left (South)	W1	Plaster	White	Chipping	20	11.8	Positive
1	1	112B	Side Room from Stage Left (South)	W2	Plaster	White	Chipping	10	14.3	Positive
1	1	112B	Side Room from Stage Left (South)	W3	Plaster	White	Chipping	25	12.4	Positive
1	1	112B	Side Room from Stage Left (South)	W4	Plaster	White	Chipping	20	0.07	Negative
1	1	112B	Side Room from Stage Left (South)	Ceiling	Plaster	White	Chipping	50	15.7	Positive
1	1	112D	Side Room from Stage Right (North)	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	112D	Side Room from Stage Right (North)	W1	Plaster	Green/White	Flaking	5	15.1	Positive
1	1	112D	Side Room from Stage Right (North)	W2	Plaster	Green/White	Flaking	10	15.4	Positive
1	1	112D	Side Room from Stage Right (North)	W3	Plaster	Tan	None	0	11.6	Positive
1	1	112D	Side Room from Stage Right (North)	W4	Sheetrock	Green/White	None	0	0.1	Negative
1	1	112D	Side Room from Stage Right (North)	Ceiling	Plaster	White	Flaking	30	17.3	Positive
1	1	112E	North Hallway alongside Auditorium	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	112E	North Hallway alongside Auditorium	W1	Plaster	White	None	0	23.3	Positive
1	1	112E	North Hallway alongside Auditorium	W2	Plaster	White	Flaking	20	24.6	Positive
1	1	112E	North Hallway alongside Auditorium	W3	Plaster	White	None	0	9.9	Positive
1	1	112E	North Hallway alongside Auditorium	W4	Plaster	White	Flaking	100	0	Negative
1	1	112E	North Hallway alongside Auditorium	Ceiling	Plaster	Tan	Chipping	30	21.7	Positive
1	1	115	South Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115	South Cafeteria	W1	Brick	Green	None	0	5.9	Positive
1	1	115	South Cafeteria	W2	Brick	Green	None	0	3.6	Positive
1	1	115	South Cafeteria	W3	Brick	Green	None	0	3.4	Positive
1	1	115	South Cafeteria	W4	Brick	Green	None	0	3.6	Positive
1	1	115	South Cafeteria	Ceiling	Plaster	Green	None	0	2.5	Positive
1	1	115B	old Ticket Booth for South Cafeteria	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	115B	old Ticket Booth for South Cafeteria	W1	Brick	Tan	None	0	3.2	Positive
1	1	115B	old Ticket Booth for South Cafeteria	W2	Brick	Tan	None	0	3.4	Positive
1	1	115B	old Ticket Booth for South Cafeteria	W3	Brick	Tan	None	0	3.6	Positive
1	1	115B	old Ticket Booth for South Cafeteria	W4	Brick	Tan	None	0	5.8	Positive
1	1	115B	old Ticket Booth for South Cafeteria	Ceiling	Plaster	Tan	Cracking	10	10.6	Positive
1	1	115A	Kitchen Locker Room	Floor	Wood	Grey	Chipping	10	0	Negative
1	1	115A	Kitchen Locker Room	W1	Plaster	Tan	Alligating	15	15.2	Positive
1	1	115A	Kitchen Locker Room	W2	Plaster	Tan	Cracking	10	15.6	Positive
1	1	115A	Kitchen Locker Room	W3	Plaster	Tan	Cracking	10	11.8	Positive
1	1	115A	Kitchen Locker Room	W4	Plaster	Tan	Chipping	25	12.1	Positive
1	1	115A	Kitchen Locker Room	Ceiling	Plaster	Tan	Cracking	35	13.1	Positive
1	1	114B	Kitchen	Floor	Concrete	Grey	Friction	80	0.05	Negative
1	1	114B	Kitchen	W1	Brick	Tan	None	0	3.7	Positive
1	1	114B	Kitchen	W2	Brick	Tan	None	0	5.8	Positive
1	1	114B	Kitchen	W3	Brick	Tan	None	0	4	Positive

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 10/3/2022- 12/21/2022</b>							
			<b>Inspector Name and Certificate Number: Michael A Martin-#006416</b>		<b>1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year</b>					
			<b>Inspection Company: Criterion labs</b>		<b>4725 Fairmount Avenue, Philadelphia, PA 19139</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading</b>	<b>XRF (positive/ negative)</b>
1	1	114B	Kitchen	W4	Brick	Tan	None	0	3.6	Positive
1	1	114B	Kitchen	Ceiling	Plaster	Tan	Cracking	20	7.4	Positive
1	1	114A	Kitchen Office	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	114A	Kitchen Office	W1	Plaster	Tan	Chipping	15	14.7	Positive
1	1	114A	Kitchen Office	W2	Plaster	Tan	Flaking	8	8.6	Positive
1	1	114A	Kitchen Office	W3	Plaster	Tan	Flaking	10	9.3	Positive
1	1	114A	Kitchen Office	W4	Plaster	Tan	Flaking	5	12.4	Positive
1	1	114A	Kitchen Office	Ceiling	Plaster	Tan	No Access	No Access	No Access	No Access
1	1	114D	Kitchen Dry Storage Room	Floor	Concrete	Grey	Chipping	25	0.03	Negative
1	1	114D	Kitchen Dry Storage Room	W1	Brick	Tan	Flaking	5	2.4	Positive
1	1	114D	Kitchen Dry Storage Room	W2	Brick	Tan	Flaking	7	2.5	Positive
1	1	114D	Kitchen Dry Storage Room	W3	Brick	Tan	Flaking	8	0.5	Negative
1	1	114D	Kitchen Dry Storage Room	W4	Brick	Tan	Flaking	5	6	Positive
1	1	114D	Kitchen Dry Storage Room	Ceiling	Plaster	Tan	None	0	0.4	Negative
1	1	115C	Kitchen Refrigerator/Freezer Room	Floor	Concrete	Grey	None	0	0.01	Negative
1	1	115C	Kitchen Refrigerator/Freezer Room	W1	Brick	Yellow	None	0	4.2	Positive
1	1	115C	Kitchen Refrigerator/Freezer Room	W2	Brick	Tan	Chipping	20	6.1	Positive
1	1	115C	Kitchen Refrigerator/Freezer Room	W3	Brick	Yellow	None	0	3.4	Positive
1	1	115C	Kitchen Refrigerator/Freezer Room	W4	Brick	Yellow	None	0	5.6	Positive
1	1	115C	Kitchen Refrigerator/Freezer Room	Ceiling	Plaster	Tan	Flaking	15	9.5	Positive
1	1	114	North Cafeteria	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	North Cafeteria	W1	Brick	Green	None	0	2.4	Positive
1	1	114	North Cafeteria	W2	Brick	Green	None	0	4.2	Positive
1	1	114	North Cafeteria	W3	Brick	Green	None	0	6.2	Positive
1	1	114	North Cafeteria	W4	Brick	Green	None	0	2	Positive
1	1	114	North Cafeteria	Ceiling	Plaster	Green	None	0	5.5	Positive
1	B	113	Boy's Gym/North Gym	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	B	113	Boy's Gym/North Gym	W1	Brick	White	None	0	28.6	Positive
1	B	113	Boy's Gym/North Gym	W2	Brick	White	None	0	26.1	Positive
1	B	113	Boy's Gym/North Gym	W3	Brick	White	None	0	5.6	Positive
1	B	113	Boy's Gym/North Gym	W4	Brick	White	None	0	21.2	Positive
1	B	113	Boy's Gym/North Gym	Ceiling	Concrete	White	Flaking	10	No Access	No Access
1	1	113E	BE Storage in North East Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	113E	BE Storage in North East Stairwell	W1	Brick	Tan	None	0	0.23	Negative
1	1	113E	BE Storage in North East Stairwell	W2	Brick	Tan	None	0	0.17	Negative
1	1	113E	BE Storage in North East Stairwell	W3	Brick	Tan	None	0	0.26	Negative
1	1	113E	BE Storage in North East Stairwell	W4	Brick	Tan	None	0	0.23	Negative
1	1	113E	BE Storage in North East Stairwell	Ceiling	Concrete	White	None	0	0.03	Negative
1	1	113F	Storage Closet under North East Stairwall	Floor	Concrete	N/A	N/A	0	N/A	N/A

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	113F	Storage Closet under North East Stairwall	W1	Brick	Tan	None	0	0.19	Negative
1	1	113F	Storage Closet under North East Stairwall	W2	Brick	Tan	None	0	0.21	Negative
1	1	113F	Storage Closet under North East Stairwall	W3	Brick	Tan	None	0	0.17	Negative
1	1	113F	Storage Closet under North East Stairwall	W4	Brick	Tan	None	0	0.17	Negative
1	1	113F	Storage Closet under North East Stairwall	Ceiling	Concrete	White	None	0	0	Negative
1	1	S116	Stairwell leading to the North Boy's Gym	Floor	Concrete	Brown	None	0	0.03	Negative
1	1	S116	Stairwell leading to the North Boy's Gym	W1	Brick	White	None	0	18.6	Positive
1	1	S116	Stairwell leading to the North Boy's Gym	W2	Brick	White	None	0	21.8	Positive
1	1	S116	Stairwell leading to the North Boy's Gym	W3	Brick	White	None	0	22.2	Positive
1	1	S116	Stairwell leading to the North Boy's Gym	W4	Brick	White	None	0	15.7	Positive
1	1	S116	Stairwell leading to the North Boy's Gym	Ceiling	Concrete	White	None	0	13.7	Positive
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	Floor	Concrete	Brown	None	0	0	Negative
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	W1	Brick	White	None	0	26.8	Positive
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	W2	Brick	White	None	0	23.6	Positive
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	W3	Plaster	White	None	0	15.1	Positive
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	W4	Plaster	White	None	0	15.7	Positive
1	1	S115	North East stairwell leading to Stairwell to North Boy's Gym	Ceiling	Concrete	White	Flaking	5	15.3	Positive
1	1	113G	Storage Closet across from 113F	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	113G	Storage Closet across from 113F	W1	Brick	Tan	None	0	0.17	Negative
1	1	113G	Storage Closet across from 113F	W2	Brick	Tan	None	0	0.13	Negative
1	1	113G	Storage Closet across from 113F	W3	Brick	Tan	None	0	0.11	Negative
1	1	113G	Storage Closet across from 113F	W4	Brick	Tan	None	0	0.13	Negative
1	1	113G	Storage Closet across from 113F	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	113B	Long Pipe Run Closet in North Gym	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113B	Long Pipe Run Closet in North Gym	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113B	Long Pipe Run Closet in North Gym	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113B	Long Pipe Run Closet in North Gym	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113B	Long Pipe Run Closet in North Gym	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113B	Long Pipe Run Closet in North Gym	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113C	North Gym Storage Closet	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	113C	North Gym Storage Closet	W1	Brick	Tan	Flaking	10	0.06	Negative
1	B	113C	North Gym Storage Closet	W2	Brick	Tan	Flaking	5	0.09	Negative
1	B	113C	North Gym Storage Closet	W3	Brick	Tan	Cracking	7	0.06	Negative
1	B	113C	North Gym Storage Closet	W4	Brick	Tan	Flaking	15	0.13	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	B	113C	North Gym Storage Closet	Ceiling	Concrete	White	Alligating	10	0.01	Negative
1	1	113R	Former North Locker Room	Floor	Concrete	Grey	None	0	0	Negative
1	1	113R	Former North Locker Room	W1	Brick	White	None	0	5.2	Positive
1	1	113R	Former North Locker Room	W2	Brick	White	None	0	14.3	Positive
1	1	113R	Former North Locker Room	W3	Brick	White	None	0	0	Negative
1	1	113R	Former North Locker Room	W4	Brick	White	None	0	4.7	Positive
1	1	113R	Former North Locker Room	Ceiling	Concrete	White	None	0	12.3	Positive
1	1	S113	Stairs to Former North Locker Room	Floor	Concrete	Grey	None	0	0.21	Negative
1	1	S113	Stairs to Former North Locker Room	W1	Brick	White	None	0	18.5	Positive
1	1	S113	Stairs to Former North Locker Room	W2	Brick	White	None	0	4.7	Positive
1	1	S113	Stairs to Former North Locker Room	W3	Brick	White	None	0	14.3	Positive
1	1	S113	Stairs to Former North Locker Room	W4	Brick	White	None	0	8.9	Positive
1	1	S113	Stairs to Former North Locker Room	Ceiling	Concrete	White	None	0	12.6	Positive
1	1	113H	Storage Room in Former North Locker Room	Floor	Concrete	Grey	None	0	0.04	Negative
1	1	113H	Storage Room in Former North Locker Room	W1	Brick	White	None	0	0	Negative
1	1	113H	Storage Room in Former North Locker Room	W2	Brick	White	None	0	0	Negative
1	1	113H	Storage Room in Former North Locker Room	W3	Brick	White	None	0	0	Negative
1	1	113H	Storage Room in Former North Locker Room	W4	Brick	White	None	0	0	Negative
1	1	113H	Storage Room in Former North Locker Room	Ceiling	Concrete	White	None	0	No Access	No Access
1	1	113D	Restroom in Former North Locker Room	Floor	Concrete	Grey	None	0	0	Negative
1	1	113D	Restroom in Former North Locker Room	W1	Brick	White	None	0	15.9	Positive
1	1	113D	Restroom in Former North Locker Room	W2	Brick	White	None	0	10.4	Positive
1	1	113D	Restroom in Former North Locker Room	W3	Brick	White	None	0	16.8	Positive
1	1	113D	Restroom in Former North Locker Room	W4	Brick	White	None	0	12.3	Positive
1	1	113D	Restroom in Former North Locker Room	Ceiling	Brick	White	None	0	16.7	Positive
1	1	100A	Building Engineer's Office	Floor	Concrete	Brown	None	0	0.2	Negative
1	1	100A	Building Engineer's Office	W1	Brick	Tan	None	0	21.4	Positive
1	1	100A	Building Engineer's Office	W2	Brick	Tan	None	0	15.1	Positive
1	1	100A	Building Engineer's Office	W3	Brick	Tan	None	0	12.7	Positive
1	1	100A	Building Engineer's Office	W4	Brick	Tan	None	0	15.2	Positive
1	1	100A	Building Engineer's Office	Ceiling	Concrete	Tan	None	0	18.1	Positive
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	Floor	Concrete	Green	None	0	0	Negative
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	W1	Plaster	White	None	0	25.7	Positive
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	W2	Plaster	White	None	0	24.6	Positive
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	W3	Plaster	White	None	0	24.8	Positive
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	W4	Plaster	White	None	0	25.7	Positive
1	1	H15D	NE Entrance Vestibule by Building Engineer's Office	Ceiling	Plaster	White	Flaking	10	23.3	Positive
1	1	H15C	Hallway from NE exit to Boiler, including side exit	Floor	Concrete	Green	None	0	0	Negative
1	1	H15C	Hallway from NE exit to Boiler, including side exit	W1	Plaster	Green/White	None	0	24.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	H15C	Hallway from NE exit to Boiler, including side exit	W2	Plaster	Green/White	Flaking	5	9.2	Positive
1	1	H15C	Hallway from NE exit to Boiler, including side exit	W3	Plaster	Green/White	None	0	20.7	Positive
1	1	H15C	Hallway from NE exit to Boiler, including side exit	W4	Plaster	Green/White	None	0	9.9	Positive
1	1	H15C	Hallway from NE exit to Boiler, including side exit	Ceiling	Plaster	White	Flaking	40	24.4	Positive
1	1	114E	Old Ticket Booth for North Cafeteria	Floor	Concrete	Brown	None	0	0.06	Negative
1	1	114E	Old Ticket Booth for North Cafeteria	W1	Brick	Tan	Flaking	2	4.3	Positive
1	1	114E	Old Ticket Booth for North Cafeteria	W2	Brick	Tan	None	0	3.7	Positive
1	1	114E	Old Ticket Booth for North Cafeteria	W3	Brick	Tan	Flaking	2	4.3	Positive
1	1	114E	Old Ticket Booth for North Cafeteria	W4	Brick	Tan	None	0	2.2	Positive
1	1	114E	Old Ticket Booth for North Cafeteria	Ceiling	Concrete	White	Flaking	3	13.4	Positive
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	Floor	Concrete	Green	None	0	0	Negative
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	W1	Plaster	Green/White	None	0	18.4	Positive
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	W2	Plaster	Green/White	Chipping	35	17	Positive
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	W3	Plaster	Green/White	None	0	17.6	Positive
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	W4	Plaster	Green/White	Flaking	25	12.7	Positive
1	1	H15	Hallway from South Fan Room to Kitchen Area (or S. Stage Room)	Ceiling	Plaster	Tan	Cracking	70	19.7	Positive
1	1	H11C	SE Entrance Vestibule near School Store	Floor	Concrete	Green	None	0	0	Negative
1	1	H11C	SE Entrance Vestibule near School Store	W1	Plaster	White	None	0	17.4	Positive
1	1	H11C	SE Entrance Vestibule near School Store	W2	Plaster	White	Cracking	10	20.3	Positive
1	1	H11C	SE Entrance Vestibule near School Store	W3	Metal	Green	None	0	0	Negative
1	1	H11C	SE Entrance Vestibule near School Store	W4	Plaster	White	Cracking	30	15.7	Positive
1	1	H11C	SE Entrance Vestibule near School Store	Ceiling	Plaster	Tan	Chipping	20	18	Positive
1	1	H11	Hallway along Classrooms 108 to 109	Floor	Concrete	Green	None	0	0	Negative
1	1	H11	Hallway along Classrooms 108 to 109	W1	Plaster	White	None	0	17.8	Positive
1	1	H11	Hallway along Classrooms 108 to 109	W2	Plaster	White	None	0	16.9	Positive
1	1	H11	Hallway along Classrooms 108 to 109	W3	Plaster	White	None	0	21	Positive
1	1	H11	Hallway along Classrooms 108 to 109	W4	Plaster	White	None	0	11.4	Positive
1	1	H11	Hallway along Classrooms 108 to 109	Ceiling	Plaster	Tan	Flaking	20	19.3	Positive
1	1	H11	Hallway from Classrooms 108 to 109	Floor	Concrete	Green	None	0	0	Negative
1	1	H11	Hallway from Classrooms 108 to 109	W1	Plaster	Green	None	0	13.2	Positive
1	1	H11	Hallway from Classrooms 108 to 109	W2	Plaster	Green	None	0	16.3	Positive
1	1	H11	Hallway from Classrooms 108 to 109	W3	Plaster	Green	None	0	18.1	Positive
1	1	H11	Hallway from Classrooms 108 to 109	W4	Plaster	Green	None	0	15.6	Positive
1	1	H11	Hallway from Classrooms 108 to 109	Ceiling	Plaster	Tan	Flaking	20	20.8	Positive



			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	H11B	SW Entrance Vestibule by room 107A	Floor	Concrete	Green	None	0	0	Negative
1	1	H11B	SW Entrance Vestibule by room 107A	W1	Plaster	White	None	0	22.3	Positive
1	1	H11B	SW Entrance Vestibule by room 107A	W2	Plaster	White	Cracking	2	26.3	Positive
1	1	H11B	SW Entrance Vestibule by room 107A	W3	Metal	Green	None	0	0	Negative
1	1	H11B	SW Entrance Vestibule by room 107A	W4	Plaster	White	None	0	25.7	Positive
1	1	H11B	SW Entrance Vestibule by room 107A	Ceiling	Plaster	Tan	Flaking	7	21.6	Positive
1	1	H11A	Hallway along Classrooms 106 to 107	Floor	Concrete	Green	None	0	0	Negative
1	1	H11A	Hallway along Classrooms 106 to 107	W1	Plaster	Green/White	None	0	17.2	Positive
1	1	H11A	Hallway along Classrooms 106 to 107	W2	Plaster	Green/White	Flaking	5	12.1	Positive
1	1	H11A	Hallway along Classrooms 106 to 107	W3	Plaster	Green/White	None	0	19	Positive
1	1	H11A	Hallway along Classrooms 106 to 107	W4	Plaster	Green/White	Flaking	3	17.6	Positive
1	1	H11A	Hallway along Classrooms 106 to 107	Ceiling	Plaster	White	Flaking	25	20.7	Positive
1	1	H16	Hallway along Auditorium and Main Lobby	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H16	Hallway along Auditorium and Main Lobby	W1	Plaster	Green	None	0	18.3	Positive
1	1	H16	Hallway along Auditorium and Main Lobby	W2	Plaster	Green	None	0	22.1	Positive
1	1	H16	Hallway along Auditorium and Main Lobby	W3	Plaster	Green	None	0	20	Positive
1	1	H16	Hallway along Auditorium and Main Lobby	W4	Plaster	Green	None	0	18.9	Positive
1	1	H16	Hallway along Auditorium and Main Lobby	Ceiling	Plaster	White	None	0	17.9	Positive
1	1	H16B	Hallway from Room 104 to Main Office	Floor	Concrete	Green	None	0	0	Negative
1	1	H16B	Hallway from Room 104 to Main Office	W1	Plaster	Green/White	None	0	19.9	Positive
1	1	H16B	Hallway from Room 104 to Main Office	W2	Plaster	Green/White	None	0	12.4	Positive
1	1	H16B	Hallway from Room 104 to Main Office	W3	Plaster	Green/White	None	0	21.7	Positive
1	1	H16B	Hallway from Room 104 to Main Office	W4	Plaster	Green/White	Moisture Damage	5	16.3	Positive
1	1	H16B	Hallway from Room 104 to Main Office	Ceiling	Plaster	White	Flaking	30	22.3	Positive
1	1	H16A	NW Exit Vestibule	Floor	Concrete	Green	None	0	0	Negative
1	1	H16A	NW Exit Vestibule	W1	Plaster	White	None	0	22.6	Positive
1	1	H16A	NW Exit Vestibule	W2	Plaster	White	None	0	15.4	Positive
1	1	H16A	NW Exit Vestibule	W3	Plaster	White	None	0	23.3	Positive
1	1	H16A	NW Exit Vestibule	W4	Plaster	White	None	0	17.1	Positive
1	1	H16A	NW Exit Vestibule	Ceiling	Plaster	White	Cracking	10	13.1	Positive
1	1	H12	Hallway along Classrooms 100 to 102	Floor	Concrete	Green	None	0	0	Negative
1	1	H12	Hallway along Classrooms 100 to 102	W1	Plaster	Green/White	None	0	24	Positive
1	1	H12	Hallway along Classrooms 100 to 102	W2	Plaster	Green/White	None	0	17.3	Positive
1	1	H12	Hallway along Classrooms 100 to 102	W3	Plaster	Green/White	None	0	16.8	Positive
1	1	H12	Hallway along Classrooms 100 to 102	W4	Plaster	Green/White	None	0	16.1	Positive
1	1	H12	Hallway along Classrooms 100 to 102	Ceiling	Plaster	White	Flaking	30	13.9	Positive
1	1	S125	Fire Tower A	Floor	Concrete	Grey	None	0	0.14	Negative
1	1	S125	Fire Tower A	W1	Brick	White	Efflorescence	50	9.8	Positive
1	1	S125	Fire Tower A	W2	Brick	White	Efflorescence	50	11.3	Positive

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	S125	Fire Tower A	W3	Brick	White	Efflorescence	50	9.4	Positive
1	1	S125	Fire Tower A	W4	Brick	White	Efflorescence	50	6.7	Positive
1	1	S125	Fire Tower A	Ceiling	Plaster	White	Efflorescence	50	10.3	Positive
1	1	S123	Fire Tower B	Floor	Concrete	Grey	None	0	0.29	Negative
1	1	S123	Fire Tower B	W1	Brick	White	Efflorescence	50	12	Positive
1	1	S123	Fire Tower B	W2	Brick	White	Efflorescence	50	9.7	Positive
1	1	S123	Fire Tower B	W3	Brick	White	Efflorescence	50	8.6	Positive
1	1	S123	Fire Tower B	W4	Brick	White	Efflorescence	50	4.9	Positive
1	1	S123	Fire Tower B	Ceiling	Plaster	White	Efflorescence	50	12.7	Positive
1	1	S11	Stairwell across from Classroom 110	Floor	Concrete	N/A	N/A	0	0	N/A
1	1	S11	Stairwell across from Classroom 110	W1	Plaster	White	None	0	13.2	Positive
1	1	S11	Stairwell across from Classroom 110	W2	Plaster	White	Flaking	5	14.6	Positive
1	1	S11	Stairwell across from Classroom 110	W3	Plaster	White	None	0	12.8	Positive
1	1	S11	Stairwell across from Classroom 110	W4	Plaster	White	Flaking	5	13.5	Positive
1	1	S11	Stairwell across from Classroom 110	Ceiling	Plaster	White	Flaking	3	15.1	Positive
1	1	S110	Stairwell across from Classroom 102	Floor	Concrete	N/A	N/A	0	0	Negative
1	1	S110	Stairwell across from Classroom 102	W1	Plaster	White	None	0	15.4	Positive
1	1	S110	Stairwell across from Classroom 102	W2	Plaster	White	None	0	14.1	Positive
1	1	S110	Stairwell across from Classroom 102	W3	Plaster	White	None	0	12.8	Positive
1	1	S110	Stairwell across from Classroom 102	W4	Plaster	White	None	0	14.1	Positive
1	1	S110	Stairwell across from Classroom 102	Ceiling	Plaster	White	None	0	12.8	Positive
1	1	S12	Stairwell across from Storage Room 100	Floor	Concrete	N/A	N/A	0	0	Negative
1	1	S12	Stairwell across from Storage Room 100	W1	Plaster	White	None	0	13.5	Positive
1	1	S12	Stairwell across from Storage Room 100	W2	Plaster	White	None	0	13.8	Positive
1	1	S12	Stairwell across from Storage Room 100	W3	Plaster	White	None	0	12	Positive
1	1	S12	Stairwell across from Storage Room 100	W4	Plaster	White	None	0	12.2	Positive
1	1	S12	Stairwell across from Storage Room 100	Ceiling	Plaster	White	Flaking	15	15.9	Positive
1	1	S17	Stairwell across from Classroom 108	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S17	Stairwell across from Classroom 108	W1	Plaster	White	None	0	18.1	Positive
1	1	S17	Stairwell across from Classroom 108	W2	Plaster	White	None	0	13.1	Positive
1	1	S17	Stairwell across from Classroom 108	W3	Plaster	White	None	0	15.5	Positive
1	1	S17	Stairwell across from Classroom 108	W4	Plaster	White	None	0	15.8	Positive
1	1	S17	Stairwell across from Classroom 108	Ceiling	Plaster	White	None	0	18.3	Positive
1	2	200A	Room 200 Lounge	Floor	Wood	N/A	None	0	N/A	N/A
1	2	200A	Room 200 Lounge	W1	Plaster	Green	None	0	26.4	Positive
1	2	200A	Room 200 Lounge	W2	Plaster	Green	Chipping	3	25.1	Positive
1	2	200A	Room 200 Lounge	W3	Sheetrock	Green	None	0	0	Negative
1	2	200A	Room 200 Lounge	W4	Plaster	Green	None	0	28.3	Positive
1	2	200A	Room 200 Lounge	Ceiling	Plaster	White	Flaking	7	19.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	200B	Room 200 Lounge/Storage - Restroom	Floor	Concrete	Grey	Friction	5	6.1	Positive
1	2	200B	Room 200 Lounge/Storage - Restroom	W1	Plaster	Green	Cracking	8	18.6	Positive
1	2	200B	Room 200 Lounge/Storage - Restroom	W2	Plaster	Green	Flaking	2	19.1	Positive
1	2	200B	Room 200 Lounge/Storage - Restroom	W3	Plaster	Green	None	0	24.5	Positive
1	2	200B	Room 200 Lounge/Storage - Restroom	W4	Plaster	White	None	0	17.2	Positive
1	2	200B	Room 200 Lounge/Storage - Restroom	Ceiling	Plaster	White	Flaking	5	26.1	Positive
1	2	201	Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	W1	Plaster	Green	Flaking	5	10.1	Positive
1	2	201	Classroom 201	W2	Plaster	Green	None	0	0	Negative
1	2	201	Classroom 201	W3	Plaster	Green	Chipping	2	0	Negative
1	2	201	Classroom 201	W4	Plaster	Green	None	0	0	Negative
1	2	201	Classroom 201	Ceiling	Plaster	White	Flaking	25	17.1	Positive
1	2	201B	Classroom 203A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201B	Classroom 203A	W1	Brick	Green	None	0	0.08	Negative
1	2	201B	Classroom 203A	W2	Brick	Green	None	0	0.12	Negative
1	2	201B	Classroom 203A	W3	Brick	Green	None	0	0.08	Negative
1	2	201B	Classroom 203A	W4	Brick	Green	None	0	0	Negative
1	2	201B	Classroom 203A	Ceiling	Plaster	White	Flaking	10	20.7	Positive
1	2	201Q	Custodial Closet across from Classroom 201	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	2	201Q	Custodial Closet across from Classroom 201	W1	Plaster	White	Flaking	2	13.1	Positive
1	2	201Q	Custodial Closet across from Classroom 201	W2	Plaster	White	None	0	15.7	Positive
1	2	201Q	Custodial Closet across from Classroom 201	W3	Plaster	White	None	0	18.2	Positive
1	2	201Q	Custodial Closet across from Classroom 201	W4	Plaster	White	None	0	15.3	Positive
1	2	201Q	Custodial Closet across from Classroom 201	Ceiling	Plaster	White	Flaking	2	19.5	Positive
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC201Q	Pipe Chase in Custodial Closet across from Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201R	Boy's Restroom across from Classroom 201	Floor	Concrete	Grey	None	0	0.4	Negative
1	2	201R	Boy's Restroom across from Classroom 201	W1	Plaster	Green	Flaking	7	10.7	Positive
1	2	201R	Boy's Restroom across from Classroom 201	W2	Plaster	Green	Flaking	20	0.28	Negative
1	2	201R	Boy's Restroom across from Classroom 201	W3	Plaster	Green	Flaking	10	4.8	Positive

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	201R	Boy's Restroom across from Classroom 201	W4	Plaster	Green	Cracking	30	0.17	Negative
1	2	201R	Boy's Restroom across from Classroom 201	Ceiling	Plaster	White	Flaking	10	19.7	Positive
1	2	201S	Storage Room next to Classroom 201B to the East	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201S	Storage Room next to Classroom 201B to the East	W1	Brick	Green/White	None	0	0.23	Negative
1	2	201S	Storage Room next to Classroom 201B to the East	W2	Brick	Green/White	None	0	0.5	Negative
1	2	201S	Storage Room next to Classroom 201B to the East	W3	Brick	Green/White	None	0	0.15	Negative
1	2	201S	Storage Room next to Classroom 201B to the East	W4	Brick	Green/White	Chipping	2	0.17	Negative
1	2	201S	Storage Room next to Classroom 201B to the East	Ceiling	Plaster	White	None	0	18.1	Positive
1	2	202	Classroom 202	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	202	Classroom 202	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	203	Classroom 203	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	W1	Plaster	Green	Flaking	2	10.5	Positive
1	2	203	Classroom 203	W2	Wood	Brown	None	0	0.04	Negative
1	2	203	Classroom 203	W3	Plaster	Green	None	0	12.3	Positive
1	2	203	Classroom 203	W4	Sheetrock	Green	Friction	2	0	Negative
1	2	203	Classroom 203	Ceiling	Plaster	White	Flaking	16	20.7	Positive
1	2	203A	Nurse's Office Room 204	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203A	Nurse's Office Room 204	W1	Plaster	Green	Cracking	2	10.1	Positive
1	2	203A	Nurse's Office Room 204	W2	Plaster	Green	None	0	0	Negative
1	2	203A	Nurse's Office Room 204	W3	Plaster	Green	None	0	0.17	Negative
1	2	203A	Nurse's Office Room 204	W4	Plaster	Green	None	0	9.4	Positive
1	2	203A	Nurse's Office Room 204	Ceiling	Plaster	White	Flaking	5	18.4	Positive
1	2	203B	Nurse's Office - Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	203B	Nurse's Office - Restroom	W1	Plaster	Green	None	0	0.3	Negative
1	2	203B	Nurse's Office - Restroom	W2	Plaster	Green	None	0	0.4	Negative
1	2	203B	Nurse's Office - Restroom	W3	Plaster	Green	None	0	0.13	Negative
1	2	203B	Nurse's Office - Restroom	W4	Plaster	Green	None	0	0	Negative
1	2	203B	Nurse's Office - Restroom	Ceiling	Plaster	Green	None	0	13.8	Positive
1	2	204	Classroom 205	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 205	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 205	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 205	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 205	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	204	Classroom 205	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	205	Counselor's Office Room 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	205	Counselor's Office Room 206	W1	Plaster	Green	None	0	17.3	Positive
1	2	205	Counselor's Office Room 206	W2	Plaster	Green	None	0	12.1	Positive
1	2	205	Counselor's Office Room 206	W3	Plaster	Green	None	0	13	Positive
1	2	205	Counselor's Office Room 206	W4	Plaster	Green	None	0	15.4	Positive
1	2	205	Counselor's Office Room 206	Ceiling	Plaster	White	Chipping	20	18.1	Positive
1	2	206	Assistant Principal's Meeting Area Room 207	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Assistant Principal's Meeting Area Room 207	W1	Plaster	Green	None	0	13.4	Positive
1	2	206	Assistant Principal's Meeting Area Room 207	W2	Sheetrock	Green	None	0	0.04	Negative
1	2	206	Assistant Principal's Meeting Area Room 207	W3	Plaster	Green	None	0	15.6	Positive
1	2	206	Assistant Principal's Meeting Area Room 207	W4	Sheetrock	Green	None	0	0.05	Negative
1	2	206	Assistant Principal's Meeting Area Room 207	Ceiling	Plaster	White	Flaking	10	17.7	Positive
1	2	206A	Roster Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Roster Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Roster Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Roster Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Roster Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	206A	Roster Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207A	Assistant Principal's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Assistant Principal's Office	W1	Plaster	Green	None	0	15.6	Positive
1	2	207A	Assistant Principal's Office	W2	Plaster	Green	None	0	0.19	Negative
1	2	207A	Assistant Principal's Office	W3	Plaster	Green	None	0	0.16	Negative
1	2	207A	Assistant Principal's Office	W4	Plaster	Green	None	0	0.11	Negative
1	2	207A	Assistant Principal's Office	Ceiling	Plaster	White	Flaking	10	13.4	Positive
1	2	207	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207	Main Office	W1	Plaster	White	Moisture Damage	2	18.1	Positive
1	2	207	Main Office	W2	Plaster	White	Cracking	5	0.02	Negative
1	2	207	Main Office	W3	Plaster	White	None	0	12.4	Positive
1	2	207	Main Office	W4	Plaster	White	None	0	13.9	Positive
1	2	207	Main Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207B	Main Office Front Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207Q	Main Office Room 207 Storage Closet in Rear	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	207Q	Main Office Room 207 Storage Closet in Rear	W1	Plaster	Green	Cracking	4	27.3	Positive
1	2	207Q	Main Office Room 207 Storage Closet in Rear	W2	Plaster	Green	None	0	0.23	Negative
1	2	207Q	Main Office Room 207 Storage Closet in Rear	W3	Plaster	Green	Chipping	2	22.6	Positive

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	207Q	Main Office Room 207 Storage Closet in Rear	W4	Plaster	Green	Cracking	2	21.6	Positive
1	2	207Q	Main Office Room 207 Storage Closet in Rear	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	207C	Principal's Office next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207C	Principal's Office next to Main Office	W1	Plaster	White	Cracking	5	15	Positive
1	2	207C	Principal's Office next to Main Office	W2	Plaster	White	None	0	0.26	Negative
1	2	207C	Principal's Office next to Main Office	W3	Plaster	White	None	0	7.3	Positive
1	2	207C	Principal's Office next to Main Office	W4	Plaster	White	None	0	0.05	Negative
1	2	207C	Principal's Office next to Main Office	Ceiling	Plaster	White	Chipping	10	17.6	Positive
1	2	207D	Restroom in Principal's Office next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207D	Restroom in Principal's Office next to Main Office	W1	Plaster	White	None	0	0.07	Negative
1	2	207D	Restroom in Principal's Office next to Main Office	W2	Plaster	White	None	0	0.04	Negative
1	2	207D	Restroom in Principal's Office next to Main Office	W3	Plaster	White	None	0	0.04	Negative
1	2	207D	Restroom in Principal's Office next to Main Office	W4	Plaster	White	None	0	13.7	Positive
1	2	207D	Restroom in Principal's Office next to Main Office	Ceiling	Plaster	White	None	0	16.1	Positive
1	2	207E	Storage in Principal's Office next to Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207E	Storage in Principal's Office next to Main Office	W1	Plaster	Pink	None	0	0.02	Negative
1	2	207E	Storage in Principal's Office next to Main Office	W2	Plaster	Pink	None	0	0.05	Negative
1	2	207E	Storage in Principal's Office next to Main Office	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	2	207E	Storage in Principal's Office next to Main Office	W4	Plaster	Pink	None	0	0.02	Negative
1	2	207E	Storage in Principal's Office next to Main Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208	Former IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	Former IMC	W1	Plaster	White	None	0	9.4	Positive
1	2	208	Former IMC	W2	Sheetrock	White	None	0	0	Negative
1	2	208	Former IMC	W3	Plaster	White	None	0	12.9	Positive
1	2	208	Former IMC	W4	Plaster	White	None	0	14.9	Positive
1	2	208	Former IMC	Ceiling	Plaster	White	Cracking	55	16.3	Positive
1	2	208A	Former IMC - Kitchen	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208A	Former IMC - Kitchen	W1	Plaster	White	None	0	12.8	Positive
1	2	208A	Former IMC - Kitchen	W2	Sheetrock	White	None	0	0.11	Negative
1	2	208A	Former IMC - Kitchen	W3	Sheetrock	White	None	0	0.05	Negative
1	2	208A	Former IMC - Kitchen	W4	Plaster	White	None	0	14	Positive
1	2	208A	Former IMC - Kitchen	Ceiling	Plaster	White	Flaking	10	17.3	Positive
1	2	210	Classroom 210	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	210	Classroom 210	W1	Plaster	Green	Chipping	7	13.9	Positive
1	2	210	Classroom 210	W2	Plaster	Green	Moisture Damage	5	12.4	Positive
1	2	210	Classroom 210	W3	Plaster	Green	None	0	18.4	Positive
1	2	210	Classroom 210	W4	Plaster	Green	None	0	0.14	Negative
1	2	210	Classroom 210	Ceiling	Plaster	White	Flaking	15	22.4	Positive
1	2	210A	Small Hall between Classrooms 210 & 211	Floor	Wood	N/A	N/A	0	N/A	N/A

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	210A	Small Hall between Classrooms 210 & 211	W1	Plaster	Green	Flaking	2	17.8	Positive
1	2	210A	Small Hall between Classrooms 210 & 211	W2	Plaster	Green	None	0	12.3	Positive
1	2	210A	Small Hall between Classrooms 210 & 211	W3	Plaster	Green	None	0	14.9	Positive
1	2	210A	Small Hall between Classrooms 210 & 211	W4	Plaster	Green	None	0	0.03	Negative
1	2	210A	Small Hall between Classrooms 210 & 211	Ceiling	Plaster	White	Flaking	3	16.9	Positive
1	2	211A	Classroom 211 - Rear Closet	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	211A	Classroom 211 - Rear Closet	W1	Plaster	Green	Flaking	15	12.4	Positive
1	2	211A	Classroom 211 - Rear Closet	W2	Plaster	Green	Flaking	25	13.9	Positive
1	2	211A	Classroom 211 - Rear Closet	W3	Plaster	Green	Flaking	5	9.7	Positive
1	2	211A	Classroom 211 - Rear Closet	W4	Plaster	Green	Flaking	30	12.8	Positive
1	2	211A	Classroom 211 - Rear Closet	Ceiling	Plaster	White	Cracking	10	No Access	No Access
1	2	211B	Classroom 211 - Front Closet	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	211B	Classroom 211 - Front Closet	W1	Plaster	Green	Flaking	7	6.6	Positive
1	2	211B	Classroom 211 - Front Closet	W2	Plaster	Green	Flaking	12	10.1	Positive
1	2	211B	Classroom 211 - Front Closet	W3	Plaster	Green	Flaking	5	5.6	Positive
1	2	211B	Classroom 211 - Front Closet	W4	Plaster	Green	Flaking	40	3.4	Positive
1	2	211B	Classroom 211 - Front Closet	Ceiling	Plaster	White	No Access	No Access	No Access	No Access
1	2	211	Classroom 211	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	211	Classroom 211	W1	Plaster	Green	None	0	0.07	Negative
1	2	211	Classroom 211	W2	Plaster	Green	None	0	0	Negative
1	2	211	Classroom 211	W3	Plaster	Green	None	0	0.05	Negative
1	2	211	Classroom 211	W4	Plaster	Green	None	0	0.06	Negative
1	2	211	Classroom 211	Ceiling	Plaster	White	Flaking	15	11.6	Positive
1	2	212	Classroom 212	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212	Classroom 212	W1	Plaster	Green	None	0	15.9	Positive
1	2	212	Classroom 212	W2	Plaster	Green	None	0	12.8	Positive
1	2	212	Classroom 212	W3	Plaster	Green	None	0	10.5	Positive
1	2	212	Classroom 212	W4	Sheetrock	Green	None	0	0	Negative
1	2	212	Classroom 212	Ceiling	Plaster	White	Flaking	10	14.3	Positive
1	2	212C	Classroom 212A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212C	Classroom 212A	W1	Brick	Green	None	0	0.04	Negative
1	2	212C	Classroom 212A	W2	Sheetrock	Green	None	0	0	Negative
1	2	212C	Classroom 212A	W3	Brick	Green	None	0	0.08	Negative
1	2	212C	Classroom 212A	W4	Brick	Green	None	0	0.11	Negative
1	2	212C	Classroom 212A	Ceiling	Plaster	White	Flaking	10	17.5	Positive
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	W1	Brick	Green	None	0	0.9	Positive
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	W2	Brick	Green	None	0	0.24	Negative
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	W3	Brick	Green	None	0	0.3	Negative

			<b>Lead-Safe Certification Assessment Report</b>							
			<b>Dates: 10/3/2022- 12/21/2022</b>							
			<b>Inspector Name and Certificate Number: Michael A Martin-#006416</b>		<b>1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year</b>					
			<b>Inspection Company: Criterion labs</b>		<b>4725 Fairmount Avenue, Philadelphia, PA 19139</b>					
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading</b>	<b>XRF (positive/ negative)</b>
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	W4	Sheetrock	Green	None	0	0	Negative
1	2	212A	Teacher's Lounge Room 212B next to Girl's Restroom	Ceiling	Plaster	White	Flaking	12	21.3	Positive
1	2	212Q	Storage Closet across Room 212	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	2	212Q	Storage Closet across Room 212	W1	Sheetrock	Blue	None	0	0	Negative
1	2	212Q	Storage Closet across Room 212	W2	Brick	Blue	None	0	0.4	Negative
1	2	212Q	Storage Closet across Room 212	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212Q	Storage Closet across Room 212	W4	Brick	Blue	None	0	0.7	Positive
1	2	212Q	Storage Closet across Room 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212B	Girl's Restroom	Floor	Concrete	Grey	Friction	5	2.2	Positive
1	2	212B	Girl's Restroom	W1	Plaster	Green	Moisture Damage	8	18.8	Positive
1	2	212B	Girl's Restroom	W2	Plaster	Green	Moisture Damage	45	14.1	Positive
1	2	212B	Girl's Restroom	W3	Plaster	Green	Cracking	4	12.3	Positive
1	2	212B	Girl's Restroom	W4	Plaster	Green	Flaking	5	9.7	Positive
1	2	212B	Girl's Restroom	Ceiling	Plaster	Green	Moisture Damage	10	20.7	Positive
1	2	212R	Storage Closet next to Girl's Restroom	Floor	Concrete	N/A	N/A	0	0	N/A
1	2	212R	Storage Closet next to Girl's Restroom	W1	Plaster	Tan	Flaking	3	13.6	Positive
1	2	212R	Storage Closet next to Girl's Restroom	W2	Plaster	Tan	None	0	12.5	Positive
1	2	212R	Storage Closet next to Girl's Restroom	W3	Plaster	Tan	None	0	20.7	Positive
1	2	212R	Storage Closet next to Girl's Restroom	W4	Plaster	Tan	Chipping	2	18.6	Positive
1	2	212R	Storage Closet next to Girl's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	PC212R	Pipe Chase in Storage Closet next to Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Classroom 213	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	213	Classroom 213	W1	Plaster	Green	None	0	9.7	Positive
1	2	213	Classroom 213	W2	Sheetrock	Blue	None	0	0	Negative
1	2	213	Classroom 213	W3	Plaster	Green	None	0	12.8	Positive
1	2	213	Classroom 213	W4	Plaster	Green	Chipping	6	13.7	Positive
1	2	213	Classroom 213	Ceiling	Plaster	White	Flaking	15	21.3	Positive
1	2	214	Teacher's Lounge Room 214	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Teacher's Lounge Room 214	W1	Plaster	Green	Chipping	1	11.2	Positive
1	2	214	Teacher's Lounge Room 214	W2	Plaster	Green	None	0	14.8	Positive
1	2	214	Teacher's Lounge Room 214	W3	Sheetrock	Green	None	0	0	Negative
1	2	214	Teacher's Lounge Room 214	W4	Plaster	Green	Flaking	3	13.8	Positive
1	2	214	Teacher's Lounge Room 214	Ceiling	Plaster	White	Flaking	5	16.9	Positive
1	2	214A	Teacher's Lounge Room 214 - Restroom	Floor	Concrete	Grey	None	0	0.9	Positive



			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	214A	Teacher's Lounge Room 214 - Restroom	W1	Plaster	White	None	0	16.9	Positive
1	2	214A	Teacher's Lounge Room 214 - Restroom	W2	Plaster	White	None	0	14.1	Positive
1	2	214A	Teacher's Lounge Room 214 - Restroom	W3	Plaster	White	None	0	14.6	Positive
1	2	214A	Teacher's Lounge Room 214 - Restroom	W4	Plaster	White	None	0	19.4	Positive
1	2	214A	Teacher's Lounge Room 214 - Restroom	Ceiling	Plaster	White	Flaking	5	24.5	Positive
1	2	215	Conference Room 215	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215	Conference Room 215	W1	Plaster	Green	None	0	15.1	Positive
1	2	215	Conference Room 215	W2	Plaster	Green	Flaking	2	15.6	Positive
1	2	215	Conference Room 215	W3	Plaster	Green	None	0	18.9	Positive
1	2	215	Conference Room 215	W4	Plaster	Green	None	0	15.6	Positive
1	2	215	Conference Room 215	Ceiling	Plaster	White	Flaking	10	23.6	Positive
1	2	216	Classroom 216	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	216	Classroom 216	W1	Plaster	Green	None	0	14.4	Positive
1	2	216	Classroom 216	W2	Plaster	Green	Flaking	1	15.8	Positive
1	2	216	Classroom 216	W3	Plaster	Green	Flaking	2	4.9	Positive
1	2	216	Classroom 216	W4	Plaster	Green	None	0	15	Positive
1	2	216	Classroom 216	Ceiling	Plaster	White	Flaking	15	17.5	Positive
1	2	217	Classroom 217	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	217	Classroom 217	W1	Plaster	Green	None	0	9.3	Positive
1	2	217	Classroom 217	W2	Plaster	Green	None	0	10.1	Positive
1	2	217	Classroom 217	W3	Plaster	Green	None	0	17	Positive
1	2	217	Classroom 217	W4	Sheetrock	Blue	None	0	0	Negative
1	2	217	Classroom 217	Ceiling	Plaster	White	Flaking	10	16.3	Positive
1	2	218	Classroom 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	218	Classroom 218	W1	Plaster	Green	Flaking	2	16.8	Positive
1	2	218	Classroom 218	W2	Plaster	Green	None	0	9.2	Positive
1	2	218	Classroom 218	W3	Plaster	Green	Flaking	10	7.9	Positive
1	2	218	Classroom 218	W4	Plaster	Green	Flaking	2	10.7	Positive
1	2	218	Classroom 218	Ceiling	Plaster	White	Cracking	10	18.7	Positive
1	2	219	Classroom 219	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	219	Classroom 219	W1	Plaster	Green	None	0	15.4	Positive
1	2	219	Classroom 219	W2	Plaster	Green	None	0	6.3	Positive
1	2	219	Classroom 219	W3	Plaster	Green	None	0	8.4	Positive
1	2	219	Classroom 219	W4	Plaster	Green	None	0	18.6	Positive
1	2	219	Classroom 219	Ceiling	Plaster	White	Flaking	10	20.9	Positive
1	2	220	Classroom 220	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	220	Classroom 220	W1	Plaster	Green	Flaking	10	14.1	Positive
1	2	220	Classroom 220	W2	Plaster	Green	None	0	9.3	Positive
1	2	220	Classroom 220	W3	Plaster	Green	Flaking	3	10.1	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	220	Classroom 220	W4	Plaster	Green	Flaking	5	13.5	Positive
1	2	220	Classroom 220	Ceiling	Plaster	White	Flaking	10	22.4	Positive
1	2	221	Classroom 221	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	221	Classroom 221	W1	Plaster	Green	None	0	11.1	Positive
1	2	221	Classroom 221	W2	Plaster	Green	None	0	9.7	Positive
1	2	221	Classroom 221	W3	Plaster	Green	None	0	11.6	Positive
1	2	221	Classroom 221	W4	Plaster	Green	None	0	14	Positive
1	2	221	Classroom 221	Ceiling	Plaster	White	Flaking	10	17.2	Positive
1	2	222	Classroom 222	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	222	Classroom 222	W1	Plaster	Green	None	0	13	Positive
1	2	222	Classroom 222	W2	Plaster	Green	None	0	14.1	Positive
1	2	222	Classroom 222	W3	Plaster	Green	None	0	12.7	Positive
1	2	222	Classroom 222	W4	Plaster	Green	None	0	10.5	Positive
1	2	222	Classroom 222	Ceiling	Plaster	White	Flaking	10	21.3	Positive
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	Floor	Concrete	Green	None	0	0	Negative
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	W1	Plaster	White/Blue	None	0	21.3	Positive
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	W2	Plaster	White/Blue	Flaking	5	18.7	Positive
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	W3	Plaster	White/Blue	None	0	12	Positive
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	W4	Plaster	White/Blue	Flaking	20	15.6	Positive
1	2	H213	Hallway from Restroom 200 to Teacher's Lounge 214	Ceiling	Plaster	White	Flaking	60	23.1	Positive
1	2	H28	Hallway from Classrooms 211 to 213	Floor	Concrete	Green	None	0	0	Negative
1	2	H28	Hallway from Classrooms 211 to 213	W1	Plaster	White/Blue	None	0	13.7	Positive
1	2	H28	Hallway from Classrooms 211 to 213	W2	Plaster	White/Blue	None	0	10.2	Positive
1	2	H28	Hallway from Classrooms 211 to 213	W3	Plaster	White/Blue	None	0	12.4	Positive
1	2	H28	Hallway from Classrooms 211 to 213	W4	Plaster	White/Blue	None	0	8.6	Positive
1	2	H28	Hallway from Classrooms 211 to 213	Ceiling	Plaster	White	Flaking	30	18.8	Positive
1	2	H214A	Hallway from Room 210 to IMC	Floor	Concrete	Green	None	0	0	Negative
1	2	H214A	Hallway from Room 210 to IMC	W1	Plaster	White/Green	None	0	17.7	Positive
1	2	H214A	Hallway from Room 210 to IMC	W2	Plaster	White/Green	None	0	21.3	Positive
1	2	H214A	Hallway from Room 210 to IMC	W3	Plaster	White/Green	None	0	13.9	Positive
1	2	H214A	Hallway from Room 210 to IMC	W4	Plaster	White/Green	Flaking	5	15.7	Positive
1	2	H214A	Hallway from Room 210 to IMC	Ceiling	Plaster	White	Flaking	25	24.1	Positive
1	2	H214	Hallway along Balcony and Front Stairs	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H214	Hallway along Balcony and Front Stairs	W1	Plaster	Green	None	0	23.2	Positive
1	2	H214	Hallway along Balcony and Front Stairs	W2	Plaster	Green	None	0	18.5	Positive
1	2	H214	Hallway along Balcony and Front Stairs	W3	Plaster	Green	None	0	21.6	Positive
1	2	H214	Hallway along Balcony and Front Stairs	W4	Plaster	Green	None	0	14.8	Positive
1	2	H214	Hallway along Balcony and Front Stairs	Ceiling	Plaster	White	None	0	20.7	Positive
1	2	H214 B	Hallway from Main Office to Nurse's Office	Floor	Concrete	Green	None	0	0	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	H214 B	Hallway from Main Office to Nurse's Office	W1	Plaster	White/Green	None	0	17.1	Positive
1	2	H214 B	Hallway from Main Office to Nurse's Office	W2	Plaster	White/Green	Flaking	20	16.3	Positive
1	2	H214 B	Hallway from Main Office to Nurse's Office	W3	Plaster	White/Green	None	0	21.9	Positive
1	2	H214 B	Hallway from Main Office to Nurse's Office	W4	Plaster	White/Green	None	0	13.5	Positive
1	2	H214 B	Hallway from Main Office to Nurse's Office	Ceiling	Plaster	White	Flaking	25	19.4	Positive
1	2	H29	Hallway from Classrooms 201 to 203	Floor	Concrete	Green	None	0	0	Negative
1	2	H29	Hallway from Classrooms 201 to 203	W1	Plaster	White/Blue	None	0	13.6	Positive
1	2	H29	Hallway from Classrooms 201 to 203	W2	Plaster	White/Blue	None	0	18.7	Positive
1	2	H29	Hallway from Classrooms 201 to 203	W3	Plaster	White/Blue	None	0	14.3	Positive
1	2	H29	Hallway from Classrooms 201 to 203	W4	Plaster	White/Blue	None	0	20.8	Positive
1	2	H29	Hallway from Classrooms 201 to 203	Ceiling	Plaster	White	Flaking	20	18.9	Positive
1	2	S21	Southwest Stairwell across from Classroom 213	Floor	Concrete	Brown	None	0	0.03	Negative
1	2	S21	Southwest Stairwell across from Classroom 213	W1	Plaster	White	Moisture Damage	25	12.4	Positive
1	2	S21	Southwest Stairwell across from Classroom 213	W2	Plaster	White	Flaking	5	15.7	Positive
1	2	S21	Southwest Stairwell across from Classroom 213	W3	Plaster	White	None	0	12.3	Positive
1	2	S21	Southwest Stairwell across from Classroom 213	W4	Plaster	White	Flaking	15	17.4	Positive
1	2	S21	Southwest Stairwell across from Classroom 213	Ceiling	Plaster	White	Flaking	2	21.3	Positive
1	2	S22	Northeast Stairwell across from Classroom 201	Floor	Concrete	Brown	None	0	0.05	Negative
1	2	S22	Northeast Stairwell across from Classroom 201	W1	Plaster	White	None	0	15.9	Positive
1	2	S22	Northeast Stairwell across from Classroom 201	W2	Plaster	White	None	0	17.1	Positive
1	2	S22	Northeast Stairwell across from Classroom 201	W3	Plaster	White	None	0	11.8	Positive
1	2	S22	Northeast Stairwell across from Classroom 201	W4	Plaster	White	Flaking	8	16.3	Positive
1	2	S22	Northeast Stairwell across from Classroom 201	Ceiling	Plaster	White	Flaking	10	20.6	Positive
1	2	S210	Southeast Stairwell across from Classroom 203	Floor	Concrete	Brown	None	0	0.12	Negative
1	2	S210	Southeast Stairwell across from Classroom 203	W1	Plaster	White	None	0	13.9	Positive
1	2	S210	Southeast Stairwell across from Classroom 203	W2	Plaster	White	None	0	15.5	Positive
1	2	S210	Southeast Stairwell across from Classroom 203	W3	Plaster	White	None	0	21.3	Positive
1	2	S210	Southeast Stairwell across from Classroom 203	W4	Plaster	White	None	0	19.7	Positive
1	2	S210	Southeast Stairwell across from Classroom 203	Ceiling	Plaster	White	None	0	20.4	Positive
1	2	S27	Northwest Stairwell across from Classroom 211	Floor	Concrete	Brown	None	0	0.03	Negative
1	2	S27	Northwest Stairwell across from Classroom 211	W1	Plaster	White	None	0	17.6	Positive
1	2	S27	Northwest Stairwell across from Classroom 211	W2	Plaster	White	None	0	20.3	Positive
1	2	S27	Northwest Stairwell across from Classroom 211	W3	Plaster	White	None	0	16.6	Positive
1	2	S27	Northwest Stairwell across from Classroom 211	W4	Plaster	White	None	0	19.4	Positive
1	2	S27	Northwest Stairwell across from Classroom 211	Ceiling	Plaster	White	None	0	20.7	Positive
1	2	S223	Fire Tower B	Floor	Concrete	Grey	None	0	0.27	Negative
1	2	S223	Fire Tower B	W1	Brick	White	Friction	10	4.1	Positive
1	2	S223	Fire Tower B	W2	Brick	White	None	0	5.5	Positive
1	2	S223	Fire Tower B	W3	Brick	White	None	0	7.3	Positive

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	S223	Fire Tower B	W4	Brick	White	None	0	4.9	Positive
1	2	S223	Fire Tower B	Ceiling	Plaster	White	None	0	23.4	Positive
1	2	S225	Fire Tower A	Floor	Concrete	Grey	None	0	0.7	Positive
1	2	S225	Fire Tower A	W1	Brick	White	None	0	4.5	Positive
1	2	S225	Fire Tower A	W2	Brick	White	None	0	3.4	Positive
1	2	S225	Fire Tower A	W3	Brick	White	None	0	2.7	Positive
1	2	S225	Fire Tower A	W4	Brick	White	None	0	6.9	Positive
1	2	S225	Fire Tower A	Ceiling	Plaster	White	None	0	18.3	Positive
1	2	S29	Main Stairwell	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S29	Main Stairwell	W1	Plaster	Green	None	0	18.9	Positive
1	2	S29	Main Stairwell	W2	Plaster	Green	None	0	20	Positive
1	2	S29	Main Stairwell	W3	Plaster	Green	None	0	24.8	Positive
1	2	S29	Main Stairwell	W4	Plaster	Green	None	0	21.4	Positive
1	2	S29	Main Stairwell	Ceiling	Plaster	White	None	0	18.3	Positive
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	W1	Plaster	Green	None	0	0.21	Negative
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	W2	Plaster	Green	None	0	0.13	Negative
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	W3	Plaster	Green	None	0	24.6	Positive
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	W4	Plaster	Green	Cracking	5	21.3	Positive
1	2	217A	Room 217A Upper Part of Stage Across from Room 218	Ceiling	Plaster	Blue	Chipping	60	13.4	Positive
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	W1	Plaster	Green	Cracking	9	0.06	Negative
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	W2	Plaster	Green	None	0	24.1	Positive
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	W3	Plaster	Green	None	0	16.6	Positive
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	W4	Plaster	Green	Flaking	3	18.4	Positive
1	2	218A	Room 218A Upper Part of Stage/Book Storage Across from Room 219	Ceiling	Plaster	Blue	Cracking	40	23	Positive
1	2	224A	Auditorium Balcony	Floor	Wood	N/A	N/A	0	N/A	N/A
1	2	224A	Auditorium Balcony	W1	Plaster	White	Flaking	5	7.3	Positive
1	2	224A	Auditorium Balcony	W2	Plaster	White	None	0	6.8	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	2	224A	Auditorium Balcony	W3	Plaster	White	Flaking	3	7.2	Positive
1	2	224A	Auditorium Balcony	W4	Plaster	White	Flaking	5	5.1	Positive
1	2	224A	Auditorium Balcony	Ceiling	Plaster	White	Flaking	12	17.8	Positive
1	2	224B	Auditorium Balcony Projection Booth	Floor	Concrete	Grey	None	0	0	Negative
1	2	224B	Auditorium Balcony Projection Booth	W1	Plaster	Green	Moisture Damage	50	0.1	Negative
1	2	224B	Auditorium Balcony Projection Booth	W2	Plaster	Green	Cracking	25	0.7	Positive
1	2	224B	Auditorium Balcony Projection Booth	W3	Plaster	Green	Chipping	10	0	Negative
1	2	224B	Auditorium Balcony Projection Booth	W4	Plaster	Green	Cracking	20	0.3	Negative
1	2	224B	Auditorium Balcony Projection Booth	Ceiling	Plaster	Grey	Moisture Damage	35	0	Negative
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	W1	Plaster	Green	Flaking	4	15	Positive
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	W2	Plaster	Green	None	0	14.3	Positive
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	W3	Plaster	Green	None	0	17.3	Positive
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	W4	Plaster	Green	None	0	13.6	Positive
1	3	301A	Teacher's Lounge between Classroom 323 and Classroom 301/302	Ceiling	Plaster	White	Flaking	15	22.4	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	Floor	Concrete	Grey	Friction	5	9.5	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	W1	Plaster	Green	Chipping	20	13.7	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	W2	Plaster	Green	Chipping	15	15.7	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	W3	Plaster	Green	None	0	14.3	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	W4	Plaster	Green	None	0	14.6	Positive
1	3	301Q	Teacher's Lounge between Classroom 323 and Classroom 301/302 - Restroom	Ceiling	Plaster	Green	Flaking	12	18.1	Positive
1	3	301/302	Classroom 301/302	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	301/302	Classroom 301/302	W1	Plaster	Green	None	0	21.6	Positive
1	3	301/302	Classroom 301/302	W2	Plaster	Yellow	None	0	22.5	Positive
1	3	301/302	Classroom 301/302	W3	Plaster	Green	None	0	17.4	Positive
1	3	301/302	Classroom 301/302	W4	Plaster	Green	None	0	21.9	Positive
1	3	301/302	Classroom 301/302	Ceiling	Plaster	White	Flaking	25	26.4	Positive
1	3	303	Classroom 303	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	303	Classroom 303	W1	Plaster	Green	Flaking	3	19.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	303	Classroom 303	W2	Sheetrock	Green	None	0	0	Negative
1	3	303	Classroom 303	W3	Plaster	Green	None	0	17	Positive
1	3	303	Classroom 303	W4	Plaster	Green	None	0	22.1	Positive
1	3	303	Classroom 303	Ceiling	Plaster	White	Flaking	10	25.3	Positive
1	3	304	Classroom 304	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	304	Classroom 304	W1	Plaster	Green	Flaking	15	21.3	Positive
1	3	304	Classroom 304	W2	Plaster	Green	None	0	20.4	Positive
1	3	304	Classroom 304	W3	Plaster	Green	None	0	17.2	Positive
1	3	304	Classroom 304	W4	Plaster	Green	None	0	18.6	Positive
1	3	304	Classroom 304	Ceiling	Plaster	White	Flaking	10	23.9	Positive
1	3	305	Classroom 305	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W1	Plaster	Green	Flaking	3	26.4	Positive
1	3	305	Classroom 305	W2	Plaster	Green	None	0	22.4	Positive
1	3	305	Classroom 305	W3	Plaster	Green	Chipping	2	16.9	Positive
1	3	305	Classroom 305	W4	Plaster	Green	None	0	18.3	Positive
1	3	305	Classroom 305	Ceiling	Plaster	White	Flaking	10	24.1	Positive
1	3	306	Classroom 306	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	306	Classroom 306	W1	Plaster	Green	None	0	17.6	Positive
1	3	306	Classroom 306	W2	Plaster	Green	None	0	14.1	Positive
1	3	306	Classroom 306	W3	Plaster	Green	Friction	7	14.9	Positive
1	3	306	Classroom 306	W4	Plaster	Green	Cracking	5	19.6	Positive
1	3	306	Classroom 306	Ceiling	Plaster	White	Flaking	10	20.6	Positive
1	3	307	Classroom 307	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	307	Classroom 307	W1	Plaster	Green	None	0	0.19	Negative
1	3	307	Classroom 307	W2	Plaster	Green	None	0	0.16	Negative
1	3	307	Classroom 307	W3	Plaster	Green	None	0	0.14	Negative
1	3	307	Classroom 307	W4	Plaster	Green	None	0	0.14	Negative
1	3	307	Classroom 307	Ceiling	Plaster	White	Flaking	12	24.5	Positive
1	3	307A	Classroom 307 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307A	Classroom 307 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307A	Classroom 307 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307A	Classroom 307 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307A	Classroom 307 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	307A	Classroom 307 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308	Classroom 308	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	308	Classroom 308	W1	Plaster	Green	Cracking	2	16.1	Positive
1	3	308	Classroom 308	W2	Plaster	Green	Flaking	1	17	Positive
1	3	308	Classroom 308	W3	Plaster	Green	Friction	8	16.7	Positive
1	3	308	Classroom 308	W4	Plaster	Green	None	0	0.04	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	308	Classroom 308	Ceiling	Plaster	White	Cracking	10	21.3	Positive
1	3	308Q	Classroom 308 Closet on the Right Side	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308Q	Classroom 308 Closet on the Right Side	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308Q	Classroom 308 Closet on the Right Side	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308Q	Classroom 308 Closet on the Right Side	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308Q	Classroom 308 Closet on the Right Side	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308Q	Classroom 308 Closet on the Right Side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	308L	Classroom 308 Closet on the Left Side	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	308L	Classroom 308 Closet on the Left Side	W1	Plaster	Green	None	0	0.19	Negative
1	3	308L	Classroom 308 Closet on the Left Side	W2	Plaster	Green	None	0	0.04	Negative
1	3	308L	Classroom 308 Closet on the Left Side	W3	Plaster	Green	None	0	0.02	Negative
1	3	308L	Classroom 308 Closet on the Left Side	W4	Plaster	Green	None	0	0.13	Negative
1	3	308L	Classroom 308 Closet on the Left Side	Ceiling	Plaster	Green	No Access	No access	No access	No Access
1	3	309	Classroom 309	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	309	Classroom 309	W1	Plaster	Green	None	0	18.2	Positive
1	3	309	Classroom 309	W2	Plaster	Green	Cracking	1	14.7	Positive
1	3	309	Classroom 309	W3	Plaster	Green	Chipping	7	13.7	Positive
1	3	309	Classroom 309	W4	Plaster	Green	Chipping	3	16.1	Positive
1	3	309	Classroom 309	Ceiling	Plaster	White	Flaking	10	25.9	Positive
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	W1	Plaster	Green	None	0	18.1	Positive
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	W2	Plaster	Green	None	0	18.4	Positive
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	W3	Plaster	Green	None	0	17.6	Positive
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	W4	Plaster	Green	None	0	10.3	Positive
1	3	309H	Small Hall between Classrooms 309 and 310 Closets	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309A	Classroom 309 Storage (Prep Room)	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	309A	Classroom 309 Storage (Prep Room)	W1	Plaster	Green	None	0	14.3	Positive
1	3	309A	Classroom 309 Storage (Prep Room)	W2	Plaster	Green	Cracking	2	18.4	Positive
1	3	309A	Classroom 309 Storage (Prep Room)	W3	Plaster	Green	Cracking	2	4.7	Positive
1	3	309A	Classroom 309 Storage (Prep Room)	W4	Plaster	Green	Flaking	4	16.7	Positive
1	3	309A	Classroom 309 Storage (Prep Room)	Ceiling	Plaster	White	Chipping	25	19.6	Positive
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	309Q	Classroom 309 Closet (Lab Chemical Storage)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310Q	Classroom 310 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310Q	Classroom 310 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	310Q	Classroom 310 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310Q	Classroom 310 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310Q	Classroom 310 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310Q	Classroom 310 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	310	Classroom 310	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	310	Classroom 310	W1	Plaster	Grey	Cracking	4	17.1	Positive
1	3	310	Classroom 310	W2	Plaster	Grey	None	0	4.9	Positive
1	3	310	Classroom 310	W3	Plaster	Grey	None	0	18.3	Positive
1	3	310	Classroom 310	W4	Plaster	Grey	None	0	16.3	Positive
1	3	310	Classroom 310	Ceiling	Plaster	White	Flaking	10	18.5	Positive
1	3	311	Classroom 311	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	311	Classroom 311	W1	Plaster	Green	Cracking	2	17	Positive
1	3	311	Classroom 311	W2	Plaster	Green	Cracking	3	12.9	Positive
1	3	311	Classroom 311	W3	Plaster	Green	None	0	0	Negative
1	3	311	Classroom 311	W4	Plaster	Green	Chipping	2	15.4	Positive
1	3	311	Classroom 311	Ceiling	Plaster	White	Flaking	10	26.4	Positive
1	3	312	Classroom 312	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	312	Classroom 312	W1	Plaster	Green	Cracking	1	18.2	Positive
1	3	312	Classroom 312	W2	Sheetrock	Green	None	0	0.04	Negative
1	3	312	Classroom 312	W3	Plaster	Green	None	0	0.07	Negative
1	3	312	Classroom 312	W4	Sheetrock	Green	None	0	0.02	Negative
1	3	312	Classroom 312	Ceiling	Plaster	White	Cracking	10	20	Positive
1	3	313	Classroom 313	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	313	Classroom 313	W1	Plaster	Green	Flaking	2	20.1	Positive
1	3	313	Classroom 313	W2	Sheetrock	Green	None	0	0.02	Negative
1	3	313	Classroom 313	W3	Plaster	Green	None	0	18.6	Positive
1	3	313	Classroom 313	W4	Sheetrock	Green	None	0	0	Negative
1	3	313	Classroom 313	Ceiling	Plaster	White	Flaking	10	17.9	Positive
1	3	313A	Counselor's Suite Waiting Area	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313A	Counselor's Suite Waiting Area	W1	Sheetrock	Green	None	0	0	Negative
1	3	313A	Counselor's Suite Waiting Area	W2	Sheetrock	Green	None	0	0	Negative
1	3	313A	Counselor's Suite Waiting Area	W3	Brick	Green	None	0	0.13	Negative
1	3	313A	Counselor's Suite Waiting Area	W4	Brick	Green	None	0	0.02	Negative
1	3	313A	Counselor's Suite Waiting Area	Ceiling	Plaster	White	Flaking	10	19.4	Positive
1	3	313C	Counselor's Suite - Left Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313C	Counselor's Suite - Left Office	W1	Brick	Grey	None	0	0.05	Negative
1	3	313C	Counselor's Suite - Left Office	W2	Sheetrock	Grey	None	0	0	Negative
1	3	313C	Counselor's Suite - Left Office	W3	Sheetrock	Grey	None	0	0	Negative
1	3	313C	Counselor's Suite - Left Office	W4	Brick	Grey	None	0	0.07	Negative



Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	313C	Counselor's Suite - Left Office	Ceiling	Plaster	White	Flaking	10	23.7	Positive
1	3	313D	Counselor's Suite - Right Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313D	Counselor's Suite - Right Office	W1	Brick	Green	None	0	0.11	Negative
1	3	313D	Counselor's Suite - Right Office	W2	Sheetrock	Green	None	0	0	Negative
1	3	313D	Counselor's Suite - Right Office	W3	Sheetrock	Green	None	0	0	Negative
1	3	313D	Counselor's Suite - Right Office	W4	Sheetrock	Green	None	0	0	Negative
1	3	313D	Counselor's Suite - Right Office	Ceiling	Plaster	White	Flaking	10	23.1	Positive
1	3	313B	Book Closet across from Classroom 312	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	313B	Book Closet across from Classroom 312	W1	Brick	Green/White	None	0	0.03	Negative
1	3	313B	Book Closet across from Classroom 312	W2	Brick	Green/White	None	0	0.18	Negative
1	3	313B	Book Closet across from Classroom 312	W3	Brick	Green/White	None	0	0.05	Negative
1	3	313B	Book Closet across from Classroom 312	W4	Brick	Green/White	None	0	0.12	Negative
1	3	313B	Book Closet across from Classroom 312	Ceiling	Plaster	White	Flaking	10	18.4	Positive
1	3	314	Classroom 314	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314	Classroom 314	W1	Plaster	Green	Flaking	10	18.2	Positive
1	3	314	Classroom 314	W2	Sheetrock	Green	None	0	0.03	Negative
1	3	314	Classroom 314	W3	Plaster	Green	None	0	18.7	Positive
1	3	314	Classroom 314	W4	Plaster	Green	None	0	21.3	Positive
1	3	314	Classroom 314	Ceiling	Plaster	White	Flaking	10	19.3	Positive
1	3	315	Teacher's Lounge room 315	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	315	Teacher's Lounge room 315	W1	Plaster	Green	Chipping	2	21.6	Positive
1	3	315	Teacher's Lounge room 315	W2	Plaster	Green	Chipping	1	14.6	Positive
1	3	315	Teacher's Lounge room 315	W3	Sheetrock	Green	None	0	0	Negative
1	3	315	Teacher's Lounge room 315	W4	Plaster	Green	None	0	15.1	Positive
1	3	315	Teacher's Lounge room 315	Ceiling	Plaster	White	Flaking	5	13.6	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	Floor	Concrete	Grey	Friction	4	1.6	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	W1	Plaster	Green	Flaking	2	12.2	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	W2	Plaster	Green	None	0	17.5	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	W3	Plaster	Green	None	0	11.9	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	W4	Plaster	Green	Moisture Damage	20	13.3	Positive
1	3	315A	Restroom in Teacher's Lounge room 315	Ceiling	Plaster	White	Flaking	5	18.1	Positive
1	3	314B	Teacher Lounge next to Girl's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314B	Teacher Lounge next to Girl's Restroom	W1	Brick	Green	None	0	0.16	Negative
1	3	314B	Teacher Lounge next to Girl's Restroom	W2	Brick	Green	None	0	0.08	Negative
1	3	314B	Teacher Lounge next to Girl's Restroom	W3	Brick	Green	None	0	0.02	Negative
1	3	314B	Teacher Lounge next to Girl's Restroom	W4	Sheetrock	Green	None	0	0	Negative
1	3	314B	Teacher Lounge next to Girl's Restroom	Ceiling	Plaster	White	Flaking	10	17.5	Positive
1	3	316	Classroom 316	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	316	Classroom 316	W1	Plaster	Green	None	0	11.6	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	316	Classroom 316	W2	Plaster	Green	Cracking	15	15.4	Positive
1	3	316	Classroom 316	W3	Plaster	Green	None	0	16.4	Positive
1	3	316	Classroom 316	W4	Plaster	Green	None	0	12.5	Positive
1	3	316	Classroom 316	Ceiling	Plaster	White	Flaking	10	18.5	Positive
1	3	317	Classroom 317	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	317	Classroom 317	W1	Plaster	Green	None	0	16.3	Positive
1	3	317	Classroom 317	W2	Plaster	Green	None	0	9.5	Positive
1	3	317	Classroom 317	W3	Plaster	Green	None	0	12.6	Positive
1	3	317	Classroom 317	W4	Plaster	Green	None	0	16.7	Positive
1	3	317	Classroom 317	Ceiling	Plaster	White	Flaking	12	19.1	Positive
1	3	318	Classroom 318	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	318	Classroom 318	W1	Plaster	Green	Flaking	3	13.3	Positive
1	3	318	Classroom 318	W2	Plaster	Green	None	0	9.4	Positive
1	3	318	Classroom 318	W3	Plaster	Green	None	0	10.6	Positive
1	3	318	Classroom 318	W4	Plaster	Green	None	0	12.6	Positive
1	3	318	Classroom 318	Ceiling	Plaster	White	Flaking	10	18	Positive
1	3	319	Classroom 319	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	319	Classroom 319	W1	Plaster	Green	None	0	2	Positive
1	3	319	Classroom 319	W2	Plaster	Green	None	0	14.3	Positive
1	3	319	Classroom 319	W3	Plaster	Black	None	0	16.8	Positive
1	3	319	Classroom 319	W4	Plaster	Black	None	0	13.7	Positive
1	3	319	Classroom 319	Ceiling	Plaster	White	Cracking	10	20.6	Positive
1	3	320	Classroom 320	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	320	Classroom 320	W1	Plaster	Purple	Friction	1	14.3	Positive
1	3	320	Classroom 320	W2	Plaster	Purple	None	0	12.7	Positive
1	3	320	Classroom 320	W3	Plaster	Purple	None	0	13.9	Positive
1	3	320	Classroom 320	W4	Plaster	Purple	None	0	12.9	Positive
1	3	320	Classroom 320	Ceiling	Plaster	White	Flaking	10	18.7	Positive
1	3	321	Classroom 321	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	321	Classroom 321	W1	Plaster	Green	None	0	15.4	Positive
1	3	321	Classroom 321	W2	Plaster	Green	None	0	18.1	Positive
1	3	321	Classroom 321	W3	Plaster	Green	None	0	18.6	Positive
1	3	321	Classroom 321	W4	Plaster	Green	None	0	14.5	Positive
1	3	321	Classroom 321	Ceiling	Plaster	White	Flaking	7	16.3	Positive
1	3	322	Classroom 322	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	322	Classroom 322	W1	Plaster	Green	None	0	16.9	Positive
1	3	322	Classroom 322	W2	Plaster	Green	None	0	17.3	Positive
1	3	322	Classroom 322	W3	Plaster	Green	None	0	20	Positive
1	3	322	Classroom 322	W4	Plaster	Green	None	0	18.4	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	322	Classroom 322	Ceiling	Plaster	White	Cracking	10	16.3	Positive
1	3	323	Classroom 323	Floor	Wood	N/A	N/A	0	N/A	N/A
1	3	323	Classroom 323	W1	Plaster	Blue	None	0	22.1	Positive
1	3	323	Classroom 323	W2	Plaster	Blue	None	0	20.2	Positive
1	3	323	Classroom 323	W3	Plaster	Blue	None	0	20.7	Positive
1	3	323	Classroom 323	W4	Plaster	Blue	None	0	16.5	Positive
1	3	323	Classroom 323	Ceiling	Plaster	White	Flaking	20	19.5	Positive
1	3	302C	Boy's Restroom across from Classroom 301/302	Floor	Concrete	Grey	None	0	0.25	Negative
1	3	302C	Boy's Restroom across from Classroom 301/302	W1	Plaster	Green	Moisture Damage	8	14.7	Positive
1	3	302C	Boy's Restroom across from Classroom 301/302	W2	Plaster	Green	Cracking	5	15.6	Positive
1	3	302C	Boy's Restroom across from Classroom 301/302	W3	Plaster	Green	Chipping	2	18.1	Positive
1	3	302C	Boy's Restroom across from Classroom 301/302	W4	Plaster	Green	Moisture Damage	8	13.9	Positive
1	3	302C	Boy's Restroom across from Classroom 301/302	Ceiling	Plaster	White	Flaking	10	21.5	Positive
1	3	302Q	Custodial Closet next to Boy's Restroom	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	302Q	Custodial Closet next to Boy's Restroom	W1	Plaster	White	None	0	13.7	Positive
1	3	302Q	Custodial Closet next to Boy's Restroom	W2	Plaster	White	None	0	18.9	Positive
1	3	302Q	Custodial Closet next to Boy's Restroom	W3	Plaster	White	None	0	10.7	Positive
1	3	302Q	Custodial Closet next to Boy's Restroom	W4	Plaster	White	None	0	14.3	Positive
1	3	302Q	Custodial Closet next to Boy's Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	PC302Q	Pipe Chase in Custodial Closet next to Boy's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303A	Computer Lab Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Computer Lab Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Computer Lab Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Computer Lab Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Computer Lab Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303A	Computer Lab Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	314Q	Girl's Restroom across from Classroom 314	Floor	Concrete	Grey	Friction	5	3.2	Positive
1	3	314Q	Girl's Restroom across from Classroom 314	W1	Plaster	Green	Moisture Damage	12	22	Positive
1	3	314Q	Girl's Restroom across from Classroom 314	W2	Plaster	Green	Moisture Damage	15	14.9	Positive
1	3	314Q	Girl's Restroom across from Classroom 314	W3	Plaster	Green	Flaking	2	17.7	Positive
1	3	314Q	Girl's Restroom across from Classroom 314	W4	Plaster	Green	None	0	16.1	Positive
1	3	314Q	Girl's Restroom across from Classroom 314	Ceiling	Plaster	Green	Flaking	40	17.7	Positive
1	3	H319	Hallway between Rooms 316 and 323	Floor	Concrete	Green	None	0	0	Negative
1	3	H319	Hallway between Rooms 316 and 323	W1	Plaster	Green/White	None	0	18.4	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	H319	Hallway between Rooms 316 and 323	W2	Plaster	Green/White	Flaking	15	20.1	Positive
1	3	H319	Hallway between Rooms 316 and 323	W3	Plaster	Green/White	None	0	18.9	Positive
1	3	H319	Hallway between Rooms 316 and 323	W4	Plaster	Green/White	Chipping	10	16.9	Positive
1	3	H319	Hallway between Rooms 316 and 323	Ceiling	Plaster	white	Flaking	45	24.2	Positive
1	3	H320	Hallway between Rooms 304 and 311	Floor	Concrete	Green	None	0	0	Negative
1	3	H320	Hallway between Rooms 304 and 311	W1	Plaster	Green/White	Flaking	5	23.4	Positive
1	3	H320	Hallway between Rooms 304 and 311	W2	Plaster	Green/White	Cracking	100	16	Positive
1	3	H320	Hallway between Rooms 304 and 311	W3	Plaster	Green/White	Flaking	5	17.2	Positive
1	3	H320	Hallway between Rooms 304 and 311	W4	Plaster	Green/White	Chipping	25	20.6	Positive
1	3	H320	Hallway between Rooms 304 and 311	Ceiling	Plaster	White	Flaking	50	26.7	Positive
1	3	H316	Hallway from Classroom 301 to Classroom 304	Floor	Concrete	Green	None	0	0	Negative
1	3	H316	Hallway from Classroom 301 to Classroom 304	W1	Plaster	Green/White	None	0	23.8	Positive
1	3	H316	Hallway from Classroom 301 to Classroom 304	W2	Plaster	Green/White	None	0	16.9	Positive
1	3	H316	Hallway from Classroom 301 to Classroom 304	W3	Plaster	Green/White	None	0	18.4	Positive
1	3	H316	Hallway from Classroom 301 to Classroom 304	W4	Plaster	Green/White	None	0	15.9	Positive
1	3	H316	Hallway from Classroom 301 to Classroom 304	Ceiling	Plaster	white	Flaking	25	20.4	Positive
1	3	H315	Hallway between Rooms 312 and 314	Floor	Concrete	Green	None	0	0.02	Negative
1	3	H315	Hallway between Rooms 312 and 314	W1	Plaster	Green/White	Flaking	2	17.6	Positive
1	3	H315	Hallway between Rooms 312 and 314	W2	Plaster	Green/White	Flaking	10	27.2	Positive
1	3	H315	Hallway between Rooms 312 and 314	W3	Plaster	Green/White	Flaking	5	13.6	Positive
1	3	H315	Hallway between Rooms 312 and 314	W4	Plaster	Green/White	Flaking	18	21.4	Positive
1	3	H315	Hallway between Rooms 312 and 314	Ceiling	Plaster	White	Flaking	20	23.9	Positive
1	3	S31	Southwest Stairwell across from Classroom 314	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	S31	Southwest Stairwell across from Classroom 314	W1	Plaster	White	Flaking	3	23.6	Positive
1	3	S31	Southwest Stairwell across from Classroom 314	W2	Plaster	White	None	0	17.2	Positive
1	3	S31	Southwest Stairwell across from Classroom 314	W3	Plaster	White	None	0	17.7	Positive
1	3	S31	Southwest Stairwell across from Classroom 314	W4	Plaster	White	Flaking	20	19.8	Positive
1	3	S31	Southwest Stairwell across from Classroom 314	Ceiling	Plaster	White	Flaking	30	18.2	Positive
1	3	S32	Northeast Stairwell across from Classroom 301	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	S32	Northeast Stairwell across from Classroom 301	W1	Plaster	White	Flaking	15	11.2	Positive
1	3	S32	Northeast Stairwell across from Classroom 301	W2	Plaster	White	Flaking	30	18.3	Positive
1	3	S32	Northeast Stairwell across from Classroom 301	W3	Plaster	White	None	0	13.6	Positive
1	3	S32	Northeast Stairwell across from Classroom 301	W4	Plaster	White	Cracking	10	14.1	Positive
1	3	S32	Northeast Stairwell across from Classroom 301	Ceiling	Plaster	White	Flaking	30	19.4	Positive
1	3	S310	Southeast Stairwell across from Classroom 303	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	S310	Southeast Stairwell across from Classroom 303	W1	Plaster	White	Flaking	5	20	Positive
1	3	S310	Southeast Stairwell across from Classroom 303	W2	Plaster	White	None	0	17.3	Positive
1	3	S310	Southeast Stairwell across from Classroom 303	W3	Plaster	White	None	0	19.5	Positive
1	3	S310	Southeast Stairwell across from Classroom 303	W4	Plaster	White	None	0	13.8	Positive

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	S310	Southeast Stairwell across from Classroom 303	Ceiling	Plaster	White	Flaking	20	23.7	Positive
1	3	S37	Northwest Stairwell across from Classroom 312	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	S37	Northwest Stairwell across from Classroom 312	W1	Plaster	White	Flaking	12	19.4	Positive
1	3	S37	Northwest Stairwell across from Classroom 312	W2	Plaster	White	None	0	22.1	Positive
1	3	S37	Northwest Stairwell across from Classroom 312	W3	Plaster	White	None	0	21	Positive
1	3	S37	Northwest Stairwell across from Classroom 312	W4	Plaster	White	None	0	17.9	Positive
1	3	S37	Northwest Stairwell across from Classroom 312	Ceiling	Plaster	White	None	0	20.6	Positive
1	B	1	Boiler Room	Floor	Concrete	Grey	None	0	0	Negative
1	B	1	Boiler Room	W1	Concrete	White/Tan	None	0	0	Negative
1	B	1	Boiler Room	W2	Concrete	White/Tan	None	0	0	Negative
1	B	1	Boiler Room	W3	Brick	White/Tan	None	0	0	Negative
1	B	1	Boiler Room	W4	Concrete	White/Tan	None	0	0	Negative
1	B	1	Boiler Room	Ceiling	Concrete	White	No Access	no access	No Access	No Access
1	B	2	Electrical Room	Floor	Concrete	Grey	None	0	0.14	Negative
1	B	2	Electrical Room	W1	Concrete	White/Tan	None	0	0	Negative
1	B	2	Electrical Room	W2	Brick	White/Tan	None	0	0	Negative
1	B	2	Electrical Room	W3	Concrete	White/Tan	None	0	0	Negative
1	B	2	Electrical Room	W4	Brick	White/Tan	None	0	0	Negative
1	B	2	Electrical Room	Ceiling	Concrete	White	No Access	No Access	No Access	No Access
1	B	3	Storage/Pump Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	3	Storage/Pump Room	W1	Brick	White	None	0	0	Negative
1	B	3	Storage/Pump Room	W2	Brick	White	None	0	0	Negative
1	B	3	Storage/Pump Room	W3	Brick	White	None	0	0	Negative
1	B	3	Storage/Pump Room	W4	Brick	White	None	0	0	Negative
1	B	3	Storage/Pump Room	Ceiling	Concrete	White	None	0	0	Negative
1	B	4	Former Coal Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	4	Former Coal Storage	W1	Concrete	White/Tan	None	0	0	Negative
1	B	4	Former Coal Storage	W2	Concrete	White/Tan	None	0	0	Negative
1	B	4	Former Coal Storage	W3	Concrete	White/Tan	None	0	0	Negative
1	B	4	Former Coal Storage	W4	Concrete	White/Tan	None	0	0	Negative
1	B	4	Former Coal Storage	Ceiling	Concrete	white	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Blower Room Adjacent to Electrical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	5B	North Fan Room	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	5B	North Fan Room	W1	Brick	White	None	0	0	Negative

			Dates: 10/3/2022- 12/21/2022	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Michael A Martin-#006416	1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year						
			Inspection Company: Criterion labs	4725 Fairmount Avenue, Philadelphia, PA 19139						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	B	5B	North Fan Room	W2	Brick	White	None	0	0	Negative
1	B	5B	North Fan Room	W3	Brick	White	None	0	0	Negative
1	B	5B	North Fan Room	W4	Brick	White	None	0	0	Negative
1	B	5B	North Fan Room	Ceiling	Concrete	White	No Access	No Access	No Access	No Access
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	W1	Concrete	White	None	0	0	Negative
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	W2	Concrete	White	None	0	0	Negative
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	W3	Concrete	White	None	0	0	Negative
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	W4	Concrete	White	None	0	0	Negative
1	B	6	Hallway/Air Intake Passage from Electrical Room to North Blower Room	Ceiling	Concrete	White	None	0	0	Negative
1	A	AT	Attic Third Floor - South East Side Door	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic Third Floor - South East Side Door	W1	Concrete	White	None	0	0	Negative
1	A	AT	Attic Third Floor - South East Side Door	W2	Concrete	White	None	0	0	Negative
1	A	AT	Attic Third Floor - South East Side Door	W3	Concrete	White	None	0	0	Negative
1	A	AT	Attic Third Floor - South East Side Door	W4	Concrete	White	None	0	0	Negative
1	A	AT	Attic Third Floor - South East Side Door	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT1	North Side Attic above third floor	Floor	Concrete	N/A	N/A	0	0	N/A
1	A	AT1	North Side Attic above third floor	W1	Brick	White	None	0	0	Negative
1	A	AT1	North Side Attic above third floor	W2	Plaster	White	None	0	0	Negative
1	A	AT1	North Side Attic above third floor	W3	Brick	White	None	0	0	Negative
1	A	AT1	North Side Attic above third floor	W4	Plaster	White	None	0	0	Negative
1	A	AT1	North Side Attic above third floor	Ceiling	Concrete	N/A	N/A	0	0	N/A
1	A	AT2	Southside Attic	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	A	AT2	Southside Attic	W1	Brick	White	None	0	0	Negative
1	A	AT2	Southside Attic	W2	Brick	White	None	0	0	Negative
1	A	AT2	Southside Attic	W3	Brick	White	None	0	0	Negative
1	A	AT2	Southside Attic	W4	Plaster	White	None	0	0	Negative
1	A	AT2	Southside Attic	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS2	South Side Attic crawlspace near Fan Room	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF
										(positive/negative)
1	C	CS1	North Side Attic crawlspace	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS1	North Side Attic crawlspace	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS1	North Side Attic crawlspace	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS1	North Side Attic crawlspace	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS1	North Side Attic crawlspace	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS1	North Side Attic crawlspace	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	C	CS3	Crawlspace under Auditorium Balcony Seating	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	302C	3rd Floor Boy's Restroom	W1	Brick	Tan	None	0	0	Negative
1	3	302C	3rd Floor Boy's Restroom	W2	Brick	Tan	None	0	0	Negative
1	3	302C	3rd Floor Boy's Restroom	W3	Brick	Tan	None	0	0	Negative
1	3	302C	3rd Floor Boy's Restroom	W4	Brick	Tan	None	0	0	Negative
1	3	314Q	3rd Floor Girl's Restroom	W1	Brick	Tan	None	0	0	Negative
1	3	314Q	3rd Floor Girl's Restroom	W2	Brick	Tan	None	0	0	Negative
1	3	314Q	3rd Floor Girl's Restroom	W3	Brick	Tan	None	0	0	Negative
1	3	314Q	3rd Floor Girl's Restroom	W4	Brick	Tan	None	0	0	Negative
1	2	201R	2nd Floor Boy's Restroom	W1	Brick	Tan	None	0	0	Negative
1	2	201R	2nd Floor Boy's Restroom	W2	Brick	Tan	None	0	0	Negative
1	2	201R	2nd Floor Boy's Restroom	W3	Brick	Tan	None	0	0	Negative
1	2	201R	2nd Floor Boy's Restroom	W4	Brick	Tan	None	0	0	Negative
1	2	212B	2nd Floor Girl's Restroom	W1	Brick	Tan	None	0	0	Negative
1	2	212B	2nd Floor Girl's Restroom	W2	Brick	Tan	None	0	0	Negative
1	2	212B	2nd Floor Girl's Restroom	W3	Brick	Tan	None	0	0	Negative
1	2	212B	2nd Floor Girl's Restroom	W4	Brick	Tan	None	0	0	Negative
1	1	102B	1st Floor Boy's Restroom	W1	Brick	Tan	None	0	0	Negative
1	1	102B	1st Floor Boy's Restroom	W2	Brick	Tan	None	0	0	Negative
1	1	102B	1st Floor Boy's Restroom	W3	Brick	Tan	None	0	0	Negative
1	1	102B	1st Floor Boy's Restroom	W4	Brick	Tan	None	0	0	Negative
1	1	110B	1st Floor Girl's Restroom	W1	Brick	Tan	None	0	0	Negative
1	1	110B	1st Floor Girl's Restroom	W2	Brick	Tan	None	0	0	Negative
1	1	110B	1st Floor Girl's Restroom	W3	Brick	Tan	None	0	0	Negative
1	1	110B	1st Floor Girl's Restroom	W4	Brick	Tan	None	0	0	Negative
1	1	109	Classroom 109	Radiator	Metal	Silver	None	0	0.08	Negative
1	1	110B	1st Floor Girl's Restroom	Radiator	Metal	Silver	None	0	0.17	Negative

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	1	110	school store room 110 radiator	Radiator	Metal	Silver	None	0	0.09	Negative
1	1	107	Classroom 107	Radiator	Metal	Silver	None	0	0.17	Negative
1	1	106	Classroom 106	Radiator	Metal	Silver	None	0	2.4	Positive
1	1	108A	Storage 108A	Radiator	Metal	Green	None	0	0	Negative
1	1	108B	Storage/Faculty 108B	Radiator	Metal	Tan	None	0	0.12	Negative
1	1	110	School Store Room 110	Radiator	Metal	Silver	None	0	0.09	Negative
1	1	115	South Cafeteria	Radiator	Metal	Silver	None	0	2	Positive
1	3	S310	southeast Stairwell across from Classroom 303	Door Frame	Metal	Green	None	0	0	Negative
1	3	S31	Southwest Stairwell across from Classroom 314	Door Frame	Metal	Green	None	0	0	Negative
1	3	S32	Northeast Stairwell across from Classroom 301	Door Frame	Metal	Green	None	0	0	Negative
1	3	S37	northwest Stairwell across from Classroom 312	Door Frame	Metal	Green	None	0	0	Negative
1	2	S210	southeast Stairwell across from Classroom 203	Door Frame	Metal	Green	None	0	0	Negative
1	2	S210	southwest Stairwell across from Classroom 213	Door Frame	Metal	Green	None	0	0	Negative
1	2	S22	northeast Stairwell across from Classroom 201	Door Frame	Metal	Green	None	0	0	Negative
1	2	S27	northwest Stairwell across from Classroom 211	Door Frame	Metal	Green	None	0	0	Negative
1	3	S325	Fire Tower A 3rd Floor	Door Frame	Metal	Green	None	0	0	Negative
1	3	S323	Fire Tower B 3rd Floor	Door Frame	Metal	Green	None	0	0	Negative
1	2	S225	Fire Tower A 2nd Floor	Door Frame	Metal	Green	None	0	0	Negative
1	2	S223	Fire Tower B 2nd Floor	Door Frame	Metal	Green	None	0	0	Negative
1	3	301/302	Classroom 301/302	Door Frame	Wood	Brown	None	0	0.07	Negative
1	3	301/302	Classroom 301/302	Baseboard	Wood	Brown	None	0	0.03	Negative
1	3	301/302	Classroom 301/302	Window Frame	Wood	Brown	None	0	0	Negative
1	3	301/302	Classroom 301/302	Radiator	Metal	Silver	None	0	0.04	Negative
1	3	304	Classroom 304	Door Frame	Wood	Brown	None	0	0.03	Negative
1	3	304	Classroom 304	Baseboard	Wood	Brown	None	0	0.13	Negative
1	3	304	Classroom 304	Window Frame	Wood	Brown	None	0	0.08	Negative
1	3	304	Classroom 304	Radiator	Metal	Silver	None	0	0.17	Negative
1	3	306	Classroom 306	Door Frame	Wood	Brown	None	0	0.13	Negative
1	3	306	Classroom 306	Baseboard	Wood	Brown	None	0	0.05	Negative
1	3	306	Classroom 306	Window Frame	Wood	Brown	None	0	0	Negative
1	3	306	Classroom 306	Radiator	Metal	Silver	None	0	0.14	Negative
1	3	308	classroom 308	Door Frame	Wood	Brown	None	0	0.11	Negative
1	3	308	classroom 308	Baseboard	Wood	Brown	None	0	0.06	Negative
1	3	308	classroom 308	Window Frame	Wood	Brown	None	0	0.02	Negative
1	3	308	classroom 308	Radiator	Metal	Silver	None	0	0.21	Negative
1	3	311	classroom 311	Door Frame	Wood	Brown	None	0	0.07	Negative
1	3	311	classroom 311	Baseboard	Wood	Brown	None	0	0.02	Negative
1	3	311	classroom 311	Window Frame	Wood	Brown	None	0	0	Negative
1	3	311	classroom 311	Radiator	Metal	Silver	None	0	0.18	Negative



Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF (positive/negative)
1	3	312	classroom 312	Door Frame	Wood	Brown	None	0	0.04	Negative
1	3	312	classroom 312	Baseboard	Wood	Brown	None	0	0	Negative
1	3	312	classroom 312	Window Frame	Wood	Brown	None	0	0	Negative
1	3	312	classroom 312	Radiator	Metal	Silver	None	0	0.3	Negative
1	3	314	Classroom 314	Door Frame	Wood	Brown	None	0	0.18	Negative
1	3	314	classroom 314	Baseboard	Wood	Brown	None	0	0.02	Negative
1	3	314	classroom 314	Window Frame	Wood	Brown	None	0	0	Negative
1	3	314	classroom 314	Radiator	Metal	Silver	None	0	0.22	Negative
1	3	317	classroom 317	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	317	classroom 317	Baseboard	Wood	Brown	None	0	0	Negative
1	3	317	classroom 317	Window Frame	Wood	Brown	None	0	0	Negative
1	3	317	classroom 317	Radiator	Metal	Silver	None	0	0.09	Negative
1	3	319	classroom 319	Door Frame	Wood	Brown	None	0	0.02	Negative
1	3	319	classroom 319	Baseboard	Wood	Brown	None	0	0.02	Negative
1	3	319	classroom 319	Window Frame	Wood	Brown	None	0	0	Negative
1	3	319	classroom 319	Radiator	Metal	Silver	None	0	0.11	Negative
1	3	321	classroom 321	Door Frame	Wood	Brown	None	0	0.12	Negative
1	3	321	classroom 321	Baseboard	Wood	Brown	None	0	0.07	Negative
1	3	321	classroom 321	Window Frame	Wood	Brown	None	0	0.02	Negative
1	3	321	classroom 321	Radiator	Metal	Silver	None	0	0.15	Negative
1	3	323	classroom 323	Door Frame	Wood	Brown	None	0	0.03	Negative
1	3	323	classroom 323	Baseboard	Wood	Brown	None	0	0	Negative
1	3	323	classroom 323	Window Frame	Wood	Brown	None	0	0	Negative
1	3	323	classroom 323	Radiator	Metal	Silver	None	0	0.07	Negative
1	2	201	classroom 201	Door Frame	Wood	Brown	None	0	0.05	Negative
1	2	201	classroom 201	Baseboard	Wood	Brown	None	0	0.02	Negative
1	2	201	classroom 201	Window Frame	Wood	Brown	None	0	0	Negative
1	2	201	classroom 201	Radiator	Metal	Silver	None	0	0.07	Negative
1	2	201B	classroom 203A	Door Frame	Wood	Brown	None	0	0.11	Negative
1	2	201B	classroom 203A	Baseboard	Wood	Brown	None	0	0	Negative
1	2	201B	classroom 203A	Window Frame	Wood	Brown	None	0	0	Negative
1	2	201B	classroom 203A	Radiator	Metal	Silver	None	0	0.17	Negative
1	2	203	classroom 203	Door Frame	Wood	Brown	None	0	0	Negative
1	2	203	classroom 203	Baseboard	Wood	Brown	None	0	0	Negative
1	2	203	classroom 203	Window Frame	Wood	Brown	None	0	0	Negative
1	2	203	classroom 203	Radiator	Metal	Silver	None	0	0.02	Negative
1	2	211	classroom 211	Door Frame	Wood	Brown	None	0	0.09	Negative
1	2	211	classroom 211	Baseboard	Wood	Brown	None	0	0.03	Negative
1	2	211	classroom 211	Window Frame	Wood	Brown	None	0	0	Negative

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF
										(positive/negative)
1	2	211	classroom 211	Radiator	Metal	Silver	None	0	0.03	Negative
1	2	212	classroom 212	Door Frame	Wood	Brown	None	0	0	Negative
1	2	212	classroom 212	Baseboard	Wood	Brown	None	0	0	Negative
1	2	212	classroom 212	Window Frame	Wood	Brown	None	0	0	Negative
1	2	212	classroom 212	Radiator	Metal	Silver	None	0	0.07	Negative
1	2	217	classroom 217	Door Frame	Wood	Brown	None	0	0.06	Negative
1	2	217	classroom 217	Baseboard	Wood	Brown	None	0	0.04	Negative
1	2	217	classroom 217	Window Frame	Wood	Brown	None	0	0	Negative
1	2	217	classroom 217	Radiator	Metal	Silver	None	0	0.13	Negative
1	2	218	classroom 218	Door Frame	Wood	Brown	None	0	0.02	Negative
1	2	218	classroom 218	Baseboard	Wood	Brown	None	0	0	Negative
1	2	218	classroom 218	Window Frame	Wood	Brown	None	0	0	Negative
1	2	218	classroom 218	Radiator	Metal	Silver	None	0	0.09	Negative
1	2	220	classroom 220	Door Frame	Wood	Brown	None	0	0.07	Negative
1	2	220	classroom 220	Baseboard	Wood	Brown	None	0	0.02	Negative
1	2	220	classroom 220	Window Frame	Wood	Brown	None	0	0	Negative
1	2	220	classroom 220	Radiator	Metal	Silver	None	0	0.07	Negative
1	2	221	classroom 221	Door Frame	Wood	Brown	None	0	0.03	Negative
1	2	221	classroom 221	Baseboard	Wood	Brown	None	0	0	Negative
1	2	221	classroom 221	Window Frame	Wood	Brown	None	0	0	Negative
1	2	221	classroom 221	Radiator	Metal	Silver	None	0	0.12	Negative
1	1	108A	Storage 108A	Door Frame	Wood	Brown	None	0	0	Negative
1	1	108A	Storage 108A	Baseboard	Wood	Brown	None	0	0	Negative
1	1	108A	Storage 108A	Window Frame	Wood	Brown	None	0	0	Negative
1	1	108A	Storage 108A	Radiator	Metal	Silver	None	0	0.02	Negative
1	1	108B	Storage/Faculty 108B	Door Frame	Wood	Brown	None	0	0.05	Negative
1	1	108B	Storage/Faculty 108B	Baseboard	Wood	Brown	None	0	0	Negative
1	1	108B	Storage/Faculty 108B	Window Frame	Wood	Brown	None	0	0	Negative
1	1	108B	Storage/Faculty 108B	Radiator	Metal	Silver	None	0	0.15	Negative
1	1	101	Classroom 101	Door Frame	Wood	Brown	None	0	0.03	Negative
1	1	101	Classroom 101	Baseboard	Wood	Brown	None	0	0	Negative
1	1	101	Classroom 101	Window Frame	Wood	Brown	None	0	0.02	Negative
1	1	101	Classroom 101	Radiator	Metal	Silver	None	0	0.07	Negative
1	1	102	classroom 102	Door Frame	Wood	Brown	None	0	0	Negative
1	1	102	classroom 102	Baseboard	Wood	Brown	None	0	0	Negative
1	1	102	classroom 102	Window Frame	Wood	Brown	None	0	0	Negative
1	1	102	classroom 102	Radiator	Metal	Silver	None	0	0.12	Negative
1	1	106	classroom 106	Door Frame	Wood	Brown	None	0	0	Negative
1	1	106	classroom 106	Baseboard	Wood	Brown	None	0	0	Negative

Dates: 10/3/2022- 12/21/2022

**Lead-Safe Certification Assessment Report**

Inspector Name and Certificate Number:  
Michael A Martin-#006416

**1120/5090/1580 Parkway West HS/MYA @ Sulzberger Middle Year**

Inspection Company: Criterion labs

**4725 Fairmount Avenue, Philadelphia, PA 19139**

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading	XRF
										(positive/negative)
1	1	106	classroom 106	Window Frame	Wood	Brown	None	0	0	Negative
1	1	106	classroom 106	Radiator	Metal	Silver	None	0	0.14	Negative
1	1	107	classroom 107	Door Frame	Wood	Brown	None	0	0.05	Negative
1	1	107	classroom 107	Baseboard	Wood	Brown	None	0	0	Negative
1	1	107	classroom 107	Window Frame	Wood	Brown	None	0	0	Negative
1	1	107	classroom 107	Radiator	Metal	Silver	None	0	0.1	Negative
1	1	108	classroom 108	Door Frame	Wood	Brown	None	0	0.03	Negative
1	1	108	classroom 108	Baseboard	Wood	Brown	None	0	0.02	Negative
1	1	108	classroom 108	Window Frame	Wood	Brown	None	0	0	Negative
1	1	108	classroom 108	Radiator	Metal	Silver	None	0	0.1	Negative
1	1	109	classroom 109	Door Frame	Wood	Brown	None	0	0.05	Negative
1	1	109	classroom 109	Baseboard	Wood	Brown	None	0	0.07	Negative
1	1	109	classroom 109	Window Frame	Wood	Brown	None	0	0.02	Negative
1	1	114	classroom 109	Radiator	Metal	Silver	None	0	0.11	Negative
1	1	114	North Cafeteria	Door Frame	Wood	Brown	None	0	0	Negative
1	1	114	North Cafeteria	Baseboard	Wood	Brown	None	0	0	Negative
1	1	114	North Cafeteria	Window Frame	Wood	Brown	None	0	0	Negative
1	1	114	North Cafeteria	Radiator	Metal	Silver	None	0	0.03	Negative
1	1	115	South Cafeteria	Door Frame	Wood	Brown	None	0	0.05	Negative
1	1	115	South Cafeteria	Baseboard	Wood	Brown	None	0	0	Negative
1	1	115	South Cafeteria	Window Frame	Wood	Brown	None	0	0	Negative
1	1	115	South Cafeteria	Radiator	Metal	Silver	None	0	0.14	Negative
1	B	5B	North Fan room	Fan Unit	Metal	Silver	None	0	29.1	Positive
1	3	H319	Hallway between Rooms 316 and 323	Radiator	Metal	Silver	None	0	4.2	Positive
1	3	H319	Hallway between Rooms 316 and 323	Radiator	Metal	Silver	None	0	5.6	Positive
1	3	H319	Hallway between Rooms 316 and 323	Radiator	Metal	Silver	None	0	4.3	Positive
1	3	H319	Hallway between Rooms 316 and 323	Radiator	Metal	Silver	None	0	2.9	Positive
1	3	H320	Hallway between Rooms 304 and 311	Radiator	Metal	Silver	None	0	0.11	Negative
1	3	H320	Hallway between Rooms 304 and 311	Radiator	Metal	Silver	None	0	0.14	Negative
1	3	H320	Hallway between Rooms 304 and 311	Radiator	Metal	Silver	None	0	0.18	Negative
1	3	H320	Hallway between Rooms 304 and 311	Radiator	Metal	Silver	None	0	0.07	Negative