

		Lead-Safe Certification Assessment Report	
		The Workshop School	
		221 S. Hanson St, Philadelphia PA 19139	
		Dates: 8/28/2023 - 8/31/2023	
		Inspector Name and Certificate Number: CJ Karoly 006424	
		Inspection Company: Criterion Laboratories	
		On-Site Room Name	Component
	Space #		Substrate Material [1]
			Paint Color
			Description of Damage
			Damage Quantity [2]
			XRF Reading (mg/cm2)
			XRF (positive/negative) [3]
E			
I			
e			
m			
e			
n			
t			
1	107	Fire Pump Room inside Classroom beside Front Entrance Vestibule	W2
1	107	Fire Pump Room inside Classroom beside Front Entrance Vestibule	W3
1	107	Fire Pump Room inside Classroom beside Front Entrance Vestibule	W4
1	107	Fire Pump Room inside Classroom beside Front Entrance Vestibule	Ceiling
1	107	Fire Pump Room inside Classroom beside Front Entrance Vestibule	Floor
1	108	Storage Closet inside Woodshop	W1
1	108	Storage Closet inside Woodshop	W2
1	108	Storage Closet inside Woodshop	W3
1	108	Storage Closet inside Woodshop	W4
1	108	Storage Closet inside Woodshop	Ceiling
1	108	Storage Closet inside Woodshop	Floor
1	BE	Building Engineer's Office	W1
1	BE	Building Engineer's Office	W2
1	BE	Building Engineer's Office	W3
1	BE	Building Engineer's Office	W4
1	BE	Building Engineer's Office	Ceiling
1	BE	Building Engineer's Office	Floor
1	BE	Building Engineer's Office	W1
1	BE	Building Engineer's Office	W2
1	BE	Building Engineer's Office	W3
1	BE	Building Engineer's Office	W4
1	BE	Building Engineer's Office	Ceiling
1	BE	Building Engineer's Office	Floor
1	BE	Building Engineer's Office	W1
1	BE	Building Engineer's Office	W2
1	BE	Building Engineer's Office	W3
1	BE	Building Engineer's Office	W4
1	BE	Building Engineer's Office	Ceiling
1	BE	Building Engineer's Office	Floor
1	CAD/CAM	Computer Aided Drafting/Computer Aided Manufacturing	W1
1	CAD/CAM	Computer Aided Drafting/Computer Aided Manufacturing	W2

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
		On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E	I								
e	F								
m	I								
e	o								
n	o								
t	r								
1	1	Computer Aided Drafting/Computer Aided Manufacturing	W3	CMU	White	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	W4	Brick	White	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Ceiling	Concrete	Black	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Floor	Sheetrock	White	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Door	Metal	Blue	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Door Casing	Metal	Blue	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Duct	Metal	White	None	0	0	Negative
1	1	Computer Aided Drafting/Computer Aided Manufacturing	Pipe	Metal	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W1	Sheetrock	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W1	CMU	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W2	Sheetrock	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W2	Brick	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W3	Sheetrock	White	Flaking	100	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W3	CMU	White	None	0	0	Negative
1	1	Classroom beside Front Entrance Vestibule	W4	Sheetrock	White	None	0	0	Negative

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	CR1	Classroom beside Front Entrance Vestibule	Ceiling	Sheetrock	White	Flaking	50	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CR1	Classroom beside Front Entrance Vestibule	Window Casing	Wood	White	None	0	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Window Casing	Metal	Blue	None	0	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Door	Metal	Blue	None	0	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Door Casing	Metal	Blue	None	0	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Air Duct	Metal	White	None	0	0	Negative
1	CR1	Classroom beside Front Entrance Vestibule	Pipe	Metal	White	None	0	0	Negative
1	CR2	Classroom behind Staff Restroom	W1	CMU	Blue	None	0	0	Negative
1	CR2	Classroom behind Staff Restroom	W2	CMU	White	None	0	0	Negative
1	CR2	Classroom behind Staff Restroom	W3	Brick	Blue	Chipping	10	0	Negative
1	CR2	Classroom behind Staff Restroom	W4	Brick	White	Chipping	80	0	Negative
1	CR2	Classroom behind Staff Restroom	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	CR2	Classroom behind Staff Restroom	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	CR2	Classroom behind Staff Restroom	Door	Wood	Blue	None	0	0	Negative
1	CR2	Classroom behind Staff Restroom	Door Casing	Metal	Blue	Friction	5	0	Negative
1	CR2	Classroom behind Staff Restroom	Window Casing	Metal	Blue	None	0	0	Negative
1	CR3	Woodshop - Front Section	W1	CMU	White	None	0	0	Negative
1	CR3	Woodshop - Front Section	W2	Sheetrock	Blue	None	0	0	Negative
1	CR3	Woodshop - Front Section	W3	Brick	White	None	0	0	Negative
1	CR3	Woodshop - Front Section	W4	Sheetrock	White	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023									
		Inspector Name and Certificate Number: CJ Karoly 006424									
		Inspection Company: Criterion Laboratories									
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
E I e m e n t	1	CR3	Woodshop - Front Section	Ceiling	Sheetrock	White	None	0	0	Negative	
	1	CR3	Woodshop - Front Section	Floor	Concrete	Black	None	0	0	Negative	
	1	CR3	Woodshop - Front Section	Door	Wood	Blue	None	0	0	Negative	
	1	CR3	Woodshop - Front Section	Door Casing	Metal	Blue	None	0	0	Negative	
	1	CR3	Woodshop - Front Section	Air Duct	Metal	White	None	0	0	Negative	
	1	CR3	Woodshop - Front Section	Pipe	Metal	White	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	W1	Sheetrock	White	Holes	15	0	Negative	
	1	CR4	Woodshop - Rear Section	W2	Sheetrock	White	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	W2	Brick	White	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	W3	Brick	Red	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	W4	CMU	White	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	Ceiling	Sheetrock	White	None	0	0	Negative	
	1	CR4	Woodshop - Rear Section	Floor	Concrete	Yellow	None	None	0	1.5	Positive
	1	CR4	Woodshop - Rear Section	Door	Wood	Blue	None	None	0	0	Negative
	1	CR4	Woodshop - Rear Section	Door Casing	Metal	Blue	None	None	0	0	Negative
	1	CR4	Woodshop - Rear Section	Window Casing	Metal	Blue	None	None	0	0	Negative
	1	CR4	Woodshop - Rear Section	Air Duct	Metal	White	None	None	0	0	Negative
	1	CR5	Classroom inside Auto Shop	W1	CMU	White	None	None	0	0	Negative
	1	CR5	Classroom inside Auto Shop	W2	Brick	Green	Cracking	Cracking	15	3.4	Positive
	1	CR5	Classroom inside Auto Shop	W3	Brick	White	Cracking	Cracking	20	1.8	Positive
1	CR5	Classroom inside Auto Shop	W4	CMU	White	None	None	0	0	Negative	
1	CR5	Classroom inside Auto Shop	Ceiling	Sheetrock/Joint c	White	None	None	0	0	Negative	
1	CR5	Classroom inside Auto Shop	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	CR5	Classroom inside Auto Shop	Door	Metal	Blue	None	None	0	0	Negative	
1	CR5	Classroom inside Auto Shop	Door Casing	Metal	Blue	None	None	0	0	Negative	
1	CR5	Classroom inside Auto Shop	Window Casing	Metal	Blue	None	None	0	0	Negative	

		Dates: 8/28/2023 - 8/31/2023		Lead-Safe Certification Assessment Report					
		Inspector Name and Certificate Number: CJ Karoly 006424		The Workshop School					
		Inspection Company: Criterion Laboratories		221 S. Hanson St, Philadelphia PA 19139					
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	CR5	Classroom inside Auto Shop	Pipe	Metal	Green	None	0	0	Negative
1	CR6	Auto Shop	W1	Brick	Green	Chipping	20	0	Negative
1	CR6	Auto Shop	W1	CMU	Green	None	0	0	Negative
1	CR6	Auto Shop	W2	Sheetrock	White	None	0	0	Negative
1	CR6	Auto Shop	W2	Brick	White	Chipping	10	0	Negative
1	CR6	Auto Shop	W2	CMU	White	None	0	0	Negative
1	CR6	Auto Shop	W3	Sheetrock	White	None	0	0	Negative
1	CR6	Auto Shop	W3	Brick	White	Chipping	10	0	Negative
1	CR6	Auto Shop	W3	CMU	White	None	0	0	Negative
1	CR6	Auto Shop	W4	CMU	White	None	0	0	Negative
1	CR6	Auto Shop	Door	Metal	Blue	None	0	0	Negative
1	CR6	Auto Shop	Door Casing	Metal	Blue	Friction	2	0	Negative
1	CR6	Auto Shop	Window Casing	Metal	White	None	0	0	Negative
1	CR6	Auto Shop	Air Duct	Metal	White	None	0	0	Negative
1	CR6	Auto Shop	Ceiling	Sheetrock	White	None	0	0	Negative
1	CR6	Auto Shop	Floor	Concrete	Yellow	Friction	100	1.4	Positive
1	CR6	Auto Shop	Pipe	Metal	White	None	0	0	Negative
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	W1	Sheetrock	Black	None	0	0	Negative
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	W2	Sheetrock	Black	None	0	0	Negative
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	W3	Sheetrock	Black	None	0	0	Negative
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	W4	Sheetrock	Black	None	0	0	Negative
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	Ceiling	Sheetrock	Black	None	0	0	Negative

		Lead-Safe Certification Assessment Report							
		The Workshop School							
		221 S. Hanson St, Philadelphia PA 19139							
	Dates: 8/28/2023 - 8/31/2023								
	Inspector Name and Certificate Number: CJ Karoly 006424								
	Inspection Company: Criterion Laboratories								
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	CR6 A	Storage Closet in Auto Shop next to Ramp to Auto Body/Paint Shop	Floor	concrete	Unpainted	N/A	N/A	N/A	N/A
1	CR9	Classroom associated with Large Garage	W1	Sheetrock	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	W2	Brick	White	Flaking	15	0	Negative
1	CR9	Classroom associated with Large Garage	W3	Brick	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	W4	Sheetrock	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Floor	Concrete	Grey	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Floor	Concrete	Yellow	Friction	100	1.4	Positive
1	CR9	Classroom associated with Large Garage	Ceiling	Sheetrock	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Door	Metal	Blue	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Door Casing	Metal	Blue	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Door	Wood	Grey	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Door Casing	Wood	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Window Sill	Wood	White	None	0	0	Negative
1	CR9	Classroom associated with Large Garage	Air Duct	Metal	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	W1	CMU	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	W2	Brick	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	W3	CMU	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	W3	Brick	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	W4	Brick	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	Ceiling	Sheetrock	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	Floor	Concrete	Yellow	Friction	150	1.5	Positive
1	CR7	Auto Body Shop and Paint Area	Air Duct	Metal	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	Pipe	Metal	White	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	Handrail	Metal	Blue	None	0	0	Negative
1	CR7	Auto Body Shop and Paint Area	Door	Wood	Blue	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023								
		Inspector Name and Certificate Number: CJ Karoly 006424								
		Inspection Company: Criterion Laboratories								
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E I e m e n t	1	CR7	Auto Body Shop and Paint Area	Door Casing	Metal	Blue	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	W1	CMU	Grey	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	W2	CMU	White	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	W3	Brick	Grey	Flaking	100	0.2	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	W4	Brick	White	Flaking	120	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Ceiling	Sheetrock	White	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Door	Metal	Blue	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Door Casing	Metal	Blue	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Window Casing	Metal	Blue	None	0	0	Negative
	1	CR8	Classroom inside Auto Body Shop and Paint Area	Pipe	Metal	Blue	None	0	0	Negative
	1	EL1	Elevator	Elevator	W1	Metal	Unpainted	N/A	N/A	N/A
	1	EL1	Elevator	Elevator	W2	Metal	Unpainted	N/A	N/A	N/A
	1	EL1	Elevator	Elevator	W3	Metal	Unpainted	N/A	N/A	N/A
	1	EL1	Elevator	Elevator	W4	Metal	Unpainted	N/A	N/A	N/A
	1	EL1	Elevator	Elevator	Ceiling	Metal	Unpainted	N/A	N/A	N/A
1	EL1	Elevator	Elevator	Floor	Floor tile	Unpainted	N/A	N/A	N/A	
1	ELLEC1	Electrical Room	Electrical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	ELLEC1	Electrical Room	Electrical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
Item	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	ELEC1	Electrical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	ELEC1	Electrical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	ELEC1	Electrical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	ELEC1	Electrical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	H11	Hallway outside Main Entrance Vestibule	W1	CMU	Grey	None	0	0	Negative
1	H11	Hallway outside Main Entrance Vestibule	W2	CMU	Grey	None	0	0	Negative
1	H11	Hallway outside Main Entrance Vestibule	W3	CMU	Grey	None	0	0	Negative
1	H11	Hallway outside Main Entrance Vestibule	W4	CMU	Grey	None	0	0	Negative
1	H11	Hallway outside Main Entrance Vestibule	Ceiling	Sheetrock	White	None	0	0	Negative
1	H11	Hallway outside Main Entrance Vestibule	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	W1	CMU	White	None	0	0	Negative
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	W2	Brick	White	None	0	0	Negative
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	W3	CMU	White	None	0	0	Negative
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	W4	CMU	White	None	0	0	Negative
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	Ceiling	2x2 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	Door	Wood	Blue	None	0	0	Negative
1	M1	Men's Student Restroom in Auto Body Shop and Paint Area	Door Casing	Metal	Blue	None	0	0	Negative
1	MECH1	Elevator Machine Room	W1	CMU	Grey	None	0	0	Negative
1	MECH1	Elevator Machine Room	W2	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	MECH1	Elevator Machine Room	W3	Brick	Grey	None	0	0	Negative

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	MECH1	Elevator Machine Room	W4	CMU	Grey	None	0	0	Negative
1	MECH1	Elevator Machine Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	MECH1	Elevator Machine Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	MECH1	Elevator Machine Room	Door	Wood	Blue	None	0	0	Negative
1	MECH1	Elevator Machine Room	Door Casing	Metal	Blue	Friction	2	0	Negative
1	PC1	Pipe Chase in Auto Body/Paint Shop	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PC1	Pipe Chase in Auto Body/Paint Shop	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PC1	Pipe Chase in Auto Body/Paint Shop	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	PC1	Pipe Chase in Auto Body/Paint Shop	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	PC1	Pipe Chase in Auto Body/Paint Shop	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	PC1	Pipe Chase in Auto Body/Paint Shop	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	RR1-1	Staff Restroom beside Elevator Machine Room	W1	CMU	White	None	0	0	Negative
1	RR1-1	Staff Restroom beside Elevator Machine Room	W2	CMU	White	None	0	0	Negative
1	RR1-1	Staff Restroom beside Elevator Machine Room	W3	Brick	White	None	0	0	Negative
1	RR1-1	Staff Restroom beside Elevator Machine Room	W4	CMU	White	None	0	0	Negative
1	RR1-1	Staff Restroom beside Elevator Machine Room	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	RR1-1	Staff Restroom beside Elevator Machine Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	RR1-1	Staff Restroom beside Elevator Machine Room	Door	Wood	Blue	None	0	0	Negative
1	RR1-1	Staff Restroom beside Elevator Machine Room	Door Casing	Metal	Blue	None	0	0	Negative
1	SS	Sound Studio in Auto Shop	W1	Sheetrock	White	None	0	0	Negative
1	SS	Sound Studio in Auto Shop	W2	Sheetrock	White	None	0	0	Negative

		Dates: 8/28/2023 - 8/31/2023		Lead-Safe Certification Assessment Report									
		Inspector Name and Certificate Number: CJ Karoly 006424		The Workshop School									
		Inspection Company: Criterion Laboratories		221 S. Hanson St, Philadelphia PA 19139									
E	I	F	I	O	O	R	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	SS	Sound Studio in Auto Shop	W3	Sheetrock	White	None	0	0	Negative			
1	1	SS	Sound Studio in Auto Shop	W4	CMU	White	None	0	0	Negative			
1	1	SS	Sound Studio in Auto Shop	Ceiling	Sheetrock	White	None	0	0	Negative			
1	1	SS	Sound Studio in Auto Shop	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A			
1	1	ST1-1	Rear Storage Room in Auto Shop	W1	CMU	White	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	W2	Sheetrock	White	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	W3	Brick	Grey	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	W4	Brick	Grey	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	Ceiling	Sheetrock	White	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A			
1	1	ST1-1	Rear Storage Room in Auto Shop	Door	Wood	Blue	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	Door Casing	Metal	Blue	None	0	0	Negative			
1	1	ST1-1	Rear Storage Room in Auto Shop	Air Duct	Metal	White	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	W1	Sheetrock	White	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	W2	CMU	Grey	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	W3	Sheetrock	White	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	W4	Brick	Grey	Cracking	30	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	Ceiling	Sheetrock	White	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	Floor	Concrete	Grey	None	0	0	Negative			
1	1	ST1-1A	Office in Rear Storage Room in Auto Shop	Handrail	Metal	White	None	0	0	Negative			
1	1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	W1	CMU	Grey	None	0	0	Negative			
1	1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	W2	CMU	Grey	None	0	0	Negative			
1	1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	W3	Brick	Grey	None	0	0	Negative			

Lead-Safe Certification Assessment Report										
The Workshop School										
221 S. Hanson St, Philadelphia PA 19139										
		Dates: 8/28/2023 - 8/31/2023	Inspector Name and Certificate Number: CJ Karoly 006424	Inspection Company: Criterion Laboratories						
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	W4	CMU	Grey	None	0	0	Negative	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	Ceiling	Sheetrock	White	None	0	0	Negative	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	Door	Wood	Blue	None	0	0	Negative	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	Door Casing	Metal	Blue	Friction	4	0	Negative	
1	ST2	Storage Room in Auto Shop in Auto Body Shop and Paint Area	Duct	Metal	Blue	None	0	0	Negative	
1	VEST1	Main Entrance Vestibule	W1	Brick	White	None	0	0.1	Negative	
1	VEST1	Main Entrance Vestibule	W2	CMU	White	None	0	0	Negative	
1	VEST1	Main Entrance Vestibule	W3	CMU	White	None	0	0	Negative	
1	VEST1	Main Entrance Vestibule	W4	CMU	White	None	0	0	Negative	
1	VEST1	Main Entrance Vestibule	Door	Metal	Blue	None	0	0	Negative	
1	VEST1	Main Entrance Vestibule	Door Casing	Metal	Blue	Friction	2	0	Negative	
1	VEST1	Main Entrance Vestibule	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A	
1	VEST1	Main Entrance Vestibule	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	W1	CMU	White	None	0	0	Negative	
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	W2	CMU	White	None	0	0	Negative	
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	W3	CMU	White	None	0	0	Negative	
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	W4	Brick	White	None	0	0	Negative	
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	Ceiling	Sheetrock	White	None	0	0	Negative	

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	Door	Wood	Blue	None	0	0	Negative
1	W1	Women's Student Restroom in Auto Body Shop and Paint Area	Door Casing	Metal	Blue	Friction	<1	0	Negative
1	200	Main Office	W1	Sheetrock	White	None	0	0	Negative
1	200	Main Office	W2	Sheetrock	White	None	0	0	Negative
1	200	Main Office	W3	Sheetrock	White	None	0	0	Negative
1	200	Main Office	W4	Sheetrock	White	None	0	0	Negative
1	200	Main Office	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	200	Main Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	200	Main Office	Door	Wood	Grey	None	0	0	Negative
1	200	Main Office	Door Casing	Metal	Grey	None	0	0	Negative
1	200	Main Office	Window Casing	Metal	Grey	None	0	0	Negative
1	200A	IT MDF Closet inside Main Office	W1	Sheetrock	White	None	0	0	Negative
1	200A	IT MDF Closet inside Main Office	W2	Sheetrock	White	Peeling	5	0	Negative
1	200A	IT MDF Closet inside Main Office	W3	Sheetrock	White	None	0	0	Negative
1	200A	IT MDF Closet inside Main Office	W4	Sheetrock	White	None	0	0	Negative
1	200A	IT MDF Closet inside Main Office	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	200A	IT MDF Closet inside Main Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	200A	IT MDF Closet inside Main Office	Door	Wood	Yellow	None	0	0	Negative
1	200A	IT MDF Closet inside Main Office	Door Casing	Metal	Yellow	None	0	0	Negative
1	200B	Principal's Office inside Main Office	W1	Sheetrock	Grey	None	0	0	Negative
1	200B	Principal's Office inside Main Office	W2	Sheetrock	Grey	None	0	0	Negative
1	200B	Principal's Office inside Main Office	W3	Sheetrock	Grey	None	0	0	Negative
1	200B	Principal's Office inside Main Office	W4	Sheetrock	Grey	None	0	0	Negative

		Lead-Safe Certification Assessment Report							
		The Workshop School							
		221 S. Hanson St, Philadelphia PA 19139							
		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	200B	Principal's Office inside Main Office	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	200B	Principal's Office inside Main Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	200B	Principal's Office inside Main Office	Door	Wood	Grey	None	0	0	Negative
1	200B	Principal's Office inside Main Office	Door Casing	Metal	Grey	None	0	0	Negative
1	200C	Conference Room inside Main Office	W1	Sheetrock	Blue	None	0	0	Negative
1	200C	Conference Room inside Main Office	W2	Sheetrock	Blue	None	0	0	Negative
1	200C	Conference Room inside Main Office	W3	Sheetrock	Blue	None	0	0	Negative
1	200C	Conference Room inside Main Office	W4	Sheetrock	Blue	None	0	0	Negative
1	200C	Conference Room inside Main Office	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	200C	Conference Room inside Main Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	200C	Conference Room inside Main Office	Door	Wood	Yellow	None	0	0	Negative
1	200C	Conference Room inside Main Office	Door Casing	Metal	Yellow	None	0	0	Negative
1	201	Classroom 201	W1	Sheetrock	Blue	None	0	0	Negative
1	201	Classroom 201	W2	Sheetrock	Red	None	0	0	Negative
1	201	Classroom 201	W3	Sheetrock	White	None	0	0	Negative
1	201	Classroom 201	W4	Sheetrock	White	None	0	0	Negative
1	201	Classroom 201	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	201	Classroom 201	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	201	Classroom 201	Window Sill	Wood	White	None	0	0	Negative
1	201	Classroom 201	Door	Wood	Grey	None	0	0	Negative
1	201	Classroom 201	Door Casing	Metal	Grey	Friction	3	0	Negative
1	201A	Closet in Classroom 201	Window Sill	Wood	White	None	0	0	Negative
1	201A	Closet in Classroom 201	W1	Sheetrock	White	None	0	0	Negative
1	201A	Closet in Classroom 201	W2	Sheetrock	White	None	0	0	Negative
1	201A	Closet in Classroom 201	W3	CMU	Blue	None	0	0	Negative
1	201A	Closet in Classroom 201	W4	Sheetrock	White	None	0	0	Negative

		Dates: 8/28/2023 - 8/31/2023		Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: CJ Karoly 006424		The Workshop School						
		Inspection Company: Criterion Laboratories		221 S. Hanson St, Philadelphia PA 19139						
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	201A	Closet in Classroom 201	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A	
1	201A	Closet in Classroom 201	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	W1	Sheetrock	Grey	None	0	0	Negative	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	W2	CMU	Grey	None	0	0	Negative	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	W3	Brick	Grey	None	0	0	Negative	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	W4	CMU	Grey	None	0	0	Negative	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	Door	Wood	Grey	None	0	0	Negative	
1	202	Storage Closet beside Main Entrance Vestibule Stairway	Door Casing	Metal	Grey	None	0	0	Negative	
1	210	Classroom 210	W1	Sheetrock	Purple	None	0	0	Negative	
1	210	Classroom 210	W2	Brick	Green	Flaking	10	0.2	Negative	
1	210	Classroom 210	W3	Sheetrock	Purple	Holes	15	0	Negative	
1	210	Classroom 210	W4	Sheetrock	Purple	None	0	0	Negative	
1	210	Classroom 210	Ceiling	Sheetrock	White	Peeling	25	0	Negative	
1	210	Classroom 210	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	
1	210	Classroom 210	Door	Wood	Grey	None	0	0	Negative	
1	210	Classroom 210	Door Casing	Metal	Grey	None	0	0	Negative	
1	210A	Study Room beside Classroom 210	W1	Sheetrock	Purple	None	0	0	Negative	
1	210A	Study Room beside Classroom 210	W2	Brick	Green	None	0	0	Negative	
1	210A	Study Room beside Classroom 210	W3	Sheetrock	Purple	None	0	0	Negative	

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023								
		Inspector Name and Certificate Number: CJ Karoly 006424								
		Inspection Company: Criterion Laboratories								
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E I e m e n t	2	210A	Study Room beside Classroom 210	W4	Sheetrock	Purple	None	0	0	Negative
	1	210A	Study Room beside Classroom 210	Ceiling	2x4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
	1	210A	Study Room beside Classroom 210	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
	1	210A	Study Room beside Classroom 210	Door	Wood	Yellow	None	0	0	Negative
	1	210A	Study Room beside Classroom 210	Door Casing	Metal	Yellow	None	0	0	Negative
	1	210A	Study Room beside Classroom 210	Door	Wood	Yellow	None	0	0	Negative
	1	210A	Study Room beside Classroom 210	Door Casing	Metal	Yellow	None	0	0	Negative
	1	210A	Study Room beside Classroom 210	Baseboard	Metal	White	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	W1	Sheetrock	White	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	W2	Sheetrock	White	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	W3	Sheetrock	White	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	W4	Sheetrock	White	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	Ceiling	2x4 Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A
	1	210B	Study Room beside Classroom 210	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
	1	210B	Study Room beside Classroom 210	Door	Wood	Green	None	0	0	Negative
	1	210B	Study Room beside Classroom 210	Door Casing	Metal	Green	None	0	0	Negative
	1	211		Mechanical Room across from Classroom 210	W1	Sheetrock	White	None	0	0
1	211		Mechanical Room across from Classroom 210	W2	Sheetrock	White	None	0	0	Negative
1	211		Mechanical Room across from Classroom 210	W3	Sheetrock	White	None	0	0	Negative
1	211		Mechanical Room across from Classroom 210	W4	Sheetrock	White	None	0	0	Negative
1	211		Mechanical Room across from Classroom 210	Ceiling	Sheetrock	White	None	0	0	Negative
1	211		Mechanical Room across from Classroom 210	Floor	Concrete	Dark Grey	None	0	0	Negative

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	211	Mechanical Room across from Classroom 210	Door	Wood	Grey	None	0	0	Negative
1	211	Mechanical Room across from Classroom 210	Door Casing	Metal	White	None	0	0	Negative
1	211	Mechanical Room across from Classroom 210	Air Duct	Metal	White	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	W1	Sheetrock	White	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	W2	Sheetrock	White	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	W3	Sheetrock	White	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	W4	CMU	White	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	211A	Storage Room beside Mechanical Room	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	211A	Storage Room beside Mechanical Room	Door	Wood	Grey	None	0	0	Negative
1	211A	Storage Room beside Mechanical Room	Door Casing	Metal	Grey	None	0	0	Negative
1	212	Classroom 212	W1	Sheetrock	Grey	None	0	0	Negative
1	212	Classroom 212	W2	Sheetrock	Yellow	None	0	0	Negative
1	212	Classroom 212	W3	Sheetrock	Grey	None	0	0	Negative
1	212	Classroom 212	W4	Brick	Grey	None	0	0	Negative
1	212	Classroom 212	Ceiling	Sheetrock	White	Peeling	100	0	Negative
1	212	Classroom 212	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	212	Classroom 212	Door	Wood	Grey	None	0	0	Negative
1	212	Classroom 212	Door Casing	Metal	Grey	None	0	0	Negative
1	212A	Counselor Office on left outside of Classroom 212	W1	Sheetrock	Grey	None	0	0	Negative
1	212A	Counselor Office on left outside of Classroom 212	W2	Sheetrock	Grey	None	0	0	Negative
1	212A	Counselor Office on left outside of Classroom 212	W3	Sheetrock	Grey	None	0	0	Negative

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	212A	Counselor Office on left outside of Classroom 212	W4	Sheetrock	Grey	None	0	0	Negative
1	212A	Counselor Office on left outside of Classroom 212	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	212A	Counselor Office on left outside of Classroom 212	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	212A	Counselor Office on left outside of Classroom 212	Door Casing	Wood	White	None	0	0	Negative
1	212B	Office on right outside of Classroom 212	W1	Sheetrock	Blue	None	0	0	Negative
1	212B	Office on right outside of Classroom 212	W2	Sheetrock	Blue	None	0	0	Negative
1	212B	Office on right outside of Classroom 212	W3	Sheetrock	Blue	None	0	0	Negative
1	212B	Office on right outside of Classroom 212	W4	Sheetrock	Blue	None	0	0	Negative
1	212B	Office on right outside of Classroom 212	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	212B	Office on right outside of Classroom 212	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	212B	Office on right outside of Classroom 212	Door	Wood	White	None	0	0	Negative
1	213	Classroom 213	W1	Sheetrock	White	None	0	0	Negative
1	213	Classroom 213	W2	Sheetrock	White	None	0	0	Negative
1	213	Classroom 213	W2	Brick	White	None	0	0.1	Negative
1	213	Classroom 213	W2	CMU	White	None	0	0	Negative
1	213	Classroom 213	W3	Sheetrock	White	Chipping	30	0	Negative
1	213	Classroom 213	W4	Sheetrock	Blue	None	0	0	Negative
1	213	Classroom 213	Ceiling	Sheetrock/Joint compound	White	None	0	0	Negative
1	213	Classroom 213	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	213	Classroom 213	Door	Wood	White	None	0	0	Negative
1	213	Classroom 213	Door Casing	Metal	White	None	0	0	Negative
1	213	Classroom 213	Window Sill	Wood	White	None	0	0	Negative
1	213	Classroom 213	Conduit	Metal	White	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023								
		Inspector Name and Certificate Number: CJ Karoly 006424								
		Inspection Company: Criterion Laboratories								
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E I e m e n t	1	214	Classroom 214	W1	Sheetrock	Grey	Peeling	20	0	Negative
	1	214	Classroom 214	W2	Brick	Green	None	0	0	Negative
	1	214	Classroom 214	W3	Sheetrock	Blue	Peeling	60	0	Negative
	1	214	Classroom 214	W4	Sheetrock	Green	Peeling	20	0	Negative
	1	214	Classroom 214	Ceiling	Sheetrock/Joint compound	White	None	0	0	Negative
	1	214	Classroom 214	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
	1	214	Classroom 214	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	214	Classroom 214	Door	Wood	Grey	None	0	0	Negative
	1	214	Classroom 214	Door Casing	Metal	Green	None	0	0	Negative
	1	214A	Office next to Classroom 214	W1	Sheetrock	Grey	None	0	0	Negative
	1	214A	Office next to Classroom 214	W2	Sheetrock	Grey	None	0	0	Negative
	1	214A	Office next to Classroom 214	W3	Sheetrock	Grey	None	0	0	Negative
	1	214A	Office next to Classroom 214	W4	Sheetrock	Grey	None	0	0	Negative
	1	214A	Office next to Classroom 214	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
	1	214A	Office next to Classroom 214	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	214A	Office next to Classroom 214	Door Casing	Wood	White	None	0	0	Negative
	1	214B	Closet in Classroom 214	W1	Sheetrock	White	None	0	0	Negative
	1	214B	Closet in Classroom 214	W2	Sheetrock	White	None	0	0	Negative
	1	214B	Closet in Classroom 214	W3	Sheetrock	White	None	0	0	Negative
	1	214B	Closet in Classroom 214	W4	CMU	White	None	0	0	Negative
1	214B	Closet in Classroom 214	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A	
1	214B	Closet in Classroom 214	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	
1	214B	Closet in Classroom 214	Door	Wood	Yellow	None	0	0	Negative	
1	214B	Closet in Classroom 214	Door Casing	Metal	Yellow	None	0	0	Negative	
1	215	Classroom 215	W1	Sheetrock	Blue	Holes	10	0	Negative	
1	215	Classroom 215	W2	Sheetrock	Yellow	None	0	0	Negative	

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	215	Classroom 215	W3	Sheetrock	Blue	None	0	0	Negative
1	215	Classroom 215	W4	Sheetrock	Yellow	None	0	0	Negative
1	215	Classroom 215	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	215	Classroom 215	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	215	Classroom 215	Door	Wood	Grey	None	0	0	Negative
1	215	Classroom 215	Door Casing	Metal	Grey	None	0	0	Negative
1	215	Classroom 215	Window Casing	Metal	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	W1	Sheetrock	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	W2	Sheetrock	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	W3	Sheetrock	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	W4	Sheetrock	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	Ceiling	2x4 Ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	215B	Classroom 215 office (nurse's office)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	215B	Classroom 215 office (nurse's office)	Window Sill	Wood	Black	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	Door	Metal	Grey	None	0	0	Negative
1	215B	Classroom 215 office (nurse's office)	Door Casing	Metal	Grey	None	0	0	Negative
1	215A	Storage Room in Classroom 215	W1	Sheetrock	White	None	0	0	Negative
1	215A	Storage Room in Classroom 215	W2	Sheetrock	White	None	0	0	Negative
1	215A	Storage Room in Classroom 215	W3	Sheetrock	White	None	0	0	Negative
1	215A	Storage Room in Classroom 215	W4	Sheetrock	White	None	0	0	Negative
1	215A	Storage Room in Classroom 215	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	215A	Storage Room in Classroom 215	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	215A	Storage Room in Classroom 215	Door	Wood	Yellow	None	0	0	Negative
1	215A	Storage Room in Classroom 215	Door Casing	Metal	Yellow	None	0	0	Negative
1	216	Classroom 216	W1	Sheetrock	White	None	0	0	Negative
1	216	Classroom 216	W2	Sheetrock	White	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023								
		Inspector Name and Certificate Number: CJ Karoly 006424								
		Inspection Company: Criterion Laboratories								
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E I e m e n t	1	216	Classroom 216	W3	Sheetrock	Green	None	0	0	Negative
	1	216	Classroom 216	W4	Sheetrock	White	None	0	0	Negative
	1	216	Classroom 216	W4	CMU	White	None	0	0.1	Negative
	1	216	Classroom 216	W4	Brick	White	None	0	0.2	Negative
	1	216	Classroom 216	Ceiling	Sheetrock	White	Peeling	20	0	Negative
	1	216	Classroom 216	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	216	Classroom 216	Door	Metal	Grey	None	0	0	Negative
	1	216	Classroom 216	Door Casing	Metal	Grey	None	0	0	Negative
	1	216	Classroom 216	Window Casing	Metal	Grey	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	W1	Sheetrock	White	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	W2	Sheetrock	White	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	W3	Sheetrock	White	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	W4	Sheetrock	White	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
	1	216A	Closet on left in Classroom 216	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	216A	Closet on left in Classroom 216	Door	Metal	Yellow	None	0	0	Negative
	1	216A	Closet on left in Classroom 216	Door Casing	Metal	Yellow	None	0	0	Negative
	1	216B	Closet on right in Classroom 216	W1	Sheetrock	White	None	0	0	Negative
1	216B	Closet on right in Classroom 216	W2	Sheetrock	White	None	0	0	Negative	
1	216B	Closet on right in Classroom 216	W3	Sheetrock	White	None	0	0	Negative	
1	216B	Closet on right in Classroom 216	W4	Sheetrock	White	None	0	0	Negative	
1	216B	Closet on right in Classroom 216	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A	
1	216B	Closet on right in Classroom 216	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A	
1	216B	Closet on right in Classroom 216	Door	Metal	Yellow	None	0	0	Negative	
1	216B	Closet on right in Classroom 216	Door Casing	Metal	Yellow	None	0	0	Negative	
1	218		Kitchen Office	W1	Sheetrock	White	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023								
		Inspector Name and Certificate Number: CJ Karoly 006424								
		Inspection Company: Criterion Laboratories								
		Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
E I e m e n t	1	218	Kitchen Office	W2	Sheetrock	White	None	0	0	Negative
	1	218	Kitchen Office	W3	Sheetrock	White	None	0	0	Negative
	1	218	Kitchen Office	W4	Sheetrock	White	None	0	0	Negative
	1	218	Kitchen Office	Ceiling	Sheetrock	White	None	0	0	Negative
	1	218	Kitchen Office	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
	1	218	Kitchen Office	Door	Metal	Yellow	None	0	0	Negative
	1	218	Kitchen Office	Door Casing	Metal	Yellow	None	0	0	Negative
	1	218	Kitchen Office	Window Casing	Metal	Yellow	None	0	0	Negative
	1	H21	Main Hallway	W1	Sheetrock	White	Peeling	20	0	Negative
	1	H21	Main Hallway	W1	Brick	White	Chipping	10	0	Negative
	1	H21	Main Hallway	W2	Sheetrock	White	None	0	0	Negative
	1	H21	Main Hallway	W2	Brick	White	Peeling	30	0	Negative
	1	H21	Main Hallway	W3	Sheetrock	White	None	0	0	Negative
	1	H21	Main Hallway	W4	Sheetrock	White	None	0	0	Negative
	1	H21	Main Hallway	W4	CMU	White	None	0	0	Negative
	1	H21	Main Hallway	Ceiling	2x2 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
	1	H21	Main Hallway	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
	1	H21	Main Hallway	Baseboard	Wood	White	None	0	0	Negative
	1	KIT1	Kitchen	W1	Sheetrock	White	None	0	0	Negative
	1	KIT1	Kitchen	W2	Sheetrock	White	None	0	0	Negative
1	KIT1	Kitchen	W3	Sheetrock	White	None	0	0	Negative	
1	KIT1	Kitchen	W4	Sheetrock	White	None	0	0	Negative	
1	KIT1	Kitchen	Ceiling	Sheetrock	White	None	0	0	Negative	
1	KIT1	Kitchen	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	KIT1	Kitchen	Door	Metal	Green	None	0	0	Negative	
1	KIT1	Kitchen	Door Casing	Metal	Green	None	0	0	Negative	

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

Dates: 8/28/2023 - 8/31/2023
Inspector Name and Certificate Number: CJ Karoly 006424
Inspection Company: Criterion Laboratories

Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	KIT1	Kitchen	Pipe	Metal	White	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	W1	Sheetrock	White	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	W2	Sheetrock	White	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	W3	Brick	White	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	W4	Sheetrock	White	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	Ceiling	2x2 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	M2	Men's Staff Restroom outside Main Office	Floor	Concrete	Grey	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	Door	Wood	Yellow	None	0	0	Negative
1	M2	Men's Staff Restroom outside Main Office	Door Casing	Metal	Yellow	None	0	0	Negative
1	MPR2	Multipurpose Room	W1	Sheetrock	Brown	None	0	0	Negative
1	MPR2	Multipurpose Room	W2	Brick	White	Flaking	1000	0.2	Negative
1	MPR2	Multipurpose Room	W3	Brick	White	Flaking	200	0.2	Negative
1	MPR2	Multipurpose Room	W4	Sheetrock	Green	None	0	0	Negative
1	MPR2	Multipurpose Room	Ceiling	Sheetrock	White	Holes	50	0	Negative
1	MPR2	Multipurpose Room	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	MPR2	Multipurpose Room	Door	Metal	Grey	None	0	0	Negative
1	MPR2	Multipurpose Room	Door Casing	Metal	Green	None	0	0	Negative
1	MPR2	Multipurpose Room	Air Duct	Metal	White	None	0	0	Negative
1	MPR2	Multipurpose Room	Rafter	Metal	Blue	None	0	0.1	Negative
1	MPR2	Multipurpose Room	Pipe	Metal	White	None	0	0	Negative
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	W3	No Access	No Access	No Access	No Access	No Access	No Access

		Lead-Safe Certification Assessment Report							
		The Workshop School							
		221 S. Hanson St, Philadelphia PA 19139							
	Dates: 8/28/2023 - 8/31/2023								
	Inspector Name and Certificate Number: CJ Karoly 006424								
	Inspection Company: Criterion Laboratories								
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2	Pipe Chase between Staff Restrooms outside of Main Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	PC2A	Pipe Chase in Multi-Purpose Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	W1	CMU	White	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	W2	Sheetrock	White	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	W3	Sheetrock	White	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	W4	Sheetrock	White	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	Ceiling	Sheetrock	White	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	Door	Metal	Grey	None	0	0	Negative
1	RR1-2	Staff Restroom outside of Multi-Purpose Room	Door Casing	Metal	Grey	None	0	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	W1	Sheetrock	Green	None	0	0	Negative

Lead-Safe Certification Assessment Report									
The Workshop School									
221 S. Hanson St, Philadelphia PA 19139									
		Dates: 8/28/2023 - 8/31/2023							
		Inspector Name and Certificate Number: CJ Karoly 006424							
		Inspection Company: Criterion Laboratories							
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	RR2	Staff Restroom inside Multi-Purpose Room	W2	Sheetrock	Green	Peeling	5	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	W3	CMU	Green	None	0	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	W4	Sheetrock	Green	None	0	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	Ceiling	Sheetrock	White	None	0	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	RR2	Staff Restroom inside Multi-Purpose Room	Door	Metal	Yellow	None	0	0	Negative
1	RR2	Staff Restroom inside Multi-Purpose Room	Door Casing	Metal	Yellow	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	W1	Sheetrock	White	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	W2	Sheetrock	White	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	W3	Sheetrock	White	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	W4	CMU	White	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	ST1-2	Storage Closet inside Multi-Purpose Room	Floor	Floor tile	Unpainted	N/A	N/A	N/A	N/A
1	ST1-2	Storage Closet inside Multi-Purpose Room	Door	Metal	Yellow	None	0	0	Negative
1	ST1-2	Storage Closet inside Multi-Purpose Room	Door Casing	Metal	Yellow	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	W1	Brick	White	None	0	0	Negative

		Lead-Safe Certification Assessment Report							
		The Workshop School							
		221 S. Hanson St, Philadelphia PA 19139							
	Dates: 8/28/2023 - 8/31/2023								
	Inspector Name and Certificate Number: CJ Karoly 006424								
	Inspection Company: Criterion Laboratories								
E I e m e n t	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	SW1	Main Entrance Vestibule Stairway	W2	CMU	White	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	W3	CMU	White	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	W4	Brick	White	None	0	0.2	Negative
1	SW1	Main Entrance Vestibule Stairway	Handrail	Metal	Black	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	Handrail	Metal	Red	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	Stair Stringer	Metal	Red	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	Beam	Metal	White	None	0	0	Negative
1	SW1	Main Entrance Vestibule Stairway	Ceiling	2X4 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	SW1	Main Entrance Vestibule Stairway	Floor	Concrete	Grey	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	W1	Brick	White	None	0	0.1	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	W2	CMU	White	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	W3	CMU	White	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	W4	Brick	White	None	0	0.2	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	Handrail	Metal	Blue	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	Stair Stringer	Metal	Blue	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	Door	Metal	Blue	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	Door Casing	Metal	Blue	None	0	0	Negative
1	SW2-2	Stairwell beside Multi-Purpose Room	Ceiling	2x2 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
1	SW2-2	Stairwell beside Multi-Purpose Room	Floor	Concrete	Grey	None	0	0	Negative
1	W2	Women's Staff Restroom outside Main Office	W1	Sheetrock	White	None	0	0	Negative
1	W2	Women's Staff Restroom outside Main Office	W2	Sheetrock	White	None	0	0	Negative
1	W2	Women's Staff Restroom outside Main Office	W3	Brick	White	None	0	0	Negative
1	W2	Women's Staff Restroom outside Main Office	W4	CMU	White	None	0	0	Negative

Lead-Safe Certification Assessment Report

The Workshop School

221 S. Hanson St, Philadelphia PA 19139

		Dates: 8/28/2023 - 8/31/2023											
		Inspector Name and Certificate Number: CJ Karoly 006424											
		Inspection Company: Criterion Laboratories											
E	I	F	I	O	O	R	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2						Ceiling	2x2 ceiling tiles	Unpainted	N/A	N/A	N/A	N/A
							Floor	Concrete	Grey	None	0	0	Negative
							Door	Wood	Yellow	None	0	0	Negative
							Door Casing	Metal	Yellow	None	0	0	Negative