

		Lead-Safe Certification Assessment Report							
		John Bartram High School Field (Fieldhouse)							
		5801 Elmwood Ave, Philadelphia PA 19143							
	Dates: 9/11-9/12/23								
	Inspector Name and Certificate Number: Tim Smith 057662								
	Inspection Company: Batta								
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Field Supply Storage	W1	CMU	Tan	Flaking	1	0.5	Negative
1	1	Field Supply Storage	Door Frame	Metal	Tan	Chipping	12	6.7	Positive
1	1	Field Supply Storage	Door	Metal	Gray	Chipping	1	5.4	Positive
1	1	Field Supply Storage	W2	CMU	Tan	Flaking	2	0.2	Negative
1	1	Field Supply Storage	W3	CMU	Tan	Flaking	3	0.3	Negative
1	1	Field Supply Storage	W4	CMU	Tan	Flaking	1	0.4	Negative
1	1	Field Supply Storage	Conduit	Metal	Tan	None	0	0.3	Negative
1	1	Field Supply Storage	Pipe	Metal	Tan	None	0	0.3	Negative
1	1	Field Supply Storage	Stairs	Concrete	Gray	Flaking	8	0.1	Negative
1	1	Field Supply Storage	Door Frame	Metal	Tan	Chipping	3	4.4	Positive
1	1	Field Supply Storage	Door	Wood	Tan	Flaking	3	0	Negative
1	1	Field Supply Storage	Ceiling	Plaster	White	Flaking	40	0	Negative
1	1	Field Supply Storage	Floor	Concrete	Gray	Friction	400	0.1	Negative
1	1	Boy's Team Locker Room Restroom	W1	CMU	White	None	0	0.7	Positive
1	1	Boy's Team Locker Room Restroom	Door Frame	Metal	Gray	Chipping	10	4.6	Positive
1	1	Boy's Team Locker Room Restroom	Door	Wood	Gray	Friction	1	0	Negative
1	1	Boy's Team Locker Room Restroom	Conduit	Plastic	White/Gray	None	0	0.2	Negative
1	1	Boy's Team Locker Room Restroom	W2	CMU	White	Flaking	5	0.2	Negative
1	1	Boy's Team Locker Room Restroom	W3	CMU	White	None	0	0.6	Negative
1	1	Boy's Team Locker Room Restroom	W4	CMU	White	None	0	0.3	Negative
1	1	Boy's Team Locker Room Restroom	Ceiling	Plaster	White	Efflorescence	12	0.3	Negative
1	1	Boy's Team Locker Room Restroom	Floor	Concrete	Gray	Friction	30	0.2	Negative
1	1	Restroom	W1	CMU	White	None	0	0.7	Positive
1	1	Restroom	Door Frame	Metal	Gray	Chipping	4	0.5	Negative
1	1	Restroom	Door	Wood	Unpainted	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	10	Restroom	W2	CMU	White	None	0	0.6	Negative
1	10	Restroom	W3	CMU	White	None	0	0.7	Positive
1	10	Restroom	W4	CMU	White	None	0	0.5	Negative
1	10	Restroom	Ceiling	Plaster	White	Efflorescence	5	0.3	Negative
1	10	Restroom	Floor	Concrete	Gray	Friction	16	0	Negative
1	2	Boiler Room	W1	CMU	White	None	0	0.2	Negative
1	2	Boiler Room	Door Frame	Metal	Green/Gray	Chipping	10	7.6	Positive
1	2	Boiler Room	Door	Metal	Red	Chipping	6	9.5	Positive
1	2	Boiler Room	Stairs	Concrete	Gray	Flaking	10	0.4	Negative
1	2	Boiler Room	Pipe	Metal	Green	Flaking	8	1.6	Positive
1	2	Boiler Room	W2	CMU	White/Gray	Flaking	5	0.4	Negative
1	2	Boiler Room	Conduit	Metal	White	Flaking	1	0.2	Negative
1	2	Boiler Room	Sink	Ceramic	Gray/Green	Flaking	4	0.5	Negative
1	2	Boiler Room	W3	CMU	White/Gray	Flaking	2	0.5	Negative
1	2	Boiler Room	W4	CMU	White/Gray	None	0	0.3	Negative
1	2	Boiler Room	Ceiling	Plaster	White	Flaking	150	0.1	Negative
1	2	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boiler Room Storage	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boiler Room Storage	Door Frame	Wood	Green/Gray	Friction	10	0.6	Negative
1	3	Boiler Room Storage	Door	Wood	Green/Tan	Friction	3	0.6	Negative
1	3	Boiler Room Storage	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boiler Room Storage	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boiler Room Storage	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boiler Room Storage	Pipe	Metal	White	None	0	0.1	Negative
1	3	Boiler Room Storage	Ceiling	Plaster	Unpainted	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Boiler Room Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	5	Girl's Restroom	W1	CMU	Tan/White	None	0	0.4	Negative
1	5	Girl's Restroom	Door Frame	Metal	Gray	Flaking	2	7.6	Positive
1	5	Girl's Restroom	Door	Metal	Red	Friction	1	0	Negative
1	5	Girl's Restroom	W2	CMU	Tan/White	None	0	0.6	Negative
1	5	Girl's Restroom	Door Frame	Metal	Gray	None	0	0.3	Negative
1	5	Girl's Restroom	Door	Metal	Gray	None	0	0	Negative
1	5	Girl's Restroom	W3	CMU	Tan/White	None	0	0.6	Negative
1	5	Girl's Restroom	Pipe	Metal	Tan	Moisture Damage	1	0	Negative
1	5	Girl's Restroom	W4	CMU	Tan/White	None	0	0.3	Negative
1	5	Girl's Restroom	Bathroom Stall	Wood	Gray	Chipping	5	0.1	Negative
1	5	Girl's Restroom	Access Panel Door Frame	Metal	Gray	Flaking	3	2.1	Positive
1	5	Girl's Restroom	Access Panel Door	Wood	Gray	Flaking	5	0.2	Negative
1	5	Girl's Restroom	Ceiling	Plaster	White	None	0	0	Negative
1	5	Girl's Restroom	Floor	Concrete	Gray	Chipping	15	0.2	Negative
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4PC/5PC	Pipe Chase at Girl's and Boy's Rest	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Boy's Restroom	W1	CMU	Green	Flaking	10	0.3	Negative
1	4	Boy's Restroom	Door Frame	Metal	Gray	Chipping	12	0.1	Negative
1	4	Boy's Restroom	Door	Metal	Tan	Chipping	2	0	Negative
1	4	Boy's Restroom	W2	CMU	Green	Cracking	5	0.5	Negative

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	Boy's Restroom	Bathroom Stall	Wood	Tan	Flaking	2	0.1	Negative
1	4	Boy's Restroom	Access Panel Door Frame	Metal	Tan	Chipping	2	5.4	Positive
1	4	Boy's Restroom	W3	CMU	Green	Chipping	10	0.5	Negative
1	4	Boy's Restroom	W4	CMU	Green	None	0	0.5	Negative
1	4	Boy's Restroom	Ceiling	Plaster	Tan	Flaking	5	0.1	Negative
1	4	Boy's Restroom	Floor	Concrete	Gray	Flaking	40	0.2	Negative
1	6	Guest Team Locker Room	W1	CMU	Multi-Colored	None	0	0.3	Negative
1	6	Guest Team Locker Room	Door Frame	Metal	Gray	Chipping	4	12	Positive
1	6	Guest Team Locker Room	Door	Metal	Red	Chipping	6	0.1	Negative
1	6	Guest Team Locker Room	Coat Rack	Wood	White/Gray	None	0	0	Negative
1	6	Guest Team Locker Room	W2	CMU	Multi-Colored	None	0	0.1	Negative
1	6	Guest Team Locker Room	Bathroom Stall	Wood	Gray	Friction	5	0.2	Negative
1	6	Guest Team Locker Room	W3	CMU	Multi-Colored	None	0	0.1	Negative
1	6	Guest Team Locker Room	W4	CMU	Multi-Colored	None	0	0.5	Negative
1	6	Guest Team Locker Room	Ceiling	Plaster	White	None	0	0.1	Negative
1	6	Guest Team Locker Room	Floor	Concrete	Gray	Friction	320	0.2	Negative
1	7	Boy's Team Locker Room	W1	CMU	White/Gray	None	0	0.5	Negative
1	7	Boy's Team Locker Room	Door Frame	Metal	Green	Chipping	14	19.7	Positive
1	7	Boy's Team Locker Room	Door	Metal	Gray/Red	Flaking	20	0.1	Negative
1	7	Boy's Team Locker Room	Door	Wood	Gray/Red	Flaking	20	0.1	Negative
1	7	Boy's Team Locker Room	W2	CMU	White/Gray	None	0	0.5	Negative
1	7	Boy's Team Locker Room	W3	CMU	White/Gray	None	0	0.6	Negative
1	7	Boy's Team Locker Room	Pipe	Metal	Tan	Flaking	3	0.2	Negative
1	7	Boy's Team Locker Room	W4	CMU	White/Gray	None	0	0.1	Negative
1	7	Boy's Team Locker Room	Ceiling	Plaster	White	None	0	0	Negative

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	7	Boy's Team Locker Room	Floor	Concrete	Gray	Friction	20	0.2	Negative
1	7	Boy's Team Locker Room	Bench	Wood	Gray	Friction	10	0.1	Negative
1	8	Restroom	W1	CMU	Pink	None	0	0.1	Negative
1	8	Restroom	Door Frame	Metal	Gray	Chipping	6	0.3	Negative
1	8	Restroom	Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	8	Restroom	W2	CMU	Pink	None	0	0	Negative
1	8	Restroom	W3	CMU	Pink	Efflorescence	12	0.3	Negative
1	8	Restroom	W4	CMU	Pink	Efflorescence	12	0.7	Positive
1	8	Restroom	Ceiling	Plaster	White	Flaking	6	0.3	Negative
1	8	Restroom	Floor	Concrete	Gray	Friction	28	0.3	Negative
1	8A	Team Equipment Storage	W1	CMU	White	Flaking	24	0.3	Negative
1	8A	Team Equipment Storage	Door Frame	Metal	Gray	Chipping	8	0.2	Negative
1	8A	Team Equipment Storage	Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	8A	Team Equipment Storage	W2	CMU	White	Flaking	6	0.5	Negative
1	8A	Team Equipment Storage	W3	CMU	White	Flaking	12	0.5	Negative
1	8A	Team Equipment Storage	W4	CMU	White	Flaking	30	0.5	Negative
1	8A	Team Equipment Storage	Pipe	Metal	White/Gray	Flaking	10	0.4	Negative
1	8A	Team Equipment Storage	Ceiling	Plaster	White	Flaking	30	0.3	Negative
1	8A	Team Equipment Storage	Floor	Concrete	Gray	Friction	80	0.1	Negative
1	9	Field staff office	W1	CMU	Gray/White	Flaking	4	0.4	Negative
1	9	Field staff office	Door Frame	Metal	Gray	Chipping	12	13.9	Positive
1	9	Field staff office	Door	Metal	Red	Flaking	2	0.1	Negative
1	9	Field staff office	W2	CMU	Gray/White	Chipping	3	0.7	Positive
1	9	Field staff office	W3	CMU	Gray/White	Flaking	20	0.1	Negative
1	9	Field staff office	W4	CMU	Gray/White	Flaking	6	0.6	Negative

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	9	Field staff office	Ceiling	Plaster	White	Flaking	42	0	Negative
1	9	Field staff office	Floor	Concrete	Gray	Friction	50	0.2	Negative
1	001A	Kitchen	W1	Plaster	White	Flaking	20	0	Negative
1	001A	Kitchen	Door Frame	Metal	Red/Gray	Chipping	4	0.2	Negative
1	001A	Kitchen	W2	Plaster	White	Flaking	40	0.4	Negative
1	001A	Kitchen	Baseboard	Wood	Gray	None	0	0.4	Negative
1	001A	Kitchen	W3	Plaster	White	Flaking	20	0.5	Negative
1	001A	Kitchen	W4	Plaster	White	Flaking	30	0.1	Negative
1	001A	Kitchen	Radiator	Metal	Gray	None	0	0.2	Negative
1	001A	Kitchen	Ceiling	Plaster	White	Flaking	2	0	Negative
1	001A	Kitchen	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	002A	Closet	W1	Plaster	White	None	0	0	Negative
1	002A	Closet	Door Frame	Metal	Gray/Red	Chipping	4	1	Positive
1	002A	Closet	W2	Plaster	White	None	0	0.2	Negative
1	002A	Closet	W3	Plaster	White	None	0	0	Negative
1	002A	Closet	W4	Plaster	White	None	0	0.2	Negative
1	002A	Closet	Baseboard	Wood	Tan	Flaking	4	0.4	Negative
1	002A	Closet	Ceiling	Plaster	White	None	0	0.1	Negative
1	002A	Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	003A	Equipment Storage #2	W1	Plaster	Gray	Flaking	6	0	Negative
1	003A	Equipment Storage #2	Door Frame	Metal	Gray/Red	Flaking	10	1.2	Positive
1	003A	Equipment Storage #2	W2	Plaster	Gray	None	0	0.2	Negative
1	003A	Equipment Storage #2	Baseboard	Wood	Red	None	0	0.3	Negative
1	003A	Equipment Storage #2	W3	Plaster	Gray	Chipping	5	0.2	Negative
1	003A	Equipment Storage #2	Window Frame	Metal	Gray	Flaking	12	0.8	Positive

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	003A	Equipment Storage #2	Radiator	Metal	Silver	Flaking	4	0	Negative
1	003A	Equipment Storage #2	W4	Plaster	Gray	Efflorescence	20	0	Negative
1	003A	Equipment Storage #2	Ceiling	Plaster	White	Flaking	5	0.1	Negative
1	003A	Equipment Storage #2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	004A	Equipment Storage #1 (nearest to bathroom)	W1	Plaster	Tan	Flaking	14	0.2	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	Door Frame	Metal	Gray/Red	Flaking	16	1	Positive
1	004A	Equipment Storage #1 (nearest to bathroom)	W2	Plaster	Tan	Flaking	120	0.1	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	W3	Plaster	Tan	Flaking	120	0.2	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	Window Frame	Metal	Tan	Flaking	10	1.8	Positive
1	004A	Equipment Storage #1 (nearest to bathroom)	Radiator	Metal	Silver	Flaking	8	0.4	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	W4	Plaster	Tan	Flaking	80	0.2	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	Baseboard	Wood	Tan	Flaking	32	0.2	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	Ceiling	Plaster	Tan	Flaking	145	0.1	Negative
1	004A	Equipment Storage #1 (nearest to bathroom)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	005A	Coach's Lounge	W1	Plaster	Gray	None	0	0.3	Negative
1	005A	Coach's Lounge	Door Frame	Metal	Red/Gray	Chipping	10	0.8	Positive
1	005A	Coach's Lounge	Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	005A	Coach's Lounge	Baseboard	Wood	Red	None	0	0.1	Negative
1	005A	Coach's Lounge	W2	Plaster	Gray	Flaking	2	0.2	Negative
1	005A	Coach's Lounge	W3	Plaster	Gray	Flaking	3	0.1	Negative
1	005A	Coach's Lounge	W4	Plaster	Gray	Efflorescence	24	0.1	Negative
1	005A	Coach's Lounge	Ceiling	Plaster	White	Flaking	20	0	Negative
1	005A	Coach's Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	BT1	Staff Restroom	W1	Plaster	White	Flaking	30	0.2	Negative
1	BT1	Staff Restroom	Door Frame	Metal	Gray/Red	Chipping	10	1	Positive
1	BT1	Staff Restroom	Door	Wood	Unpainted	N/A	N/A	N/A	N/A
1	BT1	Staff Restroom	W2	Plaster	White	Flaking	10	0.3	Negative
1	BT1	Staff Restroom	Window Frame	Metal	White	Flaking	9	1.9	Positive
1	BT1	Staff Restroom	W3	Plaster	White	Flaking	10	0.3	Negative
1	BT1	Staff Restroom	W4	Plaster	White	Flaking	10	0.3	Negative
1	BT1	Staff Restroom	Baseboard	Wood	Gray	Chipping	5	0.3	Negative
1	BT1	Staff Restroom	Ceiling	Plaster	White	None	0	0	Negative
1	BT1	Staff Restroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	H11	Main Hallway	W1	Plaster	Gray	None	0	0.3	Negative
1	H11	Main Hallway	Door Frame	Metal	Red/Gray	Chipping	1	0.5	Negative
1	H11	Main Hallway	Baseboard	Wood	Red	None	0	0.2	Negative
1	H11	Main Hallway	W2	Plaster	Gray	None	0	0.1	Negative
1	H11	Main Hallway	W3	Plaster	Gray	Cracking	2	0.2	Negative
1	H11	Main Hallway	W4	Plaster	Gray	None	0	0.1	Negative
1	H11	Main Hallway	Ceiling	Plaster	White	None	0	0.1	Negative
1	H11	Main Hallway	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	S11	Stairwell	W1	CMU	Gray/Red	None	0	1.4	Positive
1	S11	Stairwell	Door Frame	Metal	Gray	Flaking	12	2.6	Positive
1	S11	Stairwell	Door	Wood	Green/Gray	Chipping	4	7.2	Positive
1	S11	Stairwell	W2	CMU	Red	None	0	2	Positive
1	S11	Stairwell	W2	Plaster	Tan	Flaking	15	0.6	Negative
1	S11	Stairwell	Stair Stringer	Metal	Gray	Flaking	3	5.1	Positive
1	S11	Stairwell	Window Frame	Metal	Gray	Flaking	1	1.6	Positive



Lead-Safe Certification Assessment Report									
John Bartram High School Field (Fieldhouse)									
5801 Elmwood Ave, Philadelphia PA 19143									
Element	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	S11	Stairwell	W3	Plaster	Tan	Flaking	10	0.3	Negative
1	S11	Stairwell	Baseboard	Wood	Red	None	0	0.2	Negative
1	S11	Stairwell	W4	CMU	Gray	Chipping	1	1.9	Positive
1	S11	Stairwell	W4	Plaster	Tan	Flaking	30	0.1	Negative
1	S11	Stairwell	Stair Railing	Metal	Gray	Chipping	10	0.4	Negative
1	S11	Stairwell	Ceiling	Plaster	Tan	Flaking	10	0.4	Negative
1	S11	Stairwell	Floor	Concrete	Gray	Flaking/Friction	3	0.3	Negative
1	S11	Stairwell	Stair Tread	Concrete	Gray	Flaking	30	0.4	Negative
1	S11	Stairwell	Stair Riser	Metal	Gray	Flaking	5	7.6	Positive
2	STANDS 1	Stands	W1	CMU	White/Gray	None	0	0.5	Negative
2	STANDS 1	Stands	Door Frame	Metal	Tan	Chipping	20	0.4	Negative
2	STANDS 1	Stands	Door	Metal	Tan	Chipping	40	0.1	Negative
2	STANDS 1	Stands	W2	CMU	White/Gray	None	0	0	Negative
2	STANDS 1	Stands	W3	CMU	White/Gray	None	0	0	Negative
2	STANDS 1	Stands	Support Beam	Metal	Gray	Chipping	60	5.5	Positive
2	STANDS 1	Stands	W4	CMU	White/Gray	None	0	0	Negative
2	STANDS 1	Stands	Ceiling	Concrete Decking	White	Flaking	66	0.4	Negative
2	STANDS 1	Stands	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A