

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	W1	CMU	White	None	0	0.04	Negative
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	W2	CMU	White	None	0	0.07	Negative
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	W3	CMU	White	None	0	0.01	Negative
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	W4	CMU	White	None	0	0.05	Negative
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	GD	Pre-K Hallway (Hallway outside 400 Rooms)	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Women's Restroom	W1	CMU	White	None	0	0.04	Negative
2	GD	Women's Restroom	W2	CMU	White	None	0	0.07	Negative
2	GD	Women's Restroom	W3	CMU	White	None	0	0.01	Negative
2	GD	Women's Restroom	W4	CMU	White	None	0	0.05	Negative
2	GD	Women's Restroom	Ceiling	Concrete	White	Cracking	2	0	Negative
2	GD	Women's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	GD	Women's Restroom	Door Frame	Metal	Blue	Chipping	2	0.02	Negative
2	GD	Girl's Restroom	W1	CMU	White	None	0	0.03	Negative
2	GD	Girl's Restroom	W2	CMU	White	None	0	0.04	Negative
2	GD	Girl's Restroom	W3	CMU	White	None	0	0.01	Negative
2	GD	Girl's Restroom	W4	CMU	White	None	0	0.01	Negative
2	GD	Girl's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Girl's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	GD	Girl's Restroom	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Girl's Restroom	W1	CMU	Tan	None	0	0.02	Negative
2	GD	Girl's Restroom	W2	CMU	Tan	None	0	0.04	Negative
2	GD	Girl's Restroom	W3	CMU	Tan	None	0	0.01	Negative
2	GD	Girl's Restroom	W4	CMU	Tan	None	0	0.02	Negative
2	GD	Girl's Restroom	Duct	Metal	White	None	0	0	Negative
2	GD	Men's Restroom	W1	CMU	White	None	0	0.01	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	GD	Men's Restroom	W2	CMU	White	None	0	0.01	Negative
2	GD	Men's Restroom	W3	CMU	White	None	0	0.02	Negative
2	GD	Men's Restroom	W4	CMU	White	None	0	0.04	Negative
2	GD	Men's Restroom	Ceiling	Concrete	White	Cracking	2	0	Negative
2	GD	Men's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	GD	Men's Restroom	Door Frame	Metal	Blue	None	0	0.02	Negative
2	GD	Boy's Restroom	W1	CMU	White	None	0	0.03	Negative
2	GD	Boy's Restroom	W2	CMU	White	None	0	0.06	Negative
2	GD	Boy's Restroom	W3	CMU	White	None	0	0.01	Negative
2	GD	Boy's Restroom	W4	CMU	White	None	0	0.02	Negative
2	GD	Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	GD	Boy's Restroom	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Boy's Restroom	W1	CMU	Grey	None	0	0.05	Negative
2	GD	Boy's Restroom	W2	CMU	Grey	None	0	0.01	Negative
2	GD	Boy's Restroom	W3	CMU	Grey	None	0	0	Negative
2	GD	Boy's Restroom	W4	CMU	Grey	None	0	0.02	Negative
2	GD	Boy's Restroom	Duct	Metal	White	None	0	0.03	Negative
2	GD	Classroom 414	W1	CMU	White	None	0	0.03	Negative
2	GD	Classroom 414	W2	Sheetrock	White	None	0	0	Negative
2	GD	Classroom 414	W3	CMU	White	None	0	0.01	Negative
2	GD	Classroom 414	W4	CMU	White	None	0	0.05	Negative
2	GD	Classroom 414	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 414	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 414	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 411	W1	CMU	White	None	0	0.03	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	GD	Classroom 411	W2	CMU	White	None	0	0.05	Negative
2	GD	Classroom 411	W3	CMU	White	None	0	0.06	Negative
2	GD	Classroom 411	W4	CMU	White	None	0	0.02	Negative
2	GD	Classroom 411	Ceiling	Concrete	White	None	0	0.03	Negative
2	GD	Classroom 411	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 411	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 411	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 412	W1	CMU	White	None	0	0.05	Negative
2	GD	Classroom 412	W2	CMU	White	None	0	0.06	Negative
2	GD	Classroom 412	W3	CMU	White	None	0	0.07	Negative
2	GD	Classroom 412	W4	Sheetrock	Blue	None	0	0	Negative
2	GD	Classroom 412	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 412	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 412	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 409	W1	CMU	White	None	0	0.05	Negative
2	GD	Classroom 409	W2	CMU	White	None	0	0.06	Negative
2	GD	Classroom 409	W3	CMU	White	None	0	0.02	Negative
2	GD	Classroom 409	W4	CMU	White	None	0	0.01	Negative
2	GD	Classroom 409	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 409	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 409	Door Frame	Metal	Blue	Chipping	1	0.02	Negative
2	GD	Classroom 410	W1	CMU	White	None	0	0.01	Negative
2	GD	Classroom 410	W2	CMU	White	None	0	0.01	Negative
2	GD	Classroom 410	W3	CMU	White	None	0	0.01	Negative
2	GD	Classroom 410	W4	CMU	White	None	0	0.03	Negative
2	GD	Classroom 410	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	GD	Classroom 410	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 410	Door Frame	Metal	Blue	Chipping	1	0.02	Negative
2	GD	Classroom 408	W1	CMU	White	None	0	0.02	Negative
2	GD	Classroom 408	W2	CMU	White	None	0	0.03	Negative
2	GD	Classroom 408	W3	CMU	White	None	0	0.02	Negative
2	GD	Classroom 408	W4	CMU	White	None	0	0.01	Negative
2	GD	Classroom 408	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 408	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 408	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
2	GD	Classroom 408	Door Frame	Metal	White	Chipping	1	0.01	Negative
2	GD	Classroom 406	W1	CMU	White	None	0	0	Negative
2	GD	Classroom 406	W2	CMU	White	None	0	0.01	Negative
2	GD	Classroom 406	W3	CMU	White	None	0	0	Negative
2	GD	Classroom 406	W4	CMU	White	None	0	0.03	Negative
2	GD	Classroom 406	Ceiling	Concrete	White	Efflorescence	1	0	Negative
2	GD	Classroom 406	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 406	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 406	Door Frame	Metal	White	Chipping	1	0.01	Negative
2	GD	Classroom 403	W1	CMU	White	None	0	0.02	Negative
2	GD	Classroom 403	W2	CMU	White	None	0	0.04	Negative
2	GD	Classroom 403	W3	CMU	White	Chipping	150	0.01	Negative
2	GD	Classroom 403	W4	CMU	White	None	0	0.02	Negative
2	GD	Classroom 403	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 403	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 403	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 402	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	GD	Classroom 402	W2	CMU	White	Cracking	4	0	Negative
2	GD	Classroom 402	W3	CMU	White	None	0	0	Negative
2	GD	Classroom 402	W4	CMU	White	None	0	0	Negative
2	GD	Classroom 402	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 402	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 402	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 402	Door Frame	Metal	White	Chipping	1	0.02	Negative
2	GD	Classroom 402 Storage	W1	CMU	White	None	0	0.03	Negative
2	GD	Classroom 402 Storage	W2	CMU	White	None	0	0.07	Negative
2	GD	Classroom 402 Storage	W3	CMU	White	None	0	0	Negative
2	GD	Classroom 402 Storage	W4	CMU	White	None	0	0.02	Negative
2	GD	Classroom 402 Storage	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 402 Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 402 Storage	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	GD	Classroom 401	W1	CMU	Yellow	None	0	0	Negative
2	GD	Classroom 401	W2	CMU	Yellow	None	0	0	Negative
2	GD	Classroom 401	W3	CMU	Yellow	Efflorescence	50	0	Negative
2	GD	Classroom 401	W4	CMU	Yellow	Efflorescence	10	0.04	Negative
2	GD	Classroom 401	Ceiling	Concrete	White	None	0	0	Negative
2	GD	Classroom 401	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	GD	Classroom 401	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	W1	CMU	White	None	0	0	Negative
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	W2	CMU	White	None	0	0	Negative
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	W3	CMU	White	None	0	0	Negative
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	W4	CMU	White	None	0	0	Negative
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Mini Hallway from Kitchen to Ladies Locker Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Section D Ground Hallway	W1	CMU	White	None	0	0	Negative
1	GD	Section D Ground Hallway	W2	CMU	White	None	0	0	Negative
1	GD	Section D Ground Hallway	W3	CMU	White	None	0	0	Negative
1	GD	Section D Ground Hallway	W4	CMU	White	None	0	0	Negative
1	GD	Section D Ground Hallway	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Section D Ground Hallway	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room	W1	CMU	White	None	0	0	Negative
1	GD	Ladies Locker Room	W2	CMU	White	None	0	0	Negative
1	GD	Ladies Locker Room	W3	CMU	White	None	0	0	Negative
1	GD	Ladies Locker Room	W4	CMU	White	None	0	0	Negative
1	GD	Ladies Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room	Column 1	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 2	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 3	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 4	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 5	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 6	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 7	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 8	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 9	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Column 10	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room	Duct	Metal	White	None	0	0	Negative
1	GD	Ladies Locker Room	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Kitchen Fridge	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Kitchen Fridge	W2	CMU	White	None	0	0	Negative
1	GD	Kitchen Fridge	W3	CMU	White	None	0	0	Negative
1	GD	Kitchen Fridge	W4	CMU	White	None	0	0	Negative
1	GD	Kitchen Fridge	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Kitchen Fridge	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room	W1	CMU	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	W2	CMU	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	W3	CMU	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	W4	CMU	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room	Column 1	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 2	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 3	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 4	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 5	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 6	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 7	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 8	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 9	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Column 10	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Duct	Metal	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Locker Room Across from REC Room	W1	CMU	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	W2	CMU	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Locker Room Across from REC Room	W4	CMU	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room	Column 1	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 2	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 3	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 4	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 5	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 6	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 7	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 8	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 9	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Column 10	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Duct	Metal	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Locker Room Across from REC Room Girl's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room Girl's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room Girl's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room Girl's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room Girl's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Locker Room Across from REC Room Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Across from REC Room Girl's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Locker Room Next to Beacon Room Boy's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room Boy's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room Boy's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room Boy's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Locker Room Next to Beacon Room Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Locker Room Next to Beacon Room Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Locker Room Next to Beacon Room Boy's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 18 Office	W1	CMU	White	None	0	0.01	Negative
1	GD	Classroom 18 Office	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Office	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Office	W4	CMU	White	None	0	0.01	Negative
1	GD	Classroom 18 Office	Ceiling	Concrete	White	None	0	0.03	Negative
1	GD	Classroom 18 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 18 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 18 Middle Storage	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Middle Storage	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Middle Storage	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Middle Storage	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Middle Storage	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 18 Middle Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 18 Middle Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 18 Storage	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Storage	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Storage	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Storage	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 18 Storage	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 18 Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 18 Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Maintenance Garage	W1	CMU	White	None	0	0	Negative
1	GD	Maintenance Garage	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Maintenance Garage	W3	CMU	White	None	0	0	Negative
1	GD	Maintenance Garage	W4	CMU	White	None	0	0	Negative
1	GD	Maintenance Garage	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Maintenance Garage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Maintenance Garage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 18	W1	CMU	White	None	0	0.01	Negative
1	GD	Classroom 18	W2	CMU	White	None	0	0.05	Negative
1	GD	Classroom 18	W3	Concrete	Purple	None	0	0.04	Negative
1	GD	Classroom 18	W4	CMU	White	None	0	0.03	Negative
1	GD	Classroom 18	Ceiling	Concrete	White	None	0	0.06	Negative
1	GD	Classroom 18	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 18	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Storage in Classroom 16	W1	CMU	White	None	0	0	Negative
1	GD	Storage in Classroom 16	W2	CMU	White	None	0	0	Negative
1	GD	Storage in Classroom 16	W3	CMU	White	None	0	0	Negative
1	GD	Storage in Classroom 16	W4	CMU	White	None	0	0	Negative
1	GD	Storage in Classroom 16	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Storage in Classroom 16	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Storage in Classroom 16	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Other Storage in Classroom 16	W1	CMU	White	None	0	0	Negative
1	GD	Other Storage in Classroom 16	W2	CMU	White	None	0	0	Negative
1	GD	Other Storage in Classroom 16	W3	CMU	White	None	0	0	Negative
1	GD	Other Storage in Classroom 16	W4	CMU	White	None	0	0	Negative
1	GD	Other Storage in Classroom 16	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Other Storage in Classroom 16	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Other Storage in Classroom 16	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 16	W1	CMU	White	None	0	0.01	Negative
1	GD	Classroom 16	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 16	W3	Concrete	White	None	0	0.04	Negative
1	GD	Classroom 16	W4	CMU	White	None	0	0.04	Negative
1	GD	Classroom 16	Ceiling	Concrete	White	None	0	0.03	Negative
1	GD	Classroom 16	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 16	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Office in Classroom 16	W1	CMU	White	None	0	0.01	Negative
1	GD	Office in Classroom 16	W2	CMU	White	None	0	0	Negative
1	GD	Office in Classroom 16	W3	Concrete	White	None	0	0.04	Negative
1	GD	Office in Classroom 16	W4	CMU	White	None	0	0.04	Negative
1	GD	Office in Classroom 16	Ceiling	Concrete	White	None	0	0.03	Negative
1	GD	Office in Classroom 16	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Office in Classroom 16	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	REC Room	W1	CMU	White	None	0	0	Negative
1	GD	REC Room	W2	CMU	White	None	0	0	Negative
1	GD	REC Room	W3	CMU	White	None	0	0	Negative
1	GD	REC Room	W4	CMU	White	None	0	0	Negative
1	GD	REC Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	REC Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	REC Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	REC Room	Radiator	Metal	White	None	0	0	Negative
1	GD	Kitchen Office	W1	CMU	White	None	0	0	Negative
1	GD	Kitchen Office	W2	CMU	White	None	0	0	Negative
1	GD	Kitchen Office	W3	CMU	White	None	0	0	Negative
1	GD	Kitchen Office	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>						
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	GD	Kitchen Office	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Kitchen Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Kitchen Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Kitchen Office	Radiator	Metal	White	None	0	0	Negative
1	GD	The Beacon	W1	CMU	White	None	0	0	Negative
1	GD	The Beacon	W2	CMU	White	None	0	0	Negative
1	GD	The Beacon	W3	CMU	White	None	0	0	Negative
1	GD	The Beacon	W4	CMU	White	None	0	0	Negative
1	GD	The Beacon	Ceiling	Concrete	White	None	0	0	Negative
1	GD	The Beacon	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	The Beacon	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Cafeteria	Ceiling	Metal	White	None	0	0	Negative
1	GD	Cafeteria	Column	Concrete	Blue	None	0	0	Negative
1	GD	Cafeteria	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria	W1	CMU	White	None	0	0	Negative
1	GD	Cafeteria	W2	CMU	White	None	0	0	Negative
1	GD	Cafeteria	W3	CMU	White	None	0	0	Negative
1	GD	Cafeteria	W4	CMU	Multi	None	0	0	Negative
1	GD	Cafeteria	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Cafeteria	Radiator	Metal	Blue	None	0	0	Negative
1	GD	Cafeteria	Door Frame 1	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 2	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 3	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 4	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 5	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 6	Metal	Blue	Chipping	2	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Cafeteria	Door Frame 7	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 8	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 9	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door Frame 10	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 1	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 2	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 3	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 4	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 5	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 6	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 7	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Door 8	Metal	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 1	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 2	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 3	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 4	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 5	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 6	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 7	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 8	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 9	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 10	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 11	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 12	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 13	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 14	Concrete	Blue	Chipping	2	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Cafeteria	Column 15	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 16	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 17	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 18	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 19	Concrete	Blue	Chipping	2	0	Negative
1	GD	Cafeteria	Column 20	Concrete	Blue	Chipping	2	0	Negative
1	GD	Kitchen Office Storage	W1	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Storage	W2	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Storage	W3	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Storage	W4	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Storage	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Kitchen Office Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Kitchen Office Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Kitchen Office Storage	Radiator	Metal	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Kitchen Office Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Kitchen Office Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Kitchen Office Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Staff Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Staff Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Staff Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Staff Restroom	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Staff Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Staff Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Staff Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Staff Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Student Restroom #2	W1	CMU	White	None	0	0	Negative
1	GD	Student Restroom #2	W2	CMU	White	None	0	0	Negative
1	GD	Student Restroom #2	W3	CMU	White	None	0	0	Negative
1	GD	Student Restroom #2	W4	CMU	White	None	0	0	Negative
1	GD	Student Restroom #2	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Student Restroom #2	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Student Restroom #2	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Student Restroom #2	Radiator	Metal	White	None	0	0	Negative
1	GD	Student Restroom #1	W1	CMU	White	None	0	0	Negative
1	GD	Student Restroom #1	W2	CMU	White	None	0	0	Negative
1	GD	Student Restroom #1	W3	CMU	White	None	0	0	Negative
1	GD	Student Restroom #1	W4	CMU	White	None	0	0	Negative
1	GD	Student Restroom #1	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Student Restroom #1	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Student Restroom #1	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Student Restroom #1	Radiator	Metal	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	W1	CMU	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	W2	CMU	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	W3	CMU	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	W4	CMU	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Mens Restroom Next to Ladies Locker Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Mens Restroom Next to Ladies Locker Room	Radiator	Metal	White	None	0	0	Negative
1	GD	Ladies Locker Room Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Ladies Locker Room Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Ladies Locker Room Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Compressor Room	W1	CMU	White	Cracking	10	0	Negative
1	GD	Compressor Room	W2	CMU	White	Cracking	10	0	Negative
1	GD	Compressor Room	W3	CMU	White	Cracking	10	0	Negative
1	GD	Compressor Room	W4	CMU	White	Cracking	10	0	Negative
1	GD	Compressor Room	Ceiling	Concrete	White	Cracking	10	0	Negative
1	GD	Compressor Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Compressor Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	W1	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	W2	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	W3	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	W4	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria Kitchen - Dry Storage (right side from rear entrance)	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Cafeteria Kitchen	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria Kitchen	W1	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen	W2	CMU	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Cafeteria Kitchen	W3	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen	W4	CMU	White	None	0	0	Negative
1	GD	Cafeteria Kitchen	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Cafeteria Kitchen	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria Kitchen	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Cafeteria Kitchen	Radiator	Metal	White	None	0	0	Negative
1	GD	Cafeteria Serving Area	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria Serving Area	Column 1	concrete	White	None	0	0	Negative
1	GD	Cafeteria Serving Area	Column 2	concrete	White	None	0	0	Negative
1	GD	Cafeteria Serving Area	Pipe 1	Metal	White	Flaking	2	0	Negative
1	GD	Cafeteria Serving Area	Pipe 2	Metal	White	Flaking	2	0	Negative
1	GD	Cafeteria Serving Area	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Cafeteria Serving Area	W2	CMU	White	None	0	0	Negative
1	GD	Cafeteria Serving Area	W3	CMU	White	None	0	0	Negative
1	GD	Cafeteria Serving Area	W4	CMU	Multi	None	0	0	Negative
1	GD	Cafeteria Serving Area	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	W1	CMU	White	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	W2	CMU	White	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	W3	CMU	White	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	W4	CMU	White	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Hallway from BE Office to Classroom 22	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Hallway from Classroom 13-17	W1	CMU	White	None	0	0	Negative
1	GD	Hallway from Classroom 13-17	W2	CMU	White	None	0	0	Negative
1	GD	Hallway from Classroom 13-17	W3	CMU	White	None	0	0	Negative
1	GD	Hallway from Classroom 13-17	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Hallway from Classroom 13-17	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Hallway from Classroom 13-17	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Boys Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Boys Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Boys Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Boys Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Girls Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Girls Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Girls Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Girls Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Mens Faculty Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Mens Faculty Restroom	Radiator	Metal	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Womens Faculty Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Womens Faculty Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Womens Faculty Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	W1	CMU	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	W2	CMU	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	W3	CMU	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	W4	CMU	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Garage Across Classroom 13	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Garage Across Classroom 13	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Building Engineer's Office Storage	W1	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Storage	W2	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Storage	W3	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Storage	W4	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Storage	Ceiling	Concrete	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Building Engineer's Office Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Building Engineer's Office Restroom	W1	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Restroom	W2	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Restroom	W3	CMU	Grey	None	0	0	Negative
1	GD	Building Engineer's Office Restroom	W4	CMU	Grey	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	GD	Building Engineer's Office Restroom	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Building Engineer's Office Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Building Engineer's Office Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Building Engineer's Office Restroom	Radiator	Metal	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	W1	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	W2	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	W3	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	W4	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Building Engineer's Office Closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Building Engineer's Office Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Building Engineer's Office	W1	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office	W2	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office	W3	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office	W4	CMU	Grey	None	0	0	Negative	
1	GD	Building Engineer's Office	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Building Engineer's Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Building Engineer's Office	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Building Engineer's Office	Radiator	Metal	Grey	None	0	0	Negative	
1	GD	Dean's Office	W1	SheetRock	White	None	0	0	Negative	
1	GD	Dean's Office	W2	SheetRock	White	None	0	0	Negative	
1	GD	Dean's Office	W3	CMU	White	None	0	0	Negative	
1	GD	Dean's Office	W4	CMU	White	None	0	0	Negative	
1	GD	Dean's Office	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Dean's Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Dean's Office	Column	Concrete	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Dean's Office	Door Frame	Metal	Tan	Chipping	2	0	Negative
1	GD	Dean's Office	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 023	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 023	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 023	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 023	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 023	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 023	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 023	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 023	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 023	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	Ceiling	Concrete	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 22 Closet (IDF-12 Room)	Column	Concrete	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	W1	CMU	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	W2	CMU	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	W3	CMU	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	W4	CMU	Green	None	0	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	Door Frame	Metal	Green	Chipping	2	0	Negative
1	GD	Classroom 22 Closet (IDF-12 Room)	Radiator	Metal	Green	None	0	0	Negative
1	GD	Classroom 22	Column	Concrete	Green	None	0	0	Negative
1	GD	Classroom 22	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 22	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 22	W1	CMU	Green	None	0	0	Negative
1	GD	Classroom 22	W2	CMU	Green	None	0	0	Negative
1	GD	Classroom 22	W3	CMU	Green	Chipping	40	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 22	W4	CMU	Green	None	0	0	Negative
1	GD	Classroom 22	Door Frame	Metal	White	None	0	0	Negative
1	GD	Classroom 22	Radiator	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 021	Column	Concrete	White	Chipping	5	0	Negative
1	GD	Classroom 021	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 021	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 021	W1	CMU	Blue	None	0	0	Negative
1	GD	Classroom 021	W2	CMU	Blue	None	0	0	Negative
1	GD	Classroom 021	W3	CMU	Blue	None	0	0	Negative
1	GD	Classroom 021	W4	CMU	Blue	None	0	0	Negative
1	GD	Classroom 021	Door frame	Metal	Blue	None	0	0	Negative
1	GD	Classroom 021	Radiator	Metal	White	None	0	0	Negative
1	GD	School Police	W1	CMU	Grey	None	0	0	Negative
1	GD	School Police	W2	CMU	Grey	None	0	0	Negative
1	GD	School Police	W3	CMU	Grey	None	0	0	Negative
1	GD	School Police	W4	CMU	Grey	None	0	0	Negative
1	GD	School Police	Ceiling	Concrete	White	None	0	0	Negative
1	GD	School Police	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	School Police	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	School Police	Radiator	Metal	Grey	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	Ceiling	CMU	White	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 019 (Business Academy)	W1	CMU	Blue	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 019 (Business Academy)	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Classroom 019 (Business Academy)	Radiator	Metal	White	None	0	0	Negative
1	GD	Service Closet	W1	CMU	White	None	0	0	Negative
1	GD	Service Closet	W2	CMU	White	None	0	0	Negative
1	GD	Service Closet	W3	CMU	White	None	0	0	Negative
1	GD	Service Closet	W4	CMU	White	None	0	0	Negative
1	GD	Service Closet	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Service Closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Service Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Girls Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Girls Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Girls Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Girls Restroom	Radiator	Metal	Grey	None	0	0	Negative
1	GD	Classroom 017 (Sewing)	W1	CMU	Blue	Chipping	5	0.04	Negative
1	GD	Classroom 017 (Sewing)	W2	CMU	Green	None	0	0.03	Negative
1	GD	Classroom 017 (Sewing)	W3	CMU	Green	Flaking	5	0.02	Negative
1	GD	Classroom 017 (Sewing)	W4	CMU	Green	None	0	0	Negative
1	GD	Classroom 017 (Sewing)	Ceiling	Concrete	White	None	0	0.03	Negative
1	GD	Classroom 017 (Sewing)	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 017 (Sewing)	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Classroom 017 (Sewing)	Radiator	Metal	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	GD	Boys Restroom	Ceiling	CMU	White	Flaking	200	0	Negative	
1	GD	Boys Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Boys Restroom	Radiator	Metal	White	None	0	0	Negative	
1	GD	Boys Restroom	Door Frame	Metal	Blue	Chipping	2	0	Negative	
1	GD	Boys Restroom	W1	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W2	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W3	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W4	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W1	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W2	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W3	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	W4	CMU	White	None	0	0	Negative	
1	GD	Boys Restroom	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Boys Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Boys Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Boys Restroom	Radiator	Metal	Grey	None	0	0	Negative	
1	GD	Classroom 015	W1	CMU	Green	None	0	0.1	Negative	
1	GD	Classroom 015	W2	CMU	Green	Cracking	5	0.04	Negative	
1	GD	Classroom 015	W3	CMU	Green	Flaking	10	0.02	Negative	
1	GD	Classroom 015	W4	CMU	Green	None	0	0	Negative	
1	GD	Classroom 015	Ceiling	Concrete	White	None	0	0.03	Negative	
1	GD	Classroom 015	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Classroom 015	Door Frame	Metal	Blue	None	0	0	Negative	
1	GD	Classroom 015	Radiator	Metal	White	None	0	0	Negative	
1	GD	Classroom 014	W1	CMU	White	None	0	0	Negative	
1	GD	Classroom 014	W2	CMU	White	None	0	0	Negative	



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 014	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 014	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 014	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 014	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 014	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 014	Radiator	Metal	Grey	None	0	0	Negative
1	GD	Classroom 013 Closet	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 013 Closet	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 013 Closet	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 013 Closet	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 013 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 013 Closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 013 Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 013	W1	CMU	Green	None	0	0.1	Negative
1	GD	Classroom 013	W2	CMU	Green	Cracking	5	0.04	Negative
1	GD	Classroom 013	W3	CMU	Green	Flaking	10	0.02	Negative
1	GD	Classroom 013	W4	CMU	Green	None	0	0	Negative
1	GD	Classroom 013	Ceiling	Concrete	White	None	0	0.03	Negative
1	GD	Classroom 013	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 013	Door Frame	Metal	Blue	None	0	0	Negative
1	GD	Classroom 013	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 12	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 12	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 12	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 12	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 12	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	GD	Classroom 12	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Classroom 12	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Classroom 12	Radiator	Metal	Grey	None	0	0	Negative	
1	GD	Service Closet	W1	CMU	White	None	0	0	Negative	
1	GD	Service Closet	W2	CMU	White	None	0	0	Negative	
1	GD	Service Closet	W3	CMU	White	None	0	0	Negative	
1	GD	Service Closet	W4	CMU	White	None	0	0	Negative	
1	GD	Service Closet	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Service Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Service Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Service Closet 16	W1	CMU	White	None	0	0	Negative	
1	GD	Service Closet 16	W2	CMU	White	None	0	0	Negative	
1	GD	Service Closet 16	W3	CMU	White	None	0	0	Negative	
1	GD	Service Closet 16	W4	CMU	White	None	0	0	Negative	
1	GD	Service Closet 16	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Service Closet 16	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Service Closet 16	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	W1	CMU	White	None	0	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	W2	CMU	White	None	0	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	W3	CMU	White	None	0	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	W4	CMU	White	None	0	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Hallway between Generator Room and Classroom 35	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Classroom 9	Column	Concrete	Green	None	0	0	Negative	
1	GD	Classroom 9	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Classroom 9	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	GD	Classroom 9	W1	CMU	Green	None	0	0	Negative	
1	GD	Classroom 9	W2	CMU	Green	None	0	0	Negative	
1	GD	Classroom 9	W3	CMU	Green	Chipping	20	0	Negative	
1	GD	Classroom 9	W4	CMU	Green	None	0	0	Negative	
1	GD	Classroom 9	Radiator	Metal	White	Chipping	2	0	Negative	
1	GD	Classroom 9	Door Frame	Metal	Blue	Chipping	2	0	Negative	
1	GD	Office in Room 11A	W1	CMU	White	None	0	0.02	Negative	
1	GD	Office in Room 11A	W2	CMU	White	None	0	0.02	Negative	
1	GD	Office in Room 11A	W3	CMU	White	Flaking	10	0	Negative	
1	GD	Office in Room 11A	W4	CMU	White	None	0	0.04	Negative	
1	GD	Office in Room 11A	Ceiling	Concrete	White	None	0	0.06	Negative	
1	GD	Office in Room 11A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Office in Room 11A	Door Frame	Metal	Blue	Chipping	2	0	Negative	
1	GD	Classroom 7	W1	CMU	White	None	0	0.02	Negative	
1	GD	Classroom 7	W2	CMU	White	None	0	0.02	Negative	
1	GD	Classroom 7	W3	CMU	White	Flaking	10	0	Negative	
1	GD	Classroom 7	W4	CMU	White	None	0	0.04	Negative	
1	GD	Classroom 7	Ceiling	Concrete	White	None	0	0.06	Negative	
1	GD	Classroom 7	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Classroom 7	Door Frame	Metal	Blue	Chipping	2	0	Negative	
1	GD	Classroom 7	Radiator	Metal	White	None	0	0	Negative	
1	GD	Womens Faculty Restroom	Ceiling	Concrete	White	None	0	0	Negative	
1	GD	Womens Faculty Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	GD	Womens Faculty Restroom	W1	CMU	White	None	0	0	Negative	
1	GD	Womens Faculty Restroom	W2	CMU	White	None	0	0	Negative	
1	GD	Womens Faculty Restroom	W3	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Womens Faculty Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Womens Faculty Restroom	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 5	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 5	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 5	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 5	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 5	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 5	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 5	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 5	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 5	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Girls Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Girls Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Girls Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Girls Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Girls Restroom	Radiator	Metal	Grey	None	0	0	Negative
1	GD	Mens Faculty Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Mens Faculty Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Mens Faculty Restroom	Radiator	Metal	White	None	0	0	Negative
1	GD	Mens Faculty Restroom	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 39	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 39	ceiling	CMU	White	Flaking	200	0	Negative
1	GD	Classroom 39	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 39	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 39	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 39	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 39	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 39	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 39	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 39	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 39	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 39	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 39	Radiator	Metal	White	None	0	0	Negative
1	GD	Generator Room	W1	CMU	White	None	0	0	Negative
1	GD	Generator Room	W2	CMU	White	None	0	0	Negative
1	GD	Generator Room	W3	CMU	White	None	0	0	Negative
1	GD	Generator Room	W4	CMU	White	None	0	0	Negative
1	GD	Generator Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Generator Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Generator Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 37	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 37	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 37	W3	Concrete	White	None	0	0	Negative
1	GD	Classroom 37	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 37	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 37	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 37	Door frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 37	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 37	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 37	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 37	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 37	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 37	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 37	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 37	Radiator	Metal	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	W1	CMU	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	W2	CMU	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	W3	CMU	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	W4	CMU	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Service Closet accross from Classroom 17	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Service Closet accross from Classroom 17	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Boys Restroom	W1	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W2	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W3	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	W4	CMU	White	None	0	0	Negative
1	GD	Boys Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Boys Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Boys Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Boys Restroom	Radiator	Metal	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 35	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 35	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 35	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 35	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 35	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 35	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 35	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 35	Radiator	Metal	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	W1	CMU	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	W2	CMU	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	W3	CMU	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	W4	CMU	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Custodial Service Storage and Lounge	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Custodial Service Storage and Lounge	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Custodial Service Storage and Lounge	Radiator	Metal	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	W1	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	W2	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	W3	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	W4	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Storage Closet in Discipline Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Storage Closet in Discipline Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 33	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 33	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 33	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 33	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 33	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 33	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 33	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 33	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 33	Radiator	Metal	Blue	Chipping	25	0	Negative
1	GD	Back Room	W1	CMU	White	None	0	0	Negative
1	GD	Back Room	W2	CMU	White	None	0	0	Negative
1	GD	Back Room	W3	CMU	White	None	0	0	Negative
1	GD	Back Room	W4	CMU	White	None	0	0	Negative
1	GD	Back Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Back Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Back Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 31	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 31	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 31	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 31	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 31	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 31	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 31	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 31	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 31	Radiator	Metal	Blue	Chipping	25	0	Negative
1	GD	Classroom 3	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 3	Ceiling	Concrete	White	Chipping	20	0	Negative
1	GD	Classroom 3	W1	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 3	W2	CMU	Yellow	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 3	W3	CMU	Yellow	Chipping	5	0	Negative
1	GD	Classroom 3	W4	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 3	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 3	Radiator	Metal	White	Chipping	5	0	Negative
1	GD	Classroom 3	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 3	W1	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 3	W2	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 3	W3	CMU	Yellow	Flaking	50	0	Negative
1	GD	Classroom 3	W4	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 3	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 3	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 3	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 3	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 25 Closet	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 25 Closet	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 25 Closet	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 25 Closet	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 25 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 25 Closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 25 Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 29	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 29	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 29	W1	CMU	White	None	0	0	Negative
1	GD	Classroom 29	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 29	W3	CMU	White	None	0	0	Negative
1	GD	Classroom 29	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 29	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 29	Radiator	Metal	Blue	Flaking	30	0	Negative
1	GD	Classroom 29	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 027 Media Room	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 027 Media Room	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 027 Media Room	W1	CMU	Blue	None	0	0	Negative
1	GD	Classroom 027 Media Room	W2	CMU	Blue	None	0	0	Negative
1	GD	Classroom 027 Media Room	W3	CMU	Blue	None	0	0	Negative
1	GD	Classroom 027 Media Room	W4	CMU	Blue	None	0	0	Negative
1	GD	Classroom 027 Media Room	Radiator	Metal	White	Chipping	2	0	Negative
1	GD	Classroom 027 Media Room	Door Frame	Metal	White	None	0	0	Negative
1	GD	Classroom 027 Media Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 25	Column	Concrete	White	None	0	0	Negative
1	GD	Classroom 25	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 25	Ceiling	Concrete	White	Flaking	20	0	Negative
1	GD	Classroom 25	W1	CMU	Green	None	0	0	Negative
1	GD	Classroom 25	W2	CMU	White	None	0	0	Negative
1	GD	Classroom 25	W3	CMU	White	Flaking	15	0	Negative
1	GD	Classroom 25	W4	CMU	White	None	0	0	Negative
1	GD	Classroom 25	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 25	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Room 11A	W1	CMU	White	None	0	0	Negative
1	GD	Room 11A	W2	CMU	White	None	0	0	Negative
1	GD	Room 11A	W3	CMU	White	None	0	0	Negative
1	GD	Room 11A	W4	CMU	White	None	0	0	Negative
1	GD	Room 11A	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Room 11A	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Room 11A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Room 11A	Radiator	Metal	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	W1	CMU	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	W2	CMU	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	W3	CMU	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	W4	CMU	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Service Closet outside Room 11A	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Service Closet outside Room 11A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 11	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 11	Column	Concrete	Green	Chipping	15	0	Negative
1	GD	Classroom 11	W1	CMU	Green	None	0	0	Negative
1	GD	Classroom 11	W2	CMU	Green	None	0	0	Negative
1	GD	Classroom 11	W3	CMU	Green	None	0	0	Negative
1	GD	Classroom 11	W4	CMU	Green	None	0	0	Negative
1	GD	Classroom 11	Radiator	Metal	White	None	0	0	Negative
1	GD	Classroom 11	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Storage Closet in Room 11A	W1	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Room 11A	W2	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Room 11A	W3	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Room 11A	W4	CMU	White	None	0	0	Negative
1	GD	Storage Closet in Room 11A	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Storage Closet in Room 11A	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Storage Closet in Room 11A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Storage Closet in Room 11A	Radiator	Metal	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Classroom 1	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 1	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 1	W1	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	W2	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	W3	CMU	Yellow	Flaking	15	0	Negative
1	GD	Classroom 1	W4	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	GD	Classroom 1	Radiator	Metal	White	Chipping	5	0	Negative
1	GD	Classroom 1	Column	Concrete	White	Flaking	15	0	Negative
1	GD	Classroom 1	W1	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	W2	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	W3	CMU	Yellow	Flaking	50	0	Negative
1	GD	Classroom 1	W4	CMU	Yellow	None	0	0	Negative
1	GD	Classroom 1	Ceiling	Concrete	White	None	0	0	Negative
1	GD	Classroom 1	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	GD	Classroom 1	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	GD	Classroom 1	Radiator	Metal	White	None	0	0	Negative
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Women's Faculty Restroom Pipe Chase (Located in adjace	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Pipe Chase in Men's Faculty Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Pipe Chase in Men's Faculty Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Pipe Chase in Men's Faculty Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	GD	Pipe Chase in Men's Faculty Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	GD	Pipe Chase in Men's Faculty Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	GD	Pipe Chase in Men's Faculty Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	South Chiller Crawlspace - Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	North Chiller Crawlspace - Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawl Space near stairwell 3	W1	CMU	White	None	0	0	Negative
1	CS	Crawl Space near stairwell 3	W2	CMU	White	None	0	0	Negative
1	CS	Crawl Space near stairwell 3	W3	CMU	White	None	0	0	Negative
1	CS	Crawl Space near stairwell 3	W4	CMU	White	None	0	0	Negative
1	CS	Crawl Space near stairwell 3	Ceiling	Concrete	White	None	0	0	Negative
1	CS	Crawl Space near stairwell 3	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Boiler Room Crawlspace	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Boiler Room Crawlspace	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Boiler Room Crawlspace	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Boiler Room Crawlspace	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Boiler Room Crawlspace	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	CS	Boiler Room Crawlspace	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near stairwell #1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	CS	Crawlspace near Building Enginners Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Hallway from Old Restroom to Old Pump Room	W1	CMU	White	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	W2	CMU	White	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	W2	CMU	Grey	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	W3	CMU	White	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	W4	CMU	White	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	W4	CMU	Grey	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	Ceiling	Concrete	White	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Hallway from Old Restroom to Old Pump Room	Door	Metal	Blue	None	0	0	Negative
1	BS	Hallway from Old Restroom to Old Pump Room	Door Frame	Metal	Blue	None	0	0	Negative
1	BS	Old Pump Room	W1	CMU	White	None	0	0	Negative
1	BS	Old Pump Room	W2	CMU	White	None	0	0	Negative
1	BS	Old Pump Room	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	BS	Old Pump Room	W4	CMU	White	None	0	0	Negative
1	BS	Old Pump Room	Ceiling	Concrete	White	None	0	0	Negative
1	BS	Old Pump Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Old Pump Room	Door	Metal	Blue	None	0	0	Negative
1	BS	Old Pump Room	Door Frame	Metal	Blue	None	0	0	Negative
1	BS	Old Restroom	W1	CMU	White	None	0	0	Negative
1	BS	Old Restroom	W2	CMU	White	None	0	0	Negative
1	BS	Old Restroom	W3	CMU	White	None	0	0	Negative
1	BS	Old Restroom	W4	CMU	White	None	0	0	Negative
1	BS	Old Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	BS	Old Restroom	Floor	Concrete	Grey	None	0	0	Negative
1	BS	Old Restroom	Door	Metal	Blue	None	0	0	Negative
1	BS	Old Restroom	Door Frame	Metal	Blue	None	0	0	Negative
1	BS	Room Next to Boiler Room	W1	CMU	White	None	0	0	Negative
1	BS	Room Next to Boiler Room	W2	Concrete	White	Chipping	15	0	Negative
1	BS	Room Next to Boiler Room	W3	CMU	White	None	0	0	Negative
1	BS	Room Next to Boiler Room	W4	Concrete	White	Chipping	15	0	Negative
1	BS	Room Next to Boiler Room	Ceiling	Concrete	White	Chipping	15	0	Negative
1	BS	Room Next to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Room Next to Boiler Room	Pipe	Metal	Grey	None	0	0	Negative
1	BS	Room Next to Boiler Room	Handrail	Metal	Grey	None	0	0	Negative
1	BS	Room Next to Boiler Room	Duct	Metal	White	None	0	0	Negative
1	BS	Room Next to Boiler Room	Riser	Concrete	White	None	0	0	Negative
1	BS	Room Next to Boiler Room	Column 1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Room Next to Boiler Room	Column 1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Room Next to Boiler Room	Column 2	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	BS	Room Next to Boiler Room	Column 2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Room Next to Boiler Room	Column 2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Room Next to Boiler Room	Column 2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Chimney Room	W1	Brick	Grey	Chipping	5	0	Negative
1	BS	Chimney Room	W2	CMU	Grey	Chipping	5	0	Negative
1	BS	Chimney Room	W3	CMU	Grey	Chipping	5	0	Negative
1	BS	Chimney Room	W4	CMU	Grey	Chipping	5	0	Negative
1	BS	Chimney Room	Ceiling	Concrete	Grey	Chipping	15	0	Negative
1	BS	Chimney Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Chimney Room	Stringer	Metal	Black	None	0	0	Negative
1	BS	Chimney Room	Tread	Metal	Black	None	0	0	Negative
1	BS	Chimney Room	Handrail	Metal	Black	None	0	0	Negative
1	BS	Long Room Next to Boiler Room	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Long Room Next to Boiler Room	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Long Room Next to Boiler Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Long Room Next to Boiler Room	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Long Room Next to Boiler Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Long Room Next to Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Boiler Room	W1	CMU	White	None	0	0	Negative
1	BS	Boiler Room	W2	CMU	White	None	0	0	Negative
1	BS	Boiler Room	W3	Concrete	White	None	0	0	Negative
1	BS	Boiler Room	W4	Concrete	White	None	0	0	Negative
1	BS	Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
1	BS	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	BS	Boiler Room	Pipe	Metal	Grey	None	0	0	Negative
1	BS	Boiler Room	Stringer	Metal	Grey	None	0	2.1	Positive



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	BS	Boiler Room	Tread	Metal	Grey	None	0	1.8	Positive
1	BS	Boiler Room	Handrail	Metal	Blue	None	0	0	Negative
1	BS	Boiler Room	Door Frame	Metal	Blue	None	0	0	Negative
1	BS	Boiler Room	Door	Metal	Blue	None	0	0	Negative
1	BS	Boiler Room	Boiler	Metal	Blue	None	0	0	Negative
1	BS	Boiler Room	I Beam	Metal	Grey	None	0	0	Negative
1	A	Attic- Closet/Rear of Gym	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic- Closet/Rear of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairs adjacent to Classroom 330	W1	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 330	W2	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 330	W3	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 330	W4	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 330	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 330	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairs adjacent to Classroom 330	Door	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 330	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Stairs adjacent to Classroom 330	Stringer	Metal	Grey	Chipping	2	3.2	Positive
1	3	Stairs adjacent to Classroom 330	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairs adjacent to Classroom 330	Riser	Metal	Grey	Chipping	2	2.4	Positive
1	3	Stairs adjacent to Classroom 330	Newell Post	Metal	Grey	Chipping	2	5.2	Positive
1	3	Stairs adjacent to Classroom 330	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 324	W1	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 324	W2	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 324	W3	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 324	W4	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 324	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 324	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairs adjacent to Classroom 324	Door	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 324	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 324	Stringer	Metal	Grey	Chipping	2	3.1	Positive
1	3	Stairs adjacent to Classroom 324	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairs adjacent to Classroom 324	Riser	Metal	Grey	Chipping	2	1.5	Positive
1	3	Stairs adjacent to Classroom 324	Newell Post	Metal	Grey	Chipping	2	4.3	Positive
1	3	Stairs adjacent to Classroom 324	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 312	W1	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 312	W2	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 312	W3	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 312	W4	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 312	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 312	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairs adjacent to Classroom 312	Door	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 312	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Stairs adjacent to Classroom 312	Stringer	Metal	Grey	Chipping	2	6.1	Positive
1	3	Stairs adjacent to Classroom 312	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairs adjacent to Classroom 312	Riser	Metal	Grey	Chipping	2	2.2	Positive
1	3	Stairs adjacent to Classroom 312	Newell Post	Metal	Grey	Chipping	2	3.5	Positive
1	3	Stairs adjacent to Classroom 312	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 300	W1	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 300	W2	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 300	W3	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 300	W4	CMU	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 300	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairs adjacent to Classroom 300	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairs adjacent to Classroom 300	Door	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 300	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Stairs adjacent to Classroom 300	Stringer	Metal	Grey	Chipping	2	4.1	Positive
1	3	Stairs adjacent to Classroom 300	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairs adjacent to Classroom 300	Riser	Metal	Grey	Chipping	2	2.3	Positive
1	3	Stairs adjacent to Classroom 300	Newell Post	Metal	Grey	Chipping	2	1.1	Positive
1	3	Stairs adjacent to Classroom 300	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Hallway from Classroom 332-339	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 332-339	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 332-339	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 332-339	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 332-339	Ceiling	Concrete	White	None	0	0	Negative
1	3	Hallway from Classroom 332-339	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 314-322	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 314-322	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Hallway from Classroom 314-322	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 314-322	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 314-322	Ceiling	Concrete	White	None	0	0	Negative
1	3	Hallway from Classroom 314-322	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 324-330	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 324-330	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 324-330	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 324-330	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 324-330	Ceiling	Concrete	White	None	0	0	Negative
1	3	Hallway from Classroom 324-330	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classroom 300-312	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 300-312	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 300-312	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 300-312	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classroom 300-312	Ceiling	Concrete	White	None	0	0	Negative
1	3	Hallway from Classroom 300-312	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Closet in Classroom 328	W1	CMU	White	None	0	0.02	Negative
1	3	Closet in Classroom 328	W2	CMU	White	None	0	0	Negative
1	3	Closet in Classroom 328	W3	CMU	White	None	0	0.01	Negative
1	3	Closet in Classroom 328	W4	CMU	White	None	0	0.02	Negative
1	3	Closet in Classroom 328	Ceiling	Concrete	White	None	0	0	Negative
1	3	Closet in Classroom 328	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Closet in Classroom 328	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Closet in Classroom 328	Radiator	Metal	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	W1	CMU	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Boy's Restroom at Classroom 339	W3	CMU	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	W4	CMU	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	Ceiling	Concrete	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom at Classroom 339	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Boy's Restroom at Classroom 339	Radiator	Metal	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 339	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	W1	CMU	Blue	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	W2	CMU	Blue	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	W3	CMU	Blue	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	W4	CMU	Blue	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	Ceiling	Concrete	White	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 334 and 336	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Mini Connector at Back of Classroom 334 and 336	Door Frame	Metal	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	W1	CMU	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	W2	CMU	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	W3	CMU	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	W4	CMU	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	Ceiling	Concrete	White	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet Between Classroom 334 and 336	Door Frame	Metal	Blue	None	0	0	Negative
1	3	Storage Closet Between Classroom 334 and 336	Duct	Metal	White	None	0	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	W1	CMU	Yellow	Chipping	2	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	W2	CMU	Yellow	Chipping	5	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	W3	CMU	Yellow	Chipping	1	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	W4	CMU	Yellow	Chipping	5	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Mini Connector at Back of Classroom 327 and 329	Ceiling	Concrete	White	Chipping	25	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Mini Connector at Back of Classroom 327 and 329	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Mini Connector at Back of Classroom 327 and 329	Radiator	Metal	White	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	W1	CMU	Yellow	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	W2	CMU	Yellow	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	W3	CMU	Yellow	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	W4	CMU	Yellow	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	Ceiling	Concrete	White	None	0	0	Negative
1	3	Storage Closet Between Classroom 327 and 329	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet Between Classroom 327 and 329	Door Frame	Metal	Gray	None	0	0	Negative
1	3	Science Laboratory Storage	W1	CMU	Blue	None	0	0	Negative
1	3	Science Laboratory Storage	W2	CMU	Blue	None	0	0	Negative
1	3	Science Laboratory Storage	W3	CMU	Blue	None	0	0	Negative
1	3	Science Laboratory Storage	W4	CMU	Blue	None	0	0	Negative
1	3	Science Laboratory Storage	Ceiling	Concrete	White	None	0	0.03	Negative
1	3	Science Laboratory Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Science Laboratory Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Science Laboratory Storage	Radiator	Metal	Blue	None	0	0	Negative
1	3	Science Office	W1	CMU	Blue	None	0	0.01	Negative
1	3	Science Office	W2	CMU	Blue	None	0	0.02	Negative
1	3	Science Office	W3	CMU	Blue	None	0	0.02	Negative
1	3	Science Office	W4	CMU	Blue	None	0	0.05	Negative
1	3	Science Office	Ceiling	Concrete	White	None	0	0.03	Negative
1	3	Science Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Science Office	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Science Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	3	Boy's Restroom at Classroom 327	W1	CMU	White	None	0	0.01	Negative
1	3	Boy's Restroom at Classroom 327	W2	CMU	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 327	W3	CMU	White	None	0	0.02	Negative
1	3	Boy's Restroom at Classroom 327	W4	CMU	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 327	Ceiling	Concrete	White	None	0	0	Negative
1	3	Boy's Restroom at Classroom 327	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom at Classroom 327	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Boy's Restroom at Classroom 327	Radiator	Metal	White	None	0	0	Negative
1	3	Girl's Restroom at Classroom 321	W1	CMU	White	None	0	0.01	Negative
1	3	Girl's Restroom at Classroom 321	W2	CMU	White	None	0	0	Negative
1	3	Girl's Restroom at Classroom 321	W3	CMU	White	None	0	0.02	Negative
1	3	Girl's Restroom at Classroom 321	W4	CMU	White	None	0	0	Negative
1	3	Girl's Restroom at Classroom 321	Ceiling	Concrete	White	None	0	0	Negative
1	3	Girl's Restroom at Classroom 321	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom at Classroom 321	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Girl's Restroom at Classroom 321	Door Frame	Metal	White	None	0	0	Negative
1	3	Classroom 339	W1	CMU	White	None	0	0.01	Negative
1	3	Classroom 339	W2	CMU	White	None	0	0.02	Negative
1	3	Classroom 339	W3	Concrete	White	None	0	0.02	Negative
1	3	Classroom 339	W4	CMU	White	None	0	0.05	Negative
1	3	Classroom 339	Ceiling	Concrete	White	None	0	0.03	Negative
1	3	Classroom 339	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 339	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 339	Radiator	Metal	Blue	Chipping	10	0	Negative
1	3	Classroom 338	W1	CMU	White	None	0	0.03	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	3	Classroom 338	W2	CMU	White	None	0	0.04	Negative	
1	3	Classroom 338	W3	Concrete	White	None	0	0.01	Negative	
1	3	Classroom 338	W4	CMU	White	None	0	0.03	Negative	
1	3	Classroom 338	Ceiling	Concrete	White	None	0	0.04	Negative	
1	3	Classroom 338	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 338	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 338	Radiator	Metal	Blue	None	0	0	Negative	
1	3	Classroom 337	W1	CMU	White	None	0	0.01	Negative	
1	3	Classroom 337	W2	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 337	W3	Concrete	White	None	0	0.01	Negative	
1	3	Classroom 337	W4	CMU	White	None	0	0.02	Negative	
1	3	Classroom 337	Ceiling	Concrete	White	None	0	0.04	Negative	
1	3	Classroom 337	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 337	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 337	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 336	W1	CMU	Blue	None	0	0.01	Negative	
1	3	Classroom 336	W2	CMU	Blue	None	0	0.01	Negative	
1	3	Classroom 336	W3	Concrete	Blue	None	0	0.02	Negative	
1	3	Classroom 336	W4	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 336	Ceiling	Concrete	White	None	0	0.04	Negative	
1	3	Classroom 336	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 336	Radiator	Metal	Blue	None	0	0	Negative	
1	3	Classroom 336	Door Frame	Metal	Blue	None	0	0	Negative	
1	3	Classroom 335	W1	CMU	White	None	0	0.01	Negative	
1	3	Classroom 335	W2	CMU	White	None	0	0	Negative	
1	3	Classroom 335	W3	Concrete	White	None	0	0.01	Negative	



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 335	W4	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335	Ceiling	Concrete	White	None	0	0.04	Negative
1	3	Classroom 335	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 335	Radiator	Metal	Blue	Chipping	15	0	Negative
1	3	Classroom 334 Laboratory	W1	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 334 Laboratory	W2	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 334 Laboratory	W3	Concrete	Blue	None	0	0.02	Negative
1	3	Classroom 334 Laboratory	W4	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 334 Laboratory	Ceiling	Concrete	White	None	0	0.05	Negative
1	3	Classroom 334 Laboratory	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334 Laboratory	Door Frame	Metal	Blue	None	0	0	Negative
1	3	Classroom 334 Laboratory	Radiator	Metal	Blue	None	0	0	Negative
1	3	Classroom 334	W1	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 334	W2	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 334	W3	Concrete	Blue	None	0	0.02	Negative
1	3	Classroom 334	W4	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 334	Ceiling	Concrete	White	None	0	0.05	Negative
1	3	Classroom 334	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334	Door Frame	Metal	Blue	None	0	0	Negative
1	3	Classroom 334	Radiator	Metal	Blue	None	0	0	Negative
1	3	Women's Restroom	W1	CMU	White	None	0	0	Negative
1	3	Women's Restroom	W2	CMU	White	None	0	0	Negative
1	3	Women's Restroom	W3	CMU	White	None	0	0	Negative
1	3	Women's Restroom	W4	CMU	White	None	0	0	Negative
1	3	Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Women's Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	3	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Women's Restroom	Radiator	Metal	White	None	0	0	Negative
1	3	Men's Restroom	Radiator	Metal	White	None	0	0	Negative
1	3	Men's Restroom	W2	CMU	White	None	0	0	Negative
1	3	Men's Restroom	W3	CMU	White	None	0	0	Negative
1	3	Men's Restroom	W4	CMU	White	None	0	0	Negative
1	3	Men's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	3	Men's Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Men's Restroom	Radiator	Metal	White	None	0	0	Negative
1	3	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Men's Restroom	Radiator	Metal	White	None	0	0	Negative
1	3	Vice Principal's Office	W1	CMU	Blue	None	0	0	Negative
1	3	Vice Principal's Office	W2	CMU	Blue	None	0	0	Negative
1	3	Vice Principal's Office	W3	CMU	Blue	None	0	0	Negative
1	3	Vice Principal's Office	W4	CMU	Blue	None	0	0	Negative
1	3	Vice Principal's Office	Ceiling	Concrete	White	None	0	0	Negative
1	3	Vice Principal's Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Vice Principal's Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Vice Principal's Office	Radiator	Metal	White	None	0	0	Negative
1	3	Vice Principal's Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Vice Principal's Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 332	W1	CMU	White	None	0	0.1	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	3	Classroom 332	W2	CMU	White	None	0	0.03	Negative	
1	3	Classroom 332	W3	Concrete	White	None	0	0.03	Negative	
1	3	Classroom 332	W4	CMU	White	None	0	0.03	Negative	
1	3	Classroom 332	Ceiling	Concrete	White	Flaking	2	0.07	Negative	
1	3	Classroom 332	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 332	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 332	Radiator	Metal	Blue	Chipping	3	0	Negative	
1	3	Classroom 332	Lockers	Metal	Blue	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	W1	CMU	Yellow	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	W2	CMU	Yellow	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	W3	CMU	Yellow	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	W4	CMU	Yellow	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	Ceiling	Concrete	White	None	0	0	Negative	
1	3	Book Room Next to Classroom 328	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	3	Book Room Next to Classroom 328	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 330	W1	CMU	Blue	None	0	0.01	Negative	
1	3	Classroom 330	W2	CMU	Blue	None	0	0.04	Negative	
1	3	Classroom 330	W3	Concrete	Blue	None	0	0.02	Negative	
1	3	Classroom 330	W4	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 330	Ceiling	Concrete	White	None	0	0.06	Negative	
1	3	Classroom 330	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 330	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 330	Radiator	Metal	Blue	None	0	0	Negative	
1	3	Classroom 329	W1	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 329	W2	CMU	Blue	None	0	0.04	Negative	
1	3	Classroom 329	W3	Concrete	Blue	None	0	0.02	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	3	Classroom 329	W4	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 329	Ceiling	Concrete	White	Chipping	50	0.02	Negative	
1	3	Classroom 329	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 329	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 329	Radiator	Metal	White	Chipping	1	0	Negative	
1	3	Classroom 328	W1	CMU	Blue	None	0	0.01	Negative	
1	3	Classroom 328	W2	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 328	W3	Concrete	Blue	None	0	0.01	Negative	
1	3	Classroom 328	W4	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 328	Ceiling	Concrete	White	None	0	0.06	Negative	
1	3	Classroom 328	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 328	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 328	Radiator	Metal	Blue	None	0	0	Negative	
1	3	Classroom 327	W1	CMU	White	None	0	0.02	Negative	
1	3	Classroom 327	W2	CMU	White	None	0	0.02	Negative	
1	3	Classroom 327	W3	Concrete	White	None	0	0.01	Negative	
1	3	Classroom 327	W4	CMU	White	None	0	0.03	Negative	
1	3	Classroom 327	Ceiling	Concrete	White	None	0	0.02	Negative	
1	3	Classroom 327	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 327	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 327	Radiator	Metal	Blue	Chipping	10	0	Negative	
1	3	Classroom 326	W1	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 326	W2	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 326	W3	Concrete	Blue	Chipping	10	0.01	Negative	
1	3	Classroom 326	W4	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 326	Ceiling	Concrete	White	Chipping	2	0.05	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 326	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 326	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 326	Radiator	Metal	Blue	Chipping	1	0	Negative
1	3	Book Room Next to Classroom 326	W1	CMU	Yellow	None	0	0	Negative
1	3	Book Room Next to Classroom 326	W2	CMU	Yellow	None	0	0	Negative
1	3	Book Room Next to Classroom 326	W3	CMU	Yellow	None	0	0	Negative
1	3	Book Room Next to Classroom 326	W4	CMU	Yellow	None	0	0	Negative
1	3	Book Room Next to Classroom 326	Ceiling	Concrete	White	None	0	0	Negative
1	3	Book Room Next to Classroom 326	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Book Room Next to Classroom 326	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 324	W1	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 324	W2	CMU	Blue	None	0	0.04	Negative
1	3	Classroom 324	W3	Concrete	Blue	None	0	0.02	Negative
1	3	Classroom 324	W4	CMU	Blue	None	0	0.03	Negative
1	3	Classroom 324	Ceiling	Concrete	White	None	0	0.06	Negative
1	3	Classroom 324	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 324	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 324	Radiator	Metal	Blue	None	0	0	Negative
1	3	Science Department Conference Room	W1	CMU	Purple	None	0	0.03	Negative
1	3	Science Department Conference Room	W2	CMU	Purple	None	0	0.04	Negative
1	3	Science Department Conference Room	W3	CMU	White	None	0	0.01	Negative
1	3	Science Department Conference Room	W4	Concrete	White	None	0	0	Negative
1	3	Science Department Conference Room	Ceiling	CMU	White	None	0	0.01	Negative
1	3	Science Department Conference Room	Floor	Concrete	White	None	0	0.05	Negative
1	3	Science Department Conference Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Science Department Conference Room	Radiator	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	3	Classroom 322	W1	CMU	White	None	0	0.01	Negative	
1	3	Classroom 322	W2	CMU	White	None	0	0.02	Negative	
1	3	Classroom 322	W3	Concrete	White	None	0	0.01	Negative	
1	3	Classroom 322	W4	CMU	White	None	0	0.05	Negative	
1	3	Classroom 322	Ceiling	Concrete	White	None	0	0.02	Negative	
1	3	Classroom 322	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 322	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 322	Radiator	Metal	Blue	Chipping	20	0	Negative	
1	3	Classroom 321	W1	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 321	W2	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 321	W3	Concrete	Blue	Chipping	5	0.03	Negative	
1	3	Classroom 321	W4	CMU	Blue	None	0	0.01	Negative	
1	3	Classroom 321	Ceiling	Concrete	White	Cracking	40	0.02	Negative	
1	3	Classroom 321	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 321	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 321	Radiator	Metal	Blue	Chipping	10	0	Negative	
1	3	Classroom 320	W1	CMU	Blue	None	0	0	Negative	
1	3	Classroom 320	W2	CMU	Blue	Moisture Damage	200	0.04	Negative	
1	3	Classroom 320	W3	Concrete	Blue	Chipping	5	0.02	Negative	
1	3	Classroom 320	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 320	Ceiling	Concrete	White	None	0	0.02	Negative	
1	3	Classroom 320	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 320	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 320	Radiator	Metal	Tan	Chipping	5	0	Negative	
1	3	Science Department Office	W1	CMU	White	None	0	0	Negative	
1	3	Science Department Office	W2	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Science Department Office	W3	CMU	White	None	0	0	Negative
1	3	Science Department Office	W4	CMU	White	None	0	0	Negative
1	3	Science Department Office	Ceiling	Concrete	White	None	0	0	Negative
1	3	Science Department Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Science Department Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Science Department Office	Radiator	Metal	Blue	Chipping	4	0	Negative
1	3	Classroom 318	W1	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 318	W2	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318	W3	Concrete	Blue	Chipping	5	0.01	Negative
1	3	Classroom 318	W4	CMU	Blue	None	0	0.05	Negative
1	3	Classroom 318	Ceiling	Concrete	Blue	None	0	0.02	Negative
1	3	Classroom 318	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 318	Radiator	Metal	Blue	None	0	0	Negative
1	3	Science Department Office Storage	W1	CMU	White	None	0	0	Negative
1	3	Science Department Office Storage	W2	CMU	White	None	0	0	Negative
1	3	Science Department Office Storage	W3	CMU	White	None	0	0	Negative
1	3	Science Department Office Storage	W4	CMU	Purple	None	0	0	Negative
1	3	Science Department Office Storage	Ceiling	Concrete	White	None	0	0	Negative
1	3	Science Department Office Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Science Department Office Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 316	W1	CMU	Blue	Moisture Damage	25	0.03	Negative
1	3	Classroom 316	W2	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 316	W3	Concrete	Blue	Chipping	10	0.02	Negative
1	3	Classroom 316	W4	CMU	Blue	Moisture Damage	200	0.03	Negative
1	3	Classroom 316	Ceiling	Concrete	White	Chipping	20	0.01	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	3	Classroom 316	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 316	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 316	Radiator	Metal	Tan	Chipping	1	0	Negative	
1	3	Classroom 315	W1	CMU	Blue	None	0	0.03	Negative	
1	3	Classroom 315	W2	CMU	Blue	None	0	0.05	Negative	
1	3	Classroom 315	W3	Concrete	Blue	Chipping	5	0.02	Negative	
1	3	Classroom 315	W4	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 315	Ceiling	Concrete	White	Cracking	20	0.04	Negative	
1	3	Classroom 315	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 315	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 315	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 314	W1	CMU	Blue	None	0	0	Negative	
1	3	Classroom 314	W2	CMU	Blue	Moisture Damage	200	0.05	Negative	
1	3	Classroom 314	W3	Concrete	Blue	Chipping	10	0.01	Negative	
1	3	Classroom 314	W4	CMU	Blue	None	0	0.02	Negative	
1	3	Classroom 314	Ceiling	Concrete	White	None	0	0.07	Negative	
1	3	Classroom 314	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	3	Classroom 314	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	3	Classroom 314	Radiator	Metal	Tan	Chipping	1	0	Negative	
1	3	Women's Restroom across from Classroom 314	W1	CMU	White	None	0	0	Negative	
1	3	Women's Restroom across from Classroom 314	W2	CMU	White	None	0	0	Negative	
1	3	Women's Restroom across from Classroom 314	W3	CMU	White	None	0	0	Negative	
1	3	Women's Restroom across from Classroom 314	W4	CMU	White	None	0	0	Negative	
1	3	Women's Restroom across from Classroom 314	Ceiling	Concrete	White	None	0	0	Negative	
1	3	Women's Restroom across from Classroom 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	3	Women's Restroom across from Classroom 314	Door Frame	Metal	Blue	Chipping	1	0	Negative	



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Women's Restroom across from Classroom 314	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 312	W1	CMU	Blue	None	0	0.03	Negative
1	3	Classroom 312	W2	CMU	Blue	None	0	0.03	Negative
1	3	Classroom 312	W3	Concrete	Blue	Chipping	10	0.01	Negative
1	3	Classroom 312	W4	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 312	Ceiling	Concrete	White	None	0	0.01	Negative
1	3	Classroom 312	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 312	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Men's Restroom across from Classroom 314	W1	CMU	White	None	0	0	Negative
1	3	Men's Restroom across from Classroom 314	W2	CMU	White	None	0	0	Negative
1	3	Men's Restroom across from Classroom 314	W3	CMU	White	None	0	0	Negative
1	3	Men's Restroom across from Classroom 314	W4	CMU	White	None	0	0	Negative
1	3	Men's Restroom across from Classroom 314	Ceiling	Concrete	White	None	0	0	Negative
1	3	Men's Restroom across from Classroom 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom across from Classroom 314	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Men's Restroom across from Classroom 314	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 310	W1	CMU	White	Chipping	10	0.04	Negative
1	3	Classroom 310	W2	CMU	White	None	0	0.02	Negative
1	3	Classroom 310	W3	Concrete	White	Chipping	10	0.05	Negative
1	3	Classroom 310	W4	CMU	White	None	0	0.01	Negative
1	3	Classroom 310	Ceiling	Concrete	White	Flaking	50	0.09	Negative
1	3	Classroom 310	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 310	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 310	Radiator	Metal	White	Chipping	1	0	Negative
1	3	Classroom 308	W1	CMU	Blue	None	0	0.23	Negative
1	3	Classroom 308	W2	CMU	Tan	None	0	0.04	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 308	W3	Concrete	Blue	None	0	0.02	Negative
1	3	Classroom 308	W4	CMU	Blue	None	0	0.03	Negative
1	3	Classroom 308	Ceiling	Concrete	White	Flaking	10	0.05	Negative
1	3	Classroom 308	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 308	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 308	Radiator	Metal	White	Chipping	1	0	Negative
1	3	Classroom 307	W1	CMU	Blue	Chipping	4	0.01	Negative
1	3	Classroom 307	W2	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 307	W3	Concrete	Blue	Chipping	2	0.03	Negative
1	3	Classroom 307	W4	CMU	Blue	None	0	0.05	Negative
1	3	Classroom 307	Ceiling	Concrete	White	Chipping	15	0.03	Negative
1	3	Classroom 307	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 307	Radiator	Metal	Tan	None	0	0	Negative
1	3	Classroom 306	W1	CMU	Tan	None	0	0.03	Negative
1	3	Classroom 306	W2	CMU	Tan	None	0	0.02	Negative
1	3	Classroom 306	W3	Concrete	White	Chipping	10	0	Negative
1	3	Classroom 306	W4	CMU	Tan	None	0	0.04	Negative
1	3	Classroom 306	Ceiling	Concrete	White	Flaking	10	0.03	Negative
1	3	Classroom 306	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 306	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 306	Radiator	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 305	W1	CMU	Blue	None	0	0.02	Negative
1	3	Classroom 305	W2	CMU	Blue	None	0	0.07	Negative
1	3	Classroom 305	W3	Concrete	Blue	None	0	0.04	Negative
1	3	Classroom 305	W4	CMU	Blue	None	0	0.02	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 305	Ceiling	Concrete	White	Flaking	10	0.04	Negative
1	3	Classroom 305	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 305	Radiator	Metal	Blue	Chipping	10	0	Negative
1	3	Classroom 304	W1	CMU	Tan	None	0	0.06	Negative
1	3	Classroom 304	W2	CMU	Tan	None	0	0.02	Negative
1	3	Classroom 304	W3	Concrete	White	None	0	0.03	Negative
1	3	Classroom 304	W4	CMU	Tan	None	0	0.02	Negative
1	3	Classroom 304	Ceiling	Concrete	White	Flaking	10	0.01	Negative
1	3	Classroom 304	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 304	Radiator	Metal	White	Chipping	1	0	Negative
1	3	Classroom 303	W1	CMU	Blue	Chipping	6	0.01	Negative
1	3	Classroom 303	W2	CMU	Blue	None	0	0.03	Negative
1	3	Classroom 303	W3	Concrete	Blue	Chipping	4	0.01	Negative
1	3	Classroom 303	W4	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 303	Ceiling	Concrete	White	Chipping	2	0.02	Negative
1	3	Classroom 303	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 303	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 303	Radiator	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 302	W1	CMU	Tan	None	0	0.02	Negative
1	3	Classroom 302	W2	CMU	Tan	None	0	0.05	Negative
1	3	Classroom 302	W3	Concrete	White	Chipping	12	0.03	Negative
1	3	Classroom 302	W4	CMU	Tan	None	0	0.04	Negative
1	3	Classroom 302	Ceiling	Concrete	White	Flaking	5	0.08	Negative
1	3	Classroom 302	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 302	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 302	Radiator	Metal	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	W1	CMU	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	W2	CMU	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	W3	CMU	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	W4	CMU	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	Ceiling	Concrete	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom across from Classroom 338	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Girl's Restroom across from Classroom 338	Radiator	Metal	White	None	0	0	Negative
1	3	Girl's Restroom across from Classroom 338	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Girl's Restroom across from Classroom 338	Radiator	Metal	White	None	0	0	Negative
1	3	Classroom 300	W1	CMU	Blue	None	0	0.01	Negative
1	3	Classroom 300	W2	CMU	Tan	None	0	0.04	Negative
1	3	Classroom 300	W3	Concrete	White	None	0	0.02	Negative
1	3	Classroom 300	W4	CMU	Tan	None	0	0.03	Negative
1	3	Classroom 300	Ceiling	Concrete	White	Flaking	5	0.04	Negative
1	3	Classroom 300	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 300	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	3	Classroom 300	Radiator	Metal	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	W1	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	W2	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	W3	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	W4	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 236	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairs adjacent to Classroom 236	Door	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 236	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 236	Stringer	Metal	Grey	Chipping	2	2	Positive
1	2	Stairs adjacent to Classroom 236	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairs adjacent to Classroom 236	Riser	Metal	Grey	Chipping	2	2.5	Positive
1	2	Stairs adjacent to Classroom 236	Newell Post	Metal	Grey	Chipping	2	3.4	Positive
1	2	Stairs adjacent to Classroom 236	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 224	W1	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 224	W2	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 224	W3	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 224	W4	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 224	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 224	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairs adjacent to Classroom 224	Door	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 224	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 224	Stringer	Metal	Grey	Chipping	2	5.1	Positive
1	2	Stairs adjacent to Classroom 224	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairs adjacent to Classroom 224	Riser	Metal	Grey	Chipping	2	2.4	Positive
1	2	Stairs adjacent to Classroom 224	Newell Post	Metal	Grey	Chipping	2	3.3	Positive
1	2	Stairs adjacent to Classroom 224	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 212	W1	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 212	W2	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 212	W3	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 212	W4	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 212	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 212	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Stairs adjacent to Classroom 212	Door	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 212	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 212	Stringer	Metal	Grey	Chipping	2	3.8	Positive
1	2	Stairs adjacent to Classroom 212	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairs adjacent to Classroom 212	Riser	Metal	Grey	Chipping	2	4.9	Positive
1	2	Stairs adjacent to Classroom 212	Newell Post	Metal	Grey	Chipping	2	4.7	Positive
1	2	Stairs adjacent to Classroom 212	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 200	W1	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 200	W2	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 200	W3	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 200	W4	CMU	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 200	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairs adjacent to Classroom 200	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairs adjacent to Classroom 200	Door	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 200	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Stairs adjacent to Classroom 200	Stringer	Metal	Grey	Chipping	2	2.6	Positive
1	2	Stairs adjacent to Classroom 200	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairs adjacent to Classroom 200	Riser	Metal	Grey	Chipping	2	4.2	Positive
1	2	Stairs adjacent to Classroom 200	Newell Post	Metal	Grey	Chipping	2	2.5	Positive
1	2	Stairs adjacent to Classroom 200	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Hallway from Classroom 224-236	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 224-236	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 224-236	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 224-236	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 224-236	Ceiling	Concrete	White	None	0	0	Negative
1	2	Hallway from Classroom 224-236	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Hallway from Classroom 238-246	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 238-246	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 238-246	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 238-246	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 238-246	Ceiling	Concrete	White	None	0	0	Negative
1	2	Hallway from Classroom 238-246	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classroom 214-222	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 214-222	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 214-222	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 214-222	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 214-222	Ceiling	Concrete	White	None	0	0	Negative
1	2	Hallway from Classroom 214-222	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classroom 200-212	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 200-212	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 200-212	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 200-212	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classroom 200-212	Ceiling	Concrete	White	None	0	0	Negative
1	2	Hallway from Classroom 200-212	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom across Classroom 246	W1	CMU	White	None	0	0	Negative
1	2	Girl's Restroom across Classroom 246	W2	CMU	White	None	0	0	Negative
1	2	Girl's Restroom across Classroom 246	W3	CMU	White	None	0	0	Negative
1	2	Girl's Restroom across Classroom 246	W4	CMU	White	None	0	0	Negative
1	2	Girl's Restroom across Classroom 246	Ceiling	Concrete	White	None	0	0	Negative
1	2	Girl's Restroom across Classroom 246	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom across Classroom 246	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom across Classroom 246	Radiator	Metal	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Girl's Restroom across Classroom 246	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom across Classroom 246	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 243	W1	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	W2	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	W3	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	W4	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	Ceiling	Concrete	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom at Classroom 243	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 243	Radiator	Metal	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 243	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 243	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Conference Room	W1	CMU	White	None	0	0.01	Negative
1	2	History Department Conference Room	W2	CMU	White	None	0	0.04	Negative
1	2	History Department Conference Room	W3	Concrete	White	None	0	0.05	Negative
1	2	History Department Conference Room	W4	CMU	White	None	0	0.02	Negative
1	2	History Department Conference Room	Ceiling	Concrete	White	Cracking	2	0.08	Negative
1	2	History Department Conference Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	History Department Conference Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Conference Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Office	W1	CMU	White	None	0	0	Negative
1	2	History Department Office	W2	CMU	White	None	0	0	Negative
1	2	History Department Office	W3	CMU	White	None	0	0	Negative
1	2	History Department Office	W4	CMU	White	None	0	0	Negative
1	2	History Department Office	Ceiling	Concrete	White	None	0	0	Negative
1	2	History Department Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	History Department Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Office	Radiator	Metal	White	None	0	0	Negative
1	2	History Department Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 246	W1	CMU	White	None	0	0	Negative
1	2	Classroom 246	W2	CMU	White	None	0	0	Negative
1	2	Classroom 246	W3	CMU	White	None	0	0	Negative
1	2	Classroom 246	W4	CMU	White	None	0	0	Negative
1	2	Classroom 246	Ceiling	Concrete	White	None	0	0	Negative
1	2	Classroom 246	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 246	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 246	Radiator	Metal	White	None	0	0	Negative
1	2	Classroom 246	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 246	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	History Department Office Storage	W1	CMU	White	None	0	0.03	Negative
1	2	History Department Office Storage	W2	CMU	White	None	0	0.04	Negative
1	2	History Department Office Storage	W3	Concrete	White	None	0	0.02	Negative
1	2	History Department Office Storage	W4	CMU	White	None	0	0.05	Negative
1	2	History Department Office Storage	Ceiling	Concrete	White	None	0	0.07	Negative
1	2	History Department Office Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	History Department Office Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 244	W1	CMU	White	None	0	0.02	Negative
1	2	Classroom 244	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 244	W3	Concrete	White	Cracking	5	0.03	Negative
1	2	Classroom 244	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 244	Ceiling	Concrete	White	Flaking	20	0.04	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 244	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 244	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 244	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 243	W1	CMU	White	None	0	0.04	Negative
1	2	Classroom 243	W2	CMU	White	None	0	0.05	Negative
1	2	Classroom 243	W3	Concrete	White	Cracking	10	0.02	Negative
1	2	Classroom 243	W4	CMU	White	None	0	0.01	Negative
1	2	Classroom 243	Ceiling	Concrete	White	Flaking	25	0.08	Negative
1	2	Classroom 243	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 243	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 243	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 242	W1	CMU	White	None	0	0.02	Negative
1	2	Classroom 242	W2	CMU	White	None	0	0.01	Negative
1	2	Classroom 242	W3	Concrete	White	Cracking	5	0.07	Negative
1	2	Classroom 242	W4	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 242	Ceiling	Concrete	White	Flaking	10	0.05	Negative
1	2	Classroom 242	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 242	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 242	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 241	W1	CMU	White	None	0	0.05	Negative
1	2	Classroom 241	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 241	W3	Concrete	White	None	0	0.03	Negative
1	2	Classroom 241	W4	CMU	White	None	0	0.04	Negative
1	2	Classroom 241	Ceiling	Concrete	White	Flaking	10	0.08	Negative
1	2	Classroom 241	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 241	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 241	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 240	W1	CMU	White	None	0	0.02	Negative
1	2	Classroom 240	W2	CMU	White	None	0	0.03	Negative
1	2	Classroom 240	W3	Concrete	White	Cracking	5	0.05	Negative
1	2	Classroom 240	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 240	Ceiling	Concrete	White	Flaking	20	0.02	Negative
1	2	Classroom 240	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 240	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 240	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Women's Restroom	W1	CMU	White	None	0	0	Negative
1	2	Women's Restroom	W2	CMU	White	None	0	0	Negative
1	2	Women's Restroom	W3	CMU	White	None	0	0	Negative
1	2	Women's Restroom	W4	CMU	White	None	0	0	Negative
1	2	Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	2	Women's Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Women's Restroom	Radiator	Metal	White	None	0	0	Negative
1	2	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Women's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Men's Restroom	W1	CMU	White	None	0	0	Negative
1	2	Men's Restroom	W2	CMU	White	None	0	0	Negative
1	2	Men's Restroom	W3	CMU	White	None	0	0	Negative
1	2	Men's Restroom	W4	CMU	White	None	0	0	Negative
1	2	Men's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	2	Men's Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Men's Restroom	Radiator	Metal	White	None	0	0	Negative
1	2	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Men's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Assistant Principal Office	W1	CMU	White	None	0	0.04	Negative
1	2	Assistant Principal Office	W2	CMU	White	None	0	0.01	Negative
1	2	Assistant Principal Office	W3	CMU	White	None	0	0.03	Negative
1	2	Assistant Principal Office	W4	CMU	White	None	0	0.02	Negative
1	2	Assistant Principal Office	Ceiling	Concrete	White	Cracking	25	0.01	Negative
1	2	Assistant Principal Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Assistant Principal Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Assistant Principal Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 238	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 238	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 238	W3	Concrete	White	None	0	0.02	Negative
1	2	Classroom 238	W4	CMU	White	None	0	0.07	Negative
1	2	Classroom 238	Ceiling	Concrete	White	None	0	0.04	Negative
1	2	Classroom 238	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 238	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 238	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 236	W1	CMU	White	None	0	0.02	Negative
1	2	Classroom 236	W2	CMU	White	None	0	0.04	Negative
1	2	Classroom 236	W3	Concrete	White	None	0	0.02	Negative
1	2	Classroom 236	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 236	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Classroom 236	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 236	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 236	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage adjacent to Classroom 231	W1	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 231	W2	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 231	W3	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 231	W4	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 231	Ceiling	Concrete	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 231	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 231	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 231	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage adjacent to Classroom 231	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 234	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 234	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 234	W3	Concrete	White	Chipping	5	0.04	Negative
1	2	Classroom 234	W4	CMU	White	None	0	0.05	Negative
1	2	Classroom 234	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	Classroom 234	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 234	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 234	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage adjacent to Classroom 229	W1	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 229	W2	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 229	W3	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 229	W4	CMU	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 229	Ceiling	Concrete	White	None	0	0	Negative
1	2	Book Storage adjacent to Classroom 229	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Book Storage adjacent to Classroom 229	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage adjacent to Classroom 229	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	2	Classroom 232	W1	CMU	Blue	None	0	0.05	Negative	
1	2	Classroom 232	W2	CMU	Blue	None	0	0.04	Negative	
1	2	Classroom 232	W3	Concrete	White	Chipping	10	0.03	Negative	
1	2	Classroom 232	W4	CMU	Blue	None	0	0.04	Negative	
1	2	Classroom 232	Ceiling	Concrete	White	None	0	0.01	Negative	
1	2	Classroom 232	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 232	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 232	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 231	W1	CMU	Blue	None	0	0	Negative	
1	2	Classroom 231	W2	CMU	Blue	None	0	0.05	Negative	
1	2	Classroom 231	W3	Concrete	Tan	Chipping	1	0.02	Negative	
1	2	Classroom 231	W4	CMU	Blue	None	0	0.01	Negative	
1	2	Classroom 231	Ceiling	Concrete	White	Cracking	1	0.03	Negative	
1	2	Classroom 231	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 231	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 231	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 230	W1	CMU	White	None	0	0.03	Negative	
1	2	Classroom 230	W2	CMU	White	None	0	0.02	Negative	
1	2	Classroom 230	W3	Concrete	White	None	0	0.06	Negative	
1	2	Classroom 230	W4	CMU	White	None	0	0.04	Negative	
1	2	Classroom 230	Ceiling	Concrete	White	None	0	0.03	Negative	
1	2	Classroom 230	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 230	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 230	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 229	W1	CMU	White	None	0	0.02	Negative	
1	2	Classroom 229	W2	CMU	White	None	0	0.05	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 229	W3	Concrete	White	Chipping	5	0.01	Negative
1	2	Classroom 229	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 229	Ceiling	Concrete	White	Chipping	10	0.07	Negative
1	2	Classroom 229	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 229	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 229	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 228	W1	CMU	Blue	None	0	0.04	Negative
1	2	Classroom 228	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 228	W3	Concrete	White	Chipping	10	0.02	Negative
1	2	Classroom 228	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 228	Ceiling	Concrete	White	Flaking	10	0.06	Negative
1	2	Classroom 228	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 228	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 228	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 221	W1	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	W2	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	W3	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	W4	CMU	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	Ceiling	Concrete	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom at Classroom 221	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 221	Radiator	Metal	White	None	0	0	Negative
1	2	Boy's Restroom at Classroom 221	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Boy's Restroom at Classroom 221	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 226	W1	CMU	Green	None	0	0.03	Negative
1	2	Classroom 226	W2	CMU	White	None	0	0.02	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 226	W3	Concrete	White	Chipping	5	0.01	Negative
1	2	Classroom 226	W4	CMU	White	None	0	0.05	Negative
1	2	Classroom 226	Ceiling	Concrete	White	Cracking	10	0.04	Negative
1	2	Classroom 226	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 226	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 226	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom at Classroom 221	W1	CMU	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	W2	CMU	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	W3	CMU	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	W4	CMU	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	Ceiling	Concrete	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom at Classroom 221	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom at Classroom 221	Radiator	Metal	White	None	0	0	Negative
1	2	Girl's Restroom at Classroom 221	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Girl's Restroom at Classroom 221	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 224	W1	CMU	Green	None	0	0.05	Negative
1	2	Classroom 224	W2	CMU	White	None	0	0.01	Negative
1	2	Classroom 224	W3	Concrete	White	Chipping	5	0.03	Negative
1	2	Classroom 224	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 224	Ceiling	Concrete	White	Flaking	20	0.02	Negative
1	2	Classroom 224	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 224	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Office 223	W1	CMU	White	None	0	0	Negative
1	2	Office 223	W2	CMU	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Office 223	W3	CMU	White	None	0	0	Negative
1	2	Office 223	W4	CMU	White	None	0	0	Negative
1	2	Office 223	Ceiling	Concrete	White	None	0	0	Negative
1	2	Office 223	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 223	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Office 223	Radiator	Metal	White	None	0	0	Negative
1	2	Office 223	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Office 223	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 222	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 222	W2	CMU	White	None	0	0.02	Negative
1	2	Classroom 222	W3	Concrete	White	None	0	0.01	Negative
1	2	Classroom 222	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 222	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Classroom 222	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 222	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 222	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 221	W1	CMU	White	None	0	0.01	Negative
1	2	Classroom 221	W2	CMU	White	None	0	0.01	Negative
1	2	Classroom 221	W3	Concrete	White	Flaking	1	0.04	Negative
1	2	Classroom 221	W4	CMU	White	None	0	0.06	Negative
1	2	Classroom 221	Ceiling	Concrete	White	Flaking	10	0.03	Negative
1	2	Classroom 221	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 221	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 221	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 220/218	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 220/218	W2	CMU	White	None	0	0.02	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 220/218	W3	Concrete	White	None	0	0.03	Negative
1	2	Classroom 220/218	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 220/218	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	Classroom 220/218	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 220/218	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 220/218	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Teacher's Lounge/Copy Room	W1	CMU	White	None	0	0	Negative
1	2	Teacher's Lounge/Copy Room	W2	CMU	White	None	0	0.02	Negative
1	2	Teacher's Lounge/Copy Room	W3	CMU	White	None	0	0.03	Negative
1	2	Teacher's Lounge/Copy Room	W4	Concrete	White	None	0	0.04	Negative
1	2	Teacher's Lounge/Copy Room	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Teacher's Lounge/Copy Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Lounge/Copy Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Teacher's Lounge/Copy Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage	W1	CMU	White	None	0	0	Negative
1	2	Book Storage	W2	CMU	White	None	0	0	Negative
1	2	Book Storage	W3	CMU	White	None	0	0	Negative
1	2	Book Storage	W4	CMU	White	None	0	0	Negative
1	2	Book Storage	Ceiling	Concrete	White	None	0	0	Negative
1	2	Book Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Book Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Book Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 216	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 216	W2	CMU	White	None	0	0.04	Negative
1	2	Classroom 216	W3	Concrete	White	Chipping	2	0.02	Negative
1	2	Classroom 216	W4	CMU	White	None	0	0.02	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	2	Classroom 216	Ceiling	Concrete	White	None	0	0.01	Negative	
1	2	Classroom 216	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 216	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 216	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 215	W1	CMU	White	None	0	0	Negative	
1	2	Classroom 215	W2	CMU	White	None	0	0.04	Negative	
1	2	Classroom 215	W3	Concrete	White	Flaking	3	0.07	Negative	
1	2	Classroom 215	W4	CMU	White	None	0	0.03	Negative	
1	2	Classroom 215	Ceiling	Concrete	White	None	0	0.02	Negative	
1	2	Classroom 215	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 215	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 215	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 214	W1	CMU	White	None	0	0.02	Negative	
1	2	Classroom 214	W2	CMU	White	Cracking	3	0.02	Negative	
1	2	Classroom 214	W3	Concrete	White	Cracking	2	0.03	Negative	
1	2	Classroom 214	W4	CMU	White	None	0	0.05	Negative	
1	2	Classroom 214	Ceiling	Concrete	White	Flaking	2	0.04	Negative	
1	2	Classroom 214	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 214	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	2	Classroom 214	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	2	Men's Restroom accross from Classroom 214	W1	CMU	White	None	0	0	Negative	
1	2	Men's Restroom accross from Classroom 214	W2	CMU	White	None	0	0	Negative	
1	2	Men's Restroom accross from Classroom 214	W3	CMU	White	None	0	0	Negative	
1	2	Men's Restroom accross from Classroom 214	W4	CMU	White	None	0	0	Negative	
1	2	Men's Restroom accross from Classroom 214	Ceiling	Concrete	White	None	0	0	Negative	
1	2	Men's Restroom accross from Classroom 214	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Men's Restroom accross from Classroom 214	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Men's Restroom accross from Classroom 214	Radiator	Metal	White	None	0	0	Negative
1	2	Men's Restroom accross from Classroom 214	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Men's Restroom accross from Classroom 214	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 212	W1	CMU	White	None	0	0.08	Negative
1	2	Classroom 212	W2	CMU	White	None	0	0.03	Negative
1	2	Classroom 212	W3	Concrete	White	None	0	0.05	Negative
1	2	Classroom 212	W4	CMU	White	None	0	0.14	Negative
1	2	Classroom 212	Ceiling	Concrete	White	Cracking	2	0.06	Negative
1	2	Classroom 212	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 212	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 212	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Women's Restroom accross from Classroom 214	W1	CMU	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	W2	CMU	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	W3	CMU	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	W4	CMU	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	Ceiling	Concrete	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom accross from Classroom 214	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Women's Restroom accross from Classroom 214	Radiator	Metal	White	None	0	0	Negative
1	2	Women's Restroom accross from Classroom 214	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 210	W1	CMU	White	Cracking	1	0.04	Negative
1	2	Classroom 210	W2	CMU	White	None	0	0.01	Negative
1	2	Classroom 210	W3	Concrete	White	Chipping	3	0.02	Negative
1	2	Classroom 210	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 210	Ceiling	Concrete	White	Cracking	4	0.04	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 210	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 210	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 210	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Room S2-1 book closet	W1	CMU	White	None	0	0	Negative
1	2	Room S2-1 book closet	W2	CMU	White	None	0	0	Negative
1	2	Room S2-1 book closet	W3	CMU	White	None	0	0	Negative
1	2	Room S2-1 book closet	W4	CMU	White	None	0	0	Negative
1	2	Room S2-1 book closet	Ceiling	Concrete	White	None	0	0	Negative
1	2	Room S2-1 book closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Room S2-1 book closet	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Room S2-1 book closet	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 208	W1	CMU	White	None	0	0.04	Negative
1	2	Classroom 208	W2	CMU	White	None	0	0.01	Negative
1	2	Classroom 208	W3	Concrete	White	None	0	0.1	Negative
1	2	Classroom 208	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 208	Ceiling	Concrete	White	None	0	0.03	Negative
1	2	Classroom 208	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 208	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 208	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 207	W1	CMU	White	None	0	0.04	Negative
1	2	Classroom 207	W2	CMU	White	None	0	0.03	Negative
1	2	Classroom 207	W3	Concrete	White	None	0	0.09	Negative
1	2	Classroom 207	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 207	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Classroom 207	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 207	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 206	W1	CMU	White	None	0	0.02	Negative
1	2	Classroom 206	W2	CMU	White	None	0	0.04	Negative
1	2	Classroom 206	W3	Concrete	White	None	0	0.02	Negative
1	2	Classroom 206	W4	CMU	White	None	0	0.03	Negative
1	2	Classroom 206	Ceiling	Concrete	White	None	0	0.05	Negative
1	2	Classroom 206	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 206	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 205	W1	CMU	White	None	0	0.07	Negative
1	2	Classroom 205	W2	CMU	White	None	0	0.03	Negative
1	2	Classroom 205	W3	Concrete	White	None	0	0.02	Negative
1	2	Classroom 205	W4	CMU	White	Alligatoring	20	0.05	Negative
1	2	Classroom 205	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	Classroom 205	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 205	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 204	W1	CMU	White	None	0	0.04	Negative
1	2	Classroom 204	W2	CMU	White	None	0	0.05	Negative
1	2	Classroom 204	W3	Concrete	White	None	0	0.03	Negative
1	2	Classroom 204	W4	CMU	White	None	0	0.04	Negative
1	2	Classroom 204	Ceiling	Concrete	White	Chipping	1	0.07	Negative
1	2	Classroom 204	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 204	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 204	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 203	W1	CMU	White	None	0	0.04	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 203	W2	CMU	White	Chipping	2	0.02	Negative
1	2	Classroom 203	W3	Concrete	White	Cracking	1	0.02	Negative
1	2	Classroom 203	W4	CMU	White	None	0	0.05	Negative
1	2	Classroom 203	Ceiling	Concrete	White	None	0	0.01	Negative
1	2	Classroom 203	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 203	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 203	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 202	W1	CMU	White	None	0	0.03	Negative
1	2	Classroom 202	W2	CMU	White	None	0	0.03	Negative
1	2	Classroom 202	W3	Concrete	White	None	0	0.09	Negative
1	2	Classroom 202	W4	CMU	White	None	0	0.02	Negative
1	2	Classroom 202	Ceiling	Concrete	White	None	0	0.04	Negative
1	2	Classroom 202	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 202	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 202	Radiator	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 200	W1	CMU	White	None	0	0.01	Negative
1	2	Classroom 200	W2	CMU	White	None	0	0.07	Negative
1	2	Classroom 200	W3	Concrete	White	None	0	0.03	Negative
1	2	Classroom 200	W4	CMU	White	None	0	0.04	Negative
1	2	Classroom 200	Ceiling	Concrete	White	None	0	0.02	Negative
1	2	Classroom 200	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	2	Classroom 200	Radiator	Metal	Blue	Chipping	1	0	Negative
2	1	Stairs adjacent to Bridge	W1	CMU	White	None	0	0	Negative
2	1	Stairs adjacent to Bridge	W2	CMU	White	None	0	0	Negative
2	1	Stairs adjacent to Bridge	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Stairs adjacent to Bridge	W4	CMU	White	None	0	0	Negative
2	1	Stairs adjacent to Bridge	Ceiling	Concrete	White	None	0	0	Negative
2	1	Stairs adjacent to Bridge	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Stairs adjacent to Bridge	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Stairs adjacent to Bridge	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Stairs adjacent to Bridge	Stringer	Metal	Grey	Chipping	2	5.3	Positive
2	1	Stairs adjacent to Bridge	Handrail	Metal	Grey	Chipping	2	0	Negative
2	1	Stairs adjacent to Bridge	Riser	Metal	Grey	Chipping	2	3.3	Positive
2	1	Stairs adjacent to Bridge	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Hallway from Classroom 501-514	W1	CMU	White	None	0	0	Negative
2	1	Hallway from Classroom 501-514	W2	CMU	White	None	0	0	Negative
2	1	Hallway from Classroom 501-514	W3	CMU	White	None	0	0	Negative
2	1	Hallway from Classroom 501-514	W4	CMU	White	None	0	0	Negative
2	1	Hallway from Classroom 501-514	Ceiling	Concrete	White	None	0	0	Negative
2	1	Hallway from Classroom 501-514	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 510	W1	CMU	White	None	0	0	Negative
2	1	Classroom 510	W2	CMU	White	None	0	0	Negative
2	1	Classroom 510	W3	CMU	White	Efflorescence	5	0	Negative
2	1	Classroom 510	W4	CMU	White	Efflorescence	50	0	Negative
2	1	Classroom 510	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 510	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 510	Door Frame 1	Metal	Blue	Chipping	1	0.01	Negative
2	1	Classroom 510	Door Frame 2	Metal	Blue	Chipping	2	0.02	Negative
2	1	Service Closet Next to Women's Restroom	W1	CMU	White	None	0	0	Negative
2	1	Service Closet Next to Women's Restroom	W2	CMU	White	None	0	0	Negative
2	1	Service Closet Next to Women's Restroom	W3	CMU	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Service Closet Next to Women's Restroom	W4	CMU	White	None	0	0	Negative
2	1	Service Closet Next to Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	1	Service Closet Next to Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Service Closet Next to Women's Restroom	Door Frame	Metal	Blue	Chipping	2	0.15	Negative
2	1	Classroom 509	W1	CMU	White	None	0	0	Negative
2	1	Classroom 509	W2	CMU	White	None	0	0	Negative
2	1	Classroom 509	W3	CMU	White	None	0	0	Negative
2	1	Classroom 509	W4	CMU	White	None	0	0	Negative
2	1	Classroom 509	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 509	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 508	W1	CMU	White	None	0	0	Negative
2	1	Classroom 508	W2	CMU	White	None	0	0	Negative
2	1	Classroom 508	W3	CMU	White	None	0	0	Negative
2	1	Classroom 508	W4	CMU	White	None	0	0	Negative
2	1	Classroom 508	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 508	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Dean's Office	W1	CMU	White	None	0	0	Negative
2	1	Dean's Office	W2	CMU	White	None	0	0	Negative
2	1	Dean's Office	W3	CMU	White	None	0	0	Negative
2	1	Dean's Office	W4	CMU	White	None	0	0	Negative
2	1	Dean's Office	Ceiling	Concrete	White	None	0	0	Negative
2	1	Dean's Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Dean's Office	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	1	Dean's Office	Duct	Metal	White	None	0	0.04	Negative
2	1	Classroom 506	W1	CMU	White	None	0	0	Negative
2	1	Classroom 506	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Classroom 506	W3	CMU	White	None	0	0	Negative
2	1	Classroom 506	W4	CMU	White	None	0	0	Negative
2	1	Classroom 506	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 506	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 506	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
2	1	Girl's Restroom	W1	CMU	White	None	0	0	Negative
2	1	Girl's Restroom	W2	CMU	White	None	0	0	Negative
2	1	Girl's Restroom	W3	CMU	White	Efflorescence	5	0	Negative
2	1	Girl's Restroom	W4	CMU	White	None	0	0	Negative
2	1	Girl's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	1	Girl's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Restroom	Door Frame	Metal	Blue	Chipping	3	0.07	Negative
2	1	Girl's Restroom	W1	CMU	Grey	None	0	0	Negative
2	1	Girl's Restroom	W2	CMU	Grey	Efflorescence	5	0	Negative
2	1	Girl's Restroom	W3	CMU	Grey	None	0	0	Negative
2	1	Girl's Restroom	W4	CMU	Grey	None	0	0	Negative
2	1	Girl's Restroom	Duct	Metal	White	None	0	0	Negative
2	1	Classroom 504	W1	CMU	White	None	0	0.02	Negative
2	1	Classroom 504	W2	CMU	White	None	0	0.01	Negative
2	1	Classroom 504	W3	CMU	White	None	0	0.05	Negative
2	1	Classroom 504	W4	CMU	White	None	0	0.01	Negative
2	1	Classroom 504	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 504	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 504	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
2	1	Boy's Restroom	W1	CMU	White	None	0	0	Negative
2	1	Boy's Restroom	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Boy's Restroom	W3	CMU	White	Efflorescence	5	0	Negative
2	1	Boy's Restroom	W4	CMU	White	None	0	0	Negative
2	1	Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	1	Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Restroom	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
2	1	Boy's Restroom	Duct	Metal	White	None	0	0.03	Negative
2	1	Office adjacent to Classroom 502	W1	CMU	White	None	0	0	Negative
2	1	Office adjacent to Classroom 502	W2	CMU	White	None	0	0	Negative
2	1	Office adjacent to Classroom 502	W3	CMU	White	None	0	0	Negative
2	1	Office adjacent to Classroom 502	W4	CMU	Blue	None	0	0	Negative
2	1	Office adjacent to Classroom 502	Ceiling	Concrete	White	None	0	0	Negative
2	1	Office adjacent to Classroom 502	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Office adjacent to Classroom 502	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
2	1	Office adjacent to Classroom 502	Radiator	Metal	White	None	0	0	Negative
2	1	Classroom 503	W1	CMU	White	None	0	0.03	Negative
2	1	Classroom 503	W2	CMU	White	None	0	0.01	Negative
2	1	Classroom 503	W3	CMU	White	Efflorescence	10	0.09	Negative
2	1	Classroom 503	W4	CMU	Blue	None	0	0.03	Negative
2	1	Classroom 503	Ceiling	Concrete	White	Efflorescence	10	0	Negative
2	1	Classroom 503	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 503	Door Frame	Metal	Blue	Chipping	2	0.02	Negative
2	1	Classroom 502	W1	CMU	White	None	0	0	Negative
2	1	Classroom 502	W2	CMU	White	Efflorescence	20	0	Negative
2	1	Classroom 502	W3	CMU	White	Efflorescence	10	0	Negative
2	1	Classroom 502	W4	CMU	White	None	0	0	Negative
2	1	Classroom 502	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Classroom 502	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 502	Door Frame	Metal	Blue	Chipping	2	0.06	Negative
2	1	Classroom 501	W1	CMU	White	None	0	0.04	Negative
2	1	Classroom 501	W2	CMU	White	None	0	0	Negative
2	1	Classroom 501	W3	CMU	White	None	0	0.02	Negative
2	1	Classroom 501	W4	CMU	White	None	0	0.03	Negative
2	1	Classroom 501	Ceiling	Concrete	White	None	0	0	Negative
2	1	Classroom 501	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
2	1	Classroom 501	Door Frame	Metal	Blue	Chipping	2	0.02	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	W1	CMU	White	None	0	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	W2	CMU	White	None	0	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	W3	CMU	White	None	0	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	W4	CMU	White	None	0	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	Ceiling	Concrete	White	None	0	0	Negative
1	1	Mini Hallway Connecting Gym 3 and 4	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Section D 1st Floor Hallway	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Section D 1st Floor Hallway	W1	CMU	White	None	0	0	Negative
1	1	Section D 1st Floor Hallway	W2	CMU	White	None	0	0	Negative
1	1	Section D 1st Floor Hallway	W3	CMU	White	None	0	0	Negative
1	1	Section D 1st Floor Hallway	W4	CMU	White	None	0	0	Negative
1	1	Section D 1st Floor Hallway	Ceiling	Concrete	White	None	0	0	Negative
1	1	Section D 1st Floor Hallway	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Gym 4 Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Gym 4 Storage	W1	CMU	White	None	0	0	Negative
1	1	Gym 4 Storage	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Gym 4 Storage	W3	CMU	White	None	0	0	Negative
1	1	Gym 4 Storage	W4	CMU	White	None	0	0	Negative
1	1	Gym 4 Storage	Ceiling	Concrete	White	None	0	0	Negative
1	1	Gym 4 Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room F4-3	W1	CMU	White	None	0	0	Negative
1	1	Room F4-3	W2	CMU	White	None	0	0	Negative
1	1	Room F4-3	W3	CMU	White	None	0	0	Negative
1	1	Room F4-3	W4	CMU	White	None	0	0	Negative
1	1	Room F4-3	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room F4-3	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Gym 4	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Gym 4	W1	CMU	White	None	0	0	Negative
1	1	Gym 4	W2	Wood	White	None	0	0	Negative
1	1	Gym 4	W3	CMU	White	None	0	0	Negative
1	1	Gym 4	W4	CMU	White	None	0	0	Negative
1	1	Gym 4	W1	CMU	Blue	None	0	0	Negative
1	1	Gym 4	W2	Wood	Blue	None	0	0	Negative
1	1	Gym 4	W3	CMU	Blue	None	0	0	Negative
1	1	Gym 4	W4	CMU	Blue	None	0	0	Negative
1	1	Gym 4	Ceiling	Concrete	White	None	0	0	Negative
1	1	Gym 4	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Gym 3 Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Gym 3 Storage	W1	CMU	White	None	0	0	Negative
1	1	Gym 3 Storage	W2	CMU	White	None	0	0	Negative
1	1	Gym 3 Storage	W3	CMU	White	None	0	0	Negative
1	1	Gym 3 Storage	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Gym 3 Storage	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Gym 3 Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gym Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Gym Storage	W1	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W2	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W3	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W4	CMU	White	None	0	0	Negative	
1	1	Gym Storage	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Gym Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gym 2 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Gym 2 Office	W1	CMU	White	None	0	0	Negative	
1	1	Gym 2 Office	W2	CMU	White	None	0	0	Negative	
1	1	Gym 2 Office	W3	CMU	White	None	0	0	Negative	
1	1	Gym 2 Office	W4	CMU	White	None	0	0	Negative	
1	1	Gym 2 Office	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Gym 2 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Gym Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Gym Storage	W1	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W2	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W3	CMU	White	None	0	0	Negative	
1	1	Gym Storage	W4	CMU	White	None	0	0	Negative	
1	1	Gym Storage	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Gym Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Basketball Gym(Gym 1 & 2 Combined)	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W1	CMU	White	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W2	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W3	CMU	White	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W4	Wood	White	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W1	CMU	Blue	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W2	CMU	Blue	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W3	CMU	Blue	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	W4	Wood	Blue	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Basketball Gym(Gym 1 & 2 Combined)	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Closet in Weight Room 158	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Closet in Weight Room 158	W1	CMU	White	None	0	0	Negative	
1	1	Closet in Weight Room 158	W2	CMU	White	None	0	0	Negative	
1	1	Closet in Weight Room 158	W3	CMU	White	None	0	0	Negative	
1	1	Closet in Weight Room 158	W4	CMU	White	None	0	0	Negative	
1	1	Closet in Weight Room 158	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Closet in Weight Room 158	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Weight Room 158	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Weight Room 158	W1	CMU	White	None	0	0	Negative	
1	1	Weight Room 158	W2	CMU	White	None	0	0	Negative	
1	1	Weight Room 158	W3	CMU	White	None	0	0	Negative	
1	1	Weight Room 158	W4	CMU	White	None	0	0	Negative	
1	1	Weight Room 158	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Weight Room 158	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room 144B	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Room 144B	W1	CMU	White	None	0	0	Negative	
1	1	Room 144B	W2	CMU	White	None	0	0	Negative	
1	1	Room 144B	W3	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Room 144B	W4	CMU	White	None	0	0	Negative
1	1	Room 144B	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room 144B	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 144A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Room 144A	W1	CMU	White	None	0	0	Negative
1	1	Room 144A	W2	CMU	White	None	0	0	Negative
1	1	Room 144A	W3	CMU	White	None	0	0	Negative
1	1	Room 144A	W4	CMU	White	None	0	0	Negative
1	1	Room 144A	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room 144A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom in Teacher Office 142A	W1	CMU	White	None	0	0	Negative
1	1	Restroom in Teacher Office 142A	W2	CMU	White	None	0	0	Negative
1	1	Restroom in Teacher Office 142A	W3	CMU	White	None	0	0	Negative
1	1	Restroom in Teacher Office 142A	W4	CMU	White	None	0	0	Negative
1	1	Restroom in Teacher Office 142A	Ceiling	Concrete	White	None	0	0	Negative
1	1	Restroom in Teacher Office 142A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Next to Teacher Office 142A	W1	CMU	White	None	0	0	Negative
1	1	Storage Next to Teacher Office 142A	W2	CMU	White	None	0	0	Negative
1	1	Storage Next to Teacher Office 142A	W3	CMU	White	None	0	0	Negative
1	1	Storage Next to Teacher Office 142A	W4	CMU	White	None	0	0	Negative
1	1	Storage Next to Teacher Office 142A	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage Next to Teacher Office 142A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 148	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Room 148	W1	CMU	White	None	0	0	Negative
1	1	Room 148	W2	CMU	White	None	0	0	Negative
1	1	Room 148	W3	CMU	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Room 148	W4	CMU	White	None	0	0	Negative
1	1	Room 148	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room 148	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 146	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 146	W1	CMU	White	None	0	0	Negative
1	1	Classroom 146	W2	CMU	White	None	0	0	Negative
1	1	Classroom 146	W3	CMU	White	None	0	0	Negative
1	1	Classroom 146	W4	CMU	White	None	0	0	Negative
1	1	Classroom 146	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 146	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Training Room 140	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Training Room 140	W1	CMU	White	None	0	0	Negative
1	1	Training Room 140	W2	CMU	White	None	0	0	Negative
1	1	Training Room 140	W3	CMU	White	None	0	0	Negative
1	1	Training Room 140	W4	CMU	White	None	0	0	Negative
1	1	Training Room 140	Ceiling	Concrete	White	None	0	0	Negative
1	1	Training Room 140	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room 144	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Room 144	W1	CMU	White	None	0	0	Negative
1	1	Room 144	W2	CMU	White	None	0	0	Negative
1	1	Room 144	W3	CMU	White	None	0	0	Negative
1	1	Room 144	W4	CMU	White	None	0	0	Negative
1	1	Room 144	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room 144	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Dance 142C	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Dance 142C	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Dance 142C	W2	CMU	White	None	0	0	Negative
1	1	Dance 142C	W3	CMU	White	None	0	0	Negative
1	1	Dance 142C	W4	CMU	White	None	0	0	Negative
1	1	Dance 142C	Ceiling	Concrete	White	None	0	0	Negative
1	1	Dance 142C	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher Office 142A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Teacher Office 142A	W1	CMU	White	None	0	0	Negative
1	1	Teacher Office 142A	W2	CMU	White	None	0	0	Negative
1	1	Teacher Office 142A	W3	CMU	White	None	0	0	Negative
1	1	Teacher Office 142A	W4	CMU	White	None	0	0	Negative
1	1	Teacher Office 142A	Ceiling	Concrete	White	None	0	0	Negative
1	1	Teacher Office 142A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Girls Locker Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Girls Locker Room	W1	CMU	White	None	0	0	Negative
1	1	Girls Locker Room	W2	CMU	White	None	0	0	Negative
1	1	Girls Locker Room	W3	CMU	White	None	0	0	Negative
1	1	Girls Locker Room	W4	CMU	White	None	0	0	Negative
1	1	Girls Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girls Locker Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Weight Room 138	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Weight Room 138	W1	CMU	White	None	0	0	Negative
1	1	Weight Room 138	W2	CMU	White	None	0	0	Negative
1	1	Weight Room 138	W3	CMU	White	None	0	0	Negative
1	1	Weight Room 138	W4	CMU	White	None	0	0	Negative
1	1	Weight Room 138	Ceiling	Concrete	White	None	0	0	Negative
1	1	Weight Room 138	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 134 & 136 Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 134 & 136 Storage	W1	CMU	White	None	0	0	Negative
1	1	Classroom 134 & 136 Storage	W2	CMU	White	None	0	0	Negative
1	1	Classroom 134 & 136 Storage	W3	CMU	White	None	0	0	Negative
1	1	Classroom 134 & 136 Storage	W4	CMU	White	None	0	0	Negative
1	1	Classroom 134 & 136 Storage	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 134 & 136 Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 136	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 136	W1	CMU	White	None	0	0	Negative
1	1	Classroom 136	W2	CMU	White	None	0	0	Negative
1	1	Classroom 136	W3	CMU	White	None	0	0	Negative
1	1	Classroom 136	W4	CMU	White	None	0	0	Negative
1	1	Classroom 136	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 136	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 134 Electrical Shop Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 134 Electrical Shop Office	W1	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop Office	W2	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop Office	W3	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop Office	W4	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 134 Electrical Shop	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 134 Electrical Shop	W1	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop	W2	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop	W3	CMU	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 134 Electrical Shop	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 134 Electrical Shop	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Large Storage in Classroom 132	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Large Storage in Classroom 132	W1	CMU	White	None	0	0	Negative
1	1	Large Storage in Classroom 132	W2	CMU	White	None	0	0	Negative
1	1	Large Storage in Classroom 132	W3	CMU	White	None	0	0	Negative
1	1	Large Storage in Classroom 132	W4	CMU	White	None	0	0	Negative
1	1	Large Storage in Classroom 132	Ceiling	Concrete	White	None	0	0	Negative
1	1	Large Storage in Classroom 132	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Weight Room 138 Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Weight Room 138 Storage	W1	CMU	White	None	0	0	Negative
1	1	Weight Room 138 Storage	W2	CMU	White	None	0	0	Negative
1	1	Weight Room 138 Storage	W3	CMU	White	None	0	0	Negative
1	1	Weight Room 138 Storage	W4	CMU	White	None	0	0	Negative
1	1	Weight Room 138 Storage	Ceiling	Concrete	White	None	0	0	Negative
1	1	Weight Room 138 Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage next to Classroom 132 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Storage next to Classroom 132 Office	W1	CMU	White	None	0	0	Negative
1	1	Storage next to Classroom 132 Office	W2	CMU	White	None	0	0	Negative
1	1	Storage next to Classroom 132 Office	W3	CMU	White	None	0	0	Negative
1	1	Storage next to Classroom 132 Office	W4	CMU	White	None	0	0	Negative
1	1	Storage next to Classroom 132 Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage next to Classroom 132 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 132	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 132	W1	CMU	White	None	0	0	Negative
1	1	Classroom 132	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 132	W3	CMU	White	None	0	0	Negative
1	1	Classroom 132	W4	CMU	White	None	0	0	Negative
1	1	Classroom 132	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 132	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 132 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 132 Office	W1	CMU	White	None	0	0	Negative
1	1	Classroom 132 Office	W2	CMU	White	None	0	0	Negative
1	1	Classroom 132 Office	W3	CMU	White	None	0	0	Negative
1	1	Classroom 132 Office	W4	CMU	White	None	0	0	Negative
1	1	Classroom 132 Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 132 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 151-154	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 151-154	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 151-154	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 151-154	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 151-154	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Classroom 151-154	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 128-131	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 128-131	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 128-131	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 128-131	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 128-131	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Classroom 128-131	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Business 156 Closet	W1	CMU	White	None	0	0	Negative
1	1	Business 156 Closet	W2	CMU	White	None	0	0	Negative
1	1	Business 156 Closet	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Business 156 Closet	W4	CMU	White	None	0	0	Negative
1	1	Business 156 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	Business 156 Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Business 156	W1	CMU	White	None	0	0.26	Negative
1	1	Business 156	W2	CMU	White	None	0	0.04	Negative
1	1	Business 156	W3	Concrete	White	Cracking	5	0.02	Negative
1	1	Business 156	W4	CMU	White	None	0	0.05	Negative
1	1	Business 156	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	Business 156	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Business 156	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
1	1	Business 156	Radiator	Metal	White	None	0	0.05	Negative
1	1	Business 156	Duct	Metal	White	None	0	0.05	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	W1	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	W2	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	W3	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	W4	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts) Custodial Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Kitchen (Culinary Arts)	W1	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts)	W2	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts)	W3	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts)	W4	CMU	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts)	Ceiling	Concrete	White	None	0	0	Negative
1	1	Kitchen (Culinary Arts)	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room F3-1	W1	CMU	Yellow	None	0	0	Negative
1	1	Room F3-1	W2	CMU	Yellow	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Room F3-1	W3	CMU	Yellow	None	0	0	Negative	
1	1	Room F3-1	W4	CMU	Yellow	None	0	0	Negative	
1	1	Room F3-1	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Room F3-1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Room F3-1	Door Frame	Metal	Blue	None	0	0.04	Negative	
1	1	Classroom 154 (Culinary Arts)	W1	CMU	Blue	Cracking	1	0.02	Negative	
1	1	Classroom 154 (Culinary Arts)	W2	CMU	Blue	None	0	0.01	Negative	
1	1	Classroom 154 (Culinary Arts)	W3	Concrete	Blue	Flaking	10	0.04	Negative	
1	1	Classroom 154 (Culinary Arts)	W4	CMU	Blue	None	0	0.03	Negative	
1	1	Classroom 154 (Culinary Arts)	Ceiling	Concrete	White	Alligating	30	0.04	Negative	
1	1	Classroom 154 (Culinary Arts)	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 154 (Culinary Arts)	Door Frame	Metal	Blue	Chipping	2	0.04	Negative	
1	1	Classroom 154 (Culinary Arts)	Radiator	Metal	White	None	0	0.05	Negative	
1	1	CAFE Storage	W1	CMU	White	None	0	0	Negative	
1	1	CAFE Storage	W2	CMU	White	None	0	0	Negative	
1	1	CAFE Storage	W3	CMU	White	None	0	0	Negative	
1	1	CAFE Storage	W4	CMU	White	None	0	0	Negative	
1	1	CAFE Storage	Ceiling	Concrete	White	None	0	0	Negative	
1	1	CAFE Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	CAFE Small Closet	W1	CMU	White	None	0	0	Negative	
1	1	CAFE Small Closet	W2	CMU	White	None	0	0	Negative	
1	1	CAFE Small Closet	W3	CMU	White	None	0	0	Negative	
1	1	CAFE Small Closet	W4	CMU	White	None	0	0	Negative	
1	1	CAFE Small Closet	Ceiling	Concrete	White	None	0	0	Negative	
1	1	CAFE Small Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	CAFE Small Closet	Door Frame	Metal	Blue	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	CAFE	W1	CMU	White	None	0	0	Negative
1	1	CAFE	W2	CMU	White	None	0	0	Negative
1	1	CAFE	W3	CMU	White	None	0	0	Negative
1	1	CAFE	W4	CMU	White	None	0	0	Negative
1	1	CAFE	Ceiling	Concrete	White	None	0	0	Negative
1	1	CAFE	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	CAFE	Door Frame	Metal	Blue	None	0	0	Negative
1	1	CAFE	Radiator	Metal	Blue	None	0	0	Negative
1	1	Classroom 152 (Culinary)	W1	CMU	White	None	0	0.05	Negative
1	1	Classroom 152 (Culinary)	W2	CMU	White	None	0	0.03	Negative
1	1	Classroom 152 (Culinary)	W3	Concrete	White	Flaking	7	0.04	Negative
1	1	Classroom 152 (Culinary)	W4	CMU	White	None	0	0.02	Negative
1	1	Classroom 152 (Culinary)	Ceiling	Concrete	White	Flaking	50	0.02	Negative
1	1	Classroom 152 (Culinary)	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 152 (Culinary)	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
1	1	Classroom 151	W1	CMU	White	None	0	0.04	Negative
1	1	Classroom 151	W2	CMU	White	None	0	0.01	Negative
1	1	Classroom 151	W3	Concrete	White	Flaking	25	0.02	Negative
1	1	Classroom 151	W4	CMU	White	None	0	0.02	Negative
1	1	Classroom 151	Ceiling	Concrete	White	Flaking	100	0.04	Negative
1	1	Classroom 151	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 151	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
1	1	Classroom 151	Radiator	Metal	White	None	0	0.05	Negative
1	1	Boy's Restroom at Classroom 161	W1	CMU	White	None	0	0	Negative
1	1	Boy's Restroom at Classroom 161	W2	CMU	White	None	0	0	Negative
1	1	Boy's Restroom at Classroom 161	W3	CMU	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Restroom at Classroom 161	W4	CMU	White	None	0	0	Negative
1	1	Boy's Restroom at Classroom 161	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Restroom at Classroom 161	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom at Classroom 106	W1	CMU	White	None	0	0	Negative
1	1	Girl's Restroom at Classroom 106	W2	CMU	White	None	0	0	Negative
1	1	Girl's Restroom at Classroom 106	W3	CMU	White	None	0	0	Negative
1	1	Girl's Restroom at Classroom 106	W4	CMU	White	None	0	0	Negative
1	1	Girl's Restroom at Classroom 106	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girl's Restroom at Classroom 106	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom Across Classroom 131	W1	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Across Classroom 131	W2	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Across Classroom 131	W3	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Across Classroom 131	W4	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Across Classroom 131	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girl's Restroom Across Classroom 131	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom across from Classroom 131	W1	CMU	White	None	0	0	Negative
1	1	Boy's Restroom across from Classroom 131	W2	CMU	White	None	0	0	Negative
1	1	Boy's Restroom across from Classroom 131	W3	CMU	White	None	0	0	Negative
1	1	Boy's Restroom across from Classroom 131	W4	CMU	White	None	0	0	Negative
1	1	Boy's Restroom across from Classroom 131	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Restroom across from Classroom 131	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom	W1	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W4	CMU	White	None	0	0	Negative
1	1	Men's Restroom	Ceiling	Concrete	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Men's Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom	W1	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W4	CMU	White	None	0	0	Negative
1	1	Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Women's Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Service Closet Next to Women's Restroom	W1	CMU	White	None	0	0	Negative
1	1	Service Closet Next to Women's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Service Closet Next to Women's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Service Closet Next to Women's Restroom	W4	CMU	White	None	0	0	Negative
1	1	Service Closet Next to Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Service Closet Next to Women's Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Art Classroom 129 Closet	W1	CMU	White	None	0	0	Negative
1	1	Art Classroom 129 Closet	W2	CMU	White	None	0	0	Negative
1	1	Art Classroom 129 Closet	W3	CMU	White	None	0	0	Negative
1	1	Art Classroom 129 Closet	W4	CMU	White	None	0	0	Negative
1	1	Art Classroom 129 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	Art Classroom 129 Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 131 Closet	W1	CMU	White	None	0	0	Negative
1	1	Classroom 131 Closet	W2	CMU	White	None	0	0	Negative
1	1	Classroom 131 Closet	W3	CMU	White	None	0	0	Negative
1	1	Classroom 131 Closet	W4	CMU	White	None	0	0	Negative
1	1	Classroom 131 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 131 Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 131	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 131	W2	CMU	White	None	0	0	Negative
1	1	Classroom 131	W3	CMU	White	None	0	0	Negative
1	1	Classroom 131	W4	CMU	White	None	0	0	Negative
1	1	Classroom 131	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 131	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 130	W1	CMU	White	None	0	0	Negative
1	1	Classroom 130	W2	CMU	White	None	0	0	Negative
1	1	Classroom 130	W3	CMU	White	None	0	0	Negative
1	1	Classroom 130	W4	CMU	White	None	0	0	Negative
1	1	Classroom 130	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 130	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 128	W1	CMU	White	None	0	0	Negative
1	1	Classroom 128	W2	CMU	White	None	0	0	Negative
1	1	Classroom 128	W3	CMU	White	None	0	0	Negative
1	1	Classroom 128	W4	CMU	White	None	0	0	Negative
1	1	Classroom 128	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 128	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Art Classroom 129	W1	CMU	White	None	0	0	Negative
1	1	Art Classroom 129	W2	CMU	White	None	0	0	Negative
1	1	Art Classroom 129	W3	CMU	White	None	0	0	Negative
1	1	Art Classroom 129	W4	CMU	White	None	0	0	Negative
1	1	Art Classroom 129	Ceiling	Concrete	White	None	0	0	Negative
1	1	Art Classroom 129	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 127	W1	CMU	White	None	0	0	Negative
1	1	Classroom 127	W2	CMU	White	None	0	0	Negative
1	1	Classroom 127	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 127	W4	CMU	White	None	0	0	Negative
1	1	Classroom 127	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 127	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairs adjacent to Yearbook Room	W1	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Yearbook Room	W2	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Yearbook Room	W3	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Yearbook Room	W4	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Yearbook Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Stairs adjacent to Yearbook Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairs adjacent to Yearbook Room	Door	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Yearbook Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Yearbook Room	Stringer	Metal	Grey	Chipping	2	2.9	Positive
1	1	Stairs adjacent to Yearbook Room	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairs adjacent to Yearbook Room	Riser	Metal	Grey	Chipping	2	1.5	Positive
1	1	Stairs adjacent to Yearbook Room	Newell Post	Metal	Grey	Chipping	2	1.8	Positive
1	1	Stairs adjacent to Classroom 126	W1	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 126	W2	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 126	W3	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 126	W4	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 126	Ceiling	Concrete	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 126	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairs adjacent to Classroom 126	Door	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Classroom 126	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Classroom 126	Stringer	Metal	Grey	Chipping	2	4.3	Positive
1	1	Stairs adjacent to Classroom 126	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairs adjacent to Classroom 126	Riser	Metal	Grey	Chipping	2	3.7	Positive

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Stairs adjacent to Classroom 126	Newell Post	Metal	Grey	Chipping	2	4.2	Positive
1	1	Stairs adjacent to Classroom 116	W1	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 116	W2	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 116	W3	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 116	W4	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 116	Ceiling	Concrete	White	None	0	0	Negative
1	1	Stairs adjacent to Classroom 116	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairs adjacent to Classroom 116	Door	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Classroom 116	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Classroom 116	Stringer	Metal	Grey	Chipping	2	2.6	Positive
1	1	Stairs adjacent to Classroom 116	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairs adjacent to Classroom 116	Riser	Metal	Grey	Chipping	2	4.4	Positive
1	1	Stairs adjacent to Classroom 116	Newell Post	Metal	Grey	Chipping	2	1.1	Positive
1	1	Stairs adjacent to Counselor's Suite	W1	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Counselor's Suite	W2	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Counselor's Suite	W3	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Counselor's Suite	W4	CMU	White	None	0	0	Negative
1	1	Stairs adjacent to Counselor's Suite	Ceiling	Concrete	White	None	0	0	Negative
1	1	Stairs adjacent to Counselor's Suite	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairs adjacent to Counselor's Suite	Door	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Counselor's Suite	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Stairs adjacent to Counselor's Suite	Stringer	Metal	Grey	Chipping	2	2.2	Positive
1	1	Stairs adjacent to Counselor's Suite	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairs adjacent to Counselor's Suite	Riser	Metal	Grey	Chipping	2	2.1	Positive
1	1	Stairs adjacent to Counselor's Suite	Newell Post	Metal	Grey	Chipping	2	4.2	Positive
1	1	Hallway from Classroom 116 to F2-3 Closet	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway from Classroom 116 to F2-3 Closet	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 116 to F2-3 Closet	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 116 to F2-3 Closet	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 116 to F2-3 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Classroom 116 to F2-3 Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Yearbook Room to Main Office	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Yearbook Room to Main Office	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Yearbook Room to Main Office	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Yearbook Room to Main Office	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Yearbook Room to Main Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Yearbook Room to Main Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 127-159	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 127-159	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 127-159	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 127-159	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classroom 127-159	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Classroom 127-159	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Counselor's Suite to Classroom 116	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Counselor's Suite to Classroom 116	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Counselor's Suite to Classroom 116	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Counselor's Suite to Classroom 116	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Counselor's Suite to Classroom 116	Ceiling	Concrete	White	None	0	0	Negative
1	1	Hallway from Counselor's Suite to Classroom 116	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office G	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office G	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office G	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Counselor Office G	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office G	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office G	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office G	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office F	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office F	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office F	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office F	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office F	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office F	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office F	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office E	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office E	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office E	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office E	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office E	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office E	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office E	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office D	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office D	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office D	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office D	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office D	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office D	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office D	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office C	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Counselor Office C	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office C	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office C	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office C	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office C	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office C	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office B	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office B	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office B	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office B	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office B	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office B	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office B	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Counselor Office A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Counselor Office A	W1	CMU	White	None	0	0	Negative
1	1	Counselor Office A	W2	CMU	White	None	0	0	Negative
1	1	Counselor Office A	W3	CMU	White	None	0	0	Negative
1	1	Counselor Office A	W4	CMU	White	None	0	0	Negative
1	1	Counselor Office A	Ceiling	Concrete	White	None	0	0	Negative
1	1	Counselor Office A	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Next to Bilingual Counseling Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Storage Next to Bilingual Counseling Office	W1	CMU	White	None	0	0	Negative
1	1	Storage Next to Bilingual Counseling Office	W2	CMU	White	None	0	0	Negative
1	1	Storage Next to Bilingual Counseling Office	W3	CMU	White	None	0	0	Negative
1	1	Storage Next to Bilingual Counseling Office	W4	CMU	White	None	0	0	Negative
1	1	Storage Next to Bilingual Counseling Office	Ceiling	Concrete	White	None	0	0	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Storage Next to Bilingual Counseling Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Bilingual Counseling Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Bilingual Counseling Office	W1	CMU	White	None	0	0	Negative
1	1	Bilingual Counseling Office	W2	CMU	White	None	0	0	Negative
1	1	Bilingual Counseling Office	W3	CMU	White	None	0	0	Negative
1	1	Bilingual Counseling Office	W4	CMU	White	None	0	0	Negative
1	1	Bilingual Counseling Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Bilingual Counseling Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Small Conference Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Small Conference Room	W1	CMU	White	None	0	0	Negative
1	1	Small Conference Room	W2	CMU	White	None	0	0	Negative
1	1	Small Conference Room	W3	CMU	White	None	0	0	Negative
1	1	Small Conference Room	W4	CMU	White	None	0	0	Negative
1	1	Small Conference Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Small Conference Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Outside Bilingual Counseling Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Outside Bilingual Counseling Office	W1	CMU	White	None	0	0	Negative
1	1	Outside Bilingual Counseling Office	W2	CMU	White	None	0	0	Negative
1	1	Outside Bilingual Counseling Office	W3	CMU	White	None	0	0	Negative
1	1	Outside Bilingual Counseling Office	W4	CMU	White	None	0	0	Negative
1	1	Outside Bilingual Counseling Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Outside Bilingual Counseling Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Mail Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Mail Room	W1	CMU	White	None	0	0	Negative
1	1	Mail Room	W2	CMU	White	None	0	0	Negative
1	1	Mail Room	W3	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Mail Room	W4	CMU	White	None	0	0	Negative
1	1	Mail Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Mail Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Roster Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Roster Office	W1	CMU	White	None	0	0	Negative
1	1	Roster Office	W2	CMU	White	None	0	0	Negative
1	1	Roster Office	W3	CMU	White	None	0	0	Negative
1	1	Roster Office	W4	CMU	White	None	0	0	Negative
1	1	Roster Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Roster Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 157	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 157	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 157	W1	CMU	White	None	0	0	Negative
1	1	Classroom 157	W2	CMU	White	None	0	0	Negative
1	1	Classroom 157	W3	CMU	White	None	0	0	Negative
1	1	Classroom 157	W4	CMU	White	None	0	0	Negative
1	1	Classroom 157	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 157	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom Next to Mail Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Girl's Restroom Next to Mail Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Girl's Restroom Next to Mail Room	W1	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Next to Mail Room	W2	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Next to Mail Room	W3	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Next to Mail Room	W4	CMU	White	None	0	0	Negative
1	1	Girl's Restroom Next to Mail Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girl's Restroom Next to Mail Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Restroom next to Mail Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Boy's Restroom next to Mail Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Boy's Restroom next to Mail Room	W1	CMU	White	None	0	0	Negative
1	1	Boy's Restroom next to Mail Room	W2	CMU	White	None	0	0	Negative
1	1	Boy's Restroom next to Mail Room	W3	CMU	White	None	0	0	Negative
1	1	Boy's Restroom next to Mail Room	W4	CMU	White	None	0	0	Negative
1	1	Boy's Restroom next to Mail Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Restroom next to Mail Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office Storage	W1	CMU	White	None	0	0	Negative
1	1	Main Office Storage	W2	CMU	White	None	0	0	Negative
1	1	Main Office Storage	W3	CMU	White	None	0	0	Negative
1	1	Main Office Storage	W4	CMU	White	None	0	0	Negative
1	1	Main Office Storage	Ceiling	Concrete	White	None	0	0	Negative
1	1	Main Office Storage	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office	W1	CMU	Yellow	Friction	2	0.03	Negative
1	1	Main Office	W2	CMU	Yellow	None	0	0	Negative
1	1	Main Office	W3	CMU	Yellow	None	0	0.05	Negative
1	1	Main Office	W4	CMU	Yellow	Chipping	3	0.08	Negative
1	1	Main Office	Column 1	Concrete	Yellow	None	0	0	Negative
1	1	Main Office	Column 2	Concrete	Yellow	None	0	0.03	Negative
1	1	Main Office	Door Frame 1	Metal	Blue	Chipping	1	0	Negative
1	1	Main Office	Door Frame 2	Metal	Blue	Chipping	1	0	Negative
1	1	Main Office	Door Frame 3	Metal	Blue	Chipping	1	0.03	Negative
1	1	Main Office	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Vice Principal Office #1	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Vice Principal Office #1	W2	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #1	W3	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #1	W4	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #1	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Vice Principal Office #1	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Vice Principal Office #1	Door Frame 1	Metal	Blue	None	0	0.17	Negative	
1	1	Vice Principal Office #1	Door Frame 2	Metal	Blue	None	0	0.05	Negative	
1	1	Vice Principal Office #1	Door Frame 1	Metal	Tan	None	0	0.06	Negative	
1	1	Vice Principal Office #1	Door Frame 2	Metal	Tan	None	0	0.04	Negative	
1	1	Vice Principal Office #1	Window Frame	Metal	Tan	None	0	0.08	Negative	
1	1	Vice Principal Office #1	Radiator	Metal	Tan	None	0	0.02	Negative	
1	1	Vice Principal Office #2	W1	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #2	W2	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #2	W3	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #2	W4	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #2	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Vice Principal Office #2	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Vice Principal Office #3	W1	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #3	W2	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #3	W3	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #3	W4	CMU	White	None	0	0	Negative	
1	1	Vice Principal Office #3	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Vice Principal Office #3	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Vice Principal Meeting Room	W1	CMU	White	None	0	0	Negative	
1	1	Vice Principal Meeting Room	W2	CMU	White	None	0	0	Negative	
1	1	Vice Principal Meeting Room	W3	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Vice Principal Meeting Room	W4	CMU	White	None	0	0	Negative
1	1	Vice Principal Meeting Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Vice Principal Meeting Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	School Operations Officer Office	W1	CMU	White	None	0	0	Negative
1	1	School Operations Officer Office	W2	CMU	White	None	0	0	Negative
1	1	School Operations Officer Office	W3	CMU	White	None	0	0	Negative
1	1	School Operations Officer Office	W4	CMU	White	None	0	0	Negative
1	1	School Operations Officer Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	School Operations Officer Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office Restroom	W1	CMU	White	None	0	0	Negative
1	1	Main Office Restroom	W2	CMU	White	None	0	0	Negative
1	1	Main Office Restroom	W3	CMU	White	None	0	0	Negative
1	1	Main Office Restroom	W4	CMU	White	None	0	0	Negative
1	1	Main Office Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Main Office Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Women's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Women's Restroom	W1	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W4	CMU	White	None	0	0	Negative
1	1	Women's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Women's Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Men's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W4	CMU	White	None	0	0	Negative
1	1	Men's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	1	Men's Restroom	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Lounge	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Teacher's Lounge	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Teacher's Lounge	W1	CMU	White	None	0	0	Negative
1	1	Teacher's Lounge	W2	CMU	White	None	0	0	Negative
1	1	Teacher's Lounge	W3	CMU	White	None	0	0	Negative
1	1	Teacher's Lounge	W4	CMU	White	None	0	0	Negative
1	1	Teacher's Lounge	Ceiling	Concrete	White	None	0	0	Negative
1	1	Teacher's Lounge	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	F2-2 Closet	W1	CMU	White	None	0	0	Negative
1	1	F2-2 Closet	W2	CMU	White	None	0	0	Negative
1	1	F2-2 Closet	W3	CMU	White	None	0	0	Negative
1	1	F2-2 Closet	W4	CMU	White	None	0	0	Negative
1	1	F2-2 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	1	F2-2 Closet	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Yearbook Room	W1	CMU	White	None	0	0	Negative
1	1	Yearbook Room	W2	CMU	White	None	0	0	Negative
1	1	Yearbook Room	W3	CMU	White	None	0	0	Negative
1	1	Yearbook Room	W4	CMU	White	None	0	0	Negative
1	1	Yearbook Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Yearbook Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	W1	CMU	White	None	0	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	W2	CMU	White	None	0	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	W3	CMU	White	None	0	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	W4	CMU	White	None	0	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	Ceiling	Concrete	White	None	0	0	Negative
1	1	Culinary Arts Kitchen Classroom 155 Back Storage(The Cla	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	L-130 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	L-130 Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	L-130 Office	W1	CMU	White	None	0	0	Negative
1	1	L-130 Office	W2	CMU	White	None	0	0	Negative
1	1	L-130 Office	W3	CMU	White	None	0	0	Negative
1	1	L-130 Office	W4	CMU	White	None	0	0	Negative
1	1	L-130 Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	L-130 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 139B	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Office 139B	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Office 139B	W1	CMU	White	None	0	0	Negative
1	1	Office 139B	W2	CMU	White	None	0	0	Negative
1	1	Office 139B	W3	CMU	White	None	0	0	Negative
1	1	Office 139B	W4	CMU	White	None	0	0	Negative
1	1	Office 139B	Ceiling	Concrete	White	None	0	0	Negative
1	1	Office 139B	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Finance Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Finance Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Finance Office	W1	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Finance Office	W2	CMU	White	None	0	0	Negative
1	1	Finance Office	W3	CMU	White	None	0	0	Negative
1	1	Finance Office	W4	CMU	White	None	0	0	Negative
1	1	Finance Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	Finance Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	L-127 Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	L-127 Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	L-127 Office	W1	CMU	White	None	0	0	Negative
1	1	L-127 Office	W2	CMU	White	None	0	0	Negative
1	1	L-127 Office	W3	CMU	White	None	0	0	Negative
1	1	L-127 Office	W4	CMU	White	None	0	0	Negative
1	1	L-127 Office	Ceiling	Concrete	White	None	0	0	Negative
1	1	L-127 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129E	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Office 129E	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Office 129E	W1	CMU	White	None	0	0.02	Negative
1	1	Office 129E	W2	CMU	White	None	0	0.04	Negative
1	1	Office 129E	W3	Concrete	White	Chipping	10	0.05	Negative
1	1	Office 129E	W4	CMU	White	None	0	0.02	Negative
1	1	Office 129E	Ceiling	Concrete	White	Chipping	10	0.02	Negative
1	1	Office 129E	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	ID Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	ID Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	ID Office	W1	CMU	White	None	0	0.01	Negative
1	1	ID Office	W2	CMU	White	None	0	0.02	Negative
1	1	ID Office	W3	Concrete	White	Chipping	10	0.02	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	ID Office	W4	CMU	White	None	0	0.04	Negative
1	1	ID Office	Ceiling	Concrete	White	Chipping	10	0.03	Negative
1	1	ID Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	ID Office	Door Frame	Metal	Blue	None	0	0	Negative
1	1	ID Office	Radiator	Metal	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Right Side Storage Closet in Classroom 127	W1	CMU	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	W2	CMU	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	W3	CMU	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	W4	CMU	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	Ceiling	Concrete	White	None	0	0	Negative
1	1	Right Side Storage Closet in Classroom 127	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Left Side Storage Closet in Classroom 127	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Left Side Storage Closet in Classroom 127	W1	CMU	White	None	0	0	Negative
1	1	Left Side Storage Closet in Classroom 127	W2	CMU	White	None	0	0	Negative
1	1	Left Side Storage Closet in Classroom 127	W3	CMU	White	None	0	0	Negative
1	1	Left Side Storage Closet in Classroom 127	W4	CMU	White	None	0	0	Negative
1	1	Left Side Storage Closet in Classroom 127	Ceiling	Concrete	White	None	0	0	Negative
1	1	Left Side Storage Closet in Classroom 127	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Room F2-3	W1	CMU	White	None	0	0	Negative
1	1	Room F2-3	W2	CMU	White	None	0	0	Negative
1	1	Room F2-3	W3	CMU	White	None	0	0	Negative
1	1	Room F2-3	W4	CMU	White	None	0	0	Negative
1	1	Room F2-3	Ceiling	Concrete	White	None	0	0	Negative
1	1	Room F2-3	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	IMC Lounge	W1	CMU	Yellow	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	IMC Lounge	W2	CMU	Yellow	None	0	0	Negative	
1	1	IMC Lounge	W3	CMU	Yellow	None	0	0	Negative	
1	1	IMC Lounge	W4	CMU	Yellow	None	0	0	Negative	
1	1	IMC Lounge	Ceiling	Concrete	White	None	0	0	Negative	
1	1	IMC Lounge	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	IMC Lounge	Door Frame	Metal	Yellow	Chipping	1	0	Negative	
1	1	IMC Copy Room	W1	CMU	Yellow	None	0	0	Negative	
1	1	IMC Copy Room	W2	CMU	Yellow	None	0	0	Negative	
1	1	IMC Copy Room	W3	CMU	Yellow	None	0	0	Negative	
1	1	IMC Copy Room	W4	CMU	Yellow	None	0	0	Negative	
1	1	IMC Copy Room	Ceiling	Concrete	White	None	0	0	Negative	
1	1	IMC Copy Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	IMC Copy Room	Door Frame	Metal	Yellow	Chipping	1	0	Negative	
1	1	IMC	W1	CMU	Blue	None	0	0.02	Negative	
1	1	IMC	W2	CMU	Blue	None	0	0.03	Negative	
1	1	IMC	W3	CMU	Blue	None	0	0	Negative	
1	1	IMC	W4	CMU	Blue	None	0	0.03	Negative	
1	1	IMC	Ceiling	Concrete	White	None	0	0	Negative	
1	1	IMC	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	IMC	Column 1	CMU	Blue	None	0	0	Negative	
1	1	IMC	Column 2	CMU	Blue	None	0	0	Negative	
1	1	IMC	Column 3	CMU	Blue	None	0	0	Negative	
1	1	IMC	Column 4	CMU	Blue	None	0	0.04	Negative	
1	1	IMC	Column 5	CMU	Blue	None	0	0	Negative	
1	1	IMC	Door Frame 1	Metal	Blue	Chipping	2	0	Negative	
1	1	IMC	Door Frame 2	Metal	Blue	Chipping	2	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	IMC	Radiator	Metal	White	None	0	0.05	Negative
1	1	Classroom 127	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 127	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 127	W1	CMU	White	None	0	0.04	Negative
1	1	Classroom 127	W2	CMU	White	None	0	0	Negative
1	1	Classroom 127	W3	Concrete	White	Flaking	15	0.05	Negative
1	1	Classroom 127	W4	CMU	White	None	0	0.02	Negative
1	1	Classroom 127	Ceiling	Concrete	White	Flaking	15	0.03	Negative
1	1	Classroom 127	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 127	Door Frame	Metal	Blue	None	0	0.01	Negative
1	1	Classroom 127	Radiator	Metal	White	None	0	0.03	Negative
1	1	Classroom 126	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 126	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 126	W1	CMU	Pink	None	0	0.03	Negative
1	1	Classroom 126	W2	CMU	White	None	0	0.05	Negative
1	1	Classroom 126	W3	Concrete	White	Chipping	15	0.06	Negative
1	1	Classroom 126	W4	CMU	White	None	0	0.05	Negative
1	1	Classroom 126	Ceiling	Concrete	White	Chipping	10	0.01	Negative
1	1	Classroom 126	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 126	Door Frame	Metal	Blue	None	0	0.02	Negative
1	1	Classroom 126	Radiator	Metal	White	None	0	0.04	Negative
1	1	Classroom 124	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 124	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 124	W1	CMU	Pink	None	0	0.26	Negative
1	1	Classroom 124	W2	CMU	White	None	0	0.02	Negative
1	1	Classroom 124	W3	Concrete	White	Chipping	15	0.05	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 124	W4	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 124	Ceiling	Concrete	White	Chipping	5	0.03	Negative
1	1	Classroom 124	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 124	Door Frame	Metal	Blue	None	0	0.02	Negative
1	1	Classroom 124	Radiator	Metal	White	Chipping	5	0.02	Negative
1	1	Classroom 123	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 123	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 123	W1	CMU	White	None	0	0.03	Negative
1	1	Classroom 123	W2	CMU	White	None	0	0.04	Negative
1	1	Classroom 123	W3	CMU	White	None	0	0	Negative
1	1	Classroom 123	W4	CMU	White	None	0	0.05	Negative
1	1	Classroom 123	Ceiling	Concrete	White	None	0	0	Negative
1	1	Classroom 123	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 123	Door Frame	Metal	Blue	Chipping	1	0.01	Negative
1	1	Classroom 123	Radiator	Metal	White	None	0	0.07	Negative
1	1	Classroom 122	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 122	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 122	W1	CMU	Pink	None	0	0	Negative
1	1	Classroom 122	W2	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 122	W3	Concrete	White	Flaking	15	0.03	Negative
1	1	Classroom 122	W3	CMU	White	Flaking	5	0.03	Negative
1	1	Classroom 122	W4	CMU	White	None	0	0.04	Negative
1	1	Classroom 122	Ceiling	Concrete	White	Chipping	20	0.06	Negative
1	1	Classroom 122	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 122	Door Frame	Metal	White	Chipping	1	0.03	Negative
1	1	Classroom 122	Radiator	Metal	White	None	0	0.05	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Language Office Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office Storage	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office Storage	W1	CMU	Tan	None	0	0.02	Negative
1	1	Language Office Storage	W2	CMU	Tan	None	0	0	Negative
1	1	Language Office Storage	W3	Concrete	Tan	None	0	0	Negative
1	1	Language Office Storage	W4	CMU	Tan	None	0	0.01	Negative
1	1	Language Office Storage	Ceiling	Concrete	White	None	0	0.05	Negative
1	1	Language Office Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Language Office Storage	Door Frame	Metal	White	None	0	0	Negative
1	1	Language Office	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office	W1	CMU	Blue	None	0	0	Negative
1	1	Language Office	W2	CMU	Blue	None	0	0.01	Negative
1	1	Language Office	W3	Concrete	Blue	None	0	0.04	Negative
1	1	Language Office	W4	CMU	Blue	None	0	0	Negative
1	1	Language Office	Ceiling	Concrete	White	None	0	0.08	Negative
1	1	Language Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Language Office	Door Frame	Metal	Blue	None	0	0	Negative
1	1	Language Office	Radiator	Metal	Blue	None	0	0	Negative
1	1	Language Office Conference Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office Conference Room	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Language Office Conference Room	W1	CMU	Blue	None	0	0.02	Negative
1	1	Language Office Conference Room	W2	CMU	Blue	None	0	0	Negative
1	1	Language Office Conference Room	W3	Concrete	Blue	None	0	0	Negative
1	1	Language Office Conference Room	W4	CMU	Blue	None	0	0.01	Negative
1	1	Language Office Conference Room	Ceiling	Concrete	White	None	0	0.05	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Language Office Conference Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Language Office Conference Room	Radiator	Metal	Blue	None	0	0.09	Negative
1	1	Language Office Conference Room	Door Frame	Metal	Blue	Friction	1	0.05	Negative
1	1	Classroom 121	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 121	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 121	W1	CMU	White	None	0	0.04	Negative
1	1	Classroom 121	W2	CMU	White	None	0	0.03	Negative
1	1	Classroom 121	W3	CMU	White	None	0	0.05	Negative
1	1	Classroom 121	W3	Concrete	White	None	0	0.05	Negative
1	1	Classroom 121	W4	CMU	White	None	0	0.04	Negative
1	1	Classroom 121	Ceiling	Concrete	White	None	0	0.02	Negative
1	1	Classroom 121	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 121	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
1	1	Classroom 121	Radiator	Metal	Blue	None	0	0.02	Negative
1	1	Classroom 120	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 120	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 120	W1	CMU	White	None	0	0.03	Negative
1	1	Classroom 120	W2	CMU	White	None	0	0.02	Negative
1	1	Classroom 120	W3	CMU	White	None	0	0.02	Negative
1	1	Classroom 120	W3	Concrete	White	None	0	0.02	Negative
1	1	Classroom 120	W4	CMU	White	None	0	0.05	Negative
1	1	Classroom 120	Ceiling	Concrete	White	None	0	0.02	Negative
1	1	Classroom 120	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 120	Door Frame	Metal	Blue	Chipping	2	0.04	Negative
1	1	Classroom 120	Radiator	Metal	Blue	Flaking	15	0.03	Negative
1	1	Classroom 118	Door Frame	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 118	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 118	W1	CMU	Green	None	0	0.02	Negative
1	1	Classroom 118	W2	CMU	Green	None	0	0.01	Negative
1	1	Classroom 118	W3	CMU	White	Chipping	10	0.02	Negative
1	1	Classroom 118	W3	Concrete	White	Chipping	10	0.02	Negative
1	1	Classroom 118	W4	CMU	Green	None	0	0	Negative
1	1	Classroom 118	Ceiling	Concrete	White	None	0	0.02	Negative
1	1	Classroom 118	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 118	Door Frame	Metal	Blue	Chipping	2	0.06	Negative
1	1	Classroom 118	Radiator	Metal	Green	Chipping	5	0	Negative
1	1	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Women's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Women's Restroom	W1	CMU	White	None	0	0.02	Negative
1	1	Women's Restroom	W2	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W3	CMU	White	None	0	0	Negative
1	1	Women's Restroom	W4	CMU	White	None	0	0.01	Negative
1	1	Women's Restroom	Ceiling	Concrete	White	Flaking	10	0.05	Negative
1	1	Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom	Radiator	Metal	White	Flaking	1	0.09	Negative
1	1	Women's Restroom	Door Frame	Metal	Blue	Friction	1	0.05	Negative
1	1	Classroom 116	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 116	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 116	W1	CMU	Green	None	0	0.02	Negative
1	1	Classroom 116	W2	CMU	Green	None	0	0.01	Negative
1	1	Classroom 116	W3	Concrete	White	Chipping	10	0.02	Negative
1	1	Classroom 116	W3	Concrete	White	Chipping	10	0.02	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Classroom 116	W4	CMU	Green	None	0	0	Negative
1	1	Classroom 116	Ceiling	Concrete	White	None	0	0.02	Negative
1	1	Classroom 116	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 116	Door Frame	Metal	Blue	None	0	0.05	Negative
1	1	Classroom 116	Radiator	Metal	White	None	0	0.05	Negative
1	1	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	W1	CMU	White	None	0	0	Negative
1	1	Men's Restroom	W2	CMU	White	None	0	0.06	Negative
1	1	Men's Restroom	W3	CMU	White	None	0	0.02	Negative
1	1	Men's Restroom	W4	CMU	White	None	0	0.03	Negative
1	1	Men's Restroom	Ceiling	Concrete	White	Flaking	10	0.02	Negative
1	1	Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom	Radiator	Metal	White	Flaking	1	0.04	Negative
1	1	Men's Restroom	Door Frame	Metal	Blue	Friction	1	0.09	Negative
1	1	Classroom 114	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 114	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 114	W1	CMU	White	None	0	0.03	Negative
1	1	Classroom 114	W2	CMU	Tan	None	0	0.02	Negative
1	1	Classroom 114	W3	Concrete	Tan	Chipping	15	0.04	Negative
1	1	Classroom 114	W3	CMU	Tan	Chipping	15	0.04	Negative
1	1	Classroom 114	W4	CMU	Tan	None	0	0.01	Negative
1	1	Classroom 114	Ceiling	Concrete	White	Chipping	3	0.03	Negative
1	1	Classroom 114	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 114	Door Frame	Metal	Blue	Chipping	2	0.02	Negative
1	1	Classroom 114	Radiator	Metal	White	Chipping	4	0.1	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Storage Room adjacent to Classroom 111	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Storage Room adjacent to Classroom 111	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Storage Room adjacent to Classroom 111	W1	CMU	White	None	0	0	Negative
1	1	Storage Room adjacent to Classroom 111	W2	CMU	White	None	0	0	Negative
1	1	Storage Room adjacent to Classroom 111	W3	CMU	White	None	0	0	Negative
1	1	Storage Room adjacent to Classroom 111	W4	CMU	White	None	0	0	Negative
1	1	Storage Room adjacent to Classroom 111	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage Room adjacent to Classroom 111	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 112	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 112	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 112	W1	CMU	Red	None	0	0.03	Negative
1	1	Classroom 112	W2	CMU	White	None	0	0.01	Negative
1	1	Classroom 112	W3	CMU	White	None	0	0.06	Negative
1	1	Classroom 112	W3	Concrete	White	None	0	0.04	Negative
1	1	Classroom 112	W4	CMU	White	None	0	0.08	Negative
1	1	Classroom 112	Radiator	Metal	Red	Chipping	4	0.03	Negative
1	1	Classroom 112	Door Frame	Metal	Blue	Chipping	1	0.09	Negative
1	1	Classroom 112	Ceiling	Concrete	White	None	0	0.04	Negative
1	1	Classroom 112	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 111	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 111	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 111	W1	CMU	Blue	None	0	0	Negative
1	1	Classroom 111	W2	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 111	W3	CMU	White	None	0	0.02	Negative
1	1	Classroom 111	W3	Concrete	White	None	0	0.08	Negative
1	1	Classroom 111	W4	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Classroom 111	Radiator	Metal	Blue	Chipping	1	0.03	Negative	
1	1	Classroom 111	Door Frame	Metal	Blue	Chipping	1	0.04	Negative	
1	1	Classroom 111	Ceiling	Concrete	White	None	0	0.04	Negative	
1	1	Classroom 111	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 110	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 110	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 110	W1	CMU	White	None	0	0.02	Negative	
1	1	Classroom 110	W2	CMU	White	None	0	0.01	Negative	
1	1	Classroom 110	W3	CMU	White	None	0	0.01	Negative	
1	1	Classroom 110	W3	Concrete	White	None	0	0.01	Negative	
1	1	Classroom 110	W4	CMU	White	None	0	0.07	Negative	
1	1	Classroom 110	Radiator	Metal	White	Chipping	1	0.05	Negative	
1	1	Classroom 110	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 110	Ceiling	Concrete	White	None	0	0.04	Negative	
1	1	Classroom 110	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 109	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 109	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 109	W1	CMU	White	None	0	0.03	Negative	
1	1	Classroom 109	W2	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 109	W3	Concrete	White	Chipping	5	0.05	Negative	
1	1	Classroom 109	W3	CMU	White	Chipping	5	0.05	Negative	
1	1	Classroom 109	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 109	Ceiling	Concrete	White	Chipping	10	0.03	Negative	
1	1	Classroom 109	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 109	Door Frame	Metal	Blue	Chipping	2	0.02	Negative	
1	1	Classroom 109	Radiator	Metal	White	None	0	0.08	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Special Needs Office D	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office D	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office D	W1	CMU	Purple	None	0	0.02	Negative
1	1	Special Needs Office D	W2	CMU	Purple	None	0	0.02	Negative
1	1	Special Needs Office D	W3	Concrete	Purple	None	0	0.04	Negative
1	1	Special Needs Office D	W4	CMU	Purple	None	0	0.01	Negative
1	1	Special Needs Office D	Ceiling	Concrete	White	None	0	0.02	Negative
1	1	Special Needs Office D	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Special Needs Office C	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office C	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office C	W1	CMU	Purple	None	0	0.02	Negative
1	1	Special Needs Office C	W2	CMU	Purple	None	0	0.03	Negative
1	1	Special Needs Office C	W3	Concrete	Purple	None	0	0.03	Negative
1	1	Special Needs Office C	W4	CMU	Purple	None	0	0.01	Negative
1	1	Special Needs Office C	Ceiling	Concrete	White	None	0	0.06	Negative
1	1	Special Needs Office C	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Special Needs Office B	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office B	Radiator	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office B	W1	CMU	Purple	None	0	0.05	Negative
1	1	Special Needs Office B	W2	CMU	Purple	None	0	0.02	Negative
1	1	Special Needs Office B	W3	Concrete	Purple	None	0	0.02	Negative
1	1	Special Needs Office B	W4	CMU	Purple	None	0	0.02	Negative
1	1	Special Needs Office B	Ceiling	Concrete	White	None	0	0.04	Negative
1	1	Special Needs Office B	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Special Needs Office A	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Special Needs Office A	Radiator	Metal	Blue	Chipping	1	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Special Needs Office A	W1	CMU	Purple	None	0	0.01	Negative	
1	1	Special Needs Office A	W2	CMU	Purple	None	0	0.02	Negative	
1	1	Special Needs Office A	W3	Concrete	Purple	None	0	0.02	Negative	
1	1	Special Needs Office A	W4	CMU	Purple	None	0	0.02	Negative	
1	1	Special Needs Office A	Ceiling	Concrete	White	None	0	0.04	Negative	
1	1	Special Needs Office A	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Special Needs Suite Lobby	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Special Needs Suite Lobby	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	1	Special Needs Suite Lobby	W1	CMU	Purple	None	0	0	Negative	
1	1	Special Needs Suite Lobby	W2	CMU	Purple	None	0	0	Negative	
1	1	Special Needs Suite Lobby	W3	Concrete	Purple	None	0	0	Negative	
1	1	Special Needs Suite Lobby	W4	CMU	Purple	None	0	0	Negative	
1	1	Special Needs Suite Lobby	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Special Needs Suite Lobby	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 107	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 107	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	1	Classroom 107	W1	CMU	White	None	0	0	Negative	
1	1	Classroom 107	W2	CMU	White	None	0	0	Negative	
1	1	Classroom 107	W3	CMU	White	None	0	0	Negative	
1	1	Classroom 107	W4	CMU	White	None	0	0	Negative	
1	1	Classroom 107	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Classroom 107	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 107	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Classroom 107	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Counselor's Suite Copy Room	W1	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Copy Room	W2	CMU	White	None	0	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Counselor's Suite Copy Room	W3	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Copy Room	W4	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Copy Room	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Counselor's Suite Copy Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Counselor's Suite Copy Room	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Counselor's Suite Copy Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Counselor's Suite Lobby	W1	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	W2	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	W3	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	W4	CMU	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Counselor's Suite Lobby	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Counselor's Suite Lobby	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Principal's Office Closet	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Principal's Office Closet	Radiator	Metal	Blue	Chipping	1	0	Negative	
1	1	Principal's Office Closet	W1	CMU	Yellow	None	0	0	Negative	
1	1	Principal's Office Closet	W2	CMU	Yellow	None	0	0	Negative	
1	1	Principal's Office Closet	W3	CMU	Yellow	None	0	0.05	Negative	
1	1	Principal's Office Closet	W4	CMU	Yellow	None	0	0.03	Negative	
1	1	Principal's Office Closet	Ceiling	Concrete	Yellow	None	0	0.01	Negative	
1	1	Principal's Office Closet	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Principal's Office Closet	Door Frame	Metal	Blue	None	0	0.02	Negative	
1	1	Principal's Office Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Principal's Office Restroom	W1	CMU	Yellow	None	0	0.01	Negative	
1	1	Principal's Office Restroom	W2	CMU	Yellow	Flaking	5	0.03	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Principal's Office Restroom	W3	CMU	Yellow	None	0	0	Negative	
1	1	Principal's Office Restroom	W4	CMU	Yellow	None	0	0.03	Negative	
1	1	Principal's Office Restroom	Ceiling	Concrete	Yellow	Flaking	5	0	Negative	
1	1	Principal's Office Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Principal's Office Restroom	Door Frame	Metal	Blue	None	0	0.05	Negative	
1	1	Principal's Office	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Principal's Office	W1	CMU	Yellow	None	0	0.01	Negative	
1	1	Principal's Office	W2	CMU	Yellow	None	0	0.05	Negative	
1	1	Principal's Office	W3	CMU	Yellow	None	0	0	Negative	
1	1	Principal's Office	W4	CMU	Yellow	None	0	0	Negative	
1	1	Principal's Office	Door Frame 1	Metal	Blue	None	0	0	Negative	
1	1	Principal's Office	Door Frame 2	Metal	Blue	None	0	0	Negative	
1	1	Principal's Office	Door Frame 3	Metal	Blue	None	0	0.02	Negative	
1	1	Principal's Office	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Principal's Office	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Hallway between Practice Rooms	W1	CMU	White	None	0	0	Negative	
1	1	Hallway between Practice Rooms	W2	CMU	White	None	0	0	Negative	
1	1	Hallway between Practice Rooms	W3	CMU	White	None	0	0	Negative	
1	1	Hallway between Practice Rooms	W4	CMU	White	None	0	0	Negative	
1	1	Hallway between Practice Rooms	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Hallway between Practice Rooms	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Hallway from Classroom 100 to Ticket Room	W2	CMU	Yellow	None	0	0.02	Negative	
1	1	Hallway from Classroom 100 to Ticket Room	W2	CMU	Red	Flaking	5	0.05	Negative	
1	1	Hallway from Classroom 100 to Ticket Room	W4	CMU	Yellow	Chipping	25	0.01	Negative	
1	1	Hallway from Classroom 100 to Ticket Room	W4	Concrete	Yellow	Flaking	2	0.03	Negative	
1	1	Hallway from Classroom 100 to Ticket Room	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway from Classroom 100 to Ticket Room	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 100 to Ticket Room	Spindle	Metal	Tan	Flaking	5	0.27	Negative
1	1	Hallway from Classroom 100 to Ticket Room	Riser	Metal	Grey	Flaking	10	1.1	Positive
1	1	Hallway from Classroom 100 to Ticket Room	Stringer	Metal	Grey	Flaking	10	0.7	Positive
1	1	Hallway from Classroom 100 to Ticket Room	Handrail	Metal	Tan	Flaking	5	0.08	Negative
1	1	Hallway from Classroom 162 to 164	W1	CMU	Yellow	None	0	0.02	Negative
1	1	Hallway from Classroom 162 to 164	W1	CMU	Red	None	0	0	Negative
1	1	Hallway from Classroom 162 to 164	W3	CMU	Multi	None	0	0.04	Negative
1	1	Hallway from Classroom 162 to 164	W3	CMU	Yellow	None	0	0.02	Negative
1	1	Hallway from Classroom 162 to 164	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 162 to 164	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 162 to 164	Door 1	Metal	Blue	Chipping	2	0.07	Negative
1	1	Hallway from Classroom 162 to 164	Door Frame 1	Metal	Blue	Chipping	2	0.11	Negative
1	1	Hallway from Classroom 162 to 164	Door 2	Metal	Blue	None	0	0	Negative
1	1	Hallway from Classroom 162 to 164	Door Frame 2	Metal	Blue	None	0	0	Negative
1	1	Hallway from Classroom 156 to 160	W2	CMU	Yellow	None	0	0.02	Negative
1	1	Hallway from Classroom 156 to 160	W2	CMU	Red	Flaking	15	0.05	Negative
1	1	Hallway from Classroom 156 to 160	W4	CMU	Yellow	Chipping	25	0.01	Negative
1	1	Hallway from Classroom 156 to 160	W4	Concrete	Yellow	Flaking	2	0.03	Negative
1	1	Hallway from Classroom 156 to 160	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 156 to 160	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classroom 156 to 160	Spindle	Metal	Tan	Flaking	5	0.04	Negative
1	1	Hallway from Classroom 156 to 160	Riser	Metal	Grey	Flaking	10	3	Positive
1	1	Hallway from Classroom 156 to 160	Stringer	Metal	Grey	Flaking	10	1.1	Positive
1	1	Hallway from Classroom 156 to 160	Handrail	Metal	Tan	Flaking	5	0.06	Negative
1	1	Hallway in Front of Auditorium	W1	Marble	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Hallway in Front of Auditorium	W2	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway in Front of Auditorium	W3	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway in Front of Auditorium	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway in Front of Auditorium	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway in Front of Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway in Front of Auditorium	Door 1	Metal	Blue	Chipping	2	0.14	Negative
1	1	Hallway in Front of Auditorium	Door 2	Metal	Blue	Chipping	2	0.05	Negative
1	1	Hallway in Front of Auditorium	Door 3	Metal	Blue	Chipping	2	0.1	Negative
1	1	Hallway in Front of Auditorium	Door 4	Metal	Blue	Chipping	2	0	Negative
1	1	Hallway in Front of Auditorium	Door 5	Metal	Blue	Chipping	2	0.06	Negative
1	1	Hallway in Front of Auditorium	Door 6	Metal	Blue	Chipping	2	0.01	Negative
1	1	Hallway in Front of Auditorium	Door 7	Metal	Blue	Chipping	2	0.17	Negative
1	1	Hallway in Front of Auditorium	Door 8	Metal	Blue	Chipping	2	0.04	Negative
1	1	Hallway in Front of Auditorium	Door 9	Metal	Blue	Chipping	2	0.02	Negative
1	1	Hallway in Front of Auditorium	Door 10	Metal	Blue	Chipping	2	0	Negative
1	1	Hallway in Front of Auditorium	Door Frame 1	Metal	Blue	Chipping	2	0	Negative
1	1	Hallway in Front of Auditorium	Door Frame 2	Metal	Blue	Chipping	2	0.03	Negative
1	1	Hallway in Front of Auditorium	Door Frame 3	Metal	Blue	Chipping	2	0.02	Negative
1	1	Hallway in Front of Auditorium	Door Frame 4	Metal	Blue	Chipping	2	0.07	Negative
1	1	Hallway in Front of Auditorium	Door Frame 5	Metal	Blue	Chipping	2	0	Negative
1	1	Hallway in Front of Auditorium	Door Frame 6	Metal	Blue	Chipping	2	0.03	Negative
1	1	Hallway in Front of Auditorium	Door Frame 7	Metal	Blue	Chipping	2	0.05	Negative
1	1	Hallway in Front of Auditorium	Door Frame 8	Metal	Blue	Chipping	2	0	Negative
1	1	Hallway in Front of Auditorium	Door Frame 9	Metal	Blue	Chipping	2	0.02	Negative
1	1	Hallway in Front of Auditorium	Door Frame 10	Metal	Blue	Chipping	2	0.05	Negative
1	1	Classroom 160	W1	CMU	White	None	0	0.03	Negative



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Classroom 160	W2	CMU	White	None	0	0.04	Negative	
1	1	Classroom 160	W3	Concrete	White	None	0	0.02	Negative	
1	1	Classroom 160	W4	CMU	White	None	0	0.02	Negative	
1	1	Classroom 160	Ceiling	Concrete	White	None	0	0.05	Negative	
1	1	Classroom 160	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 160	Door Frame	Metal	Blue	None	0	0	Negative	
1	1	Classroom 158	W1	CMU	White	None	0	0	Negative	
1	1	Classroom 158	W2	CMU	White	None	0	0	Negative	
1	1	Classroom 158	W3	CMU	White	None	0	0	Negative	
1	1	Classroom 158	W4	CMU	White	None	0	0	Negative	
1	1	Classroom 158	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Classroom 158	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 158	Door Frame	Metal	Blue	None	0	0	Negative	
1	1	Storage Room	W2	CMU	White	Flaking	15	0.03	Negative	
1	1	Storage Room	W3	CMU	White	Flaking	15	0.04	Negative	
1	1	Storage Room	W4	CMU	White	Flaking	15	0.01	Negative	
1	1	Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom Next to Music Classroom 162	W1	CMU	Blue	None	0	0	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	W2	CMU	Blue	None	0	0	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	W3	CMU	Blue	None	0	0	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	W4	CMU	Blue	None	0	0	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	1	Girl's Restroom Next to Music Classroom 162	Radiator	Metal	White	Chipping	5	0.1	Negative	
1	1	Girl's Restroom Next to Music Classroom 162	Door Frame	Metal	Blue	Chipping	1	0.02	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Restroom next to Music Classroom 164	W1	CMU	Blue	Flaking	2	0	Negative
1	1	Boy's Restroom next to Music Classroom 164	W2	CMU	Blue	None	0	0	Negative
1	1	Boy's Restroom next to Music Classroom 164	W3	CMU	Blue	None	0	0	Negative
1	1	Boy's Restroom next to Music Classroom 164	W4	CMU	Blue	None	0	0	Negative
1	1	Boy's Restroom next to Music Classroom 164	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Restroom next to Music Classroom 164	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom next to Music Classroom 164	Radiator	Metal	White	Chipping	5	0.07	Negative
1	1	Boy's Restroom next to Music Classroom 164	Door Frame	Metal	Blue	Chipping	1	0.02	Negative
1	1	Practice Room #4	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #4	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #4	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #4	W4	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #4	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #4	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #4	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #3	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #3	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #3	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #3	W4	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #3	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #3	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #3	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #2	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #2	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #2	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #2	W4	CMU	Grey	None	0	0.01	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Practice Room #2	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #2	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #2	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #1	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #1	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #1	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #1	W4	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #1	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #1	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #1	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #7	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #7	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #7	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #7	W4	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #7	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #7	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #7	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #6	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #6	W2	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #6	W3	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #6	W4	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #6	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #6	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Practice Room #6	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Practice Room #5	W1	CMU	Grey	None	0	0.01	Negative
1	1	Practice Room #5	W2	CMU	Grey	None	0	0.01	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Practice Room #5	W3	CMU	Grey	None	0	0.01	Negative	
1	1	Practice Room #5	W4	CMU	Grey	None	0	0.01	Negative	
1	1	Practice Room #5	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Practice Room #5	Door Frame	Metal	Grey	Chipping	1	0	Negative	
1	1	Practice Room #5	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Music Classroom 164	W1	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164	W2	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164	W3	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164	W4	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Music Classroom 164	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Music Classroom 164	Door Frame	Metal	Grey	Chipping	1	0	Negative	
1	1	Music Classroom 164 Office	W1	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164 Office	W2	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164 Office	W3	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164 Office	W4	CMU	Grey	None	0	0.01	Negative	
1	1	Music Classroom 164 Office	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Music Classroom 164 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Music Classroom 164 Office	Door Frame	Metal	Grey	Chipping	1	0	Negative	
1	1	Little Music Room Next to Office	W1	CMU	Grey	None	0	0.01	Negative	
1	1	Little Music Room Next to Office	W2	CMU	Grey	None	0	0.01	Negative	
1	1	Little Music Room Next to Office	W3	CMU	Grey	None	0	0.01	Negative	
1	1	Little Music Room Next to Office	W4	CMU	Grey	None	0	0.01	Negative	
1	1	Little Music Room Next to Office	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	1	Little Music Room Next to Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Little Music Room Next to Office	Door Frame	Metal	Grey	Chipping	1	0	Negative	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Music Classroom 162 Office	W1	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162 Office	W2	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162 Office	W3	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162 Office	W4	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162 Office	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 162 Office	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 162 Office	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	1	Music Classroom 162	W1	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162	W2	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162	W3	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162	W4	CMU	Grey	None	0	0.01	Negative
1	1	Music Classroom 162	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 162	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 162	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Storage Along Right Side of Auditorium	W1	CMU	White	None	0	0.03	Negative
1	1	Storage Along Right Side of Auditorium	W2	CMU	White	None	0	0.03	Negative
1	1	Storage Along Right Side of Auditorium	W3	CMU	White	None	0	0.03	Negative
1	1	Storage Along Right Side of Auditorium	W4	CMU	White	None	0	0.03	Negative
1	1	Storage Along Right Side of Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Along Right Side of Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Storage	W2	CMU	White	Flaking	15	0.03	Negative
1	1	Music Storage	W3	CMU	White	Flaking	15	0.04	Negative
1	1	Music Storage	W4	CMU	White	Flaking	15	0.01	Negative
1	1	Music Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Costume Storage	W1	CMU	Grey	None	0	0.01	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Costume Storage	W2	CMU	Grey	None	0	0.01	Negative
1	1	Costume Storage	W3	CMU	Grey	None	0	0.01	Negative
1	1	Costume Storage	W4	CMU	Grey	None	0	0.01	Negative
1	1	Costume Storage	Ceiling	Concrete	White	Cracking	10	0	Negative
1	1	Costume Storage	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Costume Storage	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Classroom 156 Restroom	W1	CMU	White	None	0	0.01	Negative
1	1	Classroom 156 Restroom	W2	CMU	White	None	0	0.01	Negative
1	1	Classroom 156 Restroom	W3	CMU	White	None	0	0.01	Negative
1	1	Classroom 156 Restroom	W4	CMU	White	None	0	0.01	Negative
1	1	Classroom 156 Restroom	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	Classroom 156 Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 156 Restroom	Door Frame	Metal	White	Chipping	1	0	Negative
1	1	Classroom 158 Kitchen Restroom	W1	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen Restroom	W2	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen Restroom	W3	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen Restroom	W4	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen Restroom	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen Restroom	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 158 Kitchen Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	Classroom 158 Kitchen	W1	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen	W2	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen	W3	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen	W4	CMU	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen	Ceiling	Concrete	White	None	0	0.01	Negative
1	1	Classroom 158 Kitchen	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Classroom 158 Kitchen	Door Frame	Metal	White	Chipping	1	0	Negative	
1	1	Kitchen Classroom 156	W1	CMU	White	None	0	0.01	Negative	
1	1	Kitchen Classroom 156	W2	CMU	White	None	0	0.01	Negative	
1	1	Kitchen Classroom 156	W3	CMU	White	None	0	0.01	Negative	
1	1	Kitchen Classroom 156	W4	CMU	White	None	0	0.01	Negative	
1	1	Kitchen Classroom 156	Ceiling	Concrete	White	None	0	0.01	Negative	
1	1	Kitchen Classroom 156	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 156	W1	CMU	White	None	0	0.01	Negative	
1	1	Classroom 156	W2	CMU	White	None	0	0.01	Negative	
1	1	Classroom 156	W3	CMU	White	None	0	0.01	Negative	
1	1	Classroom 156	W4	CMU	White	None	0	0.01	Negative	
1	1	Classroom 156	Ceiling	Concrete	White	None	0	0.01	Negative	
1	1	Classroom 156	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 156	Radiator	Metal	White	None	0	0.01	Negative	
1	1	Classroom 156	Door Frame	Metal	Blue	Chipping	1	0	Negative	
1	1	Storage Room in Back of Auditorium D	W1	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium D	W2	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium D	W3	CMU	Green	None	0	0.07	Negative	
1	1	Storage Room in Back of Auditorium D	W4	CMU	Green	None	0	0.03	Negative	
1	1	Storage Room in Back of Auditorium D	Ceiling	Metal	White	None	0	1.3	Positive	
1	1	Storage Room in Back of Auditorium D	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage Room in Back of Auditorium C	W1	CMU	Green	None	0	0.03	Negative	
1	1	Storage Room in Back of Auditorium C	W2	CMU	Green	None	0	0.01	Negative	
1	1	Storage Room in Back of Auditorium C	W3	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium C	W4	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium C	Ceiling	Metal	White	None	0	2.2	Positive	

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E</b> <b>l</b> <b>e</b> <b>m</b> <b>e</b> <b>n</b> <b>t</b>	<b>F</b> <b>l</b> <b>o</b> <b>o</b> <b>r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Storage Room in Back of Auditorium C	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage Room in Back of Auditorium C	Duct	Metal	Silver	None	0	0	Negative	
1	1	Auditorium	W1	CMU	White	None	0	0.01	Negative	
1	1	Auditorium	W2	CMU	White	None	0	0.03	Negative	
1	1	Auditorium	W3	CMU	White	None	0	0.02	Negative	
1	1	Auditorium	W4	CMU	White	None	0	0	Negative	
1	1	Auditorium	Ceiling	Plaster	White	None	0	0	Negative	
1	1	Auditorium	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Auditorium	Door Frame 1	Metal	Blue	Chipping	1	0.03	Negative	
1	1	Auditorium	Door Frame 2	Metal	Blue	Chipping	1	0.07	Negative	
1	1	Auditorium	Door Frame 3	Metal	Blue	Chipping	1	0.02	Negative	
1	1	Auditorium	Door Frame 4	Metal	Blue	Chipping	1	0	Negative	
1	1	Auditorium	Door Frame 5	Metal	Blue	Chipping	1	0.04	Negative	
1	1	Auditorium	Door Frame 6	Metal	Blue	Chipping	1	0.05	Negative	
1	1	Auditorium	Door Frame 7	Metal	Blue	Chipping	1	0	Negative	
1	1	Auditorium	Door Frame 8	Metal	Blue	Chipping	1	0.01	Negative	
1	1	Auditorium	Door Frame 9	Metal	Blue	Chipping	1	0	Negative	
1	1	Auditorium	Door Frame 10	Metal	Blue	Chipping	1	0.02	Negative	
1	1	Stage	W2	CMU	White	None	0	0	Negative	
1	1	Stage	W3	CMU	White	None	0	0	Negative	
1	1	Stage	W4	CMU	White	None	0	0	Negative	
1	1	Stage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stage	Ceiling	Concrete	White	None	0	0.04	Negative	
1	1	Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	1	Stage	Door Frame 1	Metal	Blue	None	0	0.06	Negative	
1	1	Stage	Door Frame 2	Metal	Blue	None	0	0.01	Negative	



		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report							
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)							
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116							
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	1	Storage Room in Back of Auditorium B	W1	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium B	W2	CMU	Green	None	0	0.01	Negative	
1	1	Storage Room in Back of Auditorium B	W3	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium B	W4	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium B	Ceiling	Metal	White	None	0	1.4	Positive	
1	1	Storage Room in Back of Auditorium B	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage Room in Back of Auditorium B	Duct	Metal	Silver	None	0	0.02	Negative	
1	1	Storage Room in Back of Auditorium A	W1	CMU	Green	None	0	0.01	Negative	
1	1	Storage Room in Back of Auditorium A	W2	CMU	Green	None	0	0	Negative	
1	1	Storage Room in Back of Auditorium A	W3	CMU	Green	None	0	0.02	Negative	
1	1	Storage Room in Back of Auditorium A	W4	CMU	Green	None	0	0.04	Negative	
1	1	Storage Room in Back of Auditorium A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
1	1	Storage Room in Back of Auditorium A	Floor	12x12 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Ticket Room	W1	CMU	Yellow	None	0	0.02	Negative	
1	1	Ticket Room	W2	CMU	Yellow	None	0	0.01	Negative	
1	1	Ticket Room	W3	CMU	Yellow	None	0	0	Negative	
1	1	Ticket Room	W4	CMU	Yellow	None	0	0.07	Negative	
1	1	Ticket Room	Ceiling	Concrete	White	None	0	0.03	Negative	
1	1	Ticket Room	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Ticket Room	Door Frame	Metal	Blue	Chipping	1	0.09	Negative	
1	1	Womens Faculty Restroom	W1	CMU	White	Flaking	1	0.03	Negative	
1	1	Womens Faculty Restroom	W2	CMU	White	Flaking	1	0.08	Negative	
1	1	Womens Faculty Restroom	W3	CMU	White	Flaking	1	0.01	Negative	
1	1	Womens Faculty Restroom	W4	CMU	White	Flaking	1	0.1	Negative	
1	1	Womens Faculty Restroom	Ceiling	Concrete	White	Flaking	2	0.07	Negative	
1	1	Womens Faculty Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Womens Faculty Restroom	Radiator	Metal	White	Chipping	2	0.07	Negative
1	1	Womens Faculty Restroom	Door Frame	Metal	Blue	None	0	0.01	Negative
1	1	Mens Faculty Restroom	W1	CMU	White	Flaking	1	0.01	Negative
1	1	Mens Faculty Restroom	W2	CMU	White	Flaking	1	0.02	Negative
1	1	Mens Faculty Restroom	W3	CMU	White	Flaking	1	0.04	Negative
1	1	Mens Faculty Restroom	W4	CMU	White	Flaking	1	0	Negative
1	1	Mens Faculty Restroom	Ceiling	Concrete	White	Flaking	2	0.05	Negative
1	1	Mens Faculty Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Mens Faculty Restroom	Radiator	Metal	White	Chipping	2	0.09	Negative
1	1	Mens Faculty Restroom	Door Frame	Metal	Blue	None	0	0.01	Negative
1	1	Health Suite #4	W1	CMU	Tan	None	0	0	Negative
1	1	Health Suite #4	W2	CMU	Tan	None	0	0	Negative
1	1	Health Suite #4	W3	CMU	Tan	None	0	0	Negative
1	1	Health Suite #4	W4	CMU	Tan	None	0	0	Negative
1	1	Health Suite #4	W1	CMU	White	None	0	0	Negative
1	1	Health Suite #4	W2	CMU	White	None	0	0	Negative
1	1	Health Suite #4	W3	CMU	White	None	0	0	Negative
1	1	Health Suite #4	W4	CMU	White	None	0	0	Negative
1	1	Health Suite #4	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #4	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #4	Radiator	Metal	Blue	None	0	0	Negative
1	1	Health Suite #4	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
1	1	Health Suite #3	W1	CMU	Pink	None	0	0	Negative
1	1	Health Suite #3	W2	CMU	Pink	None	0	0	Negative
1	1	Health Suite #3	W3	CMU	Pink	None	0	0	Negative
1	1	Health Suite #3	W4	CMU	Pink	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Health Suite #3	W1	CMU	White	None	0	0	Negative
1	1	Health Suite #3	W2	CMU	White	None	0	0	Negative
1	1	Health Suite #3	W3	CMU	White	None	0	0	Negative
1	1	Health Suite #3	W4	CMU	White	None	0	0	Negative
1	1	Health Suite #3	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #3	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #3	Radiator	Metal	Blue	None	0	0	Negative
1	1	Health Suite #3	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
1	1	Health Suite #2	W1	CMU	Tan	None	0	0	Negative
1	1	Health Suite #2	W2	CMU	Tan	None	0	0	Negative
1	1	Health Suite #2	W3	CMU	Tan	None	0	0	Negative
1	1	Health Suite #2	W4	CMU	Tan	None	0	0	Negative
1	1	Health Suite #2	W1	CMU	White	None	0	0	Negative
1	1	Health Suite #2	W2	CMU	White	None	0	0	Negative
1	1	Health Suite #2	W3	CMU	White	None	0	0	Negative
1	1	Health Suite #2	W4	CMU	White	None	0	0	Negative
1	1	Health Suite #2	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #2	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #2	Radiator	Metal	Blue	None	0	0	Negative
1	1	Health Suite #2	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
1	1	Health Suite #1	W1	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W2	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W3	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W4	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W1	CMU	White	None	0	0	Negative
1	1	Health Suite #1	W2	CMU	White	None	0	0	Negative

		Dates: 9/12/23-10/6/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	George Washington High School (9-12)						
		Inspection Company: Viva EHS	10175 Bustleton Ave, Philadelphia PA 19116						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Health Suite #1	W3	CMU	White	None	0	0	Negative
1	1	Health Suite #1	W4	CMU	White	None	0	0	Negative
1	1	Health Suite #1	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #1	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #1	Radiator	Metal	Blue	None	0	0	Negative
1	1	Health Suite #1	Door Frame	Metal	Blue	Chipping	1	0.03	Negative
1	1	Teacher's Lounge	W1	CMU	Tan	None	0	0.02	Negative
1	1	Teacher's Lounge	W2	CMU	Tan	None	0	0	Negative
1	1	Teacher's Lounge	W3	CMU	Tan	None	0	0	Negative
1	1	Teacher's Lounge	W3	Concrete	Tan	None	0	0.03	Negative
1	1	Teacher's Lounge	W4	CMU	Tan	None	0	0	Negative
1	1	Teacher's Lounge	Ceiling	Concrete	White	None	0	0	Negative
1	1	Teacher's Lounge	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Lounge	Radiator	Metal	White	None	0	0	Negative
1	1	Teacher's Lounge	Door Frame	Metal	Blue	Chipping	1	0.08	Negative
1	1	Health Suite #1	W1	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W2	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W3	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W4	CMU	Tan	None	0	0	Negative
1	1	Health Suite #1	W1	CMU	White	None	0	0	Negative
1	1	Health Suite #1	W2	CMU	White	None	0	0	Negative
1	1	Health Suite #1	W3	CMU	White	None	0	0	Negative
1	1	Health Suite #1	W4	CMU	White	None	0	0	Negative
1	1	Health Suite #1	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #1	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A
1	1	Health Suite #1	Radiator	Metal	Blue	None	0	0	Negative

		Dates: 9/12/23-10/6/23	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Erik Swanson #006917	<b>George Washington High School (9-12)</b>							
		Inspection Company: Viva EHS	<b>10175 Bustleton Ave, Philadelphia PA 19116</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	1	Health Suite #1	Door Frame	Metal	Blue	Chipping	1	0.03	Negative	
1	1	Classroom 100	W1	CMU	Tan	None	0	0	Negative	
1	1	Classroom 100	W2	CMU	Tan	None	0	0.06	Negative	
1	1	Classroom 100	W3	CMU	Tan	None	0	0	Negative	
1	1	Classroom 100	W3	Concrete	Tan	None	0	0	Negative	
1	1	Classroom 100	W4	CMU	Tan	None	0	0.01	Negative	
1	1	Classroom 100	Ceiling	Concrete	White	None	0	0	Negative	
1	1	Classroom 100	Floor	9x9 VAT	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 100	Radiator	Metal	White	None	0	0	Negative	
1	1	Classroom 100	Door Frame	Metal	Blue	Chipping	1	0.03	Negative	

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.