

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Athletic Office 107B	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Athletic Office 107B	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Athletic Office 107B	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Athletic Office 107B	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Athletic Office 107B	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Athletic Office 107B	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Auditorium Balcony	W1	Plaster	White	None	0	32.1	Positive
1	1	Auditorium Balcony	W2	Plaster	White	None	0	1.1	Positive
1	1	Auditorium Balcony	W4	Plaster	White	None	0	12.6	Positive
1	1	Auditorium Balcony	Door Frame 1	Wood	Pink	None	0	32.8	Positive
1	1	Auditorium Balcony	Door Frame 2	Wood	Pink	None	0	38	Positive
1	1	Auditorium Balcony	Door Frame 3	Wood	Pink	None	0	33.5	Positive
1	1	Auditorium Balcony	Door Frame 4	Wood	Pink	None	0	31.9	Positive
1	1	Auditorium Balcony	Door Frame 5	Wood	Pink	None	0	36.4	Positive
1	1	Auditorium Balcony	Baseboard	Wood	Pink	None	0	29.5	Positive
1	1	Auditorium Balcony	Ceiling	Plaster	White	None	0	32.7	Positive
1	1	Auditorium Balcony	Floor	Wood	Unpainted	None	0	N/A	N/A
1	1	Book closet adjacent Nurse's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Book closet adjacent Nurse's Office	W1	Plaster	White	None	0	6.9	Positive
1	1	Book closet adjacent Nurse's Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Book closet adjacent Nurse's Office	W2	Plaster	White	None	0	8.1	Positive
1	1	Book closet adjacent Nurse's Office	W3	Plaster	White	None	0	17.3	Positive
1	1	Book closet adjacent Nurse's Office	W4	Plaster	White	None	0	25	Positive
1	1	Book closet adjacent Nurse's Office	Door Frame	Wood	Brown	None	0	0.01	Negative
1	1	Book closet adjacent Nurse's Office	Baseboard	Wood	Brown	None	0	0.01	Negative
1	1	Book closet adjacent Nurse's Office	Door	Wood	Brown	None	0	0.02	Negative
1	1	Boy's Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Old Boiler Room	Column	Concrete	Grey	Flaking	10	2.9	Positive
1	B	Old Boiler Room	Door	Metal	White	Flaking	5	1.9	Positive
1	1	Boy's Restroom	W2	Plaster	White	None	0	1.4	Positive
1	1	Boy's Restroom	W3	CMU	Light Blue	None	0	1.6	Positive
1	1	Boy's Restroom	W4	Plaster	White	None	0	29.1	Positive
1	1	Boy's Restroom	W4	Brick	White	None	0	4.4	Positive
1	1	Boy's Restroom	Pipe 1	Metal	White	None	0	5.4	Positive
1	1	Boy's Restroom	Pipe 2	Metal	Blue	None	0	8.4	Positive
1	1	Boy's Restroom	Pipe 2	Metal	White	None	0	10.1	Positive
1	1	Boy's Restroom	Pipe 3	Metal	Blue	None	0	0.2	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Boy's Restroom	Pipe 3	Metal	White	None	0	0.21	Negative
1	1	Boy's Restroom	Pipe 4	Metal	Blue	None	0	0.02	Negative
1	1	Boy's Restroom	Pipe 4	Metal	White	None	0	0.01	Negative
1	1	Boy's Restroom	Pipe 5	Metal	Blue	None	0	0.06	Negative
1	1	Boy's Restroom	Pipe 5	Metal	White	None	0	0.21	Negative
1	B	Old Boiler Room	Door	Wood	White	Alligatoring	5	20.9	Positive
1	1	Boy's Restroom	Pipe 6	Metal	White	None	0	0.27	Negative
1	1	Boy's Restroom	Pipe 7	Metal	White	None	0	0	Negative
1	1	Boy's Restroom	Pipe 8	Metal	White	None	0	0	Negative
1	1	Boy's Restroom	Pipe 9	Metal	White	None	0	0	Negative
1	1	Boy's Restroom	Floor	Concrete	Brown	None	0	0.08	Negative
1	1	Boy's Restroom	Baseboard	Concrete	Brown	None	0	7.6	Positive
1	1	Boy's Restroom	Door Frame	Wood	White	None	0	0.17	Negative
1	1	Boy's Restroom	Pipe 6	Metal	Blue	Cracking	2	0.5	Negative
1	B	Old Boiler Room	Door Frame	Metal	White	Flaking	5	0.9	Positive
1	1	Boy's Restroom	W1	Brick	Blue	None	0	0.02	Negative
1	1	Boy's Restroom	W2	CMU	Blue	None	0	0.02	Negative
1	1	Boy's Restroom	W2	Brick	Blue	None	0	0.03	Negative
1	1	Boy's Restroom	W1	Brick	White	None	0	0.04	Negative
1	1	Boy's Restroom	W2	CMU	White	None	0	0.16	Negative
1	B	Old Boiler Room	Door Frame	Wood	White	Flaking	10	32.5	Positive
1	B	Old Boiler Room	Door Frame	Wood	White	Chipping	5	3.6	Positive
1	1	Classroom 100	W1	Plaster	Green	None	0	31.7	Positive
1	B	Old Boiler Room	Hand Rail	Metal	White	Flaking	20	3	Positive
1	B	Old Boiler Room	Incinerator	Metal	Grey	Cracking	50	9.5	Positive
1	1	Classroom 100	W4	Plaster	Green	None	0	42.8	Positive
1	1	Classroom 100	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 100	W1	Plaster	White	None	0	48.2	Positive
1	1	Classroom 100	W2	Plaster	White	None	0	46.5	Positive
1	1	Classroom 100	W3	Plaster	White	None	0	42.7	Positive
1	1	Classroom 100	W4	Plaster	White	None	0	41.7	Positive
1	1	Classroom 100	Door Frame	Wood	Brown	None	0	0.16	Negative
1	1	Classroom 100	Window Frame 2	Wood	Brown	None	0	0.3	Negative
1	1	Classroom 100	Window Sill 2	Wood	Brown	None	0	0.13	Negative
1	1	Classroom 100	Window Frame 3	Wood	Brown	None	0	0.15	Negative
1	1	Classroom 100	Window Sill 3	Wood	Brown	None	0	0.3	Negative
1	1	Classroom 100	Window Frame 4	Wood	Brown	None	0	0.08	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130				
				Inspection Company: Viva		Franklin Learning Center				
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	1	Classroom 100	Window Sill 4	Wood	Brown	None	0	0.19	Negative	
1	1	Classroom 100	Window Frame 5	Wood	Brown	None	0	0.24	Negative	
1	1	Classroom 100	Window Sill 5	Wood	Brown	None	0	0.22	Negative	
1	1	Classroom 100	Pipe 1	Metal	Green	None	0	0.28	Negative	
1	1	Classroom 100	Pipe 1	Metal	White	None	0	0.24	Negative	
1	B	Old Boiler Room	Stringer	Metal	White	Flaking	10	5.5	Positive	
1	1	Classroom 100	Floor	Wood	Unpainted	None	0	N/A	N/A	
1	1	Classroom 100	Baseboard	Wood	Brown	None	0	0.16	Negative	
1	1	Classroom 100	Door	Wood	Brown	None	0	0.25	Negative	
1	1	Classroom 100	Window Frame 1	No Access	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 100	Window Sill 1	No Access	N/A	N/A	N/A	N/A	N/A	
1	1	Classroom 101	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 101	W1	Plaster	Green	None	0	0	Negative	
1	1	Classroom 101	W4	Plaster	Green	None	0	0	Negative	
1	1	Classroom 101	Ceiling	Plaster	White	None	0	>10	Positive	
1	B	Old Boiler Room	W4	Brick	Grey	Chipping	20	14.7	Positive	
1	1	Classroom 101	W1	Plaster	White	None	0	37.2	Positive	
1	B	Electrical Room	Hand Rail	Metal	White	Chipping	20	18.4	Positive	
1	1	Classroom 101	W4	Plaster	White	None	0	37.1	Positive	
1	1	Classroom 101	Window Sill 1	Wood	Brown	None	0	0.06	Negative	
1	1	Classroom 101	Window Frame 1	Wood	Brown	None	0	0.08	Negative	
1	1	Classroom 101	Window Sill 2	Wood	Brown	None	0	0.06	Negative	
1	1	Classroom 101	Window Frame 2	Wood	Brown	None	0	0.3	Negative	
1	1	Classroom 101	Window Sill 3	Wood	Brown	None	0	0.08	Negative	
1	1	Classroom 101	Window Frame 3	Wood	Brown	None	0	0.13	Negative	
1	1	Classroom 101	Door Frame	Wood	Brown	None	0	0.02	Negative	
1	1	Classroom 101	W3	Plaster	Green	None	0	0.04	Negative	
1	1	Classroom 101	Door	Wood	Brown	None	0	0.06	Negative	
1	1	Classroom 101	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	1	Classroom 101	W2	Partition Wall	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 105	Ceiling	Plaster	White	None	0	>10	Positive	
1	B	Electrical Room	Stringer	Metal	White	Chipping	15	22.4	Positive	
1	B	Electrical Room	Supprt Beam	Metal	Grey	Chipping	5	5	Positive	
1	B	Boy's Locker Room	Column 1	Metal	White	Chipping	1	40.3	Positive	
1	1	Classroom 105	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	1	Classroom 105	W2	Plaster	Blue	None	0	45.4	Positive	
1	B	Boy's Locker Room	Column 2	Metal	White	Chipping	1	28.1	Positive	

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	HVAC Room/Gym Storage	W1	Brick	White	Flaking	50	10.6	Positive
1	1	Classroom 105	Door Frame	Metal	Brown	None	0	0.02	Negative
1	1	Classroom 105	Window Sill	Wood	Brown	None	0	1.3	Positive
1	1	Classroom 105	Window Frame	Wood	Brown	None	0	0.02	Negative
1	1	Classroom 105	Door	Metal	Brown	None	0	0.03	Negative
1	1	Classroom 105	Baseboard	Wood	Black	None	0	0.12	Negative
1	B	HVAC Room/Gym Storage	W2	Brick	White	Flaking	20	9	Positive
1	B	HVAC Room/Gym Storage	W3	Brick	White	Flaking	50	0.7	Positive
1	B	HVAC Room/Gym Storage	W4	Brick	White	Flaking	15	11.1	Positive
1	1	Classroom 120	W1	Plaster	Tan	None	0	33.1	Positive
1	1	Classroom 120	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 120	W2	Plaster	Tan	None	0	37.8	Positive
1	1	Classroom 120	W3	Plaster	Tan	None	0	37.5	Positive
1	1	Classroom 120	W4	Plaster	Tan	None	0	35.4	Positive
1	1	Classroom 120	W1	Plaster	White	None	0	35.9	Positive
1	1	Classroom 120	W2	Plaster	White	None	0	32.5	Positive
1	1	Classroom 120	W3	Plaster	White	None	0	41.8	Positive
1	1	Classroom 120	W4	Plaster	White	None	0	37.2	Positive
1	1	Classroom 120	Door Frame	Metal	Brown	None	0	0.04	Negative
1	1	Classroom 120	Window Sill	Wood	Brown	None	0	0.4	Negative
1	1	Classroom 120	Pipe 1	Metal	Tan	None	0	0.25	Negative
1	1	Classroom 120	Pipe 1	Metal	White	None	0	0.27	Negative
1	1	Classroom 120	Door	Metal	Brown	None	0	0.01	Negative
1	1	Classroom 120	Window Frame	Wood	Brown	None	0	0.02	Negative
1	1	Classroom 120	Baseboard	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 121	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 121	W1	Plaster	Blue	None	0	32.9	Positive
1	1	Classroom 121	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 121	W4	Plaster	Blue	None	0	35.4	Positive
1	1	Classroom 121	W1	Plaster	White	None	0	43.7	Positive
1	1	Classroom 121	W2	Plaster	White	None	0	47.9	Positive
1	1	Classroom 121	W3	Plaster	White	None	0	46.1	Positive
1	1	Classroom 121	W4	Plaster	White	None	0	45.4	Positive
1	1	Classroom 121	Door Frame	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 121	Window Sill 1	Wood	Brown	None	0	0.17	Negative
1	1	Classroom 121	Window Frame 1	Wood	Brown	None	0	0.16	Negative
1	1	Classroom 121	Window Sill 2	Wood	Brown	None	0	0.23	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 121	Window Frame 2	Wood	Brown	None	0	0.24	Negative
1	1	Classroom 121	Window Sill 3	Wood	Brown	None	0	0.11	Negative
1	1	Classroom 121	Window Frame 3	Wood	Brown	None	0	0.19	Negative
1	1	Classroom 121	W3	Plaster	Blue	None	0	0.02	Negative
1	1	Classroom 121	Door	Wood	Brown	None	0	0.03	Negative
1	1	Classroom 121	W2	Plaster	Blue	None	0	0.04	Negative
1	1	Classroom 121	Baseboard	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 122	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 122	W1	Plaster	White	None	0	45.8	Positive
1	1	Classroom 122	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 122	W2	Plaster	White	None	0	20.1	Positive
1	1	Classroom 122	W3	Plaster	White	None	0	52.4	Positive
1	1	Classroom 122	W4	Plaster	White	None	0	45.9	Positive
1	1	Classroom 122	W1	Plaster	Tan	None	0	39	Positive
1	1	Classroom 122	W2	Plaster	Tan	None	0	40.8	Positive
1	1	Classroom 122	Window Sill 1	Wood	Brown	None	0	0.17	Negative
1	1	Classroom 122	Window Frame 1	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 122	Window Sill 2	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 122	Window Frame 2	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 122	Window Sill 3	Wood	Brown	None	0	0.24	Negative
1	1	Classroom 122	Window Frame 3	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 122	Door Frame 1	Wood	Brown	None	0	0.03	Negative
1	1	Classroom 122	Door 1	Wood	Brown	None	0	0.01	Negative
1	1	Classroom 122	Door Frame 2	Wood	Brown	None	0	0.04	Negative
1	1	Classroom 122	Door 2	Wood	Brown	None	0	0.04	Negative
1	1	Classroom 122	W3	Plaster	Tan	None	0	0.02	Negative
1	1	Classroom 122	Baseboard	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 122	W4	Plaster	Tan	None	0	0.4	Negative
1	1	Classroom 123	W1	Plaster	Blue	None	0	0	Negative
1	1	Classroom 123	W2	Plaster	Blue	None	0	0	Negative
1	1	Classroom 123	W3	Plaster	Blue	None	0	0	Negative
1	1	Classroom 123	W4	Plaster	Blue	None	0	0	Negative
1	1	Classroom 123	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 123	W1	Plaster	White	None	0	48.1	Positive
1	1	Classroom 123	W2	Plaster	White	None	0	10.3	Positive
1	1	Classroom 123	W3	Plaster	White	None	0	50.4	Positive
1	1	Classroom 123	W4	Plaster	White	None	0	43.7	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 123	Window Sill 1	Wood	Brown	None	0	0.09	Negative
1	1	Classroom 123	Window Frame 1	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 123	Window Sill 2	Wood	Brown	None	0	0.14	Negative
1	1	Classroom 123	Window Frame 2	Wood	Brown	None	0	0.17	Negative
1	1	Classroom 123	Window Sill 3	Wood	Brown	None	0	0.24	Negative
1	1	Classroom 123	Window Frame 3	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 123	Window Sill 4	Wood	Brown	None	0	0.11	Negative
1	1	Classroom 123	Window Frame 4	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 123	Door Frame	Wood	Brown	None	0	0.03	Negative
1	1	Classroom 123	Pipe 1	Metal	Blue	None	0	38.2	Positive
1	1	Classroom 123	Pipe 2	Metal	Blue	None	0	27.6	Positive
1	1	Classroom 123	Pipe 3	Metal	Blue	None	0	0	Negative
1	1	Classroom 123	Pipe 1	Metal	White	None	0	49.9	Positive
1	1	Classroom 123	Pipe 2	Metal	White	None	0	43.3	Positive
1	1	Classroom 123	Pipe 3	Metal	White	None	0	0.2	Negative
1	1	Classroom 123	Pipe 4	Metal	Blue	None	0	1.7	Positive
1	1	Classroom 123	Pipe 4	Metal	White	None	0	3	Positive
1	1	Classroom 123	Door	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 123	Baseboard	Wood	Brown	None	0	0.09	Negative
1	1	Classroom 123	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 129	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Classroom 129	W1	Plaster	White	None	0	34.2	Positive
1	1	Classroom 129	W2	Plaster	White	None	0	31.7	Positive
1	1	Classroom 129	W4	Plaster	White	None	0	30.1	Positive
1	B	Kitchen Office	Baseboard	Concrete	Grey	Chipping	20	5.4	Positive
1	B	Kitchen Office	W2	Brick	Yellow	Cracking	3	12.6	Positive
1	B	Kitchen Office	W4	Brick	Yellow	Alligatoring	5	15.1	Positive
1	1	Classroom 129	Door Frame	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 129	Window Frame 1	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 129	Window Frame 2	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 129	W3	Plaster	Green	None	0	0.04	Negative
1	1	Classroom 129	W3	Plaster	White	None	0	0.07	Negative
1	1	Classroom 129	Door	Wood	Brown	None	0	0.09	Negative
1	1	Classroom 129	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 129	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	Classroom 131	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 131	Pipe 1	Metal	Blue	Chipping	1	0.4	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 131	Pipe 2	Metal	White	Chipping	1	0.3	Negative
1	1	Classroom 131	W1	Plaster	White	None	0	46.9	Positive
1	1	Classroom 131	W2	Plaster	White	None	0	53.6	Positive
1	1	Classroom 131	W3	Plaster	White	None	0	46.1	Positive
1	1	Classroom 131	W4	Plaster	White	None	0	51.2	Positive
1	1	Classroom 131	W2	Plaster	Blue	None	0	32.9	Positive
1	1	Classroom 131	Window Frame 1	Wood	Brown	None	0	0.14	Negative
1	1	Classroom 131	Window Sill 1	Wood	Brown	None	0	0.24	Negative
1	1	Classroom 131	Window Frame 2	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 131	Window Sill 2	Wood	Brown	None	0	0.22	Negative
1	1	Classroom 131	Door Frame	Wood	Brown	None	0	0.03	Negative
1	1	Classroom 131	Pipe 1	Metal	White	None	0	0.3	Negative
1	1	Classroom 131	Pipe 2	Metal	Blue	None	0	19.3	Positive
1	1	Classroom 131	Pipe 3	Metal	White	None	0	0.5	Negative
1	1	Classroom 131	Door	Wood	Brown	None	0	0.02	Negative
1	1	Classroom 131	Baseboard	Cement	Brown	None	0	0.08	Negative
1	1	Classroom 131	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 131	W3	Plaster	Blue	None	0	0.19	Negative
1	1	Classroom 131	W1	Plaster	Blue	None	0	0.3	Negative
1	1	Classroom 132	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 132	W1	Plaster	White	None	0	30	Positive
1	1	Classroom 132	W2	Plaster	White	None	0	31.8	Positive
1	1	Classroom 132	W3	Plaster	White	None	0	40.9	Positive
1	1	Classroom 132	W4	Plaster	White	None	0	49.4	Positive
1	1	Classroom 132	W1	Plaster	Tan	None	0	47.9	Positive
1	1	Classroom 132	W2	Plaster	Tan	None	0	31.8	Positive
1	1	Classroom 132	W3	Plaster	Tan	None	0	34.8	Positive
1	1	Classroom 132	W4	Plaster	Tan	None	0	36	Positive
1	1	Classroom 132	Pipe	Metal	White	None	0	55.7	Positive
1	1	Classroom 132	Window Sill 1	Wood	Brown	None	0	0.05	Negative
1	1	Classroom 132	Window Frame 1	Wood	Brown	None	0	0.18	Negative
1	1	Classroom 132	Window Sill 2	Wood	Brown	None	0	0.16	Negative
1	1	Classroom 132	Window Frame 2	Wood	Brown	None	0	0.12	Negative
1	1	Classroom 132	Window Sill 3	Wood	Brown	None	0	0.12	Negative
1	1	Classroom 132	Window Frame 3	Wood	Brown	None	0	0.11	Negative
1	1	Classroom 132	Window Sill 4	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 132	Window Frame 4	Wood	Brown	None	0	0.29	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 132	Door Frame	Wood	Brown	None	0	0	Negative
1	1	Classroom 132	Baseboard	Wood	Brown	None	0	0.06	Negative
1	1	Classroom 132	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 133	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Cafeteria	Baseboard	Concrete	Brown	Chipping	10	3.5	Positive
1	1	Classroom 133	W1	Plaster	Tan	None	0	32.6	Positive
1	1	Classroom 133	W2	Plaster	Tan	None	0	38.2	Positive
1	B	Cafeteria	Column 1	Concrete	Blue	Flaking	2	33.4	Positive
1	1	Classroom 133	W4	Plaster	Tan	None	0	36.9	Positive
1	1	Classroom 133	W1	Plaster	White	None	0	41.4	Positive
1	1	Classroom 133	W2	Plaster	White	None	0	5.9	Positive
1	1	Classroom 133	W3	Plaster	White	None	0	1.4	Positive
1	1	Classroom 133	W4	Plaster	White	None	0	51.9	Positive
1	1	Classroom 133	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	1	Classroom 133	Window Frame 1	Wood	Brown	None	0	0.19	Negative
1	1	Classroom 133	Window Sill 2	Wood	Brown	None	0	0.15	Negative
1	1	Classroom 133	Window Frame 2	Wood	Brown	None	0	0.13	Negative
1	1	Classroom 133	Window Sill 3	Wood	Brown	None	0	0.4	Negative
1	1	Classroom 133	Window Frame 3	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 133	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	1	Classroom 133	Window Frame 4	Wood	Brown	None	0	0.3	Negative
1	1	Classroom 133	Window Sill 5	Wood	Brown	None	0	0.21	Negative
1	1	Classroom 133	Window Frame 5	Wood	Brown	None	0	0.13	Negative
1	1	Classroom 133	Pipe 1	Metal	White	None	0	0.17	Negative
1	1	Classroom 133	Pipe 1	Metal	Tan	None	0	0.11	Negative
1	1	Classroom 133	Pipe 2	Metal	Tan	None	0	0.26	Negative
1	1	Classroom 133	Door 1	Wood	Brown	None	0	0.07	Negative
1	1	Classroom 133	Door Frame 1	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 133	Door 2	Wood	Brown	None	0	0.04	Negative
1	1	Classroom 133	Door Frame 2	Wood	Brown	None	0	0.08	Negative
1	1	Classroom 133	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 133	Baseboard	Wood	Brown	None	0	0.14	Negative
1	1	Closet adjacent Nurse's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Closet adjacent Nurse's Office	Door	Wood	Brown	None	0	0.02	Negative
1	1	Closet adjacent Nurse's Office	Baseboard	Wood	Brown	None	0	0.02	Negative
1	B	Cafeteria	Column 2	Concrete	Blue	Flaking	3	36.1	Positive
1	1	Closet adjacent Nurse's Office	W2	Plaster	Green	None	0	28	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Closet adjacent Nurse's Office	W3	Plaster	Green	None	0	9	Positive
1	1	Closet adjacent Nurse's Office	W4	Plaster	Green	None	0	22.4	Positive
1	1	Closet adjacent Nurse's Office	Door Frame	Wood	Brown	None	0	0.03	Negative
1	1	Closet adjacent Nurse's Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Connector Hall to Balcony from Hallway H11	Door Frame 1	Wood	Brown	Chipping	1	0.12	Negative
1	B	Cafeteria	Column 3	Concrete	Blue	Chipping	1	31.9	Positive
1	1	Connector Hall to Balcony from Hallway H11	W2	Wood	White	None	0	37.5	Positive
1	1	Connector Hall to Balcony from Hallway H11	W4	Wood	White	None	0	41.3	Positive
1	1	Connector Hall to Balcony from Hallway H11	Window Frame 1	Wood	Brown	None	0	0	Negative
1	1	Connector Hall to Balcony from Hallway H11	Window Sill 1	Wood	Brown	None	0	31.2	Positive
1	1	Connector Hall to Balcony from Hallway H11	Window Frame 2	Wood	Brown	None	0	0.03	Negative
1	1	Connector Hall to Balcony from Hallway H11	Window Sill 2	Wood	Brown	None	0	30.8	Positive
1	1	Connector Hall to Balcony from Hallway H11	Ceiling	Metal	White	None	0	5.3	Positive
1	1	Connector Hall to Balcony from Hallway H11	W3	Plaster	White	Cracking	2	0.06	Negative
1	1	Connector Hall to Balcony from Hallway H11	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Connector Hall to Balcony from Hallway H13	W1	Plaster	White	None	0	0.01	Negative
1	1	Connector Hall to Balcony from Hallway H13	W3	Plaster	White	None	0	0.01	Negative
1	1	Connector Hall to Balcony from Hallway H13	W2	Wood	White	None	0	37.4	Positive
1	1	Connector Hall to Balcony from Hallway H13	W4	Wood	White	None	0	29.7	Positive
1	1	Connector Hall to Balcony from Hallway H13	Ceiling	Metal	White	None	0	4.8	Positive
1	1	Connector Hall to Balcony from Hallway H13	Window Frame 1	Wood	Brown	None	0	0.03	Negative
1	1	Connector Hall to Balcony from Hallway H13	Window Sill 1	Wood	White	None	0	28.2	Positive
1	1	Connector Hall to Balcony from Hallway H13	Window Frame 2	Wood	Brown	None	0	0.01	Negative
1	1	Connector Hall to Balcony from Hallway H13	Window Sill 2	Wood	White	None	0	35.3	Positive
1	1	Connector Hall to Balcony from Hallway H13	Door Frame	Wood	Brown	None	0	0.08	Negative
1	1	Connector Hall to Balcony from Hallway H13	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet across from Multipurpose Room 102	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Cafeteria	Column 4	Concrete	Blue	Chipping	2	32.5	Positive
1	1	Custodial Closet across from Multipurpose Room 102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Cafeteria	Pipe	Metal	Blue	Chipping	2	1.9	Positive
1	B	Cafeteria	Radiator	Metal	Brown	Flaking	5	1.5	Positive
1	B	Cafeteria	Radiator	Metal	Brown	Flaking	5	7.3	Positive
1	1	Fire Tower adj 120	Ceiling	Concrete	White	Flaking	4	0.4	Negative
1	1	Fire Tower adj 120	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adj 120	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adj 120	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Fire Tower adj 120	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adj 120	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Classroom 100	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Cafeteria	W1	Brick	Blue	Flaking	10	23.5	Positive
1	1	Fire Tower adjacent to Classroom 100	W1	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Classroom 100	W2	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Classroom 100	W3	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Classroom 100	W4	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Fire Tower adjacent to Classroom 100	Door	Metal	Brown	Flaking	5	0.1	Negative
1	B	Cafeteria	W3	Brick	White	Chipping	1	18.8	Positive
1	1	Girl's Restroom	Door	Wood	Brown	None	0	0	Negative
1	1	Girl's Restroom	Floor	Concrete	Brown	None	0	0.3	Negative
1	1	Girl's Restroom	Pipe 1	Metal	Blue	None	0	0	Negative
1	1	Girl's Restroom	Pipe 2	Metal	Blue	None	0	0	Negative
1	1	Girl's Restroom	Pipe 3	Metal	Blue	None	0	0	Negative
1	1	Girl's Restroom	Baseboard	Concrete	Brown	None	0	7.6	Positive
1	1	Girl's Restroom	Door Frame	Wood	Brown	None	0	0	Negative
1	1	Girl's Restroom	W3	CMU	Blue	None	0	0.1	Negative
1	1	Girl's Restroom	W1	Brick	Blue	None	0	0.2	Negative
1	1	Girl's Restroom	W3	Brick	Blue	None	0	0.3	Negative
1	1	Girl's Restroom	W4	Brick	Blue	None	0	0.3	Negative
1	1	Girl's Restroom	W2	Plaster	Blue	None	0	3.8	Positive
1	1	Girl's Restroom	W4	Plaster	Blue	None	0	4	Positive
1	1	Girl's Restroom	W1	Plaster	Blue	None	0	4.1	Positive
1	1	Girl's Restroom	W2	Brick	Blue	None	0	4.2	Positive
1	1	Girl's Restroom	W3	Plaster	Blue	None	0	6.2	Positive
1	1	Hallway from Classrooms 100 to 105	W2	Plaster	Purple	None	0	0	Negative
1	1	Hallway from Classrooms 100 to 105	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 100 to 105	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 100 to 105	Window Frame 1	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 100 to 105	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 100 to 105	Window Frame 2	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 100 to 105	W4	Plaster	Purple	None	0	4.9	Positive
1	1	Hallway from Classrooms 100 to 105	W2	Plaster	White	None	0	5	Positive
1	1	Hallway from Classrooms 100 to 105	W4	Plaster	White	None	0	7.4	Positive
1	1	Hallway from Classrooms 100 to 105	Radiator	Metal	Grey	None	0	8.2	Positive
1	1	Hallway from Classrooms 100 to 105	Baseboard	Concrete	Brown	None	0	9.7	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Hallway from Classrooms 100 to 105	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 100 to 125	W4	CMU	Purple	None	0	0	Negative
1	1	Hallway from Classrooms 100 to 125	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 100 to 125	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 100 to 125	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 100 to 125	Window Frame 1	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 100 to 125	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 100 to 125	Window Frame 2	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 100 to 125	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	1	Hallway from Classrooms 100 to 125	Radiator 1	Metal	Grey	None	0	9.5	Positive
1	1	Hallway from Classrooms 100 to 125	Radiator 2	Metal	Grey	None	0	4.4	Positive
1	1	Hallway from Classrooms 100 to 125	Baseboard	Concrete	Brown	None	0	6.1	Positive
1	1	Hallway from Classrooms 100 to 125	W1	Plaster	Purple	None	0	>10	Positive
1	1	Hallway from Classrooms 100 to 125	W1	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 100 to 125	W3	Plaster	Purple	None	0	>10	Positive
1	1	Hallway from Classrooms 100 to 125	W3	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 120 to 125	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 120 to 125	W2	Plaster	Purple	None	0	0.1	Negative
1	1	Hallway from Classrooms 120 to 125	Window Sill 1	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 120 to 125	Window Frame 1	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 120 to 125	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 120 to 125	Window Frame 2	Wood	Brown	None	0	0.3	Negative
1	1	Hallway from Classrooms 120 to 125	Window Sill 3	Wood	Brown	None	0	0.1	Negative
1	1	Hallway from Classrooms 120 to 125	Window Frame 3	Wood	Brown	None	0	0.2	Negative
1	1	Hallway from Classrooms 120 to 125	Baseboard	Concrete	Brown	None	0	4.2	Positive
1	1	Hallway from Classrooms 120 to 125	W2	Plaster	White	None	0	6.7	Positive
1	1	Hallway from Classrooms 120 to 125	Radiator	Metal	Grey	None	0	7.6	Positive
1	1	Hallway from Classrooms 120 to 125	W4	Plaster	Purple	None	0	>10	Positive
1	1	Hallway from Classrooms 120 to 125	W4	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 120 to 125	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 131 to 133	Pipe	Metal	Purple	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 133	Pipe	Metal	White	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 133	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Hallway from Classrooms 131 to 133	Baseboard	Concrete	Brown	None	0	4.7	Positive
1	1	Hallway from Classrooms 131 to 133	W4	Plaster	White	None	0	8.1	Positive
1	B	Cafeteria	W3	Brick	Blue	Chipping	2	21.7	Positive
1	B	Kitchen	Baseboard	Concrete	Grey	Flaking	20	7.7	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Hallway from Classrooms 131 to 133	W4	Plaster	Purple	None	0	>10	Positive
1	1	Hallway from Classrooms 131 to 133	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	IT MDF Room 106	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	IT MDF Room 106	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	IT MDF Room 106	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	IT MDF Room 106	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	IT MDF Room 106	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	IT MDF Room 106	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Main Office	Radiator	Metal	Brown	None	0	0	Negative
1	1	Main Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Main Office	Baseboard	Wood	Brown	None	0	0.06	Negative
1	1	Main Office	Door	Wood	Brown	None	0	0.08	Negative
1	1	Main Office	W1	Plaster	White	None	0	39.5	Positive
1	1	Main Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Office	W2	Plaster	White	None	0	44.8	Positive
1	1	Main Office	W3	Plaster	White	None	0	30.1	Positive
1	1	Main Office	W4	Plaster	White	None	0	30.2	Positive
1	1	Main Office	Door Frame	Wood	Brown	None	0	0	Negative
1	1	Main Office	Window Frame 1	Wood	Brown	None	0	0.12	Negative
1	1	Main Office	Window Frame 2	Wood	Brown	None	0	0.15	Negative
1	B	School Police Office	Pipe	Metal	Yellow	Chipping	1	16.1	Positive
1	1	Main Office	W2	Plaster	Blue	None	0	39.5	Positive
1	B	Building Engineer's Office	W1	Plaster	White	Cracking	20	44.7	Positive
1	B	Building Engineer's Office	W3	Plaster	White	Cracking	30	42.2	Positive
1	1	Main Office	Pipe 1	Metal	White	None	0	18.8	Positive
1	1	Main Office	Pipe 2	Metal	White	None	0	0	Negative
1	B	Building Engineer's Office	W4	Plaster	White	Cracking	50	44.9	Positive
1	1	Multipurpose Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	1	Multipurpose Room	Pipe	Metal	White	Chipping	1	0.14	Negative
1	1	Multipurpose Room	W2	Sheetrock	White	None	0	0	Negative
1	1	Multipurpose Room	W1	Plaster	Green	None	0	0	Negative
1	1	Multipurpose Room	W2	Sheetrock	Green	None	0	0	Negative
1	1	Multipurpose Room	W3	Plaster	Green	None	0	0	Negative
1	1	Multipurpose Room	Baseboard	Wood	Brown	None	0	0.08	Negative
1	1	Multipurpose Room	W1	Plaster	White	None	0	38.1	Positive
1	1	Multipurpose Room	W3	Plaster	White	None	0	44	Positive
1	1	Multipurpose Room	Door 1	Wood	Brown	None	0	0.04	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Multipurpose Room	Door Frame 1	Wood	Brown	None	0	0.02	Negative
1	1	Multipurpose Room	Door 2	Wood	Brown	None	0	0.03	Negative
1	1	Multipurpose Room	Door Frame 2	Wood	Brown	None	0	0.04	Negative
1	1	Multipurpose Room	Window Sill 1	Wood	Brown	None	0	0.08	Negative
1	1	Multipurpose Room	Window Frame 1	Wood	Brown	None	0	0.07	Negative
1	1	Multipurpose Room	Window Sill 2	Wood	Brown	None	0	0.04	Negative
1	1	Multipurpose Room	Window Frame 2	Wood	Brown	None	0	0.08	Negative
1	1	Multipurpose Room	Window Sill 3	Wood	Brown	None	0	0.06	Negative
1	1	Multipurpose Room	Window Frame 3	Wood	Brown	None	0	0.2	Negative
1	1	Multipurpose Room	Window Sill 4	Wood	Brown	None	0	0.16	Negative
1	1	Multipurpose Room	Window Frame 4	Wood	Brown	None	0	0.03	Negative
1	1	Multipurpose Room	Window Sill 5	Wood	Brown	None	0	0.07	Negative
1	1	Multipurpose Room	Window Frame 5	Wood	Brown	None	0	0.06	Negative
1	1	Multipurpose Room	W4	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 125	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Music Classroom 125	W1	Plaster	White	None	0	>10	Positive
1	1	Music Classroom 125	W2	Plaster	White	None	0	>10	Positive
1	1	Music Classroom 125	W3	Plaster	White	None	0	>10	Positive
1	1	Music Classroom 125	W4	Plaster	White	None	0	>10	Positive
1	1	Music Classroom 125	Window Sill 1	Wood	Brown	None	0	0.1	Negative
1	1	Music Classroom 125	Window Sill 2	Wood	Brown	None	0	0.1	Negative
1	1	Music Classroom 125	Window Frame 1	Wood	Brown	None	0	0.1	Negative
1	1	Music Classroom 125	Window Frame 2	Wood	Brown	None	0	0.1	Negative
1	B	Building Engineer's Office	Pipe	Metal	White	Cracking	5	42.7	Positive
1	1	Music Classroom 125	Door	Metal	Brown	None	0	0.1	Negative
1	1	Music Classroom 125	Door Frame	Metal	Brown	None	0	0.1	Negative
1	1	Music Classroom 125	W1	Plaster	Yellow	None	0	0.1	Negative
1	1	Music Classroom 125	W2	Plaster	Yellow	None	0	0.1	Negative
1	1	Music Classroom 125	W3	Plaster	Yellow	None	0	0.1	Negative
1	1	Music Classroom 125	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Building Engineer's Office	Radiator	Metal	Grey	Chipping	1	7.9	Positive
1	1	Nurse's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Nurse's Office	Door	Wood	Brown	None	0	0.09	Negative
1	1	Nurse's Office	Baseboard	Wood	Brown	None	0	0.14	Negative
1	1	Nurse's Office	Window Frame	Wood	Brown	None	0	0.3	Negative
1	B	Staff Locker Room	Radiator 1	Metal	Grey	Chipping	1	14.9	Positive
1	B	Staff Locker Room	Radiator 2	Metal	Grey	Chipping	2	3.3	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Staff Locker Room	W1	Plaster	White	Cracking	3	9.8	Positive
1	1	Nurse's Office	W4	Plaster	White	None	0	32.9	Positive
1	1	Nurse's Office	Window Sill	Wood	Brown	None	0	0.29	Negative
1	1	Nurse's Office	Door Frame	Wood	Brown	None	0	0.06	Negative
1	1	Nurse's Office	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Staff Locker Room	W2	Plaster	White	Cracking	10	31.6	Positive
1	1	Nurse's Reception Area	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Staff Locker Room	W3	Plaster	White	Cracking	20	29.5	Positive
1	1	Nurse's Reception Area	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Nurse's Reception Area	W1	Plaster	White	None	0	33.8	Positive
1	1	Nurse's Reception Area	W2	Plaster	White	None	0	31.3	Positive
1	1	Nurse's Reception Area	W3	Plaster	White	None	0	33.9	Positive
1	1	Nurse's Reception Area	W4	Plaster	White	None	0	35.3	Positive
1	1	Nurse's Reception Area	Window Frame	Wood	Brown	None	0	34	Positive
1	1	Nurse's Reception Area	Window Sill	Wood	Brown	None	0	29	Positive
1	1	Nurse's Reception Area	Pipe 1	Metal	White	None	0	12.1	Positive
1	1	Nurse's Reception Area	Pipe 2	Metal	White	None	0	2.3	Positive
1	1	Nurse's Reception Area	Door 1	Wood	Brown	None	0	0.04	Negative
1	1	Nurse's Reception Area	Door 2	Wood	Brown	None	0	30	Positive
1	1	Nurse's Reception Area	Door Frame 1	Wood	Brown	None	0	0.05	Negative
1	1	Nurse's Restroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Staff Locker Room	W4	Plaster	White	Cracking	40	37.1	Positive
1	1	Nurse's Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Nurse's Restroom	W1	Plaster	White	None	0	4.4	Positive
1	1	Nurse's Restroom	W2	Plaster	White	None	0	25.8	Positive
1	1	Nurse's Restroom	W3	Plaster	White	None	0	23.4	Positive
1	B	Men's Restroom	Ceiling	Plaster	White	Flaking	20	>10	Positive
1	1	Nurse's Restroom	Window Frame	Wood	Brown	None	0	29.6	Positive
1	1	Nurse's Restroom	Door	Wood	Brown	None	0	28.2	Positive
1	1	Principal's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Principal's Office	Baseboard	Concrete	Grey	None	0	0.1	Negative
1	1	Principal's Office	Door	Wood	Brown	None	0	0.1	Negative
1	1	Principal's Office	Window Frame 1	Wood	Brown	None	0	0.3	Negative
1	1	Principal's Office	Door Frame	Wood	Brown	None	0	0.2	Negative
1	1	Principal's Office	W1	Plaster	Yellow	None	0	>10	Positive
1	B	Women's Restroom	Ceiling	Plaster	White	Flaking	20	>10	Positive
1	1	Principal's Office	W3	Plaster	Yellow	None	0	>10	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Principal's Office	W4	Plaster	Yellow	None	0	>10	Positive
1	1	Principal's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Women's Restroom	W1	Plaster	White	Cracking	10	>10	Positive
1	1	Principal's Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Principal's Restroom	Floor	Concrete	Grey	None	0	0.1	Negative
1	1	Principal's Restroom	W1	Plaster	Green	None	0	4.4	Positive
1	B	Women's Restroom	W2	Plaster	White	Cracking	10	>10	Positive
1	1	Principal's Restroom	W3	Plaster	Green	None	0	6.5	Positive
1	1	Principal's Restroom	W4	Plaster	Green	None	0	35.1	Positive
1	1	Principal's Restroom	W1	Brick	Green	None	0	3.9	Positive
1	1	Principal's Restroom	W2	Brick	Green	None	0	3.6	Positive
1	1	Principal's Restroom	W3	Brick	Green	None	0	2.6	Positive
1	1	Principal's Restroom	W4	Brick	Green	None	0	4.1	Positive
1	1	Principal's Restroom	Window Frame	Wood	Green	None	0	5.2	Positive
1	1	Principal's Restroom	Window Sill	Brick	Green	None	0	3.2	Positive
1	1	Principal's Restroom	Pipe 1	Metal	Green	None	0	0	Negative
1	1	Principal's Restroom	Radiator	Metal	Grey	None	0	6.3	Positive
1	1	Principal's Restroom	Door Frame 1	Wood	Green	None	0	0.2	Negative
1	1	Principal's Restroom	Baseboard	Concrete	Grey	None	0	7.7	Positive
1	1	School Store	W4	Sheetrock	White	None	0	0	Negative
1	1	School Store	W1	Plaster	Blue	None	0	0	Negative
1	1	School Store	W2	Plaster	Blue	None	0	0	Negative
1	1	School Store	W3	Plaster	Blue	None	0	0	Negative
1	1	School Store	W4	Sheetrock	Blue	None	0	0	Negative
1	1	School Store	Ceiling	Plaster	White	None	0	>10	Positive
1	1	School Store	Door	Wood	Brown	None	0	0.1	Negative
1	1	School Store	Baseboard	Wood	Brown	None	0	0.1	Negative
1	1	School Store	Window Frame	Wood	Brown	None	0	0.4	Negative
1	1	School Store	W3	Plaster	White	None	0	9.2	Positive
1	1	School Store	Window Sill	Wood	Brown	None	0	0.4	Negative
1	1	School Store	Door Frame	Wood	Brown	None	0	0.1	Negative
1	1	School Store	W1	Plaster	White	None	0	>10	Positive
1	1	School Store	W2	Plaster	White	None	0	>10	Positive
1	1	School Store	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Women's Restroom	W3	Plaster	White	Cracking	10	>10	Positive
1	1	Staff Lounge	W2	Sheetrock	White	None	0	0	Negative
1	1	Staff Lounge	W1	Plaster	Blue	None	0	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Staff Lounge	W2	Sheetrock	Blue	None	0	0	Negative
1	1	Staff Lounge	W4	Plaster	White	None	0	0.01	Negative
1	1	Staff Lounge	Pipe	Metal	White	None	0	0.11	Negative
1	1	Staff Lounge	Baseboard	Wood	Brown	None	0	0.13	Negative
1	1	Staff Lounge	Pipe	Metal	Blue	None	0	0.24	Negative
1	1	Staff Lounge	W1	Plaster	White	None	0	49.8	Positive
1	1	Staff Lounge	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Staff Lounge	W3	Plaster	White	None	0	46.8	Positive
1	1	Staff Lounge	W3	Plaster	Blue	Chipping	1	0	Negative
1	1	Staff Lounge	W4	Plaster	Blue	Chipping	1	0	Negative
1	1	Staff Lounge	Window Sill 1	Wood	Brown	None	0	0.23	Negative
1	1	Staff Lounge	Window Frame 1	Wood	Brown	None	0	0.4	Negative
1	1	Staff Lounge	Window Sill 2	Wood	Brown	None	0	0.13	Negative
1	1	Staff Lounge	Window Frame 2	Wood	Brown	None	0	0.12	Negative
1	1	Staff Lounge	Window Sill 3	Wood	Brown	None	0	0.3	Negative
1	1	Staff Lounge	Window Frame 3	Wood	Brown	None	0	0.06	Negative
1	1	Staff Lounge	Door 1	Metal	Brown	None	0	1.3	Positive
1	1	Staff Lounge	Door Frame 1	Wood	Brown	None	0	0.16	Negative
1	1	Stairwell adjacent Classroom 106	W4	Sheetrock	White	None	0	0	Negative
1	1	Stairwell adjacent Classroom 106	W1	Plaster	White	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	W2	Brick	White	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	W3	Metal	White	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Ceiling	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Floor	Metal	Blue	None	0	9	Positive
1	1	Stairwell adjacent Classroom 106	Stair Tread	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Stair Riser	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Stringer	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Newell Post	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 106	Hand Rail	Metal	Blue	None	0	1.2	Positive
1	1	Stairwell adjacent Classroom 125	W2	Metal	Blue	None	0	0.2	Negative
1	1	Stairwell adjacent Classroom 125	W4	Metal	Blue	None	0	0.3	Negative
1	1	Stairwell adjacent Classroom 125	Riser	Wood	Blue	None	0	0.2	Negative
1	1	Stairwell adjacent Classroom 125	Ceiling	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent Classroom 125	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent Classroom 125	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent Classroom 125	Handrail	Metal	Brown	None	0	0.2	Negative
1	1	Stairwell adjacent Classroom 125	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Stairwell adjacent to Classroom 100	W1	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 100	W2	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 100	W3	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 100	W4	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Women's Restroom	W4	Plaster	White	Cracking	10	>10	Positive
1	1	Stairwell adjacent to Classroom 100	Riser	Concrete	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 100	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 100	Window Frame	Metal	Blue	None	0	9.6	Positive
1	1	Stairwell adjacent to Classroom 100	Ceiling	Concrete	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 105	W2	Metal	Blue	None	0	0.3	Negative
1	1	Stairwell adjacent to Classroom 105	W4	Metal	Blue	None	0	0.3	Negative
1	1	Stairwell adjacent to Classroom 105	Ceiling	Metal	Blue	None	0	8.8	Positive
1	1	Stairwell adjacent to Classroom 105	W1	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 105	W3	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 105	Riser	Metal	Blue	None	0	8.7	Positive
1	1	Stairwell adjacent to Classroom 105	Floor	Cement	Grey	None	0	N/A	N/A
1	1	Stairwell adjacent to Classroom 105	Hand Rail	Metal	Brown	Chipping	2	0.2	Negative
1	1	Stairwell adjacent to Classroom 120	Ceiling	Cement	Blue	None	0	8.6	Positive
1	1	Stairwell adjacent to Classroom 120	Window Frame	Wood	Blue	None	0	9.4	Positive
1	1	Stairwell adjacent to Classroom 120	Riser	Wood	Blue	None	0	9.3	Positive
1	1	Stairwell adjacent to Classroom 120	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 120	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 120	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 120	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 120	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Classroom 120	Hand Rail	Metal	Brown	Chipping	1	0.6	Negative
1	1	Stairwell adjacent to Classroom 131	W2	Brick	White	None	0	0.4	Negative
1	1	Stairwell adjacent to Classroom 131	W1	Brick	White	None	0	0.5	Negative
1	1	Stairwell adjacent to Classroom 131	W4	Brick	White	None	0	0.7	Positive
1	1	Stairwell adjacent to Classroom 131	W3	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Floor	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Stair Tread	Metal	Blue	None	0	5.4	Positive
1	1	Stairwell adjacent to Classroom 131	Stair Riser	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Stringer	Metal	Blue	None	0	>10	Positive
1	1	Stairwell adjacent to Classroom 131	Newell Post	Metal	Blue	None	0	>10	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Stairwell adjacent to Classroom 131	Hand Rail	Metal	Blue	None	0	0.1	Negative
1	1	Stairwell adjacent to Office 126	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Stairwell adjacent to Office 126	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 126	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 126	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 126	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 126	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 129	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Stairwell adjacent to Office 129	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 129	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 129	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 129	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Stairwell adjacent to Office 129	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Vice- Principal's Office	Door	Wood	Brown	None	0	0.05	Negative
1	1	Vice- Principal's Office	Window Frame	Wood	Brown	None	0	0.11	Negative
1	B	Women's Restroom	Pipe 1	Metal	White	Cracking	10	>10	Positive
1	1	Vice- Principal's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Vice- Principal's Office	W3	Plaster	Pink	None	0	0.5	Negative
1	1	Vice- Principal's Office	W1	Plaster	Pink	None	0	34.9	Positive
1	1	Vice- Principal's Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Vice- Principal's Office	W2	Plaster	Pink	None	0	30.2	Positive
1	B	Women's Restroom	Pipe 2	Metal	White	Cracking	10	>10	Positive
1	1	Vice- Principal's Office	W1	Plaster	White	None	0	44.7	Positive
1	1	Vice- Principal's Office	W2	Plaster	White	None	0	42.3	Positive
1	1	Vice- Principal's Office	W3	Plaster	White	None	0	41.4	Positive
1	1	Vice- Principal's Office	W4	Plaster	White	None	0	43	Positive
1	1	Vice- Principal's Office	Window Sill	Wood	Brown	None	0	0.22	Negative
1	1	Vice- Principal's Office	Baseboard	Wood	Brown	None	0	1.7	Positive
1	1	Vice- Principal's Office	Door Frame	Wood	Brown	None	0	0.07	Negative
1	1	Weight Room 104	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Weight Room 104	Baseboard	Wood	Brown	None	0	0.18	Negative
1	1	Weight Room 104	W1	Plaster	White	None	0	9.5	Positive
1	1	Weight Room 104	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Weight Room 104	W2	Plaster	White	None	0	45.4	Positive
1	B	Women's Restroom	Pipe 3	Metal	White	Cracking	10	>10	Positive
1	1	Weight Room 104	W4	Plaster	White	None	0	39.9	Positive
1	1	Weight Room 104	Door 1	Wood	Brown	None	0	0.04	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Weight Room 104	Door Frame 1	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104	Door 2	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104	Door Frame 2	Wood	Brown	None	0	0.03	Negative
1	1	Weight Room 104	Door Frame 3	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104	Window Sill 1	Wood	Brown	None	0	0.03	Negative
1	1	Weight Room 104	Window Frame 1	Wood	Brown	None	0	0.05	Negative
1	1	Weight Room 104	Window Sill 2	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104	Window Frame 2	Wood	Brown	None	0	0.01	Negative
1	1	Weight Room 104	Window Sill 3	Wood	Brown	None	0	0.02	Negative
1	1	Weight Room 104	Window Frame 3	Wood	Brown	None	0	0.12	Negative
1	1	Weight Room 104	Window Sill 4	Wood	Brown	None	0	0.02	Negative
1	1	Weight Room 104	Window Frame 4	Wood	Brown	None	0	0.03	Negative
1	1	Weight Room 104	Window Sill 5	Wood	Brown	None	0	0.19	Negative
1	1	Weight Room 104	Window Frame 5	Wood	Brown	None	0	0.05	Negative
1	1	Weight Room 104	Window Sill 6	Wood	Brown	None	0	0.11	Negative
1	1	Weight Room 104	Window Frame 6	Wood	Brown	None	0	0.07	Negative
1	1	Weight Room 104 Boys Bathroom	W1	Sheetrock	White	None	0	0	Negative
1	1	Weight Room 104 Boys Bathroom	W4	Sheetrock	White	None	0	0	Negative
1	1	Weight Room 104 Boys Bathroom	W1	Sheetrock	Blue	None	0	0	Negative
1	1	Weight Room 104 Boys Bathroom	W4	Sheetrock	Blue	None	0	0	Negative
1	1	Weight Room 104 Boys Bathroom	Window Frame	Wood	Blue	None	0	0.18	Negative
1	B	Women's Restroom	Window Frame	Metal	Brown	Flaking	5	6.4	Positive
1	1	Weight Room 104 Boys Bathroom	W3	Plaster	White	None	0	34.3	Positive
1	1	Weight Room 104 Boys Bathroom	W2	Plaster	Blue	None	0	41.4	Positive
1	1	Weight Room 104 Boys Bathroom	W3	Plaster	Blue	None	0	45	Positive
1	1	Weight Room 104 Boys Bathroom	Radiator	Metal	Blue	None	0	16.7	Positive
1	1	Weight Room 104 Boys Bathroom	Door Frame	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104 Boys Bathroom	Window Sill	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104 Boys Bathroom	Pipe 1	Metal	White	None	0	0.21	Negative
1	1	Weight Room 104 Boys Bathroom	Pipe 2	Metal	Blue	None	0	0.3	Negative
1	1	Weight Room 104 Boys Bathroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Weight Room 104 Girls Bathroom	W1	Sheetrock	White	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	W2	Plaster	White	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	W1	Sheetrock	Blue	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	W2	Plaster	Blue	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	Radiator Cover	Metal	Blue	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	W3	Plaster	White	None	0	32.4	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Weight Room 104 Girls Bathroom	W4	Plaster	White	None	0	39.7	Positive
1	1	Weight Room 104 Girls Bathroom	W3	Plaster	Blue	None	0	31.8	Positive
1	1	Weight Room 104 Girls Bathroom	W4	Plaster	Blue	None	0	33.1	Positive
1	1	Weight Room 104 Girls Bathroom	Door Frame	Wood	Brown	None	0	0.02	Negative
1	1	Weight Room 104 Girls Bathroom	Window Sill	Wood	Brown	None	0	0.04	Negative
1	1	Weight Room 104 Girls Bathroom	Window Frame	Wood	Blue	None	0	1.2	Positive
1	1	Weight Room 104 Girls Bathroom	Pipe 1	Metal	White	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	Pipe 2	Metal	Blue	None	0	0	Negative
1	1	Weight Room 104 Girls Bathroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	216/217 Hallway	Door 1	Wood	Brown	None	0	0.15	Negative
1	2	216/217 Hallway	Door 2	Wood	Brown	None	0	0	Negative
1	2	216/217 Hallway	Door Frame 1	Wood	Brown	None	0	0.09	Negative
1	2	216/217 Hallway	Door Frame 2	Wood	Brown	None	0	0.15	Negative
1	2	216/217 Hallway	W1	Plaster	Yellow	None	0	39.3	Positive
1	2	216/217 Hallway	W2	Plaster	Yellow	None	0	30.5	Positive
1	2	216/217 Hallway	W3	Plaster	Yellow	None	0	31	Positive
1	B	Women's Restroom	Baseboard	Concrete	Grey	Flaking	2	3.2	Positive
1	2	216/217 Hallway	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	216/217 Hallway	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Backstage Right Closet	W1	Plaster	White	Flaking	2	41.3	Positive
1	B	Backstage Right Closet	W2	Plaster	White	Flaking	2	1.1	Positive
1	B	Backstage Right Closet	W3	Plaster	White	Flaking	2	44.1	Positive
1	2	Classroom 200	W4	Plaster	Yellow	None	0	45.9	Positive
1	2	Classroom 200	Window Frame 1	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 200	Window Sill 1	Wood	Brown	None	0	0.27	Negative
1	2	Classroom 200	Window Frame 2	Wood	Brown	None	0	0.22	Negative
1	2	Classroom 200	Window Sill 2	Wood	Brown	None	0	0.28	Negative
1	2	Classroom 200	Window Frame 3	Wood	Brown	None	0	0.19	Negative
1	2	Classroom 200	Window Sill 3	Wood	Brown	None	0	0.22	Negative
1	2	Classroom 200	Door Frame	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 200	Pipe 1	Metal	Yellow	None	0	0.15	Negative
1	2	Classroom 200	Pipe 2	Metal	White	None	0	0.18	Negative
1	2	Classroom 200	Door	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 200	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 200	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 200	Baseboard	Wood	Brown	None	0	0.19	Negative
1	B	Backstage Right Closet	W4	Plaster	White	Flaking	2	35.7	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Backstage Right Closet	Pipe	Metal	White	Flaking	3	7.5	Positive
1	2	Classroom 201	W2	Plaster	Yellow	None	0	34.9	Positive
1	B	Backstage Right Closet	Window Frame 1	Wood	Brown	Flaking	3	3.3	Positive
1	B	Backstage Right Closet	Window Frame 2	Wood	Brown	Flaking	2	4.7	Positive
1	2	Classroom 201	Window Frame 1	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 201	Window Sill 1	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 201	Window Frame 2	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 201	Window Sill 2	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 201	Window Frame 3	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 201	Window Sill 3	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 201	Window Frame 4	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 201	Window Sill 4	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 201	Door 1	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 201	Door 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 201	Door Frame 1	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 201	Door Frame 2	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 201	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 201	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 201	Baseboard	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 202	Pipe 2	Metal	Yellow	Flaking	5	0.13	Negative
1	B	Fan Room	Fan Unit	Metal	Grey	Flaking	400	15.5	Positive
1	2	Classroom 202	Door 1	Wood	Brown	None	0	0.06	Negative
1	2	Classroom 202	Door 2	Wood	Brown	None	0	0.06	Negative
1	2	Classroom 202	Door Frame 1	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 202	Door Frame 2	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 202	Pipe 1	Metal	Yellow	None	0	1.6	Positive
1	2	Classroom 202	Baseboard	Wood	Brown	None	0	1.2	Positive
1	B	Fan Room	Stringer	Concrete	White	Flaking	5	7.2	Positive
1	B	Fan Room- Left Side Fan Unit	Fan Unit	Metal	Grey	Flaking	100	5.5	Positive
1	B	Fan Room- Right Side Fan Unit	Fan Unit	Metal	Grey	Chipping	200	16.4	Positive
1	2	Classroom 202	Window Frame 1	Wood	Brown	None	0	0.22	Negative
1	2	Classroom 202	Window Sill 1	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 202	Window Frame 2	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 202	Window Sill 2	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 202	Window Frame 3	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 202	Window Sill 3	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 202	Window Frame 4	Wood	Brown	None	0	0.17	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 202	Window Sill 4	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 202	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 202	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 203-204	W1	Plaster	Yellow	None	0	1.3	Positive
1	2	Classroom 203-204	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 203-204	W3	Plaster	Yellow	None	0	31.6	Positive
1	2	Classroom 203-204	W4	Plaster	Yellow	None	0	1.8	Positive
1	2	Classroom 203-204	Door 1	Wood	Brown	None	0	0.02	Negative
1	2	Classroom 203-204	Door 3	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 203-204	Door Frame 1	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 203-204	Door Frame 3	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 203-204	Window Frame 1	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 203-204	Window Sill 1	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 203-204	Window Frame 2	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 203-204	Window Sill 2	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 203-204	Window Frame 3	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 203-204	Window Sill 3	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 203-204	Window Frame 4	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 203-204	Window Sill 4	Wood	Brown	None	0	0.24	Negative
1	2	Classroom 203-204	Window Frame 5	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 203-204	Window Sill 5	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 203-204	Window Frame 6	Wood	Brown	None	0	0.19	Negative
1	2	Classroom 203-204	Window Sill 6	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 203-204	Window Frame 7	Wood	Brown	None	0	0.25	Negative
1	2	Classroom 203-204	Window Sill 7	Wood	Brown	None	0	0.27	Negative
1	2	Classroom 203-204	Window Frame 8	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 203-204	Window Sill 8	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 203-204	Pipe	Metal	Yellow	None	0	0.14	Negative
1	2	Classroom 203-204	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 203-204	W2	Plaster	Yellow	Cracking	5	0.14	Negative
1	2	Classroom 203-204	Baseboard	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 203-204	Door 2	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 203-204	Door Frame 2	Wood	Unpainted	None	0	N/A	N/A
1	B	Cafeteria Storage	Ceiling	Plaster	White	Cracking	5	>10	Positive
1	B	Foyer	Door 1	Wood	White	Cracking	2	32.3	Positive
1	B	Foyer	Door 2	Wood	White	Cracking	2	37.7	Positive
1	B	Foyer	Door 3	Wood	White	Cracking	2	32.5	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 205	W2	Plaster	White	None	0	37.4	Positive
1	2	Classroom 205	W3	Plaster	White	None	0	35.6	Positive
1	2	Classroom 205	W4	Plaster	White	None	0	37.6	Positive
1	2	Classroom 205	Door Frame	Metal	Brown	None	0	0.02	Negative
1	2	Classroom 205	Window Sill	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 205	Door	Metal	Brown	None	0	0.02	Negative
1	2	Classroom 205	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 205	Window Frame	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 205	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 205	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 207	Pipe 2	Metal	White	Flaking	2	0.15	Negative
1	B	Foyer	Door 4	Wood	White	Cracking	2	32.6	Positive
1	B	Foyer	Door 5	Wood	White	Cracking	2	35.5	Positive
1	2	Classroom 207	W3	Plaster	Yellow	None	0	33.6	Positive
1	2	Classroom 207	W4	Plaster	Yellow	None	0	44.1	Positive
1	2	Classroom 207	Door 1	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 207	Door 2	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 207	Door Frame 1	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 207	Door Frame 2	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 207	Window Frame 1	Wood	Brown	None	0	0.25	Negative
1	2	Classroom 207	Window Sill 1	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 207	Window Frame 2	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 207	Window Sill 2	Wood	Brown	None	0	0.28	Negative
1	2	Classroom 207	Window Frame 3	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 207	Window Sill 3	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 207	Window Frame 4	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 207	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 207	Window Frame 5	Wood	Brown	None	0	0.16	Negative
1	2	Classroom 207	Window Sill 5	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 207	Pipe 1	Metal	White	None	0	1.8	Positive
1	2	Classroom 207	Pipe 3	Metal	Yellow	None	0	0.03	Negative
1	2	Classroom 207	Baseboard	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 207	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 207	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Foyer	W3	Plaster	White	Cracking	15	49.2	Positive
1	2	Classroom 208	W1	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 208	W2	Plaster	Blue	Flaking	2	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 208	W4	Sheetrock	White	None	0	0	Negative
1	2	Classroom 208	W4	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 208	W1	Sheetrock	White	None	0	0	Negative
1	B	Foyer	Door Frame 1	Wood	White	Cracking	2	38.1	Positive
1	2	Classroom 208	W3	Plaster	White	None	0	2.6	Positive
1	2	Classroom 208	Window Frame 1	Wood	Brown	None	0	0.01	Negative
1	2	Classroom 208	Window Sill 1	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 208	Window Frame 2	Wood	Brown	None	0	0.24	Negative
1	2	Classroom 208	Window Sill 2	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 208	Window Frame 3	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 208	Window Sill 3	Wood	Brown	None	0	0.5	Negative
1	2	Classroom 208	Window Frame 4	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 208	Window Sill 4	Wood	Brown	None	0	0.28	Negative
1	2	Classroom 208	Door Frame	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 208	Door	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 208	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 208	Baseboard	Wood	Brown	None	0	0.15	Negative
1	2	Classroom 208	W3	Plaster	Blue	Chipping	1	0.6	Negative
1	2	Classroom 209	W1	Plaster	Yellow	None	0	41	Positive
1	2	Classroom 209	W2	Plaster	Yellow	None	0	48.3	Positive
1	2	Classroom 209	W3	Plaster	Yellow	None	0	44	Positive
1	2	Classroom 209	W4	Plaster	Yellow	None	0	2.5	Positive
1	2	Classroom 209	Window Frame 1	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 209	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 209	Window Frame 2	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 209	Window Sill 2	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 209	Window Frame 3	Wood	Brown	None	0	0.16	Negative
1	2	Classroom 209	Window Sill 3	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 209	Window Frame 4	Wood	Brown	None	0	0.24	Negative
1	2	Classroom 209	Window Sill 4	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 209	Window Frame 5	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 209	Window Sill 5	Wood	Brown	None	0	0.13	Negative
1	2	Classroom 209	Door 1	Wood	Brown	None	0	0.16	Negative
1	2	Classroom 209	Door Frame 1	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 209	Door 2	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 209	Door Frame 2	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 209	Pipe	Metal	White	None	0	1.6	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 209	Baseboard	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 209	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 209	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Foyer	Door Frame 2	Wood	White	Cracking	2	30.7	Positive
1	2	Classroom 210	W1	Plaster	Blue	Flaking	1	0	Negative
1	2	Classroom 210	W2	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 210	W4	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 210	W2	Sheetrock	White	None	0	0	Negative
1	2	Classroom 210	W4	Sheetrock	White	None	0	0	Negative
1	2	Classroom 210	W3	Plaster	Blue	None	0	0.02	Negative
1	B	Foyer	Door Frame 3	Wood	White	Cracking	2	39.4	Positive
1	B	Foyer	Door Frame 4	Wood	White	Cracking	2	39	Positive
1	2	Classroom 210	Window Frame 1	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 210	Window Sill 1	Wood	Brown	None	0	0.28	Negative
1	2	Classroom 210	Window Frame 2	Wood	Brown	None	0	0.03	Negative
1	2	Classroom 210	Window Sill 2	Wood	Brown	None	0	0.24	Negative
1	2	Classroom 210	Window Frame 3	Wood	Brown	None	0	0	Negative
1	2	Classroom 210	Window Sill 3	Wood	Brown	None	0	0.25	Negative
1	2	Classroom 210	Window Frame 4	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 210	Window Sill 4	Wood	Brown	None	0	0.01	Negative
1	2	Classroom 210	Window Frame 5	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 210	Window Sill 5	Wood	Brown	None	0	0.11	Negative
1	2	Classroom 210	Door Frame	Wood	Brown	None	0	0.03	Negative
1	2	Classroom 210	Baseboard	Wood	Brown	None	0	0.13	Negative
1	2	Classroom 210	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 212	W1	Plaster	Yellow	None	0	44.2	Positive
1	2	Classroom 212	W2	Plaster	Yellow	None	0	40.6	Positive
1	2	Classroom 212	W3	Plaster	Yellow	None	0	33.2	Positive
1	2	Classroom 212	W4	Plaster	Yellow	None	0	51.1	Positive
1	2	Classroom 212	W1	Plaster	Green	None	0	34.6	Positive
1	2	Classroom 212	W2	Plaster	Green	None	0	33.9	Positive
1	2	Classroom 212	W3	Plaster	Green	None	0	39.5	Positive
1	2	Classroom 212	W4	Plaster	Green	None	0	33.6	Positive
1	2	Classroom 212	Door Frame 1	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 212	Door 1	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 212	Door Frame 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 212	Door 2	Wood	Brown	None	0	0.09	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 212	Window Frame 1	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 212	Window Sill 1	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 212	Window Frame 2	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 212	Window Sill 2	Wood	Brown	None	0	0.5	Negative
1	2	Classroom 212	Window Frame 3	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 212	Window Sill 3	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 212	Window Frame 4	Wood	Brown	None	0	0.11	Negative
1	2	Classroom 212	Window Sill 4	Wood	Brown	None	0	0.28	Negative
1	2	Classroom 212	Window Frame 5	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 212	Window Sill 5	Wood	Brown	None	0	0.22	Negative
1	2	Classroom 212	Baseboard	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 212	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 212	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 214	W1	Plaster	Yellow	None	0	42.1	Positive
1	2	Classroom 214	W2	Plaster	Yellow	None	0	48.3	Positive
1	2	Classroom 214	W3	Plaster	Yellow	None	0	34	Positive
1	2	Classroom 214	W4	Plaster	Yellow	None	0	36.4	Positive
1	2	Classroom 214	Door Frame	Wood	Brown	None	0	0.13	Negative
1	2	Classroom 214	Window Sill	Wood	Brown	None	0	1	Positive
1	2	Classroom 214	Pipe 1	Metal	Yellow	None	0	0.01	Negative
1	2	Classroom 214	Pipe 2	Metal	Yellow	None	0	0.21	Negative
1	2	Classroom 214	Pipe 3	Metal	Yellow	None	0	1.3	Positive
1	2	Classroom 214	Window Frame	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 214	Door	Wood	Purple	None	0	0.09	Negative
1	2	Classroom 214	Baseboard	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 214	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 214	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Foyer	Door Frame 5	Wood	White	Cracking	2	38.7	Positive
1	2	Classroom 215	W2	Plaster	Yellow	None	0	48	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Radiator 1	Metal	Grey	Chipping	4	2.5	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Radiator 2	Metal	Grey	Chipping	4	1.2	Positive
1	2	Classroom 215	Door 1	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 215	Door Frame 1	Wood	Brown	None	0	0.06	Negative
1	2	Classroom 215	Door 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 215	Door Frame 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 215	Window Frame 1	Wood	Brown	None	0	0.16	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 215	Window Sill 1	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 215	Window Frame 2	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 215	Window Sill 2	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 215	Window Frame 3	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 215	Window Sill 3	Wood	Brown	None	0	0.6	Negative
1	2	Classroom 215	Window Frame 4	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 215	Window Sill 4	Wood	Brown	None	0	0.23	Negative
1	2	Classroom 215	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 215	Baseboard	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 215	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 216	Pipe 2	Metal	Yellow	Flaking	3	0.2	Negative
1	2	Classroom 216	W1	Plaster	Yellow	None	0	26.9	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Radiator 3	Metal	Grey	Chipping	4	3.6	Positive
1	B	Hallway adjacent to Gymnasium	W1	Plaster	White	Cracking	10	27.2	Positive
1	B	Hallway adjacent to Gymnasium	W2	Plaster	White	Cracking	1	13.5	Positive
1	2	Classroom 216	Door 1	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 216	Door 2	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 216	Door Frame 1	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 216	Door Frame 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 216	Window Frame 1	Wood	Brown	None	0	0.15	Negative
1	2	Classroom 216	Window Sill 1	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 216	Window Frame 2	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 216	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 216	Window Frame 3	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 216	Window Sill 3	Wood	Brown	None	0	0.5	Negative
1	2	Classroom 216	Window Frame 4	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 216	Window Sill 4	Wood	Brown	None	0	1.8	Positive
1	2	Classroom 216	Window Frame 5	Wood	Brown	None	0	0.1	Negative
1	2	Classroom 216	Window Sill 5	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 216	Pipe 1	Metal	Yellow	None	0	1	Positive
1	2	Classroom 216	Pipe 3	Metal	Yellow	None	0	0.7	Positive
1	2	Classroom 216	Baseboard	Wood	Brown	None	0	0.11	Negative
1	2	Classroom 216	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 216	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Hallway adjacent to Gymnasium	W3	Plaster	White	Chipping	4	37.6	Positive
1	2	Classroom 217	Pipe 5	Metal	White	Flaking	1	0	Negative

		Dates: 1/17/23-1/27/23, 5/19/23			Lead-Safe Certification Assessment Report				
		Inspector Name and Certificate Number: Erik Swanson 006917			616 N. 15th Street, Philadelphia, PA 19130				
		Inspection Company: Viva			Franklin Learning Center				
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Hallway adjacent to Gymnasium	Handrail 1	Metal	Brown	Chipping	2	0.7	Positive
1	B	Hallway adjacent to Gymnasium	Handrail 3	Metal	Brown	Chipping	2	3.5	Positive
1	2	Classroom 217	Floor	Wood	Brown	None	0	0.13	Negative
1	2	Classroom 217	W2	Plaster	Yellow	None	0	2.3	Positive
1	2	Classroom 217	W4	Plaster	Yellow	None	0	12.6	Positive
1	2	Classroom 217	Door 1	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 217	Door Frame 1	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 217	Door 2	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 217	Door Frame 2	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 217	Window Frame 1	Wood	Brown	None	0	0.04	Negative
1	2	Classroom 217	Window Sill 1	Wood	Brown	None	0	0.5	Negative
1	2	Classroom 217	Window Frame 2	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 217	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 217	Window Frame 3	Wood	Brown	None	0	0.08	Negative
1	2	Classroom 217	Window Sill 3	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 217	Window Frame 4	Wood	Brown	None	0	0.11	Negative
1	2	Classroom 217	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	2	Classroom 217	Window Frame 5	Wood	Brown	None	0	0.17	Negative
1	2	Classroom 217	Window Sill 5	Wood	Brown	None	0	0.21	Negative
1	2	Classroom 217	Baseboard	Wood	Brown	None	0	0.2	Negative
1	2	Classroom 217	Pipe 1	Metal	Yellow	None	0	0.21	Negative
1	2	Classroom 217	Pipe 2	Metal	Yellow	None	0	0.1	Negative
1	2	Classroom 217	Pipe 4	Metal	Yellow	None	0	0.5	Negative
1	2	Classroom 217	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 217	W3	Plaster	Yellow	Flaking	2	0.22	Negative
1	2	Classroom 218	W2	Plaster	Yellow	None	0	0	Negative
1	2	Classroom 218	W4	Plaster	White	None	0	0.01	Negative
1	2	Classroom 218	Door	Metal	Brown	None	0	0.04	Negative
1	2	Classroom 218	W1	Plaster	Yellow	None	0	29.9	Positive
1	2	Classroom 218	W3	Plaster	Yellow	None	0	0.8	Positive
1	2	Classroom 218	W4	Plaster	Yellow	None	0	0.9	Positive
1	2	Classroom 218	W1	Plaster	White	None	0	38.6	Positive
1	2	Classroom 218	W2	Plaster	White	None	0	36.9	Positive
1	2	Classroom 218	W3	Plaster	White	None	0	2.6	Positive
1	2	Classroom 218	Door Frame	Metal	Brown	None	0	0.03	Negative
1	2	Classroom 218	Window Sill 1	Wood	Brown	None	0	0.27	Negative
1	2	Classroom 218	Window Sill 2	Wood	Brown	None	0	0.5	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Classroom 218	Window Frame 1	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 218	Window Frame 2	Wood	Brown	None	0	0.09	Negative
1	2	Classroom 218	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 218	Baseboard	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 218	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Classroom 220	W1	Plaster	Yellow	None	0	34.2	Positive
1	B	Hallway adjacent to Gymnasium	Radiator	Metal	Grey	Chipping	2	7.4	Positive
1	B	Hallway from Office B05 to Staff Locker Room	Baseboard	Concrete	Brown	Chipping	2	18	Positive
1	2	Classroom 220	W4	Plaster	Yellow	None	0	42.4	Positive
1	2	Classroom 220	Door Frame 1	Wood	Brown	None	0	0.06	Negative
1	2	Classroom 220	Door Frame 2	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 220	Door 1	Wood	Brown	None	0	0.05	Negative
1	2	Classroom 220	Door 2	Wood	Brown	None	0	0.03	Negative
1	2	Classroom 220	Window Frame 1	Wood	Brown	None	0	0.16	Negative
1	2	Classroom 220	Window Sill 1	Wood	Brown	None	0	0.26	Negative
1	2	Classroom 220	Window Frame 2	Wood	Brown	None	0	0.06	Negative
1	2	Classroom 220	Window Sill 2	Wood	Brown	None	0	0.15	Negative
1	2	Classroom 220	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 220	Baseboard	Wood	Brown	None	0	0.15	Negative
1	2	Classroom 220	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Closet 213	W1	Plaster	Yellow	None	0	20	Positive
1	2	Closet 213	W3	Plaster	Yellow	None	0	42	Positive
1	B	Hallway from Office B05 to Staff Locker Room	Elevator Frame	Wood	Brown	Chipping	2	7.4	Positive
1	2	Closet 213	Window Frame 1	Wood	Brown	None	0	0.19	Negative
1	2	Closet 213	Window Sill 1	Wood	Brown	None	0	0.6	Negative
1	2	Closet 213	Window Frame 2	Wood	Brown	None	0	0.13	Negative
1	2	Closet 213	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	2	Closet 213	Radiator	Metal	Grey	None	0	5.7	Positive
1	2	Closet 213	Baseboard	Wood	Brown	None	0	0.07	Negative
1	2	Closet 213	Door	Wood	Brown	None	0	0.04	Negative
1	2	Closet 213	Door Frame	Wood	Brown	None	0	0.04	Negative
1	2	Closet 213	W2	Plaster	White	No Access	No Access	No Access	No Access
1	2	Closet 213	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Closet 213	Floor	Wood	Unpainted	None	0	N/A	N/A
1	2	Custodial Closet across from 201	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Custodial Closet across from 201	W1	N/A	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet across from 201	W2	N/A	No Access	No Access	No Access	No Access	No Access

		Dates: 1/17/23-1/27/23, 5/19/23			Lead-Safe Certification Assessment Report				
		Inspector Name and Certificate Number: Erik Swanson 006917			616 N. 15th Street, Philadelphia, PA 19130				
		Inspection Company: Viva			Franklin Learning Center				
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Custodial Closet across from 201	W3	N/A	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet across from 201	W4	N/A	No Access	No Access	No Access	No Access	No Access
1	2	Custodial Closet across from 201	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Fire Tower adjacent Classroom 200	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway from Office B05 to Staff Locker Room	Ceiling	Plaster	White	Flaking	25	>10	Positive
1	2	Fire Tower adjacent Classroom 200	W1	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 200	W2	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 200	W3	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 200	W4	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 214	Door Frame	Metal	Brown	Flaking	2	0.2	Negative
1	2	Fire Tower adjacent Classroom 214	Door	Metal	Brown	Flaking	2	0.5	Negative
1	2	Fire Tower adjacent Classroom 214	Ceiling	Concrete	White	Flaking	10	0.6	Negative
1	2	Fire Tower adjacent Classroom 214	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 214	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 214	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 214	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Tower adjacent Classroom 214	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 200 to 218	W2	Plaster	Yellow	None	0	0.1	Negative
1	2	Hallway from Classrooms 200 to 218	W4	Plaster	Yellow	None	0	0.1	Negative
1	2	Hallway from Classrooms 200 to 218	Radiator 2	Metal	Grey	None	0	8.5	Positive
1	2	Hallway from Classrooms 200 to 218	Radiator 3	Metal	Grey	None	0	8.5	Positive
1	2	Hallway from Classrooms 200 to 218	Window Frame 1	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 1	Wood	Brown	None	0	0.5	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 2	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 2	Wood	Brown	None	0	0.5	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 3	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 3	Wood	Brown	None	0	0.5	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 4	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 5	Wood	Brown	Chipping	2	0.1	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 5	Wood	Brown	None	0	0.5	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 6	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 6	Wood	Brown	None	0	0.6	Negative
1	2	Hallway from Classrooms 200 to 218	Window Frame 7	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 200 to 218	Window Sill 7	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 200 to 218	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 200 to 218	Baseboard	Concrete	Brown	None	0	6.4	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Hallway from Office B05 to Staff Locker Room	Radiator	Metal	Grey	Chipping	3	9.6	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	W2	Plaster	White	Flaking	5	1.7	Positive
1	2	Hallway from Classrooms 200 to 218	W4	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 200 to 218	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 201 to 204/204	Window Frame 1	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Sill 1	Wood	Brown	None	0	0.7	Positive
1	2	Hallway from Classrooms 201 to 204/204	Window Frame 2	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Frame 3	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Sill 3	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Frame 4	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 201 to 204/204	Window Sill 4	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 201 to 204/204	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 201 to 204/204	W2	Plaster	Yellow	None	0	1.1	Positive
1	2	Hallway from Classrooms 201 to 204/204	W2	Plaster	White	None	0	1.8	Positive
1	2	Hallway from Classrooms 201 to 204/204	W4	Plaster	Yellow	None	0	1.8	Positive
1	2	Hallway from Classrooms 201 to 204/204	Baseboard	Concrete	Brown	None	0	2.4	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Ceiling	Plaster	White	Flaking	25	>10	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Radiator 1	Metal	Grey	Flaking	2	7.3	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Radiator 2	Metal	Grey	Flaking	2	10.1	Positive
1	2	Hallway from Classrooms 201 to 204/204	W4	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 201 to 204/204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 207 to 212	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 207 to 212	Baseboard	Concrete	Brown	None	0	6.8	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Radiator 3	Metal	Grey	Flaking	2	3.8	Positive
1	2	Hallway from Classrooms 207 to 212	W4	Plaster	Yellow	None	0	9.3	Positive
1	2	Hallway from Classrooms 207 to 212	W2	Plaster	Yellow	None	0	9.6	Positive
1	B	Stairwell adjacent to School Police Office B05	Handrail	Metal	Brown	Chipping	1	4.2	Positive
1	2	Hallway from Classrooms 207 to 212	W4	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 207 to 212	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 218 to 221	Window Frame 1	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 218 to 221	Window Sill 1	Wood	Brown	None	0	0.2	Negative
1	2	Hallway from Classrooms 218 to 221	Window Frame 2	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 218 to 221	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 218 to 221	Window Frame 3	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 218 to 221	Window Sill 3	Wood	Brown	None	0	0.1	Negative
1	2	Hallway from Classrooms 218 to 221	Window Frame 4	Wood	Brown	None	0	0.2	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Hallway from Classrooms 218 to 221	Window Sill 4	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 218 to 221	Window Frame 5	Wood	Brown	None	0	0.3	Negative
1	2	Hallway from Classrooms 218 to 221	Window Sill 5	Wood	Brown	None	0	0.7	Positive
1	2	Hallway from Classrooms 218 to 221	W2	Plaster	Yellow	Efflorescence	5	0.2	Negative
1	2	Hallway from Classrooms 218 to 221	W4	Plaster	Yellow	None	0	0.2	Negative
1	2	Hallway from Classrooms 218 to 221	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 218 to 221	Baseboard	Concrete	Brown	None	0	7.7	Positive
1	B	Fire Tower adjacent to Athletic Equipment Storage Room 016	Ceiling	Concrete	White	Flaking	6	36.5	Positive
1	B	Fire Tower adjacent to Athletic Equipment Storage Room 016	Door 1	Metal	Blue	Chipping	1	0.8	Positive
1	B	Stairwell adjacent to Staff Locker Room 014	Rail	Metal	Brown	Chipping	2	7.3	Positive
1	2	Hallway from Classrooms 218 to 221	W4	Plaster	White	None	0	>10	Positive
1	2	Hallway from Classrooms 218 to 221	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC 221	W2	Sheetrock	Blue	None	0	0	Negative
1	2	IMC 221	W2	Sheetrock	White	None	0	0.01	Negative
1	B	Fire Tower adjacent to Staff Locker Room 014	Ceiling	Concrete	White	Chipping	50	>10	Positive
1	4	Dance Locker Restroom	W1	Plaster	Green	Chipping	6	5.6	Positive
1	2	IMC 221	Baseboard	Wood	Brown	None	0	0.11	Negative
1	2	IMC 221	Ceiling	Plaster	White	None	0	>10	Positive
1	2	IMC 221	W1	Plaster	White	None	0	38.4	Positive
1	2	IMC 221	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC 221	W3	Plaster	White	None	0	33.6	Positive
1	4	Stairwell adjacent to Closet 400	Rail	Metal	Brown	Chipping	2	5.1	Positive
1	2	IMC 221	W1	Plaster	Blue	None	0	20.6	Positive
1	4	Fire Tower adjacent to Closet 400	Ceiling	Concrete	White	Flaking	50	8.7	Positive
1	2	IMC 221	Window Frame 1	Wood	Brown	None	0	0.14	Negative
1	2	IMC 221	Window Sill 1	Wood	Brown	None	0	0.11	Negative
1	2	IMC 221	Window Frame 2	Wood	Brown	None	0	0.11	Negative
1	2	IMC 221	Window Sill 2	Wood	Brown	None	0	0.04	Negative
1	2	IMC 221	Window Frame 3	Wood	Brown	None	0	0.12	Negative
1	2	IMC 221	Window Sill 3	Wood	Brown	None	0	0.5	Negative
1	2	IMC 221	Window Frame 4	Wood	Brown	None	0	0.07	Negative
1	2	IMC 221	Window Sill 4	Wood	Brown	None	0	0.3	Negative
1	2	IMC 221	Door Frame 1	Wood	Brown	None	0	0.1	Negative
1	2	IMC 221	Door 1	Wood	Brown	None	0	0.03	Negative
1	2	IMC 221	Door Frame 2	Wood	Brown	None	0	0.08	Negative
1	2	IMC 221	Door 2	Wood	Brown	None	0	0.06	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	IMC Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC Office	W1	Sheetrock	White	None	0	0	Negative
1	2	IMC Office	W1	Sheetrock	Blue	None	0	0	Negative
1	2	IMC Office	W2	Sheetrock	White	None	0	0	Negative
1	2	IMC Office	W2	Sheetrock	Blue	None	0	0	Negative
1	2	IMC Office	W3	Plaster	White	None	0	0	Negative
1	2	IMC Office	W3	Plaster	Blue	None	0	0	Negative
1	2	IMC Office	W4	Plaster	White	Chipping	4	0	Negative
1	2	IMC Office	W4	Plaster	Blue	None	0	0	Negative
1	2	IMC Office	Ceiling	Plaster	White	None	0	>10	Positive
1	2	IMC Storage Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC Storage Room	W1	Sheetrock	White	None	0	0	Negative
1	2	IMC Storage Room	W1	Sheetrock	Blue	None	0	0	Negative
1	2	IMC Storage Room	W2	Sheetrock	White	None	0	0	Negative
1	2	IMC Storage Room	W2	Sheetrock	Blue	None	0	0	Negative
1	2	IMC Storage Room	W3	Plaster	White	Chipping	4	0	Negative
1	2	IMC Storage Room	W4	Plaster	White	Chipping	4	0	Negative
1	2	IMC Storage Room	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Laptop Charging Room	W1	Plaster	White	None	0	0	Negative
1	2	Laptop Charging Room	W2	Sheetrock	White	None	0	0	Negative
1	2	Laptop Charging Room	W3	Plaster	White	None	0	0	Negative
1	2	Laptop Charging Room	W4	Plaster	White	None	0	0	Negative
1	2	Laptop Charging Room	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Laptop Charging Room	Door Frame	Wood	Brown	None	0	0.1	Negative
1	2	Laptop Charging Room	Window Sill	Wood	Brown	None	0	0.4	Negative
1	2	Laptop Charging Room	Door	Wood	Brown	None	0	0.1	Negative
1	2	Laptop Charging Room	Window Frame	Wood	Brown	None	0	0.2	Negative
1	2	Laptop Charging Room	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Laptop Charging Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 300	W4	Plaster	Pink	Chipping	1	38.9	Positive
1	3	Classroom 300	W1	Plaster	Pink	Cracking	5	37.5	Positive
1	3	Classroom 303	W2	Plaster	Pink	Alligatoring	15	32.7	Positive
1	3	Classroom 303	W2	Plaster	White	Alligatoring	10	39.6	Positive
1	3	Classroom 303	W3	Plaster	White	Efflorescence	15	4.4	Positive
1	2	Office 206	Door	Wood	Brown	None	0	0.08	Negative
1	2	Office 206	Baseboard	Wood	Brown	None	0	0.21	Negative
1	2	Office 206	Ceiling	Plaster	White	None	0	>10	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Office 206	W1	Plaster	Yellow	None	0	35.6	Positive
1	2	Office 206	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 206	Window Frame 1	Wood	Brown	None	0	0.18	Negative
1	2	Office 206	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	2	Office 206	Window Frame 2	Wood	Brown	None	0	0.1	Negative
1	2	Office 206	Window Sill 2	Wood	Brown	None	0	0.2	Negative
1	2	Office 206	Pipe 2	Metal	Yellow	None	0	29.6	Positive
1	2	Office 206	Door Frame	Wood	Brown	None	0	0.09	Negative
1	3	Classroom 303	W1	Plaster	Pink	Alligatoring	2	37.6	Positive
1	2	Office 219	Door	Wood	Brown	None	0	0.06	Negative
1	2	Office 219	Baseboard	Wood	Brown	None	0	0.09	Negative
1	2	Office 219	Window Frame	Wood	Brown	None	0	0.1	Negative
1	2	Office 219	W3	Plaster	Blue	None	0	0.19	Negative
1	2	Office 219	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Office 219	W1	Plaster	Blue	None	0	31	Positive
1	2	Office 219	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 219	W2	Plaster	Blue	None	0	28.9	Positive
1	2	Office 219	W1	Plaster	White	None	0	33	Positive
1	3	Classroom 303	W1	Plaster	White	Chipping	3	5.3	Positive
1	2	Office 219	W4	Plaster	Blue	None	0	1.8	Positive
1	2	Office 219	Pipe	Metal	Grey	None	0	1.2	Positive
1	2	Office 219	W3	Plaster	White	None	0	40.4	Positive
1	2	Office 219	W4	Plaster	White	None	0	22.7	Positive
1	2	Office 219	Door Frame	Wood	Brown	None	0	0.09	Negative
1	2	Office 219	Window Sill	Wood	Brown	None	0	0.16	Negative
1	2	Stairwell adjacent Classroom 200	W1	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 200	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 200	W2	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 200	W3	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 200	W4	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	W1	Plaster	Pink	Flaking	15	33.7	Positive
1	2	Stairwell adjacent Classroom 200	Riser	Concrete	Blue	None	0	5.4	Positive
1	2	Stairwell adjacent Classroom 200	Window Frame	Metal	Blue	None	0	9.6	Positive
1	2	Stairwell adjacent Classroom 200	Ceiling	Concrete	Blue	None	0	>10	Positive
1	2	Stairwell adjacent Classroom 205	W2	Metal	Blue	None	0	0.4	Negative
1	2	Stairwell adjacent Classroom 205	W1	ceramic tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 205	W3	ceramic tile	Unpainted	N/A	N/A	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	2	Stairwell adjacent Classroom 205	W4	Metal	Blue	None	0	0.5	Negative
1	2	Stairwell adjacent Classroom 205	Riser	Metal	Blue	None	0	>10	Positive
1	2	Stairwell adjacent Classroom 205	Ceiling	Metal	Blue	None	0	8	Positive
1	2	Stairwell adjacent Classroom 205	Floor	Cement	Grey	None	0	N/A	N/A
1	2	Stairwell adjacent Classroom 205	Hand Rail	Metal	Brown	Chipping	2	0.1	Negative
1	2	Stairwell adjacent Classroom 214	Door	Metal	Black	Flaking	2	0.1	Negative
1	2	Stairwell adjacent Classroom 214	Riser	Wood	Blue	None	0	6.8	Positive
1	2	Stairwell adjacent Classroom 214	Door Frame	Metal	Black	Flaking	1	0.2	Negative
1	2	Stairwell adjacent Classroom 214	Ceiling	Cement	Blue	None	0	8.7	Positive
1	2	Stairwell adjacent Classroom 214	Window Frame	Wood	Blue	None	0	9.6	Positive
1	2	Stairwell adjacent Classroom 214	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 214	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 214	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 214	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 214	Hand Rail	Metal	Brown	Chipping	1	0	Negative
1	2	Stairwell adjacent Classroom 214	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 218	W2	Metal	Blue	None	0	0	Negative
1	2	Stairwell adjacent Classroom 218	W4	Metal	Blue	None	0	0	Negative
1	2	Stairwell adjacent Classroom 218	Ceiling	Metal	Blue	None	0	>10	Positive
1	2	Stairwell adjacent Classroom 218	Riser	Wood	Blue	None	0	>10	Positive
1	2	Stairwell adjacent Classroom 218	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 218	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell adjacent Classroom 218	Handrail	Metal	Brown	None	0	9.6	Positive
1	2	Stairwell adjacent Classroom 218	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 300	Pipe 1	Metal	Pink	None	0	0.24	Negative
1	3	Classroom 300	Pipe 2	Metal	Pink	None	0	3	Positive
1	3	Classroom 300	W2	Plaster	Pink	None	0	1.4	Positive
1	3	Classroom 300	W3	Plaster	Pink	None	0	1.5	Positive
1	3	Classroom 304	W2	Plaster	Pink	Cracking	10	30.3	Positive
1	3	Classroom 304	W3	Plaster	Pink	Chipping	3	21.2	Positive
1	3	Classroom 300	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 300	Door	Wood	Brown	Chipping	1	0.06	Negative
1	3	Classroom 300	Door Frame	Wood	Brown	Chipping	1	0.04	Negative
1	3	Classroom 300	Baseboard	Wood	Brown	None	0	0.06	Positive
1	3	Classroom 300	Window Frame 1	Wood	Brown	None	0	0.13	Negative
1	3	Classroom 300	Window Frame 2	Wood	Brown	None	0	0.21	Negative
1	3	Classroom 300	Window Frame 3	Wood	Brown	None	0	0.09	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 300	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 302	Pipe	Metal	White	N/A	N/A	0.14	Negative
1	3	Classroom 302	W2	Plaster	Multi	None	0	38.2	Positive
1	3	Classroom 302	W2	Plaster	White	None	0	48.1	Positive
1	3	Classroom 302	W3	Plaster	White	None	0	38.6	Positive
1	3	Classroom 302	W3	Plaster	Pink	N/A	N/A	0	Negative
1	3	Classroom 302	W4	Plaster	White	None	0	45.9	Positive
1	3	Classroom 302	W4	Plaster	Pink	None	0	35.5	Positive
1	3	Classroom 302	W1	Plaster	Pink	None	0	27.8	Positive
1	3	Classroom 302	W1	Plaster	White	None	0	36.6	Positive
1	3	Classroom 302	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 302	Door	Wood	Brown	N/A	N/A	0.02	Negative
1	3	Classroom 302	Door Frame	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 302	Door	Wood	Brown	N/A	N/A	0.04	Negative
1	3	Classroom 302	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.4	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.32	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.14	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.23	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.31	Negative
1	3	Classroom 302	Baseboard	Wood	Brown	None	0	0.12	Negative
1	3	Classroom 302	Window Frame	Wood	Brown	N/A	N/A	0.13	Negative
1	3	Classroom 302	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 304	Pipe 2	Metal	Pink	Chipping	2	2	Positive
1	3	Classroom 305	Pipe 1	Metal	Pink	Chipping	3	15.8	Positive
1	3	Classroom 305	Pipe 3	Metal	Pink	Flaking	1	15.4	Positive
1	3	Classroom 303	W4	Plaster	Pink	N/A	N/A	0.22	Negative
1	3	Classroom 303	W4	Plaster	White	None	0	3.2	Positive
1	3	Classroom 305	Pipe 4	Metal	Pink	Flaking	2	6	Positive
1	3	Classroom 305	Radiator 2	Metal	Grey	Chipping	5	19.6	Positive
1	3	Classroom 303	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 303	Baseboard	Wood	Brown	None	0	1.4	Positive
1	3	Classroom 303	Window Frame	Wood	Brown	N/A	N/A	0.1	Negative
1	3	Classroom 303	Window Frame	Wood	Brown	N/A	N/A	0.04	Negative
1	3	Classroom 303	Window Frame	Wood	Brown	N/A	N/A	0.12	Negative
1	3	Classroom 303	Window Frame	Wood	Brown	N/A	N/A	0.08	Negative
1	3	Classroom 303	Window Frame	Wood	Brown	N/A	N/A	0.2	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130				
				Inspection Company: Viva		Franklin Learning Center				
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	3	Classroom 303	Door	Wood	Brown	N/A	N/A	0.31	Negative	
1	3	Classroom 303	Door	Wood	Brown	N/A	N/A	0.1	Negative	
1	3	Classroom 303	Door Frame	Wood	Brown	None	0	0.09	Negative	
1	3	Classroom 303	Door Frame	Wood	Brown	None	0	0.06	Negative	
1	3	Classroom 303	Ceiling	Plaster	White	None	0	>10	Positive	
1	3	Classroom 303	W3	Plaster	Pink	Efflorescence	20	0.25	Negative	
1	3	Classroom 303	Window Sill	Wood	Brown	Flaking	2	0.4	Negative	
1	3	Classroom 307	Pipe 2	Metal	White	Flaking	2	27.4	Positive	
1	3	Classroom 307	W3	Plaster	White	Cracking	5	46.3	Positive	
1	3	Classroom 307	W4	Plaster	White	Flaking	10	43.2	Positive	
1	3	Classroom 304	W4	Plaster	Pink	None	0	46	Positive	
1	3	Classroom 304	W1	Plaster	Green	None	0	34.6	Positive	
1	3	Classroom 304	W1	Plaster	Blue	None	0	34.6	Positive	
1	3	Classroom 304	Pipe 1	Metal	Pink	None	0	0	Negative	
1	3	Classroom 304	Window Frame 1	Wood	Brown	None	0	0.12	Negative	
1	3	Classroom 304	Window Sill 1	Wood	Brown	None	0	0.11	Negative	
1	3	Classroom 304	Window Frame 2	Wood	Brown	None	0	0.09	Negative	
1	3	Classroom 304	Window Sill 2	Wood	Brown	None	0	0.3	Negative	
1	3	Classroom 304	Window Frame 3	Wood	Brown	None	0	0.1	Negative	
1	3	Classroom 304	Window Sill 3	Wood	Brown	None	0	0.3	Negative	
1	3	Classroom 304	Door Frame	Wood	Brown	None	0	0.09	Negative	
1	3	HRT Room	Ceiling	Plaster	White	Cracking	5	>10	Positive	
1	3	Classroom 304	Door	Wood	Brown	None	0	0.12	Negative	
1	3	Classroom 304	Baseboard	Wood	Brown	None	0	0.12	Negative	
1	3	Classroom 304	Ceiling	Plaster	White	None	0	>10	Positive	
1	3	Classroom 304	Floor	Wood	Unpainted	None	0	N/A	N/A	
1	3	Classroom 305	Door	Metal	Brown	None	0	0.05	Negative	
1	3	Classroom 305	W1	Plaster	Pink	None	0	47.4	Positive	
1	3	Classroom 305	W2	Plaster	Pink	None	0	42.4	Positive	
1	3	Classroom 305	W3	Plaster	Pink	None	0	2.2	Positive	
1	3	Classroom 305	W4	Plaster	Pink	None	0	31.4	Positive	
1	3	Classroom 305	Door Frame	Metal	Brown	None	0	0.02	Negative	
1	3	HRT Room	Radiator	Metal	Grey	Chipping	1	16.7	Positive	
1	3	Classroom 305	Pipe 2	Metal	Pink	None	0	0.08	Negative	
1	3	Classroom 305	Window Frame 1	Wood	Brown	None	0	0.11	Negative	
1	3	Classroom 305	Window Sill 1	Wood	Brown	None	0	0.15	Negative	
1	3	Classroom 305	Radiator 3	Metal	Grey	None	0	7.8	Positive	

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 312	Pipe 2	Metal	Pink	Flaking	2	16.4	Positive
1	3	Classroom 312	W1	Plaster	Pink	Peeling	3	29.3	Positive
1	3	Classroom 305	Baseboard	Wood	Brown	None	0	0.12	Negative
1	3	Classroom 305	Radiator 1	Metal	Grey	Chipping	2	0.04	Negative
1	3	Classroom 312	W2	Plaster	Pink	Cracking	2	37.6	Positive
1	3	Classroom 305	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 305	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Classroom 312	W3	Plaster	Pink	Flaking	2	35.5	Positive
1	3	Classroom 307	W1	Plaster	White	None	0	47.3	Positive
1	3	Classroom 307	W2	Plaster	White	None	0	40.7	Positive
1	3	Classroom 312	W4	Plaster	Pink	Flaking	2	35.7	Positive
1	3	Office 312A	Radiator	Metal	Grey	Flaking	1	5.1	Positive
1	3	Classroom 307	Door Frame	Wood	Brown	None	0	0.07	Negative
1	3	Classroom 307	Window Frame 1	Wood	Brown	None	0	0.23	Negative
1	3	Classroom 307	Window Sill 1	Wood	Brown	None	0	0.3	Negative
1	3	Classroom 307	Window Frame 2	Wood	Brown	None	0	0.26	Negative
1	3	Classroom 307	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 307	Window Frame 3	Wood	Brown	None	0	0.22	Negative
1	3	Classroom 307	Window Sill 3	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 307	Window Frame 4	Wood	Brown	None	0	0.3	Negative
1	3	Classroom 307	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 307	Pipe 1	Metal	White	None	0	0.11	Negative
1	3	Classroom 307	Pipe 3	Metal	White	None	0	0.02	Negative
1	3	Classroom 307	Baseboard	Wood	Brown	None	0	4.8	Positive
1	3	Classroom 307	Door	Wood	Brown	None	0	0.09	Negative
1	3	Classroom 307	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 307	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Office 312A	Radiator	Metal	Grey	Flaking	1	4.9	Positive
1	3	Classroom 312	Pipe	Metal	Pink	None	0	13.9	Positive
1	3	Men's Restroom on 3rd Floor	Ceiling	Plaster	White	Flaking	100	>10	Positive
1	3	Men's Restroom on 3rd Floor	W4	Plaster	Blue	Cracking	10	8.5	Positive
1	3	Men's Restroom on 3rd Floor	W1	Plaster	Blue	Cracking	10	5.5	Positive
1	3	Women's Restroom on 3rd Floor	Radiator	Metal	Grey	Chipping	2	5.4	Positive
1	3	Classroom 312	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 312	Baseboard	Wood	Brown	None	0	4.2	Positive
1	3	Classroom 312	Window Frame 1	Wood	Brown	None	0	0.17	Negative
1	3	Classroom 312	Window Sill 1	Wood	Brown	None	0	0.5	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 312	Window Frame 2	Wood	Brown	None	0	0.15	Negative
1	3	Classroom 312	Window Sill 2	Wood	Brown	None	0	0.25	Negative
1	3	Classroom 312	Window Frame 3	Wood	Brown	None	0	0.3	Negative
1	3	Classroom 312	Window Sill 3	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 312	Door Frame 1	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 312	Door 1	Wood	Brown	None	0	0.04	Negative
1	3	Classroom 312	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 316	Door	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 316	W2	Plaster	Pink	None	0	32.9	Positive
1	3	Classroom 316	W2	Plaster	White	None	0	41.3	Positive
1	3	Classroom 316	W3	Plaster	Pink	N/A	N/A	0.06	Negative
1	3	Classroom 316	W3	Plaster	White	None	0	40	Positive
1	3	Women's Restroom on 3rd Floor	Pipe 3	Metal	Green	Flaking	5	1.4	Positive
1	3	Classroom 316	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 316	W4	Plaster	White	None	0	43.1	Positive
1	3	Classroom 316	W1	Plaster	Pink	None	0	30.9	Positive
1	3	Classroom 316	W1	Plaster	White	None	0	40.6	Positive
1	3	Classroom 316	Floor	Wood	Glazed	N/A	N/A	N/A	N/A
1	3	Classroom 316	Baseboard	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 316	Door Frame	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 316	Window Sill	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 316	Window Frame	Wood	Brown	N/A	N/A	0.1	Negative
1	3	Classroom 316	Window Frame	Wood	Brown	N/A	N/A	0.14	Negative
1	3	Classroom 316	Window Frame	Wood	Brown	N/A	N/A	0.12	Negative
1	3	Classroom 317	W1	Plaster	Pink	None	0	0	Negative
1	3	Classroom 317	W2	Plaster	Pink	Flaking	3	0	Negative
1	3	Classroom 317	W4	Plaster	Pink	Flaking	1	0.01	Negative
1	3	Women's Restroom on 3rd Floor	W1	Plaster	Green	Cracking	5	40.4	Positive
1	3	Classroom 317	Baseboard	Concrete	Brown	None	0	9.3	Positive
1	3	Classroom 317	Pipe 2	Metal	Pink	None	0	0.2	Negative
1	3	Classroom 317	Pipe 3	Metal	Pink	None	0	0.13	Negative
1	3	Classroom 317	Window Frame 1	Wood	Brown	None	0	1.3	Positive
1	3	Classroom 317	Window Sill 1	Wood	Brown	None	0	0.6	Negative
1	3	Classroom 317	Window Frame 2	Wood	Brown	None	0	0.27	Negative
1	3	Classroom 317	Window Frame 3	Wood	Brown	None	0	0.21	Negative
1	3	Classroom 317	Window Sill 3	Wood	Brown	None	0	0.29	Negative
1	3	Classroom 317	Window Frame 4	Wood	Brown	None	0	0.29	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 317	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 317	Window Frame 5	Wood	Brown	None	0	1.6	Positive
1	3	Classroom 317	Window Sill 5	Wood	Brown	None	0	1.2	Positive
1	3	Classroom 317	Door 1	Wood	Brown	None	0	0.09	Negative
1	3	Classroom 317	Door Frame 1	Wood	Brown	None	0	0.01	Negative
1	3	Classroom 317	Door 2	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 317	Door Frame 2	Wood	Brown	None	0	0.07	Negative
1	3	Classroom 317	W3	Plaster	Pink	None	0	0.12	Negative
1	3	Classroom 317	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 317	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Women's Restroom on 3rd Floor	W2	Plaster	Green	Cracking	5	37.1	Positive
1	3	Women's Restroom on 3rd Floor	W3	Plaster	Blue	Cracking	10	11	Positive
1	3	Classroom 318	W1	Plaster	Green	None	0	0	Negative
1	3	Classroom 318	W2	Plaster	Green	None	0	0	Negative
1	3	Classroom 318	W4	Plaster	Green	None	0	0	Negative
1	3	Classroom 318	Pipe	Metal	White	Chipping	2	0.01	Negative
1	3	Classroom 318	W3	Plaster	Green	None	0	0.03	Negative
1	3	Classroom 318	Door	Wood	Brown	None	0	0.03	Negative
1	3	Classroom 318	Baseboard	Concrete	Brown	None	0	10	Positive
1	3	Classroom 318	W1	Plaster	White	None	0	42.6	Positive
1	3	Women's Restroom on 3rd Floor	W3	Plaster	Green	Cracking	5	40	Positive
1	3	Classroom 318	W3	Plaster	White	None	0	1.3	Positive
1	3	Classroom 318	W4	Plaster	White	None	0	1.5	Positive
1	3	Classroom 318	Door Frame	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 318	Window Frame 1	Wood	Brown	None	0	0.15	Negative
1	3	Classroom 318	Window Sill 1	Wood	Brown	None	0	0.5	Negative
1	3	Classroom 318	Window Frame 2	Wood	Brown	None	0	0.21	Negative
1	3	Classroom 318	Window Sill 2	Wood	Brown	None	0	0.5	Negative
1	3	Classroom 318	Window Frame 3	Wood	Brown	None	0	0.17	Negative
1	3	Classroom 318	Window Sill 3	Wood	Brown	None	0	1	Positive
1	3	Classroom 318	Window Frame 4	Wood	Brown	None	0	0.13	Negative
1	3	Classroom 318	Window Sill 4	Wood	Brown	None	0	1.2	Positive
1	3	Classroom 318	Window Frame 5	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 318	Window Sill 5	Wood	Brown	None	0	0.22	Negative
1	3	Classroom 318	Door Frame 2	Wood	Brown	None	0	0.13	Negative
1	3	Classroom 318	Door 2	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 318	Floor	Wood	Unpainted	None	0	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 319	Door	Metal	Brown	None	0	0.02	Positive
1	3	Classroom 319	Door Frame	Metal	Brown	None	0	0.04	Negative
1	3	Classroom 319	W2	Plaster	White	None	0	24.8	Positive
1	3	Classroom 319	W3	Plaster	White	None	0	0.19	Positive
1	3	Classroom 319	W4	Plaster	White	None	0	22.3	Positive
1	3	Classroom 319	W1	Plaster	White	None	0	30.9	Positive
1	3	Classroom 319	Window Frame 1	Wood	Brown	None	0	0.09	Negative
1	3	Classroom 319	Window Frame 2	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 319	Window Sill 1	Wood	Brown	None	0	1.7	Positive
1	3	Classroom 319	Window Sill 2	Wood	Brown	None	0	1.7	Positive
1	3	Classroom 319	Baseboard	Wood	Brown	None	0	0.12	Positive
1	3	Classroom 319	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 319	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Classroom 320	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 320	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	Classroom 321	Floor	Wood	Brown	None	0	N/A	Positive
1	3	Girl's Restroom on 3rd Floor	Pipe 2	Metal	Blue	Chipping	1	11	Positive
1	3	Girl's Restroom on 3rd Floor	W3	Plaster	Blue	Cracking	30	18.1	Positive
1	3	Girl's Restroom on 3rd Floor	W1	Plaster	Blue	Cracking	20	33.9	Positive
1	3	Classroom 321	W2	Sheetrock	Pink	None	0	0.04	Positive
1	3	Classroom 321	Window Sill	Wood	Brown	None	0	0.23	Negative
1	3	Classroom 321	Window Frame	Wood	Brown	None	0	0.07	Positive
1	3	Classroom 321	Baseboard	Wood	Brown	None	0	0.17	Positive
1	3	Classroom 321	Door	Wood	Brown	None	0	0.07	Positive
1	3	Classroom 321	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 321	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 321	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 323	Pipe	Metal	Grey	None	0	38.2	Positive
1	3	Girl's Restroom on 3rd Floor	W2	Plaster	Blue	Cracking	20	32.7	Positive
1	3	Classroom 316	W4	Plaster	Pink	Cracking	2	27.4	Positive
1	3	Classroom 317	Pipe 1	Metal	Pink	Cracking	1	31.7	Positive
1	3	Classroom 317	Window Sill 2	Wood	Brown	Chipping	1	1.3	Positive
1	3	Classroom 323	Door Frame	Wood	Brown	None	0	0.07	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 323	Window Frame 1	Wood	Brown	None	0	0.1	Negative
1	3	Classroom 323	Window Frame 2	Wood	Brown	None	0	0.16	Negative
1	3	Classroom 323	Window Sill 1	Wood	Brown	None	0	0.23	Negative
1	3	Classroom 323	Window Sill 2	Wood	Brown	None	0	0.26	Negative
1	3	Classroom 323	Door	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 323	Baseboard	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 323	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Classroom 323	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Closet 318	Ceiling	Plaster	White	Cracking	5	>10	Positive
1	3	Classroom 324	Pipe	Metal	Pink	None	0	24.5	Positive
1	3	Classroom 318	Ceiling	Plaster	White	Cracking	5	>10	Positive
1	3	Classroom 318	W2	Plaster	White	Flaking	1	1.6	Positive
1	3	Office 320 (IDF-2)	Radiator	Metal	Grey	Flaking	2	5.6	Positive
1	3	Office 320 (IDF-2)	W2	Plaster	White	Chipping	1	35.1	Positive
1	3	Classroom 324	Door	Wood	Brown	None	0	0.06	Positive
1	3	Classroom 324	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	Classroom 324	Window Frame 1	Wood	Brown	None	0	0.11	Negative
1	3	Classroom 324	Window Frame 2	Wood	Brown	None	0	0.28	Negative
1	3	Classroom 324	Baseboard	Wood	Brown	None	0	0.11	Positive
1	3	Classroom 324	Window Sill 1	Wood	Brown	None	0	0.25	Negative
1	3	Classroom 324	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 324	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Office 320 (IDF-2)	W4	Plaster	White	Alligating	5	40.6	Positive
1	3	Classroom 323	W1	Plaster	Pink	Cracking	15	32.7	Positive
1	3	Classroom 323	W2	Plaster	Pink	Cracking	10	29.3	Positive
1	3	Classroom 325	W3	Plaster	Pink	Flaking	1	0.02	Negative
1	3	Classroom 323	W3	Plaster	Pink	Cracking	20	29.9	Positive
1	3	Classroom 323	W4	Plaster	Pink	Cracking	20	43.5	Positive
1	3	Classroom 325	W4	Plaster	White	None	0	49.1	Positive
1	3	Classroom 323	Radiator	Metal	Grey	Flaking	2	17.4	Positive
1	3	Classroom 324	W2	Plaster	Pink	Flaking	5	35.1	Positive
1	3	Classroom 325	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 325	Door Frame	Wood	Brown	None	0	0.09	Negative
1	3	Classroom 325	Door	Wood	Brown	None	0	0.05	Positive
1	3	Classroom 325	Baseboard	Wood	Brown	None	0	0.07	Positive
1	3	Classroom 325	Window Sill	Wood	Brown	None	0	0.27	Negative
1	3	Classroom 325	Window Frame	Wood	Brown	None	0	0.11	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 325	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Closet 307/309	W1	Plaster	Pink	None	0	32.8	Positive
1	3	Closet 307/309	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Closet 307/309	W2	Plaster	Pink	None	0	31	Positive
1	3	Closet 307/309	W3	Plaster	Pink	None	0	27.4	Positive
1	3	Closet 307/309	W4	Plaster	Pink	None	0	26.6	Positive
1	3	Closet 307/309	Pipe 1	Metal	Pink	None	0	28.2	Positive
1	3	Closet 307/309	Door Frame	Wood	Brown	None	0	0.05	Negative
1	3	Closet 307/309	Door	Wood	Brown	None	0	0.09	Negative
1	3	Closet 307/309	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Closet 309	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Closet 309	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Closet 309	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Closet 309	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Closet 309	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	Closet 309	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Closet 314	Baseboard	Wood	Brown	None	0	0.1	Negative
1	3	Closet 314	W1	Plaster	Pink	None	0	39.3	Positive
1	3	Closet 314	W2	Plaster	Pink	None	0	41.9	Positive
1	3	Classroom 324	W3	Plaster	Pink	Flaking	15	46.1	Positive
1	3	Closet 314	W4	Plaster	Pink	None	0	35.6	Positive
1	3	Closet 314	Pipe	Metal	Pink	None	0	3.1	Positive
1	3	Closet 314	Window Frame 1	Wood	Brown	None	0	0.4	Negative
1	3	Closet 314	Window Sill 1	Wood	Brown	None	0	0.19	Negative
1	3	Closet 314	Window Frame 2	Wood	Brown	None	0	0.1	Negative
1	3	Closet 314	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	3	Closet 314	Door 1	Wood	Brown	None	0	0.08	Negative
1	3	Closet 314	Door Frame 1	Wood	Brown	None	0	0.11	Negative
1	3	Closet 314	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Closet 314	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Classroom 324	W4	Plaster	Pink	Cracking	2	33.1	Positive
1	3	Classroom 324	W1	Plaster	Pink	Flaking	10	38.3	Positive
1	3	Closet 318	W1	Plaster	White	none	0	0	Negative
1	3	Closet 318	W3	Plaster	White	None	0	0	Negative
1	3	Closet 318	W4	Plaster	White	None	0	0	Negative
1	3	Closet 318	W2	Sheetrock	White	None	0	0	Negative
1	3	Closet 318	Baseboard	Wood	Brown	None	0	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Closet 318	Door Frame 1	Wood	Brown	None	0	0.06	Negative
1	3	Closet 318	Door 1	Wood	Brown	None	0	0.12	Negative
1	3	Closet 318	Door Frame 2	Wood	Brown	None	0	0.16	Negative
1	3	Closet 318	Door 2	Wood	Brown	None	0	0.1	Negative
1	3	Closet 318	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Custodial Closet across from 301	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 324	Radiator	Metal	Grey	Chipping	5	15.5	Positive
1	3	Custodial Closet across from 301	Door Frame	Wood	Brown	None	0	0.18	Negative
1	3	Custodial Closet across from 301	Pipe	Metal	White	None	0	17.6	Positive
1	3	Custodial Closet across from 301	Door	Wood	Brown	N/A	N/A	0	Negative
1	3	Classroom 325	W2	Plaster	White	Flaking	1	42	Positive
1	3	Custodial Closet across from 301	W2	Plaster	White	Chipping	5	0	Negative
1	3	Custodial Closet across from 301	W3	Plaster	White	Efflorescence	10	0.02	Negative
1	3	Custodial Closet across from 301	W4	Plaster	White	Flaking	10	0	Negative
1	3	Custodial Closet across from 301	Window Frame	Wood	Brown	None	0	0	Negative
1	3	Custodial Closet across from 301	Window Sill	Wood	Brown	None	0	0.4	Negative
1	3	Fire Tower adjacent Classroom 300	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 325	W2	Plaster	Pink	Flaking	1	36.4	Positive
1	3	Fire Tower adjacent Classroom 300	W1	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 300	W2	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 300	W3	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 300	W4	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	Door Frame	Metal	Brown	Flaking	5	0.1	Negative
1	3	Fire Tower adjacent Classroom 320	Door	Metal	Brown	Flaking	5	0.4	Negative
1	3	Fire Tower adjacent Classroom 320	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Tower adjacent Classroom 320	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom on 3rd Floor	W4	CMU	Blue	None	0	0	Negative
1	3	Girl's Restroom on 3rd Floor	W1	Brick	White	None	0	0.01	Negative
1	3	Girl's Restroom on 3rd Floor	W2	Brick	Brown	Peeling	5	0.02	Negative
1	3	Girl's Restroom on 3rd Floor	Floor	Concrete	Brown	Friction	15	0.04	Negative
1	3	Girl's Restroom on 3rd Floor	W2	Brick	White	None	0	0.05	Negative
1	3	Classroom 325	W3	Plaster	White	Efflorescence	15	46.8	Positive
1	3	Girl's Restroom on 3rd Floor	Ceiling	Plaster	White	None	0	>10	Positive

		Dates: 1/17/23-1/27/23, 5/19/23			Lead-Safe Certification Assessment Report				
		Inspector Name and Certificate Number: Erik Swanson 006917			616 N. 15th Street, Philadelphia, PA 19130				
		Inspection Company: Viva			Franklin Learning Center				
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Classroom 325	W4	Plaster	Pink	Alligatoring	2	34.9	Positive
1	3	Classroom 325	W1	Plaster	White	Flaking	1	43.4	Positive
1	3	Classroom 325	W1	Plaster	Pink	Flaking	1	41	Positive
1	3	Girl's Restroom on 3rd Floor	W3	Brick	Blue	None	0	5.4	Positive
1	3	Girl's Restroom on 3rd Floor	Pipe 1	Metal	Blue	None	0	0	Negative
1	3	Girl's Restroom on 3rd Floor	Pipe 3	Metal	Blue	None	0	0	Negative
1	3	Girl's Restroom on 3rd Floor	Baseboard	Concrete	Brown	None	0	6.3	Positive
1	3	Girl's Restroom on 3rd Floor	Door Frame	Wood	White	None	0	0.1	Negative
1	3	Hallway from Classrooms 300 to 319	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 300 to 319	W2	Plaster	Purple	None	0	0.03	Negative
1	3	Hallway from Classrooms 300 to 319	Baseboard	Concrete	Brown	None	0	11.9	Positive
1	3	Hallway from Classrooms 300 to 319	W2	Plaster	White	None	0	39.1	Positive
1	3	Custodial Closet across from 301	Ceiling	Concrete	White	Flaking	10	1.1	Positive
1	3	Custodial Closet across from 301	W1	Plaster	White	Efflorescence	5	15	Positive
1	3	Hallway from Classrooms 300 to 319	Window Sill 1	Wood	Brown	None	0	0.28	Negative
1	3	Hallway from Classrooms 300 to 319	Window Sill 2	Wood	Brown	None	0	0.24	Negative
1	3	Hallway from Classrooms 300 to 319	Window Sill 3	Wood	Brown	None	0	0.8	Positive
1	3	Hallway from Classrooms 300 to 319	Window Sill 4	Wood	Brown	None	0	0.4	Negative
1	3	Hallway from Classrooms 300 to 319	Window Sill 5	Wood	Brown	None	0	0.29	Negative
1	3	Hallway from Classrooms 300 to 319	Window Sill 6	Wood	Brown	None	0	0.5	Negative
1	3	Hallway from Classrooms 300 to 319	Window Sill 7	Wood	Brown	None	0	0.23	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 1	Wood	Brown	None	0	0.08	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 2	Wood	Brown	None	0	0.27	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 3	Wood	Brown	None	0	0.22	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 4	Wood	Brown	None	0	0.15	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 5	Wood	Brown	None	0	0.19	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 6	Wood	Brown	None	0	0.11	Negative
1	3	Hallway from Classrooms 300 to 319	Window Frame 7	Wood	Brown	None	0	0.1	Negative
1	3	Hallway from Classrooms 300 to 319	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Office 306 (IDF-3)	Pipe 1	Metal	White	Cracking	2	17.1	Positive
1	3	Office 306 (IDF-3)	Pipe 2	Metal	White	Chipping	4	16.1	Positive
1	3	Office 306 (IDF-3)	Pipe 3	Metal	White	Flaking	1	14.2	Positive
1	3	Hallway from Classrooms 301 to 304	W1	Plaster	Purple	None	0	0	Negative
1	3	Hallway from Classrooms 301 to 304	W1	CMU	Purple	None	0	0.03	Negative
1	3	Hallway from Classrooms 301 to 304	W1	CMU	White	None	0	0.04	Negative
1	3	Hallway from Classrooms 301 to 304	Baseboard	Concrete	Brown	None	0	11.1	Positive
1	3	Hallway from Classrooms 301 to 304	W3	Plaster	White	None	0	7.8	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Hallway from Classrooms 301 to 304	W3	Plaster	Multi	None	0	1.5	Positive
1	3	Hallway from Classrooms 301 to 304	W4	plaster	Purple	None	0	28	Positive
1	3	Hallway from Classrooms 301 to 304	W4	Plaster	White	None	0	41.6	Positive
1	3	Hallway from Classrooms 301 to 304	W1	Plaster	White	None	0	37.5	Positive
1	3	Hallway from Classrooms 301 to 304	Window Frame 1	Wood	Brown	None	0	0.18	Negative
1	3	Hallway from Classrooms 301 to 304	Window Sill 1	Wood	Brown	None	0	0.5	Negative
1	3	Hallway from Classrooms 301 to 304	Window Frame 2	Wood	Brown	None	0	0.16	Negative
1	3	Hallway from Classrooms 301 to 304	Window Sill 2	Wood	Brown	None	0	0.4	Negative
1	3	Hallway from Classrooms 301 to 304	Window Frame 3	Wood	Brown	None	0	0.22	Negative
1	3	Hallway from Classrooms 301 to 304	Window Sill 3	Wood	Brown	None	0	0.17	Negative
1	3	Hallway from Classrooms 301 to 304	Window Frame 4	Wood	Brown	None	0	0.21	Negative
1	3	Hallway from Classrooms 301 to 304	Window Sill 4	Wood	Brown	None	0	0.3	Negative
1	3	Hallway from Classrooms 301 to 304	Floor	Concrete	Grey	None	0	N/A	N/A
1	3	Office 306 (IDF-3)	W2	Plaster	White	Cracking	1	42.6	Positive
1	3	Office 306 (IDF-3)	W4	Plaster	White	Cracking	2	52.9	Positive
1	3	Closet 314	W3	Plaster	Pink	Cracking	1	38.9	Positive
1	3	Hallway from Classrooms 305 to 320	W4	Plaster	Purple	None	0	0	Negative
1	3	Hallway from Classrooms 305 to 320	W2	Plaster	White	None	0	39.8	Positive
1	3	Hallway from Classrooms 305 to 320	W2	Plaster	Purple	None	0	28.1	Positive
1	3	Hallway from Classrooms 305 to 320	W4	Plaster	White	None	0	43.4	Positive
1	3	Hallway from Classrooms 305 to 320	Baseboard	Wood	Brown	None	0	7	Positive
1	3	Hallway from Classrooms 305 to 320	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Closet 314	Radiator	Metal	Grey	Chipping	2	3.9	Positive
1	3	Hallway from Classrooms 316 to 318	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	3	Hallway from Classrooms 316 to 318	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Hallway from Classrooms 316 to 318	Baseboard	Concrete	Brown	None	0	9.2	Positive
1	3	Hallway from Classrooms 316 to 318	W1	Plaster	Purple	None	0	38.2	Positive
1	3	Hallway from Classrooms 316 to 318	W2	Plaster	Purple	None	0	30.9	Positive
1	3	Hallway from Classrooms 316 to 318	W2	Plaster	White	None	0	44.3	Positive
1	3	Classroom 321	W3	Plaster	Pink	Chipping	50	10.1	Positive
1	3	Hallway from Classrooms 316 to 318	W3	Plaster	White	None	0	45.1	Positive
1	3	Hallway from Classrooms 316 to 318	W4	Plaster	Purple	None	0	29.2	Positive
1	3	Hallway from Classrooms 316 to 318	W4	Plaster	White	None	0	43.1	Positive
1	3	Hallway from Classrooms 316 to 318	Window Frame 1	Wood	Brown	None	0	0.19	Negative
1	3	Hallway from Classrooms 316 to 318	Window Frame 2	Wood	Brown	None	0	0.18	Negative
1	3	Hallway from Classrooms 316 to 318	Window Frame 3	Wood	Brown	None	0	0.12	Negative
1	3	Hallway from Classrooms 316 to 318	Window Frame 4	Wood	Brown	None	0	0.25	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Hallway from Classrooms 316 to 318	Window Frame 5	Wood	Brown	None	0	0.24	Negative
1	3	Hallway from Classrooms 316 to 318	Window Sill 1	Wood	Brown	None	0	0.2	Negative
1	3	Hallway from Classrooms 316 to 318	Window Sill 2	Wood	Brown	None	0	0.12	Negative
1	3	Hallway from Classrooms 316 to 318	Window Sill 3	Wood	Brown	None	0	0.4	Negative
1	3	Hallway from Classrooms 316 to 318	Window Sill 4	Wood	Brown	None	0	0.23	Negative
1	3	Hallway from Classrooms 316 to 318	Window Sill 5	Wood	Brown	None	0	0.4	Negative
1	3	Classroom 321	W4	Plaster	Pink	Chipping	50	44.1	Positive
1	3	Classroom 321	W1	Plaster	Pink	Chipping	30	40.8	Positive
1	3	Hallway from Classrooms 300 to 319	W4	Plaster	Purple	Flaking	2	38.7	Positive
1	3	Hallway from Classrooms 300 to 319	W4	Plaster	White	Alligatoring	5	45.1	Positive
1	3	Hallway from Classrooms 300 to 319	Radiator 1	Metal	Grey	Chipping	1	12.6	Positive
1	3	HRT Room	Door	Wood	Brown	None	0	0.02	Negative
1	3	HRT Room	Baseboard	Wood	Brown	None	0	0.08	Negative
1	3	HRT Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	HRT Room	W1	Plaster	White	None	0	33.4	Positive
1	3	HRT Room	W2	Plaster	White	None	0	30.1	Positive
1	3	HRT Room	W3	Plaster	White	None	0	39.7	Positive
1	3	HRT Room	W4	Plaster	White	None	0	1.4	Positive
1	3	HRT Room	Window Frame 1	Wood	Brown	none	0	0.4	Negative
1	3	HRT Room	Window Sill 1	Wood	Brown	none	0	0.12	Negative
1	3	HRT Room	Pipe	Metal	White	None	0	16.7	Positive
1	3	HRT Room	Frame	Wood	Brown	None	0	0.06	Negative
1	3	Men's Restroom on 3rd Floor	Floor	Concrete	Brown	Cracking	10	0.02	Negative
1	3	Men's Restroom on 3rd Floor	Pipe	Metal	White	Flaking	20	0.09	Negative
1	3	Men's Restroom on 3rd Floor	W1	Brick	Blue	Chipping	1	0.01	Negative
1	3	Men's Restroom on 3rd Floor	W2	Plaster	Blue	Efflorescence	15	0	Negative
1	3	Hallway from Classrooms 300 to 319	Radiator 3	Metal	Grey	Chipping	1	10.1	Positive
1	3	Men's Restroom on 3rd Floor	W2	Brick	Blue	N/A	N/A	0.01	Negative
1	3	Men's Restroom on 3rd Floor	W4	Brick	Blue	Cracking	50	0	Negative
1	3	Men's Restroom on 3rd Floor	W2	CMU	Blue	N/A	N/A	0.01	Negative
1	3	Men's Restroom on 3rd Floor	Baseboard	Concrete	Brown	None	0	7.9	Positive
1	3	Men's Restroom on 3rd Floor	Pipe	Metal	Blue	N/A	N/A	0.08	Negative
1	3	Hallway from Classrooms 300 to 319	Radiator 3	Metal	Grey	Chipping	1	10.2	Positive
1	3	Hallway from Classrooms 305 to 320	Radiator	Metal	Grey	Chipping	1	9.3	Positive
1	3	Men's Restroom on 3rd Floor	Door Frame	Wood	White	None	0	0.16	Negative
1	3	Men's Restroom on 3rd Floor	W3	CMU	Blue	None	0	0	Negative
1	3	Office 306 (IDF-3)	Radiator	Metal	white	none	0	2.8	Positive

				Dates: 1/17/23-1/27/23, 5/19/23	Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Erik Swanson 006917	616 N. 15th Street, Philadelphia, PA 19130				
				Inspection Company: Viva	Franklin Learning Center				
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Hallway from Classrooms 316 to 318	W3	Plaster	Purple	Efflorescence	20	1.7	Positive
1	3	Hallway from Classrooms 316 to 318	Radiator 1	Wood	Brown	Chipping	1	10.1	Positive
1	3	Office 306 (IDF-3)	Baseboard	Wood	Brown	None	0	0.06	Negative
1	3	Office 306 (IDF-3)	Door	Wood	Brown	None	0	0.06	Negative
1	3	Hallway from Classrooms 316 to 318	Radiator 2	Wood	Brown	Chipping	1	10	Positive
1	3	Office 306 (IDF-3)	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Office 306 (IDF-3)	W1	Plaster	White	None	0	34.5	Positive
1	3	Office 306 (IDF-3)	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 316 to 318	Radiator 3	Wood	Brown	Chipping	1	13.8	Positive
1	3	Office 306 (IDF-3)	W3	Plaster	White	None	0	44	Positive
1	3	Hallway from Classrooms 301 to 304	Radiator 1	Metal	Grey	chipping	1	1	Positive
1	3	Office 306 (IDF-3)	Window Sill 1	Wood	Brown	None	0	0.4	Negative
1	3	Office 306 (IDF-3)	Window Sill 2	Wood	Brown	None	0	0.3	Negative
1	3	Office 306 (IDF-3)	Window Frame 1	Wood	Brown	None	0	0.3	Negative
1	3	Office 306 (IDF-3)	Window Frame 2	Wood	Brown	None	0	0.16	Negative
1	3	Office 306 (IDF-3)	Door Frame	Wood	Brown	None	0	0.06	Negative
1	3	Hallway from Classrooms 301 to 304	Radiator 2	Metal	Grey	chipping	1	10.8	Positive
1	3	Hallway from Classrooms 301 to 304	Radiator 4	Metal	Grey	chipping	1	12	Positive
1	3	Office 312A	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Office 312A	Pipe	Metal	Pink	None	0	20.7	Positive
1	3	Office 312A	W2	Plaster	Pink	None	0	0.9	Positive
1	3	Office 312A	W3	Plaster	Pink	None	0	33.3	Positive
1	3	Office 312A	W4	Plaster	Pink	None	0	40.5	Positive
1	3	Office 312A	W1	Plaster	Pink	None	0	31.7	Positive
1	3	Office 312A	Window Frame	Wood	Brown	N/A	N/A	0.28	Negative
1	3	Office 312A	Window Frame	Wood	Brown	N/A	N/A	0.15	Negative
1	3	Office 312A	Door	Wood	Brown	N/A	N/A	0.05	Negative
1	3	Office 312A	Door Frame	Wood	Brown	None	0	0.09	Negative
1	3	Office 312A	Window Sill	Wood	Brown	None	0	0.4	Negative
1	3	Office 312A	Baseboard	Wood	Brown	None	0	0.14	Negative
1	3	Office 312A	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell adjacent Classroom 300	Rail	Metal	Brown	Chipping	2	5.3	Positive
1	3	Office 320 (IDF-2)	Ceiling	Plaster	White	None	0	>10	Positive
1	3	Office 320 (IDF-2)	Pipe	Metal	White	None	0	0.28	Positive
1	3	Fire Tower adjacent Classroom 300	Ceiling	Concrete	White	Chipping	50	>10	Positive
1	3	Office 320 (IDF-2)	W3	Plaster	White	None	0	0.02	Positive
1	3	Stairwell adjacent Classroom 320	Hand Rail	Metal	Brown	Chipping	1	9.5	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Office 320 (IDF-2)	W1	Plaster	White	None	0	33.8	Positive
1	3	Office 320 (IDF-2)	Window Sill	Wood	Brown	None	0	0.05	Negative
1	3	Office 320 (IDF-2)	Window Frame	Wood	Brown	None	0	0.07	Positive
1	3	Office 320 (IDF-2)	Baseboard	Wood	Brown	None	0	0.14	Positive
1	3	Office 320 (IDF-2)	Door	Wood	Brown	None	0	0.05	Positive
1	3	Office 320 (IDF-2)	Door Frame	Wood	Brown	None	0	0.1	Negative
1	3	Office 320 (IDF-2)	Floor	Wood	Unpainted	None	0	N/A	N/A
1	3	Office 322	W2	Plaster	Pink	None	0	26.2	Positive
1	3	Office 322	W3	Plaster	Pink	None	0	45.3	Positive
1	3	Office 322	W1	Plaster	Pink	None	0	36.9	Positive
1	3	Office 322	W4	Sheetrock	Pink	None	0	0.04	Positive
1	3	Office 322	Floor	Wood	Brown	None	0	N/A	N/A
1	3	Office 322	Door Frame	Wood	Brown	None	0	0.06	Negative
1	3	Office 322	Door	Wood	Brown	None	0	0.04	Positive
1	3	Office 322	Baseboard	Wood	Brown	None	0	0.07	Positive
1	3	Office 322	Window Frame	Wood	Brown	None	0	0.19	Positive
1	3	Office 322	Window Sill	Wood	Brown	None	0	0.03	Negative
1	3	Stairwell adjacent Classroom 300	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 300	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 300	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 300	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	2	Classroom 200	W1	Plaster	Yellow	Cracking	4	43.8	Positive
1	3	Stairwell adjacent Classroom 300	Riser	Concrete	Blue	None	0	8.7	Positive
1	3	Stairwell adjacent Classroom 300	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 300	Window Frame	Metal	Blue	None	0	9.6	Positive
1	3	Stairwell adjacent Classroom 300	Ceiling	Concrete	Blue	None	0	>10	Positive
1	3	Stairwell adjacent Classroom 305	W4	Metal	Blue	None	0	0.3	Negative
1	3	Stairwell adjacent Classroom 305	W2	Metal	Blue	None	0	0.4	Negative
1	3	Stairwell adjacent Classroom 305	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 305	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 305	Ceiling	Metal	Blue	None	0	>10	Positive
1	3	Stairwell adjacent Classroom 305	Riser	Metal	Blue	None	0	>10	Positive
1	3	Stairwell adjacent Classroom 305	Floor	Cement	Grey	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 305	Hand Rail	Metal	Brown	Chipping	2	0.2	Negative
1	3	Stairwell adjacent Classroom 319	W2	Metal	Blue	None	0	0	Negative
1	3	Stairwell adjacent Classroom 319	W4	Metal	Blue	None	0	0	Negative
1	3	Stairwell adjacent Classroom 319	Ceiling	Metal	Blue	None	0	>10	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	3	Stairwell adjacent Classroom 319	Riser	Wood	Blue	None	0	>10	Positive
1	3	Stairwell adjacent Classroom 319	W1	Brick	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 319	W3	Brick	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 319	Handrail	Metal	Brown	None	0	0.2	Negative
1	3	Stairwell adjacent Classroom 319	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	3	Stairwell adjacent Classroom 320	Door	Metal	Brown	None	0	0.1	Negative
1	3	Stairwell adjacent Classroom 320	Window Frame	Wood	Blue	None	0	3.8	Positive
1	3	Stairwell adjacent Classroom 320	Ceiling	Cement	Blue	None	0	9	Positive
1	3	Stairwell adjacent Classroom 320	Riser	Wood	Blue	None	0	>10	Positive
1	3	Stairwell adjacent Classroom 320	Door Frame	Metal	Brown	None	0	0.1	Negative
1	3	Stairwell adjacent Classroom 320	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell adjacent Classroom 320	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell adjacent Classroom 320	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell adjacent Classroom 320	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell adjacent Classroom 320	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200	W2	Plaster	Yellow	Cracking	4	45	Positive
1	2	Classroom 200	W3	Plaster	Yellow	Alligating	5	36.7	Positive
1	3	Women's Restroom on 3rd Floor	W2	CMU	Green	None	0	0	Negative
1	3	Women's Restroom on 3rd Floor	W4	Brick	Blue	Chipping	1	0.01	Negative
1	3	Women's Restroom on 3rd Floor	W4	CMU	Blue	Chipping	5	0.01	Negative
1	3	Women's Restroom on 3rd Floor	W3	CMU	Green	None	0	0.01	Negative
1	3	Women's Restroom on 3rd Floor	W3	Brick	Green	None	0	0.02	Negative
1	3	Women's Restroom on 3rd Floor	W1	CMU	Purple	None	0	0.02	Negative
1	3	Women's Restroom on 3rd Floor	W1	Brick	Green	None	0	0.04	Negative
1	3	Women's Restroom on 3rd Floor	W1	CMU	White	None	0	0.04	Negative
1	3	Women's Restroom on 3rd Floor	Pipe 2	Metal	Green	Flaking	10	0.1	Negative
1	2	Classroom 202	W1	Plaster	Yellow	Alligating	20	41.4	Positive
1	3	Women's Restroom on 3rd Floor	W3	Brick	Blue	None	0	0.07	Negative
1	3	Women's Restroom on 3rd Floor	Pipe 4	Metal	Blue	Chipping	1	0.6	Negative
1	3	Women's Restroom on 3rd Floor	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 202	W2	Plaster	Yellow	Cracking	20	34.5	Positive
1	3	Women's Restroom on 3rd Floor	Floor	Concrete	Brown	None	0	0.06	Negative
1	2	Classroom 202	W3	Plaster	Yellow	Chipping	10	1.4	Positive
1	2	Classroom 202	W4	Plaster	Yellow	Alligating	10	40.7	Positive
1	2	Office 206	Pipe 1	Metal	White	Chipping	3	19.5	Positive
1	3	Women's Restroom on 3rd Floor	Pipe 1	Metal	Green	None	0	0.06	Negative
1	3	Women's Restroom on 3rd Floor	Baseboard	Concrete	Brown	None	0	6.8	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	Dance Locker Restroom	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	2	Office 206	Radiator	Metal	Grey	Flaking	2	20.3	Positive
1	4	Dance Locker Restroom	W4	Plaster	Green	None	0	7.1	Positive
1	4	Dance Locker Restroom	W4	Plaster	Green	None	0	7.1	Positive
1	4	Dance Locker Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Dance Locker Restroom	W2	CMU	Green	None	0	0	Negative
1	4	Dance Locker Restroom	W3	CMU	Green	None	0	0	Negative
1	4	Dance Locker Restroom	Baseboard	Concrete	Brown	None	0	0	Negative
1	4	Dance Locker Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	4	Dance Locker Room	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	4	Dance Locker Room	Pipe	Metal	White	Chipping	5	0	Negative
1	4	Dance Locker Room	W1	Plaster	Tan	None	0	0	Negative
1	4	Dance Locker Room	W2	Plaster	Tan	None	0	0	Negative
1	4	Dance Locker Room	W3	Plaster	White	None	0	0.1	Negative
1	4	Dance Locker Room	W4	Plaster	White	None	0	0.1	Negative
1	4	Dance Locker Room	Duct	Metal	White	None	0	0	Negative
1	4	Dance Locker Room	Radiator Cover	Metal	White	None	0	0.1	Negative
1	4	Dance Office	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Dance Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	4	Dance Office	W1	Sheetrock	Blue	None	0	0	Negative
1	4	Dance Office	W2	Plaster	White	None	0	9.2	Positive
1	4	Dance Office	W2	Plaster	Blue	None	0	0.1	Negative
1	4	Dance Office	W3	Plaster	White	None	0	7.3	Positive
1	4	Dance Office	W3	Plaster	Blue	Efflorescence	15	0.4	Negative
1	4	Dance Office	W4	Sheetrock	Blue	None	0	0	Negative
1	4	Dance Office	Baseboard	Wood	Brown	None	0	0	Negative
1	4	Dance Office	Door Frame	Metal	Brown	None	0	0	Negative
1	4	Dance Office Closet	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Dance Office Closet	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	4	Dance Office Closet	W1	Sheetrock	Unpainted	None	0	N/A	N/A
1	4	Dance Office Closet	W2	Sheetrock	Unpainted	None	0	N/A	N/A
1	4	Dance Office Closet	W3	Sheetrock	Unpainted	None	0	N/A	N/A
1	4	Dance Office Closet	W4	Sheetrock	Unpainted	None	0	N/A	N/A
1	4	Dance Studio	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Dance Studio	Floor	Wood	Unpainted	None	0	N/A	N/A
1	4	Dance Studio	W1	Plaster	White	None	0	>10	Positive
1	4	Dance Studio	W2	Plaster	White	None	0	>10	Positive

		Dates: 1/17/23-1/27/23, 5/19/23			Lead-Safe Certification Assessment Report				
		Inspector Name and Certificate Number: Erik Swanson 006917			616 N. 15th Street, Philadelphia, PA 19130				
		Inspection Company: Viva			Franklin Learning Center				
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	Dance Studio	W3	Plaster	White	None	0	>10	Positive
1	4	Dance Studio	W4	Plaster	White	None	0	>10	Positive
1	4	Dance Studio	W1	Plaster	Green	None	0	>10	Positive
1	4	Dance Studio	W2	Plaster	Green	None	0	0.2	Negative
1	4	Dance Studio	W3	Plaster	Green	None	0	0.1	Negative
1	4	Dance Studio	W4	Plaster	Green	None	0	>10	Positive
1	4	Dance Studio	Window Frame 1	Wood	Brown	None	0	0.1	Negative
1	4	Dance Studio	Window Frame 2	Wood	Brown	None	0	0.2	Negative
1	4	Dance Studio	Window Frame 3	Wood	Brown	None	0	0.2	Negative
1	4	Dance Studio	Window Frame 4	Wood	Brown	None	0	0.3	Negative
1	4	Dance Studio	Window Frame 5	Wood	Brown	None	0	0.3	Negative
1	4	Dance Studio	Window Frame 6	Wood	Brown	None	0	0.2	Negative
1	4	Dance Studio	Window Frame 7	Wood	Brown	None	0	0.3	Negative
1	4	Dance Studio	Window Sill 1	Wood	Brown	None	0	1	Positive
1	4	Dance Studio	Window Sill 2	Wood	Brown	None	0	0.1	Negative
1	4	Dance Studio	Window Sill 3	Wood	Brown	None	0	0.2	Negative
1	4	Dance Studio	Window Sill 4	Wood	Brown	None	0	0.2	Negative
1	4	Dance Studio	Window Sill 5	Wood	Brown	None	0	0.1	Negative
1	4	Dance Studio	Window Sill 6	Wood	Brown	None	0	0.3	Negative
1	4	Dance Studio	Window Sill 7	Wood	Brown	None	0	0.1	Negative
1	4	Dance Studio	Baseboard	Wood	Brown	None	0	0.1	Negative
1	4	Dance Studio Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Dance Studio Closet	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Dance Studio Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Dance Studio Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Dance Studio Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Dance Studio Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Fire Tower adjacent to Closet 400	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	2	Office 206	W2	Plaster	Brown	Alligatoring	10	34.8	Positive
1	4	Fire Tower adjacent to Closet 400	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Fire Tower adjacent to Closet 400	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Fire Tower adjacent to Closet 400	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Fire Tower adjacent to Closet 400	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Fire Tower adjacent to Closet 400	Door Frame	Metal	Brown	None	0	0.4	Negative
1	4	Fire Tower adjacent to Closet 400	Door	Metal	Brown	None	0	0.4	Negative
1	4	Hallway from Closet 400 to Dance Studio	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	4	Hallway from Closet 400 to Dance Studio	W1	CMU	White	None	0	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	Hallway from Closet 400 to Dance Studio	W1	CMU	Blue	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	W1	Plaster	Tan	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	W2	Plaster	Tan	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	W3	Plaster	Tan	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	W4	Plaster	Tan	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	Ceiling	Concrete	White	None	0	0	Negative
1	4	Hallway from Closet 400 to Dance Studio	W4	Plaster	White	None	0	0.8	Positive
1	4	Hallway from Closet 400 to Dance Studio	Baseboard	Concrete	Brown	None	0	8.7	Positive
1	4	Hallway from Closet 400 to Dance Studio	W1	Plaster	White	None	0	>10	Positive
1	4	Hallway from Closet 400 to Dance Studio	W2	Plaster	White	None	0	>10	Positive
1	4	Hallway from Closet 400 to Dance Studio	W3	Plaster	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W1	CMU	White	None	0	0	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	W1	CMU	Purple	None	0	0	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	W4	CMU	Purple	None	0	0	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	Door Frame	Metal	Brown	None	0	0.2	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	Ceiling	Plaster	White	None	0	9.2	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W1	Plaster	Yellow	None	0	0.1	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	W3	Plaster	Yellow	None	0	0.2	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	Door	Metal	Brown	None	0	0.3	Negative
1	4	Hallway from Dance Studio to Dance Locker Room	W2	Plaster	Yellow	None	0	0.9	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	Baseboard	Concrete	Grey	None	0	7.3	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W1	Plaster	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W2	Plaster	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W3	Plaster	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	W4	CMU	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Hallway from Dance Studio to Dance Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Stairwell adjacent to Closet 400	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Stairwell adjacent to Closet 400	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Stairwell adjacent to Closet 400	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	4	Stairwell adjacent to Closet 400	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	2	Office 206	W3	Plaster	Brown	Alligatoring	10	34	Positive
1	4	Stairwell adjacent to Closet 400	Riser	Concrete	Blue	None	0	6.4	Positive
1	4	Stairwell adjacent to Closet 400	Window Frame	Metal	Blue	None	0	3.2	Positive
1	4	Stairwell adjacent to Closet 400	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	4	Stairwell adjacent to Closet 400	Ceiling	Concrete	Blue	None	0	>10	Positive
1	4	Stairwell adjacent to Dance Locker Room	W1	Metal	Blue	None	0	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	4	Stairwell adjacent to Dance Locker Room	W2	Metal	Blue	None	0	0	Negative
1	4	Stairwell adjacent to Dance Locker Room	W3	Metal	Blue	None	0	0	Negative
1	4	Stairwell adjacent to Dance Locker Room	W4	Metal	Blue	None	0	0	Negative
1	4	Stairwell adjacent to Dance Locker Room	Window Frame	Metal	Blue	None	0	>10	Positive
1	4	Stairwell adjacent to Dance Locker Room	Riser	Metal	Blue	None	0	>10	Positive
1	4	Stairwell adjacent to Dance Locker Room	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Stairwell adjacent to Dance Locker Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	4	Stairwell adjacent to Dance Locker Room	Hand Rail	Metal	Brown	None	0	>10	Positive
1	4	Storage Room 400	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Storage Room 400	Ceiling	Plaster	White	None	0	>10	Positive
1	4	Storage Room 400	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Storage Room 400	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Storage Room 400	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	Storage Room 400	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	W1	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	W2	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	W3	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	W4	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fifth Floor (above 4th Floor Gym)	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	W1	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	W2	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	W3	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	W4	Brick	Unpainted	None	0	N/A	N/A
1	AT	Attic-Fourth Floor	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	W1	Brick	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	W2	Brick	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	W3	Brick	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	W4	Brick	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	AT	Auditorium Attic	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Athletic Equipment Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Athletic Equipment Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Athletic Equipment Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Athletic Equipment Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report				
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130				
				Inspection Company: Viva		Franklin Learning Center				
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B	Athletic Equipment Storage	Ceiling	Plaster	White	None	0	>10	Positive	
1	B	Athletic Equipment Storage	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B	Auditorium	W1	Plaster	White	None	0	45.3	Positive	
1	B	Auditorium	W2	Plaster	White	None	0	42.1	Positive	
1	B	Auditorium	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1	B	Auditorium	W4	Plaster	White	None	0	43.7	Positive	
1	B	Auditorium	W1	Wood	Pink	None	0	29.9	Positive	
1	B	Auditorium	W2	Wood	Pink	None	0	36.2	Positive	
1	B	Auditorium	W4	Wood	Pink	None	0	30.8	Positive	
1	B	Auditorium	Column 1	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 2	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 3	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 4	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 5	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 6	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 7	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 8	Metal	White	None	0	0	Negative	
1	B	Auditorium	Column 9	Metal	White	None	0	0	Negative	
1	B	Auditorium	Door Frame 1	Wood	White	None	0	38.2	Positive	
1	B	Auditorium	Door Frame 2	Wood	White	None	0	33.1	Positive	
1	B	Auditorium	Door Frame 3	Wood	White	None	0	42.9	Positive	
1	B	Auditorium	Door Frame 4	Wood	White	None	0	35.3	Positive	
1	B	Auditorium	Door Frame 5	Wood	White	None	0	38.1	Positive	
1	B	Auditorium	Door Frame 6	Wood	White	None	0	31	Positive	
1	B	Auditorium	Door Frame 7	Wood	White	None	0	40.3	Positive	
1	B	Auditorium	Door Frame 8	Wood	White	None	0	34.8	Positive	
1	B	Auditorium	Door Frame 9	Wood	White	None	0	34.2	Positive	
1	B	Auditorium	Door Frame 10	Wood	White	None	0	37.4	Positive	
1	B	Auditorium	Door Frame 11	Wood	White	None	0	31.1	Positive	
1	B	Auditorium	Door Frame 12	Wood	White	None	0	40.9	Positive	
1	B	Auditorium	Door Frame 13	Wood	White	None	0	36.5	Positive	
1	B	Auditorium	Ceiling	Plaster	White	None	0	>10	Positive	
1	2	Office 206	W4	Plaster	Brown	Cracking	5	40.4	Positive	
1	2	Classroom 208	Ceiling	Plaster	White	Cracking	5	>10	Positive	
1	2	Classroom 208	W2	Plaster	White	Flaking	2	46.1	Positive	
1	2	Classroom 210	Ceiling	Plaster	White	Cracking	5	>10	Positive	
1	B	Backstage Right Closet	Window Sill 1	Wood	Brown	None	0	0.28	Negative	

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Backstage Right Closet	Door Frame	Wood	Brown	None	0	0.07	Negative
1	2	Classroom 210	W1	Plaster	White	Cracking	2	28.9	Positive
1	B	Backstage Right Closet	Ceiling	Plaster	White	None	0	>10	Positive
1	2	Classroom 210	W3	Plaster	White	Flaking	3	45.6	Positive
1	2	Classroom 217	Pipe 3	Metal	Yellow	Cracking	2	33.1	Positive
1	B	Backstage Right Closet	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Backstage Right Closet	Baseboard	Wood	Brown	None	0	0.17	Negative
1	B	Backstage Right Closet	Window Sill 2	No Access	N/A	N/A	N/A	N/A	N/A
1	B	Boy's Locker Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	B	Boy's Locker Restroom	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Restroom	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Restroom	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Restroom	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Boy's Locker Restroom	Floor	Laminated	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Restroom	Pipe	Metal	White	None	0	0.24	Negative
1	B	Boy's Locker Room	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Room	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Room	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Room	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Boy's Locker Room	Pipe 1	Metal	White	None	0	0.4	Negative
1	2	Classroom 217	Pipe 6	Metal	White	Flaking	2	1.2	Positive
1	2	Classroom 217	W1	Plaster	Yellow	Alligating	20	33.3	Positive
1	B	Boy's Locker Room	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Boy's Locker Room	Floor	Laminated	Unpainted	None	0	N/A	N/A
1	2	Classroom 215	W1	Plaster	Yellow	Alligating	10	46.5	Positive
1	B	Building Engineer's Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W2	Plaster	White	None	0	22.3	Positive
1	2	Classroom 215	W3	Plaster	Yellow	Cracking	5	41	Positive
1	2	Classroom 215	W4	Plaster	Yellow	Alligating	25	48	Positive
1	B	Building Engineer's Office	Door Frame	Wood	Brown	None	0	0.3	Negative
1	B	Building Engineer's Office	Baseboard	Concrete	Brown	None	0	10.8	Positive
1	B	Building Engineer's Office	Window Sill	Wood	Brown	None	0	0.3	Negative
1	2	Classroom 216	W2	Plaster	Yellow	Chipping	1	50.1	Positive
1	2	Classroom 216	W3	Plaster	Yellow	Chipping	5	55.4	Positive
1	B	Building Engineer's Office	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Building Engineer's Office	Door	Wood	Brown	None	0	0.07	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Building Engineer's Office	Window Frame	Wood	Brown	None	0	0.23	Negative
1	B	Cafeteria	Column	Plaster	White	None	0	33.2	Positive
1	B	Cafeteria	Column	Plaster	Blue	None	0	34.5	Positive
1	B	Cafeteria	W2	Brick	White	None	0	7.8	Positive
1	B	Cafeteria	W2	Brick	Blue	None	0	6.5	Positive
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.1	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.11	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.09	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.03	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.3	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.2	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.12	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.16	Negative
1	B	Cafeteria	Window Frame	Wood	Brown	N/A	N/A	0.19	Negative
1	B	Cafeteria	Pipe	Metal	White	N/A	N/A	0	Negative
1	B	Cafeteria	Pipe	Metal	Blue	N/A	N/A	0.05	Negative
1	B	Cafeteria	Pipe	Metal	White	None	0	27.4	Positive
1	B	Cafeteria	Pipe	Metal	Blue	None	0	30.8	Positive
1	B	Cafeteria	Pipe	Metal	White	None	0	30.4	Positive
1	B	Cafeteria	Pipe	Metal	Blue	None	0	20.7	Positive
1	B	Cafeteria	Pipe	Metal	White	N/A	N/A	0.09	Negative
1	B	Cafeteria	Pipe	Metal	Blue	N/A	N/A	0.12	Negative
1	B	Cafeteria	W3	Sheetrock	White	N/A	N/A	0	Negative
1	2	Classroom 216	W4	Plaster	Yellow	Alligatoring	5	51.5	Positive
1	B	Cafeteria	W4	Brick	White	None	0	10	Positive
1	B	Cafeteria	W4	Brick	Blue	None	0	12.4	Positive
1	B	Cafeteria	Door Frame	Wood	Brown	None	0	0.19	Negative
1	B	Cafeteria	Door Frame	Wood	Brown	None	0	0.2	Negative
1	B	Cafeteria	Pipe	Metal	White	None	0	1.2	Positive
1	B	Cafeteria	Pipe	Metal	Blue	None	0	1.1	Positive
1	B	Cafeteria	Pipe	Metal	White	None	0	3.2	Positive
1	B	Cafeteria	Column	Concrete	White	None	0	35.2	Positive
1	B	Cafeteria	Column	Concrete	White	None	0	30.2	Positive
1	B	Cafeteria	Column	Concrete	White	None	0	35.2	Positive
1	B	Cafeteria	Column	Concrete	White	None	0	34.2	Positive
1	B	Cafeteria	Door Frame	Metal	Brown	None	0	0.05	Negative
1	B	Cafeteria	Door	Metal	Brown	N/A	N/A	0.3	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Cafeteria	Pipe	Metal	White	None	0	2.3	Positive
1	B	Cafeteria	Pipe	Metal	Blue	N/A	N/A	0	Negative
1	B	Cafeteria	W1	Brick	White	None	0	23.1	Positive
1	B	Cafeteria	W1	Sheetrock	White	N/A	N/A	0	Negative
1	2	Office 219	Radiator	Metal	Grey	Chipping	1	9.7	Positive
1	2	Office 219	W2	Plaster	White	Cracking	4	1.1	Positive
1	B	Cafeteria	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC 221	Radiator 1	Metal	Grey	Flaking	10	24.3	Positive
1	2	IMC 221	Radiator 2	Metal	Grey	Flaking	2	10.1	Positive
1	2	IMC 221	W4	Plaster	White	Cracking	10	37.4	Positive
1	2	IMC 221	W3	Plaster	Blue	Chipping	5	31.4	Positive
1	2	Classroom 201	Pipe	Metal	Yellow	Flaking	10	15.7	Positive
1	2	Classroom 201	W1	Plaster	Yellow	Cracking	5	44.2	Positive
1	2	Classroom 201	W3	Plaster	Yellow	Cracking	10	22.2	Positive
1	2	Classroom 201	W4	Plaster	Yellow	Cracking	2	43.7	Positive
1	B	Cafeteria	W3	Sheetrock	Blue	None	0	0	Negative
1	B	Cafeteria	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205	Radiator 1	Metal	Grey	Flaking	5	10.1	Positive
1	B	Cafeteria Storage	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Cafeteria Storage	W1	Sheetrock	White	None	0	0	Negative
1	B	Cafeteria Storage	W2	Sheetrock	White	None	0	0	Negative
1	B	Cafeteria Storage	W3	Brick	Blue	None	0	0	Negative
1	B	Cafeteria Storage	W3	Brick	White	None	0	0	Negative
1	B	Cafeteria Storage	W4	Brick	Blue	None	0	0	Negative
1	B	Cafeteria Storage	W4	Brick	White	None	0	0	Negative
1	B	Electrical Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Electrical Room	W3	Brick	White	N/A	N/A	0	Negative
1	B	Electrical Room	Supprt Beam	Metal	White	None	0	3.5	Positive
1	B	Electrical Room	Column	Concrete	White	None	0	0	Negative
1	B	Electrical Room	Ceiling	Concrete	White	Chipping	100	No Access	No Access
1	2	Classroom 205	Radiator 2	Metal	Grey	Chipping	5	7.9	Positive
1	2	Classroom 205	Radiator 3	Metal	Grey	Flaking	5	6.1	Positive
1	2	Classroom 205	W1	Plaster	White	Cracking	2	36.2	Positive
1	B	Electrical Room	W1	Brick	White	Chipping	100	0	Negative
1	B	Electrical Room	W2	Brick	White	Flaking	200	0	Negative
1	B	Electrical Room	W4	Brick	White	Flaking	100	0	Negative
1	B	Electrical Service Room	Floor	Concrete	Unpainted	None	0	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Electrical Service Room	W2	Brick	White	N/A	N/A	0.04	Negative
1	B	Electrical Service Room	Ceiling	Plaster	White	Efflorescence	150	0.01	Negative
1	B	Electrical Service Room	Door	Wood	Grey	Chipping	10	0.1	Negative
1	B	Electrical Service Room	Door Frame	Wood	Grey	Flaking	10	0.4	Negative
1	B	Electrical Service Room	W1	Brick	White	Efflorescence	25	0.02	Negative
1	B	Electrical Service Room	W3	CMU	White	Alligatoring	50	0	Negative
1	B	Electrical Service Room	W4	CMU	White	Flaking	50	0.3	Negative
1	B	Fan Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Fan Room	Door	Wood	Grey	Chipping	2	0.02	Negative
1	B	Fan Room	Ceiling	Concrete	White	None	0	>10	Positive
1	B	Fan Room	Door Frame	Wood	Grey	Flaking	1	0.01	Negative
1	2	Classroom 207	W1	Plaster	Yellow	Flaking	1	29.3	Positive
1	B	Fan Room	Hand Rail	Metal	White	Chipping	10	0.24	Negative
1	2	Classroom 207	W2	Plaster	Yellow	Cracking	1	36.9	Positive
1	B	Fan Room	W1	Brick	White	Flaking	20	0	Negative
1	B	Fan Room	W2	Brick	White	Chipping	100	0.01	Negative
1	B	Fan Room	W3	Brick	White	Chipping	10	0.01	Negative
1	B	Fan Room	W4	CMU	White	Flaking	100	0	Negative
1	B	Fan Room- Left Side Fan Unit	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Fan Room- Left Side Fan Unit	Column	Terracotta	White	None	0	0	Negative
1	B	Fan Room- Left Side Fan Unit	Ceiling	Concrete	White	None	0	>10	Positive
1	B	Fan Room- Left Side Fan Unit	Door Frame	Wood	White	Flaking	1	0.13	Negative
1	2	Closet 213	W4	Plaster	Yellow	Cracking	2	28.3	Positive
1	B	Fan Room- Left Side Fan Unit	W1	Brick	White	Chipping	50	0.01	Negative
1	B	Fan Room- Left Side Fan Unit	W2	Brick	White	Flaking	100	0.02	Negative
1	B	Fan Room- Left Side Fan Unit	W3	CMU	White	Flaking	50	0	Negative
1	B	Fan Room- Left Side Fan Unit	W4	CMU	White	Efflorescence	15	0	Negative
1	B	Fan Room- Right Side Fan Unit	Column	Terracotta	White	Chipping	15	0.02	Negative
1	B	Fan Room- Right Side Fan Unit	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Fan Room- Right Side Fan Unit	Ceiling	Concrete	White	None	0	>10	Positive
1	B	Fan Room- Right Side Fan Unit	Door Frame	Wood	Grey	Flaking	2	0.11	Negative
1	2	216/217 Hallway	W4	Plaster	Yellow	Cracking	2	32.1	Positive
1	B	Fan Room- Right Side Fan Unit	W1	Brick	White	Flaking	100	0.04	Negative
1	B	Fan Room- Right Side Fan Unit	W2	Brick	White	Flaking	100	0	Negative
1	B	Fan Room- Right Side Fan Unit	W3	CMU	White	Flaking	100	0	Negative
1	B	Fan Room- Right Side Fan Unit	W4	CMU	White	Flaking	200	0.02	Negative
1	2	Classroom 220	W2	Plaster	Yellow	Cracking	15	32.1	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Fire Tower adjacent to Athletic Equipment Storage 016	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Fire Tower adjacent to Athletic Equipment Storage 016	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Athletic Equipment Storage 016	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Athletic Equipment Storage 016	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Athletic Equipment Storage 016	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	2	Classroom 220	W3	Plaster	Yellow	Cracking	10	47.5	Positive
1	B	Fire Tower adjacent to Athletic Equipment Storage Room 016	Door 1	Metal	Brown	Chipping	3	0.5	Negative
1	B	Fire Tower adjacent to Athletic Equipment Storage Room 016	Door Frame 1	Metal	Brown	Chipping	2	0.3	Negative
1	B	Fire Tower adjacent to Athletic Equipment Storage Room 016	Door Frame 1	Metal	Blue	Chipping	1	0.2	Negative
1	B	Fire Tower adjacent to Staff Locker Room 014	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Staff Locker Room 014	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Staff Locker Room 014	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Staff Locker Room 014	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Fire Tower adjacent to Staff Locker Room 014	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	2	Hallway from Classrooms 200 to 218	Radiator 1	Metal	Grey	Chipping	2	7.9	Positive
1	B	Foyer	Floor	Marble	Unpainted	None	0	N/A	N/A
1	2	Hallway from Classrooms 200 to 218	W2	Plaster	White	Flaking	10	>10	Positive
1	2	Hallway from Classrooms 207 to 212	Radiator 1	Metal	Grey	Chipping	2	8.9	Positive
1	2	Hallway from Classrooms 207 to 212	W2	Plaster	White	Flaking	10	9.8	Positive
1	2	Hallway from Classrooms 218 to 221	Radiator 1	Metal	Grey	Chipping	2	9.1	Positive
1	2	Hallway from Classrooms 218 to 221	Radiator 2	Metal	Grey	Chipping	2	9.3	Positive
1	B	Foyer	W1	Plaster	White	None	0	19.1	Positive
1	B	Foyer	W2	Plaster	White	None	0	42.5	Positive
1	2	Hallway from Classrooms 218 to 221	W2	Plaster	White	Efflorescence	5	>10	Positive
1	B	Foyer	W4	Plaster	White	None	0	47.5	Positive
1	2	Hallway from Classrooms 201 to 204/204	Radiator 3	Metal	Grey	Chipping	2	7.4	Positive
1	2	Hallway from Classrooms 201 to 204/204	Radiator 1	Metal	Grey	Chipping	2	7.8	Positive
1	2	Hallway from Classrooms 201 to 204/204	Radiator 2	Metal	Grey	Chipping	2	8.6	Positive
1	2	Stairwell adjacent Classroom 200	Rail	Metal	Brown	Chipping	2	8.2	Positive
1	2	Fire Tower adjacent Classroom 200	Ceiling	Concrete	White	Chipping	50	>10	Positive
1	B	Foyer	Ceiling	Plaster	White	None	0	>10	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Girl's Locker Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Locker Room	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Girl's Locker Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Locker Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Locker Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Girl's Locker Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Gymnasium	W1	Brick	Blue	None	0	0	Negative
1	B	Gymnasium	W2	Brick	Blue	None	0	0	Negative
1	B	Gymnasium	W3	Brick	Blue	None	0	0	Negative
1	B	Gymnasium	W4	Brick	White	None	0	0	Negative
1	B	Gymnasium	W1	Brick	White	None	0	6.3	Positive
1	B	Gymnasium	W2	Brick	White	None	0	6.7	Positive
1	B	Gymnasium	W3	Brick	White	None	0	14.1	Positive
1	B	Gymnasium	Door 1	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Door Frame 1	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Door 2	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Door Frame 2	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Door 3	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Door Frame 3	Metal	Blue	None	0	0	Negative
1	B	Gymnasium	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Gymnasium	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Hallway adjacent to Gymnasium	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Hallway adjacent to Gymnasium	W1	Plaster	Yellow	None	0	0.03	Negative
1	1	Classroom 100	Pipe 2	Metal	White	Flaking	4	48.5	Positive
1	B	Hallway adjacent to Gymnasium	W2	Plaster	Yellow	None	0	0.16	Negative
1	1	Classroom 100	Pipe 3	Metal	Green	Flaking	2	2.5	Positive
1	B	Hallway adjacent to Gymnasium	W3	CMU	White	None	0	0.03	Negative
1	B	Hallway adjacent to Gymnasium	W3	CMU	Yellow	None	0	0.03	Negative
1	1	Classroom 100	W2	Plaster	Green	Flaking	2	33.1	Positive
1	B	Hallway adjacent to Gymnasium	W3	Plaster	Yellow	None	0	0.03	Negative
1	B	Hallway adjacent to Gymnasium	W4	CMU	White	None	0	0.1	Negative
1	B	Hallway adjacent to Gymnasium	W4	CMU	Yellow	None	0	0.03	Negative
1	B	Hallway adjacent to Gymnasium	Baseboard	Concrete	Brown	None	0	12.9	Positive
1	1	Classroom 100	W3	Plaster	Green	Chipping	3	39.6	Positive
1	B	Hallway adjacent to Gymnasium	Handrail 2	Metal	Brown	Chipping	2	0.17	Negative
1	1	Classroom 100	Radiator	Metal	Grey	Chipping	1	7	Positive
1	B	Hallway adjacent to Gymnasium	Handrail 4	Metal	Brown	Chipping	2	0.09	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Classroom 101	Pipe	Metal	White	Flaking	10	19.6	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W1	CMU	White	None	0	0	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W1	CMU	Yellow	None	0	0	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W2	Plaster	Yellow	None	0	3.2	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W2	Plaster	White	None	0	37	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W3	Plaster	Yellow	None	0	0.06	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W3	Plaster	White	None	0	0.03	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W4	Plaster	White	None	0	23.8	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Window Sill 1	Wood	Brown	None	0	0.4	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Window Sill 1	Wood	Brown	None	0	1	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Window Frame 1	Wood	Brown	None	0	2.2	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Window Frame 2	Wood	Brown	None	0	2.1	Positive
1	1	Classroom 101	W3	Plaster	White	Cracking	5	45.9	Positive
1	1	Multipurpose Room	Ceiling	Plaster	White	Cracking	5	>10	Positive
1	1	Weight Room 104	W3	Plaster	White	Chipping	2	41.3	Positive
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	W4	Plaster	Yellow	Chipping	4	0.08	Negative
1	B	Hallway from Kitchen Office to Athletic Equipment Storage 016	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 105	Pipe	Metal	Blue	Flaking	6	28.8	Positive
1	1	Classroom 105	Pipe 2	Metal	Blue	Flaking	6	31.8	Positive
1	1	Classroom 105	W1	Plaster	Blue	Chipping	5	54.5	Positive
1	B	Hallway from Office B05 to Staff Locker Room	W2	Plaster	White	None	0	35.2	Positive
1	B	Hallway from Office B05 to Staff Locker Room	W3	CMU	White	N/A	N/A	0.04	Negative
1	B	Hallway from Office B05 to Staff Locker Room	W4	Plaster	White	None	0	40.5	Positive
1	B	Hallway from Office B05 to Staff Locker Room	W1	CMU	White	N/A	N/A	0.06	Negative
1	1	Classroom 105	W3	Plaster	Blue	Cracking	1	47.4	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Hallway from Office B05 to Staff Locker Room	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Hallway from Old Boiler Room to HVAC Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Hallway from Old Boiler Room to HVAC Room	W1	CMU	White	N/A	N/A	0.03	Negative
1	B	Hallway from Old Boiler Room to HVAC Room	W1	CMU	Yellow	N/A	N/A	0.02	Negative
1	1	Classroom 105	W4	Plaster	Blue	Flaking	2	48.9	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	W3	Plaster	White	None	0	0.21	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	W4	Plaster	White	N/A	N/A	0.07	Negative
1	B	Hallway from Old Boiler Room to HVAC Room	Baseboard	Concrete	Brown	None	0	8.3	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Door	Metal	Brown	N/A	N/A	0.09	Negative
1	1	Nurse's Office	Radiator	Metal	Grey	Chipping	4	9.3	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Pipe 1	Metal	Brown	None	0	22.3	Positive
1	B	Hallway from Old Boiler Room to HVAC Room	Pipe 2	Metal	White	None	0	12.1	Positive
1	1	Nurse's Office	W1	Plaster	White	Flaking	2	31.4	Positive
1	1	Nurse's Office	W2	Plaster	White	Flaking	8	32.4	Positive
1	1	Nurse's Office	W3	Plaster	White	Cracking	2	32.9	Positive
1	B	HVAC Room/Gym Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	HVAC Room/Gym Storage	Door 1	Metal	Brown	Chipping	1	0	Negative
1	B	HVAC Room/Gym Storage	Door 2	Metal	Brown	Chipping	1	0.4	Negative
1	B	HVAC Room/Gym Storage	Door Frame 1	Metal	Brown	Chipping	1	0.01	Negative
1	B	HVAC Room/Gym Storage	Door Frame 2	Metal	Brown	Chipping	1	0.16	Negative
1	1	Nurse's Reception Area	Door Frame 2	Wood	Brown	Flaking	3	29.4	Positive
1	1	Nurse's Reception Area	Radiator	Metal	Grey	Chipping	2	31.8	Positive
1	1	Classroom 120	Ceiling	Plaster	White	Cracking	20	>10	Positive
1	1	Classroom 120	Pipe 2	Metal	White	Chipping	1	13.5	Positive
1	B	HVAC Room/Gym Storage	Ceiling	Plaster	White	None	0	>10	Positive
1	1	Classroom 120	Pipe 2	Metal	Tan	Chipping	1	2.1	Positive
1	B	Kitchen	Floor	Concrete	Grey	Chipping	300	0.15	Negative
1	B	Kitchen	Ceiling	Concrete	White	None	0	0	Negative
1	B	Kitchen	W2	Brick	White	N/A	N/A	0.04	Negative
1	B	Kitchen	W3	Brick	White	N/A	N/A	0.01	Negative
1	B	Kitchen	Vent	Metal	Grey	None	0	0.23	Negative
1	B	Kitchen	Window Frame	Wood	White	N/A	N/A	0.16	Negative
1	B	Kitchen	W1	Brick	White	N/A	N/A	0.05	Negative
1	B	Kitchen	W4	Brick	White	Cracking	2	0	Negative
1	1	Staff Lounge	Ceiling	Plaster	White	Cracking	5	>10	Positive
1	B	Kitchen Office	Floor	Concrete	Grey	Chipping	50	0.01	Negative
1	B	Kitchen Office	W1	Brick	Yellow	None	0	15.6	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Kitchen Office	W1	Brick	White	None	0	0	Negative
1	B	Kitchen Office	W2	Brick	White	None	0	0	Negative
1	B	Kitchen Office	W3	Brick	Yellow	None	0	5.3	Positive
1	B	Kitchen Office	W3	Brick	White	None	0	0	Negative
1	B	Kitchen Office	W4	Brick	White	None	0	0	Negative
1	B	Kitchen Office	Ceiling	Plaster	Unpainted	N/A	N/A	N/A	N/A
1	B	Kitchen Office	Radiator Cover	Metal	White	None	0	0	Negative
1	B	Kitchen Office	Door Frame	Wood	Brown	None	0	0.01	Negative
1	1	Music Classroom 125	Radiator	Metal	Grey	Flaking	2	4.3	Positive
1	1	Vice- Principal's Office	Radiator	Metal	Grey	Chipping	2	16.9	Positive
1	1	Vice- Principal's Office	W4	Plaster	Pink	Flaking	1	32.1	Positive
1	B	Men's Restroom	W1	Sheetrock	White	None	0	0	Negative
1	B	Men's Restroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	Men's Restroom	W2	Plaster	White	None	0	>10	Positive
1	B	Men's Restroom	W2	Plaster	Yellow	None	0	0.3	Negative
1	B	Men's Restroom	W3	Plaster	White	None	0	>10	Positive
1	B	Men's Restroom	W3	Plaster	Yellow	None	0	0.3	Negative
1	B	Men's Restroom	W3	Sheetrock	White	None	0	0	Negative
1	B	Men's Restroom	W3	Sheetrock	Yellow	None	0	0	Negative
1	B	Men's Restroom	W4	Plaster	White	None	0	>10	Positive
1	B	Men's Restroom	W4	Plaster	Yellow	None	0	0.3	Negative
1	B	Men's Restroom	Baseboard	Wood	Brown	None	0	0.3	Negative
1	B	Men's Restroom	Door Frame	Wood	Brown	None	0	0.2	Negative
1	1	Main Office	W1	Plaster	Blue	Flaking	2	34.2	Positive
1	1	Main Office	W3	Plaster	Blue	Flaking	2	37.6	Positive
1	1	Main Office	W4	Plaster	Blue	Chipping	2	38.8	Positive
1	1	Principal's Office	W2	Plaster	Yellow	Chipping	1	>10	Positive
1	1	Classroom 133	Pipe 2	Metal	White	Flaking	2	1.3	Positive
1	1	Classroom 133	W3	Plaster	Tan	Peeling	1	40	Positive
1	1	Classroom 129	W1	Plaster	Green	Flaking	1	36.7	Positive
1	1	Classroom 129	W2	Plaster	Green	Chipping	1	32.3	Positive
1	B	Old Boiler Room	Pipe	Metal	White	Flaking	5	0.17	Negative
1	1	Classroom 129	W4	Plaster	Green	Flaking	6	32.5	Positive
1	B	Old Boiler Room	W1	Brick	White	Cracking	100	0	Negative
1	B	Old Boiler Room	W2	Brick	White	Flaking	50	0	Negative
1	B	Old Boiler Room	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Old Boiler Room	W3	Brick	White	Chipping	200	0	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Custodial Closet across from Multipurpose Room 102	W1	Plaster	White	Cracking	4	>10	Positive
1	B	Old Boiler Room	W4	Brick	White	Flaking	200	0.01	Negative
1	B	Old Boiler Room	Tank	Metal	Grey	None	0	0.06	Negative
1	B	Old Boiler Room	Supprt Beam	Metal	Grey	None	0	3.3	Positive
1	B	Old Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Custodial Closet across from Multipurpose Room 102	W2	Plaster	White	Cracking	4	>10	Positive
1	B	School Police Office	Ceiling	Plaster	White	None	0	>10	Positive
1	B	School Police Office	W1	Plaster	Yellow	None	0	33.1	Positive
1	B	School Police Office	W2	Plaster	Yellow	None	0	28.7	Positive
1	B	School Police Office	W3	Plaster	Yellow	None	0	24.6	Positive
1	B	School Police Office	Radiator	Metal	Grey	None	0	3.4	Positive
1	B	School Police Office	Window sill 1	Wood	Brown	None	0	4.6	Positive
1	B	School Police Office	W4	Plaster	Yellow	None	0	27.2	Positive
1	B	School Police Office	Baseboard	Concrete	Brown	None	0	0.04	Negative
1	B	School Police Office	Window sill 2	Wood	Brown	None	0	2.5	Positive
1	B	School Police Office	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	School Police Office	W1	Plaster	Yellow	None	0	22.9	Positive
1	B	School Police Office Closet	Ceiling	Plaster	White	None	0	>10	Positive
1	B	School Police Office Closet	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	School Police Office Closet	W1	Plaster	Purple	None	0	0	Negative
1	B	School Police Office Closet	W1	Sheetrock	Purple	None	0	0	Negative
1	B	School Police Office Closet	W2	Plaster	Purple	None	0	0	Negative
1	B	School Police Office Closet	W3	Plaster	Purple	None	0	0	Negative
1	B	School Police Office Closet	W4	Sheetrock	Purple	None	0	0	Negative
1	B	School Police Office Closet	Pipe	Metal	White	None	0	0.4	Negative
1	B	School Police Office Closet	Baseboard	Concrete	White	None	0	0.4	Negative
1	B	School Police Office Security Equipment/Server Room	Ceiling	Plaster	White	None	0	>10	Positive
1	B	School Police Office Security Equipment/Server Room	Door Frame (W1)	Wood	Grey	No Access	No Access	2.2	Positive
1	B	School Police Office Security Equipment/Server Room	Door Stop (W1)	Wood	Green	No Access	No Access	3.8	Positive
1	B	School Police Office Security Equipment/Server Room	Door Jamb (W1)	Wood	Green	No Access	No Access	4.2	Positive
1	B	School Police Office Security Equipment/Server Room	Baseboard (W1)	Concrete	Grey	None	0	0.17	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	School Police Office Security Equipment/Server Room	W2	Plaster	Green	No Access	No Access	1.6	Positive
1	B	School Police Office Security Equipment/Server Room	Riser (W2)	Metal	Green	No Access	No Access	2.2	Positive
1	B	School Police Office Security Equipment/Server Room	Window sill (W2)	Wood	Green	No Access	No Access	3.5	Positive
1	B	School Police Office Security Equipment/Server Room	Chair/Picture Rail (W2)	Wood	Grey	No Access	No Access	4.8	Positive
1	B	School Police Office Security Equipment/Server Room	Baseboard (W2)	Concrete	Grey	None	0	0.14	Negative
1	B	School Police Office Security Equipment/Server Room	W3	Plaster	Green	No Access	No Access	28.4	Positive
1	B	School Police Office Security Equipment/Server Room	Riser (W3)	Metal	Green	None	0	0.4	Negative
1	B	School Police Office Security Equipment/Server Room	Drain Pipe (W3)	Metal	Green	None	0	0.6	Negative
1	B	School Police Office Security Equipment/Server Room	Chair/Picture Rail (W3)	Wood	Grey	No Access	No Access	6.2	Positive
1	B	School Police Office Security Equipment/Server Room	Baseboard (W3)	Concrete	Grey	None	0	0.16	Negative
1	B	School Police Office Security Equipment/Server Room	W4	Plaster	Green	No Access	No Access	20.7	Positive
1	B	School Police Office Security Equipment/Server Room	Chair/Picture Rail (W4)	Wood	Grey	No Access	No Access	4.3	Positive
1	B	School Police Office Security Equipment/Server Room	Baseboard (W4)	Concrete	Grey	None	0	0.18	Negative
1	B	School Police Office Security Equipment/Server Room	Ductwork (Ceiling)	Metal	Green	No Access	No Access	9.5	Positive
1	B	School Police Office Security Equipment/Server Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	School Police Office Security Equipment/Server Room	W1	Plaster	Green	No Access	No Access	29.9	Positive
1	B	Staff Locker Room	Pipe	Metal	Grey	None	0	0.3	Negative
1	1	Custodial Closet across from Multipurpose Room 102	W3	Plaster	White	Cracking	4	>10	Positive
1	1	Custodial Closet across from Multipurpose Room 102	W4	Plaster	White	Cracking	4	>10	Positive
1	B	Staff Locker Room	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom	W4	Brick	Blue	Efflorescence	4	3.7	Positive
1	1	Boy's Restroom	W1	Plaster	White	Chipping	1	37.6	Positive

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	1	Boy's Restroom	Pipe 1	Metal	Blue	Chipping	1	5.7	Positive
1	1	Boy's Restroom	Radiator	Metal	Grey	Chipping	3	2.5	Positive
1	B	Staff Locker Room	Window Sill 1	Wood	Brown	None	0	0.09	Negative
1	B	Staff Locker Room	Window Frame 1	Wood	Brown	None	0	0.14	Negative
1	B	Staff Locker Room	Window Sill 2	Wood	Brown	None	0	0.18	Negative
1	B	Staff Locker Room	Window Frame 2	Wood	Brown	None	0	0.09	Negative
1	B	Staff Locker Room	Baseboard	Concrete	Brown	None	0	8.6	Positive
1	B	Staff Locker Room	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Staff Restroom	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	Stage	W2	Plaster	Black	None	0	>10	Positive
1	B	Stage	W3	Plaster	Black	None	0	>10	Positive
1	B	Stage	W4	Plaster	Black	None	0	>10	Positive
1	B	Stage	Door Frame 1	Wood	Black	None	0	>10	Positive
1	B	Stage	Door Frame 2	Wood	Black	None	0	>10	Positive
1	B	Stage	Ceiling	Plaster	White	None	0	>10	Positive
1	B	Stage	Floor	Wood	Unpainted	None	0	N/A	N/A
1	B	Stairwell adjacent to Athletic Equipment Storage 016	Hand Rail	Metal	Brown	Chipping	1	0.1	Negative
1	B	Stairwell adjacent to Athletic Equipment Storage 016	Ceiling	Concrete	Blue	None	0	2.3	Positive
1	B	Stairwell adjacent to Athletic Equipment Storage 016	Riser	Wood	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Athletic Equipment Storage 016	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Athletic Equipment Storage 016	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Athletic Equipment Storage 016	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Athletic Equipment Storage 016	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Athletic Equipment Storage 016	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Boy's Locker Room 005	Hand Rail	Metal	Blue	None	0	0.1	Negative
1	B	Stairwell adjacent to Boy's Locker Room 005	W2	Brick	White	None	0	0.4	Negative

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Stairwell adjacent to Boy's Locker Room 005	W1	Brick	White	None	0	0.5	Negative
1	B	Stairwell adjacent to Boy's Locker Room 005	W4	Brick	White	None	0	0.7	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	W3	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Ceiling	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Floor	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Stair Tread	Metal	Blue	None	0	5.4	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Stair Riser	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Stringer	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Boy's Locker Room 005	Newell Post	Metal	Blue	None	0	>10	Positive
1	1	Weight Room 104 Boys Bathroom	W2	Plaster	White	Cracking	10	39.1	Positive
1	B	Stairwell adjacent to School Police Office B05	Door	Metal	Blue	Chipping	2	0	Negative
1	B	Stairwell adjacent to School Police Office B05	W2	Metal	Blue	None	0	0.3	Negative
1	B	Stairwell adjacent to School Police Office B05	W4	Metal	Blue	None	0	0.4	Negative
1	B	Stairwell adjacent to School Police Office B05	Riser	Concrete	Blue	None	0	9.9	Positive
1	B	Stairwell adjacent to School Police Office B05	Door Frame	Metal	Blue	Chipping	2	0	Negative
1	B	Stairwell adjacent to School Police Office B05	Ceiling	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to School Police Office B05	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to Staff Locker Room 014	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	B	Stairwell adjacent to Staff Locker Room 014	Ceiling	Concrete	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to Staff Locker Room 014	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Stairwell adjacent to Staff Locker Room 014	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Stairwell adjacent to Staff Locker Room 014	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	B	Stairwell adjacent to Staff Locker Room 014	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A
1	1	Principal's Restroom	Pipe 2	Metal	Green	Flaking	10	1.6	Positive
1	B	Stairwell adjacent to Staff Locker Room 014	Riser	Concrete	Blue	None	0	5.8	Positive
1	B	Stairwell adjacent to Staff Locker Room 014	Window Frame	Metal	Blue	None	0	>10	Positive
1	B	Stairwell adjacent to the left of Foyer	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the left of Foyer	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the left of Foyer	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the left of Foyer	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the left of Foyer	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the left of Foyer	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the right of Foyer	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the right of Foyer	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the right of Foyer	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the right of Foyer	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	B	Stairwell adjacent to the right of Foyer	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 1/17/23-1/27/23, 5/19/23		Lead-Safe Certification Assessment Report			
				Inspector Name and Certificate Number: Erik Swanson 006917		616 N. 15th Street, Philadelphia, PA 19130			
				Inspection Company: Viva		Franklin Learning Center			
Element	Floor	On-Site Room Name	Component	Substrate Material	PaintColor	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B	Stairwell adjacent to the right of Foyer	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	Principal's Restroom	W2	Plaster	Green	Cracking	15	3.4	Positive
1	B	Women's Restroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Closet adjacent Nurse's Office	W1	Plaster	Green	Flaking	10	12.6	Positive
1	1	Nurse's Restroom	Door Frame	Wood	Brown	Flaking	2	28.7	Positive
1	1	Nurse's Restroom	W4	Plaster	White	Cracking	3	30.7	Positive
1	1	Girl's Restroom	Ceiling	Plaster	White	Flaking	100	>10	Positive
1	1	Connector Hall to Balcony from Hallway H11	W1	Plaster	White	Cracking	2	0.8	Positive
1	1	Hallway from Classrooms 131 to 133	W2	Plaster	White	Flaking	2	>10	Positive
1	1	Hallway from Classrooms 131 to 133	W2	Plaster	Multi	Chipping	10	>10	Positive
1	1	Stairwell adjacent to Classroom 100	Rail	Metal	Brown	Chipping	2	6.4	Positive
1	1	Fire Tower adjacent to Classroom 100	Ceiling	Concrete	White	Chipping	50	>10	Positive
1	CS	Crawlspace (concrete tunnel in fan room)	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace (concrete tunnel in fan room)	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace (concrete tunnel in fan room)	W1	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace (concrete tunnel in fan room)	W2	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace (concrete tunnel in fan room)	W3	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace (concrete tunnel in fan room)	W4	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	W1	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	W2	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	W3	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- (Auditorium Plenum)	W4	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	Ceiling	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	Floor	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	W1	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	W2	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	W3	Concrete	Unpainted	None	0	N/A	N/A
1	CS	Crawlspace- Elev Foyer 401-404	W4	Concrete	Unpainted	None	0	N/A	N/A