

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Locker Room (Visitor)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room (Visitor)	W1	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Visitor)	W2	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Visitor)	W3	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Visitor)	W4	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Visitor)	Ceiling	Concrete	White	Flaking	100	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	W1	CMU	Blue	None	0	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	W2	CMU	Blue	None	0	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	W3	CMU	Blue	None	0	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	W4	CMU	Blue	None	0	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	Ceiling	Concrete	White	Flaking	100	0	Negative
1	1	Closet in Boy's Locker Room (Visitor)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Showers in Boy's Locker Room (Visitor)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Showers in Boy's Locker Room (Visitor)	W1	CMU	Blue	None	0	0	Negative
1	1	Showers in Boy's Locker Room (Visitor)	W2	CMU	Blue	None	0	0	Negative
1	1	Showers in Boy's Locker Room (Visitor)	W3	CMU	Blue	None	0	0	Negative
1	1	Showers in Boy's Locker Room (Visitor)	W4	CMU	Blue	None	0	0	Negative
1	1	Showers in Boy's Locker Room (Visitor)	Ceiling	Concrete	White	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	W1	CMU	Blue	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	W2	CMU	Blue	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	W3	CMU	Blue	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	W4	CMU	Blue	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	Ceiling	Concrete	White	None	0	0	Negative
1	1	Bathroom in Boy's Locker Room (Visitor)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Locker Room next to Transformer Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Locker Room next to Transformer Room	W1	CMU	White	None	0	0	Negative
1	1	Locker Room next to Transformer Room	W2	CMU	Blue	None	0	0	Negative
1	1	Locker Room next to Transformer Room	W3	CMU	White	None	0	0	Negative
1	1	Locker Room next to Transformer Room	W4	CMU	Blue	None	0	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Locker Room next to Transformer Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Locker Room next to Transformer Room	Locker	Wood	Blue	None	0	0	Negative
1	1	Locker Room next to Transformer Room	Door Frame	Metal	Blue	None	0	0	Negative
1	1	Locker Room next to Transformer Room	Door	Metal	Blue	None	0	0	Negative
1	1	Garage	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage	Garage Door Frame	Metal	Blue	Chipping	5	8.6	Positive
1	1	Boiler Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boiler Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boiler Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boiler Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boiler Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Boiler Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	Building Engineer's Office next to Garage	W1	CMU	White	None	0	0	Negative
1	1	Building Engineer's Office next to Garage	W2	CMU	White	None	0	0	Negative
1	1	Building Engineer's Office next to Garage	W3	CMU	White	None	0	0	Negative
1	1	Building Engineer's Office next to Garage	W4	CMU	White	None	0	0	Negative
1	1	Building Engineer's Office next to Garage	Ceiling	Concrete	White	None	0	0	Negative
1	1	Building Engineer's Office next to Garage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office next to Garage	Garage Door Frame	Metal	Blue	Chipping	5	12.7	Positive
1	1	Women's Restroom	W1	CMU	Blue	None	0	0	Negative
1	1	Women's Restroom	W2	CMU	Blue	None	0	0	Negative
1	1	Women's Restroom	W3	CMU	Blue	None	0	0	Negative
1	1	Women's Restroom	W4	CMU	Blue	Efflorescence	100	0	Negative
1	1	Women's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Women's Restroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom	Door	Metal	Blue	Chipping	2	0	Negative
1	1	Women's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	W1	CMU	Blue	None	0	0	Negative
1	1	Men's Restroom	W2	CMU	Blue	Flaking	2	0	Negative
1	1	Men's Restroom	W3	CMU	Blue	None	0	0	Negative
1	1	Men's Restroom	W4	CMU	Blue	None	0	0	Negative
1	1	Men's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom	Door	Metal	Blue	Chipping	1	0	Negative
1	1	Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Crawl Space in back of Men's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Men's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Men's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Men's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Men's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	Ceiling	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase by Sinks in Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room (Home)	W1	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Home)	W2	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Home)	W3	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Home)	W4	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room (Home)	Ceiling	Concrete	White	Flaking	100	0	Negative
1	1	Boy's Locker Room (Home)	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room (Home)	Door	Metal	Blue	None	0	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Boy's Locker Room (Home)	Door Frame	Metal	Blue	None	0	0	Negative
1	1	Crawl Space in back of Boy's Locker Room (Home)	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Boy's Locker Room (Home)	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Boy's Locker Room (Home)	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Boy's Locker Room (Home)	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Boy's Locker Room (Home)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Crawl Space in back of Boy's Locker Room (Home)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Shower (Home)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Shower (Home)	W1	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Shower (Home)	W2	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Shower (Home)	W3	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Shower (Home)	W4	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Shower (Home)	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	W1	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	W2	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	W3	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	W4	CMU	Blue	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Locker Room Restroom (Home)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage next to Transformer Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage next to Transformer Room	W1	CMU	Blue	None	0	0	Negative
1	1	Garage next to Transformer Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage next to Transformer Room	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage next to Transformer Room	W4	Sheetrock	Blue	None	0	0	Negative
1	1	Garage next to Transformer Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Garage next to Transformer Room	Door Frame	Metal	Blue	None	0	0	Negative
1	1	Garage next to Transformer Room	Door	Metal	Blue	None	0	0	Negative
1	1	Garage next to Transformer Room	Garage Door Frame	Metal	Blue	Chipping	5	8.6	Positive
1	1	Transformer Room	W1	CMU	Blue	None	0	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Transformer Room	W2	CMU	Blue	None	0	0	Negative
1	1	Transformer Room	W3	CMU	Blue	None	0	0	Negative
1	1	Transformer Room	W4	CMU	Blue	Cracking	20	0	Negative
1	1	Transformer Room	Ceiling	Concrete	Black	None	0	0	Negative
1	1	Transformer Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Transformer Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Transformer Room	Door	Metal	Blue	Chipping	4	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Closest to Northeast Ave.	W1	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	W2	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	W3	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	W4	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	Ceiling	Concrete	White	Flaking	50	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Closest to Northeast Ave.	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave.	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Locker Room farthest from Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Locker Room farthest from Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Locker Room farthest from Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Locker Room farthest from Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Locker Room farthest from Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Locker Room farthest from Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Locker Room farthest from Northeast Ave	Ceiling	Concrete	White	Cracking	20	0	Negative
2	1	Locker Room farthest from Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	W4	CMU	Blue	None	0	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Restroom in Locker Room farthest from Northeast Ave	Ceiling	Concrete	White	Flaking	100	0	Negative
2	1	Restroom in Locker Room farthest from Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Closet in Locker Room farthest from Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Closet in Locker Room farthest from Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Showers in Locker Room farthest from Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Showers in Locker Room farthest from Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Showers in Locker Room farthest from Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Showers in Locker Room farthest from Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Showers in Locker Room farthest from Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Showers in Locker Room farthest from Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	W1	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	W2	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	W3	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	W4	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	Ceiling	Concrete	White	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Shower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Girl's Locker Room Closest to Northeast Ave. Restroom	Ceiling	Concrete	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	Door Frame	Metal	Blue	Chipping	1	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Large Garage next to Boiler Room	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Large Garage next to Boiler Room	W1	CMU	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	W2	CMU	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	W3	CMU	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	W4	CMU	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
2	1	Large Garage next to Boiler Room	Garage Door	Metal	Blue	Chipping	1	0	Negative
2	1	Large Garage next to Boiler Room	Garage Door Frame	Metal	Blue	Chipping	5	17.5	Positive
2	1	Garage to right of Large Garage next to Boiler Room	Garage Door	Metal	Blue	Chipping	1	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	Garage Door Frame	Metal	Blue	Chipping	5	22.1	Positive
2	1	Garage to right of Large Garage next to Boiler Room	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	W1	CMU	White	None	0	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	W2	CMU	White	None	0	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	W3	CMU	White	None	0	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	W4	CMU	White	None	0	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
2	1	Garage to right of Large Garage next to Boiler Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Garage Door	Metal	Blue	Chipping	1	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Garage Door Frame	Metal	Blue	Chipping	5	12.6	Positive
2	1	Garage next to Locker Room farthest from Northeast Ave	W1	CMU	White	None	0	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	W2	CMU	White	None	0	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	W3	CMU	White	None	0	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	W4	CMU	White	None	0	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Garage next to Locker Room farthest from Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Coaching Staff Office next to Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	Door	Metal	Blue	Chipping	1	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Coaching Staff Office next to Men's Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	Ceiling	Concrete	White	Flaking	20	0	Negative
2	1	Coaching Staff Office next to Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Shower in Coaching Staff Office next to Men's Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Shower in Coaching Staff Office next to Men's Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Shower in Coaching Staff Office next to Men's Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Shower in Coaching Staff Office next to Men's Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Shower in Coaching Staff Office next to Men's Restroom	Ceiling	Concrete	White	Flaking	20	0	Negative
2	1	Shower in Coaching Staff Office next to Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Restroom in Coaching Staff Office next to Men's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	Ceiling	Concrete	White	Flaking	20	0	Negative
2	1	Restroom in Coaching Staff Office next to Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Storage Room connected to Coaching Staff Office next to M	W1	CMU	White	None	0	0	Negative
2	1	Storage Room connected to Coaching Staff Office next to M	W2	CMU	White	None	0	0	Negative
2	1	Storage Room connected to Coaching Staff Office next to M	W3	CMU	White	None	0	0	Negative
2	1	Storage Room connected to Coaching Staff Office next to M	W4	CMU	White	None	0	0	Negative
2	1	Storage Room connected to Coaching Staff Office next to M	Ceiling	Concrete	White	None	0	0	Negative
2	1	Storage Room connected to Coaching Staff Office next to M	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Restroom in Storage Room connected to Coaching Staff Off	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	W1	CMU	White	None	0	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Restroom in Storage Room connected to Coaching Staff Off	W2	CMU	White	None	0	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	W3	CMU	White	None	0	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	W4	CMU	White	None	0	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	Ceiling	Concrete	White	None	0	0	Negative
2	1	Restroom in Storage Room connected to Coaching Staff Off	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Boiler Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Boiler Room	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Boiler Room	W1	CMU	White	Chipping	10	0	Negative
2	1	Boiler Room	W2	CMU	White	Chipping	10	0	Negative
2	1	Boiler Room	W3	CMU	White	Chipping	10	0	Negative
2	1	Boiler Room	W4	CMU	White	Chipping	10	0	Negative
2	1	Boiler Room	Ceiling	Concrete	White	Chipping	100	0	Negative
2	1	Girl's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Girl's Restroom	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Girl's Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Girl's Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Girl's Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Girl's Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Girl's Restroom	Ceiling	Concrete	White	Flaking	20	0	Negative
2	1	Girl's Restroom	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Boy's Restroom	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Boy's Restroom	W1	CMU	Blue	None	0	0	Negative
2	1	Boy's Restroom	W2	CMU	Blue	None	0	0	Negative
2	1	Boy's Restroom	W3	CMU	Blue	None	0	0	Negative
2	1	Boy's Restroom	W4	CMU	Blue	None	0	0	Negative
2	1	Boy's Restroom	Ceiling	Concrete	White	Flaking	20	0	Negative
2	1	Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Crawl Space in back of Boy's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Crawl Space in back of Boy's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Crawl Space in back of Boy's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Crawl Space in back of Boy's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Crawl Space in back of Boy's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Crawl Space in back of Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Urinals in Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Pipe Chase next to Sinks in Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Weight Room	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Weight Room	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Weight Room	W1	CMU	Blue	Cracking	10	0	Negative
2	1	Weight Room	W2	CMU	Blue	Cracking	10	0	Negative
2	1	Weight Room	W3	CMU	Blue	Cracking	10	0	Negative
2	1	Weight Room	W4	CMU	Blue	Cracking	10	0	Negative
2	1	Weight Room	Ceiling	Concrete	White	Cracking	50	0	Negative
2	1	Weight Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Boy's Locker Room 2nd closest to Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	W1	CMU	Blue	Cracking	10	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	W2	CMU	Blue	Cracking	10	0	Negative

Dates: 10/6/23

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number: Erik Swanson #006917

George Washington High School Field House

Inspection Company: Viva

800 Selmar Rd, Philadelphia PA 19116

Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
2	1	Boy's Locker Room 2nd closest to Northeast Ave	W3	CMU	Blue	Cracking	10	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	W4	CMU	Blue	Cracking	10	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	Ceiling	Concrete	White	Cracking	50	0	Negative
2	1	Boy's Locker Room 2nd closest to Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Closet in Boy's Locker Room 2nd closest to Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	Door Frame	Metal	Blue	Chipping	1	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	Door	Metal	Blue	Chipping	1	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Showers in Boy's Locker Room 2nd closest to Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	W1	CMU	Blue	None	0	0	Negative
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	W2	CMU	Blue	None	0	0	Negative
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	W3	CMU	Blue	None	0	0	Negative
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	W4	CMU	Blue	None	0	0	Negative
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	Ceiling	Concrete	White	None	0	0	Negative
2	1	Restroom in Boy's Locker Room 2nd closest to Northeast Ave	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.