

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Learning Center 100	Door Frame 1	Metal	Purple	Chipping	1	0	Negative
1	1	Learning Center 100	Door Frame 2	Metal	Purple	Chipping	1	0	Negative
1	1	Learning Center 100	Door Frame 3	Metal	Purple	None	0	0	Negative
1	1	Learning Center 100	Door Frame 4	Metal	Purple	Chipping	1	0	Negative
1	1	Learning Center 100	Column 1	Concrete	Purple	None	0	0	Negative
1	1	Learning Center 100	Column 2	Concrete	Purple	None	0	0	Negative
1	1	Learning Center 100	Column 3	Concrete	Purple	None	0	0	Negative
1	1	Learning Center 100	Column 4	CMU	Purple	None	0	0	Negative
1	1	Learning Center 100	W1	CMU	White	None	0	0	Negative
1	1	Learning Center 100	W2	CMU	White	None	0	0	Negative
1	1	Learning Center 100	W3	CMU	White	None	0	0	Negative
1	1	Learning Center 100	W4	CMU	White	None	0	0	Negative
1	1	Learning Center 100	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Learning Center 100	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Closet 100A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100B	W1	CMU	Orange	None	0	0	Negative
1	1	Office 100B	W2	CMU	Blue	None	0	0	Negative
1	1	Office 100B	W3	CMU	Orange	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Office 100B	W4	CMU	Blue	None	0	0	Negative
1	1	Office 100B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100C	W1	CMU	Blue	None	0	0	Negative
1	1	Office 100C	W2	CMU	Blue	None	0	0	Negative
1	1	Office 100C	W3	CMU	Blue	None	0	0	Negative
1	1	Office 100C	W4	CMU	Blue	None	0	0	Negative
1	1	Office 100C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100D	W1	CMU	White	None	0	0	Negative
1	1	Office 100D	W2	CMU	White	None	0	0	Negative
1	1	Office 100D	W3	CMU	White	None	0	0	Negative
1	1	Office 100D	W4	CMU	White	None	0	0	Negative
1	1	Office 100D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100E	W1	CMU	White	None	0	0	Negative
1	1	Office 100E	W2	CMU	White	None	0	0	Negative
1	1	Office 100E	W3	CMU	White	None	0	0	Negative
1	1	Office 100E	W4	CMU	White	None	0	0	Negative
1	1	Office 100E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100F	W1	CMU	Blue	None	0	0	Negative
1	1	Office 100F	W2	CMU	Blue	None	0	0	Negative
1	1	Office 100F	W3	CMU	Blue	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Office 100F	W4	CMU	Blue	None	0	0	Negative
1	1	Office 100F	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100F	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100G	W1	CMU	Blue	None	0	0	Negative
1	1	Office 100G	W2	CMU	Blue	None	0	0	Negative
1	1	Office 100G	W3	CMU	White	None	0	0	Negative
1	1	Office 100G	W4	CMU	Blue	None	0	0	Negative
1	1	Office 100G	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 100G	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	W1	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	W2	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	W3	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	W4	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	Ceiling	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 100H	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100I	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Closet 100I	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100I	W2	CMU	White	None	0	0	Negative
1	1	Storage Closet 100I	W3	CMU	White	None	0	0	Negative
1	1	Storage Closet 100I	W4	CMU	White	None	0	0	Negative
1	1	Storage Closet 100I	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 100I	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 101	Door Frame	Metal	Gray	Chipping	3	0	Negative
1	1	Classroom 101	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 101	W2	CMU	White	None	0	0	Negative
1	1	Classroom 101	W3	CMU	White	Flaking	12	0	Negative
1	1	Classroom 101	W4	CMU	White	Flaking	6	0	Negative
1	1	Classroom 101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 101	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 102	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Classroom 102	W1	CMU	White	Cracking	1	0	Negative
1	1	Classroom 102	W2	CMU	White	None	0	0	Negative
1	1	Classroom 102	W3	CMU	White	Chipping	15	0	Negative
1	1	Classroom 102	W4	CMU	White	None	0	0	Negative
1	1	Classroom 102	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Office 103	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Teacher's Office 103	W1	CMU	White	None	0	0	Negative
1	1	Teacher's Office 103	W2	CMU	White	None	0	0	Negative
1	1	Teacher's Office 103	W3	CMU	White	None	0	0	Negative
1	1	Teacher's Office 103	W4	CMU	White	None	0	0	Negative
1	1	Teacher's Office 103	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Office 103	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 104	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Classroom 104	W1	CMU	White	Flaking	1	0	Negative
1	1	Classroom 104	W2	CMU	White	Flaking	5	0	Negative
1	1	Classroom 104	W3	CMU	Red	None	0	0	Negative
1	1	Classroom 104	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 105	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Classroom 105	W1	CMU	Blue	Flaking	1	0	Negative
1	1	Classroom 105	W2	CMU	Purple	None	0	0	Negative
1	1	Classroom 105	W3	CMU	Blue	None	0	0	Negative
1	1	Classroom 105	W4	CMU	Blue	None	0	0	Negative
1	1	Classroom 105	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 105	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 106	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 106	W1	CMU	White	Cracking	1	0	Negative
1	1	Classroom 106	W2	CMU	White	None	0	0	Negative
1	1	Classroom 106	W3	CMU	White	None	0	0	Negative
1	1	Classroom 106	W4	CMU	White	None	0	0	Negative
1	1	Classroom 106	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 106	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 107	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 107	W1	CMU	White	None	0	0	Negative
1	1	Classroom 107	W2	CMU	White	None	0	0	Negative
1	1	Classroom 107	W3	CMU	White	Flaking	30	0	Negative
1	1	Classroom 107	W4	CMU	White	None	0	0	Negative
1	1	Classroom 107	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 107	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 108	Door Frame	Metal	Gray	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 108	W1	CMU	White	Cracking	2	0	Negative
1	1	Classroom 108	W2	CMU	White	Flaking	1	0	Negative
1	1	Classroom 108	W3	CMU	White	None	0	0	Negative
1	1	Classroom 108	W4	CMU	White	None	0	0	Negative
1	1	Classroom 108	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 108	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 109	Door Frame	Metal	Gray	Chipping	3	0	Negative
1	1	Classroom 109	W1	CMU	White	None	0	0	Negative
1	1	Classroom 109	W2	CMU	Purple	None	0	0	Negative
1	1	Classroom 109	W3	CMU	White	None	0	0	Negative
1	1	Classroom 109	W4	CMU	White	None	0	0	Negative
1	1	Classroom 109	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 109	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 110	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Classroom 110	W1	CMU	Blue	Chipping	1	0	Negative
1	1	Classroom 110	W2	CMU	Blue	None	0	0	Negative
1	1	Classroom 110	W3	CMU	Blue	None	0	0	Negative
1	1	Classroom 110	W4	CMU	Blue	Flaking	2	0	Negative
1	1	Classroom 110	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 110	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 111	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 111	W1	CMU	White	None	0	0	Negative
1	1	Classroom 111	W2	CMU	White	None	0	0	Negative
1	1	Classroom 111	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 111	W4	CMU	White	None	0	0	Negative
1	1	Classroom 111	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 111	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	112A Pantry	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	112A Pantry	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A	Door Frame 1	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112A	Door Frame 2	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112A	Door Frame 3	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112A	Door Frame 4	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112A	W1	CMU	Multi	None	0	0	Negative
1	1	Cafeteria 112A	W2	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112A	W3	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112A	W4	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B	Door Frame 1	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112B	Door Frame 2	Metal	Purple	Chipping	1	0	Negative
1	1	Cafeteria 112B	W1	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112B	W2	CMU	Yellow	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Cafeteria 112B	W3	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112B	W4	CMU	Yellow	None	0	0	Negative
1	1	Cafeteria 112B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Cafeteria 112A Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112A Storage Room	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Cafeteria 112B Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Cafeteria 112B Storage Room	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Mechanical Room In Cafeteria 112A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Mechanical Room In Cafeteria 112A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Mechanical Room In Cafeteria 112A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Mechanical Room In Cafeteria 112A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Mechanical Room In Cafeteria 112A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Mechanical Room In Cafeteria 112A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Mechanical Room In Cafeteria 112A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Faculty Lounge 113	W1	CMU	White	None	0	0	Negative
1	1	Faculty Lounge 113	W2	CMU	White	None	0	0	Negative
1	1	Faculty Lounge 113	W3	CMU	White	None	0	0	Negative
1	1	Faculty Lounge 113	W4	CMU	White	None	0	0	Negative
1	1	Faculty Lounge 113	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Faculty Lounge 113	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 113A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 113B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom 114C	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom 114C	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom 114C	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom 114C	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Restroom 114C	Ceiling	Sheetrock	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Girl's Restroom 114C	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom 114D	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom 114D	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom 114D	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom 114D	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Restroom 114D	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Boy's Restroom 114D	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 115	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Classroom 115	W1	CMU	Purple	None	0	0	Negative
1	1	Classroom 115	W2	CMU	White	None	0	0	Negative
1	1	Classroom 115	W3	CMU	White	None	0	0	Negative
1	1	Classroom 115	W4	CMU	White	None	0	0	Negative
1	1	Classroom 115	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 115	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 116	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 116	W1	CMU	White	None	0	0	Negative
1	1	Classroom 116	W2	CMU	White	Chipping	2	0	Negative
1	1	Classroom 116	W3	CMU	White	None	0	0	Negative
1	1	Classroom 116	W4	CMU	White	Flaking	10	0	Negative
1	1	Classroom 116	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 116	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 117	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 117	W1	CMU	White	None	0	0	Negative
1	1	Classroom 117	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 117	W3	CMU	White	None	0	0	Negative
1	1	Classroom 117	W4	CMU	White	None	0	0	Negative
1	1	Classroom 117	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 117	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 118	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 118	W1	CMU	Blue	None	0	0	Negative
1	1	Classroom 118	W2	CMU	Blue	None	0	0	Negative
1	1	Classroom 118	W3	CMU	Blue	None	0	0	Negative
1	1	Classroom 118	W4	CMU	Blue	None	0	0	Negative
1	1	Classroom 118	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 118	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Office 119	W1	CMU	White	None	0	0	Negative
1	1	Teacher's Office 119	W2	CMU	White	None	0	0	Negative
1	1	Teacher's Office 119	W3	CMU	White	None	0	0	Negative
1	1	Teacher's Office 119	W4	CMU	White	None	0	0	Negative
1	1	Teacher's Office 119	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Teacher's Office 119	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 120	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 120	W1	CMU	White	None	0	0	Negative
1	1	Classroom 120	W2	CMU	Blue	None	0	0	Negative
1	1	Classroom 120	W3	CMU	White	None	0	0	Negative
1	1	Classroom 120	W4	CMU	White	None	0	0	Negative
1	1	Classroom 120	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 120	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 121	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 121	W1	CMU	White	None	0	0	Negative
1	1	Classroom 121	W2	CMU	White	None	0	0	Negative
1	1	Classroom 121	W3	CMU	White	None	0	0	Negative
1	1	Classroom 121	W4	CMU	White	None	0	0	Negative
1	1	Classroom 121	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 121	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 122	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 122	W1	CMU	White	None	0	0	Negative
1	1	Classroom 122	W2	CMU	White	None	0	0	Negative
1	1	Classroom 122	W3	CMU	White	None	0	0	Negative
1	1	Classroom 122	W4	CMU	White	None	0	0	Negative
1	1	Classroom 122	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 122	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 123	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 123	W1	CMU	White	None	0	0	Negative
1	1	Classroom 123	W2	CMU	White	None	0	0	Negative
1	1	Classroom 123	W3	CMU	White	None	0	0	Negative
1	1	Classroom 123	W4	CMU	White	None	0	0	Negative
1	1	Classroom 123	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 123	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 124	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Classroom 124	W1	CMU	White	None	0	0	Negative
1	1	Classroom 124	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Classroom 124	W3	CMU	White	None	0	0	Negative
1	1	Classroom 124	W4	CMU	White	None	0	0	Negative
1	1	Classroom 124	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 124	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 125	W1	CMU	White	None	0	0	Negative
1	1	Classroom 125	W2	CMU	White	None	0	0	Negative
1	1	Classroom 125	W3	CMU	White	None	0	0	Negative
1	1	Classroom 125	W4	CMU	White	None	0	0	Negative
1	1	Classroom 125	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Classroom 125	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Learning Center 126	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	1	Learning Center 126	Door Frame 2	Metal	Gray	None	0	0	Negative
1	1	Learning Center 126	Door Frame 3	Metal	Gray	None	0	0	Negative
1	1	Learning Center 126	Door Frame 4	Metal	Gray	None	0	0	Negative
1	1	Learning Center 126	Column 1	Concrete	Blue	None	0	0	Negative
1	1	Learning Center 126	Column 2	Concrete	Purple	None	0	0	Negative
1	1	Learning Center 126	Column 3	Concrete	Purple	None	0	0	Negative
1	1	Learning Center 126	Column 4	CMU	Blue	None	0	0	Negative
1	1	Learning Center 126	W1	CMU	Blue	None	0	0	Negative
1	1	Learning Center 126	W2	CMU	Blue	None	0	0	Negative
1	1	Learning Center 126	W3	CMU	Blue	None	0	0	Negative
1	1	Learning Center 126	W4	CMU	Blue	None	0	0	Negative
1	1	Learning Center 126	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Learning Center 126	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Closet 126A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Closet 126A	W1	CMU	White	None	0	0	Negative
1	1	Storage Closet 126A	W2	CMU	White	None	0	0	Negative
1	1	Storage Closet 126A	W3	CMU	White	None	0	0	Negative
1	1	Storage Closet 126A	W4	CMU	White	None	0	0	Negative
1	1	Storage Closet 126A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 126A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126B	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Office 126B	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126B	W2	CMU	Blue	None	0	0	Negative
1	1	Office 126B	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126B	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126C	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Office 126C	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126C	W2	CMU	Blue	None	0	0	Negative
1	1	Office 126C	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126C	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126D	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Office 126D	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126D	W2	CMU	Blue	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Office 126D	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126D	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126E	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Office 126E	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126E	W2	CMU	Blue	None	0	0	Negative
1	1	Office 126E	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126E	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126F	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Office 126F	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126F	W2	CMU	Blue	None	0	0	Negative
1	1	Office 126F	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126F	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126F	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126F	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 126G	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Office 126G	W1	CMU	Blue	None	0	0	Negative
1	1	Office 126G	W2	CMU	Blue	None	0	0	Negative
1	1	Office 126G	W3	CMU	Blue	None	0	0	Negative
1	1	Office 126G	W4	CMU	Blue	None	0	0	Negative
1	1	Office 126G	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Office 126G	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 126H	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Custodial Closet 126H	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 126H	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 126H	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 126H	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Custodial Closet 126H	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Custodial Closet 126H	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 126I	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Storage Closet 126I	W1	CMU	White	None	0	0	Negative
1	1	Storage Closet 126I	W2	CMU	White	None	0	0	Negative
1	1	Storage Closet 126I	W3	CMU	White	None	0	0	Negative
1	1	Storage Closet 126I	W4	CMU	White	None	0	0	Negative
1	1	Storage Closet 126I	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet 126I	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Maintenance Storage Room 127A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room 127B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room 127B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room 127B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Electrical Room 127B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room 127B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room 127B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room Between 127A and 127B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	School Store 128	W1	CMU	White	None	0	0	Negative
1	1	School Store 128	W2	CMU	White	None	0	0	Negative
1	1	School Store 128	W3	CMU	White	None	0	0	Negative
1	1	School Store 128	W4	CMU	White	None	0	0	Negative
1	1	School Store 128	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	School Store 128	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office Suite 129	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Building Engineer's Office Suite 129	W1	CMU	Tan	None	0	0	Negative
1	1	Building Engineer's Office Suite 129	W2	CMU	Tan	None	0	0	Negative
1	1	Building Engineer's Office Suite 129	W3	CMU	Tan	None	0	0	Negative
1	1	Building Engineer's Office Suite 129	W4	CMU	Tan	None	0	0	Negative
1	1	Building Engineer's Office Suite 129	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Building Engineer's Office Suite 129	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 129A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Women's Restroom 129A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Women's Restroom 129A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 129A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 129A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Women's Restroom 129A	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Women's Restroom 129A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 129B	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Men's Restroom 129B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 129B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 129B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 129B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom 129B	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Men's Restroom 129B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Men's Restroom 129B	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	1	Pipe Chase In Men's Restroom 129B	W1	CMU	White	None	0	0	Negative
1	1	Pipe Chase In Men's Restroom 129B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Men's Restroom 129B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Men's Restroom 129B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Men's Restroom 129B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Men's Restroom 129B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129C	Door Frame	metal	Gray	None	0	0	Negative
1	1	Office 129C	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129C	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129C	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129C	W4	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Office 129C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129C	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129D	W1	CMU	White	None	0	0	Negative
1	1	Office 129D	W2	CMU	White	None	0	0	Negative
1	1	Office 129D	W3	CMU	White	None	0	0	Negative
1	1	Office 129D	W4	CMU	White	None	0	0	Negative
1	1	Office 129D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office 129D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 130A	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 130A	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 130A	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 130A	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 130A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 130A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Manufacturing Technology Room 131	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Manufacturing Technology Room 131	W1	CMU	Blue	None	0	0	Negative
1	1	Manufacturing Technology Room 131	W2	CMU	Blue	None	0	0	Negative
1	1	Manufacturing Technology Room 131	W3	CMU	Blue	None	0	0	Negative
1	1	Manufacturing Technology Room 131	W4	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	1	Manufacturing Technology Room 131	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Manufacturing Technology Room 131	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Clean Room 131A	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Clean Room 131A	W1	CMU	Blue	None	0	0	Negative
1	1	Clean Room 131A	W2	CMU	Blue	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Clean Room 131A	W3	CMU	Blue	None	0	0	Negative
1	1	Clean Room 131A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Clean Room 131A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Clean Room 131A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Clean Room 131A	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Storage Room 131B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 131B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 131B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 131B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 131B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 131B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Industrial Art Storage Room 132	W1	CMU	White	None	0	0	Negative
1	1	Industrial Art Storage Room 132	W2	CMU	White	None	0	0	Negative
1	1	Industrial Art Storage Room 132	W2	Sheetrock	White	None	0	0	Negative
1	1	Industrial Art Storage Room 132	W3	CMU	White	None	0	0	Negative
1	1	Industrial Art Storage Room 132	W4	CMU	White	None	0	0	Negative
1	1	Industrial Art Storage Room 132	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Industrial Art Storage Room 132	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Industrial Arts Department Room 133	W1	CMU	White	None	0	0	Negative
1	1	Industrial Arts Department Room 133	W2	CMU	White	None	0	0	Negative
1	1	Industrial Arts Department Room 133	W3	CMU	White	None	0	0	Negative
1	1	Industrial Arts Department Room 133	W4	CMU	White	None	0	0	Negative
1	1	Industrial Arts Department Room 133	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Industrial Arts Department Room 133	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Sorting Room T134	W1	CMU	White	None	0	0	Negative
1	1	Sorting Room T134	W2	CMU	White	None	0	0	Negative
1	1	Sorting Room T134	W3	CMU	White	None	0	0	Negative
1	1	Sorting Room T134	W4	CMU	White	None	0	0	Negative
1	1	Sorting Room T134	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Sorting Room T134	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 134A	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 134A	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 134A	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 134A	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 134A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 134A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 134B	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 134B	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 134B	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 134B	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 134B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 134B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Auto Technology Room 135	W1	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 135	W2	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 135	W3	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 135	W4	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 135	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Auto Technology Room 135	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Auto Technology Lecture Room 135A	W1	CMU	White	None	0	0	Negative
1	1	Auto Technology Lecture Room 135A	W2	CMU	White	None	0	0	Negative
1	1	Auto Technology Lecture Room 135A	W3	CMU	White	None	0	0	Negative
1	1	Auto Technology Lecture Room 135A	W4	CMU	White	None	0	0	Negative
1	1	Auto Technology Lecture Room 135A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Auto Technology Lecture Room 135A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 135B	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 135B	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 135B	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 135B	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 135B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 135B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 135C	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 135D	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 135D	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 135D	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 135D	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 135D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 135D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Auto Technology Room 136	W1	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 136	W2	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 136	W3	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 136	W4	CMU	White	None	0	0	Negative
1	1	Auto Technology Room 136	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Auto Technology Room 136	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 136A	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 136A	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 136A	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 136A	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 136A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 136A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Restroom 136B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Book Bank Room 137	W1	CMU	White	None	0	0	Negative
1	1	Book Bank Room 137	W2	CMU	White	None	0	0	Negative
1	1	Book Bank Room 137	W3	CMU	White	None	0	0	Negative
1	1	Book Bank Room 137	W4	CMU	White	None	0	0	Negative
1	1	Book Bank Room 137	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Book Bank Room 137	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Room 137A	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 137A	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 137A	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 137A	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 137A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 137A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 137B	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 137B	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 137B	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 137B	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 137B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 137B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Power Technology Room 138	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Power Technology Room 138	W1	CMU	White	None	0	0	Negative
1	1	Power Technology Room 138	W2	CMU	White	None	0	0	Negative
1	1	Power Technology Room 138	W3	CMU	White	None	0	0	Negative
1	1	Power Technology Room 138	W4	CMU	White	None	0	0	Negative
1	1	Power Technology Room 138	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Power Technology Room 138	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 138A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Room 138A	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 138A	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 138A	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 138A	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Room 138A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 138A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms in 138	Door Frame	Metal	White	Chipping	1	0	Negative
1	1	Student Restrooms in 138	W1	Sheetrock	White	None	0	0	Negative
1	1	Student Restrooms in 138	W2	Sheetrock	White	None	0	0	Negative
1	1	Student Restrooms in 138	W3	Sheetrock	White	None	0	0	Negative
1	1	Student Restrooms in 138	W4	Sheetrock	White	None	0	0	Negative
1	1	Student Restrooms in 138	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Student Restrooms in 138	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Staff Restroom in 138	Door Frame	Metal	White	Chipping	1	0	Negative
1	1	Staff Restroom in 138	W1	Sheetrock	White	None	0	0	Negative
1	1	Staff Restroom in 138	W2	Sheetrock	White	None	0	0	Negative
1	1	Staff Restroom in 138	W3	Sheetrock	White	None	0	0	Negative
1	1	Staff Restroom in 138	W4	Sheetrock	White	None	0	0	Negative
1	1	Staff Restroom in 138	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Staff Restroom in 138	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Office in 138 Near Staff Restroom	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Office in 138 Near Staff Restroom	W1	CMU	White	None	0	0	Negative
1	1	Office in 138 Near Staff Restroom	W2	CMU	White	None	0	0	Negative
1	1	Office in 138 Near Staff Restroom	W3	CMU	White	None	0	0	Negative
1	1	Office in 138 Near Staff Restroom	W4	CMU	White	None	0	0	Negative
1	1	Office in 138 Near Staff Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Office in 138 Near Staff Restroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Kitchen in 138	Door Frame	Metal	Gray	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Kitchen in 138	W1	CMU	White	None	0	0	Negative
1	1	Kitchen in 138	W2	CMU	White	None	0	0	Negative
1	1	Kitchen in 138	W3	CMU	White	None	0	0	Negative
1	1	Kitchen in 138	W4	CMU	White	None	0	0	Negative
1	1	Kitchen in 138	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Kitchen in 138	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage inside Kitchen 138E	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Storage inside Kitchen 138E	W1	CMU	White	None	0	0	Negative
1	1	Storage inside Kitchen 138E	W2	CMU	White	None	0	0	Negative
1	1	Storage inside Kitchen 138E	W3	CMU	White	None	0	0	Negative
1	1	Storage inside Kitchen 138E	W4	CMU	White	None	0	0	Negative
1	1	Storage inside Kitchen 138E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage inside Kitchen 138E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage in 138G	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Storage in 138G	W1	CMU	White	None	0	0	Negative
1	1	Storage in 138G	W2	CMU	White	None	0	0	Negative
1	1	Storage in 138G	W3	CMU	White	None	0	0	Negative
1	1	Storage in 138G	W4	CMU	White	None	0	0	Negative
1	1	Storage in 138G	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage in 138G	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 139	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 139	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 139	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 139	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Room 139	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 139	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen	W1	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen	W2	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen	W3	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen	W4	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen Office	W1	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Office	W2	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Office	W3	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Office	W4	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen Office	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen Dry Storage	W1	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Dry Storage	W2	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Dry Storage	W3	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Dry Storage	W4	CMU	White	None	0	0	Negative
1	1	First Floor Kitchen Dry Storage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	First Floor Kitchen Dry Storage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Kitchen receiving/Custodial Room	W1	CMU	White	None	0	0	Negative
1	1	Kitchen receiving/Custodial Room	W2	CMU	White	None	0	0	Negative
1	1	Kitchen receiving/Custodial Room	W3	CMU	White	None	0	0	Negative
1	1	Kitchen receiving/Custodial Room	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Kitchen receiving/Custodial Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Kitchen receiving/Custodial Room	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Faculty Cafeteria 140	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Faculty Cafeteria 140	W1	CMU	White	None	0	0	Negative
1	1	Faculty Cafeteria 140	W2	CMU	White	None	0	0	Negative
1	1	Faculty Cafeteria 140	W3	CMU	White	None	0	0	Negative
1	1	Faculty Cafeteria 140	W4	CMU	White	None	0	0	Negative
1	1	Faculty Cafeteria 140	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Faculty Cafeteria 140	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Locker Room 140A	W1	CMU	White	None	0	0	Negative
1	1	Locker Room 140A	W2	CMU	White	None	0	0	Negative
1	1	Locker Room 140A	W3	CMU	White	None	0	0	Negative
1	1	Locker Room 140A	W4	CMU	White	None	0	0	Negative
1	1	Locker Room 140A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Locker Room 140A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room 141	W1	CMU	White	None	0	0	Negative
1	1	Stock Room 141	W2	CMU	White	None	0	0	Negative
1	1	Stock Room 141	W3	CMU	White	None	0	0	Negative
1	1	Stock Room 141	W4	CMU	White	None	0	0	Negative
1	1	Stock Room 141	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room 141	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 171	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 171	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 171	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Room 171	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 171	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 171	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 172	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 172	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 172	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 172	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 172	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 172	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 173	W1	CMU	White	None	0	0	Negative
1	1	Storage Room 173	W2	CMU	White	None	0	0	Negative
1	1	Storage Room 173	W3	CMU	White	None	0	0	Negative
1	1	Storage Room 173	W4	CMU	White	None	0	0	Negative
1	1	Storage Room 173	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 173	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Team Room 174	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	1	Team Room 174	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	1	Team Room 174	Duct	Metal	White	Flaking	40	0	Negative
1	1	Team Room 174	W1	CMU	Multi	None	0	0	Negative
1	1	Team Room 174	W2	CMU	Multi	None	0	0	Negative
1	1	Team Room 174	W3	CMU	Multi	None	0	0	Negative
1	1	Team Room 174	W4	CMU	Multi	None	0	0	Negative
1	1	Team Room 174	Ceiling	Concrete	White	None	0	0	Negative
1	1	Team Room 174	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Storage Closet next to Team Room 174	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Closet next to Team Room 174	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Storage Closet next to Team Room 174	Duct	Metal	White	Flaking	20	0	Negative
1	1	Storage Closet next to Team Room 174	W1	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 174	W2	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 174	W3	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 174	W4	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 174	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 174	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet next to Team Room 177	Door Frame	Metal	Grey	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W1	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W1	CMU	Black	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W2	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W2	CMU	Black	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W3	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W3	CMU	Black	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W4	CMU	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	W4	CMU	Black	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage Closet next to Team Room 177	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	1	Boy's Locker Room	Column 1	Concrete	Purple	None	0	0	Negative
1	1	Boy's Locker Room	Column 2	Concrete	Purple	None	0	0	Negative
1	1	Boy's Locker Room	Duct	Metal	White	Flaking	100	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room	W2	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room	W3	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room	W4	Concrete	White	Flaking	150	0	Negative
1	1	Boy's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Boy's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Boy's Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room next to Boy's Locker Room Shower R	Door Frame	Metal	Blue	Chipping	1	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	W1	CMU	White	None	0	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	W2	CMU	White	None	0	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	W3	CMU	White	None	0	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	W4	CMU	White	None	0	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	Ceiling	Concrete	White	Cracking	10	0	Negative
1	1	Storage Room next to Boy's Locker Room Shower R	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Weight Room	Door Frame	Metal	Purple	Cracking	1	0	Negative
1	1	Boy's Locker Room Weight Room	Door Frame	Metal	Purple	None	0	0	Negative
1	1	Boy's Locker Room Weight Room	Duct	Metal	White	Flaking	200	0	Negative
1	1	Boy's Locker Room Weight Room	W1	CMU	Multi	None	0	0	Negative
1	1	Boy's Locker Room Weight Room	W2	CMU	Multi	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Boy's Locker Room Weight Room	W3	CMU	Multi	None	0	0	Negative
1	1	Boy's Locker Room Weight Room	W4	CMU	Multi	None	0	0	Negative
1	1	Boy's Locker Room Weight Room	Ceiling	Concrete	White	Cracking	10	0	Negative
1	1	Boy's Locker Room Weight Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Team Room 177	W1	CMU	White	None	0	0	Negative
1	1	Team Room 177	W2	CMU	White	None	0	0	Negative
1	1	Team Room 177	W3	CMU	White	None	0	0	Negative
1	1	Team Room 177	W4	CMU	White	None	0	0	Negative
1	1	Team Room 177	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Team Room 177	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Boy's Locker Room Shower Room	W1	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room Shower Room	W2	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room Shower Room	W3	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room Shower Room	W4	CMU	White	None	0	0	Negative
1	1	Boy's Locker Room Shower Room	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Boy's Locker Room Shower Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room next to Girl's Locker Room Shower R	W1	CMU	White	None	0	0	Negative
1	1	Storage Room next to Girl's Locker Room Shower R	W2	CMU	White	None	0	0	Negative
1	1	Storage Room next to Girl's Locker Room Shower R	W3	CMU	White	None	0	0	Negative
1	1	Storage Room next to Girl's Locker Room Shower R	W4	CMU	White	None	0	0	Negative
1	1	Storage Room next to Girl's Locker Room Shower R	Ceiling	Concrete	White	None	0	0	Negative
1	1	Storage Room next to Girl's Locker Room Shower R	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room	Door Frame 1	Metal	Gray	None	0	0	Negative
1	1	Girl's Locker Room	Door Frame 2	Metal	Gray	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Girl's Locker Room	Door Frame 3	Metal	Gray	None	0	0	Negative
1	1	Girl's Locker Room	Column 1	Concrete	White	None	0	0	Negative
1	1	Girl's Locker Room	Column 2	Concrete	White	None	0	0	Negative
1	1	Girl's Locker Room	Column 3	Concrete	White	None	0	0	Negative
1	1	Girl's Locker Room	Column 4	Concrete	White	None	0	0	Negative
1	1	Girl's Locker Room	Duct	Metal	White	Flaking	100	0	Negative
1	1	Girl's Locker Room	W1	Concrete	White	Flaking	150	0	Negative
1	1	Girl's Locker Room	W2	Concrete	White	Flaking	10	0	Negative
1	1	Girl's Locker Room	W3	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room	W4	Concrete	White	Flaking	150	0	Negative
1	1	Girl's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	1	Girl's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room	Duct	Metal	White	None	0	0	Negative
1	1	Pipe Chase In Girls Locker Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Girls Locker Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Girls Locker Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Girls Locker Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Girls Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase In Girls Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Restroom	W1	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Restroom	W2	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Restroom	W3	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Restroom	W4	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Restroom	Ceiling	Sheetrock	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Girl's Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 180	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 181	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Sink Room	W1	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Sink Room	W2	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Sink Room	W3	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Sink Room	W4	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Sink Room	Ceiling	Sheetrock	White	None	0	0	Negative
1	1	Girl's Locker Room Sink Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Girl's Locker Room Shower Room	W1	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Shower Room	W2	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Shower Room	W3	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Shower Room	W4	CMU	White	None	0	0	Negative
1	1	Girl's Locker Room Shower Room	Ceiling	Sheetrock	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Girl's Locker Room Shower Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room 183	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	W1	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	W2	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	W3	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	W4	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	Elevator outside of Cafe 112B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Hallway from 127A to 139B	W1	CMU	White	None	0	0	Negative
1	1	Main Hallway from 127A to 139B	W2	CMU	White	None	0	0	Negative
1	1	Main Hallway from 127A to 139B	W3	CMU	White	None	0	0	Negative
1	1	Main Hallway from 127A to 139B	W4	CMU	White	None	0	0	Negative
1	1	Main Hallway from 127A to 139B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Hallway from 127A to 139B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase near Boy's Restroom 114D in H110	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase near Boy's Restroom 114D in H110	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase near Boy's Restroom 114D in H110	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase near Boy's Restroom 114D in H110	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Pipe Chase near Boy's Restroom 114D in H110	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Pipe Chase near Boy's Restroom 114D in H110	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway lobby outside Building Engineer's Office Suite	W1	CMU	White	None	0	0	Negative
1	1	Hallway lobby outside Building Engineer's Office Suite	W2	CMU	White	None	0	0	Negative
1	1	Hallway lobby outside Building Engineer's Office Suite	W3	CMU	White	None	0	0	Negative
1	1	Hallway lobby outside Building Engineer's Office Suite	W4	CMU	White	None	0	0	Negative
1	1	Hallway lobby outside Building Engineer's Office Suite	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway lobby outside Building Engineer's Office Suite	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Hallway to outside 126 Learning Center	W1	CMU	White	None	0	0	Negative
1	1	Main Hallway to outside 126 Learning Center	W2	CMU	White	None	0	0	Negative
1	1	Main Hallway to outside 126 Learning Center	W3	CMU	White	None	0	0	Negative
1	1	Main Hallway to outside 126 Learning Center	W4	CMU	White	None	0	0	Negative
1	1	Main Hallway to outside 126 Learning Center	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Main Hallway to outside 126 Learning Center	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 115 to 116	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 115 to 116	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 115 to 116	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 115 to 116	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 115 to 116	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 115 to 116	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Stairwell to Team Room 174	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Stairwell to Team Room 174	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Stairwell to Team Room 174	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Stairwell to Team Room 174	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Stairwell to Team Room 174	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Hallway from Stairwell to Team Room 174	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from stairs to Storage closet 175	W1	CMU	White	None	0	0	Negative
1	1	Hallway from stairs to Storage closet 175	W2	CMU	White	None	0	0	Negative
1	1	Hallway from stairs to Storage closet 175	W3	CMU	White	None	0	0	Negative
1	1	Hallway from stairs to Storage closet 175	W4	Concrete	White	Flaking	200	0	Negative
1	1	Hallway from stairs to Storage closet 175	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from stairs to Storage closet 175	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from storage room 181 to girl's locker toom	W1	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 181 to girl's locker toom	W2	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 181 to girl's locker toom	W3	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 181 to girl's locker toom	W4	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 181 to girl's locker toom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from storage room 181 to girl's locker toom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from H113 to Girl's Locker Room 179	W1	CMU	White	None	0	0	Negative
1	1	Hallway from H113 to Girl's Locker Room 179	W2	CMU	White	None	0	0	Negative
1	1	Hallway from H113 to Girl's Locker Room 179	W3	CMU	White	None	0	0	Negative
1	1	Hallway from H113 to Girl's Locker Room 179	W4	CMU	White	None	0	0	Negative
1	1	Hallway from H113 to Girl's Locker Room 179	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from H113 to Girl's Locker Room 179	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway between storage rooms 173 and 174	W1	CMU	White	None	0	0	Negative
1	1	Hallway between storage rooms 173 and 174	W2	CMU	White	None	0	0	Negative
1	1	Hallway between storage rooms 173 and 174	W3	CMU	White	None	0	0	Negative
1	1	Hallway between storage rooms 173 and 174	W4	CMU	White	None	0	0	Negative
1	1	Hallway between storage rooms 173 and 174	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Hallway between storage rooms 173 and 174	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from storage room 171 to boy's locker room	W1	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 171 to boy's locker room	W2	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 171 to boy's locker room	W3	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 171 to boy's locker room	W4	CMU	White	None	0	0	Negative
1	1	Hallway from storage room 171 to boy's locker room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from storage room 171 to boy's locker room	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway outside Visual Communication Classroom T	W1	CMU	White	None	0	0	Negative
1	1	Hallway outside Visual Communication Classroom T	W2	CMU	White	None	0	0	Negative
1	1	Hallway outside Visual Communication Classroom T	W3	CMU	White	None	0	0	Negative
1	1	Hallway outside Visual Communication Classroom T	W4	CMU	White	None	0	0	Negative
1	1	Hallway outside Visual Communication Classroom T	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway outside Visual Communication Classroom T	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 140 to 141	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 140 to 141	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 140 to 141	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 140 to 141	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 140 to 141	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 140 to 141	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway leading to Loading Dock	W1	CMU	White	None	0	0	Negative
1	1	Hallway leading to Loading Dock	W2	CMU	White	None	0	0	Negative
1	1	Hallway leading to Loading Dock	W3	CMU	White	None	0	0	Negative
1	1	Hallway leading to Loading Dock	W4	CMU	White	None	0	0	Negative
1	1	Hallway leading to Loading Dock	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Hallway leading to Loading Dock	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 131 to 134	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 134	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 134	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 134	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 131 to 134	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 131 to 134	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 101 to 104	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 101 to 104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 101 to 104	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 110 to 111	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 110 to 111	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 110 to 111	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 110 to 111	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 110 to 111	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 110 to 111	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 105 to 109	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 105 to 109	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 105 to 109	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 105 to 109	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 105 to 109	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Hallway from Classrooms 105 to 109	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 117 to 122	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 117 to 122	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 117 to 122	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 117 to 122	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 117 to 122	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 117 to 122	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway entrance to Team room 177	W1	CMU	White	None	0	0	Negative
1	1	Hallway entrance to Team room 177	W2	CMU	White	None	0	0	Negative
1	1	Hallway entrance to Team room 177	W3	CMU	White	None	0	0	Negative
1	1	Hallway entrance to Team room 177	W4	CMU	White	None	0	0	Negative
1	1	Hallway entrance to Team room 177	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway entrance to Team room 177	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 123 to 125	W1	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 123 to 125	W2	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 123 to 125	W3	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 123 to 125	W4	CMU	White	None	0	0	Negative
1	1	Hallway from Classrooms 123 to 125	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway from Classrooms 123 to 125	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Hallway outside Classroom 125	W1	CMU	White	None	0	0	Negative
1	1	Hallway outside Classroom 125	W2	CMU	White	None	0	0	Negative
1	1	Hallway outside Classroom 125	W3	CMU	White	None	0	0	Negative
1	1	Hallway outside Classroom 125	W4	CMU	White	None	0	0	Negative
1	1	Hallway outside Classroom 125	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Hallway outside Classroom 125	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Boiler/Chiller Room M127A	W1	CMU	White	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W1	CMU	Tan	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W2	Concrete	White	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W2	Concrete	Tan	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W3	CMU	White	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W3	CMU	Tan	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W4	CMU	White	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	W4	CMU	Tan	None	0	0	Negative
1	1	Boiler/Chiller Room M127A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Boiler/Chiller Room M127A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 1	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 1	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 1	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 1	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 1	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 1	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 1	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 1	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 1	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 10	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 10	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 10	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Stairwell 10	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 10	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 10	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 10	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 10	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 10	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 10	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 11	Riser	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 11	Stringer	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 11	Tread	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 11	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Stairwell 11	W1	Concrete	White	Flaking	40	0	Negative
1	1	Stairwell 11	W2	Concrete	White	Flaking	80	0	Negative
1	1	Stairwell 11	W3	Concrete	White	Flaking	150	0	Negative
1	1	Stairwell 11	W4	Concrete	White	Flaking	100	0	Negative
1	1	Stairwell 11	Ceiling	Concrete	White	None	0	0	Negative
1	1	Stairwell 11	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 12	Riser	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 12	Stringer	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 12	Tread	Metal	Grey	Flaking	5	0	Negative
1	1	Stairwell 12	Door Frame	Metal	Gray	None	0	0	Negative
1	1	Stairwell 12	W1	Concrete	White	Flaking	40	0	Negative
1	1	Stairwell 12	W2	Concrete	White	Flaking	200	0	Negative
1	1	Stairwell 12	W3	Concrete	White	Flaking	150	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Stairwell 12	W4	Concrete	White	Flaking	150	0	Negative
1	1	Stairwell 12	Ceiling	Concrete	White	Flaking	50	0	Negative
1	1	Stairwell 12	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 15	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 15	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 15	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 15	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 15	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 15	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 15	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 15	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 15	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 15	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 2	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 2	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 2	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 2	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 2	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 2	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 2	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 2	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 2	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 3	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Stairwell 3	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 3	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 3	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 3	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 3	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 3	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 3	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 3	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 3	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 4	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 4	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 4	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 4	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 4	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 4	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 4	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 4	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 4	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 4	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 5	Riser	Metal	Gray	Chipping	5	0	Negative
1	1	Stairwell 5	Stringer	Metal	Grey	Chipping	5	0	Negative
1	1	Stairwell 5	Stringer	Metal	Grey	Chipping	5	0	Negative
1	1	Stairwell 5	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 5	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Stairwell 5	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 5	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 5	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 5	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 6	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 6	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 6	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 6	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 6	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 6	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 6	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 6	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 6	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 7	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 7	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 7	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 7	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 7	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 7	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 7	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 7	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 7	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 7	Handrail	Metal	Grey	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Stairwell 9	W1	CMU	White	None	0	0	Negative
1	1	Stairwell 9	W2	CMU	White	None	0	0	Negative
1	1	Stairwell 9	W3	CMU	White	None	0	0	Negative
1	1	Stairwell 9	W4	CMU	White	None	0	0	Negative
1	1	Stairwell 9	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairwell 9	Floor	Concrete	Grey	Chipping	2	0	Negative
1	1	Stairwell 9	Tread	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 9	Riser	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 9	Stringer	Metal	Grey	Chipping	2	0	Negative
1	1	Stairwell 9	Handrail	Metal	Grey	Chipping	2	0	Negative
1	1	Visual Communication Classroom T130	Door Frame 1	Metal	Black	Chipping	1	0	Negative
1	1	Visual Communication Classroom T130	Door Frame 2	Metal	Black	Chipping	1	0	Negative
1	1	Visual Communication Classroom T130	Column 1	Concrete	Blue	None	0	0	Negative
1	1	Visual Communication Classroom T130	Column 2	Concrete	Blue	None	0	0	Negative
1	1	Visual Communication Classroom T130	W1	CMU	White	None	0	0	Negative
1	1	Visual Communication Classroom T130	W2	CMU	White	None	0	0	Negative
1	1	Visual Communication Classroom T130	W3	CMU	White	None	0	0	Negative
1	1	Visual Communication Classroom T130	W4	CMU	White	None	0	0	Negative
1	1	Visual Communication Classroom T130	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Visual Communication Classroom T130	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Left Storage room in Visual Communication Classroom	Door Frame	Metal	Black	None	0	0	Negative
1	1	Left Storage room in Visual Communication Classroom	W1	CMU	Blue	None	0	0	Negative
1	1	Left Storage room in Visual Communication Classroom	W2	CMU	Blue	None	0	0	Negative
1	1	Left Storage room in Visual Communication Classroom	W3	CMU	Blue	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Left Storage room in Visual Communication Classroom	W4	CMU	White	None	0	0	Negative
1	1	Left Storage room in Visual Communication Classroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Left Storage room in Visual Communication Classroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Right Storage room in Visual Communication Classroom	Door Frame	Metal	Black	None	0	0	Negative
1	1	Right Storage room in Visual Communication Classroom	W1	CMU	White	None	0	0	Negative
1	1	Right Storage room in Visual Communication Classroom	W2	CMU	Blue	None	0	0	Negative
1	1	Right Storage room in Visual Communication Classroom	W3	CMU	White	None	0	0	Negative
1	1	Right Storage room in Visual Communication Classroom	W4	CMU	White	None	0	0	Negative
1	1	Right Storage room in Visual Communication Classroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Right Storage room in Visual Communication Classroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room T134B	W1	CMU	White	None	0	0	Negative
1	1	Storage Room T134B	W2	CMU	White	None	0	0	Negative
1	1	Storage Room T134B	W3	CMU	White	None	0	0	Negative
1	1	Storage Room T134B	W4	CMU	White	None	0	0	Negative
1	1	Storage Room T134B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Room T134B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	Door frame	Metal	Gray	None	0	0	Negative
1	1	Stock Room T142	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Stock Room T142	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	1	Electrical Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	Electrical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Learning Center 200	Door Frame 1	Metal	Purple	Chipping	1	0	Negative
1	2	Learning Center 200	Door Frame 2	Metal	Purple	None	0	0	Negative
1	2	Learning Center 200	Door Frame 3	Metal	Purple	None	0	0	Negative
1	2	Learning Center 200	Column 1	CMU	Purple	None	0	0	Negative
1	2	Learning Center 200	Column 2	Concrete	Purple	None	0	0	Negative
1	2	Learning Center 200	W1	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 200	W2	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 200	W3	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 200	W4	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 200	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Learning Center 200	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Learning Center 200A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Storage Closet 200A	W1	CMU	White	None	0	0	Negative
1	2	Storage Closet 200A	W2	CMU	White	None	0	0	Negative
1	2	Storage Closet 200A	W3	CMU	White	None	0	0	Negative
1	2	Storage Closet 200A	W4	CMU	White	None	0	0	Negative
1	2	Storage Closet 200A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 200A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200B	Door Frame	Metal	Purple	Chipping	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 200B	W1	CMU	White	None	0	0	Negative
1	2	Office 200B	W2	CMU	White	None	0	0	Negative
1	2	Office 200B	W3	CMU	White	None	0	0	Negative
1	2	Office 200B	W4	CMU	White	None	0	0	Negative
1	2	Office 200B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200C	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Office 200C	W1	CMU	White	None	0	0	Negative
1	2	Office 200C	W2	CMU	White	None	0	0	Negative
1	2	Office 200C	W3	CMU	White	None	0	0	Negative
1	2	Office 200C	W4	CMU	White	None	0	0	Negative
1	2	Office 200C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200D	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Office 200D	W1	CMU	White	None	0	0	Negative
1	2	Office 200D	W2	CMU	White	None	0	0	Negative
1	2	Office 200D	W3	CMU	White	None	0	0	Negative
1	2	Office 200D	W4	CMU	White	None	0	0	Negative
1	2	Office 200D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200E	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Office 200E	W1	CMU	White	None	0	0	Negative
1	2	Office 200E	W2	CMU	White	None	0	0	Negative
1	2	Office 200E	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 200E	W4	CMU	White	None	0	0	Negative
1	2	Office 200E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200F	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Office 200F	W1	CMU	White	None	0	0	Negative
1	2	Office 200F	W2	CMU	White	None	0	0	Negative
1	2	Office 200F	W3	CMU	White	None	0	0	Negative
1	2	Office 200F	W4	CMU	White	None	0	0	Negative
1	2	Office 200F	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200F	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200G	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Office 200G	W1	CMU	White	None	0	0	Negative
1	2	Office 200G	W2	CMU	White	None	0	0	Negative
1	2	Office 200G	W3	CMU	White	None	0	0	Negative
1	2	Office 200G	W4	CMU	White	None	0	0	Negative
1	2	Office 200G	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 200G	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 200H	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Custodial Closet 200H	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 200H	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 200H	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 200H	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 200H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 200I	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
2	2	Storage Closet 200I	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Storage Closet 200I	W1	CMU	White	None	0	0	Negative
1	2	Storage Closet 200I	W2	CMU	White	None	0	0	Negative
1	2	Storage Closet 200I	W3	CMU	White	None	0	0	Negative
1	2	Storage Closet 200I	W4	CMU	White	None	0	0	Negative
1	2	Storage Closet 200I	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 200I	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200J	Door Frame 1	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 200J	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 200J	W1	CMU	Blue	None	0	0	Negative
1	2	Classroom 200J	W2	CMU	Blue	None	0	0	Negative
1	2	Classroom 200J	W3	CMU	Blue	None	0	0	Negative
1	2	Classroom 200J	W4	Sheetrock	Blue	None	0	0	Negative
1	2	Classroom 200J	Column	Concrete	Blue	None	0	0	Negative
1	2	Classroom 200J	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200J	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200J	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200K	W1	CMU	White	None	0	0	Negative
1	2	Classroom 200K	W2	CMU	White	None	0	0	Negative
1	2	Classroom 200K	W3	CMU	White	None	0	0	Negative
1	2	Classroom 200K	W4	CMU	White	None	0	0	Negative
1	2	Classroom 200K	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 200K	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 201	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 201	W2	CMU	White	None	0	0	Negative
1	2	Classroom 201	W3	CMU	White	None	0	0	Negative
1	2	Classroom 201	W4	CMU	White	None	0	0	Negative
1	2	Classroom 201	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 201	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room next to stairwell 8	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 202	W1	CMU	White	None	0	0	Negative
1	2	Classroom 202	W2	CMU	White	None	0	0	Negative
1	2	Classroom 202	W3	CMU	White	None	0	0	Negative
1	2	Classroom 202	W4	CMU	White	None	0	0	Negative
1	2	Classroom 202	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 202	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office 203	W1	CMU	White	None	0	0	Negative
1	2	Teacher's Office 203	W2	CMU	White	None	0	0	Negative
1	2	Teacher's Office 203	W3	CMU	White	None	0	0	Negative
1	2	Teacher's Office 203	W4	CMU	White	None	0	0	Negative
1	2	Teacher's Office 203	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office 203	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 204	Door Frame	Metal	Gray	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 204	W1	CMU	White	None	0	0	Negative
1	2	Classroom 204	W2	CMU	White	None	0	0	Negative
1	2	Classroom 204	W3	CMU	White	Chipping	20	0	Negative
1	2	Classroom 204	W4	CMU	White	Chipping	10	0	Negative
1	2	Classroom 204	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 204	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 205	W1	CMU	White	None	0	0	Negative
1	2	Classroom 205	W2	CMU	White	None	0	0	Negative
1	2	Classroom 205	W3	CMU	White	None	0	0	Negative
1	2	Classroom 205	W4	CMU	White	None	0	0	Negative
1	2	Classroom 205	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 205	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 206	W1	CMU	Purple	None	0	0	Negative
1	2	Classroom 206	W2	CMU	Purple	None	0	0	Negative
1	2	Classroom 206	W3	CMU	Purple	None	0	0	Negative
1	2	Classroom 206	W4	CMU	Purple	None	0	0	Negative
1	2	Classroom 206	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 206	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 207	W1	CMU	White	None	0	0	Negative
1	2	Classroom 207	W2	CMU	White	None	0	0	Negative
1	2	Classroom 207	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 207	W4	CMU	White	None	0	0	Negative
1	2	Classroom 207	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 207	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 208	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 208	W1	CMU	White	None	0	0	Negative
1	2	Classroom 208	W2	CMU	Blue	None	0	0	Negative
1	2	Classroom 208	W3	CMU	Yellow	None	0	0	Negative
1	2	Classroom 208	W4	CMU	White	None	0	0	Negative
1	2	Classroom 208	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 208	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 209	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 209	W1	CMU	Gray	None	0	0	Negative
1	2	Classroom 209	W2	CMU	Gray	None	0	0	Negative
1	2	Classroom 209	W3	CMU	Gray	None	0	0	Negative
1	2	Classroom 209	W4	CMU	Gray	None	0	0	Negative
1	2	Classroom 209	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 209	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 210	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 210	W1	CMU	White	None	0	0	Negative
1	2	Classroom 210	W2	CMU	White	None	0	0	Negative
1	2	Classroom 210	W3	CMU	White	None	0	0	Negative
1	2	Classroom 210	W4	CMU	White	None	0	0	Negative
1	2	Classroom 210	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 210	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 211	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 211	W1	CMU	White	None	0	0	Negative
1	2	Classroom 211	W2	CMU	White	None	0	0	Negative
1	2	Classroom 211	W3	CMU	White	None	0	0	Negative
1	2	Classroom 211	W4	CMU	White	None	0	0	Negative
1	2	Classroom 211	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 211	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212	W1	CMU	White	None	0	0	Negative
1	2	Computer Lab 212	W2	CMU	White	None	0	0	Negative
1	2	Computer Lab 212	W3	CMU	White	None	0	0	Negative
1	2	Computer Lab 212	W4	CMU	White	None	0	0	Negative
1	2	Computer Lab 212	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212B	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Computer Lab 212B	W1	CMU	White	None	0	0	Negative
1	2	Computer Lab 212B	W2	CMU	White	None	0	0	Negative
1	2	Computer Lab 212B	W3	CMU	White	None	0	0	Negative
1	2	Computer Lab 212B	W4	CMU	White	None	0	0	Negative
1	2	Computer Lab 212B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212C	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Computer Lab 212C	W1	CMU	White	None	0	0	Negative
1	2	Computer Lab 212C	W2	CMU	White	None	0	0	Negative
1	2	Computer Lab 212C	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Computer Lab 212C	W4	CMU	White	None	0	0	Negative
1	2	Computer Lab 212C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Computer Lab 212C	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Mechanical Room in 212 Foyer	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage/IT MDF Room 213	W1	CMU	White	None	0	0	Negative
1	2	Storage/IT MDF Room 213	W2	CMU	White	None	0	0	Negative
1	2	Storage/IT MDF Room 213	W3	CMU	White	None	0	0	Negative
1	2	Storage/IT MDF Room 213	W4	CMU	White	None	0	0	Negative
1	2	Storage/IT MDF Room 213	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage/IT MDF Room 213	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 213A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 213B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 213B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 213B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Girl's Restroom 213B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 213B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 213B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Girl's Restroom 213B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Cafeteria 214	Door Frame 1	Metal	Purple	Chipping	1	0	Negative
1	2	Cafeteria 214	Door Frame 2	Metal	Purple	Chipping	2	0	Negative
1	2	Cafeteria 214	W1	CMU	Yellow	None	0	0	Negative
1	2	Cafeteria 214	W2	CMU	Yellow	None	0	0	Negative
1	2	Cafeteria 214	W3	CMU	Yellow	None	0	0	Negative
1	2	Cafeteria 214	W4	CMU	Yellow	None	0	0	Negative
1	2	Cafeteria 214	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Cafeteria 214	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase off Cafeteria 214	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	Door Frame	Metal	Gray	Chipping	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Pantry 214A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Pantry 214A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	214B Storage	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	214B Storage	W1	CMU	White	None	0	0	Negative
1	2	214B Storage	W2	CMU	White	None	0	0	Negative
1	2	214B Storage	W3	CMU	White	None	0	0	Negative
1	2	214B Storage	W4	CMU	White	None	0	0	Negative
1	2	214B Storage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	214B Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 214C	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 214C	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 214C	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 214C	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 214C	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Girl's Restroom 214C	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 214D	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 214D	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 214D	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 214D	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom 214D	Ceiling	Sheetrock	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Boy's Restroom 214D	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 215	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 215	W1	CMU	White	None	0	0	Negative
1	2	Classroom 215	W2	CMU	White	None	0	0	Negative
1	2	Classroom 215	W3	CMU	White	None	0	0	Negative
1	2	Classroom 215	W4	CMU	White	None	0	0	Negative
1	2	Classroom 215	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 215	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 216	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 216	W1	CMU	White	None	0	0	Negative
1	2	Classroom 216	W2	CMU	White	None	0	0	Negative
1	2	Classroom 216	W3	CMU	White	None	0	0	Negative
1	2	Classroom 216	W4	CMU	White	None	0	0	Negative
1	2	Classroom 216	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 216	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 217	W1	CMU	White	None	0	0	Negative
1	2	Classroom 217	W2	CMU	White	None	0	0	Negative
1	2	Classroom 217	W3	CMU	White	None	0	0	Negative
1	2	Classroom 217	W4	CMU	White	None	0	0	Negative
1	2	Classroom 217	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 217	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 218	W1	CMU	White	None	0	0	Negative
1	2	Classroom 218	W2	CMU	White	None	0	0	Negative
1	2	Classroom 218	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 218	W4	CMU	White	None	0	0	Negative
1	2	Classroom 218	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 218	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Roster Office 219	Door Frame 1	Metal	Gray	Chipping	2	0	Negative
1	2	Roster Office 219	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Roster Office 219	W1	CMU	White	None	0	0	Negative
1	2	Roster Office 219	W2	CMU	White	None	0	0	Negative
1	2	Roster Office 219	W3	CMU	White	None	0	0	Negative
1	2	Roster Office 219	W4	CMU	White	None	0	0	Negative
1	2	Roster Office 219	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Roster Office 219	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 220	W1	CMU	White	None	0	0	Negative
1	2	Classroom 220	W2	CMU	White	None	0	0	Negative
1	2	Classroom 220	W3	CMU	White	None	0	0	Negative
1	2	Classroom 220	W4	CMU	White	None	0	0	Negative
1	2	Classroom 220	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 220	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 221	Door Frame	Metal	Purple	Chipping	2	0	Negative
1	2	Classroom 221	W1	CMU	White	None	0	0	Negative
1	2	Classroom 221	W2	CMU	White	None	0	0	Negative
1	2	Classroom 221	W3	CMU	White	None	0	0	Negative
1	2	Classroom 221	W4	CMU	White	None	0	0	Negative
1	2	Classroom 221	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 221	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 222	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	2	Classroom 222	W1	CMU	White	None	0	0	Negative
1	2	Classroom 222	W2	CMU	White	None	0	0	Negative
1	2	Classroom 222	W3	CMU	White	None	0	0	Negative
1	2	Classroom 222	W4	CMU	White	None	0	0	Negative
1	2	Classroom 222	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 222	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223	W1	CMU	White	None	0	0	Negative
1	2	Classroom 223	W2	CMU	White	None	0	0	Negative
1	2	Classroom 223	W3	CMU	White	None	0	0	Negative
1	2	Classroom 223	W4	CMU	White	None	0	0	Negative
1	2	Classroom 223	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	W1	CMU	White	None	0	0	Negative
1	2	Classroom 224	W2	CMU	White	None	0	0	Negative
1	2	Classroom 224	W3	CMU	White	None	0	0	Negative
1	2	Classroom 224	W4	CMU	White	None	0	0	Negative
1	2	Classroom 224	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 225	Door Frame	Metal	Gray	Chipping	3	0	Negative
1	2	Classroom 225	W1	CMU	White	None	0	0	Negative
1	2	Classroom 225	W2	CMU	White	None	0	0	Negative
1	2	Classroom 225	W3	CMU	White	None	0	0	Negative
1	2	Classroom 225	W4	CMU	White	Flaking	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 225	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 225	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Learning Center 226	Door Frame 1	Metal	Yellow	Chipping	1	0	Negative
1	2	Learning Center 226	Door Frame 2	Metal	Yellow	Chipping	2	0	Negative
1	2	Learning Center 226	Door Frame 3	Metal	Yellow	Chipping	1	0	Negative
1	2	Learning Center 226	W1	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 226	W2	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 226	W3	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 226	W4	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 226	Column 1	Concrete	Yellow	None	0	0	Negative
1	2	Learning Center 226	Column 2	CMU	Yellow	None	0	0	Negative
1	2	Learning Center 226	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Learning Center 226	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 226A	W1	CMU	White	None	0	0	Negative
1	2	Storage Closet 226A	W2	CMU	White	None	0	0	Negative
1	2	Storage Closet 226A	W3	CMU	White	None	0	0	Negative
1	2	Storage Closet 226A	W4	CMU	White	None	0	0	Negative
1	2	Storage Closet 226A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 226A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226B	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Office 226B	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Office 226B	Door Frame 3	Metal	Gray	Chipping	2	0	Negative
1	2	Office 226B	W1	CMU	Yellow	Chipping	2	0	Negative
1	2	Office 226B	W2	CMU	Yellow	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 226B	W3	CMU	Purple	None	0	0	Negative
1	2	Office 226B	W4	CMU	Yellow	None	0	0	Negative
1	2	Office 226B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226B	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226C	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Office 226C	W1	CMU	White	None	0	0	Negative
1	2	Office 226C	W2	CMU	White	None	0	0	Negative
1	2	Office 226C	W3	CMU	White	None	0	0	Negative
1	2	Office 226C	W4	CMU	White	None	0	0	Negative
1	2	Office 226C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226C	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226D	W1	CMU	White	None	0	0	Negative
1	2	Office 226D	W2	CMU	White	None	0	0	Negative
1	2	Office 226D	W3	CMU	White	None	0	0	Negative
1	2	Office 226D	W4	CMU	White	None	0	0	Negative
1	2	Office 226D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226E	W1	CMU	White	None	0	0	Negative
1	2	Office 226E	W2	CMU	White	None	0	0	Negative
1	2	Office 226E	W3	CMU	White	None	0	0	Negative
1	2	Office 226E	W4	CMU	White	None	0	0	Negative
1	2	Office 226E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226F	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 226F	W2	CMU	White	None	0	0	Negative
1	2	Office 226F	W3	CMU	White	None	0	0	Negative
1	2	Office 226F	W4	CMU	White	None	0	0	Negative
1	2	Office 226F	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226F	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226G	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Office 226G	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Office 226G	Duct	Metal	White	None	0	0	Negative
1	2	Office 226G	W1	CMU	White	None	0	0	Negative
1	2	Office 226G	W2	CMU	White	None	0	0	Negative
1	2	Office 226G	W3	CMU	White	None	0	0	Negative
1	2	Office 226G	W4	CMU	White	None	0	0	Negative
1	2	Office 226G	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 226G	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Custodial Closet 226H	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet 226H	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 226I	W1	CMU	White	None	0	0	Negative
1	2	Storage Closet 226I	W2	CMU	White	None	0	0	Negative
1	2	Storage Closet 226I	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Storage Closet 226I	W4	CMU	White	None	0	0	Negative
1	2	Storage Closet 226I	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet 226I	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Deans Office 226J	W1	CMU	White	None	0	0	Negative
1	2	Deans Office 226J	W2	CMU	White	None	0	0	Negative
1	2	Deans Office 226J	W3	CMU	White	None	0	0	Negative
1	2	Deans Office 226J	W4	CMU	White	None	0	0	Negative
1	2	Deans Office 226J	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Deans Office 226J	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	School Police Office 226K	Door Frame 1	Metal	Gray	None	0	0	Negative
1	2	School Police Office 226K	Door Frame 2	Metal	Gray	None	0	0	Negative
1	2	School Police Office 226K	Column	Concrete	White	None	0	0	Negative
1	2	School Police Office 226K	W1	CMU	White	None	0	0	Negative
1	2	School Police Office 226K	W2	CMU	White	None	0	0	Negative
1	2	School Police Office 226K	W3	CMU	White	None	0	0	Negative
1	2	School Police Office 226K	W4	CMU	White	None	0	0	Negative
1	2	School Police Office 226K	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	School Police Office 226K	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC (Library) 227	W1	CMU	White	None	0	0	Negative
1	2	IMC (Library) 227	W2	CMU	White	None	0	0	Negative
1	2	IMC (Library) 227	W3	CMU	White	None	0	0	Negative
1	2	IMC (Library) 227	W4	CMU	White	None	0	0	Negative
1	2	IMC (Library) 227	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC (Library) 227	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	IMC (Library) 227	Column	Concrete	Yellow	None	0	0	Negative
1	2	IMC (Library) 227	Column	Concrete	Yellow	None	0	0	Negative
1	2	IMC (Library) 227	Column	Concrete	Yellow	None	0	0	Negative
1	2	IMC (Library) 227	Column	Concrete	Purple	None	0	0	Negative
1	2	IMC (Library) 227	Column	Concrete	Purple	None	0	0	Negative
1	2	IMC (Library) 227	Column	Concrete	Purple	None	0	0	Negative
1	2	Work Room 227A	W1	CMU	White	None	0	0	Negative
1	2	Work Room 227A	W2	CMU	White	None	0	0	Negative
1	2	Work Room 227A	W3	CMU	White	None	0	0	Negative
1	2	Work Room 227A	W4	CMU	White	None	0	0	Negative
1	2	Work Room 227A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Work Room 227A	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Work Room 227B	W1	CMU	White	None	0	0	Negative
1	2	Work Room 227B	W2	CMU	White	None	0	0	Negative
1	2	Work Room 227B	W3	CMU	White	None	0	0	Negative
1	2	Work Room 227B	W4	CMU	White	None	0	0	Negative
1	2	Work Room 227B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Work Room 227B	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC (Library) Receiving Room	W1	CMU	White	None	0	0	Negative
1	2	IMC (Library) Receiving Room	W2	CMU	White	None	0	0	Negative
1	2	IMC (Library) Receiving Room	W3	CMU	White	None	0	0	Negative
1	2	IMC (Library) Receiving Room	W4	CMU	White	None	0	0	Negative
1	2	IMC (Library) Receiving Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	IMC (Library) Receiving Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Librarian's Office 227D	W1	CMU	White	None	0	0	Negative
1	2	Librarian's Office 227D	W2	CMU	White	None	0	0	Negative
1	2	Librarian's Office 227D	W3	CMU	White	None	0	0	Negative
1	2	Librarian's Office 227D	W4	CMU	White	None	0	0	Negative
1	2	Librarian's Office 227D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Librarian's Office 227D	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Workroom 227E	W1	CMU	White	None	0	0	Negative
1	2	Workroom 227E	W2	CMU	White	None	0	0	Negative
1	2	Workroom 227E	W3	CMU	White	None	0	0	Negative
1	2	Workroom 227E	W4	CMU	White	None	0	0	Negative
1	2	Workroom 227E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Workroom 227E	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Professional Collection Room 227F	W1	CMU	White	None	0	0	Negative
1	2	Professional Collection Room 227F	W2	CMU	White	None	0	0	Negative
1	2	Professional Collection Room 227F	W3	CMU	White	None	0	0	Negative
1	2	Professional Collection Room 227F	W4	CMU	White	None	0	0	Negative
1	2	Professional Collection Room 227F	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Professional Collection Room 227F	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Magazine Storage Room 227H	W1	CMU	White	None	0	0	Negative
1	2	Magazine Storage Room 227H	W2	CMU	White	None	0	0	Negative
1	2	Magazine Storage Room 227H	W3	CMU	White	None	0	0	Negative
1	2	Magazine Storage Room 227H	W4	CMU	White	None	0	0	Negative
1	2	Magazine Storage Room 227H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Magazine Storage Room 227H	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	AV Equipment Storage Room 227I	W1	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227I	W2	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227I	W3	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227I	W4	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227I	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	AV Equipment Storage Room 227I	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	AV Equipment Storage Room 227J	W1	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227J	W2	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227J	W3	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227J	W4	CMU	White	None	0	0	Negative
1	2	AV Equipment Storage Room 227J	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	AV Equipment Storage Room 227J	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 227K	W1	CMU	White	None	0	0	Negative
1	2	Conference Room 227K	W2	CMU	White	None	0	0	Negative
1	2	Conference Room 227K	W3	CMU	White	None	0	0	Negative
1	2	Conference Room 227K	W4	CMU	White	None	0	0	Negative
1	2	Conference Room 227K	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 227K	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 227L	W1	CMU	White	None	0	0	Negative
1	2	Conference Room 227L	W2	CMU	White	None	0	0	Negative
1	2	Conference Room 227L	W3	CMU	White	None	0	0	Negative
1	2	Conference Room 227L	W4	CMU	White	None	0	0	Negative
1	2	Conference Room 227L	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 227L	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Conference Room 227M	W1	CMU	White	None	0	0	Negative
1	2	Conference Room 227M	W2	CMU	White	None	0	0	Negative
1	2	Conference Room 227M	W3	CMU	White	None	0	0	Negative
1	2	Conference Room 227M	W4	CMU	White	None	0	0	Negative
1	2	Conference Room 227M	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 227M	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Coop. Coordinator Office 228	W1	CMU	White	None	0	0	Negative
1	2	Coop. Coordinator Office 228	W2	CMU	White	None	0	0	Negative
1	2	Coop. Coordinator Office 228	W3	CMU	White	None	0	0	Negative
1	2	Coop. Coordinator Office 228	W4	CMU	White	None	0	0	Negative
1	2	Coop. Coordinator Office 228	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Coop. Coordinator Office 228	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Faculty 228B	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Men's Faculty 228B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Faculty 228B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Faculty 228B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Faculty 228B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Men's Faculty 228B	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Men's Faculty 228B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 229	W1	CMU	White	None	0	0	Negative
1	2	Classroom 229	W2	CMU	White	None	0	0	Negative
1	2	Classroom 229	W3	CMU	White	None	0	0	Negative
1	2	Classroom 229	W4	CMU	White	None	0	0	Negative
1	2	Classroom 229	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 229	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 229 Closet	W1	CMU	White	None	0	0	Negative
1	2	Classroom 229 Closet	W2	CMU	White	None	0	0	Negative
1	2	Classroom 229 Closet	W3	CMU	White	None	0	0	Negative
1	2	Classroom 229 Closet	W4	CMU	White	None	0	0	Negative
1	2	Classroom 229 Closet	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 229 Closet	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 230	Door Frame 1	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 230	Door Frame 2	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 230	W1	CMU	Blue	None	0	0	Negative
1	2	Classroom 230	W2	CMU	Blue	None	0	0	Negative
1	2	Classroom 230	W3	CMU	Blue	None	0	0	Negative
1	2	Classroom 230	W4	CMU	Blue	None	0	0	Negative
1	2	Classroom 230	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 230	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 230A	W1	CMU	White	None	0	0	Negative
1	2	Storage Room 230A	W2	CMU	White	None	0	0	Negative
1	2	Storage Room 230A	W3	CMU	White	None	0	0	Negative
1	2	Storage Room 230A	W4	CMU	White	None	0	0	Negative
1	2	Storage Room 230A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 230A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 231	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 231	W1	CMU	White	Flaking	2	0	Negative
1	2	Classroom 231	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 231	W3	CMU	White	None	0	0	Negative
1	2	Classroom 231	W4	CMU	White	None	0	0	Negative
1	2	Classroom 231	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 231	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 232	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 232	W1	CMU	White	None	0	0	Negative
1	2	Classroom 232	W2	CMU	White	None	0	0	Negative
1	2	Classroom 232	W3	CMU	White	None	0	0	Negative
1	2	Classroom 232	W4	CMU	White	None	0	0	Negative
1	2	Classroom 232	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 232	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 233	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Classroom 233	W1	CMU	White	None	0	0	Negative
1	2	Classroom 233	W2	CMU	White	None	0	0	Negative
1	2	Classroom 233	W3	CMU	White	None	0	0	Negative
1	2	Classroom 233	W4	CMU	Yellow	None	0	0	Negative
1	2	Classroom 233	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 233	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 233A	W1	CMU	White	None	0	0	Negative
1	2	Storage Room 233A	W2	CMU	White	None	0	0	Negative
1	2	Storage Room 233A	W3	CMU	White	None	0	0	Negative
1	2	Storage Room 233A	W4	CMU	White	None	0	0	Negative
1	2	Storage Room 233A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 233A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 234A	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 234A	W1	CMU	White	None	0	0	Negative
1	2	Classroom 234A	W2	CMU	White	None	0	0	Negative
1	2	Classroom 234A	W3	CMU	White	None	0	0	Negative
1	2	Classroom 234A	W4	CMU	White	None	0	0	Negative
1	2	Classroom 234A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 234A	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 234B	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 234B	W1	CMU	White	None	0	0	Negative
1	2	Classroom 234B	W2	CMU	White	None	0	0	Negative
1	2	Classroom 234B	W3	CMU	White	None	0	0	Negative
1	2	Classroom 234B	W4	CMU	White	None	0	0	Negative
1	2	Classroom 234B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 234B	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 235	Door Frame 1	Metal	Gray	Chipping	2	0	Negative
1	2	Office 235	Door Frame 2	Metal	Gray	Chipping	2	0	Negative
1	2	Office 235	W1	CMU	White	None	0	0	Negative
1	2	Office 235	W2	CMU	White	None	0	0	Negative
1	2	Office 235	W3	CMU	White	None	0	0	Negative
1	2	Office 235	W4	CMU	White	None	0	0	Negative
1	2	Office 235	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 235	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Department Head Office to Business Education 236	W1	CMU	White	None	0	0	Negative
1	2	Department Head Office to Business Education 236	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Department Head Office to Business Education 236	W3	CMU	White	None	0	0	Negative
1	2	Department Head Office to Business Education 236	W4	CMU	White	None	0	0	Negative
1	2	Department Head Office to Business Education 236	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Department Head Office to Business Education 236	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Home Economics Office 237	W1	CMU	White	None	0	0	Negative
1	2	Home Economics Office 237	W2	CMU	White	None	0	0	Negative
1	2	Home Economics Office 237	W3	CMU	White	None	0	0	Negative
1	2	Home Economics Office 237	W4	CMU	White	None	0	0	Negative
1	2	Home Economics Office 237	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Home Economics Office 237	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet	W1	CMU	White	None	0	0	Negative
1	2	Storage Closet	W2	CMU	White	None	0	0	Negative
1	2	Storage Closet	W3	CMU	White	None	0	0	Negative
1	2	Storage Closet	W4	CMU	White	None	0	0	Negative
1	2	Storage Closet	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Closet	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 238	W1	CMU	White	None	0	0	Negative
1	2	Classroom 238	W2	CMU	White	None	0	0	Negative
1	2	Classroom 238	W3	CMU	White	None	0	0	Negative
1	2	Classroom 238	W4	CMU	White	None	0	0	Negative
1	2	Classroom 238	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 238	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 238A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 238A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Girl's Restroom 238A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 238A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom 238A	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Girl's Restroom 238A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	Ceiling	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Women's Restroom next to Girl's Restroom 238A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 239	W1	CMU	White	None	0	0	Negative
1	2	Classroom 239	W2	CMU	White	None	0	0	Negative
1	2	Classroom 239	W3	CMU	White	None	0	0	Negative
1	2	Classroom 239	W4	CMU	White	None	0	0	Negative
1	2	Classroom 239	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 239	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage in 239A	W1	CMU	White	None	0	0	Negative
1	2	Storage in 239A	W2	CMU	White	None	0	0	Negative
1	2	Storage in 239A	W3	CMU	White	None	0	0	Negative
1	2	Storage in 239A	W4	CMU	White	None	0	0	Negative
1	2	Storage in 239A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage in 239A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 240	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 240	Door Frame	Metal	Gray	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Classroom 240	W1	CMU	White	Flaking	10	0	Negative
1	2	Classroom 240	W2	CMU	White	None	0	0	Negative
1	2	Classroom 240	W3	CMU	White	None	0	0	Negative
1	2	Classroom 240	W4	CMU	White	None	0	0	Negative
1	2	Classroom 240	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 240	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 241	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 241	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Classroom 241	W1	CMU	White	Flaking	5	0	Negative
1	2	Classroom 241	W2	CMU	White	None	0	0	Negative
1	2	Classroom 241	W3	CMU	White	None	0	0	Negative
1	2	Classroom 241	W4	CMU	White	None	0	0	Negative
1	2	Classroom 241	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 241	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage closet in 241	W1	CMU	White	None	0	0	Negative
1	2	Storage closet in 241	W2	CMU	White	None	0	0	Negative
1	2	Storage closet in 241	W3	CMU	White	None	0	0	Negative
1	2	Storage closet in 241	W4	CMU	White	None	0	0	Negative
1	2	Storage closet in 241	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage closet in 241	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Maintenance Shop 247	W1	CMU	White	None	0	0	Negative
1	2	Maintenance Shop 247	W2	CMU	White	None	0	0	Negative
1	2	Maintenance Shop 247	W3	CMU	White	None	0	0	Negative
1	2	Maintenance Shop 247	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Maintenance Shop 247	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Maintenance Shop 247	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Large Mail Room 250	Door Frame 1	Metal	Gray	None	0	0	Negative
1	2	Main Office Large Mail Room 250	Door Frame 2	Metal	Gray	None	0	0	Negative
1	2	Main Office Large Mail Room 250	W1	CMU	White	None	0	0	Negative
1	2	Main Office Large Mail Room 250	W2	CMU	White	None	0	0	Negative
1	2	Main Office Large Mail Room 250	W3	CMU	White	None	0	0	Negative
1	2	Main Office Large Mail Room 250	W4	CMU	White	None	0	0	Negative
1	2	Main Office Large Mail Room 250	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Large Mail Room 250	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	Ceiling	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Restroom outside of Gymnasium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	Ceiling	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Restroom outside of Gymnasium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet between the Boy's and Girl's Restro	Door Frame	Metal	Gray	Chipping	2	0	Negative
1	2	Custodial Closet between the Boy's and Girl's Restro	Pipe	Metal	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Custodial Closet between the Boy's and Girl's Restro	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet between the Boy's and Girl's Restro	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet between the Boy's and Girl's Restro	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet between the Boy's and Girl's Restro	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Custodial Closet between the Boy's and Girl's Restro	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Custodial Closet between the Boy's and Girl's Restro	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Mail Room 251	W1	CMU	White	None	0	0	Negative
1	2	Mail Room 251	W2	CMU	White	None	0	0	Negative
1	2	Mail Room 251	W3	CMU	White	None	0	0	Negative
1	2	Mail Room 251	W4	CMU	White	None	0	0	Negative
1	2	Mail Room 251	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Mail Room 251	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251A	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Office 251A	W1	CMU	White	None	0	0	Negative
1	2	Office 251A	W2	CMU	White	None	0	0	Negative
1	2	Office 251A	W3	CMU	White	None	0	0	Negative
1	2	Office 251A	W4	CMU	White	None	0	0	Negative
1	2	Office 251A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251B	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Office 251B	W1	CMU	White	None	0	0	Negative
1	2	Office 251B	W2	CMU	White	None	0	0	Negative
1	2	Office 251B	W3	CMU	White	None	0	0	Negative
1	2	Office 251B	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 251B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251C	Door Frame	Metal	Black	None	0	0	Negative
1	2	Office 251C	W1	CMU	White	None	0	0	Negative
1	2	Office 251C	W2	CMU	White	None	0	0	Negative
1	2	Office 251C	W3	CMU	White	None	0	0	Negative
1	2	Office 251C	W4	CMU	White	None	0	0	Negative
1	2	Office 251C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 251C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office 252	Door frame 1	Metal	Brown	Chipping	1	0	Negative
1	2	Main Office 252	Door Frame 2	Metal	Brown	Chipping	1	0	Negative
1	2	Main Office 252	Door Frame 3	Metal	Brown	Chipping	1	0	Negative
1	2	Main Office 252	W1	Metal	Brown	None	0	0	Negative
1	2	Main Office 252	W2	Metal	Brown	None	0	0	Negative
1	2	Main Office 252	W3	Metal	Brown	None	0	0	Negative
1	2	Main Office 252	W4	Metal	Brown	None	0	0	Negative
1	2	Main Office 252	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office 252	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Storage Room 252C	Door frame	Metal	Gray	Chipping	1	0	Negative
1	2	Main Office Storage Room 252C	W1	CMU	White	None	0	0	Negative
1	2	Main Office Storage Room 252C	W2	CMU	White	None	0	0	Negative
1	2	Main Office Storage Room 252C	W3	CMU	White	None	0	0	Negative
1	2	Main Office Storage Room 252C	W4	CMU	White	None	0	0	Negative
1	2	Main Office Storage Room 252C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Main Office Storage Room 252C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Storage Room 253A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Main Office Storage Room 253A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Main Office Storage Room 253A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Main Office Storage Room 253A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Main Office Storage Room 253A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Main Office Storage Room 253A	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	Office 254	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Office 254	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Office 254	W1	CMU	White	None	0	0	Negative
1	2	Office 254	W2	CMU	White	None	0	0	Negative
1	2	Office 254	W3	CMU	White	None	0	0	Negative
1	2	Office 254	W4	CMU	White	None	0	0	Negative
1	2	Office 254	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254B	W1	Metal	White	None	0	0	Negative
1	2	Office 254B	W2	Metal	White	None	0	0	Negative
1	2	Office 254B	W3	CMU	White	None	0	0	Negative
1	2	Office 254B	W4	Metal	White	None	0	0	Negative
1	2	Office 254B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254C	W1	Metal	White	None	0	0	Negative
1	2	Office 254C	W2	Metal	White	None	0	0	Negative
1	2	Office 254C	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 254C	W4	CMU	White	None	0	0	Negative
1	2	Office 254C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office 254D	Door Frame 1	Metal	Black	Chipping	1	0	Negative
1	2	Principal's Office 254D	Door Frame 2	Metal	Black	Chipping	1	0	Negative
1	2	Principal's Office 254D	W1	CMU	Multi	None	0	0	Negative
1	2	Principal's Office 254D	W2	CMU	Multi	None	0	0	Negative
1	2	Principal's Office 254D	W3	CMU	Multi	None	0	0	Negative
1	2	Principal's Office 254D	W4	CMU	Multi	None	0	0	Negative
1	2	Principal's Office 254D	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office 254D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	Door frame	Metal	Black	Chipping	1	0	Negative
1	2	Principal's Office Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Principal's Office Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Principal's Office Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom across from Office 254	Door Frame	Metal	Tan	None	0	0	Negative
1	2	Restroom across from Office 254	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom across from Office 254	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom across from Office 254	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom across from Office 254	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom across from Office 254	Ceiling	Sheetrock	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Restroom across from Office 254	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 255	Door frame	Metal	Black	None	0	0	Negative
1	2	Conference Room 255	W1	CMU	Multi	None	0	0	Negative
1	2	Conference Room 255	W2	CMU	Multi	None	0	0	Negative
1	2	Conference Room 255	W3	CMU	Multi	None	0	0	Negative
1	2	Conference Room 255	W4	CMU	Multi	None	0	0	Negative
1	2	Conference Room 255	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Conference Room 255	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 256 next to Office 254	Door frame 1	Metal	Black	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	Door Frame 2	Metal	Black	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	W1	CMU	White	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	W2	CMU	White	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	W3	CMU	White	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	W4	CMU	White	None	0	0	Negative
1	2	Storage Room 256 next to Office 254	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 256 next to Office 254	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Dressing Room next to Auditorium Stage	W1	CMU	White	None	0	0	Negative
1	2	Boy's Dressing Room next to Auditorium Stage	W2	CMU	White	None	0	0	Negative
1	2	Boy's Dressing Room next to Auditorium Stage	W3	CMU	White	None	0	0	Negative
1	2	Boy's Dressing Room next to Auditorium Stage	W4	CMU	White	None	0	0	Negative
1	2	Boy's Dressing Room next to Auditorium Stage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Dressing Room next to Auditorium Stage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	W2	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Boy's Dressing Room next to Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	W1	CMU	White	None	0	0	Negative
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	W2	CMU	White	None	0	0	Negative
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	W3	CMU	White	None	0	0	Negative
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	W4	CMU	White	None	0	0	Negative
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room inside Boy's Dressing Room next to Auditorium	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Boy's Dressing Room next to Auditorium	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Boy's Dressing Room next to Auditorium	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Boy's Dressing Room next to Auditorium	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Boy's Dressing Room next to Auditorium	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Boy's Dressing Room next to Auditorium	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Restroom inside Boy's Dressing Room next to Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267A	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Music Practice Room 267A	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267A	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267A	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267A	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267B	Door Frame	Metal	Gray	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Music Practice Room 267B	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267B	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267B	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267B	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267C	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Music Practice Room 267C	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267C	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267C	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267C	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267D	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Music Practice Room 267D	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267D	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267D	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267D	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 267D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 267D	Radiator	Metal	White	None	0	0	Negative
1	2	Storage Room next to Music Classroom A267	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Storage Room next to Music Classroom A267	W1	CMU	White	None	0	0	Negative
1	2	Storage Room next to Music Classroom A267	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Storage Room next to Music Classroom A267	W3	CMU	White	None	0	0	Negative
1	2	Storage Room next to Music Classroom A267	W4	CMU	White	None	0	0	Negative
1	2	Storage Room next to Music Classroom A267	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room next to Music Classroom A267	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room next to Music Classroom A267	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom 268	Door Frame 1	Metal	Gray	None	0	0	Negative
1	2	Music Classroom 268	Door Frame 2	Metal	Gray	None	0	0	Negative
1	2	Music Classroom 268	W1	CMU	White	None	0	0	Negative
1	2	Music Classroom 268	W2	CMU	White	None	0	0	Negative
1	2	Music Classroom 268	W3	CMU	White	None	0	0	Negative
1	2	Music Classroom 268	W4	CMU	White	None	0	0	Negative
1	2	Music Classroom 268	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom 268	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 268A	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Music Practice Room 268A	W1	CMU	Gray	None	0	0	Negative
1	2	Music Practice Room 268A	W2	CMU	Gray	None	0	0	Negative
1	2	Music Practice Room 268A	W3	CMU	Gray	None	0	0	Negative
1	2	Music Practice Room 268A	W4	CMU	Gray	None	0	0	Negative
1	2	Music Practice Room 268A	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 268A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom 269	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Music Classroom 269	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Music Classroom 269	W1	CMU	White	None	0	0	Negative
1	2	Music Classroom 269	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Music Classroom 269	W3	CMU	White	None	0	0	Negative
1	2	Music Classroom 269	W4	CMU	White	None	0	0	Negative
1	2	Music Classroom 269	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom 269	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Music Practice Room 269A	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269A	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269A	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269A	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269A	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269B	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Music Practice Room 269B	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269B	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269B	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269B	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269B	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269C	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Music Practice Room 269C	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269C	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269C	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269C	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269C	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Music Practice Room 269C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269D	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Music Practice Room 269D	W1	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269D	W2	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269D	W3	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269D	W4	CMU	White	None	0	0	Negative
1	2	Music Practice Room 269D	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Practice Room 269D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Community Room 270	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Community Room 270	W1	CMU	White	None	0	0	Negative
1	2	Community Room 270	W2	CMU	White	None	0	0	Negative
1	2	Community Room 270	W3	CMU	White	None	0	0	Negative
1	2	Community Room 270	W4	CMU	White	None	0	0	Negative
1	2	Community Room 270	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Community Room 270	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 271 next to Health Classroom 270	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Storage Room 271 next to Health Classroom 270	W1	CMU	White	None	0	0	Negative
1	2	Storage Room 271 next to Health Classroom 270	W2	CMU	White	None	0	0	Negative
1	2	Storage Room 271 next to Health Classroom 270	W3	CMU	White	None	0	0	Negative
1	2	Storage Room 271 next to Health Classroom 270	W4	CMU	White	None	0	0	Negative
1	2	Storage Room 271 next to Health Classroom 270	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 271 next to Health Classroom 270	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 272 next to Weight Room 273A	W1	CMU	White	None	0	0	Negative
1	2	Office 272 next to Weight Room 273A	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Office 272 next to Weight Room 273A	W3	CMU	White	None	0	0	Negative
1	2	Office 272 next to Weight Room 273A	W4	CMU	White	None	0	0	Negative
1	2	Office 272 next to Weight Room 273A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 272 next to Weight Room 273A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 273 next to Weight Room 273A	W1	CMU	White	None	0	0	Negative
1	2	Storage Room 273 next to Weight Room 273A	W2	CMU	White	None	0	0	Negative
1	2	Storage Room 273 next to Weight Room 273A	W3	CMU	White	None	0	0	Negative
1	2	Storage Room 273 next to Weight Room 273A	W4	CMU	White	None	0	0	Negative
1	2	Storage Room 273 next to Weight Room 273A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room 273 next to Weight Room 273A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Weight Room 273A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Weight Room 273A	W1	CMU	White	None	0	0	Negative
1	2	Weight Room 273A	W2	CMU	White	None	0	0	Negative
1	2	Weight Room 273A	W3	CMU	White	None	0	0	Negative
1	2	Weight Room 273A	W4	CMU	White	None	0	0	Negative
1	2	Weight Room 273A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Weight Room 273A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office inside Weight Room 273A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Office inside Weight Room 273A	W1	CMU	White	None	0	0	Negative
1	2	Office inside Weight Room 273A	W2	CMU	White	None	0	0	Negative
1	2	Office inside Weight Room 273A	W3	CMU	White	None	0	0	Negative
1	2	Office inside Weight Room 273A	W4	CMU	White	None	0	0	Negative
1	2	Office inside Weight Room 273A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office inside Weight Room 273A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Boy's Gym Teacher Office 274	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Boy's Gym Teacher Office 274	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Boy's Gym Teacher Office 274	W1	CMU	White	None	0	0	Negative
1	2	Boy's Gym Teacher Office 274	W2	CMU	White	None	0	0	Negative
1	2	Boy's Gym Teacher Office 274	W3	CMU	White	None	0	0	Negative
1	2	Boy's Gym Teacher Office 274	W4	CMU	White	None	0	0	Negative
1	2	Boy's Gym Teacher Office 274	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office 274	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Boy's Gym Teacher Office Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Boy's Gym Teacher Office Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office 275	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	W1	CMU	White	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	W2	CMU	White	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	W3	CMU	White	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	W4	CMU	White	None	0	0	Negative
1	2	Girl's Gym Teacher Office 275	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office 275	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	Door Frame	Metal	Gray	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Gymnasium B Storage Room 275A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B Storage Room 275A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Girl's Gym Teacher Office Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Gym Teacher Office Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium A	Duct	Metal	White	None	0	0	Negative
1	2	Gymnasium A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium A	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium A	W1	CMU	White	None	0	0	Negative
1	2	Gymnasium A	W2	CMU	White	None	0	0	Negative
1	2	Gymnasium A	W3	CMU	White	None	0	0	Negative
1	2	Gymnasium A	Ceiling	Metal	White	None	0	0	Negative
1	2	Gymnasium A	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium B	Duct	Metal	White	None	0	0	Negative
1	2	Gymnasium B	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium B	Door Frame	Metal	Gray	Chipping	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Gymnasium B	W1	CMU	White	None	0	0	Negative
1	2	Gymnasium B	W3	CMU	White	None	0	0	Negative
1	2	Gymnasium B	Ceiling	Metal	White	None	0	0	Negative
1	2	Gymnasium B	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C	Duct	Metal	White	None	0	0	Negative
1	2	Gymnasium C	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium C	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium C	W1	CMU	White	None	0	0	Negative
1	2	Gymnasium C	W3	CMU	White	None	0	0	Negative
1	2	Gymnasium C	Ceiling	Metal	White	None	0	0	Negative
1	2	Gymnasium C	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium D	Duct	Metal	White	None	0	0	Negative
1	2	Gymnasium D	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium D	Door Frame	Metal	Gray	Chipping	1	0	Negative
1	2	Gymnasium D	W1	CMU	White	None	0	0	Negative
1	2	Gymnasium D	W3	CMU	White	None	0	0	Negative
1	2	Gymnasium D	W4	CMU	White	None	0	0	Negative
1	2	Gymnasium D	Ceiling	Metal	White	None	0	0	Negative
1	2	Gymnasium D	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium	Door Frame 3	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium	Door Frame 4	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium	W1	Metal	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Auditorium	W2	CMU	White	None	0	0	Negative
1	2	Auditorium	W3	CMU	White	None	0	0	Negative
1	2	Auditorium	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Equipment Storage Room 290B	W1	CMU	White	None	0	0	Negative
1	2	Equipment Storage Room 290B	W2	CMU	White	None	0	0	Negative
1	2	Equipment Storage Room 290B	W3	CMU	White	None	0	0	Negative
1	2	Equipment Storage Room 290B	W4	CMU	White	None	0	0	Negative
1	2	Equipment Storage Room 290B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Equipment Storage Room 290B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium Stage	Door Frame 1	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium Stage	Door Frame 2	Metal	Gray	Chipping	1	0	Negative
1	2	Auditorium Stage	W1	CMU	White	None	0	0	Negative
1	2	Auditorium Stage	W2	Wood	White	None	0	0	Negative
1	2	Auditorium Stage	W4	CMU	White	None	0	0	Negative
1	2	Auditorium Stage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	2	Auditorium Stage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Kitchen 252A	Door frame	Metal	Brown	Chipping	1	0	Negative
1	2	Main Office Kitchen 252A	W1	CMU	White	None	0	0	Negative
1	2	Main Office Kitchen 252A	W2	CMU	White	None	0	0	Negative
1	2	Main Office Kitchen 252A	W3	CMU	White	None	0	0	Negative
1	2	Main Office Kitchen 252A	W4	CMU	White	None	0	0	Negative
1	2	Main Office Kitchen 252A	Ceiling	Concrete	White	None	0	0	Negative
1	2	Main Office Kitchen 252A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Main Office Restroom 252B	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	2	Main Office Restroom 252B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Restroom 252B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Restroom 252B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Restroom 252B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Restroom 252B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Office Restroom 252B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254A	W1	Metal	White	None	0	0	Negative
1	2	Office 254A	W2	Metal	White	None	0	0	Negative
1	2	Office 254A	W3	CMU	White	None	0	0	Negative
1	2	Office 254A	W4	Metal	White	None	0	0	Negative
1	2	Office 254A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Office 254A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Dressing Room next to Auditorium Stage	W1	CMU	White	None	0	0	Negative
1	2	Girl's Dressing Room next to Auditorium Stage	W2	CMU	White	None	0	0	Negative
1	2	Girl's Dressing Room next to Auditorium Stage	W3	CMU	White	None	0	0	Negative
1	2	Girl's Dressing Room next to Auditorium Stage	W4	CMU	White	None	0	0	Negative
1	2	Girl's Dressing Room next to Auditorium Stage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Girl's Dressing Room next to Auditorium Stage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Pipe Chase in Storage Room inside Girl's Dressing Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	W1	CMU	White	None	0	0	Negative
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	W2	CMU	White	None	0	0	Negative
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	W3	CMU	White	None	0	0	Negative
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	W4	CMU	White	None	0	0	Negative
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room inside Girl's Dressing Room next to Auditorium	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Girl's Dressing Room next to Auditorium	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Girl's Dressing Room next to Auditorium	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Girl's Dressing Room next to Auditorium	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Girl's Dressing Room next to Auditorium	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Restroom inside Girl's Dressing Room next to Auditorium	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Restroom inside Girl's Dressing Room next to Auditorium	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Teacher's Office A264	Door Frame 1	Metal	Black	None	0	0	Negative
1	2	Music Teacher's Office A264	Door Frame 2	Metal	Gray	None	0	0	Negative
1	2	Music Teacher's Office A264	Door Frame 3	Metal	Gray	None	0	0	Negative
1	2	Music Teacher's Office A264	W1	CMU	White	None	0	0	Negative
1	2	Music Teacher's Office A264	W2	CMU	White	None	0	0	Negative
1	2	Music Teacher's Office A264	W3	CMU	White	None	0	0	Negative
1	2	Music Teacher's Office A264	W4	CMU	White	None	0	0	Negative
1	2	Music Teacher's Office A264	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Teacher's Office A264	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Girl's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Girl's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Teacher's Office A264 Girl's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Girl's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Girl's Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Teacher's Office A264 Girl's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Boy's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Boy's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Boy's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Boy's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Teacher's Office A264 Boy's Restroom	Ceiling	Sheetrock	White	None	0	0	Negative
1	2	Teacher's Office A264 Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom A267	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Music Classroom A267	W1	CMU	White	None	0	0	Negative
1	2	Music Classroom A267	W2	CMU	White	None	0	0	Negative
1	2	Music Classroom A267	W3	CMU	White	None	0	0	Negative
1	2	Music Classroom A267	W4	CMU	White	None	0	0	Negative
1	2	Music Classroom A267	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Music Classroom A267	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	Door Frame	Metal	Gray	None	0	0	Negative
1	2	Gymnasium C Storage Room G274A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Gymnasium C Storage Room G274A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G277 in Rear Stairwell to Girl's Locker	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Storage Room G278 in Rear Stairwell to Boy's Locker	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main hallway from 241 to 227H	W1	CMU	White	None	0	0	Negative
1	2	Main hallway from 241 to 227H	W2	CMU	White	None	0	0	Negative
1	2	Main hallway from 241 to 227H	W3	CMU	White	None	0	0	Negative
1	2	Main hallway from 241 to 227H	W4	CMU	White	None	0	0	Negative
1	2	Main hallway from 241 to 227H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main hallway from 241 to 227H	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Hallway outside IMC from 226K School Police to 227H	W1	CMU	White	None	0	0	Negative
1	2	Main Hallway outside IMC from 226K School Police to 227H	W2	CMU	White	None	0	0	Negative
1	2	Main Hallway outside IMC from 226K School Police to 227H	W3	CMU	White	None	0	0	Negative
1	2	Main Hallway outside IMC from 226K School Police to 227H	W4	CMU	White	None	0	0	Negative
1	2	Main Hallway outside IMC from 226K School Police to 227H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main Hallway outside IMC from 226K School Police to 227H	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Hallway from Classrooms 215 to 216	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 215 to 216	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 215 to 216	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 215 to 216	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 215 to 216	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 215 to 216	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway/Foyer outside of Computer Lab Suite 212	W1	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer outside of Computer Lab Suite 212	W2	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer outside of Computer Lab Suite 212	W3	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer outside of Computer Lab Suite 212	W4	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer outside of Computer Lab Suite 212	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway/Foyer outside of Computer Lab Suite 212	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway between Computer Lab 212 and 200 Learning Center	W1	CMU	White	None	0	0	Negative
1	2	Hallway between Computer Lab 212 and 200 Learning Center	W2	CMU	White	None	0	0	Negative
1	2	Hallway between Computer Lab 212 and 200 Learning Center	W3	CMU	White	None	0	0	Negative
1	2	Hallway between Computer Lab 212 and 200 Learning Center	W4	CMU	White	None	0	0	Negative
1	2	Hallway between Computer Lab 212 and 200 Learning Center	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway between Computer Lab 212 and 200 Learning Center	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway/Foyer Entrance at Stairwell 6	W1	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer Entrance at Stairwell 6	W2	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer Entrance at Stairwell 6	W3	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer Entrance at Stairwell 6	W4	CMU	White	None	0	0	Negative
1	2	Hallway/Foyer Entrance at Stairwell 6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway/Foyer Entrance at Stairwell 6	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Hallway from H24 to H221 at 239	W1	CMU	White	None	0	0	Negative
1	2	Hallway from H24 to H221 at 239	W2	CMU	White	None	0	0	Negative
1	2	Hallway from H24 to H221 at 239	W3	CMU	White	None	0	0	Negative
1	2	Hallway from H24 to H221 at 239	W4	CMU	White	None	0	0	Negative
1	2	Hallway from H24 to H221 at 239	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from H24 to H221 at 239	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 239 to 241	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 239 to 241	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 239 to 241	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 239 to 241	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 239 to 241	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 239 to 241	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from H222 to Storage Room 273	W2	CMU	White	None	0	0	Negative
1	2	Hallway from H222 to Storage Room 273	W4	CMU	White	None	0	0	Negative
1	2	Hallway from H222 to Storage Room 273	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from H222 to Storage Room 273	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway From G270 to Gymnasium A and B	W1	CMU	White	None	0	0	Negative
1	2	Hallway From G270 to Gymnasium A and B	W2	CMU	White	None	0	0	Negative
1	2	Hallway From G270 to Gymnasium A and B	W3	CMU	White	None	0	0	Negative
1	2	Hallway From G270 to Gymnasium A and B	W4	CMU	White	None	0	0	Negative
1	2	Hallway From G270 to Gymnasium A and B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway From G270 to Gymnasium A and B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway/Entrance Foyer from Main Office Suite to Gy	W1	Metal	Brown	None	0	0	Negative
1	2	Hallway/Entrance Foyer from Main Office Suite to Gy	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Hallway/Entrance Foyer from Main Office Suite to Gym	W3	Concrete	Grey	None	0	0	Negative
1	2	Hallway/Entrance Foyer from Main Office Suite to Gym	W4	CMU	White	None	0	0	Negative
1	2	Hallway/Entrance Foyer from Main Office Suite to Gym	Ceiling	Concrete	White	None	0	0	Negative
1	2	Hallway/Entrance Foyer from Main Office Suite to Gym	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Music Classrooms A267 to A269	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Music Classrooms A267 to A269	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Music Classrooms A267 to A269	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Music Classrooms A267 to A269	W4	CMU	Multi	None	0	0	Negative
1	2	Hallway from Music Classrooms A267 to A269	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Music Classrooms A267 to A269	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway to Left of Auditorium Stage	W2	CMU	White	None	0	0	Negative
1	2	Hallway to Left of Auditorium Stage	W3	CMU	White	None	0	0	Negative
1	2	Hallway to Left of Auditorium Stage	W4	CMU	multi	None	0	0	Negative
1	2	Hallway to Left of Auditorium Stage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway to Left of Auditorium Stage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	W1	Metal	Brown	None	0	0	Negative
1	2	Hallway outside Main Office Suite	W2	CMU	White	None	0	0	Negative
1	2	Hallway outside Main Office Suite	W3	CMU	White	None	0	0	Negative
1	2	Hallway outside Main Office Suite	W4	CMU	White	None	0	0	Negative
1	2	Hallway outside Main Office Suite	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway outside Main Office Suite	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 229 to 233	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 229 to 233	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 229 to 233	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Hallway from Classrooms 229 to 233	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 229 to 233	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 229 to 233	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 201 to 204	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 201 to 204	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 201 to 204	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 201 to 204	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 201 to 204	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 201 to 204	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 205 to 209	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 205 to 209	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 205 to 209	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 205 to 209	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 205 to 209	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 205 to 209	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 210 to 211	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 210 to 211	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 210 to 211	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 210 to 211	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 210 to 211	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 210 to 211	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 217 to 222	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 217 to 222	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 217 to 222	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Hallway from Classrooms 217 to 222	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 217 to 222	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 217 to 222	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 223 to 225	W1	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 223 to 225	W2	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 223 to 225	W3	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 223 to 225	W4	CMU	White	None	0	0	Negative
1	2	Hallway from Classrooms 223 to 225	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway from Classrooms 223 to 225	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway along Right Side of Auditorium Stage	W1	CMU	White	None	0	0	Negative
1	2	Hallway along Right Side of Auditorium Stage	W2	CMU	White	None	0	0	Negative
1	2	Hallway along Right Side of Auditorium Stage	W3	CMU	White	None	0	0	Negative
1	2	Hallway along Right Side of Auditorium Stage	W4	CMU	White	None	0	0	Negative
1	2	Hallway along Right Side of Auditorium Stage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway along Right Side of Auditorium Stage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway outside Auditorium	W1	CMU	Yellow	None	0	0	Negative
1	2	Hallway outside Auditorium	W2	CMU	White	None	0	0	Negative
1	2	Hallway outside Auditorium	W3	Concrete	multi	None	0	0	Negative
1	2	Hallway outside Auditorium	W4	CMU	multi	None	0	0	Negative
1	2	Hallway outside Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway outside Auditorium	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway outside Auditorium	Radiator	Metal	Purple	None	0	0	Negative
1	2	Stairwell 1	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 1	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 1	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 1	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 1	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Stairwell 1	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 1	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 1	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 1	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Front Stairwell to Girl's Locker Room	W1	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Girl's Locker Room	W2	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Girl's Locker Room	W3	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Girl's Locker Room	W4	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Floor	Concrete	Grey	Chipping	50	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Tread	Metal	Black	Chipping	5	0	Negative
1	2	Front Stairwell to Girl's Locker Room	Handrail	Metal	Black	Chipping	5	0	Negative
1	2	Front Stairwell to Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Boy's Locker Room	W2	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Boy's Locker Room	W3	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Boy's Locker Room	W4	CMU	White	None	0	0	Negative
1	2	Front Stairwell to Boy's Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Front Stairwell to Boy's Locker Room	Floor	Concrete	Grey	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Front Stairwell to Boy's Locker Room	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Front Stairwell to Boy's Locker Room	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Front Stairwell to Boy's Locker Room	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Front Stairwell to Boy's Locker Room	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	W1	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	W2	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	W3	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	W4	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Rear Stairwell to Girl's Locker Room	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Riser	Metal	Grey	Flaking	5	0	Negative
1	2	Rear Stairwell to Girl's Locker Room	Stringer	Metal	Grey	Flaking	5	0	Negative
1	2	Stairwell 13	Tread	Metal	Grey	Flaking	5	0	Negative
1	2	Stairwell 13	Door Frame	Metal	Grey	None	0	0	Negative
1	2	Stairwell 13	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 13	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 13	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 13	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 13	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 13	Floor	Concrete	Grey	Flaking	10	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 14	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 14	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 14	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 14	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 14	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 14	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Stairwell 14	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 14	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 14	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 14	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 15	W1	Concrete	White	None	0	0	Negative
1	2	Stairwell 15	W2	Concrete	White	None	0	0	Negative
1	2	Stairwell 15	W3	Concrete	White	None	0	0	Negative
1	2	Stairwell 15	W4	Concrete	White	None	0	0	Negative
1	2	Stairwell 15	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 15	Floor	Concrete	Grey	Chipping	50	0	Negative
1	2	Stairwell 15	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 15	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 15	Tread	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 15	Handrail	Metal	Purple	Chipping	5	0	Negative
1	2	Stairwell 2	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 2	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 2	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 2	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 2	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Stairwell 2	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 2	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 2	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 2	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Entrance Vestibule at Stairwell 6	W1	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule at Stairwell 6	W2	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule at Stairwell 6	W3	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule at Stairwell 6	W4	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule at Stairwell 6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Entrance Vestibule at Stairwell 6	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Main/Visitor's Entrance Vestibule	W1	CMU	White	None	0	0	Negative
1	2	Main/Visitor's Entrance Vestibule	W2	CMU	White	None	0	0	Negative
1	2	Main/Visitor's Entrance Vestibule	W3	CMU	White	None	0	0	Negative
1	2	Main/Visitor's Entrance Vestibule	W4	CMU	White	None	0	0	Negative
1	2	Main/Visitor's Entrance Vestibule	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Main/Visitor's Entrance Vestibule	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 3	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 3	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 3	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 3	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 3	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 3	Floor	Concrete	Grey	Chipping	50	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 3	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 3	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 3	Tread	Metal	Black	Chipping	5	0	Negative
1	2	Stairwell 3	Handrail	Metal	Black	Chipping	5	0	Negative
1	2	Stairwell 4	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 4	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 4	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 4	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 4	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 4	Floor	Concrete	Grey	Chipping	50	0	Negative
1	2	Stairwell 4	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 4	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 4	Tread	Metal	Black	Chipping	5	0	Negative
1	2	Stairwell 4	Handrail	Metal	Black	Chipping	5	0	Negative
1	2	Stairwell 5	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 5	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 5	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 5	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 5	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 5	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Stairwell 5	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 5	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 5	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 5	Handrail	Metal	Grey	Chipping	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 6	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 6	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 6	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 6	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairwell 6	Floor	Concrete	Grey	Chipping	2	0	Negative
1	2	Stairwell 6	Tread	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 6	Riser	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 6	Stringer	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 6	Handrail	Metal	Grey	Chipping	2	0	Negative
1	2	Stairwell 7	Riser	Metal	Grey	None	0	0	Negative
1	2	Stairwell 7	Stringer	Metal	Grey	None	0	0	Negative
1	2	Stairwell 7	Tread	Metal	Grey	None	0	0	Negative
1	2	Stairwell 7	Handrail	Metal	Grey	None	0	0	Negative
1	2	Stairwell 7	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 7	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 7	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 7	W4	CMU	White	None	0	0	Negative
1	2	Stairwell 7	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 7	Floor	Concrete	Grey	Flaking	5	0	Negative
1	2	Stairwell 8	W1	CMU	White	None	0	0	Negative
1	2	Stairwell 8	W2	CMU	White	None	0	0	Negative
1	2	Stairwell 8	W3	CMU	White	None	0	0	Negative
1	2	Stairwell 8	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Stairwell 8	Ceiling	Concrete	White	None	0	0	Negative
1	2	Stairwell 8	Floor	Concrete	Grey	Chipping	50	0	Negative
1	2	Stairwell 8	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 8	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Stairwell 8	Tread	Metal	Black	Chipping	5	0	Negative
1	2	Stairwell 8	Handrail	Metal	Black	Chipping	5	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	W2	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	W3	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	W4	CMU	White	None	0	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Floor	Concrete	Grey	Chipping	50	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Riser	Metal	Grey	Chipping	5	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Stringer	Metal	Grey	Chipping	5	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Tread	Metal	Black	Chipping	5	0	Negative
1	2	Rear Stairwell to Boy's Locker Room	Handrail	Metal	Black	Chipping	5	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	W1	Metal	Brown	None	0	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	W2	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	W3	Metal	Brown	None	0	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	W4	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	Ceiling	Concrete	White	None	0	0	Negative
1	2	Entrance Vestibule beside Stairwell 11	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Entrance Vestibule to Hallway/Entrance Foyer betwe	W1	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway/Entrance Foyer betwe	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	2	Entrance Vestibule to Hallway/Entrance Foyer between	W3	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway/Entrance Foyer between	W4	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway/Entrance Foyer between	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Entrance Vestibule to Hallway/Entrance Foyer between	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	2	Entrance Vestibule to Hallway outside Main Office Suite	W1	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway outside Main Office Suite	W2	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway outside Main Office Suite	W3	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway outside Main Office Suite	W4	CMU	White	None	0	0	Negative
1	2	Entrance Vestibule to Hallway outside Main Office Suite	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	Entrance Vestibule to Hallway outside Main Office Suite	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Kitchen	W1	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Kitchen	W2	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Kitchen	W3	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Kitchen	W4	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Kitchen	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Kitchen	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Lab Classroom	W1	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Lab Classroom	W2	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Lab Classroom	W3	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Lab Classroom	W4	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Lab Classroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Lab Classroom	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Restaurant	W1	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Restaurant	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Culinary Arts Learning Center Restaurant	W3	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Restaurant	W4	CMU	White	None	0	0	Negative
1	3	Culinary Arts Learning Center Restaurant	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Arts Learning Center Restaurant	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Dry Goods Storage	W1	CMU	White	None	0	0	Negative
1	3	Dry Goods Storage	W2	CMU	White	None	0	0	Negative
1	3	Dry Goods Storage	W3	CMU	White	None	0	0	Negative
1	3	Dry Goods Storage	W4	CMU	White	None	0	0	Negative
1	3	Dry Goods Storage	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Dry Goods Storage	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Locker Hallway	W1	CMU	White	None	0	0	Negative
1	3	Culinary Locker Hallway	W2	CMU	White	None	0	0	Negative
1	3	Culinary Locker Hallway	W3	CMU	White	None	0	0	Negative
1	3	Culinary Locker Hallway	W4	CMU	White	None	0	0	Negative
1	3	Culinary Locker Hallway	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Culinary Locker Hallway	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room 300L outside of Culinary Arts Learning Center	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 301	W1	CMU	White	None	0	0	Negative
1	3	Classroom 301	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 301	W3	CMU	White	None	0	0	Negative
1	3	Classroom 301	W4	CMU	White	None	0	0	Negative
1	3	Classroom 301	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 301	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 304	W2	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	W3	CMU	Blue	None	0	0	Negative
1	3	Classroom 304	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 304	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 304	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305	W1	CMU	White	None	0	0	Negative
1	3	Classroom 305	W2	CMU	White	None	0	0	Negative
1	3	Classroom 305	W3	CMU	White	None	0	0	Negative
1	3	Classroom 305	W4	CMU	White	None	0	0	Negative
1	3	Classroom 305	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 305	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 306	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 306	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 306	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 306	W3	CMU	Blue	None	0	0	Negative
1	3	Classroom 306	W4	CMU	Red	None	0	0	Negative
1	3	Classroom 306	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 306	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307	Door Frame	Metal	Grey	Chipping	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 307	W1	CMU	White	None	0	0	Negative
1	3	Classroom 307	W2	CMU	White	None	0	0	Negative
1	3	Classroom 307	W3	CMU	White	None	0	0	Negative
1	3	Classroom 307	W4	CMU	White	None	0	0	Negative
1	3	Classroom 307	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 307	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 308	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 308	W1	CMU	White	None	0	0	Negative
1	3	Classroom 308	W2	CMU	White	None	0	0	Negative
1	3	Classroom 308	W3	CMU	White	None	0	0	Negative
1	3	Classroom 308	W4	CMU	White	None	0	0	Negative
1	3	Classroom 308	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 308	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 309	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 309	W1	CMU	White	None	0	0	Negative
1	3	Classroom 309	W2	CMU	White	None	0	0	Negative
1	3	Classroom 309	W3	CMU	White	None	0	0	Negative
1	3	Classroom 309	W4	CMU	White	None	0	0	Negative
1	3	Classroom 309	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 309	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 310	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 310	W1	CMU	White	None	0	0	Negative
1	3	Classroom 310	W2	CMU	Tan	None	0	0	Negative
1	3	Classroom 310	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 310	W4	CMU	White	None	0	0	Negative
1	3	Classroom 310	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 310	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 311	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 311	W1	CMU	White	None	0	0	Negative
1	3	Classroom 311	W2	CMU	White	None	0	0	Negative
1	3	Classroom 311	W3	CMU	White	None	0	0	Negative
1	3	Classroom 311	W4	CMU	White	None	0	0	Negative
1	3	Classroom 311	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 311	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 312	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 312	W1	CMU	White	None	0	0	Negative
1	3	Classroom 312	W2	CMU	White	None	0	0	Negative
1	3	Classroom 312	W3	CMU	White	None	0	0	Negative
1	3	Classroom 312	W4	CMU	White	None	0	0	Negative
1	3	Classroom 312	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 312	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Storage Room 313	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 313	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Boy's Restroom 313A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 313A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 313A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 313A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 313A	Ceiling	Sheetrock	White	None	0	0	Negative
1	3	Boy's Restroom 313A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 313B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Girl's Restroom 313B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	313A Computer Lab	W1	CMU	White	None	0	0	Negative
1	3	313A Computer Lab	W2	CMU	White	None	0	0	Negative
1	3	313A Computer Lab	W3	CMU	White	None	0	0	Negative
1	3	313A Computer Lab	W4	CMU	White	None	0	0	Negative
1	3	313A Computer Lab	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	313A Computer Lab	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	313A Computer Lab	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	3	Mechanical Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room	Door Frame	Metal	Purple	Chipping	1	0	Negative
1	3	Cafeteria 314	Door Frame 1	Metal	Purple	None	0	0	Negative
1	3	Cafeteria 314	Door Frame 2	Metal	Purple	None	0	0	Negative
1	3	Cafeteria 314	W1	CMU	Yellow	None	0	0	Negative
1	3	Cafeteria 314	W2	CMU	Yellow	None	0	0	Negative
1	3	Cafeteria 314	W3	CMU	Yellow	None	0	0	Negative
1	3	Cafeteria 314	W4	CMU	Yellow	None	0	0	Negative
1	3	Cafeteria 314	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Cafeteria 314	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase off Cafeteria 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	314B Pantry	Door Frame	Metal	Purple	None	0	0	Negative
1	3	314B Pantry	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	314B Pantry	W2	CMU	White	None	0	0	Negative
1	3	314B Pantry	W3	CMU	White	None	0	0	Negative
1	3	314B Pantry	W4	CMU	White	None	0	0	Negative
1	3	314B Pantry	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	314B Pantry	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 314C	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 314C	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 314C	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 314C	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 314C	Ceiling	Sheetrock	White	None	0	0	Negative
1	3	Girl's Restroom 314C	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 314D	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 314D	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 314D	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 314D	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 314D	Ceiling	Sheetrock	White	None	0	0	Negative
1	3	Boy's Restroom 314D	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage in Cafeteria 314	W1	CMU	White	None	0	0	Negative
1	3	Storage in Cafeteria 314	W2	CMU	White	None	0	0	Negative
1	3	Storage in Cafeteria 314	W3	CMU	White	None	0	0	Negative
1	3	Storage in Cafeteria 314	W4	CMU	White	None	0	0	Negative
1	3	Storage in Cafeteria 314	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage in Cafeteria 314	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 315	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 315	W2	CMU	White	None	0	0	Negative
1	3	Classroom 315	W3	CMU	White	None	0	0	Negative
1	3	Classroom 315	W4	CMU	White	None	0	0	Negative
1	3	Classroom 315	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 315	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 316	Door Frame	Metal	Grey	Chipping	2	0	Negative
1	3	Classroom 316	W1	CMU	Blue	Flaking	100	0	Negative
1	3	Classroom 316	W2	CMU	Blue	Flaking	10	0	Negative
1	3	Classroom 316	W3	CMU	Blue	Flaking	25	0	Negative
1	3	Classroom 316	W4	CMU	Yellow	Flaking	50	0	Negative
1	3	Classroom 316	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 316	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 317	Door Frame	Metal	Tan	Chipping	2	0	Negative
1	3	Classroom 317	W1	CMU	White	None	0	0	Negative
1	3	Classroom 317	W2	CMU	White	None	0	0	Negative
1	3	Classroom 317	W3	CMU	White	None	0	0	Negative
1	3	Classroom 317	W4	CMU	White	None	0	0	Negative
1	3	Classroom 317	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 317	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318	Door Frame	Metal	Tan	Chipping	2	0	Negative
1	3	Classroom 318	W1	CMU	White	None	0	0	Negative
1	3	Classroom 318	W2	CMU	White	None	0	0	Negative
1	3	Classroom 318	W3	CMU	White	None	0	0	Negative
1	3	Classroom 318	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 318	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 318	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Teacher's Office 319	W1	CMU	White	None	0	0	Negative
1	3	Teacher's Office 319	W2	CMU	White	None	0	0	Negative
1	3	Teacher's Office 319	W3	CMU	White	None	0	0	Negative
1	3	Teacher's Office 319	W4	CMU	White	None	0	0	Negative
1	3	Teacher's Office 319	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Teacher's Office 319	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 320	Door Frame	Metal	Tan	Chipping	2	0	Negative
1	3	Classroom 320	W1	CMU	Blue	Chipping	5	0	Negative
1	3	Classroom 320	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 320	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 320	W4	CMU	Blue	Chipping	25	0	Negative
1	3	Classroom 320	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 320	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 321	Door Frame	Metal	Tan	None	0	0	Negative
1	3	Classroom 321	W1	CMU	White	Chipping	2	0	Negative
1	3	Classroom 321	W2	CMU	White	None	0	0	Negative
1	3	Classroom 321	W3	CMU	White	Chipping	10	0	Negative
1	3	Classroom 321	W4	CMU	White	Chipping	25	0	Negative
1	3	Classroom 321	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 321	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 322	Door Frame	Metal	Tan	Chipping	2	0	Negative
1	3	Classroom 322	W1	CMU	Blue	Chipping	10	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 322	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 322	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 322	W4	CMU	Blue	Chipping	25	0	Negative
1	3	Classroom 322	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 322	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 323	Door Frame	Metal	Tan	Chipping	10	0	Negative
1	3	Classroom 323	W1	CMU	Green	Chipping	2	0	Negative
1	3	Classroom 323	W2	CMU	Green	None	0	0	Negative
1	3	Classroom 323	W3	CMU	Green	Chipping	10	0	Negative
1	3	Classroom 323	W4	CMU	Green	Chipping	25	0	Negative
1	3	Classroom 323	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 323	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 324	Door Frame	Metal	Tan	None	0	0	Negative
1	3	Classroom 324	W1	CMU	White	Chipping	3	0	Negative
1	3	Classroom 324	W2	CMU	White	None	0	0	Negative
1	3	Classroom 324	W3	CMU	White	Chipping	10	0	Negative
1	3	Classroom 324	W4	CMU	White	Chipping	25	0	Negative
1	3	Classroom 324	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 324	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 325	Door Frame	Metal	Tan	None	0	0	Negative
1	3	Classroom 325	W1	CMU	White	Chipping	4	0	Negative
1	3	Classroom 325	W2	CMU	White	Flaking	25	0	Negative
1	3	Classroom 325	W3	CMU	White	Chipping	5	0	Negative
1	3	Classroom 325	W4	CMU	White	Chipping	5	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 325	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 325	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Learning Center 326	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Learning Center 326	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Learning Center 326	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Learning Center 326	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Learning Center 326	Concrete	Column 1	White	None	0	0	Negative
1	3	Learning Center 326	Concrete	Column 1	Purple	None	0	0	Negative
1	3	Learning Center 326	Concrete	Column 2	White	None	0	0	Negative
1	3	Learning Center 326	Concrete	Column 2	Purple	None	0	0	Negative
1	3	Learning Center 326	Column 3	Concrete	White	None	0	0	Negative
1	3	Learning Center 326	Column 3	Concrete	Purple	None	0	0	Negative
1	3	Learning Center 326	Column 4	Concrete	White	None	0	0	Negative
1	3	Learning Center 326	Column 4	Concrete	Purple	None	0	0	Negative
1	3	Learning Center 326	W1	CMU	White	None	0	0	Negative
1	3	Learning Center 326	W1	CMU	Purple	None	0	0	Negative
1	3	Learning Center 326	W2	CMU	White	None	0	0	Negative
1	3	Learning Center 326	W2	CMU	Purple	None	0	0	Negative
1	3	Learning Center 326	W3	CMU	White	None	0	0	Negative
1	3	Learning Center 326	W3	CMU	Purple	None	0	0	Negative
1	3	Learning Center 326	W4	CMU	White	None	0	0	Negative
1	3	Learning Center 326	W4	CMU	Purple	None	0	0	Negative
1	3	Learning Center 326	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Learning Center 326	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Storage Closet 326A	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet 326A	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet 326A	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet 326A	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet 326A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 326A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326B	W1	CMU	White	None	0	0	Negative
1	3	Office 326B	W2	CMU	White	None	0	0	Negative
1	3	Office 326B	W3	CMU	White	None	0	0	Negative
1	3	Office 326B	W4	CMU	White	None	0	0	Negative
1	3	Office 326B	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326B	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Office 326C	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Office 326C	W1	CMU	White	None	0	0	Negative
1	3	Office 326C	W2	CMU	White	None	0	0	Negative
1	3	Office 326C	W3	CMU	White	None	0	0	Negative
1	3	Office 326C	W4	CMU	White	None	0	0	Negative
1	3	Office 326C	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326D	W1	CMU	White	None	0	0	Negative
1	3	Office 326D	W2	CMU	White	None	0	0	Negative
1	3	Office 326D	W3	CMU	White	None	0	0	Negative
1	3	Office 326D	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Office 326D	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326D	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326D	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Office 326E	Door Frame	Metal	Grey	Chipping	2	0	Negative
1	3	Office 326E	W1	CMU	White	None	0	0	Negative
1	3	Office 326E	W2	CMU	White	None	0	0	Negative
1	3	Office 326E	W3	CMU	White	None	0	0	Negative
1	3	Office 326E	W4	CMU	White	None	0	0	Negative
1	3	Office 326E	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326E	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326F	W1	CMU	White	None	0	0	Negative
1	3	Office 326F	W2	CMU	White	None	0	0	Negative
1	3	Office 326F	W3	CMU	White	None	0	0	Negative
1	3	Office 326F	W4	CMU	White	None	0	0	Negative
1	3	Office 326F	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326F	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326F	Door Frame	Metal	Grey	Chipping	1	0	Negative
1	3	Office 326G	W1	CMU	White	None	0	0	Negative
1	3	Office 326G	W2	CMU	White	None	0	0	Negative
1	3	Office 326G	W3	CMU	White	None	0	0	Negative
1	3	Office 326G	W4	CMU	White	None	0	0	Negative
1	3	Office 326G	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326G	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 326G	Door Frame	Metal	Grey	Chipping	1	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Custodial Closet 326H	W1	CMU	White	None	0	0	Negative
1	3	Custodial Closet 326H	W2	CMU	White	None	0	0	Negative
1	3	Custodial Closet 326H	W3	CMU	White	None	0	0	Negative
1	3	Custodial Closet 326H	W4	CMU	White	None	0	0	Negative
1	3	Custodial Closet 326H	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Custodial Closet 326H	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 326l	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Storage Closet 326l	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet 326l	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet 326l	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet 326l	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet 326l	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 326l	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	TV Studio 327	Door Frame	Metal	Tan	Chipping	1	0	Negative
1	3	TV Studio 327	W1	CMU	White	Chipping	2	0	Negative
1	3	TV Studio 327	W2	CMU	White	None	0	0	Negative
1	3	TV Studio 327	W3	CMU	White	Chipping	5	0	Negative
1	3	TV Studio 327	W4	CMU	White	Chipping	2	0	Negative
1	3	TV Studio 327	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	TV Studio 327	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 328	Door Frame	Metal	Tan	None	0	0	Negative
1	3	Classroom 328	W1	CMU	Blue	Chipping	3	0	Negative
1	3	Classroom 328	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 328	W3	CMU	Blue	Chipping	10	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 328	W4	CMU	Blue	Chipping	5	0	Negative
1	3	Classroom 328	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 328	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329	W1	CMU	White	None	0	0	Negative
1	3	Storage Room 329	W2	CMU	White	None	0	0	Negative
1	3	Storage Room 329	W3	CMU	White	None	0	0	Negative
1	3	Storage Room 329	W4	CMU	White	None	0	0	Negative
1	3	Storage Room 329	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329A	W1	CMU	White	None	0	0	Negative
1	3	Storage Room 329A	W2	CMU	White	None	0	0	Negative
1	3	Storage Room 329A	W3	CMU	White	None	0	0	Negative
1	3	Storage Room 329A	W4	CMU	White	None	0	0	Negative
1	3	Storage Room 329A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329B	W1	CMU	White	None	0	0	Negative
1	3	Storage Room 329B	W2	CMU	White	None	0	0	Negative
1	3	Storage Room 329B	W3	CMU	White	None	0	0	Negative
1	3	Storage Room 329B	W4	CMU	White	None	0	0	Negative
1	3	Storage Room 329B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329C	W1	CMU	White	None	0	0	Negative
1	3	Storage Room 329C	W2	CMU	White	None	0	0	Negative
1	3	Storage Room 329C	W3	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Storage Room 329C	W4	CMU	White	None	0	0	Negative
1	3	Storage Room 329C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 329C	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 330	Door Frame	Metal	Yellow	None	0	0	Negative
1	3	Storage Room 330	W1	CMU	White	None	0	0	Negative
1	3	Storage Room 330	W2	CMU	White	None	0	0	Negative
1	3	Storage Room 330	W3	CMU	White	None	0	0	Negative
1	3	Storage Room 330	W4	CMU	White	None	0	0	Negative
1	3	Storage Room 330	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 330	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 331	W1	CMU	White	None	0	0	Negative
1	3	Office 331	W2	CMU	White	None	0	0	Negative
1	3	Office 331	W3	CMU	White	None	0	0	Negative
1	3	Office 331	W4	CMU	White	None	0	0	Negative
1	3	Office 331	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 331	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	Door Frame	Metal	Yellow	None	0	0	Negative
1	3	Storage Room 332	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 332	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Computer Lab 333	Door Frame	Metal	Yellow	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Computer Lab 333	W1	CMU	White	None	0	0	Negative
1	3	Computer Lab 333	W2	CMU	White	None	0	0	Negative
1	3	Computer Lab 333	W3	CMU	White	None	0	0	Negative
1	3	Computer Lab 333	W4	CMU	White	None	0	0	Negative
1	3	Computer Lab 333	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Computer Lab 333	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet in Computer Lab 333	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet in Computer Lab 333	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet in Computer Lab 333	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet in Computer Lab 333	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet in Computer Lab 333	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet in Computer Lab 333	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Electrical Room in 321	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office Space in T349	W1	CMU	White	None	0	0	Negative
1	3	Office Space in T349	W2	CMU	White	None	0	0	Negative
1	3	Office Space in T349	W3	CMU	White	None	0	0	Negative
1	3	Office Space in T349	W4	CMU	White	None	0	0	Negative
1	3	Office Space in T349	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Office Space in T349	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Pipe Chase in Staff Restroom 354B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Staff Restroom 354B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Staff Restroom 354B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Staff Restroom 354B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Staff Restroom 354B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Staff Restroom 354B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 370A	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 370A	W1	CMU	Blue	Flaking	50	0	Negative
1	3	Classroom 370A	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 370A	W3	CMU	Blue	Flaking	50	0	Negative
1	3	Classroom 370A	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 370A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 370A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 370B	W1	CMU	White	None	0	0	Negative
1	3	Classroom 370B	W2	CMU	White	None	0	0	Negative
1	3	Classroom 370B	W3	CMU	White	None	0	0	Negative
1	3	Classroom 370B	W4	CMU	White	None	0	0	Negative
1	3	Classroom 370B	Ceiling	Concrete	White	None	0	0	Negative
1	3	Classroom 370B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room G371	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Mechanical Room G371	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room G371	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room G371	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room G371	W4	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Mechanical Room G371	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room G371	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 372	Door Frame	Metal	Grey	Chipping	5	0	Negative
1	3	Classroom 372	W1	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 372	W2	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 372	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 372	W4	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 372	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 372	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 373	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 373	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 373	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 373	W3	CMU	Blue	None	0	0	Negative
1	3	Classroom 373	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 373	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 373	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 374	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 374	W1	CMU	Blue	Flaking	10	0	Negative
1	3	Classroom 374	W2	CMU	Blue	Flaking	10	0	Negative
1	3	Classroom 374	W3	CMU	Blue	Flaking	10	0	Negative
1	3	Classroom 374	W4	CMU	Blue	Flaking	10	0	Negative
1	3	Classroom 374	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 374	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	Door Frame	Metal	Grey	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Nurse's Office Waiting Room 375	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Waiting Room 375	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Nurse's Office 375A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office 375A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Nurse's Office Storage Closet	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Storage Closet	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Rear Patient Room	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Nurse's Office Suite Rear Patient Room	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Rear Patient Room	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Rear Patient Room	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Nurse's Office Suite Rear Patient Room	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Rear Patient Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Rear Patient Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Nurse's Office Suite Side Patient Room	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Side Patient Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Nurse's Office Suite Front Patient Room	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Nurse's Office Suite Front Patient Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Nurse's Office Suite Front Patient Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Restroom in 375D	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Restroom in 375D	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375D	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375D	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375D	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375D	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Restroom in 375E	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in 375E	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Auditorium Balcony	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Auditorium Balcony	W1	CMU	White	Chipping	5	0	Negative
1	3	Auditorium Balcony	W2	CMU	White	None	0	0	Negative
1	3	Auditorium Balcony	Banister	Wood	White	None	0	0	Negative
1	3	Auditorium Balcony	W4	CMU	White	Chipping	5	0	Negative
1	3	Auditorium Balcony	Ceiling	Sheetrock	White	None	0	0	Negative
1	3	Auditorium Balcony	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351	Door Frame	Metal	White	None	0	0	Negative
1	3	Classroom 351	W1	CMU	White	None	0	0	Negative
1	3	Classroom 351	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 351	W3	CMU	White	None	0	0	Negative
1	3	Classroom 351	W4	CMU	White	None	0	0	Negative
1	3	Classroom 351	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Storage Room 351A	Door Frame	Metal	White	None	0	0	Negative
1	3	Classroom 351 Storage Room 351A	W1	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351A	W2	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351A	W3	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351A	W4	CMU	White	None	0	0	Negative
1	3	Classroom 351 Storage Room 351A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Storage Room 351A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Storage Room 351B	Door Frame	Metal	White	None	0	0	Negative
1	3	Classroom 351 Storage Room 351B	W1	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351B	W2	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351B	W3	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351B	W4	CMU	Purple	None	0	0	Negative
1	3	Classroom 351 Storage Room 351B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Storage Room 351B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Boy's Restroom 351C	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 351 Boy's Restroom 351C	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Boy's Restroom 351C	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Boy's Restroom 351C	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Boy's Restroom 351C	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Boy's Restroom 351C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 351 Boy's Restroom 351C	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 351 Girl's Restroom 351D	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 351 Girl's Restroom 351D	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352	Door Frame	Metal	Blue	None	0	0	Negative
1	3	Classroom 352	W1	CMU	Yellow	None	0	0	Negative
1	3	Classroom 352	W2	CMU	Yellow	None	0	0	Negative
1	3	Classroom 352	W3	CMU	Yellow	None	0	0	Negative
1	3	Classroom 352	W4	CMU	Yellow	None	0	0	Negative
1	3	Classroom 352	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 352 Storage Room 352A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 352 Storage Room 352A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353	W1	CMU	Yellow	None	0	0	Negative
1	3	Classroom 353	W2	CMU	Yellow	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 353	W3	CMU	Yellow	None	0	0	Negative
1	3	Classroom 353	W4	CMU	Yellow	None	0	0	Negative
1	3	Classroom 353	Ceiling	Concrete	White	None	0	0	Negative
1	3	Classroom 353	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Classroom 353 Storage Room 353A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353 Storage Room 353A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353 Storage Room 353A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353 Storage Room 353A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353 Storage Room 353A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 353 Storage Room 353A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room A354	Door Frame	Metal	Grey	Chipping	5	0	Negative
1	3	Storage Room A354	W1	CMU	White	None	0	0	Negative
1	3	Storage Room A354	W2	CMU	White	None	0	0	Negative
1	3	Storage Room A354	W3	CMU	White	None	0	0	Negative
1	3	Storage Room A354	W4	CMU	White	None	0	0	Negative
1	3	Storage Room A354	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room A354	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 354A	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Storage Room 354A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 354A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 354A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 354A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room 354A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Storage Room 354A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Staff Restroom 354B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Staff Restroom 354B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Kitchen 355	Door Frame	Metal	Grey	None	0	0	Negative
1	3	Kitchen 355	W1	CMU	White	None	0	0	Negative
1	3	Kitchen 355	W2	CMU	White	None	0	0	Negative
1	3	Kitchen 355	W3	CMU	White	None	0	0	Negative
1	3	Kitchen 355	W4	CMU	White	None	0	0	Negative
1	3	Kitchen 355	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Kitchen 355	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Assistant Superintendent's Office across from Classroom 356	Door Frame	Metal	Grey	Chipping	5	0	Negative
1	3	Assistant Superintendent's Office across from Classroom 356	W1	CMU	White	None	0	0	Negative
1	3	Assistant Superintendent's Office across from Classroom 356	W2	CMU	White	None	0	0	Negative
1	3	Assistant Superintendent's Office across from Classroom 356	W3	CMU	White	None	0	0	Negative
1	3	Assistant Superintendent's Office across from Classroom 356	W4	CMU	White	None	0	0	Negative
1	3	Assistant Superintendent's Office across from Classroom 356	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Assistant Superintendent's Office across from Classroom 356	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Conference room next to A356	Door Frame 1	Metal	Grey	None	0	0	Negative
1	3	Conference room next to A356	Door Frame 2	Metal	Grey	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Conference room next to A356	W1	CMU	White	None	0	0	Negative
1	3	Conference room next to A356	W2	CMU	White	None	0	0	Negative
1	3	Conference room next to A356	W3	CMU	White	None	0	0	Negative
1	3	Conference room next to A356	W4	CMU	White	None	0	0	Negative
1	3	Conference room next to A356	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Conference room next to A356	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	3	Auditorium Balcony Projection Room	W1	Plaster	White	None	0	0	Negative
1	3	Auditorium Balcony Projection Room	W2	Plaster	White	None	0	0	Negative
1	3	Auditorium Balcony Projection Room	W3	Plaster	White	None	0	0	Negative
1	3	Auditorium Balcony Projection Room	W4	Plaster	White	None	0	0	Negative
1	3	Auditorium Balcony Projection Room	Ceiling	Plaster	White	None	0	0	Negative
1	3	Auditorium Balcony Projection Room	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Mechanical Room A374	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Shaft in Mechanical Room A374	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Main Hallway from T346 to 333	W1	CMU	White	None	0	0	Negative
1	3	Main Hallway from T346 to 333	W2	CMU	White	None	0	0	Negative
1	3	Main Hallway from T346 to 333	W3	CMU	White	None	0	0	Negative
1	3	Main Hallway from T346 to 333	W4	CMU	White	None	0	0	Negative
1	3	Main Hallway from T346 to 333	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Main Hallway from T346 to 333	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Main Hallway from 322 to 327	W1	CMU	White	None	0	0	Negative
1	3	Main Hallway from 322 to 327	W2	CMU	White	None	0	0	Negative
1	3	Main Hallway from 322 to 327	W3	CMU	White	None	0	0	Negative
1	3	Main Hallway from 322 to 327	W4	CMU	White	None	0	0	Negative
1	3	Main Hallway from 322 to 327	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Main Hallway from 322 to 327	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 315 to 316	Door Frame	Metal	Yellow	Chipping	5	0	Negative
1	3	Hallway from Classrooms 315 to 316	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 315 to 316	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 315 to 316	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 315 to 316	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 315 to 316	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 315 to 316	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from T334 to T335A	W1	CMU	White	None	0	0	Negative
1	3	Hallway from T334 to T335A	W2	CMU	White	None	0	0	Negative
1	3	Hallway from T334 to T335A	W3	CMU	White	None	0	0	Negative
1	3	Hallway from T334 to T335A	W4	CMU	White	None	0	0	Negative
1	3	Hallway from T334 to T335A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Hallway from T334 to T335A	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from T340 to t341	W1	CMU	White	None	0	0	Negative
1	3	Hallway from T340 to t341	W2	CMU	White	None	0	0	Negative
1	3	Hallway from T340 to t341	W3	CMU	White	None	0	0	Negative
1	3	Hallway from T340 to t341	W4	CMU	White	None	0	0	Negative
1	3	Hallway from T340 to t341	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from T340 to t341	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Science Wing Classrooms T341 to 346	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Science Wing Classrooms T341 to 346	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Science Wing Classrooms T341 to 346	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Science Wing Classrooms T341 to 346	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Science Wing Classrooms T341 to 346	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Science Wing Classrooms T341 to 346	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase In Hallway H321	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside Mechanical Room G371	W2	CMU	White	None	0	0	Negative
1	3	Hallway outside Mechanical Room G371	W2	CMU	Orange	None	0	0	Negative
1	3	Hallway outside Mechanical Room G371	W4	CMU	White	None	0	0	Negative
1	3	Hallway outside Mechanical Room G371	W4	CMU	Orange	None	0	0	Negative
1	3	Hallway outside Mechanical Room G371	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Hallway outside Mechanical Room G371	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 370A to 370B	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 370A to 370B	W2	CMU	Orange	None	0	0	Negative
1	3	Hallway from Classrooms 370A to 370B	W3	CMU	White	Chipping	5	0	Negative
1	3	Hallway from Classrooms 370A to 370B	W4	CMU	Orange	None	0	0	Negative
1	3	Hallway from Classrooms 370A to 370B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 370A to 370B	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from H323 to H327	W1	CMU	White	None	0	0	Negative
1	3	Hallway from H323 to H327	W2	CMU	White	None	0	0	Negative
1	3	Hallway from H323 to H327	W3	CMU	White	None	0	0	Negative
1	3	Hallway from H323 to H327	W4	CMU	White	None	0	0	Negative
1	3	Hallway from H323 to H327	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from H323 to H327	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Main Hallway to Classroom 328	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Main Hallway to Classroom 328	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Main Hallway to Classroom 328	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Main Hallway to Classroom 328	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Main Hallway to Classroom 328	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside Auditorium Balcony	W1	CMU	White	None	0	0	Negative
1	3	Hallway outside Auditorium Balcony	W2	CMU	White	None	0	0	Negative
1	3	Hallway outside Auditorium Balcony	W3	CMU	White	None	0	0	Negative
1	3	Hallway outside Auditorium Balcony	W4	CMU	White	None	0	0	Negative
1	3	Hallway outside Auditorium Balcony	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside Auditorium Balcony	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Hallway outside Balcony to Mechanical Room A374	W1	CMU	White	None	0	0	Negative
1	3	Hallway outside Balcony to Mechanical Room A374	W2	CMU	White	None	0	0	Negative
1	3	Hallway outside Balcony to Mechanical Room A374	W3	CMU	White	None	0	0	Negative
1	3	Hallway outside Balcony to Mechanical Room A374	W4	CMU	White	None	0	0	Negative
1	3	Hallway outside Balcony to Mechanical Room A374	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside Balcony to Mechanical Room A374	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms A351 to A353	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms A351 to A353	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms A351 to A353	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms A351 to A353	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms A351 to A353	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms A351 to A353	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in H329 Near 351	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Restroom in Hallway H329 Near Section D	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Small Hallway next to T345 Music	W1	CMU	White	None	0	0	Negative
1	3	Small Hallway next to T345 Music	W2	CMU	White	None	0	0	Negative
1	3	Small Hallway next to T345 Music	W3	CMU	White	None	0	0	Negative
1	3	Small Hallway next to T345 Music	W4	CMU	White	None	0	0	Negative
1	3	Small Hallway next to T345 Music	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Small Hallway next to T345 Music	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside classroom 333	W1	CMU	White	None	0	0	Negative
1	3	Hallway outside classroom 333	W2	CMU	White	None	0	0	Negative
1	3	Hallway outside classroom 333	W3	CMU	White	None	0	0	Negative
1	3	Hallway outside classroom 333	W4	CMU	White	None	0	0	Negative
1	3	Hallway outside classroom 333	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway outside classroom 333	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway From 345A to 339	W1	CMU	White	None	0	0	Negative
1	3	Hallway From 345A to 339	W2	CMU	White	None	0	0	Negative
1	3	Hallway From 345A to 339	W3	CMU	White	None	0	0	Negative
1	3	Hallway From 345A to 339	W4	CMU	White	None	0	0	Negative
1	3	Hallway From 345A to 339	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway From 345A to 339	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Pipe Chase in Hallway From 345A to 339	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Hallway from Classrooms 301 to 304	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 301 to 304	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 301 to 304	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 301 to 304	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 301 to 304	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 301 to 304	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway to rooms A354A and A354B	W1	CMU	White	None	0	0	Negative
1	3	Hallway to rooms A354A and A354B	W2	CMU	White	None	0	0	Negative
1	3	Hallway to rooms A354A and A354B	W3	CMU	White	None	0	0	Negative
1	3	Hallway to rooms A354A and A354B	W4	CMU	White	None	0	0	Negative
1	3	Hallway to rooms A354A and A354B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway to rooms A354A and A354B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 310 to 312	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 310 to 312	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 310 to 312	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 310 to 312	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 310 to 312	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 310 to 312	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 305 to 309	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 305 to 309	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 305 to 309	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 305 to 309	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 305 to 309	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 305 to 309	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Hallway from Classrooms 317 to 322	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 317 to 322	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 317 to 322	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 317 to 322	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 317 to 322	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 317 to 322	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 323 to 325	W1	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 323 to 325	W2	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 323 to 325	W3	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 323 to 325	W4	CMU	White	None	0	0	Negative
1	3	Hallway from Classrooms 323 to 325	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Hallway from Classrooms 323 to 325	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Stairwell 1	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 1	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 1	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 1	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 1	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 1	Floor	Concrete	Brown	Friction	2	0	Negative
1	3	Stairwell 1	Stringer	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 1	Tread	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 1	Riser	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 1	Handrail	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 10	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 10	W2	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Stairwell 10	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 10	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 10	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 10	Floor	Concrete	Brown	Friction	2	0	Negative
1	3	Stairwell 10	Stringer	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 10	Tread	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 10	Riser	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 10	Handrail	Metal	Black	Friction	2	0	Negative
1	3	Stairwell 13	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 13	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 13	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 13	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 13	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 13	Floor	Concrete	Brown	Friction	2	0	Negative
1	3	Stairwell 13	Stringer	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 13	Tread	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 13	Riser	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 13	Handrail	Metal	Black	Friction	2	0	Negative
1	3	Stairwell 14	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 14	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 14	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 14	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 14	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 14	Floor	Concrete	Grey	Friction	5	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Stairwell 14	Stringer	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 14	Tread	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 14	Riser	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 14	Handrail	Metal	Black	Friction	2	0	Negative
1	3	Stairwell 15	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 15	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 15	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 15	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 15	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 15	Floor	Concrete	Blue	Friction	5	0	Negative
1	3	Stairwell 15	Stringer	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 15	Tread	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 15	Riser	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 15	Handrail	Metal	Purple	Friction	2	0	Negative
1	3	Stairwell 2	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 2	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 2	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 2	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 2	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 2	Floor	Concrete	Blue	Friction	5	0	Negative
1	3	Stairwell 2	Stringer	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 2	Tread	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 2	Riser	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 2	Handrail	Metal	Black	Friction	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Stairwell 3	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 3	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 3	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 3	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 3	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 3	Floor	Concrete	Grey	Chipping	2	0	Negative
1	3	Stairwell 3	Riser	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 3	Tread	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 3	Stringer	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 3	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 4	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 4	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 4	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 4	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 4	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 4	Floor	Concrete	Grey	Chipping	2	0	Negative
1	3	Stairwell 4	Riser	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 4	Tread	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 4	Stringer	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 4	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 5	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 5	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 5	W3	CMU	White	Chipping	5	0	Negative
1	3	Stairwell 5	W4	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Stairwell 5	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 5	Floor	Concrete	Brown	Friction	5	0	Negative
1	3	Stairwell 5	Stringer	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 5	Tread	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 5	Riser	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 5	Handrail	Metal	Black	Friction	2	0	Negative
1	3	Stairwell 6	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 6	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 6	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 6	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 6	Ceiling	Concrete	Grey	Chipping	2	0	Negative
1	3	Stairwell 6	Floor	Concrete	White	None	0	0	Negative
1	3	Stairwell 6	Riser	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 6	Tread	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 6	Stringer	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 6	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 7	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 7	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 7	W3	CMU	White	Chipping	5	0	Negative
1	3	Stairwell 7	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 7	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 7	Floor	Concrete	Blue	Friction	5	0	Negative
1	3	Stairwell 7	Stringer	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 7	Tread	Metal	Blue	Friction	2	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Stairwell 7	Riser	Metal	Blue	Friction	2	0	Negative
1	3	Stairwell 7	Handrail	Metal	Purple	Friction	2	0	Negative
1	3	Stairwell 8	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 8	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 8	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 8	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 8	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 8	Floor	Concrete	Grey	Chipping	2	0	Negative
1	3	Stairwell 8	Riser	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 8	Tread	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 8	Stringer	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 8	Handrail	Metal	Grey	Chipping	2	0	Negative
1	3	Stairwell 9	W1	CMU	White	None	0	0	Negative
1	3	Stairwell 9	W2	CMU	White	None	0	0	Negative
1	3	Stairwell 9	W3	CMU	White	None	0	0	Negative
1	3	Stairwell 9	W4	CMU	White	None	0	0	Negative
1	3	Stairwell 9	Ceiling	Concrete	White	None	0	0	Negative
1	3	Stairwell 9	Floor	Concrete	Brown	Friction	2	0	Negative
1	3	Stairwell 9	Stringer	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 9	Tread	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 9	Riser	Metal	Brown	Friction	2	0	Negative
1	3	Stairwell 9	Handrail	Metal	Black	Friction	2	0	Negative
1	3	Classroom 334	Door Frame	Metal	Yellow	None	0	0	Negative
1	3	Classroom 334	W1	CMU	White	None	0	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 334	W2	CMU	White	None	0	0	Negative
1	3	Classroom 334	W3	CMU	White	None	0	0	Negative
1	3	Classroom 334	W4	CMU	White	Flaking	10	0	Negative
1	3	Classroom 334	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335	Door Frame	Metal	Purple	None	0	0	Negative
1	3	Classroom 335	W1	CMU	White	None	0	0	Negative
1	3	Classroom 335	W2	CMU	White	None	0	0	Negative
1	3	Classroom 335	W3	CMU	White	None	0	0	Negative
1	3	Classroom 335	W4	CMU	White	None	0	0	Negative
1	3	Classroom 335	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 335	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Men's Restroom 335A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Boy's Restroom 335B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 336	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 336	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 336	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 336	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 336	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 336	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 337	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 337	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 337	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 337	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 337	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 337	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage closet in Classroom 337	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 338	W1	CMU	White	None	0	0	Negative
1	3	Classroom 338	W2	CMU	White	None	0	0	Negative
1	3	Classroom 338	W3	CMU	White	Chipping	10	0	Negative
1	3	Classroom 338	W4	CMU	White	None	0	0	Negative
1	3	Classroom 338	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 338	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Storage Room inside Classroom 338	W1	CMU	White	None	0	0	Negative
1	3	Storage Room inside Classroom 338	W2	CMU	White	None	0	0	Negative
1	3	Storage Room inside Classroom 338	W3	CMU	White	None	0	0	Negative
1	3	Storage Room inside Classroom 338	W4	CMU	White	None	0	0	Negative
1	3	Storage Room inside Classroom 338	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room inside Classroom 338	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 339	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 339	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 339	W3	CMU	Blue	None	0	0	Negative
1	3	Classroom 339	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 339	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 339	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 340	W1	CMU	White	None	0	0	Negative
1	3	Classroom 340	W2	CMU	White	None	0	0	Negative
1	3	Classroom 340	W3	CMU	White	None	0	0	Negative
1	3	Classroom 340	W4	CMU	White	None	0	0	Negative
1	3	Classroom 340	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 340	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 341	W1	CMU	Blue	Flaking	15	0	Negative
1	3	Classroom 341	W2	CMU	Blue	Flaking	15	0	Negative
1	3	Classroom 341	W3	CMU	Blue	Flaking	15	0	Negative
1	3	Classroom 341	W4	CMU	Blue	Flaking	15	0	Negative
1	3	Classroom 341	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 341	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Chemical Storage Room 342	W1	CMU	White	None	0	0	Negative
1	3	Chemical Storage Room 342	W2	CMU	White	None	0	0	Negative
1	3	Chemical Storage Room 342	W3	CMU	White	None	0	0	Negative
1	3	Chemical Storage Room 342	W4	CMU	White	None	0	0	Negative
1	3	Chemical Storage Room 342	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Chemical Storage Room 342	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 342A in 342	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet 342A in 342	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet 342A in 342	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet 342A in 342	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet 342A in 342	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 342A in 342	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 342B in 342	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet 342B in 342	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet 342B in 342	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet 342B in 342	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet 342B in 342	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet 342B in 342	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet next to T343	W1	CMU	White	None	0	0	Negative
1	3	Storage Closet next to T343	W2	CMU	White	None	0	0	Negative
1	3	Storage Closet next to T343	W3	CMU	White	None	0	0	Negative
1	3	Storage Closet next to T343	W4	CMU	White	None	0	0	Negative
1	3	Storage Closet next to T343	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Closet next to T343	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 343	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 343	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 343	W3	CMU	Blue	None	0	0	Negative
1	3	Classroom 343	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 343	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 343	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 344	W1	CMU	White	None	0	0	Negative
1	3	Classroom 344	W2	CMU	White	None	0	0	Negative
1	3	Classroom 344	W3	CMU	White	Chipping	10	0	Negative
1	3	Classroom 344	W4	CMU	White	None	0	0	Negative
1	3	Classroom 344	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 344	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 345	Door Frame 1	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 345	Door Frame 2	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 345	W1	CMU	White	None	0	0	Negative
1	3	Classroom 345	W2	CMU	White	None	0	0	Negative
1	3	Classroom 345	W3	CMU	White	None	0	0	Negative
1	3	Classroom 345	W4	CMU	White	None	0	0	Negative
1	3	Classroom 345	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 345	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 345A	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 345A	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 345A	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 345A	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Girl's Restroom 345A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Girl's Restroom 345A	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Women's Restroom 345B	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	3	Custodial Closet 345C next to Women's Restroom 345B	W1	CMU	White	None	0	0	Negative
1	3	Custodial Closet 345C next to Women's Restroom 345B	W2	CMU	White	None	0	0	Negative
1	3	Custodial Closet 345C next to Women's Restroom 345B	W3	CMU	White	None	0	0	Negative
1	3	Custodial Closet 345C next to Women's Restroom 345B	W4	CMU	White	None	0	0	Negative
1	3	Custodial Closet 345C next to Women's Restroom 345B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Custodial Closet 345C next to Women's Restroom 345B	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 346	Door Frame 1	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 346	Door Frame 2	Metal	Grey	Chipping	1	0	Negative
1	3	Classroom 346	Column	Concrete	Yellow	None	0	0	Negative
1	3	Classroom 346	W1	CMU	Yellow	Chipping	150	0	Negative
1	3	Classroom 346	W2	CMU	Yellow	None	0	0	Negative
1	3	Classroom 346	W3	CMU	Yellow	None	0	0	Negative
1	3	Classroom 346	W4	CMU	Purple	None	0	0	Negative
1	3	Classroom 346	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 346	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 347	W1	CMU	Blue	Chipping	10	0	Negative

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	3	Classroom 347	W2	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 347	W3	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 347	W4	CMU	Blue	Chipping	10	0	Negative
1	3	Classroom 347	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 347	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 348	W1	CMU	White	None	0	0	Negative
1	3	Classroom 348	W2	CMU	White	Flaking	10	0	Negative
1	3	Classroom 348	W3	CMU	White	Flaking	10	0	Negative
1	3	Classroom 348	W4	CMU	White	None	0	0	Negative
1	3	Classroom 348	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 348	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 349	W1	CMU	White	None	0	0	Negative
1	3	Office 349	W2	CMU	White	None	0	0	Negative
1	3	Office 349	W3	CMU	White	None	0	0	Negative
1	3	Office 349	W4	CMU	White	None	0	0	Negative
1	3	Office 349	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Office 349	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 350	W1	CMU	Blue	None	0	0	Negative
1	3	Classroom 350	W2	CMU	Blue	None	0	0	Negative
1	3	Classroom 350	W3	CMU	Purple	None	0	0	Negative
1	3	Classroom 350	W4	CMU	Blue	None	0	0	Negative
1	3	Classroom 350	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 350	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A
1	4	Penthouse Mechanical Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/9/23-11/9/23	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erik Swanson #006917	Martin Luther King High School						
		Inspection Company: Viva EHS	6100 Stenton Ave, Philadelphia PA 19138						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/ negative) [3]
1	4	Penthouse Mechanical Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Penthouse Mechanical Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Penthouse Mechanical Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Penthouse Mechanical Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	4	Penthouse Mechanical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	4	Freight Elevator Mechanical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	4	Maintenance Elevator Mechanical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
1	AT	Auditorium Attic at Mechanical Room 374	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A