

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Small Kitchen in Rear of Auditorium	W1	Plaster	White	None	0	0.01	Negative
1	1	Small Kitchen in Rear of Auditorium	W2	Plaster	White	None	0	0.06	Negative
1	1	Small Kitchen in Rear of Auditorium	W3	Plaster	White	None	0	0.05	Negative
1	1	Small Kitchen in Rear of Auditorium	W4	Plaster	White	None	0	0.01	Negative
1	1	Small Kitchen in Rear of Auditorium	Ceiling	Plaster	White	None	0	0.01	Negative
1	1	Small Kitchen in Rear of Auditorium	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Room in Rear of Auditorium next to Vestibule	W1	Plaster	White	None	0	0.05	Negative
1	1	Room in Rear of Auditorium next to Vestibule	W2	Plaster	White	Chipping	1	0.02	Negative
1	1	Room in Rear of Auditorium next to Vestibule	W3	Plaster	White	None	0	0.04	Negative
1	1	Room in Rear of Auditorium next to Vestibule	W4	Plaster	White	None	0	0.02	Negative
1	1	Room in Rear of Auditorium next to Vestibule	Ceiling	Plaster	White	None	0	0.03	Negative
1	1	Room in Rear of Auditorium next to Vestibule	Floor	12X12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Large Storage Room next to Kitchen	W1	Plaster	White	None	0	0.34	Negative
1	1	Large Storage Room next to Kitchen	W2	Plaster	White	Alligating	10	0.26	Negative
1	1	Large Storage Room next to Kitchen	W3	Plaster	White	Chipping	15	0.4	Negative
1	1	Large Storage Room next to Kitchen	W4	Plaster	White	None	0	0.35	Negative
1	1	Large Storage Room next to Kitchen	Ceiling	Plaster	White	None	0	0.14	Negative
1	1	Large Storage Room next to Kitchen	Floor	12X12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Auditorium	W1	Plaster	White	None	0	0.03	Negative
1	1	Auditorium	W2	Plaster	White	None	0	0.03	Negative
1	1	Auditorium	W2	Plaster	Green	Chipping	5	0.1	Negative
1	1	Auditorium	W4	Plaster	White	None	0	0.09	Negative
1	1	Auditorium	W4	Plaster	Green	Chipping	15	0.04	Negative
1	1	Auditorium	Door	Metal	Brown	None	0	0	Negative
1	1	Auditorium	Door Frame	Wood	Brown	None	0	0	Negative
1	1	Auditorium	Ceiling	Plaster	White	None	0	0.09	Negative
1	1	Auditorium	Radiator Cover	Metal	Green	Chipping	16	0.24	Negative
1	1	Auditorium	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	W1	Plaster	Green	None	0	0.05	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	W2	Plaster	Green	None	0	0.07	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	W3	Plaster	Green	None	0	0.03	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	W4	Plaster	Green	None	0	0.01	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	Ceiling	Plaster	White	None	0	0.05	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	Radiator Cover	Metal	Green	None	0	0.07	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	Baseboard	Wood	White	None	0	0.03	Negative
1	1	Vice Principal Office on Landing of Stairs between 1st and 2nd Fl	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	W1	Plaster	Blue	None	0	0.01	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	W2	Plaster	Blue	None	0	0.02	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	W3	Plaster	Blue	Flaking	2	0.03	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	W4	Plaster	Blue	None	0	0.19	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	Radiator Cover	Metal	Blue	None	0	0.17	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	Baseboard	Wood	White	None	0	0.28	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	Ceiling	Plaster	White	None	0	0.03	Negative
1	1	Storage Closet in Vice Principal Office in Landing of Stairs betwee	Floor	Wood	Grey	None	0	0.29	Negative
1	1	Stage	W1	Plaster	Black	Friction	5	0.02	Negative
1	1	Stage	W2	Plaster	Black	Friction	10	0.05	Negative
1	1	Stage	W3	Wood	Black	None	0	0.27	N/A
1	1	Stage	W4	Plaster	Black	Friction	10	0.04	Negative
1	1	Stage	Ceiling	Plaster	White	None	0	0.49	Negative
1	1	Stage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stage	Stair Tread	Wood	Black	None	0	0.01	Negative
1	1	Stage	Stair Riser	Wood	Black	None	0	0.08	Negative
1	1	Women's Restroom to Right of Stage	Floor	Concrete	Grey	None	0	0.01	Negative
1	1	Women's Restroom to Right of Stage	W1	Plaster	White	None	0	0.01	Negative
1	1	Women's Restroom to Right of Stage	W2	Plaster	White	None	0	0.01	Negative
1	1	Women's Restroom to Right of Stage	W3	Plaster	White	None	0	0	Negative

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Women's Restroom to Right of Stage	W4	Plaster	White	None	0	0	Negative
1	1	Women's Restroom to Right of Stage	Ceiling	Plaster	White	None	0	0	Negative
1	1	Women's Restroom to Right of Stage	Floor	Concrete	Brown	Friction	20	0.01	Negative
1	1	Auditorium side Foyer	W1	Plaster	White	None	0	0.03	Negative
1	1	Auditorium side Foyer	W2	Plaster	White	Alligating	10	0.04	Negative
1	1	Auditorium side Foyer	W3	Plaster	White	Chipping	15	0.01	Negative
1	1	Auditorium side Foyer	W4	Plaster	White	None	0	0	Negative
1	1	Auditorium side Foyer	Ceiling	Plaster	White	None	0	0.17	Negative
1	1	Auditorium side Foyer	Floor	12X12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stage Storage Room	W1	Plaster	White	None	0	0.23	Negative
1	1	Stage Storage Room	W2	Plaster	White	Efflorescence	15	0.36	Negative
1	1	Stage Storage Room	W3	Plaster	White	None	0	0.29	Negative
1	1	Stage Storage Room	W4	Plaster	White	None	0	0.48	Negative
1	1	Stage Storage Room	Window Sill	Wood	Brown	None	0	0.03	Negative
1	1	Stage Storage Room	Window Component	Wood	Brown	None	0	4.23	Positive
1	1	Stage Storage Room	Ceiling	Plaster	White	None	0	0.14	Negative
1	1	Stage Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Men's Restroom to Left of Stage	W1	Brick	White	None	0	0.08	Negative
1	1	Men's Restroom to Left of Stage	W2	Brick	White	None	0	0.16	Negative
1	1	Men's Restroom to Left of Stage	W3	Brick	White	None	0	0.23	Negative
1	1	Men's Restroom to Left of Stage	W4	Brick	White	None	0	0.54	Negative
1	1	Men's Restroom to Left of Stage	Ceiling	Plaster	White	None	0	0.39	Negative
1	1	Men's Restroom to Left of Stage	Floor	Concrete	Green	Moisture Damage	25	0	Negative
1	1	Main Entrance	W1	Plaster	White	None	0	0.01	Negative
1	1	Main Entrance	W2	Plaster	White	None	0	0.06	Negative
1	1	Main Entrance	W3	Plaster	White	None	0	0.04	Negative
1	1	Main Entrance	W4	Plaster	White	None	0	0.03	Negative
1	1	Main Entrance	Ceiling	Plaster	White	Chipping	1	0.05	Negative

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Main Entrance	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairway between 1st and 2nd floor Stairway	Door	Metal	Brown	None	0	0.12	Negative
1	1	Stairway between 1st and 2nd floor Stairway	W1	Plaster	White	None	0	0.26	Negative
1	1	Stairway between 1st and 2nd floor Stairway	W2	Plaster	White	Moisture Damage	36	0.43	Negative
1	1	Stairway between 1st and 2nd floor Stairway	W3	Plaster	White	None	0	0.34	Negative
1	1	Stairway between 1st and 2nd floor Stairway	W4	Plaster	White	None	0	0.29	Negative
1	1	Stairway between 1st and 2nd floor Stairway	Ceiling	Wood	Brown	None	0	2.36	Positive
1	1	Stairway between 1st and 2nd floor Stairway	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	Stairway between 1st and 2nd floor Stairway	Handrail	Wood	Brown	None	0	0.34	Negative
1	1	Stairway between 1st and 2nd floor Stairway	Newel Post	Wood	Brown	None	0	0.24	Negative
1	1	Stairway between 1st and 2nd floor Stairway	Stringer	Wood	Brown	Friction	2	0.12	Negative
1	1	Stairway between 1st and 2nd floor Stairway	Spindle	Metal	Brown	None	0	0	Negative
1	1	Stairway between 1st and 2nd floor Stairway	Baseboard	Wood	Brown	None	0	1.68	Positive
1	1	Stairway between 1st and 2nd floor Stairway	Door	Wood	Brown	Friction	15	0.34	Negative
1	2	Stairs near Classroom 23	Ceiling	Plaster	White	None	0	0.06	Negative
1	2	Stairs near Classroom 23	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Stairs near Classroom 23	Handrail	Wood	Brown	None	0	0.34	Negative
1	2	Stairs near Classroom 23	Newel Post	Wood	Brown	Flaking	1	0.24	Negative
1	2	Stairs near Classroom 23	Stringer	Metal	White	None	0	0	Negative
1	2	Stairs near Classroom 23	Spindle	Wood	Brown	Friction	2	0.12	Negative
1	2	Stairs near Classroom 23	Radiator Cover	Metal	Brown	None	0	0	Negative
1	2	Stairs near Classroom 23	Baseboard	Wood	Brown	None	0	0	Negative
1	2	Stairs near Classroom 23	Door	Wood	Brown	Friction	15	0.34	Negative
1	2	Stairs near Classroom 23	Door Frame	Wood	Brown	Chipping	1	0.09	Negative
1	2	Stairs near Classroom 23	Radiator Cover	Metal	Brown	None	0	0.07	Negative
1	1	Stairway near Main Entrance	W1	Plaster	White	Chipping	1	0.19	Negative
1	1	Stairway near Main Entrance	W2	Plaster	White	None	0	0.09	Negative
1	1	Stairway near Main Entrance	W3	Plaster	White	None	0	0.4	Negative

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Stairway near Main Entrance	W4	Plaster	White	None	0	0.52	Negative
1	1	Stairway near Main Entrance	Ceiling	Plaster	White	None	0	0.46	Negative
1	1	Stairway near Main Entrance	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 222	W1	Plaster	White	None	0	0.47	Negative
1	2	Classroom 222	W2	Plaster	White	None	0	0.19	Negative
1	2	Classroom 222	W3	Plaster	White	None	0	0.21	Negative
1	2	Classroom 222	W4	Plaster	Green	Chipping	1	0.23	Negative
1	2	Classroom 222	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 222	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 222	Baseboard	Wood	Brown	None	0	0.12	Negative
1	2	Classroom 222	Radiator Cover	Metal	Brown	None	0	0.15	Negative
1	2	Classroom 222	Whiteboard Frame	Wood	White	None	0	0.16	Negative
1	2	Classroom 222	Whiteboard Frame	Wood	Green	None	0	0.35	Negative
1	2	Closet next to Classroom 21	W1	Plaster	White	Chipping	2	0.22	Negative
1	2	Closet next to Classroom 21	W2	Plaster	White	None	0	0.15	Negative
1	2	Closet next to Classroom 21	W3	Plaster	White	None	0	0.14	Negative
1	2	Closet next to Classroom 21	W4	Plaster	White	Chipping	2	0.12	Negative
1	2	Closet next to Classroom 21	Ceiling	Plaster	White	None	0	0.29	Negative
1	2	Closet next to Classroom 21	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Closet next to Classroom 21	Coatrack	Wood	White	None	0	0.21	Negative
1	2	Closet next to Classroom 21	Baseboard	Wood	Brown	None	0	0.12	Negative
1	2	Closet next to Classroom 21	Radiator Cover	Metal	White	None	0	0.08	Negative
1	2	Classroom 223	W1	Plaster	White	None	0	0.45	Negative
1	2	Classroom 223	W2	Plaster	White	None	0	0.36	Negative
1	2	Classroom 223	W3	Plaster	White	None	0	0.22	Negative
1	2	Classroom 223	W4	Plaster	Green	Chipping	4	0.21	Negative
1	2	Classroom 223	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 223	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Classroom 223	Baseboard	Wood	Brown	None	0	0.14	Negative
1	2	Classroom 223	Radiator Cover	Metal	Brown	None	0	0.1	Negative
1	2	Classroom 223	Whiteboard Frame	Wood	White	None	0	0.23	Negative
1	2	Classroom 223	Whiteboard Frame	Wood	Green	None	0	0.31	Negative
1	2	Classroom 224	W1	Plaster	White	None	0	0.43	Negative
1	2	Classroom 224	W2	Plaster	White	None	0	0.32	Negative
1	2	Classroom 224	W3	Plaster	White	None	0	0.29	Negative
1	2	Classroom 224	W4	Plaster	Green	Chipping	4	0.26	Negative
1	2	Classroom 224	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Classroom 224	Baseboard	Wood	Brown	None	0	0.18	Negative
1	2	Classroom 224	Radiator Cover	Metal	Brown	None	0	0.08	Negative
1	2	Classroom 224	Whiteboard Frame	Wood	White	None	0	0.25	Negative
1	2	Classroom 224	Whiteboard Frame	Wood	Green	None	0	0.2	Negative
1	2	Closet next to Classroom 23	W1	Plaster	White	Chipping	2	0.42	Negative
1	2	Closet next to Classroom 23	W2	Plaster	White	None	0	0.11	Negative
1	2	Closet next to Classroom 23	W3	Plaster	White	None	0	0.18	Negative
1	2	Closet next to Classroom 23	W4	Plaster	White	Chipping	2	0.21	Negative
1	2	Closet next to Classroom 23	Ceiling	Plaster	White	None	0	0.19	Negative
1	2	Closet next to Classroom 23	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Closet next to Classroom 23	Coatrack	Wood	White	None	0	0.25	Negative
1	2	Closet next to Classroom 23	Baseboard	Wood	Brown	None	0	0.19	Negative
1	2	Closet next to Classroom 23	Radiator Cover	Metal	White	None	0	0.02	Negative
1	2	Classroom 221	W1	Plaster	Green	Chipping	1	0.5	Negative
1	2	Classroom 221	W2	Plaster	White	None	0	0.25	Negative
1	2	Classroom 221	W3	Plaster	White	None	0	0.53	Negative
1	2	Classroom 221	W4	Plaster	White	Chipping	1	0.43	Negative
1	2	Classroom 221	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	<b>Lead-Safe Certification Assessment Report</b>							
		Inspector Name and Certificate Number: Zak Khalil 007233	<b>Our Lady of Pompei (Bayard Taylor Annex)</b>							
		Inspection Company: Viva EHS	<b>608 W Erie Ave, Philadelphia PA 19140</b>							
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>	
1	2	Classroom 221	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Classroom 221	Baseboard	Wood	Brown	None	0	0.31	Negative	
1	2	Classroom 221	Radiator Cover	Metal	Brown	None	0	0.08	Negative	
1	2	Classroom 221	Whiteboard Frame	Wood	White	None	0	0.15	Negative	
1	2	Classroom 221	Whiteboard Frame	Wood	Green	None	0	0.24	Negative	
1	2	Office next to Classroom 21	W1	Plaster	White	None	0	0.31	Negative	
1	2	Office next to Classroom 21	W2	Plaster	White	None	0	0.35	Negative	
1	2	Office next to Classroom 21	W3	Plaster	White	None	0	0.27	Negative	
1	2	Office next to Classroom 21	W4	Plaster	White	None	0	0.18	Negative	
1	2	Office next to Classroom 21	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	2	Office next to Classroom 21	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Office next to Classroom 21	Baseboard	Wood	Brown	Friction	5	0.09	Negative	
1	2	Office next to Classroom 21 Restroom	W1	Plaster	White	None	0	0.05	Negative	
1	2	Office next to Classroom 21 Restroom	W2	Plaster	White	None	0	0.07	Negative	
1	2	Office next to Classroom 21 Restroom	W3	Plaster	White	None	0	0.08	Negative	
1	2	Office next to Classroom 21 Restroom	W4	Plaster	White	None	0	0.07	Negative	
1	2	Office next to Classroom 21 Restroom	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A	
1	2	Office next to Classroom 21 Restroom	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A	
1	2	Girl's Restroom	W1	Plaster	White	None	0	0	Negative	
1	2	Girl's Restroom	W2	Plaster	White	Cracking	5	0	Negative	
1	2	Girl's Restroom	W3	Plaster	White	None	0	0	Negative	
1	2	Girl's Restroom	W4	Plaster	White	None	0	0	Negative	
1	2	Girl's Restroom	Ceiling	Plaster	White	None	0	0	Negative	
1	2	Girl's Restroom	Floor	Concrete	Blue	None	0	0	Negative	
1	2	Girl's Restroom	Radiator Cover	Metal	White	None	0	0.06	Negative	
1	2	Girl's Restroom	Window Sill	Wood	White	Chipping	2	0.24	Negative	
1	2	Girl's Restroom	Window Component	Wood	White	Chipping	5	4.72	Positive	
1	1	Stairway near Main Entrance	Door	Metal	Brown	Chipping	5	0.01	Negative	

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	Stairway near Main Entrance	Door Frame	Wood	Brown	None	0	3.48	Positive
1	1	Stairway near Main Entrance	Radiator Cover	Metal	Brown	Chipping	2	0.08	Negative
1	2	Hallway next to Classroom 22	Cork Board Frame	Wood	White	None	0	0.19	Negative
1	2	Hallway next to Classroom 22	Baseboard	Wood	Brown	Friction	3	0.28	Negative
1	2	Hallway next to Classroom 22	Door Frame	Wood	Brown	Friction	1	3.09	Positive
1	2	Hallway next to Classroom 22	Door	Wood	Brown	Friction	2	0	Negative
1	2	Hallway next to Classroom 22	W1	Plaster	White	None	0	0.27	Negative
1	2	Hallway next to Classroom 22	W2	Plaster	White	None	0	0.2	Negative
1	2	Hallway next to Classroom 22	W3	Plaster	White	None	0	0.19	Negative
1	2	Hallway next to Classroom 22	W4	Plaster	White	None	0	0.18	Negative
1	2	Hallway next to Classroom 22	Ceiling	Plaster	White	None	0	0.21	Negative
1	2	Hallway next to Classroom 22	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Hallway next to Classroom 22	Radiator Cover	Metal	White	None	0	0.14	Negative
1	2	Hallway next to Classroom 23	Baseboard	Wood	Brown	Friction	5	0.28	Negative
1	2	Hallway next to Classroom 23	Door Frame	Wood	Brown	Friction	15	0.31	Negative
1	2	Hallway next to Classroom 23	Door	Wood	Brown	Friction	2	0.15	Negative
1	2	Hallway next to Classroom 23	W1	Plaster	White	None	0	0.29	Negative
1	2	Hallway next to Classroom 23	W2	Plaster	White	None	0	0.24	Negative
1	2	Hallway next to Classroom 23	W3	Plaster	White	None	0	0.27	Negative
1	2	Hallway next to Classroom 23	W4	Plaster	White	None	0	0.36	Negative
1	2	Hallway next to Classroom 23	Ceiling	Plaster	White	None	0	0.1	Negative
1	2	Hallway next to Classroom 23	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	Fire Stair next near Girl's Restroom	Window Sill	Wood	White	Cracking	3	4.67	Positive
1	2	Fire Stair next near Girl's Restroom	Window Component	Metal	White	Chipping	1	0.02	Negative
1	2	Fire Stair next near Girl's Restroom	Stair Tread	Concrete	Grey	None	0	0.03	Negative
1	2	Fire Stair next near Girl's Restroom	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	2	Fire Stair next near Girl's Restroom	W1	Brick	White	None	0	0.02	Negative
1	2	Fire Stair next near Girl's Restroom	W2	Plaster	White	Chipping	3	0.06	Negative



		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	Fire Stair next near Girl's Restroom	W3	Brick	White	None	0	0.04	Negative
1	2	Fire Stair next near Girl's Restroom	W4	Plaster	White	None	0	0.05	Negative
1	2	Fire Stair next near Girl's Restroom	Ceiling	Plaster	White	None	0	0.01	Negative
1	2	Fire Stair next near Girl's Restroom	Floor	Concrete	Grey	None	0	0	Negative
1	3	Fire Stair next to Boys' Restroom	Window Frame	Wood	White	Cracking	3	4.67	Positive
1	3	Fire Stair next to Boys' Restroom	Window Component	Metal	White	Chipping	1	0.02	Negative
1	2	Stairs near Classroom 23	W1	Plaster	White	None	0	0.34	Negative
1	2	Stairs near Classroom 23	W2	Plaster	White	None	0	0.12	Negative
1	2	Stairs near Classroom 23	W3	Plaster	White	None	0	0.26	Negative
1	2	Stairs near Classroom 23	W4	Plaster	White	None	0	0.43	Negative
1	2	Stairs near Classroom 23	Ceiling	Plaster	White	None	0	0.34	Negative
1	2	Stairs near Classroom 23	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 331	W1	Plaster	White	None	0	0.18	Negative
1	3	Classroom 331	W2	Plaster	White	None	0	0.17	Negative
1	3	Classroom 331	W3	Plaster	White	None	0	0.14	Negative
1	3	Classroom 331	W4	Plaster	Blue	Chipping	2	0.12	Negative
1	3	Classroom 331	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 331	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 331	Baseboard	Wood	Brown	Friction	20	0.15	Negative
1	3	Classroom 331	Radiator Cover	Metal	Brown	None	0	0.18	Negative
1	3	Classroom 331	Whiteboard Frame	Wood	White	None	0	0.16	Negative
1	3	Classroom 331	Whiteboard Frame	Wood	Blue	None	0	0.28	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	W1	Plaster	White	None	0	0.13	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	W2	Plaster	White	None	0	0.17	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	W3	Plaster	White	Chipping	10	0.15	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	W4	Plaster	White	None	0	0.13	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	Ceiling	Plaster	White	Chipping	5	0.06	Negative
1	3	Storage Between Classroom 331 and Fire tower stairs	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 332	W1	Plaster	White	Chipping	1	0.01	Negative
1	3	Classroom 332	W2	Plaster	White	None	0	0.15	Negative
1	3	Classroom 332	W3	Plaster	White	None	0	0.13	Negative
1	3	Classroom 332	W4	Plaster	Blue	Chipping	3	0.23	Negative
1	3	Classroom 332	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 332	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 332	Baseboard	Wood	Brown	Friction	4	0	Negative
1	3	Classroom 332	Radiator Cover	Metal	Brown	None	0	0.21	Negative
1	3	Classroom 332	Whiteboard Frame	Wood	White	None	0	0.19	Negative
1	3	Classroom 332	Whiteboard Frame	Wood	Blue	None	0	0.05	Negative
1	3	Storage Room between Classrooms 331 and 332	W1	Plaster	White	None	0	0.14	Negative
1	3	Storage Room between Classrooms 331 and 332	W2	Plaster	White	None	0	0.19	Negative
1	3	Storage Room between Classrooms 331 and 332	W3	Plaster	White	None	0	0.09	Negative
1	3	Storage Room between Classrooms 331 and 332	W4	Plaster	White	None	0	0.08	Negative
1	3	Storage Room between Classrooms 331 and 332	Ceiling	Plaster	White	None	0	0.21	Negative
1	3	Storage Room between Classrooms 331 and 332	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Storage Room between Classrooms 331 and 332	Coatrack	Wood	White	None	0	0.21	Negative
1	3	Storage Room between Classrooms 331 and 332	Baseboard	Wood	Brown	None	0	0.23	Negative
1	3	Classroom 333	W1	Plaster	White	Chipping	1	0.01	Negative
1	3	Classroom 333	W2	Plaster	White	None	0	0.15	Negative
1	3	Classroom 333	W3	Plaster	White	None	0	0.13	Negative
1	3	Classroom 333	W4	Plaster	Blue	Chipping	3	0.23	Negative
1	3	Classroom 333	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 333	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 333	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Classroom 333	Radiator Cover	Metal	Brown	None	0	0.21	Negative
1	3	Classroom 333	Whiteboard Frame	Wood	White	None	0	0.19	Negative
1	3	Classroom 333	Whiteboard Frame	Wood	Blue	None	0	0.05	Negative

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Classroom 334	W1	Plaster	White	None	0	0.13	Negative
1	3	Classroom 334	W2	Plaster	White	None	0	0.12	Negative
1	3	Classroom 334	W3	Plaster	White	None	0	0.1	Negative
1	3	Classroom 334	W4	Plaster	Blue	Chipping	2	0.11	Negative
1	3	Classroom 334	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Classroom 334	Baseboard	Wood	Brown	Friction	20	0.01	Negative
1	3	Classroom 334	Radiator Cover	Metal	Brown	None	0	0.1	Negative
1	3	Classroom 334	Whiteboard Frame	Wood	White	None	0	0.13	Negative
1	3	Classroom 334	Whiteboard Frame	Wood	Blue	None	0	0.21	Negative
1	3	Boy's Restroom next to Classroom 31	W1	Plaster	White	None	0	0	Negative
1	3	Boy's Restroom next to Classroom 31	W2	Plaster	White	Chipping	2	0	Negative
1	3	Boy's Restroom next to Classroom 31	W3	Plaster	White	Cracking	5	0	Negative
1	3	Boy's Restroom next to Classroom 31	W4	Plaster	White	None	0	0	Negative
1	3	Boy's Restroom next to Classroom 31	Ceiling	Plaster	White	None	0	0	Negative
1	3	Boy's Restroom next to Classroom 31	Floor	Concrete	Blue	None	0	0	Negative
1	3	Boy's Restroom next to Classroom 31	Radiator Cover	Metal	White	None	0	0.01	Negative
1	3	Boy's Restroom next to Classroom 31	Window Component	Wood	White	Cracking	8	3.46	Positive
1	3	Hallway next to Classroom 32	Baseboard	Wood	Brown	Friction	10	0	Negative
1	3	Hallway next to Classroom 32	Door	Wood	Brown	Friction	10	0.34	Negative
1	3	Hallway next to Classroom 32	Door Frame	Wood	Brown	Friction	5	0.13	Negative
1	3	Hallway next to Classroom 32	Radiator Cover	Metal	White	None	0	0.15	Negative
1	3	Hallway next to Classroom 32	W1	Plaster	White	None	0	0.4	Negative
1	3	Hallway next to Classroom 32	W2	Plaster	White	None	0	0.26	Negative
1	3	Hallway next to Classroom 32	W3	Plaster	White	None	0	0.42	Negative
1	3	Hallway next to Classroom 32	W4	Plaster	White	None	0	0.5	Negative
1	3	Hallway next to Classroom 32	Ceiling	Plaster	White	None	0	0.23	Negative
1	3	Hallway next to Classroom 32	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
E l e m e n t	F l o o r	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Hallway next to Classroom 33	Baseboard	Wood	Brown	None	0	0	Negative
1	3	Hallway next to Classroom 33	Door	Wood	Brown	None	0	0.05	Negative
1	3	Hallway next to Classroom 33	Door Frame	Wood	Brown	Friction	3	0.15	Negative
1	3	Hallway next to Classroom 33	Radiator Cover	Metal	White	None	0	0.08	Negative
1	3	Hallway next to Classroom 33	W1	Plaster	White	None	0	0.15	Negative
1	3	Hallway next to Classroom 33	W2	Plaster	White	None	0	0.21	Negative
1	3	Hallway next to Classroom 33	W3	Plaster	White	None	0	0.28	Negative
1	3	Hallway next to Classroom 33	W4	Plaster	White	None	0	0.2	Negative
1	3	Hallway next to Classroom 33	Ceiling	Plaster	White	None	0	0.03	Negative
1	3	Hallway next to Classroom 33	Floor	Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	Fire Stair next to Boys' Restroom	Stair Tread	Concrete	Grey	None	0	0.08	Negative
1	3	Fire Stair next to Boys' Restroom	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	3	Fire Stair next to Boys' Restroom	W1	Brick	White	None	0	0.02	Negative
1	3	Fire Stair next to Boys' Restroom	W2	Plaster	White	None	0	0.06	Negative
1	3	Fire Stair next to Boys' Restroom	W3	Brick	White	Chipping	5	0.04	Negative
1	3	Fire Stair next to Boys' Restroom	W4	Plaster	White	None	0	0.05	Negative
1	3	Fire Stair next to Boys' Restroom	Ceiling	Plaster	White	None	0	0.01	Negative
1	3	Fire Stair next to Boys' Restroom	Floor	Concrete	Grey	None	0	0	Negative
1	3	Stairs near Classroom 34	Newel Post	Wood	Brown	Friction	5	0.25	Negative
1	3	Stairs near Classroom 34	Stringer	Wood	Brown	None	0	0.31	Negative
1	3	Stairs near Classroom 34	Spindle	Wood	Brown	None	0	0.01	Negative
1	3	Stairs near Classroom 34	Radiator Cover	Metal	Brown	Chipping	5	0.12	Negative
1	3	Stairs near Classroom 34	Baseboard	Wood	Brown	Friction	5	0.06	Negative
1	3	Stairs near Classroom 34	Door	Metal	Brown	None	0	0	Negative
1	3	Stairs near Classroom 34	Door Frame	Wood	Brown	None	0	1.35	Positive
1	3	Stairs near Classroom 34	Handrail	Wood	Brown	Friction	15	0.22	Negative
1	3	Stairs near Classroom 34	W1	Plaster	White	None	0	0.34	Negative
1	3	Stairs near Classroom 34	W2	Plaster	White	None	0	0.46	Negative

		Dates: 10/31/2023 - 11/15/2023	Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Zak Khalil 007233	Our Lady of Pompei (Bayard Taylor Annex)						
		Inspection Company: Viva EHS	608 W Erie Ave, Philadelphia PA 19140						
Element	Floor	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	Stairs near Classroom 34	W3	Plaster	White	None	0	0.4	Negative
1	3	Stairs near Classroom 34	W4	Plaster	White	None	0	0.38	Negative
1	3	Stairs near Classroom 34	Ceiling	Plaster	White	None	0	0.08	Negative
1	3	Stairs near Classroom 34	Floor	12x12 floor tile	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	Attic	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	Building Engineer's Office	W1	Plaster	White	None	0	0	Negative
1	B	Building Engineer's Office	W2	Plaster	White	None	0	0	Negative
1	B	Building Engineer's Office	W3	CMU	White	None	0	0	Negative
1	B	Building Engineer's Office	W3	CMU	White	None	0	0	Negative
1	B	Building Engineer's Office	W4	Plaster	White	None	0	0	Negative
1	B	Building Engineer's Office	Ceiling	Plaster	White	None	0	0	Negative
1	B	Building Engineer's Office	Floor	Concrete	Grey	Chipping	20	0.01	Negative
1	B	Building Engineer's Office	Floor	Concrete	Brown	None	0	0.03	Negative
1	B	Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
1	B	Boiler Room	W1	CMU	White	None	0	0	Negative
1	B	Boiler Room	W2	Plaster	White	Efflorescence	50	0	Negative
1	B	Boiler Room	W3	Plaster	White	Efflorescence	50	0	Negative
1	B	Boiler Room	W4	Plaster	White	None	0	0	Negative
1	B	Boiler Room	Ceiling	Plaster	White	Chipping	10	0	Negative
1	B	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	Crawl Space below Auditorium Stage	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	C	Crawl Space below Auditorium Stage	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	C	Crawl Space below Auditorium Stage	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

		Dates: 10/31/2023 - 11/15/2023	<b>Lead-Safe Certification Assessment Report</b>						
		Inspector Name and Certificate Number: Zak Khalil 007233	<b>Our Lady of Pompei (Bayard Taylor Annex)</b>						
		Inspection Company: Viva EHS	<b>608 W Erie Ave, Philadelphia PA 19140</b>						
<b>E l e m e n t</b>	<b>F l o o r</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material [1]</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf) [2]</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/negative) [3]</b>
1	C	Crawl Space below Auditorium Stage	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	C	Crawl Space below Auditorium Stage	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	C	Crawl Space below Auditorium Stage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A