

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	W1	Brick	White	Flaking	40	5.8	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	W2	Brick	White	Flaking	40	4.3	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	W3	Brick	White	Flaking	40	3.5	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	W4	Brick	White	Flaking	40	7.1	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Ceiling	Concrete	White	Flaking	10	2.8	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Window Frame	Metal	Brown	Chipping	1	5	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Handrail	Metal	Brown	Chipping	10	2.3	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Pipe	Metal	Grey	Chipping	12	1	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Stringer	Concrete	Grey	Chipping	12	1.6	Positive
1	1	S15	Stairs, Fire Tower	Stairwell adjacent to Classroom 111	Tread	Concrete	Grey	Chipping	12	0.4	Negative
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Floor	Concrete	Grey	None	0	0	Negative
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Stringer	Concrete	Grey	Chipping	2	2.8	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Tread	Concrete	Grey	Chipping	2	2.2	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Handrail	Concrete	Grey	Chipping	2	1.6	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Baluster	Concrete	Grey	Chipping	2	3.5	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Newel Post	Concrete	Grey	Chipping	2	2.7	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	W1	Plaster	White	None	0	15	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	W2	Plaster	White	None	0	11.7	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	W3	Plaster	White	None	0	14.8	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	W4	Plaster	White	Chipping	3	16.3	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Ceiling	Plaster	White	Flaking	1	18.5	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Stair Soffit	Metal	Grey	Chipping	2	2.8	Positive
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	W1	Terracotta	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	W2	Terracotta	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	W3	Terracotta	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	W4	Terracotta	N/A	N/A	N/A	N/A	N/A
1	1	FT1	Circulation (Hallway)	1st Floor Hallway to Fire Tower Stairwell	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	100	Intermediate/Middle	Classroom 100 Music	Floor	Wood	N/A	None	0	0	Negative
1	1	100	Intermediate/Middle	Classroom 100 Music	W1	Plaster	Brown	Efflorescence	12	16.1	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	W1	Concrete	Brown	None	0	0.04	Negative
1	1	100	Intermediate/Middle	Classroom 100 Music	Door Frame	Metal	Brown	Chipping	2	0.17	Negative
1	1	100	Intermediate/Middle	Classroom 100 Music	W2	Plaster	Brown	Flaking	3	13.7	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	W3	Plaster	Brown	Flaking	18	13.1	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	Radiators	Metal	Silver	Chipping	12	10.1	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	W4	Plaster	Brown	Flaking	11	16.9	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	Ceiling	Plaster	White	Flaking	20	12.2	Positive
1	1	100	Intermediate/Middle	Classroom 100 Music	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	W1	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	W2	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	W3	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	W4	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	Door Frame	Metal	Brown	Chipping	1	0.23	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	100-1	Intermediate/Middle	Classroom 100 Music Rear Storage Room Left	Radiator	Metal	Tan	None	0	0.02	Negative
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	W1	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	Door Frame	Metal	Brown	Chipping	1	0.11	Negative
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	W2	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	W3	Plaster	White	Flaking	6	13.8	Positive
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	Radiator	Metal	Tan	None	0	0	Negative
1	1	100-2	Intermediate/Middle	Classroom 100 Music Rear Storage Room Right	W4	Acoustical Wall Tile	White	None	0	0	Negative
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	W1	CMU	White	Flaking	80	4.2	Positive
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	W2	CMU	White	Flaking	120	5.4	Positive
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	W3	CMU	White	Flaking	80	5.1	Positive
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	W4	CMU	White	Flaking	120	3.9	Positive
1	1	100B	Lockers - Male	Boys Gym Locker Room #1	Ceiling	Concrete	White	Flaking	100	8.2	Positive
1	1	101	Intermediate/Middle	Classroom 101	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	101	Intermediate/Middle	Classroom 101	W1	Plaster	Blue	Partially Inaccessible	1	15.6	Positive
1	1	101	Intermediate/Middle	Classroom 101	W2	Plaster	Blue	Partially Inaccessible	0	17.7	Positive
1	1	101	Intermediate/Middle	Classroom 101	W3	Plaster	Blue	Flaking	8	15.4	Positive
1	1	101	Intermediate/Middle	Classroom 101	W4	Plaster	Blue	None	0	16.5	Positive
1	1	101	Intermediate/Middle	Classroom 101	Ceiling	Plaster	White	Flaking	20	11.9	Positive
1	1	101	Intermediate/Middle	Classroom 101	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	101	Intermediate/Middle	Classroom 101	Chalkboard Frame	Wood	Brown	Chipping	2	0.05	Negative
1	1	101	Intermediate/Middle	Classroom 101	Closet Door	Wood	Brown	None	0	0	Negative
1	1	101	Intermediate/Middle	Classroom 101	Vent	Metal	White	Flaking	1	19.3	Positive
1	1	101	Intermediate/Middle	Classroom 101	Baseboard	Wood	Brown	Partially Inaccessible	0	0.03	Negative
1	1	101	Intermediate/Middle	Classroom 101	Chalkboard Ledge	Wood	Brown	Chipping	1	0.05	Negative
1	1	101	Intermediate/Middle	Classroom 101	Window Sill	Wood	Brown	Chipping	1	0.11	Negative
1	1	101	Intermediate/Middle	Classroom 101	Window Apron	Wood	Brown	None	0	0.08	Negative
1	1	101	Intermediate/Middle	Classroom 101	Pipe	Metal	White	Flaking	2	18.2	Positive
1	1	101	Intermediate/Middle	Classroom 101	Chalkboard Ledge	Wood	Brown	Chipping	1	0	Negative
1	1	101	Intermediate/Middle	Classroom 101	Chalkboard Frame	Wood	Brown	None	0	0.04	Negative
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	W1	CMU	White	Flaking	80	4.2	Positive
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	W2	CMU	White	Flaking	120	5.4	Positive
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	W3	CMU	White	Flaking	80	5.1	Positive
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	W4	CMU	White	Flaking	120	3.9	Positive
1	1	101A	Lockers - Male	Boys Gym Locker Room #2	Ceiling	Concrete	White	Flaking	100	8.2	Positive
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Concrete	Grey	Chipping	1	0.03	Negative
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Brick	Grey	None	0	0.01	Negative
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Plaster	White	Efflorescence	9	6.1	Positive
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	Door Frame	Metal	Brown	None	0	0	Negative
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Plaster	White	Efflorescence	13	10.9	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Plaster	White	Efflorescence	10	9.8	Positive
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Plaster	White	Efflorescence	45	3.7	Positive
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	Panel	Transite	White	None	0	0	Negative
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	Pipe	Metal	Grey	Cracking	3	0.08	Negative
1	1	101B	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Plaster	White	Efflorescence	20	9.5	Positive
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	W1	CMU	White	Flaking	60	4.2	Positive
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	W2	CMU	White	Flaking	80	5.4	Positive
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	W3	CMU	White	Flaking	60	5.1	Positive
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	W4	CMU	White	Flaking	80	3.9	Positive
1	1	101C	Lockers - Male	Boys Gym Locker Room Shower	Ceiling	Concrete	White	Flaking	40	8.2	Positive
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Boys Bathroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	W1	Plaster	White	Cracking	10	8.1	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	W2	Plaster	White	Cracking	14	11.5	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	W3	Plaster	White	Cracking	21	6.1	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	W4	Plaster	White	Cracking	27	9.3	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Ceiling	Plaster	White	Efflorescence	8	10.4	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Floor	Concrete	Blue	Chipping	16	0.08	Negative
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Pipe	Metal	White	None	0	0.04	Negative
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Sink	Porcelain	Grey	Flaking	1	7.2	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Sink	Porcelain	White	Flaking	2	4.4	Positive
1	1	101E	Service Closets	Service Closet Adjacent to Boys Restroom	Baseboard	Concrete	Blue	Flaking	1	0.9	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	102	Academic Classroom (SGI)	Classroom 102	W1	Plaster	White	Efflorescence	12	14.8	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	W2	Plaster	White	Flaking	1	11.4	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	W3	Plaster	White	Flaking	2	19.1	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Window Sill	Wood	Brown	Chipping	1	0.07	Negative
1	1	102	Academic Classroom (SGI)	Classroom 102	Window Apron	Wood	Brown	None	0	0.06	Negative
1	1	102	Academic Classroom (SGI)	Classroom 102	Trench Plate	Metal	Brown	None	0	2.4	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Radiator	Metal	Silver	Chipping	6	4.7	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Trench Plate	Metal	Brown	Chipping	3	1.2	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	W4	Plaster	White	Partially Inaccessible	0	18.4	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Ceiling	Plaster	White	Flaking	360	20.4	Positive
1	1	102	Academic Classroom (SGI)	Classroom 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103	Academic Classroom (SGI)	Classroom 103	Floor	Wood	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	103	Academic Classroom (SGI)	Classroom 103	W1	Brick	Brown	Chipping	4	3.3	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	W1	Brick	Tan	None	0	0	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	Pipe	Metal	White	Chipping	1	0.02	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	Closet Door	Wood	Brown	None	0	0	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	Bulletin Board Frame	Wood	White	Chipping	1	0	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	W2	Brick	Brown	None	0	2.9	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	Electric Panel	Metal	White	None	0	0.03	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	W3	Brick	Brown	Chipping	4	2.1	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	Pipe	Metal	White	Flaking	1	0.13	Negative
1	1	103	Academic Classroom (SGI)	Classroom 103	Trench Plate	Metal	Brown	None	0	1.7	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	Radiator	Metal	Silver	Chipping	2	3.5	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	W4	Brick	Brown	Chipping	1	3.4	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	Ceiling	Plaster	White	Flaking	25	10.5	Positive
1	1	103	Academic Classroom (SGI)	Classroom 103	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	103A	Restrooms, Staff - Male	Men's Restroom	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	103A	Restrooms, Staff - Male	Men's Restroom	W1	Plaster	White	Flaking	10	14.2	Positive
1	1	103A	Restrooms, Staff - Male	Men's Restroom	W2	Plaster	White	Flaking	10	18.3	Positive
1	1	103A	Restrooms, Staff - Male	Men's Restroom	W3	Plaster	White	Flaking	2	16.8	Positive
1	1	103A	Restrooms, Staff - Male	Men's Restroom	W4	Plaster	White	Flaking	2	12.4	Positive
1	1	103A	Restrooms, Staff - Male	Men's Restroom	Ceiling	Plaster	White	Flaking	30	15.1	Positive
1	1	104	Intermediate/Middle	Classroom 104	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104	Intermediate/Middle	Classroom 104	W1	Plaster	White	Partially Inaccessible	0	15.1	Positive
1	1	104	Intermediate/Middle	Classroom 104	W1	CMU	White	None	0	0	Negative
1	1	104	Intermediate/Middle	Classroom 104	W2	Plaster	White	Partially Inaccessible	0	16.2	Positive
1	1	104	Intermediate/Middle	Classroom 104	W3	Plaster	White	Partially Inaccessible	0	12.8	Positive
1	1	104	Intermediate/Middle	Classroom 104	W4	Plaster	White	Partially Inaccessible	0	14.2	Positive
1	1	104	Intermediate/Middle	Classroom 104	Ceiling	Plaster	White	Flaking	20	11.1	Positive
1	1	104	Intermediate/Middle	Classroom 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	Intermediate/Middle	Classroom 104B	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	104B	Intermediate/Middle	Classroom 104B	W1	Plaster	White	Partially Inaccessible	0	17.2	Positive
1	1	104B	Intermediate/Middle	Classroom 104B	W2	Plaster	White	Partially Inaccessible	0	19.3	Positive
1	1	104B	Intermediate/Middle	Classroom 104B	W3	Plaster	White	Partially Inaccessible	0	16.2	Positive
1	1	104B	Intermediate/Middle	Classroom 104B	W4	Plaster	White	Partially Inaccessible	0	16.1	Positive
1	1	104B	Intermediate/Middle	Classroom 104B	Ceiling	Plaster	White	Flaking	20	10.8	Positive
1	1	104B	Intermediate/Middle	Classroom 104B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105	Intermediate/Middle	Classroom 105	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	105	Intermediate/Middle	Classroom 105	W1	Brick	White	Partially Inaccessible	8	5.7	Positive
1	1	105	Intermediate/Middle	Classroom 105	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	105	Intermediate/Middle	Classroom 105	Chalkboard Ledge	Wood	Brown	Chipping	2	0.08	Negative
1	1	105	Intermediate/Middle	Classroom 105	Closet Door	Wood	Brown	None	0	0	Negative
1	1	105	Intermediate/Middle	Classroom 105	Pipe	Metal	Brown	None	0	0.26	Negative
1	1	105	Intermediate/Middle	Classroom 105	Pipe	Metal	White	None	0	0.04	Negative
1	1	105	Intermediate/Middle	Classroom 105	W2	Brick	White	Partially Inaccessible	1	1.8	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	105	Intermediate/Middle	Classroom 105	Chalkboard Ledge	Wood	Brown	Chipping	4	0.01	Negative
1	1	105	Intermediate/Middle	Classroom 105	W3	Brick	White	Chipping	1	2.4	Positive
1	1	105	Intermediate/Middle	Classroom 105	W3	Brick	Tan	None	0	0	Negative
1	1	105	Intermediate/Middle	Classroom 105	Pipe	Metal	Brown	Chipping	7	0.07	Negative
1	1	105	Intermediate/Middle	Classroom 105	Radiator	Metal	Silver	Chipping	2	5.1	Positive
1	1	105	Intermediate/Middle	Classroom 105	Trench Plate	Metal	Brown	Flaking	20	2.2	Positive
1	1	105	Intermediate/Middle	Classroom 105	W4	Brick	White	Chipping	3	3	Positive
1	1	105	Intermediate/Middle	Classroom 105	W4	Concrete	White	Partially Inaccessible	3	0.16	Negative
1	1	105	Intermediate/Middle	Classroom 105	Ceiling	Plaster	White	Flaking	20	18.7	Positive
1	1	105	Intermediate/Middle	Classroom 105	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	105B	Storage	Classroom 105 Closet	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105B	Storage	Classroom 105 Closet	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105B	Storage	Classroom 105 Closet	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105B	Storage	Classroom 105 Closet	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105B	Storage	Classroom 105 Closet	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105B	Storage	Classroom 105 Closet	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	105A	Restrooms, Staff - Female	Women's Restroom	W1	Brick	White	None	0	0.11	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Door Frame	Wood	Brown	None	0	0.06	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	W2	Brick	White	Flaking	2	0.05	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Electric Panel	Metal	White	Chipping	1	5.7	Positive
1	1	105A	Restrooms, Staff - Female	Women's Restroom	W3	Brick	White	Partially Inaccessible	2	0.03	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	W4	Brick	White	Efflorescence	1	0.2	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Pipe	Metal	White	Flaking	1	0.18	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Pipe	Metal	White	Flaking	2	0.05	Negative
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Radiator	Metal	Silver	None	0	3.2	Positive
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Ceiling	Concrete	White	None	0	9.4	Positive
1	1	105A	Restrooms, Staff - Female	Women's Restroom	Ceiling	Plaster	White	Efflorescence	2	9.9	Positive
1	1	106	Intermediate/Middle	Classroom 106	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	106	Intermediate/Middle	Classroom 106	W1	Plaster	White	None	0	18.3	Positive
1	1	106	Intermediate/Middle	Classroom 106	Vent	Metal	White	Flaking	1	22.6	Positive
1	1	106	Intermediate/Middle	Classroom 106	W2	Plaster	White	None	0	20	Positive
1	1	106	Intermediate/Middle	Classroom 106	W3	Sheetrock	White	None	0	0	Negative
1	1	106	Intermediate/Middle	Classroom 106	W3	Plaster	Tan	Cracking	1	19.2	Positive
1	1	106	Intermediate/Middle	Classroom 106	Door Frame	Metal	Brown	None	0	0	Negative
1	1	106	Intermediate/Middle	Classroom 106	Radiator	Metal	Silver	Chipping	2	3.5	Positive
1	1	106	Intermediate/Middle	Classroom 106	W4	Plaster	White	None	0	18.4	Positive
1	1	106	Intermediate/Middle	Classroom 106	Ceiling	Plaster	White	Flaking	20	9.8	Positive
1	1	106	Intermediate/Middle	Classroom 106	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	106B	Storage	Classroom 106 Closet	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	106B	Storage	Classroom 106 Closet	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	1	106B	Storage	Classroom 106 Closet	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	1	106B	Storage	Classroom 106 Closet	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	1	106B	Storage	Classroom 106 Closet	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	1	106B	Storage	Classroom 106 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	107	Intermediate/Middle	Classroom 107	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	107	Intermediate/Middle	Classroom 107	W1	Plaster	Yellow	None	0	23.6	Positive
1	1	107	Intermediate/Middle	Classroom 107	W2	Sheetrock	Yellow	None	0	0	Negative
1	1	107	Intermediate/Middle	Classroom 107	W3	Plaster	Yellow	None	0	20.7	Positive
1	1	107	Intermediate/Middle	Classroom 107	Radiators	Metal	Silver	Flaking	2	3.9	Positive
1	1	107	Intermediate/Middle	Classroom 107	W4	Plaster	Yellow	None	0	18.1	Positive
1	1	107	Intermediate/Middle	Classroom 107	Ceiling	Plaster	White	Flaking	20	7.6	Positive
1	1	107	Intermediate/Middle	Classroom 107	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	107B	Storage	Classroom 107 Closet	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107B	Storage	Classroom 107 Closet	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107B	Storage	Classroom 107 Closet	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107B	Storage	Classroom 107 Closet	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107B	Storage	Classroom 107 Closet	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107B	Storage	Classroom 107 Closet	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	1	107A	Storage	Storage Room 108	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	1	ARTS	Storage	Storage Room 108 Closet	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	1	109	Intermediate/Middle	Classroom 109	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	109	Intermediate/Middle	Classroom 109	W1	Plaster	Brown	None	0	18.1	Positive
1	1	109	Intermediate/Middle	Classroom 109	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	109	Intermediate/Middle	Classroom 109	W2	Plaster	Brown	Chipping	1	19.4	Positive
1	1	109	Intermediate/Middle	Classroom 109	W3	Plaster	Yellow	None	0	23.5	Positive
1	1	109	Intermediate/Middle	Classroom 109	Radiator	Metal	Silver	Flaking	4	2.6	Positive
1	1	109	Intermediate/Middle	Classroom 109	W4	Plaster	Brown	Partially Inaccessible	0	22.1	Positive
1	1	109	Intermediate/Middle	Classroom 109	Ceiling	Plaster	White	Flaking	20	11.9	Positive
1	1	109	Intermediate/Middle	Classroom 109	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Intermediate/Middle	Classroom 109A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109A	Intermediate/Middle	Classroom 109A	Baseboard	Concrete	Brown	None	0	0	Negative
1	1	109A	Intermediate/Middle	Classroom 109A	W1	Plaster	White	Cracking	2	19	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	109A	Intermediate/Middle	Classroom 109A	Pipe	Metal	White	Flaking	1	0.03	Negative
1	1	109A	Intermediate/Middle	Classroom 109A	W2	Plaster	White	Flaking	1	15	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	W3	Plaster	White	Cracking	8	16.4	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	Radiators	Metal	Silver	Chipping	12	3.8	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	Pipe	Metal	White	Flaking	2	0.4	Negative
1	1	109A	Intermediate/Middle	Classroom 109A	Window Sill	Wood	Brown	Chipping	1	0.07	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	109A	Intermediate/Middle	Classroom 109A	Window Apron	Wood	Brown	None	0	0.06	Negative
1	1	109A	Intermediate/Middle	Classroom 109A	W4	Plaster	White	None	0	16.3	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	Ceiling	Plaster	White	Flaking	30	11.5	Positive
1	1	109A	Intermediate/Middle	Classroom 109A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	Floor	No Access	No Access	N/A	N/A	N/A	N/A
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109PS	Pipe Shaft	Pipe Shaft in Classroom 109A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	W1	CMU	White	Flaking	60	4.2	Positive
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	W2	CMU	White	Flaking	80	5.4	Positive
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	W3	CMU	White	Flaking	60	5.1	Positive
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	W4	CMU	White	Flaking	80	3.9	Positive
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	Ceiling	Concrete	White	Flaking	40	8.2	Positive
1	1	101D	Lockers - Male	Boys' Gym Locker Room Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	W1	CMU	White	Flaking	80	5.2	Positive
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	W2	CMU	White	Flaking	120	4.5	Positive
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	W3	CMU	White	Flaking	80	4.3	Positive
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	W4	CMU	White	Flaking	120	6.4	Positive
1	1	110A	Lockers - Female	Girls Gym Locker Room #1	Ceiling	Concrete	White	Flaking	100	5.9	Positive
1	1	110	Intermediate/Middle	Classroom 110	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	110	Intermediate/Middle	Classroom 110	W1	Plaster	Brown	Chipping	1	16.1	Positive
1	1	110	Intermediate/Middle	Classroom 110	Vent	Metal	White	None	0	23.6	Positive
1	1	110	Intermediate/Middle	Classroom 110	W2	Plaster	Brown	Chipping	1	13.5	Positive
1	1	110	Intermediate/Middle	Classroom 110	W3	Plaster	Brown	Chipping	1	13.9	Positive
1	1	110	Intermediate/Middle	Classroom 110	Radiators	Metal	Silver	Chipping	3	2.1	Positive
1	1	110	Intermediate/Middle	Classroom 110	W4	Plaster	Brown	Chipping	1	13.6	Positive
1	1	110	Intermediate/Middle	Classroom 110	Ceiling	Plaster	White	Flaking	20	15.8	Positive
1	1	110	Intermediate/Middle	Classroom 110	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111	Intermediate/Middle	Classroom 111	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	111	Intermediate/Middle	Classroom 111	W1	Plaster	White	None	0	20.6	Positive
1	1	111	Intermediate/Middle	Classroom 111	Chalkboard Frame	Wood	Brown	Chipping	8	0.03	Negative
1	1	111	Intermediate/Middle	Classroom 111	Chalkboard Ledge	Wood	Brown	Chipping	1	0.04	Negative
1	1	111	Intermediate/Middle	Classroom 111	W2	Plaster	White	Partially Inaccessible	2	17	Positive
1	1	111	Intermediate/Middle	Classroom 111	Chalkboard Ledge	Wood	Brown	Chipping	2	0.14	Negative
1	1	111	Intermediate/Middle	Classroom 111	W3	Plaster	White	Cracking	2	21.1	Positive
1	1	111	Intermediate/Middle	Classroom 111	Window Sill	Wood	Brown	Chipping	2	0.06	Negative
1	1	111	Intermediate/Middle	Classroom 111	Window Apron	Wood	Brown	None	0	0.05	Negative
1	1	111	Intermediate/Middle	Classroom 111	Radiators	Metal	Silver	Chipping	2	1.3	Positive
1	1	111	Intermediate/Middle	Classroom 111	W4	Plaster	White	None	0	18.1	Positive

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	111	Intermediate/Middle	Classroom 111	Chalkboard Ledge	Wood	Brown	Partially Inaccessible	1	0.03	Negative
1	1	111	Intermediate/Middle	Classroom 111	Ceiling	Plaster	White	Flaking	100	17.6	Positive
1	1	111	Intermediate/Middle	Classroom 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	111A	Restroom	Girl's Restroom	Floor	Concrete	Grey	None	0	0.01	Negative
1	1	111A	Restroom	Girl's Restroom	W1	Plaster	White	Cracking	1	8.2	Positive
1	1	111A	Restroom	Girl's Restroom	W1	Brick	Gray	None	0	0.01	Negative
1	1	111A	Restroom	Girl's Restroom	Door Frame	Wood	Brown	None	0	0	Negative
1	1	111A	Restroom	Girl's Restroom	W2	Plaster	White	Chipping	4	8.7	Positive
1	1	111A	Restroom	Girl's Restroom	Pipe	Metal	Grey	None	0	0.02	Negative
1	1	111A	Restroom	Girl's Restroom	W3	Plaster	White	Flaking	3	9.2	Positive
1	1	111A	Restroom	Girl's Restroom	Window Sill	Wood	Grey	None	0	0.01	Negative
1	1	111A	Restroom	Girl's Restroom	Window Apron	Wood	Grey	None	0	0.01	Negative
1	1	111A	Restroom	Girl's Restroom	Radiator	Metal	Grey	Chipping	1	1	Positive
1	1	111A	Restroom	Girl's Restroom	W4	Plaster	White	Efflorescence	12	3.1	Positive
1	1	111A	Restroom	Girl's Restroom	Stall Partition	Wood	Grey	None	0	0	Negative
1	1	111A	Restroom	Girl's Restroom	Ceiling	Plaster	White	Efflorescence	25	4.1	Positive
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	W1	CMU	White	Flaking	80	5.2	Positive
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	W2	CMU	White	Flaking	120	4.5	Positive
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	W3	CMU	White	Flaking	80	4.3	Positive
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	W4	CMU	White	Flaking	120	6.4	Positive
1	1	111B	Lockers - Female	Girls Gym Locker Room #2	Ceiling	Concrete	White	Flaking	100	5.9	Positive
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	W1	CMU	White	Flaking	60	5.2	Positive
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	W2	CMU	White	Flaking	80	4.5	Positive
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	W3	CMU	White	Flaking	60	4.3	Positive
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	W4	CMU	White	Flaking	80	6.4	Positive
1	1	111C	Ident Restrooms - Female (4-	Girl's Restroom in Girls Gym Locker Room	Ceiling	Concrete	White	Flaking	40	5.9	Positive
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	111PC	Pipe Chase	Service Closet Pipe Chase Adjacent to the Girls Restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	113	Storage	Women's Restroom 113	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	113	Storage	Women's Restroom 113	W1	Plaster	White	Cracking	3	12.1	Positive
1	1	113	Storage	Women's Restroom 113	W2	Plaster	White	Efflorescence	3	7.8	Positive
1	1	113	Storage	Women's Restroom 113	W3	Plaster	White	Flaking	1	12	Positive
1	1	113	Storage	Women's Restroom 113	W4	Plaster	White	Cracking	1	8.9	Positive
1	1	113	Storage	Women's Restroom 113	Ceiling	Plaster	White	None	0	10.9	Positive

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Dates: 08/31/2022						
					Inspector Name and Certificate Number: Ryan Hutsell 059512						
					Inspection Company: Synertech						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	114	Administrative Office	Security Office 114	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114	Administrative Office	Security Office 114	W1	Plaster	White	Efflorescence	6	14.7	Positive
1	1	114	Administrative Office	Security Office 114	W2	Plaster	White	Cracking	3	18.3	Positive
1	1	114	Administrative Office	Security Office 114	W3	Plaster	White	Partially Inaccessible	8	17.7	Positive
1	1	114	Administrative Office	Security Office 114	W4	Plaster	White	Efflorescence	5	18.4	Positive
1	1	114	Administrative Office	Security Office 114	Ceiling	Plaster	White	Flaking	20	14.1	Positive
1	1	114	Administrative Office	Security Office 114	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	Floor	Concrete	Grey	Partially Inaccessible	2	1.3	Positive
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	W1	Plaster	White	Cracking	1	20	Positive
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	W2	Plaster	White	Partially Inaccessible	0	16.3	Positive
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	W3	Plaster	White	Partially Inaccessible	0	21	Positive
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	W4	Plaster	White	Cracking	1	17.3	Positive
1	1	114A	Restrooms, Staff - Male	Restroom Next to Security Office 114	Ceiling	Plaster	White	Flaking	90	8.2	Positive
1	1	115	Office	Security Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	115	Office	Security Office	W1	Plaster	White	Cracking	4	13.8	Positive
1	1	115	Office	Security Office	Pipe	Metal	White	None	0	0.04	Negative
1	1	115	Office	Security Office	W2	Plaster	White	Partially Inaccessible	4	20.5	Positive
1	1	115	Office	Security Office	W3	Plaster	White	Efflorescence	16	15.9	Positive
1	1	115	Office	Security Office	Window Sill	Wood	Brown	Chipping	1	0.04	Negative
1	1	115	Office	Security Office	Window Apron	Wood	Brown	None	0	0.04	Negative
1	1	115	Office	Security Office	Radiator	Metal	Silver	Chipping	1	5.6	Positive
1	1	115	Office	Security Office	W4	Plaster	White	None	0	14.5	Positive
1	1	115	Office	Security Office	Ceiling	Plaster	White	Efflorescence	120	11.7	Positive
1	1	115	Office	Security Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	115	Office	Security Office	Baseboard	Wood	Grey	Chipping	3	0.07	Negative
1	1	115B	Restrooms, Staff	Security Office Restroom	Floor	Concrete	Grey	Chipping	2	0.1	Negative
1	1	115B	Restrooms, Staff	Security Office Restroom	W1	Plaster	White	None	0	15.7	Positive
1	1	115B	Restrooms, Staff	Security Office Restroom	W2	Plaster	White	Cracking	25	19	Positive
1	1	115B	Restrooms, Staff	Security Office Restroom	W3	Plaster	White	Cracking	4	17.9	Positive
1	1	115B	Restrooms, Staff	Security Office Restroom	W4	Plaster	White	Cracking	22	16.4	Positive
1	1	115B	Restrooms, Staff	Security Office Restroom	Ceiling	Plaster	White	None	0	8.9	Positive
1	1	115B	Restrooms, Staff	Security Office Restroom	Radiator	Metal	Silver	Chipping	2	9.2	Positive
1	1	115A	Storage	Storage Room Next To 115	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	115A	Storage	Storage Room Next To 115	W1	Plaster	White	Cracking	8	18.4	Positive
1	1	115A	Storage	Storage Room Next To 115	W2	Plaster	White	Efflorescence	22	8.9	Positive
1	1	115A	Storage	Storage Room Next To 115	W3	Plaster	White	Cracking	8	17.2	Positive
1	1	115A	Storage	Storage Room Next To 115	Radiator	Metal	Silver	Chipping	1	1.9	Positive
1	1	115A	Storage	Storage Room Next To 115	W4	Plaster	White	Efflorescence	40	19.3	Positive
1	1	115A	Storage	Storage Room Next To 115	Pipe	Metal	White	Chipping	3	15.4	Positive
1	1	115A	Storage	Storage Room Next To 115	Pipe	Metal	White	None	0	0.12	Negative
1	1	116	Auditorium	Auditorium	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	1	116	Auditorium	Auditorium	W1	Wood	White	None	0	21.8	Positive
1	1	116	Auditorium	Auditorium	W1	Wood	Black	None	0	15.8	Positive
1	1	116	Auditorium	Auditorium	W1	Wood	Yellow	None	0	16.6	Positive
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	White	Cracking	2	16.8	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	Black	Chipping	1	15.9	Positive	
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	Yellow	Chipping	1	15.7	Positive	
1	1	116	Auditorium	Auditorium	Radiator	Metal	White	Flaking	3	5.2	Positive	
1	1	116	Auditorium	Auditorium	Window Frame	Wood	White	Chipping	10	24.9	Positive	
1	1	116	Auditorium	Auditorium	Baseboard	Wood	Brown	Chipping	3	15.8	Positive	
1	1	116	Auditorium	Auditorium	Door Frame	Wood	White	Chipping	3	20.5	Positive	
1	1	116	Auditorium	Auditorium	Door Frame	Wood	White	Chipping	3	19.8	Positive	
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	Yellow	Flaking	4	21.6	Positive	
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	Black	None	0	17.5	Positive	
1	1	116	Auditorium	Auditorium	Radiator Cover	Wood	White	Chipping	3	24.6	Positive	
1	1	116	Auditorium	Auditorium	Window Frame	Wood	White	Chipping	10	22.8	Positive	
1	1	116	Auditorium	Auditorium	Ceiling	Plaster	White	Flaking	240	15.6	Positive	
1	1	116	Auditorium	Auditorium	Door Frame	Wood	White	Chipping	2	22.3	Positive	
1	1	116	Auditorium	Auditorium	Door	Wood	White	Chipping	2	20.4	Positive	
1	1	116	Auditorium	Auditorium	Door	Wood	Black	Chipping	2	22.6	Positive	
1	1	116	Auditorium	Auditorium	Crown Moulding	Wood	White	Cracking	2	23.4	Positive	
1	1	116	Auditorium	Auditorium	Crown Moulding	Wood	White	Cracking	7	11.8	Positive	
1	1	116A	Auditorium	Auditorium Stage	W1	Plaster	White	Flaking	6	8.9	Positive	
1	1	116A	Auditorium	Auditorium Stage	W2	Plaster	Green	Flaking	8	18.6	Positive	
1	1	116A	Auditorium	Auditorium Stage	W3	Plaster	White	Partially Inaccessible	0	12.8	Positive	
1	1	116A	Auditorium	Auditorium Stage	W4	Plaster	Green	Flaking	3	17	Positive	
1	1	116A	Auditorium	Auditorium Stage	Column	Plaster	White	Flaking	18	31.1	Positive	
1	1	116A	Auditorium	Auditorium Stage	Column	Plaster	White	Cracking	15	10.8	Positive	
1	1	116A	Auditorium	Auditorium Stage	Door Frame	Wood	Green	Chipping	2	21.5	Positive	
1	1	116A	Auditorium	Auditorium Stage	Baseboard	Wood	Green	Chipping	1	17.4	Positive	
1	1	116A	Auditorium	Auditorium Stage	Radiator	Metal	Silver	Flaking	9	8.1	Positive	
1	1	116A	Auditorium	Auditorium Stage	Door Frame	Wood	Green	Chipping	1	21.7	Positive	
1	1	116A	Auditorium	Auditorium Stage	Ceiling	Plaster	White	None	0	N/A	N/A	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	W1	Plaster	Yellow	None	0	18.5	Positive	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	W2	Plaster	Yellow	None	0	23.4	Positive	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	W3	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	W4	Plaster	Yellow	Cracking	2	23.7	Positive	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Doors	Metal	Brown	None	0	0	Negative	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Door Frames	Metal	Brown	Chipping	2	0.24	Negative	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Baseboard	Concrete	Brown	None	0	0.22	Negative	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Ceiling	Plaster	Yellow	Efflorescence	5	22.1	Positive	
1	1	H15A	Circulation (Hallway)	1st Floor Exit at Room 102	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	W1	N/A	N/A	N/A	N/A	N/A	N/A	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Doors	Metal	Brown	Chipping	1	0.1	Negative	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Door Frames	Metal	Brown	Chipping	1	0	Negative	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	W2	Plaster	White	Cracking	18	22.9	Positive	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Radiator	Metal	Silver	Chipping	3	5.7	Positive	
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	W3	N/A	N/A	N/A	N/A	N/A	N/A	

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	W4	Plaster	White	Flaking	4	16.4	Positive
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Pipe Chase Door	Wood	Brown	None	0	0	Negative
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Pipe Chase Door Frame	Wood	Brown	None	0	0.08	Negative
1	1	H14A	Circulation (Hallway)	1st Floor Exit at Storage Room 108	Doors	Metal	Brown	Chipping	1	0	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Baseboard	Concrete	Brown	None	0	0.23	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Doors	Metal	Brown	Chipping	2	0	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Door Frames	Metal	Brown	Chipping	2	0	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	W2	Plaster	White	Flaking	20	15.4	Positive
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Doors	Metal	Brown	Chipping	2	0	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Door Frames	Metal	Brown	Chipping	1	0.1	Negative
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	W4	Plaster	White	Cracking	25	16.7	Positive
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Ceiling	Plaster	White	Flaking	250	20.7	Positive
1	1	H15B	Circulation (Hallway)	1st Floor Exit at Room 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Baseboard	Concrete	Brown	N/A	10	0	Negative
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	W1	Plaster	Yellow	Cracking	1	18.4	Positive
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Baseboard	Concrete	Brown	None	0	0.13	Negative
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	W2	Plaster	Yellow	Cracking	2	20.6	Positive
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	W4	Plaster	Yellow	Cracking	4	22.6	Positive
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Ceiling	Plaster	Yellow	None	0	23.9	Positive
1	1	H14B	Circulation (Hallway)	1st Floor Exit at Room 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	W1	Plaster	Yellow	Cracking	1	20.2	Positive
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Electric Panel	Metal	Yellow	None	0	8.1	Positive
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	W2	Plaster	Yellow	Cracking	1	28.7	Positive
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Elevator Door	Metal	Tan	None	0	0.02	Negative
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Elevator Door Frame	Metal	Tan	Flaking	1	0.07	Negative
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Ceiling	Plaster	White	Flaking	120	20	Positive
1	1	H14	Circulation (Hallway)	Hallway from Classrooms 109 to 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W1	Plaster	Yellow	Flaking	5	26.4	Positive
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W2	Plaster	Yellow	Flaking	8	20.2	Positive
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Elevator Door	Metal	Tan	None	0	0	Negative
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Elevator Door Frame	Metal	Tan	Chipping	1	0.18	Negative
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W3	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Ceiling	Plaster	White	Flaking	190	22.3	Positive
1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	W1	Plaster	Yellow	Flaking	1	17.9	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Radiators	Metal	Silver	Chipping	2	3.9	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Pipe	Metal	Yellow	None	0	0.04	Negative
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	W2	Plaster	Yellow	Flaking	2	19	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Pipe	Metal	Yellow	None	0	0.18	Negative
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Radiators	Metal	Silver	Flaking	4	2	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Baseboard	Concrete	Brown	None	0	0.04	Negative
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Electric Panel	Metal	Yellow	None	0	1.2	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	W3	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Ceiling	Plaster	White	Flaking	200	18.6	Positive
1	1	H16	Circulation (Hallway)	Hallway from Classrooms 101 to 111	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	W1	Plaster	Yellow	Cracking	1	16.6	Positive
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	Electric Panel	Metal	Yellow	Chipping	1	10.1	Positive
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	W2	Plaster	Yellow	Flaking	2	16.7	Positive
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	Baseboard	Concrete	Brown	Flaking	1	0.12	Negative
1	1	H17A	Circulation (Hallway)	Hallway from Classrooms 107 to 106	Pipe	Metal	Yellow	Flaking	2	10.3	Positive
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Lockers	Metal	Black	None	0	0.01	Negative
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Baseboard	Concrete	Brown	None	0	0.05	Negative
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Radiators	Metal	Silver	Flaking	2	5.9	Positive
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Pipe	Metal	Yellow	Flaking	1	14.5	Positive
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	1	H17B	Circulation (Hallway)	Hallway from Classrooms 104 to 105	Ceiling	Plaster	White	None	0	16.1	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Stringer	Concrete	Grey	Chipping	2	4.1	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Tread	Concrete	Grey	Chipping	2	2.5	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Handrail	Concrete	Grey	Chipping	2	1.1	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Baluster	Concrete	Grey	Chipping	2	3.2	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Newel Post	Concrete	Grey	Chipping	2	3.9	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	W1	Plaster	White	Flaking	12	10.9	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	W2	Plaster	White	Flaking	12	16.1	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	W3	Plaster	White	Flaking	12	15.7	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	W4	Plaster	White	Flaking	12	15.9	Positive
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	1	S11	Stairs	Stairwell adjacent to Classroom 109A	Stair Soffit	Metal	Grey	Chipping	2	4.1	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	1	100C	Stairs	Stairs to Boy's Gym from H16	W1	Plaster	White	Flaking	10	14.9	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16	W2	Plaster	White	Flaking	30	16.2	Positive

					Lead-Safe Certification Assessment Report									
					1130 Tilden Middle School									
					6601 Elmwood Avenue, Philadelphia, PA 19142									
					Dates: 08/31/2022									
					Inspector Name and Certificate Number: Ryan Hutsell 059512									
					Inspection Company: Synertech									
E	l	e	m	e										
n	e	n	t	n	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
t	r	e	n	t										
1	1	100C	Stairs	Stairs to Boy's Gym from H16				W3	Plaster	White	Flaking	10	16.9	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				W4	Plaster	White	Flaking	30	15.4	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Ceiling	Plaster	White	Flaking	15	12.9	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Stringer	Concrete	Grey	Chipping	2	3.2	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Tread	Concrete	Grey	Chipping	2	3.5	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Handrail	Concrete	Grey	Chipping	1	2.6	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Baluster	Concrete	Grey	Chipping	2	1.9	Positive
1	1	100C	Stairs	Stairs to Boy's Gym from H16				Newel Post	Concrete	Grey	Chipping	2	2.7	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				W1	Plaster	White	Flaking	4	15.4	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				W2	Plaster	White	Flaking	12	12.9	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				W3	Plaster	White	Flaking	16	16.2	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				W4	Plaster	White	Flaking	12	13.5	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				Ceiling	Plaster	White	Flaking	4	11.5	Positive
1	1	100C-1	Storage	Storage Closet at bottom of Stairs to Boys' Gym from H16 (adj. Stage Side of Auditorium)				Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				W1	Brick	White	Flaking	40	4.2	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				W2	Brick	White	Flaking	40	5.6	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				W3	Brick	White	Flaking	40	2.1	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				W4	Brick	White	Flaking	40	6.9	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Ceiling	Concrete	White	Flaking	10	3.8	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Window Frame	Metal	Brown	Chipping	1	4.2	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Handrail	Metal	Brown	Chipping	10	2.1	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Pipe	Metal	Grey	Chipping	12	1.5	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Stringer	Concrete	Grey	Chipping	12	1.5	Positive
1	2	S24	Stairs, Fire Tower	Stairwell adjacent to men's room 220				Tread	Concrete	Grey	Chipping	12	0.25	Negative
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				W1	Brick	White	Flaking	40	4.6	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				W2	Brick	White	Flaking	40	4.7	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				W3	Brick	White	Flaking	40	3.2	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				W4	Brick	White	Flaking	40	5.9	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Ceiling	Concrete	White	Flaking	10	6.1	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Window Frame	Metal	Brown	Chipping	1	4.8	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Handrail	Metal	Brown	Chipping	10	2.3	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Pipe	Metal	Grey	Chipping	12	2.1	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Stringer	Concrete	Grey	Chipping	12	1.2	Positive
1	2	S25	Stairs, Fire Tower	Stairwell adjacent to Classroom 215				Tread	Concrete	Grey	Chipping	12	0.15	Negative
1	1	S12	Stairs	Stairwell adjacent to Classroom 100				Tread	Concrete	Grey	None	0	2.2	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100				Riser	Concrete	Grey	Chipping	0	9.2	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100				Stringer	Concrete	Grey	None	0	7	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100				Door	Metal	Brown	Flaking	1	0	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Radiator	Metal	Silver	Chipping	5	2.6	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Electric Panel	Metal	Brown	None	0	0.7	Positive
1	1	S12	Stairs	Stairwell adjacent to Classroom 100	Newel Post	Concrete	Grey	Chipping	6	4.6	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Floor	Concrete	Grey	None	0	0	Negative
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Stringer	Concrete	Grey	Chipping	2	3.2	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Tread	Concrete	Grey	Chipping	2	1.5	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Handrail	Metal	Grey	Chipping	2	1.5	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Baluster	Metal	Grey	Chipping	2	3.6	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Newel Post	Concrete	Grey	Chipping	2	3.9	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	W1	Plaster	White	None	0	16.1	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	W2	Plaster	White	Cracking	10	9.2	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	W2	Plaster	White	Cracking	10	13.1	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	W3	Plaster	White	None	0	14.8	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Radiator	Metal	Silver	Chipping	2	3.2	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	W4	Plaster	White	None	0	15.4	Positive
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S22	Stairs	Stairwell adjacent to Classroom 203A	Stair Soffit	Metal	Grey	Chipping	2	3.2	Positive
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	W1	Terracotta	N/A	N/A	N/A	N/A	N/A
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	W2	Terracotta	N/A	N/A	N/A	N/A	N/A
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	W3	Terracotta	N/A	N/A	N/A	N/A	N/A
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	W4	Terracotta	N/A	N/A	N/A	N/A	N/A
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	Ceiling	Concrete	White	Chipping	5	10.2	Positive
1	2	FT2	Circulation (Hallway)	2nd Floor Hallway to Fire Tower Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	W1	Plaster	Yellow	None	0	39.1	Positive
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	W3	Plaster	Yellow	None	0	26.1	Positive
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	Ceiling	Plaster	White	Flaking	40	13.2	Positive
1	2	H21	Circulation (Hallway)	Hallway from Classrooms 207 to 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Floor	Concrete	Brown	Chipping	10	0	Negative
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	W1	Plaster	White	Cracking	12	18.4	Positive
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	W2	Plaster	White	Cracking	25	19.3	Positive
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Elevator Door Frame	Metal	Tan	Chipping	1	0.11	Negative
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Elevator Door	Metal	Tan	None	0	0	Negative
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Ceiling	Plaster	White	Flaking	600	6.8	Positive
1	2	H22	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	Floor	Concrete	Brown	Chipping	10	0	Negative
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	W1	Plaster	White	Cracking	4	16.7	Positive
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	W3	Plaster	White	Cracking	6	23	Positive
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	W4	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	Ceiling	Plaster	White	Efflorescence	120	16	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	H23	Circulation (Hallway)	Hallway from Classrooms 201 to 215	Radiators	Metal	Silver	Chipping	10	2.9	Positive
1	2	H24	Circulation (Hallway)	Hallway from Classrooms 211 to 215	Floor	Concrete	Brown	Chipping	10	0	Negative
1	2	H24	Circulation (Hallway)	Hallway from Classrooms 211 to 215	W1	Plaster	White	None	0	19.3	Positive
1	2	H24	Circulation (Hallway)	Hallway from Classrooms 211 to 215	W2	Plaster	White	Cracking	2	17.4	Positive
1	2	H24	Circulation (Hallway)	Hallway from Classrooms 211 to 215	Ceiling	Plaster	White	Efflorescence	40	13	Positive
1	2	H24	Circulation (Hallway)	Hallway from Classrooms 211 to 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	W1	Brick	White	Flaking	40	6.2	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	W2	Brick	White	Flaking	40	4.9	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	W3	Brick	White	Flaking	40	5.8	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	W4	Brick	White	Flaking	40	6.6	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Ceiling	Concrete	White	Flaking	10	5.2	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Window Frame	Metal	Brown	Chipping	1	4.1	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Handrail	Metal	Brown	Chipping	10	1.5	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Pipe	Metal	Grey	Chipping	12	1.3	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Stringer	Concrete	Grey	Chipping	12	1.6	Positive
1	2	S23	Stairs, Fire Tower	Stairwell adjacent to Classroom 201	Tread	Concrete	Grey	Chipping	12	0.45	Negative
1	2	201	Intermediate/Middle	Classroom 201	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	201	Intermediate/Middle	Classroom 201	W1	Plaster	Blue	None	0	16.3	Positive
1	2	201	Intermediate/Middle	Classroom 201	W2	Plaster	Blue	None	0	15.9	Positive
1	2	201	Intermediate/Middle	Classroom 201	W3	Plaster	Blue	None	0	20.4	Positive
1	2	201	Intermediate/Middle	Classroom 201	W4	Plaster	Blue	None	0	22.6	Positive
1	2	201	Intermediate/Middle	Classroom 201	Ceiling	Plaster	White	Flaking	25	7.2	Positive
1	2	201	Intermediate/Middle	Classroom 201	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	201	Intermediate/Middle	Classroom 201	Security Gate	Metal	Black	None	0	0	Negative
1	2	201	Intermediate/Middle	Classroom 201	Chalkboard Ledge	Wood	Brown	Chipping	1	0.02	Negative
1	2	201	Intermediate/Middle	Classroom 201	Chalkboard Ledge	Wood	Brown	Chipping	1	0.04	Negative
1	2	201	Intermediate/Middle	Classroom 201	Chalkboard Ledge	Wood	Brown	Chipping	1	0.09	Negative
1	2	201	Intermediate/Middle	Classroom 201	Window Sill	Wood	Brown	Chipping	2	0.17	Negative
1	2	201	Intermediate/Middle	Classroom 201	Pipe	Metal	Blue	None	0	24.4	Positive
1	2	201	Intermediate/Middle	Classroom 201	Baseboard	Concrete	Grey	N/A	0	0.05	Negative
1	2	202	Intermediate/Middle	Classroom 202	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	202	Intermediate/Middle	Classroom 202	W1	Plaster	Blue	Cracking	2	17.1	Positive
1	2	202	Intermediate/Middle	Classroom 202	W2	Plaster	Blue	Cracking	1	15.1	Positive
1	2	202	Intermediate/Middle	Classroom 202	W3	Plaster	Blue	Efflorescence	16	19.7	Positive
1	2	202	Intermediate/Middle	Classroom 202	W4	Plaster	Blue	None	0	9.5	Positive
1	2	202	Intermediate/Middle	Classroom 202	Ceiling	Plaster	White	Flaking	300	15	Positive
1	2	202	Intermediate/Middle	Classroom 202	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	202	Intermediate/Middle	Classroom 202	Baseboard	Rubber	Grey	N/A	0	0.02	Negative
1	2	202	Intermediate/Middle	Classroom 202	Chalkboard Ledge	Wood	Brown	Chipping	1	0	Negative
1	2	202	Intermediate/Middle	Classroom 202	Window Sill	Wood	Brown	Chipping	1	0.1	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	2	202	Intermediate/Middle	Classroom 202	Window Apron	Wood	Brown	Chipping	1	0.06	Negative	
1	2	202	Intermediate/Middle	Classroom 202	Radiators	Metal	Silver	Chipping	2	3	Positive	
1	2	203	Intermediate/Middle	Classroom 203	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	203	Intermediate/Middle	Classroom 203	W1	Plaster	White	Chipping	1	14.6	Positive	
1	2	203	Intermediate/Middle	Classroom 203	W2	Plaster	White	Cracking	2	15.8	Positive	
1	2	203	Intermediate/Middle	Classroom 203	W3	Plaster	White	Cracking	3	16.9	Positive	
1	2	203	Intermediate/Middle	Classroom 203	W4	Plaster	White	Cracking	0	19.3	Positive	
1	2	203	Intermediate/Middle	Classroom 203	Ceiling	Plaster	White	Flaking	25	16.4	Positive	
1	2	203	Intermediate/Middle	Classroom 203	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	203	Intermediate/Middle	Classroom 203	Baseboard	Wood	Brown	Chipping	2	0.04	Negative	
1	2	203	Intermediate/Middle	Classroom 203	Chalkboard Ledge	Wood	Brown	Chipping	1	0.03	Negative	
1	2	203	Intermediate/Middle	Classroom 203	Chalkboard Ledge	Wood	Brown	Chipping	1	0.03	Negative	
1	2	203	Intermediate/Middle	Classroom 203	Chalkboard Ledge	Wood	Brown	Chipping	1	0.05	Negative	
1	2	203	Intermediate/Middle	Classroom 203	Window Sill	Wood	Brown	Chipping	3	0.03	Negative	
1	2	203	Intermediate/Middle	Classroom 203	Window Apron	Wood	Brown	None	0	0.09	Negative	
1	2	203A	Intermediate/Middle	Classroom 203A	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	203A	Intermediate/Middle	Classroom 203A	W1	Plaster	White	None	0	21.1	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	W1	Concrete	White	None	0	0.08	Negative	
1	2	203A	Intermediate/Middle	Classroom 203A	W2	Plaster	White	None	0	18.8	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	W3	Plaster	White	None	0	20.5	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	W4	Plaster	White	None	0	20.4	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	Ceiling	Plaster	White	Flaking	20	10.9	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	203A	Intermediate/Middle	Classroom 203A	Radiators	Metal	Blue	Chipping	2	8.7	Positive	
1	2	203A	Intermediate/Middle	Classroom 203A	Door Frame	Metal	Brown	Friction	1	0.01	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Concrete	Grey	Chipping	1	0.03	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Plaster	White	Chipping	4	5.6	Positive	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Brick	Grey	None	0	0	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Plaster	White	Flaking	4	11.4	Positive	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Brick	Grey	Chipping	3	0.01	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Plaster	White	Cracking	1	8.6	Positive	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Brick	Grey	Chipping	5	6.8	Positive	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Concrete	Grey	None	0	0.01	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Transite	Grey	None	0	0.02	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	Pipe	Metal	Grey	Cracking	2	0.13	Negative	
1	2	203B	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Plaster	White	None	0	14.2	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	W1	Plaster	Tan	Cracking	35	12.7	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	W2	Plaster	Tan	Cracking	50	6.1	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	W3	Plaster	Tan	Efflorescence	45	12.1	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	W4	Plaster	Tan	Efflorescence	40	11.4	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	Sink	Metal	White	None	0	7.8	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	Sink	Metal	Grey	None	0	4.2	Positive	

					Lead-Safe Certification Assessment Report							
					Dates: 08/31/2022							
					Inspector Name and Certificate Number: Ryan Hutsell 059512							
					Inspection Company: Synertech							
					1130 Tilden Middle School							
					6601 Elmwood Avenue, Philadelphia, PA 19142							
E	l	e	m	e								
n	e	n	t	s	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	Ceiling	Plaster	Tan	Cracking	25	10.7	Positive	
1	2	203C	Service Closets	Service Closet next to Boys' Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	W1	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	W2	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	W3	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	W4	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	203PC	Pipe Chase	Pipe Chase in Service Closet Adjacent to the Boys Restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	204	Intermediate/Middle	Classroom 204	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	204	Intermediate/Middle	Classroom 204	W1	Plaster	Blue	None	0	19.6	Positive	
1	2	204	Intermediate/Middle	Classroom 204	W2	Plaster	Blue	None	0	10.1	Positive	
1	2	204	Intermediate/Middle	Classroom 204	W3	Plaster	Blue	Efflorescence	2	13.7	Positive	
1	2	204	Intermediate/Middle	Classroom 204	W4	Plaster	Blue	Chipping	1	10.3	Positive	
1	2	204	Intermediate/Middle	Classroom 204	Ceiling	Plaster	White	Partially Inaccessible	0	12.4	Positive	
1	2	204	Intermediate/Middle	Classroom 204	Baseboard	Wood	Brown	Chipping	3	0.12	Negative	
1	2	204	Intermediate/Middle	Classroom 204	Closet Door	Wood	Brown	None	0	0	Negative	
1	2	204	Intermediate/Middle	Classroom 204	Radiators	Metal	Silver	Chipping	2	9	Positive	
1	2	205	Health Service Room	Health Service Room (Nurse)	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	2	205	Health Service Room	Health Service Room (Nurse)	W1	Plaster	White	None	0	18.3	Positive	
1	2	205	Health Service Room	Health Service Room (Nurse)	W2	Plaster	White	None	0	0.03	Negative	
1	2	205	Health Service Room	Health Service Room (Nurse)	W3	Plaster	White	None	0	0.02	Negative	
1	2	205	Health Service Room	Health Service Room (Nurse)	W4	Plaster	White	Chipping	1	0.01	Negative	
1	2	205	Health Service Room	Health Service Room (Nurse)	Ceiling	Plaster	White	Partially Inaccessible	0	9.5	Positive	
1	2	205	Health Service Room	Health Service Room (Nurse)	Door Frame	Wood	Brown	Chipping	2	23.3	Positive	
1	2	205	Health Service Room	Health Service Room (Nurse)	Bulletin Board Frame	Wood	Brown	Chipping	1	22.4	Positive	
1	2	205	Health Service Room	Health Service Room (Nurse)	Door Frame	Wood	Brown	Chipping	1	0.01	Negative	
1	2	205	Health Service Room	Health Service Room (Nurse)	Window Apron	Wood	Brown	Chipping	1	22.8	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	W1	Plaster	Blue	Cracking	2	17.5	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Door Frame	Wood	Brown	Chipping	1	24	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Door	Wood	Blue	Chipping	1	23.3	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Door Frame	Wood	Blue	Chipping	1	15.9	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Mullions	Wood	Tan	Flaking	3	18.3	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	W2	Plaster	Blue	Cracking	1	18.2	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	W3	Plaster	Blue	Cracking	3	20.2	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Window Sill	Wood	Brown	Flaking	2	25	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Window Apron	Wood	Brown	Cracking	1	25.1	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Baseboard	Wood	Brown	Chipping	1	3.9	Positive	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	W4	Plaster	Blue	Cracking	1	0.02	Negative	
1	2	205A	udent Restrooms - Male/Fema	Restroom in Health Service Room (Nurse)	Ceiling	Plaster	White	None	0	12.6	Negative	

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	206	Intermediate/Middle	Storage 206	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	206	Intermediate/Middle	Storage 206	W1	Plaster	White	Cracking	1	15.2	Positive
1	2	206	Intermediate/Middle	Storage 206	W2	Sheetrock	White	Partially Inaccessible	0	0.02	Negative
1	2	206	Intermediate/Middle	Storage 206	W3	Sheetrock	White	Partially Inaccessible	0	0.03	Negative
1	2	206	Intermediate/Middle	Storage 206	W4	Plaster	White	Partially Inaccessible	0	0.03	Negative
1	2	206	Intermediate/Middle	Storage 206	Ceiling	Plaster	White	Partially Inaccessible	0	14.8	Positive
1	2	206	Intermediate/Middle	Storage 206	Radiator	Metal	Brown	None	0	0.02	Negative
1	2	207A	Administrative Office	Sel Suite C	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207A	Administrative Office	Sel Suite C	W1	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207A	Administrative Office	Sel Suite C	W2	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207A	Administrative Office	Sel Suite C	W3	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207A	Administrative Office	Sel Suite C	W4	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207A	Administrative Office	Sel Suite C	Ceiling	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207B	Administrative Office	SP Suite D Copy Room	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207B	Administrative Office	SP Suite D Copy Room	W1	Sheetrock	White	Flaking	2	0.03	Negative
1	2	207B	Administrative Office	SP Suite D Copy Room	W2	Sheetrock	White	Cracking	1	0.01	Negative
1	2	207B	Administrative Office	SP Suite D Copy Room	W3	Plaster	White	Partially Inaccessible	1	20.1	Positive
1	2	207B	Administrative Office	SP Suite D Copy Room	W4	Plaster	White	Flaking	3	16.9	Positive
1	2	207B	Administrative Office	SP Suite D Copy Room	Ceiling	Sheetrock	White	Partially Inaccessible	0	0	Negative
1	2	207B	Administrative Office	SP Suite D Copy Room	Door Frame	Metal	Brown	Chipping	1	0.03	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	W1	Sheetrock	White	None	0	0.04	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	W2	Plaster	White	Cracking	8	18	Positive
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	W3	Plaster	White	Efflorescence	20	19.5	Positive
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	W4	Sheetrock	White	Partially Inaccessible	1	0.06	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Ceiling	Plaster	White	Partially Inaccessible	0	10.8	Positive
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Door Frame	Metal	Brown	Chipping	1	0.02	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Window Sill	Wood	Brown	Chipping	1	0.11	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Window Apron	Wood	Brown	None	0	0.06	Negative
1	2	207C	Administrative Office	Counselor's Suite C (Small next to Principal)	Baseboard	Rubber	Brown	None	0	0.05	Negative
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207D	Administrative Office	Counselor's Suite D (In Small Hallway next to C)	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	W1	Plaster	White	Cracking	1	21.4	Positive
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	W2	Sheetrock	White	Chipping	1	0.04	Negative
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	W3	Sheetrock	White	Cracking	2	0.01	Negative
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	W4	Sheetrock	White	None	0	0.03	Negative
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	W3	Plaster	White	Cracking	1	18	Positive
1	2	207E	Administrative Office	Counselor's Suite E (Large Open Area)	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207F	Administrative Office	Counselor's Suite F (Back Corner Room)	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	W1	Sheetrock	White	Partially Inaccessible	0	0.02	Negative
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	W2	Sheetrock	White	None	0	0.03	Negative
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	W3	Plaster	White	Flaking	6	21.9	Positive
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	W4	Plaster	White	Flaking	4	25.2	Positive
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	Ceiling	Plaster	White	Partially Inaccessible	0	10.8	Positive
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	Baseboard	Rubber	Brown	None	0	0.15	Negative
1	2	207G	Administrative Office	Counselor's Suite G (Center Office off of Large Open Area)	Door Frame	Metal	Brown	Chipping	1	0.03	Negative
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	2	207H	Administrative Office	Counselor's Suite H (Behind Storage 206)	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access
1	2	208	General Administrative Reception	Main Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208	General Administrative Reception	Main Office	W1	Plaster	Red	Flaking	2	22.9	Positive
1	2	208	General Administrative Reception	Main Office	Duct Vent	Metal	White	None	0	0.03	Negative
1	2	208	General Administrative Reception	Main Office	W1	Plaster	White	None	0	16.4	Positive
1	2	208	General Administrative Reception	Main Office	Baseboard	Wood	Black	Flaking	1	0.16	Negative
1	2	208	General Administrative Reception	Main Office	Chalkboard Ledge	Wood	Black	None	0	0.04	Negative
1	2	208	General Administrative Reception	Main Office	W2	Plaster	Red	Partially Inaccessible	0	20.2	Positive
1	2	208	General Administrative Reception	Main Office	W2	Plaster	White	Flaking	2	22.2	Positive
1	2	208	General Administrative Reception	Main Office	W3	Plaster	Red	Partially Inaccessible	0	0.09	Negative
1	2	208	General Administrative Reception	Main Office	Chalkboard Ledge	Wood	Black	None	0	0.09	Negative
1	2	208	General Administrative Reception	Main Office	Baseboard	Wood	Black	None	0	0.4	Negative
1	2	208	General Administrative Reception	Main Office	W3	Plaster	White	Cracking	1	27.2	Positive
1	2	208	General Administrative Reception	Main Office	W4	Concrete	Red	Flaking	4	18.9	Positive
1	2	208	General Administrative Reception	Main Office	W4	Plaster	White	None	0	0.02	Negative
1	2	208	General Administrative Reception	Main Office	Ceiling	Plaster	White	Flaking	20	14.5	Positive
1	2	208	General Administrative Reception	Main Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208C	General Administrative Reception	Main Office Foyer	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208C	General Administrative Reception	Main Office Foyer	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	208C	General Administrative Reception	Main Office Foyer	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208C	General Administrative Reception	Main Office Foyer	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208C	General Administrative Reception	Main Office Foyer	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208C	General Administrative Reception	Main Office Foyer	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208A	Principal/Directors Office	Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208A	Principal/Directors Office	Principal's Office	W1	Plaster	Yellow	None	0	20.8	Positive
1	2	208A	Principal/Directors Office	Principal's Office	W2	Plaster	Yellow	Cracking	3	22.3	Positive
1	2	208A	Principal/Directors Office	Principal's Office	W3	Plaster	White	Flaking	4	19.9	Positive
1	2	208A	Principal/Directors Office	Principal's Office	W4	Plaster	White	Partially Inaccessible	0	0.14	Negative
1	2	208A	Principal/Directors Office	Principal's Office	Ceiling	Plaster	White	Partially Inaccessible	0	10.8	Positive
1	2	208A	Principal/Directors Office	Principal's Office	Chalkboard Ledge	Wood	Burgundy	None	0	0.09	Negative
1	2	208A	Principal/Directors Office	Principal's Office	W2	Plaster	Black	Flaking	1	21.5	Positive
1	2	208A	Principal/Directors Office	Principal's Office	W2	Plaster	White	Cracking	1	21.6	Positive
1	2	208A	Principal/Directors Office	Principal's Office	Chalkboard Ledge	Wood	White	None	0	0.07	Negative
1	2	208A	Principal/Directors Office	Principal's Office	Baseboard	Wood	White	Flaking	1	0.16	Negative
1	2	208A1	Principal/Directors Office	Principal's Office Restroom	W1	Plaster	White	Cracking	1	15.9	Positive
1	2	208A1	Principal/Directors Office	Principal's Office Restroom	W2	Plaster	White	Cracking	1	18.4	Positive
1	2	208A1	Principal/Directors Office	Principal's Office Restroom	W3	Plaster	White	None	0	17.3	Positive
1	2	208A1	Principal/Directors Office	Principal's Office Restroom	W4	Plaster	White	Chipping	1	21.2	Positive
1	2	208A1	Principal/Directors Office	Principal's Office Restroom	Baseboard	Wood	Brown	None	0	0.19	Negative
1	2	208B	Copying Room	Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208B	Copying Room	Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208B	Copying Room	Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208B	Copying Room	Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208B	Copying Room	Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208B	Copying Room	Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	Ceiling	Plaster	White	Flaking	5	15.2	Positive
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	W1	Plaster	White	Flaking	1	15.9	Positive
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	W2	Plaster	White	Cracking	1	18.4	Positive
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	W3	Plaster	White	None	0	17.3	Positive
1	2	208L	Restrooms, Staff - Male/Female	Faculty Restroom	W4	Plaster	White	Chipping	1	0.19	Negative
1	2	209	IMC (Library)	IMC	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209	IMC (Library)	IMC	W1	Plaster	Blue	None	0	21.8	Positive
1	2	209	IMC (Library)	IMC	W1	Plaster	Green	Partially Inaccessible	8	14.3	Positive
1	2	209	IMC (Library)	IMC	Baseboard	Concrete	Black	Cracking	1	0.02	Negative
1	2	209	IMC (Library)	IMC	W2	Plaster	Blue	Partially Inaccessible	0	19.2	Positive
1	2	209	IMC (Library)	IMC	W3	Plaster	Blue	Cracking	12	16	Positive
1	2	209	IMC (Library)	IMC	W4	Plaster	Tan	Partially Inaccessible	3	13.3	Positive
1	2	209	IMC (Library)	IMC	W4	Plaster	Blue	None	0	21.4	Positive
1	2	209	IMC (Library)	IMC	Ceiling	Plaster	White	Flaking	50	9.3	Positive
1	2	209	IMC (Library)	IMC	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	209A	Administrative Office	IMC Office Left	Floor	No Access	No Access	No Access	No Access	No Access	No Access

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	209A	Administrative Office	IMC Office Left	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209A	Administrative Office	IMC Office Left	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209A	Administrative Office	IMC Office Left	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209A	Administrative Office	IMC Office Left	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209A	Administrative Office	IMC Office Left	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	2	209B	Administrative Office	IMC Office Right	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	211	Intermediate/Middle	Classroom 211	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	211	Intermediate/Middle	Classroom 211	W1	Plaster	White	Cracking	3	19	Positive
1	2	211	Intermediate/Middle	Classroom 211	W2	Plaster	White	Partially Inaccessible	0	15.8	Positive
1	2	211	Intermediate/Middle	Classroom 211	W3	Plaster	White	Flaking	5	12.9	Positive
1	2	211	Intermediate/Middle	Classroom 211	Window Sill	Wood	Brown	Chipping	1	0.13	Negative
1	2	211	Intermediate/Middle	Classroom 211	Window Apron	Wood	Brown	Chipping	1	0.07	Negative
1	2	211	Intermediate/Middle	Classroom 211	Pipe	Metal	White	Cracking	1	0	Negative
1	2	211	Intermediate/Middle	Classroom 211	W4	Plaster	White	Partially Inaccessible	0	0	Negative
1	2	211	Intermediate/Middle	Classroom 211	Ceiling	Plaster	White	Flaking	20	8.5	Positive
1	2	211	Intermediate/Middle	Classroom 211	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	212A/B	Intermediate/Middle	Classroom 212	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	212A/B	Intermediate/Middle	Classroom 212	W1	Plaster	Tan	Partially Inaccessible	4	18.5	Positive
1	2	212A/B	Intermediate/Middle	Classroom 212	Baseboard	Wood	Brown	None	0	0.06	Negative
1	2	212A/B	Intermediate/Middle	Classroom 212	Wall Partition	Wood	Tan	Flaking	1	0.21	Negative
1	2	212A/B	Intermediate/Middle	Classroom 212	Chalkboard Ledge	Wood	Brown	Chipping	1	0.05	Negative
1	2	212A/B	Intermediate/Middle	Classroom 212	W2	Plaster	White	Cracking	1	15.5	Positive
1	2	212A/B	Intermediate/Middle	Classroom 212	Baseboard	Wood	Brown	Chipping	2	0.08	Negative
1	2	212A/B	Intermediate/Middle	Classroom 212	W3	Plaster	Tan	Flaking	2	23.4	Positive
1	2	212A/B	Intermediate/Middle	Classroom 212	W4	Plaster	Tan	Partially Inaccessible	0	16.4	Positive
1	2	212A/B	Intermediate/Middle	Classroom 212	Ceiling	Plaster	White	Flaking	20	11.8	Positive
1	2	212A/B	Intermediate/Middle	Classroom 212	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	213	Intermediate/Middle	Classroom 213	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	213	Intermediate/Middle	Classroom 213	W1	Plaster	Tan	Chipping	1	16.5	Positive
1	2	213	Intermediate/Middle	Classroom 213	W2	Plaster	Tan	None	0	13	Positive
1	2	213	Intermediate/Middle	Classroom 213	Chalkboard Ledge	Wood	Brown	Chipping	1	0.03	Negative
1	2	213	Intermediate/Middle	Classroom 213	W3	Plaster	Tan	Flaking	1	16.3	Positive
1	2	213	Intermediate/Middle	Classroom 213	Window Sill	Wood	Brown	Chipping	2	0.09	Negative
1	2	213	Intermediate/Middle	Classroom 213	Window Apron	Wood	Brown	None	0	0.06	Negative
1	2	213	Intermediate/Middle	Classroom 213	W4	Wood	White	None	0	0.15	Negative
1	2	213	Intermediate/Middle	Classroom 213	Ceiling	Plaster	White	Flaking	20	10.9	Positive
1	2	213	Intermediate/Middle	Classroom 213	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214	Intermediate/Middle	Classroom 214	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	214	Intermediate/Middle	Classroom 214	Baseboard	Wood	Brown	None	0	0	Negative

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	214	Intermediate/Middle	Classroom 214	W1	Plaster	White	Flaking	1	15.9	Positive
1	2	214	Intermediate/Middle	Classroom 214	Chalkboard Ledge	Wood	Brown	Friction	2	0.26	Negative
1	2	214	Intermediate/Middle	Classroom 214	W2	Plaster	White	None	0	15.4	Positive
1	2	214	Intermediate/Middle	Classroom 214	Window Sill	Wood	Brown	Chipping	1	0.07	Negative
1	2	214	Intermediate/Middle	Classroom 214	Window Apron	Wood	Brown	Chipping	1	0.05	Negative
1	2	214	Intermediate/Middle	Classroom 214	Chalkboard Ledge	Wood	Brown	Friction	2	0.09	Negative
1	2	214	Intermediate/Middle	Classroom 214	W3	Plaster	White	Chipping	1	20.2	Positive
1	2	214	Intermediate/Middle	Classroom 214	W4	Plaster	White	None	0	11	Positive
1	2	214	Intermediate/Middle	Classroom 214	Chalkboard Ledge	Wood	Brown	Chipping	2	0.3	Negative
1	2	214	Intermediate/Middle	Classroom 214	Ceiling	Plaster	White	Flaking	25	9.3	Positive
1	2	214	Intermediate/Middle	Classroom 214	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Intermediate/Middle	Classroom 214A	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Intermediate/Middle	Classroom 214A	W1	Plaster	White	Chipping	5	14.1	Positive
1	2	214A	Intermediate/Middle	Classroom 214A	W1	Concrete	White	None	0	0.15	Negative
1	2	214A	Intermediate/Middle	Classroom 214A	W2	Plaster	White	None	0	20.9	Positive
1	2	214A	Intermediate/Middle	Classroom 214A	W2	Concrete	White	None	0	0.13	Negative
1	2	214A	Intermediate/Middle	Classroom 214A	W3	Plaster	White	Chipping	5	18.3	Positive
1	2	214A	Intermediate/Middle	Classroom 214A	W4	Plaster	White	None	0	17.5	Positive
1	2	214A	Intermediate/Middle	Classroom 214A	Ceiling	Plaster	White	Flaking	25	9.3	Positive
1	2	214A	Intermediate/Middle	Classroom 214A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	214A	Storage	Classroom 214A	Door Frame	Metal	Brown	Chipping	1	0.05	Negative
1	2	214A-1	Storage	Classroom 214A storage closet	W1	Concrete	White	None	0	0.02	Negative
1	2	214A-1	Storage	Classroom 214A storage closet	W2	Plaster	White	Cracking	2	18.7	Positive
1	2	214A-1	Storage	Classroom 214A storage closet	W3	Plaster	White	None	0	18.6	Positive
1	2	214A-1	Storage	Classroom 214A storage closet	W4	Plaster	White	None	0	22.7	Positive
1	2	214A-1	Storage	Classroom 214A storage closet	Door Frame	Metal	Brown	Chipping	1	0.08	Negative
1	2	215	Intermediate/Middle	Classroom 215	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	215	Intermediate/Middle	Classroom 215	W1	Plaster	Blue	None	0	17.3	Positive
1	2	215	Intermediate/Middle	Classroom 215	Chalkboard Ledge	Wood	Brown	Chipping	1	0.05	Negative
1	2	215	Intermediate/Middle	Classroom 215	Baseboard	Wood	Brown	None	0	0.02	Negative
1	2	215	Intermediate/Middle	Classroom 215	W2	Plaster	Blue	Chipping	1	16.3	Positive
1	2	215	Intermediate/Middle	Classroom 215	W3	Plaster	Blue	Cracking	3	15.1	Positive
1	2	215	Intermediate/Middle	Classroom 215	Window Sill	Wood	Brown	None	0	0.05	Negative
1	2	215	Intermediate/Middle	Classroom 215	Window Apron	Wood	Brown	None	0	0.05	Negative
1	2	215	Intermediate/Middle	Classroom 215	W4	Plaster	Blue	None	0	17.8	Positive
1	2	215	Intermediate/Middle	Classroom 215	Ceiling	Plaster	White	Flaking	20	16.2	Positive
1	2	215	Intermediate/Middle	Classroom 215	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Student Restrooms - Female (4-5)	Girl's Restroom	Floor	Concrete	Grey	None	0	0.03	Negative
1	2	215A	Student Restrooms - Female (4-5)	Girl's Restroom	W1	Plaster	White	Efflorescence	2	10.4	Positive
1	2	215A	Student Restrooms - Female (4-5)	Girl's Restroom	W1	Brick	Grey	None	0	0.01	Negative
1	2	215A	Student Restrooms - Female (4-5)	Girl's Restroom	W2	Plaster	White	None	0	14.7	Positive
1	2	215A	Student Restrooms - Female (4-5)	Girl's Restroom	W3	Plaster	White	None	0	0.21	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	W4	Plaster	White	Efflorescence	3	0.02	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	W4	Wood	Grey	None	0	0.01	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Ceiling	Plaster	White	Efflorescence	10	9.2	Positive
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Door Frame	Metal	Brown	Chipping	1	0.01	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Pipe	Metal	Grey	None	0	0.08	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Window Frame	Wood	Brown	Chipping	1	0.06	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Window Sill	Wood	Grey	Chipping	1	0.05	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Window Apron	Wood	Grey	None	0	0.09	Negative
1	2	215A	Ident Restrooms - Female (4-	Girl's Restroom	Radiator	Metal	Silver	Chipping	2	4.5	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	W1	Plaster	White	Cracking	6	13.4	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	W2	Plaster	White	Cracking	2	17.4	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	W3	Plaster	White	Flaking	5	18.2	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	W4	Plaster	White	Flaking	2	16	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Ceiling	Plaster	White	Cracking	2	11.2	Positive
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Shelf	Wood	White	Flaking	1	0.19	Negative
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Shelf Bracket	Wood	White	None	0	0.17	Negative
1	2	215B	Service Closets	Service Closet Adjacent to the Girls Restroom	Pipe	Metal	White	None	0	0.19	Negative
1	2	216	Storage	Storage Room 216	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	216	Storage	Storage Room 216	W1	Plaster	White	Partially Inaccessible	0	8.2	Positive
1	2	216	Storage	Storage Room 216	W2	Plaster	White	Partially Inaccessible	0	15.6	Positive
1	2	216	Storage	Storage Room 216	W3	Plaster	White	Partially Inaccessible	0	12.3	Positive
1	2	216	Storage	Storage Room 216	W4	Plaster	White	Partially Inaccessible	0	18.3	Positive
1	2	216	Storage	Storage Room 216	Ceiling	Plaster	White	Partially Inaccessible	0	10.7	Positive
1	2	218	Storage	Storage Room 218	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	2	218	Storage	Storage Room 218	W1	Plaster	Tan	Flaking	15	29	Positive
1	2	218	Storage	Storage Room 218	Baseboard	Concrete	Grey	Chipping	2	7.7	Positive
1	2	218	Storage	Storage Room 218	W2	Plaster	Tan	Flaking	25	34.7	Positive
1	2	218	Storage	Storage Room 218	W3	Plaster	Tan	Flaking	20	31.3	Positive
1	2	218	Storage	Storage Room 218	W4	Plaster	Tan	Flaking	6	36.3	Positive
1	2	218	Storage	Storage Room 218	Ceiling	Plaster	White	Flaking	5	13.1	Positive
1	2	218	Storage	Storage Room 218	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	2	217	Storage	Storage Room 217	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	217	Storage	Storage Room 217	W1	Plaster	White	Partially Inaccessible	0	18.1	Positive
1	2	217	Storage	Storage Room 217	W2	Plaster	White	Partially Inaccessible	0	14.7	Positive
1	2	217	Storage	Storage Room 217	W3	Plaster	White	Partially Inaccessible	0	16.2	Positive
1	2	217	Storage	Storage Room 217	W4	Plaster	White	Partially Inaccessible	0	11.3	Positive
1	2	217	Storage	Storage Room 217	Ceiling	Plaster	White	Partially Inaccessible	0	12.4	Positive
1	2	219	TextBook Storage Area	Book Storage Room 219	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	2	219	TextBook Storage Area	Book Storage Room 219	W1	Plaster	White	Partially Inaccessible	0	15.5	Positive
1	2	219	TextBook Storage Area	Book Storage Room 219	W2	Plaster	White	Partially Inaccessible	0	14.2	Positive
1	2	219	TextBook Storage Area	Book Storage Room 219	W3	Plaster	White	Partially Inaccessible	0	13.8	Positive
1	2	219	TextBook Storage Area	Book Storage Room 219	W4	Plaster	White	Partially Inaccessible	0	13.6	Positive

					Lead-Safe Certification Assessment Report						
					Dates: 08/31/2022						
					Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School				
					Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142				
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	2	219	TextBook Storage Area	Book Storage Room 219	Ceiling	Plaster	White	Partially Inaccessible	0	11.4	Positive
1	2	220	Restrooms, Staff - Male	Men's Restroom	Floor	Concrete	Grey	Chipping	2	0.02	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	W1	Plaster	White	Flaking	17	15.1	Positive
1	2	220	Restrooms, Staff - Male	Men's Restroom	W2	Plaster	White	Flaking	32	18	Positive
1	2	220	Restrooms, Staff - Male	Men's Restroom	Chalkboard Ledge	Wood	White	None	0	0.01	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	Pipe	Metal	White	None	0	0.13	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	W3	Plaster	White	Partially Inaccessible	10	17.4	Positive
1	2	220	Restrooms, Staff - Male	Men's Restroom	W3	Concrete	White	None	0	0.02	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	Panel	Transite	White	None	0	0.03	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	Pipe	Metal	White	Chipping	2	0.27	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	W4	Plaster	White	Cracking	40	17.6	Positive
1	2	220	Restrooms, Staff - Male	Men's Restroom	Window Sill	Wood	White	None	0	0.04	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	Window Apron	Wood	White	None	0	0.08	Negative
1	2	220	Restrooms, Staff - Male	Men's Restroom	Window Frame	Wood	White	None	0	0.11	Negative
1	2	221	Auditorium	Auditorium Balcony	Floor	No Access	No Access	No Access	N/A	N/A	No Access
1	2	221	Auditorium	Auditorium Balcony	W1	No Access	No Access	No Access	N/A	N/A	No Access
1	2	221	Auditorium	Auditorium Balcony	W2	No Access	No Access	No Access	N/A	N/A	No Access
1	2	221	Auditorium	Auditorium Balcony	W3	No Access	No Access	No Access	N/A	N/A	No Access
1	2	221	Auditorium	Auditorium Balcony	W4	No Access	No Access	No Access	N/A	N/A	No Access
1	2	221	Auditorium	Auditorium Balcony	Ceiling	Plaster	White	Flaking	240	15.6	No Access
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	Floor	Concrete	Grey	None	0	0	Negative
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	W1	Plaster	White	None	0	12.8	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	W2	Plaster	White	Cracking	10	19.2	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	W2	Plaster	White	Cracking	10	15.1	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	W3	Plaster	White	None	0	17.2	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	Radiator	Metal	Silver	Chipping	2	3.7	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	W4	Plaster	White	None	0	16.2	Positive
1	2	S21	Stairs	Stairwell adjacent to Classroom 214A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	W1	Brick	White	Flaking	40	3.9	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	W2	Brick	White	Flaking	40	5.2	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	W3	Brick	White	Flaking	40	3.7	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	W4	Brick	White	Flaking	40	5.8	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Ceiling	Concrete	White	Flaking	10	2.8	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Window Frame	Metal	Brown	Chipping	1	4.2	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Handrail	Metal	Brown	Chipping	10	3.1	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Pipe	Metal	Grey	Chipping	12	1.1	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Stringer	Concrete	Grey	Chipping	12	1.9	Positive
1	3	S34	Stairs, Fire Tower	Stairwell adjacent to Hallway H33	Tread	Concrete	Grey	Chipping	12	0.15	Negative
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	W1	Brick	White	Flaking	40	4.3	Positive
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	W2	Brick	White	Flaking	40	4.1	Positive
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	W3	Brick	White	Flaking	40	5.8	Positive
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	W4	Brick	White	Flaking	40	5.1	Positive
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Ceiling	Concrete	White	Flaking	10	4	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Window Frame	Metal	Brown	Chipping	1	3.8	Positive	
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Handrail	Metal	Brown	Chipping	10	2.7	Positive	
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Pipe	Metal	Grey	Chipping	12	1.6	Positive	
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Stringer	Concrete	Grey	Chipping	12	1.1	Positive	
1	3	S35	Stairs, Fire Tower	Stairwell adjacent to Classroom 319	Tread	Concrete	Grey	Chipping	12	0.34	Negative	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	Floor	Terracotta	N/A	N/A	N/A	N/A	N/A	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	W1	Terracotta	N/A	N/A	N/A	N/A	N/A	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	W2	Terracotta	N/A	N/A	N/A	N/A	N/A	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	W3	Terracotta	N/A	N/A	N/A	N/A	N/A	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	W4	Terracotta	N/A	N/A	N/A	N/A	N/A	
1	3	FT3	Circulation (Hallway)	3rd Floor Hallway to Fire Tower Stairwell	Ceiling	Concrete	White	None	0	N/A	N/A	
1	3	301	Intermediate/Middle	Classroom 301	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	3	301	Intermediate/Middle	Classroom 301	Baseboard	Wood	Brown	Friction	20	0	Negative	
1	3	301	Intermediate/Middle	Classroom 301	W1	Plaster	Yellow	Partially Inaccessible	0	12.5	Positive	
1	3	301	Intermediate/Middle	Classroom 301	Door Frame	Metal	Brown	Chipping	3	0	Negative	
1	3	301	Intermediate/Middle	Classroom 301	Chalkboard Ledge	Wood	Brown	Friction	12	0.1	Negative	
1	3	301	Intermediate/Middle	Classroom 301	W2	Plaster	Yellow	Partially Inaccessible	0	14.3	Positive	
1	3	301	Intermediate/Middle	Classroom 301	Chalkboard Ledge	Wood	Brown	Friction	12	0.1	Negative	
1	3	301	Intermediate/Middle	Classroom 301	W3	Plaster	Yellow	Efflorescence	5	16.5	Positive	
1	3	301	Intermediate/Middle	Classroom 301	Radiators	Metal	Silver	Chipping	2	5.9	Positive	
1	3	301	Intermediate/Middle	Classroom 301	W4	Plaster	Yellow	Partially Inaccessible	2	13.5	Positive	
1	3	301	Intermediate/Middle	Classroom 301	Chalkboard Ledge	Wood	Brown	Friction	12	0.1	Negative	
1	3	301	Intermediate/Middle	Classroom 301	Ceiling	Plaster	White	Flaking	50	10.5	Positive	
1	3	301	Intermediate/Middle	Classroom 301	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	302A	Administrative Office	Office 302	Floor	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	302A	Administrative Office	Office 302	W1	Plaster	White	Partially Inaccessible	0	14.7	Positive	
1	3	302A	Administrative Office	Office 302	Chalkboard Ledge	Wood	Brown	Friction	5	0.05	Negative	
1	3	302A	Administrative Office	Office 302	W2	Plaster	White	Chipping	2	15.1	Positive	
1	3	302A	Administrative Office	Office 302	Bulletin Board Frame	Wood	Brown	Chipping	1	0	Negative	
1	3	302A	Administrative Office	Office 302	W3	Plaster	White	Partially Inaccessible	0	13.4	Positive	
1	3	302A	Administrative Office	Office 302	Radiator	Metal	Silver	Flaking	6	5.7	Positive	
1	3	302A	Administrative Office	Office 302	Window Sill	Wood	Brown	Friction	5	0	Negative	
1	3	302A	Administrative Office	Office 302	Window Apron	Wood	Brown	Friction	5	0	Negative	
1	3	302A	Administrative Office	Office 302	W4	Plaster	White	Chipping	2	16.5	Positive	
1	3	302A	Administrative Office	Office 302	Ceiling	Plaster	White	Flaking	20	23.2	Positive	
1	3	302A	Administrative Office	Office 302	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	3	303	Intermediate/Middle	Classroom 303	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	3	303	Intermediate/Middle	Classroom 303	W1	Plaster	White	Chipping	20	13.7	Positive	
1	3	303	Intermediate/Middle	Classroom 303	Chalkboard Ledge	Wood	Brown	Friction	12	0.04	Negative	
1	3	303	Intermediate/Middle	Classroom 303	W2	Plaster	White	Chipping	5	14.4	Positive	

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	303	Intermediate/Middle	Classroom 303	W3	Plaster	White	Chipping	2	16.9	Positive
1	3	303	Intermediate/Middle	Classroom 303	Window Sill	Wood	Brown	Friction	12	0.02	Negative
1	3	303	Intermediate/Middle	Classroom 303	Window Apron	Wood	Brown	Friction	12	0	Negative
1	3	303	Intermediate/Middle	Classroom 303	Radiators	Metal	Silver	Flaking	12	3.5	Positive
1	3	303	Intermediate/Middle	Classroom 303	W4	Plaster	White	Chipping	20	15.4	Positive
1	3	303	Intermediate/Middle	Classroom 303	Ceiling	Plaster	White	Flaking	50	17.2	Positive
1	3	303	Intermediate/Middle	Classroom 303	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303A	Intermediate/Middle	Classroom 303A	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	303A	Intermediate/Middle	Classroom 303A	Cove Base	Concrete	Black	Friction	20	0	Negative
1	3	303A	Intermediate/Middle	Classroom 303A	W1	Plaster	Blue	Flaking	10	12.8	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	Door Frame	Metal	Brown	Friction	4	0	Negative
1	3	303A	Intermediate/Middle	Classroom 303A	W2	Plaster	Blue	Chipping	5	15.1	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	W2	CMU	Blue	None	0	0.15	Negative
1	3	303A	Intermediate/Middle	Classroom 303A	Door Frame	Metal	Brown	Friction	4	0	Negative
1	3	303A	Intermediate/Middle	Classroom 303A	W3	Plaster	Blue	Flaking	10	19.5	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	Radiators	Metal	Silver	Flaking	12	3.6	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	W4	Plaster	Blue	Chipping	5	16.1	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	Ceiling	Plaster	White	Flaking	20	11.6	Positive
1	3	303A	Intermediate/Middle	Classroom 303A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	Floor	Concrete	Grey	Chipping	10	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W1	Plaster	White	None	0	5.6	Positive
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W1	Brick	Grey	None	0	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W2	Plaster	White	Efflorescence	64	5.8	Positive
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W2	Brick	Grey	None	0	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W3	Plaster	White	None	0	6.9	Positive
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W3	Brick	Grey	None	0	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	Window Sill	Wood	Brown	Friction	4	0.13	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W4	Plaster	White	Efflorescence	20	7.7	Positive
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W4	Brick	Grey	None	0	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	W4	CMU	Grey	None	0	0	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	Pipe	Metal	White	Chipping	1	0.17	Negative
1	3	303B	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 301	Ceiling	Plaster	White	Flaking	120	10.9	Positive
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	Floor	Concrete	Grey	Flaking	20	0.11	Negative
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	W1	Plaster	Yellow	Flaking	10	4.1	Positive
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	W2	Plaster	Yellow	Flaking	6	8.2	Positive
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	W3	Plaster	Yellow	Flaking	12	6.9	Positive
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	W4	Plaster	Yellow	Flaking	5	5.7	Positive
1	3	303SC	Service Closets	Service Closet adjacent Boy's Restroom	Ceiling	Plaster	White	Flaking	15	8.5	Positive
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303PC	Pipe Chase	Pipe Chase Adjacent to Boy's Restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	303C	Storage	Classroom 303A Storage	Floor	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	303C	Storage	Classroom 303A Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303C	Storage	Classroom 303A Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303C	Storage	Classroom 303A Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303C	Storage	Classroom 303A Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	3	303C	Storage	Classroom 303A Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	3	304	Intermediate/Middle	Classroom 304	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	3	304	Intermediate/Middle	Classroom 304	W1	Plaster	Blue	Partially Inaccessible	0	14.3	Positive
1	3	304	Intermediate/Middle	Classroom 304	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	304	Intermediate/Middle	Classroom 304	W2	Plaster	Blue	Partially Inaccessible	0	12.8	Positive
1	3	304	Intermediate/Middle	Classroom 304	Bulletin Board Frame	Wood	Brown	Chipping	2	0.06	Negative
1	3	304	Intermediate/Middle	Classroom 304	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	304	Intermediate/Middle	Classroom 304	W3	Plaster	Blue	Flaking	2	13.5	Positive
1	3	304	Intermediate/Middle	Classroom 304	Window Sill	Wood	Brown	Friction	10	0.05	Negative
1	3	304	Intermediate/Middle	Classroom 304	Window Apron	Wood	Brown	Friction	10	0	Negative
1	3	304	Intermediate/Middle	Classroom 304	Radiators	Metal	Silver	Flaking	12	3.1	Positive
1	3	304	Intermediate/Middle	Classroom 304	W4	Plaster	Blue	Chipping	2	14.6	Positive
1	3	304	Intermediate/Middle	Classroom 304	Bulletin Board Frame	Wood	Brown	Chipping	2	0.13	Negative
1	3	304	Intermediate/Middle	Classroom 304	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	304	Intermediate/Middle	Classroom 304	Ceiling	Plaster	White	Flaking	100	13.1	Positive
1	3	304	Intermediate/Middle	Classroom 304	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305	Intermediate/Middle	Classroom 305	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305	Intermediate/Middle	Classroom 305	W1	Plaster	Blue	Partially Inaccessible	0	8.5	Positive
1	3	305	Intermediate/Middle	Classroom 305	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	3	305	Intermediate/Middle	Classroom 305	W2	Plaster	Blue	Partially Inaccessible	0	19.6	Positive
1	3	305	Intermediate/Middle	Classroom 305	Pipe	Metal	White	Chipping	1	0.1	Negative
1	3	305	Intermediate/Middle	Classroom 305	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	3	305	Intermediate/Middle	Classroom 305	Duct	Metal	White	Chipping	1	15.3	Positive
1	3	305	Intermediate/Middle	Classroom 305	W3	Plaster	Blue	Partially Inaccessible	0	13.4	Positive
1	3	305	Intermediate/Middle	Classroom 305	Window Sill	Wood	Brown	Friction	5	0	Negative
1	3	305	Intermediate/Middle	Classroom 305	Window Apron	Wood	Brown	Friction	5	0	Negative
1	3	305	Intermediate/Middle	Classroom 305	Radiators	Metal	Silver	Flaking	6	8	Positive
1	3	305	Intermediate/Middle	Classroom 305	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	3	305	Intermediate/Middle	Classroom 305	W4	Plaster	Blue	Partially Inaccessible	0	15.2	Positive
1	3	305	Intermediate/Middle	Classroom 305	Ceiling	Plaster	White	Flaking	20	10.9	Positive
1	3	305	Intermediate/Middle	Classroom 305	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305	W1	Plaster	White	None	0	14.2	Positive
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305	Chalkboard Ledge	Wood	Brown	Chipping	2	0.08	Negative

					Lead-Safe Certification Assessment Report									
					Dates: 08/31/2022									
					Inspector Name and Certificate Number: Ryan Hutsell 059512									
					Inspection Company: Synertech									
					1130 Tilden Middle School									
					6601 Elmwood Avenue, Philadelphia, PA 19142									
E	l	e	m	e										
n	e	n	t	l	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
t	r	o	r	l										
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				W2	Plaster	White	None	0	17.9	Positive
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Chalkboard Ledge	Wood	Brown	Chipping	2	0	Negative
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				W3	Plaster	White	None	0	13.1	Positive
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Chalkboard Ledge	Wood	Brown	Chipping	2	0	Negative
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Window Sill	Wood	Brown	Chipping	2	0.17	Negative
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Window Apron	Wood	Brown	Chipping	2	0	Negative
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Radiator	Metal	Silver	Flaking	4	5.3	Positive
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				W4	Plaster	White	Flaking	4	15.1	Positive
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Chalkboard Ledge	Wood	Brown	Chipping	2	0.11	Negative
1	3	305A	Restrooms, Staff - Male	Men's Restroom next to Classroom 305				Ceiling	Plaster	White	None	0	N/A	N/A
1	3	306	Intermediate/Middle	Classroom 306				Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	306	Intermediate/Middle	Classroom 306				W1	Plaster	Blue	Partially Inaccessible	0	16.2	Positive
1	3	306	Intermediate/Middle	Classroom 306				W2	Plaster	Blue	Partially Inaccessible	0	14.3	Positive
1	3	306	Intermediate/Middle	Classroom 306				W3	Plaster	Blue	Partially Inaccessible	0	11.9	Positive
1	3	306	Intermediate/Middle	Classroom 306				Window Sill	Wood	Brown	Friction	10	0.04	Negative
1	3	306	Intermediate/Middle	Classroom 306				Window Apron	Wood	Brown	Friction	10	0.04	Negative
1	3	306	Intermediate/Middle	Classroom 306				Radiators	Metal	Silver	Flaking	12	5.4	Positive
1	3	306	Intermediate/Middle	Classroom 306				W4	Plaster	Blue	Partially Inaccessible	0	12.7	Positive
1	3	306	Intermediate/Middle	Classroom 306				Ceiling	Plaster	White	Partially Inaccessible	0	12.2	Positive
1	3	307	Intermediate/Middle	Classroom 307				Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	307	Intermediate/Middle	Classroom 307				Baseboard	Wood	Brown	Friction	20	0	Negative
1	3	307	Intermediate/Middle	Classroom 307				W1	Plaster	White	Chipping	3	14.3	Positive
1	3	307	Intermediate/Middle	Classroom 307				W2	Plaster	White	Flaking	4	15.1	Positive
1	3	307	Intermediate/Middle	Classroom 307				W3	Plaster	White	Flaking	20	12.3	Positive
1	3	307	Intermediate/Middle	Classroom 307				Window Sill	Wood	Brown	Friction	12	0	Negative
1	3	307	Intermediate/Middle	Classroom 307				Window Apron	Wood	Brown	Friction	12	0	Negative
1	3	307	Intermediate/Middle	Classroom 307				Radiators	Metal	Silver	Flaking	12	3.7	Positive
1	3	307	Intermediate/Middle	Classroom 307				W4	Plaster	White	None	0	18.2	Positive
1	3	307	Intermediate/Middle	Classroom 307				Chalkboard Ledge	Wood	Brown	Chipping	1	0.07	Negative
1	3	307	Intermediate/Middle	Classroom 307				Ceiling	Plaster	White	Flaking	20	18.7	Positive
1	3	307	Intermediate/Middle	Classroom 307				Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	308	Intermediate/Middle	Classroom 308				Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	308	Intermediate/Middle	Classroom 308				W1	Plaster	White	Flaking	18	14.4	Positive
1	3	308	Intermediate/Middle	Classroom 308				Chalkboard Ledge	Wood	Brown	Friction	12	0.08	Negative
1	3	308	Intermediate/Middle	Classroom 308				W2	Plaster	White	Flaking	5	16.8	Positive
1	3	308	Intermediate/Middle	Classroom 308				Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	308	Intermediate/Middle	Classroom 308				W3	Plaster	White	Flaking	4	20.1	Positive
1	3	308	Intermediate/Middle	Classroom 308				Window Sill	Wood	Brown	Friction	8	0.11	Negative
1	3	308	Intermediate/Middle	Classroom 308				Window Apron	Wood	Brown	Friction	2	0	Negative
1	3	308	Intermediate/Middle	Classroom 308				Radiators	Metal	Silver	Flaking	12	5.2	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	308	Intermediate/Middle	Classroom 308	W4	Plaster	White	Flaking	1	15.9	Positive
1	3	308	Intermediate/Middle	Classroom 308	Chalkboard Ledge	Wood	Brown	Friction	12	0.12	Negative
1	3	308	Intermediate/Middle	Classroom 308	Ceiling	Plaster	White	Flaking	35	12.7	Positive
1	3	308	Intermediate/Middle	Classroom 308	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W1	Plaster	White	Chipping	3	15.4	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W1	Plaster	Yellow	Partially Inaccessible	0	11.7	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	Partition Divider	Wood	White	Friction	10	0.11	Negative
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W2	Plaster	White	Partially Inaccessible	0	16.2	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W3	Plaster	White	Efflorescence	6	10.3	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W3	Plaster	Yellow	Partially Inaccessible	0	14.3	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	Radiator Cover	Metal	Brown	Chipping	4	0.12	Negative
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	W4	Plaster	White	Flaking	8	9.2	Positive
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	Chalkboard Ledge	Wood	Brown	Friction	12	0.07	Negative
1	3	309A/309B/310	Intermediate/Middle	Classroom 309/310	Ceiling	Plaster	White	Partially Inaccessible	0	14.6	Positive
1	3	311	Intermediate/Middle	Classroom 311	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	311	Intermediate/Middle	Classroom 311	W1	Plaster	Brown	Flaking	4	14.3	Positive
1	3	311	Intermediate/Middle	Classroom 311	Duct	Metal	Brown	None	0	14.3	Positive
1	3	311	Intermediate/Middle	Classroom 311	W2	Plaster	Brown	Chipping	1	19.2	Positive
1	3	311	Intermediate/Middle	Classroom 311	Chalkboard Ledge	Wood	Brown	Friction	10	0.06	Negative
1	3	311	Intermediate/Middle	Classroom 311	W3	Plaster	Brown	Efflorescence	8	12.7	Positive
1	3	311	Intermediate/Middle	Classroom 311	Window Sill	Wood	Brown	Friction	12	0.5	Negative
1	3	311	Intermediate/Middle	Classroom 311	Window Apron	Wood	Brown	Friction	12	0.5	Negative
1	3	311	Intermediate/Middle	Classroom 311	Radiators	Metal	Silver	Flaking	12	5.7	Positive
1	3	311	Intermediate/Middle	Classroom 311	W4	Plaster	Brown	Partially Inaccessible	0	12.5	Positive
1	3	311	Intermediate/Middle	Classroom 311	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	3	311	Intermediate/Middle	Classroom 311	Ceiling	Plaster	White	Partially Inaccessible	0	10.8	Positive
1	3	312	Intermediate/Middle	Classroom 312	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	312	Intermediate/Middle	Classroom 312	W1	Plaster	White	Chipping	4	14	Positive
1	3	312	Intermediate/Middle	Classroom 312	Chalkboard Ledge	Wood	Brown	Friction	10	0.1	Negative
1	3	312	Intermediate/Middle	Classroom 312	W2	Plaster	White	Chipping	2	13.6	Positive
1	3	312	Intermediate/Middle	Classroom 312	Chalkboard Ledge	Wood	Brown	Friction	10	0.04	Negative
1	3	312	Intermediate/Middle	Classroom 312	W3	Plaster	White	Efflorescence	16	12.9	Positive
1	3	312	Intermediate/Middle	Classroom 312	Window Sill	Wood	Brown	Friction	12	0	Negative
1	3	312	Intermediate/Middle	Classroom 312	Window Apron	Wood	Brown	Friction	12	0	Negative
1	3	312	Intermediate/Middle	Classroom 312	Radiators	Metal	Silver	Flaking	12	3.5	Positive
1	3	312	Intermediate/Middle	Classroom 312	W4	Plaster	White	Partially Inaccessible	0	17.4	Positive
1	3	312	Intermediate/Middle	Classroom 312	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	3	312	Intermediate/Middle	Classroom 312	Ceiling	Plaster	White	Partially Inaccessible	0	15.5	Positive
1	3	313	Intermediate/Middle	Classroom 313	Floor	Wood	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	313	Intermediate/Middle	Classroom 313	Baseboard	Wood	Brown	Friction	20	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	W1	Plaster	Blue	Chipping	5	13.3	Positive
1	3	313	Intermediate/Middle	Classroom 313	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	W2	Plaster	Blue	Flaking	4	10.7	Positive
1	3	313	Intermediate/Middle	Classroom 313	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	W3	Plaster	Blue	Flaking	30	16.2	Positive
1	3	313	Intermediate/Middle	Classroom 313	Window Sill	Wood	Brown	Friction	12	0.12	Negative
1	3	313	Intermediate/Middle	Classroom 313	Window Apron	Wood	Brown	None	0	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	Radiators	Metal	Silver	Flaking	12	3.8	Positive
1	3	313	Intermediate/Middle	Classroom 313	W4	Plaster	Blue	Chipping	1	17.1	Positive
1	3	313	Intermediate/Middle	Classroom 313	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	Bulletin Board Frame	Wood	Brown	Chipping	1	0	Negative
1	3	313	Intermediate/Middle	Classroom 313	Ceiling	Plaster	White	Flaking	20	13.2	Positive
1	3	313	Intermediate/Middle	Classroom 313	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	314	Intermediate/Middle	Classroom 314	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	314	Intermediate/Middle	Classroom 314	Baseboard	Wood	Brown	Friction	20	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	W1	Plaster	Yellow	Partially Inaccessible	0	15.5	Positive
1	3	314	Intermediate/Middle	Classroom 314	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Chalkboard Frame	Wood	Brown	Chipping	2	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Door Frame	Wood	Brown	Friction	2	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	W2	Plaster	Yellow	Partially Inaccessible	0	14.9	Positive
1	3	314	Intermediate/Middle	Classroom 314	Radiators	Metal	Silver	Flaking	6	5.9	Positive
1	3	314	Intermediate/Middle	Classroom 314	Window Frame	Wood	Brown	Chipping	2	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Window Sill	Wood	Brown	Friction	12	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Window Apron	Wood	Brown	Friction	1	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	W3	Plaster	Yellow	Flaking	18	15.2	Positive
1	3	314	Intermediate/Middle	Classroom 314	W4	Plaster	Yellow	Flaking	2	15.5	Positive
1	3	314	Intermediate/Middle	Classroom 314	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Chalkboard Frame	Wood	Brown	Chipping	1	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Door Frame	Wood	Brown	Friction	2	0.08	Negative
1	3	314	Intermediate/Middle	Classroom 314	Door	Wood	Brown	Friction	2	0	Negative
1	3	314	Intermediate/Middle	Classroom 314	Ceiling	Plaster	White	Flaking	50	10.9	Positive
1	3	314	Intermediate/Middle	Classroom 314	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	315	Administrative Office	Office 315	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	315	Administrative Office	Office 315	W1	Plaster	Tan	Partially Inaccessible	0	6.1	Positive
1	3	315	Administrative Office	Office 315	W1	Plaster	White	Partially Inaccessible	0	9.2	Positive
1	3	315	Administrative Office	Office 315	Chalkboard Ledge	Wood	White	Friction	2	0	Negative
1	3	315	Administrative Office	Office 315	W2	Plaster	Tan	Partially Inaccessible	0	11.9	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	315	Administrative Office	Office 315	W2	Plaster	White	Partially Inaccessible	0	14.1	Positive
1	3	315	Administrative Office	Office 315	Chalkboard Ledge	Wood	White	Friction	2	0	Negative
1	3	315	Administrative Office	Office 315	W3	Plaster	Tan	Partially Inaccessible	0	5.9	Positive
1	3	315	Administrative Office	Office 315	W3	Plaster	White	Partially Inaccessible	0	5.1	Positive
1	3	315	Administrative Office	Office 315	Chalkboard Ledge	Wood	White	Friction	2	0	Negative
1	3	315	Administrative Office	Office 315	Radiators	Metal	Silver	Flaking	8	4.8	Positive
1	3	315	Administrative Office	Office 315	W4	Plaster	Tan	Partially Inaccessible	0	16.2	Positive
1	3	315	Administrative Office	Office 315	W4	Plaster	White	Partially Inaccessible	0	13.8	Positive
1	3	315	Administrative Office	Office 315	Chalkboard Ledge	Wood	White	Friction	2	0	Negative
1	3	315	Administrative Office	Office 315	Ceiling	Plaster	White	Flaking	50	14.9	Positive
1	3	315	Administrative Office	Office 315	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	317	Intermediate/Middle	Classroom 316	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317	Intermediate/Middle	Classroom 316	Baseboard	Wood	Brown	Friction	20	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	W1	Plaster	Blue	Holes	2	14.1	Positive
1	3	317	Intermediate/Middle	Classroom 316	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	W2	Plaster	Blue	Chipping	4	18.2	Positive
1	3	317	Intermediate/Middle	Classroom 316	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	W3	Plaster	Blue	Efflorescence	22	14.6	Positive
1	3	317	Intermediate/Middle	Classroom 316	Window Sill	Wood	Brown	Friction	24	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	Window Apron	Wood	Brown	Friction	6	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	Radiators	Metal	Silver	Flaking	12	5.7	Positive
1	3	317	Intermediate/Middle	Classroom 316	W4	Plaster	Blue	Chipping	2	15.5	Positive
1	3	317	Intermediate/Middle	Classroom 316	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	317	Intermediate/Middle	Classroom 316	Ceiling	Plaster	White	Flaking	20	11.2	Positive
1	3	317	Intermediate/Middle	Classroom 316	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	317	Intermediate/Middle	Classroom 317	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317	Intermediate/Middle	Classroom 317	W1	Plaster	Blue	Partially Inaccessible	0	12.6	Positive
1	3	317	Intermediate/Middle	Classroom 317	Chalkboard Ledge	Wood	Brown	Friction	8	0	Negative
1	3	317	Intermediate/Middle	Classroom 317	W2	Plaster	Blue	Partially Inaccessible	0	10.9	Positive
1	3	317	Intermediate/Middle	Classroom 317	Chalkboard Ledge	Wood	Brown	Friction	8	0	Negative
1	3	317	Intermediate/Middle	Classroom 317	W3	Plaster	Blue	Efflorescence	4	18.2	Positive
1	3	317	Intermediate/Middle	Classroom 317	Radiators	Metal	Silver	Flaking	6	3.1	Positive
1	3	317	Intermediate/Middle	Classroom 317	Window Sill	Wood	Brown	Friction	10	0	Negative
1	3	317	Intermediate/Middle	Classroom 317	Window Apron	Wood	Brown	Friction	10	0	Negative
1	3	317	Intermediate/Middle	Classroom 317	W4	Plaster	Blue	None	0	14.9	Positive
1	3	317	Intermediate/Middle	Classroom 317	Chalkboard Ledge	Wood	Brown	Friction	8	0	Negative
1	3	317	Intermediate/Middle	Classroom 317	Ceiling	Plaster	White	Flaking	665	10	Positive
1	3	317	Intermediate/Middle	Classroom 317	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	W1	Plaster	White	Flaking	4	13.2	Positive
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Bulletin Board Frame	Wood	White	Chipping	2	0	Negative
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Chalkboard Ledge	Wood	White	Friction	2	0	Negative
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	W2	Plaster	White	Flaking	16	16.9	Positive
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	W3	Plaster	White	Flaking	6	17.4	Positive
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Window Sill	Wood	Brown	Friction	6	0.12	Negative
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Window Apron	Wood	Brown	Friction	6	0	Negative
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Radiators	Metal	Silver	Flaking	6	5.1	Positive
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	W4	Plaster	White	Flaking	4	20.4	Positive
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Mirror Frame	Wood	White	Chipping	1	0	Negative
1	3	317A	Restrooms, Staff - Female	Women's Staff Restroom Lounge	Ceiling	Plaster	White	Flaking	40	16.1	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	Floor	Concrete	Grey	None	0	0.3	Negative
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	W1	Plaster	White	Flaking	12	13.2	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	W2	Plaster	White	Flaking	5	20.5	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	Window Sill	Wood	Brown	Friction	2	0	Negative
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	Window Apron	Wood	Brown	Friction	2	0	Negative
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	Radiators	Metal	Silver	Flaking	6	4.5	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	W3	Plaster	White	Flaking	15	19.2	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	W4	Plaster	White	Flaking	2	15.6	Positive
1	3	317B	Restrooms, Staff - Female	Women's Staff Lounge	Ceiling	Plaster	White	Flaking	36	19.4	Positive
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	W1	CMU	Green	None	0	0.14	Negative
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	Door Frame	Metal	Green	Friction	2	0.1	Negative
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	W2	Plaster	Green	Chipping	1	23.5	Positive
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	W3	Plaster	Green	Chipping	2	15.6	Positive
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	W4	Plaster	Green	None	0	16.5	Positive
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	Radiator	Metal	Tan	Chipping	2	0.25	Negative
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	Ceiling	Plaster	White	Holes	4	10.2	Positive
1	3	318A-1	Intermediate/Middle	Classroom 318A Closet	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	318A	Intermediate/Middle	Classroom 318A	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	318A	Intermediate/Middle	Classroom 318A	Cove Base	Concrete	Black	Friction	20	0	Negative
1	3	318A	Intermediate/Middle	Classroom 318A	W1	Plaster	White	Flaking	18	16.1	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	Door Frame	Metal	Brown	Friction	5	0	Negative
1	3	318A	Intermediate/Middle	Classroom 318A	W2	Plaster	White	Chipping	2	12.4	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	W2	CMU	White	None	0	0.12	Negative
1	3	318A	Intermediate/Middle	Classroom 318A	Door Frame	Metal	Brown	Friction	5	0	Negative
1	3	318A	Intermediate/Middle	Classroom 318A	Pipe	Metal	Brown	Chipping	1	0.14	Negative
1	3	318A	Intermediate/Middle	Classroom 318A	W3	Plaster	White	Flaking	10	15.2	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	Radiators	Metal	Silver	Flaking	12	6.2	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	W4	Plaster	White	Chipping	1	13.4	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	Ceiling	Plaster	White	Flaking	20	14.9	Positive
1	3	318A	Intermediate/Middle	Classroom 318A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	318	Intermediate/Middle	Classroom 318	Floor	Wood	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	318	Intermediate/Middle	Classroom 318	Baseboard	Wood	Brown	Friction	20	0	Negative
1	3	318	Intermediate/Middle	Classroom 318	W1	Plaster	White	Chipping	2	16.3	Positive
1	3	318	Intermediate/Middle	Classroom 318	Chalkboard Ledge	Wood	Brown	Friction	2	0	Negative
1	3	318	Intermediate/Middle	Classroom 318	W2	Plaster	White	Chipping	1	10.8	Positive
1	3	318	Intermediate/Middle	Classroom 318	Chalkboard Ledge	Wood	Brown	Friction	2	0	Negative
1	3	318	Intermediate/Middle	Classroom 318	W3	Plaster	White	Chipping	4	14.9	Positive
1	3	318	Intermediate/Middle	Classroom 318	Window Sill	Wood	Brown	Friction	12	0	Negative
1	3	318	Intermediate/Middle	Classroom 318	Window Apron	Wood	Brown	Friction	12	0	Negative
1	3	318	Intermediate/Middle	Classroom 318	Radiators	Metal	Silver	Flaking	12	2.6	Positive
1	3	318	Intermediate/Middle	Classroom 318	W4	Plaster	White	Chipping	3	20.8	Positive
1	3	318	Intermediate/Middle	Classroom 318	Chalkboard Ledge	Wood	Brown	Friction	2	0.1	Negative
1	3	318	Intermediate/Middle	Classroom 318	Ceiling	Plaster	White	Flaking	30	19.1	Positive
1	3	318	Intermediate/Middle	Classroom 318	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	319	Intermediate/Middle	Classroom 319	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	319	Intermediate/Middle	Classroom 319	W1	Plaster	White	Flaking	4	18.2	Positive
1	3	319	Intermediate/Middle	Classroom 319	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	319	Intermediate/Middle	Classroom 319	W2	Plaster	White	Flaking	4	14.3	Positive
1	3	319	Intermediate/Middle	Classroom 319	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	319	Intermediate/Middle	Classroom 319	W3	Plaster	White	Flaking	32	13.9	Positive
1	3	319	Intermediate/Middle	Classroom 319	Window Sill	Wood	Brown	Friction	12	0	Negative
1	3	319	Intermediate/Middle	Classroom 319	Window Apron	Wood	Brown	Friction	12	0	Negative
1	3	319	Intermediate/Middle	Classroom 319	Radiators	Metal	Silver	Flaking	12	5.5	Positive
1	3	319	Intermediate/Middle	Classroom 319	W4	Plaster	White	Flaking	16	18.8	Positive
1	3	319	Intermediate/Middle	Classroom 319	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	3	319	Intermediate/Middle	Classroom 319	Ceiling	Plaster	White	Flaking	20	16.2	Positive
1	3	319	Intermediate/Middle	Classroom 319	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	Floor	Concrete	Grey	None	0	0	Negative
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W1	Plaster	White	Flaking	10	9.7	Positive
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W1	Brick	Grey	None	0	0	Negative
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W2	Plaster	White	None	0	12.8	Positive
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W2	Brick	Grey	None	0	0	Negative
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W3	Plaster	White	None	0	11.2	Positive
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W3	Brick	Grey	None	0	0	Negative
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	Radiator	Metal	Silver	Chipping	1	2.7	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W4	Plaster	White	Efflorescence	40	16.4	Positive
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	W4	Brick	Grey	None	0	0	Negative
1	3	319A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 318	Ceiling	Plaster	White	Efflorescence	20	9.9	Positive
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	Floor	Concrete	Grey	Chipping	16	0	Negative
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	W1	Plaster	White	Flaking	20	13.4	Positive
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	W2	Plaster	White	Flaking	20	15.2	Positive
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	W3	Plaster	White	Flaking	20	10.9	Positive
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	Pipe	Metal	White	Chipping	6	0.5	Negative
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	W4	Plaster	White	Flaking	20	11.8	Positive
1	3	319B	Service Closets	Service Closet adjacent Girls' Restroom	Ceiling	Plaster	White	Flaking	20	14.1	Positive
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	319PC	Pipe Chase	Pipe Chase Adjacent to Girl's Restroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	STORAGE	Storage	Room behind Elevator	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	STORAGE	Storage	Room behind Elevator	W1	Plaster	Blue	None	0	14.3	Positive
1	3	STORAGE	Storage	Room behind Elevator	W2	Plaster	Blue	None	0	18.2	Positive
1	3	STORAGE	Storage	Room behind Elevator	W3	Plaster	Blue	None	0	11.6	Positive
1	3	STORAGE	Storage	Room behind Elevator	W4	Plaster	Blue	None	0	17.2	Positive
1	3	STORAGE	Storage	Room behind Elevator	Window Frame	Wood	Brown	Chipping	2	0	Negative
1	3	STORAGE	Storage	Room behind Elevator	Window Apron	Wood	Brown	Chipping	1	0	Negative
1	3	STORAGE	Storage	Room behind Elevator	Radiator	Metal	Silver	Flaking	6	2.5	Positive
1	3	STORAGE	Storage	Room behind Elevator	Ceiling	Plaster	White	Flaking	130	12.4	Positive
1	3	321A	Mechanical Room	Fan Room 321A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	321A	Mechanical Room	Fan Room 321A	W1	Plaster	White	Flaking	25	14.8	Positive
1	3	321A	Mechanical Room	Fan Room 321A	W2	Plaster	White	Flaking	25	16.2	Positive
1	3	321A	Mechanical Room	Fan Room 321A	W3	Plaster	White	Flaking	25	19.4	Positive
1	3	321A	Mechanical Room	Fan Room 321A	W4	Plaster	White	Flaking	25	19.5	Positive
1	3	321A	Mechanical Room	Fan Room 321A	Ceiling	Plaster	White	Flaking	10	14.2	Positive
1	3	322	Storage	Storage Room 322	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	322	Storage	Storage Room 322	W1	Plaster	White	Flaking	5	13.4	Positive
1	3	322	Storage	Storage Room 322	W2	Plaster	White	Flaking	5	15.2	Positive
1	3	322	Storage	Storage Room 322	W3	Plaster	White	Partially Inaccessible	0	18.9	Positive
1	3	322	Storage	Storage Room 322	Pipe	Metal	White	Flaking	12	2.5	Positive
1	3	322	Storage	Storage Room 322	Radiator	Metal	Silver	Flaking	6	4.2	Positive
1	3	322	Storage	Storage Room 322	W4	Plaster	White	Holes	2	17.6	Positive
1	3	322	Storage	Storage Room 322	Ceiling	Plaster	White	Flaking	60	13.1	Positive
1	3	323	Storage	Room Across Hallway from Storage 322	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	323	Storage	Room Across Hallway from Storage 322	W1	Plaster	White	Flaking	100	15.5	Positive
1	3	323	Storage	Room Across Hallway from Storage 322	W2	Plaster	White	Flaking	100	16.5	Positive
1	3	323	Storage	Room Across Hallway from Storage 322	W3	Plaster	White	Flaking	100	14.9	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	323	Storage	Room Across Hallway from Storage 322	W4	Plaster	White	Flaking	100	18.2	Positive
1	3	323	Storage	Room Across Hallway from Storage 322	Ceiling	Plaster	White	Flaking	100	13.7	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W1	Plaster	White	Flaking	36	15.4	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W1	Plaster	Pink	Chipping	18	17.2	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W2	Plaster	White	Flaking	12	13.9	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W2	Plaster	Pink	None	0	16.8	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	Pipe	Metal	White	Flaking	2	20.4	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W3	Plaster	White	Flaking	12	20.8	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W3	Plaster	Pink	Flaking	18	16.4	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	Radiator	Metal	Silver	Flaking	6	4.2	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W4	Plaster	White	Flaking	4	13.1	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	W4	Plaster	Pink	Flaking	2	19.7	Positive
1	3	324	Storage	Storage Room 324 - Computer Equipment Storage	Ceiling	Plaster	White	Flaking	200	21.8	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	325	Storage	Room Across Hallway from Storage 324	W1	Plaster	White	Partially Inaccessible	0	12.8	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	W2	Plaster	White	Partially Inaccessible	0	16.4	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	W3	Plaster	White	Flaking	20	10.9	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	Radiator	Metal	Silver	Flaking	6	3.9	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	W4	Plaster	White	Flaking	20	18.8	Positive
1	3	325	Storage	Room Across Hallway from Storage 324	Ceiling	Plaster	White	Flaking	40	14.3	Positive
1	3	321	Storage	Storage adjacent Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	321	Storage	Storage adjacent Kitchen	W1	Plaster	White	Flaking	100	10.5	Positive
1	3	321	Storage	Storage adjacent Kitchen	W2	Plaster	White	Flaking	100	18.2	Positive
1	3	321	Storage	Storage adjacent Kitchen	W3	Plaster	White	Flaking	100	16.9	Positive
1	3	321	Storage	Storage adjacent Kitchen	W4	Plaster	White	Flaking	100	14.3	Positive
1	3	321	Storage	Storage adjacent Kitchen	Ceiling	Plaster	White	Flaking	150	12.2	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	Floor	Concrete	Brown	Chipping	10	0	Negative
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	W1	Plaster	White	Chipping	5	16.2	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	Radiators	Metal	Silver	Chipping	12	4.3	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	W2	Plaster	White	None	0	19.2	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	Radiators	Metal	Silver	Chipping	12	5.2	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	W3	Plaster	White	Chipping	5	14.3	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	W4	Plaster	White	None	0	17.1	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	Ceiling	Plaster	White	Flaking	25	8.1	Positive
1	3	H31	Circulation (Hallway)	Hallway from Classrooms 306 to 314	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	Floor	Concrete	Brown	Chipping	10	0	Negative
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	W1	Plaster	N/A	N/A	N/A	N/A	N/A
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	W2	Plaster	White	Chipping	4	20.1	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	Radiators	Metal	Silver	Chipping	12	1.8	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	W3	Plaster	White	None	0	12.9	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	W4	Plaster	White	Chipping	4	15.8	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	Radiators	Metal	Silver	Chipping	12	4.4	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	Ceiling	Plaster	White	Efflorescence	8	12.1	Positive
1	3	H32	Circulation (Hallway)	Hallway from Classrooms 301 to 306	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Floor	Concrete	Brown	Chipping	10	0	Negative
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	W1	Plaster	White	Efflorescence	24	14.2	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Radiators	Metal	Silver	Flaking	24	3.8	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	W2	Plaster	White	None	0	11.9	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	W3	Plaster	White	None	0	17.3	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Radiators	Metal	Silver	Flaking	24	2.7	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	W4	Plaster	White	None	0	15	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Ceiling	Plaster	White	Flaking	100	10.6	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Ceiling	Plaster	White	Efflorescence	175	13.5	Positive
1	3	H33	Circulation (Hallway)	Hallway from Classrooms 301 to 319	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Floor	Concrete	Brown	Chipping	20	0	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	W2	Plaster	Yellow	Chipping	4	16.9	Positive
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Door Frames	Metal	Brown	Chipping	12	0.07	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Elevator Door Frame	Metal	Tan	Chipping	4	0.12	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Elevator Door	Metal	Tan	Chipping	1	0	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	W3	Plaster	Yellow	Chipping	2	15.4	Positive
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Radiators	Metal	Silver	Chipping	8	3.2	Positive
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Radiator Cover	Metal	Brown	Chipping	2	0	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	W4	Plaster	Yellow	Chipping	2	13.8	Positive
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Door Frames	Metal	Brown	Chipping	12	0.12	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Doors	Metal	Brown	Chipping	4	0	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Transom Panel	Metal	Brown	Chipping	1	0	Negative
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Ceiling	Plaster	White	Efflorescence	12	10.4	Positive
1	3	H34	Circulation (Hallway)	Hallway from Classrooms 314 to 319	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Stringer	Concrete	Grey	Chipping	2	4.2	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Tread	Concrete	Grey	Chipping	2	7.1	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Handrail	Metal	Grey	Chipping	2	1.5	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Baluster	Concrete	Grey	Chipping	2	3.6	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Newel Post	Concrete	Grey	Chipping	2	2.9	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	W1	Plaster	White	Flaking	12	10.9	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	W2	Plaster	White	Flaking	16	16.1	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	W3	Plaster	White	Flaking	8	15.7	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	W4	Plaster	White	Flaking	10	15.9	Positive
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S32	Stairs	Stairwell adjacent to Classroom 303A	Stair Soffit	Metal	Grey	Chipping	2	4.2	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	W1	Brick	White	Flaking	40	6.5	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	W2	Brick	White	Flaking	40	7.2	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	W3	Brick	White	Flaking	40	6.3	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	W4	Brick	White	Flaking	40	3.9	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Ceiling	Concrete	White	Flaking	10	5.7	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Window Frame	Metal	Brown	Chipping	1	2.8	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Handrail	Metal	Brown	Chipping	10	3.7	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Pipe	Metal	Grey	Chipping	12	1.9	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Stringer	Concrete	Grey	Chipping	12	2.1	Positive
1	3	S33	Stairs, Fire Tower	Stairwell adjacent to Classroom 301	Tread	Concrete	Grey	Chipping	12	0.2	Negative
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Stringer	Concrete	Grey	Chipping	2	3.1	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Tread	Concrete	Grey	Chipping	2	2.9	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Handrail	Metal	Grey	Chipping	2	1.5	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Baluster	Concrete	Grey	Chipping	2	1.9	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Newel Post	Concrete	Grey	Chipping	2	2.7	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	W1	Plaster	White	Flaking	12	10.9	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	W2	Plaster	White	Flaking	16	16.1	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	W3	Plaster	White	Flaking	8	15.7	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	W4	Plaster	White	Flaking	10	15.9	Positive
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	3	S31	Stairs	Stairwell adjacent to Classroom 318A	Stair Soffit	Metal	Grey	Chipping	2	3.1	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Floor	Concrete	Brown	Chipping	2	0	Negative
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	W1	Plaster	Yellow	Efflorescence	4	15.4	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Radiators	Metal	Silver	Chipping	4	6.2	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Bulletin Board Frame	Wood	Brown	None	0	0	Negative
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	W2	N/A	N/A	N/A	N/A	N/A	N/A
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	W3	Plaster	Yellow	None	0	13.9	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Radiators	Metal	Silver	Chipping	4	5.2	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Door Frames	Metal	Brown	None	0	0	Negative
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Doors	Metal	Brown	None	0	0	Negative
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	W4	Plaster	Yellow	None	0	14.2	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Ceiling	Plaster	White	Efflorescence	36	10.9	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Ceiling	Plaster	White	Flaking	200	9.8	Positive
1	4	FT4	Circulation (Hallway)	4th Floor Hallway to Fire Tower Stairwell	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	401	Intermediate/Middle	Classroom 401	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	401	Intermediate/Middle	Classroom 401	Baseboard	Wood	Brown	Friction	5	0.05	Negative
1	4	401	Intermediate/Middle	Classroom 401	W1	Plaster	White	Chipping	4	14.8	Positive
1	4	401	Intermediate/Middle	Classroom 401	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	4	401	Intermediate/Middle	Classroom 401	W2	Plaster	White	None	0	11.7	Positive
1	4	401	Intermediate/Middle	Classroom 401	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative
1	4	401	Intermediate/Middle	Classroom 401	W3	Plaster	White	Flaking	24	15.2	Positive
1	4	401	Intermediate/Middle	Classroom 401	Radiators	Metal	Silver	Flaking	24	6.2	Positive
1	4	401	Intermediate/Middle	Classroom 401	Window Sill	Wood	Brown	Friction	12	0	Negative
1	4	401	Intermediate/Middle	Classroom 401	Window Apron	Wood	Brown	Friction	12	0	Negative
1	4	401	Intermediate/Middle	Classroom 401	W4	Plaster	White	None	0	13	Positive
1	4	401	Intermediate/Middle	Classroom 401	Chalkboard Ledge	Wood	Brown	Friction	10	0	Negative

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	401	Intermediate/Middle	Classroom 401	Ceiling	Plaster	White	Flaking	50	12.2	Positive
1	4	401	Intermediate/Middle	Classroom 401	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	402	Administrative Office	Office adjacent to Classroom 404	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	402	Administrative Office	Office adjacent to Classroom 404	W1	Plaster	White	Gouges	2	12.1	Positive
1	4	402	Administrative Office	Office adjacent to Classroom 404	W2	Plaster	White	Partially Inaccessible	0	15.2	Positive
1	4	402	Administrative Office	Office adjacent to Classroom 404	W3	Plaster	White	Partially Inaccessible	0	11.8	Positive
1	4	402	Administrative Office	Office adjacent to Classroom 404	Bookshelf	Wood	Brown	Friction	12	0.15	Negative
1	4	402	Administrative Office	Office adjacent to Classroom 404	W4	Plaster	White	Flaking	2	13.9	Positive
1	4	402	Administrative Office	Office adjacent to Classroom 404	Chalkboard Ledge	Wood	White	None	0	0.08	Negative
1	4	402	Administrative Office	Office adjacent to Classroom 404	Ceiling	Plaster	White	Flaking	20	10.5	Positive
1	4	402	Administrative Office	Office adjacent to Classroom 404	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403A	Intermediate/Middle	Classroom 403A	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	403A	Intermediate/Middle	Classroom 403A	Baseboard	Wood	Brown	Chipping	5	0	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	W1	Plaster	White	Flaking	1	13.9	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Chalkboard Ledge	Wood	White	None	0	0.05	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	Door Frame	Wood	Brown	Chipping	5	4.5	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	W2	Plaster	White	None	0	12.4	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Pipe	Metal	White	Chipping	1	0.1	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	Conduit	Metal	White	Chipping	1	0.1	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	W3	Plaster	White	Flaking	4	10.5	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Radiators	Metal	Silver	Flaking	24	6.5	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Window Frame	Wood	White	Friction	20	0.08	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	Window Sill	Wood	White	Friction	20	0	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	Window Apron	Wood	White	Friction	20	0	Negative
1	4	403A	Intermediate/Middle	Classroom 403A	W4	Plaster	White	None	0	6.9	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Ceiling	Plaster	White	Flaking	50	10.6	Positive
1	4	403A	Intermediate/Middle	Classroom 403A	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	403B	Storage	Storage Room 403	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	403B	Storage	Storage Room 403	Cove Base	Concrete	Black	Friction	12	0	Negative
1	4	403B	Storage	Storage Room 403	W1	Plaster	White	Flaking	10	15.2	Positive
1	4	403B	Storage	Storage Room 403	Door Frame	Metal	Brown	Friction	4	0	Negative
1	4	403B	Storage	Storage Room 403	W2	Plaster	White	Chipping	5	16.8	Positive
1	4	403B	Storage	Storage Room 403	W2	CMU	White	None	0	0.1	Negative
1	4	403B	Storage	Storage Room 403	Door Frame	Metal	Brown	Friction	4	0	Negative
1	4	403B	Storage	Storage Room 403	W3	Plaster	White	Flaking	4	17.5	Positive
1	4	403B	Storage	Storage Room 403	Radiators	Metal	Silver	Flaking	12	2.9	Positive
1	4	403B	Storage	Storage Room 403	W4	Plaster	Blue	Chipping	5	20.1	Positive
1	4	403B	Storage	Storage Room 403	Ceiling	Plaster	White	Cracking	20	15.6	Positive
1	4	404	Intermediate/Middle	Classroom 404	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	404	Intermediate/Middle	Classroom 404	W1	Plaster	Blue	Chipping	5	13.9	Positive
1	4	404	Intermediate/Middle	Classroom 404	Pipe	Metal	White	Chipping	1	0.1	Negative
1	4	404	Intermediate/Middle	Classroom 404	W2	Plaster	Blue	Gouges	12	12.5	Positive
1	4	404	Intermediate/Middle	Classroom 404	Window Sill	Wood	Brown	Friction	20	0.2	Negative
1	4	404	Intermediate/Middle	Classroom 404	Window Apron	Wood	Brown	Friction	20	0.12	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	404	Intermediate/Middle	Classroom 404	Radiators	Metal	Silver	Flaking	24	6.9	Positive
1	4	404	Intermediate/Middle	Classroom 404	W3	Plaster	Blue	Flaking	24	15.2	Positive
1	4	404	Intermediate/Middle	Classroom 404	W4	Plaster	Blue	Chipping	12	11.7	Positive
1	4	404	Intermediate/Middle	Classroom 404	Ceiling	Plaster	White	Flaking	50	10.6	Positive
1	4	404	Intermediate/Middle	Classroom 404	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	404A	Administrative Office	Deans Office	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	404A	Administrative Office	Deans Office	Baseboard	Wood	Grey	Friction	12	0	Negative
1	4	404A	Administrative Office	Deans Office	W1	Plaster	White	None	0	16.2	Positive
1	4	404A	Administrative Office	Deans Office	W2	Plaster	White	None	0	11.8	Positive
1	4	404A	Administrative Office	Deans Office	W3	Plaster	White	Flaking	8	10.8	Positive
1	4	404A	Administrative Office	Deans Office	Window Sill	Wood	Brown	Friction	12	0.08	Negative
1	4	404A	Administrative Office	Deans Office	Window Apron	Wood	Brown	None	0	0	Negative
1	4	404A	Administrative Office	Deans Office	Radiator	Metal	Silver	Flaking	12	4.6	Positive
1	4	404A	Administrative Office	Deans Office	W4	Plaster	White	None	0	15.4	Positive
1	4	404A	Administrative Office	Deans Office	Ceiling	Plaster	White	Flaking	10	8.2	Positive
1	4	404A	Administrative Office	Deans Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	405	Intermediate/Middle	Classroom 405	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	405	Intermediate/Middle	Classroom 405	Baseboard	Wood	Brown	Friction	10	0	Negative
1	4	405	Intermediate/Middle	Classroom 405	W1	Plaster	White	Chipping	4	9.5	Positive
1	4	405	Intermediate/Middle	Classroom 405	Pipe	Metal	White	Chipping	1	0.12	Negative
1	4	405	Intermediate/Middle	Classroom 405	W2	Plaster	White	Gouges	1	10.9	Positive
1	4	405	Intermediate/Middle	Classroom 405	W3	Plaster	White	Chipping	2	6.8	Positive
1	4	405	Intermediate/Middle	Classroom 405	Window Sill	Wood	Brown	Friction	10	0.26	Negative
1	4	405	Intermediate/Middle	Classroom 405	Window Apron	Wood	Brown	Friction	10	0.1	Negative
1	4	405	Intermediate/Middle	Classroom 405	Radiators	Metal	Silver	Flaking	36	5.9	Positive
1	4	405	Intermediate/Middle	Classroom 405	W4	Plaster	White	None	0	12.8	Positive
1	4	405	Intermediate/Middle	Classroom 405	Ceiling	Plaster	White	Flaking	50	13.4	Positive
1	4	405	Intermediate/Middle	Classroom 405	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	406	Intermediate/Middle	Classroom 406	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	406	Intermediate/Middle	Classroom 406	Baseboard	Wood	Brown	Friction	10	0	Negative
1	4	406	Intermediate/Middle	Classroom 406	W1	Plaster	White	None	0	14.4	Positive
1	4	406	Intermediate/Middle	Classroom 406	Sink	Porcelain	Brown	Chipping	2	0	Negative
1	4	406	Intermediate/Middle	Classroom 406	Pipe	Metal	White	Chipping	1	0.1	Negative
1	4	406	Intermediate/Middle	Classroom 406	W2	Plaster	White	None	0	12.9	Positive
1	4	406	Intermediate/Middle	Classroom 406	W3	Plaster	White	Flaking	4	15.5	Positive
1	4	406	Intermediate/Middle	Classroom 406	Window Sill	Wood	Brown	Friction	12	0	Negative
1	4	406	Intermediate/Middle	Classroom 406	Window Apron	Wood	Brown	Friction	12	0.08	Negative
1	4	406	Intermediate/Middle	Classroom 406	Conduit	Metal	White	Chipping	1	0.14	Negative
1	4	406	Intermediate/Middle	Classroom 406	Radiators	Metal	Silver	Flaking	24	5.9	Positive
1	4	406	Intermediate/Middle	Classroom 406	W4	Plaster	White	None	0	10.5	Positive
1	4	406	Intermediate/Middle	Classroom 406	Ceiling	Plaster	White	Flaking	20	11.9	Positive
1	4	406	Intermediate/Middle	Classroom 406	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	407	Intermediate/Middle	Classroom 407	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	407	Intermediate/Middle	Classroom 407	Baseboard	Wood	Brown	Friction	10	0	Negative
1	4	407	Intermediate/Middle	Classroom 407	W1	Plaster	White	Chipping	3	11.5	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	407	Intermediate/Middle	Classroom 407	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	407	Intermediate/Middle	Classroom 407	Duct	Metal	White	Chipping	1	4.6	Positive
1	4	407	Intermediate/Middle	Classroom 407	W2	Plaster	White	Partially Inaccessible	0	12.5	Positive
1	4	407	Intermediate/Middle	Classroom 407	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	407	Intermediate/Middle	Classroom 407	W3	Plaster	White	Efflorescence	25	15.4	Positive
1	4	407	Intermediate/Middle	Classroom 407	Window Sill	Wood	Brown	Friction	12	0.1	Negative
1	4	407	Intermediate/Middle	Classroom 407	Window Apron	Wood	Brown	Friction	12	0	Negative
1	4	407	Intermediate/Middle	Classroom 407	Radiators	Metal	Silver	Flaking	24	6.2	Positive
1	4	407	Intermediate/Middle	Classroom 407	W4	Plaster	White	None	0	15.1	Positive
1	4	407	Intermediate/Middle	Classroom 407	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	407	Intermediate/Middle	Classroom 407	Ceiling	Plaster	White	None	0	10.6	Positive
1	4	408	Intermediate/Middle	Classroom 408	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	408	Intermediate/Middle	Classroom 408	W1	Plaster	White	Chipping	2	21.1	Positive
1	4	408	Intermediate/Middle	Classroom 408	W2	Plaster	White	Partially Inaccessible	0	14.2	Positive
1	4	408	Intermediate/Middle	Classroom 408	W3	Plaster	White	Flaking	8	18.6	Positive
1	4	408	Intermediate/Middle	Classroom 408	Radiators	Metal	Silver	Chipping	4	5.1	Positive
1	4	408	Intermediate/Middle	Classroom 408	W4	Plaster	White	Partially Inaccessible	0	16.5	Positive
1	4	408	Intermediate/Middle	Classroom 408	Ceiling	Plaster	White	Flaking	20	13.7	Positive
1	4	408	Intermediate/Middle	Classroom 408	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	409	Storage	Storage Room 409 School Store	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	409	Storage	Storage Room 409 School Store	W1	Plaster	White	Flaking	50	16.2	Positive
1	4	409	Storage	Storage Room 409 School Store	W2	Plaster	White	Flaking	50	13.9	Positive
1	4	409	Storage	Storage Room 409 School Store	W3	Plaster	White	Flaking	50	12.5	Positive
1	4	409	Storage	Storage Room 409 School Store	W4	Plaster	White	Flaking	50	9.6	Positive
1	4	409	Storage	Storage Room 409 School Store	Ceiling	Plaster	White	Flaking	100	5.8	Positive
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	W1	Plaster	White	Flaking	100	10.8	Positive
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	W2	Plaster	White	Flaking	100	14.2	Positive
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	W3	Plaster	White	Flaking	100	13.7	Positive
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	W4	Plaster	White	Flaking	100	10.9	Positive
1	4	409A	TextBook Storage Area	Book Closet adjacent School Store	Ceiling	Plaster	White	Flaking	100	7.8	Positive
1	4	410A	Intermediate/Middle	Classroom 410	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	410A	Intermediate/Middle	Classroom 410	W1	Plaster	White	Chipping	2	14.9	Positive
1	4	410A	Intermediate/Middle	Classroom 410	Door Frame	Wood	Brown	Friction	1	0.12	Negative
1	4	410A	Intermediate/Middle	Classroom 410	Conduit	Metal	White	Chipping	1	0.16	Negative
1	4	410A	Intermediate/Middle	Classroom 410	W2	Sheetrock	White	Chipping	10	0	Negative
1	4	410A	Intermediate/Middle	Classroom 410	W3	Plaster	White	Efflorescence	8	13.2	Positive
1	4	410A	Intermediate/Middle	Classroom 410	Radiator Cover	Metal	White	Chipping	12	0.17	Negative
1	4	410A	Intermediate/Middle	Classroom 410	W4	Plaster	White	Efflorescence	5	12.5	Positive
1	4	410A	Intermediate/Middle	Classroom 410	Ceiling	Plaster	White	Efflorescence	5	10.9	Positive
1	4	410A	Intermediate/Middle	Classroom 410	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	410B	Conference Room	Conference Room 410B	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	410B	Conference Room	Conference Room 410B	W1	Plaster	White	Flaking	8	10.7	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	4	410B	Conference Room	Conference Room 410B	Door Frame	Metal	Brown	Chipping	1	0.4	Negative	
1	4	410B	Conference Room	Conference Room 410B	Bulletin Board Frame	Wood	White	Friction	5	0	Negative	
1	4	410B	Conference Room	Conference Room 410B	W2	Plaster	White	Chipping	1	15.2	Positive	
1	4	410B	Conference Room	Conference Room 410B	Bulletin Board Frame	Wood	White	Friction	5	0	Negative	
1	4	410B	Conference Room	Conference Room 410B	W3	Plaster	White	Efflorescence	20	16.1	Positive	
1	4	410B	Conference Room	Conference Room 410B	Radiator Cover	Metal	White	Chipping	2	0.19	Negative	
1	4	410B	Conference Room	Conference Room 410B	Pipe	Metal	White	Chipping	1	0.12	Negative	
1	4	410B	Conference Room	Conference Room 410B	Window Frame	Wood	Brown	Friction	4	0.17	Negative	
1	4	410B	Conference Room	Conference Room 410B	Window Sill	Wood	Brown	Friction	12	0.11	Negative	
1	4	410B	Conference Room	Conference Room 410B	Window Apron	Wood	Brown	Friction	12	0.2	Negative	
1	4	410B	Conference Room	Conference Room 410B	W4	Sheetrock	White	None	0	0	Negative	
1	4	410B	Conference Room	Conference Room 410B	Ceiling	Plaster	White	Flaking	10	12.8	Positive	
1	4	410B	Conference Room	Conference Room 410B	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	4	410C	Conference Room	Conference Room 410B Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	4	410C	Conference Room	Conference Room 410B Closet	W1	Plaster	White	Partially Inaccessible	0	15.1	Positive	
1	4	410C	Conference Room	Conference Room 410B Closet	W2	Plaster	White	Partially Inaccessible	0	12.8	Positive	
1	4	410C	Conference Room	Conference Room 410B Closet	W3	Plaster	White	Partially Inaccessible	0	10.9	Positive	
1	4	410C	Conference Room	Conference Room 410B Closet	W4	Plaster	White	Partially Inaccessible	0	14.6	Positive	
1	4	410C	Conference Room	Conference Room 410B Closet	Ceiling	Plaster	White	Partially Inaccessible	0	13.6	Positive	
1	4	411	Intermediate/Middle	Classroom 411	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	4	411	Intermediate/Middle	Classroom 411	Cove Base	Concrete	Brown	Chipping	10	0	Negative	
1	4	411	Intermediate/Middle	Classroom 411	W1	Plaster	White	None	0	11.6	Positive	
1	4	411	Intermediate/Middle	Classroom 411	W1	CMU	White	None	0	0.13	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Door Frame	Wood	Brown	Chipping	3	0.2	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Pipe	Metal	White	Chipping	1	0.1	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Pipe	Metal	Brown	Chipping	1	0.1	Negative	
1	4	411	Intermediate/Middle	Classroom 411	W2	Plaster	White	None	0	13.2	Positive	
1	4	411	Intermediate/Middle	Classroom 411	W2	CMU	White	None	0	0.09	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Door Frame	Metal	Brown	Chipping	1	0.14	Negative	
1	4	411	Intermediate/Middle	Classroom 411	W3	Plaster	White	None	0	12.5	Positive	
1	4	411	Intermediate/Middle	Classroom 411	Window Frame	Wood	Brown	Friction	4	0.1	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Window Sill	Wood	Brown	Friction	12	0.12	Negative	
1	4	411	Intermediate/Middle	Classroom 411	Window Apron	Wood	Brown	Friction	12	0.15	Negative	
1	4	411	Intermediate/Middle	Classroom 411	W4	Plaster	White	None	0	15.2	Positive	
1	4	411	Intermediate/Middle	Classroom 411	Ceiling	Plaster	White	None	0	10.8	Positive	
1	4	411A	Storage	Classroom 411 Closet	Floor	Wood	N/A	N/A	N/A	N/A	N/A	
1	4	411A	Storage	Classroom 411 Closet	W1	Plaster	White	Partially Inaccessible	0	10.5	Positive	
1	4	411A	Storage	Classroom 411 Closet	W2	Plaster	White	Partially Inaccessible	0	10.9	Positive	
1	4	411A	Storage	Classroom 411 Closet	W3	Plaster	White	Partially Inaccessible	0	16.2	Positive	
1	4	411A	Storage	Classroom 411 Closet	W4	Plaster	White	Partially Inaccessible	0	13.4	Positive	
1	4	411A	Storage	Classroom 411 Closet	Ceiling	Plaster	White	Partially Inaccessible	0	N/A	N/A	
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	W1	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	W2	Concrete	N/A	N/A	N/A	N/A	N/A	

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	411PS	Pipe Shaft	Pipe Shaft in Classroom 411 Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Baseboard	Wood	Brown	Chipping	12	0	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	W1	Plaster	White	Chipping	4	12.5	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Door Frame	Metal	Brown	None	0	0	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	W2	Plaster	White	None	0	14.9	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Door Frame	Metal	Brown	Chipping	1	0.12	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	W3	Plaster	White	Chipping	2	15.4	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Radiators	Metal	Silver	Flaking	18	6.4	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Window Sill	Wood	Brown	Friction	12	0.15	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Window Apron	Wood	Brown	Friction	4	0	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Pipe	Metal	White	Chipping	1	0.14	Negative
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	W4	Plaster	White	Efflorescence	20	5.4	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Ceiling	Plaster	White	Flaking	50	10.2	Positive
1	4	412	Intermediate/Middle -- Science L	Classroom 412 Science Lab	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	425A	Storage	Classroom 412 Storage	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	425A	Storage	Classroom 412 Storage	W1	Plaster	White	Partially Inaccessible	0	15.2	Positive
1	4	425A	Storage	Classroom 412 Storage	W2	Plaster	White	Partially Inaccessible	0	4.9	Positive
1	4	425A	Storage	Classroom 412 Storage	W3	Plaster	White	Partially Inaccessible	0	9.5	Positive
1	4	425A	Storage	Classroom 412 Storage	W4	Plaster	White	Partially Inaccessible	0	12.9	Positive
1	4	425A	Storage	Classroom 412 Storage	Ceiling	Plaster	White	Partially Inaccessible	0	8.3	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	Floor	Concrete	Grey	Friction	4	0.1	Negative
1	4	404B	Restrooms, Staff - Male	Men's Room	W1	Plaster	White	None	0	10.5	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	W2	Plaster	White	None	0	10.8	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	W3	Plaster	Blue	Flaking	20	13.4	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	W3	Plaster	White	Flaking	5	12.1	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	W4	Plaster	Blue	Flaking	20	16.2	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	W4	Plaster	White	Flaking	5	17.4	Positive
1	4	404B	Restrooms, Staff - Male	Men's Room	Ceiling	Plaster	White	None	0	12.6	Positive
1	4	414	Intermediate/Middle	Classroom 414	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	414	Intermediate/Middle	Classroom 414	Baseboard	Wood	Brown	Friction	20	0	Negative
1	4	414	Intermediate/Middle	Classroom 414	W1	Plaster	White	Chipping	4	11.6	Positive
1	4	414	Intermediate/Middle	Classroom 414	Door Frame	Metal	Brown	Friction	2	0.15	Negative
1	4	414	Intermediate/Middle	Classroom 414	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	414	Intermediate/Middle	Classroom 414	W2	Plaster	White	None	0	12.1	Positive
1	4	414	Intermediate/Middle	Classroom 414	W3	Plaster	White	Chipping	2	10.4	Positive
1	4	414	Intermediate/Middle	Classroom 414	Pipe	Metal	White	Chipping	2	0.23	Negative
1	4	414	Intermediate/Middle	Classroom 414	Radiators	Metal	Silver	Flaking	12	4.8	Positive
1	4	414	Intermediate/Middle	Classroom 414	Window Sill	Wood	Brown	Friction	12	0	Negative
1	4	414	Intermediate/Middle	Classroom 414	Window Apron	Wood	Brown	Friction	12	0	Negative
1	4	414	Intermediate/Middle	Classroom 414	W4	Plaster	White	None	0	9.5	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	414	Intermediate/Middle	Classroom 414	Door Frame	Wood	Brown	Chipping	1	0.11	Negative
1	4	414	Intermediate/Middle	Classroom 414	Ceiling	Plaster	White	Flaking	5	12.8	Positive
1	4	414	Intermediate/Middle	Classroom 414	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	Baseboard	Wood	Brown	Friction	20	0	Negative
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	W1	Plaster	White	None	0	14.9	Positive
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	W2	Plaster	White	None	0	15.6	Positive
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	W3	Plaster	White	None	0	15.1	Positive
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	Window Sill	Wood	Brown	Friction	12	0	Negative
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	Window Apron	Wood	Brown	None	0	0	Negative
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	W4	Plaster	White	None	0	12.4	Positive
1	4	414A	Restrooms, Staff - Female	Women's Restroom adjacent to Classroom 414	Ceiling	Plaster	White	None	0	9.8	Positive
1	4	415	Intermediate/Middle	Classroom 415	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	4	415	Intermediate/Middle	Classroom 415	Baseboard	Wood	Brown	Friction	20	0	Negative
1	4	415	Intermediate/Middle	Classroom 415	W1	Plaster	White	Chipping	3	14.2	Positive
1	4	415	Intermediate/Middle	Classroom 415	W2	Plaster	White	Partially Inaccessible	0	12.6	Positive
1	4	415	Intermediate/Middle	Classroom 415	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	415	Intermediate/Middle	Classroom 415	W3	Plaster	White	Gouges	3	10.9	Positive
1	4	415	Intermediate/Middle	Classroom 415	Radiators	Metal	Silver	Flaking	12	5.8	Positive
1	4	415	Intermediate/Middle	Classroom 415	Window Sill	Wood	Brown	Friction	12	0.1	Negative
1	4	415	Intermediate/Middle	Classroom 415	Window Apron	Wood	Brown	Friction	12	0.1	Negative
1	4	415	Intermediate/Middle	Classroom 415	W4	Plaster	White	Partially Inaccessible	0	5.4	Positive
1	4	415	Intermediate/Middle	Classroom 415	Chalkboard Ledge	Wood	Brown	Friction	12	0	Negative
1	4	415	Intermediate/Middle	Classroom 415	Ceiling	Plaster	White	Partially Inaccessible	0	6.2	Positive
1	4	415	Intermediate/Middle	Classroom 415	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	Floor	Concrete	Grey	Flaking	12	0	Negative
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	W1	Plaster	White	Flaking	4	12	Positive
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	W2	Plaster	White	Flaking	12	12.4	Positive
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	W3	Plaster	White	Flaking	16	13.9	Positive
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	W4	Plaster	White	Flaking	8	18	Positive
1	4	415SC	Service Closets	Service Closet adjacent Girl's Restroom	Ceiling	Plaster	White	Flaking	8	15.7	Positive
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	415PC	Pipe Chase	Girls's Restroom Pipe Chase	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	416	Intermediate/Middle	Classroom 416	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	416	Intermediate/Middle	Classroom 416	Floor	Concrete	Brown	Flaking	20	0	Negative
1	4	416	Intermediate/Middle	Classroom 416	W1	Brick	White	Flaking	60	1.4	Positive
1	4	416	Intermediate/Middle	Classroom 416	Conduit	Metal	White	Chipping	1	0.19	Negative
1	4	416	Intermediate/Middle	Classroom 416	Closet Wall	CMU	White	None	0	0.3	Negative
1	4	416	Intermediate/Middle	Classroom 416	Door Frame	Metal	White	Chipping	2	0.04	Negative
1	4	416	Intermediate/Middle	Classroom 416	W2	Brick	White	Flaking	120	2.9	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	416	Intermediate/Middle	Classroom 416	Upper Window Lintel	Plaster	White	Flaking	12	3.6	Positive
1	4	416	Intermediate/Middle	Classroom 416	Pipe	Metal	Brown	Chipping	1	0.27	Negative
1	4	416	Intermediate/Middle	Classroom 416	Pipe	Metal	White	Chipping	1	0.26	Negative
1	4	416	Intermediate/Middle	Classroom 416	Radiators	Metal	Silver	Flaking	30	4.9	Positive
1	4	416	Intermediate/Middle	Classroom 416	W3	Brick	White	Flaking	60	1.5	Positive
1	4	416	Intermediate/Middle	Classroom 416	Pipe	Metal	Grey	Chipping	4	0.2	Negative
1	4	416	Intermediate/Middle	Classroom 416	Vent	Metal	White	Chipping	2	1.1	Positive
1	4	416	Intermediate/Middle	Classroom 416	Door Frame	Wood	Brown	Chipping	2	0	Negative
1	4	416	Intermediate/Middle	Classroom 416	Door	Wood	Brown	Chipping	4	0	Negative
1	4	416	Intermediate/Middle	Classroom 416	W4	Brick	White	Flaking	120	3.1	Positive
1	4	416	Intermediate/Middle	Classroom 416	Pipe	Metal	Brown	Chipping	1	0.21	Negative
1	4	416	Intermediate/Middle	Classroom 416	Pipe	Metal	White	Chipping	1	0.26	Negative
1	4	416	Intermediate/Middle	Classroom 416	Radiators	Metal	Silver	Flaking	30	5.8	Positive
1	4	416	Intermediate/Middle	Classroom 416	Upper Window Lintel	Plaster	White	Flaking	12	3.9	Positive
1	4	416	Intermediate/Middle	Classroom 416	Ceiling	Plaster	White	Efflorescence	40	12.6	Positive
1	4	416	Intermediate/Middle	Classroom 416	Beam	Concrete	White	None	0	0.19	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	W1	Plaster	White	Flaking	12	13.4	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Conduit	Metal	White	Chipping	1	0.12	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Closet Wall	CMU	White	None	0	0.3	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Door Frame	Metal	White	Friction	2	0.04	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	W2	Plaster	White	Flaking	8	18.2	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Pipe	Metal	Brown	Chipping	2	0.27	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Pipe	Metal	White	Chipping	2	0.26	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Radiators	Metal	Silver	Chipping	24	5.7	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Upper Window Lintel	Plaster	White	Flaking	12	3.6	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	W3	Plaster	White	Flaking	12	16.2	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Pipe	Metal	Grey	Chipping	1	0.1	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Vent	Metal	White	Chipping	1	1.1	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Door Frame	Wood	Brown	Chipping	2	0	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Door	Wood	Brown	Chipping	4	0	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	W4	Plaster	White	Flaking	8	15.4	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Pipe	Metal	Brown	Chipping	2	0.2	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Pipe	Metal	White	Chipping	2	0.18	Negative
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Radiators	Metal	Silver	Chipping	24	4.3	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Upper Window Lintel	Plaster	White	Flaking	12	3.9	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Ceiling	Plaster	White	Flaking	10	13.1	Positive
1	4	424	Cafeteria (Dining Area)	Cafeteria 424	Ceiling Beams	Concrete	White	Chipping	5	0.19	Negative
1	4	426	Kitchen	Kitchen Room 426	Floor	Concrete	Grey	Chipping	20	0	Negative
1	4	426	Kitchen	Kitchen Room 426	W1	Brick	White	Chipping	2	8.4	Positive
1	4	426	Kitchen	Kitchen Room 426	Door Frame	Wood	Brown	Friction	2	0.04	Negative
1	4	426	Kitchen	Kitchen Room 426	Door	Wood	Brown	Friction	2	0.25	Negative

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	4	426	Kitchen	Kitchen Room 426	W2	Brick	White	Chipping	1	6.2	Positive	
1	4	426	Kitchen	Kitchen Room 426	Door Frame	Wood	Brown	Friction	2	0	Negative	
1	4	426	Kitchen	Kitchen Room 426	Door	Wood	Brown	Friction	2	0.12	Negative	
1	4	426	Kitchen	Kitchen Room 426	W3	Brick	White	Flaking	5	3.9	Positive	
1	4	426	Kitchen	Kitchen Room 426	Radiator	Metal	Silver	Flaking	6	4.5	Positive	
1	4	426	Kitchen	Kitchen Room 426	Window Frame	Wood	Brown	Chipping	8	0.11	Negative	
1	4	426	Kitchen	Kitchen Room 426	Spiral Staircase	Metal	Grey	Flaking	60	2.7	Positive	
1	4	426	Kitchen	Kitchen Room 426	W4	Brick	White	Chipping	2	4.5	Positive	
1	4	426	Kitchen	Kitchen Room 426	Elevator Door Frame	Metal	Yellow	Chipping	2	0.15	Negative	
1	4	426	Kitchen	Kitchen Room 426	Elevator Door	Metal	Yellow	Chipping	4	0.14	Negative	
1	4	426	Kitchen	Kitchen Room 426	Ceiling	Plaster	White	Flaking	200	7.4	Positive	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	W1	Plaster	White	Flaking	150	15.4	Positive	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	W2	Plaster	White	Flaking	100	15.1	Positive	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	W3	Plaster	White	Flaking	150	19.2	Positive	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	W4	Plaster	White	Flaking	100	16.5	Positive	
1	4	426E	Lockers - Staff	Locker Room above Kitchen	Ceiling	Plaster	White	Flaking	250	14.9	Positive	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	W1	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	W2	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	W3	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	W4	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426PC	Pipe Chase	Boy's Restroom Pipe Chase	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426C	Kitchen and Dry Storage Area	Room adjacent to Kitchen	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426B	Kitchen and Dry Storage Area	Kitchen Storage in Hallway	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	4	426D	Administrative Office	Kitchen Office	Ceiling	No Access	No Access	No Access	N/A	N/A	No Access	
1	4	426D	Administrative Office	Kitchen Office	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A	
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	W1	Plaster	Yellow	None	0	17.2	Positive	
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	W2	Plaster	Yellow	None	0	15.1	Positive	

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	W3	Plaster	Yellow	None	0	13.9	Negative
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	Window Sill	Wood	Brown	Friction	2	0	Negative
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	Radiators	Metal	Silver	Flaking	48	6.1	Positive
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	W4	Plaster	Yellow	None	0	11.6	Positive
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	Ceiling	Plaster	White	Flaking	400	16.6	Positive
1	4	H410	Circulation (Hallway)	Hallway from Classrooms 406 to 410	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Floor	Concrete	Grey	Chipping	12	0	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	W1	Brick	White	Chipping	2	3.6	Positive
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	W2	Brick	White	None	0	2.9	Positive
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	W3	Brick	White	None	0	4.5	Positive
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Panel Cover	Metal	Grey	Chipping	2	0.5	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Door Frames	Wood	Brown	Chipping	2	0	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Doors	Wood	Brown	Chipping	2	0	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	W4	Brick	White	None	0	3.1	Positive
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Door Frames	Wood	Brown	Chipping	2	0	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Doors	Wood	Brown	Chipping	2	0	Negative
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Ceiling	Plaster	White	Flaking	16	14.2	Positive
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H413	Circulation (Hallway)	4th Floor Back Hallway adjacent to Kitchen	Duct	Metal	White	Flaking	4	1.1	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	W2	Plaster	Yellow	Chipping	2	16.2	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	Radiators	Metal	Silver	Chipping	6	2.9	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	W3	Plaster	Yellow	None	0	16.9	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	W4	Plaster	Yellow	Chipping	2	13.4	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	Ceiling	Plaster	White	Flaking	200	12.2	Positive
1	4	H411	Circulation (Hallway)	Hallway from Classrooms 401 to 405	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W1	Brick	White	None	0	3.5	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W2	Brick	White	None	0	3.6	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W3	Brick	White	None	0	4.9	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W4	Brick	White	None	0	2.7	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Ceiling	Plaster	White	Efflorescence	40	22	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Floor	Concrete	Grey	None	0	0	Negative
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W1	Brick	White	None	0	1.9	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W2	Brick	White	None	0	3.2	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Fire Hose Box	Metal	Red	Chipping	2	0.1	Negative
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Conduit	Metal	White	Chipping	1	0.1	Negative
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W3	Brick	White	Chipping	1	3	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Door Frames	Wood	Brown	Chipping	2	0.05	Negative
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Doors	Wood	Brown	Chipping	4	0.3	Negative
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	W4	Brick	White	Chipping	2	2.6	Positive
1	4	CORRIDOR	Circulation (Hallway)	4th Floor Hallway adjacent to Kitchen	Ceiling	Plaster	White	None	0	7.9	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
					Dates: 08/31/2022						
					Inspector Name and Certificate Number: Ryan Hutsell 059512						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	W1	N/A	N/A	N/A	N/A	N/A	N/A
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	W2	Plaster	Yellow	Chipping	12	13.2	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Doors	Metal	Brown	Chipping	2	0	Negative
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Radiators	Metal	Silver	Flaking	12	5.7	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Door Frames	Metal	Brown	Chipping	5	0.2	Negative
					Elevator Door						
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Frame	Metal	Yellow	Chipping	2	0.3	Negative
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Elevator Door	Metal	Yellow	Chipping	2	0	Negative
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	W3	Plaster	Yellow	Chipping	2	9.8	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	W4	Plaster	Yellow	Chipping	12	16.1	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Radiators	Metal	Silver	Flaking	12	5.7	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Door Frames	Metal	Brown	Chipping	5	0.15	Negative
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Ceiling	Plaster	White	Flaking	100	16.5	Positive
1	4	H412	Circulation (Hallway)	Hallway from Classrooms 412 to 416	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	W1	Brick	White	Flaking	40	4.9	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	W2	Brick	White	Flaking	40	5.2	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	W3	Brick	White	Flaking	40	2.7	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	W4	Brick	White	Flaking	40	5.5	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Ceiling	Concrete	White	Flaking	10	4.5	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Window Frame	Metal	Brown	Chipping	1	4.9	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Handrail	Metal	Brown	Chipping	10	1.9	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Pipe	Metal	Grey	Chipping	12	1.2	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Stringer	Metal	Grey	Chipping	12	1.5	Positive
1	4	S45	Stairs, Fire Tower	Stairwell adjacent to Classroom 416	Tread	Concrete	Grey	Chipping	12	0.5	Negative
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Stringer	Metal	Grey	Chipping	2	3.5	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Tread	Concrete	Grey	Chipping	2	1.8	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Handrail	Metal	Grey	Chipping	2	1.2	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Baluster	Concrete	Grey	Chipping	2	2.7	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Newel Post	Concrete	Grey	Chipping	2	3.1	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	W1	Plaster	White	Flaking	12	10.9	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	W2	Plaster	White	Flaking	16	16.1	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	W3	Plaster	White	Flaking	8	15.7	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	W4	Plaster	White	Flaking	10	15.9	Positive
1	4	S42	Stairs	Stairwell adjacent to Classroom 403B	Ceiling	Plaster	White	Flaking	10	13.2	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Stringer	Metal	Grey	Chipping	2	1.8	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Tread	Concrete	Grey	Chipping	2	5.2	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Handrail	Metal	Grey	Chipping	2	2.5	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Baluster	Metal	Grey	Chipping	2	2.3	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Newel Post	Concrete	Grey	Chipping	2	2.8	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	W1	Plaster	White	Flaking	12	16.2	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	W2	Plaster	White	Flaking	16	19.5	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	W3	Plaster	White	Flaking	8	18.1	Positive
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	W4	Plaster	White	Flaking	10	11.6	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	4	S41	Stairs	Stairwell adjacent to Classroom 411	Ceiling	Plaster	White	Flaking	10	22.1	Positive
1	5	500	Intermediate/Middle	Classroom 500	Floor	Wood	N/A	N/A	N/A	N/A	N/A
1	5	500	Intermediate/Middle	Classroom 500	W1	Plaster	White	Flaking	200	16.9	Positive
1	5	500	Intermediate/Middle	Classroom 500	W2	Plaster	White	Flaking	200	12.6	Positive
1	5	500	Intermediate/Middle	Classroom 500	W3	Plaster	White	Flaking	200	10.8	Positive
1	5	500	Intermediate/Middle	Classroom 500	W4	Plaster	White	Flaking	200	10.5	Positive
1	5	500	Intermediate/Middle	Classroom 500	Ceiling	Plaster	White	Flaking	800	11.9	Positive
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	W1	Plaster	White	Flaking	50	15.2	Positive
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	W2	Plaster	White	Flaking	50	11.7	Positive
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	W3	Plaster	White	Flaking	50	17.5	Positive
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	W4	Plaster	White	Flaking	50	15.4	Positive
1	5	500A	Student Restrooms - Female (4-12)	Girl's Restroom adjacent to Classroom 500	Ceiling	Plaster	White	Flaking	150	19.2	Positive
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	W1	Plaster	White	Flaking	50	9.5	Positive
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	W2	Plaster	White	Flaking	50	16.2	Positive
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	W3	Plaster	White	Flaking	50	13.9	Positive
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	W4	Plaster	White	Flaking	50	10.4	Positive
1	5	500B	Student Restrooms - Male (4-12)	Boy's Restroom behind Stairwell to Classroom 500	Ceiling	Plaster	White	Flaking	150	12.4	Positive
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	W1	Plaster	White	Flaking	50	9.5	Positive
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	W2	Plaster	White	Flaking	50	16.2	Positive
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	W3	Plaster	White	Flaking	50	13.9	Positive
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	W4	Plaster	White	Flaking	50	10.4	Positive
1	5	500C	Restrooms, Staff - Male	Men's Restroom behind Stairwell to Classroom 500	Ceiling	Plaster	White	Flaking	150	12.4	Positive
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	Fence	Metal	Grey	Flaking	100	0.18	Negative
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	W2	Brick	N/A	N/A	N/A	N/A	N/A
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	Fence	Metal	Grey	Flaking	100	0.25	Negative
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	5	500D	Gymnasium (Rooftop)	Roof Gym (Vacant)	Ceiling	N/A	N/A	N/A	N/A	N/A	N/A
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	W1	Plaster	White	Flaking	150	14.2	Positive
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	W2	Plaster	White	Flaking	150	15.4	Positive
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	W3	Plaster	White	Flaking	150	13.9	Positive
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	W4	Plaster	White	Flaking	150	10.6	Positive
1	5	H516	Circulation (Hallway)	5th Floor Hallway Interior (Vacant)	Ceiling	Plaster	White	Flaking	600	7.8	Positive
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	W1	Plaster	White	Flaking	150	10.6	Positive
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	W2	Plaster	White	Flaking	150	14.9	Positive
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	W3	Plaster	White	Flaking	150	12.9	Positive
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	W4	Plaster	White	Flaking	150	13.4	Positive
1	5	H516A	Circulation (Hallway)	5th Floor Hallway adjacent to Elevator	Ceiling	Plaster	N/A	N/A	600	11.7	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	W1	Brick	White	Flaking	200	8.5	Positive
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	W2	Brick	White	Flaking	200	10.6	Positive
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	W3	Brick	White	Flaking	200	7.3	Positive
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	W4	Brick	White	Flaking	200	12.4	Positive
1	5	H513	Circulation (Hallway)	Roof Hallway to Stairwell	Ceiling	Concrete	White	Flaking	800	6.9	Positive
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	W1	Brick	White	Flaking	200	15.1	Positive
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	W2	Brick	White	Flaking	200	13.2	Positive
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	W3	Brick	White	Flaking	200	11.8	Positive
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	W4	Brick	White	Flaking	200	9.5	Positive
1	5	H514	Circulation (Hallway)	Roof Hallway behind Penthouse	Ceiling	Concrete	White	Flaking	800	16.2	Positive
1	5	S51	Stairs	Stairwell to Rooftop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	S51	Stairs	Stairwell to Rooftop	W1	Plaster	White	Flaking	100	10.5	Positive
1	5	S51	Stairs	Stairwell to Rooftop	W2	Brick	White	Flaking	200	11.6	Positive
1	5	S51	Stairs	Stairwell to Rooftop	W3	Plaster	White	Flaking	100	12.9	Positive
1	5	S51	Stairs	Stairwell to Rooftop	W4	Brick	White	Flaking	200	10.4	Positive
1	5	S51	Stairs	Stairwell to Rooftop	Ceiling	Plaster	White	Flaking	500	9.5	Positive
1	5	S54	Stairs	Stairwell adjacent to Roof	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	5	S54	Stairs	Stairwell adjacent to Roof	W1	Plaster	White	Flaking	100	15.4	Positive
1	5	S54	Stairs	Stairwell adjacent to Roof	W2	Brick	White	Flaking	200	7.2	Positive
1	5	S54	Stairs	Stairwell adjacent to Roof	W3	Plaster	White	Flaking	100	16.1	Positive
1	5	S54	Stairs	Stairwell adjacent to Roof	W4	Brick	White	Flaking	200	14.9	Positive
1	5	S54	Stairs	Stairwell adjacent to Roof	Ceiling	Plaster	White	Flaking	500	10.7	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Floor	Concrete	Grey	Chipping	200	0.2	Negative
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Duct	Metal	White	Flaking	250	3.1	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Tank	Metal	Grey	Flaking	120	8.2	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Radiator	Metal	White	Flaking	12	4.9	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Handrail	Metal	Grey	Chipping	12	2.5	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Stringer	Metal	Grey	Chipping	12	2.7	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	W1	Brick	White	Flaking	250	5.2	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	W2	Brick	White	Flaking	250	4.3	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	W3	Brick	White	Flaking	250	2.9	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	W4	Brick	White	Flaking	250	6.2	Positive
1	PH	PH	Mechanical Room	Penthouse Mechanical Room (above roof play deck)	Ceiling	Concrete	White	Flaking	500	12.9	Positive
1	A	AT	Attic	Main Attic	Floor	Plaster	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Main Attic	W1	Terracotta	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Main Attic	W2	Terracotta	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Main Attic	W3	Terracotta	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Main Attic	W4	Terracotta	N/A	N/A	N/A	N/A	N/A
1	A	AT	Attic	Main Attic	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	W1	No Access	N/A	N/A	N/A	N/A	N/A
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	W2	No Access	N/A	N/A	N/A	N/A	N/A
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	W3	No Access	N/A	N/A	N/A	N/A	N/A

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	W4	No Access	N/A	N/A	N/A	N/A	N/A
1	B	PS	Pipe Shaft	Main Steam Pipe Shaft	Ceiling	No Access	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	SP	SP	Auditorium	Auditorium Supply Plenum	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S02	Stairs	Stairwell adjacent to Gym 011	W1	Plaster	White	Flaking	10	16.3	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	W2	Plaster	White	Flaking	30	14.7	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	W3	Plaster	White	Flaking	10	15.8	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	W4	Plaster	White	Flaking	30	13.4	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Ceiling	Plaster	White	Flaking	15	14.9	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Stringer	Concrete	Grey	Chipping	2	3.5	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Tread	Concrete	Grey	Chipping	2	4.2	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Handrail	Concrete	Grey	Chipping	1	1.7	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Baluster	Concrete	Grey	Chipping	2	2.9	Positive
1	B	S02	Stairs	Stairwell adjacent to Gym 011	Newel Post	Concrete	Grey	Chipping	2	4.6	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	S01	Stairs	Stairwell at Gym 009	W1	Plaster	White	Flaking	10	16.7	Positive
1	B	S01	Stairs	Stairwell at Gym 009	W2	Plaster	White	Flaking	30	16.2	Positive
1	B	S01	Stairs	Stairwell at Gym 009	W3	Plaster	White	Flaking	10	16.1	Positive
1	B	S01	Stairs	Stairwell at Gym 009	W4	Plaster	White	Flaking	30	17.8	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Ceiling	Plaster	White	Flaking	15	15.4	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Stringer	Concrete	Grey	Chipping	2	2.9	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Tread	Concrete	Grey	Chipping	2	1.8	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Handrail	Concrete	Grey	Chipping	1	3.1	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Baluster	Concrete	Grey	Chipping	2	3.5	Positive
1	B	S01	Stairs	Stairwell at Gym 009	Newel Post	Concrete	Grey	Chipping	2	3.2	Positive
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	Floor	No Access	N/A	N/A	N/A	N/A	N/A
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	W1	No Access	N/A	N/A	N/A	N/A	N/A
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	W2	No Access	N/A	N/A	N/A	N/A	N/A
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	W3	No Access	N/A	N/A	N/A	N/A	N/A
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	W4	No Access	N/A	N/A	N/A	N/A	N/A
1	B	001	Mechanical Room	Fan Room #2 (next to boiler room)	Ceiling	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	Floor	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	W1	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	W2	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	W3	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	W4	No Access	N/A	N/A	N/A	N/A	N/A
1	B	26	Boiler Room	Old Summer Boiler Room	Ceiling	No Access	N/A	N/A	N/A	N/A	N/A
1	B	002	Mechanical Room	Old Boiler Room	Floor	No Access	N/A	N/A	N/A	N/A	N/A
1	B	002	Mechanical Room	Old Boiler Room	Ceiling	No Access	N/A	N/A	N/A	N/A	N/A
1	B	023	Storage	Operations Storage between boiler room and electrical room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512	1130 Tilden Middle School						
				Inspection Company: Synertech	6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	023	Storage	Operations Storage between boiler room and electrical room	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	023	Storage	Operations Storage between boiler room and electrical room	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	023	Storage	Operations Storage between boiler room and electrical room	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	023	Storage	Operations Storage between boiler room and electrical room	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	023	Storage	Operations Storage between boiler room and electrical room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	W1	Brick	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	W2	Brick	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	W3	Brick	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	W4	Brick	N/A	N/A	N/A	N/A	N/A
1	B	18	Mechanical Room	Auditorium Plenum	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	W2	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	W3	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	20	Mechanical Room	Incinerator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	W1	Plaster	White	Flaking	1	11.1	Positive
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Door	Metal	Brown	None	0	0	Negative
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Door Frame	Wood	Brown	None	0	0	Negative
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	W2	Concrete	White	None	0	8.3	Positive
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Stall Partition	Concrete	White	None	0	0	Negative
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	W3	Plaster	White	Efflorescence	6	10.1	Positive
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Pipe	Metal	White	Flaking	1	0	Negative
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	W4	Plaster	White	Efflorescence	15	16.5	Positive
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Ceiling	Plaster	White	Efflorescence	10	10.6	Positive
1	B	004	Restrooms, Staff - Male	Men's Restroom behind Stairwell by Building Engineer's Office	Radiator	Metal	Silver	Cracking	2	4.2	Positive
1	B	005	Administrative Office	Building Engineer's Office	Floor	N/A	N/A	N/A	N/A	N/A	N/A
1	B	005	Administrative Office	Building Engineer's Office	W1	Plaster	White	Efflorescence	10	13.1	Positive

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School					
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142					
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	005	Administrative Office	Building Engineer's Office	Door	Metal	Brown	Chipping	1	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Window Frame	Metal	Brown	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Window Louver	Metal	Brown	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	W2	Plaster	White	Flaking	2	11.9	Positive
1	B	005	Administrative Office	Building Engineer's Office	Coat Rack	Wood	White	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	W3	Plaster	White	Cracking	3	11.2	Positive
1	B	005	Administrative Office	Building Engineer's Office	Door	Wood	Brown	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Door Frame	Wood	Brown	Chipping	1	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	W4	Plaster	White	Efflorescence	16	10.2	Positive
1	B	005	Administrative Office	Building Engineer's Office	Door	Metal	Brown	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Door Frame	Wood	Brown	None	0	0	Negative
1	B	005	Administrative Office	Building Engineer's Office	Ceiling	Plaster	White	Flaking	4	7.8	Positive
1	B	006	Circulation (Hallway)	Electrical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006	Circulation (Hallway)	Electrical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	006	Circulation (Hallway)	Electrical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	007	Mechanical Room	Auditorium Fan Room #3	W1	Concrete	White	Flaking	100	5.5	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	W2	Brick	White	Cracking	200	2.7	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	W3	Concrete	White	Flaking	200	4.9	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	W4	Concrete	White	Flaking	100	3.8	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	W4	Brick	White	Cracking	120	2.4	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	Ceiling	Concrete	White	Flaking	2000	5.2	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	Duct	Metal	White	Flaking	750	1.4	Positive
1	B	007	Mechanical Room	Auditorium Fan Room #3	Beam	Concrete	White	Flaking	60	5.6	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	W1	Plaster	Red	Efflorescence	1	4.4	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Door	Metal	Brown	None	0	0	Negative
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Door Frame	Wood	Brown	None	0	0	Negative
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	W2	Plaster	White	Efflorescence	8	15.5	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	W3	Plaster	Red	Flaking	1	16.2	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	W3	Plaster	White	Flaking	6	15.8	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	W4	Plaster	Red	None	0	15.4	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Ceiling	Plaster	White	Cracking	48	17	Positive
1	B	008A	Restrooms, Staff - Female	Basement Women's Staff Restroom	Radiator	Metal	Silver	Chipping	2	3.5	Positive
1	B	H02	Circulation (Hallway)	Basement Hallway	Floor	Concrete	Grey	Chipping	150	0	Negative
1	B	H02	Circulation (Hallway)	Basement Hallway	W1	Concrete	White	Flaking	100	11.4	Positive
1	B	H02	Circulation (Hallway)	Basement Hallway	W2	Concrete	White	Flaking	50	4.7	Positive
1	B	H02	Circulation (Hallway)	Basement Hallway	W3	Brick	White	Partially Inaccessible	100	20.8	Positive
1	B	H02	Circulation (Hallway)	Basement Hallway	W4	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	H02	Circulation (Hallway)	Basement Hallway	Ceiling	Concrete	White	Flaking	550	12.8	Positive
1	B	H02	Circulation (Hallway)	Basement Hallway	Duct	Metal	White	Flaking	36	2.7	Positive
1	B	012	Mechanical Room	Fan Room #1 (adjacent to boy's gym 011)	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	012	Mechanical Room	Fan Room #1 (adjacent to boy's gym 011)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access

					Lead-Safe Certification Assessment Report						
					1130 Tilden Middle School						
					6601 Elmwood Avenue, Philadelphia, PA 19142						
					Inspection Company: Synertech						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	3	Mechanical Room	Old Coal Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	3	Mechanical Room	Old Coal Room	W1	Concrete	White	Flaking	60	5.6	Positive
1	B	3	Mechanical Room	Old Coal Room	Column	Concrete	White	Flaking	48	18.2	Positive
1	B	3	Mechanical Room	Old Coal Room	W2	Concrete	White	Flaking	30	24.4	Positive
1	B	3	Mechanical Room	Old Coal Room	W3	Concrete	White	Flaking	300	1.2	Positive
1	B	3	Mechanical Room	Old Coal Room	Window Frame	Wood	White	Flaking	12	8.9	Positive
1	B	3	Mechanical Room	Old Coal Room	W4	Concrete	White	Flaking	450	36	Positive
1	B	3	Mechanical Room	Old Coal Room	Ceiling	Concrete	White	Flaking	1800	5.2	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Floor	Rubber	N/A	N/A	N/A	N/A	N/A
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Baseboard	Concrete	Brown	Chipping	10	0.08	Negative
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W1	Brick	Yellow	Flaking	200	15.6	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W1	Brick	White	Flaking	200	6.2	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Radiators	Metal	White	Chipping	18	3.5	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Door Frame	Metal	Brown	Chipping	4	0	Negative
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Door	Metal	Brown	Chipping	4	0	Negative
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W2	Brick	Yellow	Flaking	200	15.4	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W2	Brick	White	Flaking	200	13.2	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Backboard	Wood	White	Chipping	1	14.4	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W3	Brick	Yellow	Flaking	200	5.1	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W3	Brick	White	Flaking	200	10.2	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Radiators	Metal	White	Chipping	18	4.2	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W4	Brick	Yellow	Flaking	200	10.8	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	W4	Brick	White	Flaking	200	14.5	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Door Frame	Metal	Brown	Chipping	4	0	Negative
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Door	Metal	Brown	Chipping	4	0	Negative
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Ceiling	Plaster	White	Flaking	200	5.9	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Beam	Metal	White	Flaking	80	18.8	Positive
1	B	009	Gymnasium - Intermediate Midd	Girl's Gymnasium	Duct	Metal	White	Flaking	40	0.28	Negative
1	B	17	Stairs	Girl's Gym Stair to H16	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	17	Stairs	Girl's Gym Stair to H16	W1	Plaster	White	Flaking	10	12.5	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	W2	Plaster	White	Flaking	30	14.9	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	W3	Plaster	White	Flaking	10	15.2	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	W4	Plaster	White	Flaking	30	15.7	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Ceiling	Plaster	White	Flaking	15	11.6	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Stringer	Concrete	Grey	Chipping	2	3.6	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Tread	Concrete	Grey	Chipping	2	2.9	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Handrail	Concrete	Grey	Chipping	1	3.5	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Baluster	Concrete	Grey	Chipping	2	3.3	Positive
1	B	17	Stairs	Girl's Gym Stair to H16	Newel Post	Concrete	Grey	Chipping	2	4.1	Positive
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	W1	Plaster	White	Flaking	2	16.4	Positive
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	W2	Plaster	White	Flaking	12	15.9	Positive
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	W3	Plaster	White	Flaking	16	13.2	Positive

				Dates: 08/31/2022	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512	1130 Tilden Middle School						
				Inspection Company: Synertech	6601 Elmwood Avenue, Philadelphia, PA 19142						
Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	W4	Plaster	White	Flaking	12	12.4	Positive
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	Ceiling	Plaster	White	Flaking	2	14.5	Positive
1	B	17A	Storage	Storage Closet at bottom of Girls' Gym Stairs to H16 (adj. Stage Side of Auditorium)	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	016A	Administrative Office	Girl's Gymnasium Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	016A	Administrative Office	Girl's Gymnasium Office	Trench Plate	Metal	Grey	Flaking	12	3.1	Positive
1	B	016A	Administrative Office	Girl's Gymnasium Office	W1	Plaster	White	Flaking	20	4.2	Positive
1	B	016A	Administrative Office	Girl's Gymnasium Office	W2	Plaster	White	Flaking	30	16.9	Positive
1	B	016A	Administrative Office	Girl's Gymnasium Office	W3	Plaster	White	Flaking	20	18.2	Positive
1	B	016A	Administrative Office	Girl's Gymnasium Office	W4	Plaster	White	Flaking	30	16.5	Positive
1	B	016A	Administrative Office	Girl's Gymnasium Office	Ceiling	Plaster	White	Flaking	25	14.8	Positive
1	B	016B	Storage	Girl's Gymnasium Office Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	016B	Storage	Girl's Gymnasium Office Closet	W1	Plaster	White	Flaking	6	15.4	Positive
1	B	016B	Storage	Girl's Gymnasium Office Closet	W2	Plaster	White	Flaking	12	19.2	Positive
1	B	016B	Storage	Girl's Gymnasium Office Closet	W3	Plaster	White	Flaking	18	16.5	Positive
1	B	016B	Storage	Girl's Gymnasium Office Closet	W4	Plaster	White	Flaking	12	14.2	Positive
1	B	016B	Storage	Girl's Gymnasium Office Closet	Ceiling	Plaster	White	Flaking	6	20.2	Positive
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	W1	Plaster	White	Flaking	20	15.9	Positive
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	W2	Plaster	White	Flaking	20	15.3	Positive
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	W3	Plaster	White	Flaking	20	16.2	Positive
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	W4	Plaster	White	Flaking	20	14.9	Positive
1	B	016	Restrooms, Staff - Female	Girl's Gymnasium Office Restroom	Ceiling	Plaster	White	Flaking	20	18.7	Positive
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	W1	Plaster	White	Flaking	40	16.2	Positive
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	W2	Plaster	White	Flaking	60	21.5	Positive
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	W3	Plaster	White	Flaking	40	14.3	Positive
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	W4	Plaster	White	Flaking	60	14.9	Positive
1	B	015	Gymnasium Storage	Girl's Gymnasium Storage	Ceiling	Plaster	White	Flaking	30	10.5	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Floor	Rubber	N/A	N/A	N/A	N/A	N/A
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Baseboard	Concrete	Brown	Chipping	10	0.1	Negative
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W1	Brick	Yellow	Flaking	200	11.5	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W1	Brick	White	Flaking	200	8.1	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Door Frame	Metal	Brown	Chipping	4	0	Negative
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Door	Metal	Brown	Chipping	4	0	Negative
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Radiators	Metal	White	Chipping	18	2.9	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W2	Brick	Yellow	Flaking	200	10.9	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W2	Brick	White	Flaking	200	8.6	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Radiators	Metal	White	Chipping	18	5.2	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	Backboard	Wood	White	Chipping	1	14.4	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W3	Brick	Yellow	Flaking	200	6.4	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W3	Brick	White	Flaking	200	15.2	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W4	Brick	Yellow	Flaking	200	5.9	Positive
1	B	011	Gymnasium - Intermediate Middle	Boy's Gymnasium	W4	Brick	White	Flaking	200	5.8	Positive

	Dates: 08/31/2022 Inspector Name and Certificate Number: Ryan Hutsell 059512 Inspection Company: Synertech	Lead-Safe Certification Assessment Report 1130 Tilden Middle School 6601 Elmwood Avenue, Philadelphia, PA 19142
--	---	--

Element	Floor	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B	011	Gymnasium - Intermediate Midd	Boy's Gymnasium	Door Frame	Metal	Brown	Chipping	4	0	Negative
1	B	011	Gymnasium - Intermediate Midd	Boy's Gymnasium	Door	Metal	Brown	Chipping	4	0	Negative
1	B	011	Gymnasium - Intermediate Midd	Boy's Gymnasium	Ceiling	Plaster	White	Flaking	200	11.8	Positive
1	B	011	Gymnasium - Intermediate Midd	Boy's Gymnasium	Beam	Metal	White	Flaking	80	6.7	Positive
1	B	011	Gymnasium - Intermediate Midd	Boy's Gymnasium	Duct	Metal	White	Flaking	40	0.19	Negative
1	B	013	Administrative Office	Boy's Gymnasium Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	013	Administrative Office	Boy's Gymnasium Office	Trench Plate	Metal	Grey	Flaking	12	3.5	Positive
1	B	013	Administrative Office	Boy's Gymnasium Office	W1	Plaster	White	Flaking	20	15.4	Positive
1	B	013	Administrative Office	Boy's Gymnasium Office	W2	Plaster	White	Flaking	30	15.9	Positive
1	B	013	Administrative Office	Boy's Gymnasium Office	W3	Plaster	White	Flaking	20	18.6	Positive
1	B	013	Administrative Office	Boy's Gymnasium Office	W4	Plaster	White	Flaking	30	15.4	Positive
1	B	013	Administrative Office	Boy's Gymnasium Office	Ceiling	Plaster	White	Flaking	15	13.2	Positive
1	B	013B	Storage	Boy's Gymnasium Office Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	013B	Storage	Boy's Gymnasium Office Closet	W1	Plaster	White	Flaking	20	14.8	Positive
1	B	013B	Storage	Boy's Gymnasium Office Closet	W2	Plaster	White	Flaking	30	14.4	Positive
1	B	013B	Storage	Boy's Gymnasium Office Closet	W3	Plaster	White	Flaking	40	16.8	Positive
1	B	013B	Storage	Boy's Gymnasium Office Closet	W4	Plaster	White	Flaking	30	12.7	Positive
1	B	013B	Storage	Boy's Gymnasium Office Closet	Ceiling	Plaster	White	Flaking	16	14.5	Positive
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	W1	Plaster	White	Flaking	20	13.9	Positive
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	W2	Plaster	White	Flaking	20	12.5	Positive
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	W3	Plaster	White	Flaking	20	18.2	Positive
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	W4	Plaster	White	Flaking	20	14.8	Positive
1	B	013C	Restrooms, Staff - Male	Boy's Gymnasium Office Restroom	Ceiling	Plaster	White	Flaking	20	15.1	Positive
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	W1	Brick	White	Flaking	2	5.4	Positive
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	W2	Brick	White	Flaking	8	5.2	Positive
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	W3	Brick	White	Flaking	6	4.3	Positive
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	W4	Brick	White	Flaking	2	6.1	Positive
1	B	14	Gymnasium Storage	Boy's Gymnasium Storage #1	Ceiling	Concrete	White	Flaking	2	5.2	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	W1	Brick	Brown	Flaking	40	4.1	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	W2	Brick	Brown	Flaking	10	3.5	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	W3	Brick	Brown	Flaking	2	6.7	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	W4	Brick	Brown	Flaking	6	5.4	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	Ceiling	Concrete	Brown	Flaking	8	5.2	Positive
1	B	011A	Gymnasium Storage	Boy's Gymnasium Storage #2	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	W1	Brick	White	Flaking	20	4.8	Positive
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	W2	Brick	White	Flaking	20	3.9	Positive
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	W3	Brick	White	Flaking	20	5.1	Positive
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	W4	Brick	White	Flaking	20	5.4	Positive
1	B	24	Gymnasium Storage	Boy's Gymnasium Storage #3	Ceiling	Concrete	White	Flaking	20	6.1	Positive
1	B	025	Storage	Boiler Room Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	025	Storage	Boiler Room Storage	W1	Concrete	N/A	N/A	N/A	N/A	N/A
1	B	025	Storage	Boiler Room Storage	W2	Concrete	N/A	N/A	N/A	N/A	N/A

				Dates: 08/31/2022		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Ryan Hutsell 059512		1130 Tilden Middle School						
				Inspection Company: Synertech		6601 Elmwood Avenue, Philadelphia, PA 19142						
E l e m e n t	F l o o r	Space #	Space Type	On-Site Room Name	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B	025	Storage	Boiler Room Storage	W3	Concrete	N/A	N/A	N/A	N/A	N/A	
1	B	025	Storage	Boiler Room Storage	W4	Concrete	N/A	N/A	N/A	N/A	N/A	
1	B	025	Storage	Boiler Room Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	