

			1/5-6/22, 9/14/22, 12/14-16/22, 1/25/23, 2/10/23		School District of Philadelphia						
			Inspector Name and Certificate Number: Jim Mongan 056598. Jessica Smenkowski 059701, Paul Davis 060094, Drew DiMichele 056324		Lead Safe Certification Assessment Report						
			Inspection Company: Vertex		Woodrow Wilson Middle School						
E l e m e n t	F l o o r	Space #	On-Site Room Name	Student/ Teacher Occupied (yes/no)	Component	Substrate Material	Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	W1	Brick	White	Chipping	100	0	Negative
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	W2	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	W3	Concrete	N/A	N/A	0	0	Negative
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	W4	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	Door	Wood	Varnish	Chipping	8	0	Negative
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	Door Frame	Wood	Varnish	Chipping	8	0.04	Negative
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-1	PH-1 : Penthouse Tank Room	no	Tank	Metal	Black	None	0	N/A	N/A
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-2	Penthouse Exhaust Fan Room along Loretto Avenue	no	Door	Wood	Grey	Chipping	1	10.1	Positive
1	PH	PH-2	Penthouse Exhaust Fan Room along Loretto Avenue	no	Door Frame	Wood	Grey	Chipping	1	12.9	Positive
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	W2	Brick	White	Chipping	20	0	Negative
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	W3	Brick	White	Chipping	10	0.01	Negative
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	W4	Brick	White	Chipping	10	0	Negative
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	Pipe	Metal	White	Chipping	8	0.07	Negative
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-2	Penthouse Exhaust Fan Room along Loretto Avenue	no	Duct	Metal	Grey	Flaking	6	4.3	Positive
1	PH	PH-2	PH-2 : Penthouse Exhaust Fan Room along Loretto Avenue	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-3	Large Penthouse Exhaust Fan Room along Englewood Street	no	Door Frame	Wood	Grey	Chipping	6	7.2	Positive
1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	W3	Brick	White	Chipping	10	0	Negative
1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	W4	Brick	White	Chipping	5	0	Negative
1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-3	Large Penthouse Exhaust Fan Room along Englewood Street	no	Duct	Metal	White	Chipping	4	3	Positive

1	PH	PH-3	PH-3 : Large Penthouse Exhaust Fan Room along Englewood Street	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-4	Penthouse Exhaust Fan Room along Frontenac Street	no	Door	Wood	Grey	Chipping	2	7.7	Positive
1	PH	PH-4	Penthouse Exhaust Fan Room along Frontenac Street	no	Door Frame	Wood	Grey	Chipping	4	12.4	Positive
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	W2	Brick	White	None	0	N/A	N/A
1	PH	PH-4	Penthouse Exhaust Fan Room along Frontenac Street	no	Pipe	Metal	White	Chipping	13	5.8	Positive
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	W3	Brick	White	None	0	N/A	N/A
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	W4	Brick	White	Chipping	10	0	Negative
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	PH	PH-4	Penthouse Exhaust Fan Room along Frontenac Street	no	Duct	Metal	Grey	Chipping	5	7.2	Positive
1	PH	PH-4	PH-4 : Penthouse Exhaust Fan Room along Frontenac Street	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	W1	Brick	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	W3	Brick	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	W4	Brick	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	A	MA	MA : Main Attic above Third Floor	no	Floor	N/A	N/A	N/A	0	N/A	N/A
1	4	401	Office 401 City Year	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	401	Office 401 City Year	yes	W2	Sheetrock	White	Flaking	2	0	Negative
1	4	401	Office 401 City Year	yes	Door	Wood	N/A	N/A	N/A	N/A	N/A
1	4	401	Office 401 City Year	yes	Door Frame	Metal	White	Chipping	5	0	Negative
1	4	401	Office 401 City Year	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	401	Office 401 City Year	yes	Radiator	Metal	Grey	Flaking	8	No Access	No Access
1	4	401	Office 401 City Year	yes	W4	Sheetrock	White	Chipping	5	0	Negative
1	4	401	Office 401 City Year	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	401	Office 401 City Year	yes	Door Frame	Metal	White	Chipping	5	0	Negative
1	4	401	Office 401 City Year	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	401	Office 401 City Year	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	401	Office 401 City Year	yes	Column	Brick	White	Friction	4	5.2	Positive
1	4	415	Boy's Restroom Adj Classroom 402A	yes	W1	Brick	White	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Door Frame	Metal	White	Chipping	6	0	Negative
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Panel	Wood	White	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	W2	Ceramic Tile	N/A	N/A	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	W3	Brick	White	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Door	Metal	Beige	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Door Frame	Metal	Beige	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	W4	Brick	White	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Floor	Concrete	Grey	Flaking	2	0.02	Negative
1	4	415	Boy's Restroom Adj Classroom 402A	yes	Stall Supports	Metal	White	Chipping	10	0	Negative
1	4	412A	Girl's Restroom Vestibule	yes	W1	Brick	N/A	N/A	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	Door Frame	Metal	White	Chipping	4	0	Negative
1	4	412A	Girl's Restroom Vestibule	yes	W2	Brick	N/A	N/A	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	W3	Brick	N/A	N/A	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	Door	Wood	N/A	N/A	0	N/A	N/A

1	4	412A	Girl's Restroom Vestibule	yes	Door Frame	Metal	White	Chipping	4	0	Negative
1	4	412A	Girl's Restroom Vestibule	yes	W4	Brick	N/A	N/A	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	4	412A	Girl's Restroom Vestibule	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	W1	Brick	White	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	door frame	Metal	Yellow	Flaking	3	0.01	Negative
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	W2	Brick	White	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	W3	Brick	White	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	W4	Ceramic	Tan	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	412	Girl's Restroom adjacent to Classroom 409	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	4	412-PC	412-PC : Pipe Chase - Restroom adjacent to Classroom 409	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	W1	Plaster	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	W2	Plaster	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	W3	Plaster	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	W4	Plaster	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	4	412A	412A : Penthouse Tank Room Entrance across from office 401	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	4	409	409 : Conference Room	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	409	409 : Conference Room	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	409	Conference Room	yes	Door Frame	Metal	White	Chipped	5	0	Negative
1	4	409	Conference Room	yes	W2	Sheetrock	White	Cracking	4	5.8	Positive
1	4	409	Conference Room	yes	W3	Sheetrock	White	Cracking	2	6.5	Positive
1	4	409	409 : Conference Room	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	409	409 : Conference Room	yes	Window Frame	Wood	White	None	0	N/A	N/A
1	4	409	409 : Conference Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	409	409 : Conference Room	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	Door Frame	Metal	White	N/A	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	W4	Sheetrock	White	Hole	1	0	Negative
1	4	408	408 : 8th Grade Counselor's Office	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	4	408	408 : 8th Grade Counselor's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	407	7th Grade Counselor's Office	yes	Door Frame	Metal	White	Chipping	3	0	Negative

1	4	407	7th Grade Counselor's Office	yes	W2	Sheetrock	White	None	0	3.5	Positive
1	4	407	407 : 7th Grade Counselor's Office	yes	Window Frame	Wood	N/A	N/A	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	4	407	407 : 7th Grade Counselor's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	402	402 : Classroom 402 (Music)	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	402	402 : Classroom 402 (Music)	yes	Door	Wood	N/A	None	0	N/A	N/A
1	4	402	Classroom 402 (Music)	yes	Door Frame	Metal	White	Friction	3	0	Negative
1	4	402	Classroom 402 (Music)	yes	W2	Sheetrock	Purple	Holes	3	6.5	Positive
1	4	402	Classroom 402 (Music)	yes	W3	Sheetrock	White	Hole	1	5.2	Positive
1	4	402	402 : Classroom 402 (Music)	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	402	402 : Classroom 402 (Music)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	402	402 : Classroom 402 (Music)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	Door	Metal	White	Chipping	5	0	Negative
1	4	402A	Classroom 402A	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	4	402A	Classroom 402A	yes	Window Frame	Wood	White	N/A	0	N/A	N/A
1	4	402A	Classroom 402A	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	W3	Sheetrock	Purple	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	402A	Classroom 402A	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	406	6th Grade Counselor's Office	yes	Door Frame	Metal	White	Chipping	3	0	Negative
1	4	406	6th Grade Counselor's Office	yes	W2	Sheetrock	White	None	0	18.8	Positive
1	4	406	406 : 6th Grade Counselor's Office	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	Window Frame	Wood	White	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	406	406 : 6th Grade Counselor's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	404	404 : Classroom 404 (Music)	yes	W1	Sheetrock	Yellow	holes	4	0	Negative
1	4	404	404 : Classroom 404 (Music)	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	4	404	404 : Classroom 404 (Music)	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	404	404 : Classroom 404 (Music)	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	404	404 : Classroom 404 (Music)	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	4	404	404 : Classroom 404 (Music)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	door frame	Metal	White	None	0	0.03	Negative
1	4	404A	404A: Classroom 404 Closet	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	4	404A	404A: Classroom 404 Closet	yes	Floor	Concrete	White	None	0	N/A	N/A
1	4	403	6th Grade Counselor's Office	yes	W1	Sheetrock	White	Cracking/Holes	4	5.2	Positive
1	4	403	403 : Classroom 403 (Music)	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	403	Classroom 403 (Music)	yes	Door Frame	Metal	White	Friction	3	0	Negative
1	4	403	Classroom 403 (Music)	yes	W2	Sheetrock	White	Chipping/Cracking	5	5.8	Positive
1	4	403	403 : Classroom 403 (Music)	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	403	Classroom 403 (Music)	yes	Door Frame	Metal	White	Friction	5	0	Negative
1	4	403	Classroom 403 (Music)	yes	W3	Sheetrock	White	Cracking	6	5.2	Positive
1	4	403	403 : Classroom 403 (Music)	yes	W4	Sheetrock	Blue	None	0	N/A	N/A

1	4	403	403 : Classroom 403 (Music)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	403	403 : Classroom 403 (Music)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	H410	Hallway from Classroom 403 to Office 401	yes	W1	Sheetrock	White	Cracking	7	3.5	Positive
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	H410	Hallway from Classroom 403 to Office 401	yes	Door Frame	Metal	White	Friction	6	0.03	Negative
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Window Frame	Wood	White	None	0	N/A	N/A
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	W3	Brick	N/A	N/A	0	N/A	N/A
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	H410	Hallway from Classroom 403 to Office 401	yes	Door Frame	Metal	White	Friciton/Peeling	10	0.01	Negative
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Door	Metal	Red	None	0	N/A	N/A
1	4	H410	Hallway from Classroom 403 to Office 401	yes	Door Frame	Wood	Brown	Chipping	10	0.03	Negative
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	H410	Hallway from Classroom 403 to Office 401	yes	Door Frame	Metal	Brown	Chipping	15	0.2	Negative
1	4	H410	Hallway from Classroom 403 to Office 401	yes	Ceiling	Plaster	White	Cracked/Holes	7	5.8	Positive
1	4	H410	H410 : Hallway from Classroom 403 to Office 401	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	W1	Brick	N/A	None	0	N/A	N/A
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	W2	Sheetrock	White	Flaking	1	0.01	Negative
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	W4	Brick	N/A	None	0	N/A	N/A
1	4	H401A	Hallway from Loretto side Fire Tower to Boy's Restroom	yes	Door	Metal	Brown	Chipping	6	10.1	Positive
1	4	H401A	Hallway from Loretto side Fire Tower to Boy's Restroom	yes	Door Frame	Metal	Brown	Chipping	6	10.1	Positive
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	4	H401A	H401A : Hallway from Loretto side Fire Tower to Boy's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	W1	Sheetrock	Green	holes	4	16	Positive
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Door	Wood	N/A	Hole/Peeling	12	0	Negative
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Door Frame	Metal	Black	N/A	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	W2	Sheetrock	Green	None	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	W3	Sheetrock	Green	None	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Door	Metal	Green	N/A	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Door Frame	Metal	Green	N/A	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	W4	Sheetrock	Green	None	0	N/A	N/A
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Ceiling	Plaster	White	Holes	5	5.2	Positive
1	4	410A	Storeroom next to Loretto side Fire Tower	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	410	School Psychologist Office	yes	W1	Plaster	White	None	0	N/A	N/A
1	4	410	School Psychologist Office	yes	Door	Metal	N/A	N/A	0	N/A	N/A
1	4	410	School Psychologist Office	yes	Door Frame	Metal	N/A	N/A	0	N/A	N/A
1	4	410	School Psychologist Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	4	410	School Psychologist Office	yes	W3	Plaster	White	Cracking/Efflorescence	10	3.5	Positive
1	4	410	School Psychologist Office	yes	Radiator	Metal	Grey	Flaking	8	No Access	No Access
1	4	410	School Psychologist Office	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	410	School Psychologist Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	410	School Psychologist Office	yes	Floor	Wood	N/A	None	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A

1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Radiator	Metal	Silver	Flaking	8	3.2	Positive
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door	Wood	Brown	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door Frame	Wood	Brown	N/A	0	N/A	N/A
1	4	H401	Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	W3	Plaster	White	Holes	1	5.8	Positive
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door	Metal	Red	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door Frame	Metal	Red	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door	Wood	Brown	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door Frame	Wood	Brown	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Door Frame	Metal	Black	N/A	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Duct	Metal	White	None	0	N/A	N/A
1	4	H401	H401 : Hallway from Frontenac side Fire Tower to Girl's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	W1	Sheetrock	Green	None	0	N/A	N/A
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	W2	Sheetrock	Green	Peeling	10	0.02	Negative
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	W3	Sheetrock	Green	Peeling	8	0.07	Negative
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	W4	Plaster	Green	None	0	N/A	N/A
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	4	411	411 : North Storage Room adjacent to Main Attic	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	W1	Sheetrock	Tan	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	W2	Sheetrock	Tan	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	W3	Sheetrock	Tan	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	W4	Sheetrock	Tan	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	Ceiling	Sheetrock	Tan	None	0	N/A	N/A
1	4	416	416: Office next to Frontenac side Fire Tower	yes	Floor	Concrete	White	None	0	N/A	N/A
1	3	301	Classroom 301	yes	W1	Plaster	White	Chipping	6	20.4	Positive
1	3	301	301 : Classroom 301	yes	door	Wood	Varnish	Chipping	2	0.04	Negative
1	3	301	301 : Classroom 301	yes	door frame	Wood	Varnish	Chipping	6	0.03	Negative
1	3	301	301 : Classroom 301	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	3	301	301 : Classroom 301	yes	W3	Plaster	White	Chipping	2	0.4	Negative
1	3	301	301 : Classroom 301	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	301	301 : Classroom 301	yes	Pipe Sleeve	Metal	White	Chipping	3	0.12	Negative
1	3	301	301 : Classroom 301	yes	Window Sill	Wood	Varnish	Chipping	20	0.23	Negative
1	3	301	Classroom 301	yes	W4	Plaster	Purple	None	0	29.3	Positive
1	3	301	301 : Classroom 301	yes	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	3	301	301 : Classroom 301	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	Radiator	Metal	Silver	None	0	4.3	Positive
1	3	S34	S34 : Stairwell across from Classroom 301	yes	W2	Plaster	White	None	0	N/A	N/A

1	3	S34	Stairwell across from Classroom 301	yes	Newel Post	Metal	Grey	Chipping	4	4.2	Positive
1	3	S34	Stairwell across from Classroom 301	yes	W3	Plaster	White	None	0	28.3	Positive
1	3	S34	S34 : Stairwell across from Classroom 301	yes	door	Metal	Blue	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	door frame	Metal	Blue	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	S34	S34 : Stairwell across from Classroom 301	yes	Tread	Metal	Grey	Chipping	5	0.4	Negative
1	3	S34	Stairwell across from Classroom 301	yes	Riser	Metal	Grey	Chipping	5	2.8	Positive
1	3	S34	Stairwell across from Classroom 301	yes	Spindle	Metal	Grey	Chipping	10	6.8	Positive
1	3	302A	Boy's Restroom across from Classroom 302	yes	W1	Plaster	Tan	None	0	20.4	Positive
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	door	Wood	Varnish	Chipping	3	0.02	Negative
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	door frame	Wood	Varnish	Chipping	4	0.01	Negative
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	Ceiling	Plaster	Tan	Flaking	20	0.03	Negative
1	3	302A	302A : Boy's Restroom across from Classroom 302	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	3	302A-PC	302A-PC : Pipe Chase - Boy's Restroom across from Classroom 302	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	302B	302B : Custodial Closet next to Boy's Restroom across from Classroom 302	no	W1	Plaster	Tan	None	0	N/A	N/A
1	3	302B	Custodial Closet next to Boy's Restroom across from Classroom 302	no	W2	Plaster	Tan	Chipping	3	11	Positive
1	3	302B	Custodial Closet next to Boy's Restroom across from Classroom 302	no	W3	Plaster	Tan	Flaking	2	14.5	Positive
1	3	302B	302B : Custodial Closet next to Boy's Restroom across from Classroom 302	no	Pipe	Metal	Tan	Flaking	15	0.4	Negative
1	3	302B	302B : Custodial Closet next to Boy's Restroom across from Classroom 302	no	W4	Plaster	Tan	None	0	N/A	N/A
1	3	302B	Custodial Closet next to Boy's Restroom across from Classroom 302	no	Ceiling	Plaster	Tan	Cracking/Flaking	3	18.9	Positive
1	3	302B	302B : Custodial Closet next to Boy's Restroom across from Classroom 302	no	Floor	Concrete	Grey	Chipping	10	0.07	Negative
1	3	326	Classroom 326 Now Classroom 323	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	3	326	Classroom 326 Now Classroom 323	yes	W2	Plaster	Purple	None	0	N/A	N/A
1	3	326	Classroom 326 Now Classroom 323	yes	W3	Plaster	Purple	None	0	N/A	N/A
1	3	326	Classroom 326 Now Classroom 323	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	326	Classroom 326 Now Classroom 323	yes	W4	Concrete Block	Purple	None	0	N/A	N/A
1	3	326	Classroom 326 Now Classroom 323	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	326	Classroom 326 Now Classroom 323	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	3	302	Classroom 302	yes	W1	Plaster	Purple	Chipping	4	29.1	Positive
1	3	302	302 : Classroom 302	yes	door frame	Wood	Varnish	Chipping	4	0.8	Positive
1	3	302	302 : Classroom 302	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	3	302	Classroom 302	yes	W3	Plaster	White	Chipping	3	29.7	Positive
1	3	302	302 : Classroom 302	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access

1	3	302	302 : Classroom 302	yes	Window Sill	Wood	Varnish	Chipping	15	0.24	Negative
1	3	302	302 : Classroom 302	yes	Pipe Sleeve	Metal	Beige	Chipping	3	0.02	Negative
1	3	302	302 : Classroom 302	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	3	302	302 : Classroom 302	yes	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	3	302	302 : Classroom 302	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	W2	Concrete Block	White	None	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	323	Classroom 323 Now Classroom 324	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	3	323	Classroom 323 Now Classroom 324	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	W1	Plaster	White	Chipping	1	24.3	Positive
1	3	S33	S33 : Stairwell across from Classroom 303	yes	Radiator	Metal	Silver	Flaking	5	4.4	Positive
1	3	S33	S33 : Stairwell across from Classroom 303	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	W3	Plaster	White	Flaking	3	24.1	Positive
1	3	S33	S33 : Stairwell across from Classroom 303	yes	Door	Metal	Blue	None	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	Door Frame	Metal	Blue	None	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S33	S33 : Stairwell across from Classroom 303	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	S33	Stairwell across from Classroom 303	yes	Stair Newel Post	Concrete	Grey	Chipping	10	16.9	Positive
1	3	S33	Stairwell across from Classroom 303	yes	Stair Ballust	Concrete	Grey	Chipping	10	18.8	Positive
1	3	S33	Stairwell across from Classroom 303	yes	Stair Riser	Concrete	Grey	Chipping	10	3.5	Positive
1	3	S33	Stairwell across from Classroom 303	yes	Stair Stringer	Concrete	Grey	Chipping	10	5.8	Positive
1	3	S33	Stairwell across from Classroom 303	yes	Stair Tread	Concrete	Grey	Chipping	10	6.5	Positive
1	3	303	303 : Classroom 303	yes	W1	Plaster	Purple	Chipping	1	26.3	Positive
1	3	303	303 : Classroom 303	yes	door frame	Wood	Varnish	Chipping	4	0.06	Negative
1	3	303	303 : Classroom 303	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	303	303 : Classroom 303	yes	W3	Plaster	White	Chipping	4	22.4	Positive
1	3	303	303 : Classroom 303	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	303	303 : Classroom 303	yes	Window Sill	Wood	Varnish	Chipping	10	0.1	Negative
1	3	303	303 : Classroom 303	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	3	303	303 : Classroom 303	yes	Ceiling	Plaster	No Access	None	0	N/A	N/A
1	3	303	303 : Classroom 303	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	W2	Plaster	Yellow	Chipping	4	30	Positive
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	W4	Plaster	Yellow	Cracking/Chipping	5	28.6	Positive
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	3	H31	H31 : Hallway outside Classrooms 301 - 303	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	304	304 : Classroom 304	yes	W1	Plaster	Purple	Chipping	3	17.2	Positive
1	3	304	304 : Classroom 304	yes	W2	Plaster	White	Cracking	3	17.3	Positive
1	3	304	304 : Classroom 304	yes	W3	Plaster	White	Flaking	30	0.07	Negative
1	3	304	304 : Classroom 304	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	304	Classroom 304	yes	Pipe	Metal	White	Cracking	3	5.2	Positive
1	3	304	304 : Classroom 304	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	304	304 : Classroom 304	yes	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access

1	3	304	304 : Classroom 304	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	305	305 : Classroom 305	yes	W1	Plaster	Purple	Chipping	7	25.5	Positive
1	3	305	305 : Classroom 305	yes	door	Wood	Varnish	Chipping	6	0.07	Negative
1	3	305	305 : Classroom 305	yes	W2	Plaster	White	Hole/Flaking	8	15.1	Positive
1	3	305	305 : Classroom 305	yes	W3	Plaster	White	Cracking/Chipping	10	31.9	Positive
1	3	305	305 : Classroom 305	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	305	305 : Classroom 305	yes	Window Sill	Wood	Varnish	Chipping	18	0.12	Negative
1	3	305	305 : Classroom 305	yes	W4	Plaster	White	holes	4	25.7	Positive
1	3	305	305 : Classroom 305	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	305	305 : Classroom 305	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	W1	Plaster	Orange	Hole	1	23.7	Positive
1	3	306	306 : Classroom 306	yes	Pipe	Metal	White	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	door	Wood	Varnish	Friction	1	0.14	Negative
1	3	306	306 : Classroom 306	yes	door frame	Wood	Varnish	Friction	4	0.07	Negative
1	3	306	306 : Classroom 306	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	306	306 : Classroom 306	yes	Window Sill	Wood	Varnish	Friction	15	0.25	Negative
1	3	306	306 : Classroom 306	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	306	306 : Classroom 306	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	330	330 : Science Storage Room across from Classroom 306	yes	W1	Plaster	White	Chipping	2	17	Positive
1	3	330	330 : Science Storage Room across from Classroom 306	yes	Door Frame	Wood	Varnish	Chipping	3	0.04	Negative
1	3	330	330 : Science Storage Room across from Classroom 306	yes	W2	Plaster	White	Cracking	3	6.5	Positive
1	3	330	330 : Science Storage Room across from Classroom 306	yes	W3	Plaster	White	Chipping	4	15.6	Positive
1	3	330	330 : Science Storage Room across from Classroom 306	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	330	330 : Science Storage Room across from Classroom 306	yes	Ceiling	Plaster	White	Chipping/Flaking	2	24.3	Positive
1	3	330	330 : Science Storage Room across from Classroom 306	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	307	307 : Classroom 307	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	307	307 : Classroom 307	yes	door frame	Wood	Varnish	Friction	5	0.01	Negative
1	3	307	307 : Classroom 307	yes	W2	Plaster	Orange	None	0	N/A	N/A
1	3	307	307 : Classroom 307	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	307	307 : Classroom 307	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	307	307 : Classroom 307	yes	W4	Plaster	White	Large Hole	2	26.4	Positive
1	3	307	307 : Classroom 307	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	307	307 : Classroom 307	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	329A	329A : Storage Room across from Classroom 308	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	330A	330A : Storage Room across from Classroom 307	yes	W1	Plaster	White	Cracking	3	8.6	Positive
1	3	330A	330A : Storage Room across from Classroom 307	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	330A	330A : Storage Room across from Classroom 307	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	330A	330A : Storage Room across from Classroom 307	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	330A	330A : Storage Room across from Classroom 307	yes	Ceiling	Plaster	White	None	0	N/A	N/A

1	3	330A	330A : Storage Room across from Classroom 307	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	W1	Plaster	White	Hole	1	20	Positive
1	3	308	308 : Classroom 308	yes	Door frame	Wood	Varnish	Chipping	6	0.08	Negative
1	3	308	308 : Classroom 308	yes	W2	Plaster	Orange	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	308	308 : Classroom 308	yes	Pipe	Metal	White	Chipping	1	27	Positive
1	3	308	308 : Classroom 308	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	308	308 : Classroom 308	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	329	329 : Science Storage Room across from Classroom 309	yes	W1	Plaster	White	chipping/cracking	8	18.3	Positive
1	3	329	329 : Science Storage Room across from Classroom 309	yes	W2	Plaster	White	Chipping	2	17	Positive
1	3	329	329 : Science Storage Room across from Classroom 309	yes	W3	Plaster	White	Chipping	2	13.8	Positive
1	3	329	329 : Science Storage Room across from Classroom 309	yes	W4	Plaster	White	Moisture/Chipping/Cracking	12	17.7	Positive
1	3	329	329 : Science Storage Room across from Classroom 309	yes	Ceiling	Plaster	White	Hole/Moisture/Flaking	10	15.6	Positive
1	3	329	329 : Science Storage Room across from Classroom 309	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	W1	Plaster	Orange	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Door	Wood	Varnish	Chipping	6	0.04	Negative
1	3	309	309 : Classroom 309	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	309	309 : Classroom 309	yes	Window Sill	Wood	Varnish	Chipping	20	0.06	Negative
1	3	309	309 : Classroom 309	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	309	309 : Classroom 309	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	309A	309A : Lab Prep Room between Classrooms 309 and 310	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W1	N/A	N/A	N/A	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W2	N/A	N/A	N/A	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W3	N/A	N/A	N/A	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W4	N/A	N/A	N/A	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	3	309B	309B : Chemical Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	Floor	N/A	N/A	N/A	0	N/A	N/A

1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W1	N/A	N/A	N/A	0	N/A	N/A
1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W2	N/A	N/A	N/A	0	N/A	N/A
1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W3	N/A	N/A	N/A	0	N/A	N/A
1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	W4	N/A	N/A	N/A	0	N/A	N/A
1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	3	309C	309C : Storage Closet inside Lab Prep Room between Classrooms 309 and 310	no	Floor	N/A	N/A	N/A	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	W1	Plaster	Orange	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	310	310 : Classroom 310	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	310	310 : Classroom 310	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	W1	Plaster	Orange	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	3	311	311 : Classroom 311	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	311	311 : Classroom 311	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Radiator	Metal	Silver	Flaking	8	0.8	Positive
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door	Metal	Red	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Door Frame	Wood	Red	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	H32	H32 : Hallway outside Classrooms 304 - 311	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	312	312 : Classroom 312	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	3	312	312 : Classroom 312	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	3	312	312 : Classroom 312	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	312	312 : Classroom 312	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	312	312 : Classroom 312	yes	W4	Plaster	White	Flaking	4	3.5	Positive
1	3	312	312 : Classroom 312	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	312	312 : Classroom 312	yes	Floor	Concrete	Varnish	None	0	N/A	N/A
1	A	AA	AA : Attic above Auditorium	no	W1	Brick	N/A	N/A	0	N/A	N/A
1	A	AA	AA : Attic above Auditorium	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	A	AA	AA : Attic above Auditorium	no	W3	Brick	N/A	N/A	0	N/A	N/A
1	A	AA	AA : Attic above Auditorium	no	W4	Brick	N/A	N/A	0	N/A	N/A

1	A	AA	AA : Attic above Auditorium	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	A	AA	AA : Attic above Auditorium	no	Floor	N/A	N/A	N/A	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Radiator	Metal	Silver	None	0	0.18	Negative
1	3	S32	S32 : Stairwell across from Classroom 312	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	S32	Stairwell across from Classroom 312	yes	Newel Post	Metal	Grey	Chipping	3	3.4	Positive
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Stair riser	Metal	Grey	Chipping	10	0.18	Negative
1	3	S32	Stairwell across from Classroom 312	yes	Spindle	Metal	Grey	Chipping	10	4.5	Positive
1	3	S32	S32 : Stairwell across from Classroom 312	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Door	Metal	Blue	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Door Frame	Metal	Blue	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S32	S32 : Stairwell across from Classroom 312	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	W1	Concrete/Brick	White	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	W2	Concrete/Brick	White	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	W3	Concrete/Brick	White	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	325	Special Education Now room 327	yes	W4	Concrete	White	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	325	Special Education Now room 327	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	W1	Plaster	Purple	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	313	313 : Classroom 313	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	313	313 : Classroom 313	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	324A	324A: Classroom 324A Now Classroom 328	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	door frame	Wood	Varnish	Chipping	8	0.01	Negative
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	W2	Plaster	White	Flaking	1	23.4	Positive
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	W3	Plaster	White	Flaking	2	0	Negative
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	W4	Plaster	White	Flaking	4	18	Positive
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	314A	314A : Girl's Restroom across from Classroom 314	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A

1	3	314A-PC	314A-PC : Pipe Chase - Girl's Restroom across from Classroom 314	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	W1	Plaster	White	Flaking	4	9.8	Positive
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	W2	Plaster	White	Flaking	6	13.9	Positive
1	3	314B	Custodial Closet next to Girl's Restroom across from Classroom 314	no	Shelf	Wood	White	Flaking	4	0.25	Negative
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	W3	Plaster	White	Flaking	8	14.4	Positive
1	3	314B	Custodial Closet next to Girl's Restroom across from Classroom 314	no	Pipe	Metal	White	Flaking	7	18.8	Positive
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	W4	Plaster	White	Flaking	2	15.7	Positive
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	Ceiling	Plaster	White	Flaking	6	12.5	Positive
1	3	314B	314B : Custodial Closet next to Girl's Restroom across from Classroom 314	no	Floor	Concrete	Grey	Chipping	20	0.04	Negative
1	3	314	314 : Classroom 314	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	314	314 : Classroom 314	yes	W2	Plaster	Purple	Chipping	3	0	Negative
1	3	314	314 : Classroom 314	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	314	314 : Classroom 314	yes	radiator	Metal	Silver	Chipping	No Access	No Access	No Access
1	3	314	314 : Classroom 314	yes	Window Sill	Wood	Varnish	Friction	20	0.08	Negative
1	3	314	314 : Classroom 314	yes	W4	Plaster	Varnish	None	0	N/A	N/A
1	3	314	314 : Classroom 314	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	314	314 : Classroom 314	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	S31	S31 : Stairwell across from Classroom 314	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	S31	S31 : Stairwell across from Classroom 314	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	S31	S31 : Stairwell across from Classroom 314	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	S31	Stairwell across from Classroom 314	yes	Newel Post	Metal	Grey	Chipping	3	3.3	Positive
1	3	S31	Stairwell across from Classroom 314	yes	Riser	Metal	Grey	Chipping	10	6.9	Positive
1	3	S31	Stairwell across from Classroom 314	yes	Spindle	Metal	Grey	Chipping	10	5.8	Positive
1	3	S31	S31 : Stairwell across from Classroom 314	yes	W4	Plaster	White	Hole	1	23.3	Positive
1	3	S31	S31 : Stairwell across from Classroom 314	yes	Door	Metal	Blue	None	0	0	Negative
1	3	S31	S31 : Stairwell across from Classroom 314	yes	door frame	Metal	Blue	None	0	0	Negative
1	3	S31	S31 : Stairwell across from Classroom 314	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	S31	S31 : Stairwell across from Classroom 314	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	W2	Plaster	White	Cracking/Flaking/Hole	2	5.2	Positive
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	W4	Plaster	White	Hole	1	3.5	Positive
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	H33	H33 : Hallway outside Classrooms 312 - 314	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	315A	315A : Women's Lounge	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	315A	315A : Women's Lounge	yes	door	Wood	Varnish	None	0	N/A	N/A
1	3	315A	315A : Women's Lounge	yes	door frame	Wood	Varnish	Chipping	8	0.04	Negative
1	3	315A	315A : Women's Lounge	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	315A	315A : Women's Lounge	yes	Chair Rail	Wood	Varnish	Chipping	8	0.06	Negative
1	3	315A	315A : Women's Lounge	yes	Baseboard	Wood	Varnish	Chipping	15	0.01	Negative
1	3	315A	315A : Women's Lounge	yes	W3	Plaster	White	Cracking	10	18.2	Positive
1	3	315A	315A : Women's Lounge	yes	Radiator	Metal	Silver	Cracking	4	0.04	Negative
1	3	315A	315A : Women's Lounge	yes	Window Sill	Wood	Varnish	Chipping	5	0.08	Negative
1	3	315A	315A : Women's Lounge	yes	Window Frame	Wood	Varnish	None	0	N/A	N/A
1	3	315A	315A : Women's Lounge	yes	W4	Plaster	White	Cracking	4	30.3	Positive
1	3	315A	315A : Women's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A

1	3	315A	315A : Women's Lounge	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	Door	Wood	Varnish	Chipping	8	0.04	Negative
1	3	315B	315B : Women's Restroom	yes	Door frame	Wood	Varnish	Chipping	8	0.06	Negative
1	3	315B	315B : Women's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	Pipe	Metal	Tan	Cracking	3	5.2	Positive
1	3	315B	315B : Women's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	315B	315B : Women's Restroom	yes	Bathroom Stall Door	Wood	Brown	Chipping	4	0	Negative
1	3	315	315 : Classroom 315	yes	W1	Plaster	Purple	Cracking	1	20.4	Positive
1	3	315	315 : Classroom 315	yes	Door	Wood	Varnish	Chipping	10	0.1	Negative
1	3	315	315 : Classroom 315	yes	Door Frame	Wood	Varnish	Chipping	10	0.1	Negative
1	3	315	315 : Classroom 315	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	315	315 : Classroom 315	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	315	315 : Classroom 315	yes	radiator	Metal	Silver	Chipping	No Access	No Access	No Access
1	3	315	315 : Classroom 315	yes	W4	Plaster	White	Chipping	1	30	Positive
1	3	315	315 : Classroom 315	yes	Window Sill	Wood	Varnish	Chipping	2	0.11	Negative
1	3	315	315 : Classroom 315	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	315	315 : Classroom 315	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	316	316 : Classroom 316	yes	W1	Plaster	White	Flaking	2	5.8	Positive
1	3	316	316 : Classroom 316	yes	W2	Plaster	White	Moisture Damage	20	6.5	Positive
1	3	316	316 : Classroom 316	yes	W3	Plaster	White	Chipping	1	27.3	Positive
1	3	316	316 : Classroom 316	yes	radiator	Metal	Silver	Chipping	No Access	No Access	No Access
1	3	316	316 : Classroom 316	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	3	316	316 : Classroom 316	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	316	316 : Classroom 316	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	W3	Brick	White	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	door	Metal	Red	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	door frame	Metal	Red	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	W4	Brick	White	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S36	S36 : Fire Tower Stairwell next to Classroom 316	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	317	317 : Classroom 317	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	317	317 : Classroom 317	yes	Door	Wood	Varnish	Chipping	10	0.14	Negative
1	3	317	317 : Classroom 317	yes	W2	Plaster	Purple	Cracking	2	0	Negative
1	3	317	317 : Classroom 317	yes	W3	Plaster	White	Chipping	1	30.1	Positive
1	2	317	317 : Classroom 317	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	317	317 : Classroom 317	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	317	317 : Classroom 317	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	317	317 : Classroom 317	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	318	318 : Classroom 318	yes	W1	Plaster	White	Chipping	3	23.5	Positive
1	3	318	318 : Classroom 318	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	318	318 : Classroom 318	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	318	318 : Classroom 318	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	318	318 : Classroom 318	yes	W4	Plaster	Purple	Chipping	1	0.01	Negative
1	3	318	318 : Classroom 318	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	318	318 : Classroom 318	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	327	Storage Room across from Classroom 318	yes	W1	Plaster	White	Chipping	3	11.4	Positive

1	3	327	Storage Room across from Classroom 318	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	3	327	Storage Room across from Classroom 318	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	327	Storage Room across from Classroom 318	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	327	Storage Room across from Classroom 318	yes	Ceiling	Metal	White	Chipping	15	14.7	Positive
1	3	327	Storage Room across from Classroom 318	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	327	Storage Room across from Classroom 318	yes	Shelves	Wood	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	Ceiling	Metal	White	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	328	Storage Room across from Classroom 319	yes	Shelves	Wood	White	None	0	N/A	N/A
1	3	319	319 : Classroom 319	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	319	319 : Classroom 319	yes	Door	Wood	Varnish	Chipped	6	0.06	Negative
1	3	319	319 : Classroom 319	yes	W2	Plaster	Purple	None	0	N/A	N/A
1	3	319	319 : Classroom 319	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	319	319 : Classroom 319	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	319	319 : Classroom 319	yes	Window Sill	Wood	Varnish	Chipping	15	0.27	Negative
1	3	319	319 : Classroom 319	yes	W4	Plaster	White	Chipping	1	32.9	Positive
1	3	319	319 : Classroom 319	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	319	319 : Classroom 319	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	320	320 : Classroom 320	yes	Window Sill	Wood	Varnish	Chipping	15	0.03	Negative
1	3	320	320 : Classroom 320	yes	Baseboard	Wood	Varnish	Chipping	6	0.13	Negative
1	3	320	320 : Classroom 320	yes	W4	Plaster	Purple	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	320	320 : Classroom 320	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	W1	Brick	White	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	W2	Brick	White	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	door	Metal	Red	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	door frame	Metal	Red	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	W4	Brick	White	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	3	S35	S35 : Fire Tower Stairwell next to Classroom 321	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	321	321 : Classroom 321	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	321	321 : Classroom 321	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	321	321 : Classroom 321	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	321	321 : Classroom 321	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	321	321 : Classroom 321	yes	W4	Plaster	Purple	Chipping	1	0	Negative
1	3	321	321 : Classroom 321	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	321	321 : Classroom 321	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	322	322 : Classroom 322	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	322	322 : Classroom 322	yes	W2	Plaster	White	Cracking	8	0.5	Negative
1	3	322	322 : Classroom 322	yes	Radiator	Metal	Silver	Chipping	8	No Access	No Access
1	3	322	322 : Classroom 322	yes	Pipe Sleeve	Metal	White	Chipping	4	0.05	Negative
1	3	322	322 : Classroom 322	yes	W3	Plaster	White	Flaking	10	23.2	Positive
1	3	322	322 : Classroom 322	yes	W4	Plaster	Purple	Chipping	10	29.7	Positive
1	3	322	322 : Classroom 322	yes	Ceiling	Plaster	White	None	0	N/A	N/A

1	3	322	322 : Classroom 322	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	Radiator	Metal	Silver	Chipping	8	0.28	Negative
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	W2	Plaster	White	Chipping/Hole	8	35	Positive
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	W4	Plaster	White	Chipping	6	29.4	Positive
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	H34	H34 : Hallway outside Classrooms 315 - 322	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	3	323A	323A : Men's Lounge	yes	W1	Plaster	White	None	0	N/A	N/A
1	3	323A	323A : Men's Lounge	yes	W2	Plaster	White	Chipping/cracking	8	23.1	Positive
1	3	323A	323A : Men's Lounge	yes	W3	Plaster	White	None	0	N/A	N/A
1	3	323A	323A : Men's Lounge	yes	Radiator	Metal	Silver	Chipping	8	0.5	Negative
1	3	323A	323A : Men's Lounge	yes	W4	Plaster	White	None	0	N/A	N/A
1	3	323A	323A : Men's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	323A	323A : Men's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	3	323B	323B : Men's Restroom	yes	W1	Plaster	White	Holes	2	18.6	Positive
1	3	323B	323B : Men's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	3	323B	323B : Men's Restroom	yes	W3	Plaster	Beige	Flaking/Chipping	4	27.9	Positive
1	3	323B	Men's Restroom	yes	Pipe	Metal	White	Chipping	10	22	Positive
1	3	323B	323B : Men's Restroom	yes	W4	Plaster	White	Holes	2	19.8	Positive
1	3	323B	323B : Men's Restroom	yes	Radiator	Metal	Silver	Chipping	3	0.3	Negative
1	3	323B	323B : Men's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	3	323B	323B : Men's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	W1	Plaster	Blue	Chipping	8	26	Positive
1	2	201	201 : Classroom 201	yes	Door	Wood	Varnish	Chipping	10	0.04	Negative
1	2	201	201 : Classroom 201	yes	Door Frame	Wood	Varnish	Chipping	10	0.13	Negative
1	2	201	201 : Classroom 201	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	W3	Plaster	White	None	0	28.8	Positive
1	2	201	201 : Classroom 201	yes	Window Sill	Wood	Varnish	Chipping	15	0.16	Negative
1	2	201	201 : Classroom 201	yes	W4	Plaster	White	None	0	26.1	Positive
1	2	201	201 : Classroom 201	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	201	201 : Classroom 201	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	S24	S24 : Stairwell across from Classroom 201	yes	W1	Plaster	White	None	0	25.5	Positive
1	2	S24	Stairwell across from Classroom 201	yes	Newel Post	Metal	Grey	Chipping	3	4.7	Positive
1	2	S24	Stairwell across from Classroom 201	yes	Riser	Metal	Grey	Chipping	10	1.9	Positive
1	2	S24	Stairwell across from Classroom 201	yes	Spindle	Metal	Grey	Chipping	10	4	Positive
1	2	S24	S24 : Stairwell across from Classroom 201	yes	Stringer	Concrete	Grey	None	0	N/A	N/A
1	2	S24	S24 : Stairwell across from Classroom 201	yes	W2	Plaster	White	None	0	28.7	Positive
1	2	S24	Stairwell across from Classroom 201	yes	Door	Metal	Blue	None	0	0	Negative
1	2	S24	S24 : Stairwell across from Classroom 201	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	S24	S24 : Stairwell across from Classroom 201	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	S24	S24 : Stairwell across from Classroom 201	yes	radiator	Metal	Silver	None	0	4.2	Positive
1	2	S24	S24 : Stairwell across from Classroom 201	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S24	S24 : Stairwell across from Classroom 201	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	201A	201A : Men's Lounge	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	201A	201A : Men's Lounge	yes	Door	Wood	Varnish	Chipping	10	0.08	Negative
1	2	201A	201A : Men's Lounge	yes	Door Frame	Wood	Varnish	Chipping	10	0.09	Negative
1	2	201A	201A : Men's Lounge	yes	W2	Plaster	Beige	None	0	22.5	Positive
1	2	201A	201A : Men's Lounge	yes	W3	Plaster	Beige	Flaking	3	21.3	Positive
1	2	201A	201A : Men's Lounge	yes	Radiator	Metal	Silver	Chipping	10	4.6	Positive
1	2	201A	201A : Men's Lounge	yes	W4	Plaster	Beige	None	0	25	Positive
1	2	201A	201A : Men's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	201A	201A : Men's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A

1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	Door Frame	Wood	Varnish	Chipping	4	0.04	Negative
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	W2	Plaster	Beige	None	0	17.1	Positive
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	W4	Plaster	Beige	None	0	5.2	Positive
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	Ceiling	Concrete	Beige	Flaking	6	15.3	Positive
1	2	201B	201B : Boy's Restroom across from Classroom 202	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	W1	Plaster	White	Chipping	8	20.8	Positive
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	W2	Plaster	White	None	0	N/A	N/A
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	W3	Plaster	White	Efflorescence	12	16	Positive
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	Pipe	Metal	White	Chipping	10	8.4	Positive
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	W4	Plaster	White	Efflorescence	6	24.1	Positive
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	Ceiling	Plaster	White	Efflorescence	16	17.2	Positive
1	2	201C	201C : Custodial Closet next to Boy's Restroom across from Classroom 202	no	Floor	Concrete	Grey	Chipping	10	0	Negative
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	2	201B-PC	201B-PC : Pipe Chase - Boy's Restroom across from Classroom 202	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	2	201RR	201RR : Men's Restroom	yes	W1	Plaster	Beige	None	0	N/A	N/A
1	2	201RR	Men's Restroom	yes	Pipe	Metal	Beige	Chipping	3	5.5	Positive
1	2	201RR	201RR : Men's Restroom	yes	W2	Plaster	Beige	None	0	N/A	N/A
1	2	201RR	201RR : Men's Restroom	yes	W3	Plaster	Beige	Chipping	8	21.1	Positive
1	2	201RR	201RR : Men's Restroom	yes	W4	Plaster	Beige	None	0	N/A	N/A
1	2	201RR	201RR : Men's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	201RR	201RR : Men's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	202	202 : Classroom 202	yes	W1	Plaster	Blue	None	0	24.8	Positive
1	2	202	202 : Classroom 202	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	2	202	202 : Classroom 202	yes	W3	Plaster	White	None	0	27.6	Positive
1	2	202	202 : Classroom 202	yes	Radiator	Metal	Silver	Chipping	10	2.6	Positive
1	2	202	202 : Classroom 202	yes	Pipe Sleeve	Metal	Pink	Chipping	7	0.07	Negative
1	2	202	202 : Classroom 202	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	2	202	202 : Classroom 202	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	202	202 : Classroom 202	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	223B	223B : Classroom 223	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	223B	223B : Classroom 223	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	223B	223B : Classroom 223	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	223B	223B : Classroom 223	yes	W4	Plaster	White	Flaking	2	3.5	Positive
1	2	223B	223B : Classroom 223	yes	Ceiling	Concrete	White	N/A	0	N/A	N/A
1	2	223B	223B : Classroom 223	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	2	223A	223A : Mail Room opposite Classroom 202	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	223A	223A : Mail Room opposite Classroom 203	yes	W2	Plaster	White	None	0	N/A	N/A

1	2	223A	223A : Mail Room opposite Classroom 203	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	223A	223A : Mail Room opposite Classroom 203	yes	Radiator	Metal	Silver	Chipping	12	No Access	No Access
1	2	223A	223A : Mail Room opposite Classroom 203	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	223A	223A : Mail Room opposite Classroom 203	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	223A	223A : Mail Room opposite Classroom 203	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	2	223C	Office 224	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	223C	Office 224	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	223C	Office 224	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	223C	Office 224	yes	Radiator	Metal	Silver	Chipping	13	No Access	No Access
1	2	223C	Office 224	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	223C	Office 224	yes	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	2	223C	Office 224	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	W2	Plaster	White	None	0	5.8	Positive
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	W4	Plaster	White	Chipping	1	29.3	Positive
1	2	H21	Hallway outside Classrooms 201 - 203	yes	Baseboard	Concrete	Brown	Chipping	10	6.5	Positive
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	H21	H21 : Hallway outside Classrooms 201 - 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	W1	Plaster	Blue	None	0	23.2	Positive
1	2	203	203 : Classroom 203	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	2	203	203 : Classroom 203	yes	Pipe Sleeve	Metal	White	Chipping	3	0	Negative
1	2	203	203 : Classroom 203	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	203	203 : Classroom 203	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	S23	S23 : Stairwell across from Classroom 203	yes	W1	Plaster	White	None	0	25.8	Positive
1	2	S23	Stairwell across from Classroom 203	yes	Newel Post	Metal	Grey	Chipping	3	3	Positive
1	2	S23	Stairwell across from Classroom 203	yes	Riser	Metal	Grey	Chipping	10	2.3	Positive
1	2	S23	Stairwell across from Classroom 203	yes	Spindle	Metal	Grey	Chipping	10	8	Positive
1	2	S23	S23 : Stairwell across from Classroom 203	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	S23	Stairwell across from Classroom 203	yes	Door	Metal	Blue	None	0	0.01	Negative
1	2	S23	S23 : Stairwell across from Classroom 203	yes	W3	Plaster	White	None	0	28.1	Positive
1	2	S23	S23 : Stairwell across from Classroom 203	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	S23	S23 : Stairwell across from Classroom 203	yes	Ceiling	Concrete	White	Chipping	8	0	Negative
1	2	S23	S23 : Stairwell across from Classroom 203	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	203A	203A : Nurse's Office Now Room 226	yes	W1	Wood	White	N/A	0	N/A	N/A
1	2	203A	Nurse's Office Now Room 226	yes	Door	Wood	Varnish	None	0	17	Positive
1	2	203A	203A : Nurse's Office Now Room 226	yes	W2	Plaster	White	holes	10	33.2	Positive
1	2	203A	203A : Nurse's Office Now Room 229	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	2	203A	203A : Nurse's Office Now Room 226	yes	W4	Plaster	White	Chipping	1	23.5	Positive
1	2	203A	203A : Nurse's Office Now Room 226	yes	Cabinet	Wood	White	None	0	0.9	Positive
1	2	203A	203A : Nurse's Office Now Room 232	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	203A	203A : Nurse's Office Now Room 233	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	W2	Plaster	White	None	0	25.3	Positive
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	Window Sill	Wood	White	Chipping	2	22.2	Positive
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	W3	Plaster	White	None	0	24.5	Positive
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	203A-RR	203A-RR : Nurse's Office Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204H	204H : Climate Suite Hallway	yes	W1	Sheetrock	Orange	Chipping	4	0.16	Negative

1	2	204H	204H : Climate Suite Hallway	yes	W2	Sheetrock	Yellow	Chipping	10	0	Negative
1	2	204H	204H : Climate Suite Hallway	yes	W3	Sheetrock	Yellow	Flaking	1	0	Negative
1	2	204H	204H : Climate Suite Hallway	yes	W4	Plaster	White	Chipping	4	20.4	Positive
1	2	204H	204H : Climate Suite Hallway	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204H	204H : Climate Suite Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204	204 : Climate Suite - 1st Office on the right	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	204	204 : Climate Suite - 1st Office on the right	yes	door frame	Metal	Brown	Chipping	4	0	Negative
1	2	204	204 : Climate Suite - 1st Office on the right	yes	W2	Sheetrock	Tan	Chipping	25	0	Negative
1	2	204	204 : Climate Suite - 1st Office on the right	yes	W3	Plaster	White	None	0	23.5	Positive
1	2	204	204 : Climate Suite - 1st Office on the right	yes	W4	Plaster	Tan	Flaking	6	0	Negative
1	2	204	204 : Climate Suite - 1st Office on the right	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204	204 : Climate Suite - 1st Office on the right	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	W1	Sheetrock	Grey	Chipping	4	0	Negative
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	W2	Sheetrock	Grey	Chipping	5	0	Negative
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	W3	Plaster	White	None	0	29.4	Positive
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	W4	Sheetrock	Grey	Chipping	3	0	Negative
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204A	204A : Climate Suite - 2nd Office on the right	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	W1	Sheetrock	Tan	Chipping	7	0	Negative
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	W2	Sheetrock	Tan	Chipping	3	0	Negative
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	W3	Plaster	Tan	Chipping	2	0.1	Negative
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	Window Sill	Wood	Brown	Chipping	3	0.1	Negative
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	W4	Plaster	White	None	0	27.4	Positive
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204B	204B : Climate Suite - Office at end of Suite Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	W1	Sheetrock	Tan	Flaking	6	0	Negative
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	Door Frame	Metal	Brown	Chipping	8	0.12	Negative
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	W2	Sheetrock	Tan	Flaking	3	0	Negative
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	W3	Plaster	Tan	Chipping	3	0	Negative
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	W4	Plaster	Tan	Chipping	1	0.3	Negative
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204C	204C : Climate Suite - 2nd Office on the left	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	W1	Sheetrock	Green	None	0	N/A	N/A
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	Door Frame	Wood	Yellow	Chipping	3	0.12	Negative
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	W2	Plaster	Green	Chipping	6	0	Negative
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	W3	Sheetrock	Green	Chipping	1	0	Negative
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	W4	Sheetrock	Green	None	0	N/A	N/A
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	204D	204D : Climate Suite - 1st Office on the left	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	205	205 : Roster Office	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	205	205 : Roster Office	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	2	205	205 : Roster Office	yes	W3	Plaster	White	None	0	28.7	Positive
1	2	205	205 : Roster Office	yes	Radiator	Metal	Silver	None	0	0.6	Negative
1	2	205	205 : Roster Office	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	2	205	205 : Roster Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	205	205 : Roster Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	206	206 : School Police Office next to Roster Office	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	2	206	206 : School Police Office next to Roster Office	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	2	206	206 : School Police Office next to Roster Office	yes	W3	Plaster	White	Flaking	18	23.2	Positive
1	2	206	206 : School Police Office next to Roster Office	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	2	206	206 : School Police Office next to Roster Office	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	2	206	206 : School Police Office next to Roster Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	206	206 : School Police Office next to Roster Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A

1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	W1	Plaster	White	Chipping	1	23.8	Positive
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	radiator	Metal	Silver	None	0	N/A	N/A
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	H2	H2 : Small Hallway outside of School Police Office and School Psychologist	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	Door frame	Wood	Varnish	Chipping	4	0.12	Negative
1	2	207	207 : Copy Room/Teacher's Lounge	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	Radiator	Metal	Silver	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	Window Sill	Wood	Varnish	Chipping	12	0.14	Negative
1	2	207	207 : Copy Room/Teacher's Lounge	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207	207 : Copy Room/Teacher's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207C	207C : Restroom outside of School Police Office and School Psychologist	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207B	207B Vice Principal	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	W1	Sheetrock	White	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	207A	207A : School Psychologist	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208	208 : Principal's Office	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	208-RR	208-RR : Principal's Office Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	208-RR	208-RR : Principal's Office Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	208-RR	208-RR : Principal's Office Restroom	yes	W3	Plaster	White	None	0	N/A	N/A

1	2	208-RR	208-RR : Principal's Office Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	208-RR	208-RR : Principal's Office Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208-RR	208-RR : Principal's Office Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	208A	208A : Main Office	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	208A	208A : Main Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	208A	208A : Main Office	yes	W3	Plaster	White	Efflorescence	8	25	Positive
1	2	208A	208A : Main Office	yes	Radiator	Metal	Silver	Chipping	3	No Access	No Access
1	2	208A	208A : Main Office	yes	W4	Plaster	White	None	0	29.6	Positive
1	2	208A	208A : Main Office	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208A	208A : Main Office	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	208B	Main Office Closet	yes	W1	Plaster	Green	None	0	N/A	N/A
1	2	208B	Main Office Closet	yes	W2	Plaster	Green	None	0	N/A	N/A
1	2	208B	Main Office Closet	yes	W3	Plaster	White	None	0	10.1	Positive
1	2	208B	Main Office Closet	yes	W4	Plaster	White	None	0	10.6	Positive
1	2	208B	Main Office Closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	208B	Main Office Closet	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	208C	Main Office Sink Closet	no	W1	Plaster	White	None	0	N/A	N/A
1	2	208C	Main Office Sink Closet	no	W2	Plaster	White	Holes/Cracking	6	33.4	Positive
1	2	208C	Main Office Sink Closet	no	W3	Plaster	White	None	0	29.2	Positive
1	2	208C	Main Office Sink Closet	no	W4	Plaster	White	Flaking	8	24.6	Positive
1	2	208C	Main Office Sink Closet	no	Ceiling	Plaster	White	Flaking	8	26.4	Positive
1	2	208C	Main Office Sink Closet	no	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	W1	Plaster	Tan	None	0	21.4	Positive
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	W4	Plaster	Tan	None	0	22.5	Positive
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	Ceiling	Plaster	White	None	0	15	Positive
1	1	GEF	GEF : Grand Entrance Foyer Hallway	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	H22	H22 : Hallway outside Main Office Suite	yes	W1	Plaster	Tan	Flaking	12	19.2	Positive
1	2	H22	H22 : Hallway outside Main Office Suite	yes	W2	Plaster	Tan	None	0	N/A	N/A
1	2	H22	H22 : Hallway outside Main Office Suite	yes	W3	Plaster	Tan	Flaking	3	21.1	Positive
1	2	H22	H22 : Hallway outside Main Office Suite	yes	W4	Plaster	Tan	Flaking	12	22.5	Positive
1	2	H22	H22 : Hallway outside Main Office Suite	yes	Ceiling	Plaster	Tan	Flaking	15	0.01	Negative
1	2	H22	H22 : Hallway outside Main Office Suite	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	BALC	BALC : Auditorium Balcony	yes	W1	Plaster	White	None	0	6.1	Positive
1	2	BALC	BALC : Auditorium Balcony	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	BALC	BALC : Auditorium Balcony	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	BALC	BALC : Auditorium Balcony	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	BALC	BALC : Auditorium Balcony	yes	Window Sill	Wood	White	None	0	2.5	Positive
1	2	BALC	BALC : Auditorium Balcony	yes	Ceiling	Plaster	White	None	0	8.1	Positive
1	2	BALC	BALC : Auditorium Balcony	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	Ceiling	Plaster	White	Flaking	30	0.05	Negative
1	2	PRO	PRO : Auditorium Balcony Projection Room	yes	Floor	Concrete	Grey	Chipping	10	0.04	Negative
1	2	209B	209B : Classroom 209 Server Room	yes	W1	Metal	White	Holes	2	0.01	Negative
1	2	209B	209B : Classroom 209 Server Room	yes	W2	Metal	White	Partially Inaccessible	8	0	Negative
1	2	209B	209B : Classroom 209 Server Room	yes	W3	Plaster	White	Holes/Peeling	6	27.8	Positive
1	2	209B	209B : Classroom 209 Server Room	yes	W4	Plaster	White	Holes	2	19.8	Positive
1	2	209B	209B : Classroom 209 Server Room	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	209B	209B : Classroom 209 Server Room	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A

1	2	209A	209A : Classroom 209 Office	yes	W1	Metal	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Office	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Office	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	209A	209A : Classroom 209 Office	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	2	209A	209A : Classroom 209 Office	yes	W4	Metal	White	Hole	1	0.01	Negative
1	2	209A	209A : Classroom 209 Office	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	2	209A	209A : Classroom 209 Office	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	2	209	209 : Computer Lab 209	yes	W1	Plaster	White	Flaking	3	0.01	Negative
1	2	209	209 : Computer Lab 209	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	209	209 : Computer Lab 209	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	209	209 : Computer Lab 209	yes	Radiator	Metal	Silver	Flaking	8	7.1	Positive
1	2	209	209 : Computer Lab 209	yes	Window Sill	Wood	Varnish	Chipping	30	0.15	Negative
1	2	209	209 : Computer Lab 209	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	2	209	209 : Computer Lab 209	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	209	209 : Computer Lab 209	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	210	210 : Computer Lab 210	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	210	210 : Computer Lab 210	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	210	210 : Computer Lab 210	yes	W3	Plaster	White	None	0	25	Positive
1	2	210	210 : Computer Lab 210	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	2	210	210 : Computer Lab 210	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	210	210 : Computer Lab 210	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	210	210 : Computer Lab 210	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	211	211 : Classroom 211	yes	W1	Plaster	White	None	0	14.5	Positive
1	2	211	211 : Classroom 211	yes	Door Frame	Wood	Varnish	Chipping	8	0.07	Negative
1	2	211	211 : Classroom 211	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	211	211 : Classroom 211	yes	W3	Plaster	White	Flaking	10	21.7	Positive
1	2	211	211 : Classroom 211	yes	Radiator	Metal	Silver	Flaking	8	No Access	No Access
1	2	211	211 : Classroom 211	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	211	211 : Classroom 211	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	211	211 : Classroom 211	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	W1	Plaster	White	None	0	30	Positive
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	baseboard	Concrete	Brown	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	Radiator	Metal	Silver	Chipping	4	8.2	Positive
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	Heat Shield	Metal	Silver	Cracking	4	3.3	Positive
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	H22A	H22A : Hallway outside Computer Lab Classrooms 209 and 210	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	212	212 : Classroom 212	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	212A	212A : Storage Closet in Classroom 212	yes	W1	Plaster	White	None	0	9.4	Positive

1	2	212A	212A : Storage Closet in Classroom 212	yes	W2	Plaster	Green	None	0	N/A	N/A
1	2	212A	212A : Storage Closet in Classroom 212	yes	W3	Plaster	Green	None	0	N/A	N/A
1	2	212A	212A : Storage Closet in Classroom 212	yes	W4	Plaster	Green	None	0	N/A	N/A
1	2	212A	212A : Storage Closet in Classroom 212	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	212A	212A : Storage Closet in Classroom 212	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	S22	S22 : Stairwell across from Classroom 212	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	S22	Stairwell across from Classroom 212	yes	Newel Post	Metal	Grey	Chipping	3	1.8	Positive
1	2	S22	Stairwell across from Classroom 212	yes	Riser	Metal	Grey	Chipping	10	1.6	Positive
1	2	S22	Stairwell across from Classroom 212	yes	Spindle	Metal	Grey	Chipping	10	5.8	Positive
1	2	S22	S22 : Stairwell across from Classroom 212	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	S22	S22 : Stairwell across from Classroom 212	yes	radiator	Metal	Silver	None	0	0.3	Negative
1	2	S22	S22 : Stairwell across from Classroom 212	yes	W3	Plaster	White	None	0	23.2	Positive
1	2	S22	S22 : Stairwell across from Classroom 212	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	S22	Stairwell across from Classroom 212	yes	Door	Metal	Blue	None	0	14.1	Positive
1	2	S22	S22 : Stairwell across from Classroom 212	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S22	S22 : Stairwell across from Classroom 212	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	225	225 : Classroom 225	yes	W1	Plaster/Brick	White	None	0	N/A	N/A
1	2	225	225 : Classroom 225	yes	W2	Plaster/Brick	White	None	0	N/A	N/A
1	2	225	225 : Classroom 225	yes	W3	Plaster/Brick	White	None	0	N/A	N/A
1	2	225	225 : Classroom 225	yes	W4	Concrete Block	Blue	Holes	2	0.16	Negative
1	2	225	225 : Classroom 225	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	225	225 : Classroom 225	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	Door Frame	Wood	Varnish	Chipping	8	0.04	Negative
1	2	213	213 : Classroom 213	yes	W2	Wood	Varnish	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	213	213 : Classroom 213	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	224A	224A : Classroom 224	yes	W1	Plaster/Brick	White	None	0	N/A	N/A
1	2	224A	224A : Classroom 224	yes	W2	Concrete Block	Blue	None	0	N/A	N/A
1	2	224A	224A : Classroom 224	yes	W3	Plaster/Brick	White	Flaking	1	0.01	Negative
1	2	224A	224A : Classroom 224	yes	W4	Plaster/Brick	White	None	0	N/A	N/A
1	2	224A	224A : Classroom 224	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	224A	224A : Classroom 224	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	Window Sill	Wood	Varnish	Chipping	30	0.19	Negative
1	2	214	214 : Classroom 214	yes	Radiator	Metal	Silver	Flaking	4	1.8	Positive
1	2	214	214 : Classroom 214	yes	W4	Wood	Varnish	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	214	214 : Classroom 214	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	214A	214A : Girl's Restroom across from Classroom 214	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	W1	Plaster	White	Flaking	3	12.3	Positive
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	W2	Plaster	White	Flaking	20	14.7	Positive

1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	W3	Plaster	White	Chipping/Flaking	10	16	Positive
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	Pipe	Metal	White	Chipping	8	0.4	Negative
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	W4	Plaster	White	Chipping	3	7.7	Positive
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	Ceiling	Concrete	White	Chipping	8	12	Positive
1	2	214B	214B : Custodial Closet next to Girl's Restroom across from Classroom 214	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	2	214A-PC	214A-PC : Pipe Chase - Girl's Restroom across from Classroom 214	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	2	215A	215A : Women's Lounge	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	215A	215A : Women's Lounge	yes	W2	Plaster	White	None	0	22	Positive
1	2	215A	215A : Women's Lounge	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	215A	215A : Women's Lounge	yes	W4	Plaster	White	None	0	21.3	Positive
1	2	215A	215A : Women's Lounge	yes	Radiator	Metal	Grey	Chipping	4	0.3	Negative
1	2	215A	215A : Women's Lounge	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	215A	215A : Women's Lounge	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	215B	215B : Women's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Door	Metal	Blue	N/A	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Door Frame	Metal	Blue	N/A	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	H23	H23 : Hallway outside Classrooms 212 - 214	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	S21	S21 : Stairwell across from Classroom 214	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	S21	S21 : Stairwell across from Classroom 214	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	S21	S21 : Stairwell across from Classroom 214	yes	radiator	Metal	Silver	None	0	0.25	Negative
1	2	S21	S21 : Stairwell across from Classroom 214	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	S21	Stairwell across from Classroom 214	yes	Newel Post	Metal	Grey	Chipping	4	3.3	Positive
1	2	S21	Stairwell across from Classroom 214	yes	Riser	Metal	Grey	Chipping	10	1.8	Positive
1	2	S21	Stairwell across from Classroom 214	yes	Spindle	Metal	Grey	Chipping	10	4	Positive
1	2	S21	S21 : Stairwell across from Classroom 214	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	S21	Stairwell across from Classroom 214	yes	Door	Metal	Blue	None	0	0.18	Negative
1	2	S21	S21 : Stairwell across from Classroom 214	yes	Ceiling	Concrete	White	None	0	N/A	N/A

1	2	S21	S21 : Stairwell across from Classroom 214	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	215	215 : Classroom 215	yes	W1	Plaster	Blue	None	0	N/A	N/A
1	2	215	215 : Classroom 215	yes	Door Frame	Wood	Varnish	Chipping	8	0.007	Negative
1	2	215	215 : Classroom 215	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	215	215 : Classroom 215	yes	W3	Plaster	White	None	0	16.9	Positive
1	2	215	215 : Classroom 215	yes	Radiator	Metal	Silver	Flaking	4	0.02	Negative
1	2	215	215 : Classroom 215	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	215	215 : Classroom 215	yes	Window Sill	Wood	Varnish	Chipping	12	0.14	Negative
1	2	215	215 : Classroom 215	yes	Radiator	Metal	Silver	Flaking	4	0.02	Negative
1	2	215	215 : Classroom 215	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	215	215 : Classroom 215	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	W1	Plaster	White	None	0	21.3	Positive
1	2	216	216 : Classroom 216	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	W3	Plaster	White	None	0	18.8	Positive
1	2	216	216 : Classroom 216	yes	Radiator	Metal	Silver	None	0	0	Negative
1	2	216	216 : Classroom 216	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	216	216 : Classroom 216	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	W1	Brick	White	Flaking	1	0.23	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	Door	Metal	Brown	Chipping	4	0.24	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	Door Frame	Metal	Brown	Chipping	4	0.24	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	W2	Brick	White	Flaking	6	0.16	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	W3	Metal	White	Flaking	16	0	Negative
1	2	S26	Fire Tower Stairwell next to Classroom 216	yes	Door	Metal	Red	None	0	0	Negative
1	2	S26	Fire Tower Stairwell next to Classroom 216	yes	Door Frame	Metal	Red	None	0	0	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	W4	Brick	White	None	0	N/A	N/A
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	Ceiling	Concrete	White	None	0	0	Negative
1	2	S26	S26 : Fire Tower Stairwell next to Classroom 216	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	W1	Brick	White	None	0	N/A	N/A
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	W2	Brick	White	Cracking	3	0.01	Negative
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	W3	Brick	White	None	0	N/A	N/A
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	W4	Brick	White	None	0	N/A	N/A
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	229	229 : Girl's Locker Room - Enter from the Girl's Gym Stairwell on the 1st Floor	yes	Floor	Concrete	Grey	Chipping	15	0	Negative
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	W1	Brick	White	None	0	N/A	N/A
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	Door	Wood	Varnish	Chipping	8	0.1	Negative
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	W2	Brick	White	None	0	N/A	N/A
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	W3	Brick	White	None	0	N/A	N/A
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	W4	Brick	White	None	0	N/A	N/A
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	Ceiling	Concrete	White	Flaking	15	5.1	Positive
1	2	229A	229A : Storage Room inside Girl's Locker Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	229B	229B : Restroom inside Girl's Locker Room	yes	W1	Brick	White	None	0	N/A	N/A
1	2	229B	229B : Restroom inside Girl's Locker Room	yes	W2	Brick	White	None	0	N/A	N/A
1	2	229B	229B : Restroom inside Girl's Locker Room	yes	W3	Brick	White	None	0	N/A	N/A
1	2	229B	229B : Restroom inside Girl's Locker Room	yes	W4	Brick	White	None	0	N/A	N/A
1	2	229B	229B : Restroom inside Girl's Locker Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A

1	2	229B	229B : Restroom inside Girl's Locker Room	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	W3	Plaster	White	None	0	5.8	Positive
1	2	217	217 : Classroom 217	yes	Radiator	Metal	Silver	None	0	5.4	Positive
1	2	217	217 : Classroom 217	yes	W4	Plaster	White	None	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	217	217 : Classroom 217	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	226	226 : Storage Room across from Classroom 218	yes	W1	Plaster	Green	Chipping	2	6.5	Positive
1	2	226	226 : Storage Room across from Classroom 218	yes	W2	Plaster	Green	Large Holes	6	5.2	Positive
1	2	226	226 : Storage Room across from Classroom 218	yes	W3	Plaster	Green	None	0	N/A	N/A
1	2	226	226 : Storage Room across from Classroom 218	yes	W4	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	2	226	226 : Storage Room across from Classroom 218	yes	Ceiling	Plaster	White	Chipping	6	3.5	Positive
1	2	226	226 : Storage Room across from Classroom 218	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	2	218	218 : Classroom 218	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	218	218 : Classroom 218	yes	Door frame	Wood	Varnish	Chipping	8	0.07	Negative
1	2	218	218 : Classroom 218	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	218	218 : Classroom 218	yes	W3	Plaster	White	None	0	5.8	Positive
1	2	218	218 : Classroom 218	yes	Window Sill	Wood	Varnish	Chipping	30	0.17	Negative
1	2	218	218 : Classroom 218	yes	Radiator	Metal	Silver	Flaking	3	0	Negative
1	2	218	218 : Classroom 218	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	218	218 : Classroom 218	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	218	218 : Classroom 218	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	W1	Plaster	White	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	W2	Plaster	Blue	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	W3	Plaster	White	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	Radiator	Metal	Silver	Flaking	5	2.2	Positive
1	2	219	219 : Classroom 219	yes	W4	Plaster	White	None	0	6.5	Positive
1	2	219	219 : Classroom 219	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	219	219 : Classroom 219	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	227	227 : Storage Room across from Classroom 219	yes	W1	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	2	227	227 : Storage Room across from Classroom 219	yes	W2	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	2	227	227 : Storage Room across from Classroom 219	yes	W3	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	2	227	227 : Storage Room across from Classroom 219	yes	W4	Plaster	White	None	0	5.2	Positive
1	2	227	227 : Storage Room across from Classroom 219	yes	Ceiling	Plaster	White	None	0	3.5	Positive
1	2	227	227 : Storage Room across from Classroom 219	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	220	220 : Classroom 220	yes	W1	Plaster	White	None	0	5.8	Positive
1	2	220	220 : Classroom 220	yes	Door frame	Wood	Varnish	Chipping	8	0.1	Negative
1	2	220	220 : Classroom 220	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	220	220 : Classroom 220	yes	W3	Plaster	White	None	0	16.9	Positive
1	2	220	220 : Classroom 220	yes	Window Sill	Wood	Varnish	Chipping	30	0.1	Negative
1	2	220	220 : Classroom 220	yes	Radiator	Metal	Silver	Chipping	4	0.02	Negative
1	2	220	220 : Classroom 220	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	220	220 : Classroom 220	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	220	220 : Classroom 220	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	W1	Brick	White	Flaking	1	4.9	Positive

1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Door	Metal	Brown	Chipping	8	0.16	Negative
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Door Frame	Metal	Brown	Chipping	8	0.19	Negative
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	W2	Brick	White	Flaking	6	7.7	Positive
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	W3	Metal	Tan	None	0	0	Negative
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Door	Metal	Tan	None	0	0	Negative
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Door Frame	Metal	Tan	None	0	0	Negative
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	W4	Brick	White	Flaking	2	4.1	Positive
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	S25	Fire Tower Stairwell next to Classroom 221	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	W1	Brick	White	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	W2	Brick	White	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	W3	Brick	White	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	W4	Brick	White	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	Floor	Concrete	Grey	Chipping	10	0	Negative
1	2	228	228 : Boy's Locker Room - Enter from the Boy's Gym Stairwell on the 1st Floor	yes	column	Brick	White	Flaking	4	0.02	Negative
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	W1	Brick	White	holes	1	0	Negative
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	W2	Brick	White	holes	3	0	Negative
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	W3	Brick	White	None	0	N/A	N/A
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	W4	Brick	White	holes	2	0	Negative
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	228A	228A : Storage Room inside Boy's Locker Room	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	W1	Brick	White	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	W2	Brick	White	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	W3	Brick	White	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	W4	Brick	White	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	2	228B	228B : Restroom inside Boy's Locker Room	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	W1	Plaster	White	None	0	3.5	Positive
1	2	221	221 : Classroom 221	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	W2	Plaster	White	None	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	W3	Plaster	White	None	0	5.8	Positive
1	2	221	221 : Classroom 221	yes	Radiator	Metal	Silver	Flaking	3	0.5	Negative
1	2	221	221 : Classroom 221	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	221	221 : Classroom 221	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	2	222	222 : Classroom 222	yes	W1	Plaster	White	None	0	21	Positive
1	2	222	222 : Classroom 222	yes	Door	Wood	N/A	N/A	0	N/A	N/A
1	2	222	222 : Classroom 222	yes	Door Frame	Wood	N/A	N/A	0	N/A	N/A
1	2	222	222 : Classroom 222	yes	W2	Plaster	White	None	0	32.3	Positive
1	2	222	222 : Classroom 222	yes	Radiator	Metal	Silver	Flaking	8	1	Positive
1	2	222	222 : Classroom 222	yes	W3	Plaster	White	None	0	33.1	Positive
1	2	222	222 : Classroom 222	yes	Radiator	Metal	Silver	Flaking	8	1	Positive
1	2	222	222 : Classroom 222	yes	W4	Plaster	Blue	None	0	N/A	N/A
1	2	222	222 : Classroom 222	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	222	222 : Classroom 222	yes	Floor	Wood	Varnish	None	0	N/A	N/A

1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	W1	Plaster	White	None	0	28.9	Positive
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	radiator	Metal	Silver	Chipping	6	1.8	Positive
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	Heat Shield	Metal	Silver	Cracking	4	7.2	Positive
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	W3	Plaster	White	None	0	28	Positive
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	baseboard	Concrete	Brown	None	0	N/A	N/A
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	2	H24	H24 : Hallway outside Classrooms 215 - 222	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	GEF-F	GEF-F : Women's Staff Restroom in Grand Entrance Foyer	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	W3	Plaster	White	None	0	32.4	Positive
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	W4	Plaster	White	None	0	24.6	Positive
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	GEF-M	GEF-M : Men's Staff Restroom in Grand Entrance Foyer	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	W1	Plaster	White	None	0	20.9	Positive
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	W2	Plaster	White	None	0	17.6	Positive
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	W3	Plaster	White	None	0	18.6	Positive
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	W4	Plaster	White	None	0	29	Positive
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	Ceiling	Plaster	White	None	0	24.3	Positive
1	1	ST1	ST1 : Storage Room next to Women's Staff Restroom in Grand Entrance Foyer	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	W2	Plaster	Tan	None	0	20.5	Positive
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	W4	Plaster	Tan	None	0	20.7	Positive
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	Ceiling	Plaster	Tan	None	0	22.4	Positive
1	1	ST2	ST2 : Storage Room next to Men's Staff Restroom in Grand Entrance Foyer	yes	Floor	Concrete	N/A	None	0	N/A	N/A

1	1	119	119 : Auditorium	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	119	119 : Auditorium	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	119	119 : Auditorium	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	119	119 : Auditorium	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	119	119 : Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	119	119 : Auditorium	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	119 STAGE	Auditorium	yes	W1	Plaster	White	None	0	6.3	Positive
1	1	119 STAGE	Auditorium	yes	W2	Plaster	Tan	None	0	6.5	Positive
1	1	119 STAGE	Auditorium	yes	Door	Wood	White	Flaking	16	9.4	Positive
1	1	119 STAGE	Auditorium	yes	Door Frame	Wood	White	Flaking	10	11.3	Positive
1	1	119 STAGE	119 STAGE : Auditorium	yes	W3	Plaster	Tan	None	0	N/A	N/A
1	1	119 STAGE	119 STAGE : Auditorium	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	119 STAGE	Auditorium	yes	Door	Wood	White	Flaking	16	6.6	Positive
1	1	119 STAGE	Auditorium	yes	Door Frame	Wood	White	Flaking	10	10.3	Positive
1	1	119 STAGE	119 STAGE : Auditorium	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	119 STAGE	119 STAGE : Auditorium	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	1	105	Classroom 105 now Classroom 107	yes	W1	Plaster/Ceramic	White	None	0	24.8	Positive
1	1	105	Classroom 105 now Classroom 107	yes	W2	Plaster/Ceramic	White	None	0	N/A	N/A
1	1	105	Classroom 105 now Classroom 107	yes	W3	Plaster/Ceramic	White	Efflorescence	6	27.8	Positive
1	1	105	Classroom 105 now Classroom 107	yes	W4	Plaster/Ceramic	Yellow	Flaking	6	1.1	Positive
1	1	105	Classroom 105 now Classroom 107	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	105	Classroom 105 now Classroom 107	yes	Floor	Concrete	N/a	None	0	N/A	N/A
1	1	105A	105A closet now 107Acloset	yes	W1	Plaster	White	None	0	10.1	Positive
1	1	105A	105A closet now 107Acloset	yes	W2	Plaster	White	None	0	9.8	Positive
1	1	105A	105A closet now 107Acloset	yes	W3	Plaster	White	None	0	10.1	Positive
1	1	105A	105A closet now 107Acloset	yes	W4	Plaster	White	None	0	10.1	Positive
1	1	105A	105A closet now 107Acloset	yes	Ceiling	Plaster	White	None	0	12.3	Positive
1	1	105A	105A closet now 107Acloset	yes	Floor	Concrete	N/a	None	0	N/A	N/A
1	1	106	Classroom 106 Now Room 108	yes	W1	Plaster/Ceramic	White	Flaking	2	8.6	Positive
1	1	106	Classroom 106 Now Room 108	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	106	Classroom 106 Now Room 108	yes	W3	Plaster/Ceramic	White	Flaking	3	9.5	Positive
1	1	106	Classroom 106 Now Room 108	yes	W4	Plaster/Ceramic	White	Chipping	2	30.9	Positive
1	1	106	Classroom 106 Now Room 108	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	106	Classroom 106 Now Room 108	yes	Floor	Concrete	N/a	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Closet Now 108	yes	W1	Plaster	Beige	Hole	1	4.1	Positive
1	1	106A	106A : Classroom 106 Closet Now 108	yes	W2	Plaster	Beige	Cracking	4	0.01	Negative
1	1	106A	106A : Classroom 106 Closet Now 108	yes	W3	Plaster	Beige	None	0	N/A	N/A
1	1	106A	106A : Classroom 106 Closet Now 108	yes	W4	Plaster	Beige	Cracking	10	4.3	Positive
1	1	106A	106A : Classroom 106 Closet Now 108	yes	Ceiling	Plaster	Beige	Hole/Flaking	2	3.2	Positive
1	1	106A	106A : Classroom 106 Closet Now 108	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	122	Storeroom opposite Classroom 106 now 108	no	W1	Plaster	White	None	0	10.3	Positive
1	1	122	Storeroom opposite Classroom 106 now 108	no	W2	Plaster	Tan	None	0	N/A	N/A
1	1	122	Storeroom opposite Classroom 106 now 108	no	W3	Plaster	Tan	None	0	N/A	N/A
1	1	122	Storeroom opposite Classroom 106 now 108	no	W4	Plaster	Tan	None	0	N/A	N/A
1	1	122	Storeroom opposite Classroom 106 now 108	no	Ceiling	Plaster	Tan	Cracking	20	0.15	Negative

1	1	122	Storeroom opposite Classroom 106 now 108	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	107	107 : Classroom 107 now classroom 109	yes	W1	Plaster/Ceramic	White	None	0	7.4	Positive
1	1	107	107 : Classroom 107 now classroom 109	yes	W2	Plaster/Ceramic	White	None	0	33.9	Positive
1	1	107	107 : Classroom 107 now classroom 109	yes	W3	Plaster/Ceramic	White	None	0	38.9	Positive
1	1	107	107 : Classroom 107 now classroom 109	yes	W4	Sheetrock	Yellow	None	0	N/A	N/A
1	1	107	107 : Classroom 107 now classroom 109	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	107	107 : Classroom 107 now classroom 109	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	113	113 : Administrative Office 116 now room 110	yes	W1	Plaster	White	Flaking	2	22.4	Positive
1	1	113	113 : Administrative Office 116 now room 110	yes	W2	Plaster	White	Efflorescence/Flaking	4	23.7	Positive
1	1	113	113 : Administrative Office 116 now room 110	yes	W3	Plaster	White	Flaking	3	3.5	Positive
1	1	113	113 : Administrative Office 116 now room 110	yes	W4	Plaster	White	Flaking	1	23.2	Positive
1	1	113	113 : Administrative Office 116 now room 110	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	113	113 : Administrative Office 116 now room 110	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 109	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 110	yes	W2	Plaster	White	None	0	25.1	Positive
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 111	yes	W3	Plaster	White	None	0	23.5	Positive
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 112	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 113	yes	baseboard	Concrete	Brown	None	0	N/A	N/A
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 114	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H12A	H12A : Hallway outside Classroom 105 to Office 116 now hallway 107 to 115	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	108	108 : Classroom 108 now room 111	yes	W1	Plaster/Ceramic	Yellow	Flaking	3	30.6	Positive
1	1	108	108 : Classroom 108 now room 111	yes	W2	Plaster/Ceramic	White	Flaking	2	34.5	Positive
1	1	108	108 : Classroom 108 now room 111	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A
1	1	108	108 : Classroom 108 now room 111	yes	W4	Plaster/Ceramic	White	None	0	N/A	N/A
1	1	108	108 : Classroom 108 now room 111	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108	108 : Classroom 108 now room 111	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	108B	Classroom 108 Closet now room 111 closet	yes	W1	Plaster	White	None	0	8	Positive
1	1	108B	Classroom 108 Closet now room 111 closet	yes	W2	Plaster	Green	None	0	N/A	N/A
1	1	108B	Classroom 108 Closet now room 111 closet	yes	W3	Plaster	White	None	0	3.2	Positive
1	1	108B	Classroom 108 Closet now room 111 closet	yes	W4	Plaster	White	Efflorescence	10	6.7	Positive
1	1	108B	Classroom 108 Closet now room 111 closet	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	108B	Classroom 108 Closet now room 111 closet	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S12	Stairwell across from Classroom 108 now room 111	yes	Riser	Metal	Grey	Friction	10	1.2	Positive
1	1	S12	Stairwell across from Classroom 108 now room 111	yes	Spindle	Metal	Grey	Chipping	10	4.7	Positive
1	1	S12	Stairwell across from Classroom 108 now room 111	yes	Newel Post	Metal	Grey	Chipping	3	4.4	Positive
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	S12	Stairwell across from Classroom 108 now room 111	yes	Door	Metal	Tan	Chipping	12	6.2	Positive
1	1	S12	Stairwell across from Classroom 108 now room 111	yes	Door Frame	Metal	Tan	Chipping	12	8.9	Positive
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S12	S12 : Stairwell across from Classroom 108 now room 111	yes	Floor	Concrete	N/A	None	0	N/A	N/A

1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	W1	Plaster/Ceramic	White	Peeling	8	0	Negative
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	W2	Plaster/Ceramic	White	Peeling	5	0.01	Negative
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	W3	Plaster/Ceramic	White	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	Radiator	Metal	Silver	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	W4	Concrete Block	Yellow	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	110	Classroom 110 across from Classroom 108 now room118 across from room 111	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112/ on site name 119	yes	W1	CMU	White	None	0	18.3	Positive
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112	yes	W2	CMU	Green	Partially Inaccessible	0	0	Negative
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112/ on site name 119	yes	W3	Plaster	White	None	0	17.5	Positive
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112	yes	Pipe	Metal	Green and Tan	Flaking	5	0.14	Negative
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112/ on site name 119	yes	W4	CMU/Plaster	White	None	0	21.9	Positive
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112/ on site name 119	yes	Ceiling	Plaster	White	None	0	13.5	Positive
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112/ on site name 119	yes	Radiator	Metal	Silver	Chipping	3	6.1	Positive
1	1	110B	Mail Room next to Girl's Restroom across from Classroom 112	yes	Floor	Ceramic	N/A	N/A	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	Ceiling	Plaster	White	None	0	21.8	Positive
1	1	110A	Girl's Restroom across from Classroom 108A	yes	Pipe	Metal	White	Flaking	3	6.5	Positive
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	Duct	Metal	White	None	0	N/A	N/A
1	1	110A	110A : Girl's Restroom across from Classroom 108A	yes	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	W1	Plaster	Tan	Flaking	2	18.4	Positive
1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	W2	Plaster	Tan	Flaking/Chipping	6	15.7	Positive
1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	W3	Plaster	Tan	Flaking	12	14.8	Positive
1	1	110C	Custodial Closet next to Girl's Restroom across from Classroom 108A	no	Pipe	Metal	White	Flaking	4	3	Positive

1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	W4	Plaster	Tan	Chipping	3	13.3	Positive
1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	Ceiling	Plaster	Tan	Flaking	2	21.8	Positive
1	1	110C	110C : Custodial Closet next to Girl's Restroom across from Classroom 108A	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	1	110A-PC	110A-PC : Pipe Chase - Girl's Restroom across from Classroom 108A	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	W1	Plaster	Beige	Chipping	2	8.6	Positive
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	W2	Plaster	Beige	Flaking	3	10.3	Positive
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	W3	Plaster	Beige	Flaking	3	10.1	Positive
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	W4	Plaster	Beige	Flaking	2	7.1	Positive
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	Ceiling	Plaster	Beige	None	0	N/A	N/A
1	1	110D	110D : Closet between Custodial Closet and Stairwell across from Classroom 108A	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	108A	108A : Classroom 108A now room 112	yes	W1	Plaster	White	None	0	5.2	Positive
1	1	108A	Classroom 108A now room 112	yes	Door	Metal	White	Holes/Flaking	2	3.5	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	108A	Classroom 108A now room 112	yes	Baseboard	Concrete	Grey	Flaking/Cracking	8	5.8	Positive
1	1	108A	Classroom 108A now room 112	yes	W2	Plaster/Ceramic	White	None	0	35	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	W3	Plaster	White	None	0	11.2	Positive
1	1	108A	Classroom 108A now room 112	yes	Baseboard	Concrete	Grey	Flaking/Cracking	8	6.5	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	Radiator	Metal	Silver	Chipping	3	0.01	Negative
1	1	108A	Classroom 108A now room 112	yes	Window Frame	Wood	White	Cracking	3	5.2	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	W4	Plaster	Yellow	None	0	3.5	Positive
1	1	108A	Classroom 108A now room 112	yes	Baseboard	Concrete	Grey	Flaking/Cracking	8	16.9	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	Ceiling	Plaster	White	None	0	18.8	Positive
1	1	108A	108A : Classroom 108A now room 112	yes	Floor	Concrete	Grey	Chipping	2	0.01	Negative
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	W1	Brick	White	None	0	5.6	Positive
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	W2	Brick	White	None	0	13.3	Positive
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	W3	Brick	White	None	0	7	Positive
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	W4	Brick	White	None	0	5.7	Positive
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	109	109 : Custodial Storeroom opposite Cleaning Staff Office	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Door	Wood	Varnish	None	0	N/A	N/A

1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Radiator	Metal	Silver	None	0	0.1	Negative
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S11	Stairwell next to Girl's Restroom	yes	Newel Post	Metal	Grey	Chipping	3	2.7	Positive
1	1	S11	Stairwell next to Girl's Restroom	yes	Riser	Metal	Grey	Chipping	10	7.7	Positive
1	1	S11	Stairwell next to Girl's Restroom	yes	Spindles	Metal	Grey	Chipping	10	3.8	Positive
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Door Frame	Metal	Blue	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S11	S11 : Stairwell next to Girl's Restroom	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	W2	Plaster	White	None	0	16.9	Positive
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	W4	Plaster	White	Flaking/Cracking	5	18.8	Positive
1	1	H13	Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Electrical Panel	Metal	White	Chipping	2	16.9	Positive
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H13	H13 : Hallway outside Classrooms 108 - 109 now rooms 111-112	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	W1	Brick	White	Flaking	30	2.3	Positive
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	W2	Brick	White	Flaking	40	8	Positive
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	W3	Sheetrock	White	None	0	N/A	N/A
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	W4	Brick	White	Flaking	15	4.6	Positive
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	123	119 : Cleaning Staff Office next to North Fan Room and Staff Parking Lot	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	W1	Sheetrock	White	None	0	N/A	N/A

1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	W2	Brick	White	None	0	N/A	N/A
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	W3	Brick	White	None	0	N/A	N/A
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	Pipe	Metal	White	Flaking	6	18.8	Positive
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	W4	Brick	White	None	0	N/A	N/A
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	123A	119A : Cleaning Staff Office Restroom next to North Fan Room and Staff Parking Lot	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	W1	Brick	White	Chipping	2	10	Positive
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	W2	Brick	White	Chipping	5	8.4	Positive
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Window Frame	Wood	White	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	W3	Brick	White	Chipping	3	7.3	Positive
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Radiator	Metal	Silver	Chipping	3	0.6	Negative
1	1	120	Girl's Cafeteria Lunch Room 114	yes	W4	Brick	White	Chipping	2	10.1	Positive
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Radiator	Metal	Silver	Chipping	2	0.6	Negative
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	120	Girl's Cafeteria Lunch Room 114	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	W1	Brick	White	Chipping	2	11.3	Positive
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	W2	Brick	White	Chipping	3	6.6	Positive
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Radiator	Metal	Silver	Flaking	3	0.02	Negative
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	W3	Brick	White	Chipping	3	9.7	Positive
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Radiator	Metal	Silver	Flaking	4	0.02	Negative
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door	Metal	Brown	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door Frame	Metal	Brown	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Pipe	Metal	Tan	Flaking	4	4.4	Positive
1	1	115	Boy's Cafeteria Lunch Room 115	yes	W4	Brick	White	Chipping	2	7.3	Positive
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Door Frame	Wood	Varnish	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	115	Boy's Cafeteria Lunch Room 115	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	115A	115A : Kitchen	no	W1	Brick	White	None	0	N/A	N/A
1	1	115A	115A : Kitchen	no	W2	Brick	White	Flaking	6	0	Negative
1	1	115A	115A : Kitchen	no	W3	Brick	White	None	0	N/A	N/A
1	1	115A	115A : Kitchen	no	W4	Brick	White	None	0	N/A	N/A
1	1	115A	115A : Kitchen	no	Ceiling	Concrete	White	Flaking	3	0	Negative
1	1	115A	115A : Kitchen	no	Duct	Metal	White	Flaking	14	0.02	Negative
1	1	115A	115A : Kitchen	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	100A	100A : Building Engineer's Office	no	W1	Brick	White	Chipping	5	9.5	Positive
1	1	100A	100A : Building Engineer's Office	no	W2	Brick	White	Chipping	18	7.7	Positive
1	1	100A	100A : Building Engineer's Office	no	W3	Sheetrock	White	None	0	N/A	N/A
1	1	100A	100A : Building Engineer's Office	no	W4	Brick	White	Chipping	6	11.9	Positive
1	1	100A	100A : Building Engineer's Office	no	Ceiling	Concrete	White	None	0	N/A	N/A

1	1	100A	100A : Building Engineer's Office	no	Floor	Concrete	Grey	Chipping	10	0	Negative
1	1	100B	100B : Building Engineer's Office Restroom	no	W1	Sheetrock	White	None	0	N/A	N/A
1	1	100B	100B : Building Engineer's Office Restroom	no	W2	Brick	White	None	0	N/A	N/A
1	1	100B	100B : Building Engineer's Office Restroom	no	W3	Brick	White	None	0	N/A	N/A
1	1	100B	100B : Building Engineer's Office Restroom	no	W4	Brick	White	None	0	N/A	N/A
1	1	100B	100B : Building Engineer's Office Restroom	no	Pipe	Metal	White	Flaking	5	6.8	Positive
1	1	100B	100B : Building Engineer's Office Restroom	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	100B	100B : Building Engineer's Office Restroom	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	W1	Plaster	White	None	0	15.3	Positive
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Radiator	Metal	Silver	Chipping	4	0.05	Negative
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Heat Shield	Metal	Silver	Chipping	3	0.7	Positive
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	W3	Plaster	White	None	0	23.9	Positive
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	W4	Plaster	White	None	0	22	Positive
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door	Wood	Red	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H14	H14 : Hallway outside Cafeteria and Fan Rooms	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	101	Classroom 101 (Art)	yes	W1	Brick	White	Chipping	2	4.1	Positive
1	1	101	Classroom 101 (Art)	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	101	Classroom 101 (Art)	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	101	Classroom 101 (Art)	yes	W2	Brick	White	Chipping	2	5.5	Positive
1	1	101	Classroom 101 (Art)	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	101	Classroom 101 (Art)	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	101	Classroom 101 (Art)	yes	W3	Brick	White	Flaking	4	7.2	Positive
1	1	101	Classroom 101 (Art)	yes	Radiator	Metal	Silver	Chipping	3	0.7	Positive
1	1	101	Classroom 101 (Art)	yes	W4	Brick	White	Chipping	1	7.6	Positive
1	1	101	Classroom 101 (Art)	yes	Ceiling	Plaster	White	Chipping	4	5.8	Positive
1	1	101	Classroom 101 (Art)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	W1	Plaster	Yellow	None	0	33.8	Positive
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Radiator	Metal	Silver	Chipping	3	3.9	Positive
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	S14	Stairwell across from Classroom 101	yes	Newel Post	Metal	Grey	Chipping	3	6.9	Positive
1	1	S14	Stairwell across from Classroom 101	yes	riser	Metal	Grey	Chipping	10	5.2	Positive
1	1	S14	Stairwell across from Classroom 101	yes	spindle	Metal	Grey	Chipping	10	5.2	Positive
1	1	S14	S14 : Stairwell across from Classroom 101	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	W3	Plaster	Yellow	None	0	25.4	Positive
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Door/Door Frame	Metal	Blue	N/A	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	W4	Plaster	Yellow	None	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	S14	S14 : Stairwell across from Classroom 101	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	111	111 : Boy's Restroom	yes	W1	Plaster	Tan	None	0	N/A	N/A
1	1	111	111 : Boy's Restroom	yes	W2	Plaster	Tan	Flaking/Chipping	30	18.5	Positive

1	1	111	111 : Boy's Restroom	yes	W3	Plaster	Tan	Flaking/Chipping	10	22.7	Positive
1	1	111	111 : Boy's Restroom	yes	W4	Plaster	Tan	None	0	N/A	N/A
1	1	111	111 : Boy's Restroom	yes	Ceiling	Plaster	Tan	Flaking	8	15.4	Positive
1	1	111	111 : Boy's Restroom	yes	Floor	Concrete	Grey	Chipping	2	0.01	Negative
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	W1	Plaster	Tan	chipping/flaking	16	19	Positive
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	W2	Plaster	Tan	chipping/flaking	4	20.3	Positive
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	W3	Plaster	Tan	chipping/flaking	12	0	Negative
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	Pipe	Metal	Tan	Flaking	10	0.02	Negative
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	W4	Plaster	Tan	chipping/flaking	20	15.1	Positive
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	Ceiling	Plaster	Tan	chipping/flaking	30	0	Negative
1	1	111B	111B : Custodial Closet next to Boy's Restroom across from Classroom 101	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	W1	CMU	N/A	N/A	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	W2	CMU	N/A	N/A	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	W3	CMU	N/A	N/A	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	W4	CMU	N/A	N/A	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	1	111B-PC	111B-PC : Pipe Chase - Boy's Restroom across from Classroom 101	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	W1	Plaster	Tan	None	0	N/A	N/A
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	W2	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible	Partially Inaccessible
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	W3	Plaster	Tan	None	0	N/A	N/A
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	W4	Plaster	Tan	Flaking	4	22.9	Positive
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	111C	111C : Closet between Custodial Closet and Stairwell across from Classroom 101	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	114	114 : Office 114 now 116	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	114 : Office 114 now 116	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	114 : Office 114 now 116	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	114 : Office 114 now 116	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	114 : Office 114 now 116	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	114	114 : Office 114 now 116	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	112	112 : Office 112 now room 117	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	102	Classroom 102 (Art)	yes	W1	Brick	White	Chipping	2	14.2	Positive
1	1	102	Classroom 102 (Art)	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A

1	1	102	Classroom 102 (Art)	yes	W2	Brick	White	None	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	W3	Brick	White	Flaking	3	6.5	Positive
1	1	102	Classroom 102 (Art)	yes	Radiator	Metal	Silver	Chipping	3	2.3	Positive
1	1	102	Classroom 102 (Art)	yes	W4	Brick	Blue	None	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	Door	Wood	Varnish	N/A	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	Door Frame	Wood	Varnish	N/A	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102	Classroom 102 (Art)	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Storage Room	yes	W1	Brick	Tan	Partially Inaccessible	0	7.1	Positive
1	1	102A	102A : Classroom 102 Storage Room	yes	W2	Brick	Tan	Partially Inaccessible	0	5.3	Positive
1	1	102A	102A : Classroom 102 Storage Room	yes	W3	Brick	Tan	Partially Inaccessible	0	4.4	Positive
1	1	102A	102A : Classroom 102 Storage Room	yes	Shelving	Wood	Varnish	Partially Inaccessible	0	0.02	Negative
1	1	102A	102A : Classroom 102 Storage Room	yes	W4	Brick	Tan	Partially Inaccessible	0	4.5	Positive
1	1	102A	102A : Classroom 102 Storage Room	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	102A	102A : Classroom 102 Storage Room	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	1	101A	101A : Classroom 101 Storage Room	yes	W1	Brick	Tan	Partially Inaccessible	0	6.1	Positive
1	1	101A	101A : Classroom 101 Storage Room	yes	W2	Brick	Tan	Partially Inaccessible	0	3	Positive
1	1	101A	101A : Classroom 101 Storage Room	yes	W3	Brick	Tan	Partially Inaccessible	0	4.4	Positive
1	1	101A	101A : Classroom 101 Storage Room	yes	Shelving	Wood	Varnish	Partially Inaccessible	0	0.04	Negative
1	1	101A	101A : Classroom 101 Storage Room	yes	W4	Brick	Tan	Partially Inaccessible	0	10.1	Positive
1	1	101A	101A : Classroom 101 Storage Room	yes	Ceiling	Plaster	White	Scrapes/Hole	6	5.6	Positive
1	1	101A	101A : Classroom 101 Storage Room	yes	Floor	Wood	N/A	N/A	0	N/A	N/A
1	1	S13	S13 : Stairwell across from Classroom 102	yes	W1	Plaster	White	None	0	25.6	Positive
1	1	S13	S13 : Stairwell across from Classroom 102	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	S13	S13 : Stairwell across from Classroom 102	yes	Door/Door Frame	Metal	Blue	None	0	N/A	N/A
1	1	S13	S13 : Stairwell across from Classroom 102	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	S13	Stairwell across from Classroom 102	yes	Newel Post	Metal	Grey	Chipping	3	3.9	Positive
1	1	S13	Stairwell across from Classroom 102	yes	riser	Metal	Grey	Chipping	10	6	Positive
1	1	S13	Stairwell across from Classroom 102	yes	spindle	Metal	Grey	Chipping	10	4.1	Positive
1	1	S13	S13 : Stairwell across from Classroom 102	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	S13	S13 : Stairwell across from Classroom 102	yes	Radiator	Metal	Silver	Chipping	3	4.2	Positive
1	1	S13	S13 : Stairwell across from Classroom 102	yes	Ceiling	Plaster	White	Chipping	2	0.04	Negative
1	1	S13	S13 : Stairwell across from Classroom 102	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	W1	Plaster	Yellow	None	0	N/A	N/A
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	W2	Plaster	Yellow	None	0	N/A	N/A
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	Electrical Panel	Metal	White	Chipping	3	5.2	Positive
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	W3	Plaster	Yellow	None	0	N/A	N/A
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	W4	Plaster	White	Chipping	3	22.8	Positive
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	H11	H11 : Hallway outside Classrooms 101 - 102	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	W1	Brick	White	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	W2	Sheetrock	White	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	W3	Sheetrock	White	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	W4	Sheetrock	White	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	Ceiling	Sheetrock	White	None	0	N/A	N/A
1	1	103C	103C : Foyer outside Classrooms 103A & 103B	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	103B	103B : Classroom 103B now room 103	yes	W1	Brick	White	None	0	N/A	N/A
1	1	103B	103B : Classroom 103B now room 103	yes	door frame	Metal	Brown	Chipping	8	0	Negative
1	1	103B	103B : Classroom 103B now room 103	yes	W2	Brick	White	Chipping	10	3.5	Positive
1	1	103B	103B : Classroom 103B now room 103	yes	W3	Brick	White	None	0	N/A	N/A
1	1	103B	103B : Classroom 103B now room 103	yes	Radiator	Metal	Silver	Chipping	3	0.05	Negative
1	1	103B	103B : Classroom 103B now room 103	yes	W4	Brick	Yellow	Flaking	3	7	Positive

1	1	103B	103B : Classroom 103B now room 103	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	1	103B	103B : Classroom 103B now room 103	yes	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	121	Storeroom opposite Classroom 103A	no	W1	Plaster	White	Chipping	6	14.4	Positive
1	1	121	Storeroom opposite Classroom 103A	no	W2	Plaster	Tan	None	0	N/A	N/A
1	1	121	Storeroom opposite Classroom 103A	no	W3	Plaster	Tan	None	0	N/A	N/A
1	1	121	Storeroom opposite Classroom 103A	no	W4	Plaster	White	Chipping	18	23	Positive
1	1	121	Storeroom opposite Classroom 103A	no	Ceiling	Plaster	Tan	None	0	N/A	N/A
1	1	121	Storeroom opposite Classroom 103A	no	Floor	Concrete	N/A	None	0	N/A	N/A
1	1	103A	Classroom 103A now room 104	yes	W1	Sheetrock	Blue	Holes/Chipping	6	0	Negative
1	1	103A	Classroom 103A now room 104	yes	Door Frame	Metal	Brown	Chipping	6	0	Negative
1	1	103A	Classroom 103A now room 104	yes	W2	Brick	Yellow	Chipping/Flaking	5	0	Negative
1	1	103A	Classroom 103A now room 104	yes	W3	CMU	White	Chipping	2	0	Negative
1	1	103A	Classroom 103A now room 104	yes	W4	Brick	White	Cracking	2	2.2	Positive
1	1	103A	Classroom 103A now room 104	yes	Radiator	Metal	Silver	Chipping	3	0	Negative
1	1	103A	Classroom 103A now room 104	yes	Ceiling	Concrete	White	Holes	30	3.5	Positive
1	1	103A	Classroom 103A now room 104	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104	Classroom 104 now room 105	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	Classroom 104 Closet now 105 closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104A	104A : Classroom 104A	yes	W1	Brick	White	Chipping	4	8	Positive
1	1	104A	104A : Classroom 104A	yes	W2	Brick	White	Chipping	2	0.23	Negative
1	1	104A	104A : Classroom 104A	yes	W3	Brick	White	None	0	N/A	N/A
1	1	104A	104A : Classroom 104A	yes	W4	CMU	Green	None	0	N/A	N/A
1	1	104A	104A : Classroom 104A	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	1	104A	104A : Classroom 104A	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	W1	Brick	White	None	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	W2	Brick	White	None	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	W3	Brick	White	None	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	W4	Brick	White	None	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-1	104A-1 : Classroom 104A Window Wall Closet	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104A-2	104A-2 : Classroom 104A Hallway Wall Closet	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	W1	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104B	104B : Classroom 104B	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	W1	N/A	N/A	N/A	0	N/A	N/A

1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	W2	N/A	N/A	N/A	0	N/A	N/A
1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	W3	N/A	N/A	N/A	0	N/A	N/A
1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	W4	N/A	N/A	N/A	0	N/A	N/A
1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	104C	104C : Foyer outside of Classrooms 104A & 104B	yes	Floor	N/A	N/A	N/A	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	W1	Plaster	White	None	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	W2	Plaster	White	None	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	W3	Plaster	White	None	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	W4	Plaster	White	None	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	Ceiling	N/A	N/A	N/A	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	1	H12	H12 : Hallway outside Classrooms 103 - 104 now rooms 103-105	yes	Baseboard	Concrete	Grey	Chipping	12	3.3	Positive
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	W1	Brick	Grey & White	Chipping/Flaking	30	0.03	Negative
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	W2	Brick	Grey & White	Chipping/Flaking	10	0.11	Negative
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	W3	Brick	Grey & White	Chipping/Flaking	12	0.04	Negative
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	W4	Brick	Grey & White	Chipping/Flaking	10	0.07	Negative
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	Ceiling	Concrete	White	Flaking	50	0.07	Negative
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	Hand Rail	Metal	Grey	Friction	25	18.7	Positive
1	B	100	100 : South Fan Room # 1 across from Classroom 101	no	Duct Work	Metal	White	Flaking	75	1.7	Positive
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	W2	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	W3	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	W4	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-1	100-1 : Ramp between Fan Room # 1 and the Auditorium Fan Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	W2	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	W3	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	W4	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	100-RAS	100-RAS : South Fan Room # 1 and Auditorium Fan Room Return Airshaft/Pipe Shaft	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	W1	Brick	Grey & White	Flaking	50	7.9	Positive
1	B	5	Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Door	Wood	Grey	Friction	4	11.6	Positive
1	B	5	Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Door Frame	Wood	Grey	Friction	4	11.6	Positive

1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	W2	Brick	Grey & White	Flaking	50	7.7	Positive
1	B	5	Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Door	Wood	Grey	Friction	4	11.8	Positive
1	B	5	Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Door Frame	Wood	Grey	Friction	4	11.8	Positive
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	W3	Concrete	Grey & White	Flaking	250	4.7	Positive
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	W4	Concrete	Grey & White	Flaking	250	4.1	Positive
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Pipe	Metal	Grey & White	Flaking	12	2.3	Positive
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Ceiling	Concrete	White	Flaking	75	0.09	Negative
1	B	5	5 : Auditorium Fan Room # 3 (between Electrical Room and South Fan Room Ramp)	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	W1	Brick	Grey & White	Flaking	50	0.04	Negative
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	W2	Brick	Grey & White	Flaking	25	0.27	Negative
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	W3	Brick	Grey & White	Flaking	50	0.08	Negative
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	W4	Brick	Grey & White	Flaking	25	0.07	Negative
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	Ceiling	Concrete	White	Flaking	200	0.04	Negative
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	Duct Work	Metal	White	Flaking	20	2.2	Positive
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	Hand Rail	Metal	Grey	Friction	20	10.1	Positive
1	B	100C	100C : North Fan Room # 2 next to Staff Parking Lot	no	Steps	Concrete	Grey	Flaking	20	9.1	Positive
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	W2	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	W3	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	W4	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-1	100C-1 : Ramp between Fan Room # 2 and the Return Airshaft	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	W1	Brick	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	W3	Brick	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	W4	Brick	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	100C-RAS	100C-RAS : North Fan Room # 2 Return Airshaft	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	W1	Plaster	White	Cracking	4	10.6	Positive
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	W2	Plaster	White	Flaking	40	10.8	Positive
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	W3	Plaster	White	Flaking	20	8.9	Positive
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	W4	Plaster	White	Flaking	40	8	Positive
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	005C-1	005C-1 : Foyer to Previous Restroom below Auditorium Stage	no	Floor	Concrete	Grey	None	0	N/A	N/A
1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	W1	Plaster	White	None	0	N/A	N/A
1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	W2	Plaster	White	Flaking	25	9.3	Positive

1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	W3	Plaster	White	None	0	N/A	N/A
1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	W4	Plaster	White	None	0	N/A	N/A
1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	Ceiling	Plaster	White	Flaking	10	9.4	Positive
1	B	005C-2	005C-2 : Previous Restroom below Auditorium Stage	no	Floor	Wood	Brown	Friction	25	0.07	Negative
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	W1	Plaster	White	Flaking	3	0.01	Negative
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Hand Rail	Metal	Grey	Friction	2	0.6	Negative
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Steps	Concrete	Grey	Friction	6	2	Positive
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	W2	Plaster	White	None	0	N/A	N/A
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	W3	Plaster	White	None	0	N/A	N/A
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	W4	Plaster	White	None	0	N/A	N/A
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Hand Rail	Metal	Grey	Friction	2	9.1	Positive
1	B	005C-3	005C-3 : Old Dressing Room next to Auditorium Supply Plenum	no	Steps	Concrete	Grey	Friction	4	2.9	Positive
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	W3	Concrete	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	W4	Brick	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	005D	005D : Auditorium Supply Plenum (below Auditorium)	no	Duct Work	Metal	White	Flaking	200	0.01	Negative
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	W1	Brick	Grey & White	Flaking	150	6.5	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Door/Door Frame	Metal	Brown	Scrapes	20	0.4	Negative
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Hand Rail	Metal	Grey	Friction	10	1.4	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Steps	Concrete	Grey	Flaking	20	9.7	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	W2	Brick	Grey & White	Flaking	300	6.1	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Pipe	Metal	Grey & White	Flaking	12	0.04	Negative
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Door	Wood	Grey	Friction	15	6.4	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Door Frame	Wood	Grey	Friction	15	6.4	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	W3	Brick	Grey & White	Flaking	50	1.2	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	W4	Brick	Grey & White	Flaking	100	14.3	Positive
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Ceiling	Concrete	White	Flaking	750	0.02	Negative
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Pipes	Metal	White	Flaking	50	0.18	Negative
1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Floor	Concrete	N/A	N/A	0	0.1	Negative

1	B	4	Electrical Room between Auditorium Fan Room and Boiler Room	no	Platforms	Concrete	Grey	Flaking	10	0.01	Negative
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	W1	Brick	Grey & White	Flaking	12	0.4	Negative
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	W2	Concrete	Grey & White	Flaking	15	0.12	Negative
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	Pipe	Metal	Grey & White	Flaking	6	0.13	Negative
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	W3	Brick	White	None	0	N/A	N/A
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	W4	Brick	Grey & White	None	0	N/A	N/A
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	Stall Door	Wood	Blue and Green	Flaking	8	8.7	Positive
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	Ceiling	Concrete	White	Flaking	12	0.09	Negative
1	B	004A	004A : Restroom inside Electrical Room between Auditorium Fan Room and Boiler Room	no	Floor	Concrete	Grey	Flaking	6	0.04	Negative
1	B	3	3 : Boiler Room	no	W1	Brick	Grey & White	Flaking	750	0.09	Negative
1	B	3	3 : Boiler Room	no	Steps	Metal	Grey	Friction	15	11.9	Positive
1	B	3	3 : Boiler Room	no	Hand Rail	Metal	Grey	Friction	10	10.1	Positive
1	B	3	3 : Boiler Room	no	W2	Concrete	Grey & White	Flaking	1000	0.28	Negative
1	B	3	3 : Boiler Room	no	Pipes	Metal	White	Flaking	30	0.11	Negative
1	B	3	3 : Boiler Room	no	W3	Concrete	Grey & White	Flaking	750	4.9	Positive
1	B	3	3 : Boiler Room	no	W4	Concrete	Grey & White	Flaking	350	0.11	Negative
1	B	3	3 : Boiler Room	no	Pipes	Metal	White	Flaking	30	0.03	Negative
1	B	3	3 : Boiler Room	no	Ceiling	Concrete	White	Flaking	2500	0	Negative
1	B	3	3 : Boiler Room	no	Pipes	Metal	White	Flaking	50	0	Negative
1	B	3	3 : Boiler Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	3	3 : Boiler Room	no	Platforms	Concrete	Grey	Flaking	12	15.4	Positive
1	B	2	2 : Old Coal Storage Room	no	W1	Concrete	N/A	N/A	0	N/A	N/A
1	B	2	2 : Old Coal Storage Room	no	W2	Brick	N/A	N/A	0	N/A	N/A
1	B	2	2 : Old Coal Storage Room	no	W3	Concrete	N/A	N/A	0	N/A	N/A
1	B	2	2 : Old Coal Storage Room	no	W4	Concrete	N/A	N/A	0	N/A	N/A
1	B	2	2 : Old Coal Storage Room	no	Ceiling	Concrete	N/A	N/A	0	N/A	N/A
1	B	2	2 : Old Coal Storage Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	W1	Concrete	White	None	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	W2	Concrete	White	None	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	W3	Concrete	White	None	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	Pipes	Metal	White	Flaking	15	0	Negative
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	W4	Concrete	White	None	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	003A	003A : Emergency Generator/Oil Pump Room next to Boiler Room	no	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	7	7 : Girl's Gym	yes	W1	Brick	Yellow	None	0	N/A	N/A
1	B	7	7 : Girl's Gym	yes	W2	Brick	Yellow	None	0	N/A	N/A
1	B	7	7 : Girl's Gym	yes	W3	Brick	N/A	N/A	0	N/A	N/A
1	B	7	7 : Girl's Gym	yes	W4	Brick	Yellow	None	0	N/A	N/A
1	B	7	7 : Girl's Gym	yes	Ceiling	Plaster	White	None	0	14.3	Positive
1	B	7	7 : Girl's Gym	yes	Ceiling	Concrete	White	None	0	15.2	Positive

1	B	7	7 : Girl's Gym	yes	Pipes	Metal	White	Flaking	100	0.06	Negative
1	B	7	7 : Girl's Gym	yes	Radiators	Metal	Grey	Flaking	55	4.1	Positive
1	B	7	7 : Girl's Gym	yes	Trusses	Metal	White	Flaking	50	25.2	Positive
1	B	7	7 : Girl's Gym	yes	Floor	Concrete	Tan	Chipping	100	0	Negative
1	B	11	11 : Boy's Gym	yes	W1	Brick	Yellow & White	None	0	N/A	N/A
1	B	11	11 : Boy's Gym	yes	W2	Brick	Yellow & White	None	0	N/A	N/A
1	B	11	11 : Boy's Gym	yes	W3	Brick	White	None	0	N/A	N/A
1	B	11	11 : Boy's Gym	yes	W4	Brick	Yellow & White	None	0	N/A	N/A
1	B	11	11 : Boy's Gym	yes	Ceiling	Plaster	White	None	0	18.3	Positive
1	B	11	11 : Boy's Gym	yes	Ceiling	Concrete	White	None	0	16.9	Positive
1	B	11	11 : Boy's Gym	yes	Pipes	Metal	Tan	Flaking	400	0.25	Negative
1	B	11	11 : Boy's Gym	yes	Radiators	Metal	Grey	Flaking	55	3.2	Positive
1	B	11	11 : Boy's Gym	yes	Trusses	Metal	White	Flaking	55	27.8	Positive
1	B	11	11 : Boy's Gym	yes	Floor	Concrete	Tan	Chipping	200	0	Negative
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	W1	Brick	White	None	0	N/A	N/A
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	W2	Brick	White	Partially Inaccessible	0	0.08	Negative
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	W3	Concrete	White	Partially Inaccessible	0	0.08	Negative
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	W4	Brick	White	Partially Inaccessible	0	0.09	Negative
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	Ceiling	Concrete	White	None	0	N/A	N/A
1	B	10	8 : Rear Storage Room inside Girl's Gym	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	Radiator	Metal	Grey	Flaking	6	10.1	Positive
1	B	009A	009A : Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	9	9 : Small Hallway to Girl's Gym Office - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A

1	B	009B	009B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W1	Brick	White	None	0	10.8	Positive
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W2	Brick	White	None	0	13.8	Positive
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	10.9	Positive
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W4	Brick	White	None	0	15.3	Positive
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	10.1	Positive
1	B	8	10 : Girl's Gym Storage - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	W1	Brick	White	Partially Inaccessible	0	0.02	Negative
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	W2	Concrete	White	Partially Inaccessible	0	0.01	Negative
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	W3	Concrete	White	Partially Inaccessible	0	0.01	Negative
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	W4	Concrete	White	Partially Inaccessible	0	0.02	Negative
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	Ceiling	Concrete	White	Partially Inaccessible	0	0.12	Negative
1	B	010A	010A : Girl's Gym Storage Room Below Stairwell	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	W1	Brick	White	None	0	5.3	Positive
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	W2	Brick	White	None	0	4.2	Positive
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	W3	Concrete	White	None	0	5.7	Positive
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	W4	Brick	White	None	0	2.7	Positive
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	Ceiling	Concrete	White	None	0	4.7	Positive
1	B	13	12 : Rear Storage Room inside Boy's Gym	yes	Floor	Wood	Varnish	None	0	N/A	N/A
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	Tan	None	0	8.2	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	Radiator	Metal	Tan	Flaking	12	8.6	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	Tan	None	0	3.9	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	Tan	None	0	5.7	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	Tan	None	0	10.2	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	17.4	Positive
1	B	12	13 : Boy's Gym Storage - Bottom of Stairs at Gym Entrance	yes	Floor	Wood	Varnish	Partially Inaccessible	0	0.01	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	W1	Brick	White	Partially Inaccessible	0	0.03	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	Door Frame	Metal	Tan	Chipping	4	0	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	W2	Brick	White	Partially Inaccessible	0	0.02	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	W3	Brick	White	Partially Inaccessible	0	0.01	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	W4	Concrete	White	Partially Inaccessible	0	0.01	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	Ceiling	Concrete	White	Partially Inaccessible	0	0.01	Negative
1	B	013A	013A : Boy's Gym Storage Room Below Stairwell	yes	Floor	Concrete	N/A	N/A	0	N/A	N/A
1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	Tan	Broken	150	25.1	Positive

1	B	014A	014A : Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	Tan	Efflorescence	4	15.2	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	Tan	None	0	19.6	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	Tan	None	0	14.6	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	Tan	Efflorescence	4	16.5	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	Tan	Flaking/Broken	35	16.7	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	Pipe	Metal	Tan	Flaking	9	26.2	Positive
1	B	14	14 : Small Hallway to Boy's Gym Office - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W1	Plaster	White	None	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W2	Plaster	White	None	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W3	Plaster	White	None	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	W4	Plaster	White	None	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	Ceiling	Plaster	White	None	0	N/A	N/A
1	B	014B	014B : Gym Teacher's Restroom - Bottom of Stairs at Gym Entrance	yes	Floor	Floor Tile	N/A	N/A	0	N/A	N/A
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100-PL	100-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 1	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	SB	100C-PL	100C-PL : Concrete Distribution Tunnel/Air Supply Plenum connected to Fan Room # 2	no	Floor	No Access	No Access	No Access	No Access	No Access	No Access