

LEAD SAFE ASSESSMENT REPORT



Swenson Arts and Technology High School

2750 Red Lion Road
Philadelphia, Pennsylvania

November 14, 2023

Prepared For:



440 N. Broad Street
Philadelphia, PA 19130

Prepared by:



1012 Industrial Drive
West Berlin, NJ 08091

ACER Project Number: SDP201.14
EP#2023-0131-8090



TABLE OF CONTENTS

1.0 INTRODUCTION

2.0 SCOPE OF WORK

3.0 FINDINGS & RECOMMENDATIONS

3.1 Inspection Findings

3.2 Limitations

4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

5.0 APPENDICES

Appendix A Lead Safe Certification Assessment

Appendix B Lead Safe Certificate



1.0 INTRODUCTION

Acer Associates, LLC (ACER) has prepared this report to summarize the findings of the Lead Safe Assessment at Swenson Arts and Technology High School, located at 2750 Red Lion Road in Philadelphia, Pennsylvania. The purpose of the inspection was to identify and assess painted surfaces within the school.

The inspection was completed on September 27, 2023, through October 4, 2023, by Mr. J. Chuck Wilkins (006732) and Ms. Kristen Masotes (058358) of ACER, both of whom are licensed Commonwealth of Pennsylvania Lead Risk Assessors.

The lead survey was conducted in accordance with the requirements of Federal, State, and local regulations pertaining to lead paint, including the United States Department of Housing and Urban Development (HUD) Guidelines for the Evaluation of Lead-Based Paint Hazards in Housing. The findings in this report are consistent with accepted principles and practices established and prescribed by the City of Philadelphia, Commonwealth of Pennsylvania, EPA, and HUD.

This report, and the supporting data, findings, conclusions, opinions, and the recommendations it contains, represents the result of ACER's efforts. This report is not an abatement specification and should not be used for specifying removal methods or techniques. The results, assessments, conclusions, and recommendations stated in this report are factually representative of the conditions observed at this location on the dates of the inspection. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

Any reliance on this report by a party other than The School District of Philadelphia shall be at the party's sole risk unless that party has written authorization from ACER to use this document. The purpose of this restriction is to attempt to protect the interest of parties to whom the report may not be appropriately directed.

2.0 INSPECTION

Swenson Arts and Technology High School is a two (2) story building.

Please Note: Direction "W1" corresponds to the entry wall of each room/location. Direction "W2" corresponds to the next adjacent wall in the clockwise directions and so forth for directions "W3" and "W4".

A Niton model XLP-703A X-ray fluorescence lead paint analyzer was used for determination of lead content in paint. The calibration of the Niton XLP-703A is done in accordance with Performance Characteristic Sheets (PCS). This XRF instrument is



calibrated using a calibration block that is supplied by Niton to determine if the instrument is within calibration. Three (3) calibration readings are taken and averaged before and after the property was tested to assure the instrument was working within the manufacturer's standards. If for any reason the instrument does not maintain a consistent reproducible calibration, manufacturer's recommendations are used to bring the instrument into calibration. If the instrument cannot be brought back into calibration it is immediately removed from active service and sent back to the manufacturer for examination, service and/or recalibration. A Viken model Pb200i X-ray fluorescence lead paint analyzer was also used during the inspection. Calibration checks of the Viken Pb200i were done in accordance with Performance Characteristic Sheets (PCS). Calibration checks were performed on this Viken instrument using a National Institute of Standards and Technology (NIST) Standard Reference Material (SRM) sheet supplied by Viken at the beginning and end of each day's testing and at intervals of every four (4) hours during the testing. Calibration checks consist of the average of three (3) readings taken of the nominal 1.0 mg/cm² paint film (SRM 2573). If for any reason the instrument does not maintain a consistent reproducible calibration, it is immediately removed from active service and sent back to the manufacturer for examination, service and/or recalibration.

The inspection consisted of collecting test readings of all substrate types in a room as depicted above and described as follows. One (1) test point (reading) was taken for each testing combination, except for the walls where at least four (4) were tested, to determine the amount of lead contained in the paint for that substrate. A testing combination is characterized by the room equivalent (Room 102, Main Office, etc.), component type (door, window, wall, etc.) and substrate (metal, sheetrock, etc.). The resulting test readings are then classified as POSITIVE OR NEGATIVE according to the action level, which is set in accordance with the applicable action level of the governing municipality, county, or state. The lead safe certification assessment report for this inspection is provided in Appendix A.

3.0 FINDINGS

ACER conducted an inspection for lead-based paint at Swenson Arts and Technology High School, located at 2750 Red Lion Road in Philadelphia, Pennsylvania.

3.1 Findings

In accordance with The Philadelphia Code, Chapter 6-800, lead-based paint is defined as greater than 0.7 mg/cm². ACER's inspection identified lead-based paint throughout the school associated with the following building components:

- Stair Components (51B)



- Door Components (51M)
- Cabinet (244D)
- Lockers (H29)

3.2 Limitations

The inspection and sample procedures used to complete this inspection are consistent with prevalent environmental and industrial hygiene standards for lead-based paint. All reasonable efforts were made to identify the presence of lead-based paint within the inspected areas. Materials not identified in this report should be considered as not sampled. ACER cannot assume responsibility for any change in conditions that occurred after the inspection.

4.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONAL

Sincerely,
Acer Associates, LLC

Prepared By:


Kristen Masotes
Project Manager

Reviewed By:


Matthew J. DePalma
Vice President



5.0 APPENDICES



Appendix A
Lead Safe Certification Assessment Report

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	10	Automotive Shop	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	10	Automotive Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10	Automotive Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10	Automotive Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10	Automotive Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10	Automotive Shop	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10	Automotive Shop	Door Casing W1	Metal	Blue	None	0	0.21	Negative	N/A	
1	1	10	Automotive Shop	Door W1	Metal	Blue	None	0	0.01	Negative	N/A	
1	1	10	Automotive Shop	Roll up Door W1	Metal	Blue	None	0	0.01	Negative	N/A	
1	1	10	Automotive Shop	Column	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10	Automotive Shop	Drain	Metal	Tan	None	0	0.1	Negative	N/A	
1	1	10	Automotive Shop	Roll up Door Casing W4	Metal	Blue	None	0	0.01	Negative	N/A	
1	1	10	Automotive Shop	Pipe Casing W4	Metal	Blue	None	0	0.01	Negative	N/A	
1	1	10	Automotive Shop	Door W4	Metal	Grey	None	0	0	Negative	N/A	
1	1	10	Automotive Shop	Roll up Door Casing W3	Metal	Black	None	0	0.06	Negative	N/A	
1	1	100	Main Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	100	Main Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	100	Main Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	100	Main Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	100	Main Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	100	Main Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	100	Main Office	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	100	Main Office	Door Frame W2	Metal	Grey	None	0	0.06	Negative	N/A	
1	1	100	Main Office	Door Frame W4	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	100	Main Office	Window Frame W1	Metal	Grey	None	0	0.08	Negative	N/A	
1	1	100	Main Office	Window Frame W2	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	100	Main Office	Window Frame W3	Metal	Grey	None	0	0.023	Negative	N/A	
1	1	101	Principal's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	101	Principal's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	101	Principal's Office	W3	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	101	Principal's Office	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	101	Principal's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	101	Principal's Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	101	Principal's Office	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	101A	Principal's Office Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	101A	Principal's Office Storage	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	101B	Principal's Office Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	101B	Principal's Office Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	101B	Principal's Office Restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	101B	Principal's Office Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	101B	Principal's Office Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	101B	Principal's Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	101B	Principal's Office Restroom	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	102	Assistant Principals Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	102	Assistant Principals Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	102	Assistant Principals Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	102	Assistant Principals Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	102	Assistant Principals Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	102	Assistant Principals Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	102	Assistant Principals Office	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	103	Counselors Office	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	103	Counselors Office	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	103	Counselors Office	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	103	Counselors Office	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	103	Counselors Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	103	Counselors Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	103	Counselors Office	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	104	Office 105 - Roster Office	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	104	Office 105 - Roster Office	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	104	Office 105 - Roster Office	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	104	Office 105 - Roster Office	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	104	Office 105 - Roster Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	104	Office 105 - Roster Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	104	Office 105 - Roster Office	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	104	Office 105 - Roster Office	Door Frame W3	Metal	Grey	None	0	0.09	Negative	N/A	
1	1	105	Copy-Supply Room	W1	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	105	Copy-Supply Room	W2	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	105	Copy-Supply Room	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	105	Copy-Supply Room	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	105	Copy-Supply Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	105	Copy-Supply Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	105	Copy-Supply Room	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	105	Copy-Supply Room	Column	CMU	White	None	0	0	Negative	Positive	Entered by ST
1	1	105	Copy-Supply Room	Conduit Box	Metal	Tan	None	0	0.18	Negative	N/A	
1	1	106	Faculty Mail Room 108	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	106	Faculty Mail Room 108	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	106	Faculty Mail Room 108	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	106	Faculty Mail Room 108	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	106	Faculty Mail Room 108	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	106	Faculty Mail Room 108	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	106	Faculty Mail Room 108	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	106	Faculty Mail Room 108	Door Frame W3	Metal	Grey	None	0	0.03	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	107	Principal's Office Conference Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	107	Principal's Office Conference Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	107	Principal's Office Conference Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	107	Principal's Office Conference Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	107	Principal's Office Conference Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	107	Principal's Office Conference Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	107	Principal's Office Conference Room	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	107	Principal's Office Conference Room	Door Frame W4	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	108	Room 105	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	108	Room 105	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	108	Room 105	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	108	Room 105	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	108	Room 105	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	108	Room 105	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	108	Room 105	Door Frame W1	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	109	Counseling Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	109	Counseling Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	109	Counseling Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	109	Counseling Room	W4	CMU	Tan	None	0	0.016	Negative	Positive	Confirmed in Donesafe-SRT
1	1	109	Counseling Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	109	Counseling Room	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	109	Counseling Room	Door Frame W1	Metal	Grey	None	0	0.09	Negative	N/A	
1	1	10A	Tire Storage	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10A	Tire Storage	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10A	Tire Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10A	Tire Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10A	Tire Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10A	Tire Storage	Ceiling	Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10A	Tire Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	unpainted
1	1	10A	Tire Storage	Window Frame W2	Metal	Tan	None	0	0	Negative	N/A	
1	1	10A	Tire Storage	Window Frame W3	Metal	Tan	None	0	0	Negative	N/A	
1	1	10A	Tire Storage	Door Frame W1	Metal	Tan	None	0	0	Negative	N/A	
1	1	10A	Tire Storage	Door Frame W3	Metal	Tan	None	0	0	Negative	N/A	
1	1	10A	Tire Storage	Door	Metal	Tan	None	0	0	Negative	N/A	
1	1	10B	Auto Shop Theory Classroom	Ceiling	Concrete	Tan	None	0	0.2	Negative	N/A	Sampling not required
1	1	10B	Auto Shop Theory Classroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10B	Auto Shop Theory Classroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10B	Auto Shop Theory Classroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10B	Auto Shop Theory Classroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10B	Auto Shop Theory Classroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10B	Auto Shop Theory Classroom	Door Frame W1	Metal	Blue	None	0	0.02	Negative	N/A	
1	1	10B	Auto Shop Theory Classroom	Door Frame W3	Metal	Blue	None	0	0.02	Negative	N/A	
1	1	10B	Auto Shop Theory Classroom	Window Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	10B	Auto Shop Theory Classroom	Window Frame W3	Metal	Blue	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	10B	Auto Shop Theory Classroom	Window Frame W4	Metal	Blue	None	0	0	Negative	N/A	
1	1	10C	Auto Shop Office	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	10C	Auto Shop Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10C	Auto Shop Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10C	Auto Shop Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10C	Auto Shop Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10C	Auto Shop Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10C	Auto Shop Office	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	10C	Auto Shop Office	Door Frame W3	Metal	Blue	None	0	0	Negative	N/A	
1	1	10C	Auto Shop Office	Window Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	10C	Auto Shop Office	Window Frame W3	Metal	Blue	None	0	0	Negative	N/A	
1	1	10D	Auto Shop Tool Storage	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	10D	Auto Shop Tool Storage	W2	Sheetrock	Tan	None	0	0.1	Negative	N/A	Sampling not required
1	1	10D	Auto Shop Tool Storage	W3	Sheetrock	Tan	None	0	0.1	Negative	N/A	Sampling not required
1	1	10D	Auto Shop Tool Storage	W4	Sheetrock	Tan	None	0	0.1	Negative	N/A	Sampling not required
1	1	10D	Auto Shop Tool Storage	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	10D	Auto Shop Tool Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10D	Auto Shop Tool Storage	Column	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10D	Auto Shop Tool Storage	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	10E	Classroom 005	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10E	Classroom 005	W1	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	1	10E	Classroom 005	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10E	Classroom 005	W3	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	10E	Classroom 005	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	10E	Classroom 005	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10E	Classroom 005	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	10E	Classroom 005	Door Frame W1	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Door Frame W1	Metal	Blue	None	0	0.2	Negative	N/A	
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Window Frame W2	Metal	Blue	None	0	0	Negative	N/A	
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Window Frame W1	Metal	Blue	None	0	0.3	Negative	N/A	
1	1	10F	Tool Storage near Auto-Body Shop Exit Door A2	Duct	Metal	Tan	None	0	0.2	Negative	N/A	
1	1	10G	Tool Storage next to Paint mixing Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Principal only has the key
1	1	10G	Tool Storage next to Paint mixing Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	10G	Tool Storage next to Paint mixing Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	10G	Tool Storage next to Paint mixing Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	10G	Tool Storage next to Paint mixing Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	10G	Tool Storage next to Paint mixing Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	10H	Paint Mixing Room	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	10H	Paint Mixing Room	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10H	Paint Mixing Room	W3	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10H	Paint Mixing Room	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10H	Paint Mixing Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	unpainted
1	1	10H	Paint Mixing Room	Floor	Concrete	Grey	None	0	0.2	Negative	N/A	
1	1	10J	Painting/Detail Garage	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10J	Painting/Detail Garage	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10J	Painting/Detail Garage	W3	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10J	Painting/Detail Garage	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10J	Painting/Detail Garage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	10J	Painting/Detail Garage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	11	Female Student Restroom by School Police Office	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	11	Female Student Restroom by School Police Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	11	Female Student Restroom by School Police Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	11	Female Student Restroom by School Police Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	11	Female Student Restroom by School Police Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	11	Female Student Restroom by School Police Office	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	11	Female Student Restroom by School Police Office	Pipe Chase	Metal	Blue	None	0	0.04	Negative	N/A	
1	1	110	Psychologist Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	110	Psychologist Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	110	Psychologist Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	110	Psychologist Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	110	Psychologist Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	110	Psychologist Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	110	Psychologist Office	Door Frame W1	Metal	Grey	None	0	0.07	Negative	N/A	
1	1	111	Small Meeting Room	W1	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	111	Small Meeting Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	111	Small Meeting Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	111	Small Meeting Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	111	Small Meeting Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	111	Small Meeting Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	111	Small Meeting Room	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	111	Small Meeting Room	Door Frame W3	Wood	White	None	0	0	Negative	N/A	
1	1	111	Small Meeting Room	Window Frame W3	Wood	White	None	0	0	Negative	N/A	
1	1	112	Counselor's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	112	Counselor's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	112	Counselor's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	112	Counselor's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	112	Counselor's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	112	Counselor's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	112	Counselor's Office	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	113	Counselor's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	113	Counselor's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	113	Counselor's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	113	Counselor's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	113	Counselor's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	113	Counselor's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	113	Counselor's Office	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	114	Large Counselors Office	W1	Sheetrock	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	114	Large Counselors Office	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114	Large Counselors Office	W2	Sheetrock	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	114	Large Counselors Office	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114	Large Counselors Office	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114	Large Counselors Office	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114	Large Counselors Office	W4	Sheetrock	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	114	Large Counselors Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	114	Large Counselors Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	114	Large Counselors Office	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	114	Large Counselors Office	Door Frame W4	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	114-1C	Room 114 Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114-1C	Room 114 Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114-1C	Room 114 Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114-1C	Room 114 Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	114-1C	Room 114 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	114-1C	Room 114 Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	114-1C	Room 114 Closet	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	192	Men's Staff Bathroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	192	Men's Staff Bathroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	192	Men's Staff Bathroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	192	Men's Staff Bathroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	192	Men's Staff Bathroom	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	192	Men's Staff Bathroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	192	Men's Staff Bathroom	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	193	Women's Staff Bathroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	193	Women's Staff Bathroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	193	Women's Staff Bathroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	193	Women's Staff Bathroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	193	Women's Staff Bathroom	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	193	Women's Staff Bathroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	193	Women's Staff Bathroom	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	194	Room 116	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	194	Room 116	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	194	Room 116	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	194	Room 116	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	194	Room 116	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	194	Room 116	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	194	Room 116	Door Frame W1	Metal	Grey	None	0	0.07	Negative	N/A	
1	1	115	Nurse's Office Examination Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	115	Nurse's Office Examination Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	115	Nurse's Office Examination Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	115	Nurse's Office Examination Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	115	Nurse's Office Examination Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	115	Nurse's Office Examination Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	115	Nurse's Office Examination Room	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	115	Nurse's Office Examination Room	Window Frame W4	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	116	Rear Nurse's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	116	Rear Nurse's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	116	Rear Nurse's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	116	Rear Nurse's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	116	Rear Nurse's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	116	Rear Nurse's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	116	Rear Nurse's Office	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	117	Nurse Office Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	117	Nurse Office Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	117	Nurse Office Restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	117	Nurse Office Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	117	Nurse Office Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	117	Nurse Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	117	Nurse Office Restroom	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	118	Room 114 Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	118	Room 114 Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	118	Room 114 Restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	118	Room 114 Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	118	Room 114 Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	118	Room 114 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	118	Room 114 Restroom	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	119	Nurse Waiting Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	119	Nurse Waiting Room	W2	Wood	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	119	Nurse Waiting Room	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	119	Nurse Waiting Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	119	Nurse Waiting Room	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	119	Nurse Waiting Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	119	Nurse Waiting Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	119	Nurse Waiting Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	119	Nurse Waiting Room	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	119	Nurse Waiting Room	Door Frame W3	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	119	Nurse Waiting Room	Door Frame W4	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	W4	CMU	Tan	None	0	0.2	Negative	Positive	Confirmed in Donesafe-SRT
1	1	12	Mens Faculty Restroom by Auto-Shop Theory Classroom	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	Sampling not required
1	1	120	Classroom 138	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120	Classroom 138	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120	Classroom 138	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	120	Classroom 138	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120	Classroom 138	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	120	Classroom 138	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	120	Classroom 138	Door Frame W1	Metal	Grey	None	0	0.07	Negative	N/A	
1	1	120	Classroom 138	Door Frame W3	Metal	Grey	None	0	0	Negative	N/A	
1	1	120A	Classroom 138 Closet	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120A	Classroom 138 Closet	W2	CMU	Blue	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120A	Classroom 138 Closet	W3	CMU	Blue	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120A	Classroom 138 Closet	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	120A	Classroom 138 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	120A	Classroom 138 Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	120A	Classroom 138 Closet	Door Frame	Metal	Grey	None	0	0.5	Negative	N/A	
1	1	124	Female Locker Room Outside Classroom 126	W1	CMU	Yellow	None	0	0.03	Negative	Positive	Confirmed in Donesafe-SRT
1	1	124	Female Locker Room Outside Classroom 126	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	124	Female Locker Room Outside Classroom 126	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	124	Female Locker Room Outside Classroom 126	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	124	Female Locker Room Outside Classroom 126	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	124	Female Locker Room Outside Classroom 126	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	124	Female Locker Room Outside Classroom 126	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	125	Staff Restroom by Classroom 126	W1	CMU	Yellow	None	0	0.03	Negative	Positive	Confirmed in Donesafe-SRT
1	1	125	Staff Restroom by Classroom 126	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	125	Staff Restroom by Classroom 126	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	125	Staff Restroom by Classroom 126	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	125	Staff Restroom by Classroom 126	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	125	Staff Restroom by Classroom 126	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	125	Staff Restroom by Classroom 126	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	126	Classroom 126 (Nursing & Clinical Studies)	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126	Classroom 126 (Nursing & Clinical Studies)	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126	Classroom 126 (Nursing & Clinical Studies)	W2	Sheetrock	Yellow	None	0	0	Negative	N/A	
1	1	126	Classroom 126 (Nursing & Clinical Studies)	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126	Classroom 126 (Nursing & Clinical Studies)	W4	Sheetrock	Yellow	None	0	0	Negative	N/A	
1	1	126	Classroom 126 (Nursing & Clinical Studies)	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	126	Classroom 126 (Nursing & Clinical Studies)	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	126	Classroom 126 (Nursing & Clinical Studies)	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	1	126	Classroom 126 (Nursing & Clinical Studies)	Door Frame W3	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	126	Classroom 126 (Nursing & Clinical Studies)	Door Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	1	126A	Locker Room Storage in Classroom 126	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126A	Locker Room Storage in Classroom 126	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	126A	Locker Room Storage in Classroom 126	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126A	Locker Room Storage in Classroom 126	W4	CMU	Yellow	None	0	0	Negative	Positive	Inaccessible due to storage-Confirmed in Donesafe-SRT
1	1	126A	Locker Room Storage in Classroom 126	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	126A	Locker Room Storage in Classroom 126	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	126A	Locker Room Storage in Classroom 126	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	126B	Classroom 126 - Restroom	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126B	Classroom 126 - Restroom	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126B	Classroom 126 - Restroom	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126B	Classroom 126 - Restroom	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126B	Classroom 126 - Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	126B	Classroom 126 - Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	126B	Classroom 126 - Restroom	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	126C	Health Room 126	W1	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	126C	Health Room 126	W2	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	126C	Health Room 126	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	126C	Health Room 126	W4	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	126C	Health Room 126	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	126C	Health Room 126	Floor	Carpet	Unpainted	None	0	N/A	N/A	N/A	
1	1	129	Classroom 128	W1	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129	Classroom 128	W1	Sheetrock	White	None	0	0	Negative	N/A	Sampling not required
1	1	129	Classroom 128	W2	Sheetrock	White	None	0	0	Negative	N/A	Sampling not required
1	1	129	Classroom 128	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129	Classroom 128	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129	Classroom 128	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	129	Classroom 128	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129	Classroom 128	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	129	Classroom 128	Door Frame W4	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	129	Classroom 128	Door W4	Metal	Grey	None	0	0.01	Negative	N/A	
1	1	129A	Classroom 128 Restroom	W1	Sheetrock	White	None	0	0	Negative	N/A	Sampling not required
1	1	129A	Classroom 128 Restroom	W2	Sheetrock	White	None	0	0	Negative	N/A	Sampling not required
1	1	129A	Classroom 128 Restroom	W2	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129A	Classroom 128 Restroom	W3	Sheetrock	White	None	0	0	Negative	N/A	Sampling not required
1	1	129A	Classroom 128 Restroom	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129A	Classroom 128 Restroom	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129A	Classroom 128 Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	129A	Classroom 128 Restroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129A	Classroom 128 Restroom	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	129B	Classroom 128 Office	W1	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129B	Classroom 128 Office	W2	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129B	Classroom 128 Office	W3	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129B	Classroom 128 Office	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129B	Classroom 128 Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	129B	Classroom 128 Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129C	Classroom 128 Storage Room	W1	CMU	Black	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	129C	Classroom 128 Storage Room	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W2	CMU	Black	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W3	CMU	Black	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W4	CMU	Black	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129C	Classroom 128 Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	129C	Classroom 128 Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129C	Classroom 128 Storage Room	Door Frame W1	Metal	Grey	None	0	0.01	Negative	N/A	
1	1	129C	Classroom 128 Storage Room	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	129D	Greenhouse Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129D	Greenhouse Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129D	Greenhouse Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129D	Greenhouse Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	129D	Greenhouse Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	129D	Greenhouse Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	129D	Greenhouse Office	Door Frame W1	Metal	Red	None	0	0.05	Negative	N/A	
1	1	129D	Greenhouse Office	Door Frame W1	Metal	Red	None	0	0.05	Negative	N/A	
1	1	129D	Greenhouse Office	Column	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	129D	Greenhouse Office	Window Frame W3	Metal	Red	None	0	0.06	Negative	N/A	
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	13	Boy's Restroom by Auto-Shop Theory Classroom	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	13-PC	Pipe Chase inside Boy's Restroom near Auto-Body Shop	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	130	Classroom 130	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130	Classroom 130	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130	Classroom 130	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130	Classroom 130	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130	Classroom 130	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	130	Classroom 130	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	130	Classroom 130	Door Frame W1	Metal	Green	None	0	0.08	Negative	N/A	
1	1	130	Classroom 130	Window Frame W1	Metal	Green	None	0	0.1	Negative	N/A	
1	1	130	Classroom 130	Door Frame W2	Metal	Green	None	0	0.21	Negative	N/A	
1	1	130	Classroom 130	Door W2	Metal	Green	None	0	0.02	Negative	N/A	
1	1	130A	Classroom 130 Foyer Area	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130A	Classroom 130 Foyer Area	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130A	Classroom 130 Foyer Area	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130A	Classroom 130 Foyer Area	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130A	Classroom 130 Foyer Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	130A	Classroom 130 Foyer Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	130A	Classroom 130 Foyer Area	Door Frame W1	Metal	Green	None	0	0.01	Negative	N/A	
1	1	130A	Classroom 130 Foyer Area	Door Frame W2	Metal	Green	None	0	0.06	Negative	N/A	
1	1	130A	Classroom 130 Foyer Area	Door Frame W4	Metal	Green	None	0	0.04	Negative	N/A	
1	1	130A	Classroom 130 Foyer Area	Window Frame W1	Metal	Green	None	0	0.09	Negative	N/A	
1	1	130A	Classroom 130 Foyer Area	Shelf	Wood	Green	None	0	0	Negative	N/A	
1	1	130B	Classroom 130 Foyer Storage	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130B	Classroom 130 Foyer Storage	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130B	Classroom 130 Foyer Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130B	Classroom 130 Foyer Storage	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	130B	Classroom 130 Foyer Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	130B	Classroom 130 Foyer Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	130B	Classroom 130 Foyer Storage	Door Frame W1	Metal	Green	None	0	0.3	Negative	N/A	
1	1	131	Greenhouse Garage	W1	CMU	White	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	131	Greenhouse Garage	W2	CMU	White	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	131	Greenhouse Garage	W3	CMU	White	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	131	Greenhouse Garage	W4	CMU	White	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	131	Greenhouse Garage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	131	Greenhouse Garage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	131	Greenhouse Garage	Door Frame W1	Metal	Green	None	0	0.2	Negative	N/A	
1	1	132-2	Boys Restroom outside Classroom 130	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	132-2	Boys Restroom outside Classroom 130	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	132-2	Boys Restroom outside Classroom 130	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	132-2	Boys Restroom outside Classroom 130	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	132-2	Boys Restroom outside Classroom 130	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	132-2	Boys Restroom outside Classroom 130	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	132-2	Boys Restroom outside Classroom 130	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	134	Hallway Storage Health Room 126	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	134	Hallway Storage Health Room 126	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	134	Hallway Storage Health Room 126	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	134	Hallway Storage Health Room 126	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	134	Hallway Storage Health Room 126	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	134	Hallway Storage Health Room 126	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	134	Hallway Storage Health Room 126	Door Frame W1	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	140	Classroom 144	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	140	Classroom 144	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	140	Classroom 144	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140	Classroom 144	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140	Classroom 144	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	140	Classroom 144	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	140	Classroom 144	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	140	Classroom 144	Door Frame W3	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	140	Classroom 144	Door Frame W4	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	140-RR	Boy's restroom inside Classroom 144	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140-RR	Boy's restroom inside Classroom 144	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140-RR	Boy's restroom inside Classroom 144	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140-RR	Boy's restroom inside Classroom 144	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140-RR	Boy's restroom inside Classroom 144	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	140-RR	Boy's restroom inside Classroom 144	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	140-RR	Boy's restroom inside Classroom 144	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	140a	Classroom 140	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140a	Classroom 140	W1	Metal	Tan	None	0	0.18	Negative	N/A	Sampling not required
1	1	140a	Classroom 140	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140a	Classroom 140	W2	Metal	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	140a	Classroom 140	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	140a	Classroom 140	W3	Metal	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	140a	Classroom 140	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	140a	Classroom 140	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	140a	Classroom 140	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	140a	Classroom 140	Door Frame W1	Metal	Grey	None	0	0.07	Negative	N/A	
1	1	141	Storage Area Connecting space 144 & 140	W1	Metal	Tan	None	0	0.18	Negative	N/A	Sampling not required
1	1	141	Storage Area Connecting space 144 & 140	W2	Metal	Tan	None	0	0.15	Negative	N/A	Sampling not required
1	1	141	Storage Area Connecting space 144 & 140	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	141	Storage Area Connecting space 144 & 140	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	141	Storage Area Connecting space 144 & 140	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	141	Storage Area Connecting space 144 & 140	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	141	Storage Area Connecting space 144 & 140	Column	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	142	Classroom 142 (School Store)	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	142	Classroom 142 (School Store)	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	142	Classroom 142 (School Store)	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	142	Classroom 142 (School Store)	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	142	Classroom 142 (School Store)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	142	Classroom 142 (School Store)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	143	Storage Closet 143 inside Classroom 144	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	143	Storage Closet 143 inside Classroom 144	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	143	Storage Closet 143 inside Classroom 144	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	143	Storage Closet 143 inside Classroom 144	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	143	Storage Closet 143 inside Classroom 144	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	143	Storage Closet 143 inside Classroom 144	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	143	Storage Closet 143 inside Classroom 144	Door Frame	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	144	Classroom 144 Large Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	144	Classroom 144 Large Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	144	Classroom 144 Large Storage	W3	CMU	Tan	None	0	0.2	Negative	Positive	Confirmed in Donesafe-SRT
1	1	144	Classroom 144 Large Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	144	Classroom 144 Large Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	144	Classroom 144 Large Storage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	144	Classroom 144 Large Storage	Door Frame	Metal	Grey	None	0	0.6	Negative	N/A	
1	1	145	Girl's Restroom inside Classroom 144	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	145	Girl's Restroom inside Classroom 144	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	145	Girl's Restroom inside Classroom 144	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	145	Girl's Restroom inside Classroom 144	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	145	Girl's Restroom inside Classroom 144	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	145	Girl's Restroom inside Classroom 144	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	145	Girl's Restroom inside Classroom 144	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	Sampling not required
1	1	146	Classroom 146	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	146	Classroom 146	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	146	Classroom 146	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	146	Classroom 146	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	146	Classroom 146	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	146	Classroom 146	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	unpainted
1	1	146	Classroom 146	Door Frame W1	Metal	Yellow	None	0	0	Negative	N/A	
1	1	146	Classroom 146	Door Frame W2	Metal	Grey	None	0	0.08	Negative	N/A	Sampling not required
1	1	146	Classroom 146	Window Frame W2	Metal	Grey	None	0	0.09	Negative	N/A	Sampling not required
1	1	150	Special Needs Classroom 160	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150	Special Needs Classroom 160	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	150	Special Needs Classroom 160	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150	Special Needs Classroom 160	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150	Special Needs Classroom 160	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150	Special Needs Classroom 160	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	150	Special Needs Classroom 160	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150	Special Needs Classroom 160	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	150A	Special Needs Classroom 160 - Kitchen	W1	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	150A	Special Needs Classroom 160 - Kitchen	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150A	Special Needs Classroom 160 - Kitchen	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150A	Special Needs Classroom 160 - Kitchen	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150A	Special Needs Classroom 160 - Kitchen	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150A	Special Needs Classroom 160 - Kitchen	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	150B	Special Needs Classroom 160 - Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150B	Special Needs Classroom 160 - Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150B	Special Needs Classroom 160 - Restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150B	Special Needs Classroom 160 - Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150B	Special Needs Classroom 160 - Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150B	Special Needs Classroom 160 - Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	150B	Special Needs Classroom 160 - Restroom	Shelf	Wood	Tan	None	0	0.01	Negative	N/A	
1	1	150C	Special Needs Classroom 160 - Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150C	Special Needs Classroom 160 - Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150C	Special Needs Classroom 160 - Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150C	Special Needs Classroom 160 - Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150C	Special Needs Classroom 160 - Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150C	Special Needs Classroom 160 - Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	150D	Therapy Room A in Room 160	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150D	Therapy Room A in Room 160	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150D	Therapy Room A in Room 160	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150D	Therapy Room A in Room 160	W4	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	150D	Therapy Room A in Room 160	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150D	Therapy Room A in Room 160	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	150E	Therapy Room B in Room 160	W1	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	150E	Therapy Room B in Room 160	W2	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	150E	Therapy Room B in Room 160	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	150E	Therapy Room B in Room 160	W4	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	150E	Therapy Room B in Room 160	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	150E	Therapy Room B in Room 160	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	150E	Therapy Room B in Room 160	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	150E	Therapy Room B in Room 160	Chair Rail - W4	Wood	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	150E	Therapy Room B in Room 160	Chair Rail - W1	Wood	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	151	Office 151 Special Needs Counselor	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151	Office 151 Special Needs Counselor	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151	Office 151 Special Needs Counselor	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151	Office 151 Special Needs Counselor	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151	Office 151 Special Needs Counselor	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	151	Office 151 Special Needs Counselor	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	151	Office 151 Special Needs Counselor	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	Sampling not required
1	1	151	Office 151 Special Needs Counselor	Door Frame W3	Metal	Grey	None	0	0.02	Negative	N/A	Sampling not required
1	1	151A	Office 151 Special Needs Counselor Restroom	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151A	Office 151 Special Needs Counselor Restroom	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151A	Office 151 Special Needs Counselor Restroom	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151A	Office 151 Special Needs Counselor Restroom	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151A	Office 151 Special Needs Counselor Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	151A	Office 151 Special Needs Counselor Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	151A	Office 151 Special Needs Counselor Restroom	Door Frame W1	Metal	Grey	None	0	0.06	Negative	N/A	Sampling not required
1	1	151B	Office 151 Special Needs Counselor Storage	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151B	Office 151 Special Needs Counselor Storage	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151B	Office 151 Special Needs Counselor Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151B	Office 151 Special Needs Counselor Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	151B	Office 151 Special Needs Counselor Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	151B	Office 151 Special Needs Counselor Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	151B	Office 151 Special Needs Counselor Storage	Door Frame W1	Metal	Grey	None	0	0.5	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	15	Auto-Body Shop Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	15	Auto-Body Shop Storage	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	15	Auto-Body Shop Storage	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	15	Auto-Body Shop Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	15	Auto-Body Shop Storage	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	15	Auto-Body Shop Storage	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	Sampling not required
1	1	15	Auto-Body Shop Storage	Pipe	Metal	Red	None	0	0	Negative	N/A	Sampling not required
1	1	15	Auto-Body Shop Storage	Door Frame W1	Metal	Blue	None	0	0.2	Negative	N/A	Sampling not required
1	1	15A	Compressor Room in Auto Body Shop	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	15A	Compressor Room in Auto Body Shop	Pipe	Metal	Green	None	0	0	Negative	N/A	Sampling not required
1	1	15A	Compressor Room in Auto Body Shop	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	15A	Compressor Room in Auto Body Shop	Door W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	15A	Compressor Room in Auto Body Shop	Duct	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	164	Bakery Class - Kitchen Teaching Area	W1	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	164	Bakery Class - Kitchen Teaching Area	W2	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	164	Bakery Class - Kitchen Teaching Area	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	164	Bakery Class - Kitchen Teaching Area	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	164	Bakery Class - Kitchen Teaching Area	W4	Sheetrock	White	None	0	0	Negative	N/A	
1	1	164	Bakery Class - Kitchen Teaching Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	164	Bakery Class - Kitchen Teaching Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	164	Bakery Class - Kitchen Teaching Area	Column	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	164	Bakery Class - Kitchen Teaching Area	Door Frame W3	Metal	Grey	None	0	0.01	Negative	N/A	Sampling not required
1	1	164	Bakery Class - Kitchen Teaching Area	Door Frame W4	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	165	Bakery Kitchen - Storage Area	W1	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165	Bakery Kitchen - Storage Area	W2	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165	Bakery Kitchen - Storage Area	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165	Bakery Kitchen - Storage Area	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165	Bakery Kitchen - Storage Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	165	Bakery Kitchen - Storage Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	165A	Bakery Storage Room	W1	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	165A	Bakery Storage Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165A	Bakery Storage Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165A	Bakery Storage Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	165A	Bakery Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	165A	Bakery Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	165A	Bakery Storage Room	Door Frame	Metal	Grey	None	0	0	Negative	N/A	
1	1	166	Bake Shop Theory Room	W1	Sheetrock	White	None	0	0	Negative	N/A	
1	1	166	Bake Shop Theory Room	W1	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166	Bake Shop Theory Room	W2	Sheetrock	White	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	166	Bake Shop Theory Room	W2	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166	Bake Shop Theory Room	W3	Sheetrock	White	None	0	0	Negative	N/A	
1	1	166	Bake Shop Theory Room	W3	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166	Bake Shop Theory Room	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166	Bake Shop Theory Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	166	Bake Shop Theory Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166	Bake Shop Theory Room	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	166	Bake Shop Theory Room	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	166	Bake Shop Theory Room	Door Frame W3	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	166	Bake Shop Theory Room	Window Frame W4	Metal	Grey	None	0	0.13	Negative	N/A	Sampling not required
1	1	166-1	Bake Shop Theory Room Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-1	Bake Shop Theory Room Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-1	Bake Shop Theory Room Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-1	Bake Shop Theory Room Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-1	Bake Shop Theory Room Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	166-1	Bake Shop Theory Room Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W1	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	166-2	Bake Shop Theory Room Storage - across from restroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-3	Bake Shop Theory Room Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-3	Bake Shop Theory Room Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-3	Bake Shop Theory Room Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-3	Bake Shop Theory Room Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-3	Bake Shop Theory Room Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-3	Bake Shop Theory Room Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-3	Bake Shop Theory Room Closet	Door Frame	Metal	Grey	None	0	0.5	Negative	N/A	
1	1	166-4	Bake Shop Theory Room Custodial Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-4	Bake Shop Theory Room Custodial Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-4	Bake Shop Theory Room Custodial Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-4	Bake Shop Theory Room Custodial Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	166-4	Bake Shop Theory Room Custodial Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	166-4	Bake Shop Theory Room Custodial Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	166-4	Bake Shop Theory Room Custodial Closet	Door Frame W1	Metal	Grey	None	0	0.01	Negative	N/A	Sampling not required
1	1	167	Locker Room Storage - across from School Store	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	167	Locker Room Storage - across from School Store	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	167	Locker Room Storage - across from School Store	W3	CMU	Yellow	None	0	0	Negative	Positive	inaccessible from storage and lockers-Confirmed in Donesafe-SRT
1	1	167	Locker Room Storage - across from School Store	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	167	Locker Room Storage - across from School Store	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	167	Locker Room Storage - across from School Store	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167	Locker Room Storage - across from School Store	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167-PC	Pipe Chase outside of 167A - Student Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167A	Student Restroom across from Classroom 144	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	167A	Student Restroom across from Classroom 144	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	167A	Student Restroom across from Classroom 144	W3	CMU	Yellow	None	0	0	Negative	Positive	inaccessible from storage and lockers-Confirmed in Donesafe-SRT
1	1	167A	Student Restroom across from Classroom 144	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	167A	Student Restroom across from Classroom 144	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	167A	Student Restroom across from Classroom 144	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	167A	Student Restroom across from Classroom 144	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	168	Textbook Storage closet across from School Store - Room 161	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	168	Textbook Storage closet across from School Store - Room 161	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	168	Textbook Storage closet across from School Store - Room 161	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	168	Textbook Storage closet across from School Store - Room 161	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	168	Textbook Storage closet across from School Store - Room 161	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	168	Textbook Storage closet across from School Store - Room 161	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	168	Textbook Storage closet across from School Store - Room 161	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	168	Textbook Storage closet across from School Store - Room 161	Conduit box	Metal	Grey	None	0	0.06	Negative	N/A	
1	1	168	Textbook Storage closet across from School Store - Room 161	Conduit	Metal	Grey	None	0	0	Negative	N/A	
1	1	170	Culinary Cafe	W1	CMU	Brown	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	170	Culinary Cafe	W2	CMU	Brown	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	170	Culinary Cafe	W3	CMU	Brown	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	1	170	Culinary Cafe	W4	CMU	Brown	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	170	Culinary Cafe	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	170	Culinary Cafe	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	170	Culinary Cafe	Door Frame W4	Metal	Brown	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	170	Culinary Cafe	Door W4	Metal	Brown	None	0	0.02	Negative	N/A	
1	1	171	Teacher Dining Hall 171 (Lion's Den)	W1	Fiberboard	Grey	None	0	0	Negative	N/A	
1	1	171	Teacher Dining Hall 171 (Lion's Den)	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	171	Teacher Dining Hall 171 (Lion's Den)	W3	Fiberboard	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	171	Teacher Dining Hall 171 (Lion's Den)	W4	Fiberboard	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	171	Teacher Dining Hall 171 (Lion's Den)	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	171	Teacher Dining Hall 171 (Lion's Den)	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	171	Teacher Dining Hall 171 (Lion's Den)	Door Frame W4	Metal	Grey	None	0	0.03	Negative	N/A	Sampling not required
1	1	171	Teacher Dining Hall 171 (Lion's Den)	Door W4	Wood	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	W2	Metal	Tan	None	0	0.02	Negative	N/A	
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Door Frame W1	Metal	Green	None	0	0.05	Negative	N/A	
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Door W1	Wood	Green	None	0	0	Negative	N/A	
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Door Frame W4	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	172	Restaurant Classroom - Kitchen adj to Lion's Den	Door W4	Wood	Grey	None	0	0	Negative	N/A	
1	1	172A	Kitchen 172 - Teacher's Office	W1	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	172A	Kitchen 172 - Teacher's Office	W2	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	172A	Kitchen 172 - Teacher's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172A	Kitchen 172 - Teacher's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172A	Kitchen 172 - Teacher's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172A	Kitchen 172 - Teacher's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172B	Custodial Closet across from Teachers Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172B	Custodial Closet across from Teachers Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172B	Custodial Closet across from Teachers Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172B	Custodial Closet across from Teachers Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172B	Custodial Closet across from Teachers Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172B	Custodial Closet across from Teachers Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172B	Custodial Closet across from Teachers Office	Door W1	Wood	Green	None	0	0.02	Negative	N/A	
1	1	172B	Custodial Closet across from Teachers Office	Door Frame W1	Metal	Green	None	0	0.02	Negative	N/A	
1	1	172C	Electrical Room inside Kitchen 172	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172C	Electrical Room inside Kitchen 172	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172C	Electrical Room inside Kitchen 172	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172C	Electrical Room inside Kitchen 172	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172C	Electrical Room inside Kitchen 172	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172C	Electrical Room inside Kitchen 172	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172C	Electrical Room inside Kitchen 172	Conduit	Metal	Tan	None	0	0.11	Negative	N/A	
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172D	Custodial Closet in Kitchen 172 across from Electrical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172E	Food Storage Room next to Boys Restroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172E	Food Storage Room next to Boys Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172E	Food Storage Room next to Boys Restroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172E	Food Storage Room next to Boys Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172E	Food Storage Room next to Boys Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172E	Food Storage Room next to Boys Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172F	Boy's Restroom in Culinary	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172F	Boy's Restroom in Culinary	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172F	Boy's Restroom in Culinary	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172F	Boy's Restroom in Culinary	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172F	Boy's Restroom in Culinary	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172F	Boy's Restroom in Culinary	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172F	Boy's Restroom in Culinary	Door W1	Wood	Green	None	0	0	Negative	N/A	Sampling not required
1	1	172F	Boy's Restroom in Culinary	Door Frame W1	Metal	Green	None	0	0.02	Negative	N/A	Sampling not required
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	172G	Dry Storage area across from Kitchen 172 Boy's Room	Pipe	Metal	Tan	None	0	0	Negative	N/A	
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	Floor	Epoxy	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	Door Frame W1	Metal	Green	None	0	0	Negative	N/A	Sampling not required
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	Door W1	Wood	Green	None	0	0	Negative	N/A	Sampling not required
1	1	175	Candy Making Kitchen adjacent to Stairwell #4	Window Frame W2	Metal	Green	None	0	0.1	Negative	N/A	Sampling not required
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	W3	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	175A	Kitchen Storage Area between Candy Kitchen & Special Needs Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175B	Girl's Restroom inside Candy Kitchen Area	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175B	Girl's Restroom inside Candy Kitchen Area	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175B	Girl's Restroom inside Candy Kitchen Area	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175B	Girl's Restroom inside Candy Kitchen Area	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	175B	Girl's Restroom inside Candy Kitchen Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	175B	Girl's Restroom inside Candy Kitchen Area	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	175B	Girl's Restroom inside Candy Kitchen Area	Door W1	Wood	Green	None	0	0	Negative	N/A	Sampling not required
1	1	175B	Girl's Restroom inside Candy Kitchen Area	Door Frame W1	Metal	Green	None	0	0.03	Negative	N/A	Sampling not required
1	1	176	Candy Making Storage Area	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	176	Candy Making Storage Area	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	176	Candy Making Storage Area	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	176	Candy Making Storage Area	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	176	Candy Making Storage Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	176	Candy Making Storage Area	Floor	Epoxy	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176A	Office Inside Candy Making Storage	W1	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	176A	Office Inside Candy Making Storage	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	176A	Office Inside Candy Making Storage	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176A	Office Inside Candy Making Storage	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176A	Office Inside Candy Making Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	176A	Office Inside Candy Making Storage	Floor	Epoxy	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176A	Office Inside Candy Making Storage	Door Frame W1	Wood	Grey	None	0	0.03	Negative	N/A	Sampling not required
1	1	176A	Office Inside Candy Making Storage	Door Frame W2	Wood	Grey	None	0	0.03	Negative	N/A	Sampling not required
1	1	176B	Storage Inside Candy Making Office	W1	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	176B	Storage Inside Candy Making Office	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	176B	Storage Inside Candy Making Office	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176B	Storage Inside Candy Making Office	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176B	Storage Inside Candy Making Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	176B	Storage Inside Candy Making Office	Floor	Epoxy	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	176C	Storage room adjacent to Girls Restroom in Candy Kitchen	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	180	Student Cafeteria	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180	Student Cafeteria	Door Frame W1	Metal	Grey	None	0	0.5	Negative	N/A	
1	1	180	Student Cafeteria	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180	Student Cafeteria	Door Frame W3	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	180	Student Cafeteria	W2	Metal	Purple	None	0	0	Negative	N/A	
1	1	180	Student Cafeteria	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180	Student Cafeteria	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180	Student Cafeteria	W4	Sheetrock	Green	None	0	0	Negative	N/A	
1	1	180	Student Cafeteria	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Above Drop Ceiling/Unpainted
1	1	180	Student Cafeteria	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	180	Student Cafeteria	Railing	Metal	Red	None	0	0.2	Negative	N/A	
1	1	180A	Cafeteria Storage	W1	CMU	Tan	None	0	0.3	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180A	Cafeteria Storage	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180A	Cafeteria Storage	W3	CMU	Tan	None	0	0.4	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180A	Cafeteria Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180A	Cafeteria Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	180A	Cafeteria Storage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	180A	Cafeteria Storage	Door Casing	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	180B	Student Dining Area Storage outside H11B	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180B	Student Dining Area Storage outside H11B	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	180B	Student Dining Area Storage outside H11B	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180B	Student Dining Area Storage outside H11B	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	180B	Student Dining Area Storage outside H11B	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	180B	Student Dining Area Storage outside H11B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	180B	Student Dining Area Storage outside H11B	Door Frame	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	181	Math Classroom 184	W1	Sheetrock	Yellow	None	0	0	Negative	N/A	Sampling not required
1	1	181	Math Classroom 184	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181	Math Classroom 184	W2	Sheetrock	Yellow	None	0	0	Negative	N/A	Sampling not required
1	1	181	Math Classroom 184	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181	Math Classroom 184	W3	Sheetrock	Yellow	None	0	0	Negative	N/A	Sampling not required
1	1	181	Math Classroom 184	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181	Math Classroom 184	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181	Math Classroom 184	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	Sampling not required
1	1	181	Math Classroom 184	Column	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2	Classroom 182	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2	Classroom 182	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2	Classroom 182	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	181-2	Classroom 182	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	181-2	Classroom 182	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	181-2	Classroom 182	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2	Classroom 182	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2	Classroom 182	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2	Classroom 182	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	181-2	Classroom 182	Door Frame W4	Metal	Grey	None	0	0.03	Negative	N/A	Sampling not required
1	1	181-2	Classroom 182	Convector W3	Metal	Brown	None	0	0.06	Negative	N/A	Sampling not required
1	1	181-2C	Closet in Classroom 182	W1	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2C	Closet in Classroom 182	W2	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2C	Closet in Classroom 182	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2C	Closet in Classroom 182	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2C	Closet in Classroom 182	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2C	Closet in Classroom 182	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2C	Closet in Classroom 182	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	181-2S	Storage Room inside Classroom 182	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2S	Storage Room inside Classroom 182	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2S	Storage Room inside Classroom 182	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2S	Storage Room inside Classroom 182	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	181-2S	Storage Room inside Classroom 182	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2S	Storage Room inside Classroom 182	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	181-2S	Storage Room inside Classroom 182	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	Sampling not required
1	1	184	Cafeteria Kitchen	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	184	Cafeteria Kitchen	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	184	Cafeteria Kitchen	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	184	Cafeteria Kitchen	W4	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	184	Cafeteria Kitchen	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	184	Cafeteria Kitchen	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	184	Cafeteria Kitchen	Door Frame	Metal	Red	None	0	0.4	Negative	N/A	
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	W1	CMU	Tan	None	0	0.4	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	185	Men's Faculty Restroom in Kitchen - Locker Area	Door Frame	Metal	Red	None	0	0.4	Negative	N/A	
1	1	185-RR	Restroom Inside Space 185	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185-RR	Restroom Inside Space 185	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185-RR	Restroom Inside Space 185	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185-RR	Restroom Inside Space 185	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185-RR	Restroom Inside Space 185	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	185-RR	Restroom Inside Space 185	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	185-RR	Restroom Inside Space 185	Door Frame	Metal	Red	None	0	0.1	Negative	N/A	
1	1	185A	Cafeteria Office	W1	CMU	Tan	None	0	0.6	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185A	Cafeteria Office	W2	CMU	Tan	None	0	0.3	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185A	Cafeteria Office	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185A	Cafeteria Office	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	185A	Cafeteria Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	185A	Cafeteria Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	185A	Cafeteria Office	Door Frame	Metal	Red	None	0	0.5	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	186	Women's Restroom in Kitchen - Locker Room	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186	Women's Restroom in Kitchen - Locker Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186	Women's Restroom in Kitchen - Locker Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186	Women's Restroom in Kitchen - Locker Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186	Women's Restroom in Kitchen - Locker Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	186	Women's Restroom in Kitchen - Locker Room	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	186	Women's Restroom in Kitchen - Locker Room	Door Frame	Metal	Red	None	0	0.3	Negative	N/A	
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	186-RR	Women's Faculty Restroom in Kitchen - Restroom	Door Frame	Metal	Red	None	0	0.1	Negative	N/A	
1	1	187	Cafeteria Kitchen Dry Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	187	Cafeteria Kitchen Dry Storage	W2	CMU	Tan	None	0	0.4	Negative	Positive	Confirmed in Donesafe-SRT
1	1	187	Cafeteria Kitchen Dry Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	187	Cafeteria Kitchen Dry Storage	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	187	Cafeteria Kitchen Dry Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	187	Cafeteria Kitchen Dry Storage	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	187	Cafeteria Kitchen Dry Storage	Door Frame	Metal	Red	None	0	0.4	Negative	N/A	
1	1	188	Kitchen and Wash Storage by Windows	W1	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	188	Kitchen and Wash Storage by Windows	W2	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	188	Kitchen and Wash Storage by Windows	W3	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	188	Kitchen and Wash Storage by Windows	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	188	Kitchen and Wash Storage by Windows	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	188	Kitchen and Wash Storage by Windows	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	188	Kitchen and Wash Storage by Windows	Door Frame	Metal	Red	None	0	0.4	Negative	N/A	
1	1	189	Custodial Service Closet across from School Store room 142	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	189	Custodial Service Closet across from School Store room 142	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	189	Custodial Service Closet across from School Store room 142	W3	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	189	Custodial Service Closet across from School Store room 142	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	189	Custodial Service Closet across from School Store room 142	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	189	Custodial Service Closet across from School Store room 142	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	189	Custodial Service Closet across from School Store room 142	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	190	Boy's Restroom (Cafeteria) in H11D	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	190	Boy's Restroom (Cafeteria) in H11D	W2	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	190	Boy's Restroom (Cafeteria) in H11D	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	190	Boy's Restroom (Cafeteria) in H11D	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	190	Boy's Restroom (Cafeteria) in H11D	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	190	Boy's Restroom (Cafeteria) in H11D	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	190	Boy's Restroom (Cafeteria) in H11D	Door Casing	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	191	Girl's Restroom in Cafeteria in H11B	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	191	Girl's Restroom in Cafeteria in H11B	W2	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	191	Girl's Restroom in Cafeteria in H11B	W3	CMU	Tan	None	0	0.4	Negative	Positive	Confirmed in Donesafe-SRT
1	1	191	Girl's Restroom in Cafeteria in H11B	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	191	Girl's Restroom in Cafeteria in H11B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	191	Girl's Restroom in Cafeteria in H11B	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	191	Girl's Restroom in Cafeteria in H11B	Door Casing	Metal	Grey	None	0	0.2	Negative	N/A	
1	1	195	Student Resource Center	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	195	Student Resource Center	W2	CMU	Grey	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	1	195	Student Resource Center	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	195	Student Resource Center	W3	CMU	Grey	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	1	195	Student Resource Center	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	195	Student Resource Center	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	195	Student Resource Center	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	195	Student Resource Center	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	195	Student Resource Center	Door Frame W3	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	195	Student Resource Center	Window Frame W2	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	196	IMC Office	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	196	IMC Office	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	196	IMC Office	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	196	IMC Office	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	196	IMC Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	196	IMC Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	196	IMC Office	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	196	IMC Office	Window Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	196	IMC Office	Window Frame W4	Metal	Grey	None	0	0.14	Negative	N/A	
1	1	197	Student Resource Center Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	197	Student Resource Center Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	197	Student Resource Center Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	197	Student Resource Center Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	197	Student Resource Center Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	197	Student Resource Center Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	197	Student Resource Center Office	Door Frame W1	Metal	Grey	None	0	0.01	Negative	N/A	Sampling not required
1	1	198	Book Storage (MDF)	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	198	Book Storage (MDF)	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	198	Book Storage (MDF)	W3	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	198	Book Storage (MDF)	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	198	Book Storage (MDF)	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	198	Book Storage (MDF)	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	198	Book Storage (MDF)	Door Frame W1	Metal	Grey	None	0	0.1	Negative	N/A	Sampling not required
1	1	198	Book Storage (MDF)	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	199	Elevator Control Room	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	199	Elevator Control Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	199	Elevator Control Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	199	Elevator Control Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	199	Elevator Control Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	199	Elevator Control Room	Ceiling	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	199	Elevator Control Room	Door Frame W1	Metal	Grey	None	0	0.07	Negative	N/A	Sampling not required
1	1	199	Elevator Control Room	Door	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	20	Tool Storage near Gym	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	20	Tool Storage near Gym	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20	Tool Storage near Gym	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20	Tool Storage near Gym	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20	Tool Storage near Gym	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20	Tool Storage near Gym	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	20	Tool Storage near Gym	Shelf	Wood	White	None	0	0.02	Negative	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	20A	Room 55 - Classroom outside Machine Shop	W1	Sheetrock	Tan	None	0	0.2	Negative	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	W2	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20A	Room 55 - Classroom outside Machine Shop	W4	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	20A	Room 55 - Classroom outside Machine Shop	Pipe	Metal	Tan	None	0	0.1	Negative	N/A	
1	1	20A-2	Batting Cage Classroom	W1	Sheetrock	White	None	0	0	Negative	N/A	
1	1	20A-2	Batting Cage Classroom	W2	Sheetrock	White	None	0	0	Negative	N/A	
1	1	20A-2	Batting Cage Classroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20A-2	Batting Cage Classroom	W4	CMU	White	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20A-2	Batting Cage Classroom	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	20A-2	Batting Cage Classroom	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	20A-3	Batting Cage Classroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20A-3	Batting Cage Classroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20A-3	Batting Cage Classroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20A-3	Batting Cage Classroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20A-3	Batting Cage Classroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20A-3	Batting Cage Classroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Inaccessible due to items in room
1	1	20B	Machine Shop	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	20B	Machine Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20B	Machine Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20B	Machine Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20B	Machine Shop	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	20B	Machine Shop	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	20B	Machine Shop	Column	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20B	Machine Shop	Door Frame	Metal	Brown	None	0	0.04	Negative	N/A	
1	1	20C	Staff Locker Room	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	20C	Staff Locker Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	20C	Staff Locker Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20C	Staff Locker Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20C	Staff Locker Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20C	Staff Locker Room	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	20C	Staff Locker Room	Door Frame W1	Metal	Green	None	0	0.02	Negative	N/A	
1	1	20SR	Gym Storage Room #1	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20SR	Gym Storage Room #1	Door Frame W1	Metal	Blue	None	0	0.4	Negative	N/A	
1	1	20SR	Gym Storage Room #1	Door W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	20SR	Gym Storage Room #1	W2	CMU	Unpainted	None	N/A	N/A	N/A	N/A	
1	1	20SR	Gym Storage Room #1	W3	CMU	Unpainted	None	N/A	N/A	N/A	N/A	
1	1	20SR	Gym Storage Room #1	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	20SR	Gym Storage Room #1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	20SR	Gym Storage Room #1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	Door Frame	Metal	Black	None	0	0.05	Negative	N/A	
1	1	21	Custodial Closet in H-Gym1 below Weight Room Storage	Pipe	Metal	Black	None	0	0.04	Negative	N/A	
1	1	22	Weight Room Storage	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	22	Weight Room Storage	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	22	Weight Room Storage	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	22	Weight Room Storage	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	22	Weight Room Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	22	Weight Room Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	23	Female Staff Restroom (Gym) - Outside Machine Shop	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	24	Girl's Restroom (Gym) - Outside Machine Shop	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	25	Mens Faculty Restroom (Gym) - outside Machine	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	25	Mens Faculty Restroom (Gym) - outside Machine Shop	Door Frame W1	Metal	Green	None	0	0.02	Negative	N/A	
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	W4	CMU	Tan	None	0	0.6	Negative	Positive	Confirmed in Donesafe-SRT
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	Pipe	Metal	White	None	0	0.1	Negative	N/A	
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	Convector	Metal	White	None	0	0	Negative	N/A	
1	1	26	Men's Restroom (Gym) - Outside of Machine Shop	Door Frame	Metal	Black	None	0	0.2	Negative	N/A	
1	1	27	Gym Storage	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	27	Gym Storage	W1	CMU	Pink	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	27	Gym Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	27	Gym Storage	W2	CMU	Pink	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	27	Gym Storage	Shelf	Wood	Tan	None	0	0	Negative	N/A	
1	1	27	Gym Storage	W3	CMU	Pink	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	27	Gym Storage	W4	CMU	Pink	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	27	Gym Storage	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	27	Gym Storage	Window Frame W1	Metal	Pink	None	0	0.16	Negative	N/A	
1	1	27	Gym Storage	Door Frame W1	Metal	Pink	None	0	0.02	Negative	N/A	
1	1	27	Gym Storage	Duct W1	Metal	Pink	None	0	0.02	Negative	N/A	
1	1	27	Gym Storage	Shelf W2	Wood	Purple	None	0	0	Negative	N/A	
1	1	28	Health Classroom	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	28	Health Classroom	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	28	Health Classroom	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	28	Health Classroom	W3	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	28	Health Classroom	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	28	Health Classroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	28	Health Classroom	Door Frame W1	Metal	Red	None	0	0.5	Negative	N/A	
1	1	28	Health Classroom	Window Frame W1	Metal	Red	None	0	0.4	Negative	N/A	
1	1	28	Health Classroom	Door W1	Wood	Blue	None	0	0	Negative	N/A	
1	1	29	Gym Office	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	29	Gym Office	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	29	Gym Office	W2	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	29	Gym Office	W3	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	29	Gym Office	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	29	Gym Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	29	Gym Office	Window Frame W1	Metal	Green	None	0	0.3	Negative	N/A	
1	1	29	Gym Office	Door Frame W1	metal	Red	None	0	0.06	Negative	N/A	
1	1	30	Weight Room	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	30	Weight Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	30	Weight Room	Baseboard W1	Wood	Red	None	0	0	Negative	N/A	
1	1	30	Weight Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	30	Weight Room	Baseboard W2	Wood	Red	None	0	0	Negative	N/A	
1	1	30	Weight Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	30	Weight Room	Baseboard W3	Wood	Red	None	0	0	Negative	N/A	
1	1	30	Weight Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	30	Weight Room	Baseboard W4	Wood	Red	None	0	0	Negative	N/A	
1	1	30	Weight Room	Floor	Foam	Unpainted	None	0	N/A	N/A	N/A	
1	1	30	Weight Room	Door Frame W1	Metal	Red	None	0	0.04	Negative	N/A	
1	1	30	Weight Room	Window Frame W1	Metal	Red	None	0	0.03	Negative	N/A	
1	1	40	Boys Locker Room	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	40	Boys Locker Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	40	Boys Locker Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	40	Boys Locker Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	40	Boys Locker Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	40	Boys Locker Room	Pipe	Metal	Red	None	0	0	Negative	N/A	
1	1	40	Boys Locker Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	41	Boy's Restroom Across from Machine Shop in H15D	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	41	Boy's Restroom Across from Machine Shop in H15D	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	41	Boy's Restroom Across from Machine Shop in H15D	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	41	Boy's Restroom Across from Machine Shop in H15D	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	41	Boy's Restroom Across from Machine Shop in H15D	W4	CMU	Tan	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	1	41	Boy's Restroom Across from Machine Shop in H15D	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	41	Boy's Restroom Across from Machine Shop in H15D	pipe	metal	red	None	0	0.01	Negative	N/A	
1	1	41	Boy's Restroom Across from Machine Shop in H15D	Convactor	metal	Grey	none	0	0.14	Negative	N/A	
1	1	42	Custodial Closet outside plumbing Office	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	42	Custodial Closet outside plumbing Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	42	Custodial Closet outside plumbing Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	42	Custodial Closet outside plumbing Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	42	Custodial Closet outside plumbing Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	42	Custodial Closet outside plumbing Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	42	Custodial Closet outside plumbing Office	Door Frame	Metal	Yellow	None	0	0.05	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	43	Girl's Restroom Across from Machine Shop in H15D	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	43	Girl's Restroom Across from Machine Shop in H15D	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	43	Girl's Restroom Across from Machine Shop in H15D	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	43	Girl's Restroom Across from Machine Shop in H15D	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	43	Girl's Restroom Across from Machine Shop in H15D	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	43	Girl's Restroom Across from Machine Shop in H15D	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	43	Girl's Restroom Across from Machine Shop in H15D	Door Frame W1	Metal	Yellow	None	0	0	Negative	N/A	
1	1	44	Welding Shop Storage	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	44	Welding Shop Storage	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	44	Welding Shop Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	44	Welding Shop Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	44	Welding Shop Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	44	Welding Shop Storage	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	44	Welding Shop Storage	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	
1	1	44	Welding Shop Storage	pipe	Metal	Red	None	0	0	Negative	N/A	
1	1	44	Welding Shop Storage	Door Frame W4	Metal	Yellow	None	0	0.04	Negative	N/A	
1	1	45	Machine Shop Storage (IDF-2)	Wall	CMU	No Access	No Access	No Access	No Access	No Access	Positive	
1	1	45	Machine Shop Storage (IDF-2)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	45	Machine Shop Storage (IDF-2)	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	45	Machine Shop Storage (IDF-2)	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	45	Machine Shop Storage (IDF-2)	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	45	Machine Shop Storage (IDF-2)	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	45	Machine Shop Storage (IDF-2)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	46	Staff Restroom outside Masonry Classroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	47	Masonry Classroom Storage	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	47	Masonry Classroom Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	47	Masonry Classroom Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	47	Masonry Classroom Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	47	Masonry Classroom Storage	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	47	Masonry Classroom Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	48	Welding Classroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	48	Welding Classroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	48	Welding Classroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	48	Welding Classroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	48	Welding Classroom	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	48	Welding Classroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Above Drop Ceiling/Unpainted
1	1	48	Welding Classroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	48	Welding Classroom	Door frame W1	Metal	Yellow	None	0	0	Negative	N/A	
1	1	48	Welding Classroom	Window Frame W4	Metal	Yellow	None	0	0.11	Negative	N/A	
1	1	48	Welding Classroom	Window Frame W1	Wood	Yellow	None	0	0.06	Negative	N/A	
1	1	49	Shop Theory Classroom #1 Carpentry	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	49	Shop Theory Classroom #1 Carpentry	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	49	Shop Theory Classroom #1 Carpentry	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	49	Shop Theory Classroom #1 Carpentry	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	49	Shop Theory Classroom #1 Carpentry	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	49	Shop Theory Classroom #1 Carpentry	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	49	Shop Theory Classroom #1 Carpentry	Door Frame W1	Metal	Yellow	None	0	0.02	Negative	N/A	
1	1	49	Shop Theory Classroom #1 Carpentry	Window Frame W1	Metal	Yellow	None	0	0.09	Negative	N/A	
1	1	49	Shop Theory Classroom #1 Carpentry	Window Frame W2	Metal	Yellow	None	0	0.03	Negative	N/A	
1	1	50	Shop Theory Classroom #2 Plumbing	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	50	Shop Theory Classroom #2 Plumbing	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	50	Shop Theory Classroom #2 Plumbing	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	50	Shop Theory Classroom #2 Plumbing	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	50	Shop Theory Classroom #2 Plumbing	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	50	Shop Theory Classroom #2 Plumbing	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	50	Shop Theory Classroom #2 Plumbing	Door Frame	Metal	Yellow	None	0	0.03	Negative	N/A	
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	Ceiling	Concrete	White	None	0	0.2	Negative	N/A	Sampling not required
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	Door Frame	Metal	Red	None	0	0.3	Negative	N/A	
1	1	51	Shop Theory Classroom #3 Electrical - Room 51	Window Frame	Metal	Red	None	0	0.4	Negative	N/A	
1	1	51-S	Electrical Shop Storage above Classroom areas	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51-S	Electrical Shop Storage above Classroom areas	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51-S	Electrical Shop Storage above Classroom areas	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51-S	Electrical Shop Storage above Classroom areas	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51-S	Electrical Shop Storage above Classroom areas	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51-S	Electrical Shop Storage above Classroom areas	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51S-2	Electrical Shop Storage next to Classroom areas	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	51A	CTE Computer Lab - Room 69	Ceiling	Concrete	Tan	None	0	0.1	Negative	N/A	Sampling not required
1	1	51A	CTE Computer Lab - Room 69	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51A	CTE Computer Lab - Room 69	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	51A	CTE Computer Lab - Room 69	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51A	CTE Computer Lab - Room 69	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51A	CTE Computer Lab - Room 69	Floor	Wood	Unpainted	None	0	N/A	N/A	N/A	
1	1	51A	CTE Computer Lab - Room 69	Door	Metal	Tan	None	0	0	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Door Frame	Metal	Tan	None	0	0.5	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Pipe	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Baseboard W1	Wood	Blue	None	0	0	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Baseboard W2	Wood	Blue	None	0	0.1	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Baseboard W3	Wood	Blue	None	0	0.2	Negative	N/A	
1	1	51A	CTE Computer Lab - Room 69	Baseboard W4	Wood	Blue	None	0	0.1	Negative	N/A	
1	1	51B	Electrical Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B	Electrical Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B	Electrical Shop	W3	Wood	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	51B	Electrical Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B	Electrical Shop	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	51B	Electrical Shop	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	51B	Electrical Shop	Railing	Metal	Yellow	None	0	3.4	Positive	N/A	
1	1	51B	Electrical Shop	Stair Riser	Metal	Yellow	None	0	0.06	Negative	N/A	
1	1	51B	Electrical Shop	Stair Stringer	Metal	Yellow	None	0	1.6	Positive	N/A	
1	1	51B	Electrical Shop	Roll up Door Casing W4	Metal	Red	None	0	0	Negative	N/A	
1	1	51B	Electrical Shop	Door Frame W4	Metal	Yellow	None	0	0.2	Negative	N/A	
1	1	51B	Electrical Shop	Door W4	Metal	Yellow	None	0	0.3	Negative	N/A	
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	Shelf	Metal	Green	None	0	0.2	Negative	N/A	
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	Door Frame	Metal	Yellow	None	0	0	Negative	N/A	
1	1	51B-S1	Electrical Shop - Storage Closet near Garage Door	Door	Metal	Yellow	None	0	0	Negative	N/A	
1	1	51B-S2	Electric Shop - Large Storage Area near Garage Bay Door	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S2	Electric Shop - Large Storage Area near Garage Bay Door	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S2	Electric Shop - Large Storage Area near Garage Bay Door	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S2	Electric Shop - Large Storage Area near Garage Bay Door	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51B-S2	Electric Shop - Large Storage Area near Garage Bay Door	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	51C	Electrical Shop - Storage Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51C	Electrical Shop - Storage Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51C	Electrical Shop - Storage Room	W3	Concrete	Tan	None	0	0.1	Negative	N/A	
1	1	51C	Electrical Shop - Storage Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	51C	Electrical Shop - Storage Room	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	51C	Electrical Shop - Storage Room	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	51C	Electrical Shop - Storage Room	Door Frame W1	Concrete	Yellow	None	0	0.4	Negative	N/A	
1	1	51D	Electrical Shop - Tool Storage	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51D	Electrical Shop - Tool Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51D	Electrical Shop - Tool Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51D	Electrical Shop - Tool Storage	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51D	Electrical Shop - Tool Storage	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	51D	Electrical Shop - Tool Storage	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	51D	Electrical Shop - Tool Storage	Door Frame w1	Metal	Yellow	None	0	0.3	Negative	N/A	
1	1	51D	Electrical Shop - Tool Storage	Railing	Metal	Yellow	None	0	0	Negative	N/A	
1	1	51E	Carpentry / Construction Area	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51E	Carpentry / Construction Area	W2	CMU	Tan	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51E	Carpentry / Construction Area	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51E	Carpentry / Construction Area	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51E	Carpentry / Construction Area	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	51E	Carpentry / Construction Area	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	51E	Carpentry / Construction Area	Conduit W4	Metal	Blue	None	0	0.14	Negative	N/A	
1	1	51E	Carpentry / Construction Area	Electrical Box W4	Metal	Green	None	0	0.5	Negative	N/A	
1	1	51E	Carpentry / Construction Area	Garage Door Frame W1	Metal	Green	None	0	0.4	Negative	N/A	
1	1	51E	Carpentry / Construction Area	Door W1	Metal	Yellow	None	0	0.05	Negative	N/A	
1	1	51E	Carpentry / Construction Area	Garage Door Frame W4	Metal	Yellow	None	0	0.03	Negative	N/A	
1	1	51M	Masonry Classroom	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51M	Masonry Classroom	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51M	Masonry Classroom	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51M	Masonry Classroom	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	51M	Masonry Classroom	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	51M	Masonry Classroom	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	51M	Masonry Classroom	Door Frame W3	Metal	Orange	None	0	2.8	Positive	N/A	
1	1	51M	Masonry Classroom	Door W3	Metal	Red/Orange	None	0	6.4	Positive	N/A	
1	1	51M	Masonry Classroom	Garage Door Frame W3	Metal	Yellow	None	0	0	Negative	N/A	
1	1	51M	Masonry Classroom	Electrical Box W4	Metal	Grey	None	0	0.01	Negative	N/A	
1	1	51M	Masonry Classroom	Conduit W4	Metal	Tan	None	0	0.09	Negative	N/A	
1	1	6	Office across from School Police	Ceiling	Concrete	White	None	0	0.3	Negative	N/A	Sampling not required
1	1	6	Office across from School Police	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6	Office across from School Police	W2	CMU	Blue	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6	Office across from School Police	W3	Sheetrock	Blue	None	0	0	Negative	N/A	
1	1	6	Office across from School Police	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6	Office across from School Police	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	6	Office across from School Police	Baseboard W3	Wood	Unpainted	None	0	N/A	N/A	N/A	
1	1	6	Office across from School Police	Window Frame W3	Wood	Unpainted	None	0	N/A	N/A	N/A	
1	1	6A	Storage Room	W1	Sheetrock	Blue	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	6A	Storage Room	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6A	Storage Room	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6A	Storage Room	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	6A	Storage Room	Ceiling	Concrete	White	None	0	0.3	Negative	N/A	Sampling not required
1	1	6A	Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	6A	Storage Room	Door Frame W1	Metal	Blue	None	0	0.2	Negative	N/A	Sampling not required
1	1	6A	Storage Room	Door Frame W3	Metal	Blue	None	0	0.4	Negative	N/A	Sampling not required
1	1	6A	Storage Room	Window Frame W3	Wood	Blue	None	0	0	Negative	N/A	Sampling not required
1	1	60	Electrical Room	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60	Electrical Room	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60	Electrical Room	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60	Electrical Room	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60	Electrical Room	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	60	Electrical Room	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	60	Electrical Room	Door W3	Metal	Grey	None	0	0.02	Negative	N/A	
1	1	60	Electrical Room	Door Frame W3	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	60	Electrical Room	Door W1	Metal	Grey	None	0	0.13	Negative	N/A	
1	1	60	Electrical Room	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	1	60A	Boiler Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	W1	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	W2	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	W3	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	W4	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	Door	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	Door Frame	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60A	Boiler Room	Duct	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60B	Loading Dock	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	60B	Loading Dock	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60B	Loading Dock	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60B	Loading Dock	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60B	Loading Dock	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	60B	Loading Dock	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	60B	Loading Dock	Door Frame W1	Metal	Grey	None	0	0.06	Negative	N/A	
1	1	60B	Loading Dock	Door W1	Metal	Grey	None	0	0.06	Negative	N/A	
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	60D	Hallway from Building Engineers Office to Loading Dock Exit	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	60E	Emergency Generator Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60E	Emergency Generator Room	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	60E	Emergency Generator Room	W3	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	60E	Emergency Generator Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	60E	Emergency Generator Room	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	60E	Emergency Generator Room	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	60E	Emergency Generator Room	Pipe	Metal	Red	None	0	0.4	Negative	N/A	
1	1	64	Trash Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	64	Trash Area	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W1	CMU	Brown	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W2	CMU	Brown	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W3	CMU	Brown	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	W4	CMU	Brown	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	64	Trash Area	Door W3	Metal	Grey	None	0	0.05	Negative	N/A	
1	1	64	Trash Area	Door Frame W3	Metal	Grey	None	0	0.03	Negative	N/A	
1	1	64	Trash Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	65	FAC Office	W1	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	65	FAC Office	W2	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	1	65	FAC Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	65	FAC Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	65	FAC Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	65	FAC Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	65	FAC Office	Door Frame W1	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	65	FAC Office	Convactor	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	66	Building Engineer's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	66	Building Engineer's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	66	Building Engineer's Office	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	66	Building Engineer's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	66	Building Engineer's Office	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	66	Building Engineer's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	66	Building Engineer's Office	Door Frame W1	Metal	Grey	None	0	0.4	Negative	N/A	
1	1	66	Building Engineer's Office	Convactor	Metal	Grey	None	0	0.3	Negative	N/A	Unpainted
1	1	67	Men's Restroom by Building Engineers Office	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67	Men's Restroom by Building Engineers Office	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67	Men's Restroom by Building Engineers Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67	Men's Restroom by Building Engineers Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67	Men's Restroom by Building Engineers Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	67	Men's Restroom by Building Engineers Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	67	Men's Restroom by Building Engineers Office	Convactor	Metal	Grey	None	0	0	Negative	N/A	
1	1	67A	Custodial Break Room	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	67A	Custodial Break Room	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67A	Custodial Break Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67A	Custodial Break Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	67A	Custodial Break Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	67A	Custodial Break Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	67A	Custodial Break Room	Convactor	Metal	Grey	None	0	0	Negative	N/A	
1	1	68	Women's Restroom by Building Engineers Office	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	68	Women's Restroom by Building Engineers Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	68	Women's Restroom by Building Engineers Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	68	Women's Restroom by Building Engineers Office	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	68	Women's Restroom by Building Engineers Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	68	Women's Restroom by Building Engineers Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	68	Women's Restroom by Building Engineers Office	Door Frame	Metal	Grey	None	0	0.2	Negative	N/A	
1	1	68	Women's Restroom by Building Engineers Office	Convactor	Metal	Grey	None	0	0	Negative	N/A	
1	1	7	School Police	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	7	School Police	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	7	School Police	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	7	School Police	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	7	School Police	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	7	School Police	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	7	School Police	Door Frame W1	Wood	Blue	None	0	0.3	Negative	N/A	Sampling not required
1	1	7	School Police	Pipe	Metal	Red	None	0	0.1	Negative	N/A	Sampling not required
1	1	7	School Police	Window Frame W1	Metal	Blue	None	0	0.1	Negative	N/A	Sampling not required
1	1	8	Custodial Closet near School Police Office	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	8	Custodial Closet near School Police Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	8	Custodial Closet near School Police Office	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	8	Custodial Closet near School Police Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	8	Custodial Closet near School Police Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	8	Custodial Closet near School Police Office	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	8	Custodial Closet near School Police Office	Shelf	Wood	Tan	None	0	0	Negative	N/A	
1	1	8	Custodial Closet near School Police Office	Door Frame W1	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	9	Auto Body Storage adj to Custodial Closet	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9	Auto Body Storage adj to Custodial Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9	Auto Body Storage adj to Custodial Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9	Auto Body Storage adj to Custodial Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9	Auto Body Storage adj to Custodial Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9	Auto Body Storage adj to Custodial Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
1	1	9A	Female Faculty Restroom by School Police Office	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	1	9A	Female Faculty Restroom by School Police Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	9A	Female Faculty Restroom by School Police Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	9A	Female Faculty Restroom by School Police Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	9A	Female Faculty Restroom by School Police Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	9A	Female Faculty Restroom by School Police Office	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	9A	Female Faculty Restroom by School Police Office	Pipe Chase	Metal	Blue	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	GH1	Greenhouse next to Classroom 130	W1	Brick	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GH1	Greenhouse next to Classroom 130	W2	Brick	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GH1	Greenhouse next to Classroom 130	W3	Brick	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GH1	Greenhouse next to Classroom 130	W4	Brick	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GH1	Greenhouse next to Classroom 130	Ceiling	Glass	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GH1	Greenhouse next to Classroom 130	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	GYM	Gym	Floor	Concrete	Grey	None	0	0.4	Negative	N/A	Sampling not required
1	1	GYM	Gym	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	GYM	Gym	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	GYM	Gym	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	GYM	Gym	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	GYM	Gym	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	GYM	Gym	Roll up Door	Metal	Blue	None	0	0	Negative	N/A	
1	1	GYM	Gym	Door Frame W1	Metal	Blue	None	0	0.5	Negative	N/A	
1	1	GYM	Gym	Door Frame W3	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Door Frame W4	Metal	Blue	None	0	0	Negative	N/A	
1	1	GYM	Gym	Door W1	Metal	Blue	None	0	0	Negative	N/A	
1	1	GYM	Gym	Door W3	Metal	Blue	None	0	0	Negative	N/A	
1	1	GYM	Gym	Baseboard W1	Wood	Red	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Baseboard W2	Wood	Red	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Baseboard W3	Wood	Red	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Baseboard W4	Wood	Red	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Pipe	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	GYM	Gym	Electrical Panel	Metal	Blue	None	0	0	Negative	N/A	
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-ABS	Hallway from School Police to Auto-Body Shop	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	W2	Sheetrock	White	None	0	0.1	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	W3	Sheetrock	White	None	0	0.1	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	W4	CMU	Tan	None	0	0.4	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Door Frame W2	Metal	Red	None	0	0	Negative	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Pipe	Metal	Blue	None	0	0.1	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Baseboard W1	Wood	Red	None	0	0.1	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Baseboard W2	Wood	Red	None	0	0	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Baseboard W3	Wood	Red	None	0	0	Negative	N/A	
1	1	H-Gym1	Hallway from Welding Classroom to Health Classroom near Gym	Baseboard W4	Wood	Red	None	0	0.1	Negative	N/A	
1	1	H10	Hallway between Main Office and Nurse's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10	Hallway between Main Office and Nurse's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10	Hallway between Main Office and Nurse's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10	Hallway between Main Office and Nurse's Office	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10	Hallway between Main Office and Nurse's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H10	Hallway between Main Office and Nurse's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H10A	Hallway adjacent to Room 113	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10A	Hallway adjacent to Room 113	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10A	Hallway adjacent to Room 113	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10A	Hallway adjacent to Room 113	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10A	Hallway adjacent to Room 113	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H10A	Hallway adjacent to Room 113	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H10B	Hallway at Nursing Suite	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10B	Hallway at Nursing Suite	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10B	Hallway at Nursing Suite	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10B	Hallway at Nursing Suite	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	above drop ceiling/Unpainted
1	1	H10B	Hallway at Nursing Suite	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H10C	Hallway in Main Office Suite	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10C	Hallway in Main Office Suite	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H10C	Hallway in Main Office Suite	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H10C	Hallway in Main Office Suite	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11	Hallway from Stairwell #2 to Stairwell #5	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11A	Hallway Vestibule outside Stairs #5	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11A	Hallway Vestibule outside Stairs #5	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11A	Hallway Vestibule outside Stairs #5	W3	CMU	Tan	None	0	0.3	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11A	Hallway Vestibule outside Stairs #5	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11A	Hallway Vestibule outside Stairs #5	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11A	Hallway Vestibule outside Stairs #5	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11B	Hallway at Emergency Exit adjacent to Nurse's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11C	Hallway Connector to IMC	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11C	Hallway Connector to IMC	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11C	Hallway Connector to IMC	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H11C	Hallway Connector to IMC	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	H11C	Hallway Connector to IMC	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11C	Hallway Connector to IMC	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	W1	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	W2	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	W3	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	W4	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11D	Corridor 180A - Hallway between boys cafeteria restroom & Kitchen	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	W1	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	W2	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	W3	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	W4	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E	Corridor 180B - Hallway outside Girl's Cafeteria Restroom	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	Shot as 180 (Cafeteria)
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11E-PC1	Pipe Chase adjacent to Girls Cafeteria Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H11E-PC2	Pipe Chase Across from Girls Cafeteria Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	H12	Hallway from H13 to Classroom 128	W1	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H12	Hallway from H13 to Classroom 128	W2	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H12	Hallway from H13 to Classroom 128	W2	Sheetrock	Tan	None	0	0	Negative	N/A	
1	1	H12	Hallway from H13 to Classroom 128	W3	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H12	Hallway from H13 to Classroom 128	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H12	Hallway from H13 to Classroom 128	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H12	Hallway from H13 to Classroom 128	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H12	Hallway from H13 to Classroom 128	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	H12	Hallway from H13 to Classroom 128	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	1	H12	Hallway from H13 to Classroom 128	Door Frame W3	Metal	Grey	None	0	0	Negative	N/A	
1	1	H13	Hallway From School Store to Classroom 130	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13	Hallway From School Store to Classroom 130	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13	Hallway From School Store to Classroom 130	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13	Hallway From School Store to Classroom 130	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13	Hallway From School Store to Classroom 130	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13	Hallway From School Store to Classroom 130	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13-PC	Pipe Chase outside space H13A	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H13-PC	Pipe Chase outside space H13A	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H13-PC	Pipe Chase outside space H13A	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H13-PC	Pipe Chase outside space H13A	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	1	H13-PC	Pipe Chase outside space H13A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13-PC	Pipe Chase outside space H13A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13A	Hallway Foyer outside Classroom 131	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13A	Hallway Foyer outside Classroom 131	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13A	Hallway Foyer outside Classroom 131	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13A	Hallway Foyer outside Classroom 131	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13A	Hallway Foyer outside Classroom 131	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13A	Hallway Foyer outside Classroom 131	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13B	Hallway at Culinary/Bakery(Kitchen)	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13B	Hallway at Culinary/Bakery(Kitchen)	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13B	Hallway at Culinary/Bakery(Kitchen)	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	H13B	Hallway at Culinary/Bakery(Kitchen)	Floor	Ceramic Tile	Unpainted	None	0	N/A	N/A	N/A	
1	1	H13C	Hallway in Culinary/Bakery (Wing)	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C	Hallway in Culinary/Bakery (Wing)	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C	Hallway in Culinary/Bakery (Wing)	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C	Hallway in Culinary/Bakery (Wing)	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	H13C	Hallway in Culinary/Bakery (Wing)	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13C	Hallway in Culinary/Bakery (Wing)	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H13C-S	Kitchen Cleaning and Cooking Supplies next to Bake Shoppe Theory Room (with IDF-3)	Door Frame W1	Metal	Grey	None	0	0.5	Negative	N/A	
1	1	H15	Hallway by Main Lobby	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15	Hallway by Main Lobby	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15	Hallway by Main Lobby	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15	Hallway by Main Lobby	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15	Hallway by Main Lobby	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15	Hallway by Main Lobby	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H151	Hallway outside Room 151	W1	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H151	Hallway outside Room 151	W2	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H151	Hallway outside Room 151	W3	Sheetrock	Yellow	None	0	0	Negative	N/A	Sampling not required
1	1	H151	Hallway outside Room 151	W4	CMU	Yellow	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H151	Hallway outside Room 151	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H151	Hallway outside Room 151	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H151	Hallway outside Room 151	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	1	H15A	Main Building Entrance Foyer	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15A	Main Building Entrance Foyer	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15A	Main Building Entrance Foyer	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15A	Main Building Entrance Foyer	W4	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15A	Main Building Entrance Foyer	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15A	Main Building Entrance Foyer	Floor	Concrete	Unpainted	None	0	N/A	N/A	N/A	
1	1	H15A	Main Building Entrance Foyer	Door Frame	Metal	Brown	None	0	0.3	Negative	N/A	
1	1	H15A	Main Building Entrance Foyer	Door	Metal	Brown	None	0	0	Negative	N/A	
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15B	Hallway between Main Lobby and Hall to Maintenance Area	Lockers	Metal	Blue	None	0	0.4	Negative	N/A	
1	1	H15C	Entrance foyer by Stairwell #6	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15C	Entrance foyer by Stairwell #6	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15C	Entrance foyer by Stairwell #6	W3	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15C	Entrance foyer by Stairwell #6	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15C	Entrance foyer by Stairwell #6	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15D	Hallway from H15B to Electrical Shop	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15D	Hallway from H15B to Electrical Shop	W2	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	H15D	Hallway from H15B to Electrical Shop	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15D	Hallway from H15B to Electrical Shop	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15D	Hallway from H15B to Electrical Shop	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15D	Hallway from H15B to Electrical Shop	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	H15D	Hallway from H15B to Electrical Shop	Door Frame	Metal	Yellow	None	0	0	Negative	N/A	
1	1	H15E	Masonry/Carpentry Hallway	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15E	Masonry/Carpentry Hallway	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15E	Masonry/Carpentry Hallway	W3	Wood	Tan	None	0	0	Negative	N/A	Sampling not required
1	1	H15E	Masonry/Carpentry Hallway	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	H15E	Masonry/Carpentry Hallway	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	H15E	Masonry/Carpentry Hallway	Floor	Concrete	Grey	None	0	0	Negative	N/A	
1	1	S-AB	Auto-Body Shop Stairs	W1	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S-AB	Auto-Body Shop Stairs	W2	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S-AB	Auto-Body Shop Stairs	W3	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S-AB	Auto-Body Shop Stairs	W4	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S-AB	Auto-Body Shop Stairs	Ceiling	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S-AB	Auto-Body Shop Stairs	Floor	N/A	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairs next to Main Office	W1	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S11	Stairs next to Main Office	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S11	Stairs next to Main Office	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S11	Stairs next to Main Office	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S11	Stairs next to Main Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairs next to Main Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S11	Stairs next to Main Office	Stringer	Metal	Grey	None	0	0	Negative	N/A	
1	1	S11	Stairs next to Main Office	Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	S11	Stairs next to Main Office	Door	Metal	Grey	None	0	0	Negative	N/A	
1	1	S11	Stairs next to Main Office	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	S12	Stairs next to Classroom 138	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S12	Stairs next to Classroom 138	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S12	Stairs next to Classroom 138	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S12	Stairs next to Classroom 138	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S12	Stairs next to Classroom 138	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S12	Stairs next to Classroom 138	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S12	Stairs next to Classroom 138	Stringer	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	S12	Stairs next to Classroom 138	Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	S12	Stairs next to Classroom 138	Door	Metal	Grey	None	0	0	Negative	N/A	
1	1	S12	Stairs next to Classroom 138	Door Frame	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	S13	Stairs next to Classroom 128	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S13	Stairs next to Classroom 128	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S13	Stairs next to Classroom 128	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S13	Stairs next to Classroom 128	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S13	Stairs next to Classroom 128	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S13	Stairs next to Classroom 128	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S13	Stairs next to Classroom 128	Stringer	Metal	Grey	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	1	S13	Stairs next to Classroom 128	Riser	Metal	Grey	None	0	0	Negative	N/A	
1	1	S13	Stairs next to Classroom 128	Door	Metal	Grey	None	0	0	Negative	N/A	
1	1	S13	Stairs next to Classroom 128	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	S14	Stairs next to Classroom 175	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S14	Stairs next to Classroom 175	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S14	Stairs next to Classroom 175	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S14	Stairs next to Classroom 175	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S14	Stairs next to Classroom 175	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S14	Stairs next to Classroom 175	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S14	Stairs next to Classroom 175	Stringer	Metal	Grey	None	0	0	Negative	N/A	
1	1	S14	Stairs next to Classroom 175	Riser	Metal	Grey	None	0	0	Negative	N/A	
1	1	S14	Stairs next to Classroom 175	Door	Metal	Grey	None	0	0	Negative	N/A	
1	1	S14	Stairs next to Classroom 175	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	S15	Stairs next to Classroom 171	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S15	Stairs next to Classroom 171	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S15	Stairs next to Classroom 171	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S15	Stairs next to Classroom 171	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S15	Stairs next to Classroom 171	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S15	Stairs next to Classroom 171	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S15	Stairs next to Classroom 171	Stringer	Metal	Grey	None	0	0	Negative	N/A	
1	1	S15	Stairs next to Classroom 171	Riser	Metal	Grey	None	0	0	Negative	N/A	
1	1	S15	Stairs next to Classroom 171	Door	Metal	Brown	None	0	0.1	Negative	N/A	
1	1	S15	Stairs next to Classroom 171	Door Frame	Metal	Brown	None	0	0.4	Negative	N/A	
1	1	S16	Stairs next to Classroom 181	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S16	Stairs next to Classroom 181	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S16	Stairs next to Classroom 181	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S16	Stairs next to Classroom 181	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	1	S16	Stairs next to Classroom 181	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	1	S16	Stairs next to Classroom 181	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	1	S16	Stairs next to Classroom 181	Stringer	Metal	Grey	None	0	0.3	Negative	N/A	
1	1	S16	Stairs next to Classroom 181	Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	1	S16	Stairs next to Classroom 181	Door	Metal	Brown	None	0	0	Negative	N/A	
1	1	S16	Stairs next to Classroom 181	Door Frame	Metal	Brown	None	0	0.5	Negative	N/A	
1	2	200A	Classroom 200	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200A	Classroom 200	W1	CMU	Tan	None	0	0.05	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200A	Classroom 200	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200A	Classroom 200	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200A	Classroom 200	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200A	Classroom 200	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200A	Classroom 200	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200A	Classroom 200	Door Frame	Metal	Grey	None	0	0	Negative	N/A	
1	2	200A	Classroom 200	Convactor	Metal	Tan	N/A	N/A	0.02	Negative	N/A	
1	2	200C-1	Classroom 200 - Right Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-1	Classroom 200 - Right Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	200C-1	Classroom 200 - Right Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-1	Classroom 200 - Right Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-1	Classroom 200 - Right Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200C-1	Classroom 200 - Right Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200C-1	Classroom 200 - Right Closet	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	200C-2	Classroom 200 - Left Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-2	Classroom 200 - Left Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-2	Classroom 200 - Left Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-2	Classroom 200 - Left Closet	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200C-2	Classroom 200 - Left Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200C-2	Classroom 200 - Left Closet	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200C-2	Classroom 200 - Left Closet	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	2	200C-2	Classroom 200 - Left Closet	Convactor	Metal	Tan	N/A	N/A	0.02	Negative	N/A	
1	2	200C-2	Classroom 200 - Left Closet	Pipe	Metal	Tan	N/A	N/A	0	Negative	N/A	
1	2	200B	Server/Electrical Room 214	Floor	Concrete	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	200B	Server/Electrical Room 214	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200B	Server/Electrical Room 214	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200B	Server/Electrical Room 214	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200B	Server/Electrical Room 214	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	200B	Server/Electrical Room 214	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200B	Server/Electrical Room 214	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	2	200F	ROTC Classroom 204	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200F	ROTC Classroom 204	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200F	ROTC Classroom 204	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200F	ROTC Classroom 204	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	200F	ROTC Classroom 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200F	ROTC Classroom 204	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	200F	ROTC Classroom 204	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	200F	ROTC Classroom 204	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	2	200F	ROTC Classroom 204	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	201	Classroom 201	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201	Classroom 201	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201	Classroom 201	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201	Classroom 201	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201	Classroom 201	W4	Concrete	Tan	None	0	0	Negative	N/A	
1	2	201	Classroom 201	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	201	Classroom 201	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	201	Classroom 201	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	201	Classroom 201	Convactor	Metal	Tan	N/A	N/A	0.05	Negative	N/A	
1	2	201B	Closet Inside Room 201	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201B	Closet Inside Room 201	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201B	Closet Inside Room 201	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201B	Closet Inside Room 201	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	201B	Closet Inside Room 201	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	201B	Closet Inside Room 201	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	201B	Closet Inside Room 201	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	201B	Closet Inside Room 201	Convector	Metal	Tan	N/A	N/A	0.03	Negative	N/A	
1	2	201A	Office 201A	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201A	Office 201A	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201A	Office 201A	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201A	Office 201A	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	201A	Office 201A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	201A	Office 201A	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	201A	Office 201A	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	201A	Office 201A	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	202	Classroom 202	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	202	Classroom 202	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	202	Classroom 202	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	202	Classroom 202	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	202	Classroom 202	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	202	Classroom 202	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	202	Classroom 202	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	202	Classroom 202	Column	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203	Classroom 203	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Classroom 203	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203	Classroom 203	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Classroom 203	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203	Classroom 203	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203	Classroom 203	W4	Sheetrock	Green	None	0	0	Negative	N/A	Sampling not required
1	2	203	Classroom 203	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	203	Classroom 203	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	203	Classroom 203	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	203	Classroom 203	Convector	Metal	Tan	None	0	0	Negative	N/A	
1	2	203	Storage Room in Room 203	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Storage Room in Room 203	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Storage Room in Room 203	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Storage Room in Room 203	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203	Storage Room in Room 203	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	203	Storage Room in Room 203	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	203	Storage Room in Room 203	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	(Formerly 203A)
1	2	203	Storage Room in Room 203	Column	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203	Storage Room in Room 203	Window Frame W3	Metal	Grey	None	0	0	Negative	N/A	(Formerly 203A)
1	2	203B	Office inside of Classroom 203	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203B	Office inside of Classroom 203	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203B	Office inside of Classroom 203	W3	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	2	203B	Office inside of Classroom 203	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	203B	Office inside of Classroom 203	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	203B	Office inside of Classroom 203	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	203B	Office inside of Classroom 203	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	203B	Office inside of Classroom 203	Door Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	203B	Office inside of Classroom 203	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	203B	Office inside of Classroom 203	Convactor	Metal	Grey	None	0	0.01	Negative	Not Sampled	
1	2	203B	Office inside of Classroom 203	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	2	205	Classroom 205	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205	Classroom 205	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205	Classroom 205	W2	Fiberboard	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205	Classroom 205	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	205	Classroom 205	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	205	Classroom 205	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	205	Classroom 205	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	205	Classroom 205	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	205	Classroom 205	Convactor	Metal	Grey	None	0	0.4	Negative	N/A	
1	2	205	Classroom 205	Door Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	205	Classroom 205	Pipe	Metal	Grey	None	0	0	Negative	N/A	
1	2	205	Classroom 205	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	205A	Large Office inside Classroom 205	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205A	Large Office inside Classroom 205	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205A	Large Office inside Classroom 205	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205A	Large Office inside Classroom 205	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	205A	Large Office inside Classroom 205	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	205A	Large Office inside Classroom 205	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	205A	Large Office inside Classroom 205	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	205A	Large Office inside Classroom 205	Door Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	2	205A	Large Office inside Classroom 205	Window Frame	Metal	Grey	None	0	0	Negative	N/A	
1	2	205A	Large Office inside Classroom 205	Column	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207	Classroom 207	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207	Classroom 207	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207	Classroom 207	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207	Classroom 207	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207	Classroom 207	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207	Classroom 207	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207	Classroom 207	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	207	Classroom 207	Door Frame W3	Metal	Grey	None	0	0	Negative	N/A	
1	2	207	Classroom 207	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	207	Classroom 207	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	207	Classroom 207	Convactor	Metal	Grey	None	0	0.06	Negative	N/A	
1	2	207	Classroom 207	Column	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207A	Front Storage Area	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207A	Front Storage Area	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207A	Front Storage Area	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207A	Front Storage Area	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207A	Front Storage Area	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	207A	Front Storage Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207A	Front Storage Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207A	Front Storage Area	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	207A	Front Storage Area	Window Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	2	207A	Front Storage Area	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207B	Classroom 207 Tech/Equipment Area	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207B	Classroom 207 Tech/Equipment Area	W2	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	207B	Classroom 207 Tech/Equipment Area	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207B	Classroom 207 Tech/Equipment Area	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207B	Classroom 207 Tech/Equipment Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Window Frame W2	Metal	Grey	None	0	0	Negative	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Door Frame W3	Metal	Grey	None	0	0	Negative	N/A	
1	2	207B	Classroom 207 Tech/Equipment Area	Convactor	Metal	Grey	None	0	0.08	Negative	N/A	
1	2	207C	Tech Area Closet inside Classroom 207	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207C	Tech Area Closet inside Classroom 207	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	207C	Tech Area Closet inside Classroom 207	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207C	Tech Area Closet inside Classroom 207	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207C	Tech Area Closet inside Classroom 207	W4	CMU	Grey	None	0	0.06	Negative	Positive	Confirmed in Donesafe-SRT
1	2	207C	Tech Area Closet inside Classroom 207	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207C	Tech Area Closet inside Classroom 207	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	207C	Tech Area Closet inside Classroom 207	Door Frame	Metal	Grey	None	0	0	Negative	N/A	
1	2	207C	Tech Area Closet inside Classroom 207	Convactor	Metal	Grey	None	0	0.03	Negative	N/A	
1	2	209	Classroom 209	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	209	Classroom 209	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	209	Classroom 209	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	209	Classroom 209	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	209	Classroom 209	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	209	Classroom 209	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	209	Classroom 209	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	209	Classroom 209	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	209	Classroom 209	Window Frame W3	Metal	Grey	None	0	0	Negative	N/A	
1	2	209	Classroom 209	Window Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	209A	Classroom 209 Closet	W1	CMU	Grey	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	2	209A	Classroom 209 Closet	W2	CMU	Grey	None	0	0.03	Negative	Positive	Confirmed in Donesafe-SRT
1	2	209A	Classroom 209 Closet	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	209A	Classroom 209 Closet	W4	CMU	Grey	None	0	0.05	Negative	Positive	Confirmed in Donesafe-SRT
1	2	209A	Classroom 209 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	209A	Classroom 209 Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	209A	Classroom 209 Closet	Door Frame W1	Metal	Grey	None	0	0.01	Negative	N/A	
1	2	213	Storage Room 213	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	213	Storage Room 213	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	213	Storage Room 213	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	213	Storage Room 213	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	213	Storage Room 213	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	213	Storage Room 213	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	213	Storage Room 213	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	
1	2	213	Storage Room 213	Air Duct	Metal	Grey	None	0	0.06	Negative	N/A	
1	2	215	Storage Room 215 in Art Room	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	215	Storage Room 215 in Art Room	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	215	Storage Room 215 in Art Room	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	215	Storage Room 215 in Art Room	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	215	Storage Room 215 in Art Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	215	Storage Room 215 in Art Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	215	Storage Room 215 in Art Room	Door Frame W1	Metal	Grey	None	0	0.09	Negative	N/A	
1	2	216	Art Classroom 216	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	216	Art Classroom 216	W1	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216	Art Classroom 216	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216	Art Classroom 216	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216	Art Classroom 216	W4	CMU	Green	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216	Art Classroom 216	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	216	Art Classroom 216	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216	Art Classroom 216	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216	Art Classroom 216	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	216	Art Classroom 216	Convactor	Metal	Grey	None	0	0.03	Negative	N/A	Limited Access
1	2	216	Art Classroom 216	Column	Concrete	Grey	None	0	0	Negative	N/A	
1	2	216A	Art Room Storage near Windows	W1	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216A	Art Room Storage near Windows	W2	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216A	Art Room Storage near Windows	W3	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216A	Art Room Storage near Windows	W4	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216A	Art Room Storage near Windows	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216A	Art Room Storage near Windows	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216A	Art Room Storage near Windows	Door Frame W1	Metal	Grey	None	0	0.05	Negative	N/A	
1	2	216A	Art Room Storage near Windows	Duct W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	216A	Art Room Storage near Windows	Duct W2	Metal	Grey	None	0	0.01	Negative	N/A	
1	2	216B	Storage near Art Classroom Entry on Right	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216B	Storage near Art Classroom Entry on Right	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216B	Storage near Art Classroom Entry on Right	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216B	Storage near Art Classroom Entry on Right	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216B	Storage near Art Classroom Entry on Right	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216B	Storage near Art Classroom Entry on Right	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216B	Storage near Art Classroom Entry on Right	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	216C	Storage next to Art Office	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	216C	Storage next to Art Office	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216C	Storage next to Art Office	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216C	Storage next to Art Office	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216C	Storage next to Art Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216C	Storage next to Art Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216C	Storage next to Art Office	Door Frame W1	Metal	Grey	None	0	0.06	Negative	N/A	
1	2	216D	Office in Art Classroom	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216D	Office in Art Classroom	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216D	Office in Art Classroom	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216D	Office in Art Classroom	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216D	Office in Art Classroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216D	Office in Art Classroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216D	Office in Art Classroom	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	2	216E	Art Room Storage in Rear	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216E	Art Room Storage in Rear	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216E	Art Room Storage in Rear	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216E	Art Room Storage in Rear	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	216E	Art Room Storage in Rear	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216E	Art Room Storage in Rear	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216E	Art Room Storage in Rear	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	216F	Art Storage Room found inside Rear Storage Room	W1	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216F	Art Storage Room found inside Rear Storage Room	W2	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216F	Art Storage Room found inside Rear Storage Room	W3	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216F	Art Storage Room found inside Rear Storage Room	W4	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	216F	Art Storage Room found inside Rear Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216F	Art Storage Room found inside Rear Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	216F	Art Storage Room found inside Rear Storage Room	Door Frame W1	Metal	Grey	None	0	0.03	Negative	N/A	Limited Access
1	2	216F	Art Storage Room found inside Rear Storage Room	Duct W2	Metal	Grey	None	0	0.02	Negative	N/A	Limited Access
1	2	218A	AFJROTC Instructor's Office	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218A	AFJROTC Instructor's Office	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218A	AFJROTC Instructor's Office	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218A	AFJROTC Instructor's Office	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	218A	AFJROTC Instructor's Office	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218A	AFJROTC Instructor's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218A	AFJROTC Instructor's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218A	AFJROTC Instructor's Office	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	218A	AFJROTC Instructor's Office	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	218A	AFJROTC Instructor's Office	Pipe	Metal	Grey	None	0	0	Negative	N/A	
1	2	218B	AFJROTC Right Office	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	218B	AFJROTC Right Office	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218B	AFJROTC Right Office	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218B	AFJROTC Right Office	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218B	AFJROTC Right Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218B	AFJROTC Right Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218B	AFJROTC Right Office	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	218B	AFJROTC Right Office	Window Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	218C	Storage in AFJROTC Instructor's Office	W1	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218C	Storage in AFJROTC Instructor's Office	W2	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218C	Storage in AFJROTC Instructor's Office	W3	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218C	Storage in AFJROTC Instructor's Office	W4	Sheetrock	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	218C	Storage in AFJROTC Instructor's Office	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218C	Storage in AFJROTC Instructor's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	218C	Storage in AFJROTC Instructor's Office	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	220	ROTC Clothing Storage Area	W1	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	220	ROTC Clothing Storage Area	W2	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	220	ROTC Clothing Storage Area	W3	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	220	ROTC Clothing Storage Area	W4	CMU	Grey	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	220	ROTC Clothing Storage Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	220	ROTC Clothing Storage Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	220	ROTC Clothing Storage Area	Door Frame W1	Metal	Grey	None	0	0.02	Negative	N/A	
1	2	221	Girl's Restroom (ROTC) across from 204	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	221	Girl's Restroom (ROTC) across from 204	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	221	Girl's Restroom (ROTC) across from 204	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	221	Girl's Restroom (ROTC) across from 204	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	221	Girl's Restroom (ROTC) across from 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	221	Girl's Restroom (ROTC) across from 204	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	221	Girl's Restroom (ROTC) across from 204	Door Frame W1	Metal	Grey	None	0	0.09	Negative	N/A	
1	2	221	Girl's Restroom (ROTC) across from 204	Convector	Metal	Brown	None	0	0.08	Negative	N/A	
1	2	222	Custodial Closet across from Classroom 204	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	222	Custodial Closet across from Classroom 204	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	222	Custodial Closet across from Classroom 204	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	222	Custodial Closet across from Classroom 204	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	222	Custodial Closet across from Classroom 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	222	Custodial Closet across from Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	222	Custodial Closet across from Classroom 204	Door Frame W1	Metal	Blue	None	0	0.02	Negative	N/A	
1	2	222	Custodial Closet across from Classroom 204	Pipe	Metal	Grey	None	0	0.09	Negative	N/A	
1	2	222	Custodial Closet across from Classroom 204	Shelves	Wood	Tan	None	0	0.03	Negative	N/A	
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	W1	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	W2	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	W3	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	W4	CMU	Grey	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	Door Frame W1	Metal	Blue	None	0	0.01	Negative	N/A	
1	2	223	Women's Faculty Restroom (ROTC) by Classroom 204	Convactor	Metal	Brown	None	0	0	Negative	N/A	
1	2	224	Men's Restroom (ROTC) by room 204	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	224	Men's Restroom (ROTC) by room 204	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	224	Men's Restroom (ROTC) by room 204	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	224	Men's Restroom (ROTC) by room 204	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	224	Men's Restroom (ROTC) by room 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	224	Men's Restroom (ROTC) by room 204	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	224	Men's Restroom (ROTC) by room 204	Door Frame	Metal	Blue	None	0	0.02	Negative	N/A	
1	2	224	Men's Restroom (ROTC) by room 204	Convactor W3	Metal	Blue	None	0	0	Negative	N/A	
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	224PC	Pipe Chase between Men's & Women's Faculty Restrooms by 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	225	Boy's Restroom (ROTC) by Room 204	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	225	Boy's Restroom (ROTC) by Room 204	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	225	Boy's Restroom (ROTC) by Room 204	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	225	Boy's Restroom (ROTC) by Room 204	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	225	Boy's Restroom (ROTC) by Room 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	225	Boy's Restroom (ROTC) by Room 204	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	225	Boy's Restroom (ROTC) by Room 204	Door Frame W1	Metal	Blue	None	0	0.03	Negative	N/A	
1	2	225	Boy's Restroom (ROTC) by Room 204	Convactor W3	Metal	Grey	None	0	0.01	Negative	N/A	
1	2	226	Storage Room 226	W1	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	226	Storage Room 226	W2	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	226	Storage Room 226	W3	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	226	Storage Room 226	W4	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	226	Storage Room 226	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	226	Storage Room 226	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	226	Storage Room 226	Door Frame W1	Metal	Grey	None	0	0.04	Negative	N/A	
1	2	227	Classroom 227	W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	227	Classroom 227	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	227	Classroom 227	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	227	Classroom 227	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	227	Classroom 227	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	227	Classroom 227	W4	Metal	Tan	None	0	0.06	Negative	N/A	
1	2	227	Classroom 227	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	227	Classroom 227	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	227	Classroom 227	Door Frame W4	Metal	Brown	None	0	0	Negative	N/A	
1	2	227	Classroom 227	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	227B	Classroom 227 Closet	W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	227B	Classroom 227 Closet	W2	Metal	Brown	None	0	0	Negative	N/A	
1	2	227B	Classroom 227 Closet	W3	Metal	Brown	None	0	0	Negative	N/A	
1	2	227B	Classroom 227 Closet	W4	Metal	Brown	None	0	0	Negative	N/A	
1	2	227B	Classroom 227 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	227B	Classroom 227 Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	227B	Classroom 227 Closet	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	231	Office 231	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	231	Office 231	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	231	Office 231	W3	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	231	Office 231	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	2	231	Office 231	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	231	Office 231	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	228	Classroom 228	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	228	Classroom 228	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	228	Classroom 228	W3	Metal	Brown	None	0	0	Negative	N/A	
1	2	228	Classroom 228	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	228	Classroom 228	W4	CMU	Blue	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	228	Classroom 228	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	228	Classroom 228	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	228	Classroom 228	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	228	Classroom 228	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	228	Classroom 228	Cabinet	Metal	Pink	None	0	0	Negative	N/A	
1	2	229	Classroom 229	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229	Classroom 229	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	229	Classroom 229	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229	Classroom 229	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229	Classroom 229	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	229	Classroom 229	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	229	Classroom 229	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	229	Classroom 229	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	229	Classroom 229	Convactor	Metal	Blue	N/A	N/A	0	Negative	N/A	
1	2	229AB	Classroom 230	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	229AB	Classroom 230	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229AB	Classroom 230	W3	Metal	Tan	None	0	0.05	Negative	N/A	Sampling not required
1	2	229AB	Classroom 230	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229AB	Classroom 230	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	229AB	Classroom 230	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	229AB	Classroom 230	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	229AB	Classroom 230	Door Frame W2	Metal	Brown	None	0	0	Negative	N/A	
1	2	229AB	Classroom 230	Door Frame W4	Metal	Brown	None	0	0	Negative	N/A	
1	2	229D	Classroom 229 Closet	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229D	Classroom 229 Closet	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229D	Classroom 229 Closet	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229D	Classroom 229 Closet	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	229D	Classroom 229 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	229D	Classroom 229 Closet	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	230	Office 232B	W1	Sheetrock	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	230	Office 232B	W1	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	2	230	Office 232B	W2	Metal	Brown	None	0	0	Negative	N/A	
1	2	230	Office 232B	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	230	Office 232B	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	230	Office 232B	W4	Sheetrock	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	230	Office 232B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	230	Office 232B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	230	Office 232B	Door Frame W1	Metal	Brown	N/A	N/A	0	Negative	N/A	
1	2	231A	Room 230 Closet	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	231A	Room 230 Closet	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	231A	Room 230 Closet	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	231A	Room 230 Closet	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	231A	Room 230 Closet	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	231A	Room 230 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	231A	Room 230 Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232	Classroom 232	W1	Sheetrock	Yellow	None	0	0	Negative	N/A	Sampling not required
1	2	232	Classroom 232	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232	Classroom 232	W3	CMU	Tan	None	0	0.01	Negative	Positive	Confirmed in Donesafe-SRT
1	2	232	Classroom 232	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232	Classroom 232	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	232	Classroom 232	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232	Classroom 232	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232A	Classroom 235B	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	232A	Classroom 235B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	232A	Classroom 235B	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	232A	Classroom 235B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	232A	Classroom 235B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	234	Classroom 234	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	234	Classroom 234	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	234	Classroom 234	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	234	Classroom 234	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	234	Classroom 234	Door Casing	Metal	Brown	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	234	Classroom 234	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	234	Classroom 234	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	234	Classroom 234	Door Frame W3	Metal	Brown	None	0	0	Negative	N/A	
1	2	235	Textbook Storage Room	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	235	Textbook Storage Room	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	235	Textbook Storage Room	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	235	Textbook Storage Room	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	235	Textbook Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	235	Textbook Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	235	Textbook Storage Room	Door Frame	Metal	Brown	None	0	0.02	Negative	N/A	
1	2	235	Textbook Storage Room	Convector	Metal	Grey	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	236	Classroom 236	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	236	Classroom 236	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	236	Classroom 236	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	236	Classroom 236	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	236	Classroom 236	Door Casing	Metal	Brown	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	236	Classroom 236	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	236	Classroom 236	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	236	Classroom 236	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	236	Classroom 236	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	236	Classroom 236	Door Frame W4	Metal	Brown	None	0	0	Negative	N/A	
1	2	236	Classroom 236	Cabinet	Metal	Pink	None	0	0.01	Negative	N/A	
1	2	236A	Classroom 236 Closet	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	236A	Classroom 236 Closet	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	236A	Classroom 236 Closet	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	236A	Classroom 236 Closet	W3	CMU	Tan	none	0	0.03	Negative	Positive	Confirmed in Donesafe-SRT
1	2	236A	Classroom 236 Closet	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	236A	Classroom 236 Closet	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	236A	Classroom 236 Closet	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	236A	Classroom 236 Closet	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	236A	Classroom 236 Closet	Door Frame W4	Metal	Grey	None	0	0	Negative	N/A	
1	2	263SR	Storage Room 263 by Classroom 265	W1	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	263SR	Storage Room 263 by Classroom 265	W2	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	263SR	Storage Room 263 by Classroom 265	W3	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	263SR	Storage Room 263 by Classroom 265	W4	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	263SR	Storage Room 263 by Classroom 265	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	263SR	Storage Room 263 by Classroom 265	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	263SR	Storage Room 263 by Classroom 265	Door Frame	Metal	Grey	None	0	0	Negative	N/A	
1	2	263SR	Storage Room 263 by Classroom 265	Convector	Metal	Grey	Friction	1	0	Negative	Assumed	Sampling not required not LBP

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	237A	Girl's Restroom outside Classroom 265	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	237A	Girl's Restroom outside Classroom 265	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	237A	Girl's Restroom outside Classroom 265	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	237A	Girl's Restroom outside Classroom 265	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	237A	Girl's Restroom outside Classroom 265	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	237A	Girl's Restroom outside Classroom 265	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	237A	Girl's Restroom outside Classroom 265	Door Frame W1	Metal	Grey	Friction	1	0.09	Negative	Assumed	Sampling not required not LBP
1	2	237A	Girl's Restroom outside Classroom 265	Pipe Chase Door Frame	Metal	Grey	Friction	1	0.07	Negative	Assumed	Sampling not required not LBP
1	2	237A	Girl's Restroom outside Classroom 265	Convactor	Metal	Grey	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	237A-PC	Pipe Chase in Girls Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	237A-PC	Pipe Chase in Girls Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	237A-PC	Pipe Chase in Girls Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	237A-PC	Pipe Chase in Girls Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	237A-PC	Pipe Chase in Girls Restroom	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	237A-PC	Pipe Chase in Girls Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238	Classroom 238	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	238	Classroom 238	W2	CMU	Tan	None	0	0.02	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238	Classroom 238	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238	Classroom 238	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	238	Classroom 238	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238	Classroom 238	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238	Classroom 238	Door Frame W1	Metal	Pink	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	238	Classroom 238	Door Frame W3	Metal	Pink	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	238	Classroom 238	Convactor	Metal	Pink	Friction	20	0	Negative	Assumed	Sampling not required not LBP
1	2	238	Classroom 238	Cabinet	Metal	Blue	None	0	0	Negative	N/A	
1	2	238	Classroom 238	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	238A	Classroom 238 Storage	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	238A	Classroom 238 Storage	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	238A	Classroom 238 Storage	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238A	Classroom 238 Storage	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	238A	Classroom 238 Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238A	Classroom 238 Storage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238A	Classroom 238 Storage	Door Frame W1	Metal	Pink	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	238BR	Girls Restroom outside classroom 249	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238BR	Girls Restroom outside classroom 249	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238BR	Girls Restroom outside classroom 249	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238BR	Girls Restroom outside classroom 249	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	238BR	Girls Restroom outside classroom 249	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238BR	Girls Restroom outside classroom 249	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	238BR	Girls Restroom outside classroom 249	Door Frame W1	Metal	Grey	N/A	N/A	0.02	Negative	N/A	
1	2	238BR	Girls Restroom outside classroom 249	Convactor	Metal	Grey	N/A	N/A	0	Negative	N/A	
1	2	239	Men's Restroom outside Classroom 253	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	239	Men's Restroom outside Classroom 253	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	239	Men's Restroom outside Classroom 253	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	239	Men's Restroom outside Classroom 253	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	239	Men's Restroom outside Classroom 253	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	239	Men's Restroom outside Classroom 253	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	239	Men's Restroom outside Classroom 253	Door Frame	Metal	Grey	N/A	N/A	0	Negative	N/A	
1	2	239	Men's Restroom outside Classroom 253	Convactor	Metal	Blue	N/A	N/A	0	Negative	N/A	
1	2	240	Custodian Storage Room outside room 253	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	240	Custodian Storage Room outside room 253	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	240	Custodian Storage Room outside room 253	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	240	Custodian Storage Room outside room 253	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	240	Custodian Storage Room outside room 253	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	240	Custodian Storage Room outside room 253	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	240	Custodian Storage Room outside room 253	Door Frame	Metal	Grey	Friction	2	0.11	Negative	Assumed	Sampling not required not LBP
1	2	240	Custodian Storage Room outside room 253	Shelves	Wood	Tan	None	0	0	Negative	N/A	
1	2	241	Boys Restroom outside Classroom 253	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	241	Boys Restroom outside Classroom 253	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	241	Boys Restroom outside Classroom 253	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	241	Boys Restroom outside Classroom 253	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	241	Boys Restroom outside Classroom 253	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	241	Boys Restroom outside Classroom 253	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	241	Boys Restroom outside Classroom 253	Door Frame	Metal	Grey	N/A	N/A	0.01	Negative	N/A	
1	2	241	Boys Restroom outside Classroom 253	Convactor	Metal	Grey	N/A	N/A	0	Negative	N/A	
1	2	242	Women's Restroom outdid Classroom 263	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	242	Women's Restroom outdid Classroom 263	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	242	Women's Restroom outdid Classroom 263	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	242	Women's Restroom outdid Classroom 263	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	242	Women's Restroom outdid Classroom 263	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	242	Women's Restroom outdid Classroom 263	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	242	Women's Restroom outdid Classroom 263	Door Frame W1	Metal	Grey	N/A	N/A	0.07	Negative	N/A	
1	2	242	Women's Restroom outdid Classroom 263	Convactor	Metal	Blue	N/A	N/A	0	Negative	N/A	
1	2	243	Boy's Restroom outside Classroom 265	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	243	Boy's Restroom outside Classroom 265	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	243	Boy's Restroom outside Classroom 265	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	243	Boy's Restroom outside Classroom 265	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	243	Boy's Restroom outside Classroom 265	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	243	Boy's Restroom outside Classroom 265	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	243	Boy's Restroom outside Classroom 265	Door Frame W1	Metal	Grey	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	243	Boy's Restroom outside Classroom 265	Convactor	Metal	Blue	Friction	1	0.03	Negative	Assumed	Sampling not required not LBP
1	2	244D	Classroom 263	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D	Classroom 263	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244D	Classroom 263	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D	Classroom 263	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244D	Classroom 263	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D	Classroom 263	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	244D	Classroom 263	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	244D	Classroom 263	Door Frame W1	Metal	Blue	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	244D	Classroom 263	Door Frame W4	Metal	Blue	Friction	1	0	Negative	Assumed	Sampling not required not LBP
1	2	244D	Classroom 263	Pipe	Metal	Tan	Flaking	2	0	Negative	Assumed	Sampling not required not LBP
1	2	244D	Classroom 263	Convactor	Metal	Blue	Friction	20	0.14	Negative	Assumed	Sampling not required not LBP
1	2	244D	Classroom 263	Cabinet	Metal	Blue	None	0	2	Positive	N/A	
1	2	244D-C	Closet Inside Classroom 263	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D-C	Closet Inside Classroom 263	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D-C	Closet Inside Classroom 263	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D-C	Closet Inside Classroom 263	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244D-C	Closet Inside Classroom 263	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	244D-C	Closet Inside Classroom 263	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	244D-C	Closet Inside Classroom 263	Door Frame W1	Metal	Blue	N/A	N/A	0	Negative	N/A	
1	2	245	Classroom 245	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245	Classroom 245	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245	Classroom 245	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245	Classroom 245	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	245	Classroom 245	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245	Classroom 245	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245	Classroom 245	Door Frame W1	Metal	Pink	N/A	N/A	0	Negative	N/A	
1	2	245	Classroom 245	Cabinet W4	Metal	Pink	None	0	0.01	Negative	N/A	
1	2	245	Classroom 245	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	245A	Classroom 264	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245A	Classroom 264	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245A	Classroom 264	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	245A	Classroom 264	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245A	Classroom 264	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245A	Classroom 264	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245A	Classroom 264	Door Frame W1	Metal	Blue	N/A	N/A	0	Negative	N/A	
1	2	245A	Classroom 264	Convactor	Metal	Blue	None	0	0.09	Negative	N/A	
1	2	245A	Classroom 264	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	245C	Classroom 265	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245C	Classroom 265	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	245C	Classroom 265	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245C	Classroom 265	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	245C	Classroom 265	W4	Metal	Tan	None	0	0.017	Negative	N/A	Sampling not required
1	2	245C	Classroom 265	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245C	Classroom 265	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	245C	Classroom 265	Door Frame	Metal	Blue	None	0	0	Negative	N/A	
1	2	247	Classroom 246/247	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	247	Classroom 246/247	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	247	Classroom 246/247	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	247	Classroom 246/247	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	247	Classroom 246/247	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	247	Classroom 246/247	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	247	Classroom 246/247	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	249	Classroom 249	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	249	Classroom 249	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	249	Classroom 249	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	249	Classroom 249	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	249	Classroom 249	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	249	Classroom 249	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	249	Classroom 249	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	249	Classroom 249	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	249	Classroom 249	Door Frame W2	Metal	Brown	None	0	0.01	Negative	N/A	
1	2	250	Classroom 250	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250	Classroom 250	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250	Classroom 250	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	250	Classroom 250	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250	Classroom 250	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250	Classroom 250	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250	Classroom 250	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	250	Classroom 250	Door Frame W2	Metal	Brown	None	0	0.01	Negative	N/A	
1	2	250	Classroom 250	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	250A	Office 249B	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250A	Office 249B	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250A	Office 249B	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250A	Office 249B	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250A	Office 249B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250A	Office 249B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250A	Office 249B	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	250B	Office 249A	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250B	Office 249A	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250B	Office 249A	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250B	Office 249A	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	250B	Office 249A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250B	Office 249A	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	250B	Office 249A	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	253	Classroom 253	W1	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	253	Classroom 253	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	253	Classroom 253	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	253	Classroom 253	W3	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Confirmed in Donesafe-SRT
1	2	253	Classroom 253	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	253	Classroom 253	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	253	Classroom 253	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	253	Classroom 253	Cabinet	Metal	Blue	None	0	0.01	Negative	N/A	
1	2	253	Classroom 253	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	253	Classroom 253	Door Frame W4	Metal	Brown	None	0	0	Negative	N/A	

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	253	Classroom 253	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	257	Classroom 257	W1	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	257	Classroom 257	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	257	Classroom 257	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	257	Classroom 257	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	257	Classroom 257	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	257	Classroom 257	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	257	Classroom 257	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	257	Classroom 257	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	257	Classroom 257	Cabinet	Metal	Blue	None	0	0	Negative	N/A	
1	2	258	Classroom 258	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	258	Classroom 258	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	258	Classroom 258	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	258	Classroom 258	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	258	Classroom 258	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	258	Classroom 258	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	258	Classroom 258	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	258	Classroom 258	Cabinet	Metal	Blue	None	0	0	Negative	N/A	
1	2	259	Classroom 259	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	259	Classroom 259	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	259	Classroom 259	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	259	Classroom 259	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	259	Classroom 259	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	259	Classroom 259	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	259	Classroom 259	Column	Concrete	Tan	None	0	0	Negative	N/A	
1	2	259A	Storage 259A	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259A	Storage 259A	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259A	Storage 259A	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259A	Storage 259A	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259A	Storage 259A	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	259A	Storage 259A	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	259A	Storage 259A	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	
1	2	259B	Office 259B	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259B	Office 259B	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259B	Office 259B	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259B	Office 259B	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	259B	Office 259B	Ceiling	Metal	Unpainted	None	0	N/A	N/A	N/A	
1	2	259B	Office 259B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	259B	Office 259B	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	244C	Teacher's Lounge - 260	Column	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244C	Teacher's Lounge - 260	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244C	Teacher's Lounge - 260	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244C	Teacher's Lounge - 260	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244C	Teacher's Lounge - 260	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	244C	Teacher's Lounge - 260	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244C	Teacher's Lounge - 260	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244C	Teacher's Lounge - 260	Door Frame W1	Metal	Grey	None	0	0	Negative	N/A	Sampling not required
1	2	260A	Chair Storage Room	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260A	Chair Storage Room	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260A	Chair Storage Room	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260A	Chair Storage Room	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260A	Chair Storage Room	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260A	Chair Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260A	Chair Storage Room	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	260B	Office 260B	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260B	Office 260B	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260B	Office 260B	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	260B	Office 260B	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260B	Office 260B	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260B	Office 260B	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260B	Office 260B	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	260B	Office 260B	Convactor	Metal	Blue	None	0	0.15	Negative	N/A	
1	2	260C	Office 260C	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260C	Office 260C	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	260C	Office 260C	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	260C	Office 260C	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260C	Office 260C	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260C	Office 260C	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	260C	Office 260C	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	260C	Office 260C	Convactor	Metal	Blue	None	0	0.1	Negative	N/A	
1	2	244B-2	Classroom 261	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244B-2	Classroom 261	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244B-2	Classroom 261	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244B-2	Classroom 261	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244B-2	Classroom 261	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244B-2	Classroom 261	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244B-2	Classroom 261	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	244B-2	Classroom 261	Convactor	Metal	Blue	None	0	0.21	Negative	N/A	
1	2	244A	Classroom 261 Storage	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244A	Classroom 261 Storage	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	244A	Classroom 261 Storage	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244A	Classroom 261 Storage	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	244A	Classroom 261 Storage	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244A	Classroom 261 Storage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	244A	Classroom 261 Storage	Door Frame W1	Metal	Blue	None	0	0	Negative	N/A	Sampling not required
1	2	244A	Classroom 261 Storage	Convactor	Metal	Blue	None	0	0.08	Negative	N/A	
1	2	262A	Storage Closet 262A	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	262A	Storage Closet 262A	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	262A	Storage Closet 262A	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	262A	Storage Closet 262A	W4	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Entered by ST
1	2	262A	Storage Closet 262A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	262A	Storage Closet 262A	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	262A	Storage Closet 262A	Door Frame	Metal	Brown	None	0	0	Negative	N/A	
1	2	265A	Storage Room 265A	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	265A	Storage Room 265A	W2	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	265A	Storage Room 265A	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	265A	Storage Room 265A	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	265A	Storage Room 265A	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	265A	Storage Room 265A	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	265A	Storage Room 265A	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	
1	2	H21	Hallway between Classroom 244-227	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H21	Hallway between Classroom 244-227	W2	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H21	Hallway between Classroom 244-227	W3	Sheetrock	Tan	None	0	0	Negative	N/A	
1	2	H21	Hallway between Classroom 244-227	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H21	Hallway between Classroom 244-227	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H21	Hallway between Classroom 244-227	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H22	Hallway between Stairwells 3 and 4	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H22	Hallway between Stairwells 3 and 4	W2	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H22	Hallway between Stairwells 3 and 4	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H22	Hallway between Stairwells 3 and 4	W4	Sheetrock	Tan	None	0	0.1	Negative	N/A	Sampling not required
1	2	H22	Hallway between Stairwells 3 and 4	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22	Hallway between Stairwells 3 and 4	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H22	Hallway between Stairwells 3 and 4	Pipe	Metal	Tan	None	0	0	Negative	N/A	
1	2	H22	Hallway between Classroom 232 & 259	W1	CMU	Tan	None	0	0	Negative	Positive	(Formerly H20)
1	2	H22	Hallway between Classroom 232 & 259	W3	Sheetrock	Tan	None	0	0	Negative	N/A	(Formerly H20)
1	2	H22	Hallway between Classroom 232 & 259	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22	Hallway between Classroom 232 & 259	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	(Formerly H20)
1	2	H22	Hallway between Classroom 232 & 259	Lockers	Metal	Blue	None	0	0.4	Negative	N/A	(Formerly H20)
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	W2	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Entered by ST
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	W4	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22-C1	Textbook Storage Closet Outside Classroom 263	Door Frame	Metal	Brown	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C2	Textbook Storage outside Classroom 265	W1	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C2	Textbook Storage outside Classroom 265	W2	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Entered by ST
1	2	H22-C2	Textbook Storage outside Classroom 265	W3	Sheetrock	Tan	None	0	0	Negative	N/A	Sampling not required
1	2	H22-C2	Textbook Storage outside Classroom 265	W4	CMU	Tan	None	0	0	Negative	Positive	Limited Access/Entered by ST
1	2	H22-C2	Textbook Storage outside Classroom 265	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22-C2	Textbook Storage outside Classroom 265	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H22-C2	Textbook Storage outside Classroom 265	Door Frame W1	Metal	Brown	None	0	0	Negative	N/A	Sampling not required

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	H23	Hallway between Classroom 247 & 253	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H23	Hallway between Classroom 247 & 253	W3	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H23	Hallway between Classroom 247 & 253	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H23	Hallway between Classroom 247 & 253	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H23	Hallway between Classroom 247 & 253	Electrical Panel	Metal	Grey	None	0	0	Negative	N/A	
1	2	H23	Hallway between Classroom 247 & 253	Lockers	Metal	Blue	None	0	0.4	Negative	N/A	
1	2	H24	Hallway between Classroom 237A-264	W2	CMU	Tan	None	0	0.5	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H24	Hallway between Classroom 237A-264	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H24	Hallway between Classroom 237A-264	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H24	Hallway between Classroom 237A-264	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H24	Hallway between Classroom 237A-264	Lockers	Metal	Blue	None	0	0.5	Negative	N/A	
1	2	H24A	Hallway at Classroom 264	W2	CMU	Tan	None	0	0.5	Negative	Positive	Included in H22 Entered by ST
1	2	H24A	Hallway at Classroom 264	W4	CMU	Tan	None	0	0.1	Negative	Positive	Included in H22/Entered by ST
1	2	H24B	Hallway between Classroom 249-250	W2	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H24B	Hallway between Classroom 249-250	W3	Sheetrock	Tan	None	0	0	Negative	N/A	
1	2	H24B	Hallway between Classroom 249-250	W4	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H24B	Hallway between Classroom 249-250	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H24B	Hallway between Classroom 249-250	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H25	Hallway between Classroom 230 - 231	W3	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H25	Hallway between Classroom 230 - 231	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H25	Hallway between Classroom 230 - 231	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H25	Hallway between Classroom 230 - 231	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H26	Hallway between S26 and Classroom 204	W1	Sheetrock	White	None	0	0.1	Negative	N/A	
1	2	H26	Hallway between S26 and Classroom 204	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H26	Hallway between S26 and Classroom 204	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H26	Hallway between S26 and Classroom 204	W4	Sheetrock	White	None	0	0.1	Negative	N/A	
1	2	H26	Hallway between S26 and Classroom 204	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H26	Hallway between S26 and Classroom 204	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H26	Hallway between S26 and Classroom 204	Electrical Panel	Metal	Tan	None	0	0.1	Negative	N/A	
1	2	H27	Hallway from Classroom 205 to Storage Room 220	W1	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H27	Hallway from Classroom 205 to Storage Room 220	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H27	Hallway from Classroom 205 to Storage Room 220	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H27	Hallway from Classroom 205 to Storage Room 220	W3	Sheetrock	Blue	None	0	0	Negative	N/A	
1	2	H27	Hallway from Classroom 205 to Storage Room 220	W4	Sheetrock	Blue	None	0	0	Negative	N/A	
1	2	H27	Hallway from Classroom 205 to Storage Room 220	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H27	Hallway from Classroom 205 to Storage Room 220	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H28	Hallway from Art Room 216 to Storage 226	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H28	Hallway from Art Room 216 to Storage 226	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	2	H28	Hallway from Art Room 216 to Storage 226	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H28	Hallway from Art Room 216 to Storage 226	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H28	Hallway from Art Room 216 to Storage 226	Lockers	Metal	Grey	None	0	1.2	Positive	N/A	
1	2	H29	Hallway from Storage 226 to Stairwell #1	W1	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H29	Hallway from Storage 226 to Stairwell #1	W1	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H29	Hallway from Storage 226 to Stairwell #1	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	H29	Hallway from Storage 226 to Stairwell #1	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H29	Hallway from Storage 226 to Stairwell #1	W3	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H29	Hallway from Storage 226 to Stairwell #1	W4	Sheetrock	Tan	None	0	0	Negative	N/A	
1	2	H29	Hallway from Storage 226 to Stairwell #1	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H29	Hallway from Storage 226 to Stairwell #1	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	H29	Hallway from Storage 226 to Stairwell #1	Lockers	Metal	Grey	None	0	1.2	Positive	N/A	
1	2	H30	Elevator Lobby Area	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	H30	Elevator Lobby Area	W2	Sheetrock	Green	None	0	0.2	Negative	N/A	
1	2	H30	Elevator Lobby Area	W3	Sheetrock	Tan	None	0	0.1	Negative	N/A	
1	2	H30	Elevator Lobby Area	W4	Sheetrock	Green	None	0	0.1	Negative	N/A	
1	2	H30	Elevator Lobby Area	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	H30	Elevator Lobby Area	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A	N/A	
1	2	S21	Stairs next to Classroom 200	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S21	Stairs next to Classroom 200	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S21	Stairs next to Classroom 200	W3	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S21	Stairs next to Classroom 200	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S21	Stairs next to Classroom 200	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S21	Stairs next to Classroom 200	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S21	Stairs next to Classroom 200	Door Frame	Metal	Grey	None	0	0.2	Negative	N/A	
1	2	S21	Stairs next to Classroom 200	Door	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S21	Stairs next to Classroom 200	Stair Riser	Metal	Grey	None	0	0.5	Negative	N/A	
1	2	S21	Stairs next to Classroom 200	Stair Stringer	Metal	Grey	None	0	0	Negative	N/A	
1	2	S22	Stairs next to Classroom 229	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	2	S22	Stairs next to Classroom 229	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S22	Stairs next to Classroom 229	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S22	Stairs next to Classroom 229	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S22	Stairs next to Classroom 229	W4	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S22	Stairs next to Classroom 229	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S22	Stairs next to Classroom 229	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	2	S22	Stairs next to Classroom 229	Stair Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S22	Stairs next to Classroom 229	Stair Stringer	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S23	Stairwell 3 next to Classroom 262	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S23	Stairwell 3 next to Classroom 262	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S23	Stairwell 3 next to Classroom 262	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S23	Stairwell 3 next to Classroom 262	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S23	Stairwell 3 next to Classroom 262	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	2	S23	Stairwell 3 next to Classroom 262	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S23	Stairwell 3 next to Classroom 262	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	2	S23	Stairwell 3 next to Classroom 262	Door	Metal	Grey	None	0	0	Negative	N/A	
1	2	S23	Stairwell 3 next to Classroom 262	Stair Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S23	Stairwell 3 next to Classroom 262	Stair Stringer	Metal	Grey	None	0	0.2	Negative	N/A	
1	2	S23	Stairwell 3 next to Classroom 262	Baseboard	Wood	Grey	None	0	0.2	Negative	N/A	
1	2	S24	Stairwell 4 next to Classroom 257	Ceiling	Concrete	White	None	0	0	Negative	N/A	Sampling not required
1	2	S24	Stairwell 4 next to Classroom 257	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S24	Stairwell 4 next to Classroom 257	W2	CMU	Tan	None	0	0.1	Negative	Positive	Confirmed in Donesafe-SRT

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative)	Asbestos Paint sampled (positive/negative) [3]	Comments/ Description/ Notes
1	2	S24	Stairwell 4 next to Classroom 257	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S24	Stairwell 4 next to Classroom 257	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S24	Stairwell 4 next to Classroom 257	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S24	Stairwell 4 next to Classroom 257	Door Frame	Metal	Grey	None	0	0.2	Negative	N/A	
1	2	S24	Stairwell 4 next to Classroom 257	Door	Metal	Grey	None	0	0	Negative	N/A	
1	2	S24	Stairwell 4 next to Classroom 257	Stair Riser	Metal	Grey	None	0	0	Negative	N/A	
1	2	S24	Stairwell 4 next to Classroom 257	Stair Stringer	Metal	Grey	None	0	0.2	Negative	N/A	
1	2	S24	Stairwell 4 next to Classroom 257	Baseboard	Wood	Grey	None	0	0.1	Negative	N/A	
1	2	S25	Stairs next to Classroom 245	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	2	S25	Stairs next to Classroom 245	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S25	Stairs next to Classroom 245	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S25	Stairs next to Classroom 245	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S25	Stairs next to Classroom 245	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S25	Stairs next to Classroom 245	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S25	Stairs next to Classroom 245	Door Frame	Metal	Grey	None	0	0.3	Negative	N/A	
1	2	S25	Stairs next to Classroom 245	Door	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S25	Stairs next to Classroom 245	Stair Riser	Metal	Grey	None	0	0	Negative	N/A	
1	2	S25	Stairs next to Classroom 245	Stair Stringer	Metal	Grey	None	0	0.2	Negative	N/A	
1	2	S25	Stairs next to Classroom 245	Baseboard	Wood	Grey	None	0	0.2	Negative	N/A	
1	2	S26	Stairs next to Classroom 211	Ceiling	Concrete	White	None	0	0.1	Negative	N/A	Sampling not required
1	2	S26	Stairs next to Classroom 211	W1	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S26	Stairs next to Classroom 211	W2	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S26	Stairs next to Classroom 211	W3	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S26	Stairs next to Classroom 211	W4	CMU	Tan	None	0	0	Negative	Positive	Confirmed in Donesafe-SRT
1	2	S26	Stairs next to Classroom 211	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	Unpainted
1	2	S26	Stairs next to Classroom 211	Door Frame	Metal	Blue	None	0	0.2	Negative	N/A	
1	2	S26	Stairs next to Classroom 211	Door	Metal	Blue	None	0	0.1	Negative	N/A	
1	2	S26	Stairs next to Classroom 211	Stair Riser	Metal	Grey	None	0	0.1	Negative	N/A	
1	2	S26	Stairs next to Classroom 211	Stair Stringer	Metal	Grey	None	0	0.3	Negative	N/A	

[1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[3] Damaged paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.



Appendix B
Lead Safe Certificate



Philadelphia Department of Public Health Certification of School Lead Safe Status

By signing this certificate, I confirm that I have done a visual inspection of the areas where children have access, including contact surfaces where children store their equipment or materials, and confirm these areas do not have deteriorated lead-based paint. A certified risk assessor or lead dust sampling technician completed verification wipe tests in accordance with the EPA's RRP guidelines and confirms they meet the EPA's cleanliness standard. A certified risk assessor or lead dust sampling technician collected interior dust wipe samples in compliance with EPA regulations in work areas and confirms they did not contain lead contaminated dust in excess of EPA dust lead standards in Pre-K, Kindergarten, and 1st Grade classrooms as well as the restrooms, offices, cafeterias, gymnasiums, and auditoriums these children routinely occupy. This certificate is valid for 4 years from date of verification.

Swenson Arts & Technology High School

2750 Red Lion Road Spruance Street, Philadelphia, PA

School Name

Street Address

Acer Associates, LLC

Kristen Masotes PA#058358

Certifying Company (print)

Risk Assessor, Lead Inspector PA Lic. #, EPA Firm Certification or Lead Dust Sampling Technician Certification #

Kristen Masotes

November 14, 2023

Inspector/Risk Assessor or Dust Wipe Sampling Technician Name (Signature)

Date of Verification

Jennifer Donovan 215-400-5719 jdonovan2@philasd.org

School Official Name, Telephone and E-mail Address

Please note: A visual inspection of the areas listed above has been completed by a certified risk assessor and no damage to Lead Based Painted surfaces was observed. Therefore, no verification wipe samples were completed. This school will be reassessed within 4 years of this certification.