

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C101	Girl's Gym	Beam	Metal	White	None	0	No Access	No Access
1	ML	C101	Girl's Gym	Duct	Metal	White	None	0	No Access	No Access
1	ML	C102	Boy's Gym	Beam	Metal	White	None	0	No Access	No Access
1	ML	C102	Boy's Gym	Duct	Metal	White	None	0	No Access	No Access
1	LL	B1	Classroom B-1	W1	CMU	White	None	0	0	Negative
1	LL	B1	Classroom B-1	W2	CMU	White	Flaking	25	0	Negative
1	LL	B1	Classroom B-1	W3	CMU	White	None	0	0	Negative
1	LL	B1	Classroom B-1	W4	CMU	White	None	0	0	Negative
1	LL	B1	Classroom B-1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B1	Classroom B-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B1	Classroom B-1	Door Casing	Metal	Blue	Friction	2	0.1	Negative
1	LL	B1	Classroom B-1	Duct	Metal	Blue	None	0	0.3	Negative
1	LL	B10	B-10 Storage Room next to Girl's Restroom	W1	CMU	White	Flaking	5	0	Negative
1	LL	B10	B-10 Storage Room next to Girl's Restroom	W2	CMU	White	Flaking	25	0	Negative
1	LL	B10	B-10 Storage Room next to Girl's Restroom	W3	CMU	White	Flaking	25	0	Negative
1	LL	B10	B-10 Storage Room next to Girl's Restroom	W4	CMU	White	Flaking	25	0	Negative
1	LL	B10	B-10 Storage Room next to Girl's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B10	B-10 Storage Room next to Girl's Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B10	B-10 Storage Room next to Girl's Restroom	Door Casing	Metal	White	None	0	0	Negative
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	W1	CMU	White	None	0	0	Negative
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	W2	CMU	White	None	0	0	Negative
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	W3	CMU	White	None	0	0	Negative
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	W4	CMU	White	None	0	0	Negative
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B11	Book Storage Room B-11 across from Classroom B-2	Door Casing	Metal	White	None	0	0	Negative
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	W1	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	W2	CMU	White	None	0	0	Negative
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	W3	CMU	White	None	0	0	Negative
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	W4	CMU	White	Flaking	100	0	Negative
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B12	Room B-12 in Blue Office Suite - First Counselor's Office on Left Side	Door Casing	Metal	White	None	0	0	Negative
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	W1	CMU	White	None	0	0	Negative
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	W2	CMU	White	None	0	0	Negative
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	W3	CMU	White	None	0	0	Negative
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	W4	CMU	White	None	0	0	Negative
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B13	Room B-13 in Blue Office Suite - Second Counselor's Office on Left Side	Door Casing	Metal	White	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	W1	CMU	Multi	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	W2	CMU	Multi	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	W3	CMU	Multi	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	W4	CMU	Multi	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B14	Blue Office Suite File and Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B14	Blue Office Suite File and Locker Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	B14	Blue Office Suite File and Locker Room	Door Casing	Metal	Grey	None	0	0	Negative
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	W1	CMU	White	None	0	0	Negative
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	W2	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	W3	CMU	White	None	0	0	Negative
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	W4	CMU	White	None	0	0	Negative
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B15	Room B-15 in Blue Office Suite - Counselor's Office on Right Side	Door Casing	Metal	White	None	0	0	Negative
1	LL	B16	Blue Office Suite Hallway and Waiting Area	W1	CMU	White	None	0	0	Negative
1	LL	B16	Blue Office Suite Hallway and Waiting Area	W2	CMU	White	None	0	0	Negative
1	LL	B16	Blue Office Suite Hallway and Waiting Area	W3	CMU	White	None	0	0	Negative
1	LL	B16	Blue Office Suite Hallway and Waiting Area	W4	CMU	White	None	0	0	Negative
1	LL	B16	Blue Office Suite Hallway and Waiting Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B16	Blue Office Suite Hallway and Waiting Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B16	Blue Office Suite Hallway and Waiting Area	Door Casing	Metal	White	None	0	0.1	Negative
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	W1	CMU	White	Flaking	75	0	Negative
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	W2	CMU	White	Flaking	75	0	Negative
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	W3	CMU	White	Flaking	75	0	Negative
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	W4	CMU	White	Flaking	75	0	Negative
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B17	Room B-17 Food Service Closet next to Seminar Room 18	Door Casing	Metal	White	None	0	0	Negative
1	LL	B1A	Classroom B-1 Storage Room	W1	CMU	White	Flaking	20	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	B1A	Classroom B-1 Storage Room	W2	CMU	White	Cracking	10	0	Negative
1	LL	B1A	Classroom B-1 Storage Room	W3	CMU	White	None	0	0	Negative
1	LL	B1A	Classroom B-1 Storage Room	W4	CMU	White	None	0	0	Negative
1	LL	B1A	Classroom B-1 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	B1A	Classroom B-1 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B1A	Classroom B-1 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	B2	Classroom B-2	W1	CMU	White	Flaking	16	0	Negative
1	LL	B2	Classroom B-2	W2	CMU	White	None	0	0	Negative
1	LL	B2	Classroom B-2	W3	CMU	White	None	0	0	Negative
1	LL	B2	Classroom B-2	W4	CMU	White	Flaking	75	0	Negative
1	LL	B2	Classroom B-2	Ceiling	Concrete	White	None	0	0	Negative
1	LL	B2	Classroom B-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B2	Classroom B-2	Door Casing	Metal	Blue	Friction	7	0	Negative
1	LL	B2	Classroom B-2	Duct	Metal	White	None	0	0.4	Negative
1	LL	B2	Classroom B-2	Pipe	Metal	Blue	None	0	0.3	Negative
1	LL	B3	Classroom B-3	W1	CMU	White	None	0	0	Negative
1	LL	B3	Classroom B-3	W2	CMU	White	None	0	0	Negative
1	LL	B3	Classroom B-3	W3	CMU	White	None	0	0	Negative
1	LL	B3	Classroom B-3	W4	CMU	White	None	0	0	Negative
1	LL	B3	Classroom B-3	Ceiling	Concrete	White	None	0	0	Negative
1	LL	B3	Classroom B-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B3	Classroom B-3	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	B3	Classroom B-3	Duct	Metal	White	None	0	0.3	Negative
1	LL	B3	Classroom B-3	Pipe	Metal	Blue	None	0	0.4	Negative
1	LL	B4	Classroom B-4	W1	CMU	White	None	0	0	Negative
1	LL	B4	Classroom B-4	W2	CMU	White	None	0	0	Negative
1	LL	B4	Classroom B-4	W3	CMU	White	None	0	0	Negative
1	LL	B4	Classroom B-4	W4	CMU	White	None	0	0	Negative
1	LL	B4	Classroom B-4	Ceiling	Concrete	White	None	0	0	Negative
1	LL	B4	Classroom B-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B4	Classroom B-4	Door Casing	Metal	Blue	Friction	1	0	Negative
1	LL	B4	Classroom B-4	Pipe	Metal	Blue	None	0	0.3	Negative
1	LL	B4	Classroom B-4	Duct	Metal	White	None	0	0.4	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	B5	Classroom B-5	W1	CMU	White	None	0	0	Negative
1	LL	B5	Classroom B-5	W2	CMU	White	None	0	0	Negative
1	LL	B5	Classroom B-5	W3	CMU	White	Flaking	40	0	Negative
1	LL	B5	Classroom B-5	W4	CMU	White	Flaking	20	0	Negative
1	LL	B5	Classroom B-5	Ceiling	Concrete	White	None	0	0	Negative
1	LL	B5	Classroom B-5	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	B5	Classroom B-5	Pipe	Metal	White	Flaking	3	0.4	Negative
1	LL	B5	Classroom B-5	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	B5	Classroom B-5	Duct	Metal	White	None	0	0.4	Negative
1	LL	C1	Girl's Locker Room	W1	CMU	White	None	0	0	Negative
1	LL	C1	Girl's Locker Room	W2	CMU	White	None	0	0	Negative
1	LL	C1	Girl's Locker Room	W3	CMU	White	None	0	0	Negative
1	LL	C1	Girl's Locker Room	W4	CMU	White	None	0	0	Negative
1	LL	C1	Girl's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C1	Girl's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C1	Girl's Locker Room	Door	Metal	Blue	None	0	0	Negative
1	LL	C1	Girl's Locker Room	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	C1	Girl's Locker Room	Duct	Metal	White	None	0	0	Negative
1	LL	C11	Boiler Room	Duct	Metal	Blue	None	0	0	Negative
1	LL	C11	Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C11	Boiler Room	W1	CMU	White	None	0	0	Negative
1	LL	C11	Boiler Room	W2	Concrete	White	None	0	0.1	Negative
1	LL	C11	Boiler Room	W3	CMU	White	None	0	0	Negative
1	LL	C11	Boiler Room	W4	CMU	White	None	0	0	Negative
1	LL	C11	Boiler Room	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C11	Boiler Room	Door	Metal	White	None	0	0	Negative
1	LL	C11	Boiler Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	C11	Boiler Room	Floor	Concrete	Gray	None	0	0	Negative
1	LL	C11	Boiler Room	Hand Rail	Metal	Gray	None	0	0	Negative
1	LL	C12	Adaptive Gym	W1	CMU	White	None	0	0	Negative
1	LL	C12	Adaptive Gym	W2	CMU	White	None	0	0	Negative
1	LL	C12	Adaptive Gym	W3	CMU	White	None	0	0	Negative
1	LL	C12	Adaptive Gym	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	C12	Adaptive Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12	Adaptive Gym	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12	Adaptive Gym	Door	Metal	White	None	0	0	Negative
1	LL	C12	Adaptive Gym	Door Casing	Metal	White	None	0	0	Negative
1	LL	C12	Adaptive Gym	Pipe	Metal	White	None	0	0	Negative
1	LL	C12A	Adaptive Gym's Front Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12A	Adaptive Gym's Front Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12A	Adaptive Gym's Front Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12A	Adaptive Gym's Front Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12A	Adaptive Gym's Front Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12A	Adaptive Gym's Front Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C12B	Adaptive Gym's Rear Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C18	Boy's Locker Room Restroom	W1	CMU	Green	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	W2	CMU	Green	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	W3	CMU	Green	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	W4	CMU	Green	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C18	Boy's Locker Room Restroom	Duct	Metal	White	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	pipe	Metal	White	None	0	0	Negative
1	LL	C18	Boy's Locker Room Restroom	pipe	Metal	Green	None	0	0.2	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	W1	CMU	White	None	0	0	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	W2	CMU	White	None	0	0	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	W3	CMU	White	None	0	0	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	Door Casing	Metal	White	None	0	0	Negative
1	LL	C1A	Girl's Locker Room Storage Room between Showers and Restroom	Duct	Metal	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	W2	Concrete	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	W3	Cmu	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	W4	CMU	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C20	Boy's Locker Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C14	Boiler Room	Door	Metal	White	None	0	0	Negative
1	LL	C14	Boiler Room	Door Casing	Metal	White	None	0	0.2	Negative
1	LL	C14	Boiler Room	Pipe	Metal	White	None	0	0	Negative
1	LL	C14	Boiler Room	Duct	Metal	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	W1	CMU	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	W2	CMU	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	W3	CMU	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	W4	CMU	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	pipe	Metal	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	C20A	Boy's Locker Room Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C21	Boy's Locker Room Shower Area	W1	CMU	White	None	0	0	Negative
1	LL	C21	Boy's Locker Room Shower Area	W2	CMU	White	None	0	0	Negative
1	LL	C21	Boy's Locker Room Shower Area	W3	Concrete	White	None	0	0.3	Negative
1	LL	C21	Boy's Locker Room Shower Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C21	Boy's Locker Room Shower Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C24	Boy's Restroom in Lower Commons Area	W1	CMU	White	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	W2	CMU	White	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	C24	Boy's Restroom in Lower Commons Area	W4	CMU	White	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	Door	Metal	Green	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	Door Casing	Metal	Green	None	0	0	Negative
1	LL	C24	Boy's Restroom in Lower Commons Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C24	Boy's Restroom in Lower Commons Area	pipe	Metal	White	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	W1	CMU	Green	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	W2	CMU	Green	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	W3	CMU	Green	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	W4	CMU	Green	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25	Men's Restroom in Lower Commons Area	Pipe	Metal	White	None	0	0	Negative
1	LL	C25	Men's Restroom in Lower Commons Area	Door	Metal	Green	None	0	0	Negative
1	LL	C26	Men's Restroom in Lower Commons Area	Door Casing	Metal	Green	None	0	0	Negative
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	Door Casing	Metal	White	None	0	0	Negative
1	LL	C25A	Custodial Closet between Men's Restroom and Girl's Restroom in Lower Commons Area	Door	Metal	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	W1	CMU	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	W2	CMU	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	W3	CMU	White	None	0	0	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	W4	CMU	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	Door	Metal	Green	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	Door Casing	Metal	Green	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	pipe	Metal	White	None	0	0	Negative
1	LL	C28	Girl's Restroom next to Women's Restroom in Lower Commons Area	Duct	Metal	White	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	W1	CMU	White	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	W2	CMU	White	None	0	0.1	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	W3	CMU	White	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	W4	CMU	White	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	Door	Metal	Green	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	Door Casing	Metal	Green	None	0	0	Negative
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C29	Women's Restroom next to Girl's Restroom in Lower Commons Area	pipe	Metal	White	None	0	0.3	Negative
1	LL	C3	Girl's Locker Room Shower Area	W1	CMU	Tan	None	0	0	Negative
1	LL	C3	Girl's Locker Room Shower Area	W2	CMU	Tan	None	0	0	Negative
1	LL	C3	Girl's Locker Room Shower Area	W3	CMU	Tan	None	0	0	Negative
1	LL	C3	Girl's Locker Room Shower Area	W4	CMU	Tan	None	0	0	Negative
1	LL	C3	Girl's Locker Room Shower Area	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C3	Girl's Locker Room Shower Area	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C34	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C35	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	Door	Metal	White	None	0	0	Negative
1	LL	C36	Storage Room and Air Handler Equipment Room across from the Adaptive Gym	Door Casing	Metal	White	None	0	0.1	Negative
1	LL	C36	Electrical Room in Boiler Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C36	Electrical Room in Boiler Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	C36	Electrical Room in Boiler Room	Door	Metal	White	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	W1	CMU	Green	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	W2	CMU	Green	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	W3	CMU	Green	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	W4	CMU	Green	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	LL	C7	Girl's Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	C7	Girl's Locker Room Restroom	Duct	Metal	White	None	0	0	Negative
1	LL	Elevator	Passenger Elevator	W1	Metal	Tan	None	0	0.2	Negative
1	LL	Elevator	Passenger Elevator	W2	Metal	Tan	None	0	0.2	Negative
1	LL	Elevator	Passenger Elevator	W3	Metal	Tan	None	0	0.2	Negative
1	LL	Elevator	Passenger Elevator	W4	Metal	Tan	None	0	0.4	Negative
1	LL	Elevator	Passenger Elevator	Ceiling	Metal	Tan	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	Elevator	Passenger Elevator	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Elevator	Passenger Elevator	Door	Metal	Yellow	None	0	0.3	Negative
1	LL	Elevator	Passenger Elevator	Door	Metal	Blue	None	0	0	Negative
1	LL	G1	Classroom G-1	W1	CMU	White	Flaking	10	0	Negative
1	LL	G1	Classroom G-1	W2	CMU	White	None	0	0	Negative
1	LL	G1	Classroom G-1	W3	CMU	White	Flaking	30	0	Negative
1	LL	G1	Classroom G-1	W4	CMU	White	Flaking	10	0	Negative
1	LL	G1	Classroom G-1	Ceiling	Concrete	White	None	0	0	Negative
1	LL	G1	Classroom G-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G1	Classroom G-1	Door Casing	Metal	Blue	Friction	3	0	Negative
1	LL	G1	Classroom G-1	Duct	Metal	White	None	0	0.1	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	W1	CMU	White	None	0	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	W2	CMU	White	Flaking	100	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	W3	CMU	White	Flaking	50	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	W4	CMU	White	Flaking	60	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	Ceiling	Concrete	Yellow	None	0	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G10	Room G-10 Storage Room with Transformer	Door Casing	Metal	White	None	0	0	Negative
1	LL	G10	Room G-10 Storage Room with Transformer	Duct	Metal	Yellow	None	0	0	Negative
1	LL	G11	Classroom G-6	W1	CMU	White	None	0	0	Negative
1	LL	G11	Classroom G-6	W2	CMU	White	None	0	0	Negative
1	LL	G11	Classroom G-6	W3	CMU	White	Flaking	100	0	Negative
1	LL	G11	Classroom G-6	W4	CMU	White	None	0	0	Negative
1	LL	G11	Classroom G-6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	G11	Classroom G-6	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G11	Classroom G-6	Door Casing	Metal	White	None	0	0	Negative
1	LL	G11	Classroom G-6	Pipe	Metal	White	None	0	0	Negative
1	LL	G11	Classroom G-6	Electrical Box	Metal	White	None	0	0	Negative
1	LL	G18	Seminar Room 18 Special Education	W1	CMU	White	Flaking	75	0	Negative
1	LL	G18	Seminar Room 18 Special Education	W2	Sheetrock	White	None	0	0	Negative
1	LL	G18	Seminar Room 18 Special Education	W2	CMU	White	None	0	0	Negative
1	LL	G18	Seminar Room 18 Special Education	W3	CMU	White	Flaking	20	0	Negative
1	LL	G18	Seminar Room 18 Special Education	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	G18	Seminar Room 18 Special Education	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	G18	Seminar Room 18 Special Education	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G18	Seminar Room 18 Special Education	Door Casing	Metal	White	None	0	0	Negative
1	LL	G18A	Seminar Room 18 Restroom	W1	Sheetrock	White	None	0	0	Negative
1	LL	G18A	Seminar Room 18 Restroom	W2	CMU	White	Flaking	30	0	Negative
1	LL	G18A	Seminar Room 18 Restroom	W3	CMU	White	Flaking	20	0	Negative
1	LL	G18A	Seminar Room 18 Restroom	W4	Sheetrock	White	None	0	0	Negative
1	LL	G18A	Seminar Room 18 Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	G18A	Seminar Room 18 Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G18A	Seminar Room 18 Restroom	Door Casing	Metal	White	None	0	0	Negative
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	W1	CMU	White	None	0	0	Negative
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	W2	CMU	White	None	0	0	Negative
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	W3	CMU	White	None	0	0	Negative
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	W4	CMU	White	None	0	0	Negative
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	G19	Hub Copy Room between Blue and Yellow Office Suites	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	C14	Boiler Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	W1	CMU	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	W2	CMU	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	W3	CMU	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	W4	CMU	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	Ceiling	Concrete	White	Flaking	25	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G1A	Classroom G-1 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	G1A	Classroom G-1 Storage Room	Pipe	Metal	White	None	0	0	Negative
1	LL	G2	Classroom G-2	W1	CMU	White	None	0	0	Negative
1	LL	G2	Classroom G-2	W2	CMU	White	None	0	0	Negative
1	LL	G2	Classroom G-2	W3	CMU	White	None	0	0	Negative
1	LL	G2	Classroom G-2	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	G2	Classroom G-2	Ceiling	Concrete	White	None	0	0	Negative
1	LL	G2	Classroom G-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G2	Classroom G-2	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	G2	Classroom G-2	Duct	Metal	White	None	0	0.7	Positive
1	LL	G2	Classroom G-2	Pipe	Metal	Blue	None	0	0.2	Negative
1	LL	G3	Classroom G-3	W1	CMU	White	None	0	0	Negative
1	LL	G3	Classroom G-3	W2	CMU	White	None	0	0	Negative
1	LL	G3	Classroom G-3	W3	CMU	White	None	0	0	Negative
1	LL	G3	Classroom G-3	W4	CMU	White	None	0	0	Negative
1	LL	G3	Classroom G-3	Ceiling	Concrete	White	None	0	0	Negative
1	LL	G3	Classroom G-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G3	Classroom G-3	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	G3	Classroom G-3	Duct	Metal	White	None	0	1	Positive
1	LL	G3	Classroom G-3	Pipe	Metal	Blue	None	0	0.2	Negative
1	LL	G4	Classroom G-4	W1	CMU	White	None	0	0	Negative
1	LL	G4	Classroom G-4	W2	CMU	White	None	0	0	Negative
1	LL	G4	Classroom G-4	W3	CMU	White	None	0	0	Negative
1	LL	G4	Classroom G-4	W4	CMU	White	None	0	0	Negative
1	LL	G4	Classroom G-4	Ceiling	Concrete	White	None	0	0	Negative
1	LL	G4	Classroom G-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G4	Classroom G-4	Door Casing	Metal	Blue	Friction	1	0	Negative
1	LL	G4	Classroom G-4	Pipe	Metal	Blue	None	0	0.2	Negative
1	LL	G4	Classroom G-4	Duct	Metal	White	None	0	0.2	Negative
1	LL	G5	Classroom G-5	W1	CMU	White	None	0	0	Negative
1	LL	G5	Classroom G-5	W2	CMU	White	None	0	0	Negative
1	LL	G5	Classroom G-5	W3	CMU	White	None	0	0	Negative
1	LL	G5	Classroom G-5	W4	CMU	White	None	0	0	Negative
1	LL	G5	Classroom G-5	Ceiling	Concrete	White	None	0	0	Negative
1	LL	G5	Classroom G-5	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	G5	Classroom G-5	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	G5	Classroom G-5	Pipe	Metal	White	Flaking	2	0.3	Negative
1	LL	G5	Classroom G-5	Duct	Metal	White	None	0	0.1	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	W2	CMU	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	W3	CMU	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	W4	CMU	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	Door	Metal	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	H010	Hallway from Adaptive Gym to Boy's Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011	Hallway between Classrooms Y-1 and O-1	W1	CMU	White	None	0	0.1	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	W2	CMU	White	None	0	1.5	Positive
1	LL	H011	Hallway between Classrooms Y-1 and O-1	W3	CMU	White	None	0	0.2	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	W4	CMU	White	None	0	1.1	Positive
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Door Casing	Metal	Orange	None	0	0.4	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Door	Metal	Orange	None	0	0.4	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Cove Base	CMU	Black	None	0	1.1	Positive
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Door Casing	Metal	Yellow	None	0	0	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Door	Metal	Yellow	None	0	0	Negative
1	LL	H011	Hallway between Classrooms Y-1 and O-1	Locker	Metal	Tan	None	0	0	Negative
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	W1	CMU	White	None	0	0.1	Negative
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	W2	CMU	White	None	0	0.9	Positive
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	W3	CMU	White	None	0	1.2	Positive
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Door Casing	Metal	White	None	0	0	Negative
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Door	Metal	Blue	None	0	0	Negative
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Door Casing	Metal	Yellow	None	0	0.8	Positive
1	LL	H011A	Hallway from Classroom Y-1 to Lower Lecture Hall	Cove Base	CMU	Black	None	0	0.8	Positive
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	W1	CMU	White	None	0	1.3	Positive
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	W2	CMU	White	None	0	0	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	W3	CMU	White	None	0	0	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	W4	CMU	White	None	0	1	Positive
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Door	Metal	Blue	None	0	0	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Door Casing	Metal	Yellow	None	0	0.8	Positive
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Door	Metal	Yellow	None	0	0.5	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Door	Metal	White	None	0	0.4	Negative
1	LL	H011B	Hallway from Classroom O-1 to Lower Lecture Hall	Cove Base	CMU	Black	None	0	0.9	Positive
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	W1	CMU	White	None	0	0.2	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	W2	CMU	White	None	0	0	Negative
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	W3	CMU	White	None	0	0	Negative
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	W4	CMU	White	None	0	1.2	Positive
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	Cove Base	CMU	Black	None	0	0	Negative
1	LL	H012	Hallway from Classroom G-5 to end of Lockers passed Room Y-17	Door Casing	Metal	Blue	None	0	0.1	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	W1	CMU	White	None	0	0	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	W2	CMU	White	None	0	0.2	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	W3	CMU	White	None	0	0	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	W4	CMU	White	None	0	0.2	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	Cove Base	CMU	Black	None	0	0	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	Door Casing	Metal	White	None	0	0.1	Negative
1	LL	H013	Hallway from Seminar Room 17 to Classroom G-4	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	W1	CMU	White	None	0	0.1	Negative
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	W2	CMU	White	None	0	0	Negative
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	W3	CMU	White	None	0	0.2	Negative
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	W4	CMU	White	None	0	0	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	H014	Hallway from Classroom B-4 to Seminar Room 19	Cove Base	CMU	Black	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	W1	CMU	White	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	W2	CMU	White	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	W3	CMU	White	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	W4	CMU	White	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Cove Base	CMU	Black	None	0	0	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Pipe	Metal	White	None	0	0.4	Negative
1	LL	H015	Hallway from Lockers next to Classroom O-1 to Classroom B-5	Locker	Metal	Tan	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	W1	CMU	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	W2	CMU	White	Flaking	30	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	W3	CMU	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	W4	CMU	White	None	0	0.1	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H06	Hallway C-7a to Outside Exit	Door	Metal	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	pipe	Metal	White	None	0	0.3	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Univent	Metal	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Door	Metal	Blue	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Door Casing	Metal	Blue	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H06	Hallway C-7a to Outside Exit	Door Casing	Metal	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Door	Metal	White	None	0	0	Negative
1	LL	H06	Hallway C-7a to Outside Exit	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H07	Hallway from Hallway C-7a to Elevator	W1	CMU	White	None	0	0	Negative
1	LL	H07	Hallway from Hallway C-7a to Elevator	W2	CMU	White	None	0	0.2	Negative
1	LL	H07	Hallway from Hallway C-7a to Elevator	W3	CMU	White	None	0	0.1	Negative
1	LL	H07	Hallway from Hallway C-7a to Elevator	W4	CMU	White	None	0	0	Negative
1	LL	H07	Hallway from Hallway C-7a to Elevator	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H07	Hallway from Hallway C-7a to Elevator	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H07	Hallway from Hallway C-7a to Elevator	Door	Metal	White	None	0	0	Negative
1	LL	H07	Hallway from Hallway C-7a to Elevator	Door Casing	Metal	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	W1	CMU	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	W2	CMU	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	W3	CMU	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	W4	CMU	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	Door Casing	Metal	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	Door	Metal	White	None	0	0	Negative
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08	Hallway between Elevator Machine Room and Room S-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08A	Elevator Machine Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	C14	Boiler Room	Door	Metal	White	None	0	0	Negative
1	LL	C14	Boiler Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	H08B	S-1 Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H08B	S-1 Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08B	S-1 Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08B	S-1 Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08B	S-1 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08B	S-1 Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H08B	S-1 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	W1	CMU	White	None	0	0	Negative
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	W2	CMU	White	None	0	0	Negative
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	W3	CMU	White	None	0	0	Negative
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	W4	CMU	White	None	0	0	Negative
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H09	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H10	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	Door	Metal	White	None	0	0	Negative
1	LL	H11	Hallway from Storage and Air Handler Equipment Room to Girl's Locker Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	W1	CMU	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	W2	CMU	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	W3	CMU	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	W4	CMU	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	Door	Metal	White	None	0	0	Negative
1	LL	H09A	Hallway along back side of Boiler Room to Outside Steps	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H1	Lower Lecture Hall	W1	CMU	White	Flaking	10	0	Negative
1	LL	H1	Lower Lecture Hall	W2	CMU	White	None	0	0	Negative
1	LL	H1	Lower Lecture Hall	W3	CMU	White	None	0	0	Negative
1	LL	H1	Lower Lecture Hall	W4	CMU	White	None	0	0	Negative
1	LL	H1	Lower Lecture Hall	Ceiling	Concrete	White	None	0	0	Negative
1	LL	H1	Lower Lecture Hall	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H1	Lower Lecture Hall	Door Casing	Metal	Blue	Friction	1	0	Negative
1	LL	H1	Lower Lecture Hall	Pipe	Metal	Blue	None	0	0.4	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	W1	CMU	White	Flaking	50	0	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	W2	CMU	White	None	0	0	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	W3	CMU	White	Flaking	80	0	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	W4	CMU	White	Flaking	50	0	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H23	Seminar Room 17 Physical Therapy	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H23	Seminar Room 17 Physical Therapy	Door Casing	Metal	Blue	Friction	1	0	Negative
1	LL	H23	Seminar Room 17 Physical Therapy	Pipe	Metal	White	None	0	0.2	Negative
1	LL	H26	Seminar Room 19	W1	CMU	White	Flaking	10	0	Negative
1	LL	H26	Seminar Room 19	W2	CMU	White	Flaking	20	0	Negative
1	LL	H26	Seminar Room 19	W3	CMU	White	Flaking	40	0	Negative
1	LL	H26	Seminar Room 19	W4	CMU	White	Flaking	20	0	Negative
1	LL	H26	Seminar Room 19	Ceiling	Concrete	White	None	0	0	Negative
1	LL	H26	Seminar Room 19	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H26	Seminar Room 19	Door Casing	Metal	White	None	0	0	Negative
1	LL	H26	Seminar Room 19	Pipe	Metal	White	Flaking	2	0.2	Negative
1	LL	H47	Room Y-17 Speech Therapy Office	W1	CMU	White	None	0	0	Negative
1	LL	H47	Room Y-17 Speech Therapy Office	W2	CMU	White	Flaking	20	0	Negative
1	LL	H47	Room Y-17 Speech Therapy Office	W3	CMU	White	Flaking	50	0	Negative
1	LL	H47	Room Y-17 Speech Therapy Office	W4	CMU	White	Flaking	50	0	Negative
1	LL	H47	Room Y-17 Speech Therapy Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H47	Room Y-17 Speech Therapy Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H47	Room Y-17 Speech Therapy Office	Door Casing	Metal	White	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	W1	CMU	Green	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	W2	CMU	Green	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H57	Boy's Restroom across from Classroom Y-4	W3	CMU	Green	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	W4	CMU	Green	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	Ceiling	Concrete	White	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	H57	Boy's Restroom across from Classroom Y-4	Door Casing	Metal	Green	None	0	0	Negative
1	LL	H57	Boy's Restroom across from Classroom Y-4	Pipe	Metal	White	None	0	0.2	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	W1	CMU	Green	None	0	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	W2	CMU	Green	None	0	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	W3	CMU	Green	None	0	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	W4	CMU	Green	None	0	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	Door Casing	Metal	Green	None	0	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	Pipe	Metal	White	None	0	0.2	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	Ceiling	Concrete	White	Flaking	10	0	Negative
1	LL	H58	Girl's Restroom near Classroom G-2	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	H58A	Custodial Closet near Classroom G-4	Door Casing	Metal	White	None	0	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	W1	CMU	Green	None	0	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	W2	CMU	Grey	None	0	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	W3	CMU	Green	None	0	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	W4	CMU	Green	None	0	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	Ceiling	Concrete	White	Cracking	5	0	Negative
1	LL	H80	Girl's Restroom near Classroom B-2	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	H81	Girl's Restroom near Classroom B-3	Pipe	Metal	White	None	0	0.3	Negative
1	LL	H82	Girl's Restroom near Classroom B-4	Door Casing	Metal	Green	None	0	0	Negative
1	LL	H80.1	Girls restroom pipe chase	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H80.1	Girls restroom pipe chase	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H80.1	Girls restroom pipe chase	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	H80.1	Girls restroom pipe chase	W4	CMU	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	H80.1	Girls restroom pipe chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H80.1	Girls restroom pipe chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	H80.1	Girls restroom pipe chase	Door	Metal	Green	None	0	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	W1	CMU	Green	None	0	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	W2	CMU	Green	None	0	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	W3	CMU	Green	None	0	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	W4	CMU	Green	None	0	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	Ceiling	Concrete	White	Cracking	5	0	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	LL	H81	Boy's Restroom across from Classroom O-4	Pipe	Metal	White	None	0	0.3	Negative
1	LL	H81	Boy's Restroom across from Classroom O-4	Door Casing	Metal	Green	None	0	0	Negative
1	LL	O-8	Classroom O-8	W1	CMU	White	None	0	0	Negative
1	LL	O-8	Classroom O-8	W2	CMU	White	None	0	0	Negative
1	LL	O-8	Classroom O-8	W3	CMU	White	None	0	0	Negative
1	LL	O-8	Classroom O-8	W4	CMU	White	None	0	0	Negative
1	LL	O-8	Classroom O-8	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	O-8	Classroom O-8	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O-8	Classroom O-8	Door Casing	Metal	White	None	0	0	Negative
1	LL	O1	Classroom O-1	W1	CMU	White	None	0	0	Negative
1	LL	O1	Classroom O-1	W2	CMU	White	None	0	0	Negative
1	LL	O1	Classroom O-1	W3	CMU	White	None	0	0	Negative
1	LL	O1	Classroom O-1	W4	CMU	White	None	0	0	Negative
1	LL	O1	Classroom O-1	Ceiling	Concrete	White	Cracking	10	0	Negative
1	LL	O1	Classroom O-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O1	Classroom O-1	Door Casing	Metal	Blue	Friction	1	0	Negative
1	LL	O1	Classroom O-1	Duct	Metal	White	None	0	0.3	Negative
1	LL	O10	O-10 Storage Room across from Classroom O-4	W1	CMU	White	Flaking	10	0	Negative
1	LL	O10	O-10 Storage Room across from Classroom O-4	W2	CMU	White	Flaking	40	0	Negative
1	LL	O10	O-10 Storage Room across from Classroom O-4	W3	CMU	White	Flaking	50	0	Negative
1	LL	O10	O-10 Storage Room across from Classroom O-4	W4	CMU	White	Flaking	25	0	Negative
1	LL	O10	O-10 Storage Room across from Classroom O-4	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	O10	O-10 Storage Room across from Classroom O-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O10	O-10 Storage Room across from Classroom O-4	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	O13	Classroom O-6	W1	CMU	White	None	0	0	Negative
1	LL	O13	Classroom O-6	W2	CMU	White	None	0	0	Negative
1	LL	O13	Classroom O-6	W3	CMU	White	Flaking	75	0	Negative
1	LL	O13	Classroom O-6	W4	CMU	White	Flaking	100	0	Negative
1	LL	O13	Classroom O-6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	O13	Classroom O-6	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O13	Classroom O-6	Door Casing	Metal	White	None	0	0	Negative
1	LL	O14	Classroom O-7	W1	CMU	White	None	0	0	Negative
1	LL	O14	Classroom O-7	W2	CMU	White	None	0	0	Negative
1	LL	O14	Classroom O-7	W3	CMU	White	None	0	0	Negative
1	LL	O14	Classroom O-7	W4	CMU	White	None	0	0	Negative
1	LL	O14	Classroom O-7	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	O14	Classroom O-7	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O14	Classroom O-7	Door Casing	Metal	White	None	0	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	W1	CMU	White	Flaking	10	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	W2	CMU	White	None	0	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	W3	CMU	White	Flaking	15	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	W4	CMU	White	Flaking	25	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	O1A	Classroom O-1 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O1A	Classroom O-1 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	O1A	Classroom O-1 Storage Room	Pipe	Metal	White	None	0	0.1	Negative
1	LL	O1A	Classroom O-1 Storage Room	Pipe	Metal	Yellow	None	0	0.2	Negative
1	LL	O2	Classroom O-2	W1	CMU	White	Flaking	10	0	Negative
1	LL	O2	Classroom O-2	W2	CMU	White	None	0	0	Negative
1	LL	O2	Classroom O-2	W3	CMU	White	None	0	0	Negative
1	LL	O2	Classroom O-2	W4	CMU	White	Flaking	50	0	Negative
1	LL	O2	Classroom O-2	Ceiling	Concrete	White	None	0	0	Negative
1	LL	O2	Classroom O-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O2	Classroom O-2	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	O2	Classroom O-2	Pipe	Metal	Blue	None	0	0.3	Negative
1	LL	O2	Classroom O-2	Duct	Metal	White	None	0	0.2	Negative
1	LL	O3	Classroom O-3	W1	CMU	White	Flaking	10	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	O3	Classroom O-3	W2	CMU	White	None	0	0	Negative
1	LL	O3	Classroom O-3	W3	CMU	White	None	0	0	Negative
1	LL	O3	Classroom O-3	W4	CMU	White	Flaking	35	0	Negative
1	LL	O3	Classroom O-3	Ceiling	Concrete	White	None	0	0	Negative
1	LL	O3	Classroom O-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O3	Classroom O-3	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	O3	Classroom O-3	Duct	Metal	White	None	0	0.5	Negative
1	LL	O4	Classroom O-4	W1	CMU	White	Flaking	15	0	Negative
1	LL	O4	Classroom O-4	W2	CMU	White	None	0	0	Negative
1	LL	O4	Classroom O-4	W3	CMU	White	None	0	0	Negative
1	LL	O4	Classroom O-4	W4	CMU	White	None	0	0	Negative
1	LL	O4	Classroom O-4	Ceiling	Concrete	White	None	0	0	Negative
1	LL	O4	Classroom O-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O4	Classroom O-4	Duct	Metal	White	None	0	0.2	Negative
1	LL	O4	Classroom O-4	Door Casing	Metal	Blue	Friction	8	0	Negative
1	LL	O5	Classroom O-5	W1	CMU	White	None	0	0	Negative
1	LL	O5	Classroom O-5	W2	CMU	White	None	0	0	Negative
1	LL	O5	Classroom O-5	W3	CMU	White	None	0	0	Negative
1	LL	O5	Classroom O-5	W4	CMU	White	None	0	0	Negative
1	LL	O5	Classroom O-5	Ceiling	Concrete	White	None	0	0	Negative
1	LL	O5	Classroom O-5	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	O5	Classroom O-5	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	O5	Classroom O-5	Duct	Metal	White	None	0	0.1	Negative
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC18	Pipe Chase in Boy's Locker Room Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC19	Pipe Chase in Boy's Locker Room Restroom	Door	Metal	White	None	0	0	Negative
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC20A	Pipe Chase in Boy's Locker Room Storage Room	Door	Metal	White	None	0	0	Negative
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCC28	Pipe Chase in Girl's Restroom next to Women's Restroom in Lower Commons Area	Door	Metal	White	None	0	0	Negative
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH08B	Pipe Chase in S-1 Storage Room	Door	Metal	White	None	0	0	Negative
1	LL	PCH26	Pipe Chase in Seminar Room 19	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH26	Pipe Chase in Seminar Room 19	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH26	Pipe Chase in Seminar Room 19	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH26	Pipe Chase in Seminar Room 19	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH26	Pipe Chase in Seminar Room 19	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	PCH26	Pipe Chase in Seminar Room 19	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	PCH26	Pipe Chase in Seminar Room 19	Door	Metal	White	None	0	0	Negative
1	LL	S010	Stairwell next to Classroom B-2	W1	CMU	Blue	None	0	0.9	Positive
1	LL	S010	Stairwell next to Classroom B-2	W2	CMU	Blue	None	0	1.1	Positive
1	LL	S010	Stairwell next to Classroom B-2	W3	CMU	Blue	None	0	1	Positive
1	LL	S010	Stairwell next to Classroom B-2	W4	CMU	Blue	None	0	0.8	Positive
1	LL	S010	Stairwell next to Classroom B-2	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S010	Stairwell next to Classroom B-2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S010	Stairwell next to Classroom B-2	Stair stringer	Concrete	Black	None	0	0	Negative
1	LL	S010	Stairwell next to Classroom B-2	Hand Rail	Metal	Blue	None	0	0	Negative
1	LL	S010	Stairwell next to Classroom B-2	Door	Metal	Blue	None	0	0.3	Negative
1	LL	S010	Stairwell next to Classroom B-2	Door Casing	Metal	Blue	None	0	0.5	Negative
1	LL	S010	Stairwell next to Classroom B-2	Univent	Metal	Black	None	0	0	Negative
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	W1	CMU	Blue	None	0	0.8	Positive
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	W2	CMU	Blue	None	0	0.9	Positive
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	W3	CMU	Blue	None	0	0.9	Positive
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	W4	CMU	Blue	None	0	1	Positive
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Door Casing	Metal	Blue	None	0	0.7	Positive
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Hand Rail	Metal	Blue	Friction	15	0	Negative
1	LL	S011	Stairwell (S-9) next to Lower Lecture Hall	Stair Stringer	Metal	White	None	0	0	Negative
1	LL	S018	Stairwell next to Restrooms	W1	CMU	Blue	None	0	1.3	Positive
1	LL	S018	Stairwell next to Restrooms	W2	CMU	Blue	None	0	1.1	Positive
1	LL	S018	Stairwell next to Restrooms	W3	CMU	Blue	None	0	2.3	Positive
1	LL	S018	Stairwell next to Restrooms	W4	CMU	Blue	None	0	1	Positive
1	LL	S018	Stairwell next to Restrooms	Hand Rail	Metal	Blue	Friction	10	0	Negative
1	LL	S018	Stairwell next to Restrooms	stair stringer	Concrete	Blue	None	0	0	Negative
1	LL	S018	Stairwell next to Restrooms	Door	Metal	Blue	None	0	0	Negative
1	LL	S018	Stairwell next to Restrooms	Door Casing	Metal	Blue	None	0	0.9	Positive
1	LL	S018	Stairwell next to Restrooms	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S018	Stairwell next to Restrooms	Door Casing	Metal	Blue	Friction	2	0.9	Positive
1	LL	S018	Stairwell next to Restrooms	Door	Metal	Blue	Flaking	5	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	S018	Stairwell next to Restrooms	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	W1	CMU	Blue	None	0	0.9	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	W2	CMU	Blue	Flaking	20	0.7	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	W3	Concrete	Blue	None	0	0.8	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	W4	CMU	Blue	None	0	1	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	Ceiling	Metal	White	None	0	0	Negative
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	Door Casing	Metal	Blue	None	0	0.9	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	univent	Metal	White	None	0	0	Negative
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	pole	Metal	Blue	None	0	0.9	Positive
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	stair stringer	Metal	White	None	0	0	Negative
1	LL	S021	Stairwell from Boy's Locker Room to Boy's side of Gym	Rail	Metal	Blue	Friction	25	0	Negative
1	LL	S08	Stairwell next to Classroom G-2	W1	CMU	Blue	None	0	0	Negative
1	LL	S08	Stairwell next to Classroom G-2	W2	CMU	Blue	None	0	1.5	Positive
1	LL	S08	Stairwell next to Classroom G-2	W3	CMU	Blue	None	0	1	Positive
1	LL	S08	Stairwell next to Classroom G-2	W4	CMU	Blue	None	0	0.8	Positive
1	LL	S08	Stairwell next to Classroom G-2	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S08	Stairwell next to Classroom G-2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S08	Stairwell next to Classroom G-2	Door Casing	Metal	Blue	None	0	0.3	Negative
1	LL	S08	Stairwell next to Classroom G-2	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S08	Stairwell next to Classroom G-2	Univent	Metal	Blue	None	0	0	Negative
1	LL	S08	Stairwell next to Classroom G-2	Hand Rail	Metal	Blue	Friction	2	0	Negative
1	LL	S08	Stairwell next to Classroom G-2	Stair Stringer	Metal	White	None	0	0	Negative
1	LL	S12C	Stairwell near Adaptive Gym	W2	CMU	Blue	None	0	1.3	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	S12C	Stairwell near Adaptive Gym	W3	CMU	Blue	None	0	2.1	Positive
1	LL	S12C	Stairwell near Adaptive Gym	W4	CMU	Blue	None	0	1.4	Positive
1	LL	S12C	Stairwell near Adaptive Gym	Ceiling	Concrete	Blue	None	0	0	Negative
1	LL	S12C	Stairwell near Adaptive Gym	Hand Rail	Metal	Blue	Friction	30	0.1	Negative
1	LL	S12C	Stairwell near Adaptive Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	W1	CMU	Blue	None	0	2.4	Positive
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	W3	CMU	Blue	None	0	1.5	Positive
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	W4	CMU	Blue	None	0	1.4	Positive
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	Ceiling	Concrete	Blue	Flaking	10	0.3	Negative
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	Door	Metal	Blue	None	0	0.7	Positive
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	Door Casing	Metal	Blue	None	0	0.7	Positive
1	LL	S34A	Stairwell next to Storage and Air Handler Equipment Room	Hand Rail	Metal	Blue	Friction	25	0	Negative
1	LL	Y1	Classroom Y-1	W1	CMU	White	Flaking	50	0	Negative
1	LL	Y1	Classroom Y-1	W2	CMU	White	Flaking	75	0.2	Negative
1	LL	Y1	Classroom Y-1	W3	CMU	White	Flaking	10	0	Negative
1	LL	Y1	Classroom Y-1	W4	CMU	White	Flaking	50	0	Negative
1	LL	Y1	Classroom Y-1	Ceiling	Concrete	White	Cracking	10	0	Negative
1	LL	Y1	Classroom Y-1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y1	Classroom Y-1	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	Y1	Classroom Y-1	Pipe	Metal	Blue	None	0	0.2	Negative
1	LL	Y1	Classroom Y-1	Duct	Metal	White	None	0	0.1	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	W1	CMU	White	None	0	0	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	W2	CMU	White	None	0	0	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	W3	CMU	White	None	0	0	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	W4	CMU	White	None	0	0	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	Ceiling	Concrete	Yellow	None	0	0	Negative
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School							
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115							
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	LL	Y10	Y-10 Storage Room across from Classroom Y-4	Door Casing	Metal	White	None	0	0	Negative	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	W1	CMU	White	None	0	0	Negative	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	W2	CMU	White	None	0	0	Negative	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	W3	CMU	White	None	0	0	Negative	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	W4	CMU	White	None	0	0	Negative	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y11	Book Storage Room Y-11 across from Classroom Y-3	Door Casing	Metal	White	None	0	0	Negative	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	W1	CMU	White	None	0	0	Negative	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	W2	CMU	White	None	0	0	Negative	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	W3	CMU	White	None	0	0	Negative	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	W4	CMU	White	None	0	0	Negative	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y12	Room Y-12 in Yellow Office Suite - First Counselor's Office on Left Side	Door Casing	Metal	White	None	0	0	Negative	
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	W1	CMU	White	None	0	0	Negative	
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	W2	CMU	White	None	0	0	Negative	
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	W3	CMU	White	None	0	0	Negative	
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	W4	CMU	White	None	0	0	Negative	
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y13	Room Y-13 in Yellow Office Suite - Second Counselor's Office on Left Side	Door Casing	Metal	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	W1	CMU	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	W2	CMU	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	W3	CMU	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	W4	CMU	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y14	Yellow Office Suite File and Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y14	Yellow Office Suite File and Locker Room	Door Casing	Metal	White	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	Door Casing	Metal	Grey	None	0	0	Negative
1	LL	Y14	Yellow Office Suite File and Locker Room	Pillar	Concrete	Blue	None	0	0	Negative
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	W1	CMU	White	None	0	0	Negative
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	W2	CMU	White	None	0	0	Negative
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	W3	CMU	White	None	0	0	Negative
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	W4	CMU	White	None	0	0	Negative
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y15	Room Y-15 in Yellow Office Suite -&nbsp; Counselor's Office on Right Side	Door Casing	Metal	White	None	0	0	Negative
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	W1	CMU	White	None	0	0	Negative
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	W2	CMU	White	Flaking	10	0	Negative
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	W3	CMU	White	None	0	0	Negative
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	W4	CMU	White	None	0	0	Negative
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y16	Yellow Office Suite Hallway and Waiting Area	Door Casing	Metal	White	None	0	0	Negative
1	LL	Y17	Book Storage Room across from Classroom Y-2	W1	CMU	White	Flaking	25	0	Negative
1	LL	Y17	Book Storage Room across from Classroom Y-2	W2	CMU	White	Flaking	25	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School							
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115							
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	LL	Y17	Book Storage Room across from Classroom Y-2	W3	CMU	White	Flaking	25	0	Negative	
1	LL	Y17	Book Storage Room across from Classroom Y-2	W4	CMU	White	Flaking	25	0	Negative	
1	LL	Y17	Book Storage Room across from Classroom Y-2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y17	Book Storage Room across from Classroom Y-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y17	Book Storage Room across from Classroom Y-2	Door Casing	Metal	White	None	0	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	W1	CMU	White	Flaking	10	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	W2	CMU	White	Flaking	30	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	W3	CMU	White	Flaking	10	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	W4	CMU	White	Flaking	50	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y1A	Classroom Y-1 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y1A	Classroom Y-1 Storage Room	Door Casing	Metal	White	None	0	0	Negative	
1	LL	Y1A	Classroom Y-1 Storage Room	Pipe	Metal	White	Flaking	3	0.3	Negative	
1	LL	Y2	Classroom Y-2	W1	CMU	White	None	0	0	Negative	
1	LL	Y2	Classroom Y-2	W2	CMU	White	Flaking	75	0	Negative	
1	LL	Y2	Classroom Y-2	W3	CMU	White	None	0	0	Negative	
1	LL	Y2	Classroom Y-2	W4	CMU	White	None	0	0	Negative	
1	LL	Y2	Classroom Y-2	Ceiling	Concrete	White	None	0	0	Negative	
1	LL	Y2	Classroom Y-2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y2	Classroom Y-2	Door Casing	Metal	Blue	Friction	2	0	Negative	
1	LL	Y2	Classroom Y-2	Duct	Metal	White	None	0	0.2	Negative	
1	LL	Y3	Classroom Y-3	W1	CMU	White	None	0	0.1	Negative	
1	LL	Y3	Classroom Y-3	W2	CMU	White	Flaking	25	0	Negative	
1	LL	Y3	Classroom Y-3	W3	CMU	White	None	0	0	Negative	
1	LL	Y3	Classroom Y-3	W4	CMU	White	None	0	0	Negative	
1	LL	Y3	Classroom Y-3	Ceiling	Concrete	White	None	0	0	Negative	
1	LL	Y3	Classroom Y-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	LL	Y3	Classroom Y-3	Door Casing	Metal	Blue	Friction	2	0	Negative	
1	LL	Y3	Classroom Y-3	Duct	Metal	White	None	0	0.1	Negative	
1	LL	Y4	Classroom Y-4	W1	CMU	White	Flaking	10	0	Negative	
1	LL	Y4	Classroom Y-4	W2	CMU	White	None	0	0	Negative	
1	LL	Y4	Classroom Y-4	W3	CMU	White	None	0	0	Negative	
1	LL	Y4	Classroom Y-4	W4	CMU	White	Flaking	15	0	Negative	

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	Y4	Classroom Y-4	Ceiling	Concrete	White	None	0	0	Negative
1	LL	Y4	Classroom Y-4	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y4	Classroom Y-4	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	Y4	Classroom Y-4	Duct	Metal	White	None	0	0.3	Negative
1	LL	Y5	Classroom Y-5	W1	CMU	White	None	0	0	Negative
1	LL	Y5	Classroom Y-5	W2	CMU	White	None	0	0	Negative
1	LL	Y5	Classroom Y-5	W3	CMU	White	None	0	0	Negative
1	LL	Y5	Classroom Y-5	W4	CMU	White	None	0	0	Negative
1	LL	Y5	Classroom Y-5	Ceiling	Concrete	White	None	0	0	Negative
1	LL	Y5	Classroom Y-5	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	LL	Y5	Classroom Y-5	Door Casing	Metal	Blue	Friction	2	0	Negative
1	LL	Y5	Classroom Y-5	Duct	Metal	White	None	0	0.4	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	W1	CMU	White	None	0	0	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	W2	CMU	White	None	0	0	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	W3	CMU	White	None	0	0	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	W4	CMU	White	None	0	0	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	Cove Base	CMU	Black	None	0	0	Negative
1	ML	A10	Hallway from Custodial Closet to Girl's Restroom	Door Casing	Metal	White	None	0	0	Negative
1	ML	A102	Girl's Restroom	W1	CMU	Green	None	0	0	Negative
1	ML	A102	Girl's Restroom	W2	CMU	Green	None	0	0	Negative
1	ML	A102	Girl's Restroom	W3	CMU	Green	None	0	0	Negative
1	ML	A102	Girl's Restroom	W4	CMU	Green	None	0	0	Negative
1	ML	A102	Girl's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A102	Girl's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	A102	Girl's Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	A102	Girl's Restroom	Pipe	Metal	Green	None	0	0.2	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A102	Girl's Restroom	Pipe	Metal	White	None	0	0	Negative
1	ML	A102	Girl's Restroom	Univent	Metal	White	None	0	0.1	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	W1	CMU	Green	None	0	0	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	W2	CMU	Green	None	0	0	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	W3	CMU	Green	None	0	0	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	W4	CMU	Green	None	0	0.4	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	A105	Gender neutral restroom near Instrument Music Room	Door Casing	Metal	Green	None	0	0	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	Duct	Metal	White	None	0	0.2	Negative
1	ML	A105	Gender neutral restroom near Instrument Music Room	Pipe	Metal	White	None	0	0	Negative
1	ML	A106	Custodial Closet next to Women's Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A106	Custodial Closet next to Women's Restroom	Door Casing	Metal	White	None	0	0	Negative
1	ML	A107	Boy's Restroom	W1	CMU	Green	None	0	0	Negative
1	ML	A107	Boy's Restroom	W2	CMU	Green	None	0	0	Negative
1	ML	A107	Boy's Restroom	W3	CMU	Green	None	0	0	Negative
1	ML	A107	Boy's Restroom	W4	CMU	Green	None	0	0	Negative
1	ML	A107	Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A107	Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	A107	Boy's Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	A107	Boy's Restroom	Pipe	Metal	White	None	0	0	Negative
1	ML	A107	Boy's Restroom	Univent	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A108	Womans Restroom	W1	CMU	Green	None	0	0	Negative
1	ML	A108	Womans Restroom	W2	CMU	Green	None	0	0	Negative
1	ML	A108	Womans Restroom	W3	CMU	Green	None	0	0	Negative
1	ML	A108	Womans Restroom	W4	CMU	Green	None	0	0	Negative
1	ML	A108	Womans Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A108	Womans Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	A108	Womans Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	A109	Instrument Music Room	W1	Sheetrock	Blue	None	0	0	Negative
1	ML	A109	Instrument Music Room	W2	Sheetrock	Blue	None	0	0	Negative
1	ML	A109	Instrument Music Room	W3	Sheetrock	Blue	None	0	0	Negative
1	ML	A109	Instrument Music Room	W4	CMU	Blue	None	0	0	Negative
1	ML	A109	Instrument Music Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A109	Instrument Music Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A109	Instrument Music Room	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A109	Instrument Music Room	Duct	Metal	White	None	0	0.4	Negative
1	ML	A110	Music Room - 2 Office	W1	CMU	White	Flaking	10	0	Negative
1	ML	A110	Music Room - 2 Office	W2	CMU	White	None	0	0	Negative
1	ML	A110	Music Room - 2 Office	W3	CMU	White	Flaking	25	0	Negative
1	ML	A110	Music Room - 2 Office	W4	CMU	White	Flaking	100	0	Negative
1	ML	A110	Music Room - 2 Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A110	Music Room - 2 Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A110	Music Room - 2 Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	W1	CMU	White	Flaking	40	0	Negative
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	W2	CMU	White	Flaking	25	0	Negative
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	W3	CMU	White	Flaking	20	0	Negative
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	W4	CMU	White	Flaking	75	0	Negative
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A111	Practice Room (Used for Storage) next to Music Room 2	Door Casing	Metal	White	None	0	0	Negative
1	ML	A112	Middle Practice Room (Used for Storage)	W1	CMU	White	Flaking	30	0	Negative
1	ML	A112	Middle Practice Room (Used for Storage)	W2	CMU	White	Flaking	50	0	Negative
1	ML	A112	Middle Practice Room (Used for Storage)	W3	CMU	White	None	0	0	Negative
1	ML	A112	Middle Practice Room (Used for Storage)	W4	CMU	White	Flaking	40	0	Negative
1	ML	A112	Middle Practice Room (Used for Storage)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A112	Middle Practice Room (Used for Storage)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A112	Middle Practice Room (Used for Storage)	Door Casing	Metal	White	None	0	0	Negative
1	ML	A113	Right Practice Room next to Instrument Music Room	W1	CMU	White	Flaking	100	0	Negative
1	ML	A113	Right Practice Room next to Instrument Music Room	W2	CMU	White	Flaking	75	0	Negative
1	ML	A113	Right Practice Room next to Instrument Music Room	W3	CMU	White	Flaking	100	0	Negative
1	ML	A113	Right Practice Room next to Instrument Music Room	W4	CMU	White	Flaking	75	0	Negative
1	ML	A113	Right Practice Room next to Instrument Music Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A113	Right Practice Room next to Instrument Music Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A113	Right Practice Room next to Instrument Music Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	W1	CMU	White	None	0	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	W2	CMU	White	Flaking	75	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	W3	CMU	White	None	0	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	W4	CMU	White	None	0	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A114	Hallway between Instrument Music Practice Rooms	Door Casing	Metal	White	None	0	0	Negative
1	ML	A114	Hallway between Instrument Music Practice Rooms	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A115	Practice Room (Bass Only) near Music Room 2	W1	CMU	White	Flaking	50	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A115	Practice Room (Bass Only) near Music Room 2	W2	CMU	White	Flaking	50	0	Negative
1	ML	A115	Practice Room (Bass Only) near Music Room 2	W3	CMU	White	None	0	0	Negative
1	ML	A115	Practice Room (Bass Only) near Music Room 2	W4	CMU	White	None	0	0	Negative
1	ML	A115	Practice Room (Bass Only) near Music Room 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A115	Practice Room (Bass Only) near Music Room 2	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A115	Practice Room (Bass Only) near Music Room 2	Door Casing	Metal	White	None	0	0	Negative
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	W1	CMU	White	Flaking	25	0	Negative
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	W2	CMU	White	None	0	0	Negative
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	W3	CMU	White	None	0	0	Negative
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	W4	CMU	White	Flaking	25	0	Negative
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A116	Left&nbsp;Practice Room next to Instrument Music Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A117	ELA/SS Academic Office	W1	CMU	White	Flaking	50	0	Negative
1	ML	A117	ELA/SS Academic Office	W2	CMU	White	Flaking	75	0	Negative
1	ML	A117	ELA/SS Academic Office	W3	CMU	White	Flaking	30	0	Negative
1	ML	A117	ELA/SS Academic Office	W4	CMU	White	Flaking	100	0	Negative
1	ML	A117	ELA/SS Academic Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A117	ELA/SS Academic Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A117	ELA/SS Academic Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	W1	CMU	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	W2	CMU	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	W3	CMU	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	W4	CMU	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A118	Math/ Science Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A118	Math/ Science Room	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	A118	Math/ Science Room	Duct	Metal	White	None	0	0.3	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A119	Academic Room-Storage Room in Rear	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A119	Academic Room-Storage Room in Rear	Door Casing	Metal	White	None	0	0	Negative
1	ML	A120	ML1	W1	CMU	White	None	0	0	Negative
1	ML	A120	ML1	W2	CMU	White	None	0	0	Negative
1	ML	A120	ML1	W3	CMU	White	None	0	0	Negative
1	ML	A120	ML1	W4	CMU	White	None	0	0	Negative
1	ML	A120	ML1	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A120	ML1	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A120	ML1	Door Casing	Metal	White	None	0	0	Negative
1	ML	A120	ML1	Duct	Metal	White	None	0	0	Negative
1	ML	A126	Computer Lab C	W1	CMU	White	None	0	0	Negative
1	ML	A126	Computer Lab C	W2	CMU	White	None	0	0	Negative
1	ML	A126	Computer Lab C	W3	CMU	White	None	0	0	Negative
1	ML	A126	Computer Lab C	W4	CMU	White	None	0	0	Negative
1	ML	A126	Computer Lab C	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A126	Computer Lab C	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A126	Computer Lab C	Door Casing	Metal	White	None	0	0	Negative
1	ML	A126	Computer Lab C	Door Casing	Metal	White	None	0	0	Negative
1	ML	A126	Computer Lab C	Duct	Metal	White	None	0	0.5	Negative
1	ML	A126	Computer Lab C	Pipe	Metal	White	None	0	0	Negative
1	ML	A127	Computer Lab B	W1	CMU	White	None	0	0	Negative
1	ML	A127	Computer Lab B	W2	CMU	White	None	0	0	Negative
1	ML	A127	Computer Lab B	W3	CMU	White	None	0	0	Negative
1	ML	A127	Computer Lab B	W4	CMU	White	None	0	0	Negative
1	ML	A127	Computer Lab B	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A127	Computer Lab B	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A127	Computer Lab B	Door Casing	Metal	White	None	0	0	Negative
1	ML	A127	Computer Lab B	Duct	Metal	Yellow	None	0	0.1	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A127	Computer Lab B	Pipe	Metal	White	None	0	0	Negative
1	ML	A127	Computer Lab B	Gate	Metal	Black	None	0	0	Negative
1	ML	A128	Computer Lab A	W1	CMU	Green	None	0	0	Negative
1	ML	A128	Computer Lab A	W2	CMU	Green	None	0	0	Negative
1	ML	A128	Computer Lab A	W2	CMU	Grey	None	0	0	Negative
1	ML	A128	Computer Lab A	W3	CMU	Green	None	0	0	Negative
1	ML	A128	Computer Lab A	W3	CMU	Grey	None	0	0	Negative
1	ML	A128	Computer Lab A	W4	CMU	Grey	None	0	0	Negative
1	ML	A128	Computer Lab A	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128	Computer Lab A	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128	Computer Lab A	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A128	Computer Lab A	Door	Metal	Blue	None	0	0	Negative
1	ML	A128	Computer Lab A	Duct	Metal	Yellow	None	0	0	Negative
1	ML	A128	Computer Lab A	Duct	Metal	Grey	None	0	0	Negative
1	ML	A128	Computer Lab A	Pipe	Metal	Yellow	None	0	0.1	Negative
1	ML	A128	Computer Lab A	Pipe	Metal	Grey	None	0	0.2	Negative
1	ML	A128	Computer Lab A	Door Casing	Metal	Grey	None	0	0	Negative
1	ML	A128	Computer Lab A	Door	Wood	Grey	None	0	0	Negative
1	ML	A128A	Computer Lab A Storage Room by Entrance	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A128A	Computer Lab A Storage Room by Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A130	Computer Lab C Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A130	Computer Lab C Storage Room	Duct	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A130	Computer Lab C Storage Room	Pipe	Metal	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A130A	Computer Lab C Storage Room in rear of Storage Room	Pipe	Metal	White	None	0	0	Negative
1	ML	A131	Computer Lab B Left Side Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A131	Computer Lab B Left Side Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	W1	CMU	Green	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	W2	CMU	Green	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	W3	CMU	Green	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	W4	CMU	Green	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	Door Casing	Metal	Green	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A135	Men's Restroom and Shower next to Building Engineer's Office	Stall Divider	Metal	Yellow	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	W1	CMU	Pink	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	W2	CMU	Pink	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	W3	CMU	Pink	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	W4	CMU	Pink	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	Door Casing	Metal	Pink	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	Duct	Metal	White	None	0	0	Negative
1	ML	A136	Women's Restroom and Shower near Building Engineer's Office	Stall Divider	Metal	Blue	None	0	0	Negative
1	ML	A140	Building Engineer's Office	W1	CMU	White	None	0	0	Negative
1	ML	A140	Building Engineer's Office	W2	CMU	White	None	0	0	Negative
1	ML	A140	Building Engineer's Office	W3	CMU	White	Flaking	15	0	Negative
1	ML	A140	Building Engineer's Office	W4	CMU	White	None	0	0	Negative
1	ML	A140	Building Engineer's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A140	Building Engineer's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A140	Building Engineer's Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	A140	Building Engineer's Office	Duct	Metal	White	None	0	0	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	W1	CMU	White	None	0	0	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	W2	CMU	White	None	0	0	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	W3	CMU	White	None	0	0	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	W4	CMU	White	None	0	0	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	A141	Maintenance Staff Office between Building Engineer's Office and Restrooms	Univent	Metal	White	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	W1	CMU	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	W2	CMU	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	W3	CMU	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	W4	CMU	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A142	Maintenance Staff Break Room and Dining Area	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	Univent	Metal	Blue	None	0	0	Negative
1	ML	A142	Maintenance Staff Break Room and Dining Area	Pipe	Metal	White	None	0	0.1	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	W1	CMU	Blue	None	0	0.1	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	W2	CMU	Blue	None	0	0.2	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	W3	CMU	Blue	None	0	0.3	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	W4	CMU	Blue	None	0	0.4	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	Pipe	Metal	Blue	None	0	0.2	Negative
1	ML	A143	Ante Room Maintenance Storage Area next to Loading Dock	Door	Metal	Blue	None	0	0	Negative
1	ML	A146	Auditorium	W1	CMU	White	None	0	0	Negative
1	ML	A146	Auditorium	W1 (accent wall)	CMU	Blue	None	0	0.5	Negative
1	ML	A146	Auditorium	W2	CMU	White	None	0	0	Negative
1	ML	A146	Auditorium	W2 (accent wall)	CMU	Blue	None	0	0.5	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A146	Auditorium	W3	CMU	White	None	0	0	Negative
1	ML	A146	Auditorium	W3 (accent wall)	CMU	Blue	None	0	0.6	Negative
1	ML	A146	Auditorium	W4	CMU	White	None	0	0	Negative
1	ML	A146	Auditorium	W4 (accent wall)	CMU	Blue	None	0	0.4	Negative
1	ML	A146	Auditorium	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A146	Auditorium	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A146	Auditorium	Beam	Metal	White	None	0	0	Negative
1	ML	A146	Auditorium	Door	Metal	Blue	None	0	0	Negative
1	ML	A146	Auditorium	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A146	Auditorium	Stair Stringer	Concrete	Blue	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	W2	CMU	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	W3	CMU	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	W4	CMU	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	ML	A146 STAGE	Auditorium Stage	Door	Metal	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	Door Casing	Metal	White	None	0	0	Negative
1	ML	A146 STAGE	Auditorium Stage	Duct	Metal	Yellow	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A148	Computer Lab B Right Side Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A148	Computer Lab B Right Side Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	A148	Computer Lab B Right Side Storage Room	Duct	Metal	White	None	0	0	Negative
1	ML	A149	Computer Lab A Storage Room in Rear	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A149	Computer Lab A Storage Room in Rear	Door	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	A149	Computer Lab A Storage Room in Rear	Duct	Metal	White	None	0	0	Negative
1	ML	A149	Computer Lab A Storage Room in Rear	Gate	Metal	Black	None	0	0	Negative
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A153	Sprinkler System Room in Stairwell next to Instrument Music Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	B101	Classroom O-101	W1	CMU	White	None	0	0	Negative
1	ML	B101	Classroom O-101	W2	CMU	White	None	0	0	Negative
1	ML	B101	Classroom O-101	W3	CMU	White	None	0	0	Negative
1	ML	B101	Classroom O-101	W4	CMU	White	Flaking	50	0	Negative
1	ML	B101	Classroom O-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	B101	Classroom O-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B101	Classroom O-101	Door Casing	Metal	White	None	0	0	Negative
1	ML	B101	Classroom O-101	Duct	Metal	White	None	0	0.1	Negative
1	ML	B101A	Classroom O-101 Storage Room	W1	CMU	White	Flaking	25	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	W4	CMU	White	Flaking	25	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	Ceiling	Concrete	White	Flaking	75	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B101A	Classroom O-101 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	B101A	Classroom O-101 Storage Room	Pipe	Metal	White	None	0	0.2	Negative
1	ML	B102	Classroom O-102	W1	CMU	White	None	0	0	Negative
1	ML	B102	Classroom O-102	W2	CMU	White	None	0	0	Negative
1	ML	B102	Classroom O-102	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	B102	Classroom O-102	W4	CMU	White	None	0	0	Negative
1	ML	B102	Classroom O-102	Ceiling	Concrete	White	Flaking	10	0	Negative
1	ML	B102	Classroom O-102	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B102	Classroom O-102	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	B102	Classroom O-102	Duct	Metal	White	None	0	0.3	Negative
1	ML	B102	Classroom O-102	Pole	Metal	White	None	0	0.3	Negative
1	ML	B103	Classroom O-103	W1	CMU	White	None	0	0.1	Negative
1	ML	B103	Classroom O-103	W2	CMU	White	None	0	0	Negative
1	ML	B103	Classroom O-103	W3	CMU	White	None	0	0	Negative
1	ML	B103	Classroom O-103	W4	CMU	White	None	0	0	Negative
1	ML	B103	Classroom O-103	Ceiling	Concrete	White	None	0	0	Negative
1	ML	B103	Classroom O-103	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B103	Classroom O-103	Door Casing	Metal	White	None	0	0	Negative
1	ML	B103	Classroom O-103	Duct	Metal	White	None	0	0.3	Negative
1	ML	B104	Classroom O-104	W1	CMU	White	None	0	0.1	Negative
1	ML	B104	Classroom O-104	W2	CMU	White	None	0	0.1	Negative
1	ML	B104	Classroom O-104	W3	CMU	White	None	0	0	Negative
1	ML	B104	Classroom O-104	W4	CMU	White	None	0	0	Negative
1	ML	B104	Classroom O-104	Ceiling	Concrete	White	None	0	0	Negative
1	ML	B104	Classroom O-104	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B104	Classroom O-104	Door Casing	Metal	White	None	0	0	Negative
1	ML	B104	Classroom O-104	Duct	Metal	White	None	0	0.3	Negative
1	ML	B105	Classroom O-105	W1	CMU	White	None	0	0	Negative
1	ML	B105	Classroom O-105	W2	CMU	White	None	0	0	Negative
1	ML	B105	Classroom O-105	W3	CMU	White	None	0	0	Negative
1	ML	B105	Classroom O-105	W4	CMU	White	None	0	0	Negative
1	ML	B105	Classroom O-105	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	B105	Classroom O-105	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B105	Classroom O-105	Duct	Metal	Yellow	None	0	0.1	Negative
1	ML	B105	Classroom O-105	Door Casing	Metal	White	None	0	0.3	Negative
1	ML	C101	Girl's Gym	W1	CMU	White	None	0	1.2	Positive
1	ML	C101	Girl's Gym	W2	CMU	White	None	0	0	Negative
1	ML	C101	Girl's Gym	W3	CMU	White	None	0	1.1	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C101	Girl's Gym	W4	CMU	White	None	0	0.8	Positive
1	ML	C101	Girl's Gym	Column	Concrete	Blue	None	0	0	Negative
1	ML	C101	Girl's Gym	Door	Metal	Blue	None	0	0	Negative
1	ML	C101	Girl's Gym	Door Casing	Metal	Blue	None	0	0.2	Negative
1	ML	C101	Girl's Gym	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	ML	C101	Girl's Gym	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	ML	C101	Girl's Gym	Grate	Metal	Blue	None	0	0.7	Positive
1	ML	C102	Boy's Gym	W1	CMU	White	None	0	1	Positive
1	ML	C102	Boy's Gym	W2	CMU	White	None	0	1.3	Positive
1	ML	C102	Boy's Gym	W3	CMU	White	None	0	1.1	Positive
1	ML	C102	Boy's Gym	W4	CMU	White	None	0	Assumed	Assumed
1	ML	C102	Boy's Gym	Ceiling	Wood	Unpainted	N/A	N/A	N/A	N/A
1	ML	C102	Boy's Gym	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	ML	C102	Boy's Gym	Door	Metal	Blue	None	0	0	Negative
1	ML	C102	Boy's Gym	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	C102	Boy's Gym	Column	Concrete	Blue	None	0	0	Negative
1	ML	C102	Boy's Gym	Grate	Metal	Blue	None	0	0.7	Positive
1	ML	C103	Storage and Fan Room on Girl's side of Gym	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C103	Storage and Fan Room on Girl's side of Gym	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C103	Storage and Fan Room on Girl's side of Gym	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C103	Storage and Fan Room on Girl's side of Gym	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C103	Storage and Fan Room on Girl's side of Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C103	Storage and Fan Room on Girl's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C104	Gym Office on Girl's side of Gym	W1	CMU	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	W2	CMU	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	W3	CMU	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	W4	CMU	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C104	Gym Office on Girl's side of Gym	Door Casing	Metal	White	None	0	0	Negative
1	ML	C104	Gym Office on Girl's side of Gym	Duct	Metal	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	W1	CMU	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	W2	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C105	Gym Office Restroom on Girl's side of Gym	W3	CMU	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	W4	CMU	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	Duct	Metal	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	Door Casing	Metal	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C105	Gym Office Restroom on Girl's side of Gym	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C110	Gym Office Restroom on Boy's side of Gym	W1	CMU	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	W2	CMU	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	W3	CMU	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	W4	CMU	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	C110	Gym Office Restroom on Boy's side of Gym	Door Casing	Metal	White	None	0	0	Negative
1	ML	C110	Gym Office Restroom on Boy's side of Gym	Duct	Metal	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	W1	CMU	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	W2	CMU	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	W3	CMU	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	W4	CMU	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	Door Casing	Metal	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	Duct	Metal	White	None	0	0	Negative
1	ML	C111	Gym Office on Boy's side of Gym	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	Door Casing	Metal	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C112	Storage and Fan Room on Boy's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C113	Boy's Restroom next to Men's Restroom	W1	CMU	Green	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	W2	CMU	Green	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	W3	CMU	Green	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	W4	CMU	Green	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C113	Boy's Restroom next to Men's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	C113	Boy's Restroom next to Men's Restroom	Door	Metal	Green	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	Pipe	Metal	White	None	0	0	Negative
1	ML	C113	Boy's Restroom next to Men's Restroom	Duct	Metal	White	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	W1	cmu	Green	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	W2	cmu	Green	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	W3	cmu	Green	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	W4	cmu	Green	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	Ceiling	concrete	White	None	0	0	Negative
1	ML	C114	Men's Restroom between Custodial Closet and Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	C115	Men's Restroom between Custodial Closet and Boy's Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	C116	Men's Restroom between Custodial Closet and Boy's Restroom	Door	Metal	Green	None	0	0	Negative
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C114A	Room 102 Custodial Closet between Girl's Restroom and Men's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C117	Girl's Restroom next to Women's Restroom	W1	CMU	Green	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	W2	CMU	Green	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	W3	CMU	Green	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	W4	CMU	Green	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C117	Girl's Restroom next to Women's Restroom	Ceiling	concrete	White	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	C117	Girl's Restroom next to Women's Restroom	duct	Metal	White	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	Door	Metal	Green	None	0	0	Negative
1	ML	C117	Girl's Restroom next to Women's Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	W1	CMU	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	W2	CMU	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	W3	CMU	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	W4	CMU	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	Ceiling	concrete	White	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	C118	Women's Restroom near Art Lab C-D	Door Casing	Metal	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	Door	Metal	Green	None	0	0	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	pipe	Metal	White	None	0	0.1	Negative
1	ML	C118	Women's Restroom near Art Lab C-D	Duct	Metal	White	None	0	0	Negative
1	ML	C120	Art Lab C-D	W1	CMU	White	None	0	0	Negative
1	ML	C120	Art Lab C-D	W2	CMU	White	None	0	0	Negative
1	ML	C120	Art Lab C-D	W3	CMU	White	None	0	0	Negative
1	ML	C120	Art Lab C-D	W4	CMU	White	None	0	0	Negative
1	ML	C120	Art Lab C-D	Ceiling	Concrete	Blue	None	0	0	Negative
1	ML	C120	Art Lab C-D	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C120	Art Lab C-D	Duct	Metal	Blue	None	0	0.3	Negative
1	ML	C120	Art Lab C-D	Pipe	Metal	Blue	Flaking	2	0.2	Negative
1	ML	C120	Art Lab C-D	Door	Metal	Blue	Flaking	5	0	Negative
1	ML	C120	Art Lab C-D	Door Casing	Metal	Blue	Flaking	2	0.1	Negative
1	ML	C121	Art Lab C-D Storage Room near Entrance	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	Ceiling	concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	Floor	concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C121	Art Lab C-D Storage Room near Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	C121	Art Lab C-D Storage Room near Entrance	pipe	Metal	White	None	0	0.1	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	W1	CMU	White	Flaking	35	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	W2	CMU	White	None	0	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	W3	CMU	White	Flaking	20	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	W4	CMU	White	Flaking	35	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	C122	Art Lab C-D Storage Room and Kiln Room	Duct	Metal	White	None	0	0	Negative
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	Ceiling	concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C123	Art Lab C-D Storage Room third in from Entrance	Floor	concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	B104	Classroom O-105	Door Casing	Metal	White	None	0	0	Negative
1	ML	C124	Art Lab C-D Office	W1	CMU	White	Flaking	25	0	Negative
1	ML	C124	Art Lab C-D Office	W2	CMU	White	None	0	0	Negative
1	ML	C124	Art Lab C-D Office	W3	CMU	White	Flaking	20	0	Negative
1	ML	C124	Art Lab C-D Office	W4	CMU	White	Flaking	9	0	Negative
1	ML	C124	Art Lab C-D Office	Ceiling	concrete	White	Flaking	15	0	Negative
1	ML	C124	Art Lab C-D Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C125	Art Lab C-D Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	C126	Art Lab A-B Office	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C126	Art Lab A-B Office	W1	CMU	White	Flaking	30	0	Negative
1	ML	C126	Art Lab A-B Office	W2	CMU	White	Flaking	50	0	Negative
1	ML	C126	Art Lab A-B Office	W3	CMU	White	Flaking	50	0	Negative
1	ML	C126	Art Lab A-B Office	W4	CMU	White	Flaking	25	0	Negative
1	ML	C126	Art Lab A-B Office	Ceiling	Concrete	White	Flaking	10	0	Negative
1	ML	C126	Art Lab A-B Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C126	Art Lab A-B Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	W1	CMU	White	None	0	0	Negative
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	W2	CMU	White	None	0	0	Negative
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	W3	CMU	White	None	0	0	Negative
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	W4	CMU	White	None	0	0	Negative
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C127	Art Lab A-B Storage Room fourth in from Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	Pipe	Metal	White	None	0	0.2	Negative
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	W1	CMU	White	None	0	0	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	W2	CMU	White	None	0	0	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	W3	CMU	White	None	0	0	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	W4	CMU	White	None	0	0	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C130	Art Lab A-B Storage Room and Kiln Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C129	Art Lab A-B Storage Room third in from Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	C131	Art Lab A-B Storage Room near Entrance	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C131	Art Lab A-B Storage Room near Entrance	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C131	Art Lab A-B Storage Room near Entrance	W3	CMU	Multi	None	0	0	Negative
1	ML	C131	Art Lab A-B Storage Room near Entrance	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C131	Art Lab A-B Storage Room near Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C131	Art Lab A-B Storage Room near Entrance	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C131	Art Lab A-B Storage Room near Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	C131	Art Lab A-B Storage Room near Entrance	Pipe	Metal	White	Flaking	3	0.3	Negative
1	ML	C132	Art Lab A-B	W1	CMU	White	None	0	0	Negative
1	ML	C132	Art Lab A-B	W2	CMU	White	None	0	0	Negative
1	ML	C132	Art Lab A-B	W3	CMU	White	None	0	0	Negative
1	ML	C132	Art Lab A-B	W4	CMU	White	None	0	0	Negative
1	ML	C132	Art Lab A-B	Ceiling	Concrete	Blue	None	0	0	Negative
1	ML	C132	Art Lab A-B	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	C132	Art Lab A-B	Door Casing	Metal	White	None	0	0	Negative
1	ML	C132	Art Lab A-B	Pipe	Metal	White	Flaking	3	0.1	Negative
1	ML	C132	Art Lab A-B	Duct	Metal	Blue	None	0	0.4	Negative
1	ML	C133	Security Office (NTA) Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C133	Security Office (NTA) Storage Room	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	C133	Security Office (NTA) Storage Room	Door	Metal	White	None	0	0	Negative
1	ML	C133	Security Office (NTA) Storage Room	Pipe	Metal	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	W1	CMU	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	W2	CMU	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	W3	CMU	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	W4	CMU	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	Ceiling	Concrete	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	C134	Security Office (NTA)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C134	Security Office (NTA)	Door Casing	Metal	White	None	0	0	Negative
1	ML	C134	Security Office (NTA)	Door	Metal	White	None	0	0	Negative
1	ML	C136	Cage Storage Area in "Ante Room"	W1	CMU	Blue	None	0	0.1	Negative
1	ML	C136	Cage Storage Area in "Ante Room"	W2	CMU	Blue	None	0	0.2	Negative
1	ML	C136	Cage Storage Area in "Ante Room"	W3	CMU	Blue	None	0	0.3	Negative
1	ML	C136	Cage Storage Area in "Ante Room"	W4	CMU	Blue	None	0	0.4	Negative
1	ML	C136	Cage Storage Area in "Ante Room"	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C136	Cage Storage Area in "Ante Room"	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	C137	Storage Room with Walk-in Refrigerator and Freezer across from Art Lab A-B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	G101	Classroom G-101	W1	CMU	White	None	0	0	Negative
1	ML	G101	Classroom G-101	W2	CMU	White	None	0	0	Negative
1	ML	G101	Classroom G-101	W3	CMU	White	None	0	0	Negative
1	ML	G101	Classroom G-101	W4	CMU	White	None	0	0	Negative
1	ML	G101	Classroom G-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	G101	Classroom G-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	G101	Classroom G-101	Duct	Metal	Yellow	None	0	0.3	Negative
1	ML	G101	Classroom G-101	Door Casing	Metal	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	Ceiling	Concrete	White	None	0	0	Negative
1	ML	G101A	Classroom G-101 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	G101A	Classroom G-101 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	G102	Classroom G-102	W1	CMU	White	None	0	0	Negative
1	ML	G102	Classroom G-102	W2	CMU	White	None	0	0	Negative
1	ML	G102	Classroom G-102	W3	Sheetrock	White	None	0	0	Negative
1	ML	G102	Classroom G-102	W4	CMU	White	None	0	0	Negative
1	ML	G102	Classroom G-102	Ceiling	Concrete	White	None	0	0	Negative
1	ML	G102	Classroom G-102	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	G102	Classroom G-102	Duct	Metal	Yellow	None	0	0	Negative
1	ML	G102	Classroom G-102	Pipe	Metal	Yellow	None	0	0	Negative
1	ML	G102	Classroom G-102	Door Casing	Metal	White	None	0	0	Negative
1	ML	G103	Classroom G-103	W1	CMU	White	None	0	0	Negative
1	ML	G103	Classroom G-103	W2	Sheetrock	White	None	0	0	Negative
1	ML	G103	Classroom G-103	W3	CMU	White	None	0	0	Negative
1	ML	G103	Classroom G-103	W4	Sheetrock	White	None	0	0	Negative
1	ML	G103	Classroom G-103	Ceiling	Concrete	White	None	0	0	Negative
1	ML	G103	Classroom G-103	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	G103	Classroom G-103	Pipe	Metal	Yellow	None	0	0.4	Negative
1	ML	G103	Classroom G-103	Duct	Metal	Yellow	None	0	0.4	Negative
1	ML	G103	Classroom G-103	Door Casing	Metal	White	None	0	0	Negative
1	ML	G104	Classroom G-104	W1	CMU	White	None	0	0	Negative
1	ML	G104	Classroom G-104	W2	Sheetrock	White	None	0	0	Negative
1	ML	G104	Classroom G-104	W3	CMU	White	None	0	0	Negative
1	ML	G104	Classroom G-104	W4	Sheetrock	White	None	0	0	Negative
1	ML	G104	Classroom G-104	Ceiling	Concrete	White	None	0	0	Negative
1	ML	G104	Classroom G-104	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	G104	Classroom G-104	Pipe	Metal	Yellow	None	0	0.3	Negative
1	ML	G104	Classroom G-104	Duct	Metal	Yellow	None	0	0.4	Negative
1	ML	G104	Classroom G-104	Door Casing	Metal	White	None	0	0	Negative
1	ML	G105	Classroom G-105	W1	CMU	White	None	0	0	Negative
1	ML	G105	Classroom G-105	W2	CMU	White	None	0	0	Negative
1	ML	G105	Classroom G-105	W3	CMU	White	None	0	0	Negative
1	ML	G105	Classroom G-105	W4	Sheetrock	White	None	0	0	Negative
1	ML	G105	Classroom G-105	Ceiling	Concrete	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	G105	Classroom G-105	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	G105	Classroom G-105	Pipe	Metal	Yellow	None	0	0.4	Negative
1	ML	G105	Classroom G-105	Duct	Metal	Yellow	None	0	0.2	Negative
1	ML	G105	Classroom G-105	Door Casing	Metal	White	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	W1	CMU	White	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	W2	CMU	White	None	0	0.9	Positive
1	ML	H01	Hallway from Boy's Restroom to Security Office	W3	CMU	White	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	W4	CMU	White	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H01	Hallway from Boy's Restroom to Security Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H01	Hallway from Boy's Restroom to Security Office	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	Door	Metal	Blue	None	0	0	Negative
1	ML	H01	Hallway from Boy's Restroom to Security Office	Cove Base	CMU	Black	None	0	0.9	Positive
1	ML	H02	Hallway between Auditorium and Music Rooms	W1	CMU	White	None	0	1.3	Positive
1	ML	H02	Hallway between Auditorium and Music Rooms	W2	CMU	White	None	0	1.8	Positive
1	ML	H02	Hallway between Auditorium and Music Rooms	W3	CMU	White	None	0	0.1	Negative
1	ML	H02	Hallway between Auditorium and Music Rooms	W4	CMU	White	None	0	0	Negative
1	ML	H02	Hallway between Auditorium and Music Rooms	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H02	Hallway between Auditorium and Music Rooms	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	B104	Classroom O-106	Door	Metal	Blue	None	0	0.2	Negative
1	ML	B104	Classroom O-107	Door Casing	Metal	Blue	None	0	0.2	Negative
1	ML	B104	Classroom O-108	Cove Base	CMU	Black	None	0	0.8	Positive
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	W1	CMU	White	None	0	0	Negative
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	W2	CMU	White	None	0	0	Negative
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	W3	CMU	White	None	0	0	Negative
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	W4	CMU	White	None	0	1.3	Positive
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H03	Hallway from Computer Lab A to Computer Lab C	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H04	Hallway along back of Stage and Maintenance Areas	W1	CMU	White	None	0	1.4	Positive
1	ML	H04	Hallway along back of Stage and Maintenance Areas	W2	CMU	White	None	0	0	Negative
1	ML	H04	Hallway along back of Stage and Maintenance Areas	W3	CMU	White	None	0	0	Negative
1	ML	H04	Hallway along back of Stage and Maintenance Areas	W4	CMU	White	None	0	0	Negative
1	ML	H04	Hallway along back of Stage and Maintenance Areas	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H04	Hallway along back of Stage and Maintenance Areas	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H04	Hallway along back of Stage and Maintenance Areas	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	W1	CMU	White	None	0	0	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	W2	CMU	White	None	0	0	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	W3	CMU	White	None	0	1.2	Positive
1	ML	H05	Hallway between Auditorium and Main Entrance	W4	CMU	White	None	0	0.2	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05	Hallway between Auditorium and Main Entrance	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05	Hallway between Auditorium and Main Entrance	Door	Metal	Blue	None	0	0.3	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	Door Casing	Metal	Blue	None	0	0.2	Negative
1	ML	H05	Hallway between Auditorium and Main Entrance	Cove Base	CMU	Black	None	0	1.3	Positive
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	W1	CMU	White	Flaking	25	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	W2	CMU	White	None	0	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	W3	CMU	White	Flaking	50	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	W4	CMU	White	Flaking	10	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	Pipe	Metal	White	Flaking	10	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	Door Casing	Metal	White	None	0	0	Negative
1	ML	H05A	Small Storage Room&nbsp;in Hallway between Auditorium and Main Entrance	Duct	Metal	White	None	0	0	Negative
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	Door Casing	Metal	White	None	0	0	Negative
1	ML	H05B	Large Storage Room in Hallway between Auditorium and Main Entrance (Under Stairs)	Door	Metal	White	None	0	0	Negative
1	ML	H101	Classroom H-101	W1	CMU	White	None	0	0	Negative
1	ML	H101	Classroom H-101	W2	CMU	White	None	0	0	Negative
1	ML	H101	Classroom H-101	W3	CMU	White	None	0	0	Negative
1	ML	H101	Classroom H-101	W4	CMU	White	None	0	0	Negative
1	ML	H101	Classroom H-101	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H101	Classroom H-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H101	Classroom H-101	Door Casing	Metal	White	None	0	0	Negative
1	ML	H101	Classroom H-101	Pipe	Metal	White	None	0	0.3	Negative
1	ML	H120	Center Atrium near Gym	W1	Concrete	Blue	None	0	0	Negative
1	ML	H120	Center Atrium near Gym	W2	Concrete	Blue	None	0	0	Negative
1	ML	H120	Center Atrium near Gym	W3	Concrete	Blue	None	0	0	Negative
1	ML	H120	Center Atrium near Gym	W4	Concrete	Blue	None	0	0	Negative
1	ML	H120	Center Atrium near Gym	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H120	Center Atrium near Gym	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H120	Center Atrium near Gym	Pillar	Concrete	Multi	None	0	0	Negative



		Dates: 10/16/2023-01/29/2024		Lead-Safe Certification Assessment Report						
		Inspector Name and Certificate Number: Erika Barron 007296		Baldi School						
		Inspection Company: Criterion Labs Inc		8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H120A	Hallway around Atrium	W1	CMU	Multi	None	0	1.3	Positive
1	ML	H120A	Hallway around Atrium	W2	CMU	Multi	None	0	0	Negative
1	ML	H120A	Hallway around Atrium	W3	CMU	Multi	None	0	2.1	Positive
1	ML	H120A	Hallway around Atrium	W4	CMU	Multi	None	0	0	Negative
1	ML	H120A	Hallway around Atrium	W5	CMU	Multi	None	0	1.1	Positive
1	ML	H120A	Hallway around Atrium	W6	CMU	Multi	None	0	0	Negative
1	ML	H120A	Hallway around Atrium	W7	CMU	Multi	None	0	1.2	Positive
1	ML	H120A	Hallway around Atrium	W8	CMU	Multi	None	0	0	Negative
1	ML	H120A	Hallway around Atrium	Ceiling	concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H120A	Hallway around Atrium	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H120A	Hallway around Atrium	Door	Metal	Blue	None	0	0.1	Negative
1	ML	H120A	Hallway around Atrium	Door Casing	Metal	Blue	None	0	0.8	Positive
1	ML	H120B	Hallway outside Art Lab A-B	W1	CMU	White	None	0	1.1	Positive
1	ML	H120B	Hallway outside Art Lab A-B	W2	CMU	White	None	0	0.1	Negative
1	ML	H120B	Hallway outside Art Lab A-B	W4	CMU	White	None	0	0	Negative
1	ML	H120B	Hallway outside Art Lab A-B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H120B	Hallway outside Art Lab A-B	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H120B	Hallway outside Art Lab A-B	Cove Base	CMU	Black	None	0	0.7	Positive
1	ML	H120B	Hallway outside Art Lab A-B	Door Casing	Metal	Blue	None	0	0.8	Positive
1	ML	H120B	Hallway outside Art Lab A-B	Door	Metal	Blue	None	0	0	Negative
1	ML	H121	Hallway and Stairs between Commons Area and Gym	W1	CMU	Blue	None	0	1.4	Positive
1	ML	H121	Hallway and Stairs between Commons Area and Gym	W2	CMU	Blue	None	0	1.6	Positive
1	ML	H121	Hallway and Stairs between Commons Area and Gym	W3	CMU	Blue	None	0	1.8	Positive
1	ML	H121	Hallway and Stairs between Commons Area and Gym	W4	CMU	Blue	None	0	1.3	Positive
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Door	Metal	Blue	None	0	0.5	Negative
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Door Casing	Metal	Blue	None	0	0.7	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Cove Base	CMU	Black	None	0	1	Positive
1	ML	H121	Hallway and Stairs between Commons Area and Gym	Panel	Metal	Blue	None	0	0.9	Positive
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	W1	CMU	White	None	0	0	Negative
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	W2	CMU	White	None	0	1.1	Positive
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	W3	CMU	White	None	0	0	Negative
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	W4	CMU	White	None	0	1.9	Positive
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Door Casing	Metal	White	None	0	0.4	Negative
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Pillar	Concrete	Orange	None	0	0	Negative
1	ML	H122	Hallway from Classroom Y-101 to Classroom O-101	Pillar	Concrete	Yellow	None	0	0	Negative
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	W1	CMU	White	None	0	0.7	Positive
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	W2	CMU	White	None	0	0.7	Positive
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	W3	CMU	White	None	0	0.7	Positive
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	W4	CMU	White	None	0	0.4	Negative
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	Door Casing	Metal	White	None	0	0.7	Positive
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	Cove Base	CMU	Black	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H122A	Hallway from Classroom H-101 to Classroom Y-101	Door	Metal	White	None	0	0	Negative
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	W1	CMU	White	None	0	1.1	Positive
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	W2	CMU	White	None	0	1	Positive
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	W3	CMU	White	None	0	1.4	Positive
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	W4	CMU	White	None	0	0	Negative
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	Door Casing	Metal	White	None	0	0.3	Negative
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	Cove Base	CMU	Black	None	0	0.7	Positive
1	ML	H122B	Hallway from Classroom H-101 to Classroom O-101	Door	Metal	White	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	W1	CMU	White	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	W2	CMU	White	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	W3	CMU	White	None	0	0.1	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	W4	CMU	White	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Pillar	Concrete	Black	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Pillar	Concrete	Yellow	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Door Casing	Metal	White	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Cove Base	CMU	Black	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Door Casing	Metal	Red	None	0	0	Negative
1	ML	H123	Hallway from Classroom G-105 to Kitchen Pantry B	Grate	Metal	White	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	W1	CMU	White	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	W2	CMU	White	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	W3	CMU	White	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	W4	CMU	White	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Door Casing	Metal	Green	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Door	Metal	Blue	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Door Casing	Metal	White	None	0	0.9	Positive
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Pillar	Concrete	Black	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Pillar	Concrete	Green	None	0	0	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Pipe	Metal	Green	None	0	0.3	Negative
1	ML	H123A	Hallway from Teacher's Lounge to Classroom G-104	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H124	Teacher's Lounge	W1	CMU	Blue	None	0	0	Negative
1	ML	H124	Teacher's Lounge	W2	CMU	Blue	None	0	0	Negative
1	ML	H124	Teacher's Lounge	W3	CMU	Blue	None	0	0	Negative
1	ML	H124	Teacher's Lounge	W4	Sheetrock	White	None	0	0	Negative
1	ML	H124	Teacher's Lounge	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H124	Teacher's Lounge	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H124	Teacher's Lounge	Door Casing	Metal	Grey	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H124A	Computer Server Room next to Teacher's Lounge	W1	Sheetrock	White	None	0	0	Negative
1	ML	H124A	Computer Server Room next to Teacher's Lounge	W2	CMU	Blue	None	0	0	Negative
1	ML	H124A	Computer Server Room next to Teacher's Lounge	W3	CMU	Blue	None	0	0	Negative
1	ML	H124A	Computer Server Room next to Teacher's Lounge	W4	CMU	Blue	None	0	0	Negative
1	ML	H124A	Computer Server Room next to Teacher's Lounge	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H124A	Computer Server Room next to Teacher's Lounge	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H124A	Computer Server Room next to Teacher's Lounge	Door Casing	Metal	Brown	None	0	0	Negative
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	W1	CMU	White	None	0	0	Negative
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	W2	CMU	White	None	0	0	Negative
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	W3	CMU	White	None	0	0	Negative
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	W4	CMU	White	None	0	0	Negative
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H125	Hallway from Classroom B-104 to Storage Room next to Food Service Manager's Office	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	W1	CMU	White	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	W2	CMU	White	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	W3	CMU	White	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	W4	CMU	White	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Pillar	Concrete	Orange	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Pillar	Concrete	Black	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Door Casing	Metal	White	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Door Casing	Metal	Orange	None	0	0	Negative
1	ML	H125A	Hallway from Lockers near Classroom O-102 to Classroom B-105	Cove Base	CMU	Black	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	W1	CMU	White	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	W2	CMU	White	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	W3	CMU	White	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	W4	CMU	White	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H126	Food Service Manager's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H126	Food Service Manager's Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	H126A	Food Service Manager's Office Restroom	W1	CMU	White	None	0	0	Negative
1	ML	H126A	Food Service Manager's Office Restroom	W2	CMU	White	None	0	0	Negative
1	ML	H126A	Food Service Manager's Office Restroom	W3	CMU	White	None	0	0	Negative
1	ML	H126A	Food Service Manager's Office Restroom	W4	CMU	White	None	0	0	Negative
1	ML	H126A	Food Service Manager's Office Restroom	Ceiling	Concrete	White	Flaking	10	0.1	Negative
1	ML	H126A	Food Service Manager's Office Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H126A	Food Service Manager's Office Restroom	Univent	Metal	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	W1	CMU	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	W2	CMU	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	W3	CMU	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	W4	CMU	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H127-ML	Storage Room next to Food Service Manager's Office	Door Casing	Metal	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	W1	CMU	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	W2	CMU	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	W3	CMU	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	W4	CMU	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Pipe	Metal	White	None	0	0.1	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Duct	Metal	White	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Door Casing	Metal	Red	None	0	0	Negative
1	ML	H146	Kitchen Pantry   B for the Orange and Yellow Cafeterias	Cove Base	CMU	Red	None	0	0	Negative
1	ML	H148	Yellow Cafeteria	W1	CMU	Red	None	0	1.2	Positive
1	ML	H148	Yellow Cafeteria	W2	CMU	White	None	0	0	Negative
1	ML	H148	Yellow Cafeteria	W3	CMU	White	None	0	0	Negative
1	ML	H148	Yellow Cafeteria	W4	CMU	White	None	0	0	Negative
1	ML	H148	Yellow Cafeteria	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H148	Yellow Cafeteria	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H148	Yellow Cafeteria	Duct	Metal	White	None	0	0.5	Negative
1	ML	H148	Yellow Cafeteria	Door Casing	Metal	Red	None	0	0.4	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	W1	CMU	Green	None	0	0	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	W2	CMU	Green	None	0	0	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	W3	CMU	Green	None	0	0	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	W4	CMU	Green	None	0	0	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H149	Boy's Restroom across from Classroom Y-104	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H150	Women's Restroom across from Classroom G-102	W1	CMU	Green	None	0	0	Negative
1	ML	H150	Women's Restroom across from Classroom G-102	W2	CMU	Green	None	0	0	Negative
1	ML	H150	Women's Restroom across from Classroom G-102	W3	CMU	Green	None	0	0	Negative
1	ML	H150	Women's Restroom across from Classroom G-102	W4	CMU	Green	None	0	0	Negative
1	ML	H150	Women's Restroom across from Classroom G-102	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H150	Women's Restroom across from Classroom G-102	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H150A	Custodial Closet next to Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	H151	Green Cafeteria	W1	CMU	Green	None	0	0	Negative
1	ML	H151	Green Cafeteria	W2	CMU	White	None	0	0	Negative
1	ML	H151	Green Cafeteria	W3	CMU	White	None	0	0	Negative
1	ML	H151	Green Cafeteria	W4	CMU	White	None	0	0	Negative
1	ML	H151	Green Cafeteria	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H151	Green Cafeteria	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H151	Green Cafeteria	Duct	Metal	White	None	0	0.4	Negative
1	ML	H151	Green Cafeteria	Door Casing	Metal	Green	None	0	0	Negative
1	ML	H154	Kitchen Pantry    A for the    Blue and Green Cafeterias	W1	CMU	White	None	0	0	Negative
1	ML	H154	Kitchen Pantry    A for the    Blue and Green Cafeterias	W2	CMU	White	None	0	0	Negative
1	ML	H154	Kitchen Pantry    A for the    Blue and Green Cafeterias	W3	CMU	White	None	0	0	Negative
1	ML	H154	Kitchen Pantry    A for the    Blue and Green Cafeterias	W4	CMU	White	None	0	0	Negative
1	ML	H154	Kitchen Pantry    A for the    Blue and Green Cafeterias	Ceiling	Concrete	White	None	0	0	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H154	Kitchen Pantry&nbsp;A for the&nbsp;Blue and Green Cafeterias	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H154	Kitchen Pantry&nbsp;A for the&nbsp;Blue and Green Cafeterias	Pipe	Metal	White	None	0	0.2	Negative
1	ML	H154	Kitchen Pantry&nbsp;A for the&nbsp;Blue and Green Cafeterias	Door Casing	Metal	Red	None	0	0	Negative
1	ML	H154	Kitchen Pantry&nbsp;A for the&nbsp;Blue and Green Cafeterias	Cove Base	CMU	Red	None	0	0	Negative
1	ML	H154	Kitchen Pantry&nbsp;A for the&nbsp;Blue and Green Cafeterias	Duct	Metal	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	W1	CMU	Blue	None	0	0	Negative
1	ML	H155	Blue Cafeteria	W2	CMU	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	W3	CMU	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	W4	CMU	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H155	Blue Cafeteria	Duct	Metal	White	None	0	0	Negative
1	ML	H155	Blue Cafeteria	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	W1	CMU	Green	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	W2	CMU	Green	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	W3	CMU	Green	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	W4	CMU	Green	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H156	Women's Restroom near Classroom B-102	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	H156	Women's Restroom near Classroom B-102	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	W1	CMU	Green	None	0	0.1	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	W2	CMU	Green	None	0	0	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	W3	CMU	Green	None	0	0.1	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	W4	CMU	Green	None	0	0	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H157	Men's Restroom across from Classroom O-104	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	ML	H157	Men's Restroom across from Classroom O-104	Door Casing	Metal	Green	None	0	0	Negative
1	ML	H158	Orange Cafeteria	W1	CMU	Orange	None	0	1.3	Positive
1	ML	H158	Orange Cafeteria	W2	CMU	White	None	0	0	Negative
1	ML	H158	Orange Cafeteria	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	H158	Orange Cafeteria	W4	CMU	White	None	0	0	Negative
1	ML	H158	Orange Cafeteria	Ceiling	Concrete	White	None	0	0	Negative
1	ML	H158	Orange Cafeteria	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	H158	Orange Cafeteria	Duct	Metal	White	None	0	1.1	Positive
1	ML	H158	Orange Cafeteria	Door Casing	Metal	Orange	None	0	0	Negative
1	ML	O101	Classroom B-101	W1	CMU	White	None	0	0	Negative
1	ML	O101	Classroom B-101	W2	CMU	White	None	0	0	Negative
1	ML	O101	Classroom B-101	W3	CMU	White	None	0	0	Negative
1	ML	O101	Classroom B-101	W4	CMU	White	None	0	0	Negative
1	ML	O101	Classroom B-101	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O101	Classroom B-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	O101	Classroom B-101	Door Casing	Metal	White	None	0	0	Negative
1	ML	O101	Classroom B-101	Duct	Metal	Yellow	None	0	0.4	Negative
1	ML	O101A	Classroom B-101 Storage Room	W1	CMU	White	None	0	0	Negative
1	ML	O101A	Classroom B-101 Storage Room	W2	CMU	White	None	0	0	Negative
1	ML	O101A	Classroom B-101 Storage Room	W3	CMU	White	None	0	0	Negative
1	ML	O101A	Classroom B-101 Storage Room	W4	CMU	White	None	0	0	Negative
1	ML	O101A	Classroom B-101 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O101A	Classroom B-101 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	O101A	Classroom B-101 Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	ML	O102	Classroom B-102	W1	CMU	White	None	0	0	Negative
1	ML	O102	Classroom B-102	W2	CMU	White	None	0	0	Negative
1	ML	O102	Classroom B-102	W3	CMU	White	None	0	0	Negative
1	ML	O102	Classroom B-102	W4	CMU	White	None	0	0	Negative
1	ML	O102	Classroom B-102	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O102	Classroom B-102	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	O102	Classroom B-102	Duct	Metal	Yellow	None	0	0.2	Negative
1	ML	O102	Classroom B-102	Door Casing	Metal	White	None	0	0	Negative
1	ML	O102	Classroom B-102	Pipe	Metal	Blue	None	0	0.1	Negative
1	ML	O103	Classroom B-103	W1	CMU	White	None	0	0	Negative
1	ML	O103	Classroom B-103	W2	CMU	White	None	0	0	Negative
1	ML	O103	Classroom B-103	W3	CMU	White	None	0	0	Negative
1	ML	O103	Classroom B-103	W4	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	O103	Classroom B-103	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O103	Classroom B-103	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	O103	Classroom B-103	Pipe	Metal	White	None	0	0.2	Negative
1	ML	O103	Classroom B-103	Duct	Metal	Yellow	None	0	0.3	Negative
1	ML	O103	Classroom B-103	Door Casing	Metal	White	None	0	0	Negative
1	ML	O104	Classroom B-104	W1	CMU	White	None	0	0	Negative
1	ML	O104	Classroom B-104	W2	CMU	White	None	0	0	Negative
1	ML	O104	Classroom B-104	W3	CMU	White	None	0	0	Negative
1	ML	O104	Classroom B-104	W4	CMU	White	None	0	0	Negative
1	ML	O104	Classroom B-104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O104	Classroom B-104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O104	Classroom B-104	Pipe	Metal	Blue	None	0	0.2	Negative
1	ML	O104	Classroom B-104	Duct	Metal	Yellow	None	0	0.4	Negative
1	ML	O104	Classroom B-104	Door Casing	Metal	White	None	0	0	Negative
1	ML	O105	Classroom B-105	W1	CMU	White	None	0	0	Negative
1	ML	O105	Classroom B-105	W2	CMU	White	None	0	0	Negative
1	ML	O105	Classroom B-105	W3	CMU	White	None	0	0	Negative
1	ML	O105	Classroom B-105	W4	CMU	White	None	0	0	Negative
1	ML	O105	Classroom B-105	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	O105	Classroom B-105	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	O105	Classroom B-105	Pipe	Metal	Blue	None	0	0.2	Negative
1	ML	O105	Classroom B-105	Duct	Metal	Yellow	None	0	0.3	Negative
1	ML	O105	Classroom B-105	Door Casing	Metal	White	None	0	0	Negative
1	ML	PC122	Pipe chase in hallway near gym 2	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122	Pipe chase in hallway near gym 2	Door	Metal	Blue	None	0	0	Negative
1	ML	PC122.1	Pipe chase in hall next to gym 1	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122.1	Pipe chase in hall next to gym 1	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122.1	Pipe chase in hall next to gym 1	W3	CMU	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	PC122.1	Pipe chase in hall next to gym 1	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122.1	Pipe chase in hall next to gym 1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122.1	Pipe chase in hall next to gym 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PC122.1	Pipe chase in hall next to gym 1	Door	Metal	Blue	None	0	0	Negative
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCA105	Pipe Chase in Gender neutral Restroom near Instrument Music Room	Door	Metal	White	None	0	0	Negative
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCC117	Pipe Chase in Girl's Restroom next to Women's Restroom	Door	Metal	Green	None	0	0	Negative
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	W3	CMU	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH127	Pipe Chase in Storage Room next to Food Service Manager's Office	Door	Metal	White	None	0	0	Negative
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	PCH150	Pipe Chase in Women's Restroom across from Classroom G-102	Door	Metal	Green	None	0	0	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	W1	CMU	Blue	None	0	0.1	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	W2	CMU	Blue	None	0	0.1	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	W3	CMU	Blue	None	0	0.1	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	W4	CMU	Blue	None	0	0.1	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Door Casing	Metal	Blue	None	0	0.1	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Door	Metal	Blue	None	0	0	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Hand Rail	Metal	Blue	Friction	6	0.1	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Stair stringer	Metal	White	None	0	0	Negative
1	ML	S012	Stairwell next to Instrument Music Room and Boy's Restroom	Univent	Metal	Blue	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	W1	CMU	White	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	W2	CMU	White	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	W4	CMU	White	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Hand Rail	Metal	Black	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Cove Base	CMU	Black	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Door	Metal	Blue	None	0	0	Negative
1	ML	S013	Stairwell A1/ 2ML Mezzanine Area	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	W1	CMU	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	W2	CMU	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	W3	CMU	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	W4	CMU	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	Ceiling	Concrete	White	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	S014	Stairwell near Computer Lab A	Door Casing	Metal	Blue	None	0	0.1	Negative
1	ML	S014	Stairwell near Computer Lab A	Door	Metal	Blue	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	Hand Rail	Metal	Blue	Friction	5	0	Negative
1	ML	S014	Stairwell near Computer Lab A	Stair Stringer	Metal	White	None	0	0	Negative
1	ML	S014	Stairwell near Computer Lab A	Univent	Metal	Blue	None	0	0	Negative
1	ML	S110	Stairwell next to Classroom B-102	W1	CMU	Blue	None	0	0.8	Positive
1	ML	S110	Stairwell next to Classroom B-102	W2	CMU	Blue	None	0	1.1	Positive
1	ML	S110	Stairwell next to Classroom B-102	W3	CMU	Blue	None	0	1.2	Positive
1	ML	S110	Stairwell next to Classroom B-102	W4	CMU	Blue	None	0	1.1	Positive
1	ML	S110	Stairwell next to Classroom B-102	Ceiling	Concrete	White	None	0	Assumed	Assumed
1	ML	S110	Stairwell next to Classroom B-102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	S110	Stairwell next to Classroom B-102	Hand Rail	Metal	Blue	None	0	0.4	Negative
1	ML	S110	Stairwell next to Classroom B-102	Stair stringer	Concrete	Black	None	0	0	Negative
1	ML	S110	Stairwell next to Classroom B-102	Door	Metal	Blue	None	0	0.5	Negative
1	ML	S110	Stairwell next to Classroom B-102	Door Casing	Metal	Blue	None	0	0.8	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	W1	CMU	Green	None	0	1.5	Positive
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	W2	CMU	Green	None	0	1.5	Positive
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	W3	CMU	Green	None	0	1.2	Positive
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	W4	CMU	Green	None	0	1.2	Positive
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Ceiling	Concrete	White	None	0	1.9	Positive
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Hand Rail	Metal	Blue	Friction	25	0	Negative
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Stair stringer	Metal	Blue	None	0	0	Negative
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Stairs	Metal	Blue	None	0	0	Negative
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Door	Metal	Blue	None	0	0.3	Negative
1	ML	S117	Stairwell C-7 near Art Lab A-B Office	Door Casing	Metal	Blue	None	0	0.9	Positive
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	W1	CMU	White	None	0	1.3	Positive
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	W2	CMU	White	None	0	1.6	Positive
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	W3	CMU	White	None	0	1.2	Positive
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	W4	CMU	White	None	0	1.2	Positive
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Ceiling	Concrete	White	None	0	0	Negative
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Door	Metal	Blue	None	0	0	Negative
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Hand Rail	Metal	Blue	Friction	5	0	Negative
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Stair stringer	concrete	Blue	None	0	0	Negative
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	S118	Stairwell and Hallway around Stairwell between Art Lab C-D and Boy's Restroom	grate	Metal	White	None	0	0	Negative
1	ML	S18	Stairwell (S-10) next to Classroom G-102	W1	CMU	Blue	None	0	1.2	Positive
1	ML	S18	Stairwell (S-10) next to Classroom G-102	W2	CMU	Blue	None	0	1.2	Positive
1	ML	S18	Stairwell (S-10) next to Classroom G-102	W3	CMU	Blue	None	0	0.5	Negative
1	ML	S18	Stairwell (S-10) next to Classroom G-102	W4	CMU	Blue	None	0	1.1	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Ceiling	Concrete	White	None	0	0	Negative
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Door Casing	Metal	Blue	None	0	1	Positive
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Door	Metal	Blue	None	0	0	Negative
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Hand Rail	Metal	Blue	Friction	5	0	Negative
1	ML	S18	Stairwell (S-10) next to Classroom G-102	Stair stringer	Metal	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	W1	CMU	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	W2	CMU	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	W3	CMU	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	W4	CMU	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	Ceiling	Concrete	Blue	None	0	0	Negative
1	ML	Y101	Classroom Y-101	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y101	Classroom Y-101	Door Casing	Metal	White	None	0	0	Negative
1	ML	Y101	Classroom Y-101	Duct	Metal	Blue	None	0	0.4	Negative
1	ML	Y101	Classroom Y-101	Pole	Metal	Blue	None	0	0	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	W1	CMU	White	Flaking	15	0	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	W2	CMU	White	Flaking	25	0	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	W3	CMU	White	Flaking	50	0	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	W4	CMU	White	Flaking	25	0	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y101A	Classroom Y-101 Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y101A	Classroom Y-101 Storage Room	Pipe	Metal	White	Flaking	8	0.2	Negative
1	ML	Y101A	Classroom Y-101 Storage Room	Door Casing	Metal	White	None	0	0.1	Negative
1	ML	Y102	Classroom Y-102	W1	CMU	White	None	0	0	Negative
1	ML	Y102	Classroom Y-102	W2	Sheetrock	White	None	0	0	Negative
1	ML	Y102	Classroom Y-102	W3	CMU	White	None	0	0	Negative
1	ML	Y102	Classroom Y-102	W4	Sheetrock	White	None	0	0	Negative
1	ML	Y102	Classroom Y-102	Ceiling	Concrete	White	None	0	0	Negative
1	ML	Y102	Classroom Y-102	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y102	Classroom Y-102	Duct	Metal	White	None	0	0.3	Negative
1	ML	Y102	Classroom Y-102	Door Casing	Metal	White	None	0	0	Negative
1	ML	Y103	Classroom Y-103	W1	CMU	White	None	0	0	Negative
1	ML	Y103	Classroom Y-103	W2	Sheetrock	White	None	0	0	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	ML	Y103	Classroom Y-103	W3	CMU	White	None	0	0	Negative
1	ML	Y103	Classroom Y-103	W4	Sheetrock	White	None	0	0	Negative
1	ML	Y103	Classroom Y-103	Ceiling	Concrete	White	None	0	0	Negative
1	ML	Y103	Classroom Y-103	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y103	Classroom Y-103	Duct	Metal	White	None	0	0.3	Negative
1	ML	Y103	Classroom Y-103	Door Casing	Metal	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	W1	CMU	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	W2	Sheetrock	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	W3	CMU	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	W4	Sheetrock	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	Ceiling	Concrete	White	None	0	0	Negative
1	ML	Y104	Classroom Y-104	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y104	Classroom Y-104	Duct	Metal	White	None	0	0.3	Negative
1	ML	Y104	Classroom Y-104	Door Casing	Metal	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	W1	CMU	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	W2	Sheetrock	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	W3	CMU	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	W4	CMU	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	Ceiling	Concrete	White	None	0	0	Negative
1	ML	Y105	Classroom Y-105	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	Y105	Classroom Y-105	Pipe	Metal	Yellow	None	0	0.4	Negative
1	ML	Y105	Classroom Y-105	Duct	Metal	Yellow	None	0	0.3	Negative
1	ML	Y105	Classroom Y-105	Door Casing	Metal	White	None	0	0	Negative
1	UL	A200	Room 200 Special Education Liason Office	W1	CMU	White	None	0	0	Negative
1	UL	A200	Room 200 Special Education Liason Office	W2	CMU	White	None	0	0	Negative
1	UL	A200	Room 200 Special Education Liason Office	W3	CMU	White	None	0	0	Negative
1	UL	A200	Room 200 Special Education Liason Office	W4	CMU	White	None	0	0	Negative
1	UL	A200	Room 200 Special Education Liason Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200	Room 200 Special Education Liason Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200	Room 200 Special Education Liason Office	Door Casing	Metal	White	None	0	0	Negative
1	UL	A200A	Room 200 Back office	W1	CMU	White	Flaking	25	0	Negative
1	UL	A200A	Room 200 Back office	W2	CMU	White	None	0	0	Negative
1	UL	A200A	Room 200 Back office	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A200A	Room 200 Back office	W4	CMU	White	None	0	0	Negative
1	UL	A200A	Room 200 Back office	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A200A	Room 200 Back office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200A	Room 200 Back office	Door Casing	Metal	White	None	0	0	Negative
1	UL	A200B	Room 200 Storage and Copy Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A200B	Room 200 Storage and Copy Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A201	Room 201	W1	CMU	White	None	0	0	Negative
1	UL	A201	Room 201	W2	CMU	White	None	0	0	Negative
1	UL	A201	Room 201	W3	CMU	White	None	0	0	Negative
1	UL	A201	Room 201	W4	CMU	White	None	0	0	Negative
1	UL	A201	Room 201	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A201	Room 201	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A201	Room 201	Pipe	Metal	Gray	None	0	0.2	Negative
1	UL	A201	Room 201	Door Casing	Metal	Gray	None	0	0	Negative
1	UL	A202	Classroom 202	W1	CMU	White	None	0	0	Negative
1	UL	A202	Classroom 202	W2	CMU	White	None	0	0	Negative
1	UL	A202	Classroom 202	W3	CMU	White	None	0	0	Negative
1	UL	A202	Classroom 202	W4	CMU	White	None	0	0	Negative
1	UL	A202	Classroom 202	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A202	Classroom 202	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A202	Classroom 202	Door Casing	Metal	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	W1	CMU	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	W2	CMU	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	W3	CMU	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	W4	CMU	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A202A	Classroom 202 Closet	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A202A	Classroom 202 Closet	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A203	Women's Restroom near Community Room	W1	CMU	Green	None	0	0	Negative
1	UL	A203	Women's Restroom near Community Room	W2	CMU	Green	None	0	0	Negative
1	UL	A203	Women's Restroom near Community Room	W3	CMU	Green	None	0	0	Negative
1	UL	A203	Women's Restroom near Community Room	W4	CMU	Green	None	0	0	Negative
1	UL	A203	Women's Restroom near Community Room	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A203	Women's Restroom near Community Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203	Women's Restroom near Community Room	Door Casing	Metal	Green	None	0	0	Negative
1	UL	A203A	Custodial Closet next to Women's Restroom	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A203A	Custodial Closet next to Women's Restroom	Door Casing	Metal	White	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	W1	CMU	Green	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	W2	CMU	Green	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	W3	CMU	Green	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	W4	CMU	Green	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A204	Girl's Restroom near Community Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	UL	A204	Girl's Restroom near Community Room	Pipe	Metal	Green	None	0	0.1	Negative
1	UL	A204	Girl's Restroom near Community Room	Door Casing	Metal	Green	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	W1	CMU	Green	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	W2	CMU	White	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	W3	CMU	White	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	W4	CMU	White	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	UL	A205	Men's Restroom near Community Room	Door Casing	Metal	Green	None	0	0	Negative
1	UL	A205	Men's Restroom near Community Room	Duct	Metal	White	None	0	0	Negative
1	UL	A206	Boy's Restroom near Community Room	W1	CMU	White	None	0	0	Negative
1	UL	A206	Boy's Restroom near Community Room	W2	CMU	White	None	0	0	Negative
1	UL	A206	Boy's Restroom near Community Room	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A206	Boy's Restroom near Community Room	W4	CMU	White	None	0	0	Negative
1	UL	A206	Boy's Restroom near Community Room	Ceiling	Concrete	White	None	0	0	Negative
1	UL	A206	Boy's Restroom near Community Room	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	UL	A206	Boy's Restroom near Community Room	Door Casing	Metal	Green	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-3	W1	CMU	White	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-3	W2	CMU	White	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-3	W3	CMU	White	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-4	W3	Concrete	White	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-3	W4	CMU	White	None	0	0	Negative
1	UL	A207	Room 205 Community Room next to Exit A-3	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207	Room 205 Community Room next to Exit A-3	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207	Room 205 Community Room next to Exit A-3	Door Casing	Metal	White	None	0	0	Negative
1	UL	A207A	Computer Server Room in Community Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207A	Computer Server Room in Community Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A207B	Storage Closet in Community Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A207B	Storage Closet in Community Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A208	Nurse's Office Waiting Area	W1	CMU	White	None	0	0	Negative
1	UL	A208	Nurse's Office Waiting Area	W2	CMU	White	None	0	0	Negative
1	UL	A208	Nurse's Office Waiting Area	W3	CMU	White	None	0	0	Negative
1	UL	A208	Nurse's Office Waiting Area	W4	CMU	White	None	0	0	Negative
1	UL	A208	Nurse's Office Waiting Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A208	Nurse's Office Waiting Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A208	Nurse's Office Waiting Area	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A208A	Nurse's Office Waiting Area Restroom	W1	CMU	Green	None	0	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	W2	CMU	Green	None	0	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	W3	CMU	Green	None	0	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	W4	CMU	Green	None	0	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	Ceiling	Concrete	White	Flaking	5	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A208A	Nurse's Office Waiting Area Restroom	Door Casing	Metal	Green	None	0	0	Negative
1	UL	A208A	Nurse's Office Waiting Area Restroom	Duct	Metal	White	Flaking	2	0	Negative
1	UL	A210	Nurse's Office	W1	CMU	White	None	0	0	Negative
1	UL	A210	Nurse's Office	W2	CMU	White	None	0	0	Negative
1	UL	A210	Nurse's Office	W3	CMU	White	None	0	0	Negative
1	UL	A210	Nurse's Office	W4	CMU	White	None	0	0	Negative
1	UL	A210	Nurse's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A210	Nurse's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A210	Nurse's Office	Pipe	Metal	White	None	0	0.3	Negative
1	UL	A210	Nurse's Office	Univent	Metal	White	None	0	0	Negative
1	UL	A211	Nurse's Office Storage Room	W1	CMU	White	None	0	0	Negative
1	UL	A211	Nurse's Office Storage Room	W2	CMU	White	None	0	0	Negative
1	UL	A211	Nurse's Office Storage Room	W3	CMU	White	Flaking	25	0	Negative
1	UL	A211	Nurse's Office Storage Room	W4	CMU	White	None	0	0	Negative
1	UL	A211	Nurse's Office Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A211	Nurse's Office Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A211	Nurse's Office Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A212	Vice Principal's Office next to Mail Room	W1	CMU	White	Flaking	15	0	Negative
1	UL	A212	Vice Principal's Office next to Mail Room	W2	CMU	White	Flaking	25	0	Negative
1	UL	A212	Vice Principal's Office next to Mail Room	W3	CMU	Yellow	None	0	0	Negative
1	UL	A212	Vice Principal's Office next to Mail Room	W4	CMU	White	Flaking	25	0	Negative
1	UL	A212	Vice Principal's Office next to Mail Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A212	Vice Principal's Office next to Mail Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A212	Vice Principal's Office next to Mail Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A213	Main Office Mail Room	W1	CMU	White	None	0	0	Negative
1	UL	A213	Main Office Mail Room	W2	CMU	White	None	0	0	Negative
1	UL	A213	Main Office Mail Room	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A213	Main Office Mail Room	W4	CMU	White	Flaking	20	0	Negative
1	UL	A213	Main Office Mail Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A213	Main Office Mail Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A213	Main Office Mail Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A214	Principal's Office	W1	CMU	White	None	0	0	Negative
1	UL	A214	Principal's Office	W2	CMU	White	None	0	0	Negative
1	UL	A214	Principal's Office	W3	CMU	White	None	0	0	Negative
1	UL	A214	Principal's Office	W4	Concrete	White	None	0	0	Negative
1	UL	A214	Principal's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A214	Principal's Office	Floor	Floor Tile	Unpainted	N/A	N/a	N/A	N/A
1	UL	A214	Principal's Office	Univent	Metal	Blue	None	0	0	Negative
1	UL	A214	Principal's Office	Pole	Metal	Blue	None	0	0.1	Negative
1	UL	A214	Principal's Office	Door Casing	Metal	Blue	None	0	0	Negative
1	UL	A216	Main Office	W1	CMU	White	None	0	0	Negative
1	UL	A216	Main Office	W2	CMU	White	None	0	0	Negative
1	UL	A216	Main Office	W3	CMU	White	None	0	0	Negative
1	UL	A216	Main Office	W4	CMU	White	None	0	0	Negative
1	UL	A216	Main Office	W4	CMU	White	None	0	0	Negative
1	UL	A216	Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A216	Main Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A216	Main Office	Door Casing	Metal	Blue	Friction	8	0	Negative
1	UL	A216	Main Office	Univent	Metal	Blue	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	W1	CMU	White	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	W2	CMU	White	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	W3	CMU	White	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	W4	CMU	White	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A218	Vice Principal's Office next to main office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A218	Vice Principal's Office next to main office	Pillar	Concrete	Blue	None	0	0	Negative
1	UL	A218	Vice Principal's Office next to main office	Door Casing	Metal	White	None	0	0	Negative
1	UL	A219	Main Office Storage Room	W1	CMU	White	None	0	0	Negative
1	UL	A219	Main Office Storage Room	W2	CMU	White	None	0	0	Negative
1	UL	A219	Main Office Storage Room	W3	CMU	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A219	Main Office Storage Room	W4	CMU	White	None	0	0	Negative
1	UL	A219	Main Office Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A219	Main Office Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A216	Main Office	Door Casing	Metal	Blue	Friction	8	0	Negative
1	UL	A220	Copy Room's Restroom	W1	CMU	Blue	None	0	0	Negative
1	UL	A220	Copy Room's Restroom	W2	Concrete	White	None	0	0.2	Negative
1	UL	A220	Copy Room's Restroom	W3	CMU	Blue	None	0	0	Negative
1	UL	A220	Copy Room's Restroom	W4	CMU	Blue	None	0	0	Negative
1	UL	A220	Copy Room's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A220	Copy Room's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	UL	A220	Copy Room's Restroom	Door Casing	Metal	White	None	0	0	Negative
1	UL	A221	Organization Room near Main Office	W1	CMU	White	None	0	0	Negative
1	UL	A221	Organization Room near Main Office	W2	CMU	White	None	0	0	Negative
1	UL	A221	Organization Room near Main Office	W3	CMU	White	None	0	0	Negative
1	UL	A221	Organization Room near Main Office	W4	CMU	White	None	0	0	Negative
1	UL	A221	Organization Room near Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A221	Organization Room near Main Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A221	Organization Room near Main Office	Door Casing	Metal	White	None	0	0	Negative
1	UL	A221A	Hallway from Hall next to Organization Room to Roster Office	W1	CMU	White	None	0	0	Negative
1	UL	A221A	Hallway from Hall next to Organization Room to Roster Office	W3	CMU	White	None	0	0	Negative
1	UL	A221A	Hallway from Hall next to Organization Room to Roster Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A221A	Hallway from Hall next to Organization Room to Roster Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A221A	Hallway from Hall next to Organization Room to Roster Office	Door Casing	Metal	White	None	0	0	Negative
1	UL	A222	Roster Office in Main Office	W1	CMU	White	None	0	0	Negative
1	UL	A222	Roster Office in Main Office	W2	CMU	White	Flaking	25	0	Negative
1	UL	A222	Roster Office in Main Office	W3	CMU	White	Flaking	15	0	Negative
1	UL	A222	Roster Office in Main Office	W4	CMU	White	Flaking	20	0	Negative
1	UL	A222	Roster Office in Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A222	Roster Office in Main Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A222	Roster Office in Main Office	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	A225	Copy Room in back right corner of Main Office	W1	CMU	White	None	0	0	Negative
1	UL	A225	Copy Room in back right corner of Main Office	W2	CMU	White	None	0	0	Negative
1	UL	A225	Copy Room in back right corner of Main Office	W3	CMU	White	None	0	0	Negative
1	UL	A225	Copy Room in back right corner of Main Office	W4	CMU	White	None	0	0	Negative
1	UL	A225	Copy Room in back right corner of Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A225	Copy Room in back right corner of Main Office	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240	Home Economics A (includes three classrooms)	W1	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W2	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W3	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W4	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240	Home Economics A (includes three classrooms)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240	Home Economics A (includes three classrooms)	Door Casing	Metal	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	Duct	Metal	Yellow	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	Pipe	Metal	Yellow	None	0	0.1	Negative
1	UL	A240B	Home Economics A Mid-Left Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A240B	Home Economics A Mid-Left Storage Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A239	Electrical/Transformer Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	A239	Electrical/Transformer Room	Door Casing	Metal	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W1	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W2	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W3	CMU	White	None	0	0	Negative
1	UL	A240	Home Economics A (includes three classrooms)	W4	CMU	White	None	0	0	Negative



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School							
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115							
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	UL	A240	Home Economics A (includes three classrooms)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	Duct	Metal	Yellow	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	Pipe	Metal	Yellow	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	Door Casing	Metal	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	W1	CMU	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	W2	CMU	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	W3	CMU	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	W4	CMU	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240A	Home Economics A Locker Room	Door Casing	Metal	White	None	0	0	Negative	
1	UL	A240A	Home Economics A Locker Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	W1	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W2	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W3	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W4	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240C	Home Economics A Mid-Right Storage Room	Door Casing	Metal	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W1	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W2	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W3	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	W4	CMU	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240	Home Economics A (includes three classrooms)	Door Casing	Metal	White	None	0	0	Negative	
1	UL	A240	Home Economics A (includes three classrooms)	Pipe	Metal	Yellow	None	0	0.1	Negative	

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School							
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115							
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	UL	A240	Home Economics A (includes three classrooms)	Duct	Metal	Yellow	None	0	0.4	Negative	
1	UL	A240D	Home Economics A Right Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A240D	Home Economics A Right Storage Room	Door Casing	Metal	White	None	0	0	Negative	
1	UL	A240D	Home Economics A Right Storage Room	Door	Metal	White	None	0	0.2	Negative	
1	UL	A301	HVAC Penthouse 1A2 on Roof	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A301	HVAC Penthouse 1A2 on Roof	Door Casing	Metal	Red	None	0	0	Negative	
1	UL	A301	HVAC Penthouse 1A2 on Roof	Door	Metal	Red	None	0	0	Negative	
1	UL	A302	HVAC Penthouse 2A1 on Roof	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	UL	A302	HVAC Penthouse 2A1 on Roof	Door Casing	Metal	Red	None	0	0	Negative	
1	UL	A302	HVAC Penthouse 2A1 on Roof	Door	Metal	Red	None	0	0	Negative	
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	W1	CMU	White	Cracking	20	0	Negative	
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	W2	CMU	White	None	0	0	Negative	
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	W3	CMU	White	None	0	0	Negative	
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	W4	CMU	White	None	0	0	Negative	
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	C201	Foreign Language Lab next to IMC/Library Room 215	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C202	IMC/Library Rear Storage Room 216	W1	CMU	White	None	0	0	Negative
1	UL	C202	IMC/Library Rear Storage Room 216	W2	CMU	White	None	0	0	Negative
1	UL	C202	IMC/Library Rear Storage Room 216	W3	CMU	White	None	0	0	Negative
1	UL	C202	IMC/Library Rear Storage Room 216	W4	CMU	White	None	0	0	Negative
1	UL	C202	IMC/Library Rear Storage Room 216	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C202	IMC/Library Rear Storage Room 216	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C202	IMC/Library Rear Storage Room 216	Door Casing	Metal	White	None	0	0	Negative
1	UL	C203	Foreign Language Lab Storage Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab Storage Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab Storage Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab Storage Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab Storage Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab Storage Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C203	Foreign Language Lab next to IMC/Library Room 216	Door Casing	Metal	White	None	0	0	Negative
1	UL	C203	Foreign Language Lab next to IMC/Library Room 217	Door	Metal	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	W1	CMU	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	W2	CMU	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	W3	CMU	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	W4	CMU	Green	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	Ceiling	Concrete	White	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C204	IMC/Library Computer Testing Area	Door Casing	Metal	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	Door	Metal	Blue	None	0	0	Negative
1	UL	C204	IMC/Library Computer Testing Area	Duct	Metal	Green	None	0	0.3	Negative
1	UL	C204	IMC/Library Computer Testing Area	Pipe	Metal	Blue	None	0	0.2	Negative
1	UL	C205	IMC/Library Main Area	W1	Sheetrock	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W2	Sheetrock	Blue	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W3	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W4	Sheetrock	Blue	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Ceiling	Concrete	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	C205	IMC/Library Main Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C205	IMC/Library Main Area	Door Casing	Metal	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W1	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W2	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W3	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W4	Sheetrock	Blue	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Ceiling	Concrete	White	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C205	IMC/Library Main Area	Door Casing	Metal	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Duct	Metal	Blue	None	0	0.6	Negative
1	UL	C205	IMC/Library Main Area	W1	Sheetrock	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W2	Sheetrock	Blue	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W3	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	W4	CMU	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Ceiling	Concrete	White	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C205	IMC/Library Main Area	Door Casing	Metal	Grey	None	0	0	Negative
1	UL	C205	IMC/Library Main Area	Duct	Metal	Blue	None	0	0.3	Negative
1	UL	C205	IMC/Library Main Area	Pipe	Metal	Grey	None	0	0.1	Negative
1	UL	C206	Recording studio/storage next IMC	W1	CMU	Blue	None	0	0	Negative
1	UL	C206	Recording studio/storage next IMC	W2	CMU	Blue	None	0	0	Negative
1	UL	C206	Recording studio/storage next IMC	W3	CMU	Blue	None	0	0	Negative
1	UL	C206	Recording studio/storage next IMC	W4	CMU	Blue	None	0	0	Negative
1	UL	C206	Recording studio/storage next IMC	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C206	Recording studio/storage next IMC	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C206	Recording studio/storage next IMC	Door Casing	Metal	White	None	0	0	Negative
1	UL	C207	Storage closet/kitchen in IMC	W1	CMU	White	None	0	0	Negative
1	UL	C207	Storage closet/kitchen in IMC	W2	CMU	White	None	0	0	Negative
1	UL	C207	Storage closet/kitchen in IMC	W3	CMU	White	None	0	0	Negative
1	UL	C207	Storage closet/kitchen in IMC	W4	CMU	White	None	0	0	Negative
1	UL	C207	Storage closet/kitchen in IMC	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C207	Storage closet/kitchen in IMC	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C207	Storage closet/kitchen in IMC	Door Casing	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	C208	Room 203 Dean of Students Office	W1	CMU	Blue	None	0	0	Negative
1	UL	C208	Room 203 Dean of Students Office	W2	CMU	Blue	None	0	0	Negative
1	UL	C208	Room 203 Dean of Students Office	W3	CMU	Blue	None	0	0	Negative
1	UL	C208	Room 203 Dean of Students Office	W4	CMU	Blue	None	0	0	Negative
1	UL	C208	Room 203 Dean of Students Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C208	Room 203 Dean of Students Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C208	Room 203 Dean of Students Office	Door Casing	Metal	White	None	0	0	Negative
1	UL	C209	Office 204	W1	CMU	White	None	0	0	Negative
1	UL	C209	Office 204	W2	CMU	White	None	0	0	Negative
1	UL	C209	Office 204	W3	CMU	White	Flaking	60	0	Negative
1	UL	C209	Office 204	W4	CMU	White	None	0	0	Negative
1	UL	C209	Office 204	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C209	Office 204	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	C209	Office 204	Door Casing	Metal	White	None	0	0	Negative
1	UL	H131	Hallway outside IMC	W1	CMU	Multi	None	0	0	Negative
1	UL	H131	Hallway outside IMC	W2	Sheetrock	Blue	None	0	0	Negative
1	UL	H131	Hallway outside IMC	W3	Sheetrock	Blue	None	0	0	Negative
1	UL	H131	Hallway outside IMC	W4	Sheetrock	Blue	None	0	0	Negative
1	UL	H131	Hallway outside IMC	Ceiling	Concrete	White	None	0	0	Negative
1	UL	H131	Hallway outside IMC	Door Casing	Metal	White	None	0	0	Negative
1	UL	H131	Hallway outside IMC	Door	Metal	Multi	None	0	0	Negative
1	UL	C215	Air Handler Room C-6	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	C215	Air Handler Room C-6	Door	Metal	White	None	0	0	Negative
1	UL	C215	Air Handler Room C-6	Door Casing	Metal	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	W1	CMU	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	W2	CMU	Blue	None	0	0.8	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	W3	CMU	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	W4	CMU	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Cove Base	CMU	Black	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Door	Metal	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Door Casing	Metal	White	None	0	0	Negative
1	UL	H116	Hallway from Stairwell by Community Room and Boy's Restroom to Exit by Dean's Office	Grate	Metal	White	None	0	0.8	Positive
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	W1	CMU	White	None	0	0	Negative
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	W2	CMU	White	None	0	0.8	Positive
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	W3	CMU	White	None	0	0.1	Negative
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	W4	CMU	White	None	0	0	Negative
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H117	Hallway from Stairwell A-1 near Main Entrance to Stairwell near Community Room and Boy's Restroom	Cove Base	CMU	Black	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	W1	CMU	White	None	0	0.7	Positive
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	W2	CMU	White	None	0	0	Negative
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	W3	CMU	White	None	0	0	Negative
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	W4	CMU	White	None	0	0.4	Negative
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Door	Metal	Blue	None	0	0.1	Negative
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Door Casing	Metal	Blue	None	0	0.2	Negative
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Grate	Metal	White	None	0	0.9	Positive
1	UL	H118	Hallway from Room 200 to Stairwell A-1 near Main Entrance	Cove Base	CMU	Black	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	W1	CMU	White	None	0	0.5	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	W2	CMU	White	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	W3	CMU	White	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	W4	CMU	White	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Cove Base	CMU	Black	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Door	Metal	White	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Door Casing	Metal	White	None	0	0	Negative
1	UL	H119	Hallway from Exit Doors by Dean's Office to Room 200	Grate	Metal	White	None	0	0.7	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	H127-UL	Hallway from Stairwell C-7 to Stairwell C-6	W1	CMU	White	None	0	1.3	Positive
1	UL	H127-UL	Hallway from Stairwell C-7 to Stairwell C-6	W3	CMU	White	None	0	0	Negative
1	UL	H127-UL	Hallway from Stairwell C-7 to Stairwell C-6	Ceiling	Concrete	White	None	0	0	Negative
1	UL	H127-UL	Hallway from Stairwell C-7 to Stairwell C-6	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H128	Hallway from Stairwell C-6 to Elevator	W1	CMU	White	None	0	1.6	Positive
1	UL	H128	Hallway from Stairwell C-6 to Elevator	W3	CMU	White	None	0	0	Negative
1	UL	H128	Hallway from Stairwell C-6 to Elevator	Ceiling	Concrete	White	None	0	0	Negative
1	UL	H128	Hallway from Stairwell C-6 to Elevator	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	W1	CMU	White	None	0	0.8	Positive
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	W3	CMU	White	None	0	0	Negative
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	Ceiling	Concrete	White	None	0	0	Negative
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	Elevator door	Metal	Blue	None	0	0	Negative
1	UL	H129	Hallway near Elevator to Hall by Upper Auditorium	Elevator door casing	Metal	Blue	None	0	0	Negative
1	UL	H130	Hallway from&nbsp;Upper Auditorium to Stairwell C-7	W1	CMU	White	None	0	1.5	Positive
1	UL	H130	Hallway from&nbsp;Upper Auditorium to Stairwell C-7	W3	CMU	White	None	0	0	Negative
1	UL	H130	Hallway from&nbsp;Upper Auditorium to Stairwell C-7	Ceiling	Concrete	White	None	0	0	Negative
1	UL	H130	Hallway from&nbsp;Upper Auditorium to Stairwell C-7	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A



			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA205	Pipe Chase in Men's Restroom near Community Room	Door	Metal	White	None	0	0	Negative
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	PCA225	Pipe Chase in Copy Room in back right corner of Main Office	Door	Metal	White	None	0	0	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	W1	CMU	Blue	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	W2	CMU	Blue	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	W3	CMU	Blue	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	W3	Concrete	Blue	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	W4	CMU	Blue	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Ceiling	Concrete	White	None	0	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Door	Metal	Blue	None	0	0	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Door Casing	Metal	Blue	None	0	0	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Hand Rail	Metal	Blue	Friction	5	0.1	Negative
1	UL	S112	Stairwell next to Community Room and Boy's Restroom	Stair stringer	Metal	White	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	S113	Stairwell A1/Mezzanine Area	W1	CMU	White	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	W2	CMU	Orange	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	W2	CMU	Multi	None	0	0.2	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	W3	CMU	White	None	0	0.7	Positive
1	UL	S113	Stairwell A1/Mezzanine Area	W4	CMU	White	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	S113	Stairwell A1/Mezzanine Area	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	S113	Stairwell A1/Mezzanine Area	Cove Base	CMU	Black	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	Door	Metal	Blue	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	Door Casing	Metal	Blue	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	Hand Rail	Metal	Black	None	0	0	Negative
1	UL	S113	Stairwell A1/Mezzanine Area	Stairs	Concrete	Gray	None	0	0	Negative
1	UL	S114	Stairwell near Room 200	W1	CMU	Blue	None	0	0.2	Negative
1	UL	S114	Stairwell near Room 200	W2	CMU	Blue	None	0	0.1	Negative
1	UL	S114	Stairwell near Room 200	W3	CMU	Blue	None	0	0.1	Negative
1	UL	S114	Stairwell near Room 200	W3	Concrete	Blue	None	0	0	Negative
1	UL	S114	Stairwell near Room 200	W4	CMU	Blue	None	0	0.2	Negative
1	UL	S114	Stairwell near Room 200	Ceiling	Concrete	White	None	0	0	Negative
1	UL	S114	Stairwell near Room 200	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	S114	Stairwell near Room 200	Door	Metal	Blue	None	0	0.1	Negative
1	UL	S114	Stairwell near Room 200	Door Casing	Metal	Blue	None	0	0	Negative
1	UL	S114	Stairwell near Room 200	Stair stringer	Metal	White	None	0	0.1	Negative
1	UL	S114	Stairwell near Room 200	Hand Rail	Metal	Blue	Flaking	10	0	Negative
1	UL	S114	Stairwell near Room 200	Pipe	Metal	Blue	None	0	0.1	Negative
1	UL	S217	Stairwell C-7 next to IMC/Library	W1	CMU	Green	None	0	1.7	Positive
1	UL	S217	Stairwell C-7 next to IMC/Library	W2	CMU	Green	None	0	1.4	Positive
1	UL	S217	Stairwell C-7 next to IMC/Library	W3	CMU	Green	None	0	1.7	Positive
1	UL	S217	Stairwell C-7 next to IMC/Library	W4	CMU	Green	None	0	1.7	Positive
1	UL	S217	Stairwell C-7 next to IMC/Library	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	UL	S217	Stairwell C-7 next to IMC/Library	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	S217	Stairwell C-7 next to IMC/Library	Hand Rail	Metal	Blue	Friction	15	0	Negative
1	UL	S217	Stairwell C-7 next to IMC/Library	Stair stringer	Metal	Blue	None	0	0	Negative
1	UL	S217	Stairwell C-7 next to IMC/Library	Stairs	Metal	Blue	None	0	0	Negative

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	UL	S217	Stairwell C-7 next to IMC/Library	Door	Metal	Blue	None	0	0.7	Positive
1	UL	S217	Stairwell C-7 next to IMC/Library	Door Casing	Metal	Blue	None	0	1.1	Positive
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	W1	CMU	White	None	0	0.4	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	W2	CMU	White	None	0	0.4	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	W3	CMU	White	None	0	0.4	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	W4	CMU	White	None	0	0.4	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Ceiling	concrete	White	None	0	0	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Stair stringer	Metal	Blue	None	0	Assumed	Assumed
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Hand Rail	Metal	Blue	Friction	10	0	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Door	Metal	Blue	None	0	0.2	Negative
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Door Casing	Metal	Blue	None	0	0.8	Positive
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	grate	Metal	White	None	0	1.1	Positive
1	UL	S218	Hallway and Stairwell C-6 between Foreign Language Lab and Mechanical Room	Stairs	concrete	Multi	None	0	0	Negative
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	W1	CMU	Blue	None	0	1	Positive
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	W2	CMU	Blue	None	0	1.1	Positive
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	W3	CMU	Blue	None	0	1	Positive
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	W4	CMU	Blue	None	0	0.9	Positive
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Hand Rail	Metal	Blue	Friction	20	0	Negative
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Stair stringer	Metal	White	None	0	0	Negative
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Door Casing	Metal	Blue	None	0	0	Negative
1	LL	S121	Stairwell from Boy's Locker Room to Boy's side of Gym	Door	Metal	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	W1	Sheetrock	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	W2	CMU	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	W3	CMU	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	W4	CMU	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	Ceiling	Concrete	White	None	0	0	Negative
1	ML	A109A	BLA/SS	Floor	Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	ML	A109A	BLA/SS	Door Casing	Metal	Blue	None	0	0	Negative
1	ML	A109A	BLA/SS	Duct	Metal	Blue	None	0	0.4	Negative
2	ML	A109A	BLA/SS	Pipe	Metal	Blue	None	0	0.2	Negative
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	W1	CMU	Blue	None	0	0.7	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	W2	CMU	Blue	None	0	1.2	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	W3	CMU	Blue	None	0	0.9	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	W4	CMU	Blue	None	0	1.2	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Door Casing	Metal	Blue	None	0	0.7	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Door	Metal	Blue	None	0	0.7	Positive
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Hand Rail	Metal	Blue	Friction	15	0.1	Negative
1	LL	S111	Stairwell (S-9) Between O-101 and Y-101	Stair Stringer	Metal	White	None	0	0.1	Negative
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	W1	CMU	Blue	None	0	0.7	Positive
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	W2	CMU	Blue	None	0	0.9	Positive
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	W3	CMU	Blue	None	0	0.8	Positive
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	W4	CMU	Blue	None	0	1	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Door Casing	Metal	Blue	None	0	0.7	Positive
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Hand Rail	Metal	Blue	Friction	10	0	Negative
1	LL	S211	Stairwell (S-9) Above S111 Leading to Roof Access	Stair Stringer	Metal	White	None	0	0	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	W1	CMU	Blue	None	0	1.1	Positive
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	W3	CMU	Blue	None	0	1.4	Positive
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	W4	CMU	Blue	None	0	0.9	Positive
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Hand Rail	Metal	Blue	Friction	5	0	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Stair stringer	Metal	White	None	0	0	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Door Casing	Metal	Blue	None	0	0.4	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S120	Stairwell from Girl's Locker Room to Girl's side of Gym	Pipe	Metal	Blue	None	0	0.7	Positive
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	W1	CMU	Blue	None	0	1.1	Positive
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	W2	CMU	Blue	None	0	0.9	Positive
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	W3	CMU	Blue	None	0	1.3	Positive
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	W4	CMU	Blue	None	0	1.2	Positive

			Dates: 10/16/2023-01/29/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Erika Barron 007296	Baldi School						
			Inspection Company: Criterion Labs Inc	8801 Verree Rd, Philadelphia PA 19115						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Ceiling	Concrete	White	None	0	0	Negative
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Hand Rail	Metal	Blue	Friction	10	0	Negative
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Stair stringer	Metal	White	None	0	0	Negative
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Door Casing	Metal	Blue	None	0	0.5	Negative
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Door	Metal	Blue	None	0	0.4	Negative
1	LL	S020	Stairwell from Girl's Locker Room to Girl's side of Gym	Pipe	Metal	Blue	None	0	0.9	Positive
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	W2	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	W3	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	W4	CMU	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	Door	Metal	White	None	0	0	Negative
1	LL	S05	Stairwell Outside Girl's Locker Room to Outside the Building	Door Casing	Metal	White	None	0	0	Negative
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

			<b>Dates: 10/16/2023-01/29/2024</b>	<b>Lead-Safe Certification Assessment Report</b>						
			<b>Inspector Name and Certificate Number: Erika Barron 007296</b>	<b>Baldi School</b>						
			<b>Inspection Company: Criterion Labs Inc</b>	<b>8801 Verree Rd, Philadelphia PA 19115</b>						
<b>Element</b>	<b>Floor</b>	<b>Space #</b>	<b>On-Site Room Name</b>	<b>Component</b>	<b>Substrate Material</b>	<b>Paint Color</b>	<b>Description of Damage</b>	<b>Damage Quantity (sf)</b>	<b>XRF Reading (mg/cm2)</b>	<b>XRF (positive/ negative)</b>
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	Door	Metal	Blue	None	0	0	Negative
1	LL	S119	Stairwell From Girl's Locker Room to Outside the Building	Door Casing	Metal	Blue	None	0	0	Negative