

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	100	Main Office 1	W1	Plaster	Blue	Chipping	10	8.43	Positive
1	1	100	Main Office 1	W2	Plaster	Blue	Chipping	5	8.51	Positive
1	1	100	Main Office 1	W3	Plaster	Blue	Chipping	3	8.42	Positive
1	1	100	Main Office 1	W4	Plaster	Blue	Chipping	2	8.47	Positive
1	1	100	Main Office 1	Ceiling	Plaster	White	Flaking	800	5.69	Positive
1	1	100	Main Office 1	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	100	Main Office 1	Baseboard	Wood	Blue	Friction	20	0.09	Negative
1	1	100	Main Office 1	Radiator	Metal	Grey	Chipping	10	3.94	Positive
1	1	100	Main Office 1	Door	Wood	Blue	None	0	0.04	Negative
1	1	100	Main Office 1	Door Frame	Wood	Blue	None	0	0.01	Negative
1	1	100	Main Office 1	Cork Board Frame	Wood	Blue	None	0	0.3	Negative
1	1	100	Main Office 1	Pipe Cover	Metal	Blue	None	0	0.19	Negative
1	1	101	Principal's Office	W1	Plaster	White	None	0	7.94	Positive
1	1	101	Principal's Office	W2	Plaster	White	None	0	7.86	Positive
1	1	101	Principal's Office	W3	Plaster	White	None	0	7.82	Positive
1	1	101	Principal's Office	W4	Plaster	White	None	0	7.75	Positive
1	1	101	Principal's Office	Ceiling	Plaster	White	Flaking	150	2.36	Positive
1	1	101	Principal's Office	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	101	Principal's Office	Window Frame	Wood	Brown	None	0	0.08	Negative
1	1	101	Principal's Office	Door	Wood	Brown	None	0	0.09	Negative
1	1	101	Principal's Office	Door Frame	Wood	Brown	None	0	0.09	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	101	Principal's Office	Pipe Cover	Metal	White	None	0	0.26	Negative
1	1	101	Principal's Office	Baseboard	Wood	Grey	None	0	0.12	Negative
1	1	101	Principal's Office	Radiator	Metal	Grey	None	0	6.14	Positive
1	1	101	Principal's Office	Whiteboard Frame	Wood	Brown	None	0	0.05	Negative
1	1	101A	Service Closet adjacent to Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101A	Service Closet adjacent to Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101A	Service Closet adjacent to Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101A	Service Closet adjacent to Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	101A	Service Closet adjacent to Elevator	Ceiling	Plaster	White	None	0	6.71	Positive
1	1	101A	Service Closet adjacent to Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	102	Main Office 1 Telecommunication Equipment Room	W1	Plaster	Blue	Chipping	3	7.82	Positive
1	1	102	Main Office 1 Telecommunication Equipment Room	W2	Plaster	Blue	Cracking	10	7.86	Positive
1	1	102	Main Office 1 Telecommunication Equipment Room	W3	Plaster	Blue	None	0	7.54	Positive
1	1	102	Main Office 1 Telecommunication Equipment Room	W4	Plaster	Blue	Chipping	10	7.73	Positive
1	1	102	Main Office 1 Telecommunication Equipment Room	Ceiling	Plaster	White	Flaking	100	4.23	Positive
1	1	102	Main Office 1 Telecommunication Equipment Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	102	Main Office 1 Telecommunication Equipment Room	Radiator	Metal	Grey	Chipping	10	1.21	Positive
1	1	102A	Teacher's Lounge 102	W1	Plaster	Blue	Flaking	5	7.82	Positive
1	1	102A	Teacher's Lounge 102	W2	Plaster	Blue	Moisture Damage	20	7.89	Positive
1	1	102A	Teacher's Lounge 102	W3	Plaster	Blue	Flaking	5	6.95	Positive
1	1	102A	Teacher's Lounge 102	W4	Plaster	Purple	None	0	5.32	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	102A	Teacher's Lounge 102	Ceiling	Plaster	White	Flaking	100	8.39	Positive
1	1	102A	Teacher's Lounge 102	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	102A	Teacher's Lounge 102	Radiator	Metal	Grey	Chipping	5	1.05	Positive
1	1	102A	Teacher's Lounge 102	Pipe Cover	Metal	White	None	0	0.12	Negative
1	1	103	Main Office 2	W1	Plaster	White	Chipping	5	10	Positive
1	1	103	Main Office 2	W2	Plaster	White	Cracking	10	9.5	Positive
1	1	103	Main Office 2	W3	Plaster	White	Flaking	70	9.6	Positive
1	1	103	Main Office 2	W4	Sheetrock	White	None	0	0	Negative
1	1	103	Main Office 2	Ceiling	Plaster	White	Flaking	300	4.6	Positive
1	1	103	Main Office 2	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	103	Main Office 2	Pipe Cover	Metal	White	None	0	0.19	Negative
1	1	103	Main Office 2	Pipe	Metal	White	None	0	8.53	Positive
1	1	103	Main Office 2	Radiator	Metal	Grey	Chipping	10	9.45	Positive
1	1	103A	Main Office 2 Principal's Office	W1	Sheetrock	White	None	0	0	Negative
1	1	103A	Main Office 2 Principal's Office	W2	Plaster	White	None	0	0	Negative
1	1	103A	Main Office 2 Principal's Office	W3	Plaster	White	Flaking	3	5.87	Positive
1	1	103A	Main Office 2 Principal's Office	W4	Sheetrock	White	None	0	0	Negative
1	1	103A	Main Office 2 Principal's Office	Ceiling	Plaster	White	Flaking	200	5.49	Positive
1	1	103A	Main Office 2 Principal's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	103A	Main Office 2 Principal's Office	Radiator	Metal	Grey	None	0	4.45	Positive
1	1	103B	Main Office 2 Conference Room	W1	Sheetrock	White	None	0	0	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	103B	Main Office 2 Conference Room	W2	Sheetrock	White	None	0	0	Negative
1	1	103B	Main Office 2 Conference Room	W3	Plaster	White	Chipping	5	0.01	Negative
1	1	103B	Main Office 2 Conference Room	W4	Plaster	White	Friction	5	5.69	Positive
1	1	103B	Main Office 2 Conference Room	Ceiling	Plaster	White	Flaking	500	6.79	Positive
1	1	103B	Main Office 2 Conference Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	W1	Plaster	White	Chipping	10	7.34	Positive
1	1	104	Classroom 104	W2	Plaster	White	Chipping	15	3.39	Positive
1	1	104	Classroom 104	W3	Plaster	White	Chipping	5	6.82	Positive
1	1	104	Classroom 104	W4	Plaster	White	Chipping	10	6.54	Positive
1	1	104	Classroom 104	Ceiling	Plaster	White	Flaking	150	1.25	Positive
1	1	104	Classroom 104	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	104	Classroom 104	Radiator	Metal	Grey	Chipping	10	6.59	Positive
1	1	104	Classroom 104	Pipe Cover	Metal	White	Chipping	1	0.09	Negative
1	1	104A	Girl's Restroom adjacent to Classroom 104	W1	CMU	Unpainted	N/A	N/A	N/A	N/A
1	1	104A	Girl's Restroom adjacent to Classroom 104	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	104A	Girl's Restroom adjacent to Classroom 104	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	104A	Girl's Restroom adjacent to Classroom 104	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	104A	Girl's Restroom adjacent to Classroom 104	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	104A	Girl's Restroom adjacent to Classroom 104	Ceiling	Plaster	White	Efflorescence	50	2.5	Positive
1	1	104A	Girl's Restroom adjacent to Classroom 104	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	W1	Plaster	White	Flaking	10	9.27	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	105	Classroom 105	W2	Plaster	White	Chipping	15	9.35	Positive
1	1	105	Classroom 105	W3	Plaster	White	Chipping	3	9.78	Positive
1	1	105	Classroom 105	W4	Plaster	White	None	0	9.32	Positive
1	1	105	Classroom 105	Ceiling	Plaster	White	Flaking	200	4.39	Positive
1	1	105	Classroom 105	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	105	Classroom 105	Pipe Cover	Metal	White	None	0	0.14	Negative
1	1	105	Classroom 105	Radiator	Metal	Grey	Chipping	10	5.89	Positive
1	1	106	Office 106 in West Stairwell	W1	Plaster	White	Flaking	15	10	Positive
1	1	106	Office 106 in West Stairwell	W2	Plaster	White	Chipping	5	9.56	Positive
1	1	106	Office 106 in West Stairwell	W3	Plaster	White	Flaking	15	10	Positive
1	1	106	Office 106 in West Stairwell	W4	Plaster	White	Alligating	20	10	Positive
1	1	106	Office 106 in West Stairwell	Ceiling	Plaster	White	Flaking	100	3.3	Positive
1	1	106	Office 106 in West Stairwell	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	106	Office 106 in West Stairwell	Radiator	Metal	Grey	Chipping	10	1.14	Positive
1	1	106	Office 106 in West Stairwell	Radiator Cover	Metal	Grey	Chipping	10	5.04	Positive
1	1	106	Office 106 in West Stairwell	Pipe Cover	Metal	White	Chipping	5	0.06	Negative
1	1	107	Classroom 107	W1	Plaster	White	Chipping	10	8.54	Positive
1	1	107	Classroom 107	W2	Plaster	White	Cracking	5	8.39	Positive
1	1	107	Classroom 107	W3	Plaster	White	Chipping	40	8.56	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	107	Classroom 107	W4	Plaster	White	Chipping	10	8.46	Positive
1	1	107	Classroom 107	Ceiling	Plaster	White	Flaking	200	2.25	Positive
1	1	107	Classroom 107	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107	Classroom 107	Radiator	Metal	Grey	Chipping	30	5.04	Positive
1	1	107	Classroom 107	Pipe Cover	Metal	White	None	0	0	Negative
1	1	107B	Custodial Closet adjacent to Classroom 107	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107B	Custodial Closet adjacent to Classroom 107	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107B	Custodial Closet adjacent to Classroom 107	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107B	Custodial Closet adjacent to Classroom 107	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	107B	Custodial Closet adjacent to Classroom 107	Ceiling	Plaster	White	None	0	2.22	Positive
1	1	107B	Custodial Closet adjacent to Classroom 107	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	W1	Plaster	White	Chipping	30	5.37	Positive
1	1	108	Classroom 108	W2	Plaster	White	Flaking	15	2.5	Positive
1	1	108	Classroom 108	W3	Plaster	White	None	0	4.21	Positive
1	1	108	Classroom 108	W4	Plaster	White	Chipping	15	4.12	Positive
1	1	108	Classroom 108	Ceiling	Plaster	White	Flaking	300	1.78	Positive
1	1	108	Classroom 108	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	108	Classroom 108	Baseboard	Wood	Tan	Chipping	15	3.13	Positive
1	1	108	Classroom 108	Radiator	Metal	Grey	Chipping	10	0.35	Negative
1	1	108	Classroom 108	Door	Wood	Tan	Chipping	10	0.46	Negative
1	1	108	Classroom 108	Door Frame	Wood	Tan	Chipping	15	3.14	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	108	Classroom 108	Window Frame	Wood	White	None	0	4.57	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	W1	Plaster	White	Flaking	15	4	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	W2	Plaster	White	Flaking	20	2.9	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	W3	Plaster	White	Flaking	10	4	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	W4	Plaster	White	Flaking	11	3.1	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	Ceiling	Plaster	White	None	0	2	Positive
1	1	108A	Classroom 108 Closet adjacent to Classroom 109	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	W1	Plaster	White	None	0	3.2	Positive
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	W2	Plaster	White	None	0	2.6	Positive
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	W3	Plaster	White	None	0	4.9	Positive
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	W4	Plaster	White	None	0	5.7	Positive
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	Ceiling	Plaster	White	None	0	2.3	Positive
1	1	108B	Classroom 108 Closet adjacent to Classroom 107 by Windows	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	1	108C	Classroom 108 Closet adjacent to Classroom 107 by Entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	1	109	Classroom 109	W1	Plaster	Yellow	Chipping	15	4.8	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	109	Classroom 109	W2	Plaster	Yellow	Cracking	15	4.53	Positive
1	1	109	Classroom 109	W3	Plaster	Yellow	Chipping	10	5.32	Positive
1	1	109	Classroom 109	W4	Plaster	Yellow	Flaking	10	5.41	Positive
1	1	109	Classroom 109	Ceiling	Plaster	White	Flaking	200	8.46	Positive
1	1	109	Classroom 109	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	109	Classroom 109	Radiator	Metal	Grey	Chipping	10	5.84	Positive
1	1	110	Principal's Office 110	W1	Plaster	White	Chipping	10	7.32	Positive
1	1	110	Principal's Office 110	W2	Plaster	White	Chipping	1	7.02	Positive
1	1	110	Principal's Office 110	W3	Plaster	White	Flaking	4	7.42	Positive
1	1	110	Principal's Office 110	W4	Plaster	White	Chipping	3	7.28	Positive
1	1	110	Principal's Office 110	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Principal's Office 110	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	110	Principal's Office 110	Radiator	Metal	Grey	None	0	4.3	Positive
1	1	110	Principal's Office 110	Pipe Cover	Metal	White	Flaking	1	0.24	Negative
1	1	111	Classroom 111	W1	Plaster	White	Chipping	40	5.07	Positive
1	1	111	Classroom 111	W2	Plaster	White	Chipping	40	5.41	Positive
1	1	111	Classroom 111	W3	Plaster	White	Chipping	50	5.66	Positive
1	1	111	Classroom 111	W4	Plaster	White	Chipping	20	5.6	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	111	Classroom 111	Ceiling	Plaster	White	Flaking	200	2.58	Positive
1	1	111	Classroom 111	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	111	Classroom 111	Radiator	Metal	Grey	Chipping	10	2.12	Positive
1	1	112	Department Office 112	W1	Plaster	Orange	None	0	2.3	Positive
1	1	112	Department Office 112	W2	Plaster	Orange	Flaking	26	1.5	Positive
1	1	112	Department Office 112	W3	Plaster	Orange	None	0	3.7	Positive
1	1	112	Department Office 112	W4	Plaster	Orange	None	0	2.1	Positive
1	1	112	Department Office 112	Ceiling	Plaster	White	Flaking	50	10	Positive
1	1	112	Department Office 112	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Women's Restroom across from Classroom 104	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Women's Restroom across from Classroom 104	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Women's Restroom across from Classroom 104	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Women's Restroom across from Classroom 104	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	113	Women's Restroom across from Classroom 104	Ceiling	Plaster	White	Flaking	50	6.47	Positive
1	1	113	Women's Restroom across from Classroom 104	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	W1	Plaster	White	Chipping	10	4.68	Positive
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	W2	Plaster	White	Moisture Damage	20	4.96	Positive
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	W3	Plaster	White	Moisture Damage	5	8.67	Positive
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	W4	Plaster	White	None	0	7.12	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	Ceiling	Plaster	White	None	0	6.73	Positive
1	1	113A	Foyer outside Women's Restroom across from Classroom 104	Floor	Concrete	Grey	Chipping	5	0	Negative
1	1	114	Classroom 114	W1	Plaster	White	Chipping	4	7.95	Positive
1	1	114	Classroom 114	W2	Plaster	White	Chipping	6	8	Positive
1	1	114	Classroom 114	W3	Plaster	White	Cracking	12	8.65	Positive
1	1	114	Classroom 114	W4	Plaster	White	Chipping	10	10	Positive
1	1	114	Classroom 114	Ceiling	Plaster	White	Flaking	400	5.82	Positive
1	1	114	Classroom 114	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	114	Classroom 114	Radiator	Metal	Grey	Chipping	12	2.4	Positive
1	1	114	Classroom 114	Pipe Cover	Metal	White	Chipping	1	0.19	Negative
1	1	115	Classroom 115	W1	Plaster	Green	Chipping	10	9.07	Positive
1	1	115	Classroom 115	W2	Plaster	Green	None	0	9.43	Positive
1	1	115	Classroom 115	W3	Plaster	Green	Chipping	15	9.38	Positive
1	1	115	Classroom 115	W4	Plaster	Green	Chipping	10	10	Positive
1	1	115	Classroom 115	Ceiling	Plaster	White	Flaking	300	4.98	Positive
1	1	115	Classroom 115	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	115	Classroom 115	Radiator	Metal	Grey	Chipping	10	9.15	Positive
1	1	115	Classroom 115	Pipe Cover	Metal	Green	None	0	0.15	Negative
1	1	116	Classroom 116	W1	Plaster	White	None	0	8.47	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	116	Classroom 116	W2	Plaster	White	None	0	9.01	Positive
1	1	116	Classroom 116	W3	Plaster	White	Flaking	5	9.14	Positive
1	1	116	Classroom 116	W4	Plaster	White	None	0	9.55	Positive
1	1	116	Classroom 116	Ceiling	Plaster	White	None	0	6.55	Positive
1	1	116	Classroom 116	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	116	Classroom 116	Radiator	Metal	Grey	Chipping	5	8.45	Positive
1	1	116	Classroom 116	Pipe Cover	Metal	White	None	0	0.07	Negative
1	1	116A	Classroom 116 Telecommunication Equipment Room	W1	Sheetrock	White	None	0	0	Negative
1	1	116A	Classroom 116 Telecommunication Equipment Room	W2	Sheetrock	White	None	0	0	Negative
1	1	116A	Classroom 116 Telecommunication Equipment Room	W3	Plaster	White	None	0	0	Negative
1	1	116A	Classroom 116 Telecommunication Equipment Room	W4	Sheetrock	White	None	0	0	Negative
1	1	116A	Classroom 116 Telecommunication Equipment Room	Ceiling	Plaster	White	None	0	6.55	Positive
1	1	116A	Classroom 116 Telecommunication Equipment Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	117	Classroom 117	W1	Plaster	White	Chipping	10	2.19	Positive
1	1	117	Classroom 117	W2	Plaster	White	Chipping	40	2.43	Positive
1	1	117	Classroom 117	W3	Plaster	White	None	0	2.63	Positive
1	1	117	Classroom 117	W4	Plaster	White	None	0	3.06	Positive
1	1	117	Classroom 117	Ceiling	Plaster	White	Flaking	300	1.23	Positive
1	1	117	Classroom 117	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	117	Classroom 117	Baseboard	Wood	White	Friction	20	0.12	Negative
1	1	117	Classroom 117	Pipe Cover	Metal	Blue	Chipping	1	0.07	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	117	Classroom 117	Window Frame	Wood	Tan	None	0	0.07	Negative
1	1	118	Classroom 118	W1	Plaster	White	Chipping	1	8.81	Positive
1	1	118	Classroom 118	W2	Plaster	White	None	0	7.26	Positive
1	1	118	Classroom 118	W3	Plaster	White	Alligatoring	8	8.16	Positive
1	1	118	Classroom 118	W4	Plaster	White	None	0	7.3	Positive
1	1	118	Classroom 118	Ceiling	Plaster	White	Flaking	200	4.98	Positive
1	1	118	Classroom 118	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	118	Classroom 118	Radiator	Metal	White	Chipping	5	4.24	Positive
1	1	118	Classroom 118	Pipe Cover	Metal	Brown	None	0	0.17	Negative
1	1	118	Classroom 118	Cork Board Frame	Wood	Blue	Friction	1	0.12	Negative
1	1	119	Principal's Storage Room 119	W1	Plaster	White	Chipping	5	4.69	Positive
1	1	119	Principal's Storage Room 119	W2	Plaster	White	None	0	8.67	Positive
1	1	119	Principal's Storage Room 119	W3	Plaster	White	None	0	5.13	Positive
1	1	119	Principal's Storage Room 119	W4	Plaster	White	None	0	2.23	Positive
1	1	119	Principal's Storage Room 119	Ceiling	Plaster	White	None	0	2.56	Positive
1	1	119	Principal's Storage Room 119	Floor	Concrete	Grey	None	0	0	Negative
1	1	119A	Principal's Storage Room 119 Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119A	Principal's Storage Room 119 Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119A	Principal's Storage Room 119 Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119A	Principal's Storage Room 119 Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	119A	Principal's Storage Room 119 Restroom	Ceiling	Plaster	White	None	0	6.75	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	119A	Principal's Storage Room 119 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	120	Auditorium Balcony	W1	Plaster	White	None	0	9.03	Positive
1	1	120	Auditorium Balcony	W2	Plaster	White	Cracking	10	9.56	Positive
1	1	120	Auditorium Balcony	W3	Plaster	White	None	0	8.98	Positive
1	1	120	Auditorium Balcony	W4	Plaster	White	Flaking	100	9.68	Positive
1	1	120	Auditorium Balcony	Ceiling	Plaster	White	Flaking	1000	No Access	Assumed
1	1	120	Auditorium Balcony	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	200	Classroom 200	Radiator	Metal	Grey	Chipping	15	7.8	Positive
1	2	200	Classroom 200	Pipe Cover	Metal	White	Chipping	2	0.06	Negative
1	1	120A	Auditorium Projection Room	W1	Plaster	White	Chipping	5	3.3	Positive
1	1	120A	Auditorium Projection Room	W2	Plaster	White	Chipping	10	4.59	Positive
1	1	120A	Auditorium Projection Room	W3	Plaster	White	Chipping	5	6.65	Positive
1	1	120A	Auditorium Projection Room	W4	Plaster	White	Chipping	5	3.81	Positive
1	1	120A	Auditorium Projection Room	Ceiling	Plaster	White	Chipping	15	6.6	Positive
1	1	120A	Auditorium Projection Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	123	Main Office 1 Copy Room	W1	Plaster	White	Flaking	5	10	Positive
1	1	123	Main Office 1 Copy Room	W2	Plaster	White	Flaking	5	10	Positive
1	1	123	Main Office 1 Copy Room	W3	Plaster	White	Flaking	5	10	Positive
1	1	123	Main Office 1 Copy Room	W4	Plaster	White	Flaking	15	10	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	123	Main Office 1 Copy Room	Ceiling	Plaster	White	Flaking	75	2.64	Positive
1	1	123	Main Office 1 Copy Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	123	Main Office 1 Copy Room	Radiator	Metal	Grey	Chipping	10	3.15	Positive
1	1	123	Main Office 1 Copy Room	Pipe Cover	Metal	White	None	0	3.2	Positive
1	1	124	Main Office 1 Book Closet	W1	Plaster	White	None	0	4.6	Positive
1	1	124	Main Office 1 Book Closet	W2	Plaster	White	None	0	4.6	Positive
1	1	124	Main Office 1 Book Closet	W3	Plaster	White	None	0	2.3	Positive
1	1	124	Main Office 1 Book Closet	W4	Plaster	White	None	0	3.3	Positive
1	1	124	Main Office 1 Book Closet	Ceiling	Plaster	White	None	0	1.2	Positive
1	1	124	Main Office 1 Book Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	125	School Police Office 120	W1	Plaster	White	Cracking	10	10	Positive
1	1	125	School Police Office 120	W2	Plaster	White	Chipping	40	10	Positive
1	1	125	School Police Office 120	W3	Plaster	White	Chipping	20	10	Positive
1	1	125	School Police Office 120	W4	Plaster	White	Flaking	100	10	Positive
1	1	125	School Police Office 120	Ceiling	Plaster	White	Flaking	400	2.86	Positive
1	1	125	School Police Office 120	Floor	Terrazzo	Unpainted	N/A	N/A	N/A	N/A
1	1	125	School Police Office 120	Radiator	Metal	Grey	Chipping	10	2.01	Positive
1	1	125	School Police Office 120	Radiator Cover	Metal	Grey	None	0	3.72	Positive
1	1	125	School Police Office 120	Pipe Cover	Metal	White	None	0	0.11	Negative
1	1	126	Office to Left of Stage Balcony Level	W1	Plaster	White	Chipping	10	9.71	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	126	Office to Left of Stage Balcony Level	W2	Plaster	White	Chipping	5	9.4	Positive
1	1	126	Office to Left of Stage Balcony Level	W3	Plaster	White	Chipping	15	9.54	Positive
1	1	126	Office to Left of Stage Balcony Level	W4	Plaster	White	Chipping	5	9.46	Positive
1	1	126	Office to Left of Stage Balcony Level	Door	Metal	Grey	None	0	0.24	Negative
1	1	126	Office to Left of Stage Balcony Level	Door Frame	Metal	Grey	None	0	0.24	Negative
1	1	126	Office to Left of Stage Balcony Level	Pipe Cover	Metal	Grey	Chipping	2	0.15	Negative
1	1	126	Office to Left of Stage Balcony Level	Ceiling	Plaster	White	Flaking	150	2.1	Positive
1	1	126	Office to Left of Stage Balcony Level	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Office to Left of Stage Balcony Level Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Office to Left of Stage Balcony Level Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Office to Left of Stage Balcony Level Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Office to Left of Stage Balcony Level Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	126A	Office to Left of Stage Balcony Level Restroom	Ceiling	Plaster	White	None	0	6.7	Positive
1	1	126A	Office to Left of Stage Balcony Level Restroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	1	ELEV	Elevator	W1	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	ELEV	Elevator	W2	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	ELEV	Elevator	W3	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	ELEV	Elevator	W4	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	ELEV	Elevator	Ceiling	Metal	White	None	0	0	Negative
1	1	ELEV	Elevator	Floor	Metal	Unpainted	N/A	N/A	N/A	N/A
1	1	H101	Upper Hallway behind Stage	W1	Plaster	White	Alligatoring	30	9.82	Positive
1	1	H101	Upper Hallway behind Stage	W2	Plaster	White	Flaking	150	9.9	Positive
1	1	H101	Upper Hallway behind Stage	W3	Plaster	White	Alligatoring	50	9.7	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	H101	Upper Hallway behind Stage	W4	Plaster	White	Flaking	150	9.62	Positive
1	1	H101	Upper Hallway behind Stage	Ceiling	Plaster	White	Flaking	150	4.9	Positive
1	1	H101	Upper Hallway behind Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	1	H101	Upper Hallway behind Stage	Radiator	Metal	Grey	Chipping	5	3.31	Positive
1	1	H101	Upper Hallway behind Stage	Radiator Cover	Metal	Grey	None	0	4.95	Positive
1	1	H101	Upper Hallway behind Stage	Pipe	Metal	Grey	None	0	0.14	Negative
1	1	H11	Hallway outside Auditorium Balcony	W1	Plaster	White	None	0	9.24	Positive
1	1	H11	Hallway outside Auditorium Balcony	W2	Plaster	White	Flaking	5	10	Positive
1	1	H11	Hallway outside Auditorium Balcony	W3	Plaster	White	None	0	10	Positive
1	1	H11	Hallway outside Auditorium Balcony	W4	Plaster	White	None	0	10	Positive
1	1	H11	Hallway outside Auditorium Balcony	Ceiling	Plaster	White	Flaking	600	8.87	Positive
1	1	H11	Hallway outside Auditorium Balcony	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	H11	Hallway outside Auditorium Balcony	Trim	Concrete	Grey	None	0	0.07	Negative
1	1	H11	Hallway outside Auditorium Balcony	Radiator	Metal	Grey	Chipping	15	0.96	Positive
1	1	H11	Hallway outside Auditorium Balcony	Radiator Cover	Metal	Grey	Chipping	5	2.4	Positive
1	1	H11	Hallway outside Auditorium Balcony	Pipe Cover	Metal	White	None	0	0.06	Negative
1	1	H12	Hallway from the Elevator to Office 112	W2	Plaster	White	Chipping	5	10	Positive
1	1	H12	Hallway from the Elevator to Office 112	W3	Plaster	White	None	0	10	Positive
1	1	H12	Hallway from the Elevator to Office 112	W4	Plaster	White	None	0	10	Positive
1	2	200	Classroom 200	Door	Metal	Red	Flaking	5	0.05	Negative
1	2	200	Classroom 200	Door Frame	Metal	Red	Flaking	5	0.01	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	200	Classroom 200	Univent	Metal	Red	None	0	0	Negative
1	2	200	Classroom 200	Pipe Cover	Metal	White	Cracking	10	0.06	Negative
1	1	H12	Hallway from the Elevator to Office 112	Ceiling	Plaster	White	Flaking	800	5.56	Positive
1	1	H12	Hallway from the Elevator to Office 112	Floor	Concrete	Grey	None	0	0.1	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	W1	Plaster	White	Cracking	10	9.5	Positive
1	1	H13	Hallway from Classroom 111 to West Stairwell	W2	Plaster	White	Moisture Damage	15	7.98	Positive
1	1	H13	Hallway from Classroom 111 to West Stairwell	W3	Plaster	White	Cracking	15	8.68	Positive
1	1	H13	Hallway from Classroom 111 to West Stairwell	W4	Plaster	White	Flaking	15	10	Positive
1	1	H13	Hallway from Classroom 111 to West Stairwell	Ceiling	Plaster	White	Flaking	900	3.33	Positive
1	1	H13	Hallway from Classroom 111 to West Stairwell	Floor	Concrete	Grey	None	0	0.04	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	Pipe	Metal	White	None	0	0	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	Pipe Cover	Metal	White	Flaking	15	0.05	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	Radiator	Metal	Grey	Flaking	15	0.09	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	Door Frame	Metal	Red	None	0	0.01	Negative
1	1	H13	Hallway from Classroom 111 to West Stairwell	Door	Metal	Red	Flaking	5	0.01	Negative
1	1	H13B	Pipe Chase across from Classroom 109	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	H13B	Pipe Chase across from Classroom 109	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	H13B	Pipe Chase across from Classroom 109	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	H13B	Pipe Chase across from Classroom 109	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	H13B	Pipe Chase across from Classroom 109	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	H13B	Pipe Chase across from Classroom 109	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC100A	Pipe Chase in Main Office 1	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC100A	Pipe Chase in Main Office 1	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC100A	Pipe Chase in Main Office 1	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	PC100A	Pipe Chase in Main Office 1	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC100A	Pipe Chase in Main Office 1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC100A	Pipe Chase in Main Office 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC104B	Pipe Chase in Classroom 104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC105A	Pipe Chase in Classroom 107	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC107A	Pipe Chase in Classroom 107	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC109A	Pipe Chase Classroom 109	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC111A	Pipe Chase in Classroom 111	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC111A	Pipe Chase in Classroom 111	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC111A	Pipe Chase in Classroom 111	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	PC111A	Pipe Chase in Classroom 111	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC111A	Pipe Chase in Classroom 111	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC111A	Pipe Chase in Classroom 111	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC112A	Pipe Chase in Department Office 112	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC113B	Pipe Chase in Foyer outside Women's Restroom across from Classroom 104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC114A	Pipe Chase in Classroom 114	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC115A	Pipe Chase in Classroom 115	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC115A	Pipe Chase in Classroom 115	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC115A	Pipe Chase in Classroom 115	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC115A	Pipe Chase in Classroom 115	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC115A	Pipe Chase in Classroom 115	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	PC115A	Pipe Chase in Classroom 115	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC117A	Pipe Chase in Classroom 117	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC118A	Pipe Chase in Classroom 118	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	PC122A	Pipe Chase in Roster Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S01-1	Stairs across from Classroom 104	W1	Plaster	White	Flaking	10	2.6	Positive
1	1	S01-1	Stairs across from Classroom 104	W2	Plaster	White	Moisture Damage	20	7.65	Positive
1	1	S01-1	Stairs across from Classroom 104	W3	Plaster	White	Moisture Damage	20	4.03	Positive
1	1	S01-1	Stairs across from Classroom 104	W4	Plaster	White	Moisture Damage	30	7.1	Positive
1	1	S01-1	Stairs across from Classroom 104	Ceiling	Plaster	White	Flaking	15	5.69	Positive
1	1	S01-1	Stairs across from Classroom 104	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S01-1	Stairs across from Classroom 104	Radiator	Metal	Grey	Flaking	5	3.71	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	S01-1	Stairs across from Classroom 104	Radiator Cover	Metal	Grey	Flaking	5	3.29	Positive
1	1	S01-1	Stairs across from Classroom 104	Spindle	Metal	Grey	Chipping	10	7.71	Positive
1	1	S01-1	Stairs across from Classroom 104	Stringer	Concrete	Grey	Friction	5	4.15	Positive
1	1	S01-1	Stairs across from Classroom 104	Handrail	Metal	Grey	Friction	10	0	Negative
1	1	S01-1	Stairs across from Classroom 104	Stair Riser	Concrete	Grey	Friction	5	2.91	Positive
1	1	S01-1	Stairs across from Classroom 104	Trim	Concrete	Grey	None	0	2.54	Positive
1	1	S01-1	Stairs across from Classroom 104	Newel Post	Metal	Grey	Friction	8	5.58	Positive
1	1	S01-1	Stairs across from Classroom 104	Door	Metal	Red	Friction	15	0.01	Negative
1	1	S01-1	Stairs across from Classroom 104	Door Frame	Metal	Red	None	0	0.11	Negative
1	1	S02-1	Stairs next to 119 Principal Only Room	W1	Plaster	White	Moisture Damage	10	1.01	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	W2	Plaster	White	Moisture Damage	15	6.05	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	W3	Plaster	White	Cracking	10	4	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	W4	Plaster	White	Efflorescence	20	8.56	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Ceiling	Plaster	White	Flaking	15	5.69	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S02-1	Stairs next to 119 Principal Only Room	Radiator	Metal	Grey	Flaking	5	3.71	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Radiator Cover	Metal	Grey	Flaking	5	3.29	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Spindle	Metal	Grey	Chipping	9	7.2	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Stringer	Concrete	Grey	None	0	4.28	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Handrail	Metal	Grey	Friction	1	0.03	Negative
1	1	S02-1	Stairs next to 119 Principal Only Room	Pipe Cover	Metal	Grey	Flaking	5	0.11	Negative
1	1	S02-1	Stairs next to 119 Principal Only Room	Stair Riser	Concrete	Grey	None	0	5.65	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Trim	Concrete	Grey	None	0	5.56	Positive
1	1	S02-1	Stairs next to 119 Principal Only Room	Newel Post	Metal	Grey	Friction	5	5.08	Positive
1	1	S03-1	East Stairwell	W1	Plaster	White	Chipping	5	7.03	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	S03-1	East Stairwell	W2	Plaster	White	Flaking	40	7.56	Positive
1	1	S03-1	East Stairwell	W3	Plaster	White	Flaking	50	8.24	Positive
1	1	S03-1	East Stairwell	W4	Plaster	White	Flaking	50	9.46	Positive
1	1	S03-1	East Stairwell	Ceiling	Plaster	White	Alligating	200	5.6	Positive
1	1	S03-1	East Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S03-1	East Stairwell	Radiator	Metal	Grey	Chipping	10	3.49	Positive
1	1	S03-1	East Stairwell	Radiator Cover	Metal	Grey	Chipping	5	1.42	Positive
1	1	S03-1	East Stairwell	Pipe Cover	Metal	Grey	Flaking	10	0.05	Negative
1	1	S03-1	East Stairwell	Trim	Concrete	Grey	Moisture Damage	10	0.31	Negative
1	1	S03-1	East Stairwell	Handrail	Metal	Grey	Chipping	15	0.31	Negative
1	1	S03A-1	East Fire Tower	Ceiling	Plaster	White	Flaking	50	1.33	Positive
1	1	S03A-1	East Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S03A-1	East Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S03A-1	East Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S03A-1	East Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S03A-1	East Fire Tower	Ceiling	Plaster	White	Alligating	150	4.36	Positive
1	1	S03A-1	East Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S04-1	West Stairwell	Window Bars	Metal	Grey	Chipping	50	No Access	Assumed
1	1	S04-1	West Stairwell	W1	Plaster	White	None	0	2.02	Positive
1	1	S04-1	West Stairwell	W2	Plaster	White	Flaking	60	2.63	Positive
1	1	S04-1	West Stairwell	W3	Plaster	White	Chipping	60	9.86	Positive
1	1	S04-1	West Stairwell	W4	Plaster	White	Flaking	60	7.54	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	S04-1	West Stairwell	Ceiling	Plaster	White	Alligating	40	5.18	Positive
1	1	S04-1	West Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S04-1	West Stairwell	Handrail	Metal	Grey	Chipping	10	0.13	Negative
1	1	S04-1	West Stairwell	Window Frame	Metal	Grey	Chipping	10	0.4	Negative
1	1	S04-1	West Stairwell	Radiator	Metal	Grey	Flaking	10	0.5	Negative
1	1	S04-1	West Stairwell	Radiator Cover	Metal	Grey	Flaking	15	4.44	Positive
1	1	S04-1	West Stairwell	Stair Riser	Concrete	Grey	None	0	0.43	Negative
1	1	S04-1	West Stairwell	Trim	Concrete	Grey	Friction	10	2.56	Positive
1	1	S04-1	West Stairwell	Pipe Cover	Metal	Grey	Chipping	15	0.13	Negative
1	1	S04A-1	West Stairwell Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S04A-1	West Stairwell Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S04A-1	West Stairwell Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S04A-1	West Stairwell Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	1	S04A-1	West Stairwell Fire Tower	Ceiling	Plaster	White	Alligating	150	7.98	Positive
1	1	S04A-1	West Stairwell Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S04A-1	West Stairwell Fire Tower	Window Bars	Metal	Grey	Chipping	50	No Access	Assumed
1	1	S05-1	Stairs to Assistant Principal's Office 110	W1	Plaster	White	Moisture Damage	10	7.56	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	W2	Plaster	White	Moisture Damage	15	8.43	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	W4	Plaster	White	Moisture Damage	40	5.78	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Ceiling	Plaster	White	Chipping	5	6.98	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S05-1	Stairs to Assistant Principal's Office 110	Spindle	Metal	Grey	Chipping	10	6.41	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Stringer	Metal	Grey	None	0	5.12	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Stair Riser	Concrete	Grey	Friction	10	5.56	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Newel Post	Metal	Grey	Friction	5	5.49	Positive
1	1	S05-1	Stairs to Assistant Principal's Office 110	Trim	Concrete	Grey	None	0	0.25	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	1	S05-1	Stairs to Assistant Principal's Office 110	Door	Metal	Red	Friction	5	0.01	Negative
1	1	S05-1	Stairs to Assistant Principal's Office 110	Door Frame	Metal	Red	Flaking	5	0.01	Negative
1	1	S06-1	School Police Office 120 Stairwell	W1	Plaster	White	Cracking	30	7.48	Positive
1	1	S06-1	School Police Office 120 Stairwell	W2	Plaster	White	Cracking	15	7.04	Positive
1	1	S06-1	School Police Office 120 Stairwell	W3	Plaster	White	Efflorescence	15	7.84	Positive
1	1	S06-1	School Police Office 120 Stairwell	W4	Plaster	White	Efflorescence	20	8.18	Positive
1	1	S06-1	School Police Office 120 Stairwell	Ceiling	Plaster	White	Chipping	15	7.1	Positive
1	1	S06-1	School Police Office 120 Stairwell	Floor	Marble	Unpainted	N/A	N/A	N/A	N/A
1	1	S06-1	School Police Office 120 Stairwell	Handrail	Metal	Grey	None	0	0.21	Negative
1	1	S06-1	School Police Office 120 Stairwell	Newel Post	Metal	Grey	None	0	5.36	Positive
1	1	S06-1	School Police Office 120 Stairwell	Spindle	Metal	Grey	None	0	5.36	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	W1	Plaster	White	None	0	3.85	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	W2	Plaster	White	Flaking	40	3.74	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	W3	Plaster	White	Flaking	60	4.31	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	W4	Plaster	White	Flaking	30	4.62	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Ceiling	Plaster	White	None	0	4.36	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	200	Classroom 200	W1	Plaster	White	Chipping	15	6.69	Positive
1	2	200	Classroom 200	W2	Plaster	White	Chipping	40	6.73	Positive
1	2	200	Classroom 200	W3	Plaster	White	Chipping	10	5.98	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	200	Classroom 200	W4	Plaster	White	Chipping	4	5.91	Positive
1	2	200	Classroom 200	Ceiling	Plaster	White	Flaking	150	2.36	Positive
1	2	200	Classroom 200	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	200	Classroom 200	Radiator	Metal	Grey	Chipping	10	2.81	Positive
1	2	200	Classroom 200	Pipe Cover	Metal	White	Chipping	5	0.16	Negative
1	2	201	Classroom 201	W1	Plaster	White	Chipping	3	6.26	Positive
1	2	201	Classroom 201	W1	Sheetrock	White	None	0	0	Negative
1	2	201	Classroom 201	W2	Plaster	White	Chipping	10	5.89	Positive
1	2	201	Classroom 201	W3	Plaster	White	Chipping	30	6.13	Positive
1	2	201	Classroom 201	W4	Sheetrock	White	None	0	0	Negative
1	2	201	Classroom 201	Ceiling	Plaster	White	Flaking	200	5.58	Positive
1	2	201	Classroom 201	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201	Classroom 201	Pipe	Metal	White	None	0	0	Negative
1	2	201	Classroom 201	Pipe Cover	Metal	White	None	0	0.16	Negative
1	2	201	Classroom 201	Door	Metal	Blue	Chipping	5	0	Negative
1	2	201	Classroom 201	Door Frame	Metal	Blue	Chipping	5	0	Negative
1	2	201A	Nurse's Office	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201A	Nurse's Office	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201A	Nurse's Office	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201A	Nurse's Office	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201A	Nurse's Office	Ceiling	Plaster	White	Flaking	150	5	Positive
1	2	201A	Nurse's Office	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201B	Nurse's Office Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201B	Nurse's Office Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201B	Nurse's Office Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	201B	Nurse's Office Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	201B	Nurse's Office Restroom	Ceiling	Plaster	White	Flaking	50	7	Positive
1	2	201B	Nurse's Office Restroom	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	W1	Sheetrock	White	None	0	0	Negative
1	2	202	Classroom 202	W1	Plaster	White	None	0	8.45	Positive
1	2	202	Classroom 202	W2	Plaster	White	Chipping	50	8.73	Positive
1	2	202	Classroom 202	W3	Plaster	White	Chipping	50	8.72	Positive
1	2	202	Classroom 202	W4	Sheetrock	White	None	0	0	Negative
1	2	202	Classroom 202	Ceiling	Plaster	White	Flaking	300	4.39	Positive
1	2	202	Classroom 202	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	202	Classroom 202	Pipe	Metal	White	None	0	0	Negative
1	2	202	Classroom 202	Pipe Cover	Metal	White	None	0	0.08	Negative
1	2	203	Classroom 203	W1	Plaster	White	Chipping	30	6.06	Positive
1	2	203	Classroom 203	W2	Plaster	White	Chipping	10	6.44	Positive
1	2	203	Classroom 203	W3	Plaster	White	Chipping	5	6.85	Positive
1	2	203	Classroom 203	W4	Plaster	White	Chipping	20	6.79	Positive
1	2	203	Classroom 203	W4	Metal	White	Chipping	10	0.3	Negative
1	2	203	Classroom 203	Ceiling	Plaster	White	Flaking	200	2.36	Positive
1	2	203	Classroom 203	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	203	Classroom 203	Radiator	Metal	Grey	Chipping	10	6.02	Positive
1	2	203	Classroom 203	Pipe Cover	Metal	White	None	0	0.08	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	204	Classroom 204	W1	Plaster	White	Chipping	20	7.17	Positive
1	2	204	Classroom 204	W2	Plaster	White	Chipping	15	7.2	Positive
1	2	204	Classroom 204	W3	Plaster	White	Chipping	40	6.31	Positive
1	2	204	Classroom 204	W4	Plaster	White	Chipping	30	6.48	Positive
1	2	204	Classroom 204	Ceiling	Plaster	White	Flaking	300	2.14	Positive
1	2	204	Classroom 204	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	204	Classroom 204	Radiator	Metal	Grey	Chipping	5	4.4	Positive
1	2	204	Classroom 204	Pipe Cover	Metal	White	None	0	0.1	Negative
1	2	204A	Girl's Restroom adjacent to Classroom 204	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	204A	Girl's Restroom adjacent to Classroom 204	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	204A	Girl's Restroom adjacent to Classroom 204	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	204A	Girl's Restroom adjacent to Classroom 204	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	204A	Girl's Restroom adjacent to Classroom 204	Ceiling	Plaster	White	Chipping	15	1.59	Positive
1	2	204A	Girl's Restroom adjacent to Classroom 204	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	W1	Plaster	Blue	Chipping	3	6.88	Positive
1	2	205	Classroom 205	W2	Plaster	Blue	Chipping	2	7.27	Positive
1	2	205	Classroom 205	W3	Plaster	Blue	Cracking	1	7.66	Positive
1	2	205	Classroom 205	W4	Plaster	Blue	Chipping	1	7.24	Positive
1	2	205	Classroom 205	Ceiling	Plaster	White	Flaking	200	4.37	Positive
1	2	205	Classroom 205	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	205	Classroom 205	Baseboard	Wood	Black	None	0	0.24	Negative
1	2	205	Classroom 205	Radiator	Metal	Black	None	0	1.93	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	205	Classroom 205	Whiteboard Frame	Wood	Black	None	0	0.06	Negative
1	2	205	Classroom 205	Pipe Cover	Metal	Grey	None	0	0.18	Negative
1	2	206	Office 206 in West Stairwell	W1	Plaster	White	Chipping	5	5.36	Positive
1	2	206	Office 206 in West Stairwell	W2	Plaster	White	None	0	4.32	Positive
1	2	206	Office 206 in West Stairwell	W3	Plaster	White	Chipping	5	6.31	Positive
1	2	206	Office 206 in West Stairwell	W4	Plaster	White	Flaking	15	8.35	Positive
1	2	206	Office 206 in West Stairwell	Ceiling	Plaster	White	Flaking	50	5.97	Positive
1	2	206	Office 206 in West Stairwell	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	W1	Plaster	Purple	None	0	4.95	Positive
1	2	207	Classroom 207	W2	Plaster	Purple	None	0	5.09	Positive
1	2	207	Classroom 207	W3	Plaster	Purple	None	0	4.81	Positive
1	2	207	Classroom 207	W4	Plaster	Purple	None	0	4.93	Positive
1	2	207	Classroom 207	Ceiling	Plaster	White	Flaking	200	6	Positive
1	2	207	Classroom 207	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	207	Classroom 207	Radiator	Metal	Red	None	0	0.23	Negative
1	2	207	Classroom 207	Pipe Cover	Metal	Purple	None	0	0.28	Negative
1	2	207	Classroom 207	Baseboard	Wood	Black	None	0	0.12	Negative
1	2	207	Classroom 207	Blackboard Frame	Wood	Black	None	0	0.13	Negative
1	2	208	Classroom 208	W1	Plaster	White	Chipping	20	8.82	Positive
1	2	208	Classroom 208	W2	Plaster	White	Chipping	10	7.72	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	208	Classroom 208	W3	Plaster	White	None	0	8.08	Positive
1	2	208	Classroom 208	W4	Plaster	White	Chipping	5	7.95	Positive
1	2	208	Classroom 208	Ceiling	Plaster	White	Flaking	100	7.1	Positive
1	2	208	Classroom 208	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	208	Classroom 208	Baseboard	Wood	Brown	None	0	0.26	Negative
1	2	208	Classroom 208	Radiator	Metal	Grey	None	0	4.74	Positive
1	2	209	Classroom 209	W1	Plaster	Blue	Flaking	7	10	Positive
1	2	209	Classroom 209	W2	Sheetrock	Blue	None	0	0	Negative
1	2	209	Classroom 209	W3	Plaster	Blue	Cracking	4	10	Positive
1	2	209	Classroom 209	W4	Plaster	Blue	Chipping	15	10	Positive
1	2	209	Classroom 209	Ceiling	Plaster	White	Flaking	300	2.67	Positive
1	2	209	Classroom 209	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	209	Classroom 209	Radiator	Metal	Grey	Chipping	20	1.07	Positive
1	2	209	Classroom 209	Pipe Cover	Metal	White	Chipping	1	0.11	Negative
1	2	210	Office 210	W1	Plaster	White	Cracking	12	10	Positive
1	2	210	Office 210	W2	Plaster	White	Cracking	15	10	Positive
1	2	210	Office 210	W3	Plaster	White	Chipping	10	10	Positive
1	2	210	Office 210	W4	Sheetrock	White	None	0	0	Negative
1	2	210	Office 210	Ceiling	Plaster	White	Flaking	75	5.97	Positive
1	2	210	Office 210	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	210	Office 210	Radiator	Metal	Grey	Chipping	5	2.28	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	210	Office 210	Pipe Cover	Metal	White	None	0	0.1	Negative
1	2	211	Classroom 211	W1	Plaster	White	Chipping	8	7.85	Positive
1	2	211	Classroom 211	W2	Plaster	White	Chipping	5	9.13	Positive
1	2	211	Classroom 211	W3	Plaster	White	Chipping	3	9.61	Positive
1	2	211	Classroom 211	W4	Plaster	White	None	0	9.89	Positive
1	2	211	Classroom 211	Ceiling	Plaster	White	Flaking	300	4.67	Positive
1	2	211	Classroom 211	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	211	Classroom 211	Radiator	Metal	Grey	Chipping	15	0.42	Negative
1	2	212	Dean's Office 212	W1	Plaster	Blue	Cracking	15	8.67	Positive
1	2	212	Dean's Office 212	W2	Plaster	Blue	Cracking	40	8.66	Positive
1	2	212	Dean's Office 212	W3	Plaster	Blue	Chipping	20	8.94	Positive
1	2	212	Dean's Office 212	W4	Plaster	Blue	Chipping	20	9	Positive
1	2	212	Dean's Office 212	Ceiling	Plaster	White	Flaking	25	4.25	Positive
1	2	212	Dean's Office 212	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	212	Dean's Office 212	Pipe Cover	Metal	White	None	0	0.11	Negative
1	2	212	Dean's Office 212	Radiator	Metal	Grey	None	0	6.39	Positive
1	2	213	Men's Staff Restroom across from Classroom 204	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	213	Men's Staff Restroom across from Classroom 204	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	213	Men's Staff Restroom across from Classroom 204	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	213	Men's Staff Restroom across from Classroom 204	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	213	Men's Staff Restroom across from Classroom 204	Ceiling	Plaster	White	Flaking	15	4.22	Positive
1	2	213	Men's Staff Restroom across from Classroom 204	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	W1	Plaster	White	Cracking	15	8.83	Positive
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	W2	Plaster	White	Cracking	30	8.65	Positive
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	W3	Plaster	White	Cracking	10	9.05	Positive
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	W4	Plaster	White	Chipping	15	9.26	Positive
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	Ceiling	Plaster	White	Flaking	15	3.14	Positive
1	2	213A	Foyer to the Men's Staff Restroom across from Classroom 204	Floor	Concrete	Blue	Friction	50	0.43	Negative
1	2	214	Classroom 214	W1	Plaster	White	Chipping	25	4.33	Positive
1	2	214	Classroom 214	W2	Plaster	White	Chipping	30	5.08	Positive
1	2	214	Classroom 214	W3	Plaster	White	Chipping	20	5.51	Positive
1	2	214	Classroom 214	W4	Plaster	White	Chipping	30	5.71	Positive
1	2	214	Classroom 214	Ceiling	Plaster	White	Flaking	400	2.67	Positive
1	2	214	Classroom 214	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	214	Classroom 214	Radiator	Metal	Grey	Chipping	20	4.48	Positive
1	2	215	Classroom 215	W1	Plaster	White	Chipping	40	6.71	Positive
1	2	215	Classroom 215	W2	Plaster	White	Flaking	15	5.93	Positive
1	2	215	Classroom 215	W3	Plaster	White	Chipping	40	5.77	Positive
1	2	215	Classroom 215	W4	Plaster	White	Chipping	40	5.72	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	215	Classroom 215	Ceiling	Plaster	White	Flaking	300	5.97	Positive
1	2	215	Classroom 215	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	215	Classroom 215	Radiator	Metal	Grey	Chipping	15	4.21	Positive
1	2	215	Classroom 215	Pipe Cover	Metal	White	None	0	0.01	Negative
1	2	216	Classroom 216	W1	Plaster	White	Chipping	15	8.82	Positive
1	2	216	Classroom 216	W2	Plaster	White	None	0	9.07	Positive
1	2	216	Classroom 216	W3	Plaster	White	Chipping	20	7.72	Positive
1	2	216	Classroom 216	W4	Plaster	White	None	0	8.15	Positive
1	2	216	Classroom 216	Ceiling	Plaster	White	Flaking	300	4.52	Positive
1	2	216	Classroom 216	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	216	Classroom 216	Radiator	Metal	Grey	Chipping	15	6.67	Positive
1	2	216	Classroom 216	Baseboard	Wood	White	Chipping	10	0.2	Negative
1	2	216	Classroom 216	Pipe Cover	Metal	White	Chipping	5	0.01	Negative
1	2	216	Classroom 216	Window Frame	Wood	White	Chipping	5	0.05	Negative
1	2	218	Computer Classroom 218	W1	Plaster	White	Chipping	10	8.86	Positive
1	2	218	Computer Classroom 218	W2	Plaster	White	Chipping	5	9.2	Positive
1	2	218	Computer Classroom 218	W3	Plaster	White	Chipping	15	8.21	Positive
1	2	218	Computer Classroom 218	W4	Plaster	White	Chipping	4	7.97	Positive
1	2	218	Computer Classroom 218	Ceiling	Plaster	White	Flaking	200	1.36	Positive
1	2	218	Computer Classroom 218	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	218	Computer Classroom 218	Radiator	Metal	Grey	Chipping	5	0.85	Positive
1	2	218	Computer Classroom 218	Pipe Cover	Metal	White	None	0	0.05	Negative
1	2	219	Boy's Restroom across Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	219	Boy's Restroom across Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	219	Boy's Restroom across Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	219	Boy's Restroom across Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	219	Boy's Restroom across Elevator	Ceiling	Plaster	White	Flaking	10	2.97	Positive
1	2	219	Boy's Restroom across Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	W1	Plaster	White	None	0	0	Negative
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	W2	Plaster	White	None	0	0	Negative
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	W3	Plaster	White	None	0	0	Negative
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	W4	Plaster	White	Flaking	5	0	Negative
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	Ceiling	Plaster	White	Flaking	15	5.7	Positive
1	2	219A	Foyer leading to the Boy's Restroom across the Elevator	Floor	Concrete	Grey	None	0	0	Negative
1	2	221	Classroom 221	W1	Plaster	White	Chipping	6	10	Positive
1	2	221	Classroom 221	W2	Plaster	White	Chipping	70	10	Positive
1	2	221	Classroom 221	W3	Plaster	Brown	Chipping	3	10	Positive
1	2	221	Classroom 221	W4	Plaster	White	Chipping	75	10	Positive
1	2	221	Classroom 221	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	221	Classroom 221	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	221	Classroom 221	Radiator	Metal	Grey	Chipping	15	0.33	Negative
1	2	221	Classroom 221	Radiator Cover	Metal	Grey	None	0	2.6	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	221	Classroom 221	Pipe Cover	Metal	White	Chipping	2	0.01	Negative
1	2	223	Dean's Office 223	W1	Plaster	White	Chipping	10	7.44	Positive
1	2	223	Dean's Office 223	W2	Plaster	White	Chipping	4	7.22	Positive
1	2	223	Dean's Office 223	W3	Plaster	White	Chipping	3	7.06	Positive
1	2	223	Dean's Office 223	W4	Plaster	White	Chipping	20	7.21	Positive
1	2	223	Dean's Office 223	Ceiling	Plaster	White	Flaking	60	4.29	Positive
1	2	223	Dean's Office 223	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	2	223	Dean's Office 223	Radiator	Metal	Grey	Chipping	10	5.52	Positive
1	2	223	Dean's Office 223	Window Frame	Wood	White	Chipping	5	3.49	Positive
1	2	223	Dean's Office 223	Baseboard	Wood	White	None	0	3.1	Positive
1	2	224	Custodial Closet adjacent to Dean's Office 223	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224	Custodial Closet adjacent to Dean's Office 223	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224	Custodial Closet adjacent to Dean's Office 223	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224	Custodial Closet adjacent to Dean's Office 223	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224	Custodial Closet adjacent to Dean's Office 223	Ceiling	Plaster	White	None	0	6.89	Positive
1	2	224	Custodial Closet adjacent to Dean's Office 223	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224.1	Service Closet outside Classroom 207	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224.1	Service Closet outside Classroom 207	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224.1	Service Closet outside Classroom 207	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224.1	Service Closet outside Classroom 207	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	224.1	Service Closet outside Classroom 207	Ceiling	Plaster	White	None	0	5.31	Positive
1	2	224.1	Service Closet outside Classroom 207	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225	Foyer leading to Girl's Restroom near Elevator	W1	Plaster	White	None	0	2.36	Positive
1	2	225	Foyer leading to Girl's Restroom near Elevator	W2	Plaster	White	None	0	5.39	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	225	Foyer leading to Girl's Restroom near Elevator	W3	Plaster	White	None	0	4.78	Positive
1	2	225	Foyer leading to Girl's Restroom near Elevator	W4	Plaster	White	Chipping	20	4.81	Positive
1	2	225	Foyer leading to Girl's Restroom near Elevator	Ceiling	Plaster	White	None	0	4.29	Positive
1	2	225	Foyer leading to Girl's Restroom near Elevator	Floor	Concrete	Grey	None	0	0.01	Negative
1	2	225	Foyer leading to Girl's Restroom near Elevator	Stair Tread	Concrete	Grey	None	0	0.01	Negative
1	2	225	Foyer leading to Girl's Restroom near Elevator	Stair Riser	Concrete	Grey	None	0	2.93	Positive
1	2	225	Foyer leading to Girl's Restroom near Elevator	Trim	Concrete	Grey	None	0	1.2	Positive
1	2	225A	Girl's Restroom near Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225A	Girl's Restroom near Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225A	Girl's Restroom near Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225A	Girl's Restroom near Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	225A	Girl's Restroom near Elevator	Ceiling	Plaster	White	Flaking	15	5.33	Positive
1	2	225A	Girl's Restroom near Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	AT14	Attic above Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	H21	Hallway from Classrooms 207 to 211	W1	Plaster	White	None	0	7.28	Positive
1	2	H21	Hallway from Classrooms 207 to 211	W2	Plaster	White	Flaking	15	10	Positive
1	2	H21	Hallway from Classrooms 207 to 211	W3	Plaster	White	Moisture Damage	15	8.64	Positive
1	2	H21	Hallway from Classrooms 207 to 211	W4	Plaster	White	Moisture Damage	40	10	Positive
1	2	H21	Hallway from Classrooms 207 to 211	Ceiling	Plaster	White	Flaking	800	9.87	Positive
1	2	H21	Hallway from Classrooms 207 to 211	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	H21A	Pipe Chase across from Classroom 209	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	H21A	Pipe Chase across from Classroom 209	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	H21A	Pipe Chase across from Classroom 209	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	H21A	Pipe Chase across from Classroom 209	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	H21A	Pipe Chase across from Classroom 209	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	H21A	Pipe Chase across from Classroom 209	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Classroom 300	Door	Metal	Red	Flaking	5	0.01	Negative
1	3	300	Classroom 300	Door Frame	Metal	Red	None	0	0.02	Negative
1	3	300	Classroom 300	Pipe Cover	Metal	White	Flaking	10	0	Negative
1	3	300	Classroom 300	Trim	Concrete	Grey	None	0	0.01	Negative
1	3	300	Classroom 300	Radiator	Metal	Grey	Chipping	15	5.44	Positive
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	W1	Plaster	White	Flaking	10	10	Positive
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	W3	Plaster	White	Flaking	15	2.63	Positive
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	W4	Plaster	White	Flaking	20	7.64	Positive
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Ceiling	Plaster	White	Flaking	800	10	Positive
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Door	Metal	Red	Cracking	5	0.07	Negative
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Door Frame	Metal	Red	None	0	0.04	Negative
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Trim	Concrete	Grey	None	0	0.01	Negative
1	2	H22	Hallway from Classroom 200 to Dean's Office 212	Pipe Cover	Metal	White	Cracking	5	0.09	Negative
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	W1	Plaster	White	Cracking	25	7.63	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	W2	Plaster	White	Cracking	60	10	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	W3	Plaster	White	Cracking	25	8.6	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	W4	Plaster	White	Cracking	25	10	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Ceiling	Plaster	White	Flaking	700	10	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC200A	Pipe Chase in Classroom 200	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC201C	Pipe Chase in Classroom 201	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC203A	Pipe Chase in Classroom 203	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC204B	Pipe Chase in Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC205A	Pipe Chase in Classroom 205	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC205A	Pipe Chase in Classroom 205	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC205A	Pipe Chase in Classroom 205	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	PC205A	Pipe Chase in Classroom 205	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC205A	Pipe Chase in Classroom 205	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC205A	Pipe Chase in Classroom 205	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC207A	Pipe Chase - Classroom 207	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC208A	Pipe Chase in Classroom 208	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC210A	Pipe Chase in Office 210	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC211A	Pipe Chase in Classroom 211	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC212A	Pipe Chase Dean's Office 212	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC212A	Pipe Chase Dean's Office 212	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC212A	Pipe Chase Dean's Office 212	W3	Brick	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	PC212A	Pipe Chase Dean's Office 212	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC212A	Pipe Chase Dean's Office 212	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC212A	Pipe Chase Dean's Office 212	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC213B	Pipe Chase in Foyer to the Men's Staff Restroom across from Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC214A	Pipe Chase in Classroom 214	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC215A	Pipe Chase in Classroom 215	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC216A	Pipe Chase in Classroom 216	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC216A	Pipe Chase in Classroom 216	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC216A	Pipe Chase in Classroom 216	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC216A	Pipe Chase in Classroom 216	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC216A	Pipe Chase in Classroom 216	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	PC216A	Pipe Chase in Classroom 216	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC218A	Pipe Chase in Computer Classroom 218	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	PC219D	Pipe Chase in Foyer leading to the Boy's Restroom across the Elevator	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Stair Riser	Concrete	Grey	None	0	0.18	Negative
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Handrail	Metal	Grey	Chipping	10	0.76	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Pipe Cover	Metal	White	None	0	0.06	Negative
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	pipe	Metal	White	Flaking	5	8.63	Positive
1	2	H23	Hallway from Classroom 221 to Girl's Restroom	Trim	Concrete	Grey	None	0	0.19	Negative
1	2	S01-2	Stairwell 1 across from Classroom 204	W1	Plaster	White	Flaking	15	0	Negative
1	2	S01-2	Stairwell 1 across from Classroom 204	W2	Plaster	White	Moisture Damage	40	0.02	Negative
1	2	S01-2	Stairwell 1 across from Classroom 204	W3	Plaster	White	Cracking	20	0.05	Negative
1	2	S01-2	Stairwell 1 across from Classroom 204	W4	Plaster	White	Moisture Damage	5	0	Negative
1	2	S01-2	Stairwell 1 across from Classroom 204	Ceiling	Plaster	White	None	0	4.87	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report							
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School							
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125							
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]	
1	2	S01-2	Stairwell 1 across from Classroom 204	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	2	S01-2	Stairwell 1 across from Classroom 204	Newel Post	Metal	Grey	Friction	5	5.47	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Trim	Concrete	Grey	None	0	2.34	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Stair Riser	Concrete	Grey	Flaking	5	5.75	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Stringer	Concrete	Grey	None	0	5.33	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Handrail	Metal	Grey	Friction	10	0	Negative	
1	2	S01-2	Stairwell 1 across from Classroom 204	Spindle	Metal	Grey	Chipping	10	5.79	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Radiator	Metal	Grey	Chipping	10	3.03	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Radiator Cover	Metal	Grey	Chipping	5	1.34	Positive	
1	2	S01-2	Stairwell 1 across from Classroom 204	Window Rails	Metal	Red	Flaking	10	0.79	Positive	
1	2	S02-2	Stairs across the Elevator	W1	Plaster	White	Flaking	10	2.34	Positive	
1	2	S02-2	Stairs across the Elevator	W2	Plaster	White	Moisture Damage	15	2.58	Positive	
1	2	S02-2	Stairs across the Elevator	W3	Plaster	White	Moisture Damage	15	6.78	Positive	
1	2	S02-2	Stairs across the Elevator	W4	Plaster	White	Moisture Damage	15	2.95	Positive	
1	2	S02-2	Stairs across the Elevator	Ceiling	Plaster	White	Efflorescence	5	4.87	Positive	
1	2	S02-2	Stairs across the Elevator	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	2	S02-2	Stairs across the Elevator	Newel Post	Metal	Grey	Flaking	5	4.27	Positive	
1	2	S02-2	Stairs across the Elevator	Trim	Concrete	Grey	None	0	0.05	Negative	
1	2	S02-2	Stairs across the Elevator	Stair Riser	Concrete	Grey	Flaking	5	4.73	Positive	
1	2	S02-2	Stairs across the Elevator	Stringer	Concrete	Grey	None	0	5.33	Positive	
1	2	S02-2	Stairs across the Elevator	Handrail	Metal	Grey	Friction	10	0.03	Negative	
1	2	S02-2	Stairs across the Elevator	Spindle	Metal	Grey	Chipping	10	1.77	Positive	
1	2	S02-2	Stairs across the Elevator	Radiator	Metal	Grey	Flaking	20	0.27	Negative	
1	2	S02-2	Stairs across the Elevator	Radiator Cover	Metal	Grey	Flaking	10	1.77	Positive	
1	2	S02-2	Stairs across the Elevator	Pipe Cover	Metal	Grey	None	0	0.09	Negative	
1	2	S03-2	East Stairwell adjacent to Classroom 221	W1	Plaster	White	Chipping	30	8.52	Positive	

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	S03-2	East Stairwell adjacent to Classroom 221	W2	Plaster	White	Flaking	80	8.56	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	W3	Plaster	White	Flaking	80	7.54	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	W4	Plaster	White	Chipping	40	4.53	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	Ceiling	Plaster	White	Efflorescence	50	1.46	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S03-2	East Stairwell adjacent to Classroom 221	Trim	Concrete	Grey	Friction	15	0.43	Negative
1	2	S03-2	East Stairwell adjacent to Classroom 221	Radiator	Metal	Grey	Chipping	10	3.22	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	Radiator Cover	Metal	Grey	Chipping	5	4.04	Positive
1	2	S03-2	East Stairwell adjacent to Classroom 221	Pipe Cover	Metal	Grey	Flaking	10	0.08	Negative
1	2	S04-2	West Stairwell	W1	Plaster	White	Cracking	10	1	Positive
1	2	S04-2	West Stairwell	W2	Plaster	White	Chipping	10	1.5	Positive
1	2	S04-2	West Stairwell	W3	Plaster	White	Flaking	60	7.64	Positive
1	2	S04-2	West Stairwell	W4	Plaster	White	Moisture Damage	50	9.48	Positive
1	2	S04-2	West Stairwell	Ceiling	Plaster	White	Alligatoring	60	6.89	Positive
1	2	S04-2	West Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S04-2	West Stairwell	Stair Riser	Concrete	Grey	Friction	10	0.13	Negative
1	2	S04-2	West Stairwell	Pipe Cover	Metal	Grey	Chipping	5	0.11	Negative
1	2	S04-2	West Stairwell	Radiator	Metal	Grey	Chipping	15	1.93	Positive
1	2	S04-2	West Stairwell	Radiator Cover	Metal	Grey	Flaking	11	5.14	Positive
1	2	S04-2	West Stairwell	Window Frame	Metal	Grey	Chipping	15	0.2	Negative
1	2	S04-2	West Stairwell	Handrail	Metal	Grey	Chipping	20	0.2	Negative
1	2	S04A-2	West Stairwell Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S04A-2	West Stairwell Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S04A-2	West Stairwell Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S04A-2	West Stairwell Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	2	S04A-2	West Stairwell Fire Tower	Ceiling	Plaster	White	Flaking	150	5.21	Positive
1	2	S04A-2	West Stairwell Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S04A-2	West Stairwell Fire Tower	Window Bars	Metal	Grey	Chipping	73	No Access	Assumed
1	2	S202	East Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S202	East Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S202	East Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S202	East Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	2	S202	East Fire Tower	Ceiling	Plaster	White	Flaking	150	4.56	Positive
1	2	S202	East Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S202	East Fire Tower	Window Frame	Wood	Grey	Chipping	5	0.15	Negative
1	2	S202	East Fire Tower	Window Bars	Metal	Grey	Chipping	50	No Access	Assumed
1	2	S202	East Fire Tower	Window Rails	Metal	Grey	Chipping	6	0.11	Negative
1	2	S202	East Fire Tower	Handrail	Metal	Grey	Chipping	10	0.21	Negative
1	2	S206	Stairs leading into Classroom 221	W1	Plaster	White	None	0	8.64	Positive
1	2	S206	Stairs leading into Classroom 221	W2	Plaster	White	Flaking	5	8.02	Positive
1	2	S206	Stairs leading into Classroom 221	W3	Plaster	White	None	0	2.36	Positive
1	2	S206	Stairs leading into Classroom 221	W4	Plaster	White	Chipping	5	8.74	Positive
1	2	S206	Stairs leading into Classroom 221	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	2	S206	Stairs leading into Classroom 221	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	2	S206	Stairs leading into Classroom 221	Window Frame	Wood	Grey	Chipping	5	0.06	Negative
1	2	S206	Stairs leading into Classroom 221	Stair Riser	Concrete	Grey	None	0	0.16	Negative
1	2	S206	Stairs leading into Classroom 221	pipe	Metal	Grey	Chipping	5	7.33	Positive
1	2	S206	Stairs leading into Classroom 221	Trim	Concrete	Grey	None	0	0.25	Negative
1	3	300	Classroom 300	W1	Plaster	White	Chipping	13	9.5	Positive
1	3	300	Classroom 300	W2	Plaster	White	Chipping	10	6.15	Positive
1	3	300	Classroom 300	W3	Plaster	White	Chipping	50	7.72	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	300	Classroom 300	W4	Plaster	White	Chipping	50	7.71	Positive
1	3	300	Classroom 300	Ceiling	Plaster	White	Flaking	70	0	Negative
1	3	300	Classroom 300	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	300	Classroom 300	Pipe Cover	Metal	White	None	0	0.12	Negative
1	3	300	Classroom 300	Radiator	Metal	Grey	Chipping	12	0.71	Positive
1	3	301	Classroom 301	W1	Plaster	White	Chipping	4	8.39	Positive
1	3	301	Classroom 301	W2	Plaster	White	Chipping	40	5.88	Positive
1	3	301	Classroom 301	W3	Plaster	White	Chipping	50	6.56	Positive
1	3	301	Classroom 301	W4	Plaster	White	Chipping	1	4.24	Positive
1	3	301	Classroom 301	Ceiling	Plaster	White	Flaking	50	0	Negative
1	3	301	Classroom 301	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	301	Classroom 301	Pipe Cover	Metal	White	None	0	0.23	Negative
1	3	301A	Lab Prep Room between Classrooms 302 and 301	W1	sheetrock	White	None	0	0	Negative
1	3	301A	Lab Prep Room between Classrooms 302 and 301	W1	Plaster	White	None	0	4.26	Positive
1	3	301A	Lab Prep Room between Classrooms 302 and 301	W2	Plaster	White	None	0	6.79	Positive
1	3	301A	Lab Prep Room between Classrooms 302 and 301	W3	Plaster	White	None	0	4.23	Positive
1	3	301A	Lab Prep Room between Classrooms 302 and 301	W4	Plaster	White	None	0	3.16	Positive
1	3	301A	Lab Prep Room between Classrooms 302 and 301	Ceiling	Plaster	White	Flaking	60	5.67	Positive
1	3	301A	Lab Prep Room between Classrooms 302 and 301	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	302	Classroom 302	W1	Plaster	White	None	0	9.31	Positive
1	3	302	Classroom 302	W2	Plaster	White	Chipping	1	6.48	Positive
1	3	302	Classroom 302	W3	Plaster	White	Chipping	15	6.31	Positive
1	3	302	Classroom 302	W4	Plaster	White	Flaking	40	9.38	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	302	Classroom 302	Ceiling	Plaster	White	Flaking	80	4.25	Positive
1	3	302	Classroom 302	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	W1	Plaster	White	Cracking	2	5.25	Positive
1	3	303	Classroom 303	W2	Plaster	White	Chipping	2	6.81	Positive
1	3	303	Classroom 303	W3	Plaster	White	Chipping	1	5.16	Positive
1	3	303	Classroom 303	W4	Plaster	White	Chipping	10	2.25	Positive
1	3	303	Classroom 303	Ceiling	Plaster	White	Flaking	70	3.22	Positive
1	3	303	Classroom 303	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	303	Classroom 303	Radiator	Plaster	White	Flaking	10	0.12	Negative
1	3	303	Classroom 303	Pipe Cover	Metal	White	None	0	0.11	Negative
1	3	304	Classroom 304	W1	Plaster	White	None	0	8.85	Positive
1	3	304	Classroom 304	W2	Plaster	White	Chipping	5	8.87	Positive
1	3	304	Classroom 304	W3	Plaster	White	None	0	5.56	Positive
1	3	304	Classroom 304	W4	Plaster	White	None	0	8.2	Positive
1	3	304	Classroom 304	Ceiling	Plaster	White	Flaking	200	6.79	Positive
1	3	304	Classroom 304	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	304	Classroom 304	Radiator	Metal	Grey	Chipping	20	0.7	Positive
1	3	304A	Girl's Restroom across from Office 312	Ceiling	Plaster	White	None	0	9.83	Positive
1	3	304A	Girl's Restroom across from Office 312	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	304A	Girl's Restroom across from Office 312	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	304A	Girl's Restroom across from Office 312	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	304A	Girl's Restroom across from Office 312	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	304A	Girl's Restroom across from Office 312	Ceiling	Plaster	White	Flaking	10	3.14	Positive
1	3	304A	Girl's Restroom across from Office 312	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	W1	Plaster	White	None	0	5.22	Positive
1	3	305	Classroom 305	W2	Plaster	White	Flaking	10	4.68	Positive
1	3	305	Classroom 305	W3	Plaster	White	Flaking	20	4.56	Positive
1	3	305	Classroom 305	W4	Plaster	White	Efflorescence	50	6.55	Positive
1	3	305	Classroom 305	Ceiling	Plaster	White	Chipping	100	3.22	Positive
1	3	305	Classroom 305	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	305	Classroom 305	Radiator	Metal	Grey	Chipping	15	1.6	Positive
1	3	305	Classroom 305	Pipe Cover	Metal	White	None	0	0.01	Negative
1	3	306	Office 306 in West Stairwell	W1	Plaster	Yellow	None	0	8.56	Positive
1	3	306	Office 306 in West Stairwell	W2	Plaster	Yellow	None	0	9.32	Positive
1	3	306	Office 306 in West Stairwell	W3	Plaster	Yellow	Efflorescence	15	9.12	Positive
1	3	306	Office 306 in West Stairwell	W4	Plaster	Yellow	None	0	9.51	Positive
1	3	306	Office 306 in West Stairwell	Ceiling	Plaster	White	Efflorescence	15	5.23	Positive
1	3	306	Office 306 in West Stairwell	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	307	Classroom 307	W1	Plaster	White	Chipping	60	10	Positive
1	3	307	Classroom 307	W2	Plaster	White	Chipping	25	6.43	Positive
1	3	307	Classroom 307	W3	Plaster	White	Chipping	70	8.43	Positive
1	3	307	Classroom 307	W4	Plaster	White	Chipping	40	6.99	Positive
1	3	307	Classroom 307	Ceiling	Plaster	White	Flaking	90	4.28	Positive
1	3	307	Classroom 307	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	307	Classroom 307	Radiator	Metal	Grey	Chipping	50	2.22	Positive
1	3	307	Classroom 307	Pipe Cover	Metal	Grey	Chipping	1	0.12	Negative
1	3	307B	Custodial Closet adjacent to Classroom 307	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307B	Custodial Closet adjacent to Classroom 307	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307B	Custodial Closet adjacent to Classroom 307	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307B	Custodial Closet adjacent to Classroom 307	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	307B	Custodial Closet adjacent to Classroom 307	Ceiling	Plaster	White	None	0	7.23	Positive
1	3	307B	Custodial Closet adjacent to Classroom 307	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	308	Classroom 308	W1	Plaster	White	Chipping	25	10	Positive
1	3	308	Classroom 308	W2	Plaster	White	Moisture Damage	60	10	Positive
1	3	308	Classroom 308	W3	Plaster	White	Chipping	15	10	Positive
1	3	308	Classroom 308	W4	Plaster	White	Flaking	5	10	Positive
1	3	308	Classroom 308	W4	Sheetrock	Blue	None	0	0	Negative
1	3	308	Classroom 308	Ceiling	Plaster	White	Alligatoring	50	4.12	Positive
1	3	308	Classroom 308	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	309	Classroom 309	W1	Plaster	White	Chipping	1	10	Positive
1	3	309	Classroom 309	W2	Plaster	White	Chipping	10	10	Positive
1	3	309	Classroom 309	W3	Plaster	White	Chipping	20	10	Positive
1	3	309	Classroom 309	W4	Plaster	White	Chipping	1	6.41	Positive
1	3	309	Classroom 309	Radiator on W4	Metal	White	Flaking	10	0.06	Negative
1	3	309	Classroom 309	Ceiling	Plaster	White	Flaking	100	5.16	Positive
1	3	309	Classroom 309	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	311	Classroom 311	W1	Plaster	White	Chipping	20	10	Positive
1	3	311	Classroom 311	W2	Plaster	White	Chipping	20	7.3	Positive
1	3	311	Classroom 311	W3	Plaster	White	Chipping	25	10	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	311	Classroom 311	W4	Plaster	White	Chipping	20	5.55	Positive
1	3	311	Classroom 311	Radiator	Metal	Grey	Chipping	20	0.8	Positive
1	3	311	Classroom 311	Pipe Cover	Metal	Grey	Chipping	1	0.33	Negative
1	3	311	Classroom 311	Ceiling	Plaster	White	Flaking	100	3.29	Positive
1	3	311	Classroom 311	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	312	Office 312	W1	Plaster	White	Chipping	10	9.28	Positive
1	3	312	Office 312	W2	Plaster	White	Chipping	15	10	Positive
1	3	312	Office 312	W3	Plaster	White	Chipping	25	9.23	Positive
1	3	312	Office 312	W4	Plaster	White	Chipping	1	8.4	Positive
1	3	312	Office 312	Pipe Cover	Metal	White	Chipping	1	0.12	Negative
1	3	312	Office 312	Ceiling	Plaster	White	Flaking	100	4.21	Positive
1	3	312	Office 312	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	313	Men's Restroom across Room 304	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313	Men's Restroom across Room 304	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313	Men's Restroom across Room 304	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313	Men's Restroom across Room 304	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313	Men's Restroom across Room 304	Ceiling	Plaster	White	Moisture Damage	4	8.63	Positive
1	3	313	Men's Restroom across Room 304	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313A	Foyer to Men's Restroom across from Classroom 304	W1	Plaster	White	Flaking	10	3.91	Positive
1	3	313A	Foyer to Men's Restroom across from Classroom 304	W2	Plaster	White	Flaking	15	2.55	Positive
1	3	313A	Foyer to Men's Restroom across from Classroom 304	W3	Plaster	White	None	0	1.99	Positive
1	3	313A	Foyer to Men's Restroom across from Classroom 304	W4	Plaster	White	None	0	2.28	Positive
1	3	313A	Foyer to Men's Restroom across from Classroom 304	Ceiling	Plaster	White	None	0	3.69	Positive
1	3	313A	Foyer to Men's Restroom across from Classroom 304	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	W1	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	313B	Pipe Chase in Foyer to Men's Restroom across from Classroom 304	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	314	Classroom 314	W1	Plaster	White	Chipping	10	10	Positive
1	3	314	Classroom 314	W2	Plaster	White	Chipping	20	10	Positive
1	3	314	Classroom 314	W3	Plaster	White	Chipping	40	10	Positive
1	3	314	Classroom 314	W4	Plaster	White	Chipping	10	10	Positive
1	3	314	Classroom 314	Radiator	Metal	White	Chipping	25	10	Positive
1	3	314	Classroom 314	Pipe Cover	Metal	White	Chipping	4	10	Positive
1	3	314	Classroom 314	Ceiling	Plaster	White	Flaking	300	9.24	Positive
1	3	314	Classroom 314	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	315	Classroom 315	W1	Plaster	White	Chipping	1	10	Positive
1	3	315	Classroom 315	W2	Plaster	White	None	0	10	Positive
1	3	315	Classroom 315	W3	Plaster	White	Chipping	40	10	Positive
1	3	315	Classroom 315	W4	Plaster	White	None	0	6.15	Positive
1	3	315	Classroom 315	Ceiling	Plaster	White	Alligatoring	400	5.11	Positive
1	3	315	Classroom 315	Radiator	Metal	White	Chipping	30	1.2	Positive
1	3	315	Classroom 315	Pipe Cover	Metal	White	Chipping	2	0.15	Negative
1	3	315	Classroom 315	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	316	Classroom 316	W1	Plaster	White	Chipping	10	10	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	316	Classroom 316	W2	Plaster	White	Cracking	10	10	Positive
1	3	316	Classroom 316	W3	Plaster	White	Chipping	15	9.94	Positive
1	3	316	Classroom 316	W4	Plaster	White	None	0	9.09	Positive
1	3	316	Classroom 316	Pipe Cover	Metal	White	None	0	0.1	Negative
1	3	316	Classroom 316	Radiator	Metal	Grey	Chipping	5	3.45	Positive
1	3	316	Classroom 316	Window Frame	Wood	Brown	Chipping	10	0.07	Negative
1	3	316	Classroom 316	Baseboard	Wood	Brown	Friction	15	0.09	Negative
1	3	316	Classroom 316	Ceiling	Plaster	White	Flaking	800	8.33	Positive
1	3	316	Classroom 316	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	318	Classroom 318	W1	Plaster	White	Cracking	40	8.11	Positive
1	3	318	Classroom 318	W2	Plaster	White	Cracking	20	9.15	Positive
1	3	318	Classroom 318	W3	Plaster	White	Chipping	20	7.59	Positive
1	3	318	Classroom 318	W4	Plaster	White	Chipping	20	9.2	Positive
1	3	318	Classroom 318	Radiator	Metal	White	Chipping	30	0.28	Negative
1	3	318	Classroom 318	Pipe Cover	Metal	White	Chipping	20	0.28	Negative
1	3	318	Classroom 318	Ceiling	Plaster	White	Flaking	300	9.32	Positive
1	3	318	Classroom 318	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	319	Office 319	W1	Plaster	White	Chipping	5	9.94	Positive
1	3	319	Office 319	W2	Plaster	White	Chipping	10	9.31	Positive
1	3	319	Office 319	W3	Plaster	White	Chipping	20	8.46	Positive
1	3	319	Office 319	W4	Plaster	White	Chipping	30	8.08	Positive
1	3	319	Office 319	Radiator	Metal	Grey	Chipping	5	5.56	Positive
1	3	319	Office 319	Pipe	Metal	Grey	Alligating	40	5.1	Positive
1	3	319	Office 319	Pipe Cover	Metal	White	None	0	0.2	Negative
1	3	319	Office 319	Baseboard	Wood	Brown	None	0	0.09	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	319	Office 319	Ceiling	Plaster	White	Flaking	150	4.66	Positive
1	3	319	Office 319	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	320A	Teacher's Lounge 320	Ductwork, Exterior	Metal	White	None	0	5.67	Positive
1	3	320A	Teacher's Lounge 320	W1	Plaster	White	Flaking	1	10	Positive
1	3	320A	Teacher's Lounge 320	W2	Plaster	White	Cracking	40	9.05	Positive
1	3	320A	Teacher's Lounge 320	W3	Plaster	White	Chipping	10	10	Positive
1	3	320A	Teacher's Lounge 320	W4	Plaster	White	Cracking	20	9.67	Positive
1	3	320A	Teacher's Lounge 320	Ceiling	Plaster	White	Flaking	100	8.22	Positive
1	3	320A	Teacher's Lounge 320	Pipe	Metal	White	None	0	10	Positive
1	3	320A	Teacher's Lounge 320	Baseboard	Concrete	White	None	0	0.72	Positive
1	3	320A	Teacher's Lounge 320	Radiator	Metal	White	None	0	7.13	Positive
1	3	320A	Teacher's Lounge 320	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	320B	Teacher's Lounge 320 Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320B	Teacher's Lounge 320 Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320B	Teacher's Lounge 320 Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320B	Teacher's Lounge 320 Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320B	Teacher's Lounge 320 Restroom	Ceiling	Plaster	White	Flaking	25	2.54	Positive
1	3	320B	Teacher's Lounge 320 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320C	Teacher's Lounge 320 Back Room	W1	Plaster	White	Cracking	15	10	Positive
1	3	320C	Teacher's Lounge 320 Back Room	W2	Plaster	White	Cracking	15	8.68	Positive
1	3	320C	Teacher's Lounge 320 Back Room	W3	Plaster	White	Cracking	20	10	Positive
1	3	320C	Teacher's Lounge 320 Back Room	W4	Plaster	White	Cracking	10	9.61	Positive
1	3	320C	Teacher's Lounge 320 Back Room	Ceiling	Plaster	White	Flaking	25	4.97	Positive
1	3	320C	Teacher's Lounge 320 Back Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	320C	Teacher's Lounge 320 Back Room	Radiator	Metal	Grey	Chipping	1	5.08	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	322	Gymnasium	W1	Plaster	Yellow	Chipping	100	3.69	Positive
1	3	322	Gymnasium	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	322	Gymnasium	W2	Plaster	Yellow	Chipping	150	7.71	Positive
1	3	322	Gymnasium	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	322	Gymnasium	W3	Plaster	Yellow	Cracking	100	4.42	Positive
1	3	322	Gymnasium	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	322	Gymnasium	W4	Plaster	Yellow	Chipping	100	5.38	Positive
1	3	322	Gymnasium	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	322	Gymnasium	Radiator	Metal	Grey	Chipping	40	0.93	Positive
1	3	322	Gymnasium	Baseboard	Wood	Brown	Chipping	100	0.11	Negative
1	3	322	Gymnasium	Ceiling	Plaster	White	Flaking	300	No Access	Assumed
1	3	322	Gymnasium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	323	Counselor's Office 323	W1	Plaster	White	None	0	7.13	Positive
1	3	323	Counselor's Office 323	W2	Plaster	White	None	0	5.58	Positive
1	3	323	Counselor's Office 323	W3	Plaster	White	Flaking	25	7.42	Positive
1	3	323	Counselor's Office 323	W4	Plaster	White	Flaking	10	9.32	Positive
1	3	323	Counselor's Office 323	Ceiling	Plaster	White	Flaking	20	2.34	Positive
1	3	323	Counselor's Office 323	Baseboard	Wood	Brown	None	0	1.99	Positive
1	3	323	Counselor's Office 323	Radiator	Metal	Grey	Chipping	5	0.03	Negative
1	3	323	Counselor's Office 323	Pipe Cover	Metal	White	Chipping	1	0.02	Negative
1	3	323	Counselor's Office 323	Window Frame	Metal	Brown	Chipping	15	2.1	Positive
1	3	323	Counselor's Office 323	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323	Counselor's Office 323	Door Frame	Metal	Brown	Flaking	2	3.46	Positive
1	3	323A	Girl's Locker Room Upper Level	W1	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
1	3	323A	Girl's Locker Room Upper Level	W2	Plaster	White	Alligating	50	2.01	Positive
1	3	323A	Girl's Locker Room Upper Level	W3	Plaster	White	Alligating	60	4.06	Positive
1	3	323A	Girl's Locker Room Upper Level	W4	CMU	White	None	0	0.01	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	323A	Girl's Locker Room Upper Level	Ceiling	Plaster	White	Alligating	50	8.63	Positive
1	3	323A	Girl's Locker Room Upper Level	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	323AA	Girl's Locker Room Lower Level	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	323AA	Girl's Locker Room Lower Level	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	323AA	Girl's Locker Room Lower Level	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	323AA	Girl's Locker Room Lower Level	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	323AA	Girl's Locker Room Lower Level	Ceiling	Plaster	White	Moisture Damage	100	5.9	Positive
1	3	323AA	Girl's Locker Room Lower Level	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	323B	Boy's Locker Room	W1	CMU	White	None	0	7.65	Positive
1	3	323B	Boy's Locker Room	W1	CMU	White	None	0	0	Negative
1	3	323B	Boy's Locker Room	W1	Plaster	White	Chipping	15	7.49	Positive
1	3	323B	Boy's Locker Room	W2	CMU	White	None	0	0	Negative
1	3	323B	Boy's Locker Room	W3	Plaster	White	Alligating	40	2.71	Positive
1	3	323B	Boy's Locker Room	W4	CMU	White	None	0	0	Negative
1	3	323B	Boy's Locker Room	Ceiling	Plaster	White	Chipping	50	4.39	Positive
1	3	323B	Boy's Locker Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	Ceiling	Plaster	White	Chipping	10	1.39	Positive
1	3	323D	Custodial Closet adjacent to Counselor's Office 323	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	3	324	Weight Room	W1	Plaster	White	Flaking	20	8.43	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	324	Weight Room	W2	Plaster	White	Chipping	40	10	Positive
1	3	324	Weight Room	W3	Plaster	White	Chipping	20	9.84	Positive
1	3	324	Weight Room	W4	Sheetrock	White	None	0	0	Negative
1	3	324	Weight Room	Ceiling	Plaster	White	Chipping	75	5.63	Positive
1	3	324	Weight Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	3	324	Weight Room	Pipe Cover	Metal	White	Chipping	5	0.18	Negative
1	3	324	Weight Room	Radiator Cover	Metal	Grey	Chipping	15	5.22	Positive
1	3	324	Weight Room	Radiator	Metal	Grey	Chipping	20	5.01	Positive
1	3	324	Weight Room	Window Rails	Metal	White	Chipping	40	0.79	Positive
1	3	H31	Hallway from Classrooms 307 to 311	W1	Plaster	White	Flaking	10	9.63	Positive
1	3	H31	Hallway from Classrooms 307 to 311	W2	Plaster	White	None	0	10	Positive
1	3	H31	Hallway from Classrooms 307 to 311	W3	Plaster	White	Moisture Damage	15	8.93	Positive
1	3	H31	Hallway from Classrooms 307 to 311	W4	Plaster	White	Moisture Damage	60	7.95	Positive
1	3	H31	Hallway from Classrooms 307 to 311	Ceiling	Plaster	White	Flaking	800	7.23	Positive
1	3	H31	Hallway from Classrooms 307 to 311	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	H31A	Pipe Chase across from Classroom 309	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	H31	Hallway from Classrooms 307 to 311	Door Frame	Metal	Red	None	0	0.1	Negative
1	3	H31	Hallway from Classrooms 307 to 311	Door	Metal	Red	Flaking	5	0.04	Negative
1	3	H31	Hallway from Classrooms 307 to 311	Trim	Concrete	Grey	None	0	0.02	Negative
1	3	H31	Hallway from Classrooms 307 to 311	Pipe Cover	Metal	Red	None	0	0.07	Negative
1	3	H32	Hallway from Classroom 300 to Office 312	W1	Plaster	White	Moisture Damage	20	10	Positive
1	3	H32	Hallway from Classroom 300 to Office 312	W2	Plaster	White	Flaking	15	9.63	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	H32	Hallway from Classroom 300 to Office 312	W3	Plaster	White	Flaking	10	10	Positive
1	3	H32	Hallway from Classroom 300 to Office 312	W4	Plaster	White	Flaking	10	10	Positive
1	3	H32	Hallway from Classroom 300 to Office 312	Ceiling	Plaster	White	Flaking	800	4.52	Positive
1	3	H32	Hallway from Classroom 300 to Office 312	Floor	Concrete	Grey	None	0	0.01	Negative
1	3	H32	Hallway from Classroom 300 to Office 312	Trim	Concrete	Grey	None	0	0.01	Negative
1	3	H32	Hallway from Classroom 300 to Office 312	Door	Metal	Blue	None	0	0.06	Negative
1	3	H32	Hallway from Classroom 300 to Office 312	Door Frame	Metal	Blue	None	0	0.03	Negative
1	3	H32	Hallway from Classroom 300 to Office 312	Pipe Cover	Metal	White	None	0	0.12	Negative
1	3	H33	Hallway at Gymnasium	W1	Plaster	White	Chipping	10	8.8	Positive
1	3	H33	Hallway at Gymnasium	W2	Plaster	White	Flaking	5	8.63	Positive
1	3	H33	Hallway at Gymnasium	W3	Plaster	White	Chipping	10	7.94	Positive
1	3	H33	Hallway at Gymnasium	W4	Plaster	White	Moisture Damage	25	6.43	Positive
1	3	H33	Hallway at Gymnasium	Ceiling	Plaster	White	Flaking	500	4.98	Positive
1	3	H33	Hallway at Gymnasium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC300A	Pipe Chase in Classroom 300	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC303A	Pipe Chase in Classroom 303	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC304B	Pipe Chase in Classroom 304	W1	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	PC304B	Pipe Chase in Classroom 304	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC304B	Pipe Chase in Classroom 304	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC304B	Pipe Chase in Classroom 304	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC304B	Pipe Chase in Classroom 304	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC304B	Pipe Chase in Classroom 304	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC305A	Pipe Chase in Classroom 305	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC307A	Pipe Chase in Classroom 307	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC308A	Pipe Chase in Classroom 308	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC310A	Pipe Chase in Classroom 310	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC311A	Pipe Chase in Classroom 311	W1	Brick	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	PC311A	Pipe Chase in Classroom 311	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC311A	Pipe Chase in Classroom 311	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC311A	Pipe Chase in Classroom 311	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC311A	Pipe Chase in Classroom 311	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC311A	Pipe Chase in Classroom 311	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC312A	Pipe Chase in Office 312	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC314A	Pipe Chase in Classroom 314	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC315A	Pipe Chase in Classroom 315	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC317A	Pipe Chase in Classroom 317	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC318A	Pipe Chase in Classroom 318	W1	Brick	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	PC318A	Pipe Chase in Classroom 318	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC318A	Pipe Chase in Classroom 318	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC318A	Pipe Chase in Classroom 318	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC318A	Pipe Chase in Classroom 318	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC318A	Pipe Chase in Classroom 318	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	PC319A	Pipe Chase in Office 319	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	H33	Hallway at Gymnasium	Door	Metal	Blue	Flaking	5	0	Negative
1	3	H33	Hallway at Gymnasium	Door Frame	Metal	Blue	None	0	0.02	Negative
1	3	H33	Hallway at Gymnasium	Radiator	Metal	Grey	Chipping	25	5.9	Positive
1	3	H33	Hallway at Gymnasium	Radiator Cover	Metal	Grey	Chipping	10	6.99	Positive
1	3	H33	Hallway at Gymnasium	Pipe Cover	Metal	White	Chipping	15	0.02	Negative
1	3	H33	Hallway at Gymnasium	Trim	Concrete	Grey	None	0	0.2	Negative
1	3	S01-3	Stairwell 1 adjacent to Office 312	W1	Plaster	White	Chipping	5	2.83	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	W2	Plaster	White	Moisture Damage	20	2.42	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	W3	Plaster	White	Moisture Damage	30	2.98	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	W4	Plaster	White	Moisture Damage	40	8.84	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Ceiling	Plaster	White	None	0	5.63	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S01-3	Stairwell 1 adjacent to Office 312	Spindle	Metal	Grey	Flaking	15	5.36	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Stringer	Metal	Grey	None	0	5.34	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Newel Post	Metal	Grey	Flaking	5	5.86	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Window Rails	Metal	Red	Flaking	5	0	Negative
1	3	S01-3	Stairwell 1 adjacent to Office 312	Handrail	Metal	Red	Flaking	20	0	Negative
1	3	S01-3	Stairwell 1 adjacent to Office 312	Stair Riser	Concrete	Grey	None	0	4.93	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	S01-3	Stairwell 1 adjacent to Office 312	Radiator Cover	Metal	Grey	Flaking	10	2.82	Positive
1	3	S01-3	Stairwell 1 adjacent to Office 312	Radiator	Metal	Grey	Flaking	20	0.03	Negative
1	3	S01-3	Stairwell 1 adjacent to Office 312	Trim	Concrete	Grey	None	0	0.03	Negative
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	W1	Plaster	White	Flaking	5	5.83	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	W2	Plaster	White	Moisture Damage	5	3.84	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	W3	Plaster	White	Moisture Damage	15	7.85	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	W4	Plaster	White	Moisture Damage	40	2.75	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Ceiling	Plaster	White	None	0	4.32	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Spindle	Metal	Grey	Flaking	10	7.37	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Stringer	Metal	Grey	Flaking	5	5.31	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Newel Post	Metal	Grey	None	0	5.86	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Trim	Concrete	Grey	None	0	3.51	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Handrail	Metal	Grey	Flaking	20	0.05	Negative
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Stair Riser	Concrete	Grey	Flaking	15	5.86	Positive
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Radiator Cover	Metal	Grey	Flaking	5	0.1	Negative
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Radiator	Metal	Grey	Flaking	20	0.03	Negative
1	3	S02-3	Stairwell 2 adjacent to Teacher's Lounge 320	Pipe Cover	Metal	White	Cracking	5	0.08	Negative
1	3	S03-3	East Fire Tower	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	Ceiling	Plaster	White	Chipping	100	4.69	Positive
1	3	S03-3	East Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S03-3	East Fire Tower	Window Frame	Wood	Grey	Chipping	2	0.43	Negative
1	3	S03-3	East Fire Tower	Handrail	Metal	Grey	Flaking	5	0.13	Negative
1	3	S03-3	East Fire Tower	Window Rails	Metal	Grey	Flaking	6	0.08	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	S03-3	East Fire Tower	Window Bars	Metal	Grey	Flaking	60	No Access	Assumed
1	3	S03A-3	East Stairwell	W1	Plaster	White	Flaking	10	8.43	Positive
1	3	S03A-3	East Stairwell	W2	Plaster	White	Flaking	150	9.53	Positive
1	3	S03A-3	East Stairwell	W3	Plaster	White	Efflorescence	80	10	Positive
1	3	S03A-3	East Stairwell	W4	Plaster	White	Efflorescence	50	8.56	Positive
1	3	S03A-3	East Stairwell	Ceiling	Plaster	White	Efflorescence	300	6.75	Positive
1	3	S03A-3	East Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S03A-3	East Stairwell	Handrail	Metal	Grey	Chipping	5	0.14	Negative
1	3	S03A-3	East Stairwell	Radiator	Metal	Grey	Chipping	50	6.18	Positive
1	3	S03A-3	East Stairwell	Radiator Cover	Metal	Grey	Chipping	15	5.83	Positive
1	3	S03A-3	East Stairwell	Window Rails	Metal	Grey	Flaking	5	0.18	Negative
1	3	S03A-3	East Stairwell	Trim	Concrete	Grey	Flaking	15	0.36	Negative
1	3	S03A-3	East Stairwell	Pipe Cover	Metal	Grey	Chipping	5	0.06	Negative
1	3	S04-3	West Stairwell	W1	Plaster	White	Cracking	20	8.64	Positive
1	3	S04-3	West Stairwell	W2	Plaster	White	Efflorescence	30	9.43	Positive
1	3	S04-3	West Stairwell	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S04-3	West Stairwell	W4	Plaster	White	Flaking	25	8.95	Positive
1	3	S04-3	West Stairwell	Ceiling	Plaster	White	Efflorescence	80	7.65	Positive
1	3	S04-3	West Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S04-3	West Stairwell	Pipe Cover	Metal	Grey	Flaking	20	0.08	Negative
1	3	S04-3	West Stairwell	Window Frame	Metal	Grey	Flaking	21	0.11	Negative
1	3	S04A-3	West Fire Tower	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	Ceiling	Plaster	White	Efflorescence	75	4.89	Positive
1	3	S04A-3	West Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	Handrail	Metal	Grey	Chipping	25	0.12	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	3	S04A-3	West Fire Tower	Window Rails	Metal	Grey	Chipping	10	0.09	Negative
1	3	S04A-3	West Fire Tower	Window Bars	Metal	Grey	Chipping	45	No Access	Assumed
1	4	400	4th Floor Large Storage Room	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	400	4th Floor Large Storage Room	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	400	4th Floor Large Storage Room	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	400	4th Floor Large Storage Room	W4	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	400	4th Floor Large Storage Room	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	400	4th Floor Large Storage Room	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	W4	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	401	4th Floor Small Storage Room	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	403	Exhaust Fan Room	W1	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	403	Exhaust Fan Room	W2	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	403	Exhaust Fan Room	W3	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	403	Exhaust Fan Room	W4	Concrete	No Access	No Access	No Access	No Access	No Access

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	403	Exhaust Fan Room	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	403	Exhaust Fan Room	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	W1	Brick	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	W2	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	W3	Brick	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	W4	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	AT-G	Attic above Gymnasium	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	W4	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	H41	Hallway near Stairwell 1	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	H42	Main Hallway	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H42	Main Hallway	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H42	Main Hallway	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H42	Main Hallway	W4	Plaster	No Access	No Access	No Access	No Access	No Access

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	H42	Main Hallway	Ceiling	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	H42	Main Hallway	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	H43	Hallway to Left of Elevator	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S01-4	Stairwell behind Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S02-4	Stairwell across from Elevator	W1	Plaster/Brick	No Access	No Access	No Access	No Access	No Access
1	4	S02-4	Stairwell across from Elevator	W2	Plaster/Brick	No Access	No Access	No Access	No Access	No Access
1	4	S02-4	Stairwell across from Elevator	W3	Plaster/Brick	No Access	No Access	No Access	No Access	No Access
1	4	S02-4	Stairwell across from Elevator	W4	Plaster/Brick	No Access	No Access	No Access	No Access	No Access

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	4	S02-4	Stairwell across from Elevator	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S02-4	Stairwell across from Elevator	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	W1	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	W2	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	W3	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	W4	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	Ceiling	Plaster	No Access	No Access	No Access	No Access	No Access
1	4	S03-4	Stairwell 1	Floor	Concrete	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	4	S04A-4	East Fire Tower	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	500	Upper Mechanical Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	500	Upper Mechanical Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	500	Upper Mechanical Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	500	Upper Mechanical Room	W4	No Access	No Access	No Access	No Access	No Access	No Access

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	5	500	Upper Mechanical Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	500	Upper Mechanical Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	5	501	Elevator Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	A	AT-1	Main Attic - Section 1	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-1	Main Attic - Section 1	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-1	Main Attic - Section 1	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-1	Main Attic - Section 1	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-1	Main Attic - Section 1	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-1	Main Attic - Section 1	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-2	Main Attic - Section 2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-3	Main Attic - Section 3	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-3	Main Attic - Section 3	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-3	Main Attic - Section 3	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-3	Main Attic - Section 3	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-3	Main Attic - Section 3	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	A	AT-3	Main Attic - Section 3	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-4	Main Attic - Section 4	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-5	Main Attic - Section 5	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-6	Main Attic - Section 6	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-7	Main Attic - Old Tank Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	A	AT-CPS	Main Attic - Central Pipe Shaft Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001A	Boiler Room	W1	Concrete	White	Chipping	400	1.6	Positive
1	B	001A	Boiler Room	w1	Brick	White	Chipping	200	0.04	Negative
1	B	001A	Boiler Room	W2	Concrete	White	Alligating	500	5.52	Positive
1	B	001A	Boiler Room	w2	Brick	White	Alligating	200	0.02	Negative
1	B	001A	Boiler Room	W3	Concrete	White	Chipping	150	0.19	Negative
1	B	001A	Boiler Room	W4	Concrete	White	Moisture Damage	50	4.95	Positive
1	B	001A	Boiler Room	W4	Brick	White	Moisture Damage	100	3.18	Positive
1	B	001A	Boiler Room	Column	Concrete	White	Chipping	100	8.34	Positive
1	B	001A	Boiler Room	Door	Metal	White	Chipping	50	5.88	Positive
1	B	001A	Boiler Room	Stair Tread	Metal	Grey	Flaking	200	3.83	Positive
1	B	001A	Boiler Room	Handrail	Metal	Grey	Chipping	80	0.25	Negative
1	B	001A	Boiler Room	Ductwork, Exterior	Metal	White	Flaking	200	2.7	Positive
1	B	001A	Boiler Room	Ceiling	Concrete	White	Chipping	800	No Access	Assumed
1	B	001A	Boiler Room	Floor	Concrete	Grey	Chipping	50	0.23	Negative
1	B	001B	Loading Dock	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001B	Loading Dock	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001B	Loading Dock	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001B	Loading Dock	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001B	Loading Dock	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001C	New Electrical Room	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001C	New Electrical Room	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001C	New Electrical Room	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001C	New Electrical Room	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	001C	New Electrical Room	Ceiling	Concrete	White	Flaking	500	No Access	Assumed
1	B	001C	New Electrical Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W1	Concrete	Grey	Chipping	100	10	Positive
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W1	Brick	White	Chipping	400	0.03	Negative
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W2	Concrete	Grey	Chipping	200	10	Positive
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W2	Brick	White	Chipping	600	0.12	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W3	Concrete	Grey	Chipping	150	10	Positive
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W3	Brick	White	Chipping	400	0.05	Negative
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W4	Concrete	Grey	Chipping	500	10	Positive
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	W4	Brick	White	Chipping	300	0.04	Negative
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	Pipe	Metal	Grey	Chipping	20	0.04	Negative
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	Ceiling	Concrete	White	Flaking	200	No Access	Assumed
1	B	001D	Boiler Room Storage Room adjacent to Loading Dock	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001E	Boiler Room Shower	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	001E	Boiler Room Shower	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001E	Boiler Room Shower	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001E	Boiler Room Shower	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001E	Boiler Room Shower	Ceiling	Concrete	White	Chipping	20	4.8	Positive
1	B	001E	Boiler Room Shower	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001F	Boiler Room Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001F	Boiler Room Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001F	Boiler Room Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001F	Boiler Room Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001F	Boiler Room Restroom	Ceiling	Plaster	White	Chipping	20	3.1	Positive
1	B	001F	Boiler Room Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	001G	Fan Room adjacent to Cafeteria	W1	Brick	White	Flaking	50	0.01	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W1	Brick	Grey	Flaking	50	0.02	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W1	Concrete	Grey	Flaking	20	3.45	Positive
1	B	001G	Fan Room adjacent to Cafeteria	W2	Brick	White	Moisture Damage	50	0.05	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W2	Brick	Grey	Flaking	60	0.02	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W2	Concrete	Grey	Flaking	15	3.55	Positive
1	B	001G	Fan Room adjacent to Cafeteria	W3	Brick	White	Flaking	10	0.07	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W3	Brick	Grey	Flaking	15	0	Negative
1	B	001G	Fan Room adjacent to Cafeteria	W3	Concrete	Grey	Flaking	30	4.21	Positive
1	B	001G	Fan Room adjacent to Cafeteria	W4	Metal	Grey	Flaking	50	0.03	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	001G	Fan Room adjacent to Cafeteria	Handrail	Metal	Grey	Chipping	15	2.12	Positive
1	B	001G	Fan Room adjacent to Cafeteria	Ductwork, Exterior	Metal	Grey	Flaking	60	10	Positive
1	B	001G	Fan Room adjacent to Cafeteria	Ceiling	Concrete	White	Chipping	40	2.2	Positive
1	B	001G	Fan Room adjacent to Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	002A	Classroom 2 Closet	W1	Plaster	White	None	0	6.7	Positive
1	B	002A	Classroom 2 Closet	W2	Sheetrock	White	None	0	0	Negative
1	B	002A	Classroom 2 Closet	W3	Plaster	White	None	0	5.5	Positive
1	B	002A	Classroom 2 Closet	W4	Sheetrock	White	None	0	0	Negative
1	B	002A	Classroom 2 Closet	Ceiling	Sheetrock	White	None	0	0	Negative
1	B	002A	Classroom 2 Closet	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	002B	Classroom 2 Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	002B	Classroom 2 Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	002B	Classroom 2 Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	002B	Classroom 2 Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	002B	Classroom 2 Restroom	Ceiling	Plaster	White	None	0	6.48	Positive
1	B	002B	Classroom 2 Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	003A	Parent Resource Room 3 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003A	Parent Resource Room 3 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003A	Parent Resource Room 3 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003A	Parent Resource Room 3 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003A	Parent Resource Room 3 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003A	Parent Resource Room 3 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	003B	Parent Resource Room 3 Pipe Chase	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Parent Resource Room 3 Pipe Chase	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Parent Resource Room 3 Pipe Chase	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Parent Resource Room 3 Pipe Chase	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Parent Resource Room 3 Pipe Chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	003B	Parent Resource Room 3 Pipe Chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	004A	Office 4 Pipe Chase	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	004A	Office 4 Pipe Chase	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	004A	Office 4 Pipe Chase	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	004A	Office 4 Pipe Chase	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	004A	Office 4 Pipe Chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	004A	Office 4 Pipe Chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	005D	Scholarship Office	W1	Concrete	White	Chipping	5	0.1	Negative
1	B	005D	Scholarship Office	W2	Concrete	White	Chipping	12	0.1	Negative
1	B	005D	Scholarship Office	W3	Concrete	White	Chipping	15	0.2	Negative
1	B	005D	Scholarship Office	W4	Concrete	White	Chipping	10	0.1	Negative
1	B	005D	Scholarship Office	Ceiling	Metal	White	Chipping	5	1.3	Positive
1	B	005D	Scholarship Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	006A	Kitchen Loading Dock	Handrail	Metal	Red	Friction	15	2.25	Positive
1	B	006A	Kitchen Loading Dock	Stair Tread	Metal	Red	Friction	40	1.08	Positive
1	B	006A	Kitchen Loading Dock	Stringer	Metal	Red	Chipping	10	1.91	Positive
1	B	006A	Kitchen Loading Dock	W1	Brick	White	None	0	1.1	Positive
1	B	006A	Kitchen Loading Dock	W2	Brick	White	None	0	0.8	Positive
1	B	006A	Kitchen Loading Dock	W3	Brick	White	None	0	0.9	Positive
1	B	006A	Kitchen Loading Dock	W4	Brick	White	None	0	1.88	Positive
1	B	006A	Kitchen Loading Dock	Ceiling	Concrete	White	None	0	0.01	Negative
1	B	006A	Kitchen Loading Dock	Floor	Concrete	Red	Chipping	50	0.02	Negative
1	B	006B	School Police Mini Office Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	006B	School Police Mini Office Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	006B	School Police Mini Office Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	006B	School Police Mini Office Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	006B	School Police Mini Office Restroom	Ceiling	Concrete	White	Flaking	20	0.09	Negative
1	B	006B	School Police Mini Office Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007A	Boy's Restroom across from Classroom 5	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007A	Boy's Restroom across from Classroom 5	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007A	Boy's Restroom across from Classroom 5	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	007A	Boy's Restroom across from Classroom 5	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007A	Boy's Restroom across from Classroom 5	Ceiling	Plaster	White	None	0	4.67	Positive
1	B	007A	Boy's Restroom across from Classroom 5	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	Ceiling	Concrete	White	None	0	5.69	Positive
1	B	007B	Girl's Restroom across from Classroom 5	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	007B	Girl's Restroom across from Classroom 5	Trench Cover	Metal	Brown	Friction	20	0.41	Negative
1	B	007B	Girl's Restroom across from Classroom 5	Window Frame	Wood	Brown	None	0	0.06	Negative
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	007C	Pipe Chase between Boy's and Girl's Restrooms across from Classroom 5	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	008A	Kitchen Storage	W1	Brick	White	None	0	0.1	Negative
1	B	008A	Kitchen Storage	W2	Brick	White	None	0	0	Negative
1	B	008A	Kitchen Storage	W3	Brick	White	None	0	0	Negative
1	B	008A	Kitchen Storage	W4	Brick	White	None	0	0	Negative
1	B	008A	Kitchen Storage	Ceiling	Concrete	White	Flaking	10	0	Negative
1	B	008A	Kitchen Storage	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	009B	009B Front Storage Room	W1	Sheetrock	White	None	0	0	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	009B	009B Front Storage Room	W2	Plaster	White	None	0	4.55	Positive
1	B	009B	009B Front Storage Room	W3	Sheetrock	White	None	0	0	Negative
1	B	009B	009B Front Storage Room	W4	Plaster	White	None	0	6.24	Positive
1	B	009B	009B Front Storage Room	Ceiling	Plaster	White	Flaking	60	9.68	Positive
1	B	009B	009B Front Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009C	Foyer to the 009 Suite of Rooms	W1	Plaster	White	Cracking	40	6.85	Positive
1	B	009C	Foyer to the 009 Suite of Rooms	W2	CMU	White	None	0	0	Negative
1	B	009C	Foyer to the 009 Suite of Rooms	W3	Sheetrock	White	None	0	0	Negative
1	B	009C	Foyer to the 009 Suite of Rooms	W4	Sheetrock	White	None	0	0	Negative
1	B	009C	Foyer to the 009 Suite of Rooms	Trim	Concrete	Grey	Chipping	15	1.09	Positive
1	B	009C	Foyer to the 009 Suite of Rooms	Ceiling	Plaster	White	Flaking	30	3.89	Positive
1	B	009C	Foyer to the 009 Suite of Rooms	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009C	Foyer to the 009 Suite of Rooms	Door Frame	Metal	Black	None	0	1.03	Positive
1	B	009D	009 Suite Former Teacher's Lounge	W1	Sheetrock	White	None	0	0	Negative
1	B	009D	009 Suite Former Teacher's Lounge	W2	Sheetrock	White	None	0	0	Negative
1	B	009D	009 Suite Former Teacher's Lounge	W3	Plaster	White	Cracking	60	7.16	Positive
1	B	009D	009 Suite Former Teacher's Lounge	Trench Cover	Metal	Black	Friction	30	1.16	Positive
1	B	009D	009 Suite Former Teacher's Lounge	W4	CMU	White	None	0	0	Negative
1	B	009D	009 Suite Former Teacher's Lounge	Ceiling	Plaster	White	Flaking	75	4.58	Positive
1	B	009D	009 Suite Former Teacher's Lounge	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009E	009B Rear Storage Room	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009E	009B Rear Storage Room	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009E	009B Rear Storage Room	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	009E	009B Rear Storage Room	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	009E	009B Rear Storage Room	Ceiling	Plaster	White	Flaking	40	6.54	Positive
1	B	009E	009B Rear Storage Room	Ductwork, Exterior	Metal	White	Chipping	40	3.32	Positive
1	B	009E	009B Rear Storage Room	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	010A	Building Engineer's Small Rear Storage Room	Ceiling	Concrete	White	Flaking	30	0.05	Negative
1	B	010A	Building Engineer's Small Rear Storage Room	W1	CMU	Yellow	None	0	0	Negative
1	B	010A	Building Engineer's Small Rear Storage Room	W2	Sheetrock	Yellow	None	0	0	Negative
1	B	010A	Building Engineer's Small Rear Storage Room	W3	Plaster	Yellow	Chipping	5	0.16	Negative
1	B	010A	Building Engineer's Small Rear Storage Room	W4	Plaster	Yellow	None	0	0	Negative
1	B	010A	Building Engineer's Small Rear Storage Room	Ceiling	Plaster	White	None	0	1.05	Positive
1	B	010A	Building Engineer's Small Rear Storage Room	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	010A	Building Engineer's Small Rear Storage Room	Door Frame	Metal	Grey	None	0	0.05	Negative
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	010B	Mechanical Room behind Building Engineer's Small Rear Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	012A	Girl's Restroom across the Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012A	Girl's Restroom across the Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012A	Girl's Restroom across the Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012A	Girl's Restroom across the Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012A	Girl's Restroom across the Elevator	Ceiling	Plaster	White	None	0	5.17	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	012A	Girl's Restroom across the Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	Ceiling	Concrete	White	None	0	0.03	Negative
1	B	012B	Boy's Restroom across the Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	Ceiling	Plaster	White	None	0	6.34	Positive
1	B	012B	Boy's Restroom across the Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	012B	Boy's Restroom across the Elevator	Window Frame	Wood	White	Chipping	5	5.6	Positive
1	B	013A	Staff Restroom across from Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	013A	Staff Restroom across from Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	013A	Staff Restroom across from Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	013A	Staff Restroom across from Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	013A	Staff Restroom across from Elevator	Ceiling	Plaster	White	None	0	8.34	Positive
1	B	013A	Staff Restroom across from Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	W1	CMU	White	None	0	0.01	Negative
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	W2	Plaster	White	Moisture Damage	80	9.68	Positive
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	W3	Plaster	White	Flaking	60	5.34	Positive
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	W4	Plaster	White	Moisture Damage	80	7.26	Positive
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	Ceiling	Plaster	White	Chipping	30	8.21	Positive
1	B	013B	Water Meter Room behind the Staff Restrooms across the Elevator	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	014A	Stage	W1	Plaster	Black	Chipping	20	6.11	Positive
1	B	014A	Stage	W2	Plaster	Black	Chipping	40	2.76	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	014A	Stage	W3	Plaster	Black	Chipping	100	2.51	Positive
1	B	014A	Stage	W4	Plaster	Black	Chipping	40	3.99	Positive
1	B	014A	Stage	Ceiling	Plaster	Black	None	0	6.32	Positive
1	B	014A	Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	014A	Stage	Door	Wood	Brown	Chipping	20	0	Negative
1	B	014A	Stage	Door Frame	Metal	Brown	Chipping	20	0	Negative
1	B	016A	Kitchen Freezer area	W1	Brick	White	Cracking	5	0.2	Negative
1	B	016A	Kitchen Freezer area	W2	Brick	White	Chipping	10	0.11	Negative
1	B	016A	Kitchen Freezer area	W3	Brick	White	Cracking	15	0.14	Negative
1	B	016A	Kitchen Freezer area	W4	Brick	White	Cracking	10	0.16	Negative
1	B	016A	Kitchen Freezer area	Ceiling	Concrete	White	None	0	0.05	Negative
1	B	016A	Kitchen Freezer area	Floor	Concrete	Green	Chipping	15	0	Negative
1	B	016A	Kitchen Freezer area	Trim	Concrete	Red	Chipping	70	0.02	Negative
1	B	020A	Foyer to Left of Stage Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	020A	Foyer to Left of Stage Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	020A	Foyer to Left of Stage Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	020A	Foyer to Left of Stage Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	020A	Foyer to Left of Stage Restroom	Ceiling	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	020A	Foyer to Left of Stage Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	023A	Paint Room in Hallway outside Cafeteria	W1	Plaster	White	Alligating	10	10	Positive
1	B	023A	Paint Room in Hallway outside Cafeteria	W2	Plaster	White	None	0	10	Positive
1	B	023A	Paint Room in Hallway outside Cafeteria	W3	Plaster	White	Cracking	5	10	Positive
1	B	023A	Paint Room in Hallway outside Cafeteria	W4	Plaster	White	Chipping	15	10	Positive
1	B	023A	Paint Room in Hallway outside Cafeteria	Ceiling	Concrete	White	Chipping	30	0.01	Negative
1	B	023A	Paint Room in Hallway outside Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	1	Classroom 1	Trim	Concrete	Grey	Chipping	15	0.03	Negative
1	B	1	Classroom 1	Ductwork, Exterior	Metal	White	Chipping	40	8.75	Positive
1	B	1	Classroom 1	Pipe	Metal	White	Chipping	25	0.02	Negative
1	B	1	Classroom 1	W1	Brick	White	Chipping	15	0.02	Negative
1	B	1	Classroom 1	W2	Brick	White	Chipping	20	0.02	Negative
1	B	1	Classroom 1	W3	Brick	White	Chipping	15	0.01	Negative
1	B	1	Classroom 1	W4	Brick	White	Chipping	20	0.05	Negative
1	B	1	Classroom 1	Ceiling	Concrete	White	Chipping	100	0.06	Negative
1	B	1	Classroom 1	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	1	Classroom 1	Cork Board Frame	Metal	White	Chipping	10	0	Negative
1	B	1	Classroom 1	Coat Rack	Wood	White	None	0	0	Negative
1	B	1	Classroom 1	Window Frame	Wood	White	None	0	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	W1	Sheetrock	Yellow	None	0	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	W2	Sheetrock	Yellow	None	0	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	W3	CMU	Yellow	Chipping	10	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	W4	Plaster	Yellow	None	0	0.13	Negative
1	B	10	Building Engineer's Large Front Storage Room	Ceiling	Concrete	White	None	0	0.05	Negative
1	B	10	Building Engineer's Large Front Storage Room	Floor	9x9 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	10	Building Engineer's Large Front Storage Room	Door	Metal	Brown	Chipping	1	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	Door Frame	Metal	Brown	None	0	0	Negative
1	B	10	Building Engineer's Large Front Storage Room	Trench Cover	Metal	Grey	None	0	1.26	Positive
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	pipe	Metal	Yellow	Chipping	5	0.01	Negative
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	W1	Plaster	White	Chipping	1	5	Positive
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	W2	Plaster	White	Flaking	10	3.35	Positive
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	W3	Plaster	White	Cracking	60	2.36	Positive
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	W4	Plaster	White	Cracking	80	2.49	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	Ceiling	Concrete	White	Flaking	80	4.89	Positive
1	B	11	Electrical Closet at the entrance to the Building Engineer's Office Area	Floor	Concrete	Grey	None	0	0.02	Negative
1	B	11B	Service Closet adjacent to Elevator	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	11B	Service Closet adjacent to Elevator	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	11B	Service Closet adjacent to Elevator	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	11B	Service Closet adjacent to Elevator	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	11B	Service Closet adjacent to Elevator	Ceiling	Plaster	White	None	0	5.38	Positive
1	B	11B	Service Closet adjacent to Elevator	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	12	Hallway outside Boy's and Girl's Restrooms	Ceiling	Plaster	White	None	0	8.46	Positive
1	B	12	Hallway outside Boy's and Girl's Restrooms	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	12	Hallway outside Boy's and Girl's Restrooms	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	12	Hallway outside Boy's and Girl's Restrooms	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	12	Hallway outside Boy's and Girl's Restrooms	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	12	Hallway outside Boy's and Girl's Restrooms	Ceiling	Plaster	White	Flaking	50	8.64	Positive
1	B	12	Hallway outside Boy's and Girl's Restrooms	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	W1	Plaster	White	Chipping	5	2.36	Positive
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	W2	Plaster	White	Flaking	45	3.34	Positive
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	W3	CMU	White	None	0	0.02	Negative
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	W4	Plaster	White	Cracking	20	7.46	Positive
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	Ceiling	Plaster	White	Flaking	50	8.53	Positive
1	B	13	Staff Lounge outside Staff Restroom across from Elevator	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	14	Auditorium	W1	Wood	Black	Friction	80	0.06	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	14	Auditorium	W1	Plaster	White	Chipping	40	6.04	Positive
1	B	14	Auditorium	W2	Wood	Black	Friction	50	0.45	Negative
1	B	14	Auditorium	W2	Plaster	White	Chipping	20	2.48	Positive
1	B	14	Auditorium	W3	Wood	Black	Chipping	50	0.31	Negative
1	B	14	Auditorium	W3	Plaster	White	Cracking	100	4.35	Positive
1	B	14	Auditorium	W4	Wood	Black	Chipping	40	0.11	Negative
1	B	14	Auditorium	W4	Plaster	White	Cracking	10	9.33	Positive
1	B	14	Auditorium	Ceiling	Plaster	White	Flaking	200	No Access	Assumed
1	B	14	Auditorium	Column	Wood	Black	None	0	0.3	Negative
1	B	14	Auditorium	Column	Plaster	White	Chipping	10	7.42	Positive
1	B	14	Auditorium	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B	14	Auditorium	Door Frame	Wood	Black	Chipping	20	0.08	Negative
1	B	14	Auditorium	Door	Wood	Black	Friction	10	0.09	Negative
1	B	14	Auditorium	Window Frame	Wood	Black	None	0	0.08	Negative
1	B	14	Auditorium	Door	Metal	Grey	Chipping	20	0	Negative
1	B	14	Auditorium	Door Frame	Metal	Grey	Chipping	10	0	Negative
1	B	15	Main Entrance Hallway	W1	Plaster	White	None	0	7.42	Positive
1	B	15	Main Entrance Hallway	W2	Plaster	White	Flaking	5	7.32	Positive
1	B	15	Main Entrance Hallway	W3	Plaster	White	None	0	7.42	Positive
1	B	15	Main Entrance Hallway	W4	Plaster	White	None	0	7.05	Positive
1	B	15	Main Entrance Hallway	Handrail	Metal	Grey	Chipping	5	3.24	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	15	Main Entrance Hallway	Ceiling	Plaster	White	None	0	5.46	Positive
1	B	15	Main Entrance Hallway	Trim	Concrete	Grey	None	0	0.45	Negative
1	B	15	Main Entrance Hallway	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	16	Kitchen	W1	Brick	White	None	0	1.28	Positive
1	B	16	Kitchen	W2	Brick	White	None	0	1.81	Positive
1	B	16	Kitchen	W3	Brick	White	None	0	1.47	Positive
1	B	16	Kitchen	W4	Brick	White	None	0	1.36	Positive
1	B	16	Kitchen	Ceiling	Concrete	White	None	0	9.1	Positive
1	B	16	Kitchen	Floor	Concrete	Green	None	0	0	Negative
1	B	16	Kitchen	Trench Cover	Metal	Red	Friction	15	0.18	Negative
1	B	16	Kitchen	Radiator	Metal	Grey	Chipping	40	0.37	Negative
1	B	16	Kitchen	Trim	Concrete	Red	Chipping	200	0	Negative
1	B	16	Kitchen	Door	Wood	Brown	Friction	10	0.45	Negative
1	B	16	Kitchen	Door Frame	Wood	Brown	Chipping	10	0.04	Negative
1	B	19	Main Entrance Vestibule	W1	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	19	Main Entrance Vestibule	W2	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	19	Main Entrance Vestibule	W3	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	19	Main Entrance Vestibule	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	19	Main Entrance Vestibule	Ceiling	Plaster	White	None	0	2.5	Positive
1	B	19	Main Entrance Vestibule	Floor	Terrazzo	Unpainted	N/A	N/A	N/A	N/A
1	B	2	Classroom 2	W1	Ceramic Tile	Unpainted	Chipping	5	2.73	Positive
1	B	2	Classroom 2	W1	Plaster	White	Chipping	4	4.54	Positive
1	B	2	Classroom 2	W2	Ceramic Tile	Unpainted	Chipping	5	2.2	Positive
1	B	2	Classroom 2	W2	Plaster	White	Chipping	5	7.19	Positive
1	B	2	Classroom 2	W3	Ceramic Tile	Unpainted	Cracking	5	2.57	Positive
1	B	2	Classroom 2	W3	Plaster	White	None	0	6.22	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	2	Classroom 2	W4	Ceramic Tile	Unpainted	Chipping	10	2.93	Positive
1	B	2	Classroom 2	W4	Plaster	White	Chipping	1	7.1	Positive
1	B	2	Classroom 2	Ceiling	Plaster	White	Flaking	200	9.63	Positive
1	B	2	Classroom 2	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	2	Classroom 2	Door	Metal	Brown	Chipping	2	0	Negative
1	B	2	Classroom 2	Door Frame	Metal	Brown	Chipping	1	0	Negative
1	B	2	Classroom 2	Pipe	Metal	White	Chipping	15	6.16	Positive
1	B	2	Classroom 2	Radiator	Metal	Grey	Chipping	15	2.97	Positive
1	B	2	Classroom 2	Radiator Cover	Metal	Grey	Chipping	15	0	Negative
1	B	2	Classroom 2	Pipe Cover	Metal	Brown	None	0	0.05	Negative
1	B	20	Foyer to Left of Stage	W1	Plaster	White	Flaking	30	5.23	Positive
1	B	20	Foyer to Left of Stage	W2	Plaster	White	Cracking	10	7.55	Positive
1	B	20	Foyer to Left of Stage	W3	Sheetrock	White	None	0	0	Negative
1	B	20	Foyer to Left of Stage	W4	Plaster	White	Chipping	10	7.35	Positive
1	B	20	Foyer to Left of Stage	Ceiling	Plaster	White	Alligating	30	5.34	Positive
1	B	20	Foyer to Left of Stage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	20	Foyer to Left of Stage	Radiator	Metal	Grey	Flaking	5	2.2	Positive
1	B	20	Foyer to Left of Stage	Pipe Cover	Metal	White	Friction	10	0.01	Negative
1	B	21	Hallway to Building Engineer's Office	W1	Plaster	White	Flaking	10	1.25	Positive
1	B	21	Hallway to Building Engineer's Office	W2	Plaster	White	Flaking	5	1.66	Positive
1	B	21	Hallway to Building Engineer's Office	W3	CMU	White	None	0	0.07	Negative
1	B	21	Hallway to Building Engineer's Office	W4	Plaster	White	None	0	2.7	Positive
1	B	21	Hallway to Building Engineer's Office	Ceiling	Plaster	White	None	0	6.38	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	21	Hallway to Building Engineer's Office	Trim	Concrete	White	None	0	0.54	Negative
1	B	21	Hallway to Building Engineer's Office	pipe	Metal	White	Chipping	20	4.3	Positive
1	B	21	Hallway to Building Engineer's Office	Floor	9x9 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	22	Time Clock Room outside Building Engineer's Office	W1	CMU	White	None	0	0.65	Negative
1	B	22	Time Clock Room outside Building Engineer's Office	W2	Plaster	White	Chipping	5	1.65	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	W3	Plaster	White	Flaking	5	1.15	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	W4	Plaster	White	Flaking	3	1.95	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	Ceiling	Concrete	White	Flaking	20	2.2	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	Trench Cover	Metal	Grey	None	0	0.8	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	Door Frame	Metal	Grey	None	0	4.43	Positive
1	B	22	Time Clock Room outside Building Engineer's Office	Door	Metal	Grey	None	0	0	Negative
1	B	22	Time Clock Room outside Building Engineer's Office	Trim	Concrete	Grey	None	0	0.25	Negative
1	B	22	Time Clock Room outside Building Engineer's Office	Floor	9x9 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	23	Building Engineer's Office	W1	Plaster	White	None	0	6.85	Positive
1	B	23	Building Engineer's Office	W2	Plaster	White	None	0	2.34	Positive
1	B	23	Building Engineer's Office	W3	Plaster	White	None	0	8.65	Positive
1	B	23	Building Engineer's Office	W4	Plaster	White	None	0	8.13	Positive
1	B	23	Building Engineer's Office	Ceiling	Plaster	White	Flaking	50	8.46	Positive
1	B	23	Building Engineer's Office	Floor	9x9 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	23	Building Engineer's Office	Trim	Concrete	Grey	None	0	2.23	Positive
1	B	23	Building Engineer's Office	Trench Cover	Metal	Grey	None	0	1.65	Positive
1	B	3	Parent Resource Room 3	W1	Ceramic Tile	Unpainted	Chipping	10	2.9	Positive
1	B	3	Parent Resource Room 3	W1	Plaster	Orange	Chipping	6	5.83	Positive
1	B	3	Parent Resource Room 3	W2	Ceramic Tile	Unpainted	None	0	3.09	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	3	Parent Resource Room 3	W2	Plaster	Orange	Chipping	10	7.07	Positive
1	B	3	Parent Resource Room 3	W3	Ceramic Tile	Unpainted	Chipping	10	3.12	Positive
1	B	3	Parent Resource Room 3	W3	Plaster	Orange	Chipping	3	7.4	Positive
1	B	3	Parent Resource Room 3	W4	Ceramic Tile	Unpainted	Chipping	15	2.84	Positive
1	B	3	Parent Resource Room 3	W4	Plaster	Orange	Chipping	5	8.7	Positive
1	B	3	Parent Resource Room 3	Ceiling	Plaster	White	Flaking	200	8.35	Positive
1	B	3	Parent Resource Room 3	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	3	Parent Resource Room 3	Radiator	Metal	Grey	Chipping	25	0.08	Negative
1	B	3	Parent Resource Room 3	Radiator Cover	Metal	Grey	None	0	0	Negative
1	B	3	Parent Resource Room 3	Pipe Cover	Metal	Brown	None	0	0.09	Negative
1	B	3	Parent Resource Room 3	Blackboard Frame	Wood	Brown	None	0	0.11	Negative
1	B	3	Parent Resource Room 3	Door	Metal	Black	None	0	0	Negative
1	B	3	Parent Resource Room 3	Door Frame	Metal	Brown	None	0	0	Negative
1	B	30	Student Store under the stairs in front of the Auditorium	W1	Sheetrock	White	None	0	0	Negative
1	B	30	Student Store under the stairs in front of the Auditorium	W2	Sheetrock	White	None	0	0	Negative
1	B	30	Student Store under the stairs in front of the Auditorium	W3	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	30	Student Store under the stairs in front of the Auditorium	W4	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	30	Student Store under the stairs in front of the Auditorium	Ceiling	Sheetrock	White	None	0	0	Negative
1	B	30	Student Store under the stairs in front of the Auditorium	Floor	Marble	Unpainted	N/A	N/A	N/A	N/A
1	B	4	Classroom 004	W1	Plaster	White	Chipping	20	10	Positive
1	B	4	Classroom 004	W2	Plaster	White	Chipping	11	10	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	4	Classroom 004	W3	Plaster	White	Chipping	20	10	Positive
1	B	4	Classroom 004	W4	Plaster	White	Chipping	12	10	Positive
1	B	4	Classroom 004	Ceiling	Plaster	White	Flaking	100	9.35	Positive
1	B	4	Classroom 004	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	4	Classroom 004	Pipe	Metal	White	Chipping	10	0.08	Negative
1	B	4	Classroom 004	Baseboard	Wood	White	Chipping	25	0.16	Negative
1	B	4	Classroom 004	Radiator	Metal	Grey	Chipping	15	5.23	Positive
1	B	5	Classroom 5	W1	Plaster	White	Chipping	15	8.75	Positive
1	B	5	Classroom 5	W2	Plaster	White	None	0	9.54	Positive
1	B	5	Classroom 5	W3	Plaster	White	Chipping	3	9.25	Positive
1	B	5	Classroom 5	W4	Plaster	White	Chipping	3	7.76	Positive
1	B	5	Classroom 5	Ceiling	Plaster	White	Flaking	300	8.13	Positive
1	B	5	Classroom 5	Floor	9x9 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	5	Classroom 5	Radiator	Metal	Grey	Chipping	25	3.68	Positive
1	B	5	Classroom 5	Radiator Cover	Metal	Grey	Chipping	10	0	Negative
1	B	5	Classroom 5	Baseboard	Concrete	Grey	None	0	2.14	Positive
1	B	5	Classroom 5	Pipe Cover	Metal	White	None	0	0.15	Negative
1	B	5	Classroom 5	Pipe	Metal	Grey	Chipping	1	0.2	Negative
1	B	6	School Police Mini Office	Ceiling	Concrete	White	Flaking	15	0.01	Negative
1	B	6	School Police Mini Office	W1	Plaster	White	Chipping	15	4.35	Positive
1	B	6	School Police Mini Office	W2	Plaster	White	None	0	9.65	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	6	School Police Mini Office	W3	Plaster	White	None	0	9.13	Positive
1	B	6	School Police Mini Office	W4	Plaster	White	Cracking	20	8.34	Positive
1	B	6	School Police Mini Office	Ceiling	Concrete	White	Moisture Damage	15	0.02	Negative
1	B	6	School Police Mini Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	7	Kitchen Office	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Kitchen Office	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Kitchen Office	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Kitchen Office	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Kitchen Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B	7	Kitchen Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B	8	Cafeteria	W1	Brick	White	None	0	2.22	Positive
1	B	8	Cafeteria	W2	Brick	White	None	0	1.66	Positive
1	B	8	Cafeteria	W3	Brick	White	Chipping	1	3.39	Positive
1	B	8	Cafeteria	W4	Brick	White	None	0	2.24	Positive
1	B	8	Cafeteria	Ceiling	Concrete	White	None	0	2.04	Positive
1	B	8	Cafeteria	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	8	Cafeteria	Trim	Concrete	Grey	Chipping	10	0.48	Negative
1	B	8	Cafeteria	Radiator	Metal	Grey	Chipping	25	0.79	Positive
1	B	8	Cafeteria	Ductwork, Exterior	Metal	White	None	0	2.61	Positive
1	B	8	Cafeteria	Column	Brick	White	None	0	1.11	Positive
1	B	8	Cafeteria	Pipe	Metal	White	Chipping	20	0.43	Negative
1	B	8	Cafeteria	Trench Cover	Metal	Brown	Friction	40	0.16	Negative
1	B	9	Office 009A	W1	Sheetrock	White	None	0	0	Negative
1	B	9	Office 009A	W2	CMU	White	None	0	0.17	Negative
1	B	9	Office 009A	W3	Plaster	White	Cracking	27	10	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	9	Office 009A	W4	Sheetrock	White	None	0	0	Negative
1	B	9	Office 009A	Ceiling	Plaster	White	Flaking	50	5.36	Positive
1	B	9	Office 009A	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	9	Office 009A	Door Frame	Metal	Brown	None	0	0	Negative
1	B	9	Office 009A	Window Frame	Wood	Brown	None	0	3.76	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W1	Sheetrock	White	None	0	0	Negative
1	B	H01	Hallway outside Classroom 1 to Office 4	W1	Sheetrock	Black	None	0	0	Negative
1	B	H01	Hallway outside Classroom 1 to Office 4	W2	Plaster	White	None	0	3.2	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W2	Plaster	Black	None	0	7.56	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W3	Plaster	White	None	0	3.1	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W3	Plaster	Black	None	0	7.66	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W4	Plaster	White	None	0	3.12	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	W4	Plaster	Black	None	0	7.98	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	Ceiling	Concrete	White	None	0	5.32	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H01	Hallway outside Classroom 1 to Office 4	Pipe Cover	Metal	Grey	Chipping	5	0.01	Negative
1	B	H01	Hallway outside Classroom 1 to Office 4	Trench Cover	Metal	Grey	Friction	15	1.35	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	Trim	Concrete	Grey	Chipping	5	1.12	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	Door	Metal	Red	Chipping	2	0.01	Negative
1	B	H01	Hallway outside Classroom 1 to Office 4	Door Frame	Metal	Red	Chipping	5	0.06	Negative
1	B	H01	Hallway outside Classroom 1 to Office 4	Radiator	Metal	Grey	Chipping	15	2.2	Positive
1	B	H01	Hallway outside Classroom 1 to Office 4	Ductwork, Exterior	Metal	Black	None	0	0	Negative
1	B	H01A	Pipe Chase across from Parent Resource Room	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H01A	Pipe Chase across from Parent Resource Room	W2	Brick	Unpainted	N/A	N/A	N/A	N/A

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2] (sf)	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	H01A	Pipe Chase across from Parent Resource Room	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H01A	Pipe Chase across from Parent Resource Room	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H01A	Pipe Chase across from Parent Resource Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H01A	Pipe Chase across from Parent Resource Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H01B	Hallway behind Stage	W1	Plaster	White	None	0	9.38	Positive
1	B	H01B	Hallway behind Stage	W2	Plaster	White	None	0	8	Positive
1	B	H01B	Hallway behind Stage	W3	Plaster	White	None	0	5.36	Positive
1	B	H01B	Hallway behind Stage	W4	Plaster	White	None	0	9.13	Positive
1	B	H01B	Hallway behind Stage	Ceiling	Plaster	White	None	0	10	Positive
1	B	H01B	Hallway behind Stage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	H01B	Hallway behind Stage	Radiator	Metal	Grey	Chipping	10	1.21	Positive
1	B	H01B	Hallway behind Stage	Pipe Cover	Metal	White	Chipping	10	0.02	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	W1	Plaster	White	None	0	1.65	Positive
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	W2	Plaster	White	None	0	2.1	Positive
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	W3	Plaster	White	None	0	2.13	Positive
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	W4	Plaster	White	None	0	2.38	Positive
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Ceiling	Sheetrock	White	None	0	0	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Door	Metal	Red	None	0	0	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Door Frame	Metal	Red	Flaking	10	0	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Trench Cover	Metal	Grey	Friction	10	0.08	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Trim	Concrete	Grey	Chipping	5	0.49	Negative
1	B	H02	Hallway from the Cafeteria Entrance to Classroom 5	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H03	Hallway along Auditorium	W1	Plaster	White	None	0	7.92	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	H03	Hallway along Auditorium	W2	Brick	Blue	None	0	0	Negative
1	B	H03	Hallway along Auditorium	W2	Plaster	White	None	0	7.62	Positive
1	B	H03	Hallway along Auditorium	W3	Plaster	White	None	0	7.99	Positive
1	B	H03	Hallway along Auditorium	W4	Plaster	Blue	Flaking	5	7.93	Positive
1	B	H03	Hallway along Auditorium	Ceiling	Plaster	White	Flaking	600	4.36	Positive
1	B	H03	Hallway along Auditorium	Trim	Concrete	Grey	None	0	1.7	Positive
1	B	H03	Hallway along Auditorium	Door	Metal	Blue	None	0	0.07	Negative
1	B	H03	Hallway along Auditorium	Pipe Cover	Metal	Grey	None	0	0.07	Negative
1	B	H03	Hallway along Auditorium	Trench Cover	Metal	Grey	None	0	0.28	Negative
1	B	H03	Hallway along Auditorium	Door Frame	Metal	Blue	None	0	0.03	Negative
1	B	H03	Hallway along Auditorium	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H03A	Hallway outside Foyer to Left of Stage	Ceiling	Concrete	White	None	0	0.31	Negative
1	B	H03A	Hallway outside Foyer to Left of Stage	W1	Plaster	White	None	0	2.02	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	W2	Plaster	White	None	0	1.75	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	W3	Plaster	White	None	0	2.99	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	W4	Plaster	Red	None	0	2.34	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	W4	Brick	Red	None	0	0	Negative
1	B	H03A	Hallway outside Foyer to Left of Stage	Radiator	Metal	Grey	Chipping	10	0.84	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	Radiator Cover	Metal	Grey	Chipping	10	0.11	Negative
1	B	H03A	Hallway outside Foyer to Left of Stage	Ceiling	Plaster	White	None	0	2.15	Positive
1	B	H03A	Hallway outside Foyer to Left of Stage	Door	Metal	Blue	None	0	0.06	Negative
1	B	H03A	Hallway outside Foyer to Left of Stage	Door Frame	Metal	Blue	None	0	0	Negative
1	B	H03A	Hallway outside Foyer to Left of Stage	pipe	Metal	Grey	Chipping	10	0.02	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	H03A	Hallway outside Foyer to Left of Stage	Floor	Concrete	Grey	None	0	0.03	Negative
1	B	H03B	Pipe Chase adjacent to East Stairwell	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H03B	Pipe Chase adjacent to East Stairwell	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H03B	Pipe Chase adjacent to East Stairwell	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H03B	Pipe Chase adjacent to East Stairwell	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H03B	Pipe Chase adjacent to East Stairwell	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H03B	Pipe Chase adjacent to East Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	W1	Plaster	White	None	0	9.56	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	W2	Plaster	Blue	None	0	9.8	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	w2	Brick	Blue	None	0	0	Negative
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	W3	Plaster	White	None	0	9.47	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	W4	Plaster	Blue	None	0	10	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	W4	Brick	Blue	None	0	0	Negative
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Ceiling	Plaster	White	Flaking	450	2.21	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Floor	Concrete	Grey	None	0	0	Negative
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Trench Cover	Metal	Grey	None	0	0	Negative
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Door Frame	Metal	Blue	None	0	2.54	Positive
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Door	Metal	Blue	None	0	0	Negative
1	B	H04	Hallway from the Elevator to the Cafeteria Entrance	Trim	Concrete	Grey	None	0	0.41	Negative
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	W1	Plaster	White	None	0	6.36	Positive
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	W2	Plaster	White	None	0	5.98	Positive
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	W3	Plaster	White	None	0	5.78	Positive
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	W4	Plaster	White	None	0	5.96	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	Ceiling	Spline	Unpainted	N/A	N/A	N/A	N/A
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	Floor	Concrete	Grey	Chipping	2	0.08	Negative
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	Radiator	Metal	Grey	Chipping	15	1.58	Positive
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	Radiator Cover	Metal	Grey	Chipping	5	1.78	Positive
1	B	H05	Hallway from Classroom 2 to the Gas Shut Off Room	Pipe Cover	Metal	Grey	None	0	0.11	Negative
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	H05A	Hallway from Classroom 2 to the Gas Shut Off Room Pipe Chase	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	W1	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	W2	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	W3	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	W4	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	Ceiling	Concrete	White	Chipping	15	0.02	Negative
1	B	NP-3	Gas Shut Off Room / Male and Female Restroom	Floor	Ceramic Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	W1	Plaster	White	Chipping	5	7.03	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	W2	Plaster	White	Moisture Damage	5	7.56	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	W3	Plaster	White	None	0	6.56	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	W4	Plaster	White	Chipping	15	8.54	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Ceiling	Metal	White	Flaking	10	2.11	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Floor	Concrete	Grey	None	0	0.11	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Stringer	Metal	Grey	None	0	7.68	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Stair Riser	Concrete	Grey	None	0	2.11	Positive
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Trim	Concrete	Grey	None	0	0.01	Negative
1	B	S01-B	Stairwell across from the Boy's and Girl's Restrooms	Handrail	Metal	Red	Flaking	2	0	Negative
1	B	S02-B	Stairwell across from Elevator	W1	Plaster	White	Chipping	5	7.26	Positive
1	B	S02-B	Stairwell across from Elevator	W2	Plaster	White	Efflorescence	20	7.01	Positive
1	B	S02-B	Stairwell across from Elevator	W3	Plaster	White	Moisture Damage	5	7.56	Positive
1	B	S02-B	Stairwell across from Elevator	W4	Plaster	White	Moisture Damage	5	8.54	Positive
1	B	S02-B	Stairwell across from Elevator	Ceiling	Plaster	White	Flaking	15	5.36	Positive
1	B	S02-B	Stairwell across from Elevator	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	3	S04A-3	West Fire Tower	Spindle	Metal	Grey	None	0	6.26	Positive
1	3	S04A-3	West Fire Tower	Stringer	Metal	Grey	None	0	4.87	Positive
1	3	S04A-3	West Fire Tower	Newel Post	Metal	Grey	Friction	5	6.7	Positive
1	3	S04A-3	West Fire Tower	Stair Riser	Concrete	Grey	None	0	2.28	Positive
1	3	S04A-3	West Fire Tower	Handrail	Metal	Grey	Friction	5	0.11	Negative
1	3	S04A-3	West Fire Tower	Door	Metal	Blue	Friction	5	0.04	Negative
1	3	S04A-3	West Fire Tower	Door Frame	Metal	Blue	None	0	0.16	Negative
1	3	S04A-3	West Fire Tower	Trim	Concrete	Grey	None	0	2.11	Positive
1	B	S03-B	East Stairwell	W1	Plaster	White	Flaking	10	6.03	Positive
1	B	S03-B	East Stairwell	W2	Plaster	White	Moisture Damage	25	6	Positive
1	B	S03-B	East Stairwell	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S03-B	East Stairwell	W4	Plaster	White	Flaking	15	6.38	Positive
1	B	S03-B	East Stairwell	Ceiling	Plaster	White	Alligatoring	200	4.89	Positive
1	B	S03-B	East Stairwell	Floor	Concrete	Grey	Friction	5	0.05	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	S03-B	East Stairwell	Trim	Concrete	Grey	None	0	0.03	Negative
1	B	S03-B	East Stairwell	Stair Riser	Concrete	Grey	None	0	0.01	Negative
1	B	S03-B	East Stairwell	Handrail	Metal	Grey	Chipping	10	0.13	Negative
1	B	S04-B	West Stairs at the Gas Shut Off Room	W1	Plaster	White	Moisture Damage	50	2.68	Positive
1	B	S04-B	West Stairs at the Gas Shut Off Room	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S04-B	West Stairs at the Gas Shut Off Room	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S04-B	West Stairs at the Gas Shut Off Room	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B	S04-B	West Stairs at the Gas Shut Off Room	Ceiling	Plaster	White	Chipping	150	5.68	Positive
1	B	S04-B	West Stairs at the Gas Shut Off Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B	S04-B	West Stairs at the Gas Shut Off Room	Handrail	Metal	Grey	Chipping	10	0.08	Negative
1	B	S04-B	West Stairs at the Gas Shut Off Room	Stair Riser	Concrete	Grey	Flaking	15	0.21	Negative
1	B	S04-B	West Stairs at the Gas Shut Off Room	Window Frame	Wood	Grey	Chipping	10	0.11	Negative
1	B	S05-B	Stairwell adjacent to Classroom 5	W1	Plaster	White	None	0	6.02	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	W2	Plaster	White	Moisture Damage	5	6.05	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	W3	Plaster	White	Moisture Damage	10	6.54	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	W4	Plaster	White	Moisture Damage	10	3.56	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	Ceiling	Plaster	White	Flaking	15	5	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	Floor	Concrete	Grey	None	0	0.03	Negative
1	B	S05-B	Stairwell adjacent to Classroom 5	Stair Riser	Concrete	Grey	Flaking	2	7.12	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	Stringer	Metal	Grey	Chipping	2	4.87	Positive
1	B	S05-B	Stairwell adjacent to Classroom 5	Trim	Concrete	Grey	None	0	0.28	Negative
1	B	S06-B	Fire Exit by Classroom 2	W1	Plaster	White	Flaking	50	3.56	Positive
1	B	S06-B	Fire Exit by Classroom 2	W2	Plaster	White	Moisture Damage	50	4.56	Positive

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	S06-B	Fire Exit by Classroom 2	W3	Plaster	White	Cracking	10	5.42	Positive
1	B	S06-B	Fire Exit by Classroom 2	W4	Plaster	White	Flaking	20	3.28	Positive
1	B	S06-B	Fire Exit by Classroom 2	W4	Wood	Grey	None	0	0.03	Negative
1	B	S06-B	Fire Exit by Classroom 2	Ceiling	Plaster	White	None	0	3.68	Positive
1	B	S06-B	Fire Exit by Classroom 2	Floor	Concrete	Grey	None	0	0.03	Negative
1	B	S06-B	Fire Exit by Classroom 2	Stair Tread	Concrete	Grey	Chipping	1	0.1	Negative
1	B	S06-B	Fire Exit by Classroom 2	Stair Riser	Concrete	Grey	None	0	0.02	Negative
1	B	S06-B	Fire Exit by Classroom 2	Door	Metal	Red	Friction	15	0.01	Negative
1	B	S06-B	Fire Exit by Classroom 2	Door Frame	Metal	Red	Friction	5	0.05	Negative
1	B	S06-B	Fire Exit by Classroom 2	Handrail	Metal	Grey	Chipping	20	0.23	Negative
1	B	S06-B	Fire Exit by Classroom 2	Trim	Concrete	Grey	None	0	0.11	Negative
1	B	S07-B	Stairwell to Right of Stage	W1	Plaster	White	Flaking	10	7.68	Positive
1	B	S07-B	Stairwell to Right of Stage	W2	Plaster	White	Flaking	20	6.54	Positive
1	B	S07-B	Stairwell to Right of Stage	W3	Plaster	White	Moisture Damage	50	7.55	Positive
1	B	S07-B	Stairwell to Right of Stage	W4	Plaster	White	Moisture Damage	50	7.94	Positive
1	B	S07-B	Stairwell to Right of Stage	Ceiling	Metal	White	Chipping	10	8	Positive
1	B	S07-B	Stairwell to Right of Stage	Floor	12x12 Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B	S07-B	Stairwell to Right of Stage	Stringer	Metal	Grey	None	0	4.43	Positive
1	B	S07-B	Stairwell to Right of Stage	Spindle	Metal	Grey	Flaking	5	4.37	Positive
1	B	S07-B	Stairwell to Right of Stage	Newel Post	Metal	Grey	Friction	10	4.62	Positive
1	B	S07-B	Stairwell to Right of Stage	Stair Riser	Concrete	Grey	Friction	10	4.69	Positive
1	B	S07-B	Stairwell to Right of Stage	Radiator	Metal	Grey	Chipping	10	2.7	Positive
1	B	S07-B	Stairwell to Right of Stage	Radiator Cover	Metal	Grey	Chipping	10	2.97	Positive
1	B	S07-B	Stairwell to Right of Stage	Pipe Cover	Metal	White	Flaking	5	0.07	Negative
1	B	S07-B	Stairwell to Right of Stage	Trim	Concrete	Grey	Friction	10	3.83	Positive

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	B	S07-B	Stairwell to Right of Stage	Handrail	Wood	Grey	Friction	10	0.06	Negative
1	C	CS	Sub Basement Crawl Space	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	CS	Sub Basement Crawl Space	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	CS	Sub Basement Crawl Space	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	CS	Sub Basement Crawl Space	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	CS	Sub Basement Crawl Space	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	C	CS	Sub Basement Crawl Space	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	EXT	Exterior	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	L-Roof	Lower Roof	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	W2	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	W3	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	W4	Brick	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	EXT	U-Roof	Upper Roof	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	A	Sub Basement Room A	W1	Concrete	White	Flaking	50	0.1	Negative
1	SB	A	Sub Basement Room A	W2	Concrete	White	Flaking	60	0.1	Negative
1	SB	A	Sub Basement Room A	W3	Concrete	White	Flaking	40	0.2	Negative

Dates: 6/23/23 - 01/2024

Lead-Safe Certification Assessment Report

Inspector Name and Certificate Number:
Zak Khalil #007233

Kensington High School

Inspection Company: Viva EHS

2051 E Cumberland St, Philadelphia PA 19125

Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	SB	A	Sub Basement Room A	W4	Concrete	White	Flaking	55	0.1	Negative
1	SB	A	Sub Basement Room A	Ceiling	Concrete	White	Flaking	80	0.2	Negative
1	SB	A	Sub Basement Room A	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	B	Sub Basement Room B	W1	Concrete	White	Flaking	100	0.1	Negative
1	SB	B	Sub Basement Room B	W2	Concrete	White	Flaking	60	0.3	Negative
1	SB	B	Sub Basement Room B	W3	Concrete	White	Flaking	65	0.2	Negative
1	SB	B	Sub Basement Room B	W4	Concrete	White	Flaking	45	0.1	Negative
1	SB	B	Sub Basement Room B	Ceiling	Concrete	White	Flaking	52	0.1	Negative
1	SB	B	Sub Basement Room B	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-1	Sub Basement Plenum	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	C-2	Auditorium Sub Basement Plenum	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	D	Sub Basement Storage-Louver Room	W1	Concrete	White	Chipping	10	0.1	Negative
1	SB	D	Sub Basement Storage-Louver Room	W2	Concrete	White	Flaking	12	0.1	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	SB	D	Sub Basement Storage-Louver Room	Fan Unit	Metal	White	Flaking	20	1.9	Positive
1	SB	D	Sub Basement Storage-Louver Room	W3	Concrete	White	Chipping	16	0.2	Negative
1	SB	D	Sub Basement Storage-Louver Room	W4	Concrete	White	Chipping	20	0.1	Negative
1	SB	D	Sub Basement Storage-Louver Room	Ceiling	Concrete	White	Chipping	50	0.1	Negative
1	SB	D	Sub Basement Storage-Louver Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	E	Auditorium Fan Room	Fan Unit	Metal	White	Flaking	40	2.4	Positive
1	SB	E	Auditorium Fan Room	Ductwork	Metal	White	Flaking	30	3.9	Positive
1	SB	E	Auditorium Fan Room	W1	Concrete	White	Chipping	26	0.1	Negative
1	SB	E	Auditorium Fan Room	W2	Concrete	White	Chipping	16	0.1	Negative
1	SB	E	Auditorium Fan Room	W3	Concrete	White	Chipping	20	0.2	Negative
1	SB	E	Auditorium Fan Room	W4	Concrete	White	Chipping	26	0.3	Negative
1	SB	E	Auditorium Fan Room	Ceiling	Concrete	White	Flaking	30	0.1	Negative
1	SB	E	Auditorium Fan Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	SB	HSB1	Sub Basement Hallway	W1	Concrete	White	Chipping	15	0.1	Negative
1	SB	HSB1	Sub Basement Hallway	W2	Concrete	White	Cracking	26	0.2	Negative
1	SB	HSB1	Sub Basement Hallway	W3	Concrete	White	Chipping	48	0.3	Negative
1	SB	HSB1	Sub Basement Hallway	W4	Concrete	White	Flaking	23	0.1	Negative
1	SB	HSB1	Sub Basement Hallway	Ceiling	Concrete	White	Flaking	50	0.1	Negative

			Dates: 6/23/23 - 01/2024	Lead-Safe Certification Assessment Report						
			Inspector Name and Certificate Number: Zak Khalil #007233	Kensington High School						
			Inspection Company: Viva EHS	2051 E Cumberland St, Philadelphia PA 19125						
Element	Floor	Space #	On-Site Room Name	Component	Substrate Material [1]	Paint Color	Description of Damage	Damage Quantity (sf) [2]	XRF Reading (mg/cm2)	XRF (positive/negative) [3]
1	SB	HSB1	Sub Basement Hallway	Ductwork	Metal	White	Flaking	100	4.7	Positive
1	SB	HSB1	Sub Basement Hallway	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Radiator	Metal	Grey	Chipping	3	1.26	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Radiator Cover	Metal	Grey	Chipping	3	2.51	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Pipe Cover	Metal	White	Chipping	5	0.02	Negative
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Handrail	Metal	Brown	Chipping	3	0.09	Negative
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Newel Post	Metal	Blue	Chipping	10	4.84	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Spindle	Metal	Blue	None	0	6.29	Positive
1	1	S07-1	Foyer/Stairwell to Right of Stage Balcony Level	Stair Tread	Metal	Black	None	0	6.21	Positive

- [1] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.
- [2] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."
- [3] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.
- [4] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.
- [5] Debris associated with a positive material (lead and/or asbestos), notify OEP ASAP.
- [6] Unless the answer is N/A. There should be a number stated. 0 or more.
- [7] Report LBP debris ASAP
- [8] If applicable enter the quantity of damaged paint behind radiator on the line with the component that is in front of the damage (ex. wall or ceiling). If zero damage behind radiator enter zero and if no radiator present enter N/A.
- [9] If radiators need to be removed call and/or e
- [10] If asbestos abatement is needed a DDC should be created.