

Report: Lead-Based Paint Assessment

Site:

**Martin Luther King High School
6100 Stenton Avenue
Philadelphia, PA 19138
ULCS# 6060**

Prepared For:

**The School District of Philadelphia
Office of Capital Programs
440 North Broad Street, "Portal C" Third Floor
Philadelphia, PA 19130**

Prepared By:

**Erik Swanson
Viva Environmental, Health, & Safety, LLC.
368 Daly Street
Philadelphia, PA 19148**

Date(s) of Project:

October 9 – November 9, 2023

Date of Report:

December 8, 2023

Project Number:

230511

EP2024-0220-6060

TABLE OF CONTENTS

1.0 Executive Summary

2.0 Conclusions

3.0 Recommendations

Attachments

- ◆ XRF Results Spreadsheet
- ◆ Calibration Check Test Results
- ◆ Lead Safe Certification

1.0 EXECUTIVE SUMMARY

Viva Environmental, Health, & Safety, LLC. (Viva EHS), was requested to perform a Lead-Based Paint Assessment at Martin Luther King High School located at 6100 Stenton Avenue, Philadelphia, PA 19138. The purpose of the inspection was to explore the presence and condition of painted surfaces for lead-based paint within rooms the entire building

Erik Swanson, a PA-licensed Lead Risk Assessor with Viva EHS, performed the inspection from October 9th to November 9th, 2023. He was assisted on-site by Lead Technicians, Jared Whack and Stephen Langan, of Viva EHS.

Painted surfaces were analyzed for lead using an X-ray Fluorescence Spectrometer (XRF) manufactured by Thermo Scientific-NITON.

The U.S. Department of Housing and Urban Development (HUD) considers 1.0 milligrams of lead per square centimeter of painted surface, or greater, to be lead based paint ($\leq 1.0 \text{ mg/c m}^2$). However, the City of Philadelphia's Department of Public Health document entitled "Regulations Relating to Labeling, Application and Removal of Lead Paint", dated December 26, 1977, states that any paint lacquer or other applied liquid surface coating, and putty or caulking or other sealing compound with a lead content of **0.7 mg/cm² or greater, is considered "lead-based"**.

2.0 CONCLUSIONS

During the inspection, **no** lead-based paint was detected throughout the school (refer to Attachments). The inspector made recommendations based on many factors, i.e., condition, friction/non-friction surface, height at which lead-based paint is located, and other information that was obtained from the client. Listed on the attached sheets (Attachments) are location and components for the areas where painted surfaces were sampled. A summary of the locations/components that were tested for lead-based paint is included in the attached spreadsheet.

The Environmental Protection Agency's (EPA) Renovation, Repair, and Painting Program Final Rule (40 CFR Part 745) (RRP Rule) mandates that if lead-based paint is disturbed during renovation or painting activity then the work should be completed using lead-safe work practices as defined in the RRP Rule. In addition, the individual disturbing the lead-based paint has to be certified as well as the firm with whom he/she is employed.

3.0 RECOMMENDATIONS

Any painted surface that has **any** concentration of lead should not be sanded, demolished or disturbed without the proper engineering controls and work methods, as spelled out under the OSHA's 29 CFR Part 1926.62 Lead Exposure in Construction, Interim Rule. Improper disturbance of any paint with lead content can cause lead to become airborne. The emphasis on controlling lead dust derives from the conclusion that lead dust appears to be the primary route of exposure to lead, especially of low-level exposure.

The Environmental Protection Agency's (EPA) Renovation, Repair, and Painting Program Final Rule (40 CFR Part 745) (RRP Rule) mandates that if lead-based paint is disturbed during renovation

or painting activity then the work should be completed using lead-safe work practices as defined in the RRP Rule. In addition, the individual disturbing the lead-based paint has to be certified as well as the firm with whom he/she is employed.

It is therefore important that occupants of the building and any contractors be made aware of the presence of the lead-based paint and the potential health risks associated with the ingestion of lead-based paint or the associated dust that results from the damaging of the painted surfaces.

Occupants and/or contractors should also be made aware of the importance of not damaging the painted surfaces and creating loose and flaking paint or the creation of dust. If the painted surfaces are damaged this should be reported to the proper building representative/maintenance personnel to properly correct the problem to prevent an increased exposure potential.

A summary of the locations/components where XRF readings were collected is included in the attached spreadsheet.

Within the spreadsheet, walls are labeled as “1”, “2”, “3”, or “4”. The wall that you enter the room through is labeled as “1” Wall. The walls are then labeled in a clockwise fashion as “2” Wall, “3” Wall, and “4” Wall. For hallways, the front entrance-side of the building is considered the “1” Wall.

ATTACHMENTS

Lead-Safe Certification Assessment Report																											
Dates: 10/9/23-11/9/23 Inspector Name and Certificate Number: Erik Swanson #006917 Inspection Company: Viva EHS Martin Luther King High School 6100 Stenton Ave, Philadelphia PA 19138																											
ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occs/No [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes	
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Door Frame 1	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Door Frame 2	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Door Frame 3	Metal	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Door Frame 4	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Column 1	Concrete	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Column 2	Concrete	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Column 4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100	Senior High	Learning Center 100	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100A	Storage	Storage Closet 100A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	W1	CMU	Orange	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	W3	CMU	Orange	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100B	Administrative Office	Office 100B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100C	Administrative Office	Office 100C	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100D	Administrative Office	Office 100D	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100E	Administrative Office	Office 100E	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100F	Administrative Office	Office 100F	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100G	Administrative Office	Office 100G	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100H	Service Closets	Custodial Closet 100H	no	W1	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100H	Service Closets	Custodial Closet 100H	no	W2	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100H	Service Closets	Custodial Closet 100H	no	W3	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	100H	Service Closets	Custodial Closet 100H	no	W4	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1																								

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occs/(yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [3]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes
6060	1	B606001	1	102	Senior High	Classroom 102	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	102	Senior High	Classroom 102	yes	W3	CMU	White	Chipping	15	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	102	Senior High	Classroom 102	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	102	Senior High	Classroom 102	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	102	Senior High	Classroom 102	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	103	Administrative Office	Teacher's Office 103	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	104	Senior High	Classroom 104	yes	W1	CMU	White	Flaking	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	W2	CMU	White	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	W3	CMU	Red	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	104	Senior High	Classroom 104	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	105	Senior High	Classroom 105	yes	W1	CMU	Blue	Flaking	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	W2	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	105	Senior High	Classroom 105	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	106	Senior High	Classroom 106	yes	W1	CMU	White	Cracking	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	106	Senior High	Classroom 106	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	107	Senior High	Classroom 107	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	W3	CMU	White	Flaking	30	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	107	Senior High	Classroom 107	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	108	Senior High	Classroom 108	yes	W1	CMU	White	Cracking	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	W2	CMU	White	Flaking	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	108	Senior High	Classroom 108	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	Door Frame	Metal	Gray	Chipping	3	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	109	Senior High	Classroom 109	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	W2	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	109	Senior High	Classroom 109	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	110	Senior High	Classroom 110	yes	W1	CMU	Blue	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	W4	CMU	Blue	Flaking	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	110	Senior High	Classroom 110	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	111	Senior High	Classroom 111	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A						

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	Element	Bldg/Emt ID	Room #	Space #	Space Type	On-Site Room Name	Student/Teacher Occ./yes/no [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [3]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes
6060	1	B606001	1	117	Senior High	Classroom 117	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	117	Senior High	Classroom 117	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	117	Senior High	Classroom 117	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	117	Senior High	Classroom 117	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	117	Senior High	Classroom 117	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	117	Senior High	Classroom 117	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	117	Senior High	Classroom 117	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	118	Senior High	Classroom 118	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	118	Senior High	Classroom 118	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	118	Senior High	Classroom 118	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	118	Senior High	Classroom 118	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	118	Senior High	Classroom 118	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	118	Senior High	Classroom 118	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	118	Senior High	Classroom 118	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	119	Administrative Office	Teacher's Office 119	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	120	Senior High	Classroom 120	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	120	Senior High	Classroom 120	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	120	Senior High	Classroom 120	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	120	Senior High	Classroom 120	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	120	Senior High	Classroom 120	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	120	Senior High	Classroom 120	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	120	Senior High	Classroom 120	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	121	Senior High	Classroom 121	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	121	Senior High	Classroom 121	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	121	Senior High	Classroom 121	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	121	Senior High	Classroom 121	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	121	Senior High	Classroom 121	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	121	Senior High	Classroom 121	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	121	Senior High	Classroom 121	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	122	Senior High	Classroom 122	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	122	Senior High	Classroom 122	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	122	Senior High	Classroom 122	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	122	Senior High	Classroom 122	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	122	Senior High	Classroom 122	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	122	Senior High	Classroom 122	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	122	Senior High	Classroom 122	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	123	Senior High	Classroom 123	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	123	Senior High	Classroom 123	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	123	Senior High	Classroom 123	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	123	Senior High	Classroom 123	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	123	Senior High	Classroom 123	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	123	Senior High	Classroom 123	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	123	Senior High	Classroom 123	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	124	Senior High	Classroom 124	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	124	Senior High	Classroom 124	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	124	Senior High	Classroom 124	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	124	Senior High	Classroom 124	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	124	Senior High	Classroom 124	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	124	Senior High	Classroom 124	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	124	Senior High	Classroom 124	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	125	Senior High	Classroom 125	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	125	Senior High	Classroom 125	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	125	Senior High	Classroom 125	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	125	Senior High	Classroom 125	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	125	Senior High	Classroom 125	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	125	Senior High	Classroom 125	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	126	Senior High	Learning Center 126	yes	Door Frame 1	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	126	Senior High	Learning Center 126	yes	Door Frame 2	Metal	Gray	None	0	0	Negative												

Lead-Safe Certification Assessment Report																											
Dates: 10/9/23-11/9/23 Inspector Name and Certificate Number: Erik Swanson #006917 Inspection Company: Viva EHS Martin Luther King High School 6100 Stenton Ave, Philadelphia PA 19138																											
ULCS#	E l e m e n t	Bldg/Elt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occur (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity (SF) of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes	
6060	1	B606001	1	128	School Store	School Store 128	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	128	School Store	School Store 128	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	128	School Store	School Store 128	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	128	School Store	School Store 128	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	W1	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	W2	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	W3	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	W4	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129	General Office	Building Engineer's Office Suite 129	no	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129A	Restrooms, Staff - F	Women's Restroom 129A	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B	Restrooms, Staff - M	Men's Restroom 129B	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129B-PC	Pipe Chase	Pipe Chase In Men's Restroom 129B	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129C	Administrative Office	Office 129C	yes	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	129D	Administrative Office	Office 129D	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	130A	Storage	Storage Room 130A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	W4	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131	Vo-Tech Classroom	Manufacturing Technology Room 131	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131A	Storage	Clean Room 131A	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	131A	Storage	Clean Room 131A	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	131A	Storage	Clean Room 131A	yes	W2</																			

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occ./(yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139B	Kitchen Office	First Floor Kitchen Office	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139C	Kitchen and Dry Stor	First Floor Kitchen Dry Storage	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	139D	Custodial Receiving	Kitchen receiving/Custodial Room	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140	Teacher Lounge/Dini	Faculty Cafeteria 140	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	140A	Lockers - Male/Fema	Locker Room 140A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	141	Storage	Stock Room 141	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	171	Storage	Storage Room 171	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	172	Storage	Storage Room 172	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	173	Storage	Storage Room 173	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	174	Storage	Team Room 174	yes	Door Frame	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	174	Storage	Team Room 174	yes	Door Frame	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	1	174	Storage	Team Room 174	yes	Duct	Metal	White	Flaking	40	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	174	Storage	Team Room 174	yes	W1	CMU	Multi	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	174	Storage	Team Room 174	yes	W2	CMU	Multi	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	174	Storage	Team Room 174	yes	W3	CMU	Multi	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	1	174	Storage	Team Room 174	yes	W4	CMU	Multi	None	0	0	Negative	Negative	N/A	N/A	N/A								

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Ent ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occupancy (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/m2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes	
6060	1	B606001	1	179A	Student Restrooms	Girl's Locker Room Restroom	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	179A	Student Restrooms	Girl's Locker Room Restroom	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	179A	Student Restrooms	Girl's Locker Room Restroom	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	180	Storage	Storage Room 180	yes	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	180	Storage	Storage Room 180	yes	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	180	Storage	Storage Room 180	yes	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	180	Storage	Storage Room 180	yes	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	180	Storage	Storage Room 180	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	181	Storage	Storage Room 181	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182	Lockers - Female	Girl's Locker Room Sink Room	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	182A	Showers - Female	Girl's Locker Room Shower Room	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	W1	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	W2	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	W3	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	W4	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	183	Storage	Storage Room 183	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	ELEV	Elevators, Passenge	Elevator outside of Cafe 112B	yes	W1	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	ELEV	Elevators, Passenge	Elevator outside of Cafe 112B	yes	W2	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	ELEV	Elevators, Passenge	Elevator outside of Cafe 112B	yes	W3	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	ELEV	Elevators, Passenge	Elevator outside of Cafe 112B	yes	W4	Metal	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	ELEV	Elevators, Passenge	Elevator outside of Cafe 112B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110	Circulation (Hallway)	Main Hallway from 127A to 139B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110-PC	Pipe Chase	Pipe Chase near Boy's Restroom 114D in H110	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110A	Circulation (Hallway)	Hallway lobby outside Building Engineer's Office Suf	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	H110B	Circulation (Hallway)	Main Hallway to outside 126 Learning Center	yes	Floor	12x12	Unpainted	N																

Lead-Safe Certification Assessment Report																											
Dates: 10/9/23-11/9/23 Inspector Name and Certificate Number: Erik Swanson #006917 Inspection Company: Viva EHS Martin Luther King High School 6100 Stenton Ave, Philadelphia PA 19138																											
ULCS#	E l e m e n t	Bldg/Emt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sq) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes	
6060	1	B606001	1	H177	Circulation (Hallway)	Hallway entrance to Team room 177	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6060	1	B606001	1	H18	Circulation (Hallway)	Hallway from Classrooms 123 to 125	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H18	Circulation (Hallway)	Hallway from Classrooms 123 to 125	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H18	Circulation (Hallway)	Hallway from Classrooms 123 to 125	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H18	Circulation (Hallway)	Hallway from Classrooms 123 to 125	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H18	Circulation (Hallway)	Hallway from Classrooms 123 to 125	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	H19	Circulation (Hallway)	Hallway outside Classroom 125	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W1	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W2	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W2	Concrete	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W3	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	W4	CMU	Tan	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	M127A	Boiler Room	Boiler/Chiller Room M127A	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S1-1	Stairs	Stairwell 1	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S10-1	Stairs	Stairwell 10	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Riser	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Stringer	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Tread	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	W1	Concrete	White	Flaking	40	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	W2	Concrete	White	Flaking	80	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	W3	Concrete	White	Flaking	150	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	W4	Concrete	White	Flaking	100	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S11A	Stairs	Stairwell 11	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	Riser	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	Stringer	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	Tread	Metal	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	W1	Concrete	White	Flaking	40	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	W2	Concrete	White	Flaking	200	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	W3	Concrete	White	Flaking	150	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	1	S12-1	Stairs	Stairwell 12	yes	W4	Concrete	White	Flaking	150	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B6																									

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Ent ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occs/No [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity (SF) of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptors/ Notes	
6060	1	B606001	1	S2-1	Stairs	Stairwell 2	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S2-1	Stairs	Stairwell 2	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S2-1	Stairs	Stairwell 2	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S2-1	Stairs	Stairwell 2	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S3-1	Stairs	Stairwell 3	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S4-1	Stairs	Stairwell 4	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S5-1	Stairs	Stairwell 5	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S6-1	Stairs	Stairwell 6	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S7-1	Stairs	Stairwell 7	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones		
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	1	S9-1	Stairs	Stairwell 9	yes	Handrail	Metal	Grey</																	

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Emt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date reported to OEP and/or BE [8]	Quantity (SF) of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptors/ Notes	
6060	1	B606001	2	213B	Student Restrooms	Girls Restroom 213B	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6060	1	B606001	2	213B	Student Restrooms	Girls Restroom 213B	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B	Student Restrooms	Girls Restroom 213B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B	Student Restrooms	Girls Restroom 213B	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	213B-PC	Pipe Chase	Pipe Chase in Girls Restroom 213B	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	Door Frame 1	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	Door Frame 2	Metal	Purple	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	W1	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	W2	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	W3	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	W4	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214	Cafeteria (Dining Area)	Cafeteria 214	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pipe Chase off Cafeteria 214	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Cafeteria (Dining Area)	Pantry 214A	no	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214A	Kitchen and Dry Stor	Pantry 214A	no	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214B	Kitchen and Dry Stor	214B Storage	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214C	Student Restrooms	Girls Restroom 214C	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	Ceiling	Sheetrock	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	214D	Student Restrooms	Boys Restroom 214D	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	215	Senior High	Classroom 215	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	215	Senior High	Classroom 215	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	215	Senior High	Classroom 215	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	215	Senior High	Classroom 215	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	215	Senior High	Classroom 215	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	215	Senior High	Classroom 215	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	215	Senior High	Classroom 215	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	2	216	Senior High	Classroom 216	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	2	216	Senior High	Classroom 216	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	2	216	Senior High	Classroom 216	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A							

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occur (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity (SF) of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes
6060	1	B606001	2	229A	Storage	Classroom 229 Closet	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	229A	Storage	Classroom 229 Closet	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	229A	Storage	Classroom 229 Closet	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	229A	Storage	Classroom 229 Closet	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	230	Senior High	Classroom 230	yes	Door Frame 1	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	230	Senior High	Classroom 230	yes	Door Frame 2	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	230	Senior High	Classroom 230	yes	W1	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230	Senior High	Classroom 230	yes	W2	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230	Senior High	Classroom 230	yes	W3	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230	Senior High	Classroom 230	yes	W4	CMU	Blue	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230	Senior High	Classroom 230	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230	Senior High	Classroom 230	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	230A	Storage	Storage Room 230A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	231	Senior High	Classroom 231	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	231	Senior High	Classroom 231	yes	W1	CMU	White	Flaking	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva/Verte
6060	1	B606001	2	231	Senior High	Classroom 231	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	231	Senior High	Classroom 231	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	231	Senior High	Classroom 231	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	231	Senior High	Classroom 231	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	231	Senior High	Classroom 231	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	232	Senior High	Classroom 232	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	232	Senior High	Classroom 232	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	Door Frame	Metal	Gray	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	233	Senior High	Classroom 233	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233	Senior High	Classroom 233	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	233A	Storage	Storage Room 233A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234A	Senior High	Classroom 234A	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	Door Frame	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	234B	Senior High	Classroom 234B	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	235	Computer - Senior H	Office 235	yes	Door Frame 1	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	235	Computer - Senior H	Office 235	yes	Door Frame 2	Metal	Gray	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	235	Computer - Senior H	Office 235	yes	W1	CMU	White	None	0	0	N												

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occ./ (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptors/ Notes	
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267C	Music	Music Practice Room 267C	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267D	Music	Music Practice Room 267D	yes	Radiator	Metal	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	267E	Storage	Storage Room next to Music Classroom A267	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	Door Frame 1	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	268	Music	Music Classroom 268	yes	Door Frame 2	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	268	Music	Music Classroom 268	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268	Music	Music Classroom 268	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	Door Frame	Metal	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	W1	CMU	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	W2	CMU	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	W3	CMU	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	W4	CMU	Gray	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	268A	Music	Music Practice Room 268A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	Door Frame 1	Metal	Gray	Chipping	1	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	269	Music	Music Classroom 269	yes	Door Frame 2	Metal	Gray	Chipping	1	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	269	Music	Music Classroom 269	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269	Music	Music Classroom 269	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	Door Frame	Metal	Gray	Chipping	1	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269A	Music	Music Practice Room 269A	yes	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	Door Frame	Metal	Gray	Chipping	1	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	Ceiling	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269B	Music	Music Practice Room 269B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	2	269C	Music	Music Practice Room 269C	yes	Door Frame	Metal	Gray	Chipping	1	1	0</													

Dates: 10/9/23-11/9/23

Inspector Name and Certificate Number: Erik Swanson #006917

Inspection Company: Viva EHS

Lead-Safe Certification Assessment Report

Martin Luther King High School

6100 Stenton Ave, Philadelphia PA 19138

ULCS#	Element	Bldg/Ent ID	Floor	Space #	Space Type	On-Site Room Name	Student/Teacher Occ'd (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S14-2	Stairs	Stairwell 14	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	W1	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	W2	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	W3	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	W4	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Floor	Concrete	Grey	Chipping	50	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Tread	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S15-2	Stairs	Stairwell 15	yes	Handrail	Metal	Purple	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Floor	Concrete	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Tread	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Riser	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S2-2	Stairs	Stairwell 2	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S22	Circulation (Hallway)	Entrance Vestibule at Stairwell 6	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S28	Circulation (Hallway)	Main/Visitor's Entrance Vestibule	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Floor	Concrete	Grey	Chipping	50	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Tread	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S3-2	Stairs	Stairwell 3	yes	Handrail	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Floor	Concrete	Grey	Chipping	50	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Tread	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S4-2	Stairs	Stairwell 4	yes	Handrail	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD - Viva EHS	
6060	1	B606001	2	S5-2	Stairs	Stairwell 5	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S5-2	Stairs	Stairwell 5	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	2	S5-2	Stairs	Stairwell 5	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no		

																		Lead-Safe Certification Assessment Report																			
																		Dates: 10/9/23-11/9/23																			
																		Inspector Name and Certificate Number: Erik Swanson #006917										Martin Luther King High School									
																		Inspection Company: Viva EHS										6100 Stenton Ave, Philadelphia PA 19138									
ULCS#	E l e m e n t	Bldg/Ent ID	F o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occupied (yes/no) [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes											
6060	1	B606001	2	S6-2	Stairs	Stairwell 6	yes	Stringer	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S6-2	Stairs	Stairwell 6	yes	Handrail	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Riser	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Stringer	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Tread	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Handrail	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S7-2	Stairs	Stairwell 7	yes	Floor	Concrete	Grey	Flaking	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Floor	Concrete	Grey	Chipping	50	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Tread	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S8-2	Stairs	Stairwell 8	yes	Handrail	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S8-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Floor	Concrete	Grey	Chipping	50	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Riser	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Stringer	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Tread	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	S9-2	Stairs	Rear Stairwell to Boy's Locker Room	yes	Handrail	Metal	Black	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	W1	Metal	Brown	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	W3	Metal	Brown	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V222	Lobby	Entrance Vestibule beside Stairwell 11	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V224	Circulation (Hallway)	Entrance Vestibule to Hallway/Entrance Foyer betwe	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	2	V229	Circulation (Hallway)	Entrance Vestibule to Hallway outside Main Office S	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300	Kitchen (Family and	Culinary Arts Learning Center Kitchen	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones											
6060	1	B606001	3	300A	Vo-Tech Classroom	Culinary Arts Learning Center Lab Classroom	yes	Floor	12x12																												

										Lead-Safe Certification Assessment Report																							
										Dates: 10/9/23-11/9/23																							
										Inspector Name and Certificate Number: Erik Swanson #006917																							
										Inspection Company: Viva EHS																							
										6100 Stenton Ave, Philadelphia PA 19138																							
ULCS#	E	I	E	F						Student/Teacher	Component	Substrate	Paint Color	Description of	Damage	XRF Reading	XRF	Asbestos Paint	Debris Present	Quantity (sf)	Date	Quantity (SF)	Quantity of	Padlock	Contents	On-going	Plastering	Asbestos	Comments/				
	lement	nt	ldg	or	Space #	Space Type	On-Site Room Name	Occupancy [1]		Occupancy [1]		[2]		Damage	[3]	(mc/m2)	(positive/negative) [4]	sampd (positive/negative) [5]	(describe location) [6]	[7]	reported to OEP and/or BE [8]	of Damage Paint behind Radiator [9]	of Ceiling Tiles to be Replaced (Number of ceiling tiles not the SF)	Needs to be Removed	Need to be Moved [10]	Moisture Intrusion	Needed (yes or no) [11]	Abatement Needed (yes or no) [11]	Descriptions/ Notes				
6060	1	B606001	3	313	Storage	Storage Room 313	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6060	1	B606001	3	313	Storage	Storage Room 313	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313A	Student Restrooms	Boy's Restroom 313A	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313A	Student Restrooms	Boy's Restroom 313A	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313A	Student Restrooms	Boy's Restroom 313A	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313A	Student Restrooms	Boy's Restroom 313A	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313A	Student Restrooms	Boy's Restroom 313A	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B	Student Restrooms	Girl's Restroom 313B	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313B-PC	Pipe Chase	Pipe Chase in Girl's Restroom 313B	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313C	Computer - Senior High	313A Computer Lab	yes	Door Frame	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	313D	Mechanical Room	Mechanical Room	no	Door Frame	Metal	Purple	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	Door Frame 1	Metal	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	Door Frame 2	Metal	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	W1	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	W2	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	W3	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	W4	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314	Cafeteria (Dining Area)	Cafeteria 314	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314A	Pipe Chase	Pipe Chase off Cafeteria 314	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314B	Storage	314B Pantry	yes	Door Frame	Metal	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314B	Storage	314B Pantry	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3	314B	Storage	314B Pantry	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6060	1	B606001	3																														

										Lead-Safe Certification Assessment Report																			
										Dates: 10/9/23-11/9/23																			
										Inspector Name and Certificate Number: Erik Swanson #006917										Martin Luther King High School									
										Inspection Company: Viva EHS										6100 Stenton Ave, Philadelphia PA 19138									
ULCS#	E l e m e n t	Bldg/Elmt ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occs/yr [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2) [3]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/ Descriptions/ Notes			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	Column 4	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	Column 4	Concrete	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W1	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W2	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W3	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	W4	CMU	Purple	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326	Senior High	Learning Center 326	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326A	Storage	Storage Closet 326A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326B	Administrative Office	Office 326B	yes	Door Frame	Metal	Grey	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	Door Frame	Metal	Grey	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326C	Administrative Office	Office 326C	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326D	Administrative Office	Office 326D	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	Door Frame	Metal	Grey	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	Door Frame	Metal	Grey	Chipping	2	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326E	Administrative Office	Office 326E	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326F	Administrative Office	Office 326F	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	Door Frame	Metal	Grey	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	Ceiling	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326G	Administrative Office	Office 326G	yes	Door Frame	Metal	Grey	Chipping	1	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS			
6060	1	B606001	3	326H	Service Closets	Custodial Closet 326H	no	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones			
6060	1	B606001	3	326H	Service Closets	Custodial Closet 326H	no	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A									

Lead-Safe Certification Assessment Report																											
Dates: 10/9/23-11/9/23 Inspector Name and Certificate Number: Erik Swanson #006917 Inspection Company: Viva EHS Martin Luther King High School 6100 Stenton Ave, Philadelphia PA 19138																											
ULCS#	E l e m e n t	Bldg/Ent ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occ./yes/no [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/cm2)	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity (SF) of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes	
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A352A	Storage	Classroom 352 Storage Room 352A	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	W1	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	W3	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	W4	CMU	Yellow	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	Ceiling	Concrete	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353	Senior High	Classroom 353	yes	Door Frame	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A353A-3	Storage	Classroom 353 Storage Room 353A	yes	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	Door Frame	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A354	Storage	Storage Room A354	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	Door Frame	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354A	Storage	Storage Room 354A	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	Door Frame	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A354B	Restrooms, Staff - M	Staff Restroom 354B	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	Door Frame	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A355	Administrative Office	Kitchen 355	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	Door Frame	Metal	Grey	Chipping	5	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A356	Administrative Office	Assistant Superintendent's Office across from Class	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	Door Frame 1	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	Door Frame 2	Metal	Grey	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD - Viva EHS
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	NAD per Dones
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A357	Administrative Office	Conference room next to A356	yes	Floor	Carpet	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
6060	1	B606001	3	A370	Auditorium Balcony	Auditorium Balcony Projection Room	yes	W1	Plaster	White	None	0	0	Negative	Negative	N/A</											

Lead-Safe Certification Assessment Report																										
Dates: 10/9/23-11/9/23 Inspector Name and Certificate Number: Erik Swanson #006917 Inspection Company: Viva EHS Martin Luther King High School 6100 Stenton Ave, Philadelphia PA 19138																										
ULCS#	E l e m e n t	Bldg/Ent ID	F l o o r	Space #	Space Type	On-Site Room Name	Student/Teacher Occ./yes/no [1]	Component	Substrate Material [2]	Paint Color	Description of Damage	Damage Quantity (sf) [3]	XRF Reading (mg/mc2) [4]	XRF (positive/negative) [4]	Asbestos Paint sampled (positive/negative) [5]	Debris Present (describe location) [6]	Quantity (sf) [7]	Date debris reported to OEP and/or BE [8]	Quantity of Damage Paint behind Radiator [9]	Quantity of Ceiling Tile to be Replaced (Number of ceiling tiles not the SF)	Padlock Needs to be Removed	Contents Need to be Moved [10]	On-going Moisture Intrusion	Plastering Needed (yes or no)	Asbestos Abatement Needed (yes or no) [11]	Comments/Description/Notes
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329	Circulation (Hallway)	Hallway from Classrooms A351 to A353	yes	Floor	9x9	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-R	Restrooms, Staff - M	Restroom in H329 Near 351	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H329-RR	Restrooms, Staff - M	Restroom in Hallway H329 Near Section D	yes	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H32A	Circulation (Hallway)	Small Hallway next to T345 Music	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H33	Circulation (Hallway)	Hallway outside classroom 333	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34	Circulation (Hallway)	Hallway From 345A to 339	no	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	W1	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	W2	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	W3	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	W4	CMU	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H34-PC	Pipe Chase	Pipe Chase in Hallway From 345A to 339	no	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35	Circulation (Hallway)	Hallway from Classrooms 301 to 304	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H35A	Circulation (Hallway)	Hallway to rooms A354A and A354B	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	W2	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	W3	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	W4	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36	Circulation (Hallway)	Hallway from Classrooms 310 to 312	yes	Floor	12x12	Unpainted	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36A	Circulation (Hallway)	Hallway from Classrooms 305 to 309	yes	W1	CMU	White	None	0	0	Negative	Negative	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	no	NAD per Dones	
6060	1	B606001	3	H36A	Circulation (Hallway)	Hallway from Classrooms 305																				

[1] Use the drop down

[2] If the substrate is an undamaged ceramic tile that is unpainted, please note that in the comments. If undamaged ceramic tile is painted and the paint is damaged, a paint chip sample should be collected to determine whether or not the paint is lead-based.

[3] With the exception of "No Access," the entry should be numerical. For example, if there is no damage enter "0."

[4] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.

[5] Positive damaged lead-based paint requires a negative or positive entry in the asbestos paint sampled column. If no data, sampling, and analysis are required.

[6] Debris associated with a positive material (lead and/or asbestos), notify OEP ASAP.

[7] Unless the answer is N/A. There should be a number stated. 0 or more.

[8] Report LBP debris ASAP

[9] If applicable enter the quantity of damaged paint behind radiator on the line with the component that is in front of the damage (ex. wall or ceiling). If zero damage behind radiator enter zero and if no radiator present enter N/A.

[10] If radiators need to be removed call and/or e

[11] If asbestos abatement is needed a DDC should be created.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/9/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.0	2	0.9		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	374.9							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/10/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.0		
0.71 ± 0.08	3	0.8	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	371.3							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/11/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0.01	1	0		
1.04 ± 0.06	2	1.0	2	1.0	2	1.0		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	373.1							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/13/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.0		
0.71 ± 0.08	3	0.8	3	0.7	3	0.8		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	377.4							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/16/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.01	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.1	2	1.0		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	369.6							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/19/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.1	2	1.0		
0.71 ± 0.08	3	0.8	3	0.8	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	372.8							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/20/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.0		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	375.1							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/23/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.1	2	1.0		
0.71 ± 0.08	3	0.7	3	0.8	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	373.4							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/24/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.0	2	1.0		
0.71 ± 0.08	3	0.8	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	375.9							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/25/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.0	2	1.0		
0.71 ± 0.08	3	0.7	3	0.7	3	0.9		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	374.4							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/26/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.1	2	1.0		
0.71 ± 0.08	3	0.8	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	378.1							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/27/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.01	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.1		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	370.7							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/30/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.0	2	1.1	2	1.1		
0.71 ± 0.08	3	0.7	3	0.9	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	375.3							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 10/31/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.1		
0.71 ± 0.08	3	0.7	3	0.7	3	0.8		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	377.7							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 11/8/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.01	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.0	2	1.1		
0.71 ± 0.08	3	0.7	3	0.7	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	370.7							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



— EHS —

Calibration Check Test Results

Client: SDP


Address: MLK High

Date: 11/9/23

XRF Serial #: 112574

Project Number: 230511

Inspector: Erik Swanson

Inspector
Signature: 

Lead Paint Standards Surface Lead mg/cm ²	Start of Job 1 st Calibration Check		2 nd Calibration Check		3 rd Calibration Check		4 th Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0	1	0	1	0		
1.04 ± 0.06	2	1.1	2	1.1	2	1.1		
0.71 ± 0.08	3	0.7	3	0.8	3	0.7		
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
Detector Resolution	373.3							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.



Philadelphia Department of Public Health Certification of School Lead Safe Status

By signing this certificate, I confirm that I have done a visual inspection of the areas where children have access, including contact surfaces where children store their equipment or materials, and confirm these areas do not have deteriorated lead-based paint. A certified risk assessor or lead dust sampling technician completed verification wipe tests in accordance with the EPA's RRP guidelines and confirms they meet the EPA's cleanliness standard. A certified risk assessor or lead dust sampling technician collected interior dust wipe samples in compliance with EPA regulations in work areas and confirms they did not contain lead contaminated dust in excess of EPA dust lead standards in Pre-K, Kindergarten, and 1st Grade classrooms as well as the restrooms, offices, cafeterias, gymnasiums, and auditoriums these children routinely occupy. This certificate is valid for 4 years from date of verification.

Martin Luther King HS, 6100 Stenton Avenue, Philadelphia, PA 19138

School Name

Street Address

Viva Environmental, Health, & Safety, LLC.

Erik Swanson #006917

Certifying Company (print)

Risk Assessor, Lead Inspector PA Lic. #, EPA Firm Certification or Lead Dust Sampling Technician Certification #

11/9/23

Inspector/Risk Assessor or Dust Wipe Sampling Technician Name (Signature)

Date of Verification

Victoria Flemming, 215.400.5768 (Office) 267.800.5045 (Cell) vflemming-ext@philasd.org

School Official Name, Telephone and E-mail Address

Please note: A visual inspection of the areas listed above has been completed by a certified risk assessor and no damage to Lead Based Painted surfaces was observed. Therefore, no verification wipe samples were completed. This school will be reassessed within 4 years of this certification.