

AMY @ Levering Lead Safe Assessment Sheet XRF

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W1	Brick	White	Flaking	30	4.6	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Column	Concrete	White	Flaking	4	2	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W2	Brick	White	Flaking	32	4.1	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Column	Concrete	White	Flaking	12	3.7	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W3	Brick	White	Flaking	160	5.3	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Column	Concrete	White	Flaking	2	5.1	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Pipe	Metal	White	Cracking	2	0.2	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W4	Brick	White	Flaking	15	4.7	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W4	Concrete	White	Flaking	16	4.3	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	W4	CMU	White	None	0	0.1	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Door Frame	Metal	Tan	Chipping	1	0	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Door	Metal	Tan	Chipping	1	0	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Window Frame	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Pipe	Metal	White	Flaking	5	0.1	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Column	Concrete	White	Flaking	15	5.6	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Wall Divider	CMU	White	None	0	0	Negative
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Ceiling	Concrete	White	Flaking	120	4.8	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Radiator	Metal	White	Flaking	3	5.9	Positive
1	B629001-1	B	1-1	Custodial Storeroom and Restroom next to Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2-1	Boy's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2-1	Boy's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2-1	Boy's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2-1	Boy's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2-1	Boy's Restroom	Ceiling	Concrete	White	Cracking	2	3.8	Positive
1	B629001-1	B	2-1	Boy's Restroom	Conduit	Metal	White	None	0	0	Negative
1	B629001-1	B	2-1	Boy's Restroom	Radiator	Metal	Silver	Flaking	32	1.1	Positive
1	B629001-1	B	2-1	Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	W1	CMU	Gray	None	0	0	Negative

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	W1	Brick	White	None	0	2.37	Positive
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	W2	Concrete	White	Chipping	3	2.32	Positive
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	W3	Brick	White	Chipping	5	2.27	Positive
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	W4	Brick	White	None	0	2.74	Positive
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	Door Frame	Wood	Brown	Chipping	1	0.06	Negative
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	Duct	Metal	White	None	0	2.35	Positive
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	Shelving Bracket	Wood	Brown	Friction	5	0.4	Negative
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	Shelving	Wood	White	Friction	30	0.4	Negative
1	B629001-1	B	2A-1-B	Hallway Closet next to Boy's Restroom	Ceiling	Concrete	White	Cracking	2	3.48	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	W1	Brick	White	Flaking	20	7	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	W2	Brick	White	Flaking	15	7.7	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	Access Panel	Metal	White	None	0	0	Negative
1	B629001-1	B	2H	Closet next to Cafeteria	W3	Brick	White	Flaking	20	6.1	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	W4	Brick	White	Flaking	8	4.5	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	Ceiling	Concrete	White	Chipping	2	4.3	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	Ceiling	Wood	White	None	0	4.1	Positive
1	B629001-1	B	2H	Closet next to Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	W1	Brick	White	None	0	4.4	Positive
1	B629001-1	B	3-1	Cafeteria	Conduit	Vinyl	Tan	None	0	1.8	Positive
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	White	Chipping	2	5.2	Positive
1	B629001-1	B	3-1	Cafeteria	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	W2	Brick	White	None	0	5.7	Positive
1	B629001-1	B	3-1	Cafeteria	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	B	3-1	Cafeteria	W3	Brick	White	None	0	4.2	Positive
1	B629001-1	B	3-1	Cafeteria	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	White	None	0	0.1	Negative
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	Brown	None	0	0	Negative
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	White	None	0	0.1	Negative
1	B629001-1	B	3-1	Cafeteria	W4	Brick	White	None	0	3.6	Positive
1	B629001-1	B	3-1	Cafeteria	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	Conduit	Metal	Tan	Flaking	12	0	Negative
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	White	Chipping	1	4.6	Positive
1	B629001-1	B	3-1	Cafeteria	Pipe	Metal	Brown	None	0	5.2	Positive
1	B629001-1	B	3-1	Cafeteria	Ceiling	Concrete	White	Flaking	5	4.2	Positive
1	B629001-1	B	3-1	Cafeteria	Duct	Metal	White	None	0	6.7	Positive
1	B629001-1	B	3-1	Cafeteria	Radiator	Metal	Silver	None	0	2.5	Positive
1	B629001-1	B	3-1	Cafeteria	Radiator	Metal	Silver	None	0	1.4	Positive
1	B629001-1	B	3-1	Cafeteria	Column	Brick	White	None	0	4.3	Positive
1	B629001-1	B	3-1	Cafeteria	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	3-1	Cafeteria	Window Lintel	Concrete	White	None	0	0	Negative
1	B629001-1	B	3-1	Cafeteria	Baseboard	Concrete	Gray	None	0	0	Negative
1	B629001-1	B	3-1	Cafeteria	Stair Tread	Metal	Gray	Chipping	1	0.7	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W1	Brick	White	Flaking	35	2.9	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W1	Brick	Gray	Chipping	3	5	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W1	Concrete	Gray	Flaking	50	0.4	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Handrail	Metal	Gray	Chipping	4	4.7	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Stair Tread	Concrete	Gray	Chipping	2	2.5	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Stair Tread	Metal	Gray	Chipping	2	1	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Stair Riser	Concrete	Gray	Chipping	1	2.6	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Stair Stringer	Concrete	Gray	None	0	1.9	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Conduit	Metal	White	Flaking	12	0.4	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Electrical Panel	Metal	Gray	Chipping	3	0.3	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Pipe	Metal	White	Flaking	14	3.4	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W2	Brick	White	Chipping	5	2.7	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W2	Brick	Gray	Flaking	5	2.7	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W2	Concrete	Gray	Chipping	9	1.8	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Conduit	Metal	White	None	0	0	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Electrical Panel	Wood	Gray	None	0	0.9	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W3	Brick	White	Flaking	80	0.1	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W3	Concrete	Gray	Flaking	160	0.8	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W3	Concrete	Blue	Flaking	48	2.9	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Pipe	Metal	Gray	Flaking	2	1.8	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Window Frame	Wood	Brown	Chipping	4	3.2	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W4	Brick	White	None	0	3.6	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W4	Brick	Gray	Chipping	1	4.2	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	W4	Concrete	Gray	Flaking	14	0.6	Negative	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Ceiling	Concrete	White	Flaking	100	4.4	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Column	Concrete	Gray	Flaking	20	3.6	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Duct	Metal	White	Flaking	400	2.2	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Duct	Metal	Gray	Flaking	200	4.5	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Pump Deck	Concrete	Gray	Flaking	8	9.6	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Fan Unit	Metal	White	Flaking	350	3.9	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Fan Unit	Metal	Gray	Flaking	10	6.1	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Fan Unit	Metal	White	Flaking	370	3.5	Positive	
1	B629001-1	B	4	Fan Room/Building Engineer's Office	Fan Unit	Metal	Gray	Flaking	90	4.3	Positive	
1	B629001-1	B	5-1	Girl's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5-1	Girl's Restroom	Access Panel	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	B	5-1	Girl's Restroom	Duct	Metal	White	Flaking	1	3.8	Positive	
1	B629001-1	B	5-1	Girl's Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5-1	Girl's Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5-1	Girl's Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5-1	Girl's Restroom	Ceiling	Concrete	White	Flaking	20	5.7	Positive	
1	B629001-1	B	5-1	Girl's Restroom	Radiator	Metal	Silver	None	0	5.6	Positive	
1	B629001-1	B	5-1	Girl's Restroom	Radiator	Metal	Silver	None	0	4.6	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	B	5-1	Girl's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	W1	Brick	White	Flaking	25	0.3	Negative	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	W2	Brick	White	Flaking	4	0.3	Negative	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	W3	Brick	White	Flaking	32	2.4	Positive	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	Pipe	Metal	White	None	0	3.2	Positive	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	W4	Brick	White	Flaking	10	0.4	Negative	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	W4	Concrete	White	Flaking	9	0.7	Positive	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	Bracket	Metal	White	None	0	1.9	Positive	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	Ceiling	Plaster	White	Cracking	2	0.9	Positive	
1	B629001-1	B	5B	Hallway Closet next to Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5A-1	Boiler Room	W1	Brick	White	Flaking	350	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W1	Concrete	White	Flaking	40	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W1	Concrete	Silver	Flaking	100	4.3	Positive	
1	B629001-1	B	5A-1	Boiler Room	Pipe	Metal	White	Flaking	18	0.3	Negative	
1	B629001-1	B	5A-1	Boiler Room	W2	Brick	White	Flaking	450	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W2	Concrete	White	Flaking	120	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W2	Concrete	Silver	Flaking	120	3.6	Positive	
1	B629001-1	B	5A-1	Boiler Room	Pipe	Metal	White	Flaking	16	3	Positive	
1	B629001-1	B	5A-1	Boiler Room	Boiler	Metal	Gray	None	0	0	Negative	
1	B629001-1	B	5A-1	Boiler Room	Conduit	Metal	White	None	0	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W3	Brick	White	Flaking	280	0	Negative	
1	B629001-1	B	5A-1	Boiler Room	W3	Brick	Silver	Chipping	30	7.2	Positive	
1	B629001-1	B	5A-1	Boiler Room	W3	Concrete	White	Flaking	450	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W3	Concrete	Silver	Chipping	45	5.3	Positive	
1	B629001-1	B	5A-1	Boiler Room	W4	Brick	White	Flaking	50	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W4	Concrete	White	Flaking	200	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room	W4	Concrete	Silver	Chipping	200	5.4	Positive	
1	B629001-1	B	5A-1	Boiler Room	Window Frame	Wood	Gray	Flaking	250	3.2	Positive	
1	B629001-1	B	5A-1	Boiler Room	Sink	Porcelain	Black	Chipping	5	2.3	Positive	
1	B629001-1	B	5A-1	Boiler Room	Ceiling	Concrete	White	Flaking	100	0	Negative	
1	B629001-1	B	5A-1	Boiler Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	5A-1	Boiler Room	Duct	Metal	Silver	Flaking	300	0	Negative	
1	B629001-1	B	5A-1	Boiler Room	Duct	Metal	White	Flaking	50	4.3	Positive	
1	B629001-1	B	5A-1	Boiler Room	Column	Concrete	White	Flaking	50	4.3	Positive	
1	B629001-1	B	5A-1	Boiler Room	Column	Concrete	Gray	Flaking	20	3.5	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 1	Door Frame	Wood	Brown	Friction	4	0	Negative	
1	B629001-1	B	5A-1	Boiler Room Wall 1	Door	Wood	Brown	Friction	5	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room Wall 1	Handrail	Metal	Gray	Chipping	5	4.6	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 1	Stair Stringer	Metal	Gray	Chipping	2	4.2	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 1	Stair Tread	Concrete	Gray	Chipping	10	1.5	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 2	Duct	Metal	Silver	Flaking	40	0	Negative	
1	B629001-1	B	5A-1	Boiler Room Wall 2	Pipe	Metal	White	Flaking	25	0.1	Negative	
1	B629001-1	B	5A-1	Boiler Room Wall 3	Chimney Door	Metal	Silver	None	0	4.7	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	B	5A-1	Boiler Room Wall 3	Chimney Door Frame	Metal	Silver	Flaking	2	5.6	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 3	Pipe	Metal	Silver	Flaking	1	1.8	Positive	
1	B629001-1	B	5A-1	Boiler Room Wall 3	Pipe	Metal	White	Flaking	20	0.4	Negative	
1	B629001-1	B	5A-1	Boiler Room Wall 4	Window Frame	Wood	Gray	Flaking	40	2.9	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	W1	Brick	White	Cracking	2	3.4	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	Door Frame	Wood	Blue	Chipping	1	0.1	Negative	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	Door	Wood	Blue	Chipping	1	0.1	Negative	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	W2	Brick	White	None	0	3.4	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	W3	Concrete	White	Flaking	6	4.2	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	W4	Brick	White	Flaking	4	2.2	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	W4	Concrete	White	Flaking	8	3	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	Ceiling	Concrete	White	Flaking	40	4.1	Positive	
1	B629001-1	B	6D	Closet off Boy's Side Stairwell to Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	W1	Brick	White	Chipping	2	6.8	Positive	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	Door Frame	Wood	Blue	Chipping	1	0.1	Negative	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	Door	Wood	Blue	Chipping	1	0.1	Negative	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	W2	Concrete	White	Flaking	30	1.8	Positive	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	W3	Concrete	White	Flaking	50	3.8	Positive	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	W4	Brick	White	Flaking	30	3.9	Positive	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	Ceiling	Concrete	White	Flaking	20	3.4	Positive	
1	B629001-1	B	6F	Closet off Girl's Side Stairwell to Gym	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	S002	Girl's Side Stairwell	W1	Plaster	Tan	None	0	11.2	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Door Frame	Metal	Blue	Chipping	2	3.8	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Door	Metal	Blue	Chipping	3	3.1	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Shelving	Wood	White	None	0	6.1	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	W2	Plaster	Tan	None	0	10.7	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Handrail Support	Metal	Blue	Chipping	1	0.9	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	W3	Plaster	Tan	None	0	11	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Radiator Shield	Metal	Silver	Chipping	2	4.7	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Radiator	Metal	Silver	Chipping	2	0	Negative	
1	B629001-1	B	S002	Girl's Side Stairwell	Radiator Cover	Metal	Silver	Chipping	1	0.1	Negative	
1	B629001-1	B	S002	Girl's Side Stairwell	W4	Plaster	Tan	None	0	10.8	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Handrail Support	Metal	Blue	Chipping	1	2	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Ceiling	Plaster	White	None	0	10.8	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	B	S002	Girl's Side Stairwell	Stair Tread	Concrete	Gray	None	0	2.9	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Stair Riser	Concrete	Gray	None	0	0.6	Negative	
1	B629001-1	B	S002	Girl's Side Stairwell	Newel Post	Metal	Blue	Chipping	1	5.5	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Baluster	Metal	Blue	Chipping	1	2.8	Positive	
1	B629001-1	B	S002	Girl's Side Stairwell	Stair Stringer	Concrete	Blue	None	0	0.7	Positive	
1	B629001-1	B	H001	Basement Hallway	W1	Brick	White	Chipping	5	5.3	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	B	H001	Basement Hallway	Door	Wood	Brown	Chipping	3	0.3	Negative
1	B629001-1	B	H001	Basement Hallway	Door Frame	Wood	Brown	Chipping	3	3.3	Positive
1	B629001-1	B	H001	Basement Hallway	Cove Base	Concrete	Gray	Chipping	1	0	Negative
1	B629001-1	B	H001	Basement Hallway	W2	Brick	White	Chipping	12	3.5	Positive
1	B629001-1	B	H001	Basement Hallway	Door Frame	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	H001	Basement Hallway	Door Frame	Metal	Brown	Chipping	1	0.1	Negative
1	B629001-1	B	H001	Basement Hallway	Cove Base	Concrete	Gray	Flaking	10	0.1	Negative
1	B629001-1	B	H001	Basement Hallway	W3	Brick	White	None	0	4.8	Positive
1	B629001-1	B	H001	Basement Hallway	Cove Base	Concrete	Gray	Chipping	1	0	Negative
1	B629001-1	B	H001	Basement Hallway	W4	Brick	White	Chipping	40	4.5	Positive
1	B629001-1	B	H001	Basement Hallway	Ceiling	Concrete	White	Flaking	250	5.7	Positive
1	B629001-1	B	H001	Basement Hallway	Duct	Metal	White	Flaking	10	7.4	Positive
1	B629001-1	B	H001	Basement Hallway	Radiator	Metal	White	None	0	6.6	Positive
1	B629001-1	B	H001	Basement Hallway	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	H001	Basement Hallway	Trench Cover	Metal	Gray	Cracking	18	5.4	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	W1	Brick	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	B	S001	Boy's Side Stairwell	W1	Plaster	Tan	None	0	10	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Door	Metal	Blue	Chipping	3	4.48	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Door Frame	Metal	Blue	Chipping	3	4.43	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Transom Panel	Metal	Blue	Chipping	3	0.95	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	W2	Plaster	Tan	None	0	10	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Handrail	Metal	Blue	Chipping	1	0.26	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Door Frame	Wood	Blue	Chipping	1	0.1	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Door	Wood	Blue	Flaking	5	0.12	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	W3	Plaster	Tan	Cracking	1	9.64	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Door Frame	Wood	Blue	Flaking	5	0.4	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Door	Metal	Blue	Flaking	10	0	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	W4	Plaster	Tan	Chipping	2	9.28	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Duct	Metal	Tan	None	0	8.34	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Baluster	Metal	Blue	Friction	3	0.08	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Newel Post	Metal	Blue	Friction	5	4.64	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Stair Tread	Concrete	Gray	Flaking	10	0.15	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Stair Riser	Concrete	Gray	Flaking	5	1.41	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Stair Stringer	Concrete	Gray	Friction	2	0.87	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Handrail Support	Metal	Blue	Friction	1	0	Negative
1	B629001-1	B	S001	Boy's Side Stairwell	Ceiling	Concrete	White	Flaking	4	5.7	Positive
1	B629001-1	B	S001	Boy's Side Stairwell	Floor	Concrete	Brown	None	0	0	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	W1	Plaster	Tan	Flaking	10	10.3	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	Door	Metal	Brown	Chipping	1	0.4	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	Door Frame	Metal	Brown	Chipping	1	0.4	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	W2	Plaster	Tan	Cracking	4	10.9	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Conduit	Metal	Tan	None	0	0	Negative

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	1	Lobby	Main Entrance Lobby	Vent	Metal	Brown	None	0	0	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	W3	Plaster	Tan	None	0	10.7	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	W4	Plaster	Tan	Cracking	8	10.8	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Vent	Metal	Brown	None	0	0	Negative
1	B629001-1	1	Lobby	Main Entrance Lobby	Ceiling	Plaster	Tan	Cracking	6	10.9	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Decorative Moulding	Plaster	White	Cracking	8	11.4	Positive
1	B629001-1	1	Lobby	Main Entrance Lobby	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	W1	Plaster	Tan	None	0	11.2	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Door	Wood	Gray	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	W2	Plaster	Tan	None	0	11.9	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Electrical Panel	Metal	Gray	None	0	0.1	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Fire Alarm	Metal	Red	None	0	1.3	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Conduit	Metal	Tan	None	0	0.2	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	W3	Plaster	Tan	None	0	10.9	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator Cover	Metal	Silver	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator	Metal	Silver	Flaking	1	0.4	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Electrical Panel	Metal	Tan	None	0	1.2	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Electrical Panel	Metal	Tan	None	0	1	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator Cover	Metal	Silver	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator	Metal	Silver	None	0	0.1	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator Cover	Metal	Silver	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator	Metal	Silver	Flaking	1	0.5	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator Cover	Metal	Silver	None	0	0.1	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Radiator	Metal	Silver	Chipping	2	0.2	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Pipe	Metal	Gray	None	0	7.8	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Pipe	Metal	Tan	None	0	10.5	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Klaxon Horn	Metal	Gray	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	W4	Plaster	Tan	None	0	10.4	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Electrical Panel	Metal	Gray	None	0	0.1	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Door Frame	Wood	Brown	None	0	0.1	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Ceiling	Plaster	White	None	0	10.8	Positive
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Conduit	Metal	White	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Conduit	Vinyl	White	None	0	0	Negative
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	W1	Concrete	White	Cracking	2	0	Negative
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	W2	Concrete	White	Cracking	10	0	Negative
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	W3	Concrete	White	Cracking	12	0	Negative
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	W4	Concrete	White	Cracking	1	0.1	Negative
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	Ceiling	Concrete	White	Cracking	2	0.2	Negative
1	B629001-1	1	PS1	Pipe Shaft next to Main Office	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	S101	Stairwell across from Classroom 101	W1	Plaster	White	None	0	10.7	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Door Frame	Metal	Blue	Chipping	2	0.4	Negative	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Door	Metal	Blue	Chipping	1	0.6	Negative	
1	B629001-1	1	S101	Stairwell across from Classroom 101	W2	Plaster	White	None	0	8.9	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	W3	Plaster	White	None	0	2.2	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Radiator	Metal	Silver	Flaking	2	0.6	Negative	
1	B629001-1	1	S101	Stairwell across from Classroom 101	W4	Plaster	White	None	0	10.4	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Handrail Support	Metal	Blue	Chipping	1	3.2	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Ceiling	Plaster	White	None	0	10.8	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Newel Post	Metal	Blue	Chipping	4	7.6	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Stair Tread	Concrete	Gray	None	0	1.4	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Stair Riser	Concrete	Gray	None	0	1.7	Positive	
1	B629001-1	1	S101	Stairwell across from Classroom 101	Stair Stringer	Concrete	Gray	Chipping	1	1.5	Positive	
1	B629001-1	1	S102	Stairwell across from Library	W1	Plaster	White	None	0	10.4	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Door	Metal	Blue	Chipping	1	0.5	Negative	
1	B629001-1	1	S102	Stairwell across from Library	Door Frame	Metal	Blue	Chipping	1	0.3	Negative	
1	B629001-1	1	S102	Stairwell across from Library	W2	Plaster	White	None	0	11.6	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Handrail Support	Metal	Blue	Chipping	1	1.4	Positive	
1	B629001-1	1	S102	Stairwell across from Library	W3	Plaster	White	None	0	2.7	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Radiator	Metal	Silver	Flaking	3	3.9	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Radiator Shield	Metal	Silver	Flaking	1	2.1	Positive	
1	B629001-1	1	S102	Stairwell across from Library	W4	Plaster	White	None	0	11.5	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Handrail Support	Metal	Blue	Chipping	1	2.8	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Ceiling	Plaster	White	None	0	10.6	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	S102	Stairwell across from Library	Newel Post	Metal	Blue	Chipping	2	7.6	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Baluster	Metal	Blue	Chipping	1	5.3	Positive	
1	B629001-1	1	S102	Stairwell across from Library	Stair Stringer	Concrete	Blue	None	0	0.3	Negative	
1	B629001-1	1	S102	Stairwell across from Library	Stair Tread	Concrete	Gray	None	0	0	Negative	
1	B629001-1	1	S102	Stairwell across from Library	Stair Riser	Concrete	Gray	None	0	0.3	Negative	
1	B629001-1	1	H101	Hallway from Counselor's Office to Teacher's Lounge	Cove Base	Concrete	Gray	None	0	0	Negative	
1	B629001-1	1	S103	Fire Tower next to Library	W1	Brick	White	Chipping	1	4.9	Positive	
1	B629001-1	1	S103	Fire Tower next to Library	Door Frame	Metal	Brown	None	0	0.1	Negative	
1	B629001-1	1	S103	Fire Tower next to Library	Door	Metal	Brown	None	0	0	Negative	
1	B629001-1	1	S103	Fire Tower next to Library	W2	Brick	White	Chipping	5	5.3	Positive	
1	B629001-1	1	S103	Fire Tower next to Library	W3	Metal	Brown	Flaking	15	5.8	Positive	
1	B629001-1	1	S103	Fire Tower next to Library	Door Frame	Metal	Brown	None	0	0	Negative	
1	B629001-1	1	S103	Fire Tower next to Library	Door	Metal	Brown	None	0	0	Negative	
1	B629001-1	1	S103	Fire Tower next to Library	W4	Brick	White	Chipping	2	5.3	Positive	
1	B629001-1	1	S103	Fire Tower next to Library	Ceiling	Concrete	White	Chipping	20	4.2	Positive	
1	B629001-1	1	S103	Fire Tower next to Library	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	101	Classroom 101	W1	Plaster	Tan	Cracking	3	10.6	Positive	
1	B629001-1	1	101	Classroom 101	Bulletin Board	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	Door Frame	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	101	Classroom 101	Door	Wood	Brown	None	0	0	Negative	
1	B629001-1	1	101	Classroom 101	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	W2	Plaster	Tan	None	0	0	Negative	
1	B629001-1	1	101	Classroom 101	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	W3	Plaster	Tan	Cracking	8	11.2	Positive	
1	B629001-1	1	101	Classroom 101	Window Sill	Wood	Brown	Chipping	1	0.4	Negative	
1	B629001-1	1	101	Classroom 101	Radiator	Metal	Silver	Chipping	2	2.3	Positive	
1	B629001-1	1	101	Classroom 101	Radiator Cover	Metal	Silver	Chipping	1	0.1	Negative	
1	B629001-1	1	101	Classroom 101	Window Apron	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	W4	Plaster	Tan	None	0	3.3	Positive	
1	B629001-1	1	101	Classroom 101	Blackboard Ledge	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	101	Classroom 101	Ceiling	Plaster	White	Flaking	60	9.8	Positive	
1	B629001-1	1	101	Classroom 101	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	101A	Classroom 101 Restroom	W1	Plaster	White	Cracking	2	8.5	Positive	
1	B629001-1	1	101A	Classroom 101 Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	101A	Classroom 101 Restroom	W2	Plaster	White	Efflorescence	30	1.3	Positive	
1	B629001-1	1	101A	Classroom 101 Restroom	W3	Plaster	White	Efflorescence	20	6.3	Positive	
1	B629001-1	1	101A	Classroom 101 Restroom	W4	Plaster	White	Cracking	10	6.4	Positive	
1	B629001-1	1	101A	Classroom 101 Restroom	Ceiling	Plaster	White	Cracking	2	7.4	Positive	
1	B629001-1	1	101A	Classroom 101 Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W1	Plaster	White	None	0	7.6	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W1	Plaster	Tan	Flaking	2	11.5	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W2	Plaster	White	None	0	9.4	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W2	Plaster	Tan	None	0	9.1	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W3	Plaster	White	None	0	7.1	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W3	Plaster	Tan	None	0	8.5	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W4	Plaster	White	Flaking	4	9.3	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	W4	Plaster	Tan	None	0	8.1	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	Radiator	Metal	Silver	Chipping	1	2.3	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	Ceiling	Plaster	White	None	0	8.8	Positive	
1	B629001-1	1	101B	Counselor's Office next to Classroom 101	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	101C	Classroom 101 Coat Closet	W1	Plaster	White	Cracking	2	8.9	Positive	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Conduit	Metal	White	None	0	0.1	Negative	
1	B629001-1	1	101C	Classroom 101 Coat Closet	W2	Plaster	White	Cracking	1	9.1	Positive	
1	B629001-1	1	101C	Classroom 101 Coat Closet	W3	Plaster	White	Efflorescence	40	10.4	Positive	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Coat Rack	Wood	White	None	0	0.1	Negative	
1	B629001-1	1	101C	Classroom 101 Coat Closet	W4	Plaster	White	Cracking	1	10.1	Positive	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Pipe	Metal	White	Flaking	1	8.8	Positive	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Ceiling	Plaster	White	Cracking	2	9.9	Positive	

AMY @ Levering Lead Safe Assessment Sheet XRF

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	101C	Classroom 101 Coat Closet	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	101D	Classroom 101 Closet	W1	Plaster	Green	None	0	10.3	Positive	
1	B629001-1	1	101D	Classroom 101 Closet	W2	Plaster	Green	Cracking	25	10.5	Positive	
1	B629001-1	1	101D	Classroom 101 Closet	W3	Plaster	Green	Cracking	10	7.1	Positive	
1	B629001-1	1	101D	Classroom 101 Closet	W4	Plaster	Green	Cracking	12	8.9	Positive	
1	B629001-1	1	101D	Classroom 101 Closet	Ceiling	Plaster	Green	Cracking	20	9.9	Positive	
1	B629001-1	1	101D	Classroom 101 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	W1	Plaster	White	None	0	10.6	Positive	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	Chair Rail	Wood	Brown	None	0	0	Negative	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	W2	Plaster	White	Chipping	1	10.8	Positive	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	W2	Sheetrock	White	Chipping	1	0	Negative	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	W3	Plaster	White	None	0	10.8	Positive	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	Radiator	Metal	Silver	Chipping	3	1.5	Positive	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	W4	Plaster	White	Chipping	1	10.3	Positive	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	Ceiling	Plaster	White	None	0	0.4	Negative	
1	B629001-1	1	102	Staff Locker Room next to Classroom 103	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102A	Staff Locker Room Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102A	Staff Locker Room Restroom	Door Frame	Metal	Tan	Chipping	1	0	Negative	
1	B629001-1	1	102A	Staff Locker Room Restroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102A	Staff Locker Room Restroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102A	Staff Locker Room Restroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102A	Staff Locker Room Restroom	Radiator	Metal	Silver	Chipping	5	0.2	Negative	
1	B629001-1	1	102A	Staff Locker Room Restroom	Ceiling	Sheetrock	White	None	0	0	Negative	
1	B629001-1	1	102A	Staff Locker Room Restroom	Access Panel	Metal	Gray	None	0	0	Negative	
1	B629001-1	1	102A	Staff Locker Room Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	102B	Staff Locker Room Closet	W1	Plaster	White	Chipping	7	11.2	Positive	
1	B629001-1	1	102B	Staff Locker Room Closet	W2	Plaster	White	None	0	12.2	Positive	
1	B629001-1	1	102B	Staff Locker Room Closet	W3	Plaster	White	None	0	10.9	Positive	
1	B629001-1	1	102B	Staff Locker Room Closet	W4	Plaster	White	Chipping	12	10.7	Positive	
1	B629001-1	1	102B	Staff Locker Room Closet	Ceiling	Plaster	White	Chipping	5	7.1	Positive	
1	B629001-1	1	102B	Staff Locker Room Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	103	Classroom 103	W1	Plaster	White	Cracking	6	10.2	Positive	
1	B629001-1	1	103	Classroom 103	Beam	Concrete	White	Cracking	2	0.2	Negative	
1	B629001-1	1	103	Classroom 103	Conduit	Metal	White	None	0	0.1	Negative	
1	B629001-1	1	103	Classroom 103	W2	Plaster	Tan	Cracking	16	9.3	Positive	
1	B629001-1	1	103	Classroom 103	Window Sill	Wood	Brown	Chipping	4	0.2	Negative	
1	B629001-1	1	103	Classroom 103	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	103	Classroom 103	Radiator	Metal	Brown	None	0	0.1	Negative	
1	B629001-1	1	103	Classroom 103	W3	Plaster	Tan	None	0	9.1	Positive	
1	B629001-1	1	103	Classroom 103	Window Sill	Wood	Brown	Chipping	10	0.2	Negative	
1	B629001-1	1	103	Classroom 103	W4	Plaster	Tan	Cracking	1	9.9	Positive	
1	B629001-1	1	103	Classroom 103	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	103	Classroom 103	Ceiling	Plaster	White	Cracking	6	10.2	Positive	

AMY @ Levering Lead Safe Assessment Sheet XRF

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	103	Classroom 103	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	103A	Classroom 103 Restrooms	W1	Plaster	White	Flaking	20	9.6	Positive	
1	B629001-1	1	103A	Classroom 103 Restrooms	W2	Plaster	White	Cracking	16	8.9	Positive	
1	B629001-1	1	103A	Classroom 103 Restrooms	W3	Plaster	White	Flaking	8	9.3	Positive	
1	B629001-1	1	103A	Classroom 103 Restrooms	W4	Plaster	White	Flaking	10	9.8	Positive	
1	B629001-1	1	103A	Classroom 103 Restrooms	Ceiling	Plaster	White	Flaking	100	10.4	Positive	
1	B629001-1	1	103A	Classroom 103 Restrooms	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	103B	Classroom 103 Closet	W1	Plaster	Blue	Cracking	2	9.7	Positive	
1	B629001-1	1	103B	Classroom 103 Closet	W2	Plaster	Blue	Cracking	1	9.1	Positive	
1	B629001-1	1	103B	Classroom 103 Closet	W3	Plaster	Blue	Cracking	4	8.8	Positive	
1	B629001-1	1	103B	Classroom 103 Closet	W4	Plaster	Blue	Cracking	1	9.3	Positive	
1	B629001-1	1	103B	Classroom 103 Closet	Ceiling	Plaster	Blue	Flaking	6	10.2	Positive	
1	B629001-1	1	103B	Classroom 103 Closet	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	103C	Classroom 103 Coat Closet	W1	Plaster	Tan	Cracking	1	9	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	W2	Plaster	Tan	None	0	9.6	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	W3	Plaster	Tan	None	0	9.3	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	Vent	Metal	Tan	None	0	10.1	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	W4	Plaster	Tan	Cracking	4	9.9	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	Ceiling	Plaster	White	Flaking	12	10.4	Positive	
1	B629001-1	1	103C	Classroom 103 Coat Closet	Baseboard	Wood	Brown	Chipping	2	0.2	Negative	
1	B629001-1	1	103C	Classroom 103 Coat Closet	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	104	Classroom 104	W1	Plaster	Tan	Cracking	6	10.7	Positive	
1	B629001-1	1	104	Classroom 104	Door Frame	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	104	Classroom 104	Blackboard Ledge	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	W2	Plaster	Tan	Cracking	2	11.1	Positive	
1	B629001-1	1	104	Classroom 104	Bulletin Board	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Door Frame	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Window Frame	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	104	Classroom 104	W3	Plaster	Tan	Efflorescence	14	7.6	Positive	
1	B629001-1	1	104	Classroom 104	Window Sill	Wood	Brown	Chipping	2	0.3	Negative	
1	B629001-1	1	104	Classroom 104	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	104	Classroom 104	Radiator	Metal	Gray	Chipping	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	W4	Plaster	Tan	Cracking	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Blackboard Ledge	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	104	Classroom 104	Baseboard	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	104	Classroom 104	Ceiling	Plaster	White	Efflorescence	25	10.2	Positive	
1	B629001-1	1	104	Classroom 104	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	104A	Classroom 104 Coat Closet	W1	Plaster	Tan	Cracking	1	10	Positive	
1	B629001-1	1	104A	Classroom 104 Coat Closet	W2	Plaster	Tan	Cracking	1	8.2	Positive	
1	B629001-1	1	104A	Classroom 104 Coat Closet	W3	Plaster	Blue	None	0	9.4	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	1	104A	Classroom 104 Coat Closet	Vent	Metal	Tan	None	0	10.2	Positive	
1	B629001-1	1	104A	Classroom 104 Coat Closet	W4	Plaster	Tan	Cracking	2	7.6	Positive	
1	B629001-1	1	104A	Classroom 104 Coat Closet	Ceiling	Plaster	White	Cracking	4	9.1	Positive	
1	B629001-1	1	104A	Classroom 104 Coat Closet	Baseboard	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	104A	Classroom 104 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	W1	Plaster	Blue	Cracking	10	9.5	Positive	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	Conduit	Metal	Blue	Chipping	1	0.1	Negative	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	W2	Plaster	Blue	Cracking	1	7.3	Positive	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	W3	Plaster	Blue	Cracking	4	8.8	Positive	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	W4	Plaster	Blue	Cracking	12	9.2	Positive	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	Ceiling	Plaster	Blue	Cracking	2	9.3	Positive	
1	B629001-1	1	104B	Classroom 104 Closet on windows side	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104C	Classroom 104 Closet on Hallway side	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	W1	Plaster	Tan	Cracking	4	7.6	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	W2	Plaster	Tan	Cracking	1	7.2	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	W3	Plaster	Tan	Cracking	13	7	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	W4	Plaster	Tan	None	0	6.5	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	Ceiling	Plaster	Tan	Cracking	2	11.1	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	Duct	Metal	White	Flaking	3	6.7	Positive	
1	B629001-1	1	104D	Hallway Closet next to Classroom 104	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	105	Main Office	W1	Plaster	Tan	None	0	8.9	Positive	
1	B629001-1	1	105	Main Office	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	105	Main Office	Conduit	Metal	White	None	0	0	Negative	
1	B629001-1	1	105	Main Office	W2	Plaster	Tan	None	0	9.8	Positive	
1	B629001-1	1	105	Main Office	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	105	Main Office	Bulletin Board	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	1	105	Main Office	W3	Plaster	Tan	Efflorescence	6	8.2	Positive	
1	B629001-1	1	105	Main Office	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Window Sill	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Radiator	Metal	Gray	None	0	0.2	Negative	
1	B629001-1	1	105	Main Office	W4	Plaster	Tan	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105	Main Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	105	Main Office	Ceiling	Plaster	White	Cracking	35	10.1	Positive	
1	B629001-1	1	105	Main Office	Baseboard	Wood	Brown	Chipping	8	0.2	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	105	Main Office	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	105A	Principal's Office	W1	Plaster	Tan	None	0	9.2	Positive	
1	B629001-1	1	105A	Principal's Office	W1	Plaster	White	None	0	9.6	Positive	
1	B629001-1	1	105A	Principal's Office	Conduit	Metal	White	None	0	0	Negative	
1	B629001-1	1	105A	Principal's Office	Chair Rail	Wood	Brown	None	0	0	Negative	
1	B629001-1	1	105A	Principal's Office	Conduit	Vinyl	Tan	None	0	0.8	Positive	
1	B629001-1	1	105A	Principal's Office	W2	Plaster	Tan	Cracking	2	9.2	Positive	
1	B629001-1	1	105A	Principal's Office	W2	Plaster	White	Cracking	2	9.8	Positive	
1	B629001-1	1	105A	Principal's Office	Window Frame	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105A	Principal's Office	Window Sill	Wood	Brown	Cracking	1	0.2	Negative	
1	B629001-1	1	105A	Principal's Office	Window Apron	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105A	Principal's Office	Radiator	Metal	Silver	Chipping	3	9.2	Positive	
1	B629001-1	1	105A	Principal's Office	Pipe	Metal	Tan	None	0	9.4	Positive	
1	B629001-1	1	105A	Principal's Office	W3	Plaster	Tan	Chipping	2	9.7	Positive	
1	B629001-1	1	105A	Principal's Office	W3	Plaster	White	Flaking	2	10.1	Positive	
1	B629001-1	1	105A	Principal's Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	105A	Principal's Office	W4	Plaster	Tan	Chipping	2	9.4	Positive	
1	B629001-1	1	105A	Principal's Office	Moulding	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	105A	Principal's Office	Baseboard	Wood	Brown	Chipping	6	0.5	Negative	
1	B629001-1	1	105A	Principal's Office	Ceiling	Plaster	White	None	0	10	Positive	
1	B629001-1	1	105A	Principal's Office	Conduit	Metal	White	None	0	0	Negative	
1	B629001-1	1	105A	Principal's Office	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	105B	Principal's Office Restroom	W1	Plaster	Tan	None	0	9.2	Positive	
1	B629001-1	1	105B	Principal's Office Restroom	W2	Plaster	Tan	None	0	10.1	Positive	
1	B629001-1	1	105B	Principal's Office Restroom	W3	Plaster	Tan	Cracking	2	8	Positive	
1	B629001-1	1	105B	Principal's Office Restroom	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	105B	Principal's Office Restroom	W4	Plaster	Tan	None	0	10	Positive	
1	B629001-1	1	105B	Principal's Office Restroom	Baseboard	Wood	Brown	Chipping	6	0.5	Negative	
1	B629001-1	1	105B	Principal's Office Restroom	Ceiling	Plaster	White	None	0	9.1	Positive	
1	B629001-1	1	105B	Principal's Office Restroom	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	105C	Main Office Closet	W1	Plaster	White	Cracking	2	6.3	Positive	
1	B629001-1	1	105C	Main Office Closet	W2	Plaster	White	Cracking	2	6.7	Positive	
1	B629001-1	1	105C	Main Office Closet	W3	Plaster	White	Cracking	4	7.5	Positive	
1	B629001-1	1	105C	Main Office Closet	W4	Plaster	White	Cracking	15	4.1	Positive	
1	B629001-1	1	105C	Main Office Closet	Ceiling	Plaster	White	Cracking	30	10.1	Positive	
1	B629001-1	1	105C	Main Office Closet	Floor	Linoleum	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	105D	Principal's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	105D	Principal's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	105D	Principal's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	105D	Principal's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	105D	Principal's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	105D	Principal's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	106-1	Nurse's Office	W1	Plaster	Tan	Cracking	1	9	Positive	
1	B629001-1	1	106-1	Nurse's Office	Moulding	Wood	Brown	None	0	7.7	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	106-1	Nurse's Office	Door Frame	Wood	Brown	Chipping	1	9	Positive	
1	B629001-1	1	106-1	Nurse's Office	Door	Wood	Brown	Chipping	1	9.5	Positive	
1	B629001-1	1	106-1	Nurse's Office	Window Frame	Wood	Brown	None	0	8.7	Positive	
1	B629001-1	1	106-1	Nurse's Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	106-1	Nurse's Office	W2	Plaster	Tan	Cracking	2	8.8	Positive	
1	B629001-1	1	106-1	Nurse's Office	Moulding	Wood	Brown	None	0	7.4	Positive	
1	B629001-1	1	106-1	Nurse's Office	Chair Rail	Wood	Brown	None	0	8.5	Positive	
1	B629001-1	1	106-1	Nurse's Office	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	106-1	Nurse's Office	W3	Plaster	Tan	Flaking	3	8.6	Positive	
1	B629001-1	1	106-1	Nurse's Office	Moulding	Wood	Brown	None	0	7.6	Positive	
1	B629001-1	1	106-1	Nurse's Office	Window Frame	Wood	Brown	None	0	8.9	Positive	
1	B629001-1	1	106-1	Nurse's Office	Window Sill	Wood	Brown	Chipping	2	8.2	Positive	
1	B629001-1	1	106-1	Nurse's Office	Radiator	Metal	Black	None	0	0	Negative	
1	B629001-1	1	106-1	Nurse's Office	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	106-1	Nurse's Office	W4	Plaster	Tan	Flaking	4	8.9	Positive	
1	B629001-1	1	106-1	Nurse's Office	Moulding	Wood	Brown	None	0	6.9	Positive	
1	B629001-1	1	106-1	Nurse's Office	Bulletin Board	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	106-1	Nurse's Office	Cabinet	Wood	White	Chipping	1	9.3	Positive	
1	B629001-1	1	106-1	Nurse's Office	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	106-1	Nurse's Office	Door	Wood	Brown	Chipping	1	9.2	Positive	
1	B629001-1	1	106-1	Nurse's Office	Door Frame	Wood	Brown	Chipping	1	9.5	Positive	
1	B629001-1	1	106-1	Nurse's Office	Ceiling	Plaster	White	None	0	10.4	Positive	
1	B629001-1	1	106-1	Nurse's Office	Baseboard	Wood	Brown	Chipping	10	9.3	Positive	
1	B629001-1	1	106-1	Nurse's Office	Floor	9" x 9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	106A	Nurse's Office Restroom	W1	Plaster	Green	None	0	11.4	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Door	Wood	White	Chipping	1	9.3	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Door Frame	Wood	White	Chipping	1	9.4	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	W2	Plaster	Green	Cracking	24	11.1	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	W3	Plaster	Green	None	0	10.2	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Window Frame	Wood	White	None	0	9.4	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Window Frame	Wood	White	None	0	9.8	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Stall Divider	Wood	White	Chipping	2	8.7	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	W4	Plaster	Green	Cracking	100	10.8	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Ceiling	Plaster	White	Flaking	12	9.2	Positive	
1	B629001-1	1	106A	Nurse's Office Restroom	Floor	9" x 9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	107-1	Classroom 107	W1	Plaster	Tan	Chipping	1	11.1	Positive	
1	B629001-1	1	107-1	Classroom 107	W1	Plaster	White	None	0	10.7	Positive	
1	B629001-1	1	107-1	Classroom 107	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	107-1	Classroom 107	W2	Plaster	Tan	None	0	12.3	Positive	
1	B629001-1	1	107-1	Classroom 107	W2	Plaster	White	None	0	11	Positive	
1	B629001-1	1	107-1	Classroom 107	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	107-1	Classroom 107	W3	Plaster	Tan	Flaking	12	11.3	Positive	
1	B629001-1	1	107-1	Classroom 107	W3	Plaster	White	Cracking	1	10.8	Positive	
1	B629001-1	1	107-1	Classroom 107	Conduit	Metal	Tan	None	0	0.1	Negative	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	107-1	Classroom 107	Radiator	Metal	Silver	Flaking	2	6.7	Positive	
1	B629001-1	1	107-1	Classroom 107	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	107-1	Classroom 107	W4	Plaster	Tan	Cracking	2	11.4	Positive	
1	B629001-1	1	107-1	Classroom 107	W4	Plaster	White	None	0	11.1	Positive	
1	B629001-1	1	107-1	Classroom 107	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	107-1	Classroom 107	Beam	Concrete	White	Flaking	4	0.1	Negative	
1	B629001-1	1	107-1	Classroom 107	Ceiling	Plaster	White	None	0	12.1	Positive	
1	B629001-1	1	107-1	Classroom 107	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	107-1	Classroom 107	Baseboard	Wood	Brown	Chipping	2	0.1	Negative	
1	B629001-1	1	107A	Classroom 107 Coat Closet	W1	Plaster	Tan	Chipping	20	5.9	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	107A	Classroom 107 Coat Closet	W2	Plaster	Tan	Efflorescence	25	9.1	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	Vent	Metal	Tan	Chipping	1	10.7	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	W3	Plaster	Tan	Efflorescence	100	1.9	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	Coat Rack	Wood	White	None	0	0.1	Negative	
1	B629001-1	1	107A	Classroom 107 Coat Closet	W4	Plaster	Tan	Efflorescence	25	4.6	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	Ceiling	Plaster	Tan	Efflorescence	60	9.4	Positive	
1	B629001-1	1	107A	Classroom 107 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	107B	Classroom 107 Closet	W1	Plaster	Green	Cracking	6	7.1	Positive	
1	B629001-1	1	107B	Classroom 107 Closet	W2	Plaster	Green	None	0	8.7	Positive	
1	B629001-1	1	107B	Classroom 107 Closet	W3	Plaster	Green	Efflorescence	13	8.8	Positive	
1	B629001-1	1	107B	Classroom 107 Closet	W4	Plaster	Green	Efflorescence	10	10.2	Positive	
1	B629001-1	1	107B	Classroom 107 Closet	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	107B	Classroom 107 Closet	Ceiling	Plaster	Green	Cracking	1	9.3	Positive	
1	B629001-1	1	107B	Classroom 107 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	108-1	Teacher's Lounge	W1	Plaster	Tan	Cracking	6	9.8	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Conduit	Metal	Tan	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	W2	Plaster	Tan	Flaking	7	10.4	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	Chair Rail	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Bulletin Board	Wood	Brown	None	0	6.4	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Moulding	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	W3	Plaster	Tan	Efflorescence	10	9.4	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	Window Frame	Wood	Brown	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Window Sill	Wood	Brown	Cracking	1	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Radiator	Metal	Silver	Cracking	2	4.3	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	Pipe	Metal	Brown	None	0	0	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	W4	Plaster	Tan	Cracking	2	10	Positive	
1	B629001-1	1	108-1	Teacher's Lounge	W4	Sheetrock	Tan	None	0	0	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Door Frame	Metal	Brown	None	0	0.1	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Moulding	Wood	Tan	None	0	0	Negative	
1	B629001-1	1	108-1	Teacher's Lounge	Conduit	Metal	Tan	None	0	0.1	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	1	108-1	Teacher's Lounge	Conduit	Vinyl	Tan	None	0	0	Negative
1	B629001-1	1	108-1	Teacher's Lounge	Beam	Concrete	White	None	0	0.1	Negative
1	B629001-1	1	108-1	Teacher's Lounge	Ceiling	Plaster	White	Flaking	20	10.7	Positive
1	B629001-1	1	108-1	Teacher's Lounge	Baseboard	Wood	Brown	Chipping	0	0.1	Negative
1	B629001-1	1	108-1	Teacher's Lounge	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	W1	Plaster	Tan	None	0	10.1	Positive
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	W2	Plaster	Tan	Flaking	6	9.3	Positive
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	Conduit	Metal	Tan	None	0	9.4	Positive
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	W3	Plaster	Tan	Flaking	4	0	Negative
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	W4	Plaster	Tan	Cracking	1	9.5	Positive
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	Ceiling	Plaster	Tan	None	0	10.1	Positive
1	B629001-1	1	108A	Custodial Closet next to Teacher's Lounge	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	108B	Teacher's Lounge Kitchen	W1	Plaster	Tan	Cracking	1	9.2	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	W2	Plaster	Tan	Cracking	12	10.6	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Conduit	Metal	Tan	None	0	0.1	Negative
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Pipe	Metal	Tan	Cracking	3	9.7	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	W3	Plaster	Tan	Cracking	2	10	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Sink	Porcelain	White	None	0	4	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Sink	Metal	Brown	None	0	0.7	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Sink Legs	Metal	Brown	Chipping	1	0.2	Negative
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Conduit	Metal	Tan	None	0	0.1	Negative
1	B629001-1	1	108B	Teacher's Lounge Kitchen	W4	Plaster	Tan	None	0	9.3	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Cabinet	Wood	Tan	None	0	0.1	Negative
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Vent	Metal	White	None	0	10.3	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Ceiling	Plaster	White	None	0	9.4	Positive
1	B629001-1	1	108B	Teacher's Lounge Kitchen	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	1	108C	Teacher's Lounge Server Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	108C	Teacher's Lounge Server Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	108C	Teacher's Lounge Server Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	108C	Teacher's Lounge Server Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	108C	Teacher's Lounge Server Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	108C	Teacher's Lounge Server Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	1	109-1	Library	W1	Plaster	Tan	None	0	11.1	Positive
1	B629001-1	1	109-1	Library	Conduit	Metal	White	None	0	0	Negative
1	B629001-1	1	109-1	Library	Conduit	Vinyl	Tan	None	0	0	Negative
1	B629001-1	1	109-1	Library	Shelving	Wood	White	None	0	0.1	Negative
1	B629001-1	1	109-1	Library	W2	Plaster	Tan	None	0	9.8	Positive
1	B629001-1	1	109-1	Library	Conduit	Metal	White	None	0	0	Negative
1	B629001-1	1	109-1	Library	Conduit	Vinyl	Tan	None	0	0	Negative
1	B629001-1	1	109-1	Library	W3	Plaster	Tan	None	0	11.1	Positive
1	B629001-1	1	109-1	Library	Window Sill	Wood	White	None	0	0	Negative
1	B629001-1	1	109-1	Library	Radiator	Metal	Black	None	0	0.4	Negative
1	B629001-1	1	109-1	Library	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	1	109-1	Library	W4	Plaster	White	None	0	11.2	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	1	109-1	Library	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	1	109-1	Library	Shelving	Wood	White	None	0	0	Negative	
1	B629001-1	1	109-1	Library	Ceiling	Plaster	White	Flaking	200	10.9	Positive	
1	B629001-1	1	109-1	Library	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	109A	Library Coat Closet	W1	Plaster	White	None	0	7.3	Positive	
1	B629001-1	1	109A	Library Coat Closet	W2	Plaster	White	Cracking	2	8.3	Positive	
1	B629001-1	1	109A	Library Coat Closet	Vent	Metal	White	None	0	5.5	Positive	
1	B629001-1	1	109A	Library Coat Closet	W3	Plaster	White	None	0	10.4	Positive	
1	B629001-1	1	109A	Library Coat Closet	W4	Plaster	White	Flaking	14	10.2	Positive	
1	B629001-1	1	109A	Library Coat Closet	Pipe	Metal	White	Flaking	1	7.9	Positive	
1	B629001-1	1	109A	Library Coat Closet	Radiator Shield	Metal	Silver	None	0	5.2	Positive	
1	B629001-1	1	109A	Library Coat Closet	Radiator	Metal	Silver	None	0	0.4	Negative	
1	B629001-1	1	109A	Library Coat Closet	Ceiling	Plaster	White	None	0	10.5	Positive	
1	B629001-1	1	109A	Library Coat Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	109B	Library Server Closet	W1	Plaster	White	None	0	10	Positive	
1	B629001-1	1	109B	Library Server Closet	W2	Plaster	White	None	0	10.3	Positive	
1	B629001-1	1	109B	Library Server Closet	Vent	Metal	White	None	0	9.8	Positive	
1	B629001-1	1	109B	Library Server Closet	Server Box	Metal	Black	None	0	0	Negative	
1	B629001-1	1	109B	Library Server Closet	W3	Plaster	White	Cracking	2	1.7	Positive	
1	B629001-1	1	109B	Library Server Closet	Shelving	Metal	Gray	None	0	0	Negative	
1	B629001-1	1	109B	Library Server Closet	W4	Plaster	White	Cracking	5	9.8	Positive	
1	B629001-1	1	109B	Library Server Closet	Ceiling	Plaster	White	None	0	8.7	Positive	
1	B629001-1	1	109B	Library Server Closet	Conduit	Metal	White	None	0	0	Negative	
1	B629001-1	1	109B	Library Server Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	W1	Plaster	White	Chipping	1	7.9	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	W2	Plaster	White	Chipping	1	8.6	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	W3	Plaster	White	Cracking	4	9	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	Pipe	Metal	White	Chipping	1	7.7	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	W4	Plaster	White	Chipping	1	7.7	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	Ceiling	Plaster	White	Chipping	1	10.1	Positive	
1	B629001-1	1	109C	Library Closet on Girl's Restroom side	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	109D	Library Closet on Fire Tower side	W1	Plaster	White	None	0	10.4	Positive	
1	B629001-1	1	109D	Library Closet on Fire Tower side	W2	Plaster	White	None	0	8.1	Positive	
1	B629001-1	1	109D	Library Closet on Fire Tower side	W3	Plaster	White	None	0	10.1	Positive	
1	B629001-1	1	109D	Library Closet on Fire Tower side	W4	Plaster	White	None	0	9.5	Positive	
1	B629001-1	1	109D	Library Closet on Fire Tower side	Ceiling	Plaster	White	None	0	9.7	Positive	
1	B629001-1	1	109D	Library Closet on Fire Tower side	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	1	110-1	Hallway Closet next to Fire Tower	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	H201	Hallway from Boy's Restroom to Girl's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	2	H211	Hallway from Classroom 209 to Fire Tower	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	W1	Plaster	Tan	Flaking	3	3.3	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Cove Base	Plaster	Tan	Flaking	3	0.33	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	W2	Plaster	Tan	Alligatoring	10	0	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Radiator Cover	Metal	Brown	Chipping	5	0	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Radiator	Metal	Silver	Flaking	15	0.62	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	W3	Plaster	Tan	None	0	3.96	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Newel Post	Metal	Blue	Friction	3	7.7	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Stair Tread	Metal	Gray	Chipping	1	1.78	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Stair Stringer	Metal	Gray	None	0	0.55	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Stair Riser	Metal	Gray	Friction	1	0.38	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Baluster	Metal	Blue	Chipping	1	5.9	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Handrail Support	Metal	Blue	Chipping	2	0.9	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Conduit	Metal	Tan	None	0	0.3	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Door	Metal	Blue	Chipping	3	0.47	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Door Frame	Metal	Blue	Chipping	1	0.5	Negative	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Ceiling	Concrete	White	None	0	10	Positive	
1	B629001-1	2	S201	Stairwell near Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	W1	Plaster	Tan	None	0	9.98	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Door	Metal	Blue	Chipping	5	0.3	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Door Frame	Metal	Blue	Chipping	2	0.5	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Transom Panel	Metal	Blue	None	0	0.33	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	W2	Plaster	Tan	Chipping	1	10	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Cove Base	Concrete	Gray	Friction	1	0.46	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	W3	Plaster	Tan	None	0	9.85	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Radiator	Metal	Silver	Flaking	20	2.87	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	W4	Plaster	Tan	None	0	2.08	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Ceiling	Concrete	White	None	0	8.47	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Stair Stringer	Concrete	Gray	None	0	0.8	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Newel Post	Metal	Blue	Friction	2	8.37	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Stair Tread	Concrete	Gray	Friction	1	0.3	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Stair Riser	Concrete	Gray	Friction	1	0.26	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Stair Stringer	Metal	Blue	Friction	3	5.3	Positive	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Conduit	Metal	Tan	None	0	0.5	Negative	
1	B629001-1	2	S202	Stairwell opposite Classroom 209	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	W1	Brick	White	Chipping	100	4.4	Positive	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Window Frame	Metal	Silver	Chipping	3	3.73	Positive	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Door Frame	Metal	Brown	None	0	0.3	Negative	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Door	Metal	Brown	None	0	0	Negative	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Ceiling	Concrete	White	None	0	5.1	Positive	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Cove Base	Concrete	Gray	Flaking	20	0.6	Negative	
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Handrail	Metal	Gray	Flaking	30	0.78	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Wall Divider	Metal	Gray	Alligatoring	220	1.55	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Stair Stringer	Concrete	Gray	Flaking	100	1.25	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Stair Riser	Metal	Gray	Flaking	100	2.3	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Stair Tread	Metal	Gray	Flaking	100	2.45	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	W2	Brick	White	Flaking	40	4.98	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	W3	Brick	White	Flaking	350	5.19	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	W4	Brick	White	Flaking	275	5.09	Positive
1	B629001-1	2	S203	Fire Tower next to Classroom 208	Ceiling	Concrete	White	Flaking	250	5.42	Positive
1	B629001-1	2	203	Classroom 203	W1	Plaster	Tan	None	0	10.4	Positive
1	B629001-1	2	203	Classroom 203	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	2	203	Classroom 203	Conduit 203	Vinyl	Tan	None	0	1.3	Positive
1	B629001-1	2	203	Classroom 203	W2	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	203	Classroom 203	W3	Plaster	Tan	Flaking	4	9.7	Positive
1	B629001-1	2	203	Classroom 203	Window Sill	Wood	Brown	Chipping	2	0.2	Negative
1	B629001-1	2	203	Classroom 203	Radiator	Metal	Silver	Chipping	1	2	Positive
1	B629001-1	2	203	Classroom 203	W4	Plaster	Tan	Cracking	2	8.9	Positive
1	B629001-1	2	203	Classroom 203	Conduit	Vinyl	Tan	None	0	0	Negative
1	B629001-1	2	203	Classroom 203	Conduit	Metal	Tan	None	0	0.2	Negative
1	B629001-1	2	203	Classroom 203	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	203	Classroom 203	Ceiling	Plaster	White	Flaking	60	10.8	Positive
1	B629001-1	2	203	Classroom 203	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	203A	Classroom 203 Coat Closet	W1	Plaster	Tan	Flaking	4	10.9	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	W2	Plaster	Tan	Flaking	8	1.8	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	Pipe	Metal	White	Flaking	10	0.1	Negative
1	B629001-1	2	203A	Classroom 203 Coat Closet	Radiator	Metal	Silver	Chipping	2	2	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	Radiator Shield	Metal	Silver	Flaking	1	4.3	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	W3	Plaster	Tan	None	0	0	Negative
1	B629001-1	2	203A	Classroom 203 Coat Closet	Conduit 203 Coat Closet	Metal	White	Flaking	10	0.1	Negative
1	B629001-1	2	203A	Classroom 203 Coat Closet	W4	Plaster	Tan	Cracking	2	8.9	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	Vent	Metal	Tan	None	0	10.3	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	Ceiling	Plaster	Tan	None	0	11.1	Positive
1	B629001-1	2	203A	Classroom 203 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	203B	Classroom 203 Closet	W1	Plaster	Tan	Flaking	8	10.4	Positive
1	B629001-1	2	203B	Classroom 203 Closet	W2	Plaster	Tan	Flaking	5	10.1	Positive
1	B629001-1	2	203B	Classroom 203 Closet	W3	Plaster	Tan	Flaking	24	10.2	Positive
1	B629001-1	2	203B	Classroom 203 Closet	W4	Plaster	Tan	Flaking	20	8.2	Positive
1	B629001-1	2	203B	Classroom 203 Closet	Ceiling	Plaster	Tan	Efflorescence	4	9.7	Positive
1	B629001-1	2	203B	Classroom 203 Closet	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	W1	Plaster	Tan	Flaking	8	5.3	Positive
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	W2	Plaster	Tan	Cracking	3	7.8	Positive
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	W3	Plaster	Tan	Flaking	14	6.2	Positive
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	W4	Plaster	Tan	Flaking	10	5.9	Positive
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	Ceiling	Plaster	Tan	Cracking	4	6.1	Positive
1	B629001-1	2	203C	Hallway Closet near Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	W1	Plaster	Tan	Flaking	8	10.3	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	W2	Plaster	Tan	Flaking	5	10.1	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	W3	Plaster	Tan	Flaking	24	10.2	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	Shelving	Wood	White	Chipping	1	4.2	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	W4	Plaster	Tan	Flaking	20	7.8	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	Ceiling	Plaster	Tan	Efflorescence	4	9.7	Positive
1	B629001-1	2	203D	Custodial Closet near Boy's Restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	204	Classroom 204	W1	Plaster	White	Chipping	3	11.3	Positive
1	B629001-1	2	204	Classroom 204	W2	Sheetrock	Blue	None	0	0	Negative
1	B629001-1	2	204	Classroom 204	W3	Plaster	White	Flaking	30	11	Positive
1	B629001-1	2	204	Classroom 204	Radiator	Metal	Silver	Chipping	2	6.8	Positive
1	B629001-1	2	204	Classroom 204	W4	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	204	Classroom 204	Ceiling	Plaster	White	Flaking	8	9.9	Positive
1	B629001-1	2	204	Classroom 204	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	204A	Classroom 204 Coat Closet	W1	Plaster	White	None	0	6.8	Positive
1	B629001-1	2	204A	Classroom 204 Coat Closet	W2	Plaster	White	None	0	9.5	Positive
1	B629001-1	2	204A	Classroom 204 Coat Closet	W3	Plaster	White	None	0	8.5	Positive
1	B629001-1	2	204	Classroom 204	Vent	Metal	White	None	0	11.1	Positive
1	B629001-1	2	204A	Classroom 204 Coat Closet	W4	Plaster	White	None	0	5	Positive
1	B629001-1	2	204A	Classroom 204 Coat Closet	Ceiling	Plaster	White	None	0	10.6	Positive
1	B629001-1	2	204A	Classroom 204 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	204B	Classroom 204 Closet	W1	Plaster	White	Cracking	1	8.1	Positive
1	B629001-1	2	204B	Classroom 204 Closet	W2	Plaster	White	None	0	7.3	Positive
1	B629001-1	2	204B	Classroom 204 Closet	W3	Plaster	White	None	0	8.1	Positive
1	B629001-1	2	204B	Classroom 204 Closet	Radiator	Metal	Silver	Chipping	5	4.2	Positive
1	B629001-1	2	204B	Classroom 204 Closet	W4	Plaster	White	Cracking	1	7.2	Positive
1	B629001-1	2	204B	Classroom 204 Closet	Pipe	Metal	White	Chipping	1	11.7	Positive
1	B629001-1	2	204B	Classroom 204 Closet	Ceiling	Plaster	White	None	0	8	Positive
1	B629001-1	2	204B	Classroom 204 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	205	Classroom 205	W1	Plaster	White	Flaking	6	11.2	Positive
1	B629001-1	2	205	Classroom 205	W2	Wood	White	None	0	0.2	Negative
1	B629001-1	2	205	Classroom 205	W3	Plaster	White	Flaking	40	10.8	Positive
1	B629001-1	2	205	Classroom 205	Radiator	Metal	Silver	Chipping	1	0	Negative
1	B629001-1	2	205	Classroom 205	Radiator	Metal	Silver	None	0	0	Negative
1	B629001-1	2	205	Classroom 205	W4	Sheetrock	White	Chipping	1	0	Negative
1	B629001-1	2	205	Classroom 205	Ceiling	Plaster	White	Flaking	12	11.4	Positive
1	B629001-1	2	205	Classroom 205	Beam	Concrete	White	None	0	9.2	Positive
1	B629001-1	2	205	Classroom 205	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	205A	Classroom 205 Coat Closet	W1	Plaster	White	None	0	5.1	Positive
1	B629001-1	2	205A	Classroom 205 Coat Closet	W2	Plaster	White	Chipping	3	10.2	Positive
1	B629001-1	2	205A	Classroom 205 Coat Closet	W3	Plaster	White	Flaking	1	10.7	Positive
1	B629001-1	2	205A	Classroom 205 Coat Closet	W4	Plaster	White	Chipping	1	6.7	Positive
1	B629001-1	2	205A	Classroom 205 Coat Closet	Vent	Metal	White	None	0	11.7	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	2	205A	Classroom 205 Coat Closet	Ceiling	Plaster	White	None	0	9.9	Positive	
1	B629001-1	2	205A	Classroom 205 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	205B	Classroom 205 Closet	W1	Plaster	White	Cracking	1	6.1	Positive	
1	B629001-1	2	205B	Classroom 205 Closet	W2	Plaster	White	None	0	10.3	Positive	
1	B629001-1	2	205B	Classroom 205 Closet	W3	Plaster	White	None	0	10.2	Positive	
1	B629001-1	2	205B	Classroom 205 Closet	W4	Plaster	White	Cracking	2	7.9	Positive	
1	B629001-1	2	205B	Classroom 205 Closet	Ceiling	Plaster	White	None	0	6.5	Positive	
1	B629001-1	2	205B	Classroom 205 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	206	Classroom 206	W1	Plaster	White	Chipping	2	11.1	Positive	
1	B629001-1	2	206	Classroom 206	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	2	206	Classroom 206	W2	Plaster	White	Cracking	2	11.3	Positive	
1	B629001-1	2	206	Classroom 206	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	2	206	Classroom 206	W3	Plaster	White	Flaking	12	10.7	Positive	
1	B629001-1	2	206	Classroom 206	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	2	206	Classroom 206	Radiator	Metal	Silver	Chipping	4	5.5	Positive	
1	B629001-1	2	206	Classroom 206	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	206	Classroom 206	Ceiling	Plaster	White	Flaking	25	10.7	Positive	
1	B629001-1	2	206	Classroom 206	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	206A	Classroom 206 Coat Closet	W1	Plaster	White	None	0	5.4	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	W2	Plaster	White	Chipping	1	9.7	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	W3	Plaster	White	None	0	9.4	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	Vent	Metal	White	None	0	10.5	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	W4	Plaster	White	None	0	10.7	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	Ceiling	Plaster	White	None	0	10.6	Positive	
1	B629001-1	2	206A	Classroom 206 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	206B	Classroom 206 Closet	W1	Plaster	White	Cracking	2	8.6	Positive	
1	B629001-1	2	206B	Classroom 206 Closet	W2	Plaster	White	None	0	9.1	Positive	
1	B629001-1	2	206B	Classroom 206 Closet	W3	Plaster	White	None	0	7.4	Positive	
1	B629001-1	2	206B	Classroom 206 Closet	W4	Plaster	White	Cracking	12	7.5	Positive	
1	B629001-1	2	206B	Classroom 206 Closet	Ceiling	Plaster	White	None	0	6.8	Positive	
1	B629001-1	2	206B	Classroom 206 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	206C	Pipe Shaft next to Classroom 206	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	2	207	Classroom 207	W1	Plaster	Tan	Flaking	5	11.1	Positive	
1	B629001-1	2	207	Classroom 207	W2	Plaster	Tan	Flaking	2	11.4	Positive	
1	B629001-1	2	207	Classroom 207	W3	Plaster	Tan	Flaking	25	11.5	Positive	
1	B629001-1	2	207	Classroom 207	Radiator	Metal	Gray	None	0	0	Negative	
1	B629001-1	2	207	Classroom 207	W4	Plaster	Tan	Flaking	3	10.5	Positive	
1	B629001-1	2	207	Classroom 207	Ceiling	Plaster	White	Flaking	30	11.2	Positive	
1	B629001-1	2	207	Classroom 207	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	2	207A	Classroom 207 Coat Closet	W1	Plaster	White	Chipping	1	5.6	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	W2	Plaster	White	Flaking	4	9.5	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Vent	Metal	White	Cracking	1	10.3	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	W3	Plaster	White	Flaking	15	0.3	Negative	
1	B629001-1	2	207A	Classroom 207 Coat Closet	W4	Plaster	White	Efflorescence	15	10.1	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Radiator	Metal	Silver	Chipping	5	2.1	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Radiator Shield	Metal	Silver	Chipping	1	6.2	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Pipe	Metal	White	Chipping	1	9.5	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Ceiling	Plaster	White	Flaking	3	10.5	Positive	
1	B629001-1	2	207A	Classroom 207 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	207B	Classroom 207 Closet	W1	Plaster	White	Cracking	2	1.4	Positive	
1	B629001-1	2	207B	Classroom 207 Closet	W2	Plaster	White	None	0	9.5	Positive	
1	B629001-1	2	207B	Classroom 207 Closet	W3	Plaster	White	None	0	10.2	Positive	
1	B629001-1	2	207B	Classroom 207 Closet	W4	Plaster	White	None	0	7	Positive	
1	B629001-1	2	207B	Classroom 207 Closet	Ceiling	Plaster	White	None	0	8.2	Positive	
1	B629001-1	2	207B	Classroom 207 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	209	Classroom 209	W1	Plaster	Tan	Chipping	1	11	Positive	
1	B629001-1	2	209	Classroom 209	Blackboard Ledge	Wood	Black	None	0	0	Negative	
1	B629001-1	2	209	Classroom 209	W2	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	209	Classroom 209	W3	Plaster	Tan	Efflorescence	8	9.3	Positive	
1	B629001-1	2	209	Classroom 209	Window Sill	Wood	Brown	Chipping	1	0.1	Negative	
1	B629001-1	2	209	Classroom 209	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	2	209	Classroom 209	Radiator	Metal	Silver	Chipping	1	6	Positive	
1	B629001-1	2	209	Classroom 209	W4	Plaster	Tan	None	0	10.9	Positive	
1	B629001-1	2	209	Classroom 209	Baseboard	Wood	Brown	None	0	0.2	Negative	
1	B629001-1	2	209	Classroom 209	Ceiling	Plaster	White	Flaking	1	9.4	Positive	
1	B629001-1	2	209	Classroom 209	Beam	Concrete	White	None	0	0	Negative	
1	B629001-1	2	209	Classroom 209	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	209A	Classroom 209 Coat Closet	W1	Plaster	Tan	Chipping	1	10.1	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	W2	Plaster	Tan	Flaking	2	10.1	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	Vent	Metal	Tan	None	0	10.8	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	W3	Plaster	Tan	Flaking	1	11.6	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	W4	Plaster	Tan	None	0	8.4	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	Baseboard	Wood	Brown	None	0	0.2	Negative	
1	B629001-1	2	209A	Classroom 209 Coat Closet	Ceiling	Plaster	White	Cracking	3	9.4	Positive	
1	B629001-1	2	209A	Classroom 209 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	209B	Classroom 209 Closet	W1	Plaster	White	None	0	7	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	W2	Plaster	White	None	0	8.8	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	W3	Plaster	White	None	0	4.8	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	W4	Plaster	White	None	0	7.5	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	Conduit	Metal	Tan	None	0	2.4	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	Ceiling	Plaster	White	None	0	8.1	Positive	
1	B629001-1	2	209B	Classroom 209 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	2	210A	Classroom 210 Coat Closet	W1	Plaster	Tan	Chipping	1	5.5	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	W2	Plaster	Tan	Cracking	3	8	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Vent	Metal	Tan	None	0	10.6	Positive
1	B629001-1	2	209B	Classroom 209 Closet	Vent	Metal	White	None	0	8.2	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	W3	Plaster	Tan	Flaking	5	10.1	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	W4	Plaster	Tan	Flaking	25	10.2	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Pipe	Metal	Tan	Chipping	1	9.5	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Pipe	Metal	Tan	None	0	10.8	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Radiator	Metal	Silver	Chipping	1	8.7	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Radiator Shield	Metal	Silver	Chipping	1	5.4	Positive
1	B629001-1	2	209B	Classroom 209 Closet	Pipe	Metal	White	Flaking	2	9.5	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Ceiling	Plaster	White	Cracking	2	10.2	Positive
1	B629001-1	2	210A	Classroom 210 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	210B	Classroom 210 Closet	W1	Plaster	White	None	0	6.5	Positive
1	B629001-1	2	210B	Classroom 210 Closet	W2	Plaster	White	Chipping	2	9.1	Positive
1	B629001-1	2	210B	Classroom 210 Closet	W3	Plaster	White	None	0	8.1	Positive
1	B629001-1	2	210B	Classroom 210 Closet	W4	Plaster	White	None	0	6.8	Positive
1	B629001-1	2	210B	Classroom 210 Closet	Ceiling	Plaster	White	None	0	7.8	Positive
1	B629001-1	2	210B	Classroom 210 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	W1	Plaster	White	Flaking	50	11.6	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	W2	Plaster	White	Flaking	20	11.2	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	Pipe	Metal	White	Chipping	1	8.7	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	W3	Plaster	White	Flaking	30	10.4	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	W4	Plaster	White	Flaking	25	9.6	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	Ceiling	Plaster	White	Flaking	50	9.6	Positive
1	B629001-1	2	212G	Hallway Closet across from Women's Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	W1	Plaster	White	None	0	5.7	Positive
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	W2	Plaster	White	None	0	5.2	Positive
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	W3	Plaster	White	None	6	8.2	Positive
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	W4	Plaster	White	None	0	7.5	Positive
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	Ceiling	Plaster	White	None	0	8.2	Positive
1	B629001-1	2	213B	Hallway Closet next to Women's Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	213A	Women's Lounge	W1	Plaster	White	Flaking	12	11.5	Positive
1	B629001-1	2	213A	Women's Lounge	Chair Rail	Wood	Brown	Friction	1	0.1	Negative
1	B629001-1	2	213A	Women's Lounge	W2	Plaster	White	Flaking	40	11.5	Positive
1	B629001-1	2	213A	Women's Lounge	Radiator Shield	Metal	Silver	Flaking	3	0.1	Negative
1	B629001-1	2	213A	Women's Lounge	Radiator	Metal	Silver	Flaking	4	3.4	Positive
1	B629001-1	2	213A	Women's Lounge	W3	Plaster	White	Flaking	6	7.3	Positive
1	B629001-1	2	213A	Women's Lounge	W4	Plaster	White	Flaking	15	11.8	Positive
1	B629001-1	2	213A	Women's Lounge	Ceiling	Plaster	White	Flaking	18	10.3	Positive
1	B629001-1	2	213A	Women's Lounge	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	2	213A1	Women's Lounge Restroom	W1	Plaster	White	Flaking	16	5.9	Positive
1	B629001-1	2	213A1	Women's Lounge Restroom	W2	Plaster	White	Flaking	40	8.5	Positive
1	B629001-1	2	213A1	Women's Lounge Restroom	W3	Plaster	White	Flaking	25	6.7	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	2	213A1	Women's Lounge Restroom	W4	Plaster	White	Flaking	8	8.6	Positive	
1	B629001-1	2	213A1	Women's Lounge Restroom	Ceiling	Plaster	White	Flaking	4	7.8	Positive	
1	B629001-1	2	213A1	Women's Lounge Restroom	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	W1	Plaster	White	Cracking	1	10.1	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	W2	Plaster	White	Chipping	2	10.2	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	W3	Plaster	White	Flaking	12	10.3	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	Radiator Shield	Metal	Silver	Chipping	1	0.9	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	Radiator	Metal	Silver	Chipping	4	2.4	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	Pipe	Metal	White	Chipping	1	10.9	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	W4	Plaster	White	Flaking	25	10.9	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	W4	Sheetrock	White	Chipping	1	0	Negative	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	Ceiling	Plaster	White	Flaking	10	8.2	Positive	
1	B629001-1	2	214-1	Storeroom next to Classroom 203	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214A	Staff Restroom off Storeroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214A	Staff Restroom off Storeroom	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214A	Staff Restroom off Storeroom	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214A	Staff Restroom off Storeroom	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	2	214A	Staff Restroom off Storeroom	Ceiling	Plaster	White	None	0	9.5	Positive	
1	B629001-1	2	214A	Staff Restroom off Storeroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W1	Brick	White	None	0	6.1	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W1	Concrete	White	Flaking	2	3.8	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W2	Brick	White	None	0	6.5	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W2	Concrete	White	Flaking	6	6.7	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	Door Frame	Metal	Brown	Chipping	5	0	Negative	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	Door	Metal	Brown	None	0	0	Negative	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W4	Brick	White	None	0	5.3	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	W4	Concrete	White	Flaking	5	6.2	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	Ceiling	Concrete	White	Flaking	2	5.3	Positive	
1	B629001-1	3	S303	Fire Stairwell near Closet 311	Floor	Concrete	Brown	None	0	0	Negative	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	W1	Plaster	White	Efflorescence	10	10.6	Positive	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Radiator	Metal	Silver	Flaking	4	0	Negative	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Radiator Shield	Metal	Silver	Chipping	1	0.1	Negative	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Radiator	Metal	Silver	Flaking	2	0.1	Negative	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Radiator Shield	Metal	Silver	None	0	0	Negative	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	W2	Plaster	White	None	0	10.4	Positive	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	W3	Plaster	White	None	0	9.6	Positive	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Ceiling	Plaster	White	None	0	9.3	Positive	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	H311	Hallway from Art Room 309 to Closet 311	Cove Base	Concrete	Gray	None	0	0.1	Negative	
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	W1	Plaster	White	None	0	10.3	Positive	
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Radiator	Metal	Silver	Chipping	2	0	Negative	
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Radiator Shield	Metal	Silver	Chipping	1	0	Negative	
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Radiator	Metal	Silver	Chipping	2	0.1	Negative	
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Radiator Shield	Metal	Silver	Chipping	1	0	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	W2	Plaster	White	Chipping	1	10.5	Positive
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	W3	Plaster	White	Flaking	1	10.1	Positive
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	W4	Plaster	White	Chipping	1	10.3	Positive
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Ceiling	Plaster	White	Cracking	1	9.1	Positive
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	H301	Hallway from Girls Room to Boys Room	Cove Base	Concrete	Gray	None	0	0.1	Negative
1	B629001-1	3	303	Classroom 303	W1	Plaster	White	Chipping	5	10.5	Positive
1	B629001-1	3	303	Classroom 303	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	3	303	Classroom 303	Conduit	Vinyl	Tan	None	0	2.2	Positive
1	B629001-1	3	303	Classroom 303	W2	Sheetrock	White	None	0	0	Negative
1	B629001-1	3	303	Classroom 303	Door Frame	Metal	Tan	Chipping	1	0.1	Negative
1	B629001-1	3	303	Classroom 303	W3	Plaster	White	Cracking	15	10.5	Positive
1	B629001-1	3	303	Classroom 303	Radiator	Metal	Silver	Chipping	2	3	Positive
1	B629001-1	3	303	Classroom 303	Radiator Shield	Metal	Silver	None	0	2.3	Positive
1	B629001-1	3	303	Classroom 303	Window Sill	Wood	White	None	0	0	Negative
1	B629001-1	3	303	Classroom 303	W4	Plaster	White	Cracking	1	9.3	Positive
1	B629001-1	3	303	Classroom 303	W4	Plaster	Blue	None	0	5.8	Positive
1	B629001-1	3	303	Classroom 303	Conduit	Metal	Blue	None	0	0	Negative
1	B629001-1	3	303	Classroom 303	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	3	303	Classroom 303	Vent	Metal	Tan	None	0	10.7	Positive
1	B629001-1	3	303	Classroom 303	Ceiling	Plaster	White	Flaking	50	11.1	Positive
1	B629001-1	3	303	Classroom 303	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	W1	Plaster	White	Cracking	1	5.6	Positive
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	W2	Plaster	White	Chipping	1	8.1	Positive
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	W3	Plaster	White	None	0	6.1	Positive
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	W4	Plaster	White	Flaking	1	6.7	Positive
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	Ceiling	Plaster	White	None	0	5.1	Positive
1	B629001-1	3	303A	Classroom 303 Closet on Men's Lounge side	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	W1	Plaster	White	Chipping	1	7.7	Positive
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	W2	Plaster	White	None	0	7.3	Positive
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	W3	Plaster	White	Cracking	1	5.8	Positive
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	W4	Plaster	White	None	0	6.7	Positive
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	Ceiling	Plaster	White	None	0	7.1	Positive
1	B629001-1	3	304A	Classroom 303 Closet on exterior wall	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	304B	Classroom 303 Coat Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304B	Classroom 303 Coat Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304B	Classroom 303 Coat Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304B	Classroom 303 Coat Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304B	Classroom 303 Coat Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304B	Classroom 303 Coat Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	W1	Plaster	White	Cracking	4	3.3	Positive
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	W2	Plaster	White	None	0	3.7	Positive
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	W3	Plaster	White	None	0	5.5	Positive
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	W4	Plaster	White	None	0	5.7	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	Pipe	Metal	White	Chipping	1	9.8	Positive	
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	Ceiling	Plaster	White	None	0	6.8	Positive	
1	B629001-1	3	304C	Classroom 303 Closet next to Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	305	Classroom 305	W1	Plaster	White	Chipping	5	10.1	Positive	
1	B629001-1	3	305	Classroom 305	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	305	Classroom 305	Conduit	Vinyl	Tan	None	0	0	Negative	
1	B629001-1	3	305	Classroom 305	Pipe	Metal	White	Flaking	25	0	Negative	
1	B629001-1	3	305	Classroom 305	W2	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	305	Classroom 305	W3	Plaster	White	Flaking	25	10.8	Positive	
1	B629001-1	3	305	Classroom 305	Radiator	Metal	Silver	Chipping	1	6.2	Positive	
1	B629001-1	3	305	Classroom 305	W4	Sheetrock	White	Chipping	1	0	Negative	
1	B629001-1	3	305	Classroom 305	Door Frame	Metal	White	None	0	0	Negative	
1	B629001-1	3	305	Classroom 305	Ceiling	Plaster	White	Flaking	25	10.3	Positive	
1	B629001-1	3	305	Classroom 305	Beam	Concrete	White	Flaking	3	0.2	Negative	
1	B629001-1	3	305	Classroom 305	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	305A	Classroom 305 Coat Closet	W1	Plaster	White	Chipping	1	6.6	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	W2	Plaster	White	Flaking	1	6.2	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	W3	Plaster	White	Flaking	2	8.2	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	W4	Plaster	White	Flaking	2	10.4	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	Ceiling	Plaster	White	Cracking	1	8.7	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	Duct	Metal	White	None	0	10.4	Positive	
1	B629001-1	3	305A	Classroom 305 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	305B	Classroom 305 Closet	W1	Plaster	White	Chipping	2	4.8	Positive	
1	B629001-1	3	305B	Classroom 305 Closet	W2	Plaster	White	Cracking	5	5.3	Positive	
1	B629001-1	3	305B	Classroom 305 Closet	W3	Plaster	White	Cracking	2	5.7	Positive	
1	B629001-1	3	305B	Classroom 305 Closet	W4	Plaster	White	Cracking	10	6.3	Positive	
1	B629001-1	3	305B	Classroom 305 Closet	Ceiling	Plaster	White	None	0	5.7	Positive	
1	B629001-1	3	305B	Classroom 305 Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	306	Classroom 306	W1	Plaster	White	Cracking	1	10.1	Positive	
1	B629001-1	3	306	Classroom 306	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	306	Classroom 306	Conduit	Vinyl	Tan	None	0	0.7	Positive	
1	B629001-1	3	306	Classroom 306	W2	Plaster	White	Chipping	1	0	Negative	
1	B629001-1	3	306	Classroom 306	W3	Plaster	White	Cracking	6	10.1	Positive	
1	B629001-1	3	306	Classroom 306	Radiator	Metal	Silver	Chipping	1	6.7	Positive	
1	B629001-1	3	306	Classroom 306	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	306	Classroom 306	W4	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	306	Classroom 306	Ceiling	Plaster	White	Flaking	100	10.1	Positive	
1	B629001-1	3	306	Classroom 306	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	306A	Classroom 306 Coat Closet	W1	Plaster	White	None	0	9.8	Positive	
1	B629001-1	3	306A	Classroom 306 Coat Closet	W2	Plaster	White	None	0	6.6	Positive	
1	B629001-1	3	306A	Classroom 306 Coat Closet	W3	Plaster	White	Flaking	2	8.2	Positive	
1	B629001-1	3	306A	Classroom 306 Coat Closet	W4	Plaster	White	Flaking	4	8.7	Positive	
1	B629001-1	3	306A	Classroom 306 Coat Closet	Ceiling	Plaster	White	Flaking	8	8.7	Positive	
1	B629001-1	3	306A	Classroom 306 Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	306C	Pipe Shaft next to Classroom 306	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307	Classroom 307	W1	Plaster	White	Flaking	12	10.5	Positive	
1	B629001-1	3	307	Classroom 307	W1	Plaster	Tan	Efflorescence	8	10.9	Positive	
1	B629001-1	3	307	Classroom 307	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	307	Classroom 307	W2	Plaster	White	Cracking	3	11.1	Positive	
1	B629001-1	3	307	Classroom 307	W2	Plaster	Tan	None	0	10.9	Positive	
1	B629001-1	3	307	Classroom 307	Blackboard Ledge	Wood	Tan	None	0	0.1	Negative	
1	B629001-1	3	307	Classroom 307	W3	Plaster	White	Flaking	30	10.4	Positive	
1	B629001-1	3	307	Classroom 307	W3	Plaster	Tan	Flaking	6	11.2	Positive	
1	B629001-1	3	307	Classroom 307	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	307	Classroom 307	Window Sill	Wood	Tan	None	0	0.4	Negative	
1	B629001-1	3	307	Classroom 307	Radiator	Metal	Silver	None	0	0	Negative	
1	B629001-1	3	307	Classroom 307	W4	Plaster	White	Cracking	8	10.6	Positive	
1	B629001-1	3	307	Classroom 307	W4	Plaster	Tan	Cracking	2	10.2	Positive	
1	B629001-1	3	307	Classroom 307	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	307	Classroom 307	Blackboard Ledge	Wood	Tan	None	0	0.1	Negative	
1	B629001-1	3	307	Classroom 307	Conduit	Vinyl	Tan	None	0	0.9	Positive	
1	B629001-1	3	307	Classroom 307	Ceiling	Plaster	White	Flaking	8	10.4	Positive	
1	B629001-1	3	307	Classroom 307	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	W1	Plaster	White	Cracking	1	10.2	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	W2	Plaster	White	None	0	7.6	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	W3	Plaster	White	Flaking	15	5.9	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	W4	Plaster	White	Efflorescence	20	9.5	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Vent	Metal	White	None	0	8.2	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Conduit	Metal	Tan	None	0	0	Negative	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Radiator	Metal	Silver	None	0	1.2	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Radiator Shield	Metal	Silver	Chipping	1	1.1	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Ceiling	Plaster	White	Chipping	10	8.7	Positive	
1	B629001-1	3	307A	Classroom 307 Coat/Server Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	307B	Classroom 307 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307B	Classroom 307 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307B	Classroom 307 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307B	Classroom 307 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307B	Classroom 307 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	307B	Classroom 307 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
1	B629001-1	3	309	Art Room 309	W1	Plaster	White	Chipping	2	8.6	Positive	
1	B629001-1	3	309	Art Room 309	W2	Plaster	White	None	0	10	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	3	309	Art Room 309	W3	Plaster	White	Flaking	12	9.8	Positive
1	B629001-1	3	309	Art Room 309	Radiator	Metal	Silver	Flaking	15	0.1	Negative
1	B629001-1	3	309	Art Room 309	Radiator	Metal	Silver	Flaking	15	0.1	Negative
1	B629001-1	3	309	Art Room 309	Wall Divider	Sheetrock	White	Chipping	1	0.1	Negative
1	B629001-1	3	309	Art Room 309	W4	Plaster	White	Flaking	4	10.1	Positive
1	B629001-1	3	309	Art Room 309	Ceiling	Plaster	White	Flaking	200	9.5	Positive
1	B629001-1	3	309	Art Room 309	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309	Art Room 309	Cove Base	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309A	Art Room Coat Closet	W1	Plaster	White	Chipping	2	6.9	Positive
1	B629001-1	3	309A	Art Room Coat Closet	W2	Plaster	White	Cracking	4	9.4	Positive
1	B629001-1	3	309A	Art Room Coat Closet	W3	Plaster	White	Flaking	1	6.4	Positive
1	B629001-1	3	309A	Art Room Coat Closet	W4	Plaster	White	Efflorescence	40	9.4	Positive
1	B629001-1	3	309A	Art Room Coat Closet	Pipe	Metal	White	None	0	7.5	Positive
1	B629001-1	3	309A	Art Room Coat Closet	Radiator Shield	Metal	Silver	Flaking	1	1.1	Positive
1	B629001-1	3	309A	Art Room Coat Closet	Radiator	Metal	Silver	Chipping	1	1.1	Positive
1	B629001-1	3	309A	Art Room Coat Closet	Ceiling	Plaster	White	Flaking	6	9.7	Positive
1	B629001-1	3	309A	Art Room Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	W1	Plaster	White	Efflorescence	4	4.8	Positive
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	W2	Plaster	White	Efflorescence	4	7.4	Positive
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	W3	Plaster	White	None	0	9.5	Positive
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	W4	Plaster	White	None	0	6.1	Positive
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	Ceiling	Plaster	White	Chipping	6	8	Positive
1	B629001-1	3	309B	Art Room Closet next to Coat Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309C	Art Room Sink Alcove	W1	Plaster	Blue	None	0	8.3	Positive
1	B629001-1	3	309C	Art Room Sink Alcove	W2	Plaster	Blue	None	0	9.4	Positive
1	B629001-1	3	309C	Art Room Sink Alcove	W3	Plaster	Blue	None	0	9.8	Positive
1	B629001-1	3	309C	Art Room Sink Alcove	W4	Sheetrock	Blue	None	0	0	Negative
1	B629001-1	3	309C	Art Room Sink Alcove	Ceiling	Plaster	White	Flaking	25	8.7	Positive
1	B629001-1	3	309C	Art Room Sink Alcove	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	W1	Plaster	White	Flaking	1	10.8	Positive
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	W2	Sheetrock	White	None	0	0	Negative
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	W3	Plaster	White	Chipping	5	10.3	Positive
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	W4	Plaster	White	None	0	8.7	Positive
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	Ceiling	Plaster	White	Flaking	25	9.5	Positive
1	B629001-1	3	309D	Art Room Large Closet next to Sink Alcove	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	309E	Art Room Closet next to Large Closet	W1	Plaster	White	None	0	5.7	Positive
1	B629001-1	3	309E	Art Room Closet next to Large Closet	W2	Plaster	White	None	0	7.2	Positive
1	B629001-1	3	309E	Art Room Closet next to Large Closet	W3	Plaster	White	Chipping	3	5.3	Positive
1	B629001-1	3	309E	Art Room Closet next to Large Closet	W4	Plaster	White	None	0	7.8	Positive
1	B629001-1	3	309E	Art Room Closet next to Large Closet	Ceiling	Plaster	White	Chipping	1	9.4	Positive
1	B629001-1	3	309E	Art Room Closet next to Large Closet	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	311	Hallway Closet 311	W1	Plaster	White	Cracking	8	7.2	Positive
1	B629001-1	3	311	Hallway Closet 311	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	3	311	Hallway Closet 311	W2	Plaster	White	Efflorescence	25	7.2	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
1	B629001-1	3	311	Hallway Closet 311	Radiator	Metal	Black	None	0	0	Negative	
1	B629001-1	3	311	Hallway Closet 311	W3	Plaster	White	Flaking	45	4.4	Positive	
1	B629001-1	3	311	Hallway Closet 311	W4	Plaster	White	Flaking	5	7.5	Positive	
1	B629001-1	3	311	Hallway Closet 311	Baseboard	Wood	White	None	0	0	Negative	
1	B629001-1	3	311	Hallway Closet 311	Ceiling	Plaster	White	Flaking	5	6.8	Positive	
1	B629001-1	3	311	Hallway Closet 311	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	312	Girl's Restroom	W1	Plaster	White	Flaking	2	8.4	Positive	
1	B629001-1	3	312	Girl's Restroom	Vent	Metal	White	None	0	0	Negative	
1	B629001-1	3	312	Girl's Restroom	W2	Plaster	White	None	0	8.3	Positive	
1	B629001-1	3	312	Girl's Restroom	W2	Plaster	Purple	None	0	8.3	Positive	
1	B629001-1	3	312	Girl's Restroom	Pipe	Metal	White	None	0	3.6	Positive	
1	B629001-1	3	312	Girl's Restroom	W3	Plaster	White	Chipping	5	8.6	Positive	
1	B629001-1	3	312	Girl's Restroom	W3	Plaster	Purple	Chipping	0	8.6	Positive	
1	B629001-1	3	312	Girl's Restroom	Radiator	Metal	Brown	Chipping	1	0	Negative	
1	B629001-1	3	312	Girl's Restroom	W4	Plaster	White	Chipping	1	4.7	Positive	
1	B629001-1	3	312	Girl's Restroom	W4	Plaster	Purple	Chipping	0	4.7	Positive	
1	B629001-1	3	312	Girl's Restroom	Ceiling	Plaster	White	None	0	7.5	Positive	
1	B629001-1	3	312	Girl's Restroom	Floor	Concrete	Gray	None	0	0	Negative	
1	B629001-1	3	317	Boy's Restroom	W1	Plaster	White	None	0	8.6	Positive	
1	B629001-1	3	317	Boy's Restroom	Duct	Metal	White	None	0	0	Negative	
1	B629001-1	3	317	Boy's Restroom	Door Frame	Metal	Tan	Chipping	1	0	Negative	
1	B629001-1	3	317	Boy's Restroom	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	317	Boy's Restroom	W2	Plaster	White	Flaking	25	9.3	Positive	
1	B629001-1	3	317	Boy's Restroom	W3	Plaster	White	Flaking	7	8.7	Positive	
1	B629001-1	3	317	Boy's Restroom	Radiator	Metal	Brown	Flaking	1	0	Negative	
1	B629001-1	3	317	Boy's Restroom	W4	Sheetrock	White	None	0	0	Negative	
1	B629001-1	3	317	Boy's Restroom	Ceiling	Plaster	White	None	0	9.8	Positive	
1	B629001-1	3	317	Boy's Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	W1	Plaster	White	Flaking	1	7.6	Positive	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	W2	Plaster	White	Cracking	12	8	Positive	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	W3	Plaster	White	Flaking	8	10.6	Positive	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	Shelving	Wood	White	Flaking	1	0.1	Negative	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	W4	Plaster	White	Flaking	12	8.4	Positive	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	Ceiling	Plaster	White	Efflorescence	5	8.2	Positive	
1	B629001-1	3	315	Custodial Closet o/s Boys restroom	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
1	B629001-1	3	313	Women's Lounge/Copy Room	W1	Plaster	White	None	0	10.1	Positive	
1	B629001-1	3	313	Women's Lounge/Copy Room	Chair Rail	Wood	Brown	Chipping	1	0	Negative	
1	B629001-1	3	313	Women's Lounge/Copy Room	W2	Plaster	White	None	0	0	Negative	
1	B629001-1	3	313	Women's Lounge/Copy Room	W3	Plaster	White	None	0	9.9	Positive	
1	B629001-1	3	313	Women's Lounge/Copy Room	Radiator Shield	Metal	Silver	Chipping	2	6.3	Positive	
1	B629001-1	3	313	Women's Lounge/Copy Room	Radiator	Metal	Silver	Flaking	1	6.3	Positive	
1	B629001-1	3	313	Women's Lounge/Copy Room	Pipe	Metal	White	None	0	0	Negative	
1	B629001-1	3	313	Women's Lounge/Copy Room	W4	Plaster	White	None	0	9.7	Positive	
1	B629001-1	3	313	Women's Lounge/Copy Room	Ceiling	Plaster	White	None	0	8.6	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
1	B629001-1	3	313	Women's Lounge/Copy Room	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	313 A	Womens Lounge Restroom	W1	Plaster	White	None	0	7.9	Positive
1	B629001-1	3	313 A	Womens Lounge Restroom	W2	Plaster	White	Chipping	1	2.7	Positive
1	B629001-1	3	313 A	Womens Lounge Restroom	W3	Plaster	White	None	0	9.1	Positive
1	B629001-1	3	313 A	Womens Lounge Restroom	W4	Plaster	White	None	0	9.1	Positive
1	B629001-1	3	313 A	Womens Lounge Restroom	Ceiling	Plaster	White	None	0	9	Positive
1	B629001-1	3	313 A	Womens Lounge Restroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	313 B	Next to Teachers Lounge	W1	Plaster	White	None	0	2	Positive
1	B629001-1	3	313 B	Next to Teachers Lounge	W2	Plaster	White	None	0	5.6	Positive
1	B629001-1	3	313 B	Next to Teachers Lounge	W3	Plaster	White	None	0	7.4	Positive
1	B629001-1	3	313 B	Next to Teachers Lounge	W4	Plaster	White	None	0	6.1	Positive
1	B629001-1	3	313 B	Next to Teachers Lounge	Ceiling	Plaster	White	Chipping	10	7.2	Positive
1	B629001-1	3	313 B	Next to Teachers Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	W1	Plaster	White	None	0	7.5	Positive
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	W2	Plaster	White	None	0	9.8	Positive
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	W3	Plaster	White	None	0	8.1	Positive
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	W4	Plaster	White	None	0	9.8	Positive
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	Ceiling	Plaster	White	None	0	8.1	Positive
1	B629001-1	3	313G	Hallway Closet opposite Women's Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	316	Men's Lounge	W1	Plaster	White	None	0	9.8	Positive
1	B629001-1	3	316	Men's Lounge	W2	Plaster	White	Cracking	2	10	Positive
1	B629001-1	3	316	Men's Lounge	W3	Plaster	White	Flaking	12	9.3	Positive
1	B629001-1	3	316	Men's Lounge	Radiator Shield	Metal	Silver	Flaking	4	2.6	Positive
1	B629001-1	3	316	Men's Lounge	Radiator	Metal	Silver	Flaking	1	2.9	Positive
1	B629001-1	3	316	Men's Lounge	Pipe	Metal	White	Flaking	1	0.4	Negative
1	B629001-1	3	316	Men's Lounge	W4	Plaster	White	Flaking	6	9.8	Positive
1	B629001-1	3	316	Men's Lounge	Ceiling	Plaster	White	Flaking	2	10.4	Positive
1	B629001-1	3	316	Men's Lounge	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
1	B629001-1	3	316A	Men's Lounge Restroom	W1	Plaster	White	Cracking	6	8.7	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	W2	Plaster	White	None	0	7.6	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	W3	Plaster	White	Flaking	28	9.1	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	Vent	Metal	White	Cracking	1	10.1	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	Conduit	Metal	Tan	None	0	0	Negative
1	B629001-1	3	316A	Men's Lounge Restroom	W4	Plaster	White	Chipping	5	10	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	Ceiling	Plaster	White	Flaking	6	10.1	Positive
1	B629001-1	3	316A	Men's Lounge Restroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B5	Storage next to Monastery Street	W1	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B5	Storage next to Monastery Street	W1	Metal	Tan	Flaking	1	0.02	Negative
2	B629002-1	B	B5	Storage next to Monastery Street	W1	CMU	White	None	0	0.01	Negative
2	B629002-1	B	B5	Storage next to Monastery Street	Door Frame	Metal	Gray	None	0	0	Negative
2	B629002-1	B	B5	Storage next to Monastery Street	W1	Plaster	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B5	Storage next to Monastery Street	W2	Plaster	White	Flaking	150	0.05	Negative
2	B629002-1	B	B5	Storage next to Monastery Street	Window Sill	Concrete	White	Flaking	5	0.02	Negative
2	B629002-1	B	B5	Storage next to Monastery Street	Window Frame	Wood	White	Flaking	4	5.2	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	B	B5	Storage next to Monastery Street	W3	Plaster	White	Flaking	250	0.01	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	W4	Plaster	White	Flaking	200	0.03	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	W4	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B5	Storage next to Monastery Street	Electrical Panel	Metal	Tan	Flaking	2	0.09	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Conduit	Metal	White	Flaking	1	0.1	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Wall Divider	Plaster	White	Flaking	350	0.02	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Panel	Wood	Tan	Chipping	2	0.12	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Baseboard	Wood	Tan	Chipping	1	0.14	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Chair Rail	Wood	Tan	Chipping	1	0.16	Negative	
2	B629002-1	B	B5	Storage next to Monastery Street	Ceiling	Concrete	White	None	0	N/A	N/A	
2	B629002-1	B	B5	Storage next to Monastery Street	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B5A	Storage next to Monastery Street	W1	Wood	Tan	Flaking	2	0.08	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Door Frame	Wood	Tan	Flaking	2	0.01	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	W2	Wood	Tan	Flaking	5	0.11	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	W3	Wood	Tan	Cracking	3	0.12	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Window Frame	Wood	Tan	Flaking	5	0.08	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Window Sill	Wood	Tan	Friction	1	0.07	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Window Apron	Wood	Tan	None	0	0.09	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	W4	Wood	Tan	Flaking	10	0.14	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Ceiling	Wood	Tan	Flaking	50	0.14	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Pipe	Metal	White	None	0	0.03	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B5A	Storage next to Monastery Street	Baseboard	Wood	Tan	Friction	2	0.07	Negative	
2	B629002-1	B	B5A	Storage next to Monastery Street	Floor	Wood	Gray	None	0	0.07	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W1	Sheetrock	White	None	0	0	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W1	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Door Frame	Metal	Gray	None	0	0	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W2	Plaster	White	Flaking	250	0.01	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W2	Plaster	Tan	Flaking	5	0	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Conduit	Metal	White	None	0	16.5	Positive	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Conduit	Metal	Tan	Flaking	5	9.2	Positive	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W3	Sheetrock	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W4	Plaster	White	Flaking	120	0.12	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	W4	Plaster	Tan	Flaking	5	0.01	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Ceiling	Metal	White	Cracking	200	0	Negative	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	H002	Hallway in Basement Storage Area	Trench Cover	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	001C	Corner Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001C	Corner Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001C	Corner Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001C	Corner Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001C	Corner Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001C	Corner Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001B	Storeroom next to Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	B	001B	Storeroom next to Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001B	Storeroom next to Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001B	Storeroom next to Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001B	Storeroom next to Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	001B	Storeroom next to Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	2BB	Former Incinerator Room	W1	Brick	White	Flaking	200	23.8	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	W2	Brick	White	Flaking	200	36.1	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	W3	Brick	White	Flaking	200	36.5	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	W4	Brick	White	Flaking	200	34.5	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	2BB	Former Incinerator Room	Floor	Concrete	Gray	Chipping	400	0	Negative	
2	B629002-1	B	2BB	Former Incinerator Room	Furnace Cleanout Door	Metal	Silver	Chipping	2	5.2	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	Door Frame	Metal	Brown	Chipping	8	0.7	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	Door	Metal	Brown	Chipping	10	0.7	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	Window Frame	Wood	Gray	Flaking	50	2.5	Positive	
2	B629002-1	B	2BB	Former Incinerator Room	Incinerator	Metal	Gray	None	0	0	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	W1	Wood	Tan	Chipping	1	0.03	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Door Frame	Wood	Tan	Chipping	1	0.18	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	W2	Wood	Tan	None	0	0.14	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Window Frame	Wood	Tan	Chipping	1	0.09	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	W3	Wood	Tan	Chipping	1	0.08	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	W4	Wood	Tan	Chipping	1	0.2	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Ceiling	Wood	White	Chipping	2	0.02	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Conduit	Metal	White	None	0	0.14	Negative	
2	B629002-1	B	2A-2-B	Storeroom next to Loading Area	Baseboard	Wood	White	Chipping	2	0.03	Negative	
2	B629002-1	B	2B	Loading Area	W1	Wood	Tan	Flaking	1	0.15	Negative	
2	B629002-1	B	2B	Loading Area	W1	Wood	White	Chipping	1	0.16	Negative	
2	B629002-1	B	2B	Loading Area	W2	Plaster	White	Flaking	50	0	Negative	
2	B629002-1	B	2B	Loading Area	W2	Plaster	Tan	Flaking	25	0	Negative	
2	B629002-1	B	2B	Loading Area	Window Sill	Wood	Tan	Chipping	1	0	Negative	
2	B629002-1	B	2B	Loading Area	Conduit	Metal	White	Flaking	1	0.09	Negative	
2	B629002-1	B	2B	Loading Area	Transfer Box	Metal	White	None	0	0.02	Negative	
2	B629002-1	B	2B	Loading Area	Handrail	Wood	Gray	Chipping	1	2.7	Positive	
2	B629002-1	B	2B	Loading Area	Door Frame	Metal	Brown	Moisture Damage	1	0.6	Negative	
2	B629002-1	B	2B	Loading Area	Door	Metal	Brown	Chipping	2	0.5	Negative	
2	B629002-1	B	2B	Loading Area	W3	Plaster	Tan	Flaking	60	0	Negative	
2	B629002-1	B	2B	Loading Area	W3	Plaster	White	Flaking	60	0	Negative	
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	Flaking	1	20.9	Positive	
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	Alligatoring	1	0.06	Negative	
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	None	0	20.8	Positive	
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	Flaking	1	0.05	Negative	
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	None	0	20.9	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	B	2B	Loading Area	Window Frame	Wood	Tan	None	0	0.06	Negative
2	B629002-1	B	2B	Loading Area	Ceiling	Plaster	White	Flaking	50	0.09	Negative
2	B629002-1	B	2B	Loading Area	Conduit	Metal	White	Flaking	5	0.05	Negative
2	B629002-1	B	2B	Loading Area	Floor	Concrete	Red	Chipping	300	0.01	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W1	Sheetrock	Tan	None	0	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W1	Sheetrock	White	None	0	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W1	Wood	Tan	Chipping	2	0.07	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Moulding	Wood	Tan	Chipping	1	0.16	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W1	Plaster	Tan	Flaking	100	0.12	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W1	Plaster	White	Flaking	150	0.02	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Air Handling Unit	Metal	Tan	Flaking	10	5.2	Positive
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Air Handling Unit	Metal	Tan	Flaking	10	5.2	Positive
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Pipe	Metal	Tan	Flaking	1	0.18	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Air Handling Unit	Metal	Tan	Flaking	8	5.2	Positive
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Pipe	Metal	Tan	Chipping	1	0.18	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Air Handling Unit	Metal	Tan	Flaking	10	5.3	Positive
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Air Handling Unit	Metal	Tan	Flaking	10	5.4	Positive
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Pipe	Metal	Tan	Chipping	1	0.18	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Conduit	Metal	Tan	None	0	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Conduit	Metal	Tan	None	0	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Pipe	Metal	Tan	None	0	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W2	Plaster	White	Flaking	10	0	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W2	Wood	Tan	Flaking	1	0.15	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Stair Riser	Concrete	Gray	Flaking	20	0.03	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W3	Wood	Tan	Chipping	2	0.09	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Window Frame	Wood	White	None	0	0.12	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	W3	Wood	White	None	0	0.19	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Conduit	Metal	White	None	0	0.02	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Ceiling	Plaster	White	Flaking	100	0.04	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Baseboard	Wood	Gray	Chipping	1	0.09	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Duct	Metal	Gray	Chipping	1	0.07	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Duct	Metal	Gray	Chipping	1	0.07	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Duct	Metal	Gray	Chipping	1	0.07	Negative
2	B629002-1	B	H00111	Hallway next to Basement Classrooms	Trench Cover	Metal	Gray	Friction	5	0.04	Negative
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W1	Wood	Tan	None	0	0.8	Positive
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W1	Sheetrock	Tan	None	0	0	Negative

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Door Frame	Wood	Tan	Flaking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Blackboard Frame	Wood	Tan	Chipping	1	0	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Vent	Metal	Tan	Chipping	1	0.11	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Conduit	Metal	Tan	None	0	0.11	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W2	Wood	Tan	None	0	0.6	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W2	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W2	Wood	White	Flaking	1	0.6	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Cabinet Interior	Wood	Tan	None	0	0.02	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Cabinet Door	Wood	Tan	Flaking	3	0.9	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W3	Wood	Tan	Flaking	10	2.4	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Sill	Wood	Tan	Cracking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Apron	Wood	Tan	Cracking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Sill	Wood	Tan	Cracking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Apron	Wood	Tan	None	0	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Sill	Wood	Tan	Flaking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Window Apron	Wood	Tan	Flaking	1	1	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Radiator	Metal	Silver	Flaking	4	0.12	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Radiator	Metal	Silver	Flaking	4	0.13	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Pipe	Metal	Silver	Flaking	20	0.11	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W4	Wood	Tan	Chipping	1	0.8	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	W4	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Blackboard Frame	Wood	Tan	Cracking	1	1.9	Positive	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Conduit	Metal	Tan	None	0	0.11	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Ceiling	Wood	White	Flaking	150	0.22	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Duct	Metal	White	Flaking	1	0.5	Negative	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	0B2	Far Right Classroom on Basement Floor (to Left of Ridge Ave Entrance)	Baseboard	Wood	Tan	Chipping	1	1	Positive	
2	B629002-1	B	001A	Center Classroom	W1	Wood	Tan	None	0	0.15	Negative	
2	B629002-1	B	001A	Center Classroom	W1	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	B	001A	Center Classroom	Door Frame	Wood	Tan	Chipping	1	0.06	Negative	
2	B629002-1	B	001A	Center Classroom	Blackboard Frame	Wood	Tan	None	0	0.08	Negative	
2	B629002-1	B	001A	Center Classroom	Vent	Metal	Tan	None	0	0.22	Negative	
2	B629002-1	B	001A	Center Classroom	Conduit	Metal	Tan	None	0	6.7	Positive	
2	B629002-1	B	001A	Center Classroom	W2	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	001A	Center Classroom	W2	Wood	Tan	None	0	0.07	Negative	
2	B629002-1	B	001A	Center Classroom	W2	Wood	White	Flaking	1	0.07	Negative	
2	B629002-1	B	001A	Center Classroom	Door Frame	Metal	Tan	None	0	0	Negative	
2	B629002-1	B	001A	Center Classroom	Conduit	Metal	Tan	None	0	0	Negative	
2	B629002-1	B	001A	Center Classroom	Closet Door	Wood	Tan	Chipping	1	0.11	Negative	
2	B629002-1	B	001A	Center Classroom	Closet Wall	Wood	Tan	None	0	0.06	Negative	
2	B629002-1	B	001A	Center Classroom	W3	Wood	Tan	Flaking	12	0.06	Negative	
2	B629002-1	B	001A	Center Classroom	Window Sill	Wood	Tan	None	0	10.4	Positive	
2	B629002-1	B	001A	Center Classroom	Window Apron	Wood	Tan	None	0	0.21	Negative	
2	B629002-1	B	001A	Center Classroom	Window Sill	Wood	Tan	Cracking	1	0.03	Negative	
2	B629002-1	B	001A	Center Classroom	Window Apron	Wood	Tan	Cracking	1	0.02	Negative	
2	B629002-1	B	001A	Center Classroom	Window Sill	Wood	Tan	None	0	0.4	Negative	
2	B629002-1	B	001A	Center Classroom	Window Apron	Wood	Tan	Flaking	1	0.14	Negative	
2	B629002-1	B	001A	Center Classroom	Pipe	Metal	Tan	Flaking	15	0.1	Negative	
2	B629002-1	B	001A	Center Classroom	Pipe	Metal	Silver	Flaking	8	0.1	Negative	
2	B629002-1	B	001A	Center Classroom	Pipe	Metal	Silver	Flaking	25	0.1	Negative	
2	B629002-1	B	001A	Center Classroom	Radiator	Metal	Silver	Flaking	4	0.02	Negative	
2	B629002-1	B	001A	Center Classroom	Radiator	Metal	Silver	Flaking	12	0.02	Negative	
2	B629002-1	B	001A	Center Classroom	Radiator	Metal	Silver	None	0	0.02	Negative	
2	B629002-1	B	001A	Center Classroom	Cabinet Door	Wood	Tan	Chipping	1	0.04	Negative	
2	B629002-1	B	001A	Center Classroom	Cabinet Exterior	Wood	Tan	Chipping	1	0.17	Negative	
2	B629002-1	B	001A	Center Classroom	Cabinet Interior	Wood	White	Moisture Damage	5	0.03	Negative	
2	B629002-1	B	001A	Center Classroom	Shelving	Wood	White	Chipping	1	0.03	Negative	
2	B629002-1	B	001A	Center Classroom	W4	Wood	Tan	Chipping	1	0.08	Negative	
2	B629002-1	B	001A	Center Classroom	W4	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	001A	Center Classroom	Door Frame	Wood	Tan	Flaking	1	0.8	Positive	
2	B629002-1	B	001A	Center Classroom	Blackboard Frame	Wood	Tan	Flaking	2	0	Negative	
2	B629002-1	B	001A	Center Classroom	Ceiling	Wood	White	Flaking	20	0.08	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	B	001A	Center Classroom	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	001A	Center Classroom	Baseboard	Wood	Tan	Cracking	2	0.4	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W1	Wood	Tan	None	0	0.19	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W1	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Vent	Metal	Tan	None	0	0.18	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Door Frame	Wood	Tan	Flaking	1	0.06	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Conduit	Metal	Tan	None	0	11.6	Positive	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W2	Wood	Tan	Flaking	5	0.14	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Window Sill	Wood	Tan	Chipping	1	0.12	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Window Apron	Wood	Tan	Flaking	1	0.04	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Radiator	Metal	Silver	Flaking	1	0.03	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Pipe	Metal	Silver	Flaking	5	0.01	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W3	Wood	Tan	None	0	0.23	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Window Frame	Wood	Tan	Chipping	1	2.4	Positive	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Radiator	Metal	Silver	Flaking	1	0.07	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Moulding	Wood	Tan	None	0	0.13	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W4	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Radiator	Metal	Silver	None	0	0.06	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	W4	Wood	Tan	None	0	0.13	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Moulding	Wood	Tan	None	0	0.13	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Door Frame	Metal	Tan	None	0	0	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Baseboard	Wood	Tan	Friction	2	0.01	Negative	
2	B629002-1	B	0B1	Far Left Classroom in Basement near Monastery St. Entrance	Ceiling	Wood	Tan	Flaking	10	0.09	Negative	
2	B629002-1	B	S0001	Stairwell on Gerhard St side	W1	Metal	Tan	None	0	0	Negative	
2	B629002-1	B	S0001	Stairwell on Gerhard St side	Door Frame	Metal	Tan	Chipping	1	0.01	Negative	
2	B629002-1	B	S0001	Stairwell on Gerhard St side	W2	Plaster	White	Efflorescence	20	0.3	Negative	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	B	S0001	Stairwell on Gerhard St side	W4	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	B	S0001	Stairwell on Gerhard St side	Stair Stringer	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	B	S0001	Stairwell on Gerhard St side	Stair Riser	Metal	Tan	Chipping	4	0	Negative
2	B629002-1	B	S0001	Stairwell on Gerhard St side	Handrail	Metal	Tan	Flaking	15	0.12	Negative
2	B629002-1	B	S0001	Stairwell on Gerhard St side	Ceiling	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W1	Plaster	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	W1	CMU	White	None	0	0	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W1	Metal	Tan	None	0	0	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W1	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	W2	Plaster	Tan	Flaking	80	0.08	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W2	Sheetrock	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	W3	Plaster	Tan	Flaking	30	0.06	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W3	Plaster	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	W3	CMU	White	None	0	0	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	W4	Plaster	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	Window Frame	Wood	Tan	Moisture Damage	8	2.4	Positive
2	B629002-1	B	B7	Storage next to Gerhard Street	Window Sill	Concrete	Gray	None	0	0.01	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	Window Frame	Wood	Gray	Moisture Damage	8	2.4	Positive
2	B629002-1	B	B7	Storage next to Gerhard Street	Window Sill	Concrete	Gray	Efflorescence	4	0.01	Negative
2	B629002-1	B	B7	Storage next to Gerhard Street	Wall Divider	Plaster	Tan	Flaking	350	2	Positive
2	B629002-1	B	B7	Storage next to Gerhard Street	Ceiling	Fireproofing	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7	Storage next to Gerhard Street	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	B	B7A	Storage next to Gerhard Street	W1	Wood	White	Flaking	1	13.4	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Door Frame	Wood	White	Flaking	2	10.1	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	W2	Wood	White	Flaking	30	9.3	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	W3	Wood	White	Flaking	10	11.4	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Pipe	Metal	White	Flaking	2	8.9	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Conduit	Metal	Tan	Flaking	2	0.07	Negative
2	B629002-1	B	B7A	Storage next to Gerhard Street	W4	Wood	White	Flaking	20	10.1	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Conduit	Metal	Tan	None	0	3	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Baseboard	Wood	White	Chipping	5	3.4	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Ceiling	Wood	White	Flaking	20	10.2	Positive
2	B629002-1	B	B7A	Storage next to Gerhard Street	Pipe	Metal	Tan	Flaking	6	0.04	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	W1	Metal	Tan	None	0	0.01	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	Door Frame	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	W2	Metal	Tan	Chipping	1	0.02	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	W4	Plaster	Tan	Efflorescence	25	0	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	Ceiling	Metal	Tan	None	0	0	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	Stair Stringer	Metal	Tan	Chipping	1	0.01	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	Stair Riser	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	B	S0002	Stairwell on Monastery St side	Handrail	Metal	Tan	Chipping	5	0.13	Negative
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002C	Corner Storage Room adjacent to Monastery Street Entrance	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	W1	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	W2	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	W3	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	W4	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	002D	Storage adjacent to Basement Stairwell	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	B	B7B	Storage next to Gerhard Street	W1	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7B	Storage next to Gerhard Street	W2	CMU	White	None	0	0.02	Negative	
2	B629002-1	B	B7B	Storage next to Gerhard Street	W3	CMU	White	None	0	0.02	Negative	
2	B629002-1	B	B7B	Storage next to Gerhard Street	W4	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7B	Storage next to Gerhard Street	Door Frame	Metal	White	Chipping	1	0.01	Negative	
2	B629002-1	B	B7B	Storage next to Gerhard Street	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7C	Storage next to Gerhard Street	W1	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7C	Storage next to Gerhard Street	W2	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7C	Storage next to Gerhard Street	W3	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7C	Storage next to Gerhard Street	W4	CMU	White	None	0	0.01	Negative	
2	B629002-1	B	B7C	Storage next to Gerhard Street	Door Frame	Metal	White	None	0	0.03	Negative	
2	B629002-1	B	B7C	Storage next to Gerhard Street	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7D	Storage next to Gerhard Street	W1	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7D	Storage next to Gerhard Street	Door Frame	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	B	B7D	Storage next to Gerhard Street	W2	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7D	Storage next to Gerhard Street	W3	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7D	Storage next to Gerhard Street	W4	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	B	B7D	Storage next to Gerhard Street	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	B	B7D	Storage next to Gerhard Street	Access Panel	Metal	Tan	Flaking	1	0	Negative	
2	B629002-1	B	B7D	Storage next to Gerhard Street	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	W1	Brick	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	W2	Brick	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	W3	Brick	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	W4	Brick	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door Frame	Wood	Tan	Chipping	1	19.1	Positive	
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Window Frame	Wood	Tan	Chipping	1	20	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door	Wood	Brown	Chipping	5	0.08	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Conduit	Wood	Tan	None	0	0.3	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door Frame	Metal	Brown	Chipping	1	0.3	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door	Metal	Brown	Flaking	2	0.03	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Push Bar	Metal	Gray	Flaking	1	0	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Transom Panel	Metal	Brown	None	0	0	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Conduit	Metal	Black	None	0	0.06	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door Frame	Wood	Tan	Chipping	2	32.5	Positive
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door	Wood	Brown	Friction	2	0	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Transom Panel	Wood	Tan	Cracking	1	20.8	Positive
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door Frame	Metal	Brown	None	0	0.01	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Door	Metal	Brown	Friction	1	0.07	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Transom Panel	Metal	Brown	None	0	0.17	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Pipe	Metal	Tan	Flaking	10	0.13	Negative
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Conduit	Metal	White	Flaking	10	10.1	Positive
2	B629002-1	1	H011	Foyer/Hallway Between Element 1 and Element 2	Pipe	Metal	White	Flaking	6	0.7	Positive
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	W1	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	W2	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	W3	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	W4	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	Ceiling	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	106-2	Staff Restroom across from Classroom 1	Floor	No Access	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	1-2	Classroom 1	W1	Plaster	White	Chipping	5	46	Positive
2	B629002-1	1	1-2	Classroom 1	Door Frame	Wood	Tan	Chipping	1	13	Positive
2	B629002-1	1	1-2	Classroom 1	Column	Wood	Tan	None	0	41.1	Positive
2	B629002-1	1	1-2	Classroom 1	Blackboard Frame	Wood	Tan	Chipping	2	16.2	Positive
2	B629002-1	1	1-2	Classroom 1	Wainscoting	Wood	White	None	0	15.9	Positive
2	B629002-1	1	1-2	Classroom 1	Vent Cover	Metal	Tan	None	0	38.2	Positive
2	B629002-1	1	1-2	Classroom 1	Vent Cover	Metal	White	None	0	22.7	Positive
2	B629002-1	1	1-2	Classroom 1	W2	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	1	1-2	Classroom 1	Conduit	Metal	White	None	0	0	Negative
2	B629002-1	1	1-2	Classroom 1	Conduit	Vinyl	White	None	0	0	Negative
2	B629002-1	1	1-2	Classroom 1	W3	Sheetrock	White	Chipping	1	0.3	Negative
2	B629002-1	1	1-2	Classroom 1	Wainscoting	Wood	White	None	0	17.2	Positive
2	B629002-1	1	1-2	Classroom 1	Chair Rail	Wood	Tan	None	0	21.5	Positive
2	B629002-1	1	1-2	Classroom 1	Post	Wood	Tan	None	0	10.6	Positive
2	B629002-1	1	1-2	Classroom 1	Wainscoting	Wood	Tan	Flaking	2	14.7	Positive
2	B629002-1	1	1-2	Classroom 1	Radiator	Metal	Silver	Flaking	150	8.1	Positive
2	B629002-1	1	1-2	Classroom 1	Bulletin Board	Wood	Tan	None	0	15.1	Positive
2	B629002-1	1	1-2	Classroom 1	Bulletin Board	Wood	Tan	Chipping	1	15.1	Positive
2	B629002-1	1	1-2	Classroom 1	Bulletin Board	Wood	Tan	Chipping	1	15.1	Positive
2	B629002-1	1	1-2	Classroom 1	Window Frame	Wood	Tan	Chipping	1	9	Positive
2	B629002-1	1	1-2	Classroom 1	Window Sill	Wood	Tan	Cracking	1	18	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	1-2	Classroom 1	Window Frame	Wood	Tan	Chipping	1	9	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Sill	Wood	Tan	Cracking	1	18	Positive	
2	B629002-1	1	1-2	Classroom 1	W4	Sheetrock	White	Flaking	2	0	Negative	
2	B629002-1	1	1-2	Classroom 1	Window Frame	Wood	Tan	Chipping	1	24	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Sill	Wood	Tan	Cracking	2	11.6	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Frame	Wood	Tan	Chipping	1	24	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Sill	Wood	Tan	Cracking	4	11.6	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Frame	Wood	Tan	None	0	24	Positive	
2	B629002-1	1	1-2	Classroom 1	Window Sill	Wood	Tan	Cracking	1	11.6	Positive	
2	B629002-1	1	1-2	Classroom 1	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	1-2	Classroom 1	Ceiling	Metal	White	Flaking	200	44.7	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	W1	Brick	White	Efflorescence	15	23.8	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Door Frame	Wood	Tan	Chipping	4	20.1	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Door	Wood	Tan	Chipping	1	10.1	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Pipe	Metal	White	None	0	27.4	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Coat Rack	Wood	White	None	0	12.4	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	W2	Brick	White	None	0	36.1	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Window Frame	Wood	Tan	None	0	16.6	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Window Sill	Wood	Tan	None	0	16.7	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Window Apron	Wood	Tan	None	0	9.9	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Coat Rack	Wood	White	None	0	10.8	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	W3	Brick	White	Cracking	2	36.5	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Coat Rack	Wood	White	Chipping	1	11.4	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Conduit	Metal	White	Chipping	1	17.2	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	W4	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	1A	Classroom 1 Closet	Ceiling	Metal	White	Flaking	15	31.8	Positive	
2	B629002-1	1	1A	Classroom 1 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	1B	Classroom 1 Vestibule	W1	Plaster	Tan	None	0	41.4	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Wainscoting	Wood	Tan	Flaking	2	19.7	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	W2	Plaster	Tan	Chipping	1	43.9	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Wainscoting	Wood	Tan	Flaking	2	20.7	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	W3	Plaster	Tan	Cracking	1	41.2	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	W4	Plaster	Tan	None	0	45	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Wainscoting	Wood	Tan	Flaking	2	21.8	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Door Frame	Wood	Tan	Chipping	1	20.4	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Closet Door	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Door Frame	Wood	Brown	Flaking	1	22	Positive	
2	B629002-1	1	1B	Classroom 1 Vestibule	Transom Panel	Wood	Brown	None	0	0	Negative	
2	B629002-1	1	1B	Classroom 1 Vestibule	Door Frame	Metal	Brown	Chipping	1	0	Negative	
2	B629002-1	1	2B	Classroom 2 Vestibule	W1	Plaster	White	Chipping	1	40.6	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	2B	Classroom 2 Vestibule	W2	Plaster	White	None	0	44.7	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Wainscoting	Wood	Tan	Chipping	2	40.9	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	W3	Plaster	White	None	0	46.1	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	2B	Classroom 2 Vestibule	Wainscoting	Wood	Tan	Chipping	1	14.7	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Door Frame	Wood	Tan	Chipping	1	14.2	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Door Frame	Metal	Tan	Friction	1	0.01	Negative	
2	B629002-1	1	2B	Classroom 2 Vestibule	W4	Plaster	White	None	0	11.1	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Wainscoting	Wood	Tan	Chipping	1	17	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Closet Door Frame	Wood	Tan	Chipping	1	16.7	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Door	Wood	Tan	Chipping	5	14.7	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Pipe Chase Door	Wood	Tan	None	0	14.7	Positive	
2	B629002-1	1	2B	Classroom 2 Vestibule	Ceiling	Metal	White	Flaking	10	31.8	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	W1	Sheetrock	White	None	0	0.01	Negative	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Door Frame	Metal	Tan	Chipping	1	0.03	Negative	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	W2	Plaster	White	Efflorescence	5	40.2	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Chair Rail	Wood	Tan	Flaking	1	14	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	W3	Plaster	White	Chipping	4	48.6	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Chair Rail	Wood	Tan	Chipping	4	16	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	W4	Sheetrock	White	Flaking	1	0	Negative	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Duct	Metal	White	Chipping	1	0	Negative	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Ceiling	Metal	White	Flaking	5	30.6	Positive	
2	B629002-1	1	107-2	Custodial Closet and Storage next to Staff Restroom	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W1	Sheetrock	White	Cracking	1	0	Negative	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W2	Plaster	White	Flaking	2	40.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Wainscoting	Wood	White	None	0	12.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Moulding	Wood	Tan	Chipping	1	13.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W3	Plaster	White	Chipping	1	41.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Wainscoting	Wood	White	None	0	11.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Moulding	Wood	Tan	None	0	18.9	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Window Frame	Wood	Tan	None	0	20.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Window Sill	Wood	Tan	Flaking	3	12.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Window Apron	Wood	Tan	None	0	10.2	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W4	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W4	Plaster	White	None	0	35.6	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	W4	Wood	White	None	0	0	Negative	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Wainscoting	Wood	White	None	0	12.8	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Moulding	Wood	Tan	None	0	19.9	Positive	
2	B629002-1	1	107-2-B	Custodial Closet and Restroom	Ceiling	Metal	White	Flaking	30	35.9	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	W1	Plaster	White	None	0	35.5	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Wainscoting	Wood	White	None	0	12.6	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Door Frame	Wood	Tan	Chipping	4	12.6	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Door Frame	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	W3	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Door Frame	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	W4	Plaster	White	None	0	39.2	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Moulding	Wood	Tan	Chipping	1	12.6	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Wainscoting	Wood	White	None	0	13.4	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Conduit	Metal	White	None	0	14.7	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Ceiling	Metal	White	Flaking	5	35.6	Positive	
2	B629002-1	1	107-2-A	Vestibule Custodial Closet and Storage next to Staff Restroom	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	2-2	Classroom 2	W1	Plaster	White	Cracking	15	47.4	Positive	
2	B629002-1	1	2-2	Classroom 2	W1	Wood	White	Chipping	1	16.5	Positive	
2	B629002-1	1	2-2	Classroom 2	Door Frame	Wood	Tan	Chipping	1	14.5	Positive	
2	B629002-1	1	2-2	Classroom 2	Door Frame	Metal	Tan	Friction	1	0.01	Negative	
2	B629002-1	1	2-2	Classroom 2	Transom Panel	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	1	2-2	Classroom 2	Blackboard Frame	Wood	Tan	Chipping	2	17	Positive	
2	B629002-1	1	2-2	Classroom 2	Vent	Metal	Tan	None	0	36.3	Positive	
2	B629002-1	1	2-2	Classroom 2	Conduit	Metal	White	None	0	20.2	Positive	
2	B629002-1	1	2-2	Classroom 2	Conduit	Metal	Tan	None	0	0.02	Negative	
2	B629002-1	1	2-2	Classroom 2	Vent	Metal	White	Chipping	1	17.6	Positive	
2	B629002-1	1	2-2	Classroom 2	Closet Door Frame	Wood	Tan	Chipping	1	14.1	Positive	
2	B629002-1	1	2-2	Classroom 2	Closet Door	Wood	Tan	Chipping	1	15.3	Positive	
2	B629002-1	1	2-2	Classroom 2	Closet Window Frame	Wood	Tan	None	0	14.6	Positive	
2	B629002-1	1	2-2	Classroom 2	Moulding	Wood	Tan	Chipping	1	19.8	Positive	
2	B629002-1	1	2-2	Classroom 2	W2	Sheetrock	White	Flaking	2	0	Negative	
2	B629002-1	1	2-2	Classroom 2	W2	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	1	2-2	Classroom 2	W3	Wood	Tan	Flaking	4	13.8	Positive	
2	B629002-1	1	2-2	Classroom 2	W3	Sheetrock	White	Flaking	5	0	Negative	
2	B629002-1	1	2-2	Classroom 2	Window Frame	Wood	Tan	Chipping	1	13.4	Positive	
2	B629002-1	1	2-2	Classroom 2	Window Sill	Wood	Tan	Cracking	1	18.4	Positive	
2	B629002-1	1	2-2	Classroom 2	Window Frame	Wood	Tan	Flaking	1	13.4	Positive	
2	B629002-1	1	2-2	Classroom 2	Window Sill	Wood	Tan	Cracking	1	18.4	Positive	
2	B629002-1	1	2-2	Classroom 2	Window Apron	Wood	Tan	Chipping	1	15.4	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	2-2	Classroom 2	Conduit	Metal	White	None	0	20.2	Positive	
2	B629002-1	1	2-2	Classroom 2	Pipe	Metal	White	None	0	0.02	Negative	
2	B629002-1	1	2-2	Classroom 2	Pipe	Metal	Tan	Chipping	1	0.01	Negative	
2	B629002-1	1	2-2	Classroom 2	Radiator	Metal	Silver	Chipping	6	5.1	Positive	
2	B629002-1	1	2-2	Classroom 2	W4	Sheetrock	White	Flaking	3	0	Negative	
2	B629002-1	1	2-2	Classroom 2	W4	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	1	2-2	Classroom 2	Moulding	Wood	Tan	Chipping	1	0	Negative	
2	B629002-1	1	2-2	Classroom 2	Ceiling	Metal	White	Flaking	200	30.8	Positive	
2	B629002-1	1	2-2	Classroom 2	Crown Moulding	Wood	Tan	None	0	12.4	Positive	
2	B629002-1	1	2-2	Classroom 2	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	W1	Brick	White	Flaking	50	34.5	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Door Frame	Wood	Tan	Chipping	5	9.4	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Door	Wood	Tan	Chipping	1	16.1	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Transom Panel	Wood	Tan	Chipping	2	15.7	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Coat Rack	Wood	White	Chipping	1	14.8	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	W2	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	W3	Brick	White	Flaking	20	35.1	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Coat Rack	Wood	White	Chipping	1	11.7	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	W4	Wood	White	Cracking	5	12.8	Positive	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Conduit	Metal	White	None	0	0.5	Negative	
2	B629002-1	1	2A-2-1	Classroom 2 Closet	Ceiling	Metal	White	Flaking	20	32	Positive	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W1	Brick	White	Chipping	1	19.6	Positive	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W2	CMU	White	Flaking	1	0.01	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W3	CMU	White	Efflorescence	5	0.01	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W4	Brick	White	Chipping	1	10	Positive	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Floor	Concrete	Gray	Friction	10	0.04	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W2	Brick	White	Flaking	25	5.2	Positive	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	W3	Brick	White	Efflorescence	20	2.8	Positive	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Door Frame	Metal	Blue	Flaking	1	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Door Frame	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Door	Metal	Blue	None	0	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Door	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Radiator Shield	Metal	Black	None	0	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Pipe	Metal	White	None	0	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Pipe	Metal	White	Flaking	1	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Pipe	Metal	White	Flaking	1	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Radiator Shield	Metal	Tan	Flaking	2	0	Negative	
2	B629002-1	1	108-2	Girl's Restroom across from Classroom 3	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	1	3B	Classroom 3 Vestibule	W1	Plaster	White	Cracking	2	39	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	W2	Plaster	White	Cracking	2	41	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Wainscoting	Wood	White	None	0	11.2	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Chair Rail	Wood	Tan	None	0	16.2	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	3B	Classroom 3 Vestibule	Door Frame	Wood	Tan	Chipping	1	16.1	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Door	Wood	Tan	Flaking	1	13.6	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	W3	Plaster	White	Cracking	1	39.7	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Wainscoting	Wood	White	None	0	13	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Chair Rail	Wood	Tan	None	0	15.4	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Door Frame	Wood	Tan	Chipping	1	14.5	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Door	Wood	Tan	Chipping	1	12.4	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	W4	Plaster	White	Cracking	1	40.6	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	W4	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	1	3B	Classroom 3 Vestibule	Wainscoting	Wood	White	Cracking	1	13.5	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Chair Rail	Wood	Tan	Chipping	1	13.4	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Baseboard	Wood	White	Moisture Damage	3	9.7	Positive	
2	B629002-1	1	3B	Classroom 3 Vestibule	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	3-2	Classroom 3	W1	Plaster	White	Cracking	40	36.4	Positive	
2	B629002-1	1	3-2	Classroom 3	Wainscoting	Wood	Tan	Chipping	1	13.6	Positive	
2	B629002-1	1	3-2	Classroom 3	Chair Rail	Wood	Tan	Chipping	2	18.2	Positive	
2	B629002-1	1	3-2	Classroom 3	Conduit	Metal	White	None	0	14.9	Positive	
2	B629002-1	1	3-2	Classroom 3	Blackboard Frame	Wood	Tan	Chipping	1	13.9	Positive	
2	B629002-1	1	3-2	Classroom 3	Vent Cover	Metal	White	None	0	36.5	Positive	
2	B629002-1	1	3-2	Classroom 3	Vent Cover	Metal	Tan	None	0	12.8	Positive	
2	B629002-1	1	3-2	Classroom 3	W2	Sheetrock	Brown	None	0	0	Negative	
2	B629002-1	1	3-2	Classroom 3	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	3-2	Classroom 3	W3	Plaster	White	Cracking	10	15.6	Positive	
2	B629002-1	1	3-2	Classroom 3	Wainscoting	Wood	White	Cracking	1	12.1	Positive	
2	B629002-1	1	3-2	Classroom 3	Window Sill	Wood	Tan	Cracking	4	2.5	Positive	
2	B629002-1	1	3-2	Classroom 3	Pipe	Metal	Tan	None	0	0	Negative	
2	B629002-1	1	3-2	Classroom 3	Pipe	Metal	Tan	None	0	0	Negative	
2	B629002-1	1	3-2	Classroom 3	Pipe	Metal	Tan	None	0	0	Negative	
2	B629002-1	1	3-2	Classroom 3	Window Frame	Wood	Tan	Cracking	2	13	Positive	
2	B629002-1	1	3-2	Classroom 3	Window Apron	Wood	Tan	Chipping	3	16.4	Positive	
2	B629002-1	1	3-2	Classroom 3	Decorative Column	Wood	Tan	Chipping	1	10.1	Positive	
2	B629002-1	1	3-2	Classroom 3	W4	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	1	3-2	Classroom 3	W4	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	1	3-2	Classroom 3	Chair Rail	Wood	Tan	Chipping	1	15.8	Positive	
2	B629002-1	1	3-2	Classroom 3	Baseboard	Wood	Gray	Friction	4	14.7	Positive	
2	B629002-1	1	3-2	Classroom 3	Baseboard	Wood	Gray	Friction	8	0	Negative	
2	B629002-1	1	3-2	Classroom 3	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	3-2	Classroom 3	Ceiling	Metal	White	Flaking	800	34.2	Positive	
2	B629002-1	1	3-2	Classroom 3	Beam	Wood	Tan	None	0	12.9	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	W1	Brick	White	Flaking	80	21.9	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	Door Frame	Wood	Tan	Chipping	1	11.5	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	Door	Wood	Tan	Chipping	2	10	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	3A	Classroom 3 Closet	Coat Rack	Wood	White	Chipping	1	0.2	Negative	
2	B629002-1	1	3A	Classroom 3 Closet	W2	Wood	White	Cracking	20	0.4	Negative	
2	B629002-1	1	3A	Classroom 3 Closet	Coat Rack	Wood	White	Chipping	1	13	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	W3	Brick	White	Flaking	30	39.2	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	Coat Rack	Wood	White	Chipping	1	13	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	W4	Sheetrock	White	None	0	0	Negative	
2	B629002-1	1	3A	Classroom 3 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	3A	Classroom 3 Closet	Ceiling	Metal	White	Flaking	20	30.9	Positive	
2	B629002-1	1	3A	Classroom 3 Closet	Conduit	Metal	White	None	0	9.7	Positive	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Floor	Concrete	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W1	Brick	White	None	0	9.9	Positive	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W2	Brick	White	Flaking	5	25.6	Positive	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W3	Brick	White	Chipping	5	0.4	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W3	CMU	White	Flaking	5	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W4	CMU	White	Flaking	10	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Pipe	Metal	White	None	0	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	W4	Brick	White	None	0	1.6	Positive	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Radiator Shield	Metal	Black	None	0	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Floor	Concrete	Gray	Chipping	5	0.01	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Ceiling	2' x 4' Ceiling Tile	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Door	Metal	Blue	None	0	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Door	Metal	Gray	Friction	1	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Door Frame	Metal	Blue	Chipping	1	0	Negative	
2	B629002-1	1	109-2	Boy's Restroom across from Classroom 4	Door Frame	Metal	Gray	Flaking	1	0	Negative	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	W1	Plaster	White	None	0	11.1	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Conduit	Metal	White	None	0	10	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Door Frame	Wood	Tan	Chipping	1	8.7	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Door Frame	Metal	Tan	Chipping	1	0.1	Negative	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	W2	Plaster	White	None	0	0.3	Negative	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	W3	Plaster	White	None	0	10.8	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Radiator	Metal	Silver	Chipping	1	5.1	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Conduit	Vinyl	White	None	0	0	Negative	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Frame	Wood	Tan	Chipping	1	4.4	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Sill	Wood	Tan	Chipping	1	9.2	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Apron	Wood	Tan	Chipping	1	7.4	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Decorative Column	Wood	Tan	Chipping	1	7.7	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	W4	Plaster	White	None	0	11.1	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Conduit	Vinyl	White	None	0	0.9	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Radiator	Metal	Silver	None	0	6.4	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Pipe	Metal	Tan	None	0	0	Negative	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Frame	Wood	Tan	None	0	9.3	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Sill	Wood	Tan	Chipping	1	8.5	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Window Apron	Wood	Tan	Chipping	1	8.4	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Decorative Column	Wood	Tan	None	0	9.1	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Ceiling	Metal	White	None	0	7.5	Positive	
2	B629002-1	1	110-2	Teacher's Lounge across from Classroom 5	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	4C	Classroom 4 Vestibule	W1	Plaster	White	Cracking	4	40.2	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	W2	Plaster	White	Cracking	1	39.3	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Wainscoting	Wood	White	Chipping	1	16.7	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Moulding	Wood	Tan	None	0	14.5	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Door Frame	Wood	Tan	Chipping	1	18.78	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Door	Wood	Tan	Chipping	1	15.7	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Pipe Chase Door	Wood	Tan	None	0	15.8	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	W3	Plaster	White	None	0	39	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Wainscoting	Wood	White	Chipping	1	13.6	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Moulding	Wood	Tan	Chipping	1	12.7	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Door Frame	Wood	Tan	Chipping	1	0.01	Negative	
2	B629002-1	1	4C	Classroom 4 Vestibule	W4	Plaster	White	Cracking	1	40	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Wainscoting	Wood	White	Chipping	1	14.6	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Moulding	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	1	4C	Classroom 4 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	4C	Classroom 4 Vestibule	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	4B	Classroom 4	Ceiling	Metal	White	Flaking	150	35.4	Positive	
2	B629002-1	1	4B	Classroom 4	W1	Plaster	White	Cracking	10	39.9	Positive	
2	B629002-1	1	4B	Classroom 4	W1	Plaster	Black	Flaking	2	42.3	Positive	
2	B629002-1	1	4B	Classroom 4	Wainscoting	Wood	White	Cracking	2	11	Positive	
2	B629002-1	1	4B	Classroom 4	Blackboard Frame	Wood	Tan	Chipping	1	15.1	Positive	
2	B629002-1	1	4B	Classroom 4	Moulding	Wood	Tan	Chipping	4	14.3	Positive	
2	B629002-1	1	4B	Classroom 4	Vent	Metal	Tan	None	0	37	Positive	
2	B629002-1	1	4B	Classroom 4	Vent	Metal	White	Chipping	3	11.5	Positive	
2	B629002-1	1	4B	Classroom 4	Conduit	Metal	White	Chipping	1	14.6	Positive	
2	B629002-1	1	4B	Classroom 4	Switch Plate	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	1	4B	Classroom 4	W2	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	1	4B	Classroom 4	W2	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	1	4B	Classroom 4	Moulding	Wood	Brown	Chipping	3	0	Negative	
2	B629002-1	1	4B	Classroom 4	W3	Sheetrock	White	Cracking	3	0	Negative	
2	B629002-1	1	4B	Classroom 4	Wainscoting	Wood	White	Cracking	4	10.6	Positive	
2	B629002-1	1	4B	Classroom 4	Window Frame	Wood	Tan	Chipping	2	12.2	Positive	
2	B629002-1	1	4B	Classroom 4	Window Sill	Wood	Tan	Cracking	4	0.08	Negative	
2	B629002-1	1	4B	Classroom 4	Window Apron	Wood	Tan	Chipping	2	10.4	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	B629002-1	1	4B	Classroom 4	Pipe	Metal	Tan	None	0	0	Negative
2	B629002-1	1	4B	Classroom 4	Decorative Column	Wood	Tan	None	0	11.3	Positive
2	B629002-1	1	4B	Classroom 4	W4	Sheetrock	White	None	0	0	Negative
2	B629002-1	1	4B	Classroom 4	W4	Sheetrock	Tan	None	0	0	Negative
2	B629002-1	1	4B	Classroom 4	Moulding	Wood	Tan	None	0	0	Negative
2	B629002-1	1	4B	Classroom 4	Baseboard	Wood	Brown	Friction	5	0	Negative
2	B629002-1	1	4B	Classroom 4	Baseboard	Wood	Brown	Friction	5	9.8	Positive
2	B629002-1	1	4A	Classroom 4 Closet	W1	Brick	White	Flaking	40	21.1	Positive
2	B629002-1	1	4A	Classroom 4 Closet	Door Frame	Wood	Tan	Chipping	1	14.1	Positive
2	B629002-1	1	4A	Classroom 4 Closet	W2	Wood	White	Cracking	2	15.6	Positive
2	B629002-1	1	4A	Classroom 4 Closet	W3	Brick	White	Flaking	30	39.6	Positive
2	B629002-1	1	4A	Classroom 4 Closet	Coat Rack	Wood	White	Chipping	1	18.2	Positive
2	B629002-1	1	4A	Classroom 4 Closet	Conduit	Metal	White	None	0	4.4	Positive
2	B629002-1	1	4A	Classroom 4 Closet	W4	Sheetrock	White	None	0	0	Negative
2	B629002-1	1	4A	Classroom 4 Closet	Baseboard	Wood	Brown	Friction	8	6.5	Positive
2	B629002-1	1	4A	Classroom 4 Closet	Ceiling	Metal	White	Flaking	20	30	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	W1	Plaster	White	Flaking	10	37.8	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	W2	Sheetrock	White	None	0	0	Negative
2	B629002-1	1	5B	Classroom 5 Vestibule	Wainscoting	Wood	White	Chipping	1	12.7	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Moulding	Wood	Tan	Chipping	1	15.6	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	W3	Plaster	White	None	0	43	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Wainscoting	Wood	White	Chipping	1	16.1	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Moulding	Wood	Tan	Chipping	1	20.5	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Door Frame	Wood	Tan	Chipping	1	12.1	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Door Frame	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	1	5B	Classroom 5 Vestibule	W4	Plaster	White	Cracking	1	39.8	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Wainscoting	Wood	White	None	0	13.8	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Moulding	Wood	Tan	None	0	12.1	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Door Frame	Wood	Tan	Chipping	1	14.6	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Door	Wood	Tan	Flaking	2	11.6	Positive
2	B629002-1	1	5B	Classroom 5 Vestibule	Transom Panel	Sheetrock	Tan	None	0	0	Negative
2	B629002-1	1	5B	Classroom 5 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	5B	Classroom 5 Vestibule	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	5B	Classroom 5 Vestibule	Baseboard	Wood	Brown	Friction	4	3	Positive
2	B629002-1	1	5-2	Classroom 5	W1	Plaster	Pink	Chipping	1	43.4	Positive
2	B629002-1	1	5-2	Classroom 5	Wainscoting	Wood	White	Chipping	2	15	Positive
2	B629002-1	1	5-2	Classroom 5	Door Frame	Wood	White	Chipping	1	15.6	Positive
2	B629002-1	1	5-2	Classroom 5	Blackboard Frame	Wood	White	Cracking	1	14.8	Positive
2	B629002-1	1	5-2	Classroom 5	Vent	Metal	Pink	None	0	31.5	Positive
2	B629002-1	1	5-2	Classroom 5	Vent	Metal	White	Chipping	2	14.8	Positive
2	B629002-1	1	5-2	Classroom 5	Conduit	Metal	Pink	None	0	14.2	Positive
2	B629002-1	1	5-2	Classroom 5	Conduit	Metal	White	None	0	14	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	1	5-2	Classroom 5	W2	Plaster	Pink	Cracking	40	45.8	Positive
2	B629002-1	1	5-2	Classroom 5	Bulletin Board Frame	Wood	White	Chipping	1	13	Positive
2	B629002-1	1	5-2	Classroom 5	Bulletin Board Frame	Wood	White	None	0	13	Positive
2	B629002-1	1	5-2	Classroom 5	Bulletin Board Frame	Wood	White	None	0	13	Positive
2	B629002-1	1	5-2	Classroom 5	Bulletin Board Frame	Wood	White	Chipping	1	13	Positive
2	B629002-1	1	5-2	Classroom 5	Window Frame	Wood	White	Cracking	1	18	Positive
2	B629002-1	1	5-2	Classroom 5	Window Frame	Wood	White	Chipping	1	18	Positive
2	B629002-1	1	5-2	Classroom 5	Window Frame	Wood	White	Cracking	2	18	Positive
2	B629002-1	1	5-2	Classroom 5	Window Sill	Wood	White	Flaking	4	4.6	Positive
2	B629002-1	1	5-2	Classroom 5	Window Sill	Wood	White	Cracking	2	4.6	Positive
2	B629002-1	1	5-2	Classroom 5	Window Sill	Wood	White	Cracking	3	4.6	Positive
2	B629002-1	1	5-2	Classroom 5	Window Apron	Wood	White	None	0	13.5	Positive
2	B629002-1	1	5-2	Classroom 5	Decorative Column	Wood	White	Chipping	1	10.1	Positive
2	B629002-1	1	5-2	Classroom 5	Pipe	Fiberglass	Pink	None	0	0	Negative
2	B629002-1	1	5-2	Classroom 5	W3	Plaster	Pink	Flaking	10	27.2	Positive
2	B629002-1	1	5-2	Classroom 5	Window Frame	Wood	White	Chipping	1	18	Positive
2	B629002-1	1	5-2	Classroom 5	Window Frame	Wood	White	Chipping	1	18	Positive
2	B629002-1	1	5-2	Classroom 5	Window Sill	Wood	White	Cracking	3	15.1	Positive
2	B629002-1	1	5-2	Classroom 5	Window Sill	Wood	White	Cracking	2	15.1	Positive
2	B629002-1	1	5-2	Classroom 5	Bulletin Board Frame	Wood	White	None	0	0.06	Negative
2	B629002-1	1	5-2	Classroom 5	Decorative Column	Wood	White	Chipping	1	17.7	Positive
2	B629002-1	1	5-2	Classroom 5	Pipe	Metal	Pink	None	0	0	Negative
2	B629002-1	1	5-2	Classroom 5	Wainscoting	Wood	White	None	0	14.1	Positive
2	B629002-1	1	5-2	Classroom 5	Moulding	Wood	White	None	0	15.7	Positive
2	B629002-1	1	5-2	Classroom 5	W4	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	1	5-2	Classroom 5	W4	Sheetrock	Pink	Chipping	1	0	Negative
2	B629002-1	1	5-2	Classroom 5	Ceiling	Metal	White	Flaking	400	31.6	Positive
2	B629002-1	1	5-2	Classroom 5	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	1	5-2	Classroom 5	Radiator	Metal	Silver	Flaking	60	0.08	Negative
2	B629002-1	1	5A-B	Classroom 5 Closet	W1	Brick	Tan	Flaking	20	36	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	W1	Brick	Pink	Flaking	30	23.2	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	Door Frame	Wood	Tan	Chipping	1	10.5	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	Door	Wood	Tan	Chipping	1	17	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	Coat Rack	Wood	Tan	Chipping	1	13.9	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	Coat Rack	Wood	Pink	Chipping	1	14.6	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	W2	Sheetrock	Pink	None	0	0	Negative
2	B629002-1	1	5A-B	Classroom 5 Closet	W3	Brick	Tan	Flaking	20	49.5	Positive
2	B629002-1	1	5A-B	Classroom 5 Closet	W3	Brick	Pink	Flaking	30	4.5	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	1	5A-B	Classroom 5 Closet	Coat Rack	Wood	Pink	Chipping	1	14.7	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	W4	Brick	Tan	Flaking	30	49.9	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	W4	Brick	Pink	None	0	25.6	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Window Frame	Wood	Tan	None	0	15.7	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Window Sill	Wood	Tan	None	0	15.4	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Window Apron	Wood	Tan	None	0	7.5	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Coat Rack	Wood	Pink	Chipping	1	13	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Ceiling	Metal	White	Flaking	50	30.6	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Conduit	Metal	Tan	None	0	4	Positive	
2	B629002-1	1	5A-B	Classroom 5 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	5A-B	Classroom 5 Closet	Pipe	Metal	Tan	Flaking	1	9.6	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W1	Brick	White	Flaking	5	37.3	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Conduit	Metal	White	Flaking	1	25.3	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Pipe	Metal	White	Chipping	1	50.8	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Pipe	Metal	White	Chipping	1	50.8	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W2	Brick	White	Flaking	50	10	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W2	Plaster	White	Cracking	60	35.4	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Door Frame	Metal	Brown	Friction	5	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Ceiling	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Door Frame	Metal	Brown	Chipping	1	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W3	Brick	White	Flaking	40	40	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Conduit	Metal	White	None	0	19.8	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Pipe	Metal	White	Flaking	1	15.1	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Door Frame	Metal	Brown	None	5	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Door	Metal	Brown	Friction	1	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Transom Panel	Metal	Brown	None	0	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Stair Stringer	Metal	Brown	None	0	0.01	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Stair Riser	Metal	Brown	Chipping	1	0.01	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Stair Tread	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Radiator Shield	Metal	Brown	None	0	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Handrail	Metal	Brown	Chipping	1	0.13	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Radiator Shield	Metal	Brown	Chipping	1	0	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Handrail	Metal	Brown	Chipping	1	0.13	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W4	Brick	White	Flaking	50	44.9	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	W4	Plaster	White	Chipping	5	47.8	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Radiator	Metal	Gray	None	0	0.2	Negative	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Radiator Shield	Metal	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Frame	Wood	Tan	Chipping	1	14	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Sill	Wood	Tan	Chipping	1	19.6	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Apron	Wood	Tan	None	0	11.9	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Frame	Wood	Tan	Chipping	1	14	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Sill	Wood	Tan	Chipping	1	19.6	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Window Apron	Wood	Tan	None	0	11.9	Positive	
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Conduit	Metal	White	None	0	0.14	Negative	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Fire Alarm	Metal	Red	None	0	1	Positive
2	B629002-1	1	H0201-1	Hallway between Classrooms 1 through 5	Electrical Panel	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Floor	Concrete	Brown	Friction	2	0.05	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	W2	Plaster	White	Flaking	2	4.1	Positive
2	B629002-1	2	S0101	Stairwell on Element 1 side	W3	Plaster	White	Chipping	2	0.4	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Window Frame	Wood	Tan	Cracking	1	11.2	Positive
2	B629002-1	2	S0101	Stairwell on Element 1 side	Window Sill	Wood	Tan	Chipping	1	12.3	Positive
2	B629002-1	2	S0101	Stairwell on Element 1 side	Window Apron	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	S0101	Stairwell on Element 1 side	Radiator Shield	Metal	Tan	None	0	0	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	W4	Plaster	White	Flaking	2	0.14	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Handrail	Metal	Tan	Flaking	30	0.24	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Stair Cage	Metal	Tan	None	0	0.03	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Stair Stringer	Metal	Tan	None	0	0.01	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Stair Riser	Metal	Brown	None	0	0.02	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Stair Tread	Concrete	Brown	None	0	0.06	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Handrail	Metal	Brown	Friction	4	0.05	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Door Frame	Metal	Brown	Chipping	2	0.06	Negative
2	B629002-1	2	S0101	Stairwell on Element 1 side	Door	Metal	Brown	Chipping	2	0.02	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	W1	Plaster	White	Flaking	1	40.6	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Door Frame	Wood	Tan	Chipping	2	12.9	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Wainscoting	Wood	White	Cracking	1	18.4	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Door	Wood	Tan	Flaking	1	9.7	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Door Louver	Metal	Tan	Chipping	1	0.01	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	Transom Panel	Wood	Tan	None	0	11.6	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Conduit	Metal	White	Chipping	1	21.9	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	W2	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	W2	Sheetrock	Tan	Chipping	1	0	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	Door Frame	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	W3	Sheetrock	White	Cracking	2	0	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	Window Frame	Wood	Tan	Chipping	1	5.2	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Window Sill	Wood	Tan	Chipping	2	0.17	Negative
2	B629002-1	2	213-2	Office across from Classroom 6	Window Apron	Wood	Tan	Chipping	1	14.7	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Wainscoting	Wood	White	Chipping	1	11.7	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	W4	Plaster	White	Flaking	100	41.5	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Wainscoting	Wood	White	Chipping	1	16.8	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Chair Rail	Wood	Tan	Chipping	1	6.9	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Door Frame	Wood	Tan	Chipping	1	12.9	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Door	Wood	Tan	Chipping	1	11.3	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Moulding	Wood	Tan	None	1	12.4	Positive
2	B629002-1	2	213-2	Office across from Classroom 6	Baseboard	Wood	Brown	Friction	2	6.3	Positive
2	B629002-1	2	214-2	Storeroom next to Classroom 6	W1	Plaster	White	Cracking	1	14.6	Positive
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Door Frame	Wood	Tan	Chipping	1	16.8	Positive
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Wainscoting	Wood	White	Cracking	1	17.9	Positive
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Window Sill	Wood	Tan	Chipping	1	14.6	Positive

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Window Apron	Wood	Tan	None	0	18.5	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Conduit	Metal	Tan	None	0	0	Negative	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Door	Wood	Tan	Chipping	1	15.1	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	W2	Plaster	White	None	0	51.1	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Stair Stringer	Wood	White	None	0	15.3	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Cabinet	Wood	White	Chipping	1	12.6	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Door	Wood	White	Chipping	1	13.7	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	W3	Plaster	White	Cracking	1	14.6	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Window Frame	Wood	Tan	None	0	17.2	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Window Sill	Wood	Tan	None	0	17.4	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Window Apron	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Wainscoting	Wood	White	Cracking	1	14.8	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Decorative Column	Wood	Tan	None	0	22	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Radiator	Metal	Silver	Chipping	1	6.6	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	W4	Plaster	White	Cracking	3	47.2	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Cabinet	Wood	White	Chipping	2	14.7	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Ceiling	Metal	White	Flaking	1	38.9	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Baseboard	Wood	Brown	Friction	4	17.6	Positive	
2	B629002-1	2	214-2	Storeroom next to Classroom 6	Attic Stair Walls	Plaster	White	Flaking	50	10.1	Positive	
2	B629002-1	2	6-2	Classroom 6	W1	Plaster	White	Cracking	10	9.87	Positive	
2	B629002-1	2	6-2	Classroom 6	Door Frame	Wood	Brown	Chipping	4	8.4	Positive	
2	B629002-1	2	6-2	Classroom 6	Door	Wood	Brown	Chipping	6	9.4	Positive	
2	B629002-1	2	6-2	Classroom 6	Wainscoting	Wood	Tan	None	0	7.89	Positive	
2	B629002-1	2	6-2	Classroom 6	Cork Board Frame	Wood	Tan	None	0	8.51	Positive	
2	B629002-1	2	6-2	Classroom 6	Vent Cover	Metal	Tan	Chipping	1	8.55	Positive	
2	B629002-1	2	6-2	Classroom 6	Conduit	Metal	White	None	0	9.82	Positive	
2	B629002-1	2	6-2	Classroom 6	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	6-2	Classroom 6	W2	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	2	6-2	Classroom 6	Cove Base	Wood	Brown	None	0	0.01	Negative	
2	B629002-1	2	6-2	Classroom 6	W3	Plaster	White	Cracking	5	9.91	Positive	
2	B629002-1	2	6-2	Classroom 6	Chair Rail	Wood	Brown	Chipping	1	6.4	Positive	
2	B629002-1	2	6-2	Classroom 6	Wainscoting	Wood	Tan	Cracking	10	7.16	Positive	
2	B629002-1	2	6-2	Classroom 6	Cork Board Frame	Wood	Brown	None	0	6.4	Positive	
2	B629002-1	2	6-2	Classroom 6	Window Frame	Wood	Brown	Cracking	6	6.25	Positive	
2	B629002-1	2	6-2	Classroom 6	Radiator Shield	Metal	Silver	Flaking	30	0.01	Negative	
2	B629002-1	2	6-2	Classroom 6	Radiator	Metal	Silver	Flaking	5	7.52	Positive	
2	B629002-1	2	6-2	Classroom 6	W4	Plaster	White	Chipping	30	9.69	Positive	
2	B629002-1	2	6-2	Classroom 6	Window Frame	Wood	Brown	Flaking	35	9.13	Positive	
2	B629002-1	2	6-2	Classroom 6	Window Sill	Wood	Brown	Flaking	10	0.33	Negative	
2	B629002-1	2	6-2	Classroom 6	Radiator Shield	Metal	Silver	Flaking	10	0.16	Negative	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	6-2	Classroom 6	Radiator	Metal	Silver	Flaking	10	3.17	Positive	
2	B629002-1	2	6-2	Classroom 6	Post	Wood	Brown	Chipping	10	7.51	Positive	
2	B629002-1	2	6-2	Classroom 6	Ceiling	Metal	White	Flaking	450	8.88	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	W1	Brick	White	Flaking	3	9.95	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Door	Wood	Brown	Cracking	5	7.21	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Door Frame	Wood	Brown	Cracking	6	7.09	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Pipe	Metal	White	None	0	4.72	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	W2	Brick	White	Chipping	1	9.47	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Coat Rack	Wood	White	Cracking	10	7.43	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Window Frame	Wood	Brown	None	0	7.95	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	W3	Brick	White	Cracking	5	3.34	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Conduit	Metal	White	None	0	3.29	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	W4	Brick	White	Cracking	5	4.39	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	W4	Sheetrock	White	Cracking	1	0	Negative	
2	B629002-1	2	6A-2	Classroom 6 Closet	Transom Panel	Wood	Brown	None	0	2.96	Positive	
2	B629002-1	2	6A-2	Classroom 6 Closet	Ceiling	Metal	White	Cracking	16	6.28	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	W1	Plaster	White	Chipping	1	42.3	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	W2	Plaster	White	Cracking	1	44.5	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Wainscoting	Wood	White	None	0	6.1	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Moulding	Wood	Tan	Chipping	1	18	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Door Frame	Wood	Tan	Chipping	1	14.3	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Door	Wood	Tan	Chipping	1	15.1	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	W3	Plaster	White	None	0	46.4	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Wainscoting	Wood	White	Chipping	1	16.4	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Moulding	Wood	Tan	Chipping	1	6.6	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	W4	Plaster	White	None	0	46.4	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Wainscoting	Wood	White	Chipping	1	14.2	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Moulding	Wood	Tan	Chipping	1	12.2	Positive	
2	B629002-1	2	6B	Classroom 6 Vestibule	Baseboard	Wood	Brown	Friction	3	9.3	Positive	
2	B629002-1	2	7	Classroom 7	W1	Plaster	White	Flaking	20	50	Positive	
2	B629002-1	2	7	Classroom 7	Conduit	Metal	White	Chipping	1	29	Positive	
2	B629002-1	2	7	Classroom 7	Door Frame	Wood	Tan	Chipping	1	18.3	Positive	
2	B629002-1	2	7	Classroom 7	Door Frame	Metal	Tan	Chipping	1	0	Negative	
2	B629002-1	2	7	Classroom 7	Wainscoting	Wood	White	Chipping	1	18.9	Positive	
2	B629002-1	2	7	Classroom 7	Blackboard Frame	Wood	Tan	Chipping	1	14.5	Positive	
2	B629002-1	2	7	Classroom 7	Transom Panel	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	2	7	Classroom 7	Vent	Metal	Tan	None	0	51.7	Positive	
2	B629002-1	2	7	Classroom 7	Vent	Metal	White	Chipping	2	7.9	Positive	
2	B629002-1	2	7	Classroom 7	W2	Sheetrock	White	Chipping	2	0	Negative	
2	B629002-1	2	7	Classroom 7	W2	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	2	7	Classroom 7	Moulding	Wood	Brown	None	0	0	Negative	
2	B629002-1	2	7	Classroom 7	W3	Plaster	White	Flaking	20	28.9	Positive	
2	B629002-1	2	7	Classroom 7	Window Frame	Wood	Tan	Cracking	1	13.8	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	7	Classroom 7	Window Sill	Wood	Tan	Chipping	1	14	Positive	
2	B629002-1	2	7	Classroom 7	Window Apron	Wood	Tan	Chipping	2	13.1	Positive	
2	B629002-1	2	7	Classroom 7	Window Frame	Wood	Tan	Flaking	1	13.8	Positive	
2	B629002-1	2	7	Classroom 7	Window Sill	Wood	Tan	Chipping	1	14	Positive	
2	B629002-1	2	7	Classroom 7	Window Apron	Wood	Tan	None	0	13.1	Positive	
2	B629002-1	2	7	Classroom 7	Wainscoting	Wood	White	Chipping	1	12.1	Positive	
2	B629002-1	2	7	Classroom 7	Radiator Shield	Metal	Gray	None	0	0	Negative	
2	B629002-1	2	7	Classroom 7	Radiator	Metal	Silver	Flaking	5	7.1	Positive	
2	B629002-1	2	7	Classroom 7	Decorative Column	Wood	Tan	Chipping	5	20.5	Positive	
2	B629002-1	2	7	Classroom 7	Moulding	Wood	Tan	None	0	9.3	Positive	
2	B629002-1	2	7	Classroom 7	W4	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	2	7	Classroom 7	W4	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	2	7	Classroom 7	Moulding	Wood	Brown	None	0	0	Negative	
2	B629002-1	2	7	Classroom 7	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	2	7	Classroom 7	Moulding	Plaster	Tan	None	0	20.6	Positive	
2	B629002-1	2	7	Classroom 7	Wainscoting	Wood	White	Flaking	30	52.3	Positive	
2	B629002-1	2	7	Classroom 7	Ceiling	Metal	White	Flaking	250	28.2	Positive	
2	B629002-1	2	7	Classroom 7	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	7B	Classroom 7 Vestibule	W1	Plaster	White	Chipping	1	40.3	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	7B	Classroom 7 Vestibule	W2	Plaster	White	Cracking	2	42.6	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Wainscoting	Wood	White	Chipping	1	11.7	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Moulding	Wood	Tan	Chipping	1	9.8	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	W3	Plaster	White	Cracking	1	44.7	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Wainscoting	Wood	White	Cracking	1	11	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Moulding	Wood	Tan	Chipping	1	13.2	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Door Frame	Wood	Tan	Chipping	1	11.8	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	W4	Plaster	White	Flaking	1	41.9	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Wainscoting	Wood	White	Cracking	1	13	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Moulding	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Door Frame	Wood	White	Chipping	1	9.7	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Door	Wood	White	Chipping	1	8.6	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Transom Panel	Wood	White	None	0	8.6	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Baseboard	Wood	Brown	Friction	5	8.2	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Ceiling	Metal	White	Flaking	40	30.3	Positive	
2	B629002-1	2	7B	Classroom 7 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	7A	Classroom 7 Closet	W1	Brick	White	Flaking	20	20	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Door	Wood	Tan	Chipping	1	12.9	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Door Frame	Wood	Tan	Chipping	1	12.5	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Coat Rack	Wood	White	Chipping	1	0.09	Negative	
2	B629002-1	2	7A	Classroom 7 Closet	W2	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	2	7A	Classroom 7 Closet	W3	Brick	White	Cracking	25	39.4	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Coat Rack	Wood	White	Flaking	2	11.7	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	7A	Classroom 7 Closet	Conduit	Metal	White	Chipping	1	7.7	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	W4	Wood	White	Cracking	10	10.6	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Coat Rack	Wood	White	Chipping	1	16.7	Positive	
2	B629002-1	2	7A	Classroom 7 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	7A	Classroom 7 Closet	Ceiling	Metal	White	Flaking	50	38.2	Positive	
2	B629002-1	2	8	Classroom 8	W1	Plaster	White	Cracking	30	46.6	Positive	
2	B629002-1	2	8	Classroom 8	Door Frame	Wood	Tan	Chipping	1	15.4	Positive	
2	B629002-1	2	8	Classroom 8	Door	Wood	Tan	Chipping	1	17.8	Positive	
2	B629002-1	2	8	Classroom 8	Transom Panel	Wood	Tan	Chipping	1	15.4	Positive	
2	B629002-1	2	8	Classroom 8	Wainscoting	Wood	White	Cracking	1	13.6	Positive	
2	B629002-1	2	8	Classroom 8	Blackboard Ledge	Wood	Tan	Chipping	1	15	Positive	
2	B629002-1	2	8	Classroom 8	Blackboard Ledge	Wood	Tan	Chipping	1	12.6	Positive	
2	B629002-1	2	8	Classroom 8	Vent	Metal	Tan	None	0	41	Positive	
2	B629002-1	2	8	Classroom 8	Vent	Metal	White	Chipping	1	6.4	Positive	
2	B629002-1	2	8	Classroom 8	W2	Sheetrock	White	Chipping	10	0	Negative	
2	B629002-1	2	8	Classroom 8	W2	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	2	8	Classroom 8	W3	Plaster	White	Flaking	10	39.9	Positive	
2	B629002-1	2	8	Classroom 8	Wainscoting	Wood	Tan	None	0	17.1	Positive	
2	B629002-1	2	8	Classroom 8	Conduit	Metal	White	None	0	0	Negative	
2	B629002-1	2	8	Classroom 8	Window Frame	Wood	Tan	Cracking	1	13.6	Positive	
2	B629002-1	2	8	Classroom 8	Window Sill	Wood	Tan	Cracking	1	15.7	Positive	
2	B629002-1	2	8	Classroom 8	Window Apron	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	2	8	Classroom 8	Window Frame	Wood	Tan	Chipping	2	13.6	Positive	
2	B629002-1	2	8	Classroom 8	Window Sill	Wood	Tan	Cracking	3	15.7	Positive	
2	B629002-1	2	8	Classroom 8	Window Apron	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	2	8	Classroom 8	Decorative Column	Wood	Tan	Chipping	1	20	Positive	
2	B629002-1	2	8	Classroom 8	Radiator	Metal	Silver	Flaking	10	8.8	Positive	
2	B629002-1	2	8	Classroom 8	Radiator	Metal	Silver	Flaking	10	8.8	Positive	
2	B629002-1	2	8	Classroom 8	Chair Rail	Wood	Brown	None	0	13.7	Positive	
2	B629002-1	2	8	Classroom 8	W4	Sheetrock	White	Chipping	1	0	Negative	
2	B629002-1	2	8	Classroom 8	W4	Sheetrock	Tan	None	0	0	Negative	
2	B629002-1	2	8	Classroom 8	Moulding	Plaster	Tan	None	0	16.5	Positive	
2	B629002-1	2	8	Classroom 8	Ceiling	Metal	White	Flaking	350	35.9	Positive	
2	B629002-1	2	8	Classroom 8	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	8	Classroom 8	Wainscoting	Wood	White	Flaking	10	36.2	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	W1	Brick	White	Flaking	5	23.1	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	Door Frame	Wood	Tan	Chipping	2	15.6	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	Door	Wood	Tan	Chipping	2	11.7	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	Conduit	Metal	White	None	0	6.4	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	W2	Wood	White	Cracking	30	6.4	Positive	
2	B629002-1	2	8A	Classroom 8 Closet	Coat Rack	Wood	White	Chipping	1	13.5	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128						
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
2	B629002-1	2	8A	Classroom 8 Closet	W3	Brick	White	Flaking	5	23.1	Positive
2	B629002-1	2	8A	Classroom 8 Closet	Conduit	Metal	White	Chipping	1	15.6	Positive
2	B629002-1	2	8A	Classroom 8 Closet	W4	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	2	8A	Classroom 8 Closet	Baseboard	Wood	Brown	Friction	3	17.4	Positive
2	B629002-1	2	8A	Classroom 8 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	2	8A	Classroom 8 Closet	Ceiling	Metal	White	Flaking	50	35.2	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	W1	Plaster	White	Cracking	1	47.3	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	W2	Sheetrock	White	Cracking	6	42.7	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Door Frame	Wood	Tan	Chipping	1	13.5	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Door	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Wainscoting	Wood	White	None	0	12.5	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Moulding	Wood	Tan	None	0	14.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	W3	Plaster	White	None	0	42.3	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Door Frame	Wood	Tan	Chipping	1	13.02	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Door Frame	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Wainscoting	Wood	White	None	0	14.3	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Moulding	Wood	Tan	Chipping	1	15.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	W4	Plaster	White	None	0	44.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Wainscoting	Wood	White	None	0	13.5	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Moulding	Wood	Tan	Chipping	1	18.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Baseboard	Wood	Gray	Friction	1	7.6	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	2	8B	Classroom 8 Vestibule	Ceiling	Metal	White	Flaking	25	36.7	Positive
2	B629002-1	2	8B	Classroom 8 Vestibule	W4	Sheetrock	White	None	0	0	Negative
2	B629002-1	2	9	Classroom 9	W1	Plaster	White	Flaking	15	41.2	Positive
2	B629002-1	2	9	Classroom 9	Door Frame	Wood	Tan	Chipping	1	13.2	Positive
2	B629002-1	2	9	Classroom 9	Wainscoting	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	9	Classroom 9	Moulding	Wood	Tan	Chipping	1	15.6	Positive
2	B629002-1	2	9	Classroom 9	Blackboard Frame	Wood	Tan	Chipping	1	16.6	Positive
2	B629002-1	2	9	Classroom 9	Vent	Metal	White	None	0	44.6	Positive
2	B629002-1	2	9	Classroom 9	Vent	Metal	Tan	Chipping	2	19.5	Positive
2	B629002-1	2	9	Classroom 9	W2	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	2	9	Classroom 9	W2	Sheetrock	Tan	Chipping	1	0	Negative
2	B629002-1	2	9	Classroom 9	W3	Plaster	White	Flaking	10	40.6	Positive
2	B629002-1	2	9	Classroom 9	Wainscoting	Wood	Tan	Chipping	1	18.9	Positive
2	B629002-1	2	9	Classroom 9	Moulding	Wood	Tan	Chipping	1	15.6	Positive
2	B629002-1	2	9	Classroom 9	Window Frame	Wood	Tan	Cracking	1	15.7	Positive
2	B629002-1	2	9	Classroom 9	Window Sill	Wood	Tan	Chipping	4	14.9	Positive
2	B629002-1	2	9	Classroom 9	Window Apron	Wood	Tan	Chipping	1	12.3	Positive
2	B629002-1	2	9	Classroom 9	Window Frame	Wood	Tan	Cracking	1	15.7	Positive
2	B629002-1	2	9	Classroom 9	Window Sill	Wood	Tan	Chipping	1	14.9	Positive
2	B629002-1	2	9	Classroom 9	Window Apron	Wood	Tan	Chipping	1	12.3	Positive
2	B629002-1	2	9	Classroom 9	Radiator	Metal	Silver	Flaking	5	8.4	Positive

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)
2	B629002-1	2	9	Classroom 9	Radiator	Metal	Silver	Flaking	15	8.4	Positive
2	B629002-1	2	9	Classroom 9	Decorative Column	Wood	Tan	Chipping	1	10.2	Positive
2	B629002-1	2	9	Classroom 9	Chair Rail	Wood	Tan	Chipping	1	20.9	Positive
2	B629002-1	2	9	Classroom 9	W4	Sheetrock	White	None	0	0	Negative
2	B629002-1	2	9	Classroom 9	W4	Sheetrock	Tan	None	0	0	Negative
2	B629002-1	2	9	Classroom 9	Baseboard	Wood	Brown	Friction	5	7.6	Positive
2	B629002-1	2	9	Classroom 9	Ceiling	Metal	White	Flaking	700	37.9	Positive
2	B629002-1	2	9	Classroom 9	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	2	9B	Classroom 9 Vestibule	W1	Plaster	White	Chipping	2	15.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	W2	Plaster	White	Cracking	2	37.4	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Wainscoting	Wood	White	Chipping	1	24.4	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Moulding	Wood	Tan	Chipping	1	17.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Door Frame	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Door	Wood	Tan	Chipping	5	12.3	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Pipe Chase Door	Wood	Tan	Chipping	5	14.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	W3	Plaster	White	None	0	41.3	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Wainscoting	Wood	White	Cracking	1	18.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Moulding	Wood	Tan	Chipping	1	17.6	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Door Frame	Wood	Tan	Chipping	1	14.5	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Door Frame	Metal	Tan	Chipping	1	0	Negative
2	B629002-1	2	9B	Classroom 9 Vestibule	W4	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	2	9B	Classroom 9 Vestibule	W4	Plaster	White	Chipping	1	42.3	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Wainscoting	Wood	White	Cracking	1	15	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Moulding	Wood	Tan	Chipping	1	13	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Baseboard	Wood	Brown	Friction	1	7	Positive
2	B629002-1	2	9B	Classroom 9 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	2	9B	Classroom 9 Vestibule	Ceiling	Metal	White	Flaking	5	35.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	W1	Brick	Tan	Flaking	2	30.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Door	Wood	Tan	Chipping	1	15.7	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Door Frame	Wood	Tan	Chipping	1	12.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Coat Rack	Wood	White	Chipping	1	13.4	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Transom Panel	Wood	Tan	Chipping	1	15.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	W2	Wood	White	Cracking	5	8.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	W3	Brick	White	Flaking	2	13.9	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Conduit	Metal	White	Chipping	1	2.3	Positive
2	B629002-1	2	9A	Classroom 9 Closet	W4	Sheetrock	White	Chipping	1	0	Negative
2	B629002-1	2	9A	Classroom 9 Closet	Baseboard	Wood	Brown	Friction	1	6.7	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Ceiling	Metal	White	Flaking	80	34.6	Positive
2	B629002-1	2	9A	Classroom 9 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
2	B629002-1	2	10B	Classroom 10 Vestibule	Ceiling	Metal	White	Flaking	15	30.1	Positive
2	B629002-1	2	10B	Classroom 10 Vestibule	W1	Plaster	White	Chipping	1	46.1	Positive
2	B629002-1	2	10B	Classroom 10 Vestibule	W2	Sheetrock	White	Chipping	1	0	Negative

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	2	10B	Classroom 10 Vestibule	Wainscoting	Wood	White	Chipping	1	20.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Moulding	Wood	Tan	Chipping	1	14.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	W3	Plaster	White	Flaking	2	40.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Wainscoting	Wood	White	Chipping	1	12.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Moulding	Wood	Tan	Chipping	1	15.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Door Frame	Wood	Tan	Chipping	1	12.6	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Door	Wood	Tan	Chipping	2	14.1	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	W4	Plaster	White	None	0	42.9	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Wainscoting	Wood	White	None	1	16.9	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Moulding	Wood	Tan	Chipping	1	15.2	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Baseboard	Wood	Brown	Friction	5	8.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Door Frame	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Door	Wood	Tan	Chipping	2	13.2	Positive	
2	B629002-1	2	10B	Classroom 10 Vestibule	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	10	Classroom 10	W1	Plaster	White	Flaking	60	40.6	Positive	
2	B629002-1	2	10	Classroom 10	Conduit	Metal	White	None	0	15.4	Positive	
2	B629002-1	2	10	Classroom 10	Vent	Metal	White	None	0	12.3	Positive	
2	B629002-1	2	10	Classroom 10	Vent	Metal	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	10	Classroom 10	Blackboard Frame	Wood	Tan	Chipping	1	12.6	Positive	
2	B629002-1	2	10	Classroom 10	Wainscoting	Wood	White	Chipping	1	15.3	Positive	
2	B629002-1	2	10	Classroom 10	Moulding	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	2	10	Classroom 10	Door Frame	Wood	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	10	Classroom 10	Transom Panel	Wood	Tan	None	0	20.3	Positive	
2	B629002-1	2	10	Classroom 10	W2	Plaster	White	Flaking	60	40.4	Positive	
2	B629002-1	2	10	Classroom 10	Wainscoting	Wood	White	None	0	19.6	Positive	
2	B629002-1	2	10	Classroom 10	Moulding	Wood	Tan	Chipping	1	18.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Frame	Wood	Tan	Cracking	1	17.5	Positive	
2	B629002-1	2	10	Classroom 10	Window Sill	Wood	Tan	Flaking	4	14.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Apron	Wood	Tan	Cracking	1	12.9	Positive	
2	B629002-1	2	10	Classroom 10	Window Frame	Wood	Tan	Chipping	1	17.5	Positive	
2	B629002-1	2	10	Classroom 10	Window Sill	Wood	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Apron	Wood	Tan	Chipping	1	12.9	Positive	
2	B629002-1	2	10	Classroom 10	Window Frame	Wood	Tan	None	0	17.5	Positive	
2	B629002-1	2	10	Classroom 10	Window Sill	Wood	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Apron	Wood	Tan	Chipping	1	12.9	Positive	
2	B629002-1	2	10	Classroom 10	Decorative Column	Wood	Tan	Chipping	1	21.3	Positive	
2	B629002-1	2	10	Classroom 10	Bulletin Board Frame	Wood	Tan	Chipping	1	11.1	Positive	
2	B629002-1	2	10	Classroom 10	Radiator	Metal	Silver	Flaking	10	6.9	Positive	
2	B629002-1	2	10	Classroom 10	W3	Plaster	White	Flaking	2	40.3	Positive	
2	B629002-1	2	10	Classroom 10	Wainscoting	Wood	White	None	0	12.3	Positive	
2	B629002-1	2	10	Classroom 10	Moulding	Wood	Tan	Chipping	1	18.9	Positive	

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
2	B629002-1	2	10	Classroom 10	Window Frame	Wood	Tan	None	0	11.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Sill	Wood	Tan	Chipping	1	15.7	Positive	
2	B629002-1	2	10	Classroom 10	Window Apron	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	2	10	Classroom 10	Window Frame	Wood	Tan	None	0	11.6	Positive	
2	B629002-1	2	10	Classroom 10	Window Sill	Wood	Tan	Chipping	1	15.7	Positive	
2	B629002-1	2	10	Classroom 10	Window Apron	Wood	Tan	Chipping	1	16.8	Positive	
2	B629002-1	2	10	Classroom 10	Bulletin Board Frame	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	2	10	Classroom 10	Decorative Column	Wood	Tan	Chipping	1	20.8	Positive	
2	B629002-1	2	10	Classroom 10	Conduit	Metal	White	None	0	10.6	Positive	
2	B629002-1	2	10	Classroom 10	W4	Sheetrock	White	Chipping	2	0	Negative	
2	B629002-1	2	10	Classroom 10	W4	Sheetrock	Tan	Chipping	1	0	Negative	
2	B629002-1	2	10	Classroom 10	Chair Rail	Wood	Tan	Chipping	2	17.8	Positive	
2	B629002-1	2	10	Classroom 10	Baseboard	Wood	Brown	Friction	5	2.8	Positive	
2	B629002-1	2	10	Classroom 10	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	10A	Classroom 10 Closet	W1	Brick	White	Flaking	5	42.3	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Door	Wood	Tan	Chipping	1	15.6	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Door Frame	Wood	Tan	Chipping	1	13.6	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Coat Rack	Wood	White	Cracking	1	8.9	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Transom Panel	Wood	Tan	Cracking	1	12.6	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	W2	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	10A	Classroom 10 Closet	W3	Brick	White	Flaking	5	40.3	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Conduit	Metal	White	None	0	16.3	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	W4	Brick	White	Flaking	1	41.3	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Baseboard	Wood	Brown	Friction	2	13.6	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Ceiling	Metal	White	Flaking	20	32.5	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	10A	Classroom 10 Closet	Window Frame	Wood	Tan	None	0	21.3	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Window Sill	Wood	Tan	Chipping	1	19.6	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Window Apron	Wood	Tan	None	0	21.7	Positive	
2	B629002-1	2	10A	Classroom 10 Closet	Pipe	Metal	White	None	0	8	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	W1	Plaster	White	Cracking	1	14.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Door Frame	Wood	Tan	Chipping	1	17.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Door	Wood	Tan	Chipping	2	16.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Conduit	Metal	Tan	None	0	12.4	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Wainscoting	Wood	White	Chipping	1	13.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Sill	Wood	Tan	Chipping	3	14.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Apron	Wood	Tan	Chipping	2	18.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Frame	Wood	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	W2	Plaster	White	Cracking	10	33.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Wainscoting	Wood	White	Chipping	1	17.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Moulding	Wood	Tan	Chipping	1	12.3	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Conduit	Metal	White	None	0	0	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Door Frame	Wood	Tan	Chipping	1	17.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	W3	Plaster	White	Cracking	10	43.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Wainscoting	Wood	White	Chipping	1	16.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Moulding	Wood	Tan	Chipping	1	14.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Sill	Wood	Tan	Chipping	1	25.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Apron	Wood	Tan	Chipping	1	20.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Window Frame	Wood	Tan	Chipping	1	20.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Radiator	Metal	Silver	Flaking	5	0.06	Negative	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Decorative Column	Wood	Tan	Chipping	1	19.1	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	W4	Plaster	White	Cracking	10	40.9	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Wainscoting	Wood	White	Chipping	1	15.2	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Moulding	Wood	Tan	Chipping	1	19.6	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Baseboard	Wood	White	Friction	4	6.2	Positive	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	211-2	Storeroom next to Classroom 10	Ceiling	Metal	White	Flaking	25	36	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	W1	Plaster	White	Cracking	15	40.6	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Conduit	Metal	White	None	0	33	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Door Frame	Wood	Tan	Chipping	2	9.6	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Door Frame	Wood	Tan	Chipping	1	9.6	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Door	Wood	Tan	Chipping	1	9.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Door	Wood	Tan	Chipping	1	9.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Wainscoting	Wood	White	Cracking	1	12.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Moulding	Wood	Tan	Chipping	1	14.6	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	W2	Plaster	White	Cracking	20	42.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Wainscoting	Wood	White	None	0	16.7	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Moulding	Wood	Tan	Chipping	1	17.5	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	W3	Plaster	White	None	0	42.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Wainscoting	Wood	White	Cracking	1	12.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Moulding	Wood	Tan	Chipping	1	17.9	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Frame	Wood	Tan	Cracking	1	14.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Sill	Wood	Tan	Flaking	5	13.2	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Apron	Wood	Tan	Chipping	1	11.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Frame	Wood	Tan	None	0	14.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Sill	Wood	Tan	Flaking	2	13.2	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Apron	Wood	Tan	None	0	11.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Decorative Column	Wood	Tan	None	0	20.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Radiator	Metal	Silver	Flaking	2	6.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	W4	Plaster	White	Cracking	10	40.6	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Wainscoting	Wood	White	Chipping	1	15.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Moulding	Wood	Tan	Chipping	1	16.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Radiator	Metal	Silver	Chipping	2	6.2	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Sill	Wood	Tan	Cracking	5	8.3	Positive	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Frame	Wood	Tan	Chipping	1	9.3	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Window Apron	Wood	Tan	None	0	10.9	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Decorative Column	Wood	Tan	None	0	18.9	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Baseboard	Wood	Black	Friction	5	6.7	Positive	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	010B	Teacher's Lounge across from Classroom 10	Ceiling	Metal	White	Flaking	10	36.9	Positive	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Floor	Concrete	Brown	None	0	0.05	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	W2	Plaster	White	Efflorescence	5	0	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	W3	Plaster	White	Efflorescence	25	0	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Window Frame	Wood	Tan	Chipping	1	21.3	Positive	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Window Sill	Wood	Tan	Cracking	3	17.9	Positive	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Window Apron	Wood	Tan	Chipping	1	18.3	Positive	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Radiator Shield	Metal	Tan	None	0	0	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	W4	Plaster	White	Cracking	6	40.9	Positive	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Handrail	Metal	Tan	Flaking	15	0	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Stair Cage	Metal	Tan	None	0	0.01	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Stair Stringer	Metal	Tan	None	0	0.02	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Stair Riser	Metal	Brown	None	0	0.04	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Stair Tread	Concrete	Brown	None	0	0.01	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Handrail	Metal	Brown	Chipping	1	0.04	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Door Frame	Metal	Brown	Chipping	2	0.05	Negative	
2	B629002-1	2	S0102	Stairwell on Monastery Ave side	Door	Metal	Brown	Chipping	4	0.02	Negative	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	W1	Wood	White	Chipping	1	12.6	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Frame	Wood	White	Chipping	1	13.5	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	W2	Plaster	White	Chipping	3	40.6	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Pipe	Metal	White	None	0	33.3	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Ceiling	Metal	White	Flaking	500	36.5	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	W4	Plaster	White	Efflorescence	25	45.9	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	W3	Wood	White	Chipping	1	13.6	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Frame	Wood	White	Chipping	1	17.9	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Conduit	Metal	White	None	0	11.1	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Radiator	Metal	Silver	Flaking	4	5.9	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Radiator Shield	Metal	Silver	Flaking	1	1.1	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Frame	Wood	Tan	Cracking	2	7.9	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Sill	Wood	Tan	Cracking	1	6.6	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Apron	Wood	Tan	None	0	0	Negative	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Frame	Wood	Tan	Cracking	1	7.9	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Sill	Wood	Tan	Chipping	1	6.6	Positive	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Window Apron	Wood	Tan	Chipping	1	0	Negative	
2	B629002-1	2	H0201-2	Hallway between Classrooms 6 through 10	Radiator	Metal	Silver	Flaking	5	5.9	Positive	
3	B629001-2	B	6-3	Gymnasium	W1	Brick	White	Cracking	0	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Door Frame	Metal	Blue	Chipping	2	0	Negative	

				Dates: 1/10-03/07/2024	Lead-Safe Certification Assessment Report							
				Inspector Name and Certificate Number: Brandon Dunning #007031	AMY Northwest @ Levering Middle School (6-8)							
				Inspection Company: Synertech	6000 Ridge Avenue, Philadelphia, PA 19128							
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
3	B629001-2	B	6-3	Gymnasium	Conduit	Vinyl	White	None	0	1.8	Positive	
3	B629001-2	B	6-3	Gymnasium	Pipe	Metal	White	Chipping	1	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Pipe	Metal	Blue	Chipping	2	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Pipe Chase Door	Metal	Blue	Chipping	1	5	Positive	
3	B629001-2	B	6-3	Gymnasium	Radiator	Metal	Silver	Flaking	32	5.1	Positive	
3	B629001-2	B	6-3	Gymnasium	Radiator Grate	Metal	Silver	None	0	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Radiator Shield	Metal	Silver	Flaking	32	5.1	Positive	
3	B629001-2	B	6-3	Gymnasium	W2	Brick	White	None	0	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Door	Wood	Brown	Chipping	1	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Backboard	Wood	White	Chipping	6	2.3	Positive	
3	B629001-2	B	6-3	Gymnasium	W3	Brick	White	Flaking	85	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Pipe Chase Door	Metal	Blue	Chipping	2	0.8	Positive	
3	B629001-2	B	6-3	Gymnasium	Pipe	Metal	White	Chipping	2	0.3	Negative	
3	B629001-2	B	6-3	Gymnasium	Conduit	Metal	White	None	0	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Radiator	Metal	Silver	None	0	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Radiator Grate	Metal	Silver	None	0	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Radiator Shield	Metal	Silver	Flaking	32	1.2	Positive	
3	B629001-2	B	6-3	Gymnasium	W4	Brick	White	Cracking	12	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Door Frame	Metal	Blue	Chipping	1	0.1	Negative	
3	B629001-2	B	6-3	Gymnasium	Door	Metal	Blue	Chipping	3	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Transom Panel	Metal	Blue	Flaking	1	0.9	Positive	
3	B629001-2	B	6-3	Gymnasium	Push Bar	Metal	Gray	Chipping	2	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Conduit	Metal	White	None	0	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Backboard	Wood	White	Chipping	4	3.9	Positive	
3	B629001-2	B	6-3	Gymnasium	Ceiling	Plaster	White	Efflorescence	125	9.6	Positive	
3	B629001-2	B	6-3	Gymnasium	Conduit	Metal	White	None	0	0	Negative	
3	B629001-2	B	6-3	Gymnasium	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
3	B629001-2	B	6-3	Gymnasium	Trench Cover	Metal	Gray	Chipping	25	1.5	Positive	
3	B629001-2	B	6B	Gym Storage Closet	W1	Brick	White	None	0	0	Negative	
3	B629001-2	B	6B	Gym Storage Closet	W2	Brick	White	Cracking	4	0	Negative	
3	B629001-2	B	6B	Gym Storage Closet	W3	Brick	White	Cracking	2	0	Negative	
3	B629001-2	B	6B	Gym Storage Closet	W4	Brick	White	Flaking	2	0	Negative	
3	B629001-2	B	6B	Gym Storage Closet	Ceiling	Concrete	White	None	0	0	Negative	
3	B629001-2	B	6B	Gym Storage Closet	Duct	Metal	White	None	0	1.4	Positive	
3	B629001-2	B	6B	Gym Storage Closet	Floor	12" x 12" Floor Tile	Unpainted	N/A	N/A	N/A	N/A	
3	B629001-2	B	6A-3	Gym Teacher's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	B	6A-3	Gym Teacher's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	B	6A-3	Gym Teacher's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	B	6A-3	Gym Teacher's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	B	6A-3	Gym Teacher's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	B	6A-3	Gym Teacher's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	1	100	Auditorium	W1	CMU	White	Cracking	4	0	Negative	

AMY @ Levering Lead Safe Assessment Sheet XRF

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report					
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)					
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128					
Element	BldgElmt ID	Floor	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/negative)
3	B629001-2	1	100	Auditorium	Conduit	Metal	Tan	None	0	0.1	Negative
3	B629001-2	1	100	Auditorium	W2	CMU	White	None	0	0.1	Negative
3	B629001-2	1	100	Auditorium	W3	CMU	White	None	0	0	Negative
3	B629001-2	1	100	Auditorium	Ceiling	1' x 1' Ceiling Tiles	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	1	100	Auditorium	Floor	9" x 9" Floor Tile	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	1	100A	Auditorium Stage	W1	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A	Auditorium Stage	W2	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A	Auditorium Stage	W3	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A	Auditorium Stage	W4	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A	Auditorium Stage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A	Auditorium Stage	Floor	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A-1	Auditorium Stage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100A-1	Auditorium Stage	Door	Metal	Blue	Chipping	2	0.1	Negative
3	B629001-2	1	100A-1	Auditorium Stage	Door Frame	Metal	Blue	Chipping	1	0.1	Negative
3	B629001-2	1	100A-1	Auditorium Stage	W2	CMU	Blue	Cracking	2	0.1	Negative
3	B629001-2	1	100A-1	Auditorium Stage	W3	CMU	Blue	Cracking	4	0	Negative
3	B629001-2	1	100A-1	Auditorium Stage	W4	CMU	Blue	Cracking	20	0.1	Negative
3	B629001-2	1	100A-1	Auditorium Stage	Floor	Wood	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	1	100B	Auditorium Rear Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100B	Auditorium Rear Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100B	Auditorium Rear Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100B	Auditorium Rear Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100B	Auditorium Rear Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	100B	Auditorium Rear Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	1	H102	Hallway alongside Auditorium	W1	CMU	White	None	0	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Conduit	Metal	White	None	0	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	W2	CMU	White	Cracking	2	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Radiator	Metal	Brown	None	0	0.1	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Door Frame	Metal	Brown	Chipping	2	0.1	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Door	Metal	Brown	Flaking	3	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	W3	CMU	White	None	0	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	W4	CMU	White	Cracking	2	0	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Conduit	Metal	White	None	0	0.1	Negative
3	B629001-2	1	H102	Hallway alongside Auditorium	Baseboard	Ceramic	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	1	H102	Hallway alongside Auditorium	Ceiling	Concrete	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	1	H102	Hallway alongside Auditorium	Beam	Metal	Black	None	0	6.1	Positive
3	B629001-2	1	H102	Hallway alongside Auditorium	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A
3	B629001-2	A	AT3	Attic Above Auditorium	W1	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	A	AT3	Attic Above Auditorium	W2	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	A	AT3	Attic Above Auditorium	W3	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	A	AT3	Attic Above Auditorium	W4	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	A	AT3	Attic Above Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	A	AT3	Attic Above Auditorium	Floor	No Access	No Access	No Access	No Access	No Access	No Access
3	B629001-2	C	CS3	Crawl Space below Auditorium	W1	No Access	No Access	No Access	No Access	No Access	No Access

				Dates: 1/10-03/07/2024		Lead-Safe Certification Assessment Report						
				Inspector Name and Certificate Number: Brandon Dunning #007031		AMY Northwest @ Levering Middle School (6-8)						
				Inspection Company: Synertech		6000 Ridge Avenue, Philadelphia, PA 19128						
E l e m e n t	BldgElmt ID	F l o o r	Space #	On-Site Room Name	Component	Substrate Material	Paint Color	Description of Damage	Damage Quantity (sf)	XRF Reading (mg/cm2)	XRF (positive/ negative)	
3	B629001-2	C	CS3	Crawl Space below Auditorium	W2	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	C	CS3	Crawl Space below Auditorium	W3	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	C	CS3	Crawl Space below Auditorium	W4	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	C	CS3	Crawl Space below Auditorium	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	
3	B629001-2	C	CS3	Crawl Space below Auditorium	Floor	No Access	No Access	No Access	No Access	No Access	No Access	
2	B629002-1	2	213-2	Office across from Classroom 6	Ceiling	Metal	White	Flaking	2	41.5	Positive	
2	B629002-1	2	213-2	Office across from Classroom 6	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	213-A	213 Book Closet	W2	Plaster	White	Cracking	2	24.4	Positive	
2	B629002-1	2	213-A	213 Book Closet	W3	Plaster	White	Cracking	10	10.1	Positive	
2	B629002-1	2	213-A	213 Book Closet	W4	Plaster	White	Cracking	6	28.2	Positive	
2	B629002-1	2	213-A	213 Book Closet	Ceiling	Metal	White	Cracking	4	26.7	Positive	
2	B629002-1	2	213-A	213 Book Closet	Floor	Vinyl	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	213-A	213 Book Closet	Baseboard	Wood	White	Friction	2	0.13	Negative	
2	B629002-1	2	213-B	213 Costodial Closet	W1	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	213-B	213 Costodial Closet	W2	Plaster	White	Cracking	1	44.3	Positive	
2	B629002-1	2	213-B	213 Costodial Closet	W3	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	213-B	213 Costodial Closet	W4	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	213-B	213 Costodial Closet	Duct	Metal	White	Chipping	1	0	Negative	
2	B629002-1	2	213-B	213 Costodial Closet	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	
2	B629002-1	2	213-B	213 Costodial Closet	Ceiling	Metal	White	Flaking	1	36.2	Positive	
2	B629002-1	2	213-C	213 Bathroom	W1	Sheetrock	White	None	0	0	Negative	
2	B629002-1	2	213-C	213 Bathroom	W2	Plaster	White	Flaking	1	45.5	Positive	
2	B629002-1	2	213-C	213 Bathroom	W3	Plaster	White	Cracking	1	46.6	Positive	
2	B629002-1	2	213-C	213 Bathroom	Window Frame	Wood	Tan	None	0	13.2	Positive	
2	B629002-1	2	213-C	213 Bathroom	Window Sill	Wood	Tan	None	0	13.6	Positive	
2	B629002-1	2	213-C	213 Bathroom	Decorative Column	Wood	Tan	None	0	13.2	Positive	
2	B629002-1	2	213-C	213 Bathroom	W4	Plaster	White	Cracking	1	38.7	Positive	
2	B629002-1	2	213-C	213 Bathroom	Window Frame	Wood	Tan	None	0	15.1	Positive	
2	B629002-1	2	213-C	213 Bathroom	Window Sill	Wood	Tan	Chipping	1	8	Positive	
2	B629002-1	2	213-C	213 Bathroom	Decorative Column	Wood	Tan	None	0	10.2	Positive	
2	B629002-1	2	213-C	213 Bathroom	Radiator	Metal	Silver	Flaking	2	17	Positive	
2	B629002-1	2	213-C	213 Bathroom	Floor	Ceramic	Unpainted	N/A	N/A	N/A	N/A	