

| | | | Dates: 3/13/2023 to 7/21/2023 | Lead-Safe Certification Assessment Report | | | | | | |
|---------------------------------|-----------------------|---------|---|---|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | Parkway Center City Middle College | | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | 540 North 13th Street, Philadelphia, PA 19123 | | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | W1 | Plaster | White | Flaking | 10 | 7 | Positive |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | W2 | Plaster | White | Flaking | 3 | 6.6 | Positive |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | W3 | Plaster | White | Flaking | 5 | 0.2 | Negative |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | W4 | Plaster | White | Flaking | 5 | 7.4 | Positive |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Ceiling | Plaster | White | Flaking | 10 | 8.1 | Positive |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Floor | Concrete | White | None | 0 | 0.1 | Negative |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Radiator | Metal | Gray | None | 0 | 0.2 | Negative |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Window Frame | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Door | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 600 | Girl's Restroom on Brandywine Street Side | Door Frame | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | Ceiling | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600A | Pipe Chase behind Toilets in Girl's Restroom on Brandywine Street Side | Floor | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | Ceiling | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 600B | Pipe Chase between Restrooms in Girl's Restroom on Brandywine Street Side | Floor | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | W1 | Plaster | Tan | Flaking | 20 | 0.1 | Negative |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | W2 | Plaster | Tan | Flaking | 50 | 7.1 | Positive |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | W3 | Plaster | Tan | Flaking | 50 | 8.3 | Positive |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | W4 | Plaster | Tan | Flaking | 40 | 7.2 | Positive |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Ceiling | Plaster | Tan | Flaking | 30 | 4 | Positive |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Floor | Concrete | Gray | None | 0 | 4.4 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Radiator | Metal | Gray | Flaking | 3 | 0.5 | Negative |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Window Frame | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Door | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 601 | Boy's Restroom on Brandywine Street Side | Door Frame | Metal | White | None | 0 | 0.1 | Negative |
| 1 | 6 | 602 | Large Center Classroom | W1 | Plaster | White | Flaking | 50 | 0.1 | Negative |
| 1 | 6 | 602 | Large Center Classroom | W2 | Plaster | White | Flaking | 80 | 0 | Negative |
| 1 | 6 | 602 | Large Center Classroom | W3 | Plaster | White | Flaking | 80 | 1.1 | Positive |
| 1 | 6 | 602 | Large Center Classroom | W4 | Plaster | White | Flaking | 100 | 0.2 | Negative |
| 1 | 6 | 602 | Large Center Classroom | Ceiling | Plaster | Green | Flaking | 700 | 10.2 | Positive |
| 1 | 6 | 602 | Large Center Classroom | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 602 | Large Center Classroom | Radiator | Metal | Gray | Flaking | 4 | 2.5 | Positive |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | W1 | Plaster | Tan | Flaking | 20 | 0 | Negative |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | W2 | Plaster | Tan | Flaking | 50 | 0 | Negative |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | W3 | Plaster | Tan | Flaking | 50 | 0 | Negative |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | W4 | Plaster | Tan | Flaking | 40 | 0 | Negative |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | Ceiling | Plaster | Tan | Flaking | 30 | 0 | Negative |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | Radiator | Metal | Gray | Flaking | 3 | 4.4 | Positive |
| 1 | 6 | 603 | Staff Restroom on Green Street Side | Window Frame | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 605 | Closet near Student Restrooms | W1 | Plaster | White | Flaking | 3 | 9.5 | Positive |
| 1 | 6 | 605 | Closet near Student Restrooms | W2 | Plaster | White | Flaking | 4 | 0.1 | Negative |
| 1 | 6 | 605 | Closet near Student Restrooms | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | 605 | Closet near Student Restrooms | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | 605 | Closet near Student Restrooms | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | 605 | Closet near Student Restrooms | Shelf | Wood | White | None | 0 | 0 | Negative |
| 1 | 6 | 605 | Closet near Student Restrooms | Shelf Support | Wood | White | None | 0 | 0.1 | Negative |
| 1 | 6 | 605 | Closet near Student Restrooms | Door | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 605 | Closet near Student Restrooms | Door Frame | Metal | White | None | 0 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W1 | Plaster | Gray | Flaking | 100 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W2 | Plaster | Gray | Flaking | 50 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W3 | Plaster | Gray | Flaking | 80 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W4 | Plaster | Gray | Flaking | 60 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W1 | Plaster | White | Flaking | 100 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W2 | Plaster | White | Flaking | 50 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W3 | Plaster | White | Flaking | 45 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | W4 | Plaster | White | Flaking | 40 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | Ceiling | Concrete | White | Flaking | 400 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--------------------------------------|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 6 | 606 | Penthouse Mechanical Room | Door | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 6 | 606 | Penthouse Mechanical Room | Door Frame | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 6 | E2 | Freight Elevator | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | E2 | Freight Elevator | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | E2 | Freight Elevator | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | E2 | Freight Elevator | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | E2 | Freight Elevator | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | E2 | Freight Elevator | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 6 | S65 | Fire Tower on Green Street Side | W1 | Brick | White | None | 0 | 4.4 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | W2 | Brick | White | None | 0 | 6.7 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | W3 | Brick | White | None | 0 | 7.6 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | W4 | Brick | White | None | 0 | 6.3 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Ceiling | Concrete | White | None | 0 | No access | No Access |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Window Frame | Metal | Brown | Flaking | 4 | 4.4 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Handrail | Metal | Brown | None | 0 | 5.1 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Stair Riser | Concrete | Grey | None | 0 | 1.4 | Positive |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Stair Tread | Concrete | Grey | None | 0 | 0.1 | Negative |
| 1 | 6 | S65 | Fire Tower on Green Street Side | Stair Stringer | Concrete | Grey | None | 0 | 1.8 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | W1 | Brick | White | None | 0 | 5.4 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | W2 | Brick | White | None | 0 | 6.1 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | W3 | Brick | White | None | 0 | 5.8 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | W4 | Brick | White | None | 0 | 6.3 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Ceiling | Concrete | White | Flaking | 40 | 6.9 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Door | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Window Frame | Metal | Brown | Flaking | 6 | 5 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Handrail | Metal | Brown | Chipping | 10 | 0.7 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Stair Riser | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Stair Tread | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 6 | S66 | Fire Tower on Brandywine Street Side | Stair Stringer | Concrete | Gray | None | 0 | 2.4 | Positive |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | W1 | Plaster | White | Flaking | 30 | 8.1 | Positive |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | W2 | Plaster | White | Flaking | 10 | 0 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | W3 | Plaster | White | Flaking | 30 | 6.2 | Positive |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | W4 | Plaster | White | Flaking | 15 | 0.1 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Ceiling | Plaster | White | Cracking | 60 | 0.1 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Radiator | Metal | Gray | Flaking | 1 | 0 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 509 | Girl's Restroom adjacent to Kitchen | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | Ceiling | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | Floor | No Access | No Access | N/A | N/A | N/A | N/A |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | Door | Wood | Brown | Chipping | 1 | 0 | Negative |
| 1 | 5 | 509A | Pipe Chase in Girl's Restroom adjacent to Kitchen | Door Frame | Wood | Brown | Chipping | 1 | 0 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | W1 | Plaster | White | Flaking | 20 | 10.9 | Positive |
| 1 | 5 | 508 | Lunch Director's Office | W2 | Plaster | White | Flaking | 20 | 1.2 | Positive |
| 1 | 5 | 508 | Lunch Director's Office | W3 | Plaster | White | Flaking | 40 | 10.6 | Positive |
| 1 | 5 | 508 | Lunch Director's Office | W4 | Plaster | White | Flaking | 5 | 10.9 | Positive |
| 1 | 5 | 508 | Lunch Director's Office | Ceiling | Plaster | Tan | Flaking | 100 | 11.8 | Positive |
| 1 | 5 | 508 | Lunch Director's Office | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 508 | Lunch Director's Office | Door | Wood | Brown | Friction | 2 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Door Casing | Wood | Brown | Friction | 3 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Chair Rail | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Window Casing | Wood | Brown | Alligatoring | 5 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508 | Lunch Director's Office | Radiator | Metal | Gray | None | 0 | 4.2 | Positive |
| 1 | 5 | 508A | Lunch Director's Office Restroom | W1 | Plaster | White | Flaking | 20 | 4.8 | Positive |
| 1 | 5 | 508A | Lunch Director's Office Restroom | W2 | Plaster | White | Efflorescence | 60 | 7.7 | Positive |
| 1 | 5 | 508A | Lunch Director's Office Restroom | W3 | Plaster | White | Flaking | 20 | 0.4 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | W4 | Plaster | White | Flaking | 20 | 0.5 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Ceiling | Plaster | Tan | Cracking | 80 | 2 | positive |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Door Casing | Wood | Brown | Friction | 1 | 0.1 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Window Casing | Wood | Brown | Flaking | 3 | 0.1 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Window Sill | Wood | Brown | None | 0 | 0.5 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 508A | Lunch Director's Office Restroom | Radiator | Metal | Gray | Flaking | 3 | 3.7 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | W1 | Plaster | White | None | 0 | 1.4 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | W2 | Plaster | White | None | 0 | 10.2 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | W3 | Plaster | White | None | 0 | 7.5 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | W4 | Plaster | White | None | 0 | 9.1 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | Ceiling | Plaster | White | None | 0 | 11.1 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 507 | Lunch Assistant Room | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Window Sill | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Chair Rail | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Radiator | Metal | Gray | Flaking | 3 | 3.4 | Positive |
| 1 | 5 | 507 | Lunch Assistant Room | Door | Wood | Brown | Friction | 2 | 0.1 | Negative |
| 1 | 5 | 507 | Lunch Assistant Room | Door Casing | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | W1 | Plaster | White | Flaking | 10 | 11.2 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | W2 | Plaster | White | Flaking | 10 | 10.5 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | W3 | Plaster | White | Flaking | 5 | 1.8 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | W4 | Plaster | White | None | 0 | 12.6 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Ceiling | Plaster | White | None | 0 | 10 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Radiator | Metal | Gray | Chipping | 3 | 3.5 | Positive |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507A | Lunch Assistant Room Restroom | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | W1 | Plaster | White | Flaking | 20 | 11.5 | Positive |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | W2 | Plaster | White | Flaking | 15 | 12.5 | Positive |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | W3 | Plaster | White | Flaking | 5 | 11.9 | Positive |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | W4 | Plaster | White | None | 0 | 12.5 | Positive |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Ceiling | Plaster | White | Cracking | 15 | 13.2 | Positive |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Radiator | Metal | Gray | Flaking | 5 | 0.1 | Negative |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Window Casing | Wood | Brown | Alligating | 6 | 0.2 | Negative |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Window Apron | Wood | Brown | None | 0 | 0.2 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 507B | Kitchen Storage Room adjacent to Fire Tower | Baseboard | Wood | Gray | None | 0 | 0 | Negative |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | W1 | Brick | White | None | 0 | 9.2 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | W2 | Brick | White | None | 0 | 10 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | W3 | Brick | White | None | 0 | 6.7 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | W4 | Brick | White | None | 0 | 8.1 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Ceiling | Concrete | White | Flaking | 140 | 0.2 | Negative |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Floor | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Drain Pipe | Metal | Brown | Flaking | 24 | 10 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Security Gate | Metal | Brown | Flaking | 100 | 10 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Handrail | Metal | Brown | Chipping | 8 | 2.1 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Stair Riser | Concrete | Gray | None | 0 | 1 | Positive |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Stair Treads | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | 5 | S55 | Fire Tower adjacent to Kitchen Dry Storage | Stair Stringer | Concrete | Gray | None | 0 | 2.2 | Positive |
| 1 | 5 | 506A | Art Supply and Drying Room | W1 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 506A | Art Supply and Drying Room | W2 | Plaster | Gray | Flaking | 15 | 0.3 | Negative |
| 1 | 5 | 506A | Art Supply and Drying Room | W3 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 506A | Art Supply and Drying Room | W4 | Plaster | Gray | Flaking | 4 | 9.9 | Positive |
| 1 | 5 | 506A | Art Supply and Drying Room | Ceiling | Plaster | White | Cracking | 40 | 9.5 | Positive |
| 1 | 5 | 506A | Art Supply and Drying Room | Floor | Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 506A | Art Supply and Drying Room | Radiator | Metal | Gray | Flaking | 5 | 3.9 | Positive |
| 1 | 5 | 506A | Art Supply and Drying Room | Window Casing | Wood | Brown | Alligating | 20 | 0.5 | Negative |
| 1 | 5 | 506A | Art Supply and Drying Room | Window Sill | Wood | Brown | Friction | 20 | 0 | Negative |
| 1 | 5 | 506A | Art Supply and Drying Room | Window Apron | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | W1 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | W2 | Plaster | White | None | 0 | 11.8 | Positive |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | W3 | Wood | White | None | 0 | 0 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | W4 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Ceiling | Plaster | White | None | 0 | 11.8 | Positive |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Radiator | Metal | Gray | None | 0 | 3 | Positive |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 506B | Art Supply and Drying Room Kiln Room | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | W2 | Plaster | White | Efflorescence | 10 | 9.2 | Positive |
| 1 | 5 | 506 | Classroom 506 Art Room | W3 | Plaster | White | Flaking | 5 | 10.4 | Positive |
| 1 | 5 | 506 | Classroom 506 Art Room | W4 | Plaster | White | Flaking | 2 | 9.1 | Positive |
| 1 | 5 | 506 | Classroom 506 Art Room | Ceiling | Plaster | White | Cracking | 40 | 10.5 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 506 | Classroom 506 Art Room | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 506 | Classroom 506 Art Room | Radiator | Metal | Gray | Flaking | 10 | 3.8 | Positive |
| 1 | 5 | 506 | Classroom 506 Art Room | Radiator | Metal | Gray | Flaking | 1 | 4.3 | Positive |
| 1 | 5 | 506 | Classroom 506 Art Room | Door | Wood | Brown | Friction | 1 | 0 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | Door Casing | Metal | Brown | Friction | 1 | 0.1 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | Window Casing | Wood | Brown | Alligating | 5 | 0.1 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | Window Sill | Wood | Brown | Flaking | 5 | 0.1 | Negative |
| 1 | 5 | 506 | Classroom 506 Art Room | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | W1 | Plaster | Gray | None | 0 | 7.1 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | W2 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | W3 | Plaster | Gray | None | 0 | 12 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Ceiling | Plaster | White | None | 0 | 10.7 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Floor | Concrete | Gray | None | 0 | 1.9 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Stair Treads | Concrete | Gray | None | 0 | 1 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Stair Riser | Concrete | Gray | None | 0 | 1.2 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Stair Stringer | Concrete | Gray | None | 0 | 2.3 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Newel Post | Metal | Brown | None | 0 | 7.4 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Radiator | Metal | Gray | None | 0 | 0.8 | Positive |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 5 | S53 | Stairwell adjacent to Classroom 506 Art Room | Door Casing | Metal | Brown | None | 0 | 6.8 | Positive |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | W1 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | W2 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | W3 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 505C | Vestibule outside Storage Room 505B | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 505B | Storage Room 505B | W1 | Plaster | Gray | Flaking | 5 | 9.4 | Positive |
| 1 | 5 | 505B | Storage Room 505B | W2 | Plaster | Gray | Flaking | 10 | 6.8 | Positive |
| 1 | 5 | 505B | Storage Room 505B | W3 | Plaster | Gray | None | 0 | 11.3 | Positive |
| 1 | 5 | 505B | Storage Room 505B | W4 | Sheetrock | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 505B | Storage Room 505B | Ceiling | Plaster | Tan | Cracking | 25 | 10.9 | Positive |
| 1 | 5 | 505B | Storage Room 505B | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 505B | Storage Room 505B | Radiator | Metal | Gray | Flaking | 3 | 5.5 | Positive |
| 1 | 5 | 505B | Storage Room 505B | Radiator | Metal | Gray | Flaking | 3 | 3.6 | Positive |
| 1 | 5 | 505B | Storage Room 505B | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | 505B | Storage Room 505B | Window Sill | Wood | Gray | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | 505B | Storage Room 505B | Window Apron | Wood | Gray | None | 0 | 0.1 | Negative |
| 1 | 5 | 505B | Storage Room 505B | Baseboard | Wood | Gray | None | 0 | 0.1 | Negative |
| 1 | 5 | 505B | Storage Room 505B | Door Casing | Metal | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | W2 | Plaster | White | Cracking | 25 | 1.2 | Positive |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | W4 | Plaster | Blue | None | 0 | 0 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Ceiling | Plaster | White | Cracking | 100 | 10.1 | Positive |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Radiator | Metal | Gray | None | 0 | 4.8 | Positive |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Radiator | Metal | Gray | None | 0 | 3.6 | Positive |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Radiator | Metal | Gray | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 505A | Classroom 505 - Science Classroom | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | W1 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | W2 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | W3 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | W4 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 504A | Hallway to Science Lab Prep Room between Classrooms 505A and 504 | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | W1 | Plaster | Beige | Flaking | 5 | 11.5 | Positive |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | W2 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | W3 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | W4 | Sheetrock | Beige | None | 0 | 0 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Ceiling | No Access | No Access | No Access | N/A | N/A | N/A |

| | | | Dates: 3/13/2023 to 7/21/2023 | Lead-Safe Certification Assessment Report | | | | | | |
|---------------------------------|-----------------------|---------|--|---|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | Parkway Center City Middle College | | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | 540 North 13th Street, Philadelphia, PA 19123 | | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Radiator | Metal | Gray | None | 0 | 3.2 | Positive |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Window Sill | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504B | Science Lab Prep Room between Classrooms 505A and 504 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | W1 | Sheetrock | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | W2 | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | W3 | Sheetrock | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | W4 | Sheetrock | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | Ceiling | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 504C | Service Closet adjacent to Science Lab Prep Room | Door Casing | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | W1 | Sheetrock | Tan | None | 0 | 0.6 | Negative |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | W2 | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | W3 | Sheetrock | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | W4 | Sheetrock | Tan | None | 0 | 0 | Negative |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | Ceiling | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 504D | Staff Restroom near Science Lab Prep Room | Door Casing | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504 | Classroom 504 | W1 | Sheetrock | White | Flaking | 1 | 0 | Negative |
| 1 | 5 | 504 | Classroom 504 | W2 | Plaster | White | Flaking | 20 | 6 | Positive |
| 1 | 5 | 504 | Classroom 504 | W3 | Plaster | White | Flaking | 25 | 0 | Negative |
| 1 | 5 | 504 | Classroom 504 | W4 | Plaster | Green | Efflorescence | 10 | 0 | Negative |
| 1 | 5 | 504 | Classroom 504 | Ceiling | Plaster | White | Alligating | 60 | 7.7 | Positive |
| 1 | 5 | 504 | Classroom 504 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 504 | Classroom 504 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504 | Classroom 504 | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | 504 | Classroom 504 | Window Sill | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 5 | 504 | Classroom 504 | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 504 | Classroom 504 | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 504 | Classroom 504 | Radiator | Metal | Gray | None | 0 | 5 | Positive |
| 1 | 5 | 504 | Classroom 504 | Radiator | Metal | Gray | None | 0 | 3.9 | Positive |
| 1 | 5 | 504 | Classroom 504 | Radiator | Metal | Gray | None | 0 | 5.4 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | W1 | Plaster | Gray | None | 0 | 10.3 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | W2 | Plaster | Gray | None | 0 | 0.3 | Negative |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | W3 | Plaster | Gray | None | 0 | 10.2 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Door Frame | Metal | Brown | None | 0 | 5.4 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Door | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Newel Post | Metal | Brown | None | 0 | 6.9 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Handrail | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Ceiling | Plaster | White | Flaking | 3 | 8.8 | Positive |
| 1 | 5 | S54 | Stairwell adjacent to Classroom 504 | Floor | Concrete | Gray | None | 0 | 1.9 | Positive |
| 1 | 5 | 503A | Classroom 503 | W1 | Plaster | White | Flaking | 2 | 0.1 | Negative |
| 1 | 5 | 503A | Classroom 503 | W1 | Plaster | Gray | Flaking | 2 | 0.2 | Negative |
| 1 | 5 | 503A | Classroom 503 | W2 | Plaster | Gray | Flaking | 5 | 8.8 | Positive |
| 1 | 5 | 503A | Classroom 503 | W2 | Plaster | Black | None | 0 | 9.9 | Positive |
| 1 | 5 | 503A | Classroom 503 | W3 | Sheetrock | Green | None | 0 | 0 | Negative |
| 1 | 5 | 503A | Classroom 503 | W3 | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 503A | Classroom 503 | W4 | Plaster | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | 503A | Classroom 503 | W4 | Plaster | White | None | 0 | 10.9 | Positive |
| 1 | 5 | 503A | Classroom 503 | Ceiling | Plaster | White | Cracking | 20 | 11.6 | Positive |
| 1 | 5 | 503A | Classroom 503 | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 503A | Classroom 503 | Radiator | Metal | Gray | Flaking | 5 | 6.8 | Positive |
| 1 | 5 | 503A | Classroom 503 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 503A | Classroom 503 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 503A | Classroom 503 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 5 | 503A | Classroom 503 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 5 | 503A | Classroom 503 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | W1 | Sheetrock | White | Flaking | 10 | 0 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | W2 | Plaster | White | Flaking | 40 | 8.8 | Positive |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | W3 | Sheetrock | White | Flaking | 10 | 0 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | W4 | Plaster | White | Flaking | 30 | 9.6 | Positive |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Ceiling | Plaster | White | Cracking | 40 | 9.5 | Positive |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Radiator | Metal | Gray | Flaking | 10 | 5.5 | Positive |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Radiator | Metal | Gray | Flaking | 10 | 3.7 | Positive |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Window Sill | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 5 | 503 | Teacher's Lounge adjacent to Classroom 503 | Window Apron | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 5 | 502 | Classroom 502 | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 5 | 502 | Classroom 502 | W2 | Plaster | White | Flaking | 5 | 9.7 | Positive |
| 1 | 5 | 502 | Classroom 502 | W3 | Plaster | White | None | 0 | 10.6 | Positive |
| 1 | 5 | 502 | Classroom 502 | W4 | Plaster | White | Flaking | 10 | 13.2 | Positive |
| 1 | 5 | 502 | Classroom 502 | Ceiling | Plaster | White | Cracking | 30 | 9.3 | Positive |
| 1 | 5 | 502 | Classroom 502 | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 502 | Classroom 502 | Radiator | Metal | Gray | Flaking | 2 | 5.8 | Positive |
| 1 | 5 | 502 | Classroom 502 | Radiator | Metal | Gray | Flaking | 4 | 4.2 | Positive |
| 1 | 5 | 502 | Classroom 502 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 502 | Classroom 502 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 502 | Classroom 502 | Window Casing | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 5 | 502 | Classroom 502 | Window Sill | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 5 | 502 | Classroom 502 | Window Apron | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | W1 | Brick | White | None | 0 | 4.7 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | W2 | Brick | White | None | 0 | 3.7 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | W3 | Brick | White | None | 0 | 5.5 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | W4 | Brick | White | None | 0 | 5.4 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Door Casing | Metal | Brown | None | 0 | 0.4 | Negative |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Ceiling | Concrete | White | Flaking | 40 | 5.1 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Floor | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Security Gate | Metal | Brown | Flaking | 100 | 2.9 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Drain Pipe | Metal | Brown | Flaking | 24 | 0.15 | Negative |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Handrail | Metal | Brown | Chipping | 10 | 0.5 | Negative |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Stair Riser | Concrete | Gray | None | 0 | 2.8 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Stair Treads | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 5 | S56 | Fire Tower adjacent to Classroom 502 | Stair Stringer | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 5 | 501 | Classroom 501 | W1 | Plaster | Gray | Flaking | 3 | 8.7 | Positive |
| 1 | 5 | 501 | Classroom 501 | W2 | Plaster | Gray | Efflorescence | 20 | 8.7 | Positive |
| 1 | 5 | 501 | Classroom 501 | W3 | Plaster | Gray | Efflorescence | 20 | 9.1 | Positive |
| 1 | 5 | 501 | Classroom 501 | W4 | Plaster | Gray | Flaking | 20 | 11.4 | Positive |
| 1 | 5 | 501 | Classroom 501 | Ceiling | Plaster | White | Efflorescence | 720 | 10.9 | Positive |
| 1 | 5 | 501 | Classroom 501 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 501 | Classroom 501 | Radiator | Metal | Gray | Flaking | 10 | 4.2 | Positive |
| 1 | 5 | 501 | Classroom 501 | Radiator Cover | Metal | Gray | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | 501 | Classroom 501 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 501 | Classroom 501 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 501 | Classroom 501 | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 501 | Classroom 501 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 5 | 501 | Classroom 501 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | W1 | Plaster | White | Flaking | 120 | 0 | Negative |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 501A | Classroom 501 Pipe Chase | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | W1 | Plaster | White | None | 0 | 5.8 | Positive |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | W2 | Plaster | White | None | 0 | 8.1 | Positive |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | W3 | Plaster | White | None | 0 | 11.3 | Positive |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | W4 | Plaster | White | None | 0 | 7.7 | Positive |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | Ceiling | Concrete | White | Cracking | 1 | 0 | Negative |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | Radiator | Metal | Gray | Flaking | 1 | 0 | Negative |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 511 | Boy's Restroom adjacent to Classroom 501 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | Ceiling | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 511B | Pipe Chase in Boy's Restroom adjacent to Classroom 501 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | Ceiling | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | Floor | No Access | No Access | None | N/A | N/A | N/A |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 511A | Pipe Shaft adjacent to Kitchen | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 5 | 512 | Cafeteria | W1 | Plaster | White | Flaking | 10 | 7.3 | Positive |
| 1 | 5 | 512 | Cafeteria | W2 | Plaster | White | Flaking | 6 | 10.1 | Positive |
| 1 | 5 | 512 | Cafeteria | W3 | Plaster | White | Flaking | 4 | 8.9 | Positive |
| 1 | 5 | 512 | Cafeteria | W4 | Plaster | White | Flaking | 2 | 7.1 | Positive |
| 1 | 5 | 512 | Cafeteria | Ceiling | Plaster | White | Flaking | 80 | 8.1 | Positive |
| 1 | 5 | 512 | Cafeteria | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 2.5 | Positive |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 1.5 | Positive |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 1.9 | Positive |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 2.9 | Positive |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 0.5 | Negative |
| 1 | 5 | 512 | Cafeteria | Radiator | Metal | Gray | Flaking | 5 | 1.7 | Positive |
| 1 | 5 | 512 | Cafeteria | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | 512 | Cafeteria | Window Casing | Metal | Brown | None | 0 | 1.9 | Positive |
| 1 | 5 | 512 | Cafeteria | Window Casing | Metal | Brown | None | 0 | 5.9 | Positive |
| 1 | 5 | 510 | Kitchen | W1 | Plaster | White | None | 0 | 20.3 | Positive |
| 1 | 5 | 510 | Kitchen | W2 | Plaster | White | None | 0 | 12.4 | Positive |
| 1 | 5 | 510 | Kitchen | W3 | Plaster | White | None | 0 | 13.9 | Positive |
| 1 | 5 | 510 | Kitchen | W4 | Plaster | White | None | 0 | 17 | Positive |
| 1 | 5 | 510 | Kitchen | Ceiling | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 5 | 510 | Kitchen | Floor | Ceramic Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | 510 | Kitchen | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 5 | 510 | Kitchen | Radiator | Metal | Gray | Flaking | 1 | 0.1 | Negative |
| 1 | 5 | 510 | Kitchen | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 5 | 510 | Kitchen | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | 510 | Kitchen | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 5 | ST512 | Stairway adjacent to cafeteria serving line | W1 | Plaster | Tan | Flaking | 300 | 0.8 | Positive |
| 1 | 5 | ST512 | Stairway adjacent to cafeteria serving line | W2 | Plaster | Tan | Flaking | 100 | 0.1 | Negative |
| 1 | 5 | ST512 | Stairway adjacent to cafeteria serving line | W3 | Plaster | Tan | Flaking | 100 | 0.1 | Negative |
| 1 | 5 | ST512 | Stairway adjacent to cafeteria serving line | W4 | Plaster | Tan | None | 0 | 0.1 | Negative |
| 1 | 5 | ST512 | Stairway adjacent to cafeteria serving line | Ceiling | Plaster | Tan | Chipping | 250 | No Access | Assumed |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | W1 | Plaster | Gray | None | 0 | 0.2 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | W2 | Plaster | Gray | None | 0 | 8.2 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | W3 | Plaster | Gray | None | 0 | 0.4 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | W4 | Plaster | Gray | None | 0 | 0.4 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Ceiling | Plaster | Tan | Flaking | 30 | 11.9 | Positive |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Floor | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Floor | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Floor | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Radiators | Metal | Gray | Flaking | 5 | 0.9 | Positive |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Radiators | Metal | Gray | Flaking | 3 | 1.1 | Positive |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Radiators | Metal | Gray | Flaking | 2 | 0.9 | Positive |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Locker | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H51 | Hallway outside Kitchen to Classroom 503 | Locker | Metal | Green | None | 0 | 0 | Negative |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H51PCS | Pipe/Cable Shaft in Hallway next to Classroom 502 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | W1 | Plaster | Gray | None | 0 | 10.2 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | W2 | Plaster | Gray | None | 0 | 7.6 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | W3 | Plaster | Gray | None | 0 | 10.5 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | W4 | Plaster | Gray | None | 0 | 9.7 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | Ceiling | Plaster | Tan | Cracking | 200 | 13 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | Floor | Concrete | Gray | None | 0 | 3.1 | Positive |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | Electrical Panel | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 5 | H53 | Hallway outside Classrooms 504 to 505B | Electrical Panel | Metal | Brown | None | 0 | 2.3 | Positive |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | H53PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 504 | Door Casing | Wood | Brown | None | 0 | 0.2 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|---|-----------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | H53PCS2 | Pipe/Cable Shaft in Hallway over Hydration Station near Classroom 504 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | W4 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 5 | H53PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 505 | Door Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | W1 | Plaster | White | None | 0 | 11.8 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | W2 | Plaster | White | None | 0 | 5.1 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | W3 | Plaster | White | None | 0 | 8.8 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | W4 | Plaster | White | None | 0 | 9.7 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Ceiling | Plaster | Tan | Flaking | 100 | 11.2 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Floor | Plaster | Gray | None | 0 | 1.2 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Radiator | Metal | Gray | None | 0 | 2.4 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Radiator | Metal | Gray | None | 0 | 1 | Positive |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Radiator | Metal | Gray | None | 0 | 0.3 | Negative |
| 1 | 5 | H52 | Hallway outside Classroom 506 to Kitchen | Door Electrical Panel | Metal | Gray | None | 0 | 8 | Positive |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | Door | Wood | Brown | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 5 | H52PCS | Pipe/Cable Shaft in Hallway next to Classroom 506 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | W1 | Plaster | White | Flaking | 300 | 9.9 | positive |
| 1 | 4 | 412A | Storage Room near Classroom 411 | W2 | Plaster | White | Flaking | 150 | 8.9 | positive |
| 1 | 4 | 412A | Storage Room near Classroom 411 | W3 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | W4 | Plaster | White | Flaking | 20 | 1.6 | Positive |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Ceiling | Plaster | White | Flaking | 100 | 10 | Positive |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Radiator 2 Cover | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Window sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 412A | Storage Room near Classroom 411 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | W1 | Plaster | Gray | None | 0 | 10 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | W2 | Plaster | Gray | None | 0 | 7.41 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | W3 | Plaster | Gray | Flaking | 5 | 9 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | W4 | Plaster | Gray | None | 0 | 9.3 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Floor | Concrete | Gray | None | 0 | 2.12 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Ceiling | Plaster | White | None | 0 | 11.5 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Stair Tread | Concrete | Gray | None | 0 | 1.1 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Stair Riser | Concrete | Gray | None | 0 | 5.3 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Stair Stringer | Concrete | Gray | None | 0 | 6.4 | Positive |
| 1 | 4 | S412 | Stairs between Cafeteria and Storage Room near Classroom 411 | Floor | Concrete | Gray | None | 0 | 2.12 | Positive |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | W1 | Plaster | Tan | None | 0 | 0 | Negative |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | W2 | Plaster | Tan | None | 0 | 0 | Negative |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | W3 | Plaster | Tan | None | 0 | 8.9 | Positive |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | W4 | Plaster | Tan | None | 0 | 7.8 | Positive |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | Ceiling | Concrete | White | Flaking | 10 | 8.5 | Positive |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | Floor | Concrete | Gray | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | Radiator | Metal | Gray | Cracking | 5 | 0.3 | Negative |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 412 | Girl's Restroom next to Classroom 411 | Door Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | Door | Wood | Tan | None | 0 | 0.1 | Negative |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | Door Casing | Wood | Tan | None | 0 | 0 | Negative |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 412B | Pipe Chase in Girl's Restroom next to Classroom 411 | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 411 | Classroom 411 | W1 | Plaster | Gray | Flaking | 100 | 0.1 | Negative |
| 1 | 4 | 411 | Classroom 411 | W2 | Plaster | Gray | Flaking | 50 | 0.1 | Negative |
| 1 | 4 | 411 | Classroom 411 | W3 | Plaster | Gray | Efflorescence | 60 | 10.7 | Positive |
| 1 | 4 | 411 | Classroom 411 | W4 | Plaster | Gray | Flaking | 25 | 10.9 | Positive |
| 1 | 4 | 411 | Classroom 411 | Ceiling | Plaster | Tan | Flaking | 300 | 1.2 | Positive |
| 1 | 4 | 411 | Classroom 411 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 411 | Classroom 411 | Radiator | Metal | Gray | Flaking | 10 | 0.2 | Negative |
| 1 | 4 | 411 | Classroom 411 | Radiator | Metal | Gray | Flaking | 10 | 3.1 | Positive |
| 1 | 4 | 411 | Classroom 411 | Radiator | Metal | Gray | Flaking | 10 | 3.2 | Positive |
| 1 | 4 | 411 | Classroom 411 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 411 | Classroom 411 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 411 | Classroom 411 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 411 | Classroom 411 | Window Sill | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 411 | Classroom 411 | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 411 | Classroom 411 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | W1 | Brick | White | None | 0 | 5.8 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | W2 | Brick | White | None | 0 | 8.2 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | W3 | Brick | White | None | 0 | 10.1 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | W4 | Brick | White | None | 0 | 8.5 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Ceiling | Concrete | White | Flaking | 10 | 11.6 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Floor | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Door | Metal | Brown | Flaking | 5 | 0.1 | Negative |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Door Casing | Metal | Brown | Flaking | 5 | 0.3 | Negative |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Drain Pipe | Metal | Brown | Flaking | 24 | 23.4 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Security Gate | Metal | Brown | Flaking | 100 | 26.4 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Handrail | Metal | Brown | Chipping | 10 | 8 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Stair Riser | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Stair Tread | Concrete | Gray | None | 0 | 0.2 | Negative |
| 1 | 4 | S45 | Fire Tower adjacent to Classroom 411 | Stair Stringer | Concrete | Gray | None | 0 | 1.8 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 410B | Office and Restroom 410B | W1 | Plaster | Green | Cracking | 10 | 21.1 | Positive |
| 1 | 4 | 410B | Office and Restroom 410B | W2 | Plaster | Green | Flaking | 40 | 20.3 | Positive |
| 1 | 4 | 410B | Office and Restroom 410B | W3 | Plaster | Green | Flaking | 10 | 24.9 | Positive |
| 1 | 4 | 410B | Office and Restroom 410B | W4 | Plaster | Green | None | 0 | 15.4 | Positive |
| 1 | 4 | 410B | Office and Restroom 410B | Ceiling | Plaster | Green | None | 0 | 20.6 | Positive |
| 1 | 4 | 410B | Office and Restroom 410B | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 410B | Office and Restroom 410B | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Window Casing | Wood | Varnish | None | 0 | 0.6 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Chair Rail | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 410B | Office and Restroom 410B | Crown Molding | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 410 | Classroom 410 | W1 | Plaster | White | Flaking | 15 | 8.8 | Positive |
| 1 | 4 | 410 | Classroom 410 | W2 | Plaster | White | Efflorescence | 70 | 5.4 | Positive |
| 1 | 4 | 410 | Classroom 410 | W3 | Plaster | White | Flaking | 10 | 0.1 | Negative |
| 1 | 4 | 410 | Classroom 410 | W4 | Plaster | White | Efflorescence | 15 | 0.1 | Negative |
| 1 | 4 | 410 | Classroom 410 | Ceiling | Plaster | Tan | Flaking | 60 | 16.2 | Positive |
| 1 | 4 | 410 | Classroom 410 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 410 | Classroom 410 | Radiator | Metal | Gray | Flaking | 1 | 1 | Positive |
| 1 | 4 | 410 | Classroom 410 | Radiator | Metal | Gray | Flaking | 5 | 3 | Positive |
| 1 | 4 | 410 | Classroom 410 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 410 | Classroom 410 | Electrical Panel | | | | | | |
| 1 | 4 | 410 | Classroom 410 | Door | Metal | White | Flaking | 5 | 0 | Negative |
| 1 | 4 | 410 | Classroom 410 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 410 | Classroom 410 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 410 | Classroom 410 | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 4 | 410 | Classroom 410 | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 410 | Classroom 410 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 410A | Classroom 410 Storage Closet | W1 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 4 | 410A | Classroom 410 Storage Closet | W2 | Plaster | White | None | 0 | 12.2 | Positive |
| 1 | 4 | 410A | Classroom 410 Storage Closet | W3 | Plaster | White | None | 0 | 8.7 | Positive |
| 1 | 4 | 410A | Classroom 410 Storage Closet | W4 | Plaster | White | None | 0 | 13.7 | Positive |
| 1 | 4 | 410A | Classroom 410 Storage Closet | Ceiling | Plaster | White | None | 0 | No Access | No Access |
| 1 | 4 | 410A | Classroom 410 Storage Closet | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 410A | Classroom 410 Storage Closet | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 410A | Classroom 410 Storage Closet | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|-----------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 410A | Classroom 410 Storage Closet | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 409 | Classroom 409 | W1 | Plaster | Gray | None | 0 | 0.1 | Negative |
| 1 | 4 | 409 | Classroom 409 | W2 | Plaster | Gray | Efflorescence | 10 | 4.4 | Positive |
| 1 | 4 | 409 | Classroom 409 | W3 | Plaster | Gray | Cracking | 8 | 8.5 | Positive |
| 1 | 4 | 409 | Classroom 409 | W4 | Plaster | Gray | Cracking | 3 | 7.9 | Positive |
| 1 | 4 | 409 | Classroom 409 | Ceiling | Plaster | Tan | Flaking | 75 | 8.2 | Positive |
| 1 | 4 | 409 | Classroom 409 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 409 | Classroom 409 | Radiator | Metal | Gray | Flaking | 5 | 0 | Negative |
| 1 | 4 | 409 | Classroom 409 | Radiator | Metal | Gray | Flaking | 5 | 2.1 | Positive |
| 1 | 4 | 409 | Classroom 409 | Drain Pipe | Metal | Gray | None | 0 | 0.1 | Negative |
| 1 | 4 | 409 | Classroom 409 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 409 | Classroom 409 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 409 | Classroom 409 | Door Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 409 | Classroom 409 | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 409 | Classroom 409 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 409 | Classroom 409 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | W1 | Plaster | Gray | None | 0 | 18.4 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | W2 | Plaster | Gray | None | 0 | 0.4 | Negative |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | W3 | Plaster | Gray | None | 0 | 21.7 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Ceiling | Plaster | Gray | None | 0 | 18.9 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Floor | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Door Casing | Metal | Brown | None | 0 | 2.3 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Stair Tread | Concrete | Gray | None | 0 | 0.4 | Negative |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Stair Riser | Concrete | Gray | None | 0 | 1.8 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Stair Stringer | Concrete | Gray | None | 0 | 3.4 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Radiator | Metal | Gray | None | 0 | 0.6 | Negative |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Newel Post | Metal | Brown | None | 0 | 7.6 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Spindle | Metal | Gray | None | 0 | 10.2 | Positive |
| 1 | 4 | S43 | Stairwell adjacent to Classroom 408 | Electrical Panel Door | Metal | Gray | None | 0 | 0.1 | Negative |
| 1 | 4 | 408 | Classroom 408 | W1 | Plaster | Gray | Efflorescence | 100 | 10.6 | Positive |
| 1 | 4 | 408 | Classroom 408 | W2 | Plaster | Gray | Efflorescence | 50 | 6.5 | Positive |
| 1 | 4 | 408 | Classroom 408 | W3 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 4 | 408 | Classroom 408 | W4 | Plaster | Gray | Flaking | 20 | 10.2 | Positive |
| 1 | 4 | 408 | Classroom 408 | Ceiling | Plaster | Tan | Flaking | 50 | 22.3 | Positive |
| 1 | 4 | 408 | Classroom 408 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 408 | Classroom 408 | Radiator | Metal | Gray | Flaking | 10 | 5.3 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 4 | 408 | Classroom 408 | Radiator | Metal | Gray | Flaking | 5 | 1.5 | Positive |
| 1 | 4 | 408 | Classroom 408 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 408 | Classroom 408 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 408 | Classroom 408 | Window Sill | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 4 | 408 | Classroom 408 | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 408 | Classroom 408 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 408 | Classroom 408 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 407 | Classroom 407 | W1 | Plaster | Gray | None | 0 | 0.2 | Negative |
| 1 | 4 | 407 | Classroom 407 | W2 | Plaster | Gray | Efflorescence | 50 | 12.6 | Positive |
| 1 | 4 | 407 | Classroom 407 | W3 | Plaster | Gray | Flaking | 40 | 0.1 | Negative |
| 1 | 4 | 407 | Classroom 407 | W4 | Plaster | Gray | Flaking | 30 | 11 | Positive |
| 1 | 4 | 407 | Classroom 407 | Ceiling | Plaster | Tan | Flaking | 100 | 24.8 | Positive |
| 1 | 4 | 407 | Classroom 407 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 407 | Classroom 407 | Radiator | Metal | Gray | Flaking | 15 | 3.1 | Positive |
| 1 | 4 | 407 | Classroom 407 | Radiator | Metal | Gray | Flaking | 10 | 3.8 | Positive |
| 1 | 4 | 407 | Classroom 407 | Door | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 407 | Classroom 407 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 407 | Classroom 407 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 407 | Classroom 407 | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 407 | Classroom 407 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 407 | Classroom 407 | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | W1 | Plaster | White | Cracking | 10 | 14.9 | Positive |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | W2 | Plaster | White | Cracking | 15 | 7.8 | Positive |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | W3 | Plaster | White | Cracking | 15 | 5.4 | Positive |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | W4 | Plaster | White | None | 0 | 5.8 | Positive |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | Ceiling | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 407A | Service Closet across from Classroom 407 | Drain Pipe | Metal | White | None | 0 | 14.9 | Positive |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | W1 | Plaster | Gray | Cracking | 5 | 0.1 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | W2 | Plaster | Gray | Cracking | 10 | 9.4 | Positive |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | W3 | Plaster | Gray | Cracking | 10 | 0.1 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | W4 | Plaster | Gray | Cracking | 2 | 0.1 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Ceiling | Plaster | Tan | Cracking | 75 | 18.7 | Positive |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Radiator | Metal | Gray | Flaking | 5 | 0.1 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Door | Wood | Varnish | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 406A | Teacher's Lounge adjacent to Classroom 407 | Chair Rail | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | W1 | Plaster | White | Flaking | 30 | 6.2 | Positive |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | W2 | Plaster | White | Flaking | 50 | 6.1 | Positive |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | W3 | Plaster | White | Flaking | 10 | 9.3 | Positive |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | W4 | Plaster | Tan | No Access | No Access | No Access | No Access |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | Ceiling | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 406B | Teacher's Lounge adjacent to Classroom 407 Closet | Door Casing | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | W1 | Plaster | White | Flaking | 10 | 0.1 | Negative |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | W2 | Plaster | White | Flaking | 5 | 6.3 | Positive |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | W3 | Plaster | White | Flaking | 5 | 0.1 | Negative |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | W4 | Plaster | White | None | 0 | 0.1 | Negative |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | Floor | Concrete | Gray | Friction | 5 | 0 | Negative |
| 1 | 4 | 406D | Teacher's Lounge adjacent to Classroom 407 Restroom | Ceiling | Plaster | White | None | 0 | No Access | No Access |
| 1 | 4 | 406 | Classroom 406 | W1 | Plaster | White | Flaking | 50 | 9.1 | Positive |
| 1 | 4 | 406 | Classroom 406 | W2 | Plaster | White | Flaking | 60 | 10.2 | Positive |
| 1 | 4 | 406 | Classroom 406 | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 406 | Classroom 406 | W4 | Plaster | White | Flaking | 200 | 9.9 | Positive |
| 1 | 4 | 406 | Classroom 406 | Ceiling | Plaster | Tan | Flaking | 200 | 21.1 | Positive |
| 1 | 4 | 406 | Classroom 406 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 406 | Classroom 406 | Radiator | Metal | Gray | Flaking | 5 | 4 | Positive |
| 1 | 4 | 406 | Classroom 406 | Radiator | Metal | Gray | Flaking | 10 | 6 | Positive |
| 1 | 4 | 406 | Classroom 406 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 406 | Classroom 406 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 406 | Classroom 406 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 406 | Classroom 406 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 406 | Classroom 406 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 406 | Classroom 406 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | Lead-Safe Certification Assessment Report | | | | | | |
|---------------------------------|-----------------------|---------|--|---|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | Parkway Center City Middle College | | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | 540 North 13th Street, Philadelphia, PA 19123 | | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 406C | Closet across from Classroom 406 | W1 | Plaster | White | None | 0 | 2.8 | Positive |
| 1 | 4 | 406C | Closet across from Classroom 406 | W2 | Plaster | White | None | 0 | 5.5 | Positive |
| 1 | 4 | 406C | Closet across from Classroom 406 | W3 | Plaster | White | None | 0 | 5.3 | Positive |
| 1 | 4 | 406C | Closet across from Classroom 406 | W4 | Plaster | White | None | 0 | 4.2 | Positive |
| 1 | 4 | 406C | Closet across from Classroom 406 | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 406C | Closet across from Classroom 406 | Ceiling | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 4 | 406C | Closet across from Classroom 406 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 406C | Closet across from Classroom 406 | Door Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 405 | Classroom 405 | W1 | Plaster | White | Flaking | 10 | 0.2 | Negative |
| 1 | 4 | 405 | Classroom 405 | W2 | Plaster | White | Efflorescence | 50 | 8.7 | Positive |
| 1 | 4 | 405 | Classroom 405 | W3 | Plaster | White | Cracking | 5 | 8.8 | Positive |
| 1 | 4 | 405 | Classroom 405 | W4 | Sheetrock | White | Cracking | 6 | 0 | Negative |
| 1 | 4 | 405 | Classroom 405 | Ceiling | Plaster | Tan | Cracking | 50 | 20.9 | Positive |
| 1 | 4 | 405 | Classroom 405 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 405 | Classroom 405 | Radiator | Metal | Gray | Flaking | 5 | 3.5 | Positive |
| 1 | 4 | 405 | Classroom 405 | Radiator | Metal | Gray | Flaking | 5 | 3.5 | Positive |
| 1 | 4 | 405 | Classroom 405 | Door Casing | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405 | Classroom 405 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405 | Classroom 405 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 405 | Classroom 405 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 405 | Classroom 405 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 405 | Classroom 405 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | W2 | Plaster | White | Efflorescence | 30 | 5.8 | Positive |
| 1 | 4 | 405A | Classroom 405 Copy Room | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | W4 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 405A | Classroom 405 Copy Room | Ceiling | Plaster | Tan | Flaking | 50 | 19.6 | Positive |
| 1 | 4 | 405A | Classroom 405 Copy Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Door Casing | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | W2 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | W4 | Plaster | White | Cracking | 20 | 10.1 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|-------------------------------------|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 4 | 405B | Classroom 405 Vestibule | Ceiling | Plaster | Tan | Cracking | 10 | 17.4 | Positive |
| 1 | 4 | 405B | Classroom 405 Vestibule | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 405B | Classroom 405 Vestibule | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 405B | Classroom 405 Vestibule | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | W1 | Plaster | White | None | 0 | 9 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | W2 | Plaster | White | None | 0 | 2.8 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | W3 | Plaster | White | None | 0 | 12.7 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Stair Tread | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Stair Riser | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Stair Stringer | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 4 | 404 | Classroom 404 | W1 | Plaster | Gray | None | 0 | 9 | Positive |
| 1 | 4 | 404 | Classroom 404 | W2 | Plaster | Gray | Flaking | 10 | 0 | Negative |
| 1 | 4 | 404 | Classroom 404 | W3 | Plaster | Gray | None | 0 | 7 | Positive |
| 1 | 4 | 404 | Classroom 404 | W4 | Plaster | Gray | None | 0 | 8.6 | Positive |
| 1 | 4 | 404 | Classroom 404 | Ceiling | Plaster | Tan | None | 0 | 11.3 | Positive |
| 1 | 4 | 404 | Classroom 404 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 404 | Classroom 404 | Radiator | Metal | Gray | Flaking | 3 | 2.6 | Positive |
| 1 | 4 | 404 | Classroom 404 | Radiator | Metal | Gray | Flaking | 10 | 5.1 | Positive |
| 1 | 4 | 404 | Classroom 404 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | 404 | Classroom 404 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 404 | Classroom 404 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 404 | Classroom 404 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 404 | Classroom 404 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 404 | Classroom 404 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 403 | Classroom 403 | W1 | Plaster | Gray | Flaking | 3 | 9.1 | Positive |
| 1 | 4 | 403 | Classroom 403 | W2 | Plaster | Gray | Flaking | 15 | 7 | Positive |
| 1 | 4 | 403 | Classroom 403 | W3 | Plaster | Gray | Flaking | 5 | 5.1 | Positive |
| 1 | 4 | 403 | Classroom 403 | W4 | Plaster | Gray | Flaking | 5 | 7.1 | Positive |
| 1 | 4 | 403 | Classroom 403 | Ceiling | Plaster | Tan | Cracking | 75 | 11.4 | Positive |
| 1 | 4 | 403 | Classroom 403 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 403 | Classroom 403 | Radiator | Metal | Gray | Flaking | 3 | 3.8 | Positive |
| 1 | 4 | 403 | Classroom 403 | Radiator | Metal | Gray | Flaking | 3 | 4 | Positive |
| 1 | 4 | 403 | Classroom 403 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 403 | Classroom 403 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 403 | Classroom 403 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 4 | 403 | Classroom 403 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 4 | 403 | Classroom 403 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 403 | Classroom 403 | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 402 | Classroom 402 | W1 | Plaster | Gray | Flaking | 10 | 0.2 | Negative |
| 1 | 4 | 402 | Classroom 402 | W2 | Plaster | Gray | Cracking | 15 | 7 | Positive |
| 1 | 4 | 402 | Classroom 402 | W3 | Plaster | Gray | Cracking | 10 | 0.1 | Negative |
| 1 | 4 | 402 | Classroom 402 | W4 | Plaster | Gray | Cracking | 4 | 8.1 | Positive |
| 1 | 4 | 402 | Classroom 402 | Ceiling | Plaster | Tan | Flaking | 50 | 11.3 | Positive |
| 1 | 4 | 402 | Classroom 402 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 402 | Classroom 402 | Radiator | Metal | Gray | Flaking | 5 | 5.3 | Positive |
| 1 | 4 | 402 | Classroom 402 | Radiator | Metal | Gray | Flaking | 3 | 4.5 | Positive |
| 1 | 4 | 402 | Classroom 402 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 402 | Classroom 402 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 402 | Classroom 402 | Door Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 402 | Classroom 402 | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 402 | Classroom 402 | Window Sill | Wood | Brown | None | 0 | 0.4 | Negative |
| 1 | 4 | 402 | Classroom 402 | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | W1 | Brick | White | None | 0 | 3.6 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | W2 | Brick | White | None | 0 | 3.7 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | W3 | Brick | White | None | 0 | 4.1 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | W4 | Brick | White | None | 0 | 4.2 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Ceiling | Concrete | White | Flaking | 5 | 7.3 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Floor | Concrete | Gray | None | 0 | 1 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Security Gate | Metal | Brown | Flaking | 120 | 3.6 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Drain Pipe | Metal | Brown | Flaking | 24 | 22.6 | Positive |
| 1 | 4 | 401 | Classroom 401 | W1 | Plaster | Gray | Efflorescence | 20 | 9.6 | Positive |
| 1 | 4 | 401 | Classroom 401 | W2 | Plaster | Gray | Cracking | 20 | 0.1 | Negative |
| 1 | 4 | 401 | Classroom 401 | W3 | Plaster | Gray | Cracking | 25 | 9.2 | Positive |
| 1 | 4 | 401 | Classroom 401 | W4 | Plaster | Gray | Cracking | 5 | 8.8 | Positive |
| 1 | 4 | 401 | Classroom 401 | Ceiling | Plaster | Tan | Flaking | 50 | 10.6 | Positive |
| 1 | 4 | 401 | Classroom 401 | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | W1 | Plaster | White | Moisture Damage | 160 | 2.8 | Positive |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 401A | Classroom 401 Pipe Chase | Ceiling | Concrete | White | Flaking | 30 | 18.9 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | W1 | Plaster | White | Flaking | 2 | 5.6 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|-------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | W2 | Plaster | White | Flaking | 4 | 4.8 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | W3 | Plaster | White | Flaking | 20 | 0.8 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | W4 | Plaster | White | Chipping | 10 | 4.8 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Ceiling | Concrete | White | Cracking | 20 | 7.4 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Radiator | Metal | Gray | Flaking | 5 | 2 | Positive |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | Door | Wood | Brown | Chipping | 1 | 0 | Negative |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | Door Casing | Wood | Brown | Chipping | 1 | 0 | Negative |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 413A | Pipe Chase in Boy's Restroom adjacent to Classroom 401 | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | 413B | Pipe Shaft adjacent to 4th Floor Boy's Restroom | W1 | Brick | White | None | 0 | 0 | Negative |
| 1 | 4 | 413B | Pipe Shaft adjacent to 4th Floor Boy's Restroom | W2 | Brick | White | None | 0 | 0 | Negative |
| 1 | 4 | 413B | Pipe Shaft adjacent to 4th Floor Boy's Restroom | W3 | Brick | White | None | 0 | 0 | Negative |
| 1 | 4 | 413B | Pipe Shaft adjacent to 4th Floor Boy's Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 413B | Pipe Shaft adjacent to 4th Floor Boy's Restroom | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | W1 | Plaster | Gray | Cracking | 2 | 9.9 | Positive |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | W2 | Plaster | Gray | Flaking | 1 | 0 | Negative |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | W3 | Plaster | Gray | Flaking | 10 | 6.6 | Positive |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | W4 | Plaster | Gray | None | 0 | 4.8 | Positive |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | Ceiling | Plaster | Tan | None | 0 | 9.6 | Positive |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | Stair Tread | Concrete | Gray | None | 0 | 2.9 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | W1 | Plaster | Gray | Flaking | 6 | 4.6 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | W2 | Plaster | Gray | None | 0 | 9.4 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | W3 | Plaster | Gray | None | 0 | 10.2 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | W4 | Plaster | Gray | None | 0 | 0.4 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Ceiling | Plaster | Tan | Efflorescence | 40 | 10.7 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Lockers | Metal | Blue | None | 0 | 0.2 | Negative |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | Door Casing | Wood | Varnish | None | 0 | 0.2 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|-------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H41PCS | Pipe/Cable Shaft in Hallway next to Classroom 402 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | W1 | Plaster | Gray | None | 0 | 8.8 | Positive |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | W2 | Plaster | Gray | None | 0 | 11.2 | Positive |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | W3 | Plaster | Gray | None | 0 | 11.2 | Positive |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | W4 | Plaster | Gray | None | 0 | 8.6 | Positive |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | Ceiling | Plaster | Tan | Flaking | 200 | 18.5 | Positive |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | Door Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 405 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 405 | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | W1 | No Access | No Access | No Access | No Access | No Access | No Access |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|---------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H43PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 408 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | W1 | Plaster | Gray | None | 0 | 25.8 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | W2 | Plaster | Gray | None | 0 | 18.9 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | W3 | Plaster | Gray | Cracking | 1 | 21 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | W4 | Plaster | Gray | None | 0 | 14.9 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Ceiling | Plaster | Tan | Flaking | 100 | 17 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Floor | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Radiator | Metal | Gray | Flaking | 5 | 1.7 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Radiator | Metal | Gray | Flaking | 5 | 2 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Radiator | Metal | Gray | Flaking | 5 | 3.2 | Positive |
| 1 | 4 | H42 | Hallway outside Classrooms 409 to 411 | Lockers | Metal | Blue | None | 0 | 0.4 | Negative |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 4 | H42PCS | Pipe/Cable Shaft in Hallway next to Classroom 409 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | W1 | Plaster | Gray | None | 0 | 16.2 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | W2 | Plaster | Gray | None | 0 | 7.6 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | W3 | Plaster | Gray | None | 0 | 17.6 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | W4 | Plaster | Gray | None | 0 | 16.5 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Ceiling | Plaster | Tan | Flaking | 15 | 19.6 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Floor | Concrete | Gray | None | 0 | 1.2 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Elevator Door | Metal | Pink | None | 0 | 0.1 | Negative |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Elevator Door Frame | Metal | Pink | None | 0 | 0 | Negative |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Stair Tread | Concrete | Gray | None | 0 | 0.4 | Negative |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Stair Riser | Concrete | Gray | None | 0 | 4.4 | Positive |
| 1 | 4 | H42A | Hallway outside 4th Floor Girl's Restroom | Stair Stringer | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | 313B | Pipe Shaft adjacent to 3rd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Ceiling | Concrete | White | Cracking | 5 | 0 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | W1 | Plaster | White | Cracking | 8 | 15.3 | Positive |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | W2 | Plaster | White | Cracking | 5 | 6 | Positive |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | W3 | Plaster | White | Cracking | 10 | 1 | Positive |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | W4 | Plaster | White | Cracking | 10 | 17.7 | Positive |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Door Frame | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Window Casing | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Radiator | Metal | Gray | Flaking | 10 | 0 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 3 | 313 | Boy's Restroom adjacent to Classroom 301 | Drain Pipe | Metal | Brown | Flaking | 12 | 0.8 | Positive |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 313A | Pipe Chase in Boy's Restroom adjacent to Classroom 301 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 301 | Classroom 301 | Ceiling | Plaster | Tan | Cracking | 20 | 16.4 | Positive |
| 1 | 3 | 301 | Classroom 301 | W1 | Plaster | Gray | None | 0 | 19.7 | Positive |
| 1 | 3 | 301 | Classroom 301 | W2 | Plaster | Gray | Peeling | 10 | 13.4 | Positive |
| 1 | 3 | 301 | Classroom 301 | W3 | Plaster | Gray | None | 0 | 16.6 | Positive |
| 1 | 3 | 301 | Classroom 301 | W4 | Plaster | Gray | None | 0 | 16.1 | Positive |
| 1 | 3 | 301 | Classroom 301 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 301 | Classroom 301 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 301 | Classroom 301 | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 301 | Classroom 301 | Window Casing | Wood | Varnish | None | N/A | 0.3 | Negative |
| 1 | 3 | 301 | Classroom 301 | Window Sill | Wood | Varnish | None | N/A | 0.1 | Negative |
| 1 | 3 | 301 | Classroom 301 | Window Apron | Wood | Varnish | None | N/A | 0.2 | Negative |
| 1 | 3 | 301 | Classroom 301 | Radiator | Metal | Gray | Flaking | 5 | 6.3 | Positive |
| 1 | 3 | 301 | Classroom 301 | Radiator | Metal | Gray | Flaking | 3 | 0 | Negative |
| 1 | 3 | 301 | Classroom 301 | Radiator | Metal | Gray | Flaking | 10 | 5.5 | Positive |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | W1 | Plaster | White | Cracking | 8 | 10 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 301B | Classroom 301 Pipe Chase | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | W1 | Brick | White | None | 0 | 7.4 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | W2 | Brick | White | None | 0 | 6.7 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | W3 | Brick | White | None | 0 | 8.7 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | W4 | Brick | White | None | 0 | 5.1 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Ceiling | Concrete | White | None | 0 | 9 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Floor | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Door | Metal | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Door Frame | Metal | Brown | None | 0 | 0.5 | Negative |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Drain Pipe | Metal | Brown | Flaking | 12 | 0.7 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Security Gate | Metal | Brown | Flaking | 40 | 0.1 | Negative |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Handrail | Metal | Brown | None | 10 | 0.8 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Stair Riser | Concrete | Gray | None | 0 | 1 | Positive |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Stair Tread | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | 3 | S36 | Fire Tower adjacent to Classroom 302 | Stair Stringer | Concrete | Gray | None | 0 | 2.4 | Positive |
| 1 | 3 | 302A | Office 301A | W1 | Plaster | Blue | Flaking | 3 | 0 | Negative |
| 1 | 3 | 302A | Office 301A | W2 | Plaster | Blue | Flaking | 10 | 9.2 | Positive |
| 1 | 3 | 302A | Office 301A | W3 | Plaster | Blue | Flaking | 6 | 0.1 | Negative |
| 1 | 3 | 302A | Office 301A | W4 | Plaster | Blue | Flaking | 4 | 0.1 | Negative |
| 1 | 3 | 302A | Office 301A | Ceiling | Plaster | Tan | Flaking | 100 | 19.2 | Positive |
| 1 | 3 | 302A | Office 301A | Radiator | Metal | Gray | Flaking | 10 | 4.1 | Positive |
| 1 | 3 | 302A | Office 301A | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 302A | Office 301A | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 302A | Office 301A | Window Casing | Wood | Varnish | None | 0 | 0.6 | Negative |
| 1 | 3 | 302A | Office 301A | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 302A | Office 301A | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 302 | Classroom 302 | W1 | Plaster | White | Flaking | 1 | 13.8 | Positive |
| 1 | 3 | 302 | Classroom 302 | W2 | Plaster | White | Flaking | 20 | 11.8 | Positive |
| 1 | 3 | 302 | Classroom 302 | W3 | Plaster | White | Flaking | 20 | 0 | Negative |
| 1 | 3 | 302 | Classroom 302 | W4 | Plaster | White | Flaking | 10 | 14.4 | Positive |
| 1 | 3 | 302 | Classroom 302 | Ceiling | Plaster | Tan | Flaking | 400 | 23.5 | Positive |
| 1 | 3 | 302 | Classroom 302 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 302 | Classroom 302 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 302 | Classroom 302 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|-------------------------------------|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 302 | Classroom 302 | Radiator | Metal | Gray | Flaking | 10 | 7 | Positive |
| 1 | 3 | 302 | Classroom 302 | Radiator | Metal | Gray | Flaking | 10 | 6.4 | Positive |
| 1 | 3 | 302 | Classroom 302 | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 3 | 302 | Classroom 302 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 302 | Classroom 302 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 303 | Classroom 303 | Ceiling | Plaster | Tan | Chipping | 20 | 17.8 | Positive |
| 1 | 3 | 303 | Classroom 303 | W1 | Plaster | Gray | None | 0 | 0.2 | Negative |
| 1 | 3 | 303 | Classroom 303 | W2 | Plaster | Gray | None | 0 | 10.2 | Positive |
| 1 | 3 | 303 | Classroom 303 | W3 | Plaster | Gray | None | 0 | 18.7 | Positive |
| 1 | 3 | 303 | Classroom 303 | W4 | Plaster | Gray | Flaking | 25 | 13.6 | Positive |
| 1 | 3 | 303 | Classroom 303 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 303 | Classroom 303 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 303 | Classroom 303 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 303 | Classroom 303 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 303 | Classroom 303 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 303 | Classroom 303 | Radiators | Metal | Gray | Flaking | 5 | 3.3 | Positive |
| 1 | 3 | 303 | Classroom 303 | Radiators | Metal | Gray | Flaking | 5 | 3.9 | Positive |
| 1 | 3 | 303 | Classroom 303 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 303A | Office 303A | Ceiling | Plaster | Tan | Flaking | 50 | 18.6 | Positive |
| 1 | 3 | 303A | Office 303A | W1 | Plaster | Blue | Flaking | 25 | 18.9 | Positive |
| 1 | 3 | 303A | Office 303A | W2 | Plaster | Blue | Flaking | 10 | 11.3 | Positive |
| 1 | 3 | 303A | Office 303A | W3 | Plaster | Blue | None | 0 | 0.1 | Negative |
| 1 | 3 | 303A | Office 303A | W4 | Plaster | Blue | Flaking | 3 | 14.2 | Positive |
| 1 | 3 | 303A | Office 303A | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 303A | Office 303A | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 303A | Office 303A | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 303A | Office 303A | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 303A | Office 303A | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 303A | Office 303A | Baseboard | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 303A | Office 303A | Radiator | Metal | Gray | None | 0 | 3.7 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | W1 | Plaster | Gray | None | 0 | 17.1 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | W2 | Plaster | Gray | None | 0 | 15.5 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | W3 | Plaster | Gray | None | 0 | 18.1 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Floor | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Door Frame | Metal | Brown | None | 0 | 4.4 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Stair Tread | Concrete | Gray | None | 0 | 0.6 | Negative |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Stair Riser | Concrete | Gray | None | 0 | 1.3 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Stair Stringer | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Spindle | Metal | Gray | None | 0 | 7.7 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Post | Metal | Brown | None | 0 | 9 | Positive |
| 1 | 3 | S34 | Stairwell adjacent to Classroom 304 | Ceiling | Plaster | White | None | 0 | 19.1 | Positive |
| 1 | 3 | 304 | Classroom 304 | Ceiling | Plaster | Tan | Flaking | 400 | 23.2 | Positive |
| 1 | 3 | 304 | Classroom 304 | W1 | Plaster | Gray | None | 0 | 16.5 | Positive |
| 1 | 3 | 304 | Classroom 304 | W2 | Plaster | Gray | Flaking | 50 | 19.5 | Positive |
| 1 | 3 | 304 | Classroom 304 | W3 | Plaster | Gray | Flaking | 20 | 19 | Positive |
| 1 | 3 | 304 | Classroom 304 | W4 | Plaster | Gray | Flaking | 30 | 23.9 | Positive |
| 1 | 3 | 304 | Classroom 304 | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 304 | Classroom 304 | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 304 | Classroom 304 | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | 304 | Classroom 304 | Window Casing | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 304 | Classroom 304 | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 304 | Classroom 304 | Window Sill | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 3 | 304 | Classroom 304 | Radiator | Metal | Gray | Flaking | 10 | 7.3 | Positive |
| 1 | 3 | 304 | Classroom 304 | Radiator | Metal | Gray | Flaking | 10 | 7.1 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | W1 | Plaster | White | None | 0 | 20 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | W2 | Plaster | White | Flaking | 40 | 18.5 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | W3 | Plaster | White | Flaking | 40 | 0.3 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | W4 | Plaster | White | None | 0 | 16.1 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | Ceiling | Plaster | Tan | None | 0 | 20.5 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 304A | Classroom 304 Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | 304A | Classroom 304 Office | Radiator | Metal | Gray | None | 0 | 3.2 | Positive |
| 1 | 3 | 304A | Classroom 304 Office | Steam Pipe | Metal | Gray | None | 0 | 16.7 | Positive |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | W1 | Plaster | White | None | 0 | 5.2 | Positive |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | W2 | Plaster | White | None | 0 | 4.6 | Positive |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | W3 | Plaster | White | None | 0 | 6 | Positive |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | W4 | Plaster | White | None | 0 | 4 | Positive |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | Ceiling | Plaster | No Access | None | N/A | N/A | No Access |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | Door | Wood | Varnish | None | 0 | 0 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 304B | Classroom 304 Office Left Closet | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | W1 | Plaster | White | None | 0 | 3.3 | Positive |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | W2 | Plaster | White | None | 0 | 1.9 | Positive |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | W3 | Plaster | White | None | 0 | 2.2 | Positive |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | W4 | Plaster | White | None | 0 | 2.3 | Positive |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | Ceiling | Plaster | No Access | None | N/A | N/A | No Access |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 304C | Classroom 304 Office Right Closet | Baseboard | Wood | No Access | None | 0 | N/A | N/A |
| 1 | 3 | 305 | Classroom 305 | W1 | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 305 | Classroom 305 | W2 | Plaster | Gray | Efflorescence | 20 | 22.3 | Positive |
| 1 | 3 | 305 | Classroom 305 | W3 | Plaster | Gray | Efflorescence | 5 | 18.7 | Positive |
| 1 | 3 | 305 | Classroom 305 | W4 | Plaster | Gray | None | 0 | 3.3 | Positive |
| 1 | 3 | 305 | Classroom 305 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 305 | Classroom 305 | Ceiling | Plaster | Tan | None | 0 | 21.2 | Positive |
| 1 | 3 | 305 | Classroom 305 | Radiator | Metal | Gray | Flaking | 10 | 5.2 | Positive |
| 1 | 3 | 305 | Classroom 305 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 305 | Classroom 305 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 305 | Classroom 305 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 305 | Classroom 305 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 305 | Classroom 305 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 305A | Closet across from Classroom 305 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 305A | Closet across from Classroom 305 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 305A | Closet across from Classroom 305 | W1 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 3 | 305A | Closet across from Classroom 305 | W2 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 3 | 305A | Closet across from Classroom 305 | W3 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 3 | 305A | Closet across from Classroom 305 | W4 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 3 | 305A | Closet across from Classroom 305 | Ceiling | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 3 | 305A | Closet across from Classroom 305 | Floor | Concrete | No Access | No Access | N/A | N/A | N/A |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | W1 | Plaster | White | None | 0 | 2.6 | Positive |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | W2 | Plaster | White | None | 0 | 5.5 | Positive |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | W3 | Plaster | White | None | 0 | 4.7 | Positive |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | W4 | Plaster | White | None | 0 | 3.5 | Positive |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | Ceiling | Plaster | White | None | 0 | N/A | N/A |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 306A | Custodial Closet across from Classroom 306 | Shelf Support | Wood | White | None | 0 | 0 | Negative |
| 1 | 3 | 306 | Classroom 306 | W1 | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 306 | Classroom 306 | W2 | Plaster | White | Flaking | 10 | 10 | Positive |
| 1 | 3 | 306 | Classroom 306 | W3 | Wood | Varnish | No Access | No Access | 0 | Negative |
| 1 | 3 | 306 | Classroom 306 | W4 | Plaster | White | Flaking | 5 | 10 | Positive |
| 1 | 3 | 306 | Classroom 306 | Ceiling | Plaster | White | Flaking | 10 | 10 | Positive |
| 1 | 3 | 306 | Classroom 306 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 306 | Classroom 306 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 306 | Classroom 306 | Drain Pipe | Metal | White | Flaking | 8 | 0.3 | Negative |
| 1 | 3 | 306 | Classroom 306 | Radiator | Metal | Gray | Chipping | 8 | 2.2 | Positive |
| 1 | 3 | 306 | Classroom 306 | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 306 | Classroom 306 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 306 | Classroom 306 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 307 | Classroom 307 | W1 | Plaster | White | Flaking | 15 | 20.5 | Positive |
| 1 | 3 | 307 | Classroom 307 | W2 | Plaster | White | Flaking | 15 | 18.9 | Positive |
| 1 | 3 | 307 | Classroom 307 | W3 | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 307 | Classroom 307 | W4 | Plaster | White | Flaking | 20 | 18.9 | Positive |
| 1 | 3 | 307 | Classroom 307 | Ceiling | Plaster | Tan | Flaking | 50 | 22.9 | Positive |
| 1 | 3 | 307 | Classroom 307 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 307 | Classroom 307 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 307 | Classroom 307 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 307 | Classroom 307 | Window Casing | Wood | Varnish | None | 0 | 0.9 | Positive |
| 1 | 3 | 307 | Classroom 307 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 307 | Classroom 307 | Window Apron | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 307 | Classroom 307 | Radiator | Metal | Gray | Flaking | 10 | 3.3 | Positive |
| 1 | 3 | 307 | Classroom 307 | Radiator | Metal | Gray | Flaking | 10 | 3.1 | Positive |
| 1 | 3 | 307 | Classroom 307 | Radiator | Metal | Gray | Flaking | 10 | 1.4 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | W1 | Plaster | Gray | None | 0 | 15.3 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | W2 | Plaster | Gray | Efflorescence | 10 | 0 | Negative |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | W3 | Plaster | Gray | None | 0 | 22.1 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Floor | Concrete | Gray | None | 0 | 1.1 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Door Frame | Metal | Brown | None | 0 | 4.4 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Stair Tread | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Stair Riser | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Stair Stringer | Concrete | Gray | None | 0 | 2.4 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Spindle | Metal | Gray | None | 0 | 7.2 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--------------------------------------|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Post | Metal | Brown | None | 0 | 6.7 | Positive |
| 1 | 3 | S33 | Stairwell adjacent to Classroom 308 | Ceiling | Plaster | White | None | 0 | 19.4 | Positive |
| 1 | 3 | 308 | Classroom 308 | W1 | Plaster | Blue | Flaking | 2 | 16.9 | Positive |
| 1 | 3 | 308 | Classroom 308 | W2 | Plaster | Gray | None | 0 | 15.3 | Positive |
| 1 | 3 | 308 | Classroom 308 | W3 | Plaster | Gray | None | 0 | 20.2 | Positive |
| 1 | 3 | 308 | Classroom 308 | W4 | Plaster | Gray | None | 0 | 22.9 | Positive |
| 1 | 3 | 308 | Classroom 308 | Ceiling | Plaster | Tan | Chipping | 40 | 23.9 | Positive |
| 1 | 3 | 308 | Classroom 308 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 308 | Classroom 308 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 308 | Classroom 308 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 308 | Classroom 308 | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 3 | 308 | Classroom 308 | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 308 | Classroom 308 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 308 | Classroom 308 | Radiator | Metal | Gray | Flaking | 5 | 3.4 | Positive |
| 1 | 3 | 308 | Classroom 308 | Radiator | Metal | Gray | Flaking | 5 | 4.9 | Positive |
| 1 | 3 | 308 | Classroom 308 | Radiator | Metal | Gray | None | 0 | 3.5 | Positive |
| 1 | 3 | 309 | Weight Room 309 | W1 | Plaster | White | Flaking | 40 | 18.6 | Positive |
| 1 | 3 | 309 | Weight Room 309 | W2 | Plaster | White | Efflorescence | 40 | 9.8 | Positive |
| 1 | 3 | 309 | Weight Room 309 | W3 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 3 | 309 | Weight Room 309 | W4 | Plaster | White | None | 0 | 15.2 | Positive |
| 1 | 3 | 309 | Weight Room 309 | Ceiling | Plaster | Tan | Flaking | 200 | 0.4 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Door | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Baseboard | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Radiator Cover | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 3 | 309 | Weight Room 309 | Radiator | Metal | Gray | Flaking | 5 | 4.4 | Positive |
| 1 | 3 | 309 | Weight Room 309 | Radiator | Metal | Gray | Flaking | 5 | 0.4 | Negative |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | W1 | Brick | White | None | 0 | 8.2 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | W2 | Brick | White | None | 0 | 10 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | W3 | Brick | White | None | 0 | 13.8 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | W4 | Brick | White | None | 0 | 5.3 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Ceiling | Concrete | White | Flaking | 15 | 9.1 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Floor | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Door | Metal | Brown | Flaking | 5 | 0 | Negative |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Door Frame | Metal | Brown | Flaking | 12 | 0.4 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Security Gate | Metal | Brown | Flaking | 100 | 28.3 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Drain Pipe | Metal | Brown | Flaking | 24 | 1.3 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Handrail | Metal | Brown | Chipping | 14 | 2.7 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Stair Riser | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Stair Tread | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 3 | S35 | Fire Tower adjacent to Classroom 309 | Stair Stringer | Concrete | Gray | None | 0 | 2.5 | Positive |
| 1 | 3 | 310 | Classroom 310 | W1 | Plaster | Gray | Flaking | 20 | 20.3 | Positive |
| 1 | 3 | 310 | Classroom 310 | W2 | Plaster | Gray | Flaking | 15 | 22.7 | Positive |
| 1 | 3 | 310 | Classroom 310 | W3 | Plaster | Gray | Flaking | 5 | 0 | Negative |
| 1 | 3 | 310 | Classroom 310 | W4 | Plaster | Gray | None | 0 | 0.1 | Negative |
| 1 | 3 | 310 | Classroom 310 | Ceiling | Plaster | Tan | Flaking | 200 | 18.3 | Positive |
| 1 | 3 | 310 | Classroom 310 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 310 | Classroom 310 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 310 | Classroom 310 | Window Casing | Wood | Varnish | None | 0 | 0.7 | Positive |
| 1 | 3 | 310 | Classroom 310 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 310 | Classroom 310 | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 310 | Classroom 310 | Chair Rail | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 310 | Classroom 310 | Crown Molding | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 310 | Classroom 310 | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 310 | Classroom 310 | Radiator | Metal | Gray | Flaking | 5 | 4.6 | Positive |
| 1 | 3 | 310 | Classroom 310 | Radiator | Metal | Gray | Flaking | 5 | 7 | Positive |
| 1 | 3 | 310 | Classroom 310 | Radiator | Metal | Gray | Flaking | 5 | 3.7 | Positive |
| 1 | 3 | 310 | Classroom 310 | Closet Door | Wood | Blue | None | 0 | 0.1 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | W1 | Plaster | White | None | 0 | 12.2 | Positive |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | W2 | Plaster | White | None | 0 | 15.7 | Positive |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | W3 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | W4 | Plaster | White | Flaking | 5 | 0 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Ceiling | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Door Frame | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Radiator | Metal | Gray | Flaking | 10 | 0 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | 311 | Girl's Restroom adjacent to Classroom 310 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | Door | Wood | White | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | Door Frame | Wood | White | None | 0 | 0 | Negative |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 311A | Pipe Chase in Girl's Restroom adjacent to Classroom 310 | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 316 | Gymnasium | W1 | Plaster | White | None | 0 | 23.8 | Positive |
| 1 | 3 | 316 | Gymnasium | W2 | Plaster | White | None | 0 | 17.8 | Positive |
| 1 | 3 | 316 | Gymnasium | W3 | Plaster | White | None | 0 | 0.1 | Negative |
| 1 | 3 | 316 | Gymnasium | W4 | Plaster | White | None | 0 | 18.2 | Positive |
| 1 | 3 | 316 | Gymnasium | Ceiling | Concrete | White | Cracking | 40 | No Access | Assumed |
| 1 | 3 | 316 | Gymnasium | Covebase | Concrete | Brown | None | 0 | 12.6 | Positive |
| 1 | 3 | 316 | Gymnasium | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 316 | Gymnasium | Door Frame | Metal | Gray | None | 0 | 0.5 | Negative |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | 316 | Gymnasium | Radiator | Metal | Gray | No Access | No Access | No Access | No Access |
| 1 | 3 | S316 | Stairwell to Gymnasium Balcony | W1 | Plaster | Tan | Flaking | 40 | 0 | Negative |
| 1 | 3 | S316 | Stairwell to Gymnasium Balcony | W2 | Plaster | Tan | None | 0 | 16.2 | Positive |
| 1 | 3 | S316 | Stairwell to Gymnasium Balcony | W3 | Plaster | Tan | None | 0 | 16.3 | Positive |
| 1 | 3 | S316 | Stairwell to Gymnasium Balcony | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | S316 | Stairwell to Gymnasium Balcony | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 4 | 414 | Gymnasium Balcony | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | W1 | Plaster | Blue | None | 0 | 12.2 | Positive |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | W2 | Plaster | Blue | None | 0 | 11.1 | Positive |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | W3 | Plaster | Blue | None | 0 | 14.4 | Positive |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | W4 | Plaster | Blue | None | 0 | 10.3 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Ceiling | Plaster | Blue | None | 0 | 12.4 | Positive |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 3 | 314 | Gymnasium Office on Boy's Side | Radiator | Metal | Gray | Flaking | 10 | 0.4 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | W1 | Plaster | Blue | None | 0 | 7.3 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | W2 | Plaster | Blue | None | 0 | 8 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | W3 | Plaster | Blue | None | 0 | 9.3 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | W4 | Plaster | Blue | None | 0 | 7.8 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Ceiling | Plaster | White | None | 0 | 8 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Duct | Metal | White | None | 0 | 9.2 | Positive |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 314A | Gymnasium Office on Boy's Side Restroom | Radiator | Metal | Gray | Chipping | 10 | 2 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | W1 | Plaster | Blue | None | 0 | 14.5 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | W2 | Plaster | Blue | None | 0 | 15 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | W3 | Plaster | Blue | None | 0 | 11.3 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | W4 | Plaster | Blue | None | 0 | 16.4 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Ceiling | Plaster | White | None | 0 | 12 | Positive |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Chair Rail | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 315 | Gymnasium Office on Girl's Side | Radiator | Metal | Gray | Flaking | 3 | 0.2 | Negative |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | W1 | Plaster | White | None | 0 | 12.9 | Positive |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | W2 | Plaster | White | None | 0 | 9.8 | Positive |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | W3 | Plaster | White | None | 0 | 14.3 | Positive |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | W4 | Plaster | White | None | 0 | 7.7 | Positive |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | Ceiling | Plaster | White | None | 0 | 14.7 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 315A | Gymnasium Office on Girl's Side Restroom | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | W1 | Plaster | White | None | 0 | 0.3 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | W2 | CMU | White | None | 0 | 0.1 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | W3 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312 | Boy's Locker Room | W4 | Plaster | White | Efflorescence | 16 | 10.2 | Positive |
| 1 | 3 | 312 | Boy's Locker Room | Floor | Concrete | Gray | None | 0 | 0.2 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | Ceiling | Plaster | Gray | Efflorescence | 70 | 12.1 | Positive |
| 1 | 3 | 312 | Boy's Locker Room | Radiator | Concrete | Gray | Flaking | 10 | 0.1 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | Sanitary Line | Concrete | White | Flaking | 10 | 0.2 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 312 | Boy's Locker Room | Radiator | Metal | Gray | None | 0 | 0.9 | Positive |
| 1 | 3 | 312 | Boy's Locker Room | Duct | Metal | White | None | 0 | 10.5 | Positive |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | W1 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | W2 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | W3 | CMU | White | None | 0 | 0 | Negative |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | W4 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | Ceiling | Plaster | White | Flaking | 10 | 8 | Positive |
| 1 | 3 | 312A | Boy's Locker Room Storage Room | Floor | Concrete | Grey | None | 0 | 0.4 | Negative |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | W1 | Plaster | Tan | None | 0 | 6.2 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | W2 | Plaster | Tan | Flaking | 25 | 7 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | W3 | Plaster | Tan | Flaking | 25 | 7.9 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | W4 | Plaster | Tan | Flaking | 5 | 6.2 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | Ceiling | Plaster | White | Flaking | 10 | 5.9 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | Drain Pipe | Metal | White | Flaking | 8 | 8.5 | Positive |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 312B | Boy's Locker Room Storage Closet | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | W1 | Plaster | Tan | None | 0 | 3.1 | Positive |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | W2 | Plaster | Tan | None | 0 | 0.2 | Negative |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | W3 | Plaster | Tan | None | 0 | 1.6 | Positive |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | W4 | Plaster | Tan | None | 0 | 0.5 | Negative |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312C | Closet adjacent to Boy's Locker Room | Ceiling | Plaster | Tan | Cracking | 3 | 2.7 | Positive |
| 1 | 3 | 312D | Girl's Locker Room | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 3 | 312D | Girl's Locker Room | W1 | Wood | White | None | 0 | 0.1 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | W2 | CMU | White | None | 0 | 0.2 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | W3 | Plaster | White | None | 0 | 0.1 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | W4 | Plaster | White | Efflorescence | 40 | 9.2 | Positive |
| 1 | 3 | 312D | Girl's Locker Room | Ceiling | Concrete | White | Flaking | 60 | 16.4 | Positive |
| 1 | 3 | 312D | Girl's Locker Room | Radiator | Metal | Gray | Flaking | 10 | 0.1 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | Sanitary Line | Metal | White | Flaking | 20 | 3 | Positive |
| 1 | 3 | 312D | Girl's Locker Room | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 312D | Girl's Locker Room | Window Sill | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | W1 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | W2 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | W3 | CMU | White | None | 0 | 0 | Negative |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | W4 | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | Ceiling | Plaster | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | Door Frame | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | Drain Pipe | Metal | White | Flaking | 10 | 0.1 | Negative |
| 1 | 3 | 312E | Girl's Locker Room Storage Room | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | W1 | Plaster | Tan | Cracking | 15 | 5.9 | Positive |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | W2 | Plaster | Tan | Cracking | 15 | 6.2 | Positive |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | W3 | Plaster | Tan | None | 0 | 6.7 | Positive |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | W4 | Plaster | Tan | None | 0 | 6.7 | Positive |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | Ceiling | Plaster | Tan | Flaking | 20 | 7.1 | Positive |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | 312F | Girl's Locker Room Storage Closet | Drain Pipe | Metal | White | Flaking | 10 | 0 | Negative |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | W1 | Plaster | Gray | Flaking | 10 | 0.1 | Negative |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | W2 | Plaster | Gray | None | 0 | 17.3 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | W3 | Plaster | Gray | Flaking | 10 | 9.3 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | W4 | Plaster | Gray | None | 0 | 1.1 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | Ceiling | Plaster | Tan | None | 0 | 15.1 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | Covebase | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | Stair Tread | Concrete | Blue | None | 0 | 4.3 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | Stair Riser | Concrete | Blue | None | 0 | 7.4 | Positive |
| 1 | 3 | H31A | Hallway outside 3rd Floor Boy's Restroom | Stair Stringer | Concrete | Blue | None | 0 | 3.8 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | W1 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | W2 | Plaster | Gray | None | 0 | 17.5 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | W3 | Plaster | Gray | None | 0 | 23.9 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | W4 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Floor | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Ceiling | Plaster | Tan | Peeling | 100 | 21.8 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Lockers | Metal | Red | None | 0 | 0 | Negative |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Radiators | Metal | Gray | None | 0 | 0.1 | Negative |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Radiators | Metal | Gray | None | 0 | 2.1 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Radiators | Metal | Gray | None | 0 | 2.4 | Positive |
| 1 | 3 | H31 | Hallway outside Classroom 301 to Office 303A | Electrical Panel | Metal | Gray | None | 0 | 3.5 | Positive |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H31PCS | Pipe/Cable Shaft in Hallway next to Classroom 302 | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | W1 | Plaster | Gray | None | 0 | 18.7 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | W2 | Plaster | Gray | None | 0 | 19.3 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | W3 | Plaster | Gray | None | 0 | 21.3 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | W4 | Plaster | Gray | None | 0 | 19.4 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | Ceiling | Plaster | Tan | Cracking | 100 | 20.1 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | Floor | Concrete | Gray | None | 0 | 1.9 | Positive |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | Elevator Door | Metal | White | None | 0 | 0.1 | Negative |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | Elevator Door Frame | Metal | White | None | 0 | 0.2 | Negative |
| 1 | 3 | H33 | Hallway from Classrooms 304 to 307 | Crown Molding | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H33A | Stairs to Gym | W1 | Plaster | Gray | None | 0 | 16.5 | Positive |
| 1 | 3 | H33A | Stairs to Gym | W2 | Plaster | Gray | None | 0 | 0.1 | Negative |
| 1 | 3 | H33A | Stairs to Gym | W3 | Plaster | Gray | None | 0 | 19.5 | Positive |
| 1 | 3 | H33A | Stairs to Gym | Ceiling | Plaster | Tan | None | 0 | 14.8 | Positive |
| 1 | 3 | H33A | Stairs to Gym | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H33A | Stairs to Gym | Door Frame | Metal | Gray | None | 0 | 0.5 | Negative |
| 1 | 3 | H33A | Stairs to Gym | Stair Tread | Concrete | Gray | None | 0 | 0.5 | Negative |
| 1 | 3 | H33A | Stairs to Gym | Stair Riser | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 3 | H33A | Stairs to Gym | Stair Stringer | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 3 | H33A | Stairs to Gym | CoveBase | Concrete | Gray | None | 0 | 5.1 | Positive |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | Door | Wood | Varnish | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 304 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | Door Frame | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | W1 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | W2 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | W3 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 3 | H33PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 304 | W4 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H33PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 307 | No Access | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | W1 | Plaster | Gray | None | 0 | 19.6 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | W2 | Plaster | Gray | None | 0 | 25.6 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | W3 | Plaster | Gray | None | 0 | 15.4 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | W4 | Plaster | Gray | None | 0 | 28.4 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Ceiling | Plaster | Tan | Cracking | 100 | 19.7 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Floor | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Lockers | Metal | Red | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Radiator | Metal | Gray | Flaking | 2 | 1.2 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Radiator | Metal | Gray | None | 0 | 0.2 | Negative |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Radiator | Metal | Gray | Flaking | 2 | 1 | Positive |
| 1 | 3 | H32 | Hallway from Classrooms 308 to 310 | Crown Molding | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 3 | H32PCS | Pipe/Cable Shaft in Hallway next to Classroom 308 | W4 | No Access | No Access | N/A | N/A | No Access | No Access |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | W1 | Plaster | Gray | None | 0 | 21.9 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | W2 | Plaster | Gray | None | 0 | 18.8 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | W3 | Plaster | Gray | None | 0 | 20.6 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | W4 | Plaster | Gray | None | 0 | 25.9 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Floor | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Ceiling | Plaster | White | None | 0 | 20.9 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Stair Tread | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Stair Riser | Concrete | Gray | None | 0 | 6.1 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Stair Stringer | Concrete | Gray | None | 0 | 5.4 | Positive |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Elevator Door | Metal | Pink | None | 0 | 0 | Negative |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Elevator Door Frame | Metal | Pink | Flaking | 5 | 0.1 | Negative |
| 1 | 3 | H32A | Hallway outside 3rd Floor Girl's Restroom | Crown Molding | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 212B | Pipe Shaft adjacent to 2nd Floor Boy's Restroom | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | W1 | Plaster | White | Flaking | 5 | 13.9 | Positive |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | W2 | Plaster | White | Flaking | 15 | 0 | Negative |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | W3 | Plaster | White | Flaking | 25 | 12.6 | Positive |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | W4 | Plaster | White | Flaking | 40 | 13.3 | Positive |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Ceiling | Concrete | White | None | 0 | 11.4 | Positive |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Floor | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Door Frame | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Window Casing | Wood | Brown | None | 0 | 0.5 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Radiator | Metal | Gray | Flaking | 20 | 0 | Negative |
| 1 | 2 | 212 | Boy's Restroom adjacent to Office Suite 201 | Drain Pipe | Metal | Gray | Flaking | 8 | 10 | Positive |
| 1 | 2 | 212A | Pipe Chase in Boy's Restroom adjacent to Office Suite 201 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 212A | Pipe Chase in Boy's Restroom adjacent to Office Suite 201 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 212A | Pipe Chase in Boys Restroom adjacent to Office Suite 201 | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 212A | Pipe Chase in Boy's Restroom adjacent to Office Suite 201 | W2 | Plaster | White | None | 0 | 10 | Positive |
| 1 | 2 | 212A | Pipe Chase in Boy's Restroom adjacent to Office Suite 201 | W3 | Plaster | White | None | 0 | 10 | Positive |
| 1 | 2 | 212A | Pipe Chase in Boy's Restroom adjacent to Office Suite 201 | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201D | Office Suite 201 Common Area | W1 | Wood | White | None | 0 | 0 | Negative |
| 1 | 2 | 201D | Office Suite 201 Common Area | W2 | Wood | White | None | 0 | 0 | Negative |
| 1 | 2 | 201D | Office Suite 201 Common Area | W3 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 2 | 201D | Office Suite 201 Common Area | W4 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 2 | 201D | Office Suite 201 Common Area | Ceiling | Plaster | Tan | Flaking | 50 | 23.4 | Positive |
| 1 | 2 | 201D | Office Suite 201 Common Area | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201D | Office Suite 201 Common Area | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201D | Office Suite 201 Common Area | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | W2 | Plaster | Tan | None | 0 | 20.9 | Positive |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | W3 | Plaster | Tan | None | 0 | 15.3 | Positive |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | Floor | Linoleum | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201E | Office Suite 201 Common Area Pipe Chase | Ceiling | Plaster | Tan | No Access | No Access | No Access | No Access |
| 1 | 2 | 201A | Office Suite 201 Right Office | W1 | Wood | Green | None | 0 | 0 | Negative |
| 1 | 2 | 201A | Office Suite 201 Right Office | W2 | Plaster | Green | Cracking | 50 | 23.1 | Positive |
| 1 | 2 | 201A | Office Suite 201 Right Office | W3 | Plaster | Green | Cracking | 5 | 26.1 | Positive |
| 1 | 2 | 201A | Office Suite 201 Right Office | W4 | Plaster | Green | Flaking | 5 | 0.1 | Negative |
| 1 | 2 | 201A | Office Suite 201 Right Office | Ceiling | Plaster | Tan | Flaking | 50 | 15.9 | Positive |
| 1 | 2 | 201A | Office Suite 201 Right Office | Radiator | Metal | Gray | Flaking | 12 | 4.3 | Positive |
| 1 | 2 | 201A | Office Suite 201 Right Office | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201A | Office Suite 201 Right Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201A | Office Suite 201 Right Office | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--------------------------------------|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 2 | 201A | Office Suite 201 Right Office | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201A | Office Suite 201 Right Office | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 201A | Office Suite 201 Right Office | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | W1 | Wood | White | None | 0 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | W2 | Plaster | White | Flaking | 5 | 0.2 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | W3 | Wood | White | None | 0 | 0.2 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | W4 | Wood | White | None | 0 | 0 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Ceiling | Plaster | Tan | Flaking | 25 | 18.3 | Positive |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Radiator | Metal | Gray | Flaking | 8 | 0.1 | Negative |
| 1 | 2 | 201B | Office Suite 201 Center Right Office | Drain Pipe | Metal | White | Flaking | 4 | 22.4 | Positive |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | W1 | Wood | Blue | None | 0 | 0 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | W2 | Plaster | Blue | Flaking | 10 | 0.4 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | W3 | Plaster | Blue | Flaking | 10 | 25 | Positive |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | W4 | Wood | Blue | None | 0 | 0 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Ceiling | Plaster | Tan | Efflorescence | 15 | 20.8 | Positive |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201C | Office Suite 201 Center Left Office | Radiator | Metal | Gray | Flaking | 5 | 3.6 | Positive |
| 1 | 2 | 201 | Office Suite 201 Left Office | W1 | Plaster | Blue | None | 0 | 6.6 | Positive |
| 1 | 2 | 201 | Office Suite 201 Left Office | W2 | Plaster | Blue | None | 0 | 8.2 | Positive |
| 1 | 2 | 201 | Office Suite 201 Left Office | W3 | Wood | Blue | None | 0 | 0 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | W4 | Wood | Blue | None | 0 | 0 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | Floor | 9 x 9 floor tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 201 | Office Suite 201 Left Office | Ceiling | Plaster | Tan | Flaking | 15 | 18.9 | Positive |
| 1 | 2 | 201 | Office Suite 201 Left Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--------------------------------------|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 2 | 201 | Office Suite 201 Left Office | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 201 | Office Suite 201 Left Office | Radiator | Metal | Gray | None | 0 | 0.9 | Positive |
| 1 | 2 | 201 | Office Suite 201 Left Office | Wall Baseboard | Plaster | Brown | None | 0 | 5.8 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | W1 | Brick | White | None | 0 | 7.6 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | W2 | Brick | White | None | 0 | 6.7 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | W3 | Brick | White | None | 0 | 5.8 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | W4 | Brick | White | None | 0 | 9.8 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Ceiling | Concrete | White | None | 0 | 11.4 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Floor | Concrete | Gray | None | 0 | 3.4 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Door | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Door Frame | Metal | Brown | None | 0 | 0.4 | Negative |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Security Gate | Metal | Brown | Flaking | 100 | 5.9 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Drain Pipe | Metal | Brown | Flaking | 24 | 1 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Handrail | Metal | Brown | Chipping | 10 | 1 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Stair Riser | Concrete | Gray | None | 0 | 2.5 | Positive |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Stair Treads | Concrete | Gray | None | 0 | 0.2 | Negative |
| 1 | 2 | S26 | Fire Tower adjacent to Classroom 202 | Stair Stringer | Concrete | Gray | None | 0 | 2.3 | Positive |
| 1 | 2 | 202 | Classroom 202 | W1 | Plaster | White | None | 0 | 9.4 | Positive |
| 1 | 2 | 202 | Classroom 202 | W2 | Plaster | White | None | 0 | 2.5 | Positive |
| 1 | 2 | 202 | Classroom 202 | W3 | Plaster | White | Cracking | 8 | 25.6 | Positive |
| 1 | 2 | 202 | Classroom 202 | W4 | Plaster | White | Flaking | 50 | 11.7 | Positive |
| 1 | 2 | 202 | Classroom 202 | Ceiling | Plaster | Tan | Flaking | 250 | 22.1 | Positive |
| 1 | 2 | 202 | Classroom 202 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 202 | Classroom 202 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 202 | Classroom 202 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 202 | Classroom 202 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 202 | Classroom 202 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 202 | Classroom 202 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 202 | Classroom 202 | Baseboard | Wood | Brown | Cracking | 10 | 0.3 | Negative |
| 1 | 2 | 202 | Classroom 202 | Radiator | Metal | Gray | Flaking | 10 | 3.4 | Positive |
| 1 | 2 | 202 | Classroom 202 | Radiator | Metal | Gray | Flaking | 15 | 3.5 | Positive |
| 1 | 2 | 203 | Classroom 203 | W1 | Plaster | White | None | 0 | 11.5 | Positive |
| 1 | 2 | 203 | Classroom 203 | W2 | Plaster | Blue | Flaking | 10 | 14.5 | Positive |
| 1 | 2 | 203 | Classroom 203 | W3 | Plaster | White | None | 0 | 21.7 | Positive |
| 1 | 2 | 203 | Classroom 203 | W4 | Plaster | White | Flaking | 20 | 5.4 | Positive |
| 1 | 2 | 203 | Classroom 203 | Ceiling | Plaster | Tan | None | 0 | 20.8 | Positive |
| 1 | 2 | 203 | Classroom 203 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 203 | Classroom 203 | Baseboard | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|---|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 203 | Classroom 203 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 203 | Classroom 203 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 203 | Classroom 203 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 203 | Classroom 203 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 203 | Classroom 203 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 203 | Classroom 203 | Radiator | Metal | Gray | Flaking | 10 | 4.5 | Positive |
| 1 | 2 | 203 | Classroom 203 | Radiator | Metal | Gray | Flaking | 10 | 3.7 | Positive |
| 1 | 2 | 204 | Classroom 204 | W1 | Plaster | Gray | None | 0 | 10.8 | Positive |
| 1 | 2 | 204 | Classroom 204 | W2 | Plaster | Gray | None | 0 | 13.7 | Positive |
| 1 | 2 | 204 | Classroom 204 | W3 | Plaster | Gray | None | 0 | 21.4 | Positive |
| 1 | 2 | 204 | Classroom 204 | W4 | Plaster | Gray | None | 0 | 21.4 | Positive |
| 1 | 2 | 204 | Classroom 204 | Ceiling | Plaster | Tan | Flaking | 300 | 19.6 | Positive |
| 1 | 2 | 204 | Classroom 204 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204 | Classroom 204 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 204 | Classroom 204 | Chair Rail | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 204 | Classroom 204 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 204 | Classroom 204 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 204 | Classroom 204 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 204 | Classroom 204 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 204 | Classroom 204 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204 | Classroom 204 | Radiator | Metal | Gray | Flaking | 10 | 2.5 | Positive |
| 1 | 2 | 204 | Classroom 204 | Radiator | Metal | Gray | Flaking | 5 | 5.4 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | W1 | Plaster | Gray | None | 0 | 15.9 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | W2 | Plaster | Gray | None | 0 | 18.2 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | W3 | Plaster | Gray | None | 0 | 19.5 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Ceiling | Plaster | Gray | None | 0 | 18.9 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Floor | Concrete | Gray | None | 0 | 0.8 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Stair Treads | Concrete | Gray | None | 0 | 0.4 | Negative |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Stair Riser | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Stair Stringer | Concrete | Gray | None | 0 | 1.1 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Post | Metal | Brown | None | 0 | 10.1 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Spindle | Metal | Brown | None | 0 | 7.1 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Door Frame | Metal | Brown | None | 0 | 7.2 | Positive |
| 1 | 2 | S24 | Stairwell adjacent to Main Office | Radiator | Metal | Gray | None | 0 | 1.1 | Positive |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|---|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 204E | Main Distribution Frame Room located in Stairwell adjacent to Main Office | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 204C | Main Office | W1 | Plaster | Gray | None | 0 | 9.1 | Positive |
| 1 | 2 | 204C | Main Office | W1 | Plaster | Purple | None | 0 | 27.2 | Positive |
| 1 | 2 | 204C | Main Office | W2 | Plaster | Purple | None | 0 | 21.6 | Positive |
| 1 | 2 | 204C | Main Office | W3 | Plaster | Gray | None | 0 | 20.7 | Positive |
| 1 | 2 | 204C | Main Office | W3 | Plaster | Purple | None | 0 | 26.3 | Positive |
| 1 | 2 | 204C | Main Office | W4 | Plaster | Gray | None | 0 | 24.4 | Positive |
| 1 | 2 | 204C | Main Office | W4 | Plaster | Purple | None | 0 | 24.2 | Positive |
| 1 | 2 | 204C | Main Office | Ceiling | Plaster | Tan | None | 0 | 19.2 | Positive |
| 1 | 2 | 204C | Main Office | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204C | Main Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 204C | Main Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204C | Main Office | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 204C | Main Office | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 204C | Main Office | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204C | Main Office | Chair Rail | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 204C | Main Office | Radiator | Metal | Gray | Flaking | 8 | 3.2 | Positive |
| 1 | 2 | 204C | Main Office | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | W1 | Plaster | White | None | 0 | 28.6 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | W2 | Plaster | White | None | 0 | 28.3 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | W3 | Plaster | White | None | 0 | 27.8 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | W4 | Plaster | White | None | 0 | 28.2 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | Ceiling | Plaster | Tan | None | 0 | 18 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204B | Main Office Copy Room | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | Chair Rail | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | Radiator | Metal | Grey | Flaking | 3 | 2.8 | Positive |
| 1 | 2 | 204B | Main Office Copy Room | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | Door frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------|-------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 204B | Main Office Copy Room | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204B | Main Office Copy Room | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 204F | Main Office Closet with Sink | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204F | Main Office Closet with Sink | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204F | Main Office Closet with Sink | W1 | Plaster | Green | None | 0 | 21.3 | Positive |
| 1 | 2 | 204F | Main Office Closet with Sink | W2 | Plaster | Green | None | 0 | 19.3 | Positive |
| 1 | 2 | 204F | Main Office Closet with Sink | W3 | Plaster | Green | None | 0 | 22.1 | Positive |
| 1 | 2 | 204F | Main Office Closet with Sink | W4 | No Access | Green | None | 0 | No Access | No Access |
| 1 | 2 | 204F | Main Office Closet with Sink | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204F | Main Office Closet with Sink | Ceiling | Plaster | Green | None | 0 | No Access | No Access |
| 1 | 2 | 204G | Main Office Storage Closet | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204G | Main Office Storage Closet | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204G | Main Office Storage Closet | W1 | Plaster | Tan | None | 0 | 21.1 | Positive |
| 1 | 2 | 204G | Main Office Storage Closet | W2 | Plaster | Tan | None | 0 | 21.4 | Positive |
| 1 | 2 | 204G | Main Office Storage Closet | W3 | Plaster | Tan | None | 0 | 21.8 | Positive |
| 1 | 2 | 204G | Main Office Storage Closet | W4 | Plaster | Tan | None | 0 | 26.7 | Positive |
| 1 | 2 | 204G | Main Office Storage Closet | Shelf | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204A | Principal's Office | W1 | Plaster | Brown | None | 0 | 26.4 | Positive |
| 1 | 2 | 204A | Principal's Office | W1 | Plaster | Yellow | None | 0 | 26.3 | Positive |
| 1 | 2 | 204A | Principal's Office | W2 | Plaster | Brown | None | 0 | 26 | Positive |
| 1 | 2 | 204A | Principal's Office | W2 | Plaster | Yellow | None | 0 | 28.6 | Positive |
| 1 | 2 | 204A | Principal's Office | W2 | Plaster | Red | None | 0 | 25.7 | Positive |
| 1 | 2 | 204A | Principal's Office | W3 | Plaster | Yellow | None | 0 | 20.6 | Positive |
| 1 | 2 | 204A | Principal's Office | W3 | Plaster | Brown | None | 0 | 31 | Positive |
| 1 | 2 | 204A | Principal's Office | W4 | Plaster | Yellow | None | 0 | 24.9 | Positive |
| 1 | 2 | 204A | Principal's Office | W4 | Plaster | Brown | None | 0 | 25 | Positive |
| 1 | 2 | 204A | Principal's Office | W4 | Plaster | Red | None | 0 | 22.9 | Positive |
| 1 | 2 | 204A | Principal's Office | Ceiling | Plaster | Tan | None | 0 | 26.5 | Positive |
| 1 | 2 | 204A | Principal's Office | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204A | Principal's Office | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 204A | Principal's Office | Chair Rail | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 204A | Principal's Office | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 2 | 204A | Principal's Office | Radiator | Metal | Gray | Flaking | 10 | 0.7 | Positive |
| 1 | 2 | 204A | Principal's Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 204A | Principal's Office | Door frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 204A | Principal's Office | Window Casing | Wood | Brown | None | 0 | 0.4 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 204A | Principal's Office | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 204A | Principal's Office | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | W1 | Plaster | Red | None | 0 | 22.8 | Positive |
| 1 | 2 | 204D | Principal's Office Restroom | W2 | Plaster | Yellow | None | 0 | 0.1 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | W3 | Plaster | Red | None | 0 | 2.4 | Positive |
| 1 | 2 | 204D | Principal's Office Restroom | W4 | Plaster | Yellow | None | 0 | 22.7 | Positive |
| 1 | 2 | 204D | Principal's Office Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | Door Frame | Wood | Brown | None | 0 | 2.2 | Positive |
| 1 | 2 | 204D | Principal's Office Restroom | Window Casing | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | Window Sill | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | Window Apron | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 204D | Principal's Office Restroom | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 2 | 204D | Principal's Office Restroom | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 204H | Principal's Office Closet | W1 | Plaster | Multi | None | 0 | 2.5 | Positive |
| 1 | 2 | 204H | Principal's Office Closet | W2 | Plaster | Multi | None | 0 | 3 | Positive |
| 1 | 2 | 204H | Principal's Office Closet | W3 | Plaster | Multi | None | 0 | 2.5 | Positive |
| 1 | 2 | 204H | Principal's Office Closet | W4 | Plaster | Multi | None | 0 | No Access | No Access |
| 1 | 2 | 204H | Principal's Office Closet | Ceiling | Plaster | Tan | None | 0 | None | No Access |
| 1 | 2 | 204H | Principal's Office Closet | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 213 | Auditorium Balcony | W1 | Plaster | White | Cracking | 20 | 20.2 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | W3 | Plaster | White | Efflorescence | 40 | 19.6 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | W4 | Plaster | White | Cracking | 60 | 21.1 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Ceiling | Plaster | White | Flaking | 20 | 0.9 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Floor | Linoleum | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 213 | Auditorium Balcony | Baseboard | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 213 | Auditorium Balcony | Window Casing | Wood | Varnish | None | 0 | 15.6 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Window Sill | Wood | Varnish | None | 0 | 13.8 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Window Apron | Wood | Varnish | None | 0 | 14.2 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Side Panel | Plaster | White | None | 0 | 14.6 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Door | Wood | White | None | 0 | 14.1 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Door Frame | Wood | White | None | 0 | 16.8 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Kick Plate | Wood | White | None | 0 | 11.4 | Positive |
| 1 | 2 | 213 | Auditorium Balcony | Cornice | Plaster | White | Efflorescence | 100 | 16.8 | Positive |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | W1 | Plaster | White | Chipping | 3 | 19.9 | Positive |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | W2 | Plaster | White | Flaking | 10 | 22.7 | Positive |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | W3 | Plaster | White | Flaking | 2 | 19.7 | Positive |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | W4 | Plaster | White | Flaking | 5 | 20.2 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Ceiling | Plaster | White | Flaking | 40 | 18.1 | Positive |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Baseboard | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 2 | 213A | Auditorium Balcony Projection Room | Drain Pipe | Metal | White | Flaking | 5 | 0 | Negative |
| 1 | 2 | 205 | IMC 205 | W1 | Plaster | White | None | 0 | 32 | Positive |
| 1 | 2 | 205 | IMC 205 | W2 | Plaster | White | None | 0 | 22.8 | Positive |
| 1 | 2 | 205 | IMC 205 | W3 | Plaster | White | None | 0 | 32 | Positive |
| 1 | 2 | 205 | IMC 205 | W4 | Plaster | White | None | 0 | 27.7 | Positive |
| 1 | 2 | 205 | IMC 205 | Ceiling | Plaster | Tan | None | 0 | 19.6 | Positive |
| 1 | 2 | 205 | IMC 205 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 205 | IMC 205 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 205 | IMC 205 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 205 | IMC 205 | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 205 | IMC 205 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 205 | IMC 205 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 205 | IMC 205 | Radiator | Metal | Gray | Flaking | 5 | 2.9 | Positive |
| 1 | 2 | 205 | IMC 205 | Radiator | Metal | Gray | Flaking | 2 | 2.5 | Positive |
| 1 | 2 | 205 | IMC 205 | Radiator | Metal | Gray | Flaking | 4 | 0.3 | Negative |
| 1 | 2 | 205 | IMC 205 | Crown Molding | Wood | Brown | None | 0 | 3.7 | Positive |
| 1 | 2 | 205 | IMC 205 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 205A | IMC 205 Office | W1 | Plaster | White | Cracking | 10 | 20.7 | Positive |
| 1 | 2 | 205A | IMC 205 Office | W2 | Plaster | White | Cracking | 20 | 25.4 | Positive |
| 1 | 2 | 205A | IMC 205 Office | W3 | Plaster | White | None | 0 | 22.9 | Positive |
| 1 | 2 | 205A | IMC 205 Office | W4 | Plaster | White | Cracking | 1 | 18.9 | Positive |
| 1 | 2 | 205A | IMC 205 Office | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 205A | IMC 205 Office | Ceiling | Plaster | Tan | Flaking | 15 | 23.1 | Positive |
| 1 | 2 | 205A | IMC 205 Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 205A | IMC 205 Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 205A | IMC 205 Office | Window Casing | Wood | Varnish | None | 0 | 0.8 | Positive |
| 1 | 2 | 205A | IMC 205 Office | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 205A | IMC 205 Office | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 205A | IMC 205 Office | Baseboard | Wood | Brown | None | 0 | 0.7 | Positive |
| 1 | 2 | 205A | IMC 205 Office | Radiator | Metal | Gray | Flaking | 5 | 3.4 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | W1 | Plaster | Gray | None | 0 | 16.7 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | W2 | Plaster | Gray | None | 0 | 21.3 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | W3 | Plaster | Gray | None | 0 | 19 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Ceiling | Plaster | White | None | 0 | 16.4 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Door Frame | Metal | Brown | None | 0 | 6.4 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Radiator | Metal | Gray | Flaking | 6 | 0.6 | Negative |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Stair Treads | Concrete | Gray | None | 0 | 0.5 | Negative |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Stair Riser | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Stair Stringer | Concrete | Gray | None | 0 | 0.9 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Floor | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Post | Metal | Brown | None | 0 | 10.9 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Spindle | Metal | Gray | None | 0 | 8.8 | Positive |
| 1 | 2 | S23 | Stairwell adjacent to Classroom 206 | Panel Box | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 2 | 206 | Classroom 206 | W1 | Plaster | Gray | Cracking | 5 | 16.6 | Positive |
| 1 | 2 | 206 | Classroom 206 | W2 | Plaster | Gray | Cracking | 80 | 15.7 | Positive |
| 1 | 2 | 206 | Classroom 206 | W3 | Plaster | Gray | None | 0 | 9.1 | Positive |
| 1 | 2 | 206 | Classroom 206 | W4 | Plaster | Gray | None | 0 | 22.5 | Positive |
| 1 | 2 | 206 | Classroom 206 | Ceiling | Plaster | Tan | Flaking | 300 | 18 | Positive |
| 1 | 2 | 206 | Classroom 206 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 206 | Classroom 206 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 206 | Classroom 206 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 206 | Classroom 206 | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 206 | Classroom 206 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 206 | Classroom 206 | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 206 | Classroom 206 | Radiator | Metal | Gray | None | 0 | 0.3 | Negative |
| 1 | 2 | 206 | Classroom 206 | Radiator | Metal | Gray | Flaking | 6 | 2.5 | Positive |
| 1 | 2 | 206 | Classroom 206 | Baseboard | Wood | Brown | Cracking | 6 | 0 | Negative |
| 1 | 2 | 207 | Classroom 207 | W1 | Plaster | Gray | None | 0 | 22.6 | Positive |
| 1 | 2 | 207 | Classroom 207 | W2 | Plaster | Gray | None | 0 | 12.1 | Positive |
| 1 | 2 | 207 | Classroom 207 | W3 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 2 | 207 | Classroom 207 | W4 | Plaster | Gray | None | 0 | 14.3 | Positive |
| 1 | 2 | 207 | Classroom 207 | Ceiling | Plaster | Tan | Flaking | 500 | 20.8 | Positive |
| 1 | 2 | 207 | Classroom 207 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 207 | Classroom 207 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 207 | Classroom 207 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 207 | Classroom 207 | Window Casing | Wood | Varnish | None | 0 | 0.6 | Negative |
| 1 | 2 | 207 | Classroom 207 | Window Sill | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 207 | Classroom 207 | Window Apron | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 207 | Classroom 207 | Radiator | Metal | Black | None | 0 | 0 | Negative |
| 1 | 2 | 207 | Classroom 207 | Radiator | Metal | Black | Flaking | 3 | 1.5 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 207 | Classroom 207 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 208 | Classroom 208 | W1 | Plaster | Gray | None | 0 | 24.5 | Positive |
| 1 | 2 | 208 | Classroom 208 | W2 | Plaster | Gray | None | 0 | 10.7 | Positive |
| 1 | 2 | 208 | Classroom 208 | W3 | Plaster | Gray | None | 0 | 0.3 | Negative |
| 1 | 2 | 208 | Classroom 208 | W4 | Plaster | Gray | None | 0 | 13.4 | Positive |
| 1 | 2 | 208 | Classroom 208 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 208 | Classroom 208 | Ceiling | Plaster | Tan | Cracking | 100 | 25.1 | Positive |
| 1 | 2 | 208 | Classroom 208 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 208 | Classroom 208 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 208 | Classroom 208 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 208 | Classroom 208 | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 208 | Classroom 208 | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 208 | Classroom 208 | Radiator | Metal | Gray | Flaking | 6 | 3 | Positive |
| 1 | 2 | 208 | Classroom 208 | Radiator | Metal | Gray | Flaking | 5 | 3.2 | Positive |
| 1 | 2 | 208 | Classroom 208 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | W1 | Brick | White | None | 0 | 7.8 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | W2 | Brick | White | None | 0 | 9.6 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | W3 | Brick | White | None | 0 | 11.1 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | W4 | Brick | White | None | 0 | 7.1 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Ceiling | Concrete | White | None | 0 | 13.9 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Floor | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Door Frame | Metal | Brown | None | 0 | 0.4 | Negative |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Security Gate | Metal | Brown | Flaking | 100 | 32 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Drain Pipe | Metal | Brown | Flaking | 24 | 26.7 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Handrail | Metal | Brown | Chipping | 8 | 4.5 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Stair Riser | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Stair Tread | Concrete | Gray | None | 0 | 0.7 | Positive |
| 1 | 2 | S25 | Fire Tower adjacent to Classroom 208 | Stair Stringer | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 2 | 209A | Nurse's Main Office | W1 | Plaster | White | None | 0 | 19.5 | Positive |
| 1 | 2 | 209A | Nurse's Main Office | W2 | Plaster | White | None | 0 | 18.9 | Positive |
| 1 | 2 | 209A | Nurse's Main Office | W3 | Plaster | White | Cracking | 10 | 18.7 | Positive |
| 1 | 2 | 209A | Nurse's Main Office | W4 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Ceiling | Plaster | Tan | Cracking | 5 | 19.7 | Positive |
| 1 | 2 | 209A | Nurse's Main Office | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 209A | Nurse's Main Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 209A | Nurse's Main Office | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Radiator | Metal | Gray | Flaking | 5 | 0 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Crown Molding | Wood | Brown | None | 0 | 0.5 | Negative |
| 1 | 2 | 209A | Nurse's Main Office | Drain Pipe | Metal | Brown | None | 0 | 0.5 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | W1 | Plaster | White | Cracking | 20 | 0 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | W2 | Plaster | White | Cracking | 5 | 22.4 | Positive |
| 1 | 2 | 209 | Nurse's Student Patient Room | W3 | Plaster | White | Cracking | 10 | 0.4 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | W4 | Plaster | White | Cracking | 15 | 20 | Positive |
| 1 | 2 | 209 | Nurse's Student Patient Room | Ceiling | Plaster | White | Flaking | 100 | 0.6 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 209 | Nurse's Student Patient Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Baseboard | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Radiator | Metal | Gray | Flaking | 10 | 0 | Negative |
| 1 | 2 | 209 | Nurse's Student Patient Room | Drain Pipe | Metal | White | Flaking | 5 | 25.3 | Positive |
| 1 | 2 | 209B | Nurse's Office Restroom | W1 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | W2 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | W3 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | W4 | Plaster | White | Flaking | 2 | 0 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | Floor | Concrete | Gray | Flaking | 4 | 0.2 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | Ceiling | Plaster | White | None | 0 | No Access | N/A |
| 1 | 2 | 209B | Nurse's Office Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | Window Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 209B | Nurse's Office Restroom | Window Sill | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | W1 | Plaster | White | Flaking | 5 | 25.9 | Positive |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | W2 | Plaster | White | Flaking | 2 | 20.1 | Positive |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | W3 | Plaster | White | None | 0 | 0.1 | Negative |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | W4 | Plaster | White | None | 0 | 20.3 | Positive |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | Ceiling | Plaster | Tan | Flaking | 40 | 20.3 | Positive |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | Baseboard | Wood | Brown | None | 0 | 0 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 2 | 210C | Vestibule outside Nurse's Office and Staff Lounge | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | W1 | Plaster | White | Flaking | 5 | 19.6 | Positive |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | W2 | Plaster | White | Flaking | 5 | 4.9 | Positive |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | W3 | Plaster | White | None | 0 | 23.2 | Positive |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | W4 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Ceiling | Plaster | Tan | Flaking | 100 | 0.3 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Window Sill | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Baseboard | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Crown Molding | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Radiator | Metal | Gray | Flaking | 10 | 0.9 | Positive |
| 1 | 2 | 210 | Staff Lounge adjacent to Nurse's Office | Drain Pipe | Metal | White | Flaking | 3 | 0.8 | Positive |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | W1 | Plaster | White | Flaking | 5 | 0.5 | Negative |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | W2 | Plaster | White | Flaking | 20 | 6.1 | Positive |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | W3 | Plaster | White | Flaking | 4 | 0 | Negative |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | W4 | Plaster | White | None | 0 | 12.4 | Positive |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Ceiling | Plaster | White | No Access | N/A | No Access | N/A |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Radiator | Metal | Gray | Flaking | 10 | 11.1 | Positive |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Grate | Metal | Black | None | 0 | 0 | Negative |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 210A | Staff Lounge adjacent to Nurse's Office Restroom | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | W1 | Plaster | White | None | 0 | 4.6 | Positive |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | W2 | Plaster | White | Flaking | 2 | 5.8 | Positive |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | W3 | Plaster | White | Flaking | 3 | 4.4 | Positive |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | W4 | Plaster | White | No Access | No Access | No Access | No Access |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | Baseboard | Wood | White | None | 0 | 0 | Negative |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | Ceiling | Plaster | White | No Access | N/A | No Access | N/A |
| 1 | 2 | 210B | Staff Lounge adjacent to Nurse's Office Closet | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | W1 | Plaster | White | None | 0 | 12.7 | Positive |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | W2 | Plaster | White | None | 0 | 10.1 | Positive |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | W3 | Plaster | White | None | 0 | 13.3 | Positive |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | W4 | Plaster | White | Flaking | 10 | 15.9 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Ceiling | Concrete | White | Flaking | 10 | 18.8 | Positive |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Floor | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Door Frame | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Window Casing | Wood | Brown | None | 0 | 0.9 | Positive |
| 1 | 2 | 211 | Girl's Restroom near Nurse's Office | Radiator | Metal | Gray | Flaking | 5 | 0 | Negative |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | Door | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | W1 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | W2 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | W3 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 2 | 211B | Pipe Chase in Girl's Restroom near Nurse's Office | W4 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | W1 | Plaster | Tan | Cracking | 8 | 2.9 | Positive |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | W2 | Plaster | White | Cracking | 20 | 2.1 | Positive |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | W3 | Plaster | White | Cracking | 60 | 0 | Negative |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | W4 | Plaster | White | Cracking | 20 | 2 | Positive |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | Ceiling | Plaster | White | Cracking | 20 | No Access | Assumed |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | Drain Pipe | Metal | White | Flaking | 12 | 0.6 | Negative |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | 211A | Custodial Closet Next to Second Floor Girl's Restroom | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | W1 | Plaster | Gray | None | 0 | 24 | Positive |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | W2 | Plaster | Gray | None | 0 | 21.6 | Positive |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | W3 | Plaster | Gray | None | 0 | 24.7 | Positive |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | W4 | Plaster | Gray | None | 0 | 22.1 | Positive |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | Floor | Concrete | Gray | None | 0 | 2 | Positive |
| 1 | 2 | H2 | Hallway outside Second Floor Girl's Restroom | Ceiling | Plaster | Tan | None | 0 | 20.6 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | W1 | Plaster | Gray | None | 0 | 22.6 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | W2 | Plaster | Gray | None | 0 | 19.5 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | W3 | Plaster | Gray | None | 0 | 22.8 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | W4 | Plaster | Gray | None | 0 | 18.9 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Ceiling | Plaster | Tan | Cracking | 100 | 26.6 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Floor | Concrete | Gray | None | 0 | 2.8 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Radiator | Metal | Gray | None | 0 | 0.7 | Positive |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Radiator | Metal | Gray | None | 0 | 0.2 | Negative |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 2 | H2C | Hallway from IMC 205 to Nurse's Office | Lockers | Metal | Red | None | 0 | 0 | Negative |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | Door | Wood | Varnish | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2CPCS | Pipe/Cable Shaft in Hallway next to Classroom 206 | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | W1 | Plaster | White | None | 0 | 20.3 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | W2 | Plaster | White | None | 0 | 19.4 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | W3 | Plaster | White | None | 0 | 23.5 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | W4 | Plaster | White | None | 0 | 27 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Ceiling | Plaster | White | None | 0 | 15.7 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Spindle | Metal | Blue | None | 0 | 13.7 | Positive |
| 1 | 2 | H2B | Hallway outside Auditorium Balcony | Post | Metal | Blue | None | 0 | 11.1 | Positive |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Main Office | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Main Office | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | Door | Wood | Varnish | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | | |
|---------|-------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|--|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) | |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative | |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2BPCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by IMC | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | S22 | Main Entrance Stairwell | W1 | Plaster | White | None | 0 | 24.4 | Positive | |
| 1 | 2 | S22 | Main Entrance Stairwell | W2 | Plaster | White | None | 0 | 20.1 | Positive | |
| 1 | 2 | S22 | Main Entrance Stairwell | W3 | Plaster | White | None | 0 | 21.5 | Positive | |
| 1 | 2 | S22 | Main Entrance Stairwell | Window Casing | Concrete | Black | None | 0 | 0.1 | Negative | |
| 1 | 2 | S22 | Main Entrance Stairwell | Newel Post | Metal | Blue | None | 0 | 12.8 | Positive | |
| 1 | 2 | S22 | Main Entrance Stairwell | Spindle | Metal | Blue | None | 0 | 18.8 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | W1 | Plaster | Gray | None | 0 | 24.5 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | W2 | Plaster | Gray | None | 0 | 0.2 | Negative | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | W3 | Plaster | Gray | None | 0 | 16.5 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | W4 | Plaster | Gray | None | 0 | 18.8 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Ceiling | Plaster | Tan | None | 0 | 18.3 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Floor | Concrete | Gray | Cracking | 10 | 1.6 | Positive | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Radiator | Metal | Gray | Flaking | 3 | 0.3 | Negative | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Radiator | Metal | Gray | Flaking | 2 | 0.3 | Negative | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Radiator | Metal | Gray | Flaking | 2 | 0.3 | Negative | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Lockers | Metal | Red | None | 0 | 0.1 | Negative | |
| 1 | 2 | H2A | Hallway from Office Suite 201 to Main Office | Electrical Panel | Metal | Brown | None | 0 | 0.1 | Negative | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | Door | Wood | Varnish | None | 0 | 0.1 | Negative | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | Door Frame | Wood | Varnish | None | 0 | 0 | Negative | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2APCS | Pipe/Cable Shaft in Hallway next to Classroom 202 | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | W1 | Plaster | Gray | None | 0 | 0.2 | Negative | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | W2 | Plaster | Gray | None | 0 | 15.4 | Positive | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | W3 | Plaster | Gray | None | 0 | 20.3 | Positive | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | W4 | Plaster | Gray | None | 0 | 20.5 | Positive | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | Floor | Concrete | Gray | None | 0 | 0.1 | Negative | |
| 1 | 2 | H2D | Hallway outside Second Floor Boy's Restroom | Ceiling | Plaster | Tan | Cracking | 80 | 18.8 | Positive | |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | W1 | Plaster | White | Cracking | 20 | 6.8 | Positive | |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | W2 | Plaster | White | Cracking | 40 | 0.5 | Negative | |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | W3 | Plaster | White | Cracking | 40 | 0.3 | Negative | |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | W4 | Plaster | White | Cracking | 20 | 7 | Positive | |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | Ceiling | Plaster | White | Cracking | 12 | 6.4 | Positive |
| 1 | 1 | 108 | Auditorium Control Room adjacent to Stage | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | W1 | Plaster | White | Flaking | 120 | 6.3 | Positive |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | W2 | Plaster | White | Flaking | 50 | 8.3 | Positive |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | W3 | Plaster | White | Flaking | 80 | 6.5 | Positive |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | W4 | Plaster | White | Flaking | 100 | 0.2 | Negative |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | Ceiling | Plaster | White | Flaking | 30 | 6.5 | Positive |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 1 | 109 | Men's Restroom near Building Engineer's Office | Radiator | Metal | Gray | Flaking | 2 | 0 | Negative |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | W1 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | W2 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | W3 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 109A | Pipe Shaft near First Floor Men's Restroom | W4 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 100 | Building Engineer's Office | W1 | Plaster | White | Cracking | 10 | 8 | Positive |
| 1 | 1 | 100 | Building Engineer's Office | W2 | Plaster | White | None | 0 | 10.5 | Positive |
| 1 | 1 | 100 | Building Engineer's Office | W3 | Plaster | White | Cracking | 40 | 8.4 | Positive |
| 1 | 1 | 100 | Building Engineer's Office | W4 | Plaster | White | Cracking | 20 | 8.8 | Positive |
| 1 | 1 | 100 | Building Engineer's Office | Ceiling | Plaster | White | Alligatoring | 70 | 11.1 | Positive |
| 1 | 1 | 100 | Building Engineer's Office | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 100 | Building Engineer's Office | Radiator | Metal | Gray | Flaking | 10 | 0.4 | Negative |
| 1 | 1 | 100 | Building Engineer's Office | Radiator | Metal | Gray | Flaking | 10 | 0.7 | Positive |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | W1 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | W2 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | W3 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | 100A | Pipe Chase outside Building Engineer's Office | W4 | No Access | No Access | No Access | N/A | N/A | N/A |
| 1 | 1 | H11C | Hallway to Best Door | W1 | Plaster | Gray | None | 0 | 17.3 | Positive |
| 1 | 1 | H11C | Hallway to Best Door | W2 | Plaster | Gray | None | 0 | 17.8 | Positive |
| 1 | 1 | H11C | Hallway to Best Door | W3 | Plaster | Gray | None | 0 | 19.5 | Positive |
| 1 | 1 | H11C | Hallway to Best Door | Ceiling | Plaster | Gray | None | 0 | 15.3 | Positive |
| 1 | 1 | H11C | Hallway to Best Door | Door | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | H11C | Hallway to Best Door | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | H11C | Hallway to Best Door | Floor | Concrete | Gray | None | 0 | 1.1 | Positive |
| 1 | 1 | H11C | Hallway to Best Door | Drain Pipe | Metal | White | None | 0 | 0.1 | Negative |
| 1 | 1 | H11D | Best Door Vestibule | W1 | Brick | White | None | 0 | 5.1 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | H11D | Best Door Vestibule | W2 | Brick | White | None | 0 | 3.9 | Positive |
| 1 | 1 | H11D | Best Door Vestibule | W3 | Brick | White | None | 0 | 6.1 | Positive |
| 1 | 1 | H11D | Best Door Vestibule | W4 | Brick | White | Cracking | 5 | 5.1 | Positive |
| 1 | 1 | H11D | Best Door Vestibule | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 1 | H11D | Best Door Vestibule | Ceiling | Concrete | White | Cracking | 8 | 0 | Negative |
| 1 | 1 | H11D | Best Door Vestibule | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | H11D | Best Door Vestibule | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 101 | Office 101 | W1 | Sheetrock | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101 | Office 101 | W2 | Plaster | White | Flaking | 5 | 0 | Negative |
| 1 | 1 | 101 | Office 101 | W3 | Plaster | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 101 | Office 101 | W4 | Plaster | White | None | 0 | 6.8 | Positive |
| 1 | 1 | 101 | Office 101 | Ceiling | Plaster | White | Flaking | 70 | 9.2 | Positive |
| 1 | 1 | 101 | Office 101 | Radiator | Metal | Gray | None | 0 | 1 | Positive |
| 1 | 1 | 101 | Office 101 | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 101 | Office 101 | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 101 | Office 101 | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 101 | Office 101 | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 101 | Office 101 | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 101 | Office 101 | Window Apron | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102 | Office Suite 102 Common Area | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 102 | Office Suite 102 Common Area | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 102 | Office Suite 102 Common Area | W1 | Plaster | White | None | 0 | 16.7 | Positive |
| 1 | 1 | 102 | Office Suite 102 Common Area | W2 | Plaster | White | None | 0 | 0.2 | Negative |
| 1 | 1 | 102 | Office Suite 102 Common Area | W3 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102 | Office Suite 102 Common Area | W4 | Plaster | White | None | 0 | 17.4 | Positive |
| 1 | 1 | 102 | Office Suite 102 Common Area | Baseboard | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 102 | Office Suite 102 Common Area | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102 | Office Suite 102 Common Area | Ceiling | Plaster | Tan | None | 0 | 15.8 | Positive |
| 1 | 1 | 102H | Office Suite 102 Common Area Closet | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102H | Office Suite 102 Common Area Closet | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102H | Office Suite 102 Common Area Closet | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102H | Office Suite 102 Common Area Closet | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102H | Office Suite 102 Common Area Closet | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102G | Office 102B (Left Office) | Ceiling | Plaster | Tan | None | 0 | 15.1 | Positive |
| 1 | 1 | 102G | Office 102B (Left Office) | Floor | Carpet | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102G | Office 102B (Left Office) | W1 | Plaster | White | None | 0 | 16.2 | Positive |
| 1 | 1 | 102G | Office 102B (Left Office) | W2 | Plaster | White | None | 0 | 0 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 1 | 102G | Office 102B (Left Office) | W3 | Plaster | White | None | 0 | 17.3 | Positive |
| 1 | 1 | 102G | Office 102B (Left Office) | W4 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Window Casing | Wood | Brown | None | 0 | 0.5 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Window Apron | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Radiator | Metal | Gray | None | 0 | 2.8 | Positive |
| 1 | 1 | 102G | Office 102B (Left Office) | Baseboard | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 102G | Office 102B (Left Office) | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Ceiling | Plaster | Tan | Flaking | 4 | 11.7 | Positive |
| 1 | 1 | 102F | Office 102C (Center Office) | Floor | Carpet | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102F | Office 102C (Center Office) | W1 | Plaster | White | None | 0 | 17.1 | Positive |
| 1 | 1 | 102F | Office 102C (Center Office) | W2 | Plaster | Gray | None | 0 | 13.2 | Positive |
| 1 | 1 | 102F | Office 102C (Center Office) | W3 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102F | Office 102C (Center Office) | W4 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102F | Office 102C (Center Office) | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Window Casing | Wood | Brown | None | 0 | 0.4 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Window Sill | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Window Apron | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 102F | Office 102C (Center Office) | Radiator | Metal | Gray | None | 0 | 0.4 | Negative |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Ceiling | Plaster | Tan | None | 0 | 13.7 | Positive |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Floor | Carpet | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | W1 | Plaster | Gray | None | 0 | 17.7 | Positive |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | W2 | Plaster | Gray | None | 0 | 14.5 | Positive |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | W3 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | W4 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Door | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Radiator | Metal | Gray | Flaking | 5 | 1.9 | Positive |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 102E | Office 102D (adjacent to Computer Classroom) | Window Apron | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | W1 | Plaster | White | Flaking | 40 | 15.2 | Positive |
| 1 | 1 | 101A | Office Suite 102 Computer Room | W2 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101A | Office Suite 102 Computer Room | W3 | Plaster | White | None | 0 | 22.1 | Positive |
| 1 | 1 | 101A | Office Suite 102 Computer Room | W4 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Ceiling | Plaster | Tan | Flaking | 20 | 19.8 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Window Casing | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Window Sill | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Window Apron | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Radiator | Metal | Gray | Flaking | 10 | 1.5 | Positive |
| 1 | 1 | 101A | Office Suite 102 Computer Room | Radiator | Metal | Gray | Flaking | 10 | 0.5 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | W2 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | W3 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | W4 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102D | Office Suite 102 Computer Room Restroom | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 101B | Office Suite 102 Computer Room Closet with Stove | W1 | Sheetrock | Tan | None | 0 | 0 | Negative |
| 1 | 1 | 101B | Office Suite 102 Computer Room Closet with Stove | W2 | Plaster | Tan | None | 0 | 18.9 | Positive |
| 1 | 1 | 101B | Office Suite 102 Computer Room Closet with Stove | W3 | Sheetrock | Tan | None | 0 | 0 | Negative |
| 1 | 1 | 101B | Office Suite 102 Computer Room Closet with Stove | W4 | Sheetrock | Tan | None | 0 | 0 | Negative |
| 1 | 1 | 101B | Office Suite 102 Computer Room Closet with Stove | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | W1 | Textured Wallpapered Sheetrock | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | W2 | Plaster | Tan | None | 0 | 0.1 | Negative |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | W3 | Textured Wallpapered Sheetrock | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | W4 | Textured Wallpapered Sheetrock | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 101C | Office Suite 102 Computer Room Kitchen | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | W1 | Plaster | Gray | None | 0 | 9.4 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | W2 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | W3 | Plaster | Gray | None | 0 | 8.5 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | W4 | Plaster | Gray | None | 0 | 10.4 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Ceiling | Plaster | Gray | None | 0 | 7.3 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Floor | Concrete | Gray | None | 0 | 1.3 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Door Frame | Metal | Brown | None | 0 | 2.2 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Entry Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Entry Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Stair Tread | Concrete | Gray | Chipping | 4 | 0.3 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Stair Riser | Concrete | Gray | Chipping | 4 | 0.6 | Negative |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Stair Stringer | Metal | Gray | Chipping | 4 | 1.1 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Stair Spindle | Metal | Gray | Chipping | 4 | 7.2 | Positive |
| 1 | 1 | S14 | Stairwell adjacent to "SYOP" Classroom | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | S14A | Stairwell adjacent to "SYOP" Classroom Closet | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102A | SYOP Classroom | W1 | CMU | Gray | None | 0 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | W2 | Plaster | Gray | None | 0 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | W3 | Plaster | Gray | Efflorescence | 10 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | W4 | Plaster | Gray | None | 0 | 3.5 | Positive |
| 1 | 1 | 102A | SYOP Classroom | Ceiling | Plaster | White | Flaking | 40 | 10.7 | Positive |
| 1 | 1 | 102A | SYOP Classroom | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102A | SYOP Classroom | Radiator | Metal | Gray | Chipping | 2 | 3.1 | Positive |
| 1 | 1 | 102A | SYOP Classroom | Radiator | Metal | Gray | Chipping | 2 | 3.9 | Positive |
| 1 | 1 | 102A | SYOP Classroom | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | Window Casing | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102A | SYOP Classroom | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | Door | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | 102I | SYOP Classroom Pipe Shaft | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | W1 | Plaster | Gray | None | 0 | 19.4 | Positive |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | W2 | Plaster | Gray | None | 0 | 21.8 | Positive |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | W3 | Plaster | Gray | None | 0 | 20.1 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | W4 | Plaster | Gray | None | 0 | 21.8 | Positive |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | Ceiling | Plaster | Tan | Moisture Damage | 60 | 5.5 | Positive |
| 1 | 1 | H11A | Hallway outside First Floor Men's Restroom | Floor | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | W1 | Plaster | Gray | Cracking | 10 | 18.7 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | W2 | Plaster | Gray | Cracking | 10 | 27.5 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | W3 | Plaster | Gray | Cracking | 10 | 19.9 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | W4 | Plaster | Gray | Cracking | 5 | 21.2 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Ceiling | Plaster | Tan | Cracking | 60 | 20.3 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Floor | Concrete | Gray | None | 0 | 2.4 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Locker | Metal | Tan | None | 0 | 0 | Negative |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Electrical Panel | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Radiator | Metal | Gray | Cracking | 5 | 0.7 | Positive |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Radiator | Metal | Gray | Cracking | 5 | 0.1 | Negative |
| 1 | 1 | H11 | Hallway from Building Engineer's Office to "SYOP" Classroom | Radiator | Metal | Gray | Cracking | 5 | 0.3 | Negative |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H11PCS | Pipe/Cable Shaft in Hallway next to Classroom 101 | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | W1 | Plaster | Gray | None | 0 | 20.8 | Positive |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | W2 | Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | W3 | Plaster | Gray | None | 0 | 13.9 | Positive |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | W4 | Plaster | Gray | None | 0 | 0 | Negative |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Ceiling | Plaster | Tan | None | 0 | 13 | Positive |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Floor | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Stair Tread | Concrete | Gray | None | 0 | 0.2 | Negative |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Stair Riser | Concrete | Gray | None | 0 | 1.4 | Positive |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Stair Stringer | Concrete | Gray | None | 0 | 1.5 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|---|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | H11B | Stairs to Auditorium Left Side | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | W1 | cmu | White | None | 0 | 22.1 | Positive |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | W2 | CMU | White | None | 0 | 24.1 | Positive |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | W3 | CMU | White | None | 0 | 22.3 | Positive |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | W4 | CMU | White | None | 0 | 21.1 | Positive |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13 | Hallway outside Rear Auditorium Entrance | Ceiling | Plaster | White | None | 0 | 18.9 | Positive |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS1 | Pipe/Cable Shaft in Hallway next to Stairwell by Classroom 102A | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | Door Frame | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS2 | Pipe/Cable Shaft in Hallway above Hydration Station near Classroom 102B | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 1 | H13PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Room 103 | W1 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Room 103 | W2 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Room 103 | W3 | Brick | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Room 103 | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | H13PCS3 | Pipe/Cable Shaft in Hallway next to Stairwell by Room 103 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|-----------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 107 | Auditorium | W1 | Plaster | White | Flaking | 40 | 20.2 | Positive |
| 1 | 1 | 107 | Auditorium | W1 | Wood | White | None | 0 | 13.2 | Positive |
| 1 | 1 | 107 | Auditorium | W2 | Plaster | White | Efflorescence | 200 | 25.3 | Positive |
| 1 | 1 | 107 | Auditorium | W2 | Wood | White | None | 0 | 13.6 | Positive |
| 1 | 1 | 107 | Auditorium | W3 | Plaster | White | Efflorescence | 100 | 22.7 | Positive |
| 1 | 1 | 107 | Auditorium | W3 | Wood | White | None | 0 | 12.6 | Positive |
| 1 | 1 | 107 | Auditorium | W4 | Plaster | White | Cracking | 20 | 24 | Positive |
| 1 | 1 | 107 | Auditorium | W4 | Wood | White | None | 0 | 12.7 | Positive |
| 1 | 1 | 107 | Auditorium | Door | Wood | White | None | 0 | 14.9 | Positive |
| 1 | 1 | 107 | Auditorium | Door Casing | Wood | White | None | 0 | 16.5 | Positive |
| 1 | 1 | 107 | Auditorium | Window Casing | Wood | White | None | 0 | 16.5 | Positive |
| 1 | 1 | 107 | Auditorium | Radiator Cover | Metal | White | None | 0 | 4.9 | Positive |
| 1 | 1 | 107 | Auditorium | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 107 | Auditorium | Baseboard | Wood | Brown | None | 0 | 22.4 | Positive |
| 1 | 1 | 107 | Auditorium | Ceiling | Plaster | White | Flaking | 300 | 11.9 | Positive |
| 1 | 1 | 107 STAGE | Auditorium Stage | W1 | Plaster | Black | Flaking | 120 | 4.3 | Positive |
| 1 | 1 | 107 STAGE | Auditorium Stage | W2 | Plaster | White | Flaking | 300 | 0 | Negative |
| 1 | 1 | 107 STAGE | Auditorium Stage | W3 | Plaster | White | Flaking | 100 | 5.7 | Positive |
| 1 | 1 | 107 STAGE | Auditorium Stage | W4 | Plaster | White | Flaking | 220 | 0 | Negative |
| 1 | 1 | 107 STAGE | Auditorium Stage | Ceiling | Plaster | White | Flaking | 60 | No Access | Assumed |
| 1 | 1 | 107 STAGE | Auditorium Stage | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 107 STAGE | Auditorium Stage | Radiator | Metal | Gray | Flaking | 5 | 0.1 | Negative |
| 1 | 1 | H13A | Main Lobby | W1 | Plaster | White | None | 0 | 8.2 | Positive |
| 1 | 1 | H13A | Main Lobby | W2 | Plaster | White | Cracking | 10 | 10 | Positive |
| 1 | 1 | H13A | Main Lobby | W3 | Plaster | White | None | 0 | 8.3 | Positive |
| 1 | 1 | H13A | Main Lobby | W4 | Plaster | White | Cracking | 5 | 9.3 | Positive |
| 1 | 1 | H13A | Main Lobby | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13A | Main Lobby | Ceiling | Plaster | White | None | 0 | 9.6 | Positive |
| 1 | 1 | H13B | Main Entrance Vestibule | W1 | Ceramic Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13B | Main Entrance Vestibule | W2 | Ceramic Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13B | Main Entrance Vestibule | W3 | Ceramic Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13B | Main Entrance Vestibule | W4 | Ceramic Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13B | Main Entrance Vestibule | Floor | Ceramic | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H13B | Main Entrance Vestibule | Ceiling | Plaster | White | Flaking | 5 | 6.5 | Positive |
| 1 | 1 | H13B | Main Entrance Vestibule | Door | Metal | Brown | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | H13B | Main Entrance Vestibule | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | W1 | Plaster | White | Efflorescence | 60 | 5.1 | Positive |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | W2 | CMU | White | None | 0 | 0.2 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | W3 | Plaster | White | Chipping | 3 | 3.3 | Positive |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | W4 | Plaster | White | None | 0 | 0.3 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Ceiling | Plaster | White | None | 0 | 9.8 | Positive |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Door | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Baseboard | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Radiator | Metal | Brown | None | 0 | 3.1 | Positive |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Window Sill | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 102B | Classroom to Left of Main Entrance Vestibule | Window Apron | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | W1 | Plaster | White | Flaking | 60 | 16.1 | Positive |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | W2 | Plaster | White | Flaking | 20 | 19.6 | Positive |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | W3 | Plaster | White | Flaking | 80 | 0 | Negative |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | W4 | Plaster | White | Flaking | 10 | 16.4 | Positive |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Ceiling | Plaster | White | Flaking | 5 | 16.2 | Positive |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Door Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Radiator Panel | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Stair Tread | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Stair Riser | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | S06 | Main Entrance Vestibule Stairs to Men's Restroom | Stair Stringer | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | W1 | Plaster | White | Flaking | 40 | 18.8 | Positive |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | W2 | Plaster | White | Flaking | 80 | 17.3 | Positive |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | W3 | Plaster | White | Flaking | 20 | 0 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | W4 | Plaster | White | Flaking | 100 | 2 | Positive |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Ceiling | Plaster | White | Flaking | 50 | 19.1 | Positive |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Floor | Concrete | Gray | Flaking | 40 | 0.2 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Drain Pipe | Metal | White | Chipping | 4 | 24.3 | Positive |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Radiator | Metal | White | Chipping | 3 | No Access | Assumed |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Partition Wall | Marble | White | Flaking | 5 | 0.2 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Partition Door | Wood | White | None | 0 | 0.2 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Partition Wall | Wood | White | None | 0 | 0.2 | Negative |
| 1 | B | 9 | Men's Restroom below Main Entrance Vestibule | Partition Door | Wood | White | Flaking | 5 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | W1 | Plaster | White | Cracking | 40 | 17.5 | Positive |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | W2 | Plaster | White | Flaking | 15 | 19.1 | Positive |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | W3 | Plaster | White | Flaking | 10 | 19.2 | Positive |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Ceiling | Plaster | White | Alligating | 10 | 21.8 | Positive |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Door Casing | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Radiator Panel | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Stair Tread | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Stair Riser | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Stair Stringer | Marble | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | S05 | Main Entrance Vestibule Stairs to Women's Restroom | Drain Pipe | Metal | White | Flaking | 3 | 0.1 | Negative |
| 1 | B | 8-1 | Women's Restroom below Main Entrance Vestibule | W1 | Plaster | White | Flaking | 100 | 20.4 | Positive |
| 1 | B | 8-1 | Women's Restroom below Main Entrance Vestibule | W2 | Plaster | White | Cracking | 200 | 20.4 | Positive |
| 1 | B | 45139 | Women's Restroom below Main Entrance Vestibule | W3 | Plaster | White | Cracking | 100 | 0 | Negative |
| 1 | B | 45139 | Women's Restroom below Main Entrance Vestibule | W4 | Plaster | White | Cracking | 200 | 3.8 | Positive |
| 1 | B | 45139 | Women's Restroom below Main Entrance Vestibule | Ceiling | Plaster | White | Flaking | 200 | 0.1 | Negative |
| 1 | B | 45139 | Women's Restroom below Main Entrance Vestibule | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 45139 | Women's Restroom below Main Entrance Vestibule | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | B | 8-1 | Women's Restroom below Main Entrance Vestibule | Drain Pipe | Metal | White | Flaking | 12 | 25.3 | Positive |
| 1 | B | 8-1 | Women's Restroom below Main Entrance Vestibule | Radiator | Metal | White | Cracking | 10 | No Access | Assumed |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | W1 | Plaster | White | Flaking | 20 | 21 | Positive |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | W2 | Plaster | White | Flaking | 10 | 15.6 | Positive |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | W3 | Plaster | White | Flaking | 10 | 1.2 | Positive |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | W4 | Plaster | White | None | 0 | 1.6 | Positive |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Ceiling | Plaster | Tan | Chipping | 30 | 18.3 | Positive |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Floor | Concrete | Gray | None | 0 | 0 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Floor | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Baseboard | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Window Casing | Wood | Brown | None | 0 | 0.4 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Window Sill | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Window Apron | Wood | Brown | None | 0 | 0.3 | Negative |
| 1 | 1 | 103A | Women's Restroom Next to Main Lobby | Radiator | Metal | Gray | None | 0 | 6.2 | Positive |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|--------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | W1 | Plaster | Tan | None | 0 | 1.7 | Positive |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | W2 | Plaster | Tan | None | 0 | 1.5 | Positive |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | W3 | Plaster | Tan | None | 0 | 1.5 | Positive |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | W4 | Plaster | Tan | None | 0 | 1.6 | Positive |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | Shelf | Wood | Tan | None | 0 | 0.1 | Negative |
| 1 | 1 | 103E | Women's Restroom Next to Main Lobby Closet 1 | Ceiling | Plaster | Tan | None | 0 | 2 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | Door | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | Door Frame | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | W1 | Plaster | Tan | None | 0 | 1.8 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | W2 | Plaster | Tan | None | 0 | 2 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | W3 | Plaster | Tan | None | 0 | 2.2 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | W4 | Plaster | Tan | None | 0 | 2.4 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | Ceiling | Plaster | Tan | None | 0 | 2.1 | Positive |
| 1 | 1 | 103F | Women's Restroom Next to Main Lobby Closet 2 | Shelf | Wood | Tan | None | 0 | 0.1 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | W1 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103 | Office Suite 103 Reception Area | W2 | Plaster | White | None | 0 | 20.7 | Positive |
| 1 | 1 | 103 | Office Suite 103 Reception Area | W3 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103 | Office Suite 103 Reception Area | W4 | Plaster | White | None | 0 | 16.6 | Positive |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Ceiling | Plaster | Tan | Cracking | 60 | 25 | Positive |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Radiator | Metal | Gray | None | 0 | 0.2 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Window Sill | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 1 | 103 | Office Suite 103 Reception Area | Floor Trench Cover | Metal | Black | None | 0 | 0.4 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | W1 | Plaster | Tan | None | 0 | 0.3 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | W2 | Plaster | Tan | None | 0 | 9.8 | Positive |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | W3 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | W4 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Ceiling | Plaster | Tan | Efflorescence | 25 | 25.1 | Positive |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Window Casing | Wood | Varnish | None | 0 | 0.5 | Negative |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 103B | Office Suite 103 Office adjacent to Kitchen | Radiator | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 1 | 103C | Office Suite 103 Kitchen | W1 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103C | Office Suite 103 Kitchen | W2 | Plaster | White | Flaking | 10 | 23 | Positive |
| 1 | 1 | 103C | Office Suite 103 Kitchen | W3 | Plaster | White | Flaking | 50 | 20.5 | Positive |
| 1 | 1 | 103C | Office Suite 103 Kitchen | W4 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103C | Office Suite 103 Kitchen | Ceiling | Plaster | Tan | Flaking | 40 | 27.1 | Positive |
| 1 | 1 | 103C | Office Suite 103 Kitchen | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103C | Office Suite 103 Kitchen | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 103C | Office Suite 103 Kitchen | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Ceiling | Plaster | Tan | Cracking | 5 | 24.3 | Positive |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | W1 | Plaster | White | None | 0 | 20.4 | Positive |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | W2 | Plaster | White | None | 0 | 28 | Positive |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | W3 | Plaster | White | None | 0 | 27.2 | Positive |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | W4 | Fabric | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Window Casing | Wood | Varnish | None | 0 | 0.4 | Negative |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Window Sill | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 103G | Office Suite 103 Office adjacent to Restroom | Radiator | Metal | Gray | None | 0 | 0.3 | Negative |
| 1 | 1 | 103D | Office Suite 103 Restroom | W1 | Plaster | White | None | 0 | 14 | Positive |
| 1 | 1 | 103D | Office Suite 103 Restroom | W2 | Plaster | White | None | 0 | 11.2 | Positive |
| 1 | 1 | 103D | Office Suite 103 Restroom | W3 | Plaster | White | None | 0 | 9.7 | Positive |
| 1 | 1 | 103D | Office Suite 103 Restroom | W4 | Plaster | White | None | 0 | 13.8 | Positive |
| 1 | 1 | 103D | Office Suite 103 Restroom | Ceiling | Plaster | Tan | No Access | N/A | No Access | Negative |
| 1 | 1 | 103D | Office Suite 103 Restroom | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 103D | Office Suite 103 Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 103D | Office Suite 103 Restroom | Door Frame | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | W1 | Plaster | Gray | Cracking | 20 | 0.3 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | W2 | Plaster | Gray | Cracking | 5 | 0.1 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | W3 | Plaster | Gray | Cracking | 40 | 3.8 | Positive |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | W4 | Plaster | Gray | Cracking | 8 | 6.8 | Positive |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Ceiling | Plaster | Gray | None | 0 | 7.6 | Positive |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Floor | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Radiator | Metal | Gray | Chipping | 5 | 0.3 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Stair Tread | Concrete | Gray | Chipping | 4 | 0 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Stair Riser | Concrete | Gray | Chipping | 2 | 1.2 | Positive |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Stair Stringer | Metal | Gray | Chipping | 4 | 1.7 | Positive |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | | |
|---------|-------|---------|--|------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|--|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | | |
| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | S13A | Closet in Stairwell adjacent to Office Suite 103 | No Access | No Access | No Access | No Access | No Access | No Access | No Access | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | W1 | Sheetrock | White | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | W2 | Sheetrock | White | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | W3 | Sheetrock | White | None | 0 | 5.5 | Positive | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | W4 | Sheetrock | White | None | 0 | 23.3 | Positive | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | Door | Wood | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | Floor | 12 x 12 Floor Tile | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104 | Office Suite 104 Hallway and Common Area | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | W1 | Sheetrock | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | W2 | Tile | White | None | 0 | 24.8 | Positive | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | W3 | Plaster | White | None | 0 | 0.7 | Positive | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | W4 | Sheetrock | White | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | Door | Wood | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | Floor | 12 x 12 Floor Tile | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104A | Office Suite 104 Southwest Office | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | W1 | Sheetrock | White | None | 0 | 0 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | W2 | Plaster | White | None | 0 | 19.1 | Positive | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | W3 | Sheetrock | White | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | W4 | Sheetrock | White | None | 0 | 0.1 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | Door | Wood | Varnish | None | 0 | 0 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | Door Frame | Metal | Brown | None | 0 | 0 | Negative | |
| 1 | 1 | 104B | Office Suite 104 Southwest Area Facilities Management Office | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A | |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W1 | Tile | Tan | None | 0 | 36 | Positive | |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W1 | Plaster | Tan | None | 0 | 27.3 | Positive | |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W2 | Tile | Tan | None | 0 | 34 | Positive | |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W2 | Plaster | Tan | None | 0 | 21.4 | Positive | |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W3 | Sheetrock | Tan | None | 0 | 0.1 | Negative | |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W3 | Plaster | Tan | None | 0 | 17.2 | Positive |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W3 | Tile | Tan | None | 0 | 36 | Positive |
| 1 | 1 | 104C | Office Suite 104 Camera Room | W4 | Sheetrock | Tan | None | 0 | 0.1 | Negative |
| 1 | 1 | 104C | Office Suite 104 Camera Room | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 104C | Office Suite 104 Camera Room | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 104C | Office Suite 104 Camera Room | Window Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | Door Frame | Wood | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | W1 | Plaster | White | None | 0 | 3.4 | Positive |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | W2 | Plaster | White | None | 0 | 3.3 | Positive |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | W3 | Plaster | White | Efflorescence | 40 | 2.3 | Positive |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | W4 | Plaster | White | Efflorescence | 10 | 4.1 | Positive |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 105A | Office Suite 104 Camera Room Closet | Window Apron | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | W1 | Plaster | White | None | 0 | 15.3 | Positive |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | W2 | Plaster | White | None | 0 | 21.7 | Positive |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | W4 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | 104D | Office Suite 104 Office at end of Hallway | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | W1 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | W2 | Plaster | White | None | 0 | 11.4 | Positive |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | W3 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | W4 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 104E | Office Suite 104 Northeast Area Services Office in Center | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | W1 | Sheetrock | White | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | W2 | Plaster | White | None | 0 | 26 | Positive |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | W3 | Sheetrock | White | None | 0 | 0.2 | Negative |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | W4 | Sheetrock | White | None | 0 | 0.1 | Negative |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | 104F | Office Suite 104 Northwest Area Services Office on End | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 105 | Classroom 105 | W1 | Plaster | White | None | 0 | 0 | Negative |
| 1 | 1 | 105 | Classroom 105 | W2 | Plaster | White | None | 0 | 8.2 | Positive |
| 1 | 1 | 105 | Classroom 105 | W3 | Plaster | White | None | 0 | 8 | Positive |
| 1 | 1 | 105 | Classroom 105 | W4 | Plaster | White | None | 0 | 8.9 | Positive |
| 1 | 1 | 105 | Classroom 105 | W1 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 105 | Classroom 105 | W2 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 105 | Classroom 105 | Ceiling | Plaster | White | Cracking | 10 | 10.5 | Positive |
| 1 | 1 | 105 | Classroom 105 | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | W1 | Plaster | White | Cracking | 30 | 7.8 | Positive |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | W2 | Plaster | White | None | 0 | 9.9 | Positive |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | W3 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | W4 | Sheetrock | White | None | 0 | 0 | Negative |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | Ceiling | Plaster | White | Chipping | 15 | 10.2 | Positive |
| 1 | 1 | 105B | Classroom 105 Cleaning Supply Usage Restroom | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | W1 | Plaster | Gray | None | 0 | 17.7 | Positive |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | W2 | Plaster | Gray | None | 0 | 17.5 | Positive |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | W3 | Plaster | Gray | None | 0 | 16.3 | Positive |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | W4 | Plaster | Gray | None | 0 | 0.1 | Negative |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | Floor | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | Radiator | Metal | Gray | None | 0 | 0.3 | Negative |
| 1 | 1 | H12C | Hallway adjacent to Classroom 105 | Locker | Metal | Tan | None | 0 | 0 | Negative |
| 1 | 1 | H12C | Hallway adjacent to Classroom 106 | Electrical Panel | Metal | Brown | None | 0 | 5.7 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | W1 | Plaster | Gray | None | 0 | 20.5 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | W2 | Plaster | Gray | None | 0 | 19 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | W3 | Plaster | Gray | None | 0 | 20.6 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|---|----------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Ceiling | Plaster | Gray | None | 0 | 15.5 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Floor | Concrete | Gray | None | 0 | 1.1 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Handrail | Metal | Gray | Chipping | 6 | 1.5 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Stair Tread | Concrete | Gray | None | 0 | 1.8 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Stair Riser | Concrete | Gray | None | 0 | 1.6 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Stair Stringer | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | H12D | Vestibule adjacent to Classroom 105 | Door Frame | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | W1 | Brick | White | None | 0 | 8.4 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | W2 | Brick | White | Flaking | 10 | 8.3 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | W3 | Brick | White | None | 0 | 6 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | Floor | Concrete | Gray | None | 0 | 1 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | Handrail | Metal | Gray | Chipping | 10 | 1.7 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | Stair Tread | Concrete | Gray | None | 0 | 0.7 | Positive |
| 1 | 1 | S16 | Fire Tower adjacent to Building Engineer's Office | Stair Riser | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | W1 | Brick | White | None | 0 | 15.9 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | W2 | Brick | White | None | 0 | 17.2 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | W3 | Brick | White | None | 0 | 16.2 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | W4 | Brick | White | None | 0 | 15 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Ceiling | Concrete | White | Flaking | 30 | 13.7 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Door | Concrete | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Door Frame | Concrete | Brown | None | 0 | 0.1 | Negative |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Stair Tread | Concrete | Gray | None | 0 | 0.5 | Negative |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Stair Riser | Concrete | Gray | None | 0 | 1.8 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Stair Stringer | Concrete | Gray | None | 0 | 1.7 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Handrail | Metal | Gray | Flaking | 14 | 6.6 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Drain pipe | Metal | White | Flaking | 12 | 13.9 | Positive |
| 1 | 1 | S15 | Fire Tower adjacent to Classroom 105 | Drain pipe | Metal | Brown | Flaking | 12 | 5.5 | Positive |
| 1 | 1 | 106 | Facilities Training Center Room 106 | W1 | Plaster | White | Flaking | 10 | 0 | Negative |
| 1 | 1 | 106 | Facilities Training Center Room 106 | W2 | Plaster | White | Flaking | 40 | 0.1 | Negative |
| 1 | 1 | 106 | Facilities Training Center Room 106 | W3 | Plaster | White | Flaking | 20 | 0 | Negative |
| 1 | 1 | 106 | Facilities Training Center Room 106 | W4 | Plaster | White | Flaking | 30 | 0.1 | Negative |
| 1 | 1 | 106 | Facilities Training Center Room 106 | Ceiling | Plaster | White | Efflorescence | 70 | 0 | Negative |
| 1 | 1 | 106 | Facilities Training Center Room 106 | Floor | Wood | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | W1 | Plaster | Tan | None | 0 | 10.1 | Positive |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | W2 | Plaster | Tan | Efflorescence | 15 | 12.4 | Positive |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | W3 | Plaster | Tan | Efflorescence | 40 | 8.7 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|---------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | W4 | Plaster | Tan | Cracking | 8 | 13 | Positive |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Ceiling | Plaster | Tan | No Access | 80 | No Access | Assumed |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Floor | 12 x 12 Floor Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Window Sill | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Window Apron | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | 106B | Staff Restroom next to Office 106 | Radiator | Metal | Gray | Flaking | 5 | 2.4 | Positive |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | W1 | Plaster | Blue | Efflorescence | 100 | 0.1 | Negative |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | W2 | Plaster | Blue | Efflorescence | 100 | 0 | Negative |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | W3 | Plaster | Blue | Efflorescence | 100 | 14.4 | Positive |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | W4 | Plaster | Blue | Efflorescence | 100 | 3.5 | Positive |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Column | Plaster | Blue | Flaking | 30 | 11.3 | Positive |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Drain Pipe | Metal | Blue | Flaking | 10 | 0.7 | Positive |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Door | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Ceiling | Concrete | White | Flaking | 20 | Limited Access | Assumed |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Radiator | Metal | Gray | Cracking | 5 | 0.3 | Negative |
| 1 | 1 | 106A | Custodial Closet 106A Next to Restroom | Floor | Wood | Gray | Moisture Damage | 50 | 0.1 | Negative |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | W1 | Plaster | Gray | None | 0 | 15.1 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | W2 | Plaster | Gray | None | 0 | 15.7 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | W3 | Plaster | Gray | None | 0 | 24 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | W4 | Plaster | Gray | None | 0 | 16.4 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Floor | Concrete | Gray | None | 0 | 1.8 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Ceiling | Plaster | Tan | Efflorescence | 100 | 21.3 | Positive |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Radiator | Metal | Gray | Flaking | 4 | 0.1 | Negative |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Radiator | Metal | Gray | Flaking | 4 | 0 | Negative |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Radiator | Metal | Gray | Flaking | 2 | 0.2 | Negative |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | H12 | Hallway from Office Suite 103 to Classroom 105 | Locker | Metal | Tan | None | 0 | 0.2 | Negative |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | Door Frame | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | W1 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | W2 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | W3 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12PCS | Pipe/Cable Shaft in Hallway next to Office Suite 104 | W4 | Terracotta | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | W1 | Plaster | Gray | None | 0 | 0.5 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|----------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | W2 | Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | W3 | Plaster | Gray | None | 0 | 22.5 | Positive |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | W4 | Tile | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Ceiling | Plaster | Gray | None | 0 | 21.1 | Positive |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Floor | Concrete | Gray | None | 0 | 2.7 | Positive |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Stair Tread | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Stair Riser | Concrete | Gray | None | 0 | 2.1 | Positive |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Stair Stringer | Concrete | Gray | None | 0 | 2.1 | Positive |
| 1 | 1 | H12A | Stairs to Auditorium Right Side | Window Casing | Wood | Varnish | None | 0 | 0.3 | Negative |
| 1 | 1 | E1 | Passenger Elevator | W1 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | E1 | Passenger Elevator | W2 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | E1 | Passenger Elevator | W3 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | E1 | Passenger Elevator | W4 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | 1 | E1 | Passenger Elevator | Door | Metal | Tan | None | 0 | 0 | Negative |
| 1 | 1 | E1 | Passenger Elevator | Ceiling | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 4 | Older Lower Boiler Room | W1 | Concrete | White | Flaking | 200 | 0 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W1 | Concrete | Gray | Flaking | 200 | 0.4 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W2 | Brick | White | Flaking | 200 | 0.1 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W2 | Brick | Gray | Flaking | 200 | 22.3 | Positive |
| 1 | B | 4 | Older Lower Boiler Room | W3 | Concrete | White | Flaking | 200 | 0.1 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W3 | Concrete | Gray | Flaking | 200 | 0.1 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W4 | Concrete | White | Flaking | 200 | 0.2 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | W4 | Concrete | Gray | Flaking | 200 | 0.2 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | Ceiling | Concrete | Gray | No Access | 200 | No Access | Assumed |
| 1 | B | 4 | Older Lower Boiler Room | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 4 | Older Lower Boiler Room | Column | Concrete | White | Flaking | 200 | 0.2 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | Column | Concrete | Gray | Flaking | 200 | 0.1 | Negative |
| 1 | B | 4 | Older Lower Boiler Room | Drain Pipe | Metal | White | Flaking | 200 | 23.3 | Positive |
| 1 | B | 4 | Older Lower Boiler Room | Drain Pipe | Metal | Gray | Flaking | 200 | 15.7 | Positive |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W1 | Concrete | White | Flaking | 40 | 0.1 | Negative |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W1 | Concrete | Gray | Flaking | 40 | 0.3 | Negative |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W2 | Concrete | White | Flaking | 40 | 0.2 | Negative |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W2 | Concrete | Gray | Flaking | 40 | 0.4 | Negative |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W3 | Brick | White | Flaking | 40 | No Access | Assumed |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W3 | Brick | Gray | Flaking | 40 | No Access | Assumed |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W4 | Brick | White | Flaking | 40 | 0.7 | Positive |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | W4 | Brick | Gray | Flaking | 40 | 0.2 | Negative |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | Ceiling | Concrete | Unpainted | N/A | N/A | N/A | N/A |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | B | 004B | Small Sump Pump Room in Old Boiler Room Area | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | W1 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | W2 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | W3 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | W4 | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | Ceiling | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 2 | Large Storage Room in Old Boiler Room (Old Coal Room) | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | W1 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | W2 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | W3 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | W4 | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | Ceiling | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 3 | Small Storage Room next to Old Boiler Room (Old Ash Room) | Floor | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 6 | New Boiler Room | W1 | Brick | Gray | Flaking | 60 | 12.7 | Positive |
| 1 | B | 6 | New Boiler Room | W2 | Concrete | Gray | Flaking | 40 | 2.1 | Positive |
| 1 | B | 6 | New Boiler Room | W3 | Concrete | Gray | Flaking | 100 | 0.4 | Negative |
| 1 | B | 6 | New Boiler Room | W4 | Brick | Gray | Flaking | 40 | 8.9 | Positive |
| 1 | B | 6 | New Boiler Room | Ceiling | Concrete | Gray | Flaking | 200 | 0.2 | Negative |
| 1 | B | 6 | New Boiler Room | Floor | Concrete | Gray | None | 0 | 0.1 | Negative |
| 1 | B | 6 | New Boiler Room | Floor | Concrete | Black | None | 0 | 0.2 | Negative |
| 1 | B | 6 | New Boiler Room | Column | Concrete | Gray | Flaking | 60 | 9.4 | Positive |
| 1 | B | 6 | New Boiler Room | Window Casing | Wood | Gray | None | 0 | 9.7 | Positive |
| 1 | B | 7 | Electrical Gated Area | W1 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 7 | Electrical Gated Area | W2 | Concrete | Gray | Flaking | 60 | 3.7 | Positive |
| 1 | B | 7 | Electrical Gated Area | W3 | Concrete | Gray | Flaking | 40 | 0.2 | Negative |
| 1 | B | 7 | Electrical Gated Area | W4 | Metal | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 7 | Electrical Gated Area | Ceiling | Concrete | Gray | Flaking | 10 | No Access | Assumed |
| 1 | B | 7 | Electrical Gated Area | Floor | No Access | No Access | No Access | No Access | No Access | No Access |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|---------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W1 | Brick | White | Flaking | 100 | 0.6 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W1 | Brick | Gray | Flaking | 100 | 0.1 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W2 | Brick | White | Flaking | 100 | 0.1 | Negative |
| 1 | B | 45140 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W2 | Brick | Gray | Flaking | 100 | 0 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W3 | Concrete | White | Flaking | 100 | 1.9 | Positive |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W3 | Concrete | Gray | Flaking | 100 | 2 | Positive |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W4 | Brick | White | Flaking | 100 | 0.1 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | W4 | Brick | Gray | Flaking | 100 | 0.1 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Ceiling | Concrete | No Access | Flaking | 200 | No Access | Assumed |
| 1 | B | 45140 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Floor | Concrete | Gray | None | 0 | 0.3 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Column | Concrete | White | Flaking | 16 | 0.2 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Column | Concrete | Gray | Flaking | 16 | 0.3 | Negative |
| 1 | B | 45140 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Window Casing | Wood | Gray | None | 0 | 12.3 | Positive |
| 1 | B | 45140 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Door | Wood | Gray | None | 0 | 23.8 | Positive |
| 1 | B | 45140 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Door Casing | Wood | Gray | None | 0 | 23.6 | Positive |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Stair Tread | Concrete | Gray | Flaking | 20 | 0.5 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Stair Riser | Concrete | Gray | Flaking | 5 | 2.3 | Positive |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Fan Unit | Metal | Gray | Flaking | 100 | 0 | Negative |
| 1 | B | 8-2 | Fan Room along 13th Street (adjacent to the New Boiler Room's Electrical Gated Area) | Duct Work | Concrete | Gray | Flaking | 100 | 0.1 | Negative |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | W1 | Concrete | Gray | Flaking | 300 | 0.4 | Negative |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | W2 | Concrete | Gray | Flaking | 500 | 0.4 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|---|-------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | W3 | Concrete | Gray | Flaking | 300 | 25.2 | Positive |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | W4 | Brick | Gray | Flaking | 500 | 16.7 | Positive |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | Fan Unit | Metal | Gray | Flaking | 200 | 0.1 | Negative |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | Floor | Concrete | White | Chipping | 2000 | No Access | Assumed |
| 1 | B | 5 | Fan Room No. 1 (next to Basement Stairs to New Boiler Room - Under BE Office) | Ceiling | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W1 | Concrete | White | Flaking | 200 | 0.3 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W1 | Concrete | Gray | Flaking | 200 | 26.7 | Positive |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W2 | Concrete | White | Flaking | 200 | 0.2 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W2 | Concrete | Gray | Flaking | 200 | 0.3 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W3 | Brick | White | Flaking | 200 | 0.3 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W3 | Brick | Gray | Flaking | 200 | 0.3 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W4 | Brick | White | Flaking | 200 | 0.6 | Negative |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | W4 | Brick | Gray | Flaking | 200 | 0.9 | Positive |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | Ceiling | Concrete | White | Flaking | 1000 | No Access | Assumed |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | Floor | Concrete | Unpainted | N/A | N/A | N/A | N/A |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | Door | Wood | Gray | Flaking | 28 | 24.2 | Positive |
| 1 | B | 1 | Fan Room No. 2 next to Rear stair to Old Boiler Room | Door Casing | Wood | Gray | Flaking | 10 | 25.7 | Positive |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | 001A | Former Shower Room next to Fan Room #2 near rear stair to Old Boiler Room | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W1 | Brick | Gray | Flaking | 100 | 7.1 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W1 | Brick | White | Flaking | 100 | 7.3 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W2 | Concrete | Gray | Flaking | 100 | 0.3 | Negative |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W2 | Concrete | White | Flaking | 100 | 0.2 | Negative |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W3 | Brick | Gray | Flaking | 100 | 5.3 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W3 | Brick | White | Flaking | 100 | 6.1 | Positive |

Dates: 3/13/2023 to 7/21/2023

Inspector Name and PA License Number:
Lawrence Jackson 003683

Inspection Company: USA Environmental
Management Inc

Lead-Safe Certification Assessment Report

Parkway Center City Middle College

540 North 13th Street, Philadelphia, PA 19123

| Element | Floor | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
|---------|-------|---------|--|-------------|--------------------|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | | | | | | | | |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W4 | Brick | Gray | Flaking | 12 | 5.1 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | W4 | Brick | White | Flaking | 12 | 6.3 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Ceiling | Concrete | White | Flaking | 80 | 3.6 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Door | Metal | Tan | None | 0 | 0.1 | Negative |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Door Casing | Metal | Tan | None | 0 | 0.4 | Negative |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Handrail | Metal | Gray | Chipping | 20 | 18.3 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Stair Tread | Concrete | Gray | Flaking | 100 | 15.3 | Positive |
| 1 | B | S001 | Rear Stair to Old Boiler Room near Room 106 | Stair Riser | Concrete | Gray | Flaking | 100 | 11.3 | Positive |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W1 | Brick | Tan | None | 0 | 0.6 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W1 | Brick | White | None | 0 | 0.5 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W2 | Concrete | Tan | None | 0 | 0 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W2 | Concrete | White | None | 0 | 0.2 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W3 | Brick | Tan | None | 0 | 2.2 | Positive |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | W3 | Brick | White | None | 0 | 0.7 | Positive |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Door | Metal | Gray | None | 0 | 0.1 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Door Casing | Metal | Gray | None | 0 | 0.3 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Stair Tread | Concrete | Gray | Cracking | 80 | 0.4 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Stair Riser | Concrete | Gray | Cracking | 50 | 0 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Handrail | Metal | Gray | None | 0 | 0 | Negative |
| 1 | B | SB1 | Stairs to Fan Room No. 1 and New Boiler Room | Ceiling | Concrete | White | None | 0 | 0.3 | Negative |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | A | Main AT | Main Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | 3 | Aud AT | Auditorium Attic | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |
| 1 | C | CS | Crawl Space | No Access | No Access | No Access | No Access | No Access | No Access | No Access |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Entry Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Entry Door Frame | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 1 | S13 | Stairwell adjacent to Office Suite 103 | Door Frame | Metal | Brown | None | 0 | 0.8 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Drain Pipe | Metal | Brown | Flaking | 6 | 2 | Positive |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Window Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 413 | Boy's Restroom adjacent to Classroom 401 | Door Casing | Wood | Brown | None | 0 | 0.2 | Negative |
| 1 | 4 | 401 | Classroom 401 | Radiator | Metal | Gray | Flaking | 4 | 3.5 | Positive |
| 1 | 4 | 401 | Classroom 401 | Radiator | Metal | Gray | Flaking | 4 | 0 | Negative |
| 1 | 4 | 401 | Classroom 401 | Radiator | Metal | Gray | Flaking | 5 | 0.1 | Negative |
| 1 | 4 | 401 | Classroom 401 | Drain Pipe | Metal | Gray | Chipping | 1 | 0.3 | Negative |
| 1 | 4 | 401 | Classroom 401 | Drain Pipe | Metal | White | Chipping | 1 | 3.7 | Positive |
| 1 | 4 | 401 | Classroom 401 | Door | Wood | Varnish | None | 0 | 0.1 | Negative |
| 1 | 4 | 401 | Classroom 401 | Door Casing | Wood | Varnish | None | 0 | 0 | Negative |
| 1 | 4 | 401 | Classroom 401 | Window Casing | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 401 | Classroom 401 | Window Sill | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | 401 | Classroom 401 | Window Apron | Wood | Varnish | None | 0 | 0.2 | Negative |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | Stair Riser | Concrete | Gray | None | 0 | 4.8 | Positive |
| 1 | 4 | H41A | Hallway outside 4th Floor Boy's Restroom | Stair Stringer | Concrete | Gray | None | 0 | 5.9 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door Casing | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door | Metal | Brown | None | 0 | 0.1 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door Casing | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Drain Pipe | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Drain Pipe | Metal | White | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Drain Pipe | Metal | Brown | Flaking | 12 | 11.4 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Security Gate | Metal | Brown | Flaking | 100 | 9.8 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Door Casing | Metal | Brown | Flaking | 5 | 0.1 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Ceiling | Concrete | White | Flaking | 100 | 0 | Negative |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Handrail | Metal | Brown | Chipping | 10 | 0.8 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Stair Riser | Concrete | Grey | None | 0 | 1.9 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Stair Tread | Concrete | Grey | None | 0 | 1.5 | Positive |
| 1 | 4 | S46 | Fire Tower adjacent to Classroom 402 | Stair Stringer | Concrete | Grey | None | 0 | 2.3 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Floor | Concrete | Gray | None | 0 | 1.5 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Newel Post | Metal | Brown | None | 0 | 5.8 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Door | Metal | Brown | None | 0 | 0 | Negative |

| | | | Dates: 3/13/2023 to 7/21/2023 | | Lead-Safe Certification Assessment Report | | | | | |
|---------------------------------|-----------------------|---------|--|-----------------------|---|-------------|-----------------------|----------------------|----------------------|-------------------------|
| | | | Inspector Name and PA License Number: Lawrence Jackson 003683 | | Parkway Center City Middle College | | | | | |
| | | | Inspection Company: USA Environmental Management Inc | | 540 North 13th Street, Philadelphia, PA 19123 | | | | | |
| E l e m e n t | F l o o r | Space # | Onsite Room Name | Component | Substrate Material | Paint Color | Description of Damage | Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/negative) |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Door Casing | Metal | Brown | None | 0 | 2.4 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Ceiling | Plaster | White | None | 0 | 10.8 | Positive |
| 1 | 4 | S44 | Stairwell adjacent to Classroom 405 | Radiator | Metal | Gray | None | 0 | 1.5 | Positive |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Radiator | Metal | Gray | None | 0 | 0 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Radiator | Metal | Gray | Chipping | 5 | 0 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Radiator | Metal | Gray | Chipping | 5 | 0 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Lockers | Metal | Blue | None | 0 | 0.1 | Negative |
| 1 | 4 | H41 | Hallway outside Classrooms 401 to 404 | Door Electrical Panel | Metal | Blue | None | 0 | 3.5 | Positive |
| 1 | 4 | 405A | Classroom 405 Copy Room | Door Casing | Metal | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Baseboard | Wood | Brown | None | 0 | 0 | Negative |
| 1 | 4 | 405A | Classroom 405 Copy Room | Window Casing | Wood | Brown | None | 0 | 0.5 | Negative |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | Lockers | Metal | Blue | None | 0 | 0.2 | Negative |
| 1 | 4 | H43 | Hallway outside Classrooms 405 to 408 | Lockers | Metal | Orange | None | 0 | 0.4 | Negative |