

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2520	1	2	211B	Equipment Storage	Book Closet (Room 10) next to Teacher's Work Area	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Shelves	N	
2	2520	1	2	211B	Equipment Storage	Book Closet (Room 10) next to Teacher's Work Area	W3	Flaking	2	N	N	0	Y - 42 SF Shelves	N	
3	2520	1	2	211B	Equipment Storage	Book Closet (Room 10) next to Teacher's Work Area	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Shelves	N	
4	2520	1	2	210B	Storage	Book Closet (Room 11) next to Nurse's Office	W2	Cracking	2	N	N	0	Y - 40 SF Shelves	N	
5	2520	1	2	210B	Storage	Book Closet (Room 11) next to Nurse's Office	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves	N	
6	2520	1	2	210B	Storage	Book Closet (Room 11) next to Nurse's Office	W4	Partially Inaccessible	0	N	N	0	Y - 8 SF Shelves	N	
7	2520	1	2	212A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 203	Ceiling	Chipping	2	N	N	0	N	N	
8	2520	1	2	212A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 203	Floors	Flaking	2	N	N	0	N	N	Flaking beneath Urinals
9	2520	1	2	212A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 203	W3	Cracking	2	N	N	0	N	N	
10	2520	1	2	201	Computer - Intermediate Middle	Classroom 201 (Computer Lab)	W1	Partially Inaccessible	0	N	N	0	Y - 168 SF Bulletin Boards, Whiteboard, Desks	N	
11	2520	1	2	201	Computer - Intermediate Middle	Classroom 201 (Computer Lab)	W2	Flaking	5	N	N	0	N	Y - 8 SF	Plastering Needed Around All Windows
12	2520	1	2	201	Computer - Intermediate Middle	Classroom 201 (Computer Lab)	W3	Flaking	15	N	N	0	Y - 32 SF Posters	Y - 12 SF	Plastering Needed Around All Windows
13	2520	1	2	201	Computer - Intermediate Middle	Classroom 201 (Computer Lab)	W4	Partially Inaccessible	0	N	N	0	Y - 182 SF Posters, Bulletin Boards	N	
14	2520	1	2	201A	Storage	Classroom 201 Closet	Ceiling	Flaking	144	N	N	0	N	N	Entire Ceiling
15	2520	1	2	201A	Storage	Classroom 201 Closet	W1	Flaking	72	N	N	0	Y - Entire Room Filled with Boxes	N	Entire Wall
16	2520	1	2	201A	Storage	Classroom 201 Closet	W2	Flaking	288	N	N	0	Y - Entire Room Filled with Boxes	N	Entire Wall
17	2520	1	2	201A	Storage	Classroom 201 Closet	W3	Flaking	72	N	N	0	Y - Entire Room Filled with Boxes	N	Entire Wall
18	2520	1	2	201A	Storage	Classroom 201 Closet	W4	Flaking	288	N	N	0	Y - Entire Room Filled with Boxes	N	Entire Wall

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
19	2520	1	2	202	Primary	Classroom 202	W1	Flaking	1	N	N	0	Y - 72 SF Bulletin Boards, Posters	N	
20	2520	1	2	202	Primary	Classroom 202	W2	Cracking	2	N	N	0	Y - 96 SF Bulletin Boards, Posters	N	2 Locations; Additional Cracking
21	2520	1	2	202	Primary	Classroom 202	W3	Flaking	4	N	Y - Window Sills 1-3	6	Y - 45 SF Posters	Y - 12 SF	2 Locations; Flaking @ Radiator & Wall
22	2520	1	2	202	Primary	Classroom 202	W4	Flaking	26	N	N	0	N	Y - 8 SF	
23	2520	1	2	202A	Storage	Classroom 202 Closet	Ceiling	Flaking	12	N	N	0	N	N	
24	2520	1	2	202A	Storage	Classroom 202 Closet	W1	Cracking	2	N	N	0	N	N	
25	2520	1	2	202A	Storage	Classroom 202 Closet	W2	Flaking	12	Y	N	0	N	N	Water Stain on Wall 2
26	2520	1	2	202A	Storage	Classroom 202 Closet	W3	Flaking	24	N	N	0	Y - 16 SF Bookcases	N	
27	2520	1	2	202A	Storage	Classroom 202 Closet	W4	Flaking	16	N	N	0	N	N	
28	2520	1	2	203	Primary	Classroom 203	Ceiling	Flaking	10	Y	N	0	N	N	3 Locations; Water Stains
29	2520	1	2	203	Primary	Classroom 203	W1	Partially Inaccessible	0	N	N	0	Y - 126 SF Bulletin Boards, Cabinets, Posters	N	
30	2520	1	2	203	Primary	Classroom 203	W2	Cracking	8	N	N	0	Y - 110 SF Cabinets, Posters	N	
31	2520	1	2	203	Primary	Classroom 203	W3	Flaking	44	N	N	0	Y - 48 SF Contents, Desks, Chairs	Y - 36 SF	3 Locations; Additional Cracking; Plastering Needed @ Window Frames; Damage Includes Radiator, Wall, Window Frames
32	2520	1	2	203	Primary	Classroom 203	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Bulletin Boards, Bookcases	N	
33	2520	1	2	203A	Storage	Classroom 203 Closet	Ceiling	Flaking	16	N	N	0	N	N	
34	2520	1	2	203A	Storage	Classroom 203 Closet	W2	Flaking	10	N	N	0	Y - 40 SF Contents	N	2 Locations
35	2520	1	2	204	Primary	Classroom 204	W1	Partially Inaccessible	0	N	N	0	Y - 175 SF Bulletin Boards, White Board, Posters	N	
36	2520	1	2	204	Primary	Classroom 204	W2	Cracking	2	N	N	0	Y - 120 SF Bulletin Boards, Posters	N	
37	2520	1	2	204	Primary	Classroom 204	W3	Flaking	26	N	N	0	N	Y - 26 SF	2 Locations; Plastering Needed on Windows 1-4
38	2520	1	2	204	Primary	Classroom 204	W4	Partially Inaccessible	0	N	N	0	Y - 200 SF Posters, Bulletin Boards	N	
39	2520	1	2	204A	Storage	Classroom 204 Closet	Ceiling	Flaking	72	Y	N	0	N	N	
40	2520	1	2	204A	Storage	Classroom 204 Closet	W2	Significant Moisture Damage	8	Y	N	0	Y - 96 SF Cabinets	N	
41	2520	1	2	204A	Storage	Classroom 204 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Cabinets	N	
42	2520	1	2	204A	Storage	Classroom 204 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Cabinets	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
43	2520	1	2	205	Primary	Classroom 205	Ceiling	Flaking	28	Y	N	0	N	N	Water Stain on Ceiling
44	2520	1	2	205	Primary	Classroom 205	W1	Cracking	6	N	N	0	Y - 150 SF Whiteboard, Posters	N	2 Locations
45	2520	1	2	205	Primary	Classroom 205	W2	Flaking	3	N	N	0	Y - 120 SF Whiteboard, Posters	N	
46	2520	1	2	205	Primary	Classroom 205	W3	Flaking	26	N	N	0	Y - 75 SF Desks, Posters, Contents	Y - 22 SF	2 Locations; Plaster Needed on Window Frames
47	2520	1	2	205	Primary	Classroom 205	W4	Cracking	5	N	N	0	N	N	
48	2520	1	2	205A	Storage	Classroom 205 Closet	Ceiling	Cracking	16	N	N	0	N	N	
49	2520	1	2	205A	Storage	Classroom 205 Closet	W2	Flaking	2	N	N	0	Y - 21 SF Cabinets	N	
50	2520	1	2	205A	Storage	Classroom 205 Closet	W3	Flaking	8	N	N	0	Y - 30 SF Boxes	N	2 Locations; Including Metal Pipe
51	2520	1	2	205A	Storage	Classroom 205 Closet	W4	Flaking	6	N	N	0	N	N	
52	2520	1	2	206	Primary	Classroom 206	Ceiling	Flaking	2	N	N	0	N	N	
53	2520	1	2	206	Primary	Classroom 206	W1	Holes	2	N	N	0	N	N	
54	2520	1	2	206	Primary	Classroom 206	W2	Flaking	12	N	N	0	Y - 144 SF Bookcases, Posters	Y - 12 SF	Plastering Needed on Window Frames
55	2520	1	2	206	Primary	Classroom 206	W3	Flaking	24	N	N	0	Y - 70 SF Desks, Posters	Y - 18 SF	Plastering Needed on Window Frames; Flaking on Radiator Grate & Wall
56	2520	1	2	206	Primary	Classroom 206	W4	Partially Inaccessible	0	N	N	0	Y - 84 SF Contents, Whiteboard	N	
57	2520	1	2	206A	Storage	Classroom 206 Closet	W1	Cracking	2	N	N	0	N	N	
58	2520	1	2	206A	Storage	Classroom 206 Closet	W2	Flaking	5	N	N	0	Y - 48 SF Contents	N	2 Locations; Including Metal Pipe
59	2520	1	2	206A	Storage	Classroom 206 Closet	W3	Cracking	12	N	N	0	Y - 60 SF Contents	N	
60	2520	1	2	206A	Storage	Classroom 206 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Cabinets	N	
61	2520	1	2	207	Primary	Classroom 207	Ceiling	Flaking	2	N	N	0	N	Y - 2 SF	Additional Spalling
62	2520	1	2	207	Primary	Classroom 207	Floors	Chipping	12	N	N	0	N	N	
63	2520	1	2	207	Primary	Classroom 207	W1	Cracking	1	N	N	0	Y - 168 SF Bulletin Boards, Desks	N	
64	2520	1	2	207	Primary	Classroom 207	W2	Flaking	2	N	N	0	N	N	
65	2520	1	2	207	Primary	Classroom 207	W3	Flaking	66	Y	N	0	Y - 50 SF Bookcases, Posters	Y - 35 SF	Additional Efflorescence; Plastering Needed on Windows
66	2520	1	2	207	Primary	Classroom 207	W4	Flaking	46	N	N	0	N	Y - 12 SF	Additional Cracking; Plastering Needed on Windows

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
67	2520	1	2	207A	Storage	Classroom 207 Closet	Ceiling	Flaking	72	Y	N	0	N	Y - 72 SF	Additional Efflorescence & Significant Moisture Damage
68	2520	1	2	207A	Storage	Classroom 207 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 64 SF Cabinets, Bookcases	N	
69	2520	1	2	207A	Storage	Classroom 207 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Cabinets	N	
70	2520	1	2	207A	Storage	Classroom 207 Closet	W4	Flaking	3	N	N	0	Y - 40 SF Contents	N	Additional Chipping
71	2520	1	2	208	Administrative Office	Counselor's Office next to Nurse's Office	Ceiling	Flaking	24	N	N	0	N	Y - 4 SF	
72	2520	1	2	208	Administrative Office	Counselor's Office next to Nurse's Office	W1	Flaking	16	N	N	0	N	Y - 16 SF	
73	2520	1	2	208	Administrative Office	Counselor's Office next to Nurse's Office	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Desk	N	
74	2520	1	2	208	Administrative Office	Counselor's Office next to Nurse's Office	W3	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
75	2520	1	2	208	Administrative Office	Counselor's Office next to Nurse's Office	W4	Flaking	20	N	N	0	N	Y - 20 SF	
76	2520	1	2	S4	Stairs	Fire Tower Stairwell near Teacher's Work Area	W1	Flaking	1	N	N	0	N	N	
77	2520	1	2	212	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 203	Floors	Chipping	4	N	N	0	N	N	
78	2520	1	2	H210	Circulation (Hallway)	Hallway from Classrooms 201 to 207	Floors	Flaking	20 SF	N	N	0	N	N	
79	2520	1	2	H210	Circulation (Hallway)	Hallway from Classrooms 201 to 207	W2	Holes	3	N	N	0	Y - 48 SF Posters	Y - 1 SF	
80	2520	1	2	H210	Circulation (Hallway)	Hallway from Classrooms 201 to 207	W4	Partially Inaccessible	0	N	N	0	Y - 64 SF Bulletin Boards, Posters	N	
81	2520	1	2	210	Administrative Office	Nurse's Office	Ceiling	Cracking	8	N	N	0	N	N	
82	2520	1	2	210	Administrative Office	Nurse's Office	Floors	Flaking	18	N	N	0	N	N	
83	2520	1	2	210	Administrative Office	Nurse's Office	W2	Flaking	6	N	N	0	N	N	Debris Falls When Paper Towel Dispenser is Used
84	2520	1	2	210	Administrative Office	Nurse's Office	W3	Flaking	3	N	N	0	N	N	
85	2520	1	2	210	Administrative Office	Nurse's Office	W4	Cracking	8	N	N	0	N	N	
86	2520	1	2	210A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	Ceiling	Cracking	2	N	N	0	N	N	2 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
87	2520	1	2	210A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W1	Flaking	72	N	N	0	N	N	Entire Wall; Additional Cracking
88	2520	1	2	210A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W2	Flaking	80	N	N	0	N	N	Additional Cracking
89	2520	1	2	210A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W3	Flaking	42	N	N	0	N	N	
90	2520	1	2	210A	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W4	Flaking	84	N	Y - Window Sill	1	N	N	
91	2520	1	2	S2	Stairs	Stairwell near Classrooms 201 and 202	Floors	Flaking	10	N	N	0	N	N	10 Locations
92	2520	1	2	S2	Stairs	Stairwell near Classrooms 201 and 202	W3	Cracking	10	N	N	0	N	N	
93	2520	1	2	S1	Stairs	Stairwell near Classrooms 206 and 207	Floors	Flaking	4	N	N	0	N	N	Flaking on Landing Between 1st & 2nd Floors
94	2520	1	2	S1	Stairs	Stairwell near Classrooms 206 and 207	W2	Cracking	13	N	N	0	N	N	2 Locations; Additional Chipping
95	2520	1	2	S1	Stairs	Stairwell near Classrooms 206 and 207	W4	Cracking	12	N	N	0	N	N	
96	2520	1	2	211	Administrative Office	Teacher's Work Area (Copy Machine)	W3	Flaking	2	N	N	0	N	N	Flaking @ Window 2
97	2520	1	2	211C	Restrooms, Staff - Male/Female	Teacher's Work Area Restroom	W1	Flaking	72	N	N	0	N	N	Additional Cracking
98	2520	1	2	211C	Restrooms, Staff - Male/Female	Teacher's Work Area Restroom	W2	Flaking	12	N	N	0	N	N	3 Locations; Top of Window & Radiator
99	2520	1	2	211C	Restrooms, Staff - Male/Female	Teacher's Work Area Restroom	W3	Flaking	40	N	N	0	N	N	Additional Cracking
100	2520	1	2	211C	Restrooms, Staff - Male/Female	Teacher's Work Area Restroom	W4	Flaking	40	N	N	0	N	N	Additional Cracking
101	2520	1	1	107	Auditorium	Auditorium	Ceiling	Cracking	10	N	N	0	N	N	
102	2520	1	1	107	Auditorium	Auditorium	Floors	Flaking	120	N	N	0	N	N	Additional Chipping; Damage Around Perimeter

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
103	2520	1	1	107	Auditorium	Auditorium	W1	Flaking	8	N	N	0	N	N	
104	2520	1	1	107	Auditorium	Auditorium	W2	Flaking	18	N	N	0	N	N	3 Locations
105	2520	1	1	107	Auditorium	Auditorium	W4	Flaking	8	N	N	0	N	N	2 Locations
106	2520	1	1	107 STAGE	Stage	Auditorium Stage	W1	Partially Inaccessible	0	N	N	0	Y - 160 SF Curtains	N	
107	2520	1	1	107 STAGE	Stage	Auditorium Stage	W2	Partially Inaccessible	0	N	N	0	Y - 8 SF File Cabinets	N	
108	2520	1	1	107 STAGE	Stage	Auditorium Stage	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	
109	2520	1	1	101	Primary	Classroom 101	Ceiling	Flaking	3	N	N	0	N	N	
110	2520	1	1	101	Primary	Classroom 101	W1	Chipping	12	N	N	0	Y - 182 SF Cabinets, Bulletin Boards, Posters	N	
111	2520	1	1	101	Primary	Classroom 101	W2	Flaking	2	N	N	0	Y - 96 SF Posters	N	Additional Cracking; Damage @ Window 2
112	2520	1	1	101	Primary	Classroom 101	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Posters	N	
113	2520	1	1	101	Primary	Classroom 101	W4	Partially Inaccessible	0	N	N	0	Y - 144 SF Posters	N	
114	2520	1	1	101A	Storage	Classroom 101 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Contents	N	
115	2520	1	1	101A	Storage	Classroom 101 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Shelves	N	
116	2520	1	1	101A	Storage	Classroom 101 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Shelves	N	
117	2520	1	1	112	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W1	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
118	2520	1	1	112	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W2	Flaking	48	N	N	0	N	N	Entire Wall; Including Radiator Grate
119	2520	1	1	112	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W3	Flaking	96	N	N	0	N	N	2 Locations
120	2520	1	1	112	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W4	Flaking	6	N	N	0	N	N	
121	2520	1	1	102	Primary	Classroom 102	W1	Flaking	2	N	N	0	Y - 180 SF Bookcases, Bulletin Boards, Posters	N	
122	2520	1	1	102	Primary	Classroom 102	W2	Partially Inaccessible	0	N	N	0	Y - 210 SF Desks, Posters, Bulletin Boards	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
123	2520	1	1	102	Primary	Classroom 102	W3	Spalling	1	N	N	0	Y - 60 SF Desks, Contents	N	
124	2520	1	1	102	Primary	Classroom 102	W4	Cracking	4	Y	N	0	Y - 48 SF Contents	N	
125	2520	1	1	102A	Storage	Classroom 102 Closet	Ceiling	Flaking	1	N	N	0	N	N	
126	2520	1	1	102A	Storage	Classroom 102 Closet	W2	Flaking	13	N	N	0	Y - 30 SF Shelves	N	2 Locations
127	2520	1	1	102A	Storage	Classroom 102 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
128	2520	1	1	102A	Storage	Classroom 102 Closet	W4	Flaking	18	N	N	0	Y - 54 SF Desks, Shelves	N	
129	2520	1	1	103	Primary	Classroom 103	W1	Cracking	2	N	N	0	Y - 125 SF Bookcases, Posters	N	Cracking @ Entrance
130	2520	1	1	103	Primary	Classroom 103	W2	Partially Inaccessible	0	N	N	0	Y - 184 SF Contents	N	
131	2520	1	1	103	Primary	Classroom 103	W3	Flaking	18	N	N	0	Y - 40 SF Contents	N	4 Locations
132	2520	1	1	103	Primary	Classroom 103	W4	Partially Inaccessible	0	N	N	0	Y - 184 SF Bookcases, Desks, Fridge	N	
133	2520	1	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking	2	Y	N	0	N	N	Water Stain on Ceiling
134	2520	1	1	103A	Storage	Classroom 103 Closet	W2	Flaking	24	N	N	0	N	N	4 Locations; Including Metal Pipe
135	2520	1	1	103A	Storage	Classroom 103 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 42 SF Shelves	N	
136	2520	1	1	103A	Storage	Classroom 103 Closet	W4	Cracking	10	N	N	0	N	N	
137	2520	1	1	104	Primary	Classroom 104	W1	Partially Inaccessible	0	N	N	0	Y - 96 SF Bulletin Boards	N	
138	2520	1	1	104	Primary	Classroom 104	W2	Partially Inaccessible	0	N	N	0	Y - 140 SF Bulletin Boards, Whiteboard, Desks	N	
139	2520	1	1	104	Primary	Classroom 104	W3	Cracking	2	N	N	0	N	N	Cracking @ Window 1
140	2520	1	1	104	Primary	Classroom 104	W4	Partially Inaccessible	0	N	N	0	Y - 140 SF Bulletin Boards, Contents	N	
141	2520	1	1	105	Primary	Classroom 105	W2	Partially Inaccessible	0	N	N	0	Y - 88 SF Cabinets, Desks, Tables, Contents	N	
142	2520	1	1	105	Primary	Classroom 105	W3	Flaking	5	Y	N	0	Y - 120 SF Bookcases, Tables, Desks	Y - 5 SF	Additional Efflorescence; Damage @ Window 1
143	2520	1	1	105	Primary	Classroom 105	W4	Partially Inaccessible	0	N	N	0	Y - 96 SF Bookcases, Posters	N	
144	2520	1	1	105A	Storage	Classroom 105 Closet	W2	Cracking	8	N	N	0	Y - 42 SF File Cabinets, Contents	N	
145	2520	1	1	105A	Storage	Classroom 105 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Shelves, Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
146	2520	1	1	105A	Storage	Classroom 105 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents, Boxes	N	
147	2520	1	1	106	Primary	Classroom 106	W2	Flaking	4	N	Y - Window Sills	4	Y - 80 SF Bookcases, Shelves	N	2 Locations; Debris on Window Sills 1,2
148	2520	1	1	106	Primary	Classroom 106	W3	Flaking	6	N	Y - Window Sills	6	Y - 120 SF Bookcases, Desks, Tables	N	3 Locations; Debris on Window Sills 1-3
149	2520	1	1	106	Primary	Classroom 106	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents	N	
150	2520	1	1	106A	Storage	Classroom 106 Closet	W1	Cracking	13	N	N	0	N	N	2 Locations; Additional Chipping
151	2520	1	1	106A	Storage	Classroom 106 Closet	W2	Flaking	24	N	N	0	Y - 96 SF Contents	N	Additional Chipping; Damage on Coat Rack Hook Board
152	2520	1	1	106A	Storage	Classroom 106 Closet	W3	Cracking	12	N	N	0	Y - 46 SF Contents	N	
153	2520	1	1	106A	Storage	Classroom 106 Closet	W4	Flaking	38	N	N	0	Y - 96 SF Contents	N	Additional Cracking
154	2520	1	1	S107C	Circulation (Hallway)	Hallway between Auditorium Entrance and Home & School Office	W2	Partially Inaccessible	0	N	N	0	Y - 6 SF Posters	N	
155	2520	1	1	S107C	Circulation (Hallway)	Hallway between Auditorium Entrance and Home & School Office	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Bulletin Boards, Contents	N	Flaking on Top of Door Frame
156	2520	1	1	S107C	Circulation (Hallway)	Hallway between Auditorium Entrance and Home & School Office	W4	Flaking	6	N	N	0	N	N	
157	2520	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 106	W1	Flaking	2	N	N	0	N	N	Flaking @ S1 Door
158	2520	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 106	W2	Cracking	13	N	N	0	Y - 330 SF Bulletin Boards, Posters	N	
159	2520	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 101 to 106	W4	Flaking	1	N	N	0	Y - 330 SF Bulletin Boards, Posters	Y - 1 SF	
160	2520	1	1	S107D	Administrative Office	Home and School Office	Floors	Chipping	52	N	N	0	N	N	
161	2520	1	1	S107D	Administrative Office	Home and School Office	W2	Flaking	1	N	N	0	Y - 60 SF Desks, File Cabinets, Boxes	N	
162	2520	1	1	S107D	Administrative Office	Home and School Office	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
163	2520	1	1	S107D	Administrative Office	Home and School Office	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Bulletin Boards, Shelves	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
164	2520	1	1	108	Administrative Office	Main Office	W1	Flaking	5	N	N	0	Y - 50 SF Whiteboards, Desks, Copier	N	
165	2520	1	1	108	Administrative Office	Main Office	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Bookcase, Bench	N	
166	2520	1	1	108	Administrative Office	Main Office	W3	Cracking	4	N	N	0	Y - 60 SF Posters, Desks	N	
167	2520	1	1	108	Administrative Office	Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 96 SF Cabinets	N	
168	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
169	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	Floors	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
170	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
171	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
172	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
173	2520	1	1	110B	Storage	Music Instrument Storage Room next to Teacher's Lounge	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
174	2520	1	1	109	Administrative Office	Principal's Office	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Fridge, Bookcases	N	
175	2520	1	1	109	Administrative Office	Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases	N	
176	2520	1	1	109	Administrative Office	Principal's Office	W4	Partially Inaccessible	0	N	N	0	Y - 42 SF File Cabinets, Cabinets	N	
177	2520	1	1	109A	Restrooms, Staff - Female	Principal's Office Restroom	W1	Cracking	4	N	N	0	Y - 8 SF Locker	N	
178	2520	1	1	109A	Restrooms, Staff - Female	Principal's Office Restroom	W2	Flaking	3	N	N	0	Y - 8 SF Locker	N	Additional Cracking
179	2520	1	1	109A	Restrooms, Staff - Female	Principal's Office Restroom	W3	Cracking	12	N	N	0	N	N	2 Locations
180	2520	1	1	109A	Restrooms, Staff - Female	Principal's Office Restroom	W4	Flaking	3	N	N	0	N	N	2 Locations; Additional Cracking; Damage Includes Radiator Grate & ACPI

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
181	2520	1	1	S1	Stairs	Stairwell near Classroom 106	Floors	Flaking	18	N	N	0	N	N	Additional Chipping; Damage in Various Locations on Entire Staircase
182	2520	1	1	S3	Stairs	Stairwell from Main Hall to Parking Lot	W3	Flaking	3	N	N	0	N	N	Flaking above Door
183	2520	1	1	S3	Stairs	Stairwell from Main Hall to Parking Lot	W4	Flaking	1	N	N	0	N	N	
184	2520	1	1	S107F	Stairs	Stairwell from Rear Auditorium Door to Parking Lot	Ceiling	Cracking	1	N	N	0	N	N	
185	2520	1	1	S107F	Stairs	Stairwell from Rear Auditorium Door to Parking Lot	W3	Cracking	8	N	N	0	N	N	
186	2520	1	1	S107F	Stairs	Stairwell from Rear Auditorium Door to Parking Lot	W4	Flaking	10	N	N	0	N	N	Flaking on Door Frame
187	2520	1	1	S2	Stairs	Stairwell near Classrooms 101 and 102	Floors	Flaking	9	N	N	0	N	N	
188	2520	1	1	S2	Stairs	Stairwell near Classrooms 101 and 102	W3	Flaking	12	N	N	0	N	N	
189	2520	1	1	109B	Storage	Storage Room across from Classroom 104	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
190	2520	1	1	109B	Storage	Storage Room across from Classroom 104	Floors	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
191	2520	1	1	109B	Storage	Storage Room across from Classroom 104	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
192	2520	1	1	109B	Storage	Storage Room across from Classroom 104	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
193	2520	1	1	109B	Storage	Storage Room across from Classroom 104	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
194	2520	1	1	109B	Storage	Storage Room across from Classroom 104	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
195	2520	1	1	110	Administrative Office	Teacher's Lounge	Ceiling	Flaking	1	N	N	0	N	N	
196	2520	1	1	110	Administrative Office	Teacher's Lounge	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Cabinets, Bulletin Boards	N	
197	2520	1	1	110	Administrative Office	Teacher's Lounge	W3	Flaking	7	N	N	0	N	N	3 Locations; Additional Cracking
198	2520	1	1	110	Administrative Office	Teacher's Lounge	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Vending Machine, Fridge	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
199	2520	1	1	111	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	W1	Flaking	4	N	N	0	N	N	Including Metal Pipe
200	2520	1	1	111	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	W2	Flaking	48	N	N	0	N	N	
201	2520	1	1	111	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	W3	Flaking	54	N	N	0	N	N	
202	2520	1	1	111	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	W4	Flaking	4	N	N	0	N	N	Flaking on Radiator Grate
203	2520	1	0	001	Student Restrooms - Male (4-12)	Boys" Restroom next to Tank Room	Floors	Chipping	4	N	N	0	N	N	4 Locations
204	2520	1	0	001	Student Restrooms - Male (4-12)	Boys" Restroom next to Tank Room	W1	Flaking	10	N	N	0	N	N	2 Locations
205	2520	1	0	001	Student Restrooms - Male (4-12)	Boys" Restroom next to Tank Room	W3	Flaking	18	N	N	0	N	N	Flaking Above Radiator
206	2520	1	0	001	Student Restrooms - Male (4-12)	Boys" Restroom next to Tank Room	W4	Flaking	12	N	N	0	N	N	
207	2520	1	0	020	Cafeteria	Cafeteria and Kitchen	Ceiling	Flaking	24	Y	N	0	N	N	3 Locations; Additional Efflorescence; Damage on Window Lentils 1-3
208	2520	1	0	020	Cafeteria	Cafeteria and Kitchen	W1	Chipping	20	N	N	0	Y - 80 SF Posters	N	5 Locations
209	2520	1	0	020	Cafeteria	Cafeteria and Kitchen	W2	Partially Inaccessible	0	N	N	0	Y - 192 SF Oven, Freezer, Posters	N	
210	2520	1	0	020	Cafeteria	Cafeteria and Kitchen	W3	Flaking	2	N	N	0	Y - 80 SF Posters	N	2 Locations; Additional Chipping
211	2520	1	0	020	Cafeteria	Cafeteria and Kitchen	W4	Flaking	16	N	N	0	Y - 18 SF Posters	N	Additional Chipping
212	2520	1	0	017	Primary	Classroom 014 (ESOL Room)	Ceiling	Flaking	16	N	N	0	N	N	2 Locations
213	2520	1	0	017	Primary	Classroom 014 (ESOL Room)	W1	Chipping	2	N	N	0	Y - 54 SF Contents	N	
214	2520	1	0	017	Primary	Classroom 014 (ESOL Room)	W3	Flaking	7	N	N	0	Y - 90 SF Bookcases	N	3 Locations; Flaking on ACPI
215	2520	1	0	017	Primary	Classroom 014 (ESOL Room)	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Desks, Bookcases	N	
216	2520	1	0	017B	Storage	Classroom 014 (ESOL Room) Closet/Storage	Ceiling	Partially Inaccessible	0	N	N	0	Y - 18 SF Ductwork	N	
217	2520	1	0	017B	Storage	Classroom 014 (ESOL Room) Closet/Storage	W2	Flaking	42	N	N	0	N	N	Entire Wall
218	2520	1	0	017B	Storage	Classroom 014 (ESOL Room) Closet/Storage	W4	Flaking	42	N	N	0	N	N	Entire Wall

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
219	2520	1	0	011	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Flaking	20	Y	N	0	N	Y - 8 SF	Additional Efflorescence
220	2520	1	0	011	Gymnasium - Intermediate Middle	Gymnasium	Floors	Flaking	30	N	N	0	N	N	Additional Chipping; Damage around Perimeter
221	2520	1	0	011	Gymnasium - Intermediate Middle	Gymnasium	W2	Partially Inaccessible	0	N	N	0	Y - 150 SF Contents	N	
222	2520	1	0	011	Gymnasium - Intermediate Middle	Gymnasium	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Contents	N	
223	2520	1	0	011	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking	4	N	N	0	Y - 24 SF Contents	N	
224	2520	1	0	001A	Administrative Office	Gymnasium Office	Ceiling	Flaking	30	Y	Y - Boxes & Equipment Beneath	6	N	N	
225	2520	1	0	001A	Administrative Office	Gymnasium Office	W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Desk, Bookcases, Contents	N	
226	2520	1	0	001A	Administrative Office	Gymnasium Office	W2	Flaking	16	N	N	0	N	N	
227	2520	1	0	001A	Administrative Office	Gymnasium Office	W3	Flaking	42	N	N	0	N	N	
228	2520	1	0	013A	Storage	Gymnasium Storage Area (near Gym Entrance/Steps) used by Home and School Program	W1	Partially Inaccessible	0	N	N	0	Y - 80 SF Shelves	N	
229	2520	1	0	013A	Storage	Gymnasium Storage Area (near Gym Entrance/Steps) used by Home and School Program	W2	Partially Inaccessible	0	N	N	0	Y - 100 SF Shelves	N	
230	2520	1	0	013A	Storage	Gymnasium Storage Area (near Gym Entrance/Steps) used by Home and School Program	W3	Partially Inaccessible	0	N	N	0	Y - 140 SF Shelves	N	
231	2520	1	0	013A	Storage	Gymnasium Storage Area (near Gym Entrance/Steps) used by Home and School Program	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Shelves	N	
232	2520	1	0	013	Storage	Gymnasium Storage Area (next to exterior wall) used by Home and School Program	W1	Partially Inaccessible	0	N	N	0	Y - 96 SF Shelves	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
233	2520	1	0	013	Storage	Gymnasium Storage Area (next to exterior wall) used by Home and School Program	W2	Flaking	100	N	N	0	Y - 60 SF Boxes	N	
234	2520	1	0	013	Storage	Gymnasium Storage Area (next to exterior wall) used by Home and School Program	W3	Partially Inaccessible	0	N	N	0	Y - 144 SF Shelves	N	
235	2520	1	0	013	Storage	Gymnasium Storage Area (next to exterior wall) used by Home and School Program	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves	N	
236	2520	1	0	019B	Storage	Hallway (used for Storage) from Smaller Cafeteria (Room 15) to Classroom 14.	Ceiling	Partially Inaccessible	0	N	N	0	Y - 216 SF Ductwork	N	
237	2520	1	0	019B	Storage	Hallway (used for Storage) from Smaller Cafeteria (Room 15) to Classroom 14.	Floors	None	0	N	Y	288	N	N	
238	2520	1	0	019B	Storage	Hallway (used for Storage) from Smaller Cafeteria (Room 15) to Classroom 14.	W2	Flaking	576	N	N	0	N	N	
239	2520	1	0	019B	Storage	Hallway (used for Storage) from Smaller Cafeteria (Room 15) to Classroom 14.	W4	Flaking	576	N	N	0	N	N	
240	2520	1	0	H01	Circulation (Hallway)	Hallway between IMC and Boiler Room	Ceiling	Flaking	16	N	N	0	N	N	3 Locations
241	2520	1	0	H01	Circulation (Hallway)	Hallway between IMC and Boiler Room	W1	Cracking	4	N	N	0	N	N	2 Locations; Additional Cracking
242	2520	1	0	H01	Circulation (Hallway)	Hallway between IMC and Boiler Room	W2	Flaking	4	N	N	0	N	N	Additional Chipping
243	2520	1	0	H01	Circulation (Hallway)	Hallway between IMC and Boiler Room	W3	Flaking	7	N	N	0	N	N	3 Locations; Additional Cracking
244	2520	1	0	H01	Circulation (Hallway)	Hallway between IMC and Boiler Room	W4	Flaking	1	N	N	0	N	N	
245	2520	1	0	H04	Circulation (Hallway)	Hallway from Boys' Restroom to Main Hallway	Ceiling	Flaking	18	N	N	0	N	N	2 Locations
246	2520	1	0	H04	Circulation (Hallway)	Hallway from Boys' Restroom to Main Hallway	Floors	Chipping	2	N	N	0	N	N	2 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
247	2520	1	0	H04	Circulation (Hallway)	Hallway from Boys' Restroom to Main Hallway	W1	Partially Inaccessible	0	N	N	0	Y - 44 SF Cabinets, Contents	N	
248	2520	1	0	H04	Circulation (Hallway)	Hallway from Boys' Restroom to Main Hallway	W2	Flaking	18	N	N	0	N	N	2 Locations
249	2520	1	0	H04	Circulation (Hallway)	Hallway from Boys' Restroom to Main Hallway	W4	Flaking	6	N	N	0	N	N	
250	2520	1	0	H03	Circulation (Hallway)	Hallway from Stairwell near Cafeteria/Kitchen to Boiler Room	Ceiling	Flaking	200	N	N	0	Y - 28 SF Ductwork	N	Entire Ceiling; Including ACPI, FGPI
251	2520	1	0	H03	Circulation (Hallway)	Hallway from Stairwell near Cafeteria/Kitchen to Boiler Room	W1	Flaking	20	N	N	0	N	N	4 Locations
252	2520	1	0	H03	Circulation (Hallway)	Hallway from Stairwell near Cafeteria/Kitchen to Boiler Room	W2	Flaking	32	N	N	0	N	N	
253	2520	1	0	H03	Circulation (Hallway)	Hallway from Stairwell near Cafeteria/Kitchen to Boiler Room	W3	Flaking	70	N	N	0	N	N	4 Locations
254	2520	1	0	H03	Circulation (Hallway)	Hallway from Stairwell near Cafeteria/Kitchen to Boiler Room	W4	Flaking	10	N	N	0	N	N	3 Locations
255	2520	1	0	016	IMC (Library)	Library	W1	Cracking	8	N	N	0	Y - 60 SF Bookcases	N	
256	2520	1	0	016	IMC (Library)	Library	W2	Flaking	2	N	N	0	Y - 120 SF Bookcases, Contents	N	2 Locations; Including Metal Pipe
257	2520	1	0	016	IMC (Library)	Library	W3	Flaking	4	N	N	0	Y - 90 SF Bookcases, Desks	N	Flaking @ Radiator by Window 2
258	2520	1	0	016	IMC (Library)	Library	W4	Cracking	4	N	N	0	Y - 88 SF Bookcases	N	
259	2520	1	0	016A	Storage	Library Storage Closet	Ceiling	Partially Inaccessible	0	N	N	0	Y - 45 SF Ductwork	N	
260	2520	1	0	016A	Storage	Library Storage Closet	W1	Partially Inaccessible	0	N	N	0	Y - 150 SF Shelves	N	
261	2520	1	0	016A	Storage	Library Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves	N	
262	2520	1	0	016A	Storage	Library Storage Closet	W3	Cracking	16	N	N	0	Y - 200 SF Shelves	N	
263	2520	1	0	016A	Storage	Library Storage Closet	W4	Flaking	10	N	N	0	Y - 20 SF Contents	N	Flaking on Metal Pipe
264	2520	1	0	019	Cafeteria	Smaller Cafeteria - Room 15 (next to Boiler Room)	Floors	Chipping	36	N	N	0	N	N	

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
265	2520	1	0	019	Cafeteria	Smaller Cafeteria - Room 15 (next to Boiler Room)	W1	Partially Inaccessible	0	N	N	0	Y - 120 SF Cabinets, Oven, Sink	N	
266	2520	1	0	019	Cafeteria	Smaller Cafeteria - Room 15 (next to Boiler Room)	W2	Flaking	21	N	N	0	Y - 42 SF Lockers	N	Flaking on Door
267	2520	1	0	019	Cafeteria	Smaller Cafeteria - Room 15 (next to Boiler Room)	W3	Flaking	6	N	N	0	N	N	Flaking @ Radiator & Window 2
268	2520	1	0	S05	Stairs	Stairwell from Boys' Restroom	Ceiling	Flaking	9	N	N	0	N	N	
269	2520	1	0	S05	Stairs	Stairwell from Boys' Restroom	W1	Flaking	5	N	N	0	N	N	2 Locations
270	2520	1	0	S05	Stairs	Stairwell from Boys' Restroom	W2	Flaking	4	N	N	0	N	N	
271	2520	1	0	S2	Stairs	Stairwell near Cafeteria/Kitchen	Floors	Flaking	36	N	N	0	N	N	Entire Stairs; Additional Chipping
272	2520	1	0	S2	Stairs	Stairwell near Cafeteria/Kitchen	W3	Flaking	18	N	N	0	Y - 40 SF Posters	N	2 Locations; Additional Cracking
273	2520	1	0	S1	Stairs	Stairwell near IMC/Library	Floors	Flaking	30	N	N	0	N	N	Entire Stairs; Additional Chipping
274	2520	1	0	S1	Stairs	Stairwell near IMC/Library	W1	Cracking	4	N	N	0	N	N	2 Locations
275	2520	1	0	S1	Stairs	Stairwell near IMC/Library	W2	Flaking	12	N	N	0	N	N	Flaking @ Radiator
276	2520	1	0	S03	Stairs	Stairwell next to Gym Office	W3	Flaking	10	N	N	0	N	N	Additional Cracking; Damage Includes Door Frame
277	2520	1	0	020A	Storage	Storage Area next to Cafeteria/Kitchen	Floors	None	0	N	Y - 3 SF on Floor	3	N	N	
278	2520	1	0	020A	Storage	Storage Area next to Cafeteria/Kitchen	W2	Flaking	4	N	N	0	Y - 120 SF Boxes	N	Including Metal Pipe
279	2520	1	0	020A	Storage	Storage Area next to Cafeteria/Kitchen	W3	Flaking	12	Y	Y - 3 SF on Boxes	3	Y - 18 SF Contents	Y - 9 SF	2 Locations; Additional Efflorescence;
280	2520	1	0	020A	Storage	Storage Area next to Cafeteria/Kitchen	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Boxes	N	
281	2520	1	0	019A	Storage	Storage Closet in Smaller Cafeteria (Room 15)	Ceiling	Flaking	4	N	N	0	Y - 18 SF Ductwork	N	
282	2520	1	0	019A	Storage	Storage Closet in Smaller Cafeteria (Room 15)	W2	Flaking	60	N	N	0	Y - 36 SF Shelves	N	Entire Wall

