

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7200	1	3	307B	Student Restrooms - Male (4-12)	Boy's Restroom Next to Classroom 307	Ceiling	Cracking, Chipping	8	No	No	N/A	N/A	No	
2	7200	1	3	300	Primary	Classroom 300	Ceiling	Spalling above windows	3	Yes	No	N/A	Cabinets, Shelves	Yes	
3	7200	1	3	300	Primary	Classroom 300	W1	Cracking, Chipping, Flaking	88	No	No	N/A	Table, Chairs	No	
4	7200	1	3	300	Primary	Classroom 300	W2	Cracking, Flaking	32	No	No	N/A	Crates, Shelves	No	Limited inspection due to shelves and stored materials
5	7200	1	3	300	Primary	Classroom 300	W3	Flaking, Efflorescence	4	Yes	No	N/A	Cabinets, Shelves	Yes	Limited inspection due to shelves and stored materials
6	7200	1	3	300	Primary	Classroom 300	W4	Cracking, Flaking in air shaft	33	No	No	N/A	Posters	No	
7	7200	1	3	300B	Storage	Classroom 300 Closet	W1	Cracking, Coat hooks pulling off wall	21	No	No	N/A	N/A	Yes	
8	7200	1	3	300B	Storage	Classroom 300 Closet	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
9	7200	1	3	300B	Storage	Classroom 300 Closet	W3	Cracking, Coat hooks pulling off wall	15	No	No	N/A	N/A	Yes	
10	7200	1	3	300B	Storage	Classroom 300 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
11	7200	1	3	301	Primary	Classroom 301	W1	Cracking	1	No	No	N/A	N/A	No	
12	7200	1	3	301	Primary	Classroom 301	W2	Cracking	2	No	No	N/A	N/A	No	
13	7200	1	3	301	Primary	Classroom 301	W3	Flaking behind radiator and cover	10	No	Debris and paint chips on windowsills	1	N/A	No	
14	7200	1	3	301	Primary	Classroom 301	W4	Cracking	10	No	No	N/A	N/A	No	
15	7200	1	3	301A	Storage	Classroom 301 Storage Closet	Ceiling	Cracking	10	No	No	N/A	N/A	Yes	
16	7200	1	3	301A	Storage	Classroom 301 Storage Closet	W2	Cracking, Chipping, Coat hooks pulling off wall	25	No	No	N/A	N/A	Yes	
17	7200	1	3	301A	Storage	Classroom 301 Storage Closet	W3	Cracking, Flaking behind radiator and cover	9	No	No	N/A	N/A	Yes	
18	7200	1	3	301A	Storage	Classroom 301 Storage Closet	W4	Cracking, Coat hooks pulling off wall	30	No	Debris on coat hooks	1	N/A	Yes	
19	7200	1	3	302	Primary	Classroom 302	W1	Cracking, Flaking	28	No	No	N/A	Posters	No	
20	7200	1	3	302	Primary	Classroom 302	W2	Cracking	25	No	No	N/A	Posters, Shelf	No	
21	7200	1	3	302	Primary	Classroom 302	W3	Flaking behind radiator and cover	10	No	No	N/A	Shelves	No	
22	7200	1	3	302	Primary	Classroom 302	W4	Cracking	25	No	No	N/A	N/A	No	
23	7200	1	3	302A	Storage	Classroom 302 Closet	Ceiling	Flaking	15	No	No	N/A	Shelves with stored materials	No	
24	7200	1	3	302A	Storage	Classroom 302 Closet	Floor	N/A	N/A	No	No	N/A	Shelves with stored materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
25	7200	1	3	302A	Storage	Classroom 302 Closet	W1	Cracking, Hole, paint has been stabilized	1	No	No	N/A	Shelves with stored materials	Yes	
26	7200	1	3	302A	Storage	Classroom 302 Closet	W2	Coat hooks pulling off wall	15	No	No	N/A	Shelves with stored materials	Yes	
27	7200	1	3	302A	Storage	Classroom 302 Closet	W3	Cracking	10	No	No	N/A	Shelves with stored materials	No	
28	7200	1	3	302A	Storage	Classroom 302 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	39	No	No	N/A	Shelves with stored materials	Yes	
29	7200	1	3	303	Primary	Classroom 303	Ceiling	Flaking above windows	1	No	No	N/A	N/A	No	
30	7200	1	3	303	Primary	Classroom 303	W1	Chipping, Hole, Flaking	5	No	No	N/A	N/A	Yes	
31	7200	1	3	303	Primary	Classroom 303	W3	Cracking, Staple Holes, Flaking behind radiator	30	No	No	N/A	N/A	Yes	
32	7200	1	3	303	Primary	Classroom 303	W4	Cracking	15	No	No	N/A	N/A	No	
33	7200	1	3	303A	Storage	Classroom 303 Closet	Ceiling	Cracking	15	No	No	N/A	N/A	No	
34	7200	1	3	303A	Storage	Classroom 303 Closet	Floor	N/A	N/A	No	Paint chips near radiator	1	N/A	No	
35	7200	1	3	303A	Storage	Classroom 303 Closet	W2	Cracking, Flaking	51	No	No	N/A	Shirts	No	
36	7200	1	3	303A	Storage	Classroom 303 Closet	W3	Flaking behind radiator and cover	2	No	No	N/A	N/A	No	
37	7200	1	3	303A	Storage	Classroom 303 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	41	No	No	N/A	Shirts, Posters	Yes	
38	7200	1	3	304	Primary	Classroom 304	Floor	N/A	N/A	No	Paint chips in corner of walls 2&3	1	N/A	No	
39	7200	1	3	304	Primary	Classroom 304	W1	N/A	N/A	No	No	N/A	Posters	No	Limited inspection
40	7200	1	3	304	Primary	Classroom 304	W3	Flaking behind radiator and cover	10	No	No	N/A	Cabinets, Posters	No	Limited inspection
41	7200	1	3	304	Primary	Classroom 304	W4	Cracking, Chipping, Flaking	21	No	No	N/A	Furniture, Posters	No	Limited inspection
42	7200	1	3	304A	Storage	Classroom 304 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
43	7200	1	3	304A	Storage	Classroom 304 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
44	7200	1	3	304A	Storage	Classroom 304 Closet	W1	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
45	7200	1	3	304A	Storage	Classroom 304 Closet	W2	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
46	7200	1	3	304A	Storage	Classroom 304 Closet	W3	Cracking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
47	7200	1	3	304A	Storage	Classroom 304 Closet	W4	Cracking, Coat hooks pulling off wall	20	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
48	7200	1	3	305	Primary	Classroom 305	Ceiling	Flaking above windows	1	No	No	N/A	N/A	No	
49	7200	1	3	305	Primary	Classroom 305	W1	Cracking, Chipping, Flaking	38	No	No	N/A	N/A	No	
50	7200	1	3	305	Primary	Classroom 305	W3	Cracking, Chipping, Flaking, some behind radiator, Significant Moisture Damage	38	Yes	No	N/A	N/A	No	
51	7200	1	3	305	Primary	Classroom 305	W4	Cracking	20	No	No	N/A	N/A	No	
52	7200	1	3	305A	Storage	Classroom 305 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
53	7200	1	3	305A	Storage	Classroom 305 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
54	7200	1	3	305A	Storage	Classroom 305 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
55	7200	1	3	305A	Storage	Classroom 305 Closet	W2	Cracking, Chipping, Hole, paint has been stabilized, Coat hooks pulling off wall	17	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
56	7200	1	3	305A	Storage	Classroom 305 Closet	W3	Cracking, Chipping, Flaking	14	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
57	7200	1	3	305A	Storage	Classroom 305 Closet	W4	Cracking, Chipping, Flaking, Coat hooks pulling off wall	63	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
58	7200	1	3	306	Primary	Classroom 306	W1	Cracking in air shaft, Chipping, Flaking, some in air shaft, Hole	8	No	No	N/A	N/A	Yes	
59	7200	1	3	306	Primary	Classroom 306	W3	Cracking, chipping, flaking	16	No	No	N/A	N/A	No	
60	7200	1	3	306	Primary	Classroom 306	W4	Wood trim missing	<1	No	No	N/A	N/A	Yes	
61	7200	1	3	306A	Storage	Classroom 306 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
62	7200	1	3	306A	Storage	Classroom 306 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
63	7200	1	3	306A	Storage	Classroom 306 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
64	7200	1	3	306A	Storage	Classroom 306 Closet	W2	Flaking, Coat hooks pulling off wall	25	No	No	N/A	Stored Materials	Yes	Limited inspection in back half of closet due to stored materials
65	7200	1	3	306A	Storage	Classroom 306 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
66	7200	1	3	306A	Storage	Classroom 306 Closet	W4	Chipping, Coat hooks pulling off wall	25	No	No	N/A	Stored Materials	Yes	Limited inspection in back half of closet due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
67	7200	1	3	307	Primary	Classroom 307	W1	Cracking, Chipping, Holes	15	No	No	N/A	Desks, Stored Materials	Yes	
68	7200	1	3	307	Primary	Classroom 307	W2	Cracking	3	No	No	N/A	N/A	No	
69	7200	1	3	307	Primary	Classroom 307	W3	Flaking behind radiator and cover	10	No	No	N/A	N/A	No	
70	7200	1	3	307A	Storage	Classroom 307 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
71	7200	1	3	307A	Storage	Classroom 307 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	
72	7200	1	3	307A	Storage	Classroom 307 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
73	7200	1	3	307A	Storage	Classroom 307 Closet	W2	Chipping, Holes, Flaking	10	No	No	N/A	Stored Materials	Yes	Limited inspection in back half of closet due to stored materials
74	7200	1	3	307A	Storage	Classroom 307 Closet	W3	Cracking	5	No	No	N/A	Stored Materials	No	Limited inspection in back half of closet due to stored materials
75	7200	1	3	307A	Storage	Classroom 307 Closet	W4	Cracking, Chipping, Flaking, Coat hooks pulling off wall	21	No	No	N/A	Stored Materials	Yes	Limited inspection in back half of closet due to stored materials
76	7200	1	3	308	Primary	Classroom 308	Ceiling	Flaking above windows	3	No	No	N/A	N/A	No	
77	7200	1	3	308	Primary	Classroom 308	W1	Cracking, Chipping	29	No	No	N/A	Posters	No	
78	7200	1	3	308	Primary	Classroom 308	W2	Cracking, Chipping, Staple Holes	33	No	No	N/A	Furniture, Posters	Yes	
79	7200	1	3	308	Primary	Classroom 308	W3	Flaking, Efflorescence behind radiators and covers	20	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
80	7200	1	3	308	Primary	Classroom 308	W4	Flaking	1	No	No	N/A	N/A	No	
81	7200	1	3	308A	Storage	Classroom 308 Closet	Ceiling	Cracking, Efflorescence, Significant Moisture Damage	15	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to stored materials
82	7200	1	3	308A	Storage	Classroom 308 Closet	Floor	N/A	N/A	No	Paint chips by wall 4 door	3	Cabinets, Shelves, Stored Materials	No	Limited inspection due to stored materials
83	7200	1	3	308A	Storage	Classroom 308 Closet	W1	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
84	7200	1	3	308A	Storage	Classroom 308 Closet	W2	Flaking, Efflorescence, Coat hooks pulling off wall	27	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to stored materials
85	7200	1	3	308A	Storage	Classroom 308 Closet	W3	Cracking, Efflorescence	16	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to stored materials
86	7200	1	3	308A	Storage	Classroom 308 Closet	W4	Holes, Flaking	10	No	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to stored materials
87	7200	1	3	309	Primary	Classroom 309	W1	Cracking, Chipping	22	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
88	7200	1	3	309	Primary	Classroom 309	W2	Cracking	25	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
89	7200	1	3	309	Primary	Classroom 309	W3	Chipping	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
90	7200	1	3	309	Primary	Classroom 309	W4	Cracking, Chipping	52	No	No	N/A	N/A	No	
91	7200	1	3	309A	Storage	Classroom 309 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	No access to back half of closet due to stored materials
92	7200	1	3	309A	Storage	Classroom 309 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	No access to back half of closet due to stored materials
93	7200	1	3	309A	Storage	Classroom 309 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
94	7200	1	3	309A	Storage	Classroom 309 Closet	W2	Cracking	2	No	No	N/A	Stored Materials	No	No access to back half of closet due to stored materials
95	7200	1	3	309A	Storage	Classroom 309 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	No access to back half of closet due to stored materials
96	7200	1	3	309A	Storage	Classroom 309 Closet	W4	Cracking, Coat hooks pulling off wall	55	No	No	N/A	Stored Materials	Yes	No access to back half of closet due to stored materials
97	7200	1	3	310	Primary	Classroom 310	Ceiling	N/A	N/A	No	No	N/A	Posters, Shelves, Stored Materials	No	
98	7200	1	3	310	Primary	Classroom 310	Floor	N/A	N/A	No	No	N/A	Posters, Shelves, Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
99	7200	1	3	310	Primary	Classroom 310	W1	N/A	N/A	No	No	N/A	Posters, Shelves, Stored Materials	No	
100	7200	1	3	310	Primary	Classroom 310	W2	N/A	N/A	No	No	N/A	Posters, Shelves, Stored Materials	No	
101	7200	1	3	310	Primary	Classroom 310	W3	Holes, paint has been stabilized, Efflorescence behind radiator and cover	12	Yes	No	N/A	Posters, Shelves, Stored Materials	Yes	
102	7200	1	3	310	Primary	Classroom 310	W4	Cracking, Chipping	4	No	No	N/A	Posters, Shelves, Stored Materials	No	
103	7200	1	3	310A	Storage	Classroom 310 Large Closet	Ceiling	Flaking	N/A	No	No	N/A	N/A	No	
104	7200	1	3	310A	Storage	Classroom 310 Large Closet	W2	Chipping, Hole, paint has been stabilized, Coat hooks pulling off wall	7	No	No	N/A	N/A	Yes	
105	7200	1	3	310A	Storage	Classroom 310 Large Closet	W3	Flaking on wall and metal pipe	3	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to Cabinet and stored materials
106	7200	1	3	311	Primary	Classroom 311	W1	Cracking, Chipping	7	No	No	N/A	N/A	No	
107	7200	1	3	311	Primary	Classroom 311	W3	Cracking, Chipping, Holes, Flaking behind radiator	19	No	No	N/A	Shelves, Instruments, Furniture	Yes	Limited inspection due to shelves and stored materials
108	7200	1	3	311	Primary	Classroom 311	W4	Chipping	1	No	No	N/A	N/A	No	
109	7200	1	3	311A	Storage	Classroom 311 Large Closet	Ceiling	N/A	N/A	No	No	N/A	Instruments	No	
110	7200	1	3	311A	Storage	Classroom 311 Large Closet	Floor	N/A	N/A	No	No	N/A	Instruments	No	
111	7200	1	3	311A	Storage	Classroom 311 Large Closet	W1	Cracking, Flaking	8	No	No	N/A	Instruments	No	
112	7200	1	3	311A	Storage	Classroom 311 Large Closet	W2	Flaking	1	No	No	N/A	Instruments	No	
113	7200	1	3	311A	Storage	Classroom 311 Large Closet	W3	Chipping on radiator, Flaking on heat shield	10	No	No	N/A	Instruments	No	
114	7200	1	3	311A	Storage	Classroom 311 Large Closet	W4	Spalling	1	Yes	No	N/A	Instruments	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
115	7200	1	3	311B	Storage	Classroom 311 Small Closet	Ceiling	Cracking	2	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
116	7200	1	3	311B	Storage	Classroom 311 Small Closet	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
117	7200	1	3	311B	Storage	Classroom 311 Small Closet	W1	Cracking	10	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
118	7200	1	3	311B	Storage	Classroom 311 Small Closet	W2	Cracking	10	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
119	7200	1	3	311B	Storage	Classroom 311 Small Closet	W3	Cracking	50	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
120	7200	1	3	311B	Storage	Classroom 311 Small Closet	W4	Cracking	50	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
121	7200	1	3	312	Primary	Classroom 312	Ceiling	N/A	N/A	No	No	N/A	Furniture, Stored materials	No	
122	7200	1	3	312	Primary	Classroom 312	Floor	N/A	N/A	No	No	N/A	Furniture, Stored materials	No	
123	7200	1	3	312	Primary	Classroom 312	W1	Cracking, Chipping, Holes, Flaking	9	No	No	N/A	Furniture, Stored materials	Yes	
124	7200	1	3	312	Primary	Classroom 312	W2	Cracking, Chipping, Flaking	4	No	No	N/A	Furniture, Stored materials	No	
125	7200	1	3	312	Primary	Classroom 312	W3	Flaking behind radiator and cover	10	No	No	N/A	Furniture, Stored materials	No	
126	7200	1	3	312	Primary	Classroom 312	W4	Cracking, Flaking	12	No	No	N/A	Furniture, Stored materials	No	
127	7200	1	3	312B	Storage	Classroom 312 Large Closet	Ceiling	Chipping, Hole	2	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
128	7200	1	3	312B	Storage	Classroom 312 Large Closet	W1	Cracking, Flaking on wall and metal pipe	15	No	Debris and paint chips on hooks	2	Shelves with stored materials	No	
129	7200	1	3	312B	Storage	Classroom 312 Large Closet	W2	Chipping, Flaking	13	No	No	N/A	N/A	No	
130	7200	1	3	312B	Storage	Classroom 312 Large Closet	W3	Cracking, Flaking behind radiator and cover	13	No	No	N/A	N/A	No	
131	7200	1	3	312D	Storage	Classroom 312 Small Closet	Ceiling	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
132	7200	1	3	312D	Storage	Classroom 312 Small Closet	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
133	7200	1	3	312D	Storage	Classroom 312 Small Closet	W1	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
134	7200	1	3	312D	Storage	Classroom 312 Small Closet	W2	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
135	7200	1	3	312D	Storage	Classroom 312 Small Closet	W3	Efflorescence	50	Yes	Debris on shelves and stored materials	20	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
136	7200	1	3	312D	Storage	Classroom 312 Small Closet	W4	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
137	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	Ceiling	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
138	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
139	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	W1	Gouges	2	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	W2	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
141	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	W3	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
142	7200	1	3	H314A	Storage	Closet adjacent to Classroom 311	W4	Cracking, Chipping	3	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
143	7200	1	3	300A	Storage	ESOL Classroom 300A	Ceiling	Flaking above missing ceiling tiles	40	No	No	N/A	N/A	No	
144	7200	1	3	300A	Storage	ESOL Classroom 300A	W1	Cracking	<1	No	No	N/A	N/A	No	
145	7200	1	3	300A	Storage	ESOL Classroom 300A	W2	Cracking	25	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
146	7200	1	3	300A	Storage	ESOL Classroom 300A	W3	Cracking behind radiator, Efflorescence	10	Yes	No	N/A	Paintings	Yes	
147	7200	1	3	300A	Storage	ESOL Classroom 300A	W4	Cracking, Chipping, Holes	20	No	No	N/A	Paintings, Posters	Yes	
148	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	Ceiling	Flaking	420	No	No	N/A	N/A	No	
149	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	Floor	Chipping on stairs and railings	90	No	No	N/A	N/A	No	
150	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	W1	Flaking	200	No	No	N/A	N/A	No	
151	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	W2	Chipping on door, Flaking	205	No	No	N/A	N/A	No	
152	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	W3	Flaking on wall, bars, and window frames	100	No	No	N/A	N/A	No	
153	7200	1	3	S31	Stairs	Fire Tower across from Classroom 307	W4	Chipping on door, Flaking	60	No	No	N/A	N/A	No	
154	7200	1	3	303B	Restroom	Girl's Restroom adjacent to Classroom 304	Ceiling	Spalling	2	Yes	No	N/A	N/A	Yes	
155	7200	1	3	H311	Circulation (Hallway)	Hallway outside Classrooms 300-303	Floor	Chipping floor and cove	40	No	No	N/A	N/A	No	
156	7200	1	3	H311	Circulation (Hallway)	Hallway outside Classrooms 300-303	W1	Chipping	2	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
157	7200	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 304-307	Ceiling	Efflorescence, Significant Moisture Damage above windows	20	Yes	No	N/A	N/A	Yes	
158	7200	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 304-307	Floor	Chipping floor and cove	19	No	No	N/A	N/A	No	
159	7200	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 304-307	W1	Cracking, Flaking behind radiator and cover	12	No	No		N/A	No	
160	7200	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 304-307	W3	Flaking, some behind radiators and covers	17	No	Debris on windowsills	6	N/A	No	
161	7200	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 308-310	Ceiling	Flaking, Efflorescence above windows	4	Yes	No	N/A	N/A	No	
162	7200	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 308-310	Floor	Chipping floor and cove	15	No	No	N/A	N/A	No	
163	7200	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 308-310	W1	Chipping	1	No	No	N/A	N/A	No	
164	7200	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 308-310	W2	Cracking behind radiator and cover, Flaking	7	No	No	N/A	N/A	No	
165	7200	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 308-310	W4	Cracking, Flaking	3	No	No	N/A	N/A	No	
166	7200	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 311-312	Ceiling	Cracking	3	No	No	N/A	N/A	No	
167	7200	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 311-312	W1	Cracking, Chipping	17	No	No	N/A	N/A	Yes	
168	7200	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 311-312	W4	Cracking	2	No	No	N/A	N/A	No	
169	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	Ceiling	Cracking	5	No	No	N/A	N/A	No	
170	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	Floor	Chipping on floor, stairs, cove and railings	93	No	No	N/A	N/A	No	
171	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	W1	Significant Moisture Damage behind radiator and cover	20	Yes	No	N/A	N/A	Yes	
172	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	W2	Cracking	3	No	No	N/A	N/A	No	
173	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	W3	Chipping, Flaking	7	No	No	N/A	N/A	No	
174	7200	1	3	S323	Stairs	Stairwell adjacent to Classroom 303	W4	Cracking, Flaking	28	No	No	N/A	N/A	No	
175	7200	1	3	S322	Stairs	Stairwell adjacent to Classroom 308	Floor	Chipping on stairs and railings	46	No	No	N/A	N/A	No	
176	7200	1	3	S322	Stairs	Stairwell adjacent to Classroom 308	W1	Flaking, some behind radiator and cover	27	No	No	N/A	N/A	No	
177	7200	1	3	S322	Stairs	Stairwell adjacent to Classroom 308	W2	Flaking	10	No	No	N/A	N/A	No	
178	7200	1	3	S322	Stairs	Stairwell adjacent to Classroom 308	W3	Chipping, Flaking	11	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
179	7200	1	3	S322	Stairs	Stairwell adjacent to Classroom 308	W4	Flaking	10	No	No	N/A	N/A	No	
180	7200	1	3	312A	Primary	Storage Room 312A	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	
181	7200	1	3	312A	Primary	Storage Room 312A	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	
182	7200	1	3	312A	Primary	Storage Room 312A	W1	Cracking, Flaking	6	No	No	N/A	Stored Materials	Yes	
183	7200	1	3	312A	Primary	Storage Room 312A	W2	Flaking	5	No	No	N/A	Stored Materials	No	
184	7200	1	3	312A	Primary	Storage Room 312A	W3	Cracking, Chipping	3	No	No	N/A	Stored Materials	No	
185	7200	1	3	312A	Primary	Storage Room 312A	W4	Chipping, Flaking on and behind radiator cover, Efflorescence	24	Yes	No	N/A	Stored Materials	Yes	
186	7200	1	3	313	Storage	Storage Room across from Classroom 306	W2	Hole, Flaking behind radiator, Efflorescence	7	Yes	Debris on outlets	1	N/A	Yes	
187	7200	1	2	206B	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 206	Ceiling	Hole, Efflorescence	2	Yes	No	N/A	N/A	Yes	
188	7200	1	2	203	Primary	Classroom 203	Ceiling	Flaking, Efflorescence above windows	2	Yes	No	N/A	N/A	Yes	
189	7200	1	2	203	Primary	Classroom 203	W1	Chipping, Hole painted over	11	No	No	N/A	Furniture, Posters	Yes	
190	7200	1	2	203	Primary	Classroom 203	W3	Flaking behind radiator and cover	20	No	No	N/A	N/A	No	
191	7200	1	2	203	Primary	Classroom 203	W4	Chipping, Efflorescence	8	Yes	No	N/A	N/A	Yes	Source of moisture is leak from adjacent restroom. Leak and wall have reportedly been repaired but issue is returning.
192	7200	1	2	203A	Storage	Classroom 203 Closet	Ceiling	Cracking, Flaking	9	No	No	N/A	N/A	No	
193	7200	1	2	203A	Storage	Classroom 203 Closet	W2	Hole	1	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
194	7200	1	2	203A	Storage	Classroom 203 Closet	W3	Cracking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
195	7200	1	2	203A	Storage	Classroom 203 Closet	W4	Cracking, Chipping, Flaking	64	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
196	7200	1	2	200	Primary	Classroom 200	W1	Chipping, Gouge, Flaking	5	No	No	N/A	Posters	No	
197	7200	1	2	200	Primary	Classroom 200	W2	Cracking, Chipping. Limited inspection due to stored materials.	7	No	No	N/A	Shelves with stored materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
198	7200	1	2	200	Primary	Classroom 200	W3	Holes, Flaking, Efflorescence	6	Yes	Debris on radiator inside cover	3	Shelves with stored materials	Yes	
199	7200	1	2	200	Primary	Classroom 200	W4	Flaking on wall and metal pipe	20	No	No	N/A	Posters, Shelves with stored materials	No	
200	7200	1	2	200A	Storage	Classroom 200 Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials
201	7200	1	2	200A	Storage	Classroom 200 Closet	W1	Flaking	2	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials
202	7200	1	2	200A	Storage	Classroom 200 Closet	W2	Cracking, Chipping	30	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials
203	7200	1	2	200A	Storage	Classroom 200 Closet	W3	Chipping on metal jacket, Flaking on ACM pipe, Flaking behind radiator and cover	8	No	Debris on windowsill	2	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials
204	7200	1	2	200A	Storage	Classroom 200 Closet	W4	Cracking	25	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials
205	7200	1	2	201	Primary	Classroom 201	Ceiling	Efflorescence above windows	1	Yes	No	N/A	N/A	Yes	
206	7200	1	2	201	Primary	Classroom 201	W1	Cracking, Flaking	6	No	No	N/A	Posters	No	
207	7200	1	2	201	Primary	Classroom 201	W2	Flaking	3	No	No	N/A	Posters, Shelves, and Stored Materials	No	Limited inspection due to posters, shelves, and stored materials
208	7200	1	2	201	Primary	Classroom 201	W3	Efflorescence	3	Yes	Debris and paint chips on windowsill and around ACM Pipe	2	Posters, Shelves, and Stored Materials	Yes	
209	7200	1	2	201	Primary	Classroom 201	W4	N/A	N/A	No	No	N/A	Posters, Shelves, and Stored Materials	No	
210	7200	1	2	201A	Storage	Classroom 201 Closet	Ceiling	Flaking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
211	7200	1	2	201A	Storage	Classroom 201 Closet	W2	Chipping, Flaking	11	No	No	N/A	Cabinet, Shelves, Stored Materials	No	
212	7200	1	2	201A	Storage	Classroom 201 Closet	W3	Flaking	1	No	No	N/A	N/A	No	
213	7200	1	2	201A	Storage	Classroom 201 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	22	No	No	N/A	N/A	Yes	
214	7200	1	2	202	Primary	Classroom 202	Ceiling	Flaking	4	No	No	N/A	N/A	No	
215	7200	1	2	202	Primary	Classroom 202	W1	Flaking in air shaft, Staples all along wall	1	No	No	N/A	N/A	Yes	Plastering needed only if staples are removed
216	7200	1	2	202	Primary	Classroom 202	W3	Flaking behind radiators and covers	30	No	No	N/A	N/A	No	
217	7200	1	2	202A	Storage	Classroom 202 Closet	Floor	N/A	N/A	No	Paint chips in corner of walls 1&4	1	N/A	No	
218	7200	1	2	202A	Storage	Classroom 202 Closet	W2	Coat hooks pulling off wall	1	No	No	N/A	Stored Materials	No	
219	7200	1	2	202A	Storage	Classroom 202 Closet	W4	Cracking, Coat hooks pulling off wall	15	No	No	N/A	N/A	No	
220	7200	1	2	204	Primary	Classroom 204	Floor	N/A	N/A	No	Debris below efflorescence	1	N/A	No	
221	7200	1	2	204	Primary	Classroom 204	W1	Cracking in air shaft, Chipping, Flaking	3	No	No	N/A	N/A	No	
222	7200	1	2	204	Primary	Classroom 204	W3	Efflorescence behind pipe	<1	Yes	No	N/A	N/A	Yes	
223	7200	1	2	204A	Storage	Classroom 204 Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	
224	7200	1	2	204A	Storage	Classroom 204 Closet	W2	Cracking, Hole, Flaking	13	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to shelves with stored materials
225	7200	1	2	204A	Storage	Classroom 204 Closet	W3	Chipping	1	No	No	N/A	Cabinet	No	Limited inspection due to cabinet
226	7200	1	2	204A	Storage	Classroom 204 Closet	W4	Cracking	100	No	No	N/A	N/A	No	
227	7200	1	2	205	Primary	Classroom 205	Ceiling	Spalling, Efflorescence	10	Yes	No	N/A	N/A	Yes	
228	7200	1	2	205	Primary	Classroom 205	Floor	N/A	N/A	No	Paint chips in corner of walls 2&3	5	N/A	No	
229	7200	1	2	205	Primary	Classroom 205	W1	Cracking, Chipping, Flaking	28	No	No	N/A	N/A	No	
230	7200	1	2	205	Primary	Classroom 205	W3	Chipping, Flaking, some behind radiator and cover	26	No	No	N/A	N/A	No	
231	7200	1	2	205	Primary	Classroom 205	W4	Cracking	5	No	No	N/A	N/A	No	
232	7200	1	2	205A	Storage	Classroom 205 Closet	Floor	N/A	N/A	No	Paint chips scattered throughout	5	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
233	7200	1	2	205A	Storage	Classroom 205 Closet	W2	Holes	4	No	Debris on coat hooks	10	Shelves, Telecommunication Equipment	Yes	Limited inspection due to shelves and telecommunication equipment
234	7200	1	2	205A	Storage	Classroom 205 Closet	W3	Cracking, Holes, Flaking	9	No	No	N/A	N/A	Yes	
235	7200	1	2	205A	Storage	Classroom 205 Closet	W4	Cracking, Flaking	30	No	No	N/A	N/A	No	
236	7200	1	2	206	Primary	Classroom 206	Floor	N/A	N/A	No	Paint chips in corner of walls 2&3	1	N/A	No	
237	7200	1	2	206	Primary	Classroom 206	W1	Flaking	1	No	No	N/A	N/A	No	
238	7200	1	2	206	Primary	Classroom 206	W2	Spalling	1	Yes	No	N/A	Shelves, Stored Materials	Yes	
239	7200	1	2	206	Primary	Classroom 206	W3	Flaking behind radiator and cover	3	No	Paint chips on windowsill	1	N/A	No	
240	7200	1	2	206A	Storage	Classroom 206 Closet	W2	Hole, Flaking, Coat hooks pulling off wall	8	No	No	N/A	N/A	Yes	
241	7200	1	2	206A	Storage	Classroom 206 Closet	W3	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
242	7200	1	2	206A	Storage	Classroom 206 Closet	W4	Coat hooks pulling off wall	5	No	Paint chips on frame above door	2	N/A	Yes	
243	7200	1	2	207	Primary	Classroom 207	Ceiling	Efflorescence above windows	5	Yes	No	N/A	N/A	Yes	
244	7200	1	2	207	Primary	Classroom 207	W1	Efflorescence	1	Yes	No	N/A	N/A	Yes	
245	7200	1	2	207	Primary	Classroom 207	W2	Cracking	5	No	No	N/A	N/A	No	
246	7200	1	2	207	Primary	Classroom 207	W3	Flaking behind radiators and covers	20	No	Debris on windowsills and inside middle radiator cover	7	N/A	No	
247	7200	1	2	207A	Storage	Classroom 207 Closet	Ceiling	Cracking, Efflorescence	100	Yes	No	N/A	Cabinets, Shelves, and Stored Materials	Yes	Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.
248	7200	1	2	207A	Storage	Classroom 207 Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials. Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
249	7200	1	2	207A	Storage	Classroom 207 Closet	W1	Flaking	5	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials. Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.
250	7200	1	2	207A	Storage	Classroom 207 Closet	W2	Flaking, Efflorescence	105	Yes	No	N/A	Cabinets, Shelves, and Stored Materials	Yes	Limited inspection due to cabinets, shelves, and stored materials. Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.
251	7200	1	2	207A	Storage	Classroom 207 Closet	W3	Cracking, Efflorescence	10	Yes	No	N/A	Cabinets, Shelves, and Stored Materials	Yes	Limited inspection due to cabinets, shelves, and stored materials. Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.
252	7200	1	2	207A	Storage	Classroom 207 Closet	W4	Flaking	25	No	No	N/A	Cabinets, Shelves, and Stored Materials	No	Limited inspection due to cabinets, shelves, and stored materials. Reportedly nothing was able to be moved out of this closet when prior work was performed because of secure materials.
253	7200	1	2	208	Primary	Classroom 208	W1	Cracking, Chipping in air shaft, Holes	8	No	No	N/A	N/A	No	
254	7200	1	2	208	Primary	Classroom 208	W2	Cracking, Flaking	15	No	No	N/A	N/A	No	
255	7200	1	2	208	Primary	Classroom 208	W3	Flaking behind radiator and cover	20	No	Debris on windowsills	2	N/A	No	
256	7200	1	2	208	Primary	Classroom 208	W4	Chipping, Flaking	3	No	No	N/A	Shelves and books	No	
257	7200	1	2	208A	Storage	Classroom 208 Closet	Floor	N/A	N/A	No	Paint chips near wall 4 entrance	5	N/A	No	
258	7200	1	2	208A	Storage	Classroom 208 Closet	W2	Cracking	2	No	No	N/A	Cabinet, Stored Materials	Yes	
259	7200	1	2	208A	Storage	Classroom 208 Closet	W4	Cracking, Hole	26	No	No	N/A	N/A	No	
260	7200	1	2	209	Primary	Classroom 209	Ceiling	Flaking, Efflorescence above windows	4	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
261	7200	1	2	209	Primary	Classroom 209	W1	Cracking, Chipping in air shaft, Flaking	8	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
262	7200	1	2	209	Primary	Classroom 209	W2	Efflorescence	1	Yes	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
263	7200	1	2	209	Primary	Classroom 209	W3	Flaking, some behind radiator and cover, Efflorescence	24	Yes	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
264	7200	1	2	209	Primary	Classroom 209	W4	Chipping	1	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
265	7200	1	2	209A	Storage	Classroom 209 Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	
266	7200	1	2	209A	Storage	Classroom 209 Closet	W2	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Shelves, Stored Materials	No	
267	7200	1	2	209A	Storage	Classroom 209 Closet	W3	Flaking on wall and metal pipe, Efflorescence	18	Yes	No	N/A	Stored Materials	Yes	
268	7200	1	2	209A	Storage	Classroom 209 Closet	W4	Cracking, Flaking	22	No	No	N/A	Stored Materials	No	
269	7200	1	2	210	Primary	Classroom 210	W1	Chipping	2	No	No	N/A	Posters, Shelves	No	
270	7200	1	2	210	Primary	Classroom 210	W2	N/A	N/A	No	No	N/A	Posters, Shelves	No	
271	7200	1	2	210	Primary	Classroom 210	W3	Flaking behind radiator and cover	5	No	No	N/A	Posters, Shelves	No	
272	7200	1	2	210	Primary	Classroom 210	W4	N/A	N/A	No	No	N/A	Posters, Shelves	No	
273	7200	1	2	210A	Storage	Classroom 210 Large Closet	Ceiling	Hole, paint has been stabilized	1	No	No	N/A	N/A	No	
274	7200	1	2	210A	Storage	Classroom 210 Large Closet	W1	Holes	3	No	No	N/A	Shelves, Stored Materials	No	
275	7200	1	2	210A	Storage	Classroom 210 Large Closet	W2	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Shelves, Stored Materials	No	
276	7200	1	2	210A	Storage	Classroom 210 Large Closet	W3	Cracking, Chipping, Flaking on wall and radiator	9	No	No	N/A	Shelves, Stored Materials	No	
277	7200	1	2	210A	Storage	Classroom 210 Large Closet	W4	Cracking, Chipping	13	No	No	N/A	Shelves, Stored Materials	Yes	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
278	7200	1	2	210B	Storage	Classroom 210 Small Closet	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
279	7200	1	2	210B	Storage	Classroom 210 Small Closet	W1	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
280	7200	1	2	210B	Storage	Classroom 210 Small Closet	W2	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
281	7200	1	2	210B	Storage	Classroom 210 Small Closet	W3	Cracking, Flaking	30	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
282	7200	1	2	210B	Storage	Classroom 210 Small Closet	W4	Cracking, Flaking	30	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
283	7200	1	2	211	Primary	Classroom 211	Ceiling	Flaking, Efflorescence above windows	4	Yes	Debris on floor	2	Shelves, Stored Materials	Yes	
284	7200	1	2	211	Primary	Classroom 211	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	
285	7200	1	2	211	Primary	Classroom 211	W1	Chipping on cove	16	No	No	N/A	Shelves, Stored Materials	No	
286	7200	1	2	211	Primary	Classroom 211	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	
287	7200	1	2	211	Primary	Classroom 211	W3	Flaking behind radiator and cover	20	No	Debris on windowsills	2	Shelves, Stored Materials	No	
288	7200	1	2	211	Primary	Classroom 211	W4	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	
289	7200	1	2	211A	Storage	Classroom 211 Large Closet	W1	Chipping	2	No	No	N/A	N/A	No	
290	7200	1	2	211A	Storage	Classroom 211 Large Closet	W3	Flaking on radiator	10	No	Debris on windowsill	2	N/A	No	
291	7200	1	2	211A	Storage	Classroom 211 Large Closet	W4	Cracking	2	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
292	7200	1	2	211D	Storage	Classroom 211 Small Closet	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
293	7200	1	2	211D	Storage	Classroom 211 Small Closet	W1	Hole	1	No	No	N/A	N/A	Yes	Limited inspection due to shelves and stored materials
294	7200	1	2	211D	Storage	Classroom 211 Small Closet	W2	Cracking, Flaking	30	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
295	7200	1	2	211D	Storage	Classroom 211 Small Closet	W3	Flaking	50	No	Debris on shelves and stored materials	25	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
296	7200	1	2	211D	Storage	Classroom 211 Small Closet	W4	Flaking	5	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
297	7200	1	2	H27A	Storage	Closet at the End of the Hallway across from Office 211A	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
298	7200	1	2	H27A	Storage	Closet at the End of the Hallway across from Office 211A	W2	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
299	7200	1	2	H27A	Storage	Closet at the End of the Hallway across from Office 211A	W3	Cracking	5	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
300	7200	1	2	H27A	Storage	Closet at the End of the Hallway across from Office 211A	W4	Cracking, Flaking	12	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
301	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	Ceiling	Flaking	3	No	No	N/A	Stored Materials	No	
302	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	
303	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	W1	Chipping on wall and doorframe	6	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
304	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	W2	Chipping on metal duct, Flaking	7	No	No	N/A	Stored Materials	No	
305	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	W3	Chipping, Gouges	2	No	No	N/A	Stored Materials	Yes	
306	7200	1	2	213	Storage	Closet in Hallway across from Classroom 205	W4	Cracking	1	No	No	N/A	Stored Materials	No	
307	7200	1	2	200B	Primary	ESOL Class by Classroom 200	Floor	Chipping on cove and floor perimeter	37	No	No	N/A	Furniture, Stored Materials	No	
308	7200	1	2	200B	Primary	ESOL Class by Classroom 200	W1	Flaking on wood shelf	5	No	No	N/A	Furniture, Stored Materials	No	
309	7200	1	2	200B	Primary	ESOL Class by Classroom 200	W2	Flaking on metal pipe above fiberglass	1	No	Paint chips in corner of walls 2&3	1	Furniture, Stored Materials	No	
310	7200	1	2	200B	Primary	ESOL Class by Classroom 200	W3	Flaking on wall, Flaking on metal pipe above fiberglass, Efflorescence behind radiator and cover	9	Yes	Debris on windowsill	2	Furniture, Stored Materials	Yes	
311	7200	1	2	200B	Primary	ESOL Class by Classroom 200	W4	Significant moisture damage	15	Yes	Debris below damage	5	Furniture, Built in shelves, Stored Materials	Yes	
312	7200	1	2	216	Student Restrooms - Male/Female (Classroom)	Faculty Restroom adjacent to Teacher's Lounge	Ceiling	Flaking	2	No	No	N/A	N/A	No	
313	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	Ceiling	Flaking	150	No	No	N/A	N/A	No	
314	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	Floor	Chipping on stairs and railings	75	No	No	N/A	N/A	No	
315	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	W1	Chipping on door, Flaking	65	No	No	N/A	N/A	No	
316	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	W2	Flaking on wall and metal pipe	60	No	No	N/A	N/A	No	
317	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	W3	Flaking	75	No	No	N/A	N/A	No	
318	7200	1	2	S24	Stairs	Fire Tower across from Classroom 206	W4	Flaking on wall, window frame, and bars	115	No	No	N/A	N/A	No	
319	7200	1	2	H210	Circulation (Hallway)	Hallway in Front of Classroom 201	Floor	Chipping on cove and floor along walls 2,3,&4	14	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
320	7200	1	2	H210	Circulation (Hallway)	Hallway in Front of Classroom 201	W1	Chipping	1	No	No	N/A	N/A	No	
321	7200	1	2	H210	Circulation (Hallway)	Hallway in Front of Classroom 201	W3	Cracking behind cabinet	5	No	No	N/A	Cabinet	No	
322	7200	1	2	H210	Circulation (Hallway)	Hallway in Front of Classroom 201	W4	Missing wood trim	<1	No	No	N/A	N/A	No	
323	7200	1	2	H29	Circulation (Hallway)	Hallway in Front of Classroom 206	Floor	Chipping scattered along cove and floor	58	No	No	N/A	N/A	No	
324	7200	1	2	H29	Circulation (Hallway)	Hallway in Front of Classroom 206	W1	Cracking behind radiators and covers, Hole below water fountain, Flaking, Significant Moisture Damage behind radiator and cover	24	Yes	No	N/A	N/A	Yes	
325	7200	1	2	H29	Circulation (Hallway)	Hallway in Front of Classroom 206	W3	Cracking, some behind radiator and cover, Flaking, Spalling, Efflorescence	13	Yes	No	N/A	N/A	Yes	
326	7200	1	2	H28	Circulation (Hallway)	Hallway in Front of Classroom 208	Ceiling	Efflorescence above windows	3	Yes	No	N/A	N/A	Yes	
327	7200	1	2	H28	Circulation (Hallway)	Hallway in Front of Classroom 208	Floor	Chipping on cove and floor scattered along wall 2	17	No	No	N/A	N/A	No	
328	7200	1	2	H28	Circulation (Hallway)	Hallway in Front of Classroom 208	W2	Cracking, Flaking behind cabinet and radiator and cover	10	No	Debris on windowsill	1	Cabinets	No	Limited inspection behind cabinets
329	7200	1	2	H27	Circulation (Hallway)	Hallway in Front of Classroom 210	Floor	Chipping on cove and floor scattered along walls 1&4	13	No	No	N/A	N/A	No	
330	7200	1	2	H210A	Circulation (Hallway)	Hallway outside Faculty Restroom adjacent to Teacher's Lounge	W1	Flaking on doorframe	6	No	No	N/A	N/A	No	
331	7200	1	2	H210A	Circulation (Hallway)	Hallway outside Faculty Restroom adjacent to Teacher's Lounge	W3	Cracking, Chipping on doorframe	36	No	No	N/A	N/A	No	
332	7200	1	2	H210A	Circulation (Hallway)	Hallway outside Faculty Restroom adjacent to Teacher's Lounge	W4	Cracking, Chipping on wall, door, and frame, Flaking	18	No	No	N/A	N/A	No	
333	7200	1	2	211B	Primary	Office 211A	W2	Flaking	10	No	No	N/A	N/A	No	
334	7200	1	2	211B	Primary	Office 211A	W4	Cracking, Chipping, Efflorescence	7	Yes	No	N/A	N/A	Yes	
335	7200	1	2	212	Storage	Office across from Classroom 206	Ceiling	Cracking	10	No	No	N/A	N/A	No	
336	7200	1	2	212	Storage	Office across from Classroom 206	W2	Cracking behind radiator, Hole	6	No	No	N/A	N/A	Yes	
337	7200	1	2	212	Storage	Office across from Classroom 206	W3	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
338	7200	1	2	212	Storage	Office across from Classroom 206	W4	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	N/A	No	
339	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	Ceiling	Flaking, Significant Moisture Damage above windows	7	Yes	No	N/A	Furniture	Yes	
340	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	Floor	N/A	N/A	No	Debris along wall 3	5	Furniture	No	
341	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	W1	Chipping on both sides of door and frame, Flaking	11	No	No	N/A	Furniture	No	
342	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	W2	Flaking on windowsill and window frame	5	No	No	N/A	Furniture	No	
343	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	W3	Cracking, Flaking on wall, windowsills, and behind radiator and cover	30	No	Debris on windowsill and table	10	Furniture	No	
344	7200	1	2	215	Primary	Office adjacent to Teacher's Lounge	W4	Hole, paint has been stabilized, Flaking	6	No	No	N/A	Furniture	No	
345	7200	1	2	S23	Stairs	Stairwell near Classroom 202	Floor	Chipping on stairs and railings	65	No	No	N/A	N/A	No	
346	7200	1	2	S23	Stairs	Stairwell near Classroom 202	W1	Flaking on wall and wood radiator cover	15	No	No	N/A	N/A	No	
347	7200	1	2	S23	Stairs	Stairwell near Classroom 202	W3	Chipping on both sides of doors, Flaking	7	No	No	N/A	N/A	No	
348	7200	1	2	S22	Stairs	Stairwell next to Classroom 207	Floor	Chipping on stairs, cove, and railings, Flaking on stairs and cove	75	No	No	N/A	N/A	No	
349	7200	1	2	S22	Stairs	Stairwell next to Classroom 207	W2	Flaking	1	No	No	N/A	N/A	No	
350	7200	1	2	S22	Stairs	Stairwell next to Classroom 207	W3	Chipping, Flaking inside doorframe	20	No	No	N/A	N/A	No	
351	7200	1	2	S22	Stairs	Stairwell next to Classroom 207	W4	Cracking, Chipping	10	No	No	N/A	N/A	No	
352	7200	1	2	214	Administrative Office	Teacher's Lounge across from Classroom 201	Ceiling	Flaking above windows	4	No	No	N/A	N/A	No	
353	7200	1	2	214	Administrative Office	Teacher's Lounge across from Classroom 201	W2	Cracking, Hole, Flaking	12	No	No	N/A	N/A	Yes	
354	7200	1	2	214	Administrative Office	Teacher's Lounge across from Classroom 201	W3	Flaking behind radiator and cover, Spalling	15	Yes	No	N/A	N/A	Yes	
355	7200	1	2	214	Administrative Office	Teacher's Lounge across from Classroom 201	W4	Cracking, Flaking	4	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
356	7200	1	2	214A	Administrative Office	Teacher's Lounge across from Classroom 201 Kitchen	W2	Flaking, some behind radiator and cover	4	No	No	N/A	N/A	No	
357	7200	1	2	214A	Administrative Office	Teacher's Lounge across from Classroom 201 Kitchen	W3	Hole behind sink, Flaking	2	No	No	N/A	N/A	Yes	
358	7200	1	1	113	Auditorium	Auditorium	Ceiling	Cracking, Flaking	3	No	No	N/A	N/A	Yes	Ceiling is assumed asbestos
359	7200	1	1	113	Auditorium	Auditorium	Floor	N/A	N/A	No	Debris along walls 2&4	20	N/A	No	
360	7200	1	1	113	Auditorium	Auditorium	W2	Chipping on wall, doors, and frames, Efflorescence, some in decorative plaster	29	Yes	Debris on windowsills	4	N/A	Yes	
361	7200	1	1	113	Auditorium	Auditorium	W4	Chipping on wall, doors, and frames, Efflorescence, some in decorative plaster	42	Yes	Debris on windowsills	2	N/A	Yes	
362	7200	1	1	106B	Student Restrooms - Male (4-12)	Boy's Restroom near Classroom 107	Ceiling	Hole, Efflorescence	9	Yes	No	N/A	N/A	Yes	
363	7200	1	1	100	Primary	Classroom 100	Ceiling	Flaking above windows, Efflorescence near wall 4	10	Yes	No	N/A	N/A	Yes	
364	7200	1	1	100	Primary	Classroom 100	W1	Cracking, Flaking	21	No	No	N/A	N/A	No	
365	7200	1	1	100	Primary	Classroom 100	W2	Cracking, Flaking	15	No	No	N/A	N/A	No	
366	7200	1	1	100	Primary	Classroom 100	W3	Flaking, some behind radiator and cover, Efflorescence	30	Yes	Paint Chips on windowsills	1	N/A	Yes	
367	7200	1	1	100	Primary	Classroom 100	W4	Cracking, Chipping on built in wood benches	3	No	No	N/A	N/A	No	
368	7200	1	1	100B	Storage	Classroom 100 Coat Closet	W1	Flaking	<1	No	No	N/A	N/A	No	
369	7200	1	1	100B	Storage	Classroom 100 Coat Closet	W2	Chipping, Flaking, Coat hooks pulling off wall	17	No	No	N/A	N/A	Yes	
370	7200	1	1	100B	Storage	Classroom 100 Coat Closet	W3	Cracking	5	No	No	N/A	N/A	No	
371	7200	1	1	100B	Storage	Classroom 100 Coat Closet	W4	Chipping, Coat hooks pulling off wall	16	No	No	N/A	N/A	Yes	
372	7200	1	1	100A	Primary	Classroom 100 Restroom	Ceiling	Spalling, Efflorescence	7	Yes	No	N/A	N/A	Yes	
373	7200	1	1	101	Primary	Classroom 101	W1	Cracking, Chipping, Holes	17	No	No	N/A	N/A	Yes	
374	7200	1	1	101	Primary	Classroom 101	W2	Cracking, Flaking	8	No	No	N/A	Shelves, Stored Materials, Posters	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
375	7200	1	1	101	Primary	Classroom 101	W3	Flaking, some behind radiator and cover, Spalling	12	Yes	Debris on windowsills	2	Shelves, Stored Materials, Posters	Yes	
376	7200	1	1	101	Primary	Classroom 101	W4	N/A	N/A	No	No	N/A	Shelves, Stored Materials, Posters	No	
377	7200	1	1	101A	Storage	Classroom 101 Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
378	7200	1	1	101A	Storage	Classroom 101 Closet	W1	Cracking	1	No	No	N/A	N/A	No	
379	7200	1	1	101A	Storage	Classroom 101 Closet	W2	Cracking	5	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
380	7200	1	1	101A	Storage	Classroom 101 Closet	W3	Chipping	1	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
381	7200	1	1	101A	Storage	Classroom 101 Closet	W4	Cracking, Coat hooks pulling off wall	30	No	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to stored materials
382	7200	1	1	103	Primary	Classroom 103	Ceiling	Flaking, Efflorescence above windows	4	Yes	No	N/A	Shelves, Stored Materials	Yes	
383	7200	1	1	103	Primary	Classroom 103	W1	Chipping	25	No	No	N/A	Posters	No	
384	7200	1	1	103	Primary	Classroom 103	W3	Chipping, Flaking, some behind radiator and cover, Spalling	44	Yes	Debris on windowsills and inside radiator cover	13	Shelves, Stored Materials	Yes	
385	7200	1	1	103	Primary	Classroom 103	W4	Chipping	1	No	No	N/A	Shelves, Stored Materials	No	
386	7200	1	1	103A	Storage	Classroom 103 Coat Closet	Ceiling	Flaking on metal pipe	5	No	No	N/A	N/A	No	
387	7200	1	1	103A	Storage	Classroom 103 Coat Closet	W1	Hole	1	No	No	N/A	N/A	Yes	
388	7200	1	1	103A	Storage	Classroom 103 Coat Closet	W2	Cracking, Flaking	4	No	No	N/A	Shelves, Stored Materials	No	
389	7200	1	1	103A	Storage	Classroom 103 Coat Closet	W3	Flaking	1	No	No	N/A	Stored Materials	No	
390	7200	1	1	103A	Storage	Classroom 103 Coat Closet	W4	Cracking, Flaking	54	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
391	7200	1	1	107	Primary	Classroom 107	W1	Cracking, Spalling	11	Yes	No	N/A	Shelves, Stored Materials	Yes	
392	7200	1	1	107	Primary	Classroom 107	W2	Cracking, Flaking behind shelf	3	No	No	N/A	Shelves, Stored Materials	No	
393	7200	1	1	107	Primary	Classroom 107	W3	Flaking behind radiators and covers, Efflorescence	32	Yes	No	N/A	Stored Materials	Yes	
394	7200	1	1	107	Primary	Classroom 107	W4	Flaking behind file cabinet	1	No	No	N/A	File Cabinet, Stored Materials	No	
395	7200	1	1	107A	Storage	Classroom 107 Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	
396	7200	1	1	107A	Storage	Classroom 107 Closet	W2	Cracking, Flaking	25	No	No	N/A	N/A	No	
397	7200	1	1	107A	Storage	Classroom 107 Closet	W3	N/A	N/A	No	Debris inside radiator cover	2	N/A	No	
398	7200	1	1	107A	Storage	Classroom 107 Closet	W4	Cracking, Flaking	51	No	No	N/A	N/A	No	
399	7200	1	1	108	Primary	Classroom 108	Ceiling	Flaking, Efflorescence above windows	8	Yes	No	N/A	Shelves, Stored Materials	Yes	
400	7200	1	1	108	Primary	Classroom 108	Floor	N/A	N/A	No	Paint Chips near pipe and corner of walls 3&4	2	N/A	No	
401	7200	1	1	108	Primary	Classroom 108	W1	Cracking, Chipping, Holes, Spalling, Staple holes scattered throughout	30	Yes	No	N/A	Shelf	No	
402	7200	1	1	108	Primary	Classroom 108	W2	Cracking, Chipping	47	No	No	N/A	Cabinets, Stored Materials	Yes	
403	7200	1	1	108	Primary	Classroom 108	W3	Cracking, Chipping, Flaking	24	No	Paint Chips on windowsills	2	Shelves, Stored Materials	Yes	
404	7200	1	1	108	Primary	Classroom 108	W4	Cracking, Staple holes throughout	25	No	No	N/A	Shelves, Books	Yes	
405	7200	1	1	108A	Storage	Classroom 108 Closet	W2	Cracking	15	No	No	N/A	Cabinet, Shelves, Stored Materials	No	Limited inspection due to cabinet and shelves with stored materials
406	7200	1	1	108A	Storage	Classroom 108 Closet	W3	Cracking	5	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
407	7200	1	1	108A	Storage	Classroom 108 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	31	No	No	N/A	N/A	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
408	7200	1	1	109	Primary	Classroom 109	Ceiling	Spalling, Flaking, Efflorescence above windows	5	Yes	No	N/A	Shelves with stored materials	Yes	
409	7200	1	1	109	Primary	Classroom 109	Floor	N/A	N/A	No	No	N/A	Shelves with stored materials	No	
410	7200	1	1	109	Primary	Classroom 109	W1	Cracking, Chipping, Flaking, Staple holes scattered throughout	43	No	No	N/A	Shelves with stored materials	Yes	
411	7200	1	1	109	Primary	Classroom 109	W2	Cracking, Staple holes scattered throughout	10	No	No	N/A	Shelves with stored materials	Yes	
412	7200	1	1	109	Primary	Classroom 109	W3	Spalling, Flaking, some behind radiators and covers, Efflorescence behind radiator and cover	31	Yes	Debris inside radiator cover	12	Furniture, Stored Materials	Yes	
413	7200	1	1	109	Primary	Classroom 109	W4	Cracking, Flaking	11	No	No	N/A	Shelves, Stored Materials, Refrigerator	No	Limited inspection due to refrigerator and shelves with stored materials
414	7200	1	1	109A	Storage	Classroom 109 Closet	Ceiling	Cracking, Flaking	15	No	No	N/A	N/A	No	
415	7200	1	1	109A	Storage	Classroom 109 Closet	W1	Hole, paint has been stabilized	1	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to shelves with stored materials
416	7200	1	1	109A	Storage	Classroom 109 Closet	W2	Cracking, Chipping, Hole	41	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to shelves with stored materials
417	7200	1	1	109A	Storage	Classroom 109 Closet	W3	Flaking	10	No	No	N/A	N/A	No	
418	7200	1	1	109A	Storage	Classroom 109 Closet	W4	Cracking, Chipping, Flaking, Coat hooks pulling off wall	81	No	No	N/A	N/A	Yes	
419	7200	1	1	110	Primary	Classroom 110	Floor	N/A	N/A	No	Paint chips behind shelf	2	N/A	No	
420	7200	1	1	110	Primary	Classroom 110	W1	Chipping, flaking	3	No	No	N/A	Posters, Furniture	No	
421	7200	1	1	110	Primary	Classroom 110	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	
422	7200	1	1	110	Primary	Classroom 110	W3	Flaking	30	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to furniture and stored materials
423	7200	1	1	110	Primary	Classroom 110	W4	Flaking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
424	7200	1	1	110A	Storage	Classroom 110 Large Closet	Floor	N/A	N/A	No	Paint chips by pipe	1	N/A	No	
425	7200	1	1	110A	Storage	Classroom 110 Large Closet	W1	Chipping, Gouges	3	No	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
426	7200	1	1	110A	Storage	Classroom 110 Large Closet	W2	Chipping	1	No	No	N/A	N/A	No	
427	7200	1	1	110A	Storage	Classroom 110 Large Closet	W3	Chipping on radiator, Flaking on wall and metal jacket	17	No	No	N/A	N/A	No	
428	7200	1	1	110B	Storage	Classroom 110 Small Closet	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
429	7200	1	1	110B	Storage	Classroom 110 Small Closet	W1	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
430	7200	1	1	110B	Storage	Classroom 110 Small Closet	W2	Cracking	15	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
431	7200	1	1	110B	Storage	Classroom 110 Small Closet	W3	Cracking, Flaking	28	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
432	7200	1	1	110B	Storage	Classroom 110 Small Closet	W4	Cracking, Flaking	27	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
433	7200	1	1	111	Primary	Classroom 111	Ceiling	Flaking, Efflorescence above missing ceiling tile	3	Yes	No	N/A	N/A	Yes	
434	7200	1	1	111	Primary	Classroom 111	Floor	N/A	N/A	No	Paint chips in corner near pipe	1	N/A	No	
435	7200	1	1	111	Primary	Classroom 111	W1	Chipping, Flaking	27	No	No	N/A	N/A	No	
436	7200	1	1	111	Primary	Classroom 111	W2	N/A	N/A	No	No	N/A	Built in Shelves	No	
437	7200	1	1	111	Primary	Classroom 111	W3	Efflorescence, Significant Moisture Damage behind radiator and cover	25	Yes	Paint chips inside radiator cover	5	N/A	Yes	
438	7200	1	1	111	Primary	Classroom 111	W4	Flaking	4	No	No	N/A	N/A	No	
439	7200	1	1	111C	Storage	Classroom 111 Center Closet	Floor	N/A	N/A	No	Debris by metal pipe, Paint chips along wall 3	3	Stored Materials	No	
440	7200	1	1	111C	Storage	Classroom 111 Center Closet	W1	Flaking on metal pipe, Coat hooks pulling off wall	2	No	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
441	7200	1	1	111C	Storage	Classroom 111 Center Closet	W2	Cracking, Flaking	17	No	No	N/A	Stored Materials	No	
442	7200	1	1	111C	Storage	Classroom 111 Center Closet	W3	Flaking on metal jacket	2	No	No	N/A	Stored Materials	No	
443	7200	1	1	111C	Storage	Classroom 111 Center Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	
444	7200	1	1	111E	Storage	Classroom 111 Closet adjacent to Windows	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
445	7200	1	1	111E	Storage	Classroom 111 Closet adjacent to Windows	W1	Cracking	20	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
446	7200	1	1	111E	Storage	Classroom 111 Closet adjacent to Windows	W2	Cracking, Flaking	12	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
447	7200	1	1	111E	Storage	Classroom 111 Closet adjacent to Windows	W3	Cracking, Efflorescence	40	Yes	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
448	7200	1	1	111E	Storage	Classroom 111 Closet adjacent to Windows	W4	Cracking, Efflorescence	22	Yes	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
449	7200	1	1	111A	Student Restrooms - Male/Female (Classroom)	Classroom 111 Restroom	Ceiling	Cracking, Flaking	7	No	No	N/A	N/A	No	
450	7200	1	1	H18A	Storage	Closet at the End of the Hallway from the Nurse's Office	Floor	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
451	7200	1	1	H18A	Storage	Closet at the End of the Hallway from the Nurse's Office	W1	Cracking, Chipping, Hole	5	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
452	7200	1	1	H18A	Storage	Closet at the End of the Hallway from the Nurse's Office	W2	Cracking	5	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
453	7200	1	1	H18A	Storage	Closet at the End of the Hallway from the Nurse's Office	W3	Cracking, Flaking	7	No	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
454	7200	1	1	H18A	Storage	Closet at the End of the Hallway from the Nurse's Office	W4	Cracking	3	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
455	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	Ceiling	Flaking	115	No	No	N/A	N/A	No	
456	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	Floor	Chipping on floor, stairs, and railings	110	No	Paint chips	10	N/A	No	
457	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	W1	Chipping on door and frame, Flaking	47	No	No	N/A	N/A	No	
458	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	W2	Flaking on wall and metal pipe	70	No	No	N/A	N/A	No	
459	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	W3	Chipping on exit door, Flaking	125	No	No	N/A	N/A	No	
460	7200	1	1	S11	Stairs	Fire Tower Across from Boy's Restroom	W4	Flaking on wall, bars, and window frames	100	No	No	N/A	N/A	No	
461	7200	1	1	112A	Primary	Former Projection Room	Ceiling	Hole	3	No	No	N/A	Stored Computer Equipment	Yes	
462	7200	1	1	112A	Primary	Former Projection Room	Floor	N/A	N/A	No	No	N/A	Stored Computer Equipment	No	
463	7200	1	1	112A	Primary	Former Projection Room	W1	N/A	N/A	No	No	N/A	Stored Computer Equipment	No	
464	7200	1	1	112A	Primary	Former Projection Room	W2	Efflorescence	1	Yes	No	N/A	Stored Computer Equipment	Yes	
465	7200	1	1	112A	Primary	Former Projection Room	W3	Cracking, Holes	7	No	No	N/A	Stored Computer Equipment	Yes	
466	7200	1	1	112A	Primary	Former Projection Room	W4	Flaking on wall and metal pipe	9	No	No	N/A	Stored Computer Equipment	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
467	7200	1	1	102B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 103	Ceiling	Efflorescence	1	Yes	No	N/A	N/A	Yes	
468	7200	1	1	H16A	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Left	Ceiling	Spalling	1	No	No	N/A	N/A	No	
469	7200	1	1	H16A	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Left	Floor	Chipping on floor and cove scattered	20	No	No	N/A	N/A	No	
470	7200	1	1	H16A	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Left	W1	Flaking	2	No	Debris	1	N/A	No	
471	7200	1	1	H16A	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Left	W2	Cracking	20	No	No	N/A	N/A	No	
472	7200	1	1	H16A	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Left	W3	Cracking, Flaking, Spalling	22	Yes	No	N/A	N/A	Yes	
473	7200	1	1	H16B	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Right	Ceiling	Chipping on metal pipe	2	No	No	N/A	N/A	No	
474	7200	1	1	H16B	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Right	Floor	Chipping on floor and cove scattered	26	No	Debris	3	N/A	No	
475	7200	1	1	H16B	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Right	W1	Cracking	10	No	Debris	2	N/A	No	
476	7200	1	1	H16B	Circulation (Hallway)	Hall/Stairwell leading to the Auditorium from the Right	W3	Cracking	5	No	No	N/A	N/A	No	
477	7200	1	1	H18	Circulation (Hallway)	Hallway at the Nurse's Office	Floor	Chipping on floor and cove scattered	15	No	No	N/A	N/A	No	
478	7200	1	1	H18	Circulation (Hallway)	Hallway at the Nurse's Office	W2	Flaking by cabinet	<1	No	No	N/A	N/A	No	
479	7200	1	1	H18	Circulation (Hallway)	Hallway at the Nurse's Office	W3	Chipping	1	No	No	N/A	N/A	No	
480	7200	1	1	H16	Circulation (Hallway)	Hallway in Front of Auditorium	Ceiling	Efflorescence	10	Yes	No	N/A	N/A	Yes	
481	7200	1	1	H16	Circulation (Hallway)	Hallway in Front of Auditorium	Floor	Chipping on floor and cove scattered	21	No	No	N/A	N/A	No	
482	7200	1	1	H16	Circulation (Hallway)	Hallway in Front of Auditorium	W1	Cracking, Chipping on wall and metal jacket, Hole, Flaking	30	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
483	7200	1	1	H16	Circulation (Hallway)	Hallway in Front of Auditorium	W3	Cracking, Chipping on railings, Flaking behind radiator and cover, Efflorescence	94	Yes	No	N/A	N/A	Yes	
484	7200	1	1	H17	Circulation (Hallway)	Hallway in Front of Classroom 109	Floor	Chipping on floor and cove scattered	14	No	No	N/A	N/A	No	
485	7200	1	1	H17	Circulation (Hallway)	Hallway in Front of Classroom 109	W1	Chipping	1	No	No	N/A	N/A	No	
486	7200	1	1	H17	Circulation (Hallway)	Hallway in Front of Classroom 109	W2	Cracking, Chipping	11	No	No	N/A	N/A	No	
487	7200	1	1	H15	Circulation (Hallway)	Hallway outside Main Office	Floor	Chipping on floor and cove scattered	9	No	No	N/A	N/A	No	
488	7200	1	1	H15	Circulation (Hallway)	Hallway outside Main Office	W2	Flaking	<1	No	No	N/A	N/A	No	
489	7200	1	1	H15	Circulation (Hallway)	Hallway outside Main Office	W4	Chipping	2	No	No	N/A	N/A	No	
490	7200	1	1	104	IMC (Library)	IMC 104	Floor	N/A	N/A	No	Paint chips behind built in shelf	2	N/A	No	
491	7200	1	1	104	IMC (Library)	IMC 104	W1	Cracking, Chipping, Flaking	5	No	No	N/A	N/A	No	
492	7200	1	1	104	IMC (Library)	IMC 104	W3	Flaking behind built-in shelf and radiator and cover	30	No	Debris on windowsills and inside radiator cover	12	N/A	No	
493	7200	1	1	104A	Storage	IMC 104 Closet	Ceiling	Flaking	5	No	No	N/A	N/A	No	
494	7200	1	1	104A	Storage	IMC 104 Closet	W1	Hole	1	No	No	N/A	N/A	Yes	
495	7200	1	1	104A	Storage	IMC 104 Closet	W2	Cracking, Chipping, Flaking	53	No	No	N/A	N/A	No	
496	7200	1	1	104A	Storage	IMC 104 Closet	W3	Cracking, Flaking on vent cover	7	No	No	N/A	N/A	Yes	
497	7200	1	1	104A	Storage	IMC 104 Closet	W4	Cracking, Flaking, Holes	30	No	No	N/A	N/A	No	
498	7200	1	1	104B	IMC (Library)	IMC 104 Office adjacent to Windows	Ceiling	Flaking above windows	2	No	No	N/A	N/A	No	
499	7200	1	1	104B	IMC (Library)	IMC 104 Office adjacent to Windows	W1	Chipping on wall and doorframe	3	No	No	N/A	N/A	No	
500	7200	1	1	104B	IMC (Library)	IMC 104 Office adjacent to Windows	W2	Flaking	2	No	No	N/A	N/A	No	
501	7200	1	1	104C	IMC (Library)	IMC 104 Office near Hallway	W2	Chipping	4	No	No	N/A	N/A	No	
502	7200	1	1	105	IMC (Library)	IMC 105	W1	Cracking, Chipping	11	No	No	N/A	N/A	No	Limited inspection due to built in shelves
503	7200	1	1	105	IMC (Library)	IMC 105	W3	Flaking behind radiator and cover	20	No	No	N/A	Shelves, Stored Materials	No	
504	7200	1	1	105A	Storage	IMC 105 Closet	W2	Cracking	30	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves with stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
505	7200	1	1	105A	Storage	IMC 105 Closet	W3	Cracking	20	No	No	N/A	Shelves, Stored Materials	No	No
506	7200	1	1	105A	Storage	IMC 105 Closet	W4	Cracking, Flaking	70	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
507	7200	1	1	106	IMC (Library)	IMC 106	Ceiling	Flaking above windows	1	No	No	N/A	N/A	No	
508	7200	1	1	106	IMC (Library)	IMC 106	W1	Cracking, Flaking	9	No	No	N/A	Shelves	No	
509	7200	1	1	106	IMC (Library)	IMC 106	W2	Cracking	2	No	No	N/A	N/A	No	
510	7200	1	1	106A	IMC (Library)	IMC 106 Closet	Ceiling	Flaking	10	No	No	N/A	Shelves, Stored Materials	No	
511	7200	1	1	106A	IMC (Library)	IMC 106 Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves with stored materials
512	7200	1	1	106A	IMC (Library)	IMC 106 Closet	W1	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves with stored materials
513	7200	1	1	106A	IMC (Library)	IMC 106 Closet	W2	Cracking, Flaking, Coat hooks pulling off walls	41	No	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to shelves with stored materials
514	7200	1	1	106A	IMC (Library)	IMC 106 Closet	W3	Cracking, Flaking	20	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves with stored materials
515	7200	1	1	106A	IMC (Library)	IMC 106 Closet	W4	Cracking, Flaking, Coat hooks pulling off walls	70	No	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to shelves with stored materials
516	7200	1	1	114	Administrative Office	Main Office	W3	Holes, Flaking on and behind radiator	24	No	No	N/A	N/A	No	
517	7200	1	1	114A	Storage	Main Office Storage Closet	W1	Cracking, Chipping	22	No	No	N/A	Shelves with stored materials	No	
518	7200	1	1	114A	Storage	Main Office Storage Closet	W2	Cracking	4	No	No	N/A	Shelves with stored materials	No	
519	7200	1	1	114A	Storage	Main Office Storage Closet	W3	Cracking, Chipping on metal pipe, Flaking	36	No	Debris on card holders	3	Shelves with stored materials	No	
520	7200	1	1	114A	Storage	Main Office Storage Closet	W4	Chipping	1	No	No	N/A	Shelves with stored materials	No	
521	7200	1	1	111B	Administrative Office	Nurse's Office by Classroom 111	Ceiling	Efflorescence above windows	5	Yes	No	N/A	N/A	Yes	
522	7200	1	1	111B	Administrative Office	Nurse's Office by Classroom 111	W2	Chipping on wood door	2	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
523	7200	1	1	111B	Administrative Office	Nurse's Office by Classroom 111	W4	Flaking on window frames	5	No	Debris on windowsill	1	N/A	No	
524	7200	1	1	102	Administrative Office	Office 102 Common Area	W1	Cracking, Chipping	55	No	No	N/A	Wood Cabinets	No	
525	7200	1	1	102	Administrative Office	Office 102 Common Area	W4	Cracking	10	No	No	N/A	Copier, File Cabinet, Refrigerator	No	
526	7200	1	1	102D	Administrative Office	Office 102 Dean's Office (Center Office)	W1	Chipping on wall and doorframe	6	No	No	N/A	Chairs	No	
527	7200	1	1	102D	Administrative Office	Office 102 Dean's Office (Center Office)	W2	Chipping	2	No	No	N/A	Shelves	No	
528	7200	1	1	102D	Administrative Office	Office 102 Dean's Office (Center Office)	W3	Flaking on wall, some behind radiator and cover and on metal pipe	15	No	No	N/A	N/A	No	
529	7200	1	1	102A	Storage	Office 102 Large Closet	Ceiling	Cracking	5	No	No	N/A	N/A	No	
530	7200	1	1	102A	Storage	Office 102 Large Closet	W2	Cracking, Hole	26	No	No	N/A	N/A	Yes	
531	7200	1	1	102A	Storage	Office 102 Large Closet	W3	Flaking behind radiator	5	No	No	N/A	Cabinet, Shelves, Stored Materials	No	Limited inspection due to cabinet, shelves, and stored materials
532	7200	1	1	102A	Storage	Office 102 Large Closet	W4	Cracking, Flaking	103	No	No	N/A	Cabinet	No	Limited inspection due to cabinet
533	7200	1	1	102E	Administrative Office	Office 102 Left Office	Ceiling	Chipping above window	1	No	No	N/A	N/A	No	
534	7200	1	1	102E	Administrative Office	Office 102 Left Office	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
535	7200	1	1	102E	Administrative Office	Office 102 Left Office	W2	Cracking, Efflorescence	20	Yes	No	N/A	Shelf	Yes	
536	7200	1	1	102E	Administrative Office	Office 102 Left Office	W3	Chipping behind radiator, Spalling	10	Yes	No	N/A	N/A	Yes	
537	7200	1	1	102C	Administrative Office	Office 102 Psychologist Office (Right Office)	Ceiling	Flaking, Efflorescence above window	2	Yes	No	N/A	Desk, File Cabinet	Yes	
538	7200	1	1	102C	Administrative Office	Office 102 Psychologist Office (Right Office)	W1	Chipping on doorframe	4	No	No	N/A	N/A	No	
539	7200	1	1	102C	Administrative Office	Office 102 Psychologist Office (Right Office)	W2	Chipping	2	No	No	N/A	Desk	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
540	7200	1	1	102C	Administrative Office	Office 102 Psychologist Office (Right Office)	W3	Flaking, Efflorescence	21	Yes	Paint chips on windowsill	1	Desk, File Cabinet	Yes	
541	7200	1	1	102C	Administrative Office	Office 102 Psychologist Office (Right Office)	W4	Cracking	10	No	No	N/A	Chairs, File Cabinet	No	
542	7200	1	1	102F	Administrative Office	Office 102 Small Closet	Floor	N/A	N/A	No	Paint chips along wall 2	5	N/A	No	
543	7200	1	1	102F	Administrative Office	Office 102 Small Closet	W1	Cracking	2	No	No	N/A	N/A	No	
544	7200	1	1	102F	Administrative Office	Office 102 Small Closet	W2	Flaking	25	No	No	N/A	Stored Materials	No	
545	7200	1	1	115	Administrative Office	Principal's Office	W3	Chipping on radiator	5	No	No	N/A	N/A	No	
546	7200	1	1	115	Administrative Office	Principal's Office	W4	Flaking on and behind radiator and on ACM Pipe	12	No	Debris on desk	1	N/A	No	
547	7200	1	1	115B	Administrative Office	Principal's Office Closet	Ceiling	Cracking, Efflorescence	10	Yes	No	N/A	N/A	Yes	
548	7200	1	1	115B	Administrative Office	Principal's Office Closet	W1	Cracking	50	No	No	N/A	N/A	No	
549	7200	1	1	115B	Administrative Office	Principal's Office Closet	W2	Cracking, Flaking on metal pipe	22	No	Debris on shelves	7	Built in Shelves, Stored Materials	No	
550	7200	1	1	115B	Administrative Office	Principal's Office Closet	W3	Cracking, Hole, Efflorescence	21	Yes	Debris on shelves	7	Built in Shelves, Stored Materials	Yes	
551	7200	1	1	115B	Administrative Office	Principal's Office Closet	W4	Cracking, Hole	21	No	Debris on shelves	7	Built in Shelves, Stored Materials	Yes	
552	7200	1	1	115A	Administrative Office	Principal's Office Restroom	Ceiling	Efflorescence	3	Yes	No	N/A	N/A	Yes	
553	7200	1	1	115A	Administrative Office	Principal's Office Restroom	W4	N/A	N/A	No	Debris on windowsill	2	N/A	No	
554	7200	1	1	113C	Stage	Stage	Ceiling	Efflorescence	20	Yes	No	N/A	N/A	Yes	Ceiling is assumed asbestos
555	7200	1	1	113C	Stage	Stage	Floor	N/A	N/A	No	Debris and paint chips on left stairs, corner of walls 1&2, and along wall 3	37	Ladders	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
556	7200	1	1	113C	Stage	Stage	W1	Chipping, Flaking in decorative plaster, Efflorescence in decorative plaster	5	Yes	No	N/A	N/A	Yes	
557	7200	1	1	113C	Stage	Stage	W2	Hole, Flaking, Efflorescence	36	Yes	No	N/A	N/A	Yes	
558	7200	1	1	113C	Stage	Stage	W3	Efflorescence	100	Yes	No	N/A	Ladders	Yes	
559	7200	1	1	113C	Stage	Stage	W4	Flaking, Efflorescence	15	Yes	No	N/A	N/A	Yes	
560	7200	1	1	S13	Stairs	Stairwell adjacent to Office 102	Floor	Chipping on stairs, floor, cove and railings	68	No	No	N/A	N/A	No	
561	7200	1	1	S13	Stairs	Stairwell adjacent to Office 102	W1	Chipping on door and frame, Flaking, Spalling	10	Yes	No	N/A	N/A	Yes	
562	7200	1	1	S13	Stairs	Stairwell adjacent to Office 102	W2	Cracking	15	No	No	N/A	N/A	No	
563	7200	1	1	S13	Stairs	Stairwell adjacent to Office 102	W3	Chipping on door and frame at top and bottom, Flaking	73	No	No	N/A	N/A	No	
564	7200	1	1	S13	Stairs	Stairwell adjacent to Office 102	W4	Chipping	7	No	No	N/A	N/A	No	
565	7200	1	1	S12	Stairs	Stairwell at Classroom 107	Ceiling	Chipping	1	No	No	N/A	N/A	No	
566	7200	1	1	S12	Stairs	Stairwell at Classroom 107	Floor	Chipping on floor, cove and railings	77	No	No	N/A	N/A	No	
567	7200	1	1	S12	Stairs	Stairwell at Classroom 107	W1	Chipping on doors and frames	25	No	No	N/A	N/A	No	
568	7200	1	1	S12	Stairs	Stairwell at Classroom 107	W2	Chipping	5	No	No	N/A	N/A	No	
569	7200	1	1	S12	Stairs	Stairwell at Classroom 107	W3	Cracking, Chipping on both sides of top and bottom doors	26	No	No	N/A	N/A	No	
570	7200	1	1	S12	Stairs	Stairwell at Classroom 107	W4	Chipping	6	No	No	N/A	N/A	No	
571	7200	1	1	S15	Stairs	Stairwell at Room 100	W3	Chipping on door	3	No	No	N/A	N/A	No	
572	7200	1	1	S15	Stairs	Stairwell at Room 100	W4	Cracking, Flaking	5	No	No	N/A	N/A	No	
573	7200	1	1	S17	Stairs	Stairwell in Front of Classroom 109	Floor	Chipping on stairs and railings	50	No	No	N/A	N/A	No	
574	7200	1	1	S17	Stairs	Stairwell in Front of Classroom 109	W2	Spalling	10	Yes	No	N/A	N/A	Yes	
575	7200	1	1	S17	Stairs	Stairwell in Front of Classroom 109	W4	Cracking, Chipping, Flaking	4	No	No	N/A	N/A	No	
576	7200	1	1	113B	Storage	Storage to the Left of Stage	W1	Cracking	10	No	No	N/A	Instruments	No	Auditorium Entrance
577	7200	1	1	113B	Storage	Storage to the Left of Stage	W4	Cracking	5	No	No	N/A	Instruments	No	
578	7200	1	1	113A	Storage	Storage to the Right of Stage	Ceiling	Flaking on metal duct, Efflorescence	10	Yes	No	N/A	Furniture, Stored Material	Yes	Ceiling is assumed asbestos. Limited inspection due to furniture and stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
579	7200	1	1	113A	Storage	Storage to the Right of Stage	Floor	N/A	N/A	No	No	N/A	Furniture, Stored Material	No	Limited inspection due to furniture and stored materials
580	7200	1	1	113A	Storage	Storage to the Right of Stage	W1	N/A	N/A	No	No	N/A	Furniture, Stored Material	No	Auditorium Entrance. Limited inspection due to furniture and stored materials
581	7200	1	1	113A	Storage	Storage to the Right of Stage	W2	N/A	N/A	No	No	N/A	Furniture, Stored Material	No	Limited inspection due to furniture and stored materials
582	7200	1	1	113A	Storage	Storage to the Right of Stage	W3	Flaking	50	No	Debris on stored material	5	Furniture, Stored Material	No	Limited inspection due to furniture and stored materials
583	7200	1	1	113A	Storage	Storage to the Right of Stage	W4	Flaking	25	No	No	N/A	Furniture, Stored Material	No	Limited inspection due to furniture and stored materials
584	7200	1	1	116	Restrooms, Staff - Female	Women's Restroom by Classroom 100	Ceiling	Flaking	2	No	No	N/A	N/A	No	
585	7200	1	0	9	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom B8	Ceiling	Flaking, Efflorescence, Significant Moisture Damage	12	No	No	N/A	N/A	No	
586	7200	1	0	9	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom B8	W3	N/A	N/A	No	Debris on Radiator	2	N/A	No	
587	7200	1	0	1	Student Restrooms - Male (4-12)	Boy's Restroom next to the Cafeteria	Ceiling	Flaking	7	No	No	N/A	N/A	No	
588	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	Ceiling	Significant Moisture Damage above missing ceiling tiles	18	Yes	No	N/A	N/A	Yes	
589	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	Floor	N/A	N/A	No	Debris in corner of walls 3&4	2	N/A	No	
590	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	W1	Chipping on wall and metal pipe, Significant Moisture Damage in air shaft	10	Yes	No	N/A	N/A	Yes	
591	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	W2	Hole, Efflorescence	16	Yes	No	N/A	Cabinets	Yes	
592	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	W3	Efflorescence	3	Yes	No	N/A	N/A	Yes	
593	7200	1	0	2	Cafeteria (Dining Area)	Cafeteria	W4	Chipping	1	No	No	N/A	N/A	No	
594	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	Ceiling	Cracking, Flaking	80	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
595	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
596	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	W1	Cracking, Chipping on wall and doorframe, Hole	17	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
597	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	W2	Hole	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
598	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	W3	Cracking, Flaking	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
599	7200	1	0	002C	Storage	Cafeteria Closet adjacent to Boy's Restroom by Hallway	W4	Chipping	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
600	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	Ceiling	Cracking, Holes, Flaking	28	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
601	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	Floor	N/A	N/A	No	Debris and paint chips	20	Stored Materials	No	Limited inspection due to stored materials
602	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	W1	Cracking, Hole, Flaking	31	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
603	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	W2	Flaking, Efflorescence	53	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
604	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	W3	Flaking, Significant Moisture Damage	20	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
605	7200	1	0	002B	Storage	Cafeteria Closet adjacent to Boy's Restroom by Windows	W4	Flaking	20	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
606	7200	1	0	002A	Storage	Cafeteria Closet adjacent to Main Entrance	Ceiling	Significant Moisture Damage above missing ceiling tile	4	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
607	7200	1	0	002A	Storage	Cafeteria Closet adjacent to Main Entrance	W3	Efflorescence	5	Yes	No	N/A	Shelf, Stored Materials	Yes	Limited inspection due to shelves and stored materials
608	7200	1	0	10	Primary	Classroom B10	Ceiling	Flaking, Efflorescence above windows	6	Yes	No	N/A	N/A	Yes	
609	7200	1	0	10	Primary	Classroom B10	Floor	N/A	N/A	No	Debris in corner of walls 1&4	2	N/A	No	
610	7200	1	0	10	Primary	Classroom B10	W1	Chipping, Flaking	10	No	No	N/A	N/A	No	
611	7200	1	0	10	Primary	Classroom B10	W2	Flaking	10	No	No	N/A	N/A	No	
612	7200	1	0	10	Primary	Classroom B10	W3	Chipping, Flaking, Spalling, Efflorescence	11	Yes	No	N/A	N/A	Yes	
613	7200	1	0	10	Primary	Classroom B10	W4	Flaking	10	No	No	N/A	N/A	No	
614	7200	1	0	10A	Storage	Classroom B10 Large Closet	Ceiling	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	
615	7200	1	0	10A	Storage	Classroom B10 Large Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	
616	7200	1	0	10A	Storage	Classroom B10 Large Closet	W1	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	
617	7200	1	0	10A	Storage	Classroom B10 Large Closet	W2	Efflorescence	1	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	
618	7200	1	0	10A	Storage	Classroom B10 Large Closet	W3	Flaking, Efflorescence, Significant Moisture Damage	33	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Some damage has been repaired but is returning. Significant damage is behind materials on lower part of the wall. Debris may be present but could not see any due to stored materials.
619	7200	1	0	10A	Storage	Classroom B10 Large Closet	W4	Efflorescence behind cabinet	5	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	
620	7200	1	0	010B	Storage	Classroom B10 Small Closet	Floor	N/A	N/A	No	Debris	10	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
621	7200	1	0	010B	Storage	Classroom B10 Small Closet	W1	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
622	7200	1	0	010B	Storage	Classroom B10 Small Closet	W2	N/A	N/A	No	No	N/A	Built in Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
623	7200	1	0	010B	Storage	Classroom B10 Small Closet	W3	Significant Moisture Damage	25	Yes	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials. Damage has previously been repaired but is returning.
624	7200	1	0	010B	Storage	Classroom B10 Small Closet	W4	Efflorescence, Significant Moisture Damage	20	Yes	No	N/A	Built in Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials. Damage has previously been repaired but is returning.
625	7200	1	0	11	Primary	Classroom B11	Ceiling	Flaking, some above window by closet, Significant Moisture Damage	8	Yes	No	N/A	Stored Furniture and Materials	Yes	Limited inspection due to furniture and stored materials
626	7200	1	0	11	Primary	Classroom B11	Floor	N/A	N/A	No	No	N/A	Stored Furniture and Materials	No	Limited inspection due to furniture and stored materials
627	7200	1	0	11	Primary	Classroom B11	W1	Flaking	1	No	No	N/A	N/A	No	
628	7200	1	0	11	Primary	Classroom B11	W2	Cracking	3	No	No	N/A	N/A	No	
629	7200	1	0	11	Primary	Classroom B11	W3	Cracking, Hole, Spalling	9	Yes	No	N/A	Stored Furniture and Materials	Yes	Limited inspection due to furniture and stored materials
630	7200	1	0	11	Primary	Classroom B11	W4	Flaking, Efflorescence	15	Yes	No	N/A	Stored Furniture and Materials	Yes	Limited inspection due to furniture and stored materials
631	7200	1	0	11B	Storage	Classroom B11 Large Closet	Ceiling	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
632	7200	1	0	11B	Storage	Classroom B11 Large Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
633	7200	1	0	11B	Storage	Classroom B11 Large Closet	W1	N/A	N/A	No	No	N/A	Cabinets, Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
634	7200	1	0	11B	Storage	Classroom B11 Large Closet	W2	Efflorescence, Coat hooks pulling off wall	30	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
635	7200	1	0	11B	Storage	Classroom B11 Large Closet	W3	Flaking, Efflorescence, Significant Moisture Damage	18	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
636	7200	1	0	11B	Storage	Classroom B11 Large Closet	W4	Efflorescence	2	Yes	No	N/A	Cabinets, Shelves, Stored Materials	Yes	Limited inspection due to shelves and stored materials
637	7200	1	0	11A	Storage	Classroom B11 Small Closet	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	Damage has previously been repaired but is returning
638	7200	1	0	11A	Storage	Classroom B11 Small Closet	Floor	N/A	N/A	No	Debris	3	N/A	No	
639	7200	1	0	11A	Storage	Classroom B11 Small Closet	W1	Efflorescence	2	Yes	No	N/A	N/A	Yes	Damage has previously been repaired but is returning
640	7200	1	0	11A	Storage	Classroom B11 Small Closet	W2	Efflorescence	5	Yes	No	N/A	N/A	Yes	Damage has previously been repaired but is returning
641	7200	1	0	11A	Storage	Classroom B11 Small Closet	W3	Efflorescence	3	Yes	No	N/A	N/A	Yes	Damage has previously been repaired but is returning
642	7200	1	0	11A	Storage	Classroom B11 Small Closet	W4	Efflorescence	20	Yes	No	N/A	N/A	Yes	Damage has previously been repaired but is returning
643	7200	1	0	7	Primary	Classroom B7	Floor	N/A	N/A	No	Debris along wall 3	2	N/A	No	
644	7200	1	0	7	Primary	Classroom B7	W1	Cracking	20	No	No	N/A	N/A	No	
645	7200	1	0	7	Primary	Classroom B7	W2	Chipping	1	No	No	N/A	N/A	No	
646	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	Ceiling	Hole	1	No	No	N/A	Stored Materials	Yes	
647	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	
648	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	W1	Hole	3	No	No	N/A	Stored Materials	Yes	
649	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	W2	N/A	N/A	No	No	N/A	Stored Materials	No	
650	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	W3	N/A	N/A	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
651	7200	1	0	007A	Storage	Classroom B7 Storage Closet at Entrance	W4	N/A	N/A	No	No	N/A	Stored Materials	No	
652	7200	1	0	007B	Storage	Classroom B7 Storage Closet Southeast Corner	Ceiling	Flaking on ceiling and metal duct	4	No	No	N/A	N/A	No	
653	7200	1	0	007B	Storage	Classroom B7 Storage Closet Southeast Corner	Floor	Chipping	80	No	Debris in corner of walls 1&2	2	N/A	No	
654	7200	1	0	007B	Storage	Classroom B7 Storage Closet Southeast Corner	W1	Efflorescence	1	Yes	No	N/A	N/A	Yes	
655	7200	1	0	8	Primary	Classroom B8	W3	Chipping on metal jacket, Flaking on metal jacket	3	No	Debris inside radiator cover	3	N/A	No	
656	7200	1	0	008A	Storage	Classroom B8 Closet	W2	Hole	1	No	No	N/A	N/A	No	
657	7200	1	0	H04A	Storage	Closet across from Boy's and Girl's Restrooms near Cafeteria	Ceiling	Flaking	10	No	No	N/A	Maintenance Equipment	No	
658	7200	1	0	H04A	Storage	Closet across from Boy's and Girl's Restrooms near Cafeteria	W4	Flaking	20	No	No	N/A	Maintenance Equipment	No	
659	7200	1	0	H02A	Storage	Closet across from Boy's and Girl's Restrooms near Classroom B8	W2	Flaking	25	No	No	N/A	N/A	No	
660	7200	1	0	H05	Stairs	Emergency Exit in Gym	Ceiling	Chipping on metal duct, Flaking on ACM pipe	4	No	No	N/A	N/A	No	
661	7200	1	0	H05	Stairs	Emergency Exit in Gym	Floor	Chipping	5	No	Paint chips scattered	5	N/A	No	
662	7200	1	0	H05	Stairs	Emergency Exit in Gym	W1	Chipping on door	3	No	No	N/A	N/A	No	
663	7200	1	0	H05	Stairs	Emergency Exit in Gym	W3	Chipping on door and frame	4	No	No	N/A	N/A	No	
664	7200	1	0	009A	Student Restrooms - Female (4-12)	Girl's Restroom near Classroom B8	Ceiling	Flaking	2	No	No	N/A	N/A	No	
665	7200	1	0	001A	Student Restrooms - Female (4-12)	Girl's Restroom next to the Cafeteria	Ceiling	Cracking, Flaking	100	No	No	N/A	N/A	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
666	7200	1	0	6	Gymnasium - Intermediate Middle	Gym	Ceiling	Cracking, Chipping on metal duct, Holes, Flaking on ceiling, radiators, ACM pipe insulation, fiberglass pipe insulation, metal jackets, and vertical metal pipes in center, Efflorescence, Significant Moisture Damage above radiator	454	Yes	No	N/A	N/A	Yes	
667	7200	1	0	6	Gymnasium - Intermediate Middle	Gym	W1	Chipping on metal jackets, Flaking on wall, metal pipe, and ACM pipe insulation	15	No	No	N/A	N/A	No	From Main Entrance Side
668	7200	1	0	6	Gymnasium - Intermediate Middle	Gym	W2	Cracking, Chipping on metal jackets, Flaking on wall and ACM pipe insulation	43	No	No	N/A	N/A	No	
669	7200	1	0	6	Gymnasium - Intermediate Middle	Gym	W3	Cracking, Chipping on doors, Flaking	30	No	No	N/A	N/A	No	
670	7200	1	0	6	Gymnasium - Intermediate Middle	Gym	W4	Cracking, Chipping on wall and metal jackets, Flaking on wall, metal jackets, and ACM pipe insulation	90	No	No	N/A	N/A	No	
671	7200	1	0	006A	Administrative Office	Gym Office	Ceiling	Flaking on metal duct	100	No	No	N/A	Furniture, Stored Materials	No	
672	7200	1	0	006A	Administrative Office	Gym Office	Floor	N/A	N/A	No	Paint chips on floor and stored materials	144	Furniture, Stored Materials	No	
673	7200	1	0	006A	Administrative Office	Gym Office	W1	Chipping, Flaking on metal pipe	11	No	No	N/A	Furniture, Stored Materials	No	
674	7200	1	0	006A	Administrative Office	Gym Office	W2	Chipping on air vent	3	No	No	N/A	Furniture, Stored Materials	No	
675	7200	1	0	006A	Administrative Office	Gym Office	W3	N/A	N/A	No	No	N/A	Furniture, Stored Materials	No	
676	7200	1	0	006A	Administrative Office	Gym Office	W4	N/A	N/A	No	No	N/A	Furniture, Stored Materials	No	
677	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	Ceiling	N/A	N/A	No	No	N/A	Gym Equipment	No	
678	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	Floor	N/A	N/A	No	Debris along wall 2	2	Gym Equipment	No	
679	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	W1	Holes	6	No	No	N/A	Gym Equipment	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
680	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	W2	Chipping, Flaking	6	No	No	N/A	Gym Equipment	No	
681	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	W3	Cracking, Gouges, Flaking	9	No	No	N/A	Gym Equipment	Yes	
682	7200	1	0	006C	Storage	Gym Storage Closet adjacent to Stairwell	W4	N/A	N/A	No	No	N/A	Gym Equipment	No	
683	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	Ceiling	Hole, Flaking on ceiling and metal duct	141	No	No	N/A	Gym Equipment	Yes	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
684	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	Floor	N/A	N/A	No	Paint chips on floor and stored materials	100	Gym Equipment	No	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
685	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	W1	N/A	N/A	No	No	N/A	Gym Equipment	No	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
686	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	W2	N/A	N/A	No	No	N/A	Gym Equipment	No	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
687	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	W3	Flaking on metal pipe	4	No	No	N/A	Gym Equipment	No	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
688	7200	1	0	006B	Storage	Gym Storage Closet near Gym Office	W4	N/A	N/A	No	No	N/A	Gym Equipment	No	Limited inspection due to gym equipment. This space need to be fully inspected. More damage is likely present.
689	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	Ceiling	Chipping on ceiling and metal duct, Holes, Flaking on ceiling and fiberglass pipe insulation, Efflorescence	92	Yes	No	N/A	N/A	Yes	
690	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	Floor	Chipping on floor and railings	40	No	No	N/A	N/A	No	
691	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	W1	Cracking, Chipping	16	No	No	N/A	N/A	No	
692	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	W2	Cracking, Chipping on wall and metal jackets, Flaking on metal pipe	28	No	No	N/A	N/A	No	
693	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	W3	Chipping on metal pipe	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
694	7200	1	0	H02	Circulation (Hallway)	Hallway in Front of Classroom B8	W4	Cracking, Chipping	43	No	No	N/A	N/A	No	
695	7200	1	0	H01	Circulation (Hallway)	Hallway in Front of Classrooms B10-B11	Ceiling	Chipping on ceiling and metal duct, Flaking on fiberglass pipe insulation	20	No	No	N/A	N/A	No	
696	7200	1	0	H01	Circulation (Hallway)	Hallway in Front of Classrooms B10-B11	Floor	Chipping	8	No	No	N/A	N/A	No	
697	7200	1	0	H01	Circulation (Hallway)	Hallway in Front of Classrooms B10-B11	W1	Chipping	6	No	No	N/A	N/A	No	
698	7200	1	0	H01	Circulation (Hallway)	Hallway in Front of Classrooms B10-B11	W2	Chipping on door and frame	15	No	No	N/A	N/A	No	
699	7200	1	0	H04	Circulation (Hallway)	Hallway in Front of the Cafeteria	Ceiling	Chipping, Holes, Flaking on ceiling, fiberglass pipe insulation, metal duct, and ACM pipe insulation	501	No	No	N/A	N/A	Yes	
700	7200	1	0	H04	Circulation (Hallway)	Hallway in Front of the Cafeteria	Floor	N/A	N/A	No	Debris outside Girl's Restroom	1	N/A	No	
701	7200	1	0	H04	Circulation (Hallway)	Hallway in Front of the Cafeteria	W1	Chipping on both sides of doors, Flaking	50	No	No	N/A	N/A	No	
702	7200	1	0	H04	Circulation (Hallway)	Hallway in Front of the Cafeteria	W2	Cracking, Flaking, Efflorescence	31	Yes	No	N/A	N/A	Yes	
703	7200	1	0	H04	Circulation (Hallway)	Hallway in Front of the Cafeteria	W3	Flaking on metal pipe	10	No	No	N/A	N/A	No	
704	7200	1	0	H03	Circulation (Hallway)	Hallway in Front of the Kitchen leading to the Gym	Ceiling	Chipping on metal duct, Flaking on ceiling, metal duct, fiberglass pipe insulation, metal pipes, conduit	874	No	No	N/A	N/A	No	Some damage is above duct and piping. Quantity is from entire ceiling number from room by room inventory and may not be accurate.
705	7200	1	0	H03	Circulation (Hallway)	Hallway in Front of the Kitchen leading to the Gym	Floor	N/A	N/A	No	Debris and Paint Chips under lockers along wall 1	5	Lockers	No	
706	7200	1	0	H03	Circulation (Hallway)	Hallway in Front of the Kitchen leading to the Gym	W1	Flaking	1	No	No	N/A	N/A	No	
707	7200	1	0	H03	Circulation (Hallway)	Hallway in Front of the Kitchen leading to the Gym	W3	Flaking on wall and metal pipe	31	No	No	N/A	N/A	No	
708	7200	1	0	H03	Circulation (Hallway)	Hallway in Front of the Kitchen leading to the Gym	W4	Flaking	4	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
709	7200	1	0	4	Kitchen	Kitchen and Small Cafeteria Area	Ceiling	Flaking on ceiling, fiberglass pipe insulation, and metal duct, Efflorescence	178	Yes	Debris on ceiling pipe	1	Cafeteria Tables	Yes	
710	7200	1	0	4	Kitchen	Kitchen and Small Cafeteria Area	W3	Chipping on radiator behind ovens, Flaking on metal jacket, metal pipe behind ovens, and fiberglass pipe insulation, Efflorescence on non painted bricks	93	Yes	No	N/A	Ovens	No	
711	7200	1	0	4	Kitchen	Kitchen and Small Cafeteria Area	W4	Chipping on metal pipe	3	No	No	N/A	N/A	No	
712	7200	1	0	004B	Kitchen	Kitchen and Small Cafeteria Area Gas Meter Room	Ceiling	Significant Moisture Damage	15	Yes	No	N/A	N/A	Yes	
713	7200	1	0	004B	Kitchen	Kitchen and Small Cafeteria Area Gas Meter Room	Floor	N/A	N/A	No	Paint chips and ACM debris	15	N/A	No	
714	7200	1	0	004B	Kitchen	Kitchen and Small Cafeteria Area Gas Meter Room	W3	Flaking	60	No	No	N/A	N/A	No	
715	7200	1	0	5	Administrative Office	Kitchen Office	Ceiling	Flaking on metal pipe	3	No	Shelves, Stored Materials, Safe	N/A	N/A	No	
716	7200	1	0	5	Administrative Office	Kitchen Office	W2	Flaking	25	No	No	N/A	N/A	No	
717	7200	1	0	11C	Restrooms, Staff - Male/Female	Restroom outside of Classroom B11	Ceiling	Cracking, Flaking	5	No	No	N/A	N/A	No	
718	7200	1	0	S01	Stairs	Stairwell that leads to the Boy's and Girl's Restrooms near the Cafeteria	Ceiling	Chipping on metal pipe, Flaking	25	No	No	N/A	N/A	No	
719	7200	1	0	S01	Stairs	Stairwell that leads to the Boy's and Girl's Restrooms near the Cafeteria	Floor	N/A	N/A	No	Debris along wall 4	2	N/A	No	
720	7200	1	0	S01	Stairs	Stairwell that leads to the Boy's and Girl's Restrooms near the Cafeteria	W1	Chipping on door, Flaking	4	No	No	N/A	N/A	No	
721	7200	1	0	S01	Stairs	Stairwell that leads to the Boy's and Girl's Restrooms near the Cafeteria	W2	Chipping on metal pipe	2	No	No	N/A	N/A	No	

