

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	5260	1	3	201	Primary	Classroom 201	Ceiling	Staining, Holes	9	Yes	No	N/A	Furniture	No	
2	5260	1	3	201	Primary	Classroom 201	W1	Chipping, Flaking	25	No	No	N/A	Posters, Furniture	No	
3	5260	1	3	201	Primary	Classroom 201	W2	Flaking	10	No	No	N/A	Posters, Furniture	No	
4	5260	1	3	202	Primary	Classroom 202	W3	Cracking	15	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
5	5260	1	3	203	Primary	Classroom 203	Ceiling	Staining	2	No	No	N/A	N/A	No	
6	5260	1	3	203	Primary	Classroom 203	W2	Cracking	20	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
7	5260	1	3	204	Primary	Classroom 204	Ceiling	Staining	2	No	No	N/A	Furniture	No	
8	5260	1	3	204	Primary	Classroom 204	W1	Chipping on door	3	No	No	N/A	Posters	No	
9	5260	1	3	205	Primary	Classroom 205	Ceiling	Flaking	<1	No	No	N/A	N/A	No	
10	5260	1	3	205	Primary	Classroom 205	W2	Chipping around univent	25	No	No	N/A	Stored Materials	No	
11	5260	1	3	205	Primary	Classroom 205	W3	Cracking	3	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
12	5260	1	3	206	Primary	Classroom 206	W1	Cracking	3	No	No	N/A	Posters, Furniture	No	Entrance from Classroom 205. Repair to wall caulk needed.
13	5260	1	3	206	Primary	Classroom 206	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
14	5260	1	3	207	Primary	Classroom 207	Ceiling	Flaking along wall 2	3	No	No	N/A	Posters, Furniture	No	
15	5260	1	3	207	Primary	Classroom 207	W4	Cracking	15	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall and wall caulk needed
16	5260	1	3	208	Primary	Classroom 208	W1	Chipping	30	No	No	N/A	Posters, Furniture	No	
17	5260	1	3	208	Primary	Classroom 208	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
18	5260	1	3	209	Primary	Classroom 209	Ceiling	Staining, Flaking	2	No	No	N/A	N/A	No	
19	5260	1	3	209	Primary	Classroom 209	W1	Cracking, Chipping	37	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
20	5260	1	3	209	Primary	Classroom 209	W2	Cracking, Chipping, Flaking	55	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
21	5260	1	3	209	Primary	Classroom 209	W3	Chipping	20	No	No	N/A	Posters, Furniture	No	
22	5260	1	3	209	Primary	Classroom 209	W4	Chipping	3	No	No	N/A	Posters, Furniture	No	
23	5260	1	3	210	Primary	Classroom 210	Ceiling	Flaking	2	No	No	N/A	Furniture	No	
24	5260	1	3	210	Primary	Classroom 210	W1	Flaking	10	No	No	N/A	Posters, Furniture	No	
25	5260	1	3	210	Primary	Classroom 210	W2	Flaking	10	No	No	N/A	Posters, Furniture	No	
26	5260	1	3	210	Primary	Classroom 210	W3	Chipping	10	No	No	N/A	Posters, Furniture	No	
27	5260	1	3	210	Primary	Classroom 210	W4	Chipping	5	No	No	N/A	Posters, Furniture	No	
28	5260	1	3	211	Primary	Classroom 211	Ceiling	Flaking	1	No	No	N/A	Furniture	No	
29	5260	1	3	211	Primary	Classroom 211	W1	Chipping	5	No	No	N/A	Posters, Furniture	No	
30	5260	1	3	211	Primary	Classroom 211	W2	Chipping	15	No	No	N/A	Posters, Furniture	No	
31	5260	1	3	211	Primary	Classroom 211	W3	Cracking	3	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
32	5260	1	3	211	Primary	Classroom 211	W4	Cracking	5	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
33	5260	1	3	212	Primary	Classroom 212	Ceiling	Staining	20	No	No	N/A	Furniture	No	
34	5260	1	3	212	Primary	Classroom 212	W1	Chipping on univent and cabinets	10	No	No	N/A	Posters, Furniture	No	
35	5260	1	3	212	Primary	Classroom 212	W2	Chipping, Flaking, some on cabinets	22	No	No	N/A	Posters, Furniture	No	
36	5260	1	3	212	Primary	Classroom 212	W3	Chipping	10	No	No	N/A	Posters, Furniture	No	
37	5260	1	3	212	Primary	Classroom 212	W4	Chipping	20	No	No	N/A	Posters, Furniture	No	
38	5260	1	3	213	Primary	Classroom 213	Ceiling	Staining, Cracking	15	No	No	N/A	Furniture	No	
39	5260	1	3	213	Primary	Classroom 213	W1	Flaking	10	No	No	N/A	Posters, Furniture	No	
40	5260	1	3	213	Primary	Classroom 213	W4	Chipping on cabinets	5	No	No	N/A	Posters, Furniture	No	
41	5260	1	3	214	Primary	Classroom 214	W1	Chipping	10	No	No	N/A	Posters, Furniture	No	
42	5260	1	3	214	Primary	Classroom 214	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall and wall caulk needed
43	5260	1	3	215	Primary	Classroom 215	W3	Cracking	5	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
44	5260	1	3	215	Primary	Classroom 215	W4	Cracking, Flaking	18	No	No	N/A	Cabinet and shelves	No	Repair to concrete block wall and wall caulk needed
45	5260	1	3	216	Primary	Classroom 216	W3	Cracking, Chipping	13	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
46	5260	1	3	216	Primary	Classroom 216	W4	Cracking, Chipping	13	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall and wall caulk needed
47	5260	1	3	218	Computer - Intermediate Middle	Classroom 218	W1	Cracking	15	No	No	N/A	N/A	No	Repair to concrete block wall and wall caulk needed
48	5260	1	3	218	Computer - Intermediate Middle	Classroom 218	W2	Cracking	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
49	5260	1	3	218	Computer - Intermediate Middle	Classroom 218	W3	Chipping around univent	25	No	No	N/A	N/A	No	
50	5260	1	3	218	Computer - Intermediate Middle	Classroom 218	W4	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
51	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
52	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
53	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
54	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
55	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
56	5260	1	3	219	Storage	Storage Room adjacent to Classroom 218	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
57	5260	1	3	220	Administrative Office	Speech Pathologist Office, Former Men's Lounge	Ceiling	Flaking	2	No	No	N/A	N/A	No	
58	5260	1	3	220	Administrative Office	Speech Pathologist Office, Former Men's Lounge	W3	Cracking	20	No	No	N/A	N/A	No	Repair to wall caulk needed
59	5260	1	3	220	Administrative Office	Speech Pathologist Office, Former Men's Lounge	W4	Cracking	10	No	No	N/A	N/A	No	Repair to wall caulk needed
60	5260	1	3	221	IMC (Library)	IMC	Ceiling	Flaking	100	Yes	No	N/A	Furniture	No	
61	5260	1	3	223	Restrooms, Staff - Male	3rd Floor Men's Restroom	W3	Cracking	4	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
62	5260	1	3	223	Restrooms, Staff - Male	3rd Floor Men's Restroom	W4	Chipping	5	No	No	N/A	N/A	No	
63	5260	1	3	224	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	Ceiling	Cracking, Efflorescence	7	Yes	No	N/A	N/A	Yes	Some damage may be from towels/toilet paper
64	5260	1	3	224	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	W1	Chipping	15	No	No	N/A	N/A	No	
65	5260	1	3	224	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	W3	Chipping	3	No	No	N/A	N/A	No	
66	5260	1	3	224	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	W4	Chipping	2	No	No	N/A	N/A	No	
67	5260	1	3	225	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	Ceiling	Efflorescence	25	Yes	No	N/A	N/A	Yes	Some damage may be from towels/toilet paper
68	5260	1	3	228	Storage	Storage Room across from Classroom 209	W2	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
69	5260	1	3	204A	Primary	Classroom 204A	W3	Cracking	30	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
70	5260	1	3	207A	Primary	Classroom 207A	W2	Chipping on univert	15	No	No	N/A	Stored Materials	No	
71	5260	1	3	207A	Primary	Classroom 207A	W3	Cracking	20	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
72	5260	1	3	207A	Primary	Classroom 207A	W4	Cracking	20	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall and wall caulk needed
73	5260	1	3	211A	Primary	Classroom 211A	W3	Cracking	20	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
74	5260	1	3	211A	Primary	Classroom 211A	W4	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
75	5260	1	3	215A	Primary	Classroom 215A	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
76	5260	1	3	215A	Primary	Classroom 215A	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
77	5260	1	3	215A	Primary	Classroom 215A	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
78	5260	1	3	215A	Primary	Classroom 215A	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
79	5260	1	3	215A	Primary	Classroom 215A	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
80	5260	1	3	215A	Primary	Classroom 215A	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
81	5260	1	3	221A	Administrative Office	IMC Office	W1	Chipping	1	No	No	N/A	N/A	No	
82	5260	1	3	221C	Copying Room	IMC Copy Room	W1	Chipping on doorframe	8	No	No	N/A	N/A	No	
83	5260	1	3	221D	Storage	IMC Storage Room	W1	Cracking	5	No	No	N/A	Stored Materials	No	Entrance from IMC. Repair to concrete block wall needed.
84	5260	1	3	221D	Storage	IMC Storage Room	W2	Cracking	5	No	No	N/A	Stored Materials	No	Repair to concrete block wall needed
85	5260	1	3	221D	Storage	IMC Storage Room	W3	Cracking	15	No	No	N/A	Stored Materials	No	Repair to concrete block wall needed
86	5260	1	3	222A	Restrooms, Staff - Female	3rd Floor Women's Restroom	W3	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
87	5260	1	3	H22	Circulation (Hallway)	Hallway outside Classrooms 217 and 218	Ceiling	Staining	1	No	No	N/A	N/A	No	
88	5260	1	3	H22	Circulation (Hallway)	Hallway outside Classrooms 217 and 218	W2	Flaking	1	No	No	N/A	N/A	No	Repair to wall caulk needed
89	5260	1	3	H22	Circulation (Hallway)	Hallway outside Classrooms 217 and 218	W4	Flaking	2	No	No	N/A	N/A	No	Repair to wall caulk needed
90	5260	1	3	H320	Circulation (Hallway)	Hallway outside Classrooms 209, 212, and 213	Ceiling	Staining	5	No	No	N/A	N/A	No	
91	5260	1	3	H320	Circulation (Hallway)	Hallway outside Classrooms 209, 212, and 213	W3	Flaking	10	No	No	N/A	N/A	No	Repair to wall caulk needed
92	5260	1	3	H321	Circulation (Hallway)	Stairwell 3 Hallway	Ceiling	Staining, Flaking	17	No	No	N/A	N/A	No	
93	5260	1	3	H321	Circulation (Hallway)	Stairwell 3 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
94	5260	1	3	H321	Circulation (Hallway)	Stairwell 3 Hallway	W2	Cracking	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
95	5260	1	3	H321	Circulation (Hallway)	Stairwell 3 Hallway	W4	Cracking	20	No	No	N/A	N/A	No	Repair to concrete block wall needed
96	5260	1	3	H323	Circulation (Hallway)	Stairwell 4 Hallway	Ceiling	Staining	25	No	No	N/A	N/A	No	
97	5260	1	3	H323	Circulation (Hallway)	Stairwell 4 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
98	5260	1	3	H323	Circulation (Hallway)	Stairwell 4 Hallway	W2	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
99	5260	1	3	H323	Circulation (Hallway)	Stairwell 4 Hallway	W4	Cracking, Flaking	12	No	No	N/A	N/A	No	Repair to concrete block wall and wall caulk needed
100	5260	1	3	H324	Circulation (Hallway)	Stairwell 2 Hallway	Ceiling	Staining, Flaking	5	No	No	N/A	N/A	No	
101	5260	1	3	H324	Circulation (Hallway)	Stairwell 2 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
102	5260	1	3	H324	Circulation (Hallway)	Stairwell 2 Hallway	W1	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
103	5260	1	3	H324	Circulation (Hallway)	Stairwell 2 Hallway	W3	Cracking, Flaking	6	No	No	N/A	N/A	No	Repair to concrete block wall and wall caulk needed
104	5260	1	3	H325	Circulation (Hallway)	Lobby outside Stairwell 2 and 3 and IMC	W4	Flaking	1	No	No	N/A	N/A	No	
105	5260	1	3	S31	Stairs	Stairwell 2	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
106	5260	1	3	S32	Stairs	Stairwell 1	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
107	5260	1	3	S32	Stairs	Stairwell 1	W2	Cracking, Flaking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
108	5260	1	3	S32	Stairs	Stairwell 1	W4	Cracking	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
109	5260	1	3	S33	Stairs	Stairwell 3	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
110	5260	1	3	S34	Stairs	Stairwell 4	Floor	Chipping on railing	10	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
111	5260	1	3	S34	Stairs	Stairwell 4	W2	Chipping	5	No	No	N/A	N/A	No	
112	5260	1	2	102	Primary	Classroom 102	Ceiling	Staining	6	No	No	N/A	Furniture	No	
113	5260	1	2	102	Primary	Classroom 102	W1	Cracking on wall, chipping on univent	14	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
114	5260	1	2	102	Primary	Classroom 102	W2	Cracking	25	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
115	5260	1	2	103	Primary	Classroom 103	W4	Cracking on wall, Chipping and Flaking on univent	28	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
116	5260	1	2	104	Primary	Classroom 104	Ceiling	Staining	2	No	No	N/A	Furniture	No	
117	5260	1	2	104	Primary	Classroom 104	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
118	5260	1	2	105	Primary	Classroom 105	W2	Cracking	5	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
119	5260	1	2	105	Primary	Classroom 105	W3	Chipping on cabinet	10	No	No	N/A	Posters, Furniture	No	
120	5260	1	2	105	Primary	Classroom 105	W4	Cracking, Chipping on univent	20	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
121	5260	1	2	106	Primary	Classroom 106	Ceiling	Cracking	5	No	No	N/A	Furniture	No	Repair to concrete ceiling needed
122	5260	1	2	106	Primary	Classroom 106	W4	Cracking	2	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
123	5260	1	2	107	Primary	Classroom 107	Ceiling	Staining	1	No	No	N/A	Furniture	No	
124	5260	1	2	107	Primary	Classroom 107	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
125	5260	1	2	108	Primary	Classroom 108	W1	Chipping on univent	5	No	No	N/A	Posters, Furniture	No	
126	5260	1	2	109	Primary	Classroom 109	Ceiling	Staining	1	No	No	N/A	Furniture	No	
127	5260	1	2	110	Primary	Classroom 110	Ceiling	Flaking	1	No	No	N/A	N/A	No	
128	5260	1	2	110	Primary	Classroom 110	W2	Cracking	3	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
129	5260	1	2	111	Primary	Classroom 111	W1	Chipping on cabinet	10	No	No	N/A	Posters, Furniture	No	
130	5260	1	2	111	Primary	Classroom 111	W2	Cracking on wall, Chipping on cabinet	18	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
131	5260	1	2	112	Primary	Classroom 112	W1	Chipping on univent	5	No	No	N/A	Posters, Furniture	No	
132	5260	1	2	112	Primary	Classroom 112	W2	Cracking	10	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
133	5260	1	2	113	Primary	Classroom 113	W2	Cracking on wall, Chipping on univent	25	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
134	5260	1	2	113	Primary	Classroom 113	W3	Cracking	15	No	No	N/A	Posters, Furniture	No	Repair to concrete block wall needed
135	5260	1	2	114	Primary	Classroom 114	W3	Cracking	35	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
136	5260	1	2	114	Primary	Classroom 114	W4	Cracking	25	No	No	N/A	Posters, Furniture	No	Repair to wall caulk needed
137	5260	1	2	115	Primary	Classroom 115	Ceiling	Staining, Flaking	4	No	No	N/A	N/A	No	
138	5260	1	2	115	Primary	Classroom 115	W1	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
139	5260	1	2	115	Primary	Classroom 115	W3	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
140	5260	1	2	115	Primary	Classroom 115	W4	Staining	2	No	No	N/A	N/A	No	Staining appears to be from some type of fresh oil
141	5260	1	2	116	Primary	Classroom 116	W4	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
142	5260	1	2	117	Administrative Office	Former Principal's Conference Room adjacent to Classroom 116	W1	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
143	5260	1	2	117	Administrative Office	Former Principal's Conference Room adjacent to Classroom 116	W2	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
144	5260	1	2	117	Administrative Office	Former Principal's Conference Room adjacent to Classroom 116	W3	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
145	5260	1	2	118	Administrative Office	Counselor's Office	W2	Cracking	1	No	No	N/A	N/A	No	Repair to wall caulk needed
146	5260	1	2	119	Administrative Office	Counselor's Office	W1	Cracking	4	No	No	N/A	N/A	No	Repair to wall caulk needed
147	5260	1	2	119	Administrative Office	Counselor's Office	W4	Cracking	5	No	No	N/A	N/A	No	Repair to wall caulk needed
148	5260	1	2	120	Administrative Office	School Police Office	W3	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall and wall caulk needed
149	5260	1	2	121	Administrative Office	Main Office	W3	Cracking	20	No	No	N/A	N/A	No	Repair to wall caulk needed
150	5260	1	2	121	Administrative Office	Main Office	W4	Cracking	10	No	No	N/A	N/A	No	Cracking in corner of walls 3&4. Repair to concrete block wall needed.
151	5260	1	2	123	Restrooms, Staff - Female	Women's Lounge outside Restroom	W2	Cracking	2	No	No	N/A	N/A	No	Repair to concrete block wall needed
152	5260	1	2	125	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	W1	Chipping	2	No	No	N/A	N/A	No	
153	5260	1	2	126	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	Ceiling	Efflorescence	2	Yes	No	N/A	N/A	Yes	
154	5260	1	2	126	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	W1	Chipping	40	No	No	N/A	N/A	No	
155	5260	1	2	126	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	W2	Chipping	20	No	No	N/A	N/A	No	
156	5260	1	2	126	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	W3	Chipping	10	No	No	N/A	N/A	No	
157	5260	1	2	126	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	W4	Chipping	10	No	No	N/A	N/A	No	
158	5260	1	2	129	Administrative Office	Office adjacent to Nurse's Office	W1	Chipping, Flaking	2	No	No	N/A	N/A	No	
159	5260	1	2	129	Administrative Office	Office adjacent to Nurse's Office	W2	Chipping	3	No	No	N/A	N/A	No	
160	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
161	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
162	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
163	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
164	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
165	5260	1	2	131	Telecommunication Equipment Room	Telecommunication Equipment Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
166	5260	1	2	132	Mail Room	Mail Room	W1	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
167	5260	1	2	102B	Restrooms, Staff - Male/Female	Classrooms 102 and 103 Staff Restroom	W2	Cracking	8	No	No	N/A	N/A	No	Cracking in corner of walls 1&2. Repair to concrete block wall needed.
168	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
169	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
170	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
171	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
172	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
173	5260	1	2	102C	Storage	Closet between Classrooms 102 and 103	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
174	5260	1	2	103A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W2	Chipping	1	No	No	N/A	N/A	No	
175	5260	1	2	103A	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
176	5260	1	2	104B	Restrooms, Staff - Male/Female	Classrooms 104 and 105 Staff Restroom	W2	Cracking	8	No	No	N/A	N/A	No	Cracking in corner of walls 2&3. Repair to concrete block wall needed.
177	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
178	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
179	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
180	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
181	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
182	5260	1	2	104C	Storage	Closet between Classrooms 104 and 105	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
183	5260	1	2	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Ceiling	Chipping	3	No	No	N/A	N/A	No	
184	5260	1	2	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W2	Cracking, Chipping	5	No	No	N/A	N/A	No	Cracking in corner of walls 2&3. Repair to concrete block wall needed.
185	5260	1	2	110A	Student Restrooms - Male/Female (Classroom)	Classroom 110 Restroom	W1	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
186	5260	1	2	110A	Student Restrooms - Male/Female (Classroom)	Classroom 110 Restroom	W4	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
187	5260	1	2	117A	Administrative Office	Office behind Former Principal's Office Conference Room	Ceiling	Staining	2	No	No	N/A	N/A	No	
188	5260	1	2	117A	Administrative Office	Office behind Former Principal's Office Conference Room	W1	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
189	5260	1	2	117A	Administrative Office	Office behind Former Principal's Office Conference Room	W2	Flaking on univent	2	No	No	N/A	N/A	No	
190	5260	1	2	117A	Administrative Office	Office behind Former Principal's Office Conference Room	W4	Cracking	4	No	No	N/A	N/A	No	Repair to concrete block wall needed
191	5260	1	2	121B	Storage	Main Office Storage Room	W2	Chipping on cabinets	3	No	No	N/A	N/A	No	
192	5260	1	2	121C	Conference Room	Main Office Conference Room	W3	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
193	5260	1	2	121C	Conference Room	Main Office Conference Room	W4	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
194	5260	1	2	121D	Administrative Office	Principal's Office	W3	Cracking	3	No	No	N/A	N/A	No	Repair to wall caulk needed
195	5260	1	2	121E	Administrative Office	Office across from Principal's Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
196	5260	1	2	121E	Administrative Office	Office across from Principal's Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
197	5260	1	2	121E	Administrative Office	Office across from Principal's Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
198	5260	1	2	121E	Administrative Office	Office across from Principal's Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
199	5260	1	2	121E	Administrative Office	Office across from Principal's Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
200	5260	1	2	121E	Administrative Office	Office across from Principal's Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
201	5260	1	2	121H	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
202	5260	1	2	121I	Storage	Principal's Office Small Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
203	5260	1	2	121I	Storage	Principal's Office Small Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
204	5260	1	2	121I	Storage	Principal's Office Small Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
205	5260	1	2	121I	Storage	Principal's Office Small Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
206	5260	1	2	121I	Storage	Principal's Office Small Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
207	5260	1	2	121I	Storage	Principal's Office Small Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
208	5260	1	2	122A	Student Restrooms - Male/Female	Nurse's Office Restroom	W4	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
209	5260	1	2	122C	Health Service Room	Nurse's Office Sink Area	W1	Flaking on cabinet	5	No	No	N/A	N/A	No	
210	5260	1	2	122C	Health Service Room	Nurse's Office Sink Area	W4	Cracking	20	No	No	N/A	N/A	No	Repair to concrete block wall needed
211	5260	1	2	122D	Health Service Room	Nurse's Office	W3	Cracking	11	No	No	N/A	N/A	No	Repair to concrete block wall and wall caulk needed
212	5260	1	2	122E	Health Service Room	Nurse's Office Exam Room	W4	Cracking	12	No	No	N/A	N/A	No	Repair to concrete block wall needed
213	5260	1	2	123A	Restrooms, Staff - Female	2nd Floor Women's Restroom	Ceiling	Spalling	1	Yes	No	N/A	N/A	Yes	
214	5260	1	2	132A	Administrative Office	Office adjacent to Mail Room	W3	Cracking	5	No	No	N/A	N/A	No	Repair to concrete block wall needed
215	5260	1	2	132A	Administrative Office	Office adjacent to Mail Room	W4	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed
216	5260	1	2	132C	Storage	Office adjacent to Mail Room Closet at back of Office	W2	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
217	5260	1	2	132C	Storage	Office adjacent to Mail Room Closet at back of Office	W3	Cracking	2	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
218	5260	1	2	132C	Storage	Office adjacent to Mail Room Closet at back of Office	W4	Cracking, Flaking	30	No	No	N/A	Cabinets	No	Repair to concrete block wall needed
219	5260	1	2	H17	Circulation (Hallway)	Main Lobby	Ceiling	Staining	3	No	No	N/A	N/A	No	
220	5260	1	2	H17	Circulation (Hallway)	Main Lobby	W1	Flaking on caulk	8	No	No	N/A	N/A	No	
221	5260	1	2	H17	Circulation (Hallway)	Main Lobby	W3	Chipping	3	No	No	N/A	N/A	No	
222	5260	1	2	H17A	Circulation (Hallway)	Hallway outside Stairwell 1	W1	Cracking	20	No	No	N/A	N/A	No	Repair to wall caulk needed
223	5260	1	2	H216	Circulation (Hallway)	Hallway from 2nd Floor Women's Restroom to Elevator	Ceiling	Staining	1	No	No	N/A	N/A	No	
224	5260	1	2	H218	Circulation (Hallway)	Hallway outside Classrooms 101-102	W4	Cracking	2	No	No	N/A	N/A	No	Repair to concrete block wall needed
225	5260	1	2	H219	Circulation (Hallway)	Hallway from Elevator to Stairwell 2	Ceiling	Staining	8	No	No	N/A	N/A	No	
226	5260	1	2	H219	Circulation (Hallway)	Hallway from Elevator to Stairwell 2	W1	Chipping	1	No	No	N/A	N/A	No	
227	5260	1	2	H222	Circulation (Hallway)	Stairwell 3 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
228	5260	1	2	H222	Circulation (Hallway)	Stairwell 3 Hallway	W2	Cracking	2	No	No	N/A	N/A	No	Repair to concrete block wall needed
229	5260	1	2	H222	Circulation (Hallway)	Stairwell 3 Hallway	W3	Chipping on doors	3	No	No	N/A	N/A	No	
230	5260	1	2	H222	Circulation (Hallway)	Stairwell 3 Hallway	W4	Chipping on radiator	2	No	No	N/A	N/A	No	
231	5260	1	2	H223	Circulation (Hallway)	Hallway outside Classroom 116 and Office 117	W1	Cracking	16	No	No	N/A	N/A	No	Repair to concrete block wall needed
232	5260	1	2	H223	Circulation (Hallway)	Hallway outside Classroom 116 and Office 117	W3	Cracking	10	No	No	N/A	N/A	No	Repair to wall caulk needed
233	5260	1	2	S21	Stairs	Stairwell 2	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
234	5260	1	2	S21	Stairs	Stairwell 2	W1	Chipping	20	No	No	N/A	N/A	No	
235	5260	1	2	S21	Stairs	Stairwell 2	W3	Chipping	10	No	No	N/A	N/A	No	
236	5260	1	2	S21A	Circulation (Hallway)	Stairwell 2 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
237	5260	1	2	S21A	Circulation (Hallway)	Stairwell 2 Hallway	W1	Cracking on wall, Chipping on radiator	11	No	No	N/A	N/A	No	Repair to concrete block wall needed
238	5260	1	2	S21A	Circulation (Hallway)	Stairwell 2 Hallway	W2	Chipping on doors	5	No	No	N/A	N/A	No	
239	5260	1	2	S21A	Circulation (Hallway)	Stairwell 2 Hallway	W3	Cracking	8	No	No	N/A	N/A	No	
240	5260	1	2	S22	Stairs	Stairwell 1	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
241	5260	1	2	S22	Stairs	Stairwell 1	W2	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
242	5260	1	2	S22	Stairs	Stairwell 1	W4	Cracking	4	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
243	5260	1	2	S23	Stairs	Stairwell 3	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
244	5260	1	2	S24	Stairs	Stairwell 4	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
245	5260	1	2	S24	Stairs	Stairwell 4	W2	Chipping	5	No	No	N/A	N/A	No	
246	5260	1	2	S24	Stairs	Stairwell 4	W4	Chipping	2	No	No	N/A	N/A	No	
247	5260	1	2	S24A	Circulation (Hallway)	Stairwell 4 Hallway	Ceiling	Staining	5	No	No	N/A	N/A	No	
248	5260	1	2	S24A	Circulation (Hallway)	Stairwell 4 Hallway	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
249	5260	1	2	S24A	Circulation (Hallway)	Stairwell 4 Hallway	W2	Cracking, Chipping	12	No	No	N/A	N/A	No	Repair to concrete block wall needed
250	5260	1	2	S24A	Circulation (Hallway)	Stairwell 4 Hallway	W4	Cracking	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
251	5260	1	1	B01	Art - Elementary	Art Room	W1	Cracking, Chipping on door and doorframe	8	No	No	N/A	N/A	No	Repair to concrete block wall needed
252	5260	1	1	B01A	Storage	Art Room Closet by Entrance	W2	Cracking	2	No	No	N/A	N/A	No	Repair to concrete block wall needed
253	5260	1	1	B01A	Storage	Art Room Closet by Entrance	W3	Cracking corner of Walls 3&4	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
254	5260	1	1	B01B	Storage	Art Room Closet by Kiln	W1	Staining, Chipping on doorframe	4	Yes	No	N/A	N/A	No	Staining appears to be from some type of fresh oil
255	5260	1	1	B01B	Storage	Art Room Closet by Kiln	W3	Staining	5	Yes	No	N/A	Metal Shelves	No	Staining appears to be from some type of fresh oil
256	5260	1	1	B01B	Storage	Art Room Closet by Kiln	W4	Staining	5	Yes	No	N/A	Metal Shelves	No	Staining appears to be from some type of fresh oil
257	5260	1	1	B02	Primary	Classroom B02	W1	Chipping on door	10	No	No	N/A	N/A	No	
258	5260	1	1	B02	Primary	Classroom B02	W4	Chipping on door	2	No	No	N/A	N/A	No	
259	5260	1	1	B02A	Storage	Classroom B02 Closet	W1	Chipping on doorframe	N/A	No	No	N/A	N/A	No	
260	5260	1	1	B03	Music	Classroom B03	W1	Chipping on door	15	No	No	N/A	N/A	No	
261	5260	1	1	B03	Music	Classroom B03	W3	Staining, Chipping on door	8	Yes	No	N/A	N/A	No	Staining appears to be from some type of fresh oil
262	5260	1	1	B04	Music	Classroom B04	W2	Chipping on univent cover	2	No	No	N/A	N/A	No	
263	5260	1	1	B05	Auditorium / Cafeteria	Auditorium/Cafeteria	Ceiling	Staining, Flaking	110	No	No	N/A	N/A	No	
264	5260	1	1	B05	Auditorium / Cafeteria	Auditorium/Cafeteria	W1	Chipping doorframe	3	No	No	N/A	N/A	No	
265	5260	1	1	B05	Auditorium / Cafeteria	Auditorium/Cafeteria	W2	Chipping doorframe	3	No	No	N/A	N/A	No	
266	5260	1	1	B05A	Stage	Auditorium Stage	Ceiling	Staining	6	No	No	N/A	N/A	No	
267	5260	1	1	B05A	Stage	Auditorium Stage	W3	Flaking on panel above door	5	No	No	N/A	N/A	No	
268	5260	1	1	B06	Teacher Lounge/Dining	Teacher Lounge	Ceiling	Flaking	5	No	No	N/A	N/A	No	
269	5260	1	1	B07	Kitchen Serving Area	Kitchen Serving Area	W3	Cracking, Chipping some on doorframe	7	No	No	N/A	N/A	No	Repair to concrete block wall needed
270	5260	1	1	B08	Kitchen	Kitchen	W1	Chipping doorframe	2	No	No	N/A	N/A	No	Hallway entrance
271	5260	1	1	B08	Kitchen	Kitchen	W3	Chipping doorframe	3	No	No	N/A	N/A	No	
272	5260	1	1	B08	Kitchen	Kitchen	W4	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
273	5260	1	1	B09	Gymnasium - Intermediate Middle	Gymnasium	Floor	Chipping	20	No	No	N/A	N/A	No	
274	5260	1	1	B09C	Administrative Office	Gym Office	W1	Cracking	6	No	No	N/A	N/A	No	Repair to concrete block wall needed
275	5260	1	1	B09D	Lockers - Male	Boy's Locker Room	Ceiling	Efflorescence	50	Yes	No	N/A	N/A	Yes	
276	5260	1	1	B09D	Lockers - Male	Boy's Locker Room	W1	Flaking, Spalling	10	Yes	No	N/A	N/A	No	
277	5260	1	1	B09F	Restrooms, Staff - Male/Female	Gym Office Restroom	Ceiling	Flaking, Spalling	6	Yes	No	N/A	N/A	Yes	
278	5260	1	1	B09G	Circulation (Hallway)	Vestibule outside Girl's Locker Room	W1	Chipping on door	10	No	No	N/A	N/A	No	
279	5260	1	1	B09G	Circulation (Hallway)	Vestibule outside Girl's Locker Room	W3	Cracking, Chipping, Flaking	17	No	No	N/A	N/A	No	Repair to concrete block wall needed
280	5260	1	1	B09H	Lockers - Female	Girl's Locker Room	Ceiling	Flaking on radiator cover, Spalling, Efflorescence	22	Yes	No	N/A	N/A	Yes	
281	5260	1	1	B09I	Showers - Female	Girl's Locker Room Showers	Ceiling	Efflorescence	1	Yes	No	N/A	Stored Materials	Yes	
282	5260	1	1	B09L	Circulation (Hallway)	Vestibule outside Boy's Locker Room	W1	Chipping on door and frame	5	No	No	N/A	N/A	No	
283	5260	1	1	B09L	Circulation (Hallway)	Vestibule outside Boy's Locker Room	W3	Flaking corner of walls 2&3	5	No	No	N/A	N/A	No	
284	5260	1	1	B10	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	Ceiling	Spalling	15	Yes	No	N/A	N/A	Yes	
285	5260	1	1	B10	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	W1	Chipping	25	No	No	N/A	N/A	No	
286	5260	1	1	B10	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	W3	Chipping	10	No	No	N/A	N/A	No	
287	5260	1	1	B10	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	W4	Chipping	5	No	No	N/A	N/A	No	
288	5260	1	1	B11	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	W1	Chipping	5	No	No	N/A	N/A	No	
289	5260	1	1	B11	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	W2	Chipping	5	No	No	N/A	N/A	No	
290	5260	1	1	B11	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	W3	Chipping	5	No	No	N/A	N/A	No	
291	5260	1	1	B12	Restrooms, Staff - Male	1st Floor Men's Restroom	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
292	5260	1	1	B14A	Restrooms, Staff - Male/Female	Cafeteria Staff Locker Room Restroom	W3	Cracking	8	No	No	N/A	N/A	No	Repair to concrete block wall needed

