

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6220	3	0E	EXT	Exterior	Element 3 Exterior Metal Walls	Walls	Chipping, Flaking	3770	No	No	N/A	N/A	No	
2	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Spalling	8	Yes	No	N/A	N/A	Yes	
3	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipping	1	No	No	N/A	N/A	No	
4	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Spalling	8	Yes	No	N/A	N/A	Yes	
5	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Spalling	17	Yes	No	N/A	N/A	Yes	
6	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Chipping on radiator, Efflorescence	31	Yes	No	N/A	N/A	Yes	
7	6220	1	3	316	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Spalling	16	Yes	No	N/A	N/A	Yes	
8	6220	1	3	301	Primary	Classroom 301	Ceiling	Chipping, Flaking on metal pipe, Efflorescence, all above missing ceiling tile	8	Yes	No	N/A	N/A	Yes	
9	6220	1	3	301	Primary	Classroom 301	W1	Cracking, Flaking behind shelf	13	No	No	N/A	Shelves with stored materials	No	
10	6220	1	3	301	Primary	Classroom 301	W2	Chipping on metal pipe, Flaking behind radiator, Efflorescence	7	Yes	Debris on windowsill	1	Cabinets, Shelves	Yes	
11	6220	1	3	301	Primary	Classroom 301	W3	Chipping, Flaking, some behind shelf	11	No	No	N/A	Shelves with stored materials	No	
12	6220	1	3	301	Primary	Classroom 301	W4	Cracking, Holes, Flaking behind radiators and covers	14	No	Debris on windowsills	5	Shelves with stored materials, Cabinets, Table with computers	Yes	
13	6220	1	3	301A	Storage	Classroom 301 Closet	Ceiling	Cracking, Flaking, Efflorescence	17	Yes	No	N/A	N/A	Yes	
14	6220	1	3	301A	Storage	Classroom 301 Closet	Floor	N/A	N/A	No	Paint chips in corner of walls 3&4	2	N/A	No	
15	6220	1	3	301A	Storage	Classroom 301 Closet	W1	Cracking, Holes, Flaking	109	No	No	N/A	Shelves with stored materials	Yes	Entrance from classroom
16	6220	1	3	301A	Storage	Classroom 301 Closet	W3	Cracking, Chipping, Holes, Flaking, Spalling	118	Yes	No	N/A	Cabinets, Stored Materials	Yes	
17	6220	1	3	301A	Storage	Classroom 301 Closet	W4	Cracking, Hole, Flaking on wall and behind radiator and cover	38	No	No	N/A	Stored Materials	Yes	
18	6220	1	3	301B		Classroom 301 Closet Storage Closet	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	
19	6220	1	3	301B		Classroom 301 Closet Storage Closet	W2	Cracking, Flaking on metal pipe	11	No	No	N/A	Built in shelves with stored materials	Yes	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
20	6220	1	3	301B		Classroom 301 Closet Storage Closet	W3	Cracking	25	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
21	6220	1	3	301B		Classroom 301 Closet Storage Closet	W4	Cracking	20	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
22	6220	1	3	302	Primary	Classroom 302	Ceiling	Cracking	10	No	No	N/A	N/A	No	
23	6220	1	3	302	Primary	Classroom 302	W1	Cracking, Chipping	13	No	No	N/A	N/A	Yes	
24	6220	1	3	302	Primary	Classroom 302	W2	Cracking, Chipping, Holes	22	No	No	N/A	N/A	Yes	
25	6220	1	3	302	Primary	Classroom 302	W3	Cracking	8	No	No	N/A	N/A	No	
26	6220	1	3	302	Primary	Classroom 302	W4	Chipping, Hole	8	No	No	N/A	N/A	Yes	
27	6220	1	3	302A	Storage	Classroom 302 Closet	W2	Cracking, Coat hooks pulling off wall	18	No	Debris on hooks	5	Shelf, Cabinet, Stored Materials	Yes	
28	6220	1	3	302A	Storage	Classroom 302 Closet	W3	Cracking, Flaking behind radiator and cover	16	No	No	N/A	N/A	No	
29	6220	1	3	302A	Storage	Classroom 302 Closet	W4	Cracking, Coat hooks pulling off wall	35	No	Debris on hooks	6	N/A	Yes	
30	6220	1	3	304	Primary	Classroom 304	Ceiling	Cracking	15	No	No	N/A	N/A	No	
31	6220	1	3	304	Primary	Classroom 304	W1	Cracking, Chipping, Flaking	21	No	No	N/A	Furniture, Posters	No	
32	6220	1	3	304	Primary	Classroom 304	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials, Posters	No	Limited inspection due to stored materials
33	6220	1	3	304	Primary	Classroom 304	W3	Chipping, Holes, Flaking behind radiator	14	No	Debris on windowsill	1	Shelves, Stored Materials, Posters	Yes	
34	6220	1	3	304	Primary	Classroom 304	W4	Cracking	26	No	No	N/A	Furniture, Posters	No	
35	6220	1	3	304A	Storage	Classroom 304 Closet	Ceiling	Cracking, Chipping above missing ceiling tile	10	No	No	N/A	N/A	No	
36	6220	1	3	304A	Storage	Classroom 304 Closet	W2	Coat hooks pulling off wall	24	No	No	N/A	Stored Materials	Yes	
37	6220	1	3	304A	Storage	Classroom 304 Closet	W3	Cracking, Chipping on metal pipe, Hole, Flaking behind radiator and cover	5	No	Debris on windowsill	3	Stored Materials	Yes	Limited inspection due to stored materials
38	6220	1	3	304A	Storage	Classroom 304 Closet	W4	Chipping, Coat hooks pulling off wall	17	No	No	N/A	Stored Materials	Yes	
39	6220	1	3	305	Primary	Classroom 305	W1	Chipping, Hole	10	No	No	N/A	Posters	Yes	
40	6220	1	3	305	Primary	Classroom 305	W2	Cracking, Chipping	12	No	No	N/A	Posters	Yes	
41	6220	1	3	305	Primary	Classroom 305	W3	Cracking behind radiator, Chipping, Hole, Flaking behind radiator	11	No	Debris on windowsills	2	Shelves with stored materials, Posters	Yes	
42	6220	1	3	305	Primary	Classroom 305	W4	Chipping	11	No	No	N/A	N/A	No	
43	6220	1	3	305A	Storage	Classroom 305 Closet	W1	Chipping, Coat hooks pulling off wall	13	No	No	N/A	N/A	Yes	
44	6220	1	3	305A	Storage	Classroom 305 Closet	W2	Chipping	4	No	No	N/A	Cabinets	No	
45	6220	1	3	305A	Storage	Classroom 305 Closet	W3	Coat hooks pulling off wall	16	No	Debris on hooks	1	Cabinets	Yes	
46	6220	1	3	305A	Storage	Classroom 305 Closet	W4	Hole	1	No	Debris on windowsill	2	Cabinets	Yes	Limited inspection due to stored materials
47	6220	1	3	306	Primary	Classroom 306	Ceiling	Cracking, Hole, paint has been stabilized	11	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
48	6220	1	3	306	Primary	Classroom 306	W1	Cracking, Chipping	18	No	No	N/A	Desks	No	
49	6220	1	3	306	Primary	Classroom 306	W2	Cracking, Gouge	6	No	No	N/A	Shelf, Desk	Yes	
50	6220	1	3	306	Primary	Classroom 306	W3	Chipping, Holes behind radiator and cover	8	No	No	N/A	Shelf, Desks, Table with computers	Yes	
51	6220	1	3	306	Primary	Classroom 306	W4	Cracking, Chipping	7	No	No	N/A	Furniture, Stored Materials	No	
52	6220	1	3	306A	Storage	Classroom 306 Closet	W2	Cracking, Coat hooks pulling off wall	45	No	No	N/A	N/A	Yes	
53	6220	1	3	306A	Storage	Classroom 306 Closet	W3	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
54	6220	1	3	306A	Storage	Classroom 306 Closet	W4	Coat hooks pulling off wall	20	No	No	N/A	Cabinets	Yes	
55	6220	1	3	307	Primary	Classroom 307	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	
56	6220	1	3	307	Primary	Classroom 307	W1	Chipping, Staples and Holes	75	No	No	N/A	N/A	Yes	
57	6220	1	3	307	Primary	Classroom 307	W2	Cracking, some behind radiator, Chipping, Staples and Staple Holes, Spalling	98	Yes	No	N/A	Shelves, Stored Materials	Yes	
58	6220	1	3	307	Primary	Classroom 307	W3	Staples and Staple Holes	100	No	No	N/A	Table with computers	Yes	
59	6220	1	3	307	Primary	Classroom 307	W4	Chipping, Staples and Staple Holes	169	No	No	N/A	Cabinet	Yes	
60	6220	1	3	307A	Storage	Classroom 307 Closet	W2	Cracking, Coat hooks pulling off wall	18	No	No	N/A	N/A	Yes	
61	6220	1	3	307A	Storage	Classroom 307 Closet	W4	Coat hooks pulling off wall	8	No	Debris on hooks	1	Cabinet, Stored Materials	Yes	Limited inspection due to stored materials
62	6220	1	3	310	Primary	Classroom 310	W1	Chipping	10	No	No	N/A	N/A	No	
63	6220	1	3	310	Primary	Classroom 310	W3	Chipping, Hole from missing wood trim, Flaking on wall and behind radiators	25	No	Debris on windowsills	1	Cabinet	Yes	
64	6220	1	3	310	Primary	Classroom 310	W4	Cracking, Chipping	7	No	No	N/A	N/A	Yes	
65	6220	1	3	310A	Storage	Classroom 310 Closet	W2	Cracking	25	No	No	N/A	Cabinet	No	
66	6220	1	3	310A	Storage	Classroom 310 Closet	W3	Cracking, Flaking in air shaft	5	No	No	N/A	N/A	No	
67	6220	1	3	310A	Storage	Classroom 310 Closet	W4	Cracking	25	No	No	N/A	Desks	No	
68	6220	1	3	311	Primary	Classroom 311	W1	Chipping, Holes, Flaking	38	No	No	N/A	N/A	Yes	
69	6220	1	3	311	Primary	Classroom 311	W2	Chipping, Holes	21	No	No	N/A	N/A	Yes	
70	6220	1	3	311	Primary	Classroom 311	W3	Chipping on wall and radiators, Flaking behind radiator	49	No	No	N/A	N/A	No	
71	6220	1	3	311	Primary	Classroom 311	W4	Chipping, Staple Holes	7	No	No	N/A	N/A	Yes	
72	6220	1	3	311A	Storage	Classroom 311 Closet	W2	Cracking, Chipping, Coat hooks pulling off wall	24	No	No	N/A	N/A	Yes	
73	6220	1	3	311A	Storage	Classroom 311 Closet	W3	Flaking in air shaft	3	No	No	N/A	Cabinet	No	
74	6220	1	3	311A	Storage	Classroom 311 Closet	W4	Cracking, Coat hooks pulling off wall	22	No	No	N/A	N/A	Yes	
75	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	Ceiling	Flaking, Significant Moisture Damage	29	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
76	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	Floor	N/A	N/A	No	Paint chips towards rear	5	N/A	No	
77	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	W1	Cracking	15	No	No	N/A	N/A	No	
78	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	W2	Cracking, Chipping, Holes, Flaking, Significant Moisture Damage	86	Yes	No	N/A	N/A	Yes	
79	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	W3	Flaking, Significant Moisture Damage	28	Yes	Debris on shelves	20	Built in shelves	Yes	
80	6220	1	3	318	Service Closets	Custodial Closet next to Storage Room 308	W4	Cracking, Flaking	34	No	No	N/A	N/A	No	
81	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	Ceiling	Hole, Flaking	80	No	No	N/A	N/A	No	Repair to concrete needed
82	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	Floor	N/A	N/A	No	No	180	N/A	No	
83	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	W1	Chipping on door and doorframe, Flaking on wall, door, and doorframe	161	No	No	N/A	N/A	No	
84	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	W2	Flaking on wall, bars, metal pipe, door, and doorframe	207	No	No	N/A	N/A	No	
85	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	W3	Flaking on wall, bars, and window frames	490	No	No	N/A	N/A	No	
86	6220	1	3	FT3	Stairs	Fire Tower Stairs near Storage Room 308	W4	Flaking on wall and window frames	109	No	No	N/A	N/A	No	
87	6220	1	3	313	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Spalling	12	Yes	No	N/A	N/A	Yes	
88	6220	1	3	313	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Spalling	4	Yes	No	N/A	N/A	Yes	
89	6220	1	3	313	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Cracking	10	No	No	N/A	N/A	Yes	
90	6220	1	3	313	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Cracking, Spalling	4	Yes	No	N/A	N/A	Yes	
91	6220	1	3	313	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Cracking, Efflorescence	16	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
92	6220	1	3	C301	Circulation (Hallway)	Hallway from Classrooms 302 to 307	Floor	Chipping	74	No	No	N/A	N/A	No	
93	6220	1	3	C301	Circulation (Hallway)	Hallway from Classrooms 302 to 307	W1	Cracking	30	No	No	N/A	N/A	No	
94	6220	1	3	C301	Circulation (Hallway)	Hallway from Classrooms 302 to 307	W3	Cracking, Chipping on wall, radiator covers, and electrical panel, Holes, paint has been stabilized on 2	55	No	No	N/A	N/A	Yes	
95	6220	1	3	C300	Circulation (Hallway)	Hallway from Storage Room 308 to Fire Tower	Ceiling	Chipping	6	No	No	N/A	N/A	No	
96	6220	1	3	C300	Circulation (Hallway)	Hallway from Storage Room 308 to Fire Tower	W2	Cracking, Chipping on radiator, Flaking on radiator shield, Efflorescence	22	Yes	No	N/A	Cabinets	Yes	
97	6220	1	3	C300	Circulation (Hallway)	Hallway from Storage Room 308 to Fire Tower	W4	Cracking	25	No	No	N/A	N/A	No	
98	6220	1	3	303	IMC (Library)	IMC 303	Ceiling	Cracking	10	No	No	N/A	N/A	No	
99	6220	1	3	303	IMC (Library)	IMC 303	W1	Cracking, Chipping, Hole	9	No	No	N/A	Shelves	Yes	
100	6220	1	3	303	IMC (Library)	IMC 303	W2	Staple Holes	17	No	No	N/A	Shelves	Yes	
101	6220	1	3	303	IMC (Library)	IMC 303	W3	Chipping, Holes, Flaking behind radiator and cover	8	No	No	N/A	Shelves	Yes	
102	6220	1	3	303	IMC (Library)	IMC 303	W4	N/A	N/A	No	No	N/A	Shelves	No	Limited inspection due to stored materials
103	6220	1	3	303A	Storage	IMC Closet	Ceiling	Chipping above missing ceiling tile	3	No	No	N/A	Stored Books	No	
104	6220	1	3	303A	Storage	IMC Closet	Floor	N/A	N/A	No	Debris along wall 3	3	Stored Books	No	
105	6220	1	3	303A	Storage	IMC Closet	W1	Cracking	1	No	No	N/A	Stored Books	No	
106	6220	1	3	303A	Storage	IMC Closet	W2	Cracking, Chipping, Flaking, Coat hooks pulling off wall	28	No	No	N/A	Stored Books	Yes	
107	6220	1	3	303A	Storage	IMC Closet	W3	Cracking, Flaking	8	No	No	N/A	Stored Books	No	
108	6220	1	3	303A	Storage	IMC Closet	W4	Cracking, Gouge, Flaking, Coat hooks pulling off wall	35	No	No	N/A	Stored Books	Yes	
109	6220	1	3	308A	Administrative Office	Speech Office 308A	Floor	N/A	N/A	No	Debris in corner of walls 3&4	1	N/A	No	
110	6220	1	3	308A	Administrative Office	Speech Office 308A	W1	N/A	N/A	No	Debris on chair rail	3	Cabinets	No	
111	6220	1	3	308A	Administrative Office	Speech Office 308A	W2	N/A	N/A	No	No	N/A	Furniture, Posters	No	Limited inspection due to stored materials
112	6220	1	3	308A	Administrative Office	Speech Office 308A	W3	Chipping on radiator, Hole behind radiator	8	No	Debris on windowsill	1	N/A	Yes	
113	6220	1	3	308A	Administrative Office	Speech Office 308A	W4	Chipping	2	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
114	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	Ceiling	Efflorescence	6	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
115	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	Floor	Chipping on stairs, cove, and railings	48	No	No	N/A	N/A	No	
116	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	W1	Cracking	20	No	No	N/A	N/A	No	
117	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	W2	Cracking	10	No	No	N/A	N/A	No	
118	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	W3	Cracking, Hole, paint has been stabilized, Efflorescence	12	Yes	No	N/A	N/A	Yes	
119	6220	1	3	S3B	Stairs	Stairwell across from Storage Room 308	W4	Chipping on doors and doorframe	29	No	No	N/A	N/A	No	
120	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	Ceiling	Spalling	12	Yes	No	N/A	N/A	Yes	
121	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	Floor	Chipping	18	No	No	N/A	N/A	No	
122	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	W1	Cracking	20	No	No	N/A	N/A	No	
123	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	W2	Chipping on doors and doorframe, Hole, paint has been stabilized, Spalling	33	Yes	No	N/A	N/A	Yes	
124	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	W3	Hole, Spalling	5	Yes	No	N/A	N/A	Yes	
125	6220	1	3	S3C	Stairs	Stairwell next to Classroom 301	W4	Efflorescence	1	Yes	No	N/A	N/A	Yes	
126	6220	1	3	317	Storage	Storage Closet next to Office 308A	Ceiling	Flaking on ceiling and ACM pipe insulation, Holes	20	No	No	N/A	N/A	No	Repair to concrete needed
127	6220	1	3	317	Storage	Storage Closet next to Office 308A	W1	Efflorescence	3	Yes	No	N/A	N/A	Yes	
128	6220	1	3	317	Storage	Storage Closet next to Office 308A	W2	Cracking, Flaking, Mold	85	No	Debris on shelves	3	Built in shelves, Stored Materials	No	
129	6220	1	3	317	Storage	Storage Closet next to Office 308A	W3	Chipping on radiator, Holes behind radiator, Efflorescence	9	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
130	6220	1	3	317	Storage	Storage Closet next to Office 308A	W4	Chipping	3	No	No	N/A	Built in shelves, Stored Materials	No	
131	6220	1	3	308	Administrative Office	Storage Room 308	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
132	6220	1	3	308	Administrative Office	Storage Room 308	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
133	6220	1	3	308	Administrative Office	Storage Room 308	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
134	6220	1	3	308	Administrative Office	Storage Room 308	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
135	6220	1	3	308	Administrative Office	Storage Room 308	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
136	6220	1	3	308	Administrative Office	Storage Room 308	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
137	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
138	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
139	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
140	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
141	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
142	6220	1	3	308B	Administrative Office	Storage Room 308 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This is PSSA storage room. This space will need to be inspected
143	6220	1	3	309	Primary	Storage Room 309	Ceiling	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
144	6220	1	3	309	Primary	Storage Room 309	Floor	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
145	6220	1	3	309	Primary	Storage Room 309	W1	Chipping	6	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
146	6220	1	3	309	Primary	Storage Room 309	W2	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
147	6220	1	3	309	Primary	Storage Room 309	W3	Chipping	3	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
148	6220	1	3	309	Primary	Storage Room 309	W4	Chipping	4	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
149	6220	1	3	309A	Storage	Storage Room 309 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
150	6220	1	3	309A	Storage	Storage Room 309 Closet	Floor	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
151	6220	1	3	309A	Storage	Storage Room 309 Closet	W1	N/A	N/A	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
152	6220	1	3	309A	Storage	Storage Room 309 Closet	W2	Chipping	1	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
153	6220	1	3	309A	Storage	Storage Room 309 Closet	W3	Cracking, Hole	16	No	No	N/A	Stored Furniture throughout	Yes	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
154	6220	1	3	309A	Storage	Storage Room 309 Closet	W4	Cracking, Chipping	30	No	No	N/A	Stored Furniture throughout	No	Limited inspection due to stored materials
155	6220	1	3	314	Teacher Lounge/Dining	Teacher's Lounge	Ceiling	Flaking, Efflorescence above windows	10	Yes	No	N/A	N/A	Yes	
156	6220	1	3	314	Teacher Lounge/Dining	Teacher's Lounge	W1	Hole from missing wood trim	1	No	No	N/A	N/A	No	
157	6220	1	3	314	Teacher Lounge/Dining	Teacher's Lounge	W3	Chipping on radiator	6	No	Debris on windowsills	6	N/A	No	
158	6220	1	3	314B	Storage	Teacher's Lounge Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
159	6220	1	3	314B	Storage	Teacher's Lounge Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
160	6220	1	3	314B	Storage	Teacher's Lounge Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
161	6220	1	3	314B	Storage	Teacher's Lounge Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
162	6220	1	3	314B	Storage	Teacher's Lounge Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
163	6220	1	3	314B	Storage	Teacher's Lounge Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
164	6220	1	3	314A	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	Ceiling	Cracking	4	No	No	N/A	N/A	No	
165	6220	1	3	314A	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	W2	Efflorescence in air shaft	8	Yes	No	N/A	N/A	Yes	
166	6220	1	2	212G	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipping, Holes, Spalling	8	No	Debris under radiator and cover	3	N/A	No	
167	6220	1	2	212G	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Cracking, Spalling	21	Yes	No	N/A	N/A	Yes	
168	6220	1	2	212G	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Spalling	2	Yes	No	N/A	N/A	Yes	
169	6220	1	2	201	Computer - Intermediate Middle	Classroom 201	W1	Chipping, Flaking	15	No	No	N/A	Table with computers	No	
170	6220	1	2	201	Computer - Intermediate Middle	Classroom 201	W2	Cracking, Chipping, Holes	55	No	No	N/A	Furniture	Yes	
171	6220	1	2	201	Computer - Intermediate Middle	Classroom 201	W3	Cracking, Chipping, Hole, Flaking on wall and behind radiator cover, Efflorescence, Significant Moisture Damage behind radiator	87	Yes	No	N/A	Stored Materials	Yes	
172	6220	1	2	201	Computer - Intermediate Middle	Classroom 201	W4	Cracking	50	No	No	N/A	Stored Materials	Yes	
173	6220	1	2	201A		Classroom 201 Center Closet	Ceiling	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
174	6220	1	2	201A		Classroom 201 Center Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
175	6220	1	2	201A		Classroom 201 Center Closet	W1	Chipping on doorframe	6	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
176	6220	1	2	201A		Classroom 201 Center Closet	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
177	6220	1	2	201A		Classroom 201 Center Closet	W3	Cracking	4	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
178	6220	1	2	201A		Classroom 201 Center Closet	W4	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
179	6220	1	2	201B		Classroom 201 Closet near Windows	W3	Cracking	10	No	No	N/A	N/A	No	
180	6220	1	2	202	Primary	Classroom 202	W1	Chipping	2	No	No	N/A	Posters, Books	No	
181	6220	1	2	202	Primary	Classroom 202	W2	Chipping	3	No	No	N/A	Posters, Stored Materials, Furniture	No	
182	6220	1	2	202	Primary	Classroom 202	W3	Cracking	30	No	No	N/A	Posters, Stored Materials, Furniture	No	
183	6220	1	2	202	Primary	Classroom 202	W4	Chipping, Flaking behind radiator, Efflorescence	17	Yes	No	N/A	Posters, Stored Materials, Furniture	Yes	
184	6220	1	2	202A	Storage	Classroom 202 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
185	6220	1	2	202A	Storage	Classroom 202 Closet	W2	Coat hooks pulling off wall	12	No	No	N/A	Stored Materials	Yes	
186	6220	1	2	202A	Storage	Classroom 202 Closet	W3	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
187	6220	1	2	202A	Storage	Classroom 202 Closet	W4	Chipping	3	No	No	N/A	Stored Materials	No	
188	6220	1	2	203	Primary	Classroom 203	W1	Chipping	5	No	No	N/A	Furniture, Stored Materials	No	
189	6220	1	2	203	Primary	Classroom 203	W2	N/A	N/A	No	No	N/A	Posters, Stored Materials	No	Limited inspection due to stored materials
190	6220	1	2	203	Primary	Classroom 203	W3	Chipping, Staple Holes, Flaking on wall and behind radiator, Efflorescence	27	Yes	Debris on windowsills	2	Posters, Cabinet, Shelf	Yes	
191	6220	1	2	203	Primary	Classroom 203	W4	Staple Holes	10	No	No	N/A	Posters, Stored Materials	Yes	
192	6220	1	2	203A	Storage	Classroom 203 Closet	W2	Holes, Flaking, Coat hooks pulling off wall	13	No	No	N/A	Shelves with stored materials	Yes	
193	6220	1	2	203A	Storage	Classroom 203 Closet	W3	Chipping, Flaking, Significant Moisture Damage behind radiator and cover	19	Yes	Debris on windowsills and inside radiator cover	3	N/A	Yes	
194	6220	1	2	203A	Storage	Classroom 203 Closet	W4	Chipping, Holes, Flaking, Coat hooks pulling off wall	18	No	No	N/A	N/A	Yes	
195	6220	1	2	204	Primary	Classroom 204	W1	Cracking, Chipping, Hole, Flaking	21	No	No	N/A	Posters	Yes	
196	6220	1	2	204	Primary	Classroom 204	W2	Chipping on wall and metal pipe, Gouge	5	No	No	N/A	Furniture	Yes	
197	6220	1	2	204	Primary	Classroom 204	W3	Chipping, Significant Moisture Damage behind radiator	23	Yes	No	N/A	Furniture	Yes	
198	6220	1	2	204	Primary	Classroom 204	W4	Chipping on wall and metal pipe, Hole	5	No	No	N/A	Furniture	Yes	
199	6220	1	2	204A	Storage	Classroom 204 Closet	Ceiling	Hole, Flaking, Efflorescence, all above missing ceiling tiles	13	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
200	6220	1	2	204A	Storage	Classroom 204 Closet	W2	Chipping, Hole above missing ceiling tile, Flaking	7	No	No	N/A	N/A	Yes	
201	6220	1	2	204A	Storage	Classroom 204 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
202	6220	1	2	204A	Storage	Classroom 204 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	24	No	No	N/A	N/A	Yes	
203	6220	1	2	205	Primary	Classroom 205	Floor	N/A	N/A	No	Paint chips scattered along wall 3	5	N/A	No	
204	6220	1	2	205	Primary	Classroom 205	W1	Chipping, Staple Holes	49	No	No	N/A	N/A	Yes	
205	6220	1	2	205	Primary	Classroom 205	W2	Chipping, Staple Holes	33	No	No	N/A	Furniture	Yes	
206	6220	1	2	205	Primary	Classroom 205	W3	Chipping, Staple Holes, Efflorescence on wall and behind radiator	33	Yes	Debris on windowsills and inside radiator cover	11	Shelf	Yes	
207	6220	1	2	205	Primary	Classroom 205	W4	Chipping, Staple Holes	35	No	No	N/A	Posters, Cabinet	Yes	
208	6220	1	2	205A	Storage	Classroom 205 Closet	Floor	N/A	N/A	No	Debris behind radiator	2	N/A	No	
209	6220	1	2	205A	Storage	Classroom 205 Closet	W1	Coat hooks pulling off wall	6	No	No	N/A	Shelf, Stored Materials	Yes	
210	6220	1	2	205A	Storage	Classroom 205 Closet	W3	Flaking, Coat hooks pulling off wall	17	No	No	N/A	Shelf, Stored Materials	Yes	
211	6220	1	2	205A	Storage	Classroom 205 Closet	W4	Flaking behind radiator and cover	4	No	Debris on windowsill	2	N/A	No	
212	6220	1	2	206	Primary	Classroom 206	Ceiling	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
213	6220	1	2	206	Primary	Classroom 206	Floor	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
214	6220	1	2	206	Primary	Classroom 206	W1	Cracking, Chipping, Hole, Flaking	69	No	No	N/A	Furniture, Stored Materials, Posters	Yes	Limited inspection due to stored materials
215	6220	1	2	206	Primary	Classroom 206	W2	N/A	N/A	No	No	N/A	Furniture, Stored Materials, Posters	No	Limited inspection due to stored materials
216	6220	1	2	206	Primary	Classroom 206	W3	Flaking	2	No	No	N/A	Furniture, Stored Materials, Posters	No	Limited inspection due to stored materials
217	6220	1	2	206	Primary	Classroom 206	W4	N/A	N/A	No	No	N/A	Furniture, Stored Materials, Posters	No	Limited inspection due to stored materials
218	6220	1	2	206A	Storage	Classroom 206 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
219	6220	1	2	206A	Storage	Classroom 206 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
220	6220	1	2	206A	Storage	Classroom 206 Closet	W1	Cracking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
221	6220	1	2	206A	Storage	Classroom 206 Closet	W2	Cracking, Chipping, Coat hooks pulling off wall	24	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
222	6220	1	2	206A	Storage	Classroom 206 Closet	W3	Flaking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
223	6220	1	2	206A	Storage	Classroom 206 Closet	W4	Coat hooks pulling off wall	6	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
224	6220	1	2	207	Primary	Classroom 207	W1	Cracking, Chipping, Staple Holes	27	No	No	N/A	Posters, Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
225	6220	1	2	207	Primary	Classroom 207	W2	Chipping, Staple Holes, Spalling, Efflorescence, Significant Moisture Damage behind radiator	40	Yes	Debris on windowsills	5	Furniture, Stored Materials	Yes	Some damage has been repaired but is returning
226	6220	1	2	207	Primary	Classroom 207	W3	Staple Holes, Flaking, Efflorescence	52	Yes	No	N/A	Furniture, Stored Materials	Yes	
227	6220	1	2	207	Primary	Classroom 207	W4	Chipping, Staple Holes	165	No	No	N/A	Furniture, Stored Materials	Yes	
228	6220	1	2	207A	Storage	Classroom 207 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
229	6220	1	2	207A	Storage	Classroom 207 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
230	6220	1	2	207A	Storage	Classroom 207 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
231	6220	1	2	207A	Storage	Classroom 207 Closet	W2	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
232	6220	1	2	207A	Storage	Classroom 207 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
233	6220	1	2	207A	Storage	Classroom 207 Closet	W4	Cracking, Chipping	22	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
234	6220	1	2	208	Primary	Classroom 208	W1	Cracking, Chipping	71	No	No	N/A	N/A	No	
235	6220	1	2	208	Primary	Classroom 208	W2	Cracking, Flaking	95	No	No	N/A	N/A	No	
236	6220	1	2	208	Primary	Classroom 208	W3	Chipping, Holes, Flaking on wall and behind radiator	24	No	Debris on windowsill	1	Furniture	Yes	
237	6220	1	2	208	Primary	Classroom 208	W4	Cracking, Flaking	81	No	No	N/A	Furniture	No	
238	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	Ceiling	Chipping above missing ceiling tile	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
239	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	Floor	N/A	N/A	No	Debris inside radiator cover	3	Stored Materials	No	Limited inspection due to stored materials
240	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	W1	Chipping, Coat hooks pulling off wall	38	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
241	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	W2	Cracking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
242	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	W3	Chipping	50	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
243	6220	1	2	2082	Primary	Classroom 208 Closet on exterior wall	W4	Chipping, Holes, Efflorescence	12	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
244	6220	1	2	2081	Primary	Classroom 208 Closet on hall wall	Ceiling	Cracking	13	No	No	N/A	N/A	Yes	
245	6220	1	2	2081	Primary	Classroom 208 Closet on hall wall	W2	Cracking, Chipping	12	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
246	6220	1	2	2081	Primary	Classroom 208 Closet on hall wall	W3	Cracking, Gouge	16	No	No	N/A	Built in shelves with stored materials	Yes	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
247	6220	1	2	2081	Primary	Classroom 208 Closet on hall wall	W4	Cracking	3	No	Debris on shelves	2	Built in shelves with stored materials	Yes	Limited inspection due to stored materials
248	6220	1	2	209	Primary	Classroom 209	Ceiling	Efflorescence above windows	15	Yes	No	N/A	N/A	Yes	
249	6220	1	2	209	Primary	Classroom 209	W1	Chipping, Staples and Staple Holes	139	No	No	N/A	N/A	Yes	
250	6220	1	2	209	Primary	Classroom 209	W3	Chipping, Flaking, Efflorescence	58	Yes	Debris on windowsills	16	Shelf	Yes	
251	6220	1	2	209	Primary	Classroom 209	W4	Chipping, Staples and Staple Holes, Flaking	86	No	No	N/A	N/A	Yes	
252	6220	1	2	209A	Storage	Classroom 209 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
253	6220	1	2	209A	Storage	Classroom 209 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
254	6220	1	2	209A	Storage	Classroom 209 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
255	6220	1	2	209A	Storage	Classroom 209 Closet	W2	Chipping	17	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
256	6220	1	2	209A	Storage	Classroom 209 Closet	W3	Chipping, Holes	33	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
257	6220	1	2	209A	Storage	Classroom 209 Closet	W4	Chipping, Hole, Coat hooks pulling off wall	31	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
258	6220	1	2	210	Primary	Classroom 210	W1	Cracking, Chipping	35	No	No	N/A	N/A	No	
259	6220	1	2	210	Primary	Classroom 210	W3	Chipping	5	No	Debris on windowsills	2	N/A	No	
260	6220	1	2	210	Primary	Classroom 210	W4	Chipping	7	No	No	N/A	N/A	No	
261	6220	1	2	210A	Storage	Classroom 210 Closet	Ceiling	Cracking above missing ceiling tile	2	No	No	N/A	N/A	No	
262	6220	1	2	210A	Storage	Classroom 210 Closet	W1	Cracking	2	No	No	N/A	N/A	No	
263	6220	1	2	210A	Storage	Classroom 210 Closet	W2	Cracking, Chipping, Coat hooks pulling off wall	54	No	No	N/A	Cabinet, Shelf, Stored Materials	Yes	
264	6220	1	2	210A	Storage	Classroom 210 Closet	W3	Cracking, Chipping	11	No	No	N/A	N/A	No	
265	6220	1	2	210A	Storage	Classroom 210 Closet	W4	Cracking, Chipping, Flaking, Spalling above missing ceiling tile	69	Yes	No	N/A	N/A	Yes	
266	6220	1	2	211	Primary	Classroom 211	W1	Chipping, Staple Holes	67	No	No	N/A	Posters, Furniture	Yes	
267	6220	1	2	211	Primary	Classroom 211	W2	Cracking, Staple Holes	25	No	No	N/A	Posters, Furniture	Yes	
268	6220	1	2	211	Primary	Classroom 211	W3	Chipping, Staple Holes	12	No	Debris on windowsills	2	Furniture, Stored Materials	Yes	
269	6220	1	2	211	Primary	Classroom 211	W4	Chipping, Staple Holes, Flaking	9	No	No	N/A	Posters, Furniture	Yes	
270	6220	1	2	211A	Storage	Classroom 211 Closet	W2	Cracking, Chipping, Coat hooks pulling off wall	14	No	No	N/A	N/A	Yes	
271	6220	1	2	211A	Storage	Classroom 211 Closet	W3	Cracking, Flaking	27	No	No	N/A	N/A	No	
272	6220	1	2	211A	Storage	Classroom 211 Closet	W4	Cracking, Coat hooks pulling off wall	80	No	No	N/A	N/A	Yes	
273	6220	2	2	213	Primary	Classroom 213	Ceiling	Flaking, Efflorescence above windows	11	Yes	No	N/A	N/A	Yes	
274	6220	2	2	213	Primary	Classroom 213	W1	Chipping, Staples	93	No	No	N/A	Furniture	Yes	
275	6220	2	2	213	Primary	Classroom 213	W2	Chipping, Staples	81	No	No	N/A	Furniture	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
276	6220	2	2	213	Primary	Classroom 213	W3	Chipping on wall and behind radiator, Staples, Flaking on wall and behind radiator	56	No	Paint chips on windowsills	8	Tables with computers, Furniture	Yes	
277	6220	2	2	213	Primary	Classroom 213	W4	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored materials
278	6220	2	2	213B	Storage	Classroom 213 Coat Closet	W1	Staples	2	No	No	N/A	N/A	Yes	
279	6220	2	2	213B	Storage	Classroom 213 Coat Closet	W2	Chipping	4	No	No	N/A	N/A	No	
280	6220	2	2	213B	Storage	Classroom 213 Coat Closet	W3	Cracking, Chipping, Holes, Staples, Flaking, Coat hooks pulling off wall	45	No	No	N/A	N/A	Yes	
281	6220	2	2	213B	Storage	Classroom 213 Coat Closet	W4	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
282	6220	2	2	213C		Classroom 213 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
283	6220	2	2	213C		Classroom 213 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
284	6220	2	2	213C		Classroom 213 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
285	6220	2	2	213C		Classroom 213 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
286	6220	2	2	213C		Classroom 213 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
287	6220	2	2	213C		Classroom 213 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
288	6220	2	2	214	Primary	Classroom 214	Ceiling	Flaking above windows	13	No	No	N/A	N/A	No	
289	6220	2	2	214	Primary	Classroom 214	W1	Chipping	12	No	No	N/A	Stored Materials	No	
290	6220	2	2	214	Primary	Classroom 214	W2	N/A	N/A	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
291	6220	2	2	214	Primary	Classroom 214	W3	Chipping, Significant Moisture Damage behind radiator	22	Yes	No	N/A	Furniture, Stored Materials	Yes	
292	6220	2	2	214	Primary	Classroom 214	W4	N/A	N/A	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
293	6220	2	2	215	Primary	Classroom 215	Ceiling	Flaking above windows	9	No	No	N/A	N/A	No	
294	6220	2	2	215	Primary	Classroom 215	W1	Chipping	13	No	No	N/A	Furniture, Stored Materials	No	
295	6220	2	2	215	Primary	Classroom 215	W2	N/A	N/A	No	No	N/A	Desks with computers	No	Limited inspection due to stored materials
296	6220	2	2	215	Primary	Classroom 215	W3	Holes behind radiator and cover, Flaking on wall and behind radiator and cover, Efflorescence, Significant Moisture Damage behind radiator	42	Yes	No	N/A	Cabinets, Furniture	Yes	
297	6220	2	2	215	Primary	Classroom 215	W4	N/A	N/A	No	No	N/A	Furniture, Stored Materials	No	Limited inspection due to stored materials
298	6220	2	2	215B	Storage	Classroom 215 Coat Closet	Ceiling	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
299	6220	2	2	215B	Storage	Classroom 215 Coat Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
300	6220	2	2	215B	Storage	Classroom 215 Coat Closet	W1	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
301	6220	2	2	215B	Storage	Classroom 215 Coat Closet	W2	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
302	6220	2	2	215B	Storage	Classroom 215 Coat Closet	W3	Flaking, Coat hooks pulling off wall	12	No	Paint Chips inside radiator cover	2	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
303	6220	2	2	215B	Storage	Classroom 215 Coat Closet	W4	Cracking	18	No	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
304	6220	2	2	215C		Classroom 215 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
305	6220	2	2	215C		Classroom 215 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
306	6220	2	2	215C		Classroom 215 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
307	6220	2	2	215C		Classroom 215 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
308	6220	2	2	215C		Classroom 215 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
309	6220	2	2	215C		Classroom 215 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
310	6220	2	2	216	Storage	Classroom 216	Ceiling	Flaking above windows	12	No	No	N/A	N/A	No	
311	6220	2	2	216	Storage	Classroom 216	W1	Chipping, Staples and Staple Holes	66	No	No	N/A	Desks	Yes	
312	6220	2	2	216	Storage	Classroom 216	W2	Staples and Staple Holes, Flaking	36	No	No	N/A	Furniture, Stored Materials	Yes	
313	6220	2	2	216	Storage	Classroom 216	W3	Chipping, Flaking on wall and behind radiators	53	No	No	N/A	Shelves with stored materials	No	
314	6220	2	2	216	Storage	Classroom 216	W4	Cracking, Staples	53	No	No	N/A	Furniture, Stored Materials	Yes	
315	6220	2	2	216B	Storage	Classroom 216 Coat Closet	Ceiling	Flaking above missing ceiling tile	4	No	No	N/A	N/A	No	
316	6220	2	2	216B	Storage	Classroom 216 Coat Closet	W1	Chipping, Flaking above missing ceiling tile, Coat hooks pulling off wall	12	No	No	N/A	N/A	Yes	
317	6220	2	2	216B	Storage	Classroom 216 Coat Closet	W2	Cracking	1	No	No	N/A	N/A	No	
318	6220	2	2	216B	Storage	Classroom 216 Coat Closet	W3	Chipping, Hole on wall and behind radiator, Flaking above missing ceiling tile, Efflorescence above missing ceiling tile, Coat hooks pulling off wall	27	Yes	No	N/A	N/A	Yes	
319	6220	2	2	216B	Storage	Classroom 216 Coat Closet	W4	Flaking above missing ceiling tile	10	No	No	N/A	Cabinet, Stored Materials	No	
320	6220	2	2	216A		Classroom 216 Storage Closet	Ceiling	Cracking	6	No	No	N/A	N/A	No	
321	6220	2	2	216A		Classroom 216 Storage Closet	W2	Cracking	4	No	No	N/A	Built in shelves with stored materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
322	6220	2	2	216A		Classroom 216 Storage Closet	W3	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
323	6220	2	2	216A		Classroom 216 Storage Closet	W4	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
324	6220	2	2	217	Primary	Classroom 217	W1	Chipping	15	No	No	N/A	Cabinet	No	
325	6220	2	2	217	Primary	Classroom 217	W2	Chipping, Staples	9	No	No	N/A	Furniture	Yes	
326	6220	2	2	217	Primary	Classroom 217	W3	Chipping, Flaking on wall and behind radiator	25	No	No	N/A	Cabinet	No	
327	6220	2	2	217	Primary	Classroom 217	W4	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored materials
328	6220	2	2	218	Primary	Classroom 218	Ceiling	Efflorescence above windows	1	Yes	No	N/A	N/A	Yes	
329	6220	2	2	218	Primary	Classroom 218	W1	Chipping, Staples and Staple Holes	96	No	No	N/A	Posters, Furniture	Yes	
330	6220	2	2	218	Primary	Classroom 218	W2	Chipping, Staples	38	No	No	N/A	Posters, Furniture	Yes	
331	6220	2	2	218	Primary	Classroom 218	W3	Flaking behind radiators and covers	20	No	Paint chips on windowsill	1	Posters, Furniture	No	
332	6220	2	2	218	Primary	Classroom 218	W4	Staples	30	No	No	N/A	Furniture	Yes	
333	6220	2	2	218A	Storage	Classroom 218 Coat Closet	Ceiling	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
334	6220	2	2	218A	Storage	Classroom 218 Coat Closet	Floor	N/A	N/A	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
335	6220	2	2	218A	Storage	Classroom 218 Coat Closet	W1	Cracking	2	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
336	6220	2	2	218A	Storage	Classroom 218 Coat Closet	W2	Cracking	2	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
337	6220	2	2	218A	Storage	Classroom 218 Coat Closet	W3	Cracking, Chipping	18	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
338	6220	2	2	218A	Storage	Classroom 218 Coat Closet	W4	Hole, paint has been stabilized	1	No	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
339	6220	2	2	218B		Classroom 218 Storage Closet	W2	Chipping	2	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
340	6220	2	2	218B		Classroom 218 Storage Closet	W3	Cracking	1	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
341	6220	2	2	218B		Classroom 218 Storage Closet	W4	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
342	6220	1	2	212H	Service Closets	Custodial Closet next to Classroom 208	Ceiling	Chipping	1	No	No	N/A	N/A	No	
343	6220	1	2	212H	Service Closets	Custodial Closet next to Classroom 208	W2	Cracking	15	No	No	N/A	Built in shelves with stored materials	No	
344	6220	1	2	212H	Service Closets	Custodial Closet next to Classroom 208	W3	Cracking	25	No	No	N/A	Built in shelves with stored materials	No	
345	6220	1	2	212H	Service Closets	Custodial Closet next to Classroom 208	W4	Chipping	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
346	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	Ceiling	Cracking, Chipping, Hole	7	No	No	N/A	N/A	Yes	
347	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	Floor	Chipping	13	No	No	N/A	N/A	No	
348	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	W1	Cracking, Chipping	11	No	No	N/A	N/A	No	
349	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	W2	Cracking, Hole, Efflorescence	80	Yes	No	N/A	N/A	Yes	
350	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	W3	Cracking, Flaking, Significant Moisture Damage behind radiator	17	Yes	Debris on windowsill	2	N/A	Yes	
351	6220	1	2	212	Storage	Faculty Restroom/IT Server Room next to Classroom 201	W4	Cracking, Chipping, Flaking, Mold	89	No	No	N/A	N/A	No	
352	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	Ceiling	Flaking	360	No	No	N/A	N/A	No	
353	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	Floor	Chipping on stairs	75	No	Paint chips scattered	220	N/A	No	
354	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	W1	Chipping on door and doorframe, Flaking on wall, door and doorframe	271	No	No	N/A	N/A	No	
355	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	W2	Flaking on wall, bars, and metal pipe	207	No	No	N/A	N/A	No	
356	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	W3	Flaking on wall, bars, and window frames	490	No	No	N/A	N/A	No	
357	6220	1	2	FT2	Stairs	Fire Tower Stairs near Classroom 208	W4	Flaking on wall, door, doorframe, and window frames	139	No	No	N/A	N/A	No	
358	6220	1	2	212A	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Spalling	3	Yes	No	N/A	N/A	Yes	
359	6220	1	2	212A	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Chipping	3	No	No	N/A	N/A	No	
360	6220	1	2	212A	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Holes, paint has been stabilized	3	No	No	N/A	N/A	Yes	
361	6220	1	2	212A	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Efflorescence	20	Yes	No	N/A	N/A	Yes	
362	6220	1	2	C202	Circulation (Hallway)	Hallway Classroom 201	Floor	Chipping	15	No	No	N/A	N/A	No	
363	6220	1	2	C202	Circulation (Hallway)	Hallway Classroom 201	W2	Cracking, Flaking	9	No	No	N/A	N/A	No	
364	6220	1	2	C202	Circulation (Hallway)	Hallway Classroom 201	W4	Cracking	8	No	Debris on windowsills	8	N/A	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
365	6220	1	2	C201	Circulation (Hallway)	Hallway Classroom 202-207	Ceiling	Chipping, Hole	6	No	No	N/A	N/A	Yes	
366	6220	1	2	C201	Circulation (Hallway)	Hallway Classroom 202-207	Floor	Chipping on wall and sinks	117	No	No	N/A	N/A	No	
367	6220	1	2	C201	Circulation (Hallway)	Hallway Classroom 202-207	W1	Cracking, Chipping	19	No	No	N/A	Posters	Yes	
368	6220	1	2	C201	Circulation (Hallway)	Hallway Classroom 202-207	W2	Hole	1	No	No	N/A	N/A	Yes	
369	6220	1	2	C201	Circulation (Hallway)	Hallway Classroom 202-207	W3	Cracking, Chipping on wall and electric panels, Holes on wall and behind radiator, Flaking	14	No	No	N/A	Posters	Yes	
370	6220	1	2	C200	Circulation (Hallway)	Hallway Classroom 208	Ceiling	Significant Moisture Damage above windows	4	Yes	No	N/A	N/A	Yes	
371	6220	1	2	C200	Circulation (Hallway)	Hallway Classroom 208	Floor	Chipping	6	No	No	N/A	N/A	No	
372	6220	1	2	C200	Circulation (Hallway)	Hallway Classroom 208	W2	Cracking, Chipping, Hole, Spalling	34	Yes	Paint chips and debris inside radiator cover	3	N/A	Yes	
373	6220	1	2	C200	Circulation (Hallway)	Hallway Classroom 208	W3	Cracking, Hole	11	No	No	N/A	N/A	Yes	
374	6220	1	2	C200	Circulation (Hallway)	Hallway Classroom 208	W4	Cracking, Chipping	61	No	No	N/A	N/A	No	
375	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
376	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
377	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
378	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
379	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
380	6220	2	2	213A		Hallway Closet adjacent to Classroom 213	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
381	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
382	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
383	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
384	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
385	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
386	6220	2	2	C204B		Hallway Closet adjacent to Classroom 217	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
387	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	Ceiling	Cracking	3	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
388	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
389	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
390	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
391	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	W3	Cracking	2	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
392	6220	2	2	C204A		Hallway Closet adjacent to Classroom 218	W4	Cracking	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
393	6220	2	2	C204	Circulation (Hallway)	Hallway from Classrooms 213 to 218	W2	Chipping on wall and electrical panel, Staples and Staple Holes	55	No	No	N/A	N/A	Yes	
394	6220	2	2	C204	Circulation (Hallway)	Hallway from Classrooms 213 to 218	W4	Cracking, Chipping, Hole behind radiator, Staple Holes	17	No	No	N/A	N/A	Yes	
395	6220	1	2	C203		Hallway to Faculty Restroom/IT Server Room	Floor	Chipping	6	No	No	N/A	N/A	No	
396	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
397	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
398	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
399	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
400	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
401	6220	2	2	C203E	Storage	Lobby Closet across from side of Classroom 218	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
402	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	Ceiling	Significant Moisture Damage, poly has fallen down	15	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
403	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	Floor	N/A	N/A	No	Debris on materials	20	Stored Materials	No	Limited inspection due to stored materials
404	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	W1	N/A	N/A	No	Debris on materials	20	Stored Materials	No	Limited inspection due to stored materials
405	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	W2	Chipping	3	No	Debris on materials	35	Stored Materials	No	Limited inspection due to stored materials
406	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	W3	Cracking, Efflorescence	23	Yes	Debris on materials	40	Stored Materials	Yes	Limited inspection due to stored materials
407	6220	2	2	C203B	Storage	Lobby Closet by Classroom 213	W4	N/A	N/A	No	Debris on materials	35	Stored Materials	No	Limited inspection due to stored materials
408	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
409	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
410	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	6220	2	2	C203C	Storage	Lobby Closet next to Classroom 218	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	6220	2	2	C203A	Storage	Lobby Closet next to windows on Classroom 213 side	Ceiling	Cracking, Chipping, Hole covered with poly	12	No	No	N/A	N/A	Yes	
415	6220	2	2	C203A	Storage	Lobby Closet next to windows on Classroom 213 side	W1	Cracking	6	No	No	N/A	N/A	No	
416	6220	2	2	C203A	Storage	Lobby Closet next to windows on Classroom 213 side	W2	Cracking, Chipping	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
417	6220	2	2	C203A	Storage	Lobby Closet next to windows on Classroom 213 side	W3	N/A	N/A	No	No	N/A	Shelf with stored materials	No	Limited inspection due to stored materials
418	6220	2	2	C203A	Storage	Lobby Closet next to windows on Classroom 213 side	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
419	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	Ceiling	Cracking, Chipping	7	No	No	N/A	N/A	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
420	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
421	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	W1	Cracking, Chipping	4	No	No	N/A	N/A	No	Limited inspection due to stored materials
422	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
423	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	W3	N/A	N/A	No	No	N/A	Shelf with stored materials	No	Limited inspection due to stored materials
424	6220	2	2	C203D	Storage	Lobby Closet next to windows on Classroom 218 side	W4	Cracking, Chipping	13	No	No	N/A	Shelf with stored materials	No	Limited inspection due to stored materials
425	6220	2	2	C203	Circulation (Hallway)	Lobby next to Classroom 218	Ceiling	Flaking above windows	7	No	No	N/A	N/A	No	
426	6220	2	2	C203	Circulation (Hallway)	Lobby next to Classroom 218	Floor	Chipping	29	No	No	N/A	N/A	No	
427	6220	2	2	C203	Circulation (Hallway)	Lobby next to Classroom 218	W2	Spalling behind radiator	4	Yes	No	N/A	N/A	Yes	
428	6220	2	2	C203	Circulation (Hallway)	Lobby next to Classroom 218	W3	Cracking	9	No	No	N/A	N/A	No	
429	6220	2	2	C203	Circulation (Hallway)	Lobby next to Classroom 218	W4	Cracking, Chipping, Hole, Flaking behind radiator	14	No	No	N/A	N/A	Yes	
430	6220	2	2	S203		Lobby Stairwell	Floor	Chipping on railings	20	No	No	N/A	N/A	No	
431	6220	2	2	S203		Lobby Stairwell	W1	Cracking, Spalling	9	Yes	No	N/A	N/A	Yes	
432	6220	2	2	S203		Lobby Stairwell	W4	N/A	N/A	No	Debris on chair rail	1	N/A	No	
433	6220	2	2	215A	Primary	Reading Office 215A	W1	Chipping	2	No	No	N/A	N/A	No	
434	6220	2	2	215A	Primary	Reading Office 215A	W2	Chipping, Holes, Efflorescence	14	Yes	No	N/A	N/A	Yes	
435	6220	2	2	215A	Primary	Reading Office 215A	W3	Hole behind radiator and cover, Flaking	12	No	Paint chips on windowsill	1	N/A	Yes	
436	6220	2	2	215A	Primary	Reading Office 215A	W4	Cracking, Chipping, Holes	14	No	No	N/A	N/A	Yes	
437	6220	1	2	S2C	Stairs	Stairwell across from Classroom 201	Ceiling	Flaking, Spalling	3	Yes	No	N/A	N/A	Yes	
438	6220	1	2	S2C	Stairs	Stairwell across from Classroom 201	Floor	Chipping on stairs, cove, and railings	78	No	No	N/A	N/A	No	
439	6220	1	2	S2C	Stairs	Stairwell across from Classroom 201	W1	Chipping, Hole, paint has been stabilized	2	No	No	N/A	N/A	Yes	
440	6220	1	2	S2C	Stairs	Stairwell across from Classroom 201	W2	Chipping on doors and doorframe, Hole, paint has been stabilized	54	No	No	N/A	N/A	Yes	
441	6220	1	2	S2C	Stairs	Stairwell across from Classroom 201	W4	Hole behind radiator	1	No	No	N/A	N/A	Yes	
442	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	Ceiling	Flaking	4	No	No	N/A	N/A	No	
443	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	Floor	Chipping on stairs, cove, and railings	54	No	No	N/A	N/A	No	
444	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	W1	Cracking	10	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
445	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	W2	Flaking, Hole, Spalling	16	Yes	No	N/A	N/A	Yes	
446	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	W3	Cracking	5	No	No	N/A	N/A	No	
447	6220	1	2	S2B	Stairs	Stairwell across from Classroom 208	W4	Chipping on doors and doorframe	50	No	No	N/A	N/A	No	
448	6220	1	2	219	Storage	Storage Closet across from Classroom 202	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
449	6220	1	2	219	Storage	Storage Closet across from Classroom 202	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
450	6220	1	2	219	Storage	Storage Closet across from Classroom 202	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
451	6220	1	2	219	Storage	Storage Closet across from Classroom 202	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
452	6220	1	2	219	Storage	Storage Closet across from Classroom 202	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
453	6220	1	2	219	Storage	Storage Closet across from Classroom 202	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
454	6220	1	2	220	Storage	Storage Closet next to Teacher's Lounge	W2	N/A	N/A	No	Debris on shelves	5	Built in shelves with books	No	Limited inspection due to stored materials
455	6220	1	2	220	Storage	Storage Closet next to Teacher's Lounge	W3	N/A	N/A	No	No	N/A	Built in shelves with books	No	Limited inspection due to stored materials
456	6220	1	2	220	Storage	Storage Closet next to Teacher's Lounge	W4	Cracking	8	No	Debris on shelves	5	Built in shelves with books	Yes	Limited inspection due to stored materials
457	6220	1	2	212C	Teacher Lounge/Dining	Teacher's Lounge	Ceiling	Chipping	1	No	No	N/A	N/A	No	
458	6220	1	2	212C	Teacher Lounge/Dining	Teacher's Lounge	W3	Chipping on radiator	10	No	No	N/A	N/A	No	
459	6220	1	2	212B	Restrooms, Staff - Male/Female	Teacher's Lounge Restroom	Ceiling	N/A	N/A	No	ACM debris in air shaft	1	N/A	No	
460	6220	2	1.5	MS1		Auditorium Stairs	Ceiling	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
461	6220	2	1.5	MS2	Stairs	Auditorium Stairs	Ceiling	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
462	6220	2	1.5	MS1		Auditorium Stairs	Floor	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
463	6220	2	1.5	MS2	Stairs	Auditorium Stairs	Floor	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
464	6220	2	1.5	MS1	Stairs	Auditorium Stairs	W1	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
465	6220	2	1.5	MS2		Auditorium Stairs	W1	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
466	6220	2	1.5	MS1	Stairs	Auditorium Stairs	W2	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
467	6220	2	1.5	MS2		Auditorium Stairs	W2	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
468	6220	2	1.5	MS1	Stairs	Auditorium Stairs	W3	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
469	6220	2	1.5	MS2		Auditorium Stairs	W3	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
470	6220	2	1.5	MS1		Auditorium Stairs	W4	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
471	6220	2	1.5	MS2	Stairs	Auditorium Stairs	W4	See Note	N/A	No	No	N/A	N/A	No	Not sure where this space is located
472	6220	2	1.5	200	Primary	Classroom 200	Floor	Chipping	3	No	No	N/A	N/A	No	
473	6220	2	1.5	200	Primary	Classroom 200	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	
474	6220	2	1.5	200	Primary	Classroom 200	W2	Cracking, Gouge	26	No	No	N/A	N/A	Yes	
475	6220	2	1.5	200	Primary	Classroom 200	W3	Cracking, Chipping, Hole	25	No	No	N/A	N/A	Yes	
476	6220	2	1.5	200	Primary	Classroom 200	W4	Chipping, Flaking on metal pipe	17	No	No	N/A	N/A	No	
477	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	Ceiling	Flaking above missing ceiling tile	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
478	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
479	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	W1	Chipping on doorframe	4	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
480	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
481	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	W3	Flaking	17	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
482	6220	2	1.5	200B	Storage	Classroom 200 Storage Room #1	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
483	6220	2	1.5	200A	Storage	Classroom 200 Storage Room #2	Floor	N/A	N/A	No	Debris on shelves and floor	20	N/A	No	
484	6220	2	1.5	200A	Storage	Classroom 200 Storage Room #2	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
485	6220	2	1.5	200A	Storage	Classroom 200 Storage Room #2	W2	Flaking, Efflorescence	14	Yes	No	N/A	Shelves with stored materials	Yes	
486	6220	2	1.5	200A	Storage	Classroom 200 Storage Room #2	W3	Flaking, Efflorescence	49	Yes	No	N/A	Shelves with stored materials	Yes	
487	6220	2	1.5	200A	Storage	Classroom 200 Storage Room #2	W4	Flaking, Efflorescence	14	Yes	No	N/A	Shelves with stored materials	Yes	
488	6220	2	1.5	202	Administrative Office	Dressing Room (schoolyard side)	Floor	Chipping	30	No	Paint chips from table	10	N/A	No	
489	6220	2	1.5	202	Administrative Office	Dressing Room (schoolyard side)	W1	Chipping, Hole from missing cove	5	No	No	N/A	N/A	Yes	
490	6220	2	1.5	202	Administrative Office	Dressing Room (schoolyard side)	W2	N/A	N/A	No	Debris on windowsill	1	N/A	No	
491	6220	2	1.5	202	Administrative Office	Dressing Room (schoolyard side)	W3	Chipping on wall and radiator	21	No	Debris around pipes	2	N/A	No	
492	6220	2	1.5	201	Administrative Office	Dressing Room (Sharpnack St side)	Ceiling	Chipping, Efflorescence	4	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
493	6220	2	1.5	201	Administrative Office	Dressing Room (Sharpnack St side)	W1	Spalling	4	Yes	No	N/A	N/A	Yes	
494	6220	2	1.5	201	Administrative Office	Dressing Room (Sharpnack St side)	W2	Chipping, Spalling	5	Yes	No	N/A	N/A	Yes	
495	6220	2	1.5	201	Administrative Office	Dressing Room (Sharpnack St side)	W3	Chipping, Flaking on wall and metal pipe, Efflorescence	15	Yes	No	N/A	N/A	Yes	
496	6220	2	1.5	201	Administrative Office	Dressing Room (Sharpnack St side)	W4	Chipping, Spalling, Efflorescence	7	Yes	No	N/A	N/A	Yes	
497	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
498	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
499	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
500	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
501	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
502	6220	2	1.5	202B	Storage	Dressing Room Closet (schoolyard side)	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
503	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	Ceiling	Cracking	6	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
504	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	Floor	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
505	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	W1	Cracking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
506	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	W2	Cracking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
507	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
508	6220	2	1.5	201B	Storage	Dressing Room Closet (Sharpnack St side)	W4	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
509	6220	2	1.5	202A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (schoolyard side)	Floor	N/A	N/A	No	Paint chips	5	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
510	6220	2	1.5	202A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (schoolyard side)	W1	Cracking, Flaking, Efflorescence	10	Yes	No	N/A	N/A	Yes	
511	6220	2	1.5	202A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (schoolyard side)	W3	Cracking	5	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
512	6220	2	1.5	201A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (Sharpnack St side)	W1	Spalling	3	Yes	No	N/A	N/A	Yes	
513	6220	2	1.5	201A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (Sharpnack St side)	W2	Spalling	3	Yes	No	N/A	N/A	Yes	
514	6220	2	1.5	201A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (Sharpnack St side)	W3	Spalling	5	Yes	No	N/A	N/A	Yes	
515	6220	2	1.5	201A	Student Restrooms - Male/Female (Classroom)	Dressing Room Restroom (Sharpnack St side)	W4	Spalling	3	Yes	No	N/A	N/A	Yes	
516	6220	2	1.5	203		Hallway outside Classroom 200	Floor	Chipping	5	No	No	N/A	N/A	No	
517	6220	2	1.5	203		Hallway outside Classroom 200	W1	Spalling	4	Yes	No	N/A	N/A	Yes	
518	6220	2	1.5	203		Hallway outside Classroom 200	W2	Chipping on radiator	10	No	No	N/A	N/A	No	
519	6220	2	1.5	203		Hallway outside Classroom 200	W4	Chipping on radiator, Flaking behind radiator	17	No	No	N/A	N/A	No	
520	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
521	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
522	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
523	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
524	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
525	6220	2	1.5	203A		Hallway outside Classroom 200 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
526	6220	2	1.5	203B		Stairwell outside Classroom 200	Ceiling	Cracking, Spalling	4	Yes	No	N/A	N/A	Yes	
527	6220	2	1.5	203B		Stairwell outside Classroom 200	Floor	Chipping on railings	10	No	No	N/A	N/A	No	
528	6220	2	1.5	203B		Stairwell outside Classroom 200	W1	Chipping, Spalling	2	Yes	No	N/A	N/A	Yes	
529	6220	2	1.5	203B		Stairwell outside Classroom 200	W2	Cracking, Flaking	12	No	No	N/A	N/A	No	
530	6220	2	1.5	203B		Stairwell outside Classroom 200	W3	Spalling	1	Yes	No	N/A	N/A	Yes	
531	6220	2	1.5	202C	Stairs	Stairwell to Dressing Room (schoolyard side)	Floor	N/A	N/A	No	Debris scattered throughout	22	N/A	No	
532	6220	2	1.5	202C	Stairs	Stairwell to Dressing Room (schoolyard side)	W2	Chipping	4	No	No	N/A	N/A	No	
533	6220	2	1.5	202C	Stairs	Stairwell to Dressing Room (schoolyard side)	W4	Chipping on electrical panel	6	No	No	N/A	N/A	No	
534	6220	2	1.5	201C	Stairs	Stairwell to Dressing Room (Sharpnack St side)	Floor	N/A	N/A	No	Debris scattered throughout	14	N/A	No	
535	6220	2	1.5	201C	Stairs	Stairwell to Dressing Room (Sharpnack St side)	W1	Spalling	1	Yes	No	N/A	N/A	Yes	
536	6220	2	1.5	201C	Stairs	Stairwell to Dressing Room (Sharpnack St side)	W2	Cracking, Spalling	22	Yes	No	N/A	N/A	Yes	
537	6220	2	1.5	201C	Stairs	Stairwell to Dressing Room (Sharpnack St side)	W3	Spalling	3	Yes	No	N/A	N/A	Yes	
538	6220	2	1.5	201C	Stairs	Stairwell to Dressing Room (Sharpnack St side)	W4	Spalling, Efflorescence	16	Yes	Debris on top of doorframe	1	N/A	Yes	
539	6220	2	1	100	Auditorium	Auditorium	Ceiling	Flaking	27	No	No	N/A	N/A	No	
540	6220	2	1	100	Auditorium	Auditorium	W1	Cracking, Flaking	31	No	No	N/A	N/A	No	
541	6220	2	1	100	Auditorium	Auditorium	W2	Cracking, Chipping, Hole, Flaking	27	No	No	N/A	N/A	Yes	
542	6220	2	1	100	Auditorium	Auditorium	W3	Holes, Flaking	3	No	No	N/A	N/A	Yes	
543	6220	2	1	100	Auditorium	Auditorium	W4	Cracking, Hole, Flaking	46	No	No	N/A	N/A	Yes	
544	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	Ceiling	Spalling	28	Yes	No	N/A	N/A	Yes	
545	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	Floor	N/A	N/A	No	Paint chips scattered	6	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
546	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	W1	Cracking, Flaking, Spalling	18	Yes	No	N/A	N/A	Yes	
547	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	W2	Cracking, Holes, Spalling	15	Yes	Debris on radiator cover	7	Stored Materials	Yes	
548	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	W3	Cracking, Chipping on wall, doors, and doorframe, Flaking on doorframe	32	No	No	N/A	N/A	No	
549	6220	2	1	102	Circulation (Hallway)	Auditorium Exit Vestibule (Sharpnack St side)	W4	Flaking	1	No	No	N/A	N/A	No	
550	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
551	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
552	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
553	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
554	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
555	6220	2	1	102A	Storage	Auditorium Exit Vestibule (Sharpnack St. side) - Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
556	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	Ceiling	Spalling	1	Yes	No	N/A	N/A	Yes	
557	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	Floor	N/A	N/A	No	Paint chips scattered	10	N/A	No	
558	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	W1	Cracking, Spalling	5	Yes	No	N/A	N/A	Yes	
559	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	W2	Spalling	6	Yes	No	N/A	N/A	Yes	
560	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	W3	Cracking, Chipping on doors	20	No	No	N/A	N/A	No	
561	6220	2	1	101	Circulation (Hallway)	Auditorium Exit Vestibule (Yard side)	W4	Cracking, Spalling	21	Yes	No	N/A	Desks	Yes	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
562	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	Ceiling	Chipping, Efflorescence	3	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
563	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	Floor	N/A	N/A	No	Paint chips	1	Stored Materials	No	Limited inspection due to stored materials
564	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
565	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	W2	Flaking	4	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
566	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	W3	Flaking, Efflorescence	15	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
567	6220	2	1	101A	Storage	Auditorium Exit Vestibule (Yard side) - Closet	W4	Flaking, Efflorescence	3	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
568	6220	2	1	H01	Circulation (Hallway)	Auditorium Lobby	Ceiling	Flaking, Spalling	25	Yes	No	N/A	N/A	Yes	
569	6220	2	1	H01	Circulation (Hallway)	Auditorium Lobby	W2	Cracking, Chipping on doors, Flaking on doorframes	43	No	No	N/A	N/A	No	
570	6220	2	1	H01	Circulation (Hallway)	Auditorium Lobby	W3	Spalling	13	Yes	No	N/A	N/A	Yes	
571	6220	2	1	H01	Circulation (Hallway)	Auditorium Lobby	W4	Spalling	30	Yes	No	N/A	N/A	Yes	
572	6220	2	1	H01A		Auditorium Lobby Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
573	6220	2	1	H01A		Auditorium Lobby Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
574	6220	2	1	H01A		Auditorium Lobby Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
575	6220	2	1	H01A		Auditorium Lobby Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
576	6220	2	1	H01A		Auditorium Lobby Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
577	6220	2	1	H01A		Auditorium Lobby Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
578	6220	2	1	100A	Student Restrooms - Male/Female (Classroom)	Auditorium Lobby Restroom	Floor	Chipping, Spalling	19	No	No	N/A	N/A	No	
579	6220	2	1	100A	Student Restrooms - Male/Female (Classroom)	Auditorium Lobby Restroom	W1	Cracking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
580	6220	2	1	100A	Student Restrooms - Male/Female (Classroom)	Auditorium Lobby Restroom	W2	Spalling	1	Yes	No	N/A	N/A	Yes	
581	6220	2	1	100A	Student Restrooms - Male/Female (Classroom)	Auditorium Lobby Restroom	W3	Spalling	8	Yes	No	N/A	N/A	Yes	
582	6220	2	1	100A	Student Restrooms - Male/Female (Classroom)	Auditorium Lobby Restroom	W4	Cracking	5	No	No	N/A	N/A	No	
583	6220	2	1	100C		Auditorium Lobby Restroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
584	6220	2	1	100C		Auditorium Lobby Restroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
585	6220	2	1	100C		Auditorium Lobby Restroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
586	6220	2	1	100C		Auditorium Lobby Restroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
587	6220	2	1	100C		Auditorium Lobby Restroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
588	6220	2	1	100C		Auditorium Lobby Restroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
589	6220	2	1	AS1	Stairs	Auditorium Lobby Stairs	Ceiling	Flaking	4	No	No	N/A	N/A	No	
590	6220	2	1	AS1	Stairs	Auditorium Lobby Stairs	W3	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	
591	6220	2	1	AS1	Stairs	Auditorium Lobby Stairs	W4	Cracking, Gouges	6	No	No	N/A	N/A	Yes	
592	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	Ceiling	Cracking	4	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
593	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	Floor	N/A	N/A	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
594	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	W1	N/A	N/A	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
595	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	W2	N/A	N/A	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
596	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	W3	Cracking	3	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
597	6220	2	1	AS1A		Auditorium Lobby Stairs Closet	W4	N/A	N/A	No	No	N/A	Built in shelves, Stored Materials	No	Limited inspection due to stored materials
598	6220	2	1	100B	Auditorium	Auditorium Stage	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
599	6220	2	1	100B	Auditorium	Auditorium Stage	Floor	N/A	N/A	No	Debris scattered around edges	10	N/A	No	
600	6220	2	1	100B	Auditorium	Auditorium Stage	W1	Chipping	6	No	No	N/A	N/A	No	
601	6220	2	1	100B	Auditorium	Auditorium Stage	W2	Chipping on radiator, Hole, Flaking, Spalling, Efflorescence	38	Yes	No	N/A	Cabinet	Yes	
602	6220	2	1	100B	Auditorium	Auditorium Stage	W3	Flaking	60	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
603	6220	2	1	100B	Auditorium	Auditorium Stage	W4	Chipping on radiator, Flaking, Spalling, Efflorescence	71	Yes	No	N/A	N/A	Yes	
604	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	Ceiling	Chipping, Hole, Flaking, Spalling	20	Yes	No	N/A	N/A	Yes	
605	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	Floor	N/A	N/A	No	Paint chips scattered throughout	35	N/A	No	
606	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	W1	Flaking	44	No	No	N/A	N/A	No	
607	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	W2	Flaking	3	No	No	N/A	N/A	No	
608	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	W3	Hole, Flaking, Spalling, Efflorescence	85	Yes	Debris on windowsill	1	N/A	Yes	
609	6220	2	1	100RH	Auditorium	Auditorium Stage - Rear Hall	W4	Cracking, Flaking, Spalling	23	Yes	No	N/A	N/A	Yes	
610	6220	1	1	114		Boy's Restroom adjacent to Classroom 106	Ceiling	Cracking	6	No	No	N/A	N/A	No	
611	6220	1	1	114		Boy's Restroom adjacent to Classroom 106	Floor	Chipping	2	No	No	N/A	N/A	No	
612	6220	1	1	114		Boy's Restroom adjacent to Classroom 106	W2	Cracking	10	No	No	N/A	N/A	No	
613	6220	1	1	114		Boy's Restroom adjacent to Classroom 106	W4	Cracking	20	No	No	N/A	N/A	No	
614	6220	3	1	002A	Cafeteria (Dining Area)	Cafeteria	W1	Chipping on wall, doors, and doorframes, Hole, Flaking	42	No	No	N/A	Cabinets	No	Repair to sheetrock needed
615	6220	3	1	002A	Cafeteria (Dining Area)	Cafeteria	W2	Cracking	3	No	No	N/A	N/A	No	Repair to sheetrock needed
616	6220	3	1	002A	Cafeteria (Dining Area)	Cafeteria	W3	Cracking, Chipping on wall, windows and window frames, Gouge, Flaking on windows and window frames	30	No	No	N/A	N/A	No	Repair to sheetrock needed
617	6220	3	1	004A	Primary	Childcare Pickup Room / Small Cafeteria	W1	Chipping on door and doorframe	19	No	No	N/A	Cabinets	No	
618	6220	3	1	004A	Primary	Childcare Pickup Room / Small Cafeteria	W3	Cracking, Chipping on windows and windowsills, Flaking on windows and windowsills	34	No	No	N/A	N/A	No	Repair to sheetrock needed
619	6220	3	1	004A	Primary	Childcare Pickup Room / Small Cafeteria	W4	Cracking	4	No	No	N/A	N/A	No	Repair to sheetrock needed
620	6220	1	1	101	Primary	Classroom 101	W1	Flaking	7	No	No	N/A	Furniture, Posters	No	
621	6220	1	1	101	Primary	Classroom 101	W2	Chipping, Holes, Flaking	32	No	Debris on chalk ledge	1	Furniture, Posters	Yes	
622	6220	1	1	101	Primary	Classroom 101	W3	Chipping, Holes behind radiator, Flaking on wall and behind radiators, Efflorescence	89	Yes	Debris on windowsills	8	Furniture, Posters	Yes	
623	6220	1	1	101	Primary	Classroom 101	W4	Chipping	8	No	No	N/A	Furniture, Posters	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
624	6220	1	1	102	Primary	Classroom 102	W1	Cracking, Chipping, Holes, Flaking	131	No	No	N/A	Furniture, Stored Materials	Yes	
625	6220	1	1	102	Primary	Classroom 102	W2	Cracking, Flaking, Efflorescence	106	Yes	No	N/A	Furniture, Stored Materials	Yes	
626	6220	1	1	102	Primary	Classroom 102	W3	Cracking, Chipping, Holes, Flaking on wall and behind radiator, Efflorescence	57	Yes	No	N/A	Furniture, Stored Materials	Yes	
627	6220	1	1	102	Primary	Classroom 102	W4	Cracking, Chipping, Flaking in air shaft	74	No	No	N/A	Furniture, Posters	No	
628	6220	1	1	102A	Storage	Classroom 102 Closet	Floor	N/A	N/A	No	Debris in corner of walls 3&4	1	N/A	No	
629	6220	1	1	102A	Storage	Classroom 102 Closet	W1	Cracking	2	No	No	N/A	N/A	No	
630	6220	1	1	102A	Storage	Classroom 102 Closet	W2	Chipping, Flaking, Coat hooks pulling off wall	23	No	No	N/A	Cabinet, Stored Materials	Yes	
631	6220	1	1	102A	Storage	Classroom 102 Closet	W3	Holes, Flaking	3	No	No	N/A	Stored Materials	Yes	
632	6220	1	1	102A	Storage	Classroom 102 Closet	W4	Cracking, Chipping, Holes, Flaking, Coat hooks pulling off wall	39	No	No	N/A	Stored Materials	Yes	
633	6220	1	1	103	Primary	Classroom 103	Ceiling	Cracking	10	No	No	N/A	N/A	No	
634	6220	1	1	103	Primary	Classroom 103	W1	Cracking, Chipping, Flaking	42	No	No	N/A	Furniture, Posters	No	
635	6220	1	1	103	Primary	Classroom 103	W2	Cracking, Chipping	80	No	No	N/A	Furniture	No	
636	6220	1	1	103	Primary	Classroom 103	W3	Flaking on wall and behind radiator	6	No	No	N/A	Furniture, Posters	No	
637	6220	1	1	103	Primary	Classroom 103	W4	Cracking	80	No	No	N/A	Furniture	No	
638	6220	1	1	103A	Storage	Classroom 103 Closet	Ceiling	Significant Moisture Damage above missing ceiling tile	5	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
639	6220	1	1	103A	Storage	Classroom 103 Closet	Floor	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
640	6220	1	1	103A	Storage	Classroom 103 Closet	W1	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
641	6220	1	1	103A	Storage	Classroom 103 Closet	W2	Cracking, Chipping, Flaking	65	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
642	6220	1	1	103A	Storage	Classroom 103 Closet	W3	Efflorescence	3	Yes	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
643	6220	1	1	103A	Storage	Classroom 103 Closet	W4	Cracking	60	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
644	6220	1	1	106	Primary	Classroom 106	Floor	N/A	N/A	No	Debris below radiator	3	N/A	No	
645	6220	1	1	106	Primary	Classroom 106	W1	Chipping, Flaking	8	No	No	N/A	Furniture, Posters	No	
646	6220	1	1	106	Primary	Classroom 106	W2	Chipping, Flaking behind radiator	22	No	Debris on windowsills	2	Furniture, Posters	No	
647	6220	1	1	106	Primary	Classroom 106	W3	Cracking	90	No	No	N/A	Furniture, Posters	No	
648	6220	1	1	106	Primary	Classroom 106	W4	Chipping	8	No	No	N/A	Posters	No	
649	6220	1	1	106A	Storage	Classroom 106 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
650	6220	1	1	106A	Storage	Classroom 106 Closet	W2	Cracking, Coat hooks pulling off wall	26	No	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to stored materials
651	6220	1	1	106A	Storage	Classroom 106 Closet	W3	N/A	N/A	No	Debris inside radiator cover	4	Stored Materials	No	Limited inspection due to stored materials
652	6220	1	1	106A	Storage	Classroom 106 Closet	W4	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
653	6220	1	1	106B	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	Ceiling	Cracking	2	No	No	N/A	N/A	No	
654	6220	1	1	106B	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	Floor	Chipping	21	No	No	N/A	N/A	No	
655	6220	1	1	106B	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W1	Cracking, Chipping on doorframe	18	No	No	N/A	N/A	No	
656	6220	1	1	106B	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W3	Cracking	5	No	No	N/A	N/A	No	
657	6220	1	1	106B	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W4	N/A	N/A	No	Debris on windowsill	3	N/A	No	
658	6220	1	1	107	Primary	Classroom 107	W1	Cracking, Chipping, Staples and Staple Holes	72	No	No	N/A	Posters, Stored Materials	Yes	
659	6220	1	1	107	Primary	Classroom 107	W2	Cracking, Chipping, Staples and Staple Holes, Flaking	22	No	No	N/A	Posters, Stored Materials	Yes	
660	6220	1	1	107	Primary	Classroom 107	W3	Chipping, Staples and Staple Holes, Flaking	47	No	Debris on windowsills	1	Furniture, Posters, Stored Materials	Yes	
661	6220	1	1	107	Primary	Classroom 107	W4	Chipping, Flaking	6	No	No	N/A	Posters, Stored Materials	No	
662	6220	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Center Restroom	Floor	Chipping	17	No	No	N/A	N/A	No	
663	6220	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Center Restroom	W1	Cracking, Chipping, Flaking	21	No	No	N/A	N/A	No	
664	6220	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Center Restroom	W2	Cracking, Chipping, Flaking	10	No	No	N/A	Stored Materials	No	
665	6220	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Center Restroom	W3	Cracking, Chipping, Holes	10	No	No	N/A	Stored Materials	Yes	
666	6220	1	1	107C	Storage	Classroom 107 Coat Closet	W1	Cracking, Chipping	72	No	No	N/A	Cabinets	No	
667	6220	1	1	107C	Storage	Classroom 107 Coat Closet	W2	Cracking, Flaking	17	No	No	N/A	N/A	No	
668	6220	1	1	107C	Storage	Classroom 107 Coat Closet	W3	Cracking, Chipping, Flaking	78	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
669	6220	1	1	107C	Storage	Classroom 107 Coat Closet	W4	Cracking, Chipping, Hole, Flaking	28	No	No	N/A	N/A	Yes	
670	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
671	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	Floor	Chipping	12	No	Debris below efflorescence	2	Stored Materials	No	Limited inspection due to stored materials
672	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
673	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
674	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	W3	Cracking, Chipping, Flaking, Spalling	16	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
675	6220	1	1	107B		Classroom 107 Restroom adjacent to windows	W4	Hole behind radiator, Flaking, Efflorescence	12	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
676	6220	1	1	107D		Classroom 107 Storage Closet	Ceiling	Cracking	6	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
677	6220	1	1	107D		Classroom 107 Storage Closet	Floor	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
678	6220	1	1	107D		Classroom 107 Storage Closet	W1	Cracking	10	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
679	6220	1	1	107D		Classroom 107 Storage Closet	W2	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
680	6220	1	1	107D		Classroom 107 Storage Closet	W3	Cracking	1	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
681	6220	1	1	107D		Classroom 107 Storage Closet	W4	Cracking	3	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
682	6220	1	1	108	Primary	Classroom 108	W1	Cracking, Chipping	12	No	No	N/A	Posters, Stored Materials	No	
683	6220	1	1	108	Primary	Classroom 108	W2	Chipping	7	No	No	N/A	Posters	No	
684	6220	1	1	108	Primary	Classroom 108	W3	Efflorescence	1	Yes	Debris on windowsills	6	Furniture, Posters	Yes	Limited inspection due to stored materials
685	6220	1	1	108	Primary	Classroom 108	W4	Chipping	6	No	No	N/A	Furniture, Posters	No	
686	6220	1	1	108A	Storage	Classroom 108 Closet	W1	Cracking	4	No	No	N/A	N/A	No	
687	6220	1	1	108A	Storage	Classroom 108 Closet	W2	Chipping, Flaking, Coat hooks pulling off wall	13	No	No	N/A	Stored Materials	Yes	
688	6220	1	1	108A	Storage	Classroom 108 Closet	W3	N/A	N/A	No	No	N/A	Shelf, Stored Materials	No	Limited inspection due to stored materials
689	6220	1	1	108A	Storage	Classroom 108 Closet	W4	Cracking, Chipping, Coat hooks pulling off wall	45	No	No	N/A	N/A	Yes	
690	6220	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Chipping, Flaking	5	No	No	N/A	Posters	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
691	6220	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W2	N/A	N/A	No	No	N/A	Shelf, Stored Materials	No	Limited inspection due to stored materials
692	6220	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Chipping, Hole, Flaking	8	No	No	N/A	N/A	Yes	
693	6220	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W4	Flaking, Spalling	6	Yes	No	N/A	N/A	Yes	
694	6220	1	1	109	Primary	Classroom 109	Ceiling	Cracking, Efflorescence	21	Yes	No	N/A	N/A	Yes	
695	6220	1	1	109	Primary	Classroom 109	W1	Chipping	20	No	No	N/A	Posters, Stored Materials, Furniture	No	
696	6220	1	1	109	Primary	Classroom 109	W2	Chipping, Hole, Flaking on wall and behind radiator, Efflorescence	26	Yes	No	N/A	Furniture, Stored Materials	Yes	
697	6220	1	1	109	Primary	Classroom 109	W3	Flaking on wall and metal pipe	3	No	No	N/A	Stored Materials	No	
698	6220	1	1	109	Primary	Classroom 109	W4	Chipping on wall and door, Flaking on doorframe	29	No	No	N/A	Furniture, Stored Materials	No	
699	6220	1	1	109A	Storage	Classroom 109 Coat Closet	W1	Coat hooks pulling off wall	1	No	No	N/A	N/A	Yes	
700	6220	1	1	109A	Storage	Classroom 109 Coat Closet	W2	Chipping, Hole	8	No	No	N/A	N/A	Yes	
701	6220	1	1	109A	Storage	Classroom 109 Coat Closet	W4	Cracking, Chipping	12	No	No	N/A	N/A	No	
702	6220	1	1	109B	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom	Floor	Chipping	7	No	No	N/A	N/A	No	
703	6220	1	1	109B	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom	W2	Cracking, Flaking	28	No	No	N/A	N/A	No	
704	6220	1	1	109B	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom	W3	Cracking, Chipping on metal pipe, Flaking on metal pipe	11	No	No	N/A	N/A	No	
705	6220	1	1	109B	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom	W4	Cracking, Holes, paint has been stabilized on 1	17	No	No	N/A	N/A	Yes	
706	6220	1	1	109C		Classroom 109 Storage Closet	Ceiling	Cracking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
707	6220	1	1	109C		Classroom 109 Storage Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
708	6220	1	1	109C		Classroom 109 Storage Closet	W1	Cracking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
709	6220	1	1	109C		Classroom 109 Storage Closet	W2	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
710	6220	1	1	109C		Classroom 109 Storage Closet	W3	Cracking	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
711	6220	1	1	109C		Classroom 109 Storage Closet	W4	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
712	6220	1	1	110	Primary	Conference Room 110	W1	Chipping, Flaking, Spalling	7	Yes	Debris on chalk ledge and cove	5	Furniture, Posters	Yes	
713	6220	1	1	110	Primary	Conference Room 110	W2	N/A	N/A	No	Debris on chalk ledge	7	Furniture, Posters	No	
714	6220	1	1	110	Primary	Conference Room 110	W3	Chipping, Hole behind radiator, Flaking behind radiators, Efflorescence	48	Yes	No	N/A	Furniture, Posters	Yes	
715	6220	1	1	110	Primary	Conference Room 110	W4	Cracking	3	No	No	N/A	Furniture	Yes	
716	6220	1	1	110A	Storage	Conference Room 110 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
717	6220	1	1	110A	Storage	Conference Room 110 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
718	6220	1	1	110A	Storage	Conference Room 110 Closet	W1	N/A	N/A	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
719	6220	1	1	110A	Storage	Conference Room 110 Closet	W2	Cracking, Chipping	16	No	No	N/A	Stored Materials	No	
720	6220	1	1	110A	Storage	Conference Room 110 Closet	W3	Cracking, Flaking on metal pipe	6	No	No	N/A	Stored Materials	No	
721	6220	1	1	110A	Storage	Conference Room 110 Closet	W4	Cracking, Chipping, Flaking, Coat hooks pulling off wall	40	No	No	N/A	Stored Materials	Yes	
722	6220	1	1	101A	Administrative Office	Copy Room 101A	Ceiling	Flaking above windows	2	No	No	N/A	N/A	No	
723	6220	1	1	101A	Administrative Office	Copy Room 101A	W3	Spalling on windowsill	1	No	No	N/A	N/A	No	
724	6220	1	1	105A	Administrative Office	Counselor's Office across from Suite entrance	W1	Chipping on wall and doorframe, Flaking	9	No	No	N/A	Table	No	
725	6220	1	1	105A	Administrative Office	Counselor's Office across from Suite entrance	W2	Chipping	3	No	No	N/A	Cabinets	No	
726	6220	1	1	105A	Administrative Office	Counselor's Office across from Suite entrance	W3	Chipping, Flaking	2	No	No	N/A	Desk, Posters	No	
727	6220	1	1	105A	Administrative Office	Counselor's Office across from Suite entrance	W4	Chipping	10	No	No	N/A	Desk, Shelf, Posters, Wall hanging	No	
728	6220	1	1	105B	Administrative Office	Counselor's Office next to School Psychologist's Office	Floor	Chipping	3	No	No	N/A	N/A	No	
729	6220	1	1	105B	Administrative Office	Counselor's Office next to School Psychologist's Office	W1	Chipping on doorframe	8	No	No	N/A	Shelves, Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
730	6220	1	1	105B	Administrative Office	Counselor's Office next to School Psychologist's Office	W2	Chipping	7	No	No	N/A	Posters	No	
731	6220	1	1	105B	Administrative Office	Counselor's Office next to School Psychologist's Office	W3	N/A	N/A	No	No	N/A	Desk, Stored Materials	No	Limited inspection due to stored materials
732	6220	1	1	105B	Administrative Office	Counselor's Office next to School Psychologist's Office	W4	Hole	1	No	No	N/A	Desk, Cabinets, Stored Materials	Yes	
733	6220	1	1	105	Administrative Office	Counselor's Suite 105	Floor	Chipping	23	No	No	N/A	N/A	No	
734	6220	1	1	105	Administrative Office	Counselor's Suite 105	W1	Cracking, Chipping, Flaking	26	No	No	N/A	Cabinets, Posters	No	Limited inspection due to stored materials
735	6220	1	1	105	Administrative Office	Counselor's Suite 105	W2	Holes, paint has been stabilized	2	No	No	N/A	N/A	Yes	
736	6220	1	1	105	Administrative Office	Counselor's Suite 105	W3	Cracking, Chipping, Holes, Flaking	10	No	No	N/A	N/A	Yes	
737	6220	1	1	105	Administrative Office	Counselor's Suite 105	W4	Cracking, Chipping, Flaking	14	No	No	N/A	N/A	No	
738	6220	1	1	105D	Storage	Counselor's Suite Storage Closet	Ceiling	Flaking above windows	2	No	No	N/A	N/A	No	
739	6220	1	1	105D	Storage	Counselor's Suite Storage Closet	Floor	N/A	N/A	No	Paint chips near wall 3	10	N/A	No	
740	6220	1	1	105D	Storage	Counselor's Suite Storage Closet	W2	Flaking	10	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
741	6220	1	1	105D	Storage	Counselor's Suite Storage Closet	W3	Flaking on wall and metal pipe	18	No	No	N/A	N/A	No	
742	6220	1	1	105D	Storage	Counselor's Suite Storage Closet	W4	Flaking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
743	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
744	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
745	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	W1	Cracking, Chipping	7	No	No	N/A	Stored Materials	No	
746	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
747	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	W3	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
748	6220	1	1	105E		Counselor's Suite Storage Closet Vestibule	W4	Cracking	15	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
749	6220	1	1	S11	Stairs	Fire Tower Stairs near Classroom 107	Ceiling	Flaking	220	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
750	6220	1	1	S11	Stairs	Fire Tower Stairs near Classroom 107	W1	Flaking	220	No	No	N/A	N/A	No	
751	6220	1	1	S11	Stairs	Fire Tower Stairs near Classroom 107	W2	Flaking on wall, door, and doorframe	171	No	No	N/A	N/A	No	
752	6220	1	1	S11	Stairs	Fire Tower Stairs near Classroom 107	W3	Flaking on wall and window frame	250	No	No	N/A	N/A	No	
753	6220	1	1	S11	Stairs	Fire Tower Stairs near Classroom 107	W4	Chipping on doors and doorframe, Flaking on wall and doorframe	153	No	No	N/A	N/A	No	
754	6220	1	1	S11A		Fire Tower Vestibule near Classroom 107	W1	Chipping on door and doorframe, Flaking on door and doorframe	50	No	No	N/A	N/A	No	
755	6220	1	1	S11A		Fire Tower Vestibule near Classroom 107	W2	Flaking on bars and metal pipe	162	No	No	N/A	N/A	No	
756	6220	1	1	S11A		Fire Tower Vestibule near Classroom 107	W3	Flaking on bars	100	No	No	N/A	N/A	No	
757	6220	1	1	111	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Spalling	3	Yes	No	N/A	N/A	Yes	
758	6220	1	1	111	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Chipping	5	No	No	N/A	N/A	No	
759	6220	3	1	008A	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Chipping on wall, cove, door, and doorframe, Flaking	13	No	No	N/A	N/A	No	
760	6220	1	1	111	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Cracking	10	No	No	N/A	N/A	No	
761	6220	3	1	008A	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Chipping on cove and metal pipes	14	No	No	N/A	N/A	No	
762	6220	1	1	111	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Spalling	1	Yes	No	N/A	N/A	Yes	
763	6220	3	1	008A	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Cracking, Chipping on window and window frame, Hole	16	No	No	N/A	N/A	No	Repair to sheetrock needed
764	6220	1	1	111	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Spalling	7	Yes	No	N/A	N/A	Yes	
765	6220	3	1	008A	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Cracking, Chipping on metal jacket, Hole	13	No	No	N/A	N/A	No	Repair to sheetrock needed
766	6220	1	1	C103	Circulation (Hallway)	Hallway Classroom 101	Ceiling	Flaking, Efflorescence above windows	7	Yes	No	N/A	N/A	Yes	
767	6220	1	1	C103	Circulation (Hallway)	Hallway Classroom 101	Floor	Chipping	3	No	No	N/A	N/A	No	
768	6220	1	1	C103	Circulation (Hallway)	Hallway Classroom 101	W2	Chipping	1	No	No	N/A	N/A	No	
769	6220	1	1	C103	Circulation (Hallway)	Hallway Classroom 101	W3	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
770	6220	1	1	C103	Circulation (Hallway)	Hallway Classroom 101	W4	Chipping, Flaking behind radiator	7	No	Debris on windowsills	6	N/A	No	
771	6220	1	1	C100	Circulation (Hallway)	Hallway Classroom 107	Ceiling	Flaking above windows	4	No	No	N/A	N/A	No	
772	6220	1	1	C100	Circulation (Hallway)	Hallway Classroom 107	Floor	Chipping	10	No	No	N/A	N/A	No	
773	6220	1	1	C100	Circulation (Hallway)	Hallway Classroom 107	W2	Cracking, Chipping, Gouge, Flaking behind radiator	41	No	Debris on windowsills	1	Cabinets	Yes	
774	6220	1	1	C100	Circulation (Hallway)	Hallway Classroom 107	W3	Cracking	20	No	No	N/A	N/A	No	
775	6220	1	1	C100	Circulation (Hallway)	Hallway Classroom 107	W4	Cracking, Chipping	53	No	No	N/A	Furniture, Posters	No	
776	6220	3	1	H002		Hallway from Element 1 to Element 3	W1	Chipping on doors and doorframe, Flaking on door fame	20	No	No	N/A	N/A	No	
777	6220	3	1	H002		Hallway from Element 1 to Element 3	W2	Cracking, Chipping on cove, door, and doorframe,	41	No	No	N/A	Lockers	No	Repair to sheetrock needed
778	6220	3	1	H002		Hallway from Element 1 to Element 3	W4	Chipping on cove, radiator, doors, and doorframe, Flaking on doorframe	64	No	No	N/A	N/A	No	
779	6220	1	1	C102		Hallway from Main Entrance to Classroom 102	Floor	Chipping	25	No	No	N/A	N/A	No	
780	6220	1	1	C102		Hallway from Main Entrance to Classroom 102	W1	Cracking, Hole, Spalling	16	Yes	No	N/A	N/A	Yes	
781	6220	1	1	C102		Hallway from Main Entrance to Classroom 102	W3	Cracking, Chipping on electrical panel, Hole, Flaking	11	No	No	N/A	N/A	Yes	
782	6220	1	1	C101	Circulation (Hallway)	Hallway from Main Entrance to Classroom 106	Floor	Chipping	31	No	No	N/A	N/A	No	
783	6220	1	1	C101	Circulation (Hallway)	Hallway from Main Entrance to Classroom 106	W1	Cracking	21	No	No	N/A	N/A	No	
784	6220	1	1	C101	Circulation (Hallway)	Hallway from Main Entrance to Classroom 106	W3	Chipping on electrical panel, Flaking on radiator shield	4	No	No	N/A	N/A	No	
785	6220	3	1	006A	Kitchen	Kitchen	W1	Cracking, Chipping on wall, door, and doorframe, Hole, Flaking	52	No	No	N/A	Cabinet, Oven, Stored Materials	No	Repair to sheetrock needed
786	6220	3	1	006A	Kitchen	Kitchen	W2	Chipping, Flaking	9	No	No	N/A	Walk-in Refrigerator	No	
787	6220	3	1	006A	Kitchen	Kitchen	W3	Flaking on wall, windows, and window frames	49	No	Paint chips on windowsills	3	Stored Materials	No	
788	6220	3	1	006A	Kitchen	Kitchen	W4	N/A	N/A	No	No	N/A	Walk-in Refrigerator	No	Limited inspection due to stored materials
789	6220	3	1	006A1	Storage	Kitchen Locker Room	W1	Flaking	3	No	No	N/A	Lockers	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
790	6220	3	1	006A1	Storage	Kitchen Locker Room	W2	Chipping	1	No	No	N/A	N/A	No	
791	6220	3	1	006A1	Storage	Kitchen Locker Room	W3	Flaking	9	No	No	N/A	Stored Materials	No	
792	6220	3	1	006A1	Storage	Kitchen Locker Room	W4	Holes, Flaking, Mold	52	Yes	No	N/A	N/A	No	Repair to sheetrock needed
793	6220	3	1	006A2	Restrooms, Staff - Male/Female	Kitchen Restroom	W1	Flaking	16	No	No	N/A	N/A	No	
794	6220	3	1	006A2	Restrooms, Staff - Male/Female	Kitchen Restroom	W2	Chipping, Flaking	2	No	No	N/A	N/A	No	
795	6220	3	1	006A2	Restrooms, Staff - Male/Female	Kitchen Restroom	W3	Chipping, Flaking	7	No	No	N/A	N/A	No	
796	6220	3	1	006A2	Restrooms, Staff - Male/Female	Kitchen Restroom	W4	Flaking on metal pipe	2	No	No	N/A	N/A	No	
797	6220	1	1	MEL	Lobby	Main Entrance Lobby	Ceiling	Cracking	9	No	No	N/A	N/A	No	
798	6220	1	1	MEL	Lobby	Main Entrance Lobby	W1	Chipping on doors and doorframe, Flaking on doorframe	32	No	No	N/A	N/A	No	
799	6220	1	1	112	Administrative Office	Main Office	Ceiling	Flaking, Efflorescence above windows	13	Yes	No	N/A	N/A	Yes	
800	6220	1	1	112	Administrative Office	Main Office	W1	Chipping	1	No	No	N/A	Stored Materials	No	
801	6220	1	1	112	Administrative Office	Main Office	W2	Holes	2	No	No	N/A	Furniture	Yes	
802	6220	1	1	112	Administrative Office	Main Office	W3	N/A	N/A	No	Debris on windowsills	8	Stored Materials	No	
803	6220	1	1	112	Administrative Office	Main Office	W4	Cracking, Chipping	10	No	No	N/A	Cabinet, Chairs	No	
804	6220	1	1	112C	Storage	Main Office Closet	Ceiling	Hole	1	No	No	N/A	Shelves, Stored Materials	Yes	
805	6220	1	1	112C	Storage	Main Office Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
806	6220	1	1	112C	Storage	Main Office Closet	W1	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
807	6220	1	1	112C	Storage	Main Office Closet	W2	Holes	6	No	No	N/A	Shelves, Stored Materials	Yes	
808	6220	1	1	112C	Storage	Main Office Closet	W3	Cracking	1	No	No	N/A	Shelves, Stored Materials	No	
809	6220	1	1	112C	Storage	Main Office Closet	W4	Cracking	12	No	No	N/A	Shelves, Stored Materials	No	
810	6220	3	1	005A	Primary	Music Room	W1	Cracking, Chipping on wall, cove, door, and doorframe, Hole	54	No	No	N/A	Posters	No	Repair to sheetrock needed
811	6220	3	1	005A	Primary	Music Room	W2	Chipping on wall and cove	13	No	No	N/A	Cabinets	No	
812	6220	3	1	005A	Primary	Music Room	W3	Cracking, Chipping, Flaking on windows and window frames	39	No	No	N/A	N/A	No	Repair to sheetrock needed
813	6220	3	1	005A	Primary	Music Room	W4	Chipping on wall and cove	27	No	No	N/A	Posters	No	
814	6220	1	1	104D	Administrative Office	Nurse's Office	W1	Chipping on doorframe	6	No	No	N/A	N/A	No	
815	6220	1	1	104D	Administrative Office	Nurse's Office	W2	Chipping, Flaking	6	No	No	N/A	N/A	No	
816	6220	1	1	104D	Administrative Office	Nurse's Office	W4	Chipping, Flaking	6	No	No	N/A	N/A	No	
817	6220	1	1	104D	Administrative Office	Nurse's Office	W3	Cracking, Flaking	4	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
818	6220	1	1	104J		Nurse's Office Closet	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	
819	6220	1	1	104B	Administrative Office	Nurse's Office Exam Room	W1	Chipping on wall and doorframes, Gouge	8	No	No	N/A	N/A	Yes	
820	6220	1	1	104B	Administrative Office	Nurse's Office Exam Room	W2	Cracking, Efflorescence in air shaft	9	Yes	No	N/A	N/A	Yes	
821	6220	1	1	104B	Administrative Office	Nurse's Office Exam Room	W3	Chipping, Flaking	12	No	No	N/A	Furniture	No	
822	6220	1	1	104H	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	Ceiling	Hole, Efflorescence above missing ceiling tile	6	Yes	No	N/A	N/A	Yes	
823	6220	1	1	104H	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W1	Chipping on doorframe, Flaking	2	No	No	N/A	N/A	No	
824	6220	1	1	104H	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W2	Cracking, Chipping on wall and radiator	11	No	Debris on windowsill	3	N/A	No	
825	6220	1	1	104H	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W3	Chipping, Flaking, Efflorescence above missing ceiling tile	9	Yes	No	N/A	N/A	Yes	
826	6220	1	1	104H	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W4	Flaking	1	No	No	N/A	N/A	No	
827	6220	1	1	104F	Administrative Office	Nurse's Office Storage Room	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
828	6220	1	1	104F	Administrative Office	Nurse's Office Storage Room	W3	Chipping	2	No	No	N/A	Cabinets, Shelf	No	
829	6220	1	1	104F	Administrative Office	Nurse's Office Storage Room	W4	Chipping	1	No	No	N/A	Cabinets	No	
830	6220	1	1	104C	Administrative Office	Nurse's Office Waiting Room	W1	Cracking, Chipping, Flaking	17	No	No	N/A	N/A	No	
831	6220	1	1	104C	Administrative Office	Nurse's Office Waiting Room	W2	Chipping	1	No	No	N/A	N/A	No	
832	6220	1	1	104C	Administrative Office	Nurse's Office Waiting Room	W3	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
833	6220	1	1	104C	Administrative Office	Nurse's Office Waiting Room	W4	Chipping	1	No	No	N/A	N/A	No	
834	6220	1	1	104E	Storage	Nurse's Waiting Room Closet	W1	Chipping on acoustical wall tile and doorframe	4	No	No	N/A	N/A	No	Acoustical wall tiles are assumed
835	6220	1	1	104E	Storage	Nurse's Waiting Room Closet	W2	Hole in acoustical wall tile	1	No	No	N/A	N/A	No	Acoustical wall tiles are assumed
836	6220	1	1	104E	Storage	Nurse's Waiting Room Closet	W3	Chipping on metal pipe	2	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
837	6220	3	1	H001	Circulation (Hallway)	Portable Hallway	Ceiling	Chipping, Flaking, Spalling	8	Yes	No	N/A	N/A	No	
838	6220	3	1	H001	Circulation (Hallway)	Portable Hallway	W1	Chipping on doors and doorframe	39	No	No	N/A	N/A	No	
839	6220	3	1	H001	Circulation (Hallway)	Portable Hallway	W2	Chipping on cove	28	No	No	N/A	N/A	No	
840	6220	3	1	H001	Circulation (Hallway)	Portable Hallway	W3	Cracking, Chipping on doors	8	No	No	N/A	N/A	No	
841	6220	3	1	H001	Circulation (Hallway)	Portable Hallway	W4	Chipping on cove	42	No	No	N/A	N/A	No	
842	6220	1	1	112A	Administrative Office	Principal's Office	W1	N/A	N/A	No	No	N/A	Posters, Cabinet, Stored Materials	No	Limited inspection due to stored materials
843	6220	1	1	112A	Administrative Office	Principal's Office	W2	Chipping	3	No	No	N/A	Stored Materials	No	
844	6220	1	1	112A	Administrative Office	Principal's Office	W3	N/A	N/A	No	No	N/A	Furniture, Pictures	No	Limited inspection due to stored materials
845	6220	1	1	112A	Administrative Office	Principal's Office	W4	Flaking on radiator shield	5	No	Debris on windowsills	4	Stored Materials	No	
846	6220	1	1	112B	Restrooms, Staff - Male/Female	Principal's Office Restroom	Ceiling	Cracking	1	No	No	N/A	N/A	No	
847	6220	3	1	001A	Storage	Prize Room	W1	Cracking, Chipping on wall, cove, door, and doorframe, Gouge	42	No	No	N/A	Posters	No	Repair to sheetrock needed
848	6220	3	1	001A	Storage	Prize Room	W2	Chipping on cove	4	No	No	N/A	Stored Materials	No	
849	6220	3	1	001A	Storage	Prize Room	W3	Cracking, Flaking on metal jacket, windows, and window frames	45	No	No	N/A	Stored Materials	No	Repair to sheetrock needed
850	6220	3	1	001A	Storage	Prize Room	W4	Chipping, Gouges, Flaking	11	No	No	N/A	N/A	No	Repair to sheetrock needed
851	6220	3	1	100A2	Storage	Prize Room Closet next to Restroom	W1	Chipping on wall, doorframe, and cove, Flaking	23	No	No	N/A	Stored Materials	No	
852	6220	3	1	100A2	Storage	Prize Room Closet next to Restroom	W3	Chipping on wall and cove	10	No	No	N/A	Furniture	No	Limited inspection due to stored materials
853	6220	3	1	100A2	Storage	Prize Room Closet next to Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
854	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
855	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
856	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
857	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
858	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
859	6220	3	1	100A3	Storage	Prize Room Closet on exterior wall	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
860	6220	3	1	001A1	Student Restrooms - Male/Female (Classroom)	Prize Room Restroom	W1	Chipping on doorframe, Flaking	18	No	No	N/A	N/A	No	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
861	6220	3	1	001A1	Student Restrooms - Male/Female (Classroom)	Prize Room Restroom	W2	Flaking on metal pipe	2	No	No	N/A	N/A	No	
862	6220	3	1	001A1	Student Restrooms - Male/Female (Classroom)	Prize Room Restroom	W3	Flaking	4	No	No	N/A	N/A	No	
863	6220	3	1	001A1	Student Restrooms - Male/Female (Classroom)	Prize Room Restroom	W4	Chipping	2	No	No	N/A	N/A	No	
864	6220	1	1	105C	Administrative Office	School Psychologist's Office (next to 106)	Floor	Chipping	5	No	No	N/A	N/A	No	
865	6220	1	1	105C	Administrative Office	School Psychologist's Office (next to 106)	W1	Chipping on doorframe	3	No	No	N/A	Desk	No	
866	6220	1	1	105C	Administrative Office	School Psychologist's Office (next to 106)	W2	Cracking	24	No	No	N/A	Picture	No	
867	6220	1	1	105C	Administrative Office	School Psychologist's Office (next to 106)	W3	Chipping	3	No	No	N/A	Cabinet, Stored Materials	No	
868	6220	1	1	105C	Administrative Office	School Psychologist's Office (next to 106)	W4	N/A	N/A	No	No	N/A	Desks, Stored Materials	No	Limited inspection due to stored materials
869	6220	1	1	S12	Stairs	Stairwell across from Classroom 107	Floor	Chipping on stairs, cove, and railings	69	No	No	N/A	N/A	No	
870	6220	1	1	S12	Stairs	Stairwell across from Classroom 107	W1	Spalling	1	Yes	No	N/A	N/A	Yes	
871	6220	1	1	S12	Stairs	Stairwell across from Classroom 107	W2	Flaking behind radiator, Spalling	9	Yes	No	N/A	N/A	Yes	
872	6220	1	1	S12	Stairs	Stairwell across from Classroom 107	W3	Spalling	2	Yes	No	N/A	N/A	Yes	
873	6220	1	1	S12	Stairs	Stairwell across from Classroom 107	W4	Chipping on doors and doorframe	52	No	No	N/A	N/A	No	
874	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	Ceiling	Flaking, Spalling	9	Yes	No	N/A	N/A	Yes	
875	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	Floor	Chipping	10	No	Debris in wall 3 corners	2	N/A	No	
876	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	W1	Gouge, Spalling	6	Yes	No	N/A	N/A	Yes	
877	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	W2	Spalling, Flaking on wall and metal pipe, Efflorescence	18	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
878	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	W3	Flaking, Efflorescence	18	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
879	6220	1	1	S12A		Stairwell across from Classroom 107 Vestibule	W4	Chipping on wall, doors, and doorframe, Flaking on doorframe, Efflorescence	44	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
880	6220	1	1	S13	Stairs	Stairwell across from Copy Room 101A	Ceiling	Cracking	3	No	No	N/A	N/A	No	
881	6220	1	1	S13	Stairs	Stairwell across from Copy Room 101A	Floor	Chipping on stairs, cove, and railings	68	No	No	N/A	N/A	No	
882	6220	1	1	S13	Stairs	Stairwell across from Copy Room 101A	W2	Cracking, Chipping on doors and doorframe	36	No	No	N/A	N/A	No	
883	6220	1	1	S13	Stairs	Stairwell across from Copy Room 101A	W3	Efflorescence	2	Yes	No	N/A	N/A	Yes	
884	6220	1	1	S13	Stairs	Stairwell across from Copy Room 101A	W4	Cracking, Hole	3	No	No	N/A	N/A	Yes	
885	6220	1	1	S13A		Stairwell across from Copy Room 101A Vestibule	Floor	Chipping	17	No	No	N/A	N/A	No	
886	6220	1	1	S13A		Stairwell across from Copy Room 101A Vestibule	W1	Hole	1	No	No	N/A	N/A	Yes	
887	6220	1	1	S13A		Stairwell across from Copy Room 101A Vestibule	W2	Spalling	2	Yes	No	N/A	N/A	Yes	
888	6220	1	1	S13A		Stairwell across from Copy Room 101A Vestibule	W3	Chipping on doors, Flaking on doorframe, Spalling	86	Yes	No	N/A	N/A	Yes	
889	6220	3	1	008B	Restrooms, Staff - Female	Women's Restroom	W1	Chipping on door and doorframe	16	No	No	N/A	N/A	No	
890	6220	3	1	008B	Restrooms, Staff - Female	Women's Restroom	W2	Chipping, Flaking	9	No	No	N/A	N/A	No	
891	6220	3	1	008B	Restrooms, Staff - Female	Women's Restroom	W3	Cracking	1	No	No	N/A	N/A	No	
892	6220	3	1	008B	Student Restrooms - Female (4-12)	Women's Restroom	W4	Chipping on cove	1	No	No	N/A	N/A	No	
893	6220	1	0	17	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking	56	No	No	N/A	N/A	No	
894	6220	1	0	17	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipping on floor and pole near entrance, Flaking	241	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
895	6220	1	0	17	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Flaking	8	No	No	N/A	N/A	No	
896	6220	1	0	17	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Chipping on wall and window frames, Flaking	67	No	No	N/A	N/A	No	
897	6220	1	0	17	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Chipping, Flaking	5	No	No	N/A	N/A	No	
898	6220	1	0	001SB	Mechanical Room	Condensate Tank Room	Floor	N/A	N/A	No	ACM debris	5	N/A	No	
899	6220	1	0	19	Storage	Custodial Restroom	Ceiling	Chipping, Flaking on radiator	13	No	No	N/A	N/A	No	
900	6220	1	0	19	Storage	Custodial Restroom	W1	Chipping on door, Flaking	15	No	No	N/A	N/A	No	
901	6220	1	0	19	Storage	Custodial Restroom	W2	Flaking	30	No	No	N/A	N/A	No	
902	6220	1	0	19	Storage	Custodial Restroom	W3	Flaking	25	No	No	N/A	N/A	No	
903	6220	1	0	19	Storage	Custodial Restroom	W4	Flaking	65	No	No	N/A	N/A	No	
904	6220	1	0	20	Storage	Custodial Restroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
905	6220	1	0	20	Storage	Custodial Restroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
906	6220	1	0	20	Storage	Custodial Restroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
907	6220	1	0	20	Storage	Custodial Restroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
908	6220	1	0	20	Storage	Custodial Restroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
909	6220	1	0	20	Storage	Custodial Restroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
910	6220	1	0	3	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Chipping on ceiling and metal duct	7	No	No	N/A	N/A	No	
911	6220	1	0	3	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Flaking	2	No	No	N/A	N/A	No	
912	6220	1	0	3	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Chipping	6	No	No	N/A	N/A	No	
913	6220	1	0	3	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Chipping on conduit line	1	No	No	N/A	N/A	No	
914	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	Ceiling	Cracking, Chipping on metal pipes, Hole, Spalling	43	Yes	No	N/A	N/A	Yes	
915	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	Floor	Chipping	132	No	No	N/A	N/A	No	
916	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	W1	Chipping on metal pipe, Efflorescence	77	Yes	No	N/A	N/A	No	Entrance from Boy's Side
917	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	W2	Chipping	3	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
918	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	W3	Chipping on metal pipe, Efflorescence	11	Yes	No	N/A	N/A	No	
919	6220	1	0	14	Gymnasium - Intermediate Middle	Gym	W4	Chipping on doors and doorframes, Flaking on doorframes	49	No	No	N/A	N/A	No	
920	6220	1	0	11	Storage	Gym Equipment Storage next to Gym Office	W1	Chipping	17	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
921	6220	1	0	11	Storage	Gym Equipment Storage next to Gym Office	W2	Chipping, Holes	12	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials. Repair to brick needed.
922	6220	1	0	11	Storage	Gym Equipment Storage next to Gym Office	W3	Chipping	30	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
923	6220	1	0	11	Storage	Gym Equipment Storage next to Gym Office	W4	Chipping	7	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
924	6220	1	0	10	Administrative Office	Gym Office	Ceiling	Cracking	50	No	No	N/A	N/A	Yes	
925	6220	1	0	10	Administrative Office	Gym Office	W1	Chipping, Flaking	3	No	No	N/A	N/A	No	
926	6220	1	0	10	Administrative Office	Gym Office	W2	Flaking	15	No	No	N/A	N/A	No	
927	6220	1	0	10	Administrative Office	Gym Office	W4	Flaking	2	No	No	N/A	N/A	No	
928	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
929	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
930	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
931	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
932	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
933	6220	1	0	12	Storage	Gym Storage next to Boiler Room Entrance Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
934	6220	1	0	9	Storage	Gym Storage next to Sharpnack St Stairwell	Ceiling	Cracking	30	No	No	N/A	N/A	No	
935	6220	1	0	9	Storage	Gym Storage next to Sharpnack St Stairwell	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
936	6220	1	0	9	Storage	Gym Storage next to Sharpnack St Stairwell	W3	Flaking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
937	6220	1	0	9	Storage	Gym Storage next to Sharpnack St Stairwell	W4	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
938	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	Ceiling	Flaking on ceiling, radiator, and metal duct	43	No	No	N/A	N/A	No	
939	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	Floor	Chipping	30	No	No	N/A	N/A	No	
940	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	W1	Chipping	3	No	No	N/A	N/A	No	
941	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	W2	Chipping, Flaking, Mold	27	No	No	N/A	N/A	No	
942	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	W3	Chipping on wall and metal pipe, Flaking	8	No	No	N/A	N/A	No	
943	6220	1	0	C021	Circulation (Hallway)	Hallway from Boy's Restroom to Custodial Storage Room	W4	Flaking	8	No	No	N/A	N/A	No	
944	6220	1	0	15	Circulation (Hallway)	Hallway from Girl's Restroom to Music Room	Ceiling	Holes, Flaking	58	No	No	N/A	N/A	Yes	
945	6220	1	0	15	Circulation (Hallway)	Hallway from Girl's Restroom to Music Room	Floor	Chipping on stairs	26	No	No	N/A	N/A	No	
946	6220	1	0	15	Circulation (Hallway)	Hallway from Girl's Restroom to Music Room	W3	Flaking, Mold	9	No	No	N/A	N/A	No	
947	6220	1	0	15	Circulation (Hallway)	Hallway from Girl's Restroom to Music Room	W4	Chipping on door and doorframe, Flaking on wall, door, and doorframe	37	No	No	N/A	N/A	No	
948	6220	1	0	15A		Hallway from Girl's Restroom to Music Room Closet	Ceiling	Cracking, Flaking	4	No	No	N/A	N/A	No	Repair to concrete needed
949	6220	1	0	15A		Hallway from Girl's Restroom to Music Room Closet	W1	Flaking	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
950	6220	1	0	15A		Hallway from Girl's Restroom to Music Room Closet	W3	Chipping	4	No	No	N/A	N/A	No	
951	6220	1	0	4	Kitchen	Head Start Kitchen	Ceiling	Chipping on radiator and metal pipes, Flaking on ceiling and metal duct	50	No	No	N/A	N/A	No	
952	6220	1	0	4	Kitchen	Head Start Kitchen	Floor	N/A	N/A	No	Paint chips along walls 3&4	12	N/A	No	
953	6220	1	0	4	Kitchen	Head Start Kitchen	W1	Flaking	1	No	No	N/A	Stored Materials	No	
954	6220	1	0	4	Kitchen	Head Start Kitchen	W2	Chipping on doorframe, Flaking on wall and metal pipe	30	No	No	N/A	Tables	No	
955	6220	1	0	4	Kitchen	Head Start Kitchen	W3	Chipping, Flaking on wall and metal pipes	15	No	No	N/A	N/A	No	
956	6220	1	0	4	Kitchen	Head Start Kitchen	W4	Chipping, Flaking	17	No	No	N/A	Cabinets, Oven	No	
957	6220	1	0	6	Primary	Music Room	Ceiling	Flaking	10	No	No	N/A	N/A	No	
958	6220	1	0	6	Primary	Music Room	Floor	Chipping	66	No	No	N/A	N/A	No	
959	6220	1	0	6	Primary	Music Room	W1	Chipping on metal pipe	1	No	No	N/A	N/A	No	
960	6220	1	0	6	Primary	Music Room	W2	Chipping	10	No	No	N/A	N/A	No	
961	6220	1	0	6	Primary	Music Room	W3	Chipping	9	No	No	N/A	N/A	No	
962	6220	1	0	6	Primary	Music Room	W4	Chipping, Efflorescence on non painted bricks	10	Yes	No	N/A	N/A	No	
963	6220	1	0	SBB	Stairs	Stairwell across from Boy's Restroom	Floor	Chipping on stairs and cove	29	No	No	N/A	N/A	No	
964	6220	1	0	SBB	Stairs	Stairwell across from Boy's Restroom	W1	Cracking, Chipping on electrical panel	12	No	No	N/A	N/A	No	
965	6220	1	0	SBB	Stairs	Stairwell across from Boy's Restroom	W2	Cracking	3	No	No	N/A	N/A	No	
966	6220	1	0	SBB	Stairs	Stairwell across from Boy's Restroom	W3	Cracking, Spalling, Efflorescence	21	Yes	No	N/A	N/A	Yes	
967	6220	1	0	SBB	Stairs	Stairwell across from Boy's Restroom	W4	Cracking, Chipping on wall, doors, and doorframe	52	No	No	N/A	N/A	No	
968	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	Ceiling	Significant Moisture Damage	50	Yes	No	N/A	N/A	Yes	
969	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	Floor	N/A	N/A	No	Debris throughout	50	N/A	No	
970	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	W1	Significant Moisture Damage	85	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
971	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	W2	Significant Moisture Damage	85	Yes	No	N/A	N/A	Yes	
972	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	W3	Significant Moisture Damage	85	Yes	No	N/A	N/A	Yes	
973	6220	1	0	SBB2		Stairwell across from Boy's Restroom Closet adjacent to Gym	W4	Significant Moisture Damage	85	Yes	No	N/A	N/A	Yes	
974	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	Ceiling	Flaking	7	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
975	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
976	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
977	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
978	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
979	6220	1	0	SBB1		Stairwell across from Boy's Restroom Closet under Stairs	W4	Flaking	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
980	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	Ceiling	Flaking	2	No	No	N/A	N/A	No	
981	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	Floor	Chipping on stairs and cove	60	No	No	N/A	N/A	No	
982	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	W1	Chipping on electrical panel	8	No	No	N/A	N/A	No	
983	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	W2	Chipping on doors and doorframe	29	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
984	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	W3	Efflorescence	25	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
985	6220	1	0	SBC	Stairs	Stairwell across from Head Start Kitchen	W4	Chipping	1	No	No	N/A	N/A	No	
986	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
987	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
988	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
989	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
990	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
991	6220	1	0	009B		Stairwell across from Head Start Kitchen Closet adjacent to Gym	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
992	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
993	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
994	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
995	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
996	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
997	6220	1	0	009A		Stairwell across from Head Start Kitchen Closet under Stairs	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
998	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	Ceiling	Chipping on metal duct, Flaking on ceiling and metal duct	56	No	No	N/A	N/A	No	
999	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	Floor	N/A	N/A	No	Paint chips scattered	5	N/A	No	
1000	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	W1	Flaking	20	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
1001	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	W2	Flaking	10	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
1002	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	W3	Flaking	11	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
1003	6220	1	0	8	Storage	Storage Closet across from Head Start Kitchen	W4	Flaking	20	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
1004	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	Ceiling	Flaking on ceiling and metal pipes	19	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1005	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1006	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	W1	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1007	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	W2	Chipping	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1008	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1009	6220	1	0	18	Storage	Storage Room adjacent to Boy's Room	W4	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
1010	6220	2	0	2	Storage	Storage Room adjacent to Element 1 Girl's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

