

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7270	1	3	301	Primary	Classroom 301	Ceiling	Flaking paint at all windows.	10	Y				Y	
2	7270	1	3	301	Primary	Classroom 301	W3	Flaking paint near entrance, behind radiator, and at windows.	25	Y	Sill, Floor	1		N	
3	7270	1	3	301	Primary	Classroom 301	W4	Flaking paint below blackboard.	3	N				N	
4	7270	1	3	302	Primary	Classroom 302	Ceiling	Flaking paint at ceilings.	5	N				N	
5	7270	1	3	302	Primary	Classroom 302	W1	Flaking paint below blackboard	1	N				N	
6	7270	1	3	302	Primary	Classroom 302	W2	Flaking paint near entrance	2	N				Y	
7	7270	1	3	302	Primary	Classroom 302	W3	Flaking paint below windows and behind radiator.	10	Y	Sill, Floor	2		N	
8	7270	1	3	302	Primary	Classroom 302	W4	Flaking paint at wall near entrance.	2	N				N	
9	7270	1	3	303	Primary	Classroom 303	Ceiling	Flaking paint at windows.	10	Y				N	
10	7270	1	3	303	Primary	Classroom 303	W2	Flaking paint near entrance	2	N				N	
11	7270	1	3	303	Primary	Classroom 303	W3	Flaking paint below windows, behind radiators and to the left and right of window 1.	10	Y	Sill, Floor	1		Y	
12	7270	1	3	304	Primary	Classroom 304	Ceiling	Flaking paint at windows.	5	Y				N	
13	7270	1	3	304	Primary	Classroom 304	W1	Flaking paint near entrance and below blackboard	2	N				N	
14	7270	1	3	304	Primary	Classroom 304	W2	Flaking paint near entrance	2	N				N	
15	7270	1	3	304	Primary	Classroom 304	W3	Flaking paint below windows and at columns	20	Y				N	
16	7270	1	3	304A	Storage	Classroom 304 Closet	W2	Flaking paint above and below coat rack.	2	N				N	
17	7270	1	3	305	Primary	Classroom 305	W1	Chipped paint below blackboard	2	N				N	
18	7270	1	3	305	Primary	Classroom 305	W2	Flaking paint near entrance	2	N				N	
19	7270	1	3	305	Primary	Classroom 305	W3	Flaking paint below and around windows and behind radiator	10	Y	Sill, Floor	5		Y	
20	7270	1	3	305A	Storage	Classroom 305 Closet	W4	Flaking paint near light switch	2	N				N	
21	7270	1	3	306	Primary	Classroom 306	W2	Flaking paint near entrance	2	N				N	
22	7270	1	3	306	Primary	Classroom 306	W3	Flaking paint above and below windows	10	Y	Sills, Floor	2		N	
23	7270	1	3	307	Primary	Classroom 307	Ceiling	Flaking paint at windows	5	Y				N	
24	7270	1	3	307	Primary	Classroom 307	W1	Chipped paint, plaster at door	1	N				Y	
25	7270	1	3	307	Primary	Classroom 307	W2	Flaking paint near entrance.	2	N				N	
26	7270	1	3	307	Primary	Classroom 307	W3	Flaking paint below and to the sides of windows.	10	Y				Y	
27	7270	1	3	307B	Storage	Classroom 307 Closet	W2	Flaking paint, damaged plaster where coat hangar is unattached.	2	N				Y	
28	7270	1	3	308	Primary	Classroom 308	Ceiling	Flaking paint at windows	15	Y				N	
29	7270	1	3	308	Primary	Classroom 308	W1	Flaking paint below blackboard	2	N				N	
30	7270	1	3	308	Primary	Classroom 308	W3	Flaking paint all around windows and behind radiator	15	Y	Sill, Floor	2		N	
31	7270	1	3	308	Primary	Classroom 308	W4	Flaking paint near entrance with plaster damaged.	2	N				Y	
32	7270	1	3	308A	Storage	Classroom 308 Closet	Ceiling	Flaking paint at windows	5	Y				N	
33	7270	1	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint above and to the side of window	5	Y				N	
34	7270	1	3	309	Primary	Classroom 309	Ceiling	Flaking paint at windows	5	Y				N	
35	7270	1	3	309	Primary	Classroom 309	W1	Flaking paint near entrance	2	N				N	
36	7270	1	3	309	Primary	Classroom 309	W2	Flaking paint near entrance	2	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
37	7270	1	3	309	Primary	Classroom 309	W3	Flaking paint around windows and on walls, and behind radiator	25	Y	Sills, Floor	5	Tables, supplies, posters, bookshelves	Y	
38	7270	1	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint at ceiling	5	N			Supplies, Cart, Books	N	
39	7270	1	3	310	Primary	Classroom 310	Ceiling	Flaking paint at windows	5	Y				Y	
40	7270	1	3	310	Primary	Classroom 310	W1	Flaking paint near entrance	2	N				N	
41	7270	1	3	310	Primary	Classroom 310	W2	Flaking paint near entrance	2	N				N	
42	7270	1	3	310	Primary	Classroom 310	W3	Flaking paint around windows, on walls, and behind radiator	25	Y	Sills, Floor	5	Posters, bookshelves	Y	
43	7270	1	3	311	Primary	Classroom 311	Ceiling	Flaking paint at windows	5	Y				Y	
44	7270	1	3	311	Primary	Classroom 311	W1	Flaking paint above and to the right of blackboard	5	N				N	
45	7270	1	3	311	Primary	Classroom 311	W2	Flaking paint near entrance	2	N				N	
46	7270	1	3	311	Primary	Classroom 311	W3	Flaking paint around windows, on walls, and behind radiator	25	Y	Sills, Floor	5	Posters.	Y	
47	7270	1	3	311	Primary	Classroom 311	W4	Flaking paint near entrance	2	N				Y	
48	7270	1	3	311C	Storage	Classroom 311 Storage	W2	Flaking paint below window and at pipe	3	Y				N	
49	7270	1	3	311C	Storage	Classroom 311 Storage	W3	Flaking paint where coatrack had been	1	N				Y	
50	7270	1	3	311A	Administrative Office	Copier Room at Room 301	W4	Flaking paint below window	1	Y				N	
51	7270	1	3	304B	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	Ceiling	Flaking paint, plaster damaged near light	1	N				N	
52	7270	1	3	304B	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	W2	Flaking paint, plaster damage near ceiling	2	N				N	
53	7270	1	3	H31	Circulation (Hallway)	Hallway at Rooms 301 to 303	Floor	Chipped paint at floors	150	N				N	
54	7270	1	3	H31	Circulation (Hallway)	Hallway at Rooms 301 to 303	W4	Damaged plaster outside Room 311	1	N				Y	
55	7270	1	3	H32	Circulation (Hallway)	Hallway at Rooms 304 to 307	Floor	Chipped paint at floors	400	N				N	
56	7270	1	3	H32	Circulation (Hallway)	Hallway at Rooms 304 to 307	W3	Flaking paint at windows 2, 3 & 4. Damaged plaster across from 306	25	Y				Y	
57	7270	1	3	H33	Circulation (Hallway)	Hallway at Rooms 308 to 310	Floor	Chipped paint at floors	50	N				N	
58	7270	1	3	H33	Circulation (Hallway)	Hallway at Rooms 308 to 310	W2	Chipped paint at electrical conduit.	2	N				N	
59	7270	1	3	311B	Restrooms, Staff - Male/Female	Room 311 Restroom	W3	Flaking paint around windows	5	Y				Y	
60	7270	1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	Ceiling	Flaking paint at ceiling	10	N				N	
61	7270	1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	W2	Chipped plaster.	2	N				N	
62	7270	1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	W3	Flaking paint at pipe and radiator.	15	N				N	
63	7270	1	2	207B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	W4	Flaking paint at pipe.	1	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
64	7270	1	2	201	Primary	Classroom 201	Ceiling	Flaking paint at windows.	10	Y			Classroom supplies.	N	
65	7270	1	2	201	Primary	Classroom 201	W3	Flaking paint, efflorescence to side of Window 5 with debris.	5	Y	Sill	1		N	
66	7270	1	2	201	Primary	Classroom 201	W4	Flaking paint at wall near entrance.	2	N				N	
67	7270	1	2	201A	Storage	Classroom 201 Closet	W2	Flaking paint at left side of window with debris.	2	Y	Floor	1		N	
68	7270	1	2	201A	Storage	Classroom 201 Closet	W4	Flaking paint, plaster damage near entrance	2	N				Y	
69	7270	1	2	202	Primary	Classroom 202	Ceiling	Flaking paint above windows	10	Y				N	
70	7270	1	2	202	Primary	Classroom 202	W2	Flaking paint, plaster damage near entrance	2	N				Y	
71	7270	1	2	202	Primary	Classroom 202	W4	Flaking paint at sides of windows and behind radiator. Debris	15	Y	Sill, Floor.	4		N	
72	7270	1	2	203	Primary	Classroom 203	Ceiling	Flaking paint at windows.	5	Y				N	
73	7270	1	2	203	Primary	Classroom 203	W1	Flaking paint above and below blackboard	4	N				N	
74	7270	1	2	203	Primary	Classroom 203	W2	Flaking paint near entrance and above and below bulletin board.	5	N				N	
75	7270	1	2	203	Primary	Classroom 203	W3	Flaking at and around windows on walls.	20	Y	Sills, Floor.	5	Posters, supplies.	N	
76	7270	1	2	203A	Storage	Classroom 203 Closet	W3	Flaking paint, damaged plaster.	1	N				N	
77	7270	1	2	203A	Storage	Classroom 203 Closet	W4	Spalling paint/plaster.	2	Y			Cabinets	N	
78	7270	1	2	204	Primary	Classroom 204	Ceiling	Flaking paint at windows	10	Y					
79	7270	1	2	204	Primary	Classroom 204	W1	Flaking paint below blackboard	2	N				N	
80	7270	1	2	204	Primary	Classroom 204	W3	Flaking paint at walls by Windows 1 & 4	20	Y			Posters	N	
81	7270	1	2	204	Primary	Classroom 204	W4	Flaking paint below blackboard	5	N				Y	
82	7270	1	2	204A	Storage	Classroom 204 Closet	W1	Flaking paint at wall.	3	N			Supplies	N	
83	7270	1	2	205	Primary	Classroom 205	Ceiling	Flaking paint near windows.	10	Y				N	
84	7270	1	2	205	Primary	Classroom 205	W1	Flaking paint at front door, near entrance, and below blackboard.	8	N				N	
85	7270	1	2	205	Primary	Classroom 205	W2	Flaking paint near entrance.	2	N				N	
86	7270	1	2	205	Primary	Classroom 205	W3	Flaking paint by Windows 1 & 4	20	Y	Sill	5	Posters	N	
87	7270	1	2	205	Primary	Classroom 205	W4	Flaking paint below phone near entrance	1	N				N	
88	7270	1	2	206	Primary	Classroom 206	Ceiling	Flaking paint at windows	10	Y				N	
89	7270	1	2	206	Primary	Classroom 206	W1	Chipped paint below blackboard	3	N				N	
90	7270	1	2	206	Primary	Classroom 206	W2	Chipped paint near entrance	3	N				N	
91	7270	1	2	206	Primary	Classroom 206	W3	Flaking paint below windows and behind radiator	15	Y			Posters, Bookshelves, Cabinets,	N	
92	7270	1	2	207	Primary	Classroom 207	Ceiling	Flaking paint at windows	15	Y				N	
93	7270	1	2	207	Primary	Classroom 207	W1	Flaking paint by entrance and below blackboard	5	N				N	
94	7270	1	2	207	Primary	Classroom 207	W2	Flaking paint above blackboard	40	N				N	
95	7270	1	2	207	Primary	Classroom 207	W3	Flaking paint below and around windows	30	Y			2 Bookshelves	N	
96	7270	1	2	208	Primary	Classroom 208	W2	Flaking paint above blackboard	2	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
97	7270	1	2	208	Primary	Classroom 208	W3	Flaking paint around and below window 1. Flaking paint at sides of window 5. Flaking paint at pipe . Paint debris at window 4 sill.	25	Y	Sill, Floor	2	Posters, Bookshelves	N	
98	7270	1	2	208	Primary	Classroom 208	W4	Flaking paint by entrance and closet.	2	N				N	
99	7270	1	2	208A	Storage	Classroom 208 Closet	W2	Flaking paint at pipe.	5	N	Floor	1		N	
100	7270	1	2	209	Primary	Classroom 209	Ceiling	Flaking paint at ceiling.	5	Y				N	
101	7270	1	2	209	Primary	Classroom 209	W1	Flaking paint below blackboard	2	N				N	
102	7270	1	2	209	Primary	Classroom 209	W2	Flaking paint near entrance	2	N				N	
103	7270	1	2	209	Primary	Classroom 209	W3	Flaking paint below windows	30	Y				N	
104	7270	1	2	209	Primary	Classroom 209	W4	Flaking paint by entrance and above blackboard	10	N				N	
105	7270	1	2	210	Primary	Classroom 210	W1	Flaking paint below blackboard	1	N				N	
106	7270	1	2	210	Primary	Classroom 210	W2	Flaking paint near entrance, above blackboard and on pipe.	20	N				N	
107	7270	1	2	210	Primary	Classroom 210	W3	Flaking paint below and around windows and on pipe.	30	Y				N	
108	7270	1	2	210A	Storage	Classroom 210 Closet	Ceiling	Flaking paint at ceiling.	30	N				N	
109	7270	1	2	210A	Storage	Classroom 210 Closet	W4	Flaking paint at wall with debris	40	N	10	Floor, Cart, Supplies	Supplies, Cart.	N	
110	7270	1	2	203B	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	Ceiling	Efflorescence at ceiling.	5	Y				N	
111	7270	1	2	H21	Circulation (Hallway)	Hallway at Rooms 201 to 203	Floor	Chipped paint at floors	150	N				N	
112	7270	1	2	H22	Circulation (Hallway)	Hallway at Rooms 204 to 207	Floor	Chipped paint at floors	150	N				N	
113	7270	1	2	H22	Circulation (Hallway)	Hallway at Rooms 204 to 207	W3	Flaking paint at windows 1 & 2.	20	Y				N	
114	7270	1	2	H23	Circulation (Hallway)	Hallway at Rooms 208 to 210	Floor	Chipped paint at floors	150	N				N	
115	7270	1	2	217	Administrative Office	Health Service Office	Ceiling	Flaking paint at windows 4.	1	Y				N	
116	7270	1	2	217	Administrative Office	Health Service Office	W1	Flaking paint at baseboards	10	N				N	
117	7270	1	2	217	Administrative Office	Health Service Office	W2	Flaking paint at baseboards	10	N				N	
118	7270	1	2	217	Administrative Office	Health Service Office	W3	Flaking paint at baseboards	10	N				N	
119	7270	1	2	217	Administrative Office	Health Service Office	W4	Flaking paint at baseboards and window casing.	12	N				N	
120	7270	1	2	215	Health Service Room	Nurse's Office across from Room 201	W1	Flaking paint near entrance.	2	N				N	
121	7270	1	2	215	Health Service Room	Nurse's Office across from Room 201	W3	Flaking paint below and at sides of windows	10	Y	Floor, Sill	1		N	
122	7270	1	2	216	Student Restrooms - Male/Female	Nurse's Office Restroom	W3	Flaking paint below and to the sides of windows	3	Y				N	
123	7270	1	2	215	Health Service Room	Nurse's Office across from Room 201	W2	Flaking paint below windows	3	Y				N	
124	7270	1	2	211	Administrative Office	Room 210A Office	W3	Flaking paint around windows with debris.	60	Y	Sill, Floor	5		N	
125	7270	1	2	212	Administrative Office	Room 212 across from Room 207	Ceiling	Flaking paint, efflorescence at ceiling.	20	Y				N	
126	7270	1	2	212	Administrative Office	Room 212 across from Room 207	W2	Flaking paint above and around windows with debris.	30	Y	Sill, Floor	5		N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
127	7270	1	1	113	Auditorium	Auditorium	Ceiling	Flaking paint at ceiling.	400	Y				N	
128	7270	1	1	113	Auditorium	Auditorium	W2	Flaking paint along walls, above windows, near exit door.	600	Y	Sills	10		Y	
129	7270	1	1	113	Auditorium	Auditorium	W4	Flaking paint along walls, above windows, near exit door.	600	Y	Sills	10		Y	
130	7270	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	Ceiling	Flaking paint at ceiling.	30	N				N	
131	7270	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	W3	Flaking paint around windows and the radiator itself.	40	Y				Y	
132	7270	1	1	107B	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	W4	Flaking paint at wall.	50	N				Y	
133	7270	1	1	101	Primary	Classroom 101	Ceiling	Flaking paint near windows	20	Y				N	
134	7270	1	1	101	Primary	Classroom 101	W1	Flaking paint below blackboard and above closet door.	100	Y	Floor and Window Sill	5		Y	
135	7270	1	1	101	Primary	Classroom 101	W2	Flaking paint near entrance.	2	N				N	
136	7270	1	1	101	Primary	Classroom 101	W3	Flaking paint and efflorescence all around windows	100	Y	Floor and Window Sill	10		Y	
137	7270	1	1	101	Primary	Classroom 101	W4	Flaking paint near entrance.	10	N				N	
138	7270	1	1	101A	Storage	Classroom 101 Closet	W4	Flaking paint at unattached coat rack.	2	N	Floor	1		N	Coat rack should be reattached.
139	7270	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	Ceiling	Flaking paint	100	Y				N	
140	7270	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W1	Flaking paint	30	N				N	
141	7270	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W2	Flaking paint	30	Y	Floor	2		N	
142	7270	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W3	Flaking paint	30	N				N	
143	7270	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W4	Flaking paint	30	N				N	
144	7270	1	1	102	Primary	Classroom 102	Ceiling	Flaking paint at windows.	15	Y				N	
145	7270	1	1	102	Primary	Classroom 102	W1	Flaking paint above blackboard	2	N				N	
146	7270	1	1	102	Primary	Classroom 102	W2	Flaking paint near entrance.	2	N				N	
147	7270	1	1	102	Primary	Classroom 102	W3	Flaking paint all around windows.	50	Y	Floor, Sill	5	Posters, Bookshelves, Supplies	Y	
148	7270	1	1	102	Primary	Classroom 102	W4	Flaking paint near entrance and above blackboard	15	N				N	
149	7270	1	1	102A	Storage	Classroom 102 Closet	W4	Flaking paint by coat hanger	5	N				N	
150	7270	1	1	103	Primary	Classroom 103	Ceiling	Flaking paint at windows.	30	Y	Sill	5		N	
151	7270	1	1	104	Primary	Classroom 104	Ceiling	Flaking paint at arch near entrance and windows	30	N					
152	7270	1	1	104	Primary	Classroom 104	W1	Flaking paint above blackboard	2	N					Posters
153	7270	1	1	104	Primary	Classroom 104	W2	Flaking paint near entrance	2	N					
154	7270	1	1	104	Primary	Classroom 104	W3	Flaking paint all around windows	100	Y			Posters, Bookshelves, Cabinets		

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
155	7270	1	1	104	Primary	Classroom 104	W4	Flaking paint above blackboard and near entrance	50	N					
156	7270	1	1	105	Primary	Classroom 105	Ceiling	Flaking paint at windows	15	Y				N	
157	7270	1	1	105	Primary	Classroom 105	W2	Flaking paint near entrance	20	N				N	
158	7270	1	1	105	Primary	Classroom 105	W3	Flaking paint around and below windows	50	Y	Sill, Floor	2	Posters, Bookshelves	N	
159	7270	1	1	106	Primary	Classroom 106	Ceiling	Flaking paint at windows	10	Y				N	
160	7270	1	1	106	Primary	Classroom 106	W3	Flaking paint below window 1 and debris at window 5	15	Y	Sill, Floor	5		N	
161	7270	1	1	107	Primary	Classroom 107	Ceiling	Flaking paint near entrance and at windows	30	Y				N	
162	7270	1	1	107	Primary	Classroom 107	W2	Flaking paint near entrance	2	N				N	
163	7270	1	1	107	Primary	Classroom 107	W3	Flaking paint below and around windows	50	Y			Posters, Bookshelves, Desks		
164	7270	1	1	108	Primary	Classroom 108	Ceiling	Flaking paint at ceiling at window 3 - areas that were missed.	2	Y				N	
165	7270	1	1	108A	Storage	Classroom 108 Closet	W2	Paint debris on windows sill and floor.	2	Y	Sill, Floor	2		N	
166	7270	1	1	109	Primary	Classroom 109	Ceiling	Flaking paint at windows.	10	Y				N	
167	7270	1	1	109	Primary	Classroom 109	W1	Flaking paint below blackboard	1	N				N	
168	7270	1	1	109	Primary	Classroom 109	W2	Flaking paint near entrance.	1	N				N	
169	7270	1	1	109	Primary	Classroom 109	W3	Flaking paint around window 5.	5	Y				N	
170	7270	1	1	109	Primary	Classroom 109	W4	Cracking paint near entrance.	5	N				N	
171	7270	1	1	110	Primary	Classroom 110	Ceiling	Flaking paint at windows.	15	Y				N	
172	7270	1	1	110	Primary	Classroom 110	W3	Paint debris on window sills, floor, and desk from painting activities.	5	Y	Sill, Desk, Floor	5		N	
173	7270	1	1	110	Primary	Classroom 110	W4	Gouged paint near entrance.	1	N				N	
174	7270	1	1	110A	Storage	Classroom 110 Closet	W4	Paint debris left on sill from painting activities.	5	Y	Sill	5		N	
175	7270	1	1	S10*	Stairs	Fire Tower	Ceiling	Flaking paint at ceiling	1000	Y				N	Space not listed on AHERA log
176	7270	1	1	S10*	Stairs	Fire Tower	Floor	Flaking paint at floor perimeter.	300	Y				N	Space not listed on AHERA log
177	7270	1	1	S10*	Stairs	Fire Tower	W1	Flaking paint at walls.	100	N				N	Space not listed on AHERA log
178	7270	1	1	S10*	Stairs	Fire Tower	W2	Flaking paint at walls.	50	N				N	Space not listed on AHERA log
179	7270	1	1	S10*	Stairs	Fire Tower	W3	Flaking paint at walls.	300	Y	Floor	100		N	Space not listed on AHERA log
180	7270	1	1	S10*	Stairs	Fire Tower	W4	Flaking paint at walls.	200	Y				N	Space not listed on AHERA log
181	7270	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	Ceiling	Flaking paint at ceiling near entrance.	50	N				N	
182	7270	1	1	103B	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	W2	Flaking paint at wall and pipe.	30	N				N	
183	7270	1	1	H11	Circulation (Hallway)	Hallway at Rooms 101 to 103	Floor	Chipped paint at floors.	200	N				N	
184	7270	1	1	H12	Circulation (Hallway)	Hallway at Rooms 104 to 107	Ceiling	Cracked paint on ceiling across from Boys Room	20	N				N	
185	7270	1	1	H12	Circulation (Hallway)	Hallway at Rooms 104 to 107	Floor	Chipped paint at floors.	400	N				N	
186	7270	1	1	H13	Circulation (Hallway)	Hallway at Rooms 108 to 110	Floor	Chipped paint at floors.	200	N				N	
187	7270	1	1	H13	Circulation (Hallway)	Hallway at Rooms 108 to 110	W2	Cracked paint in closet across from Room 108	4	N				N	
188	7270	1	1	115	Storage	Left side Storage off of Stage	Ceiling	Flaking paint at ceiling.	100	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
189	7270	1	1	115	Storage	Left side Storage off of Stage	W2	Flaking paint at walls. Debris on floor.	150	Y	Floor, stored materials	20	Many stored materials, sports equipment.		
190	7270	1	1	115	Storage	Left side Storage off of Stage	W4	Flaking paint at walls and duct. Debris on Floor.	150	N	Floor, stored materials	20	Many stored materials, sports equipment.	N	
191	7270	1	1	1	Primary	Modular Classroom	Ceiling	Flaking paint at ceilings	40	N				N	Roof has been replaced
192	7270	1	1	1	Primary	Modular Classroom	W3	Flaking paint at window sills and unit ventilator	20	N				N	Roof has been replaced
193	7270	1	1	001A	Student Restrooms - Male/Female (Classroom)	Modular Classroom Restroom	Ceiling	Flaking paint at ceiling	10	N				N	
194	7270	1	1	117	Administrative Office	Principal's Office	Ceiling	Flaking paint at Window 3	4	Y	N			N	
195	7270	1	1	114	Storage	Right side Storage off of Stage	Ceiling	Flaking paint at ceiling	400	N				N	
196	7270	1	1	114	Storage	Right side Storage off of Stage	W1	Flaking paint around door.	20	N				N	
197	7270	1	1	114	Storage	Right side Storage off of Stage	W2	Flaking paint at wall and duct.	50	N	Floor	10	Stored materials, boxes, instruments.	N	
198	7270	1	1	114	Storage	Right side Storage off of Stage	W3	Flaking paint around window, debris on sill.	40	N	Sill, Floor	10	Stored materials, boxes, instruments.	Y	
199	7270	1	1	114	Storage	Right side Storage off of Stage	W4	Flaking paint at walls, debris on floor and stored materials.	100	N	Sill, Floor, on Stored materials	10	Stored materials, boxes, instruments.	N	
200	7270	1	1	111	Administrative Office	Room 111 Office	W3	Paint debris left on sill from painting activities.	5	Y	Sill	5		N	
201	7270	1	1	118	Restrooms, Staff - Male/Female	Staff Restroom near Room 101	W3	Flaking paint debris on window sill.	2	Y	Sill	2		N	
202	7270	1	1	113A	Stage	Stage	W2	Flaking paint at walls.	200	N	Floor	10		N	
203	7270	1	1	113A	Stage	Stage	W3	Flaking paint at walls.	200	N	Floor	20		N	
204	7270	1	1	113A	Stage	Stage	W4	Flaking paint at walls.	200	N	Floor	10		N	
205	7270	1	1	S09*	Stairs	Stairwell at Room 101 to Basement	Ceiling	Flaking paint at ceiling	50	N				N	Space not listed on AHERA log
206	7270	1	1	S09*	Stairs	Stairwell at Room 101 to Basement	W1	Flaking paint at walls.	10	N				N	Space not listed on AHERA log
207	7270	1	1	S09*	Stairs	Stairwell at Room 101 to Basement	W2	Flaking paint at walls.	15	N				N	Space not listed on AHERA log
208	7270	1	1	S09*	Stairs	Stairwell at Room 101 to Basement	W3	Flaking paint at walls.	20	Y	Floor	10		N	Space not listed on AHERA log
209	7270	1	1	S09*	Stairs	Stairwell at Room 101 to Basement	W4	Flaking paint at walls.	15	N				N	Space not listed on AHERA log
210	7270	1	1	S6	Stairs	Stairwell at Room 103	Floor	Flaking paint debris at floors and sills on landing between 2nd and 3rd Floors.	10	N	Floor, Sill, Radiator cover.	10		N	
211	7270	1	1	S6	Stairs	Stairwell at Room 103	W1	Chipped paint at newel posts.	10	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
212	7270	1	1	S6	Stairs	Stairwell at Room 103	W3	Flaking paint at 1st floor door and neighboring blue wall. Chipped paint at 2nd and 3rd floor doors.	20	N				N	
213	7270	1	1	S7	Stairs	Stairwell at Room 108	Floor	Flaking paint debris at floors and sills on landing between 2nd and 3rd Floors.	10	N	Floor, Sill, Radiator cover.	10		N	
214	7270	1	1	S7	Stairs	Stairwell at Room 108	W1	Chipped paint at newel posts.	10	N				N	
215	7270	1	1	S8	Stairs	Stairwell to Basement at Room 110	Ceiling	Flaking paint on ceiling.	100	N				N	
216	7270	1	1	S8	Stairs	Stairwell to Basement at Room 110	W2	Flaking paint at wall and pipe.	20	N				N	
217	7270	1	1	S8	Stairs	Stairwell to Basement at Room 110	W3	Flaking paint at wall.	30	N				N	
218	7270	1	1	S8	Stairs	Stairwell to Basement at Room 110	W4	Flaking paint at wall.	10	N				N	
219	7270	1	0	7	Primary	Art Room	Floor	Chipped paint at floor near wall 3.	300	N				N	
220	7270	1	0	7	Primary	Art Room	W1	Flaking paint debris in small closet to left upon first entering Art Room.	5	N	Cart, Supplies	5		N	
221	7270	1	0	7	Primary	Art Room	W4	Flaking paint debris on sill and floor.	5	Y	Sill, Floor	5		N	
222	7270	1	0	007A	Storage	Art Room Storage	W1	Flaking paint at wall.	4	N				N	
223	7270	1	0	007A	Storage	Art Room Storage	W2	Flaking paint near ACPI	1	N				Y	
224	7270	1	0	007B	Storage	Art Room Storage connecting Security Office	W1	Flaking paint at walls	2	N				N	
225	7270	1	0	8	Student Restrooms - Male (4-12)	Boy's Restroom by Stairwell	Ceiling	Flaking paint at ceiling and on pipes	250	N				N	
226	7270	1	0	6	Cafeteria	Cafeteria/Gym	Ceiling	Flaking paint at ceilings at concrete beams and pipe penetrations.	500	Y	Y	100			Paint debris located at boy's side of cafeteria near stored ladders and equipment.
227	7270	1	0	2	Primary	Classroom 002 next to Girl's Restroom	Ceiling	Flaking paint at ceiling where ceiling tiles are missing, at pipe penetrations and near window 2.	30	Y				Y	
228	7270	1	0	2	Primary	Classroom 002 next to Girl's Restroom	W3	Flaking paint behind pipe at window 2 and debris.	5	Y	Sill, Floor	2		N	
229	7270	1	0	1	Student Restrooms - Female (4-12)	Girl's Restroom by Stairwell	Ceiling	Flaking paint near entrance.	15	N				N	
230	7270	1	0	006B	Storage	Gym Storage	Ceiling	No Access							
231	7270	1	0	006B	Storage	Gym Storage	Floor	No Access							
232	7270	1	0	006B	Storage	Gym Storage	W1	No Access							
233	7270	1	0	006B	Storage	Gym Storage	W2	No Access							
234	7270	1	0	006B	Storage	Gym Storage	W3	No Access							
235	7270	1	0	006B	Storage	Gym Storage	W4	No Access							
236	7270	1	0	006C	Storage	Gym Storage under stairwell	W3	Flaking paint at wall	10	Y	Stored materials	5		N	
237	7270	1	0	H03	Circulation (Hallway)	Hallway at Boy's Restroom	Ceiling	Flaking paint at ceiling across from Security	100	N				N	
238	7270	1	0	H03	Circulation (Hallway)	Hallway at Boy's Restroom	W4	Flaking paint at pipe by boys restroom	5	N				N	
239	7270	1	0	H01	Circulation (Hallway)	Hallway at Girl's Restroom	Ceiling	Flaking paint at ceiling, ductwork, and pipes	300	N				N	
240	7270	1	0	H02	Circulation (Hallway)	Hallway at Kitchen	Ceiling	Flaking paint at ceiling, duct, and pipes	400	N				N	
241	7270	1	0	4	Kitchen	Kitchen	W3	Flaking paint at wall above closet door and on pipe	30	N				N	

