

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	8250	1	3	314	Teacher Lounge/Dining	Administrative Office	W3	Flaking	1	N	Y - On Trim	3	N	N	
2	8250	1	3	314	Teacher Lounge/Dining	Administrative Office	W4	Flaking	40	Y	Y - On Baseboard	6	N	Y - 4 SF	Additional Efflorescence, Cracking
3	8250	1	3	315A	Administrative Office	Administrative Office (Room 313)	W3	Chipping	2	N	N	0	Y - 64 SF Bookcases, File Cabinets	N	
4	8250	1	3	315A	Administrative Office	Administrative Office (Room 313)	W4	Chipping	4	N	N	0	Y - 18 SF Contents	N	
5	8250	1	3	315A	Administrative Office	Administrative Office (Room 313)	W2	Cracking	2	N	N	0	Y - 16 SF Contents	N	
6	8250	1	3	315A	Administrative Office	Administrative Office (Room 313)	W1	Flaking	8	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Spalling
7	8250	1	3	315	Student Restrooms - Male (4-12)	Boys' Restroom	W1	Cracking	2	N	N	0	N	N	
8	8250	1	3	315	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking	20	N	N	0	N	N	2 Locations; Additional Cracking
9	8250	1	3	315	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	24	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
10	8250	1	3	315	Student Restrooms - Male (4-12)	Boys' Restroom	W4	Flaking	30	N	N	0	N	N	Additional Cracking
11	8250	1	3	315	Student Restrooms - Male (4-12)	Boys' Restroom	Ceiling	Flaking	48	N	N	0	N	N	
12	8250	1	3	301	Primary	Classroom 301	Ceiling	Efflorescence	16	Y	N	0	N	Y - 16 SF	Suspended Ceiling
13	8250	1	3	301	Primary	Classroom 301	W1	Flaking	16	N	N	0	Y - 48 SF Posters	N	Additional Cracking, Chipping
14	8250	1	3	301	Primary	Classroom 301	W2	Flaking	4	N	N	0	Y - 30 SF Desks	N	Additional Cracking, Chipping, Holes
15	8250	1	3	301	Primary	Classroom 301	W3	Flaking	54	Y	Y - On Window Sills, 1,5	3	N	Y - 1 SF	Additional Efflorescence
16	8250	1	3	301	Primary	Classroom 301	W4	Flaking	34	Y	N	0	Y - 12 SF Desks	Y - 2 SF	4 Locations; Additional Efflorescence
17	8250	1	3	301A	Storage	Classroom 301 Coat Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
18	8250	1	3	301A	Storage	Classroom 301 Coat Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
19	8250	1	3	301A	Storage	Classroom 301 Coat Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
20	8250	1	3	301A	Storage	Classroom 301 Coat Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
21	8250	1	3	301A	Storage	Classroom 301 Coat Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
22	8250	1	3	301A	Storage	Classroom 301 Coat Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
23	8250	1	3	302	Primary	Classroom 302	W1	Cracking	4	N	N	0	N	N	
24	8250	1	3	302	Primary	Classroom 302	W2	Flaking	1	N	N	0	Y - 38 SF Bookcases, Desks	N	
25	8250	1	3	302	Primary	Classroom 302	W3	Flaking	20	N	N	0	Y - 24 SF Bookcases, Desks	N	2 Locations
26	8250	1	3	302	Primary	Classroom 302	W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Posters	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
27	8250	1	3	302A	Storage	Classroom 302 Coat Closet	W4	Holes	3	N	N	0	N	N	
28	8250	1	3	303	Primary	Classroom 303	W4	Cracking	8	N	N	0	Y - 48 SF Bookcases, Smartboard	N	2 Locations; Additional Chipping
29	8250	1	3	303	Primary	Classroom 303	W1	Flaking	42	N	N	0	Y - 16 SF Desks	N	3 Locations; Additional Chipping; Damage on Wall & Forced Air Duct
30	8250	1	3	303	Primary	Classroom 303	W2	Flaking	48	N	N	0	N	N	
31	8250	1	3	303	Primary	Classroom 303	W3	Flaking	60	N	Y - On Window Sill 1	1	Y - 60 SF Bookcases, Desks	N	
32	8250	1	3	303A	Storage	Classroom 303 Coat Closet	W3	Chipping	2	N	N	0	N	N	
33	8250	1	3	303A	Storage	Classroom 303 Coat Closet	W4	Flaking	6	N	N	0	N	N	
34	8250	1	3	303A	Storage	Classroom 303 Coat Closet	W1	Partially Inaccessible	0	N	N	0	20 SF Contents	N	
35	8250	1	3	304	Primary	Classroom 304	W1	Flaking	6	N	N	0	Y - 96 SF Desks	Y - 2 SF	3 Locations; Additional Holes
36	8250	1	3	304	Primary	Classroom 304	W3	Flaking	52	N	Y - On Window Sill 5	3	N	N	2 Locations; Flaking on Wall & Pipe
37	8250	1	3	304	Primary	Classroom 304	W4	Flaking	75	N	N	0	N	N	
38	8250	1	3	304B	Storage	Classroom 304 Coat Closet	W3	Cracking	8	N	N	0	N	N	
39	8250	1	3	304B	Storage	Classroom 304 Coat Closet	W2	Flaking	2	N	N	0	Y - 20 SF Boxes	Y - 1 SF	2 Locations
40	8250	1	3	305	Primary	Classroom 305	W3	Flaking	56	N	Y - On Window Sill 1	1	N	N	
41	8250	1	3	306	Primary	Classroom 306	W1	Flaking	1	N	N	0	Y - 28 SF Desks, Posters	Y - 1 SF	Additional Holes
42	8250	1	3	306	Primary	Classroom 306	W3	Flaking	56	N	N	0	N	N	
43	8250	1	3	306A	Storage	Classroom 306 Coat Closet	W1	Cracking	2	N	N	0	N	N	
44	8250	1	3	306A	Storage	Classroom 306 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Cabinets	N	
45	8250	1	3	306A	Storage	Classroom 306 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 64 SF Bookcases	N	
46	8250	1	3	307	Primary	Classroom 307	Floor	Chipping	120	N	N	0	N	N	Chipping @ Perimeter Baseboards
47	8250	1	3	307	Primary	Classroom 307	W1	Flaking	8	N	N	0	Y - 20 SF Bookcases, Contents	N	2 Locations; Additional Chipping
48	8250	1	3	307	Primary	Classroom 307	W3	Flaking	10	N	N	0	N	N	2 Locations; Additional Chipping
49	8250	1	3	307	Primary	Classroom 307	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Posters	N	
50	8250	1	3	307A	Storage	Classroom 307 Coat Closet	W1	Cracking	1	N	N	0	N	N	
51	8250	1	3	307A	Storage	Classroom 307 Coat Closet	W2	Flaking	6	N	N	0	N	Y - 1 SF	2 Locations; Additional Holes
52	8250	1	3	307A	Storage	Classroom 307 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases, Contents	N	
53	8250	1	3	307B	Storage	Classroom 307 Storage Closet	W1	Holes	1	N	N	0	N	N	
54	8250	1	3	307B	Storage	Classroom 307 Storage Closet	Ceiling	Holes	1	N	N	0	N	Y - 1 SF	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
55	8250	1	3	307B	Storage	Classroom 307 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves, Contents	N	
56	8250	1	3	308	Primary	Classroom 308	W1	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
57	8250	1	3	308	Primary	Classroom 308	W2	Flaking	8	N	N	0	N	N	Additional Cracking
58	8250	1	3	308	Primary	Classroom 308	W3	Flaking	110	Y	Y - On Window Sills	16	N	Y - 8 SF	Additional Efflorescence
59	8250	1	3	308	Primary	Classroom 308	W4	Flaking	72	N	N	0	Y - 28 SF Bookcases, Desks	N	Additional Cracking, Chipping
60	8250	1	3	308	Primary	Classroom 308	Ceiling	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Efflorescence; Water Stain on Ceiling Tiles
61	8250	1	3	308A	Storage	Classroom 308 Coat Closet	W3	Cracking	4	N	N	0	Y - 16 SF Shelves	N	
62	8250	1	3	308A	Storage	Classroom 308 Coat Closet	W1	Flaking	14	Y	N	0	Y - 48 SF Contents	Y - 10 SF	2 Locations; Additional Efflorescence
63	8250	1	3	308A	Storage	Classroom 308 Coat Closet	W2	Flaking	20	N	N	0	N	N	
64	8250	1	3	308A	Storage	Classroom 308 Coat Closet	Ceiling	Flaking	2	Y	N	0	N	Y - 2 SF	Additional Efflorescence
65	8250	1	3	309	Primary	Classroom 309	W4	Chipping	3	N	N	0	Y - 48 SF Bookcases, Desks	N	
66	8250	1	3	309	Primary	Classroom 309	W1	Cracking	10	N	N	0	Y - 24 SF Desks	N	2 Locations; Additional Chipping
67	8250	1	3	309	Primary	Classroom 309	W2	Flaking	14	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
68	8250	1	3	309	Primary	Classroom 309	W3	Flaking	40	N	Y - On Window Sills 2,4	4	N	N	
69	8250	1	3	309	Primary	Classroom 309	Ceiling	Flaking	12	Y	N	0	N	Y - 12 SF	Additional Cracking; Suspended Ceiling; Missing Ceiling Tile @ Water Damage
70	8250	1	3	309A	Storage	Classroom 309 Coat Closet	W2	Chipping	4	N	N	0	N	N	
71	8250	1	3	309A	Storage	Classroom 309 Coat Closet	W4	Chipping	2	N	N	0	N	N	
72	8250	1	3	309A	Storage	Classroom 309 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 8 SF Cabinets	N	
73	8250	1	3	310	Primary	Classroom 310	W1	Cracking	60	N	N	0	N	N	Additional Chipping
74	8250	1	3	310	Primary	Classroom 310	W4	Cracking	20	N	N	0	Y - 30 SF Desks, Contents	N	Additional Chipping
75	8250	1	3	310	Primary	Classroom 310	W3	Flaking	48	N	Y - On Window Sills 1,4	8	N	N	3 Locations; Flaking on Wall & Behind Radiators
76	8250	1	3	310A	Storage	Classroom 310 Coat Closet	W2	Flaking	4	N	N	20	N	N	Additional Chipping
77	8250	1	3	310A	Storage	Classroom 310 Coat Closet	W3	Flaking	20	N	Y - On Coat Rack	0	N	Y - 20 SF	Additional Cracking, Holes
78	8250	1	3	310A	Storage	Classroom 310 Coat Closet	W4	Flaking	92	Y	Y - On Window Sill	8	N	Y - 92 SF	Additional Efflorescence; Damage on Entire Wall
79	8250	1	3	310A	Storage	Classroom 310 Coat Closet	Ceiling	Flaking	4	Y	N	0	N	Y - 4 SF	Additional Efflorescence
80	8250	1	3	310A	Storage	Classroom 310 Coat Closet	W1	Partially Inaccessible	0	N	N	0	Y - 28 SF Cabinets	N	
81	8250	1	3	310B	Storage	Classroom 310 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Contents	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
82	8250	1	3	310B	Storage	Classroom 310 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	
83	8250	1	3	310B	Storage	Classroom 310 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Contents	N	
84	8250	1	3	311	Primary	Classroom 311	W1	Flaking	6	N	N	0	N	N	Additional Chipping, Holes
85	8250	1	3	311	Primary	Classroom 311	W2	Flaking	48	N	Y - On Window Sill	8	N	N	
86	8250	1	3	311	Primary	Classroom 311	W3	Flaking	96	Y	Y - On Window Sill	8	N	Y - 20 SF	Additional Efflorescence, Cracking
87	8250	1	3	311	Primary	Classroom 311	W4	Flaking	13	Y	N	0	N	Y - 8 SF	Additional Efflorescence
88	8250	1	3	315B	Storage	Custodial Closet Adjacent to Boys' Restroom	W4	Cracking	2	N	N	0	N	N	
89	8250	1	3	315B	Storage	Custodial Closet Adjacent to Boys' Restroom	Ceiling	Cracking	3	N	N	0	N	N	
90	8250	1	3	315B	Storage	Custodial Closet Adjacent to Boys' Restroom	W3	Partially Inaccessible	0	N	Y - On Shelves	2	Y - 24 SF Shelves, Contents	N	
91	8250	1	3	304C	Storage	Custodial Closet Adjacent to Girls' Restroom	W4	Cracking	2	N	N	0	N	N	
92	8250	1	3	304C	Storage	Custodial Closet Adjacent to Girls' Restroom	W3	Partially Inaccessible	0	N	N	0	Y - 18 SF Shelves, Contents	N	
93	8250	1	3	304A	Student Restrooms - Female (4-12)	Girls' Restroom	W2	Flaking	8	N	N	0	N	N	4 Locations; Additional Cracking
94	8250	1	3	304A	Student Restrooms - Female (4-12)	Girls' Restroom	W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
95	8250	1	3	304A	Student Restrooms - Female (4-12)	Girls' Restroom	W4	Flaking	12	N	N	0	N	N	Additional Chipping
96	8250	1	3	304A	Student Restrooms - Female (4-12)	Girls' Restroom	Ceiling	Flaking	24	Y	N	0	N	Y - 24 SF	Additional Efflorescence
97	8250	1	3	H311-3	Circulation (Hallway)	Hallway from Classroom 301-303	W2	Flaking	8	N	N	0	N	N	Additional Cracking
98	8250	1	3	H311-3	Circulation (Hallway)	Hallway from Classroom 301-303	W3	Flaking	24	N	N	0	N	N	
99	8250	1	3	H311-3	Circulation (Hallway)	Hallway from Classroom 301-303	W4	Flaking	8	N	N	0	Y - 48 SF File Cabinets	N	2 Locations; Additional Cracking, Chipping
100	8250	1	3	H312-3	Circulation (Hallway)	Hallway from Classrooms 304-307	W1	Flaking	68	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
101	8250	1	3	H312-3	Circulation (Hallway)	Hallway from Classrooms 304-307	W3	Flaking	92	Y	N	0	N	N	6 Locations; Additional Spalling, Cracking, Chipping
102	8250	1	3	H310-3	Circulation (Hallway)	Hallway from Classrooms 308-310	W2	Flaking	20	N	N	0	N	N	Additional Cracking
103	8250	1	3	H310-3	Circulation (Hallway)	Hallway from Classrooms 308-310	W3	Flaking	32	N	N	0	N	N	2 Locations; Additional Cracking
104	8250	1	3	H310-3	Circulation (Hallway)	Hallway from Classrooms 308-310	W4	Flaking	108	N	N	0	N	N	Additional Chipping
105	8250	1	3	313	Restrooms, Staff - Male/Female	Staff Restroom outside Room 301	W2	Flaking	4	N	N	0	N	N	Additional Cracking
106	8250	1	3	313	Restrooms, Staff - Male/Female	Staff Restroom outside Room 301	W3	Flaking	60	Y	N	0	N	Y - 8 SF	3 Locations; Additional Efflorescence, Spalling, Cracking, Chipping

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
137	8250	1	2	218	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking	25	N	N	0	N	N	2 Locations; Additional Cracking
138	8250	1	2	218	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	9	N	N	0	N	N	Additional Cracking
139	8250	1	2	218	Student Restrooms - Male (4-12)	Boys' Restroom	W4	Flaking	52	N	N	0	N	N	2 Locations; Additional Chipping
140	8250	1	2	218	Student Restrooms - Male (4-12)	Boys' Restroom	Ceiling	Flaking	3	Y	N	0	N	N	Suspended Ceiling; Water Stain on Ceiling Tiles
141	8250	1	2	201	Primary	Classroom 201	W1	Flaking	42	N	N	0	N	N	Additional Cracking
142	8250	1	2	201	Primary	Classroom 201	W2	Flaking	4	N	N	0	Y - 48 SF Desks, Posters	N	2 Locations
143	8250	1	2	201	Primary	Classroom 201	W3	Flaking	42	N	N	0	Y - 18 SF Bookcases	N	Additional Cracking
144	8250	1	2	201	Primary	Classroom 201	W4	Flaking	144	N	N	0	Y - 48 SF Desks, Posters, Contents	N	N
145	8250	1	2	201A	Storage	Classroom 201 Coat Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
146	8250	1	2	201A	Storage	Classroom 201 Coat Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
147	8250	1	2	201A	Storage	Classroom 201 Coat Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
148	8250	1	2	201A	Storage	Classroom 201 Coat Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
149	8250	1	2	201A	Storage	Classroom 201 Coat Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
150	8250	1	2	201A	Storage	Classroom 201 Coat Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
151	8250	1	2	201B	Storage	Classroom 201 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 16 SF Shelves, Contents	N	
152	8250	1	2	201B	Storage	Classroom 201 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	
153	8250	1	2	201B	Storage	Classroom 201 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 16 Shelves, Contents	N	
154	8250	1	2	202	Primary	Classroom 202	Floor	Chipping	10	N	Y - Under Window 3	4	N	N	Chipping Around Perimeter
155	8250	1	2	202	Primary	Classroom 202	W1	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
156	8250	1	2	202	Primary	Classroom 202	W3	Flaking	38	N	Y - @ Window Sill 1	3	Y - 52 SF Bookcases, Contents	N	4 Locations
157	8250	1	2	202	Primary	Classroom 202	W4	Flaking	4	N	N	0	N	N	3 Locations; Additional Chipping
158	8250	1	2	202	Primary	Classroom 202	W2	Partially Inaccessible	0	N	N	0	Y - 18 SF Desks	N	
159	8250	1	2	202A	Storage	Classroom 202 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
160	8250	1	2	202A	Storage	Classroom 202 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	
161	8250	1	2	203	Primary	Classroom 203	Floor	Chipping	30	N	N	0	N	N	Chipping @ Perimeter

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
162	8250	1	2	203	Primary	Classroom 203	W1	Flaking	5	N	N	0	Y - 32 SF Desks, Contents	N	Additional Chipping
163	8250	1	2	203	Primary	Classroom 203	W2	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
164	8250	1	2	203	Primary	Classroom 203	W3	Flaking	48	N	Y - @ Window Sill 3	3	Y - 60 SF Bookcases, Desks, Contents	N	
165	8250	1	2	203	Primary	Classroom 203	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, File Cabinets, Tables, Posters	N	
166	8250	1	2	203A	Storage	Classroom 203 Closet	W1	Flaking	6	N	N	0	N	N	
167	8250	1	2	203A	Storage	Classroom 203 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 21 SF Cabinets	N	
168	8250	1	2	203A	Storage	Classroom 203 Closet	W4	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
169	8250	1	2	204	Primary	Classroom 204	W1	Flaking	28	N	N	0	Y - 20 SF Desks	N	3 Locations; Additional Holes
170	8250	1	2	204	Primary	Classroom 204	W3	Flaking	80	N	N	0	Y - 60 SF Desks	N	Additional Cracking
171	8250	1	2	204	Primary	Classroom 204	W4	Flaking	10	N	N	0	N	N	2 Locations
172	8250	1	2	204A	Storage	Classroom 204 Coat Closet	W2	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping, Holes
173	8250	1	2	204A	Storage	Classroom 204 Coat Closet	W3	Flaking	5	N	N	0	N	N	
174	8250	1	2	204A	Storage	Classroom 204 Coat Closet	W4	Flaking	13	N	N	0	N	N	3 Locations
175	8250	1	2	204C	Storage	Classroom 204 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 8 SF Shelves, Contents	N	
176	8250	1	2	204C	Storage	Classroom 204 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Shelves, Contents	N	
177	8250	1	2	204C	Storage	Classroom 204 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Shelves, Contents	N	
178	8250	1	2	205	Primary	Classroom 205	W1	Flaking	16	N	N	0	Y - 48 SF Desks, Bookcases	N	Additional Chipping; Damage Includes Forced Air Duct
179	8250	1	2	205	Primary	Classroom 205	W3	Flaking	16	N	N	0	Y - 20 SF Desks	N	4 Locations; Additional Cracking, Chipping
180	8250	1	2	205A	Storage	Classroom 205 Coat Closet	W2	Flaking	2	N	N	0	Y - 72 SF Contents	N	Additional Chipping
181	8250	1	2	205A	Storage	Classroom 205 Coat Closet	W3	Flaking	6	N	N	0	Y - 20 SF Cabinets, Contents	N	Additional Cracking
182	8250	1	2	205A	Storage	Classroom 205 Coat Closet	W4	Flaking	6	N	N	0	Y - 28 SF Contents	N	3 Locations; Additional Cracking, Chipping, Holes
183	8250	1	2	206	Primary	Classroom 206	W3	Flaking	22	N	N	0	Y - 60 SF Bookcases	N	Additional Cracking
184	8250	1	2	206	Primary	Classroom 206	W1	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks	N	
185	8250	1	2	206A	Storage	Classroom 206 Coat Closet	W2	Flaking	2	N	N	0	Y - 20 SF Cabinets, Boxes	Y - 2 SF	Additional Cracking, Holes

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
186	8250	1	2	206A	Storage	Classroom 206 Coat Closet	W4	Flaking	6	N	N	0	N	Y - 2 SF	3 Locations; Additional Cracking, Holes
187	8250	1	2	207	Primary	Classroom 207	W2	Chipping	6	N	N	0	Y - 24 SF Bookcases, Desks	N	
188	8250	1	2	207	Primary	Classroom 207	W3	Flaking	18	Y	N	0	Y - 60 SF Bookcases, Cabinets	Y - 2 SF	2 Locations; Additional Efflorescence
189	8250	1	2	207A	Storage	Classroom 207 Closet	W2	Partially Inaccessible	0	N	N	0	Y - 8 SF Contents	N	
190	8250	1	2	207A	Storage	Classroom 207 Closet	W3	Partially Inaccessible	0	N	N	0	Y - 42 SF Contents	N	
191	8250	1	2	208	Primary	Classroom 208	W2	Chipping	2	N	N	0	N	N	
192	8250	1	2	208	Primary	Classroom 208	W3	Flaking	84	Y	Y - On Window Sill 2	1	Y - 24 SF Bookcases	Y - 4 SF	4 Locations; Additional Efflorescence, Spalling
193	8250	1	2	208	Primary	Classroom 208	W4	Flaking	44	N	N	0	Y - 48 SF Bookcases	N	Additional Cracking
194	8250	1	2	208A	Storage	Classroom 208 Coat Closet	W2	Chipping	1	N	N	0	N	N	
195	8250	1	2	208A	Storage	Classroom 208 Coat Closet	W3	Flaking	12	N	N	0	N	N	
196	8250	1	2	208B	Storage	Classroom 208 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 8 SF Shelves, Contents	N	
197	8250	1	2	208B	Storage	Classroom 208 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 24 SF Shelves, Contents	N	
198	8250	1	2	208B	Storage	Classroom 208 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 16 SF Shelves, Contents	N	
199	8250	1	2	209	Primary	Classroom 209	W1	Chipping	3	N	N	0	N	N	
200	8250	1	2	209	Primary	Classroom 209	W4	Chipping	4	N	N	0	Y - 36 SF Desks, Posters	N	
201	8250	1	2	209	Primary	Classroom 209	W2	Flaking	3	N	N	0	N	N	3 Locations; Additional Chipping
202	8250	1	2	209	Primary	Classroom 209	W3	Flaking	54	Y	Y - On Window Sills 1,4,5	3	Y - 48 SF Bookcases, Desks	Y - 6 SF	3 Locations; Additional Efflorescence, Holes
203	8250	1	2	209A	Storage	Classroom 209 Coat Closet	W2	Chipping	24	N	N	0	N	N	
204	8250	1	2	209A	Storage	Classroom 209 Coat Closet	W3	Chipping	4	N	N	0	N	N	
205	8250	1	2	209A	Storage	Classroom 209 Coat Closet	W4	Chipping	12	N	N	0	N	N	
206	8250	1	2	209A	Storage	Classroom 209 Coat Closet	Ceiling	Flaking	10	N	N	0	N	Y - 10 SF	Additional Chipping
207	8250	1	2	210	Primary	Classroom 210	W1	Chipping	8	N	N	0	N	N	
208	8250	1	2	210	Primary	Classroom 210	W2	Flaking	24	N	N	0	Y - 12 SF Bookcases	N	2 Locations
209	8250	1	2	210	Primary	Classroom 210	W3	Flaking	4	Y	Y - On Window Sill 3	5	N	Y - 8 SF	Additional Efflorescence
210	8250	1	2	210	Primary	Classroom 210	W4	Flaking	12	N	N	0	Y - 48 SF Desks, Posters	N	2 Locations; Additional Chipping
211	8250	1	2	210A	Storage	Classroom 210 Coat Closet	W1	Flaking	2	N	N	0	N	N	2 Locations; Additional Holes
212	8250	1	2	210A	Storage	Classroom 210 Coat Closet	W3	Flaking	20	N	N	0	N	N	
213	8250	1	2	210A	Storage	Classroom 210 Coat Closet	W4	Flaking	12	N	N	0	N	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
214	8250	1	2	210A	Storage	Classroom 210 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Cabinets	N	
215	8250	1	2	213	Administrative Office	Counselor's Office	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Bookcases, Posters	N	
216	8250	1	2	213	Administrative Office	Counselor's Office	W2	Partially Inaccessible	0	N	N	0	Y - 56 SF Bookcases	N	
217	8250	1	2	213	Administrative Office	Counselor's Office	W3	Partially Inaccessible	0	N	Y - @ Window Sill 2	3	Y - 48 SF File Cabinets, Contents	N	
218	8250	1	2	213	Administrative Office	Counselor's Office	W4	Partially Inaccessible	0	N	N	0	Y - 56 SF Bookcases, File Cabinets, Posters	N	
219	8250	1	2	204B	Student Restrooms - Female (4-12)	Girls' Restroom	W3	Cracking	3	N	N	0	N	N	
220	8250	1	2	204B	Student Restrooms - Female (4-12)	Girls' Restroom	W2	Flaking	4	N	N	0	N	N	
221	8250	1	2	204B	Student Restrooms - Female (4-12)	Girls' Restroom	W4	Flaking	36	N	N	0	N	N	
222	8250	1	2	204B	Student Restrooms - Female (4-12)	Girls' Restroom	Ceiling	Flaking	8	N	N	0	N	N	Suspended Ceiling
223	8250	1	2	H29-2	Circulation (Hallway)	Hallway from Classroom 204-207	W1	Flaking	60	N	N	0	N	N	Additional Cracking, Chipping
224	8250	1	2	H29-2	Circulation (Hallway)	Hallway from Classroom 204-207	W3	Flaking	90	Y	Y - On Window Sills 1,2	6	N	Y - 4 SF	Additional Efflorescence
225	8250	1	2	H28-2	Circulation (Hallway)	Hallway from Classrooms 201-203	W4	Cracking	2	N	N	0	N	N	Additional Chipping
226	8250	1	2	H28-2	Circulation (Hallway)	Hallway from Classrooms 201-203	W2	Flaking	3	N	N	0	N	N	2 Locations; Additional Cracking
227	8250	1	2	H27-2	Circulation (Hallway)	Hallway from Classrooms 208-210	W2	Flaking	19	N	N	0	N	N	5 Locations; Additional Cracking, Chipping
228	8250	1	2	H27-2	Circulation (Hallway)	Hallway from Classrooms 208-210	W3	Flaking	4	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
229	8250	1	2	H27-2	Circulation (Hallway)	Hallway from Classrooms 208-210	W4	Flaking	48	N	N	0	N	N	2 Locations
230	8250	1	2	204D	Storage	Hallway Storage Adjacent to Girls' Restroom	W3	Chipping	2	N	N	0	Y - 14 SF Contents	N	
231	8250	1	2	215	Restrooms, Staff - Male/Female	Men's Restroom	W3	Efflorescence	18	Y	N	0	N	Y - 10 SF	2 Locations; Additional Spalling, Chipping; Damage Includes Radiator & Wall
232	8250	1	2	215	Restrooms, Staff - Male/Female	Men's Restroom	W4	Efflorescence	10	Y	N	0	N	Y - 6 SF	Additional Spalling, Cracking, Chipping
233	8250	1	2	215	Restrooms, Staff - Male/Female	Men's Restroom	W1	Flaking	2	N	N	0	N	N	Additional Cracking
234	8250	1	2	215	Restrooms, Staff - Male/Female	Men's Restroom	W2	Flaking	16	N	N	0	N	N	Additional Cracking
235	8250	1	2	214B	Administrative Office	Nurse's Office	W1	Flaking	2	N	N	0	Y - 12 SF Cabinets, Posters	N	
236	8250	1	2	214B	Administrative Office	Nurse's Office	W2	Flaking	16	N	N	0	Y - 75 SF Cabinets, Chairs, Contents	N	2 Locations; Additional Cracking

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
237	8250	1	2	214B	Administrative Office	Nurse's Office	W3	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking
238	8250	1	2	214B	Administrative Office	Nurse's Office	W4	Flaking	6	Y	Y - On Window Sill	2	N	Y - 2 SF	Additional Efflorescence, Cracking
239	8250	1	2	216A	Student Restrooms - Male/Female	Nurse's Office Restroom	W2	Cracking	24	N	N	0	N	N	Additional Holes
240	8250	1	2	216A	Student Restrooms - Male/Female	Nurse's Office Restroom	W3	Cracking	49	N	N	0	N	N	
241	8250	1	2	216A	Student Restrooms - Male/Female	Nurse's Office Restroom	Ceiling	Efflorescence	1	Y	N	0	N	Y - 1 SF	Additional Cracking; Flaking @ Window Frame
242	8250	1	2	216A	Student Restrooms - Male/Female	Nurse's Office Restroom	W1	Flaking	21	N	N	0	N	N	Additional Cracking
243	8250	1	2	216A	Student Restrooms - Male/Female	Nurse's Office Restroom	W4	Flaking	30	N	N	0	N	N	
244	8250	1	2	S22	Stairs	Stairs	W3	Chipping	2	N	N	0	N	N	Chipping @ Door
245	8250	1	2	S22	Stairs	Stairs	Floor	Chipping	4	N	N	0	N	N	
246	8250	1	2	S22	Stairs	Stairs	Center Banister	Chipping	12	N	N	0	N	N	
247	8250	1	2	S24	Stairs	Stairs	W1	Flaking	20	N	N	0	N	N	Additional Chipping
248	8250	1	2	S24	Stairs	Stairs	W2	Flaking	200	N	N	0	N	N	Additional Chipping
249	8250	1	2	S24	Stairs	Stairs	W3	Flaking	4	N	N	0	N	N	Additional Chipping
250	8250	1	2	S24	Stairs	Stairs	W4	Flaking	64	N	N	0	N	N	Additional Chipping
251	8250	1	2	S24	Stairs	Stairs	Ceiling	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping
252	8250	1	2	S24	Stairs	Stairs	Floor	Flaking	6	N	N	0	N	N	Additional Chipping
253	8250	1	2	S24	Stairs	Stairs	Center Banister	Flaking	14	N	N	0	N	N	Additional Chipping
254	8250	1	2	S22	Stairs	Stairs	W1	Flaking	16	N	N	0	N	N	2 Locations
255	8250	1	2	S22	Stairs	Stairs	W2	Flaking	210	N	N	0	N	N	Flaking on Entire Wall
256	8250	1	2	S22	Stairs	Stairs	W4	Flaking	280	N	N	0	N	N	Flaking on Entire Wall
257	8250	1	2	S22	Stairs	Stairs	Ceiling	Flaking	14	N	N	0	N	N	
258	8250	1	2	S26-2	Stairs	Stairs outside Classroom 203	Center Banister	Chipping	7	N	N	0	N	N	
259	8250	1	2	S26-2	Stairs	Stairs outside Classroom 203	W1	Flaking	8	N	N	0	N	N	
260	8250	1	2	S26-2	Stairs	Stairs outside Classroom 203	W2	Flaking	40	N	N	0	N	N	2 Locations
261	8250	1	2	S26-2	Stairs	Stairs outside Classroom 203	W4	Flaking	20	N	N	0	N	N	2 Locations; Additional Chipping
262	8250	1	2	S26-2	Stairs	Stairs outside Classroom 203	Ceiling	Flaking	12	N	N	0	N	N	4 Locations
263	8250	1	2	211	Storage	Storage outside Classroom 210	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
264	8250	1	2	211	Storage	Storage outside Classroom 210	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
265	8250	1	2	211	Storage	Storage outside Classroom 210	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
266	8250	1	2	211	Storage	Storage outside Classroom 210	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
267	8250	1	2	211	Storage	Storage outside Classroom 210	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
268	8250	1	2	211	Storage	Storage outside Classroom 210	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
269	8250	1	2	214	Primary	Teacher's Lounge	W2	Efflorescence	4	Y	N	0	N	Y - 4 SF	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
270	8250	1	2	214	Primary	Teacher's Lounge	W3	Flaking	32	Y	Y - @ Window Sills 1,2	6	N	Y - 32 SF	Additional Efflorescence
271	8250	1	2	217	Administrative Office	Teacher's Lounge Storage	W2	Flaking	6	N	N	0	N	N	Additional Cracking
272	8250	1	2	217	Administrative Office	Teacher's Lounge Storage	W3	Flaking	1	N	N	0	N	N	
273	8250	1	2	217	Administrative Office	Teacher's Lounge Storage	Ceiling	Flaking	5	N	N	0	N	N	2 Locations; Additional Chipping
274	8250	1	1	113	Auditorium	Auditorium	W2	Cracking	8	N	N	0	N	N	
275	8250	1	1	113	Auditorium	Auditorium	W3	Cracking	6	N	N	0	N	N	
276	8250	1	1	113	Auditorium	Auditorium	W4	Cracking	8	N	N	0	N	N	2 Locations; Additional Chipping
277	8250	1	1	113	Auditorium	Auditorium	Ceiling	Significant Moisture Damage	100	N	N	0	N	N	Ceiling Leaks Above
278	8250	1	1	107B	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	6	N	N	0	N	N	
279	8250	1	1	107B	Student Restrooms - Male (4-12)	Boys' Restroom	W4	Flaking	34	N	N	0	N	N	3 Locations; Additional Cracking
280	8250	2	1	1	Primary	Classroom 001	W1	Cracking	6	N	N	0	Y - 24 SF Contents	N	
281	8250	2	1	1	Primary	Classroom 001	W2	Flaking	8	N	N	0	N	N	Additional Cracking; Damage across from Exit @ Window 3
282	8250	2	1	1	Primary	Classroom 001	W3	Flaking	6	N	N	0	Y - 80 SF Bookcases, Posters, Contents	N	2 Locations; Additional Chipping
283	8250	2	1	1	Primary	Classroom 001	W4	Flaking	16	N	N	0	Y - 40 SF Bookcases, Desks	N	Additional Cracking
284	8250	2	1	001-1	Student Restrooms - Male/Female (Classroom)	Classroom 001 Restroom	W1	Flaking	4	N	N	0	N	N	
285	8250	2	1	001-1	Student Restrooms - Male/Female (Classroom)	Classroom 001 Restroom	W3	Flaking	8	N	N	0	N	N	Additional Cracking
286	8250	2	1	001-2	Storage	Classroom 001 Storage	W2	Partially Inaccessible	0	N	N	0	N	N	
287	8250	2	1	001-2	Storage	Classroom 001 Storage	W3	Partially Inaccessible	0	N	N	0	N	N	
288	8250	2	1	001-2	Storage	Classroom 001 Storage	W4	Partially Inaccessible	0	N	N	0	N	N	
289	8250	1	1	101	Primary	Classroom 101	W2	Cracking	10	N	N	0	N	N	
290	8250	1	1	101	Primary	Classroom 101	W1	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
291	8250	1	1	101	Primary	Classroom 101	W3	Flaking	36	N	N	0	N	N	3 Locations; Additional Cracking
292	8250	1	1	101	Primary	Classroom 101	W4	Flaking	32	N	N	0	N	Y - 2 SF	2 Locations; Additional Spalling
293	8250	1	1	101B	Storage	Classroom 101 Storage	W4	Cracking	2	N	N	0	N	N	
294	8250	1	1	102	Primary	Classroom 102	W4	Cracking	4	N	N	0	N	N	Additional Chipping
295	8250	1	1	102	Primary	Classroom 102	W1	Flaking	7	N	N	0	Y - 12 SF Desks, Posters	N	2 Locations; Additional Cracking, Chipping
296	8250	1	1	102	Primary	Classroom 102	W3	Flaking	5	N	N	0	Y - 56 Bookcases, Desks	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
297	8250	1	1	102	Primary	Classroom 102	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Bookcases, Desks	N	
298	8250	1	1	102A	Storage	Classroom 102 Coat Closet	W3	Cracking	8	N	N	0	N	N	
299	8250	1	1	103	Primary	Classroom 103	W4	Cracking	4	N	N	0	N	N	
300	8250	1	1	103	Primary	Classroom 103	W1	Flaking	16	N	N	0	N	N	Additional Cracking
301	8250	1	1	103	Primary	Classroom 103	W2	Flaking	72	Y	Y - @ Top of Chalkboard Trim	3	N	Y - 6 SF	Additional Efflorescence, Cracking
302	8250	1	1	103	Primary	Classroom 103	W3	Flaking	16	N	Y - @ Window Sills 1,2,4	4	Y - 12 SF Contents	N	3 Locations; Additional Cracking
303	8250	1	1	103A	Storage	Classroom 103 Coat Closet	W2	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping
304	8250	1	1	103A	Storage	Classroom 103 Coat Closet	W4	Flaking	24	N	N	0	N	N	Additional Cracking
305	8250	1	1	103B	Student Restroom	Classroom 103 Restroom	W1	Flaking	80	N	N	0	N	N	
306	8250	1	1	103B	Student Restroom	Classroom 103 Restroom	W3	Flaking	110	N	N	0	N	N	Additional Cracking
307	8250	1	1	103B	Student Restroom	Classroom 103 Restroom	W4	Flaking	60	N	Y - On Radiator	2	N	N	
308	8250	1	1	103B	Student Restroom	Classroom 103 Restroom	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking
309	8250	1	1	104	Primary	Classroom 104	W3	Flaking	44	N	N	0	Y - 72 SF Bookcases, Contents	N	3 Locations; Additional Cracking
310	8250	1	1	104	Primary	Classroom 104	W4	Flaking	10	N	N	0	Y - 48 SF Contents	N	2 Locations; Additional Cracking, Chipping
311	8250	1	1	104B	Storage	Classroom 104 Coat Closet	W2	Cracking	64	N	N	0	N	N	
312	8250	1	1	104B	Storage	Classroom 104 Coat Closet	W3	Cracking	16	N	N	0	N	N	
313	8250	1	1	104B	Storage	Classroom 104 Coat Closet	W4	Cracking	45	N	N	0	Y - 48 SF Contents	N	
314	8250	1	1	104B	Storage	Classroom 104 Coat Closet	Ceiling	Flaking	4	N	N	0	N	N	3 Locations
315	8250	1	1	105	Primary	Classroom 105	W1	Flaking	8	N	N	0	Y - 28 SF Desks	N	Additional Cracking, Chipping
316	8250	1	1	105	Primary	Classroom 105	W3	Flaking	10	N	Y - @ Window Sill 5	2	Y - 60 SF Bookcases	N	2 Locations; Additional Chipping
317	8250	1	1	105A	Storage	Classroom 105 Coat Closet	W2	Cracking	3	N	N	0	N	N	
318	8250	1	1	105A	Storage	Classroom 105 Coat Closet	W4	Cracking	2	N	N	0	N	N	
319	8250	1	1	106	Primary	Classroom 106	W1	Cracking	2	N	N	0	N	Y - 1 SF	Additional Chipping
320	8250	1	1	106	Primary	Classroom 106	W3	Flaking	36	N	N	0	Y - 48 SF Desks, Bookcases	N	3 Locations
321	8250	1	1	106A	Storage	Classroom 106 Coat Closet	W2	Cracking	48	N	N	0	N	N	
322	8250	1	1	106A	Storage	Classroom 106 Coat Closet	W3	Cracking	36	N	N	0	N	N	
323	8250	1	1	106A	Storage	Classroom 106 Coat Closet	W4	Cracking	28	N	N	0	N	N	
324	8250	1	1	107	Primary	Classroom 107	W1	Flaking	4	N	N	0	Y - 18 SF Desks, Posters	N	Additional Cracking, Chipping

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
325	8250	1	1	107	Primary	Classroom 107	W3	Flaking	12	N	N	0	Y - 60 SF Bookcases, File Cabinets, Posters	N	Additional Cracking
326	8250	1	1	107	Primary	Classroom 107	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Cabinets, Bookcases	N	
327	8250	1	1	107A	Storage	Classroom 107 Coat Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
328	8250	1	1	107A	Storage	Classroom 107 Coat Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
329	8250	1	1	107A	Storage	Classroom 107 Coat Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
330	8250	1	1	107A	Storage	Classroom 107 Coat Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
331	8250	1	1	107A	Storage	Classroom 107 Coat Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
332	8250	1	1	107A	Storage	Classroom 107 Coat Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
333	8250	1	1	107B	Storage	Classroom 107 Small Storage Closet	W3	Holes	2	N	N	0	Y - 25 SF Shelves, Contents	Y - 2 SF	
334	8250	1	1	107B	Storage	Classroom 107 Small Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
335	8250	1	1	107B	Storage	Classroom 107 Small Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
336	8250	1	1	108	Primary	Classroom 108	W1	Cracking	8	N	N	0	Y - 48 SF Desks	N	Additional Chipping
337	8250	1	1	108	Primary	Classroom 108	W2	Flaking	32	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence, Chipping
338	8250	1	1	108	Primary	Classroom 108	W3	Flaking	2	N	N	0	Y - 48 SF Desks, Tables, Bookcases	Y - <1 SF	Additional Cracking, Chipping
339	8250	1	1	108	Primary	Classroom 108	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks, Bookcases, File Cabinets	N	
340	8250	1	1	108A	Storage	Classroom 108 Coat Closet	Ceiling	Flaking	3	N	N	0	N	Y - 3 SF	Additional Cracking
341	8250	1	1	108A	Storage	Classroom 108 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
342	8250	1	1	108A	Storage	Classroom 108 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 35 SF Shelves, Contents	N	
343	8250	1	1	108A	Storage	Classroom 108 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 21 SF Shelves, Contents	N	
344	8250	1	1	109	Primary	Classroom 109	W1	Cracking	2	N	N	0	N	N	Additional Chipping
345	8250	1	1	109	Primary	Classroom 109	W4	Cracking	6	N	N	0	N	N	Additional Chipping
346	8250	1	1	109	Primary	Classroom 109	W2	Flaking	2	N	N	0	N	N	
347	8250	1	1	109	Primary	Classroom 109	W3	Flaking	46	Y	N	0	N	Y - 40 SF	3 Locations; Additional Efflorescence
348	8250	1	1	109A	Storage	Classroom 109 Coat Closet	W2	Flaking	4	N	N	0	Y - 28 SF Contents	Y - 4 SF	Additional Chipping, Holes
349	8250	1	1	109A	Storage	Classroom 109 Coat Closet	W4	Flaking	2	N	N	0	Y - 32 SF Contents	N	Additional Chipping

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
350	8250	1	1	109B	Storage	Classroom 109 Storage Closet	W3	Cracking	2	N	N	0	Y - 36 SF Shelves, Contents	N	
351	8250	1	1	109B	Storage	Classroom 109 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	
352	8250	1	1	109B	Storage	Classroom 109 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Shelves, Contents	N	
353	8250	1	1	110	Primary	Classroom 110	W4	Cracking	35	N	N	0	Y - 48 SF Desks	N	Additional Chipping
354	8250	1	1	110	Primary	Classroom 110	W1	Flaking	4	N	N	0	Y - 32 SF Desks	N	Additional Chipping
355	8250	1	1	110	Primary	Classroom 110	W2	Flaking	30	N	N	0	Y - 48 SF Desks, Tables, Bookcases	N	2 Locations; Additional Cracking
356	8250	1	1	110	Primary	Classroom 110	W3	Flaking	45	N	Y - On Radiator & Window Sills 1-3	8	Y - 24 SF Bookcases	N	Additional Cracking, Chipping
357	8250	1	1	110A	Storage	Classroom 110 Coat Closet	W1	Flaking	14	N	N	0	Y - 48 SF Boxes, Contents	N	2 Locations; Additional Cracking
358	8250	1	1	110A	Storage	Classroom 110 Coat Closet	W3	Flaking	2	N	N	0	Y - 36 SF Contents	N	
359	8250	1	1	110A	Storage	Classroom 110 Coat Closet	W4	Flaking	20	N	N	0	N	N	Flaking Includes Radiator & Wall
360	8250	1	1	110A	Storage	Classroom 110 Coat Closet	Ceiling	Flaking	10	N	N	0	N	N	
361	8250	1	1	107C	Storage	Custodial Closet Adjacent to Boys' Restroom	W3	Cracking	4	N	N	0	Y - 14 SF Shelves, Contents	N	
362	8250	1	1	104A	Student Restrooms - Female (4-12)	Girls' Restroom	W2	Cracking	64	N	N	0	N	N	
363	8250	1	1	104A	Student Restrooms - Female (4-12)	Girls' Restroom	W4	Cracking	30	N	N	0	N	N	
364	8250	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101-103	W2	Flaking	24	N	N	0	N	N	3 Locations; Additional Cracking
365	8250	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101-103	W3	Flaking	12	N	N	0	N	N	
366	8250	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101-103	W4	Flaking	46	N	N	0	N	N	Additional Cracking, Chipping
367	8250	1	1	H16	Circulation (Hallway)	Hallway from Classrooms 104-107	W3	Flaking	180	N	Y - @ Radiator 1	8	N	N	Additional Cracking, Chipping
368	8250	1	1	H16	Storage	Hallway from Classrooms 104-107	W1	Flaking	42	N	N	0	N	N	Additional Cracking, Chipping
369	8250	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 108-110	W2	Flaking	90	N	N	0	N	N	Additional Cracking
370	8250	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 108-110	W3	Flaking	18	N	N	0	N	N	
371	8250	1	1	H14	Circulation (Hallway)	Hallway from Classrooms 108-110	W4	Flaking	140	N	N	0	N	N	Additional Cracking, Chipping
372	8250	1	1	H16A	Circulation (Hallway)	Hallway on Right Side of Auditorium	W2	Cracking	6	N	N	0	N	N	2 Locations
373	8250	1	1	H16A	Circulation (Hallway)	Hallway on Right Side of Auditorium	W4	Flaking	14	N	N	0	N	N	3 Locations; Additional Cracking
374	8250	1	1	H16A	Circulation (Hallway)	Hallway on Right Side of Auditorium	Ceiling	Flaking	16	Y	N	0	N	Y - 2 SF	Additional Efflorescence

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
375	8250	1	1	104C	Storage	Hallway Supply Closet Adjacent to 104A	W3	Cracking	2	N	N	0	Y - 14 SF Shelves, Contents	N	
376	8250	1	1	111	Administrative Office	Main Office	W3	Flaking	14	Y	Y - @ Window Sill 1,2	5	Y - 12 SF Desk, File Cabinet	Y - 10 SF	3 Locations; Additional Efflorescence
377	8250	1	1	111	Administrative Office	Main Office	W2	Holes	1	N	Y - @ Trim	1	N	N	
378	8250	1	1	111	Administrative Office	Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF Desk, Copier	N	
379	8250	1	1	111B	Storage	Main Office Storage	W1	Cracking	4	N	Y - On Shelf by Window Sill	1	Y - 92 SF Shelves, Contents	N	
380	8250	1	1	111B	Storage	Main Office Storage	W4	Cracking	20	N	N	0	Y - 10 SF File Cabinets	N	2 Locations
381	8250	1	1	111B	Storage	Main Office Storage	W3	Flaking	6	N	N	0	N	N	
382	8250	1	1	111B	Storage	Main Office Storage	W2	Partially Inaccessible	0	N	Y - On Shelf by Window Sill	1	Y - 16 SF Contents	N	
383	8250	1	1	112	Restrooms, Staff - Male	Men's Restroom	W4	Holes	3	N	N	0	N	Y - 3 SF	
384	8250	1	1	112	Restrooms, Staff - Male	Men's Restroom	Ceiling	Holes	2	N	N	0	N	Y - 2 SF	Suspended Ceiling; Missing Ceiling Tile
385	8250	1	1	111A	Administrative Office	Principal's Office	W3	Flaking	12	N	Y - @ Window Sill	4	N	N	
386	8250	1	1	111A	Administrative Office	Principal's Office	W4	Flaking	28	Y	Y - @ Window Sills 1,2	4	N	N	Additional Efflorescence
387	8250	1	1	111B	Storage	Principal's Office Closet	W1	Cracking	2	N	N	0	N	N	
388	8250	1	1	111B	Storage	Principal's Office Closet	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves, Contents	N	
389	8250	1	1	111B	Storage	Principal's Office Closet	W3	Partially Inaccessible	0	N	N	0	Y - 24 Shelves, Contents	N	
390	8250	1	1	111B	Storage	Principal's Office Closet	W4	Partially Inaccessible	0	N	N	0	Y - 40 Shelves, Contents	N	
391	8250	1	1	Stage	Stage	Stage	Ceiling	Flaking	30	N	N	0	N	N	
392	8250	1	1	S14	Stairs	Stairs	Floor	Chipping	8	N	N	0	N	N	
393	8250	1	1	S19	Stairs	Stairs	Ceiling	Flaking	3	N	N	0	N	N	Additional Cracking
394	8250	1	1	S14	Stairs	Stairs	W1	Flaking	40	N	N	0	N	N	Additional Chipping
395	8250	1	1	S14	Stairs	Stairs	W2	Flaking	18	N	N	0	N	N	
396	8250	1	1	S14	Stairs	Stairs	W3	Flaking	26	N	N	0	N	N	
397	8250	1	1	S14	Stairs	Stairs	W4	Flaking	72	N	N	0	N	N	
398	8250	1	1	S14	Stairs	Stairs	Ceiling	Flaking	20	N	N	0	N	N	Additional Chipping
399	8250	1	1	S14	Stairs	Stairs	Center Banister	Flaking	10	N	N	0	N	N	Additional Chipping
400	8250	1	1	S13	Stairs	Stairs	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
401	8250	1	1	S13	Stairs	Stairs	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
402	8250	1	1	S13	Stairs	Stairs	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
403	8250	1	1	S13	Stairs	Stairs	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
404	8250	1	1	S13	Stairs	Stairs	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
405	8250	1	1	S13	Stairs	Stairs	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
406	8250	1	1	S19	Stairs	Stairs	W2	Cracking	4	N	N	0	N	N	
407	8250	1	1	S19	Stairs	Stairs	W3	Cracking	1	N	N	0	N	N	
408	8250	1	1	S19	Stairs	Stairs	W4	Cracking	2	N	N	0	N	N	
409	8250	1	1	S17	Stairs	Stairs outside Classroom 101	Floor	Chipping	6	N	N	0	N	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
410	8250	1	1	S17	Stairs	Stairs outside Classroom 101	W2	Flaking	24	N	N	0	N	N	Additional Chipping
411	8250	1	1	S17	Stairs	Stairs outside Classroom 101	W3	Flaking	16	N	N	0	N	Y - 1 SF	
412	8250	1	1	S17	Stairs	Stairs outside Classroom 101	W4	Flaking	60	N	N	0	N	N	
413	8250	1	1	S16	Stairs	Stairs outside Classroom 103	Floor	Chipping	6	N	N	0	N	N	
414	8250	1	1	S16	Stairs	Stairs outside Classroom 103	Center Banister	Chipping	10	N	N	0	N	N	
415	8250	1	1	S16	Stairs	Stairs outside Classroom 103	W1	Flaking	36	N	N	0	N	N	Additional Cracking
416	8250	1	1	S16	Stairs	Stairs outside Classroom 103	W2	Flaking	22	N	N	0	N	N	2 Locations; Additional Cracking
417	8250	1	1	S16	Stairs	Stairs outside Classroom 103	W3	Flaking	14	N	N	0	N	N	Additional Cracking
418	8250	1	1	S16	Stairs	Stairs outside Classroom 103	W4	Flaking	1	N	N	0	N	N	
419	8250	1	1	S16	Stairs	Stairs outside Classroom 103	Ceiling	Flaking	8	N	N	0	N	N	2 Locations
420	8250	1	1	S12	Stairs	Stairs outside Classroom 108	Floor	Chipping	12	N	N	0	N	N	
421	8250	1	1	S12	Stairs	Stairs outside Classroom 108	Center Banister	Chipping	8	N	N	0	N	N	
422	8250	1	1	S12	Stairs	Stairs outside Classroom 108	W1	Flaking	45	N	N	0	N	N	
423	8250	1	1	S12	Stairs	Stairs outside Classroom 108	W2	Flaking	42	N	N	0	N	N	Additional Cracking
424	8250	1	1	S12	Stairs	Stairs outside Classroom 108	W3	Flaking	90	N	N	0	N	N	
425	8250	1	1	S12	Stairs	Stairs outside Classroom 108	W4	Flaking	24	N	N	0	N	N	
426	8250	1	1	S12	Stairs	Stairs outside Classroom 108	Ceiling	Flaking	50	N	N	0	N	Y - 50 SF	Additional Cracking
427	8250	1	1	S11	Stairs	Stairs outside Classroom 110	W2	Flaking	75	N	N	0	N	N	Additional Cracking; Damage Includes Metal Pipe
428	8250	1	1	S11	Stairs	Stairs outside Classroom 110	W3	Flaking	18	N	N	0	N	N	
429	8250	1	1	S11	Stairs	Stairs outside Classroom 110	W4	Flaking	48	N	N	0	N	N	
430	8250	1	1	S11	Stairs	Stairs outside Classroom 110	Ceiling	Flaking	20	N	N	0	N	N	
431	8250	1	1	S11	Stairs	Stairs outside Classroom 110	Floor	Flaking	8	N	Y - Perimeter	16	N	N	Additional Chipping on Stairs
432	8250	1	1	101A	Restrooms, Staff - Female	Women's Restroom	W2	Flaking	1	N	N	0	N	Y - 1 SF	
433	8250	1	1	101A	Restrooms, Staff - Female	Women's Restroom	W3	Flaking	2	N	Y - @ Window Sill	1	N	Y - 2 SF	Additional Efflorescence
434	8250	1	0	015C	Administrative Office	Administrative Office	W1	Flaking	40	N	N	0	N	N	
435	8250	1	0	015C	Administrative Office	Administrative Office	W2	Flaking	92	N	N	0	N	N	
436	8250	1	0	015C	Administrative Office	Administrative Office	W3	Flaking	80	N	N	0	N	N	
437	8250	1	0	015C	Administrative Office	Administrative Office	W4	Flaking	60	N	N	0	Y - 18 SF Desks	N	
438	8250	1	0	015C	Administrative Office	Administrative Office	Ceiling	Flaking	300	N	N	0	N	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
439	8250	1	0	012B	Student Restrooms - Male (4-12)	Basement Boys' Restroom	W1	Flaking	16	N	N	0	N	N	
440	8250	1	0	012B	Student Restrooms - Male (4-12)	Basement Boys' Restroom	W2	Flaking	18	N	N	0	N	N	
441	8250	1	0	012B	Student Restrooms - Male (4-12)	Basement Boys' Restroom	W3	Flaking	60	N	Y - @ Window Sill	1	N	N	
442	8250	1	0	012B	Student Restrooms - Male (4-12)	Basement Boys' Restroom	W4	Flaking	12	N	N	0	N	N	
443	8250	1	0	012B	Student Restrooms - Male (4-12)	Basement Boys' Restroom	Ceiling	Flaking	140	N	N	0	N	N	
444	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	W1	Flaking	6	N	N	0	Y - 75 SF Shelves, Books, Contents	N	
445	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	W2	Flaking	16	N	N	0	Y - 18 SF Shelves, Boxes, Contents	N	
446	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	W3	Flaking	26	N	N	0	Y - 160 SF Shelves, Boxes, Contents	N	3 Locations
447	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	Ceiling	Flaking	36	N	N	0	Y - 60 SF Ductwork, Pipes	N	
448	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF File Cabinets	N	
449	8250	1	0	004D	Storage	Book Storage Adjacent to Custodial Closet 004C	Floor	Partially Inaccessible	0	N	N	0	Y - 120 SF Boxes	N	
450	8250	1	0	002B-2	Primary	Classroom 002B (next to 003B)	W1	Chipping	4	N	N	0	N	N	
451	8250	1	0	002B-2	Primary	Classroom 002B (next to 003B)	W2	Cracking	20	N	N	0	Y - 20 SF Contents	N	
452	8250	1	0	002B-2	Primary	Classroom 002B (next to 003B)	W4	Cracking	2	N	N	0	Y - 22 SF Contents	N	
453	8250	1	0	002B-2	Primary	Classroom 002B (next to 003B)	W3	Partially Inaccessible	0	N	N	0	Y - 36 SF Contents	N	
454	8250	1	0	003B	Primary	Classroom 003B	W1	Cracking	4	N	N	0	N	N	
455	8250	1	0	003B	Primary	Classroom 003B	W3	Flaking	44	Y	N	0	N	Y - 6 SF	3 Locations; Additional Efflorescence
456	8250	1	0	003B	Primary	Classroom 003B	W4	Flaking	12	Y	Y - @ Window Sill 4	1	N	Y - 4 SF	2 Locations; Additional Efflorescence, Cracking
457	8250	1	0	003B	Primary	Classroom 003B	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Shelves, Contents	N	
458	8250	1	0	004B	Student Restrooms - Female (4-12)	Girls' Restroom	W2	Cracking	22	N	N	0	N	N	

Forrest -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
459	8250	1	0	004B	Student Restrooms - Female (4-12)	Girls' Restroom	W3	Cracking	8	N	N	0	N	N	
460	8250	1	0	004B	Student Restrooms - Female (4-12)	Girls' Restroom	W4	Cracking	10	N	N	0	N	N	
461	8250	1	0	009B	Administrative Office	Gymnasium Office	W1	Flaking	6	N	N	0	Y - 48 SF Desk, File Cabinet, Contents	N	
462	8250	1	0	009B	Administrative Office	Gymnasium Office	W2	Flaking	4	N	N	0	Y - 40 SF Sports Equipment	N	
463	8250	1	0	009B	Administrative Office	Gymnasium Office	W3	Flaking	90	N	N	0	Y - 40 SF Sports Equipment	N	
464	8250	1	0	009B	Administrative Office	Gymnasium Office	W4	Flaking	28	N	N	0	Y - 16 SF Desk, Contents	N	
465	8250	1	0	009B	Administrative Office	Gymnasium Office	Ceiling	Flaking	16	N	N	0	N	N	
466	8250	1	0	008B	Cafetorium (Cafeteria / Gymnasium)	Gymnasium/Cafeteria	W1	Flaking	180	N	N	0	N	N	5 Locations; Additional Cracking, Chipping
467	8250	1	0	008B	Cafetorium (Cafeteria / Gymnasium)	Gymnasium/Cafeteria	W3	Flaking	45	N	N	0	N	N	4 Locations; Additional Cracking
468	8250	1	0	008B	Cafetorium (Cafeteria / Gymnasium)	Gymnasium/Cafeteria	W4	Flaking	24	N	N	0	N	N	
469	8250	1	0	008B	Cafetorium (Cafeteria / Gymnasium)	Gymnasium/Cafeteria	Ceiling	Flaking	2100	N	N	0	N	N	Additional Cracking; Damage on Entire Ceiling Including Ductwork & Pipes
470	8250	1	0	008B	Cafetorium (Cafeteria / Gymnasium)	Gymnasium/Cafeteria	Floor	Flaking	27	N	Y - Near Stairs to H01B-1	36	N	N	Additional Chipping; Damage @ Both Stairs
471	8250	1	0	H04B	Circulation (Hallway)	Hallway in Gymnasium to Stairwell	W1	Flaking	10	N	N	0	N	N	
472	8250	1	0	H04B	Circulation (Hallway)	Hallway in Gymnasium to Stairwell	W2	Flaking	30	N	N	0	N	N	
473	8250	1	0	H04B	Circulation (Hallway)	Hallway in Gymnasium to Stairwell	W3	Flaking	10	N	N	0	N	N	
474	8250	1	0	H04B	Circulation (Hallway)	Hallway in Gymnasium to Stairwell	W4	Flaking	30	N	N	0	N	N	
475	8250	1	0	H04B	Circulation (Hallway)	Hallway in Gymnasium to Stairwell	Ceiling	Flaking	20	N	N	0	N	N	
476	8250	1	0	H01B-1	Circulation (Hallway)	Hallway on Boys' Restroom Side	W4	Chipping	16	N	N	0	N	N	
477	8250	1	0	H01B-1	Circulation (Hallway)	Hallway on Boys' Restroom Side	W2	Flaking	216	N	N	0	N	N	Additional Chipping
478	8250	1	0	H01B-1	Circulation (Hallway)	Hallway on Boys' Restroom Side	W3	Flaking	1	N	N	0	N	N	
479	8250	1	0	H01B-1	Circulation (Hallway)	Hallway on Boys' Restroom Side	Ceiling	Flaking	62	N	N	0	Y - 200 SF Ductwork	Y - 12 SF	

