

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6260	1	3	301	Primary	Classroom 301	W1	Flaking	18	N	N	0	Y - 18 SF Posters	N	Additional Chipping
2	6260	1	3	301	Primary	Classroom 301	W2	Flaking	4	N	N	0	Y - 12 SF Posters	N	Additional Holes
3	6260	1	3	301	Primary	Classroom 301	W3	Flaking	12	N	N	0	N	N	Flaking @ Radiator
4	6260	1	3	301A	Storage	Classroom 301 Closet	Ceiling	Significant Moisture Damage	2	Y	N	0	N	N	Water Stain
5	6260	1	3	301A	Storage	Classroom 301 Closet	W1	Partially Inaccessible		N	N	0	Y - 70 SF Cabinets, Contents	N	
6	6260	1	3	301A	Storage	Classroom 301 Closet	W2	Flaking	6	N	N	0	N	N	Flaking @ Radiator
7	6260	1	3	301A	Storage	Classroom 301 Closet	W3	Partially Inaccessible		N	N	0	Y - 60 SF Contents	N	
8	6260	1	3	302	Computer - Intermediate Middle	Classroom 302	W1	Cracking	4	N	N	0	N	N	Additional Chipping
9	6260	1	3	302	Computer - Intermediate Middle	Classroom 302	W2	Chipping	4	N	N	0	N	N	2 Locations
10	6260	1	3	302	Computer - Intermediate Middle	Classroom 302	W3	Flaking	24	N	Y - @ Window Sill 1	1	Y - 24 SF Contents	N	4 Locations; Additional Chipping
11	6260	1	3	302A	Storage	Classroom 302 Closet	Floor	Partially Inaccessible		N	N	0	Y - 120 SF Contents	N	
12	6260	1	3	302A	Storage	Classroom 302 Closet	W1	Partially Inaccessible		N	N	0	Y - 40 SF Contents	N	
13	6260	1	3	302A	Storage	Classroom 302 Closet	W2	Partially Inaccessible		N	N	0	Y - 24 SF Contents	N	
14	6260	1	3	302A	Storage	Classroom 302 Closet	W3	Partially Inaccessible		N	N	0	Y - 90 SF Contents	N	
15	6260	1	3	302A	Storage	Classroom 302 Closet	W4	Partially Inaccessible		N	N	0	Y - 20 SF Contents	N	
16	6260	1	3	303	Primary	Classroom 303	W1	Partially Inaccessible		N	N	0	Y - 20 SF Posters	N	
17	6260	1	3	303	Primary	Classroom 303	W2	Chipping	2	N	N	0	N	N	2 Locations; Additional Holes
18	6260	1	3	303	Primary	Classroom 303	W3	Flaking	30	N	Y - @ Window Sills 1 & 2	4	N	Y - 2 SF	4 Locations; Additional Chipping, Holes; Damage Includes Radiators & Walls
19	6260	1	3	303	Primary	Classroom 303	W4	Partially Inaccessible		N	N	0	Y - 60 SF File Cabinets, Desks, Bookcases, Posters	N	
20	6260	1	3	303A	Storage	Classroom 303 Closet	Ceiling	Cracking	6	N	N	0	N	N	
21	6260	1	3	303A	Storage	Classroom 303 Closet	Floor	Debris Present	0	N	Y - Under Windows	6	N	N	
22	6260	1	3	303A	Storage	Classroom 303 Closet	W1	Flaking	3	Y	N	0	N	Y - 1 SF	2 Locations; Additional Efflorescence
23	6260	1	3	303A	Storage	Classroom 303 Closet	W2	Flaking	18	N	N	0	Y - 24 SF Desks, Cabinets	N	
24	6260	1	3	303A	Storage	Classroom 303 Closet	W3	Partially Inaccessible		N	N	0	Y - 32 SF Contents	N	
25	6260	1	3	303A	Storage	Classroom 303 Closet	W4	Flaking	28	Y	N	0	N	Y - 1 SF	Additional Efflorescence
26	6260	1	3	304	Primary	Classroom 304	W1	Chipping	2	N	N	0	N	N	
27	6260	1	3	304	Primary	Classroom 304	W3	Flaking	16	Y	Y - @ Window Stills 4 & 6	2	N	Y - 1 SF	4 Locations; Additional Efflorescence, Cracking; Damage @ Wall, Radiator, Window Sills 4 & 6
28	6260	1	3	304	Primary	Classroom 304	W4	Cracking	2	N	N	0	N	Y - 1 SF	2 Locations; Additional Holes

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
29	6260	1	3	304A	Storage	Classroom 304 Closet	W2	Partially Inaccessible		N	N	0	Y - 24 SF Shelves	N	
30	6260	1	3	304A	Storage	Classroom 304 Closet	W3	Chipping	1	N	N	0	Y - 14 SF Cabinets	N	
31	6260	1	3	304A	Storage	Classroom 304 Closet	W4	Flaking	3	N	N	0	N	N	3 Locations; Additional Chipping
32	6260	1	3	305	Primary	Classroom 305	Floor	Debris Present	0	N	Y - Under Windows 2 & 3	2	N	N	
33	6260	1	3	305	Primary	Classroom 305	W1	Partially Inaccessible		N	N	0	Y - 40 SF Posters	N	
34	6260	1	3	305	Primary	Classroom 305	W3	Flaking	12	N	Y - Window Sill 4	1	N	N	2 Locations; Additional Cracking
35	6260	1	3	305A	Storage	Classroom 305 Closet	Ceiling	Inaccessible							
36	6260	1	3	305A	Storage	Classroom 305 Closet	Floor	Inaccessible							
37	6260	1	3	305A	Storage	Classroom 305 Closet	W1	Inaccessible							
38	6260	1	3	305A	Storage	Classroom 305 Closet	W2	Inaccessible							
39	6260	1	3	305A	Storage	Classroom 305 Closet	W3	Inaccessible							
40	6260	1	3	305A	Storage	Classroom 305 Closet	W4	Inaccessible							
41	6260	1	3	306	Primary	Classroom 306	W1	Chipping	8	N	N	0	Y - 24 SF Desks	N	4 Locations; Additional Holes
42	6260	1	3	306	Primary	Classroom 306	W2	Flaking	8	N	N	0	Y - 48 SF Desks, Books, Contents	N	Additional Cracking
43	6260	1	3	306	Primary	Classroom 306	W3	Flaking	24	N	Y - @ Window Sills 1, 2, 6	6	Y - 30 SF Bookcases, Desks	Y - 1 SF	4 Locations
44	6260	1	3	306A	Storage	Classroom 306 Closet	Ceiling	Inaccessible							
45	6260	1	3	306A	Storage	Classroom 306 Closet	Floor	Inaccessible							
46	6260	1	3	306A	Storage	Classroom 306 Closet	W1	Inaccessible							
47	6260	1	3	306A	Storage	Classroom 306 Closet	W2	Inaccessible							
48	6260	1	3	306A	Storage	Classroom 306 Closet	W3	Inaccessible							
49	6260	1	3	306A	Storage	Classroom 306 Closet	W4	Inaccessible							
50	6260	1	3	307	Primary	Classroom 307	W1	Chipping	5	N	N	0	Y - 10 SF Posters	N	2 Locations
51	6260	1	3	307	Primary	Classroom 307	W3	Flaking	10	N	Y - @ Window Sills 1-6	10	N	N	3 Locations; Additional Chipping; Damage on Radiator & Wall
52	6260	1	3	307	Primary	Classroom 307	W4	Cracking	12	N	N	0	N	N	
53	6260	1	3	307A	Storage	Classroom 307 Closet	W1	Partially Inaccessible		N	N	0	Y - 45 SF Bookcases, Contents	N	
54	6260	1	3	307A	Storage	Classroom 307 Closet	W2	Partially Inaccessible		N	N	0	Y - 25 SF Cabinets, Contents	N	
55	6260	1	3	307A	Storage	Classroom 307 Closet	W3	Partially Inaccessible		N	N	0	Y - 62 SF Lockers, Shelves, Contents	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
56	6260	1	3	307A	Storage	Classroom 307 Closet	W4	Partially Inaccessible		N	N	0	Y - 28 SF Lockers, Contents	N	
57	6260	1	3	308	Primary	Classroom 308	Ceiling	Significant Moisture Damage	2	Y	Y - Under Radiator	4	N	N	Suspended Ceiling
58	6260	1	3	308	Primary	Classroom 308	W1	Flaking	7	N	N	0	N	Y - 1 SF	2 Locations; Additional Cracking, Chipping
59	6260	1	3	308	Primary	Classroom 308	W2	Partially Inaccessible		N	N	0	Y - 30 SF Posters	N	
60	6260	1	3	308	Primary	Classroom 308	W3	Flaking	39	N	Y - @ Window Sills 3 & 4	3	N	Y - 1 SF	5 Locations; Additional Cracking, Chipping
61	6260	1	3	308A	Storage	Classroom 308 Closet	Ceiling	Significant Moisture Damage	2	Y	N	0	N	N	Suspended Ceiling; Water Stains
62	6260	1	3	308A	Storage	Classroom 308 Closet	W1	Flaking	3	N	N	0	Y - 40 SF Contents	N	2 Locations; Additional Cracking
63	6260	1	3	308A	Storage	Classroom 308 Closet	W3	Flaking	8	Y	N	0	N	Y - 2 SF	3 Locations; Additional Efflorescence, Cracking
64	6260	1	3	308A	Storage	Classroom 308 Closet	W4	Flaking	8	N	Y - @ Window Sill	2	N	N	Flaking Behind Radiator
65	6260	1	3	309	Primary	Classroom 309	W1	Partially Inaccessible		N	N	0	Y - 32 SF Posters	N	
66	6260	1	3	309	Primary	Classroom 309	W2	Partially Inaccessible		N	N	0	Y - 60 SF Posters	N	
67	6260	1	3	309	Primary	Classroom 309	W3	Flaking	6	N	N	0	N	N	Flaking @ Radiator 1
68	6260	1	3	309	Primary	Classroom 309	W4	Partially Inaccessible		N	N	0	Y - 36 SF File Cabinets, Posters	N	
69	6260	1	3	309C	Storage	Classroom 309 Closet	W2	Partially Inaccessible		N	N	0	Y - 120 SF Shelves, Contents	N	
70	6260	1	3	309C	Storage	Classroom 309 Closet	W4	Partially Inaccessible		N	N	0	Y - 120 SF Shelves, Contents	N	
71	6260	1	3	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 308	Floor	Debris Present	0	N	Y - Under Windows	12	N	N	
72	6260	1	3	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 308	W1	Chipping	2	N	N	0	N	N	Chipping @ Door
73	6260	1	3	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 308	W2	Flaking	78	N	N	0	N	N	2 Locations; Flaking @ Window Bars & Metal Pipe
74	6260	1	3	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 308	W3	Flaking	44	N	N	0	N	N	2 Locations; Flaking @ Window Bars & Metal Pipe
75	6260	1	3	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 308	W4	Chipping	3	N	N	0	N	N	Chipping @ Door
76	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	Ceiling	Inaccessible							
77	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	Floor	Inaccessible							
78	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	W1	Inaccessible							
79	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	W2	Inaccessible							
80	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	W3	Inaccessible							
81	6260	1	3	305B	Storage	Hallway Closet next to Classroom 305	W4	Inaccessible							
82	6260	1	3	H31	Circulation (Hallway)	Hallway outside Rooms 301-302	W2	Cracking	12	N	N	0	N	N	Additional Chipping
83	6260	1	3	H31	Circulation (Hallway)	Hallway outside Rooms 301-302	W3	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
84	6260	1	3	H31	Circulation (Hallway)	Hallway outside Rooms 301-302	W4	Cracking	3	N	Y - @ Window Sills 1-3	3	N	Y - 1 SF	3 Locations; Additional Chipping, Holes
85	6260	1	3	H32	Circulation (Hallway)	Hallway outside Rooms 303-306	W3	Partially Inaccessible		N	N	0	Y - 80 SF Posters	N	
86	6260	1	3	H33	Circulation (Hallway)	Hallway outside Rooms 307-308	W2	Cracking	16	N	Y - @ Window Sills 5 & 6	2	N	N	2 Locations
87	6260	1	3	H33	Circulation (Hallway)	Hallway outside Rooms 307-308	W3	Chipping	4	N	N	0	N	N	
88	6260	1	3	H33	Circulation (Hallway)	Hallway outside Rooms 307-308	W4	Partially Inaccessible		N	N	0	N	N	
89	6260	1	3	309A	Administrative Office	Office 309A	Ceiling	Cracking	20	N	N	0	N	N	
90	6260	1	3	309A	Administrative Office	Office 309A	Floor	Flaking	2	N	Y - Under Radiator	1	N	N	
91	6260	1	3	309A	Administrative Office	Office 309A	W1	Flaking	7	N	N	0	N	Y - 2 SF	3 Locations; Additional Cracking, Holes
92	6260	1	3	309A	Administrative Office	Office 309A	W2	Cracking	8	N	N	0	N	N	2 Locations
93	6260	1	3	309A	Administrative Office	Office 309A	W3	Flaking	12	N	Y - @ Window Sill 1	1	N	N	2 Locations
94	6260	1	3	309A	Administrative Office	Office 309A	W4	Cracking	2	N	N	0	N	N	
95	6260	1	3	311	Storage	Reading Room between Classrooms 303 and 304	Ceiling	Cracking	6	N	N	0	N	N	
96	6260	1	3	311	Storage	Reading Room between Classrooms 303 and 304	W1	Partially Inaccessible		N	N	0	Y - 106 SF Shelves, Contents	N	
97	6260	1	3	311	Storage	Reading Room between Classrooms 303 and 304	W2	Partially Inaccessible		N	N	0	Y - 140 SF Shelves, Contents	N	
98	6260	1	3	311	Storage	Reading Room between Classrooms 303 and 304	W3	Partially Inaccessible		N	N	0	Y - 106 SF Shelves, Contents	N	
99	6260	1	3	311	Storage	Reading Room between Classrooms 303 and 304	W4	Partially Inaccessible		N	N	0	Y - 140 SF Shelves, Contents	N	
100	6260	1	3	S5	Stairs	Stairwell A	Ceiling	Cracking	18	N	N	0	N	N	2 Locations
101	6260	1	3	S5	Stairs	Stairwell A	W1	Chipping	3	N	N	0	N	N	Chipping @ Door
102	6260	1	3	S5	Stairs	Stairwell A	W2	Flaking	48	N	N	0	N	N	2 Locations; Additional Cracking
103	6260	1	3	S5	Stairs	Stairwell A	W3	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking
104	6260	1	3	S5	Stairs	Stairwell A	W4	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
105	6260	1	3	S3	Stairs	Stairwell adjacent to Classroom 301	Floor	Debris Present	0	N	Y - Under Windows	12	N	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
106	6260	1	3	S3	Stairs	Stairwell adjacent to Classroom 301	W1	Chipping	4	N	N	0	N	N	Chipping @ Door
107	6260	1	3	S3	Stairs	Stairwell adjacent to Classroom 301	W2	Chipping	2	N	N	0	N	N	Chipping @ Door
108	6260	1	3	S3	Stairs	Stairwell adjacent to Classroom 301	W3	Flaking	44	N	N	0	N	N	Flaking on Window Bars & Metal Pipe
109	6260	1	3	S3	Stairs	Stairwell adjacent to Classroom 301	W4	Flaking	76	N	N	0	N	N	Flaking on Window Bars & Metal Pipe
110	6260	1	3	S4	Stairs	Stairwell B	Ceiling	Flaking	16	N	N	0	N	N	Additional Chipping; Ceilings > 20'
111	6260	1	3	S4	Stairs	Stairwell B	W2	Cracking	22	N	N	0	N	N	2 Locations
112	6260	1	3	S4	Stairs	Stairwell B	W3	Cracking	32	N	N	0	N	N	2 Locations
113	6260	1	3	S4	Stairs	Stairwell B	W4	Cracking	12	N	N	0	N	N	3 Locations
114	6260	1	2	202A	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking	22	Y	N	0	N	Y - 8 SF	3 Locations; Additional Efflorescence, Chipping
115	6260	1	2	201	Primary	Classroom 201	W1	Flaking	18	N	N	0	Y - 32 SF Desks, Posters	N	
116	6260	1	2	201	Primary	Classroom 201	W3	Partially Inaccessible		N	N	0	Y - 54 SF Posters, Contents	N	
117	6260	1	2	201	Primary	Classroom 201	W4	Partially Inaccessible		N	N	0	Y - 48 SF Desks, Posters, Contents	N	
118	6260	1	2	201A	Storage	Classroom 201 Closet	W1	Flaking	14	N	N	0	N	Y - 2 SF	2 Locations; Additional Cracking
119	6260	1	2	201A	Storage	Classroom 201 Closet	W2	Flaking	12	N	Y - @ Window Sill	3	N	N	Additional Cracking; Damage @ Wall, Window Frame, Radiator
120	6260	1	2	201A	Storage	Classroom 201 Closet	W3	Cracking	2	N	N	0	N	N	
121	6260	1	2	202	Primary	Classroom 202	W3	Flaking	7	N	Y - @ Window Sills 1-6	6	N	N	3 Locations; Additional Chipping
122	6260	1	2	202B	Storage	Classroom 202 Closet	W1	Flaking	6	N	N	0	N	N	
123	6260	1	2	202B	Storage	Classroom 202 Closet	W2	Partially Inaccessible		N	N	0	Y - 28 SF File Cabinets, Contents	N	
124	6260	1	2	202B	Storage	Classroom 202 Closet	W3	Flaking	6	N	N	0	Y - 28 SF Cabinets, Desks	N	2 Locations; Additional Cracking
125	6260	1	2	202B	Storage	Classroom 202 Closet	W4	Flaking	6	N	N	0	N	N	Flaking on/under Radiator
126	6260	1	2	203	Primary	Classroom 203	Ceiling	Significant Moisture Damage	8	Y	N	0	N	N	Suspended Ceiling; Water Stains Above Windows 1-4
127	6260	1	2	203	Primary	Classroom 203	W1	Partially Inaccessible		N	N	0	Y - 40 SF Bookcases, Posters	N	
128	6260	1	2	203	Primary	Classroom 203	W2	Chipping	1	N	N	0	N	N	
129	6260	1	2	203	Primary	Classroom 203	W3	Flaking	12	N	N	0	N	N	3 Locations; Additional Chipping; Damage @ Radiator & Wall
130	6260	1	2	203	Primary	Classroom 203	W4	Flaking	2	N	N	0	Y - 24 SF Posters	N	
131	6260	1	2	203C	Storage	Classroom 203 Large Closet	Ceiling	Significant Moisture Damage	2	Y	N	0	N	N	Suspended Ceiling; Water Stain above Window
132	6260	1	2	203C	Storage	Classroom 203 Large Closet	W1	Flaking	2	N	N	0	Y - 24 SF Cabinets, Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
133	6260	1	2	203C	Storage	Classroom 203 Large Closet	W2	Flaking	14	N	Y - Near Window	1	N	Y - 1 SF	Additional Cracking, Chipping, Holes; Tree Growing through Wall
134	6260	1	2	203C	Storage	Classroom 203 Large Closet	W3	Partially Inaccessible		N	N	0	Y - 36 SF Contents	N	
135	6260	1	2	203B	Storage	Classroom 203 Small Closet	Ceiling	Inaccessible							
136	6260	1	2	203B	Storage	Classroom 203 Small Closet	Floor	Inaccessible							
137	6260	1	2	203B	Storage	Classroom 203 Small Closet	W1	Inaccessible							
138	6260	1	2	203B	Storage	Classroom 203 Small Closet	W2	Inaccessible							
139	6260	1	2	203B	Storage	Classroom 203 Small Closet	W3	Inaccessible							
140	6260	1	2	203B	Storage	Classroom 203 Small Closet	W4	Inaccessible							
141	6260	1	2	204	Primary	Classroom 204	W3	Flaking	18	N	N	0	Y - 32 SF Contents	Y - 2 SF	2 Locations; Damage Includes Radiators
142	6260	1	2	204	Primary	Classroom 204	W4	Partially Inaccessible		N	N	0	Y - 55 SF Desks, Fridge, Posters	N	
143	6260	1	2	204A	Storage	Classroom 204 Closet	W2	Flaking	10	N	N	0	Y - 72 SF Contents	N	Additional Cracking
144	6260	1	2	204A	Storage	Classroom 204 Closet	W3	Partially Inaccessible		N	N	0	Y - 32 SF Contents	N	
145	6260	1	2	204A	Storage	Classroom 204 Closet	W4	Flaking	4	N	N	0	Y - 72 SF Contents	N	
146	6260	1	2	205	Primary	Classroom 205	Ceiling	Significant Moisture Damage	2	Y	N	N	N	N	Suspended Ceiling; Water Stain above Window 4
147	6260	1	2	205	Primary	Classroom 205	W1	Partially Inaccessible		N	N	N	Y - 16 SF Posters	N	
148	6260	1	2	205	Primary	Classroom 205	W3	Flaking	17	N	Y - @ Window Sills 4-6 & Under Radiator 1	14	N	N	4 Locations
149	6260	1	2	205A	Storage	Classroom 205 Closet	Ceiling	Inaccessible							
150	6260	1	2	205A	Storage	Classroom 205 Closet	Floor	Inaccessible							
151	6260	1	2	205A	Storage	Classroom 205 Closet	W1	Inaccessible							
152	6260	1	2	205A	Storage	Classroom 205 Closet	W2	Inaccessible							
153	6260	1	2	205A	Storage	Classroom 205 Closet	W3	Inaccessible							
154	6260	1	2	205A	Storage	Classroom 205 Closet	W4	Inaccessible							
155	6260	1	2	206	Primary	Classroom 206	Ceiling	Significant Moisture Damage	24	Y	N	0	N	N	
156	6260	1	2	206	Primary	Classroom 206	W1	Cracking	3	N	N	0	N	N	
157	6260	1	2	206	Primary	Classroom 206	W2	Cracking	2	N	N	0	Y - 32 SF Posters, Contents	N	
158	6260	1	2	206	Primary	Classroom 206	W3	Flaking	20	N	Y - @ Window Sills 3 & 4	2 SF	N	N	
159	6260	1	2	206A	Storage	Classroom 206 Closet	W2	Cracking	4	N	N	0	Y - 35 SF Bookcases	Y - 3 SF	Additional Holes

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
160	6260	1	2	206A	Storage	Classroom 206 Closet	W3	Flaking	1	N	N	0	Y - 30 SF Bookcases, Contents	N	Flaking @ Window Frame
161	6260	1	2	206A	Storage	Classroom 206 Closet	W4	Flaking	13	N	N	0	N	N	4 Locations
162	6260	1	2	207	Primary	Classroom 207	W1	Cracking	2	N	N	0	N	N	
163	6260	1	2	207	Primary	Classroom 207	W3	Spalling	19	Y	Y - @ Window Sill 2	1	N	Y - 1 SF	3 Locations; Additional Chipping; Damage @ Window Frame 2 & Radiators
164	6260	1	2	207	Primary	Classroom 207	W4	Flaking	15	N	N	0	N	N	N
165	6260	1	2	207A	Storage	Classroom 207 Closet	W1	Flaking	4	N	N	0	Y - 24 SF Boxes	N	2 Locations; Additional Chipping
166	6260	1	2	207A	Storage	Classroom 207 Closet	W2	Cracking	3	N	N	0	Y - 28 SF Cabinets	N	
167	6260	1	2	207A	Storage	Classroom 207 Closet	W3	Chipping	4	N	N	0	Y - 8 SF Boxes	N	
168	6260	1	2	207A	Storage	Classroom 207 Closet	W4	Partially Inaccessible		N	N	0	Y - 14 SF File Cabinets, Contents	N	
169	6260	1	2	208	Primary	Classroom 208	W1	Flaking	8	N	N	0	Y - 8 SF Posters	N	3 Locations
170	6260	1	2	208	Primary	Classroom 208	W2	Chipping	1	N	N	0	N	N	Previously Abated
171	6260	1	2	208	Primary	Classroom 208	W3	Flaking	32	N	Y - @ Window Sills 1 & 6	2	N	N	5 Locations; Additional Cracking, Chipping; Damage Includes Wall behind ACPI
172	6260	1	2	208A	Storage	Classroom 208 Closet	W1	Flaking	36	N	N	0	Y - 60 SF Bookcases, Contents	N	Additional Chipping
173	6260	1	2	208A	Storage	Classroom 208 Closet	W2	Partially Inaccessible		N	N	0	Y - 35 SF Cabinets, Contents	N	
174	6260	1	2	208A	Storage	Classroom 208 Closet	W3	Cracking	28	N	N	0	N	N	Wall Partially Abated
175	6260	1	2	208A	Storage	Classroom 208 Closet	W4	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
176	6260	1	2	209	Primary	Classroom 209	Ceiling	Efflorescence	2	Y	N	0	N	N	Concealed by Suspended Ceiling
177	6260	1	2	209	Primary	Classroom 209	W3	Flaking	4	Y	Y - @ Window Sills 4-6	3	N	Y - 2 SF	2 Locations; Additional Efflorescence, Chipping; Water Stains Present; Damage @ Walls & Radiator
178	6260	1	2	209	Primary	Classroom 209	W4	Partially Inaccessible		N	N	0	Y - 40 SF Bookcases, Posters	N	
179	6260	1	2	209A	Storage	Classroom 209 Closet	W2	Flaking	4	N	N	0	Y - 110 SF Bookcases, Contents	N	Additional Cracking
180	6260	1	2	209A	Storage	Classroom 209 Closet	W3	Flaking	1	N	Y - On Wood Trim	1	Y - 20 SF Contents	N	
181	6260	1	2	210	Primary	Classroom 210	Ceiling	Flaking	25	N	N	0	N	N	2 Locations
182	6260	1	2	210	Primary	Classroom 210	W1	Partially Inaccessible		N	N	0	Y - 32 SF Desks, Tables	N	
183	6260	1	2	210	Primary	Classroom 210	W2	Partially Inaccessible		N	N	0	Y - 48 SF Desks	N	
184	6260	1	2	210	Primary	Classroom 210	W3	Partially Inaccessible		N	N	0	Y - 20 SF Desks, Posters	N	
185	6260	1	2	210	Primary	Classroom 210	W4	Flaking	2	N	N	0	N	N	
186	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	Ceiling	Inaccessible							
187	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	Floor	Inaccessible							
188	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	W1	Inaccessible							

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
189	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	W2	Inaccessible							
190	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	W3	Inaccessible							
191	6260	1	2	210B	Storage	Classroom 210 Closet by Entrance	W4	Inaccessible							
192	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	Ceiling	Inaccessible							
193	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	Floor	Inaccessible							
194	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	W1	Inaccessible							
195	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	W2	Inaccessible							
196	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	W3	Inaccessible							
197	6260	1	2	210C	Storage	Classroom 210 Closet in Corner	W4	Inaccessible							
198	6260	1	2	211	Primary	Classroom 211	Ceiling	Flaking	12	N	N	0	N	N	6 Locations
199	6260	1	2	211	Primary	Classroom 211	W1	Flaking	4	N	N	0	Y - 32 SF Cabinets, Bookcases	N	
200	6260	1	2	211	Primary	Classroom 211	W2	Cracking	1	N	N	0	Y - 32 SF Cabinets, Bookcases	N	
201	6260	1	2	211	Primary	Classroom 211	W3	Flaking	4	N	N	0	N	N	
202	6260	1	2	212	Primary	Classroom 212	Ceiling	Flaking	80	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
203	6260	1	2	212	Primary	Classroom 212	W2	Flaking	80	N	N	0	N	N	Flaking on Entire Wall
204	6260	1	2	212	Primary	Classroom 212	W3	Flaking	90	N	Y - @ Window Sills	6	N	N	Flaking on Entire Wall
205	6260	1	2	212	Primary	Classroom 212	W4	Flaking	12	N	N	0	N	N	Additional Cracking; Damage above Chalkboard
206	6260	1	2	212C	Storage	Classroom 212 Closet	Ceiling	Inaccessible							
207	6260	1	2	212C	Storage	Classroom 212 Closet	Floor	Inaccessible							
208	6260	1	2	212C	Storage	Classroom 212 Closet	W1	Inaccessible							
209	6260	1	2	212C	Storage	Classroom 212 Closet	W2	Inaccessible							
210	6260	1	2	212C	Storage	Classroom 212 Closet	W3	Inaccessible							
211	6260	1	2	212C	Storage	Classroom 212 Closet	W4	Inaccessible							
212	6260	1	2	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 208	Floor	Debris Present	0	N	Y - On Ground beneath Window Sill	12	N	N	
213	6260	1	2	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 208	W2	Flaking	64	N	Y - @ Window Sill	8	N	N	Flaking @ Window Bars & Metal Pipe
214	6260	1	2	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 208	W3	Flaking	32	N	Y - @ Window Sill	4	N	N	Flaking @ Window Bars & Metal Pipe
215	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	Ceiling	Inaccessible							

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
216	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	Floor	Inaccessible							
217	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	W1	Inaccessible							
218	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	W2	Inaccessible							
219	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	W3	Inaccessible							
220	6260	1	2	205B	Storage	Hallway Closet adjacent to Classroom 205	W4	Inaccessible							
221	6260	1	2	H2B	Circulation (Hallway)	Hallway from Element 1 to Stairwell adjacent to Classroom 210	Ceiling	Flaking	100	N	N	0	N	N	Additional Cracking
222	6260	1	2	H2B	Circulation (Hallway)	Hallway from Element 1 to Stairwell adjacent to Classroom 210	W1	Flaking	3	N	N	0	N	N	Additional Cracking
223	6260	1	2	H2B	Circulation (Hallway)	Hallway from Element 1 to Stairwell adjacent to Classroom 210	W3	Flaking	8	N	N	0	N	N	3 Locations; Additional Cracking
224	6260	1	2	H2B	Circulation (Hallway)	Hallway from Element 1 to Stairwell adjacent to Classroom 210	W4	Cracking	9	Y	N	0	N	N	2 Locations; Water Stain above Window
225	6260	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	Ceiling	Significant Moisture Damage	2	Y	N	0	N	N	Suspended Ceiling; Water Stain above Window 5
226	6260	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W2	Cracking	240	N	N	0	Y - 32 SF Posters	N	
227	6260	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W3	Cracking	5	N	N	0	N	N	2 Locations; Additional Chipping
228	6260	1	2	H21	Circulation (Hallway)	Hallway outside Classrooms 201-202	W4	Flaking	27	N	Y - @ Window Sill 3	2	N	N	Additional Cracking
229	6260	1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 203-206	W1	Cracking	7	N	N	0	Y - 48 SF Posters	N	3 Locations; Additional Chipping
230	6260	1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 203-206	W2	Cracking	2	N	N	0	N	N	
231	6260	1	2	H22	Circulation (Hallway)	Hallway outside Classrooms 203-206	W3	Flaking	18	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
232	6260	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 207-208	Ceiling	Flaking	27	N	N	0	N	Y - 12 SF	Additional Cracking, Holes; 4 Ceiling Tiles @ Window 1
233	6260	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 207-208	W2	Flaking	22	N	Y - @ Window Sill & Radiator	16	Y - 20 SF Posters	N	Additional Cracking, Chipping; Damage Includes ACPI

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
234	6260	1	2	H23	Circulation (Hallway)	Hallway outside Classrooms 207-208	W4	Cracking	120	N	N	0	N	N	
235	6260	1	2	H2A	Circulation (Hallway)	Hallway outside Classrooms 210-212	Ceiling	Flaking	120	N	N	0	N	N	7 Locations; Additional Chipping
236	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	Ceiling	Inaccessible							
237	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	Floor	Inaccessible							
238	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	W1	Inaccessible							
239	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	W2	Inaccessible							
240	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	W3	Inaccessible							
241	6260	1	2	203D	Restrooms, Staff - Male/Female	Office 203 Restroom	W4	Inaccessible							
242	6260	1	2	203A	Administrative Office	Office 203A	Ceiling	Inaccessible							
243	6260	1	2	203A	Administrative Office	Office 203A	Floor	Inaccessible							
244	6260	1	2	203A	Administrative Office	Office 203A	W1	Inaccessible							
245	6260	1	2	203A	Administrative Office	Office 203A	W2	Inaccessible							
246	6260	1	2	203A	Administrative Office	Office 203A	W3	Inaccessible							
247	6260	1	2	203A	Administrative Office	Office 203A	W4	Inaccessible							
248	6260	1	2	210A	Administrative Office	Speech Therapist Office between Classrooms 210 and 211	W2	Flaking	5	N	N	0	Y - 30 SF Contents	N	2 Locations; Additional Cracking
249	6260	1	2	210A	Administrative Office	Speech Therapist Office between Classrooms 210 and 211	W3	Cracking	2	N	N	0	N	N	
250	6260	1	2	210A	Administrative Office	Speech Therapist Office between Classrooms 210 and 211	W4	Cracking	3	N	N	0	Y - 80 SF Bookcases, Tables	N	
251	6260	1	2	213	Restrooms, Staff - Male/Female	Staff Restroom across from Classroom 212	Ceiling	Flaking	8	Y	N	0	N	N	Water Stain on Ceiling
252	6260	1	2	213	Restrooms, Staff - Male/Female	Staff Restroom across from Classroom 212	W2	Flaking	1	N	N	0	N	N	
253	6260	1	2	213	Restrooms, Staff - Male/Female	Staff Restroom across from Classroom 212	W3	Flaking	4	N	N	0	N	N	Flaking above Window
254	6260	1	2	S5	Stairs	Stairwell A	Ceiling	Flaking	16	N	N	0	N	N	4 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
255	6260	1	2	S5	Stairs	Stairwell A	W2	Cracking	32	N	N	0	N	N	Additional Chipping
256	6260	1	2	S5	Stairs	Stairwell A	W3	Cracking	8	N	N	0	N	N	2 Locations
257	6260	1	2	S5	Stairs	Stairwell A	W4	Cracking	16	N	N	0	N	N	
258	6260	1	2	S1	Stairs	Stairwell across from Classroom 212	W2	Flaking	3	N	N	0	N	N	Additional Cracking
259	6260	1	2	S1	Stairs	Stairwell across from Classroom 212	W3	Cracking	2	N	N	0	N	N	
260	6260	1	2	S1	Stairs	Stairwell across from Classroom 212	W4	Cracking	6	N	N	0	N	N	
261	6260	1	2	S3	Stairs	Stairwell adjacent to Classroom 201	W1	Flaking	32	N	N	0	N	N	Additional Cracking
262	6260	1	2	S3	Stairs	Stairwell adjacent to Classroom 201	W2	Flaking	48	N	N	0	N	N	Additional Cracking
263	6260	1	2	S3	Stairs	Stairwell adjacent to Classroom 201	W3	Cracking	16	N	N	0	N	N	
264	6260	1	2	S3	Stairs	Stairwell adjacent to Classroom 201	W4	Flaking	36	N	N	0	N	N	Additional Cracking
265	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	Ceiling	Flaking	1	N	N	0	N	N	
266	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	Floor	Debris Present	0	N	Y - Under Window	4 SF	N	N	
267	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	W1	Flaking	2	N	N	0	N	N	
268	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	W2	Flaking	3	N	N	0	N	N	
269	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	W3	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
270	6260	1	2	S2	Stairs	Stairwell adjacent to Classroom 210	W4	Flaking	9	N	N	0	N	N	
271	6260	1	2	S4	Stairs	Stairwell B	W2	Cracking	36	N	N	0	N	N	Additional Chipping
272	6260	1	2	S4	Stairs	Stairwell B	W3	Cracking	9	N	N	0	N	N	2 Locations
273	6260	1	2	S4	Stairs	Stairwell B	W4	Cracking	26	N	N	0	N	N	2 Locations
274	6260	1	2	212A	Teacher Lounge/Dining	Teacher Lounge 209A	Ceiling	Flaking	8	Y	N	N	N	Y - 3 SF	2 Locations; Additional Efflorescence, Cracking
275	6260	1	2	212A	Teacher Lounge/Dining	Teacher Lounge 209A	W1	Flaking	8	Y	N	N	N	Y - 2 SF	Additional Spalling
276	6260	1	2	212A	Teacher Lounge/Dining	Teacher Lounge 209A	W2	Flaking	40	N	N	N	N	N	4 Locations; Additional Cracking, Holes
277	6260	1	2	212A	Teacher Lounge/Dining	Teacher Lounge 209A	W3	Chipping	1	N	N	N	N	N	
278	6260	1	2	212A	Teacher Lounge/Dining	Teacher Lounge 209A	W4	Flaking	15	N	N	N	N	N	3 Locations; Additional Cracking, Chipping
279	6260	1	2	211A	Restrooms, Staff - Male/Female	Teacher Lounge 209A Restroom	Ceiling	Flaking	60	Y	N	N	N	Y - 16 SF	Additional Efflorescence; Damage on Entire Ceiling
280	6260	1	2	211A	Restrooms, Staff - Male/Female	Teacher Lounge 209A Restroom	Floor	Debris Present	0	N	Y - Behind Pipe	1	N	N	
281	6260	1	2	211A	Restrooms, Staff - Male/Female	Teacher Lounge 209A Restroom	W4	Flaking	2	N	N	N	N	N	Flaking on Metal Pipe

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
282	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	Ceiling	Inaccessible							
283	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	Floor	Inaccessible							
284	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	W1	Inaccessible							
285	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	W2	Inaccessible							
286	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	W3	Inaccessible							
287	6260	1	2	212B	Telecommunication Equipment Room	Teacher Lounge 209A Telecommunication Equipment Room	W4	Inaccessible							
288	6260	1	1	115	Student Restrooms - Male (4-12)	1st Floor Element 2 Boy's Restroom	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
289	6260	1	1	121	Auditorium	Auditorium	Ceiling	Flaking	60	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence
290	6260	1	1	121	Auditorium	Auditorium	Floor	Chipping	4	N	N	0	N	N	Chipping @ Door
291	6260	1	1	121	Auditorium	Auditorium	W1	Chipping	4	N	N	0	N	N	
292	6260	1	1	121	Auditorium	Auditorium	W2	Cracking	16	N	N	0	N	N	2 Locations
293	6260	1	1	121	Auditorium	Auditorium	W3	Flaking	15	N	N	0	N	N	3 Locations; Additional Cracking
294	6260	1	1	101	Primary	Classroom 101	W1	Cracking	16	N	N	0	N	N	2 Locations; Additional Chipping, Holes
295	6260	1	1	101	Primary	Classroom 101	W3	Flaking	5	N	Y - @ Window Sills 4-6	4	Y - 56 SF Desks, Bookcases	N	3 Locations; Additional Chipping; Damage @ Wall & Radiator
296	6260	1	1	101	Primary	Classroom 101	W4	Flaking	4	N	N	0	N	N	
297	6260	1	1	101A	Storage	Classroom 101 Closet	Ceiling	Inaccessible							
298	6260	1	1	101A	Storage	Classroom 101 Closet	Floor	Inaccessible							
299	6260	1	1	101A	Storage	Classroom 101 Closet	W1	Inaccessible							
300	6260	1	1	101A	Storage	Classroom 101 Closet	W2	Inaccessible							
301	6260	1	1	101A	Storage	Classroom 101 Closet	W3	Inaccessible							
302	6260	1	1	101A	Storage	Classroom 101 Closet	W4	Inaccessible							
303	6260	1	1	102	Primary	Classroom 102	W1	Flaking	27	N	N	0	Y - 18 SF Desks	N	3 Locations; Additional Cracking, Chipping
304	6260	1	1	102	Primary	Classroom 102	W2	Flaking	3	N	N	0	N	N	2 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
305	6260	1	1	102	Primary	Classroom 102	W3	Flaking	22	N	N	0	Y - 40 SF Bookcases, Contents	N	2 Locations; Additional Chipping; Damage @ Wall & Radiator
306	6260	1	1	102A	Storage	Classroom 102 Closet	W1	Flaking	2	N	N	0	N	N	
307	6260	1	1	102A	Storage	Classroom 102 Closet	W2	Cracking	6	N	N	0	N	N	
308	6260	1	1	102A	Storage	Classroom 102 Closet	W3	Flaking	64	N	N	0	Y - 42 SF Cabinets, Contents	N	Additional Cracking
309	6260	1	1	103	Primary	Classroom 103	W1	Flaking	12	N	N	0	N	N	
310	6260	1	1	103	Primary	Classroom 103	W3	Chipping	3	N	N	0	N	N	
311	6260	1	1	103	Primary	Classroom 103	W4	Flaking	30	N	N	0	Y - 48 SF Bookcases	N	
312	6260	1	1	103A	Storage	Classroom 103 Closet	W2	Cracking	60	N	N	0	Y - 60 SF Contents	N	
313	6260	1	1	103A	Storage	Classroom 103 Closet	W3	Partially Inaccessible		N	N	0	Y - 14 SF File Cabinets	N	
314	6260	1	1	103A	Storage	Classroom 103 Closet	W4	Partially Inaccessible		N	N	0	Y - 60 SF Contents	N	
315	6260	1	1	104	Primary	Classroom 104	W1	Flaking	30	N	N	0	Y - 50 SF Desks, Chairs, Cabinets	N	Additional Chipping, Holes
316	6260	1	1	104	Primary	Classroom 104	W2	Partially Inaccessible		N	N	0	Y - 48 SF Desks, Chairs, File Cabinets	N	
317	6260	1	1	104	Primary	Classroom 104	W3	Partially Inaccessible		N	N	0	Y - 52 SF Contents	N	
318	6260	1	1	104A	Storage	Classroom 104 Closet	Ceiling	Inaccessible							
319	6260	1	1	104A	Storage	Classroom 104 Closet	Floor	Inaccessible							
320	6260	1	1	104A	Storage	Classroom 104 Closet	W1	Inaccessible							
321	6260	1	1	104A	Storage	Classroom 104 Closet	W2	Inaccessible							
322	6260	1	1	104A	Storage	Classroom 104 Closet	W3	Inaccessible							
323	6260	1	1	104A	Storage	Classroom 104 Closet	W4	Inaccessible							
324	6260	1	1	106	Primary	Classroom 106	W1	Chipping	6	N	N	0	Y - 18 SF Posters	N	2 Locations
325	6260	1	1	106	Primary	Classroom 106	W2	Flaking	18	N	N	0	Y - 8 SF Desks	N	2 Locations; Additional Cracking
326	6260	1	1	106	Primary	Classroom 106	W3	Flaking	11	N	N	0	Y - 52 SF Contents	N	3 Locations
327	6260	1	1	106	Primary	Classroom 106	W4	Partially Inaccessible		N	N	0	Y - 26 SF Desks, Posters	N	
328	6260	1	1	106A	Storage	Classroom 106 Closet	W2	Flaking	120	N	N	0	N	Y - 2 SF	Additional Cracking, Holes; Damage on Entire Wall
329	6260	1	1	106A	Storage	Classroom 106 Closet	W3	Flaking	18	N	N	0	N	N	2 Locations; Additional Cracking; Damage Includes Metal Pipe
330	6260	1	1	106A	Storage	Classroom 106 Closet	W4	Flaking	110	N	N	0	N	N	Additional Cracking, Holes
331	6260	1	1	107	Primary	Classroom 107	Floor	Debris Present	0	N	Y - Below Window Sill 1	1	N	N	
332	6260	1	1	107	Primary	Classroom 107	W1	Cracking	36	N	N	0	Y - 20 SF Posters	N	2 Locations; Additional Chipping
333	6260	1	1	107	Primary	Classroom 107	W2	Debris Present	0	N	N	0	Y - 12 SF Posters	N	
334	6260	1	1	107	Primary	Classroom 107	W3	Flaking	25	N	Y - Window Sill 1	2	N	Y - 1 SF	Additional Cracking, Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
335	6260	1	1	107	Primary	Classroom 107	W4	Flaking	3	N	N	0	Y - 16 SF Posters	N	Additional Cracking
336	6260	1	1	107A	Storage	Classroom 107 Closet	Ceiling	Cracking	8	N	N	0	N	N	2 Locations
337	6260	1	1	107A	Storage	Classroom 107 Closet	W1	Partially Inaccessible		N	N	0	Y - 50 SF Desks	N	
338	6260	1	1	107A	Storage	Classroom 107 Closet	W2	Partially Inaccessible		N	N	0	Y - 14 SF Contents	N	
339	6260	1	1	107A	Storage	Classroom 107 Closet	W3	Partially Inaccessible		N	N	0	Y - 70 SF Contents	N	
340	6260	1	1	107A	Storage	Classroom 107 Closet	W4	Partially Inaccessible		N	N	0	Y - 40 SF Contents	N	
341	6260	1	1	108	Primary	Classroom 108	W1	Partially Inaccessible		N	N	0	Y - 18 SF Bookcases, Posters	N	
342	6260	1	1	108	Primary	Classroom 108	W2	Cracking	4	N	N	0	N	N	
343	6260	1	1	108	Primary	Classroom 108	W3	Flaking	18	N	N	0	N	N	2 Locations; Additional Cracking
344	6260	1	1	108A	Storage	Classroom 108 Closet	W1	Flaking	160	N	N	0	N	N	Additional Cracking
345	6260	1	1	108A	Storage	Classroom 108 Closet	W2	Flaking	8	N	N	0	N	N	Additional Cracking
346	6260	1	1	108A	Storage	Classroom 108 Closet	W3	Cracking	80	N	N	0	N	N	
347	6260	1	1	108A	Storage	Classroom 108 Closet	W4	Flaking	8	N	N	0	N	N	Flaking @ Radiator
348	6260	1	1	109	Primary	Classroom 109	W1	Flaking	24	Y	N	0	Y - 24 SF Contents	Y - 18 SF	3 Locations; Additional Efflorescence, Cracking, Chipping
349	6260	1	1	109	Primary	Classroom 109	W2	Partially Inaccessible		N	N	0	Y - 36 SF Bookcases, Contents	N	
350	6260	1	1	109	Primary	Classroom 109	W3	Flaking	32	N	N	0	Y - 22 SF Contents	N	5 Locations; Additional Cracking, Chipping
351	6260	1	1	109	Primary	Classroom 109	W4	Flaking	16	N	N	0	Y - 48 SF Bookcases, Posters	Y - 1 SF	Additional Cracking
352	6260	1	1	109A	Storage	Classroom 109 Large Closet	W2	Flaking	1	N	N	0	Y - 56 SF Contents	N	
353	6260	1	1	109A	Storage	Classroom 109 Large Closet	W3	Cracking	4	N	N	0	N	N	
354	6260	1	1	109A	Storage	Classroom 109 Large Closet	W4	Chipping	8	N	N	0	Y - 40 SF Contents	N	
355	6260	1	1	109B	Student Restrooms - Male/Female (Classroom)	Classroom 109 Restroom	Ceiling	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence
356	6260	1	1	109C	Storage	Classroom 109 Small Closet adjacent to Restroom	Ceiling	Cracking	2	N	N	0	N	N	
357	6260	1	1	109C	Storage	Classroom 109 Small Closet adjacent to Restroom	W2	Chipping	4	N	N	0	Y - 32 SF Shelves	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
358	6260	1	1	109C	Storage	Classroom 109 Small Closet adjacent to Restroom	W3	Cracking	1	N	N	0	Y - 32 SF Shelves	N	
359	6260	1	1	109C	Storage	Classroom 109 Small Closet adjacent to Restroom	W4	Flaking	4	N	N	0	Y - 48 SF Shelves	N	
360	6260	1	1	111	Primary	Classroom 111	Ceiling	Flaking	28	N	N	0	N	N	5 Locations
361	6260	1	1	111	Primary	Classroom 111	W1	Partially Inaccessible		N	N	0	Y - 120 SF Contents	N	
362	6260	1	1	111	Primary	Classroom 111	W2	Partially Inaccessible		N	N	0	Y - 48 SF Contents	N	
363	6260	1	1	111	Primary	Classroom 111	W3	Flaking	5	N	N	0	N	N	2 Locations
364	6260	1	1	111	Primary	Classroom 111	W4	Cracking	4	N	N	0	N	N	
365	6260	1	1	111A	Storage	Classroom 111 Closet	Ceiling	Inaccessible							
366	6260	1	1	111A	Storage	Classroom 111 Closet	Floor	Inaccessible							
367	6260	1	1	111A	Storage	Classroom 111 Closet	W1	Inaccessible							
368	6260	1	1	111A	Storage	Classroom 111 Closet	W2	Inaccessible							
369	6260	1	1	111A	Storage	Classroom 111 Closet	W3	Inaccessible							
370	6260	1	1	111A	Storage	Classroom 111 Closet	W4	Inaccessible							
371	6260	1	1	112	Primary	Classroom 112	Ceiling	Flaking	5	N	N	0	N	N	2 Locations
372	6260	1	1	112	Primary	Classroom 112	W1	Flaking	8	N	N	0	Y - 64 SF Desks, Contents	N	2 Locations; Additional Cracking, Chipping
373	6260	1	1	112	Primary	Classroom 112	W2	Flaking	8	N	N	0	Y - 48 SF Tables, File Cabinets, Contents	N	Additional Cracking
374	6260	1	1	112	Primary	Classroom 112	W3	Flaking	6	N	N	0	Y - 60 SF Desks	N	Additional Cracking, Chipping
375	6260	1	1	112	Primary	Classroom 112	W4	Partially Inaccessible		N	N	0	Y - 48 SF Desks	N	
376	6260	1	1	112C	Storage	Classroom 112 Closet	Ceiling	Inaccessible							
377	6260	1	1	112C	Storage	Classroom 112 Closet	Floor	Inaccessible							
378	6260	1	1	112C	Storage	Classroom 112 Closet	W1	Inaccessible							
379	6260	1	1	112C	Storage	Classroom 112 Closet	W2	Inaccessible							
380	6260	1	1	112C	Storage	Classroom 112 Closet	W3	Inaccessible							
381	6260	1	1	112C	Storage	Classroom 112 Closet	W4	Inaccessible							
382	6260	1	1	114	Copying Room	Copy Room 103A	W1	Cracking	7	N	N	0	N	N	2 Locations; Additional Chipping
383	6260	1	1	114	Copying Room	Copy Room 103A	W2	Flaking	8	N	N	0	Y - 18 SF Tables, Bulletin Boards	N	2 Locations; Additional Chipping
384	6260	1	1	114	Copying Room	Copy Room 103A	W3	Flaking	16	N	N	0	Y - 8 SF Contents	N	3 Locations; Additional Cracking; Damage Includes Radiator

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
385	6260	1	1	114	Copying Room	Copy Room 103A	W4	Cracking	2	N	N	0	Y - 26 SF Posters	N	
386	6260	1	1	120	Administrative Office	Counselor's Office	Ceiling	Inaccessible							
387	6260	1	1	120	Administrative Office	Counselor's Office	Floor	Inaccessible							
388	6260	1	1	120	Administrative Office	Counselor's Office	W1	Inaccessible							
389	6260	1	1	120	Administrative Office	Counselor's Office	W2	Inaccessible							
390	6260	1	1	120	Administrative Office	Counselor's Office	W3	Inaccessible							
391	6260	1	1	120	Administrative Office	Counselor's Office	W4	Inaccessible							
392	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Ceiling	Inaccessible							
393	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Floor	Inaccessible							
394	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W1	Inaccessible							
395	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W2	Inaccessible							
396	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W3	Inaccessible							
397	6260	1	1	120A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W4	Inaccessible							
398	6260	1	1	H1B	Circulation (Hallway)	Entrance Vestibule behind Auditorium	Ceiling	Flaking	4	N	N	0	N	N	
399	6260	1	1	H1B	Circulation (Hallway)	Entrance Vestibule behind Auditorium	W1	Flaking	2	N	N	0	N	N	
400	6260	1	1	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 108	Floor	Debris Present	0	N	Y - Beneath Window Sills	12	N	N	
401	6260	1	1	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 108	W2	Flaking	72	N	Y - On Window Sill	8	N	N	Flaking @ Window Bars; Flaking Includes Metal Pipe
402	6260	1	1	S6	Stairs, Fire Tower	Fire Tower adjacent to Classroom 108	W3	Flaking	40	N	Y - On Window Sill	4	N	N	Flaking @ Window Bars; Flaking Includes Metal Pipe
403	6260	1	1	113C	Storage	Hallway Closet adjacent to Main Office	Ceiling	Flaking	2	N	N	0	N	Y - 2 SF	Additional Cracking, Holes
404	6260	1	1	113C	Storage	Hallway Closet adjacent to Main Office	W2	Flaking	2	N	N	0	N	N	
405	6260	1	1	113C	Storage	Hallway Closet adjacent to Main Office	W3	Partially Inaccessible		N	N	0	Y - 16 SF Contents	N	
406	6260	1	1	113C	Storage	Hallway Closet adjacent to Main Office	W4	Partially Inaccessible		N	N	0	Y - 8 SF Contents	N	
407	6260	1	1	H1A	Circulation (Hallway)	Hallway outside Auditorium	Ceiling	Flaking	1100	N	N	0	N	N	Additional Cracking; Damage on Most of Ceiling

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
408	6260	1	1	H1A	Circulation (Hallway)	Hallway outside Auditorium	W2	Flaking	36	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
409	6260	1	1	H1A	Circulation (Hallway)	Hallway outside Auditorium	W3	Chipping	2	N	N	0	N	N	
410	6260	1	1	H1A	Circulation (Hallway)	Hallway outside Auditorium	W4	Cracking	24	N	N	0	N	N	3 Locations; Additional Chipping
411	6260	1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 101-102	Ceiling	Flaking	20	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence, Cracking
412	6260	1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 101-102	W2	Flaking	360	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
413	6260	1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 101-102	W3	Cracking	26	N	N	0	N	N	
414	6260	1	1	H11	Circulation (Hallway)	Hallway outside Classrooms 101-102	W4	Cracking	60	N	N	0	N	N	3 Locations
415	6260	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 103-106	W1	Flaking	80	N	N	0	Y - 40 SF Posters	N	Additional Cracking, Chipping
416	6260	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 103-106	W2	Flaking	1	N	N	0	N	N	
417	6260	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 103-106	W3	Cracking	10	N	N	0	N	N	2 Locations; Additional Chipping
418	6260	1	1	H12	Circulation (Hallway)	Hallway outside Classrooms 103-106	W4	Cracking	12	N	N	0	N	N	
419	6260	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 107-108	W2	Flaking	24	N	N	0	Y - 10 SF Posters	N	4 Locations; Additional Cracking, Chipping
420	6260	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 107-108	W3	Chipping	4	N	N	0	N	N	Chipping @ Door
421	6260	1	1	H13	Circulation (Hallway)	Hallway outside Classrooms 107-108	W4	Flaking	180	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
422	6260	3	1	122A	Circulation (Hallway)	Hallway to Library	Ceiling	Flaking	4	N	N	0	N	N	
423	6260	3	1	122	IMC (Library)	Library	W1	Chipping	6	N	N	0	Y - 45 SF Shelves, Contents	N	
424	6260	3	1	122	IMC (Library)	Library	W2	Flaking	12	N	N	0	Y - 75 SF Shelves, Contents	N	Additional Cracking
425	6260	3	1	122	IMC (Library)	Library	W3	Partially Inaccessible		N	N	0	Y - 200 SF Bookcases, Contents	N	
426	6260	3	1	122	IMC (Library)	Library	W4	Cracking	8	N	N	0	Y - 112 Bookcases, Contents	N	
427	6260	1	1	S7	Stairs	Main Entrance Stairwell	W1	Flaking	5	N	Y - 1 SF @ Baseboard	1	N	N	3 Locations; Additional Cracking, Chipping
428	6260	1	1	S7	Stairs	Main Entrance Stairwell	W2	Flaking	60	N	N	0	Y - 20 SF Posters	N	Additional Cracking
429	6260	1	1	S7	Stairs	Main Entrance Stairwell	W4	Flaking	60	N	N	0	Y - 12 SF Posters	N	Additional Cracking
430	6260	1	1	113	Administrative Office	Main Office 105	W1	Chipping	8	N	N	0	Y - 16 SF Posters	N	
431	6260	1	1	113	Administrative Office	Main Office 105	W2	Partially Inaccessible		N	N	0	Y - 52 SF File Cabinets, Posters, Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
432	6260	1	1	113	Administrative Office	Main Office 105	W3	Partially Inaccessible		N	N	0	Y - 26 SF Desks	N	
433	6260	1	1	113	Administrative Office	Main Office 105	W4	Partially Inaccessible		N	N	0	Y - 88 SF Bulletin Boards, Posters, Contents	N	
434	6260	1	1	113A	Storage	Main Office Large Closet	W2	Partially Inaccessible		N	N	0	Y - 80 SF Shelves, Contents	N	
435	6260	1	1	113A	Storage	Main Office Large Closet	W3	Partially Inaccessible		N	N	0	Y - 40 SF Shelves, Contents	N	
436	6260	1	1	113A	Storage	Main Office Large Closet	W4	Cracking	4	N	N	0	Y - 80 SF Shelves, Contents	N	
437	6260	1	1	113B	Storage	Main Office Small Closet	W2	Partially Inaccessible		N	N	0	Y - 7 SF Shelves, Contents	N	
438	6260	1	1	113B	Storage	Main Office Small Closet	W3	Partially Inaccessible		N	N	0	Y - 14 SF Shelves, Contents	N	
439	6260	1	1	113B	Storage	Main Office Small Closet	W4	Partially Inaccessible		N	N	0	Y - 7 SF Shelves, Contents	N	
440	6260	1	1	118	Health Service Room	Nurse's Office	Ceiling	Flaking	2	N	N	0	N	N	2 Locations
441	6260	1	1	118	Health Service Room	Nurse's Office	W1	Cracking	2	N	N	0	N	N	
442	6260	1	1	118	Health Service Room	Nurse's Office	W2	Cracking	6	N	N	0	N	N	2 Locations; Additional Chipping
443	6260	1	1	118	Health Service Room	Nurse's Office	W3	Chipping	6	N	N	0	N	N	2 Locations; Chipping @ Wall & Radiator
444	6260	1	1	118A	Health Service Room	Nurse's Office Exam Room	Ceiling	Cracking	6	N	N	0	N	N	
445	6260	1	1	118A	Health Service Room	Nurse's Office Exam Room	W1	Cracking	2	N	N	0	N	N	2 Locations
446	6260	1	1	118A	Health Service Room	Nurse's Office Exam Room	W3	Chipping	2	N	N	0	N	N	Chipping @ Door Frame
447	6260	1	1	118A	Health Service Room	Nurse's Office Exam Room	W4	Holes	1	N	N	0	Y - 14 SF File Cabinets	N	
448	6260	1	1	112B	Administrative Office	Principal's Office	W1	Cracking	4	N	N	0	Y - 45 SF Boxes, Contents	N	
449	6260	1	1	112B	Administrative Office	Principal's Office	W2	Flaking	1	N	N	0	Y - 28 SF Contents	N	
450	6260	1	1	112B	Administrative Office	Principal's Office	W3	Flaking	24	N	Y - On Window Sill	2	Y - 8 SF Posters, Contents	N	2 Locations; Flaking on Wall & Radiator
451	6260	1	1	112B	Administrative Office	Principal's Office	W4	Cracking	2	N	N	0	Y - 48 SF Posters, Contents	N	
452	6260	1	1	119	Administrative Office	School Psychologist Office adjacent to Nurse's Office	Ceiling	Cracking	4	N	N	0	N	N	
453	6260	1	1	119	Administrative Office	School Psychologist Office adjacent to Nurse's Office	W3	Cracking	2	N	N	0	N	N	
454	6260	1	1	121A	Stage	Stage	Ceiling	Significant Moisture Damage	6	Y	N	0	N	N	Water Stains @ Pipe
455	6260	1	1	121A	Stage	Stage	W1	Flaking	6	N	N	0	N	Y - 1 SF	2 Locations; Additional Cracking

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
456	6260	1	1	121A	Stage	Stage	W3	Flaking	18	N	N	0	Y - 200 SF File Cabinets, Cabinets, Contents	N	3 Locations; Additional Chipping
457	6260	1	1	121A	Stage	Stage	W4	Flaking	4	N	N	0	N	N	2 Locations; Additional Cracking
458	6260	1	1	S5	Stairs	Stairwell A	Ceiling	Flaking	42	N	N	0	N	N	
459	6260	1	1	S5	Stairs	Stairwell A	W2	Cracking	8	N	N	0	N	N	
460	6260	1	1	S5	Stairs	Stairwell A	W3	Flaking	20	N	N	0	N	N	2 Locations; Additional Cracking
461	6260	1	1	S5	Stairs	Stairwell A	W4	Cracking	10	N	N	0	N	N	
462	6260	1	1	S1	Stairs	Stairwell across from Classroom 112	Ceiling	Cracking	16	N	N	0	N	N	
463	6260	1	1	S1	Stairs	Stairwell across from Classroom 112	W2	Cracking	4	N	N	0	N	N	
464	6260	1	1	S1	Stairs	Stairwell across from Classroom 112	W4	Cracking	6	N	N	0	N	N	
465	6260	1	1	S2	Stairs	Stairwell adjacent to Nurse's Office	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking, Chipping
466	6260	1	1	S2	Stairs	Stairwell adjacent to Nurse's Office	Floor	Flaking	4	N	N	0	N	N	
467	6260	1	1	S2	Stairs	Stairwell adjacent to Nurse's Office	W1	Flaking	2	N	N	0	N	N	
468	6260	1	1	S2	Stairs	Stairwell adjacent to Nurse's Office	W4	Flaking	8	N	N	0	N	N	Additional Chipping
469	6260	1	1	S4	Stairs	Stairwell B	Ceiling	Flaking	8	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
470	6260	1	1	S4	Stairs	Stairwell B	Floor	Chipping	4	N	N	0	N	N	
471	6260	1	1	S4	Stairs	Stairwell B	W2	Cracking	20	N	N	0	N	N	
472	6260	1	1	S4	Stairs	Stairwell B	W3	Flaking	26	N	N	0	N	N	Additional Cracking, Holes; Damage Includes Walls & Door
473	6260	1	1	S4	Stairs	Stairwell B	W4	Cracking	12	N	N	0	N	N	
474	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	Ceiling	Flaking	8	N	N	0	N	N	2 Locations
475	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	Center Banister	Flaking	12	N	N	0	N	N	Additional Chipping
476	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	W1	Flaking	90	N	N	0	N	N	
477	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	W2	Flaking	80	N	N	0	N	N	
478	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	W3	Flaking	120	N	N	0	N	N	2 Locations
479	6260	1	1	S3	Stairs	Stairwell next to Classroom 101	W4	Flaking	64	N	N	0	N	N	
480	6260	1	1	S24	Stairs	Stairwell next to Stage	Ceiling	Flaking	4	N	N	0	N	N	2 Locations
481	6260	1	1	150	Storage	Storage Room behind Stage	Ceiling	Inaccessible							
482	6260	1	1	150	Storage	Storage Room behind Stage	Floor	Inaccessible							
483	6260	1	1	150	Storage	Storage Room behind Stage	W1	Inaccessible							
484	6260	1	1	150	Storage	Storage Room behind Stage	W2	Inaccessible							

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
485	6260	1	1	150	Storage	Storage Room behind Stage	W3	Inaccessible							
486	6260	1	1	150	Storage	Storage Room behind Stage	W4	Inaccessible							
487	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Inaccessible							
488	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Inaccessible							
489	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Inaccessible							
490	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Inaccessible							
491	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Inaccessible							
492	6260	1	0	003	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Inaccessible							
493	6260	1	0	022	Cafeteria (Dining Area)	Cafeteria	W1	Flaking	24	N	N	0	N	N	4 Locations; Additional Cracking
494	6260	1	0	022	Cafeteria (Dining Area)	Cafeteria	W2	Flaking	22	N	N	0	N	N	5 Locations; Flaking Includes Walls & Radiators
495	6260	1	0	022	Cafeteria (Dining Area)	Cafeteria	W3	Flaking	11	N	N	0	N	N	2 Locations; Additional Cracking
496	6260	1	0	022	Cafeteria (Dining Area)	Cafeteria	W4	Flaking	24	N	N	0	N	N	3 Locations; Additional Cracking, Chipping; Damage Includes Walls & Radiators
497	6260	1	0	027	Storage	Cafeteria School Supply Room	Ceiling	Inaccessible							
498	6260	1	0	027	Storage	Cafeteria School Supply Room	Floor	Inaccessible							
499	6260	1	0	027	Storage	Cafeteria School Supply Room	W1	Inaccessible							
500	6260	1	0	027	Storage	Cafeteria School Supply Room	W2	Inaccessible							
501	6260	1	0	027	Storage	Cafeteria School Supply Room	W3	Inaccessible							
502	6260	1	0	027	Storage	Cafeteria School Supply Room	W4	Inaccessible							
503	6260	1	0	004	Primary	Former Art Room	W1	Flaking	12	N	N	0	Y - 28 SF Posters	N	3 Locations; Additional Cracking
504	6260	1	0	004	Primary	Former Art Room	W2	Flaking	30	N	N	0	Y - 36 SF Posters	N	Additional Cracking; Damage Includes ACPI
505	6260	1	0	004	Primary	Former Art Room	W3	Flaking	28	N	N	0	Y - 32 SF Posters	N	4 Locations; Flaking Includes ACPI
506	6260	1	0	004	Primary	Former Art Room	W4	Flaking	28	Y	N	0	Y - 28 SF Posters	Y - 4	Additional Efflorescence
507	6260	1	0	005	Storage	Former Art Room Back Closet	Ceiling	Flaking	72	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
508	6260	1	0	005	Storage	Former Art Room Back Closet	Floor	Partially Inaccessible		N	Y - Approx. Entire Floor & Contents	72	Y - 144 SF Contents	N	Room Partially Inaccessible; Damage Viewed from Entrance

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
509	6260	1	0	005	Storage	Former Art Room Back Closet	W1	Flaking	60	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
510	6260	1	0	005	Storage	Former Art Room Back Closet	W2	Flaking	100	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
511	6260	1	0	005	Storage	Former Art Room Back Closet	W3	Flaking	60	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
512	6260	1	0	005	Storage	Former Art Room Back Closet	W4	Flaking	100	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
513	6260	1	0	006	Storage	Former Art Room Large Storage Room	Ceiling	Flaking	144	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
514	6260	1	0	006	Storage	Former Art Room Large Storage Room	Floor	Partially Inaccessible		N	Y - Approx. Entire Floor & Contents	144	Y - 144 SF Contents	N	Room Partially Inaccessible; Damage Viewed from Entrance
515	6260	1	0	006	Storage	Former Art Room Large Storage Room	W1	Flaking	120	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
516	6260	1	0	006	Storage	Former Art Room Large Storage Room	W2	Flaking	120	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
517	6260	1	0	006	Storage	Former Art Room Large Storage Room	W3	Flaking	120	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
518	6260	1	0	006	Storage	Former Art Room Large Storage Room	W4	Flaking	120	Y	N	0	N	Y	Room Partially Inaccessible; Damage Viewed from Entrance
519	6260	1	0	004A	Storage	Former Art Room Small Front Closet	W1	Partially Inaccessible		N	N	0	Y - 60 SF Shelves, Contents	N	
520	6260	1	0	004A	Storage	Former Art Room Small Front Closet	W2	Partially Inaccessible		N	N	0	Y - 30 SF Shelves, Contents	N	
521	6260	1	0	004A	Storage	Former Art Room Small Front Closet	W3	Partially Inaccessible		N	N	0	Y - 70 SF Shelves, Contents	N	
522	6260	1	0	004A	Storage	Former Art Room Small Front Closet	W4	Partially Inaccessible		N	N	0	Y - 30 SF Shelves, Contents	N	
523	6260	1	0	312	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Efflorescence	4	Y	N	0	N	Y - 4 SF	
524	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	Ceiling	Inaccessible							
525	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	Floor	Inaccessible							
526	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	W1	Inaccessible							
527	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	W2	Inaccessible							
528	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	W3	Inaccessible							
529	6260	1	0	001A	Storage	Girl's Side Storage Room outside Gym	W4	Inaccessible							
530	6260	1	0	011A	Gymnasium - Intermediate Middle	Gym	Ceiling	Flaking	36	N	N	0	N	N	11 Locations; Additional Cracking
531	6260	1	0	011A	Gymnasium - Intermediate Middle	Gym	W2	Flaking	5	N	N	0	N	N	3 Locations
532	6260	1	0	011A	Gymnasium - Intermediate Middle	Gym	W3	Flaking	6	N	N	0	N	N	3 Locations; Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
533	6260	1	0	011A	Gymnasium - Intermediate Middle	Gym	W4	Chipping	2	N	N	0	N	N	2 Locations
534	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	Ceiling	Flaking	100	N	N	N	N	N	
535	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	Floor	Partially Inaccessible		N	N	N	Y - 720 SF Contents	N	
536	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	W1	Flaking	60	N	N	N	Y - 360 SF Contents	N	
537	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	W2	Partially Inaccessible		N	N	N	Y - 80 SF Contents	N	
538	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	W3	Flaking	60	N	N	N	Y - 360 SF Contents	N	
539	6260	1	0	012	Storage	Gym Large Storage Room on Boy's Restroom Side	W4	Flaking	240	Y	N	N	Y - 60 SF Contents	Y - 240 SF	Additional Efflorescence
540	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	Ceiling	Flaking	100	N	N	N	N	N	
541	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	Floor	Partially Inaccessible		N	N	N	Y - 720 SF Contents	N	
542	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	W1	Flaking	60	N	N	N	Y - 360 SF Contents	N	
543	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	W2	Partially Inaccessible		N	N	N	Y - 80 SF Contents	N	
544	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	W3	Flaking	60	N	N	N	Y - 360 SF Contents	N	
545	6260	1	0	014	Storage	Gym Large Storage Room on Girl's Restroom Side	W4	Flaking	240	Y	N	N	Y - 60 SF Contents	Y - 240 SF	Additional Efflorescence
546	6260	1	0	011	Administrative Office	Gym Office	Ceiling	Inaccessible							
547	6260	1	0	011	Administrative Office	Gym Office	Floor	Inaccessible							
548	6260	1	0	011	Administrative Office	Gym Office	W1	Inaccessible							
549	6260	1	0	011	Administrative Office	Gym Office	W2	Inaccessible							
550	6260	1	0	011	Administrative Office	Gym Office	W3	Inaccessible							
551	6260	1	0	011	Administrative Office	Gym Office	W4	Inaccessible							

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
552	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	Ceiling	Flaking	120	Y	N	0	N	Y - 6 SF	Additional Efflorescence
553	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	Floor	Debris Present	0	N	Y - Throughout	20	Y - 20 SF Contents	N	
554	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	W1	Chipping	20	N	N	0	N	N	
555	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	W2	Flaking	200	N	N	0	Y - 40 SF Contents	N	Flaking Includes Wall & Metal Pipe
556	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	W3	Partially Inaccessible		N	N	0	Y - 120 SF Contents	N	
557	6260	1	0	009	Storage	Gym Small Storage Room Closest to Building Engineer's Office	W4	Chipping	40	N	N	0	N	N	
558	6260	1	0	H06	Circulation (Hallway)	Hallway behind Kitchen	W1	Chipping	2	N	N	0	N	N	
559	6260	1	0	H06	Circulation (Hallway)	Hallway behind Kitchen	W3	Partially Inaccessible		N	N	0	Y - 42 SF Lockers, Contents	N	
560	6260	1	0	H01A	Circulation (Hallway)	Hallway from Cafeteria to Element 1	Ceiling	Flaking	30	N	N	0	N	N	7 Locations; Flaking Includes Ceiling & Metal Pipes
561	6260	1	0	H01A	Circulation (Hallway)	Hallway from Cafeteria to Element 1	W1	Flaking	4	N	N	0	N	N	Flaking @ Radiator
562	6260	1	0	H01A	Circulation (Hallway)	Hallway from Cafeteria to Element 1	W2	Chipping	3	N	N	0	N	N	Chipping @ Door
563	6260	1	0	H01A	Circulation (Hallway)	Hallway from Cafeteria to Element 1	W4	Flaking	3	N	N	0	N	N	Additional Cracking
564	6260	1	0	H07	Circulation (Hallway)	Hallway outside Building Engineer's Office	Ceiling	Flaking	18	N	N	N	N	N	Additional Cracking
565	6260	1	0	H07	Circulation (Hallway)	Hallway outside Building Engineer's Office	W1	Flaking	6	N	N	N	N	N	Additional Cracking, Chipping
566	6260	1	0	H07	Circulation (Hallway)	Hallway outside Building Engineer's Office	W2	Cracking	6	N	N	N	N	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
567	6260	1	0	H07	Circulation (Hallway)	Hallway outside Building Engineer's Office	W3	Flaking	4	N	N	N	N	N	Additional Cracking
568	6260	1	0	H03	Circulation (Hallway)	Hallway outside Girl's Restroom	Ceiling	Flaking	180	N	N	0	Y - 270 SF Ductwork	N	
569	6260	1	0	H03	Circulation (Hallway)	Hallway outside Girl's Restroom	W2	Flaking	90	N	N	0	N	N	Additional Cracking; Damage Includes ACPI
570	6260	1	0	H03	Circulation (Hallway)	Hallway outside Girl's Restroom	W4	Flaking	24	N	N	0	N	N	Flaking @ Radiator
571	6260	1	0	017	Administrative Office	Home and School Office	Ceiling	Inaccessible							
572	6260	1	0	017	Administrative Office	Home and School Office	Floor	Inaccessible							
573	6260	1	0	017	Administrative Office	Home and School Office	W1	Inaccessible							
574	6260	1	0	017	Administrative Office	Home and School Office	W2	Inaccessible							
575	6260	1	0	017	Administrative Office	Home and School Office	W3	Inaccessible							
576	6260	1	0	017	Administrative Office	Home and School Office	W4	Inaccessible							
577	6260	1	0	026	Cafeteria (Dining Area)	Kitchen	Ceiling	Flaking	140	N	N	0	N	N	5 Locations; Additional Cracking
578	6260	1	0	026	Cafeteria (Dining Area)	Kitchen	Floor	Chipping	630	N	N	0	N	N	Entire Floor
579	6260	1	0	026	Cafeteria (Dining Area)	Kitchen	W2	Chipping	2	N	N	0	N	N	2 Locations
580	6260	1	0	026	Cafeteria (Dining Area)	Kitchen	W3	Cracking	8	N	N	0	Y - 78 SF Kitchen Equipment	N	3 Locations; Additional Chipping
581	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	Ceiling	Inaccessible							
582	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	Floor	Inaccessible							
583	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	W1	Inaccessible							
584	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	W2	Inaccessible							
585	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	W3	Inaccessible							
586	6260	1	0	025	Kitchen and Dry Storage Area	Kitchen Dry Storage Room	W4	Inaccessible							
587	6260	1	0	029	Restrooms, Staff - Male/Female	Kitchen Office Restroom	Ceiling	Flaking	4	N	N	0	N	N	2 Locations
588	6260	1	0	028	Storage	Kitchen Office Storage Closet	W2	Partially Inaccessible		N	N	0	Y - 21 SF Shelves, Contents	N	
589	6260	1	0	028	Storage	Kitchen Office Storage Closet	W3	Cracking	18	N	N	0	Y - 18 SF Shelves, Contents	N	
590	6260	1	0	028	Storage	Kitchen Office Storage Closet	W4	Partially Inaccessible		N	N	0	Y - 21 SF Shelves, Contents	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
591	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	Ceiling	Flaking	64	N	N	0	N	N	
592	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	Floor	Debris Present	0	N	Y - Throughout	16	N	N	
593	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	W1	Flaking	80	N	N	0	N	N	
594	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	W2	Flaking	80	N	N	0	Y - 42 SF Selves	N	
595	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	W3	Flaking	80	N	N	0	Y - 24 SF Contents	N	
596	6260	1	0	019A	Storage	Left Closet adjacent to Boy's Restroom	W4	Flaking	80	N	N	0	Y - 30 SF Contents	N	
597	6260	1	0	018	Primary	Music Room 018	W1	Flaking	26	N	N	0	N	N	
598	6260	1	0	018	Primary	Music Room 018	W2	Flaking	42	N	N	0	N	N	Additional Cracking
599	6260	1	0	018	Primary	Music Room 018	W3	Flaking	16	N	N	0	N	N	Flaking @ Radiator & Wall
600	6260	1	0	018	Primary	Music Room 018	W4	Flaking	10	N	N	0	Y - 96 SF Desks	N	2 Locations; Additional Cracking
601	6260	1	0	016	Primary	Physical Therapy Room	Ceiling	Flaking	20	N	N	0	N	Y - 4 SF	2 Locations; Additional Cracking
602	6260	1	0	016	Primary	Physical Therapy Room	Floor	Debris Present	0	N	Y - Under Windows 1-3	2	N	N	
603	6260	1	0	016	Primary	Physical Therapy Room	W3	Flaking	24	N	N	0	N	Y - 3 SF	Additional Efflorescence; Damage @ Windows 1-3
604	6260	1	0	016A	Storage	Physical Therapy Room Closet	Ceiling	Inaccessible							
605	6260	1	0	016A	Storage	Physical Therapy Room Closet	Floor	Inaccessible							
606	6260	1	0	016A	Storage	Physical Therapy Room Closet	W1	Inaccessible							
607	6260	1	0	016A	Storage	Physical Therapy Room Closet	W2	Inaccessible							
608	6260	1	0	016A	Storage	Physical Therapy Room Closet	W3	Inaccessible							
609	6260	1	0	016A	Storage	Physical Therapy Room Closet	W4	Inaccessible							
610	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	Ceiling	Inaccessible							
611	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	Floor	Inaccessible							
612	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	W1	Inaccessible							
613	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	W2	Inaccessible							
614	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	W3	Inaccessible							

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
615	6260	1	0	019B	Storage	Right Closet adjacent to Boy's Restroom	W4	Inaccessible							
616	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	Ceiling	Inaccessible							
617	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	Floor	Inaccessible							
618	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	W1	Inaccessible							
619	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	W2	Inaccessible							
620	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	W3	Inaccessible							
621	6260	1	0	001	Restrooms, Staff - Male/Female	Staff Restroom adjacent to Boy's Restroom	W4	Inaccessible							
622	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	Ceiling	Inaccessible							
623	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	Floor	Inaccessible							
624	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	W1	Inaccessible							
625	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	W2	Inaccessible							
626	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	W3	Inaccessible							
627	6260	1	0	001D	Storage	Staff Restroom adjacent to Boy's Restroom Closet	W4	Inaccessible							
628	6260	1	0	S6	Stairs	Stairs to Exterior Entrance near Boy' Restroom	Ceiling	Flaking	12	N	N	0	N	N	
629	6260	1	0	S6	Stairs	Stairs to Exterior Entrance near Boy' Restroom	W1	Flaking	8	N	N	0	N	N	
630	6260	1	0	S6	Stairs	Stairs to Exterior Entrance near Boy' Restroom	W2	Flaking	4	N	N	0	N	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
631	6260	1	0	S6	Stairs	Stairs to Exterior Entrance near Boy' Restroom	W3	Flaking	10	N	N	0	N	N	
632	6260	1	0	S6	Stairs	Stairs to Exterior Entrance near Boy' Restroom	W4	Flaking	6	N	N	0	N	N	
633	6260	1	0	S5	Stairs	Stairwell A	Ceiling	Flaking	10	N	N	0	N	N	Additional Chipping
634	6260	1	0	S5	Stairs	Stairwell A	Floor	Chipping	4	N	Y - Under Window	1	N	N	
635	6260	1	0	S5	Stairs	Stairwell A	W1	Cracking	2	N	N	0	N	N	
636	6260	1	0	S5	Stairs	Stairwell A	W3	Flaking	5	Y	Y - @ Window Sill	1	N	Y - 2 SF	Additional Efflorescence, Cracking
637	6260	1	0	S5	Stairs	Stairwell A	W4	Flaking	8	N	N	0	N	N	Additional Cracking
638	6260	1	0	S2	Stairs	Stairwell adjacent to Home and School Office	Ceiling	Flaking	2	N	N	0	N	N	Flaking under Staircase
639	6260	1	0	S2	Stairs	Stairwell adjacent to Home and School Office	Center Banister	Flaking	3	N	N	0	N	N	
640	6260	1	0	S2	Stairs	Stairwell adjacent to Home and School Office	Floor	Cracking	3	N	N	0	N	N	Additional Chipping
641	6260	1	0	S2	Stairs	Stairwell adjacent to Home and School Office	W1	Flaking	22	Y	N	0	N	N	Additional Efflorescence, Spalling, Cracking; Cinder Block Wall
642	6260	1	0	S4	Stairs	Stairwell B	W3	Flaking	2	N	N	0	N	N	
643	6260	1	0	S1	Stairs	Stairwell behind Kitchen	Ceiling	Cracking	2	N	N	0	N	N	
644	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	Ceiling	Inaccessible							
645	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	Floor	Inaccessible							
646	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	W1	Inaccessible							
647	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	W2	Inaccessible							
648	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	W3	Inaccessible							
649	6260	1	0	003C	Storage	Storage Closet adjacent to Boy's Restroom	W4	Inaccessible							
650	6260	1	0	050B	Storage	Storage Closet adjacent to Girl's Restroom	Ceiling	Inaccessible							
651	6260	1	0	050B	Storage	Storage Closet adjacent to Girl's Restroom	Floor	Inaccessible							

