

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2510	1	3	301	Primary	Classroom 301	W3	Cracked paint at wall.	2	No			Poster	No	
2	2510	1	3	302	Primary	Classroom 302	W2	Flaking paint below bulletin board.	2	No				No	
3	2510	1	3	302	Primary	Classroom 302	W4	Flaking paint on window sills, on window aprons, and behind radiators	8	Yes				No	W3 needs work also
4	2510	1	3	303	Primary	Classroom 303	W1	Flaking paint at wall by entrance and below bulletin board.	2	No			Posters	No	
5	2510	1	3	303	Primary	Classroom 303	W3	Flaking paint and damaged plaster at Window 1	2	No				Yes	
6	2510	1	3	304	Primary	Classroom 304	W1	Flaking paint at wall by entrance	1	No				No	
7	2510	1	3	306	Primary	Classroom 306	W1	Flaking paint at wall by entrance.	1	No				No	
8	2510	1	3	307	Primary	Classroom 307	Ceiling	Flaking paint at ceiling above window 3	5	Yes	Window sill	2		Yes	
9	2510	1	3	307	Primary	Classroom 307	W3	Flaking paint at column by window 5	1	No				No	
10	2510	1	3	308	Primary	Classroom 308	W2	Flaking paint at wall by teachers desk	1	No				No	
11	2510	1	3	308	Primary	Classroom 308	W3	Flaking paint at window 3 window sill and below window	2	Yes				No	W1 and W4 needs work also
12	2510	1	3	309	Administrative Office	IMC Office	W1	Damaged plaster by entrance door	1	No				Yes	
13	2510	1	3	309	Administrative Office	IMC Office	W3	Paint/Plaster debris on window sill.	1	No	Window sill.	1		No	
14	2510	1	3	310	IMC (Library)	IMC/Library	W3	Paint/Plaster debris on window sills. Flaking paint behind radiators.	30	Yes				No	
15	2510	1	3	301A	Storage	Storage Closet next to Classroom 301	Ceiling	Flaking paint at ceiling	1	No				No	W1, W2, W3 and W4 needs work also
16	2510	1	3	302B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 302	Ceiling	Flaking paint at ceiling/wall above window.	3	Yes				No	
17	2510	1	3	304B	Administrative Office	Room 304-A Counselor's Office	Ceiling	Flaking paint above windows.	5	Yes	Window sill	1		No	
18	2510	1	3	304B	Administrative Office	Room 304-A Counselor's Office	W3	Flaking paint to left and right of windows	1	No				No	
19	2510	1	3	304C	Storage	Room 304-A Storage Closet	W4	Paint debris on floor below shelf.	1	No	Floor below shelf	1		No	
20	2510	1	3	305A	Storage	Classroom 305 Coat Closet Area	W3	Flaking paint behind radiator below window.	4	No				No	
21	2510	1	3	306A	Storage	Classroom 306 Coat Closet Area	W2	Cracked paint at wall.	1	No				No	
22	2510	1	3	306A	Storage	Classroom 306 Coat Closet Area	W3	Cracked paint at wall.	1	No				No	
23	2510	1	3	308A	Storage	Classroom 308 Coat Closet Area	W2	Flaking paint at pipe and wall.	3	No				Yes	
24	2510	1	3	308A	Storage	Classroom 308 Coat Closet Area	W3	Flaking paint below window	3	Yes				No	
25	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	Ceiling	No Access							
26	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	Floor	No Access							
27	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	W1	No Access							

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
28	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	W2	No Access							
29	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	W3	No Access							
30	2510	1	3	309A	Storage	Storage between IMC/Library and IMC Office	W4	No Access							
31	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W1	Flaking paint at wall.	10	No				No	
32	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W2	Flaking paint at wall.	10	No				No	
33	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W3	Flaking paint at wall.	10	No				No	
34	2510	1	3	310A	Storage	IMC/Library Middle Storage Closet	W4	Flaking paint at wall.	10	No				No	
35	2510	1	3	310B	Storage	Storage Room in IMC/Library	Ceiling	No Access							
36	2510	1	3	310B	Storage	Storage Room in IMC/Library	Floor	No Access							
37	2510	1	3	310B	Storage	Storage Room in IMC/Library	W1	No Access							
38	2510	1	3	310B	Storage	Storage Room in IMC/Library	W2	No Access							
39	2510	1	3	310B	Storage	Storage Room in IMC/Library	W3	No Access							
40	2510	1	3	310B	Storage	Storage Room in IMC/Library	W4	No Access							
41	2510	1	3	H37	Circulation (Hallway)	Hallway from Classroom 308 to Fire Tower	W2	Flaking paint behind radiator	5	No				No	
42	2510	1	3	H37	Circulation (Hallway)	Hallway from Classroom 308 to Fire Tower	W4	Flaking paint at wall by 308	2	No				No	
43	2510	1	3	H38	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W1	Flaking paint outside room 305	4	No				No	
44	2510	1	3	H38	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W3	Flaking paint at pipe by stairwell S36 and on walls at columns and where radiator covers have been pulled away from the walls. Chipped paint at baseboards.	50	No				Yes	
45	2510	1	3	S310	Stairs	Fire Tower Stairs	Ceiling	Flaking paint at exterior ceiling.	30	Yes				Yes	
46	2510	1	3	S33	Stairs	Stairwell near Classroom 308	W1	Chipped paint at newel posts	2	No				No	Stairway Top to Bottom
47	2510	1	3	S33	Stairs	Stairwell near Classroom 308	W4	Chipped paint at doors.	10	No				No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
48	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W1	Chipped paint at newel posts.	2	No				No	Stairway Top to Bottom
49	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W2	Chipped paint at doors	10	No				No	
50	2510	1	3	S36	Stairs	Stairwell next to Classroom 301	W3	Spalling paint at roof drain at top landing.	10	Yes				Yes	
51	2510	1	2	201	Art - Elementary	Classroom 201 Art	W2	Flaking paint below window 2 behind radiator.	2	No			Table.	No	
52	2510	1	2	202	Primary	Classroom 202	W4	Spalling below window 2.	2	Yes			School supplies	No	
53	2510	1	2	203	Primary	Classroom 203	Ceiling	Flaking paint above window 5	2	Yes			School supplies	No	
54	2510	1	2	203	Primary	Classroom 203	W3	Flaking paint below window 2, behind radiator below window 3, and at Pipe by window 5.	8	Yes			School supplies	No	(1) DDC Needed for ACPI - Steel wrap
55	2510	1	2	204	Primary	Classroom 204	W1	Flaking paint at wall.	4	No				No	
56	2510	1	2	204	Primary	Classroom 204	W3	Flaking paint to right of, below, window 5	2	No				No	
57	2510	1	2	205	Primary	Classroom 205	W3	Flaking paint at column by window 5, below window 5 and below window 1	15	Yes				No	
58	2510	1	2	206	Primary	Classroom 206	Ceiling	Flaking paint above window 1.	4	Yes	Window sill	1		Yes	
59	2510	1	2	207	Primary	Classroom 207	W2	Flaking paint at column	4	No				No	
60	2510	1	2	208	Primary	Classroom 208	W1	Flaking paint below blackboard.	5	No				No	
61	2510	1	2	211	Primary	Classroom 211	Ceiling	Flaking paint and efflorescence above windows 2 & 6.	8	No	Window sills	2		Yes	Windows 1,2,3,5,6
62	2510	1	2	211	Primary	Classroom 211	W2	Flaking paint at wall by Closet.	2	No				No	
63	2510	1	2	211	Primary	Classroom 211	W3	Flaking paint at wall by window 3	2	No				No	
64	2510	1	2	201B	Storage	Classroom 201 Right Side Storage Closet	W3	Efflorescence on paint.	1	No			School supplies	No	
65	2510	1	2	202B	Storage	Classroom 202 Coat Closet Area	Ceiling	Flaking paint at ceiling	10	Yes				No	
66	2510	1	2	202B	Storage	Classroom 202 Coat Closet Area	W4	Flaking paint at wall	10	No				No	
67	2510	1	2	203A	Storage	Classroom 203 Coat Closet Area	W3	Flaking paint, worn off at window sill.	1	No				No	
68	2510	1	2	204A	Primary	Classroom 204-A	Ceiling	Flaking paint above window 3.	2	Yes				No	
69	2510	1	2	205A	Storage	Classroom 205 Coat Closet Area	W3	Flaking paint above window and behind radiator.	8	Yes.	Window sill.	1		Yes	
70	2510	1	2	206A	Storage	Classroom 206 Coat Closet Area	W2	Damaged plaster at wall.	7	No				Yes	
71	2510	1	2	207A	Storage	Classroom 207 Coat Closet Area	W1	Flaking paint at wall.	2	No			School supplies	No	
72	2510	1	2	209/210	Computer - Intermediate Middle	Classroom 209/210 Computer Lab	Ceiling	Flaking paint above windows 3 & 9	5	Yes	Window sill	1		Yes	
73	2510	1	2	209/210	Computer - Intermediate Middle	Classroom 209/210 Computer Lab	W1	Flaking paint at wall.	5	No				No	
74	2510	1	2	210B	General Administrative Space	Classroom 209/210 Computer Lab Office Space and Copy Room	Ceiling	Flaking paint above windows	2	Yes	Window sill	1		Yes	Window 4 and 5

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
75	2510	1	2	210C	Computer Area	Classroom 209/210 Computer Server Room on 210 Side of Room	W3	Flaking paint and damaged plaster.	25	No				Yes	Tight space
76	2510	1	2	211A	Storage	Classroom 211 Coat Closet Area	Ceiling	Flaking paint at ceiling	1	No				No	
77	2510	1	2	211A	Storage	Classroom 211 Coat Closet Area	W1	Flaking paint at wall.	1	No				No	
78	2510	1	2	H25	Circulation (Hallway)	Hallway from Classroom 208 to Fire Tower Stairs	Floor	Chipped paint and gouges in floor.	200	No				No	
79	2510	1	2	H25	Circulation (Hallway)	Hallway from Classroom 208 to Fire Tower Stairs	W2	Flaking paint behind radiator.	20	No				No	
80	2510	1	2	H26	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	Floor	Chipped paint and gouges in floor.	400	No				No	
81	2510	1	2	H26	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W3	Chipped paint at baseboards.	15	No				No	
82	2510	1	2	NP11	Stairs	Fire Tower Stairs Landing Area by Hallway	Ceiling	Flaking paint at ceiling	30	No				Yes	
83	2510	1	2	NP11	Stairs	Fire Tower Stairs Landing Area by Hallway	W1	Flaking paint at exterior doors.	1	No				No	
84	2510	1	2	NP11	Stairs	Fire Tower Stairs Landing Area by Hallway	W3	Flaking paint at exterior walls	10	No				No	
85	2510	1	2	S23	Stairs	Stairwell near Classroom 208	W1	Chipped paint at newel posts.	2	No				No	288 - 6 - 6
86	2510	1	2	S23	Stairs	Stairwell near Classroom 208	W2	Chipped paint at doors	10	No				No	
87	2510	1	2	S23	Stairs	Stairwell near Classroom 208	W4	Cracking paint at wall.	2	No				No	
88	2510	1	2	S26	Stairs	Stairwell next to Classroom 201	Floor	Peeling paint at floor.	2	No				No	288 - 6 - 6
89	2510	1	2	S26	Stairs	Stairwell next to Classroom 201	W1	Small areas of peeling paint at wall. Chipped paint at newel posts.	4	No				No	
90	2510	1	2	S26	Stairs	Stairwell next to Classroom 201	W2	Chipped paint at doors. Small areas of peeling paint at wall.	12	No				No	
91	2510	1	2	S26	Stairs	Stairwell next to Classroom 201	W3	Small areas of peeling paint at wall.	1	No				No	
92	2510	1	2	S26	Stairs	Stairwell next to Classroom 201	W4	Small areas of peeling paint at wall.	1	No				No	
93	2510	1	1	101	Primary	Classroom 101 Pre-School	W2	Flaking paint at wall (near 101E), on baseboard by window, at window sill, and on pipe by window.	15	No			Cubbies, desks, toys,	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
94	2510	1	1	101	Primary	Classroom 101 Pre-School	W3	Flaking paint at wall.	3	No				No	
95	2510	1	1	102	Primary	Classroom 102	W4	Flaking paint near ceiling to right of Window 4	2	No				No	
96	2510	1	1	103	Primary	Classroom 103	W3	Flaking paint at wall below window 5.	2	No			Bookshelf	No	
97	2510	1	1	106	Primary	Classroom 106	W2	Flaking paint at wall and at column.	80	No				Yes	
98	2510	1	1	107	Circulation (Hallway)	Hallway from Bilingual Support Office to Nurse's Office	W1	Flaking paint at wall above cabinet.	2	No			Cabinet	No	
99	2510	1	1	109	Primary	Classroom 109	W3	Flaking paint at wall adjacent to right side exit door.	1	No				No	
100	2510	1	1	110	Primary	Classroom 110	W2	Flaking paint at wall by closet.	1	No				No	
101	2510	1	1	110	Primary	Classroom 110	W3	Flaking paint at wall behind radiator cage.	60	No				No	
102	2510	1	1	101B	Administrative Office	Classroom 101 Front Office on Right	W4	Flaking paint adjacent to Window 2.	2	No				No	
103	2510	1	1	101E	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W2	Flaking paint on and behind radiator.	5	No				No	Steamfitter needed to remove Radiator
104	2510	1	1	102B	Storage	Classroom 102 Coat Closet Area	W3	Flaking, cracking paint at wall behind shelf.	10	No	Paint chips on top of shelf.	1	Shelf.	No	
105	2510	1	1	103A	Storage	Classroom 103 Coat Closet Area	W4	Flaking paint at wall.	10	No				No	
106	2510	1	1	104A	Storage	Classroom 104 Coat Closet Area	W2	Flaking paint at wall.	6	No				No	
107	2510	1	1	104A	Storage	Classroom 104 Coat Closet Area	W3	Flaking paint at wall.	6	No				No	
108	2510	1	1	104B	Administrative Office	Main Office	W2	Chipped paint at wall by front desk	1	No				No	
109	2510	1	1	104B	Administrative Office	Main Office	W3	Chipped paint at Window 3 window sill	2	No			Copy Machine	No	
110	2510	1	1	104B	Administrative Office	Main Office	W4	Spalling paint at wall to the right, immediately upon entering the Main Office	10	No				No	
111	2510	1	1	104C	Administrative Office	Principal's Office	W1	Flaking paint on wall below white board.	2	No				No	
112	2510	1	1	104C	Administrative Office	Principal's Office	W3	Flaking paint at wall.	1	No				No	
113	2510	1	1	104C	Administrative Office	Principal's Office	W4	Flaking paint at wall behind pipe and below window.	2	No				No	
114	2510	1	1	105A	Storage	Classroom 105 Rear Coat Closet Area	W2	Flaking paint on wall leading to classroom	10	No				No	Plaster will Open
115	2510	1	1	105A	Storage	Classroom 105 Rear Coat Closet Area	W3	Flaking paint above window	2	Yes	Plaster on window sill/floor.	1	School supplies	Yes	
116	2510	1	1	106A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 106	W2	Flaking paint above tile on wall.	2	No				No	Small crack
117	2510	1	1	106B	Storage	Classroom 106 Rear Coat Closet Area	W2	Flaking paint at wall.	3	No				No	
118	2510	1	1	106B	Storage	Classroom 106 Rear Coat Closet Area	W3	Flaking paint at wall.	6	No			School supplies	No	Behind Cabinets

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
119	2510	1	1	107A	General Administrative Space	Bilingual Support Office	W2	Flaking paint at wall between windows and behind radiator.	6	No				No	Remove Radiator covers
120	2510	1	1	107B	Administrative Office	STS Office next to Nurse's Office	W3	Flaking paint at wall by window.	2	No				No	At the Column
121	2510	1	1	107C	Administrative Office	Nurse's Office	W1	Flaking paint at door.	1	No				No	
122	2510	1	1	108A	Storage	Classroom 108	Ceiling	Flaking paint above windows 2, 3, &5	3	Yes			School Supplies	No	
123	2510	1	1	108A	Storage	Classroom 108	W3	Flaking paint at pipe	5	No				No	Knee wall
124	2510	1	1	109A	Student Restrooms - Male/Female (Classroom)	Classroom 109 Boy's and Girl's Restroom	W1	Flaking paint at pipe.	2	No	Floor.	1		No	Galvanize Pipe - Can be painted
125	2510	1	1	110A	Storage	Classroom 110 Coat Closet Area	W2	Flaking paint at pipe.	4	No			School supplies.	No	Galvanize Pipe - Can be painted
126	2510	1	1	H13	Circulation (Hallway)	Hallway from Rooms 107 A-B-C to Fire Tower Stairs	W2	Flaking paint behind radiator	2	No				Yes	
127	2510	1	1	H14	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W1	Flaking paint and delaminated plaster at wall adjacent to entrance foyer. Flaking paint outside Room 103.	10	No				Yes	
128	2510	1	1	H14	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W3	Flaking paint at wall between classrooms 108 and 109. Flaking paint at wall across from Room 104. Chipped paint at baseboards.	20	No				No	
129	2510	1	1	S110	Stairs	Fire Tower Stairs near Rooms 107 A-B-C	Ceiling	Flaking paint at ceiling of exterior vestibule.	30	Yes				Yes	
130	2510	1	1	S110	Stairs	Fire Tower Stairs near Rooms 107 A-B-C	W1	Chipped and flaking paint at newel posts and railings.	10	No				No	
131	2510	1	1	S110	Stairs	Fire Tower Stairs near Rooms 107 A-B-C	W2	Chipped paint at door	1	No				No	
132	2510	1	1	S110	Stairs	Fire Tower Stairs near Rooms 107 A-B-C	W4	Flaking paint at wall by door to schoolyard. Flaking paint at wall in exterior vestibule.	11	Yes				No	
133	2510	1	1	S112	Stairs	Main Entrance to School Building Stairs	W1	Flaking and chipping paint at push bar for front door and the door casing.	10	No				No	
134	2510	1	1	S13	Stairs	Stairwell near Rooms 107 A-B-C	W1	Chipped and flaking paint at newel posts and railings..Chipping paint at doors	18	No				No	288 - 6 - 6
135	2510	1	1	S13	Stairs	Stairwell near Rooms 107 A-B-C	W3	Flaking paint at pipe.	2	No				No	
136	2510	1	1	S16	Stairs	Stairwell next to Classroom 101	W1	Chipped paint at newel post and railings	14	No				No	288 - 6 - 6
137	2510	1	1	S16	Stairs	Stairwell next to Classroom 101	W2	Chipped paint at doors.	10	No				No	
138	2510	1	0	002	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Chipping paint at floor.	150	No				No	
139	2510	1	0	002	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at right side of room near where pipes wnter ceiling.	10	Yes				No	
140	2510	1	0	005	Music	Music Classroom	Ceiling	Flaking paint on ductwork.	3	No				No	
141	2510	1	0	005	Music	Music Classroom	W2	Flaking paint at baseboard	15	No				No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
142	2510	1	0	005	Music	Music Classroom	W3	Flaking paint at drain pipe near ceiling	1	Yes	Paint debris on floor below pipe.	1	Musical equipment.	No	
143	2510	1	0	006	Storage	Storage Room next to Gym Office	Ceiling	No Access	30						Plasterers needed (Falling out) - Bad
144	2510	1	0	006	Storage	Storage Room next to Gym Office	Floor	No Access	0						Concrete No Painting - No Action
145	2510	1	0	006	Storage	Storage Room next to Gym Office	W1	No Access	1						Flaking near Door entry
146	2510	1	0	006	Storage	Storage Room next to Gym Office	W2	No Access	0						No Action
147	2510	1	0	006	Storage	Storage Room next to Gym Office	W3	No Access	0						No Action
148	2510	1	0	006	Storage	Storage Room next to Gym Office	W4	No Access	6						
149	2510	1	0	007	Kitchen and Dry Storage Area	Kitchen	Ceiling	Flaking paint, efflorescence.	5	No				No	
150	2510	1	0	007	Kitchen and Dry Storage Area	Kitchen	W3	Flaking paint, efflorescence.	10	Yes				No	
151	2510	1	0	007	Kitchen and Dry Storage Area	Kitchen	W4	Flaking paint at Column in center of area.	10	No				No	
152	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	Ceiling	No Access	0						No Action
153	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	Floor	No Access	0						VCT Tiles - No Action
154	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	W1	No Access	8						Chipping Paint (Bronzetone)
155	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	W2	No Access	0						No Action
156	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	W3	No Access	8						
157	2510	1	0	008	Administrative Office	School Store between Kitchen and Building Engineer's Office	W4	No Access							No Action
158	2510	1	0	009	Gymnasium / Auditorium / Cafeteria	Gymnasium / Auditorium / Cafeteria	W2	Flaking paint at interior brick wall.	10	No				No	Various Locations
159	2510	1	0	009	Gymnasium / Auditorium / Cafeteria	Gymnasium / Auditorium / Cafeteria	W3	Flaking paint at "Effort" Radiator Cover.	3	No				No	On Radiator cover (DTM)
160	2510	1	0	015	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Damaged plaster - ceiling mounted radiator	30	No				Yes	All Soft Plaster - Plasterer needed, this will Open Up
161	2510	1	0	017	Administrative Office	Gym Teacher's Office and Storage	W1	Chipping paint at door to Office.	2	No				No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
162	2510	1	0	018	Storage	Storage Room across from Music Room	W3	Plaster debris on shelf near musical instruments	1	No	Plaster debris on shelf in corner of room	1	Musical Instruments	No	Unfounded - Could not locate
163	2510	1	0	005A	Administrative Office	Music Classroom Office	W4	Flaking paint at pipe in corner.	6	No				No	
164	2510	1	0	H01	Circulation (Hallway)	Hallway from Boy's Restroom to Outside Exit Door by Storage Rooms	Floor	Chipping, scraped paint on concrete flooring	300	No				No	
165	2510	1	0	H02	Circulation (Hallway)	Hallway from Music Classroom to Outside Exit Door	Floor	Chipped paint and gouges in floor.	40	No				No	
166	2510	1	0	S03	Stairs	Stairwell near Boy's Restroom	W1	Chipping paint at newel post of railing.	2	No				No	
167	2510	1	0	S03	Stairs	Stairwell near Boy's Restroom	W3	Flaking paint and efflorescence at wall by Storage NP-4	15	Yes				No	Wet wall - Root cause is the constant water infiltration
168	2510	1	0	S06	Stairs	Stairwell near Music Classroom	Floor	Flaking paint at stair riser near landing between 1st Floor and Basement	1	No				No	
169	2510	1	0	S06	Stairs	Stairwell near Music Classroom	W1	Chipped and flaking paint at newel posts and railings.	10	No				No	
170	2510	1	0	S06	Stairs	Stairwell near Music Classroom	W2	Chipped paint at doors.	10	No				No	
171	2510	1	0	S06	Stairs	Stairwell near Music Classroom	W4	Flaking paint at wall adjacent to Gym/Cafe.	10	No				No	
172	2510	1	2		Student Restrooms - Male (4-12)	Boy's Restroom	W4	Flaking paint above tile on wall.	2	No	No		No	No	
173	2510	1	3	H38	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W1	Cracking paint outside room 304	1	No	No		No	No	
174	2510	1	3	H38	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W3	Cracking paint across Room 305	3	No	No		No	No	
175	2510	1	3	H37	Circulation (Hallway)	Hallway from Classroom 308 to Fire Tower	W4	Cracking paint next to Fire Tower	2	No	-			No	
176	2510	1	1	H14	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W2	Flaking paint and delaminated plaster at wall adjacent to entrance foyer.	6	No				Yes	
177	2510	1	1	H14	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W3	Flaking paint at wall between classrooms 108 and 109 and radiator across classroom 105	8	No				No	
178	2510	1	1	H14	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W1	Flaking paint at wall next to classroom 102	1	No				No	
179	2510	1	3	S33	Stairs	Stairwell near Classroom 308	Ceiling	Cracking paint on W1,W2,W3,W4 and ceiling	20	No			No		

