Task ID	ULCS#	E l m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6300	1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Chipped paint at floor	200	N			Ν		
2	6300	1	3	330	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking paint at radiator cover	5	N			Ν		
3	6300	1	3	301	Primary	Classroom 301	Ceiling	Flaking paint at ceiling	100	Y			Ν	Posters, cabinets	
4	6300	1	3	301	Primary	Classroom 301	W3	Flaking paint around windows	50	Y	Floor, sill	20	Y	Posters, cabinets	
5	6300	1	3	301	Primary	Classroom 301	W4	Flaking paint at wall	10	N			N	Posters, cabinets	
6	6300	1	3	301A	Storage	Classroom 301 Closet	W1	Damaged plaster	10	N			Y		
7	6300	1	3	301A	Storage	Classroom 301 Closet	W2	Damaged plaster	10	N			Y		
8	6300	1	3	301A	Storage	Classroom 301 Closet	W3	Damaged plaster	10	N			Y		
9	6300	1	3	301A	Storage	Classroom 301 Closet	W4	Damaged plaster	10	N			Y		
10	6300	1	3	303	Primary	Classroom 303	W1	Flaking paint on door. Cracking paint to the right of the blackboard	22	N			Ν		
11	6300	1	3	303	Primary	Classroom 303	W2	Flaking paint at closet doors. Cracking paint by closet	10	N			Ν		
12	6300	1	3	303	Primary	Classroom 303	W3	Flaking paint around windows, at trim below windows, and by radiator	35	Y			Y		
13	6300	1	3	331A	Storage	Classroom 303 Closet	W1	Flaking paint at door and damaged plaster	40	N			Y		
14	6300	1	3	331A	Storage	Classroom 303 Closet	W2	Flaking paint at wall	1	N			N		
15	6300	1	3	331A	Storage	Classroom 303 Closet	W3	Damaged plaster	40	N			Y		
16	6300	1	3	304	Primary	Classroom 304	W1	Flaking paint at blackboard trim, at doors, and at baseboards	65	N			Ν		
17	6300	1	3	304	Primary	Classroom 304	W2	Flaking paint near closet and W1, and at baseboards	75	N			Ν		
18	6300	1	3	304	Primary	Classroom 304	W3	Flaking paint at wall and baseboards	35	N			N		
19	6300	1	3	304	Primary	Classroom 304	W4	Flaking paint at blackboard trim and baseboards	45	N			Ν		
20	6300	1	3	304A	Storage	Classroom 304 Closet	W1	Damaged plaster	30	N			N		
21	6300	1	3	304A	Storage	Classroom 304 Closet	W3	Damaged plaster at windows	5	N			N		
22	6300	1	3	305	Primary	Classroom 305	W3	Flaking paint at sides of windows, below window 3, and at riser by window 3.	5	N			N	Posters	
23	6300	1	3	305A	Primary	Classroom 305 Closet	Ceiling	Flaking paint at ceiling	2	N			N	Supplies, Cabinet, Bookshelf, Table	
24	6300	1	3	305A	Primary	Classroom 305 Closet	W1	Flaking paint at wall and door	15	N			N	Supplies, Cabinet, Bookshelf, Table	
25	6300	1	3	305A	Primary	Classroom 305 Closet	W2	Flaking paint at wall	50	N			Ν	Supplies, Cabinet, Bookshelf, Table	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
26	6300	1	3	305A	Primary	Classroom 305 Closet	W3	Flaking paint at wall	20	N			N	Supplies, Cabinet, Bookshelf, Table	
27	6300	1	3	305A	Primary	Classroom 305 Closet	W4	Flaking paint at wall and door	160	Ν			Ν	Supplies, Cabinet, Bookshelf, Table	
28	6300	1	3	307	Primary	Classroom 307	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill and floor	5	N		
29	6300	1	3	307	Primary	Classroom 307	W3	Flaking paint debris by radiator	5	N	Floor	5	N		
30	6300	1	3	307A	Storage	Classroom 307 Closet	Ceiling	Flaking paint	20	N			N	Books, desks, supplies, boxes	
31	6300	1	3	307A	Storage	Classroom 307 Closet	W1	Flaking paint	5	Ν			N	Books, desks, supplies, boxes	
32	6300	1	3	307A	Storage	Classroom 307 Closet	W2	Flaking paint	50	Ν			N	Books, desks, supplies, boxes	
33	6300	1	3	307A	Storage	Classroom 307 Closet	W3	Flaking paint	20	Ν			N	Books, desks, supplies, boxes	
34	6300	1	3	307A	Storage	Classroom 307 Closet	W4	Flaking paint	100	Ν			N	Books, desks, supplies, boxes	
35	6300	1	3	308	Primary	Classroom 308	W2	Flaking paint debris on bulletin board sill and floor	5	N	Bulletin board sill and floor	5	N		
36	6300	1	3	308	Primary	Classroom 308	W3	Flaking paint at window trims and debris by radiator	15	Y	Floor	5	Ν		
37	6300	1	3	308A	Storage	Classroom 308 Closet	W1	Flaking paint at door	5	N			N		
38	6300	1	3	308A	Storage	Classroom 308 Closet	W2	Flaking paint at baseboards	5	N			N		
39	6300	1	3	308A	Storage	Classroom 308 Closet	W3	Flaking paint at baseboards	5	N			N		
40	6300	1	3	308A	Storage	Classroom 308 Closet	W4	Flaking paint at baseboards	5	N			N		
41	6300	1	3	309	Primary	Classroom 309	W3	Flaking paint at radiator and debris below window 1	5	N	Floor, sill	5	Ν		
42	6300	1	3	309A	Storage	Classroom 309 Closet	Ceiling	Flaking paint	100	Ν			N	Many books, supplies, boxes	
43	6300	1	3	309A	Storage	Classroom 309 Closet	Floor	Flaking paint debris	50	Ν	Floor	50	N	Many books, supplies, boxes	
44	6300	1	3	309A	Storage	Classroom 309 Closet	W1	Flaking paint	5	Ν			Ν	Many books, supplies, boxes	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
45	6300	1	3	309A	Storage	Classroom 309 Closet	W2	Flaking paint	20	N			N	Many books, supplies, boxes	
46	6300	1	3	309A	Storage	Classroom 309 Closet	W3	Flaking paint	20	Ν			Ν	Many books, supplies, boxes	
47	6300	1	3	309A	Storage	Classroom 309 Closet	W4	Flaking paint	50	Ν			Ν	Many books, supplies, boxes	
48	6300	1	3	310	Primary	Classroom 310	W3	Flaking paint debris by radiator	2	N	Floor	2	N		
49	6300	1	3	310A	Storage	Classroom 310 Closet	W3	Flaking paint at pipe and radiator, damaged plaster	30	Ν			Y		
50	6300	1	3	311	Primary	Classroom 311	W3	Flaking paint debris by radiator	1	N	Floor	1	N		
51	6300	1	3	311A	Storage	Classroom 311 Closet	W1	Damaged plaster	5	N			Y		
52	6300	1	3	311A	Storage	Classroom 311 Closet	W3	Damaged plaster	5	N			Y		
53	6300	1	3	312	Primary	Classroom 312	W3	Flaking paint behind radiator	10	N			N		
54	6300	1	3	313	Primary	Classroom 313	Ceiling	Flaking paint	20	Y			N		
55	6300	1	3	313 313	Primary	Classroom 313 Classroom 313	W1 W2	Flaking paint	50 40	N N			N N	Posters Posters	
56 57	6300 6300	1	3	313	Primary Primary	Classroom 313	 W3	Flaking paint Flaking paint	100	N			N	Posters	
58	6300	1	3	313A	Storage	Classroom 313 Closet	Ceiling	Flaking paint	100	N			N	Many supplies	
59	6300	1	3	313A	Storage	Classroom 313 Closet	W1	Flaking paint	20	N				Many supplies	
	6300		3		-		W2		10						
60		1		313A	Storage	Classroom 313 Closet		Flaking paint		N				Many supplies	
61	6300	1	3	313A	Storage	Classroom 313 Closet	W3	Flaking paint	30	N			N	Many supplies	
62	6300	1	3	313A	Storage	Classroom 313 Closet	W4	Flaking paint	10	Ν			Ν	Many supplies	
63	6300	1	3	S31	Stairs, Fire Tower	Fire Tower near Classroom 302	Ceiling	Damaged plaster	40	Ν			Y		
64	6300	1	3	S36	Stairs, Fire Tower	Fire Tower near Classroom 312	Ceiling	Damaged plaster	20	Ν			Y		
65	6300	1	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at exhaust fan	5	Ν			N		
66	6300	1	3	331	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Flaking paint debris at pipe by W3	5	Ν	Floor	5	Ν		
67	6300	1	3	H320	Circulation (Hallway)	Hallway outside Classrooms 301 to 303	W3	Flaking paint behind radiator	20	N			N		
68	6300	1	3	H319	Circulation (Hallway)	Hallway outside Classrooms 311 to 313	W1	Flaking paint behind radiator	20	N			Ν		
69	6300	1	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W1	Flaking paint at door	15	Ν			Ν		
70	6300	1	3	H318	Circulation (Hallway)	Hallway to Fire Tower near Classroom 302	W2	Flaking paint at door	15	N			Ν		
71	6300	1	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W2	Flaking paint at door	15	Ν			Ν		
72	6300	1	3	H317	Circulation (Hallway)	Hallway to Fire Tower near Classroom 312	W3	Flaking paint at door	15	Ν			Ν		
73	6300	1	3	329	Administrative Office	Office 313A	W1	Damaged plaster	10	N			Y		
74	6300	1	3	329	Administrative Office	Office 313A	W3	Flaking paint	30	N			N		

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
75	6300	1	3	S34	Stairs	Stairwell near Classroom 311	W1	Flaking paint above door	3	Ν			N		
76	6300	1	3	S34	Stairs	Stairwell near Classroom 311	W2	Cracking paint	15	Ν			N		
77	6300	1	3	S34	Stairs	Stairwell near Classroom 311	W3	Flaking paint	40	Ν			N		
78	6300	1	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W2	Flaking paint at pipe	2	N			N		
79	6300	1	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W3	Flaking paint at sill	5	Ν			N		
80	6300	1	3	332A	Restrooms, Staff - Male/Female	Teacher' Lounge adjacent to Classroom 301 Restroom	W4	Flaking paint at wall in copy room by radiator	5	Ν	Floor	1	Ν		
81	6300	1	2	H214	Circulation (Hallway)	2nd Floor Hallway outside Auditorium	W2	Flaking paint behind radiator	20	N			N		
82	6300	1	2	217	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Flaking paint at pipes	10	N			N		
83	6300	1	2	203	Primary	Classroom 203	Ceiling	Flaking paint, damaged plaster near windows	15	Y			Y		
84	6300	1	2	203	Primary	Classroom 203	W1	Flaking paint above closet door. Plaster damage	10	N			Y		
85	6300	1	2	203	Primary	Classroom 203	W3	Flaking paint at window trim. Plaster damage	10	N			Y		
86	6300	1	2	203B	Storage	Classroom 203 Closet	Ceiling	Flaking paint	20	Ν			Ν	Bookshelves, many supplies	
87	6300	1	2	203B	Storage	Classroom 203 Closet	W1	Flaking paint	10	Ν			Ν	Bookshelves, many supplies	
88	6300	1	2	203B	Storage	Classroom 203 Closet	W2	Flaking paint	20	Ν			Ν	Bookshelves, many supplies	
89	6300	1	2	203B	Storage	Classroom 203 Closet	W3	Flaking paint	10	Ν			Ν	Bookshelves, many supplies	
90	6300	1	2	203B	Storage	Classroom 203 Closet	W4	Flaking paint	10	Ν			N	Bookshelves, many supplies	
91	6300	1	2	205	Primary	Classroom 205	W1	Flaking paint at wall and doors	20	Ν			N	Bookshelves, posters, supplies	
92	6300	1	2	205	Primary	Classroom 205	W2	Flaking paint below bulletin board, on closet doors, and baseboards	20	N			N	Bookshelves, posters, supplies	
93	6300	1	2	205	Primary	Classroom 205	W3	Flaking paint above windows	25	Y	Sill, Floor	3	Y	Bookshelves, posters, supplies	
94	6300	1	2	205B	Storage	Classroom 205 Closet	Ceiling	Damaged plaster	5	N			Y		
95	6300	1	2	205B	Storage	Classroom 205 Closet	W1	Flaking paint at pipe and wall	10	N			Y		

Task ID	ULCS#	E l e m e n t	F l o r 2	Space # (on Floor Plan) 205B	Space Type	On Site Room Name	Component W2	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no) N	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
96					Storage			Damaged plaster Flaking paint and pipe and radiator.							
97	6300	1	2	205B	Storage	Classroom 205 Closet	W3	Damaged plaster	30	Ν			Y		
98	6300	1	2	205B	Storage	Classroom 205 Closet	W4	Damaged plaster	5	N			Y	Deelehahuaa	
99	6300	1	2	206A	Storage	Classroom 206 Closet	W1	Flaking paint at wall	10	Ν			N	Bookshelves, supplies	
100	6300	1	2	206A	Storage	Classroom 206 Closet	W3	Flaking paint at wall	20	Ν			Ν	Bookshelves, supplies	
101	6300	1	2	206A	Storage	Classroom 206 Closet	W4	Flaking paint at wall	20	Ν			N	Bookshelves, supplies	
102	6300	1	2	207	Primary	Classroom 207	Ceiling	Flaking paint near windows	100	Y			N	Posters, bookshelves	
103	6300	1	2	207	Primary	Classroom 207	W1	Flaking paint by entrance, and above blackboard	5	Ν			Ν	Posters, bookshelves	
104	6300	1	2	207	Primary	Classroom 207	W2	Flaking paint on wall by computers	2	Ν			N	Posters, bookshelves	
105	6300	1	2	207	Primary	Classroom 207	W3	Flaking paint above and below windows	80	Y			N	Posters, bookshelves	
106	6300	1	2	207	Primary	Classroom 207	W4	Flaking paint at wall around bulletin board and on baseboard	20	N			N	Posters, bookshelves	
107 108	6300 6300	1	2	209 209	Primary Primary	Classroom 209 Classroom 209	W3 W4	Flaking paint behind pipe at window 4 Flaking paint at wall	2	Y N	Window 2 Sill	2	N N	Posters Posters	
109	6300	1	2	209B	Storage	Classroom 209 Closet	W1	Flaking paint at door	1	N			N	Bookshelves	
110	6300	1	2	209B	Storage	Classroom 209 Closet	W3	Flaking paint at walls and pipe	40	N			N	and supplies Bookshelves	
111	6300	1	2	210	Administrative Office	Counselor's Office 206A	W1	Flaking at wall and baseboards	25	N			Y	and supplies Posters	
112	6300	1	2	210	Administrative Office	Counselor's Office 206A	W2	Flaking at wall and baseboards	25	Ν			Y	Posters	
113	6300	1	2	210	Administrative Office	Counselor's Office 206A	W3	Flaking at wall and baseboards	35	Ν			Y	Posters	
114	6300	1	2	210	Administrative Office	Counselor's Office 206A	W4	Flaking at wall and baseboards	50	Ν			Y	Posters	
115	6300	1	2	S21	Stairs, Fire Tower	Fire Tower near Classroom 202	Ceiling	Damaged plaster	40	Ν			Y		
116	6300	1	2	220	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at pipe	3	Ν			N		
117	6300	1	2	H215	Circulation (Hallway)	Hallway outside Classrooms 201 to 203	W3	Flaking paint behind radiator	20	Ν			N		
118	6300	1	2	H213	Circulation (Hallway)	Hallway outside Classrooms 207 to 209	W1	Flaking paint behind radiator	20	Ν			N		
119	6300	1	2	H212	Circulation (Hallway)	Hallway to Fire Tower near Classroom 202	W1	Flaking paint at door	15	Ν			N		
120	6300	1	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W3	Flaking paint at door	15	Ν			N		
121	6300	1	2	H211	Circulation (Hallway)	Hallway to Fire Tower near Classroom 208	W4	Flaking paint at door	15	N Y			N	Desks	
122 123	6300 6300		2	201	IMC (Library) IMC (Library)	Library 201 Library 201	Ceiling W1	Flaking paint near windows Flaking paint at baseboards	30 20	Y N			N N	Desks	
123	6300	1	2	201	IMC (Library)	Library 201	W1 W2	Flaking paint at baseboards	20	N N	+		N	Desks	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
125	6300	1	2	201	IMC (Library)	Library 201	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills	15	N	Desks	
126	6300	1	2	201	IMC (Library)	Library 201	W4	Flaking paint at baseboards	20	N			N	Desks	
127	6300	1	2	202	IMC (Library)	Library 202	Ceiling	Flaking paint near windows	30	Y			N	Desks	
128	6300	1	2	202	IMC (Library)	Library 202	W1	Flaking paint at baseboards	20	N			N	Desks	
129	6300	1	2	202	IMC (Library)	Library 202	W2	Flaking paint at baseboards	20	N			N	Desks	
130	6300	1	2	202	IMC (Library)	Library 202	W3	Flaking paint debris on sills. Flaking paint at baseboards	35	Y	Window sills	15	Ν	Desks	
131	6300	1	2	202	IMC (Library)	Library 202	W4	Flaking paint at baseboards	20	N			N	Desks	
132	6300	1	2	204A	Administrative Office	Nurse's Office	W1	Flaking paint on pipe in bathroom	1	N			N		
133	6300	1	2	204A	Administrative Office	Nurse's Office	W3	Flaking paint debris on floor and on pipe.	5	Y	Floor	5	Ν		
134	6300	1	2	205A	Administrative Office	Office 205A	W1	Flaking paint at door	10	N			N		
135	6300	1	2	205A	Administrative Office	Office 205A	W3	Flaking paint at wall	5	N			N		
136	6300	1	2	205A	Administrative Office	Office 205A	W4	Flaking paint at wall	5	N			N		
137	6300	1	2	209A	Administrative Office	Office 209A	Ceiling	Flaking paint and plaster damage	50	N			Y		
138	6300	1	2	209A	Administrative Office	Office 209A	W1	Flaking paint and plaster damage	12	N			Y		
139	6300	1	2	209A	Administrative Office	Office 209A	W2	Flaking paint and plaster damage	30	N			Y		
140	6300	1	2	209A	Administrative Office	Office 209A	W3	Flaking paint and plaster damage	30	N			Y		
141	6300	1	2	209A	Administrative Office	Office 209A	W4	Flaking paint and plaster damage	30	N			Y		
142	6300	1	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W1	Flaking paint at wall	5	N			Ν		
143	6300	1	2	201C	Administrative Office	Office between Library 201 Closet and Speech Pathologist Office 201A (access from Speech Pathologist Office only)	W4	Flaking paint at wall	15	Ν			N		
144	6300	1	2	201A	Administrative Office	Speech Pathologist Office 201A	W1	Flaking paint at door.	5	N			Ν		
145	6300	1	2	201A	Administrative Office	Speech Pathologist Office 201A	W4	Flaking paint at baseboards	15	N			Ν		
146	6300	1	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	Ceiling	Flaking paint near windows	5	Y			N	Many supplies	
147	6300	1	2	201D	Restrooms, Staff - Male/Female	Speech Pathologist Office 201A Restroom	W2	Flaking paint debris on sill and floor.	3	Y	Floor, sill	3	Ν	Many supplies	
148			2	201E	Storage	Speech Pathologist Office 201A Storage Room	Ceiling	Flaking paint	50	Y			N	Many supplies	
149			2	201E	Storage	Speech Pathologist Office 201A Storage Room	Floor	Flaking paint debris	40	Y			Ν	Many supplies	
150			2	201E	Storage	Speech Pathologist Office 201A Storage Room	W1	Flaking paint	50	Y			Ν	Many supplies	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
151			2	201E	Storage	Speech Pathologist Office 201A Storage Room	W2	Flaking paint	50	Y			Ν	Many supplies	
152			2	201E	Storage	Speech Pathologist Office 201A Storage Room	W3	Flaking paint	50	Y			Ν	Many supplies	
153			2	201E	Storage	Speech Pathologist Office 201A Storage Room	W4	Flaking paint	50	Y			Ν	Many supplies	
154	6300	1	2	S24	Stairs	Stairwell near Classroom 207	W1	Flaking paint around door	10	Ν			Ν		
155	6300	1	2	S24	Stairs	Stairwell near Classroom 207	W3	Flaking paint behind pipe	10	Y			N		
156	6300	1	2	S24	Stairs	Stairwell near Classroom 207	W4	Flaking paint near ceiling	10	Ν			N		
157	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	Ceiling	No access							
158	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	Floor	No access							
159	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	W1	No access							
160	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	W2	No access							
161	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	W3	No access							
162	6300	1	2	220A	Storage	Storage Closet near Girl's Restroom	W4	No access							
163	6300	1	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	Ceiling	Flaking paint at ceiling	20	Ν			Ν		
164	6300	1	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W2	Flaking paint	2	Ν			Ν		
165	6300	1	2	204	Teacher Lounge/Dining	Teacher's Lounge 204	W3	Flaking paint below window	5	Ν			N	Bookshelves	
166	6300	1	2	204B	Restrooms, Staff - Male/Female	Teacher's Lounge 204 Restroom	W1	Flaking paint at door	5	Ν			N		
167	6300	1	1	102	Administrative Office	Assistant Principal's Office 102	Ceiling	Flaking paint at ceiling	50	Ν			Ν		
168	6300	1	1	102	Administrative Office	Assistant Principal's Office 102	W1	Flaking paint at wall and doors	30	Ν			Ν	Posters	
169	6300	1	1	102	Administrative Office	Assistant Principal's Office 102	W2	Flaking paint at wall	5	Ν			Ν	Posters	
170	6300	1	1	102	Administrative Office	Assistant Principal's Office 102	W3	Flaking paint around windows and behind radiator	40	Ν			N	Posters	
171	6300	1	1	102	Administrative Office	Assistant Principal's Office 102	W4	Flaking and chipping paint at wall.	20	Ν			Ν	Posters	
172	6300	1	1	112	Auditorium	Auditorium	W1	Flaking paint and damaged plaster	30	N			Y		
173	6300	1	1	112	Auditorium	Auditorium	W2	Flaking paint and damaged plaster	30	N			Y		
174	6300	1	1	112	Auditorium	Auditorium	W3	Flaking paint and damaged plaster	35	N			Y		
175	6300	1	1	112	Auditorium	Auditorium	W4	Damaged plaster	20	N			Y		
176	6300	1	1	112A	Auditorium	Auditorium Stage	Ceiling	Flaking paint at ceiling	20	N			N		
177	6300	1	1	112A	Auditorium	Auditorium Stage	W3	Flaking paint near ceiling	10	N			N		
178	6300	1	1	112A	Auditorium	Auditorium Stage	W4	Flaking paint	5	N			N		

Task ID	ULCS#	E l m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
179	6300	1	1	104A	Administrative Office	BET Office	Ceiling	Flaking paint at ceiling	20	N			N		
180	6300	1	1	104A	Administrative Office	BET Office	W1	Flaking paint on and near door.	6	N			N		
181	6300	1	1	104A	Administrative Office	BET Office	W2	Flaking paint at wall	10	N			N		
182	6300	1	1	104A	Administrative Office	BET Office	W3	Flaking paint at wall	5	Ν			N	Posters, desks	
183	6300	1	1	104A	Administrative Office	BET Office	W4	Flaking paint at wall	10	N			N		
184	6300	1	1	101A	Storage	Classroom 101 Closet	Ceiling	Flaking paint.	15	N			N		
185	6300	1	1	101A	Storage	Classroom 101 Closet Classroom 101 Closet	W1	Flaking paint.	20	<u>N</u>			N N		
186 187	6300 6300	1	1	101A 101A	Storage Storage	Classroom 101 Closet	W2 W3	Flaking paint. Flaking paint.	5 20	N			N		
187	6300	1	1	101A 101A	Storage	Classroom 101 Closet		Flaking paint.	20	N N	+	+	N		
189	6300	1	1	101A	Primary	Classroom 101	Ceiling	Damaged plaster at ceiling.	20	N			Y		
190	6300	1	1	101	Primary	Classroom 101	W1	Flaking paint above and below blackboard and on door.	20	N			N		
191	6300	1	1	101	Primary	Classroom 101	W3	Flaking paint around windows.	20	Y			Ν	Many posters, bookshelves, desks.	
192	6300	1	1	101	Primary	Classroom 101	W4	Flaking paint above and below blackboard.	20	Ν			Ν		
193	6300	1	1	103	Primary	Classroom 103	Ceiling	Flaking paint at ceiling	40	N			N		
194	6300	1	1	103	Primary	Classroom 103	W1	Flaking paint near entrance and above white board.	15	Ν			Ν	Many supplies and posters	
195	6300	1	1	103	Primary	Classroom 103	W2	Flaking paint above and below bulletin board	20	Ν			Ν	Many supplies and posters	
196	6300	1	1	103	Primary	Classroom 103	W3	Flaking paint around windows	40	Y			Ν	Many supplies and posters	
197	6300	1	1	103	Primary	Classroom 103	W4	Flaking paint at wall	5	Ν			Ν	Many supplies and posters	
198	6300	1	1	103A	Storage	Classroom 103 Closet	Ceiling	Flaking paint	10	Ν			Ν	Many supplies, cabinets, shelving.	
199	6300	1	1	103A	Storage	Classroom 103 Closet	W1	Flaking paint	2	Ν			N	Many supplies, cabinets, shelving.	
200	6300	1	1	103A	Storage	Classroom 103 Closet	W2	Flaking paint	5	Ν			Ν	Many supplies, cabinets, shelving.	
201	6300	1	1	103A	Storage	Classroom 103 Closet	W3	Flaking paint	20	Ν			Ν	Many supplies, cabinets, shelving.	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
202	6300	1	1	103A	Storage	Classroom 103 Closet	W4	Flaking paint	10	Y			Ν	Many supplies, cabinets, shelving.	
203	6300	1	1	104	Primary	Classroom 104	Ceiling	Flaking paint near windows	20	Y			N		
204	6300	1	1	104	Primary	Classroom 104	W1	Flaking paint above and below blackboard, on door, and baseboards	30	N			N		
205	6300	1	1	104	Primary	Classroom 104	W2	Flaking paint at wall and door.	15	N			N		
206	6300	1	1	104	Primary	Classroom 104	W3	Flaking paint around windows.	10	Y			N		
207	6300	1	1	104B	Storage	Classroom 104 Closet	Ceiling	Flaking paint at ceiling	20	N			N		
208	6300	1	1	104B	Storage	Classroom 104 Closet	W1	Flaking paint at wall	20	N			N		
209	6300	1	1	104B	Storage	Classroom 104 Closet	W3	Flaking paint at wall.	30	N			N		
210	6300	1	1	104B	Storage	Classroom 104 Closet	W4	Flaking paint on pipe.	5	N	Floor	2	N		
211	6300	1	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	Ceiling	Flaking paint	20	Ν			Ν		
212	6300	1	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W1	Flaking paint	20	N			Ν		
213	6300	1	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W2	Flaking paint	20	N			Ν		
214	6300	1	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Flaking paint	20	N			N		
215	6300	1	1	104C	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W4	Flaking paint	20	N			Ν		
216	6300	1	1	106	Primary	Classroom 106	W1	Flaking paint on door, above door, and above blackboard	15	Ν			Ν	Many posters, desks, bookshelves, toys.	
217	6300	1	1	106	Primary	Classroom 106	W3	Flaking paint around windows and on trim	10	Y			N	Many posters, desks, bookshelves, toys.	
218	6300	1	1	106	Primary	Classroom 106	W4	Flaking paint above bulletin board	10	N			N	Many posters, desks, bookshelves, toys.	
219	6300	1	1	106A	Storage	Classroom 106 Closet	Ceiling	Flaking paint at ceiling	30	Y			Y	Cabinets, supplies	
220	6300	1	1	106A	Storage	Classroom 106 Closet	W2	Flaking paint at wall	20	Y			Y	Cabinets, supplies	
221	6300	1	1	107	Primary	Classroom 107	Ceiling	Damages plaster	10	N		1	Y	5422100	
222	6300	1	1	107	Primary	Classroom 107	W1	Flaking paint on doors	20	N		1	N		
								Flaking paint on baseboards and behind						Desks,	
223	6300	1	1	107	Primary	Classroom 107	W3	radiator	20	Ν			N	bookshelves	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
224	6300	1	1	108	Primary	Classroom 108	W1	Flaking paint on wall and door	10	N			N		
225	6300	1	1	108	Primary	Classroom 108	W2	Flaking paint on baseboard Flaking paint below windows and behind	15	N			N		
226	6300	1	1	108	Primary	Classroom 108	W3	radiator	30	Y			N		
227	6300	1	1	108B	Storage	Classroom 108 Closet	Ceiling	Cracking paint at ceiling	100	Ν			N	Many supplies	
228	6300	1	1	108B	Storage	Classroom 108 Closet	W3	Flaking paint	5	Ν			Ν	Many supplies	
229	6300	1	1	108B	Storage	Classroom 108 Closet	W4	Flaking paint on pipe	2	Ν			Ν	Many supplies	
230	6300	1	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	Ceiling	Flaking paint at ceiling	10	Ν			Ν		
231	6300	1	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking paint at wall and door	20	Ν			Ν		
232	6300	1	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W2	Flaking paint at wall	5	Ν			Ν		
233	6300	1	1	108C	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Flaking paint at wall	30	Ν			Ν		
234	6300	1	1	111	Storage	Closet at rear of Auditorium	Ceiling	No access							
235	6300	1	1	111	Storage	Closet at rear of Auditorium	Floor	No access							
236	6300	1	1	111	Storage	Closet at rear of Auditorium	W1	No access							
237	6300	1	1	111	Storage	Closet at rear of Auditorium	W2	No access							
238	6300	1	1	111	Storage	Closet at rear of Auditorium	W3	No access							
239	6300	1	1	111	Storage	Closet at rear of Auditorium	W4	No access							
240	6300	1	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	Ceiling	Flaking paint	40	Y			Y	Cleaning supplies, shelves, locker.	
241	6300	1	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W1	Flaking paint	10	Ν			Ν	Cleaning supplies, shelves, locker.	
242	6300	1	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W2	Flaking paint	10	Ν			Ν	Cleaning supplies, shelves, locker.	
243	6300	1	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W3	Flaking paint	20	Ν			Ν	Cleaning supplies, shelves, locker.	

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
244	6300	1	1	103B	Service Closets	Custodial Closet adjacent to Classroom 103	W4	Flaking paint	20	Ν			N	Cleaning supplies, shelves, locker.	
245	6300	1	1	S16	Stairs, Fire Tower	Fire Tower near Classroom 107	Ceiling	Damaged plaster at ceiling	20	Ν			Y		
246	6300	1	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Flaking paint at ceiling	15	Y			Ν		
247	6300	1	1	114	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Flaking paint at wall.	20	Y			Ν		
248	6300	1	1	H16	Circulation (Hallway)	Hallway from Classroom 104 to Teacher's Lounge	W2	Flaking paint behind radiators	20	Ν			Ν		
249	6300	1	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	Ceiling	Cracking paint at ceiling.	20	Ν			Ν		
250	6300	1	1	H18	Circulation (Hallway)	Hallway outside Classrooms 101 to 103	W3	Flaking paint at pipe near S15 and behind radiators	25	Ν			Y		
251	6300	1	1	H15	Circulation (Hallway)	Hallway outside Classrooms 106 to 108	W1	Flaking paint behind radiators	20	Ν			Ν		
252	6300	1	1	H17	Circulation (Hallway)	Hallway to BET Office	Ceiling	Flaking paint at ceiling	10	N			N		
253	6300	1	1	H17	Circulation (Hallway)	Hallway to BET Office	W1	Flaking paint at wall	200	N			N		
254	6300	1	1	H17	Circulation (Hallway)	Hallway to BET Office	W3	Flaking paint at wall	30	N			N	Poster	
255	6300	1	1	115	Administrative Office	Main Office	Ceiling	Flaking paint near windows.	15	Y			N		
256	6300	1	1	115	Administrative Office	Main Office	W3	Flaking paint near desk and behind radiator.	20	Ν			Ν	Desk.	
257	6300	1	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W3	Flaking paint behind radiator	5	Ν			Ν		
258	6300	1	1	108A	Restrooms, Staff - Male	Men's Restroom 109	W4	Flaking paint	5	Ν			Ν		
259	6300	1	1	115B	Administrative Office	Principal's Office	W3	Flaking paint at window sill.	2	N			N	Curtains	
260	6300	1	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	5	Ν			Ν		
261	6300	1	1	115C	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	5	Ν			Ν		
262	6300	1	1	S13	Stairs	Stairwell adjacent Classroom 103	W1	Spalling paint from ongoing steam leak.	50	Y	Floor, radiator cover	10	Ν		
263	6300	1	1	S13	Stairs	Stairwell adjacent Classroom 103	W2	Flaking paint	40	Y			Ν		
264	6300	1	1	S14	Stairs	Stairwell adjacent to Classroom 106	W1	Flaking paint at wall toward basement	50	Y			Ν		
265	6300	1	1	S17	Stairs	Stairwell near Classroom 108	Ceiling	Flaking paint near Exit.	10	Y			Ν		
266	6300	1	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W1	Flaking paint	10	Ν			N		
267	6300	1	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W2	Flaking paint	5	Ν			Ν		
268	6300	1	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W3	Flaking paint	20	Ν			N		
269	6300	1	1	105	Teacher Lounge/Dining	Teacher's Lounge 105	W4	Flaking paint	5	Ν			Ν		

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
270	6300	1	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	Ceiling	Flaking paint	100	Y			Ν	Many supplies	
271	6300	1	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W1	Flaking paint	100	Y			Ν	Many supplies	
272	6300	1	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W2	Flaking paint	100	Y			Ν	Many supplies	
273	6300	1	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W3	Flaking paint	100	Y			Ν	Many supplies	
274	6300	1	1	105A	Storage	Teacher's Lounge 105 Closet adjacent to Windows	W4	Flaking paint	100	Y			Ν	Many supplies	
275	6300	1	1	119	Restrooms, Staff - Female	Women's Restroom 100	Ceiling	Flaking paint and plaster damage	15	Ν			Y		
276	6300	1	0	0B3	Primary	Art Room	Ceiling	Flaking paint at ceiling, pipes, and ducts.	800	Ν			N	Desks	
277	6300	1	0	0B3	Primary	Art Room	W2	Flaking paint around windows & trim.	20	Y			N	Bookshelves, posters	
278	6300	1	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	Ceiling	Flaking paint at ceiling and pipe	200	Y			N		
279	6300	1	0	001	Student Restrooms - Male (4-12)	Basement Boy's Restroom	W1	Flaking paint on pipe.	10	N			N		
280	6300	1	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Flaking paint	50	Y			N		
281	6300	1	0	012	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking paint at pipe	5	N			N		
282	6300	1	0	001A	Storage	Classroom 0B1 Large Closet	Ceiling	Flaking paint	40	Y			N	Many supplies	
283	6300	1	0	001A	Storage	Classroom 0B1 Large Closet	W1	Flaking paint	10	N			N	Many supplies	
284	6300	1	0	001A	Storage	Classroom 0B1 Large Closet	W2	Flaking paint	10	Ν			N	Many supplies	
285	6300	1	0	001A	Storage	Classroom 0B1 Large Closet	W3	Flaking paint	20	N			N	Many supplies	
286	6300	1	0	001A	Storage	Classroom 0B1 Large Closet	W4	Flaking paint	20	Y			N	Many supplies	
287	6300	1	0	0B2B	Storage	Classroom 0B2 Large Closet	W1	Flaking paint	20	Y			N	Many supplies	
288	6300	1	0	0B2A	Storage	Classroom 0B2 Small Closet	W1	Flaking paint at wall and door.	10	N			N	Many supplies	
289	6300	1	0	0B1	Primary	Classroom B1	W1	Flaking paint at closet doors	10	N			N		
290	6300	1	0	0B1	Primary	Classroom B1	W2	Damaged plaster	5	N			N		
291	6300	1	0	0B1	Primary	Classroom B1	W3	Flaking paint near windows	5	N			N		
292	6300	1	0	0B1	Primary	Classroom B1	W4	Damaged plaster	5	N			N		
293	6300	1	0	001B	Storage	Classroom B1 Small Closet	Ceiling	Cracking paint	10	Ν			Ν		
294	6300	1	0	001B	Storage	Classroom B1 Small Closet	W1	Damaged plaster	5	Ν			Y	Supplies	

Task ID	ULCS#	E l m e n t	F l o r	Space # (on Floor Plan)		On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
295	6300	1	0	0B2	Primary	Classroom B2	Ceiling	Flaking paint	10	N			N		
296	6300	1	0	0B2	Primary	Classroom B2	W1	Flaking paint	5	N			N		
297	6300	1	0	0B2	Primary	Classroom B2	W2	Flaking paint	5	N			N		
298	6300	1	0	0B2	Primary	Classroom B2	W3	Flaking paint at windows and columns	20	Y			N		
299 300	6300 6300	1	0	0B2 0B4	Primary Gymnasium - Intermediate Middle	Classroom B2 Gym	W4 Ceiling	Flaking paint Flaking paint at ceiling and ducts	10 500	N N			N N		
301	6300	1	0	0B4	Gymnasium - Intermediate Middle	Gym	W3	Flaking paint at window trim and pipes	30	Y			Ν		
302	6300	1	0	008B	Administrative Office	Gym Office	Ceiling	Flaking paint at ceiling near windows	5	Y			N		
303	6300	1	0	008B	Administrative Office	Gym Office	W2	Flaking paint at window trim	5	Y			N		
304	6300	1	0	008A	Storage	Gym Storage Room	W1	Flaking paint at door	10	N			N		
305	6300	1	0	H01	Circulation (Hallway)	Hallway outside Classrooms B1-B2	Ceiling	Flaking paint on ceiling above ductwork and near Start S17	100	N			Ν		
306	6300	1	0	H02	Circulation (Hallway)	Hallway outside Gym	Ceiling	Flaking paint on deck above ductwork	500	N			N		
307 308	6300 6300	1	0	H02 H03	Circulation (Hallway) Circulation (Hallway)	Hallway outside Gym Hallway outside Logan	W1 Ceiling	Flaking paint at pipe. Flaking paint at ceiling by exit to outdoors	5 25	N Y			N		
309	6300	1	0	H03	Circulation (Hallway)	Cafe 1 Hallway outside Logan	W2	Flaking paint at wall across from Girls	10	Y	Floor	5	N		
310	6300	1	0	H03	Circulation (Hallway)	Cafe 1 Hallway outside Logan Cafe 1	W3	Restroom Flaking paint at wall across from Girls Restroom and at window trim.	15	Y	Floor	5	N		
311	6300	1	0	H03	Circulation (Hallway)	Hallway outside Logan	W4	Flaking paint at pipe by exit to outdoors	5	N			N		
312	6300	1	0	011A	Kitchen	Kitchen	W3	Flaking paint near window behind freezer	10	Y			N	Freezer	
313	6300	1	0	011B	Administrative Office	Kitchen Office	Ceiling	Flaking paint	50	N			N	Supplies, Cabinets, Shelves	
314	6300	1	0	011B	Administrative Office	Kitchen Office	W2	Flaking paint	15	N			Ν	Supplies, Cabinets, Shelves	
315	6300	1	0	011B	Administrative Office	Kitchen Office	W3	Flaking paint	20	N			N	Supplies, Cabinets, Shelves	
316	6300	1	0	011B	Administrative Office	Kitchen Office	W4	Flaking paint	20	N			N	Supplies, Cabinets, Shelves	
317	6300	1	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	Ceiling	Spalling paint at concrete ceiling beam	5	Y			N		
318	6300	1	0	0B5	Cafeteria (Dining Area)	Logan Cafe 2	W2	Spalling paint near wall 3	10	Y			Ν		
319	6300	1	0	0B5	Cafeteria (Dining Area)	Ū.	W3	Flaking paint	10	Y			N		
320	6300	1	0	010	Storage	Logan Cafe 2 Small Closet	Ceiling	Damaged plaster	10	N			Y		
321	6300	1	0	010	Storage	Logan Cafe 2 Small Closet	W1	Flaking paint behind pipe	5	N			Ν		
322	6300	1	0	010	Storage	Logan Cafe 2 Small Closet	W2	Flaking paint where pipes enter wall	10	Ν			Ν		

Task ID	ULCS#	E l e m e n t	F l o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
323	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Ceiling	Flaking paint	100	Y	Floors	50	N		
324	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	Floor	Flaking paint debris	50	Y	Floors		N		
325	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W1	Flaking paint	50	Y	Floors	50	Ν		
326	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W2	Flaking paint	50	Y	Floors	50	Ν		
327	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W3	Flaking paint	50	Y	Floors	50	Ν		
328	6300	1	0	S01	Stairs	Stairwell adjacent to Boiler Room Restroom	W4	Flaking paint	50	Y	Floors	50	Ν		
329	6300	1	0	014A	Storage	Storage Room adjacent to Building Engineer's Restroom	Ceiling	Damaged plaster	10	N			Y		
330															
					+										
					1										