

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2340	1	3	317	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 320	W2	Flaking	6	N	N	0	N	N	
2	2340	1	3	317	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 320	W4	Cracking	8	N	N	0	N	N	
3	2340	1	3	319A	Primary	Classroom 319A	W1	Flaking	3	N	N	0	Y - 110 SF Contents	N	2 Locations
4	2340	1	3	319A	Primary	Classroom 319A	W2	Flaking	24	N	N	0	Y - 112 SF Contents	N	Additional Cracking
5	2340	1	3	319A	Primary	Classroom 319A	W3	Cracking	4	N	N	0	Y - 112 SF Desks, Tables, Bookcases, Contents	N	
6	2340	1	3	319A	Primary	Classroom 319A	W4	Cracking	1	N	N	0	Y - 168 SF Shelves, Posters, Sink	N	
7	2340	1	3	319	Primary	Classroom 319B	Floor	Chipping	2	N	N	0	N	N	
8	2340	1	3	319	Primary	Classroom 319B	W1	Cracking	3	N	N	0	Y - 38 SF Posters	N	
9	2340	1	3	319	Primary	Classroom 319B	W2	Partially Inaccessible	0	N	N	0	Y - 96 SF File Cabinets, Shelves, Contents	N	
10	2340	1	3	319	Primary	Classroom 319B	W3	Flaking	10	N	N	0	Y - 16 SF Shelves	N	2 Locations; Additional Cracking, Chipping; Includes Wall & Radiator
11	2340	1	3	320	Primary	Classroom 320	Ceiling	Flaking	4	N	N	0	N	N	2 Locations; Flaking @ Window Lintel 1, 4
12	2340	1	3	320	Primary	Classroom 320	W1	Cracking	14	N	N	0	Y - 24 SF Bookcases, File Cabinets	N	
13	2340	1	3	320	Primary	Classroom 320	W2	Flaking	5	N	N	0	Y - 168 SF Posters, Contents	N	Additional Chipping; Damage @ Coat Closet Trim
14	2340	1	3	320	Primary	Classroom 320	W3	Chipping	1	N	N	0	Y - 40 SF Bookcases, Tables, Bulletin Boards	N	
15	2340	1	3	320	Primary	Classroom 320	W4	Partially Inaccessible	0	N	N	0	Y - 96 SF Bookcases, File Cabinets, Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
16	2340	1	3	321	Primary	Classroom 321	Ceiling	Flaking	2	N	N	0	ACT	N	2 Locations; Flaking @ Window Lentils 2, 3
17	2340	1	3	321	Primary	Classroom 321	Floor	Chipping	20	N	N	0	N	N	Chipping around Perimeter
18	2340	1	3	321	Primary	Classroom 321	W1	Cracking	4	N	N	0	N	N	
19	2340	1	3	321	Primary	Classroom 321	W3	Cracking	2	N	N	0	Y - 18 SF Contents	N	2 Locations; Additional Chipping; Damage near Window Frame 3
20	2340	1	3	321	Primary	Classroom 321	W4	Flaking	2	N	N	0	Y - 40 SF Posters	N	Additional Chipping
21	2340	1	3	322	Primary	Classroom 322	Ceiling	Cracking	3	N	N	0	ACT	N	2 Locations; Cracking @ Window Lentils 1, 4
22	2340	1	3	322	Primary	Classroom 322	Floor	Chipping	3	N	N	0	N	N	
23	2340	1	3	322	Primary	Classroom 322	W1	Flaking	5	N	N	0	Y - 60 SF Bookcases	N	2 Locations; Additional Cracking, Chipping
24	2340	1	3	322	Primary	Classroom 322	W2	Cracking	2	N	N	0	Y - 54 SF File Cabinets, Posters, Bulletin Boards	N	
25	2340	1	3	322	Primary	Classroom 322	W3	Flaking	7	N	N	0	N	N	3 Locations; Additional Cracking; Damage behind Radiator Falling Off Wall
26	2340	1	3	323	Primary	Classroom 323	Ceiling	Cracking	5	N	N	0	ACT	N	3 Locations; Cracking @ Window Lentils 2-4
27	2340	1	3	323	Primary	Classroom 323	W1	Flaking	18	N	N	0	Y - 18 SF Desks, Books	N	4 Locations; Additional Cracking, Chipping
28	2340	1	3	323	Primary	Classroom 323	W2	Partially Inaccessible	0	N	N	0	Y - 56 SF File Cabinets, Tables, Boxes, Posters	N	
29	2340	1	3	323	Primary	Classroom 323	W3	Flaking	5	N	N	0	N	Y - 2 SF	5 Locations;
30	2340	1	3	324	Primary	Classroom 324	Ceiling	Flaking	14	N	N	0	ACT	N	5 Locations; Additional Cracking; Damage @ Door, Window Lentils 1-4
31	2340	1	3	324	Primary	Classroom 324	W1	Flaking	21	N	N	0	Y - 52 SF Bookcases, Books	N	4 Locations; Additional Cracking
32	2340	1	3	324	Primary	Classroom 324	W2	Cracking	8	N	N	0	Y - 64 SF Posters	N	2 Locations
33	2340	1	3	324	Primary	Classroom 324	W3	Cracking	5	N	N	0	N	N	2 Locations
34	2340	1	3	324	Primary	Classroom 324	W4	Flaking	3	N	N	0	Y - 24 SF File Cabinets, Posters	N	3 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
35	2340	1	3	325	Primary	Classroom 325	Ceiling	Flaking	8	N	N	0	ACT	N	4 Locations; Flaking @ Window Lentils 1, 2, 4 & @ Wall 4
36	2340	1	3	325	Primary	Classroom 325	W1	Flaking	8	N	N	0	Y - 90 SF Cabinets	N	2 Locations; Additional Cracking
37	2340	1	3	325	Primary	Classroom 325	W2	Cracking	8	N	N	0	Y - 36 SF Posters	N	
38	2340	1	3	325	Primary	Classroom 325	W3	Chipping	4	N	N	0	Y - 24 SF Bookcases, Posters	N	Chipping @ Radiator
39	2340	1	3	325	Primary	Classroom 325	W4	Chipping	5	N	N	0	Y - 66 SF Posters	N	5 Locations
40	2340	1	3	326	Primary	Classroom 326	Floor	Chipping	6	N	N	0	N	N	
41	2340	1	3	326	Primary	Classroom 326	W1	Flaking	8	N	N	0	Y - 32 SF Posters	N	Additional Cracking
42	2340	1	3	326	Primary	Classroom 326	W2	Flaking	10	Y	N	0	Y - 36 SF Posters	N	9 Locations; Additional Cracking, Chipping; Damage beneath Windows
43	2340	1	3	326	Primary	Classroom 326	W3	Cracking	6	Y	N	0	Y - 64 SF Cabinets, Posters	N	
44	2340	1	3	326	Primary	Classroom 326	W4	Chipping	1	N	N	0	Y - 106 SF Shelves, Boxes, Contents	N	
45	2340	1	3	327	Primary	Classroom 327	Floor	Flaking	30	N	N	0	N	N	3 Locations; Additional Chipping; Additional Chipping; Most Damage near Radiator
46	2340	1	3	327	Primary	Classroom 327	W1	Flaking	4	N	N	0	Y - 144 SF Books, Contents	N	Additional Cracking; Damage in Coat Closet
47	2340	1	3	327	Primary	Classroom 327	W2	Cracking	3	N	N	0	Y - 44 SF Shelves, Posters	N	3 Locations
48	2340	1	3	327	Primary	Classroom 327	W3	Flaking	16	N	N	0	N	N	7 Locations; Additional Chipping; Damage on Radiator Grates & Window Sills 1-5
49	2340	1	3	327	Primary	Classroom 327	W4	Cracking	2	N	N	0	Y - 32 SF Bulletin Boards, Posters	N	2 Locations; Additional Chipping
50	2340	1	3	327A	Primary	Classroom 327A	Floor	Flaking	6	N	N	0	N	N	Additional Chipping
51	2340	1	3	327A	Primary	Classroom 327A	W1	Flaking	12	N	N	0	N	N	4 Locations; Additional Cracking, Chipping

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
86	2340	1	3	319C	Storage	Storage Closet inside Classroom 319B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
87	2340	1	3	319C	Storage	Storage Closet inside Classroom 319B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
88	2340	1	2	210	Primary	Classroom 210	Floor	Chipping	8	N	N	0	N	N	
89	2340	1	2	210	Primary	Classroom 210	W1	Flaking	3	N	N	0	Y - 140 SF Posters, Contents	N	3 Locations
90	2340	1	2	210	Primary	Classroom 210	W2	Partially Inaccessible	0	N	N	0	Y - 240 SF Bookcases, Posters, Desks	N	
91	2340	1	2	210	Primary	Classroom 210	W3	Partially Inaccessible	0	N	N	0	Y - 72 SF Bookcases, Posters, Desks, Cabinets	N	
92	2340	1	2	210	Primary	Classroom 210	W4	Partially Inaccessible	0	N	N	0	Y - 148 SF Bulletin Boards, Posters	N	
93	2340	1	2	211	Primary	Classroom 211	Ceiling	Cracking	9	N	N	0	ACT	N	
94	2340	1	2	211	Primary	Classroom 211	Floor	Chipping	5	N	N	0	N	N	Chipping Near Coat Closet
95	2340	1	2	211	Primary	Classroom 211	W1	Flaking	4	N	N	0	Y - 144 SF Posters	Y - 2 SF	3 Locations
96	2340	1	2	211	Primary	Classroom 211	W2	Partially Inaccessible	0	N	N	0	Y - 320 SF Bookcases, Books, Contents, Posters, Coats	N	
97	2340	1	2	211	Primary	Classroom 211	W3	Chipping	1	N	N	0	Y - 96 SF Bookcases, Cabinets, Posters	N	
98	2340	1	2	212	Primary	Classroom 212	Ceiling	Flaking	4	N	N	0	ACT	N	2 Locations; Flaking @ Window Lentils 3, 5
99	2340	1	2	212	Primary	Classroom 212	Floor	Chipping	4	N	N	0	N	N	
100	2340	1	2	212	Primary	Classroom 212	W1	Flaking	10	N	N	0	Y - 80 SF Contents	N	
101	2340	1	2	212	Primary	Classroom 212	W3	Chipping	1	N	N	0	N	N	
102	2340	1	2	212	Primary	Classroom 212	W4	Holes	1	N	N	0	Y - 52 SF Bulletin Boards, Cabinets, Posters	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
103	2340	1	2	213	Primary	Classroom 213	Ceiling	Flaking	8	N	N	0	ACT	N	4 Locations; Flaking @ Window Lentils 1, 3, 4, 5
104	2340	1	2	213	Primary	Classroom 213	W1	Flaking	20	N	N	0	Y - 120 SF Contents, Boxes, Coats	N	2 Locations
105	2340	1	2	213	Primary	Classroom 213	W2	Partially Inaccessible	0	N	N	0	Y - 44 SF File Cabinets, Cabinets, Bookcases, Tables	N	
106	2340	1	2	213	Primary	Classroom 213	W3	Cracking	10	N	N	0	N	N	2 Locations
107	2340	1	2	213	Primary	Classroom 213	W4	Chipping	2	N	N	0	Y - 42 SF Desks, Posters	N	2 Locations
108	2340	1	2	214	Primary	Classroom 214	W1	Cracking	10	N	N	0	Y - 80 SF Contents, Boxes, Coats	N	2 Locations; Entrance & Coat Closet
109	2340	1	2	214	Primary	Classroom 214	W2	Flaking	2	N	N	0	Y - 30 SF Bookcases, Desks	N	
110	2340	1	2	214	Primary	Classroom 214	W3	Cracking	4	N	N	0	Y - 40 SF Bookcases, Contents	N	
111	2340	1	2	217	Primary	Classroom 217	Ceiling	Flaking	16	Y	N	0	ACT	N	Additional Cracking; Damage @ Window Lentils 2, 5; Water Stains on ACT
112	2340	1	2	217	Primary	Classroom 217	Floor	Chipping	5	N	N	0	N	N	
113	2340	1	2	217	Primary	Classroom 217	W1	Flaking	15	N	N	0	Y - 18 SF Posters	Y - 3 SF	2 Locations; Additional Cracking, Chipping, Holes
114	2340	1	2	217	Primary	Classroom 217	W2	Flaking	5	N	N	0	Y - 24 SF Bookcases	N	2 Locations
115	2340	1	2	217	Primary	Classroom 217	W3	Flaking	8	N	N	0	Y - 112 SF Boxes, Contents, Bulletin Boards, Posters	N	
116	2340	1	2	217	Primary	Classroom 217	W4	Flaking	4	N	N	0	Y - 168 SF Books, Boxes, Coats, Contents	N	
117	2340	1	2	218	Primary	Classroom 218	Ceiling	Flaking	6	N	N	0	ACT	N	Additional Cracking
118	2340	1	2	218	Primary	Classroom 218	W1	Flaking	3	N	N	0	Y - 160 SF Contents, Coats	Y - 3 SF	3 Locations; Additional Cracking

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
119	2340	1	2	218	Primary	Classroom 218	W3	Partially Inaccessible	0	N	N	0	Y - 36 SF Bookcases	N	
120	2340	1	2	218	Primary	Classroom 218	W4	Cracking	2	N	N	0	Y - 24 SF Posters	N	
121	2340	1	2	219	Computer - Intermediate Middle	Computer Classroom 219	W1	Flaking	24	N	N	0	Y - 90 SF Desks, Tables, Contents, Bulletin Boards	N	2 Locations; Additional Cracking
122	2340	1	2	219	Computer - Intermediate Middle	Computer Classroom 219	W2	Cracking	4	N	N	0	Y - 64 SF Desks, Posters	N	
123	2340	1	2	219	Computer - Intermediate Middle	Computer Classroom 219	W3	Partially Inaccessible	0	N	N	0	Y - 60 SF Desks, Posters	N	Check beneath Wall Decals
124	2340	1	2	219	Computer - Intermediate Middle	Computer Classroom 219	W4	Cracking	4	N	N	0	N	N	
125	2340	1	2	S3	Stairs	Fire Tower across from Classroom 214	W1	Flaking	54	N	N	0	N	N	Flaking Paint on Window Bars
126	2340	1	2	S23	Stairs	Fire Tower across from Classroom 214	W3	Flaking	80	N	N	0	N	N	Flaking Paint on Window Bars
127	2340	1	2	216	IMC (Library)	IMC (Library)	Floor	Flaking	4	N	N	0	N	N	Additional Chipping
128	2340	1	2	216	IMC (Library)	IMC (Library)	W1	Flaking	6	N	N	0	Y - 78 SF Bookcases, Desks	N	
129	2340	1	2	216	IMC (Library)	IMC (Library)	W2	Partially Inaccessible	0	N	N	0	Y - 96 SF Bookcases	N	
130	2340	1	2	216	IMC (Library)	IMC (Library)	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Bookcases	N	
131	2340	1	2	216	IMC (Library)	IMC (Library)	W4	Partially Inaccessible	0	N	N	0	Y - 78 SF Bookcases	N	
132	2340	1	2	209A	Space (Kitchen)	Kitchen inside Teacher's Lounge across from Classroom 211	Ceiling	Cracking	6	N	N	0	N	Y - 1 SF	
133	2340	1	2	209A	Space (Kitchen)	Kitchen inside Teacher's Lounge across from Classroom 211	W1	Cracking	4	N	N	0	N	Y - 2 SF	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
134	2340	1	2	209A	Space (Kitchen)	Kitchen inside Teacher's Lounge across from Classroom 211	W2	Cracking	21	N	N	0	Y - 40 SF Shelves	N	2 Locations
135	2340	1	2	209A	Space (Kitchen)	Kitchen inside Teacher's Lounge across from Classroom 211	W3	Cracking	6	N	N	0	Y - 35 SF Shelves	Y - 2 SF	
136	2340	1	2	209A	Space (Kitchen)	Kitchen inside Teacher's Lounge across from Classroom 211	W4	Flaking	14	N	N	0	Y - 30 SF Bookcases	N	2 Locations
137	2340	1	2	H2	Circulation (Hallway)	Main Hallway	Floor	Chipping	30	N	N	0	N	N	
138	2340	1	2	H2	Circulation (Hallway)	Main Hallway	W1	Flaking	20	N	N	0	N	N	Additional Cracking
139	2340	1	2	H2	Circulation (Hallway)	Main Hallway	W2	Flaking	23	N	N	0	N	N	9 Locations; Additional Cracking, Chipping
140	2340	1	2	H2	Circulation (Hallway)	Main Hallway	W3	Cracking	1	N	N	0	Y - 30 SF Posters	N	
141	2340	1	2	H2	Circulation (Hallway)	Main Hallway	W4	Cracking	22	N	N	0	N	N	5 Locations; Additional Chipping
142	2340	1	2	216A	Administrative Office	Speech Office next to IMC (Library)	W2	Flaking	3	N	N	0	Y - 85 SF Fridge, Cabinets	N	Additional Cracking; Damage @ Metal Pipe
143	2340	1	2	216A	Administrative Office	Speech Office next to IMC (Library)	W3	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
144	2340	1	2	216A	Administrative Office	Speech Office next to IMC (Library)	W1	Gouges	1	N	N	0	Y - 6 SF Bookcases	N	
145	2340	1	2	211A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 211	Ceiling	Holes	6	N	N	0	N	N	
146	2340	1	2	211A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 211	W1	Cracking	6	N	N	0	N	N	Additional Chipping
147	2340	1	2	211A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 211	W2	Cracking	12	N	N	0	N	N	2 Locations; Additional Chipping
148	2340	1	2	211A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 211	W3	Flaking	9	N	N	0	N	N	Additional Cracking; Near FGPI
149	2340	1	2	211A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 211	W4	Cracking	12	N	N	0	N	N	2 Locations

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
150	2340	1	2	217A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 217	Floor	None	0	N	Y - On Floor Near Toilets	12	N	N	
151	2340	1	2	217A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 217	W1	Chipping	4	N	N	0	N	N	Additional Chipping
152	2340	1	2	217A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 217	W2	Flaking	32	N	N	0	N	N	Additional Chipping; Includes FGPI & Wall
153	2340	1	2	217A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 217	W3	Cracking	24	N	N	0	N	N	
154	2340	1	2	217A	Restrooms, Staff - Male/Female	Staff Restroom next to Classroom 217	W4	Cracking	6	N	N	0	Y - 28 SF Cabinets	N	
155	2340	1	2	S25	Stairs	Stairwell next to Classroom 211	Ceiling	Flaking	25	N	N	0	N	N	2 Locations; Additional Cracking
156	2340	1	2	S25	Stairs	Stairwell next to Classroom 211	W1	Flaking	7	N	Y - Window Sill	1	N	N	3 Locations; Additional Spalling, Chipping
157	2340	1	2	S25	Stairs	Stairwell next to Classroom 211	W2	Flaking	50	N	N	0	N	N	2 Locations; Additional Chipping
158	2340	1	2	S25	Stairs	Stairwell next to Classroom 211	W3	Spalling	1	Y	N	0	N	Y - 1 SF	
159	2340	1	2	S25	Stairs	Stairwell next to Classroom 211	W4	Cracking	12	N	N	0	N	N	
160	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	Ceiling	Cracking	14	N	N	0	N	Y - 14 SF	2 Locations
161	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	Floor	Chipping	2	N	N	0	N	Y - 2 SF	
162	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	W1	Flaking	1	N	N	0	N	N	
163	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	W2	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping
164	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	W3	Cracking	6	N	N	0	N	N	
165	2340	1	2	S22	Stairs	Stairwell next to Computer Classroom 219	W4	Cracking	2	N	N	0	N	N	2 Locations; Additional Holes

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
166	2340	1	2	209	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 211	Floor	Flaking	88	N	N	0	N	N	
167	2340	1	2	209	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 211	W1	Cracking	12	Y	N	0	Y - 54 SF Shelves, Bookcases, Posters	N	3 Locations; Additional Chipping; Water Stains
168	2340	1	2	209	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 211	W2	Flaking	2	N	N	0	Y - 36 SF Bookcases, Desks	N	2 Locations
169	2340	1	2	209	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 211	W3	Chipping	1	N	N	0	Y - 38 SF Tables, Bookcases	N	
170	2340	1	2	209	Teacher Lounge/Dining	Teacher's Lounge across from Classroom 211	W4	Chipping	3	N	N	0	N	N	
171	2340	1	2	216B	Teacher Lounge/Dining	Teacher's Lounge/Office next to IMC (Library)	Ceiling	Flaking	25	N	N	0	N	N	2 Locations
172	2340	1	2	216B	Teacher Lounge/Dining	Teacher's Lounge/Office next to IMC (Library)	W2	Flaking	50	N	N	0	N	N	2 Locations
173	2340	1	2	216B	Teacher Lounge/Dining	Teacher's Lounge/Office next to IMC (Library)	W3	Spalling	2	Y	N	0	N	N	
174	2340	1	2	216B	Teacher Lounge/Dining	Teacher's Lounge/Office next to IMC (Library)	W4	Cracking	12	N	N	0	N	N	
175	2340	2	1	AD	Auditorium	Auditorium	W1	Chipping	3	N	N	0	N	N	3 Locations
176	2340	2	1	AD	Auditorium	Auditorium	W4	Chipping	1	N	N	0	N	N	
177	2340	2	1	AD1	Stage	Auditorium Stage	W2	Chipping	64	N	N	0	N	N	
178	2340	2	1	AD1	Stage	Auditorium Stage	W3	Partially Inaccessible	0	N	N	0	Y - 1000 SF Boxes, Contents, Ductwork	N	
179	2340	2	1	AD1	Stage	Auditorium Stage	W4	Chipping	55	N	N	0	N	N	
180	2340	2	1	115	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W1	Spalling	9	Y	N	0	N	Y - 9 SF	
181	2340	2	1	115	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W2	Spalling	6	Y	N	0	N	Y - 6 SF	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
182	2340	2	1	115	Student Restrooms - Male (4-12)	Boy's Restroom inside Gymnasium	W4	Flaking	2	N	N	0	N	N	
183	2340	2	1	109A	Storage	Cafeteria Table Storage Room	W1	Cracking	4	N	N	0	N	N	
184	2340	2	1	109A	Storage	Cafeteria Table Storage Room	W4	Holes	1	N	N	0	N	N	
185	2340	1	1	101B	Primary	Classroom 101	W1	Chipping	2	N	N	0	Y - 52 SF File Cabinets, Bookcases	N	2 Locations
186	2340	1	1	101B	Primary	Classroom 101	W2	Partially Inaccessible	0	N	N	0	Y - 140 SF Shelves	N	
187	2340	1	1	101B	Primary	Classroom 101	W3	Flaking	14	N	N	0	Y - 52 SF Desks	N	2 Locations; Additional Cracking; Damage above Radiator
188	2340	1	1	101B	Primary	Classroom 101	W4	Cracking	14	N	N	0	N	N	2 Locations
189	2340	1	1	102	Primary	Classroom 102	Ceiling	Flaking	16	N	N	0	ACT	N	Flaking @ Window Lentils 1-4
190	2340	1	1	102	Primary	Classroom 102	Floor	Flaking	3	N	N	0	N	N	
191	2340	1	1	102	Primary	Classroom 102	W1	Cracking	16	N	N	0	Y - 56 SF Tables, Fridge	N	2 Locations
192	2340	1	1	102	Primary	Classroom 102	W2	Flaking	40	N	N	0	Y - 40 SF Bulletin Boards, Posters	N	4 Locations; Additional Cracking, Chipping; Includes Door
193	2340	1	1	102	Primary	Classroom 102	W3	Cracking	2	N	N	0	Y - 36 SF File Cabinets, Posters	N	
194	2340	1	1	102	Primary	Classroom 102	W4	Partially Inaccessible	0	N	N	0	Y - 75 SF Shelves	N	
195	2340	1	1	103	Primary	Classroom 103	Ceiling	Flaking	3	N	N	0	ACT	N	2 Locations; Window Lentils 2, 5
196	2340	1	1	103	Primary	Classroom 103	W1	Flaking	1	N	N	0	Y - 168 SF Shelves	Y - 1 SF	Check behind Plastic Wall Covering between Shelves
197	2340	1	1	103	Primary	Classroom 103	W2	Partially Inaccessible	0	N	N	0	Y - 144 SF Shelves, Desks	N	
198	2340	1	1	103	Primary	Classroom 103	W3	Flaking	7	N	N	0	Y - 72 SF Desks, Tables	N	2 Locations; Additional Cracking
199	2340	1	1	103	Primary	Classroom 103	W4	Flaking	1	N	N	0	N	N	Flaking @ FGPI
200	2340	1	1	105	Primary	Classroom 105	W1	Flaking	10	N	N	0	Y - 72 SF Posters, Boxes, Contents	N	3 Locations; Additional Cracking, Chipping

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
201	2340	1	1	105	Primary	Classroom 105	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF Posters, Bulletin Boards, Shelves	N	
202	2340	1	1	105	Primary	Classroom 105	W3	Flaking	5	N	N	0	Y - 72 SF Desks, Shelves, Boxes	N	
203	2340	1	1	105	Primary	Classroom 105	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Tables, Shelves, Drawers	N	
204	2340	1	1	106	Primary	Classroom 106	Ceiling	Flaking	4	N	N	0	ACT	N	2 Locations
205	2340	1	1	106	Primary	Classroom 106	W1	Cracking	2	N	N	0	Y - 168 SF Shelves, Posters, Contents	N	2 Locations; Additional Chipping
206	2340	1	1	106	Primary	Classroom 106	W2	Cracking	24	N	N	0	Y - 120 SF Posters, Contents	N	4 Locations
207	2340	1	1	106	Primary	Classroom 106	W3	Flaking	12	N	N	0	Y - 112 SF Cabinets, Desks, Posters, Boxes, Contents	N	Additional Cracking
208	2340	1	1	106	Primary	Classroom 106	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Shelves, Contents	N	
209	2340	1	1	107	Primary	Classroom 107	Ceiling	Flaking	8	N	N	0	ACT	N	Flaking @ Window Lentils 2, 3
210	2340	1	1	107	Primary	Classroom 107	Floor	Chipping	5	N	N	0	N	N	Chipping @ Perimeter
211	2340	1	1	107	Primary	Classroom 107	W1	Cracking	6	N	N	0	Y - 60 SF Posters, Shelves	N	2 Locations
212	2340	1	1	107	Primary	Classroom 107	W2	Flaking	8	N	N	0	Y - 32 SF Posters, Contents	N	3 Locations
213	2340	1	1	107	Primary	Classroom 107	W3	Flaking	3	N	N	0	Y - 75 SF Shelves, Contents	N	Flaking @ Window Sill 5
214	2340	1	1	107	Primary	Classroom 107	W4	Cracking	3	N	N	0	Y - 60 SF Bulletin Boards, Cabinets	N	2 Locations
215	2340	1	1	108	Primary	Classroom 108	Ceiling	Flaking	20	N	N	0	ACT	N	Flaking @ Window Lentils 1-5
216	2340	1	1	108	Primary	Classroom 108	W1	Flaking	2	Y	N	0	Y - 100 SF Posters	N	Water Stain above Door

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
217	2340	1	1	108	Primary	Classroom 108	W2	Flaking	1	N	N	0	Y - 72 SF Shelves, Cabinets	Y - 1 SF	Damage @ Window 5
218	2340	1	1	108	Primary	Classroom 108	W3	Cracking	5	N	N	0	Y - 64 SF Posters	N	2 Locations
219	2340	1	1	108	Primary	Classroom 108	W4	Cracking	6	N	N	0	N	N	
220	2340	1	1	109	Primary	Classroom 109	Ceiling	Flaking	2	N	N	0	ACT	N	Flaking @ Window Lintel 1
221	2340	1	1	109	Primary	Classroom 109	W1	Flaking	3	N	N	0	Y - 108 SF Contents	N	2 Locations; Flaking in Coat Closet
222	2340	1	1	109	Primary	Classroom 109	W2	Flaking	2	N	N	0	Y - 104 SF Bulletin Boards, Posters, Contents	N	2 Locations
223	2340	1	1	109	Primary	Classroom 109	W3	Flaking	1	N	N	0	Y - 78 SF Desks, Shelves, Posters	N	
224	2340	1	1	109	Primary	Classroom 109	W4	Flaking	2	N	N	0	Y - 56 SF Cabinets, Posters	N	
225	2340	1	1	S13A	Stairs	Fire Tower across from Classroom 105	W3	Flaking	120	N	N	0	N	N	Flaking on Window Bars
226	2340	1	1	S13	Stairs	Fire Tower across from Classroom 105	W4	Flaking	3	N	N	0	N	N	Flaking @ Door Frame
227	2340	1	1	101	Administrative Office	Front Office next to Classroom 101	W1	Partially Inaccessible	0	N	N	0	Y - 37 SF Bulletin Boards, File Cabinets	N	
228	2340	1	1	101	Administrative Office	Front Office next to Classroom 101	W2	Partially Inaccessible	0	N	N	0	Y - 96 SF File Cabinets, Shelves	N	
229	2340	1	1	101	Administrative Office	Front Office next to Classroom 101	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF Shelves	N	
230	2340	1	1	101	Administrative Office	Front Office next to Classroom 101	W4	Partially Inaccessible	0	N	N	0	Y - 12 SF File Cabinets	N	
231	2340	2	1	115A	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W1	Flaking	4	N	N	0	N	N	
232	2340	2	1	115A	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W2	Flaking	3	N	N	0	N	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
233	2340	2	1	115A	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W3	Flaking	8	N	N	0	N	N	
234	2340	2	1	115A	Student Restrooms - Female (4-12)	Girl's Restroom inside Gymnasium	W4	Flaking	2	N	N	0	N	N	
235	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
236	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
237	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
238	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
239	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
240	2340	2	1	115B	Storage	Gym Storage Room next to Boy's Gym Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
241	2340	2	1	106	Storage	Gym Storage Room next to Kitchen Storage Room	Ceiling	Cracking	4	N	N	0	ACT	N	
242	2340	2	1	106	Storage	Gym Storage Room next to Kitchen Storage Room	W1	Holes	1	N	N	0	Y - 32 SF Contents	N	
243	2340	2	1	106	Storage	Gym Storage Room next to Kitchen Storage Room	W2	Holes	1	N	N	0	Y - 56 SF Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
244	2340	2	1	106	Storage	Gym Storage Room next to Kitchen Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 100 SF Contents	N	
245	2340	2	1	106	Storage	Gym Storage Room next to Kitchen Storage Room	W4	Cracking	2	N	N	0	Y - 40 SF Contents	N	
246	2340	2	1	105	Administrative Office	Gym Teacher's Office	W1	Partially Inaccessible	0	N	N	0	Y - 12 SF Desks	N	
247	2340	2	1	105	Administrative Office	Gym Teacher's Office	W2	Holes	1	N	N	0	Y - 19 SF Shelves, Contents	N	
248	2340	2	1	105	Administrative Office	Gym Teacher's Office	W3	Chipping	2	N	N	0	Y - 70 SF Shelves, Contents	N	
249	2340	2	1	105	Administrative Office	Gym Teacher's Office	W4	Partially Inaccessible	0	N	N	0	Y - 72 SF Shelves, Contents	N	
250	2340	2	1	104D	Restrooms, Staff - Male/Female	Gym Teacher's Office Restroom	W3	Chipping	3	N	N	0	N	N	2 Locations
251	2340	2	1	GYM	Gymnasium - Intermediate Middle	Gymnasium	W2	Flaking	2	N	N	0	Y - 255 SF Bulletin Boards, Posters, Ductwork	N	2 Locations; Additional Chipping
252	2340	2	1	GYM	Gymnasium - Intermediate Middle	Gymnasium	W3	Cracking	4	N	N	0	Y - 30 SF Posters	N	2 Locations; Additional Chipping
253	2340	2	1	GYM	Gymnasium - Intermediate Middle	Gymnasium	W4	Flaking	31	N	N	0	Y - 220 SF Posters, Contents, Ductwork	N	4 Locations; Additional Cracking, Holes
254	2340	2	1	109B	Circulation (Hallway)	Gymnasium Entrance Vestibule from School Yard	W1	Flaking	19	N	N	0	N	N	2 Locations; Additional Cracking, Chipping; Includes Door & Wall
255	2340	2	1	109B	Circulation (Hallway)	Gymnasium Entrance Vestibule from School Yard	W2	Flaking	1	N	N	0	N	N	
256	2340	2	1	109B	Circulation (Hallway)	Gymnasium Entrance Vestibule from School Yard	W4	Cracking	5	N	N	0	N	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
257	2340	2	1	H13	Circulation (Hallway)	Hallway outside of Gym and Auditorium	W2	Flaking	1	N	N	0	Y - 115 SF Posters	N	
258	2340	2	1	H13	Circulation (Hallway)	Hallway outside of Gym and Auditorium	W4	Flaking	2	N	N	0	Y - 161 SF Posters	N	Flaking @ Fire Extinguisher
259	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
260	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
261	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
262	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
263	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
264	2340	2	1	111B	Storage	Instrument Storage Room next to Auditorium Stage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
265	2340	2	1	108	Space (Kitchen)	Kitchen	W1	Holes	3	N	N	0	N	N	
266	2340	2	1	108	Space (Kitchen)	Kitchen	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Kitchen Cart	N	
267	2340	2	1	108	Space (Kitchen)	Kitchen	W3	Partially Inaccessible	0	N	N	0	Y - 144 SF Fridge, Boxes	N	
268	2340	2	1	108	Space (Kitchen)	Kitchen	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	
269	2340	2	1	107	Storage	Kitchen Storage Room	W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
270	2340	2	1	107	Storage	Kitchen Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Boxes	N	
271	2340	2	1	107	Storage	Kitchen Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 70 SF Boxes	N	
272	2340	2	1	107	Storage	Kitchen Storage Room	W4	Partially Inaccessible	0	N	N	0	Y - 96 SF Shelves, Boxes	N	
273	2340	1	1	110	Administrative Office	Learning Support Office next to Classroom 109	Ceiling	Flaking	18	N	N	0	N	N	Additional Cracking

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
274	2340	1	1	110	Administrative Office	Learning Support Office next to Classroom 109	W1	Cracking	5	N	N	0	Y - 12 SF File Cabinets, Posters	N	2 Locations
275	2340	1	1	110	Administrative Office	Learning Support Office next to Classroom 109	W2	Flaking	12	N	N	0	Y - 74 SF Shelves, Bulletin Boards	Y - 12 SF	Shelving Ripped Out of Wall
276	2340	1	1	110	Administrative Office	Learning Support Office next to Classroom 109	W3	Flaking	13	N	N	0	Y - 50 SF Shelves	N	2 Locations; Additional Cracking; Damage on Window Lintel and Wall
277	2340	1	1	110	Administrative Office	Learning Support Office next to Classroom 109	W4	Flaking	3	N	N	0	Y - 76 SF Desks, Posters	N	2 Locations; Additional Cracking
278	2340	1	1	H1	Circulation (Hallway)	Main Hallway	W1	Flaking	38	N	N	0	Y - 272 SF Posters, Bulletin Boards	N	5 Locations; Additional Cracking, Holes
279	2340	1	1	H1	Circulation (Hallway)	Main Hallway	W2	Cracking	4	N	N	3 SF	Y - 16 SF Bulletin Boards	N	Cracking on Door Frame
280	2340	1	1	H1	Circulation (Hallway)	Main Hallway	W3	Flaking	12	N	Y - Radiator 2	6	Y - 176 SF Bulletin Boards	N	5 Locations; Additional Cracking
281	2340	1	1	H1	Circulation (Hallway)	Main Hallway	W4	Partially Inaccessible	0	N	N	0	Y - 22 SF Posters	N	
282	2340	1	1	104	Administrative Office	Main Office	W2	Flaking	5	N	N	0	Y - 80 SF Bulletin Boards, Posters, Copier	Y - 2 SF	3 Locations; Additional Holes
283	2340	1	1	104	Administrative Office	Main Office	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Desks, Shelves	N	
284	2340	1	1	104	Administrative Office	Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Posters, Cabinets	N	
285	2340	1	1	110A	Health Service Room	Nurse's Office	W1	Chipping	1	N	N	0	Y - 24 SF Fridge, Posters	N	2 Locations
286	2340	1	1	110A	Health Service Room	Nurse's Office	W2	Flaking	27	N	N	0	Y - 60 SF Desks, Posters	N	
287	2340	1	1	110A	Health Service Room	Nurse's Office	W3	Cracking	2	N	N	0	N	N	
288	2340	1	1	110B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	Ceiling	Cracking	3	N	N	0	N	N	
289	2340	1	1	110B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W1	Flaking	1	N	N	0	N	N	

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
290	2340	1	1	110B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W2	Flaking	4	N	N	0	N	N	2 Locations
291	2340	1	1	110B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W3	Cracking	2	N	N	0	N	N	
292	2340	1	1	110B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W4	Flaking	3	N	N	0	N	N	Flaking on FGPI
293	2340	1	1	104A	Administrative Office	Principal's Office	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Bookcases, Posters	N	
294	2340	1	1	104A	Administrative Office	Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF Whiteboard, Microwave, Fridge	N	
295	2340	1	1	104A	Administrative Office	Principal's Office	W3	Flaking	1	N	N	0	Y - 50 SF Desks, File Cabinets	N	Flaking @ Window Sill 2
296	2340	1	1	104A	Administrative Office	Principal's Office	W4	Cracking	4	N	N	0	Y - 56 SF Desks, Tables	N	
297	2340	1	1	104C	Storage	Principal's Office Storage Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
298	2340	1	1	104C	Storage	Principal's Office Storage Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
299	2340	1	1	104C	Storage	Principal's Office Storage Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
300	2340	1	1	104C	Storage	Principal's Office Storage Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
301	2340	1	1	104C	Storage	Principal's Office Storage Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
302	2340	1	1	104C	Storage	Principal's Office Storage Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
303	2340	1	1	101A	Administrative Office	Rear Office next to Classroom 101	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Bulletin Board	N	
304	2340	1	1	101A	Administrative Office	Rear Office next to Classroom 101	W3	Cracking	3	N	N	0	Y - 30 SF Desks, Chairs	N	
305	2340	1	1	101A	Administrative Office	Rear Office next to Classroom 101	W4	Cracking	3	N	N	0	Y - 25 SF Shelves	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
306	2340	1	1	S1	Stairs	Stairwell next to Classroom 102	W2	Cracking	26	N	N	0	N	N	
307	2340	1	1	S1	Stairs	Stairwell next to Classroom 102	W3	Cracking	8	N	N	0	N	N	
308	2340	1	1	S1	Stairs	Stairwell next to Classroom 102	W4	Cracking	12	N	N	0	N	N	
309	2340	1	1	S2	Stairs	Stairwell next to Classroom 108	W2	Flaking	60	N	N	0	N	Y - 8 SF	2 Locations; Additional Cracking, Chipping
310	2340	1	1	S2	Stairs	Stairwell next to Classroom 108	W3	Flaking	2	N	N	0	N	N	
311	2340	1	1	S2	Stairs	Stairwell next to Classroom 108	W4	Chipping	1	N	N	0	N	N	
312	2340	1	1	H12	Circulation (Hallway)	Stairwell Vestibule between Elements 1 and 2	Ceiling	Flaking	4	N	N	0	N	N	2 Locations; Ceiling > 20 feet
313	2340	1	1	H12	Circulation (Hallway)	Stairwell Vestibule between Elements 1 and 2	W1	Flaking	4	N	N	0	N	N	3 Locations; Additional Cracking, Gouges
314	2340	1	1	H12	Circulation (Hallway)	Stairwell Vestibule between Elements 1 and 2	W2	Cracking	12	N	N	0	N	Y - 1 SF	3 Locations
315	2340	1	1	H12	Circulation (Hallway)	Stairwell Vestibule between Elements 1 and 2	W3	Cracking	2	N	N	0	N	N	
316	2340	1	1	102B	Student Restrooms - Male/Female (Classroom)	Student Restroom inside Classroom 102	W1	Cracking	9	N	N	0	N	N	
317	2340	1	1	102B	Student Restrooms - Male/Female (Classroom)	Student Restroom inside Classroom 102	W2	Flaking	16	N	N	0	N	N	
318	2340	1	1	102B	Student Restrooms - Male/Female (Classroom)	Student Restroom inside Classroom 102	W3	Cracking	2	N	N	0	N	N	
319	2340	1	1	102B	Student Restrooms - Male/Female (Classroom)	Student Restroom inside Classroom 102	W4	Flaking	1	N	N	0	N	N	

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
320	2340	1	1	102A	Student Restrooms - Male/Female (Classroom)	Student Restroom outside of Classroom 102	W2	Flaking	0	N	N	0	N	N	
321	2340	1	1	108A	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 108	Ceiling	Flaking	2	N	N	0	N	N	
322	2340	1	1	108A	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 108	W1	Flaking	1	N	N	0	N	N	Flaking @ Top of Door
323	2340	1	1	108A	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 108	W3	Cracking	2	N	N	0	N	N	
324	2340	1	1	108A	Restrooms, Staff - Female	Women's Staff Restroom next to Classroom 108	W4	Cracking	13	N	N	0	N	N	2 Locations; Additional Chipping
325	2340	1	0	10	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Flaking	6	N	N	0	N	N	2 Locations; Additional Cracking
326	2340	1	0	10	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Flaking	33	N	N	0	N	N	Flaking Where Brick Meets Pipe Chase
327	2340	1	0	10	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Flaking	24	N	N	0	N	N	Flaking Where Brick Meets Pipe Chase
328	2340	1	0	10	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Flaking	33	N	N	0	N	N	Flaking Where Brick Meets Pipe Chase
329	2340	1	0	2	Primary	Classroom 1	W1	Partially Inaccessible	0	N	N	0	Y - 24 SF Posters	N	
330	2340	1	0	2	Primary	Classroom 1	W2	Flaking	4	N	N	0	Y - 96 SF Bookcases, Desks	N	2 Locations; Fiberglass Pipe Insulation & Window Sill
331	2340	1	0	2	Primary	Classroom 1	W3	Partially Inaccessible	0	N	N	0	Y - 130 SF Shelves, Bookcases, Posters	N	
332	2340	1	0	2	Primary	Classroom 1	W4	Chipping	6	N	N	0	Y - 18 SF Posters	N	
333	2340	1	0	6	Primary	Classroom 3	W1	Flaking	3	N	N	0	Y - 64 SF Contents	N	Flaking @ Door Frame

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
334	2340	1	0	6	Primary	Classroom 3	W2	Partially Inaccessible	0	N	N	0	Y - 72 SF Bookcases, Posters	N	
335	2340	1	0	6	Primary	Classroom 3	W3	Partially Inaccessible	0	N	N	0	Y - 76 SF Posters, Shelves, Smartboard	N	
336	2340	1	0	6	Primary	Classroom 3	W4	Partially Inaccessible	0	N	N	0	Y - 42 SF Contents, Desks	N	
337	2340	1	0	7	Primary	Classroom 4	Ceiling	Cracking	32	N	N	0	N	N	
338	2340	1	0	7	Primary	Classroom 4	W1	Flaking	3	N	N	0	Y - 24 SF Whiteboard, Posters, Tables	N	5 Locations; Additional Cracking, Holes
339	2340	1	0	7	Primary	Classroom 4	W2	Flaking	12	N	N	0	Y - 60 SF Desks, Shelves, Posters	N	3 Locations; Additional Cracking
340	2340	1	0	7	Primary	Classroom 4	W3	Flaking	5	N	N	0	Y - 80 SF Shelves, Cabinets	N	2 Locations; Additional Chipping
341	2340	1	0	7	Primary	Classroom 4	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Posters, Contents	N	
342	2340	1	0	008A	Primary	Classroom 5	W1	Flaking	3	N	N	0	Y - 144 SF Desks, Posters, Contents	N	3 Locations
343	2340	1	0	008A	Primary	Classroom 5	W2	Partially Inaccessible	0	N	N	0	Y - 64 SF Cabinets, Posters, Contents	N	
344	2340	1	0	008A	Primary	Classroom 5	W3	Flaking	5	N	N	0	Y - 72 SF Posters, Desks, File Cabinets	N	2 Locations
345	2340	1	0	008A	Primary	Classroom 5	W4	Flaking	2	N	N	0	Y - 84 SF Cabinets, Posters	N	2 Locations
346	2340	1	0	8	Primary	Classroom 8 (Art)	W1	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Bulletin Boards, Posters	N	
347	2340	1	0	8	Primary	Classroom 8 (Art)	W2	Partially Inaccessible	0	N	N	0	Y - 128 SF Shelves, Contents	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
348	2340	1	0	8	Primary	Classroom 8 (Art)	W3	Flaking	12	N	N	0	Y - 132 SF Shelves, Contents	N	3 Locations; Near Windows 1 & 4
349	2340	1	0	8	Primary	Classroom 8 (Art)	W4	Partially Inaccessible	0	N	N	0	Y - 12 SF Posters	N	
350	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
351	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
352	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
353	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
354	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
355	2340	1	0	010B	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
356	2340	1	0	H0B	Circulation (Hallway)	Main Hallway	Ceiling	Flaking	19	N	N	0	N	N	3 Locations; Additional Cracking
357	2340	1	0	H0B	Circulation (Hallway)	Main Hallway	W1	Flaking	48	N	N	0	N	N	2 Locations; Additional Cracking
358	2340	1	0	H0B	Circulation (Hallway)	Main Hallway	W2	Flaking	180	N	N	0	Y - 240 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
359	2340	1	0	H0B	Circulation (Hallway)	Main Hallway	W3	Flaking	58	N	N	0	Y - 120 SF Bulletin Boards, Posters	N	5 Locations; Additional Cracking
360	2340	1	0	H0B	Circulation (Hallway)	Main Hallway	W4	Flaking	110	N	N	0	Y - 86 SF Bulletin Boards, Posters	N	5 Locations; Additional Cracking
361	2340	1	0	1	Primary	Music Room 2	W1	Partially Inaccessible	0	N	N	0	Y - 160 SF Bulletin Board, Posters	N	
362	2340	1	0	1	Primary	Music Room 2	W2	Partially Inaccessible	0	N	N	0	Y - 110 SF Desks, Posters	N	
363	2340	1	0	1	Primary	Music Room 2	W3	Partially Inaccessible	0	N	N	0	Y - 72 SF Posters	N	

