

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
30	2590	1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
31	2590	1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	paint entire room
32	2590	1	4	402A	Storage	Classroom 402 Closet	W4	Efflorescence behind cabinet	3	Yes	No	N/A	Furniture	Yes	paint closet
33	2590	1	4	403A	Storage	Classroom 403 Closet	Floor	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	paint entire classroom and closet
34	2590	1	4	403A	Storage	Classroom 403 Closet	W1	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	
35	2590	1	4	403A	Storage	Classroom 403 Closet	W2	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	
36	2590	1	4	403A	Storage	Classroom 403 Closet	W3	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	
37	2590	1	4	403A	Storage	Classroom 403 Closet	W4	Flaking	1	No	No	N/A	Stored Materials	No	
38	2590	1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	Ceiling	Cracking	6	No	No	N/A	N/A	Yes	paint entire space
39	2590	1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	W1	Cracking	3	No	No	N/A	N/A	No	
40	2590	1	4	403B	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	W2	Holes	2	No	No	N/A	N/A	Yes	
41	2590	1	4	404A	Storage	Classroom 404 Closet	W2	Flaking, Coat hooks pulling off wall	10	No	No	N/A	Stored Materials	Yes	paint entire room storage
42	2590	1	4	404A	Storage	Classroom 404 Closet	W3	Cracking, Flaking	5	No	No	N/A	Stored Materials	No	
43	2590	1	4	404A	Storage	Classroom 404 Closet	W4	Flaking	5	No	No	N/A	Shelving, Stored Materials	No	
44	2590	1	4	405A	Storage	Classroom 405 Closet	W1	Cracking	1	No	No	N/A	N/A	No	paint entire closet
45	2590	1	4	405A	Storage	Classroom 405 Closet	W2	Chipping, Gouges, Coat hooks pulling off wall	9	No	No	N/A	N/A	Yes	
46	2590	1	4	405A	Storage	Classroom 405 Closet	W3	Flaking	5	No	No	N/A	N/A	No	paint entire closet
47	2590	1	4	405A	Storage	Classroom 405 Closet	W4	Cracking, Flaking	8	No	No	N/A	N/A	No	
48	2590	1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	W1	Flaking	5	No	No	N/A	N/A	No	PAIN ENTIRE ROOM
49	2590	1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	W2	Flaking	50	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
50	2590	1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	W3	Flaking, Spalling	10	Yes	No	N/A	N/A	Yes	
51	2590	1	4	406A	Administrative Office	Room 404A Office Adjacent to Classroom 405	W4	Flaking	15	No	No	N/A	N/A	No	
52	2590	1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	W1	Cracking, Hole	3	No	No	N/A	N/A	Yes	PAINTE ENTIRE 406 ROOM
53	2590	1	4	406AB	Restrooms, Staff - Male/Female	Restroom in Room 404A Office Adjacent to Classroom 405	W3	Cracking, Spalling	2	Yes	No	N/A	N/A	Yes	
54	2590	1	4	406B	Storage	Classroom 406 Closet	W2	Flaking, Coat hooks pulling off wall	11	No	No	No	N/A	No	The back half of this closet needs to be inspected
55	2590	1	4	406B	Storage	Classroom 406 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This wall needs to be inspected
56	2590	1	4	406B	Storage	Classroom 406 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	7	No	No	No	N/A	No	The back half of this closet needs to be inspected
57	2590	1	4	407A	Storage	Library (Room 407 Side Closet)	W1	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	PAINTE ENTIRE STORAGE
58	2590	1	4	407A	Storage	Library (Room 407 Side Closet)	W2	Efflorescence	5	Yes	No	N/A	Stored Materials	Yes	This wall needs to be fully inspected
59	2590	1	4	407A	Storage	Library (Room 407 Side Closet)	W3	Flaking	40	No	No	N/A	Stored Materials	No	This wall needs to be fully inspected
60	2590	1	4	407A		Library (Room 407 Side Closet)	W4	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	This wall needs to be fully inspected
61	2590	1	4	408A		Library (Room 408 Side Closet)	W2	Efflorescence	20	Yes	No	N/A	N/A	Yes	PAINTE ENTIRE ROOM
62	2590	1	4	408A		Library (Room 408 Side Closet)	W3	Efflorescence	10	Yes	No	N/A	N/A	Yes	
63	2590	1	4	H415	Circulation (Hallway)	Hallway along IMC	Ceiling	Efflorescence above windows	1	Yes	No	N/A	N/A	Yes	Paint entire hallway (U-Shaped) 4th floor
64	2590	1	4	H415	Circulation (Hallway)	Hallway along IMC	W2	Flaking, Spalling, Significant Moisture Damage, some behind radiators	65	Yes	Debris on Windowsills	3	N/A	Yes	
65	2590	1	4	H415	Circulation (Hallway)	Hallway along IMC	W3	Flaking	3	No	No	N/A	N/A	No	
66	2590	1	4	H415	Circulation (Hallway)	Hallway along IMC	W4	Flaking	3	No	No	N/A	N/A	No	
67	2590	1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	Ceiling	Spalling, Efflorescence, Significant Moisture Damage above windows	13	Yes	No	N/A	N/A	Yes	
68	2590	1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W1	Flaking	20	No	No	N/A	N/A	No	
69	2590	1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W2	Flaking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
70	2590	1	4	H416	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W3	Flaking, Spalling, Efflorescence	21	Yes	Debris on Windowsills	10	N/A	Yes	
71	2590	1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	Ceiling	Flaking, Plastering Repair paint is stabilized	11	No	No	N/A	N/A	Yes	
72	2590	1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	W2	Flaking	15	No	No	N/A	N/A	No	
73	2590	1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	W3	Flaking	5	No	No	N/A	N/A	No	
74	2590	1	4	H417	Circulation (Hallway)	Hallway from Room 401 to Room 402	W4	Flaking, Spalling, some behind radiators	45	Yes	No	N/A	N/A	Yes	
75	2590	1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	Ceiling	Cracking, Flaking	15	No	No	N/A	N/A	No	paint entire stairway 4th thru basement
76	2590	1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	Floor	Chipping on railing	40	No	No	N/A	N/A	No	
77	2590	1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	W2	Flaking	5	No	No	N/A	N/A	No	
78	2590	1	4	S41	Stairs	4th Floor Stairwell Across from Classroom 406	W3	Chipping, Flaking behind radiator	11	No	No	N/A	N/A	No	
79	2590	1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	Floor	Chipping on railing	40	No	No	N/A	N/A	No	paint entire stairway 4th thru basement
80	2590	1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	W1	Flaking	1	No	No	N/A	N/A	No	
81	2590	1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	W3	Flaking behind radiator	10	No	No	N/A	N/A	No	
82	2590	1	4	S42	Stairs	4th Floor Stairwell Across from Classroom 404	W4	Flaking	5	No	No	N/A	N/A	No	
83	2590	1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	Floor	Flaking	5	No	No	N/A	N/A	No	paint entire stairway 4th thru basement
84	2590	1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	W2	Chipping on door	2	No	No	N/A	N/A	No	
85	2590	1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	W3	Flaking on bars	25	No	No	N/A	N/A	No	
86	2590	1	4	S43	Stairs	4th Floor Fire Tower near Classroom 401	W4	Flaking on bars	50	No	No	N/A	N/A	No	
87	2590	1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	Floor	Flaking	5	No	No	N/A	N/A	No	paint entire stairway 4th thru basement
88	2590	1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	W2	Flaking on bars	50	No	No	N/A	N/A	No	
89	2590	1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	W3	Flaking on bars	25	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
90	2590	1	4	S44	Stairs	4th Floor Fire Tower near IMC (Room 408)	W4	Flaking on door	2	No	No	N/A	N/A	No	
91	2590	1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	W1	Hole	1	No	No	N/A	Posters	Yes	paint entire room
92	2590	1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	W3	Flaking behind radiator	5	No	No	N/A	Posters	No	
93	2590	1	3	300	Teacher Lounge/Dining	Room 305A Former Teacher's Lounge	W4	Flaking	30	No	No	N/A	Posters	No	
94	2590	1	3	301	Primary	Classroom 301	W1	Flaking	10	No	No	N/A	Posters, Furniture	No	pioant entire room with line goig through
95	2590	1	3	301	Primary	Classroom 301	W3	Flaking, some behind radiator, Spalling	30	Yes	No	N/A	Posters, Furniture	Yes	
96	2590	1	3	302	Primary	Classroom 302	W1	Flaking above door	2	No	No	N/A	Posters	No	paint entire room
97	2590	1	3	302	Primary	Classroom 302	W3	Flaking, Spalling	15	Yes	No	N/A	Posters, Furniture	Yes	
98	2590	1	3	303	Primary	Classroom 303	W1	Flaking below board	5	No	No	N/A	Posters, Furniture	No	paint entire room
99	2590	1	3	303	Primary	Classroom 303	W2	Cracking, Flaking	1	No	No	N/A	Posters, Furniture	No	
100	2590	1	3	303	Primary	Classroom 303	W3	Chipping, Flaking	20	No	Debris on Windowsills	5	Posters, Furniture	No	
101	2590	1	3	303	Primary	Classroom 303	W4	Flaking	15	No	No	N/A	Posters, Furniture	No	
102	2590	1	3	304	Primary	Classroom 304	W3	Flaking, Spalling	20	Yes	No	N/A	N/A	Yes	all walls have damages
103	2590	1	3	305	Primary	Classroom 305	W3	Spalling	10	Yes	Debris on Windowsills	5	Posters, Furniture	Yes	all walls have damages
104	2590	1	3	305	Primary	Classroom 305	W4	Flaking near entrance	1	No	No	N/A	Posters, Furniture	No	
105	2590	1	3	306	Primary	Classroom 306	W2	Flaking, some behind bookshelves	10	No	No	N/A	Posters, Furniture	No	all walls have damages
106	2590	1	3	306	Primary	Classroom 306	W3	Flaking behind bookshelf and radiator	15	No	Debris on window behind safety screen	1	Posters, Furniture	No	
107	2590	1	3	307	Primary	Classroom 307	W1	Cracking, Chipping	3	No	No	N/A	Posters, Furniture, Instruments	Yes	paint entire room
108	2590	1	3	307	Primary	Classroom 307	W2	Cracking	2	No	No	N/A	Posters, Furniture, Instruments	No	
109	2590	1	3	307	Primary	Classroom 307	W3	Flaking, Spalling, Efflorescence	40	Yes	Debris on Windowsills	5	Posters, Furniture, Instruments	Yes	
110	2590	1	3	308	Primary	Classroom 308	W1	Chipping	2	No	No	N/A	Posters, Furniture	No	paint entire room
111	2590	1	3	308	Primary	Classroom 308	W3	Flaking, Spalling	25	Yes	No	N/A	Posters, Furniture	Yes	
112	2590	1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	Ceiling	Cracking, Flaking	4	No	No	N/A	N/A	No	paint entire room
113	2590	1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W1	Cracking	3	No	No	N/A	N/A	No	
114	2590	1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W2	Flaking	1	No	No	N/A	N/A	No	
115	2590	1	3	309	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 306	W3	Flaking	1	No	No	N/A	N/A	No	
116	2590	1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	Ceiling	Flaking	3	No	No	N/A	Stored Materials	No	already painting entire room innprevius lines

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
117	2590	1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	W1	Cracking, Hole	11	No	No	N/A	Stored Materials	Yes	
118	2590	1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	W2	Holes	2	No	No	N/A	Stored Materials	Yes	
119	2590	1	3	300A	Satellite Kitchen	Room 305A Teacher's Lounge Former Kitchenette	W3	Flaking, Holes	8	No	No	N/A	Stored Materials	Yes	
120	2590	1	3	301A	Storage	Classroom 301 Closet	W2	Flaking	5	No	No	N/A	N/A	No	already painting entire room in a previous line
121	2590	1	3	301A	Storage	Classroom 301 Closet	W3	Flaking	10	No	No	N/A	N/A	No	
122	2590	1	3	301A	Storage	Classroom 301 Closet	W4	Flaking	5	No	No	N/A	N/A	No	
123	2590	1	3	302A	Storage	Classroom 302 Closet	W2	Cracking	5	No	No	N/A	N/A	No	already painting entire room in previous lines
124	2590	1	3	302A	Storage	Classroom 302 Closet	W4	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Stored Materials	No	This wall needs to be fully inspected
125	2590	1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	Ceiling	Cracking, Flaking	6	No	No	N/A	N/A	No	paint entire bathroom
126	2590	1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	W1	Cracking	3	No	No	N/A	N/A	Yes	
127	2590	1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	W2	Cracking	5	No	No	N/A	N/A	No	
128	2590	1	3	303A	Student Restrooms - Male (4-12)	Boy's Restroom next to Elevator	W4	Cracking, Flaking	12	No	No	N/A	N/A	No	
129	2590	1	3	303B	Storage	Classroom 303 Closet	W2	Flaking	10	No	Debris on hook rail	2	N/A	No	PAINTE ENTIRE STORAGE
130	2590	1	3	304A	Storage	Classroom 304 Closet	W2	Flaking, Spalling	2	Yes	No	N/A	Stored Materials, Furniture	Yes	
131	2590	1	3	304A	Storage	Classroom 304 Closet	W4	Coat hooks pulling off wall	10	No	No	N/A	N/A	Yes	
132	2590	1	3	305A	Storage	Classroom 305 Closet	Ceiling	Flaking above missing ceiling tile	4	No	No	N/A	N/A	No	
133	2590	1	3	305A	Storage	Classroom 305 Closet	W2	Spalling above missing ceiling tile	1	Yes	No	N/A	N/A	Yes	
134	2590	1	3	306A	Storage	Classroom 306 Closet	W2	Flaking, Coat hooks pulling off wall	5	No	No	N/A	Stored Materials	Yes	
135	2590	1	3	306A	Storage	Classroom 306 Closet	W3	Flaking	2	No	No	N/A	Stored Materials	No	
136	2590	1	3	306A	Storage	Classroom 306 Closet	W4	Coat hooks pulling off wall	10	No	No	N/A	Stored Materials	Yes	
137	2590	1	3	307A	Storage	Classroom 307 Closet	W1	Flaking	5	No	No	N/A	Stored Materials	No	
138	2590	1	3	307A	Storage	Classroom 307 Closet	W2	Flaking, Significant Moisture Damage, Coat hooks pulling off wall	9	Yes	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
139	2590	1	3	307A	Storage	Classroom 307 Closet	W3	Flaking	10	No	No	N/A	Stored Materials	No	
140	2590	1	3	307A	Storage	Classroom 307 Closet	W4	Limited inspection due to stored materials. No damage on visible areas.	N/A	No	No	N/A	Cabinets, Shelves	No	This wall needs to be fully inspected
141	2590	1	3	308A	Storage	Classroom 308 Closet	W2	Coat hooks pulling off wall	5	No	No	N/A	Stored Materials	Yes	
142	2590	1	3	308A	Storage	Classroom 308 Closet	W4	Coat hooks pulling off wall	10	No	No	N/A	Stored Materials	Yes	
143	2590	1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	Ceiling	Efflorescence above windows	3	Yes	No	N/A	N/A	Yes	paint entire U-Shape hallway
144	2590	1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	W2	Flaking, Spalling	15	Yes	No	N/A	N/A	Yes	
145	2590	1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	W3	Flaking	1	No	No	N/A	N/A	No	
146	2590	1	3	H312	Circulation (Hallway)	Hallway along Classrooms 307 and 308	W4	Holes, Flaking	12	No	No	N/A	N/A	Yes	
147	2590	1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W1	Flaking	1	No	No	N/A	N/A	No	
148	2590	1	3	H313	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W3	Flaking, some behind radiators, Spalling	33	Yes	No	N/A	N/A	Yes	
149	2590	1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	Ceiling	Spalling	1	Yes	No	N/A	N/A	Yes	
150	2590	1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	W2	Flaking	5	No	No	N/A	N/A	No	
151	2590	1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	W3	Flaking	2	No	No	N/A	N/A	No	
152	2590	1	3	H314	Circulation (Hallway)	Hallway along Classrooms 301 and 302	W4	Flaking, some behind radiators, Spalling	33	Yes	No	N/A	N/A	Yes	
153	2590	1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	Floor	Chipping on railings	40	No	No	N/A	N/A	No	for time already allocated
154	2590	1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	W2	Flaking	5	No	No	N/A	N/A	No	
155	2590	1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	W3	Flaking, most behind radiator	22	No	No	N/A	N/A	No	
156	2590	1	3	S31	Stairs	3rd Floor Stairwell near Classroom 306	W4	Flaking	5	No	No	N/A	N/A	No	
157	2590	1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	Ceiling	Flaking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
158	2590	1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	Floor	Chipping on railings	40	No	No	N/A	N/A	No	
159	2590	1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	W2	Flaking, Spalling	3	Yes	No	N/A	N/A	Yes	
160	2590	1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	W3	Flaking, some behind radiator	15	No	No	N/A	N/A	No	
161	2590	1	3	S32	Stairs	3rd Floor Stairwell across from Classroom 304	W4	Flaking	2	No	No	N/A	N/A	No	
162	2590	1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	Ceiling	Spalling	10	Yes	No	N/A	N/A	Yes	
163	2590	1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	Floor	Flaking	5	No	Debris	1	N/A	No	
164	2590	1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	W2	Flaking	2	No	No	N/A	N/A	No	
165	2590	1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	W3	Flaking on bars	25	No	No	N/A	N/A	No	
166	2590	1	3	S33	Stairs	3rd Floor Fire Tower near Classroom 301	W4	Flaking on bars	50	No	No	N/A	N/A	No	
167	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	Ceiling	Flaking	1	No	No	N/A	N/A	No	
168	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	Floor	Flaking	5	No	No	N/A	N/A	No	
169	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	W1	Flaking	5	No	No	N/A	N/A	No	
170	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	W2	Flaking on bars	50	No	No	N/A	N/A	No	
171	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	W3	Flaking on bars	25	No	No	N/A	N/A	No	
172	2590	1	3	S34	Stairs	3rd Floor Fire Tower near Classroom 308	W4	Flaking	5	No	No	N/A	N/A	No	
173	2590	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	Ceiling	Cracking, Flaking	20	No	No	N/A	N/A	Yes	paint entire room
174	2590	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	W1	Cracking	10	No	No	N/A	N/A	No	
175	2590	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	W2	Cracking	5	No	No	N/A	N/A	No	
176	2590	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom near Elevator	W3	Flaking	1	No	No	N/A	N/A	No	
177	2590	1	2	201	Primary	Classroom 201	W1	Flaking	5	No	No	N/A	Posters, Furniture	No	paint entire room
178	2590	1	2	201	Primary	Classroom 201	W3	Chipping, Flaking	10	No	No	N/A	Posters, Furniture	No	
179	2590	1	2	202	Primary	Classroom 202	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	y but how could they get to the restroom and not get to the room?
180	2590	1	2	202	Primary	Classroom 202	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
181	2590	1	2	202	Primary	Classroom 202	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
182	2590	1	2	202	Primary	Classroom 202	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
183	2590	1	2	202	Primary	Classroom 202	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
184	2590	1	2	202	Primary	Classroom 202	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
185	2590	1	2	203	ESE Full Time	Classroom 203	W1	Flaking	10	No	No	N/A	Posters, Furniture	No	paint entire room
186	2590	1	2	203	ESE Full Time	Classroom 203	W3	Flaking	10	No	No	N/A	Posters, Furniture	No	
187	2590	1	2	203	ESE Full Time	Classroom 203	W4	Cracking, Flaking, Spalling, Significant Water Damage	30	Yes	No	N/A	Posters, Furniture	Yes	
188	2590	1	2	204	Administrative Office	Room 204 Teacher's Office	Ceiling	Flaking above missing ceiling tile	3	No	No	N/A	N/A	No	paint office complete
189	2590	1	2	204	Administrative Office	Room 204 Teacher's Office	W3	Flaking	10	No	No	N/A	N/A	No	
190	2590	1	2	205	Administrative Office	Room 205 Counselor's Office	W3	Flaking behind Radiator	10	No	No	N/A	N/A	No	paint one window wall
191	2590	1	2	206	Primary	Classroom 206	W1	Cracking, Flaking	3	No	No	N/A	Posters	No	paint entire classroom
192	2590	1	2	206	Primary	Classroom 206	W2	Flaking, Spalling	22	Yes	No	N/A	Posters	No	
193	2590	1	2	206	Primary	Classroom 206	W3	Flaking behind radiators, cabinets, and shelves	30	No	No	N/A	Posters, Furniture	No	
194	2590	1	2	207	Primary	Classroom 207	W2	Spalling	3	Yes	No	N/A	Posters	Yes	
195	2590	1	2	207	Primary	Classroom 207	W3	Flaking, some behind radiator	10	No	No	N/A	Posters, Furniture	No	
196	2590	1	2	208	Administrative Office	Room 208 ESOL Office	W2	Spalling	1	Yes	No	N/A	Posters, Furniture	Yes	
197	2590	1	2	208	Administrative Office	Room 208 ESOL Office	W3	Flaking	20	No	No	N/A	Posters, Furniture	No	
198	2590	1	2	222	Storage	Storage Room across from the Teacher's Lounge	Ceiling	Cracking	10	No	No	N/A	Stored Materials	Yes	
199	2590	1	2	222	Storage	Storage Room across from the Teacher's Lounge	W1	Hole, Flaking on doorframe	3	No	No	N/A	Stored Materials	Yes	
200	2590	1	2	222	Storage	Storage Room across from the Teacher's Lounge	W2	Cracking	10	No	No	N/A	Stored Materials	Yes	
201	2590	1	2	222	Storage	Storage Room across from the Teacher's Lounge	W3	Hole	<1	No	No	N/A	Stored Materials	Yes	
202	2590	1	2	222	Storage	Storage Room across from the Teacher's Lounge	W4	Cracking	5	No	No	N/A	Stored Materials	Yes	
203	2590	1	2	201A	Storage	Classroom 201 Closet	W4	Flaking	3	No	No	N/A	Stored Materials	No	
204	2590	1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	W3	Flaking, Significant Moisture Damage behind toilet	6	No	No	N/A	N/A	Yes	
205	2590	1	2	202A	Student Restrooms - Male/Female (Classroom)	Classroom 202 Restroom	W4	Flaking, Spalling, Significant Moisture Damage	10	Yes	No	N/A	N/A	Yes	
206	2590	1	2	202B	Storage	Classroom 202 Closet	W3	Flaking	5	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
207	2590	1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	Ceiling	Flaking	1	No	No	N/A	N/A	No	
208	2590	1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	W1	Cracking	3	No	No	N/A	N/A	No	
209	2590	1	2	203A	Student Restrooms - Male/Female (Classroom)	Classroom 203 Restroom	W2	Cracking, Significant Water Damage	4	Yes	No	N/A	N/A	Yes	
210	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
211	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
212	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
213	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
214	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
215	2590	1	2	203B	Data Processing Equipment	Computer Server Room next to Classroom 203	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
216	2590	1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	W1	Flaking	1	No	No	N/A	N/A	No	
217	2590	1	2	204A	Administrative Office	Office Adjacent to Teacher's Lounge	W2	Flaking, Efflorescence, some behind radiator	22	Yes	No	N/A	N/A	No	
218	2590	1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	W1	Flaking	2	No	No	N/A	N/A	No	
219	2590	1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	W2	Flaking, Spalling	3	Yes	No	N/A	N/A	Yes	
220	2590	1	2	204B	Storage	Room 204 Teacher's Office Rear Closet	W4	Flaking	5	No	No	N/A	N/A	No	
221	2590	1	2	204C	Storage	Room 204A Office Closet	W1	Hole	1	No	No	N/A	N/A	Yes	
222	2590	1	2	204C	Storage	Room 204A Office Closet	W3	Hole	1	No	No	N/A	N/A	Yes	
223	2590	1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	W1	Cracking, Flaking	2	No	No	N/A	N/A	No	
224	2590	1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	W2	Flaking	40	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
225	2590	1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	W3	Flaking, Efflorescence	20	Yes	Debris on Windowsills	5	N/A	Yes	
226	2590	1	2	205A	Teacher Lounge/Dining	Room 204 A Teacher's Lounge	W4	Flaking	20	No	No	N/A	Posters	No	
227	2590	1	2	205B	Restrooms, Staff - Male/Female	Faculty Restroom in Room 204A Teacher's Lounge	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
228	2590	1	2	205B	Restrooms, Staff - Male/Female	Faculty Restroom in Room 204A Teacher's Lounge	W1	Hole	1	No	No	N/A	N/A	Yes	
229	2590	1	2	206A	Administrative Office	Room 206A Counselor's Office	W1	Flaking behind cabinet	2	No	No	N/A	Furniture	No	
230	2590	1	2	206A	Administrative Office	Room 206A Counselor's Office	W3	Flaking, some behind radiator	20	No	No	N/A	N/A	No	
231	2590	1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	W1	Flaking	2	No	No	N/A	N/A	No	
232	2590	1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	W2	Flaking	12	No	No	N/A	N/A	No	Paint entire hallway (U-Shaped) 4th floor
233	2590	1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	W3	Cracking, Flaking	6	No	No	N/A	N/A	No	
234	2590	1	2	206B	Circulation (Hallway)	Hallway between Rooms 205 and 206A	W4	Flaking	5	No	No	N/A	N/A	No	
235	2590	1	2	206C	Storage	Classroom 206 Closet	W1	Spalling above door	2	No	No	N/A	N/A	No	
236	2590	1	2	206C	Storage	Classroom 206 Closet	W2	Spalling	1	No	No	N/A	Stored Materials	No	
237	2590	1	2	206C	Storage	Classroom 206 Closet	W3	Limited inspection due to stored materials. No damage to visible areas.	N/A	No	No	N/A	Stored Materials	No	This wall will need to be completely inspected
238	2590	1	2	207A	Storage	Classroom 207 Closet	W3	Cracking	2	No	No	N/A	N/A	No	
239	2590	1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	Ceiling	Flaking, Spalling	21	Yes	No	N/A	N/A	Yes	
240	2590	1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	Floor	Chipping	1	No	No	N/A	N/A	No	
241	2590	1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	W1	Cracking	5	No	No	N/A	N/A	No	
242	2590	1	2	207B	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 206	W4	Flaking	1	No	No	N/A	N/A	No	
243	2590	1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	W1	Chipping	1	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
244	2590	1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	W2	Flaking	5	No	No	N/A	N/A	No	
245	2590	1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	W3	Significant Moisture Damage behind toilets	10	No	No	N/A	N/A	Yes	
246	2590	1	2	208A	Student Restrooms - Male/Female (Classroom)	Classroom 208 Restroom	W4	Flaking	2	No	No	N/A	N/A	No	
247	2590	1	2	208B	Storage	Classroom 208 Closet	W1	Flaking	2	No	No	N/A	N/A	No	
248	2590	1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	W2	Flaking, some behind radiators	55	No	No	N/A	N/A	No	
249	2590	1	2	H209	Circulation (Hallway)	Hallway along Classrooms 207 and 208	W4	Spalling	2	Yes	No	N/A	N/A	Yes	
250	2590	1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	W2	Flaking	15	No	No	N/A	N/A	No	
251	2590	1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	W3	Flaking	1	No	No	N/A	N/A	No	
252	2590	1	2	H210	Circulation (Hallway)	Hallway along Classrooms 201 and 202	W4	Flaking, Efflorescence, Significant Moisture Damage, some of each behind radiators	59	Yes	No	N/A	N/A	Yes	
253	2590	1	2	H211	Circulation (Hallway)	Hallway from Girl's Restroom to Boy's Restroom	W1	Flaking	10	No	No	N/A	N/A	No	
254	2590	1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	Ceiling	Flaking	10	No	No	N/A	N/A	No	above
255	2590	1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	Floor	Chipping on stairs and railings	60	No	No	N/A	N/A	No	
256	2590	1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	W2	Cracking, Chipping, Flaking	6	No	No	N/A	N/A	No	
257	2590	1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	W3	Flaking, Significant Moisture Damage some of both behind radiator	12	Yes	No	N/A	N/A	Yes	
258	2590	1	2	S21	Stairs	2nd Floor Stairwell across from Classroom 206	W4	Loose wood rail	3	No	No	N/A	N/A	No	
259	2590	1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	Ceiling	Flaking	30	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
260	2590	1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	Floor	Chipping on stairs and railings	41	No	No	N/A	N/A	No	
261	2590	1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	W2	Flaking	2	No	No	N/A	N/A	No	
262	2590	1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	W3	Significant Moisture Damage behind radiator	20	Yes	No	N/A	N/A	Yes	
263	2590	1	2	S22	Stairs	2nd Floor Stairwell across from Classroom 204	W4	Flaking	1	No	No	N/A	N/A	No	
264	2590	1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	Ceiling	Flaking	2	No	No	N/A	N/A	No	same hours
265	2590	1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	W2	Flaking on door	2	No	No	N/A	N/A	No	
266	2590	1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	W3	Flaking on bars	25	No	No	N/A	N/A	No	
267	2590	1	2	S23	Stairs	2nd Floor Fire Tower near Classroom 201	W4	Flaking on bars	50	No	No	N/A	N/A	No	
268	2590	1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	Floor	Flaking	10	No	No	N/A	N/A	No	
269	2590	1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	W1	Flaking	10	No	No	N/A	N/A	No	
270	2590	1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	W2	Flaking on bars	50	No	No	N/A	N/A	No	
271	2590	1	2	S24	Stairs	2nd Floor Fire Tower near Classroom 208	W3	Flaking on bars	25	No	No	N/A	N/A	No	
272	2590	1	2	S26	Storage	Storage Area above Stage Right	Ceiling	Cracking, Hole	20	No	No	N/A	Instruments	Yes	
273	2590	1	2	S26	Storage	Storage Area above Stage Right	W1	Flaking	2	No	No	N/A	Instruments	No	
274	2590	1	2	S26	Storage	Storage Area above Stage Right	W2	Flaking	2	No	No	N/A	Instruments	No	
275	2590	1	2	S26	Storage	Storage Area above Stage Right	W3	Flaking behind radiator	20	No	Debris on Windowsill	5	Instruments	No	
276	2590	1	2	S26A		Stairs to Storage Area above Stage Right	W2	Flaking	1	No	No	N/A	N/A	No	
277	2590	1	2	S26A		Stairs to Storage Area above Stage Right	W4	Cracking, Efflorescence	2	Yes	No	N/A	N/A	Yes	
278	2590	1	2	S26B		Storage Area above Stage Right Closet	W3	Spalling	10	Yes	No	N/A	Instruments	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
279	2590	1	2	S26B		Storage Area above Stage Right Closet	W4	Cracking, Flaking	10	No	No	N/A	Instruments	No	
280	2590	1	2	S27	Storage	Storage Area above Stage Left	Ceiling	Cracking, Efflorescence	5	Yes	No	N/A	Instruments	Yes	
281	2590	1	2	S27	Storage	Storage Area above Stage Left	W2	Spalling	3	Yes	No	N/A	Door, Stored Containers	Yes	
282	2590	1	2	S27	Storage	Storage Area above Stage Left	W3	Spalling	7	Yes	No	N/A	Instruments	Yes	
283	2590	1	2	S27A		Stairs to Storage Area above Stage Left	W3	Spalling	5	Yes	No	N/A	N/A	Yes	
284	2590	1	2	S27A		Stairs to Storage Area above Stage Left	W4	Spalling	10	Yes	No	N/A	N/A	Yes	
285	2590	1	2	S27B		Storage Area above Stage Left Closet	Ceiling	Efflorescence	2	Yes	No	N/A	Instruments	Yes	
286	2590	1	2	S27B		Storage Area above Stage Left Closet	W2	Cracking	1	No	No	N/A	Instruments	No	
287	2590	1	2	S27B		Storage Area above Stage Left Closet	W3	Flaking, Efflorescence	5	Yes	No	N/A	Instruments	Yes	
288	2590	1	1	101	Administrative Office	CATCH Program	W1	Cracking, Hole, Flaking	5	No	No	N/A	N/A	Yes	
289	2590	1	1	101	Administrative Office	CATCH Program	W2	Flaking	2	No	No	N/A	N/A	No	
290	2590	1	1	101	Administrative Office	CATCH Program	W3	Flaking, some behind painting and radiator	25	No	No	N/A	Painting	No	
291	2590	1	1	102	Primary	Classroom 102 Kindergarten	W3	Cracking, Flaking, Significant Moisture Damage	8	Yes	No	N/A	Posters, Furniture	Yes	
292	2590	1	1	103	Primary	Classroom 103	W1	Cracking, Chipping, Flaking	9	No	No	N/A	Posters, Furniture	No	PAIN ENTIRE ROOM
293	2590	1	1	103	Primary	Classroom 103	W2	Flaking	5	No	No	N/A	Posters, Furniture	No	
294	2590	1	1	103	Primary	Classroom 103	W3	Flaking	10	No	No	N/A	Furniture	No	
295	2590	1	1	103	Primary	Classroom 103	W4	Flaking	5	No	No	N/A	Posters, Furniture	No	
296	2590	1	1	104	Primary	Classroom 104	W1	Cracking, Flaking	8	No	No	N/A	Posters, Furniture	Yes	PAIN ENTIRE ROOM
297	2590	1	1	104	Primary	Classroom 104	W3	Flaking, Significant Moisture Damage	40	Yes	Debris on Windowsills	5	Posters, Furniture	Yes	
298	2590	1	1	105	Primary	Classroom 105	W2	Cracking, Flaking	8	No	No	N/A	Posters, Furniture	No	
299	2590	1	1	105	Primary	Classroom 105	W3	Flaking	10	No	No	N/A	Posters, Furniture	No	
300	2590	1	1	105	Primary	Classroom 105	W4	Flaking below board	2	No	No	N/A	Posters, Furniture	No	
301	2590	1	1	106	Primary	Classroom 106	W3	Flaking	25	No	No	N/A	Posters, Furniture	No	
302	2590	1	1	107	Primary	Classroom 107	W1	Chipping by Door	1	No	No	N/A	Posters	No	
303	2590	1	1	107	Primary	Classroom 107	W3	Flaking	10	No	No	N/A	Posters, Furniture	No	
304	2590	1	1	108	Administrative Office	Principal's Office	W4	Missing Chair Rail	2	No	No	N/A	Furniture	Yes	
305	2590	1	1	110	Administrative Office	Nurse's Office	Ceiling	Significant moisture damage along windows	8	Yes	No	N/A	N/A	Yes	
306	2590	1	1	110	Administrative Office	Nurse's Office	W1	Cracking near restroom	3	No	No	N/A	N/A	No	
307	2590	1	1	110	Administrative Office	Nurse's Office	W3	Flaking on metal pipe	5	No	Debris on windowsill	3	Furniture	No	
308	2590	1	1	100A Stage	Stage	Stage	Ceiling	Efflorescence	25	Yes	No	N/A	Ladders, tables	Yes	
309	2590	1	1	100A Stage	Stage	Stage	W1	Flaking on metal above curtain	15	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
310	2590	1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W3	Spalling	2	No	No	N/A	N/A	Yes	
311	2590	1	1	102 B	Student Restrooms - Male/Female (Classroom)	Classroom 102 Restroom	W4	Flaking	7	No	No	N/A	N/A	No	
312	2590	1	1	102C	Storage	Classroom 102 Closet	W2	Cracking	5	No	No	N/A	Contents	No	
313	2590	1	1	102C	Storage	Classroom 102 Closet	W4	Flaking, Coat hooks pulling off wall	12	No	No	N/A	Contents	Yes	
314	2590	1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	W2	Cracking	20	No	No	N/A	N/A	No	
315	2590	1	1	103A	Student Restrooms - Male (4-12)	Boy's Restroom next to Classroom 103	W4	Spalling by toilets	25	No	No	N/A	N/A	Yes	
316	2590	1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	Ceiling	Cracking above door, flaking on metal duct	6	No	No	N/A	N/A	Yes	
317	2590	1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W1	Flaking	1	No	No	N/A	N/A	No	
318	2590	1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W2	Flaking, Significant Moisture Damage	7	Yes	No	N/A	N/A	Yes	
319	2590	1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W3	Flaking	3	No	No	N/A	N/A	No	
320	2590	1	1	103B	Student Restrooms - Male/Female (Classroom)	Classroom 103 Restroom	W4	Cracking, Flaking, Spalling	20	No	No	N/A	N/A	Yes	
321	2590	1	1	104A	Student Restrooms - Male/Female (Classroom)	Classroom 104 Restroom	W3	Significant Moisture Damage	10	No	No	N/A	N/A	Yes	
322	2590	1	1	104B	Storage	Classroom 104 Closet	W2	Flaking	1	No	No	N/A	Stored Materials	No	
323	2590	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W1	Cracking	3	No	No	N/A	N/A	No	
324	2590	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking	3	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
325	2590	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W3	Cracking	1	No	No	N/A	N/A	No	
326	2590	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W4	Flaking, Efflorescence	5	Yes	No	N/A	N/A	Yes	
327	2590	1	1	105B	Storage	Classroom 105 Closet	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	Stored Materials	No	
328	2590	1	1	105B	Storage	Classroom 105 Closet	W2	Flaking	10	No	No	N/A	N/A	No	
329	2590	1	1	105B	Storage	Classroom 105 Closet	W4	Flaking, Coat hooks pulling off wall	4	No	No	N/A	Stored Materials	Yes	
330	2590	1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W1	Flaking	5	No	No	N/A	N/A	No	
331	2590	1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W2	Flaking	3	No	No	N/A	N/A	No	
332	2590	1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W4	Significant Moisture Damage	1	No	No	N/A	N/A	Yes	
333	2590	1	1	106B	Storage	Classroom 106 Closet	W1	Coat hooks pulling off wall	7	No	No	N/A	Stored Materials	Yes	
334	2590	1	1	106B	Storage	Classroom 106 Closet	W2	Flaking	1	No	No	N/A	Stored Materials	No	
335	2590	1	1	106B	Storage	Classroom 106 Closet	W3	Flaking	3	No	No	N/A	Stored Materials	No	
336	2590	1	1	106B	Storage	Classroom 106 Closet	W4	Flaking	5	No	No	N/A	Stored Materials	No	
337	2590	1	1	107A	Storage	Classroom 107 Closet	Ceiling	Significant Moisture Damage around drain line	3	Yes	No	N/A	Stored Materials	Yes	
338	2590	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W2	Cracking	5	No	No	N/A	N/A	No	
339	2590	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W3	Cracking	3	No	No	N/A	N/A	No	
340	2590	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W4	Cracking	3	No	No	N/A	N/A	No	
341	2590	1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	Ceiling	Flaking	2	No	No	N/A	N/A	No	
342	2590	1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	W2	Flaking	4	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
343	2590	1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	W3	Flaking, Efflorescence	3	No	No	N/A	N/A	Yes	
344	2590	1	1	108A	Restrooms, Staff - Female	Principal's Office Restroom	W4	Cracking, Flaking	6	No	No	N/A	N/A	Yes	
345	2590	1	1	108B	Storage	Principal's Office Closet	W1	Cracking	5	No	No	N/A	Supplies on shelves	No	
346	2590	1	1	108B	Storage	Principal's Office Closet	W3	Cracking	10	No	No	N/A	Supplies on shelves	No	
347	2590	1	1	109A	Storage	Main Office Closet on Right	Ceiling	Cracking	5	No	No	N/A	No	Yes	
348	2590	1	1	109A	Storage	Main Office Closet on Right	W4	Cracking	1	No	No	N/A	No	Yes	
349	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
350	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
351	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
352	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
353	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
354	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
355	2590	1	1	109C	Storage	Main Office Closet on Left	W2	Cracking	5	No	No	N/A	Supplies on shelves	No	
356	2590	1	1	109C	Storage	Main Office Closet on Left	W3	Cracking	40	No	No	N/A	Supplies on shelves	No	
357	2590	1	1	109C	Storage	Main Office Closet on Left	W4	Cracking	15	No	No	N/A	Supplies on shelves	No	
358	2590	1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	W2	Flaking, Efflorescence behind radiators	32	Yes	No	N/A	N/A	Yes	paint entire U-Shape hallway
359	2590	1	1	H14	Circulation (Hallway)	Hallway along Classrooms 106 and 107	W4	Flaking	7	No	No	N/A	N/A	No	
360	2590	1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	W2	Cracking, Gouges, Flaking	15	No	No	N/A	N/A	No	
361	2590	1	1	H17	Circulation (Hallway)	Hallway along Classrooms 101 and 102	W4	Cracking, Flaking, Efflorescence, some behind radiators	67	Yes	No	N/A	N/A	No	
362	2590	1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	Ceiling	Flaking	1	No	No	N/A	N/A	No	
363	2590	1	1	H18	Circulation (Hallway)	Hallway from Women's Restroom to Nurse's Office	W3	Flaking	1	No	No	N/A	N/A	No	
364	2590	1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	Ceiling	Flaking, Spalling	35	Yes	No	N/A	N/A	Yes	STAIR WAY ABOVE

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
365	2590	1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	Floor	Chipping on Stairs and Railings	50	No	No	N/A	N/A	No	
366	2590	1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	W2	Cracking, Flaking	20	No	No	N/A	N/A	No	
367	2590	1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	W3	Cracking	10	No	No	N/A	N/A	No	
368	2590	1	1	S11	Stairs	1st Floor Stairwell across from Principal's Office	W4	Cracking	30	No	No	N/A	N/A	No	
369	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	Ceiling	Gouges, Flaking	41	No	No	N/A	N/A	No	
370	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	Floor	Chipping on Railings and Door in center	45	No	No	N/A	N/A	No	
371	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	W1	Plaster repair needed but paint is stabilized	1	No	No	N/A	N/A	Yes	
372	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	W2	Flaking	5	No	No	N/A	N/A	No	
373	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	W3	Flaking	3	No	No	N/A	N/A	No	
374	2590	1	1	S12	Stairs	1st Floor Stairwell across from Classroom 104	W4	Flaking behind radiator, missing wood rail	11	No	No	N/A	N/A	No	
375	2590	1	1	S13	Stairs	1st Floor Fire Tower near Room 101	Floor	Flaking	5	No	No	N/A	N/A	No	
376	2590	1	1	S13	Stairs	1st Floor Fire Tower near Room 101	W2	Flaking on wall and door	12	No	No	N/A	N/A	No	
377	2590	1	1	S13	Stairs	1st Floor Fire Tower near Room 101	W3	Flaking on wall and bars	27	No	No	N/A	N/A	No	
378	2590	1	1	S13	Stairs	1st Floor Fire Tower near Room 101	W4	Flaking on bars	50	No	No	N/A	N/A	No	
379	2590	1	1	S14	Stairs	1st Floor Fire Tower near Room 107	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	No	
380	2590	1	1	S14	Stairs	1st Floor Fire Tower near Room 107	Floor	Flaking	15	No	No	N/A	N/A	No	
381	2590	1	1	S14	Stairs	1st Floor Fire Tower near Room 107	W2	Flaking on bars	50	No	No	N/A	N/A	No	
382	2590	1	1	S14	Stairs	1st Floor Fire Tower near Room 107	W3	Flaking, some on bars	27	No	No	N/A	N/A	No	
383	2590	1	1	S14	Stairs	1st Floor Fire Tower near Room 107	W4	Flaking on door	10	No	No	N/A	N/A	No	
384	2590	1	1	S16	Stairs	Stage Right Stair Area	Ceiling	Efflorescence	6	Yes	No	N/A	N/A	Yes	
385	2590	1	1	S16	Stairs	Stage Right Stair Area	W2	Efflorescence	2	Yes	Debris on Windowsill	2	N/A	Yes	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
386	2590	1	1	S16	Stairs	Stage Right Stair Area	W3	Efflorescence	2	Yes	No	N/A	N/A	Yes	
387	2590	1	1	S17	Stairs	Stage Left Stair Area	Ceiling	Efflorescence	15	Yes	No	N/A	N/A	Yes	
388	2590	1	1	S17	Stairs	Stage Left Stair Area	W3	Spalling	5	No	No	N/A	N/A	Yes	
389	2590	1	1	S17	Stairs	Stage Left Stair Area	W4	Efflorescence	2	Yes	Debris on Windowsill	3	N/A	Yes	
390	2590	1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	Ceiling	Cracking	40	No	No	N/A	N/A	No	
391	2590	1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	W1	Flaking	20	No	No	N/A	N/A	No	
392	2590	1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	W2	Cracking	20	No	No	N/A	N/A	No	
393	2590	1	1	S18	Stairs	1st Floor Stairwell next to Main Office (Main Entrance)	W4	Cracking, Flaking	12	No	No	N/A	N/A	No	
394	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
395	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
396	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
397	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
398	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
399	2590	1	0	001	Student Restrooms - Female (4-12)	Girl's Restroom near Kitchen	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
400	2590	1	0	015	Administrative Office	Building Engineer's Office	Ceiling	Flaking	2	No	No	N/A	N/A	No	
401	2590	1	0	015	Administrative Office	Building Engineer's Office	W4	Flaking around air conditioner	1	No	No	N/A	N/A	No	
402	2590	1	0	034	Kitchen	Kitchen	W1	Flaking, Spalling, and Efflorescence on wall, Chipping and Flaking on Door	31	Yes	No	N/A	Stored Materials	Yes	
403	2590	1	0	034	Kitchen	Kitchen	W2	Flaking, Plaster repair paint is stabilized	3	No	No	N/A	Stored Materials	Yes	
404	2590	1	0	034	Kitchen	Kitchen	W3	Efflorescence	15	Yes	No	N/A	Stored Materials	Yes	
405	2590	1	0	034	Kitchen	Kitchen	W4	Cracking, Spalling	2	Yes	No	N/A	Stored Materials	Yes	
406	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	Ceiling	Cracking/loose, Hole, Efflorescence	1430	Yes	No	N/A	N/A	Yes	
407	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	Floor	Chipping Cove Base	200	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
408	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	W1	Chipping on conduit line, Flaking on both sides of doors	31	No	No	N/A	N/A	No	
409	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	W2	Chipping, Flaking	11	No	No	N/A	N/A	No	
410	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	W3	Flaking	5	No	No	N/A	N/A	No	
411	2590	1	0	003B	Gymnasium - Intermediate Middle	Gym/Cafe	W4	Flaking	2	No	No	N/A	N/A	No	
412	2590	1	0	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	Ceiling	Flaking	20	No	No	N/A	N/A	No	
413	2590	1	0	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	Floor	Flaking	30	No	No	N/A	N/A	No	
414	2590	1	0	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	W1	Flaking on wall and both sides of door	35	No	No	N/A	N/A	No	
415	2590	1	0	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	W2	Flaking	20	No	No	N/A	N/A	No	
416	2590	1	0	004B	Student Restrooms - Male (4-12)	Boy's Restroom near B1 Art Room	W3	Flaking	10	No	No	N/A	N/A	No	
417	2590	1	0	006B	Administrative Office	Gym Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
418	2590	1	0	006B	Administrative Office	Gym Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
419	2590	1	0	006B	Administrative Office	Gym Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
420	2590	1	0	006B	Administrative Office	Gym Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
421	2590	1	0	006B	Administrative Office	Gym Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
422	2590	1	0	006B	Administrative Office	Gym Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
423	2590	1	0	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	W1	Efflorescence	30	Yes	No	N/A	Cafeteria Tables	No	
424	2590	1	0	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	W3	Efflorescence	10	Yes	No	N/A	Cafeteria Tables	No	
425	2590	1	0	006C	Storage	Lunch Table Storage Room between Kitchen and Gym	W4	Efflorescence	10	Yes	No	N/A	Cafeteria Tables	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
426	2590	1	0	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	W1	Plaster repair paint is stabilized	3	No	No	N/A	N/A	Yes	
427	2590	1	0	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	W2	Cracking, Flaking	6	No	No	N/A	N/A	No	
428	2590	1	0	006D	Circulation (Hallway)	Hallway Area between Lunch Table Storage Room and Gym	W4	Efflorescence, plaster repair paint in stabilized	15	Yes	No	N/A	N/A	Yes	
429	2590	1	0	007B	Storage	Gym Storage (Now Kitchen)	Ceiling	Flaking	50	No	No	N/A	Kitchen equipment, Stored Materials	No	
430	2590	1	0	007B	Storage	Gym Storage (Now Kitchen)	W1	Chipping, Flaking on wall, door, and doorframe	30	No	No	N/A	Kitchen equipment, Stored Materials	No	
431	2590	1	0	007B	Storage	Gym Storage (Now Kitchen)	W3	Chipping, Flaking	20	No	No	N/A	Kitchen equipment, Stored Materials	No	
432	2590	1	0	007B	Storage	Gym Storage (Now Kitchen)	W4	Chipping, Flaking	10	No	No	N/A	Kitchen equipment, Stored Materials	No	
433	2590	1	0	010B	Administrative Office	Classroom B1 (Art) Rear Storage Area	W1	Holes, Flaking, Efflorescence	9	Yes	No	N/A	N/A	Yes	
434	2590	1	0	010B	storage	Classroom B1 (Art) Rear Storage Area	W2	Flaking, Spalling, Efflorescence	53	Yes	No	N/A	N/A	Yes	
435	2590	1	0	010B	storage	Classroom B1 (Art) Rear Storage Area	W3	Cracking, Holes, Flaking	9	No	No	N/A	Shelves with stored materials	No	This wall needs to be fully inspected
436	2590	1	0	010B	storage	Classroom B1 (Art) Rear Storage Area	W4	Hole, Flaking	6	No	No	N/A	Shelves with stored materials	No	This wall needs to be fully inspected
437	2590	1	0	010BB	Administrative Office	Classroom B1 (Art) Closet within Rear Storage Area	W1	Holes, Significant Moisture Damage	6	Yes	No	N/A	Stored Materials	Yes	
438	2590	1	0	010BB	Administrative Office	Classroom B1 (Art) Closet within Rear Storage Area	W2	Significant Moisture Damage	5	Yes	No	N/A	Stored Materials	Yes	
439	2590	1	0	010BB	Administrative Office	Classroom B1 (Art) Closet within Rear Storage Area	W3	Limited inspection due to stored materials. No damage to visible areas.	N/A	No	No	N/A	Stored Materials	No	This wall needs to be fully inspected
440	2590	1	0	010BB	Administrative Office	Classroom B1 (Art) Closet within Rear Storage Area	W4	Limited inspection due to stored materials. No damage to visible areas.	N/A	No	No	N/A	Stored Materials	No	This wall needs to be fully inspected
441	2590	1	0	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	Ceiling	Cracking	3	No	No	N/A	N/A	No	
442	2590	1	0	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	W4	Cracking, Flaking, Spalling	6	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
443	2590	1	0	015A	Circulation (Hallway)	Hallway Area between Building Engineer's Office and Gym	W1	Cracking, Flaking	10	No	No	N/A	N/A	No	
444	2590		0	034A	Storage	Kitchen Office/Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
445	2590		0	034A	Storage	Kitchen Office/Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
446	2590		0	034A	Storage	Kitchen Office/Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
447	2590		0	034A	Storage	Kitchen Office/Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
448	2590		0	034A	Storage	Kitchen Office/Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
449	2590		0	034A	Storage	Kitchen Office/Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
450	2590	1	0	B1	Primary	Classroom B1 (Art)	W1	Chipping on doors, Flaking on wall and metal pipe	18	No	No	N/A	Posters, Furniture	No	
451	2590	1	0	B1	Primary	Classroom B1 (Art)	W3	Flaking, Efflorescence	20	Yes	No	N/A	Posters, Furniture	Yes	
452	2590	1	0	B1	Primary	Classroom B1 (Art)	W4	Flaking on wall and metal pipe	13	No	No	N/A	Posters, Furniture	No	
453	2590	1	0	B1A	Student Restrooms - Male/Female (Classroom)	Classroom B1 (Art) Restroom	W3	Chipping	1	No	No	N/A	Stored Materials	No	
454	2590	1	0	E1	Elevators, Passenger	Elevator	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
455	2590	1	0	E1	Elevators, Passenger	Elevator	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
456	2590	1	0	E1	Elevators, Passenger	Elevator	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
457	2590	1	0	E1	Elevators, Passenger	Elevator	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
458	2590	1	0	E1	Elevators, Passenger	Elevator	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
459	2590	1	0	E1	Elevators, Passenger	Elevator	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
460	2590	1	0	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	Ceiling	Chipping and Flaking on metal duct, Flaking on ACM Pipe Insulation, Flaking on ACM Pipe Fitting, loose concrete ceiling that could fall	25	No	No	N/A	N/A	No	
461	2590	1	0	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	Floor	Chipping on metal pipe along floor	20	No	No	N/A	N/A	No	
462	2590	1	0	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	W2	Flaking on wall, Chipping and Flaking on metal jackets	45	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
463	2590	1	0	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	W3	Chipping on doors	5	No	No	N/A	N/A	No	
464	2590	1	0	H01	Circulation (Hallway)	Hallway from B1 Art Room to Custodial Closet with Restroom by Exit Doors	W4	Flaking	2	No	No	N/A	N/A	No	
465	2590	1	0	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	Ceiling	Flaking on ceiling and metal duct	300	No	No	N/A	N/A	No	
466	2590	1	0	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	W1	Flaking	690	No	No	N/A	N/A	No	
467	2590	1	0	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	W2	Flaking	200	No	No	N/A	N/A	No	
468	2590	1	0	H02	Circulation (Hallway)	Hallway from near Elevator to Boiler Room	W3	Flaking	690	No	No	N/A	N/A	No	
469	2590	1	0	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	Ceiling	Flaking on wall and metal duct	4	No	No	N/A	N/A	No	
470	2590	1	0	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	Floor	Chipping on metal pipe along floor	3	No	No	N/A	N/A	No	
471	2590	1	0	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	W2	Chipping	1	No	No	N/A	N/A	No	
472	2590	1	0	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	W3	Flaking on wall, Chipping on doors and doorframes	13	No	No	N/A	N/A	No	
473	2590	1	0	H03	Circulation (Hallway)	Hallway from Kitchen to Custodial Closet with Restroom by Exit Doors	W4	Flaking on wall, Chipping and Flaking on metal jackets	11	No	No	N/A	N/A	No	
474	2590	1	0	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	Ceiling	Flaking	5	No	No	N/A	N/A	No	STAIRWAYS

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
475	2590	1	0	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	Floor	Chipping on railing	10	No	No	N/A	N/A	No	
476	2590	1	0	S01	Stairs	Basement Stairwell between Building Engineer's Office and Art Room	W2	Flaking	1	No	No	N/A	N/A	No	
477	2590	1	0	S02	Stairs	Basement Stairwell Between Kitchen and Gym	Ceiling	Flaking, plaster repair paint in stabilized	3	No	No	N/A	N/A	Yes	
478	2590	1	0	S02	Stairs	Basement Stairwell Between Kitchen and Gym	W2	Flaking, Efflorescence, plaster repair paint in stabilized	3	Yes	No	N/A	N/A	Yes	
479	2590	1	0	S02	Stairs	Basement Stairwell Between Kitchen and Gym	W3	Plaster repair paint is stabilized	2	No	No	N/A	N/A	Yes	
480	2590	1	2	208	Administrative Office	Room 208 ESOL Office	W4	Cracking, flaking	2	No	N/A	N/A	N/A	No	
481	2590	1	2	203	Circular next to Elevator (Hallway)	Room 203	W3	Cracking, Flaking	4	No	N/A	N/A	N/A	No	
482	2590	1	2	204	Administrative Office	Room 204A - Admin Office Adjacent to Teacher's Lounge	W4	Cracking, Flaking	1	No	N/A	N/A	N/A	No	
483	2590	1	2	207	Primary	Classroom 207	W4	Gouges	2	No	N/A	N/A	N/A	No	
484	2590	1	2	204	Administrative Office	Room 204A - Admin Office Adjacent to Teacher's Lounge	W3	Flaking	1	No	N/A	N/A	N/A	No	
485	2590	1	2	205	Primary	Room 205 - Counselors Office	W4	Gouges	1	No	N/A	N/A	N/A	No	
486	2590	1	2	206	Primary	Room 206	W4	Gouges, Flaking	2	No	N/A	N/A	N/A	No	
487	2590	1	4	409	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 406	W3	Spalling by the window	1	No	N/A	N/A	N/A	No	
488	2590	1	4	401	Primary	Classroom 401	W2	Cracking, Flaking	2	No	N/A	N/A	N/A	No	
489	2590	1	4	401	Primary	Classroom 401	W4	Cracking, Flaking	2	No	N/A	N/A	N/A	No	
490	2590	1	4	401	Primary	Classroom 401 - Closet	W3	Cracking, Flaking	5	No	N/A	N/A	N/A	No	
491	2590	1	1	101	Administrative Office	CATCH Program	W4	Cracking	9	No	N/A	N/A	N/A	No	
492	2590	1	3	302A	Storage	Classroom 302 Closet	W3	Flaking	9	No	N/A	N/A	N/A	No	
493	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	Ceiling	Faking, Efflorescence	6	No	N/A	N/A	N/A	No	
494	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W2	Cracking	2	No	N/A	N/A	N/A	No	
495	2590	1	1	109B	Restrooms, Staff - Female	Women's Restroom	W4	Cracking	5	No	N/A	N/A	N/A	No	
496	2590	1	2	202	Primary	Classroom 202	W3	Cracking, chipping, flaking, flaking behind radiators	9	No	N/A	N/A	N/A	No	
497	2590	1	1	104	Primary	Classroom 104	W4	Flaking on the soffet by the door	4	No	N/A	N/A	N/A	No	

