

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2620	1	6	601C	Storage	602 Storage Room in Hallway near Elevator 1 and next to Stairwell	W3	Chipping	3	N	N	0	N	N	
2	2620	1	6	601C	Storage	602 Storage Room in Hallway near Elevator 1 and next to Stairwell	W2	Flaking	28	N	N	0	N	N	Additional Chipping; Damage on Shelves & Wall Behind
3	2620	1	6	601C	Storage	602 Storage Room in Hallway near Elevator 1 and next to Stairwell	W4	Flaking	18	Y	N	0	N	N	Additional Efflorescence; Brick Wall
4	2620	1	6	601C	Storage	602 Storage Room in Hallway near Elevator 1 and next to Stairwell	Ceiling	Flaking	16	Y	N	0	N	Y - 8 SF	Additional Efflorescence
5	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
6	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
7	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
8	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
9	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
10	2620	1	6	603	Student Restrooms - Male (4-12)	Boys' Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
11	2620	1	6	H626	Circulation (Hallway)	Hallway from near Elevator No. 1 to Rooftop Play Area	W2	Chipping	7	N	N	0	N	N	
12	2620	1	6	H626	Circulation (Hallway)	Hallway from near Elevator No. 1 to Rooftop Play Area	W1	Flaking	35	N	N	0	Y - 24 SF Lockers	N	4 Locations
13	2620	1	6	H626	Circulation (Hallway)	Hallway from near Elevator No. 1 to Rooftop Play Area	W3	Flaking	21	N	N	0	N	N	Additional Chipping
14	2620	1	6	H626	Circulation (Hallway)	Hallway from near Elevator No. 1 to Rooftop Play Area	W4	Flaking	4	N	N	0	N	N	2 Locations; Damage @ Doors 1 & 2
15	2620	1	6	H626	Circulation (Hallway)	Hallway from near Elevator No. 1 to Rooftop Play Area	Ceiling	Flaking	485	N	N	0	N	N	Additional Cracking, Chipping
16	2620	1	6	H625	Circulation (Hallway)	Hallway from near Elevator No. 2 to Rooftop Play Area	Floor	Chipping	12	N	N	0	N	N	Chipping @ Perimeter
17	2620	1	6	H625	Circulation (Hallway)	Hallway from near Elevator No. 2 to Rooftop Play Area	W1	Flaking	42	N	N	0	N	N	4 Locations; Damage @ Radiators & Doors
18	2620	1	6	H625	Circulation (Hallway)	Hallway from near Elevator No. 2 to Rooftop Play Area	Ceiling	Flaking	72	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
19	2620	1	6	604	Storage	Large Storage Area near Elevator No. 2	W1	Flaking	2	N	N	0	N	N	
20	2620	1	6	604	Storage	Large Storage Area near Elevator No. 2	W2	Flaking	43	N	N	0	N	N	6 Locations; Damage @ Wall & Radiators
21	2620	1	6	604	Storage	Large Storage Area near Elevator No. 2	W3	Flaking	84	Y	Y - Near Radiator 2	6	N	N	2 Locations; Damage @ Wall & Radiators
22	2620	1	6	604	Storage	Large Storage Area near Elevator No. 2	W4	Flaking	66	Y	N	0	N	N	2 Locations; Additional Cracking, Chipping
23	2620	1	6	604	Storage	Large Storage Area near Elevator No. 2	Ceiling	Flaking	1,944	N	N	0	N	N	Additional Holes
24	2620	1	6	602		Outdoor Play Area - Center Wing	W1	Flaking	720	N	N	0	N	N	Exterior Fence
25	2620	1	6	602		Outdoor Play Area - Center Wing	W2	Flaking	945	N	N	0	N	N	Exterior Fence
26	2620	1	6	602		Outdoor Play Area - Center Wing	W3	Flaking	720	N	N	0	N	N	Exterior Fence
27	2620	1	6	602		Outdoor Play Area - Center Wing	W4	Flaking	945	N	N	0	N	N	Exterior Fence
28	2620	1	6	602		Outdoor Play Area - Center Wing	Ceiling	Flaking	3,024	N	N	0	N	N	Exterior Fence
29	2620	1	6	602A		Outdoor Play Area - From H625 to H626	W1	Flaking	2,745	N	N	0	N	N	Exterior Fence
30	2620	1	6	602A		Outdoor Play Area - From H625 to H626	W2	Flaking	495	N	N	0	N	N	Exterior Fence
31	2620	1	6	602A		Outdoor Play Area - From H625 to H626	W3	Flaking	2,745	N	N	0	N	N	Exterior Fence
32	2620	1	6	602A		Outdoor Play Area - From H625 to H626	W4	Flaking	495	N	N	0	N	N	Exterior Fence
33	2620	1	6	602A		Outdoor Play Area - From H625 to H626	Ceiling	Flaking	6,040	N	N	0	N	N	Exterior Fence
34	2620	1	6	605		Outdoor Play Area Near Elevator No. 2	W1	Flaking	765	N	N	0	N	N	Exterior Fence
35	2620	1	6	605		Outdoor Play Area Near Elevator No. 2	W2	Flaking	1,395	N	N	0	N	N	Exterior Fence
36	2620	1	6	605		Outdoor Play Area Near Elevator No. 2	W3	Flaking	765	N	N	0	N	N	Exterior Fence
37	2620	1	6	605		Outdoor Play Area Near Elevator No. 2	W4	Flaking	1,395	N	N	0	N	N	Exterior Fence
38	2620	1	6	605		Outdoor Play Area Near Elevator No. 2	Ceiling	Flaking	4,745	N	N	0	N	N	Exterior Fence
39	2620	1	6	601A	Storage	Room 603 Storage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
40	2620	1	6	601A	Storage	Room 603 Storage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
41	2620	1	6	601A	Storage	Room 603 Storage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
42	2620	1	6	601A	Storage	Room 603 Storage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
43	2620	1	6	601A	Storage	Room 603 Storage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
44	2620	1	6	601A	Storage	Room 603 Storage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
45	2620	1	6	601	Student Restrooms - Female (4-12)	Room 604 Girls' Restroom	W2	Cracking	4	N	N	0	N	N	
46	2620	1	6	601	Student Restrooms - Female (4-12)	Room 604 Girls' Restroom	W1	Flaking	5	N	N	0	N	N	2 Locations
47	2620	1	6	601	Student Restrooms - Female (4-12)	Room 604 Girls' Restroom	W3	Flaking	24	N	N	0	N	N	4 Locations; Damage on Wall & Radiators
48	2620	1	6	601	Student Restrooms - Female (4-12)	Room 604 Girls' Restroom	W4	Flaking	1	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
49	2620	1	6	601	Student Restrooms - Female (4-12)	Room 604 Girls' Restroom	Ceiling	Flaking	12	N	N	0	N	N	3 Locations
50	2620	1	6	607	Storage	Room 607 Storage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
51	2620	1	6	607	Storage	Room 607 Storage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
52	2620	1	6	607	Storage	Room 607 Storage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
53	2620	1	6	607	Storage	Room 607 Storage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
54	2620	1	6	607	Storage	Room 607 Storage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
55	2620	1	6	607	Storage	Room 607 Storage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
56	2620	1	6	S61	Stairs	Stairwell in Wrestling Practice Room	Floor	Chipping	5	N	Y - @ Perimeter	24	N	N	
57	2620	1	6	S61	Stairs	Stairwell in Wrestling Practice Room	W4	Cracking	5	N	N	0	N	N	2 Locations
58	2620	1	6	S61	Stairs	Stairwell in Wrestling Practice Room	W2	Flaking	160	Y	Y - On Window Sills & On Skirt	20	N	Y - 160 SF	Additional Efflorescence
59	2620	1	6	S61	Stairs	Stairwell in Wrestling Practice Room	W3	Flaking	8	N	N	0	N	N	Additional Chipping
60	2620	1	6	S61	Stairs	Stairwell in Wrestling Practice Room	Ceiling	Flaking	2	Y	N	0	N	Y - 2 SF	Additional Efflorescence
61	2620	1	6	S62	Stairs	Stairwell near Elevator No. 1	W3	Chipping	2	N	N	0	N	N	Chipping @ Granite Apron
62	2620	1	6	S62	Stairs	Stairwell near Elevator No. 1	Ceiling	Cracking	7	N	N	0	N	N	4 Locations
63	2620	1	6	S62	Stairs	Stairwell near Elevator No. 1	W1	Flaking	34	Y	Y - @ Radiator & Granite Apron	12	N	Y - 24 SF	4 Locations; Additional Efflorescence
64	2620	1	6	S62	Stairs	Stairwell near Elevator No. 1	W2	Flaking	12	Y	Y - On Window Sills	12	N	Y - 7 SF	2 Locations; Additional Efflorescence
65	2620	1	6	S62	Stairs	Stairwell near Elevator No. 1	W4	Flaking	56	Y	N	0	N	Y - 56 SF	Additional Efflorescence, Cracking
66	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	Floor	Chipping	2	N	N	0	N	N	
67	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	Center Banister	Chipping	1	N	N	0	N	N	
68	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	Ceiling	Efflorescence	16	Y	N	0	N	Y - 2 SF	2 Locations; Additional Efflorescence, Cracking
69	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	W1	Flaking	26	Y	Y - @ Corner of Walls 1 & 2	1	N	Y - 16 SF	2 Locations; Additional Efflorescence, Chipping; Damage @ Wall & Radiator
70	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	W2	Flaking	92	Y	N	0	N	Y - 12 SF	2 Locations; Additional Efflorescence, Cracking
71	2620	1	6	S67	Stairs	Stairwell near Elevator No. 2	W4	Flaking	18	Y	N	0	N	Y - 3 SF	2 Locations; Additional Efflorescence, Cracking
72	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	Center Banister	Chipping	1	N	N	0	N	N	
73	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	W2	Flaking	12	Y	Y - @ Granite Apron	3	N	Y - 12 SF	Additional Efflorescence
74	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	W3	Flaking	6	Y	Y - On Window Sills	6	N	Y - 6 SF	Additional Efflorescence
75	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	W4	Flaking	60	Y	Y - @ Granite Apron	3	N	Y - 60 SF	2 Locations; Additional Efflorescence
76	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	Ceiling	Flaking	120	Y	N	0	N	Y - 120 SF	Additional Efflorescence
77	2620	1	6	S610	Stairs	Stairwell next to Large Storage Area	Floor	Flaking	6	N	Y - Stairs	125	N	N	Additional Chipping
78	2620	1	6	600	Wrestling Room	Wrestling Practice Room	W1	Chipping	4	N	N	0	N	N	6th Floor Unoccupied
79	2620	1	6	600	Wrestling Room	Wrestling Practice Room	Floor	Chipping	130	N	Y - @ Perimeter	60	N	N	Chipping @ Perimeter

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
80	2620	1	6	600	Wrestling Room	Wrestling Practice Room	W2	Flaking	22	N	N	0	N	N	Additional Cracking
81	2620	1	6	600	Wrestling Room	Wrestling Practice Room	W3	Flaking	54	N	N	0	N	N	3 Locations; Additional Cracking; Damage @ Wall & Radiators
82	2620	1	6	600	Wrestling Room	Wrestling Practice Room	W4	Flaking	58	N	N	0	N	N	5 Locations; Additional Cracking, Chipping
83	2620	1	6	600	Wrestling Room	Wrestling Practice Room	Ceiling	Flaking	1,800	N	N	0	N	N	Additional Cracking, Chipping
84	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
85	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
86	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
87	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
88	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
89	2620	1	6	600A	Storage	Wrestling Practice Room Storage Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
90	2620	1	5	508D	Storage	Area containing the Walk-in Refrigerator/Freezer	Ceiling	Flaking	8	Y	N	0	N	Y - 2 SF	Additional Efflorescence
91	2620	1	5	509C	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 507	W1	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
92	2620	1	5	509C	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 507	W3	Flaking	38	Y	Y - On Window Sills & Granite Apron	9	N	Y - 4 SF	8 Locations; Additional Efflorescence, Cracking
93	2620	1	5	509C	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 507	W4	Flaking	9	N	N	0	N	N	Additional Holes
94	2620	1	5	502	Senior High	Classroom 501A	W1	Flaking	120	Y	N	0	N	Y - 50 SF	Additional Efflorescence
95	2620	1	5	502	Senior High	Classroom 501A	W3	Flaking	64	Y	Y - On Window Sills	4	N	Y - 18 SF	3 Locations; Additional Efflorescence
96	2620	1	5	502	Senior High	Classroom 501A	W4	Flaking	48	N	N	0	Y - 18 SF Posters	N	Additional Cracking
97	2620	1	5	502	Senior High	Classroom 501A	Ceiling	Flaking	10	N	N	0	N	N	Additional Cracking, Holes; Suspended Ceiling; Water Stains on Ceiling Tiles
98	2620	1	5	502	Senior High	Classroom 501A	W2	Partially Inaccessible	0	N	N	0	Y - 8 SF Posters	N	
99	2620	1	5	503	Senior High	Classroom 502	W1	Cracking	4	N	N	0	Y - 16 SF Posters	N	
100	2620	1	5	503	Senior High	Classroom 502	W2	Flaking	8	Y	N	0	N	Y - 6 SF	Additional Efflorescence, Chipping
101	2620	1	5	503	Senior High	Classroom 502	W3	Flaking	96	Y	Y - On Window Sills	24	N	Y - 48 SF	3 Locations; Additional Efflorescence
102	2620	1	5	503	Senior High	Classroom 502	W4	Flaking	4	N	N	0	N	N	Additional Cracking
103	2620	1	5	504	Senior High	Classroom 503	W1	Chipping	2	N	N	0	Y - 12 SF Posters	N	
104	2620	1	5	504	Senior High	Classroom 503	W4	Cracking	12	N	N	0	Y - 4 SF Posters	N	2 Locations; Additional Chipping
105	2620	1	5	504	Senior High	Classroom 503	W3	Efflorescence	9	Y	Y - On Window Sills	9	N	Y - 9 SF	3 Locations; Damage @ Center Wall, Window Lintels 4 & 6
106	2620	1	5	504	Senior High	Classroom 503	W2	Flaking	28	N	N	0	N	N	2 Locations; Additional Cracking

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
107	2620	1	5	505	Senior High	Classroom 504	W2	Chipping	3	N	N	0	N	N	2 Locations; Additional Gouges
108	2620	1	5	505	Senior High	Classroom 504	W1	Cracking	4	N	N	0	N	N	Water Stains on Wall
109	2620	1	5	505	Senior High	Classroom 504	W3	Flaking	96	Y	Y - On Window Sills	12	N	Y - 48 SF	Additional Efflorescence
110	2620	1	5	505	Senior High	Classroom 504	W4	Flaking	10	N	N	0	N	N	Additional Cracking
111	2620	1	5	505	Senior High	Classroom 504	Ceiling	Flaking	24	N	N	0	N	Y - 24 SF	Additional Cracking, Holes
112	2620	1	5	506	Computer - Senior High	Classroom 506	W1	Flaking	24	N	N	0	N	N	Additional Chipping
113	2620	1	5	506	Computer - Senior High	Classroom 506	W3	Flaking	32	Y	Y - On Window Sills	6	N	Y - 2 SF	5 Locations; Additional Efflorescence, Chipping; Damage @ Wall, Radiators, Behind Radiators
114	2620	1	5	506	Computer - Senior High	Classroom 506	W4	Flaking	36	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
115	2620	1	5	506	Computer - Senior High	Classroom 506	W2	Holes	36	N	N	0	Y - 28 SF Bookcases, Cabinets, Posters	N	Holes from Staples
116	2620	1	5	507	Senior High	Classroom 507	W1	Flaking	12	Y	N	0	Y - 48 SF Tables, Contents	Y - 12 SF	Additional Efflorescence
117	2620	1	5	507	Senior High	Classroom 507	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Computers	N	
118	2620	1	5	507	Senior High	Classroom 507	W3	Partially Inaccessible	0	N	N	0	Y - 64 Desks, Computers	N	
119	2620	1	5	507	Senior High	Classroom 507	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Computers	N	
120	2620	1	5	510	Senior High	Classroom 521	W1	Cracking	2	N	N	0	Y - 18 SF Posters	N	
121	2620	1	5	510	Senior High	Classroom 521	W4	Cracking	4	N	N	0	Y - 28 SF Posters	N	
122	2620	1	5	510	Senior High	Classroom 521	W2	Flaking	30	Y	N	0	N	Y - 2 SF	2 Locations; Additional Efflorescence, Cracking
123	2620	1	5	510	Senior High	Classroom 521	W3	Flaking	96	Y	Y - On Window Sills	4	N	Y - 20	Additional Efflorescence, Cracking, Chipping; Damage on Entire Wall
124	2620	1	5	510	Senior High	Classroom 521	Ceiling	Flaking	22	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence, Holes
125	2620	1	5	511	Senior High	Classroom 522	W2	Cracking	2	N	N	0	Y - 66 SF Posters	N	
126	2620	1	5	511	Senior High	Classroom 522	W1	Flaking	3	N	N	0	Y - 162 SF Whiteboards, Posters	N	Additional Chipping
127	2620	1	5	511	Senior High	Classroom 522	W3	Flaking	25	Y	N	0	N	N	3 Locations; Flaking @ Window Lintels, Behind Radiator, Behind Pije @ Window 9
128	2620	1	5	511	Senior High	Classroom 522	Ceiling	Flaking	11	Y	N	0	N	Y - 11 SF	2 Locations; Additional Efflorescence
129	2620	1	5	511	Senior High	Classroom 522	W4	Partially Inaccessible	0	N	Y - On Conduit	3	N	N	
130	2620	1	5	512	Senior High	Classroom 524	W1	Chipping	3	N	N	0	Y - 48 SF Posters	N	4 Locations
131	2620	1	5	512	Senior High	Classroom 524	W3	Flaking	19	Y	Y - On Window Sills 1, 5 & 6	6	N	Y - 6 SF	4 Locations; Additional Efflorescence, Cracking, Chipping, Holes
132	2620	1	5	512	Senior High	Classroom 524	Ceiling	Flaking	12	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
133	2620	1	5	512	Senior High	Classroom 524	W2	Partially Inaccessible	0	N	N	0	Y - 288 Cabinets, Whiteboards, Posters	N	
134	2620	1	5	512	Senior High	Classroom 524	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Posters	N	
135	2620	1	5	514	Student Restrooms - Female (4-12)	Girls' Restroom across from Room 501A	W1	Chipping	4	N	N	0	N	N	
136	2620	1	5	514	Student Restrooms - Female (4-12)	Girls' Restroom across from Room 501A	W3	Chipping	16	N	N	0	N	N	Chipping @ Radiators
137	2620	1	5	514	Student Restrooms - Female (4-12)	Girls' Restroom across from Room 501A	W2	Flaking	2	N	N	0	N	N	Additional Holes
138	2620	1	5	H521	Circulation (Hallway)	Hallway from Cafeteria to Teacher's Lounge	W1	Chipping	2	N	N	0	N	N	2 Locations
139	2620	1	5	H521	Circulation (Hallway)	Hallway from Cafeteria to Teacher's Lounge	W3	Chipping	2	N	N	0	N	N	2 Locations
140	2620	1	5	H521	Circulation (Hallway)	Hallway from Cafeteria to Teacher's Lounge	W2	Flaking	19	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
141	2620	1	5	H521	Circulation (Hallway)	Hallway from Cafeteria to Teacher's Lounge	W4	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence; Damage Behind Lockers
142	2620	1	5	H523	Circulation (Hallway)	Hallway from Classroom 521 to Classroom 522	W2	Chipping	4	N	N	0	N	N	2 Locations; Chipping @ Granite Apron
143	2620	1	5	H523	Circulation (Hallway)	Hallway from Classroom 521 to Classroom 522	W4	Chipping	1	N	N	0	N	N	
144	2620	1	5	H522	Circulation (Hallway)	Hallway from Room 501 to Classroom 507	W4	Chipping	1	N	N	0	N	N	
145	2620	1	5	H522	Circulation (Hallway)	Hallway from Room 501 to Classroom 507	Floor	Chipping	20	N	N	0	N	N	
146	2620	1	5	H522	Circulation (Hallway)	Hallway from Room 501 to Classroom 507	W1	Efflorescence	27	Y	Y - @ Granite Apron @ Locker Ends	16	N	Y - 6 SF	3 Locations; Additional Chipping
147	2620	1	5	H522	Circulation (Hallway)	Hallway from Room 501 to Classroom 507	W3	Flaking	40	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
148	2620	1	5	H522	Circulation (Hallway)	Hallway from Room 501 to Classroom 507	Ceiling	Flaking	8	N	N	0	N	Y - 2 SF	Suspended Ceiling; Missing Ceiling Tile
149	2620	1	5	H524	Circulation (Hallway)	Hallway near Elevator No. 1 to Room 529	W1	Chipping	1	N	N	0	N	N	
150	2620	1	5	H524	Circulation (Hallway)	Hallway near Elevator No. 1 to Room 529	Floor	Chipping	11	N	Y - @ Radiator/Pipe	2	N	N	Chipping @ Perimeter
151	2620	1	5	H524	Circulation (Hallway)	Hallway near Elevator No. 1 to Room 529	W2	Flaking	1	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
152	2620	1	5	H524	Circulation (Hallway)	Hallway near Elevator No. 1 to Room 529	W4	Flaking	42	N	Y - @ Granite Apron by Lockers	2	N	N	4 Locations; Additional Chipping
153	2620	1	5	508B	Storage	Kitchen Dry Storage Room	W4	Cracking	2	N	N	0	Y - 54 SF Shelves, Contents	N	
154	2620	1	5	508B	Storage	Kitchen Dry Storage Room	W1	Flaking	16	N	N	0	Y - 70 SF Shelves, Contents	N	Additional Chipping, Spalling
155	2620	1	5	508B	Storage	Kitchen Dry Storage Room	W2	Flaking	2	N	N	0	Y - 32 Shelves, Contents	N	
156	2620	1	5	508B	Storage	Kitchen Dry Storage Room	W3	Flaking	32	N	N	0	Y - 64 Shelves, Contents	N	Additional Cracking, Chipping
157	2620	1	5	508B	Storage	Kitchen Dry Storage Room	Ceiling	Flaking	160	N	N	0	N	N	
158	2620	1	5	508C	Administrative Office	Kitchen Office	W4	Cracking	4	N	N	0	N	N	Cracking @ Pipe
159	2620	1	5	508C	Administrative Office	Kitchen Office	W3	Flaking	4	Y	N	0	N	Y - 2 SF	Additional Efflorescence
160	2620	1	5	508C	Administrative Office	Kitchen Office	Ceiling	Flaking	2	N	N	0	N	N	
161	2620	1	5	S514	Stairs	Middle Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
162	2620	1	5	S514	Stairs	Middle Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
163	2620	1	5	S514	Stairs	Middle Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
164	2620	1	5	S514	Stairs	Middle Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
165	2620	1	5	S514	Stairs	Middle Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
166	2620	1	5	S514	Stairs	Middle Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
167	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
168	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
169	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
170	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
171	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
172	2620	1	5	509E	Restrooms, Staff - Male/Female	Old Teacher Lounge no longer used Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
173	2620	1	5	501A	Restrooms, Staff - Male/Female	Room 501 School Psychologist Office Restroom	W1	Cracking	1	N	N	0	N	N	
174	2620	1	5	501A	Restrooms, Staff - Male/Female	Room 501 School Psychologist Office Restroom	W3	Cracking	1	N	N	0	N	N	Cracking on Pipe
175	2620	1	5	501A	Restrooms, Staff - Male/Female	Room 501 School Psychologist Office Restroom	W2	Flaking	4	N	Y - On Window Sills	4	N	N	Additional Chipping
176	2620	1	5	501A	Restrooms, Staff - Male/Female	Room 501 School Psychologist Office Restroom	Ceiling	Flaking	2	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
177	2620	1	5	508	Cafeteria (Dining Area)	Room 509 Cafeteria	W1	Chipping	6	N	N	0	N	N	Brick Wall
178	2620	1	5	508	Cafeteria (Dining Area)	Room 509 Cafeteria	W2	Cracking	4	N	N	0	Y - 180 SF Kitchen Appliances	N	
179	2620	1	5	508	Cafeteria (Dining Area)	Room 509 Cafeteria	W3	Flaking	30	Y	N	0	N	N	6 Locations; Additional Chipping; Damage @ Wall & Radiators
180	2620	1	5	508	Cafeteria (Dining Area)	Room 509 Cafeteria	W4	Flaking	0	N	Y - On Window Sills	3	N	N	8 Locations; Additional Efflorescence, Chipping; Brick Wall
181	2620	1	5	508	Cafeteria (Dining Area)	Room 509 Cafeteria	Columns	Flaking	96	N	N	0	N	N	14 Locations; Additional Chipping
182	2620	1	5	508A	Kitchen	Room 510 Kitchen	Ceiling	Flaking	52	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
183	2620	1	5	509	Teacher Lounge/Dining	Room 512 Faculty Lounge	W1	Cracking	8	N	N	0	N		
184	2620	1	5	509	Teacher Lounge/Dining	Room 512 Faculty Lounge	W3	Flaking	30	N	Y - @ Window Sill 5	1	N		3 Locations; Additional Chipping; Damage Including Radiators
185	2620	1	5	509	Teacher Lounge/Dining	Room 512 Faculty Lounge	W4	Flaking	16	Y	N	0	Y - 38 SF Fridge, Shelves, Contents		Additional Cracking; Water Stains on Wall
186	2620	1	5	509	Teacher Lounge/Dining	Room 512 Faculty Lounge	Ceiling	Flaking	3	N	N	0	N		Suspended Ceiling; Flaking @ Window Lintel 5
187	2620	1	5	509	Teacher Lounge/Dining	Room 512 Faculty Lounge	W2	Partially Inaccessible	0	N	N	0	Y - 34 SF Copier, Shelves, Contents		
188	2620	1	5	509B	Storage	Room 513 Storage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
189	2620	1	5	509B	Storage	Room 513 Storage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
190	2620	1	5	509B	Storage	Room 513 Storage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
191	2620	1	5	509B	Storage	Room 513 Storage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
192	2620	1	5	509B	Storage	Room 513 Storage	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
193	2620	1	5	509B	Storage	Room 513 Storage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
194	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
195	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
196	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
197	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
198	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
199	2620	1	5	509A	Restrooms, Staff - Male/Female	Room 514 Staff Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
200	2620	1	5	510B	Storage	Room 519 Electrical	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
201	2620	1	5	510B	Storage	Room 519 Electrical	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
202	2620	1	5	510B	Storage	Room 519 Electrical	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
203	2620	1	5	510B	Storage	Room 519 Electrical	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
204	2620	1	5	510B	Storage	Room 519 Electrical	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
205	2620	1	5	510B	Storage	Room 519 Electrical	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
206	2620	1	5	510A	Storage	Room 520 Storage	W1	Cracking	96	N	N	0	N	N	
207	2620	1	5	510A	Storage	Room 520 Storage	W3	Cracking	96	N	N	0	N	N	
208	2620	1	5	510A	Storage	Room 520 Storage	W4	Cracking	144	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
209	2620	1	5	510A	Storage	Room 520 Storage	W2	Flaking	144	N	N	0	Y - 80 SF Cabinets, Contents	N	Additional Cracking
210	2620	1	5	510A	Storage	Room 520 Storage	Ceiling	Flaking	22	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Cracking
211	2620	1	5	511A	Academic Classroom (SGI)	Room 523 Prep Room in Classroom 522	W2	Flaking	10	Y	N	0	N	Y - 8 SF	3 Locations; Additional Efflorescence
212	2620	1	5	511A	Academic Classroom (SGI)	Room 523 Prep Room in Classroom 522	W3	Flaking	14	Y	Y - On Window Sills	12	Y - 24 SF Contents	Y - 6 SF	Additional Efflorescence; Damage @ Windows & Behind Radiators
213	2620	1	5	511A	Academic Classroom (SGI)	Room 523 Prep Room in Classroom 522	W4	Flaking	19	Y	N	0	N	N	3 Locations; Additional Efflorescence, Cracking, Chipping
214	2620	1	5	511A	Academic Classroom (SGI)	Room 523 Prep Room in Classroom 522	Ceiling	Flaking	23	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence
215	2620	1	5	514A	Academic Classroom (SGI)	Room 529	W3	Chipping	30	N	N	0	Y - 30 SF Posters	N	
216	2620	1	5	514A	Academic Classroom (SGI)	Room 529	W1	Flaking	22	N	N	0	Y - 32 SF Desks, Posters	N	2 Locations; Additional Cracking, Chipping
217	2620	1	5	514A	Academic Classroom (SGI)	Room 529	W2	Flaking	16	Y	N	0	N	Y - 10 SF	3 Locations; Additional Efflorescence, Chipping
218	2620	1	5	514A	Academic Classroom (SGI)	Room 529	Ceiling	Flaking	8	N	N	0	N	N	Flaking @ Window Lintels 1 & 2
219	2620	1	5	514A	Academic Classroom (SGI)	Room 529	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Posters	N	
220	2620	1	5	S57	Stairs	Stairwell near Cafeteria	W3	Chipping	2	N	N	0	N	Y - 36 SF	Plaster Protruding from Wall
221	2620	1	5	S57	Stairs	Stairwell near Cafeteria	Floor	Chipping	5	N	N	0	N	N	
222	2620	1	5	S57	Stairs	Stairwell near Cafeteria	Center Banister	Chipping	2	N	N	0	N	N	
223	2620	1	5	S57	Stairs	Stairwell near Cafeteria	W1	Cracking	4	N	N	0	N	N	2 Locations
224	2620	1	5	S57	Stairs	Stairwell near Cafeteria	W2	Cracking	24	N	N	0	N	N	Chipping @ Door
225	2620	1	5	S57	Stairs	Stairwell near Cafeteria	W4	Flaking	2	N	N	0	N	N	
226	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	W1	Chipping	4	N	N	0	N	N	
227	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	W4	Chipping	4	N	N	0	N	N	
228	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	Floor	Chipping	3	N	N	0	N	N	Chipping @ Skirt
229	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	Center Banister	Chipping	3	N	N	0	N	N	
230	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	W2	Flaking	3	N	N	0	N	N	
231	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	W3	Flaking	5	N	N	0	N	N	Additional Chipping; Damage @ Radiator
232	2620	1	5	S510	Stairs	Stairwell near Faculty Lounge	Ceiling	Flaking	120	Y	N	0	N	Y - 12 SF	Additional Efflorescence
233	2620	1	5	S52	Stairs	Stairwell near Room 501	W1	Chipping	4	N	N	0	N	N	Chipping @ Radiator
234	2620	1	5	S52	Stairs	Stairwell near Room 501	W3	Chipping	2	N	N	0	N	N	2 Locations
235	2620	1	5	S52	Stairs	Stairwell near Room 501	Floor	Chipping	6	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
236	2620	1	5	S52	Stairs	Stairwell near Room 501	Center Banister	Chipping	4	N	N	0	N	N	
237	2620	1	5	S52	Stairs	Stairwell near Room 501	Ceiling	Efflorescence	1	Y	N	0	N	N	Damage Above Window
238	2620	1	5	S52	Stairs	Stairwell near Room 501	W4	Flaking	32	Y	N	0	N	N	3 Locations; Additional Efflorescence, Cracking, Chipping
239	2620	1	5	S51	Stairs	Stairwell near Room 529	W1	Chipping	2	N	N	0	N	N	2 Locations
240	2620	1	5	S51	Stairs	Stairwell near Room 529	Floor	Chipping	6	N	N	0	N	N	
241	2620	1	5	S51	Stairs	Stairwell near Room 529	Center Banister	Chipping	6	N	N	0	N	N	
242	2620	1	5	S51	Stairs	Stairwell near Room 529	W4	Cracking	5	N	N	0	N	N	3 Locations; Additional Chipping
243	2620	1	5	S51	Stairs	Stairwell near Room 529	W2	Efflorescence	8	Y	N	0	N	Y - 8 SF	
244	2620	1	5	S51	Stairs	Stairwell near Room 529	W3	Flaking	1	N	N	0	N	N	
245	2620	1	5	S51	Stairs	Stairwell near Room 529	Ceiling	Flaking	7	N	N	0	N	N	
246	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
247	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
248	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
249	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
250	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
251	2620	1	5	509F	Storage	Storage Area and Computer Server behind Faculty Lounge	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
252	2620	1	5	513	Senior High	Technology Storage Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
253	2620	1	5	513	Senior High	Technology Storage Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
254	2620	1	5	513	Senior High	Technology Storage Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
255	2620	1	5	513	Senior High	Technology Storage Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
256	2620	1	5	513	Senior High	Technology Storage Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
257	2620	1	5	513	Senior High	Technology Storage Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
258	2620	1	4	408B	Storage	Book Closet next to Room 419 Electrical	Ceiling	Cracking	5	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
259	2620	1	4	408B	Storage	Book Closet next to Room 419 Electrical	W1	Flaking	10	N	N	0	N	N	
260	2620	1	4	408B	Storage	Book Closet next to Room 419 Electrical	W4	Holes	2	N	N	0	Y - 120 SF Shelves, Contents	N	
261	2620	1	4	408B	Storage	Book Closet next to Room 419 Electrical	W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Contents	N	
262	2620	1	4	408B	Storage	Book Closet next to Room 419 Electrical	W3	Partially Inaccessible	0	N	N	0	Y - 64 SF Shelves, Contents	N	
263	2620	1	4	412A	Student Restrooms - Male (4-12)	Boys' Restroom	W1	Chipping	3	N	N	0	N	Y - 3 SF	3 Locations
264	2620	1	4	412A	Student Restrooms - Male (4-12)	Boys' Restroom	W4	Chipping	3	N	N	0	N	N	Additional Chipping
265	2620	1	4	412A	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Cracking	3	N	N	0	N	N	
266	2620	1	4	412A	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Efflorescence	5	Y	N	0	N	N	4 Locations; Additional Cracking; Damage on Wall & Pipes
267	2620	1	4	402	Senior High	Classroom 401	W2	Chipping	1	N	N	0	N	N	
268	2620	1	4	402	Senior High	Classroom 401	W4	Chipping	2	N	N	0	N	N	
269	2620	1	4	402	Senior High	Classroom 401	W1	Flaking	6	N	N	0	N	N	
270	2620	1	4	402	Senior High	Classroom 401	W3	Flaking	136	Y	Y - On Window Sills	27	N	Y - 42 SF	
271	2620	1	4	402	Senior High	Classroom 401	Ceiling	Flaking	15	Y	N	0	N	Y - 12 SF	
272	2620	1	4	403	Senior High	Classroom 404	W1	Flaking	6	N	N	0	Y - 60 SF File Cabinets, Posters	N	Additional Chipping
273	2620	1	4	403	Senior High	Classroom 404	W2	Flaking	2	N	N	0	N	N	2 Locations; Additional Chipping
274	2620	1	4	403	Senior High	Classroom 404	W3	Flaking	60	Y	Y - On Window Sills	36	N	Y - 10 SF	11 Locations; Additional Efflorescence, Cracking, Chipping
275	2620	1	4	403	Senior High	Classroom 404	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Lab Hood	N	
276	2620	1	4	404	Senior High	Classroom 407	Ceiling	Efflorescence	12	Y	N	0	N	N	Suspended Ceiling; Waters Stains @ Window Lintels
277	2620	1	4	404	Senior High	Classroom 407	W3	Flaking	52	Y	Y - On Window Sills	16	N	Y - 16 SF	13 Locations; Additional Efflorescence, Cracking, Chipping
278	2620	1	4	404	Senior High	Classroom 407	W4	Holes	1	N	N	0	Y - 22 SF Lab Hood, Posters	N	
279	2620	1	4	404	Senior High	Classroom 407	W1	Partially Inaccessible	0	N	N	0	Y - 122 SF Bookcases, Posters	N	
280	2620	1	4	404	Senior High	Classroom 407	W2	Partially Inaccessible	0	N	N	0	Y - 48 Desks, Contents	N	
281	2620	1	4	407D	Senior High	Classroom 411	W2	Cracking	4	N	N	0	N	N	
282	2620	1	4	407D	Senior High	Classroom 411	W1	Flaking	12	N	N	0	N	N	3 Locations; Additional Chipping
283	2620	1	4	407D	Senior High	Classroom 411	W3	Flaking	135	Y	N	0	N	Y - 10 SF	Additional Efflorescence, Cracking, Holes
284	2620	1	4	407D	Senior High	Classroom 411	W4	Flaking	10	Y	N	0	Y - 48 SF Contents	Y - 4 SF	2 Locations; Additional Efflorescence

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
285	2620	1	4	407D	Senior High	Classroom 411	Ceiling	Flaking	76	Y	N	0	N	N	2 Locations; Additional Efflorescence
286	2620	1	4	407D	Senior High	Classroom 411	Floor	Flaking	80	N	Y - @ Perimeter	40	N	N	Additional Chipping
287	2620	1	4	408	Senior High	Classroom 421	W1	Chipping	6	N	N	0	Y - 48 SF Desks	N	
288	2620	1	4	408	Senior High	Classroom 421	W3	Flaking	30	N	Y - On Window Sills	8	N	Y - 4 SF	3 Locations; Additional Cracking
289	2620	1	4	408	Senior High	Classroom 421	Ceiling	Flaking	3	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Holes
290	2620	1	4	408	Senior High	Classroom 421	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Posters	N	
291	2620	1	4	409	Senior High	Classroom 422	W4	Cracking	16	N	N	0	N	N	
292	2620	1	4	409	Senior High	Classroom 422	W1	Flaking	3	N	N	0	Y - 16 SF Bookcases	N	2 Locations; Additional Cracking
293	2620	1	4	409	Senior High	Classroom 422	W2	Flaking	2	N	N	0	Y - 24 SF Desks, Posters	N	
294	2620	1	4	409	Senior High	Classroom 422	W3	Flaking	20	N	N	0	N	N	2 Locations; Additional Chipping
295	2620	1	4	409	Senior High	Classroom 422	Ceiling	Flaking	10	Y	N	0	N	Y - 4 SF	3 Locations; Additional Efflorescence
296	2620	1	4	410	Senior High	Classroom 423	W2	Flaking	3	N	N	0	Y - 16 SF Posters	N	3 Locations; Additional Cracking
297	2620	1	4	410	Senior High	Classroom 423	Ceiling	Flaking	8	Y	N	0	N	Y - 4 SF	3 Locations; Additional Efflorescence; Damage @ Windows 5 & 6
298	2620	1	4	410	Senior High	Classroom 423	W1	Partially Inaccessible	0	N	N	0	Y - 21 SF Posters	N	
299	2620	1	4	410	Senior High	Classroom 423	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Cabinets, Bookcases	N	
300	2620	1	4	410	Senior High	Classroom 423	W4	Partially Inaccessible	0	N	N	0	Y - 56 SF Tables	N	
301	2620	1	4	411	Senior High	Classroom 424	W4	Chipping	12	N	N	9	N	N	
302	2620	1	4	411	Senior High	Classroom 424	W1	Flaking	7	N	N	0	Y - 30 SF Tables, Posters, Contents	N	3 Locations; Additional Chipping
303	2620	1	4	411	Senior High	Classroom 424	W3	Flaking	24	N	Y - On Window Sills	8	N	N	4 Locations; Damage @ Radiators, Pipes, Wall
304	2620	1	4	411	Senior High	Classroom 424	Ceiling	Flaking	36	Y	N	9	N	Y - 6 SF	Additional Efflorescence, Cracking
305	2620	1	4	415	Senior High	Classroom 432	W1	Flaking	12	N	N	0	N	N	Additional Cracking
306	2620	1	4	415	Senior High	Classroom 432	W2	Flaking	12	N	N	0	N	N	Flaking @ Top of Wall
307	2620	1	4	415	Senior High	Classroom 432	W3	Flaking	96	Y	Y - @ Window Sills	5	Y - 12 SF Desks, Posters	Y - 14 SF	7 Locations; Additional Efflorescence, Cracking, Chipping; Damage Includes, Wall, Windows, Radiators, Pipes
308	2620	1	4	415	Senior High	Classroom 432	W4	Flaking	3	N	N	0	N	N	Flaking @ Top of Wall
309	2620	1	4	415	Senior High	Classroom 432	Ceiling	Flaking	68	Y	N	0	N	Y - 2 SF	3 Locations; Additional Efflorescence; Significant Moisture Damage
310	2620	1	4	414	Senior High	Classroom 433	W1	Flaking	12	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
311	2620	1	4	414	Senior High	Classroom 433	W2	Flaking	48	Y	Y - @ Blackboard Trim & Conduit	8	N	Y - 13 SF	Additional Efflorescence, Cracking
312	2620	1	4	414	Senior High	Classroom 433	W3	Flaking	42	Y	Y - On Window Sills	5	N	Y - 16 SF	8 Locations; Additional Efflorescence, Cracking, Chipping

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
313	2620	1	4	414	Senior High	Classroom 433	W4	Flaking	18	N	N	0	N	N	2 Locations
314	2620	1	4	414	Senior High	Classroom 433	Ceiling	Flaking	294	N	N	0	N	N	2 Locations; Additional Cracking
315	2620	1	4	413	Senior High	Classroom 434	W4	Cracking	14	N	N	0	N	N	2 Locations; Additional Chipping
316	2620	1	4	413	Senior High	Classroom 434	W1	Flaking	22	Y	N	0	Y - 40 SF Desks, Contents	Y - 6 SF	5 Locations; Additional Efflorescence, Chipping
317	2620	1	4	413	Senior High	Classroom 434	W2	Flaking	8	Y	N	0	N	Y - 1 SF	3 Locations; Additional Efflorescence, Cracking, Chipping, Holes
318	2620	1	4	413	Senior High	Classroom 434	W3	Flaking	276	Y	Y - @ Window Sills	32	N	Y - 64 SF	Additional Efflorescence, Cracking; Damage on Entire Wall
319	2620	1	4	413	Senior High	Classroom 434	Ceiling	Flaking	380	Y	N	0	N	Y - 52 SF	Additional Efflorescence, Cracking; Water Stains
320	2620	1	4	416	Senior High	Classroom 436	W1	Cracking	2	N	N	0	Y - 44 SF Posters, Contents	N	
321	2620	1	4	416	Senior High	Classroom 436	W2	Flaking	144	Y	N	0	Y - 48 SF Bookcases, Desks, Books, Contents	Y - 40 SF	Additional Efflorescence; Water Stain on Wall
322	2620	1	4	416	Senior High	Classroom 436	W3	Flaking	96	Y	Y - @ Windows	36	N	Y - 24 SF	10 Locations; Additional Efflorescence
323	2620	1	4	416	Senior High	Classroom 436	Ceiling	Flaking	36	Y	N	0	N	N	Additional Efflorescence
324	2620	1	4	416	Senior High	Classroom 436	W4	Partially Inaccessible	0	N	N	0	Y - 44 SF Bookcases, Cabinets	N	
325	2620	1	4	417	Senior High	Classroom 437	W4	Chipping	1	N	Y - @ Chalkboard Trim by Window	1	N	N	
326	2620	1	4	417	Senior High	Classroom 437	W1	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping
327	2620	1	4	417	Senior High	Classroom 437	W2	Cracking	6	N	N	0	N	N	
328	2620	1	4	417	Senior High	Classroom 437	W3	Flaking	48	Y	Y - On Window Sills	6	N	Y - 18 SF	3 Locations; Additional Efflorescence, Cracking, Chipping
329	2620	1	4	417	Senior High	Classroom 437	Ceiling	Flaking	58	Y	N	0	N	Y - 6 SF	5 Locations; Additional Efflorescence, Cracking
330	2620	1	4	406H	Student Restrooms - Female (4-12)	Female Restroom in Library/IMC	Floor	Chipping	128	N	N	0	N	N	
331	2620	1	4	407A	Student Restrooms - Female (4-12)	Girls' Restroom	W4	Cracking	1	N	N	0	N	N	Cracking on Pipe
332	2620	1	4	407A	Student Restrooms - Female (4-12)	Girls' Restroom	W3	Efflorescence	58	Y	Y - On Window Sills	28	N	Y - 40 SF	2 Locations; Additional Cracking
333	2620	1	4	H420	Circulation (Hallway)	Hallway along Room 429 Physics/Robotics Lab	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
334	2620	1	4	H420	Circulation (Hallway)	Hallway along Room 429 Physics/Robotics Lab	W2	Chipping	4	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
335	2620	1	4	H420	Circulation (Hallway)	Hallway along Room 429 Physics/Robotics Lab	W3	Chipping	2	N	N	0	N	N	Chipping @ Door
336	2620	1	4	H420	Circulation (Hallway)	Hallway along Room 429 Physics/Robotics Lab	W4	Cracking	6	N	N	0	N	N	
337	2620	1	4	402B	Circulation (Hallway)	Hallway between Classrooms 401 and 404	W2	Chipping	2	N	N	0	N	N	2 Locations
338	2620	1	4	402B	Circulation (Hallway)	Hallway between Classrooms 401 and 404	Ceiling	Cracking	2	N	N	0	N	N	
339	2620	1	4	402B	Circulation (Hallway)	Hallway between Classrooms 401 and 404	W4	Flaking	1	N	N	0	N	N	
340	2620	1	4	402B	Circulation (Hallway)	Hallway between Classrooms 401 and 404	W3	Gouges	1	N	N	0	N	N	
341	2620	1	4	404A	Circulation (Hallway)	Hallway from Classroom 404 to Classroom 407	W1	Chipping	1	N	N	0	N	N	
342	2620	1	4	404A	Circulation (Hallway)	Hallway from Classroom 404 to Classroom 407	W4	Chipping	1	N	N	0	N	N	
343	2620	1	4	404A	Circulation (Hallway)	Hallway from Classroom 404 to Classroom 407	W3	Flaking	16	N	N	0	N	N	Additional Chipping
344	2620	1	4	H419	Circulation (Hallway)	Hallway from Classroom 421 to Classroom 423	W2	Flaking	15	N	N	0	N	N	6 Locations; Additional Cracking, Chipping
345	2620	1	4	H419	Circulation (Hallway)	Hallway from Classroom 421 to Classroom 423	W4	Flaking	216	N	N	0	N	N	Additional Cracking, Chipping
346	2620	1	4	H419	Circulation (Hallway)	Hallway from Classroom 421 to Classroom 423	Ceiling	Flaking	300	N	N	0	N	N	Additional Cracking
347	2620	1	4	H419	Circulation (Hallway)	Hallway from Classroom 421 to Classroom 423	W3	Gouges	1	N	N	0	N	N	
348	2620	1	4	H421	Circulation (Hallway)	Hallway from Classroom 432 to Classroom 434	W1	Flaking	129	Y	Y - On Radiators, Window Sills & Granite Apron	0	N	N	Additional Efflorescence; Damage on Entire Wall
349	2620	1	4	H421	Circulation (Hallway)	Hallway from Classroom 432 to Classroom 434	W3	Flaking	18	N	N	0	N	N	Additional Chipping
350	2620	1	4	H421	Circulation (Hallway)	Hallway from Classroom 432 to Classroom 434	Ceiling	Flaking	108	Y	Y - @ Wall 1	34	N	Y - 34 SF	2 Locations; Additional Efflorescence
351	2620	1	4	H422	Circulation (Hallway)	Hallway from Classroom 434 to Classroom 437	W4	Chipping	2	N	N	0	N	N	2 Locations; Additional Holes
352	2620	1	4	H422	Circulation (Hallway)	Hallway from Classroom 434 to Classroom 437	Ceiling	Efflorescence	17	Y	N	0	N	Y - 2 SF	2 Locations; Additional Cracking
353	2620	1	4	H422	Circulation (Hallway)	Hallway from Classroom 434 to Classroom 437	W2	Flaking	8	Y	Y - On Window Sill 5	1	N	Y - 1 SF	3 Locations; Additional Efflorescence, Chipping

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
354	2620	1	4	H417	Circulation (Hallway)	Hallway from IMC/Library to Room 411	W1	Chipping	2	N	N	0	N	N	
355	2620	1	4	H417	Circulation (Hallway)	Hallway from IMC/Library to Room 411	W3	Chipping	2	N	N	0	N	N	
356	2620	1	4	H417	Circulation (Hallway)	Hallway from IMC/Library to Room 411	W2	Flaking	135	N	N	0	N	N	3 Locations; Damage @ Radiator & Walls
357	2620	1	4	H417	Circulation (Hallway)	Hallway from IMC/Library to Room 411	Ceiling	Flaking	330	N	N	0	N	N	
358	2620	1	4	H423	Circulation (Hallway)	Hallway near Classroom 432 across to Classroom 437	W1	Chipping	10	N	N	0	N	N	2 Locations
359	2620	1	4	H423	Circulation (Hallway)	Hallway near Classroom 432 across to Classroom 437	Ceiling	Cracking	32	Y	N	0	N	N	Water Stains on Ceiling
360	2620	1	4	H423	Circulation (Hallway)	Hallway near Classroom 432 across to Classroom 437	W3	Flaking	28	N	N	0	N	N	Additional Chipping; Missing Piece of Granite Skirt
361	2620	1	4	406	IMC (Library)	Library/IMC	W1	Chipping	11	N	N	0	Y - 110 SF Bookcases, Books	N	2 Locations
362	2620	1	4	406	IMC (Library)	Library/IMC	W3	Flaking	30	N	Y - On Window Sills	20	N	N	3 Locations; Additional Chipping; Damage @ Wall & Radiators
363	2620	1	4	406	IMC (Library)	Library/IMC	W4	Flaking	30	N	Y - On Window Sills	11	N	N	3 Locations; Additional Chipping; Damage @ Wall & Radiators
364	2620	1	4	406	IMC (Library)	Library/IMC	Ceiling	Flaking	2	Y	N	0	N	N	Suspended Ceiling; Water Stain @ Vent by Window 7 on Wall 4; Missing Ceiling Tile Above Window 1 on Wall 3
365	2620	1	4	406D	Restrooms, Staff - Male/Female	Mechanical Room Unused Restroom	W1	Chipping	3	N	N	0	N	N	
366	2620	1	4	406D	Restrooms, Staff - Male/Female	Mechanical Room Unused Restroom	W2	Cracking	23	N	N	0	N	N	Additional Chipping
367	2620	1	4	406D	Restrooms, Staff - Male/Female	Mechanical Room Unused Restroom	W3	Cracking	23	N	N	0	N	N	
368	2620	1	4	406D	Restrooms, Staff - Male/Female	Mechanical Room Unused Restroom	Ceiling	Flaking	0	N	N	0	N	Y - 70 SF	Additional Cracking
369	2620	1	4	S414	Stairs	Middle Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
370	2620	1	4	S414	Stairs	Middle Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
371	2620	1	4	S414	Stairs	Middle Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
372	2620	1	4	S414	Stairs	Middle Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
373	2620	1	4	S414	Stairs	Middle Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
374	2620	1	4	S414	Stairs	Middle Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
375	2620	1	4	402A	Space (Science Lab Prep)	Room 403 Prep Lab between Classrooms 401 and 404	W3	Flaking	6	Y	Y - On Window Sills	12	N	N	3 Locations; Additional Efflorescence
376	2620	1	4	404B	Space (Science Lab Prep)	Room 406 Lab Prep Room	W3	Flaking	4	Y	Y - @Window Sills	9	Y - 14 SF Contents	Y - 4 SF	2 Locations; Additional Efflorescence
377	2620	1	4	404B	Space (Science Lab Prep)	Room 406 Lab Prep Room	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Lab Hood, Contents	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
378	2620	1	4	404B	Space (Science Lab Prep)	Room 406 Lab Prep Room	W4	Partially Inaccessible	0	N	N	0	Y - 114 SF Contents	N	
379	2620	1	4	406I	Administrative Office	Room 409A Library/IMC Office	W3	Chipping	10	N	N	0	N	N	Chipping @ Radiator
380	2620	1	4	406I	Administrative Office	Room 409A Library/IMC Office	W1	Cracking	4	N	N	0	N	N	2 Locations
381	2620	1	4	406I	Administrative Office	Room 409A Library/IMC Office	W2	Cracking	8	N	N	0	N	N	
382	2620	1	4	406I	Administrative Office	Room 409A Library/IMC Office	W4	Holes	1	N	N	0	N	N	
383	2620	1	4	406F	Administrative Office	Room 409B Library/IMC Office	W3	Chipping	10	N	N	0	N	N	Chipping @ Radiator
384	2620	1	4	406F	Administrative Office	Room 409B Library/IMC Office	W4	Chipping	2	N	N	0	Y - 32 SF Bookcases, Boxes, Tables	N	2 Locations
385	2620	1	4	406F	Administrative Office	Room 409B Library/IMC Office	W1	Cracking	1	N	N	0	Y - 10 SF Bookcases	N	
386	2620	1	4	406G	Student Restrooms - Male (4-12)	Room 409D Male Restroom in Library/IMC	Floor	Chipping	128	N	N	0	N	N	
387	2620	1	4	406G	Student Restrooms - Male (4-12)	Room 409D Male Restroom in Library/IMC	W4	Flaking	1	N	N	0	N	N	
388	2620	1	4	406E	Storage	Room 410 Storage Room	W4	Chipping	12	N	N	0	N	N	
389	2620	1	4	406E	Storage	Room 410 Storage Room	W2	Flaking	24	N	N	0	N	N	2 Locations
390	2620	1	4	406E	Storage	Room 410 Storage Room	W3	Flaking	130	N	N	0	Y - 30 SF Contents	N	Additional Cracking
391	2620	1	4	406E	Storage	Room 410 Storage Room	Ceiling	Flaking	22	Y	N	0	N	Y - 2 SF	3 Locations; Damage @ Missing Ceiling Tile; Water Stains on Ceiling Tiles
392	2620	1	4	407C	Administrative Office	Room 412 General Use Room	W1	Chipping	1	N	N	0	Y - 18 SF Tables, Lockers	N	
393	2620	1	4	407C	Administrative Office	Room 412 General Use Room	W2	Flaking	2	N	N	0	N	N	2 Locations
394	2620	1	4	407C	Administrative Office	Room 412 General Use Room	W3	Flaking	6	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Holes
395	2620	1	4	407C	Administrative Office	Room 412 General Use Room	W4	Flaking	1	N	N	0	N	N	Flaking @ Pipe
396	2620	1	4	407C	Administrative Office	Room 412 General Use Room	Ceiling	Flaking	58	Y	N	0	N	Y - 50	3 Locations; Additional Efflorescence, Cracking
397	2620	1	4	407C	Administrative Office	Room 412 General Use Room	Floor	Flaking	6	N	Y - @ Wall 3	1	N	N	Additional Chipping
398	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	W1	Flaking	13	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
399	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	W2	Flaking	3	N	N	0	N	N	Flaking @ Top of Wall
400	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	W3	Flaking	24	Y	Y - On Window Sills	6	N	Y - 7 SF	2 Locations; Additional Efflorescence, Cracking
401	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	Ceiling	Flaking	284	N	N	0	N	N	
402	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	W4	Partially Inaccessible	0	N	N	0	Y - 36 SF Books, Contents	N	
403	2620	1	4	408A	Teacher Lounge/Dining	Room 418 Staff Lounge	Floor	Partially Inaccessible	0	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
423	2620	1	4	412H	Storage	Room 429 Physics/Robotics Lab Storage Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
424	2620	1	4	412H	Storage	Room 429 Physics/Robotics Lab Storage Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
425	2620	1	4	412H	Storage	Room 429 Physics/Robotics Lab Storage Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
426	2620	1	4	S42	Stairs	Stairwell near Classroom 401	W3	Chipping	3	N	N	0	N	N	Chipping @ Door
427	2620	1	4	S42	Stairs	Stairwell near Classroom 401	Floor	Chipping	16	N	N	0	N	N	Chipping @ Skirt
428	2620	1	4	S42	Stairs	Stairwell near Classroom 401	Center Banister	Chipping	4	N	N	0	N	N	
429	2620	1	4	S41	Stairs	Stairwell near Classroom 429	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
430	2620	1	4	S41	Stairs	Stairwell near Classroom 429	Center Banister	Chipping	4	N	N	0	N	N	
431	2620	1	4	S41	Stairs	Stairwell near Classroom 429	W2	Cracking	12	N	N	0	N	N	
432	2620	1	4	S41	Stairs	Stairwell near Classroom 429	W3	Flaking	6	N	N	0	N	N	Additional Chipping
433	2620	1	4	S47	Stairs	Stairwell next to IMC/Library	W3	Chipping	4	N	N	0	N	N	
434	2620	1	4	S47	Stairs	Stairwell next to IMC/Library	Floor	Chipping	9	N	N	0	N	N	
435	2620	1	4	S47	Stairs	Stairwell next to IMC/Library	Center Banister	Chipping	6	N	N	0	N	N	
436	2620	1	4	S47	Stairs	Stairwell next to IMC/Library	W2	Cracking	75	N	N	0	N	Y - 60 SF	2 Locations; Plaster Protruding from Wall
437	2620	1	4	S47	Stairs	Stairwell next to IMC/Library	W1	Flaking	10	N	N	0	N	N	Additional Chipping; Damage @ Radiator
438	2620	1	4	S410	Stairs	Stairwell next to Room 411	W1	Chipping	2	N	N	0	N	N	2 Locations
439	2620	1	4	S410	Stairs	Stairwell next to Room 411	Floor	Chipping	4	N	N	0	N	N	
440	2620	1	4	S410	Stairs	Stairwell next to Room 411	Center Banister	Chipping	4	N	N	0	N	N	
441	2620	1	4	S410	Stairs	Stairwell next to Room 411	W4	Cracking	24	N	N	0	N	N	
442	2620	1	4	S410	Stairs	Stairwell next to Room 411	W2	Flaking	5	N	N	0	N	N	2 Locations; Additional Chipping
443	2620	1	4	S410	Stairs	Stairwell next to Room 411	W3	Flaking	10	N	N	0	N	N	Flaking @ Radiator
444	2620	1	4	418	Storage	Storage Room in Small Hallway	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
445	2620	1	4	418	Storage	Storage Room in Small Hallway	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
446	2620	1	4	418	Storage	Storage Room in Small Hallway	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
447	2620	1	4	418	Storage	Storage Room in Small Hallway	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
448	2620	1	4	418	Storage	Storage Room in Small Hallway	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
449	2620	1	4	418	Storage	Storage Room in Small Hallway	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
450	2620	1	3	309B	Storage	Book Closet across from Classroom 305	Ceiling	Cracking	8	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
451	2620	1	3	309B	Storage	Book Closet across from Classroom 305	W2	Partially Inaccessible	0	N	N	0	Y - 70 SF Shelves, Contents	N	
452	2620	1	3	309B	Storage	Book Closet across from Classroom 305	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Shelves, Contents	N	
453	2620	1	3	309B	Storage	Book Closet across from Classroom 305	W4	Partially Inaccessible	0	N	N	0	Y - 70 SF Shelves, Contents	N	
454	2620	1	3	308A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 306	W4	Cracking	2	N	N	0	N	N	
455	2620	1	3	308A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 306	W3	Efflorescence	6	Y	Y - @ Window Sill 2	1	N	Y - 6 SF	
456	2620	1	3	308A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 306	W1	Flaking	22	N	N	0	N	N	3 Locations; Additional Chipping, Holes; Flaking @ Doorway From Sink to Stalls
457	2620	1	3	308A	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 306	W2	Flaking	1	N	N	0	N	N	
458	2620	1	3	303	Senior High	Classroom 304	W4	Cracking	6	N	N	0	Y - 24 SF Desks, Computers	N	
459	2620	1	3	303	Senior High	Classroom 304	W1	Flaking	3	N	N	0	Y - 28 SF Desks, Computers	N	3 Locations; Additional Chipping, Gouges
460	2620	1	3	303	Senior High	Classroom 304	W3	Flaking	78	Y	Y - @ Window Sills	3	Y - 72 SF Desks, Computers	Y - 4 SF	Additional Efflorescence
461	2620	1	3	303	Senior High	Classroom 304	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks	N	
462	2620	1	3	304	Senior High	Classroom 305	W1	Chipping	1	N	N	0	Y - 40 SF Posters	N	
463	2620	1	3	304	Senior High	Classroom 305	W3	Flaking	18	Y	Y - @ Radiator	1	Y - 22 SF Posters	Y - 6 SF	
464	2620	1	3	304	Senior High	Classroom 305	W4	Flaking	1	N	N	0	Y - 56 SF Shelves, Contents	N	
465	2620	1	3	304	Senior High	Classroom 305	W2	Gouges	1	N	N	0	N	N	
466	2620	1	3	305	Senior High	Classroom 306	W1	Chipping	3	N	N	0	Y - 8 SF Posters	N	3 Locations
467	2620	1	3	305	Senior High	Classroom 306	W2	Chipping	1	N	N	0	N	N	
468	2620	1	3	305	Senior High	Classroom 306	W4	Cracking	16	N	N	0	Y - 16 SF Posters	N	
469	2620	1	3	305	Senior High	Classroom 306	W3	Flaking	24	Y	N	0	Y - 42 SF Bookcases	Y - 4 SF	2 Locations; Additional Efflorescence
470	2620	1	3	306	Senior High	Classroom 307	W1	Chipping	18	N	N	0	N	N	Chipping @ Blackboard Trim
471	2620	1	3	306	Senior High	Classroom 307	W2	Chipping	16	N	N	0	N	N	2 Locations
472	2620	1	3	306	Senior High	Classroom 307	W3	Flaking	16	Y	N	0	Y - 48 SF Bookcases, Desks, Contents	Y - 16 SF	Additional Efflorescence
473	2620	1	3	306	Senior High	Classroom 307	W4	Flaking	40	N	N	0	Y - 40 SF Bookcases, Contents	N	Additional Chipping
474	2620	1	3	309	Senior High	Classroom 321	W1	Flaking	2	N	N	0	Y - 8 SF Desks, Posters	N	

Palumbo -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
475	2620	1	3	309	Senior High	Classroom 321	W2	Flaking	2	N	N	0	Y - 28 SF Posters	N	
476	2620	1	3	309	Senior High	Classroom 321	W3	Flaking	5	N	Y - @ Window 3	1	N	N	2 Locations
477	2620	1	3	309	Senior High	Classroom 321	Ceiling	Flaking	64	N	N	0	N	N	5 Locations
478	2620	1	3	309	Senior High	Classroom 321	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF File Cabinets, Desks	N	
479	2620	1	3	310	Senior High	Classroom 322	W2	Cracking	26	N	N	0	Y - 24 SF File Cabinets, Copier	N	2 Locations; Additional Chipping
480	2620	1	3	310	Senior High	Classroom 322	W1	Flaking	7	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
481	2620	1	3	310	Senior High	Classroom 322	W3	Flaking	27	N	N	0	N	N	6 Locations; Additional Chipping
482	2620	1	3	310	Senior High	Classroom 322	W4	Flaking	26	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
483	2620	1	3	310	Senior High	Classroom 322	Ceiling	Flaking	32	Y	N	0	N	Y - 8 SF	2 Locations; Additional Efflorescence
484	2620	1	3	311	Senior High	Classroom 323	W4	Cracking	12	N	N	0	Y - 24 SF Desks, Posters	N	
485	2620	1	3	311	Senior High	Classroom 323	W1	Flaking	48	N	N	0	N	N	Additional Chipping
486	2620	1	3	311	Senior High	Classroom 323	W2	Flaking	63	N	N	0	N	N	Additional Chipping
487	2620	1	3	311	Senior High	Classroom 323	W3	Flaking	12	N	N	0	N	N	3 Locations; Additional Chipping
488	2620	1	3	311	Senior High	Classroom 323	Ceiling	Flaking	31	N	N	0	N	Y - 9 SF	5 Locations; Additional Efflorescence, Cracking, Chipping
489	2620	1	3	312	Senior High	Classroom 324	W1	Chipping	4	N	N	0	Y - 12 SF Posters	N	2 Locations
490	2620	1	3	312	Senior High	Classroom 324	W3	Flaking	32	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
491	2620	1	3	312	Senior High	Classroom 324	Ceiling	Flaking	24	N	N	0	N	N	
492	2620	1	3	312	Senior High	Classroom 324	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Bookcases, Books, Desks	N	
493	2620	1	3	319	Senior High	Classroom 329 Music	W4	Chipping	8	N	N	0	Y - 72 SF Music Equipment	N	
494	2620	1	3	319	Senior High	Classroom 329 Music	Floor	Chipping	140	N	N	0	N	N	Chipping @ Perimeter
495	2620	1	3	319	Senior High	Classroom 329 Music	W1	Flaking	12	N	N	0	Y - 400 SF Music Equipment	N	3 Locations; Additional Cracking, Chipping
496	2620	1	3	319	Senior High	Classroom 329 Music	W2	Flaking	16	N	N	0	Y - 60 SF Bookcases, Contents	N	Additional Chipping
497	2620	1	3	319	Senior High	Classroom 329 Music	W3	Flaking	42	N	N	0	Y - 200 SF Music Equipment	N	2 Locations; Additional Cracking
498	2620	1	3	314	Senior High	Classroom 332	W1	Flaking	10	N	N	0	Y - 10 SF Posters	N	3 Locations; Additional Cracking, Chipping
499	2620	1	3	314	Senior High	Classroom 332	W2	Flaking	6	N	N	0	Y - 16 SF Posters	N	Additional Chipping
500	2620	1	3	314	Senior High	Classroom 332	W3	Flaking	35	Y	Y - On Window Sills	5	N	Y - 26 SF	4 Locations; Additional Efflorescence; Damage @ Wall, Pipes, Radiators

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
501	2620	1	3	314	Senior High	Classroom 332	W4	Partially Inaccessible	0	N	N	0	Y - 42 SF File Cabinets, Desks, Bookcases, Contents	N	
502	2620	1	3	315	Senior High	Classroom 333	Floor	Chipping	4	N	Y - Under Windows	32	N	N	
503	2620	1	3	315	Senior High	Classroom 333	W2	Cracking	10	N	N	0	N	N	2 Locations; Additional Chipping
504	2620	1	3	315	Senior High	Classroom 333	W4	Cracking	5	N	N	0	Y - 26 SF Posters	N	3 Locations; Additional Efflorescence, Chipping, Holes
505	2620	1	3	315	Senior High	Classroom 333	W1	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
506	2620	1	3	315	Senior High	Classroom 333	W3	Flaking	44	Y	Y - @ Window Sills	4	N	Y - 32 SF	3 Locations; Additional Efflorescence, Chipping
507	2620	1	3	315	Senior High	Classroom 333	Ceiling	Flaking	864	Y	N	0	N	Y - 4 SF	Additional Efflorescence
508	2620	1	3	315A	Storage	Classroom 333 Storage Room	Ceiling	Cracking	144	N	N	0	N	N	
509	2620	1	3	315A	Storage	Classroom 333 Storage Room	W1	Flaking	32	N	N	0	Y - 96 SF Shelves, Contents	N	2 Locations; Additional Cracking
510	2620	1	3	315A	Storage	Classroom 333 Storage Room	W3	Flaking	288	Y	N	0	Y - 80 SF Shelves, Contents	Y - 32 SF	Additional Efflorescence, Cracking
511	2620	1	3	315A	Storage	Classroom 333 Storage Room	W4	Flaking	72	N	N	0	N	N	2 Locations; Flaking @ Wall & Radiator
512	2620	1	3	315A	Storage	Classroom 333 Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Shelves, Contents	N	
513	2620	1	3	316	Senior High	Classroom 334	Ceiling	Flaking	20	Y	N	0	N	N	
514	2620	1	3	316	Senior High	Classroom 334	W1	Partially Inaccessible	0	N	N	0	Y - 60 SF Desks, Posters	N	
515	2620	1	3	316	Senior High	Classroom 334	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Posters	N	
516	2620	1	3	316	Senior High	Classroom 334	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Desks, Posters	N	
517	2620	1	3	316	Senior High	Classroom 334	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Desks, Posters	N	
518	2620	1	3	316A	Senior High	Classroom 335	W1	Cracking	4	N	N	0	N	N	2 Locations; Additional Chipping
519	2620	1	3	316A	Senior High	Classroom 335	W2	Flaking	112	N	Y - @ Window Sill 1 & 3	2	Y - 20 SF Radiator Covers	N	2 Locations; Additional Cracking; Damage @ Wall & Radiators
520	2620	1	3	316A	Senior High	Classroom 335	W4	Flaking	15	N	N	0	Y - 40 SF Music Equipment	N	Additional Cracking
521	2620	1	3	316A	Senior High	Classroom 335	W3	Gouges	1	N	N	0	Y - 38 SF Bookcases, Drums	N	
522	2620	1	3	316B	Storage	Classroom 335 Storage Room	W1	Cracking	40	N	N	0	Y - 30 SF Shelves, Contents	N	
523	2620	1	3	316B	Storage	Classroom 335 Storage Room	W2	Cracking	96	N	N	0	N	N	Cracking on Entire Wall
524	2620	1	3	316B	Storage	Classroom 335 Storage Room	W4	Cracking	72	N	N	0	Y - 30 SF Contents	N	
525	2620	1	3	316B	Storage	Classroom 335 Storage Room	W3	Flaking	96	N	N	0	Y - 24 SF Music Equipment	N	Additional Cracking
526	2620	1	3	316B	Storage	Classroom 335 Storage Room	Ceiling	Flaking	32	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
527	2620	1	3	317	Senior High	Classroom 336	W4	Cracking	12	N	N	0	N	N	
528	2620	1	3	317	Senior High	Classroom 336	W1	Flaking	72	N	N	0	Y - 20 SF Cabinets	N	5 Locations; Additional Cracking, Chipping
529	2620	1	3	317	Senior High	Classroom 336	W2	Flaking	44	N	N	0	N	N	Additional Chipping
530	2620	1	3	317	Senior High	Classroom 336	W3	Flaking	44	Y	Y - @ Window Sills & On Piano	36	N	Y - 36 SF	5 Locations; Additional Efflorescence, Chipping; Damage on Window Frames, Wall, Radiators, & Wall Behind Radiators
531	2620	1	3	317	Senior High	Classroom 336	Ceiling	Flaking	18	Y	N	0	N	Y - 18 SF	2 Locations; Additional Efflorescence
532	2620	1	3	317A	Storage	Classroom 336 Storage Room	W4	Cracking	36	N	N	0	Y - 42 SF Shelves, Contents	N	
533	2620	1	3	317A	Storage	Classroom 336 Storage Room	W1	Flaking	28	N	Y - On Shelf	2	Y - 28 SF Shelves, Contents	N	Additional Cracking, Chipping
534	2620	1	3	317A	Storage	Classroom 336 Storage Room	W2	Flaking	80	Y	Y - @ Window Sill	2	N	Y - 80 SF	Additional Efflorescence
535	2620	1	3	317A	Storage	Classroom 336 Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 72 SF File Cabinets, Cabinets	N	
536	2620	1	3	318	Senior High	Classroom 337	W4	Chipping	3	N	N	0	N	N	2 Locations; Additional Holes
537	2620	1	3	318	Senior High	Classroom 337	W3	Flaking	12	Y	Y - @ Window Sills 1, 2 & 4	6	N	Y - 2 SF	2 Locations; Additional Efflorescence, Cracking
538	2620	1	3	318	Senior High	Classroom 337	Ceiling	Flaking	12	Y	N	0	N	Y - 2 SF	3 Locations; Additional Efflorescence
539	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
540	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
541	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
542	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
543	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
544	2620	1	3	303A	Administrative Office	Computer Support Office near Classroom 304	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
545	2620	1	3	313	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 302	W1	Chipping	3	N	N	0	N	N	Chipping @ Stalls
546	2620	1	3	313	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 302	W2	Chipping	2	N	N	0	N	N	
547	2620	1	3	313	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 302	W3	Chipping	5	N	N	0	N	N	3 Locations
548	2620	1	3	307A	Space (Gym)	Gymnasium Balcony	W2	Cracking	4	N	N	0	N	N	
549	2620	1	3	307A	Space (Gym)	Gymnasium Balcony	W1	Flaking	36	N	N	0	N	N	
550	2620	1	3	307A	Space (Gym)	Gymnasium Balcony	Ceiling	Flaking	2	N	N	0	N	N	
551	2620	1	3	H316	Circulation (Hallway)	Hallway along Classroom 329	Ceiling	Chipping	1	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
577	2620	1	3	S314	Stairs	Middle Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
578	2620	1	3	S314	Stairs	Middle Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
579	2620	1	3	301	Administrative Office	Room 301 School Store	W1	Chipping	2	N	N	0	N	N	
580	2620	1	3	301	Administrative Office	Room 301 School Store	W3	Flaking	10	N	Y - @ Window Sills	3	N	N	Additional Chipping
581	2620	1	3	301	Administrative Office	Room 301 School Store	W4	Partially Inaccessible	0	N	N	0	Y - 49 SF Cabinets	N	
582	2620	1	3	302	Administrative Office	Room 302 Dean's Office	W3	Efflorescence	4	Y	N	0	Y - 48 SF Bookcases, Radiator Covers	Y - 4 SF	Damage Behind Radiator Covers
583	2620	1	3	302	Administrative Office	Room 302 Dean's Office	W1	Flaking	5	N	N	0	Y - 10 SF File Cabinets	N	Additional Chipping
584	2620	1	3	302	Administrative Office	Room 302 Dean's Office	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF File Cabinets, Bookcases	N	
585	2620	1	3	302	Administrative Office	Room 302 Dean's Office	W4	Partially Inaccessible	0	N	N	0	Y - 44 SF Desks, Posters, Contents	N	
586	2620	1	3	302A	Administrative Office	Room 303 Counselor's Office	W1	Chipping	2	N	N	0	N	N	
587	2620	1	3	302A	Administrative Office	Room 303 Counselor's Office	W3	Flaking	2	Y	N	0	N	Y - 2 SF	Additional Efflorescence
588	2620	1	3	308C	Senior High	Room 311 Weight Lifting Room	W1	Flaking	35	N	N	0	N	N	Additional Cracking, Gouges
589	2620	1	3	308C	Senior High	Room 311 Weight Lifting Room	W2	Flaking	30	N	N	0	N	N	Additional Chipping
590	2620	1	3	308C	Senior High	Room 311 Weight Lifting Room	W3	Flaking	20	Y	Y - On Window Sills & Radiators	26	N	N	Additional Efflorescence, Cracking
591	2620	1	3	308C	Senior High	Room 311 Weight Lifting Room	W4	Flaking	32	N	N	0	N	N	2 Locations; Additional Cracking, Gouges
592	2620	1	3	308C	Senior High	Room 311 Weight Lifting Room	Ceiling	Flaking	616	N	N	0	N	N	Damage on Entire Ceiling
593	2620	1	3	308	Senior High	Room 312 Cardio Room	W1	Cracking	12	N	N	0	Y - 21 SF Contents	N	5 Locations; Additional Chipping
594	2620	1	3	308	Senior High	Room 312 Cardio Room	W4	Cracking	15	N	N	0	N	N	Cracking @ Corner of Walls 1 & 4
595	2620	1	3	308	Senior High	Room 312 Cardio Room	W2	Flaking	47	N	N	0	N	N	2 Locations; Additional Cracking
596	2620	1	3	308	Senior High	Room 312 Cardio Room	W3	Flaking	100	Y	Y - On Window Sills	4	N	Y - 2 SF	5 Locations; Additional Efflorescence, Cracking, Holes
597	2620	1	3	308	Senior High	Room 312 Cardio Room	Ceiling	Flaking	672	N	N	0	N	N	Damage on Entire Ceiling
598	2620	1	3	309A	Teacher Lounge/Dining	Room 318 Men's Lounge	W1	Cracking	6	N	N	0	Y - 24 SF Boxes	N	2 Locations; Additional Chipping; Damage Above Door & On Wall
599	2620	1	3	309A	Teacher Lounge/Dining	Room 318 Men's Lounge	W2	Cracking	7	N	N	0	N	N	3 Locations
600	2620	1	3	309A	Teacher Lounge/Dining	Room 318 Men's Lounge	W3	Flaking	5	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Radiator & Pipe
601	2620	1	3	309A	Teacher Lounge/Dining	Room 318 Men's Lounge	W4	Flaking	33	N	N	0	Y - 16 SF Boxes	N	2 Locations; Additional Cracking
602	2620	1	3	309C	Restrooms, Staff - Male	Room 318 Men's Lounge Restroom	W2	Holes	1	N	N	0	N	N	
603	2620	1	3	309C	Restrooms, Staff - Male	Room 318 Men's Lounge Restroom	W3	Holes	1	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
604	2620	1	3	309C	Restrooms, Staff - Male	Room 318 Men's Lounge Restroom	W4	Holes	1	N	N	0	N	N	
605	2620	1	3	309D	Storage	Room 319 Electrical	W1	Flaking	120	N	N	0	N	N	Additional Cracking
606	2620	1	3	309D	Storage	Room 319 Electrical	W2	Flaking	125	N	N	0	N	N	
607	2620	1	3	309D	Storage	Room 319 Electrical	W3	Flaking	120	N	N	0	N	N	Additional Cracking
608	2620	1	3	309D	Storage	Room 319 Electrical	W4	Flaking	125	N	N	0	N	N	Y - 1 SF
609	2620	1	3	309D	Storage	Room 319 Electrical	Ceiling	Flaking	40	N	N	0	N	N	
610	2620	1	3	320	Administrative Office	Room 338 Staff Lounge used for Music Instrument Storage	W1	Cracking	4	N	N	0	N	N	
611	2620	1	3	320	Administrative Office	Room 338 Staff Lounge used for Music Instrument Storage	W2	Flaking	3	N	Y - On Table	4	Y - 24 SF Music Equipment, Table	N	Additional Chipping
612	2620	1	3	320	Administrative Office	Room 338 Staff Lounge used for Music Instrument Storage	Ceiling	Flaking	24	N	N	0	N	Y - 8 SF	Additional Efflorescence, Holes
613	2620	1	3	320	Administrative Office	Room 338 Staff Lounge used for Music Instrument Storage	W3	Partially Inaccessible	0	N	N	0	Y - 90 SF Music Equipment	N	
614	2620	1	3	S37	Stairs	Stairwell near Classroom 307	Center Banister	Chipping	6	N	N	0	N	N	
615	2620	1	3	S37	Stairs	Stairwell near Classroom 307	Floor	Chipping	5	N	N	0	N	N	
616	2620	1	3	S37	Stairs	Stairwell near Classroom 307	W2	Cracking	45	N	N	0	N	Y - 45 SF	Plaster Wall Protruding
617	2620	1	3	S37	Stairs	Stairwell near Classroom 307	W3	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping
618	2620	1	3	S31	Stairs	Stairwell near Classroom 329	W1	Chipping	1	N	N	0	N	N	
619	2620	1	3	S31	Stairs	Stairwell near Classroom 329	W2	Chipping	2	N	N	0	N	N	
620	2620	1	3	S31	Stairs	Stairwell near Classroom 329	W4	Chipping	8	N	N	0	N	N	
621	2620	1	3	S31	Stairs	Stairwell near Classroom 329	Floor	Chipping	6	N	N	0	N	N	
622	2620	1	3	S31	Stairs	Stairwell near Classroom 329	Center Banister	Chipping	2	N	N	0	N	N	
623	2620	1	3	S32	Stairs	Stairwell near Room 301 and Elevator No. 1	W2	Chipping	4	N	N	0	N	N	Chipping @ Granite Apron
624	2620	1	3	S32	Stairs	Stairwell near Room 301 and Elevator No. 1	W3	Chipping	1	N	N	0	N	N	
625	2620	1	3	S32	Stairs	Stairwell near Room 301 and Elevator No. 1	Floor	Chipping	4	N	N	0	N	N	
626	2620	1	3	S32	Stairs	Stairwell near Room 301 and Elevator No. 1	Center Banister	Flaking	24	N	N	0	N	N	Additional Chipping; Damage @ Skirt
627	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	W2	Chipping	4	N	N	0	N	N	
628	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	W3	Chipping	10	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
629	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	W4	Chipping	2	N	N	0	N	N	
630	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	Floor	Chipping	8	N	N	0	N	N	
631	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	Center Banister	Chipping	3	N	N	0	N	N	
632	2620	1	3	S310	Stairs	Stairwell next to Room 311 Weight Lifting Room	Ceiling	Flaking	1	N	N	0	N	N	Flaking @ Landing Between 3rd & 4th Floors
633	2620	1	2	216	Auditorium Balcony	Auditorium Balcony-Room 232	W3	Flaking	17	Y	N	0	N	Y - 17 SF	2 Locations; Additional Efflorescence
634	2620	1	2	216	Auditorium Balcony	Auditorium Balcony-Room 232	W4	Flaking	848	Y	N	0	N	Y - 60 SF	Additional Efflorescence
635	2620	1	2	216	Auditorium Balcony	Auditorium Balcony-Room 232	Ceiling	Flaking	40	Y	N	0	N	Y - 40 SF	Additional Efflorescence
636	2620	1	2	216	Auditorium Balcony	Auditorium Balcony-Room 232	Floor	Flaking	60	N	Y - Under Efflorescence	48	N	N	Additional Chipping; Damage On Vertical Surface Beneath Seating
637	2620	1	2	206	Lockers - Male	Boys' New Locker Room	W1	Chipping	9	N	N	0	N	N	Additional Gouges
638	2620	1	2	206	Lockers - Male	Boys' New Locker Room	Floor	Chipping	36	N	N	0	N	N	
639	2620	1	2	206	Lockers - Male	Boys' New Locker Room	W2	Flaking	2	N	N	0	N	N	2 Locations; Additional Cracking, Holes; 2 SF Sheetrock Needed
640	2620	1	2	206	Lockers - Male	Boys' New Locker Room	W3	Flaking	22	N	N	0	N	N	Additional Chipping
641	2620	1	2	206	Lockers - Male	Boys' New Locker Room	Ceiling	Flaking	14	N	N	0	N	N	Flaking @ Above Windows
642	2620	1	2	206C	Student Restrooms - Male (4-12)	Boys' New Locker Room Restroom	W2	Gouges	1	N	N	0	N	N	
643	2620	1	2	206D	Showers - Male	Boys' New Locker Room Showers	W4	Cracking	1	N	N	0	N	N	
644	2620	1	2	214	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 201	W2	Cracking	4	N	N	0	N	N	
645	2620	1	2	214	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 201	W3	Cracking	4	N	N	0	N	N	2 Locations
646	2620	1	2	214	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 201	W1	Flaking	8	N	N	0	N	N	2 Locations
647	2620	1	2	214	Student Restrooms - Male (4-12)	Boys' Restroom across from Classroom 201	W4	Flaking	6	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
648	2620	1	2	201B	Senior High	Classroom 204	W1	Flaking	26	N	N	0	Y - 22 SF Bookcases, Posters	N	2 Locations; Additional Chipping; Damage @ Wall & Forced Air Duct
649	2620	1	2	201B	Senior High	Classroom 204	W2	Flaking	9	N	N	0	Y - 28 SF Bookcases, Posters	Y - 1 SF	Additional Cracking, Chipping, Gouges
650	2620	1	2	201B	Senior High	Classroom 204	W3	Flaking	20	N	Y - @ Window Sills 1-3 & Window Shades	12	N	Y - 2 SF	3 Locations; Additional Cracking, Chipping

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
651	2620	1	2	201B	Senior High	Classroom 204	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Bookcases, Posters, Desks	N	
652	2620	1	2	203	Senior High	Classroom 205	W1	Chipping	2	N	N	0	N	N	2 Locations
653	2620	1	2	203	Senior High	Classroom 205	W3	Flaking	2	N	Y - @ Window Sills	18	N	N	Flaking @ Window Frame 3
654	2620	1	2	203	Senior High	Classroom 205	Ceiling	Flaking	12	Y	N	0	N	N	Suspended Ceiling; 12 SF Missing Ceiling Tiles @ Windows 1-3
655	2620	1	2	203	Senior High	Classroom 205	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, File Cabinets	N	
656	2620	1	2	204	Senior High	Classroom 206	W2	Chipping	4	N	N	0	N	N	2 Locations
657	2620	1	2	204	Senior High	Classroom 206	W1	Cracking	5	N	N	0	N	N	
658	2620	1	2	204	Senior High	Classroom 206	W3	Flaking	26	N	Y - @ Window Sills	3	N	Y - 3 SF	3 Locations; Flaking @ Radiator, Wall, Behind Pipes
659	2620	1	2	204	Senior High	Classroom 206	Ceiling	Flaking	60	N	N	0	N	N	2 Locations
660	2620	1	2	205	Senior High	Classroom 207	W1	Chipping	3	N	N	0	Y - 40 SF Posters	N	3 Locations
661	2620	1	2	205	Senior High	Classroom 207	W2	Chipping	24	N	N	0	Y - 20 SF Posters	N	Chipping @ Whiteboard
662	2620	1	2	205	Senior High	Classroom 207	W3	Flaking	24	Y	N	0	N	N	3 Locations; Additional Spalling, Chipping
663	2620	1	2	205	Senior High	Classroom 207	W4	Flaking	20	N	N	0	Y - 20 SF Posters	N	Additional Chipping
664	2620	1	2	205	Senior High	Classroom 207	Ceiling	Flaking	720	N	N	0	N	N	
665	2620	1	2	208	Senior High	Classroom 221	W2	Chipping	1	N	N	0	Y - 24 SF Desks	N	
666	2620	1	2	208	Senior High	Classroom 221	W1	Flaking	3	N	N	0	Y - 12 SF Bookcases	N	2 Locations; Additional Cracking, Chipping
667	2620	1	2	208	Senior High	Classroom 221	W4	Flaking	10	N	N	0	N	N	3 Locations; Additional Cracking; Missing Moulding
668	2620	1	2	208	Senior High	Classroom 221	Ceiling	Flaking	672	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
669	2620	1	2	208	Senior High	Classroom 221	W3	Holes	1	N	Y - @ Window Sills	6	N	N	
670	2620	1	2	209	Senior High	Classroom 223	W2	Chipping	6	N	N	0	Y - 16 SF Bookcases, Cabinets	N	6 Locations
671	2620	1	2	209	Senior High	Classroom 223	W4	Cracking	12	N	N	0	N	N	
672	2620	1	2	209	Senior High	Classroom 223	W1	Flaking	2	N	N	0	N	N	2 Locations; Additional Chipping; Damage Includes Wall & Forced Air Duct
673	2620	1	2	209	Senior High	Classroom 223	W3	Flaking	12	N	N	0	Y - 32 SF Radiator Cages	N	
674	2620	1	2	209	Senior High	Classroom 223	Ceiling	Flaking	40	Y	N	0	N	N	Flaking Above Windows; Water Stains on Ceiling Tiles
675	2620	1	2	209B	Storage	Classroom 223 Book Closet	W3	Chipping	6	N	N	0	Y - 70 SF Boxes	N	
676	2620	1	2	209B	Storage	Classroom 223 Book Closet	W1	Flaking	43	N	Y - Above Door	3	Y - 60 SF Bookcases, Books	N	Additional Cracking, Chipping
677	2620	1	2	209B	Storage	Classroom 223 Book Closet	W2	Flaking	14	N	Y - @ Window Sills	4	Y - 30 SF Boxes	N	Additional Cracking, Chipping
678	2620	1	2	209B	Storage	Classroom 223 Book Closet	Ceiling	Flaking	2	N	N	0	N	N	
679	2620	1	2	209B	Storage	Classroom 223 Book Closet	W4	Partially Inaccessible	0	N	N	0	Y - 96 SF Boxes	N	
680	2620	1	2	210	Senior High	Classroom 224	W3	Flaking	3	N	Y - @ Window Sills 3 & 4	6	N	N	2 Locations; Additional Holes

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
681	2620	1	2	210	Senior High	Classroom 224	Ceiling	Flaking	105	N	N	0	N	N	2 Locations; Water Stain on Suspended Ceiling Tiles
682	2620	1	2	210	Senior High	Classroom 224	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters	N	
683	2620	1	2	210	Senior High	Classroom 224	W2	Partially Inaccessible	0	N	N	0	Y - 45 SF Posters	N	
684	2620	1	2	210	Senior High	Classroom 224	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Posters	N	
685	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
686	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
687	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
688	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
689	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
690	2620	1	2	200	Administrative Office	General Office Area over Stage Right Stairs	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
691	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
692	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
693	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
694	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
695	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
696	2620	1	2	200A	Restrooms, Staff - Male/Female	General Office Area over Stage Right Stairs Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
697	2620	1	2	207A	Lockers - Female	Girls' Locker Room in Gym	W4	Chipping	1	N	N	0	Y - 72 SF Lockers	N	
698	2620	1	2	207A	Lockers - Female	Girls' Locker Room in Gym	W3	Flaking	17	N	Y - On Window Sills	18	N	N	3 Locations; Additional Cracking, Chipping; Damage @ Wall & Radiators
699	2620	1	2	207A	Lockers - Female	Girls' Locker Room in Gym	Ceiling	Flaking	28	Y	N	0	N	Y - 28 SF	Additional Efflorescence; Damage @ Windows
700	2620	1	2	207A	Lockers - Female	Girls' Locker Room in Gym	W1	Partially Inaccessible	0	N	N	0	Y - 168 SF Lockers	N	
701	2620	1	2	207C	Student Restrooms - Female (4-12)	Girls' Locker Room Restroom and Showers	W1	Flaking	1	Y	N	0	N	Y - 1 SF	Additional Efflorescence
702	2620	1	2	207C	Student Restrooms - Female (4-12)	Girls' Locker Room Restroom and Showers	W3	Flaking	5	Y	N	0	N	Y - 5 SF	Additional Efflorescence

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
703	2620	1	2	207C	Student Restrooms - Female (4-12)	Girls' Locker Room Restroom and Showers	W4	Flaking	32	Y	Y - On Window Sills & Radiator	8	N	Y - 8 SF	Additional Efflorescence
704	2620	1	2	207C	Student Restrooms - Female (4-12)	Girls' Locker Room Restroom and Showers	Ceiling	Flaking	40	Y	N	0	N	Y - 8 SF	2 Locations; Additional Efflorescence; Damage on Duct & Ceiling
705	2620	1	2	211	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 206	W1	Flaking	16	N	Y - @ Corner	1	N	N	4 Locations; Additional Cracking; Damage @ Granite Skirt
706	2620	1	2	211	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 206	W2	Flaking	3	N	N	0	N	N	2 Locations; Damage @ Wall & Pipe
707	2620	1	2	211	Student Restrooms - Female (4-12)	Girls' Restroom across from Classroom 206	W3	Flaking	16	N	Y - @ Corner of Wall 3 & 4	1	N	N	4 Locations; Additional Cracking, Chipping; Damage @ Wall, Pipes & Radiators
708	2620	1	2	207F	Storage	Gym Storage Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access; Personal Lock
709	2620	1	2	207F	Storage	Gym Storage Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
710	2620	1	2	207F	Storage	Gym Storage Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
711	2620	1	2	207F	Storage	Gym Storage Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
712	2620	1	2	207F	Storage	Gym Storage Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
713	2620	1	2	207F	Storage	Gym Storage Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
714	2620	1	2	207E	Storage	Gym Storage Area 209B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access; Personal Lock
715	2620	1	2	207E	Storage	Gym Storage Area 209B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
716	2620	1	2	207E	Storage	Gym Storage Area 209B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
717	2620	1	2	207E	Storage	Gym Storage Area 209B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
718	2620	1	2	207E	Storage	Gym Storage Area 209B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
719	2620	1	2	207E	Storage	Gym Storage Area 209B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
720	2620	1	2	H211	Circulation (Hallway)	Hallway along Classrooms 221 to 223	W3	Chipping	1	N	N	0	N	N	
721	2620	1	2	H211	Circulation (Hallway)	Hallway along Classrooms 221 to 223	Floor	Chipping	4	N	N	0	N	N	
722	2620	1	2	H211	Circulation (Hallway)	Hallway along Classrooms 221 to 223	W4	Flaking	4	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping, Holes
723	2620	1	2	H29	Circulation (Hallway)	Hallway along Gymnasium and Room 212	W1	Chipping	2	N	N	0	N	N	
724	2620	1	2	H29	Circulation (Hallway)	Hallway along Gymnasium and Room 212	W3	Chipping	1	N	N	0	N	N	
725	2620	1	2	H29	Circulation (Hallway)	Hallway along Gymnasium and Room 212	W2	Cracking	14	N	N	0	N	N	3 Locations; Additional Chipping
726	2620	1	2	H29	Circulation (Hallway)	Hallway along Gymnasium and Room 212	W4	Flaking	42	N	N	0	N	N	5 Locations; Additional Cracking, Chipping
727	2620	1	2	H212	Circulation (Hallway)	Hallway along Rooms 229 to 231	W1	Chipping	1	Y	Y - @ Granite Skirt	1	N	N	
728	2620	1	2	H212	Circulation (Hallway)	Hallway along Rooms 229 to 231	W3	Chipping	1	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
729	2620	1	2	H212	Circulation (Hallway)	Hallway along Rooms 229 to 231	Floor	Chipping	8	N	N	0	N	N	Chipping @ Perimeter
730	2620	1	2	H212	Circulation (Hallway)	Hallway along Rooms 229 to 231	W4	Cracking	4	N	N	0	N	Y - 1 SF	2 Locations; Additional Chipping, Holes
731	2620	1	2	H212	Circulation (Hallway)	Hallway along Rooms 229 to 231	W2	Flaking	2	N	N	0	N	Y - 1 SF	2 Locations; Additional Efflorescence, Chipping
732	2620	1	2	H210	Circulation (Hallway)	Hallway from Elevator No. 1 to Room 207	Floor	Chipping	30	N	N	0	N	N	Chipping @ Perimeter
733	2620	1	2	H210	Circulation (Hallway)	Hallway from Elevator No. 1 to Room 207	W3	Cracking	9	N	N	0	N	N	4 Locations; Additional Chipping
734	2620	1	2	H210	Circulation (Hallway)	Hallway from Elevator No. 1 to Room 207	W1	Flaking	34	N	N	0	N	N	8 Locations; Additional Cracking, Holes, Gouges
735	2620	1	2	H210	Circulation (Hallway)	Hallway from Elevator No. 1 to Room 207	W4	Flaking	5	N	N	0	N	N	2 Locations; Additional Cracking
736	2620	1	2	H210	Circulation (Hallway)	Hallway from Elevator No. 1 to Room 207	Ceiling	Flaking	50	N	N	0	N	N	3 Locations; Additional Cracking
737	2620	1	2	S214	Stairs	Middle Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
738	2620	1	2	S214	Stairs	Middle Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
739	2620	1	2	S214	Stairs	Middle Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
740	2620	1	2	S214	Stairs	Middle Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
741	2620	1	2	S214	Stairs	Middle Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
742	2620	1	2	S214	Stairs	Middle Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
743	2620	1	2	200F	Storage	Principal's Office Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
744	2620	1	2	200F	Storage	Principal's Office Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
745	2620	1	2	200F	Storage	Principal's Office Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
746	2620	1	2	200F	Storage	Principal's Office Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
747	2620	1	2	200F	Storage	Principal's Office Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
748	2620	1	2	200F	Storage	Principal's Office Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
749	2620	1	2	201C	Other Physical Education Space	Room 201 Exercise Room	W2	Chipping	12	N	N	0	Y - 18 SF Weights	N	
750	2620	1	2	201C	Other Physical Education Space	Room 201 Exercise Room	W1	Flaking	11	N	N	0	Y - 110 SF Whiteboards, Exercise Equipment	N	4 Locations; Additional Cracking, Chipping
751	2620	1	2	201C	Other Physical Education Space	Room 201 Exercise Room	W3	Flaking	54	N	Y - On Window Sills & Radiators	46	Y - 30 SF Tables, Chairs	N	Additional Chipping
752	2620	1	2	201C	Other Physical Education Space	Room 201 Exercise Room	Ceiling	Flaking	60	N	N	0	N	N	Suspended Ceiling
753	2620	1	2	201C	Other Physical Education Space	Room 201 Exercise Room	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Cabinets, Exercise Equipment	N	
754	2620	1	2	207B	Administrative Office	Room 209A Gymnasium Office	W1	Flaking	1	N	N	0	N	Y - 1 SF	Additional Cracking
755	2620	1	2	207B	Administrative Office	Room 209A Gymnasium Office	W2	Flaking	3	N	N	0	Y - 34 SF File Cabinets, Desk, Posters	Y - 1 SF	Additional Cracking, Holes

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
779	2620	1	2	213	Storage	Room 219 Electrical across from Room 205	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
780	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
781	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
782	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
783	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
784	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
785	2620	1	2	213A	Storage	Room 220 IDF across from Room 205	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
786	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	Floor	Chipping	8	N	Y	8	N	N	
787	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	W1	Flaking	16	N	N	0	N	Y - 1 SF	2 Locations; Additional Holes
788	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	W2	Flaking	1	N	N	0	Y - 40 SF Shelves, Contents	N	Additional Holes
789	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	W3	Flaking	128	N	N	0	N	N	3 Locations; Additional Cracking, Chipping; Damage @ Pipes, Wall, Radiator
790	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	W4	Flaking	48	N	N	0	N	N	
791	2620	1	2	214A	Storage	Room 227 Custodial Closet across from Classroom 201	Ceiling	Holes	1	N	N	0	N	N	
792	2620	1	2	214B	Storage	Room 229 Storage Closet	Floor	Chipping	4	N	N	0	Y - 24 SF Boxes	N	
793	2620	1	2	214B	Storage	Room 229 Storage Closet	W2	Cracking	2	N	N	0	Y - 50 SF Shelves, Boxes, Contents	N	
794	2620	1	2	214B	Storage	Room 229 Storage Closet	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Shelves, Boxes, Contents	N	
795	2620	1	2	214B	Storage	Room 229 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 26 SF Shelves, Boxes, Contents	N	
796	2620	1	2	200D	Administrative Office	Room 230 Principal's Office	W3	Flaking	6	N	N	0	Y - 36 SF Desk	N	Flaking @ Radiator Grate
797	2620	1	2	200D	Administrative Office	Room 230 Principal's Office	W1	Holes	1	N	N	0	Y - 32 SF Couch, Posters	N	
798	2620	1	2	200A	Administrative Office	Room 231 Administration Office	W2	Flaking	1	N	N	0	N	N	Additional Gouges

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
799	2620	1	2	200A	Administrative Office	Room 231 Administration Office	Ceiling	Flaking	4	N	N	0	N	Y - 1 SF	Additional Holes
800	2620	1	2	200B	Administrative Office	Room 231A School Operations Office	Floor	Chipping	4	N	Y - Under Radiator	2	N	N	
801	2620	1	2	200B	Administrative Office	Room 231A School Operations Office	W4	Flaking	4	Y	Y - @ Window Sills	12	N	Y - 4 SF	
802	2620	1	2	200C	Administrative Office	Room 231B	W2	Cracking	3	N	N	0	Y - 84 SF IT Equipment	N	2 Locations; Additional Holes
803	2620	1	2	200C	Administrative Office	Room 231B	W1	Flaking	20	N	N	0	N	N	3 Locations; Additional Chipping
804	2620	1	2	200C	Administrative Office	Room 231B	W3	Flaking	276	N	N	0	Y - 16 SF IT Equipment	N	Additional Cracking, Chipping, Holes
805	2620	1	2	200C	Administrative Office	Room 231B	W4	Flaking	48	N	Y - On Window Sill	3	N	N	Additional Cracking, Chipping
806	2620	1	2	200C	Administrative Office	Room 231B	Ceiling	Flaking	28	N	N	0	N	N	Additional Chipping, Holes; Suspended Ceiling - Missing Ceiling Tiles
807	2620	1	2	200C	Administrative Office	Room 231B	Floor	Flaking	42	N	N	0	N	N	Additional Chipping; Damage @ Baseboard Perimeter
808	2620	1	2	S218	Stairs	Stairs from General Office over Stage Right to Stage Area	W2	Flaking	4	N	N	0	N	N	
809	2620	1	2	S218	Stairs	Stairs from General Office over Stage Right to Stage Area	W3	Flaking	4	N	N	0	N	N	
810	2620	1	2	S216	Stairs	Stairs from Hall to Girls' Locker Room Area	W1	Chipping	1	N	N	0	N	Y - 1 SF	
811	2620	1	2	S216	Stairs	Stairs from Hall to Girls' Locker Room Area	W2	Cracking	18	N	N	0	N	N	5 Locations
812	2620	1	2	S216	Stairs	Stairs from Hall to Girls' Locker Room Area	W4	Flaking	3	N	Y - Corner of Wall 3 & 4	1	N	N	3 Locations; Additional Cracking, Chipping
813	2620	1	2	S216	Stairs	Stairs from Hall to Girls' Locker Room Area	Ceiling	Flaking	96	N	N	0	N	N	3 Locations; Additional Cracking, Holes
814	2620	1	2	S216	Stairs	Stairs from Hall to Girls' Locker Room Area	W3	Gouges	1	N	N	0	N	N	
815	2620	1	2	S217	Stairs	Stairs from Hallway up to Gymnasium	W1	Cracking	4	N	N	0	N	N	2 Locations; Additional Chipping
816	2620	1	2	S217	Stairs	Stairs from Hallway up to Gymnasium	W4	Cracking	3	N	N	0	N	N	
817	2620	1	2	S217	Stairs	Stairs from Hallway up to Gymnasium	Ceiling	Cracking	4	N	N	0	N	N	Additional Chipping
818	2620	1	2	S217	Stairs	Stairs from Hallway up to Gymnasium	W2	Flaking	2	N	N	0	N	N	
819	2620	1	2	S217	Stairs	Stairs from Hallway up to Gymnasium	W3	Holes	1	N	N	0	N	N	2 Locations
820	2620	1	2	S215	Stairs	Stairs from Storage Area up to Old Boys' Locker Room on Third Floor	W3	Chipping	15	N	N	0	N	N	
821	2620	1	2	S215	Stairs	Stairs from Storage Area up to Old Boys' Locker Room on Third Floor	Ceiling	Flaking	90	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
822	2620	1	2	S22	Stairs	Stairwell near Elevator No. 1	Floor	Chipping	6	N	N	0	N	N	
823	2620	1	2	S22	Stairs	Stairwell near Elevator No. 1	Center Banister	Chipping	10	N	N	0	N	N	
824	2620	1	2	S27	Stairs	Stairwell near Gymnasium and Elevator No. 2	Floor	Chipping	12	N	N	0	N	N	
825	2620	1	2	S27	Stairs	Stairwell near Gymnasium and Elevator No. 2	Center Banister	Chipping	20	N	N	0	N	N	
826	2620	1	2	S27	Stairs	Stairwell near Gymnasium and Elevator No. 2	W1	Cracking	2	N	N	0	N	N	
827	2620	1	2	S27	Stairs	Stairwell near Gymnasium and Elevator No. 2	W2	Cracking	4	N	N	0	N	N	
828	2620	1	2	S27	Stairs	Stairwell near Gymnasium and Elevator No. 2	Ceiling	Cracking	1	N	N	0	N	N	
829	2620	1	2	S210	Stairs	Stairwell near Locker Room	W4	Chipping	4	N	N	0	N	N	Additional Gouges
830	2620	1	2	S210	Stairs	Stairwell near Locker Room	Floor	Chipping	20	N	N	0	N	N	
831	2620	1	2	S210	Stairs	Stairwell near Locker Room	Center Banister	Chipping	20	N	N	0	N	N	
832	2620	1	2	S210	Stairs	Stairwell near Locker Room	W1	Flaking	3	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Door & Above Door
833	2620	1	2	S210	Stairs	Stairwell near Locker Room	W3	Flaking	28	Y	Y	6	N	Y - 16 SF	2 Locations; Additional Efflorescence
834	2620	1	2	S210	Stairs	Stairwell near Locker Room	Ceiling	Flaking	1	N	N	0	N	N	Flaking @ Landing Between 1st & 2nd Floors
835	2620	1	2	S210	Stairs	Stairwell near Locker Room	W2	Spalling	1	Y	N	0	N	N	
836	2620	1	2	S21	Stairs	Stairwell next to Balcony and Room 231	W1	Chipping	1	N	N	0	N	N	
837	2620	1	2	S21	Stairs	Stairwell next to Balcony and Room 231	Center Banister	Chipping	8	N	N	0	N	N	
838	2620	1	2	S21	Stairs	Stairwell next to Balcony and Room 231	W3	Cracking	4	N	N	0	N	N	Additional Chipping
839	2620	1	2	S21	Stairs	Stairwell next to Balcony and Room 231	W4	Cracking	4	N	N	0	N	N	
840	2620	1	2	207H	Storage	Storage Area Behind Gym Office Leading to Stairs	Ceiling	Cracking	1	N	N	0	N	N	
841	2620	1	2	207H	Storage	Storage Area Behind Gym Office Leading to Stairs	W4	Cracking	1	N	Y - On Granite Apron	1	N	N	
842	2620	1	2	207H	Storage	Storage Area Behind Gym Office Leading to Stairs	W3	Flaking	1	N	N	0	N	N	
843	2620	1	2	207H	Storage	Storage Area Behind Gym Office Leading to Stairs	W1	Partially Inaccessible	0	N	Y - On Top of Lockers	8	Y - 105 SF Lockers	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
844	2620	1	2	207H	Storage	Storage Area Behind Gym Office Leading to Stairs	W2	Partially Inaccessible	0	N	N	0	Y - 16 SF Boxes	N	
845	2620	1	2	207I	Storage	Storage Closet in Gym Office	W3	Chipping	1	N	N	0	Y - 28 SF Shelves, Contents	N	
846	2620	1	2	207I	Storage	Storage Closet in Gym Office	W4	Chipping	42	N	N	0	N	N	Additional Chipping, Gouges
847	2620	1	2	207I	Storage	Storage Closet in Gym Office	W1	Cracking	1	N	N	0	Y - 7 SF Shelves, Contents	N	
848	2620	1	2	207I	Storage	Storage Closet in Gym Office	W2	Flaking	2	N	N	0	Y - 42 SF Shelves, Contents	N	2 Locations; Additional Cracking, Chipping
849	2620	1	2	207I	Storage	Storage Closet in Gym Office	Ceiling	Flaking	2	N	N	0	N	N	Additional Cracking
850	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	W2	Chipping	1	N	N	0	N	N	
851	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	Floor	Chipping	80	N	N	0	N	N	
852	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	W1	Cracking	8	N	N	0	N	N	2 Locations
853	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	W3	Flaking	87	N	Y - Under Radiators	75	Y - 75 SF Radiator Cages	N	8 Locations; Additional Chipping; Damage @ Wall & Radiators
854	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	W4	Flaking	81	Y	Y - Under Radiators	60	Y - 60 SF Radiator Cages	Y - 12 SF	10 Locations; Additional Efflorescence; Damage @ Walls & Radiators
855	2620	1	2	207	Gymnasium - Senior High	Upper Level Gymnasium	Ceiling	Flaking	32	Y	N	0	N	Y - 12 SF	Additional Efflorescence, Cracking
856	2620	1	1	111A	Auditorium	Auditorium	W2	Cracking	24	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
857	2620	1	1	111A	Auditorium	Auditorium	W1	Flaking	80	N	Y - @ Moulding	1	N	N	4 Locations; Additional Cracking, Chipping
858	2620	1	1	111A	Auditorium	Auditorium	W3	Flaking	210	Y	Y - @ Moulding & Window Sills	24	N	Y - 42 SF	Additional Efflorescence, Cracking; Damage on Entire Wall
859	2620	1	1	111A	Auditorium	Auditorium	W4	Flaking	52	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
860	2620	1	1	111A	Auditorium	Auditorium	Ceiling	Flaking	450	N	N	0	N	N	Ceilings > 20'
861	2620	1	1	111B	Stage	Auditorium Stage	W1	Chipping	180	N	N	0	N	N	
862	2620	1	1	111B	Stage	Auditorium Stage	W2	Flaking	200	N	N	0	N	N	Additional Cracking, Chipping
863	2620	1	1	111B	Stage	Auditorium Stage	W3	Flaking	48	N	N	0	N	N	2 Locations; Additional Cracking
864	2620	1	1	111B	Stage	Auditorium Stage	W4	Flaking	200	N	N	0	N	N	Additional Cracking, Chipping
865	2620	1	1	118	Student Restrooms - Male (4-12)	Boys' Restroom across from Room 104	W4	Flaking	2	N	N	0	N	N	Additional Cracking, Chipping
866	2620	1	1	102	Senior High	Classroom 102	W4	Chipping	2	N	N	0	Y - 28 SF Posters	N	
867	2620	1	1	102	Senior High	Classroom 102	W1	Cracking	2	N	N	0	Y - 26 SF Posters	N	
868	2620	1	1	102	Senior High	Classroom 102	W2	Cracking	4	N	N	0	N	N	3 Locations; Additional Cracking, Chipping, Holes
869	2620	1	1	102	Senior High	Classroom 102	W3	Flaking	32	Y	Y - @ Window Sill 3	4	N	Y - 32 SF @ Window Frames	3 Locations; Additional Efflorescence, Cracking

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
870	2620	1	1	102	Senior High	Classroom 102	Ceiling	Flaking	32	Y	N	0	N	Y - 32 SF @ Window Lintels	Additional Efflorescence
871	2620	1	1	102A	Storage	Classroom 102 Storage Area	W3	Cracking	42	N	N	0	Y - 42 SF Shelves, Contents	N	
872	2620	1	1	102A	Storage	Classroom 102 Storage Area	W4	Cracking	40	N	N	0	Y - 40 SF Shelves, Contents	N	
873	2620	1	1	102A	Storage	Classroom 102 Storage Area	W1	Flaking	32	N	Y - On Shelf	2	Y - 35 SF Shelves, Contents	N	Additional Cracking, Holes
874	2620	1	1	102A	Storage	Classroom 102 Storage Area	W2	Holes	2	N	N	0	N	N	
875	2620	1	1	101E	Administrative Office	Counselor's Office on Left Side	W1	Chipping	1	N	N	0	Y - 20 SF Bookcases	N	
876	2620	1	1	101E	Administrative Office	Counselor's Office on Left Side	W2	Chipping	3	N	N	0	Y - 36 SF File Cabinets, Fridge, Desk, Contents	N	
877	2620	1	1	101E	Administrative Office	Counselor's Office on Left Side	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Desks, Chairs	N	
878	2620	1	1	E-1	Elevators, Passenger	Elevator No. 1 near Main Office	W2	Chipping	5	N	N	0	N	N	
879	2620	1	1	E-1	Elevators, Passenger	Elevator No. 1 near Main Office	W3	Chipping	12	N	N	0	N	N	
880	2620	1	1	E-1	Elevators, Passenger	Elevator No. 1 near Main Office	W4	Chipping	6	N	N	0	N	N	
881	2620	1	1	E-2	Elevators, Passenger	Elevator No. 2 near Room 108	W2	Chipping	3	N	N	0	N	N	
882	2620	1	1	E-2	Elevators, Passenger	Elevator No. 2 near Room 108	W3	Chipping	5	N	N	0	N	N	
883	2620	1	1	E-2	Elevators, Passenger	Elevator No. 2 near Room 108	W4	Chipping	7	N	N	0	N	N	
884	2620	1	1	H113	Circulation (Hallway)	Hallway along Lower Level Gym and Room 111	W1	Chipping	6	N	N	0	N	N	
885	2620	1	1	H113	Circulation (Hallway)	Hallway along Lower Level Gym and Room 111	W3	Chipping	6	N	N	0	N	N	
886	2620	1	1	H113	Circulation (Hallway)	Hallway along Lower Level Gym and Room 111	W2	Cracking	48	N	N	0	N	N	2 Locations
887	2620	1	1	H113	Circulation (Hallway)	Hallway along Lower Level Gym and Room 111	Ceiling	Cracking	8	N	N	0	N	N	
888	2620	1	1	H113	Circulation (Hallway)	Hallway along Lower Level Gym and Room 111	W4	Flaking	10	N	Y - On Granite Skirt	2	N	N	Additional Cracking, Chipping
889	2620	1	1	H116	Circulation (Hallway)	Hallway along the SEAMAAC After School Program Rooms	Floor	Chipping	200	N	N	0	N	N	Damage @ Perimeter
890	2620	1	1	H116	Circulation (Hallway)	Hallway along the SEAMAAC After School Program Rooms	W1	Flaking	18	Y	Y - @ Window Sill 4	2	N	Y - 1 SF	3 Locations; Additional Efflorescence, Cracking,

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
937	2620	1	1	115B	Student Restrooms - Male/Female (Classroom)	Nurse's Office Exam Room Area Restroom	Ceiling	Flaking	4	N	N	0	N	N	
938	2620	1	1	115A	Health Service Room	Nurse's Office Exam Rooms - Divided	W3	Chipping	6	N	N	0	N	N	Additional Gouges
939	2620	1	1	115A	Health Service Room	Nurse's Office Exam Rooms - Divided	W1	Cracking	1	N	N	0	N	N	
940	2620	1	1	115A	Health Service Room	Nurse's Office Exam Rooms - Divided	W2	Cracking	2	N	N	0	Y - 8 SF Posters, Fridge	N	Additional Chipping
941	2620	1	1	115A	Health Service Room	Nurse's Office Exam Rooms - Divided	W4	Flaking	12	N	N	0	N	N	Additional Chipping; Damage @ Radiator
942	2620	1	1	115C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W1	Flaking	1	N	N	0	N	N	Additional Holes
943	2620	1	1	115C	Student Restrooms - Male/Female (Classroom)	Nurse's Office Restroom	W2	Holes	1	N	N	0	N	N	
944	2620	1	1	101B	Administrative Office	Right Side Counselor's Office in Waiting Area	W3	Flaking	3	N	Y - @ Window Sill	1	N	N	
945	2620	1	1	101B	Administrative Office	Right Side Counselor's Office in Waiting Area	Ceiling	Holes	1	N	N	0	N	N	
946	2620	1	1	101	Administrative Office	Room 101 Counselor's Suite Entrance Area	Ceiling	Cracking	2	N	N	0	N	N	
947	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
948	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
949	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
950	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
951	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*No Access; Personal Lock
952	2620	1	1	102B	Storage	Room 102 Storage Closet (near edge of building)	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
953	2620	1	1	103	Senior High	Room 103 Graphic Arts	W2	Cracking	4	N	N	0	Y - 16 SF Contents	0	
954	2620	1	1	103	Senior High	Room 103 Graphic Arts	W1	Flaking	8	N	N	0	N	0	2 Locations; Additional Cracking
955	2620	1	1	103	Senior High	Room 103 Graphic Arts	W3	Flaking	10	N	Y - @ Window Sills 7 & 8	2	N	0	Additional Cracking
956	2620	1	1	103	Senior High	Room 103 Graphic Arts	W4	Flaking	4	N	N	0	N	0	Additional Chipping
957	2620	1	1	103	Senior High	Room 103 Graphic Arts	Ceiling	Flaking	6	Y	N	0	N	Y - 6 SF	Additional Efflorescence; Damage @ Window Lintels 7 & 8

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
958	2620	1	1	103A	Storage	Room 103 Graphic Arts Storage Closet	W2	Cracking	6	N	N	0	Y - 48 SF Shelves, Contents	0	
959	2620	1	1	103A	Storage	Room 103 Graphic Arts Storage Closet	W3	Cracking	36	N	N	0	Y - 42 SF Shelves, Contents	0	
960	2620	1	1	103A	Storage	Room 103 Graphic Arts Storage Closet	W4	Cracking	60	N	N	0	Y - 42 SF Contents	0	
961	2620	1	1	103B	Storage	Room 103 Graphic Arts Storage Closet (near edge of building)	W2	Cracking	6	N	N	0	Y - 48 SF Shelves, Contents	0	
962	2620	1	1	103B	Storage	Room 103 Graphic Arts Storage Closet (near edge of building)	W3	Cracking	36	N	N	0	Y - 42 SF Shelves, Contents	0	
963	2620	1	1	103B	Storage	Room 103 Graphic Arts Storage Closet (near edge of building)	W4	Cracking	60	N	N	0	Y - 60 SF Shelves, Contents	0	
964	2620	1	1	104	Senior High	Room 104 Fine Arts	W2	Chipping	1	N	N	0	Y - 12 SF Posters	N	
965	2620	1	1	104	Senior High	Room 104 Fine Arts	W4	Flaking	1	N	N	0	Y - 14 SF Posters	N	
966	2620	1	1	104	Senior High	Room 104 Fine Arts	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Posters	N	
967	2620	1	1	104A	Storage	Room 104 Fine Arts - Closet	W1	Flaking	6	N	N	0	N	N	
968	2620	1	1	104A	Storage	Room 104 Fine Arts - Closet	W2	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Contents	N	
969	2620	1	1	104A	Storage	Room 104 Fine Arts - Closet	W3	Partially Inaccessible	0	N	N	0	Y - 42 SF Shelves, Contents	N	
970	2620	1	1	104A	Storage	Room 104 Fine Arts - Closet	W4	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Contents	N	
971	2620	1	1	104B	Storage	Room 104 Fine Arts - Front Closet	W2	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves	N	
972	2620	1	1	104B	Storage	Room 104 Fine Arts - Front Closet	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves	N	
973	2620	1	1	104B	Storage	Room 104 Fine Arts - Front Closet	W4	Partially Inaccessible	0	N	N	0	Y - 7 SF Shelves	N	
974	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access; Private Lock
975	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
976	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
977	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
978	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
979	2620	1	1	105A	Administrative Office	Room 104 Fine Arts Office Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
980	2620	1	1	105C	Storage	Room 108 Storage Room across from Elevator No. 2	W1	Cracking	120	N	N	0	Y - 140 SF Shelves, Boxes, Contents	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
981	2620	1	1	105C	Storage	Room 108 Storage Room across from Elevator No. 2	W3	Cracking	16	N	N	0	Y - 180 Shelves, Boxes, Contents	N	
982	2620	1	1	105C	Storage	Room 108 Storage Room across from Elevator No. 2	W4	Cracking	180	N	N	0	N	N	
983	2620	1	1	105C	Storage	Room 108 Storage Room across from Elevator No. 2	Ceiling	Cracking	4	N	N	0	N	N	
984	2620	1	1	105C	Storage	Room 108 Storage Room across from Elevator No. 2	W2	Partially Inaccessible	0	N	N	0	Y - 90 SF Shelves, Boxes, Contents	N	
985	2620	1	1	113	Senior High	Room 118 Conference Room	W4	Chipping	1	N	N	0	Y - 29 SF Posters, Couch	N	
986	2620	1	1	113	Senior High	Room 118 Conference Room	W2	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping; Flaking @ Seam Caulk
987	2620	1	1	113	Senior High	Room 118 Conference Room	W3	Flaking	19	N	N	0	N	N	4 Locations; Additional Cracking, Chipping
988	2620	1	1	113	Senior High	Room 118 Conference Room	W1	Holes	2	N	N	0	N	N	
989	2620	1	1	111	Administrative Office	Room 123 Nurse's Office	W2	Chipping	5	N	N	0	N	N	
990	2620	1	1	111	Administrative Office	Room 123 Nurse's Office	W1	Cracking	1	N	N	0	N	N	
991	2620	1	1	111	Administrative Office	Room 123 Nurse's Office	W3	Cracking	1	N	N	0	N	N	
992	2620	1	1	111	Administrative Office	Room 123 Nurse's Office	Ceiling	Holes	4	N	N	0	N	N	
993	2620	1	1	111	Administrative Office	Room 123 Nurse's Office	W4	Partially Inaccessible	0	N	N	0	Y - 18 SF Desk, Contents	N	
994	2620	1	1	113A	Restrooms, Staff - Female	Room 126 Women's Restroom	W1	Flaking	68	Y	Y - @ Granite Apron Near Entry & Along Stalls	15	N	Y - 48 SF	Additional Efflorescence, Chipping
995	2620	1	1	113A	Restrooms, Staff - Female	Room 126 Women's Restroom	W2	Flaking	3	N	N	0	N	N	Additional Cracking, Holes
996	2620	1	1	113A	Restrooms, Staff - Female	Room 126 Women's Restroom	W3	Flaking	8	N	N	0	N	N	Additional Chipping; Damage @ Pipes & on Granite Apron
997	2620	1	1	113A	Restrooms, Staff - Female	Room 126 Women's Restroom	W4	Flaking	36	N	N	0	N	N	
998	2620	1	1	112A	Administrative Office	Room 129 Main Office	W3	Cracking	1	N	N	0	N	N	
999	2620	1	1	110B	Other Ancillary Support	SEAMAAC Program Room 132	W1	Partially Inaccessible	0	N	N	0	Y - 64 SF Tables, Posters	N	
1000	2620	1	1	110C	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 132 Restroom	W3	Chipping	1	N	N	0	N	N	
1001	2620	1	1	110C	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 132 Restroom	W2	Efflorescence	1	Y	N	0	N	N	Brick Wall
1002	2620	1	1	110	Other Ancillary Support	SEAMAAC Program Room 133	W1	Chipping	2	N	N	0	N	N	
1003	2620	1	1	110	Other Ancillary Support	SEAMAAC Program Room 133	W2	Chipping	30	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1004	2620	1	1	110A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 133 Restroom	Floor	Chipping	4	N	N	0	N	N	
1005	2620	1	1	110A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 133 Restroom	W1	Cracking	2	N	N	0	N	N	
1006	2620	1	1	109	Other Ancillary Support	SEAMAAC Program Room 134	W1	Chipping	160	N	N	0	N	N	
1007	2620	1	1	109	Other Ancillary Support	SEAMAAC Program Room 134	W3	Chipping	24	N	N	0	N	N	
1008	2620	1	1	109	Other Ancillary Support	SEAMAAC Program Room 134	Floor	Chipping	132	N	N	0	N	N	
1009	2620	1	1	109A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 134 Restroom	W1	Flaking	4	N	N	0	N	N	3 Locations
1010	2620	1	1	109A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 134 Restroom	W3	Flaking	14	N	N	0	N	N	
1011	2620	1	1	109A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 134 Restroom	W4	Flaking	2	N	N	0	N	N	
1012	2620	1	1	108	Other Ancillary Support	SEAMAAC Program Room 135	W1	Chipping	4	N	N	0	N	Y - 2 SF	2 Locations; Additional Cracking, Holes
1013	2620	1	1	108	Other Ancillary Support	SEAMAAC Program Room 135	Floor	Chipping	4	N	N	0	N	N	
1014	2620	1	1	108	Other Ancillary Support	SEAMAAC Program Room 135	W2	Flaking	7	N	N	0	N	N	Additional Chipping; Damage @ Radiators
1015	2620	1	1	108	Other Ancillary Support	SEAMAAC Program Room 135	W3	Flaking	24	N	N	0	Y - 24 SF Radiator Covers	N	
1016	2620	1	1	108A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 135 Restroom	W1	Flaking	2	N	N	0	N	N	2 Locations
1017	2620	1	1	108A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 135 Restroom	W2	Flaking	4	N	N	0	N	N	4 SF Sheetrock Needed
1018	2620	1	1	108A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 135 Restroom	W3	Flaking	4	N	N	0	N	N	4 SF Sheetrock Needed
1019	2620	1	1	107	Other Ancillary Support	SEAMAAC Program Room 136	W4	Chipping	2	N	N	0	N	N	
1020	2620	1	1	107A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 136 Restroom	W3	Chipping	3	N	N	0	N	N	
1021	2620	1	1	107A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 136 Restroom	W4	Cracking	12	N	N	0	N	N	Additional Chipping

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1022	2620	1	1	107A	Student Restrooms - Male/Female (Classroom)	SEAMAAC Program Room 136 Restroom	Ceiling	Holes	1	N	N	0	N	N	
1023	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
1024	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
1025	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
1026	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
1027	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
1028	2620	1	1	107B	Storage	SEAMAAC Program Storage Room in Hallway next to Room 136	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Access
1029	2620	1	1	112	Storage	SEAMAAC Program Storage Room across from Room 134	W3	Chipping	20	N	N	0	N	N	
1030	2620	1	1	112	Storage	SEAMAAC Program Storage Room across from Room 134	W2	Flaking	8	N	Y - @ Window Sills	8	N	N	Additional Chipping; Damage @ Radiators
1031	2620	1	1	112	Storage	SEAMAAC Program Storage Room across from Room 134	Ceiling	Flaking	8	N	N	0	N	N	2 Locations; Additional Cracking
1032	2620	1	1	111F	Storage	Stage Left Storage Area	W2	Chipping	2	N	N	0	N	N	
1033	2620	1	1	111F	Storage	Stage Left Storage Area	W4	Chipping	7	N	N	0	N	N	2 Locations; Additional Gouges
1034	2620	1	1	111F	Storage	Stage Left Storage Area	W1	Flaking	31	Y	Y - @ Window Sill	2	N	Y - 3 SF	Additional Efflorescence
1035	2620	1	1	111F	Storage	Stage Left Storage Area	W3	Flaking	16	N	N	0	N	N	2 Locations; Additional Cracking, Chipping
1036	2620	1	1	111C	Circulation (Hallway)	Stage Right Entrance from Stairs	W1	Flaking	60	N	N	0	N	N	Additional Cracking, Chipping
1037	2620	1	1	111C	Circulation (Hallway)	Stage Right Entrance from Stairs	W2	Flaking	36	Y	N	0	N	N	Additional Efflorescence
1038	2620	1	1	111C	Circulation (Hallway)	Stage Right Entrance from Stairs	W3	Flaking	110	Y	N	0	N	N	Additional Efflorescence
1039	2620	1	1	111C	Circulation (Hallway)	Stage Right Entrance from Stairs	W4	Flaking	48	N	N	0	N	N	Additional Cracking
1040	2620	1	1	111C	Circulation (Hallway)	Stage Right Entrance from Stairs	Ceiling	Flaking	96	N	N	0	N	N	

Palumbo -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1041	2620	1	1	111D	Storage	Stage Right Stairs and Storage	W2	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
1042	2620	1	1	111D	Storage	Stage Right Stairs and Storage	W3	Flaking	4	N	N	0	N	N	
1043	2620	1	1	111D	Storage	Stage Right Stairs and Storage	W4	Flaking	3	N	N	0	N	N	
1044	2620	1	1	111D	Storage	Stage Right Stairs and Storage	W1	Partially Inaccessible	0	N	N	0	Y - 96 SF Tables, Contents	N	
1045	2620	1	1	S110	Stairs	Stairs from Lower Level Gym to Basement	W3	Flaking	60	Y	Y - @ Window Sill	12	N	Y - 12 SF	Additional Efflorescence
1046	2620	1	1	S110	Stairs	Stairs from Lower Level Gym to Basement	Ceiling	Flaking	260	N	N	0	N	N	
1047	2620	1	1	S110	Stairs	Stairs from Lower Level Gym to Basement	Floor	Flaking	140	N	Y - @ Perimeter & on Contents	60	Y - 100 SF Contents	N	
1048	2620	1	1	S121	Stairs	Stairwell near Auditorium Rear	W3	Chipping	2	N	N	0	N	N	Chipping @ Door
1049	2620	1	1	S121	Stairs	Stairwell near Auditorium Rear	W4	Chipping	4	N	N	0	N	N	
1050	2620	1	1	S121	Stairs	Stairwell near Auditorium Rear	Floor	Chipping	26	N	N	0	N	N	Chipping @ Perimeter
1051	2620	1	1	S121	Stairs	Stairwell near Auditorium Rear	Center Banister	Chipping	14	N	N	0	N	N	
1052	2620	1	1	S127	Stairs	Stairwell near Lower Level Gym and Room 108	W1	Chipping	2	N	N	0	N	N	
1053	2620	1	1	S127	Stairs	Stairwell near Lower Level Gym and Room 108	Floor	Chipping	38	N	N	0	N	N	
1054	2620	1	1	S127	Stairs	Stairwell near Lower Level Gym and Room 108	W4	Flaking	4	N	N	0	N	N	
1055	2620	1	1	S127	Stairs	Stairwell near Lower Level Gym and Room 108	Ceiling	Flaking	2	N	N	0	N	N	Flaking @ Fiberglass Pipe
1056	2620	1	1	S128	Stairs	Stairwell near Lower Level Gym and Room 136	W2	Flaking	20	N	N	0	N	N	
1057	2620	1	1	S128	Stairs	Stairwell near Lower Level Gym and Room 136	W4	Flaking	72	Y	Y - On Wall, Window Will & Radiator	60	N	Y - 12 SF	2 Locations; Damage on Wall & Radiator
1058	2620	1	1	S128	Stairs	Stairwell near Lower Level Gym and Room 136	Ceiling	Flaking	200	N	N	0	N	N	
1059	2620	1	1	S128	Stairs	Stairwell near Lower Level Gym and Room 136	Floor	Flaking	150	N	Y - Entire Floor & Contents	200	Y - 200 SF Contents		
1060	2620	1	1	S122	Stairs	Stairwell near Stage and Main Entrance to School	W1	Chipping	12	N	N	0	N	N	Chipping @ Door
1061	2620	1	1	S122	Stairs	Stairwell near Stage and Main Entrance to School	W2	Chipping	1	N	N	0	N	N	
1062	2620	1	1	S122	Stairs	Stairwell near Stage and Main Entrance to School	W4	Chipping	3	N	N	0	N	N	

