

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6110	1	3	300D	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 303	Ceiling	Cracking	25	No	No	N/A	N/A	No	
2	6110	1	3	300D	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 303	Floor	Chipping	25	No	No	N/A	N/A	No	
3	6110	1	3	300D	Student Restrooms - Male (4-12)	Boy's Restroom across from Classroom 303	W4	Cracking	3	No	No	N/A	N/A	No	
4	6110	1	3	302	Primary	Classroom 302	Ceiling	Significant Moisture Damage above missing ceiling tile	4	Yes	No	N/A	N/A	Yes	
5	6110	1	3	302	Primary	Classroom 302	W1	Limited Inspection		No	No		Posters, Shelves	No	Limited Inspection due to stored materials
6	6110	1	3	302	Primary	Classroom 302	W2	Chipping on wall and radiator, Hole, Efflorescence above missing ceiling tile, Significant Moisture Damage behind radiator	27	Yes	No	N/A	Cabinet, Shelves	Yes	
7	6110	1	3	302	Primary	Classroom 302	W3	Chipping on wall and radiator, Flaking	26	No	No	N/A	Posters, Shelves	No	
8	6110	1	3	302	Primary	Classroom 302	W4	Chipping	14	No	No	N/A	Posters	No	
9	6110	1	3	303	Primary	Classroom 303	W1	Chipping, Holes, Flaking	11	No	No	N/A	Desks, Shelves	No	
10	6110	1	3	303	Primary	Classroom 303	W3	Cracking, Flaking behind radiator	25	No	No	N/A	N/A	No	
11	6110	1	3	303	Primary	Classroom 303	W4	Cracking, Chipping	14	No	No	N/A	N/A	No	
12	6110	1	3	304	Primary	Classroom 304	W1	Chipping, Holes, Flaking	17	No	No	N/A	N/A	Yes	
13	6110	1	3	304	Primary	Classroom 304	W3	Chipping on wall and radiator, Holes, Flaking behind radiator	21	No	No	N/A	N/A	Yes	
14	6110	1	3	305	Primary	Classroom 305	W1	Cracking, Chipping, Flaking	25	No	No	N/A	N/A	No	
15	6110	1	3	305	Primary	Classroom 305	W2	Cracking, Chipping, Holes	15	No	No	N/A	N/A	Yes	
16	6110	1	3	305	Primary	Classroom 305	W3	Cracking, Chipping, Hole, Flaking on wall and behind radiator	21	No	No	N/A	N/A	Yes	
17	6110	1	3	306	Primary	Classroom 306	Ceiling	Significant Moisture Damage above missing ceiling tile	4	Yes	No	N/A	N/A	Yes	
18	6110	1	3	306	Primary	Classroom 306	Floor	Debris	N/A	No	Debris in corner of walls 1&4	5	N/A	No	
19	6110	1	3	306	Primary	Classroom 306	W1	Cracking, Chipping on door	15	No	No	N/A	Tables with computers	No	
20	6110	1	3	306	Primary	Classroom 306	W2	Chipping on radiator and metal pipe	15	No	No	N/A	Tables with computers	No	
21	6110	1	3	306	Primary	Classroom 306	W3	Chipping on metal pipe, Significant Moisture Damage above missing ceiling tile	13	Yes	No	N/A	Tables with computers, Cabinet	Yes	
22	6110	1	3	306	Primary	Classroom 306	W4	Cracking, Hole	36	No	No	N/A	Desk, File Cabinet	Yes	
23	6110	1	3	307	Primary	Classroom 307	W1	Chipping, Unfinished plaster behind missing board, Flaking	53	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
24	6110	1	3	307	Primary	Classroom 307	W2	Chipping, Holes	7	No	No	N/A	N/A	Yes	
25	6110	1	3	307	Primary	Classroom 307	W3	Chipping on wall, radiators, and windowsills, Flaking behind radiators	61	No	No	N/A	N/A	No	
26	6110	1	3	308	Primary	Classroom 308	Ceiling	Flaking above missing ceiling tile by pipe, Significant Moisture Damage above missing ceiling tile by leak outside closet, Significant Moisture Damage inside closet	13	Yes	No	N/A	Shelves, Stored Materials inside closet	Yes	Active leak outside closet. Bucket is catching water. Leak is either coming from roof or a pipe in the attic.
27	6110	1	3	308	Primary	Classroom 308	W1	Hole inside top air shaft, Flaking, Significant Moisture Damage inside closet	32	Yes	No	N/A	Shelves, Stored Materials inside closet	Yes	
28	6110	1	3	308	Primary	Classroom 308	W2	Flaking	9	No	No	N/A	N/A	No	
29	6110	1	3	308	Primary	Classroom 308	W3	Chipping on radiator, Flaking on metal pipes, Efflorescence behind radiator,	25	Yes	No	N/A	N/A	Yes	
30	6110	1	3	308	Primary	Classroom 308	W4	Cracking, Flaking	10	No	No	N/A	N/A	No	
31	6110	1	3	309	Primary	Classroom 309	W1	Cracking, Chipping, Staples, Efflorescence in top air shaft	22	Yes	No	N/A	Posters	Yes	
32	6110	1	3	309	Primary	Classroom 309	W2	Cracking, Flaking	22	No	No	N/A	Posters, Shelf, Cabinet	No	
33	6110	1	3	309	Primary	Classroom 309	W3	Cracking, Chipping on wall and metal pipe, Hole, Flaking, Significant Moisture Damage behind radiator	33	Yes	No	N/A	Posters	Yes	
34	6110	1	3	309	Primary	Classroom 309	W4	Chipping	2	No	No	N/A	Posters	No	
35	6110	1	3	309A	Storage	Classroom 309 Closet	Ceiling	Cracking, Efflorescence	16	Yes	No	N/A	N/A	Yes	
36	6110	1	3	309A	Storage	Classroom 309 Closet	Floor	Debris	N/A	No	Debris	10	N/A	No	
37	6110	1	3	309A	Storage	Classroom 309 Closet	W1	Flaking, Efflorescence, Significant Moisture Damage	34	Yes	Debris on shelves	16	Built in Shelves	Yes	
38	6110	1	3	309A	Storage	Classroom 309 Closet	W2	Efflorescence, Significant Moisture Damage	11	Yes	Debris on shelves	16	Built in Shelves	Yes	
39	6110	1	3	309A	Storage	Classroom 309 Closet	W3	Holes, Flaking on wall and metal pipe, Significant Moisture Damage	35	Yes	No	N/A	N/A	Yes	
40	6110	1	3	309A	Storage	Classroom 309 Closet	W4	Cracking, Hole	6	No	No	N/A	Built in Shelves, Stored Materials	Yes	
41	6110	1	3	310	Primary	Classroom 310	W1	Cracking, some in bottom air shaft, Chipping on wall and door, Holes on wall and in air shaft, Flaking	46	No	No	N/A	Posters	Yes	
42	6110	1	3	310	Primary	Classroom 310	W2	Cracking, Chipping, Holes, paint has been stabilized, Flaking	43	No	No	N/A	Posters	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
43	6110	1	3	310	Primary	Classroom 310	W3	Chipping on wall and radiator, Flaking on wall and behind radiators, Significant Moisture Damage behind radiator	34	Yes	No	N/A	Posters	Yes	
44	6110	1	3	310	Primary	Classroom 310	W4	Cracking, Flaking	12	No	No	N/A	Posters	No	
45	6110	1	3	310A	Storage	Classroom 310 Closet	Ceiling	Spalling, Efflorescence	5	Yes	No	N/A	Stored Materials	Yes	Damage has been repaired but is returning
46	6110	1	3	310A	Storage	Classroom 310 Closet	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
47	6110	1	3	310A	Storage	Classroom 310 Closet	W1	Cracking, Hole, Flaking	12	No	No	N/A	Stored Materials	Yes	
48	6110	1	3	310A	Storage	Classroom 310 Closet	W2	Spalling	2	Yes	No	N/A	Built in Shelves, Stored Materials	Yes	
49	6110	1	3	310A	Storage	Classroom 310 Closet	W3	Flaking on metal pipe	12	No	No	N/A	Built in Shelves, Stored Materials	No	
50	6110	1	3	310A	Storage	Classroom 310 Closet	W4	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
51	6110	1	3	311	Primary	Classroom 311	W1	Cracking, Holes, paint has been stabilized on 2, Flaking	24	No	No	N/A	Posters	Yes	
52	6110	1	3	311	Primary	Classroom 311	W2	Cracking	6	No	No	N/A	Posters	No	
53	6110	1	3	311	Primary	Classroom 311	W3	Chipping on metal pipe and behind radiator, Hole, Significant Moisture Damage behind radiator	17	Yes	Paint chips on windowsill	1	N/A	Yes	
54	6110	1	3	311	Primary	Classroom 311	W4	Cracking, Flaking	4	No	No	N/A	N/A	No	
55	6110	1	3	311A	Storage	Classroom 311 and 312 Closet	Ceiling	Cracking, Efflorescence above missing ceiling tile	17	Yes	No	N/A	N/A	Yes	
56	6110	1	3	311A	Storage	Classroom 311 and 312 Closet	W1	Cracking, Chipping on door and doorframe	22	No	No	N/A	N/A	Yes	
57	6110	1	3	311A	Storage	Classroom 311 and 312 Closet	W2	Cracking	23	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
58	6110	1	3	311A	Storage	Classroom 311 and 312 Closet	W3	Chipping on metal pipe, Flaking behind radiator	13	No	No	N/A	Cabinets	No	
59	6110	1	3	311A	Storage	Classroom 311 and 312 Closet	W4	Cracking, Flaking	32	No	No	N/A	Cabinets	No	
60	6110	1	3	312	Primary	Classroom 312	W1	Chipping, Holes, paint has been stabilized, Flaking on wall, metal pipe, and conduit lines	12	No	No	N/A	Posters, Stored Materials	Yes	
61	6110	1	3	312	Primary	Classroom 312	W2	Cracking	2	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
62	6110	1	3	312	Primary	Classroom 312	W3	Chipping on metal pipe and radiators, Significant Moisture Damage behind radiator	26	Yes	No	N/A	Shelves, Stored Materials	Yes	
63	6110	1	3	312	Primary	Classroom 312	W4	Gouge	1	No	No	N/A	N/A	Yes	
64	6110	1	3	313	Primary	Classroom 313	Ceiling	Significant Moisture Damage above missing ceiling tile	8	Yes	No	N/A	N/A	Yes	
65	6110	1	3	313	Primary	Classroom 313	W1	Gouge, Holes	3	No	Debris on cove	1	Shelves, Art	Yes	
66	6110	1	3	313	Primary	Classroom 313	W2	Cracking	5	No	No	N/A	Art	No	
67	6110	1	3	313	Primary	Classroom 313	W3	Gouge, Flaking on wall and behind radiator, Significant Moisture Damage above missing ceiling tile	17	Yes	No	N/A	Shelves, Stored Materials	Yes	
68	6110	1	3	313	Primary	Classroom 313	W4	Chipping on radiator, Flaking on metal pipe and behind radiator	10	No	No	N/A	Shelves, Stored Materials	No	
69	6110	1	3	314	Primary	Classroom 314	W1	Cracking, Chipping, Flaking	10	No	No	N/A	Posters	No	
70	6110	1	3	314	Primary	Classroom 314	W3	Chipping on metal pipe and radiator cover, Hole behind radiator, Flaking behind radiator, Significant Moisture Damage behind radiator	21	Yes	No	N/A	Furniture, Posters	Yes	
71	6110	1	3	314	Primary	Classroom 314	W4	Cracking	8	No	No	N/A	Cabinets, Posters	No	
72	6110	1	3	315	Primary	Classroom 315	W1	Cracking, Chipping, Hole, paint has been stabilized	29	No	No	N/A	N/A	Yes	
73	6110	1	3	315	Primary	Classroom 315	W2	Chipping	6	No	No	N/A	N/A	No	
74	6110	1	3	315	Primary	Classroom 315	W3	Flaking behind radiators	20	No	No	N/A	N/A	No	
75	6110	1	3	316	Primary	Classroom 316	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
76	6110	1	3	316	Primary	Classroom 316	W1	Chipping, Cracking	85	No	No	N/A	N/A	No	
77	6110	1	3	316	Primary	Classroom 316	W2	Chipping, Holes, Flaking	65	No	No	N/A	N/A	Yes	
78	6110	1	3	316	Primary	Classroom 316	W3	Chipping, Flaking on wall, metal pipe, and behind radiator, Significant Moisture Damage behind radiator	39	Yes	Debris below radiator	5	N/A	Yes	
79	6110	1	3	316	Primary	Classroom 316	W4	Chipping	5	No	No	N/A	N/A	No	
80	6110	1	3	317	Primary	Classroom 317	Floor	Debris	N/A	No	Paint chips scattered along wall 4	5	N/A	No	
81	6110	1	3	317	Primary	Classroom 317	W1	Flaking, Holes	7	No	No	N/A	N/A	Yes	
82	6110	1	3	317	Primary	Classroom 317	W2	Cracking, Chipping, Flaking	88	No	No	N/A	N/A	No	
83	6110	1	3	317	Primary	Classroom 317	W3	Flaking behind radiator	10	No	No	N/A	N/A	No	
84	6110	1	3	317	Primary	Classroom 317	W4	Chipping, Flaking behind radiator	11	No	No	N/A	N/A	No	
85	6110	1	3	318	Primary	Classroom 318	Ceiling	Cracking, Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
86	6110	1	3	318	Primary	Classroom 318	W1	Chipping, Hole	42	No	No	N/A	N/A	Yes	
87	6110	1	3	318	Primary	Classroom 318	W2	Chipping	2	No	No	N/A	N/A	No	
88	6110	1	3	318/	Primary	Classroom 318	W3	Chipping on wall and metal pipes, Flaking behind radiators	31	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
89	6110	1	3	318	Primary	Classroom 318	W4	Chipping, Flaking	14	No	No	N/A	N/A	No	
90	6110	1	3	319	Primary	Classroom 319	W1	Cracking, Chipping, Flaking	19	No	No	N/A	Posters	No	
91	6110	1	3	319	Primary	Classroom 319	W2	Chipping	2	No	No	N/A	Cabinet, Shelves	No	
92	6110	1	3	319	Primary	Classroom 319	W3	Flaking behind radiators	20	No	No	N/A	N/A	No	
93	6110	1	3	319	Primary	Classroom 319	W4	Chipping	17	No	No	N/A	N/A	No	
94	6110	1	3	320	Primary	Classroom 320	Ceiling	Significant Moisture Damage from leak above missing ceiling tile	4	Yes	No	N/A	N/A	Yes	Teacher reports that this is an active leak in the mornings
95	6110	1	3	320	Primary	Classroom 320	W1	Cracking on wall and in air shaft, Chipping, Flaking	11	No	No	N/A	Posters	No	
96	6110	1	3	320	Primary	Classroom 320	W2	Chipping	13	No	No	N/A	Posters	No	
97	6110	1	3	320	Primary	Classroom 320	W3	Chipping, Flaking behind radiators, Efflorescence	37	Yes	No	N/A	N/A	Yes	
98	6110	1	3	321	Primary	Classroom 321	W3	Chipping on wall and radiator, Flaking behind radiator	25	No	No	N/A	Shelves	No	
99	6110	1	3	321	Primary	Classroom 321	W4	Cracking, Chipping, Hole	5	No	No	N/A	Posters	Yes	
100	6110	1	3	321	Primary	Classroom 321	W1	Chipping on door, Holes, Flaking, Efflorescence in air shaft	19	Yes	No	N/A	Posters	Yes	
101	6110	1	3	321	Primary	Classroom 321	W2	Limited Inspection		No	No		Posters	No	Limited Inspection due to stored materials
102	6110	1	3	322	Primary	Classroom 322	W1	Cracking, Chipping, Holes on wall and in air shaft, Efflorescence	35	Yes	No	N/A	Posters	Yes	
103	6110	1	3	322	Primary	Classroom 322	W3	Holes	2	No	Debris near wall 3	1	Posters, Furniture	Yes	
104	6110	1	3	323	Primary	Classroom 324A	Ceiling	Cracking above missing ceiling tile	4	No	No	N/A	N/A	No	
105	6110	1	3	323	Primary	Classroom 324A	W1	Cracking, Chipping on phone box, Flaking in air shaft	11	No	No	N/A	N/A	No	Repair to brick wall is needed
106	6110	1	3	323	Primary	Classroom 324A	W2	Cracking, Chipping	29	No	No	N/A	Furniture	No	Repair to brick wall is needed
107	6110	1	3	323	Primary	Classroom 324A	W3	Chipping on radiator, Flaking on wall and behind radiator	23	No	No	N/A	N/A	No	
108	6110	1	3	323	Primary	Classroom 324A	W4	Hole	1	No	No	N/A	Furniture	No	Repair to concrete block needed
109	6110	1	3	324B	Primary	Classroom 324B	Ceiling	Cracking, Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
110	6110	1	3	324B	Primary	Classroom 324B	Floor	Chipping along walls 1&3	25	No	No	N/A	N/A	No	
111	6110	1	3	324B	Primary	Classroom 324B	W1	Flaking on wall and in air shaft	52	No	No	N/A	N/A	No	
112	6110	1	3	324B	Primary	Classroom 324B	W2	Cracking	8	No	No	N/A	Tables, Stored Materials	No	Repair to concrete block needed
113	6110	1	3	324B	Primary	Classroom 324B	W3	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
114	6110	1	3	324B	Primary	Classroom 324B	W4	Chipping	16	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
115	6110	1	3	324A	Primary	Classroom 324C	Ceiling	Flaking above missing ceiling tile, Significant Moisture Damage above windows	14	Yes	No	N/A	N/A	Yes	
116	6110	1	3	324A	Primary	Classroom 324C	Floor	Chipping along walls 1,3,4	28	No	No	N/A	N/A	No	
117	6110	1	3	324A	Primary	Classroom 324C	W1	Cracking, Chipping on door	9	No	No	N/A	N/A	No	Repair to brick wall is needed
118	6110	1	3	324A	Primary	Classroom 324C	W2	Cracking, Chipping	20	No	No	N/A	N/A	No	Repair to drywall is needed
119	6110	1	3	324A	Primary	Classroom 324C	W3	Flaking, Efflorescence	13	Yes	No	N/A	N/A	No	
120	6110	1	3	324A	Primary	Classroom 324C	W4	Cracking	20	No	No	N/A	N/A	No	Repair to brick wall is needed
121	6110	1	3	301	Primary	Copy Room 301	Ceiling	Flaking above missing ceiling tile	4	No	No	N/A	N/A	No	
122	6110	1	3	301	Primary	Copy Room 301	Floor	Debris	N/A	No	Debris in corner of walls 3&4	2	N/A	No	
123	6110	1	3	301	Primary	Copy Room 301	W1	Cracking, Chipping, Flaking	7	No	No	N/A	Posters	No	
124	6110	1	3	301	Primary	Copy Room 301	W2	Limited Inspection		No	No		Posters	No	Limited Inspection due to stored materials
125	6110	1	3	301	Primary	Copy Room 301	W3	Cracking	1	No	No	N/A	Posters	No	
126	6110	1	3	301	Primary	Copy Room 301	W4	Flaking	5	No	No	N/A	Posters	No	
127	6110	1	3	301A		Copy Room 301 Office	Ceiling	No Access							This space will need to be inspected
128	6110	1	3	301A		Copy Room 301 Office	Floor	No Access							This space will need to be inspected
129	6110	1	3	301A		Copy Room 301 Office	W1	No Access							This space will need to be inspected
130	6110	1	3	301A		Copy Room 301 Office	W2	No Access							This space will need to be inspected
131	6110	1	3	301A		Copy Room 301 Office	W3	No Access							This space will need to be inspected
132	6110	1	3	301A		Copy Room 301 Office	W4	No Access							This space will need to be inspected
133	6110	1	3	ELV	Elevators, Passenger	Elevator	Ceiling	No Access							This space will need to be inspected
134	6110	1	3	ELV	Elevators, Passenger	Elevator	Floor	No Access							This space will need to be inspected
135	6110	1	3	ELV	Elevators, Passenger	Elevator	W1	No Access							This space will need to be inspected
136	6110	1	3	ELV	Elevators, Passenger	Elevator	W2	No Access							This space will need to be inspected
137	6110	1	3	ELV	Elevators, Passenger	Elevator	W3	No Access							This space will need to be inspected
138	6110	1	3	ELV	Elevators, Passenger	Elevator	W4	No Access							This space will need to be inspected
139	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	Ceiling	No Access							This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
140	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	Floor	No Access							This space will need to be inspected
141	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	W1	No Access							This space will need to be inspected
142	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	W2	No Access							This space will need to be inspected
143	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	W3	No Access							This space will need to be inspected
144	6110	1	3	S38	Stairs	Fire Stairwell near Classroom 301	W4	No Access							This space will need to be inspected
145	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	Ceiling	No Access							This space will need to be inspected
146	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	Floor	No Access							This space will need to be inspected
147	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	W1	No Access							This space will need to be inspected
148	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	W2	No Access							This space will need to be inspected
149	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	W3	No Access							This space will need to be inspected
150	6110	1	3	S33	Stairs	Fire Stairwell near Classroom 316	W4	No Access							This space will need to be inspected
151	6110	1	3	324	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 316	Ceiling	Hole, paint has been stabilized, Spalling, Efflorescence	7	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
152	6110	1	3	324	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 316	W4	Hole, paint has been stabilized, Efflorescence	3	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
153	6110	1	3	H319	Circulation (Hallway)	Hallway outside Classrooms 303-305	W2	Cracking, Hole, paint has been stabilized, Flaking	4	No	No	N/A	N/A	Yes	
154	6110	1	3	H317	Circulation (Hallway)	Hallway outside Classrooms 306-313	Ceiling	Flaking above windows	32	No	No	N/A	N/A	No	
155	6110	1	3	H317	Circulation (Hallway)	Hallway outside Classrooms 306-313	W1	Cracking, Chipping	82	No	No	N/A	N/A	No	
156	6110	1	3	H317	Circulation (Hallway)	Hallway outside Classrooms 306-313	W3	Cracking, Chipping on wall and metal pipes, Hole, paint has been stabilized, Flaking on wall and metal pipe	96	No	No	N/A	Lockers	Yes	
157	6110	1	3	H317	Circulation (Hallway)	Hallway outside Classrooms 306-313	W4	Flaking	3	No	No	N/A	N/A	No	
158	6110	1	3	H318	Circulation (Hallway)	Hallway outside Classrooms 314-316	Floor	Chipping	11	No	No	N/A	N/A	No	
159	6110	1	3	H318	Circulation (Hallway)	Hallway outside Classrooms 314-316	W2	Cracking, Chipping	9	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
160	6110	1	3	H318	Circulation (Hallway)	Hallway outside Classrooms 314-316	W4	Cracking, Holes, paint has been stabilized, Flaking	12	No	No	N/A	N/A	Yes	
161	6110	1	3	H316	Circulation (Hallway)	Hallway outside Classrooms 317-302	W1	Cracking, Chipping, Holes in ACM pipe insulation, Flaking on wall and metal pipes, Significant Moisture Damage	33	Yes	No	N/A	Lockers	Yes	
162	6110	1	3	H316	Circulation (Hallway)	Hallway outside Classrooms 317-302	W3	Cracking, Chipping, Flaking on wall and metal pipes	22	No	No	N/A	N/A	No	
163	6110	1	3	302A	Restrooms, Staff - Male	Lounge outside Men's Restroom next to Classroom 302	Floor	Debris	N/A	No	Debris in corners of walls 2&3 and walls 3&4	3	N/A	No	
164	6110	1	3	302A	Restrooms, Staff - Male	Lounge outside Men's Restroom next to Classroom 302	W1	Chipping on door	5	No	No	N/A	N/A	No	
165	6110	1	3	302A	Restrooms, Staff - Male	Lounge outside Men's Restroom next to Classroom 302	W2	Cracking, Chipping on wall, metal pipe, and metal jacket, Flaking on wall and metal pipe, Significant Moisture Damage	81	Yes	No	N/A	N/A	Yes	
166	6110	1	3	302A	Restrooms, Staff - Male	Lounge outside Men's Restroom next to Classroom 302	W3	Flaking on metal pipe, Efflorescence	9	Yes	No	N/A	N/A	Yes	
167	6110	1	3	302A	Restrooms, Staff - Male	Lounge outside Men's Restroom next to Classroom 302	W4	Cracking, Gouges, Flaking, Efflorescence	58	Yes	No	N/A	N/A	Yes	
168	6110	1	3	316A	Restrooms, Staff - Female	Lounge outside Women's Restroom next to Classroom 316	W2	Cracking, Hole, Flaking	11	No	No	N/A	N/A	Yes	
169	6110	1	3	316A	Restrooms, Staff - Female	Lounge outside Women's Restroom next to Classroom 316	W3	Flaking on radiator and behind radiator	15	No	No	N/A	N/A	No	
170	6110	1	3	316A	Restrooms, Staff - Female	Lounge outside Women's Restroom next to Classroom 316	W4	Chipping on wall and metal jacket, Holes, Flaking, Efflorescence	16	Yes	No	N/A	N/A	Yes	
171	6110	1	3	302B		Men's Restroom next to Classroom 302	Ceiling	Spalling, Efflorescence	3	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
172	6110	1	3	302B		Men's Restroom next to Classroom 302	Floor	Debris	N/A	No	Debris along wall 4	2	N/A	No	
173	6110	1	3	302B		Men's Restroom next to Classroom 302	W1	Flaking	4	No	No	N/A	N/A	No	
174	6110	1	3	302B		Men's Restroom next to Classroom 302	W2	Flaking	4	No	No	N/A	N/A	No	
175	6110	1	3	302B		Men's Restroom next to Classroom 302	W3	Cracking, Chipping, Holes, Efflorescence	35	Yes	No	N/A	N/A	Yes	
176	6110	1	3	302B		Men's Restroom next to Classroom 302	W4	Flaking on radiator, Spalling, Efflorescence	35	Yes	No	N/A	N/A	Yes	
177	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	Ceiling	Holes above missing ceiling tile, Flaking above missing ceiling tile and windows	17	No	No	N/A	N/A	Yes	
178	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	Floor	Chipping along walls 1&3	16	No	Paint chips in corner of walls 2&3 and 1&4	7	N/A	No	
179	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	W1	Holes, Flaking on wall and in air shaft	28	No	No	N/A		No	Repair to brick wall is needed
180	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	W2	Chipping	8	No	No	N/A	Cabinets	No	
181	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	W3	Cracking, Flaking	18	No	No	N/A	Guitars	No	Repair to brick wall is needed
182	6110	1	3	300A	Primary	Room next to Stairwell across from Classroom 305	W4	Cracking, Chipping, Flaking	52	No	No	N/A	Shelves with stored materials	No	Repair to brick wall is needed
183	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	Ceiling	Efflorescence	6	Yes	No	N/A	N/A	Yes	
184	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	Floor	Chipping on stairs and railings	85	No	No	N/A	N/A	No	
185	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	W1	Efflorescence	2	Yes	No	N/A	N/A	Yes	
186	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	W2	Cracking, Chipping on doors, Flaking on wall and doors	28	No	No	N/A	N/A	No	
187	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	W3	Cracking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
188	6110	1	3	S31	Stairs	Stairwell across from Classroom 303	W4	Cracking, Chipping on metal pipes	7	No	No	N/A	N/A	No	
189	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	Ceiling	Flaking	7	No	No	N/A	N/A	No	
190	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	Floor	Chipping on stairs, cove, and railings	163	No	No	N/A	N/A	No	
191	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	W1	Cracking, Hole, paint has been stabilized	8	No	No	N/A	N/A	Yes	
192	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	W2	Cracking, Chipping on doors, doorframe, and conduit lines, Flaking on doors and doorframe	56	No	No	N/A	N/A	No	
193	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	W3	Cracking, Spalling	6	Yes	No	N/A	N/A	Yes	
194	6110	1	3	S37	Stairs	Stairwell across from Classroom 305	W4	Cracking, Holes, paint has been stabilized, Flaking on metal pipe	11	No	No	N/A	N/A	Yes	
195	6110	1	3	S34	Stairs	Stairwell across from Classroom 314	Ceiling	Cracking	150	No	No	N/A	N/A	No	
196	6110	1	3	S34	Stairs	Stairwell across from Classroom 314	Floor	Chipping on stairs, cove, and railings	106	No	No	N/A	N/A	No	
197	6110	1	3	S34	Stairs	Stairwell across from Classroom 314	W1	Cracking, Spalling	6	Yes	No	N/A	N/A	Yes	
198	6110	1	3	S34	Stairs	Stairwell across from Classroom 314	W2	Chipping on metal pipe, Flaking	36	No	No	N/A	N/A	No	
199	6110	1	3	S34	Stairs	Stairwell across from Classroom 314	W4	Chipping on doors and doorframe, Flaking on door and doorframe	57	No	No	N/A	N/A	No	
200	6110	1	3	S32	Stairs	Stairwell across from Classroom 316	Floor	Chipping on stairs and railings	51	No	No	N/A	N/A	No	
201	6110	1	3	S32	Stairs	Stairwell across from Classroom 316	W1	Efflorescence	10	Yes	No	N/A	N/A	Yes	
202	6110	1	3	S32	Stairs	Stairwell across from Classroom 316	W2	Cracking, Chipping on metal pipe, Efflorescence	7	Yes	No	N/A	N/A	Yes	
203	6110	1	3	S32	Stairs	Stairwell across from Classroom 316	W4	Chipping on doors and doorframe, Flaking on doors and doorframe	32	No	No	N/A	N/A	No	
204	6110	1	3	300C	Storage	Storage Room 300A	Ceiling	Flaking above missing ceiling tile	10	No	No	N/A	Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials
205	6110	1	3	300C	Storage	Storage Room 300A	Floor	Limited Inspection		No	No		Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
206	6110	1	3	300C	Storage	Storage Room 300A	W1	Limited Inspection		No	No		Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials
207	6110	1	3	300C	Storage	Storage Room 300A	W2	Cracking	3	No	No	N/A	Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials. Repair to brick wall is needed.
208	6110	1	3	300C	Storage	Storage Room 300A	W3	Flaking on radiator	3	No	No	N/A	Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials
209	6110	1	3	300C	Storage	Storage Room 300A	W4	Chipping	3	No	No	N/A	Boxes, Shelves, Stored Materials	No	Limited inspection due to stored materials
210	6110	1	3	300B		Storage Room 300B	Ceiling	Cracking, Hole, Flaking above missing ceiling tile	5	No	No	N/A	N/A	Yes	
211	6110	1	3	300B		Storage Room 300B	Floor	Debris	N/A	No	Debris in corner of walls 2&3	1	N/A	No	
212	6110	1	3	300B		Storage Room 300B	W1	Holes, Flaking on wall and in air shaft	13	No	No	N/A	N/A	No	Repair to brick wall is needed
213	6110	1	3	300B		Storage Room 300B	W2	Chipping, Gouges	17	No	No	N/A	Cabinets, Shelves	No	Repair to drywall is needed
214	6110	1	3	300B		Storage Room 300B	W3	Flaking	25	No	No	N/A	N/A	No	
215	6110	1	3	300B		Storage Room 300B	W4	Chipping, Holes	16	No	No	N/A	N/A	No	Repair to drywall is needed
216	6110	1	3	316B		Women's Restroom next to Classroom 316	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
217	6110	1	3	316B		Women's Restroom next to Classroom 316	W1	Cracking	3	No	No	N/A	N/A	No	
218	6110	1	3	316B		Women's Restroom next to Classroom 316	W2	Flaking on wall and metal pipes	15	No	No	N/A	N/A	No	
219	6110	1	3	316B		Women's Restroom next to Classroom 316	W3	Holes, Flaking, Efflorescence	14	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
220	6110	1	3	316B		Women's Restroom next to Classroom 316	W4	Cracking	5	No	No	N/A	N/A	No	
221	6110	1	2	206	Lobby	206 Lobby to Administrative Offices	Floor	Chipping on cove	17	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
222	6110	1	2	206	Lobby	206 Lobby to Administrative Offices	W1	Cracking	80	No	No	N/A	N/A	No	
223	6110	1	2	206	Lobby	206 Lobby to Administrative Offices	W2	Cracking, Holes	6	No	No	N/A	N/A	Yes	
224	6110	1	2	206	Lobby	206 Lobby to Administrative Offices	W3	Holes	3	No	No	N/A	N/A	Yes	
225	6110	1	2	206	Lobby	206 Lobby to Administrative Offices	W4	Cracking	50	No	No	N/A	N/A	No	
226	6110	1	2	H213		2nd Floor Marble Hallway	Ceiling	Flaking	3	No	No	N/A	N/A	No	
227	6110	1	2	H213		2nd Floor Marble Hallway	W1	Chipping, Flaking	3	No	No	N/A	N/A	No	
228	6110	1	2	H213		2nd Floor Marble Hallway	W2	Cracking	1	No	No	N/A	N/A	No	
229	6110	1	2	H213		2nd Floor Marble Hallway	W3	Cracking	3	No	No	N/A	N/A	No	
230	6110	1	2	H213		2nd Floor Marble Hallway	W4	Chipping	1	No	No	N/A	N/A	No	
231	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	Ceiling	Flaking	210	No	No	N/A	N/A	No	Ceiling is assumed
232	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	Floor	Debris	N/A	No	Debris scattered throughout	900	N/A	No	
233	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	W1	Cracking, Flaking on wall, wood adjacent to doors, and metal pipes	132	No	No	N/A	N/A	No	
234	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	W2	Flaking on wall and windowsills	90	No	No	N/A	N/A	No	
235	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	W3	Flaking	70	No	No	N/A	N/A	No	This is low wall inside balcony
236	6110	1	2	217A	Auditorium Balcony	Auditorium Balcony	W4	Flaking on wall and windowsills, Efflorescence	115	Yes	Debris on windowsills	10	N/A	Yes	
237	6110	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 204	Ceiling	Flaking, Efflorescence	32	Yes	No	N/A	N/A	Yes	
238	6110	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 204	Floor	Debris	N/A	No	Paint chips near entrance	2	N/A	No	
239	6110	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 204	W1	Chipping, Efflorescence	3	Yes	No	N/A	N/A	Yes	
240	6110	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 204	W2	Cracking, Chipping, Flaking, Efflorescence	17	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
241	6110	1	2	200	Student Restrooms - Male (4-12)	Boy's Restroom across Classroom 204	W4	Chipping, Efflorescence	2	Yes	No	N/A	N/A	Yes	
242	6110	1	2	200A	Primary	Classroom 200A	Ceiling	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
243	6110	1	2	200A	Primary	Classroom 200A	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
244	6110	1	2	200A	Primary	Classroom 200A	W1	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
245	6110	1	2	200A	Primary	Classroom 200A	W2	Chipping	4	No	No	N/A	Stored Materials	No	
246	6110	1	2	200A	Primary	Classroom 200A	W3	Chipping on radiator, Flaking	12	No	No	N/A	Cabinet, Stored Materials	No	
247	6110	1	2	200A	Primary	Classroom 200A	W4	Cracking	2	No	No	N/A	Stored Materials	No	Repair to brick wall is needed
248	6110	1	2	200B	Primary	Classroom 200B	Floor	Chipping along walls 1 and 3	16	No	No	N/A	N/A	No	
249	6110	1	2	200B	Primary	Classroom 200B	W4	Chipping	9	No	No	N/A	N/A	No	
250	6110	1	2	200C	Primary	Classroom 200C	Floor	Chipping along walls 1,2 and 3	24	No	No	N/A	Furniture	No	
251	6110	1	2	200C	Primary	Classroom 200C	W1	Limited Inspection		No	No		Shelf with stored materials	No	Limited Inspection due to stored materials
252	6110	1	2	200C	Primary	Classroom 200C	W2	Flaking	1	No	No	N/A	Furniture	No	
253	6110	1	2	200C	Primary	Classroom 200C	W3	Limited Inspection		No	No		Furniture	No	Limited inspection due to stored materials
254	6110	1	2	200C	Primary	Classroom 200C	W4	Limited Inspection		No	No		Furniture	No	Limited inspection due to stored materials
255	6110	1	2	201	Primary	Classroom 201	W1	Cracking, Chipping, Holes	27	No	No	N/A	Guitars	Yes	
256	6110	1	2	201	Primary	Classroom 201	W2	Cracking, Chipping	9	No	No	N/A	Guitars, Cabinets	No	
257	6110	1	2	201	Primary	Classroom 201	W3	Chipping on wall, windowsills, and radiators, Hole behind radiator, Flaking on wall and behind radiator, Efflorescence on wall and behind radiator	60	Yes	No	N/A	Desks	Yes	
258	6110	1	2	201	Primary	Classroom 201	W4	Chipping, Flaking	12	No	No	N/A	Desks	No	
259	6110	1	2	202	Primary	Classroom 202	W1	Cracking, Chipping on wall and door, Holes	18	No	No	N/A	Furniture, Posters	Yes	
260	6110	1	2	202	Primary	Classroom 202	W2	Chipping, Flaking, Efflorescence	15	Yes	No	N/A	Furniture, Stored Materials	Yes	
261	6110	1	2	202	Primary	Classroom 202	W3	Chipping on radiator, Hole, Flaking behind radiator	26	No	No	N/A	Furniture, Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
262	6110	1	2	202	Primary	Classroom 202	W4	Cracking, Chipping, Flaking	40	No	No	N/A	Furniture, Posters	No	
263	6110	1	2	203	Primary	Classroom 203	W1	Cracking, Chipping, Flaking	18	No	No	N/A	Stored Materials	No	
264	6110	1	2	203	Primary	Classroom 203	W2	Chipping	1	No	No	N/A	Stored Materials	No	
265	6110	1	2	203	Primary	Classroom 203	W3	Chipping on wall and radiator, Flaking, Efflorescence	24	Yes	No	N/A	Stored Materials	Yes	
266	6110	1	2	203	Primary	Classroom 203	W4	Cracking, Flaking	5	No	No	N/A	Stored Materials	No	
267	6110	1	2	204	Primary	Classroom 204	W1	Cracking, Chipping	71	No	No	N/A	Boxes	No	
268	6110	1	2	204	Primary	Classroom 204	W3	Chipping on radiator, Flaking behind radiator, Efflorescence	21	Yes	No	N/A	Furniture, Stored Materials	Yes	
269	6110	1	2	205	Primary	Classroom 205	W1	Cracking, Hole, paint has been stabilized, Flaking, Efflorescence in air shaft	83	Yes	No	N/A	N/A	Yes	
270	6110	1	2	205	Primary	Classroom 205	W2	Cracking, Chipping, Flaking	3	No	No	N/A	N/A	No	
271	6110	1	2	205	Primary	Classroom 205	W3	Flaking on wall and behind radiator, Efflorescence	37	Yes	Debris on windowsills	2	Tables	Yes	
272	6110	1	2	210	Primary	Classroom 210	Floor	Chipping on cove	60	No	No	N/A	N/A	No	
273	6110	1	2	210	Primary	Classroom 210	W1	Holes, paint has been stabilized on 1, Flaking on wall and metal pipe	4	No	No	N/A	Cabinet	Yes	
274	6110	1	2	210	Primary	Classroom 210	W3	Cracking	2	No	No	N/A	Boxes, Desk	No	
275	6110	1	2	210	Primary	Classroom 210	W4	Chipping	2	No	No	N/A	N/A	No	
276	6110	1	2	211	Primary	Classroom 211	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
277	6110	1	2	211	Primary	Classroom 211	W1	Cracking, Chipping on wall and wood cabinets, Holes	31	No	No	N/A	Posters	Yes	
278	6110	1	2	211	Primary	Classroom 211	W2	Limited Inspection		No	No		Posters	No	Limited Inspection due to stored materials
279	6110	1	2	211	Primary	Classroom 211	W3	Chipping, Hole, Flaking behind radiator	12	No	No	N/A	Keyboards	No	
280	6110	1	2	211	Primary	Classroom 211	W4	Chipping on metal pipes, Efflorescence	6	Yes	No	N/A	Shelves	Yes	
281	6110	1	2	211A	Storage	Classroom 211 Storage	Ceiling	Flaking, Significant Moisture Damage above missing ceiling tiles	22	Yes	No	N/A	N/A	Yes	
282	6110	1	2	211A	Storage	Classroom 211 Storage	W1	Chipping on door	10	No	No	N/A	N/A	No	
283	6110	1	2	211A	Storage	Classroom 211 Storage	W2	Cracking, Hole, paint has been stabilized, Flaking	25	No	No	N/A	N/A	Yes	
284	6110	1	2	211A	Storage	Classroom 211 Storage	W3	Flaking on metal pipe, Efflorescence	12	Yes	Debris on windowsills	5	N/A	Yes	
285	6110	1	2	211A	Storage	Classroom 211 Storage	W4	Cracking	3	No	No	N/A	N/A	No	Repair to concrete block needed
286	6110	1	2	212	Primary	Classroom 212	Floor	Chipping on cove	20	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
287	6110	1	2	212	Primary	Classroom 212	W1	Cracking, Chipping on wall and wood cabinets	27	No	No	N/A	Posters	No	
288	6110	1	2	212	Primary	Classroom 212	W2	Chipping, Flaking	2	No	No	N/A	Posters	No	
289	6110	1	2	212	Primary	Classroom 212	W3	Flaking on wall, metal pipe, and behind radiators	25	No	No	N/A	Desk, Posters	No	
290	6110	1	2	212	Primary	Classroom 212	W4	Limited Inspection		No	No		Posters	No	Limited Inspection due to stored materials
291	6110	1	2	213	Primary	Classroom 213	W1	Cracking, Chipping, Holes, paint has been stabilized on 1, Flaking	55	No	No	N/A	Desk	Yes	
292	6110	1	2	213	Primary	Classroom 213	W2	Chipping	2	No	No	N/A	Cabinets	No	
293	6110	1	2	213	Primary	Classroom 213	W3	Chipping on metal pipes and radiator, Hole, Flaking behind radiators	43	No	No	N/A	Shelves, Stored Materials	Yes	
294	6110	1	2	213	Primary	Classroom 213	W4	Cracking, Hole	101	No	No	N/A	N/A	Yes	
295	6110	1	2	214	Primary	Classroom 214	W1	Chipping	4	No	No	N/A	Posters	No	
296	6110	1	2	214	Primary	Classroom 214	W2	Chipping, Staple Holes, Flaking	27	No	No	N/A	Posters	Yes	
297	6110	1	2	214	Primary	Classroom 214	W3	Flaking behind radiator	5	No	No	N/A	Furniture, Stored Materials	No	
298	6110	1	2	214	Primary	Classroom 214	W4	Limited Inspection		No	No		Furniture, Stored Materials	No	Limited inspection due to stored materials
299	6110	1	2	215	Primary	Classroom 215	Ceiling	Flaking, Significant Moisture Damage above missing ceiling tiles	5	Yes	No	N/A	N/A	Yes	
300	6110	1	2	215	Primary	Classroom 215	W1	Cracking, Chipping, Flaking	24	No	No	N/A	Desk	Yes	
301	6110	1	2	215	Primary	Classroom 215	W2	Cracking, Chipping	34	No	No	N/A	Tables with computers	Yes	
302	6110	1	2	215	Primary	Classroom 215	W3	Cracking, Chipping, Hole	16	No	Debris on windowsills	4	Tables with computers	Yes	
303	6110	1	2	215	Primary	Classroom 215	W4	Chipping, Flaking	32	No	No	N/A	Tables with computers	No	
304	6110	1	2	216	Primary	Classroom 216	W1	Cracking, Flaking on wall and in air shaft	14	No	No	N/A	Desk	No	
305	6110	1	2	216	Primary	Classroom 216	W2	Cracking, Chipping	6	No	No	N/A	Shelves, Stored Materials	No	
306	6110	1	2	216	Primary	Classroom 216	W3	Flaking behind radiators	40	No	No	N/A	Shelves, Stored Materials	No	
307	6110	1	2	216	Primary	Classroom 216	W4	Cracking	5	No	No	N/A	Stored Materials	No	
308	6110	1	2	217	Primary	Classroom 217	Ceiling	Flaking above missing ceiling tile	1	No	No	N/A	N/A	No	
309	6110	1	2	217	Primary	Classroom 217	W1	Cracking, Chipping, Hole	19	No	No	N/A	Shelf	Yes	
310	6110	1	2	217	Primary	Classroom 217	W2	Chipping	5	No	No	N/A	N/A	No	
311	6110	1	2	217	Primary	Classroom 217	W3	Cracking	15	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
312	6110	1	2	217	Primary	Classroom 217	W4	Flaking, Hole, paint has been stabilized	5	No	No	N/A	N/A	Yes	
313	6110	1	2	218	Primary	Classroom 218	W1	Cracking, Chipping, Hole, Flaking on wall and in air shaft	28	No	No	N/A	Posters	Yes	
314	6110	1	2	218	Primary	Classroom 218	W2	Cracking, Chipping, Gouges	14	No	No	N/A	Shelves, Cabinet, Stored Materials	Yes	
315	6110	1	2	218	Primary	Classroom 218	W3	Cracking, Chipping, Hole, Flaking on wall and behind radiators	33	No	No	N/A	Furniture, Stored Materials	Yes	
316	6110	1	2	218	Primary	Classroom 218	W4	Chipping	3	No	No	N/A	Furniture, Stored Materials	No	
317	6110	1	2	219	Primary	Classroom 219	Ceiling	Flaking, Significant Moisture Damage above missing ceiling tiles	12	Yes	No	N/A	N/A	Yes	
318	6110	1	2	219	Primary	Classroom 219	W1	Cracking, Chipping, Hole	12	No	No	N/A	Desks, Posters	Yes	
319	6110	1	2	219	Primary	Classroom 219	W2	Chipping	1	No	No	N/A	Cabinet, Shelf, Stoted Materials	No	
320	6110	1	2	219	Primary	Classroom 219	W3	Flaking on wall and behind radiator	11	No	Debris on windowsills	4	Furniture, Stored Materials	No	
321	6110	1	2	219	Primary	Classroom 219	W4	Chipping	4	No	No	N/A	Furniture, Posters	No	
322	6110	1	2	220	Primary	Classroom 220	W1	Chipping, Holes, Flaking	29	No	No	N/A	Shelves, Stored Materials, Posters	Yes	
323	6110	1	2	220	Primary	Classroom 220	W2	Chipping, Gouges, Flaking	14	No	No	N/A	Furniture, Stored Materials	Yes	
324	6110	1	2	220	Primary	Classroom 220	W3	Cracking, Chipping, Efflorescence	12	Yes	Debris on windowsills	6	Furniture, Stored Materials	Yes	
325	6110	1	2	220	Primary	Classroom 220	W4	Limited Inspection		No	No		Furniture, Stored Materials	No	Limited inspection due to stored materials
326	6110	1	2	222	Primary	Classroom 221A	Floor	Debris	N/A	No	Paint Chips along wall 3	3	N/A	No	
327	6110	1	2	222	Primary	Classroom 221A	W1	Chipping on wall and door	3	No	No	N/A	N/A	No	
328	6110	1	2	222	Primary	Classroom 221A	W2	Chipping, Flaking	10	No	No	N/A	N/A	No	
329	6110	1	2	222	Primary	Classroom 221A	W3	Flaking	50	No	No	N/A	N/A	No	
330	6110	1	2	221B	Primary	Classroom 221B	Ceiling	Cracking beam, Flaking beam	6	No	No	N/A	N/A	Yes	
331	6110	1	2	221B	Primary	Classroom 221B	Floor	Chipping along walls 1&3	5	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
332	6110	1	2	221B	Primary	Classroom 221B	W2	Cracking	10	No	No	N/A	Computer Carts	No	Repair to concrete block needed
333	6110	1	2	221B	Primary	Classroom 221B	W3	Flaking	11	No	Paint chips along wall	1	N/A	No	
334	6110	1	2	221B	Primary	Classroom 221B	W4	Cracking	12	No	No	N/A	Computer Carts	No	
335	6110	1	2	221C	Primary	Classroom 221C	Floor	Debris	N/A	No	Debris along wall 3	5	N/A	No	
336	6110	1	2	221C	Primary	Classroom 221C	W2	Cracking, Holes	8	No	No	N/A	N/A	No	Repair to sheetrock needed
337	6110	1	2	221C	Primary	Classroom 221C	W3	Flaking, Efflorescence	20	Yes	No	N/A	N/A	No	
338	6110	1	2	221C	Primary	Classroom 221C	W4	Cracking, Flaking	18	No	No	N/A	N/A	No	Repair to brick needed
339	6110	1	2	208	Administrative Office	Conference Room adjacent to Principal's Office	W1	Chipping, Gouge	31	No	No	N/A	N/A	Yes	
340	6110	1	2	208	Administrative Office	Conference Room adjacent to Principal's Office	W2	Holes	2	No	No	N/A	N/A	Yes	
341	6110	1	2	208	Administrative Office	Conference Room adjacent to Principal's Office	W3	Chipping, Gouge	16	No	No	N/A	N/A	Yes	
342	6110	1	2	208	Administrative Office	Conference Room adjacent to Principal's Office	W4	Flaking	20	No	No	N/A	N/A	No	
343	6110	1	2	207	Administrative Office	Counselor Office next to 206 Suites	W1	Flaking	1	No	No	N/A	N/A	No	
344	6110	1	2	207	Administrative Office	Counselor Office next to 206 Suites	W2	Limited Inspection		No	No		File Cabinets	No	Limited inspection due to stored materials
345	6110	1	2	207	Administrative Office	Counselor Office next to 206 Suites	W3	Cracking	2	No	No	N/A	N/A	No	
346	6110	1	2	207	Administrative Office	Counselor Office next to 206 Suites	W4	Cracking	20	No	No	N/A	N/A	No	
347	6110	1	2	S23	Stairs	Fire Stairwell near Classroom 216	Ceiling	Spalling, Efflorescence	30	Yes	No	N/A	N/A	No	
348	6110	1	2	S23	Stairs	Fire Stairwell near Classroom 216	Floor	Chipping on stairs, Flaking on stairs	126	No	No	N/A	N/A	No	
349	6110	1	2	S23	Stairs	Fire Stairwell near Classroom 216	W1	Chipping, Hole, Significant Moisture Damage	6	Yes	No	N/A	N/A	No	
350	6110	1	2	S23	Stairs	Fire Stairwell near Classroom 216	W3	Flaking on bars and metal pipe	155	No	No	N/A	N/A	No	
351	6110	1	2	S23	Stairs	Fire Stairwell near Classroom 216	W4	Chipping, Flaking	14	No	No	N/A	N/A	No	
352	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	Ceiling	Chipping, Flaking, Spalling, Efflorescence	112	Yes	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
353	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	Floor	Chipping on stairs, Flaking on stairs	126	No	Debris	35	N/A	No	
354	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	W1	Cracking, Flaking on wall, door, and windowframe	21	No	No	N/A	N/A	No	Repair to brick needed
355	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	W2	Flaking on wall and metal pipe	11	No	No	N/A	N/A	No	
356	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	W3	Cracking, Chipping, Flaking on wall and bars, Spalling	179	Yes	No	N/A	N/A	No	
357	6110	1	2	S28	Stairs	Fire Stairwell next to Classroom 220	W4	Cracking, Flaking	10	No	No	N/A	N/A	No	Repair to brick needed
358	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	Ceiling	Flaking, Efflorescence	8	Yes	No	N/A	N/A	Yes	
359	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	Floor	Chipping on floor and entrance partition	65	No	No	N/A	N/A	No	
360	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	W1	Cracking	3	No	No	N/A	N/A	No	
361	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	W2	Cracking, Flaking on wall and metal pipe, Spalling	44	Yes	No	N/A	N/A	Yes	
362	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	W3	Efflorescence	12	Yes	Debris on windowsill	3	N/A	Yes	
363	6110	1	2	221A	Student Restrooms - Female (4-12)	Girl's Restroom across from Classroom 214	W4	Cracking	3	No	No	N/A	N/A	No	
364	6110	1	2	211B		Hallway between Classrooms 210-211	W2	Chipping on wall and metal pipe	4	No	No	N/A	Piano, Fan	No	
365	6110	1	2	211B		Hallway between Classrooms 210-211	W4	Chipping	2	No	No	N/A	N/A	No	
366	6110	1	2	H215	Circulation (Hallway)	Hallway outside Classrooms 203-205	W2	Chipping on lockers, Cracking	38	No	No	N/A	N/A	No	
367	6110	1	2	H215	Circulation (Hallway)	Hallway outside Classrooms 203-205	W4	Holes, paint has been stabilized, Flaking	3	No	No	N/A	N/A	No	
368	6110	1	2	H214	Circulation (Hallway)	Hallway outside Classrooms 212-214	W2	Cracking, Chipping, Efflorescence	19	Yes	No	N/A	N/A	Yes	
369	6110	1	2	H214	Circulation (Hallway)	Hallway outside Classrooms 212-214	W4	Cracking, Holes, paint has been stabilized on 1	78	No	No	N/A	N/A	Yes	
370	6110	1	2	H212	Circulation (Hallway)	Hallway outside Classrooms 215-202	Ceiling	Flaking above windows, Significant Moisture Damage above windows	16	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
371	6110	1	2	H212	Circulation (Hallway)	Hallway outside Classrooms 215-202	W1	Cracking on wall and ACM pipe insulation, Chipping on metal pipe, Flaking on wall and metal jacket, Efflorescence	105	Yes	Debris on windowsills	4	N/A	Yes	
372	6110	1	2	H212	Circulation (Hallway)	Hallway outside Classrooms 215-202	W3	Cracking, Chipping on metal pipes and metal jackets, Hole, paint has been stabilized, Flaking	240	No	No	N/A	N/A	Yes	
373	6110	1	2	H213B	Circulation (Hallway)	Hallway outside Nurse's Office to Classroom 211	Ceiling	Flaking above windows, Significant Moisture Damage above windows	12	No	No	N/A	N/A	Yes	
374	6110	1	2	H213B	Circulation (Hallway)	Hallway outside Nurse's Office to Classroom 211	W1	Cracking	60	No	No	N/A	N/A	No	
375	6110	1	2	H213B	Circulation (Hallway)	Hallway outside Nurse's Office to Classroom 211	W2	Flaking	4	No	No	N/A	N/A	No	
376	6110	1	2	H213B	Circulation (Hallway)	Hallway outside Nurse's Office to Classroom 211	W3	Chipping on metal pipes, Hole, Flaking on wall and metal pipe	18	No	No	N/A	N/A	Yes	
377	6110	1	2	H213B	Circulation (Hallway)	Hallway outside Nurse's Office to Classroom 211	W4	Holes	4	No	No	N/A	N/A	Yes	
378	6110	1	2	H213A	Circulation (Hallway)	Hallway outside Office 206 Suite to Main Office	Ceiling	Flaking above windows, Efflorescence above windows	18	Yes	No	N/A	N/A	Yes	
379	6110	1	2	H213A	Circulation (Hallway)	Hallway outside Office 206 Suite to Main Office	W1	Cracking, Chipping, Flaking	41	No	No	N/A	N/A	No	
380	6110	1	2	H213A	Circulation (Hallway)	Hallway outside Office 206 Suite to Main Office	W3	Cracking, Spalling, Flaking	33	Yes	No	N/A	N/A	Yes	
381	6110	1	2	202A		Lounge outside Men's Restroom next to Classroom 202	Floor	Debris	N/A	No	Paint chips along wall 2	2	N/A	No	
382	6110	1	2	202A		Lounge outside Men's Restroom next to Classroom 202	W2	Chipping on metal jacket, Flaking, Spalling, Efflorescence	9	Yes	No	N/A	N/A	Yes	
383	6110	1	2	202A		Lounge outside Men's Restroom next to Classroom 202	W3	Flaking behind radiator, Efflorescence	14	Yes	Debris on windowsills	2	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
384	6110	1	2	202A		Lounge outside Men's Restroom next to Classroom 202	W4	Cracking, Chipping, Hole, Flaking, Efflorescence	30	Yes	No	N/A	N/A	Yes	
385	6110	1	2	215A		Lounge outside Women's Restroom next to Classroom 214	Ceiling	Significant Moisture Damage above missing ceiling tile	8	Yes	No	N/A	N/A	Yes	
386	6110	1	2	215A		Lounge outside Women's Restroom next to Classroom 214	W2	Cracking	25	No	No	N/A	N/A	Yes	
387	6110	1	2	215A		Lounge outside Women's Restroom next to Classroom 214	W3	Flaking on wall and radiator	12	No	No	N/A	N/A	No	
388	6110	1	2	215A		Lounge outside Women's Restroom next to Classroom 214	W4	Chipping on wall and metal jacket, Holes, Flaking, Significant Moisture Damage above missing ceiling tile	44	Yes	No	N/A	N/A	Yes	
389	6110	1	2	208F	Administrative Office	Main Office	Floor	Debris	N/A	No	Paint chips around wall 4 pipes	2	N/A	No	
390	6110	1	2	208F	Administrative Office	Main Office	W1	Cracking, Chipping	6	No	No	N/A	N/A	No	
391	6110	1	2	208F	Administrative Office	Main Office	W2	Flaking on wall and metal pipe	7	No	No	N/A	N/A	No	
392	6110	1	2	208F	Administrative Office	Main Office	W3	Chipping	3	No	No	N/A	N/A	No	
393	6110	1	2	208F	Administrative Office	Main Office	W4	Cracking, Chipping on wall and metal jackets, Hole, paint has been stabilized, Flaking on wall, metal pipe, and metal jackets	32	No	No	N/A	N/A	Yes	
394	6110	1	2	208I	Restrooms, Staff - Male/Female	Main Office Staff Restroom	Floor	Debris	N/A	No	Debris scattered around edges	8	N/A	No	
395	6110	1	2	208I	Restrooms, Staff - Male/Female	Main Office Staff Restroom	W1	Cracking	20	No	No	N/A	N/A	No	
396	6110	1	2	208I	Restrooms, Staff - Male/Female	Main Office Staff Restroom	W2	Cracking, Chipping, Flaking	22	No	No	N/A	Lockers	No	
397	6110	1	2	208I	Restrooms, Staff - Male/Female	Main Office Staff Restroom	W3	Holes in wall and ACM pipe insulation, Flaking, Efflorescence	22	No	No	N/A	N/A	Yes	
398	6110	1	2	208I	Restrooms, Staff - Male/Female	Main Office Staff Restroom	W4	Cracking, Hole, Flaking on metal pipe and radiator, Efflorescence	24	No	No	N/A	N/A	Yes	
399	6110	1	2	208G	Storage	Main Office Storage Closet	Ceiling	Hole above missing ceiling tile	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
400	6110	1	2	208G	Storage	Main Office Storage Closet	W1	Cracking, Chipping on wall and metal jackets, Holes, Flaking	22	No	No	N/A	N/A	Yes	
401	6110	1	2	208G	Storage	Main Office Storage Closet	W2	Cracking, some above missing ceiling tile, Chipping, Hole above missing ceiling tile	23	No	No	N/A	Shelves with stored materials	Yes	
402	6110	1	2	208G	Storage	Main Office Storage Closet	W3	Chipping, Flaking	2	No	No	N/A	Shelves with stored materials	No	
403	6110	1	2	208G	Storage	Main Office Storage Closet	W4	Chipping, Hole	3	No	No	N/A	Shelves with stored materials	Yes	
404	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	Ceiling	Efflorescence	6	Yes	No	N/A	N/A	Yes	
405	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	Floor	Debris	N/A	No	Debris along walls 3&4	6	N/A	No	
406	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	W1	Cracking, Spalling, Efflorescence	9	Yes	No	N/A	N/A	Yes	
407	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	W2	Cracking	25	No	No	N/A	N/A	No	
408	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	W3	Cracking, Hole, Efflorescence	44	Yes	No	N/A	N/A	Yes	
409	6110	1	2	202B	Restrooms, Staff - Male	Men's Restroom next to Classroom 202	W4	Flaking on metal pipe, Efflorescence	40	Yes	Debris on windowsill	1	N/A	Yes	
410	6110	1	2	209D		Nurse's Office	Floor	Debris	N/A	No	Debris below radiator	3	N/A	No	
411	6110	1	2	209D		Nurse's Office	W2	Hole	1	No	No	N/A	N/A	Yes	
412	6110	1	2	209D		Nurse's Office	W3	Efflorescence, Significant Moisture Damage behind radiator	4	Yes	No	N/A	N/A	Yes	
413	6110	1	2	209D		Nurse's Office	W4	Hole, Efflorescence	2	Yes	No	N/A	N/A	Yes	
414	6110	1	2	209E		Nurse's Office Exam Room	Ceiling	Flaking above missing ceiling tile	6	No	No	N/A	N/A	No	
415	6110	1	2	209E		Nurse's Office Exam Room	Floor	Debris	N/A	No	Debris along wall 4	3	N/A	No	
416	6110	1	2	209E		Nurse's Office Exam Room	W2	Cracking	5	No	No	N/A	N/A	No	
417	6110	1	2	209E		Nurse's Office Exam Room	W3	Chipping	4	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
418	6110	1	2	209F		Nurse's Office Exam Room Closet	Ceiling	No Access							This space will need to be inspected
419	6110	1	2	209F		Nurse's Office Exam Room Closet	Floor	No Access							This space will need to be inspected
420	6110	1	2	209F		Nurse's Office Exam Room Closet	W1	No Access							This space will need to be inspected
421	6110	1	2	209F		Nurse's Office Exam Room Closet	W2	No Access							This space will need to be inspected
422	6110	1	2	209F		Nurse's Office Exam Room Closet	W3	No Access							This space will need to be inspected
423	6110	1	2	209F		Nurse's Office Exam Room Closet	W4	No Access							This space will need to be inspected
424	6110	1	2	209B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W1	Hole	1	No	No	N/A	N/A	Yes	
425	6110	1	2	209B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W2	Flaking on metal pipe	3	No	No	N/A	N/A	No	
426	6110	1	2	209A	Administrative Office	Nurse's Office Waiting Area	W1	Chipping	1	No	No	N/A	N/A	No	
427	6110	1	2	209A	Administrative Office	Nurse's Office Waiting Area	W2	Limited Inspection		No	No		Shelf	No	Limited Inspection due to stored materials
428	6110	1	2	209A	Administrative Office	Nurse's Office Waiting Area	W3	Limited Inspection		No	No		Chairs	No	Limited inspection due to stored materials
429	6110	1	2	206B	Administrative Office	Office 206B	Floor	Debris	N/A	No	Debris along wall 3	5	N/A	No	
430	6110	1	2	206B	Administrative Office	Office 206B	W1	Cracking, Chipping	22	No	No	N/A	N/A	No	
431	6110	1	2	206B	Administrative Office	Office 206B	W2	Cracking	55	No	No	N/A	N/A	No	
432	6110	1	2	206B	Administrative Office	Office 206B	W3	Hole, Spalling, Efflorescence, Significant Moisture Damage above missing ceiling tile	19	Yes	Debris on windowsill	1	N/A	Yes	
433	6110	1	2	206B	Administrative Office	Office 206B	W4	Cracking, Efflorescence	21	Yes	No	N/A	N/A	Yes	
434	6110	1	2	206C	Administrative Office	Office 206C	Floor	Debris	N/A	No	Paint chips in corner of walls 2&3	1	N/A	No	
435	6110	1	2	206C	Administrative Office	Office 206C	W2	Cracking, Spalling	16	Yes	No	N/A	N/A	Yes	
436	6110	1	2	206C	Administrative Office	Office 206C	W3	Flaking, Efflorescence	10	Yes	Debris on windowsill	1	N/A	Yes	
437	6110	1	2	206C	Administrative Office	Office 206C	W4	Flaking	4	No	No	N/A	N/A	No	
438	6110	1	2	206D	Administrative Office	Office 206D	Floor	Debris	N/A	No	Paint chips below radiator	3	N/A	No	
439	6110	1	2	206D	Administrative Office	Office 206D	W1	Chipping	3	No	No	N/A	Desk	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
440	6110	1	2	206D	Administrative Office	Office 206D	W2	Cracking, Chipping	25	No	No	N/A	Table	No	
441	6110	1	2	206D	Administrative Office	Office 206D	W3	Chipping, Significant Moisture Damage behind radiator	21	Yes	No	N/A	N/A	Yes	
442	6110	1	2	206D	Administrative Office	Office 206D	W4	Hole	1	No	No	N/A	Cabinet	Yes	
443	6110	1	2	206E	Administrative Office	Office 206E	W1	Limited Inspection		No	No		Desk	No	Limited inspection due to stored materials
444	6110	1	2	206E	Administrative Office	Office 206E	W2	Cracking, Flaking	35	No	No	N/A	N/A	No	
445	6110	1	2	206E	Administrative Office	Office 206E	W3	Flaking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
446	6110	1	2	206E	Administrative Office	Office 206E	W4	Flaking	1	No	No	N/A	N/A	No	
447	6110	1	2	207A	Lobby	Office 207 Lobby area to Left of 206 Suites	W1	Chipping, Flaking on wall and in air shaft	10	No	No	N/A	Shelf	No	
448	6110	1	2	207A	Lobby	Office 207 Lobby area to Left of 206 Suites	W4	Chipping, Gouge, Flaking	3	No	No	N/A	Cabinets	Yes	
449	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	Ceiling	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
450	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
451	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	W1	Chipping on doorframe	4	No	No	N/A	Stored Materials	No	
452	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	W2	Chipping	3	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
453	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	W3	Limited Inspection		No	Debris on windowsills		Stored Materials	No	Limited Inspection due to stored materials
454	6110	1	2	208A	Administrative Office	Office next to Counselor's Office	W4	Limited Inspection		No	No		Stored Materials, Cabinet	No	Limited Inspection due to stored materials
455	6110	1	2	208D	Administrative Office	Office next to Principal's Office	W1	Chipping	1	No	No	N/A	N/A	No	
456	6110	1	2	208D	Administrative Office	Office next to Principal's Office	W3	Flaking, Efflorescence behind radiator, Significant Moisture Damage behind radiator	12	Yes	No	N/A	N/A	Yes	
457	6110	1	2	208E	Administrative Office	Principal's Office	Floor	Debris	N/A	No	Debris behind desk	7	N/A	No	
458	6110	1	2	208E	Administrative Office	Principal's Office	W2	Flaking on metal pipe, Efflorescence	7	Yes	No	N/A	Desk	Yes	
459	6110	1	2	208E	Administrative Office	Principal's Office	W3	Chipping	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
460	6110	1	2	208E	Administrative Office	Principal's Office	W4	Cracking	5	No	No	N/A	N/A	No	
461	6110	1	2	208H	Storage	Principal's Office Storage Closet	W1	Chipping	2	No	No	N/A	N/A	No	
462	6110	1	2	208H	Storage	Principal's Office Storage Closet	W2	Holes	10	No	No	N/A	N/A	Yes	
463	6110	1	2	208H	Storage	Principal's Office Storage Closet	W3	Cracking	10	No	No	N/A	Shelf, Stored Materials	No	Limited inspection due to stored materials
464	6110	1	2	208H	Storage	Principal's Office Storage Closet	W4	Hole	1	No	No	N/A	N/A	Yes	
465	6110	1	2	208C	Administrative Office	Second Office from Left in Conference Room	W1	Chipping	5	No	No	N/A	N/A	No	
466	6110	1	2	208C	Administrative Office	Second Office from Left in Conference Room	W2	Hole	1	No	No	N/A	Cabinets	Yes	
467	6110	1	2	208C	Administrative Office	Second Office from Left in Conference Room	W3	Holes, Efflorescence	6	Yes	Debris below radiator	3	N/A	Yes	
468	6110	1	2	208C	Administrative Office	Second Office from Left in Conference Room	W4	Cracking	5	No	No	N/A	N/A	No	
469	6110	1	2	208B	Administrative Office	Second Office from Right in Conference Room	W1	Chipping	3	No	No	N/A	N/A	No	
470	6110	1	2	208B	Administrative Office	Second Office from Right in Conference Room	W2	Flaking	1	No	No	N/A	N/A	No	
471	6110	1	2	208B	Administrative Office	Second Office from Right in Conference Room	W4	Chipping	7	No	No	N/A	N/A	No	
472	6110	1	2	S27	Stairs	Stairwell across from Classroom 205	Ceiling	Cracking, Spalling	10	Yes	No	N/A	N/A	Yes	
473	6110	1	2	S27	Stairs	Stairwell across from Classroom 205	Floor	Chipping on stairs, cove, and railings	179	No	No	N/A	N/A	No	
474	6110	1	2	S27	Stairs	Stairwell across from Classroom 205	W2	Cracking, Chipping on doors and doorframe, Flaking on doors and doorframe	35	No	No	N/A	N/A	No	
475	6110	1	2	S27	Stairs	Stairwell across from Classroom 205	W3	Cracking	2	No	No	N/A	N/A	No	
476	6110	1	2	S27	Stairs	Stairwell across from Classroom 205	W4	Cracking, Chipping on metal pipe	3	No	No	N/A	N/A	No	
477	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
478	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	Floor	Chipping on stairs, floor, and railings	69	No	No	N/A	N/A	No	
479	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	W1	Cracking, Chipping, Flaking	4	No	No	N/A	N/A	No	
480	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	W2	Chipping on doors and doorframe	14	No	No	N/A	N/A	No	
481	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	W3	Chipping on metal pipe	1	No	No	N/A	N/A	No	
482	6110	1	2	S21	Stairs	Stairwell across from Classroom 203	W4	Efflorescence	2	Yes	No	N/A	N/A	Yes	
483	6110	1	2	S24	Stairs	Stairwell across from Classroom 212	Ceiling	Cracking, Efflorescence	3	Yes	No	N/A	N/A	Yes	
484	6110	1	2	S24	Stairs	Stairwell across from Classroom 212	Floor	Chipping on stairs, cove, and railings	105	No	No	N/A	N/A	No	
485	6110	1	2	S24	Stairs	Stairwell across from Classroom 212	W1	Cracking	1	No	No	N/A	N/A	No	
486	6110	1	2	S24	Stairs	Stairwell across from Classroom 212	W2	Chipping on metal pipe, Efflorescence	3	Yes	No	N/A	N/A	Yes	
487	6110	1	2	S24	Stairs	Stairwell across from Classroom 212	W4	Chipping on doors and doorframe	17	No	No	N/A	N/A	No	
488	6110	1	2	S22	Stairs	Stairwell Next to Classroom 214	Floor	Chipping on floor, stairs, cove, and railings	72	No	No	N/A	N/A	No	
489	6110	1	2	S22	Stairs	Stairwell Next to Classroom 214	W2	Flaking, Spalling, Efflorescence	6	Yes	No	N/A	N/A	Yes	
490	6110	1	2	S22	Stairs	Stairwell Next to Classroom 214	W3	Cracking	1	No	No	N/A	N/A	No	
491	6110	1	2	S22	Stairs	Stairwell Next to Classroom 214	W4	Chipping on doors and doorframe	21	No	No	N/A	N/A	No	
492	6110	1	2	S217	Stairs	Stairwell Next to Main Office	Ceiling	Chipping, Flaking, Efflorescence	44	Yes	No	N/A	N/A	No	
493	6110	1	2	S217	Stairs	Stairwell Next to Main Office	Floor	Chipping on railings	80	No	No	N/A	N/A	No	
494	6110	1	2	S217	Stairs	Stairwell Next to Main Office	W1	Flaking on wall and windowframes	7	No	No	N/A	N/A	No	
495	6110	1	2	S217	Stairs	Stairwell Next to Main Office	W2	Cracking, Flaking	70	No	No	N/A	N/A	No	
496	6110	1	2	S217	Stairs	Stairwell Next to Main Office	W3	Hole	1	No	No	N/A	N/A	Yes	
497	6110	1	2	S217	Stairs	Stairwell Next to Main Office	W4	Cracking, Chipping, Flaking	86	No	No	N/A	N/A	Yes	
498	6110	1	2	224	Storage	Storage across from Classroom 218	Floor	Debris	N/A	No	Debris scattered throughout	200	N/A	No	
499	6110	1	2	224	Storage	Storage across from Classroom 218	W1	Cracking, Significant Moisture Damage	43	Yes	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
500	6110	1	2	224	Storage	Storage across from Classroom 218	W2	Significant Moisture Damage	10	Yes	No	N/A	Stored Materials	Yes	
501	6110	1	2	224	Storage	Storage across from Classroom 218	W3	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
502	6110	1	2	224	Storage	Storage across from Classroom 218	W4	Cracking, Gouges	9	No	No	N/A	Stored Materials	Yes	
503	6110	1	2	223	Storage	Storage across from Classroom 219	Ceiling	No Access							This space will need to be inspected
504	6110	1	2	223	Storage	Storage across from Classroom 219	Floor	No Access							This space will need to be inspected
505	6110	1	2	223	Storage	Storage across from Classroom 219	W1	No Access							This space will need to be inspected
506	6110	1	2	223	Storage	Storage across from Classroom 219	W2	No Access							This space will need to be inspected
507	6110	1	2	223	Storage	Storage across from Classroom 219	W3	No Access							This space will need to be inspected
508	6110	1	2	223	Storage	Storage across from Classroom 219	W4	No Access							This space will need to be inspected
509	6110	1	2	209	Teacher Lounge/Dining	Teacher's Lounge 209	W1	Cracking	30	No	No	N/A	N/A	Yes	
510	6110	1	2	209	Teacher Lounge/Dining	Teacher's Lounge 209	W3	Chipping	3	No	No	N/A	N/A	No	
511	6110	1	2	209	Teacher Lounge/Dining	Teacher's Lounge 209	W4	Cracking, Flaking behind radiator, Efflorescence	46	Yes	No	N/A	N/A	Yes	
512	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	Ceiling	No Access							This space will need to be inspected
513	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	Floor	No Access							This space will need to be inspected
514	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	W1	No Access							This space will need to be inspected
515	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	W2	No Access							This space will need to be inspected
516	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	W3	No Access							This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
517	6110	1	2	209C		Teacher's Lounge 209 Telecommunication Equipment Room	W4	No Access							This space will need to be inspected
518	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	Ceiling	Limited Inspection		No	No		Furniture, Stored Materials	No	Limited inspection due to stored materials
519	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	Floor	Limited Inspection		No	Debris in corner of walls 3&4		Furniture, Stored Materials	No	Limited inspection due to stored materials
520	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	W1	Hole	1	No	No	N/A	Furniture, Stored Materials	Yes	Limited inspection due to stored materials
521	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	W2	Efflorescence	4	Yes	No	N/A	Furniture, Stored Materials	Yes	Limited inspection due to stored materials
522	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	W3	Hole, Flaking on metal pipe, Efflorescence	15	Yes	No	N/A	Furniture, Stored Materials	Yes	Limited inspection due to stored materials
523	6110	1	2	206A	Administrative Office	Vice Principal's Office 206A	W4	Cracking, Chipping, Efflorescence	22	Yes	No	N/A	Furniture, Stored Materials	Yes	Limited inspection due to stored materials
524	6110	1	2	215B	Restrooms, Staff - Female	Women's Restroom next to Classroom 214	Ceiling	Flaking, Efflorescence	45	Yes	No	N/A	N/A	Yes	
525	6110	1	2	215B	Restrooms, Staff - Female	Women's Restroom next to Classroom 214	W1	Flaking	17	No	No	N/A	N/A	No	
526	6110	1	2	215B	Restrooms, Staff - Female	Women's Restroom next to Classroom 214	W2	Flaking on metal pipes and radiator, Efflorescence	10	Yes	No	N/A	N/A	Yes	
527	6110	1	2	215B	Restrooms, Staff - Female	Women's Restroom next to Classroom 214	W3	Flaking	10	No	No	N/A	N/A	No	
528	6110	1	2	215B	Restrooms, Staff - Female	Women's Restroom next to Classroom 214	W4	Flaking	1	No	No	N/A	N/A	No	
529	6110	1	1	H110		1st Floor Marble Hallway	W1	Cracking	4	No	No	N/A	N/A	No	
530	6110	1	1	H110		1st Floor Marble Hallway	W4	Cracking	3	No	No	N/A	N/A	No	
531	6110	1	1	S12		1st Floor Stairwell 1	Floor	Chipping	4	No	No	N/A	N/A	No	
532	6110	1	1	S12		1st Floor Stairwell 1	W1	Cracking	2	No	No	N/A	N/A	No	
533	6110	1	1	S12		1st Floor Stairwell 1	W3	Cracking	3	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
534	6110	1	1	S12		1st Floor Stairwell 1	W4	Chipping on doors and doorframe	38	No	No	N/A	N/A	No	
535	6110	1	1	S12A		1st Floor Stairwell 1 Closet	Ceiling	No Access							This space will need to be inspected
536	6110	1	1	S12A		1st Floor Stairwell 1 Closet	Floor	No Access							This space will need to be inspected
537	6110	1	1	S12A		1st Floor Stairwell 1 Closet	W1	No Access							This space will need to be inspected
538	6110	1	1	S12A		1st Floor Stairwell 1 Closet	W2	No Access							This space will need to be inspected
539	6110	1	1	S12A		1st Floor Stairwell 1 Closet	W3	No Access							This space will need to be inspected
540	6110	1	1	S12A		1st Floor Stairwell 1 Closet	W4	No Access							This space will need to be inspected
541	6110	1	1	117	Auditorium	Auditorium	Ceiling	Cracking, Flaking	350	No	No	N/A	N/A	No	Ceiling is assumed ACM
542	6110	1	1	117	Auditorium	Auditorium	W1	Cracking, Holes	22	No	No	N/A	N/A	Yes	
543	6110	1	1	117	Auditorium	Auditorium	W2	Flaking, Efflorescence	175	Yes	No	N/A	N/A	Yes	
544	6110	1	1	117	Auditorium	Auditorium	W3	Flaking	30	No	No	N/A	N/A	No	
545	6110	1	1	117	Auditorium	Auditorium	W4	Flaking on wall and doors	227	No	No	N/A	N/A	No	
546	6110	1	1	117C		Auditorium Stage	Ceiling	Flaking	330	No	No	N/A	N/A	No	
547	6110	1	1	117C		Auditorium Stage	W1	Flaking	15	No	No	N/A	N/A	No	
548	6110	1	1	117C		Auditorium Stage	W2	Flaking	75	No	No	N/A	N/A	No	
549	6110	1	1	117C		Auditorium Stage	W3	Holes, Flaking	102	No	No	N/A	N/A	Yes	
550	6110	1	1	117C		Auditorium Stage	W4	Chipping, Flaking	27	No	No	N/A	N/A	No	
551	6110	2	1	001A	Gymnasium - Intermediate Middle	Boy's Gymnasium	Ceiling	Chipping on metal ducts, Flaking on ceiling, metal pipe, and metal ducts, Efflorescence	83	Yes	No	N/A	N/A	No	
552	6110	2	1	001A	Gymnasium - Intermediate Middle	Boy's Gymnasium	W1	Cracking, Chipping on wall, doorframe, and windowframe, Holes	111	No	No	N/A	N/A	No	Repair to concrete block needed
553	6110	2	1	001A	Gymnasium - Intermediate Middle	Boy's Gymnasium	W2	Chipping	5	No	No	N/A	N/A	No	
554	6110	2	1	001A	Gymnasium - Intermediate Middle	Boy's Gymnasium	W3	Cracking, Chipping on wall, doors, and doorframe, Efflorescence	225	No	Debris	2	N/A	No	Repair to concrete block and caulk needed
555	6110	2	1	001A	Gymnasium - Intermediate Middle	Boy's Gymnasium	W4	Cracking, Chipping, Holes	129	No	No	N/A	N/A	No	Repair to concrete block and caulk needed
556	6110	2	1	012A		Boy's Gymnasium Equipment Storage	Ceiling	Significant Moisture Damage	1	No	No	N/A	Stored Equipment	No	
557	6110	2	1	012A		Boy's Gymnasium Equipment Storage	Floor	Limited Inspection		No	No		Stored Equipment	No	Limited Inspection due to stored materials
558	6110	2	1	012A		Boy's Gymnasium Equipment Storage	W1	Chipping on doorframe, Flaking	21	No	No	N/A	Stored Equipment	No	
559	6110	2	1	012A		Boy's Gymnasium Equipment Storage	W2	Holes	5	No	No	N/A	Stored Equipment	No	Repair to concrete block needed
560	6110	2	1	012A		Boy's Gymnasium Equipment Storage	W3	Holes	3	No	No	N/A	Stored Equipment	No	Repair to concrete block needed

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
561	6110	2	1	012A		Boy's Gymnasium Equipment Storage	W4	Hole	1	No	No	N/A	Stored Equipment	No	Repair to concrete block needed
562	6110	2	1	011A	Lockers - Male	Boy's Gymnasium Locker Room	Ceiling	Significant Moisture Damage	1	No	No	N/A	N/A	No	
563	6110	2	1	011A	Lockers - Male	Boy's Gymnasium Locker Room	W1	Cracking, Chipping on wall and lockers	20	No	No	N/A	N/A	No	Repair to concrete block needed
564	6110	2	1	011A	Lockers - Male	Boy's Gymnasium Locker Room	W2	Cracking, Chipping on wall and lockers	43	No	No	N/A	N/A	No	Repair to concrete block needed
565	6110	2	1	011A	Lockers - Male	Boy's Gymnasium Locker Room	W3	Chipping on lockers, Flaking	23	No	No	N/A	N/A	No	
566	6110	2	1	011A	Lockers - Male	Boy's Gymnasium Locker Room	W4	Cracking, Chipping on doors, doorframes, and lockers	64	No	No	N/A	N/A	No	Repair to concrete block needed
567	6110	2	1	011B		Boy's Gymnasium Locker Room Restroom	Ceiling	Chipping, Flaking, Mold	11	No	No	N/A	N/A	No	
568	6110	2	1	011B		Boy's Gymnasium Locker Room Restroom	W4	Flaking	14	No	No	N/A	N/A	No	
569	6110	2	1	010A	Administrative Office	Boy's Gymnasium Office	W1	Chipping on doorframe and windowframe	23	No	No	N/A	Desk	No	
570	6110	2	1	010A	Administrative Office	Boy's Gymnasium Office	W2	Limited Inspection		No	No		Shelf	No	Limited Inspection due to stored materials
571	6110	2	1	010A	Administrative Office	Boy's Gymnasium Office	W3	Limited Inspection		No	No		Cabinets	No	Limited inspection due to stored materials
572	6110	2	1	010A	Administrative Office	Boy's Gymnasium Office	W4	Chipping	5	No	No	N/A	Table, Chairs	No	
573	6110	2	1	010B		Boy's Gymnasium Office Closet	Ceiling	No Access							This space will need to be inspected
574	6110	2	1	010B		Boy's Gymnasium Office Closet	Floor	No Access							This space will need to be inspected
575	6110	2	1	010B		Boy's Gymnasium Office Closet	W1	No Access							This space will need to be inspected
576	6110	2	1	010B		Boy's Gymnasium Office Closet	W2	No Access							This space will need to be inspected
577	6110	2	1	010B		Boy's Gymnasium Office Closet	W3	No Access							This space will need to be inspected
578	6110	2	1	010B		Boy's Gymnasium Office Closet	W4	No Access							This space will need to be inspected
579	6110	2	1	010C		Boy's Gymnasium Office Restroom	Floor	Debris	N/A	No	Paint chips in shower and toilet	8	N/A	No	
580	6110	2	1	010C		Boy's Gymnasium Office Restroom	W1	Cracking, Chipping on doorframe, Flaking	21	No	No	N/A	N/A	No	Repair to concrete block needed
581	6110	2	1	010C		Boy's Gymnasium Office Restroom	W2	Cracking, Flaking	23	No	No	N/A	N/A	No	Repair to concrete block needed

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
582	6110	2	1	010C		Boy's Gymnasium Office Restroom	W3	Cracking, Flaking	23	No	No	N/A	N/A	No	Repair to concrete block needed
583	6110	2	1	010C		Boy's Gymnasium Office Restroom	W4	Cracking, Flaking	16	No	No	N/A	N/A	No	Repair to concrete block needed
584	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	Ceiling	Chipping	7	No	No	N/A	N/A	No	
585	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	Floor	Chipping	3	No	No	N/A	N/A	No	
586	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	W1	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	
587	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	W2	Chipping, Efflorescence	14	Yes	No	N/A	N/A	Yes	
588	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	W3	Chipping, Flaking	26	No	No	N/A	N/A	No	
589	6110	1	1	100D	Student Restrooms - Male (4-12)	Boy's Restroom across from Storage Room 101	W4	Chipping	1	No	No	N/A	N/A	No	
590	6110	2	1	011B	Student Restrooms - Male (4-12)	Boy's Restroom near Gymnasium	W1	Chipping on doorframe	3	No	No	N/A	N/A	No	
591	6110	2	1	011B	Student Restrooms - Male (4-12)	Boy's Restroom near Gymnasium	W2	Chipping	1	No	No	N/A	N/A	No	
592	6110	2	1	011B	Student Restrooms - Male (4-12)	Boy's Restroom near Gymnasium	W4	Flaking	4	No	No	N/A	N/A	No	
593	6110	1	1	118	Cafeteria	Cafeteria at Corner of Building near Parking Lot	Ceiling	Flaking, Efflorescence	39	Yes	No	N/A	N/A	Yes	
594	6110	1	1	118	Cafeteria	Cafeteria at Corner of Building near Parking Lot	W1	Chipping on wall and metal jacket	6	No	No	N/A	N/A	No	
595	6110	1	1	118	Cafeteria	Cafeteria at Corner of Building near Parking Lot	W2	Chipping on wall, doors, and doorframes	111	No	No	N/A	N/A	No	
596	6110	1	1	118	Cafeteria	Cafeteria at Corner of Building near Parking Lot	W3	Chipping on wall, doors, doorframe, radiators, metal jackets, and metal pipes	113	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
597	6110	1	1	118	Cafeteria	Cafeteria at Corner of Building near Parking Lot	W4	Chipping on wall and metal pipe, Gouges	26	No	No	N/A	N/A	No	Repair to sheetrock needed
598	6110	1	1	118C		Cafeteria at Corner of Building near Parking Lot Serving Area	W1	Chipping on wall and wood	19	No	No	N/A	N/A	No	
599	6110	1	1	118D		Cafeteria at Corner of Building near Parking Lot Ticket Booth	Ceiling	Flaking	12	No	No	N/A	N/A	No	
600	6110	1	1	118A	Cafeteria	Cafeteria closest to Washington Lane	Ceiling	Significant Moisture Damage above missing ceiling tiles	9	Yes	No	N/A	N/A	Yes	
601	6110	1	1	118A	Cafeteria	Cafeteria closest to Washington Lane	W1	Chipping	14	No	No	N/A	N/A	No	
602	6110	1	1	118A	Cafeteria	Cafeteria closest to Washington Lane	W2	Chipping, Flaking	58	No	No	N/A	N/A	No	
603	6110	1	1	118A	Cafeteria	Cafeteria closest to Washington Lane	W3	Chipping on doors, doorframes, metal jackets, and radiators, Flaking on wall, doors, doorframes, and metal pipes	123	No	No	N/A	N/A	No	
604	6110	1	1	118A	Cafeteria	Cafeteria closest to Washington Lane	W4	Chipping	6	No	No	N/A	N/A	No	
605	6110	1	1	119		Cafeteria closest to Washington Lane Serving Area	W1	Chipping on wall and windowsill	12	No	No	N/A	N/A	No	
606	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	Ceiling	No Access							This space will need to be inspected
607	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	Floor	No Access							This space will need to be inspected
608	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	W1	No Access							This space will need to be inspected
609	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	W2	No Access							This space will need to be inspected
610	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	W3	No Access							This space will need to be inspected
611	6110	1	1	118B		Cafeteria closest to Washington Lane Ticket Booth	W4	No Access							This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
612	6110	1	1	100C	Primary	Classroom 102	Floor	Chipping along walls 3&4	20	No	No	N/A	N/A	No	
613	6110	1	1	100C	Primary	Classroom 102	W1	Chipping on phone box	1	No	No	N/A	N/A	No	
614	6110	1	1	100C	Primary	Classroom 102	W2	Chipping	3	No	No	N/A	N/A	No	
615	6110	1	1	100C	Primary	Classroom 102	W3	Flaking on and behind radiator, Efflorescence	40	Yes	No	N/A	N/A	No	
616	6110	1	1	103	Primary	Classroom 103	Ceiling	Flaking	2	No	No	N/A	N/A	No	
617	6110	1	1	103	Primary	Classroom 103	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	
618	6110	1	1	104	Primary	Classroom 104	Ceiling	Flaking above windows, Efflorescence above windows	21	Yes	No	N/A	N/A	Yes	
619	6110	1	1	104	Primary	Classroom 104	Floor	Chipping along wall 3	12	No	Debris along wall 3	5	N/A	No	
620	6110	1	1	104	Primary	Classroom 104	W4	Chipping on metal jackets	6	No	No	N/A	N/A	No	
621	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	Ceiling	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
622	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	Floor	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
623	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	W1	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
624	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	W2	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
625	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	W3	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
626	6110	1	1	104BB	Storage	Classroom 104 Closet near Hallway Wall	W4	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited inspection due to stored materials
627	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	Ceiling	Cracking	5	No	No	N/A	Stored Materials	No	
628	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	Floor	Chipping	1	No	No	N/A	Stored Materials	No	
629	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	W1	Cracking	15	No	No	N/A	Stored Materials	No	
630	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	W2	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
631	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	W3	Cracking, Flaking on metal pipe	25	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
632	6110	1	1	104B	Storage	Classroom 104 Left Hand Closet near Windows	W4	Cracking	5	No	No	N/A	Stored Materials	No	
633	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	Ceiling	Flaking, Efflorescence	7	Yes	No	N/A	Shelves, Stored Materials	Yes	Damage has been repaired but is returning
634	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	Floor	Limited Inspection		No	Debris along wall 2		Shelves, Stored Materials	No	Limited Inspection due to stored materials
635	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	W1	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
636	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	W2	Flaking	15	No	No	N/A	Shelves, Stored Materials	No	
637	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	W3	Flaking on wall and metal pipe, Efflorescence	50	Yes	No	N/A	Shelves, Stored Materials	Yes	
638	6110	1	1	104BA	Storage	Classroom 104 Right Hand Closet near Windows	W4	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
639	6110	1	1	105	Primary	Classroom 105	W1	Chipping on wall and cove, Flaking	12	No	No	N/A	Posters	No	
640	6110	1	1	105	Primary	Classroom 105	W2	Flaking, Efflorescence	21	Yes	No	N/A	Posters, Shelves, Stored Materials	Yes	
641	6110	1	1	105	Primary	Classroom 105	W3	Flaking behind radiator, Efflorescence	12	Yes	Debris on windowsills	2	N/A	Yes	
642	6110	1	1	105	Primary	Classroom 105	W4	Chipping on cove	4	No	No	N/A	Posters	No	
643	6110	1	1	105A		Classroom 105 Coat Closet	Ceiling	Cracking	10	No	No	N/A	N/A	No	
644	6110	1	1	105A		Classroom 105 Coat Closet	Floor	Chipping	6	No	No	N/A	N/A	No	
645	6110	1	1	105A		Classroom 105 Coat Closet	W3	Flaking on metal pipes	4	No	No	N/A	Shelves, Stored Materials	No	
646	6110	1	1	105A		Classroom 105 Coat Closet	W4	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
647	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	Ceiling	Cracking, Flaking	7	No	No	N/A	Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
648	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
649	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	W1	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
650	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	W2	Chipping on radiator, Flaking on wall, behind radiator, and on metal pipe	50	No	No	N/A	Stored Materials	No	
651	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	W3	Cracking, Flaking on wall and metal pipes, Efflorescence	53	Yes	No	N/A	Stored Materials	Yes	
652	6110	1	1	105B		Classroom 105 Coat Closet Storage Closet	W4	Cracking, Flaking on wall and metal pipes, Efflorescence	56	Yes	No	N/A	Stored Materials	Yes	
653	6110	1	1	106A	Primary	Classroom 107	Floor	Debris	N/A	No	Debris behind radiator	5	N/A	No	
654	6110	1	1	106A	Primary	Classroom 107	W1	Cracking, Chipping, Gouge	10	No	No	N/A	N/A	Yes	
655	6110	1	1	106A	Primary	Classroom 107	W2	Flaking, Spalling, Efflorescence	21	Yes	No	N/A	N/A	Yes	
656	6110	1	1	106A	Primary	Classroom 107	W3	Chipping on radiators, Flaking on wall and windowframe, Efflorescence	49	Yes	Debris on windowsills	10	N/A	Yes	
657	6110	1	1	106A	Primary	Classroom 107	W4	Cracking	5	No	No	N/A	N/A	No	
658	6110	1	1	106B		Classroom 107 Closet	W1	Flaking	1	No	No	N/A	N/A	No	
659	6110	1	1	106B		Classroom 107 Closet	W2	Flaking	6	No	No	N/A	N/A	No	
660	6110	1	1	106B		Classroom 107 Closet	W4	Cracking	10	No	No	N/A	N/A	No	
661	6110	1	1	108	Primary	Classroom 108	W1	Chipping, Flaking	14	No	No	N/A	Posters, Stored Materials	No	
662	6110	1	1	108	Primary	Classroom 108	W2	Cracking	10	No	No	N/A	N/A	No	
663	6110	1	1	108	Primary	Classroom 108	W3	Cracking, Flaking on metal pipe	12	No	No	N/A	N/A	No	
664	6110	1	1	108	Primary	Classroom 108	W4	Chipping	6	No	No	N/A	Posters	No	
665	6110	1	1	108A		Classroom 108 Closet	Ceiling	Cracking	10	No	No	N/A	Stored Materials	No	
666	6110	1	1	108A		Classroom 108 Closet	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
667	6110	1	1	108A		Classroom 108 Closet	W1	Cracking, Flaking	45	No	No	N/A	Stored Materials	No	
668	6110	1	1	108A		Classroom 108 Closet	W2	Cracking, Flaking	30	No	No	N/A	Stored Materials	No	
669	6110	1	1	108A		Classroom 108 Closet	W3	Cracking, Gouges, Flaking	80	No	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
670	6110	1	1	108A		Classroom 108 Closet	W4	Flaking	10	No	No	N/A	Stored Materials	No	
671	6110	1	1	109	Primary	Classroom 109	W1	Flaking on wall and in air shaft	9	No	No	N/A	Posters	No	
672	6110	1	1	109	Primary	Classroom 109	W2	Limited Inspection		No	No		Furniture, Posters	No	Limited inspection due to stored materials
673	6110	1	1	109	Primary	Classroom 109	W3	Chipping, Flaking on wall, windowframe, and behind radiator, Significant Moisture Damage	30	Yes	No	N/A	Furniture, Stored Materials	No	
674	6110	1	1	109	Primary	Classroom 109	W4	Flaking	1	No	No	N/A	Cabinets, Stored Materials	No	
675	6110	1	1	110	Primary	Classroom 110	W1	Chipping, Staple Holes	46	No	No	N/A	Furniture	Yes	
676	6110	1	1	110	Primary	Classroom 110	W2	Staple Holes	3	No	No	N/A	Furniture	Yes	
677	6110	1	1	110	Primary	Classroom 110	W3	Cracking, Hole, Flaking on wall and behind radiators	51	No	No	N/A	Furniture, Stored Materials	Yes	
678	6110	1	1	110	Primary	Classroom 110	W4	Holes	6	No	No	N/A	Stored Materials	Yes	
679	6110	1	1	112	Student Restrooms - Male/Female	Classroom 110 Restroom	Ceiling	Flaking above windows	12	No	No	N/A	N/A	No	
680	6110	1	1	112	Student Restrooms - Male/Female	Classroom 110 Restroom	Floor	Chipping on center sheetrock, Holes in center sheetrock	7	No	No	N/A	N/A	No	Repair to sheetrock needed
681	6110	1	1	197	Primary	Classroom across from Cafeteria closest to Washington Lane	Ceiling	Flaking above missing ceiling tiles	88	No	No	N/A	N/A	N/A	
682	6110	1	1	197	Primary	Classroom across from Cafeteria closest to Washington Lane	W1	Chipping	6	No	No	N/A	N/A	N/A	
683	6110	1	1	197	Primary	Classroom across from Cafeteria closest to Washington Lane	W4	Chipping	5	No	No	N/A	N/A	N/A	
684	6110	1	1	100A	Primary	Classroom across from Classroom 101	Ceiling	No Access							This space will need to be inspected
685	6110	1	1	100A	Primary	Classroom across from Classroom 101	Floor	No Access							This space will need to be inspected
686	6110	1	1	100A	Primary	Classroom across from Classroom 101	W1	No Access							This space will need to be inspected
687	6110	1	1	100A	Primary	Classroom across from Classroom 101	W2	No Access							This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
688	6110	1	1	100A	Primary	Classroom across from Classroom 101	W3	No Access							This space will need to be inspected
689	6110	1	1	100A	Primary	Classroom across from Classroom 101	W4	No Access							This space will need to be inspected
690	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	Ceiling	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
691	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
692	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	W1	Flaking, Significant Moisture Damage	12	No	No	N/A	Stored Materials	No	Repair to sheetrock needed
693	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	W2	Flaking	62	No	No	N/A	Stored Materials	No	
694	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	W3	Flaking	10	No	No	N/A	Stored Materials	No	
695	6110	2	1	11A	Primary	Classroom near Right side of Gymnasium	W4	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
696	6110	1	1	107	Primary	Classroom to Right of Classroom 107	Floor	Flaking	5	No	Paint chips and debris scattered along edges	20	N/A	No	
697	6110	1	1	107	Primary	Classroom to Right of Classroom 107	W1	Cracking, Chipping on wall, door, and doorframe	61	No	No	N/A	Shelf, Posters	Yes	
698	6110	1	1	107	Primary	Classroom to Right of Classroom 107	W2	Chipping on radiator, Flaking behind radiator, Efflorescence	60	Yes	No	N/A	Furniture	Yes	
699	6110	1	1	107	Primary	Classroom to Right of Classroom 107	W3	Flaking behind radiator, Efflorescence	30	Yes	No	N/A	Cabinets, Furniture	Yes	
700	6110	1	1	107	Primary	Classroom to Right of Classroom 107	W4	Efflorescence	1	Yes	No	N/A	Stored Materials	Yes	
701	6110	1	1	106	Primary	Classroom/Office 106	W1	Limited Inspection		No	No		Posters	No	Limited Inspection due to stored materials
702	6110	1	1	106	Primary	Classroom/Office 106	W2	Cracking, Chipping	8	No	No	N/A	Posters	Yes	
703	6110	1	1	106	Primary	Classroom/Office 106	W3	Chipping on wall and radiators, Holes, Flaking behind radiator, Efflorescence	37	Yes	Debris on windowsills	5	N/A	Yes	
704	6110	1	1	106	Primary	Classroom/Office 106	W4	Cracking, Flaking	22	No	No	N/A	Posters	No	
705	6110	1	1	106C		Classroom/Office 106 Closet	Ceiling	Cracking, Holes, Flaking on wall and metal pipe	13	No	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
706	6110	1	1	106C		Classroom/Office 106 Closet	Floor	Limited Inspection		No	Paint chips along wall 2		Stored Materials	No	Limited Inspection due to stored materials
707	6110	1	1	106C		Classroom/Office 106 Closet	W1	Cracking, Holes	14	No	No	N/A	Stored Materials	Yes	
708	6110	1	1	106C		Classroom/Office 106 Closet	W2	Cracking, Chipping, Flaking	32	No	No	N/A	Stored Materials	No	
709	6110	1	1	106C		Classroom/Office 106 Closet	W3	Flaking	3	No	No	N/A	Stored Materials	No	
710	6110	1	1	106C		Classroom/Office 106 Closet	W4	Cracking, Chipping, Flaking on wall and conduit lines	44	No	No	N/A	Stored Materials	Yes	
711	6110	1	1	100F		Closet across from Storage Room 100	Ceiling	No Access							This space will need to be inspected
712	6110	1	1	100F		Closet across from Storage Room 100	Floor	No Access							This space will need to be inspected
713	6110	1	1	100F		Closet across from Storage Room 100	W1	No Access							This space will need to be inspected
714	6110	1	1	100F		Closet across from Storage Room 100	W2	No Access							This space will need to be inspected
715	6110	1	1	100F		Closet across from Storage Room 100	W3	No Access							This space will need to be inspected
716	6110	1	1	100F		Closet across from Storage Room 100	W4	No Access							This space will need to be inspected
717	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	Ceiling	Significant Moisture Damage	10	Yes	No	N/A	N/A	Yes	
718	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	Floor	Debris	N/A	No	Debris throughout	20	N/A	No	
719	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	W1	Flaking	4	No	No	N/A	N/A	No	
720	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	W2	Significant Moisture Damage	50	Yes	No	N/A	N/A	Yes	
721	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	W3	Significant Moisture Damage	25	Yes	No	N/A	N/A	Yes	
722	6110	1	1	110C	Primary	Closet between Stairwell 1 and Custodial Closet	W4	Flaking	24	No	No	N/A	N/A	No	
723	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	Ceiling	Flaking on fiberglass pipe insulation, Hole, Efflorescence	8	Yes	No	N/A	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
724	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	Floor	Floor sinking	N/A	No	No	N/A	Stored Materials	No	
725	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	W1	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
726	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	W2	Cracking, Flaking on metal pipes	46	No	No	N/A	Stored Materials	Yes	
727	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	W3	Flaking on metal pipes, Efflorescence	44	Yes	No	N/A	Stored Materials	Yes	
728	6110	1	1	104B1	Storage	Closet inside the Classroom 104 Left Hand Closet near Windows	W4	Cracking, Flaking on metal pipes, Efflorescence	30	Yes	No	N/A	Stored Materials	Yes	
729	6110	2	1	S21		Element 2 Stairwell	Ceiling	Flaking	18	No	No	N/A	N/A	No	
730	6110	2	1	S21		Element 2 Stairwell	W1	Cracking, Chipping on doorframe	16	No	No	N/A	N/A	No	Repair to concrete block needed
731	6110	2	1	S21		Element 2 Stairwell	W2	Cracking, Holes, Flaking	35	No	No	N/A	N/A	No	Repair to concrete block and caulk needed
732	6110	2	1	S21		Element 2 Stairwell	W3	Cracking	3	No	No	N/A	N/A	No	
733	6110	2	1	S21		Element 2 Stairwell	W4	Cracking, Chipping on railing, Hole	52	No	No	N/A	N/A	No	Repair to concrete block and caulk needed
734	6110	1	1	113F		Former Locker Room across from Cafeteria	Ceiling	Flaking on ceiling and ACM pipe insulation	93	No	No	N/A	N/A	No	
735	6110	1	1	113F		Former Locker Room across from Cafeteria	Floor	Debris	N/A	No	Paint chips scattered throughout	15	N/A	No	
736	6110	1	1	113F		Former Locker Room across from Cafeteria	W1	Chipping on metal pipe, Flaking on wall and radiator, Efflorescence	32	Yes	No	N/A	Stored Materials	No	
737	6110	1	1	113F		Former Locker Room across from Cafeteria	W2	Flaking on radiator and metal pipe	15	No	No	N/A	N/A	No	
738	6110	1	1	113F		Former Locker Room across from Cafeteria	W4	Flaking	8	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
739	6110	1	1	113G		Former Locker Room across from Cafeteria Restroom	Ceiling	Holes in ACM pipe insulation, Flaking on ACM pipe insulation	5	No	No	N/A	N/A	No	
740	6110	2	1	22A	Gymnasium - Intermediate Middle	Girl's Gymnasium	Ceiling	Flaking on ceiling and metal ducts, Efflorescence	141	Yes	No	N/A	N/A	No	
741	6110	2	1	22A	Gymnasium - Intermediate Middle	Girl's Gymnasium	W1	Cracking, Chipping on wall, doorframe, and windowframe, Holes, Flaking on fiberglass pipe insulation	147	No	No	N/A	N/A	No	Repair to concrete block and caulk needed
742	6110	2	1	22A	Gymnasium - Intermediate Middle	Girl's Gymnasium	W2	Cracking, Chipping, Flaking	413	No	Paint chips	5	N/A	No	Repair to concrete block and caulk needed
743	6110	2	1	22A	Gymnasium - Intermediate Middle	Girl's Gymnasium	W3	Cracking, Chipping on wall, doors, and doorframe, Flaking	267	No	No	N/A	N/A	No	Repair to caulk needed
744	6110	2	1	22A	Gymnasium - Intermediate Middle	Girl's Gymnasium	W4	Holes	11	No	No	N/A	N/A	No	Repair to concrete block needed
745	6110	2	1	003A		Girl's Gymnasium Equipment Storage	Ceiling	No Access							This space will need to be inspected
746	6110	2	1	003A		Girl's Gymnasium Equipment Storage	Floor	No Access							This space will need to be inspected
747	6110	2	1	003A		Girl's Gymnasium Equipment Storage	W1	No Access							This space will need to be inspected
748	6110	2	1	003A		Girl's Gymnasium Equipment Storage	W2	No Access							This space will need to be inspected
749	6110	2	1	003A		Girl's Gymnasium Equipment Storage	W3	No Access							This space will need to be inspected
750	6110	2	1	003A		Girl's Gymnasium Equipment Storage	W4	No Access							This space will need to be inspected
751	6110	2	1	004A	Lockers - Female	Girl's Gymnasium Locker Room	Ceiling	Chipping, Gouges	10	No	No	N/A	N/A	Yes	
752	6110	2	1	004A	Lockers - Female	Girl's Gymnasium Locker Room	W1	Chipping on wall, doorframe, and lockers	19	No	No	N/A	N/A	No	
753	6110	2	1	004A	Lockers - Female	Girl's Gymnasium Locker Room	W2	Cracking, Chipping on lockers	33	No	No	N/A	N/A	No	Repair to concrete block needed
754	6110	2	1	004A	Lockers - Female	Girl's Gymnasium Locker Room	W3	Cracking, Chipping on lockers	17	No	No	N/A	N/A	No	Repair to concrete block needed
755	6110	2	1	004A	Lockers - Female	Girl's Gymnasium Locker Room	W4	Cracking, Chipping on wall and lockers	45	No	No	N/A	N/A	No	Repair to concrete block needed
756	6110	2	1	004C		Girl's Gymnasium Locker Room Restroom	Ceiling	Cracking	4	No	No	N/A	N/A	Yes	
757	6110	2	1	004C		Girl's Gymnasium Locker Room Restroom	W1	Chipping	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
758	6110	2	1	004C		Girl's Gymnasium Locker Room Restroom	W2	Flaking	18	No	No	N/A	N/A	No	
759	6110	2	1	005A	Administrative Office	Girl's Gymnasium Office	W1	Chipping on doorframe and windowframe	35	No	No	N/A	N/A	No	
760	6110	2	1	005A	Administrative Office	Girl's Gymnasium Office	W3	Cracking, Chipping	7	No	No	N/A	N/A	No	Repair to concrete block needed
761	6110	2	1	005B		Girl's Gymnasium Office Closet	Ceiling	No Access							This space will need to be inspected
762	6110	2	1	005B		Girl's Gymnasium Office Closet	Floor	No Access							This space will need to be inspected
763	6110	2	1	005B		Girl's Gymnasium Office Closet	W1	No Access							This space will need to be inspected
764	6110	2	1	005B		Girl's Gymnasium Office Closet	W2	No Access							This space will need to be inspected
765	6110	2	1	005B		Girl's Gymnasium Office Closet	W3	No Access							This space will need to be inspected
766	6110	2	1	005B		Girl's Gymnasium Office Closet	W4	No Access							This space will need to be inspected
767	6110	2	1	005C		Girl's Gymnasium Office Restroom	Ceiling	Flaking	7	No	No	N/A	N/A	No	
768	6110	2	1	005C		Girl's Gymnasium Office Restroom	Floor	Debris	N/A	No	Paint chips scattered along edges	11	N/A	No	
769	6110	2	1	005C		Girl's Gymnasium Office Restroom	W1	Cracking, Chipping on wall and doorframe, Flaking	19	No	No	N/A	N/A	No	Repair to concrete block needed
770	6110	2	1	005C		Girl's Gymnasium Office Restroom	W2	Cracking, Flaking	12	No	No	N/A	N/A	No	Repair to concrete block needed
771	6110	2	1	005C		Girl's Gymnasium Office Restroom	W3	Flaking	30	No	No	N/A	N/A	No	
772	6110	2	1	005C		Girl's Gymnasium Office Restroom	W4	Cracking, Flaking	18	No	No	N/A	N/A	No	Repair to concrete block needed
773	6110	2	1	005E	Student Restrooms - Female (4-12)	Girl's Restroom near Gymnasium	W1	Chipping on wall and door	3	No	No	N/A	N/A	No	
774	6110	2	1	005E	Student Restrooms - Female (4-12)	Girl's Restroom near Gymnasium	W2	Flaking	3	No	No	N/A	N/A	No	
775	6110	2	1	005E	Student Restrooms - Female (4-12)	Girl's Restroom near Gymnasium	W4	Chipping, Flaking	7	No	No	N/A	N/A	No	
776	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	Ceiling	Cracking, Efflorescence	23	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
777	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	Floor	Chipping on floor and partition near entrance	21	No	No	N/A	N/A	No	
778	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	W1	Flaking	6	No	No	N/A	N/A	No	
779	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	W2	Cracking, Flaking on metal pipe	22	No	No	N/A	N/A	No	
780	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	W3	Flaking	1	No	No	N/A	N/A	No	
781	6110	1	1	110A	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 109	W4	Flaking, Spalling	13	Yes	No	N/A	N/A	Yes	
782	6110	1	1	H16	Circulation (Hallway)	Hallway Corridor at IMC side of Auditorium	Ceiling	Cracking, Flaking, Efflorescence	25	Yes	No	N/A	N/A	Yes	
783	6110	1	1	H16	Circulation (Hallway)	Hallway Corridor at IMC side of Auditorium	Floor	Debris	N/A	No	Debris on floor and chair rail	5	N/A	No	
784	6110	1	1	H16	Circulation (Hallway)	Hallway Corridor at IMC side of Auditorium	W2	Cracking, Flaking	55	No	No	N/A	N/A	No	
785	6110	1	1	H16	Circulation (Hallway)	Hallway Corridor at IMC side of Auditorium	W3	Flaking on doors, Spalling, Efflorescence	18	Yes	No	N/A	N/A	Yes	
786	6110	1	1	H16	Circulation (Hallway)	Hallway Corridor at IMC side of Auditorium	W4	Cracking, Flaking on wood, Efflorescence	231	Yes	No	N/A	N/A	Yes	
787	6110	1	1	H16A	Circulation (Hallway)	Hallway Corridor at Left side of Auditorium	Ceiling	Cracking, Flaking, Efflorescence	79	Yes	No	N/A	N/A	Yes	
788	6110	1	1	H16A	Circulation (Hallway)	Hallway Corridor at Left side of Auditorium	W1	Cracking, Chipping	4	No	No	N/A	N/A	No	
789	6110	1	1	H16A	Circulation (Hallway)	Hallway Corridor at Left side of Auditorium	W2	Flaking on wood, Efflorescence	55	Yes	No	N/A	N/A	Yes	
790	6110	1	1	H16A	Circulation (Hallway)	Hallway Corridor at Left side of Auditorium	W3	Flaking on doors	10	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
791	6110	1	1	H16A	Circulation (Hallway)	Hallway Corridor at Left side of Auditorium	W4	Cracking, Flaking	195	No	No	N/A	N/A	No	
792	6110	2	1	H12	Circulation (Hallway)	Hallway from Element 1 to Stairwell	W1	Cracking, Chipping on door, Flaking	9	No	No	N/A	N/A	No	Repair to concrete block needed
793	6110	2	1	H12	Circulation (Hallway)	Hallway from Element 1 to Stairwell	W2	Cracking, Hole, Flaking	18	No	No	N/A	N/A	No	Repair to concrete block and caulk needed
794	6110	2	1	H12	Circulation (Hallway)	Hallway from Element 1 to Stairwell	W3	Cracking, Flaking	17	No	No	N/A	N/A	No	Repair to concrete block needed
795	6110	2	1	H12	Circulation (Hallway)	Hallway from Element 1 to Stairwell	W4	Cracking, Efflorescence	18	Yes	No	N/A	N/A	Yes	Repair to concrete block needed
796	6110	2	1	H13	Circulation (Hallway)	Hallway from Stairwell to Gyms	W1	Chipping	1	No	No	N/A	N/A	No	
797	6110	2	1	H13	Circulation (Hallway)	Hallway from Stairwell to Gyms	W2	Chipping	13	No	No	N/A	N/A	No	
798	6110	2	1	H13	Circulation (Hallway)	Hallway from Stairwell to Gyms	W4	Chipping	7	No	No	N/A	N/A	No	
799	6110	2	1	H14	Circulation (Hallway)	Hallway from Stairwell to Gyms Entrance Vestibule	W1	Flaking	4	No	No	N/A	N/A	No	
800	6110	1	1	H20A	Circulation (Hallway)	Hallway outside Building Engineer's Office	Floor	Chipping	1	No	No	N/A	N/A	No	
801	6110	1	1	H20A	Circulation (Hallway)	Hallway outside Building Engineer's Office	W1	Cracking, Flaking	2	No	No	N/A	N/A	No	
802	6110	1	1	H20A	Circulation (Hallway)	Hallway outside Building Engineer's Office	W2	Chipping on doors and doorframe	12	No	No	N/A	N/A	No	
803	6110	1	1	H20A	Circulation (Hallway)	Hallway outside Building Engineer's Office	W3	Cracking, Gouge	8	No	No	N/A	N/A	Yes	
804	6110	1	1	H20A	Circulation (Hallway)	Hallway outside Building Engineer's Office	W4	Chipping on doors and doorframe	6	No	No	N/A	N/A	No	
805	6110	1	1	H17	Circulation (Hallway)	Hallway outside Cafeteria at Corner of Building near Parking Lot	Floor	Chipping	7	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
806	6110	1	1	H17	Circulation (Hallway)	Hallway outside Cafeteria at Corner of Building near Parking Lot	W1	Chipping on metal pipes, Hole, Flaking on wall and metal pipe	17	No	No	N/A	N/A	No	
807	6110	1	1	H17	Circulation (Hallway)	Hallway outside Cafeteria at Corner of Building near Parking Lot	W2	Gouges	6	No	No	N/A	N/A	No	
808	6110	1	1	H17	Circulation (Hallway)	Hallway outside Cafeteria at Corner of Building near Parking Lot	W3	Cracking, Chipping on metal jackets	18	No	No	N/A	N/A	No	
809	6110	1	1	H17	Circulation (Hallway)	Hallway outside Cafeteria at Corner of Building near Parking Lot	W4	Chipping on doors and doorframe	30	No	No	N/A	N/A	No	
810	6110	1	1	H20	Circulation (Hallway)	Hallway outside Classroom 197	Ceiling	Cracking	80	No	No	N/A	N/A	No	Repair to sheetrock needed
811	6110	1	1	H20	Circulation (Hallway)	Hallway outside Classroom 197	Floor	Chipping	24	No	No	N/A	N/A	No	
812	6110	1	1	H20	Circulation (Hallway)	Hallway outside Classroom 197	W1	Cracking, Chipping on wall, electrical panel, and metal pipes	27	No	No	N/A	N/A	No	
813	6110	1	1	H20	Circulation (Hallway)	Hallway outside Classroom 197	W3	Chipping on wall and ticket booth window, Flaking	8	No	No	N/A	N/A	No	
814	6110	1	1	H20	Circulation (Hallway)	Hallway outside Classroom 197	W4	Chipping on metal jackets	15	No	No	N/A	N/A	No	
815	6110	1	1	H110A	Circulation (Hallway)	Hallway outside Classroom to Right of Classroom 107	Floor	Chipping	3	No	No	N/A	N/A	No	
816	6110	1	1	H110A	Circulation (Hallway)	Hallway outside Classroom to Right of Classroom 107	W1	Cracking, Chipping, Hole	29	No	No	N/A	N/A	Yes	
817	6110	1	1	H110A	Circulation (Hallway)	Hallway outside Classroom to Right of Classroom 107	W2	Chipping on doors and doorframes	35	No	No	N/A	N/A	No	
818	6110	1	1	H110A	Circulation (Hallway)	Hallway outside Classroom to Right of Classroom 107	W3	Cracking	15	No	No	N/A	N/A	No	
819	6110	1	1	H110A	Circulation (Hallway)	Hallway outside Classroom to Right of Classroom 107	W4	Chipping on doors and doorframes	35	No	No	N/A	N/A	No	
820	6110	1	1	H110C	Circulation (Hallway)	Hallway outside Classrooms 103-104	W1	Cracking, Chipping on metal jacket, Flaking	29	No	No	N/A	Art Work	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
821	6110	1	1	H110C	Circulation (Hallway)	Hallway outside Classrooms 103-104	W3	Cracking, Chipping on wall, metal pipes, conduit line, and electrical panel	41	No	No	N/A	N/A	No	
822	6110	1	1	H110C	Circulation (Hallway)	Hallway outside Classrooms 103-104	W4	Cracking, Holes, paint has been stabilized on 1	10	No	No	N/A	N/A	Yes	
823	6110	1	1	H110B	Circulation (Hallway)	Hallway outside Classrooms 105-107	Floor	Chipping	4	No	No	N/A	N/A	No	
824	6110	1	1	H110B	Circulation (Hallway)	Hallway outside Classrooms 105-107	W1	Flaking	14	No	No	N/A	N/A	No	
825	6110	1	1	H110B	Circulation (Hallway)	Hallway outside Classrooms 105-107	W2	Flaking	1	No	No	N/A	N/A	No	
826	6110	1	1	H110B	Circulation (Hallway)	Hallway outside Classrooms 105-107	W3	Chipping on wall, metal pipes, and electrical panel, Flaking	19	No	No	N/A	N/A	No	
827	6110	1	1	H18	Circulation (Hallway)	Hallway outside Classrooms 108-110	Floor	Chipping	16	No	No	N/A	N/A	No	
828	6110	1	1	H18	Circulation (Hallway)	Hallway outside Classrooms 108-110	W2	Chipping, Holes, paint has been stabilized on 1, Flaking	8	No	No	N/A	N/A	Yes	
829	6110	1	1	H18	Circulation (Hallway)	Hallway outside Classrooms 108-110	W4	Cracking, Chipping, Hole, Flaking	27	No	No	N/A	N/A	Yes	
830	6110	1	1	H17B	Circulation (Hallway)	Hallway outside Office to Left of Exit to Parking Lot	Floor	Chipping	1	No	No	N/A	N/A	No	
831	6110	1	1	H17B	Circulation (Hallway)	Hallway outside Office to Left of Exit to Parking Lot	W1	Cracking, Chipping on metal pipe, Flaking	9	No	No	N/A	N/A	No	
832	6110	1	1	H17B	Circulation (Hallway)	Hallway outside Office to Left of Exit to Parking Lot	W3	Cracking, Flaking	16	No	No	N/A	N/A	No	
833	6110	1	1	H17B	Circulation (Hallway)	Hallway outside Office to Left of Exit to Parking Lot	W4	Chipping on doors and doorframe, Flaking, Efflorescence	41	Yes	No	N/A	N/A	Yes	
834	6110	1	1	H19	Circulation (Hallway)	Hallway outside Storage Room 100 to Room B	Floor	Chipping	42	No	No	N/A	N/A	No	
835	6110	1	1	H19	Circulation (Hallway)	Hallway outside Storage Room 100 to Room B	W2	Chipping	2	No	No	N/A	N/A	No	
836	6110	1	1	H19	Circulation (Hallway)	Hallway outside Storage Room 100 to Room B	W4	Cracking, Chipping	12	No	No	N/A	N/A	No	
837	6110	1	1	103B	Circulation (Hallway)	Hallway to Men's Restroom	Floor	Chipping	3	No	No	N/A	N/A	No	
838	6110	1	1	103B	Circulation (Hallway)	Hallway to Men's Restroom	W2	Cracking, Chipping, Flaking	51	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
839	6110	1	1	103B	Circulation (Hallway)	Hallway to Men's Restroom	W4	Cracking, Flaking	20	No	No	N/A	N/A	No	
840	6110	1	1	H20B	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria	Floor	Chipping	20	No	No	N/A	N/A	No	
841	6110	1	1	H20B	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria	W2	Cracking, Chipping	6	No	No	N/A	N/A	No	
842	6110	1	1	H20B	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria	W3	Chipping on doors and doorframe, Flaking on doors, Efflorescence	40	Yes	No	N/A	N/A	Yes	
843	6110	1	1	H20B	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria	W4	Cracking, Flaking	22	No	No	N/A	N/A	No	
844	6110	1	1	H17A	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria at Corner of Building near Parking Lot	Floor	Chipping	6	No	No	N/A	N/A	No	
845	6110	1	1	H17A	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria at Corner of Building near Parking Lot	W2	Chipping on metal pipe	6	No	No	N/A	N/A	No	
846	6110	1	1	H17A	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria at Corner of Building near Parking Lot	W3	Chipping on doors and doorframe	40	No	No	N/A	N/A	No	
847	6110	1	1	H17A	Circulation (Hallway)	Hallway to Rear Entrance adjacent to Cafeteria at Corner of Building near Parking Lot	W4	Cracking, Flaking	42	No	No	N/A	N/A	No	
848	6110	1	1	H110D	Circulation (Hallway)	Hallway to Side Entrance adjacent to Classroom 103	W1	Flaking	29	No	No	N/A	N/A	No	
849	6110	1	1	H110D	Circulation (Hallway)	Hallway to Side Entrance adjacent to Classroom 103	W2	Cracking, Chipping on wall, doors, and doorframe, Flaking on metal pipe, Spalling	30	Yes	No	N/A	N/A	Yes	
850	6110	1	1	H110D	Circulation (Hallway)	Hallway to Side Entrance adjacent to Classroom 103	W3	Cracking, Flaking	24	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
851	6110	1	1	H110D	Circulation (Hallway)	Hallway to Side Entrance adjacent to Classroom 103	W4	Chipping on doors and doorframe	22	No	No	N/A	N/A	No	
852	6110	1	1	113	IMC (Library)	IMC	Ceiling	Chipping	500	Yes	No	N/A	N/A	No	
853	6110	1	1	113	IMC (Library)	IMC	Floor	Debris	N/A	No	Debris scattered around edges	50	N/A	No	
854	6110	1	1	113	IMC (Library)	IMC	W1	Cracking, Chipping, Holes, Flaking on wall and windowframes, Efflorescence	99	Yes	No	N/A	N/A	Yes	Repair to brick needed
855	6110	1	1	113	IMC (Library)	IMC	W2	Cracking, Chipping, Efflorescence	462	Yes	No	N/A	N/A	No	Repair to brick needed
856	6110	1	1	113	IMC (Library)	IMC	W3	Cracking, Efflorescence	25	Yes	No	N/A	N/A	No	Repair to brick needed
857	6110	1	1	113	IMC (Library)	IMC	W4	Flaking, Efflorescence	450	Yes	No	N/A	N/A	No	
858	6110	1	1	113L	Circulation (Hallway)	IMC Hallway to Kitchen	W1	Chipping on doorframe	5	No	No	N/A	N/A	No	
859	6110	1	1	113L	Circulation (Hallway)	IMC Hallway to Kitchen	W2	Chipping on windowframe	3	No	No	N/A	N/A	No	
860	6110	1	1	113L	Circulation (Hallway)	IMC Hallway to Kitchen	W4	Chipping on windowframe	3	No	No	N/A	N/A	No	
861	6110	1	1	113N		IMC Kitchen	Ceiling	Flaking on metal pipe	4	No	No	N/A	N/A	No	
862	6110	1	1	113N		IMC Kitchen	W1	Chipping on doorframe	12	No	No	N/A	N/A	No	
863	6110	1	1	113N		IMC Kitchen	W2	Chipping on doorframe	15	No	No	N/A	N/A	No	
864	6110	1	1	113N		IMC Kitchen	W3	Cracking	1	No	No	N/A	N/A	No	Repair to brick needed
865	6110	1	1	113N		IMC Kitchen	W4	Flaking	11	No	No	N/A	N/A	No	
866	6110	1	1	113I		IMC Left Storage Room	Ceiling	Flaking	14	No	No	N/A	N/A	No	
867	6110	1	1	113I		IMC Left Storage Room	W1	Flaking	65	No	No	N/A	N/A	No	
868	6110	1	1	113I		IMC Left Storage Room	W2	Flaking	50	No	No	N/A	N/A	No	
869	6110	1	1	113I		IMC Left Storage Room	W3	Cracking, Flaking on wall and metal pipe	33	No	No	N/A	N/A	No	Repair to brick needed
870	6110	1	1	113I		IMC Left Storage Room	W4	Flaking	13	No	No	N/A	N/A	No	
871	6110	1	1	113A	Periodical Storage Area	IMC Storage with Elevator	Ceiling	Cracking, Holes	10	No	No	N/A	N/A	No	Repair to concrete needed
872	6110	1	1	113A	Periodical Storage Area	IMC Storage with Elevator	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	
873	6110	1	1	113A	Periodical Storage Area	IMC Storage with Elevator	W2	Flaking, Efflorescence	22	Yes	No	N/A	N/A	No	
874	6110	1	1	113A	Periodical Storage Area	IMC Storage with Elevator	W3	Flaking on wall and metal pipe	5	No	No	N/A	N/A	No	
875	6110	1	1	113A	Periodical Storage Area	IMC Storage with Elevator	W4	Flaking on window frames	5	No	No	N/A	N/A	No	
876	6110	1	1	120	Kitchen	Kitchen	Ceiling	Flaking, Efflorescence	30	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
877	6110	1	1	120	Kitchen	Kitchen	W1	Flaking on metal jackets	14	No	No	N/A	N/A	No	Entrance from 118A side
878	6110	1	1	120	Kitchen	Kitchen	W2	Chipping on metal jackets	4	No	No	N/A	N/A	No	
879	6110	1	1	120C		Kitchen Office	Ceiling	Flaking, Efflorescence	11	Yes	No	N/A	N/A	Yes	
880	6110	1	1	120C		Kitchen Office	W1	Chipping on door, Flaking on wall and metal pipe	10	No	No	N/A	Desk, Cabinet	No	
881	6110	1	1	120C		Kitchen Office	W2	Cracking, Chipping, Hole	7	No	No	N/A	Cabinets	Yes	
882	6110	1	1	120C		Kitchen Office	W3	Hole, Spalling, Flaking	12	Yes	No	N/A	N/A	Yes	
883	6110	1	1	120C		Kitchen Office	W4	Cracking, Chipping, Flaking	20	No	No	N/A	N/A	No	
884	6110	1	1	120A		Kitchen Refrigerator Room	Ceiling	Flaking on metal pipes	20	No	No	N/A	N/A	No	
885	6110	1	1	120E		Kitchen Staff Locker Room	Ceiling	Holes, paint has been stabilized, Efflorescence	17	Yes	No	N/A	N/A	Yes	
886	6110	1	1	120E		Kitchen Staff Locker Room	W2	Chipping on metal pipe, Flaking	30	No	No	N/A	N/A	No	
887	6110	1	1	120E		Kitchen Staff Locker Room	W3	Holes, Flaking	3	No	No	N/A	N/A	Yes	
888	6110	1	1	120E		Kitchen Staff Locker Room	W4	Cracking, Holes	5	No	No	N/A	Lockers	Yes	
889	6110	1	1	120B		Large Kitchen Storage Room	Ceiling	Flaking	2	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
890	6110	1	1	120B		Large Kitchen Storage Room	Floor	Limited Inspection		No	No		Shelves with stored materials	No	Limited inspection due to stored materials
891	6110	1	1	120B		Large Kitchen Storage Room	W1	Chipping on door frame	5	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
892	6110	1	1	120B		Large Kitchen Storage Room	W2	Limited Inspection		No	No		Shelves with stored materials	No	Limited inspection due to stored materials
893	6110	1	1	120B		Large Kitchen Storage Room	W3	Limited Inspection		No	No		Shelves with stored materials	No	Limited inspection due to stored materials
894	6110	1	1	120B		Large Kitchen Storage Room	W4	Limited Inspection		No	No		Shelves with stored materials	No	Limited inspection due to stored materials
895	6110	1	1	113C	Administrative Office	Library Office	Floor	Debris	N/A	No	Paint chips and debris scattered throughout	15	N/A	No	
896	6110	1	1	113C	Administrative Office	Library Office	W1	Chipping on doorframe	16	No	No	N/A	N/A	No	
897	6110	1	1	113C	Administrative Office	Library Office	W2	Holes, Flaking	33	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
898	6110	1	1	113C	Administrative Office	Library Office	W3	Flaking, Efflorescence	20	Yes	No	N/A	N/A	Yes	
899	6110	1	1	113C	Administrative Office	Library Office	W4	Flaking, Efflorescence	24	Yes	No	N/A	N/A	Yes	
900	6110	1	1	113M		Library Office Closet	Ceiling	No Access							This space will need to be inspected
901	6110	1	1	113M		Library Office Closet	Floor	No Access							This space will need to be inspected
902	6110	1	1	113M		Library Office Closet	W1	No Access							This space will need to be inspected
903	6110	1	1	113M		Library Office Closet	W2	No Access							This space will need to be inspected
904	6110	1	1	113M		Library Office Closet	W3	No Access							This space will need to be inspected
905	6110	1	1	113M		Library Office Closet	W4	No Access							This space will need to be inspected
906	6110	1	1	16A	Lobby	Main Entrance Lobby	Ceiling	Flaking	8	No	No	N/A	N/A	No	
907	6110	1	1	16A	Lobby	Main Entrance Lobby	W1	Chipping on doors and doorframes	47	No	No	N/A	N/A	No	
908	6110	1	1	16A	Lobby	Main Entrance Lobby	W2	Chipping on radiator cover	7	No	No	N/A	N/A	No	
909	6110	1	1	16A	Lobby	Main Entrance Lobby	W4	Chipping on radiator cover	7	No	No	N/A	N/A	No	
910	6110	1	1	16B		Main Entrance Vestibule	W1	Chipping on doors and doorframes, Efflorescence	53	Yes	No	N/A	N/A	Yes	
911	6110	1	1	104A	Restrooms, Staff - Male	Men's Restroom across from Auditorium	W1	Chipping on doorframe, Flaking in air shaft	2	No	No	N/A	N/A	No	
912	6110	1	1	104A	Restrooms, Staff - Male	Men's Restroom across from Auditorium	W2	Cracking, Holes	52	No	No	N/A	N/A	Yes	
913	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	Ceiling	Flaking above missing ceiling tile	2	No	No	N/A	N/A	No	
914	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	Floor	Chipping on cove behind radiator	5	No	No	N/A	N/A	No	
915	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	W1	Cracking, Chipping, Hole, Flaking	33	No	No	N/A	N/A	Yes	
916	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	W2	Cracking, Chipping	22	No	No	N/A	N/A	No	
917	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	W3	Flaking, some above missing ceiling tile, Efflorescence	7	Yes	Debris on windowsills	5	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
918	6110	1	1	103C		Men's Restroom Between Classroom 104 and Room C	W4	Cracking, Flaking	11	No	No	N/A	N/A	No	
919	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	Ceiling	Flaking	225	No	No	N/A	N/A	No	
920	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	Floor	Debris	N/A	No	Paint chips along edges	90	N/A	No	
921	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	W1	Chipping on door, Flaking	18	No	No	N/A	N/A	No	
922	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	W2	Flaking on wall and metal jackets	440	No	No	N/A	N/A	No	
923	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	W3	Flaking on wall, radiator, and metal pipe	245	No	No	N/A	N/A	No	
924	6110	1	1	113D	Administrative Office	Office to Left of Exit to Parking Lot	W4	Flaking on wall, radiator, and metal pipes	338	No	No	N/A	N/A	No	
925	6110	1	1	113H		Office to Left of Exit to Parking Lot Restroom	W2	Flaking	3	No	No	N/A	N/A	No	
926	6110	1	1	113H		Office to Left of Exit to Parking Lot Restroom	W3	Flaking on wall and metal pipe	15	No	No	N/A	N/A	No	
927	6110	1	1	113H		Office to Left of Exit to Parking Lot Restroom	W4	Flaking on wall and metal pipe	18	No	No	N/A	N/A	No	
928	6110	1	1	102	Primary	Room B	Ceiling	Holes, Flaking, Efflorescence	83	Yes	No	N/A	Stored Materials	Yes	
929	6110	1	1	102	Primary	Room B	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
930	6110	1	1	102	Primary	Room B	W1	Flaking	1	No	No	N/A	Stored Materials	No	
931	6110	1	1	102	Primary	Room B	W2	Cracking	16	No	No	N/A	Stored Materials	No	Repair to brick is needed
932	6110	1	1	102	Primary	Room B	W3	Chipping on radiator	10	No	No	N/A	Stored Materials	No	
933	6110	1	1	102	Primary	Room B	W4	Holes	5	No	No	N/A	Stored Materials	No	Repair to brick is needed
934	6110	1	1	102A		Room B Closet	Ceiling	Significant Moisture Damage	20	Yes	No	N/A	Shelves, Stored Materials	Yes	
935	6110	1	1	102A		Room B Closet	Floor	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
936	6110	1	1	102A		Room B Closet	W1	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
937	6110	1	1	102A		Room B Closet	W2	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
938	6110	1	1	102A		Room B Closet	W3	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
939	6110	1	1	102A		Room B Closet	W4	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
940	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	Ceiling	Flaking, Efflorescence	85	Yes	No	N/A	Stored Materials	Yes	
941	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
942	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	W1	Cracking, Chipping	13	No	No	N/A	Stored Materials	No	Repair to brick needed
943	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	W2	Cracking	10	No	No	N/A	Stored Materials	No	Repair to brick needed
944	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	W3	Cracking	5	No	No	N/A	Stored Materials	No	Repair to brick needed
945	6110	1	1	103A	Primary	Room C next to Classroom 103 (Paint Storage Room)	W4	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
946	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	Ceiling	Holes	3	No	No	N/A	Shelves, Stored Materials	Yes	
947	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	Floor	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
948	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	W1	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
949	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	W2	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
950	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	W3	Limited Inspection		No	No		Shelves, Stored Materials	No	Limited Inspection due to stored materials
951	6110	1	1	103E		Room C next to Classroom 103 (Paint Storage Room) Closet	W4	Flaking on metal pipe	12	No	No	N/A	Shelves, Stored Materials	No	
952	6110	1	1	113B	Kitchen and Dry Storage Area	Small Kitchen Storage Room	Floor	Chipping	65	No	No	N/A	N/A	No	
953	6110	1	1	113B	Kitchen and Dry Storage Area	Small Kitchen Storage Room	W1	Chipping, Cracking, Hole	11	No	No	N/A	N/A	Yes	
954	6110	1	1	113B	Kitchen and Dry Storage Area	Small Kitchen Storage Room	W2	Chipping, Cracking	20	No	No	N/A	Shelves with stored materials	No	
955	6110	1	1	113B	Kitchen and Dry Storage Area	Small Kitchen Storage Room	W3	Limited Inspection		No	No		Cabinets	No	Limited inspection due to stored materials
956	6110	1	1	113B	Kitchen and Dry Storage Area	Small Kitchen Storage Room	W4	Limited Inspection		No	No		Shelves with stored materials	No	Limited Inspection due to stored materials
957	6110	1	1	S113		Stairs to IMC on Classroom Side	Ceiling	Flaking on beams	10	No	No	N/A	N/A	No	
958	6110	1	1	S113		Stairs to IMC on Classroom Side	Floor	Chipping on cove	36	No	No	N/A	N/A	No	
959	6110	1	1	S113		Stairs to IMC on Classroom Side	W1	Flaking, Efflorescence	45	Yes	No	N/A	N/A	No	
960	6110	1	1	S113		Stairs to IMC on Classroom Side	W2	Flaking on window frames	4	No	No	N/A	N/A	No	
961	6110	1	1	S113		Stairs to IMC on Classroom Side	W3	Holes, Flaking on wall and windowsill	25	No	No	N/A	N/A	Yes	
962	6110	1	1	S113		Stairs to IMC on Classroom Side	W4	Flaking	40	No	No	N/A	N/A	No	
963	6110	1	1	S110	Stairs	Stairwell across from Classroom 108	Floor	Chipping	10	No	No	N/A	N/A	No	
964	6110	1	1	S110	Stairs	Stairwell across from Classroom 108	W1	Cracking	5	No	No	N/A	N/A	No	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
965	6110	1	1	S110	Stairs	Stairwell across from Classroom 108	W4	Chipping on doors and doorframe	22	No	No	N/A	N/A	No	
966	6110	1	1	S17	Stairs	Stairwell across from Classroom B	Ceiling	Flaking	6	No	No	N/A	N/A	No	
967	6110	1	1	S17	Stairs	Stairwell across from Classroom B	W1	Cracking, Chipping	4	No	No	N/A	N/A	No	
968	6110	1	1	S17	Stairs	Stairwell across from Classroom B	W2	Chipping on doors and doorframe, Flaking on doors and doorframe	24	No	No	N/A	N/A	No	
969	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	Ceiling	Cracking	1	No	No	N/A	N/A	No	
970	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	Floor	Chipping	7	No	No	N/A	N/A	No	
971	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	W1	Cracking	6	No	No	N/A	N/A	No	
972	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	W2	Chipping on doors and doorframe, Flaking on doors and doorframe, Hole, paint has been stabilized	46	No	No	N/A	N/A	Yes	
973	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	W3	Cracking, Flaking	6	No	No	N/A	N/A	No	
974	6110	1	1	S11	Stairs	Stairwell across from Storage Room 100	W4	Cracking	2	No	No	N/A	N/A	No	
975	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	Ceiling	No Access							This space will need to be inspected
976	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	Floor	No Access							This space will need to be inspected
977	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	W1	No Access							This space will need to be inspected
978	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	W2	No Access							This space will need to be inspected
979	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	W3	No Access							This space will need to be inspected
980	6110	1	1	S11A		Stairwell across from Storage Room 100 Closet	W4	No Access							This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
981	6110	1	1	S198		Stairwell to Former Gym near Classroom 104	Ceiling	Flaking	N/A	No	No	N/A	N/A	No	
982	6110	1	1	S198		Stairwell to Former Gym near Classroom 104	W1	Flaking	N/A	No	No	N/A	N/A	No	This area is not occupied and cannot be occupied without extensive repairs. Therefore, the flaking paint throughout the area was noted but not quantified.
983	6110	1	1	S198		Stairwell to Former Gym near Classroom 104	W2	Flaking	N/A	No	No	N/A	N/A	No	
984	6110	1	1	S198		Stairwell to Former Gym near Classroom 104	W3	Flaking	N/A	No	No	N/A	N/A	No	
985	6110	1	1	S198		Stairwell to Former Gym near Classroom 104	W4	Flaking	N/A	No	No	N/A	N/A	No	
986	6110	1	1	S198C		Stairwell to Former Gym near Classroom 104 Closet to Left of Entrance to Stairwell across from Classroom B	Ceiling	Flaking	N/A	No	No	N/A	N/A	No	
987	6110	1	1	S198C		Stairwell to Former Gym near Classroom 104 Closet to Left of Entrance to Stairwell across from Classroom B	W1	Flaking	N/A	No	No	N/A	N/A	No	This area is not occupied and cannot be occupied without extensive repairs. Therefore, the flaking paint throughout the area was noted but not quantified.
988	6110	1	1	S198C		Stairwell to Former Gym near Classroom 104 Closet to Left of Entrance to Stairwell across from Classroom B	W2	Flaking	N/A	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
989	6110	1	1	S198C		Stairwell to Former Gym near Classroom 104 Closet to Left of Entrance to Stairwell across from Classroom B	W3	Flaking	N/A	No	No	N/A	N/A	No	
990	6110	1	1	S198C		Stairwell to Former Gym near Classroom 104 Closet to Left of Entrance to Stairwell across from Classroom B	W4	Flaking	N/A	No	No	N/A	N/A	No	
991	6110	1	1	S198D		Stairwell to Former Gym near Classroom 104 Closet to Right of Entrance to Stairwell across from Classroom B	Ceiling	Flaking	N/A	No	No	N/A	N/A	No	
992	6110	1	1	S198D		Stairwell to Former Gym near Classroom 104 Closet to Right of Entrance to Stairwell across from Classroom B	W1	Flaking	N/A	No	No	N/A	N/A	No	This area is not occupied and cannot be occupied without extensive repairs. Therefore, the flaking paint throughout the area was noted but not quantified.
993	6110	1	1	S198D		Stairwell to Former Gym near Classroom 104 Closet to Right of Entrance to Stairwell across from Classroom B	W2	Flaking	N/A	No	No	N/A	N/A	No	
994	6110	1	1	S198D		Stairwell to Former Gym near Classroom 104 Closet to Right of Entrance to Stairwell across from Classroom B	W3	Flaking	N/A	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
995	6110	1	1	S198D		Stairwell to Former Gym near Classroom 104 Closet to Right of Entrance to Stairwell across from Classroom B	W4	Flaking	N/A	No	No	N/A	N/A	No	
996	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	Ceiling	Flaking on ceiling and metal pipes	70	No	No	N/A	N/A	No	
997	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	Floor	Debris	N/A	No	Paint chips scattered throughout	20	N/A	No	
998	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	W1	Flaking	20	No	No	N/A	N/A	No	
999	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	W2	Flaking	25	No	No	N/A	N/A	No	
1000	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	W3	Hole, Flaking	3	No	No	N/A	N/A	No	Repair to brick needed
1001	6110	1	1	S13	Stairs	Stairwell to IMC across from Cafeteria	W4	Flaking	65	No	No	N/A	N/A	No	
1002	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	Ceiling	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
1003	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	Floor	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
1004	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	W1	Efflorescence	3	Yes	No	N/A	Stored Materials	Yes	
1005	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	W2	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1006	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	W3	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
1007	6110	1	1	113E	Storage	Stairwell to IMC across from Cafeteria Storage Room	W4	Limited Inspection		No	No		Stored Materials	No	Limited Inspection due to stored materials
1008	6110	1	1	S13A		Stairwell to IMC across from Cafeteria Vestibule	Ceiling	Flaking	20	No	No	N/A	N/A	No	
1009	6110	1	1	S13A		Stairwell to IMC across from Cafeteria Vestibule	W1	Flaking on wall and metal pipe, Efflorescence	35	Yes	No	N/A	N/A	No	
1010	6110	1	1	S13A		Stairwell to IMC across from Cafeteria Vestibule	W4	Flaking	15	No	No	N/A	N/A	No	
1011	6110	1	1	101	Primary	Storage Room 100	Ceiling	Cracking, Flaking, Spalling	12	Yes	No	N/A	N/A	Yes	
1012	6110	1	1	101	Primary	Storage Room 100	W1	Chipping on metal jackets, Flaking in air shaft	7	No	No	N/A	N/A	No	
1013	6110	1	1	101	Primary	Storage Room 100	W2	Chipping, Holes	17	No	No	N/A	N/A	No	Repair to sheetrock needed
1014	6110	1	1	101	Primary	Storage Room 100	W3	Chipping on conduit and radiator	12	No	No	N/A	N/A	No	
1015	6110	1	1	101	Primary	Storage Room 100	W4	Chipping	1	No	No	N/A	N/A	No	
1016	6110	1	1	101B		Storage Room 101	Ceiling	Flaking	45	No	No	N/A	N/A	No	
1017	6110	1	1	101B		Storage Room 101	W1	Flaking in air shaft	5	No	No	N/A	N/A	No	
1018	6110	1	1	101A	Storage	Storage Room 101 Closet	W1	Flaking	11	No	No	N/A	N/A	No	
1019	6110	1	1	101A	Storage	Storage Room 101 Closet	W3	Cracking	10	No	No	N/A	N/A	No	Repair to brick needed
1020	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	Ceiling	Flaking on wall and metal pipe, Efflorescence	21	Yes	No	N/A	N/A	Yes	
1021	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	Floor	Debris	N/A	No	Debris by hall entrance	1	N/A	No	
1022	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	W1	Cracking, Chipping, Flaking on wall and doorframe	47	No	No	N/A	N/A	No	Stage Entrance
1023	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	W2	Cracking, Flaking on wall and metal pipe	50	No	No	N/A	N/A	No	
1024	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	W3	Cracking, Flaking on wall and metal pipes	47	No	No	N/A	N/A	No	
1025	6110	1	1	117A	Storage	Storage to Left of Auditorium Stage	W4	Chipping on wall and doorframe, Holes	23	No	No	N/A	N/A	Yes	
1026	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	Ceiling	Efflorescence	4	Yes	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1027	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	Floor	Debris	N/A	No	Debris by hall entrance	2	N/A	No	
1028	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	W1	Chipping on door and doorframe, Flaking on wall and door	19	No	No	N/A	N/A	No	Stage Entrance
1029	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	W2	Cracking, Chipping, Holes, Flaking	28	No	No	N/A	N/A	Yes	
1030	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	W3	Chipping on wood shelves, Flaking on wall and metal pipe	27	No	No	N/A	N/A	No	
1031	6110	1	1	117B	Storage	Storage to To Right of Auditorium Stage	W4	Chipping on wood shelves, Flaking	23	No	No	N/A	N/A	No	
1032	6110	2	1	004D		Ticket Booth	Floor	Chipping	60	No	No	N/A	N/A	No	
1033	6110	2	1	004D		Ticket Booth	W1	Chipping on doorframe and windowframe	12	No	No	N/A	N/A	No	
1034	6110	2	1	004D		Ticket Booth	W4	Chipping	7	No	No	N/A	N/A	No	
1035	6110	2	1	011C		Vestibule outside Classroom	W1	Chipping	9	No	No	N/A	N/A	No	
1036	6110	2	1	011C		Vestibule outside Classroom	W2	Chipping	13	No	No	N/A	N/A	No	
1037	6110	2	1	011C		Vestibule outside Classroom	W3	Flaking	1	No	No	N/A	N/A	No	
1038	6110	2	1	011C		Vestibule outside Classroom	W4	Flaking	1	No	No	N/A	N/A	No	
1039	6110	1	1	103D		Vestibule outside Classroom 103 and Room C	Ceiling	Cracking, Flaking	8	No	No	N/A	N/A	No	
1040	6110	1	1	103D		Vestibule outside Classroom 103 and Room C	W2	Cracking, Hole	6	No	No	N/A	N/A	No	Repair to brick and sheetrock needed
1041	6110	1	1	103D		Vestibule outside Classroom 103 and Room C	W3	Cracking	10	No	No	N/A	N/A	No	Repair to sheetrock needed
1042	6110	1	1	103D		Vestibule outside Classroom 103 and Room C	W4	Cracking, Hole	12	No	No	N/A	N/A	No	Repair to brick and sheetrock needed
1043	6110	1	1	120D		Vestibule outside Kitchen Staff Locker Room	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
1044	6110	1	1	120D		Vestibule outside Kitchen Staff Locker Room	Floor	Chipping	11	No	No	N/A	N/A	No	
1045	6110	1	1	120D		Vestibule outside Kitchen Staff Locker Room	W1	Chipping on doors	20	No	No	N/A	N/A	No	

