

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2630	1	3	329	Primary	Classroom 329	Ceiling	Flaking	16	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence
2	2630	1	3	329	Primary	Classroom 329	Floor	Chipping	5	N	Y	8	N	0	
3	2630	1	3	329	Primary	Classroom 329	W1	Flaking	36	N	N	0	Y - 192 SF Posters	N	3 Locations; Damage Including Door; Additional Cracking, Chipping
4	2630	1	3	329	Primary	Classroom 329	W2	Flaking	4	N	N	0	Y - 240 Whiteboard, Bulletin Boards, Posters	N	2 Locations
5	2630	1	3	329	Primary	Classroom 329	W3	Flaking	42	N	N	0	Y - 16 SF Posters	N	4 Locations
6	2630	1	3	329	Primary	Classroom 329	W4	Flaking	28	Y	N	0	Y - 50 SF Whiteboard, Posters	Y - 4 SF	3 Locations; Additional Efflorescence, Cracking
7	2630	1	3	330	Primary	Classroom 330	Floor	Chipping	3	N	N	0	None	N	Chipping Around Perimeter
8	2630	1	3	330	Primary	Classroom 330	W1	Flaking	38	N	N	0	Y - 42 SF Posters	N	3 Locations; Additional Cracking
9	2630	1	3	330	Primary	Classroom 330	W2	Cracking	2	N	N	0	Y - 168 SF Bookcases, Posters	N	
10	2630	1	3	330	Primary	Classroom 330	W3	Flaking	17	N	N	0	Y - 168 SF Desks, Contents	N	3 Locations; Additional Cracking
11	2630	1	3	330	Primary	Classroom 330	W4	Partially Inaccessible	0	N	N	0	Y - 192 SF Whiteboard, Posters, Contents	N	
12	2630	1	3	331	Primary	Classroom 331	Ceiling	Flaking	16	Y	N	0	N	Y - 4 SF	4 Locations; Additional Efflorescence, Cracking
13	2630	1	3	331	Primary	Classroom 331	Floor	Chipping	10	N	N	0	N	N	Chipping Around Perimeter
14	2630	1	3	331	Primary	Classroom 331	W1	Flaking	18	N	N	0	Y - 30 SF Posters	N	9 Locations; Additional Cracking, Chipping
15	2630	1	3	331	Primary	Classroom 331	W2	Flaking	15	N	N	0	Y - 192 SF Whiteboard, Posters	N	4 Locations; Additional Cracking, Chipping; Chipping Around White Board Trim
16	2630	1	3	331	Primary	Classroom 331	W3	Flaking	14	Y	N	0	Y - 114 Bookcases, Desks, Posters	Y - 2 SF	3 Locations; Additional Efflorescence, Cracking; Substantial Damage Likely Behind Obstructions
17	2630	1	3	331	Primary	Classroom 331	W4	Chipping	3	N	N	0	Y - 84 SF Whiteboard, Posters	N	3 Locations
18	2630	1	3	332	Primary	Classroom 332	Ceiling	Flaking	20	Y	N	0	N	Y - 4 SF	Additional Efflorescence
19	2630	1	3	332	Primary	Classroom 332	Floor	Chipping	6	N	Y	6	N	N	Debris on Floor
20	2630	1	3	332	Primary	Classroom 332	W1	Flaking	24	N	N	0	N	N	5 Locations
21	2630	1	3	332	Primary	Classroom 332	W2	Flaking	26	N	N	0	Y - 96 SF Bulletin Board	Y - 1 SF	3 Locations; Additional Cracking; Flaking Includes Blackboard Trim
22	2630	1	3	332	Primary	Classroom 332	W3	Flaking	192	N	N	0	N	N	Whole Wall; Additional Cracking
23	2630	1	3	332	Primary	Classroom 332	W4	Cracking	14	N	N	0	Y - 128 SF Whiteboard	N	Flaking Includes White Board Trim; Additional Chipping
24	2630	1	3	333	Primary	Classroom 333	Ceiling	Flaking	4	N	N	0	N	N	3 Locations
25	2630	1	3	333	Primary	Classroom 333	W1	Cracking	5	N	N	0	Y - 120 SF Posters, Whiteboards, Desks	N	
26	2630	1	3	333	Primary	Classroom 333	W2	Flaking	3	N	N	0	Y - 64 SF Desks, Bookcases	N	2 Locations; Additional Cracking
27	2630	1	3	333	Primary	Classroom 333	W3	Flaking	20	N	N	0	Y - 90 SF Bookcases, Contents	N	5 Locations; Flaking on Window Sills 1-5
28	2630	1	3	333	Primary	Classroom 333	W4	Cracking	12	N	N	0	N	N	Additional Chipping
29	2630	1	3	334	Primary	Classroom 334	W1	Flaking	28	N	N	0	Y - 88 SF Whiteboard, Posters	N	3 Locations; Additional Cracking; Flaking on Wall & Black Board Trim
30	2630	1	3	334	Primary	Classroom 334	W2	Gouges	2	N	N	0	Y - 216 SF Bulletin Boards, Posters	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
31	2630	1	3	334	Primary	Classroom 334	W3	Cracking	10	N	N	0	N	N	4 Locations; Additional Cracking; Damage on Window Sills & Frames
32	2630	1	3	334	Primary	Classroom 334	W4	Flaking	13	N	N	0	Y - 132 SF Whiteboard, Bulletin Boards, Desks	N	2 Locations
33	2630	1	3	335	Primary	Classroom 335	Floor	Chipping	3	N	N	0	N	N	
34	2630	1	3	335	Primary	Classroom 335	W1	Flaking	10	N	N	0	Y - 100 SF Whiteboard, Posters	N	2 Locations; Flaking on Door & White Board Trim; Additional Cracking
35	2630	1	3	335	Primary	Classroom 335	W2	Partially Inaccessible	0	N	N	0	Y - 216 SF Bulletin Boards, Posters	N	
36	2630	1	3	335	Primary	Classroom 335	W3	Flaking	5	N	Y	2	Y - 196 SF Contents	N	3 Locations; Debris on Window Sill 5; Additional Chipping
37	2630	1	3	335	Primary	Classroom 335	W4	Flaking	32	N	N	0	Y - 240 SF Whiteboard, Posters	N	2 Locations; Additional Cracking
38	2630	1	3	336	Primary	Classroom 336	Floor	Chipping	4	N	N	0	N	N	
39	2630	1	3	336	Primary	Classroom 336	W1	Flaking	25	N	N	0	Y - 144 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking, Chipping
40	2630	1	3	336	Primary	Classroom 336	W2	Flaking	10	N	N	0	Y - 84 SF Bulletin Boards, Posters	N	2 Locations; Additional Cracking
41	2630	1	3	336	Primary	Classroom 336	W3	Flaking	18	Y	N	0	Y - 30 SF Bookcases, Posters	Y - 4 SF	4 Locations; Additional Efflorescence, Cracking; Plaster @ Window 2
42	2630	1	3	336	Primary	Classroom 336	W4	Cracking	12	N	N	0	Y - 240 SF Whiteboards, Contents	N	
43	2630	1	3	337	Primary	Classroom 337	Ceiling	Efflorescence	8	Y	N	0	Y - 36 SF Ductwork	Y - 4 SF	
44	2630	1	3	337	Primary	Classroom 337	Floor	Chipping	6	N	N	0	N	N	
45	2630	1	3	337	Primary	Classroom 337	W1	Cracking	10	N	N	0	Y - 64 SF White Boards, Bulletin Boards	N	3 Locations; Additional Chipping
46	2630	1	3	337	Primary	Classroom 337	W2	Efflorescence	18	Y	N	0	Y - 136 SF Cabinets	Y - 6 SF	3 Locations; Additional Cracking
47	2630	1	3	337	Primary	Classroom 337	W3	Flaking	14	N	N	0	Y - 16 SF Desks, Posters	N	7 Locations; Additional Cracking, Chipping; Windows & Radiator
48	2630	1	3	337	Primary	Classroom 337	W4	Flaking	13	N	N	0	Y - 126 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
49	2630	1	3	338	Primary	Classroom 338	Floor	Chipping	5	N	N	0	N	N	Around Perimeter
50	2630	1	3	338	Primary	Classroom 338	W1	Flaking	14	N	N	0	Y - 32 SF Bookcases, Posters	N	4 Locations; Additional Cracking, Chipping
51	2630	1	3	338	Primary	Classroom 338	W2	Cracking	22	N	N	0	Y - 210 SF Bulletin Boards	N	2 Locations
52	2630	1	3	338	Primary	Classroom 338	W3	Flaking	24	N	N	0	Y - 40 SF Bookcases	N	4 Locations
53	2630	1	3	338	Primary	Classroom 338	W4	Flaking	105	N	N	0	Y - 228 SF Bulletin Boards, White Board	N	4 Locations; Additional Cracking, Chipping, Holes
54	2630	1	3	339	Primary	Classroom 339	W1	Cracking	28	N	N	0	Y - 36 SF Posters	N	2 Locations
55	2630	1	3	339	Primary	Classroom 339	W2	Chipping	3	N	N	0	Y - 50 SF Posters	N	3 Locations
56	2630	1	3	339	Primary	Classroom 339	W3	Flaking	8	N	N	0	N	N	
57	2630	1	3	339	Primary	Classroom 339	W4	Cracking	2	N	N	0	Y - 160 SF Posters	N	
58	2630	1	3	340	Primary	Classroom 340	W1	Flaking	8	N	N	0	Y - 20 SF Posters	N	3 Locations; Additional Cracking, Chipping; Including Door Frame
59	2630	1	3	340	Primary	Classroom 340	W2	Chipping	6	N	N	0	Y - 12 SF Bulletin Boards	N	3 Locations
60	2630	1	3	340	Primary	Classroom 340	W3	Cracking	8	N	N	0	N	N	2 Locations
61	2630	1	3	340	Primary	Classroom 340	W4	Partially Inaccessible	0	N	N	0	Y - 200 SF Whiteboards	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
62	2630	1	3	341	Primary	Classroom 341	W1	Flaking	16	N	N	0	N	N	5 Locations; Additional Cracking, Chipping, Holes
63	2630	1	3	341	Primary	Classroom 341	W2	Flaking	10	N	N	0	Y - 144 SF Whiteboard, Posters	N	Flaking around Whiteboard; Additional Cracking
64	2630	1	3	341	Primary	Classroom 341	W3	Flaking	26	N	Y	8	N	N	4 Locations; Flaking Around Window Frames; Debris on Window Sills; Additional Cracking
65	2630	1	3	341	Primary	Classroom 341	W4	Flaking	3	N	N	0	N	N	Additional Cracking
66	2630	1	3	342	Primary	Classroom 342-A	Ceiling	Flaking	6	N	N	0	N	N	3 Locations; Additional Chipping
67	2630	1	3	342	Primary	Classroom 342-A	Floor	Chipping	5	N	N	0	N	N	
68	2630	1	3	342	Primary	Classroom 342-A	W1	Flaking	36	N	N	0	Y - 72 SF Whiteboards, Posters	N	4 Locations; Flaking on Door & Wall; Additional Cracking, Chipping
69	2630	1	3	342	Primary	Classroom 342-A	W2	Cracking	64	N	N	0	Y - 40 SF Posters	N	
70	2630	1	3	342	Primary	Classroom 342-A	W3	Flaking	2	N	N	0	Y - 8 SF Posters	N	2 Locations; Additional Cracking
71	2630	1	3	342	Primary	Classroom 342-A	W4	Flaking	2	N	N	0	Y - 40 SF Shelves	N	2 Locations; Additional Chipping
72	2630	1	3	329A	Storage	Storage Room next to Classroom 329	Ceiling	Cracking	2	N	N	0	N	N	
73	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W1	Flaking	1	N	N	0	N	Y - 1 SF	
74	2630	1	3	329A	Storage	Storage Room next to Classroom 329	W2	Flaking	2	N	N	0	N	N	Flaking on Pipe
75	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W3	Flaking	14	N	N	0	N	Y - 2 SF	2 Locations
76	2630	1	3	332A	Student Restrooms - Female (4-12)	Girls' Restroom next to Classroom 333	W4	Flaking	6	N	N	0	N	N	Additional Cracking
77	2630	1	3	333A	Storage	Classroom 333 Coat Closet	Ceiling	Flaking	6	N	N	0	N	N	
78	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W1	Cracking	4	N	N	0	N	N	
79	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W2	Flaking	6	N	N	0	N	N	2 Locations; Additional Cracking
80	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W3	Flaking	16	N	N	0	N	Y - 1 SF	3 Locations; Additional Cracking
81	2630	1	3	333A	Storage	Classroom 333 Coat Closet	W4	Cracking	9	N	N	0	N	N	
82	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W1	Flaking	1	N	N	0	Y - 80 SF Contents	N	
83	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W3	Flaking	16	N	N	0	N	N	4 Locations; Additional Cracking
84	2630	1	3	334A	Storage	Classroom 334 Coat Closet	W4	Cracking	2	N	N	0	N	N	
85	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W1	Flaking	36	N	N	0	Y - 60 SF Contents	N	Additional Cracking
86	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W2	Flaking	3	N	N	0	N	N	
87	2630	1	3	335A	Storage	Classroom 335 Coat Closet	W3	Flaking	4	N	N	0	N	Y - 1 SF	2 Locations; Additional Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
88	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Ceiling	Cracking	4	N	N	0	N	N	
89	2630	1	3	336A	Storage	Classroom 336 Coat Closet	Floor	Chipping	2	N	N	0	N	N	
90	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W1	Flaking	24	N	N	0	Y - 72 SF Contents	N	3 Locations; Additional Cracking
91	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W3	Flaking	96	N	N	0	N	N	Additional Cracking
92	2630	1	3	336A	Storage	Classroom 336 Coat Closet	W4	Cracking	4	N	N	0	N	N	Additional Chipping on Doors
93	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W2	Cracking	61	N	N	0	N	N	
94	2630	1	3	337A	Storage	Classroom 337 Storage Closet	W3	Flaking	8	N	N	0	N	N	Flaking @ Radiator
95	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W2	Flaking	1	N	N	0	N	N	
96	2630	1	3	337B	Student Restrooms - Male (4-12)	Boys' Restroom	W3	Flaking	3	N	N	0	N	N	
97	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	Ceiling	Flaking	45	N	N	0	N	N	Whole Ceiling; Additional Cracking
98	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W1	Flaking	12	N	N	0	Y - 72 SF Contents	N	Additional Cracking
99	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
100	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W3	Flaking	40	N	N	0	N	N	
101	2630	1	3	342A	Storage	Classroom 342-A Storage Closet	W4	Flaking	8	N	N	0	Y - 20 SF Contents	N	Additional Cracking
102	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	Ceiling	Cracking	3	N	N	0	N	N	2 Locations
103	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W1	Cracking	12	N	N	0	Y - 12 SF File Cabinets	N	
104	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W2	Flaking	12	N	N	0	12 SF Whiteboard	N	2 Locations; Whiteboard Trim & Wall
105	2630	1	3	342B	Administrative Office	Room 342-B Speech-Language Office	W3	Flaking	30	N	N	0	N	N	2 Locations; Behind Radiator
106	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	Floor	Chipping	14	N	N	0	N	N	
107	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W2	Flaking	6	N	N	0	Y - 42 SF Papers	N	10 Locations; Additional Cracking, Chipping
108	2630	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 338 to 341	W3	Flaking	35	N	Y	3	N	N	Debris on Window Sills 1-4; Additional Cracking
109	2630	1	3	H310A	Circulation (Hallway)	Square Hallway Area between Boys' Restroom and Stairwell next to Classroom 337	W1	Cracking	8	N	N	0	N	N	2 Locations



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
131	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
132	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
133	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
134	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
135	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
136	2630	1	3	S35	Stairs	Fire Tower across from Classroom 334	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
137	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	Ceiling	Flaking	28	Y	N	0	Y - 12 SF	N	3 Locations; Including Roof Access Landing
138	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W1	Flaking	32	Y	N	0	Y - 10 SF	N	3 Locations; Flaking on Walls and Behind Radiator; Additional Cracking; Including Roof Access Landing
139	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W2	Flaking	50	Y	N	0	Y - 20 SF	N	3 Locations; Including Roof Access Landing
140	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W3	Flaking	46	Y	N	0	Y - 12 SF	N	3 Locations; Including Roof Access Landing
141	2630	1	3	S36	Stairs	Stairwell next to Classroom 334	W4	Flaking	200	Y	N	0	Y - 18 SF	N	3 Locations; Including Roof Access Landing
142	2630	1	3	S37	Stairs	Fire Tower across from Classroom 329	Ceiling	Flaking	36	Y	N	0	N	Y - 12 SF	Additional Efflorescence
143	2630	1	2	216	IMC (Library)	IMC/Library	Floor	Chipping	18	N	N	0	N	N	Chipping Around Perimeter
144	2630	1	2	216	IMC (Library)	IMC/Library	W1	Flaking	6	N	N	0	Y - 72 SF Bookcases, Posters	Y - 2 SF	4 Locations; Additional Cracking, Chipping
145	2630	1	2	216	IMC (Library)	IMC/Library	W2	Holes	3	N	N	0	N	N	3 Locations
146	2630	1	2	216	IMC (Library)	IMC/Library	W3	Flaking	7	N	N	0	Y - 86 SF Contents	N	3 Locations; Additional Chipping
147	2630	1	2	216	IMC (Library)	IMC/Library	W4	Chipping	2	N	N	0	Y - 96 SF Desks	N	2 Locations
148	2630	1	2	217	Primary	Classroom 217	Floor	Chipping	6	N	N	0	N	N	Chipping Around Perimeter
149	2630	1	2	217	Primary	Classroom 217	W1	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	Including Door & Wall
150	2630	1	2	217	Primary	Classroom 217	W3	Flaking	4	N	N	0	Y - 32 SF Posters	N	2 Locations; Additional Holes; Damage Includes Radiator
151	2630	1	2	217	Primary	Classroom 217	W4	Partially Inaccessible	0	N	N	0	Y - 140 SF Posters, Bulletin Boards	N	
152	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W1	Cracking	8	N	N	0	Y - 18 SF Contents	N	2 Locations; Additional Cracking
153	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W2	Flaking	5	N	N	0	Y - 24 SF Shelves	N	
154	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W3	Cracking	12	N	N	0	Y - 20 SF Cabinets	N	
155	2630	1	2	218	Teacher Lounge/Dining	Faculty Lounge	W4	Partially Inaccessible	0	N	N	0	Y - 6 SF Contents	N	
156	2630	1	2	219	Primary	Classroom 219	Ceiling	Flaking	24	N	N	0	N	N	Additional Cracking
157	2630	1	2	219	Primary	Classroom 219	Floor	Chipping	9	N	N	0	N	N	
158	2630	1	2	219	Primary	Classroom 219	W1	Flaking	1	N	N	0	N	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
159	2630	1	2	219	Primary	Classroom 219	W2	Cracking	2	N	N	0	Y - 90 SF Bookcases	N	
160	2630	1	2	219	Primary	Classroom 219	W3	Flaking	12	N	N	0	Y - 16 SF Posters	N	3 Locations; Additional Cracking; Including Pipe, Wall, Radiator
161	2630	1	2	219	Primary	Classroom 219	W4	Holes	4	N	N	0	N	N	
162	2630	1	2	220	Auditorium	Auditorium	Ceiling	Cracking	4	N	N	0	N	N	
163	2630	1	2	220	Auditorium	Auditorium	Floor	Chipping	30	N	N	0	N	N	
164	2630	1	2	220	Auditorium	Auditorium	W1	Flaking	18	N	N	0	Y - 72 SF Bulletin Boards	Y - 1 SF	6 Locations; Additional Cracking, Chipping
165	2630	1	2	220	Auditorium	Auditorium	W3	Flaking	74	N	N	0	Y - 96 SF Contents, Posters	N	10 Locations; Additional Cracking, Chipping
166	2630	1	2	220	Auditorium	Auditorium	W4	Flaking	18	N	N	0	Y - 240 SF Bulletin Board	N	
167	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W3	Flaking	12	N	N	0	N	Y - 1 SF	2 Locations; Additional Cracking; Flaking @ Radiator
168	2630	1	2	222	Administrative Office	Counselor's Office next to Classroom 223A	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF File Cabinets, Bookcases	N	
169	2630	1	2	223	Primary	Classroom 223	Floor	Chipping	33	N	N	0	N	N	Chipping Around Perimeter
170	2630	1	2	223	Primary	Classroom 223	W1	Flaking	8	N	N	0	Y - 42 SF Posters	N	3 Locations; Additional Chipping
171	2630	1	2	223	Primary	Classroom 223	W2	Partially Inaccessible	0	N	N	0	Y - 168 SF Bulletin Boards, Posters	N	
172	2630	1	2	223	Primary	Classroom 223	W3	Flaking	10	N	N	0	Y - 16 SF Posters	N	7 Locations; Additional Cracking
173	2630	1	2	223	Primary	Classroom 223	W4	Flaking	4	N	N	0	Y - 144 SF Whiteboard, Posters	N	2 Locations
174	2630	1	2	224	Primary	Classroom 224	Ceiling	Flaking	40	N	N	0	N	N	2 Locations
175	2630	1	2	224	Primary	Classroom 224	Floor	Chipping	4	N	N	0	N	N	
176	2630	1	2	224	Primary	Classroom 224	W1	Cracking	8	N	N	0	N	N	
177	2630	1	2	224	Primary	Classroom 224	W2	Partially Inaccessible	0	N	Y	25	Y - 48 SF Desks, Posters	N	
178	2630	1	2	224	Primary	Classroom 224	W3	Flaking	16	N	N	0	Y - 35 SF Desks Tables	N	2 Locations; Flaking @ Radiators
179	2630	1	2	224	Primary	Classroom 224	W4	Flaking	1	N	Y	1	Y - 18 SF File Cabinets, Desks	Y - 1 SF	
180	2630	1	2	225	Primary	Classroom 225	Ceiling	Cracking	2	N	N	0	N	N	2 Locations; Additional Cracking
181	2630	1	2	225	Primary	Classroom 225	Floor	Chipping	7	N	N	0	N	N	Chipping Around Perimeter
182	2630	1	2	225	Primary	Classroom 225	W1	Flaking	86	N	N	0	Y - 52 SF Contents, Posters	N	3 Locations; Additional Chipping
183	2630	1	2	225	Primary	Classroom 225	W2	Partially Inaccessible	0	N	N	0	Y - 147 SF Bulletin Boards, Posters	N	
184	2630	1	2	225	Primary	Classroom 225	W3	Flaking	22	N	N	0	Y - 54 SF Desks, Bookcases	N	3 Locations; Additional Cracking
185	2630	1	2	225	Primary	Classroom 225	W4	Flaking	12	N	N	0	Y - 48 SF Desks, Posters	N	Additional Cracking
186	2630	1	2	226	Primary	Classroom 226	W1	Flaking	24	Y	N	0	Y - 130 SF Posters, Bookcases, Desks	Y - 24 SF	Additional Efflorescence
187	2630	1	2	226	Primary	Classroom 226	W2	Flaking	8	N	N	0	Y - 52 SF Bookcases, Posters	N	2 Locations; Additional Cracking
188	2630	1	2	226	Primary	Classroom 226	W3	Flaking	26	N	N	0	Y - 100 SF Desks, File Cabinets, Posters	N	3 Locations; Additional Cracking; Flaking Including Radiator
189	2630	1	2	226	Primary	Classroom 226	W4	Partially Inaccessible	0	N	N	0	Y - 45 SF Desks, Posters	N	
190	2630	1	2	227	Primary	Classroom 227	Ceiling	Flaking	10	N	N	0	N	N	2 Locations
191	2630	1	2	227	Primary	Classroom 227	Floor	Chipping	4	N	N	0	N	N	
192	2630	1	2	227	Primary	Classroom 227	W1	Flaking	6	N	N	0	Y - 192 SF Contents, Bookcases	N	3 Locations; Additional Chipping
193	2630	1	2	227	Primary	Classroom 227	W2	Flaking	6	N	N	0	N	N	2 Locations



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
221	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
222	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
223	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
224	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
225	2630	1	2	220B	Storage	Auditorium Storage Closet next to Stage	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
226	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
227	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
228	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
229	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
230	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
231	2630	1	2	220C	Storage	Auditorium Middle Storage Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
232	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
233	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
234	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	*Visible Flaking Observed Through Window
235	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
236	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
237	2630	1	2	220D	Storage	Auditorium Rear Storage Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
238	2630	1	2	223A	Storage	Classroom 223 Coat Closet	Ceiling	Holes	2	N	N	0	None	Y - 2 SF	
239	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W1	Flaking	10	N	N	0	Y - 42 SF Bookcases	N	2 Locations; Additional Cracking, Holes
240	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W2	Flaking	4	N	N	0	Y - 24 SF Contents	N	
241	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W3	Flaking	6	N	N	0	Y - 30 SF Contents	Y - 4 SF	2 Locations; Additional Cracking, Holes
242	2630	1	2	223A	Storage	Classroom 223 Coat Closet	W4	Flaking	3	N	N	0	Y - 24 SF Contents, Boxes	N	2 Locations
243	2630	1	2	224B	Student Restrooms - Male/Female (Classroom)	Classroom 224 Restroom	W2	Flaking	16	N	N	0	N	N	Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
244	2630	1	2	226B	Student Restrooms - Male/Female (Classroom)	Classroom 226 Restroom	W3	Flaking	5	N	N	0	N	N	3 Locations; Additional Cracking
245	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W2	Chipping	1	N	N	0	N	N	
246	2630	1	2	227C	Student Restrooms - Male/Female (Classroom)	Classroom 227 Restroom	W3	Chipping	3	N	N	0	N	N	3 Locations
247	2630	1	2	228A	Storage	Classroom 228 Storage Closet	Ceiling	Flaking	75	N	N	0	N	N	
248	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W1	Flaking	42	N	N	0	N	N	Damage on Entire Wall
249	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W2	Cracking	12	N	N	0	Y - 30 SF Bookcases	N	
250	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W3	Flaking	120	N	N	0	N	N	Damage on Entire Wall
251	2630	1	2	228A	Storage	Classroom 228 Storage Closet	W4	Flaking	50	N	N	0	Y - 12 SF Ductwork	N	
252	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	Floor	Chipping	376	N	N	0	N	N	Hallway Perimeter
253	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W2	Flaking	170	N	N	0	Y - 36 SF Bookcase	N	13 Locations; Additional Cracking
254	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W3	Cracking	6	N	N	0	N	N	
255	2630	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 224 to 227	W4	Flaking	117	N	N	0	Y - 54 SF Bookcase	N	4 Locations; Additional Chipping
256	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	Floor	Chipping	2	N	N	0	N	N	
257	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W2	Partially Inaccessible	0	N	N	0	Y - 12 SF Posters	N	
258	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Bulletin Board, Posters	N	
259	2630	1	2	H27A	Circulation (Hallway)	Square Hallway Area between 223A Counselor's Office and Stairwell next to Classroom 223	W1	Cracking	65	N	N	0	Y - 36 SF Posters	N	
260	2630	1	2	H28	Circulation (Hallway)	Hallway from Classroom 219 to Fire Tower Stairs across from Stairwell near Classroom 223	Ceiling	Flaking	8	N	N	0	N		



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
279	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
280	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
281	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
282	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
283	2630	1	2	S25	Stairs	Fire Tower Stairs across from Rear Auditorium	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
284	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	Ceiling	Cracking	3	N	N	0	N	N	
285	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W1	Flaking	2	N	N	0	N	N	
286	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W2	Flaking	10	N	N	0	N	N	2 Locations; Additional Cracking
287	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Posters	N	
288	2630	1	2	S26	Stairs	Stairwell next to Classroom 219	W4	Flaking	6	N	N	0	N	N	2 Locations
289	2630	1	2	S27	Stairs	Fire Tower Stairwell across from IMC/Library	Ceiling	Flaking	8	N	N	0	N	N	3 Locations
290	2630	1	1	101	Primary	Classroom 101	Floor	Chipping	4	N	N	0	N	N	Chipping Around Perimeter
291	2630	1	1	101	Primary	Classroom 101	W1	Flaking	90	N	N	0	Y - 144 SF Contents, Posters	N	5 Locations; Additional Cracking, Chipping
292	2630	1	1	101	Primary	Classroom 101	W2	Flaking	2	N	N	0	N	N	2 Locations
293	2630	1	1	101	Primary	Classroom 101	W3	Chipping	1	N	N	0	Y - 60 SF Bookcases, Contents	N	
294	2630	1	1	101	Primary	Classroom 101	W4	Flaking	8	N	N	0	Y - 56 SF File Cabinets, Whiteboard, Desks	N	3 Locations; Additional Cracking
295	2630	1	1	102	Primary	Classroom 102	Floor	Chipping	11	N	N	0	N	N	Chipping Around Perimeter
296	2630	1	1	102	Primary	Classroom 102	W1	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	Additional Cracking
297	2630	1	1	102	Primary	Classroom 102	W2	Flaking	6	N	N	0	Y - 84 SF Bookcases, Posters	N	3 Locations; Additional Cracking
298	2630	1	1	102	Primary	Classroom 102	W3	Flaking	6	N	N	0	Y - 64 Bookcases, Desks	N	3 Locations; Including Radiator
299	2630	1	1	102	Primary	Classroom 102	W4	Chipping	4	N	N	0	Y - 60 SF Posters	N	
300	2630	1	1	103	Primary	Classroom 103	Floor	Chipping	7	N	N	0	N	N	4 Locations
301	2630	1	1	103	Primary	Classroom 103	W2	Flaking	3	N	N	0	Y - 160 SF Posters, Contents	N	3 Locations; Including Chalkboard Trim; Additional Chipping
302	2630	1	1	103	Primary	Classroom 103	W3	Flaking	40	N	N	0	Y - 72 SF Desks, Posters	N	4 Locations; Additional Cracking
303	2630	1	1	103	Primary	Classroom 103	W4	Flaking	30	N	N	0	Y - 160 SF Whiteboard, Posters	N	2 Locations; Additional Cracking
304	2630	1	1	104	Administrative Office	Nurse's Office	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking; Including Pipe Paint
305	2630	1	1	104	Administrative Office	Nurse's Office	W1	Flaking	74	N	N	0	N	N	Additional Cracking
306	2630	1	1	104	Administrative Office	Nurse's Office	W2	Flaking	8	N	N	0	Y - 45 SF Chairs	N	2 Locations; Additional Cracking & Gouges

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
307	2630	1	1	104	Administrative Office	Nurse's Office	W3	Flaking	18	N	N	0	Y - 96 SF Desks, Contents	N	Additional Cracking
308	2630	1	1	104	Administrative Office	Nurse's Office	W4	Partially Inaccessible	0	N	N	0	Y - 144 SF Bulletin Boards, File Cabinets, Posters	N	
309	2630	1	1	105	Primary	Classroom 105	Floor	Chipping	5	N	N	0	N	N	
310	2630	1	1	105	Primary	Classroom 105	W1	Partially Inaccessible	0	N	N	0	Y - 240 SF Posters	N	
311	2630	1	1	105	Primary	Classroom 105	W2	Cracking	2	N	N	0	N	N	
312	2630	1	1	105	Primary	Classroom 105	W3	Flaking	15	N	N	0	Y - 168 SF Posters	N	4 Locations; Including Pipe & Radiator
313	2630	1	1	105	Primary	Classroom 105	W4	Chipping	2	N	N	0	Y - 120 SF Bookcases	N	
314	2630	1	1	106	Primary	Classroom 106	Ceiling	Flaking	8	N	N	0	N	N	
315	2630	1	1	106	Primary	Classroom 106	Floor	Chipping	6	N	N	0	N	N	Chipping Around Perimeter
316	2630	1	1	106	Primary	Classroom 106	W1	Flaking	5	N	N	0	Y - 160 SF Posters, Contents	N	2 Locations
317	2630	1	1	106	Primary	Classroom 106	W2	Cracking	20	N	N	0	Y - 120 SF Posters	N	
318	2630	1	1	106	Primary	Classroom 106	W3	Flaking	4	N	N	0	Y - 144 SF Posters, Contents	N	
319	2630	1	1	106	Primary	Classroom 106	W4	Chipping	2	N	N	0	Y - 72 SF Desks, Bookcases	N	
320	2630	1	1	107	Primary	Classroom 107	W1	Flaking	1	N	N	0	Y - 147 Bookcases, Posters	N	
321	2630	1	1	107	Primary	Classroom 107	W2	Flaking	16	N	N	0	Y - 144 Bookcases, Posters	N	Additional Cracking
322	2630	1	1	107	Primary	Classroom 107	W3	Flaking	20	N	N	0	Y - 84 SF Bookcases, Desks	N	4 Locations; Additional Cracking
323	2630	1	1	107	Primary	Classroom 107	W4	Cracking	28	N	N	0	Y - 150 SF Bookcases, Posters	N	Additional Chipping
324	2630	1	1	108	Primary	Classroom 108	Floor	Chipping	10	N	N	0	N	N	3 Locations
325	2630	1	1	108	Primary	Classroom 108	W1	Flaking	16	N	N	0	Y - 126 SF Bookcases, Posters	N	2 Locations; Additional Cracking
326	2630	1	1	108	Primary	Classroom 108	W2	Flaking	2	N	N	0	Y - 140 SF Bulletin Boards, Posters, Bookcases	N	
327	2630	1	1	108	Primary	Classroom 108	W3	Flaking	9	N	N	0	Y - 24 SF Desks, Bookcases	N	3 Locations; Additional Cracking, Chipping
328	2630	1	1	108	Primary	Classroom 108	W4	Flaking	96	N	N	0	Y - 144 SF Desks, Tables, Contents	N	Additional Cracking
329	2630	1	1	109	Primary	Room 109 Head Start Program	Ceiling	Flaking	75	N	N	0	N	N	5 Locations; Additional Cracking
330	2630	1	1	109	Primary	Room 109 Head Start Program	Floor	Chipping	20	N	N	0	N	N	4 Locations; Additional Cracking
331	2630	1	1	109	Primary	Room 109 Head Start Program	W1	Cracking	6	N	N	0	Y - 160 SF Bulletin Boards, Posters	N	
332	2630	1	1	109	Primary	Room 109 Head Start Program	W2	Partially Inaccessible	0	N	N	0	Y - 140 SF Contents	N	
333	2630	1	1	109	Primary	Room 109 Head Start Program	W3	Flaking	24	N	N	0	Y - 72 SF Contents	N	6 Locations
334	2630	1	1	109	Primary	Room 109 Head Start Program	W4	Flaking	4	N	N	0	Y - 76 SF Posters, Bookcases, Contents	N	2 Locations



Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
354	2630	1	1	113	Storage	Storage Room between end of Gymnasium and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
355	2630	1	1	114	Primary	Room 114 Head Start Program	W1	Flaking	24	N	N	0	Y - 192 SF Cabinet, Bulletin Boards	N	2 Locations; Additional Cracking
356	2630	1	1	114	Primary	Room 114 Head Start Program	W2	Partially Inaccessible	0	N	N	0	Y - 168 SF Bulletin Boards, Posters	N	
357	2630	1	1	114	Primary	Room 114 Head Start Program	W3	Flaking	20	N	N	0	Y - 36 SF Desks, Bookcases	Y - 2	4 Locations; Additional Cracking; Plaster @ Window 3
358	2630	1	1	114	Primary	Room 114 Head Start Program	W4	Flaking	3	N	N	0	Y - 140 SF Bulletin Boards, Posters	N	3 Locations; Additional Cracking
359	2630	1	1	101A	Storage	Storage Room next to Classroom 101	Ceiling	Flaking	12	N	N	0	N	N	
360	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W1	Partially Inaccessible	0	N	N	0	Y - 160 SF Shelves	N	Flaking @ Radiator
361	2630	1	1	101A	Storage	Storage Room next to Classroom 101	W3	Flaking	2	N	N	0	Y - 160 SF Shelves	N	
362	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	Ceiling	Efflorescence	3	Y	N	0	N	Y - 5 SF	
363	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W1	Flaking	8	N	N	0	Y - 32 SF Desks, Fridge	N	3 Locations; Additional Cracking
364	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W2	Flaking	4	N	N	0	Y - 72 SF Tables, Contents	N	2 Locations; Additional Cracking
365	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W3	Flaking	13	N	N	0	N	N	2 Locations; Additional Cracking
366	2630	1	1	104A	Teacher Lounge/Dining	Maintenance Staff Lounge next to Classroom 105	W4	Efflorescence	8	Y	N	0	N	Y - 5 SF	3 Locations; Additional Cracking, Chipping
367	2630	1	1	104B	Restrooms, Staff - Male	Men's Restroom in the Maintenance Staff Lounge	W2	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
368	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	Ceiling	Cracking	3	N	N	0	N	N	
369	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W1	Flaking	20	N	N	0	N	N	3 Locations; Additional Cracking
370	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W2	Flaking	12	N	N	0	N	N	2 Locations; Additional Cracking
371	2630	1	1	105A	Student Restrooms - Male/Female (Classroom)	Classroom 105 Restroom	W3	Flaking	24	N	N	0	N	N	Additional Cracking
372	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W1	Cracking	27	N	N	0	N	N	
373	2630	1	1	105B	Storage	Classroom 105 Coat Closet	W3	Flaking	45	N	N	0	N	N	Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
374	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W1	Cracking	6	N	N	0	Y - 80 SF Contents	N	3 Locations
375	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
376	2630	1	1	106A	Storage	Classroom 106 Coat Closet	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Contents	N	
377	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W1	Partially Inaccessible	0	N	N	0	Y - 72 SF Contents	N	
378	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
379	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W3	Cracking	4	N	N	0	Y - 60 SF Contents	N	
380	2630	1	1	107A	Storage	Classroom 107 Coat Closet	W4	Cracking	2	N	N	0	N	N	
381	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W1	Cracking	3	N	N	0	N	N	
382	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
383	2630	1	1	108A	Storage	Classroom 108 Coat Closet	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	
384	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W1	Flaking	2	N	N	0	N	N	2 Locations; Additional Cracking
385	2630	1	1	108B	Student Restrooms - Male/Female (Classroom)	Classroom 108 Restroom	W3	Cracking	2	N	N	0	N	N	
386	2630	1	1	109A	Storage	Room 109 Storage Room	Ceiling	Flaking	4	N	N	0	N	N	Additional Cracking
387	2630	1	1	109A	Storage	Room 109 Storage Room	W1	Flaking	18	N	N	0	Y - 24 SF Contents	N	2 Locations; Additional Cracking
388	2630	1	1	109A	Storage	Room 109 Storage Room	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	
389	2630	1	1	109A	Storage	Room 109 Storage Room	W3	Partially Inaccessible	0	N	N	0	Y - 120 SF Shelves, Boxes	N	
390	2630	1	1	109A	Storage	Room 109 Storage Room	W4	Partially Inaccessible	0	N	N	0	Y - 40 SF Shelves	N	
391	2630	1	1	110T	Restrooms, Staff - Female	Principal's Office Restroom	W1	Flaking	2	N	N	0	N	N	
392	2630	1	1	114A	Storage	Room 114 Storage Closet	W1	Partially Inaccessible	0	N	N	0	Y - 8 SF Contents	N	
393	2630	1	1	114A	Storage	Room 114 Storage Closet	W2	Cracking	16	N	N	0	Y - 8 SF Contents	N	
394	2630	1	1	114A	Storage	Room 114 Storage Closet	W3	Cracking	8	N	N	0	Y - 50 SF File Cabinets, Contents	N	
395	2630	1	1	114A	Storage	Room 114 Storage Closet	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Contents	N	
396	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	Ceiling	Flaking	16	N	N	0	N	N	3 Locations
397	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W2	Flaking	176	N	N	0	Y - 160 SF Bookcases	N	5 Locations; Additional Cracking
398	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W3	Cracking	64	N	N	0	N	N	
399	2630	1	1	H14	Circulation (Hallway)	Hallway from Main Office to end of Gymnasium	W4	Flaking	248	N	N	0	Y - 30 SF Bookcase, Posters	N	10 Locations; Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
400	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W2	Cracking	6	N	N	0	N	N	
401	2630	1	1	H14A	Circulation (Hallway)	Square Hallway between Principal's Office and Main Entrance Stairwell	W3	Flaking	2	N	N	0	Y - 16 SF Bulletin Board	N	
402	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Ceiling	Flaking	50	Y	N	0	N	Y - 20 SF	2 Locations; Additional Efflorescence
403	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	Floor	Chipping	62	N	N	0	N	N	Hall Perimeter
404	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W1	Flaking	34	N	N	0	Y - 110 SF Bulletin Boards, Posters	N	4 Locations; Additional Cracking
405	2630	1	1	H15	Circulation (Hallway)	Hallway from Fire Tower near Principal's Office to Classroom 105	W3	Flaking	14	N	N	0	Y - 90 SF Bulletin Boards, Posters	N	5 Locations; Flaking Includes Doors; Additional Cracking
406	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W2	Flaking	10	N	N	0	Y - 84 SF Bookcases, Posters	N	
407	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W3	Cracking	12	N	N	0	N	N	Additional Cracking
408	2630	1	1	H16	Circulation (Hallway)	Hallway from Nurse's Office to Classroom 101	W4	Flaking	11	N	N	0	Y - 120 SF File Cabinets, Posters	N	
409	2630	1	1	S11	Stairs	Fire Tower Stairwell near end of Gymnasium	Ceiling	Flaking	3	N	N	0	N	N	2 Locations
410	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	Floor	Chipping	1	N	N	0	N	N	
411	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Posters	N	
412	2630	1	1	S13	Stairs	Main Entrance Stairwell near Principal's Office	W4	Flaking	18	N	N	0	N	N	
413	2630	1	1	S15	Stairs	Fire Tower Stairwell across from Classroom 106	Ceiling	Flaking	24	N	N	0	N	N	
414	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W2	Cracking	6	N	N	0	N	N	
415	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W3	Flaking	6	N	N	0	N	N	Door Frame
416	2630	1	1	S16	Stairs	Stairwell next to Classroom 105	W4	Flaking	2	N	N	0	N	N	
417	2630	1	1	S17	Stairs	Fire Tower Stairwell across from Classroom 101	Ceiling	Flaking	4	N	N	0	N	N	
418	2630	1	0	001	Art - Elementary	Art Room	Ceiling	Cracking	15	N	N	0	N	N	4 Locations; Additional Holes
419	2630	1	0	001	Art - Elementary	Art Room	W1	Flaking	2	N	N	0	Y - 368 SF Cabinets	N	
420	2630	1	0	001	Art - Elementary	Art Room	W2	Chipping	1	N	N	0	Y - 224 SF Posters	N	
421	2630	1	0	001	Art - Elementary	Art Room	W3	Flaking	10	N	N	0	Y - 216 SF Shelves, Contents	N	3 Locations; Including Radiators; Additional Chipping

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
422	2630	1	0	001	Art - Elementary	Art Room	W4	Flaking	4	N	N	0	Y - 180 SF Bookcases, Posters, Contents	N	4 Locations; Additional Cracking
423	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
424	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
425	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
426	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
427	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
428	2630	1	0	003	Storage	Head Start Storage Room next to Fan Room No. 3	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
429	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W2	Flaking	26	N	N	0	N	N	
430	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W3	Flaking	16	N	N	0	N	N	
431	2630	1	0	005	Restrooms, Staff - Male	Building Engineer's Restroom next to Kindergarten Lunchroom	W4	Partially Inaccessible	0	N	N	0	Y - 180 SF Cabinets	N	
432	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Ceiling	Flaking	30	N	N	0	N	N	3 Locations; Additional Cracking, Chipping
433	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	Floor	Flaking	24	N	N	0	N	N	Additional Chipping; Damage Around Perimeter
434	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W2	Flaking	60	N	N	0	N	N	Entire Wall; Including Pipe Paint; Additional Cracking
435	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W3	Flaking	14	N	N	0	N	N	Additional Cracking
436	2630	1	0	006	Cafeteria (Dining Area)	Kindergarten Lunchroom	W4	Flaking	168	N	N	0	N	N	Additional Cracking
437	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	Ceiling	Cracking	1125	N	N	0	N	N	Entire Ceiling
438	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W2	Chipping	8	N	N	0	N	N	Chipping on Door Frame
439	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W3	Flaking	30	N	N	0	N	N	5 Locations; Window Sills 1-5
440	2630	1	0	014	Cafeteria (Dining Area)	Girls' Cafeteria	W4	Cracking	6	N	N	0	N	N	2 Locations
441	2630	1	0	015	Kitchen	Kitchen	W2	Partially Inaccessible	0	N	N	0	Y - 96 SF Freezer	N	
442	2630	1	0	015	Kitchen	Kitchen	W3	Partially Inaccessible	0	N	N	0	Y - 21 SF Freezer	N	
443	2630	1	0	015	Kitchen	Kitchen	W4	Cracking	8	N	N	0	Y - 60 SF Contents	N	2 Locations
444	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	Ceiling	Chipping	8	N	N	0	N	N	2 Locations
445	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W1	Cracking	12	N	N	0	Y - 12 SF Posters	N	3 Locations
446	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W3	Flaking	28	N	N	0	N	N	4 Locations

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
447	2630	1	0	016	Cafeteria (Dining Area)	Boys' Cafeteria	W4	Partially Inaccessible	0	N	N	0	Y - 32 SF Posters	N	
448	2630	1	0	021	Resource Room	Room B-10 After School Program	W1	Chipping	3	N	N	0	Y - 110 SF Desks, Posters	N	
449	2630	1	0	021	Resource Room	Room B-10 After School Program	W2	Flaking	7	N	N	0	Y - 120 SF Desks, Posters	N	3 Locations
450	2630	1	0	021	Resource Room	Room B-10 After School Program	W3	Chipping	2	N	N	0	Y - 160 SF Desks, Posters	N	
451	2630	1	0	021	Resource Room	Room B-10 After School Program	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Desks, Posters	N	
452	2630	1	0	001A	Storage	Storage Closet next to Art Room	Ceiling	Flaking	8	N	N	0	Y - 36 SF Ductwork	N	
453	2630	1	0	001A	Storage	Storage Closet next to Art Room	W1	Flaking	3	N	N	0	N	N	
454	2630	1	0	001A	Storage	Storage Closet next to Art Room	W2	Flaking	14	N	N	0	Y - 112 SF Shelves	N	
455	2630	1	0	001A	Storage	Storage Closet next to Art Room	W3	Flaking	3	N	N	0	N	N	
456	2630	1	0	001A	Storage	Storage Closet next to Art Room	W4	Partially Inaccessible	0	N	N	0	Y - 112 SF Shelves	N	
457	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
458	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
459	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
460	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
461	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
462	2630	1	0	001B	Storage	Storage Room between Storage Room next to Art Room and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
463	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W1	Flaking	10	N	N	0		N	
464	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W2	Flaking	50	N	N	0	Y - 112 SF Shelves	N	
465	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W3	Flaking	30	N	N	0	Y - 60 SF Shelves	N	

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
466	2630	1	0	021A	Storage	Storage Room next to Rooms B-9 and B-10	W4	Flaking	20	N	N	0	Y - 112 SF Shelves	N	
467	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W1	Chipping	10	N	N	0	N	N	Door Frame/Door
468	2630	1	0	021B	Circulation (Hallway)	Entrance Area between Rooms B-9 and B-10	W3	Chipping	3	N	N	0	N	N	3 Locations
469	2630	1	0	021C	Storage	Room B-10 Storage Closet	Ceiling	Holes	2	N	N	0	N	N	
470	2630	1	0	021C	Storage	Room B-10 Storage Closet	W2	Partially Inaccessible	0	N	N	0	Y - 16 SF Contents	N	
471	2630	1	0	021C	Storage	Room B-10 Storage Closet	W3	Flaking	72	N	N	0	Y - 36 SF Contents	N	Entire Wall
472	2630	1	0	021C	Storage	Room B-10 Storage Closet	W4	Flaking	48	N	N	0	Y - 16 SF Contents	N	Entire Wall
473	2630	1	0	021D	Primary	Classroom B-9	Ceiling	Flaking	30	N	N	0	N	N	Including Pipe Paint
474	2630	1	0	021D	Primary	Classroom B-9	Floor	Chipping	20	N	N	0	N	N	5 Locations; Chipping Around Perimeter
475	2630	1	0	021D	Primary	Classroom B-9	W1	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks	N	
476	2630	1	0	021D	Primary	Classroom B-9	W2	Flaking	30	N	N	0	Y - 60 SF Tables, Posters	N	
477	2630	1	0	021D	Primary	Classroom B-9	W3	Chipping	2	N	N	0	Y - 168 SF Tables, Posters	N	2 Locations
478	2630	1	0	021D	Primary	Classroom B-9	W4	Partially Inaccessible	0	N	N	0	Y - 84 SF Posters	N	
479	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
480	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
481	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
482	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
483	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
484	2630	1	0	021E	Storage	Storage Room between Storage Room next to Rooms B-9 and B-10 and Fire Tower Stairwell	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	
485	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	Ceiling	Partially Inaccessible	0	N	N	0	Y - 150 SF Ductwork	N	
486	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W2	Flaking	40	N	N	0	N	N	Additional Cracking

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
487	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W3	Flaking	20	N	N	0	N	N	Additional Cracking
488	2630	1	0	H01	Circulation (Hallway)	Hallway from Boys' Restroom to Rooms B-9 and B-10	W4	Flaking	68	N	N	0	N	N	Additional Cracking
489	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Ceiling	Cracking	7	N	N	0	N	N	
490	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	Floor	Chipping	10	N	N	0	N	N	Chipping Around Perimeter
491	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W1	Flaking	4	N	N	0	N	N	
492	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W3	Flaking	8	N	N	0	N	N	
493	2630	1	0	H02	Circulation (Hallway)	Hallway between Building Engineer's Storage Area and Boys' Cafeteria	W4	Cracking	8	N	N	0	N	N	
494	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Ceiling	Partially Inaccessible	0	N	N	0	Y - 330 SF Ductwork	N	
495	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	Floor	Flaking	210	N	N	0	N	N	Additional Chipping; Damage Around Perimeter
496	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W2	Flaking	8	N	N	0	N	N	4 Locations
497	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W3	Flaking	6	N	N	0	N	N	3 Locations; Including Pipe Paint; Additional Cracking
498	2630	1	0	H03	Circulation (Hallway)	Hallway from Girls' Restroom to Storage Room next to Art Room	W4	Flaking	37	N	N	0	N	N	6 Locations; Additional Cracking
499	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Ceiling	Flaking	12	N	N	0	Y - 280 SF Ductwork	N	Including Pipe Paint
500	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	Floor	Flaking	10	N	N	0	N	N	Additional Chipping
501	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W3	Flaking	30	Y	N	0	N	Y - 12 SF	2 Locations; Additional Efflorescence
502	2630	1	0	H04	Circulation (Hallway)	Hallway between Girls' Cafeteria and Kindergarten Lunchroom	W4	Flaking	6	N	N	0	N	N	
503	2630	1	0	S06	Stairs	Stairwell next to Kindergarten Lunchroom	W1	Flaking	6	N	N	0	N	N	

