

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6380	2	3	318B	Student Restrooms - Male (4-12)	Boy's Restroom by Fire Tower Stairs near Classroom 309	Ceiling	Flaking paint	40	Y				N	
2	6380	1	3	320	Student Restrooms - Male (4-12)	Boy's Restroom near Classroom 303	W3	Flaking paint	30	Y				N	
3	6380	1	3	301	Primary	Classroom 301	W1	Cracking paint above blackboard	10	N				N	
4	6380	1	3	301	Primary	Classroom 301	W2	Chipping paint at entrance	2	N				N	
5	6380	1	3	301	Primary	Classroom 301	W3	Flaking paint	30	Y	Floor, sill	10		N	
6	6380	1	3	301A	Storage	Classroom 301 - Coat Closet	Ceiling	Flaking paint and efflorescence	5	N				N	
7	6380	1	3	301A	Storage	Classroom 301 - Coat Closet	W1	Flaking paint at coatrack	5	N				N	
8	6380	1	3	301A	Storage	Classroom 301 - Coat Closet	W3	Flaking paint	2	N				N	
9	6380	1	3	301B	Storage	Classroom 301 - Teacher's Closet	W2	Flaking paint and efflorescence	30	N	Shelves	3	Books, shelves	N	
10	6380	1	3	301B	Storage	Classroom 301 - Teacher's Closet	W3	Cracking paint	10	N				N	
11	6380	1	3	302	Primary	Classroom 302	Ceiling	Flaking paint	15	Y				N	
12	6380	1	3	302	Primary	Classroom 302	W1	Flaking paint near entrance	2	N				N	
13	6380	1	3	302	Primary	Classroom 302	W3	Flaking paint	15	Y				N	
14	6380	1	3	302B	Storage	Classroom 302 - Teacher's Closet	W4	Flaking paint and efflorescence	50	N			Books, shelves	N	
15	6380	1	3	303	Primary	Classroom 303	W2	Chipping paint near entrance	2	N				N	
16	6380	1	3	303	Primary	Classroom 303	W3	Flaking paint near closet	5	N				N	
17	6380	1	3	303A	Storage	Classroom 303 - Coat Closet	W3	Flaking paint below coatrack	10	N				N	
18	6380	1	3	304	Primary	Classroom 304	W1	Flaking paint above and below blackboard	30	N			Many posters	N	
19	6380	1	3	305A	Primary	Classroom 305A - Computer Lab	W1	Flaking paint	50	N			Desks	N	
20	6380	1	3	305A	Primary	Classroom 305A - Computer Lab	W2	Flaking paint and debris	15	N	Window sill	15		N	
21	6380	1	3	305A	Primary	Classroom 305A - Computer Lab	W4	Flaking paint and debris	15	N	Window sill	15		N	
22	6380	1	3	306	Primary	Classroom 306	W3	Spalling paint	5	Y			Cabinet	N	
23	6380	1	3	306A	Storage	Classroom 306 - Coat Closet	Ceiling	Flaking paint and efflorescence	3	Y			Supplies	N	
24	6380	1	3	306A	Storage	Classroom 306 - Coat Closet	W2	Flaking paint and efflorescence	3	Y			Supplies	N	
25	6380	1	3	307	Primary	Classroom 307	W1	Flaking paint	30	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
26	6380	1	3	307	Primary	Classroom 307	W3	Flaking paint and debris	15	N	Floor, sill	2		N	
27	6380	1	3	307A	Storage	Classroom 307 - Coat Closet	Ceiling	Flaking paint and efflorescence	5	Y				N	
28	6380	1	3	308	Primary	Classroom 308	Ceiling	Flaking paint by windows	5	Y				N	
29	6380	1	3	308	Primary	Classroom 308	W2	Chipping paint by entrance	2	N				N	
30	6380	1	3	309	Primary	Classroom 309	W2	Chipping paint	2	N				N	
31	6380	1	3	309	Primary	Classroom 309	W3	Flaking paint and debris	5	Y	Window sill	1		N	
32	6380	1	3	309A	Storage	Classroom 309 - Coat Closet	W4	Flaking paint and damaged plaster	1	N				Y	
33	6380	1	3	309B	Storage	Classroom 309 - Teacher's Closet	W2	Flaking paint	5	Y				N	
34	6380	1	3	309B	Storage	Classroom 309 - Teacher's Closet	W3	Flaking paint	5	Y				N	
35	6380	2	3	310A	Primary	Classroom 310	W1	Flaking paint at door casing	5	N				N	
36	6380	2	3	311	Primary	Classroom 311	W1	Flaking paint at door casing and around door	10	N				N	
37	6380	2	3	312	Primary	Classroom 312	W1	Flaking paint at door casing	5	N				N	
38	6380	2	3	313	Primary	Classroom 313	W1	Flaking paint at door casing	5	N				N	
39	6380	2	3	314	Primary	Classroom 314	W1	Flaking paint at door casing	5	N				N	
40	6380	1	3	S304	Stairs	Fire Tower Stairs near Classroom 301	W4	Flaking paint at doors	20	N				N	
41	6380	1	3	316	Student Restrooms - Female (4-12)	Girl's Restroom near Classroom 307	Ceiling	Flaking paint	2	N				N	
42	6380	1	3	316	Student Restrooms - Female (4-12)	Girl's Restroom near Classroom 307	W4	Flaking paint	2	N				N	
43	6380	2	3	319	Student Restrooms - Female (4-12)	Girl's Restroom near Classroom 310	Ceiling	Flaking paint	40	Y				N	
44	6380	1	3	H301	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W1	Flaking paint outside 306 & 304	20	N				N	
45	6380	1	3	H302	Circulation (Hallway)	Hallway from Fire Tower Stairs by Classroom 301 to Stairwell near Classroom 303	Ceiling	Flaking paint	200	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
46	6380	1	3	H302	Circulation (Hallway)	Hallway from Fire Tower Stairs by Classroom 301 to Stairwell near Classroom 303	W2	Flaking paint	20	N			Posters	N	
47	6380	1	3	H302	Circulation (Hallway)	Hallway from Fire Tower Stairs by Classroom 301 to Stairwell near Classroom 303	W4	Flaking paint	20	N			Posters	N	
48	6380	1	3	H303	Circulation (Hallway)	Hallway from Fire Tower Stairs near Classroom 309 to Classroom 308	W2	Flaking paint and debris across from fire tower	10	N	Floor	1		N	
49	6380	1	3	H303	Circulation (Hallway)	Hallway from Fire Tower Stairs near Classroom 309 to Classroom 308	W4	Flaking paint	10	N			Posters	N	
50	6380	1	3	BC3-6	Storage	Left Side Book Storage across from Classroom 304	W2	Flaking paint	5				Supplies	N	
51	6380	1	3	BC3-6	Storage	Left Side Book Storage across from Classroom 304	W3	Flaking paint	5				Supplies	N	
52	6380	1	3	BC3-6	Storage	Left Side Book Storage across from Classroom 304	W4	Flaking paint	5				Supplies	N	
53	6380	1	3	BC3-3	Storage	Left Side Book Storage across from Classroom 307	W2	Flaking paint	5	N			Supplies, Books	N	
54	6380	1	3	BC3-5	Storage	Middle Book Storage across from Classroom 304	W2	Flaking paint	5				Supplies	N	
55	6380	1	3	BC3-2	Storage	Middle Book Storage across from Classroom 307	W4	Flaking paint	5	N			Supplies, Books	N	
56	6380	1	3	BC3-4	Storage	Right Side Book Storage across from Classroom 304	W4	Flaking paint at wall and pipe	10	N			Supplies	N	
57	6380	1	3	BC3-1	Storage	Right Side Book Storage across from Classroom 307	W2	Flaking paint	5	N			Supplies, Books	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
58	6380	1	3	BC3-1	Storage	Right Side Book Storage across from Classroom 307	W4	Flaking paint	5	N			Supplies, Books	N	
59	6380	1	3	S302	Stairs	Stairwell across from Classroom 308	W2	Flaking paint	5	N				N	
60	6380	1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom near Classroom 203	Ceiling	Flaking paint	20	Y				N	
61	6380	1	2	213	Student Restrooms - Male (4-12)	Boy's Restroom near Classroom 203	W3	Flaking paint	20	N				N	
62	6380	1	2	201	Primary	Classroom 201	W1	Flaking paint	10	N				N	
63	6380	1	2	201	Primary	Classroom 201	W3	Flaking paint	20	N				N	
64	6380	1	2	202	Primary	Classroom 202	Ceiling	Flaking paint	5	N				N	
65	6380	1	2	202	Primary	Classroom 202	W2	Flaking paint near entrance	20	N				N	
66	6380	1	2	202	Primary	Classroom 202	W3	Flaking paint around windows	20	Y	Sill	1		N	
67	6380	1	2	202	Primary	Classroom 202	W4	Flaking paint near entrance	10	N				N	
68	6380	1	2	202A	Storage	Classroom 202 - Coat Closet	W1	Flaking paint	20	N				N	
69	6380	1	2	202A	Storage	Classroom 202 - Coat Closet	W2	Flaking paint	5	N				N	
70	6380	1	2	202A	Storage	Classroom 202 - Coat Closet	W3	Flaking paint	10	N				N	
71	6380	1	2	202B	Storage	Classroom 202 - Teacher's Closet	W3	Flaking paint	2	N			Books, shelves	N	
72	6380	1	2	202B	Storage	Classroom 202 - Teacher's Closet	W4	Flaking paint	5	N				N	
73	6380	1	2	203	Primary	Classroom 203	Ceiling	Flaking paint	5	N				N	
74	6380	1	2	203	Primary	Classroom 203	W1	Flaking paint near entrance	2	N				N	
75	6380	1	2	203	Primary	Classroom 203	W3	Flaking paint around windows	5	N				N	
76	6380	1	2	203A	Storage	Classroom 203 - Coat Closet	W1	Flaking paint at coatrack	2	N				N	
77	6380	1	2	203A	Storage	Classroom 203 - Coat Closet	W3	Flaking paint	10	N				N	
78	6380	1	2	203B	Storage	Classroom 203 - Teacher's Closet	W3	Flaking paint and efflorescence	10	N			Books, shelves	N	
79	6380	1	2	204	Primary	Classroom 204	Ceiling	Damaged plaster by window 4	1	N				N	
80	6380	1	2	204	Primary	Classroom 204	W3	Flaking paint above window	5	Y				N	
81	6380	1	2	204	Primary	Classroom 204	W4	Flaking paint	5	N				N	
82	6380	1	2	204B	Storage	Classroom 204 - Teacher's Closet	Ceiling	Flaking paint and efflorescence	50	N			Shelves, Books	N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
83	6380	1	2	204B	Storage	Classroom 204 - Teacher's Closet	W1	Flaking paint by ceiling	10	N			Shelves, Books	N	
84	6380	1	2	204B	Storage	Classroom 204 - Teacher's Closet	W2	Flaking paint by ceiling	10	N			Shelves, Books	N	
85	6380	1	2	204B	Storage	Classroom 204 - Teacher's Closet	W3	Flaking paint by ceiling	10	N			Shelves, Books	N	
86	6380	1	2	204B	Storage	Classroom 204 - Teacher's Closet	W4	Flaking paint by ceiling	10	N			Shelves, Books	N	
87	6380	1	2	206	Primary	Classroom 206	Ceiling	Flaking paint	20	N				N	
88	6380	1	2	206	Primary	Classroom 206	W1	Flaking paint near entrance	2	N				N	
89	6380	1	2	206	Primary	Classroom 206	W3	Flaking paint by window 4	2	N			Supplies	Y	
90	6380	1	2	206A	Storage	Classroom 206 - Coat Closet	W1	Flaking paint	10	N				N	
91	6380	1	2	206A	Storage	Classroom 206 - Coat Closet	W3	Flaking paint	20	N				N	
92	6380	1	2	206B	Storage	Classroom 206 - Teacher's Closet	W2	Flaking paint by ceiling	2	N			Supplies	N	
93	6380	1	2	207	Primary	Classroom 207	Ceiling	Flaking paint at window 4	2	Y				Y	
94	6380	1	2	207	Primary	Classroom 207	W1	Flaking paint near entrance and above blackboard	20	N			Posters	N	
95	6380	1	2	207	Primary	Classroom 207	W3	Flaking paint above windows	2	Y				N	
96	6380	1	2	207A	Storage	Classroom 207 - Coat Closet	W1	Flaking paint	10	N			Supplies	N	
97	6380	1	2	207A	Storage	Classroom 207 - Coat Closet	W3	Flaking paint	10	N			Supplies	N	
98	6380	1	2	208	Primary	Classroom 208	Ceiling	Flaking paint	5	N				N	
99	6380	1	2	208	Primary	Classroom 208	W1	Flaking paint near entrance	1	N			Posters	N	
100	6380	1	2	208	Primary	Classroom 208	W3	Flaking paint below windows	10	N			Desks	N	
101	6380	1	2	208	Primary	Classroom 208	W4	Flaking paint near entrance	1	N				Y	
102	6380	1	2	208A	Storage	Classroom 208 - Coat Closet	W1	Flaking paint	10	N				N	
103	6380	1	2	208A	Storage	Classroom 208 - Coat Closet	W3	Flaking paint	10	N				N	
104	6380	1	2	208B	Storage	Classroom 208 - Teacher's Closet	Ceiling	Damaged plaster	1	N				Y	
105	6380	1	2	209	Primary	Classroom 209	Ceiling	Flaking paint and plaster damage by window	1	N				Y	
106	6380	1	2	209A	Storage	Classroom 209 - Coat Closet	Ceiling	Flaking paint	5	N				N	
107	6380	1	2	209A	Storage	Classroom 209 - Coat Closet	W1	Flaking paint and debris on floor	10	N	Floor	10		N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
108	6380	1	2	209A	Storage	Classroom 209 - Coat Closet	W3	Flaking paint	10	N				N	
109	6380	1	2	S204	Stairs	Fire Tower Stairs near Classroom 201	Ceiling	Flaking paint	50	B				N	
110	6380	1	2	S204	Stairs	Fire Tower Stairs near Classroom 201	W4	Flaking paint at doors	20	N				N	
111	6380	1	2	210	Student Restrooms - Female (4-12)	Girl's Restroom near Classroom 207	Ceiling	Flaking paint	2	N				N	
112	6380	1	2	H201	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	Ceiling	Flaking paint outside 205	5	N				N	
113	6380	1	2	H201	Circulation (Hallway)	Hallway from Boy's Restroom to Girl's Restroom	W3	Flaking paint across from 205	10	N				N	
114	6380	1	2	H202	Circulation (Hallway)	Hallway from Fire Tower Stairs by Classroom 201 to Stairwell near Classroom 203	W2	Flaking paint outside 202	10	N				N	
115	6380	1	2	H202	Circulation (Hallway)	Hallway from Fire Tower Stairs by Classroom 201 to Stairwell near Classroom 203	W4	Flaking paint across from 202	5	N				N	
116	6380	2	2	IMC-1	IMC (Library)	IMC/Library	W1	Flaking paint in "Quiet Area"	5	N			Bleacher-type seating area	N	
117	6380	2	2	IMC-1	IMC (Library)	IMC/Library	W3	Flaking paint in "Quiet Area"	5	N			Bleacher-type seating area	N	
118	6380	1	2	BC2-3	Storage	Left Side Book Storage across from Classroom 207	W4	Gouges in paint	2	N				N	
119	6380	1	2	BC2-5	Storage	Middle Book Storage across from Classroom 204	W4	Gouges in paint	2	N			Books, shelves	N	
120	6380	1	2	205a	Storage	Projection Room	W1	Flaking paint	10	N				N	
121	6380	1	2	205a	Storage	Projection Room	W2	Flaking paint	10	N				N	
122	6380	1	2	205a	Storage	Projection Room	W3	Flaking paint	20	N				N	
123	6380	1	2	205a	Storage	Projection Room	W4	Flaking paint	10	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
124	6380	1	2	BC2-4	Storage	Right Side Book Storage across from Classroom 204	W4	Flaking paint at pipe	5	N	Floor	1	Supplies	N	
125	6380	1	2	BC2-1	Storage	Right Side Book Storage across from Classroom 207	W4	Cracking paint	2	N				N	
126	6380	1	2	205	Administrative Office	Room 205 Therapist's Office	Ceiling	Flaking paint and efflorescence	10	N				N	
127	6380	1	2	205	Administrative Office	Room 205 Therapist's Office	W3	Flaking paint and efflorescence	30	N				N	
128	6380	1	2	212A	Restrooms, Staff - Male/Female	Room 205 Therapist's Office - Restroom	W3	Flaking paint near ceiling	5	N				N	
129	6380	1	2	S203	Stairs	Stairwell near Classroom 203 (lower side)	W3	Flaking paint	5	N				N	
130	6380	1	2	212B	Storage	Storage Room next to Room 205	Ceiling	Flaking paint	40	N			Supplies	N	
131	6380	1	2	212B	Storage	Storage Room next to Room 205	W4	Flaking paint	10	N	Floor	2	Supplies	N	
132	6380	1	1	112	Auditorium	Auditorium	W1	Flaking paint	10	N				N	
133	6380	1	1	112	Auditorium	Auditorium	W2	Flaking paint	10	N				N	
134	6380	1	1	112	Auditorium	Auditorium	W4	Flaking paint	20	N				N	
135	6380	1	1	112C	Stage	Auditorium Stage	Ceiling	Flaking paint	10	N				N	
136	6380	1	1	112C	Stage	Auditorium Stage	W3	Flaking paint and debris behind wood stage wall	15	N	Floor, radiator	15	Wood stage wall	N	
137	6380	1	1	112C	Stage	Auditorium Stage	W4	Flaking paint	5	N				N	
138	6380	1	1	112A	Storage	Auditorium Storage Left Side of Stage	Ceiling	Efflorescence at ceiling	10	Y				N	
139	6380	1	1	112A	Storage	Auditorium Storage Left Side of Stage	W4	Flaking paint at wall and damaged plaster	2	N				Y	
140	6380	1	1	112B	Storage	Auditorium Storage Right Side of Stage	W3	Flaking paint and debris behind wheelchair lift	10	N	Floor	10	Wheelchair lift	N	
141	6380	1	1	101	Primary	Classroom 101	W3	Flaking paint above and below windows	5	Y	Sill	1	Supplies	N	
142	6380	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restrooms	W2	Flaking paint	10	N				N	
143	6380	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restrooms	W3	Flaking paint above windows and at pipe	5	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
144	6380	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restrooms	W4	Flaking paint	5	N				N	
145	6380	1	1	101C	Storage	Classroom 101 Storage Room in Far Rear	W4	Flaking paint	20	N			Supplies	N	
146	6380	1	1	103	Primary	Classroom 103	Ceiling	Damaged plaster	1	N				Y	
147	6380	1	1	103	Primary	Classroom 103	W1	Flaking paint above closet and by entrance	5	N				N	
148	6380	1	1	103B	Storage	Classroom 103 Coat Closet	W2	Flaking paint	10	N				N	
149	6380	1	1	103B	Storage	Classroom 103 Coat Closet	W3	Flaking paint	10	N				N	
150	6380	1	1	104	Primary	Classroom 104	Ceiling	Flaking paint	10	N				N	
151	6380	1	1	104	Primary	Classroom 104	W1	Flaking paint by entrance door and PA speaker	10	N				N	
152	6380	1	1	104	Primary	Classroom 104	W3	Flaking paint	10	N				N	
153	6380	1	1	104	Primary	Classroom 104	W4	Flaking paint	1	N				N	
154	6380	1	1	106	Primary	Classroom 106	W1	Flaking paint near entrance and by Clock	5	N				N	
155	6380	1	1	106	Primary	Classroom 106	W2	Flaking paint by soap dispenser	2	N				N	
156	6380	1	1	106	Primary	Classroom 106	W3	Flaking paint at window sill	2	N				N	
157	6380	1	1	106	Primary	Classroom 106	W4	Flaking paint near entrance and below blackboard	8	N				N	
158	6380	1	1	106B	Storage	Classroom 106 Coat Closet	Ceiling	Flaking paint	5	N				N	
159	6380	1	1	106B	Storage	Classroom 106 Coat Closet	W1	Flaking paint	5	N				N	
160	6380	1	1	106B	Storage	Classroom 106 Coat Closet	W3	Flaking paint	5	N				N	
161	6380	1	1	106B	Storage	Classroom 106 Coat Closet	W4	Flaking paint	5	N				N	
162	6380	1	1	106A	Student Restrooms - Male/Female (Classroom)	Classroom 106 Restroom	W3	Flaking paint at radiator	3	N				N	
163	6380	1	1	107	Primary	Classroom 107	Ceiling	Damaged plaster	5	N				Y	
164	6380	1	1	107	Primary	Classroom 107	W1	Flaking paint by door and below whiteboard	5	N				N	
165	6380	1	1	107	Primary	Classroom 107	W2	Flaking paint by entrance	2	N				N	
166	6380	1	1	107	Primary	Classroom 107	W3	Flaking paint left of windows	5	N				N	



Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
167	6380	1	1	107	Primary	Classroom 107	W4	Cracking paint	5	N				N	
168	6380	1	1	107A	Storage	Classroom 107 - Coat Closet	W1	Flaking paint	5	N				N	
169	6380	1	1	105	Administrative Office	Counselor's Office across from Auditorium	Ceiling	Flaking paint	20	N				N	
170	6380	1	1	105	Administrative Office	Counselor's Office across from Auditorium	W1	Flaking paint by clock	2	N				N	
171	6380	1	1	113A	Equipment Storage	Custodial Closet next to Nurse's Restroom	Ceiling	Damaged plaster	1	N				Y	
172	6380	1	1	S104	Stairs	Fire Tower Stairs near Classroom 101	Ceiling	Flaking paint	200	N				N	
173	6380	1	1	S104	Stairs	Fire Tower Stairs near Classroom 101	W1	Flaking paint	200	N				N	
174	6380	1	1	S104	Stairs	Fire Tower Stairs near Classroom 101	W2	Flaking paint	200	N				N	
175	6380	1	1	S104	Stairs	Fire Tower Stairs near Classroom 101	W3	Flaking paint	200	N				N	
176	6380	1	1	110	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	Floor	Flaking paint	20	N				N	
177	6380	1	1	110	Student Restrooms - Female (4-12)	Girl's Restroom next to Classroom 106	W3	Flaking paint above window	1	Y				N	
178	6380	1	1	H103	Circulation (Hallway)	Hallway from Classroom 107 to Men's Restroom	W2	Flaking paint	20	N			Posters	N	
179	6380	1	1	H103	Circulation (Hallway)	Hallway from Classroom 107 to Men's Restroom	W4	Flaking paint at door to S101	20	N			Posters	N	
180	6380	1	1	H101B	Circulation (Hallway)	Hallway from Main Lobby to Nurse's Restroom	W3	Flaking paint	40	N			Posters	N	
181	6380	1	1	H101B	Circulation (Hallway)	Hallway from Main Lobby to Nurse's Restroom	W1	Flaking paint	40	N			Posters	N	
182	6380	1	1	H102	Circulation (Hallway)	Hallway from Nurse's Office to Women's Restroom	W2	Flaking paint	20	N				N	
183	6380	1	1	H102	Circulation (Hallway)	Hallway from Nurse's Office to Women's Restroom	W4	Flaking paint	20	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
184	6380	1	1	BC1-6	Storage	Left Side Book Storage across from Classroom 104	W3	Flaking paint	5				Supplies	N	
185	6380	1	1	BC1-6	Storage	Left Side Book Storage across from Classroom 104	W4	Flaking paint	5				Supplies	N	
186	6380	1	1	BC1-3	Storage	Left Side Book Storage across from Classroom 106	W2	Flaking paint at pipe	2	N			Supplies	N	
187	6380	1	1	H101	Circulation (Hallway)	Main Lobby from Main Office to Counselor's Office	W1	Flaking paint	20	N			Posters	N	
188	6380	1	1	H101	Circulation (Hallway)	Main Lobby from Main Office to Counselor's Office	W3	Flaking paint	20	N			Posters	N	
189	6380	1	1	105C	Administrative Office	Main Office	Ceiling	Flaking paint below heater	10	N				N	
190	6380	1	1	105C	Administrative Office	Main Office	W2	Flaking paint by window	5	N				N	
191	6380	1	1	105C	Administrative Office	Main Office	W4	Flaking paint below heater	5	N				N	
192	6380	1	1	105E	Storage	Main Office - Closet next to Storage Room	W3	Cracking paint	10	N			Many supplies, shelves	N	
193	6380	1	1	105E	Storage	Main Office - Closet next to Storage Room	W4	Damaged plaster	1	N			Many supplies, shelves	Y	
194	6380	1	1	105D	Storage	Main Office - Storage Room	Ceiling	Flaking paint	10	N			Many supplies, shelves	N	
195	6380	1	1	105D	Storage	Main Office - Storage Room	W2	Flaking paint	20	N			Many supplies, shelves	N	
196	6380	1	1	105D	Storage	Main Office - Storage Room	W3	Flaking paint	20	N			Many supplies, shelves	N	
197	6380	1	1	109	Restrooms, Staff - Male	Men's Restroom near Classroom 108	Ceiling	Flaking paint	5	N				N	
198	6380	1	1	109	Restrooms, Staff - Male	Men's Restroom near Classroom 108	W4	Flaking paint	5	N				N	
199	6380	1	1	109	Restrooms, Staff - Male	Men's Restroom near Classroom 108	W1	Flaking paint	2	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
200	6380	1	1	BC1-2	Storage	Middle Book Storage across from Classroom 106	W2	Flaking paint	2	N			Supplies	N	
201	6380	1	1	BC1-2	Storage	Middle Book Storage across from Classroom 106	W4	Flaking paint	2	N			Supplies	N	
202	6380	1	1	114	Administrative Office	Nurse's Office	W1	Flaking paint and gouges at door and door casing. Flaking paint at baseboards	20	N				N	
203	6380	1	1	114	Administrative Office	Nurse's Office	W2	Flaking paint at sink. Flaking paint at baseboards	10	N				N	
204	6380	1	1	114	Administrative Office	Nurse's Office	W3	Flaking paint by windows and at window sill. flaking paint at baseboard.	15	N				N	
205	6380	1	1	114	Administrative Office	Nurse's Office	W4	Flaking paint on baseboard	10	N				N	
206	6380	1	1	113	Student Restrooms - Male/Female	Nurse's Restroom (former Boy's Restroom)	Ceiling	Flaking paint	20	Y				N	
207	6380	1	1	111	Administrative Office	Principal's Office	W4	Flaking paint	5	N				N	
208	6380	1	1	111A	Restrooms, Staff - Female	Principal's Office - Restroom	Ceiling	Flaking paint	5	N				N	
209	6380	1	1	111A	Restrooms, Staff - Female	Principal's Office - Restroom	W2	Flaking paint	10	N				N	
210	6380	1	1	111A	Restrooms, Staff - Female	Principal's Office - Restroom	W3	Flaking paint	10	N				N	
211	6380	1	1	111A	Restrooms, Staff - Female	Principal's Office - Restroom	W4	Flaking paint	1	N				N	
212	6380	1	1	BC1-4	Storage	Right Side Book Storage across from Classroom 104	W4	Flaking paint at wall and pipe	10	N			Supplies	N	
213	6380	1	1	BC1-1	Storage	Right Side Book Storage across from Classroom 106	W4	Flaking paint	2	N			Supplies	N	
214	6380	1	1	S102	Stairs	Stairwell Across from Classroom 107 (lower side)	Ceiling	Flaking paint	10	N				N	
215	6380	1	1	S102	Stairs	Stairwell Across from Classroom 107 (lower side)	W3	Flaking paint	10	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
216	6380	1	1	S103	Stairs	Stairwell Across from Nurse's Office (lower side)	W1	Flaking paint	10	N				N	
217	6380	1	1	S103	Stairs	Stairwell Across from Nurse's Office (lower side)	W2	Flaking paint	10	N				N	
218	6380	1	1	S103	Stairs	Stairwell Across from Nurse's Office (lower side)	W3	Flaking paint	10	N				N	
219	6380	1	1	S103	Stairs	Stairwell Across from Nurse's Office (lower side)	W4	Cracking paint	20	N				N	
220	6380	2	0	20	Student Restrooms - Male (4-12)	Boy's Restroom in Element 2 Area	Ceiling	Flaking paint at radiator cover	10	Y				N	
221	6380	1	0	B2	Music	Classroom B-1 Strings Room	W1	Flaking paint	10	N			Instruments	N	
222	6380	1	0	B2	Music	Classroom B-1 Strings Room	W2	Flaking paint	10	N			Instruments	N	
223	6380	1	0	B2	Music	Classroom B-1 Strings Room	W3	Flaking paint	30	N				N	
224	6380	1	0	B2	Music	Classroom B-1 Strings Room	W4	Flaking paint	20	N				N	
225	6380	1	0	B6	Primary	Classroom B-6	W1	Flaking paint by door and in closet area	20	N			Posters, shelves, supplies	N	
226	6380	1	0	B6	Primary	Classroom B-6	W3	Flaking paint near W4 where pipe enters wall	2	N				N	
227	6380	1	0	B6	Primary	Classroom B-6	W4	Flaking paint below blackboard	5	N				N	
228	6380	1	0	B6A	Student Restrooms - Male/Female (Classroom)	Classroom B-6 Restroom	W3	Flaking paint	2	N				N	
229	6380	1	0	S001	Stairs	Fire Tower Stairs near Element 2 Boy's Restroom	Ceiling	Flaking paint	20	Y				N	
230	6380	1	0	11	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Flaking paint near ductwork and at light near entrance	100	N				N	
231	6380	1	0	11	Gymnasium - Intermediate Middle	Gymnasium	W3	Flaking paint toward W2 side of wall	5	N				N	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
232	6380	1	0	011B	Storage	Gymnasium Storage Room next to Gym Office	Ceiling	Damaged plaster	1	N				Y	
233	6380	1	0	H001	Circulation (Hallway)	Hallway from Band Room Area to Storage Room next to Classroom B-6	Ceiling	Flaking paint at center and by window	5	Y				N	
234	6380	1	0	H001	Circulation (Hallway)	Hallway from Band Room Area to Storage Room next to Classroom B-6	W1	Flaking paint	10	N				N	
235	6380	1	0	H001	Circulation (Hallway)	Hallway from Band Room Area to Storage Room next to Classroom B-6	W4	Flaking paint near exit	2	Y				N	
236	6380	1	0	H003	Circulation (Hallway)	Hallway from Storage Room next to Classroom B-6 to Element 2 Exit Doors near Boy's Restroom	Ceiling	Flaking paint	200	N				N	
237	6380	1	0	H003	Circulation (Hallway)	Hallway from Storage Room next to Classroom B-6 to Element 2 Exit Doors near Boy's Restroom	W2	Flaking paint	2	N				N	
238	6380	1	0	B3B	Storage	Instrument Storage Room at end of Hallway for Band Rooms	Ceiling	Flaking paint and damaged plaster	20	Y				Y	
239	6380	1	0	B3B	Storage	Instrument Storage Room at end of Hallway for Band Rooms	W3	Flaking paint and efflorescence	20	Y				N	
240	6380	1	0	B3	Music	Music Room B-3	W1	Flaking paint at door casing and wall	20	N				N	
241	6380	1	0	B3	Music	Music Room B-3	W3	Flaking paint	20	N				N	
242	6380	1	0	B3	Music	Music Room B-3	W4	Flaking paint	100	Y				Y	
243	6380	1	0	B4	Music	Music Room B-4	W1	Flaking paint at door casing	10	N				N	
244	6380	1	0	S003	Stairs	Stairwell across from School Store	Floor	Flaking paint at stair risers and baseboard/floor	55	N	Steps	2		N	
245	6380	1	0	S003	Stairs	Stairwell across from School Store	W1	Cracked paint	20	N				n	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
246	6380	1	0	B5	Storage	Storage Room between Building Engineer's Office Area and Band Rooms	W1	Flaking paint on door	10	N				N	
247	6380	1	0	B5	Storage	Storage Room between Building Engineer's Office Area and Band Rooms	W4	Flaking paint at pipe	5	N				N	
248	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	Ceiling	No Access							
249	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	Floor	No Access							
250	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	W1	No Access							
251	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	W2	No Access							
252	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	W3	No Access							
253	6380	1	0	S003A	Storage	Storage Room in Stairwell next to Gym (old store)	W4	No Access							
254	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	Ceiling	No Access							
255	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	Floor	No Access							
256	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	W1	No Access							
257	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	W2	No Access							
258	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	W3	No Access							
259	6380	1	0	S003B	Storage	Storage Room under Stairwell next to Gym	W4	No Access							
260	6380	1	0	H001A	Storage	Supply Closet in Hallway across from Boiler Room	Ceiling	Cracking paint at ceiling	2	N				N	

