

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	Ceiling	Flaking above missing ceiling tile	10	No	No	N/A	N/A	No	
2	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	Floor	Chipping, Flaking	10	No	No	N/A	N/A	No	
3	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	W1	Cracking	10	No	No	N/A	N/A	No	
4	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	W2	Cracking, Chipping on transite, Efflorescence behind toilets	63	No	No	N/A	N/A	Yes	
5	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	W3	Cracking	15	No	No	N/A	N/A	No	
6	2690	1	3	411	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	W4	Flaking on radiator, Efflorescence	55	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
7	2690	1	3	400	Primary	Classroom 400	Floor	N/A	N/A	No	Paint chips in corner of walls 1&4	1	Furniture	No	Limited inspection due to stored materials
8	2690	1	3	400	Primary	Classroom 400	W1	Cracking, Chipping, Gouge, Holes, paint has been stabilized on 2	25	No	No	N/A	Posters, Table	Yes	
9	2690	1	3	400	Primary	Classroom 400	W2	Cracking, Chipping, Flaking	31	No	No	N/A	Stored Materials	No	
10	2690	1	3	400	Primary	Classroom 400	W3	Chipping on wall and radiators, Holes on wall, paint has been stabilized, Holes behind radiator	52	No	No	N/A	Furniture	Yes	
11	2690	1	3	400	Primary	Classroom 400	W4	Cracking, Chipping on wall and metal pipe, Gouge, Holes, paint has been stabilized, Flaking on wall and metal pipe	15	No	No	N/A	Posters, Furniture	Yes	
12	2690	1	3	400A	Storage	Classroom 400 Closet	Ceiling	Hole above window	1	No	No	N/A	Shelves and Stored Materials	Yes	Limited inspection due to shelves and stored materials
13	2690	1	3	400A	Storage	Classroom 400 Closet	Floor	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to shelves and stored materials
14	2690	1	3	400A	Storage	Classroom 400 Closet	W1	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to shelves and stored materials
15	2690	1	3	400A	Storage	Classroom 400 Closet	W2	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to shelves and stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
16	2690	1	3	400A	Storage	Classroom 400 Closet	W3	Chipping on radiator, Flaking behind radiator	4	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to shelves and stored materials
17	2690	1	3	400A	Storage	Classroom 400 Closet	W4	Cracking, Chipping	4	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to shelves and stored materials
18	2690	1	3	401	Primary	Classroom 401	W1	Chipping, Hole, Flaking on old speaker	3	No	No	N/A	Posters	No	
19	2690	1	3	401	Primary	Classroom 401	W2	Chipping	3	No	No	N/A	Posters	No	
20	2690	1	3	401	Primary	Classroom 401	W3	Flaking on wall and behind radiator	21	No	No	N/A	Posters	No	
21	2690	1	3	401	Primary	Classroom 401	W4	Hole	1	No	No	N/A	Posters	Yes	
22	2690	1	3	401A	Storage	Classroom 401 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
23	2690	1	3	401A	Storage	Classroom 401 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
24	2690	1	3	401A	Storage	Classroom 401 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
25	2690	1	3	401A	Storage	Classroom 401 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
26	2690	1	3	401A	Storage	Classroom 401 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
27	2690	1	3	401A	Storage	Classroom 401 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Teacher refused access stating it was her "private closet"
28	2690	1	3	402	Primary	Classroom 402	W1	Chipping	14	No	No	N/A	Posters	No	
29	2690	1	3	402	Primary	Classroom 402	W2	Cracking, Chipping, Hole, Flaking	32	No	No	N/A	Furniture, Stored Materials	Yes	
30	2690	1	3	402	Primary	Classroom 402	W3	Cracking, Chipping on radiators, Hole, paint has been stabilized, Flaking behind radiators, Efflorescence behind radiator	82	Yes	No	N/A	Furniture, Stored Materials	Yes	
31	2690	1	3	402	Primary	Classroom 402	W4	Cracking, Chipping, Flaking	23	No	No	N/A	Posters	No	
32	2690	1	3	402A	Storage	Classroom 402 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
33	2690	1	3	402A	Storage	Classroom 402 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
34	2690	1	3	402A	Storage	Classroom 402 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
35	2690	1	3	402A	Storage	Classroom 402 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
36	2690	1	3	402A	Storage	Classroom 402 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
37	2690	1	3	402A	Storage	Classroom 402 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
38	2690	1	3	403	Primary	Classroom 403	Ceiling	Flaking above 2nd closet entrance	1	No	No	N/A	N/A	No	
39	2690	1	3	403	Primary	Classroom 403	W1	Cracking in air shaft, Chipping, Hole, paint has been stabilized	6	No	No	N/A	Cabinet	Yes	
40	2690	1	3	403	Primary	Classroom 403	W3	Chipping on radiators, Hole, paint has been stabilized, Hole behind radiator, Flaking behind radiator	46	No	No	N/A	Tables	Yes	
41	2690	1	3	403	Primary	Classroom 403	W4	Chipping, Flaking on door	3	No	No	N/A	Shelf and Books	No	
42	2690	1	3	403A	Storage	Classroom 403 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
43	2690	1	3	403A	Storage	Classroom 403 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
44	2690	1	3	403A	Storage	Classroom 403 Closet	W1	Hole	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
45	2690	1	3	403A	Storage	Classroom 403 Closet	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
46	2690	1	3	403A	Storage	Classroom 403 Closet	W3	Cracking	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
47	2690	1	3	403A	Storage	Classroom 403 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
48	2690	1	3	404	Primary	Classroom 404	W1	Cracking, some in air shaft, Chipping, Holes	23	No	No	N/A	Posters	No	
49	2690	1	3	404	Primary	Classroom 404	W3	Chipping on radiators, Flaking behind radiators	80	No	No	N/A	N/A	No	
50	2690	1	3	404A	Storage	Classroom 404 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
51	2690	1	3	404A	Storage	Classroom 404 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
52	2690	1	3	404A	Storage	Classroom 404 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
53	2690	1	3	404A	Storage	Classroom 404 Closet	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
54	2690	1	3	404A	Storage	Classroom 404 Closet	W3	Cracking	10	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
55	2690	1	3	404A	Storage	Classroom 404 Closet	W4	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
56	2690	1	3	405	Primary	Classroom 405	W1	Cracking, Chipping, Flaking	34	No	No	N/A	N/A	Yes	
57	2690	1	3	405	Primary	Classroom 405	W2	Cracking, Chipping, Holes, paint has been stabilized	29	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
58	2690	1	3	405	Primary	Classroom 405	W3	Hole, paint has been stabilized, Flaking behind radiator	41	No	No	N/A	N/A	No	
59	2690	1	3	405A	Storage	Classroom 405 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
60	2690	1	3	405A	Storage	Classroom 405 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
61	2690	1	3	405A	Storage	Classroom 405 Closet	W1	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
62	2690	1	3	405A	Storage	Classroom 405 Closet	W2	Cracking	2	No	Debris on hooks	1	Stored Materials	No	Limited inspection due to stored materials
63	2690	1	3	405A	Storage	Classroom 405 Closet	W3	Cracking, Hole, paint has been stabilized	7	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
64	2690	1	3	405A	Storage	Classroom 405 Closet	W4	Cracking, Chipping, Flaking	11	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
65	2690	1	3	406	Primary	Classroom 406	W1	Cracking, Chipping, Holes, paint has been stabilized on 1, Flaking in air shaft	12	No	No	N/A	Posters	Yes	
66	2690	1	3	406	Primary	Classroom 406	W2	Cracking, Chipping on wall and metal pipe	8	No	No	N/A	Shelves and Stored Materials	No	
67	2690	1	3	406	Primary	Classroom 406	W3	Cracking behind shelf, Chipping on radiators, Hole, Efflorescence behind radiator	45	Yes	No	N/A	Stored Materials	Yes	
68	2690	1	3	406	Primary	Classroom 406	W4	Cracking, Chipping, Holes, paint has been stabilized	33	No	No	N/A	Desks	Yes	
69	2690	1	3	406A	Storage	Classroom 406 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
70	2690	1	3	406A	Storage	Classroom 406 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
71	2690	1	3	406A	Storage	Classroom 406 Closet	W1	Hole, paint has been stabilized	1	No	No	N/A	Stored Materials	Yes	
72	2690	1	3	406A	Storage	Classroom 406 Closet	W2	N/A	N/A	No	Debris on Hooks	1	Stored Materials	No	Limited inspection due to stored materials
73	2690	1	3	406A	Storage	Classroom 406 Closet	W3	Cracking, Hole, paint has been stabilized	7	No	No	N/A	Stored Materials	Yes	
74	2690	1	3	406A	Storage	Classroom 406 Closet	W4	Cracking, Holes, paint has been stabilized, Flaking	13	No	No	N/A	Stored Materials	Yes	
75	2690	1	3	407	Primary	Classroom 407	Ceiling	Flaking by entrance	2	No	No	N/A	N/A	No	
76	2690	1	3	407	Primary	Classroom 407	W1	Chipping	19	No	No	N/A	Posters	No	
77	2690	1	3	407	Primary	Classroom 407	W2	Chipping, Efflorescence	13	Yes	No	N/A	Posters, Shelves	Yes	
78	2690	1	3	407	Primary	Classroom 407	W3	Cracking, Chipping on radiators, Flaking behind radiators, Efflorescence	105	Yes	No	N/A	Posters, Shelves, Stored Materials	Yes	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
79	2690	1	3	407	Primary	Classroom 407	W4	Cracking, Chipping, Flaking	13	No	No	N/A	Furniture, Stored Materials	No	
80	2690	1	3	407A	Storage	Classroom 407 Closet	Floor	N/A	N/A	No	Debris in corner of walls 2&3	3	N/A	No	
81	2690	1	3	407A	Storage	Classroom 407 Closet	W2	Cracking, Holes, Flaking, Coat hooks pulling off wall	62	No	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
82	2690	1	3	407A	Storage	Classroom 407 Closet	W3	Cracking, Chipping on radiator, Efflorescence	17	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
83	2690	1	3	407A	Storage	Classroom 407 Closet	W4	Cracking, Flaking	15	No	No	N/A	N/A	No	
84	2690	1	3	408	Primary	Classroom 408	W1	Chipping, Holes, paint has been stabilized	28	No	No	N/A	Posters	Yes	
85	2690	1	3	408	Primary	Classroom 408	W2	Chipping, Gouges, Hole, paint has been stabilized	10	No	No	N/A	Posters, Furniture	Yes	
86	2690	1	3	408	Primary	Classroom 408	W3	Chipping on wall and radiators, Holes, paint has been stabilized, Flaking behind radiators	78	No	No	N/A	Posters, Furniture	Yes	
87	2690	1	3	408	Primary	Classroom 408	W4	Chipping, Holes, paint has been stabilized	10	No	No	N/A	Posters, Furniture	Yes	
88	2690	1	3	408A	Storage	Classroom 408 Closet	Ceiling	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
89	2690	1	3	408A	Storage	Classroom 408 Closet	Floor	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
90	2690	1	3	408A	Storage	Classroom 408 Closet	W1	Cracking, Flaking	4	No	No	N/A	Cabinet	Yes	Limited inspection due to stored materials
91	2690	1	3	408A	Storage	Classroom 408 Closet	W2	Cracking, Flaking	35	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
92	2690	1	3	408A	Storage	Classroom 408 Closet	W3	Chipping, Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
93	2690	1	3	408A	Storage	Classroom 408 Closet	W4	Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
94	2690	1	3	409	Primary	Classroom 409	Ceiling	Flaking outside Closet	3	No	No	N/A	N/A	No	
95	2690	1	3	409	Primary	Classroom 409	W1	Chipping, Holes, paint has been stabilized	12	No	No	N/A	Posters	Yes	
96	2690	1	3	409	Primary	Classroom 409	W2	Chipping, Hole, paint has been stabilized	7	No	No	N/A	Posters, Furniture	Yes	
97	2690	1	3	409	Primary	Classroom 409	W3	Chipping on radiators, Holes, paint has been stabilized, Holes behind radiator	47	No	No	N/A	Posters, Furniture	Yes	
98	2690	1	3	409	Primary	Classroom 409	W4	Cracking, Chipping, Flaking	15	No	No	N/A	Posters, Furniture	No	
99	2690	1	3	409A	Storage	Classroom 409 Closet	W1	Hole	1	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
100	2690	1	3	409A	Storage	Classroom 409 Closet	W2	Cracking, Flaking	22	No	No	N/A	N/A	No	
101	2690	1	3	409A	Storage	Classroom 409 Closet	W3	Flaking behind radiator	4	No	Debris behind radiator	1	Shelf	No	
102	2690	1	3	409A	Storage	Classroom 409 Closet	W4	Gouge, Flaking, Coat hooks pulling off wall	6	No	No	N/A	N/A	Yes	
103	2690	1	3	410	Primary	Classroom 410	Floor	N/A	N/A	No	Paint chips by metal pipe	1	N/A	No	
104	2690	1	3	410	Primary	Classroom 410	W1	Cracking, Chipping, Holes, paint has been stabilized on 1	11	No	No	N/A	Posters, Table	Yes	
105	2690	1	3	410	Primary	Classroom 410	W2	Chipping	4	No	No	N/A	Posters	No	
106	2690	1	3	410	Primary	Classroom 410	W3	Chipping on wall and radiators, flaking on wall and metal pipe, Efflorescence	65	Yes	No	N/A	Shelves, Stored Materials	Yes	
107	2690	1	3	410	Primary	Classroom 410	W4	Chipping, Flaking	5	No	No	N/A	Shelves, Stored Materials	No	
108	2690	1	3	410A	Storage	Classroom 410 Closet	W1	Holes, paint has been stabilized on 2, Flaking	5	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
109	2690	1	3	410A	Storage	Classroom 410 Closet	W2	Holes, paint has been stabilized	2	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
110	2690	1	3	410A	Storage	Classroom 410 Closet	W3	Chipping on wall and metal pipe, Gouge, Flaking	10	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
111	2690	1	3	410A	Storage	Classroom 410 Closet	W4	Chipping on radiator, Flaking behind radiator	10	No	No	N/A	N/A	No	
112	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	Ceiling	Cracking	24	No	No	N/A	N/A	No	Repair to concrete ceiling needed
113	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	Floor	N/A	N/A	No	Debris in corner of walls 1&2 and along wall 4	8	N/A	No	
114	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	W1	Cracking, Efflorescence	75	Yes	No	N/A	N/A	No	Repair to concrete block wall needed
115	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	W2	Cracking, Efflorescence	43	Yes	No	N/A	N/A	No	Repair to concrete block wall needed
116	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	W3	Chipping on doors and doorframe	12	No	No	N/A	N/A	No	
117	2690	1	3	S5-400	Stairs, Fire Tower	Fire Tower across from Classroom 400	W4	Cracking	25	No	No	5	N/A	No	Repair to concrete block wall needed
118	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
119	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
120	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
121	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
122	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
123	2690	1	3	S3-400	Stairs, Fire Tower	Fire Tower across from Classrooms 404-405	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
124	2690	1	3	H402	Circulation (Hallway)	Hallway outside Classrooms 400-401	W1	Chipping on radiators, Holes, paint has been stabilized, Efflorescence	44	Yes	No	N/A	Displayed Student Work	Yes	Damage has been repaired but is returning
125	2690	1	3	H402	Circulation (Hallway)	Hallway outside Classrooms 400-401	W2	Chipping on doors and doorframe	10	No	No	N/A	N/A	No	
126	2690	1	3	H402	Circulation (Hallway)	Hallway outside Classrooms 400-401	W3	Chipping on metal jackets, Holes, paint has been stabilized	5	No	No	N/A	Displayed Student Work	Yes	
127	2690	1	3	H400	Circulation (Hallway)	Hallway outside Classrooms 403-406	W2	Cracking, Chipping on wall, metal pipe, and radiators, Holes, paint has been stabilized on 8, Flaking	58	No	Debris inside radiator cover	2	Displayed Student Work	Yes	
128	2690	1	3	H400	Circulation (Hallway)	Hallway outside Classrooms 403-406	W3	Chipping, Hole, paint has been stabilized	3	No	No	N/A	N/A	Yes	
129	2690	1	3	H400	Circulation (Hallway)	Hallway outside Classrooms 403-406	W4	Chipping on metal jackets, Holes, paint has been stabilized, Efflorescence	63	Yes	Debris in windowsills	1	Displayed Student Work	Yes	
130	2690	1	3	H401	Circulation (Hallway)	Hallway outside Classrooms 408-409	W1	Chipping, Holes, paint has been stabilized, Flaking	14	No	No	N/A	Displayed Student Work	Yes	
131	2690	1	3	H401	Circulation (Hallway)	Hallway outside Classrooms 408-409	W3	Cracking, Chipping, Flaking	32	No	No	N/A	Displayed Student Work	No	
132	2690	1	3	H401	Circulation (Hallway)	Hallway outside Classrooms 408-409	W4	Cracking, Chipping	16	No	No	N/A	N/A	Yes	
133	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	Ceiling	Flaking	12	No	No	N/A	N/A	No	
134	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	Floor	Chipping on stairs, cove, and railings	89	No	No	N/A	N/A	No	
135	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	W1	Chipping on wall, doors, and doorframe, Hole, Flaking, Spalling	43	Yes	No	N/A	N/A	Yes	
136	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	W2	Cracking, Flaking on wall and side of stairs, Spalling	35	Yes	No	N/A	N/A	Yes	
137	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	W3	Cracking	3	No	No	N/A	N/A	No	
138	2690	1	3	S4-400	Stairs	Stairwell adjacent to Classroom 402	W4	Cracking, Chipping, Flaking	22	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
139	2690	1	3	S2-400	Stairs	Stairwell adjacent to Classroom 407	Floor	Chipping on stairs, cove, and railings	73	No	Paint chips along wall 3	N/A	N/A	No	
140	2690	1	3	S2-400	Stairs	Stairwell adjacent to Classroom 407	W1	Cracking	3	No	No	N/A	N/A	No	
141	2690	1	3	S2-400	Stairs	Stairwell adjacent to Classroom 407	W2	Cracking, Chipping, Flaking	9	No	No	N/A	N/A	No	
142	2690	1	3	S2-400	Stairs	Stairwell adjacent to Classroom 407	W3	Chipping on wall, doors, and doorframe, Holes, paint has been stabilized	11	No	No	N/A	N/A	Yes	
143	2690	1	3	S2-400	Stairs	Stairwell adjacent to Classroom 407	W4	Chipping, Flaking	18	No	No	N/A	N/A	No	
144	2690	1	3	S1-400	Stairs	Stairwell adjacent to Classroom 409	Floor	Chipping on stairs, cove, and railings	76	No	No	N/A	N/A	No	
145	2690	1	3	S1-400	Stairs	Stairwell adjacent to Classroom 409	W1	Cracking, Holes, Flaking	35	No	No	N/A	N/A	Yes	
146	2690	1	3	S1-400	Stairs	Stairwell adjacent to Classroom 409	W2	Cracking, Chipping on wall, door and doorframe	24	No	No	N/A	N/A	No	
147	2690	1	3	S1-400	Stairs	Stairwell adjacent to Classroom 409	W3	Cracking, Flaking	55	No	No	N/A	N/A	No	
148	2690	1	3	S1-400	Stairs	Stairwell adjacent to Classroom 409	W4	Cracking, Chipping on radiator, Hole	31	No	Debris inside radiator cover	5	N/A	Yes	
149	2690	1	3	S2-500	Stairs	Stairwell to Attic	Ceiling	Efflorescence	22	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
150	2690	1	3	S2-500	Stairs	Stairwell to Attic	Floor	Chipping on railings	7	No	No	N/A	N/A	No	
151	2690	1	3	S2-500	Stairs	Stairwell to Attic	W1	Flaking, Efflorescence	6	Yes	No	N/A	Table, Desks	Yes	
152	2690	1	3	S2-500	Stairs	Stairwell to Attic	W2	Cracking, Flaking	5	No	No	N/A	N/A	No	
153	2690	1	3	S2-500	Stairs	Stairwell to Attic	W3	Cracking	4	No	No	N/A	N/A	Yes	
154	2690	1	3	500	Storage	Storage Room 500	Ceiling	Holes, paint has been stabilized, Flaking	40	No	No	N/A	Cabinets, Stored Materials	Yes	
155	2690	1	3	500	Storage	Storage Room 500	Floor	N/A	N/A	No	Debris in corner of walls 1&4	1	Cabinets	No	Limited inspection due to stored materials
156	2690	1	3	500	Storage	Storage Room 500	W1	Chipping, Flaking	6	No	No	N/A	Cabinets	No	
157	2690	1	3	500	Storage	Storage Room 500	W2	Chipping on radiator, Gouge, Holes, paint has been stabilized	24	No	No	N/A	Furniture	Yes	
158	2690	1	3	500	Storage	Storage Room 500	W4	Cracking, Chipping, Hole, paint has been stabilized, Flaking	16	No	No	N/A	Cabinets, Stored Materials	Yes	
159	2690	1	2	313	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	Ceiling	Cracking	1	No	No	N/A	N/A	No	
160	2690	1	2	313	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	Floor	Chipping on transite stalls	13	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
161	2690	1	2	313	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	W1	Cracking, Spalling	2	Yes	No	N/A	N/A	Yes	
162	2690	1	2	313	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	W2	Cracking	2	No	No	N/A	N/A	No	
163	2690	1	2	313	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	W3	Cracking, Chipping on radiator, Flaking	5	No	No	N/A	N/A	No	
164	2690	1	2	315A	Restrooms, Staff - Male	2nd Floor Men's Restroom	Ceiling	Cracking	25	No	No	N/A	N/A	No	
165	2690	1	2	315A	Restrooms, Staff - Male	2nd Floor Men's Restroom	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
166	2690	1	2	315A	Restrooms, Staff - Male	2nd Floor Men's Restroom	W2	Chipping on transite, Holes, paint has been stabilized	10	No	No	N/A	N/A	Yes	
167	2690	1	2	315A	Restrooms, Staff - Male	2nd Floor Men's Restroom	W3	Cracking, Chipping on radiator, Holes, paint has been stabilized	32	No	No	N/A	N/A	Yes	
168	2690	1	2	315A	Restrooms, Staff - Male	2nd Floor Men's Restroom	W4	Cracking, Holes, paint has been stabilized	25	No	No	N/A	N/A	Yes	
169	2690	1	2	311	Restrooms, Staff - Female	2nd Floor Women's Restroom	Ceiling	Chipping on transite, Flaking on metal pipe	13	No	No	N/A	N/A	No	
170	2690	1	2	311	Restrooms, Staff - Female	2nd Floor Women's Restroom	W1	Holes, paint has been stabilized	8	No	No	N/A	N/A	Yes	
171	2690	1	2	311	Restrooms, Staff - Female	2nd Floor Women's Restroom	W2	Holes, paint has been stabilized	12	No	No	N/A	N/A	Yes	
172	2690	1	2	311	Restrooms, Staff - Female	2nd Floor Women's Restroom	W3	Holes, paint has been stabilized, Flaking on metal pipe	15	No	No	N/A	N/A	Yes	
173	2690	1	2	311	Restrooms, Staff - Female	2nd Floor Women's Restroom	W4	Chipping on radiator, Holes, paint has been stabilized, Flaking on radiator heat shield	33	No	No	N/A	N/A	Yes	
174	2690	1	2	300	Primary	Classroom 300	W1	Cracking, Chipping	17	No	No	N/A	Posters, Shelves	No	
175	2690	1	2	300	Primary	Classroom 300	W2	Cracking, Chipping, Holes, Flaking	19	No	No	N/A	Shelves, Stored Materials	Yes	
176	2690	1	2	300	Primary	Classroom 300	W3	Cracking, Chipping on wall and radiator	48	No	No	N/A	Shelves, Stored Materials	No	
177	2690	1	2	300	Primary	Classroom 300	W4	Cracking, Chipping, Flaking	7	No	No	N/A	Stored Materials	No	
178	2690	1	2	300A	Storage	Classroom 300 Closet	W2	Cracking, Chipping on cove	27	No	No	N/A	N/A	No	
179	2690	1	2	300A	Storage	Classroom 300 Closet	W3	Chipping on radiator, Flaking	6	No	No	N/A	Cabinet, Stored Materials	No	Limited inspection due to stored materials
180	2690	1	2	300A	Storage	Classroom 300 Closet	W4	Cracking, Chipping on wall and cove, Holes, paint has been stabilized	19	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
181	2690	1	2	301	Primary	Classroom 301	W1	Chipping, Holes, paint has been stabilized	16	No	No	N/A	Posters, Desks	Yes	
182	2690	1	2	301	Primary	Classroom 301	W2	Chipping	3	No	No	N/A	Cabinets, Desks	No	
183	2690	1	2	301	Primary	Classroom 301	W3	Chipping on radiators, Holes, paint has been stabilized, Efflorescence, Significant Moisture Damage behind radiator	45	Yes	No	N/A	Shelves with Stored Materials	Yes	
184	2690	1	2	301	Primary	Classroom 301	W4	Chipping	5	No	No	N/A	Posters, Shelves with Stored Materials	No	
185	2690	1	2	301A	Storage	Classroom 301 Closet	W1	Cracking, Flaking	3	No	No	N/A	N/A	No	
186	2690	1	2	301A	Storage	Classroom 301 Closet	W2	Cracking, Flaking on metal pipe	11	No	No	N/A	Stored Materials	No	
187	2690	1	2	301A	Storage	Classroom 301 Closet	W3	Hole	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
188	2690	1	2	301A	Storage	Classroom 301 Closet	W4	Cracking, Chipping, Flaking	31	No	No	N/A	Stored Materials	No	
189	2690	1	2	302	Primary	Classroom 302	W1	Cracking, Chipping	17	No	No	N/A	Posters	No	
190	2690	1	2	302	Primary	Classroom 302	W2	Cracking, Chipping on wall and door	17	No	No	N/A	Cabinet, Furniture	Yes	
191	2690	1	2	302	Primary	Classroom 302	W3	Cracking, Chipping on radiators and plastic jacket, Flaking behind radiators	84	No	No	N/A	Shelves, Stored Materials	No	
192	2690	1	2	302	Primary	Classroom 302	W4	Cracking, Chipping	8	No	No	N/A	N/A	No	
193	2690	1	2	302A	Storage	Classroom 302 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
194	2690	1	2	302A	Storage	Classroom 302 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
195	2690	1	2	302A	Storage	Classroom 302 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
196	2690	1	2	302A	Storage	Classroom 302 Closet	W2	Cracking, Flaking	4	No	No	N/A	Stored Materials	No	
197	2690	1	2	302A	Storage	Classroom 302 Closet	W3	Chipping on radiator, Flaking behind radiator	6	No	No	N/A	Stored Materials	No	
198	2690	1	2	302A	Storage	Classroom 302 Closet	W4	Holes, paint has been stabilized	5	No	Debris on hooks	1	Stored Materials	Yes	
199	2690	1	2	303	Primary	Classroom 303	W1	Chipping, Holes, Wood trim pulling off wall	8	No	No	N/A	Posters	Yes	
200	2690	1	2	303	Primary	Classroom 303	W3	Chipping on wall and radiators, Flaking behind radiators	61	No	No	N/A	Shelves, Stored Materials	No	
201	2690	1	2	303	Primary	Classroom 303	W4	Cracking, Chipping	3	No	No	N/A	Posters, Desks	No	
202	2690	1	2	303A	Storage	Classroom 303 Closet	Ceiling	Cracking above missing ceiling tile	8	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
203	2690	1	2	303A	Storage	Classroom 303 Closet	W2	Chipping, Coat hooks pulling off wall	6	No	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
204	2690	1	2	303A	Storage	Classroom 303 Closet	W3	Cracking, some above missing ceiling tile. Hole, paint has been stabilized	25	No	No	N/A	Stored Materials	Yes	
205	2690	1	2	303A	Storage	Classroom 303 Closet	W4	Cracking, Coat hooks pulling off wall	40	No	No	N/A	N/A	Yes	
206	2690	1	2	304	Primary	Classroom 304	Floor	N/A	N/A	No	Debris in corner of walls 3&4	1	N/A	No	
207	2690	1	2	304	Primary	Classroom 304	W1	Cracking in air shaft, Chipping, Holes	19	No	No	N/A	N/A	Yes	
208	2690	1	2	304	Primary	Classroom 304	W2	Holes, Efflorescence behind desk	6	Yes	No	N/A	Desk	Yes	
209	2690	1	2	304	Primary	Classroom 304	W3	Chipping on plastic jacket, Gouges, Holes	6	No	No	N/A	N/A	Yes	
210	2690	1	2	304	Primary	Classroom 304	W4	Chipping, Holes	14	No	No	N/A	N/A	Yes	
211	2690	1	2	304A	Storage	Classroom 304 Closet	W1	Cracking, Hole	3	No	No	N/A	N/A	Yes	
212	2690	1	2	304A	Storage	Classroom 304 Closet	W2	Cracking, Chipping	4	No	No	N/A	N/A	No	
213	2690	1	2	304A	Storage	Classroom 304 Closet	W3	Flaking	5	No	No	N/A	Stored Materials	No	
214	2690	1	2	304A	Storage	Classroom 304 Closet	W4	Cracking, Holes, paint has been stabilized on 2, Flaking	24	No	No	N/A	N/A	Yes	
215	2690	1	2	307	Primary	Classroom 307	Ceiling	Flaking above entrance and 2nd closet entrance	6	No	No	N/A	N/A	No	
216	2690	1	2	307	Primary	Classroom 307	Floor	N/A	N/A	No	Debris on carpet along wall 3	2	N/A	No	
217	2690	1	2	307	Primary	Classroom 307	W1	Cracking, Chipping, Holes, Significant Moisture Damage above entrance	35	Yes	No	N/A	Posters	Yes	
218	2690	1	2	307	Primary	Classroom 307	W2	Cracking, Chipping, Flaking	50	No	No	N/A	Posters, Shelves	No	
219	2690	1	2	307	Primary	Classroom 307	W3	Chipping on radiators, Flaking on wall and behind radiator	58	No	No	N/A	Shelves, Stored Materials	No	
220	2690	1	2	307	Primary	Classroom 307	W4	Chipping, Flaking	27	No	No	N/A	Posters, Desks	No	
221	2690	1	2	307A	Storage	Classroom 307 Closet	Ceiling	Flaking above missing ceiling tile	16	No	No	N/A	Stored Materials	No	
222	2690	1	2	307A	Storage	Classroom 307 Closet	W1	Flaking	1	No	No	N/A	N/A	No	
223	2690	1	2	307A	Storage	Classroom 307 Closet	W2	Flaking on wall and metal pipe	10	No	No	N/A	Cabinet, Shelves, Stored Material	No	Limited inspection due to stored materials
224	2690	1	2	307A	Storage	Classroom 307 Closet	W3	Flaking, some above missing ceiling tile	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
225	2690	1	2	307A	Storage	Classroom 307 Closet	W4	Flaking	30	No	No	N/A	N/A	No	
226	2690	1	2	308	Primary	Classroom 308	Ceiling	Cracking above entrance	3	No	No	N/A	N/A	No	
227	2690	1	2	308	Primary	Classroom 308	W1	Chipping, Hole, Flaking	8	No	No	N/A	N/A	Yes	
228	2690	1	2	308	Primary	Classroom 308	W2	N/A	N/A	No	No	N/A	Posters, Shelves, Stored Materials	No	Limited inspection due to stored materials
229	2690	1	2	308	Primary	Classroom 308	W3	Chipping on wall and radiators	43	No	No	N/A	N/A	No	
230	2690	1	2	308	Primary	Classroom 308	W4	N/A	N/A	No	No	N/A	Cabinets, Shelves	No	Limited inspection due to stored materials
231	2690	1	2	308A	Storage	Classroom 308 Closet	Ceiling	Cracking	30	No	No	N/A	N/A	No	
232	2690	1	2	308A	Storage	Classroom 308 Closet	W1	Cracking, Chipping, Flaking, Coat hooks pulling off wall	28	No	No	N/A	N/A	Yes	
233	2690	1	2	308A	Storage	Classroom 308 Closet	W2	Efflorescence	1	Yes	No	N/A	Cabinet, Stored Materials	Yes	Limited inspection due to stored materials
234	2690	1	2	308A	Storage	Classroom 308 Closet	W3	Cracking, Chipping	43	No	No	N/A	Refrigerator, Shelves, Stored Materials	No	Limited inspection due to stored materials
235	2690	1	2	308A	Storage	Classroom 308 Closet	W4	Cracking	20	No	No	N/A	Stored Materials	No	
236	2690	1	2	309	Art - Elementary	Classroom 309	W1	Chipping on wall, door and doorframe, Hole	31	No	No	N/A	Posters, Art	Yes	
237	2690	1	2	309	Art - Elementary	Classroom 309	W2	Cracking, Efflorescence	5	Yes	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
238	2690	1	2	309	Art - Elementary	Classroom 309	W3	Cracking, Holes	7	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
239	2690	1	2	309	Art - Elementary	Classroom 309	W4	Hole	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
240	2690	1	2	309A	Storage	Classroom 309 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.
241	2690	1	2	309A	Storage	Classroom 309 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.
242	2690	1	2	309A	Storage	Classroom 309 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.
243	2690	1	2	309A	Storage	Classroom 309 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.
244	2690	1	2	309A	Storage	Classroom 309 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
245	2690	1	2	309A	Storage	Classroom 309 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Access blocked by stored materials. This space will need to be inspected.
246	2690	1	2	312	Teacher Lounge/Dining	Dining Room	W1	Chipping, Hole	2	No	No	N/A	N/A	Yes	
247	2690	1	2	312	Teacher Lounge/Dining	Dining Room	W2	Flaking, behind cabinets	3	No	No	N/A	Cabinets	No	
248	2690	1	2	312	Teacher Lounge/Dining	Dining Room	W3	Cracking, Chipping on radiator, Flaking behind radiator	18	No	No	N/A	N/A	No	
249	2690	1	2	312	Teacher Lounge/Dining	Dining Room	W4	2 cr	2	No	No	N/A	N/A	No	
250	2690	1	2	312A	Kitchen	Dining Room Kitchen	W1	Flaking	4	No	No	N/A	N/A	No	
251	2690	1	2	312A	Kitchen	Dining Room Kitchen	W2	Cracking, Flaking, Efflorescence behind radiator	13	Yes	No	N/A	N/A	Yes	
252	2690	1	2	312A	Kitchen	Dining Room Kitchen	W3	Cracking, Holes	9	No	No	N/A	N/A	Yes	
253	2690	1	2	312A	Kitchen	Dining Room Kitchen	W4	Cracking	15	No	No	N/A	N/A	No	
254	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	Ceiling	Efflorescence	5	Yes	No	No	N/A	No	
255	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	Floor	N/A	N/A	No	Paint chips below efflorescence	2	N/A	No	
256	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	W1	Cracking, Hole, Flaking, Efflorescence	34	Yes	No	No	N/A	No	Repair to concrete block wall needed
257	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	W2	Cracking, Efflorescence	18	Yes	No	No	N/A	No	Repair to caulk needed
258	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	W3	Chipping on wall and doorframe	10	No	No	No	N/A	No	
259	2690	1	2	S5-300	Stairs. Fire Tower	Fire Tower across from Classroom 300	W4	Cracking, Flaking on metal pipe	32	No	No	No	N/A	No	Repair to concrete block wall and caulk needed
260	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
261	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
262	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
263	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
264	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
265	2690	1	2	S3-300	Stairs, Fire Tower	Fire Tower across from Classroom 304 and IMC	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
266	2690	1	2	H302	Circulation (Hallway)	Hallway outside Classrooms 300-301	W1	Cracking, Chipping on wall, radiators, and metal jackets, Flaking	67	No	No	N/A	Displayed Student Work	No	
267	2690	1	2	H302	Circulation (Hallway)	Hallway outside Classrooms 300-301	W2	Chipping on wall and doors, Gouges, Flaking	20	No	No	N/A	N/A	Yes	
268	2690	1	2	H302	Circulation (Hallway)	Hallway outside Classrooms 300-301	W3	Cracking, Chipping, Hole, Flaking	21	No	No	N/A	Displayed Student Work	Yes	
269	2690	1	2	H302	Circulation (Hallway)	Hallway outside Classrooms 300-301	W4	Flaking	2	No	No	N/A	N/A	No	
270	2690	1	2	H300	Circulation (Hallway)	Hallway outside Classrooms 303-307	W1	Chipping, Holes, paint has been stabilized	8	No	No	N/A	N/A	Yes	
271	2690	1	2	H300	Circulation (Hallway)	Hallway outside Classrooms 303-307	W2	Cracking, Chipping on wall and metal pipe, Holes, Flaking on wall and metal pipe	76	No	No	N/A	Displayed Student Work	Yes	
272	2690	1	2	H300	Circulation (Hallway)	Hallway outside Classrooms 303-307	W3	Chipping , Spalling	4	Yes	No	N/A	N/A	Yes	
273	2690	1	2	H300	Circulation (Hallway)	Hallway outside Classrooms 303-307	W4	Cracking, Chipping on wall and metal and plastic jackets, Holes, paint has been stabilized, Flaking	51	No	No	N/A	Displayed Student Work	Yes	
274	2690	1	2	H301	Circulation (Hallway)	Hallway outside Classrooms 308-309	W1	Chipping, Hole, paint has been stabilized	17	No	No	N/A	Displayed Student Work	Yes	
275	2690	1	2	H301	Circulation (Hallway)	Hallway outside Classrooms 308-309	W3	Chipping, Hole, paint has been stabilized	7	No	No	N/A	Displayed Student Work	Yes	
276	2690	1	2	H301	Circulation (Hallway)	Hallway outside Classrooms 308-309	W4	Holes, paint has been stabilized	13	No	No	N/A	N/A	Yes	
277	2690	1	2	305	IMC (Library)	IMC	Floor	N/A	N/A	No	Debris outside telecommunication equipment room	4	N/A	No	
278	2690	1	2	305	IMC (Library)	IMC	W1	Cracking, some in air shaft, Chipping, Holes	34	No	No	N/A	Shelves with books	Yes	
279	2690	1	2	305	IMC (Library)	IMC	W2	Cracking	6	No	No	N/A	N/A	No	
280	2690	1	2	305	IMC (Library)	IMC	W3	Cracking, Chipping, Flaking behind built in seats	12	No	No	N/A	Built in seats	No	Limited access to radiators
281	2690	1	2	305	IMC (Library)	IMC	W4	Chipping, Holes	5	No	No	N/A	Shelves with books	Yes	
282	2690	1	2	305D	Storage	IMC Closet	Ceiling	N/A	N/A	No	No	N/A	Shelves, Books, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
283	2690	1	2	305D	Storage	IMC Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Books, Stored Materials	No	Limited inspection due to stored materials
284	2690	1	2	305D	Storage	IMC Closet	W1	Cracking	2	No	No	N/A	Shelves, Books, Stored Materials	No	
285	2690	1	2	305D	Storage	IMC Closet	W2	Cracking, Gouge, Flaking	22	No	No	N/A	Shelves, Books, Stored Materials	Yes	Limited inspection due to stored materials
286	2690	1	2	305D	Storage	IMC Closet	W3	Cracking	3	No	No	N/A	Shelves, Books, Stored Materials	No	Limited inspection due to stored materials
287	2690	1	2	305D	Storage	IMC Closet	W4	Cracking	12	No	No	N/A	Shelves, Books, Stored Materials	Yes	Limited inspection due to stored materials
288	2690	1	2	305C	Telecommunication Equipment Room	IMC Telecommunication Equipment Room	Floor	N/A	N/A	No	Debris near wall 3	5	N/A	No	
289	2690	1	2	305C	Telecommunication Equipment Room	IMC Telecommunication Equipment Room	W1	Cracking, Hole	2	No	No	N/A	N/A	Yes	
290	2690	1	2	305C	Telecommunication Equipment Room	IMC Telecommunication Equipment Room	W2	Cracking, Hole	5	No	No	N/A	N/A	Yes	
291	2690	1	2	305C	Telecommunication Equipment Room	IMC Telecommunication Equipment Room	W3	Cracking, Holes	9	No	No	N/A	N/A	Yes	
292	2690	1	2	305C	Telecommunication Equipment Room	IMC Telecommunication Equipment Room	W4	Cracking, Hole	19	No	No	N/A	N/A	Yes	
293	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	Ceiling	Cracking, Flaking above damaged ceiling tile	4	No	No	N/A	Stored Materials	No	
294	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
295	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	W1	Holes, paint has been stabilized on 3	4	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
296	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	W2	Holes, paint has been stabilized	5	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
297	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	W3	Holes, paint has been stabilized	1	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
298	2690	1	2	315	Teacher Lounge/Dining	Men's Lounge outside 2nd Floor Men's Restroom	W4	Chipping on radiator, Cracking above missing ceiling tile, Holes, paint has been stabilized	44	No	Debris on windowsill	1	Stored Materials	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
299	2690	1	2	S4-300	Stairs	Stairwell adjacent to Classroom 302	Floor	Chipping on cove and railings	64	No	No	N/A	N/A	No	
300	2690	1	2	S4-300	Stairs	Stairwell adjacent to Classroom 302	W1	Chipping on doors and doorframe, Holes, paint has been stabilized on 4, Flaking	22	No	No	N/A	N/A	Yes	
301	2690	1	2	S4-300	Stairs	Stairwell adjacent to Classroom 302	W2	Cracking, Hole, paint has been stabilized, Flaking	13	No	No	N/A	N/A	Yes	
302	2690	1	2	S4-300	Stairs	Stairwell adjacent to Classroom 302	W3	Cracking	2	No	No	N/A	N/A	No	
303	2690	1	2	S4-300	Stairs	Stairwell adjacent to Classroom 302	W4	Hole, paint has been stabilized, Flaking	7	No	No	N/A	N/A	Yes	
304	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	Ceiling	Flaking	1	No	No	N/A	N/A	No	
305	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	Floor	Chipping on stairs, cove and railings	83	No	No	N/A	N/A	No	
306	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	W1	Cracking, Flaking	6	No	No	N/A	N/A	No	
307	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	W2	Chipping, Hole, paint has been stabilized, Flaking	6	No	No	N/A	N/A	Yes	
308	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	W3	Chipping on doors, Holes, paint has been stabilized, Flaking on doors, Efflorescence	20	Yes	No	N/A	N/A	Yes	
309	2690	1	2	S2-300	Stairs	Stairwell adjacent to Classroom 307	W4	Flaking	11	No	No	N/A	N/A	No	
310	2690	1	2	S1-300	Stairs	Stairwell adjacent to Classroom 309	Floor	Chipping on stairs, cove and railings	76	No	No	N/A	N/A	No	
311	2690	1	2	S1-300	Stairs	Stairwell adjacent to Classroom 309	W1	Cracking, Flaking	16	No	No	N/A	N/A	No	
312	2690	1	2	S1-300	Stairs	Stairwell adjacent to Classroom 309	W2	Chipping on doors and doorframe, Holes	20	No	No	N/A	N/A	Yes	
313	2690	1	2	S1-300	Stairs	Stairwell adjacent to Classroom 309	W3	Cracking, Holes, Flaking	13	No	Debris inside radiator cover	2	N/A	Yes	
314	2690	1	2	S1-300	Stairs	Stairwell adjacent to Classroom 309	W4	Cracking, Holes, paint has been stabilized	8	No	No	N/A	N/A	Yes	
315	2690	1	2	313A	Circulation (Hallway)	Vestibule outside 2nd Floor Girl's Restroom	Ceiling	Cracking, Flaking	4	No	No	N/A	N/A	No	
316	2690	1	2	313A	Circulation (Hallway)	Vestibule outside 2nd Floor Girl's Restroom	W1	Flaking	2	No	No	N/A	N/A	No	
317	2690	1	2	313A	Circulation (Hallway)	Vestibule outside 2nd Floor Girl's Restroom	W2	Cracking, Gouge	6	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
318	2690	1	2	313A	Circulation (Hallway)	Vestibule outside 2nd Floor Girl's Restroom	W3	Cracking, Hole, paint has been stabilized	11	No	No	N/A	N/A	Yes	
319	2690	1	2	313A	Circulation (Hallway)	Vestibule outside 2nd Floor Girl's Restroom	W4	Cracking	8	No	No	N/A	N/A	No	
320	2690	1	2	310	Teacher Lounge/Dining	Women's Lounge outside 2nd Floor Women's Restroom	W1	Chipping, Flaking	16	No	No	N/A	N/A	No	
321	2690	1	2	310	Teacher Lounge/Dining	Women's Lounge outside 2nd Floor Women's Restroom	W2	Cracking, Flaking	12	No	No	N/A	N/A	No	
322	2690	1	2	310	Teacher Lounge/Dining	Women's Lounge outside 2nd Floor Women's Restroom	W3	Cracking, Holes, Flaking	17	No	No	N/A	N/A	Yes	
323	2690	1	2	310	Teacher Lounge/Dining	Women's Lounge outside 2nd Floor Women's Restroom	W4	Cracking, Flaking, Spalling	24	Yes	No	N/A	N/A	Yes	
324	2690	1	1	200	Primary	Classroom 200	W1	Cracking, Chipping on wall and metal jacket	7	No	No	N/A	Posters	No	
325	2690	1	1	200	Primary	Classroom 200	W2	Cracking, Chipping, Holes	9	No	No	N/A	Posters	Yes	
326	2690	1	1	200	Primary	Classroom 200	W3	Cracking, Chipping, Flaking behind radiators	48	No	No	N/A	Shelves, Stored Materials	No	
327	2690	1	1	200	Primary	Classroom 200	W4	N/A	N/A	No	No	N/A	Posters, Built in Shelves, Stored Materials	No	
328	2690	1	1	200A	Storage	Classroom 200 Closet	Ceiling	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
329	2690	1	1	200A	Storage	Classroom 200 Closet	Floor	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
330	2690	1	1	200A	Storage	Classroom 200 Closet	W1	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
331	2690	1	1	200A	Storage	Classroom 200 Closet	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
332	2690	1	1	200A	Storage	Classroom 200 Closet	W3	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
333	2690	1	1	200A	Storage	Classroom 200 Closet	W4	Cracking	3	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
334	2690	1	1	201	Primary	Classroom 201	W1	Chipping on doorframe and cove	14	No	No	N/A	N/A	No	
335	2690	1	1	201	Primary	Classroom 201	W2	Cracking, Chipping on cove	15	No	Debris in air shaft	3	N/A	No	
336	2690	1	1	201	Primary	Classroom 201	W3	Flaking behind radiator and cover	40	No	No	N/A	Shelves with stored materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
337	2690	1	1	201A	Storage	Classroom 201 Closet	Floor	N/A	N/A	No	Debris in corner of walls 1&2, Paint chips in corner of walls 2&3	4	N/A	No	
338	2690	1	1	201A	Storage	Classroom 201 Closet	W1	Cracking, Hole	2	No	No	N/A	N/A	Yes	
339	2690	1	1	201A	Storage	Classroom 201 Closet	W2	Flaking on metal pipe	10	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
340	2690	1	1	201A	Storage	Classroom 201 Closet	W3	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
341	2690	1	1	201A	Storage	Classroom 201 Closet	W4	Cracking, Chipping, Flaking	36	No	No	N/A	Stored Materials	No	
342	2690	1	1	202	Primary	Classroom 202	W1	Chipping on wall, door and doorframe, Hole, paint has been stabilized	11	No	No	N/A	N/A	Yes	
343	2690	1	1	202	Primary	Classroom 202	W2	Cracking, Chipping	13	No	No	N/A	N/A	No	
344	2690	1	1	202	Primary	Classroom 202	W3	Chipping on radiators, Flaking behind shelves	45	No	No	N/A	Shelves	No	
345	2690	1	1	202	Primary	Classroom 202	W4	Cracking	5	No	No	N/A	N/A	No	
346	2690	1	1	202A	Storage	Classroom 202 Closet	W2	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
347	2690	1	1	202A	Storage	Classroom 202 Closet	W3	Chipping on radiator, Hole, Flaking	9	No	No	N/A	Shelves and Stored Materials	Yes	Limited inspection due to stored materials
348	2690	1	1	202A	Storage	Classroom 202 Closet	W4	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
349	2690	1	1	204	Computer - Intermediate Middle	Classroom 204	W1	Chipping on wall and cove, Holes around entrance, paint has been stabilized, Hole in air shaft	22	No	No	N/A	Computers, Tables	Yes	
350	2690	1	1	204	Computer - Intermediate Middle	Classroom 204	W2	Chipping	1	No	Paint chips on office windowsill	1	N/A	No	
351	2690	1	1	204	Computer - Intermediate Middle	Classroom 204	W3	Chipping on radiators, Flaking behind radiators	60	No	No	N/A	Computers, Tables	No	
352	2690	1	1	204	Computer - Intermediate Middle	Classroom 204	W4	Chipping	3	No	No	N/A	N/A	No	
353	2690	1	1	204C	Storage	Classroom 204 Closet near Entrance	W2	Cracking, Hole	9	No	No	N/A	N/A	Yes	
354	2690	1	1	204C	Storage	Classroom 204 Closet near Entrance	W4	Cracking, Holes, paint has been stabilized	12	No	No	N/A	N/A	Yes	
355	2690	1	1	204B	Storage	Classroom 204 Closet near front of Room	Floor	N/A	N/A	No	Debris along wall 4	5	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
356	2690	1	1	204B	Storage	Classroom 204 Closet near front of Room	W1	Cracking, Chipping, Flaking	30	No	No	N/A	N/A	Yes	
357	2690	1	1	204B	Storage	Classroom 204 Closet near front of Room	W2	Cracking	12	No	No	N/A	N/A	Yes	
358	2690	1	1	204B	Storage	Classroom 204 Closet near front of Room	W3	Cracking	14	No	No	N/A	Shelves with stored materials	Yes	Limited inspection due to stored materials
359	2690	1	1	204B	Storage	Classroom 204 Closet near front of Room	W4	Cracking, Chipping, Gouges	9	No	No	N/A	N/A	Yes	
360	2690	1	1	204A	Administrative Office	Classroom 204 Office	Ceiling	Flaking above window	3	No	No	N/A	Table	No	
361	2690	1	1	204A	Administrative Office	Classroom 204 Office	Floor	N/A	N/A	No	Paint chips along wall 4	7	N/A	No	
362	2690	1	1	204A	Administrative Office	Classroom 204 Office	W4	Chipping on radiator, Flaking behind radiator	10	No	No	N/A	Table	No	
363	2690	1	1	204D	Storage	Classroom 204 Office Closet	Floor	N/A	N/A	No	Debris along wall 3 from drilling	3	N/A	No	
364	2690	1	1	204D	Storage	Classroom 204 Office Closet	W2	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
365	2690	1	1	204D	Storage	Classroom 204 Office Closet	W3	Cracking	15	No	No	N/A	Shelves with stored materials	Yes	
366	2690	1	1	204D	Storage	Classroom 204 Office Closet	W4	Cracking	5	No	No	N/A	Shelves with stored materials	Yes	
367	2690	1	1	207	Primary	Classroom 207	Floor	N/A	N/A	No	Debris in wall 4 air shaft	2	N/A	No	
368	2690	1	1	207	Primary	Classroom 207	W1	Cracking, Chipping, Hole	19	No	No	N/A	Furniture	Yes	
369	2690	1	1	207	Primary	Classroom 207	W2	Chipping, Flaking	7	No	No	N/A	Furniture	No	
370	2690	1	1	207	Primary	Classroom 207	W3	Chipping on radiators, Holes, paint has been stabilized on 3, Flaking on wall and behind radiators	86	No	Debris on windowsills	1	Chairs, File Cabinet	Yes	Limited inspection due to stored materials
371	2690	1	1	207	Primary	Classroom 207	W4	Cracking, Chipping, Flaking in air shaft	22	No	No	N/A	N/A	No	
372	2690	1	1	207A	Storage	Classroom 207 Closet	Ceiling	N/A	N/A	No	No	N/A	Instruments, Stored Materials	No	Limited inspection due to stored materials
373	2690	1	1	207A	Storage	Classroom 207 Closet	Floor	N/A	N/A	No	Debris scattered	3	Instruments, Stored Materials	No	Limited inspection due to stored materials
374	2690	1	1	207A	Storage	Classroom 207 Closet	W1	Cracking	1	No	No	N/A	Instruments, Stored Materials	No	
375	2690	1	1	207A	Storage	Classroom 207 Closet	W2	Flaking	1	No	No	N/A	Instruments, Stored Materials	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
376	2690	1	1	207A	Storage	Classroom 207 Closet	W3	N/A	N/A	No	No	N/A	Instruments, Stored Materials, Cabinet	No	Limited inspection due to stored materials
377	2690	1	1	207A	Storage	Classroom 207 Closet	W4	N/A	N/A	No	No	N/A	Instruments, Stored Materials	No	Limited inspection due to stored materials
378	2690	1	1	208	Primary	Classroom 208	W1	Cracking, Chipping, Flaking	18	No	No	N/A	N/A	No	
379	2690	1	1	208	Primary	Classroom 208	W2	Cracking, Chipping on wall and water fountain	163	No	No	N/A	Posters, Stored Materials	No	Limited inspection due to stored materials
380	2690	1	1	208	Primary	Classroom 208	W3	Cracking, Chipping, Flaking behind radiators and covers	27	No	No	N/A	Posters, Furniture	No	
381	2690	1	1	208	Primary	Classroom 208	W4	Cracking, Chipping	13	No	No	N/A	N/A	No	
382	2690	1	1	208B	Storage	Classroom 208 Coat Closet	W1	Cracking, Holes, paint has been stabilized	53	No	No	N/A	Microwave, Refrigerator, Stored Materials	Yes	
383	2690	1	1	208B	Storage	Classroom 208 Coat Closet	W2	Cracking, Flaking on wall and behind radiator	24	No	Debris inside radiator cover	2	Stored Materials	No	
384	2690	1	1	208B	Storage	Classroom 208 Coat Closet	W3	Cracking, Flaking	27	No	No	N/A	Built in shelves with stored materials	No	
385	2690	1	1	208A	Storage	Classroom 208 Storage Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
386	2690	1	1	208A	Storage	Classroom 208 Storage Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
387	2690	1	1	208A	Storage	Classroom 208 Storage Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
388	2690	1	1	208A	Storage	Classroom 208 Storage Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
389	2690	1	1	208A	Storage	Classroom 208 Storage Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
390	2690	1	1	208A	Storage	Classroom 208 Storage Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	Padlocked. This space will need to be inspected.
391	2690	1	1	209	Primary	Classroom 209	W1	Chipping, Flaking	20	No	No	N/A	Posters	No	Limited inspection due to posters
392	2690	1	1	209	Primary	Classroom 209	W2	Chipping, Spalling	42	Yes	No	N/A	Built in Cabinets	Yes	
393	2690	1	1	209	Primary	Classroom 209	W3	Chipping, Holes, paint has been stabilized, Flaking	5	No	No	N/A	Stored Materials	Yes	
394	2690	1	1	209	Primary	Classroom 209	W4	Chipping	10	No	No	N/A	Stored Materials	No	
395	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	Ceiling	Flaking	33	No	No	N/A	Shelves, Stored Materials	No	
396	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	Floor	N/A	N/A	No	Paint chips along wall 2	5	Shelves, Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
397	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	W1	Cracking, Chipping, Flaking	18	No	No	N/A	Shelves, Stored Materials	Yes	
398	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	W2	N/A	N/A	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to stored materials
399	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	W3	Cracking	20	No	No	N/A	Shelves, Stored Materials	Yes	
400	2690	1	1	209A	Storage	Classroom 209 Storage Area to right of Entrance	W4	Cracking, Flaking	15	No	No	N/A	Shelves, Stored Materials	No	
401	2690	1	1	200B	Student Restrooms - Male/Female (Classroom)	Classrooms 200 and 201 Restroom	W1	Cracking, Efflorescence	8	Yes	No	N/A	N/A	Yes	Classroom 201 Entrance
402	2690	1	1	200B	Student Restrooms - Male/Female (Classroom)	Classrooms 200 and 201 Restroom	W2	Cracking, Chipping on stalls, Flaking behind toilets	82	No	No	N/A	N/A	No	
403	2690	1	1	200B	Student Restrooms - Male/Female (Classroom)	Classrooms 200 and 201 Restroom	W3	Chipping, Flaking	6	No	No	N/A	N/A	No	
404	2690	1	1	200B	Student Restrooms - Male/Female (Classroom)	Classrooms 200 and 201 Restroom	W4	Chipping on radiator cover, Flaking on wall and radiator	20	No	Debris on windowsill	2	N/A	No	
405	2690	1	1	208C	Student Restrooms - Male/Female (Classroom)	Classrooms 208 and 209 Restroom	Ceiling	Cracking	5	No	No	N/A	N/A	No	
406	2690	1	1	208C	Student Restrooms - Male/Female (Classroom)	Classrooms 208 and 209 Restroom	W1	Chipping on door, doorframe, and radiator, Flaking	14	No	No	N/A	N/A	No	Classroom 208 Entrance
407	2690	1	1	208C	Student Restrooms - Male/Female (Classroom)	Classrooms 208 and 209 Restroom	W2	Cracking	15	No	No	N/A	N/A	Yes	
408	2690	1	1	208C	Student Restrooms - Male/Female (Classroom)	Classrooms 208 and 209 Restroom	W3	Cracking, Chipping, Flaking on door and doorframe	55	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
409	2690	1	1	214	Administrative Office	Counselor's Office adjacent to Classroom 200	W1	Cracking, Holes, paint has been stabilized, Flaking on door and frame	40	No	No	N/A	N/A	Yes	
410	2690	1	1	214	Administrative Office	Counselor's Office adjacent to Classroom 200	W2	Cracking, Chipping on wood cabinet and bulletin board frame, Holes, paint has been stabilized	30	No	No	N/A	N/A	Yes	
411	2690	1	1	214	Administrative Office	Counselor's Office adjacent to Classroom 200	W3	Cracking, Holes, paint has been stabilized	10	No	No	N/A	N/A	Yes	
412	2690	1	1	214	Administrative Office	Counselor's Office adjacent to Classroom 200	W4	Chipping on cove and radiator, Holes, paint has been stabilized, Flaking behind radiator	55	No	No	N/A	N/A	Yes	
413	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Ceiling	Cracking	5	No	No	N/A	N/A	No	
414	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	Floor	N/A	N/A	No	Paint chips scattered	3	N/A	No	
415	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W1	Chipping on door and doorframe, Holes, paint has been stabilized	18	No	No	N/A	N/A	Yes	
416	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W2	Cracking, Holes, paint has been stabilized	8	No	No	N/A	N/A	Yes	
417	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W3	Chipping on radiator, Holes, paint has been stabilized on 3	18	No	No	N/A	N/A	Yes	
418	2690	1	1	214A	Restrooms, Staff - Male/Female	Counselor's Office Restroom	W4	Holes, paint has been stabilized	2	No	No	N/A	N/A	Yes	
419	2690	1	1	S5-200	Stairs, Fire Tower	Fire Tower across from Classroom 200	W1	Cracking, Holes	34	No	No	N/A	N/A	No	Repair to concrete block wall needed
420	2690	1	1	S5-200	Stairs, Fire Tower	Fire Tower across from Classroom 200	W2	Cracking	17	No	No	N/A	N/A	No	Repair to concrete block wall and caulk needed
421	2690	1	1	S5-200	Stairs, Fire Tower	Fire Tower across from Classroom 200	W3	Chipping on doorframe	5	No	No	N/A	N/A	No	
422	2690	1	1	S5-200	Stairs, Fire Tower	Fire Tower across from Classroom 200	W4	Cracking, Chipping on door and doorframe	22	No	No	N/A	N/A	No	Repair to caulk needed
423	2690	1	1	S3-200	Stairs, Fire Tower	Fire Tower across from Classroom 204	Floor	Chipping on left side, flaking on right side	10	No	No	N/A	N/A	No	
424	2690	1	1	S3-200	Stairs, Fire Tower	Fire Tower across from Classroom 204	W1	Chipping on door and doorframe on left and right sides	9	No	No	N/A	N/A	No	
425	2690	1	1	S3-200	Stairs, Fire Tower	Fire Tower across from Classroom 204	W3	Chipping on door and doorframe on left and right sides	6	No	No	N/A	N/A	No	
426	2690	1	1	H201	Circulation (Hallway)	Hallway outside Classroom 208	W1	Cracking, Holes	5	No	No	N/A	N/A	Yes	
427	2690	1	1	H201	Circulation (Hallway)	Hallway outside Classroom 208	W2	Chipping on doors and frame, Holes, paint has been stabilized	15	No	No	N/A	N/A	Yes	
428	2690	1	1	H201	Circulation (Hallway)	Hallway outside Classroom 208	W3	Cracking, Chipping	15	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
429	2690	1	1	H201	Circulation (Hallway)	Hallway outside Classroom 208	W4	Holes, paint has been stabilized	10	No	No	N/A	N/A	Yes	
430	2690	1	1	H202	Circulation (Hallway)	Hallway outside Classrooms 200-201	W1	Cracking, Chipping on radiator covers and metal jackets, Holes, paint has been stabilized	41	No	No	N/A	N/A	Yes	
431	2690	1	1	H202	Circulation (Hallway)	Hallway outside Classrooms 200-201	W2	Chipping, Flaking on doors and doorframe	22	No	No	N/A	N/A	No	
432	2690	1	1	H202	Circulation (Hallway)	Hallway outside Classrooms 200-201	W3	Chipping	5	No	No	N/A	N/A	No	
433	2690	1	1	H200	Circulation (Hallway)	Hallway outside Offices 203-206	W1	Chipping on wall, doors, and doorframe, Gouges, paint has been stabilized, Flaking on doors and doorframe	39	No	No	N/A	N/A	Yes	
434	2690	1	1	H200	Circulation (Hallway)	Hallway outside Offices 203-206	W2	Cracking, Chipping, Holes	28	No	No	N/A	Displayed Student Work	Yes	
435	2690	1	1	H200	Circulation (Hallway)	Hallway outside Offices 203-206	W3	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	
436	2690	1	1	H200	Circulation (Hallway)	Hallway outside Offices 203-206	W4	Cracking, Chipping on metal jackets and radiator, Holes, paint has been stabilized on 1	33	No	No	N/A	Displayed Student Work	Yes	
437	2690	1	1	210	Administrative Office	Main Office	W1	Cracking, Chipping on doorframe, Flaking	55	No	No	N/A	N/A	No	
438	2690	1	1	210	Administrative Office	Main Office	W2	Chipping on radiator, Flaking behind radiator	11	No	No	N/A	N/A	No	
439	2690	1	1	210	Administrative Office	Main Office	W3	Cracking, Chipping on conduit box	32	No	No	N/A	Desk	No	
440	2690	1	1	210	Administrative Office	Main Office	W4	Cracking	10	No	No	N/A	N/A	No	
441	2690	1	1	210B	Administrative Office	Main Office Assistant Principal's Office	Floor	N/A	N/A	No	Paint chips behind radiator	5	N/A	No	
442	2690	1	1	210B	Administrative Office	Main Office Assistant Principal's Office	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
443	2690	1	1	210B	Administrative Office	Main Office Assistant Principal's Office	W2	Cracking	15	No	No	N/A	N/A	Yes	
444	2690	1	1	210B	Administrative Office	Main Office Assistant Principal's Office	W3	Cracking, Chipping on radiator	20	No	No	N/A	N/A	No	
445	2690	1	1	210B	Administrative Office	Main Office Assistant Principal's Office	W4	Chipping	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
446	2690	1	1	210A	Storage	Main Office Closet	W2	Chipping on metal pipe	1	No	No	N/A	Built in Shelves with stored materials	No	
447	2690	1	1	210A	Storage	Main Office Closet	W3	N/A	N/A	No	No	N/A	Built in Shelves with stored materials	No	Limited inspection due to stored materials
448	2690	1	1	210A	Storage	Main Office Closet	W4	Chipping	1	No	No	N/A	N/A	No	
449	2690	1	1	211	Restrooms, Staff - Male/Female	Main Office Restroom	W1	Chipping on doorframe, Hole	14	No	No	N/A	N/A	Yes	
450	2690	1	1	211	Restrooms, Staff - Male/Female	Main Office Restroom	W2	Hole, paint has been stabilized, Flaking	3	No	No	N/A	N/A	Yes	
451	2690	1	1	211	Restrooms, Staff - Male/Female	Main Office Restroom	W3	Chipping on radiator, Hole	4	No	No	N/A	N/A	Yes	
452	2690	1	1	211	Restrooms, Staff - Male/Female	Main Office Restroom	W4	Cracking, Hole, paint has been stabilized	11	No	No	N/A	N/A	Yes	
453	2690	1	1	203	Administrative Office	Office 203	W1	Chipping on doorframe	5	No	No	N/A	N/A	No	
454	2690	1	1	203	Administrative Office	Office 203	W2	Chipping, Staple Holes	26	No	No	N/A	N/A	No	Repair to sheetrock wall needed
455	2690	1	1	203	Administrative Office	Office 203	W3	Chipping on radiator, Flaking behind radiator	10	No	No	N/A	N/A	No	
456	2690	1	1	203	Administrative Office	Office 203	W4	Cracking, Chipping, Flaking	28	No	No	N/A	N/A	No	
457	2690	1	1	205	Administrative Office	Office 205	W1	Cracking, Hole, paint has been stabilized, Flaking, Significant Moisture Damage	9	Yes	No	N/A	Cabinet	Yes	
458	2690	1	1	205	Administrative Office	Office 205	W2	Chipping	5	No	No	N/A	Posters	No	
459	2690	1	1	205	Administrative Office	Office 205	W3	Hole, paint has been stabilized, Flaking	3	No	No	N/A	N/A	Yes	
460	2690	1	1	205	Administrative Office	Office 205	W4	Holes, paint has been stabilized	2	No	No	N/A	N/A	Yes	
461	2690	1	1	205A	Storage	Office 205 Closet	W1	Cracking, Flaking	13	No	No	N/A	N/A	Yes	
462	2690	1	1	205A	Storage	Office 205 Closet	W2	Cracking, Chipping	6	No	No	N/A	N/A	No	
463	2690	1	1	205A	Storage	Office 205 Closet	W3	Cracking	5	No	No	N/A	Cabinets, Stored Materials	No	Limited inspection due to stored materials
464	2690	1	1	205A	Storage	Office 205 Closet	W4	Cracking, Chipping	13	No	No	N/A	Cabinets, Stored Materials	Yes	Limited inspection due to stored materials
465	2690	1	1	206	Administrative Office	Office 206	W1	Holes, paint has been stabilized on 1	3	No	No	N/A	Built in Cabinets, Shelves with stored materials	Yes	Limited inspection due to stored materials
466	2690	1	1	206	Administrative Office	Office 206	W2	Chipping, Hole, paint has been stabilized	2	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
467	2690	1	1	206	Administrative Office	Office 206	W3	Holes, paint has been stabilized, Flaking on wall and behind radiators and covers	51	No	No	N/A	N/A	Yes	
468	2690	1	1	206	Administrative Office	Office 206	W4	Cracking, Chipping	12	No	No	N/A	N/A	No	
469	2690	1	1	206A	Storage	Office 206 Closet	Ceiling	N/A	N/A	No	No	N/A	N/A	No	This is PSSA closet so only one person has a key
470	2690	1	1	206A	Storage	Office 206 Closet	Floor	N/A	N/A	No	No	N/A	N/A	No	This is PSSA closet so only one person has a key
471	2690	1	1	206A	Storage	Office 206 Closet	W1	N/A	N/A	No	No	N/A	N/A	No	This is PSSA closet so only one person has a key
472	2690	1	1	206A	Storage	Office 206 Closet	W2	Cracking, Flaking	20	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
473	2690	1	1	206A	Storage	Office 206 Closet	W3	Flaking	20	No	No	N/A	Cabinets	No	Limited inspection due to stored materials
474	2690	1	1	206A	Storage	Office 206 Closet	W4	Cracking, Flaking, Coat hooks pulling off wall	66	No	No	N/A	N/A	Yes	This is PSSA closet so only one person has a key
475	2690	1	1	213	Administrative Office	Principal's Office	W1	Cracking, Hole	16	No	No	N/A	N/A	Yes	
476	2690	1	1	213	Administrative Office	Principal's Office	W2	Flaking on wall and behind radiator	10	No	No	N/A	Desk	No	
477	2690	1	1	213	Administrative Office	Principal's Office	W3	Cracking	10	No	No	N/A	Desk	No	
478	2690	1	1	213A	Storage	Principal's Office Storage Area	Floor	N/A	N/A	No	Paint chips in corner of walls 2&3	1	N/A	No	
479	2690	1	1	213A	Storage	Principal's Office Storage Area	W2	Spalling	5	Yes	No	N/A	Stored Materials	Yes	
480	2690	1	1	S4-200	Stairs	Stairwell adjacent to Classroom 202	Ceiling	Flaking	12	No	No	N/A	N/A	No	
481	2690	1	1	S4-200	Stairs	Stairwell adjacent to Classroom 202	Floor	Chipping on cove and railings	33	No	No	N/A	N/A	No	
482	2690	1	1	S4-200	Stairs	Stairwell adjacent to Classroom 202	W1	Chipping on wall, doors and doorframe, Holes, paint has been stabilized, Flaking on doors and doorframe	19	No	No	N/A	N/A	Yes	
483	2690	1	1	S4-200	Stairs	Stairwell adjacent to Classroom 202	W3	Chipping on doors and doorframe, Hole, paint has been stabilized	21	No	No	N/A	N/A	Yes	
484	2690	1	1	S4-200	Stairs	Stairwell adjacent to Classroom 202	W4	Holes, paint has been stabilized	2	No	No	N/A	N/A	Yes	
485	2690	1	1	S18	Circulation (Hallway)	Stairwell adjacent to Classroom 202 Vestibule	W2	Chipping on radiator, Holes, Flaking on wall and radiator heat shield	N/A	No	No	N/A	N/A	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
486	2690	1	1	S18	Circulation (Hallway)	Stairwell adjacent to Classroom 202 Vestibule	W3	Chipping on doors and doorframe, Flaking	N/A	No	No	N/A	N/A	No	
487	2690	1	1	S18	Circulation (Hallway)	Stairwell adjacent to Classroom 202 Vestibule	W4	Holes, paint has been stabilized, Flaking on wall and radiator heat shield	N/A	No	No	N/A	N/A	Yes	
488	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	Ceiling	Flaking	15	No	No	N/A	N/A	No	
489	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	Floor	Chipping on stairs and railings	190	No	No	N/A	N/A	No	
490	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	W1	Chipping on railings, Flaking above windows	8	No	No	N/A	N/A	No	
491	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	W2	Cracking, Chipping on wall and radiator, Holes, paint has been stabilized	13	No	No	N/A	N/A	Yes	
492	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	W3	Holes, some paint has been stabilized	2	No	No	N/A	N/A	Yes	
493	2690	1	1	S2-200	Stairs	Stairwell adjacent to Classroom 207	W4	Cracking, Chipping, Holes, paint has been stabilized	31	No	No	N/A	N/A	Yes	
494	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	Ceiling	Chipping	2	No	No	N/A	N/A	No	
495	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	Floor	Chipping on stairs, cove, and railings	92	No	No	N/A	N/A	No	
496	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	W1	Cracking	2	No	No	N/A	N/A	No	
497	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	W2	Chipping on doors, Gouges	9	No	No	N/A	N/A	No	
498	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	W3	Cracking, Chipping on metal jackets, Flaking on metal pipe, Spalling, Efflorescence	32	Yes	No	N/A	N/A	Yes	
499	2690	1	1	S1-200	Stairs	Stairwell adjacent to Classroom 209	W4	Cracking, Spalling	20	Yes	No	N/A	N/A	Yes	
500	2690	1	1	203B	Circulation (Hallway)	Vestibule 203	W1	Cracking	1	No	No	N/A	N/A	No	
501	2690	1	1	203B	Circulation (Hallway)	Vestibule 203	W2	Cracking, Chipping	2	No	No	N/A	N/A	No	
502	2690	1	1	203B	Circulation (Hallway)	Vestibule 203	W3	Chipping	2	No	No	N/A	N/A	No	
503	2690	1	1	203B	Circulation (Hallway)	Vestibule 203	W4	Chipping	5	No	No	N/A	N/A	No	
504	2690	1	1	203A	Storage	Vestibule 203 Closet	Ceiling	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
505	2690	1	1	203A	Storage	Vestibule 203 Closet	Floor	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
506	2690	1	1	203A	Storage	Vestibule 203 Closet	W1	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
507	2690	1	1	203A	Storage	Vestibule 203 Closet	W2	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
508	2690	1	1	203A	Storage	Vestibule 203 Closet	W3	Chipping	2	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
509	2690	1	1	203A	Storage	Vestibule 203 Closet	W4	N/A	N/A	No	No	N/A	Shelves and Stored Materials	No	Limited inspection due to stored materials
510	2690	2	0	2-100A	Stage	Auditorium Stage	W3	Chipping	20	No	No	N/A	N/A	No	
511	2690	2	0	2-100A	Stage	Auditorium Stage	W4	Chipping	5	No	No	N/A	N/A	No	
512	2690	2	0	2-100	Gymnasium / Auditorium / Cafeteria	Auditorium/Gymnasium/Cafeteria	Ceiling	Flaking on beam	10	No	No	N/A	N/A	No	
513	2690	2	0	2-100	Gymnasium / Auditorium / Cafeteria	Auditorium/Gymnasium/Cafeteria	W1	Cracking, Chipping on wall, doorframe, and office window, Efflorescence	98	Yes	No	N/A	N/A	No	Repair to concrete block wall needed
514	2690	2	0	2-100	Gymnasium / Auditorium / Cafeteria	Auditorium/Gymnasium/Cafeteria	W2	Chipping on wall and metal duct	53	No	No	N/A	N/A	No	
515	2690	2	0	2-100	Gymnasium / Auditorium / Cafeteria	Auditorium/Gymnasium/Cafeteria	W3	Chipping on wall, doors, and frames	75	No	No	N/A	N/A	No	
516	2690	2	0	2-100	Gymnasium / Auditorium / Cafeteria	Auditorium/Gymnasium/Cafeteria	W4	Chipping	10	No	No	N/A	N/A	No	
517	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	Ceiling	Flaking on ceiling and metal ducts	768	No	No	N/A	N/A	No	Restroom is not currently in operation
518	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	Floor	N/A	N/A	No	Paint chips throughout	768	N/A	No	Restroom is not currently in operation
519	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	W1	Flaking	195	No	No	N/A	N/A	No	Restroom is not currently in operation
520	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	W2	Flaking	145	No	No	N/A	N/A	No	Restroom is not currently in operation
521	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	W3	Flaking	195	No	No	N/A	N/A	No	Restroom is not currently in operation
522	2690	1	0	107G	Student Restrooms - Male (4-12)	Basement Boy's Restroom Toilet Area	W4	Flaking	145	No	No	N/A	N/A	No	Restroom is not currently in operation

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
523	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	Ceiling	Flaking on ceiling, metal pipes, and metal ducts	336	No	No	N/A	N/A	No	Restroom is not currently in operation
524	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	Floor	N/A	N/A	No	Paint chips throughout	336	N/A	No	Restroom is not currently in operation
525	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	W1	Flaking	85	No	No	N/A	N/A	No	Restroom is not currently in operation
526	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	W2	Flaking	145	No	No	N/A	N/A	No	Restroom is not currently in operation
527	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	W3	Flaking	85	No	No	N/A	N/A	No	Restroom is not currently in operation
528	2690	1	0	107F	Student Restrooms - Male (4-12)	Basement Boy's Restroom Urinal Area	W4	Flaking	145	No	No	N/A	N/A	No	Restroom is not currently in operation
529	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Ceiling	Cracking on ACM pipe insulation, Flaking on ceiling, metal pipes, and metal ducts	1040	No	No	N/A	Stored Materials	No	Restroom is not currently in operation
530	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	Floor	N/A	N/A	No	Paint chips scattered throughout	200	Stored Materials	No	Restroom is not currently in operation
531	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W1	Flaking	10	No	No	N/A	Stored Materials	No	Restroom is not currently in operation
532	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Restroom is not currently in operation
533	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W3	Flaking	210	No	No	N/A	Stored Materials	No	Restroom is not currently in operation
534	2690	1	0	100	Student Restrooms - Female (4-12)	Basement Girl's Restroom	W4	Flaking	145	No	No	N/A	Stored Materials	No	Restroom is not currently in operation
535	2690	1	0	101	Primary	Classroom 101	Ceiling	Cracking on ACM pipe insulation, Chipping on metal duct, metal pipe, and metal steam pipes, Flaking on metal duct and metal steam pipes, Significant Moisture Damage	275	Yes	No	N/A	Furniture	Yes	Limited inspection due to stored materials
536	2690	1	0	101	Primary	Classroom 101	Floor	N/A	N/A	No	Debris under damaged ceiling	3	Furniture	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
537	2690	1	0	101	Primary	Classroom 101	W1	Cracking, Chipping, Holes, paint has been stabilized	57	No	No	N/A	Posters, Furniture	Yes	
538	2690	1	0	101	Primary	Classroom 101	W2	Chipping, Flaking	12	No	No	N/A	Stored Materials	No	
539	2690	1	0	101	Primary	Classroom 101	W3	Cracking, Holes, paint has been stabilized, Flaking on wall and metal jacket	123	No	Debris in corner of walls 2&3 and corner by restroom	10	File Cabinets, Shelves with stored materials	Yes	Limited inspection due to stored materials
540	2690	1	0	101	Primary	Classroom 101	W4	Cracking	10	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
541	2690	1	0	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	Ceiling	Significant Moisture Damage	4	Yes	No	N/A	N/A	Yes	
542	2690	1	0	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	Floor	N/A	N/A	No	Debris along wall 3	5	N/A	No	
543	2690	1	0	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Restroom	W3	Holes, paint has been stabilized	20	No	No	N/A	N/A	No	
544	2690	1	0	102C	Circulation (Hallway)	Classroom 102 Vestibule	Ceiling	Flaking on and above metal duct	13	No	No	N/A	N/A	No	
545	2690	1	0	102C	Circulation (Hallway)	Classroom 102 Vestibule	W2	Cracking, Chipping	7	No	No	N/A	N/A	No	
546	2690	1	0	102C	Circulation (Hallway)	Classroom 102 Vestibule	W3	Chipping	1	No	No	N/A	N/A	No	
547	2690	1	0	102C	Circulation (Hallway)	Classroom 102 Vestibule	W4	Cracking, Chipping	4	No	No	N/A	N/A	No	
548	2690	1	0	102	Primary	Classroom 102A	Ceiling	Chipping on metal steam pipes, Flaking on ceiling, metal duct, and metal steam pipes	38	No	No	N/A	N/A	No	
549	2690	1	0	102	Primary	Classroom 102A	W1	Chipping	20	No	No	N/A	N/A	No	
550	2690	1	0	102	Primary	Classroom 102A	W2	Holes in sheetrock	15	No	No	N/A	N/A	No	
551	2690	1	0	102	Primary	Classroom 102A	W3	Flaking	1	No	No	N/A	N/A	No	
552	2690	1	0	102	Primary	Classroom 102A	W4	Flaking	7	No	No	N/A	N/A	No	
553	2690	1	0	102B	Primary	Classroom 102B (to Right of Vestibule)	Ceiling	Cracking on ACM pipe insulation, chipping on metal steam pipes	22	No	No	N/A	N/A	No	
554	2690	1	0	102B	Primary	Classroom 102B (to Right of Vestibule)	W1	Chipping	5	No	No	N/A	N/A	No	
555	2690	1	0	102B	Primary	Classroom 102B (to Right of Vestibule)	W2	Chipping	3	No	No	N/A	N/A	No	
556	2690	1	0	102B	Primary	Classroom 102B (to Right of Vestibule)	W3	Chipping on metal jacket, Flaking	2	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
573	2690	1	0	102A	Storage	Closet adjacent to Classroom 102 Vestibule	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
574	2690	1	0	102A	Storage	Closet adjacent to Classroom 102 Vestibule	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
575	2690	1	0	102A	Storage	Closet adjacent to Classroom 102 Vestibule	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
576	2690	1	0	102A	Storage	Closet adjacent to Classroom 102 Vestibule	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
577	2690	1	0	102A	Storage	Closet adjacent to Classroom 102 Vestibule	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
578	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	Ceiling	Flaking	30	No	No	N/A	Stored Equipment	No	
579	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	Floor	N/A	N/A	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
580	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	W1	N/A	N/A	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
581	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	W2	N/A	N/A	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
582	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	W3	N/A	N/A	No	No	N/A	Stored Equipment	No	Limited inspection due to stored materials
583	2690	1	0	101B	Storage	Closet between Classroom 101 and Stairwell	W4	Efflorescence	10	Yes	No	N/A	Stored Equipment	No	
584	2690	1	0	H103D	Administrative Office	Education Works Office	Ceiling	Cracking on ACM pipe insulation	15	No	No	N/A	Stored Materials	No	
585	2690	1	0	H103D	Administrative Office	Education Works Office	Floor	N/A	N/A	No	Paint chips scattered throughout	5	N/A	No	
586	2690	1	0	H103D	Administrative Office	Education Works Office	W2	Chipping	10	No	No	N/A	Desk, File Cabinet, Cabinets	No	
587	2690	2	0	2-104	Lockers - Male	Former Boy's Locker Room	W1	Chipping on doorframe	15	No	No	N/A	Stored Equipment	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
588	2690	2	0	2-104	Lockers - Male	Former Boy's Locker Room	W2	Chipping	18	No	No	N/A	Stored Equipment	No	
589	2690	2	0	2-104	Lockers - Male	Former Boy's Locker Room	W3	Chipping	2	No	No	N/A	Stored Equipment	No	
590	2690	2	0	2-104	Lockers - Male	Former Boy's Locker Room	W4	Chipping on lockers	40	No	No	N/A	Stored Equipment	No	
591	2690	2	0	2-104A	Student Restrooms - Male (4-12)	Former Boy's Locker Room Restroom	W1	Chipping on wall and doorframe	7	No	No	N/A	N/A	No	
592	2690	2	0	2-104A	Student Restrooms - Male (4-12)	Former Boy's Locker Room Restroom	W2	Chipping	3	No	No	N/A	N/A	No	
593	2690	2	0	2-104A	Student Restrooms - Male (4-12)	Former Boy's Locker Room Restroom	W3	Chipping, Flaking on metal jacket	4	Yes	No	N/A	N/A	No	
594	2690	2	0	2-104A	Student Restrooms - Male (4-12)	Former Boy's Locker Room Restroom	W4	Chipping	5	No	No	N/A	N/A	No	
595	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	Ceiling	Chipping on partition at entrance	5	No	No	N/A	Stored Equipment	No	
596	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	Floor	Chipping on center walls for old showers	25	No	No	N/A	Stored Equipment	No	
597	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	W1	Chipping	13	No	No	N/A	Stored Equipment	No	
598	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	W2	Chipping	16	No	No	N/A	Stored Equipment	No	
599	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	W3	Chipping	15	No	No	N/A	Stored Equipment	No	
600	2690	2	0	2-104B	Showers - Male	Former Boy's Locker Room Shower Area	W4	Chipping	18	No	No	N/A	Stored Equipment	No	
601	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	Ceiling	N/A	N/A	No	No	N/A	Stored Gym Equipment	No	Limited inspection due to stored materials
602	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	Floor	N/A	N/A	No	No	N/A	Stored Gym Equipment	No	Limited inspection due to stored materials
603	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	W1	Chipping on wall and doorframe	10	No	No	N/A	Stored Gym Equipment	No	
604	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	W2	N/A	N/A	No	No	N/A	Stored Gym Equipment	No	Limited inspection due to stored materials

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
605	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	W3	Chipping	2	No	No	N/A	Stored Gym Equipment	No	
606	2690	2	0	2-105	Lockers - Female	Former Girl's Locker Room	W4	Cracking, Chipping	13	No	No	N/A	Stored Gym Equipment	No	Repair to concrete block wall needed
607	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	Ceiling	N/A	N/A	No	No	N/A	Cabinets and Stored Gym Equipment	No	Limited inspection due to stored materials
608	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	Floor	Chipping on center walls for old showers	25	No	No	N/A	Cabinets and Stored Gym Equipment	No	
609	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	W1	Chipping	8	No	No	N/A	Cabinets and Stored Gym Equipment	No	
610	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	W2	Chipping	16	No	No	N/A	Cabinets and Stored Gym Equipment	No	
611	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	W3	Chipping	14	No	No	N/A	Cabinets and Stored Gym Equipment	No	
612	2690	2	0	2-105A	Showers - Female	Former Girl's Locker Room Large Shower Area	W4	Chipping	9	No	No	N/A	Cabinets and Stored Gym Equipment	No	
613	2690	2	0	2-105B	Student Restrooms - Female (4-12)	Former Girl's Locker Room Restroom	W1	Chipping	3	No	No	N/A	N/A	No	
614	2690	2	0	2-105B	Student Restrooms - Female (4-12)	Former Girl's Locker Room Restroom	W2	Chipping	6	No	No	N/A	N/A	No	
615	2690	2	0	2-105B	Student Restrooms - Female (4-12)	Former Girl's Locker Room Restroom	W3	Cracking in corner of walls 2&3, Chipping	16	No	No	N/A	N/A	No	Repair to concrete block wall needed
616	2690	2	0	2-105B	Student Restrooms - Female (4-12)	Former Girl's Locker Room Restroom	W4	Chipping	3	No	No	N/A	N/A	No	
617	2690	2	0	2-105C	Showers - Male	Former Girl's Locker Room Small Shower Area	W1	Flaking	5	No	No	N/A	N/A	No	
618	2690	2	0	2-105C	Showers - Male	Former Girl's Locker Room Small Shower Area	W2	Flaking	6	No	No	N/A	N/A	No	
619	2690	2	0	2-105C	Showers - Male	Former Girl's Locker Room Small Shower Area	W3	Cracking in corner of walls 3&4, Flaking	6	No	No	N/A	N/A	No	Repair to concrete block wall needed

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
640	2690	1	0	013A	Storage	Hallway outside Boiler Room Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
641	2690	1	0	013A	Storage	Hallway outside Boiler Room Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
642	2690	1	0	013A	Storage	Hallway outside Boiler Room Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
643	2690	1	0	013A	Storage	Hallway outside Boiler Room Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
644	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	Ceiling	Cracking on ACM pipe insulation, Chipping on metal duct, Flaking on ceiling and metal duct around attached lights	308	No	No	N/A	N/A	No	
645	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	Floor	Chipping along walls and railings	140	No	Paint chips around wall 2 pipes	1	N/A	No	
646	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	W1	Chipping on metal jackets, Flaking on wall and ACM pipe insulation	21	No	No	N/A	N/A	No	
647	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	W2	Chipping on metal pipe	5	No	No	N/A	N/A	No	
648	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	W3	Chipping on metal pipe, Flaking	2	No	No	N/A	N/A	No	
649	2690	1	0	H102	Circulation (Hallway)	Hallway outside Classroom 101	W4	Chipping on doors and frame exterior entrance, Chipping on 3rd set of doors in, Flaking on ACM pipe insulation and wood frame of 2nd set of doors in	44	No	No	N/A	N/A	No	
650	2690	2	0	2-107	Circulation (Hallway)	Hallway outside Gym	W1	Chipping	20	No	No	N/A	N/A	No	
651	2690	2	0	2-107	Circulation (Hallway)	Hallway outside Gym	W2	Cracking in corner of walls 1&2	10	No	No	N/A	N/A	No	Repair to concrete block wall needed
652	2690	2	0	2-107	Circulation (Hallway)	Hallway outside Gym	W3	Chipping	40	No	No	N/A	N/A	No	
653	2690	2	0	2-107	Circulation (Hallway)	Hallway outside Gym	W4	Cracking, Chipping	14	No	No	N/A	N/A	No	Repair to concrete block wall needed
654	2690	1	0	H101	Circulation (Hallway)	Hallway outside Nurse's Office	Ceiling	Chipping on ceiling and metal duct, Flaking on ceiling, ACM pipe insulation, metal pipe, and metal duct	73	No	No	N/A	N/A	No	
655	2690	1	0	H101	Circulation (Hallway)	Hallway outside Nurse's Office	Floor	Chipping along walls	50	No	No	N/A	N/A	No	
656	2690	1	0	H101	Circulation (Hallway)	Hallway outside Nurse's Office	W1	Flaking on wall, metal duct, and bell	4	No	No	N/A	N/A	No	
657	2690	1	0	H101	Circulation (Hallway)	Hallway outside Nurse's Office	W3	Flaking	1	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
658	2690	1	0	H103	Circulation (Hallway)	Hallway outside Storage Room 103-Classroom 104	Ceiling	Cracking on ACM pipe insulation, Flaking on and above metal duct	255	No	No	N/A	N/A	No	
659	2690	1	0	H103	Circulation (Hallway)	Hallway outside Storage Room 103-Classroom 104	Floor	Chipping along walls	20	No	No	N/A	N/A	No	
660	2690	1	0	H103	Circulation (Hallway)	Hallway outside Storage Room 103-Classroom 104	W1	Chipping	5	No	No	N/A	N/A	No	
661	2690	1	0	H103	Circulation (Hallway)	Hallway outside Storage Room 103-Classroom 104	W2	Chipping, Staple Holes, Flaking	51	No	No	N/A	N/A	No	
662	2690	1	0	H103	Circulation (Hallway)	Hallway outside Storage Room 103-Classroom 104	W4	Chipping on wall and metal jackets	12	No	No	N/A	N/A	No	
663	2690	2	0	2-101	Kitchen	Kitchen	Ceiling	N/A	N/A	No	No	N/A	Kitchen Equipment	No	Limited inspection due to stored materials
664	2690	2	0	2-101	Kitchen	Kitchen	Floor	N/A	N/A	No	No	N/A	Kitchen Equipment	No	Limited inspection due to stored materials
665	2690	2	0	2-101	Kitchen	Kitchen	W1	Hole, Chipping on door and frame	21	No	No	N/A	Kitchen Equipment	No	Repair to concrete block wall needed
666	2690	2	0	2-101	Kitchen	Kitchen	W2	Chipping on wall, doors, and frames	25	No	No	N/A	Kitchen Equipment	No	
667	2690	2	0	2-101	Kitchen	Kitchen	W3	Chipping	10	No	No	N/A	Kitchen Equipment	No	
668	2690	2	0	2-101	Kitchen	Kitchen	W4	Chipping	3	No	No	N/A	Kitchen Equipment	No	
669	2690	2	0	2-103	Restrooms, Staff - Male/Female	Kitchen Restroom 115A	W1	Cracking, Chipping on wall and doorframe	19	No	No	N/A	N/A	No	
670	2690	2	0	2-103	Restrooms, Staff - Male/Female	Kitchen Restroom 115A	W2	Chipping	5	No	No	N/A	N/A	No	
671	2690	2	0	2-103	Restrooms, Staff - Male/Female	Kitchen Restroom 115A	W3	Cracking in corner of walls 3&4, Chipping	15	No	No	N/A	N/A	No	
672	2690	2	0	2-103	Restrooms, Staff - Male/Female	Kitchen Restroom 115A	W4	Chipping	3	No	No	N/A	N/A	No	
673	2690	2	0	2-102	Lockers - Female	Kitchen Staff Locker Room	W1	Chipping on doorframe	2	No	No	N/A	N/A	No	
674	2690	2	0	2-102	Lockers - Female	Kitchen Staff Locker Room	W3	Cracking, Chipping	6	No	No	N/A	N/A	No	Repair to concrete block wall needed
675	2690	2	0	2-102	Lockers - Female	Kitchen Staff Locker Room	W4	Chipping on lockers	5	No	No	N/A	N/A	No	
676	2690	2	0	2-109	Restrooms, Staff - Male	Men's Restroom near Gym	W1	Chipping on door and frame, Flaking	22	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
677	2690	2	0	2-109	Restrooms, Staff - Male	Men's Restroom near Gym	W2	Flaking	1	No	No	N/A	N/A	No	
678	2690	2	0	2-109	Restrooms, Staff - Male	Men's Restroom near Gym	W3	Flaking	5	No	No	N/A	N/A	No	
679	2690	2	0	2-109	Restrooms, Staff - Male	Men's Restroom near Gym	W4	Flaking	3	No	No	N/A	N/A	No	
680	2690	1	0	107D	Health Service Room	Nurse's Office 108	Ceiling	Cracking on ACM pipe insulation, Flaking on ceiling beams	76	No	No	N/A	Furniture	No	
681	2690	1	0	107D	Health Service Room	Nurse's Office 108	Floor	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored materials
682	2690	1	0	107D	Health Service Room	Nurse's Office 108	W1	Chipping	2	No	No	N/A	Furniture	No	
683	2690	1	0	107D	Health Service Room	Nurse's Office 108	W2	Cracking, Chipping, Flaking	16	No	No	N/A	Furniture	No	
684	2690	1	0	107D	Health Service Room	Nurse's Office 108	W3	Cracking, Chipping, Hole, Efflorescence	33	Yes	No	N/A	Furniture	Yes	
685	2690	1	0	107D	Health Service Room	Nurse's Office 108	W4	Flaking	15	No	No	N/A	Furniture	No	
686	2690	1	0	107E	Student Restrooms - Male/Female	Nurse's Office 108 Restroom	Ceiling	Cracking on ACM pipe insulation, Flaking	16	No	No	N/A	N/A	No	
687	2690	1	0	107E	Student Restrooms - Male/Female	Nurse's Office 108 Restroom	W1	Chipping on doorframe	2	No	No	N/A	N/A	No	
688	2690	1	0	107E	Student Restrooms - Male/Female	Nurse's Office 108 Restroom	W2	Cracking, Holes, paint has been stabilized	7	No	No	N/A	N/A	No	
689	2690	1	0	107E	Student Restrooms - Male/Female	Nurse's Office 108 Restroom	W3	Holes, paint has been stabilized, Flaking	16	No	No	N/A	N/A	No	
690	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	Ceiling	Cracking on ACM pipe insulation, Holes on ceiling beams, Flaking on ceiling beams and metal ducts, some in cage	165	No	No	N/A	Tables, Books	Yes	Limited inspection due to stored materials
691	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	Floor	N/A	N/A	No	Paint chips in cage area	5	Tables, Books	No	Limited inspection due to stored materials
692	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	W1	Cracking, Chipping on wall and cove, Flaking, some in air shaft	37	No	No	N/A	Tables, Books	No	
693	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	W2	Chipping, Flaking	35	No	No	N/A	Tables, Books	No	
694	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	W3	Cracking, Chipping, Flaking on wall and metal jacket in cage, Efflorescence in cage	39	Yes	No	N/A	Tables, Books	Yes	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
695	2690	1	0	107C	Health Service Room	Nurse's Office 108 Waiting Area	W4	Hole in cage, Flaking on wall in cage and on built in wood cabinets	21	No	No	N/A	Tables, Books	Yes	
696	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	Ceiling	Flaking	66	No	No	N/A	Stored Materials	No	
697	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	Floor	N/A	N/A	No	Paint chips on floor and stored materials	66	Stored Materials	No	Limited inspection due to stored materials
698	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	W1	Flaking on metal duct	1	No	No	N/A	Stored Materials	No	
699	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
700	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
701	2690	1	0	H103B	Closed Circuit Storage Area	Security Camera Room	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
702	2690	1	0	107B	Storage	Security Office Closet	Ceiling	Cracking on ACM pipe insulation	49	No	No	N/A	Stored Materials	No	
703	2690	1	0	107B	Storage	Security Office Closet	Floor	Chipping	96	No	Debris in corner of walls 2&3	3	Stored Materials	No	Limited inspection due to stored materials
704	2690	1	0	107B	Storage	Security Office Closet	W1	Cracking, Holes	4	No	No	N/A	Stored Materials	Yes	Hallway entrance
705	2690	1	0	107B	Storage	Security Office Closet	W2	Chipping on metal pipe, Holes, paint has been stabilized	11	No	No	N/A	Stored Materials	Yes	
706	2690	1	0	107B	Storage	Security Office Closet	W3	Holes, paint has been stabilized	20	No	No	N/A	Stored Materials	Yes	
707	2690	1	0	107B	Storage	Security Office Closet	W4	Flaking	1	No	No	N/A	Stored Materials	No	
708	2690	1	0	S3-100	Stairs	Stairwell across from Building Engineer's Office	Ceiling	Flaking	60	No	No	N/A	N/A	No	
709	2690	1	0	S3-100	Stairs	Stairwell across from Building Engineer's Office	Floor	N/A	N/A	No	Paint chips	5	N/A	No	
710	2690	1	0	S3A-100	Circulation (Hallway)	Stairwell across from Building Engineer's Office Vestibule	Ceiling	Flaking	85	No	No	N/A	N/A	No	
711	2690	1	0	S3A-100	Circulation (Hallway)	Stairwell across from Building Engineer's Office Vestibule	Floor	N/A	N/A	No	Paint chips	5	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
712	2690	1	0	S3A-100	Circulation (Hallway)	Stairwell across from Building Engineer's Office Vestibule	W1	Chipping on door and frame	5	No	No	N/A	N/A	No	
713	2690	1	0	S1-100	Stairs	Stairwell adjacent to Basement Boy's Restroom	Ceiling	Chipping	3	No	No	N/A	N/A	No	
714	2690	1	0	S1-100	Stairs	Stairwell adjacent to Basement Boy's Restroom	W1	Flaking above pipes	35	No	No	N/A	N/A	No	
715	2690	1	0	S1-100	Stairs	Stairwell adjacent to Basement Boy's Restroom	W2	Chipping on door and frame	20	No	No	N/A	N/A	No	
716	2690	1	0	S1-100	Stairs	Stairwell adjacent to Basement Boy's Restroom	W3	Chipping on side of stairs	10	No	No	N/A	N/A	No	
717	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
718	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
719	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
720	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
721	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
722	2690	1	0	S1A	Storage	Stairwell adjacent to Basement Boy's Restroom Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
723	2690	1	0	S4-100	Stairs	Stairwell adjacent to Classroom 102	Ceiling	Flaking	3	No	No	N/A	N/A	No	
724	2690	1	0	S4-100	Stairs	Stairwell adjacent to Classroom 102	Floor	Chipping on stairs	3	No	No	N/A	N/A	No	
725	2690	1	0	S4-100	Stairs	Stairwell adjacent to Classroom 102	W2	Cracking, Chipping on doors and frame	17	No	No	N/A	N/A	No	
726	2690	1	0	S4-100	Stairs	Stairwell adjacent to Classroom 102	W3	Hole, paint has been stabilized	1	No	No	N/A	N/A	Yes	
727	2690	1	0	S2-100	Stairs	Stairwell adjacent to Nurse's Office	Ceiling	Flaking	10	No	No	N/A	N/A	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
728	2690	1	0	S2-100	Stairs	Stairwell adjacent to Nurse's Office	W1	Chipping on door and frame, Flaking	13	No	No	N/A	N/A	No	
729	2690	1	0	S2-100	Stairs	Stairwell adjacent to Nurse's Office	W3	Chipping on doors and frame, including center doors. Holes, paint has been stabilized, Flaking paint on doors and frame	52	No	No	N/A	N/A	Yes	
730	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
731	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
732	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
733	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
734	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
735	2690	1	0	S2A	Storage	Stairwell adjacent to Nurse's Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	
736	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	Ceiling	Flaking	8	No	No	N/A	Boxes	No	Limited inspection due to boxes
737	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	Floor	N/A	N/A	No	Paint chips	15	Boxes	No	Limited inspection due to boxes
738	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	W1	Flaking	2	No	No	N/A	Boxes	No	Limited inspection due to boxes
739	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	W2	N/A	N/A	No	No	N/A	Boxes	No	Limited inspection due to boxes
740	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	W3	Cracking, Chipping, Flaking	16	No	No	N/A	Boxes	No	Limited inspection due to boxes
741	2690	1	0	100A	Storage	Storage Closet adjacent to Girl's Restroom	W4	Cracking, Chipping, Flaking	7	No	No	N/A	Boxes	No	Limited inspection due to boxes
742	2690	1	0	103	Storage	Storage Room 103	Ceiling	Cracking on ACM pipe insulation	94	No	No	N/A	N/A	No	
743	2690	1	0	103	Storage	Storage Room 103	W1	Cracking, Flaking	9	No	No	N/A	Shelves	No	

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
744	2690	1	0	103	Storage	Storage Room 103	W2	Chipping	1	No	No	N/A	N/A	No	
745	2690	1	0	103	Storage	Storage Room 103	W3	Chipping, Flaking on metal jackets	6	No	Debris on outlets	1	Stored Materials	No	
746	2690	1	0	103	Storage	Storage Room 103	W4	Cracking	25	No	No	N/A	Shelves	No	
747	2690	1	0	H103C	Storage	Storage Room 300	Ceiling	Flaking on ceiling and metal duct	104	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
748	2690	1	0	H103C	Storage	Storage Room 300	Floor	N/A	N/A	No	Paint chips	84	Stored Materials	No	Limited inspection due to stored materials
749	2690	1	0	H103C	Storage	Storage Room 300	W1	Chipping, Gouges in sheetrock, Flaking on metal duct	7	No	No	N/A	Stored Materials	No	
750	2690	1	0	H103C	Storage	Storage Room 300	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
751	2690	1	0	H103C	Storage	Storage Room 300	W3	Flaking	25	No	No	N/A	Stored Materials	No	
752	2690	1	0	H103C	Storage	Storage Room 300	W4	Gouges in sheetrock, Flaking	8	No	No	N/A	Stored Materials	No	
753	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	Ceiling	Flaking	72	No	No	N/A	Stored Materials	No	
754	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
755	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	W1	Flaking on metal duct	1	No	No	N/A	Stored Materials	No	
756	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
757	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
758	2690	1	0	H103A	Storage	Storage Room adjacent to Classroom 104	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
759	2690	2	0	121A	Storage	Storage Room to Left of Stage	Ceiling	Chipping on metal ducts	10	No	No	N/A	Stored Materials	No	
760	2690	2	0	121A	Storage	Storage Room to Left of Stage	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
761	2690	2	0	121A	Storage	Storage Room to Left of Stage	W1	Chipping on doorframe	5	No	No	N/A	Stored Materials	No	
762	2690	2	0	121A	Storage	Storage Room to Left of Stage	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
763	2690	2	0	121A	Storage	Storage Room to Left of Stage	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
764	2690	2	0	121A	Storage	Storage Room to Left of Stage	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

