

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2580	1	1	101	Primary	Head Start Classroom 101	W2	Peeling and Cracking paint	50	No	None		None		
2	2580	1	1	101	Primary	Head Start Classroom 101	W3	Cracking paint & Efflorescence	30	No	None		None	Y	
3	2580	1	1	101	Primary	Head Start Classroom 101	W4	Cracking paint	30	No	None		None		
4	2580	1	1	101	Student Restrooms - Male/Female (Classroom)	Classroom 101 Storage Room	W1	Peeling paint	10	No	None		None		
5	2580	1	1	101	Student Restrooms - Male/Female (Classroom)	Classroom 101 Storage Room	W2	Peeling paint by riser	15	No	None		None		
6	2580	1	1	101	Student Restrooms - Male/Female (Classroom)	Classroom 101 Storage Room	W3	Peeling paint	5	No	None		None		
7	2580	1	1	101A	Student Restrooms - Male/Female (Classroom)	Classroom 101 Storage Room	W4	Peeling paint	15	No	None		None		
8	2580	1	1	101B	Primary	Classroom 102	W1	Cracking paint	20	No	None		None		
9	2580	1	1	101B	Primary	Classroom 102	W2	Cracking paint	10	No	None		None		
10	2580	1	1	101B	Primary	Classroom 102	W3	Cracking & Peeling paint	25	No	None		None		
11	2580	1	1	102	Primary	Classroom 102	W4	Cracking, & Peeling paint at door	20	No	None		None		
12	2580	1	1	102	Primary	Classroom 102	Ceiling	Peeling paint above drop ceiling (seen through the missing ceiling tile)	8	No	None		None		
13	2580	1	1	102	Storage	Classroom 102 Closet	W1	Cracking & Peeling paint	20	No	None		None		
14	2580	1	1	102	Storage	Classroom 102 Closet	W2	Cracking	20	No	None		None		
15	2580	1	1	102	Storage	Classroom 102 Closet	W3	Cracking & Severe peeling paint	40	No	None		None		
16	2580	1	1	102A	Storage	Classroom 102 Closet	W4	Cracking	20	No	None		None		
17	2580	1	1	102A	Primary	Classroom 103	W1	Cracking paint	30	No	None		None		
18	2580	1	1	102A	Primary	Classroom 103	W2	Cracking paint	30	No	None		None		
19	2580	1	1	102A	Primary	Classroom 103	W3	Cracking & Peeling paint	40	No	None		None		
20	2580	1	1	103	Primary	Classroom 103	W4	Cracking paint	20	No	None		None		
21	2580	1	1	103	Storage	Classroom 103 Coat Closet	W1	Cracking paint	5	No	None		None		
22	2580	1	1	103	Storage	Classroom 103 Coat Closet	W2	Cracking paint	5	No	None		None		
23	2580	1	1	103	Storage	Classroom 103 Coat Closet	W3	Cracking & Peeling paint	20	No	None		None		
24	2580	1	1	103A	Storage	Classroom 103 Coat Closet	W4	Cracking	5	No	None		None		
25	2580	1	1	103A	Storage	Classroom 103 Coat Closet	Ceiling	Cracking & Peeling paint	25	No	None		None		
26	2580	1	1	103B	Storage	Classroom 103 Closet	Ceiling	Cracking & Peeling paint	30	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
27	2580	1	1	103B	Primary	Classroom 104	W1	Cracking paint below the blackboard	30	No	None		None		
28	2580	1	1	103B	Primary	Classroom 104	W2	Cracking paint below the blackboard	30	No	None		None		
29	2580	1	1	103B	Primary	Classroom 104	W3	Cracking & Peeling paint	40	No	None		None		
30	2580	1	1	104	Primary	Classroom 104	W4	Cracking & Peeling paint	40	No	None		None		
31	2580	1	1	104	Storage	Classroom 104 Closet	W1	No access		No	None		None		
32	2580	1	1	104	Storage	Classroom 104 Closet	W2	No access		No	None		None		
33	2580	1	1	104	Storage	Classroom 104 Closet	W3	No access		No	None		None		
34	2580	1	1	104A	Storage	Classroom 104 Closet	W4	No access		No	None		None		
35	2580	1	1	104A	Storage	Classroom 104 Closet	Ceiling	No access		No	None		None		
36	2580	1	1	104A	Storage	Classroom 104 Closet	Floor	No access		No	None		None		
37	2580	1	1	104B	Primary	Counselor's Office Room 105	W1	Cracking paint	30	No	None		None		
38	2580	1	1	104B	Primary	Counselor's Office Room 105	W2	Cracking paint	10	No	None		None		
39	2580	1	1	104B	Primary	Counselor's Office Room 105	W3	Peeling paint at columns & behind radiators	30	No	None		None		
40	2580	1	1	105	Primary	Counselor's Office Room 105	W4	Cracking paint	20	No	None		None		
41	2580	1	1	105	Primary	Room 105 Counselor's Sub Office	W1	No access		No	None		None		
42	2580	1	1	105	Primary	Room 105 Counselor's Sub Office	W2	No access		No	None		None		
43	2580	1	1	105	Primary	Room 105 Counselor's Sub Office	W3	No access		No	None		None		
44	2580	1	1	105.1	Primary	Room 105 Counselor's Sub Office	W4	No access		No	None		None		
45	2580	1	1	105.1	Primary	Room 105 Counselor's Sub Office	Ceiling	No access		No	None		None		
46	2580	1	1	105.1	Primary	Room 105 Counselor's Sub Office	Floor	No access		No	None		None		
47	2580	1	1	105.1	Storage	Counselor's Office Closet	W1	No access		No	None		None		
48	2580	1	1	105.1	Storage	Counselor's Office Closet	W2	No access		No	None		None		
49	2580	1	1	105.1	Storage	Counselor's Office Closet	W3	No access		No	None		None		
50	2580	1	1	105A	Storage	Counselor's Office Closet	W4	No access		No	None		None		
51	2580	1	1	105A	Storage	Counselor's Office Closet	Ceiling	No access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
52	2580	1	1	105A	Storage	Counselor's Office Closet	Floor	No access		No	None		None		
53	2580	1	1	105A	Primary	Classroom 106	W1	Cracking & Peeling paint	50	No	None		None		
54	2580	1	1	105A	Primary	Classroom 106	W2	Cracking paint	30	No	None		None		
55	2580	1	1	105A	Primary	Classroom 106	W3	Peeling paint behind radiators/casing	40	No	None		None		
56	2580	1	1	106	Primary	Classroom 106	W4	Cracking & Peeling paint	30	No	None		None		
57	2580	1	1	106	Storage	Classroom 106 Coat Closet	W1	Cracking paint	30	No	None		None		
58	2580	1	1	106	Storage	Classroom 106 Coat Closet	W2	Cracking paint	10	No	None		None		
59	2580	1	1	106	Storage	Classroom 106 Coat Closet	W3	Cracking paint	30	No	None		None		
60	2580	1	1	106A	Storage	Classroom 106 Coat Closet	Ceiling	Peeling paint above drop ceiling (seen through the missing ceiling tile)	8	No	None		None		
61	2580	1	1	106A	Primary	Room 107 Teacher's Lounge	W1	Cracking paint	10	No	None		None		
62	2580	1	1	106A	Primary	Room 107 Teacher's Lounge	W2	Cracking paint & Damaged plaster	20	No	None		None	Yes	
63	2580	1	1	106A	Primary	Room 107 Teacher's Lounge	W3	Cracking paint at columns, peeling paint behind radiators	40	No	None		None		
64	2580	1	1	107	Primary	Room 107 Teacher's Lounge	W4	Cracking paint	10	No	None		None		
65	2580	1	1	107	Storage	Room 107 Teacher's Lounge Staff Closet	W1	No access		No	None		None		
66	2580	1	1	107	Storage	Room 107 Teacher's Lounge Staff Closet	W2	No access		No	None		None		
67	2580	1	1	107	Storage	Room 107 Teacher's Lounge Staff Closet	W3	No access		No	None		None		
68	2580	1	1	107A	Storage	Room 107 Teacher's Lounge Staff Closet	W4	No access		No	None		None		
69	2580	1	1	107A	Storage	Room 107 Teacher's Lounge Staff Closet	Ceiling	No access		No	None		None		
70	2580	1	1	107A	Storage	Room 107 Teacher's Lounge Staff Closet	Floor	No access		No	None		None		
71	2580	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W1	No access		No	None		None		
72	2580	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W2	No access		No	None		None		
73	2580	1	1	107A	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W3	No access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Fl oor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
74	2580	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	W4	No access		No	None		None		
75	2580	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	Ceiling	No access		No	None		None		
76	2580	1	1	107B	Student Restrooms - Male/Female (Classroom)	Classroom 107 Restroom	Floor	No access		No	None		None		
77	2580	1	1	107B	Primary	Classroom 108	W1	Peeling paint	10	No	None		None		
78	2580	1	1	107B	Primary	Classroom 108	W2	Peeling paint	10	No	None		None		
79	2580	1	1	107B	Primary	Classroom 108	W3	Severe peeling paint at radiators, peeling paint & damaged plaster at columns	50	No	None		None		
80	2580	1	1	108	Primary	Classroom 108	W4	Flaking paint	20	No	None		None		
81	2580	1	1	108	Storage	Classroom 108 Coat Closet	W1	Cracking paint	5	No	None		None		
82	2580	1	1	108	Storage	Classroom 108 Coat Closet	W2	Severe peeling paint at columns	30	No	None		None		
83	2580	1	1	108	Storage	Classroom 108 Coat Closet	W3	Cracking & Flaking paint	20	No	None		None		
84	2580	1	1	108A	Primary	Classroom 109	W1	Cracking paint	5	No	None		None		
85	2580	1	1	108A	Primary	Classroom 109	W2	Cracking paint	30	No	None		None		
86	2580	1	1	108A	Primary	Classroom 109	W3	Severe peeling paint at radiators, Cracking paint at columns	50	No	None		None		
87	2580	1	1	109	Primary	Classroom 109	W4	Cracking & Flaking paint	20	No	None		None		
88	2580	1	1	109	Storage	Classroom 109 Storage Closet	W1	No access		No	None		None		
89	2580	1	1	109	Storage	Classroom 109 Storage Closet	W2	No access		No	None		None		
90	2580	1	1	109	Storage	Classroom 109 Storage Closet	W3	No access		No	None		None		
91	2580	1	1	109A	Storage	Classroom 109 Storage Closet	W4	No access		No	None		None		
92	2580	1	1	109A	Storage	Classroom 109 Storage Closet	Ceiling	No access		No	None		None		
93	2580	1	1	109A	Storage	Classroom 109 Storage Closet	Floor	No access		No	None		None		
94	2580	1	1	109A	Stairs	Side Entrance to 110	W1	Cracking paint	10	No	None		None		
95	2580	1	1	109A	Stairs	Side Entrance to 110	W2	Cracking, Spalling, Flaking paint	30	No	None		None		
96	2580	1	1	109A	Stairs	Side Entrance to 110	W3	Peeling paint	5	No	None		None		
97	2580	1	1	110A	Stairs	Side Entrance to 110	W4	Cracking paint	30	No	None		None		
98	2580	1	1	110A	Stairs	Side Entrance to 110	Ceiling	Peeling paint above drop ceiling (seen through the missing ceiling tile)	10	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
99	2580	1	1	110A	Storage	Classroom 110 Storage Closet	W1	No access		No	None		None		
100	2580	1	1	110A	Storage	Classroom 110 Storage Closet	W2	No access (severe peeling paint could be seen through the door)	20	No	None		None		
101	2580	1	1	110A	Storage	Classroom 110 Storage Closet	W3	No access (severe peeling paint could be seen through the door)	20	No	None		None		
102	2580	1	1	110B	Storage	Classroom 110 Storage Closet	W4	No access (severe peeling paint could be seen through the door)	20	No	None		None		
103	2580	1	1	110B	Storage	Classroom 110 Storage Closet	Ceiling	No access		No	None		None		
104	2580	1	1	110B	Storage	Classroom 110 Storage Closet	Floor	No access		No	None		None		
105	2580	1	1	110B	Primary	Classroom 110	W1	Cracking & Peeling paint	20	No	None		None		
106	2580	1	1	110B	Primary	Classroom 110	W2	Severe peeling paint & Efflorescence	50	No	None		None		
107	2580	1	1	110B	Primary	Classroom 110	W3	Cracking & Peeling paint	20	No	None		None		
108	2580	1	1	110	Primary	Classroom 110	W4	Cracking paint	20	No	None		None		
109	2580	1	1	110	Primary	Classroom 110	Ceiling	Cracking paint at stage ceiling	10	No	None		None		
110	2580	1	1	110	Administrative Office	Principal's Office	W1	Peeling paint at column	20	No	None		None		
111	2580	1	1	110	Administrative Office	Principal's Office	W2	Severe peeling paint	40	No	None		None		
112	2580	1	1	110	Administrative Office	Principal's Office	W3	Severe peeling paint behind computer desk	50	No	None		None		
113	2580	1	1	111A	Administrative Office	Principal's Office	W4	Cracking, Chipping, and peeling paint	75	No	None		None		
114	2580	1	1	111A	Restrooms, Staff - Male/Female	Principal's Office Restroom	W1	Cracking paint	5	No	None		None		
115	2580	1	1	111A	Restrooms, Staff - Male/Female	Principal's Office Restroom	W2	Cracking paint	5	No	None		None		
116	2580	1	1	111A	Restrooms, Staff - Male/Female	Principal's Office Restroom	W3	Cracking paint	5	No	None		None		
117	2580	1	1	111B	Restrooms, Staff - Male/Female	Principal's Office Restroom	W4	Cracking paint	5	No	None		None		
118	2580	1	1	111B	Restrooms, Staff - Male/Female	Principal's Office Restroom	Ceiling	Cracking paint	20	No	None		None		
119	2580	1	1	111C	Administrative Office	Main Office	W1	Cracking & Chipping paint	15	No	None		None		
120	2580	1	1	111C	Administrative Office	Main Office	W2	Cracking & Peeling paint	30	No	None		None		
121	2580	1	1	111C	Administrative Office	Main Office	W3	Peeling paint	10	No	None		None		
122	2580	1	1	111	Administrative Office	Main Office	W4	Cracking paint & hole in plaster	20	No	None		None	Yes	
123	2580	1	1	111	Administrative Office	Conference Room	W1	Severe peeling paint on door	40	No	None		None		
124	2580	1	1	111	Administrative Office	Conference Room	W2	Peeling paint	5	No	None		None		
125	2580	1	1	111	Administrative Office	Conference Room	W3	Peeling paint around windows	10	No	None		None		
126	2580	1	1	112	Administrative Office	Conference Room	W4	Peeling paint & Damaged plaster	20	No	None		None	Yes	

Kirkbride -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
127	2580	1	1	112	Administrative Office	Conference Room	Floor	Baseboard	20	No	None		None		
128	2580	1	1	112	Administrative Office	Conference Room Restroom	W1	Severe peeling paint on door	30	No	None		None		
129	2580	1	1	112	Administrative Office	Conference Room Restroom	W2	Peeling paint	5	No	None		None		
130	2580	1	1	112	Administrative Office	Conference Room Restroom	W3	Peeling paint	5	No	None		None		
131	2580	1	1	112A	Storage	Main Office Closet on the left side	Ceiling	Peeling paint	5	No	None		None		
132	2580	1	1	112A	Storage	Main Office Closet/File Room on the right side	W1	Peeling paint	5	No	None		None		
133	2580	1	1	112A	Storage	Main Office Closet/File Room on the right side	W2	Severe peeling paint	20	No	None		None		
134	2580	1	1	112C	Administrative Office	Main Office Copy Room	W1	Severe peeling paint	20	No	None		None		
135	2580	1	1	112C	Administrative Office	Main Office Copy Room	W2	Cracking paint	5	No	None		None		
136	2580	1	1	112C	Administrative Office	Main Office Copy Room	W3	Cracking paint	5	No	None		None		
137	2580	1	1	112B	Administrative Office	Main Office Copy Room	W4	Cracking paint	5	No	None		None		
138	2580	1	1	112B	Administrative Office	Nurse's Office	W1	Cracking paint	5	No	None		None		
139	2580	1	1	112B	Administrative Office	Nurse's Office	W2	Cracking paint, and damaged plaster by door	10	No	None		None		
140	2580	1	1	112B	Administrative Office	Nurse's Office	W3	Peeling paint behind radiator	10	No	None		None		
141	2580	1	1	113	Administrative Office	Nurse's Office	W4	Cracking paint	5	No	None		None		
142	2580	1	1	113	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W1	Cracking paint	15	No	None		None		
143	2580	1	1	113	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W2	Cracking paint	5	No	None		None		
144	2580	1	1	113	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W3	Cracking paint	10	No	None		None		
145	2580	1	1	113B	Restrooms, Staff - Male/Female	Nurse's Office Restroom	W4	Cracking paint	20	No	None		None		
146	2580	1	1	113B	Student Restrooms - Male/Female (Classroom)	Kindergarten Restroom by Classroom 106	W1	Peeling paint	40	No	None		None		
147	2580	1	1	113B	Student Restrooms - Male/Female (Classroom)	Kindergarten Restroom by Classroom 106	W2	Peeling paint & Efflorescence	100	No	None		None	Yes	
148	2580	1	1	113B	Student Restrooms - Male/Female (Classroom)	Kindergarten Restroom by Classroom 106	W3	Peeling paint & Efflorescence	50	No	None		None	Yes	

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
149	2580	1	1	120	Student Restrooms - Male/Female (Classroom)	Kindergarten Restroom by Classroom 106	W4	Peeling paint	50	No	None		None		
150	2580	1	1	120	Student Restrooms - Male/Female (Classroom)	Kindergarten Restroom by Classroom 106	Ceiling	Peeling paint & Efflorescence & Pipe	100	No	None		None	Yes	
151	2580	1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Cracking paint	5	No	None		None		
152	2580	1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Cracking paint	15	No	None		None		
153	2580	1	1	120	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Cracking paint & Flaking paint	10	No	None		None		
154	2580	1	1	121	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Cracking paint & Pipe	30	No	None		None		
155	2580	1	1	121	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Peeling paint & Efflorescence	40	No	None		None	Yes	
156	2580	1	1	121	Restrooms, Staff - Female	Women's Lounge	W1	Cracking paint on wall and door (varnish)	30	No	None		None		
157	2580	1	1	121	Restrooms, Staff - Female	Women's Lounge	W2	Cracking paint & peeling paint	15	No	None		None		
158	2580	1	1	121	Restrooms, Staff - Female	Women's Lounge	W3	Severely damaged plaster	15	No	None		None	Yes	
159	2580	1	1	122	Restrooms, Staff - Female	Women's Lounge	W4	Cracking paint and holes in plaster	15	No	None		None		
160	2580	1	1	122	Restrooms, Staff - Female	Women's Lounge Restroom	W1	Peeling paint & Efflorescence	10	No	None		None		
161	2580	1	1	122	Restrooms, Staff - Female	Women's Lounge Restroom	W2	Peeling paint behind radiator	10	No	None		None		
162	2580	1	1	122	Restrooms, Staff - Female	Women's Lounge Restroom	W3	Cracking paint	25	No	None		None		
163	2580	1	1	122A	Restrooms, Staff - Female	Women's Lounge Restroom	W4	Cracking paint	10	No	None		None		
164	2580	1	1	122A	Restrooms, Staff - Female	Women's Lounge Restroom	Ceiling	Cracking paint	5	No	None		None		
165	2580	1	1	122A	Circulation (Hallway)	Hallway from Classrooms 106 to 109	W1	Cracking paint	15	No	None		None		
166	2580	1	1	122A	Circulation (Hallway)	Hallway from Classrooms 106 to 109	W2	Damaged plaster at entrance to Room 108	5	No	None		None	Yes	
167	2580	1	1	122A	Circulation (Hallway)	Hallway from Classrooms 106 to 109	W3	-		No	None		None		
168	2580	1	1	H13	Circulation (Hallway)	Hallway from Classrooms 106 to 109	W4	Peeling & Cracking paint on wall, Peeling paint on pipe	40	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
169	2580	1	1	H13	Circulation (Hallway)	Main Hallway in Front of Main Office	W1	Severe peeling paint & Cracking paint	150	No	None		None		
170	2580	1	1	H13	Circulation (Hallway)	Main Hallway in Front of Main Office	W2	-		No	None		None		
171	2580	1	1	H13	Circulation (Hallway)	Main Hallway in Front of Main Office	W3	Severe peeling paint & Cracking paint	150	No	None		None		
172	2580	1	1	H14	Circulation (Hallway)	Main Hallway in Front of Main Office	W4	-		No	None		None		
173	2580	1	1	H14	Circulation (Hallway)	Main Hallway in Front of Main Office	Floor	Baseboard	30	No	None		None		
174	2580	1	1	H14	Circulation (Hallway)	Main Entrance Hallway	W1	Severe peeling paint & Efflorescence	70	No	None		None	Yes	
175	2580	1	1	H14	Circulation (Hallway)	Main Entrance Hallway	W2	Severe peeling paint & Efflorescence	80	No	None		None	Yes	
176	2580	1	1	H14	Circulation (Hallway)	Main Entrance Hallway	W3	Cracking paint	15	No	None		None		
177	2580	1	1	H14A	Circulation (Hallway)	Main Entrance Hallway	W4	Cracking & Peeling paint	40	No	None		None		
178	2580	1	1	H14A	Circulation (Hallway)	Main Entrance Hallway	Ceiling	Severe peeling paint & Efflorescence	50	No	None		None	Yes	
179	2580	1	1	H14A	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W1	-		No	None		None		
180	2580	1	1	H14A	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W2	Cracking & Peeling paint	5	No	None		None		
181	2580	1	1	H14A	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W3	Cracking paint	5	No	None		None		
182	2580	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	W4	Cracking paint along wall & Damaged plaster by fire tower	100	No	None		None	Yes	
183	2580	1	1	H15	Circulation (Hallway)	Hallway from Classrooms 101 to 104	Floor	Baseboard	10	No	None		None		
184	2580	1	1	H15	Stairs	Stairwell next to Classroom 106	W1	Cracking paint	30	No	None		None		
185	2580	1	1	H15	Stairs	Stairwell next to Classroom 106	W2	Peeling paint on door	10	No	None		None		
186	2580	1	1	H15	Stairs	Stairwell next to Classroom 106	W3	Cracking & Peeling paint, Damaged plaster	30	No	None		None	Yes	
187	2580	1	1	S11	Stairs	Stairwell next to Classroom 106	W4	Cracking paint	10	No	None		None		
188	2580	1	1	S11	Stairs	Stairwell next to Classroom 106	Ceiling	Severe peeling paint	30	No	None		None		
189	2580	1	1	S11	Stairs	Stairwell next to Classroom 104	W1	Cracking paint	30	No	None		None		
190	2580	1	1	S11	Stairs	Stairwell next to Classroom 104	W2	Cracking paint	5	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
191	2580	1	1	S11	Stairs	Stairwell next to Classroom 104	W3	Cracking & peeling paint	30	No	None		None		
192	2580	1	1	S16	Stairs	Stairwell next to Classroom 104	W4	Peeling paint on door	10	No	None		None		
193	2580	1	1	S16	Stairs	Stairwell next to Classroom 104	Ceiling	Peeling & Flaking paint	20	No	None		None		
194	2580	1	1	S16	Stairs	Stairwell next to Classroom 104	Floor	Baseboard	20	No	None		None		
195	2580	1	1	S16	Stairs	Fire Tower by Classroom 103	W3	Peeling & Flaking paint	10	No	None		None		
196	2580	1	1	S18	Stairs	Fire Tower by Classroom 103	Ceiling	Severe peeling paint	100	No	None		None		
197	2580	1	1	S18	Stairs	Fire Tower by Classroom 103	Floor	Debris	50	No	None		None		
198	2580	1	1	S18	Stairs	Fire Tower by Classroom 103	W3	Peeling paint on pipe and window sill	20	No	None		None		
199	2580	1	1	S18A	Stairs	Fire Tower by Classroom 103	Ceiling	Severe peeling paint	20	No	None		None		
200	2580	1	1	S18A	Storage	Custodial Closet outside Classroom 106	W1	Hole in plaster wall	5	No	None		None	Yes	
201	2580	1	1	S18A	Storage	Custodial Closet outside Classroom 106	W2	Severe peeling paint & Damaged plaster	70	No	None		None	Yes	
202	2580	1	1	S18A	Storage	Custodial Closet outside Classroom 106	W3	Severe peeling paint	70	No	None		None		
203	2580	1	1	120A	Storage	Custodial Closet outside Classroom 106	W4	Severe peeling paint	70	No	None		None		
204	2580	1	1	120A	Storage	Custodial Closet outside Classroom 106	Ceiling	Severe peeling paint & Damaged plaster	20	No	None		None	Yes	
205	2580	1	1	120A	Storage	Custodial Closet outside Classroom 104	W1	Peeling paint	10	No	None		None		
206	2580	1	1	120A	Storage	Custodial Closet outside Classroom 104	W3	Peeling paint	25	No	None		None		
207	2580	1	1	121A	Storage	Head Start Closet outside Girl's Restroom	W1	No Access		No	None		None		
208	2580	1	1	121A	Storage	Head Start Closet outside Girl's Restroom	W2	No Access		No	None		None		
209	2580	1	1	121A	Storage	Head Start Closet outside Girl's Restroom	W3	No Access		No	None		None		
210	2580	1	1	104R	Storage	Head Start Closet outside Girl's Restroom	W4	No Access		No	None		None		
211	2580	1	1	104R	Storage	Head Start Closet outside Girl's Restroom	Ceiling	No Access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
212	2580	1	1	104R	Storage	Head Start Closet outside Girl's Restroom	Floor	No Access		No	None		None		
213	2580	1	1	104R	Primary	Classroom 201	W1	Peeling & Flaking paint	70	No	None		None		
214	2580	1	1	104R	Primary	Classroom 201	W2	Severe peeling paint & Efflorescence	150	No	None		None	Yes	
215	2580	1	1	104R	Primary	Classroom 201	W3	Peeling, Cracking, Spalling paint & Efflorescence	80	No	None		None	Yes	
216	2580	1	2	201	Primary	Classroom 201	W4	Peeling, Cracking, Spalling paint & Efflorescence	80	No	None		None	Yes	
217	2580	1	2	201	Storage	Classroom 201 Storage Closet	W1	No Access		No	None		None		
218	2580	1	2	201	Storage	Classroom 201 Storage Closet	W2	No Access		No	None		None		
219	2580	1	2	201	Storage	Classroom 201 Storage Closet	W3	No Access		No	None		None		
220	2580	1	2	201A	Storage	Classroom 201 Storage Closet	W4	No Access (severe peeling paint could be seen through the door)	40	No	None		None		
221	2580	1	2	201A	Storage	Classroom 201 Storage Closet	Ceiling	No Access		No	None		None		
222	2580	1	2	201A	Storage	Classroom 201 Storage Closet	Floor	No Access		No	None		None		
223	2580	1	2	201A	Primary	Classroom 202	W1	Cracking paint and some spalling	5	No	None		None		
224	2580	1	2	201A	Primary	Classroom 202	W2	Cracking paint and some spalling, Damaged plaster at door	15	No	None		None	Yes	
225	2580	1	2	201A	Primary	Classroom 202	W3	Peeling paint & Severely damaged plaster	50	No	None		None	Yes	
226	2580	1	2	202	Primary	Classroom 202	W4	Cracking paint	5	No	None		None		
227	2580	1	2	202	Storage	Classroom 202 Closet	W1	No Access		No	None		None		
228	2580	1	2	202	Storage	Classroom 202 Closet	W2	No Access		No	None		None		
229	2580	1	2	202	Storage	Classroom 202 Closet	W3	No Access		No	None		None		
230	2580	1	2	202A	Storage	Classroom 202 Closet	W4	No Access		No	None		None		
231	2580	1	2	202A	Storage	Classroom 202 Closet	Ceiling	No Access		No	None		None		
232	2580	1	2	202A	Storage	Classroom 202 Closet	Floor	No Access		No	None		None		
233	2580	1	2	202A	Primary	Classroom 203	W2	Peeling paint at edges of wallboard	5	No	None		None		
234	2580	1	2	202A	Primary	Classroom 203	W3	Peeling & Cracking paint, Damaged plaster	25	No	None		None	Yes	
235	2580	1	2	203A	Storage	Classroom 203 Storage Closet	W1	No Access		No	None		None		
236	2580	1	2	203A	Storage	Classroom 203 Storage Closet	W2	No Access		No	None		None		
237	2580	1	2	203A	Storage	Classroom 203 Storage Closet	W3	No Access		No	None		None		
238	2580	1	2	203B	Storage	Classroom 203 Storage Closet	W4	No Access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
239	2580	1	2	203B	Storage	Classroom 203 Storage Closet	Ceiling	No Access		No	None		None		
240	2580	1	2	203B	Storage	Classroom 203 Storage Closet	Floor	No Access		No	None		None		
241	2580	1	2	203B	Primary	Classroom 204	W1	Cracking & Chipping paint	40	No	None		None		
242	2580	1	2	203B	Primary	Classroom 204	W2	Cracking Paint, Spalling at closet	60	No	None		None		
243	2580	1	2	203B	Primary	Classroom 204	W3	Peeling paint & Damaged plaster	30	No	None		None	Yes	
244	2580	1	2	204	Primary	Classroom 204	W4	Chipping paint at some spots	5	No	None		None		
245	2580	1	2	204	Storage	Classroom 204 Storage Closet	W3	Damaged plaster, Efflorescence, Peeling paint at windows & columns	80	No	None		None	Yes	
246	2580	1	2	204A	Storage	Classroom 204 Storage Closet	W4	Cracking paint	20	No	None		None		
247	2580	1	2	204A	Primary	Classroom 205	W1	Cracking paint & Damaged plaster	50	No	None		None	Yes	
248	2580	1	2	204A	Primary	Classroom 205	W2	Minor peeling paint	5	No	None		None		
249	2580	1	2	204A	Primary	Classroom 205	W3	Peeling & Cracking paint, Efflorescence at columns	60	No	None		None	Yes	
250	2580	1	2	205	Primary	Classroom 205	W4	Cracking paint	40	No	None		None		
251	2580	1	2	205	Storage	Classroom 205 Closet	W1	No Access		No	None		None		
252	2580	1	2	205	Storage	Classroom 205 Closet	W2	No Access		No	None		None		
253	2580	1	2	205	Storage	Classroom 205 Closet	W3	No Access		No	None		None		
254	2580	1	2	205A	Storage	Classroom 205 Closet	W4	No Access		No	None		None		
255	2580	1	2	205A	Storage	Classroom 205 Closet	Ceiling	No Access		No	None		None		
256	2580	1	2	205A	Storage	Classroom 205 Closet	Floor	No Access		No	None		None		
257	2580	1	2	205A	IMC (Library)	Library	W1	Flaking paint at one spot	1	No	None		None		
258	2580	1	2	205A	IMC (Library)	Library	W3	Peeling paint at window sill, behind radiators, at left corner column, debris on window sill	85	No	None		None		
259	2580	1	2	207	Storage	Library Office	W1	No Access		No	None		None		
260	2580	1	2	207	Storage	Library Office	W2	No Access		No	None		None		
261	2580	1	2	207	Storage	Library Office	W3	No Access		No	None		None		
262	2580	1	2	207A	Storage	Library Office	W4	No Access		No	None		None		
263	2580	1	2	207A	Storage	Library Office	Ceiling	No Access		No	None		None		
264	2580	1	2	207A	Storage	Library Office	Floor	No Access		No	None		None		
265	2580	1	2	207B	Primary	Classroom 208	W1	Cracking paint	35	No	None		None		
266	2580	1	2	207B	Primary	Classroom 208	W2	Peeling & Cracking paint, hole in plaster	55	No	None		None	Yes	
267	2580	1	2	207B	Primary	Classroom 208	W3	Peeling paint on wall including column	35	No	None		None		
268	2580	1	2	208	Primary	Classroom 208	W4	Peeling & Cracking paint below blackboard	10	No	None		None		
269	2580	1	2	208	Storage	Classroom 208 Closet	W1	Minor Flaking paint	3	No	None		None		
270	2580	1	2	208	Storage	Classroom 208 Closet	W2	Severe peeling paint & debris at column	20	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
271	2580	1	2	208	Storage	Classroom 208 Closet	W3	Peeling paint & Efflorescence at radiators	40	No	None		None		
272	2580	1	2	208A	Storage	Classroom 208 Closet	Floor	Debris	3	No	None		None		
273	2580	1	2	208A	Primary	Classroom 209	W1	Flaking paint - mostly below the blackboard	10	No	None		None		
274	2580	1	2	208A	Primary	Classroom 209	W2	Flaking paint at spots	2	No	None		None		
275	2580	1	2	208A	Primary	Classroom 209	W3	Peeling paint behind radiators, debris at far right corner window sill	15	No	None		None		
276	2580	1	2	209	Primary	Classroom 209	W4	Flaking paint below blackboard	10	No	None		None		
277	2580	1	2	209	Storage	Classroom 209 Closet	W1	Flaking paint	3	No	None		None		
278	2580	1	2	209	Storage	Classroom 209 Closet	W3	Cracking paint	1	No	None		None		
279	2580	1	2	209A	Storage	Classroom 209 Closet	W4	Severe peeling paint on wall including columns	20	No	None		None		
280	2580	1	2	209A	Primary	Classroom 210	W1	Cracking & Chipping paint		No	None		None		
281	2580	1	2	209A	Primary	Classroom 210	W2	Severe peeling paint, Cracking paint on wall and columns. Holes in plaster	80	No	None		None	Yes	
282	2580	1	2	209A	Primary	Classroom 210	W3	Peeling, Cracking, Peeling paint	30	No	None		None		
283	2580	1	2	210	Primary	Classroom 210	W4	Cracking & Flaking paint	5	No	None		None		
284	2580	1	2	210A	Storage	Storage ESOL Department	W2	Flaking paint on wall and column	10	No	None		None		
285	2580	1	2	210B	Storage	Storage ESOL Department	W4	Cracking paint	1	No	None		None		
286	2580	1	2	210B	Primary	Classroom 211	W1	Cracking paint	30	No	None		None		
287	2580	1	2	210B	Primary	Classroom 211	W2	Cracking paint	35	No	None		None		
288	2580	1	2	210B	Primary	Classroom 211	W3	Cracking paint, Damaged plaster behind radiators, Spot debris on window sill	53	No	None		None		
289	2580	1	2	211	Primary	Classroom 211	W4	Cracking paint	30	No	None		None		
290	2580	1	2	211	Primary	Classroom 211	Ceiling	Above ceiling - Severe peeling paint visible through missing tile	8	No	None		None		
291	2580	1	2	211	Storage	Classroom 211 Closet	W1	Cracking paint	20	No	None		None		
292	2580	1	2	211	Storage	Classroom 211 Closet	W2	Cracking & Chipping paint	15	No	None		None		
293	2580	1	2	211	Storage	Classroom 211 Closet	W3	Cracking, flaking, and peeling paint	50	No	None		None		
294	2580	1	2	211A	Storage	Classroom 211 Closet	W4	Cracking and peeling on wall & pipe	20	No	None		None		
295	2580	1	2	211A	Primary	Classroom 212	W1	Cracking paint	30	No	None		None		
296	2580	1	2	211A	Primary	Classroom 212	W2	Cracking paint below blackboard	50	No	None		None		
297	2580	1	2	211A	Primary	Classroom 212	W3	Damaged plaster at and behind radiators	40	No	None		None	Yes	
298	2580	1	2	212	Primary	Classroom 212	W4	Cracking paint	30	No	None		None		
299	2580	1	2	212	Storage	Classroom 212 Closet	W1	No Access		No	None		None		
300	2580	1	2	212	Storage	Classroom 212 Closet	W2	No Access		No	None		None		
301	2580	1	2	212	Storage	Classroom 212 Closet	W3	No Access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
302	2580	1	2	212A	Storage	Classroom 212 Closet	W4	No Access		No	None		None		
303	2580	1	2	212A	Storage	Classroom 212 Closet	Ceiling	No Access		No	None		None		
304	2580	1	2	212A	Storage	Classroom 212 Closet	Floor	No Access		No	None		None		
305	2580	1	2	212A	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Severe peeling paint	50	No	None		None		
306	2580	1	2	212A	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Severely damaged plaster and Efflorescence	120	No	None		None	Yes	
307	2580	1	2	212A	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Severe peeling paint & Efflorescence	30	No	None		None	Yes	
308	2580	1	2	220	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Peeling paint	30	No	None		None		
309	2580	1	2	220	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Severely damaged plaster and Efflorescence	100	No	None		None	Yes	
310	2580	1	2	220	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Debris top of urinals	50	No	None		None		
311	2580	1	2	220A	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Efflorescence at window	20	No	None		None		
312	2580	1	2	221	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Cracking paint & Efflorescence	30	No	None		None		
313	2580	1	2	221	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Damaged plaster & Efflorescence	20	No	None		None		
314	2580	1	2	221A	Student Restrooms - Female (4-12)	Custodial Closet outside Girl's Restroom	Ceiling	Peeling paint	20	No	None		None		
315	2580	1	2	221A	Teacher Lounge/Dining	Women's Restroom Lounge	W2	Efflorescence, Peeling paint at window	20	No	None		None		
316	2580	1	2	221A	Teacher Lounge/Dining	Women's Restroom Lounge	W3	Efflorescence, Peeling paint at window	10	No	None		None		
317	2580	1	2	222	Teacher Lounge/Dining	Women's Restroom Lounge	W4	Flaking paint	5	No	None		None		
318	2580	1	2	222	Teacher Lounge/Dining	Women's Restroom	W2	Efflorescence	10	No	None		None		
319	2580	1	2	222	Teacher Lounge/Dining	Women's Restroom	W3	Spalling		No	None		None		
320	2580	1	2	222A	Teacher Lounge/Dining	Women's Restroom	Ceiling	Efflorescence		No	None		None		
321	2580	1	2	H26	Circulation (Hallway)	Hallway from Classrooms 208 to 211	Floor	Baseboard	10	No	None		None		
322	2580	1	2	H26	Circulation (Hallway)	Hallway in Front of Library	W2	Damaged plaster	25	No	None		None	Yes	

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
323	2580	1	2	H26	Circulation (Hallway)	Hallway in Front of Library	W3	-		No	None		None		
324	2580	1	2	H27	Circulation (Hallway)	Hallway in Front of Library	W4	Damaged plaster	25	No	None		None	Yes	
325	2580	1	2	H27	Circulation (Hallway)	Hallway in Front of Library	Floor	Peeling paint at baseboard	50	No	None		None		
326	2580	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 201 to 204	W1	-		No	None		None		
327	2580	1	2	H27	Circulation (Hallway)	Hallway from Classrooms 201 to 204	W3	-		No	None		None		
328	2580	1	2	H28	Circulation (Hallway)	Hallway from Classrooms 201 to 204	Floor	Peeling at baseboard	100	No	None		None		
329	2580	1	2	H28	Stairs	Stairwell at Classroom 208	W1	-		No	None		None		
330	2580	1	2	H28	Stairs	Stairwell at Classroom 208	W2	Damaged plaster, peeling paint on 2nd floor and middle landing	10	No	None		None		
331	2580	1	2	S21	Stairs	Stairwell at Classroom 208	W4	Damaged plaster at middle landing, Peeling paint on 2nd floor	15	No	None		None		
332	2580	1	2	S21	Stairs	Stairwell at Classroom 208	Ceiling	Under stairs & middle landing	50	No	None		None		
333	2580	1	2	S21	Stairs	Stairwell at Classroom 208	Floor	Baseboard	30	No	None		None		
334	2580	1	2	S21	Stairs	Stairwell at Classroom 204	W1	-		No	None		None		
335	2580	1	2	S21	Stairs	Stairwell at Classroom 204	W2	Severe peeling paint	10	No	None		None		
336	2580	1	2	S21	Stairs	Stairwell at Classroom 204	W3	-		No	None		None		
337	2580	1	2	S26	Stairs	Stairwell at Classroom 204	W4	Peeling paint	5	No	None		None		
338	2580	1	2	S26	Stairs	Stairwell at Classroom 204	Ceiling	Severe peeling paint, Middle landing	35	No	None		None		
339	2580	1	2	S28	Stairs	Fire Tower near Classroom 203	Floor	Debris	30	No	None		None		
340	2580	1	2	S28	Stairs	Fire Tower walkway near Classroom 203	W3	Peeling paint at pipe	12	No	None		None		
341	2580	1	2	S28	Stairs	Fire Tower near Classroom 203	Ceiling	Peeling paint	100	No	None		None		
342	2580	1	2	S28A	Stairs	Fire Tower walkway near Classroom 203	Ceiling	Severe peeling paint, Damaged plaster	100	No	None		None	Yes	
343	2580	1	2	S28A	Primary	Classroom 301	W1	Peeling paint	20	No	None		None		
344	2580	1	2	S28A	Primary	Classroom 301	W2	Peeling paint	30	No	None		None		
345	2580	1	2	S28A	Primary	Classroom 301	W3	Cracking paint	4	No	None		None		
346	2580	1	3	301	Primary	Classroom 301	W4	Cracking & Chipping paint	30	No	None		None		
347	2580	1	3	301	Storage	Classroom 301 Closet	W1	No Access		No	None		None		
348	2580	1	3	301	Storage	Classroom 301 Closet	W2	No Access		No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
349	2580	1	3	301	Storage	Classroom 301 Closet	W3	No Access		No	None		None		
350	2580	1	3	301A	Storage	Classroom 301 Closet	W4	No Access (Severe peeling paint on wall and pipe by window - seen through the door)	40	No	None		None		
351	2580	1	3	301A	Storage	Classroom 301 Closet	Ceiling	No Access		No	None		None		
352	2580	1	3	301A	Storage	Classroom 301 Closet	Floor	No Access		No	None		None		
353	2580	1	3	301A	Primary	Classroom 302	W1	Severe peeling paint & Efflorescence	100	No	None		None		
354	2580	1	3	301A	Primary	Classroom 302	W2	Peeling & Cracking paint	10	No	None		None		
355	2580	1	3	301A	Primary	Classroom 302	W3	Cracking paint	15	No	None		None		
356	2580	1	3	302	Primary	Classroom 302	W4	Cracking paint	30	No	None		None		
357	2580	1	3	302	Primary	Classroom 302	Ceiling	Above ceiling - Severe peeling paint & damaged plaster visible through missing tile	20	No	None		None		
358	2580	1	3	302	Primary	Classroom 302	Floor	Debris	10	No	None		None		
359	2580	1	3	302	Storage	Classroom 302 Closet	W1	No Access		No	None		None		
360	2580	1	3	302	Storage	Classroom 302 Closet	W2	No Access		No	None		None		
361	2580	1	3	302	Storage	Classroom 302 Closet	W3	No Access		No	None		None		
362	2580	1	3	302A	Storage	Classroom 302 Closet	W4	No Access		No	None		None		
363	2580	1	3	302A	Storage	Classroom 302 Closet	Ceiling	No Access		No	None		None		
364	2580	1	3	302A	Storage	Classroom 302 Closet	Floor	No Access		No	None		None		
365	2580	1	3	302A	Primary	Classroom 303	W1	Cracking & Chipping paint	20	No	None		None		
366	2580	1	3	302A	Primary	Classroom 303	W2	Cracking & Chipping paint	20	No	None		None		
367	2580	1	3	302A	Primary	Classroom 303	W3	Severe peeling paint & damaged plaster	30	No	None		None	Yes	
368	2580	1	3	303	Primary	Classroom 303	W4	Cracking & peeling paint	40	No	None		None		
369	2580	1	3	303	Storage	Classroom 303 Closet	W1	Cracking paint	5	No	None		None		
370	2580	1	3	303	Storage	Classroom 303 Closet	W3	Exposed damaged plaster at coat hanger	10	No	None		None		
371	2580	1	3	303A	Storage	Classroom 303 Closet	W1	No Access		No	None		None		
372	2580	1	3	303A	Storage	Classroom 303 Closet	W2	No Access		No	None		None		
373	2580	1	3	303A	Storage	Classroom 303 Closet	W3	No Access		No	None		None		
374	2580	1	3	303B	Storage	Classroom 303 Closet	W4	No Access		No	None		None		
375	2580	1	3	303B	Storage	Classroom 303 Closet	Ceiling	No Access		No	None		None		
376	2580	1	3	303B	Storage	Classroom 303 Closet	Floor	No Access		No	None		None		
377	2580	1	3	303B	Primary	Classroom 304	W1	Cracking & Flaking paint	125	No	None		None		
378	2580	1	3	303B	Primary	Classroom 304	W2	Cracking & Flaking paint	70	No	None		None		
379	2580	1	3	303B	Primary	Classroom 304	W3	Cracking paint at columns	40	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
380	2580	1	3	304	Primary	Classroom 304	W4	Cracking & Flaking paint	60	No	None		None		
381	2580	1	3	304	Storage	Classroom 304 Closet	W1	No Access		No	None		None		
382	2580	1	3	304	Storage	Classroom 304 Closet	W2	No Access		No	None		None		
383	2580	1	3	304	Storage	Classroom 304 Closet	W3	No Access		No	None		None		
384	2580	1	3	304A	Storage	Classroom 304 Closet	W4	No Access		No	None		None		
385	2580	1	3	304A	Storage	Classroom 304 Closet	Ceiling	No Access		No	None		None		
386	2580	1	3	304A	Storage	Classroom 304 Closet	Floor	No Access		No	None		None		
387	2580	1	3	304A	Primary	Classroom 305	W1	Cracking paint	20	No	None		None		
388	2580	1	3	304A	Primary	Classroom 305	W2	-		No	None		None		
389	2580	1	3	304A	Primary	Classroom 305	W3	Cracking paint, damaged plaster at column	15	No	None		None		
390	2580	1	3	305	Primary	Classroom 305	W4	Cracking & Flaking paint	20	No	None		None		
391	2580	1	3	305	Storage	Classroom 305 Closet	W2	Flaking paint at spots	5	No	None		None		
392	2580	1	3	305A	Primary	Classroom 306	W1	Cracking paint	3	No	None		None		
393	2580	1	3	305A	Primary	Classroom 306	W2	Cracking paint	3	No	None		None		
394	2580	1	3	306	Primary	Classroom 306	W4	-		No	None		None		
395	2580	1	3	306A	Storage	Classroom 306 Closet	W4	Cracking paint	10	No	None		None		
396	2580	1	3	306A	Storage	Classroom 306 Closet	W2	Cracking paint at column	10	No	None		None		
397	2580	1	3	306B	Primary	Classroom 307	W1	Cracking paint	30	No	None		None		
398	2580	1	3	306B	Primary	Classroom 307	W2	Cracking paint	50	No	None		None		
399	2580	1	3	306B	Primary	Classroom 307	W3	Cracking paint at columns	40	No	None		None		
400	2580	1	3	307	Primary	Classroom 307	W4	Cracking paint	30	No	None		None		
401	2580	1	3	307	Storage	Classroom 307 Closet	W1	Peeling paint	5	No	None		None		
402	2580	1	3	307	Storage	Classroom 307 Closet	W2	Peeling paint	20	No	None		None		
403	2580	1	3	307A	Storage	Classroom 307 Closet	W4	Peeling paint	5	No	None		None		
404	2580	1	3	307A	Primary	Classroom 308	W1	Cracking & Chipping paint	10	No	None		None		
405	2580	1	3	307A	Primary	Classroom 308	W2	Cracking & peeling paint	20	No	None		None		
406	2580	1	3	307A	Primary	Classroom 308	W3	Cracking, flaking, and peeling paint	30	No	None		None		
407	2580	1	3	308	Primary	Classroom 308	W4	Cracking paint	20	No	None		None		
408	2580	1	3	308	Storage	Classroom 308 Closet	W1	Cracking paint	20	No	None		None		
409	2580	1	3	308	Storage	Classroom 308 Closet	W2	Severe peeling paint & Cracking paint	40	No	None		None		
410	2580	1	3	308	Storage	Classroom 308 Closet	W3	Severe peeling paint, Efflorescence at window	50	No	None		None	Yes	
411	2580	1	3	308A	Storage	Classroom 308 Closet	Ceiling	Tiles are badly damaged		No	None		None		
412	2580	1	3	308A	Primary	Classroom 309	W1	Flaking & peeling paint	15	No	None		None		
413	2580	1	3	308A	Primary	Classroom 309	W2	Cracking paint	25	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
414	2580	1	3	308A	Primary	Classroom 309	W3	Peeling paint behind radiators, and at columns	30	No	None		None		
415	2580	1	3	309	Primary	Classroom 309	W4	Cracking & peeling paint	30	No	None		None		
416	2580	1	3	309	Storage	Classroom 309 Closet	W1	No Access		No	None		None		
417	2580	1	3	309	Storage	Classroom 309 Closet	W2	No Access		No	None		None		
418	2580	1	3	309	Storage	Classroom 309 Closet	W3	No Access		No	None		None		
419	2580	1	3	309A	Storage	Classroom 309 Closet	W4	No Access (Severe peeling paint on wall and pipe by window - seen through the door)	30	No	None		None		
420	2580	1	3	309A	Storage	Classroom 309 Closet	Ceiling	No Access		No	None		None		
421	2580	1	3	309A	Storage	Classroom 309 Closet	Floor	No Access		No	None		None		
422	2580	1	3	309A	Primary	Classroom 310	W1	Cracking & peeling paint	70	No	None		None		
423	2580	1	3	309A	Primary	Classroom 310	W2	Cracking & peeling paint	70	No	None		None		
424	2580	1	3	309A	Primary	Classroom 310	W3	Cracking & peeling paint	80	No	None		None		
425	2580	1	3	310	Primary	Classroom 310	W4	Cracking & peeling paint including plenums	100	No	None		None		
426	2580	1	3	310	Primary	Classroom 310	Ceiling	Peeling paint at stage ceiling	25	No	None		None		
427	2580	1	3	310	Storage	Classroom 310 Closet	W1	No Access		No	None		None		
428	2580	1	3	310	Storage	Classroom 310 Closet	W2	No Access (Efflorescence, Damaged plaster, Flaking paint - seen through the door)	60	No	None		None	Yes	
429	2580	1	3	310	Storage	Classroom 310 Closet	W3	No Access							
430	2580	1	3	310A	Storage	Classroom 310 Closet	W4	No Access							
431	2580	1	3	310A	Storage	Classroom 310 Closet	Ceiling	No Access							
432	2580	1	3	310A	Storage	Classroom 310 Closet	Floor	No Access							
433	2580	1	3	310A	Storage	Classroom 310 Closet	W1	No Access							
434	2580	1	3	310A	Storage	Classroom 310 Closet	W2	No Access							
435	2580	1	3	310A	Storage	Classroom 310 Closet	W3	No Access (Cracking paint observed through door)	15						
436	2580	1	3	310B	Storage	Classroom 310 Closet	W4	No Access (Damaged plaster observed through door)	10					Yes	
437	2580	1	3	310B	Storage	Classroom 310 Closet	Ceiling	No Access (Damaged plaster observed through door)	15					Yes	
438	2580	1	3	310B	Storage	Classroom 310 Closet	Floor	No Access							
439	2580	1	3	310B	Primary	Classroom 311	W1	Cracking paint	40	No	None		None		
440	2580	1	3	310B	Primary	Classroom 311	W2	Cracking & peeling paint	30	No	None		None		
441	2580	1	3	310B	Primary	Classroom 311	W3	Cracking paint at columns	30	No	None		None		
442	2580	1	3	311	Primary	Classroom 311	W4	Cracking & Spalling paint	30	No	None		None		
443	2580	1	3	311	Storage	Classroom 311 Closet	W1	Cracking & Chipping paint	20	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
444	2580	1	3	311	Storage	Classroom 311 Closet	W2	Cracking & Chipping paint	30	No	None		None		
445	2580	1	3	311	Storage	Classroom 311 Closet	W3	Efflorescence, Peeling & flaking paint	50	No	None		None		
446	2580	1	3	311A	Storage	Classroom 311 Closet	W4	Cracking paint	10	No	None		None		
447	2580	1	3	311A	Primary	Classroom 312	W1	Damaged plaster, Cracking & flaking paint	30	No	None		None	Yes	
448	2580	1	3	311A	Primary	Classroom 312	W2	Cracking paint	30	No	None		None		
449	2580	1	3	311A	Primary	Classroom 312	W3	Cracking paint at columns	45	No	None		None		
450	2580	1	3	312	Primary	Classroom 312	W4	Cracking paint	50	No	None		None		
451	2580	1	3	312	Storage	Classroom 312 Closet	W1	No Access							
452	2580	1	3	312	Storage	Classroom 312 Closet	W2	No Access (Flaking paint observed through door)	20						
453	2580	1	3	312	Storage	Classroom 312 Closet	W3	No Access (Flaking paint observed through door)	15						
454	2580	1	3	312A	Storage	Classroom 312 Closet	W4	No Access							
455	2580	1	3	312A	Storage	Classroom 312 Closet	Ceiling	No Access							
456	2580	1	3	312A	Storage	Classroom 312 Closet	Floor	No Access							
457	2580	1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Severely peeling paint	50	No	None		None		
458	2580	1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Severely peeling paint	70	No	None		None		
459	2580	1	3	312A	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Severely peeling paint	50	No	None		None		
460	2580	1	3	320	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Severely peeling paint	80	No	None		None		
461	2580	1	3	320	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Severely peeling paint	60	No	None		None		
462	2580	1	3	320A	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Peeling paint	10	No	None		None		
463	2580	1	3	320A	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Peeling paint	10	No	None		None		
464	2580	1	3	320A	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Peeling paint	10	No	None		None		
465	2580	1	3	321	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Peeling paint	10	No	None		None		
466	2580	1	3	321	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Peeling paint	40	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
467	2580	1	3	321	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Peeling paint	20	No	None		None		
468	2580	1	3	321A	Restrooms, Staff - Male	Men's Restroom Lounge	W3	Flaking paint behind pipe	6	No	None		None		
469	2580	1	3	322	Restrooms, Staff - Female	Men's Restroom	W1	Cracking paint	5	No	None		None		
470	2580	1	3	322	Restrooms, Staff - Female	Men's Restroom	W2	Cracking paint	5	No	None		None		
471	2580	1	3	322	Restrooms, Staff - Female	Men's Restroom	W3	Cracking paint	5	No	None		None		
472	2580	1	3	322A	Restrooms, Staff - Female	Men's Restroom	W4	Cracking paint	5	No	None		None		
473	2580	1	3	322A	Circulation (Hallway)	Hallway from Classrooms 305 to 307	W1	Peeling & flaking paint	50	No	None		None		
474	2580	1	3	322A	Circulation (Hallway)	Hallway from Classrooms 305 to 307	W2	-		No	None		None		
475	2580	1	3	322A	Circulation (Hallway)	Hallway from Classrooms 305 to 307	W3	Cracking paint on wall including behind radiators	100	No	None		None		
476	2580	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 305 to 307	W4	-		No	None		None		
477	2580	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 305 to 307	Floor	Baseboard	10	No	None		None		
478	2580	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 304	W1	Efflorescence & damaged plaster at the arch by fire tower	5	No	None		None	Yes	
479	2580	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 304	W2	Severe peeling paint by stairwell	20	No	None		None		
480	2580	1	3	H310	Circulation (Hallway)	Hallway from Classrooms 301 to 304	W3	-	10	No	None		None		
481	2580	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 301 to 304	W4	Damaged plaster at room 303	40	No	None		None		
482	2580	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 301 to 304	Floor	Baseboard	30	No	None		None		
483	2580	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 311	W1	Flaking paint	5	No	None		None		
484	2580	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 311	W2	Severe peeling paint & flaking paint by 311	20	No	None		None		
485	2580	1	3	H311	Circulation (Hallway)	Hallway from Classrooms 308 to 311	W3	Damaged plaster at room 312, Cracking paint	10	No	None		None	Yes	

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
486	2580	1	3	H39	Circulation (Hallway)	Hallway from Classrooms 308 to 311	W4	Cracking paint	40	No	None		None		
487	2580	1	3	H39	Circulation (Hallway)	Hallway from Classrooms 308 to 311	Floor	Baseboard	30	No	None		None		
488	2580	1	3	H39	Stairs	Stairwell next to Classroom 308	W1	Peeling & flaking paint by windows and radiators	30	No	None		None		
489	2580	1	3	H39	Stairs	Stairwell next to Classroom 308	W2	Cracking paint	10	No	None		None		
490	2580	1	3	H39	Stairs	Stairwell next to Classroom 308	W3	Cracking paint	10	No	None		None		
491	2580	1	3	S31	Stairs	Stairwell next to Classroom 308	W4	Cracking paint	30	No	None		None		
492	2580	1	3	S31	Stairs	Stairwell next to Classroom 308	Ceiling	Peeling paint	30	No	None		None		
493	2580	1	3	S31	Stairs	Stairwell next to Classroom 308	Floor	Baseboard	20	No	None		None		
494	2580	1	3	S31	Stairs	Stairwell next to Classroom 304	W1	-		No	None		None		
495	2580	1	3	S31	Stairs	Stairwell next to Classroom 304	W2	Peeling paint	10	No	None		None		
496	2580	1	3	S31	Stairs	Stairwell next to Classroom 304	W3	-		No	None		None		
497	2580	1	3	S36	Stairs	Stairwell next to Classroom 304	W4	Peeling paint	20	No	None		None		
498	2580	1	3	S36	Stairs	Stairwell next to Classroom 304	Ceiling	Peeling paint	15	No	None		None		
499	2580	1	3	S36	Stairs	Fire Tower next to Classroom 303	W1	Peeling paint	10	No	None		None		
500	2580	1	3	S36	Stairs	Fire Tower next to Classroom 303	W2	Peeling paint, & damaged plaster at window	20	No	None		None		
501	2580	1	3	S36	Stairs	Fire Tower next to Classroom 303	W3	Peeling paint	20	No	None		None		
502	2580	1	3	S38	Stairs	Fire Tower next to Classroom 303	W4	Peeling paint	10	No	None		None		
503	2580	1	3	S38	Stairs	Fire Tower next to Classroom 303	Ceiling	Severe peeling paint	15	No	None		None		
504	2580	1	3	S38	Stairs	Fire Tower next to Classroom 303	Floor	Debris	3	No	Floor	3	None		
505	2580	1	3	S38	Stairs	Fire Tower walkway next to Classroom 303	W3	Damaged plaster & peeling paint	30	No	None		None		
506	2580	1	3	S38A	Stairs	Fire Tower walkway next to Classroom 303	Ceiling	Peeling paint	10	No	None		None		
507	2580	1	3	S38A	Gymnasium - Intermediate Middle	Gymnasium	W1	Cracking & Peeling paint	50	No	None		None		
508	2580	1	3	S38A	Gymnasium - Intermediate Middle	Gymnasium	W2	Cracking & Peeling paint	150	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
509	2580	1	3	S38A	Gymnasium - Intermediate Middle	Gymnasium	W3	Cracking & Peeling paint	50	No	None		None		
510	2580	1	B	1	Gymnasium - Intermediate Middle	Gymnasium	W4	Cracking & Peeling paint	100	No	None		None		
511	2580	1	B	1	Gymnasium - Intermediate Middle	Gymnasium	Ceiling	Severe peeling paint including ductwork & beams	1200	No	None		None		
512	2580	1	B	1	Gymnasium - Intermediate Middle	Gymnasium	Floor	Debris along windows & chair	20	No	Chair	4	None		
513	2580	1	B	1	Administrative Office	Gymnasium Office	W1	Peeling & flaking paint	30	No	None		None		
514	2580	1	B	1	Administrative Office	Gymnasium Office	W2	Efflorescence, Severe Peeling & flaking paint	80	No	None		None	Yes	
515	2580	1	B	1	Administrative Office	Gymnasium Office	W3	Efflorescence, Severe Peeling & flaking paint	100	No	None		None	Yes	
516	2580	1	B	001A	Administrative Office	Gymnasium Office	W4	Peeling & flaking paint	20	No	None		None		
517	2580	1	B	001A	Administrative Office	Gymnasium Office	Ceiling	Severe peeling & flaking paint	120	No	None		None		
518	2580	1	B	001A	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	W1	Cracking paint	5	No	None		None		
519	2580	1	B	001A	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	W2	Cracking paint	5	No	None		None		
520	2580	1	B	001A	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	W3	Cracking paint	5	No	None		None		
521	2580	1	B	001C	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	W4	Cracking paint	5	No	None		None		
522	2580	1	B	001C	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	Ceiling	Severe peeling paint including ductwork	80	No	None		None		
523	2580	1	B	001C	Restrooms, Staff - Male/Female	Gymnasium Office Teacher's Restroom	Floor	Severe peeling paint	30	No	None		None		
524	2580	1	B	001C	Storage	Gymnasium Storage closet at the far along Room 015	W1	Efflorescence & Severe peeling paint	80	No	None		None		
525	2580	1	B	001C	Storage	Gymnasium Storage closet at the far along Room 015	W2	Efflorescence & Severe peeling paint	100	No	None		None		
526	2580	1	B	001C	Storage	Gymnasium Storage closet at the far along Room 015	W3	Efflorescence & Severe peeling paint	120	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
527	2580	1	B	001B	Storage	Gymnasium Storage closet at the far along Room 015	W4	Efflorescence & Severe peeling paint	50	No	None		None		
528	2580	1	B	001B	Storage	Gymnasium Storage closet at the far along Room 015	Ceiling	Severely damaged plaster, Peeling & flaking paint including ductwork	200	No	None		None	Yes	
529	2580	1	B	001B	Storage	Gymnasium Storage closet at the far along Room 015	Floor	Debris on electrical components & chair	200	No	Electrical components & chair	45	None		
530	2580	1	B	001B	Storage	Gymnasium Storage Room	W1	Peeling & flaking paint	20	No	None		None		
531	2580	1	B	001B	Storage	Gymnasium Storage Room	W2	Peeling paint, flaking paint including pipes and window frame	80	No	None		None		
532	2580	1	B	001B	Storage	Gymnasium Storage Room	W3	Cracking paint	5	No	None		None		
533	2580	1	B	2	Storage	Gymnasium Storage Room	W4	Peeling & flaking paint by the door	20	No	None		None		
534	2580	1	B	2	Storage	Gymnasium Storage Room	Ceiling	Severe peeling paint, flaking paint including on ductwork	150	No	None		None		
535	2580	1	B	2	Storage	Gymnasium Storage Room	Floor	Debris on floor and maintenance supplies	200	No	Maintenance supplies	100	None		
536	2580	1	B	4	Student Restrooms - Female (4-12)	Girl's Restroom	W1	Severe peeling paint	30	No	None		None		
537	2580	1	B	4	Student Restrooms - Female (4-12)	Girl's Restroom	W2	Severe peeling paint	50	No	None		None		
538	2580	1	B	4	Student Restrooms - Female (4-12)	Girl's Restroom	W3	Severe peeling paint	50	No	None		None		
539	2580	1	B	5	Student Restrooms - Female (4-12)	Girl's Restroom	W4	Severe peeling paint	15	No	None		None		
540	2580	1	B	5	Student Restrooms - Female (4-12)	Girl's Restroom	Ceiling	Severe peeling paint including radiators	400	No	None		None		
541	2580	1	B	5	Student Restrooms - Female (4-12)	Girl's Restroom	Floor	Debris and peeling paint on baseboard	40	No	None		None		
542	2580	1	B	5	Student Restrooms - Male (4-12)	Boy's Restroom	W1	Severe peeling paint	100	No	None		None		
543	2580	1	B	5	Student Restrooms - Male (4-12)	Boy's Restroom	W2	Severe peeling paint	100	No	None		None		
544	2580	1	B	5	Student Restrooms - Male (4-12)	Boy's Restroom	W3	Severe peeling paint	100	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
545	2580	1	B	6	Student Restrooms - Male (4-12)	Boy's Restroom	W4	Severe peeling paint	50	No	None		None		
546	2580	1	B	6	Student Restrooms - Male (4-12)	Boy's Restroom	Ceiling	Severe peeling paint including radiators	600	No	None		None		
547	2580	1	B	6	Student Restrooms - Male (4-12)	Boy's Restroom	Floor	Debris	150	No	None		None		
548	2580	1	B	007B	Storage	Storage Closet in Hallway across Engineer's Office	W1	Peeling paint on pipe	20	No	None		None		
549	2580	1	B	007B	Storage	Storage Closet in Hallway across Engineer's Office	W2	Peeling paint on wall, columns, and pipe	55	No	None		None		
550	2580	1	B	007B	Storage	Storage Closet in Hallway across Engineer's Office	W3	Peeling paint on wall and pipe	30	No	None		None		
551	2580	1	B	8	Storage	Storage Closet in Hallway across Engineer's Office	W4	Peeling paint	5	No	None		None		
552	2580	1	B	8	Storage	Storage Closet in Hallway across Engineer's Office	Floor	Peeling paint	20	No	None		None		
553	2580	1	B	8	Storage	Former Engineer's Office	W1	Cracking paint	20	No	None		None		
554	2580	1	B	8	Storage	Former Engineer's Office	W2	Cracking paint	50	No	None		None		
555	2580	1	B	8	Storage	Former Engineer's Office	W3	Cracking paint	30	No	None		None		
556	2580	1	B	9	Storage	Former Engineer's Office	W4	Cracking paint	50	No	None		None		
557	2580	1	B	9	Storage	Former Engineer's Office	Ceiling	Cracking, peeling, and flaking paint	100	No	None		None		
558	2580	1	B	11	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	W1	Cracking, peeling, and flaking paint	80	No	None		None		
559	2580	1	B	11	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	W2	Cracking, peeling, and flaking paint	30	No	None		None		
560	2580	1	B	11	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	W3	Cracking paint	10	No	None		None		
561	2580	1	B	12	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	W4	Cracking paint	10	No	None		None		
562	2580	1	B	12	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	Ceiling	peeling paint	150	No	None		None		
563	2580	1	B	12	Cafeteria (Dining Area)	Kitchen/Cafeteria with Walk-in Freezer	Floor	peeling paint including baseboard	70	No	None		None		
564	2580	1	B	12	Kitchen	Storage between Lunch Rooms	W1	No Access							

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
565	2580	1	B	12	Kitchen	Storage between Lunch Rooms	W2	No Access							
566	2580	1	B	12	Kitchen	Storage between Lunch Rooms	W3	No Access							
567	2580	1	B	012A	Kitchen	Storage between Lunch Rooms	W4	No Access							
568	2580	1	B	012A	Kitchen	Storage between Lunch Rooms	Ceiling	No Access							
569	2580	1	B	012A	Kitchen	Storage between Lunch Rooms	Floor	No Access							
570	2580	1	B	012A	Circulation (Hallway)	Hallway between Lunch Rooms	W1	Cracking paint	15	No	None		None		
571	2580	1	B	012A	Circulation (Hallway)	Hallway between Lunch Rooms	W2	Cracking paint	20	No	None		None		
572	2580	1	B	012A	Circulation (Hallway)	Hallway between Lunch Rooms	W3	Cracking paint	10	No	None		None		
573	2580	1	B	13	Circulation (Hallway)	Hallway between Lunch Rooms	W4	Cracking paint	15	No	None		None		
574	2580	1	B	13	Circulation (Hallway)	Hallway between Lunch Rooms	Ceiling	Peeling paint	20	No	None		None		
575	2580	1	B	13	Cafeteria (Dining Area)	Cafeteria	W1	Cracking & flaking paint	20	No	None		None		
576	2580	1	B	13	Cafeteria (Dining Area)	Cafeteria	W3	Damaged plaster, Efflorescence, severe peeling paint, and cracking paint	120	No	None		None	Yes	
577	2580	1	B	14	Cafeteria (Dining Area)	Cafeteria	W4	flaking paint underneath the shelf	12	No	None		None		
578	2580	1	B	14	Cafeteria (Dining Area)	Cafeteria	Floor	flaking paint	350	No	None		None		
579	2580	1	B	14	Primary	Art Room	W1	Severe peeling paint near window	10	No	None		None		
580	2580	1	B	14	Primary	Art Room	W2	Peeling paint near middle column	10	No	None		None		
581	2580	1	B	14	Primary	Art Room	W3	Efflorescence & severe peeling paint	15	No	None		None	Yes	
582	2580	1	B	15	Primary	Art Room	W4	Peeling & flaking paint	30	No	None		None		
583	2580	1	B	15	Storage	Art Room Large Storage Closet	W1	Cracking paint, damaged plaster	30	No	None		None	Yes	
584	2580	1	B	15	Storage	Art Room Large Storage Closet	W3	Efflorescence & severe peeling paint	60	No	None		None	Yes	
585	2580	1	B	15A	Storage	Art Room Large Storage Closet	W4	Severe peeling paint	30	No	None		None		
586	2580	1	B	15A	Storage	Art Room Small Storage Closet	W1	Cracking paint	30	No	None		None		
587	2580	1	B	15A	Storage	Art Room Small Storage Closet	W2	Severe peeling paint	50	No	None		None		
588	2580	1	B	15A	Storage	Art Room Small Storage Closet	W3	Severe peeling paint	60	No	None		None		
589	2580	1	B	15B	Storage	Art Room Small Storage Closet	Ceiling	Peeling paint	20	No	None		None		
590	2580	1	B	15B	Circulation (Hallway)	Hallway by the Gym	W1	Severe peeling paint & flaking paint	200	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
591	2580	1	B	15B	Circulation (Hallway)	Hallway by the Gym	W2	Severe peeling paint & flaking paint	100	No	None		None		
592	2580	1	B	15B	Circulation (Hallway)	Hallway by the Gym	W3	Severe peeling paint & flaking paint	200	No	None		None		
593	2580	1	B	H01	Circulation (Hallway)	Hallway by the Gym	W4	Severe peeling paint & flaking paint	100	No	None		None		
594	2580	1	B	H01	Circulation (Hallway)	Hallway by the Gym	Ceiling	Severe peeling paint & flaking paint including ductwork and pipes	400	No	None		None		
595	2580	1	B	H01	Circulation (Hallway)	Hallway by the Gym	Floor	Baseboard	30	No	None		None		
596	2580	1	B	H01	Circulation (Hallway)	Storage area in Hallway by the Gym	W1	Severe peeling paint & flaking paint	30	No	None		None		
597	2580	1	B	H01	Circulation (Hallway)	Storage area in Hallway by the Gym	W2	Severe peeling paint & flaking paint	5	No	None		None		
598	2580	1	B	H01	Circulation (Hallway)	Storage area in Hallway by the Gym	W3	Severe peeling paint & flaking paint	30	No	None		None		
599	2580	1	B	H01A	Circulation (Hallway)	Storage area in Hallway by the Gym	W4	Severe peeling paint & flaking paint	30	No	None		None		
600	2580	1	B	H01A	Circulation (Hallway)	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	W2	Cracking paint	100	No	None		None		
601	2580	1	B	H01A	Circulation (Hallway)	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	W3	Peeling paint on electrical conduit by stairs	6	No	None		None		
602	2580	1	B	H02	Circulation (Hallway)	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	W4	Cracking, peeling, and flaking paint	100	No	None		None		
603	2580	1	B	H02	Circulation (Hallway)	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Ceiling	Peeling & flaking paint	50	No	None		None		
604	2580	1	B	H02	Circulation (Hallway)	Hallway by the Building Engineer's Office and the Boy's and Girl's Restrooms	Floor	Baseboard	20	No	None		None		
605	2580	1	B	H02	Stairs	Stairwell between the Cafeteria and Art Room	W1	Peeling paint above entrance	15	No	None		None		
606	2580	1	B	H02	Stairs	Stairwell between the Cafeteria and Art Room	W2	Cracking & Peeling paint	40	No	None		None		

Kirkbride -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
607	2580	1	B	H02	Stairs	Stairwell between the Cafeteria and Art Room	W3	Cracking paint	15	No	None		None		
608	2580	1	B	S01	Stairs	Stairwell between the Cafeteria and Art Room	W4	Cracking & Peeling paint	30	No	None		None		
609	2580	1	B	S01	Stairs	Stairwell between the Cafeteria and Art Room	Ceiling	Peeling paint at landings	100	No	None		None		
610	2580	1	B	S01	Stairs	Stairwell between the Cafeteria and Art Room	Floor	Baseboard	20	No	None		None		
611	2580	1	B	S01	Stairs	Stairwell between the Boy's and Girl's Restrooms	W3	Damaged plaster, Peeling & flaking paint	80	No	None		None	Yes	
612	2580	1	B	S06	Stairs	Stairwell between the Boy's and Girl's Restrooms	Ceiling	Peeling paint at landings	100	No	None		None		
613	2580	1	B	S06	Stairs	Stairwell between the Boy's and Girl's Restrooms	Floor	Baseboard	20	No	None		None		