

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|---|
| 1 | 5430 | 1 | 3 | 31 | | Art Room 311 | Floor | Chipping | 80 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 2 | 5430 | 1 | 3 | 31 | | Art Room 311 | W1 | Flaking | 30 | N | N | 0 | N | N | Additional Chipping |
| 3 | 5430 | 1 | 3 | 31 | | Art Room 311 | W2 | Flaking | 25 | N | N | 0 | N | N | Additional Chipping; Damage Includes Wall & Radiator |
| 4 | 5430 | 1 | 3 | 31 | | Art Room 311 | W3 | Flaking | 32 | N | N | 0 | N | N | Additional Chipping |
| 5 | 5430 | 1 | 3 | 31 | | Art Room 311 | W4 | Flaking | 80 | N | N | 0 | Y - 30 SF Posters | N | Limited Inspection |
| 6 | 5430 | 1 | 3 | 031AA | | Art Room 311 Closet next to Kiln Room | Ceiling | Flaking | 3 | N | N | 0 | N | N | |
| 7 | 5430 | 1 | 3 | 031AA | | Art Room 311 Closet next to Kiln Room | W1 | Partially Inaccessible | 0 | N | N | 0 | Y - 10 SF Boxes, Contents | N | Limited Inspection |
| 8 | 5430 | 1 | 3 | 031AA | | Art Room 311 Closet next to Kiln Room | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 20 SF Boxes, Contents | N | Limited Inspection |
| 9 | 5430 | 1 | 3 | 031AA | | Art Room 311 Closet next to Kiln Room | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 20 SF Boxes, Contents | N | Limited Inspection |
| 10 | 5430 | 1 | 3 | 031AA | | Art Room 311 Closet next to Kiln Room | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 15 SF Boxes, Contents | N | Limited Inspection |
| 11 | 5430 | 1 | 3 | 21 | | Classroom 301 | Floor | Chipping | 80 | N | N | 0 | 0 | 0 | |
| 12 | 5430 | 1 | 3 | 21 | | Classroom 301 | W1 | Flaking | 26 | N | N | 0 | 0 | 0 | |
| 13 | 5430 | 1 | 3 | 21 | | Classroom 301 | W2 | Flaking | 42 | N | N | 0 | 0 | 0 | |
| 14 | 5430 | 1 | 3 | 21 | | Classroom 301 | W3 | Flaking | 32 | Y | N | 0 | 0 | Y - 5 SF | |
| 15 | 5430 | 1 | 3 | 21 | | Classroom 301 | W4 | Flaking | 16 | N | N | 0 | 0 | 0 | |
| 16 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | Ceiling | Flaking | 10 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 17 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | Floor | Chipping | 8 | N | N | 0 | N | N | Chipping on Baseboard |
| 18 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | W1 | Flaking | 8 | N | N | 0 | Y - 20 SF Boxes, Contents | N | Limited Inspection |
| 19 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 10 SF Boxes, Contents | N | Limited Inspection |
| 20 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | W3 | Flaking | 6 | Y | N | 0 | N | Y - 6 SF | Additional Efflorescence |
| 21 | 5430 | 1 | 3 | 021A | | Classroom 301 Closet | W4 | Flaking | 16 | Y | N | 0 | N | Y - 8 SF | Additional Efflorescence |
| 22 | 5430 | 1 | 3 | 22 | | Classroom 302 | W1 | Flaking | 20 | N | N | 0 | N | N | Additional Chipping; Damage on Wall & Blackboard Trim |
| 23 | 5430 | 1 | 3 | 22 | | Classroom 302 | W2 | Flaking | 20 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 24 | 5430 | 1 | 3 | 22 | | Classroom 302 | W3 | Flaking | 40 | N | N | 0 | Y - 28 SF Cabinets, Posters | N | Limited Inspection |
| 25 | 5430 | 1 | 3 | 22 | | Classroom 302 | W4 | Flaking | 16 | N | N | 0 | Y - 16 SF Posters | N | Limited Inspection |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|----------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|--|
| 26 | 5430 | 1 | 3 | 022B | | Classroom 302 Closet | W1 | Flaking | 4 | N | N | 0 | N | N | Additional Chipping |
| 27 | 5430 | 1 | 3 | 022B | | Classroom 302 Closet | W2 | Flaking | 16 | N | N | 0 | Y - 20 SF Contents | N | Limited Inspection |
| 28 | 5430 | 1 | 3 | 022B | | Classroom 302 Closet | W3 | Flaking | 10 | N | N | 0 | N | N | Additional Chipping |
| 29 | 5430 | 1 | 3 | 022B | | Classroom 302 Closet | W4 | Flaking | 12 | N | N | 0 | Y - 20 SF Contents | N | Limited Inspection |
| 30 | 5430 | 1 | 3 | 23 | | Classroom 303 | W1 | Cracking | 34 | N | N | 0 | N | N | Additional Chipping |
| 31 | 5430 | 1 | 3 | 23 | | Classroom 303 | W2 | Chipping | 20 | N | N | 0 | Y - 40 SF Desks, Posters | N | Limited Inspection |
| 32 | 5430 | 1 | 3 | 23 | | Classroom 303 | W3 | Flaking | 20 | N | N | 0 | N | N | Additional Chipping; Damage on Wall & Window Sills |
| 33 | 5430 | 1 | 3 | 23 | | Classroom 303 | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 50 SF Posters | N | Limited Inspection |
| 34 | 5430 | 1 | 3 | 023A | | Classroom 303 Closet | Ceiling | Flaking | 4 | N | N | 0 | N | N | Suspended Ceiling; Damage @ Missing Ceiling Tile |
| 35 | 5430 | 1 | 3 | 023A | | Classroom 303 Closet | W1 | Flaking | 30 | N | N | 0 | N | N | |
| 36 | 5430 | 1 | 3 | 023A | | Classroom 303 Closet | W2 | Flaking | 20 | N | N | 0 | N | N | |
| 37 | 5430 | 1 | 3 | 023A | | Classroom 303 Closet | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 38 | 5430 | 1 | 3 | 023A | | Classroom 303 Closet | W4 | Flaking | 25 | N | N | 0 | N | N | |
| 39 | 5430 | 1 | 3 | 024A | | Classroom 304 Closet | Ceiling | Flaking | 32 | N | N | 0 | N | N | |
| 40 | 5430 | 1 | 3 | 024A | | Classroom 304 Closet | W1 | Flaking | 12 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 41 | 5430 | 1 | 3 | 024A | | Classroom 304 Closet | W2 | Flaking | 10 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 42 | 5430 | 1 | 3 | 024A | | Classroom 304 Closet | W3 | Flaking | 18 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 43 | 5430 | 1 | 3 | 024A | | Classroom 304 Closet | W4 | Flaking | 18 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 44 | 5430 | 1 | 3 | 25 | | Classroom 305 | W1 | Flaking | 6 | N | N | 0 | Y - 30 SF Bookcases, Books, Posters | N | Limited Inspection |
| 45 | 5430 | 1 | 3 | 25 | | Classroom 305 | W2 | Cracking | 8 | N | N | 0 | Y - 40 SF Bookcases, Contents | N | Limited Inspection |
| 46 | 5430 | 1 | 3 | 25 | | Classroom 305 | W3 | Flaking | 26 | N | N | 0 | N | N | |
| 47 | 5430 | 1 | 3 | 25 | | Classroom 305 | W4 | Gouges | 3 | N | N | 0 | Y - 30 SF Bookcases, Posters | N | Limited Inspection |
| 48 | 5430 | 1 | 3 | 025A | | Classroom 305 Closet | Ceiling | Flaking | 80 | N | N | 0 | N | N | |
| 49 | 5430 | 1 | 3 | 025A | | Classroom 305 Closet | W1 | Flaking | 30 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|----------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|--------------------------------|
| 50 | 5430 | 1 | 3 | 025A | | Classroom 305 Closet | W2 | Flaking | 20 | N | N | 0 | N | N | |
| 51 | 5430 | 1 | 3 | 025A | | Classroom 305 Closet | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 52 | 5430 | 1 | 3 | 025A | | Classroom 305 Closet | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 53 | 5430 | 1 | 3 | 26 | | Classroom 306 | W1 | Cracking | 8 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 54 | 5430 | 1 | 3 | 26 | | Classroom 306 | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 48 SF Posters | N | Limited Inspection |
| 55 | 5430 | 1 | 3 | 26 | | Classroom 306 | W3 | Flaking | 36 | N | N | 0 | N | N | Additional Chipping |
| 56 | 5430 | 1 | 3 | 26 | | Classroom 306 | W4 | Chipping | 18 | N | N | 0 | Y - 18 SF Posters | N | Limited Inspection |
| 57 | 5430 | 1 | 3 | 026A | | Classroom 306 Closet | W1 | Flaking | 50 | N | N | 0 | N | N | |
| 58 | 5430 | 1 | 3 | 026A | | Classroom 306 Closet | W3 | Chipping | 6 | N | N | 0 | N | N | |
| 59 | 5430 | 1 | 3 | 27 | | Classroom 307 | W1 | Flaking | 22 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 60 | 5430 | 1 | 3 | 27 | | Classroom 307 | W2 | Chipping | 4 | N | N | 0 | Y - 12 SF Posters | N | Additional Gouges |
| 61 | 5430 | 1 | 3 | 27 | | Classroom 307 | W3 | Flaking | 48 | N | N | 0 | Y - 60 SF Desks, Bookcases | N | Limited Inspection |
| 62 | 5430 | 1 | 3 | 27 | | Classroom 307 | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 63 | 5430 | 1 | 3 | 027A | | Classroom 307 Closet | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 64 | 5430 | 1 | 3 | 027A | | Classroom 307 Closet | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 65 | 5430 | 1 | 3 | 027A | | Classroom 307 Closet | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 66 | 5430 | 1 | 3 | 027A | | Classroom 307 Closet | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 67 | 5430 | 1 | 3 | 28 | | Classroom 308 | Floor | Chipping | 120 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 68 | 5430 | 1 | 3 | 28 | | Classroom 308 | W1 | Flaking | 32 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 69 | 5430 | 1 | 3 | 28 | | Classroom 308 | W2 | Chipping | 8 | N | N | 0 | Y - 16 SF Desks | N | Limited Inspection |
| 70 | 5430 | 1 | 3 | 28 | | Classroom 308 | W3 | Flaking | 48 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 71 | 5430 | 1 | 3 | 28 | | Classroom 308 | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 48 SF Desks, Posters, Contents | N | Limited Inspection |
| 72 | 5430 | 1 | 3 | 028A | | Classroom 308 Closet | W1 | Chipping | 4 | N | N | 0 | N | N | |
| 73 | 5430 | 1 | 3 | 028A | | Classroom 308 Closet | W4 | Cracking | 6 | N | N | 0 | N | N | |
| 74 | 5430 | 1 | 3 | 29 | | Classroom 309 | Floor | Chipping | 60 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 75 | 5430 | 1 | 3 | 29 | | Classroom 309 | W1 | Flaking | 60 | N | N | 0 | N | N | Additional Cracking |
| 76 | 5430 | 1 | 3 | 29 | | Classroom 309 | W2 | Chipping | 22 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|----------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|---|
| 77 | 5430 | 1 | 3 | 29 | | Classroom 309 | W3 | Flaking | 80 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 78 | 5430 | 1 | 3 | 29 | | Classroom 309 | W4 | Chipping | 18 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 79 | 5430 | 1 | 3 | 029A | | Classroom 309 Closet | Ceiling | Cracking | 4 | N | N | 0 | N | N | |
| 80 | 5430 | 1 | 3 | 029A | | Classroom 309 Closet | Floor | Chipping | 10 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 81 | 5430 | 1 | 3 | 029A | | Classroom 309 Closet | W1 | Cracking | 12 | N | N | 0 | Y - 40 SF Contents | N | Limited Inspection |
| 82 | 5430 | 1 | 3 | 029A | | Classroom 309 Closet | W2 | Flaking | 8 | N | N | 0 | Y - 80 SF Contents | N | Limited Inspection |
| 83 | 5430 | 1 | 3 | 029A | | Classroom 309 Closet | W3 | Flaking | 4 | N | N | 0 | Y - 40 SF Contents | Y - 1 SF | Limited Inspection |
| 84 | 5430 | 1 | 3 | 30 | | Classroom 310 | Floor | Chipping | 75 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 85 | 5430 | 1 | 3 | 30 | | Classroom 310 | W2 | Cracking | 8 | N | N | 0 | Y - 32 SF Desks, Cabinets, Contents | N | Limited Inspection |
| 86 | 5430 | 1 | 3 | 30 | | Classroom 310 | W3 | Flaking | 20 | N | N | 0 | Y - 36 SF Desks, Contents | N | Limited Inspection |
| 87 | 5430 | 1 | 3 | 30 | | Classroom 310 | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 40 SF Posters | N | Limited Inspection |
| 88 | 5430 | 1 | 3 | 30 | | Classroom 310 | W1 | Chipping | 8 | N | N | 0 | Y - 14 SF Posters | N | |
| 89 | 5430 | 1 | 3 | 030A | | Classroom 310 Closet | Ceiling | Flaking | 6 | Y | N | 0 | N | Y - 6 SF | Additional Efflorescence |
| 90 | 5430 | 1 | 3 | 030A | | Classroom 310 Closet | Floor | Chipping | 20 | N | N | 0 | N | N | Chipping @ Perimeter Baseboard |
| 91 | 5430 | 1 | 3 | 030A | | Classroom 310 Closet | W1 | Flaking | 18 | N | N | 0 | N | Y - 2 SF | Additional Cracking |
| 92 | 5430 | 1 | 3 | 030A | | Classroom 310 Closet | W3 | Cracking | 4 | N | N | 0 | Y - 60 SF Cabinets, Contents | N | Limited Inspection |
| 93 | 5430 | 1 | 3 | 030A | | Classroom 310 Closet | W4 | Flaking | 38 | N | N | 0 | N | N | Additional Cracking; Damage Includes Pipe |
| 94 | 5430 | 1 | 3 | 031A | | Classroom 311 Closet - Kiln Room | W1 | Flaking | 30 | N | N | 0 | N | N | |
| 95 | 5430 | 1 | 3 | 031A | | Classroom 311 Closet - Kiln Room | W2 | Flaking | 30 | N | N | 0 | N | N | |
| 96 | 5430 | 1 | 3 | 031A | | Classroom 311 Closet - Kiln Room | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 97 | 5430 | 1 | 3 | 031A | | Classroom 311 Closet - Kiln Room | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 98 | 5430 | 1 | 3 | 031B | | Classroom 311 Storage Closet | Ceiling | Flaking | 3 | N | N | 0 | N | N | |
| 99 | 5430 | 1 | 3 | 031B | | Classroom 311 Storage Closet | W1 | Partially Inaccessible | 0 | N | N | 0 | Y - 80 SF Boxes, Contents | N | Limited Inspection |
| 100 | 5430 | 1 | 3 | 031B | | Classroom 311 Storage Closet | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 120 SF Boxes, Contents | N | Limited Inspection |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 101 | 5430 | 1 | 3 | 031B | | Classroom 311 Storage Closet | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 120 SF Boxes, Contents | N | Limited Inspection |
| 102 | 5430 | 1 | 3 | 031B | | Classroom 311 Storage Closet | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 60 SF Boxes, Contents | N | Limited Inspection |
| 103 | 5430 | 1 | 3 | 022A | | Closet adjacent to Classroom 302 | W1 | Flaking | 6 | N | N | 0 | N | N | |
| 104 | 5430 | 1 | 3 | 022A | | Closet adjacent to Classroom 302 | W2 | Flaking | 45 | N | N | 0 | N | N | |
| 105 | 5430 | 1 | 3 | 022A | | Closet adjacent to Classroom 302 | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 106 | 5430 | 1 | 3 | 022A | | Closet adjacent to Classroom 302 | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 107 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | Ceiling | Flaking | 50 | N | N | 0 | N | N | |
| 108 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | Floor | Debris | 0 | N | Y - @ Perimeter | 30 | N | N | |
| 109 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | W1 | Flaking | 45 | N | N | 0 | N | N | |
| 110 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 111 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | W3 | Flaking | 45 | N | N | 0 | N | N | |
| 112 | 5430 | 1 | 3 | FTA3 | | Fire Tower A | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 113 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | Ceiling | Flaking | 80 | N | N | 0 | N | N | |
| 114 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | Floor | Debris | 0 | N | Y - @ Perimeter | 30 | N | N | |
| 115 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | W1 | Flaking | 45 | N | N | 0 | N | N | |
| 116 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | W2 | Flaking | 45 | N | N | 0 | N | N | |
| 117 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | W3 | Flaking | 45 | N | N | 0 | N | N | |
| 118 | 5430 | 1 | 3 | FTB3 | | Fire Tower B | W4 | Flaking | 45 | N | N | 0 | N | N | |
| 119 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | Ceiling | Flaking | 80 | N | N | 0 | N | N | |
| 120 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | Floor | Debris | 0 | N | Y - @ Perimeter | 30 | N | N | |
| 121 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | W1 | Flaking | 45 | N | N | 0 | N | N | |
| 122 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | W2 | Flaking | 45 | N | N | 0 | N | N | |
| 123 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | W3 | Flaking | 45 | N | N | 0 | N | N | |
| 124 | 5430 | 1 | 3 | FTC3 | | Fire Tower C | W4 | Flaking | 45 | N | N | 0 | N | N | |
| 125 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | Ceiling | Flaking | 50 | N | N | 0 | N | N | |
| 126 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | Floor | Debris | 0 | N | Y - @ Perimeter | 30 | N | N | |
| 127 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | W1 | Flaking | 45 | N | N | 0 | N | N | |
| 128 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 129 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | W3 | Flaking | 45 | N | N | 0 | N | N | |
| 130 | 5430 | 1 | 3 | FTD3 | | Fire Tower D | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 131 | 5430 | 1 | 3 | 28 | | Girls' Restroom | W1 | Flaking | 12 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 132 | 5430 | 1 | 3 | 28 | | Girls' Restroom | W2 | Flaking | 12 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 133 | 5430 | 1 | 3 | 28 | | Girls' Restroom | W3 | Flaking | 20 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 134 | 5430 | 1 | 3 | 28 | | Girls' Restroom | W4 | Flaking | 12 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 135 | 5430 | 1 | 3 | H312 | | Hallway from Classrooms 301 to 302 | W1 | Flaking | 300 | N | N | 0 | N | N | |
| 136 | 5430 | 1 | 3 | H312 | | Hallway from Classrooms 301 to 302 | W3 | Flaking | 300 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 137 | 5430 | 1 | 3 | H312 | | Hallway from Classrooms 301 to 302 | W4 | Flaking | 10 | N | N | 0 | N | N | |
| 138 | 5430 | 1 | 3 | H311 | | Hallway from Classrooms 303 to 307 | W2 | Flaking | 500 | N | N | 0 | N | N | |
| 139 | 5430 | 1 | 3 | H311 | | Hallway from Classrooms 303 to 307 | W4 | Flaking | 500 | N | N | 0 | N | N | |
| 140 | 5430 | 1 | 3 | H310 | | Hallway from Classrooms 308 to 311 | W1 | Flaking | 180 | N | N | 0 | N | N | |
| 141 | 5430 | 1 | 3 | H310 | | Hallway from Classrooms 308 to 311 | W3 | Flaking | 200 | N | N | 0 | N | N | |
| 142 | 5430 | 1 | 3 | H310 | | Hallway from Classrooms 308 to 311 | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 143 | 5430 | 1 | 3 | 24 | | Science Classroom 304 | Ceiling | Partially Inaccessible | 0 | N | N | 0 | Y - 24 SF Posters | N | Limited Inspection |
| 144 | 5430 | 1 | 3 | 24 | | Science Classroom 304 | W1 | Flaking | 60 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 145 | 5430 | 1 | 3 | 24 | | Science Classroom 304 | W2 | Chipping | 8 | N | N | 0 | Y - 28 SF Desks, Posters | N | Limited Inspection |
| 146 | 5430 | 1 | 3 | 24 | | Science Classroom 304 | W3 | Flaking | 30 | N | N | 0 | N | N | Flaking on Window Sill & Wall |
| 147 | 5430 | 1 | 3 | 24 | | Science Classroom 304 | W4 | Chipping | 6 | N | N | 0 | N | N | |
| 148 | 5430 | 1 | 3 | 024B | | Speech Classroom 314 | W1 | Cracking | 8 | N | N | 0 | Y - 18 SF Cabinets | N | Limited Inspection |
| 149 | 5430 | 1 | 3 | 024B | | Speech Classroom 314 | W2 | Cracking | 6 | N | N | 0 | Y - 20 SF Bookshelves, Posters | N | Limited Inspection |
| 150 | 5430 | 1 | 3 | 024B | | Speech Classroom 314 | W3 | Cracking | 10 | N | N | 0 | Y - 18 SF Posters | N | Limited Inspection |
| 151 | 5430 | 1 | 3 | 024B | | Speech Classroom 314 | W4 | Cracking | 4 | N | N | 0 | N | N | |
| 152 | 5430 | 1 | 3 | S31 | | Stairwell next to Classroom 303 | Ceiling | Flaking | 25 | N | N | 0 | N | N | Additional Cracking |
| 153 | 5430 | 1 | 3 | S31 | | Stairwell next to Classroom 303 | W1 | Flaking | 60 | N | N | 0 | N | N | Additional Cracking |
| 154 | 5430 | 1 | 3 | S31 | | Stairwell next to Classroom 303 | W2 | Flaking | 80 | N | N | 0 | N | N | Additional Cracking |
| 155 | 5430 | 1 | 3 | S31 | | Stairwell next to Classroom 303 | W3 | Flaking | 90 | N | N | 0 | N | N | Additional Cracking |
| 156 | 5430 | 1 | 3 | S31 | | Stairwell next to Classroom 303 | W4 | Flaking | 45 | N | N | 0 | N | N | Additional Cracking |
| 157 | 5430 | 1 | 3 | S32 | | Stairwell next to Classroom 307 | Ceiling | Flaking | 30 | N | N | 0 | N | N | |
| 158 | 5430 | 1 | 3 | S32 | | Stairwell next to Classroom 307 | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 159 | 5430 | 1 | 3 | S32 | | Stairwell next to Classroom 307 | W2 | Flaking | 45 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|--|
| 160 | 5430 | 1 | 3 | S32 | | Stairwell next to Classroom 307 | W3 | Flaking | 60 | N | N | 0 | N | N | |
| 161 | 5430 | 1 | 3 | S32 | | Stairwell next to Classroom 307 | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 162 | 5430 | 1 | 2 | 015C | | Boys' Restroom | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 163 | 5430 | 1 | 2 | 015D | | Boys' Restroom | W2 | Flaking | 10 | N | N | 0 | N | N | |
| 164 | 5430 | 1 | 2 | 015D | | Boys' Restroom | W3 | Flaking | 24 | N | N | 0 | N | N | |
| 165 | 5430 | 1 | 2 | 015D | | Boys' Restroom | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 166 | 5430 | 1 | 2 | 011C | | Classroom 201 | W1 | Flaking | 10 | N | N | 0 | N | N | Additional Cracking |
| 167 | 5430 | 1 | 2 | 011C | | Classroom 201 | W2 | Flaking | 28 | N | N | 0 | N | Y - 2 SF | Additional Cracking; Damage on Wall & Window Sill |
| 168 | 5430 | 1 | 2 | 011C | | Classroom 201 | W3 | Flaking | 64 | Y | N | 0 | N | Y - 4 SF | Additional Efflorescence |
| 169 | 5430 | 1 | 2 | 011C | | Classroom 201 | W4 | Chipping | 4 | N | N | 0 | N | N | |
| 170 | 5430 | 1 | 2 | 011D | | Classroom 201 Closet | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 171 | 5430 | 1 | 2 | 011D | | Classroom 201 Closet | W2 | Flaking | 30 | N | N | 0 | N | N | |
| 172 | 5430 | 1 | 2 | 011D | | Classroom 201 Closet | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 173 | 5430 | 1 | 2 | 011D | | Classroom 201 Closet | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 174 | 5430 | 1 | 2 | 11 | | Classroom 202 | Floor | Chipping | 120 | N | N | 0 | N | N | Chipping @ Perimeter |
| 175 | 5430 | 1 | 2 | 11 | | Classroom 202 | W1 | Cracking | 12 | N | N | 0 | Y - 28 SF Posters | N | Limited Inspection |
| 176 | 5430 | 1 | 2 | 11 | | Classroom 202 | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 40 SF Posters | N | Limited Inspection |
| 177 | 5430 | 1 | 2 | 11 | | Classroom 202 | W3 | Flaking | 80 | N | N | 0 | N | N | Additional Cracking; Damage on Wall, Window Sills, Radiator, Behind Radiator |
| 178 | 5430 | 1 | 2 | 11 | | Classroom 202 | W4 | Flaking | 18 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 179 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | Ceiling | Flaking | 72 | N | N | 0 | N | N | |
| 180 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | Floor | Chipping | 60 | N | N | 0 | N | N | Chipping @ Perimeter |
| 181 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | W1 | Flaking | 120 | N | N | 0 | N | N | |
| 182 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 183 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | W3 | Flaking | 120 | N | N | 0 | N | N | |
| 184 | 5430 | 1 | 2 | 011B | | Classroom 202 Closet | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 185 | 5430 | 1 | 2 | 12 | | Classroom 203 | Floor | Chipping | 0 | N | N | 0 | N | N | Chipping @ Perimeter |
| 186 | 5430 | 1 | 2 | 12 | | Classroom 203 | W1 | Flaking | 26 | N | N | 0 | N | Y - 4 SF | Additional Cracking, Chipping |
| 187 | 5430 | 1 | 2 | 12 | | Classroom 203 | W2 | Flaking | 16 | N | N | 0 | N | N | Additional Chipping |
| 188 | 5430 | 1 | 2 | 12 | | Classroom 203 | W3 | Flaking | 36 | N | N | 0 | N | N | Additional Chipping; Damage on Wall & Window Sill |
| 189 | 5430 | 1 | 2 | 12 | | Classroom 203 | W4 | Chipping | 20 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|----------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 190 | 5430 | 1 | 2 | 012A | | Classroom 203 Closet | W1 | Chipping | 20 | N | N | 0 | N | N | |
| 191 | 5430 | 1 | 2 | 012A | | Classroom 203 Closet | W2 | Chipping | 10 | N | N | 0 | N | N | |
| 192 | 5430 | 1 | 2 | 012A | | Classroom 203 Closet | W3 | Chipping | 20 | N | N | 0 | N | N | |
| 193 | 5430 | 1 | 2 | 012A | | Classroom 203 Closet | W4 | Chipping | 22 | N | N | 0 | N | N | |
| 194 | 5430 | 1 | 2 | 014A | | Classroom 205 Closet | Ceiling | Flaking | 6 | N | N | 0 | N | N | |
| 195 | 5430 | 1 | 2 | 014A | | Classroom 205 Closet | W2 | Flaking | 14 | N | N | 0 | N | N | |
| 196 | 5430 | 1 | 2 | 014A | | Classroom 205 Closet | W3 | Flaking | 6 | N | N | 0 | N | N | |
| 197 | 5430 | 1 | 2 | 014A | | Classroom 205 Closet | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 198 | 5430 | 1 | 2 | 16 | | Classroom 207 | W1 | Flaking | 160 | N | N | 0 | N | N | Additional Chipping |
| 199 | 5430 | 1 | 2 | 16 | | Classroom 207 | W2 | Chipping | 6 | N | N | 0 | N | N | |
| 200 | 5430 | 1 | 2 | 16 | | Classroom 207 | W3 | Flaking | 28 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 201 | 5430 | 1 | 2 | 16 | | Classroom 207 | W4 | Flaking | 80 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 202 | 5430 | 1 | 2 | 016A | | Classroom 207 Closet | W1 | Partially Inaccessible | 0 | N | N | 0 | Y - 30 SF Contents | N | Limited Inspection |
| 203 | 5430 | 1 | 2 | 016A | | Classroom 207 Closet | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 100 SF Contents | N | Limited Inspection |
| 204 | 5430 | 1 | 2 | 016A | | Classroom 207 Closet | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 80 SF Contents | N | Limited Inspection |
| 205 | 5430 | 1 | 2 | 016A | | Classroom 207 Closet | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 40 SF Contents | N | Limited Inspection |
| 206 | 5430 | 1 | 2 | 17 | | Classroom 208 | Floor | Chipping | 20 | N | N | 0 | N | N | Chipping @ Perimeter |
| 207 | 5430 | 1 | 2 | 17 | | Classroom 208 | W2 | Cracking | 16 | N | N | 0 | N | N | Additional Chipping |
| 208 | 5430 | 1 | 2 | 17 | | Classroom 208 | W3 | Flaking | 8 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 209 | 5430 | 1 | 2 | 17 | | Classroom 208 | W4 | Flaking | 8 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 210 | 5430 | 1 | 2 | 017B | | Classroom 208 Closet | W1 | Flaking | 24 | N | N | 0 | N | N | Additional Chipping |
| 211 | 5430 | 1 | 2 | 017B | | Classroom 208 Closet | W3 | Flaking | 32 | N | N | 0 | N | N | Additional Chipping |
| 212 | 5430 | 1 | 2 | 017B | | Classroom 208 Closet | W4 | Flaking | 12 | N | N | 0 | N | N | Additional Chipping |
| 213 | 5430 | 1 | 2 | 18 | | Classroom 209 | Floor | Chipping | 70 | N | N | 0 | N | N | |
| 214 | 5430 | 1 | 2 | 18 | | Classroom 209 | W1 | Flaking | 40 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 215 | 5430 | 1 | 2 | 18 | | Classroom 209 | W2 | Chipping | 2 | N | N | 0 | N | N | |
| 216 | 5430 | 1 | 2 | 18 | | Classroom 209 | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 14 SF Desks, Cabinets | N | Limited Inspection |
| 217 | 5430 | 1 | 2 | 18 | | Classroom 209 | W4 | Cracking | 8 | N | N | 0 | N | N | |
| 218 | 5430 | 1 | 2 | 018A | | Classroom 209 Closet | Ceiling | Flaking | 24 | Y | Y - Beneath Window | 3 | N | Y - 2 SF | Additional Efflorescence |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|----------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|------------------------------------|
| 219 | 5430 | 1 | 2 | 018A | | Classroom 209 Closet | W1 | Flaking | 2 | N | N | 0 | N | N | |
| 220 | 5430 | 1 | 2 | 018A | | Classroom 209 Closet | W2 | Flaking | 50 | N | N | 0 | N | N | Additional Cracking |
| 221 | 5430 | 1 | 2 | 018A | | Classroom 209 Closet | W3 | Flaking | 30 | Y | Y - On Window Sill | 4 | N | Y - 4 SF | Additional Efflorescence, Cracking |
| 222 | 5430 | 1 | 2 | 018A | | Classroom 209 Closet | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 223 | 5430 | 1 | 2 | 19 | | Classroom 210 | Floor | Chipping | 90 | N | N | 0 | N | N | Chipping @ Perimeter |
| 224 | 5430 | 1 | 2 | 19 | | Classroom 210 | W1 | Flaking | 18 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 225 | 5430 | 1 | 2 | 19 | | Classroom 210 | W2 | Flaking | 35 | N | N | 0 | N | N | Additional Chipping |
| 226 | 5430 | 1 | 2 | 19 | | Classroom 210 | W3 | Flaking | 70 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 227 | 5430 | 1 | 2 | 19 | | Classroom 210 | W4 | Flaking | 48 | N | N | 0 | N | N | Additional Chipping |
| 228 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | Ceiling | Flaking | 8 | N | N | 0 | N | N | |
| 229 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | Floor | Chipping | 60 | N | N | 0 | N | N | Chipping @ Perimeter |
| 230 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | W1 | Flaking | 8 | N | N | 0 | N | N | |
| 231 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | W2 | Flaking | 48 | N | N | 0 | N | N | |
| 232 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | W3 | Flaking | 60 | Y | N | 0 | N | Y - 6 SF | Additional Efflorescence |
| 233 | 5430 | 1 | 2 | 019A | | Classroom 210 Closet | W4 | Flaking | 120 | Y | N | 0 | N | Y - 8 SF | Additional Efflorescence |
| 234 | 5430 | 1 | 2 | 20 | | Classroom 211 | Ceiling | Chipping | 16 | N | N | 0 | N | N | |
| 235 | 5430 | 1 | 2 | 20 | | Classroom 211 | W1 | Flaking | 4 | N | N | 0 | N | N | Additional Cracking |
| 236 | 5430 | 1 | 2 | 20 | | Classroom 211 | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 40 SF Books, Posters | N | Limited Inspection |
| 237 | 5430 | 1 | 2 | 20 | | Classroom 211 | W3 | Flaking | 42 | N | N | 0 | N | N | Additional Cracking |
| 238 | 5430 | 1 | 2 | 20 | | Classroom 211 | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 239 | 5430 | 1 | 2 | 020A | | Classroom 211 Closet | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 80 SF Boxes, Contents | N | Limited Inspection |
| 240 | 5430 | 1 | 2 | 020A | | Classroom 211 Closet | W3 | Flaking | 20 | N | N | 0 | N | N | Additional Cracking |
| 241 | 5430 | 1 | 2 | 020A | | Classroom 211 Closet | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 242 | 5430 | 1 | 2 | 011E | | Closet adjacent to Classroom 202 | W1 | Flaking | 8 | N | N | 0 | N | N | Additional Chipping |
| 243 | 5430 | 1 | 2 | 011E | | Closet adjacent to Classroom 202 | W2 | Flaking | 45 | N | N | 0 | N | N | Additional Chipping |
| 244 | 5430 | 1 | 2 | 011E | | Closet adjacent to Classroom 202 | W3 | Flaking | 30 | N | N | 0 | N | N | Additional Chipping |
| 245 | 5430 | 1 | 2 | 011E | | Closet adjacent to Classroom 202 | W4 | Flaking | 50 | N | N | 0 | N | N | Additional Chipping |
| 246 | 5430 | 1 | 2 | 017A | | Closet adjacent to Classroom 208 | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 247 | 5430 | 1 | 2 | 017A | | Closet adjacent to Classroom 208 | W4 | Flaking | 60 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 248 | 5430 | 1 | 2 | 13A | | Closet next to Faculty Lounge 204 | Ceiling | Flaking | 6 | N | N | 0 | N | N | |
| 249 | 5430 | 1 | 2 | 13A | | Closet next to Faculty Lounge 204 | W2 | Flaking | 10 | N | N | 0 | Y - 40 SF Contents | N | Limited Inspection |
| 250 | 5430 | 1 | 2 | 13A | | Closet next to Faculty Lounge 204 | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 10 SF Contents | N | Limited Inspection |
| 251 | 5430 | 1 | 2 | 13A | | Closet next to Faculty Lounge 204 | W4 | Flaking | 20 | N | N | 0 | Y - 40 SF Contents | N | Limited Inspection |
| 252 | 5430 | 1 | 2 | 14 | | Computer Room 205 | W1 | Flaking | 12 | N | N | 0 | N | N | Additional Chipping |
| 253 | 5430 | 1 | 2 | 14 | | Computer Room 205 | W3 | Flaking | 46 | N | N | 0 | N | N | Additional Chipping |
| 254 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 255 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 256 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 257 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 258 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 259 | 5430 | 1 | 2 | 014AA | | Computer Room 205 Server Closet | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 260 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 261 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 262 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 263 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 264 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | E l e m e n t | F l o o r | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------------------------------|-----------------------|----------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|---|
| 265 | 5430 | 1 | 2 | 014D | | Computer Room Storage Room Closet within Closet that has a Sink | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 266 | 5430 | 1 | 2 | 13 | | Faculty Lounge 204 | W3 | Flaking | 12 | N | N | 0 | N | N | Additional Cracking, Chipping; Damage on Wall & Window Sill |
| 267 | 5430 | 1 | 2 | 020B | | Faculty Restroom adjacent to Classroom 211 | W1 | Flaking | 5 | N | N | 0 | N | N | |
| 268 | 5430 | 1 | 2 | 020B | | Faculty Restroom adjacent to Classroom 211 | W2 | Cracking | 6 | N | N | 0 | N | N | |
| 269 | 5430 | 1 | 2 | 020B | | Faculty Restroom adjacent to Classroom 211 | W3 | Flaking | 12 | N | N | 0 | N | N | |
| 270 | 5430 | 1 | 2 | 020B | | Faculty Restroom adjacent to Classroom 211 | W4 | Flaking | 8 | N | N | 0 | N | N | |
| 271 | 5430 | 1 | 2 | FTA2 | | Fire Tower A | Ceiling | Flaking | 40 | N | N | 0 | N | N | |
| 272 | 5430 | 1 | 2 | FTA2 | | Fire Tower A | W1 | Flaking | 25 | N | N | 0 | N | N | |
| 273 | 5430 | 1 | 2 | FTA2 | | Fire Tower A | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 274 | 5430 | 1 | 2 | FTA2 | | Fire Tower A | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 275 | 5430 | 1 | 2 | FTA2 | | Fire Tower A | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 276 | 5430 | 1 | 2 | FTB2 | | Fire Tower B | Ceiling | Flaking | 40 | N | N | 0 | N | N | |
| 277 | 5430 | 1 | 2 | FTB2 | | Fire Tower B | W1 | Flaking | 30 | N | N | 0 | N | N | |
| 278 | 5430 | 1 | 2 | FTB2 | | Fire Tower B | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 279 | 5430 | 1 | 2 | FTB2 | | Fire Tower B | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 280 | 5430 | 1 | 2 | FTB2 | | Fire Tower B | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 281 | 5430 | 1 | 2 | FTC2 | | Fire Tower C | Ceiling | Flaking | 40 | N | N | 0 | N | N | |
| 282 | 5430 | 1 | 2 | FTC2 | | Fire Tower C | W1 | Flaking | 30 | N | N | 0 | N | N | |
| 283 | 5430 | 1 | 2 | FTC2 | | Fire Tower C | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 284 | 5430 | 1 | 2 | FTC2 | | Fire Tower C | W3 | Flaking | 30 | N | N | 0 | N | N | |
| 285 | 5430 | 1 | 2 | FTC2 | | Fire Tower C | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 286 | 5430 | 1 | 2 | FTD2 | | Fire Tower D | Ceiling | Flaking | 50 | N | N | 0 | N | N | |
| 287 | 5430 | 1 | 2 | FTD2 | | Fire Tower D | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 288 | 5430 | 1 | 2 | FTD2 | | Fire Tower D | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 289 | 5430 | 1 | 2 | FTD2 | | Fire Tower D | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 290 | 5430 | 1 | 2 | FTD2 | | Fire Tower D | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 291 | 5430 | 1 | 2 | H29 | | Hallway from Classrooms 201 to 202 | W1 | Flaking | 200 | N | N | 0 | N | N | |
| 292 | 5430 | 1 | 2 | H29 | | Hallway from Classrooms 201 to 202 | W3 | Flaking | 200 | N | N | 0 | N | N | |
| 293 | 5430 | 1 | 2 | H29 | | Hallway from Classrooms 201 to 202 | W4 | Chipping | 10 | N | N | 0 | N | N | |
| 294 | 5430 | 1 | 2 | H28 | | Hallway from Classrooms 203 to 207 | W2 | Flaking | 360 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 295 | 5430 | 1 | 2 | H28 | | Hallway from Classrooms 203 to 207 | W4 | Flaking | 360 | N | N | 0 | N | N | |
| 296 | 5430 | 1 | 2 | H27 | | Hallway from Classrooms 208 to 211 | W1 | Flaking | 250 | N | N | 0 | N | N | |
| 297 | 5430 | 1 | 2 | H27 | | Hallway from Classrooms 208 to 211 | W3 | Flaking | 250 | N | N | 0 | N | N | |
| 298 | 5430 | 1 | 2 | 15 | | School Store 206 | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 120 SF Shelves, Contents | N | Limited Inspection |
| 299 | 5430 | 1 | 2 | 15 | | School Store 206 | W3 | Flaking | 16 | N | N | 0 | N | N | Additional Chipping |
| 300 | 5430 | 1 | 2 | S21 | | Stairwell next to Classroom 203 | W1 | Flaking | 30 | N | N | 0 | N | N | |
| 301 | 5430 | 1 | 2 | S21 | | Stairwell next to Classroom 203 | W2 | Flaking | 50 | N | N | 0 | N | N | |
| 302 | 5430 | 1 | 2 | S21 | | Stairwell next to Classroom 203 | W3 | Flaking | 25 | N | N | 0 | N | N | |
| 303 | 5430 | 1 | 2 | S21 | | Stairwell next to Classroom 203 | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 304 | 5430 | 1 | 2 | S22 | | Stairwell next to Classroom 207 | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 305 | 5430 | 1 | 2 | S22 | | Stairwell next to Classroom 207 | W2 | Flaking | 35 | N | N | 0 | N | N | |
| 306 | 5430 | 1 | 2 | S22 | | Stairwell next to Classroom 207 | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 307 | 5430 | 1 | 2 | S22 | | Stairwell next to Classroom 207 | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 308 | 5430 | 1 | 1 | 1 | | Classroom 101 | W1 | Flaking | 180 | N | N | 0 | N | N | |
| 309 | 5430 | 1 | 1 | 1 | | Classroom 101 | W2 | Flaking | 120 | N | N | 0 | N | N | |
| 310 | 5430 | 1 | 1 | 1 | | Classroom 101 | W3 | Flaking | 180 | N | N | 0 | N | N | |
| 311 | 5430 | 1 | 1 | 1 | | Classroom 101 | W4 | Flaking | 120 | N | N | 0 | N | N | |
| 312 | 5430 | 1 | 1 | 001A | | Classroom 101 Closet | Ceiling | Flaking | 10 | N | N | 0 | N | Y - 10 SF | |
| 313 | 5430 | 1 | 1 | 001A | | Classroom 101 Closet | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 314 | 5430 | 1 | 1 | 001A | | Classroom 101 Closet | W2 | Flaking | 10 | N | N | 0 | N | N | |
| 315 | 5430 | 1 | 1 | 001A | | Classroom 101 Closet | W3 | Flaking | 8 | N | N | 0 | N | N | |
| 316 | 5430 | 1 | 1 | 001A | | Classroom 101 Closet | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 317 | 5430 | 1 | 1 | 8 | | Classroom 108 | Floor | Chipping | 120 | N | N | 0 | N | N | |
| 318 | 5430 | 1 | 1 | 8 | | Classroom 108 | W1 | Flaking | 120 | N | N | 0 | N | N | |
| 319 | 5430 | 1 | 1 | 8 | | Classroom 108 | W2 | Flaking | 100 | N | N | 0 | N | N | |
| 320 | 5430 | 1 | 1 | 8 | | Classroom 108 | W3 | Flaking | 48 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 321 | 5430 | 1 | 1 | 8 | | Classroom 108 | W4 | Flaking | 60 | N | N | 0 | Y - 40 SF | N | Limited Inspection |
| 322 | 5430 | 1 | 1 | 008A | | Classroom 108 Closet | W1 | Flaking | 28 | N | N | 0 | N | N | Additional Chipping |
| 323 | 5430 | 1 | 1 | 008A | | Classroom 108 Closet | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 120 SF Contents | N | Limited Inspection |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|--------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 324 | 5430 | 1 | 1 | 008A | | Classroom 108 Closet | W4 | Flaking | 0 | N | N | 0 | Y - 80 SF Contents | N | Limited Inspection |
| 325 | 5430 | 1 | 1 | 9 | | Classroom 109 | W1 | Flaking | 60 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 326 | 5430 | 1 | 1 | 9 | | Classroom 109 | W2 | Chipping | 18 | N | N | 0 | Y - 20 SF Posters | N | Limited Inspection |
| 327 | 5430 | 1 | 1 | 9 | | Classroom 109 | W3 | Flaking | 32 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 328 | 5430 | 1 | 1 | 9 | | Classroom 109 | W4 | Flaking | 24 | N | N | 0 | N | N | |
| 329 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | Ceiling | Flaking | 10 | N | N | 0 | N | N | |
| 330 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | Floor | Chipping | 16 | N | N | 0 | N | N | Chipping @ Perimeter |
| 331 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | W1 | Cracking | 20 | N | N | 0 | N | Y - 1 SF | Additional Chipping |
| 332 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | W2 | Cracking | 4 | N | N | 0 | N | N | |
| 333 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | W3 | Flaking | 16 | N | N | 0 | N | N | |
| 334 | 5430 | 1 | 1 | 009A | | Classroom 109 Closet | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 64 SF Boxes | N | Limited Inspection |
| 335 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | Ceiling | Flaking | 10 | N | N | 0 | N | N | |
| 336 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | Floor | Chipping | 40 | N | N | 0 | N | N | Chipping @ Perimeter |
| 337 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | W1 | Cracking | 40 | N | N | 0 | N | N | |
| 338 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | W2 | Flaking | 16 | N | N | 0 | N | N | Additional Chipping |
| 339 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | W3 | Flaking | 150 | N | N | 0 | N | N | |
| 340 | 5430 | 1 | 1 | 009B | | Classroom 109 Restroom | W4 | Cracking | 30 | N | N | 0 | N | N | |
| 341 | 5430 | 1 | 1 | 002D | | Closet adjacent to Main Office | W1 | Chipping | 8 | N | N | 0 | N | N | |
| 342 | 5430 | 1 | 1 | 002D | | Closet adjacent to Main Office | W2 | Chipping | 8 | N | N | 0 | N | N | |
| 343 | 5430 | 1 | 1 | 002D | | Closet adjacent to Main Office | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 28 SF Contents | N | Limited Inspection |
| 344 | 5430 | 1 | 1 | 002D | | Closet adjacent to Main Office | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 20 SF Contents | N | Limited Inspection |
| 345 | 5430 | 1 | 1 | 002C | | Counselor's Office | W1 | Cracking | 4 | N | N | 0 | N | N | Additional Chipping |
| 346 | 5430 | 1 | 1 | 002C | | Counselor's Office | W2 | Cracking | 4 | N | N | 0 | N | N | |
| 347 | 5430 | 1 | 1 | 002C | | Counselor's Office | W3 | Flaking | 4 | Y | N | 0 | N | Y - 4 SF | Additional Efflorescence |
| 348 | 5430 | 1 | 1 | 002C | | Counselor's Office | W4 | Chipping | 12 | N | N | 0 | N | N | |
| 349 | 5430 | 1 | 1 | FTA1 | | Fire Tower A | Ceiling | Flaking | 12 | N | N | 0 | N | N | |
| 350 | 5430 | 1 | 1 | FTA1 | | Fire Tower A | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 351 | 5430 | 1 | 1 | FTA1 | | Fire Tower A | W2 | Flaking | 10 | N | N | 0 | N | N | |
| 352 | 5430 | 1 | 1 | FTA1 | | Fire Tower A | W3 | Flaking | 18 | N | N | 0 | N | N | |
| 353 | 5430 | 1 | 1 | FTA1 | | Fire Tower A | W4 | Flaking | 10 | N | N | 0 | N | N | |
| 354 | 5430 | 1 | 1 | FTB1 | | Fire Tower B | Ceiling | Flaking | 25 | N | N | 0 | N | N | |
| 355 | 5430 | 1 | 1 | FTB1 | | Fire Tower B | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 356 | 5430 | 1 | 1 | FTB1 | | Fire Tower B | W2 | Flaking | 20 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 357 | 5430 | 1 | 1 | FTB1 | | Fire Tower B | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 358 | 5430 | 1 | 1 | FTB1 | | Fire Tower B | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 359 | 5430 | 1 | 1 | FTC1 | | Fire Tower C | Ceiling | Flaking | 10 | N | N | 0 | N | N | |
| 360 | 5430 | 1 | 1 | FTC1 | | Fire Tower C | W1 | Flaking | 16 | N | N | 0 | N | N | |
| 361 | 5430 | 1 | 1 | FTC1 | | Fire Tower C | W2 | Flaking | 18 | N | N | 0 | N | N | |
| 362 | 5430 | 1 | 1 | FTC1 | | Fire Tower C | W3 | Flaking | 10 | N | N | 0 | N | N | |
| 363 | 5430 | 1 | 1 | FTC1 | | Fire Tower C | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 364 | 5430 | 1 | 1 | FTD1 | | Fire Tower D | Ceiling | Flaking | 10 | N | N | 0 | N | N | |
| 365 | 5430 | 1 | 1 | FTD1 | | Fire Tower D | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 366 | 5430 | 1 | 1 | FTD1 | | Fire Tower D | W2 | Flaking | 15 | N | N | 0 | N | N | |
| 367 | 5430 | 1 | 1 | FTD1 | | Fire Tower D | W3 | Flaking | 12 | N | N | 0 | N | N | |
| 368 | 5430 | 1 | 1 | FTD1 | | Fire Tower D | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 369 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 370 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 371 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 372 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 373 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 374 | 5430 | 1 | 1 | 010B | | Gym Equipment Storage next to Gym / Auditorium | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 375 | 5430 | 1 | 1 | 10 | | Gymnasium/Auditorium | W1 | Flaking | 40 | N | N | 0 | N | N | Additional Chipping |
| 376 | 5430 | 1 | 1 | 10 | | Gymnasium/Auditorium | W2 | Flaking | 60 | N | N | 0 | N | N | Additional Chipping |
| 377 | 5430 | 1 | 1 | 10 | | Gymnasium/Auditorium | W3 | Chipping | 16 | N | N | 0 | N | N | |
| 378 | 5430 | 1 | 1 | 10 | | Gymnasium/Auditorium | W4 | Flaking | 40 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 379 | 5430 | 1 | 1 | H16 | | Hallway from Classroom 101 to Main Office | W1 | Flaking | 200 | N | N | 0 | N | N | |
| 380 | 5430 | 1 | 1 | H16 | | Hallway from Classroom 101 to Main Office | W3 | Flaking | 150 | N | N | 0 | N | N | |
| 381 | 5430 | 1 | 1 | H15 | | Hallway from Classroom 103 to Multipurpose Room | W2 | Flaking | 180 | N | N | 0 | N | N | |
| 382 | 5430 | 1 | 1 | H15 | | Hallway from Classroom 103 to Multipurpose Room | W4 | Flaking | 210 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|--------------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 383 | 5430 | 1 | 1 | H14 | | Hallway from Classroom 108 to Gym | W1 | Flaking | 150 | N | N | 0 | N | N | |
| 384 | 5430 | 1 | 1 | H14 | | Hallway from Classroom 108 to Gym | W3 | Flaking | 180 | N | N | 0 | N | N | |
| 385 | 5430 | 1 | 1 | 3 | | IMC | W1 | Flaking | 45 | N | N | 0 | N | N | Additional Chipping |
| 386 | 5430 | 1 | 1 | 3 | | IMC | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 387 | 5430 | 1 | 1 | 3 | | IMC | W3 | Flaking | 20 | N | N | 0 | N | N | |
| 388 | 5430 | 1 | 1 | 3 | | IMC | W4 | Flaking | 40 | N | N | 0 | N | N | |
| 389 | 5430 | 1 | 1 | 003B | | IMC Closet on Main Office side | Ceiling | Flaking | 20 | N | N | 0 | N | N | |
| 390 | 5430 | 1 | 1 | 003B | | IMC Closet on Main Office side | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 391 | 5430 | 1 | 1 | 003B | | IMC Closet on Main Office side | W2 | Flaking | 14 | N | N | 0 | N | N | |
| 392 | 5430 | 1 | 1 | 003B | | IMC Closet on Main Office side | W3 | Flaking | 8 | N | N | 0 | N | N | |
| 393 | 5430 | 1 | 1 | 003B | | IMC Closet on Main Office side | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 394 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 395 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 396 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 397 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 398 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 399 | 5430 | 1 | 1 | 003D | | IMC Closet on Multipurpose Room side | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 400 | 5430 | 1 | 1 | 003C | | IMC Closet, center | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 401 | 5430 | 1 | 1 | 003C | | IMC Closet, center | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 402 | 5430 | 1 | 1 | 003C | | IMC Closet, center | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 403 | 5430 | 1 | 1 | 003C | | IMC Closet, center | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 404 | 5430 | 1 | 1 | 003C | | IMC Closet, center | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 405 | 5430 | 1 | 1 | 003C | | IMC Closet, center | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 406 | 5430 | 1 | 1 | 2 | | Main Office | W1 | Chipping | 1 | N | N | 0 | N | N | Chipping @ Door Frame |
| 407 | 5430 | 1 | 1 | 2 | | Main Office | W3 | Chipping | 4 | N | N | 0 | N | N | |
| 408 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 409 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 410 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 411 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------------|
| 412 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 413 | 5430 | 1 | 1 | 002H | | Main Office Server Closet | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 414 | 5430 | 1 | 1 | 006C | | Men's Restroom | W1 | Flaking | 5 | N | N | 0 | N | N | |
| 415 | 5430 | 1 | 1 | 006C | | Men's Restroom | W2 | Flaking | 8 | N | N | 0 | N | N | |
| 416 | 5430 | 1 | 1 | 006C | | Men's Restroom | W3 | Flaking | 4 | N | N | 0 | N | N | |
| 417 | 5430 | 1 | 1 | 006C | | Men's Restroom | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 418 | 5430 | 1 | 1 | 6 | | Multipurpose Room (MPR) | W1 | Flaking | 24 | N | N | 0 | N | N | Additional Cracking, Chipping |
| 419 | 5430 | 1 | 1 | 6 | | Multipurpose Room (MPR) | W3 | Flaking | 40 | N | N | 0 | N | N | Additional Chipping |
| 420 | 5430 | 1 | 1 | 006A | | Multipurpose Room Closet on IMC side | Ceiling | Flaking | 16 | N | N | 0 | N | N | |
| 421 | 5430 | 1 | 1 | 006A | | Multipurpose Room Closet on IMC side | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 422 | 5430 | 1 | 1 | 006A | | Multipurpose Room Closet on IMC side | W2 | Flaking | 10 | N | N | 0 | N | N | |
| 423 | 5430 | 1 | 1 | 006A | | Multipurpose Room Closet on IMC side | W3 | Flaking | 14 | N | N | 0 | N | N | |
| 424 | 5430 | 1 | 1 | 006A | | Multipurpose Room Closet on IMC side | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 425 | 5430 | 1 | 1 | 006B | | Multipurpose Room Closet on Stairwell side | Ceiling | Flaking | 10 | N | N | 0 | N | N | |
| 426 | 5430 | 1 | 1 | 006B | | Multipurpose Room Closet on Stairwell side | W1 | Flaking | 8 | N | N | 0 | N | N | |
| 427 | 5430 | 1 | 1 | 006B | | Multipurpose Room Closet on Stairwell side | W2 | Flaking | 4 | N | N | 0 | N | N | |
| 428 | 5430 | 1 | 1 | 006B | | Multipurpose Room Closet on Stairwell side | W3 | Flaking | 12 | N | N | 0 | N | N | |
| 429 | 5430 | 1 | 1 | 006B | | Multipurpose Room Closet on Stairwell side | W4 | Flaking | 12 | N | N | 0 | N | N | |
| 430 | 5430 | 1 | 1 | 002F | | Nurse's Office | W2 | Flaking | 25 | N | N | 0 | N | N | |
| 431 | 5430 | 1 | 1 | 002F | | Nurse's Office | W3 | Flaking | 4 | N | N | 0 | N | N | |
| 432 | 5430 | 1 | 1 | 002F | | Nurse's Office | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 25 SF Bookcases, Books, Contents | N | Limited Inspection |
| 433 | 5430 | 1 | 1 | 002A | | Principal's Office | W3 | Gouges | 1 | N | N | 0 | N | N | |
| 434 | 5430 | 1 | 1 | 002B | | Principal's Office Restroom | W3 | Cracking | 8 | N | N | 0 | N | N | |
| 435 | 5430 | 1 | 1 | 010A | | Stage | Ceiling | Flaking | 140 | N | N | 0 | N | N | |
| 436 | 5430 | 1 | 1 | 010A | | Stage | W2 | Chipping | 4 | N | N | 0 | N | N | |
| 437 | 5430 | 1 | 1 | 010A | | Stage | W3 | Chipping | 5 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|-----------------------------------|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 438 | 5430 | 1 | 1 | 010A | | Stage | W4 | Chipping | 5 | N | N | 0 | N | N | |
| 439 | 5430 | 1 | 1 | S12 | | Stairwell near Multipurpose Room | Ceiling | Flaking | 12 | N | N | 0 | N | N | |
| 440 | 5430 | 1 | 1 | S12 | | Stairwell near Multipurpose Room | W1 | Flaking | 9 | N | N | 0 | N | N | |
| 441 | 5430 | 1 | 1 | S12 | | Stairwell near Multipurpose Room | W2 | Flaking | 14 | N | N | 0 | N | N | |
| 442 | 5430 | 1 | 1 | S12 | | Stairwell near Multipurpose Room | W3 | Flaking | 18 | N | N | 0 | N | N | |
| 443 | 5430 | 1 | 1 | S12 | | Stairwell near Multipurpose Room | W4 | Flaking | 20 | N | N | 0 | N | N | |
| 444 | 5430 | 1 | 1 | S11 | | Stairwell next to IMC | Ceiling | Flaking | 16 | N | N | 0 | N | N | |
| 445 | 5430 | 1 | 1 | S11 | | Stairwell next to IMC | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 446 | 5430 | 1 | 1 | S11 | | Stairwell next to IMC | W2 | Flaking | 26 | N | N | 0 | N | N | |
| 447 | 5430 | 1 | 1 | S11 | | Stairwell next to IMC | W3 | Flaking | 8 | N | N | 0 | N | N | |
| 448 | 5430 | 1 | 1 | S11 | | Stairwell next to IMC | W4 | Flaking | 20 | N | N | 0 | N | N | |
| 449 | 5430 | 1 | 1 | 006D | | Women's Restroom | W1 | Flaking | 2 | N | N | 0 | N | N | |
| 450 | 5430 | 1 | 1 | 006D | | Women's Restroom | W2 | Flaking | 6 | N | N | 0 | N | N | |
| 451 | 5430 | 1 | 1 | 006D | | Women's Restroom | W3 | Flaking | 12 | N | N | 0 | N | N | |
| 452 | 5430 | 1 | 1 | 006D | | Women's Restroom | W4 | Flaking | 8 | N | N | 0 | N | N | |
| 453 | 5430 | 1 | 0 | 001B | | Boys' Restroom | Ceiling | Flaking | 16 | N | N | 0 | N | N | |
| 454 | 5430 | 1 | 0 | 001B | | Boys' Restroom | W3 | Chipping | 20 | N | N | 0 | N | N | |
| 455 | 5430 | 1 | 0 | 001B | | Boys' Restroom | W4 | Chipping | 20 | N | N | 0 | N | N | |
| 456 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 457 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 458 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 459 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 460 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|--|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 461 | 5430 | 1 | 0 | 006A | | Closet under Richmond side Stairs | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 462 | 5430 | 1 | 0 | 011B | | Closet under Salmon side stairs | W2 | Flaking | 6 | N | N | 0 | Y - 10 SF Contents | N | Limited Inspection |
| 463 | 5430 | 1 | 0 | 011B | | Closet under Salmon side stairs | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 12 SF Contents | N | Limited Inspection |
| 464 | 5430 | 1 | 0 | 011B | | Closet under Salmon side stairs | W4 | Cracking | 10 | N | N | 0 | Y - 16 SF Contents | N | Limited Inspection |
| 465 | 5430 | 1 | 0 | 003C | | Dietitian's Office | Ceiling | Flaking | 20 | N | N | 0 | N | N | |
| 466 | 5430 | 1 | 0 | 003C | | Dietitian's Office | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 467 | 5430 | 1 | 0 | 003C | | Dietitian's Office | W2 | Flaking | 14 | N | N | 0 | N | N | |
| 468 | 5430 | 1 | 0 | 003C | | Dietitian's Office | W3 | Flaking | 8 | N | N | 0 | N | N | |
| 469 | 5430 | 1 | 0 | 003C | | Dietitian's Office | W4 | Flaking | 16 | N | N | 0 | N | N | |
| 470 | 5430 | 1 | 0 | 006B | | Electrical Room | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 471 | 5430 | 1 | 0 | 006B | | Electrical Room | W2 | Flaking | 60 | N | N | 0 | N | N | |
| 472 | 5430 | 1 | 0 | 006B | | Electrical Room | W3 | Flaking | 45 | N | N | 0 | N | N | |
| 473 | 5430 | 1 | 0 | 006B | | Electrical Room | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 474 | 5430 | 1 | 0 | 003BB | | Emergency Exit | Ceiling | Flaking | 20 | N | N | 0 | N | N | |
| 475 | 5430 | 1 | 0 | 003BB | | Emergency Exit | W1 | Flaking | 15 | N | N | 0 | N | N | |
| 476 | 5430 | 1 | 0 | 003BB | | Emergency Exit | W2 | Flaking | 25 | N | N | 0 | N | N | |
| 477 | 5430 | 1 | 0 | 003BB | | Emergency Exit | W3 | Flaking | 10 | N | N | 0 | N | N | |
| 478 | 5430 | 1 | 0 | 003BB | | Emergency Exit | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 479 | 5430 | 1 | 0 | 015E | | Emergency Exit Stair | Ceiling | Flaking | 20 | N | N | 0 | N | N | |
| 480 | 5430 | 1 | 0 | 015E | | Emergency Exit Stair | W1 | Flaking | 12 | N | N | 0 | N | N | |
| 481 | 5430 | 1 | 0 | 015E | | Emergency Exit Stair | W2 | Flaking | 16 | N | N | 0 | N | N | |
| 482 | 5430 | 1 | 0 | 015E | | Emergency Exit Stair | W3 | Flaking | 18 | N | N | 0 | N | N | |
| 483 | 5430 | 1 | 0 | 015E | | Emergency Exit Stair | W4 | Flaking | 10 | N | N | 0 | N | N | |
| 484 | 5430 | 1 | 0 | 015C | | Exit Vestibule next to Custodial Storage | W1 | Flaking | 40 | N | N | 0 | N | N | |
| 485 | 5430 | 1 | 0 | 015C | | Exit Vestibule next to Custodial Storage | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 486 | 5430 | 1 | 0 | 015C | | Exit Vestibule next to Custodial Storage | W3 | Flaking | 60 | N | N | 0 | N | N | |
| 487 | 5430 | 1 | 0 | 015C | | Exit Vestibule next to Custodial Storage | W4 | Flaking | 50 | N | N | 0 | N | N | |
| 488 | 5430 | 1 | 0 | H02 | | Hallway between Richmond and Salmon Stairwells | W1 | Flaking | 110 | N | N | 0 | N | N | |
| 489 | 5430 | 1 | 0 | H02 | | Hallway between Richmond and Salmon Stairwells | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 490 | 5430 | 1 | 0 | H02 | | Hallway between Richmond and Salmon Stairwells | W3 | Flaking | 160 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|--------------------------|
| 491 | 5430 | 1 | 0 | H02 | | Hallway between Richmond and Salmon Stairwells | W4 | Flaking | 30 | N | N | 0 | N | N | |
| 492 | 5430 | 1 | 0 | H03 | | Hallway from Boys' Restroom to Utility Entry Room | W1 | Flaking | 200 | N | N | 0 | N | N | |
| 493 | 5430 | 1 | 0 | H03 | | Hallway from Boys' Restroom to Utility Entry Room | W2 | Flaking | 10 | N | N | 0 | N | N | |
| 494 | 5430 | 1 | 0 | H03 | | Hallway from Boys' Restroom to Utility Entry Room | W3 | Flaking | 160 | N | N | 0 | N | N | |
| 495 | 5430 | 1 | 0 | H03 | | Hallway from Boys' Restroom to Utility Entry Room | W4 | Flaking | 10 | N | N | 0 | N | N | |
| 496 | 5430 | 1 | 0 | H01 | | Hallway from Building Engineer's Restroom to Exit Vestibule | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 497 | 5430 | 1 | 0 | H01 | | Hallway from Building Engineer's Restroom to Exit Vestibule | W2 | Flaking | 200 | N | N | 0 | N | N | |
| 498 | 5430 | 1 | 0 | H01 | | Hallway from Building Engineer's Restroom to Exit Vestibule | W3 | Flaking | 10 | N | N | 0 | N | N | |
| 499 | 5430 | 1 | 0 | H01 | | Hallway from Building Engineer's Restroom to Exit Vestibule | W4 | Flaking | 200 | N | N | 0 | N | N | |
| 500 | 5430 | 1 | 0 | 013B | | Kitchen Storage Room next to Lunchroom A | W2 | Partially Inaccessible | 0 | N | N | 0 | Y - 20 SF Contents | N | Limited Inspection |
| 501 | 5430 | 1 | 0 | 013B | | Kitchen Storage Room next to Lunchroom A | W3 | Partially Inaccessible | 0 | N | N | 0 | Y - 16 SF Contents | N | Limited Inspection |
| 502 | 5430 | 1 | 0 | 013B | | Kitchen Storage Room next to Lunchroom A | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 24 SF Contents | N | Limited Inspection |
| 503 | 5430 | 1 | 0 | 007B | | Lunchroom A | W1 | Chipping | 30 | N | N | 0 | N | N | |
| 504 | 5430 | 1 | 0 | 007B | | Lunchroom A | W3 | Flaking | 300 | Y | N | 0 | N | Y - 40 SF | Additional Efflorescence |
| 505 | 5430 | 1 | 0 | 007B | | Lunchroom A | W4 | Chipping | 8 | N | N | 0 | N | N | |
| 506 | 5430 | 1 | 0 | 005B | | Lunchroom B | Ceiling | Cracking | 20 | N | N | 0 | N | N | |
| 507 | 5430 | 1 | 0 | 005B | | Lunchroom B | W1 | Flaking | 180 | N | N | 0 | N | N | |
| 508 | 5430 | 1 | 0 | 005B | | Lunchroom B | W2 | Flaking | 90 | N | N | 0 | N | N | |
| 509 | 5430 | 1 | 0 | 005B | | Lunchroom B | W3 | Flaking | 110 | N | N | 0 | N | N | |
| 510 | 5430 | 1 | 0 | 005B | | Lunchroom B | W4 | Flaking | 20 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 511 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 512 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 513 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 514 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 515 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 516 | 5430 | 1 | 0 | 005B1 | | Lunchroom B Storage on exterior wall | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 517 | 5430 | 1 | 0 | 005B3 | | Lunchroom B Storage on hall wall | Ceiling | Cracking | 4 | N | N | 0 | N | N | |
| 518 | 5430 | 1 | 0 | 005B3 | | Lunchroom B Storage on hall wall | W2 | Cracking | 5 | N | N | 0 | N | N | |
| 519 | 5430 | 1 | 0 | 005B3 | | Lunchroom B Storage on hall wall | W4 | Partially Inaccessible | 0 | N | N | 0 | Y - 16 SF Contents | N | Limited Inspection |
| 520 | 5430 | 1 | 0 | 004F | | Refrigerator Room | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 521 | 5430 | 1 | 0 | 004F | | Refrigerator Room | W2 | Flaking | 40 | N | N | 0 | N | N | |
| 522 | 5430 | 1 | 0 | 004F | | Refrigerator Room | W3 | Flaking | 26 | N | N | 0 | N | N | |
| 523 | 5430 | 1 | 0 | 004F | | Refrigerator Room | W4 | Flaking | 48 | N | N | 0 | N | N | |
| 524 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 525 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 526 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 527 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 528 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 529 | 5430 | 1 | 0 | 004D | | Small Storage Closet next to Lunchroom B | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 530 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | Ceiling | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | E l e m e n t | F l o o r | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------------------------------|-----------------------|----------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 531 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | Floor | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 532 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | W1 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 533 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | W2 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 534 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | W3 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 535 | 5430 | 1 | 0 | 015D | | Storage Closet next to Emergency Exit Stair | W4 | Inaccessible | N/A | N/A | N/A | N/A | N/A | N/A | Inspection Required |
| 536 | 5430 | 1 | 0 | 014B | | Storage Room across from Lunchroom A | Ceiling | Cracking | 4 | N | N | 0 | N | N | |
| 537 | 5430 | 1 | 0 | 014B | | Storage Room across from Lunchroom A | W2 | Flaking | 16 | N | N | 0 | Y - 24 SF Contents | N | Limited Inspection |
| 538 | 5430 | 1 | 0 | 014B | | Storage Room across from Lunchroom A | W3 | Flaking | 10 | N | N | 0 | Y - 12 SF Contents | N | Limited Inspection |
| 539 | 5430 | 1 | 0 | 014B | | Storage Room across from Lunchroom A | W4 | Flaking | 8 | N | N | 0 | Y - 20 SF Contents | N | Limited Inspection |
| 540 | 5430 | 1 | 0 | 017B | | Storage Room next to Building Engineer's Restroom | W2 | Chipping | 8 | N | N | 0 | N | N | |
| 541 | 5430 | 1 | 0 | 017B | | Storage Room next to Building Engineer's Restroom | W4 | Chipping | 10 | N | N | 0 | N | N | |
| 542 | 5430 | 1 | 0 | 004C | | Storage Room next to Dietitian's Office, Lunchroom B side | W1 | Flaking | 5 | N | N | 0 | N | N | |
| 543 | 5430 | 1 | 0 | 004C | | Storage Room next to Dietitian's Office, Lunchroom B side | W2 | Flaking | 20 | N | N | 0 | N | N | |
| 544 | 5430 | 1 | 0 | 004C | | Storage Room next to Dietitian's Office, Lunchroom B side | W3 | Flaking | 15 | N | N | 0 | N | N | |
| 545 | 5430 | 1 | 0 | 004C | | Storage Room next to Dietitian's Office, Lunchroom B side | W4 | Flaking | 12 | N | N | 0 | N | N | |

AMY at James Martin -Scope of Work

| Task ID | ULCS# | Element | Floor | Space # (on Floor Plan) | Space Type | On Site Room Name | Component | Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage) | Quantity (sf) | On-going Moisture Intrusion (yes or no) | Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location) | Quantity (sf) | Contents Need to be Moved (i.e. posters, contents, furniture) | Plastering Needed (yes or no) | Other Notes or Comments |
|---------|-------|---------|-------|-------------------------|------------|---|-----------|---|---------------|---|---|---------------|---|-------------------------------|-------------------------|
| 546 | 5430 | 1 | 0 | 004B | | Storage Room next to Dietitian's Office, Restrooms side | W1 | Flaking | 5 | N | N | 0 | N | N | |
| 547 | 5430 | 1 | 0 | 004B | | Storage Room next to Dietitian's Office, Restrooms side | W2 | Flaking | 12 | N | N | 0 | N | N | |
| 548 | 5430 | 1 | 0 | 004B | | Storage Room next to Dietitian's Office, Restrooms side | W3 | Flaking | 16 | N | N | 0 | N | N | |
| 549 | 5430 | 1 | 0 | 004B | | Storage Room next to Dietitian's Office, Restrooms side | W4 | Flaking | 4 | N | N | 0 | N | N | |
| 550 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | Ceiling | Flaking | 12 | N | N | 0 | N | N | Additional Cracking |
| 551 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | Floor | Chipping | 200 | N | N | 0 | N | N | Chipping @ Perimeter |
| 552 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | W1 | Flaking | 10 | N | N | 0 | N | N | |
| 553 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | W2 | Flaking | 36 | N | N | 0 | N | N | |
| 554 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | W3 | Flaking | 75 | N | N | 0 | N | N | |
| 555 | 5430 | 1 | 0 | 003B | | Storage Room next to Girls' Restroom (former Lunchroom C) | W4 | Flaking | 60 | N | N | 0 | N | N | |
| 556 | 5430 | 1 | 0 | 005A | | Utility Entry Room | W1 | Flaking | 20 | N | N | 0 | N | N | |
| 557 | 5430 | 1 | 0 | 005A | | Utility Entry Room | W2 | Flaking | 35 | N | N | 0 | N | N | |
| 558 | 5430 | 1 | 0 | 005A | | Utility Entry Room | W3 | Flaking | 25 | N | N | 0 | N | N | |
| 559 | 5430 | 1 | 0 | 005A | | Utility Entry Room | W4 | Flaking | 20 | N | N | 0 | N | N | |