

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	1010	1	4	401B		Boys' Restroom	Ceiling	Flaking	200	N	N	0	N	N	
2	1010	1	4	401B		Boys' Restroom	Floor	Debris	0	N	Y - @ Perimeter	40	N	N	
3	1010	1	4	401B		Boys' Restroom	W1	Flaking	20	N	N	0	N	N	Unoccupied
4	1010	1	4	401B		Boys' Restroom	W2	Flaking	40	N	N	0	N	N	
5	1010	1	4	401B		Boys' Restroom	W3	Flaking	10	N	N	0	N	N	
6	1010	1	4	401B		Boys' Restroom	W4	Flaking	50	N	N	0	N	N	
7	1010	1	4	S405		C-Wing Stairwell to the 4th Floor	Ceiling	Flaking	110	N	N	0	N	N	
8	1010	1	4	S405		C-Wing Stairwell to the 4th Floor	W1	Flaking	75	N	N	0	N	N	Unoccupied
9	1010	1	4	S405		C-Wing Stairwell to the 4th Floor	W2	Flaking	70	N	N	0	N	N	
10	1010	1	4	S405		C-Wing Stairwell to the 4th Floor	W3	Flaking	70	N	N	0	N	N	
11	1010	1	4	S405		C-Wing Stairwell to the 4th Floor	W4	Flaking	90	N	N	0	N	N	
12	1010	1	4	401C		Girls' Restroom	Ceiling	Flaking	16	N	N	0	N	N	
13	1010	1	4	401		Lobby 401	W1	Flaking	20	N	N	0	N	N	Unoccupied
14	1010	1	4	401		Lobby 401	W2	Flaking	20	N	N	0	N	N	
15	1010	1	4	401		Lobby 401	W3	Flaking	50	N	N	0	N	N	
16	1010	1	4	401		Lobby 401	W4	Flaking	30	N	N	0	N	N	
17	1010	1	4	400A		Music/Choir Room	Ceiling	Flaking	50	Y	N	0	N	Y - 50 SF	
18	1010	1	4	400A		Music/Choir Room	Floor	Debris	0	N	Y - @ Perimeter	40	N	N	
19	1010	1	4	400A		Music/Choir Room	W1	Flaking	60	N	N	0	N	N	Unoccupied
20	1010	1	4	400A		Music/Choir Room	W2	Flaking	48	N	N	0	N	N	
21	1010	1	4	400A		Music/Choir Room	W3	Flaking	90	N	N	0	N	N	
22	1010	1	4	400A		Music/Choir Room	W4	Flaking	50	N	N	0	N	N	
23	1010	1	4	401A		Office 401A	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
24	1010	1	4	401A		Office 401A	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
25	1010	1	4	401A		Office 401A	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
26	1010	1	4	401A		Office 401A	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
27	1010	1	4	401A		Office 401A	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
28	1010	1	4	401A		Office 401A	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
29	1010	1	4	S48		Stairwell adjacent to School Yard(402)	Ceiling	Flaking	210	Y	N	0	N	N	
30	1010	1	4	S48		Stairwell adjacent to School Yard(402)	Floor	Debris	0	N	Y - Entire Floor	200	N	N	
31	1010	1	4	S48		Stairwell adjacent to School Yard(402)	W1	Flaking	120	N	N	0	N	N	Unoccupied
32	1010	1	4	S48		Stairwell adjacent to School Yard(402)	W2	Flaking	100	N	N	0	N	N	
33	1010	1	4	S48		Stairwell adjacent to School Yard(402)	W3	Flaking	40	Y	N	0	N	N	
34	1010	1	4	S48		Stairwell adjacent to School Yard(402)	W4	Flaking	200	N	N	0	N	Y - 20 SF	Additional Efflorescence
35	1010	1	4	S44		Stairwell C	Ceiling	Cracking	10	N	N	0	N	N	
36	1010	1	4	S22		Stairwell C	Ceiling	Flaking	60	N	N	0	N	N	
37	1010	1	4	S22		Stairwell C	W1	Flaking	20	N	N	0	N	N	Unoccupied
38	1010	1	4	S44		Stairwell C	W1	Flaking	22	N	N	0	N	N	Unoccupied
39	1010	1	4	S22		Stairwell C	W2	Flaking	40	N	N	0	N	N	
40	1010	1	4	S44		Stairwell C	W2	Flaking	34	N	N	0	N	N	
41	1010	1	4	S22		Stairwell C	W3	Flaking	30	N	N	0	N	N	
42	1010	1	4	S44		Stairwell C	W3	Flaking	50	N	N	0	N	N	
43	1010	1	4	S22		Stairwell C	W4	Flaking	40	N	N	0	N	N	
44	1010	1	4	S44		Stairwell C	W4	Flaking	40	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
45	1010	1	3	3A		Book Storage (315)	Ceiling	Flaking	96	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
46	1010	1	3	3A		Book Storage (315)	W1	Cracking	41	N	N	0	N	N	
47	1010	1	3	3A		Book Storage (315)	W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Books	N	Inspection Needed
48	1010	1	3	3A		Book Storage (315)	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Books	N	Inspection Needed
49	1010	1	3	3A		Book Storage (315)	W4	Cracking	24	N	N	0	Y - 100 SF Books	N	
50	1010	1	3	3F		Book Storage (326)	Ceiling	Flaking	192	Y	N	0	N	Y - 16 SF	Additional Efflorescence, Cracking, Holes
51	1010	1	3	3F		Book Storage (326)	Floor	Debris	0	N	Y - Throughout	90	N	N	
52	1010	1	3	3F		Book Storage (326)	W1	Flaking	27	N	N	0	Y - 20 SF Bookcases, Books	N	Additional Cracking
53	1010	1	3	3F		Book Storage (326)	W2	Flaking	75	N	N	0	Y - 240 SF Bookcases, Books	N	Additional Cracking
54	1010	1	3	3F		Book Storage (326)	W3	Flaking	115	N	N	0	Y - 60 Contents, Tables	N	
55	1010	1	3	3F		Book Storage (326)	W4	Flaking	100	Y	Y - On Bookcases	20	Y - 120 SF Bookcases, Books	Y - 8 SF	Additional Efflorescence, Cracking, Chipping
56	1010	1	3	H- C		B-Wing Hallway 327-316	W2	Cracking	46	N	N	0	N	N	
57	1010	1	3	H- C		B-Wing Hallway 327-316	W3	Chipping	4	N	N	0	N	N	
58	1010	1	3	H- C		B-Wing Hallway 327-316	W4	Cracking	28	N	N	0	N	N	
59	1010	1	3	301		Classroom 301	W1	Chipping	3	N	N	0	N	N	
60	1010	1	3	301		Classroom 301	W3	Chipping	6	N	N	0	N	N	Chipping on Radiator
61	1010	1	3	301		Classroom 301	W4	Cracking	3	N	N	0	N	N	Additional Chipping
62	1010	1	3	302		Classroom 302	W1	Cracking	6	N	N	0	N	N	Additional Cracking, Holes
63	1010	1	3	302		Classroom 302	W2	Flaking	8	N	Y	2	N	N	Additional Holes
64	1010	1	3	302		Classroom 302	W4	Chipping	1	N	N	0	N	N	Sheetrock Wall
65	1010	1	3	303		Classroom 303	Ceiling	Flaking	2	Y	N	0	N	N	Additional Efflorescence; Suspended Ceiling; Damage @ Missing Ceiling Tiles
66	1010	1	3	303		Classroom 303	W1	Chipping	12	N	N	0	N	N	
67	1010	1	3	303		Classroom 303	W3	Chipping	3	N	N	0	N	N	
68	1010	1	3	304		Classroom 304	W1	Cracking	6	N	N	0	N	N	Additional Cracking, Holes
69	1010	1	3	304		Classroom 304	W2	Flaking	8	N	Y	2	N	N	Additional Holes
70	1010	1	3	304		Classroom 304	W4	Chipping	1	N	N	0	N	N	Sheetrock Wall
71	1010	1	3	305		Classroom 305	W1	Chipping	28	N	N	0	N	N	
72	1010	1	3	305		Classroom 305	W3	Chipping	3	N	N	0	N	N	2 Locations; Chipping @ Wall & Radiator
73	1010	1	3	305		Classroom 305	W4	Chipping	9	N	N	0	N	N	
74	1010	1	3	306		Classroom 306	W1	Chipping	12	N	N	0	N	N	
75	1010	1	3	306		Classroom 306	W2	Chipping	2	N	N	0	N	N	2 Locations
76	1010	1	3	306		Classroom 306	W3	Flaking	6	N	N	0	N	N	Additional Chipping
77	1010	1	3	306		Classroom 306	W4	Chipping	2	N	N	0	N	N	
78	1010	1	3	307		Classroom 307	W1	Chipping	12	N	N	0	N	N	
79	1010	1	3	307		Classroom 307	W2	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping
80	1010	1	3	307		Classroom 307	W3	Chipping	4	N	N	0	N	N	
81	1010	1	3	307		Classroom 307	W4	Chipping	2	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
82	1010	1	3	313		Classroom 313	Ceiling	Flaking	2	N	N	0	N	N	Flaking @ Window Lintel 4; Suspended Ceiling Tile
83	1010	1	3	313		Classroom 313	W1	Flaking	12	N	N	0	Y - 15 SF Posters	N	3 Locations; Additional Cracking, Chipping
84	1010	1	3	313		Classroom 313	W2	Cracking	1	N	N	0	N	N	
85	1010	1	3	313		Classroom 313	W3	Cracking	28	N	N	0	N	Y - 1 SF	Additional Chipping, Holes
86	1010	1	3	313		Classroom 313	W4	Chipping	5	N	N	0	N	N	
87	1010	1	3	316		Classroom 316	W1	Flaking	16	N	N	0	N	N	Additional Chipping; Sheetrock Wall; Room Under Construction
88	1010	1	3	316		Classroom 316	W4	Flaking	24	N	N	0	N	N	Additional Chipping; Sheetrock Wall; Room Under Construction
89	1010	1	3	317		Classroom 317	W1	Flaking	30	N	N	0	N	N	Sheetrock Wall; Room Under Construction
90	1010	1	3	317		Classroom 317	W2	Flaking	44	N	N	0	N	N	Sheetrock Wall; Room Under Construction
91	1010	1	3	318		Classroom 318	W1	Flaking	6	N	N	0	N	N	Additional Chipping; Sheetrock Wall; Room Under Construction
92	1010	1	3	318		Classroom 318	W2	Chipping	7	N	N	0	N	N	Sheetrock Wall; Room Under Construction
93	1010	1	3	319		Classroom 319	W1	Flaking	120	N	N	0	N	N	Additional Chipping; Room Under Construction
94	1010	1	3	319		Classroom 319	W4	Flaking	80	N	N	0	N	N	Additional Chipping; Room Under Construction
95	1010	1	3	320		Classroom 320	Floor	Debris	0	N	Y - Beneath Window 5	1	N	N	
96	1010	1	3	320		Classroom 320	W1	Flaking	69	N	N	0	N	Y - 2 SF	Additional Cracking
97	1010	1	3	320		Classroom 320	W2	Flaking	6	N	N	0	N	Y - 2 SF	Additional Cracking
98	1010	1	3	320		Classroom 320	W3	Flaking	60	N	N	0	N	Y - 12 SF	Additional Cracking, Chipping
99	1010	1	3	320		Classroom 320	W4	Chipping	4	N	N	0	N	N	
100	1010	1	3	321		Classroom 321	Ceiling	Flaking	3	Y	N	0	N	N	Additional Efflorescence; Damage @ Window Lintel; Suspended Ceiling
101	1010	1	3	321		Classroom 321	W1	Flaking	12	N	N	0	Y - 30 SF Cabinets	N	Additional Chipping
102	1010	1	3	321		Classroom 321	W3	Flaking	1	N	N	0	N	Y - 3 SF	Additional Cracking, Chipping
103	1010	1	3	321		Classroom 321	W4	Cracking	24	N	N	0	Y - 24 SF Cabinets, Desks	N	Additional Chipping
104	1010	1	3	324		Classroom 324	Ceiling	Cracking	3	N	N	0	N	N	Suspended Ceiling; Cracking @ Perimeter
105	1010	1	3	324		Classroom 324	W1	Flaking	24	Y	Y - On Counter	1	Y - 8 SF Posters	Y - 7 SF	Additional Efflorescence, Cracking, Chipping
106	1010	1	3	324		Classroom 324	W2	Cracking	8	N	N	0	Y - 20 SF Posters	N	Additional Chipping
107	1010	1	3	324		Classroom 324	W3	Flaking	22	Y	N	0	Y - 24 SF Tables	Y - 2 SF	Additional Efflorescence, Cracking
108	1010	1	3	324		Classroom 324	W4	Chipping	6	N	N	0	Y - 20 SF Posters	N	
109	1010	1	3	325		Classroom 325	W1	Flaking	21	Y	N	0	Y - 24 SF Posters	Y - 5 SF	Additional Efflorescence, Cracking
110	1010	1	3	325		Classroom 325	W2	Flaking	4	N	N	0	Y - 18 SF Posters	N	Additional Chipping
111	1010	1	3	325		Classroom 325	W3	Flaking	12	N	N	0	Y - 84 SF File Cabinets, Tables	N	Additional Cracking, Chipping

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
112	1010	1	3	325		Classroom 325	W4	Partially Inaccessible	0	N	Y - In Sink	1	Y - 72 SF Posters	N	Inspection Needed
113	1010	1	3	331		Classroom 331	Ceiling	Flaking	8	Y	N	0	N	N	Flaking @ Window Lintels; Suspended Ceiling; Water Stain on Ceiling Tile
114	1010	1	3	331		Classroom 331	W1	Flaking	24	N	N	0	N	Y - 2 SF	Additional Cracking, Chipping
115	1010	1	3	331		Classroom 331	W2	Cracking	7	N	N	0	N	Y - 7 SF	Additional Chipping, Holes
116	1010	1	3	331		Classroom 331	W3	Flaking	76	N	Y - On Radiator	1	N	N	Additional Cracking, Chipping
117	1010	1	3	331		Classroom 331	W4	Flaking	14	N	N	0	N	Y - 3 SF	Additional Cracking, Chipping, Holes
118	1010	1	3	332		Classroom 332	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
119	1010	1	3	332		Classroom 332	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
120	1010	1	3	332		Classroom 332	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
121	1010	1	3	332		Classroom 332	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
122	1010	1	3	332		Classroom 332	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
123	1010	1	3	332		Classroom 332	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
124	1010	1	3	333		Classroom 333	Ceiling	Flaking	12	Y	N	0	N	Y - 3 SF	Additional Efflorescence; Damage @ Window Lintel; Suspended Ceiling
125	1010	1	3	333		Classroom 333	Floor	Debris	0	N	Y - Beneath Window 3	3	N	N	
126	1010	1	3	333		Classroom 333	W1	Flaking	60	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
127	1010	1	3	333		Classroom 333	W2	Chipping	60	N	N	0	N	Y - 1 SF	Additional Gouges
128	1010	1	3	333		Classroom 333	W3	Flaking	120	Y	Y - On Window Sill	3	N	Y - 5 SF	Additional Efflorescence, Cracking, Chipping
129	1010	1	3	333		Classroom 333	W4	Cracking	5	N	N	0	N	N	Additional Chipping
130	1010	1	3	334		Classroom 334	W1	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping
131	1010	1	3	334		Classroom 334	W2	Flaking	16	N	N	0	N	N	Additional Cracking, Chipping
132	1010	1	3	334		Classroom 334	W3	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping; Damage @ Wall & Radiator
133	1010	1	3	334		Classroom 334	W4	Flaking	5	N	N	0	Y - 32 SF Tables	N	2 Locations; Additional Chipping
134	1010	1	3	335		Classroom 335	Ceiling	Flaking	16	Y	N	0	N	Y - 8 SF	Additional Efflorescence; Damage @ Window Lintels; Suspended Ceiling Tile
135	1010	1	3	335		Classroom 335	W1	Flaking	48	N	N	0	Y - 8 SF Posters	N	Additional Cracking, Chipping
136	1010	1	3	335		Classroom 335	W2	Flaking	18	N	N	0	Y - 16 SF Posters	N	Additional Cracking, Holes
137	1010	1	3	335		Classroom 335	W3	Flaking	110	N	Y	8	N	N	Additional Cracking, Chipping, Holes; Damage @ Pipe, Radiator & Wall
138	1010	1	3	335		Classroom 335	W4	Cracking	6	N	N	0	N	N	
139	1010	1	3	336		Classroom 336	Ceiling	Flaking	2	N	N	0	N	N	Suspended Ceiling
140	1010	1	3	336		Classroom 336	W1	Flaking	44	N	N	0	N	Y - 2 SF	Additional Cracking
141	1010	1	3	336		Classroom 336	W2	Cracking	10	N	N	0	N	N	
142	1010	1	3	336		Classroom 336	W3	Flaking	3	N	N	0	N	N	
143	1010	1	3	336		Classroom 336	W4	Flaking	160	N	N	0	N	N	Additional Cracking, Chipping, Holes
144	1010	1	3	337		Classroom 337	Ceiling	Flaking	12	Y	N	0	N	Y - 4 SF	Additional Efflorescence; Suspended Ceiling; Damage @ Window Lintels
145	1010	1	3	337		Classroom 337	W1	Flaking	6	N	N	0	Y - 44 SF Posters	Y - 1 SF	Additional Cracking, Chipping
146	1010	1	3	337		Classroom 337	W2	Gouges	2	N	N	0	Y - 40 SF Desks, Posters	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
147	1010	1	3	337		Classroom 337	W3	Flaking	38	N	Y - On Window Sill	2	Y - 15 SF Tables, File Cabinets	Y - 3 SF	Additional Cracking, Chipping
148	1010	1	3	337		Classroom 337	W4	Partially Inaccessible	0	N	N	0	Y - 10 SF Posters	N	Inspection Needed
149	1010	1	3	338		Classroom 338	Ceiling	Flaking	6	N	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling
150	1010	1	3	338		Classroom 338	W1	Flaking	18	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
151	1010	1	3	338		Classroom 338	W2	Cracking	5	N	N	0	N	N	2 Locations
152	1010	1	3	338		Classroom 338	W3	Flaking	100	Y	N	0	N	Y - 3 SF	Additional Efflorescence, Cracking, Chipping
153	1010	1	3	338		Classroom 338	W4	Cracking	6	N	N	0	N	N	
154	1010	1	3	339		Classroom 339	W1	Cracking	6	N	N	0	N	N	Additional Chipping
155	1010	1	3	339		Classroom 339	W2	Flaking	2	N	N	0	N	Y - 2 SF	Additional Cracking, Chipping, Holes
156	1010	1	3	339		Classroom 339	W3	Cracking	8	N	N	0	N	Y - 1 SF	Additional Chipping
157	1010	1	3	339		Classroom 339	W4	Chipping	3	N	N	0	N	N	Additional Holes, Gouges
158	1010	1	3	340		Classroom 340	Floor	Debris	0	N	Y - @ Perimeter	6	N	N	
159	1010	1	3	340		Classroom 340	W1	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
160	1010	1	3	340		Classroom 340	W2	Flaking	84	N	N	0	N	N	Additional Cracking
161	1010	1	3	340		Classroom 340	W3	Flaking	124	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall & Pipe
162	1010	1	3	340		Classroom 340	W4	Flaking	72	N	N	0	N	N	Additional Cracking, Chipping
163	1010	1	3	341		Classroom 341	Floor	Debris	0	N	Y - Beneath Windows	4	N	N	
164	1010	1	3	341		Classroom 341	W1	Flaking	24	Y	N	0	N	Y - 16 SF	Additional Efflorescence, Cracking, Chipping
165	1010	1	3	341		Classroom 341	W2	Chipping	3	N	N	0	N	N	
166	1010	1	3	341		Classroom 341	W3	Flaking	78	N	N	0	N	Y - 1 SF	Additional Chipping
167	1010	1	3	341		Classroom 341	W4	Chipping	4	N	N	0	N	N	Suspended Ceiling
168	1010	1	3	342		Classroom 342	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
169	1010	1	3	342		Classroom 342	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
170	1010	1	3	342		Classroom 342	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
171	1010	1	3	342		Classroom 342	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
172	1010	1	3	342		Classroom 342	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
173	1010	1	3	342		Classroom 342	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
174	1010	1	3	346		Classroom 346	Ceiling	Flaking	8	Y	N	0	N	N	Additional Efflorescence; Damage @ Window Lintels; Suspended Ceiling
175	1010	1	3	346		Classroom 346	Floor	Debris	0	N	Y - Beneath Windows	4	N	N	
176	1010	1	3	346		Classroom 346	W1	Flaking	280	N	N	0	Y - 24 SF Chairs, Desks	Y - 5 SF	Additional Cracking, Chipping
177	1010	1	3	346		Classroom 346	W2	Chipping	32	N	N	0	Y - 48 SF Desks, Chairs, File Cabinets	N	
178	1010	1	3	346		Classroom 346	W3	Flaking	280	N	Y - On Window Sills & Radiator	12	Y - 48 SF Desks, Chairs, File Cabinets	Y - 1 SF	Additional Cracking, Chipping
179	1010	1	3	346		Classroom 346	W4	Flaking	120	N	N	0	Y - 32 SF Desks, Contents	N	Additional Cracking, Chipping
180	1010	1	3	306		Conference Room 306	Ceiling	Flaking	5	Y	N	0	N	N	Additional Efflorescence
181	1010	1	3	306		Conference Room 306	W1	Chipping	54	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
182	1010	1	3	306		Conference Room 306	W4	Debris	0	N	Y - On Window Sills 4 & 6	4	N	N	
183	1010	1	3	309		Copy Room 307	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
184	1010	1	3	309		Copy Room 307	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
185	1010	1	3	309		Copy Room 307	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
186	1010	1	3	309		Copy Room 307	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
187	1010	1	3	309		Copy Room 307	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
188	1010	1	3	309		Copy Room 307	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
189	1010	1	3	3B		General Storage Area (315)	Ceiling	Flaking	5	Y	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling; Water Stains
190	1010	1	3	3B		General Storage Area (315)	Floor	Debris	0	N	Y - Near Radiator	1	N	N	
191	1010	1	3	3B		General Storage Area (315)	W1	Chipping	6	N	N	0	N	N	Chipping @ Door Frame
192	1010	1	3	3B		General Storage Area (315)	W3	Flaking	8	N	N	0	N	N	Additional Cracking
193	1010	1	3	3H		General Storage Area (326)	Floor	Debris	0	N	Y - @ Perimeter	3	N	N	
194	1010	1	3	3H		General Storage Area (326)	W1	Flaking	120	N	N	0	Y - 96 SF Boxes	Y - 1 SF	Additional Cracking
195	1010	1	3	3H		General Storage Area (326)	W2	Flaking	49	N	N	0	Y - 45 SF Boxes, Contents	N	Additional Cracking
196	1010	1	3	3H		General Storage Area (326)	W3	Flaking	32	N	N	0	Y - 40 SF Contents	N	Additional Cracking
197	1010	1	3	3H		General Storage Area (326)	W4	Flaking	180	N	N	0	Y - 70 SF Boxes, Contents	N	Additional Cracking
198	1010	1	3	H- B		Hallway 309-301	W2	Flaking	26	N	N	0	N	N	Additional Cracking, Chipping
199	1010	1	3	H- B		Hallway 309-301	W3	Chipping	2	N	N	0	N	N	
200	1010	1	3	H- B		Hallway 309-301	W4	Cracking	34	N	N	0	N	N	Additional Chipping
201	1010	1	3	H- A		Hallway 313-346	W1	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping
202	1010	1	3	H- A		Hallway 313-346	W3	Cracking	26	N	N	0	N	N	Additional Chipping
203	1010	1	3	H- D		Hallway 331-340	W2	Cracking	18	N	N	0	N	N	
204	1010	1	3	H- D		Hallway 331-340	W4	Cracking	30	N	N	0	N	N	
205	1010	1	3	H315		Hallway from Storage 3A to Rear Fan Room	Floor	Chipping	88	N	Y - @ Perimeter	40	N	N	
206	1010	1	3	H315		Hallway from Storage 3A to Rear Fan Room	W1	Flaking	20	N	N	0	N	Y - 5 SF	Additional Cracking, Holes
207	1010	1	3	H315		Hallway from Storage 3A to Rear Fan Room	W2	Flaking	240	Y	N	0	N	Y - 75 SF	Additional Efflorescence, Cracking
208	1010	1	3	H315		Hallway from Storage 3A to Rear Fan Room	W3	Flaking	30	N	N	0	N	N	Additional Efflorescence, Cracking
209	1010	1	3	H315		Hallway from Storage 3A to Rear Fan Room	W4	Flaking	200	Y	N	0	N	Y - 16 SF	Additional Efflorescence, Cracking
210	1010	1	3	H326		Hallway from Storage 3F to Fan Room	Floor	Debris	0	N	Y - Entire Floor	96	N	N	
211	1010	1	3	H326		Hallway from Storage 3F to Fan Room	W1	Flaking	14	N	N	0	N	N	Additional Cracking

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
212	1010	1	3	H326		Hallway from Storage 3F to Fan Room	W2	Flaking	480	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping, Holes
213	1010	1	3	H326		Hallway from Storage 3F to Fan Room	W3	Flaking	14	N	N	0	N	N	Additional Cracking
214	1010	1	3	H326		Hallway from Storage 3F to Fan Room	W4	Flaking	360	Y	N	0	N	Y - 80 SF	Additional Efflorescence, Cracking
215	1010	1	3	L-01		Lobby adjacent to Room 317	Ceiling	Flaking	120	N	N	0	N	N	
216	1010	1	3	L-01		Lobby adjacent to Room 317	W1	Flaking	90	N	N	0	N	N	
217	1010	1	3	L-01		Lobby adjacent to Room 317	W2	Flaking	60	N	N	0	N	N	
218	1010	1	3	L-01		Lobby adjacent to Room 317	W3	Flaking	80	N	N	0	N	N	
219	1010	1	3	L-01		Lobby adjacent to Room 317	W4	Flaking	40	N	N	0	N	N	
220	1010	1	3	Boy's Toilet		Men's Restroom	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
221	1010	1	3	Boy's Toilet		Men's Restroom	W2	Flaking	1	N	N	0	N	N	
222	1010	1	3	Boy's Toilet		Men's Restroom	W3	Flaking	0	N	N	0	N	N	
223	1010	1	3	309A		Office 309	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
224	1010	1	3	309		Office 309	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
225	1010	1	3	309A		Office 309	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
226	1010	1	3	309A		Office 309	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
227	1010	1	3	309A		Office 309	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
228	1010	1	3	309A		Office 309	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
229	1010	1	3	310		Office 310	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
230	1010	1	3	310		Office 310	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
231	1010	1	3	310		Office 310	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
232	1010	1	3	310		Office 310	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
233	1010	1	3	310		Office 310	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
234	1010	1	3	310		Office 310	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
235	1010	1	3	311		Office 311	Ceiling	Efflorescence	1	Y	N	0	N	N	Suspended Ceiling; Efflorescence Above Missing Ceiling Tile
236	1010	1	3	311		Office 311	Floor	Debris	0	N	Y - Under Window	3	N	N	
237	1010	1	3	311		Office 311	W1	Cracking	2	N	N	0	N	N	2 Locations; Additional Chipping
238	1010	1	3	311		Office 311	W2	Flaking	4	N	N	0	N	N	2 Locations; Additional Chipping, Holes
239	1010	1	3	311		Office 311	W3	Debris	1	N	Y - On Radiator	1	N	N	
240	1010	1	3	311		Office 311	W4	Chipping	4	N	N	0	N	N	
241	1010	1	3	314		Office 314	Ceiling	Flaking	16	N	N	0	N	Y - 8 SF	Additional Cracking, Holes
242	1010	1	3	314		Office 314	Floor	Chipping	40	N	N	0	N	N	Chipping @ Perimeter
243	1010	1	3	314		Office 314	W1	Efflorescence	30	Y	N	0	N	Y - 30 SF	Additional Cracking
244	1010	1	3	314		Office 314	W2	Flaking	84	Y	N	0	N	Y - 4 SF	Additional Efflorescence, Cracking, Chipping
245	1010	1	3	314		Office 314	W3	Cracking	20	N	N	0	N	Y - 1 SF	Additional Hole
246	1010	1	3	314		Office 314	W4	Flaking	60	N	N	0	N	N	Additional Cracking, Chipping
247	1010	1	3	328		Office 327	Floor	Debris	0	N	Y - @ Perimeter	20	N	N	
248	1010	1	3	328		Office 327	W1	Flaking	3	N	N	0	N	N	Additional Chipping
249	1010	1	3	328		Office 327	W2	Flaking	160	N	Y - On Cabinets	16	Y - 16 SF Boxes	N	Additional Cracking, Chipping, Holes
250	1010	1	3	328		Office 327	W3	Cracking	1	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
251	1010	1	3	328		Office 327	W4	Flaking	22	N	N	0	N	N	Additional Cracking
252	1010	1	3	329		Office 329	Ceiling	Flaking	3	N	N	0	N	N	Suspended Ceiling; Damage @ Window Lintel
253	1010	1	3	329		Office 329	W1	Flaking	8	N	N	0	N	Y - 1 SF	2 Locations; Additional Cracking, Chipping
254	1010	1	3	329		Office 329	W2	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping
255	1010	1	3	329		Office 329	W3	Flaking	24	N	Y - On Radiator	3	N	N	
256	1010	1	3	329		Office 329	W4	Flaking	2	N	N	0	N	N	
257	1010	1	3	330		Office 330	W1	Flaking	40	N	N	0	N	Y - 3 SF	Additional Cracking
258	1010	1	3	330		Office 330	W2	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
259	1010	1	3	330		Office 330	W3	Flaking	78	N	N	0	N	N	Additional Cracking, Chipping
260	1010	1	3	330		Office 330	W4	Cracking	6	N	N	0	N	N	
261	1010	1	3	344		Office 344	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
262	1010	1	3	344		Office 344	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
263	1010	1	3	344		Office 344	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
264	1010	1	3	344		Office 344	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
265	1010	1	3	344		Office 344	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
266	1010	1	3	344		Office 344	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
267	1010	1	3	3G		Office 3G (326)	Floor	Debris	0	Y	Y - @ Corners	3	N	N	
268	1010	1	3	3G		Office 3G (326)	W1	Flaking	20	N	N	0	Y - 28 SF Desks, Bookcases	N	Additional Chipping
269	1010	1	3	3G		Office 3G (326)	W2	Cracking	3	N	N	0	Y - 80 SF Cabinets	N	
270	1010	1	3	3G		Office 3G (326)	W3	Flaking	160	N	N	0	Y - 80 SF Bookcases, Books	N	Additional Cracking, Gouges
271	1010	1	3	3G		Office 3G (326)	W4	Flaking	36	N	N	0	Y - 18 SF Desks, Bookcases	N	Additional Chipping
272	1010	1	3	322		Prep Room 322	W2	Cracking	4	N	N	0	N	N	2 Locations; Cracking @ Pipe & Wall
273	1010	1	3	322		Prep Room 322	W3	Flaking	14	N	N	0	N	N	Additional Cracking
274	1010	1	3	322		Prep Room 322	W4	Cracking	10	N	N	0	N	N	
275	1010	1	3	323		Prep Room 323	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Cabinets, Boxes	N	Inspection Needed
276	1010	1	3	323		Prep Room 323	W2	Partially Inaccessible	0	N	N	0	Y - 80 SF Boxes, Contents	N	Inspection Needed
277	1010	1	3	323		Prep Room 323	W3	Flaking	1	N	Y - On Window Sill	1	N	N	
278	1010	1	3	323		Prep Room 323	W4	Partially Inaccessible	0	N	N	0	Y - 100 SF Boxes, Contents	N	Inspection Needed
279	1010	1	3	306A		ROTC Storage on corridor B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
280	1010	1	3	306A		ROTC Storage on corridor B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
281	1010	1	3	306A		ROTC Storage on corridor B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
282	1010	1	3	306A		ROTC Storage on corridor B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
283	1010	1	3	306A		ROTC Storage on corridor B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
284	1010	1	3	306A		ROTC Storage on corridor B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
285	1010	1	3	Teach Room		Staff Restroom	Ceiling	Flaking	32	Y	N	0	N	Y - 32	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
286	1010	1	3	Teach Room		Staff Restroom	W1	Flaking	9	N	N	0	N	N	Additional Cracking
287	1010	1	3	Teach Room		Staff Restroom	W2	Flaking	36	N	N	0	N	N	Additional Cracking
288	1010	1	3	Teach Room		Staff Restroom	W3	Flaking	56	N	N	0	N	N	Additional Cracking
289	1010	1	3	Teach Room		Staff Restroom	W4	Cracking	12	N	N	0	N	N	
290	1010	1	3	S-06		Stairwell A adjacent to Room 341	Ceiling	Chipping	3	N	N	0	N	N	
291	1010	1	3	S-06		Stairwell A adjacent to Room 341	W1	Cracking	6	N	N	0	N	N	Additional Chipping
292	1010	1	3	S-06		Stairwell A adjacent to Room 341	W2	Cracking	4	N	N	0	N	N	
293	1010	1	3	S-06		Stairwell A adjacent to Room 341	W3	Cracking	10	N	N	0	N	N	Additional Chipping
294	1010	1	3	S-06		Stairwell A adjacent to Room 341	W4	Chipping	3	N	N	0	N	N	
295	1010	1	3	S-01		Stairwell adjacent to Room 301	W1	Chipping	2	N	N	0	N	N	
296	1010	1	3	S-01		Stairwell adjacent to Room 301	W3	Flaking	20	Y	N	0	N	Y - 4 SF	Additional Efflorescence, Cracking
297	1010	1	3	S-01		Stairwell adjacent to Room 301	W4	Flaking	3	N	N	0	N	N	
298	1010	1	3	S- 03		Stairwell adjacent to Room 317	Ceiling	Cracking	100	N	N	0	N	N	
299	1010	1	3	S- 03		Stairwell adjacent to Room 317	W1	Cracking	90	N	N	0	N	N	
300	1010	1	3	S- 03		Stairwell adjacent to Room 317	W2	Cracking	60	N	N	0	N	N	
301	1010	1	3	S- 03		Stairwell adjacent to Room 317	W3	Cracking	80	N	N	0	N	N	
302	1010	1	3	S- 03		Stairwell adjacent to Room 317	W4	Cracking	40	N	N	0	N	N	
303	1010	1	3	S- 05		Stairwell adjacent to Room 331	Ceiling	Flaking	210	Y	N	0	N	Y - 100 SF	Additional Efflorescence
304	1010	1	3	S- 05		Stairwell adjacent to Room 331	Floor	Debris	0	N	Y - Entire Floor	80	N	N	
305	1010	1	3	S- 05		Stairwell adjacent to Room 331	W1	Flaking	60	Y	Y - On Door	21	N	Y - 20 SF	Additional Efflorescence
306	1010	1	3	S- 05		Stairwell adjacent to Room 331	W2	Flaking	140	Y	N	0	N	Y - 80 SF	Additional Efflorescence
307	1010	1	3	S- 05		Stairwell adjacent to Room 331	W3	Flaking	90	Y	N	0	N	Y - 40 SF	Additional Efflorescence
308	1010	1	3	S- 05		Stairwell adjacent to Room 331	W4	Flaking	180	Y	N	0	N	Y - 80 SF	Additional Efflorescence
309	1010	1	3	S-02		Stairwell B adjacent to Room 324	Floor	Chipping	6	N	N	0	N	N	
310	1010	1	3	S-02		Stairwell B adjacent to Room 324	W1	Cracking	20	N	N	0	N	N	
311	1010	1	3	S-02		Stairwell B adjacent to Room 324	W2	Cracking	8	N	N	0	N	N	
312	1010	1	3	S-02		Stairwell B adjacent to Room 324	W3	Flaking	45	N	N	0	N	N	
313	1010	1	3	S-02		Stairwell B adjacent to Room 324	W4	Flaking	16	N	N	0	N	N	
314	1010	1	3	3E		Storage 3E	Ceiling	Cracking	18	N	N	0	N	N	
315	1010	1	3	3E		Storage 3E	Floor	Debris	0	N	Y - @ Perimeter	24	N	N	
316	1010	1	3	3E		Storage 3E	W1	Flaking	50	N	Y - On Shelves	12	Y - 70 SF Boxes	N	Additional Cracking
317	1010	1	3	3E		Storage 3E	W2	Cracking	5	N	N	0	Y - 72 SF Boxes	Y - 1 SF	Additional Chipping

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
318	1010	1	3	3E		Storage 3E	W3	Cracking	8	N	Y - On Shelves	12	Y - 220 SF Boxes, Contents	N	
319	1010	1	3	3E		Storage 3E	W4	Cracking	48	N	N	0	Y - 96 SF Boxes, Contents	N	
320	1010	1	3	322A		Storage Closet in Prep Room 322 Adj. to 320	Ceiling	Flaking	8	N	N	0	N	N	
321	1010	1	3	322A		Storage Closet in Prep Room 322 Adj. to 320	W1	Flaking	2	N	N	0	N	N	
322	1010	1	3	322A		Storage Closet in Prep Room 322 Adj. to 320	W4	Flaking	6	N	N	0	N	N	Additional Cracking
323	1010	1	3	322B		Storage Closet in Prep Room 322 Adj. to 324	Ceiling	Cracking	3	N	N	0	N	N	
324	1010	1	3	322B		Storage Closet in Prep Room 322 Adj. to 324	W1	Cracking	3	N	N	0	N	N	
325	1010	1	3	322B		Storage Closet in Prep Room 322 Adj. to 324	W2	Cracking	2	N	N	0	N	N	
326	1010	1	3	322B		Storage Closet in Prep Room 322 Adj. to 324	W3	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Chemicals	N	Inspection Needed
327	1010	1	3	322B		Storage Closet in Prep Room 322 Adj. to 324	W4	Partially Inaccessible	0	N	N	0	Y - 14 SF Shelves, Chemicals	N	Inspection Needed
328	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
329	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
330	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
331	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
332	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
333	1010	1	3	323B		Storage Closet in Prep Room 323 Adj. to 321	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
334	1010	1	3	323A		Storage Closet in Prep Room 323 Adj. to 325	W1	Cracking	1	N	N	0	N	N	
335	1010	1	3	323A		Storage Closet in Prep Room 323 Adj. to 325	W2	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Needed
336	1010	1	3	323A		Storage Closet in Prep Room 323 Adj. to 325	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Needed

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
337	1010	1	3	323A		Storage Closet in Prep Room 323 Adj. to 325	W4	Partially Inaccessible	0	N	N	0	Y - 15 SF Contents	N	Inspection Needed
338	1010	1	3	Girl's Toilet		Women's Restroom	W4	Flaking	8	N	N	0	N	N	
339	1010	1	2	220C		Auditorium Balcony	Ceiling	Flaking	30	Y	N	0	N	Y - 20 SF	Additional Efflorescence
340	1010	1	2	220C		Auditorium Balcony	Floor	Debris	0	N	Y - Near Entrance	30	N	N	
341	1010	1	2	220C		Auditorium Balcony	W1	Chipping	12	N	N	0	N	N	
342	1010	1	2	220C		Auditorium Balcony	W2	Cracking	20	N	N	0	N	N	Additional Chipping
343	1010	1	2	220C		Auditorium Balcony	W3	Flaking	18	N	N	0	N	N	Additional Chipping
344	1010	1	2	H21		A-Wing Hallway	W2	Cracking	40	N	N	0	N	N	Additional Chipping; Damage on Wall & Lockers
345	1010	1	2	H21		A-Wing Hallway	W3	Chipping	4	N	N	0	N	N	
346	1010	1	2	H21		A-Wing Hallway	W4	Cracking	68	N	N	0	N	N	Additional Chipping; Damage on Wall & Lockers
347	1010	1	2	H22		B-Wing Hallway	W2	Cracking	18	N	N	0	N	N	Additional Chipping
348	1010	1	2	H22		B-Wing Hallway	W4	Cracking	14	N	N	0	N	N	Additional Chipping
349	1010	1	2	201		Classroom 201	Ceiling	Flaking	3	Y	N	0	N	N	Flaking @ Window Lintels; Suspended Ceiling; Water Stain on Ceiling Tile
350	1010	1	2	201		Classroom 201	W1	Cracking	10	N	N	0	Y - 60 SF Desks, File Cabinets, Posters	Y - 1 SF	Additional Chipping, Holes
351	1010	1	2	201		Classroom 201	W2	Flaking	12	N	N	0	N	N	
352	1010	1	2	201		Classroom 201	W3	Flaking	80	N	N	0	Y - 70 SF Cabinets, Desks	N	Additional Chipping
353	1010	1	2	202		Classroom 202	W1	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping
354	1010	1	2	202		Classroom 202	W2	Flaking	55	N	N	0	N	N	Additional Cracking, Chipping
355	1010	1	2	202		Classroom 202	W3	Flaking	110	N	N	0	N	Y - 2 SF	2 Locations; Additional Cracking, Chipping; Damage on Wall & Pipes
356	1010	1	2	202		Classroom 202	W4	Cracking	16	N	N	0	N	N	Additional Chipping
357	1010	1	2	203		Classroom 203	W1	Flaking	160	N	N	0	N	Y - 5 SF	Additional Cracking, Chipping
358	1010	1	2	203		Classroom 203	W2	Flaking	30	N	N	0	N	N	Additional Cracking
359	1010	1	2	203		Classroom 203	W3	Flaking	170	N	N	0	N	Y - 10 SF	Additional Cracking, Chipping, Holes
360	1010	1	2	203		Classroom 203	W4	Cracking	6	N	N	0	N	N	
361	1010	1	2	204		Classroom 204	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
362	1010	1	2	204		Classroom 204	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
363	1010	1	2	204		Classroom 204	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock on Door
364	1010	1	2	204		Classroom 204	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
365	1010	1	2	204		Classroom 204	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
366	1010	1	2	204		Classroom 204	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
367	1010	1	2	205		Classroom 205	W1	Flaking	128	N	N	0	N	N	Additional Cracking, Chipping
368	1010	1	2	205		Classroom 205	W2	Cracking	7	N	N	0	N	N	Additional Chipping
369	1010	1	2	205		Classroom 205	W3	Flaking	280	N	N	0	N	N	Additional Chipping
370	1010	1	2	205		Classroom 205	W4	Flaking	24	N	N	0	N	N	
371	1010	1	2	207		Classroom 207	W1	Flaking	110	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
372	1010	1	2	207		Classroom 207	W2	Flaking	14	N	N	0	N	N	Additional Cracking
373	1010	1	2	207		Classroom 207	W3	Flaking	180	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
374	1010	1	2	207		Classroom 207	W4	Flaking	46	N	N	0	N	Y - 1 SF	
375	1010	1	2	208		Classroom 208	W1	Flaking	22	N	N	0	N	N	Additional Cracking, Chipping
376	1010	1	2	208		Classroom 208	W2	Flaking	64	N	N	0	N	N	Additional Chipping
377	1010	1	2	208		Classroom 208	W3	Flaking	190	N	N	0	N	N	Additional Chipping
378	1010	1	2	208		Classroom 208	W4	Cracking	16	N	N	0	N	N	Additional Chipping

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
379	1010	1	2	210		Classroom 210	W1	Flaking	24	N	N	0	N	N	Additional Chipping
380	1010	1	2	210		Classroom 210	W2	Flaking	40	N	N	0	N	N	Additional Chipping
381	1010	1	2	210		Classroom 210	W3	Flaking	90	N	N	0	N	N	Additional Chipping
382	1010	1	2	210		Classroom 210	W4	Flaking	52	N	N	0	N	N	Additional Cracking, Chipping
383	1010	1	2	214		Classroom 214	W1	Flaking	8	N	N	0	Y - 26 SF Posters	Y - 2 SF	Additional Cracking, Chipping
384	1010	1	2	214		Classroom 214	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Posters	N	Inspection Needed
385	1010	1	2	214		Classroom 214	W3	Flaking	32	N	N	0	N	Y - 3 SF	Additional Cracking, Chipping
386	1010	1	2	214		Classroom 214	W4	Chipping	20	N	N	0	N	N	
387	1010	1	2	215		Classroom 215	Ceiling	Flaking	8	N	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling
388	1010	1	2	215		Classroom 215	W1	Flaking	40	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
389	1010	1	2	215		Classroom 215	W2	Chipping	40	N	N	0	N	N	
390	1010	1	2	215		Classroom 215	W3	Flaking	24	N	N	0	N	N	Additional Chipping
391	1010	1	2	215		Classroom 215	W4	Flaking	8	N	N	0	N	N	Additional Chipping
392	1010	1	2	216		Classroom 216	Ceiling	Flaking	4	N	N	0	N	N	Flaking @ Window Lintels; Suspended Ceiling
393	1010	1	2	216		Classroom 216	W1	Flaking	96	Y	N	0	N	Y - 1 SF	Additional Chipping
394	1010	1	2	216		Classroom 216	W2	Flaking	52	N	N	0	N	N	Additional Chipping
395	1010	1	2	216		Classroom 216	W3	Flaking	38	N	N	0	N	N	Additional Chipping
396	1010	1	2	216		Classroom 216	W4	Flaking	110	N	N	0	N	N	Additional Cracking, Chipping
397	1010	1	2	217		Classroom 217	Ceiling	Flaking	2	N	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling
398	1010	1	2	217		Classroom 217	W1	Flaking	56	N	N	0	N	N	Additional Cracking, Chipping
399	1010	1	2	217		Classroom 217	W2	Chipping	18	N	N	0	N	N	
400	1010	1	2	217		Classroom 217	W3	Flaking	120	N	Y - On Window Sills	2	N	Y - 2 SF	Additional Cracking, Chipping
401	1010	1	2	217		Classroom 217	W4	Flaking	24	N	N	0	N	N	Additional Chipping, Holes
402	1010	1	2	218		Classroom 218	W1	Flaking	45	Y	N	0	N	Y - 1 SF	Additional Cracking, Chipping
403	1010	1	2	218		Classroom 218	W2	Flaking	24	N	N	0	N	N	Additional Cracking
404	1010	1	2	218		Classroom 218	W3	Flaking	130	N	Y - On Window Sill	2	N	N	Additional Cracking, Chipping, Holes
405	1010	1	2	218		Classroom 218	W4	Chipping	5	N	N	0	N	N	
406	1010	1	2	221		Classroom 221	W1	Partially Inaccessible	0	N	N	0	Y - 66 SF Desks, Posters	N	Inspection Needed
407	1010	1	2	221		Classroom 221	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Desks, Posters	N	Inspection Needed
408	1010	1	2	221		Classroom 221	W3	Partially Inaccessible	0	N	N	0	Y - 66 SF Desks, Posters	N	Inspection Needed
409	1010	1	2	221		Classroom 221	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Desks, Posters	N	Inspection Needed
410	1010	1	2	222		Classroom 222	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
411	1010	1	2	222		Classroom 222	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
412	1010	1	2	222		Classroom 222	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
413	1010	1	2	222		Classroom 222	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
414	1010	1	2	222		Classroom 222	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
415	1010	1	2	222		Classroom 222	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
416	1010	1	2	223		Classroom 223	Floor	Debris	0	N	Y - @ Wall 3	1	N	N	
417	1010	1	2	223		Classroom 223	W1	Flaking	48	N	N	0	N	N	Additional Chipping
418	1010	1	2	223		Classroom 223	W2	Flaking	32	N	N	0	N	Y - 1 SF	Additional Cracking
419	1010	1	2	223		Classroom 223	W3	Flaking	64	N	N	0	N	N	Additional Cracking, Chipping
420	1010	1	2	223		Classroom 223	W4	Flaking	24	N	N	0	N	N	Suspended Ceiling; Water Stain on Ceiling Tile
421	1010	1	2	224		Classroom 224	Ceiling	Flaking	4	N	N	0	N	N	Flaking @ Window Lintel
422	1010	1	2	224		Classroom 224	Floor	Debris	0	N	Y - Beneath Windows & Pipe	3	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
423	1010	1	2	224		Classroom 224	W1	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
424	1010	1	2	224		Classroom 224	W2	Flaking	8	N	N	0	N	N	Additional Chipping
425	1010	1	2	224		Classroom 224	W3	Flaking	120	Y	N	0	N	Y - 21 SF	Additional Cracking, Chipping
426	1010	1	2	224		Classroom 224	W4	Cracking	10	N	N	0	N	N	Additional Chipping, Holes
427	1010	1	2	225		Classroom 225	Floor	Debris	0	N	Y - @ Wall 3	1	N	N	
428	1010	1	2	225		Classroom 225	W1	Flaking	10	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
429	1010	1	2	225		Classroom 225	W2	Flaking	7	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
430	1010	1	2	225		Classroom 225	W3	Flaking	110	Y	N	0	N	Y - 12 SF	Additional Efflorescence
431	1010	1	2	225		Classroom 225	W4	Flaking	8	N	N	0	N	N	Additional Cracking, Chipping
432	1010	1	2	226		Classroom 226	W1	Flaking	6	N	N	0	Y - 60 SF Posters	N	Additional Cracking, Chipping
433	1010	1	2	226		Classroom 226	W2	Partially Inaccessible	0	N	N	0	Y - 88 SF Desks, Posters	N	Inspection Needed
434	1010	1	2	226		Classroom 226	W3	Flaking	22	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Wall & Pipes
435	1010	1	2	227		Classroom 227	W1	Flaking	9	N	N	0	Y - 20 SF Posters	N	Additional Cracking, Chipping
436	1010	1	2	227		Classroom 227	W2	Partially Inaccessible	0	N	N	0	N	N	Inspection Needed
437	1010	1	2	227		Classroom 227	W3	Flaking	48	N	N	0	N	N	2 Locations; Flaking on Pipe & Wall
438	1010	1	2	227		Classroom 227	W4	Flaking	6	N	N	0	N	N	2 Locations; Additional Chipping
439	1010	1	2	228		Classroom 228	Ceiling	Flaking	8	Y	N	0	N	Y - 8 SF	Additional Efflorescence; Damage @ Window Lintels; Suspended Ceiling
440	1010	1	2	228		Classroom 228	Floor	Debris	0	N	Y - Beneath Windows	6	N	N	
441	1010	1	2	228		Classroom 228	W1	Flaking	56	Y	N	0	N	Y - 4 SF	Additional Efflorescence
442	1010	1	2	228		Classroom 228	W3	Flaking	125	N	Y - On Table & Window Sills	3	N	N	Additional Cracking, Chipping
443	1010	1	2	229		Classroom 229	W1	Flaking	36	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
444	1010	1	2	229		Classroom 229	W2	Cracking	4	N	N	0	N	N	Additional Chipping
445	1010	1	2	229		Classroom 229	W3	Flaking	110	N	N	0	N	N	Additional Cracking
446	1010	1	2	229		Classroom 229	W4	Flaking	32	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping
447	1010	1	2	230		Classroom 230	Ceiling	Flaking	5	Y	N	0	N	Y - 5 SF	Additional Efflorescence; Suspended Ceiling; Damage @ Window Lintels
448	1010	1	2	230		Classroom 230	Floor	Debris	0	N	Y - Beneath Windows	18	N	N	
449	1010	1	2	230		Classroom 230	W1	Holes	1	N	N	0	Y - 30 SF Tables, Computers	Y - 1 SF	
450	1010	1	2	230		Classroom 230	W3	Flaking	14	N	Y - On Window Sills	5	N	Y - 1 SF	
451	1010	1	2	232		Classroom 232	Ceiling	Flaking	2	Y	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling; Water Stain on Ceiling Tile
452	1010	1	2	232		Classroom 232	Floor	Debris	0	N	Y - Beneath Windows	2	N	N	
453	1010	1	2	232		Classroom 232	W1	Flaking	125	N	N	0	N	Y - 1 SF	Additional Cracking, Chipping, Holes
454	1010	1	2	232		Classroom 232	W2	Flaking	9	N	N	0	N	N	Additional Chipping
455	1010	1	2	232		Classroom 232	W3	Flaking	72	Y	N	0	N	Y - 4 SF	2 Locations; Additional Efflorescence, Cracking; Damage on Pipes & Wall
456	1010	1	2	232		Classroom 232	W4	Flaking	84	N	N	0	N	N	Additional Chipping
457	1010	1	2	211A		Gym Office 211	Ceiling	Flaking	2	N	N	0	N	N	Suspended Ceiling

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
458	1010	1	2	211A		Gym Office 211	W1	Cracking	3	N	N	0	Y - 24 SF Desk, Copier	N	Additional Chipping
459	1010	1	2	211A		Gym Office 211	W2	Cracking	5	N	N	0	N	N	Additional Chipping
460	1010	1	2	211A		Gym Office 211	W3	Flaking	6	N	N	0	N	N	Additional Chipping
461	1010	1	2	211A		Gym Office 211	W4	Cracking	3	N	N	0	N	N	
462	1010	1	2	211C		Gym Office 211 Closet	Ceiling	Cracking	16	N	N	0	N	N	
463	1010	1	2	211C		Gym Office 211 Closet	W1	Flaking	79	N	N	0	N	N	Additional Cracking
464	1010	1	2	211C		Gym Office 211 Closet	W2	Flaking	68	N	N	0	N	N	Additional Cracking
465	1010	1	2	211C		Gym Office 211 Closet	W3	Flaking	100	N	N	0	N	N	Additional Cracking
466	1010	1	2	211C		Gym Office 211 Closet	W4	Flaking	80	N	N	0	N	N	Additional Cracking
467	1010	1	2	236		Gym Office 236	W1	Chipping	1	N	N	0	N	N	
468	1010	1	2	236		Gym Office 236	W2	Flaking	3	N	N	0	N	N	Additional Chipping
469	1010	1	2	236		Gym Office 236	W3	Chipping	7	N	N	0	N	N	Chipping on Pipe & Wall
470	1010	1	2	236A		Gym Office 236A	W1	Flaking	2	N	N	0	N	N	2 Locations; Additional Chipping; Damage on Wall & Pipe
471	1010	1	2	236A		Gym Office 236A	W3	Chipping	2	N	N	0	N	N	
472	1010	1	2	236A		Gym Office 236A	W4	Holes	1	N	N	0	N	N	
473	1010	1	2	H23		Hallway 201-210A	W2	Cracking	10	N	N	0	N	N	Additional Chipping
474	1010	1	2	H23		Hallway 201-210A	W3	Chipping	2	N	N	0	N	N	
475	1010	1	2	H23		Hallway 201-210A	W4	Cracking	16	N	N	0	N	N	Additional Chipping
476	1010	1	2	H24		Hallway 211-236	W1	Flaking	72	N	N	0	N	N	Additional Cracking, Chipping; Damage Includes Wall & Lockers
477	1010	1	2	H24		Hallway 211-236	W3	Cracking	50	N	N	0	N	N	Additional Cracking
478	1010	1	2	H25		Hallway adjacent to 211B	Ceiling	Efflorescence	200	Y	N	0	N	N	
479	1010	1	2	H25		Hallway adjacent to 211B	Floor	Chipping	24	N	N	0	N	N	Chipping @ Ramp
480	1010	1	2	H25		Hallway adjacent to 211B	W1	Cracking	4	N	N	0	N	N	
481	1010	1	2	H25		Hallway adjacent to 211B	W3	Flaking	20	N	N	0	N	N	
482	1010	1	2	H25		Hallway adjacent to 211B	W4	Flaking	84	N	N	0	N	N	
483	1010	1	2	213		Library	W1	Flaking	28	N	N	0	N	N	Additional Chipping
484	1010	1	2	213		Library	W2	Cracking	1	N	N	0	N	N	Chipping on Pipe
485	1010	1	2	213		Library	W3	Holes	1	N	N	0	N	N	
486	1010	1	2	213		Library	W4	Flaking	3	N	N	0	N	N	Additional Chipping; Damage on Pipes
487	1010	1	2	213A/213B		Library Office	W1	Flaking	4	N	N	0	N	N	Additional Cracking
488	1010	1	2	213A/213B		Library Office	W2	Efflorescence	8	Y	N	0	Y - 32 SF Cabinets, Contents	Y - 8 SF	Additional Cracking
489	1010	1	2	213A/213B		Library Office	W3	Efflorescence	1	Y	N	0	N	Y - 1 SF	
490	1010	1	2	213A/213B		Library Office	W4	Partially Inaccessible	0	N	N	0	Y - 160 SF Cabinets, Contents	N	Inspection Needed
491	1010	1	2	2G		Main Hallway Book Storage Room 2-G	W1	Cracking	2	N	N	0	N	N	
492	1010	1	2	2G		Main Hallway Book Storage Room 2-G	W2	Flaking	48	N	N	0	Y - 80 SF Books	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
493	1010	1	2	2G		Main Hallway Book Storage Room 2-G	W3	Flaking	24	N	N	0	Y - 72 SF Books	N	
494	1010	1	2	2G		Main Hallway Book Storage Room 2-G	W4	Cracking	18	N	N	0	Y - 110 SF Books	N	
495	1010	1	2	2H		Main Hallway Book Storage Room 2-H	Ceiling	Cracking	12	N	N	0	N	N	
496	1010	1	2	2H		Main Hallway Book Storage Room 2-H	W1	Cracking	10	N	N	0	Y - 48 SF Books	Y - 2 SF	
497	1010	1	2	2H		Main Hallway Book Storage Room 2-H	W2	Partially Inaccessible	0	N	N	0	Y - 120 SF Books	N	Inspection Needed
498	1010	1	2	2H		Main Hallway Book Storage Room 2-H	W3	Partially Inaccessible	0	N	N	0	Y - 90 SF Books	N	Inspection Needed
499	1010	1	2	2H		Main Hallway Book Storage Room 2-H	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Books	N	Inspection Needed
500	1010	1	2	2K		Main Hallway Book Storage Room 2-K	W1	Flaking	40	N	N	0	N	N	
501	1010	1	2	2K		Main Hallway Book Storage Room 2-K	W2	Partially Inaccessible	0	N	N	0	Y - 90 SF Books	N	Inspection Needed
502	1010	1	2	2K		Main Hallway Book Storage Room 2-K	W3	Cracking	8	N	N	0	Y - 100 SF Books	N	
503	1010	1	2	2K		Main Hallway Book Storage Room 2-K	W4	Flaking	80	N	N	0	Y - 80 SF Books	Y - 4 SF	
504	1010	1	2	2E		Main Hallway Service Closet 2-E	Ceiling	Inaccessible	0	N	N	0	N	N	Inspection Needed
505	1010	1	2	2E		Main Hallway Service Closet 2-E	Floor	Inaccessible	0	N	N	0	N	N	Inspection Needed
506	1010	1	2	2E		Main Hallway Service Closet 2-E	W1	Inaccessible	0	N	N	0	N	N	No Key
507	1010	1	2	2E		Main Hallway Service Closet 2-E	W2	Inaccessible	0	N	N	0	N	N	Inspection Needed
508	1010	1	2	2E		Main Hallway Service Closet 2-E	W3	Inaccessible	0	N	N	0	N	N	Inspection Needed
509	1010	1	2	2E		Main Hallway Service Closet 2-E	W4	Inaccessible	0	N	N	0	N	N	Inspection Needed
510	1010	1	2	2L		Main Hallway Service Closet 2-L	Ceiling	Cracking	3	N	N	0	N	Y - 1 SF	Additional Holes
511	1010	1	2	2F		Main Hallway Service Closet 2-L	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
512	1010	1	2	2F		Main Hallway Service Closet 2-L	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
513	1010	1	2	2F		Main Hallway Service Closet 2-L	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
514	1010	1	2	2L		Main Hallway Service Closet 2-L	W2	Flaking	12	N	N	0	N	N	
515	1010	1	2	2F		Main Hallway Service Closet 2-L	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
516	1010	1	2	2L		Main Hallway Service Closet 2-L	W3	Flaking	18	N	N	0	N	N	Additional Holes
517	1010	1	2	2F		Main Hallway Service Closet 2-L	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
518	1010	1	2	2L		Main Hallway Service Closet 2-L	W4	Flaking	36	N	N	0	N	N	
519	1010	1	2	2F		Main Hallway Service Closet 2-L	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
520	1010	1	2	217B		Men's Restroom adjacent to 220A	Ceiling	Flaking	10	N	N	0	N	N	
521	1010	1	2	217B		Men's Restroom adjacent to 220A	W1	Flaking	6	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
522	1010	1	2	217B		Men's Restroom adjacent to 220A	W2	Flaking	2	N	N	0	N	N	
523	1010	1	2	217B		Men's Restroom adjacent to 220A	W3	Flaking	3	N	N	0	N	N	
524	1010	1	2	217B		Men's Restroom adjacent to 220A	W4	Flaking	3	N	N	0	N	N	
525	1010	1	2	220A		Office 200A	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
526	1010	1	2	220A		Office 200A	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
527	1010	1	2	220A		Office 200A	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
528	1010	1	2	220A		Office 200A	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
529	1010	1	2	220A		Office 200A	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
530	1010	1	2	220A		Office 200A	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
531	1010	1	2	209		Office 209	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
532	1010	1	2	209		Office 209	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
533	1010	1	2	209		Office 209	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
534	1010	1	2	209		Office 209	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
535	1010	1	2	209		Office 209	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
536	1010	1	2	209		Office 209	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
537	1010	1	2	210A		Office 210A	Ceiling	Efflorescence	16	Y	N	0	N	Y - 16 SF	Suspended Ceiling; Missing Ceiling Tiles
538	1010	1	2	210A		Office 210A	W1	Flaking	20	Y	N	0	N	Y - 8 SF	Additional Efflorescence, Chipping
539	1010	1	2	210A		Office 210A	W2	Cracking	20	N	N	0	N	N	Additional Chipping
540	1010	1	2	210A		Office 210A	W3	Efflorescence	6	Y	N	0	N	Y - 6 SF	Additional Cracking
541	1010	1	2	210A		Office 210A	W4	Efflorescence	16	Y	N	0	Y - 60 SF Books	Y - 16 SF	
542	1010	1	2	211		Office 211	W1	Cracking	8	N	N	0	N	Y - 1 SF	
543	1010	1	2	211		Office 211	W2	Flaking	32	N	N	0	N	N	Additional Chipping
544	1010	1	2	211		Office 211	W3	Cracking	4	N	N	0	Y - 20 SF Cabinets	N	Additional Chipping
545	1010	1	2	211		Office 211	W4	Flaking	15	N	N	0	Y - 18 SF Desk, Cabinets	N	Additional Chipping
546	1010	1	2	211B		Office 211B/212	W1	Flaking	5	N	N	0	N	N	
547	1010	1	2	211B		Office 211B/212	W2	Flaking	6	N	N	0	N	N	
548	1010	1	2	211B		Office 211B/212	W3	Flaking	8	N	N	0	N	N	
549	1010	1	2	211B		Office 211B/212	W4	Flaking	4	N	N	0	N	N	
550	1010	1	2	219		Office 219	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
551	1010	1	2	219		Office 219	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
552	1010	1	2	219		Office 219	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
553	1010	1	2	219		Office 219	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
554	1010	1	2	219		Office 219	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
555	1010	1	2	219		Office 219	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
556	1010	1	2	231		Office 231	W1	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Needed
557	1010	1	2	231		Office 231	W2	Chipping	40	N	N	0	N	N	
558	1010	1	2	234		Office 234	W2	Cracking	2	N	N	0	Y - 20 SF Desk, Fridge	N	
559	1010	1	2	234		Office 234	W3	Chipping	2	N	N	0	N	N	Additional Gouges
560	1010	1	2	234		Office 234	W4	Holes	1	N	N	0	Y - 30 SF Contents	N	
561	1010	1	2	212		Office 238 Adjacent to Projector Room 2C	W2	Efflorescence	2	Y	Y - On Outlet	1	N	Y - 2 SF	
562	1010	1	2	212		Office 238 Adjacent to Projector Room 2C	W3	Partially Inaccessible	0	N	N	0	Y - 80 SF Boxes	N	Inspection Needed

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
563	1010	1	2	212		Office 238 Adjacent to Projector Room 2C	W4	Cracking	20	N	N	0	N	N	Additional Chipping
564	1010	1	2	2C		Projector Room #1	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
565	1010	1	2	2C		Projector Room #1	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
566	1010	1	2	2C		Projector Room #1	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
567	1010	1	2	2C		Projector Room #1	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
568	1010	1	2	2C		Projector Room #1	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
569	1010	1	2	2C		Projector Room #1	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
570	1010	1	2	S23		Stairwell A adjacent to Room 234	W1	Flaking	28	N	N	0	N	N	
571	1010	1	2	S23		Stairwell A adjacent to Room 234	W2	Flaking	20	N	N	0	N	N	
572	1010	1	2	S23		Stairwell A adjacent to Room 234	W3	Flaking	26	N	N	0	N	N	
573	1010	1	2	S28		Stairwell adjacent to 201	Ceiling	Cracking	6	N	N	0	N	N	
574	1010	1	2	S28		Stairwell adjacent to 201	W1	Chipping	4	N	N	0	N	N	
575	1010	1	2	S28		Stairwell adjacent to 201	W2	Cracking	25	N	N	0	N	N	Additional Chipping
576	1010	1	2	S28		Stairwell adjacent to 201	W3	Flaking	8	N	N	0	N	N	Additional Chipping
577	1010	1	2	S28		Stairwell adjacent to 201	W4	Flaking	16	N	N	0	N	N	Additional Chipping
578	1010	1	2	S26		Stairwell adjacent to 211B	Ceiling	Cracking	2	N	N	0	N	N	
579	1010	1	2	S26		Stairwell adjacent to 211B	W1	Flaking	7	N	N	0	N	N	
580	1010	1	2	S26		Stairwell adjacent to 211B	W2	Cracking	10	N	N	0	N	N	
581	1010	1	2	S26		Stairwell adjacent to 211B	W3	Flaking	4	N	N	0	N	N	
582	1010	1	2	S26		Stairwell adjacent to 211B	W4	Cracking	16	N	N	0	N	N	
583	1010	1	2	S23		Stairwell adjacent to Room 222	W1	Flaking	28	N	N	0	N	N	
584	1010	1	2	S23		Stairwell adjacent to Room 222	W2	Flaking	20	N	N	0	N	N	
585	1010	1	2	S23		Stairwell adjacent to Room 222	W3	Flaking	26	N	N	0	N	N	
586	1010	1	2	S22		Stairwell B adjacent to Room 218	W1	Cracking	13	N	N	0	N	N	
587	1010	1	2	S22		Stairwell B adjacent to Room 218	W2	Cracking	8	N	N	0	N	N	
588	1010	1	2	S22		Stairwell B adjacent to Room 218	W3	Cracking	14	N	N	0	N	N	
589	1010	1	2	S29		Stairwell behind Library	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
590	1010	1	2	S29		Stairwell behind Library	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
591	1010	1	2	S29		Stairwell behind Library	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Stairwell Blocked by Bookcases
592	1010	1	2	S29		Stairwell behind Library	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
593	1010	1	2	S29		Stairwell behind Library	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
594	1010	1	2	S29		Stairwell behind Library	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
595	1010	1	2	S24		Stairwell C adjacent to Elevator	W1	Cracking	10	N	N	0	N	N	
596	1010	1	2	S24		Stairwell C adjacent to Elevator	W3	Cracking	8	N	N	0	N	N	
597	1010	1	2	S24		Stairwell C adjacent to Elevator	W4	Flaking	5	N	N	0	N	N	
598	1010	1	2	220B		Weight room	Ceiling	Flaking	22	Y	N	0	N	Y - 6 SF	Additional Efflorescence; Suspended Ceiling; Damage Includes Metal Vents
599	1010	1	2	220B		Weight room	Floor	Debris	0	N	Y - Throughout	30	N	N	
600	1010	1	2	220B		Weight room	W1	Cracking	3	N	N	0	N	N	
601	1010	1	2	220B		Weight room	W2	Flaking	120	N	N	0	N	N	Additional Chipping
602	1010	1	2	220B		Weight room	W3	Flaking	24	N	N	0	N	N	Additional Chipping
603	1010	1	2	220B		Weight room	W4	Flaking	210	N	N	0	N	N	Additional Chipping
604	1010	1	2	217A		Women's Restroom adjacent to 209	Ceiling	Flaking	64	Y	N	0	N	Y - 10 SF	Additional Cracking
605	1010	1	2	217A		Women's Restroom adjacent to 209	W1	Flaking	8	N	N	0	N	N	
606	1010	1	2	217A		Women's Restroom adjacent to 209	W2	Flaking	48	N	N	0	N	N	Additional Cracking
607	1010	1	2	217A		Women's Restroom adjacent to 209	W3	Flaking	40	N	N	0	N	N	Additional Cracking
608	1010	1	2	217A		Women's Restroom adjacent to 209	W4	Flaking	20	Y	N	0	N	Y - 1 SF	Additional Efflorescence
609	1010	1	1	136		Auditorium	Ceiling	Partially Inaccessible	0	N	N	0	N	N	Inspection Needed
610	1010	1	1	136		Auditorium	Floor	Debris	0	N	Y - @ Perimeter	40	N	N	
611	1010	1	1	136		Auditorium	W1	Flaking	320	N	N	0	N	N	Additional Cracking; Damage on Window Frames & Wall
612	1010	1	1	136		Auditorium	W2	Flaking	30	N	N	0	N	N	Additional Cracking
613	1010	1	1	136		Auditorium	W3	Flaking	400	N	N	0	N	N	Additional Cracking
614	1010	1	1	136		Auditorium	W4	Cracking	20	N	N	0	N	N	
615	1010	1	1	H11		A-Wing Hallway 123-134	W1	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall Above Door & On Door
616	1010	1	1	H11		A-Wing Hallway 123-134	W2	Cracking	12	N	N	0	N	N	Additional Chipping
617	1010	1	1	H11		A-Wing Hallway 123-134	W4	Cracking	9	N	N	0	N	N	
618	1010	1	1	H15		Boys' Gym Hallway	W1	Chipping	2	N	N	0	N	N	Chipping @ Door
619	1010	1	1	H15		Boys' Gym Hallway	W2	Chipping	2	N	N	0	N	N	
620	1010	1	1	135		Boys' Gymnasium	Ceiling	Flaking	126	Y	N	0	N	N	Additional Efflorescence
621	1010	1	1	133A		Boys' Restroom	Ceiling	Flaking	148	Y	N	0	N	N	Additional Efflorescence
622	1010	1	1	133A		Boys' Restroom	W2	Flaking	8	N	N	0	N	N	Damage on Particle Board
623	1010	1	1	133A		Boys' Restroom	W3	Flaking	10	N	N	0	N	N	
624	1010	1	1	134F		Break Room Behind Main Office Restroom	Ceiling	Flaking	2	Y	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling; Water Stain on Ceiling Tile
625	1010	1	1	H12		B-Wing Hallway 111-121	W2	Cracking	12	N	N	0	N	N	Additional Chipping
626	1010	1	1	H12		B-Wing Hallway 111-121	W4	Cracking	16	N	N	0	N	N	Additional Chipping
627	1010	1	1	101		Classroom 101	Ceiling	Flaking	10	Y	N	0	N	N	Additional Efflorescence
628	1010	1	1	101		Classroom 101	Floor	Debris	0	N	Y - Beneath Windows	3	N	N	
629	1010	1	1	101		Classroom 101	W1	Chipping	3	N	N	0	N	N	2 Locations

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
630	1010	1	1	101		Classroom 101	W2	Partially Inaccessible	0	N	N	0	Y - 66 SF Cabinets, Bookcases	N	Inspection Needed
631	1010	1	1	101		Classroom 101	W3	Flaking	14	N	Y - On Window Sills 4 & 5	3	N	N	Flaking @ Wall & Radiator
632	1010	1	1	101		Classroom 101	W4	Chipping	1	N	N	0	N	N	
633	1010	1	1	102		Classroom 102	W1	Cracking	2	N	N	0	N	N	
634	1010	1	1	102		Classroom 102	W2	Flaking	2	N	N	0	N	N	
635	1010	1	1	102		Classroom 102	W3	Flaking	14	N	N	0	N	N	
636	1010	1	1	102		Classroom 102	W4	Chipping	3	N	N	0	N	N	Additional Holes
637	1010	1	1	103		Classroom 103	W3	Flaking	3	N	N	0	N	N	Additional Chippign; 2 Locations; Damage @ Window Sill & Wall
638	1010	1	1	106		Classroom 106	W1	Cracking	10	N	N	0	N	Y - 2 SF	Additional Chipping
639	1010	1	1	106		Classroom 106	W3	Flaking	5	N	N	0	N	N	Additional Chipping; Damage @ Wall & Pipes
640	1010	1	1	106		Classroom 106	W4	Chipping	2	N	N	0	N	N	Sheetrock Wall
641	1010	1	1	106		Classroom 106 Restroom	Ceiling	Flaking	3	N	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling
642	1010	1	1	106		Classroom 106 Restroom	Floor	Chipping	4	N	N	0	N	N	
643	1010	1	1	106		Classroom 106 Restroom	W1	Gouges	1	N	N	0	N	N	
644	1010	1	1	106		Classroom 106 Restroom	W3	Flaking	6	N	N	0	N	N	Additional Cracking, Chipping
645	1010	1	1	107		Classroom 107	W1	Chipping	2	N	N	0	N	N	Additional Gouges
646	1010	1	1	107		Classroom 107	W2	Chipping	4	N	N	0	N	N	
647	1010	1	1	107		Classroom 107	W3	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping; Damage @ Wall & Radiators
648	1010	1	1	108		Classroom 108	W1	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Inspection Needed
649	1010	1	1	108		Classroom 108	W2	Partially Inaccessible	0	N	N	0	Y - 32 SF Contents	N	Inspection Needed
650	1010	1	1	108		Classroom 108	W3	Chipping	9	N	N	0	N	N	Damage @ Radiators & Pipe
651	1010	1	1	111		Classroom 111	W1	Cracking	8	N	N	0	Y - 36 SF Cabinets	N	
652	1010	1	1	111		Classroom 111	W2	Partially Inaccessible	0	N	N	0	Y - 60 SF Cabinets	N	Inspection Needed
653	1010	1	1	111		Classroom 111	W3	Flaking	3	N	N	0	Y - 30 SF Cabinets	Y - 2 SF	Additional Cracking, Holes
654	1010	1	1	111		Classroom 111	W4	Flaking	6	N	N	0	N	N	
655	1010	1	1	112		Classroom 112	Ceiling	Flaking	4	N	N	0	N	N	Flaking @ Window Lintel; Suspended Ceiling
656	1010	1	1	112		Classroom 112	W1	Cracking	52	N	N	0	N	N	2 Locations; Additional Chipping; Damage @ Wall & Door
657	1010	1	1	112		Classroom 112	W2	Chipping	60	N	N	0	Y - 60 SF Piano, Bookcases, Desks	N	Additional Holes; Sheetrock Wall
658	1010	1	1	112		Classroom 112	W3	Flaking	92	N	N	0	Y - 40 SF Bookcases, Books, File Cabinets, Desks	N	Additional Cracking, Chipping, Holes; Damage @ Wall & Pipe
659	1010	1	1	112		Classroom 112	W4	Flaking	264	N	N	0	N	N	Additional Chipping; Sheetrock Wall

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
660	1010	1	1	113		Classroom 113	Floor	Debris	0	N	Y - Beneath Windows	4	N	N	
661	1010	1	1	113		Classroom 113	W1	Flaking	64	N	N	0	N	N	Additional Cracking, Chipping
662	1010	1	1	113		Classroom 113	W2	Chipping	2	N	N	0	N	N	2 Locations; Additional Holes
663	1010	1	1	113		Classroom 113	W3	Flaking	48	N	N	0	N	N	Additional Cracking
664	1010	1	1	113		Classroom 113	W4	Chipping	20	N	N	0	N	N	
665	1010	1	1	115		Classroom 115	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
666	1010	1	1	115		Classroom 115	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
667	1010	1	1	115		Classroom 115	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
668	1010	1	1	115		Classroom 115	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
669	1010	1	1	115		Classroom 115	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
670	1010	1	1	115		Classroom 115	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
671	1010	1	1	117		Classroom 117	W1	Flaking	36	N	N	0	N	N	Additional Cracking, Chipping
672	1010	1	1	117		Classroom 117	W2	Chipping	3	N	N	0	N	N	Additional Holes
673	1010	1	1	117		Classroom 117	W3	Flaking	27	N	N	0	Y - 12 SF File Cabinets	N	Additional Cracking, Chipping
674	1010	1	1	117		Classroom 117	W4	Chipping	4	N	N	0	N	N	Additional holes
675	1010	1	1	118		Classroom 118	Floor	Debris	0	N	Y - Beneath Windows	4	N	N	
676	1010	1	1	118		Classroom 118	W1	Flaking	18	N	N	0	Y - 24 SF Boxes	N	
677	1010	1	1	118		Classroom 118	W2	Cracking	8	N	N	0	N	N	Additional Cracking, Chipping
678	1010	1	1	118		Classroom 118	W3	Flaking	50	N	N	0	Y - 14 SF Cabinets	N	Additional Chipping
679	1010	1	1	118		Classroom 118	W4	Cracking	22	N	N	0	N	N	Suspended Ceiling
680	1010	1	1	119		Classroom 119	Ceiling	Flaking	8	N	N	0	N	N	Flaking @ Window Lintels; Suspended Ceiling
681	1010	1	1	119		Classroom 119	W1	Flaking	22	N	N	0	N	Y - 2 SF	Additional Cracking, Chipping
682	1010	1	1	119		Classroom 119	W2	Cracking	4	N	N	0	N	N	
683	1010	1	1	119		Classroom 119	W3	Flaking	14	N	Y - On Window Sill 3 & 4	2	N	N	Additional Cracking, Chipping
684	1010	1	1	119		Classroom 119	W4	Chipping	5	N	N	0	N	N	2 Locations; Additional Holes
685	1010	1	1	129		Classroom 120	W1	Flaking	44	N	N	0	N	N	Additional Cracking, Chipping
686	1010	1	1	129		Classroom 120	W2	Chipping	16	N	N	0	N	N	
687	1010	1	1	129		Classroom 120	W3	Flaking	100	N	N	0	N	N	3 Locations; Additional Cracking, Chipping; Damage on Wall, Pipe, Radiator Grille
688	1010	1	1	129		Classroom 120	W4	Chipping	4	N	N	0	N	N	
689	1010	1	1	134E		Closet adjacent to Main Office Powder Room	W1	Partially Inaccessible	0	N	N	0	Y - 16 SF Boxes	N	Inspection Needed
690	1010	1	1	134E		Closet adjacent to Main Office Powder Room	W2	Cracking	4	N	N	0	Y - 18 SF Boxes	N	
691	1010	1	1	134E		Closet adjacent to Main Office Powder Room	W3	Partially Inaccessible	0	N	N	0	Y - 12 SF Boxes	N	Inspection Needed
692	1010	1	1	134E		Closet adjacent to Main Office Powder Room	W4	Partially Inaccessible	0	N	N	0	N	N	Inspection Needed
693	1010	1	1	S16		Girls' Gym Stairs	Floor	Debris	0	N	Y	1	N	N	
694	1010	1	1	S16		Girls' Gym Stairs	W1	Cracking	2	N	N	0	N	N	
695	1010	1	1	S16		Girls' Gym Stairs	W2	Cracking	5	N	N	0	N	N	
696	1010	1	1	S16		Girls' Gym Stairs	W3	Flaking	6	N	N	0	N	Y - 1 SF	Additional Cracking
697	1010	1	1	S16		Girls' Gym Stairs	W4	Cracking	36	N	N	0	N	N	
698	1010	1	1	137		Girls' Gymnasium	Ceiling	Flaking	220	Y	N	0	N	Y - 220 SF	Additional Efflorescence

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
699	1010	1	1	108A		Girls' Restroom	W1	Flaking	2	N	N	0	N	N	Additional Cracking
700	1010	1	1	H13		Hallway 101-110	W2	Flaking	70	N	N	0	N	N	Additional Chipping; Damage on Walls & Lockers
701	1010	1	1	H13		Hallway 101-110	W4	Flaking	60	N	N	0	N	N	Additional Chipping
702	1010	1	1	124A		Health Suite	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
703	1010	1	1	124A		Health Suite	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
704	1010	1	1	124		Health Suite	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
705	1010	1	1	124A		Health Suite	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
706	1010	1	1	124A		Health Suite	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
707	1010	1	1	124A		Health Suite	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
708	1010	1	1	126		Mail Office 126	W1	Cracking	10	N	N	0	N	N	Additional Chipping
709	1010	1	1	126		Mail Office 126	W2	Cracking	12	N	N	0	Y - 28 SF Desks, File Cabinets	N	Additional Chipping
710	1010	1	1	126		Mail Office 126	W3	Flaking	12	N	N	0	N	N	Additional Cracking
711	1010	1	1	126		Mail Office 126	W4	Flaking	15	N	N	0	N	Y - 1 SF	
712	1010	1	1	H14		Main Hallway 135-137	W1	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
713	1010	1	1	H14		Main Hallway 135-137	W3	Cracking	20	N	N	0	N	N	
714	1010	1	1	134		Main Office	W1	Chipping	4	N	N	0	N	N	Chipping @ Entrance Corner
715	1010	1	1	134		Main Office	W2	Cracking	3	N	N	0	N	N	2 Locations; Additional Chipping
716	1010	1	1	134		Main Office	W3	Chipping	3	N	N	0	Y - 36 SF Cabinets, Posters	N	
717	1010	1	1	134		Main Office	W4	Partially Inaccessible	0	N	N	0	Y - 24 SF Cabinets	N	Inspection Needed
718	1010	1	1	134D		Main Office Restroom	W3	Cracking	3	N	N	0	N	N	
719	1010	1	1	001K/001L		Men's Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
720	1010	1	1	001K/001L		Men's Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
721	1010	1	1	001K/001L		Men's Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Warped Door
722	1010	1	1	001K/001L		Men's Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
723	1010	1	1	001K/001L		Men's Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
724	1010	1	1	001K/001L		Men's Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
725	1010	1	1	110		Office 110	Ceiling	Flaking	1	N	N	0	N	N	Suspended Ceiling
726	1010	1	1	110		Office 110	Floor	Debris	0	N	Y - Middle of Floor	6	N	N	
727	1010	1	1	110		Office 110	W1	Chipping	1	N	N	0	N	N	
728	1010	1	1	110		Office 110	W2	Cracking	4	N	N	0	N	N	Additional Chipping, Holes
729	1010	1	1	110		Office 110	W3	Flaking	2	N	Y - On Window Sill	1	N	N	
730	1010	1	1	110		Office 110	W4	Holes	1	N	N	0	N	N	
731	1010	1	1	121		Office 121B	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
732	1010	1	1	121		Office 121B	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
733	1010	1	1	121		Office 121B	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
734	1010	1	1	121		Office 121B	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
735	1010	1	1	121		Office 121B	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
736	1010	1	1	121		Office 121B	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
737	1010	1	1	123		Office 123	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
738	1010	1	1	123		Office 123	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
739	1010	1	1	123		Office 123	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
740	1010	1	1	123		Office 123	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
741	1010	1	1	123		Office 123	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
742	1010	1	1	123		Office 123	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
743	1010	1	1	124B		Office 124A	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
744	1010	1	1	124B		Office 124A	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
745	1010	1	1	124B		Office 124A	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
746	1010	1	1	124B		Office 124A	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
747	1010	1	1	124B		Office 124A	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
748	1010	1	1	124B		Office 124A	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
749	1010	1	1	125		Office 125	W1	Holes	1	N	N	0	N	Y - 1 SF	
750	1010	1	1	125		Office 125	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF File Cabinets, Boxes	N	Inspection Needed
751	1010	1	1	125		Office 125	W3	Flaking	4	N	N	0	N	N	
752	1010	1	1	127B		Office 127B	W1	Cracking	16	N	N	0	Y - 20 SF Posters	N	
753	1010	1	1	127B		Office 127B	W2	Chipping	2	N	N	0	N	N	Chipping @ Pipe
754	1010	1	1	127B		Office 127B	W3	Chipping	3	N	N	0	N	N	2 Locations; Sheetrock Wall
755	1010	1	1	128		Office 128	W3	Flaking	30	N	N	0	Y - 8 SF Posters	N	
756	1010	1	1	128		Office 128	W4	Partially Inaccessible	0	N	N	0	N	N	Inspection Needed
757	1010	1	1	128		Office 128 Foyer	Floor	Debris	0	N	Y - @ Pipe	1	N	N	
758	1010	1	1	128		Office 128 Foyer	W1	Flaking	15	N	N	0	N	Y - 12 SF	
759	1010	1	1	128		Office 128 Foyer	W3	Flaking	5	N	N	0	N	N	Additional Cracking, Chipping
760	1010	1	1	128		Office 128 Foyer	W4	Flaking	3	N	N	0	N	Y - 1 SF	Additional Cracking
761	1010	1	1	130		Office 130	Floor	Chipping	8	N	N	0	N	N	Chipping @ Perimeter
762	1010	1	1	130		Office 130	W2	Flaking	2	N	N	0	N	N	
763	1010	1	1	130		Office 130	W3	Flaking	2	N	N	0	N	N	
764	1010	1	1	130		Office 130 Restroom	W2	Cracking	4	N	N	0	N	N	
765	1010	1	1	130		Office 130 Restroom	W3	Cracking	8	N	N	0	N	N	
766	1010	1	1	130		Office 130 Restroom	W4	Cracking	6	N	N	0	N	N	
767	1010	1	1	131		Office 131	W3	Chipping	3	N	N	0	N	N	Damage @ Radiator & Pipe
768	1010	1	1	133		Office 133	W1	Partially Inaccessible	0	N	N	0	Y - 80 SF File Cabinets, Contents	N	Inspection Needed
769	1010	1	1	133		Office 133	W2	Efflorescence	140	Y	N	0	N	N	Additional Chipping
770	1010	1	1	133		Office 133	W3	Chipping	4	N	N	0	N	N	Chipping @ Radiator
771	1010	1	1	133		Office 133	W4	Flaking	6	N	N	0	N	N	Additional Chipping
772	1010	1	1	134A		Office 134A	Floor	Chipping	3	N	N	0	N	N	
773	1010	1	1	134A		Office 134A	W1	Chipping	1	N	N	0	N	N	
774	1010	1	1	134A		Office 134A	W2	Cracking	1	N	N	0	N	N	
775	1010	1	1	134A		Office 134A	W3	Cracking	7	N	N	0	N	N	Additional Chipping; Damage @ Pipe & Radiator
776	1010	1	1	134A		Office 134A	W4	Flaking	12	N	N	0	N	N	Additional Cracking
777	1010	1	1	129		Principal's Office	W1	Chipping	1	N	N	0	N	N	Chipping @ Door Frame
778	1010	1	1	129		Principal's Office	W2	Chipping	3	N	N	0	N	N	Chipping Near Floor
779	1010	1	1	129		Principal's Office	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Inspection Needed
780	1010	1	1	129		Principal's Office	W4	Cracking	4	N	N	0	Y - 48 SF Contents	N	
781	1010	1	1	134C		Secretary Office 134C	W3	Flaking	2	N	N	0	N	N	
782	1010	1	1	134C		Secretary Office 134C	W4	Flaking	3	N	N	0	Y - 60 SF File Cabinets, Boxes	N	Additional Cracking
783	1010	1	1	136A		Stage	Ceiling	Partially Inaccessible	0	N	N	0	Y - 400 SF Curtain	N	Inspection Needed
784	1010	1	1	136A		Stage	W2	Flaking	30	N	N	0	N	N	
785	1010	1	1	136A		Stage	W3	Flaking	48	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
786	1010	1	1	136A		Stage	W4	Partially Inaccessible	0	N	N	0	Y - 400 SF Curtain	N	Inspection Needed
787	1010	1	1	S13		Stairwell A adjacent to Room 131	Ceiling	Flaking	10	N	N	0	N	N	Additional Cracking
788	1010	1	1	S13		Stairwell A adjacent to Room 131	W1	Flaking	60	N	N	0	N	N	
789	1010	1	1	S13		Stairwell A adjacent to Room 131	W2	Flaking	24	N	N	0	N	N	
790	1010	1	1	S13		Stairwell A adjacent to Room 131	W3	Flaking	20	N	N	0	N	N	Additional Cracking
791	1010	1	1	S13		Stairwell A adjacent to Room 131	W4	Cracking	5	N	N	0	N	N	Additional Chipping
792	1010	1	1	S19		Stairwell adjacent to 111	W1	Chipping	1	N	N	0	N	N	Chipping @ Door
793	1010	1	1	S19		Stairwell adjacent to 111	W2	Cracking	4	N	N	0	N	N	Additional Chipping
794	1010	1	1	S19		Stairwell adjacent to 111	W3	Cracking	4	N	N	0	N	N	Additional Chipping
795	1010	1	1	S19		Stairwell adjacent to 111	W4	Cracking	12	N	N	0	N	N	Additional Chipping
796	1010	1	1	S18		Stairwell adjacent to Room 101	W3	Flaking	10	N	N	0	N	N	Additional Chipping
797	1010	1	1	S18		Stairwell adjacent to Room 101	W4	Cracking	6	N	N	0	N	N	Chipping Above Door
798	1010	1	1	S12		Stairwell adjacent to Room 123	W1	Flaking	4	N	N	0	N	N	
799	1010	1	1	S12		Stairwell adjacent to Room 123	W2	Flaking	40	N	N	0	N	N	
800	1010	1	1	S12		Stairwell adjacent to Room 123	W3	Flaking	6	N	N	0	N	N	Additional Chipping
801	1010	1	1	S12		Stairwell adjacent to Room 123	W4	Cracking	15	N	N	0	N	N	
802	1010	1	1	S12		Stairwell B adjacent to Room 129	W1	Flaking	4	N	N	0	N	N	
803	1010	1	1	S12		Stairwell B adjacent to Room 129	W2	Flaking	40	N	N	0	N	N	
804	1010	1	1	S12		Stairwell B adjacent to Room 129	W3	Flaking	6	N	N	0	N	N	Additional Chipping
805	1010	1	1	S12		Stairwell B adjacent to Room 129	W4	Cracking	15	N	N	0	N	N	
806	1010	1	1	S14		Stairwell C adjacent to Room 129	W1	Cracking	4	N	N	0	N	N	
807	1010	1	1	S14		Stairwell C adjacent to Room 129	W2	Cracking	7	N	N	0	N	N	
808	1010	1	1	S14		Stairwell C adjacent to Room 129	W3	Cracking	4	N	N	0	N	N	
809	1010	1	1	S14		Stairwell C adjacent to Room 129	W4	Cracking	9	N	N	0	N	N	
810	1010	1	1	H15A		Vestibule to Boys' Gym Hallway	Ceiling	Flaking	12	N	N	0	N	N	
811	1010	1	1	H16A		Vestibule to Girls' Gym Hallway	Ceiling	Flaking	15	N	N	0	N	N	
812	1010	1	1	H14A		Vestibule to Hallway H14 Near Boys' Gym	Ceiling	Flaking	32	N	N	0	N	N	
813	1010	1	1	H14B		Vestibule to Hallway H14 Near Girls' Gym	Ceiling	Flaking	32	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
814	1010	1	1	116		Weight Room	Ceiling	Flaking	20	N	N	0	N	N	Additional Chipping; Damage @ Window Lintels; Suspended Ceiling
815	1010	1	1	116		Weight Room	Floor	Debris	0	N	Y - Beneath Windows	8	N	N	
816	1010	1	1	116		Weight Room	W1	Chipping	10	N	N	0	N	N	Chipping Near Floor
817	1010	1	1	116		Weight Room	W3	Flaking	30	N	N	0	N	N	Additional Chipping; Various Locations
818	1010	1	1	116		Weight Room	W4	Holes	1	N	N	0	N	N	
819	1010	1	1	001E/001F		Women's Restroom	Ceiling	Flaking	38	N	N	0	N	N	
820	1010	1	1	001E/001F		Women's Restroom	W1	Flaking	40	N	N	0	N	N	Additional Cracking
821	1010	1	1	001E/001F		Women's Restroom	W2	Flaking	32	N	N	0	N	N	Additional Cracking, Chipping
822	1010	1	1	001E/001F		Women's Restroom	W3	Chipping	3	N	N	0	N	N	
823	1010	1	1	001E/001F		Women's Restroom	W4	Cracking	5	N	N	0	N	N	Suspended Ceiling; Damage @ Window Lintels; Missing Ceiling Tiles
824	1010	1	0	28B		Break Room in Health Suite	W1	Chipping	4	N	N	0	Y - 8 SF Posters	N	Additional Gouges
825	1010	1	0	28B		Break Room in Health Suite	W2	Flaking	10	N	N	0	N	N	Additional Chipping, Gouges
826	1010	1	0	28B		Break Room in Health Suite	W3	Flaking	48	N	N	0	N	N	
827	1010	1	0	28B		Break Room in Health Suite	W4	Flaking	24	N	N	0	N	Y - 8 SF	
828	1010	1	0	H02		B-Wing Hallway 15-17	W2	Cracking	20	N	N	0	N	N	Additional Chipping
829	1010	1	0	H02		B-Wing Hallway 15-17	W4	Cracking	20	N	N	0	N	N	Additional Chipping
830	1010	1	0	23		Cafeteria	W1	Cracking	1	N	N	0	N	N	
831	1010	1	0	23		Cafeteria	W2	Chipping	40	N	N	0	Y - 40 Tables & Chairs	N	
832	1010	1	0	23		Cafeteria	W4	Cracking	20	N	N	0	N	N	Additional Chipping
833	1010	1	0	22		Cafeteria Kitchen	W1	Cracking	5	N	N	0	N	N	
834	1010	1	0	22		Cafeteria Kitchen	W2	Flaking	48	Y	N	0	N	N	Additional Efflorescence, Cracking; Damage on Pipes & Wall
835	1010	1	0	22		Cafeteria Kitchen	W4	Cracking	8	N	N	0	N	N	Additional Chipping
836	1010	1	0	21A		Cafeteria Storage	W1	Cracking	2	N	N	0	N	N	Additional Holes
837	1010	1	0	21A		Cafeteria Storage	W2	Flaking	20	N	N	0	Y - 68 SF Kitchen Appliances	N	Additional Cracking
838	1010	1	0	21A		Cafeteria Storage	W3	Flaking	35	N	N	0	Y - 72 SF Contents	N	Additional Cracking
839	1010	1	0	21A		Cafeteria Storage	W4	Flaking	40	N	N	0	Y - 10 SF Kitchen Appliances	N	Additional Cracking
840	1010	1	0	15		Classroom 15	Floor	Debris	0	N	Y - @ Perimeter	90	N	N	
841	1010	1	0	15		Classroom 15	W1	Flaking	60	N	N	0	N	N	Additional Cracking
842	1010	1	0	15		Classroom 15	W2	Partially Inaccessible	0	N	N	0	Y - 44 SF Contents	N	Inspection Needed
843	1010	1	0	15		Classroom 15	W3	Flaking	120	Y	N	0	N	Y - 20 SF	Additional Efflorescence
844	1010	1	0	15		Classroom 15	W4	Flaking	8	N	N	0	Y - 40 SF Desks, Contents	N	Additional Cracking
845	1010	1	0	2		Classroom 2	W1	Cracking	8	N	N	0	N	N	
846	1010	1	0	2		Classroom 2	W2	Cracking	4	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
847	1010	1	0	2		Classroom 2	W3	Cracking	5	N	N	0	N	N	Additional Chipping; Damage on Pipe & Wall
848	1010	1	0	C-1		Classroom C-1	Ceiling	Flaking	16	N	N	0	N	N	Suspended Ceiling; Damage @ Window Lintels
849	1010	1	0	C-1		Classroom C-1	W1	Chipping	16	N	N	0	N	N	Chipping @ Door & Wall
850	1010	1	0	C-1		Classroom C-1	W2	Flaking	34	N	N	0	N	N	Additional Cracking, Chipping
851	1010	1	0	C-1		Classroom C-1	W3	Flaking	12	N	N	0	Y - 40 SF Desks	N	Additional Cracking, Chipping
852	1010	1	0	C-1		Classroom C-1	W4	Flaking	20	N	N	0	N	N	Additional Chipping
853	1010	1	0	3		Classroom C-3	W1	Flaking	18	N	N	0	N	N	Chipping @ Door & Wall
854	1010	1	0	3		Classroom C-3	W2	Flaking	34	N	N	0	N	N	Additional Cracking, Chipping
855	1010	1	0	3		Classroom C-3	W3	Chipping	10	N	N	0	Y - 40 SF Desks	N	Additional Chipping
856	1010	1	0	3		Classroom C-3	W4	Flaking	106	N	N	0	N	N	Additional Chipping; Damage on Pipe, Radiator, Wall
857	1010	1	0	C-4		Classroom C-4	W1	Chipping	3	N	N	0	N	N	
858	1010	1	0	C-4		Classroom C-4	W2	Flaking	480	N	N	0	N	N	Additional Chipping; Damage on Pipe, Radiator, Wall
859	1010	1	0	C-4		Classroom C-4	W3	Chipping	3	N	N	0	N	N	Additional Holes
860	1010	1	0	C-4		Classroom C-4	W4	Flaking	120	N	N	0	N	N	Additional Cracking, Chipping, Holes
861	1010	1	0	C-5		Classroom C-5	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
862	1010	1	0	C-5		Classroom C-5	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
863	1010	1	0	C-5		Classroom C-5	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
864	1010	1	0	C-5		Classroom C-5	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
865	1010	1	0	C-5		Classroom C-5	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
866	1010	1	0	C-5		Classroom C-5	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
867	1010	1	0	7		Classroom C-8	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
868	1010	1	0	7		Classroom C-8	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
869	1010	1	0	7		Classroom C-8	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
870	1010	1	0	7		Classroom C-8	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
871	1010	1	0	7		Classroom C-8	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
872	1010	1	0	7		Classroom C-8	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
873	1010	1	0	H03		C-Wing Hallway 1-7	W2	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping; Damage on Pipe, Wall, Lockers
874	1010	1	0	H03		C-Wing Hallway 1-7	W3	Chipping	6	N	N	0	N	N	Chipping on Door Frame
875	1010	1	0	H03		C-Wing Hallway 1-7	W4	Chipping	10	N	N	0	N	N	Chipping on Lockers
876	1010	1	0	22A		Dishwashing Room in Kitchen	W3	Chipping	6	N	N	0	N	N	Chipping @ Door Frames
877	1010	1	0	22A		Dishwashing Room in Kitchen	W4	Flaking	6	N	N	0	N	N	
878	1010	1	0	28C		Exam Room 1	W3	Cracking	2	N	N	0	N	N	
879	1010	1	0	28E		Exam Room 3	W1	Flaking	8	N	N	0	N	N	Additional Chipping; Sheetrock Walls
880	1010	1	0	28E		Exam Room 3	W2	Chipping	6	N	N	0	N	N	
881	1010	1	0	28E		Exam Room 3	W3	Flaking	8	N	N	0	N	N	
882	1010	1	0	28E		Exam Room 3	W4	Chipping	6	N	N	0	N	N	
883	1010	1	0	28F		Exam Room 4	W1	Chipping	2	N	N	0	N	N	Sheetrock Walls
884	1010	1	0	28F		Exam Room 4	W2	Chipping	2	N	N	0	N	N	
885	1010	1	0	28F		Exam Room 4	W3	Flaking	8	N	N	0	N	N	
886	1010	1	0	28F		Exam Room 4	W4	Chipping	2	N	N	0	N	N	Additional Gouges
887	1010	1	0	28H		File Room in Health Suite	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
888	1010	1	0	28H		File Room in Health Suite	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
889	1010	1	0	28H		File Room in Health Suite	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
890	1010	1	0	28H		File Room in Health Suite	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
891	1010	1	0	28H		File Room in Health Suite	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
892	1010	1	0	28H		File Room in Health Suite	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
893	1010	1	0	26B		Girls' Restroom	Floor	Chipping	2	N	N	0	N	N	
894	1010	1	0	26B		Girls' Restroom	W1	Flaking	10	N	N	0	N	N	Additional Cracking; Damage @ Corner
895	1010	1	0	29A		Hallway into Chiller Room	Ceiling	Flaking	36	N	N	0	N	Y - 8 SF	Additional Cracking
896	1010	1	0	29A		Hallway into Chiller Room	Floor	Chipping	12	N	N	0	N	N	Chipping @ Perimeter
897	1010	1	0	29A		Hallway into Chiller Room	W1	Chipping	4	N	N	0	N	N	Chipping @ Door Frame
898	1010	1	0	29A		Hallway into Chiller Room	W2	Flaking	45	N	N	0	N	N	Additional Cracking
899	1010	1	0	29A		Hallway into Chiller Room	W4	Cracking	6	N	N	0	N	N	
900	1010	1	0	22C		Kitchen Closet	W3	Flaking	6	N	N	0	N	N	
901	1010	1	0	22C		Kitchen Closet	W4	Flaking	24	N	N	0	N	N	
902	1010	1	0	22B		Kitchen Office	W1	Chipping	5	N	N	0	N	N	Chipping @ Door & Window
903	1010	1	0	22B		Kitchen Office	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, File Cabinets, Contents	N	Inspection Needed
904	1010	1	0	22B		Kitchen Office	W3	Partially Inaccessible	0	N	N	0	Y - 20 SF File Cabinets	N	Inspection Needed
905	1010	1	0	22D		Kitchen Office Restroom	W1	Chipping	2	N	N	0	N	N	
906	1010	1	0	22D		Kitchen Office Restroom	W2	Partially Inaccessible	0	N	N	0	Y - 42 SF Lockers	N	Inspection Needed
907	1010	1	0	22D		Kitchen Office Restroom	W3	Flaking	2	N	N	0	N	N	
908	1010	1	0	22D		Kitchen Office Restroom	W4	Chipping	2	N	N	0	N	N	
909	1010	1	0	H04		Main Hallway 7-28	W1	Flaking	180	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall & Radiator
910	1010	1	0	H04		Main Hallway 7-28	W3	Flaking	210	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall & Radiator
911	1010	1	0	H04		Main Hallway 7-28	W4	Chipping	16	N	N	0	N	N	
912	1010	1	0	28/28A		Nurse's Office/Health Suite	W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
913	1010	1	0	28/28A		Nurse's Office/Health Suite	W3	Chipping	16	N	N	0	N	N	Additional Holes; Sheetrock Wall
914	1010	1	0	28/28A		Nurse's Office/Health Suite	W4	Chipping	12	N	N	0	N	N	Additional Holes, Gouges; Sheetrock Wall
915	1010	1	0	11		Office 11	W1	Cracking	8	N	N	0	N	N	
916	1010	1	0	11		Office 11	W2	Cracking	6	N	N	0	Y - 60 SF Cabinets, Contents	N	Additional Holes
917	1010	1	0	11		Office 11	W3	Flaking	4	N	N	0	Y - 18 SF Contents	N	Additional Chipping
918	1010	1	0	11		Office 11	W4	Flaking	3	N	N	0	Y - 24 SF Contents	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
919	1010	1	0	28G		Restroom in Health Suite	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
920	1010	1	0	28G		Restroom in Health Suite	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
921	1010	1	0	28G		Restroom in Health Suite	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
922	1010	1	0	28G		Restroom in Health Suite	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
923	1010	1	0	28G		Restroom in Health Suite	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
924	1010	1	0	28G		Restroom in Health Suite	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
925	1010	1	0	12		Room 12	W1	Flaking	60	N	N	0	N	N	Additional Cracking
926	1010	1	0	12		Room 12	W2	Flaking	40	N	N	0	N	N	Additional Cracking
927	1010	1	0	12		Room 12	W3	Flaking	50	N	N	0	N	N	Additional Cracking
928	1010	1	0	12		Room 12	W4	Flaking	30	N	N	0	N	N	Additional Cracking
929	1010	1	0	17		Room 17	W1	Flaking	28	N	N	0	N	N	Additional Cracking, Chipping: Damage on Wall & Pipe
930	1010	1	0	17		Room 17	W2	Cracking	6	N	N	0	N	N	
931	1010	1	0	17		Room 17	W3	Flaking	36	N	N	0	N	Y - 6 SF	Additional Holes
932	1010	1	0	17		Room 17	W4	Flaking	72	N	N	0	N	N	Additional Cracking
933	1010	1	0	16		Security Office 16	W1	Flaking	38	N	N	0	N	N	Additional Cracking
934	1010	1	0	16		Security Office 16	W2	Chipping	10	N	N	0	Y - 40 SF Lockers	N	
935	1010	1	0	16		Security Office 16	W3	Flaking	60	N	N	0	N	N	Additional Cracking
936	1010	1	0	16		Security Office 16	W4	Cracking	10	N	N	0	Y - 30 SF Tables, Contents	N	Additional Chipping
937	1010	1	0	S08		Stairwell adjacent to C-4	Ceiling	Flaking	12	N	N	0	N	N	Flaking on Pipe & Wall
938	1010	1	0	S08		Stairwell adjacent to C-4	W1	Chipping	3	N	N	0	N	N	Chipping @ Door
939	1010	1	0	S08		Stairwell adjacent to C-4	W2	Flaking	5	N	N	0	N	N	
940	1010	1	0	S08		Stairwell adjacent to C-4	W3	Flaking	4	Y	N	0	N	Y - 2 SF	Additional Efflorescence
941	1010	1	0	S08		Stairwell adjacent to C-4	W4	Flaking	12	N	N	0	N	N	Additional Cracking
942	1010	1	0	S03		Stairwell adjacent to Cafeteria	Ceiling	Flaking	80	N	N	0	N	N	
943	1010	1	0	S03		Stairwell adjacent to Cafeteria	W2	Flaking	90	N	N	0	N	N	
944	1010	1	0	S03		Stairwell adjacent to Cafeteria	W3	Flaking	8	N	N	0	N	N	Additional Chipping
945	1010	1	0	S03		Stairwell adjacent to Cafeteria	W4	Flaking	110	N	N	0	N	N	Additional Cracking
946	1010	1	0	S01		Stairwell adjacent to Cafeteria Storage	Floor	Flaking	16	N	N	0	N	N	
947	1010	1	0	S01		Stairwell adjacent to Cafeteria Storage	W2	Flaking	10	N	N	0	N	N	Additional Chipping
948	1010	1	0	S01		Stairwell adjacent to Cafeteria Storage	W3	Chipping	3	N	N	0	N	N	Additional Chipping
949	1010	1	0	S01		Stairwell adjacent to Cafeteria Storage	W4	Flaking	5	N	N	0	N	N	
950	1010	1	0	S02		Stairwell B adjacent to Room. 16	Ceiling	Chipping	5	N	N	0	N	N	
951	1010	1	0	S02		Stairwell B adjacent to Room. 16	W1	Cracking	15	N	N	0	N	N	

Bartram -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
952	1010	1	0	S02		Stairwell B adjacent to Room. 16	W2	Chipping	6	N	N	0	N	N	
953	1010	1	0	S02		Stairwell B adjacent to Room. 16	W3	Cracking	10	N	N	0	N	N	
954	1010	1	0	S02		Stairwell B adjacent to Room. 16	W4	Chipping	8	N	N	0	N	N	
955	1010	1	0	S04		Stairwell C adjacent to Room. 7	Ceiling	Chipping	8	N	N	0	N	N	
956	1010	1	0	S04		Stairwell C adjacent to Room. 7	W1	Chipping	10	N	N	0	N	N	
957	1010	1	0	S04		Stairwell C adjacent to Room. 7	W2	Chipping	9	N	N	0	N	N	
958	1010	1	0	S04		Stairwell C adjacent to Room. 7	W3	Cracking	14	N	N	0	N	N	
959	1010	1	0	S04		Stairwell C adjacent to Room. 7	W4	Cracking	5	N	N	0	N	N	
960	1010	1	0	18		Storage Adjacent to Boys' Locker	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
961	1010	1	0	18		Storage Adjacent to Boys' Locker	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
962	1010	1	0	18		Storage Adjacent to Boys' Locker	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
963	1010	1	0	18		Storage Adjacent to Boys' Locker	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
964	1010	1	0	18		Storage Adjacent to Boys' Locker	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
965	1010	1	0	18		Storage Adjacent to Boys' Locker	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
966	1010	1	0	20		Storage Area	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
967	1010	1	0	20		Storage Area	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
968	1010	1	0	20		Storage Area	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Warped Door
969	1010	1	0	20		Storage Area	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
970	1010	1	0	20		Storage Area	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
971	1010	1	0	20		Storage Area	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Needed
972	1010	1	0	10A		Storage B-H	Ceiling	Flaking	144	N	N	0	N	Y - 2 SF	Additional Cracking, Holes
973	1010	1	0	10A		Storage B-H	W1	Partially Inaccessible	0	N	N	0	Y - 7 SF Contents	N	Inspection Needed
974	1010	1	0	10A		Storage B-H	W2	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Inspection Needed
975	1010	1	0	10A		Storage B-H	W3	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Needed
976	1010	1	0	10A		Storage B-H	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Contents	N	Inspection Needed
977	1010	1	0	29B		Telecommunications Room	Ceiling	Flaking	36	N	N	0	N	N	
978	1010	1	0	29B		Telecommunications Room	W1	Flaking	2	N	N	0	N	N	
979	1010	1	0	29B		Telecommunications Room	W2	Cracking	4	N	N	0	N	N	
980	1010	1	0	29B		Telecommunications Room	W3	Flaking	4	N	N	0	N	N	
981	1010	1	0	29B		Telecommunications Room	W4	Flaking	1	N	N	0	N	N	