

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7220	1	3	307B		Boy's Restroom	Ceiling	Efflorescence	35	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
2	7220	1	3	307B		Boy's Restroom	Floor	Chipping	41	No	Debris	10	N/A	No	
3	7220	1	3	307B		Boy's Restroom	W2	Cracking, Chipping, Hole, Spalling	8	Yes	No	N/A	N/A	Yes	
4	7220	1	3	307B		Boy's Restroom	W3	Efflorescence	10	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
5	7220	1	3	307B		Boy's Restroom	W4	Cracking, Efflorescence	25	Yes	No	N/A	N/A	Yes	
6	7220	1	3	301		Classroom 301	Ceiling	Holes, Flaking, Spalling	10	Yes	No	N/A	N/A	Yes	
7	7220	1	3	301		Classroom 301	W1	Cracking, Chipping, Hole, Flaking, Spalling	80	Yes	No	N/A	Furniture	Yes	
8	7220	1	3	301		Classroom 301	W2	Cracking, Chipping, Holes	28	No	No	N/A	Furniture	Yes	
9	7220	1	3	301		Classroom 301	W3	Cracking, Chipping on wall and metal jackets, Flaking	18	No	No	N/A	Furniture	No	
10	7220	1	3	301		Classroom 301	W4	Cracking, Chipping	39	No	No	N/A	Furniture	No	
11	7220	1	3	301A		Classroom 301 Closet	Ceiling	Cracking	50	No	No	N/A	Stored Materials	No	
12	7220	1	3	301B		Classroom 301 Closet	Ceiling	Hole, Flaking	7	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
13	7220	1	3	301A		Classroom 301 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
14	7220	1	3	301B		Classroom 301 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
15	7220	1	3	301A		Classroom 301 Closet	W1	Cracking, Chipping	6	No	No	N/A	Stored Materials	No	
16	7220	1	3	301B		Classroom 301 Closet	W1	Cracking, Flaking	17	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
17	7220	1	3	301A		Classroom 301 Closet	W2	Cracking, Chipping	133	No	No	N/A	Stored Materials	No	
18	7220	1	3	301B		Classroom 301 Closet	W2	Cracking, Chipping, Flaking, Efflorescence	23	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
19	7220	1	3	301B		Classroom 301 Closet	W3	Chipping on metal pipes, Flaking	21	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
20	7220	1	3	301A		Classroom 301 Closet	W3	Cracking, Chipping	13	No	No	N/A	Stored Materials	No	
21	7220	1	3	301B		Classroom 301 Closet	W4	Cracking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
22	7220	1	3	301A		Classroom 301 Closet	W4	Cracking, Chipping	40	No	No	N/A	Stored Materials	No	
23	7220	1	3	302		Classroom 302	Ceiling	Cracking	4	No	No	N/A	N/A	No	
24	7220	1	3	302		Classroom 302	W1	Cracking, Chipping, Hole	80	No	No	N/A	N/A	Yes	
25	7220	1	3	302		Classroom 302	W2	Cracking, Chipping	16	No	No	N/A	N/A	No	
26	7220	1	3	302		Classroom 302	W3	Cracking, Chipping on wall, radiator, and metal jacket, Holes, some behind radiators, Flaking, Spalling	45	Yes	No	N/A	N/A	Yes	
27	7220	1	3	302		Classroom 302	W4	Cracking, Chipping	20	No	No	N/A	Posters	No	
28	7220	1	3	302A		Classroom 302 Closet	Ceiling	Cracking	10	No	No	N/A	N/A	No	
29	7220	1	3	302A		Classroom 302 Closet	W1	Cracking, Chipping	4	No	No	N/A	N/A	No	
30	7220	1	3	302A		Classroom 302 Closet	W2	Cracking, Chipping	43	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
31	7220	1	3	302A		Classroom 302 Closet	W3	Cracking, Chipping	30	No	No	N/A	N/A	No	
32	7220	1	3	302A		Classroom 302 Closet	W4	Cracking, Chipping, Coat hooks pulling off wall	80	No	No	N/A	N/A	Yes	
33	7220	1	3	303		Classroom 303	Ceiling	Cracking, Efflorescence	17	Yes	No	N/A	N/A	Yes	
34	7220	1	3	303		Classroom 303	W1	Cracking on wall and in air shaft, Chipping, Hole on wall and in air shaft, Efflorescence in air shaft	61	Yes	No	N/A	N/A	Yes	
35	7220	1	3	303		Classroom 303	W2	Chipping, Flaking, Spalling, Efflorescence	30	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
36	7220	1	3	303		Classroom 303	W3	Cracking, Chipping on wall, metal jacket, and radiator covers, Flaking, Efflorescence	26	Yes	Debris on windowsills and radiator cover	5	N/A	Yes	
37	7220	1	3	303		Classroom 303	W4	Chipping, Efflorescence	11	Yes	No	N/A	N/A	Yes	
38	7220	1	3	303A		Classroom 303 Closet	Ceiling	Significant Moisture Damage above missing ceiling tile	16	Yes	No	N/A	N/A	Yes	
39	7220	1	3	303A		Classroom 303 Closet	Floor	Debris	N/A	No	Debris on floor and shelf	25	N/A	No	
40	7220	1	3	303A		Classroom 303 Closet	W1	Chipping	2	No	No	N/A	N/A	No	
41	7220	1	3	303A		Classroom 303 Closet	W2	Chipping, Efflorescence, some above missing ceiling tile	32	Yes	No	N/A	N/A	Yes	
42	7220	1	3	303A		Classroom 303 Closet	W3	Chipping	3	No	No	N/A	N/A	No	
43	7220	1	3	303A		Classroom 303 Closet	W4	Chipping, Hole, Efflorescence, some above missing ceiling tile	25	Yes	No	N/A	N/A	Yes	
44	7220	1	3	304		Classroom 304	Ceiling	Cracking, Spalling	29	Yes	No	N/A	N/A	Yes	
45	7220	1	3	304		Classroom 304	W1	Cracking, Chipping, Efflorescence	28	Yes	No	N/A	N/A	Yes	Damage has been repaired but is returning
46	7220	1	3	304		Classroom 304	W3	Chipping on wall, metal pipe, and radiator, Efflorescence	68	Yes	Debris on windowsills	16	N/A	Yes	
47	7220	1	3	304		Classroom 304	W4	Chipping, Spalling	23	Yes	No	N/A	N/A	Yes	
48	7220	1	3	304B		Classroom 304 Closet	Ceiling	Cracking	3	No	No	N/A	N/A	No	
49	7220	1	3	304A		Classroom 304 Closet	Ceiling	Cracking, Flaking	11	No	No	N/A	N/A	No	
50	7220	1	3	304B		Classroom 304 Closet	W1	Cracking	2	No	No	N/A	N/A	No	
51	7220	1	3	304B		Classroom 304 Closet	W2	Chipping	5	No	No	N/A	N/A	No	
52	7220	1	3	304A		Classroom 304 Closet	W2	Chipping, Flaking, Hole	7	No	No	N/A	N/A	Yes	
53	7220	1	3	304A		Classroom 304 Closet	W3	Chipping	3	No	No	N/A	N/A	No	
54	7220	1	3	304B		Classroom 304 Closet	W3	Cracking, Efflorescence	10	Yes	No	N/A	Built in shelves with stored materials	Yes	Limited inspection die to stored materials
55	7220	1	3	304B		Classroom 304 Closet	W4	Efflorescence	7	Yes	Debris on shelf	1	Built in shelves with stored materials	Yes	Limited inspection die to stored materials
56	7220	1	3	304A		Classroom 304 Closet	W4	Cracking, Chipping	13	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
57	7220	1	3	305		Classroom 305	Ceiling	Cracking, Efflorescence	18	Yes	No	N/A	N/A	Yes	
58	7220	1	3	305		Classroom 305	W1	Cracking, Chipping, Flaking	48	No	No	N/A	N/A	No	
59	7220	1	3	305		Classroom 305	W3	Chipping on wall and radiator, Flaking, Efflorescence	29	Yes	Debris on windowsills	8	N/A	Yes	
60	7220	1	3	305A		Classroom 305 Closet	Ceiling	Cracking, Efflorescence	17	Yes	No	N/A	N/A	Yes	
61	7220	1	3	305A		Classroom 305 Closet	W1	N/A	N/A	No	No	N/A	Cabinet	No	Limited inspection due to stored materials
62	7220	1	3	305A		Classroom 305 Closet	W2	Cracking, Chipping	33	No	No	N/A	N/A	No	
63	7220	1	3	305A		Classroom 305 Closet	W3	Cracking, Chipping	20	No	No	N/A	N/A	No	
64	7220	1	3	305A		Classroom 305 Closet	W4	Chipping, Efflorescence	40	Yes	No	N/A	N/A	Yes	
65	7220	1	3	306		Classroom 306	Ceiling	Cracking, Efflorescence	14	Yes	No	N/A	N/A	Yes	
66	7220	1	3	306		Classroom 306	Floor	Debris	N/A	No	Debris along wall 3	8	N/A	No	
67	7220	1	3	306		Classroom 306	W1	Cracking, Chipping	16	No	No	N/A	Furniture	No	
68	7220	1	3	306		Classroom 306	W3	Chipping, Flaking, Efflorescence	17	Yes	Debris on windowsills	15	N/A	Yes	
69	7220	1	3	306		Classroom 306	W4	N/A	N/A	No	No	N/A	Tables with computers	No	Limited inspection due to stored materials
70	7220	1	3	306A		Classroom 306 Closet	Ceiling	Chipping	1	No	No	N/A	N/A	No	
71	7220	1	3	306B		Classroom 306 Closet	Ceiling	Cracking	1	No	No	N/A	N/A	No	
72	7220	1	3	306B		Classroom 306 Closet	W1	Cracking	8	No	No	N/A	N/A	No	
73	7220	1	3	306A		Classroom 306 Closet	W1	Cracking, Chipping	3	No	No	N/A	N/A	No	
74	7220	1	3	306A		Classroom 306 Closet	W2	Cracking, Chipping	21	No	No	N/A	N/A	No	
75	7220	1	3	306B		Classroom 306 Closet	W3	Cracking	10	No	No	N/A	N/A	No	
76	7220	1	3	306A		Classroom 306 Closet	W3	Cracking, Chipping	28	No	No	N/A	N/A	No	
77	7220	1	3	306B		Classroom 306 Closet	W4	Cracking	13	No	No	N/A	N/A	No	
78	7220	1	3	306A		Classroom 306 Closet	W4	Cracking, Chipping, Hole, Flaking	24	No	No	N/A	N/A	Yes	
79	7220	1	3	307		Classroom 307	Ceiling	Cracking, Spalling, Efflorescence	22	Yes	No	N/A	N/A	Yes	
80	7220	1	3	307		Classroom 307	W1	Cracking, Chipping	50	No	No	N/A	N/A	No	
81	7220	1	3	307		Classroom 307	W2	Chipping, Flaking	15	No	No	N/A	N/A	No	
82	7220	1	3	307		Classroom 307	W3	Cracking, Chipping on wall and radiator, Efflorescence, Significant Moisture Damage behind radiator	31	Yes	Debris on windowsills	3	N/A	Yes	
83	7220	1	3	307		Classroom 307	W4	Cracking, Efflorescence	5	Yes	No	N/A	N/A	Yes	
84	7220	1	3	307A		Classroom 307 Closet	Ceiling	Cracking	20	No	No	N/A	N/A	No	
85	7220	1	3	307A		Classroom 307 Closet	W1	Cracking	3	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
86	7220	1	3	307C		Classroom 307 Closet	W2	Cracking	2	No	No	N/A	N/A	No	
87	7220	1	3	307A		Classroom 307 Closet	W2	Cracking, Chipping, Flaking	10	No	No	N/A	N/A	No	
88	7220	1	3	307A		Classroom 307 Closet	W3	Cracking, Chipping	2	No	No	N/A	N/A	No	
89	7220	1	3	307C		Classroom 307 Closet	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
90	7220	1	3	307C		Classroom 307 Closet	W4	Cracking	3	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
91	7220	1	3	307A		Classroom 307 Closet	W4	Cracking, Chipping	11	No	No	N/A	N/A	No	
92	7220	1	3	308		Classroom 308	Ceiling	Cracking, Efflorescence	10	Yes	No	N/A	N/A	Yes	
93	7220	1	3	308		Classroom 308	Floor	Debris	N/A	No	Debris on floor and chair	5	N/A	No	
94	7220	1	3	308		Classroom 308	W1	Cracking, Chipping	31	No	No	N/A	N/A	No	
95	7220	1	3	308		Classroom 308	W2	Chipping	7	No	No	N/A	N/A	No	
96	7220	1	3	308		Classroom 308	W3	Cracking, Chipping on wall, metal pipes, and radiators, Spalling	50	Yes	No	N/A	N/A	Yes	
97	7220	1	3	308		Classroom 308	W4	Chipping, Flaking, Efflorescence	24	Yes	No	N/A	N/A	Yes	
98	7220	1	3	308A		Classroom 308 Closet	Ceiling	Efflorescence	33	Yes	No	N/A	N/A	Yes	
99	7220	1	3	308A		Classroom 308 Closet	Floor	Debris	N/A	No	Debris	20	N/A	No	
100	7220	1	3	308A		Classroom 308 Closet	W1	Cracking	1	No	No	N/A	N/A	No	
101	7220	1	3	308A		Classroom 308 Closet	W2	Cracking, Chipping, Efflorescence	36	Yes	No	N/A	N/A	Yes	
102	7220	1	3	308A		Classroom 308 Closet	W3	Cracking, Chipping	7	No	No	N/A	N/A	No	
103	7220	1	3	308A		Classroom 308 Closet	W4	Efflorescence	2	Yes	No	N/A	N/A	Yes	
104	7220	1	3	309		Classroom 309	Ceiling	Cracking, Efflorescence	15	Yes	No	N/A	N/A	Yes	
105	7220	1	3	309		Classroom 309	W1	Cracking, Chipping	38	No	No	N/A	N/A	No	
106	7220	1	3	309		Classroom 309	W2	Chipping	14	No	No	N/A	N/A	No	
107	7220	1	3	309		Classroom 309	W3	Chipping on metal pipe and radiator cover, Flaking, Efflorescence	27	Yes	Debris on windowsills	11	Cabinets	Yes	
108	7220	1	3	309		Classroom 309	W4	Chipping, Flaking	4	No	No	N/A	N/A	No	
109	7220	1	3	309A		Classroom 309 Closet	Ceiling	Flaking	3	No	No	N/A	N/A	No	
110	7220	1	3	309A		Classroom 309 Closet	W1	Cracking, Chipping	6	No	No	N/A	N/A	No	
111	7220	1	3	309A		Classroom 309 Closet	W2	Cracking, Chipping	30	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
112	7220	1	3	309A		Classroom 309 Closet	W3	Chipping	15	No	No	N/A	N/A	No	
113	7220	1	3	309A		Classroom 309 Closet	W4	Cracking, Chipping	37	No	No	N/A	N/A	No	
114	7220	1	3	310		Classroom 310	Ceiling	Flaking, Significant Moisture Damage	9	Yes	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
115	7220	1	3	310		Classroom 310	Floor	Debris	N/A	No	Debris on windowsills	4	N/A	No	
116	7220	1	3	310		Classroom 310	W1	Cracking, Chipping, Spalling	49	Yes	No	N/A	Posters	Yes	
117	7220	1	3	310		Classroom 310	W2	Cracking, Chipping	19	No	No	N/A	N/A	No	
118	7220	1	3	310		Classroom 310	W3	Cracking, Chipping on wall, radiators, and metal pipes, Hole, Flaking on wall and behind radiator, Efflorescence	63	Yes	No	N/A	Shelves	Yes	
119	7220	1	3	310		Classroom 310	W4	Cracking, Chipping	20	No	No	N/A	Stored Materials	No	
120	7220	1	3	310A		Classroom 310 Closet	Ceiling	Cracking	20	No	No	N/A	N/A	No	
121	7220	1	3	310A		Classroom 310 Closet	W1	Cracking, Hole	2	No	No	N/A	N/A	Yes	
122	7220	1	3	310A		Classroom 310 Closet	W2	Cracking, Chipping	41	No	No	N/A	Stored Materials	No	
123	7220	1	3	310A		Classroom 310 Closet	W3	Chipping	15	No	No	N/A	Stored Materials	No	
124	7220	1	3	310A		Classroom 310 Closet	W4	Cracking, Chipping	46	No	No	N/A	N/A	No	
125	7220	2	3	312		Classroom 312	Ceiling	Flaking	4	No	No	N/A	N/A	No	
126	7220	2	3	312		Classroom 312	W1	Cracking, Chipping on wall and doorframe	83	No	No	N/A	N/A	No	Concrete block will need to be repaired
127	7220	2	3	312		Classroom 312	W2	Chipping, Flaking	10	No	No	N/A	N/A	No	
128	7220	2	3	312		Classroom 312	W3	Chipping on wall, univent, built in shelves, and metal jacket	108	No	No	N/A	N/A	No	
129	7220	2	3	312		Classroom 312	W4	Chipping on wall and chalkboard ledge, Hole	18	No	No	N/A	N/A	No	Concrete block will need to be repaired
130	7220	2	3	312A		Classroom 312 Closet	W1	Chipping on doorframe	18	No	No	N/A	N/A	No	
131	7220	2	3	312B		Classroom 312 Closet	W1	Chipping on doorframe	17	No	No	N/A	N/A	No	
132	7220	2	3	312A		Classroom 312 Closet	W2	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
133	7220	2	3	312B		Classroom 312 Closet	W2	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
134	7220	2	3	312A		Classroom 312 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
135	7220	2	3	312B		Classroom 312 Closet	W3	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
136	7220	2	3	313		Classroom 313	Ceiling	Flaking	3	No	No	N/A	N/A	No	
137	7220	2	3	313		Classroom 313	W1	Cracking, Chipping on wall and doorframe	93	No	No	N/A	N/A	No	Concrete block will need to be repaired
138	7220	2	3	313		Classroom 313	W2	Chipping	7	No	No	N/A	N/A	No	
139	7220	2	3	313		Classroom 313	W3	Chipping on wall, univent, built in shelves, metal jacket and asbestos pipe insulation	117	No	No	N/A	N/A	No	
140	7220	2	3	313		Classroom 313	W4	Cracking, Chipping, Holes	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
141	7220	2	3	313D		Classroom 313 Closet	W1	Chipping on doorframe	9	No	No	N/A	N/A	No	
142	7220	2	3	313E		Classroom 313 Closet	W1	Chipping on doorframe	7	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
143	7220	2	3	313D		Classroom 313 Closet	W2	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
144	7220	2	3	313D		Classroom 313 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
145	7220	2	3	313E		Classroom 313 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
146	7220	2	3	313E		Classroom 313 Closet	W4	Cracking	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
147	7220	2	3	314		Classroom 314	Ceiling	Flaking	2	No	No	N/A	N/A	No	
148	7220	2	3	314		Classroom 314	W1	Cracking, Chipping on wall and doorframe	122	No	No	N/A	N/A	No	Concrete block will need to be repaired
149	7220	2	3	314		Classroom 314	W2	Chipping on chalkboard ledge and metal pipe	19	No	No	N/A	N/A	No	
150	7220	2	3	314		Classroom 314	W3	Chipping on wall, univent, and built in shelves	110	No	No	N/A	N/A	No	
151	7220	2	3	314		Classroom 314	W4	Chipping on wall, chalkboard ledge, and radiator cover, Flaking	54	No	No	N/A	N/A	No	
152	7220	2	3	314A		Classroom 314 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
153	7220	2	3	314A		Classroom 314 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
154	7220	2	3	314B		Classroom 314 Closet	W1	Chipping on doorframe	15	No	No	N/A	N/A	No	
155	7220	2	3	314A		Classroom 314 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
156	7220	2	3	314B		Classroom 314 Closet	W2	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
157	7220	2	3	314A		Classroom 314 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
158	7220	2	3	314B		Classroom 314 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
159	7220	2	3	314A		Classroom 314 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
160	7220	2	3	314A		Classroom 314 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
161	7220	1	3	S01		Entrance Stairs Third Floor	Ceiling	Significant Moisture Damage	100	Yes	No	N/A	N/A	Yes	
162	7220	1	3	S01		Entrance Stairs Third Floor	Floor	Chipping on stairs and railings	51	No	Debris	5	N/A	No	
163	7220	1	3	S01		Entrance Stairs Third Floor	W1	Cracking, Flaking, Spalling	25	Yes	Debris on radiator ledge and inside radiator enclosure	20	N/A	Yes	
164	7220	1	3	S01		Entrance Stairs Third Floor	W2	Cracking, Flaking, Spalling	50	Yes	No	N/A	N/A	Yes	
165	7220	1	3	S01		Entrance Stairs Third Floor	W3	Cracking, Chipping on doors and doorframe	27	No	No	N/A	N/A	No	
166	7220	1	3	S01		Entrance Stairs Third Floor	W4	Cracking, Spalling	4	Yes	No	N/A	N/A	Yes	
167	7220	1	3	303B		Girl's Restroom	Ceiling	Cracking, Chipping, Flaking, Spalling, Efflorescence	17	Yes	No	N/A	N/A	Yes	
168	7220	1	3	303B		Girl's Restroom	Floor	Chipping	41	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
169	7220	1	3	303B		Girl's Restroom	W2	Cracking, Chipping on radiator cover and metal pipe, Hole, Flaking, Spalling	39	Yes	No	N/A	N/A	Yes	
170	7220	1	3	303B		Girl's Restroom	W3	Flaking, Efflorescence	20	Yes	No	N/A	N/A	Yes	
171	7220	1	3	303B		Girl's Restroom	W4	Cracking, Chipping, Spalling, Efflorescence	23	Yes	No	N/A	N/A	Yes	
172	7220	1	3	H314A		Hallway Closet adjacent to Classroom 301	Ceiling	Flaking	1	No	No	N/A	N/A	No	
173	7220	1	3	H314A		Hallway Closet adjacent to Classroom 301	W1	N/A	N/A	No	No	N/A	Built in shelves with books	No	Limited inspection due to stored materials
174	7220	1	3	H314A		Hallway Closet adjacent to Classroom 301	W2	Cracking	10	No	No	N/A	Built in shelves with books	No	
175	7220	1	3	H314A		Hallway Closet adjacent to Classroom 301	W3	Flaking, Efflorescence	45	Yes	No	N/A	Built in shelves with books	Yes	
176	7220	1	3	H314A		Hallway Closet adjacent to Classroom 301	W4	Chipping	20	No	No	N/A	Built in shelves with books	No	
177	7220	2	3	313B		Men's Restroom	Ceiling	Flaking	7	No	No	N/A	N/A	No	
178	7220	2	3	313B		Men's Restroom	W1	Chipping on doorframe	21	No	No	N/A	N/A	No	
179	7220	2	3	313B		Men's Restroom	W3	Chipping	4	No	No	N/A	N/A	No	
180	7220	1	3	317		Speech Room Office	Ceiling	Cracking, Flaking	13	No	No	N/A	N/A	No	
181	7220	1	3	317		Speech Room Office	Floor	N/A	N/A	No	Paint Chips	20	N/A	No	
182	7220	1	3	317		Speech Room Office	W1	Cracking, Flaking	76	No	No	N/A	Furniture	No	
183	7220	1	3	317		Speech Room Office	W2	Cracking, Flaking	80	No	No	N/A	Cabinet	No	
184	7220	1	3	317		Speech Room Office	W3	Cracking, Chipping on wall and radiator, Holes, Flaking	61	No	No	N/A	Cabinet	Yes	
185	7220	1	3	317		Speech Room Office	W4	Cracking, Flaking	54	No	No	N/A	N/A	No	
186	7220	1	3	316A		Staff Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
187	7220	1	3	316A		Staff Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
188	7220	1	3	316A		Staff Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
189	7220	1	3	316A		Staff Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
190	7220	1	3	316A		Staff Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
191	7220	1	3	316A		Staff Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
192	7220	1	3	S32		Stairs Third Floor	Ceiling	Significant Moisture Damage	80	Yes	No	N/A	N/A	Yes	
193	7220	1	3	S32		Stairs Third Floor	Floor	Chipping on stairs and railings	131	No	Debris	5	N/A	No	
194	7220	1	3	S32		Stairs Third Floor	W1	Cracking, Spalling	8	Yes	Debris on radiator ledge and inside radiator enclosure	40	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
195	7220	1	3	S32		Stairs Third Floor	W2	Cracking, Chipping, Flaking, Efflorescence	19	Yes	No	N/A	N/A	Yes	
196	7220	1	3	S32		Stairs Third Floor	W3	Chipping on doors and doorframe	31	No	No	N/A	N/A	No	
197	7220	1	3	S32		Stairs Third Floor	W4	Chipping, Flaking, Spalling	11	Yes	No	N/A	N/A	Yes	
198	7220	1	3	315		Storage Closet 300	Ceiling	Cracking, Flaking	11	No	No	N/A	N/A	No	
199	7220	1	3	315		Storage Closet 300	W1	Cracking, Chipping	7	No	No	N/A	N/A	No	
200	7220	1	3	315		Storage Closet 300	W2	Cracking, Chipping on wall and wood cove base	8	No	No	N/A	N/A	No	
201	7220	1	3	315		Storage Closet 300	W3	Cracking, Chipping	22	No	No	N/A	N/A	No	
202	7220	1	3	315		Storage Closet 300	W4	Chipping on metal pipe and wood cove base, Hole, Flaking, Efflorescence	34	Yes	No	N/A	N/A	Yes	
203	7220	2	3	316		Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
204	7220	2	3	316		Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
205	7220	2	3	316		Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
206	7220	2	3	316		Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
207	7220	2	3	316		Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
208	7220	2	3	316		Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
209	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	Ceiling	Cracking	21	No	No	N/A	N/A	No	
210	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	Floor	Chipping	18	No	No	N/A	N/A	No	
211	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	W1	Cracking, Flaking	13	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
212	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	W2	Cracking, Chipping	40	No	No	N/A	N/A	No	
213	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	W3	Cracking, Chipping	2	No	No	N/A	N/A	No	
214	7220	1	3	H314		Third Floor Hallway in Element 1 Between Classroom 301 and Classroom 303	W4	Cracking, Chipping, Spalling, Efflorescence	41	Yes	No	N/A	N/A	Yes	
215	7220	1	3	H313		Third Floor Hallway in Element 1 Between Classroom 304 and Classroom 307	Ceiling	Cracking, Flaking, Efflorescence	46	Yes	No	N/A	N/A	Yes	
216	7220	1	3	H313		Third Floor Hallway in Element 1 Between Classroom 304 and Classroom 307	Floor	Chipping	53	No	No	N/A	N/A	No	
217	7220	1	3	H313		Third Floor Hallway in Element 1 Between Classroom 304 and Classroom 307	W1	Cracking, Chipping	126	No	No	N/A	N/A	No	
218	7220	1	3	H313		Third Floor Hallway in Element 1 Between Classroom 304 and Classroom 307	W3	Cracking, Chipping on wall and radiator covers, Flaking, Spalling, Significant Moisture Damage	112	Yes	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
219	7220	1	3	H312		Third Floor Hallway in Element 1 Between Classroom 308 and Classroom 310	Ceiling	Flaking, Efflorescence	9	Yes	No	N/A	N/A	Yes	
220	7220	1	3	H312		Third Floor Hallway in Element 1 Between Classroom 308 and Classroom 310	Floor	Chipping	23	No	No	N/A	N/A	No	
221	7220	1	3	H312		Third Floor Hallway in Element 1 Between Classroom 308 and Classroom 310	W2	Cracking, Chipping on wall, metal jacket, and radiator covers, Flaking, Spalling, Efflorescence	72	Yes	No	N/A	N/A	Yes	
222	7220	1	3	H312		Third Floor Hallway in Element 1 Between Classroom 308 and Classroom 310	W3	Cracking	4	No	No	N/A	N/A	No	
223	7220	1	3	H312		Third Floor Hallway in Element 1 Between Classroom 308 and Classroom 310	W4	Cracking, Chipping, Efflorescence	42	Yes	No	N/A	N/A	Yes	
224	7220	2	3	H36		Third Floor Hallway in Element 2 Between Classroom 312 and Classroom 314	W1	Chipping on wall, metal jacket, and univent, Flaking	34	No	No	N/A	N/A	No	
225	7220	2	3	H36		Third Floor Hallway in Element 2 Between Classroom 312 and Classroom 314	W3	Cracking, Chipping on wall and metal lockers, Hole	55	No	No	N/A	N/A	No	Concrete block will need to be repaired

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
226	7220	2	3	H36		Third Floor Hallway in Element 2 Between Classroom 312 and Classroom 314	W4	Cracking, Chipping	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
227	7220	2	3	H37		Third Floor Hallway in Element 2 Where Element 1 and Element 2 Meet	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
228	7220	2	3	H37		Third Floor Hallway in Element 2 Where Element 1 and Element 2 Meet	W2	Cracking, Chipping on metal lockers, Hole	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
229	7220	2	3	H37		Third Floor Hallway in Element 2 Where Element 1 and Element 2 Meet	W4	Cracking, Chipping	9	No	No	N/A	N/A	No	Concrete block will need to be repaired
230	7220	1	3	316		Women's Restroom	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
231	7220	1	3	316		Women's Restroom	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
232	7220	1	3	316		Women's Restroom	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
233	7220	1	3	316		Women's Restroom	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
234	7220	1	3	316		Women's Restroom	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
235	7220	1	3	316		Women's Restroom	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
236	7220	1	2	218		Assistant Principal's Office	W1	Chipping	1	No	No	N/A	N/A	No	
237	7220	1	2	218		Assistant Principal's Office	W2	Cracking, Chipping	14	No	No	N/A	N/A	No	
238	7220	1	2	218		Assistant Principal's Office	W3	Hole, paint has been stabilized, Efflorescence	5	Yes	No	N/A	N/A	Yes	
239	7220	1	2	218		Assistant Principal's Office	W4	Efflorescence	1	Yes	No	N/A	N/A	Yes	
240	7220	1	2	207B		Boy's Restroom	Ceiling	Cracking, Spalling, Significant Moisture Damage	24	Yes	No	N/A	N/A	Yes	
241	7220	1	2	207B		Boy's Restroom	Floor	Chipping	40	No	No	N/A	N/A	No	
242	7220	1	2	207B		Boy's Restroom	W2	Cracking, Hole	2	No	No	N/A	N/A	Yes	
243	7220	1	2	207B		Boy's Restroom	W3	Chipping, Flaking on wall and radiator cover	16	No	No	N/A	N/A	No	
244	7220	1	2	207B		Boy's Restroom	W4	Chipping, Spalling, Efflorescence	5	Yes	No	N/A	N/A	Yes	
245	7220	1	2	201		Classroom 201	Ceiling	Flaking	1	No	No	N/A	N/A	No	
246	7220	1	2	201		Classroom 201	W1	Cracking, Chipping, Hole, Staple Holes, Flaking on wall and in air shaft	86	No	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
247	7220	1	2	201		Classroom 201	W2	Cracking, Chipping, Staple Holes	23	No	No	N/A	N/A	Yes	
248	7220	1	2	201		Classroom 201	W3	Chipping on wall, metal jackets, and radiator cover, Flaking on wall and metal pipe	56	No	No	N/A	N/A	No	
249	7220	1	2	201		Classroom 201	W4	Hole, Flaking	7	No	No	N/A	N/A	Yes	
250	7220	1	2	201B		Classroom 201 Closet	Ceiling	Holes, Flaking	4	No	No	N/A	N/A	No	
251	7220	1	2	201A		Classroom 201 Closet	W1	Chipping	1	No	No	N/A	N/A	No	
252	7220	1	2	201B		Classroom 201 Closet	W1	Cracking	10	No	No	N/A	N/A	No	
253	7220	1	2	201A		Classroom 201 Closet	W2	Chipping, Flaking	61	No	No	N/A	N/A	No	
254	7220	1	2	201B		Classroom 201 Closet	W2	Chipping, Flaking, Efflorescence	16	Yes	No	N/A	N/A	Yes	
255	7220	1	2	201A		Classroom 201 Closet	W3	Chipping	7	No	No	N/A	N/A	No	
256	7220	1	2	201B		Classroom 201 Closet	W3	Cracking, Flaking on wall and metal pipe	22	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
257	7220	1	2	201A		Classroom 201 Closet	W4	Chipping	50	No	No	N/A	N/A	No	
258	7220	1	2	201B		Classroom 201 Closet	W4	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
259	7220	1	2	202		Classroom 202	Ceiling	Flaking	1	No	No	N/A	N/A	No	
260	7220	1	2	202		Classroom 202	W1	Cracking, Chipping, Holes, Flaking in air shaft	31	No	No	N/A	N/A	Yes	
261	7220	1	2	202		Classroom 202	W2	Chipping, Hole	5	No	No	N/A	N/A	Yes	
262	7220	1	2	202		Classroom 202	W3	Chipping on wall and metal jackets, Flaking	12	No	No	N/A	Shelves with stored materials	No	
263	7220	1	2	202		Classroom 202	W4	Chipping	13	No	No	N/A	N/A	No	
264	7220	1	2	202A		Classroom 202 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
265	7220	1	2	202A		Classroom 202 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
266	7220	1	2	202A		Classroom 202 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
267	7220	1	2	202A		Classroom 202 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
268	7220	1	2	202A		Classroom 202 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
269	7220	1	2	202A		Classroom 202 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
270	7220	1	2	203		Classroom 203	Ceiling	Flaking	1	No	No	N/A	N/A	No	
271	7220	1	2	203		Classroom 203	W1	Cracking, Chipping, Hole, Staple Holes, Flaking in air shaft, Efflorescence in air shaft	64	Yes	No	N/A	Posters	Yes	
272	7220	1	2	203		Classroom 203	W2	Chipping, Flaking, Efflorescence	53	Yes	No	N/A	Posters	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
273	7220	1	2	203		Classroom 203	W3	Chipping on wall, metal jackets, and asbestos pipe insulation, Flaking, Efflorescence, Significant Moisture Damage behind radiator	34	Yes	No	N/A	N/A	Yes	
274	7220	1	2	203		Classroom 203	W4	Chipping, Staple Holes	25	No	No	N/A	Posters	Yes	
275	7220	1	2	203A		Classroom 203 Closet	Ceiling	Cracking, Flaking, Efflorescence	5	Yes	No	N/A	N/A	Yes	
276	7220	1	2	203A		Classroom 203 Closet	W1	Chipping	2	No	No	N/A	N/A	No	
277	7220	1	2	203A		Classroom 203 Closet	W2	Cracking, Chipping, Flaking	70	No	No	N/A	N/A	No	
278	7220	1	2	203A		Classroom 203 Closet	W3	Chipping	7	No	No	N/A	N/A	No	
279	7220	1	2	203A		Classroom 203 Closet	W4	Cracking, Chipping, Hole	69	No	No	N/A	N/A	Yes	
280	7220	1	2	206		Classroom 206	Ceiling	Flaking	8	No	No	N/A	N/A	No	
281	7220	1	2	206		Classroom 206	W1	Chipping	30	No	No	N/A	Posters	No	
282	7220	1	2	206		Classroom 206	W3	Chipping on metal pipes, fiberglass pipe insulation, and radiator cover, Flaking, Efflorescence	64	Yes	Debris on windowsills	5	Posters	Yes	
283	7220	1	2	206A		Classroom 206 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
284	7220	1	2	206A		Classroom 206 Closet	W2	Chipping, Hole	6	No	No	N/A	Stored Materials	Yes	
285	7220	1	2	206A		Classroom 206 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
286	7220	1	2	206A		Classroom 206 Closet	W4	Cracking, Chipping	59	No	No	N/A	Stored Materials	No	
287	7220	1	2	207		Classroom 207	Ceiling	Cracking, Flaking on wall and fiberglass pipe insulation, Efflorescence	25	Yes	No	N/A	N/A	Yes	
288	7220	1	2	207		Classroom 207	W1	Cracking, Chipping, Holes, Flaking in air shaft	47	No	No	N/A	N/A	Yes	
289	7220	1	2	207		Classroom 207	W2	Hole, Flaking	4	No	No	N/A	N/A	Yes	
290	7220	1	2	207		Classroom 207	W3	Chipping on wall, radiator cover, and metal pipes, Hole, Flaking, Efflorescence	26	Yes	Debris on windowsills	2	N/A	Yes	
291	7220	1	2	207A		Classroom 207 Closet	Ceiling	Cracking	10	No	No	N/A	N/A	No	
292	7220	1	2	207A		Classroom 207 Closet	W2	Chipping on wall and metal jacket	27	No	No	N/A	N/A	No	
293	7220	1	2	207A		Classroom 207 Closet	W3	Chipping	7	No	No	N/A	N/A	No	
294	7220	1	2	207A		Classroom 207 Closet	W4	Chipping	48	No	No	N/A	N/A	No	
295	7220	1	2	208		Classroom 208	Ceiling	Cracking, Flaking, Efflorescence	4	Yes	No	N/A	N/A	Yes	
296	7220	1	2	208		Classroom 208	W1	Cracking, Chipping, Flaking, Efflorescence in air shaft	59	Yes	No	N/A	N/A	Yes	
297	7220	1	2	208		Classroom 208	W2	Chipping, Hole	26	No	No	N/A	N/A	Yes	
298	7220	1	2	208		Classroom 208	W3	Chipping on wall, radiator cover, and metal pipe, Flaking, Efflorescence	36	Yes	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
299	7220	1	2	208		Classroom 208	W4	Chipping, Flaking, Efflorescence	41	Yes	No	N/A	N/A	Yes	
300	7220	1	2	208A		Classroom 208 Closet	Ceiling	Flaking, Efflorescence	9	Yes	No	N/A	N/A	Yes	
301	7220	1	2	208B		Classroom 208 Closet	W1	Cracking, Chipping, Efflorescence	46	No	Debris on windowsills	2	N/A	No	
302	7220	1	2	208A		Classroom 208 Closet	W2	Cracking, Chipping, Flaking, Efflorescence	53	Yes	No	N/A	N/A	Yes	
303	7220	1	2	208B		Classroom 208 Closet	W2	Efflorescence	10	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
304	7220	1	2	208A		Classroom 208 Closet	W3	Chipping	13	No	No	N/A	N/A	No	
305	7220	1	2	208B		Classroom 208 Closet	W3	Cracking, Flaking	30	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials
306	7220	1	2	208A		Classroom 208 Closet	W4	Chipping	34	No	No	N/A	N/A	No	
307	7220	1	2	208B		Classroom 208 Closet	W4	Chipping	2	No	No	N/A	N/A	No	
308	7220	1	2	209		Classroom 209	Ceiling	Holes, paint has been stabilized, Flaking	6	No	No	N/A	N/A	Yes	
309	7220	1	2	209		Classroom 209	W1	Cracking, Chipping, Flaking in air shaft	31	No	No	N/A	Tables with computers	No	
310	7220	1	2	209		Classroom 209	W2	Chipping, Flaking	6	No	No	N/A	Tables with computers	No	
311	7220	1	2	209		Classroom 209	W3	Cracking, Chipping on wall, metal pipe, and fiberglass pipe insulation, Efflorescence	18	Yes	Debris on windowsills	5	Tables with computers	Yes	
312	7220	1	2	209		Classroom 209	W4	Chipping, Hole	10	No	No	N/A	Tables with computers	Yes	
313	7220	1	2	209A		Classroom 209 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
314	7220	1	2	209A		Classroom 209 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
315	7220	1	2	209A		Classroom 209 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
316	7220	1	2	209A		Classroom 209 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
317	7220	1	2	209A		Classroom 209 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
318	7220	1	2	209A		Classroom 209 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
319	7220	2	2	211		Classroom 211	Ceiling	Flaking	20	No	No	N/A	N/A	No	
320	7220	2	2	211		Classroom 211	W1	Chipping on wall and doorframe	74	No	No	N/A	N/A	No	
321	7220	2	2	211		Classroom 211	W2	Chipping on wall and chalkboard ledge	11	No	No	N/A	N/A	No	
322	7220	2	2	211		Classroom 211	W3	Chipping on wall, univent, and built in shelves, Flaking on metal jacket	109	No	No	N/A	N/A	No	
323	7220	2	2	211		Classroom 211	W4	Chipping on wall and chalkboard ledge	11	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
324	7220	2	2	211A		Classroom 211 Closet	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
325	7220	2	2	211B		Classroom 211 Closet	W1	Chipping on doorframe	8	No	No	N/A	N/A	No	
326	7220	2	2	211A		Classroom 211 Closet	W2	Cracking	8	No	No	N/A	N/A	No	Concrete block will need to be repaired
327	7220	2	2	211A		Classroom 211 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
328	7220	2	2	211B		Classroom 211 Closet	W3	Cracking	10	No	No	N/A	N/A	No	Concrete block will need to be repaired
329	7220	2	2	211A		Classroom 211 Closet	W4	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
330	7220	2	2	212		Classroom 212	Ceiling	Flaking	3	No	No	N/A	N/A	No	
331	7220	2	2	212		Classroom 212	W1	Cracking, Chipping on wall and doorframe	90	No	No	N/A	N/A	No	Concrete block will need to be repaired
332	7220	2	2	212		Classroom 212	W2	Chipping on chalkboard ledge, Hole	11	No	No	N/A	N/A	No	
333	7220	2	2	212		Classroom 212	W3	Chipping on wall, univent, built in shelves, metal jacket and asbestos pipe insulation, Hole	107	No	No	N/A	N/A	No	Concrete block will need to be repaired
334	7220	2	2	212		Classroom 212	W4	Cracking, Chipping on chalkboard ledge	12	No	No	N/A	N/A	No	Concrete block will need to be repaired
335	7220	2	2	212C		Classroom 212 Closet	Floor	Debris	N/A	No	Debris	2	N/A	No	
336	7220	2	2	212B		Classroom 212 Closet	W1	Chipping on doorframe	13	No	No	N/A	N/A	No	
337	7220	2	2	212C		Classroom 212 Closet	W1	Chipping on doorframe	16	No	No	N/A	N/A	No	
338	7220	2	2	212C		Classroom 212 Closet	W2	Cracking	2	No	No	N/A	N/A	No	Concrete block will need to be repaired
339	7220	2	2	212C		Classroom 212 Closet	W3	Debris	N/A	No	Debris on shelf	2	N/A	No	
340	7220	2	2	212B		Classroom 212 Closet	W4	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
341	7220	2	2	212C		Classroom 212 Closet	W4	Cracking	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
342	7220	2	2	213		Classroom 213	Ceiling	Flaking	16	No	No	N/A	N/A	No	
343	7220	2	2	213		Classroom 213	W1	Chipping on wall and doorframe	64	No	No	N/A	N/A	No	
344	7220	2	2	213		Classroom 213	W2	Chipping on wall, chalkboard ledge, and metal pipe	27	No	No	N/A	N/A	No	
345	7220	2	2	213		Classroom 213	W3	Chipping on wall, univent, built in shelves, and metal jacket	103	No	No	N/A	N/A	No	
346	7220	2	2	213		Classroom 213	W4	Chipping on wall and chalkboard ledge, Flaking	37	No	No	N/A	N/A	No	
347	7220	2	2	213D		Classroom 213 Closet	W1	Chipping on doorframe	18	No	No	N/A	N/A	No	
348	7220	2	2	213D		Classroom 213 Closet	W2	Cracking, Chipping	10	No	No	N/A	N/A	No	Concrete block will need to be repaired
349	7220	2	2	213D		Classroom 213 Closet	W3	Cracking, Chipping on asbestos pipe insulation	5	No	No	N/A	N/A	No	Concrete block will need to be repaired
350	7220	2	2	213D		Classroom 213 Closet	W4	Chipping	1	No	No	N/A	N/A	No	
351	7220	1	2	210		Computer Room	Ceiling	Hole, Flaking	21	No	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
352	7220	1	2	210		Computer Room	W1	Cracking, Chipping	18	No	No	N/A	Tables with computers	No	
353	7220	1	2	210		Computer Room	W2	Chipping	3	No	No	N/A	Tables with computers	No	
354	7220	1	2	210		Computer Room	W3	Chipping on radiators, Flaking on wall and metal pipe, Efflorescence	48	Yes	Debris on windowsills	7	Tables with computers	Yes	
355	7220	1	2	210		Computer Room	W4	N/A	N/A	No	No	N/A	Tables with computers	No	Limited inspection due to stored materials
356	7220	1	2	S01		Entrance Stairs Second Floor	Ceiling	Cracking, Efflorescence	4	Yes	No	N/A	N/A	Yes	
357	7220	1	2	S01		Entrance Stairs Second Floor	Floor	Chipping on stairs and railings	90	No	No	N/A	N/A	No	
358	7220	1	2	S01		Entrance Stairs Second Floor	W1	Chipping on doors and doorframe	37	No	No	N/A	N/A	No	
359	7220	1	2	S01		Entrance Stairs Second Floor	W2	Cracking, Chipping, Flaking	27	No	No	N/A	N/A	No	
360	7220	1	2	S01		Entrance Stairs Second Floor	W3	Chipping	1	No	No	N/A	N/A	No	
361	7220	1	2	S01		Entrance Stairs Second Floor	W4	Chipping, Flaking, Efflorescence	25	Yes	No	N/A	N/A	Yes	
362	7220	1	2	205C		Girl's Restroom	Ceiling	Cracking, Chipping, Flaking	9	No	No	N/A	N/A	No	
363	7220	1	2	205C		Girl's Restroom	W2	Cracking, Chipping, Efflorescence	13	Yes	No	N/A	N/A	Yes	
364	7220	1	2	205C		Girl's Restroom	W3	Chipping, Efflorescence	7	Yes	No	N/A	N/A	Yes	
365	7220	1	2	205C		Girl's Restroom	W4	Cracking, Chipping	23	No	No	N/A	N/A	No	
366	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	Ceiling	Flaking	40	No	No	N/A	N/A	No	
367	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	Floor	N/A	N/A	No	Paint chips	5	N/A	No	
368	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	W1	Flaking	10	No	Paint chips on shelves	5	Built in shelves	No	
369	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	W2	Cracking	4	No	No	N/A	Built in shelves	No	
370	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	W3	Flaking	40	No	Paint chips on shelves	20	Built in shelves	No	
371	7220	1	2	H29A		Hallway Closet Adj. to Classroom 201	W4	Flaking	50	No	Paint chips on shelves	20	Built in shelves	No	
372	7220	1	2	205		IMC Library	Ceiling	Flaking, Efflorescence above windows	12	Yes	No	N/A	N/A	Yes	
373	7220	1	2	205		IMC Library	W1	Cracking, Chipping	6	No	No	N/A	N/A	No	
374	7220	1	2	205		IMC Library	W3	Cracking, Chipping on radiator, Flaking on wall and behind radiator, Spalling, Efflorescence	38	Yes	Debris on windowsills	12	N/A	Yes	
375	7220	1	2	205E		IMC Library Closet In The Back North East West Side Of The Classroom	W2	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to stored materials

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
376	7220	1	2	205E		IMC Library Closet In The Back North East West Side Of The Classroom	W3	Cracking	2	No	No	N/A	N/A	No	
377	7220	1	2	205D		IMC Library Closet In The Front South Side Near The Entrance Of The Classroom	W1	Chipping, Hole	6	No	No	N/A	N/A	Yes	
378	7220	1	2	205D		IMC Library Closet In The Front South Side Near The Entrance Of The Classroom	W3	Chipping	1	No	No	N/A	Built in shelves	No	
379	7220	1	2	205D		IMC Library Closet In The Front South Side Near The Entrance Of The Classroom	W4	Cracking, Chipping	21	No	No	N/A	N/A	No	
380	7220	1	2	205A		IMC Library Closet In The Front South West Side Of The Classroom	W2	Cracking, Spalling	3	Yes	Debris on windowsills	1	N/A	Yes	This space was inspected as 205B on the floor plan
381	7220	1	2	205A		IMC Library Closet In The Front South West Side Of The Classroom	W3	Cracking	2	No	No	N/A	Cabinets	No	This space was inspected as 205B on the floor plan
382	7220	1	2	214		Nurse's Office	Ceiling	Flaking	10	No	No	N/A	N/A	No	
383	7220	1	2	214		Nurse's Office	Floor	N/A	N/A	No	Paint Chips	8	N/A	No	
384	7220	1	2	214		Nurse's Office	W1	Chipping on door and doorframe	18	No	No	N/A	Refrigerator	No	
385	7220	1	2	214		Nurse's Office	W2	Chipping on wall, built in wood cabinet, and wood cove base, Flaking on metal jackets and metal pipe	43	No	No	N/A	Cabinets	No	
386	7220	1	2	214		Nurse's Office	W3	Chipping on wood cove base, Flaking	4	No	No	N/A	Furniture	No	
387	7220	1	2	214		Nurse's Office	W4	Chipping on wall, wood cove base, and radiator, Flaking on wall, windowframes, metal pipe, and metal jackets, Efflorescence	62	Yes	No	N/A	Furniture	Yes	
388	7220	1	2	214A		Nurse's Restroom	Ceiling	Cracking	6	No	No	N/A	N/A	No	
389	7220	1	2	214A		Nurse's Restroom	W1	Cracking, Chipping on wall, door, and doorframe	29	No	No	N/A	N/A	No	
390	7220	1	2	214A		Nurse's Restroom	W2	Flaking on metal pipe	6	No	No	N/A	N/A	No	
391	7220	1	2	214A		Nurse's Restroom	W3	Cracking	10	No	No	N/A	N/A	No	
392	7220	1	2	214A		Nurse's Restroom	W4	Cracking, Chipping on wall, radiator, and windowframe, Flaking on metal jacket	34	No	No	N/A	N/A	No	
393	7220	1	2	219		Room inside Assistant Principal's Office	Ceiling	Holes, paint has been stabilized, Flaking	4	No	No	N/A	N/A	Yes	
394	7220	1	2	219		Room inside Assistant Principal's Office	W1	Cracking, Chipping, Flaking	10	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
395	7220	1	2	219		Room inside Assistant Principal's Office	W3	Cracking	20	No	No	N/A	N/A	No	
396	7220	1	2	219		Room inside Assistant Principal's Office	W4	Cracking	50	No	No	N/A	N/A	No	
397	7220	1	2	H210		Second Floor Hallway	Ceiling	Cracking, Chipping, Flaking, Efflorescence	54	Yes	No	N/A	N/A	Yes	
398	7220	1	2	H210		Second Floor Hallway	Floor	Chipping	51	No	No	N/A	N/A	No	
399	7220	1	2	H210		Second Floor Hallway	W1	Cracking, Chipping on wall and radiator covers, Holes	29	No	No	N/A	N/A	Yes	
400	7220	1	2	H210		Second Floor Hallway	W3	Cracking, Chipping on wall and metal pipe, Hole, Spalling, Efflorescence	22	Yes	No	N/A	N/A	Yes	
401	7220	1	2	H29		Second Floor Hallway in Element 1 Between Classroom 201 and Classroom 203	Ceiling	Flaking	2	No	No	N/A	N/A	No	
402	7220	1	2	H29		Second Floor Hallway in Element 1 Between Classroom 201 and Classroom 203	Floor	Chipping	23	No	No	N/A	N/A	No	
403	7220	1	2	H29		Second Floor Hallway in Element 1 Between Classroom 201 and Classroom 203	W2	Cracking, Chipping	8	No	No	N/A	N/A	No	
404	7220	1	2	H29		Second Floor Hallway in Element 1 Between Classroom 201 and Classroom 203	W3	Flaking, Efflorescence	7	Yes	No	N/A	N/A	Yes	
405	7220	1	2	H29		Second Floor Hallway in Element 1 Between Classroom 201 and Classroom 203	W4	Cracking, Chipping	9	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
406	7220	1	2	H211		Second Floor Hallway in Element 1 Between Classroom 208 and Classroom 210	Floor	Chipping	16	No	No	N/A	N/A	No	
407	7220	1	2	H211		Second Floor Hallway in Element 1 Between Classroom 208 and Classroom 210	W1	Hole	1	No	No	N/A	N/A	Yes	
408	7220	1	2	H211		Second Floor Hallway in Element 1 Between Classroom 208 and Classroom 210	W2	Cracking, Chipping on wall, radiator cover, and metal jackets, Flaking, Spalling, Efflorescence	37	Yes	No	N/A	N/A	Yes	
409	7220	1	2	H211		Second Floor Hallway in Element 1 Between Classroom 208 and Classroom 210	W3	Chipping, Flaking	3	No	No	N/A	N/A	No	
410	7220	1	2	H211		Second Floor Hallway in Element 1 Between Classroom 208 and Classroom 210	W4	Cracking, Chipping	4	No	No	N/A	N/A	No	
411	7220	1	2	S22		Stairs Second Floor	Ceiling	Flaking	2	No	No	N/A	N/A	No	
412	7220	1	2	S22		Stairs Second Floor	Floor	Chipping on stairs and railings	156	No	No	N/A	N/A	No	
413	7220	1	2	S22		Stairs Second Floor	W1	Chipping on doors and doorframe	27	No	No	N/A	N/A	No	
414	7220	1	2	S22		Stairs Second Floor	W2	Chipping, Flaking	7	No	No	N/A	N/A	No	
415	7220	1	2	S22		Stairs Second Floor	W4	Chipping, Flaking	8	No	No	N/A	N/A	No	
416	7220	1	2	216		Storage Closet across from Classroom 205	W1	Chipping	5	No	No	N/A	Stored Materials	No	
417	7220	1	2	216		Storage Closet across from Classroom 205	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
418	7220	1	2	216		Storage Closet across from Classroom 205	W3	Chipping	1	No	No	N/A	Stored Materials	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
419	7220	1	2	216		Storage Closet across from Classroom 205	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
420	7220	1	2	215		Storage Closet across from Classroom 207	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
421	7220	1	2	215		Storage Closet across from Classroom 207	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
422	7220	1	2	215		Storage Closet across from Classroom 207	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
423	7220	1	2	215		Storage Closet across from Classroom 207	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
424	7220	1	2	215		Storage Closet across from Classroom 207	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
425	7220	1	2	215		Storage Closet across from Classroom 207	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
426	7220	2	2	214		Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
427	7220	2	2	214		Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
428	7220	2	2	214		Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
429	7220	2	2	214		Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
430	7220	2	2	214		Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
431	7220	2	2	214		Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
432	7220	1	2	217		Teacher's Lounge	Ceiling	Holes, paint has been stabilized	3	No	No	N/A	N/A	No	
433	7220	1	2	217		Teacher's Lounge	W1	Cracking, Chipping	7	No	No	N/A	N/A	No	
434	7220	1	2	217		Teacher's Lounge	W2	Chipping	2	No	No	N/A	N/A	No	
435	7220	1	2	217		Teacher's Lounge	W3	Cracking, Chipping on radiator	4	No	No	N/A	N/A	No	
436	7220	1	2	217A		Teacher's Lounge Closet	W1	Chipping, Hole	3	No	No	N/A	N/A	No	
437	7220	1	2	217A		Teacher's Lounge Closet	W2	Chipping on radiator	3	No	No	N/A	N/A	No	
438	7220	1	2	217A		Teacher's Lounge Closet	W4	Chipping, Spalling	3	Yes	No	N/A	N/A	Yes	
439	7220	1	1	120		Auditorium	Ceiling	Flaking, Spalling	12	Yes	No	N/A	N/A	Yes	Plaster is assumed asbestos
440	7220	1	1	120		Auditorium	W1	Cracking, Chipping, Hole	28	No	No	N/A	N/A	Yes	
441	7220	1	1	120		Auditorium	W2	Chipping on wall, doors, doorframes, and windowsills, Flaking, Spalling	82	Yes	No	N/A	N/A	Yes	
442	7220	1	1	120		Auditorium	W4	Cracking, Chipping on wall, doors, doorframes, and windowsills, Hole, Flaking, Spalling	109	Yes	No	N/A	N/A	Yes	
443	7220	1	1	120A		Auditorium Stage	Ceiling	Chipping	2	No	No	N/A	N/A	No	Plaster is assumed asbestos

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
444	7220	1	1	120A		Auditorium Stage	Floor	Debris	N/A	No	Debris on floor and stored materials	20	N/A	No	
445	7220	1	1	120A		Auditorium Stage	W1	Hole	1	No	No	N/A	N/A	Yes	
446	7220	1	1	120A		Auditorium Stage	W2	Cracking, Chipping, Hole, Efflorescence	31	Yes	No	N/A	N/A	Yes	
447	7220	1	1	120A		Auditorium Stage	W3	Hole, Efflorescence	151	Yes	No	N/A	N/A	Yes	
448	7220	1	1	120A		Auditorium Stage	W4	Cracking, Chipping	22	No	No	N/A	N/A	No	
449	7220	1	1	107B		Boy's Restroom	Ceiling	Flaking, Efflorescence	35	Yes	No	N/A	N/A	Yes	
450	7220	1	1	107B		Boy's Restroom	Floor	Chipping	82	No	No	N/A	N/A	No	
451	7220	1	1	107B		Boy's Restroom	W1	Cracking	6	No	No	N/A	N/A	No	
452	7220	1	1	107B		Boy's Restroom	W2	Hole, Flaking, Efflorescence	14	Yes	No	N/A	N/A	Yes	
453	7220	1	1	107B		Boy's Restroom	W3	Flaking on radiator cover, Efflorescence	15	Yes	No	N/A	N/A	Yes	
454	7220	1	1	107B		Boy's Restroom	W4	Efflorescence	31	Yes	No	N/A	N/A	Yes	
455	7220	1	1	101		Classroom 101	Ceiling	Flaking	5	No	No	N/A	N/A	No	
456	7220	1	1	101		Classroom 101	W1	Cracking, Chipping, Flaking on wall and in air shaft	42	No	No	N/A	N/A	No	
457	7220	1	1	101		Classroom 101	W2	Cracking, Chipping, Holes	6	No	No	N/A	N/A	No	
458	7220	1	1	101		Classroom 101	W3	Chipping on wall, metal jackets, metal pipe, and radiator cover, Flaking, Significant Moisture Damage	50	Yes	No	N/A	N/A	Yes	
459	7220	1	1	101		Classroom 101	W4	Cracking, Chipping, Hole, Flaking, Efflorescence	30	Yes	No	N/A	N/A	Yes	
460	7220	1	1	101B		Classroom 101 Closet	W1	Chipping	1	No	No	N/A	N/A	No	
461	7220	1	1	101B		Classroom 101 Closet	W2	Chipping	2	No	No	N/A	N/A	No	
462	7220	1	1	101C		Classroom 101 Closet	W2	Cracking	4	No	No	N/A	Built in shelves with stored materials	No	
463	7220	1	1	101C		Classroom 101 Closet	W3	Hole	1	No	No	N/A	Built in shelves with stored materials	Yes	
464	7220	1	1	101B		Classroom 101 Closet	W4	Chipping, Hole	9	No	No	N/A	N/A	Yes	
465	7220	1	1	101C		Classroom 101 Closet	W4	Cracking, Flaking	11	No	No	N/A	Stored Materials	No	
466	7220	1	1	101A		Classroom 101 Restroom	Ceiling	Flaking	1	No	No	N/A	N/A	No	
467	7220	1	1	101A		Classroom 101 Restroom	W1	Cracking	3	No	No	N/A	N/A	No	
468	7220	1	1	101A		Classroom 101 Restroom	W2	Chipping on radiator cover	5	No	No	N/A	N/A	No	
469	7220	1	1	101A		Classroom 101 Restroom	W3	Cracking, Chipping on metal pipe, Flaking on wall and metal pipe	14	No	No	N/A	N/A	No	
470	7220	1	1	102		Classroom 102	Ceiling	Flaking	8	No	No	N/A	N/A	No	
471	7220	1	1	102		Classroom 102	Floor	Debris	N/A	No	Debris along wall 3	8	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
472	7220	1	1	102		Classroom 102	W1	Cracking, Chipping, Flaking in air shaft	16	No	No	N/A	Posters, Stored Materials	No	
473	7220	1	1	102		Classroom 102	W2	Cracking, Chipping	3	No	No	N/A	N/A	No	
474	7220	1	1	102		Classroom 102	W3	Chipping on radiator cover, Efflorescence on wall and behind radiator	62	Yes	Debris on windowsills	6	Cabinets	Yes	
475	7220	1	1	102		Classroom 102	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
476	7220	1	1	102B		Classroom 102 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
477	7220	1	1	102A		Classroom 102 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
478	7220	1	1	102B		Classroom 102 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
479	7220	1	1	102A		Classroom 102 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
480	7220	1	1	102B		Classroom 102 Closet	W1	Cracking	10	No	No	N/A	Stored Materials	No	
481	7220	1	1	102A		Classroom 102 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
482	7220	1	1	102B		Classroom 102 Closet	W2	Cracking	20	No	No	N/A	Stored Materials	No	
483	7220	1	1	102A		Classroom 102 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
484	7220	1	1	102B		Classroom 102 Closet	W3	Cracking	30	No	No	N/A	Stored Materials	No	
485	7220	1	1	102A		Classroom 102 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
486	7220	1	1	102B		Classroom 102 Closet	W4	Cracking	30	No	No	N/A	Stored Materials	No	
487	7220	1	1	102A		Classroom 102 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
488	7220	1	1	103		Classroom 103	Ceiling	Cracking, Flaking, Efflorescence	22	Yes	No	N/A	N/A	Yes	
489	7220	1	1	103		Classroom 103	W1	Chipping, Flaking in air shaft	25	No	No	N/A	Shelf	No	
490	7220	1	1	103		Classroom 103	W2	Flaking, Efflorescence	36	Yes	No	N/A	Posters	Yes	
491	7220	1	1	103		Classroom 103	W3	Cracking, Chipping on wall and metal jackets, Flaking, Efflorescence	49	Yes	No	N/A	Furniture	Yes	
492	7220	1	1	103		Classroom 103	W4	Chipping	3	No	No	N/A	N/A	No	
493	7220	1	1	103B		Classroom 103 Closet	W1	Chipping	4	No	No	N/A	N/A	No	
494	7220	1	1	103B		Classroom 103 Closet	W2	Cracking, Chipping	117	No	No	N/A	N/A	No	
495	7220	1	1	103B		Classroom 103 Closet	W3	Chipping	6	No	No	N/A	N/A	No	
496	7220	1	1	103B		Classroom 103 Closet	W4	Cracking, Chipping	118	No	No	N/A	N/A	No	
497	7220	1	1	103A		Classroom 103 Restroom	Ceiling	Cracking, Flaking, Efflorescence	7	Yes	No	N/A	N/A	Yes	
498	7220	1	1	103A		Classroom 103 Restroom	Floor	Chipping	5	No	Debris in corner of walls 1 and 4	1	N/A	No	
499	7220	1	1	103A		Classroom 103 Restroom	W1	Chipping, Holes, Efflorescence	11	Yes	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
500	7220	1	1	103A		Classroom 103 Restroom	W2	Cracking	1	No	No	N/A	N/A	No	
501	7220	1	1	103A		Classroom 103 Restroom	W3	Chipping, Flaking	11	No	No	N/A	N/A	No	
502	7220	1	1	103A		Classroom 103 Restroom	W4	Cracking, Flaking on metal pipe, Spalling, Efflorescence	18	Yes	No	N/A	N/A	Yes	
503	7220	1	1	104		Classroom 104	Ceiling	Cracking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
504	7220	1	1	104		Classroom 104	Floor	Debris	N/A	No	Debris along wall 3	3	N/A	No	
505	7220	1	1	104		Classroom 104	W1	Cracking, Chipping, Hole, Flaking in air shaft	32	No	No	N/A	Posters	Yes	
506	7220	1	1	104		Classroom 104	W3	Chipping on wall and radiator cover, Flaking on wall, metal pipe, and asbestos pipe insulation, Efflorescence	52	Yes	Debris on windowsills	2	Furniture	Yes	
507	7220	1	1	104		Classroom 104	W4	Chipping, Flaking	16	No	No	N/A	Furniture	No	
508	7220	1	1	104A		Classroom 104 Closet	Ceiling	Chipping on metal pipe	2	No	No	N/A	N/A	Yes	
509	7220	1	1	104A		Classroom 104 Closet	W1	Cracking	1	No	No	N/A	N/A	No	
510	7220	1	1	104A		Classroom 104 Closet	W2	Chipping on wall and metal jacket, Hole	6	No	No	N/A	Cabinet, Stored Materials	Yes	
511	7220	1	1	104A		Classroom 104 Closet	W3	Chipping	13	No	No	N/A	Cabinet, Stored Materials	Yes	
512	7220	1	1	104A		Classroom 104 Closet	W4	Chipping	1	No	No	N/A	N/A	No	
513	7220	1	1	104B		Classroom 104 Restroom	Ceiling	Significant Moisture Damage	25	Yes	No	N/A	N/A	Yes	
514	7220	1	1	104B		Classroom 104 Restroom	W1	Cracking, Chipping, Flaking on wall and metal pipe	9	No	Debris on windowsill	1	N/A	No	
515	7220	1	1	104B		Classroom 104 Restroom	W2	Flaking	3	No	No	N/A	N/A	No	
516	7220	1	1	104B		Classroom 104 Restroom	W3	Chipping on radiator, Flaking	14	No	No	N/A	N/A	No	
517	7220	1	1	104B		Classroom 104 Restroom	W4	Hole	1	No	No	N/A	N/A	No	
518	7220	1	1	105		Classroom 105	Ceiling	Cracking, Efflorescence	13	Yes	No	N/A	N/A	Yes	
519	7220	1	1	105		Classroom 105	W1	Cracking, Chipping, Flaking in air shaft	26	No	No	N/A	Stored Materials	No	
520	7220	1	1	105		Classroom 105	W2	Hole	1	No	No	N/A	N/A	Yes	
521	7220	1	1	105		Classroom 105	W3	Cracking, Chipping, Flaking, Efflorescence	39	Yes	Debris on windowsills	12	Stored Materials	Yes	
522	7220	1	1	105A		Classroom 105 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
523	7220	1	1	105A		Classroom 105 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
524	7220	1	1	105A		Classroom 105 Closet	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
525	7220	1	1	105A		Classroom 105 Closet	W2	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
526	7220	1	1	105A		Classroom 105 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
527	7220	1	1	105A		Classroom 105 Closet	W4	Cracking, Chipping	51	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
528	7220	1	1	106		Classroom 106	Ceiling	Cracking, Flaking, Spalling, Efflorescence	17	Yes	No	N/A	N/A	Yes	
529	7220	1	1	106		Classroom 106	W1	Cracking, Chipping, Flaking in air shaft	44	No	No	N/A	N/A	No	
530	7220	1	1	106		Classroom 106	W3	Chipping on wall, fiberglass pipe insulation, radiator, and metal pipe, Efflorescence	36	Yes	Debris on windowsills	12	N/A	Yes	
531	7220	1	1	106A		Classroom 106 Closet	W1	Chipping	1	No	No	N/A	N/A	No	
532	7220	1	1	106A		Classroom 106 Closet	W2	Chipping, Hole	3	No	No	N/A	Cabinets, Stored Materials	Yes	
533	7220	1	1	106A		Classroom 106 Closet	W3	Cracking, Chipping	30	No	No	N/A	N/A	No	
534	7220	1	1	106A		Classroom 106 Closet	W4	Cracking, Chipping	45	No	No	N/A	N/A	No	
535	7220	1	1	107		Classroom 107	Ceiling	Hole, Efflorescence	6	Yes	No	N/A	N/A	Yes	
536	7220	1	1	107		Classroom 107	W1	Cracking, Chipping, Flaking in air shaft	42	No	No	N/A	Furniture	No	
537	7220	1	1	107		Classroom 107	W2	Cracking, Chipping, Efflorescence	33	Yes	No	N/A	Furniture	Yes	
538	7220	1	1	107		Classroom 107	W3	Cracking, Chipping on wall, radiator cover, and fiberglass pipe insulation, Flaking, Efflorescence	49	Yes	Debris on windowsills	6	Furniture	Yes	
539	7220	1	1	107A		Classroom 107 Closet	W2	Chipping, Flaking on metal jacket	16	No	No	N/A	Stored Materials	No	
540	7220	1	1	107A		Classroom 107 Closet	W3	Cracking, Chipping	11	No	No	N/A	Stored Materials	No	
541	7220	1	1	107A		Classroom 107 Closet	W4	Chipping	7	No	No	N/A	Stored Materials	No	
542	7220	1	1	108		Classroom 108	Ceiling	Holes, Flaking	9	No	No	N/A	N/A	Yes	
543	7220	1	1	108		Classroom 108	W1	Cracking, Chipping, Flaking on wall and in air shaft	30	No	No	N/A	N/A	No	
544	7220	1	1	108		Classroom 108	W2	Cracking, Chipping, Hole, Flaking	13	No	No	N/A	Table	Yes	
545	7220	1	1	108		Classroom 108	W3	Chipping on wall, radiator covers, and metal pipes, Hole, Flaking, Efflorescence	58	Yes	Debris on windowsills	2	Cabinet, Furniture, Stored Materials	Yes	
546	7220	1	1	108		Classroom 108	W4	Chipping, Flaking, Efflorescence	44	Yes	No	N/A	Furniture, Cabinet	Yes	
547	7220	1	1	108B		Classroom 108 Closet	Ceiling	Efflorescence	1	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
548	7220	1	1	108B		Classroom 108 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
549	7220	1	1	108B		Classroom 108 Closet	W1	Cracking, Efflorescence	18	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
550	7220	1	1	108B		Classroom 108 Closet	W2	Efflorescence	18	Yes	Debris on shelves	20	Stored Materials	Yes	Limited inspection due to stored materials
551	7220	1	1	108A		Classroom 108 Closet	W2	Cracking, Chipping	60	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
552	7220	1	1	108B		Classroom 108 Closet	W3	Cracking, Chipping	2	No	Debris on shelves	5	Stored Materials	No	Limited inspection due to stored materials
553	7220	1	1	108A		Classroom 108 Closet	W3	Cracking	12	No	No	N/A	N/A	No	
554	7220	1	1	108A		Classroom 108 Closet	W4	Chipping, Hole	34	No	No	N/A	N/A	Yes	
555	7220	1	1	108B		Classroom 108 Closet	W4	Cracking, Hole	4	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
556	7220	1	1	109		Classroom 109	Ceiling	Cracking, Hole	2	No	No	N/A	N/A	Yes	
557	7220	1	1	109		Classroom 109	W1	Chipping, Hole	29	No	No	N/A	N/A	Yes	
558	7220	1	1	109		Classroom 109	W2	Chipping, Hole	2	No	No	N/A	Posters	Yes	
559	7220	1	1	109		Classroom 109	W3	Cracking, Chipping on wall, radiator, and metal pipes, Hole behind radiator, Efflorescence	38	Yes	Debris on windowsills	2	N/A	Yes	
560	7220	1	1	109		Classroom 109	W4	Chipping, Hole, Flaking	8	No	No	N/A	Furniture	Yes	
561	7220	1	1	109A		Classroom 109 Closet	W1	Chipping	3	No	No	N/A	N/A	No	
562	7220	1	1	109A		Classroom 109 Closet	W2	Chipping	5	No	No	N/A	N/A	No	
563	7220	1	1	109A		Classroom 109 Closet	W3	Cracking, Chipping	35	No	No	N/A	N/A	No	
564	7220	1	1	109A		Classroom 109 Closet	W4	Cracking, Chipping	59	No	No	N/A	N/A	No	
565	7220	2	1	111		Classroom 111	W1	Cracking, Chipping on wall and doorframe	69	No	No	N/A	N/A	No	Concrete block will need to be repaired
566	7220	2	1	111		Classroom 111	W2	Chipping on chalkboard ledge, Flaking	23	No	No	N/A	N/A	No	
567	7220	2	1	111		Classroom 111	W3	Chipping on wall, metal jacket, univent, and built in shelves	102	No	No	N/A	N/A	No	
568	7220	2	1	111		Classroom 111	W4	Chipping on chalkboard ledge, Holes	20	No	No	N/A	N/A	No	Concrete block will need to be repaired
569	7220	2	1	111B		Classroom 111 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
570	7220	2	1	111B		Classroom 111 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
571	7220	2	1	111A		Classroom 111 Closet	W1	Chipping on doorframe	12	No	No	N/A	N/A	No	
572	7220	2	1	111B		Classroom 111 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
573	7220	2	1	111A		Classroom 111 Closet	W2	Cracking	4	No	No	N/A	N/A	No	Concrete block will need to be repaired
574	7220	2	1	111B		Classroom 111 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
575	7220	2	1	111A		Classroom 111 Closet	W3	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
576	7220	2	1	111B		Classroom 111 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
577	7220	2	1	111A		Classroom 111 Closet	W4	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
578	7220	2	1	111B		Classroom 111 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
579	7220	2	1	112		Classroom 112	W1	Cracking, Chipping on wall and doorframe	41	No	No	N/A	N/A	No	Concrete block will need to be repaired

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
580	7220	2	1	112		Classroom 112	W2	Chipping on wall and chalkboard ledge	22	No	No	N/A	N/A	No	
581	7220	2	1	112		Classroom 112	W3	Chipping on wall, univent, and built in shelves	105	No	No	N/A	N/A	No	
582	7220	2	1	112		Classroom 112	W4	Chipping on wall and chalkboard ledge	21	No	No	N/A	N/A	No	
583	7220	2	1	112A		Classroom 112 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
584	7220	2	1	112A		Classroom 112 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
585	7220	2	1	112A		Classroom 112 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
586	7220	2	1	112A		Classroom 112 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
587	7220	2	1	112A		Classroom 112 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
588	7220	2	1	112A		Classroom 112 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
589	7220	2	1	113		Classroom 113	Ceiling	Flaking	1	No	No	N/A	N/A	No	
590	7220	2	1	113		Classroom 113	W1	Cracking, Chipping on wall and doorframe	60	No	No	N/A	N/A	No	Concrete block will need to be repaired
591	7220	2	1	113		Classroom 113	W2	Chipping on wall, metal pipe, and chalkboard ledge	27	No	No	N/A	N/A	No	
592	7220	2	1	113		Classroom 113	W3	Chipping on wall, univent, and built in shelves	104	No	No	N/A	N/A	No	
593	7220	2	1	113		Classroom 113	W4	Chipping on wall and chalkboard ledge	25	No	No	N/A	N/A	No	
594	7220	2	1	113E		Classroom 113 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
595	7220	2	1	113F		Classroom 113 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
596	7220	2	1	113E		Classroom 113 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
597	7220	2	1	113F		Classroom 113 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
598	7220	2	1	113E		Classroom 113 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
599	7220	2	1	113F		Classroom 113 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
600	7220	2	1	113E		Classroom 113 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
601	7220	2	1	113F		Classroom 113 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
602	7220	2	1	113E		Classroom 113 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
603	7220	2	1	113F		Classroom 113 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
604	7220	2	1	113E		Classroom 113 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
605	7220	2	1	113F		Classroom 113 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
606	7220	1	1	110		Computer Room 110	Ceiling	Cracking	18	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
607	7220	1	1	110		Computer Room 110	W1	Chipping	25	No	No	N/A	Tables with computers	No	
608	7220	1	1	110		Computer Room 110	W2	Chipping, Flaking	17	No	No	N/A	Tables with computers	No	
609	7220	1	1	110		Computer Room 110	W3	Cracking, Chipping on wall and radiator, Efflorescence, Significant Moisture Damage behind radiator	17	Yes	Debris on windowsills	6	Tables with computers	Yes	
610	7220	1	1	110		Computer Room 110	W4	N/A	N/A	No	No	N/A	Tables with computers	No	Limited inspection due to stored materials
611	7220	1	1	110A		Computer Room 110 Closet	W1	Cracking	1	No	No	N/A	N/A	No	
612	7220	1	1	110A		Computer Room 110 Closet	W2	Cracking, Chipping	24	No	No	N/A	Boxes	No	Limited inspection due to boxes
613	7220	1	1	110A		Computer Room 110 Closet	W3	Cracking	30	No	No	N/A	N/A	No	
614	7220	1	1	110B		Computer Room 110 Closet	W3	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
615	7220	1	1	110B		Computer Room 110 Closet	W4	Chipping	1	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
616	7220	1	1	110A		Computer Room 110 Closet	W4	Cracking, Chipping	63	No	No	N/A	Boxes	No	Limited inspection due to boxes
617	7220	1	1	114		Counselors Office Adjacent to Classroom 107	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
618	7220	1	1	114		Counselors Office Adjacent to Classroom 107	W1	Chipping on wall and wood cove base	6	No	No	N/A	Posters	No	
619	7220	1	1	114		Counselors Office Adjacent to Classroom 107	W2	Chipping on wall, wood cove base, and metal jackets	21	No	No	N/A	Posters	No	
620	7220	1	1	114		Counselors Office Adjacent to Classroom 107	W3	Chipping, Flaking	6	No	No	N/A	Furniture	No	
621	7220	1	1	114		Counselors Office Adjacent to Classroom 107	W4	Chipping on wall, radiator, wood cove base, metal pipe, and metal jackets, Flaking, Efflorescence	29	Yes	No	N/A	Furniture	Yes	
622	7220	1	1	S01		Element 1 Front Entrance to School Staircase	Ceiling	Flaking	5	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan
623	7220	1	1	S01		Element 1 Front Entrance to School Staircase	Floor	Chipping on stairs and railings, Flaking	102	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan
624	7220	1	1	S01		Element 1 Front Entrance to School Staircase	W1	Cracking, Chipping on doors and doorframe	30	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan
625	7220	1	1	S01		Element 1 Front Entrance to School Staircase	W2	Chipping, Flaking	20	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
626	7220	1	1	S01		Element 1 Front Entrance to School Staircase	W3	Cracking, Chipping on doors and doorframe	21	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan
627	7220	1	1	S01		Element 1 Front Entrance to School Staircase	W4	Chipping, Flaking	10	No	No	N/A	N/A	No	This space was inspected as S13 on the floor plan
628	7220	1	1	S12		Element 1 South West Staircase	Ceiling	Chipping	8	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
629	7220	1	1	S12		Element 1 South West Staircase	Floor	Chipping on stairs and railings, Flaking	100	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
630	7220	1	1	S12		Element 1 South West Staircase	W1	Chipping on doors and doorframe, Hole	31	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
631	7220	1	1	S12		Element 1 South West Staircase	W2	Chipping, Flaking	22	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
632	7220	1	1	S12		Element 1 South West Staircase	W3	Chipping on doors and doorframe	28	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
633	7220	1	1	S12		Element 1 South West Staircase	W4	Chipping, Flaking	7	No	No	N/A	N/A	No	This space was inspected as S12 on the floor plan
634	7220	1	1	S01		Entrance Stairs First Floor	Ceiling	Flaking	13	No	No	N/A	N/A	No	This space was inspected as S11 on the floor plan
635	7220	1	1	S01		Entrance Stairs First Floor	Floor	Chipping on stairs and railings, Flaking	85	No	No	N/A	N/A	No	This space was inspected as S11 on the floor plan
636	7220	1	1	S01		Entrance Stairs First Floor	W1	Flaking, Significant Moisture Damage	45	Yes	No	N/A	N/A	Yes	This space was inspected as S11 on the floor plan
637	7220	1	1	S01		Entrance Stairs First Floor	W2	Chipping on doors and doorframe	32	No	No	N/A	N/A	No	This space was inspected as S11 on the floor plan
638	7220	1	1	S01		Entrance Stairs First Floor	W3	Chipping on metal jacket, Flaking, Spalling, Efflorescence	75	Yes	No	N/A	N/A	Yes	This space was inspected as S11 on the floor plan
639	7220	1	1	S01		Entrance Stairs First Floor	W4	Chipping on doors, doorframe, and metal jacket, Flaking	58	No	No	N/A	N/A	No	This space was inspected as S11 on the floor plan
640	7220	2	1	H13		First Floor Hallway	W1	Chipping on doorframe	8	No	No	N/A	N/A	No	
641	7220	2	1	H12		First Floor Hallway	W1	Chipping on wall, metal jackets, and univent	24	No	No	N/A	N/A	No	
642	7220	2	1	H12		First Floor Hallway	W2	Chipping	2	No	No	N/A	N/A	No	
643	7220	2	1	H13		First Floor Hallway	W2	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
644	7220	2	1	H12		First Floor Hallway	W3	Cracking, Chipping	26	No	No	N/A	N/A	No	Concrete block will need to be repaired
645	7220	2	1	H12		First Floor Hallway	W4	Cracking	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
646	7220	2	1	H13		First Floor Hallway	W4	Hole	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
647	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	Ceiling	Flaking	20	No	No	N/A	N/A	No	
648	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	Floor	Chipping	11	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
649	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	W1	Hole	1	No	No	N/A	N/A	Yes	
650	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	W2	Cracking, Chipping, Flaking	20	No	No	N/A	N/A	No	
651	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	W3	Flaking	1	No	No	N/A	N/A	No	
652	7220	1	1	H18		First Floor Hallway in Element 1 Between Classroom 101 and Classroom 103	W4	Cracking, Chipping, Flaking, Efflorescence	29	Yes	No	N/A	N/A	Yes	
653	7220	1	1	H17		First Floor Hallway in Element 1 Between Classroom 104 and Classroom 107	Ceiling	Holes, Flaking, Efflorescence	35	Yes	No	N/A	N/A	Yes	
654	7220	1	1	H17		First Floor Hallway in Element 1 Between Classroom 104 and Classroom 107	Floor	Chipping	29	No	No	N/A	N/A	No	
655	7220	1	1	H17		First Floor Hallway in Element 1 Between Classroom 104 and Classroom 107	W1	Cracking, Chipping, Flaking	20	No	No	N/A	N/A	No	
656	7220	1	1	H17		First Floor Hallway in Element 1 Between Classroom 104 and Classroom 107	W4	Cracking, Chipping on wall, electrical panel, radiator covers, and metal pipe, Holes, Flaking, Spalling	44	Yes	No	N/A	N/A	Yes	
657	7220	1	1	H16		First Floor Hallway in Element 1 Between Classroom 110 and Classroom 108	Ceiling	Cracking, Chipping, Holes, Flaking, Efflorescence	15	Yes	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
658	7220	1	1	H16		First Floor Hallway in Element 1 Between Classroom 110 and Classroom 108	Floor	Chipping	15	No	No	N/A	N/A	No	
659	7220	1	1	H16		First Floor Hallway in Element 1 Between Classroom 110 and Classroom 108	W2	Cracking, Chipping on wall, metal jackets, and radiator covers, Flaking, Spalling, Efflorescence	49	Yes	No	N/A	N/A	Yes	
660	7220	1	1	H16		First Floor Hallway in Element 1 Between Classroom 110 and Classroom 108	W3	Chipping, Flaking	2	No	No	N/A	N/A	No	
661	7220	1	1	H16		First Floor Hallway in Element 1 Between Classroom 110 and Classroom 108	W4	Cracking, Chipping on wall and electrical panel, Staple Holes, Flaking	26	No	No	N/A	N/A	Yes	
662	7220	1	1	118		Main Office	Ceiling	Flaking, Efflorescence	35	Yes	No	N/A	N/A	Yes	
663	7220	1	1	118		Main Office	W1	Cracking, Chipping	3	No	No	N/A	N/A	No	
664	7220	1	1	118		Main Office	W2	Cracking, Chipping	12	No	No	N/A	N/A	No	
665	7220	1	1	118		Main Office	W3	Cracking	8	No	Debris on windowsill	1	N/A	No	
666	7220	1	1	118B		Main Office Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
667	7220	1	1	118B		Main Office Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
668	7220	1	1	118A		Main Office Closet	W1	Cracking, Holes	12	No	No	N/A	Shelves with stored materials	Yes	
669	7220	1	1	118B		Main Office Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
670	7220	1	1	118A		Main Office Closet	W2	N/A	N/A	No	No	N/A	Shelves with stored materials	No	Limited inspection due to stored materials
671	7220	1	1	118B		Main Office Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
672	7220	1	1	118A		Main Office Closet	W3	Cracking, Chipping	23	No	No	N/A	Shelves with stored materials	No	
673	7220	1	1	118B		Main Office Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
674	7220	1	1	118A		Main Office Closet	W4	Cracking, Hole	16	No	No	N/A	N/A	Yes	
675	7220	1	1	118B		Main Office Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
676	7220	1	1	119		Principal's Office	Ceiling	Cracking, Flaking, Efflorescence	37	Yes	No	N/A	N/A	Yes	
677	7220	1	1	119		Principal's Office	W1	Hole, paint has been stabilized, Flaking	6	No	No	N/A	N/A	Yes	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
678	7220	1	1	119		Principal's Office	W2	Cracking, Chipping, Flaking	6	No	No	N/A	N/A	No	
679	7220	1	1	119		Principal's Office	W3	Hole, Flaking	4	No	No	N/A	N/A	Yes	
680	7220	1	1	119		Principal's Office	W4	Chipping, Hole, Flaking, Spalling	6	Yes	No	N/A	N/A	Yes	
681	7220	1	1	119A		Principal's Office Restroom	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	
682	7220	1	1	119A		Principal's Office Restroom	W1	Cracking, Spalling	3	Yes	No	N/A	N/A	Yes	
683	7220	1	1	119A		Principal's Office Restroom	W2	Spalling	5	Yes	No	N/A	N/A	Yes	
684	7220	1	1	119A		Principal's Office Restroom	W3	Cracking	2	No	No	N/A	N/A	No	
685	7220	1	1	117		School Police Office	W1	Holes, Flaking on metal pipes	8	No	No	N/A	Furniture	Yes	
686	7220	1	1	117		School Police Office	W2	Cracking	3	No	No	N/A	Furniture	No	
687	7220	1	1	117		School Police Office	W3	Cracking, Chipping	28	No	No	N/A	Furniture	Yes	
688	7220	1	1	117		School Police Office	W4	Chipping, Hole	1	No	No	N/A	Furniture	Yes	
689	7220	1	1	121		Stage Closet Left Side Facing Stage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
690	7220	1	1	121		Stage Closet Left Side Facing Stage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
691	7220	1	1	121		Stage Closet Left Side Facing Stage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
692	7220	1	1	121		Stage Closet Left Side Facing Stage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
693	7220	1	1	121		Stage Closet Left Side Facing Stage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
694	7220	1	1	121		Stage Closet Left Side Facing Stage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
695	7220	1	1	122		Stage Closet Right Side Facing Stage	Ceiling	Flaking, Efflorescence	8	Yes	No	N/A	Stored Materials	Yes	
696	7220	1	1	122		Stage Closet Right Side Facing Stage	Floor	Debris	N/A	No	Debris on floor and stored materials	20	Stored Materials	No	Limited inspection due to stored materials
697	7220	1	1	122		Stage Closet Right Side Facing Stage	W1	Cracking	2	No	No	N/A	Stored Materials	No	
698	7220	1	1	122		Stage Closet Right Side Facing Stage	W2	Chipping, Hole, Flaking on metal duct	9	No	No	N/A	Stored Materials	Yes	
699	7220	1	1	122		Stage Closet Right Side Facing Stage	W3	Efflorescence	27	Yes	No	N/A	Stored Materials	Yes	
700	7220	1	1	122		Stage Closet Right Side Facing Stage	W4	Chipping	6	No	No	N/A	Stored Materials	No	
701	7220	1	1	121A		Stage Restroom Left Side Facing Stage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
702	7220	1	1	121A		Stage Restroom Left Side Facing Stage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
703	7220	1	1	121A		Stage Restroom Left Side Facing Stage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
704	7220	1	1	121A		Stage Restroom Left Side Facing Stage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
705	7220	1	1	121A		Stage Restroom Left Side Facing Stage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
706	7220	1	1	121A		Stage Restroom Left Side Facing Stage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
707	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
708	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
709	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	W1	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
710	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	W2	Spalling	6	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
711	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	W3	Spalling	20	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
712	7220	1	1	122A		Stage Restroom Stage Restroom Right Side Facing Stage	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
713	7220	1	1	S12		Stairs First Floor	Ceiling	Flaking	14	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
714	7220	1	1	S12		Stairs First Floor	Floor	Chipping on stairs and railings	85	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
715	7220	1	1	S12		Stairs First Floor	W1	Chipping, Flaking	37	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
716	7220	1	1	S12		Stairs First Floor	W2	Chipping on doors and doorframe	41	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
717	7220	1	1	S12		Stairs First Floor	W3	Chipping, Flaking	19	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
718	7220	1	1	S12		Stairs First Floor	W4	Chipping on door and metal jackets, Flaking	19	No	No	N/A	N/A	No	This space was inspected as S18 on the floor plan
719	7220	1	1	116		Storage Closet	Ceiling	Holes	40	No	No	N/A	N/A	Yes	
720	7220	1	1	116		Storage Closet	W1	Cracking, Chipping	8	No	No	N/A	Built in shelves with stored materials	No	
721	7220	1	1	116		Storage Closet	W2	N/A	N/A	No	No	N/A	Built in shelves with stored materials	No	Limited inspection due to stored materials

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
722	7220	1	1	116		Storage Closet	W3	Cracking	6	No	No	N/A	Built in shelves with stored materials	No	
723	7220	1	1	116		Storage Closet	W4	Chipping	1	No	No	N/A	Built in shelves with stored materials	No	
724	7220	1	1	115		Women's Restroom	Ceiling	Efflorescence	5	Yes	No	N/A	N/A	Yes	
725	7220	1	1	115		Women's Restroom	W1	Chipping, Flaking on metal jacket, Efflorescence	8	Yes	No	N/A	N/A	Yes	
726	7220	1	1	115		Women's Restroom	W2	Flaking on wall and metal pipe, Efflorescence	7	Yes	No	N/A	N/A	Yes	
727	7220	1	1	115		Women's Restroom	W3	Cracking, Chipping on radiator, Hole behind radiator, Flaking on wall and metal jackets, Efflorescence	20	Yes	No	N/A	N/A	Yes	
728	7220	1	0	3		Art Room	Ceiling	Flaking	4	No	No	N/A	N/A	No	
729	7220	1	0	3		Art Room	Floor	Chipping	50	No	No	N/A	N/A	No	
730	7220	1	0	3		Art Room	W1	Cracking, Chipping, Staple Holes	17	No	No	N/A	N/A	No	
731	7220	1	0	3		Art Room	W2	Chipping, Hole	14	No	No	N/A	N/A	No	
732	7220	1	0	3		Art Room	W3	Chipping on wall and metal jackets, Flaking, Efflorescence	44	Yes	No	N/A	N/A	Yes	
733	7220	1	0	3		Art Room	W4	Flaking, Efflorescence	41	Yes	No	N/A	N/A	Yes	
734	7220	1	0	003A		Art Room Closet	Ceiling	Chipping on metal duct, Holes, Flaking	47	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
735	7220	1	0	003A		Art Room Closet	Floor	N/A	N/A	No	Paint Chips	75	Stored Materials	No	Limited inspection due to stored materials
736	7220	1	0	003A		Art Room Closet	W1	Chipping, Flaking, Efflorescence	29	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
737	7220	1	0	003A		Art Room Closet	W2	Flaking, Efflorescence	15	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
738	7220	1	0	003A		Art Room Closet	W3	Efflorescence	20	Yes	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
739	7220	1	0	003A		Art Room Closet	W4	Chipping	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
740	7220	1	0	H02		Basement Element 1 Hallway Between Classroom 003 and Beginning of Element 2 Hallway	Ceiling	Chipping on metal duct, Flaking on ceiling and metal duct	155	No	No	N/A	N/A	No	
741	7220	1	0	H02		Basement Element 1 Hallway Between Classroom 003 and Beginning of Element 2 Hallway	Floor	Chipping	77	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
742	7220	1	0	H02		Basement Element 1 Hallway Between Classroom 003 and Beginning of Element 2 Hallway	W1	Chipping	7	No	No	N/A	N/A	No	
743	7220	1	0	H02		Basement Element 1 Hallway Between Classroom 003 and Beginning of Element 2 Hallway	W2	Chipping on wall and metal jackets, Flaking, Efflorescence	104	Yes	No	N/A	N/A	No	
744	7220	1	0	H02		Basement Element 1 Hallway Between Classroom 003 and Beginning of Element 2 Hallway	W4	Chipping	7	No	No	N/A	N/A	No	
745	7220	2	0	H00		Basement Element 2 Hallway Where Element 1 and Element 2 Meet	Floor	Chipping	10	No	No	N/A	N/A	No	
746	7220	2	0	H00		Basement Element 2 Hallway Where Element 1 and Element 2 Meet	W1	Chipping on doorframe	6	No	No	N/A	N/A	No	
747	7220	2	0	H00		Basement Element 2 Hallway Where Element 1 and Element 2 Meet	W2	Cracking	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
748	7220	2	0	H00		Basement Element 2 Hallway Where Element 1 and Element 2 Meet	W3	Chipping on doors and doorframe	25	No	No	N/A	N/A	No	
749	7220	2	0	H00		Basement Element 2 Hallway Where Element 1 and Element 2 Meet	W4	Cracking, Chipping	2	No	No	N/A	N/A	No	Concrete block will need to be repaired
750	7220	2	0	H01		Basement Hallway Between Classroom 007 and Classroom 005	W1	Cracking, Chipping on wall, metal jackets, and univent	25	No	No	N/A	N/A	No	Concrete block will need to be repaired
751	7220	2	0	H01		Basement Hallway Between Classroom 007 and Classroom 005	W2	Chipping on wall, doors, and doorframe	20	No	No	N/A	N/A	No	
752	7220	2	0	H01		Basement Hallway Between Classroom 007 and Classroom 005	W3	Cracking, Chipping	6	No	No	N/A	N/A	No	Concrete block will need to be repaired
753	7220	1	0	5		Boy's Restroom	Ceiling	Flaking on ceiling and radiators	45	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
754	7220	1	0	5		Boy's Restroom	Floor	Chipping	100	No	No	N/A	N/A	No	
755	7220	1	0	5		Boy's Restroom	W1	Chipping, Hole, Flaking on metal pipe	10	No	No	N/A	N/A	No	
756	7220	1	0	5		Boy's Restroom	W2	Chipping	3	No	No	N/A	N/A	No	
757	7220	1	0	4		Classroom 004	Floor	Chipping	30	No	No	N/A	N/A	No	
758	7220	1	0	4		Classroom 004	W1	Cracking, Chipping, Flaking	12	No	No	N/A	N/A	No	
759	7220	1	0	4		Classroom 004	W2	Cracking, Chipping, Flaking on metal jacket	31	No	No	N/A	N/A	No	
760	7220	1	0	4		Classroom 004	W3	Cracking, Chipping, Flaking	9	No	No	N/A	N/A	No	
761	7220	1	0	4		Classroom 004	W4	Chipping	2	No	No	N/A	N/A	No	
762	7220	2	0	5		Classroom 005	Ceiling	Flaking	24	No	No	N/A	N/A	No	
763	7220	2	0	5		Classroom 005	Floor	Chipping	32	No	No	N/A	N/A	No	
764	7220	2	0	5		Classroom 005	W1	Chipping on wall, doorframe, asbestos pipe insulation, and metal pipe	91	No	No	N/A	N/A	No	
765	7220	2	0	5		Classroom 005	W2	Chipping	27	No	No	N/A	N/A	No	
766	7220	2	0	5		Classroom 005	W3	Chipping on wall, univent, built in shelves, and metal jacket	53	No	No	N/A	N/A	No	
767	7220	2	0	5		Classroom 005	W4	Chipping on wall and chalkboard ledge	25	No	No	N/A	N/A	No	
768	7220	2	0	NP1		Classroom 005 Restroom	Floor	Chipping	6	No	No	N/A	N/A	No	
769	7220	2	0	NP1		Classroom 005 Restroom	W1	Chipping, Flaking	6	No	No	N/A	N/A	No	
770	7220	2	0	NP1		Classroom 005 Restroom	W2	Chipping	4	No	No	N/A	N/A	No	
771	7220	2	0	NP1		Classroom 005 Restroom	W3	Chipping, Flaking	6	No	No	N/A	N/A	No	
772	7220	2	0	NP1		Classroom 005 Restroom	W4	Chipping, Hole	3	No	No	N/A	N/A	No	Concrete block will need to be repaired
773	7220	2	0	6		Classroom 006	Ceiling	Flaking	400	No	No	N/A	N/A	No	
774	7220	2	0	6		Classroom 006	Floor	Chipping	37	No	No	N/A	N/A	No	
775	7220	2	0	6		Classroom 006	W1	Chipping on wall, door, and doorframe	79	No	No	N/A	N/A	No	
776	7220	2	0	6		Classroom 006	W2	Cracking, Chipping on wall and chalkboard ledge	34	No	No	N/A	N/A	No	
777	7220	2	0	6		Classroom 006	W3	Chipping, Flaking	49	No	No	N/A	N/A	No	
778	7220	2	0	6		Classroom 006	W4	Chipping on wall and chalkboard ledge	30	No	No	N/A	N/A	No	
779	7220	2	0	NP2		Classroom 006 Restroom	W1	Chipping on doorframe, Holes	13	No	No	N/A	N/A	No	
780	7220	2	0	NP2		Classroom 006 Restroom	W2	Chipping	2	No	No	N/A	N/A	No	
781	7220	2	0	NP2		Classroom 006 Restroom	W3	Chipping on metal jacket	3	No	No	N/A	N/A	No	
782	7220	2	0	NP2		Classroom 006 Restroom	W4	Chipping	1	No	No	N/A	N/A	No	
783	7220	2	0	7		Classroom 007	Ceiling	Flaking	800	No	No	N/A	N/A	No	
784	7220	2	0	7		Classroom 007	Floor	Chipping	18	No	Paint chips	8	N/A	No	
785	7220	2	0	7		Classroom 007	W1	Chipping on wall and doorframe	58	No	No	N/A	N/A	No	
786	7220	2	0	7		Classroom 007	W2	Chipping on wall and chalkboard ledge	35	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
787	7220	2	0	7		Classroom 007	W3	Chipping on wall, metal jacket, and built in shelves, Hole, Flaking	50	No	Paint chips on built in shelves	2	N/A	No	
788	7220	2	0	7		Classroom 007	W4	Chipping, Flaking	14	No	No	N/A	N/A	No	
789	7220	2	0	NP3		Classroom 007 Restroom	W1	Chipping on wall and doorframe	18	No	No	N/A	N/A	No	
790	7220	2	0	NP3		Classroom 007 Restroom	W2	Cracking, Chipping, Flaking on metal pipe	15	No	No	N/A	N/A	No	
791	7220	2	0	NP3		Classroom 007 Restroom	W4	Chipping, Holes	3	No	No	N/A	N/A	No	
792	7220	1	0	002A		Classroom 2 Closet	Ceiling	Holes	2	No	No	N/A	N/A	Yes	
793	7220	1	0	002B		Classroom 2 Closet	Floor	Debris	N/A	No	Debris along wall 4	2	N/A	No	
794	7220	1	0	002B		Classroom 2 Closet	W1	Chipping, Flaking, Spalling	11	Yes	No	N/A	N/A	Yes	
795	7220	1	0	002B		Classroom 2 Closet	W2	N/A	N/A	No	No	N/A	Shelf with stored materials	No	Limited inspection due to stored materials
796	7220	1	0	002A		Classroom 2 Closet	W3	N/A	N/A	No	No	N/A	Shelf with stored materials	No	Limited inspection due to stored materials
797	7220	1	0	002A		Classroom 2 Closet	W4	Efflorescence	1	Yes	No	N/A	N/A	Yes	
798	7220	1	0	002B		Classroom 2 Closet	W4	Spalling, Efflorescence	7	Yes	No	N/A	N/A	Yes	
799	7220	1	0	004A		Classroom 4 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
800	7220	1	0	004A		Classroom 4 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
801	7220	1	0	004A		Classroom 4 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
802	7220	1	0	004A		Classroom 4 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
803	7220	1	0	004A		Classroom 4 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
804	7220	1	0	004A		Classroom 4 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
805	7220	2	0	005A		Classroom 5 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
806	7220	2	0	005A		Classroom 5 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
807	7220	2	0	005B		Classroom 5 Closet	W1	Chipping on doorframe	9	No	No	N/A	N/A	No	
808	7220	2	0	005A		Classroom 5 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
809	7220	2	0	005B		Classroom 5 Closet	W2	Cracking	1	No	No	N/A	N/A	No	Concrete block will need to be repaired
810	7220	2	0	005A		Classroom 5 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
811	7220	2	0	005A		Classroom 5 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
812	7220	2	0	005B		Classroom 5 Closet	W4	Cracking, Chipping	6	No	No	N/A	N/A	No	Concrete block will need to be repaired

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
813	7220	2	0	005A		Classroom 5 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
814	7220	2	0	006A		Classroom 6 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
815	7220	2	0	006B		Classroom 6 Closet	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
816	7220	2	0	006A		Classroom 6 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
817	7220	2	0	006B		Classroom 6 Closet	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
818	7220	2	0	006A		Classroom 6 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
819	7220	2	0	006B		Classroom 6 Closet	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
820	7220	2	0	006A		Classroom 6 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
821	7220	2	0	006B		Classroom 6 Closet	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
822	7220	2	0	006A		Classroom 6 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
823	7220	2	0	006B		Classroom 6 Closet	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
824	7220	2	0	006A		Classroom 6 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
825	7220	2	0	006B		Classroom 6 Closet	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
826	7220	2	0	007D		Classroom 7 Closet	Floor	Chipping	7	No	No	N/A	N/A	No	
827	7220	2	0	007D		Classroom 7 Closet	W1	Chipping on doorframe	20	No	No	N/A	N/A	No	
828	7220	2	0	007D		Classroom 7 Closet	W2	Cracking, Flaking	21	No	No	N/A	N/A	No	Concrete block will need to be repaired
829	7220	1	0	1		Classroom B1	Floor	Chipping	30	No	No	N/A	N/A	No	
830	7220	1	0	1		Classroom B1	W1	Chipping	3	No	No	N/A	N/A	No	
831	7220	1	0	1		Classroom B1	W2	Cracking, Chipping	10	No	No	N/A	N/A	No	
832	7220	1	0	1		Classroom B1	W3	Chipping, Hole, Flaking, Efflorescence	25	Yes	No	N/A	N/A	Yes	
833	7220	1	0	1		Classroom B1	W4	Cracking, Flaking on metal duct, Spalling	6	Yes	No	N/A	N/A	Yes	
834	7220	1	0	2		Classroom B2	Ceiling	Cracking	4	No	No	N/A	N/A	No	
835	7220	1	0	2		Classroom B2	Floor	Chipping	5	No	No	N/A	N/A	No	
836	7220	1	0	2		Classroom B2	W1	Cracking, Chipping on wall and wood cove base	11	No	No	N/A	Furniture	No	
837	7220	1	0	2		Classroom B2	W2	Spalling	34	Yes	Debris on windowsills	2	Furniture	Yes	Limited inspection due to stored materials
838	7220	1	0	2		Classroom B2	W3	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored materials
839	7220	1	0	2		Classroom B2	W4	Cracking, Chipping on wood cove base	8	No	No	N/A	Furniture	No	
840	7220	1	0	S01		Entrance Stairs Basement	Floor	Chipping	2	No	No	N/A	N/A	No	
841	7220	1	0	S01		Entrance Stairs Basement	W2	Flaking	1	No	No	N/A	N/A	No	

Carnell -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
842	7220	1	0	S01		Entrance Stairs Basement	W3	Cracking, Chipping on doors and doorframe, Flaking	36	No	No	N/A	N/A	No	
843	7220	1	0	S01		Entrance Stairs Basement	W4	Chipping	1	No	No	N/A	N/A	No	
844	7220	1	0	B2		Girl's Restroom	Ceiling	Flaking on ceiling and radiators	48	No	No	N/A	N/A	No	
845	7220	1	0	B2		Girl's Restroom	Floor	Chipping	100	No	No	N/A	N/A	No	
846	7220	1	0	B2		Girl's Restroom	W1	Chipping, Flaking	5	No	No	N/A	N/A	No	
847	7220	1	0	B2		Girl's Restroom	W2	Chipping	2	No	No	N/A	N/A	No	
848	7220	1	0	B2		Girl's Restroom	W3	Chipping	3	No	No	N/A	N/A	No	
849	7220	1	0	B2		Girl's Restroom	W4	Chipping	7	No	No	N/A	N/A	No	
850	7220	1	0	9		Gym	Ceiling	Holes, Flaking on ceiling, metal pipes, metal ducts, Efflorescence	53	Yes	No	N/A	N/A	Yes	
851	7220	1	0	9		Gym	Floor	Chipping, Flaking on stairs	140	No	No	N/A	N/A	No	
852	7220	1	0	9		Gym	W1	Chipping on metal pipe	8	No	No	N/A	N/A	No	Entrance from girl's side
853	7220	1	0	9		Gym	W2	Chipping on metal pipes and metal duct	20	No	No	N/A	N/A	No	
854	7220	1	0	9		Gym	W3	Chipping on wall and metal pipe	13	No	No	N/A	N/A	No	
855	7220	1	0	9		Gym	W4	Chipping	4	No	No	N/A	N/A	No	
856	7220	1	0	18		Gym Coaches Office	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
857	7220	1	0	18		Gym Coaches Office	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
858	7220	1	0	18		Gym Coaches Office	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
859	7220	1	0	18		Gym Coaches Office	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
860	7220	1	0	18		Gym Coaches Office	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
861	7220	1	0	18		Gym Coaches Office	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
862	7220	1	0	NP4		Gym Storage	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
863	7220	1	0	NP4		Gym Storage	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
864	7220	1	0	NP4		Gym Storage	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
865	7220	1	0	NP4		Gym Storage	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
866	7220	1	0	NP4		Gym Storage	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
867	7220	1	0	NP4		Gym Storage	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
868	7220	1	0	S02		Stairs Basement	W2	Chipping	3	No	No	N/A	N/A	No	
869	7220	1	0	S02		Stairs Basement	W3	Cracking, Chipping on wall, doors, and doorframe	29	No	No	N/A	N/A	No	
870	7220	2	0	8		Storage Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
871	7220	2	0	8		Storage Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
872	7220	2	0	8		Storage Room	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Carnell -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
873	7220	2	0	8		Storage Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
874	7220	2	0	8		Storage Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
875	7220	2	0	8		Storage Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
876	7220	1	0	11		Student Lunch Room	Ceiling	Efflorescence	80	Yes	No	N/A	N/A	Yes	
877	7220	1	0	11		Student Lunch Room	Floor	Chipping	50	No	No	N/A	N/A	No	
878	7220	1	0	11		Student Lunch Room	W1	Chipping, Flaking	15	No	No	N/A	N/A	No	Entrance from double doors
879	7220	1	0	11		Student Lunch Room	W2	Chipping	3	No	No	N/A	N/A	No	
880	7220	1	0	11		Student Lunch Room	W3	Chipping on wall and metal jackets, Flaking on wall and metal pipe	26	No	No	N/A	N/A	No	
881	7220	1	0	11		Student Lunch Room	W4	Chipping on wall and metal pipe	8	No	No	N/A	N/A	No	