

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6010	1	4	402		Classroom 402	W1	Damaged plaster	10	No	None	N/A	None	Yes	
2	6010	1	4	402		Classroom 402	W3	Peeling paint at windows	30	No	None	N/A	None	No	
3	6010	1	4	402		Classroom 402	W4	Peeling and cracking paint	30	No	None	N/A	None	No	
4	6010	1	4	403B		Classroom 403 Storage	Ceiling	No Access							Inspection Required
5	6010	1	4	403B		Classroom 403 Storage	Floor	No Access							Inspection Required
6	6010	1	4	403A		Classroom 403 Storage	W1	No Access							Inspection Required
7	6010	1	4	403A		Classroom 403 Storage	W2	No Access							Inspection Required
8	6010	1	4	403A		Classroom 403 Storage	W3	No Access							Inspection Required
9	6010	1	4	403B		Classroom 403 Storage	W4	No Access							Inspection Required
10	6010	1	4	404		Classroom 404	W1	Peeling paint	5	No	None	N/A	None	No	
11	6010	1	4	404		Classroom 404	W2	Peeling paint on wall and windows	30	No	None	N/A	None	No	
12	6010	1	4	404		Classroom 404	W3	Peeling and cracking paint	30	No	None	N/A	None	No	
13	6010	1	4	404A		Classroom 404 Storage	W1	Cracking paint	3	No	None	N/A	None	No	
14	6010	1	4	404A		Classroom 404 Storage	W2	Cracking paint	2	No	None	N/A	None	No	
15	6010	1	4	404A		Classroom 404 Storage	W4	Holes in plaster wall	3	No	None	N/A	None	Yes	
16	6010	1	4	406		Classroom 406	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
17	6010	1	4	406		Classroom 406	W2	Cracking paint	5	No	None	N/A	None	No	
18	6010	1	4	406		Classroom 406	W3	Peeling and cracking paint - at wall and windows	50	No	None	N/A	None	No	
19	6010	1	4	406A		Classroom 406 Storage	W1	Damaged plaster	3	No	None	N/A	None	Yes	
20	6010	1	4	406A		Classroom 406 Storage	W2	Cracking paint	10	No	None	N/A	None	No	
21	6010	1	4	406A		Classroom 406 Storage	W4	Cracking paint	5	No	None	N/A	None	No	
22	6010	1	4	407		Classroom 407	W3	Peeling paint under the counter	40	No	None	N/A	None	No	
23	6010	1	4	407C		Classroom 407 Storage	Ceiling	No Access							Inspection Required
24	6010	1	4	407C		Classroom 407 Storage	Floor	No Access							Inspection Required
25	6010	1	4	407C		Classroom 407 Storage	W1	No Access							Inspection Required
26	6010	1	4	407A		Classroom 407 Storage	W1	Peeling paint by door	10	No	None	N/A	None	No	
27	6010	1	4	407C		Classroom 407 Storage	W2	No Access							Inspection Required

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
28	6010	1	4	407A		Classroom 407 Storage	W2	Peeling paint and efflorescence along window wall	75	No	None	N/A	None	No	
29	6010	1	4	407C		Classroom 407 Storage	W3	No Access							Inspection Required
30	6010	1	4	407B		Classroom 407 Storage	W3	Peeling paint on pipe	8	No	None	N/A	None	No	
31	6010	1	4	407C		Classroom 407 Storage	W4	No Access							Inspection Required
32	6010	1	4	H422		Elevator Foyer	W3	Efflorescence and damaged plaster at roof door	4	No	None	N/A	None	Yes	
33	6010	1	4	H421		Hallway at Mechanical Room	W3	Efflorescence at window	3	No	None	N/A	None	No	
34	6010	1	4	H421		Hallway at Mechanical Room	W4	Damaged plaster at radiator	3	No	None	N/A	None	Yes	
35	6010	1	4	S420		Stairwell by Mechanical Room	W3	Peeling paint	50	No	None	N/A	None	No	
36	6010	1	4	S420		Stairwell by Mechanical Room	W4	Peeling and cracking paint	5	No	None	N/A	None	No	
37	6010	1	4	S421		Stairwell by Room 406	W2	Crack in plaster wall	3	No	None	N/A	None	No	
38	6010	1	4	S421		Stairwell by Room 406	W3	Cracking paint at window	2	No	None	N/A	None	No	
39	6010	1	3	317C		Book Storage across from Boy's Restroom	Ceiling	Hole in plaster ceiling	5	No	None	N/A	None	Yes	
40	6010	1	3	301		Classroom 301	Ceiling	Cracking paint above window	10	No	None	N/A	None	No	
41	6010	1	3	301		Classroom 301	W1	Crack in plaster wall	15	No	None	N/A	None	No	
42	6010	1	3	301		Classroom 301	W3	Peeling paint on wall, efflorescence above windows	10	No	None	N/A	None	No	
43	6010	1	3	302		Classroom 302	W1	Cracking paint	15	No	None	N/A	None	No	
44	6010	1	3	302		Classroom 302	W3	Peeling and cracking paint on wall, damaged plaster and efflorescence above windows, debris on window sill	30	No	Window sill	2	None	Yes	
45	6010	1	3	302		Classroom 302	W4	Holes in plaster wall	5	No	None	N/A	None	No	
46	6010	1	3	304		Classroom 304	W1	Cracking paint by door	6	No	None	N/A	None	No	
47	6010	1	3	304		Classroom 304	W3	Peeling paint above windows	15	No	None	N/A	None	No	
48	6010	1	3	305		Classroom 305	W3	Severe peeling paint, damaged plaster, efflorescence above windows, debris on window sill	40	No	Window sill	2	None	Yes	
49	6010	1	3	306		Classroom 306	W2	Crack in plaster wall by door	6	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
50	6010	1	3	306		Classroom 306	W3	Severe peeling paint and efflorescence above windows, debris on window sill	40	No	Window sill	2	None	No	
51	6010	1	3	307		Classroom 307	W1	Damaged plaster and peeling paint	2	No	None	N/A	None	Yes	
52	6010	1	3	307		Classroom 307	W2	Damaged plaster and peeling paint	3	No	None	N/A	None	Yes	
53	6010	1	3	307		Classroom 307	W3	Damaged plaster and peeling paint	3	No	None	N/A	None	Yes	
54	6010	1	3	308		Classroom 308	W1	Damaged plaster from contact with chairs along the wall	20	No	None	N/A	None	Yes	
55	6010	1	3	308		Classroom 308	W3	Peeling paint on wall and severe peeling paint above windows	40	No	None	N/A	None	No	
56	6010	1	3	309		Classroom 309	W2	Cracking paint below the blackboard	20	No	None	N/A	None	No	
57	6010	1	3	309		Classroom 309	W3	Damaged plaster, peeling paint, and efflorescence	30	No	None	N/A	None	Yes	
58	6010	1	3	309		Classroom 309	W4	Cracking paint below the blackboard	30	No	None	N/A	None	No	
59	6010	1	3	325		Classroom 325	W3	Peeling paint above windows	10	No	None	N/A	None	No	
60	6010	1	3	326		Classroom 326	W2	Peeling paint below blackboard	20	No	None	N/A	None	No	
61	6010	1	3	326		Classroom 326	W3	Peeling paint on wall and severe peeling paint above windows	40	No	None	N/A	None	No	
62	6010	1	3	326		Classroom 326	W4	Crack in plaster wall below blackboard	4	No	None	N/A	None	No	
63	6010	1	3	327		Classroom 327	W1	Cracking paint	40	No	None	N/A	None	No	
64	6010	1	3	327		Classroom 327	W2	Cracking paint	40	No	None	N/A	None	No	
65	6010	1	3	327		Classroom 327	W3	Peeling paint on wall and above windows	10	No	None	N/A	None	No	
66	6010	1	3	327		Classroom 327	W4	Cracking paint	40	No	None	N/A	None	No	
67	6010	1	3	328		Classroom 328	W3	Damaged plaster and peeling paint above windows	10	No	None	N/A	None	Yes	
68	6010	1	3	318		Girl's Restroom across from Auditorium Balcony	Ceiling	Peeling paint	5	No	None	N/A	None	No	
69	6010	1	3	H33		Hallway at Rooms 301 to 309	W2	Cracking paint	30	No	None	N/A	None	No	
70	6010	1	3	H33		Hallway at Rooms 301 to 309	W4	Cracking paint	50	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
71	6010	1	3	H38		Hallway at Rooms 321 to 329	W4	Peeling paint	25	No	None	N/A	None	No	
72	6010	1	3	H38		Hallway at Rooms 321 to 329	W2	Peeling paint	50	No	None	N/A	None	No	
73	6010	1	3	337		Kitchen	Ceiling	Spalling and cracking paint	5	No	None	N/A	None	No	
74	6010	1	3	337A		Kitchen Office	Ceiling	Crack in plaster ceiling	10	No	None	N/A	None	No	
75	6010	1	3	336		Kitchen Staff Locker Room	Ceiling	Damaged plaster at window	3	No	None	N/A	None	Yes	
76	6010	1	3	335A		Kitchen Storage	W3	Peeling paint on pipe	12	No	None	N/A	None	No	
77	6010	1	3	H34		Main Hallway	W1	Cracking paint	10	No	None	N/A	None	No	
78	6010	1	3	H34		Main Hallway	W3	Peeling paint across from Boy's Restroom	5	No	None	N/A	None	No	
79	6010	1	3	319A		Men's Restroom across from Auditorium Balcony	Ceiling	Peeling and cracking paint	10	No	None	N/A	None	No	
80	6010	1	3	319		Men's Teacher Lounge across from Auditorium Balcony	W3	Peeling paint	5	No	None	N/A	None	No	
81	6010	1	3	321C		Music Room Office #3	W3	Peeling paint on pipe	8	No	None	N/A	None	No	
82	6010	1	3	303		Room 303 Lab Prep Room	W4	Damaged plaster and peeling paint above windows, Peeling paint on pipe	25	No	None	N/A	None	Yes	
83	6010	1	3	315		Room 315 Office next to Office Room 313	W2	Peeling and cracking paint in closet	5	No	None	N/A	None	No	
84	6010	1	3	322A		Room 322A - Office #1	Floor	Debris	4	No	None	N/A	None	No	
85	6010	1	3	322A		Room 322A - Office #1	W3	Severe peeling paint, efflorescence at the top of window, debris on window sill	20	No	Window sill	4	None	No	
86	6010	1	3	322B		Room 322B - Office #2	W1	Damaged plaster and peeling paint	6	No	None	N/A	None	Yes	
87	6010	1	3	322B		Room 322B - Office #2	W2	Damaged plaster, peeling paint and cracking paint	80	No	None	N/A	None	Yes	
88	6010	1	3	322B		Room 322B - Office #2	W3	Peeling and cracking paint	20	No	None	N/A	None	No	
89	6010	1	3	322B		Room 322B - Office #2	W4	Peeling and cracking paint	20	No	None	N/A	None	No	
90	6010	1	3	322C		Room 322C - Office #3	W3	Damaged plaster at window	4	No	None	N/A	None	Yes	
91	6010	1	3	322D		Room 322D - Storage	W3	Peeling paint	3	No	None	N/A	None	No	
92	6010	1	3	323		Room 323 - Music Room	W3	Efflorescence at window	10	No	None	N/A	None	No	ceiling tiles need to be r

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
93	6010	1	3	324		Room 324 - Music Room	W3	Damaged plaster and peeling paint at windows, debris on window sill and music panel	45	No	ow sill and music	10	None	Yes	
94	6010	1	3	331		Room 331 - Kitchen Supply Room	Ceiling	Crack in plaster ceiling	8	No	None	N/A	None	No	
95	6010	1	3	333A		Room 333A - Kitchen and Dry Storage Area	Ceiling	Peeling paint and crack in plaster ceiling	20	No	None	N/A	None	No	
96	6010	1	3	333A		Room 333A - Kitchen and Dry Storage Area	W2	Peeling paint	5	No	None	N/A	None	No	
97	6010	1	3	H35		Shorter Hallway across from Restrooms	W1	Peeling paint	10	No	None	N/A	None	No	
98	6010	1	3	H35		Shorter Hallway across from Restrooms	W2	Peeling paint	20	No	None	N/A	None	No	
99	6010	1	3	H35		Shorter Hallway across from Restrooms	W3	Peeling paint	10	No	None	N/A	None	No	
100	6010	1	3	H35		Shorter Hallway across from Restrooms	W4	Peeling paint	30	No	None	N/A	None	No	
101	6010	1	3	H39A		Shorter Hallway across from Teacher Dining Area	W1	Cracking paint	2	No	None	N/A	None	No	
102	6010	1	3	H39A		Shorter Hallway across from Teacher Dining Area	W2	Peeling and cracking paint	10	No	None	N/A	None	No	
103	6010	1	3	H39A		Shorter Hallway across from Teacher Dining Area	W3	Cracking paint	2	No	None	N/A	None	No	
104	6010	1	3	H39A		Shorter Hallway across from Teacher Dining Area	W4	Damaged plaster and cracking paint	30	No	None	N/A	None	Yes	
105	6010	1	3	S311		Stairwell at Cafeteria	W1	Peeling paint	10	No	None	N/A	None	No	
106	6010	1	3	S311		Stairwell at Cafeteria	W2	Peeling paint	20	No	None	N/A	None	No	
107	6010	1	3	S39Z		Stairwell at Cafeteria on the Kitchen Office Side	Ceiling	Crack in ceiling	5	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
108	6010	1	3	S39Z		Stairwell at Cafeteria on the Kitchen Office Side	W2	Peeling paint	5	No	None	N/A	None	No	
109	6010	1	3	S39Z		Stairwell at Cafeteria on the Kitchen Office Side	W3	Peeling paint	5	No	None	N/A	None	No	
110	6010	1	3	S39Z		Stairwell at Cafeteria on the Kitchen Office Side	W4	Peeling paint	20	No	None	N/A	None	No	
111	6010	1	3	S34		Stairwell at Room 301	Ceiling	Peeling paint and efflorescence	10	No	None	N/A	None	No	
112	6010	1	3	S34		Stairwell at Room 301	W3	Peeling paint and efflorescence	20	No	None	N/A	None	No	
113	6010	1	3	S32		Stairwell next to Room 308	W2	Peeling paint	10	No	None	N/A	None	No	
114	6010	1	3	S32		Stairwell next to Room 308	W3	Peeling paint	10	No	None	N/A	None	No	
115	6010	1	3	S32		Stairwell next to Room 308	W4	Peeling paint	25	No	None	N/A	None	No	
116	6010	1	3	S316		Stairwell next to Room 321	Ceiling	Crack in plaster ceiling	25	No	None	N/A	None	No	
117	6010	1	3	S315		Stairwell next to Room 328	Ceiling	Peeling paint	50	No	None	N/A	None	No	
118	6010	1	3	S315		Stairwell next to Room 328	W2	Damaged plaster and peeling paint	10	No	None	N/A	None	Yes	
119	6010	1	3	S315		Stairwell next to Room 328	W3	Damaged plaster	2	No	None	N/A	None	Yes	
120	6010	1	3	S315		Stairwell next to Room 328	W4	Peeling paint	2	No	None	N/A	None	No	
121	6010	1	3	310		Storage 3-B next to Women's Restroom	Ceiling	No Access							Inspection Required
122	6010	1	3	310		Storage 3-B next to Women's Restroom	Floor	No Access							Inspection Required
123	6010	1	3	310		Storage 3-B next to Women's Restroom	W1	No Access							Inspection Required
124	6010	1	3	310		Storage 3-B next to Women's Restroom	W2	No Access							Inspection Required
125	6010	1	3	310		Storage 3-B next to Women's Restroom	W3	No Access							Inspection Required

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
126	6010	1	3	310		Storage 3-B next to Women's Restroom	W4	No Access							Inspection Required
127	6010	1	3	320		Storage next to Men's Restroom	Ceiling	Cracking paint	20	No	None	N/A	None	No	
128	6010	1	3	320		Storage next to Men's Restroom	W2	Cracking paint	5	No	None	N/A	None	No	
129	6010	1	3	320		Storage next to Men's Restroom	W3	Cracking paint	5	No	None	N/A	None	No	
130	6010	1	3	320		Storage next to Men's Restroom	W4	Cracking paint	5	No	None	N/A	None	No	
131	6010	1	3	317A		Storage next to Room 315	Ceiling	Severe plaster damage	50	No	None	N/A	None	Yes	
132	6010	1	3	317A		Storage next to Room 315	Floor	Debris	20	No	None	N/A	None	No	
133	6010	1	3	330		Storage Room 3-F	Ceiling	Damaged plaster and cracking paint	20	No	None	N/A	None	Yes	
134	6010	1	3	330		Storage Room 3-F	W1	Cracking paint	5	No	None	N/A	None	No	
135	6010	1	3	330		Storage Room 3-F	W3	Severe peeling paint	15	No	None	N/A	None	No	
136	6010	1	3	330D		Storage Room next to Mechanical Room	Ceiling	No Access							Inspection Required
137	6010	1	3	330D		Storage Room next to Mechanical Room	Floor	No Access							Inspection Required
138	6010	1	3	330D		Storage Room next to Mechanical Room	W1	No Access							Inspection Required
139	6010	1	3	330D		Storage Room next to Mechanical Room	W2	No Access							Inspection Required
140	6010	1	3	330D		Storage Room next to Mechanical Room	W3	No Access							Inspection Required
141	6010	1	3	330D		Storage Room next to Mechanical Room	W4	No Access							Inspection Required
142	6010	1	3	332		Teacher Lounge/Dining	Ceiling	Peeling paint on drywall	1	No	None	N/A	None	No	
143	6010	1	3	312		Women's Restroom	Ceiling	Cracking paint	3	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
144	6010	1	2	236A		Boy's Restroom across from the Auditorium	Ceiling	Hole in plaster ceiling	4	No	None	N/A	None	Yes	
145	6010	1	2	202		Classroom 202	W3	Damaged plaster and efflorescence above windows	40	No	None	N/A	None	Yes	
146	6010	1	2	203		Classroom 203	W1	Cracking paint	10	No	None	N/A	None	No	
147	6010	1	2	203		Classroom 203	W3	Peeling paint and efflorescence above windows	20	No	None	N/A	None	No	
148	6010	1	2	204		Classroom 204	W1	Cracking paint	30	No	None	N/A	None	No	
149	6010	1	2	204		Classroom 204	W3	Peeling paint above windows	20	No	None	N/A	None	No	
150	6010	1	2	205		Classroom 205	W1	Cracking paint	30	No	None	N/A	None	No	
151	6010	1	2	205		Classroom 205	W3	Peeling and cracking paint, efflorescence above windows, debris on window sill	40	No	Window Sill	2	None	No	
152	6010	1	2	205		Classroom 205	W4	Cracking paint	50	No	None	N/A	None	No	
153	6010	1	2	206		Classroom 206	W1	Cracking paint	45	No	None	N/A	None	No	
154	6010	1	2	206		Classroom 206	W3	Damaged plaster and peeling paint above windows	20	No	None	N/A	None	Yes	
155	6010	1	2	207		Classroom 207	W1	Cracking paint	15	No	None	N/A	None	No	
156	6010	1	2	207		Classroom 207	W2	Cracking paint	20	No	None	N/A	None	No	
157	6010	1	2	207		Classroom 207	W3	Peeling paint above windows	20	No	None	N/A	None	No	
158	6010	1	2	208		Classroom 208	W3	Peeling paint above windows	20	No	None	N/A	None	No	
159	6010	1	2	209		Classroom 209	W1	Peeling paint	30	No	None	N/A	None	No	
160	6010	1	2	209		Classroom 209	W2	Peeling and cracking paint	30	No	None	N/A	None	No	
161	6010	1	2	209		Classroom 209	W3	Peeling paint on wall and above windows	40	No	None	N/A	None	No	
162	6010	1	2	209		Classroom 209	W4	Holes in plaster wall	5	No	None	N/A	None	Yes	
163	6010	1	2	211		Classroom 211	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
164	6010	1	2	211		Classroom 211	W3	Damaged plaster and peeling paint above windows	20	No	None	N/A	None	Yes	
165	6010	1	2	211A		Classroom 211 Storage/Office	W1	Cracking paint	50	No	None	N/A	None	No	
166	6010	1	2	211A		Classroom 211 Storage/Office	W2	Peeling and cracking paint	50	No	None	N/A	None	No	
167	6010	1	2	211A		Classroom 211 Storage/Office	W3	Peeling and cracking paint	50	No	None	N/A	None	No	
168	6010	1	2	211A		Classroom 211 Storage/Office	W4	Peeling and cracking paint, debris on window sill	50	No	Window Sill	2	None	No	
169	6010	1	2	224		Classroom 224	W1	Cracking paint	10	No	None	N/A	None	No	
170	6010	1	2	224		Classroom 224	W2	Peeling and cracking paint	50	No	None	N/A	None	No	
171	6010	1	2	224		Classroom 224	W3	Damaged plaster on wall, and peeling paint above windows, debris on window sill	50	No	Window sill	2	None	Yes	
172	6010	1	2	225		Classroom 225	W1	Peeling and cracking paint	5	No	None	N/A	None	No	
173	6010	1	2	225		Classroom 225	W3	Damaged plaster, peeling paint on wall and pipe	50	No	None	N/A	None	Yes	
174	6010	1	2	226		Classroom 226	W3	Efflorescence above windows	20	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
175	6010	1	2	227		Classroom 227	W1	Damaged plaster and cracking paint	20	No	None	N/A	None	Yes	
176	6010	1	2	227		Classroom 227	W2	Damaged plaster	5	No	None	N/A	None	Yes	
177	6010	1	2	227		Classroom 227	W3	Peeling paint above windows	30	No	None	N/A	None	No	
178	6010	1	2	229		Classroom 229	W2	Damaged plaster	10	No	None	N/A	None	Yes	
179	6010	1	2	229		Classroom 229	W3	Peeling paint above windows	15	No	None	N/A	None	No	
180	6010	1	2	230		Classroom 230	W3	Peeling paint above windows and pipe	40	No	None	N/A	None	No	
181	6010	1	2	231		Classroom 231	Ceiling	Peeling paint seen through the missing tile	8	No	None	N/A	None	No	
182	6010	1	2	231		Classroom 231	W1	Peeling paint	10	No	None	N/A	None	No	
183	6010	1	2	231		Classroom 231	W3	Efflorescence above windows	20	No	None	N/A	None	No	
184	6010	1	2	231		Classroom 231	W4	Crack in plaster wall	8	No	None	N/A	None	No	
185	6010	1	2	232		Classroom 232	W1	Peeling paint	5	No	None	N/A	None	No	
186	6010	1	2	232		Classroom 232	W2	Peeling paint	5	No	None	N/A	None	No	
187	6010	1	2	232		Classroom 232	W3	Peeling paint above windows and debris on window sill	30	No	Window sill	2	None	No	
188	6010	1	2	233		Classroom 233	W1	Peeling and cracking paint	20	No	None	N/A	None	No	
189	6010	1	2	233		Classroom 233	W2	Peeling paint	5	No	None	N/A	None	No	
190	6010	1	2	233		Classroom 233	W3	Damaged plaster, Severe peeling paint on wall, peeling paint above windows	45	No	None	N/A	None	Yes	
191	6010	1	2	244		Classroom 244	Ceiling	Peeling paint at door	2	No	None	N/A	None	No	
192	6010	1	2	244		Classroom 244	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
193	6010	1	2	244		Classroom 244	W3	Peeling paint and efflorescence above window	10	No	None	N/A	None	No	
194	6010	1	2	244		Classroom 244	W4	Crack in plaster wall at window	3	No	None	N/A	None	No	
195	6010	1	2	245		Classroom 245	W1	Peeling paint under the blackboard	10	No	None	N/A	None	No	
196	6010	1	2	245		Classroom 245	W3	Peeling paint above windows	20	No	None	N/A	None	No	
197	6010	1	2	246		Classroom 246	W1	Cracking paint	5	No	None	N/A	None	No	
198	6010	1	2	246		Classroom 246	W2	Cracking paint	3	No	None	N/A	None	No	
199	6010	1	2	246		Classroom 246	W3	Damaged plaster and peeling paint on wall, and peeling paint above windows	25	No	None	N/A	None	Yes	
200	6010	1	2	247		Classroom 247	W1	Peeling and cracking paint	5	No	None	N/A	None	No	
201	6010	1	2	247		Classroom 247	W3	Peeling paint at left corner of the room, peeling paint above windows	25	No	None	N/A	None	No	
202	6010	1	2	248		Classroom 248	W3	Peeling paint above windows	30	No	None	N/A	None	No	
203	6010	1	2	249		Classroom 249	W3	Peeling paint above windows	30	No	None	N/A	None	No	
204	6010	1	2	250		Classroom 250	W1	Cracking paint	40	No	None	N/A	None	No	
205	6010	1	2	250		Classroom 250	W2	Cracking paint	40	No	None	N/A	None	No	
206	6010	1	2	250		Classroom 250	W3	Peeling paint and efflorescence above window	20	No	None	N/A	None	No	
207	6010	1	2	251		Classroom 251	W3	Peeling paint above windows	30	No	None	N/A	None	No	
208	6010	1	2	252		Classroom 252	W3	Peeling paint above windows	15	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
209	6010	1	2	253		Classroom 253	W3	Damaged plaster and peeling paint	25	No	None	N/A	None	Yes	
210	6010	1	2	218A		Girl's Restroom across from the Auditorium	Ceiling	Spalling at two spots	6	No	None	N/A	None	No	
211	6010	1	2	H23		Hallway at Rooms 202 to 211	W3	Cracking paint	25	No	None	N/A	None	No	
212	6010	1	2	H28		Hallway at Rooms 224 to 233	W2	Cracking paint	25	No	None	N/A	None	No	
213	6010	1	2	H22		Hallway at Rooms 244 to 254	W1	Cracking paint	20	No	None	N/A	None	No	
214	6010	1	2	H22		Hallway at Rooms 244 to 254	W3	Cracking paint	20	No	None	N/A	None	No	
215	6010	1	2	H23		Hallway at Rooms 202 to 211	W1	Cracking paint	20	No	None	N/A	None	No	
216	6010	1	2	H29		Main Hallway	W2	Peeling and cracking paint	30	No	None	N/A	None	No	
217	6010	1	2	H29		Main Hallway	W4	Peeling and cracking paint	40	No	None	N/A	None	No	
218	6010	1	2	216		Men's Restroom across from Library	Ceiling	Damaged plaster, peeling paint and efflorescence	10	No	None	N/A	None	Yes	
219	6010	1	2	210		Office 210 next to Room 208	W1	Peeling and cracking paint	30	No	None	N/A	None	No	
220	6010	1	2	210		Office 210 next to Room 208	W2	Peeling and cracking paint	30	No	None	N/A	None	No	
221	6010	1	2	210		Office 210 next to Room 208	W3	Damaged plaster and peeling paint above windows	20	No	None	N/A	None	Yes	
222	6010	1	2	210		Office 210 next to Room 208	W4	Peeling and cracking paint	30	No	None	N/A	None	No	
223	6010	1	2	228		Room 228 - Office next to Room 226	W3	Damaged plaster and peeling paint above windows	30	No	None	N/A	None	Yes	
224	6010	1	2	242		Room 242- Storage outside Room 243	Ceiling	Hole in plaster ceiling	2	No	None	N/A	None	Yes	
225	6010	1	2	242		Room 242- Storage outside Room 243	W1	Cracking paint	20	No	None	N/A	None	No	
226	6010	1	2	242		Room 242- Storage outside Room 243	W2	Cracking paint	10	No	None	N/A	None	No	
227	6010	1	2	242		Room 242- Storage outside Room 243	W3	Cracking paint	30	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
228	6010	1	2	242		Room 242- Storage outside Room 243	W4	Cracking paint	40	No	None	N/A	None	No	
229	6010	1	2	243A		Room 243 Storage	Ceiling	Crack in plaster ceiling	8	No	None	N/A	None	No	
230	6010	1	2	243A		Room 243 Storage	W1	Crack in plaster wall	5	No	None	N/A	None	No	
231	6010	1	2	243A		Room 243 Storage	W3	Crack in plaster wall	5	No	None	N/A	None	No	
232	6010	1	2	243A		Room 243 Storage	W4	Crack in plaster wall	5	No	None	N/A	None	No	
233	6010	1	2	243		Room 243-Office near Teacher Lounge	W3	Cracking paint above window	15	No	None	N/A	None	No	
234	6010	1	2	254		Room 254 - Office	W1	Holes in plaster wall	5	No	None	N/A	None	Yes	
235	6010	1	2	S22		Stairwell next to Room 210	W2	Peeling paint	30	No	None	N/A	None	No	
236	6010	1	2	S22		Stairwell next to Room 210	W4	Peeling and cracking paint	20	No	None	N/A	None	No	
237	6010	1	2	S29		Stairwell next to Room 253	W4	Peeling and cracking paint	10	No	None	N/A	None	No	
238	6010	1	2	240		Storage 2-F	Ceiling	No Access							Inspection Required
239	6010	1	2	240		Storage 2-F	Floor	No Access							Inspection Required
240	6010	1	2	240		Storage 2-F	W1	No Access							Inspection Required
241	6010	1	2	240		Storage 2-F	W2	No Access							Inspection Required
242	6010	1	2	240		Storage 2-F	W3	No Access							Inspection Required
243	6010	1	2	240		Storage 2-F	W4	No Access							Inspection Required
244	6010	1	2	234		Storage across from the Auditorium	Ceiling	Damaged plaster and severe peeling paint	10	No	None	N/A	None	Yes	
245	6010	1	2	234		Storage across from the Auditorium	W1	Cracking paint	10	No	None	N/A	None	No	
246	6010	1	2	234		Storage across from the Auditorium	W3	Cracking paint	15	No	None	N/A	None	No	
247	6010	1	2	234		Storage across from the Auditorium	W4	Cracking paint	15	No	None	N/A	None	No	
248	6010	1	2	238		Storage next to Boy's Restroom	Ceiling	Hole in plaster ceiling	4	No	None	N/A	None	Yes	
249	6010	1	2	220		Women's Teacher Lounge	W2	Damaged Plaster	5	No	None	N/A	None	Yes	
250	6010	1	1	115		Auditorium	W1	Cracking above the exit closest to the stage	2	No	None	N/A	None	No	
251	6010	1	1	115		Auditorium	W2	Cracking paint to the left of stage	3	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
252	6010	1	1	131		Boy's Restroom across from the Auditorium	Ceiling	Damaged plaster and peeling paint, and efflorescence	30	No	None	N/A	None	Yes	
253	6010	1	1	101		Classroom 101/103	W3	Peeling paint above windows	40	No	None	N/A	None	No	
254	6010	1	1	102		Classroom 102	W3	Damaged plaster and severe peeling paint above windows	30					Yes	
255	6010	1	1	104		Classroom 104	W1	Cracking paint	30	No	None	N/A	None	No	
256	6010	1	1	104		Classroom 104	W3	Cracking and peeling paint above windows	20	No	None	N/A	None	No	
257	6010	1	1	105		Classroom 105	W3	Peeling paint above windows	20	No	None	N/A	None	No	
258	6010	1	1	106		Classroom 106	W1	Cracking and peeling paint	30	No	None	N/A	None	No	
259	6010	1	1	106		Classroom 106	W2	Damaged plaster	5					Yes	
260	6010	1	1	106		Classroom 106	W3	Peeling paint above windows	5	No	None	N/A	None	No	
261	6010	1	1	107		Classroom 107	W3	Peeling paint above windows	20	No	None	N/A	None	No	
262	6010	1	1	108		Classroom 108	W1	Crack in plaster wall and peeling paint	10	No	None	N/A	None	No	
263	6010	1	1	108		Classroom 108	W3	Flaking paint at window frame and above windows	25	No	None	N/A	None	No	
264	6010	1	1	109		Classroom 109	W1	Flaking and peeling paint by door	10	No	None	N/A	None	No	
265	6010	1	1	109		Classroom 109	W3	Peeling paint above windows and window frame	30	No	None	N/A	None	No	
266	6010	1	1	109		Classroom 109	W4	Cracking paint	30	No	None	N/A	None	No	
267	6010	1	1	111		Classroom 111	W3	Peeling paint above windows	10	No	None	N/A	None	No	
268	6010	1	1	111A		Classroom 111 Storage/Office	Ceiling	Severe peeling paint	200	No	None	N/A	None	No	
269	6010	1	1	111A		Classroom 111 Storage/Office	Floor	Debris	40	No	None	N/A	None	No	
270	6010	1	1	111A		Classroom 111 Storage/Office	W1	Cracking and peeling paint	30	No	None	N/A	None	No	
271	6010	1	1	111A		Classroom 111 Storage/Office	W2	Severe peeling paint	120	No	None	N/A	None	No	
272	6010	1	1	111A		Classroom 111 Storage/Office	W3	Severe peeling paint	120	No	None	N/A	None	No	
273	6010	1	1	111A		Classroom 111 Storage/Office	W4	Cracking paint	50	No	None	N/A	None	No	
274	6010	1	1	119		Classroom 119	W1	Cracking paint	5	No	None	N/A	None	No	
275	6010	1	1	119		Classroom 119	W2	Flaking paint	5	No	None	N/A	None	No	
276	6010	1	1	119		Classroom 119	W3	Severe peeling paint and efflorescence above windows	40	No	None	N/A	None	No	
277	6010	1	1	119		Classroom 119	W4	Severe peeling paint and efflorescence above windows	20	No	None	N/A	None	No	
278	6010	1	1	120		Classroom 120	W1	Severe peeling paint and cracking paint	30	No	None	N/A	None	No	
279	6010	1	1	120		Classroom 120	W2	Severe peeling paint and cracking paint	30	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
280	6010	1	1	120		Classroom 120	W3	Severe peeling paint on wall, peeling and cracking paint above windows	40	No	None	N/A	None	No	
281	6010	1	1	121		Classroom 121	W1	Peeling and cracking paint	10	No	None	N/A	None	No	
282	6010	1	1	121		Classroom 121	W3	Peeling paint on wall, peeling paint and efflorescence above windows	40	No	None	N/A	None	No	
283	6010	1	1	122		Classroom 122	W1	Crack in plaster wall	5	No	None	N/A	None	No	
284	6010	1	1	122		Classroom 122	W2	Severe crack in plaster wall by the door	10	No	None	N/A	None	No	
285	6010	1	1	122		Classroom 122	W4	Peeling paint	5	No	None	N/A	None	No	
286	6010	1	1	123		Classroom 123	W1	Flaking and cracking paint	10	No	None	N/A	None	No	
287	6010	1	1	123		Classroom 123	W2	Crack in plaster wall	2	No	None	N/A	None	No	
288	6010	1	1	123		Classroom 123	W3	Peeling paint above windows, debris on window sill	15	No	Window Sill	2	None	No	
289	6010	1	1	124		Classroom 124	W1	Crack in plaster wall by the door	10	No	None	N/A	None	No	
290	6010	1	1	124		Classroom 124	W2	Holes in plaster wall	10	No	None	N/A	None	No	
291	6010	1	1	124		Classroom 124	W3	Peeling, cracking, flaking paint on wall and above windows	30	No	None	N/A	None	No	
292	6010	1	1	124		Classroom 124	W4	Peeling paint at the door	10	No	None	N/A	None	No	
293	6010	1	1	125		Classroom 125	W1	Cracking and peeling paint at door	10	No	None	N/A	None	No	
294	6010	1	1	125		Classroom 125	W3	Peeling paint above windows	30	No	None	N/A	None	No	
295	6010	1	1	125		Classroom 125	W4	Cracking and peeling paint	10	No	None	N/A	None	No	
296	6010	1	1	126		Classroom 126	W1	Cracking and peeling paint	20	No	None	N/A	None	No	
297	6010	1	1	126		Classroom 126	W3	Severe peeling paint above windows, debris on window sill	30	No	Window Sill	2	None	No	
298	6010	1	1	127		Classroom 127	W3	Peeling paint above windows	30	No	None	N/A	None	No	
299	6010	1	1	141		Classroom 141	Floor	Debris by window	6	No	None	N/A	None	No	
300	6010	1	1	141		Classroom 141	W1	Cracking paint	30	No	None	N/A	None	No	
301	6010	1	1	141		Classroom 141	W2	Cracking and flaking paint	30	No	None	N/A	None	No	
302	6010	1	1	141		Classroom 141	W3	Cracking and peeling paint, Efflorescence above windows	60	No	None	N/A	None	No	
303	6010	1	1	143		Classroom 143	W1	Peeling and cracking paint	5	No	None	N/A	None	No	
304	6010	1	1	143		Classroom 143	W3	Peeling paint above windows	40	No	None	N/A	None	No	
305	6010	1	1	145		Classroom 145	W2	Cracking paint	2	No	None	N/A	None	No	
306	6010	1	1	145		Classroom 145	W3	Severe peeling paint above windows	40	No	None	N/A	None	No	
307	6010	1	1	136		Conference Room next to Principal's Office	W3	Efflorescence by radiator	5	No	None	N/A	None	No	
308	6010	1	1	144B		Copier Room in Roster Office	W1	Cracking paint	5	No	None	N/A	None	No	
309	6010	1	1	144B		Copier Room in Roster Office	W2	Peeling paint	5	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
310	6010	1	1	144B		Copier Room in Roster Office	W3	Cracking paint	5	No	None	N/A	None	No	
311	6010	1	1	144B		Copier Room in Roster Office	W4	Peeling paint	5	No	None	N/A	None	No	
312	6010	1	1	132G		Counselor Office #4-right side of the walkway	W3	Peeling paint above windows	5	No	None	N/A	None	No	
313	6010	1	1	134A		Counselor Office #5 (left) - in front of waiting area	W3	Damaged plaster at radiator	2	No	None	N/A	None	Yes	
314	6010	1	1	134B		Counselor Office #6 (right) - in front of waiting area	W3	Peeling paint above windows	3	No	None	N/A	None	No	
315	6010	1	1	134		Counselor Office waiting area	W4	Cracking paint in the copier area	20	No	None	N/A	None	No	
316	6010	1	1	H14A		Exit Foyer at Library	Ceiling	Peeling paint	30	No	None	N/A	None	No	
317	6010	1	1	H110A		Exit Foyer by Stage	Ceiling	Peeling paint and efflorescence	10	No	None	N/A	None	No	
318	6010	1	1	114		Girl's Restroom across from the Auditorium	Ceiling	Peeling paint and efflorescence	15	No	None	N/A	None	No	
319	6010	1	1	147/147C		Gym	Ceiling	Damaged plaster, Peeling paint along the perimeter	100	No	None	N/A	None	Yes	
320	6010	1	1	147B		Gym Storage	Ceiling	Severe efflorescence	80	No	None	N/A	None	No	
321	6010	1	1	H13		Hallway at Rooms 101 to 111	W2	Cracking paint	60	No	None	N/A	None	No	
322	6010	1	1	H13		Hallway at Rooms 101 to 111	W4	Cracking paint	60	No	None	N/A	None	No	
323	6010	1	1	H18		Hallway at Rooms 119 to 128	W1	Peeling paint	5	No	None	N/A	None	No	
324	6010	1	1	H18		Hallway at Rooms 119 to 128	W2	Peeling and cracking paint	80	No	None	N/A	None	No	
325	6010	1	1	H12		Hallway at Rooms 134 to 146	W1	Cracking paint	10	No	None	N/A	None	No	
326	6010	1	1	H12		Hallway at Rooms 134 to 146	W3	Cracking paint	10	No	None	N/A	None	No	
327	6010	1	1	H15		Hallway between Library and Auditorium	W3	Cracking paint	3	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
328	6010	1	1	H15		Hallway between Library and Auditorium	W4	Cracking paint	3	No	None	N/A	None	No	
329	6010	1	1	H110		Hallway by Stage	W3	Crack in plaster wall by door	4	No	None	N/A	None	No	
330	6010	1	1	H110		Hallway by Stage	W4	Crack in plaster wall by door	6	No	None	N/A	None	No	
331	6010	1	1	113		IMC/Library	Ceiling	Peeling paint at the far left corner	15	No	None	N/A	None	No	
332	6010	1	1	H14		Main Hallway	W2	Peeling paint near Main entrance	20	No	None	N/A	None	No	
333	6010	1	1	H14		Main Hallway	W4	Peeling paint near Main entrance	20	No	None	N/A	None	No	
334	6010	1	1	142		Main Office	W2	Cracking and peeling paint	5	No	None	N/A	None	No	
335	6010	1	1	142		Main Office	W3	Damaged plaster at radiators, Efflorescence above windows	30	No	None	N/A	None	Yes	
336	6010	1	1	140B		Main Office Kitchen	W3	Peeling and cracking paint	10	No	None	N/A	None	No	
337	6010	1	1	130A		Men's Restroom across from the Auditorium	Ceiling	Peeling and cracking paint	5	No	None	N/A	None	No	
338	6010	1	1	130		Men's Restroom Lounge across from the Auditorium	W3	Peeling paint at columns	15	No	None	N/A	None	No	
339	6010	1	1	130		Men's Restroom Lounge across from the Auditorium	W4	Damaged plaster and peeling paint	40	No	None	N/A	None	Yes	
340	6010	1	1	137		Nurse's Suite	W3	Peeling paint and efflorescence above windows	20	No	None	N/A	None	No	
341	6010	1	1	137D		Nurse's Suite - Kitchen	W3	Efflorescence above windows	10	No	None	N/A	None	No	
342	6010	1	1	140		Office next to Main Office	W1	Crack in plaster wall	3	No	None	N/A	None	No	
343	6010	1	1	140		Office next to Main Office	W2	Crack in plaster wall	20	No	None	N/A	None	No	
344	6010	1	1	140		Office next to Main Office	W3	Crack in plaster wall	5	No	None	N/A	None	No	
345	6010	1	1	140		Office next to Main Office	W4	Peeling paint above windows	5	No	None	N/A	None	No	
346	6010	1	1	110		Office Room 110	W3	Peeling paint above windows	10	No	None	N/A	None	No	
347	6010	1	1	142A		Office Walkway	Ceiling	Cracking paint	8	No	None	N/A	None	No	
348	6010	1	1	142A		Office Walkway	W1	Peeling and cracking paint	20	No	None	N/A	None	No	
349	6010	1	1	142A		Office Walkway	W4	Cracking paint	15	No	None	N/A	None	No	
350	6010	1	1	138		Principal's Office	W4	Peeling paint at window frame and above windows	10	No	None	N/A	None	No	
351	6010	1	1	117		Room 112B - Book Closet	Ceiling	No Access							Inspection Required
352	6010	1	1	117		Room 112B - Book Closet	Floor	No Access							Inspection Required

Central HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
353	6010	1	1	117		Room 112B - Book Closet	W1	No Access							Inspection Required
354	6010	1	1	117		Room 112B - Book Closet	W2	No Access							Inspection Required
355	6010	1	1	117		Room 112B - Book Closet	W3	No Access							Inspection Required
356	6010	1	1	117		Room 112B - Book Closet	W4	No Access							Inspection Required
357	6010	1	1	118		Room 112C - Book Closet	Ceiling	No Access							Inspection Required
358	6010	1	1	118		Room 112C - Book Closet	Floor	No Access							Inspection Required
359	6010	1	1	118		Room 112C - Book Closet	W1	No Access							Inspection Required
360	6010	1	1	118		Room 112C - Book Closet	W2	No Access							Inspection Required
361	6010	1	1	118		Room 112C - Book Closet	W3	No Access							Inspection Required
362	6010	1	1	118		Room 112C - Book Closet	W4	No Access							Inspection Required
363	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	Ceiling	Severe peeling paint	100	No	None	N/A	None	No	
364	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	Floor	Debris	60	No	None	N/A	None	No	
365	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	W1	Severe peeling paint	50	No	None	N/A	None	No	
366	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	W2	Severe peeling paint	100	No	None	N/A	None	No	
367	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	W3	Severe peeling paint	80	No	None	N/A	None	No	
368	6010	1	1	111A		Room 113 - Classroom 111 Storage/Office	W4	Severe peeling paint	100	No	None	N/A	None	No	
369	6010	1	1	128		Room 128 - Office	W3	Peeling paint above windows	15	No	None	N/A	None	No	
370	6010	1	1	128A		Room 128 - Office Closet	Ceiling	Crack in plaster ceiling	5	No	None	N/A	None	No	
371	6010	1	1	128A		Room 128 - Office Closet	W1	Crack in plaster wall	10	No	None	N/A	None	No	
372	6010	1	1	128A		Room 128 - Office Closet	W2	Crack in plaster wall	2	No	None	N/A	None	No	
373	6010	1	1	128A		Room 128 - Office Closet	W3	Crack in plaster wall	2	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
374	6010	1	1	128A		Room 128 - Office Closet	W4	Crack in plaster wall	5	No	None	N/A	None	No	
375	6010	1	1	144		Room 144 - Roster Office	W1	Cracking paint	5	No	None	N/A	None	No	
376	6010	1	1	144		Room 144 - Roster Office	W2	Flaking paint	2	No	None	N/A	None	No	
377	6010	1	1	144		Room 144 - Roster Office	W3	Severe efflorescence above and below windows, debris on top of radiator	60	No	Top of radiator	3	None	No	
378	6010	1	1	144		Room 144 - Roster Office	W4	Severe peeling paint	5	No	None	N/A	None	No	
379	6010	1	1	144C		Roster Office Closet on left	W1	Damaged plaster	2	No	None	N/A	None	Yes	
380	6010	1	1	144D		Roster Office Closet on left closer to window	Ceiling	Crack in ceiling	3	No	None	N/A	None	No	
381	6010	1	1	135		School Police Office	W3	Peeling paint above windows	10	No	None	N/A	None	No	
382	6010	1	1	115A		Stage	W2	Peeling paint near the ceiling	10	No	None	N/A	None	No	
383	6010	1	1	S14		Stairwell at Room 101	Ceiling	Peeling paint and efflorescence	60	No	None	N/A	None	No	
384	6010	1	1	S14		Stairwell at Room 101	W1	Efflorescence at exit	15	No	None	N/A	None	No	
385	6010	1	1	S14		Stairwell at Room 101	W4	Peeling and cracking paint	10	No	None	N/A	None	No	
386	6010	1	1	S111		Stairwell by Nurse's Suite (Room 137)	Ceiling	Peeling paint at beam	3	No	None	N/A	None	No	
387	6010	1	1	S12		Stairwell next to Room 110	W1	Peeling paint at exit doors	5	No	None	N/A	None	No	
388	6010	1	1	S12		Stairwell next to Room 110	W2	Peeling paint at exit doors	20	No	None	N/A	None	No	
389	6010	1	1	S116		Stairwell next to Room 119	W4	Efflorescence at exit	20	No	None	N/A	None	No	
390	6010	1	1	S115		Stairwell next to Room 128	Ceiling	Peeling paint under stairs	6	No	None	N/A	None	No	
391	6010	1	1	139A		Storage in Office next to Nurse's Suite	W2	Peeling paint	2	No	None	N/A	None	No	
392	6010	1	1	139A		Storage in Office next to Nurse's Suite	W3	Peeling paint above windows	20	No	None	N/A	None	No	
393	6010	1	1	146		Storage next to Roster Office	W1	Peeling and cracking paint	30	No	None	N/A	None	No	
394	6010	1	1	146		Storage next to Roster Office	W2	Cracking paint at door	20	No	None	N/A	None	No	
395	6010	1	1	129		Storage Room across from the Auditorium	Ceiling	Crack in ceiling	4	No	None	N/A	None	No	

Central HS -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
396	6010	1	1	116A		Women's Restroom across from the Auditorium	W1	Damaged plaster at door	20	No	None	N/A	None	Yes	
397	6010	1	1	116		Women's Restroom Lounge across from the Auditorium	Ceiling	Crack in plaster ceiling	5	No	None	N/A	None	No	
398	6010	1	1	148		Work Room	W1	Cracking paint	25	No	None	N/A	None	No	
399	6010	1	1	148		Work Room	W3	Peeling and cracking paint	15	No	None	N/A	None	No	
400	6010	1	1	148		Work Room	W4	Cracking paint	20	No	None	N/A	None	No	
401	6010	1	1	112		X	Ceiling	No Access							Inspection Required
402	6010	1	1	112		X	Floor	No Access							Inspection Required
403	6010	1	1	112		X	W1	No Access							Inspection Required
404	6010	1	1	112		X	W2	No Access							Inspection Required
405	6010	1	1	112		X	W3	No Access							Inspection Required
406	6010	1	1	112		X	W4	No Access							Inspection Required
407	6010	1	0	8		Art Studio	Ceiling	Peeling paint	30	No	None	N/A	None	No	
408	6010	1	0	8		Art Studio	W1	Peeling paint	5	No	None	N/A	None	No	
409	6010	1	0	8		Art Studio	W2	Peeling paint	10	No	None	N/A	None	No	
410	6010	1	0	8		Art Studio	W3	Severe peeling paint	20	No	None	N/A	None	No	
411	6010	1	0	8		Art Studio	W4	Peeling paint	10	No	None	N/A	None	No	
412	6010	1	0	10		Art Studio Storage	Ceiling	Peeling paint	40	No	None	N/A	None	No	
413	6010	1	0	10		Art Studio Storage	W1	Peeling paint	30	No	None	N/A	None	No	
414	6010	1	0	10		Art Studio Storage	W2	Peeling paint on wall and pipes	50	No	None	N/A	None	No	
415	6010	1	0	10		Art Studio Storage	W3	Peeling paint	30	No	None	N/A	None	No	
416	6010	1	0	HL1		Boy's Locker Room Hallway	Ceiling	Peeling paint towards room 51	60	No	None	N/A	None	No	
417	6010	1	0	36		Boy's Restroom in the Main Hallway	Ceiling	Severe peeling paint, damaged plaster, efflorescence	40	No	None	N/A	None	Yes	
418	6010	1	0	HL2		Girl's Locker Room Hallway	Ceiling	Hole in plaster ceiling	10	No	None	N/A	None	Yes	
419	6010	1	0	GX		Gym Extra Room	Ceiling	Peeling paint	10	No	None	N/A	None	No	
420	6010	1	0	GX		Gym Extra Room	W1	Peeling paint	60	No	None	N/A	None	No	
421	6010	1	0	GX		Gym Extra Room	W2	Peeling paint	80	No	None	N/A	None	No	
422	6010	1	0	GX		Gym Extra Room	W3	Peeling paint	20	No	None	N/A	None	No	
423	6010	1	0	GX		Gym Extra Room	W4	Peeling and cracking paint, efflorescence at exit	20	No	None	N/A	None	No	
424	6010	1	0	14		Gym Storage	Ceiling	No Access		No	None	N/A	None	No	Inspection Required
425	6010	1	0	14		Gym Storage	Floor	No Access		No	None	N/A	None	No	Inspection Required
426	6010	1	0	14		Gym Storage	W1	No Access		No	None	N/A	None	No	Inspection Required
427	6010	1	0	14		Gym Storage	W2	No Access		No	None	N/A	None	No	Inspection Required
428	6010	1	0	14		Gym Storage	W3	No Access		No	None	N/A	None	No	Inspection Required

Central HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
429	6010	1	0	14		Gym Storage	W4	No Access		No	None	N/A	None	No	Inspection Required
430	6010	1	0	H01		Hallway at Art Studio and Planetorium	W2	Peeling and cracking paint	10	No	None	N/A	None	No	
431	6010	1	0	H01		Hallway at Art Studio and Planetorium	W4	Peeling and cracking paint	10	No	None	N/A	None	No	
432	6010	1	0	H06		Hallway at Mechanical Rooms	W2	Peeling and cracking paint, efflorescence	40	No	None	N/A	None	No	
433	6010	1	0	H06		Hallway at Mechanical Rooms	W3	Peeling and cracking paint, efflorescence	20	No	None	N/A	None	No	
434	6010	1	0	H06		Hallway at Mechanical Rooms	W4	Peeling and cracking paint, efflorescence	40	No	None	N/A	None	No	
435	6010	1	0	H02		Main Hallway	W2	Peeling and cracking paint	50	No	None	N/A	None	No	
436	6010	1	0	H02		Main Hallway	W4	Peeling and cracking paint	20	No	None	N/A	None	No	
437	6010	1	0	33		Men's Locker Room next to Building Engineer's Office	Ceiling	Peeling paint by window	20	No	None	N/A	None	No	
438	6010	1	0	33		Men's Locker Room next to Building Engineer's Office	W2	Peeling paint by window	20	No	None	N/A	None	No	
439	6010	1	0	10		Room 010 - Office in the Main Hallway	Ceiling	Efflorescence	20	No	None	N/A	None	No	
440	6010	1	0	10		Room 010 - Office in the Main Hallway	W2	Cracking paint	20	No	None	N/A	None	No	
441	6010	1	0	010A		Room 010 - Office Restroom	Ceiling	Hole in plaster ceiling, efflorescence	20	No	None	N/A	None	Yes	
442	6010	1	0	1		Room 1 - Art Room	W2	Efflorescence near ceiling	5	No	None	N/A	None	No	
443	6010	1	0	1		Room 1 - Art Room	W3	Severe peeling paint, cracking paint, damaged plaster	60	No	None	N/A	None	Yes	
444	6010	1	0	12		Room 12 - Art Classroom	W3	Peeling paint above windows	5	No	None	N/A	None	No	
445	6010	1	0	13		Room 13 - Classroom	W3	Peeling paint on double doors	20	No	None	N/A	None	No	
446	6010	1	0	37		Room 37- Costume Room across from Boy's Restroom	Ceiling	Damaged plaster and peeling paint	40	No	None	N/A	None	Yes	

Central HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
447	6010	1	0	37		Room 37- Costume Room across from Boy's Restroom	W1	Peeling paint	10	No	None	N/A	None	No	
448	6010	1	0	37		Room 37- Costume Room across from Boy's Restroom	W2	Peeling paint	30	No	None	N/A	None	No	
449	6010	1	0	37		Room 37- Costume Room across from Boy's Restroom	W3	Peeling paint	20	No	None	N/A	None	No	
450	6010	1	0	37		Room 37- Costume Room across from Boy's Restroom	W4	Peeling and cracking paint	40	No	None	N/A	None	No	
451	6010	1	0	89		Room 89 - Chemistry Lab	Ceiling	Damaged plaster along window wall	50	No	None	N/A	None	Yes	
452	6010	1	0	9		Room 9 in Art Studio	W2	Peeling paint	5	No	None	N/A	None	No	
453	6010	1	0	9		Room 9 in Art Studio	W3	Severe peeling paint and efflorescence	12	No	None	N/A	None	No	
454	6010	1	0	97		Room 97 - Physics Lab	W3	Peeling paint and efflorescence	50	No	None	N/A	None	No	
455	6010	1	0	97		Room 97 - Physics Lab	W4	Peeling paint and efflorescence	30	No	None	N/A	None	No	
456	6010	1	0	98		Room 98 - Physics Lab	W3	Peeling paint	10	No	None	N/A	None	No	
457	6010	1	0	99		Room 99 - Physics Lab	W3	Peeling paint above windows	50	No	None	N/A	None	No	
458	6010	1	0	28		School Store	W3	Peeling paint by window	10	No	None	N/A	None	No	
459	6010	1	0	S01		Stairwell across from Classroom 12	W1	Peeling and cracking paint above doors	30	No	None	N/A	None	No	
460	6010	1	0	S01		Stairwell across from Classroom 12	W2	Severe peeling paint	50	No	None	N/A	None	No	
461	6010	1	0	S01		Stairwell across from Classroom 12	W3	Severe peeling paint	20	No	None	N/A	None	No	
462	6010	1	0	S01		Stairwell across from Classroom 12	W4	Severe peeling paint	50	No	None	N/A	None	No	
463	6010	1	0	S04		Stairwell at Gym Extra Room - GX	W1	Peeling paint	20	No	None	N/A	None	No	
464	6010	1	0	19C		Storage in Hallway	Ceiling	Damaged plaster and peeling paint	15	No	None	N/A	None	Yes	

Central HS -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
465	6010	1	0	72		Ticket Office at Upper Gym Entrance from Street	Ceiling	Damaged plaster	5	No	None	N/A	None	Yes	
466	6010	1	0	GYL2		Upper Gym Entrance at Street Level	W1	Peeling paint on door frame on middle entrance	20	No	None	N/A	None	No	
467	6010	1	0	GYL1		Upper Gym Lobby at Street Level	Ceiling	Severe peeling paint, damaged plaster, and efflorescence at 3 spots	30	No	None	N/A	None	Yes	
468	6010	1	0	GYL1		Upper Gym Lobby at Street Level	Floor	Debris at 3 spots	15	No	None	N/A	None	No	