

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	7100	1	3	301A	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	1	Flaking	2	No	No	N/A	N/A	No	
2	7100	1	3	301A	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	3	Chipping on wall and radiator cover	2	No	No	N/A	N/A	No	
3	7100	1	3	301A	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	4	Holes	3	No	No	N/A	N/A	No	
4	7100	1	3	301A	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	c	Cracking, Flaking	24	No	No	N/A	N/A	No	
5	7100	1	3	301A	Student Restrooms - Male (4-12)	3rd Floor Boy's Restroom	f	Chipping	80	No	No	N/A	N/A	No	
6	7100	1	3	314A	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	1	Chipping on door and doorframe	18	No	No	N/A	N/A	No	
7	7100	1	3	314A	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	3	Chipping	2	No	No	N/A	N/A	No	
8	7100	1	3	314A	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	4	Cracking	25	No	No	N/A	N/A	No	
9	7100	1	3	314A	Student Restrooms - Female (4-12)	3rd Floor Girl's Restroom	f	Chipping	36	No	No	N/A	N/A	No	
10	7100	1	3	322B	Restrooms, Staff - Male	3rd Floor Men's Restroom	c	Flaking above windows	1	No	No	N/A	N/A	No	
11	7100	1	3	322B	Restrooms, Staff - Male	3rd Floor Men's Restroom	f	N/A	N/A	No	Paint Chips	2	N/A	No	
12	7100	1	3	315B	Restrooms, Staff - Female	3rd Floor Women's Restroom	1	Cracking	4	No	No	N/A	N/A	No	
13	7100	1	3	315B	Restrooms, Staff - Female	3rd Floor Women's Restroom	2	N/A	N/A	No	No	N/A	Cabinets	No	
14	7100	1	3	315B	Restrooms, Staff - Female	3rd Floor Women's Restroom	4	Cracking	2	No	No	N/A	Cabinets	No	
15	7100	1	3	315B	Restrooms, Staff - Female	3rd Floor Women's Restroom	c	Hole above windows	1	No	No	N/A	N/A	Yes	
16	7100	1	3	S33	Stairs	Blue Stairwell	1	Cracking	12	No	No	N/A	N/A	No	
17	7100	1	3	S33	Stairs	Blue Stairwell	2	Cracking	8	No	No	N/A	N/A	No	
18	7100	1	3	S33	Stairs	Blue Stairwell	3	Cracking, Chipping on conduit	38	No	No	N/A	N/A	No	
19		1	3	S33	Stairs	Blue Stairwell	4	Cracking, Chipping on doors and doorframe	45	No	No	N/A	N/A	No	
20	7100	1	3	S33	Stairs	Blue Stairwell	c	Cracking	32	No	No	N/A	N/A	No	
21	7100	1	3	S33	Stairs	Blue Stairwell	f	Chipping on floor and railings	60	No	No	N/A	N/A	No	
22	7100	1	3	301	Primary	Classroom 301	1	Cracking, Chipping on wall and wood cove base	21	No	No	N/A	N/A	No	
23	7100	1	3	301	Primary	Classroom 301	3	Chipping, Hole behind radiator, Flaking behind radiator	18	No	No	N/A	N/A	No	
24	7100	1	3	301	Primary	Classroom 301	4	Cracking, Chipping on wood cove base	6	No	No	N/A	N/A	No	
25	7100	1	3	301	Primary	Classroom 301	c	Holes above windows	6	No	No	N/A	N/A	Yes	
26	7100	1	3	302	Primary	Classroom 302	1	Cracking, Chipping on wood cove base, Hole, paint has been stabilized	7	No	No	N/A	Furniture	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
27	7100	1	3	302	Primary	Classroom 302	3	Chipping on wood cove base, Hole behind radiator, Flaking behind radiators	17	No	No	N/A	Furniture	Yes	
28	7100	1	3	302	Primary	Classroom 302	c	Efflorescence above windows and missing ceiling tile	3	Yes	No	N/A	N/A	Yes	
29	7100	1	3	303	Primary	Classroom 303	1	Chipping on wall and wood cove base, Flaking	33	No	No	N/A	N/A	No	
30	7100	1	3	303	Primary	Classroom 303	2	Chipping on wall and wood cove base, Staples	33	No	No	N/A	N/A	Yes	
31	7100	1	3	303	Primary	Classroom 303	3	Chipping on wall and wood cove base, Flaking behind radiator, Efflorescence	14	Yes	Debris on windowsills	4	N/A	Yes	
32	7100	1	3	303	Primary	Classroom 303	c	Flaking, Efflorescence above windows	10	Yes	No	N/A	N/A	Yes	
33	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	1	Cracking, Chipping in air shaft	5	No	Debris in corner of walls 1 and 4	1	Stored Materials	No	
34	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	2	Flaking behind radiator, Hole behind radiator	6	No	No	N/A	Stored Materials	Yes	
35	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	3	Hole behind radiator	1	No	Debris on windowsills	4	Stored Materials	Yes	
36	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	4	Cracking	15	No	No	N/A	Stored Materials	No	
37	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	c	Holes, Efflorescence above windows	8	Yes	No	N/A	N/A	Yes	
38	7100	1	3	304	Computer - Intermediate Middle	Classroom 304	f	N/A	N/A	No	Paint chips along wall 2	1	N/A	No	
39	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
40	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
41	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
42	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
43	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
44	7100	1	3	304B	Storage	Classroom 304 Closet in corner adjacent to Classroom 305		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
45	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
46	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
47	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
48	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
49	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
50	7100	1	3	304A	Storage	Classroom 304 Closet in corner by Windows		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
51	7100	1	3	305	Computer - Intermediate Middle	Classroom 305	1	Cracking, Chipping on wall and wood cove base	13	No	No	N/A	bles with comput	No	
52	7100	1	3	305	Computer - Intermediate Middle	Classroom 305	2	Cracking, Chipping on wood cove base	22	No	No	N/A	N/A	No	
53	7100	1	3	305	Computer - Intermediate Middle	Classroom 305	3	Chipping on wall and wood cove base, Hole behind radiator, Efflorescence behind radiator	7	Yes	No	N/A	bles with comput	Yes	
54	7100	1	3	305	Computer - Intermediate Middle	Classroom 305	4	Cracking, Chipping	7	No	No	N/A	N/A	No	
55	7100	1	3	305	Computer - Intermediate Middle	Classroom 305	c	Holes, Flaking above windows	4	No	No	N/A	N/A	Yes	
56	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
57	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
58	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
59	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
60	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
61	7100	1	3	305A	Storage	Classroom 305 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
62	7100	1	3	306	Primary	Classroom 306	1	Chipping	3	No	No	N/A	N/A	No	
63	7100	1	3	306	Primary	Classroom 306	2	Chipping on wood cove base	1	No	No	N/A	N/A	No	
64	7100	1	3	306	Primary	Classroom 306	3	Flaking behind radiator	3	No	Debris on windowsills	1	N/A	No	
65	7100	1	3	306	Primary	Classroom 306	4	Chipping	4	No	No	N/A	N/A	No	
66	7100	1	3	306	Primary	Classroom 306	c	Flaking, Efflorescence above windows	8	Yes	No	N/A	N/A	Yes	
67	7100	1	3	306A	Storage	Classroom 306 Closet	1	Chipping on doorframe	1	No	No	N/A	N/A	No	
68	7100	1	3	306A	Storage	Classroom 306 Closet	3	Chipping	2	No	No	N/A	N/A	No	
69	7100	1	3	306A	Storage	Classroom 306 Closet	4	Chipping	2	No	No	N/A	N/A	No	
70	7100	1	3	307	Primary	Classroom 307	1	Chipping on wall and wood cove base	22	No	No	N/A	N/A	No	
71	7100	1	3	307	Primary	Classroom 307	2	Cracking, Chipping on wall and wood cove base	18	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
72	7100	1	3	307	Primary	Classroom 307	3	Chipping, Flaking behind radiators	14	No	No	N/A	N/A	No	
73	7100	1	3	307	Primary	Classroom 307	4	Chipping on wall and wood cove base	6	No	No	N/A	N/A	No	
74	7100	1	3	307	Primary	Classroom 307	c	Holes above windows	5	No	No	N/A	N/A	Yes	
75	7100	1	3	307A	Storage	Classroom 307 Closet	1	Chipping on wall and doorframe	18	No	No	N/A	N/A	No	
76	7100	1	3	307A	Storage	Classroom 307 Closet	2	Chipping	20	No	No	N/A	Built in shelves	No	
77	7100	1	3	307A	Storage	Classroom 307 Closet	3	Chipping, Flaking	11	No	No	N/A	Built in shelves	No	
78	7100	1	3	307A	Storage	Classroom 307 Closet	4	N/A	N/A	No	No	N/A	Built in shelves	No	
79	7100	1	3	307A	Storage	Classroom 307 Closet	c	Cracking	6	No	No	N/A	N/A	No	
80	7100	1	3	308	Art - Elementary	Classroom 308	1	Cracking, Chipping on wall and wood cove base	15	No	No	N/A	N/A	No	
81	7100	1	3	308	Art - Elementary	Classroom 308	2	Chipping on wall and wood cove base	7	No	No	N/A	N/A	No	
82	7100	1	3	308	Art - Elementary	Classroom 308	3	Cracking, Chipping on wall and wood cove base	16	No	Debris on windowsills	2	N/A	No	
83	7100	1	3	308	Art - Elementary	Classroom 308	4	Cracking, Chipping	5	No	No	N/A	N/A	No	
84	7100	1	3	308	Art - Elementary	Classroom 308	c	Cracking, Flaking above windows	6	No	No	N/A	N/A	No	
85	7100	1	3	308B	Storage	Classroom 308 Closet by Entrance	2	Hole	1	No	No	N/A	N/A	Yes	
86	7100	1	3	308B	Storage	Classroom 308 Closet by Entrance	3	Cracking	8	No	No	N/A	N/A	No	
87	7100	1	3	308B		Classroom 308 Closet by Entrance	4	Cracking, Holes, Flaking	7	No	No	N/A	N/A	Yes	
88	7100	1	3	308A	Storage	Classroom 308 Closet by Windows	1	Chipping on doorframe	12	No	No	N/A	N/A	No	
89	7100	1	3	308A	Storage	Classroom 308 Closet by Windows	2	N/A	N/A	No	No	N/A	Built in shelves	No	
90	7100	1	3	308A	Storage	Classroom 308 Closet by Windows	3	Cracking, Chipping, Flaking, Efflorescence	12	Yes	No	N/A	Built in shelves	Yes	
91	7100	1	3	308A		Classroom 308 Closet by Windows	4	Cracking, Chipping	14	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
92	7100	1	3	308A		Classroom 308 Closet by Windows	c	Flaking, Efflorescence	16	Yes	No	N/A	N/A	Yes	
93	7100	1	3	309	Primary	Classroom 309	1	Chipping on wall and wood cove base, Hole, Staples	32	No	No	N/A	N/A	Yes	
94	7100	1	3	309	Primary	Classroom 309	2	Chipping, Staples and Staple Holes, Flaking	14	No	No	N/A	N/A	Yes	
95	7100	1	3	309	Primary	Classroom 309	3	Chipping, Staples, Flaking behind radiator	5	No	No	N/A	N/A	Yes	
96	7100	1	3	309	Primary	Classroom 309	4	Chipping on wall and wood cove base, Holes	18	No	No	N/A	N/A	Yes	
97	7100	1	3	309	Primary	Classroom 309	c	Holes, Flaking above windows	16	No	No	N/A	N/A	Yes	
98	7100	1	3	310	Primary	Classroom 310	1	Chipping on wall and wood cove base	8	No	No	N/A	N/A	No	
99	7100	1	3	310	Primary	Classroom 310	2	Chipping	1	No	No	N/A	N/A	No	
100	7100	1	3	310	Primary	Classroom 310	3	Cracking, Chipping on wood cove base	7	No	No	N/A	N/A	No	
101	7100	1	3	310	Primary	Classroom 310	4	Chipping on wood cove base, Flaking	2	No	No	N/A	N/A	No	
102	7100	1	3	310	Primary	Classroom 310	c	Holes above windows	26	No	No	N/A	N/A	Yes	
103	7100	1	3	311	Primary	Classroom 311	1	Cracking, Chipping on wall and in air shaft, Holes	20	No	No	N/A	N/A	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
104	7100	1	3	311	Primary	Classroom 311	3	Chipping on wall and metal pipe, Flaking, Efflorescence above missing ceiling tile	18	Yes	No	N/A	N/A	Yes	
105	7100	1	3	311	Primary	Classroom 311	4	Chipping, Holes	9	No	No	N/A	N/A	Yes	
106	7100	1	3	311	Primary	Classroom 311	c	Holes above missing ceiling tile	3	No	No	N/A	N/A	Yes	
107	7100	1	3	311	Primary	Classroom 311	f	N/A	N/A	No	Debris below missing ceiling tile	8	N/A	No	
108	7100	1	3	311A	Storage	Classroom 311 Closet	1	Chipping on doorframe	5	No	No	N/A	N/A	No	
109	7100	1	3	311A	Storage	Classroom 311 Closet	2	Flaking	1	No	No	N/A	es with stored ma	No	Limited inspection due to stored materials
110	7100	1	3	311A	Storage	Classroom 311 Closet	3	Chipping, Hole, paint has been stabilized	2	No	Debris on windowsill	2	N/A	Yes	
111	7100	1	3	311A	Storage	Classroom 311 Closet	4	Chipping	2	No	No	N/A	es with stored ma	No	Limited inspection due to stored materials
112	7100	1	3	312	Primary	Classroom 312	1	Chipping	5	No	No	N/A	N/A	No	
113	7100	1	3	312	Primary	Classroom 312	2	Chipping	10	No	No	N/A	N/A	No	
114	7100	1	3	312	Primary	Classroom 312	3	Chipping, Holes, some behind radiator, Flaking	5	No	No	N/A	N/A	Yes	
115	7100	1	3	312	Primary	Classroom 312	4	Chipping, Flaking	6	No	No	N/A	N/A	No	
116	7100	1	3	313	Primary	Classroom 313	1	Chipping	12	No	No	N/A	N/A	No	
117	7100	1	3	313	Primary	Classroom 313	2	Chipping	8	No	No	N/A	N/A	No	
118	7100	1	3	313	Primary	Classroom 313	3	Chipping, Flaking behind radiators	17	No	No	N/A	N/A	No	
119	7100	1	3	313	Primary	Classroom 313	4	Chipping	4	No	No	N/A	N/A	No	
120	7100	1	3	313	Primary	Classroom 313	c	Holes above windows	3	No	No	N/A	N/A	Yes	
121	7100	1	3	313A	Primary	Classroom 313A	1	Chipping in air shaft	3	No	No	N/A	N/A	No	
122	7100	1	3	313A	Primary	Classroom 313A	3	Cracking	1	No	No	N/A	N/A	No	
123	7100	1	3	314	Primary	Classroom 314	1	Cracking, Chipping, Hole	3	No	No	N/A	N/A	Yes	
124	7100	1	3	314	Primary	Classroom 314	2	Cracking, Chipping	11	No	No	N/A	N/A	No	
125	7100	1	3	314	Primary	Classroom 314	3	Chipping, Holes behind radiators, Flaking	9	No	No	N/A	N/A	Yes	
126	7100	1	3	314	Primary	Classroom 314	4	Chipping	1	No	No	N/A	N/A	No	
127	7100	1	3	315	Primary	Classroom 315	1	Chipping, Hole	2	No	No	N/A	N/A	Yes	
128	7100	1	3	315	Primary	Classroom 315	2	Cracking	7	No	No	N/A	N/A	No	
129	7100	1	3	315	Primary	Classroom 315	3	Cracking, Staples, Flaking behind radiator	8	No	No	N/A	N/A	Yes	
130	7100	1	3	315	Primary	Classroom 315	4	Chipping, Hole, Flaking behind radiator	7	No	No	N/A	N/A	Yes	
131	7100	1	3	315	Primary	Classroom 315	c	Holes, Flaking above windows	9	No	No	N/A	N/A	No	
132	7100	1	3	316	Computer - Intermediate Middle	Classroom 316	1	Cracking, Chipping, Hole	5	No	No	N/A	N/A	Yes	
133	7100	1	3	316	Computer - Intermediate Middle	Classroom 316	2	Cracking, Chipping, Flaking	11	No	No	N/A	N/A	No	
134	7100	1	3	316	Computer - Intermediate Middle	Classroom 316	3	Cracking, Chipping, Hole behind radiator, Flaking, some behind radiator, Significant Moisture Damage	19	Yes	No	N/A	N/A	Yes	
135	7100	1	3	316	Computer - Intermediate Middle	Classroom 316	4	Cracking, Chipping	6	No	No	N/A	N/A	No	
136	7100	1	3	316	Computer - Intermediate Middle	Classroom 316	c	Holes above windows	13	No	No	N/A	N/A	Yes	
137	7100	1	3	317	Primary	Classroom 317	1	Chipping, Hole in air shaft	8	No	No	N/A	Posters	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
138	7100	1	3	317	Primary	Classroom 317	3	Cracking, Flaking on and behind radiators	9	No	No	N/A	N/A	No	
139	7100	1	3	317	Primary	Classroom 317	4	Cracking	2	No	No	N/A	Posters	No	
140	7100	1	3	317	Primary	Classroom 317	c	Holes above windows	12	No	No	N/A	N/A	Yes	
141	7100	1	3	318	Primary	Classroom 318	1	Chipping	2	No	No	N/A	N/A	No	
142	7100	1	3	318	Primary	Classroom 318	2	Chipping, Hole, Flaking	4	No	No	N/A	N/A	Yes	
143	7100	1	3	318	Primary	Classroom 318	3	Cracking, Flaking on wall and behind radiators	8	No	No	N/A	N/A	No	
144	7100	1	3	318	Primary	Classroom 318	c	Holes above windows	14	No	No	N/A	N/A	Yes	
145	7100	1	3	319	Primary	Classroom 319	1	Cracking, Chipping, Hole, Staples	25	No	No	N/A	N/A	Yes	
146	7100	1	3	319	Primary	Classroom 319	2	Chipping, Flaking	66	No	No	N/A	N/A	No	
147	7100	1	3	319	Primary	Classroom 319	3	Chipping, Hole, Flaking on fiberglass pipe insulation and behind radiator	18	No	No	N/A	N/A	Yes	
148	7100	1	3	319	Primary	Classroom 319	4	Chipping on wall and wood cove base, Gouge, Staples and Staple Holes, Flaking	30	No	No	N/A	N/A	Yes	
149	7100	1	3	319	Primary	Classroom 319	c	Holes above windows	10	No	No	N/A	N/A	Yes	
150	7100	1	3	320	Primary	Classroom 320	1	Chipping	1	No	No	N/A	Stored Furniture	No	Limited inspection due to stored furniture
151	7100	1	3	320	Primary	Classroom 320	2	N/A	N/A	No	No	N/A	Stored Furniture	No	Limited inspection due to stored furniture
152	7100	1	3	320	Primary	Classroom 320	3	Hole, Flaking behind radiator	4	No	No	N/A	Stored Furniture	Yes	Limited inspection due to stored furniture
153	7100	1	3	320	Primary	Classroom 320	4	Chipping	20	No	No	N/A	Stored Furniture	No	Limited inspection due to stored furniture
154	7100	1	3	320	Primary	Classroom 320	c	N/A	N/A	No	No	N/A	Stored Furniture	No	Limited inspection due to stored furniture
155	7100	1	3	320	Primary	Classroom 320	f	N/A	N/A	No	No	N/A	Stored Furniture	No	Limited inspection due to stored furniture
156	7100	1	3	321	Primary	Classroom 321	1	Chipping on wall, wood closet, and wood cove base	27	No	No	N/A	N/A	No	
157	7100	1	3	321	Primary	Classroom 321	2	Chipping on wall and wood cove base	13	No	No	N/A	N/A	No	
158	7100	1	3	321	Primary	Classroom 321	3	Cracking, Chipping on wall and wood cove base, Hole, Flaking behind radiator, Efflorescence	7	Yes	No	N/A	N/A	Yes	
159	7100	1	3	321	Primary	Classroom 321	4	Cracking, Chipping	3	No	No	N/A	N/A	No	
160	7100	1	3	321	Primary	Classroom 321	c	Cracking, Holes, Significant Moisture Damage above windows	24	Yes	No	N/A	N/A	Yes	
161	7100	1	3	322	Primary	Classroom 322	1	Cracking	2	No	No	N/A	N/A	No	
162	7100	1	3	322	Primary	Classroom 322	2	Chipping	7	No	No	N/A	Cabinets	No	
163	7100	1	3	322	Primary	Classroom 322	3	Hole behind radiator, Flaking behind radiator	8	No	No	N/A	Cabinets	Yes	
164	7100	1	3	322	Primary	Classroom 322	4	Chipping	4	No	No	N/A	N/A	No	
165	7100	1	3	322	Primary	Classroom 322	c	Holes, Flaking above windows	13	No	No	N/A	N/A	Yes	
166	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
167	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
168	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
169	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
170	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
171	7100	1	3	301D	Storage	Closet adjacent to Classroom 301		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
172	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
173	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
174	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
175	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
176	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
177	7100	1	3	314D	Storage	Closet adjacent to Classroom 314		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
178	7100	1	3	303A	Copying Room	Copy Room 303A	1	Chipping	10	No	No	N/A	N/A	No	
179	7100	1	3	303A	Copying Room	Copy Room 303A	2	Chipping	14	No	No	N/A	N/A	No	
180	7100	1	3	303A	Copying Room	Copy Room 303A	3	Chipping on wall and radiator	12	No	No	N/A	N/A	No	
181	7100	1	3	303A	Copying Room	Copy Room 303A	4	Flaking	7	No	No	N/A	N/A	No	
182	7100	1	3	303A	Copying Room	Copy Room 303A	c	Flaking above missing ceiling tile	18	No	No	N/A	N/A	No	
183	7100	1	3	303A	Copying Room	Copy Room 303A	f	N/A	N/A	No	Paint Chips	10	N/A	No	
184	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	1	Chipping on wall, door, and doorframe	13	No	No	N/A	N/A	No	
185	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	2	Chipping, Flaking	134	No	No	N/A	N/A	No	
186	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	3	Flaking	20	No	No	N/A	N/A	No	
187	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	4	Flaking on wall and metal pipe	158	No	No	N/A	N/A	No	
188	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	c	Flaking, Efflorescence	525	Yes	No	N/A	N/A	Yes	
189	7100	1	3	S31	Stairs, Fire Tower	Fire Tower between Classrooms 316 and 317	f	N/A	N/A	No	Paint Chips	525	N/A	No	
190	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	1	Chipping on wall, door, and doorframe, Flaking	27	No	No	N/A	N/A	No	
191	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	2	Flaking	45	No	No	N/A	N/A	No	
192	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	3	Flaking	20	No	No	N/A	N/A	No	
193	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	4	Flaking	35	No	No	N/A	N/A	No	
194	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	c	Flaking	525	No	No	N/A	N/A	No	
195	7100	1	3	S32	Stairs, Fire Tower	Fire Tower between Classrooms 320 and 321	f	N/A	N/A	No	Paint Chips	50	N/A	No	
196	7100	1	3	S36	Stairs	Green Stairwell	1	Chipping on wall and conduit	5	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
197	7100	1	3	S36	Stairs	Green Stairwell	2	Chipping on wall, doors, and doorframe	33	No	No	N/A	N/A	No	
198	7100	1	3	S36	Stairs	Green Stairwell	3	Cracking	30	No	No	N/A	N/A	No	
199	7100	1	3	S36	Stairs	Green Stairwell	4	Cracking	2	No	No	N/A	N/A	No	
200	7100	1	3	S36	Stairs	Green Stairwell	c	Cracking	1	No	No	N/A	N/A	No	
201	7100	1	3	S36	Stairs	Green Stairwell	f	Chipping on floor and railings	48	No	No	N/A	N/A	No	
202	7100	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 301-303	1	No Wall	No Wall	No Wall	No Wall	No Wall	No Wall	No Wall	
203	7100	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 301-303	2	Chipping on wall and metal lockers	422	No	No	N/A	N/A	No	
204	7100	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 301-303	4	Chipping	1	No	No	N/A	N/A	No	
205	7100	1	3	H312	Circulation (Hallway)	Hallway outside Classrooms 301-303	f	Chipping	1	No	No	N/A	N/A	No	
206	7100	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 304-311	1	Cracking, Chipping on wall and metal lockers	93	No	No	N/A	N/A	No	
207	7100	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 304-311	2	Cracking	2	No	No	N/A	N/A	No	
208	7100	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 304-311	3	Cracking, Chipping on electrical panel and metal lockers	133	No	No	N/A	N/A	No	
209	7100	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 304-311	4	Cracking	1	No	No	N/A	N/A	No	
210	7100	1	3	H313	Circulation (Hallway)	Hallway outside Classrooms 304-311	f	Chipping	5	No	No	N/A	N/A	No	
211	7100	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 312-314	2	Cracking, Chipping, Holes	8	No	No	N/A	N/A	Yes	
212	7100	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 312-314	4	Cracking, Chipping on wall and metal lockers	265	No	No	N/A	N/A	No	
213	7100	1	3	H314	Circulation (Hallway)	Hallway outside Classrooms 312-314	f	Chipping	4	No	No	N/A	N/A	No	
214	7100	1	3	H315	Circulation (Hallway)	Hallway outside Classrooms 315-322	1	Cracking, Chipping on wall and metal lockers	318	No	No	N/A	N/A	No	
215	7100	1	3	H315	Circulation (Hallway)	Hallway outside Classrooms 315-322	3	Cracking, Chipping on metal lockers, Hole	844	No	No	N/A	N/A	Yes	
216	7100	1	3	H315	Circulation (Hallway)	Hallway outside Classrooms 315-322	c	Efflorescence above windows	13	Yes	No	N/A	N/A	Yes	
217	7100	1	3	H315	Circulation (Hallway)	Hallway outside Classrooms 315-322	f	Chipping	14	No	No	N/A	N/A	No	
218	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
219	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
220	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
221	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
222	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
223	7100	1	3	310A	Space (Science Lab Prep)	Lab Prep Room between Classrooms 309 and 310		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
224	7100	1	3	322A	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom	1	Chipping on wall, door, and doorframe	15	No	No	N/A	N/A	No	
225	7100	1	3	322A	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom	2	Cracking, Chipping	12	No	No	N/A	N/A	No	
226	7100	1	3	322A	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom	3	Flaking behind radiator, Efflorescence behind radiator	3	Yes	No	N/A	N/A	Yes	
227	7100	1	3	322A	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom	4	Cracking, Chipping	8	No	No	N/A	N/A	No	
228	7100	1	3	322A	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom	c	Hole above windows	1	No	No	N/A	N/A	Yes	
229	7100	1	3	303B	Administrative Office	Office 303B	1	Chipping, Hole	5	No	No	N/A	N/A	No	
230	7100	1	3	303B	Administrative Office	Office 303B	2	Hole	1	No	No	N/A	N/A	No	
231	7100	1	3	303B	Administrative Office	Office 303B	3	Chipping on fiberglass pipe insulation	1	No	No	N/A	N/A	No	
232	7100	1	3	303B	Administrative Office	Office 303B	c	Cracking	18	No	No	N/A	N/A	No	
233	7100	1	3	S37	Stairs	Red Stairwell	1	Cracking	12	No	No	N/A	N/A	No	
234	7100	1	3	S37	Stairs	Red Stairwell	3	Cracking, Chipping on conduit	24	No	No	N/A	N/A	No	
235	7100	1	3	S37	Stairs	Red Stairwell	4	Cracking, Chipping on wall, doors, and doorframe	34	No	No	N/A	N/A	No	
236	7100	1	3	S37	Stairs	Red Stairwell	c	Cracking	27	No	No	N/A	N/A	No	
237	7100	1	3	S37	Stairs	Red Stairwell	f	Chipping on floor and railings	63	No	No	N/A	N/A	No	
238	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
239	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
240	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
241	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
242	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
243	7100	1	3	302A	Storage	Storage Room 302A		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
244	7100	1	3	312A	Storage	Storage Room 312A	1	Chipping, Hole above missing ceiling tile, Efflorescence above missing ceiling tile	7	Yes	No	N/A	N/A	Yes	
245	7100	1	3	312A	Storage	Storage Room 312A	2	Flaking	17	No	No	N/A	N/A	No	
246	7100	1	3	312A	Storage	Storage Room 312A	3	Flaking	7	No	No	N/A	N/A	No	
247	7100	1	3	312A	Storage	Storage Room 312A	4	Hole	1	No	No	N/A	N/A	No	
248	7100	1	3	312A	Storage	Storage Room 312A	c	Flaking above missing ceiling tile	3	No	No	N/A	N/A	No	
249	7100	1	3	315A	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	1	Chipping on doorframe	10	No	No	N/A	N/A	No	
250	7100	1	3	315A	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	2	Cracking, Chipping	16	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
251	7100	1	3	315A	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	3	Flaking behind radiator, Spalling	2	Yes	No	N/A	N/A	Yes	
252	7100	1	3	315A	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	4	Cracking	5	No	No	N/A	N/A	No	
253	7100	1	3	315A	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	c	Holes above missing ceiling tile, Holes, Flaking above windows	12	No	No	N/A	N/A	Yes	
254	7100	1	3	S34	Stairs	Yellow Stairwell	1	Cracking	10	No	No	N/A	N/A	No	
255	7100	1	3	S34	Stairs	Yellow Stairwell	2	Cracking, Chipping on doors and doorframe, Hole, paint has been stabilized	33	No	No	N/A	N/A	Yes	
256	7100	1	3	S34	Stairs	Yellow Stairwell	3	Cracking	17	No	No	N/A	N/A	No	
257	7100	1	3	S34	Stairs	Yellow Stairwell	4	Cracking	21	No	No	N/A	N/A	No	
258	7100	1	3	S34	Stairs	Yellow Stairwell	c	Cracking	18	No	No	N/A	N/A	No	
259	7100	1	3	S34	Stairs	Yellow Stairwell	f	Chipping on floor and railings	69	No	No	N/A	N/A	No	
260	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	1	Chipping on door and doorframe, Hole	20	No	No	N/A	N/A	Yes	
261	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	2	Cracking, Spalling	16	Yes	No	N/A	N/A	Yes	
262	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	3	Cracking, Efflorescence	2	Yes	No	N/A	N/A	Yes	
263	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	4	Cracking	12	No	No	N/A	N/A	No	
264	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	c	Cracking, Spalling	19	Yes	No	N/A	N/A	Yes	
265	7100	1	2	201A	Student Restrooms - Male (4-12)	2nd Floor Boy's Restroom	f	Chipping	5	No	No	N/A	N/A	No	
266	7100	1	2	209A	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	1	Chipping on door and doorframe, Hole	26	No	No	N/A	N/A	Yes	
267	7100	1	2	209A	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	2	Cracking	9	No	No	N/A	N/A	No	
268	7100	1	2	209A	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	4	Flaking, Spalling	11	Yes	No	N/A	N/A	Yes	
269	7100	1	2	209A	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	c	Cracking	18	No	No	N/A	N/A	No	
270	7100	1	2	209A	Student Restrooms - Female (4-12)	2nd Floor Girl's Restroom	f	Chipping	50	No	No	N/A	N/A	No	
271	7100	1	2	200A	Restrooms, Staff - Male	2nd Floor Men's Restroom	1	Cracking	3	No	Debris on marble	1	N/A	No	
272	7100	1	2	200A	Restrooms, Staff - Male	2nd Floor Men's Restroom	3	Cracking	8	No	No	N/A	N/A	No	
273	7100	1	2	200A	Restrooms, Staff - Male	2nd Floor Men's Restroom	4	Efflorescence	1	Yes	No	N/A	N/A	Yes	
274	7100	1	2	200A	Restrooms, Staff - Male	2nd Floor Men's Restroom	c	Cracking above windows	2	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
275	7100	1	2	200A	Restrooms, Staff - Male	2nd Floor Men's Restroom	f	Chipping	4	No	No	N/A	N/A	No	
276	7100	1	2	208A	Teacher Lounge/Dining	2nd Floor Teacher's Lounge	1	Cracking in air shafts, Flaking in air shafts	14	No	No	N/A	N/A	No	
277	7100	1	2	208A	Teacher Lounge/Dining	2nd Floor Teacher's Lounge	2	Chipping	7	No	No	N/A	N/A	No	
278	7100	1	2	208A	Teacher Lounge/Dining	2nd Floor Teacher's Lounge	3	Flaking	12	No	No	N/A	N/A	No	
279	7100	1	2	208A	Teacher Lounge/Dining	2nd Floor Teacher's Lounge	4	Chipping	1	No	No	N/A	N/A	No	
280	7100	1	2	208A	Teacher Lounge/Dining	2nd Floor Teacher's Lounge	c	Flaking above windows	5	No	No	N/A	N/A	No	
281	7100	1	2	208B	Storage	2nd Floor Teacher's Lounge Closet	2	Flaking	1	No	No	N/A	N/A	No	
282	7100	1	2	209C	Restrooms, Staff - Female	2nd Floor Women's Restroom	1	Cracking	3	No	Debris on marble	1	N/A	No	
283	7100	1	2	209C	Restrooms, Staff - Female	2nd Floor Women's Restroom	2	Cracking, Flaking, Efflorescence above missing ceiling tile	9	Yes	No	N/A	N/A	Yes	
284	7100	1	2	209C	Restrooms, Staff - Female	2nd Floor Women's Restroom	3	Efflorescence above missing ceiling tile	1	Yes	No	N/A	N/A	Yes	
285	7100	1	2	209C	Restrooms, Staff - Female	2nd Floor Women's Restroom	4	Flaking above missing ceiling tile	5	No	No	N/A	N/A	No	
286	7100	1	2	209C	Restrooms, Staff - Female	2nd Floor Women's Restroom	c	Flaking on metal pipes above missing ceiling tile, Significant Moisture Damage above missing ceiling tile	23	Yes	No	N/A	N/A	Yes	
287	7100	1	2	222A	Administrative Office	Assistant Principal Suite Center Office	1	Chipping on wall, doorframe, and wood cove base, Staples and Staple Holes	13	No	No	N/A	N/A	Yes	
288	7100	1	2	222A	Administrative Office	Assistant Principal Suite Center Office	2	Chipping, Staples and Staple Holes	6	No	No	N/A	N/A	Yes	
289	7100	1	2	222A	Administrative Office	Assistant Principal Suite Center Office	3	Cracking, Staples and Staple Holes	8	No	No	N/A	N/A	Yes	
290	7100	1	2	222A	Administrative Office	Assistant Principal Suite Center Office	4	Staples and Staple Holes	3	No	No	N/A	N/A	Yes	
291	7100	1	2	222A	Administrative Office	Assistant Principal Suite Center Office	c	Flaking above windows	4	No	No	N/A	N/A	No	
292	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
293	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
294	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
295	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
296	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
297	7100	1	2	223C	Storage	Assistant Principal Suite Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
298	7100	1	2	223	Circulation (Hallway)	Assistant Principal Suite Hallway	1	Cracking, Chipping on wood cove base	7	No	No	N/A	N/A	No	
299	7100	1	2	223	Circulation (Hallway)	Assistant Principal Suite Hallway	2	Cracking, Chipping on wood cove base	7	No	No	N/A	N/A	No	
300	7100	1	2	223	Circulation (Hallway)	Assistant Principal Suite Hallway	3	Cracking, Chipping on wood cove base	11	No	No	N/A	N/A	No	
301	7100	1	2	223	Circulation (Hallway)	Assistant Principal Suite Hallway	4	Cracking, Chipping	11	No	No	N/A	N/A	No	
302	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	1	Chipping on wall and doorframe	7	No	No	N/A	Cabinets	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
303	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	2	Chipping on wall and wood cove base	10	No	No	N/A	N/A	No	
304	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	3	Cracking, Flaking on metal pipe	14	No	Debris on windowsills	6	N/A	No	
305	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	4	Chipping on wall and wood cove base	6	No	No	N/A	N/A	No	
306	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	c	Holes above windows	2	No	No	N/A	N/A	Yes	
307	7100	1	2	222B	Administrative Office	Assistant Principal Suite Left Office	f	N/A	N/A	No	Debris along wall 3	5	N/A	No	
308	7100	1	2	222	Administrative Office	Assistant Principal Suite Right Office	1	Chipping on doorframe, Holes	5	No	No	N/A	Boxes	Yes	Limited inspection due to boxes
309	7100	1	2	222	Administrative Office	Assistant Principal Suite Right Office	2	Cracking, Chipping	6	No	No	N/A	Boxes	No	
310	7100	1	2	222	Administrative Office	Assistant Principal Suite Right Office	3	Chipping, Flaking, Efflorescence	30	Yes	Debris on windowsills	4	N/A	Yes	
311	7100	1	2	222	Administrative Office	Assistant Principal Suite Right Office	4	Flaking	13	No	No	N/A	N/A	No	
312	7100	1	2	222	Administrative Office	Assistant Principal Suite Right Office	c	Efflorescence above windows	3	Yes	No	N/A	N/A	Yes	
313	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	1	Chipping on doors and doorframes, Holes, Flaking on wall, doors, and doorframes	24	No	No	N/A	N/A	Yes	
314	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	2	Cracking, Efflorescence on wall and behind radiator	6	Yes	No	N/A	N/A	Yes	
315	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	3	Chipping, Flaking	9	No	No	N/A	N/A	No	
316	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	4	Hole behind radiator, Efflorescence	9	Yes	No	N/A	N/A	Yes	
317	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	c	Efflorescence	6	Yes	No	N/A	N/A	Yes	Plaster is assumed
318	7100	1	2	226	Auditorium Balcony	Auditorium Balcony	f	N/A	N/A	No	Debris and paint chips	30	N/A	No	
319	7100	1	2	226A	Control Booth Projection Room	Auditorium Balcony Projection Room	1	Cracking, Chipping, Holes	13	No	No	N/A	N/A	Yes	
320	7100	1	2	226A	Control Booth Projection Room	Auditorium Balcony Projection Room	2	Chipping	3	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
321	7100	1	2	226A	Control Booth Projection Room	Auditorium Balcony Projection Room	3	Chipping, Hole	3	No	No	N/A	ves, Stored Mate	Yes	Limited inspection due to shelves and stored materials
322	7100	1	2	226A	Control Booth Projection Room	Auditorium Balcony Projection Room	4	Cracking, Flaking on conduit	6	No	No	N/A	N/A	No	
323	7100	1	2	226A	Control Booth Projection Room	Auditorium Balcony Projection Room	c	Cracking, Holes	25	No	No	N/A	N/A	Yes	Plaster is assumed
324	7100	1	2	S23	Stairs	Blue Stairwell	1	Cracking, Chipping on conduit, Hole, paint has been stabilized	5	No	No	N/A	N/A	Yes	
325	7100	1	2	S23	Stairs	Blue Stairwell	2	Cracking	2	No	No	N/A	N/A	No	
326	7100	1	2	S23	Stairs	Blue Stairwell	3	Cracking, Chipping on conduit	9	No	No	N/A	N/A	No	
327	7100	1	2	S23	Stairs	Blue Stairwell	4	Cracking, Chipping on doors and doorframe	43	No	No	N/A	N/A	No	
328	7100	1	2	S23	Stairs	Blue Stairwell	c	Chipping, Flaking	8	No	No	N/A	N/A	No	
329	7100	1	2	S23	Stairs	Blue Stairwell	f	Chipping on floor and railings	123	No	No	N/A	N/A	No	
330	7100	1	2	220	Administrative Office	CASST Office	1	Cracking, Chipping on doorframe and wood cove base, Holes, Flaking	26	No	No	N/A	N/A	Yes	
331	7100	1	2	220	Administrative Office	CASST Office	2	Chipping, Flaking	7	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
332	7100	1	2	220	Administrative Office	CASST Office	3	Chippng, Flaking, Efflorescence, Significant Moisture Damage	10	Yes	No	N/A	N/A	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
333	7100	1	2	220	Administrative Office	CASST Office	4	Cracking, Chipping, Flaking	3	No	No	N/A	N/A	No	
334	7100	1	2	220	Administrative Office	CASST Office	c	Efflorescence above windows	5	Yes	No	N/A	N/A	Yes	
335	7100	1	2	201	Primary	Classroom 201	1	Chipping on wall and wood cove base, Staples	12	No	No	N/A	N/A	Yes	
336	7100	1	2	201	Primary	Classroom 201	2	Chipping	3	No	No	N/A	N/A	No	
337	7100	1	2	201	Primary	Classroom 201	3	Chipping, Flaking behind radiators	6	No	Debris on windowsills	7	N/A	No	
338	7100	1	2	201	Primary	Classroom 201	4	Chipping on wood cove base	1	No	No	N/A	N/A	No	
339	7100	1	2	201	Primary	Classroom 201	c	Flaking above windows, Efflorescence above windows, Significant Moisture Damage above missing ceiling tile	42	Yes	No	N/A	N/A	Yes	
340	7100	1	2	202	Primary	Classroom 202	1	Chipping, Hole, Staples	38	No	No	N/A	N/A	Yes	
341	7100	1	2	202	Primary	Classroom 202	2	Chipping	20	No	No	N/A	N/A	No	
342	7100	1	2	202	Primary	Classroom 202	3	Staples, Flaking behind radiator	9	No	Debris on windowsills	5	N/A	Yes	
343	7100	1	2	202	Primary	Classroom 202	c	Flaking, Significant Moisture Damage above windows	10	Yes	No	N/A	N/A	Yes	
344	7100	1	2	202A	Primary	Classroom 202A	1	Chipping, Hole, Flaking in air shafts, Efflorescence in air shafts	11	Yes	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
345	7100	1	2	202A	Primary	Classroom 202A	2	N/A	N/A	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
346	7100	1	2	202A	Primary	Classroom 202A	3	Chipping, Flaking	5	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
347	7100	1	2	202A	Primary	Classroom 202A	4	N/A	N/A	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
348	7100	1	2	202A	Primary	Classroom 202A	c	Flaking above missing ceiling tile	8	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
349	7100	1	2	202A	Primary	Classroom 202A	f	N/A	N/A	No	No	N/A	ves, Stored Mate	No	Limited inspection due to shelves and stored materials
350	7100	1	2	203	Primary	Classroom 203	1	Chipping, Staples and Staple Holes, Flaking	53	No	No	N/A	N/A	Yes	
351	7100	1	2	203	Primary	Classroom 203	2	Chipping, Staples and Staple Holes, Flaking	27	No	No	N/A	N/A	Yes	
352	7100	1	2	203	Primary	Classroom 203	3	Flaking behind radiators	7	No	Debris on windowsills	14	N/A	No	
353	7100	1	2	203	Primary	Classroom 203	4	Chipping	5	No	No	N/A	N/A	No	
354	7100	1	2	203	Primary	Classroom 203	c	Flaking, Efflorescence above windows	15	Yes	No	N/A	N/A	Yes	
355	7100	1	2	207	Primary	Classroom 207	1	Cracking, Chipping on wall and wood cove base, Staples	12	No	No	N/A	N/A	Yes	
356	7100	1	2	207	Primary	Classroom 207	2	Chipping on wood cove base, Staples	9	No	No	N/A	N/A	Yes	
357	7100	1	2	207	Primary	Classroom 207	3	Cracking, Chipping on wood cove base, Hole, Flaking behind radiators	14	No	No	N/A	N/A	Yes	
358	7100	1	2	207	Primary	Classroom 207	4	Chipping	4	No	No	N/A	N/A	No	
359	7100	1	2	207	Primary	Classroom 207	c	Significant Moisture Damage above missing ceiling tile	12	Yes	No	N/A	N/A	Yes	
360	7100	1	2	208	Primary	Classroom 208	1	Chipping on wall and wood cove base	10	No	No	N/A	N/A	No	
361	7100	1	2	208	Primary	Classroom 208	3	Chipping on wall and wood cove base, Staples, Flaking behind radiators	12	No	Debris on windowsills	5	N/A	Yes	
362	7100	1	2	208	Primary	Classroom 208	4	Chipping on wall and wood cove base	7	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
363	7100	1	2	208	Primary	Classroom 208	c	Flaking, Efflorescence above windows	11	Yes	No	N/A	N/A	Yes	
364	7100	1	2	209	Primary	Classroom 209	1	Cracking, Chipping on wall and wood cove base, Hole	13	No	No	N/A	N/A	Yes	
365	7100	1	2	209	Primary	Classroom 209	2	Cracking, Chipping on wall and wood cove base, Holes	19	No	No	N/A	N/A	Yes	
366	7100	1	2	209	Primary	Classroom 209	3	Cracking, Chipping, Hole, Flaking behind radiator	5	No	Debris on windowsills	3	N/A	Yes	
367	7100	1	2	209	Primary	Classroom 209	4	Chipping	11	No	No	N/A	N/A	No	
368	7100	1	2	209	Primary	Classroom 209	c	Flaking, Efflorescence above windows	13	Yes	No	N/A	N/A	Yes	
369	7100	1	2	210	Primary	Classroom 210	1	Cracking	1	No	No	N/A	Boxes	No	Limited inspection due to boxes
370	7100	1	2	210	Primary	Classroom 210	2	Chipping on wall and metal pipe	5	No	No	N/A	N/A	No	
371	7100	1	2	210	Primary	Classroom 210	3	Chipping on wall and wood cove base, Holes, Significant Moisture Damage behind radiator	11	Yes	No	N/A	Furniture	Yes	
372	7100	1	2	210	Primary	Classroom 210	4	Chipping on wall and wood cove base	16	No	No	N/A	N/A	No	
373	7100	1	2	210	Primary	Classroom 210	c	Flaking, Efflorescence above missing ceiling tile	2	Yes	No	N/A	N/A	Yes	
374	7100	1	2	211	Primary	Classroom 211	1	Cracking, Chipping on wall and wood cove base	17	No	No	N/A	N/A	No	
375	7100	1	2	211	Primary	Classroom 211	2	Chipping on wall, wood cove base, and bulletin board	20	No	No	N/A	N/A	No	
376	7100	1	2	211	Primary	Classroom 211	3	Cracking, Chipping on wall and wood cove base	22	No	Debris on windowsills	8	N/A	No	
377	7100	1	2	211	Primary	Classroom 211	4	Chipping on wall and wood cove base	10	No	No	N/A	N/A	No	
378	7100	1	2	211	Primary	Classroom 211	c	Flaking, Efflorescence above windows	13	Yes	No	N/A	N/A	Yes	
379	7100	1	2	211	Primary	Classroom 211	f	N/A	N/A	No	Debris	10	N/A	No	
380	7100	1	2	212	Primary	Classroom 212	1	Chipping, Staples and Staple Holes	38	No	No	N/A	N/A	Yes	
381	7100	1	2	212	Primary	Classroom 212	2	Chipping	10	No	No	N/A	N/A	No	
382	7100	1	2	212	Primary	Classroom 212	3	Cracking, Chipping, Staples and Staple Holes	12	No	No	N/A	N/A	Yes	
383	7100	1	2	212	Primary	Classroom 212	4	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to furniture
384	7100	1	2	212	Primary	Classroom 212	c	Flaking above windows	2	No	Paint chips on windowsills	1	N/A	No	
385	7100	1	2	213	Primary	Classroom 213	1	Chipping on wood cove base, Staples and Staple Holes	21	No	No	N/A	N/A	Yes	
386	7100	1	2	213	Primary	Classroom 213	2	Chipping, Staples and Staple Holes	24	No	No	N/A	N/A	Yes	
387	7100	1	2	213	Primary	Classroom 213	3	Cracking, Chipping on wall and wood cove base, Staples and Staple Holes	21	No	No	N/A	N/A	Yes	
388	7100	1	2	213	Primary	Classroom 213	c	Flaking above windows	8	No	No	N/A	N/A	No	
389	7100	1	2	214	Primary	Classroom 214	1	Chipping on wall and wood cove base, Staples and Staple Holes	38	No	No	N/A	N/A	Yes	
390	7100	1	2	214	Primary	Classroom 214	2	Chipping	10	No	No	N/A	N/A	No	
391	7100	1	2	214	Primary	Classroom 214	3	Cracking, Chipping on wood cove base, Staples and Staple Holes, Efflorescence behind radiator	24	Yes	No	N/A	N/A	Yes	
392	7100	1	2	214	Primary	Classroom 214	4	Staples and Staple Holes	40	No	No	N/A	N/A	Yes	
393	7100	1	2	215	Primary	Classroom 215	1	Chipping on wall and wood cove base, Staple Holes	61	No	No	N/A	N/A	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
394	7100	1	2	215	Primary	Classroom 215	2	Chipping on wall and wood cove base, Holes, Staples and Staple Holes	38	No	No	N/A	N/A	Yes	
395	7100	1	2	215	Primary	Classroom 215	3	Cracking, Chipping, Hole, Staples and Staple Holes, Flaking behind radiators	20	No	Debris on windowsills	3	N/A	Yes	
396	7100	1	2	215	Primary	Classroom 215	c	Flaking above windows	2	No	No	N/A	N/A	No	
397	7100	1	2	215	Primary	Classroom 215	f	N/A	N/A	No	Debris	20	N/A	No	
398	7100	1	2	216	Primary	Classroom 216	1	Chipping on wall and wood cove base	19	No	No	N/A	N/A	No	
399	7100	1	2	216	Primary	Classroom 216	2	Cracking, Chipping on wall and wood cove base	18	No	No	N/A	N/A	No	
400	7100	1	2	216	Primary	Classroom 216	3	Chipping on wall and wood cove base, Flaking	18	No	No	N/A	N/A	No	
401	7100	1	2	216	Primary	Classroom 216	4	Cracking, Chipping on wall and wood cove base	19	No	No	N/A	N/A	No	
402	7100	1	2	216	Primary	Classroom 216	c	Flaking, Efflorescence above windows	6	Yes	No	N/A	N/A	Yes	
403	7100	1	2	216	Primary	Classroom 216	f	N/A	N/A	No	Debris in air shaft	2	N/A	No	
404	7100	1	2	217	Primary	Classroom 217	1	Chipping on wall and wood cove base, Staple Holes	18	No	Debris on cove base	1	N/A	Yes	
405	7100	1	2	217	Primary	Classroom 217	2	Cracking, Chipping on wall and wood cove base	14	No	No	N/A	N/A	No	
406	7100	1	2	217	Primary	Classroom 217	3	Cracking, Chipping on wall and wood cove base	5	No	No	N/A	N/A	No	
407	7100	1	2	217	Primary	Classroom 217	4	Chipping on wall and wood cove base	8	No	No	N/A	N/A	No	
408	7100	1	2	217	Primary	Classroom 217	c	Flaking, Efflorescence above windows	5	Yes	No	N/A	N/A	Yes	
409	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
410	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
411	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
412	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
413	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
414	7100	1	2	201B	Storage	Closet adjacent to Classroom 201		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
415	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
416	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
417	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
418	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
419	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
420	7100	1	2	209F	Storage	Closet adjacent to Classroom 209		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
421	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	1	Chipping on doorframe and wood cove base, Staple Holes	23	No	No	N/A	Posters	Yes	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
422	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	2	Chipping	1	No	No	N/A	Cabinets	No	
423	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	3	Cracking, Significant Moisture Damage	6	Yes	No	N/A	N/A	Yes	
424	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	4	Cracking, Chipping	14	No	No	N/A	N/A	No	
425	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	c	Efflorescence above windows	4	Yes	No	N/A	N/A	Yes	
426	7100	1	2	221C	Administrative Office	Counselor's Office Suite Counselor's Office	f	N/A	N/A	No	Debris by radiator	2	N/A	No	
427	7100	1	2	221B	Administrative Office	Counselor's Office Suite Left Office	1	Chipping on wall, doorframe, and wood cove base	14	No	No	N/A	N/A	No	
428	7100	1	2	221B	Administrative Office	Counselor's Office Suite Left Office	2	Chipping on wall and wood cove base, Flaking	16	No	No	N/A	N/A	No	
429	7100	1	2	221B	Administrative Office	Counselor's Office Suite Left Office	3	Chipping on wall and wood cove base	10	No	No	N/A	N/A	No	
430	7100	1	2	221B	Administrative Office	Counselor's Office Suite Left Office	4	Chipping on wall and wood cove base	7	No	No	N/A	N/A	No	
431	7100	1	2	221D	Administrative Office	Counselor's Office Suite School Psychologist Office	1	Chipping on doorframe	10	No	No	N/A	Cabinets	No	
432	7100	1	2	221D	Administrative Office	Counselor's Office Suite School Psychologist Office	3	Significant Moisture Damage	1	Yes	Debris on windowsills	3	N/A	Yes	
433	7100	1	2	221D	Administrative Office	Counselor's Office Suite School Psychologist Office	c	Efflorescence above windows	3	Yes	No	N/A	N/A	Yes	
434	7100	1	2	221D	Administrative Office	Counselor's Office Suite School Psychologist Office	f	N/A	N/A	No	Debris along wall 3	4	N/A	No	
435	7100	1	2	221A	Administrative Office	Counselor's Office Suite Waiting Area	1	Cracking, Chipping on wood cove base	5	No	No	N/A	N/A	No	
436	7100	1	2	221A	Administrative Office	Counselor's Office Suite Waiting Area	2	Cracking, Flaking	4	No	No	N/A	Stored Materials	No	
437	7100	1	2	221A	Administrative Office	Counselor's Office Suite Waiting Area	3	Chipping	1	No	No	N/A	N/A	No	
438	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
439	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
440	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
441	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
442	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
443	7100	1	2	E1	Elevators, Passenger	Elevator		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
444	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	1	Chipping on door and doorframe, Flaking	72	No	No	N/A	N/A	No	
445	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	2	Cracking, Chipping, Flaking	62	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
446	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	3	Chipping on door and doorframe, Flaking	85	No	No	N/A	N/A	No	
447	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	4	Cracking, Flaking	80	No	No	N/A	N/A	No	
448	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	c	Flaking	420	No	No	N/A	N/A	No	
449	7100	1	2	S21	Stairs, Fire Tower	Fire Tower between Classrooms 211 and 212	f	N/A	N/A	No	Paint Chips	420	N/A	No	
450	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	1	Chipping on wall, doors, and doorframes, Flaking on wall and windows	118	No	No	N/A	N/A	No	
451	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	2	Chipping, Flaking on wall and metal pipes	40	No	No	N/A	N/A	No	
452	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	3	Chipping on door and doorframe, Flaking	100	No	No	N/A	N/A	No	
453	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	4	Chipping, Flaking	42	No	No	N/A	N/A	No	
454	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	c	Cracking, Flaking	433	No	No	N/A	N/A	No	
455	7100	1	2	S22	Stairs, Fire Tower	Fire Tower between Classrooms 215 and 216	f	N/A	N/A	No	Paint Chips	420	N/A	No	
456	7100	1	2	S26	Stairs	Green Stairwell	1	Cracking, Chipping on conduit	30	No	No	N/A	N/A	No	
457	7100	1	2	S26	Stairs	Green Stairwell	2	Cracking, Chipping on doors and doorframe	49	No	No	N/A	N/A	No	
458	7100	1	2	S26	Stairs	Green Stairwell	3	Cracking, Chipping on conduit	12	No	No	N/A	N/A	No	
459	7100	1	2	S26	Stairs	Green Stairwell	4	Cracking	10	No	No	N/A	N/A	No	
460	7100	1	2	S26	Stairs	Green Stairwell	c	Cracking, Flaking	8	No	No	N/A	N/A	No	
461	7100	1	2	S26	Stairs	Green Stairwell	f	Chipping on floor and railings	66	No	No	N/A	N/A	No	
462	7100	1	2	220A	Circulation (Hallway)	Hallway from Nurse's Office to CASST Office	1	Cracking, Chipping	10	No	No	N/A	Cabinets	No	
463	7100	1	2	220A	Circulation (Hallway)	Hallway from Nurse's Office to CASST Office	2	Cracking, Chipping	8	No	No	N/A	N/A	No	
464	7100	1	2	220A	Circulation (Hallway)	Hallway from Nurse's Office to CASST Office	3	Chipping	7	No	No	N/A	N/A	No	
465	7100	1	2	220A	Circulation (Hallway)	Hallway from Nurse's Office to CASST Office	4	Chipping	7	No	No	N/A	N/A	No	
466	7100	1	2	H28	Circulation (Hallway)	Hallway outside Classrooms 201-203	2	Cracking, Chipping on wall and metal lockers, Hole	429	No	No	N/A	N/A	Yes	
467	7100	1	2	H28	Circulation (Hallway)	Hallway outside Classrooms 201-203	4	Cracking	7	No	No	N/A	N/A	No	
468	7100	1	2	H28	Circulation (Hallway)	Hallway outside Classrooms 201-203	f	Chipping	26	No	No	N/A	N/A	No	
469	7100	1	2	H210	Circulation (Hallway)	Hallway outside Classrooms 207-209	2	Cracking, Holes, paint has been stabilized	25	No	No	N/A	N/A	Yes	
470	7100	1	2	H210	Circulation (Hallway)	Hallway outside Classrooms 207-209	4	Cracking, Chipping on metal lockers	428	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
471	7100	1	2	H210	Circulation (Hallway)	Hallway outside Classrooms 207-209	c	Significant Moisture Damage above missing ceiling tile	4	Yes	No	N/A	N/A	Yes	
472	7100	1	2	H210	Circulation (Hallway)	Hallway outside Classrooms 207-209	f	Chipping	17	No	No	N/A	N/A	No	
473	7100	1	2	H29	Circulation (Hallway)	Hallway outside Classrooms 210-217	1	Cracking, Chipping on wall, electrical panels, and metal lockers, Holes, Spalling	604	Yes	No	N/A	N/A	Yes	
474	7100	1	2	H29	Circulation (Hallway)	Hallway outside Classrooms 210-217	3	Cracking, Chipping on wall and metal lockers, Staples, Hole	602	No	No	N/A	N/A	Yes	
475	7100	1	2	H29	Circulation (Hallway)	Hallway outside Classrooms 210-217	f	Chipping	37	No	No	N/A	N/A	No	
476	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	1	Cracking, Hole	32	No	No	N/A	N/A	Yes	
477	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	2	Cracking	1	No	No	N/A	N/A	No	
478	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	3	Cracking, Chipping on electrical panel, Flaking	15	No	No	N/A	N/A	No	
479	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	4	Cracking	5	No	No	N/A	N/A	No	
480	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	c	Flaking above windows	6	No	No	N/A	N/A	No	
481	7100	1	2	H215	Circulation (Hallway)	Hallway outside IMC	f	Chipping	10	No	No	N/A	N/A	No	
482	7100	1	2	H216	Circulation (Hallway)	Hallway outside Main Office to Nurse's Office	1	Cracking	19	No	No	N/A	N/A	No	
483	7100	1	2	H216	Circulation (Hallway)	Hallway outside Main Office to Nurse's Office	3	Cracking, Chipping on wall and electrical panel, Flaking	29	No	No	N/A	N/A	No	
484	7100	1	2	H216	Circulation (Hallway)	Hallway outside Main Office to Nurse's Office	f	Chipping	30	No	No	N/A	N/A	No	
485	7100	1	2	205B	Circulation (Hallway)	Hallway outside Offices 205 and 205A	1	Cracking	1	No	No	N/A	N/A	No	
486	7100	1	2	205B	Circulation (Hallway)	Hallway outside Offices 205 and 205A	2	Cracking, Chipping on wall and doorframe, Holes above missing ceiling tile, Flaking above missing ceiling tile	33	No	No	N/A	N/A	Yes	
487	7100	1	2	205B	Circulation (Hallway)	Hallway outside Offices 205 and 205A	3	Chipping on wall and wood cove base	3	No	No	N/A	N/A	No	
488	7100	1	2	205B	Circulation (Hallway)	Hallway outside Offices 205 and 205A	4	Chipping	10	No	No	N/A	N/A	No	
489	7100	1	2	205B	Circulation (Hallway)	Hallway outside Offices 205 and 205A	c	Cracking, Hole above missing ceiling tile	6	No	No	N/A	N/A	Yes	
490	7100	1	2	204	IMC (Library)	IMC	1	Cracking, Chipping	20	No	No	N/A	Bookshelves	No	
491	7100	1	2	204	IMC (Library)	IMC	2	Cracking	3	No	No	N/A	N/A	No	
492	7100	1	2	204	IMC (Library)	IMC	3	Cracking, Hole, paint has been stabilized	11	No	Debris inside radiator cover	2	N/A	Yes	
493	7100	1	2	204	IMC (Library)	IMC	4	Cracking, Chipping	3	No	No	N/A	N/A	No	
494	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
495	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
496	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
497	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
498	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
499	7100	1	2	204A	Storage	IMC Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
500	7100	1	2	224	Administrative Office	Main Office	1	Cracking, Chipping, Flaking	31	No	No	N/A	N/A	No	
501	7100	1	2	224	Administrative Office	Main Office	2	Cracking, Chipping on wall, wood cove base, and metal pipe	9	No	No	N/A	N/A	No	
502	7100	1	2	224	Administrative Office	Main Office	3	Chipping on wood cove base	8	No	No	N/A	N/A	No	
503	7100	1	2	224	Administrative Office	Main Office	4	Cracking, Chipping on wall and wood cove base, Hole	20	No	No	N/A	N/A	No	
504	7100	1	2	224A	Restrooms, Staff - Male/Female	Main Office Restroom	1	Chipping on doorframe	2	No	No	N/A	N/A	No	
505	7100	1	2	224A	Restrooms, Staff - Male/Female	Main Office Restroom	2	Chipping	4	No	No	N/A	N/A	No	
506	7100	1	2	224A	Restrooms, Staff - Male/Female	Main Office Restroom	3	Chipping	5	No	No	N/A	N/A	No	
507	7100	1	2	224A	Restrooms, Staff - Male/Female	Main Office Restroom	4	Chipping	3	No	No	N/A	N/A	No	
508	7100	1	2	225	Storage	Main Office Supply Closet	1	Cracking, Chipping, Holes	36	No	Debris on power boxes	3	N/A	Yes	
509	7100	1	2	225	Storage	Main Office Supply Closet	2	Cracking, Holes	14	No	No	N/A	N/A	Yes	
510	7100	1	2	225	Storage	Main Office Supply Closet	3	Cracking, Significant Moisture Damage	56	Yes	No	N/A	N/A	Yes	Active condensate leak from AC unit. Wet wood floor and wood shelves.
511	7100	1	2	225	Storage	Main Office Supply Closet	4	Cracking, Flaking	11	No	No	N/A	N/A	No	
512	7100	1	2	225	Storage	Main Office Supply Closet	c	Cracking	9	No	No	N/A	N/A	No	
513	7100	1	2	H211	Circulation (Hallway)	Marble Hallway	1	Cracking, Staples	28	No	No	N/A	N/A	Yes	
514	7100	1	2	H211	Circulation (Hallway)	Marble Hallway	2	Staples, Flaking	13	No	No	N/A	N/A	Yes	
515	7100	1	2	H211	Circulation (Hallway)	Marble Hallway	3	Cracking, Hole, Staples	11	No	No	N/A	N/A	Yes	
516	7100	1	2	H211	Circulation (Hallway)	Marble Hallway	4	Chipping, Holes, Staples	14	No	No	N/A	N/A	Yes	
517	7100	1	2	H211	Circulation (Hallway)	Marble Hallway	c	Flaking	52	No	No	N/A	N/A	No	
518	7100	1	2	S25	Stairs	Marble Stairwell	1	Flaking, Spalling, Efflorescence	33	Yes	No	N/A	N/A	Yes	
519	7100	1	2	S25	Stairs	Marble Stairwell	2	Cracking, Staples, Flaking	29	No	No	N/A	N/A	Yes	
520	7100	1	2	S25	Stairs	Marble Stairwell	3	Hole, Staples	21	No	No	N/A	N/A	Yes	
521	7100	1	2	S25	Stairs	Marble Stairwell	4	Cracking, Staples, Flaking	31	No	No	N/A	N/A	Yes	
522	7100	1	2	S25	Stairs	Marble Stairwell	c	Flaking, Spalling	37	Yes	No	N/A	N/A	Yes	
523	7100	1	2	200	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom 200	1	Chipping on doorframe and wood cove base	21	No	No	N/A	N/A	No	
524	7100	1	2	200	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom 200	2	Cracking, Chipping on wood cove base	9	No	No	N/A	N/A	No	
525	7100	1	2	200	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom 200	3	Cracking, Flaking behind radiator	5	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
526	7100	1	2	200	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom 200	4	Cracking, Chipping on wood cove base	9	No	No	N/A	N/A	No	
527	7100	1	2	200	Teacher Lounge/Dining	Men's Lounge outside Men's Restroom 200	c	Holes, Flaking above missing ceiling tile	6	No	No	N/A	N/A	Yes	
528	7100	1	2	218	Health Service Room	Nurse's Office	1	Cracking, Chipping on wall and doorframe	19	No	No	N/A	N/A	No	
529	7100	1	2	218	Health Service Room	Nurse's Office	2	Chipping	5	No	No	N/A	N/A	No	
530	7100	1	2	218	Health Service Room	Nurse's Office	3	Cracking, Chipping	13	No	No	N/A	N/A	No	
531	7100	1	2	218	Health Service Room	Nurse's Office	4	Cracking, Chipping	6	No	No	N/A	N/A	No	
532	7100	1	2	218	Health Service Room	Nurse's Office	c	Hole, Flaking above windows	2	No	No	N/A	N/A	Yes	
533	7100	1	2	218B	Student Restrooms - Male/Female	Nurse's Office Center Restroom	1	Chipping on wall and doorframe	4	No	No	N/A	N/A	No	
534	7100	1	2	218B	Student Restrooms - Male/Female	Nurse's Office Center Restroom	2	N/A	N/A	No	Debris on ceramic tile	1	N/A	No	
535	7100	1	2	218B	Student Restrooms - Male/Female	Nurse's Office Center Restroom	3	Cracking	3	No	No	N/A	N/A	No	
536	7100	1	2	218E	Health Service Room	Nurse's Office Large Exam Room	1	Chipping on wall and doorframe, Hole, Flaking	20	No	No	N/A	N/A	Yes	
537	7100	1	2	218E	Health Service Room	Nurse's Office Large Exam Room	2	Chipping	4	No	No	N/A	N/A	No	
538	7100	1	2	218E	Health Service Room	Nurse's Office Large Exam Room	3	Chipping, Flaking	9	No	No	N/A	N/A	No	
539	7100	1	2	218E	Health Service Room	Nurse's Office Large Exam Room	4	Cracking, Hole	2	No	No	N/A	N/A	Yes	
540	7100	1	2	218A	Student Restrooms - Male/Female	Nurse's Office Restroom adjacent to Windows	1	Chipping on wall and doorframe	4	No	No	N/A	N/A	No	
541	7100	1	2	218A	Student Restrooms - Male/Female	Nurse's Office Restroom adjacent to Windows	2	Cracking	2	No	No	N/A	N/A	No	
542	7100	1	2	218A	Student Restrooms - Male/Female	Nurse's Office Restroom adjacent to Windows	3	Cracking	4	No	No	N/A	N/A	No	
543	7100	1	2	218A	Student Restrooms - Male/Female	Nurse's Office Restroom adjacent to Windows	4	N/A	N/A	No	Debris on ceramic tile	1	N/A	No	
544	7100	1	2	218D	Health Service Room	Nurse's Office Small Exam Room	1	Chipping on wall and doorframe	7	No	No	N/A	N/A	No	
545	7100	1	2	218D	Health Service Room	Nurse's Office Small Exam Room	2	Cracking, Chipping, Hole	9	No	No	N/A	N/A	Yes	
546	7100	1	2	218D	Health Service Room	Nurse's Office Small Exam Room	3	Chipping	3	No	No	N/A	Cabinets	No	
547	7100	1	2	218D	Health Service Room	Nurse's Office Small Exam Room	4	Chipping	7	No	No	N/A	N/A	No	
548	7100	1	2	218C	Storage	Nurse's Office Storage Room	1	Chipping on doorframe	8	No	No	N/A	Cabinets	No	
549	7100	1	2	218C	Storage	Nurse's Office Storage Room	2	Chipping on wall and wood cove base, Hole	5	No	No	N/A	Cabinets	No	
550	7100	1	2	218C	Storage	Nurse's Office Storage Room	3	Cracking, Flaking	31	No	No	N/A	Cabinets	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
551	7100	1	2	218C	Storage	Nurse's Office Storage Room	4	Cracking, Flaking	9	No	No	N/A	Cabinets	No	
552	7100	1	2	205	Administrative Office	Office 205	1	Chipping on doorframe and wood cove base	16	No	No	N/A	Built in shelves	No	
553	7100	1	2	205	Administrative Office	Office 205	2	Chipping, Holes	3	No	No	N/A	Cabinets	Yes	
554	7100	1	2	205	Administrative Office	Office 205	3	Chipping, Flaking	18	No	Debris on windowsills	6	N/A	No	
555	7100	1	2	205	Administrative Office	Office 205	4	N/A	N/A	No	No	N/A	Built in shelves	No	
556	7100	1	2	205	Administrative Office	Office 205	c	Hole, Flaking above missing ceiling tile	7	No	No	N/A	N/A	Yes	
557	7100	1	2	205	Administrative Office	Office 205	f	N/A	N/A	No	No	N/A	N/A	No	
558	7100	1	2	205A	Administrative Office	Office 205A	1	Cracking, Flaking	14	No	No	N/A	Built in shelves	No	
559	7100	1	2	205A	Administrative Office	Office 205A	2	Cracking, Hole, paint has been stabilized, Flaking above missing ceiling tile	10	No	No	N/A	N/A	Yes	
560	7100	1	2	205A	Administrative Office	Office 205A	3	Cracking	3	No	Debris on windowsills	4	Cabinets	No	
561	7100	1	2	205A	Administrative Office	Office 205A	4	Holes, some above missing ceiling tile, Flaking above missing ceiling tile	18	No	No	N/A	N/A	Yes	
562	7100	1	2	205A	Administrative Office	Office 205A	c	Flaking, Significant Moisture Damage above missing ceiling tile	26	Yes	No	N/A	N/A	Yes	
563	7100	1	2	205A	Administrative Office	Office 205A	f	N/A	N/A	No	Debris along wall 2	2	N/A	No	
564	7100	1	2	223A	Administrative Office	Principal's Office	1	Chipping on wood cove base, Hole	2	No	No	N/A	N/A	Yes	
565	7100	1	2	223A	Administrative Office	Principal's Office	2	Cracking	2	No	No	N/A	N/A	No	
566	7100	1	2	223A	Administrative Office	Principal's Office	3	Cracking, Chipping on wood cove base	3	No	Debris on windowsills	1	N/A	No	
567	7100	1	2	223A	Administrative Office	Principal's Office	4	Cracking, Chipping	10	No	No	N/A	N/A	No	
568	7100	1	2	223A	Administrative Office	Principal's Office	c	Efflorescence above windows	3	Yes	No	N/A	N/A	Yes	
569	7100	1	2	223B	Restrooms, Staff - Male/Female	Principal's Office Restroom	1	Chipping on wall and doorframe	2	No	No	N/A	N/A	No	
570	7100	1	2	S27	Stairs	Red Stairwell	2	Efflorescence	10	Yes	No	N/A	N/A	Yes	
571	7100	1	2	S27	Stairs	Red Stairwell	3	Cracking, Chipping on conduit, Efflorescence	11	Yes	No	N/A	N/A	Yes	
572	7100	1	2	S27	Stairs	Red Stairwell	4	Chipping on doors and doorframe, Hole, paint has been stabilized, Flaking	35	No	No	N/A	N/A	Yes	
573	7100	1	2	S27	Stairs	Red Stairwell	c	Flaking, Spalling, Efflorescence	23	Yes	No	N/A	N/A	Yes	
574	7100	1	2	S27	Stairs	Red Stairwell	f	Chipping on floor and railings	63	No	Debris	5	N/A	No	
575	7100	1	2	221	Administrative Office	Roster Room 221B	1	Chipping, Holes, Flaking	16	No	No	N/A	N/A	Yes	
576	7100	1	2	221	Administrative Office	Roster Room 221B	2	Chipping on wall, doorframe, and wood cove base	10	No	No	N/A	N/A	No	
577	7100	1	2	221	Administrative Office	Roster Room 221B	3	Chipping on wall and wood cove base	6	No	No	N/A	N/A	No	
578	7100	1	2	221	Administrative Office	Roster Room 221B	4	Chipping, Holes, Flaking	12	No	No	N/A	N/A	Yes	
579	7100	1	2	206	Administrative Office	School Police Office 206	1	Chipping on wall, doorframe, and wood cove base	37	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
580	7100	1	2	206	Administrative Office	School Police Office 206	2	Cracking, Chipping, Flaking	10	No	No	N/A	Cabinets	No	
581	7100	1	2	206	Administrative Office	School Police Office 206	3	Flaking, Efflorescence	29	Yes	No	N/A	N/A	Yes	
582	7100	1	2	206	Administrative Office	School Police Office 206	4	Cracking, Chipping	16	No	No	N/A	N/A	No	
583	7100	1	2	206	Administrative Office	School Police Office 206	c	Efflorescence above windows, Significant Moisture Damage above missing ceiling tile	16	Yes	No	N/A	N/A	Yes	
584	7100	1	2	206	Administrative Office	School Police Office 206	f	N/A	N/A	No	Debris on windowsills and along wall 3	17	N/A	No	
585	7100	1	2	219	Administrative Office	Speech and Hearing Office	1	Chipping on wall, doorframe, and wood cove base	8	No	No	N/A	N/A	No	
586	7100	1	2	219	Administrative Office	Speech and Hearing Office	2	Chipping	5	No	No	N/A	Cabinets	No	
587	7100	1	2	219	Administrative Office	Speech and Hearing Office	4	Chipping on wall and wood cove base	12	No	No	N/A	N/A	No	
588	7100	1	2	219	Administrative Office	Speech and Hearing Office	c	Flaking above windows	1	No	No	N/A	N/A	No	
589	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
590	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
591	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
592	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
593	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
594	7100	1	2	226B	Storage	Storage below Auditorium Balcony Projection Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
595	7100	1	2	207A	Storage	Storage Room 207A	1	Chipping, Hole, Flaking in air shaft	9	ole br 2 flk in	No	N/A	N/A	No	
596	7100	1	2	207A	Storage	Storage Room 207A	2	N/A	N/A	No	No	N/A	es with stored ma	No	
597	7100	1	2	207A	Storage	Storage Room 207A	3	Flaking on wall and metal pipe	35	metal pipe 2	No	N/A	Boxes	No	
598	7100	1	2	207A	Storage	Storage Room 207A	4	N/A	N/A	No	No	N/A	es with stored ma	No	
599	7100	1	2	207A	Storage	Storage Room 207A	c	Flaking	180	chalk flk	No	N/A	N/A	No	
600	7100	1	2	214A	Storage	Storage Room across from Classroom 213	1	Cracking, Hole	6	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
601	7100	1	2	214A	Storage	Storage Room across from Classroom 213	2	Cracking	20	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
602	7100	1	2	214A	Storage	Storage Room across from Classroom 213	3	Cracking	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
603	7100	1	2	214A	Storage	Storage Room across from Classroom 213	4	Cracking	100	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
604	7100	1	2	214A	Storage	Storage Room across from Classroom 213	c	Cracking	135	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
605	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
606	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
607	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
608	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
609	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
610	7100	1	2	215A	Storage	Storage Room across from Classroom 214		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
611	7100	1	2	209B	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	1	Chipping on doorframe	15	No	No	N/A	N/A	No	
612	7100	1	2	209B	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	2	Cracking, Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
613	7100	1	2	209B	Teacher Lounge/Dining	Women's Lounge outside Women's Restroom	4	Chipping, Hole	3	No	No	N/A	N/A	Yes	
614	7100	1	2	S24	Stairs	Yellow Stairwell	1	Cracking	9	No	No	N/A	N/A	No	
615	7100	1	2	S24	Stairs	Yellow Stairwell	2	Cracking, Chipping on doors and doorframe, Hole	33	No	No	N/A	N/A	Yes	
616	7100	1	2	S24	Stairs	Yellow Stairwell	3	Cracking, Chipping on conduit	19	No	No	N/A	N/A	No	
617	7100	1	2	S24	Stairs	Yellow Stairwell	4	Cracking	4	No	No	N/A	N/A	No	
618	7100	1	2	S24	Stairs	Yellow Stairwell	c	Cracking, Flaking	15	No	No	N/A	N/A	No	
619	7100	1	2	S24	Stairs	Yellow Stairwell	f	Chipping on floor and railings	88	No	No	N/A	N/A	No	
620	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	1	Chipping on door and doorframe	23	No	No	N/A	N/A	No	
621	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	2	Cracking, Flaking on marble	17	No	No	N/A	N/A	No	
622	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	3	Cracking, Efflorescence above missing ceiling tile, Significant Moisture Damage Above missing ceiling tile	16	Yes	No	N/A	N/A	Yes	
623	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	4	Cracking, some above missing ceiling tile, Chipping	15	No	No	N/A	N/A	No	
624	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	c	Flaking, Significant Moisture Damage above missing ceiling tile	12	Yes	No	N/A	N/A	Yes	
625	7100	1	1	101B	Student Restrooms - Male (4-12)	1st Floor Boy's Restroom	f	N/A	N/A	No	Paint chips	2	N/A	No	
626	7100	1	1	110B	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	1	Chipping on door and doorframe	19	No	No	N/A	N/A	No	
627	7100	1	1	110B	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	2	Cracking	2	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
628	7100	1	1	110B	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	3	Cracking	7	No	No	N/A	N/A	No	
629	7100	1	1	110B	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	4	Cracking, Efflorescence behind broken marble	5	Yes	No	N/A	N/A	No	
630	7100	1	1	110B	Student Restrooms - Female (4-12)	1st Floor Girl's Restroom	c	Cracking, Flaking on metal pipes, Spalling	17	Yes	No	N/A	N/A	No	
631	7100	1	1	104A	Restrooms, Staff - Male	1st Floor Men's Restroom	2	Cracking, Chipping, Holes, Flaking	29	No	No	N/A	N/A	Yes	
632	7100	1	1	104A	Restrooms, Staff - Male	1st Floor Men's Restroom	3	Flaking	20	No	No	N/A	N/A	No	
633	7100	1	1	104A	Restrooms, Staff - Male	1st Floor Men's Restroom	4	Chipping on wall and radiator, Hole, Flaking, Spalling	42	Yes	No	N/A	N/A	Yes	
634	7100	1	1	104A	Restrooms, Staff - Male	1st Floor Men's Restroom	c	Cracking	12	No	No	N/A	N/A	No	
635	7100	1	1	104A	Restrooms, Staff - Male	1st Floor Men's Restroom	f	Spalling	6	No	No	N/A	N/A	No	
636	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	1	Cracking, Chipping	17	No	No	N/A	N/A	No	
637	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	2	Cracking, Chipping on wall and radiator	38	No	No	N/A	N/A	No	
638	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	3	Cracking, Flaking	16	No	No	N/A	N/A	No	
639	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	4	Cracking, Chipping, Holes, Flaking	83	No	No	N/A	N/A	Yes	
640	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	c	Hole, Flaking	23	No	No	N/A	N/A	Yes	
641	7100	1	1	105A	Restrooms, Staff - Female	1st Floor Women's Restroom	f	Chipping	50	No	No	N/A	N/A	No	
642	7100	1	1	101A	Administrative Office	After School Program Office	1	Flaking in air shaft	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
643	7100	1	1	101A	Administrative Office	After School Program Office	2	Chipping	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
644	7100	1	1	101A	Administrative Office	After School Program Office	3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
645	7100	1	1	101A	Administrative Office	After School Program Office	4	Chipping on electrical panel	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
646	7100	1	1	101A	Administrative Office	After School Program Office	c	N/A	N/A	No	No	N/A	N/A	No	
647	7100	1	1	113	Auditorium	Auditorium	1	Chipping, Hole	40	No	No	N/A	N/A	No	
648	7100	1	1	113	Auditorium	Auditorium	2	Chipping, Flaking, Efflorescence	46	Yes	No	N/A	N/A	Yes	
649	7100	1	1	113	Auditorium	Auditorium	3	Flaking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
650	7100	1	1	113	Auditorium	Auditorium	4	Chipping, Efflorescence	3	Yes	No	N/A	N/A	Yes	
651	7100	1	1	113	Auditorium	Auditorium	c	Flaking	17	No	No	N/A	N/A	No	Plaster is assumed
652	7100	1	1	113	Auditorium	Auditorium	f	N/A	N/A	No	Debris and Paint Chips	50	N/A	No	
653	7100	1	1	113A	Stage	Auditorium Stage	2	Hole, Flaking	4	No	No	N/A	N/A	Yes	
654	7100	1	1	113A	Stage	Auditorium Stage	4	Flaking	2	No	No	N/A	N/A	No	
655	7100	1	1	113A	Stage	Auditorium Stage	c	Efflorescence	15	Yes	No	N/A	N/A	Yes	Plaster is assumed
656	7100	1	1	113A	Stage	Auditorium Stage	f	N/A	N/A	No	Debris	10	N/A	No	
657	7100	1	1	S13	Stairs	Blue Stairwell	1	Chipping on conduit	3	No	No	N/A	N/A	No	
658	7100	1	1	S13	Stairs	Blue Stairwell	2	N/A	N/A	No	No	N/A	N/A	No	
659	7100	1	1	S13	Stairs	Blue Stairwell	3	Cracking	5	No	No	N/A	N/A	No	
660	7100	1	1	S13	Stairs	Blue Stairwell	4	Cracking, Chipping on doors and doorframe	43	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
661	7100	1	1	S13	Stairs	Blue Stairwell	f	Chipping	28	No	No	N/A	N/A	No	
662	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
663	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
664	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
665	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
666	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
667	7100	1	1	S13A	Storage	Blue Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
668	7100	1	1	118	Cafeteria (Dining Area)	Boy's Cafeteria	1	Chipping on wall, doors, and doorframe	47	No	No	N/A	N/A	No	
669	7100	1	1	118	Cafeteria (Dining Area)	Boy's Cafeteria	3	Chipping on doors, doorframe, radiators, and metal pipes	62	No	No	N/A	N/A	No	
670	7100	1	1	118	Cafeteria (Dining Area)	Boy's Cafeteria	4	Chipping	7	No	No	N/A	N/A	No	
671	7100	1	1	118	Cafeteria (Dining Area)	Boy's Cafeteria	c	Flaking above missing ceiling tile	5	No	No	N/A	N/A	No	
672	7100	1	1	130	Kitchen Serving Area	Boy's Cafeteria Kitchen Serving Area	1	Chipping on doorframes	7	No	No	N/A	N/A	No	
673	7100	1	1	130	Kitchen Serving Area	Boy's Cafeteria Kitchen Serving Area	2	Chipping on doorframe	6	No	No	N/A	N/A	No	
674	7100	1	1	130	Kitchen Serving Area	Boy's Cafeteria Kitchen Serving Area	3	Chipping on wall, doors, and doorframe	20	No	No	N/A	N/A	No	
675	7100	1	1	130	Kitchen Serving Area	Boy's Cafeteria Kitchen Serving Area	c	Cracking	6	No	No	N/A	N/A	No	
676	7100	1	1	117C	Lockers - Female	Cafeteria Worker's Locker Room	1	Cracking, Chipping on wall, door, and doorframe, Hole, Flaking	15	No	No	N/A	N/A	Yes	
677	7100	1	1	117C	Lockers - Female	Cafeteria Worker's Locker Room	2	Cracking, Hole, Flaking	4	No	No	N/A	N/A	Yes	
678	7100	1	1	117C	Lockers - Female	Cafeteria Worker's Locker Room	3	Flaking	4	No	No	N/A	N/A	No	
679	7100	1	1	117C	Lockers - Female	Cafeteria Worker's Locker Room	4	Chipping, Hole	3	No	No	N/A	Lockers	Yes	
680	7100	1	1	117C	Lockers - Female	Cafeteria Worker's Locker Room	c	Cracking	2	No	No	N/A	N/A	No	
681	7100	1	1	101C	Primary	Classroom 101 After School Program	1	Flaking in air shaft	6	No	No	N/A	N/A	No	
682	7100	1	1	101C	Primary	Classroom 101 After School Program	4	Chipping on wall and cove base	13	No	No	N/A	N/A	No	
683	7100	1	1	101C	Primary	Classroom 101 After School Program	c	Flaking above windows	3	No	No	N/A	N/A	No	
684	7100	1	1	101C	Primary	Classroom 101 After School Program	f	Chipping	35	No	No	N/A	N/A	No	
685	7100	1	1	101D	Storage	Classroom 101 Closet	1	Chipping	3	No	No	N/A	Built in Shelves	No	
686	7100	1	1	101D	Storage	Classroom 101 Closet	2	Chipping, Holes	7	No	No	N/A	Cabinet	No	
687	7100	1	1	101D	Storage	Classroom 101 Closet	3	N/A	N/A	No	No	N/A	Built in Shelves	No	
688	7100	1	1	101D	Storage	Classroom 101 Closet	4	N/A	N/A	No	No	N/A	Built in Shelves	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
689	7100	1	1	101D	Storage	Classroom 101 Closet	c	Chipping	3	No	No	N/A	N/A	No	
690	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
691	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
692	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
693	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
694	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
695	7100	1	1	102C	Primary	Classroom 102		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
696	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
697	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
698	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
699	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
700	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
701	7100	1	1	102F	Storage	Classroom 102 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
702	7100	1	1	103	Primary	Classroom 103	1	Chipping, Flaking in air shafts	21	No	No	N/A	N/A	No	
703	7100	1	1	103	Primary	Classroom 103	2	Chipping, Flaking	12	No	No	N/A	N/A	No	
704	7100	1	1	103	Primary	Classroom 103	3	Chipping on wall and windowframes	21	No	No	N/A	N/A	No	
705	7100	1	1	103	Primary	Classroom 103	4	Chipping on wall and windowframe	11	No	No	N/A	N/A	No	
706	7100	1	1	103	Primary	Classroom 103	f	Chipping	43	No	No	N/A	N/A	No	
707	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
708	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
709	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
710	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
711	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
712	7100	1	1	103B	Storage	Classroom 103 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
713	7100	1	1	103C	Primary	Classroom 103 Small Group Instruction Room	1	Chipping on wall and doorframe	8	No	No	N/A	N/A	No	
714	7100	1	1	103C	Primary	Classroom 103 Small Group Instruction Room	2	N/A	N/A	No	No	N/A	Stored Materials	No	
715	7100	1	1	103C	Primary	Classroom 103 Small Group Instruction Room	3	Chipping	2	No	No	N/A	Stored Materials	No	
716	7100	1	1	103C	Primary	Classroom 103 Small Group Instruction Room	4	N/A	N/A	No	No	N/A	Stored Materials	No	
717	7100	1	1	104	Primary	Classroom 104	1	Chipping, Flaking on wall and in air shafts	16	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
718	7100	1	1	104	Primary	Classroom 104	2	Chipping	5	No	No	N/A	N/A	No	
719	7100	1	1	104	Primary	Classroom 104	3	Chipping	6	No	No	N/A	N/A	No	
720	7100	1	1	104	Primary	Classroom 104	4	Chipping	5	No	No	N/A	N/A	No	
721	7100	1	1	104	Primary	Classroom 104	f	Chipping	41	No	No	N/A	N/A	No	
722	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
723	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
724	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
725	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
726	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
727	7100	1	1	104B	Storage	Classroom 104 Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
728	7100	1	1	104C	Kitchen	Classroom 104 Kitchen	1	Chipping on wall and doorframe, Gouge	9	No	No	N/A	N/A	No	
729	7100	1	1	104C	Kitchen	Classroom 104 Kitchen	2	Chipping	7	No	No	N/A	Stored Materials	No	
730	7100	1	1	104C	Kitchen	Classroom 104 Kitchen	3	Chipping, Flaking	2	No	No	N/A	Stored Materials	No	
731	7100	1	1	104C	Kitchen	Classroom 104 Kitchen	4	Flaking	6	No	No	N/A	N/A	No	
732	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	1	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
733	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	2	Flaking on metal pipe	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
734	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	3	Holes, Flaking	20	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
735	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	4	Holes	10	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
736	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	c	Flaking	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
737	7100	1	1	104D	Storage	Classroom 104 Kitchen Closet	f	N/A	N/A	No	Paint Chips	60	Stored Materials	No	Limited inspection due to stored materials
738	7100	1	1	105	Music	Classroom 105	1	Cracking, Chipping	6	No	No	N/A	N/A	No	
739	7100	1	1	105	Music	Classroom 105	2	Cracking, Chipping	17	No	No	N/A	N/A	No	
740	7100	1	1	105	Music	Classroom 105	3	Cracking, Chipping, Flaking behind radiator	13	No	No	N/A	N/A	No	
741	7100	1	1	105	Music	Classroom 105	4	Cracking, Chipping	7	No	No	N/A	N/A	No	
742	7100	1	1	105	Music	Classroom 105	c	Flaking, Efflorescence above windows	11	Yes	No	N/A	N/A	Yes	
743	7100	1	1	105	Music	Classroom 105	f	Chipping	60	No	No	N/A	N/A	No	
744	7100	1	1	108	Music	Classroom 108	1	Cracking, Chipping, Holes, Flaking	5	No	No	N/A	N/A	No	
745	7100	1	1	108	Music	Classroom 108	2	Cracking, Chipping, Flaking	19	No	No	N/A	N/A	No	
746	7100	1	1	108	Music	Classroom 108	3	Cracking, Chipping	7	No	No	N/A	N/A	No	
747	7100	1	1	108	Music	Classroom 108	4	Cracking, Chipping	11	No	No	N/A	N/A	No	
748	7100	1	1	108	Music	Classroom 108	c	Flaking, Efflorescence, Significant Moisture Damage above windows	15	No	No	N/A	N/A	No	
749	7100	1	1	108	Music	Classroom 108	f	Chipping	42	No	No	N/A	N/A	No	
750	7100	1	1	108A	Storage	Classroom 108 Closet	1	Cracking	5	No	No	N/A	Wilt in wood shelves	No	
751	7100	1	1	108A	Storage	Classroom 108 Closet	2	Hole	1	No	No	N/A	Wilt in wood shelves	No	
752	7100	1	1	108A	Storage	Classroom 108 Closet	3	Cracking, Chipping, Efflorescence	40	Yes	No	N/A	Wilt in wood shelves	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
753	7100	1	1	108A	Storage	Classroom 108 Closet	4	Cracking, Hole, Efflorescence	16	Yes	No	N/A	N/A	No	
754	7100	1	1	108A	Storage	Classroom 108 Closet	c	Efflorescence	6	Yes	No	N/A	N/A	No	
755	7100	1	1	108A	Storage	Classroom 108 Closet	f	Chipping	6	No	No	N/A	N/A	No	
756	7100	1	1	110	Primary	Classroom 110	1	Chipping, Flaking in air shaft	43	No	No	N/A	N/A	No	
757	7100	1	1	110	Primary	Classroom 110	2	Chipping	31	No	No	N/A	N/A	No	
758	7100	1	1	110	Primary	Classroom 110	3	Chipping, Flaking on metal pipe and windowframes	93	No	No	N/A	N/A	No	
759	7100	1	1	110	Primary	Classroom 110	c	Flaking above missing ceiling tile	25	No	No	N/A	N/A	No	
760	7100	1	1	110	Primary	Classroom 110	f	N/A	N/A	No	Paint chips along wall 3	5	N/A	No	
761	7100	1	1	102	Gymnasium - Intermediate Middle	East Gym	1	Chipping on metal pipes, Flaking	25	No	No	N/A	N/A	No	
762	7100	1	1	102	Gymnasium - Intermediate Middle	East Gym	2	Cracking, Chipping	10	No	No	N/A	N/A	No	
763	7100	1	1	102	Gymnasium - Intermediate Middle	East Gym	3	Chipping on metal pipe, Flaking	41	No	No	N/A	N/A	No	
764	7100	1	1	102	Gymnasium - Intermediate Middle	East Gym	4	Flaking	18	No	No	N/A	N/A	No	
765	7100	1	1	102	Gymnasium - Intermediate Middle	East Gym	c	Chipping on metal pipes, Flaking	77	No	No	N/A	N/A	No	
766	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
767	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
768	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
769	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
770	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
771	7100	1	1	102D	Lockers - Male	East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
772	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
773	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
774	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
775	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
776	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
777	7100	1	1	102F	Student Restrooms - Male (4-12)	East Gym Locker Room Restroom		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
778	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
779	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
780	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
781	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
782	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
783	7100	1	1	102E	Showers - Male	East Gym Locker Room Showers		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
784	7100	1	1	102K	Administrative Office	East Gym Office	1	Chipping, Holes	5	No	No	N/A	N/A	Yes	
785	7100	1	1	102K	Administrative Office	East Gym Office	2	Cracking, Chipping	6	No	No	N/A	N/A	No	
786	7100	1	1	102K	Administrative Office	East Gym Office	3	Chipping	11	No	No	N/A	N/A	No	
787	7100	1	1	102K	Administrative Office	East Gym Office	4	Cracking, Chipping	6	No	No	N/A	N/A	No	
788	7100	1	1	102K	Administrative Office	East Gym Office	c	Chipping	1	No	No	N/A	N/A	No	
789	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
790	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
791	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
792	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
793	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
794	7100	1	1	102J	Storage	East Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
795	7100	1	1	102H	Storage	East Gym Storage Room Closest to Entrance	1	Chipping	35	No	No	N/A	red Gym Equipm	No	
796	7100	1	1	102H	Storage	East Gym Storage Room Closest to Entrance	2	Chipping	3	No	No	N/A	red Gym Equipm	No	
797	7100	1	1	102H	Storage	East Gym Storage Room Closest to Entrance	3	Cracking	5	No	No	N/A	red Gym Equipm	No	
798	7100	1	1	102H	Storage	East Gym Storage Room Closest to Entrance	4	Chipping	5	No	No	N/A	red Gym Equipm	No	
799	7100	1	1	102H	Storage	East Gym Storage Room Closest to Entrance	c	Chipping on metal pipe	15	No	No	N/A	N/A	No	
800	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	1	Chipping	100	No	No	N/A	red Gym Equipm	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
801	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	2	Chipping	3	No	No	N/A	red Gym Equipm	No	
802	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	3	Chipping	3	No	No	N/A	red Gym Equipm	No	
803	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	4	Chipping	50	No	No	N/A	red Gym Equipm	No	
804	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	c	Chipping on metal pipe, Flaking	23	No	No	N/A	N/A	No	
805	7100	1	1	102B	Storage	East Gym Storage Room Farthest from Entrance	f	N/A	N/A	No	Paint Chips	25	N/A	No	
806	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
807	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
808	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
809	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
810	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
811	7100	1	1	102G	Storage	East Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
812	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
813	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
814	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
815	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
816	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
817	7100	1	1	S12	Stairs, Fire Tower	Fire Tower adjacent to Boy's Cafeteria									This space is included in the 2nd floor fire tower
818	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower
819	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower
820	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower
821	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
822	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower
823	7100	1	1	S11	Stairs, Fire Tower	Fire Tower adjacent to Girl's Cafeteria									This space is included in the 2nd floor fire tower
824	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	1	Chipping on wall, doors, and doorframes	74	No	No	N/A	N/A	No	
825	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	2	Chipping, Flaking above missing ceiling tile	25	No	No	N/A	N/A	No	
826	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	3	Chipping on wall, doors, doorframes, radiators, and metal pipes	74	No	No	N/A	N/A	No	
827	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	4	Chipping	29	No	No	N/A	N/A	No	
828	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	c	Flaking above missing ceiling tile	12	No	No	N/A	N/A	No	
829	7100	1	1	115	Cafeteria (Dining Area)	Girl's Cafeteria	f	Chipping	33	No	No	N/A	N/A	No	
830	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
831	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
832	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
833	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
834	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
835	7100	1	1	115A	Storage	Girl's Cafeteria Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
836	7100	1	1	131	Kitchen Serving Area	Girl's Cafeteria Kitchen Serving Area	1	Chipping on doorframe	8	No	No	N/A	N/A	No	
837	7100	1	1	131	Kitchen Serving Area	Girl's Cafeteria Kitchen Serving Area	4	Chipping on wall and doorframe	3	No	No	N/A	N/A	No	
838	7100	1	1	131	Kitchen Serving Area	Girl's Cafeteria Kitchen Serving Area	c	Flaking on metal duct	18	No	No	N/A	N/A	No	
839	7100	1	1	S16	Stairs	Green Stairwell	1	Cracking	12	No	No	N/A	N/A	No	
840	7100	1	1	S16	Stairs	Green Stairwell	2	Cracking, Chipping on doors and doorframe	36	No	No	N/A	N/A	No	
841	7100	1	1	S16	Stairs	Green Stairwell	3	Chipping on conduit	3	No	No	N/A	N/A	No	
842	7100	1	1	S16	Stairs	Green Stairwell	4	Cracking, Chipping, Flaking	5	No	No	N/A	N/A	No	
843	7100	1	1	S16	Stairs	Green Stairwell	c	Cracking, Chipping, Flaking	5	No	No	N/A	N/A	No	
844	7100	1	1	S16	Stairs	Green Stairwell	f	Chipping	2	No	No	N/A	N/A	No	
845	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
846	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
847	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
848	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
849	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
850	7100	1	1	S16A	Storage	Green Stairwell Storage Room closest to Hallway		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
851	7100	1	1	103D	Circulation (Hallway)	Hallway 103A between Classrooms 103 and 104	1	Chipping on doorframe, Hole	3	No	No	N/A	N/A	Yes	
852	7100	1	1	103D	Circulation (Hallway)	Hallway 103A between Classrooms 103 and 104	2	Cracking, Chipping on wood cove base	10	No	No	N/A	N/A	No	
853	7100	1	1	103D	Circulation (Hallway)	Hallway 103A between Classrooms 103 and 104	3	Cracking, Chipping	2	No	No	N/A	N/A	No	
854	7100	1	1	103D	Circulation (Hallway)	Hallway 103A between Classrooms 103 and 104	4	Cracking, Chipping on wood cove base	12	No	No	N/A	N/A	No	
855	7100	1	1	H113	Circulation (Hallway)	Hallway adjacent to Left Side of Auditorium	2	Cracking, Efflorescence	33	Yes	No	N/A	N/A	Yes	
856	7100	1	1	H113	Circulation (Hallway)	Hallway adjacent to Left Side of Auditorium	4	Cracking	2	No	No	N/A	N/A	No	
857	7100	1	1	H113	Circulation (Hallway)	Hallway adjacent to Left Side of Auditorium	c	Cracking, Spalling	19	Yes	No	N/A	N/A	Yes	
858	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	1	N/A	N/A	No	No	N/A	N/A	No	
859	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	2	Chipping	8	No	No	N/A	N/A	No	
860	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	3	N/A	N/A	No	No	N/A	N/A	No	
861	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	4	Chipping	2	No	No	N/A	N/A	No	
862	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	c	Chipping, Spalling	8	Yes	No	N/A	N/A	Yes	
863	7100	1	1	H114	Circulation (Hallway)	Hallway adjacent to Right Side of Auditorium	f	N/A	N/A	No	No	N/A	N/A	No	
864	7100	1	1	H03	Circulation (Hallway)	Hallway outside Boy's Cafeteria	1	Cracking, Chipping	9	No	No	N/A	N/A	No	
865	7100	1	1	H03	Circulation (Hallway)	Hallway outside Boy's Cafeteria	2	Chipping on doors	1	No	No	N/A	N/A	No	
866	7100	1	1	H03	Circulation (Hallway)	Hallway outside Boy's Cafeteria	3	Cracking, Chipping on metal pipes, Hole	23	No	No	N/A	N/A	Yes	
867	7100	1	1	H06A	Circulation (Hallway)	Hallway outside Classroom 102	2	Cracking, Chipping, Flaking	34	No	No	N/A	N/A	No	
868	7100	1	1	H06A	Circulation (Hallway)	Hallway outside Classroom 102	4	Cracking, Chipping	8	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
869	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	1	Cracking	22	No	No	N/A	N/A	No	
870	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	2	Cracking	2	No	No	N/A	N/A	No	
871	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	3	Cracking, Spalling	41	Yes	No	N/A	N/A	Yes	
872	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	4	Cracking, Chipping on doors and doorframe, Spalling	8	Yes	No	N/A	N/A	Yes	
873	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	c	N/A	N/A	No	No	N/A	N/A	No	
874	7100	1	1	H07	Circulation (Hallway)	Hallway outside Classroom 105 and Health Center	f	Chipping	5	No	No	N/A	N/A	No	
875	7100	1	1	H06	Circulation (Hallway)	Hallway outside Classrooms 103 and 104	1	Cracking, Chipping	38	No	No	N/A	N/A	No	
876	7100	1	1	H06	Circulation (Hallway)	Hallway outside Classrooms 103 and 104	2	Chipping on wall and door, Efflorescence	8	Yes	No	N/A	N/A	Yes	
877	7100	1	1	H06	Circulation (Hallway)	Hallway outside Classrooms 103 and 104	3	Cracking, Chipping on wall and electrical panel, Staples	28	No	No	N/A	N/A	Yes	
878	7100	1	1	H06	Circulation (Hallway)	Hallway outside Classrooms 103 and 104	4	Cracking	5	No	No	N/A	N/A	No	
879	7100	1	1	H17	Circulation (Hallway)	Hallway outside Classrooms 108-110	2	Cracking, Hole	6	No	No	N/A	N/A	Yes	
880	7100	1	1	H17	Circulation (Hallway)	Hallway outside Classrooms 108-110	4	Cracking, Chipping	10	No	No	N/A	N/A	No	
881	7100	1	1	H04	Circulation (Hallway)	Hallway outside Girl's Cafeteria	1	Cracking, Chipping, Holes, Flaking	10	No	No	N/A	N/A	Yes	
882	7100	1	1	H04	Circulation (Hallway)	Hallway outside Girl's Cafeteria	2	Chipping	2	No	No	N/A	N/A	No	
883	7100	1	1	H04	Circulation (Hallway)	Hallway outside Girl's Cafeteria	3	Cracking, Chipping on wall and metal jacket	29	No	No	N/A	N/A	No	
884	7100	1	1	H04	Circulation (Hallway)	Hallway outside Girl's Cafeteria	4	Chipping on wall, door, and doorframe, Efflorescence	17	Yes	No	N/A	N/A	Yes	
885	7100	1	1	H03A	Circulation (Hallway)	Hallway to Entrance adjacent to Boy's Cafeteria	2	Cracking	3	No	No	N/A	N/A	No	
886	7100	1	1	H03A	Circulation (Hallway)	Hallway to Entrance adjacent to Boy's Cafeteria	3	Chipping on doorframe, Flaking	5	No	No	N/A	N/A	No	
887	7100	1	1	H03A	Circulation (Hallway)	Hallway to Entrance adjacent to Boy's Cafeteria	4	Cracking	4	No	No	N/A	N/A	No	
888	7100	1	1	H03A	Circulation (Hallway)	Hallway to Entrance adjacent to Boy's Cafeteria	f	N/A	N/A	No	No	N/A	N/A	No	
889	7100	1	1	H04A	Circulation (Hallway)	Hallway to Entrance adjacent to Girl's Cafeteria	2	Cracking	5	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
890	7100	1	1	H04A	Circulation (Hallway)	Hallway to Entrance adjacent to Girl's Cafeteria	3	Cracking, Chipping on doors and doorframe, Efflorescence	31	Yes	No	N/A	N/A	Yes	
891	7100	1	1	H04A	Circulation (Hallway)	Hallway to Entrance adjacent to Girl's Cafeteria	4	Chipping, Efflorescence	21	Yes	No	N/A	N/A	Yes	
892	7100	1	1	117	Kitchen	Kitchen	2	Chipping on wall, doors and doorframe	36	No	No	N/A	N/A	No	
893	7100	1	1	117	Kitchen	Kitchen	3	Cracking	7	No	No	N/A	N/A	No	
894	7100	1	1	117	Kitchen	Kitchen	4	Chipping on metal jacket	1	No	No	N/A	N/A	No	
895	7100	1	1	117	Kitchen	Kitchen	c	Flaking on ceiling and metal duct	57	No	No	N/A	N/A	No	
896	7100	1	1	117	Kitchen	Kitchen	f	Chipping	180	No	No	N/A	N/A	No	
897	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
898	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
899	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
900	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
901	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
902	7100	1	1	117F	Kitchen and Dry Storage Area	Kitchen Dry Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
903	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
904	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
905	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
906	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
907	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
908	7100	1	1	117A	Administrative Office	Kitchen Office		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
909	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
910	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
911	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
912	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
913	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
914	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
915	7100	1	1	117E	Kitchen	Large Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
916	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	1	Chipping on wall, door, and doorframe, Flaking	34	No	No	N/A	N/A	No	
917	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	2	Chipping on wall, door, and doorframe, Flaking	39	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
918	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	3	Chipping, Spalling	2	No	No	N/A	N/A	No	
919	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	4	Chipping, Hole, Flaking on wall and metal pipes	24	No	No	N/A	N/A	No	
920	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	c	Flaking	10	No	No	N/A	N/A	No	
921	7100	1	1	113C	Space (Auditorium)	Lighting Control Room to Left of Stage	f	N/A	N/A	No	Debris	1	N/A	No	
922	7100	1	1	S15	Circulation (Hallway)	Main Entrance Lobby	1	Chipping on doors and doorframes	110	No	No	N/A	N/A	No	
923	7100	1	1	S15	Circulation (Hallway)	Main Entrance Lobby	2	Chipping on radiator	2	No	No	N/A	N/A	No	
924	7100	1	1	S15	Circulation (Hallway)	Main Entrance Lobby	4	Chipping on radiator	6	No	No	N/A	N/A	No	
925	7100	1	1	S15	Circulation (Hallway)	Main Entrance Lobby	f	N/A	N/A	No	No	N/A	N/A	No	
926	7100	1	1	H05	Circulation (Hallway)	Marble Hallway	1	Cracking, Chipping	7	No	No	N/A	N/A	No	
927	7100	1	1	H05	Circulation (Hallway)	Marble Hallway	2	Cracking, Chipping	3	No	No	N/A	N/A	No	
928	7100	1	1	H05	Circulation (Hallway)	Marble Hallway	3	Flaking	1	No	No	N/A	N/A	No	
929	7100	1	1	H05	Circulation (Hallway)	Marble Hallway	4	Cracking	6	No	No	N/A	N/A	No	
930	7100	1	1	H05	Circulation (Hallway)	Marble Hallway	c	Chipping, Flaking	5	No	No	N/A	N/A	No	
931	7100	1	1	S17	Stairs	Red Stairwell	1	Cracking	5	No	No	N/A	N/A	No	
932	7100	1	1	S17	Stairs	Red Stairwell	3	Cracking	2	No	No	N/A	N/A	No	
933	7100	1	1	S17	Stairs	Red Stairwell	4	Chipping on doors and doorframe	34	No	No	N/A	N/A	No	
934	7100	1	1	S17	Stairs	Red Stairwell	c	Cracking	1	No	No	N/A	N/A	No	
935	7100	1	1	S17	Stairs	Red Stairwell	f	Chipping	5	No	No	N/A	N/A	No	
936	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
937	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
938	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
939	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
940	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
941	7100	1	1	S17B	Storage	Red Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
942	7100	1	1	103A	Student Restrooms - Male/Female (Classroom)	Restroom 103A between Classrooms 103 and 104	1	Cracking	30	No	No	N/A	N/A	No	
943	7100	1	1	103A	Student Restrooms - Male/Female (Classroom)	Restroom 103A between Classrooms 103 and 104	2	Cracking	20	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
944	7100	1	1	103A	Student Restrooms - Male/Female (Classroom)	Restroom 103A between Classrooms 103 and 104	3	Cracking, Spalling	25	Yes	No	N/A	N/A	Yes	
945	7100	1	1	103A	Student Restrooms - Male/Female (Classroom)	Restroom 103A between Classrooms 103 and 104	4	Cracking, Spalling	23	Yes	No	N/A	N/A	Yes	
946	7100	1	1	103A	Student Restrooms - Male/Female (Classroom)	Restroom 103A between Classrooms 103 and 104	f	Chipping	7	No	No	N/A	N/A	No	
947	7100	1	1	20	Administrative Office	Room adjacent to Entrance by Office 101A	1	Chipping on wall and metal jacket, Flaking	5	No	No	N/A	N/A	No	
948	7100	1	1	20	Administrative Office	Room adjacent to Entrance by Office 101A	2	Flaking on wall and windowframes	48	No	No	N/A	N/A	No	
949	7100	1	1	20	Administrative Office	Room adjacent to Entrance by Office 101A	3	Chipping, Flaking	45	No	No	N/A	N/A	No	
950	7100	1	1	20	Administrative Office	Room adjacent to Entrance by Office 101A	c	Flaking	260	No	No	N/A	N/A	No	
951	7100	1	1	20	Administrative Office	Room adjacent to Entrance by Office 101A	f	N/A	N/A	No	Paint chips	30	N/A	No	
952	7100	1	1	113B	Space (Auditorium)	Room to Right of Stage	1	Chipping on wall, door, and doorframe	30	No	No	N/A	N/A	No	
953	7100	1	1	113B	Space (Auditorium)	Room to Right of Stage	3	Chipping	5	No	No	N/A	N/A	No	
954	7100	1	1	113B	Space (Auditorium)	Room to Right of Stage	4	Chipping on door and doorframe	34	No	No	N/A	N/A	No	
955	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
956	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
957	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
958	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
959	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
960	7100	1	1	113F	Storage	Room to Right of Stage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
961	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
962	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
963	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
964	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
965	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
966	7100	1	1	117D	Kitchen	Small Refrigerator Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
967	7100	1	1	S102	Stairs	Stairs to East Gym	2	Chipping on metal pipes	10	No	No	N/A	N/A	No	
968	7100	1	1	S102	Stairs	Stairs to East Gym	4	Chipping on metal pipes	10	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
969	7100	1	1	S102	Stairs	Stairs to East Gym	c	Flaking, Efflorescence	24	Yes	No	N/A	N/A	Yes	
970	7100	1	1	S102	Stairs	Stairs to East Gym	f	Chipping	25	No	No	N/A	N/A	No	
971	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
972	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
973	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
974	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
975	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
976	7100	1	1	S102A	Storage	Stairs to East Gym Left Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
977	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
978	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
979	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
980	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
981	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
982	7100	1	1	S102C	Storage	Stairs to East Gym Right Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
983	7100	1	1	S18	Stairs	Stairs to West Gym	1	N/A	N/A	No	No	N/A	N/A	No	
984	7100	1	1	S18	Stairs	Stairs to West Gym	2	Chipping	5	No	No	N/A	N/A	No	
985	7100	1	1	S18	Stairs	Stairs to West Gym	c	Flaking	20	No	No	N/A	N/A	No	
986	7100	1	1	S18	Stairs	Stairs to West Gym	f	Chipping	50	No	No	N/A	N/A	No	
987	7100	1	1	S18A	Storage	Stairs to West Gym Left Storage Closet	1	Chipping	1	No	No	N/A	N/A	No	
988	7100	1	1	S18A	Storage	Stairs to West Gym Left Storage Closet	2	Chipping	1	No	No	N/A	N/A	No	
989	7100	1	1	S18A	Storage	Stairs to West Gym Left Storage Closet	c	Flaking on metal pipe	2	No	No	N/A	N/A	No	
990	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
991	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
992	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
993	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
994	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
995	7100	1	1	S18C	Storage	Stairs to West Gym Right Storage Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
996	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
997	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
998	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
999	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1000	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1001	7100	1	1	S19	Stairs	Stairwell to East Gym Locker Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1002	7100	1	1	S20	Stairs	Stairwell to West Gym Locker Room	2	Chipping	3	No	No	N/A	N/A	No	
1003	7100	1	1	S20	Stairs	Stairwell to West Gym Locker Room	3	Chipping	1	No	No	N/A	N/A	No	
1004	7100	1	1	S20	Stairs	Stairwell to West Gym Locker Room	4	Chipping	5	No	No	N/A	N/A	No	
1005	7100	1	1	S20	Stairs	Stairwell to West Gym Locker Room	c	Flaking	17	No	No	N/A	N/A	No	
1006	7100	1	1	S20	Stairs	Stairwell to West Gym Locker Room	f	N/A	N/A	No	Paint Chips	5	N/A	No	
1007	7100	1	1	109	Storage	Storage Room 109	1	Cracking, Chipping on wall, door, doorframe, and wood cove base	32	No	No	N/A	N/A	No	
1008	7100	1	1	109	Storage	Storage Room 109	2	Cracking, Chipping on wall and wood cove base	11	No	No	N/A	N/A	No	
1009	7100	1	1	109	Storage	Storage Room 109	3	Cracking, Holes, Flaking	36	No	No	N/A	N/A	Yes	
1010	7100	1	1	109	Storage	Storage Room 109	4	Cracking, Chipping, Flaking	36	No	No	N/A	N/A	No	
1011	7100	1	1	109	Storage	Storage Room 109	c	Holes, Flaking above windows	16	No	No	N/A	N/A	Yes	
1012	7100	1	1	109	Storage	Storage Room 109	f	N/A	N/A	No	Debris and Paint Chips along wall 3	16	N/A	No	
1013	7100	1	1	109A	Storage	Storage Room 109A	1	Cracking, Chipping on wall, door, and doorframe, Holes, Flaking	78	No	No	N/A	Stored Materials	Yes	Limited Inspection due to stored materials
1014	7100	1	1	109A	Storage	Storage Room 109A	2	Chipping, Flaking, Efflorescence	34	Yes	No	N/A	Stored Materials	Yes	Limited Inspection due to stored materials
1015	7100	1	1	109A	Storage	Storage Room 109A	3	Flaking on wall, windowframes, and metal pipes, Efflorescence	56	Yes	Debris on windowsills	3	Stored Materials	Yes	Limited Inspection due to stored materials
1016	7100	1	1	109A	Storage	Storage Room 109A	4	Cracking, Chipping, Flaking	18	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1017	7100	1	1	109A	Storage	Storage Room 109A	c	Flaking, Significant Moisture Damage above missing ceiling tile	38	Yes	No	N/A	Stored Materials	Yes	Limited Inspection due to stored materials
1018	7100	1	1	109A	Storage	Storage Room 109A	f	N/A	N/A	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1019	7100	1	1	110A	Storage	Storage Room 110A	1	Chipping	2	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1020	7100	1	1	110A	Storage	Storage Room 110A	2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1021	7100	1	1	110A	Storage	Storage Room 110A	3	Chipping	10	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1022	7100	1	1	110A	Storage	Storage Room 110A	4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1023	7100	1	1	110A	Storage	Storage Room 110A	c	N/A	N/A	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1024	7100	1	1	110A	Storage	Storage Room 110A	f	N/A	N/A	No	No	N/A	Stored Materials	No	Limited Inspection due to stored materials
1025	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1026	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1027	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1028	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1029	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1030	7100	1	1	H06B	Storage	Storage Room adjacent to Green Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1031	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1032	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1033	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1034	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1035	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1036	7100	1	1	H17A	Storage	Storage Room adjacent to Red Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1037	7100	1	1	118A	Ticket Booth	Ticket Booth adjacent to Boy's Cafeteria	1	Chipping on wall, door, and doorframe	19	No	No	N/A	N/A	No	
1038	7100	1	1	118A	Ticket Booth	Ticket Booth adjacent to Boy's Cafeteria	2	Chipping, Flaking	6	No	No	N/A	N/A	No	
1039	7100	1	1	118A	Ticket Booth	Ticket Booth adjacent to Boy's Cafeteria	3	Chipping	6	No	No	N/A	N/A	No	
1040	7100	1	1	118A	Ticket Booth	Ticket Booth adjacent to Boy's Cafeteria	4	Chipping, Flaking	10	No	No	N/A	N/A	No	
1041	7100	1	1	118A	Ticket Booth	Ticket Booth adjacent to Boy's Cafeteria	c	Flaking	6	No	No	N/A	N/A	No	
1042	7100	1	1	117B	Circulation (Hallway)	Vestibule between Kitchen and Exterior Entrance	1	Chipping on doors, doorframe and metal pipe	29	No	No	N/A	N/A	No	
1043	7100	1	1	117B	Circulation (Hallway)	Vestibule between Kitchen and Exterior Entrance	2	Chipping	1	No	No	N/A	N/A	No	
1044	7100	1	1	117B	Circulation (Hallway)	Vestibule between Kitchen and Exterior Entrance	3	Chipping on doors and doorframe	20	No	No	N/A	N/A	No	
1045	7100	1	1	117B	Circulation (Hallway)	Vestibule between Kitchen and Exterior Entrance	c	Cracking	3	No	No	N/A	N/A	No	
1046	7100	1	1	117B	Circulation (Hallway)	Vestibule between Kitchen and Exterior Entrance	f	Chipping	6	No	No	N/A	N/A	No	
1047	7100	1	1	102A	Weight Room	Weight Room 102A	1	Chipping on wall and in air shaft	5	No	No	N/A	N/A	No	
1048	7100	1	1	102A	Weight Room	Weight Room 102A	3	Chipping, Flaking on wall, windowframes, and metal pipe	42	No	No	N/A	N/A	No	
1049	7100	1	1	102A	Weight Room	Weight Room 102A	c	Flaking above windows	9	No	No	N/A	N/A	No	
1050	7100	1	1	102A	Weight Room	Weight Room 102A	f	Chipping	29	No	No	N/A	N/A	No	

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1051	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1052	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1053	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1054	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1055	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1056	7100	1	1	102L	Storage	Weight Room 102A Closet		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1057	7100	1	1	101	Gymnasium - Intermediate Middle	West Gym	1	Chipping on metal pipes	5	No	No	N/A	N/A	No	
1058	7100	1	1	101	Gymnasium - Intermediate Middle	West Gym	3	Chipping on metal pipes	3	No	No	N/A	N/A	No	
1059	7100	1	1	101	Gymnasium - Intermediate Middle	West Gym	c	Chipping on metal pipes, Flaking	72	No	No	N/A	N/A	No	
1060	7100	1	1	101K	Lockers - Female	West Gym Locker Room	3	Chipping on wall and metal pipe	6	No	No	N/A	N/A	No	
1061	7100	1	1	101K	Lockers - Female	West Gym Locker Room	c	Flaking	31	No	No	N/A	N/A	No	
1062	7100	1	1	101K	Lockers - Female	West Gym Locker Room	f	N/A	N/A	No	Paint Chips	20	N/A	No	
1063	7100	1	1	101L	Student Restrooms - Female (4-12)	West Gym Locker Room Rest Room	4	Cracking, Hole	5	No	No	N/A	N/A	No	
1064	7100	1	1	101L	Student Restrooms - Female (4-12)	West Gym Locker Room Rest Room	c	Flaking	18	No	No	N/A	N/A	No	
1065	7100	1	1	101L	Student Restrooms - Female (4-12)	West Gym Locker Room Rest Room	f	N/A	N/A	No	Debris and Paint Chips	10	N/A	No	
1066	7100	1	1	101N	Showers - Female	West Gym Locker Room Showers	4	Flaking on metal pipe	7	No	No	N/A	N/A	No	
1067	7100	1	1	101N	Showers - Female	West Gym Locker Room Showers	c	Flaking	27	No	No	N/A	N/A	No	
1068	7100	1	1	101N	Showers - Female	West Gym Locker Room Showers	f	N/A	N/A	No	Paint Chips	20	N/A	No	
1069	7100	1	1	101G	Administrative Office	West Gym Office	2	Chipping	3	No	No	N/A	N/A	No	
1070	7100	1	1	101G	Administrative Office	West Gym Office	3	Chipping on doorframe	6	No	No	N/A	N/A	No	
1071	7100	1	1	101G	Administrative Office	West Gym Office	c	Flaking	5	No	No	N/A	N/A	No	
1072	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1073	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1074	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1075	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1076	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1077	7100	1	1	101J	Storage	West Gym Storage Room below Stairwell		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1078	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1079	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1080	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1081	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1082	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1083	7100	1	1	101I	Storage	West Gym Storage Room Closest to Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1084	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1085	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1086	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1087	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1088	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1089	7100	1	1	101H	Storage	West Gym Storage Room Farthest from Entrance		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1090	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1091	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1092	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected

Cooke -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments	
1093	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1094	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1095	7100	1	1	101M	Storage	West Gym Storage Room Farthest from Entrance Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1096	7100	1	1	S14	Stairs	Yellow Stairwell	1	Cracking	12	No	No	N/A	N/A	No		
1097	7100	1	1	S14	Stairs	Yellow Stairwell	2	Cracking, Chipping on doors and doorframe	22	No	No	N/A	N/A	No		
1098	7100	1	1	S14	Stairs	Yellow Stairwell	c	Cracking	2	No	No	N/A	N/A	No		
1099	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1100	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1101	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1102	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1103	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
1104	7100	1	1	S14A	Storage	Yellow Stairwell Storage Room		No Access	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected