

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	2290	1	4	401		Closet 400	Floor	Debris	0	N	Y - @ Perimeter	25	N	N	
2	2290	1	4	401		Closet 400	W1	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Inspection Required
3	2290	1	4	401		Closet 400	W2	Flaking	30	N	Y - On Shelves	15	Y - 40 SF Contents	N	
4	2290	1	4	401		Closet 400	W3	Flaking	48	Y	Y - On Shelves	24	Y - 30 SF Contents	N	Additional Efflorescence
5	2290	1	4	401		Closet 400	W4	Partially Inaccessible	0	N	N	0	Y - 60 SF Contents	N	Inspection Required
6	2290	1	4	410		Dance Locker Restroom	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
7	2290	1	4	410		Dance Locker Restroom	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
8	2290	1	4	410		Dance Locker Restroom	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
9	2290	1	4	410		Dance Locker Restroom	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
10	2290	1	4	410		Dance Locker Restroom	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
11	2290	1	4	410		Dance Locker Restroom	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
12	2290	1	4	409		Dance Locker Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
13	2290	1	4	409		Dance Locker Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
14	2290	1	4	409		Dance Locker Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
15	2290	1	4	409		Dance Locker Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
16	2290	1	4	409		Dance Locker Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
17	2290	1	4	409		Dance Locker Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
18	2290	1	4	408		Dance Office	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
19	2290	1	4	408		Dance Office	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
20	2290	1	4	408		Dance Office	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
21	2290	1	4	408		Dance Office	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
22	2290	1	4	408		Dance Office	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
23	2290	1	4	408		Dance Office	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
24	2290	1	4	407		Dance Office Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
25	2290	1	4	407		Dance Office Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
26	2290	1	4	407		Dance Office Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
27	2290	1	4	407		Dance Office Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
28	2290	1	4	407		Dance Office Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
29	2290	1	4	407		Dance Office Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
30	2290	1	4	405		Dance Studio	W1	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
31	2290	1	4	405A		Dance Studio Closet	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
32	2290	1	4	405A		Dance Studio Closet	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
33	2290	1	4	405A		Dance Studio Closet	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock; Dance Teacher "Out of Town"
34	2290	1	4	405A		Dance Studio Closet	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
35	2290	1	4	405A		Dance Studio Closet	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
36	2290	1	4	405A		Dance Studio Closet	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
37	2290	1	4	S42		Fire Tower adjacent to Closet 400	Ceiling	Flaking	34	N	N	0	N	N	
38	2290	1	4	H40		Hallway from Closet 400 to Dance Studio	W2	Cracking	4	N	N	0	N	N	
39	2290	1	4	H40		Hallway from Closet 400 to Dance Studio	W3	Chipping	2	N	N	0	N	N	
40	2290	1	4	H40		Hallway outside Music Storage	W1	Cracking	1	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
41	2290	1	4	S41		Stairwell adjacent to Closet 400	Ceiling	Cracking	4	N	N	0	N	N	
42	2290	1	4	S41		Stairwell adjacent to Closet 400	Floor	Chipping	8	N	N	0	N	N	
43	2290	1	4	S40		Stairwell adjacent to Dance Locker Room	Ceiling	Cracking	6	N	N	0	N	N	
44	2290	1	4	S40		Stairwell adjacent to Dance Locker Room	Floor	Chipping	12	N	N	0	N	N	
45	2290	1	3	323		Chemical Storage Closet in Closet 318	Floor	Debris	0	N	Y - Near Radiator	8	N	N	
46	2290	1	3	323		Chemical Storage Closet in Closet 318	W3	Flaking	8	N	N	0	N	N	
47	2290	1	3	300		Classroom 300	Ceiling	Flaking	20	Y	N	0	N	Y - 12 SF	Additional Efflorescence
48	2290	1	3	300		Classroom 300	W1	Chipping	16	N	N	0	Y - 40 SF Posters	N	
49	2290	1	3	300		Classroom 300	W2	Gouges	4	N	N	0	N	Y - 1 SF	Additional Holes
50	2290	1	3	300		Classroom 300	W3	Flaking	24	Y	N	0	Y - 60 SF Tables	Y - 12 SF	
51	2290	1	3	300		Classroom 300	W4	Partially Inaccessible	0	N	N	0	Y - 48 SF Tables	N	Inspection Required
52	2290	1	3	302		Classroom 302	Ceiling	Flaking	30	N	N	0	N	N	Additional Cracking
53	2290	1	3	302		Classroom 302	W1	Flaking	30	N	N	0	N	N	Additional Chipping
54	2290	1	3	302		Classroom 302	W2	Flaking	28	N	N	0	N	N	Additional Chipping
55	2290	1	3	302		Classroom 302	W3	Flaking	44	N	N	0	N	N	Additional Chipping
56	2290	1	3	302		Classroom 302	W4	Flaking	12	N	N	0	N	N	Additional Chipping
57	2290	1	3	303		Classroom 303	Ceiling	Flaking	240	Y	N	0	N	Y - 30 SF	Additional Efflorescence
58	2290	1	3	303		Classroom 303	W1	Cracking	28	N	N	0	N	N	Additional Chipping
59	2290	1	3	303		Classroom 303	W2	Chipping	56	N	N	0	N	N	
60	2290	1	3	303		Classroom 303	W3	Flaking	210	Y	N	0	N	Y - 20 SF	Additional Efflorescence; Damage @ Wall & Window Frames
61	2290	1	3	303		Classroom 303	W4	Flaking	60	N	N	0	N	N	
62	2290	1	3	304		Classroom 304	Ceiling	Cracking	4	N	N	0	N	N	Additional Chipping
63	2290	1	3	304		Classroom 304	W1	Chipping	20	N	N	0	N	N	
64	2290	1	3	304		Classroom 304	W2	Cracking	40	N	N	0	N	N	Additional Chipping
65	2290	1	3	304		Classroom 304	W3	Chipping	12	N	N	0	N	N	Chipping @ Window Sills
66	2290	1	3	304		Classroom 304	W4	Flaking	64	N	N	0	N	N	Additional Cracking
67	2290	1	3	305		Classroom 305	Ceiling	Flaking	16	Y	N	0	N	Y - 3 SF	Additional Efflorescence
68	2290	1	3	305		Classroom 305	W1	Chipping	10	N	N	0	N	N	
69	2290	1	3	305		Classroom 305	W2	Chipping	18	N	N	0	N	N	
70	2290	1	3	305		Classroom 305	W3	Flaking	48	Y	N	0	N	Y - 12 SF	Additional Efflorescence
71	2290	1	3	305		Classroom 305	W4	Flaking	80	Y	N	0	N	Y - 12 SF	Additional Efflorescence
72	2290	1	3	307		Classroom 307	Ceiling	Flaking	6	N	N	0	N	N	Additional Cracking, Chipping
73	2290	1	3	307		Classroom 307	Floor	Chipping	45	N	N	0	N	N	Chipping @ Perimeter
74	2290	1	3	307		Classroom 307	W1	Cracking	4	N	N	0	N	N	Additional Chipping
75	2290	1	3	307		Classroom 307	W2	Cracking	6	N	N	0	N	N	Additional Chipping
76	2290	1	3	307		Classroom 307	W3	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
77	2290	1	3	307		Classroom 307	W4	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence
78	2290	1	3	311		Classroom 312	Floor	Chipping	80	N	N	0	N	N	Chipping @ Perimeter
79	2290	1	3	311		Classroom 312	W1	Chipping	4	N	N	0	N	N	
80	2290	1	3	311		Classroom 312	W2	Chipping	2	N	N	0	N	N	
81	2290	1	3	311		Classroom 312	W3	Flaking	8	N	N	0	N	N	Additional Chipping
82	2290	1	3	311		Classroom 312	W4	Cracking	5	N	N	0	N	Y - 1 SF	Additional Chipping, Holes
83	2290	1	3	320		Classroom 315	Ceiling	Flaking	12	Y	N	0	N	Y - 3 SF	Additional Efflorescence
84	2290	1	3	320		Classroom 315	Floor	Chipping	8	N	N	0	N	N	Chipping @ Baseboards

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
85	2290	1	3	320		Classroom 315	W1	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping
86	2290	1	3	320		Classroom 315	W2	Cracking	20	N	N	0	N	N	Additional Cracking, Chipping
87	2290	1	3	320		Classroom 315	W3	Flaking	80	Y	N	0	N	Y - 20 SF	Additional Efflorescence, Cracking, Chipping
88	2290	1	3	320		Classroom 315	W4	Chipping	18	N	N	0	N	N	
89	2290	1	3	321		Classroom 316	Ceiling	Flaking	12	N	N	0	N	N	Additional Chipping
90	2290	1	3	321		Classroom 316	W1	Flaking	40	N	N	0	Y - 16 SF Posters	N	Additional Chipping
91	2290	1	3	321		Classroom 316	W2	Cracking	10	N	N	0	N	N	Additional Cracking
92	2290	1	3	321		Classroom 316	W3	Flaking	64	N	N	0	N	N	Additional Cracking; Damage @ Wall & Window Lintel
93	2290	1	3	321		Classroom 316	W4	Flaking	72	N	N	0	Y - 18 SF Posters	N	Additional Cracking, Chipping
94	2290	1	3	322		Classroom 317	Ceiling	Flaking	90	N	N	0	N	N	
95	2290	1	3	322		Classroom 317	W1	Flaking	8	N	N	0	Y - 12 SF Posters	N	Additional Cracking, Chipping
96	2290	1	3	322		Classroom 317	W2	Chipping	1	N	N	0	Y - 30 SF Cabinets	N	Additional Holes
97	2290	1	3	322		Classroom 317	W3	Flaking	80	N	N	0	N	N	Additional Cracking; Damage @ Wall & Window Lintel
98	2290	1	3	324		Classroom 318	Ceiling	Flaking	6	Y	N	0	N	Y - 6 SF	Additional Efflorescence
99	2290	1	3	324		Classroom 318	Floor	Debris	0	N	Y - Beneath Windows	3	N	N	
100	2290	1	3	324		Classroom 318	W1	Chipping	8	N	N	0	Y - 38 SF Posters	N	
101	2290	1	3	324		Classroom 318	W2	Chipping	4	N	N	0	N	N	
102	2290	1	3	324		Classroom 318	W3	Flaking	3	N	Y - Window Sill 1	2	N	Y - 3 SF	Additional Efflorescence, Chipping
103	2290	1	3	324		Classroom 318	W4	Chipping	16	N	N	0	N	N	
104	2290	1	3	325		Classroom 319	Ceiling	Flaking	160	Y	N	0	N	Y - 160 SF	Additional Efflorescence
105	2290	1	3	325		Classroom 319	Floor	Debris	0	N	Y - Beneath Windows	20	N	N	
106	2290	1	3	325		Classroom 319	W1	Flaking	18	N	N	0	Y - 24 SF Posters	N	Additional Cracking, Chipping
107	2290	1	3	325		Classroom 319	W2	Chipping	20	N	N	0	Y - 18 SF Posters	N	
108	2290	1	3	325		Classroom 319	W3	Flaking	240	Y	N	0	N	Y - 240 SF	Additional Efflorescence
109	2290	1	3	325		Classroom 319	W4	Flaking	40	N	N	0	N	N	Additional Cracking
110	2290	1	3	327A		Classroom 321	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
111	2290	1	3	327A		Classroom 321	W1	Flaking	16	N	N	0	N	N	Additional Cracking
112	2290	1	3	327A		Classroom 321	W2	Chipping	10	N	N	0	N	N	
113	2290	1	3	327A		Classroom 321	W3	Flaking	18	N	N	0	Y - 18 SF Desks	N	Additional Cracking, Chipping
114	2290	1	3	327A		Classroom 321	W4	Flaking	20	N	N	0	Y - 20 SF Posters	N	Additional Chipping
115	2290	1	3	328		Classroom 323	Ceiling	Flaking	18	N	N	0	N	N	Additional Cracking
116	2290	1	3	328		Classroom 323	W1	Cracking	12	N	N	0	N	N	
117	2290	1	3	328		Classroom 323	W2	Chipping	6	N	N	0	N	N	
118	2290	1	3	328		Classroom 323	W3	Flaking	24	N	N	0	N	N	Additional Cracking, Chipping; Damage on Wall & Radiator
119	2290	1	3	328		Classroom 323	W4	Chipping	6	N	N	0	N	N	
120	2290	1	3	329		Classroom 324	Ceiling	Flaking	6	N	N	0	N	N	
121	2290	1	3	329		Classroom 324	W1	Flaking	16	N	N	0	N	N	Additional Chipping
122	2290	1	3	329		Classroom 324	W2	Flaking	32	N	N	0	N	N	Additional Chipping
123	2290	1	3	329		Classroom 324	W3	Flaking	40	N	N	0	N	N	Additional Chipping
124	2290	1	3	329		Classroom 324	W4	Chipping	10	N	N	0	N	N	Additional Chipping

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
125	2290	1	3	330		Classroom 325	W1	Flaking	32	N	N	0	N	Y - 1 SF	Additional Chipping
126	2290	1	3	330		Classroom 325	W2	Flaking	16	N	N	0	N	N	Additional Chipping
127	2290	1	3	330		Classroom 325	W3	Flaking	24	N	N	0	N	N	Additional Chipping
128	2290	1	3	330		Classroom 325	W4	Flaking	10	N	N	0	N	N	Additional Chipping
129	2290	1	3	309		Closet 309	W2	Cracking	12	N	N	0	Y - 14 SF Contents	N	
130	2290	1	3	309		Closet 309	W3	Cracking	25	N	N	0	Y - 28 SF Contents	N	
131	2290	1	3	309		Closet 309	W4	Cracking	14	N	N	0	Y - 22 SF Contents	N	
132	2290	1	3	320A		Closet 314	Ceiling	Flaking	160	Y	N	0	N	Y - 160 SF	Additional Efflorescence
133	2290	1	3	320A		Closet 314	W1	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
134	2290	1	3	320A		Closet 314	W2	Flaking	22	N	N	0	N	N	Additional Cracking, Chipping
135	2290	1	3	320A		Closet 314	W3	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
136	2290	1	3	320A		Closet 314	W4	Flaking	64	N	N	0	N	N	Additional Cracking, Chipping
137	2290	1	3	323		Closet 318	W1	Chipping	1	N	N	0	Y - 28 SF File Cabinets	N	
138	2290	1	3	323		Closet 318	W2	Partially Inaccessible	0	N	N	0	Y - 20 SF Contents	N	Inspection Required
139	2290	1	3	323		Closet 318	W3	Partially Inaccessible	0	N	N	0	Y - 18 SF Contents	N	Inspection Required
140	2290	1	3	323		Closet 318	W4	Partially Inaccessible	0	N	N	0	Y - 28 SF Posters, Contents	N	Inspection Required
141	2290	1	3	S32		Fire Tower adjacent Classroom 300	Ceiling	Flaking	32	N	N	0	N	N	
142	2290	1	3	S34		Fire Tower adjacent Classroom 320	Ceiling	Flaking	40	N	N	0	N	N	
143	2290	1	3	H30		Hallway from Classrooms 300 to 319	Ceiling	Flaking	90	Y	N	0	N	Y - 30 SF	Additional Efflorescence, Cracking
144	2290	1	3	H30		Hallway from Classrooms 300 to 319	W2	Flaking	40	Y	N	0	N	Y - 30 SF	Additional Efflorescence
145	2290	1	3	H30		Hallway from Classrooms 300 to 319	W4	Flaking	30	Y	N	0	N	Y - 20 SF	Additional Efflorescence
146	2290	1	3	H33		Hallway from Classrooms 301 to 304	Ceiling	Flaking	40	N	N	0	N	N	Additional Cracking, Chipping
147	2290	1	3	H33		Hallway from Classrooms 301 to 304	W1	Cracking	4	N	N	0	N	N	
148	2290	1	3	H33		Hallway from Classrooms 301 to 304	W3	Flaking	20	Y	N	0	N	Y - 20 SF	Additional Efflorescence
149	2290	1	3	H31		Hallway from Classrooms 305 to 320	Ceiling	Flaking	48	N	N	0	N	N	Additional Cracking
150	2290	1	3	H31		Hallway from Classrooms 305 to 320	W3	Cracking	30	N	N	0	N	N	Additional Chipping
151	2290	1	3	H32		Hallway from Classrooms 316 to 318	Ceiling	Flaking	280	N	N	0	N	N	
152	2290	1	3	H32		Hallway from Classrooms 316 to 318	W4	Efflorescence	18	Y	N	0	N	Y - 12 SF	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
153	2290	1	3	310		HRT Room	W1	Chipping	2	N	N	0	N	N	Additional Gouges
154	2290	1	3	310		HRT Room	W3	Chipping	6	N	N	0	N	N	
155	2290	1	3	315		Men's Restroom	W1	Flaking	60	N	N	0	N	N	Additional Chipping
156	2290	1	3	315		Men's Restroom	W2	Flaking	12	N	N	0	N	N	Additional Chipping
157	2290	1	3	315		Men's Restroom	W3	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
158	2290	1	3	315		Men's Restroom	W4	Flaking	64	N	N	0	N	N	Additional Chipping
159	2290	1	3	307A		Office 306	W3	Cracking	2	N	N	0	Y - 24 SF Desks, Contents	N	
160	2290	1	3	307A		Office 306	W4	Partially Inaccessible	0	N	N	0	Y - 80 SF Cabinets, Posters, Contents	N	Inspection Required
161	2290	1	3	312		Office 312A	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
162	2290	1	3	312		Office 312A	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
163	2290	1	3	312		Office 312A	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
164	2290	1	3	312		Office 312A	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
165	2290	1	3	312		Office 312A	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
166	2290	1	3	312		Office 312A	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
167	2290	1	3	326		Office 320	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Posters	N	Inspection Required
168	2290	1	3	326		Office 320	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks, Posters	N	Inspection Required
169	2290	1	3	326		Office 320	W4	Partially Inaccessible	0	N	N	0	Y - 36 Posters	N	Inspection Required
170	2290	1	3	327		Office 322	W2	Cracking	10	N	N	0	Y - 20 SF Posters	N	
171	2290	1	3	327		Office 322	W3	Cracking	18	N	N	0	Y - 30 SF Posters, Desks	N	
172	2290	1	3	327		Office 322	W4	Chipping	14	N	N	0	Y - 28 SF Posters	N	
173	2290	1	3	S31		Stairwell adjacent Classroom 300	Ceiling	Flaking	14	N	N	0	N	N	
174	2290	1	3	S33		Stairwell adjacent Classroom 305	Ceiling	Flaking	16	N	N	0	N	N	
175	2290	1	3	S30		Stairwell adjacent Classroom 319	Ceiling	Flaking	21	N	N	0	N	N	
176	2290	1	3	S35		Stairwell adjacent Classroom 320	Ceiling	Flaking	26	N	N	0	N	N	
177	2290	1	2	203A		Boy's Restroom	Ceiling	Holes	1	N	N	0	N	N	
178	2290	1	2	203A		Boy's Restroom	W2	Chipping	4	N	N	0	N	N	Chipping on Radiator
179	2290	1	2	200		Classroom 200	Ceiling	Flaking	4	Y	N	0	N	Y - 4 SF	Additional Efflorescence
180	2290	1	2	200		Classroom 200	W1	Partially Inaccessible	0	N	N	0	Y - 28 SF Posters	N	Inspection Required
181	2290	1	2	200		Classroom 200	W4	Holes	1	N	N	0	N	N	
182	2290	1	2	201		Classroom 201	Ceiling	Flaking	7	Y	N	0	N	Y - 2 SF	Additional Efflorescence, Cracking
183	2290	1	2	201		Classroom 201	Floor	Debris	0	N	Y - Beneath Efflorescence	0	N	N	
184	2290	1	2	201		Classroom 201	W1	Cracking	6	N	N	0	N	N	
185	2290	1	2	201		Classroom 201	W2	Partially Inaccessible	0	N	N	0	Y - 28 SF Posters, Contents	N	Inspection Required
186	2290	1	2	201		Classroom 201	W3	Flaking	6	N	N	0	N	N	Flaking @ Window Lintel
187	2290	1	2	201		Classroom 201	W4	Flaking	10	N	N	0	N	N	Additional Cracking, Chipping; Damage Includes Pipe & Wall
188	2290	1	2	202		Classroom 202	Ceiling	Flaking	20	Y	N	0	N	Y - 4 SF	Additional Efflorescence
189	2290	1	2	202		Classroom 202	Floor	Debris	0	N	Y - Various	6	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
190	2290	1	2	202		Classroom 202	W1	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping
191	2290	1	2	202		Classroom 202	W2	Flaking	34	N	Y - On Chair Rail	1	N	N	Additional Cracking, Chipping
192	2290	1	2	202		Classroom 202	W3	Flaking	72	Y	Y - On Window Sill	3	N	Y - 4 SF	Additional Efflorescence, Cracking
193	2290	1	2	202		Classroom 202	W4	Partially Inaccessible	0	N	N	0	Y - 26 SF File Cabinets, Desks	N	Inspection Required
194	2290	1	2	203		Classroom 203-204	W1	Flaking	6	N	N	0	Y - 128 SF Desks, Contents	N	Additional Chipping
195	2290	1	2	203		Classroom 203-204	W2	Partially Inaccessible	0	N	N	0	Y - 52 SF Desks, Contents	N	Inspection Required
196	2290	1	2	203		Classroom 203-204	W3	Partially Inaccessible	0	N	N	0	Y - 128 SF Desks, Computers, Contents	N	Inspection Required
197	2290	1	2	203		Classroom 203-204	W4	Chipping	12	N	N	0	Y - 52 SF Desks, Contents	N	
198	2290	1	2	205		Classroom 205	Ceiling	Cracking	12	N	N	0	N	N	
199	2290	1	2	205		Classroom 205	W1	Partially Inaccessible	0	N	N	0	Y - 36 SF Desks, Contents	N	Inspection Required
200	2290	1	2	205		Classroom 205	W2	Cracking	5	N	N	0	N	N	
201	2290	1	2	205		Classroom 205	W3	Flaking	18	N	N	0	N	N	Additional Chipping
202	2290	1	2	205		Classroom 205	W4	Flaking	36	N	N	0	N	Y - 36 SF	Additional Cracking, Chipping
203	2290	1	2	207		Classroom 207	W2	Partially Inaccessible	0	N	N	0	Y - 16 SF File Cabinets, Desks	N	Inspection Required
204	2290	1	2	207		Classroom 207	W3	Partially Inaccessible	0	N	N	0	Y - 32 SF Cabinets	N	Inspection Required
205	2290	1	2	207		Classroom 207	W4	Flaking	6	N	Y - On Chair Rail	1	N	N	
206	2290	1	2	208		Classroom 208	W1	Cracking	4	N	N	0	N	N	Additional Chipping
207	2290	1	2	208		Classroom 208	W2	Flaking	12	N	N	0	N	N	Additional Cracking, Chipping
208	2290	1	2	208		Classroom 208	W3	Chipping	5	N	N	0	N	N	
209	2290	1	2	208		Classroom 208	W4	Chipping	6	N	N	0	N	N	
210	2290	1	2	209		Classroom 209	Ceiling	Flaking	5	N	N	0	N	N	Additional Cracking, Chipping
211	2290	1	2	209		Classroom 209	W1	Partially Inaccessible	0	N	N	0	Y - 16 SF Contents	N	Inspection Required
212	2290	1	2	209		Classroom 209	W2	Flaking	4	N	N	0	Y - 24 SF Desks, Computers	N	
213	2290	1	2	209		Classroom 209	W3	Flaking	6	N	N	0	N	N	Additional Chipping
214	2290	1	2	210		Classroom 210	W1	Chipping	1	N	N	0	Y - 20 SF Posters	N	
215	2290	1	2	210		Classroom 210	W3	Cracking	1	N	N	0	N	N	Additional Chipping
216	2290	1	2	212		Classroom 212	W1	Flaking	5	N	N	0	N	N	Additional Cracking
217	2290	1	2	212		Classroom 212	W2	Flaking	48	N	N	0	Y - 48 SF Bookcases, Tables	N	Additional Chipping
218	2290	1	2	212		Classroom 212	W3	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
219	2290	1	2	217		Classroom 214	Ceiling	Cracking	2	N	N	0	N	N	
220	2290	1	2	217		Classroom 214	W2	Flaking	3	N	N	0	N	N	Additional Chipping
221	2290	1	2	217		Classroom 214	W3	Flaking	2	N	N	0	N	N	Additional Cracking
222	2290	1	2	218		Classroom 215	Ceiling	Chipping	2	N	N	0	N	N	
223	2290	1	2	218		Classroom 215	W1	Cracking	12	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
224	2290	1	2	219		Classroom 216	Ceiling	Flaking	2	N	N	0	N	Y - 2 SF	Additional Chipping; Suspended Ceiling; Damage @ Window Lintel
225	2290	1	2	219		Classroom 216	W3	Flaking	1	N	N	0	N	N	Flaking @ Window Frame 5
226	2290	1	2	222		Classroom 218	W1	Flaking	2	N	N	0	N	N	Additional Chipping
227	2290	1	2	222		Classroom 218	W4	Flaking	8	N	N	0	N	N	
228	2290	1	2	217A		Closet 213	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
229	2290	1	2	217A		Closet 213	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
230	2290	1	2	217A		Closet 213	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
231	2290	1	2	217A		Closet 213	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
232	2290	1	2	217A		Closet 213	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
233	2290	1	2	217A		Closet 213	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
234	2290	1	2	S22		Fire Tower adjacent Classroom 200	Ceiling	Flaking	36	N	N	0	N	N	
235	2290	1	2	S24		Fire Tower adjacent Classroom 214	Ceiling	Flaking	38	N	N	0	N	N	
236	2290	1	2	H20		Hallway from Classrooms 200 to 218	Ceiling	Flaking	8	N	N	0	N	N	
237	2290	1	2	H20		Hallway from Classrooms 200 to 218	W2	Chipping	4	N	N	0	N	N	Chipping on Door
238	2290	1	2	H20		Hallway from Classrooms 200 to 218	W3	Chipping	1	N	N	0	N	N	
239	2290	1	2	H20		Hallway from Classrooms 200 to 218	W4	Cracking	1	N	N	0	N	N	Additional Chipping; Damage behind Radiators
240	2290	1	2	H23		Hallway from Classrooms 201 to 204/204	Ceiling	Flaking	2	N	N	0	N	N	
241	2290	1	2	H23		Hallway from Classrooms 201 to 204/204	W4	Efflorescence	24	Y	N	0	N	N	Additional Chipping; Damage on/behind Radiator
242	2290	1	2	H21		Hallway from Classrooms 207 to 212	Ceiling	Cracking	6	N	N	0	N	N	
243	2290	1	2	H22		Hallway from Classrooms 218 to 221	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
244	2290	1	2	H22		Hallway from Classrooms 218 to 221	W1	Flaking	16	N	N	0	N	N	Additional Cracking; Chipping; Damage @ Window Lintel, on/behind Radiator
245	2290	1	2	225		IMC 221	W1	Chipping	6	N	N	0	Y - 90 SF Bookcases, Books	N	
246	2290	1	2	225		IMC 221	W2	Chipping	5	N	N	0	Y - 40 SF Bookcases, Books	N	
247	2290	1	2	225		IMC 221	W3	Flaking	24	N	N	0	Y - 74 SF Bookcases, Books	N	Additional Chipping
248	2290	1	2	225		IMC 221	W4	Partially Inaccessible	0	N	N	0	Y - 120 SF Bookcases, Books, Posters	N	Inspection Required
249	2290	1	2	225A		IMC Office	W3	Flaking	6	N	N	0	Y - 14 SF Tables	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
250	2290	1	2	225A		IMC Office	W4	Partially Inaccessible	0	N	N	0	Y - 20 SF Cabinets, Tables, Computers	N	Inspection Required
251	2290	1	2	225B		IMC Storage Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
252	2290	1	2	225B		IMC Storage Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
253	2290	1	2	225B		IMC Storage Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Padlocked
254	2290	1	2	225B		IMC Storage Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
255	2290	1	2	225B		IMC Storage Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
256	2290	1	2	225B		IMC Storage Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
257	2290	1	2	211		Laptop Charging Room	W1	Chipping	2	N	N	0	N	N	
258	2290	1	2	211		Laptop Charging Room	W3	Cracking	4	N	N	0	N	N	
259	2290	1	2	219A		Men's Restroom	Ceiling	Cracking	3	N	N	0	N	N	
260	2290	1	2	219A		Men's Restroom	W2	Chipping	5	N	N	0	N	N	
261	2290	1	2	206		Office 206	Ceiling	Cracking	12	N	N	0	N	N	
262	2290	1	2	206		Office 206	Floor	Debris	0	N	Y - @ Radiator	2	N	N	
263	2290	1	2	206		Office 206	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF File Cabinets, Boxes	N	Inspection Required
264	2290	1	2	206		Office 206	W3	Flaking	8	N	N	0	N	N	Additional Chipping; Damage on/behind Radiator
265	2290	1	2	206		Office 206	W4	Flaking	4	N	N	0	N	N	Additional Chipping
266	2290	1	2	223		Office 219	W3	Chipping	3	N	N	0	N	N	Chipping on Window Sill & Radiator
267	2290	1	2	223		Office 219	W4	Chipping	4	N	N	0	N	N	2 Locations
268	2290	1	2	S21		Stairwell adjacent Classroom 200	Ceiling	Flaking	8	N	N	0	N	N	Additional Cracking
269	2290	1	2	S21		Stairwell adjacent Classroom 200	Floor	Chipping	9	N	N	0	N	N	Chipping on Stairs
270	2290	1	2	S23		Stairwell adjacent Classroom 205	Ceiling	Flaking	13	N	N	0	N	N	Additional Cracking
271	2290	1	2	S23		Stairwell adjacent Classroom 205	Floor	Chipping	10	N	N	0	N	N	Chipping on Stairs
272	2290	1	2	S25		Stairwell adjacent Classroom 214	Ceiling	Flaking	10	N	N	0	N	N	
273	2290	1	2	S25		Stairwell adjacent Classroom 214	Floor	Chipping	12	N	N	0	N	N	Chipping on Stairs
274	2290	1	2	S20		Stairwell adjacent Classroom 218	Ceiling	Flaking	12	N	N	0	N	N	Additional Cracking
275	2290	1	2	S20		Stairwell adjacent Classroom 218	Floor	Chipping	12	N	N	0	N	N	Chipping on Stairs
276	2290	1	1	106		Athletic Office 107	W3	Chipping	4	N	N	0	N	N	
277	2290	1	1	100A		Auditorium Balcony	Ceiling	Flaking	40	N	N	0	N	N	
278	2290	1	1	100A		Auditorium Balcony	W1	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
279	2290	1	1	100A		Auditorium Balcony	W2	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
280	2290	1	1	100A		Auditorium Balcony	W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
281	2290	1	1	111B		Book closet adjacent Nurse's Office	W1	Chipping	4	N	N	0	N	N	
282	2290	1	1	111B		Book closet adjacent Nurse's Office	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Books	N	Inspection Required
283	2290	1	1	111B		Book closet adjacent Nurse's Office	W3	Partially Inaccessible	0	N	N	0	Y- 42 SF Books	N	Inspection Required
284	2290	1	1	111B		Book closet adjacent Nurse's Office	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Books	N	Inspection Required
285	2290	1	1	103G		Boy's Restroom	Ceiling	Cracking	2	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
286	2290	1	1	103G		Boy's Restroom	W2	Chipping	6	N	N	0	N	N	Chipping on Radiator
287	2290	1	1	103G		Boy's Restroom	W4	Flaking	6	N	N	0	N	N	
288	2290	1	1	100		Classroom 100	W1	Flaking	2	N	N	0	N	N	Additional Chipping
289	2290	1	1	100		Classroom 100	W2	Cracking	5	N	N	0	N	N	Additional Chipping
290	2290	1	1	100		Classroom 100	W3	Flaking	32	Y	Y - On Window Sill	2	N	Y - 2 SF	Additional Efflorescence
291	2290	1	1	100		Classroom 100	W4	Cracking	8	N	N	0	N	N	
292	2290	1	1	105		Classroom 105	Ceiling	Cracking	2	N	N	0	N	N	
293	2290	1	1	105		Classroom 105	W1	Flaking	10	N	N	0	N	N	Damage on Pipe & Wall
294	2290	1	1	105		Classroom 105	W2	Flaking	10	N	N	0	N	N	Flaking Behind Radiator
295	2290	1	1	105		Classroom 105	W3	Chipping	4	N	N	0	N	N	
296	2290	1	1	105		Classroom 105	W4	Chipping	120	N	N	0	N	N	Flaking on Radiator & Wall
297	2290	1	1	120		Classroom 120	Ceiling	Flaking	10	Y	N	0	N	Y - 10 SF	Suspended Ceiling; Damage @ Window Lintels & Missing Ceiling Tile
298	2290	1	1	120		Classroom 120	W2	Plastering Needed	0	N	N	0	N	Y - 1 SF	Plastering Needed
299	2290	1	1	120		Classroom 120	W3	Gouges	1	N	N	0	N	N	
300	2290	1	1	121		Classroom 121	Ceiling	Flaking	80	Y	N	0	N	Y - 3 SF	Additional Efflorescence; Damage on Ceiling & Pipes
301	2290	1	1	121		Classroom 121	W2	Flaking	4	N	N	0	N	N	
302	2290	1	1	121		Classroom 121	W4	Flaking	24	N	N	0	N	N	
303	2290	1	1	122		Classroom 122	W2	Holes	2	N	N	0	N	N	
304	2290	1	1	122		Classroom 122	W3	Flaking	4	N	N	0	Y - 30 SF Contents	N	Flaking Near Floor
305	2290	1	1	122		Classroom 122	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Required
306	2290	1	1	123		Classroom 123	W1	Flaking	14	N	N	0	N	N	Additional Chipping, Gouges
307	2290	1	1	123		Classroom 123	W2	Flaking	4	N	N	0	N	N	Additional Chipping
308	2290	1	1	133		Classroom 131	W1	Partially Inaccessible	0	N	N	0	Y - 28 SF File Cabinets	N	Inspection Required
309	2290	1	1	133		Classroom 131	W2	Cracking	3	N	N	0	N	N	
310	2290	1	1	132		Classroom 132	W3	Flaking	2	N	N	0	N	N	Flaking @ Window Lintel
311	2290	1	1	131		Classroom 133	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
312	2290	1	1	131		Classroom 133	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
313	2290	1	1	131		Classroom 133	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
314	2290	1	1	131		Classroom 133	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
315	2290	1	1	131		Classroom 133	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
316	2290	1	1	131		Classroom 133	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
317	2290	1	1	112A		Closet adjacent Nurse's Office	W1	Cracking	0	N	N	0	N	N	Additional Chipping
318	2290	1	1	112A		Closet adjacent Nurse's Office	W2	Cracking	0	N	N	0	N	N	Additional Chipping
319	2290	1	1	112A		Closet adjacent Nurse's Office	W3	Cracking	0	N	N	0	N	N	Additional Chipping
320	2290	1	1	112A		Closet adjacent Nurse's Office	W4	Cracking	0	N	N	0	N	N	Additional Chipping
321	2290	1	1	S14		Fire Tower adj 120	Ceiling	Flaking	62	N	N	0	N	N	
322	2290	1	1	S12		Fire Tower adjacent to Classroom 100	Ceiling	Flaking	48	N	N	0	N	N	
323	2290	1	1	120A		Girl's Restroom	Ceiling	Cracking	6	N	N	0	N	N	
324	2290	1	1	120A		Girl's Restroom	W1	Cracking	4	N	N	0	N	N	
325	2290	1	1	120A		Girl's Restroom	W3	Cracking	6	N	N	0	N	N	
326	2290	1	1	120A		Girl's Restroom	W4	Chipping	2	N	N	0	N	N	
327	2290	1	1	H10		Hallway from Classrooms 100 to 125	Ceiling	Flaking	16	Y	N	0	N	Y - 16 SF	Additional Efflorescence

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
328	2290	1	1	H10		Hallway from Classrooms 100 to 125	W1	Partially Inaccessible	0	N	N	0	Y - 80 SF Posters	N	Inspection Required
329	2290	1	1	H10		Hallway from Classrooms 100 to 125	W2	Plastering Needed	0	N	N	0	N	Y - 32 SF	Plastering Needed
330	2290	1	1	H10		Hallway from Classrooms 100 to 125	W3	Efflorescence	40	Y	N	0	N	N	Additional Chipping; Damage @ Wall & Window Lintel
331	2290	1	1	H11		Hallway from Classrooms 120 to 125	W2	Flaking	6	N	N	0	N	N	Additional Chipping
332	2290	1	1	H11		Hallway from Classrooms 120 to 125	W3	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping
333	2290	1	1	H12		Hallway from Classrooms 131 to 133	Ceiling	Flaking	24	N	N	0	N	N	
334	2290	1	1	H12		Hallway from Classrooms 131 to 133	W3	Chipping	20	N	N	0	N	N	
335	2290	1	1	106A		IT Closet 106	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
336	2290	1	1	106A		IT Closet 106	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
337	2290	1	1	106A		IT Closet 106	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	No Key
338	2290	1	1	106A		IT Closet 106	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
339	2290	1	1	106A		IT Closet 106	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
340	2290	1	1	106A		IT Closet 106	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
341	2290	1	1	127		Main Office	W1	Chipping	4	N	N	0	Y - 22 SF Posters	N	
342	2290	1	1	127		Main Office	W2	Partially Inaccessible	0	N	N	0	Y - 36 SF Posters, Desks	N	Inspection Required
343	2290	1	1	127		Main Office	W3	Partially Inaccessible	0	N	N	0	Y - 62 SF Posters, Desks	N	Inspection Required
344	2290	1	1	127		Main Office	W4	Partially Inaccessible	0	N	N	0	N	N	Inspection Required
345	2290	1	1	125		Music Classroom 125	W3	Flaking	6	N	N	0	N	Y - 6 SF	Additional Cracking
346	2290	1	1	112		Nurse's Office	Ceiling	Cracking	4	N	N	0	N	N	
347	2290	1	1	108		Nurse's Office	Ceiling	Flaking	3	Y	N	0	N	Y - 1 SF	Additional Efflorescence
348	2290	1	1	108		Nurse's Office	Floor	Debris	0	N	Y - Near Pipe	1	N	N	
349	2290	1	1	112A		Nurse's Restroom	Ceiling	Efflorescence	4	Y	N	0	N	Y - 4 SF	
350	2290	1	1	112A		Nurse's Restroom	Floor	Debris	0	N	Y - @ Wall 2	2	N	N	
351	2290	1	1	134		Office 129	W3	Partially Inaccessible	0	N	N	0	Y - 48 SF Desks	N	Inspection Required
352	2290	1	1	134		Office 129	W4	Partially Inaccessible	0	N	N	0	Y - 38 SF Bookcases, Desks	N	Inspection Required
353	2290	1	1	130		Office 129A	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Desks	N	Inspection Required
354	2290	1	1	129		Office 129B	W3	Partially Inaccessible	0	N	N	0	Y - 28 SF Desks	N	Inspection Required
355	2290	1	1	128		Principal's Office	W1	Partially Inaccessible	0	N	N	0	Y - 32 SF Bookcases, Books	N	Inspection Required
356	2290	1	1	128		Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 40 SF Bookcases, Books, Posters	N	Inspection Required
357	2290	1	1	128		Principal's Office	W4	Chipping	6	N	N	0	N	N	
358	2290	1	1	124A		School Store	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
359	2290	1	1	124A		School Store	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
360	2290	1	1	124A		School Store	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Personal Lock
361	2290	1	1	124A		School Store	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
362	2290	1	1	124A		School Store	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
363	2290	1	1	124A		School Store	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
364	2290	1	1	124		Staff Lounge	Ceiling	Flaking	6	N	N	0	N	N	Suspended Ceiling; Missing Ceiling Tile
365	2290	1	1	124		Staff Lounge	W4	Chipping	4	N	N	0	N	N	
366	2290	1	1	S18		Stairwell adjacent Classroom 106	Ceiling	Flaking	6	N	N	0	N	N	
367	2290	1	1	S18		Stairwell adjacent Classroom 106	W3	Chipping	8	N	N	0	N	N	
368	2290	1	1	S10		Stairwell adjacent Classroom 125	Ceiling	Flaking	14	N	N	0	N	N	
369	2290	1	1	S10		Stairwell adjacent Classroom 125	W3	Chipping	29	N	N	0	N	N	
370	2290	1	1	S11		Stairwell adjacent to Classroom 100	Ceiling	Flaking	15	N	N	0	N	N	
371	2290	1	1	S11		Stairwell adjacent to Classroom 100	W3	Chipping	14	N	N	0	N	N	
372	2290	1	1	S13		Stairwell adjacent to Classroom 105	Ceiling	Flaking	10	N	N	0	N	N	
373	2290	1	1	S15		Stairwell adjacent to Classroom 120	Ceiling	Chipping	0	N	N	0	N	N	
374	2290	1	1	S19		Stairwell adjacent to Classroom 131	Ceiling	Flaking	30	N	N	0	N	N	
375	2290	1	1	S19		Stairwell adjacent to Classroom 131	Floor	Chipping	10	N	N	0	N	N	
376	2290	1	1	S17		Stairwell adjacent to Office 126	W1	Flaking	300	N	N	0	N	N	Additional Cracking
377	2290	1	1	S17		Stairwell adjacent to Office 126	W2	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping
378	2290	1	1	S17		Stairwell adjacent to Office 126	W3	Flaking	4	N	N	0	N	N	Additional Chipping
379	2290	1	1	S17		Stairwell adjacent to Office 126	W4	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
380	2290	1	1	S16		Stairwell adjacent to Office 129	Ceiling	Cracking	3	N	N	0	N	N	
381	2290	1	1	S16		Stairwell adjacent to Office 129	W1	Flaking	200	Y	N	0	N	Y - 20 SF	Additional Efflorescence
382	2290	1	1	S16		Stairwell adjacent to Office 129	W2	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
383	2290	1	1	S16		Stairwell adjacent to Office 129	W3	Flaking	4	N	N	0	N	N	Additional Cracking; Including Window to Hall
384	2290	1	1	S16		Stairwell adjacent to Office 129	W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
385	2290	1	1	126		Vice- Principal's Office	W1	Chipping	2	N	N	0	N	N	
386	2290	1	1	126		Vice- Principal's Office	W2	Partially Inaccessible	0	N	N	0	Y - 24 SF Desks, Contents	N	Inspection Required
387	2290	1	1	126		Vice- Principal's Office	W4	Chipping	10	N	N	0	Y - 60 SF Desks, Contents	N	
388	2290	1	1	104		Weight Room 104	W3	Gouges	2	N	N	0	N	N	2 Locations
389	2290	1	1	104		Weight Room 104	W4	Cracking	4	N	N	0	N	N	Cracking Behind Radiator
390	2290	1	1	121A		Women's Restroom	Ceiling	Flaking	6	N	N	0	N	N	
391	2290	1	1	121A		Women's Restroom	W1	Cracking	2	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
392	2290	1	1	121A		Women's Restroom	W2	Flaking	2	N	N	0	N	N	
393	2290	1	1	121A		Women's Restroom	W3	Cracking	42	N	N	0	N	N	
394	2290	1	1	121A		Women's Restroom	W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping; Damage @ Windows & Wall
395	2290	1	0	16		Athletic Equipment Storage	Ceiling	Flaking	90	N	N	0	N	N	
396	2290	1	0	16		Athletic Equipment Storage	W1	Flaking	45	N	N	0	N	N	Additional Cracking, Chipping
397	2290	1	0	16		Athletic Equipment Storage	W2	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
398	2290	1	0	16		Athletic Equipment Storage	W3	Partially Inaccessible	0	N	N	0	Y - 40 SF Contents	N	Inspection Required
399	2290	1	0	16		Athletic Equipment Storage	W4	Partially Inaccessible	0	N	N	0	Y - 30 SF Contents	N	Inspection Required
400	2290	1	0	12		Auditorium	Ceiling	Flaking	360	Y	N	0	N	Y - 200 SF	Additional Efflorescence
401	2290	1	0	12		Auditorium	W1	Flaking	40	N	N	0	N	N	
402	2290	1	0	12		Auditorium	W2	Flaking	40	N	N	0	N	N	
403	2290	1	0	12		Auditorium	W3	Flaking	40	N	N	0	N	N	
404	2290	1	0	12		Auditorium	W4	Flaking	40	N	N	0	N	N	
405	2290	1	0	24		Backstage Right Closet	Ceiling	Flaking	10	N	N	0	N	N	
406	2290	1	0	24		Backstage Right Closet	Floor	Debris	0	N	Y - @ Perimeter	10	N	N	
407	2290	1	0	24		Backstage Right Closet	W1	Flaking	12	N	N	0	N	N	
408	2290	1	0	24		Backstage Right Closet	W2	Flaking	20	N	N	0	N	N	
409	2290	1	0	24		Backstage Right Closet	W3	Flaking	40	N	N	0	N	N	
410	2290	1	0	24		Backstage Right Closet	W4	Flaking	28	N	N	0	N	N	
411	2290	1	0	9		Cafeteria	Ceiling	Flaking	18	Y	N	0	N	Y - 18 SF	Damage Above Door
412	2290	1	0	9		Cafeteria	W1	Flaking	52	N	N	0	N	N	Additional Chipping
413	2290	1	0	9		Cafeteria	W2	Chipping	30	N	N	0	N	N	
414	2290	1	0	9		Cafeteria	W3	Chipping	70	N	N	0	N	N	
415	2290	1	0	9		Cafeteria	W4	Flaking	48	N	N	0	N	N	
416	2290	1	0	009A		Cafeteria Storage	Ceiling	Flaking	128	N	N	0	N	N	
417	2290	1	0	009A		Cafeteria Storage	Floor	Chipping	10	N	N	0	N	N	
418	2290	1	0	009A		Cafeteria Storage	W1	Flaking	64	N	N	0	N	N	
419	2290	1	0	009A		Cafeteria Storage	W2	Flaking	72	N	N	0	N	N	
420	2290	1	0	009A		Cafeteria Storage	W3	Flaking	50	N	N	0	N	N	
421	2290	1	0	009A		Cafeteria Storage	W4	Flaking	48	N	N	0	N	N	
422	2290	1	0	S03		Fire Tower adjacent to Athletic Equipment Storage 016	Ceiling	Flaking	80	N	N	0	N	N	
423	2290	1	0	S03		Fire Tower adjacent to Athletic Equipment Storage Room 016	Ceiling	Flaking	68	N	N	0	N	N	
424	2290	1	0	S09		Fire Tower adjacent to Staff Locker Room 014	Ceiling	Flaking	72	N	N	0	N	N	
425	2290	1	0	F01		Foyer	Ceiling	Flaking	18	N	N	0	N	N	Additional Cracking, Chipping
426	2290	1	0	F01		Foyer	W1	Flaking	68	Y	N	0	N	Y - 20 SF	Additional Efflorescence, Cracking, Chipping
427	2290	1	0	F01		Foyer	W3	Flaking	48	N	N	0	N	N	Additional Cracking, Chipping

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
428	2290	1	0	7		Gymnasium	Ceiling	Flaking	20	N	N	0	N	N	Additional Chipping; Damage Including Ductwork
429	2290	1	0	7		Gymnasium	W3	Flaking	42	N	N	0	N	N	
430	2290	1	0	H02		Hallway adjacent to Gymnasium	Ceiling	Flaking	28	N	N	0	N	N	Additional Cracking
431	2290	1	0	H02		Hallway adjacent to Gymnasium	W1	Flaking	210	N	N	0	N	N	Additional Cracking, Chipping
432	2290	1	0	H02		Hallway adjacent to Gymnasium	W4	Flaking	120	N	N	0	N	N	Additional Chipping
433	2290	1	0	H01		Hallway from Kitchen Office to Athletic Equipment Storage 016	W2	Chipping	18	N	N	0	N	N	3 Locations; Damage on Radiators & Pipe
434	2290	1	0	H01		Hallway from Kitchen Office to Athletic Equipment Storage 016	W4	Flaking	30	N	N	0	N	Y - 5 SF	
435	2290	1	0	H03		Hallway from Office B05 to Staff Locker Room	Ceiling	Flaking	6	N	N	0	N	N	
436	2290	1	0	H03		Hallway from Office B05 to Staff Locker Room	W1	Cracking	20	N	N	0	N	N	Additional Chipping
437	2290	1	0	H03		Hallway from Office B05 to Staff Locker Room	W2	Chipping	4	N	N	0	N	N	
438	2290	1	0	H03		Hallway from Office B05 to Staff Locker Room	W3	Chipping	5	N	N	0	N	N	
439	2290	1	0	H03		Hallway from Office B05 to Staff Locker Room	W4	Chipping	2	N	N	0	N	N	
440	2290	1	0	10		Kitchen	Ceiling	Flaking	100	N	N	0	N	N	Additional Cracking
441	2290	1	0	10		Kitchen	Floor	Chipping	20	N	N	0	N	N	
442	2290	1	0	8		Kitchen Office	Ceiling	Flaking	66	N	N	0	N	N	
443	2290	1	0	8		Kitchen Office	Floor	Chipping	8	N	N	0	N	N	
444	2290	1	0	8		Kitchen Office	W1	Flaking	30	N	N	0	N	N	
445	2290	1	0	8		Kitchen Office	W2	Flaking	36	N	N	0	N	N	
446	2290	1	0	8		Kitchen Office	W3	Flaking	28	N	N	0	N	N	
447	2290	1	0	8		Kitchen Office	W4	Flaking	34	N	N	0	N	N	
448	2290	1	0	10		Kitchen	W1	Flaking	30	N	N	0	N	N	
449	2290	1	0	23		Men's Restroom	W1	Flaking	4	N	N	0	N	N	Additional Cracking
450	2290	1	0	23		Men's Restroom	W2	Cracking	2	N	N	0	N	N	
451	2290	1	0	23		Men's Restroom	W3	Flaking	4	N	N	0	N	N	Additional Cracking
452	2290	1	0	23		Men's Restroom	W4	Flaking	14	N	N	0	N	N	Flaking on Radiator
453	2290	1	0	11		Office B05 (Security Office)	W1	Flaking	180	N	N	0	N	Y - 1 SF	
454	2290	1	0	11		Office B05 (Security Office)	W2	Flaking	36	N	N	0	N	N	
455	2290	1	0	11		Office B05 (Security Office)	W3	Flaking	48	N	N	0	N	N	
456	2290	1	0	11		Office B05 (Security Office)	W4	Flaking	60	N	N	0	N	N	
457	2290	1	0	011A		Office B05 Closet	W1	Flaking	6	N	N	0	N	N	
458	2290	1	0	011A		Office B05 Closet	W2	Flaking	4	N	N	0	N	N	
459	2290	1	0	011A		Office B05 Closet	W3	Flaking	10	N	N	0	N	N	
460	2290	1	0	011A		Office B05 Closet	W4	Flaking	8	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
461	2290	1	0	011B		Office B05 Closet/Server Room	Ceiling	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
462	2290	1	0	011B		Office B05 Closet/Server Room	Floor	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
463	2290	1	0	011B		Office B05 Closet/Server Room	W1	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
464	2290	1	0	011B		Office B05 Closet/Server Room	W2	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
465	2290	1	0	011B		Office B05 Closet/Server Room	W3	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
466	2290	1	0	011B		Office B05 Closet/Server Room	W4	Inaccessible	N/A	N/A	N/A	N/A	N/A	N/A	Inspection Required
467	2290	1	0	14		Staff Locker Room	Ceiling	Flaking	120	Y	N	0	N	Y - 24 SF	Additional Efflorescence
468	2290	1	0	14		Staff Locker Room	Floor	Debris	0	N	Y - @ Perimeter	10	N	N	
469	2290	1	0	14		Staff Locker Room	W1	Cracking	6	N	N	0	Y - 80 SF File Cabinets	N	
470	2290	1	0	14		Staff Locker Room	W2	Flaking	20	Y	N	0	Y - 160 SF File Cabinets	Y - 20 SF	Additional Efflorescence
471	2290	1	0	14		Staff Locker Room	W3	Flaking	55	Y	N	0	N	Y - 4 SF	Additional Efflorescence
472	2290	1	0	14		Staff Locker Room	W4	Flaking	80	Y	N	0	N	Y - 2- SF	Additional Efflorescence
473	2290	1	0	4		Staff Restroom	W1	Flaking	4	N	N	0	N	N	
474	2290	1	0	4		Staff Restroom	W2	Flaking	6	N	N	0	N	N	
475	2290	1	0	4		Staff Restroom	W3	Flaking	9	N	N	0	N	N	
476	2290	1	0	4		Staff Restroom	W4	Flaking	2	N	N	0	N	N	
477	2290	1	0	012A		Stage	Ceiling	Flaking	10	N	N	0	N	N	
478	2290	1	0	S06		Stairwell adjacent Foyer - North Side	Ceiling	Cracking	3	N	N	0	N	N	
479	2290	1	0	S05		Stairwell adjacent Foyer - North Side	W1	Flaking	200	Y	N	0	N	Y - 20 SF	Additional Efflorescence
480	2290	1	0	S05		Stairwell adjacent Foyer - North Side	W2	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
481	2290	1	0	S05		Stairwell adjacent Foyer - North Side	W3	Flaking	4	N	N	0	N	N	Additional Cracking; Including Window to Hall
482	2290	1	0	S05		Stairwell adjacent Foyer - North Side	W4	Flaking	20	N	N	0	N	N	Additional Cracking, Chipping
483	2290	1	0	S06		Stairwell adjacent Foyer - South Side	W1	Flaking	300	N	N	0	N	N	Additional Cracking
484	2290	1	0	S06		Stairwell adjacent Foyer - South Side	W2	Flaking	80	N	N	0	N	N	Additional Cracking, Chipping
485	2290	1	0	S06		Stairwell adjacent Foyer - South Side	W3	Flaking	4	N	N	0	N	N	Additional Chipping
486	2290	1	0	S06		Stairwell adjacent Foyer - South Side	W4	Flaking	30	N	N	0	N	N	Additional Cracking, Chipping
487	2290	1	0	S02		Stairwell adjacent to Athletic Equipment Storage 016	W1	Flaking	14	N	N	0	N	N	Additional Cracking, Chipping
488	2290	1	0	S02		Stairwell adjacent to Athletic Equipment Storage 016	W2	Flaking	16	Y	N	0	N	N	Additional Efflorescence
489	2290	1	0	S02		Stairwell adjacent to Athletic Equipment Storage 016	W3	Flaking	20	Y	N	0	N	N	Additional Efflorescence
490	2290	1	0	S02		Stairwell adjacent to Athletic Equipment Storage 016	W4	Flaking	4	Y	N	0	N	N	Additional Efflorescence
491	2290	1	0	S04		Stairwell adjacent to Boy's Locker Room 005	Ceiling	Flaking	20	N	N	0	N	N	

FLC -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
492	2290	1	0	S01		Stairwell adjacent to Office B05	Floor	Chipping	10	N	N	0	N	N	Chipping on Stairs
493	2290	1	0	S01		Stairwell adjacent to Office B05	W4	Chipping	4	N	N	0	N	N	
494	2290	1	0	S08		Stairwell adjacent to Staff Locker Room 014	Ceiling	Flaking	14	N	N	0	N	N	
495	2290	1	0	023A		Women's Restroom	W1	Chipping	10	N	N	0	N	N	
496	2290	1	0	023A		Women's Restroom	W2	Cracking	8	N	N	0	N	N	
497	2290	1	0	023A		Women's Restroom	W3	Chipping	6	N	N	0	N	N	
498	2290	1	0	023A		Women's Restroom	W4	Cracking	12	N	N	0	N	N	