

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
1	6230	1	B	H001		Basement Hallway from Stairwell to Stairwell	W1	Chipping	10	No	No	N/A	N/A	No	
2	6230	1	B	H001		Basement Hallway from Stairwell to Stairwell	W3	Cracking, Chipping, Flaking	20	No	No	N/A	N/A	No	
3	6230	1	B	H001		Basement Hallway from Stairwell to Stairwell	W4	Hole, Flaking	161	No	No	N/A	N/A	Yes	
4	6230	1	B	H001		Basement Hallway from Stairwell to Stairwell	W2	Chipping, Holes, Flaking, Efflorescence, Significant Moisture Damage	207	Yes	No	N/A	N/A	Yes	
5	6230	1	B	H001		Basement Hallway from Stairwell to Stairwell	Ceiling	Flaking on ceiling and metal duct	1160	No	No	N/A	N/A	No	
6	6230	1	3	322A		Boy's Restroom	W1	Chipping on door and doorframe	7	No	No	N/A	N/A	No	
7	6230	1	3	322A		Boy's Restroom	W2	Cracking, Gouges, Flaking	12	No	No	N/A	N/A	Yes	
8	6230	1	3	322A		Boy's Restroom	W4	Cracking, Efflorescence	12	Yes	No	N/A	N/A	Yes	
9	6230	1	3	322A		Boy's Restroom	W3	Cracking, Chipping on windowsill, Flaking on radiator, Efflorescence	20	Yes	No	N/A	N/A	Yes	
10	6230	1	B	8		Boy's Restroom	W2	Flaking	2	No	No	N/A	N/A	No	
11	6230	1	B	8		Boy's Restroom	W3	Flaking	2	No	No	N/A	N/A	No	
12	6230	1	B	8		Boy's Restroom	W1	Flaking	5	No	No	N/A	N/A	No	
13	6230	1	B	8		Boy's Restroom	W4	3 ch 3 flk 1 efl	7	No	No	N/A	N/A	No	
14	6230	1	B	8		Boy's Restroom	Ceiling	Chipping, Flaking, Efflorescence	330	Yes	No	N/A	N/A	No	
15	6230	2	1	100		Cafeteria	W1	Chipping on wall, door and doorframe, Flaking on metal pipe	40	No	No	N/A	N/A	No	
16	6230	2	1	100		Cafeteria	W3	Cracking, Chipping on door, doorframe, and cove base	57	No	No	N/A	N/A	No	
17	6230	2	1	100		Cafeteria	Ceiling	Flaking on ceiling and metal pipe	99	No	No	N/A	N/A	No	
18	6230	2	1	100		Cafeteria	W4	Cracking, Chipping on wall, metal jackets, radiator covers, and cove base	120	No	No	N/A	N/A	No	
19	6230	2	1	100		Cafeteria	W2	Cracking, Chipping on wall, windowsills, metal jackets, radiator covers, and cove base	127	No	No	N/A	N/A	No	
20	6230	1	1	105		Classroom 105	W2	Chipping, Holes	8	No	No	N/A	N/A	Yes	
21	6230	1	1	105		Classroom 105	W4	Cracking, Chipping on windowsills, Staple Holes, Flaking, Efflorescence	36	Yes	No	N/A	N/A	Yes	
22	6230	1	1	105		Classroom 105	W3	Cracking, Chipping on windowsills and wood cove base, Holes, Staples, Flaking, Efflorescence	44	Yes	No	N/A	N/A	Yes	
23	6230	1	1	105		Classroom 105	W1	Chipping on door, doorframe, blackboard ledge, and wood cove base, Staple Holes	101	No	No	N/A	N/A	Yes	
24	6230	1	1	105B		Classroom 105 Closet	W4	Chipping	6	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
25	6230	1	1	105B		Classroom 105 Closet	Ceiling	Flaking	8	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
26	6230	1	1	105B		Classroom 105 Closet	W1	Chipping on door and doorframe	34	No	No	N/A	N/A	No	
27	6230	1	1	105B		Classroom 105 Closet	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
28	6230	1	1	105B		Classroom 105 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
29	6230	1	1	105B		Classroom 105 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
30	6230	1	1	105A		Classroom 105 Restroom	Ceiling	Holes	5	No	No	N/A	N/A	Yes	
31	6230	1	1	105A		Classroom 105 Restroom	W2	Chipping on windowsill and metal pipe	7	No	No	N/A	N/A	No	
32	6230	1	1	105A		Classroom 105 Restroom	W3	Cracking, Flaking	11	No	No	N/A	N/A	No	
33	6230	1	1	105A		Classroom 105 Restroom	W1	Cracking, Chipping on door and doorframe, Flaking	25	No	No	N/A	N/A	No	
34	6230	1	1	106		Classroom 106	Ceiling	Cracking, Hole	16	No	No	N/A	N/A	Yes	
35	6230	1	1	106		Classroom 106	W4	Chipping on built in wood shelves, Staples	36	No	No	N/A	N/A	Yes	
36	6230	1	1	106		Classroom 106	W2	Cracking, Chipping on wall, and wood cove base, Staple holes	56	No	No	N/A	N/A	Yes	
37	6230	1	1	106		Classroom 106	W3	Cracking, Chipping on wall, windowframes, windowsills, and wood cove base, Holes, Staple Holes, Efflorescence	64	Yes	No	N/A	N/A	Yes	
38	6230	1	1	106		Classroom 106	W1	Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Holes, Staple Holes	65	No	No	N/A	N/A	Yes	
39	6230	1	1	106B		Classroom 106 Closet	W4	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
40	6230	1	1	106B		Classroom 106 Closet	Ceiling	Flaking	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
41	6230	1	1	106B		Classroom 106 Closet	W1	Chipping on door and doorframe	30	No	No	N/A	N/A	No	
42	6230	1	1	106B		Classroom 106 Closet	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
43	6230	1	1	106B		Classroom 106 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
44	6230	1	1	106B		Classroom 106 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
45	6230	1	1	106A		Classroom 106 Restroom	W3	Flaking	1	No	No	N/A	N/A	No	
46	6230	1	1	106A		Classroom 106 Restroom	Ceiling	Hole	1	No	No	N/A	N/A	Yes	
47	6230	1	1	106A		Classroom 106 Restroom	W2	Chipping	2	No	No	N/A	N/A	No	
48	6230	1	1	106A		Classroom 106 Restroom	W4	Chipping on windowframe and windowsill	8	No	No	N/A	N/A	No	
49	6230	1	1	106A		Classroom 106 Restroom	W1	Chipping on door and doorframe, Flaking on conduit and metal pipe	33	No	No	N/A	N/A	No	
50	6230	1	1	107		Classroom 107	Ceiling	Cracking	4	No	No	N/A	N/A	No	
51	6230	1	1	107		Classroom 107	W2	Chipping on wall, built in wood shelves, and wood cove base	10	No	No	N/A	N/A	No	
52	6230	1	1	107		Classroom 107	W3	Chipping on wall, windowsills, and wood cove base	10	No	No	N/A	N/A	No	
53	6230	1	1	107		Classroom 107	W4	Chipping on wall, blackboard ledge, and wood cove base, Flaking on fiberglass pipe insulation	22	No	No	N/A	N/A	No	
54	6230	1	1	107		Classroom 107	W1	Cracking, Chipping on wall, door, doorframe, built in wood cabinets, blackboard ledge, and wood cove base	27	No	No	N/A	N/A	No	
55	6230	1	1	107A		Classroom 107 Closet	W1	Chipping on doorframe	2	No	No	N/A	N/A	No	
56	6230	1	1	107A		Classroom 107 Closet	Ceiling	Cracking	4	No	No	N/A	N/A	No	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
57	6230	1	1	107A		Classroom 107 Closet	W4	Cracking, Chipping on wood cove base, Flaking on metal pipes	12	No	No	N/A	N/A	No	
58	6230	1	1	107B		Classroom 107 Restroom	W1	Chipping on door	1	No	No	N/A	N/A	No	
59	6230	1	1	107B		Classroom 107 Restroom	W2	Cracking	1	No	No	N/A	N/A	No	
60	6230	1	1	110		Classroom 110	Ceiling	Flaking	4	No	No	N/A	N/A	No	
61	6230	1	1	110		Classroom 110	W3	Cracking on wall and in air shaft, Chipping on wood cove base	12	No	No	N/A	N/A	No	
62	6230	1	1	110		Classroom 110	W1	Chipping on door, doorframe, blackboard ledge, and wood cove base	41	No	No	N/A	N/A	No	
63	6230	1	1	110		Classroom 110	W2	Chipping on wall, windowsills, and wood cove base, Flaking on wall and wood cove base, Efflorescence	56	Yes	No	N/A	N/A	Yes	
64	6230	1	1	110		Classroom 110	W4	Chipping on wall, windowsills and wood cove base, Holes, Flaking, Efflorescence	63	Yes	No	N/A	N/A	Yes	Some damage has been repaired but is returning
65	6230	1	1	110		Classroom 110	Floor	N/A	N/A	No	Debris below efflorescence	2	N/A	No	
66	6230	1	1	110C		Classroom 110 Closet	W4	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
67	6230	1	1	110C		Classroom 110 Closet	W3	Chipping on windowsill and wood cove base, Flaking	6	No	No	N/A	N/A	No	
68	6230	1	1	110C		Classroom 110 Closet	W1	Chipping on doorframe	10	No	No	N/A	N/A	No	
69	6230	1	1	110C		Classroom 110 Closet	W2	Chipping on built in wood cabinet	14	No	No	N/A	N/A	No	
70	6230	1	1	110A		Classroom 110 Restroom	W2	Chipping on radiator	2	No	No	N/A	N/A	No	
71	6230	1	1	110A		Classroom 110 Restroom	W4	Flaking on metal pipe	7	No	No	N/A	N/A	No	
72	6230	1	1	110A		Classroom 110 Restroom	W3	Chipping on windowframe and windowsill. Flaking on exhaust fan	10	No	No	N/A	N/A	No	
73	6230	1	1	110A		Classroom 110 Restroom	Ceiling	Flaking	15	No	No	N/A	N/A	No	
74	6230	1	1	110A		Classroom 110 Restroom	W1	Chipping on door and doorframe	19	No	No	N/A	N/A	No	
75	6230	1	1	110B		Classroom 110 Stairwell Exit	W1	Chipping on doorframe	3	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
76	6230	1	1	110B		Classroom 110 Stairwell Exit	W2	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
77	6230	1	1	110B		Classroom 110 Stairwell Exit	W3	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
78	6230	1	1	110B		Classroom 110 Stairwell Exit	W4	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
79	6230	1	1	110B		Classroom 110 Stairwell Exit	Ceiling	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
80	6230	1	1	110B		Classroom 110 Stairwell Exit	Floor	N/A	N/A	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
81	6230	1	2	201		Classroom 201	W4	Chipping, Hole	10	No	No	N/A	N/A	Yes	
82	6230	1	2	201		Classroom 201	W2	Chipping on wall, windowsills, and wood cove base, Hole, Staples and Staple Holes, Spalling	51	Yes	No	N/A	N/A	Yes	
83	6230	1	2	201		Classroom 201	W3	Chipping on wall, windowsills, and wood cove base, Staples and Staple Holes, Flaking, Spalling	56	Yes	No	N/A	N/A	Yes	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
84	6230	1	2	201		Classroom 201	W1	Chipping on wall, door, doorframe, blackboard ledge, and wood cove, Hole, Staples and Staple Holes, Flaking on door and doorframe	86	No	No	N/A	N/A	Yes	
85	6230	1	2	201A		Classroom 201 Closet	Ceiling	Flaking	8	No	No	N/A	N/A	No	
86	6230	1	2	201A		Classroom 201 Closet	W2	Chipping	19	No	No	N/A	N/A	No	
87	6230	1	2	201A		Classroom 201 Closet	W1	Chipping on door and doorframe	23	No	No	N/A	N/A	No	
88	6230	1	2	201A		Classroom 201 Closet	W4	Chipping on wall, door, and doorframe	39	No	No	N/A	N/A	No	
89	6230	1	2	201A		Classroom 201 Closet	W3	N/A	N/A	No	No	N/A	Cabinets	No	Limited inspection due to cabinets
90	6230	1	2	202		Classroom 202	W4	Chipping	17	No	No	N/A	N/A	No	
91	6230	1	2	202		Classroom 202	W2	Chipping	25	No	No	N/A	N/A	No	
92	6230	1	2	202		Classroom 202	W3	Chipping on wall, windowsills, and wood cove base, Hole, Staples and Staple Holes	69	No	No	N/A	N/A	Yes	
93	6230	1	2	202		Classroom 202	W1	Chipping on door, doorframe, and wood cove base, Holes, Staples and Staple Holes	99	No	No	N/A	N/A	Yes	
94	6230	1	2	202A		Classroom 202 Closet	W3	Chipping	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
95	6230	1	2	202A		Classroom 202 Closet	Ceiling	Flaking	5	No	No	N/A	N/A	No	
96	6230	1	2	202A		Classroom 202 Closet	W4	Chipping	12	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
97	6230	1	2	202A		Classroom 202 Closet	W1	Chipping on door and doorframe	40	No	No	N/A	N/A	No	
98	6230	1	2	202A		Classroom 202 Closet	W2	Chipping on wall, door, and doorframe	40	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
99	6230	1	2	203		Classroom 203	W4	Chipping, Hole	27	No	No	N/A	N/A	Yes	
100	6230	1	2	203		Classroom 203	W2	Chipping, Hole	34	No	No	N/A	N/A	Yes	
101	6230	1	2	203		Classroom 203	W3	Chipping on wall, windowsills, and wood cove base, Holes, Staples and Staple Holes, Flaking	109	No	No	N/A	N/A	Yes	
102	6230	1	2	203		Classroom 203	W1	Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Hole, Staples and Staple Holes	140	No	No	N/A	N/A	Yes	
103	6230	1	2	203A		Classroom 203 Closet	W3	Chipping	1	No	No	N/A	N/A	No	
104	6230	1	2	203A		Classroom 203 Closet	Ceiling	Flaking	4	No	No	N/A	N/A	No	
105	6230	1	2	203A		Classroom 203 Closet	W4	Chipping	5	No	No	N/A	N/A	No	
106	6230	1	2	203A		Classroom 203 Closet	W1	Chipping on door and frame	45	No	No	N/A	N/A	No	
107	6230	1	2	203A		Classroom 203 Closet	W2	Chipping on wall, door, and doorframe	45	No	No	N/A	N/A	No	
108	6230	1	2	204		Classroom 204	W4	Chipping, Flaking	38	No	No	N/A	N/A	No	
109	6230	1	2	204		Classroom 204	W2	Chipping, Flaking	44	No	No	N/A	N/A	No	
110	6230	1	2	204		Classroom 204	W3	Cracking, Chipping on wall, windowsills, and wood cove base, Holes, Staples and Staple Holes, Flaking	109	No	No	N/A	N/A	Yes	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
111	6230	1	2	204		Classroom 204	W1	Cracking, Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Holes, Staples and Staple Holes, Flaking	177	No	No	N/A	N/A	Yes	
112	6230	1	2	204A		Classroom 204 Closet	Ceiling	Flaking	2	No	No	N/A	N/A	No	Limited inspection due to stored materials
113	6230	1	2	204A		Classroom 204 Closet	W2	Chipping	5	No	No	N/A	N/A	No	Limited inspection due to stored materials
114	6230	1	2	204A		Classroom 204 Closet	W4	Chipping on door and doorframe	14	No	No	N/A	N/A	No	Limited inspection due to stored materials
115	6230	1	2	204A		Classroom 204 Closet	W1	Chipping on door and doorframe, Flaking on door and doorframe	49	No	No	N/A	N/A	No	Limited inspection due to stored materials
116	6230	1	2	204A		Classroom 204 Closet	W3	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
117	6230	1	2	204A		Classroom 204 Closet	Floor	N/A	N/A	No	No	N/A	N/A	No	Limited inspection due to stored materials
118	6230	1	2	205		Classroom 205	W2	Cracking, Chipping	29	No	No	N/A	N/A	No	
119	6230	1	2	205		Classroom 205	W4	Cracking, Chipping on wall, windowsills, and wood cove base, Hole, Staples and Staple Holes	76	No	No	N/A	N/A	Yes	
120	6230	1	2	205		Classroom 205	W3	Cracking, Chipping on wall, metal pipe, windowsills, and wood cove base, Holes, Staples and Staple Holes	97	No	No	N/A	N/A	Yes	
121	6230	1	2	205		Classroom 205	W1	Cracking, Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Staples and Staple Holes	165	No	No	N/A	N/A	Yes	
122	6230	1	2	205A		Classroom 205 Closet	W4	Chipping	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
123	6230	1	2	205A		Classroom 205 Closet	Ceiling	Flaking	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
124	6230	1	2	205A		Classroom 205 Closet	W1	Chipping on door and doorframe	22	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
125	6230	1	2	205A		Classroom 205 Closet	W2	Chipping on wall, door, doorframe, and built in wood cabinet	48	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
126	6230	1	2	205A		Classroom 205 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
127	6230	1	2	205A		Classroom 205 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
128	6230	1	2	206		Classroom 206	Ceiling	Flaking, Spalling	12	Yes	No	N/A	N/A	Yes	
129	6230	1	2	206		Classroom 206	W4	Chipping on blackboard ledge and wood cove base, Holes, Staples	37	No	No	N/A	N/A	Yes	
130	6230	1	2	206		Classroom 206	W2	Cracking, Chipping on blackboard ledge and wood cove base, Holes, Staples and Staple Holes, Flaking	59	No	No	N/A	N/A	Yes	
131	6230	1	2	206		Classroom 206	W3	Cracking, Chipping on wall, windowframes, windowsills, and wood cove base, Holes	73	No	No	N/A	Tables and Computers	Yes	
132	6230	1	2	206		Classroom 206	W1	Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Holes, Flaking	85	No	No	N/A	N/A	Yes	
133	6230	1	2	206B		Classroom 206 Closet	W2	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
134	6230	1	2	206B		Classroom 206 Closet	W4	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
135	6230	1	2	206B		Classroom 206 Closet	W1	Chipping on door and doorframe	32	No	No	N/A	Stored Materials	No	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
136	6230	1	2	206B		Classroom 206 Closet	Ceiling	Flaking	43	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
137	6230	1	2	206B		Classroom 206 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
138	6230	1	2	206B		Classroom 206 Closet	Floor	N/A	N/A	No	Paint Chips	2	Stored Materials	No	Limited inspection due to stored materials
139	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	W1	Chipping on door and doorframe	6	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
140	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
141	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
142	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
143	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
144	6230	1	2	206A		Classroom 206 Telecommunications Equipment Room	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
145	6230	1	2	207		Classroom 207	W2	Chipping on wall and wood cove base, Holes, paint has been stabilized, Staples	18	No	No	N/A	N/A	Yes	
146	6230	1	2	207		Classroom 207	Ceiling	Flaking, Efflorescence	25	Yes	No	N/A	N/A	Yes	
147	6230	1	2	207		Classroom 207	W4	Chipping on wall, blackboard ledge, and wood cove base, Holes, Staples, Efflorescence	40	Yes	No	N/A	N/A	Yes	
148	6230	1	2	207		Classroom 207	W3	Cracking, Chipping on wall, windowframes, windowsills, and wood cove base, Holes, Staples, Flaking on fiberglass pipe insulation, Efflorescence	48	Yes	No	N/A	Sheet stapled to wall	Yes	
149	6230	1	2	207		Classroom 207	W1	Chipping on wall, door, doorframe, built in wood cabinet, blackboard ledge, and wood cove base, Holes, some have been stabilized, Flaking on door and doorframe, Efflorescence	64	Yes	No	N/A	N/A	Yes	
150	6230	1	2	207A		Classroom 207 Closet	Ceiling	Chipping, Efflorescence	3	Yes	No	N/A	N/A	Yes	
151	6230	1	2	207A		Classroom 207 Closet	W3	Cracking, Chipping on wall, windowframe, windowsills, and wood cove base, Holes	49	No	No	N/A	N/A	Yes	
152	6230	1	2	207A		Classroom 207 Closet	W4	Chipping on wall, wood cove base, and radiator heat shield, Holes, Efflorescence	49	Yes	No	N/A	N/A	Yes	
153	6230	1	2	207A		Classroom 207 Closet	W1	Chipping on wall, door, and doorframe, Holes	51	No	No	N/A	N/A	Yes	
154	6230	1	2	207A		Classroom 207 Closet	W2	Cracking, Chipping on wall, door, doorframe, metal pipe, and wood cove base, Holes	148	No	No	N/A	N/A	Yes	
155	6230	1	3	301		Classroom 301	W4	Staples and Staple Holes	30	No	No	N/A	N/A	Yes	
156	6230	1	3	301		Classroom 301	W1	Chipping on wall, door, and doorframe	31	No	No	N/A	Posters	No	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
157	6230	1	3	301		Classroom 301	W3	Cracking on windowsills, Chipping on windowsills and wood cove base, Staples and Staple Holes	39	No	No	N/A	N/A	Yes	
158	6230	1	3	301		Classroom 301	W2	Cracking, Chipping on windowsills and wood cove base, Staples and Staple Holes, Efflorescence	40	Yes	No	N/A	N/A	Yes	
159	6230	1	3	301B		Classroom 301 Closet	W2	Chipping	2	No	No	N/A	N/A	No	
160	6230	1	3	301B		Classroom 301 Closet	W3	Efflorescence	6	Yes	Debris on windowsill	2	N/A	No	
161	6230	1	3	301B		Classroom 301 Closet	Ceiling	Flaking above missing ceiling tiles	8	No	No	N/A	N/A	No	
162	6230	1	3	301B		Classroom 301 Closet	W1	Chipping on door and doorframe	12	No	No	N/A	N/A	No	
163	6230	1	3	301B		Classroom 301 Closet	W4	Chipping, Efflorescence	14	Yes	No	N/A	N/A	No	
164	6230	1	3	302		Classroom 302	W4	Chipping, Staples	9	No	No	N/A	N/A	No	
165	6230	1	3	302		Classroom 302	W2	Chipping, Staples	14	No	No	N/A	N/A	No	
166	6230	1	3	302		Classroom 302	W1	Chipping on wall, door, and doorframe, Flaking	27	No	No	N/A	N/A	No	
167	6230	1	3	302		Classroom 302	W3	Cracking, Chipping on wall, windowsills, and wood cove base, Flaking, Spalling	86	Yes	No	N/A	N/A	No	
168	6230	1	3	302A		Classroom 302 Closet	W1	Chipping on door and doorframe	2	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
169	6230	1	3	302A		Classroom 302 Closet	Ceiling	Flaking	4	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
170	6230	1	3	302A		Classroom 302 Closet	W2	Chipping on door and doorframe, Holes, Flaking	21	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
171	6230	1	3	302A		Classroom 302 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
172	6230	1	3	302A		Classroom 302 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
173	6230	1	3	302A		Classroom 302 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
174	6230	1	3	303		Classroom 303	W2	Cracking, Chipping	5	No	No	N/A	N/A	No	
175	6230	1	3	303		Classroom 303	W4	Holes, Staples	8	No	No	N/A	N/A	Yes	
176	6230	1	3	303		Classroom 303	W3	Cracking, Chipping on wood cove base, Flaking	16	No	No	N/A	Furniture	No	Limited inspection due to stored furniture
177	6230	1	3	303		Classroom 303	W1	Cracking, Chipping on wall, door, doorframe, and wood cove base, Holes, Flaking	57	No	No	N/A	N/A	Yes	
178	6230	1	3	303A		Classroom 303 Closet	W4	Hole	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
179	6230	1	3	303A		Classroom 303 Closet	W1	Chipping on door and doorframe	5	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
180	6230	1	3	303A		Classroom 303 Closet	W2	Chipping on wall, door, and doorframe, Holes	15	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
181	6230	1	3	303A		Classroom 303 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
182	6230	1	3	304		Classroom 304	W2	Hole, Staples	3	No	No	N/A	N/A	Yes	
183	6230	1	3	304		Classroom 304	W4	Chipping, Hole	4	No	No	N/A	N/A	Yes	
184	6230	1	3	304		Classroom 304	W3	Cracking, Chipping on wall and wood cove base, Hole, Staple Holes	48	No	No	N/A	N/A	Yes	
185	6230	1	3	304		Classroom 304	W1	Chipping on wall, door, doorframe, and chair rail, Holes, Staple Holes, Flaking	53	No	No	N/A	N/A	Yes	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
186	6230	1	3	304A		Classroom 304 Closet	W2	Chipping	7	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
187	6230	1	3	304A		Classroom 304 Closet	W1	Chipping on door and doorframe	18	No	No	N/A	Stored Materials	No	
188	6230	1	3	304A		Classroom 304 Closet	W4	Chipping on door and doorframe	19	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
189	6230	1	3	304A		Classroom 304 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
190	6230	1	3	305		Classroom 305	W4	Cracking, Chipping on windowsills and wood cove base, Staples and Staple Holes	44	No	No	N/A	N/A	Yes	
191	6230	1	3	305		Classroom 305	W3	Cracking, Chipping on wall and wood cove base, Staples and Staple Holes	49	No	No	N/A	N/A	Yes	
192	6230	1	3	305		Classroom 305	W2	Cracking, Chipping, Staples and Staple Holes, Flaking on wood top	62	No	No	N/A	N/A	Yes	
193	6230	1	3	305		Classroom 305	W1	Chipping on wall, door, doorframe, and wood cove base, Holes, Staples and Staple Holes, Flaking	90	No	No	N/A	N/A	Yes	
194	6230	1	3	305A		Classroom 305 Closet	W4	Flaking	1	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
195	6230	1	3	305A		Classroom 305 Closet	W3	Flaking	3	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
196	6230	1	3	305A		Classroom 305 Closet	W1	Chipping on door and doorframe	9	No	No	N/A	Stored Materials	No	
197	6230	1	3	305A		Classroom 305 Closet	Ceiling	Flaking above missing ceiling tiles	12	No	No	N/A	Stored Materials	No	
198	6230	1	3	305A		Classroom 305 Closet	W2	Chipping on door, doorframe, and built in wood cabinet, Flaking on wall and built in wood cabinet, Efflorescence	22	Yes	No	N/A	Stored Materials	No	Limited inspection due to stored materials
199	6230	1	3	306		Classroom 306	Ceiling	Cracking, Flaking, Efflorescence	21	Yes	No	N/A	N/A	Yes	
200	6230	1	3	306		Classroom 306	W4	Cracking, Chipping on wall and blackboard	22	No	No	N/A	N/A	No	
201	6230	1	3	306		Classroom 306	W2	Cracking, Chipping, Holes, paint has been stabilized on some, Efflorescence	24	Yes	No	N/A	N/A	Yes	
202	6230	1	3	306		Classroom 306	W3	Chipping on wall, windowsills, and wood cove base, Staples and Staple Holes, Flaking	88	No	No	N/A	Poster with staples	Yes	
203	6230	1	3	306		Classroom 306	W1	Cracking, Chipping on wall, door, doorframe, blackboard, and wood cove base, Holes, Flaking	99	No	No	N/A	N/A	Yes	
204	6230	1	3	306A		Classroom 306 Closet	W2	Chipping, Efflorescence	3	Yes	No	N/A	Stored Materials	No	Limited inspection due to stored materials
205	6230	1	3	306A		Classroom 306 Closet	W3	Efflorescence	8	Yes	No	N/A	Stored Materials	No	Limited inspection due to stored materials
206	6230	1	3	306A		Classroom 306 Closet	Ceiling	Flaking above missing ceiling tiles	12	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
207	6230	1	3	306A		Classroom 306 Closet	W1	Chipping on door and doorframe	17	No	No	N/A	Stored Materials	No	
208	6230	1	3	306A		Classroom 306 Closet	W4	Chipping on wall, door, and doorframe, Efflorescence	18	Yes	No	N/A	Stored Materials	No	Limited inspection due to stored materials
209	6230	1	3	307		Classroom 307	W3	Chipping on wall, windowsills, and wood cove base, Flaking, Efflorescence, some behind radiator	50	Yes	Debris and paint chips on windowsills	3	N/A	Yes	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
210	6230	1	3	307		Classroom 307	W4	Cracking, Chipping on wall, blackboard, and wood cove base, Flaking, Efflorescence	56	Yes	No	N/A	N/A	Yes	
211	6230	1	3	307		Classroom 307	W2	Cracking, Chipping on wall, blackboard, and wood cove base, Holes, Flaking	68	No	No	N/A	N/A	Yes	
212	6230	1	3	307		Classroom 307	W1	Cracking, Chipping on wall, door, doorframe, blackboard, and wood cove base, Holes, some in air shaft, Flaking in air shaft, Efflorescence, Significant Moisture Damage	88	Yes	No	N/A	N/A	Yes	
213	6230	1	3	307		Classroom 307	Ceiling	Flaking	225	No	No	N/A	N/A	No	
214	6230	1	3	307		Classroom 307	Floor	N/A	N/A	No	Debris in corner of walls 1 and 4	3	N/A	No	
215	6230	1	3	307A		Classroom 307 Closet	W1	Cracking, Chipping on door and doorframe, Flaking	18	No	No	N/A	N/A	No	
216	6230	1	3	307A		Classroom 307 Closet	Ceiling	Flaking, Efflorescence	15	Yes	No	N/A	N/A	Yes	
217	6230	1	3	307A		Classroom 307 Closet	W2	Cracking, Chipping on wall, door, and doorframe, Holes, Flaking, Efflorescence	38	Yes	No	N/A	Shelves, Stored Materials	Yes	Limited inspection due to stored materials
218	6230	1	3	307A		Classroom 307 Closet	W3	Efflorescence	40	Yes	Debris on windowsill and stored materials	10	Shelves, Stored Materials	Yes	Limited inspection due to stored materials. Damage has previously been repaired but is returning.
219	6230	1	3	307A		Classroom 307 Closet	W4	Efflorescence	130	Yes	Debris on stored materials	10	Shelves, Stored Materials	Yes	Limited inspection due to stored materials. Damage has previously been repaired but is returning.
220	6230	1	3	307A		Classroom 307 Closet	Floor	N/A	N/A	No	Debris along walls 3 and 4	10	N/A	No	
221	6230	1	1	102		Conference Room	W4	Chipping	3	No	No	N/A	N/A	No	
222	6230	1	1	102		Conference Room	W2	Chipping	4	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
223	6230	1	1	102		Conference Room	W3	Chipping on wall and windowsill, Holes	4	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
224	6230	1	1	102		Conference Room	W1	Chipping on wall, door, doorframe, blackboard ledge, and wood cove base, Flaking	31	No	No	N/A	N/A	No	
225	6230	1	1	102A		Conference Room Closet	W3	Chipping	4	No	No	N/A	N/A	No	
226	6230	1	1	102A		Conference Room Closet	W1	Chipping on door and doorframe	23	No	No	N/A	N/A	No	
227	6230	1	1	102A		Conference Room Closet	W4	Flaking	38	No	No	N/A	N/A	No	
228	6230	1	1	102A		Conference Room Closet	W2	Chipping on door and doorframe, Flaking	42	No	No	N/A	Stored Materials	No	
229	6230	1	1	102A		Conference Room Closet	Ceiling	Flaking	95	No	No	N/A	N/A	No	
230	6230	1	1	111		Counselor's Office	W4	Chipping on wall and wood panel	5	No	No	N/A	N/A	No	
231	6230	1	1	111		Counselor's Office	W2	Cracking, Chipping on wall and wood panel, Hole	16	No	No	N/A	N/A	Yes	
232	6230	1	1	111		Counselor's Office	W1	Chipping on wall, door, doorframe, and built in wood cabinets, Hole	35	No	No	N/A	N/A	Yes	
233	6230	1	1	111		Counselor's Office	W3	Chipping on wood panel and windowsills, Flaking on metal pipes	44	No	No	N/A	N/A	No	
234	6230	1	1	111		Counselor's Office	Floor	N/A	N/A	No	Paint chips behind radiator	2	N/A	No	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
235	6230	1	2	216		Faculty Lounge	W4	Chipping on wood panel, Hole	3	No	Paint Chips on chair rail	1	N/A	Yes	
236	6230	1	2	216		Faculty Lounge	Ceiling	Flaking above missing ceiling tile	8	No	No	N/A	N/A	No	
237	6230	1	2	216		Faculty Lounge	W2	Chipping on wall and wood panels, Holes	15	No	No	N/A	N/A	Yes	
238	6230	1	2	216		Faculty Lounge	W3	Chipping on wood panel, windowsills, and windowframes, Hole, paint has been stabilized, Flaking on wall, windowsills, and metal pipes, Efflorescence	51	Yes	No	N/A	N/A	Yes	
239	6230	1	2	216		Faculty Lounge	W1	Chipping on door, doorframe, and built in wood cabinet	61	No	No	N/A	N/A	No	
240	6230	1	1	S104		Fire Tower across from Classroom 107	W4	Flaking	30	No	No	N/A	N/A	No	
241	6230	1	1	S104		Fire Tower across from Classroom 107	W2	Chipping on door and doorframe, Flaking on wall, door and doorframe, Efflorescence	49	Yes	No	N/A	N/A	No	
242	6230	1	1	S104		Fire Tower across from Classroom 107	W1	Chipping on door and doorframe, Flaking on wall, door and doorframe	84	No	No	N/A	N/A	No	
243	6230	1	1	S104		Fire Tower across from Classroom 107	Ceiling	Flaking	234	No	No	N/A	N/A	No	Plaster is assumed asbestos
244	6230	1	1	S104		Fire Tower across from Classroom 107	W3	Flaking on wall and windowframes	250	No	No	N/A	N/A	No	
245	6230	1	2	S203		Fire Tower across from Classroom 203	W3	Flaking	1	No	No	N/A	N/A	No	
246	6230	1	2	S203		Fire Tower across from Classroom 203	Ceiling	Flaking	8	No	No	N/A	N/A	No	
247	6230	1	2	S203		Fire Tower across from Classroom 203	W2	Chipping on door and doorframe, Flaking	9	No	No	N/A	N/A	No	
248	6230	1	2	S203		Fire Tower across from Classroom 203	W1	Chipping on door and doorframe, Flaking on door and doorframe	29	No	No	N/A	N/A	No	
249	6230	1	2	S203		Fire Tower across from Classroom 203	W4	Chipping on doors and doorframe	110	No	No	N/A	N/A	No	
250	6230	1	2	S205		Fire Tower across from Classroom 204	W1	Chipping on windowsill, Flaking	2	No	No	N/A	N/A	No	
251	6230	1	2	S205		Fire Tower across from Classroom 204	W2	Chipping on door and doorframe	5	No	No	N/A	N/A	No	
252	6230	1	2	S205		Fire Tower across from Classroom 204	Ceiling	Flaking	8	No	No	N/A	N/A	No	
253	6230	1	2	S205		Fire Tower across from Classroom 204	W4	Chipping on door and doorframe	9	No	No	N/A	N/A	No	
254	6230	1	2	S205		Fire Tower across from Classroom 204	W3	Chipping on door and doorframe, Flaking	13	No	No	N/A	N/A	No	
255	6230	1	2	S204		Fire Tower across from Classroom 207	W4	Flaking, Efflorescence	25	Yes	No	N/A	N/A	No	
256	6230	1	2	S204		Fire Tower across from Classroom 207	W2	Flaking on wall, doorframe, and windowframe	63	No	No	N/A	N/A	No	
257	6230	1	2	S204		Fire Tower across from Classroom 207	W1	Chipping on door and doorframe, Flaking, Efflorescence	112	Yes	No	N/A	N/A	No	
258	6230	1	2	S204		Fire Tower across from Classroom 207	W3	Flaking on wall and windowframe	125	No	No	N/A	N/A	No	
259	6230	1	2	S204		Fire Tower across from Classroom 207	Ceiling	Significant Moisture Damage	155	Yes	No	N/A	N/A	Yes	Plaster is assumed asbestos
260	6230	1	3	S303		Fire Tower across from Classroom 303	W3	Chipping on windowsill	1	No	No	N/A	N/A	No	
261	6230	1	3	S303		Fire Tower across from Classroom 303	W2	Chipping on door, Flaking on door	5	No	No	N/A	N/A	No	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
262	6230	1	3	S303		Fire Tower across from Classroom 303	W4	Chipping on door and doorframe	8	No	No	N/A	N/A	No	
263	6230	1	3	S303		Fire Tower across from Classroom 303	W1	Chipping on door, Flaking on door and doorframe	16	No	No	N/A	N/A	No	
264	6230	1	3	S305		Fire Tower across from Classroom 304	W1	Chipping on windowsill	1	No	No	N/A	N/A	No	
265	6230	1	3	S305		Fire Tower across from Classroom 304	W4	Chipping on door and doorframe, Flaking	9	No	No	N/A	N/A	No	
266	6230	1	3	S305		Fire Tower across from Classroom 304	W2	Chipping, Flaking on wall, door, and doorframe	24	No	Debris on windowsill	1	N/A	No	
267	6230	1	3	S305		Fire Tower across from Classroom 304	W3	Chipping on door, Flaking on wall, door, and doorframe	37	No	No	N/A	N/A	No	
268	6230	1	3	S305		Fire Tower across from Classroom 304	Floor	N/A	N/A	No	Paint chips on floor	12	N/A	No	
269	6230	1	3	S304		Fire Tower across from Classroom 307	W2	Flaking on wall and windowframe	62	No	No	N/A	N/A	No	
270	6230	1	3	S304		Fire Tower across from Classroom 307	W4	Flaking	100	No	No	N/A	N/A	No	
271	6230	1	3	S304		Fire Tower across from Classroom 307	W1	Chipping on door and doorframe, Hole, Flaking on wall, door, and doorframe	167	No	No	N/A	N/A	No	
272	6230	1	3	S304		Fire Tower across from Classroom 307	Ceiling	Flaking, Significant Moisture Damage	234	Yes	No	N/A	N/A	Yes	Plaster is assumed asbestos
273	6230	1	3	S304		Fire Tower across from Classroom 307	W3	Flaking on wall and windowframe	512	No	No	N/A	N/A	No	
274	6230	1	3	S304		Fire Tower across from Classroom 307	Floor	N/A	N/A	No	Debris and Paint Chips	117	N/A	No	
275	6230	1	B	1		Girl's Restroom	W2	Efflorescence	4	Yes	No	N/A	N/A	Yes	
276	6230	1	B	1		Girl's Restroom	W1	Hole, Flaking	11	No	No	N/A	N/A	Yes	
277	6230	1	B	1		Girl's Restroom	W3	Efflorescence	16	Yes	No	N/A	N/A	Yes	
278	6230	1	B	1		Girl's Restroom	W4	Efflorescence	20	Yes	No	N/A	N/A	Yes	
279	6230	1	B	1		Girl's Restroom	Ceiling	Flaking on ceiling and metal duct, Efflorescence	45	Yes	No	N/A	N/A	Yes	
280	6230	1	B	5		Gym	W2	Chipping, Holes	7	No	No	N/A	N/A	Yes	
281	6230	1	B	5		Gym	W4	Chipping on wall and windowsills	12	No	No	N/A	N/A	No	
282	6230	1	B	5		Gym	Floor	Chipping on metal pipe	12	No	No	N/A	N/A	No	
283	6230	1	B	5		Gym	W1	Chipping on wall, door and doorframe, Staples, Flaking	18	No	No	N/A	N/A	Yes	
284	6230	1	B	5		Gym	W3	Cracking, Chipping on windowsills, Hole, Flaking, Efflorescence	27	No	No	N/A	N/A	Yes	
285	6230	1	B	005A		Gym Closet	W1	Chipping on doorframe	8	No	No	N/A	N/A	No	
286	6230	1	B	005A		Gym Closet	W3	Holes, Flaking	22	No	No	N/A	N/A	Yes	
287	6230	1	B	005A		Gym Closet	W2	Chipping, Flaking, Efflorescence	57	Yes	No	N/A	N/A	Yes	
288	6230	1	B	005A		Gym Closet	W4	Chipping on wood shelves, Flaking, Efflorescence	75	Yes	No	N/A	N/A	Yes	
289	6230	1	B	005A		Gym Closet	Ceiling	Holes, Flaking	125	No	No	N/A	N/A	Yes	
290	6230	1	B	002B		Hallway adjacent to Emergency Generator Room to Fan Room	W1	Chipping on door and doorframe	10	No	No	N/A	N/A	No	
291	6230	1	B	002B		Hallway adjacent to Emergency Generator Room to Fan Room	W3	Flaking	50	No	No	N/A	N/A	No	
292	6230	1	B	002B		Hallway adjacent to Emergency Generator Room to Fan Room	W2	Flaking	100	No	No	N/A	N/A	No	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
293	6230	1	B	002B		Hallway adjacent to Emergency Generator Room to Fan Room	Ceiling	Flaking on ceiling and metal duct	130	No	No	N/A	N/A	No	
294	6230	1	B	002B		Hallway adjacent to Emergency Generator Room to Fan Room	Floor	N/A	N/A	No	Debris throughout	80	N/A	No	
295	6230	1	B	005B		Hallway between Gym and Fan Room	W4	Holes, Flaking, Efflorescence	10	Yes	No	N/A	N/A	Yes	
296	6230	1	B	005B		Hallway between Gym and Fan Room	W2	Flaking, Efflorescence	23	Yes	No	N/A	N/A	Yes	
297	6230	1	B	005B		Hallway between Gym and Fan Room	W3	Chipping	24	No	No	N/A	N/A	No	
298	6230	1	B	005B		Hallway between Gym and Fan Room	W1	Cracking, Chipping, Holes	25	No	No	N/A	N/A	Yes	
299	6230	1	B	005B		Hallway between Gym and Fan Room	Ceiling	Flaking on ceiling and metal duct	80	No	No	N/A	N/A	No	
300	6230	1	2	H201		Hallway from Classrooms 201 to 205	W3	Chipping, Holes, Staples	12	No	No	N/A	N/A	Yes	
301	6230	1	2	H201		Hallway from Classrooms 201 to 205	W1	Holes, Staple Holes	22	No	No	N/A	N/A	Yes	
302	6230	1	2	H201		Hallway from Classrooms 201 to 205	W2	Chipping on wall, radiator covers, windowsills, and wood cove base, Holes, Staples and Staple Holes, Flaking on wall and metal pipes, Spalling, Efflorescence	172	Yes	No	N/A	N/A	Yes	
303	6230	1	2	H201		Hallway from Classrooms 201 to 205	W4	Cracking, Chipping on wall and wood cove base, Holes, Staples and Staple Holes, Flaking	230	No	No	N/A	N/A	Yes	
304	6230	1	3	H301		Hallway from Classrooms 301 to 305	W1	Cracking, Chipping, Flaking	7	No	No	N/A	N/A	No	
305	6230	1	3	H301		Hallway from Classrooms 301 to 305	W3	Cracking	7	No	No	N/A	N/A	No	
306	6230	1	3	H301		Hallway from Classrooms 301 to 305	W2	Cracking, Chipping on wall, radiator covers, and wood cove base, Staple Holes, Efflorescence	96	No	Debris on windowsill	1	N/A	Yes	
307	6230	1	3	H301		Hallway from Classrooms 301 to 305	W4	Cracking, Chipping on wall, and wood cove base, Holes, Staples, Staple Holes, Flaking	138	No	No	N/A	N/A	Yes	
308	6230	1	B	H002		Hallway outside Boy's Restroom & Storage Room to Left of Boy's Restroom	Ceiling	Flaking	1	No	No	N/A	N/A	No	
309	6230	1	B	H002		Hallway outside Boy's Restroom & Storage Room to Left of Boy's Restroom	W4	Chipping on wall, door, and doorframe	16	No	No	N/A	N/A	No	
310	6230	1	B	H002		Hallway outside Boy's Restroom & Storage Room to Left of Boy's Restroom	W3	Chipping, Flaking	25	No	No	N/A	N/A	No	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
311	6230	1	B	H002		Hallway outside Boy's Restroom & Storage Room to Left of Boy's Restroom	W1	Chipping, Flaking	35	No	No	N/A	N/A	No	
312	6230	1	B	H002		Hallway outside Boy's Restroom & Storage Room to Left of Boy's Restroom	W2	Chipping on wall, doors, and doorframe	60	No	No	N/A	N/A	No	
313	6230	1	1	H102		Hallway outside Classrooms 106 and 107	W2	Chipping on wood cove base	3	No	No	N/A	N/A	No	
314	6230	1	1	H102		Hallway outside Classrooms 106 and 107	W4	Cracking, Chipping	6	No	No	N/A	N/A	No	
315	6230	1	1	H102		Hallway outside Classrooms 106 and 107	W1	Cracking, Chipping on wall and wood cove base, Staples and Staple Holes	64	No	No	N/A	N/A	Yes	
316	6230	1	1	H102		Hallway outside Classrooms 106 and 107	W3	Cracking, Chipping on wall, built in wood cabinets, and wood cove base, Holes inside built in wood cabinets, Flaking on wall, windowsill and metal pipe, Efflorescence	135	Yes	No	N/A	N/A	Yes	
317	6230	1	2	H202		Hallway outside Classrooms 206 and 207	W4	Chipping	3	No	No	N/A	N/A	No	
318	6230	1	2	H202		Hallway outside Classrooms 206 and 207	Ceiling	Flaking	13	No	No	N/A	N/A	No	
319	6230	1	2	H202		Hallway outside Classrooms 206 and 207	W2	Staple Holes	20	No	No	N/A	N/A	Yes	
320	6230	1	2	H202		Hallway outside Classrooms 206 and 207	W1	Cracking, Chipping on wall and wood cove base, Holes, Staple Holes, Flaking, Significant Moisture Damage	51	Yes	No	N/A	N/A	Yes	
321	6230	1	2	H202		Hallway outside Classrooms 206 and 207	W3	Chipping on wall, windowsill, built in wood cabinets, and wood cove base, Flaking, Significant Moisture Damage	101	Yes	Debris inside built in wood cabinets	25	N/A	Yes	
322	6230	1	3	H302		Hallway outside Classrooms 306 and 307	W4	Chipping	3	No	No	N/A	N/A	No	
323	6230	1	3	H302		Hallway outside Classrooms 306 and 307	W2	Cracking, Chipping on wall and wood cove base, Flaking	9	No	No	N/A	N/A	No	
324	6230	1	3	H302		Hallway outside Classrooms 306 and 307	Ceiling	Flaking	12	No	No	N/A	N/A	No	
325	6230	1	3	H302		Hallway outside Classrooms 306 and 307	W1	Cracking, Chipping on wall and wood cove base, Hole, Staple Holes, Flaking	42	No	No	N/A	N/A	Yes	
326	6230	1	3	H302		Hallway outside Classrooms 306 and 307	W3	Chipping on wall, wood cove base, radiator cover, and wood cabinets, Gouge, Staple Holes, Flaking on wood cove base, Efflorescence, some inside built in wood cabinets	192	Yes	Debris inside built in wood cabinets	25	Stored Materials inside built in wood cabinets	Yes	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
327	6230	1	1	H101		Hallway outside Main Office to Classroom 105	W3	Chipping	2	No	No	N/A	N/A	No	
328	6230	1	1	H101		Hallway outside Main Office to Classroom 105	W1	Hole, Staple Holes	11	No	No	N/A	N/A	Yes	
329	6230	1	1	H101		Hallway outside Main Office to Classroom 105	W2	Cracking, Chipping on wall, radiator covers, windowsills, and wood cove base, Holes, Flaking on wall and metal pipes, Efflorescence	146	Yes	No	N/A	N/A	Yes	
330	6230	1	1	H101		Hallway outside Main Office to Classroom 105	W4	Cracking, Chipping on wall and wood cove base, Gouges, Holes, Staples and Staple Holes, Flaking	264	No	No	N/A	N/A	Yes	
331	6230	1	1	103		IMC 103	W4	Chipping on wall and wood cove base, Hole	4	No	No	N/A	N/A	Yes	
332	6230	1	1	103		IMC 103	W3	Chipping	5	No	No	N/A	N/A	No	
333	6230	1	1	103		IMC 103	W2	Cracking, Chipping on windowframe and windowsill, Flaking	7	No	No	N/A	N/A	No	
334	6230	1	1	103		IMC 103	W1	Chipping, Gouge	11	No	No	N/A	N/A	Yes	
335	6230	1	1	103A		IMC 103 Closet	W1	Chipping on door and doorframe	9	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
336	6230	1	1	103A		IMC 103 Closet	W2	Chipping on door and doorframe	12	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
337	6230	1	1	103A		IMC 103 Closet	W3	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
338	6230	1	1	103A		IMC 103 Closet	W4	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
339	6230	1	1	103A		IMC 103 Closet	Ceiling	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
340	6230	1	1	103A		IMC 103 Closet	Floor	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
341	6230	1	1	104		IMC 104	W2	Chipping	3	No	No	N/A	N/A	No	
342	6230	1	1	104		IMC 104	W3	Cracking, Chipping on wall and windowframe, Hole, Flaking	13	No	No	N/A	Shelves with books	Yes	Limited inspection due to shelves
343	6230	1	1	104		IMC 104	W4	Chipping	13	No	No	N/A	N/A	No	
344	6230	1	1	104		IMC 104	W1	Cracking, Chipping on wall, door, and doorframe, Gouges, paint has been stabilized, Staple Holes, Flaking	64	No	No	N/A	Shelves with Stored Materials	Yes	
345	6230	1	1	104A		IMC 104 Closet	W2	Chipping	1	No	No	N/A	Shelves, Stored Materials	No	Limited inspection due to shelves and stored materials
346	6230	1	1	104A		IMC 104 Closet	W3	Chipping	4	No	No	N/A	N/A	No	
347	6230	1	1	104A		IMC 104 Closet	W4	Chipping on wall, door, and doorframe, Flaking on door and doorframe	17	No	Debris in box	1	N/A	No	
348	6230	1	1	104A		IMC 104 Closet	W1	Chipping on door and doorframe	20	No	No	N/A	N/A	No	
349	6230	2	1	100A		Kitchen	W3	Chipping	1	No	No	N/A	N/A	No	
350	6230	2	1	100A		Kitchen	W2	Chipping	3	No	No	N/A	N/A	No	
351	6230	2	1	100A		Kitchen	W4	Chipping on fan stand	3	No	No	N/A	N/A	No	
352	6230	2	1	100A		Kitchen	W1	Chipping	9	No	No	N/A	N/A	No	
353	6230	1	1	101		Main Office	W2	Chipping on wood cove base, Hole	3	No	No	N/A	Furniture	Yes	
354	6230	1	1	101		Main Office	W3	Chipping on wall and wood cove base	4	No	No	N/A	N/A	No	
355	6230	1	1	101		Main Office	W4	Chipping	16	No	No	N/A	Furniture	No	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
356	6230	1	1	101		Main Office	W1	Cracking on panel above door, Chipping on wall, doorframe, and wood cove base, Flaking	22	No	No	N/A	Cabinets, Papers	No	
357	6230	1	1	101B		Main Office Closet	W3	Flaking	35	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials
358	6230	1	1	101B		Main Office Closet	W4	Flaking	60	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials
359	6230	1	1	101B		Main Office Closet	W1	Chipping on door and doorframe, Flaking	66	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials
360	6230	1	1	101B		Main Office Closet	Floor	N/A	N/A	No	Debris in corner of walls 1 and 4	2	N/A	No	
361	6230	1	1	101C		Main Office Restroom	W1	Chipping on doorframe	1	No	No	N/A	N/A	No	
362	6230	1	1	101C		Main Office Restroom	W4	Cracking	5	No	No	N/A	N/A	No	
363	6230	1	1	101C		Main Office Restroom	W2	Chipping, Flaking	8	No	No	N/A	N/A	No	
364	6230	1	1	108B		Nurse's Office	W2	Cracking, Chipping on wood panel, Holes	15	No	No	N/A	Cabinet, Chair	No	
365	6230	1	1	108B		Nurse's Office	W4	Cracking, Chipping on wood panel and windowsill	15	No	No	N/A	Desk, Microwave	No	
366	6230	1	1	108B		Nurse's Office	W3	Chipping on wood panel and windowsill, Flaking on old telephone cord and metal pipe	20	No	No	N/A	Refrigerator	No	
367	6230	1	1	108B		Nurse's Office	W1	Chipping on door, doorframe, wood panel, and wood cabinet	34	No	No	N/A	N/A	No	
368	6230	1	1	108B		Nurse's Office	Floor	N/A	N/A	No	Paint chips near radiator	3	N/A	No	
369	6230	1	1	103C		Office 103	W1	Chipping on doorframe	2	No	No	N/A	N/A	No	
370	6230	1	1	103C		Office 103	W2	Gouges	2	No	No	N/A	N/A	Yes	
371	6230	1	1	103C		Office 103	W4	Chipping	2	No	No	N/A	N/A	No	
372	6230	1	1	103C		Office 103	W3	Chipping on windowframe, windowsills, and wood cove base	8	No	No	N/A	N/A	No	
373	6230	1	3	310		Office 310	W4	Cracking	6	No	No	N/A	N/A	No	
374	6230	1	3	310		Office 310	W3	Chipping on wall and wood panels, Flaking on wall and windowsills	20	No	No	N/A	N/A	No	
375	6230	1	3	310		Office 310	W2	Cracking, Chipping on wall and wood panels	36	No	No	N/A	N/A	No	
376	6230	1	3	310		Office 310	W1	Chipping on door, doorframe, and built in wood cabinet	40	No	No	N/A	N/A	No	
377	6230	1	1	101D		Principal's Office	W3	Chipping on windowframe and windowsill	6	No	No	N/A	Furniture	No	
378	6230	1	1	101D		Principal's Office	W4	Cracking, Chipping on wall and wood cove base, Flaking behind radiator	21	No	No	N/A	Furniture	No	
379	6230	1	2	215B		Staff Restroom	Ceiling	Flaking above missing ceiling tile	2	No	No	N/A	N/A	No	
380	6230	1	3	322		Staff Restroom	W1	Cracking, Chipping on door and doorframe	4	No	No	N/A	N/A	No	
381	6230	1	1	108		Staff Restroom	W4	Cracking, Chipping	4	No	No	N/A	N/A	No	
382	6230	1	1	108		Staff Restroom	W2	Cracking	5	No	No	N/A	N/A	No	
383	6230	1	3	322		Staff Restroom	W2	Cracking	6	No	No	N/A	N/A	No	
384	6230	1	B	007A		Staff Restroom	Ceiling	Flaking	6	No	No	N/A	N/A	No	
385	6230	1	2	215B		Staff Restroom	W1	Chipping on door and doorframe	8	No	No	N/A	N/A	No	
386	6230	1	1	108		Staff Restroom	W1	Chipping on wall, door, and doorframe	9	No	No	N/A	N/A	No	

Filtler -Scope of Work

Task ID	ULCS#	E l e m e n t	F l o o r	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
387	6230	1	1	108		Staff Restroom	W3	Cracking, Chipping on windowsill and radiator	9	No	No	N/A	N/A	No	
388	6230	1	2	215B		Staff Restroom	W3	Significant Moisture Damage	12	Yes	No	N/A	N/A	Yes	
389	6230	1	3	322		Staff Restroom	W3	Chipping on windowsill, Flaking on radiator, Efflorescence	14	Yes	No	N/A	N/A	Yes	
390	6230	1	3	322		Staff Restroom	W4	Cracking, Flaking	14	No	No	N/A	N/A	No	
391	6230	1	B	007A		Staff Restroom	W1	Chipping on door and doorframe	16	No	No	N/A	N/A	No	
392	6230	1	B	007A		Staff Restroom	W3	Chipping, Flaking, Efflorescence	16	Yes	No	N/A	N/A	Yes	
393	6230	1	B	007A		Staff Restroom	W4	Flaking	50	No	No	N/A	N/A	No	
394	6230	1	B	007A		Staff Restroom	W2	Flaking	100	No	No	N/A	N/A	No	
395	6230	1	B	007A		Staff Restroom	Floor	Chipping, Flaking on metal pipe	202	No	Debris along wall 4	2	N/A	No	
396	6230	1	1	S103		Stairwell across from IMC 103 Office	Ceiling	Flaking	4	No	No	N/A	N/A	No	
397	6230	1	1	S103		Stairwell across from IMC 103 Office	W1	Chipping	20	No	No	N/A	N/A	No	
398	6230	1	1	S103		Stairwell across from IMC 103 Office	W3	Chipping on wall, windowframe, and windowsill	20	No	No	N/A	N/A	No	
399	6230	1	1	S103		Stairwell across from IMC 103 Office	W4	Chipping on door and doorframe	24	No	No	N/A	N/A	No	
400	6230	1	1	S103		Stairwell across from IMC 103 Office	W2	Chipping on wall, door, and doorframe, Flaking on door and doorframe	33	No	No	N/A	N/A	No	
401	6230	1	1	S105		Stairwell across from IMC 104	Ceiling	Flaking	4	No	No	N/A	N/A	No	
402	6230	1	1	S105		Stairwell across from IMC 104	W4	Chipping on wall, door, and doorframe	9	No	No	N/A	N/A	No	
403	6230	1	1	S105		Stairwell across from IMC 104	W1	Chipping	25	No	No	N/A	N/A	No	
404	6230	1	1	S105		Stairwell across from IMC 104	W2	Chipping on wall, door, and doorframe, Flaking on door and doorframe	38	No	No	N/A	N/A	No	
405	6230	1	1	S105		Stairwell across from IMC 104	W3	Chipping	50	No	No	N/A	N/A	No	
406	6230	1	3	S301		Stairwell adjacent Classroom 305	W2	Cracking, Efflorescence	5	Yes	No	N/A	N/A	Yes	
407	6230	1	3	S301		Stairwell adjacent Classroom 305	W4	Chipping, Gouge, Holes	6	No	No	N/A	N/A	Yes	
408	6230	1	3	S301		Stairwell adjacent Classroom 305	W3	Chipping on doors and doorframe	18	No	No	N/A	N/A	No	
409	6230	1	3	S301		Stairwell adjacent Classroom 305	Floor	Chipping on railings	23	No	No	N/A	N/A	No	
410	6230	1	3	S301		Stairwell adjacent Classroom 305	W1	Cracking, Efflorescence	28	Yes	No	N/A	N/A	Yes	
411	6230	1	1	S102		Stairwell adjacent to Classroom 105	W4	Cracking, Chipping on wood cove base	8	No	No	N/A	N/A	No	
412	6230	1	1	S102		Stairwell adjacent to Classroom 105	W3	Chipping on door and doorframe	10	No	No	N/A	N/A	No	
413	6230	1	1	S102		Stairwell adjacent to Classroom 105	W2	Chipping, Hole, Flaking	20	No	No	N/A	N/A	No	
414	6230	1	1	S102		Stairwell adjacent to Classroom 105	W1	Chipping on wall, doors, and doorframe, Flaking on door	47	No	No	N/A	N/A	No	
415	6230	1	1	S102		Stairwell adjacent to Classroom 105	Ceiling	Flaking	65	No	No	N/A	N/A	No	
416	6230	1	2	S202		Stairwell adjacent to Classroom 201	W4	Cracking, Hole, paint has been stabilized	2	No	No	N/A	N/A	Yes	
417	6230	1	2	S202		Stairwell adjacent to Classroom 201	W3	Cracking, Chipping on windowsill	4	No	No	N/A	N/A	No	

Fittler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
418	6230	1	2	S202		Stairwell adjacent to Classroom 201	W2	Cracking	5	No	No	N/A	N/A	No	
419	6230	1	2	S202		Stairwell adjacent to Classroom 201	W1	Chipping on doors and doorframe	10	No	No	N/A	N/A	No	
420	6230	1	2	S202		Stairwell adjacent to Classroom 201	Ceiling	Flaking	14	No	No	N/A	N/A	No	
421	6230	1	2	S202		Stairwell adjacent to Classroom 201	Floor	Chipping on railings	40	No	No	N/A	N/A	No	
422	6230	1	2	S201		Stairwell adjacent to Classroom 205	W4	Chipping	1	No	No	N/A	N/A	No	
423	6230	1	2	S201		Stairwell adjacent to Classroom 205	W2	Cracking, Flaking, Efflorescence	6	Yes	No	N/A	N/A	Yes	
424	6230	1	2	S201		Stairwell adjacent to Classroom 205	W1	Chipping on windowsill, Staples, Efflorescence	13	Yes	No	N/A	N/A	Yes	
425	6230	1	2	S201		Stairwell adjacent to Classroom 205	Floor	Chipping on railings	15	No	No	N/A	N/A	No	
426	6230	1	2	S201		Stairwell adjacent to Classroom 205	W3	Chipping on doors and doorframe	18	No	No	N/A	N/A	No	
427	6230	1	2	S201		Stairwell adjacent to Classroom 205	Ceiling	Flaking	21	No	No	N/A	N/A	No	
428	6230	1	3	S302		Stairwell adjacent to Classroom 301	W4	Cracking	6	No	No	N/A	N/A	No	
429	6230	1	3	S302		Stairwell adjacent to Classroom 301	Ceiling	Chipping, Flaking	7	No	No	N/A	N/A	No	
430	6230	1	3	S302		Stairwell adjacent to Classroom 301	W3	Cracking, Hole	13	No	No	N/A	N/A	Yes	
431	6230	1	3	S302		Stairwell adjacent to Classroom 301	W2	Cracking, Flaking	14	No	No	N/A	N/A	No	
432	6230	1	3	S302		Stairwell adjacent to Classroom 301	W1	Chipping, Spalling	16	Yes	No	N/A	N/A	Yes	
433	6230	1	3	S302		Stairwell adjacent to Classroom 301	Floor	Chipping on hand rails	40	No	No	N/A	N/A	No	
434	6230	1	1	S101		Stairwell adjacent to Main Office	W1	Chipping on doors and doorframes	10	No	No	N/A	N/A	No	
435	6230	1	1	S101		Stairwell adjacent to Main Office	W4	Cracking, Chipping, Holes	12	No	No	N/A	N/A	Yes	
436	6230	1	1	S101		Stairwell adjacent to Main Office	W3	Chipping on doors and doorframes, Flaking	16	No	No	N/A	N/A	No	
437	6230	1	1	S101		Stairwell adjacent to Main Office	W2	Cracking, Chipping, Flaking	27	No	No	N/A	N/A	No	
438	6230	1	1	S101		Stairwell adjacent to Main Office	Ceiling	Flaking	33	No	No	N/A	N/A	No	
439	6230	2	1	S110		Stairwell from Element 1 to Cafeteria	W2	Chipping on wall and cove base	5	No	No	N/A	N/A	No	
440	6230	2	1	S110		Stairwell from Element 1 to Cafeteria	W4	Chipping on door and doorframe	9	No	No	N/A	N/A	No	
441	6230	2	1	S110		Stairwell from Element 1 to Cafeteria	Floor	Chipping	60	No	No	N/A	N/A	No	
442	6230	2	1	S110		Stairwell from Element 1 to Cafeteria	W3	Cracking, Chipping on wall, door, and doorframe	70	No	No	N/A	N/A	No	
443	6230	2	1	S110		Stairwell from Element 1 to Cafeteria	W1	Cracking, Chipping on wall, radiator, and metal jacket, Flaking on metal pipe	75	No	No	N/A	N/A	No	

Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
444	6230	1	B	008A		Storage Closet across from Boy's Restroom	W1	Chipping	2	No	No	N/A	N/A	No	
445	6230	1	B	008A		Storage Closet across from Boy's Restroom	W4	Chipping on windowframe	8	No	No	N/A	N/A	No	
446	6230	1	2	217		Storage Closet across from Classroom 201	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
447	6230	1	2	217		Storage Closet across from Classroom 201	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
448	6230	1	2	217		Storage Closet across from Classroom 201	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
449	6230	1	2	217		Storage Closet across from Classroom 201	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
450	6230	1	2	217		Storage Closet across from Classroom 201	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
451	6230	1	2	217		Storage Closet across from Classroom 201	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
452	6230	1	3	301A		Storage Closet across from Classroom 301	W1	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
453	6230	1	3	301A		Storage Closet across from Classroom 301	W2	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
454	6230	1	3	301A		Storage Closet across from Classroom 301	W3	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
455	6230	1	3	301A		Storage Closet across from Classroom 301	W4	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
456	6230	1	3	301A		Storage Closet across from Classroom 301	Ceiling	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
457	6230	1	3	301A		Storage Closet across from Classroom 301	Floor	No Access	No Access	No Access	No Access	No Access	No Access	No Access	This space will need to be inspected
458	6230	1	1	101A		Storage Closet across from Main Office	Ceiling	Flaking	14	No	No	N/A	N/A	No	
459	6230	1	1	101A		Storage Closet across from Main Office	W4	Chipping on built in wood shelves, Flaking	15	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials
460	6230	1	1	101A		Storage Closet across from Main Office	W1	Chipping on door and doorframe	30	No	No	N/A	N/A	No	
461	6230	1	1	101A		Storage Closet across from Main Office	W2	Chipping on wall and built in wood shelves, Flaking	32	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials
462	6230	1	1	101A		Storage Closet across from Main Office	W3	N/A	N/A	No	No	N/A	Shelves with Stored Materials	No	Limited inspection due to shelves with stored materials



Fitler -Scope of Work

Task ID	ULCS#	Element	Floor	Space # (on Floor Plan)	Space Type	On Site Room Name	Component	Description of Paint and Plaster Damage (i.e. cracking, chipping, gouges, holes, flaking, spalling, efflorescence, significant moisture damage)	Quantity (sf)	On-going Moisture Intrusion (yes or no)	Paint and Plaster Debris on Surfaces and/or Educational Materials (describe location)	Quantity (sf)	Contents Need to be Moved (i.e. posters, contents, furniture)	Plastering Needed (yes or no)	Other Notes or Comments
479	6230	1	B	010A		Storage Room to Left of Boiler Room	W2	Flaking	5	No	No	N/A	N/A	No	
480	6230	1	B	010A		Storage Room to Left of Boiler Room	W3	Efflorescence	6	Yes	No	N/A	N/A	Yes	
481	6230	1	B	010A		Storage Room to Left of Boiler Room	W4	Flaking, Efflorescence	23	Yes	No	N/A	N/A	Yes	
482	6230	1	B	010A		Storage Room to Left of Boiler Room	Ceiling	Flaking	35	No	No	N/A	N/A	No	
483	6230	1	B	7		Storage Room to Left of Boy's Restroom	W3	Efflorescence	30	No	No	N/A	Stored Materials	Yes	Limited inspection due to stored materials
484	6230	1	B	7		Storage Room to Left of Boy's Restroom	W2	N/A	N/A	No	No	N/A	Stored Materials	No	Limited inspection due to stored materials
485	6230	1	B	010B		Storage Room to Right of Boiler Room	W3	Efflorescence	5	Yes	No	N/A	N/A	No	
486	6230	1	B	010B		Storage Room to Right of Boiler Room	Ceiling	Flaking	35	No	No	N/A	N/A	No	
487	6230	1	2	215		Teacher's Office across from Classroom 204	W4	Chipping on wood panel, Flaking, Spalling on wood panel, Efflorescence	13	Yes	No	N/A	N/A	Yes	
488	6230	1	2	215		Teacher's Office across from Classroom 204	W1	Cracking, Chipping on wall, door, and doorframe, Flaking on wood panel	35	No	No	N/A	N/A	No	
489	6230	1	2	215		Teacher's Office across from Classroom 204	W3	Cracking, Chipping on wood panel and windowsills, Flaking, Efflorescence	56	Yes	Debris on windowsill	1	Shelves with Stored Materials	Yes	
490	6230	1	2	215		Teacher's Office across from Classroom 204	W2	Cracking, Chipping on wood panel, windowsills, and radiator, Flaking on wall and metal pipes	66	No	No	N/A	N/A	No	
491	6230	1	3	322C		Vestibule outside Boy's and Staff Restrooms	W2	Cracking, Flaking	5	No	No	N/A	N/A	No	
492	6230	1	3	322C		Vestibule outside Boy's and Staff Restrooms	W3	Cracking, Spalling	10	Yes	No	N/A	N/A	Yes	
493	6230	1	3	322C		Vestibule outside Boy's and Staff Restrooms	W1	Cracking, Gouges	23	No	No	N/A	N/A	Yes	
494	6230	1	3	322C		Vestibule outside Boy's and Staff Restrooms	W4	Cracking, Chipping on doorframe, Spalling	60	Yes	Debris on chair rail	2	N/A	Yes	
495	6230	1	1	103B		Vestibule outside IMC 103 & Office 103	W2	Chipping	2	No	No	N/A	N/A	No	
496	6230	1	1	103B		Vestibule outside IMC 103 & Office 103	W4	Cracking	4	No	No	N/A	N/A	No	
497	6230	1	1	103B		Vestibule outside IMC 103 & Office 103	W1	Chipping on door and doorframe, Flaking	34	No	No	N/A	N/A	No	
498	6230	1	1	108C		Vestibule outside Nurse's Office and Staff Restroom	W2	Chipping on wood panel	1	No	No	N/A	N/A	No	
499	6230	1	1	108C		Vestibule outside Nurse's Office and Staff Restroom	W4	Chipping	9	No	No	N/A	N/A	No	

